Title List of Documents Made Publicly Available

February 1-29, 1984

Office of Administration U.S. Nuclear Regulatory Commission



Title List of Documents Made Publicly Available

February 1-29, 1984

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555



CONTENTS

Preface	V
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket Items by Facility Name	XV
Docketed Items	1
Low Level Radwaste Disposal Sites — Docket 27	1
Domestic Licensing of Source Material — Docket 40	1
Domestic Licensing of Production and Utilization Facilities — Docket 50	7
Domestic Licensing of Special Nuclear Material — Docket 70	405
Packaging of Radioactive Material for Transport and Transportation of	
Radioactive Material Under Certain Conditions — Docket 71	410
Licensing of Independent Spent Fuel Storage — Docket 72	414
Nondocketed Items	415
10 CFR — Commission Meeting Records	, 415
ACRS — Advisory Committee on Reactor Safeguards	418
ADVCM — NRC Advisory Committees	. 420
COMMISSION - NRC Commissioners	420
CONTRACT — NRC Contracts and Modifications	422
FOIA — Freedom of Information Act Requests and Releases	431
GEN TECH IS — Generic Technical Issues	485
I&E — Inspection and Enforcement .	487
MISC — Public Document Room Miscellaneous	489
NUREG — NUREG Reports and Related Correspondence	490
ORG — Correspondence with Other Organizations	. 508
PR Proposed Rule.	511
PRM — Petition for Rulemaking	511
PROJ — Projects - Predocket Licensing	. 512
PT21 — Noncompliance Reports and Related Correspondence.	. 512
QA999 — Quality Assurance Inspections	514
REGGD - Regulatory Guides	. 517
RES — Research and Technical Assistance Reports	518
REVIEW GROUP — NRC Research Review Groups	518
SECY — Position Papers Before the Commission	519
STATE PROG — State Programs	520
TOPREP — Vendor Reports and Related Correspondence	526
WASTE MGT — Nuclear Waste Management	. 530
XPORTLIC - Export and Import Licenses	539
Personal Author Index	547
Corporate Source Index	581
Report Number Index	. 013
Cross Reference of Enclosures to Principal Documents.	615
Appendix A — Definitions of Docket 50 Categories	, A-1
Appendix B — Definitions of Nondocketed Categories	B-1

PREFACE

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences. LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence

- W. Decommissioning stage documents and correspondence
- X. Onsite low-level wastes storage

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:

P. Operating license stage documents & correspondence

② (3)

8203090028 Responds to 820201 ltr requesting documents re environ qualification of electrical equipment. All nonproprietary repts will be provided to Franklin Research Ctr by 820408. Proprietary repts will be provided to NRC by 820510.

4 MILLS, L.M. (5) Tennessee Valley Authority. (6) 82/03/04. (7) VASSALLO, D.B. Operating Reactors Branch 2. (8) 1p. 1216:254. 24X Fiche: 50-259, 82/03/04, 8203090028.

8203090028.

- 1. NRC/PDR Document category (see Appendix A).
- 2. NRC Accession Number (year, month, day, and sequence number of item).
- 3. Description of information contained in the document.
- 4. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source.
- 6. Date of document described.
- 7. Recipient of document and NRC or corporate affiliation.
- 8. Pages in this document.
- 9. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
- 10. This three-digit portion of this entry is the number of the frame on which this document starts.
- 11. The 24X Fiche designation consists of the docket number followed by the date of the document and the accession number for the document. This designation provides the information needed by subscribers to the National Technical Information Service docket microfiche to locate the document fiche.
- 12. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. These categories and their symbols are:

10CFR — Commission Meeting Records
ACRS — Advisory Committee on Reactor Safeguards
COMMISSION — NRC Commissioners
CONTRACT — NRC Contracts and Modifications
DISCLOSURE — Financial Disclosure Information
FOIA — Freedom of Information Act Requests and Releases
GEN TECH IS — Generic Technical Issues

I&E — Inspection and Enforcement

MISC — Public Document Room Miscellaneous

NUREG - NUREG Reports and Related Correspondence

ORG — Correspondence with Other Organizations

PR — Proposed Rule

PRM — Petition for Rulemaking

PROJ — Projects—Predocket Licensing

PT21 — Noncompliance Reports and Related Correspondence

QA999 - Quality Assurance Inspections

REGGD — Regulatory Guides

RES — Research and Technical Assistance Reports

REVIEW GRP — NRC Research Review Groups

RM - Rulemakings

SECY — Position Papers Before the Commission

STATE PROG — State Programs

TOPREP — Vendor Reports and Related Correspondence


WASH — Regulatory Publications—Pre-NUREG Series

WASTE MGT - Nuclear Waste Management

XPORTLIC - Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:



- 1. Nondocketed category
- 2. NRC Accession Number (year, month, day, and sequence number of item)
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 6. Corporate, agency or other nonindividual source.
- 7. Contract or financial (FIN) number (if any). If the document has a secondary report number, it will appear following this entry.
- 8. Secondary report number assigned by originator.
- 9. Date of document described.
- 10. NRC organizational recipient.
- 11. Pages in document.
- 12. All NUREG-series documents are available for purchase at NRC. Information on ordering documents is given below. All NUREG-series documents are also available at NTIS. Information on ordering from NTIS is also given below.
- 13. Price for which NRC sells the document.

- 14. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
- 15. This three-digit portion of this entry is the number of the frame on which this document starts.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the chargecard number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: (1) paper to paper is \$0.05 per page except for oversized documents and engineering drawings, which vary from \$0.50 to \$1.00 per square foot; (2) microform to paper is \$0.05 a page for pages on microfiche and is \$0.20 a square foot for a full-size print or \$0.25 for a reduced-size print (18" x 24") of a drawing on an aperture card; and (3) microform to microform is \$0.10 per microfiche and \$0.20 per aperture card. Orders completed for mailing or for a special delivery service will have an additional fee for the actual mailing, shipping, or delivery service rate. Unless a user requests special packing materials, there is no additional charge by the contractor for handling and wrapping materials.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Literature Research Company. An account may be established with the Literature Research Company by calling (703)-941-8018,

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
Low Level Rad	lwaste Disposal Sites — Docket 27		40-8586	Kerr-McGee Nuclear Corp , Oklahoma City, OK	6
27-039	Sheffield, IL, U.S. Ecology, Inc.	1	40-8663	Nuclear Dynamics, Inc., Phoenix, AZ	6
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc.	1	40-8681	-	
27-048	Richland, WA, U.S. Ecology, Inc	1		Energy Fuels Nuclear, Inc., Denver, CO	6
Domestic Lice	nsing of Source Material — Docket 40		40-8684	Western Nuclear, Inc., Lakewood, CO	6
40-0299	Union Carbide Corp., Grand Junction, CO	1	40-8724	Chemetron Corp., Chicago, IL	6
40-0672	Nuclear Metals, Inc., Concord, MA	2	40-8745	Ogle Petroleum, Inc., Casper, WY	6
40-1162	Western Nuclear, Inc., Jeffrey City, WY	2	40-8768	Kerr-McGee Nuclear Corp., Oklahoma City, OK	6
40-1341	Tennessee Valley Authority, Chattanooga, TN	2	40-8783	Uranerz USA, Inc., Casper, WY	6
40-1386	Raytheon Co., Waltham, MA	4	40-8786	Uranium Resources, Inc., Richardson, TX	6
40-2061	Kerr-McGee Chemical Corp.,	4	40-8794	Molycorp, Inc., Los Angeles, CA	6
	Oklahoma City, OK		Domestic Licer Docket 50	ising of Production and Utilization Facilities —	
40-2259	Pathlinder Mines Corp., Riverton, WY	4	50-3	Indian Point Station, Unit 1	7
40-3453	Atlas Minerals, Inc., Denver, CO	4	50-6	Battelle Memorial Institute Research Reactor	7
40-4658	Interior, Dept. of, Avondale, MD	4			
40-6622	Pathfinder Mines Corp., Shirley Basin, WY	4	50-10	Dresden Nuclear Power Station, Unit 1	7
40-6659	Getty Oil Co Petrotomics Co., Shirley Basin, WY	4	50-20	Massachusetts Institute of Technology Research Reactor	9
40-6920	Automation Industries, Inc.,	4	50-29	Yankee-Rowe Nuclear Power Station	9
10 (320	Phoenixville, PA	•	50-62	Univ. of Virginia Research Reactor	10
40-6940	Kawecki Berylco Industries Inc., Boyertown, PA	5	50-70	General Electric Test Reactor	10
40-7455	Whittaker Metals, Los Angeles, CA	5	50-72	Univ. of Utah Research Reactor	11
	3		50-83	Univ. of Florida Training Reactor	11
40-7580	Fansteel, Inc., North Chicago, IL	5	50-87	Westinghouse Critical Experiment	11
40-8027	Kerr-McGec Nuclear Corp., Oklahoma City, OK	5	50-89	General Atomic Co.	11
40-8084	Rio Algom Corp., Moab, UT	5	50-124	Virginia Polytechnic Institute	11
40-8380	Rocky Mountain Energy Co., Broomfield, CO	5		Training Reactor	
40-8452	Bear Creek Uranium Co., Casper, WY	5	50-128	Texas A&M Univ. Research Reactor	11
40-8502	Wyoming Mineral Corp., Lakewood, CO	5	50-133	Humboldt Bay Power Plant, Unit 3	Н
40-8511	Cotter Corp., Golden, CO	5	50-139	Univ. of Washington Research Reactor	12
40-8584	Minerals Exploration Co., Los Angeles, CA	6	50-142	UCLA Training Reactor	12
40-8585	Wyoming Mineral Corp., Lakewood, CO	6	50-146	Saxton Nuclear Experimental Facility	13

cket	Name	Page	Docket	Name	Page
50-148	Univ of Kansas Research Reactor	13	50-272	Salem Nuclear Generating Station, Unit 1	71
50-151	Univ of Illinois Research Reactor	13	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	71
50-155	Big Rock Point Nuclear Plant	13	50-277	Peach Bottom Atomic Power Station, Unit 2	74)
50 163	General Atomic Co.	15	50-278	Peach Bottom Atomic Power Station, Unit 3	81
50-166	Univ of Maryland Research Reactor	15	50-280	Surry Power Station, Unit 1	83
50-170	National Naval Medical Center	16	50-281	Surry Power Station, Unit 2	87
50-171	Peach Bottom Atomic Power Station, Unit 1	16	50-282	Prairie Island Nuclear Station, Unit 1	89
50-184	National Bureau of Standards Reactor	16	50-285	Fort Calhoun Station, Unit 1	91
50-192	Univ of Texas Research Reactor	16	50-286	Indian Point Station, Unit 3	93
50-201	West Valley Reprocessing Plant	16	50-287	Oconce Nuclear Station, Unit 3	96
50-206	San Onofre Nuclear Station, Unit 1	16	50-288	Reed College Research Reactor	gg
50-213	Haddam Neck Plant	19	50-289	Three Mile Island Nuclear Station, Unit 1	qq
50-219	Oyster Creek Nuclear Power Plant	21	50-293	Pilgrim Nucleai Power Station, Unit 1	[09
50-220	Nine Mile Point Nuclear Station, Unit 1	23	50-294	Michigan State Univ. Research Reactor	111
50-223	Univ. of Lowell Research Reactor	26	50-295	Zion Nuclear Power Station, Unit 1	Ш
50-237	Dresden Nuclear Power Station, Unit 2	26	50-296	Browns Ferry Nuclear Power Station, Unit 3	111
50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	28	50-297	North Carolina State Univ	117
50-245	Millstone Nuclear Power Station, Unit 1	30	รก วอย	PULSTAR Reactor	
50-247	Indian Point Station, Unit 2	32	50-298	Cooper Nuclear Station	117
50-249	Dresden Nuclear Power Station, Unit 3	35	50-301	Point Beach Nuclear Plant, Unit 2	119
50-250	Turkey Point Plant, Unit 3	37	50-302	Crystal River Nuclear Plant, Unit 3	171
50-251	Turkey Point Plant, Unit 4	40	50-304	Zion Nuclear Power Station, Unit 2	12/
50-254	Quad-Cities Station, Unit 1	43	50-305	Kewaunee Nuclear Power Plant	125
50-255	Palisades Nuclear Plant	45	50-306	Prairie Island Nuclear Station, Unit 2	127
50-259	Browns Ferry Nuclear Power Station, Unit 1	47	50-309	Maine Yankee Atomic Power Plant	128
50-260	Browns Ferry Nuclear Power Station, Unit 2	51	50-311	Salem Nuclear Generating Station, Unit 2	121
50-261	H B. Robinson Plant, Unit 2	55	50-312	Rancho Seco Nuclear Generating Station	133
50-262	Brigham Young Univ. Research Reactor	57	50-313	Arkansas Nuclear One, Unit 1	134
50-263	Monticello Nuclear Generating Plant	58	50-315	Donald C. Cook Nuclear Power Plant, Unit 1	1,18
50-265	Quad-Cities Station, Unit 2	59	50-316	Donald C. Cook Nuclear Power Plant, Unit 2	140
50-266	Point Beach Nuclear Plant, Unit 1	62	50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	145
50-267	Fort St. Vrain Nuclear Generating Station	64	50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	141
50-269	Oconce Nuclear Station, Unit 1	65	50-320	Three Mile Island Nuclear Station, Unit 2	147
50-270	Oconce Nuclear Station, Unit 2	67	50-321	Edwin I. Hatch Nuclear Plant, Unit 1	150
50-271	Vermont Yankee Nuclear Power Station	69	50-322	Shoreham Nuclear Power Station	[5,3
			50-323	Diablo Canyon Nuclear Power Plant, Unit 2	100

Docket	Name	Page	Docket	Name	Page
50-324	Brunswick Steam Electric Plant, Unit 2	163	50-388	Susquehanna Steam Electric Station, Unit 2	267
50-325	Brunswick Steam Electric Plant, Unit 1	166	50.390		270
50-327	Sequoyah Nuclear Plant, Umt 1	169	50-389	St Lucie Plant, Unit 2	270
50-328	Sequoyah Nuclear Plant, Unit 2	171	5()-39()	Watts Bar Nuclear Plant, Unit 1	275
50-329	Midland Plant, Unit 1	173	50-391	Watts Bai Nuclear Plant, Unit 2	273
50-330	Midland Plant, Unit 2	182	50-395	Virgil C. Summer Nuclear Station, Unit 1	279
50-331	Duane Arnold Energy Center	190	50-396	Univ of Virginia Cavalier Reactor	279
50-333	James A Fitzpatrick Nuclear Power Plant	192	50-397	WPPSS Nuclear Project, Unit 2	
50-334	Beaver Valley Power Station, Unit 1	194	50-100	Shearon Harris Nuclear Power Plant, Unit 1	281
50-335	St. Lucie Plant, Unit 1	196	50-401	Shearon Harris Nuclear Power Plant, Unit 2	285
50-336	Millstone Nuclear Power Station, Unit 2	198	T()) ()3	Univ of Utah Research Reactor	288
50-338	North Anna Power Station, Unit 1	201	50-407		288
50-339	North Anna Power Station, Unit 2	203	50-409 50-410	La Crosse Boiling Water Reactor Nine Mile Point Nuclear Station, Unit 2	290
50-341	Entico Fermi Atomic Power Plant, Unit 2	205			292
50-344	Trojan Nuclear Plant	207	50-412	Beaver Valley Power Station, Unit 2	293
50-346	Davis-Besse Nuclear Power Station, Unit 1	210	50-413	Catawba Nuclear Station, Unit I	
50-348	Joseph M. Fatley Nuclear Plant, Unit 1	212	50-114	Catawba Nuclear Station, Unit 2	300 305
50-352	Limetick Generating Station, Unit 1	215	50-416	Grand Gulf Nuclear Station, Unit 1	310
50-353	Limerick Generating Station, Unit 2	221	50-417	Grand Gulf Nuclear Station, Unit 2	
50-354	Hope Creek Nuclear Station, Unit 1	227	50-423	Millstone Nuclear Power Station, Unit 3	312
50-355	Hope Creek Nuclear Station, Unit 2	230	50-424	Vogtle Electric Generating Plant	314
50-358	William H. Zimmer Nuclear Station, Unit 1	230	50-425	Vogtle Electric Generating Plant	316
50-361	San Onofre Nuclear Station, Unit 2	232	50-433	UC-Santa Barbara Research Reactor	319 319
50-362	San Onofre Nuclear Station, Unit 3	236	50-434	Surry Power Station, Unit 3	
50-364	Joseph M. Farley Nuclear Plant, Unit 2	241	50-435	Surry Power Station, Unit 4	319
50-366	Edwin I. Hatch Nuclear Plant, Unit 2	244	STN-50-437	Floating Nuclear Plant	319
50-367	Bailly Generating Station	247	50-438	Bellefonte Nuclear Plant, Unit 1	319
50-368	Arkansas Nuclear One, Unit 2	247	50-439	Bellefonte Nuclear Plant, Unit 2	322
50-369	William B McGuire Nuclear Station,	250	50-440	Perry Nuclear Power Plant, Unit 1	324
	Unit I		50-441	Perry Nuclear Power Plant, Unit 2	328
50-370	William B. McGuire Nuclear Station, Unit 2	251	50-443	Seabrook Nuclear Station, Unit 1	332
50-373	LaSalle County Station, Unit 1	254	50-444	Seabrook Nuclear Station, Unit 2	335
50-374	LaSaile County Station, Unit 2	257	50-445	Comanche Peak Steam Electric Station, Unit 1	338
50-382	Waterford Generating Station, Unit 3	260	50-446	Comanche Peak Steam Electric Station,	343
50-387	Susquehanna Steam Electric Station, Unit 1	264	STN-50-447	Unit 2 GESSAR-238	347

Docket	Name	Page	Docket	Name	Page
STN-50-454	Byron Station, Unit 1	348	STN-50-556	Black Fox Station, Unit 1	404
STN-50-455	Byron Station, Unit 2	352	STN-50-557	Black Fox Station, Unit 2	404
STN-50-456	Braidwood Station, Unit 1	355	STN-50-566	Yellow Creek Nuclear Plant, Unit 1	404
STN-50-457	Braidwood Station, Unit 2	357	STN-50-567	Yellow Creek Nuclear Plant, Unit 2	405
50-458	River Bend Station, Unit 1	359	STN-50-584	GIBBSAR, Gibbs & Hill	405
50-459	River Bend Station, Unit 2	362	Domestic Lice	nsing of Special Nuclear Material — Docket 70	
50-460	WPPS\$ Nuclear Project, Unit 1	364	70-0008	Battelle Memorial Institute,	405
50-461	Clinton Power Station, Unit 1	365		Columbus, OH	
50-462	Clinton Power Station, Unit 2	367	70-0025	Rockwell International Corp., Canoga Park, CA	405
50-463	Fulton Generating Station, Unit 1	367	70-0027	Babcock & Wilcox Co., Lynchburg, VA	405
50 464	Fulton Generating Station, Unit 2	367	70-0135	Babcock & Wilcox Co., Apollo, PA	405
50-466	Allens Creek Nuclear Station, Unit 1	367	70-0143	Nuclear Fuel Services, Inc., Erwin, TN	405
50-467	Allens Creek Nuclear Station, Unit 2	367	70-0221	General Dynamics Corp., Groton, CT	406
STN-50-470	CESSAR System 80	367	70-0364	Babcock & Wilcox Co , Apollo, PA	406
50-471	Pilgrim Nuclear Power Station, Unit 2	367	70-0371	UNC Naval Products, Inc., Uncasville, CT	407
STN-50-482	Wolf Creek Generating Station	367	70-0687	Union Carbide Corp, Tuxedo, NY	407
STN-50-483	Callaway Plant, Unit I	372	70-0698	Westinghouse Electric Corp.,	407
STN-50-486	Callaway Plant, Unit 2	376		Pittsburgh, PA	
50-496	Montague Nuclear Power Station, Unit 1	376	70-0710	Merrimack College, North Andover, MA	407
50-497	Montague Nuclear Power Station, Unit 2	377	70-0734	GA Technologies, Inc., San Diego, CA	407
STN-50-498	South Texas Project, Unit 1	377	70-0754	General Electric Co , Pleasanton, CA	407
STN-50-499	South Texas Project, Unit 2	380	70-0820	United Nuclear Corp., Wood River Junction, RI	407
STN-50-508	WPPSS Nuclear Project, Unit 3	384	70-0824	Babcock & Wilcox Co., Lynchburg, VA	408
STN-50-509	WPPSS Nuclear Project, Unit 5	385	70-0324		
50-513	WPPSS Nuclear Project, Unit 4	386	10.0323	Kerr-McGee Nuclear Corp., Oklahoma City, OK	408
STN-50-518	Hartsville Nuclear Plant, Unit 1	386	70-1100	Combustion Engineering, Inc.,	408
TN-50-519	Hartsville Nuclear Plant, Unit 2	386	70 1112	Windsor, CT	400
50-522	Skagit Nuclear Power Project, Unit 1	386	70-1113	General Electric Co., Wilmington, NC	408
50-523	Skagit Nuclear Power Project, Unit 2	387	70-1143	Westinghouse Electric Corp., Pittsburgh, PA	408
STN-50-528	Palo Verde Nuclear Station, Unit 1	387	70-1151	Westinghouse Electric Corp.,	408
STN-50-529	Palo Verde Nuclear Station, Unit 2	393	70.1102	Pittsburgh, PA	400
STN-50-530	Palo Verde Nuclear Station, Unit 3	398	70-1193	Kerr-McGee Nuclear Corp., Oklahoma City, OK	408
50-537	Clinch River Breeder Reactor	402	70-1201	Babcock & Wilcox Co., Lynchburg, VA	409
STN-50-546	Marble Hill Nuclear Station, Unit 1	403	70-1257	Exxon Nuclear Co., Inc., Richland, WA	409
STN-50-547	Marble Hill Nuclear Station, Unit 2	404	70-1308	General Electric Co., San Jose, CA	409

Docket	Name	Page	Docket	Name	Page
70-1362	Hahnemann Medical College & Hospital, Philadelphia, PA	409	71-6058	Model B-3, U.S Ecology, Inc	412
70-1389	St Francis Hospital, Evanston, IL	409	71-6206	Model B, Babcock, & Wilcox Co	412
70-1465	St Anthony Hospital, Rockford, IL	409	71-6387	Model 60, Battelle Memorial Institute, Pacific Northwest Laboratory	412
70-2077	Suburban General Hospital, Norristown, PA	409	71-6574	Model: HN-200, Hittman Nuclear &	412
70-2134	Grandview Hospital, Dayton, OH	409	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Development Corp.	
70-2362	Brockton Hospital, Brockton, MA	409	71-6601	Model, CNS 8-120, Chem-Nuclear Systems, Inc.	412
70-2896	McKay-Dee Hospital Center, Ogden, UT	409	71-6679	Model 6679, U.S Ecology, Inc	412
70-2910	Tennessee Valley Authority,	410	71-6717	Model 6717-B, Gamma Industries	413
	Chattanooga, TN		71-9001	Model: IF-300, General Electric Co.	413
70-2932	Texas Utilities Generating Co., Dallas, TX	410	71-9009	Model FL 10-1, General Electric Co	413
70-2946	Louisiana Power & Light Co.,	410	71-9032	Model: 650, Technical Operations, Inc.	413
	New Orleans, LA		71-9033	Model: 660 & 660E, Technical Operations,	413
70-2950	Washington Public Power Supply System, Richland, WA	410	m. 20m.	Inc.	
70-2955	Edlow International Co., Washington, DC	410	71-9071	Model: AP-101, ANEFCO, Inc.	413
70-2960	Kansas Gas & Electric Co., Wichita, KS	410	71-9080	Model. HN-600, NUPAC 7-100 & CNS 7-100, Hittman Nuclear & Development Corp	413
70-2986	Weber State College, Ogden, UT	410	71-9089	Model. HN-100S, Hittman Nuclear &	413
70-2988	Philadelphia Electric Co., Philadelphia, PA	410	71.0102	Development Corp.	413
Packaging of Radioactive Material for Transport and			71-9103	Model: NLI-6502, Nuclear Assurance Corp.	413
Transportation of Radioactive Material Under Certain Conditions — Docket 71			71-9107 71-9108	Model. 771, Technical Operations, Inc. Model CNS 6-75, Chem-Nuclear Systems,	413
71-0001	ANEFCO, Inc.	410	71-9100	Inc	71.5
71-0019	Rochester Gas & Electric Corp.	411	71-9143	Model: 920, Technical Operations, Inc.	413
71-0085	Navy, Dept. of	411	71-9148	Model: 770, Technical Operations, Inc.	413
71-0133	Navy, Dept. of	411	71-9151	Model: HN-100, Series 3, Hittman Nuclear	413
71-0385	Navy, Dept. of	411	71-9156	& Development Corp. Model: IR-50, Industrial Nuclear Co.	414
71-0451	Cherne Contracting Corp.	411	71-9160	Model: 20-VS & 40-VS, Gulf Nuclear, Inc.	414
71-0512	Nuclear Energy Services	411	71-9161	Model: R, Gulf Nuclear, Inc.	414
71-0513	Edlow International Co.	411	71-9168	Model: CNS 8-120B, Chem-Nuclear Systems,	414
71-4909	Model: GE-21PF-1, General Electric Co.	411	71 7100	Inc.	
71-4949	Model: UNC-1484, United Nuclear Corp.	411	71-9175	Model: CNS6-80B, Nuclear Packaging, Inc.	414
71-5026	Model: CNS 14-190, Chem-Nuclear	411	71-9181	Model: PAS-2, Nuclear Packaging, Inc.	414
71-5450	Systems, Inc. Model: RCC, -1, -2, -3, -4, Westinghouse	412	71-9184	Model: PAS-I, Nuclear Packaging, Inc.	414
71-3430	Electric Corp.	412	71-9186	Model: S-6213, Energy, Dept. of	414
71-5607	Model: T-2, Energy, Dept. of	412	71-9187	Model: 865, Technical Operations, Inc.	414
71-5800	Model: ORNL Tritium Target Container	412	Licensing of In	dependent Spent Fuel Storage — Docket 72	
71-5957	Model: BMI-1, Battelle Columbus Laboratory	412	72-0001	Morris Operations, General Electric Co.	414

		•	
	,		

ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Low Level Radwaste Disposal Sites - Docket 27			Rocky Mountain Energy Co.,	40-8380	5
Barnwell, SC, Chem-Nuclear Systems, Inc	27-047	1	Broomfield, CO		
Richland, WA, US Ecology, Inc	27-048	1	Tennessee Valley Authority, Chattanooga, TN	40-1341	2
Sheffield, IL, US Ecology, Inc	27-039	ι	Union Carbide Corp., Grand Junction, CO	40-0299	1
Domestic Licensing of Source Material - Docket	40		Uranerz USA, Inc., Casper, WY	40-8783	6
Atlas Minerals, Inc., Denver, CO	40-3453	4	Uranium Resources, Inc., Richardson, TX	40-8786	6
Automation Industries, Inc., Phoenixville, PA	40-6920	4	Western Nuclear, Inc., Jeffrey City, WY	40-1162	2
Bear Creek Uranium Co., Casper, WY	40-8452	5	Western Nuclear, Inc., Lakewood, CO	40-8684	6
Chemetron Corp., Chicago, IL	40-8724	6	Whittaker Metals, Los Angeles, CA	40-7455	5
Cotter Corp., Golden, CO	40-8511	5	Wyoming Mineral Corp., Lakewood, CO	40-8502	5
Energy Fuels Nuclear, Inc., Denver, CO	40-8681	6	Wyoming Mineral Corp., Lakewood, CO	40-8585	6
Fansteel, Inc., North Chicago, IL	40-7580	5	Domestic Licensing of Production and Utilizatio	n Facilities	
Getty Oil Co. — Petrotomics Co., Shirley Basin, WY	40-6659	4	Docket 50		245
Interior, Dept. of, Avondale, MD	40~1658	4	Allens Creek Nuclear Station, Unit 1	50-466	367
Kawecki Berylco Industries, Inc., Boyertown, PA	40-6940	5	Allens Creek Nuclear Station, Unit 2 Arkansas Nuclear One, Unit 1	50-467 50-313	367 135
Kerr-McGee Chemical Corp., Oklahoma City, OK	40-2061	4	Arkansas Nuclear One, Unit 2	50-368	247
Kerr-McGee Nuclear Corp., Okłahoma City, OK	40-8027	5	Bailly Generating Station Battelle Memorial Institute Research Reactor	50-367 50 6	247 7
Keir-McGee Nuclear Coip.,	40-8586	6	Beaver Valley Power Station, Unit 1	50-334	194
Oklahoma City, OK			Beaver Valley Power Station, Unit 2	50-412	292
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8768	6	Bellefonte Nuclear Plant, Unit 1	50~138	319
Minerals Exploration Co., Los Angeles, CA	40-8584	6	Bellefonte Nuclear Plant, Unit 2	50-439	322
Molycorp, Inc., Los Angeles, CA	40-8794	6	Big Rock Point Nuclear Plant	50-155	13
Nuclear Dynamics, Inc., Phoenix, AZ	40-8663	6	Black Fox Station, Unit 1	STN-50-556	404
Nuclear Metals, Inc., Concord, MA	40-0672	2	Black Fox Station, Unit 2	STN-50-557	404
Ogle Petroleum, Inc., Casper, WY	40-8745	6	Braidwood Station, Unit 1	STN 50-456	355
Pathfinder Mines Corp., Riverton, WY	40-2259	4	Braidwood Station, Unit 2	STN-50-457	357
Pathfinder Mines Corp., Shirley Basin, WY	40-6622	4	Brigham Young Univ. Research Reactor	50-262	57
Raytheon Co., Waltham, MA	40-1386	4	Browns Ferry Nuclear Power Station, Unit 1	50-259	47
Rio Algom Corp., Moab, UT	40-8084	5	Browns Ferry Nuclear Power Station, Unit 2	50-260	51

Name	Docket	Page	Name	Docket	Page
Browns Ferry Nuclear Power Station, Unit 3	50-296	114	Fulton Generating Station, Unit 1	50-463	367
Brunswick Steam Electric Plant, Unit 1	50-325	166	Fulton Generating Station, Unit 2	50-464	367
Brunswick Steam Electric Plant, Unit 2	50-324	163	General Atomic Co	50-89	11
Byron Station, Unit 1	STN-50-454	348	General Atomic Co.	50-163	15
Byron Station, Unit 2	STN-50-455	352	General Electric Test Reactor	50-70	10
Callaway Plant, Unit 1	STN-50-483	372	GESSAR-238	STN-50-447	347
Callaway Plant, Unit 2	STN-50-486	376	GIBBSAR, Gibbs & Hill	STN-50-584	405
Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	142	Grand Gulf Nuclear Station, Unit 1	50-416	305
Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	144	Grand Gulf Nuclear Station, Unit 2	50-417	310
Catawba Nuclear Station, Unit 1	50-413	293	H. B. Robinson Plant, Unit 2	50-261	55
Catawba Nuclear Station, Unit 2	50-414	300	Haddam Neck Plant	50-213	19
CESSAR System 80	STN-50-470	367	Hartsville Nuclear Plant, Unit 1	STN-50-518	386
Clinch River Breeder Reactor	50-537	402	Hartsville Nuclear Plant, Unit 2	STN-50-519	386
Clinton Power Station, Unit 1	50-461	365	Hope Creek Nuclear Station, Unit 1	50-354	227
Clinton Power Station, Unit 2	50-462	367	Hope Creek Nuclear Station, Unit 2	50-355	230
Comanche Peak Steam Electric Station,	50-445	338	Humboldt Bay Power Plant, Unit 3	50-133	11
Unit !	50.146	343	Indian Point Station, Unit 1	50-3	7
Comanche Peak Steam Electric Station, Unit 2	50-446	343	Indian Point Station, Unit 2	50-247	32
Cooper Nuclear Station	50-298	117	Indian Point Station, Unit 3	50-286	93
Crystal River Nuclear Plant, Unit 3	50-302	121	James A. Fitzpatrick Nuclear Power Plant	50-333	192
Davis-Besse Nuclear Power Station, Unit 1	50-346	210	Joseph M. Farley Nuclear Plant, Unit 1	50-348	212
Diablo Canyon Nuclear Power Plant, Unit 1	50-275	74	Joseph M. Farley Nuclear Plant, Unit 2	50-364	241
Diablo Canyon Nuclear Power Plant, Unit 2	50-323	160	Kewaunee Nuclear Power Plant	50-305	125
Donald C. Cook Nuclear Power Plant, Unit 1	50-315	138	La Crosse Boiling Water Reactor	50-409	288
Donald C. Cook Nuclear Power Plant, Unit 2	50-316	140	LaSalle County Station, Unit 1	50-373	254
Dresden Nuclear Power Station, Unit 1	- 50-10	7	LaSalle County Station, Unit 2	50-374	257
Dresden Nuclear Power Station, Unit 2	50-237	26	Limerick Generating Station, Unit 1	50-352	215
Dresden Nuclear Power Station, Unit 3	50-249	35	Limerick Generating Station, Unit 2	50-353	221
Duane Arnold Energy Center	50-331	190	Maine Yankee Atomic Power Plant	50-309	128
Edwin I. Hatch Nuclear Plant, Unit 1	50-321	150	Marble Hill Nuclear Station, Unit 1	STN-50-546	403
Edwin I. Hatch Nuclear Plant, Unit 2	50-366	244	Marble Hill Nuclear Station, Unit 2	STN-50-547	404
'nrico Fermi Atomic Power Plant, Unit 2	50-341	205	Massachusetts Institute of Technology Research Reactor	50-20	9
oating Nuclear Plant	STN-50-437	319		E0 204	111
ort Calhoun Station, Unit 1	50-285	91	Michigan State Univ. Research Reactor	50-294	111
ort St. Vrain Nuclear Generating Station	50-267	64	Midland Plant, Unit 1	50-329	173

Name	Docket	Page	Name	Docket	Page
Midland Plant, Unit 2	50-330	182	Rancho Seco Nuclear Generating Station	50-312	133
Millstone Nuclear Power Station, Unit 1	50-245	30	Reed College Research Reactor	50-288	99
Millstone Nuclear Power Station, Unit 2	50-336	198	River Bend Station, Unit 1	50-458	359
Millstone Nuclear Power Station, Unit 3	50-423	312	River Bend Station, Unit 2	50-459	362
Montague Nuclear Power Station, Unit 1	50-496	376	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	28
Montague Nuclear Power Station, Unit 2	50-497	377	Salem Nuclear Generating Station, Unit 1	50-272	71
Monticello Nuclear Generating Plant	50-263	58	Salem Nuclear Generating Station, Unit 2	50-311	131
National Bureau of Standards Reactor	50-184	16	San Onofre Nuclear Station, Unit 1	50-206	16
National Naval Medical Center	50-170	16	San Onofre Nuclear Station, Unit 2	50-361	232
Nine Mile Point Nuclear Station, Unit 1	50-220	23	San Onofre Nuclear Station, Unit 3	50-362	236
Nine Mile Point Nuclear Station, Unit 2	50-410	290	Saxton Nuclear Experimental Faculty	50-146	13
North Anna Power Station, Unit 1	50-338	201	Seabrook Nuclear Station, Unit 1	50-443	332
North Anna Power Station, Unit 2	50-339	203	Seabrook Nuclear Station, Unit 2	50-444	335
North Carolina State Univ. PULSTAR Reactor	50-297	117	Sequoyah Nuclear Plant, Unit 1	50-327	169
Oconee Nuclear Station, Unit 1	50-269	65	Sequoyah Nuclear Plant, Unit 2	50-328	171
Oconee Nuclear Station, Unit 2	50-270	67	Shearon Harris Nuclear Power Plant, Unit 1	50-400	281
Oconee Nuclear Station, Unit 3	50-287	96	Shearon Harris Nuclear Power Plant, Unit 2	50-401	2 85
Oyster Creek Nuclear Power Plant	50-219	21	Shoreham Nuclear Power Station	50-322	153
Palisades Nuclear Plant	50-255	45	Skagit Nuclear Power Project, Unit 1	50-522	386
			Skagit Nuclear Power Project, Unit 2	50-523	387
Palo Verde Nuclear Station, Unit 1	STN-50-528	387 393	South Texas Project, Unit 1	STN-50-498	377
Palo Verde Nuclear Station, Unit 2 Palo Verde Nuclear Station, Unit 3	STN-50-529		South Texas Project, Unit 2	STN-50-499	380
· ·	STN-50-530	398	St. Lucie Plant, Unit 1	50-335	196
Peach Bottom Atomic Power Station, Unit 1	50-171	16	St. Lucie Plant, Unit 2	50-389	270
Peach Bottom Atomic Power Station, Unit 2	50-277	79	Surry Power Station, Unit 1	50-280	83
Peach Bottom Atomic Power Station, Unit 3	50-278	224	Survy Power Station, Unit 2	50-281	87
Perry Nuclear Power Plant, Unit 1	50-440	324	Surry Power Station, Unit 3	50-434	319
Perry Nuclear Power Plant, Unit 2	50-441	328	Surry Power Station, Unit 4	50~435	319
Pilgrim Nuclear Power Station, Unit 1	50-293	109	Susquehanna Steam Electric Station, Unit 1	50-387	264
Pilgrim Nuclear Power Station, Unit 2	50-471	367	Susquehanna Steam Electric Station, Unit 2	50-388	2 67
Point Beach Nuclear Plant, Unit 1	50-266	62	Texas A&M Univ. Research Reactor	50-128	11
Point Beach Nuclear Plant, Unit 2	50-301	119	Three Mile Island Nuclear Station, Unit 1	50-289	99
Prairie Island Nuclear Station, Unit 1	50-282	89	Three Mile Island Nuclear Station, Unit 2	50-320	147
Prairie Island Nuclear Station, Unit 2	50-306	127	Trojan Nuclear Plant	50-344	207
Quad-Cities Station, Unit 1	50-254	43	Turkey Point Plant, Unit 3	50-250	37
Quad-Cities Station, Unit 2	50-265	59			

Name	Docket	Page	Name	Docket	Page
Turkey Point Plant, Unit 4	50-251	40	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	405
UC-Santa Barbara Research Reactor	50-433	319	Zion Nuclear Power Station, Unit 1	50-295	111
UCLA Training Reactor	50-142	12	Zion Nuclear Power Station, Unit 2	50-304	123
Univ of Florida Training Reactor	50-83	11			
Univ of Illinois Research Reactor	50-151	13	Domestic Licensing of Special Nuclear Material	– Docket 70	
Univ. of Kansas Research Reactor	50-148	13	Babcock & Wilcox Co., Apollo, PA	70-0135	405
Univ. of Lowell Research Reactor	50-223	26	Babcock & Wileox Co., Apollo, PA	70-0364	406
Univ. of Maryland Research Reactor	50-166	15	Babcock & Wileox Co., Lynchburg, VA	70-1201	409
Univ of Texas Research Reactor	50-192	16	Babcock & Wilcox Co., Lynchburg, VA	70-0824	408
Univ of Utah Research Reactor	50-72	11	Babcock & Wilcox Co., Lynchburg, VA	70-0027	405
Univ. of Utah Research Reactor	50-407	288	Battelle Memorial Institute, Columbus, OH	70-0008	405
Univ of Virginia Cavalier Reactor	50-396	279	Brockton Hospital, Brockton, MA	70-2362	409
Univ of Virginia Research Reactor	50-62	10	Combustion Engineering, Inc., Windsor, CT	70-1100	408
Univ. of Washington Research Reactor	50-139	12	Edlow International Co., Washington, DC	70-2955	410
Vermont Yankee Nuclear Power Station	50-271	69	Exxon Nuclear Co . Inc , Richland, WA	70-1257	409
Virgil C Summer Nuclear Station, Unit 1	50-395	277	GA Technologies, Inc., San Diego, CA	70 0734	407
Virginia Polytechnic Institute Training Reactor	50-124	11	General Dynamics Corp., Groton, CT	70-0221	406
Vogtle Electric Generating Plant	50-424	314	General Electric Co., Pleasanton, CA	70-0754	407
Vogtle Electric Generating Plant	50-425	316	General Electric Co., San Jose, CA	70-1308	409
Waterford Generating Station, Unit 3	50-382	260	General Electric Co., Wilmington, NC	70-1113	408
Watts Bar Nuclear Plant, Unit 1	50-390	272	Grandview Hospital, Dayton, OH	70-2134	409
Watts Bai Nuclear Plant, Unit 2	50-391	275	Hahnemann Medical College & Hospital, Philadelphia, PA	70-1362	409
West Valley Reprocessing Plant	50 201	16	Kansas Gas & Electric Co., Wichita, KS	70-2960	410
Westinghouse Critical Experiment	50 87	11	Keri-McGee Nuclear Corp.,	70-1193	408
William B McGuire Nuclear Station, Unit 1	50-369	250	Oklahoma City, OK	70-1173	400
William B McGuire Nuclear Station, Unit 2	50-370	251	Kerr-McGee Nuclear Corp., Oklahoma City, OK	70-0925	408
William H. Zummer Nuclear Station, Unit 1	50-358	230	Louisiana Power & Light Co.,	70-2946	410
Wolf Creek Generating Station	STN-50-482	367	New Orleans, LA		,,
WPPSS Nuclear Project, Unit 1	50~460	364	McKay-Dee Hospital Center, Ogden, UT	70-2896	409
WPPSS Nuclear Project, Unit 2	50-397	279	Menimack College, North Andover, MA	70-0710	407
WPPSS Nuclear Project, Unit 3	STN-50-508	384	Nuclear Fuel Services, Inc., Erwin, TN	70-0143	405
WPPSS Nuclear Project, Unit 4	50-513	386	Philadelphia Electric Co , Philadelphia, PA	70-2988	410
WPPSS Nuclear Project, Unit 5	STN-50-509	385	Rockwell International Corp., Canoga Park, CA	70-0025	405
Yankee-Rowe Nuclear Power Station	50-29	9	St. Anthony Hospital, Rockford, IL	70-1465	409
Yellow Creek Nuclear Plant, Unit 1	STN-50-566	404	St. Francis Hospital, Evanston, IL	70-1389	409

φ,

Name	Docket	Page	Name	Docket	Page
Suburban General Hospital, Norristown, PA	70-2077	4()9	Model CNS 6-75 Chem-Nuclear Systems.	71-9108	417
Tennessee Valley Authority, Chattanooga TN	70 2910	410	Inc Model CNS 8-120, Chem-Nuclear Systems	71 6601	413
Texas Utilities Generating Co , Dallas, TX	70-2932	410	lne.		
UNC Navat Products, Inc., Uncasville, CT	70-0371	407	Model CNS 8-120B, Chem-Nuclear Systems, Inc	71-9168	-11-
Union Carbide Corp., Tuxedo, NY	70-0687	407	Model CNS6-80B Nuclear Packaging Inc	71-9175	41
United Nuclear Corp , Wood River Junction, RI	70-0820	407	Model FL 10-1, General Flectric Co	71-9009	410
Washington Public Power Supply System, Richland, WA	70-2950	410	Model GL-21PF-1, General Flectric Co Model HN-100, Series 3, Hittman Nuclear &	71-4909 71-9151	411 413
Weber State College, Ogden, UT	70-2986	410	Development Corp.		
Westinghouse Electric Corp., Pittsburgh, PA	70-1143	408	Model HN-100S, Hutman Nuclear & Development Corp	71-9089	417
Westinghouse Electric Corp., Pittsburgh, PA	70-1151 70-0698	408 407	Model HN-200, Hittman Nucleai & Development Corp	71-6574	412
Westinghouse Electric Corp., Pittsburgh, PA Packaging of Radioactive Material for Transport		407	Model HN-600, NUPAC 7-100 & CNS 7-100, Hittman Nuclear & Development Corp.	71-9080	411
Transportation of Radioactive Material Under Conditions — Docket 71			Model 1F-300, General Electric Co	71-9001	-41
ANEFCO, Inc.	71-0001	410	Model IR-50, Industrial Nuclear Co	71-9156	41
Cherne Contracting Corp	71-0451	411	Model NLI-6502, Nuclear Assurance Corp	71-9103	-41 ,
Edlow International Co.	71-0513	411	Model ORNL Tritium Target Container	71-5800	413
Model: 20-V\$ & 40-V\$ Gulf Nuclear, Inc.	71-9160	414	Model PAS-1, Nuclear Packaging, Inc.	71-9184	41
Model: 60, Battelle Memorial Institute, Pacific Northwest Laboratory	71-6387	412	Model, PAS-2, Nuclear Packaging, Inc	71-9181	41-
Model 650, Technical Operations, Inc.	71-9032	413	Model: R, Guli Nuclear, Inc.	71-9161	41-
Model: 660 & 660E, Technical Operations, Inc.	71-9033	413	Model RCC, -1, -2, -3, -4, Westinghouse Flectric Corp.	71-5450	112
Model, 6679, U.S. Ecology, Inc.	71-6679	412	Model, S-6213, Fnergy, Dept. of	71-9186	41
Model: 6717-B Gamma Industries	71-6717	413	Model T-2 Energy, Dept. of	71-5607	413
Model. 770, Technical Operations, Inc.		413	Model, UNC-1484, United Nuclear Corp.	71-4949	411
•	71-9148		Navy, Dept. of	71-0085	411
Model: 771, Technical Operations, Inc.	71-9107	413	Navy, Dept. of	71-0133	413
Model: 865, Technical Operations, Inc.	71-9187	414	Navy, Dept. of	71-0385	-111
Model: 920, Technical Operations, Inc.	71-9143	413	Nuclear Energy Services	71-0512	411
Model: AP-101, ANEFCO, Inc	71-9071	413	Rochester Gas & Electric Corp.	71-0019	- 41 1
Model B, Babcoek & Wilcox Co.	71-6206	412			
Model: B-3, U.S. Ecology, Inc.	71-6058	412			
Model: BMI-1, Battelle Columbus Laboratory	71-5957	412	Licensing of Independent Spent Fuel Storage —	Docket 71	
Model: CNS 14-190, Chem-Nuclear Systems, Inc.	71-5026	411	Morus Operations, General Electric Co.	72-0001	414



LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-039 SHEFFIELD, IL, U S ECOLOGY, INC

8402060077 Forwards State of WA Amend 16 to US Ecology License WN-1019-2 for Richland low level weste disposal site NUSSBAUMER, D. A. Assistant Director for State Agreements Programs 84701/13 DAVIS. J. Office of Nuclear Material Sefety & Safeguards, Director DENTON, H. Office of Nuclear Reactor Regulation, Director DEYQUNG, R. Director's Office, Office of Inspection and Enforcement 31pp 22110 026

840210033B Forwards proposed agenda for 840216-17 meeting w/Btate of IL Geological Survey and atty general ofc to define current monitoring program & to assess long-term program Comments requested by 840207 LABH.TR Illinois. State of 84/01/31 SHAFFNER.J Division of Waste Management 5pp 22208 355

8402160237 Notice of appearance in proceeding Withdrawa) of appearance for BA Chasnoff & Certificate of Bvc encl GOOD[E.J S Illinois. State of 84/02/10 5pp 222/4 336

8408220008 Forwards summary of 840119 meeting of steering committee on tritium migration investigation at site GAYNOR, RK US Ecology, Inc. (formerly Nuclear Engineering, Inc.) 84/02/13 US Ecology, Inc. (formerly Nuclear Engineering, Inc.) 3pp 22335 213

8402220294 Forwards addendum to IE Insp Rept 27-0039/83-01, consisting of results of liquid samples collected & split w/ representatives during insp PAPERIELLO,C J Region 3, Office of Director 84/02/17 SCOVILLE,J J U S Ecology, Inc (formerly Nuclear Engineering, Inc.) ip 22335 348

--8402220277 Addendum to IE Insp Rept 27-0039/83-01, consisting of results of liquid samples collected during insp * Region 3, Office of Director 84/02/17 ip 22335, 349

8402280386 Notice of appearance in proceeding Certificate of Syc encl FONNER, R. L. Regulations Division 84/02/27 3pp 22402 252,

DOCKET 27-047 BARNWELL, SC, CHEM-NUCLEAR SYSTEMS, INC

8402020214 Forwards review & comments re draft NRC Licence 12-13836-01 Conditions imposed by by-product and source matl license issued by State of SC should be adopted verbatum by NRC to avoid conflict between two licenses SHEALY, H G South Carolina, State of 84/01/10 NUSBBAUMER, D A Assistant Director for State Agreements Programs 4pp 22062 150

B402060047 Forwards comments on radwaste disposal License 12-13536-01, per request PAPPER PROPERTY OF THE PROP

8402060101 Forwards comments on draft matls license for Chem-Nuclear Bys.Inc GIBBON, A F Division of Engineering & Operational Programs 84/01/19 HIGGINBOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch 3pp 22110.023

DOCKET 27-048 RICHLAND, WA, U B ECOLOGY, INC

840202020 Forwards SNM receipt & burial rept for Dec 1983 & rept of isotopic activity. H/o encl WRIGHT US Ecology, Inc (formerly Nuclear Engineering, Inc.), 84/01/12 BROWNING, B Low Level Waste Licensing Branch ip PROAD 232 8402170305 Responds to 830106 request to dispuse of liquid scintillation wastes from UBOS containing trace amounts of Pu-239 Approval granted to bury waste in accordance w/Licenss 16-19204-01 & site operating procedures H1001NB0THAM.L Low-Level Waste & Urenium Recovery Projects Branch 84/01/31 WALLER.W K U S Ecology. Inc (formerly Nuclear Engineering, Inc.) ip 22313 222

8402220226 Forwards Waste Packaging Insp Rept 15000046/84-01 on B40201-09 Three violations of DOT/NRC regulations noted MENSLAMBKI,F A Region 5: Defice of Director 84/02/17 GRELLA,A Safeguards & Materials Program Branch 1p 22340 316

--B402220232 Waste Packaging Insp Rept 15000046/84-01 on B40201-09 Violations noted slice hole found on lower side of Drum 1270, Drum 1284 not labeled w/waste classification label & rectangular hole found on lower side of Drum 1145 ELSEN,M J. THOMAS.R D. WENELAWSKI,F A. Region 5, Office of Director 84/02/16 17pp 22340 317

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0299 UNION CARBIDE CORP : GRAND JUNCTION: CO

8402210284 Forwards "Groundwater Hydrology Near Inactive Tailings," per 830216 agreement Seepage from inactive tailings area indicated but neutralizing capacity to prevent lowering of pH values adequate LyONS, P J Union Carbide Corp 84/01/13 ENGLEMAN, R Wyoming, State of 1p 22344 241

--8402210285 "Groundwater Hydrology Near Inactive Tailings." HOWLETT.L H , WALTERMIRE, M O , HOFFMAN. C L. Hydro-Engineering 83/1/30 338pp 23344 242

8402230151 Forwards "Berm Sump Monitoring riogram," per License Condition 42(1) Program includes plan for transporting embankment seepage water to A-9 tailings sys LYONS, P J L Union Carbide Corp. 83/12/05. PETTEMOILL, H Uranium Recovery Field Office 3pp 22371 885

--8402230157 "Berm Sump Monitoring Program " W/one oversize map Aperture card is available in PDR * Union Carbide Corp 83/12/02 3pp. 22371·187

8402230264 Forwards application for parmit to modify A-9 Collection Sys 83-149 Mpd necessary to increase pumping rate so that hydraulic gradient in vicinity of tailings area will be reversed Wione oversize map Aperture card available in PDR LYONS, P J L Union Carbids Corp 83/12/07 HERMANSKY, J Wyoming, 9tate of 3pp 22371 190

8402230258 Forwards application for State of WY groundwater pollution control permit, allowing sulfuric acid to drip into drip wells near seepage collection sys LYONS, P. J. L. Union Carbide Corp 84/01/11 LAUDEN, K. Wyoming. State of 6pp 22371 148

B402210423 Forwards revised Page i of App E to "Application for Amend to Increase Capacity of A-9 Tailings Area." Installation of addl drain line in tailings area preferred before B40301. Permission to start const should be given promptly LYONS.P. J. Union Carbide Corp. B4/01/20. PETTENOILL, H. Uranium Recovery Field Office ip 22323 339.

--8402210424 Rev 3:Page 1.of App E to application for amend to License 8UA-648 to increase capacity of A-9 tailings area.

* Union Carbide Corp 84/01/31. ip 22323 340.

1

- '30076 Forwards addl info re 830921 supplemental application for ond to License SUA-648 to increase capacity of A-9 lings area in response to NRC request W/two oversize as Aperture cards are available in PDR NRS.P J L Union Carbide Corp 84/01/26 PETTENGILL, H Uranium overy Field Office 30pp 22365 066
- 12230086 "Predicted Time to Obtain Reversal for Various Collection tates " HOFFMAN.O L Hydro-Engineering 83/12/31 14pp 22365 097
- 02230091 "Drip Sys Design to A-9 Groundwater Seepage Collection Sys "
 40FFMAN.O L Hydro-Engineering 83/12/31 31pp 22365 111
- 140097 EN-B3-070A on B31027, notice of violation & proposed position of civil penalties in amount of \$4,000 to be sued Action based on eight apparent violations reseatdown in mgt oversight & radiation safety program ACK,E. AXELRAD. J Director's Office. Office of Inspection and Forcement B4/02/10 ip 22217 213
- 140317 Discusses IE ipsp on 630823-25 & forwards order imposing 14031/ Discusses le insp on 830823-25 & ropwards order imposing vil monetary penalties in amount of \$4.000 re breakdown in b control & oversight of radiation safety program YOUNG,R C Director's Office, Office of Inspection and forcement 84/02/10 SHORTRIDGE,E W Union Carbide Corp 3pp
- 02140324 Order imposing civil monetary penalties in amount of \$4,000 re breaksown in mgt control & oversight of radiation safety
- program
 DEYQUNG.R C Director's Office, Office of Inspection and
 Enforcement 84/02/10 Union Carbide Corp 9pp 22230 311
- ET 40-0672 NUCLEAR METALS, INC , CONCORD, MA
- 020271 Ack receipt of B30B19 ltr re B30B02 mgt meeting & IE Insp pt 40-0672/B3-02 Proposed audit program inadequate in veral areas Revised audit program due within 30 days RTIN, T T Division of Engineering & Technical Programs 84/01/1 UFFIN, W B Nuclear Hetals, Inc 2pp 22055 206
- 02020274 Forwards updated audit program discussing performance & frequency of audits of radiological work practices.per NRC request VUMBACO.F J Nuclear Metals, Inc. 93/08/19 MARTIN.T T
- request
 VUMBACO.F J Nuclear Metals, Inc 93/08/19 MARTIN.T 1
 Division of Engineering & Technical Programs 27pp 220 22055 20B
- 290266 Forwards summary of 830727 IE enforcement conference & 290266 Forwards summary of 83072/ It enforcement conference & D802 mpt meeting in King of Prussia.PA re violations noted B30525-27 & 0608-10 insp of License SMB-177 Corrective tion to prevent exposures remphasized RTIN,T. T Division of Engineering & Technical Programs 84/02/15 UFFIN.W B Nuclear Metals. Inc 6pp 22426 303
- ET 40-1142 WESTERN NUCLEAR, INC , JEFFREY CITY, WY
- 230203 Comments on environ monitoring rept for First Half 1983 No REIA, P J. PETTENGILL, H J. Uranium Recovery Field Office 701/13 Uranium Recovery Field Office 4pp 22379 164
- ET 40-1341 TENNESSEE VALLEY AUTHORITY, CHATTANDOGA, TN
- DBOO43 Further response to FDIA request for documents re cleanup & cision to close U mill.in Edgemont.SD Forwards App A.B & C cuments Review of remaining documents subj to request
- progress LTON, J M progress LTCN,J M Division of Rules and Records 83/11/01 GARBUS,M ankfurt, Garbus, Klein & Belz 10pp 22167-009
- 12180235 Discusses 791107 telcon re program to assess required offsite remedial action for Edgemont 9D NRC has no objections to TVA procedures for soil sampling FRAGER, E. A. Uranium Recovery Licensing Branch 79/11/14 (ALLEMEYN, V. South Dakota, State of lp. 22169-259
- 33250487 Discusses working level measurements in Edgement, SD Bradford residence has highest working level determinations Other nonitored structures do not appear to be of immediate health sisk concern TADIE, G Uranium Recovery Licensing Branch 80/03/06 SCARAND, R A Uranium Recovery Licensing Branch 20p 22169 272

- --8402080048 Ack receipt of Feb 1981 monthly rept for Edgemont cleanup action program "Proceedings of Workshop on Radiological Surveys in Support of Edgemont Cleanup Action Program" will Surveys in Support of Edgemont Cleanup Action Program" Will be issued as NURSE/CR-2003 EADIE G Uranium Recovery Licensing Branch FIN 8-2217 81/06/01 WOGMAN,N A Battelle Memorial Institute, Pacific Northwest Laboratory 2pp 22169 025
- ~-8402080050 Discusses analysis of S B 2358 NRC FY81 Authorization Rill Section Edgemont, SD Bill as reported on 800515, did not address responsibility for actual remediation work Major changes established by amends listed BRAUN. J G Licensing Process & Integration Branch 80/08/28 MARTIN, J B Division of Waste Management 6pp 22167 311
- -8402080052 Discusses NRC program for Edgemont mill tailings.per 800429 meeting
 LOUSLEY, D J Program Support Branch 80/09/30 DAVIS, J G
 Office of Nuclear Material Safety & Safeguards, Director ip
 22169 317
- --8402080056 Forwards data obtained on soils from Edgement school yerd, per 801027 telcom Data indicates that matl found at specific locations is primarily tailings WDGMAN,NA Battelle Memorial Institute, Pacific Northwest Laboratory 80/10/27 SCARANO,RA Office of Nuclear Material Safety & Safeguards.Director 2pp 22167 318
- --8402080057 Draft "Radiological Surveys at Edgemont.8D, 1980 "

 * Battelle Memorial Institute, Pacific Northwest Laboratory
 80/12/31 15pp 22169 320
- ---8402080061 Requests assistance in obtaining clarification from appropriation committees if problem exists in continuing Edgemont cleanup program W/o stated encl MARTIN, J B Division of Waste Management FIN B-2217 81/01/09 KAMMERER. C Office of Congressional Affairs 1p 22169 335
- --B4020B0063 Notifies that author assumed responsibilities of State
 Radiation Control Program director on 80091B Duties
 associated w/Edgemont U mill/Edgemont offsite cleanup
 project & general radiation activities
 BRICH, R South Dakota, State of 81/01/14 MCGRATH, J Assistant
 Director for State Agreements Programs 1p 22169 027
- --8402080067 Lists items to be discussed during mouting w/Senator McGovern re U mining & milling in State of SD CARPENTER R, MCGOVERN Senate 79/06/14 SCARAND R NRC -Detailed Affiliation Given 2pp 22167 046 SCARANDIR NRC - No
- --8402080069 Submits third status rept re Edgement cleanup Summary of BNML radiological surveys through Aug 1981 encl SCARANO, R A Uranium Recovery Licensing Branch 81/10/15 MARTIN, J B Division of Waste Management 5pp 22169 334
- --8402080074 Ack receipt of 741227 ltr re U mill tailings at Edgement.SD Phase II study must be conducted before further action taken Excerpts from "Evaluation of Impact of Mines Development.Inc" enc.) Development, Inc. enc.; KNEIP, R F Sputh Dakota, State of 76/12/30 GDSSICK, L V Office of the Executive Director for Operations Sipp 22 22169 048
- --8402080075 Discusses status of contracted work Summary of disequilibrium in Edgement soils almost complete Related info encl into eact WOGMAN, N A Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2214 82/02/01 EADIE, G G Uranium Recovery Licensing Branch 9pp 22169 341
- --8402080078 Discusses Governor Kneip 761108 concerns re Phase II studies If ERDA includes Edgemont mill in Phase II studies, Kneip concerns will be resolved KERR. G W Assistant Director for State Agreements Programs 76/11/18 RYAN.R O Office of State Programs, Director ip 22169 079
- ~-8402080081 Draft "Edgemont Remedial Action Program," annual interim rept.1981 JACKSON,P D , YOUNG,J A , THOMAS,V W Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2217 82/05/31 NRC - No Betailed Affiliation Given 41pp 22169 350
- --8402080085 Requests Phase II designation for Edgemont U mill Supporting documentation encl.

 KNEIP,R F South Dakota. State of 76/11/08 GOSSICK.L D

 Office of the Executive Director for Operations LIVERMAN.

 Energy Research & Development Admin (Presently DOC) 8pp

 22169 080 LIVERHAN, J L

- --8402080091 Discusses NRC 760826 visit to Edgement SD U milling plant Tailings piles generated by past operations found in various stages of reclamation Detailed plan to stabilize loose sand tailings area requested by 761115
 ROUSE, L C Fuel Process & Fab Branch (Pre 790727) 76/09/17
 WILLIAMS, G Tennesses Valley Authority 2pp 22169 088
- --8402080097 "Edgemont Remedial Action Program," monthly rept for Sept 1980 JACKBON,P O. OLBEN,K B., MAUCH,M L. Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2217 80/09/30 NRC - No Detailed Affiliation Given 3pp 22170 106
- --B4020B0099 Discusses interim stabilization of sand tailings at Edgemont.SD U mill, per 760901 conversation Concurs w/U9
 Bureau of Mines article that combination chemical-vegetative method of stabilization best Related info encl
 CAMERON,R E Argonne National Laboratory 76/09/02 SCARAND.R
 Fuel Process & Fab Brench (Pre 790727) App 22169 090
- ---8402080104 "Edgement Remedial Action Program," monthly rept for Oct 1980. WOGMAN, N A. JACKSON, P O., QLBEN, K β Battelle Memorial Institute, Pacific Northwest Laboratory FIN β-2217 80/10/31 NRC - No Detailed Affillation Qiven 4pp 22170 109
- ~-8402080104 Ack receipt of 760811 transmittal of Governor Kneip ltr to Senator McGovern expressing concern re environ impact of tailings from past U milling operations at Edgemont.8D Mill status clarified.

 GDSSICK,L V Office of the Executive Director for Operations 76/09/08 MMPHY.9 F Congress, Joint Committee on Atomic Energy 3pp 22149 094
- --8402080112 "Edgemont Remedial Action Program." Itr rept for Nov 1980 WOGMAN.N A , JACKBON.P G . THOMAS.V W Battelle Memorial Institute. Pacific Northwest Laboratory FIN D-2217 81/01/13 EADIE.0 Q Uranium Recovery Licensing Branch 6pp 22170 113
- --8402080ii5 Forwards Governor Kneip request that site of Mines Development Inc U mill in Edgemont 9D be included in ERDA study list of inactive U mill sites Appropriate action requested ABOUREZK.J Senate 76/09/16 PABTORE, J Congress. Joint Committee on Atomic Energy 4pp 22169 097
- --8402080117 "Edgemont Remedial Action Program." monthly rept for Dec 1780 WOGMAN,N A. JACKSON,P O., OLSEN,K B. Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2217, 80/12/31 NRC - No Detailed Affiliation Given Opp 22170 119
- --8402080120 Responds to 750805 ltr re TVA mill at Edgemont, SD Since TVA is govt corp. mill would continue to operate under NRC license even though SD became Agreement State EIB must accompany issuance of license for U mill KERR, 9, W NRC No Detailed Affiliation Given 75/09/12 NELSON, M O Bouth Dakota, State of 1p 22167 103
- --8402080122 "Edgement Remedial Action Program," ltr rept for Jan 1981 THOMAS.V.W., WOOMAN.N A Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2217-0 81/02/13 EADIE.G G Uranium Recovery Licensing Branch 7pp 22170 125
- --8402080127 "Edgement Remedial Action Program," monthly rept for Feb 1791 WOGMAN,N A., JACKBON,P D. Battelle Memorial Institute, Pacific Northwest Laboratory. FIN 8-2217-0 81/02/28 NRC - No Detailed Affiliation Given. 5pp 22170:132
- --8402080133 "Edgement Remedial Action Program," monthly rapt for May 1981. HOGMAN,N A , JACKBON,P. O Battelle Memorial Institute, Pacific Northwest Laboratory. FIN 8-2217-0 B1/05/31 NRC - No Detailed Affiliation Given 8pp 22170-137
- --8402080137 "Edgemont Remadial Action Program," monthly rept for June 1781. WOMMAN,N A. JACKBON,P O Battella Mamorial Institute, Pacific Northwest Laboratory, FIN 8-2217-0 81/06/30 NRC - No Detailed Affiliation Given, 7pp 22170 145
- --8402080138 Responds to 750425 suggestion that TVA develop E18 for proposed U milling operation at Edgement, 8D TVA plans to submit environ info by 750801.

 DIRCKS.W J Office of the Executive Director for Operations 75706/09. GREEN, J A Environmental Protection Agency ip 22169.104

- --B4020B0144 "Edgement Remedial Action Program," ltr rept for Jul 1961 JACKSON,P O , PERKINS,R W . MOGMAN.N A Battelle Memorial Institute. Pacific Northwest Laboratory FIN B-2217 B1/00/10 EADIE.G G Uranium Recovery Licensing Branch 10pp 22170 152
- --8402080153 "Edgemont Remedial Action Program." Itr rept for Aug 1981 JACKSON,P O , PERKINS,R W , WOGMAN N A Dattelle Memorial Institute, Pacific Northwest Laboratory FIN B-2217 81/09/11 EADIE,G G Uranium Recovery Licensing Branch 9pp 22170 162
- --8402080136 "Edgement Remedial Action Program," 1tr rept for Sept 19rt JACKSON,P O , PERKING,R W , WOOMAN,N A Battelle Memorial Institute, Pacific Northwest Leboratory FIN B-2217 B1/10/07 EADIE,G G Uranium Recovery Licensing Branch 9pp 22170 179
- --8402080159 "Edgement Remedial Action Program," ltr rept for Feb 198. JACKSON,P G , PERKINS,R W . WOGMAN.N A Battelle Memorial Institute. Pacific Northwest Laboratory FIN B-2217 82/03/11 EADIE,G G Uranium Recovery Licensing Branch 10pp 22170 180
- --8402080160 "Environ Evaluation of Mines Development, Inc & Vanadium Millings Operations at Edgemont SD " * Environmental Protection Agency 9A/TSB-18 73/04/30 44pp 22169 105
- --8402080163 "Edgemont Remedial Action Program," monthly rept for May 1962 WOOMAN,N A , JACKSON,P O Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2217 82/05/31 NRC - No Detailed Affiliation Given 15pp 22170 170.
- --8402080168 "Edgement Remedial Action Program," ltr rept for Jul 1982 JACKSON,P O , PERKINS.R W , WGGMAN,N A Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2217 82/08/17 FLORY.C A Uranium Recovery Licensing Branch 12pp 22170 219
- ---8402080172 Discusses status of U mill site in Edgemont. SD, per 810731 discussion w/G Eadie & F Anastasi Commission has no legal authority to conduct tailings removal or decontamination work
 MONTOOMERY, J. Region 4, Dallas, Office of the Director (81/03/01) 81/08/07 Region 4, Dallas, Office of the Director (81/03/01) 2pp 22169 191
- ---8402080176 "Recommended Protocols for Radon Daughter Measurements in Bldps in Edgemont " * Nattelle Memorial Institute, Pacific Northwest Laboratory FIN n-2217 83/06/09 NRC - No Detailed Affiliation Given 10pp 22170 241
- --8402080180 Draft "Proceedings of Workshop on Radiological Surveys in Support of Edgement Cleanup Action Program," 810121-22, Donver.CO YGUNO.J A . JACKBON.P O . THOMAS.V W Battelle Memorial Institute. Pacific Northwest Laboratory FIN B-2216 NUREO/CP-0021 DRFT B1/04/15 100pp 22169 160
- --8402080202 "Indoor Radon Study at Edgement & Cottonwood, 8D, 800204-08 "
 * NRC No Detailed Affiliation Given 80/02/08 lipp
 22169 261
- --B402080206 Forwards revised data from soil samples taken in Edgement SD in Nov 1977 DQNQVAN.T.K Tennessee Valley Authority 80/04/04 THRALL, J Environmental Protection Agency 8pp 22169 273
- --8402080211 Discusses radiation monitoring in Edgemont, SD by SD Dept of Health Measurements will utilize federal protocol, as listed SMITH, J Affiliation Not Assigned 80/04/09, RICHARDSON, R Affiliation Not Assigned ip 22169, 281
- --8402080214 Forwards memo from 8 Smith,80 Dept of Health,re radiation monitoring in Edgemont Memo outlines process established to provide necessary monitoring for EPA & HUD at request of local homeowners RICHARDSON,J R South Dakota, State of 80/04/17 MILLER,H NRC No Detailed Affiliation Given ip 22149 282
- --B4020B0216 Responds to B00321 request for add1 info re NRC request for DGE assistance in remedial action program in Edgemont. BD DIRGKB.W J Office of the Executive Director for Operations B0/04/30 FRANGUS:T Q Energy. Dept of App. 22169 283
- --8402080219 Forwards fact sheet prepared by NM89 re Benate Authorization Committee designation of NRC as lead agency for coordinating cleanup of offsite locations at Edgemont Two primary points listed Related info encl
 DAVIS.J.G. NRC No Detailed Affiliation Given 80/05/22
 KAMMERER, C. NRC No Detailed Affiliation Given 19pp
 R2147 287

- U402010294 Forwards final draft of health physics manual for TVA Ligement Mill Final version to be submitted within 1 wk Insp scheduled for 840323 M/o encl PETTENOILL: Uranium Recovery Field Office 84/01/12 EVERETT.R J Region 4. Office of Director 2pp 22044 321
- DOCKET 40-1386 RAYTHEON CO , WALTHAM, MA
- 8402220432 Discusses IT Insp Rept 40-1386/8d-04 on 830922 & forwards nutice of violation MARTIN.T T Division of Engineering & Technical Programs 84/02/15 MERROW.R Raythean Corp 2pp 22339 360
- --8402.220447 Notice of violation from insp on 830922 Violation noted cabinet in pressing room containing approx 25 lb Th-232 occasionally unlocked when not under constant surveillance & immediate control 4 Region 1, Office of Director 84/02/15 ip 22339 362
- DOCKET 40-2061 KERR-MODEE CHEMICAL CORP , ORLAHOMA CITY, ON
- 8402080187 Transcript of 840202 hearing in Chicago, IL Pp 1-217 * Merr-McGee Chemical Corp (subs of Merr-McGee Corp) 84/02/02 219pp 22128 325
- 8402240187 FOIA request for nine documents on facility BARNLG.C Affiliation Not Assigned 83/12/06 Office of Administration ip 22381 287
- 0402240180 Responds to FOIA requests for two documents by accession number on Kerr-McOse Cimerron facility & nine documents by accession number on Kerr-McOse West Chicago facility Request sent to PDR for processing by PDR contractor FELTON.J M Division of Rules and Records 83/12/15 DARNES, C Affiliation Not Assigned 1p 22381 285
- 8402090550 Amended contentions to 830707 patition for hearing & leave to intervene Proof of Bvc encl RAPAINA Illinois. State of 83/12/30 Atomic Safety and Licensing Doard Panel 19pp 82191 310
- U402090332 Requests permission to dispose of 31 drums of soil contaminated w/PCB & thorium from thorium/rare earths processing facility at CECOG, Inth PCB landfill SHELLEY,W J Kerr-McGee Corp B4/01/13 BUTTS,D 表 CECOS International ip 22177 340
- 8402020023 Response opposing Kerr-McGer contentions re disposel of thorium plant wastes Contentions raise issues not otherwise raised in proceeding in timely fashion Certificate of Syc encl f-UNNER.R. L. Regulations Division 84/01/31 Atomic Bafety and Licensing Board Panel 7pp. 22056 330
- 8482170123 Provides items of interest re 840202 Kerr-McGee West Chicago, it stabilization plan MC/DDE meeting held on 840207 to discuss nuclear matt transportation issues PAGE.R G Uranium Fuel Licensing Branch 84/02/09 DAVIS, J G Office of Nuclear Material Bafety & Safeguards Director 2pp 92013 297
- 8408230866 Summary of 640112 meeting w/Kerr-McGee in Silver Spring, MD re cleanup of Kress Creek at West Chicago, N. Barock NIXDN, W A Granium Fuel Licensing Branch B4702/10 CROW, W T Uranium Fuel Licensing Branch 2pp 22380 015
- 8408290877 Forwards revised pages for insertion into incineration sys operator procedure manual Changes clarify sys operation & sampling DENNY, I L. Kerr-McGee Corp. 84/08/17 PAPERIELLO, C. J. Region 3, Office of Director. Spp. 28427 205
- 8402270388 Summarises 840208 meeting in Chicago, IL re search for disposal site for 31 drums of soil containing PCB & thorium-natural BENNY. I L Kerr-McOse Chemical Curp (subs of Kerr-McOse Corp) 84/02/20 KPM, Y J Environmental Protection Agency 7pp. 22370, 245
- 0402280443 Prehearing conference order that Kerr-McGee & staff brief issue of acceptability of contentions & parties confer re consolidation of Chember & Atty General w/respect to Contentions GC1 & CG2 & abandonment of Contentions 3 & A. MCRRIBLE A. CARPENTER, J. H., FRYE, J. H. Atomic Safety and Licensing Board Panel 84/02/24 14pp 22407 190

- DOCKET 40-2259 PATHFINDER MINES CORP , RIVERTON, WY
- B40R230163 Corrected page to effluent monitoring rept for Fourth Quarter 1982 Original 830512 rept erroneously reported value of 3.39 uci x 10-5/ml U as 0.63 uCi x 10-5/ml U for Well Ti-1 W/640125 ltr
 HARDOROVE, T W Pathfinder Mines Corp 82/12/31 WOOLSEY, R T Uranium Recovery Field Office 2pp 22379 202
- 8402210284 Forwards one oversize map identifying areas where wasts matts with be deposited, in response to NRC 840113 request Aperture card is available in PDR MARDGROVE, T W Pathfinder Mines Corp 84/01/20 WOOLSEY, R T Uranium Recovery Field Office 2pp 22323 356
- DOCKET 40-3453 ATLAS MINERALS, INC . DENVER, CD
- B402210291 Requests specific info re calculation of storage term & final swepage quantity used in "Hater Balance Study U Mill Tailings Impoundment. Moab. UT. for Atlas Minerals." be provided by 840215
 PETTENGILL. H J Uranium Recovery Field Office B4/01/18
 BLUBAUOH. R Atlas Minerals. Inc ip 22323 361
- 8402210256 Forwards request for addl info to complete review of amend request involving changes to mill in-plant & environ manitoring requirements Response requested by 840302 PETTENOILL.H J Uranium Recovery Field Office 84/02/08 BLUBAUGH.R Atlas Minerals, Inc. 3pp 22343 251
- DOCKET 40-4658 INTERIOR, DEPT OF AVONDALE, MD
- 8402240104 IE Insp Findings & Licensee Ack dtd 840209 of Licenses 19-07068-02 & 8M8-299 Insp findings leak tests not performed at proper frequencies NVOLOSI, Frequencies NVOLOSI, ACP Region 1, Office of Director 84/02/09 ip
- DOCKET 40-6622 PATHFINDER MINES CORP , SHIRLEY BASIN, WY
- 8402170448 Requests review of "Shirley Basin Mine Hydrologic Monitoring Rept " Comments should be provided to NRC BEACH.O Wyoming. State of 84/01/17 SPEARS.R. MANCINI.T Wyoming. State of 1p 22313 196
- DOCKET 40-6659 GETTY OIL CO PETROTOMICS CO , SHIRLEY BASIN, WY
- 8402210306 Forwards "Environ Sample Data," for First & Second Gwarter 1983" & "Btack Emissions Survey," for May & Feb 1983 PFAFF, S. J. Getty/Petrotomics Co. 83/09/01 SMITH, D. Uranium Recovery Field Office 1p 22345 220
- --8402210311 "Environ Sample Date" First Quarter 1783 * Getty/Petrotomics Co 83/03/31 21pp 22345 221.
- --8402210315 "Environ Sample Data." Second Quarter 1983 * Getty/Petrotomics Co 83/06/30 22pp 22345, 242.
- --8402210320 "Stack Emissions Survey, Petratomics Co. V Mill, Shirley Basin, WY" * Western Environmental Services & Testing 83/05/31 56pp 20245 284
- --B402210323 "Stack Emissions Burvey, Petrotomics Go, U Mill, Shirley Basin, NY " * Western Environmental Services & Testing 83/02/28 49pp 22345: 342
- DOCKET 40-6920 AUTOMATION INDUSTRIES, INC , PHOENIXVILLE, PA
- B402020328 Forwards IE Insp Repts 40-06920/83-02 & 30-08998/83-02 on 831018 & 19 & 1102-07 No noncompliance noted As of B31019, design specs for extension tubes had not been modified MARTIN, T T Division of Engineering & Technical Programs 83/12/27 DWIGHT, J Automation Industries, Inc. 7pp 22055-069.
- --8402020330 IE Insp Repts 40-04920/83-02 & 30-05998/83-02 on 831018 & 19 & 1102-07. Violations noted surface dose rate of source changer containing Ir-192 exceeded 200 & external radiation levels not varified DENNIS.N A , KINNEMAN, J D Region 1, Office of Director 83/12/15 13pp 22055 076

- --8402020332 Responds to violations noted in Insp Repts 40-06920/83-0! 30-03998/83-01 Corrective actions operating procedures will be amended extension tubes analyzed & plunger assembly drawings revised MDRELAND.P E Automation Industries. Inc 83/10/13 ALLE MORELAND.PE Automation Industries, Inc. 83 Region 1. Office of Director 4pp 22055 089 83/10/13 ALLEN, J M
- 8402170165 EN-84-004 on B40216 notice of violation & proposed imposition of civil penalty in amount of \$9,625 to be issued re shipments of licensed math w/surface radiation levels in excess of regulatory limits
 FLACK.E., AKELRAD.J. Director's Office. Office of Inspection and Enforcement 84/02/13 ip 22279 025
- DOCKET 40-6940 KAWECKI BERYLCO IND , INC , BOYERTOWN, PA
- 8402090446 Forwards booklet containing answers to NRC environ questions
 COVLE,F T Cabot Corp 84/01/28 HYNGARDEN,S Uranium Fuel
 Licensing Branch 250pp 22186 082
- DOCKET 40-7455 WHITTAKER METALS, LOS ANGELES, CA
- 8402140611 "Rept on Decontamination of Aluminathermic Bldg. Whittaker Corp " * Radiation Management Corp 83/04/26 37pp 22253 314
- 8402140635 Comments on Whittaker Corp intention to aggregate all low level radioactive matis in one location at site in Greenville PA Action does not constitute permanent solution to disposal MAY, C. 9 M co disposal AY.C.B Memel, Jacobs, Pierno & Gersh 84/01/24 CROWE,W T NRC - No Døtailed Affiliation Given 2pp 22302 001
- 8402160648 Advises that Whittaker Corp avaluating feasibility of plans to aggregate all low layel radioactive matts at site in Greenville,PA Remainder of site certified radiologically
 - MAY, C B MAY,C 8 Affiliation Not Assigned 84/01/24 KINNEMAN,J Region 1, Dffice of Director 2pp 22292 359
- DOCKET 40-7580 FANSTEEL, INC., NORTH CHICAGO, IL

Rules and Records

- 8402270317 FOIA request for documents re 830908 meeting between NRC & Fansteel Metals concerning processing columbian/tantalium ore containing U thorium which requires NRC source matl license. Hammittih a FOI Bervices 83/12 ords ip 22412:332 83/12/21 FELTON, J.M. Division of
- 8402270523 Responds to FOIA request for documents re 830908 meeting between Fansteel Metals & NRC Forwards App A document FELTON, J M. Division of Rules and Records 84/01/16 HAMHITT, H A FOI Services 2pp 22412 333
- --8401170482 Summary of 830708 meeting w/licensee in Silver Spring.MD replans for ultimate disposition of solid waste generated by treatment of liquid stream RHODES.M J Uranium Fuel Licensing Branch 83/09/14 Uranium Fuel Licensing Branch 1p 82412-335
- DOCKET 40-8027 KERR-MCGEE NUCLEAR CORP., OKLAHOMA CITY, OK
- 8402020067 Advises of issuance of Amend 25 to License BUB-1010, permitting storage of raffinate sludge in Pond 4.Work on all previously submitted amend applications re disposal of solid waste has ceased.

 PAGE.R. G. Uranium Fuel Licensing Branch 84/01/24 SHELLEY, W. J. Kerr-McGee Nuclear Corp. 2pp 22062.288
- --8402020072 Recommends issuance of Amend 25 to License 8UB-1010, permitting storage of raffinate sludge in Pond 4 Comprehensive plan for disposal of solid wastes will be submitted within 1 yr of amend date KOBLA:B M. Uranium Fuel Licensing Branch 84/01/24 Uran Fuel Licensing Branch 2pp 22062-290 Uranium
- DOCKET 40-8084 RIO ALGOM CORP., MOAB, UT
- 8402010292 Reviews environ monitoring date for First Half 1983 All required sampling & analyses performed No trends or concerns noted during review of data GARCIAP J. Uranium Recovery Field Office 84/01/09 Uranium Recovery Field Office 4pp. 82046.388. Uranium

- 8402220047 Comments on 830912 semiannual land use survey conducted in vicinity of Lisbon Mill Changes in land use few since previous survey in Feb 1983 GARCIA,P J , PETTENGILL,H J Uranium Recovery Field Office Uranium Recovery Field Office 2pp 22344 356
- 8402220040 Submits review of surface water hydrology considerations & final impoundment reclamation per 821122 renewal application Interim storage capacity, increased storage capacity & reclamation stage addressed JOHABON T L., PETTENOILL, H. Uranium Recovery Field Office 84/01/30 Uranium Recovery Field Office 4pp 22363 102
- B402290014 Application for amend to License SVA-1119, revising Condition li to read that nominal mill throughput shall be 1,500 Ml U bearing ore per day, as averaged annually PATTISON, R S. LAHTON, Ml D. RIO Algom, Ltd. 84/01/30 SMITH, R. D. Uranium Recovery Field Office 2pp 22437 326
- DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CO , BROOMFIELD, CO
- 8402010039 Forwards summary of Rocky Mountain Energy & outside evaluations of geologic depositional environ, studies of regional water quality & groundwater flow modeling & updated inventory of wells in region.per 831118 request NEUMANN, M R Rocky Mountain Energy Co 83/12/07 LINEHAN, J Uranium Recovery Field Office 200pp 22047 001
- 8402210470 Comments on meeting re decommissioning activities Vendor interested in initiation of decommissioning as soon as possible PRESTON DE Rocky Mountain Energy Co 84/02 Uranium Recovery Field Office 1p 22344 010 84/02/03 HAWKINS.E
- DOCKET 40-8452 BEAR CREEK URANIUM CO , CASPER, WY
- 840223004) Forwards Rev 3 to "Tech Spec for Geotechnical Engineering Svcs Tailings Dam Const Control" & "Const Rept Bear Creek Tailings Disposal Area Clay Liner 1983 Const " MEDLOCK,R L Bear Creek Uranium Co 83/11/22 PANGBURN. G C Uranium Recovery Field Office ip 22379 263
- ---B402230053 Rev 3 to Procedure C-1 "Tech Spec for Geotechnical Engineering Sycs Tailings Dam Const Control " * Rocky Mountain Energy Co 83/11/11 9pp 22379 265
- --8402230057 Rev 2 to Procedure C-2, "Teth Spec for Expanding Capacity of Bear Creek Tailings Disposal Area " * Rocky Mountain Energy Co 83/11/11 19pp 22379 274
- --8402ನ30064 "Const Rept:Bear Creek Tailings Disposal Area Clay Liner 1983 Const " W/one oversize map Aperture card is available in PDR # Rocky Mountain Energy Co 83/11/22 47pp 22379 293
- 8408220170 Forwards info to satisfy Amend 20, Condition 51(a) to License 8UA-1310 Tables of water quality data from Third Quarter 1983 for seepage control wells & static water levels encl BLOBBOM.J N Bear Creek Uranium Co 83/12/19. Uranium Recovery Field Office 3pp 28363 098
- 8402210287 Requests review of encl questions & comments to Tech Space C-1 & C-2 concerning geotechnical angineering svcs & sxpanding capacity of tailings disposel area PETTENOILL, H. J. Uranium Recovery Field Office 84/02/02 MEDLOCK, R.L. Beat Creek Uranium Co. 3pp 22343;246
- DOCKET 40-8502 WYOMING MINERAL CORP , LAKEWOOD, CO
- B402070009 Forwards executed application for permit transfer license to mine application, bond rider, application for in-situ research & development testing license & bond rider, in response to B31212 ltr
 TOMODKA, H Westinghouse Electric Corp. B4/01/17, BRYAN, V J Wyoming, State of, 18pp 67153 172
- DOCKET 40-8511 COTTER CORP. . GOLDEN, CO
- 8402220049 Comments on Amend 2 to Source Matl License BUA-1273 Amend should be considered part of license renewal action HILDENBRAND, P., HAMKINB, E. F. Uranium Recovery Field Office 84/01/17 WE188, D. J. License Fee Management Branch ip. 22346 358

DOCKET 40-8584 MINERALS EXPLORATION CO . LOS ANGELES, CA

- B402020115 Requests comments on encl draft rept re U tailings pond at Sweet Water facility (Case Study 9) by B40113 CHASSEMI,M Noltidisciplinary Energy & Environ Sys & Applications B3/12/14 LINEHAN,J Uranium Recovery Field Office 26pp 22082 254
- B402210480 Discusses survey of land use within 5 miles of mill site Use of remote section of Red Desert limited to seasonal livestock graving, recreational pursuits, transient oil & gas exploration & U mining activities
 XLEIN:T J Union Minerals B4/01/20 SMITH.R D Uranium Recovery Field Dffice 1p 22243 355
- 8402210455 Summary of 831222 meeting w/State of MY.Dept of Environ Quality in Cheyenne.WY re tailings mgt plan proposed by Hinerals Exploration Co HONWINSKI,O R Uranium Recovery Field Office 84/02/02 Uranium Recovery Field Office 3pp 22344 173
- 8402210487 Comments on review of 840124 annual land use survey Use of land continues to be limited to seasonal grazing of livestock & U mining activities No further action required KONMINSF1.0 R , PETTENDILL.H J Uranium Recovery Field Office 84/02/08 Uranium Recovery Field Office 2pp 22343 346
- DOCKET 40-0505 WYOMING MINERAL CORP . LAKEWOOD, CD
- 8402030043 Withdraws 830510 request for approval of proposed disposal procedure for waste ion-exchange resin & appropriate minor amend to License 8VA-1315 RVTLEDGE. C. Wyoming Mineral Corp. 83/12/12 SMITH.R D. Uranium Recovery Field Office. 1p. 22091 087
- DOCKET 40-8586 MERR-MCGEE NUCLEAR CORP . OKLAHOMA CITY. OK
- B402170445 Provides undocumented reclaimation status of Kerr-McGee abandoned in-situ sites Abandoned drill hole program will check out wells & drill holes for adequate abandonment procedures
 FHANCIS, E. Wyoming, State of 84/01/12 SPEARS, R., RANDEN, L. Wyoming, State of 2pp 22313 157
- DOCKET 40-8669 NUCLEAR DYNAMICS, INC . PHOENIX, AZ
- 8402010345 Forwards consultant D Fritz 831206 request for permission to discharge certain treated water stored in evaporation ponds at Oshoto solution mining test site & to sell Hells 787 & 19XX Amend fee encl STOICK.A F ND Resources, Inc. 83/12/12 LINEMAN.J Uranium Recovery Field Office ip. 22060 348
- --8402010349 Forwards 831i09 ltr to J Wagner requesting permission to discharge water in evaporation ponds at ND Resources Oshoto solution mining test site Environ amend fee encl FRITZ, B M Hestern Mater Consultants, Inc BJ01CK.A F ND Resources, Inc BJ/12/06 LINEHAN, J Uranium Recovery Field Office 14pp 22060 347
- DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC., DENVER, CO.
- 8402210483 Bummary of meeting w/Union Carbide Corp (UCC) & Energy Fuels Nuclear (EFN) to discuss UCC submissions prior to transferring license from EFN EFN responsible for license until transfer takes place HILDENBRAND,P, HANKING,E F Uranium Recovery Field Office 84/02/08 Uranium Recovery Field Office 3pp 22343 349
- DOCKET 40-8684 WESTERN NUCLEAR, INC , LAKEWOOD, CO
- B402220097 Forwards B Koenig.of In-Bitu.Inc.comments re Dept of Environ Quality comments on pump tests in reply to Section C2 of R&D application. BOODEN.G Western Nuclear. Inc (subs of Phelps Dodge Corp.) B3/12/12 HILDERAND.P Uranium Recovery Field Office 13pp 22363 108

DOCKET 40-8724 CHEMETRON CORP . CHICAGO, IL

- B402280647 Updated application for extension of License SUB-1357 Mods to License Conditions 12 & 13 recommended DESMAN,R J Chemtron Corp B3/11/18 PAGE,R G Uranium Fuel Licensing Branch 1p 22427 066
- --8402280652 "Decontamination Plan for McGean-Rohco, Inc Facilities " * Chemtron Corp 83/10/05 10pp 22429 067
- --8402280656 Forwards check in payment of amend fee,per 840127 request DESMAN.R J Chemtron Corp 84/02/10 JACKBON.9 License Fee Management Branch 1p 22429 078
- --8402280459 Informs of amend fee for B3111B request for amend to License SUB-1337 JACKSON. © License Fee Management Branch 84/01/27 DESMAN.R. J Chemtron Corp 2pp 22427 079

DOCKET 40-8745 OGLE PETROLEUM, INC , CASPER, WY

- 8402210488 Comments on 840106 semiannual effluent release rept for Jul-Dec 1983 No radioactive effluents released to unrestricted areas No further action required HASTLER.S L. HAWKINS,E F Uranium Recovery Field Office 84/02/07 Uranium Recovery Field Office 1p 22343 345
- DOCKET 40-8768 KERR-MCGEE NUCLEAR CORP . DKLAHOMA CITY, DK
- 8402220101 Forwards "Aquifer Pump Test 'O' Sand In-Situ Leach Project, South Pouder River Basin, Converse County, Wy " SHELLEY, W J Kerr-McGee Corp 83/09/26 LINEHAN, J J Uranium Recovery Field Office 3pp 22363 121
- --8402220107 "Aquifer Pump Test '0' Band In-Situ Leach Project " LOGAN, B M Kerr-McGee Corp 83/09/26 110pp 22363 123
- 8402240357 "Semiannual ALARA Rept for May-Oct 1983 " W/831128 ltr SINXE.G J Kerr-McGes Chemical Corp (subs of Kerr-McGes Corp) 83/10/31 7pp 22380 139
- 8402210467 Forwards ltr sent to State of WY re well field operations for "D" Sand in-situ leach pilot project FREEMAN, M D Rocky Mountain Energy Co 84/01/04 LINEHAN, J J Uranium Recovery Field Office 3pp 22344 011
- 8402210475 Forwards info sent to State of WY to be inserted in "O" Sand in-situ project application Minor mods made to provide add! data FREEMAN & D Kerr-McGee Corp 84/01/25 LINEHAN, J J , HILDENBRAND:P Uranium Recovery Field Office 16pp 22343 356
- DOCKET 40-8783 URANERZ UBA, INC , CASPER, WY
- B402170451 Recommunds that goal of groundwater restoration be baseline, monitoring include full Quideline S parameter list & three injection wells be substituted for three production wells rechanges to groundwater restoration plan GGLE.X M Myoming, State of 3pp 22313 153
- DOCKET 40-8786 URANIUM RESOURCES, INC , RICHARDSON, TX
- 8402010008 Forwards lab analysis showing results of water samples obtained 830816 SMITH, M Wyoming, State of 83/09/26 Wyoming, State of 3pp 22048 186
- DDCKET 40-8794 MOLYCORP, INC . LOS ANGELES, CA
- 8402280679 Forwards revised emergency procedures manual & preparadness, prevention & contingency plan Prevention & contingency plan supercedes pollution incident prevention rept DAUGLASS, S J Molycorp, Inc 84/01/11 SDONG, A L NRC No Detailed Affiliation Given 1p 22416 324
- --8402280704 "Emergency Procedures Manual Molycorp, York Plant "
 * Molycorp, Inc. 84/01/11 17pp 22416 325

--8402280708 "Preparedness.Prevention & Contingency Plan " * Molycorp, Inc 83/01/25 11pp 22416 343

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DUCKET 50-3 INDIAN POINT STATION, UNIT 1

H General correspondence

- 8402130265 Responds to 831212 request to address D Kraut concerns re possibility that plant located on fault line will explode Plants designed to withstand DBE associated w/capable fault DIRCKS,W J Office of the Executive Director for Operations
 - DIRCKS,W J Office of the Executive Director for Operations 84/02/02 KENNEDY, E M Benate 5pp 22214 203 24X Fiche 50-003,84/02/02,8402130265
- --8402130269 Forwards constituent D Kraut ltr expressing concerns re hazards of living near nuclear power plant KENNEDY.E M Senate B3/12/12 Office of Public Affairs 2pp 22216 207 24X Fiche 50-003.84/02/02.8402130265
- P Operating license stage documents & correspondence
- 8402160003 Third partial response to FDIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILK: 9 J Office of the Secretary of the Commission 83/12/14 Public Document Branch ip 22281 023 24X Fiche 50-000,83/12/14.8402160003
- --B402160043 Btaff requirements memo re B30610 discussion & vote on facility order in Washington.DC CHILK, B J Office of the Becretary of the Commission 83/06/14 PLAINE, H H Office of the General Counsel ip 22281 060 24: Fiche 50-000.B3/12/14.B402160003
- ---8402160368 Btaff requirements memo discussing possible 821222 vote on actions re Pacility in Washington, DC
 CHILK, B J Dffice of the Becretary of the Commission 82/12/23
 Office of the Secretary of the Commission Ip 22281 248 24X
 Fiche 50-000.83/12/14,8402160003
- --8402160446 Discusses SECY-83-263 re Sunshine Act review of transcript of 830519 closed Commission meeting CHILK, 8 J. Office of the Secretary of the Commission. 83/07/08 PLAINE, H. H. Office of the General Counsel. ip 22281 304 24X Fiche 50-000,83/12/14,8402160003.
- B402010410 Generic Ltr 84-04 to all operating PWR licensees, CP holders & applicants for CPs re safety evaluation of Hestinghouse topical repts dealing w/elimination of postulated pips breaks in PWR primary main loops Svc list enci EISENHUT, D O Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc 59pp 22177 087 24X Fichs 50-000.84/02/01.8402010410
- G Inspection reports, IE Bulletins & correspondence
- B312120153 IE Info Notice B4-06. "Steam Binding of Auxiliary Feedwater Pumps " Bvc list encl. JORDAN, E L., Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/25. Consolidated Edison Co. of New York, Inc. 120pp 22057 249 24X Fiche 50-000.84/01/25.8312120153
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co. of New York, Inc. 119pp 22114 179 24X Fiche 50-000:84/02/03.8401190016
- B401190017 IE Bulletin 84-01. "Cracks in BWR Mark I Containment Vent Headers." Syc list encl DEYOUNG.R.C Director's Office. Office of Inspection and Enforcement. B4/02/03. Consolidated Edison Co of New York, Inc 102pp. 22177 156. 24X Fiche. 50-000.84/02/03.8401190017
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (100FR50, App R), " Syc list encl.

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp. 22365-259 24X Fiche: 30-000;84/02/13,8401190041
- B401190039 IE Info Notice B4-0B, "IOCFR50 7, 'Employee Protection '"
 Bvc list encl,
 JURDAN,E L. Division of Emergancy Preparedness & Engineering
 Response (Post B30103) 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp. 22365 141 24X Fiche: 50-000, 84/02/14, 8401190039

- 8401190045 IE Info Notice 83-63, Suppl 1. "Potential Failures of Westinghouse Type BA-i Differential Relays " Svc list encl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York: Inc 118pp 22366 142 24X Fiche 50-000.84/02/15,8401190045
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Bet Below Manufacturer Recommended Value " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 114pp 22366 024 24X Fiche 50-000.84/02/21.8401190062
- 8401190066 IE Info Notice 84-11. "Training Program Deficiencies "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000.84/02/24.8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Suft Beat Valve Seals "
 Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc. 120pp 22431 060 24X Fiche 50-000.84/02/27,8401190067
- DOCKET 50-6 BATTELLE MEMORIAL INST RESEARCH REACTOR

 G Inspection reports, IE Bullstins & correspondence
- 8402150249 Forwards IE Insp Repts 50-004/84-01 & 70-0008/84-01 on 840109-13 No noncompliance noted PAPERIELLO,C J Region 3, Office of Director 84/02/03 UNGAR,E W Battelle Memorial Institute, Columbus Laboratories 2pp 22280 031 24X Fichs 50-004, 84/02/03, 8402150249
- --8402150254 IE Insp Repts 50-006/84-01 & 70-0008/84-01 on 840109-13 No noncompliance noted Major areas inspected licensing status, operations review criticality safety, radiation protection & solid radwayte mpt
 MILLER.D E , FRANCE.G M , GREGER.L R Region 3, Gffice of Director 84/02/03 7pp 2250 033 24X Fiche 50-006.84/02/03.

DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

- F Security, medical, emergency & fire protection plans
- B402130191 Rev O to Emergency Plan Implementing Procedure EOF-17.
 "Emergency Operations Facility Activation Facility Log "
 BERLIN.M D Commonwealth Edison Co 83/09/23 3pp 22199 283
 24X Fiche 50-000.83/09/23.8408130191
- 8402130215 Rev O to Emergency Plan Implementing Procedure EOF-18, "Nuclear Station Div Non-Edison Transportation Incident Assistance Procedure "

 * Commonwealth Edison Co 83/09/29 5pp 22204 078 24X Fiche 50-000 83/09/27 8402130215
- 8402100137 Revised emergency plan implementing procedures, including Procedures EPIP EOF-17 re emergency operations facility activation log. EPIP CC-12 re sys power dispatcher & EPIP EOF-12 re scess control W/840203 memo & receipt form MDORE, R D Commonwealth Edison Co 83/11/09 DENTON, N R NRC No Detailed Affiliation Given 24pp. 221B1 288 24X Fiche 50-000,83/11/09,8402100137
- 8402130220 Rev 8 to Emergency Plan Implementing Procedure GC-12, "Sys Power Dispatcher" MDORE, R D Commonwealth Edison Co 83/11/09 iipp 22200.108 24X Fiche 30-000 83/11/09, 8402130220
- 8402270040 FOIA request for NRC emergency planning zone maps for facilities
 KUHLENBERGER, @ Mobil Oil Corp (subs Mobil Corp) 83/12/27
 NORRY, P Office of Administration 1p 22407 337 24X
 Ficha 50-010,83/12/27,8402270040
- 8402060444 Forwards Rev 9 to Emergency Plan Implementing Procedure CC-1. "Corporate Command Ctr Director "Recovery manager priority notification table encl MOGRE, R D Commonwealth Edison Co 84/01/30 DENTON, H R Office of Nuclear Reactor Regulation, Director Rpp 22083 129 24X Fiche 50-000,84/01/30,8402060446
- --8402040464 Rev 9 to Emergency Plan Implementing Procedure CC-1, "Corporate Command Ctr Director," controlled copy MODRE,R D Commanwealth Edison Co 83/11/30 74pp 22083 131 24X Fithe 30-000,84/01/30,8402040446

- 8402270036 Responds to FDIA request for NRC emergency planning zone maps for facilities Haps may be reproduced for listed costs or examined at Region III of:
 FELTON.J M Division of Rules and Records 84/02/01
 KOHLENBERGER,
- 8402070202 Advises that NRC will not review emergency plans to delete private or proprietary info unless specifically requested by licensee.per 830709 itr W/o request.entire plan will be placed in FDR CRUTCHFIELD.D Operating Reactors Branch 5 84/02/02 FARRAR.D L Commonwealth Edison Co 2pp 22100 029 24x Fiche 50-010.84/02/02.8402070202
- 8402100228 Forwards joint exercise rept of 830914 exercise of offsite radiological amergency preparedness plans for facilities State of IL & Grundy Kendall & Will Counties participated KRIMH, R W Federal Emergency Management Agency 84/02/06 JOROAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 22179 226 24X Fiche 50-010,84/02/06,84/02/06
- --B402100233 Evaluation of joint exercise rept of 830914 exercise of offsite radiological emergency preparedness plans for facilities
 * Federal Emergency Management Agency 83/12/13 35pp 22179 228 24X Fiche 50-010.84/02/06.8402100228
- B4022B0395 Revised emergency plan implementing procedure, including Rev 1 to BZP 600-A4, "OSEP Telephane Directory " * Commonwealth Edison Co 84/02/18 61pp 22404 158 24X Fiche 50-000.84/02/18,84022B0395
- 9 Adjudicatory correspondence
- 8402070128 Order extending time until 840213 for Commission to act to review Director's Decision DD-83-14 & extending 831029 decision denying Environ Policy Inst request to 840213 CMILK.S J Diffice of the Secretary of the Commission. 84/02/03 Commissioners ip 22100 198 24X Fiche 50-000,84/02/03.8402070128
- 8402150195 Order extending time until 840221 for Commission to act to review Director's Decision DD-83-14 CHULK: 8 J Office of the Secretary of the Commission 84/02/13 Commissioners 1p 22245 147 24X Fichs 50-000, 84/02/13, 8400150195
- 1 Financial information
- 8408280410 Annual Financial Rept 1983 M/840821 ltm, O'CONNOR,J J , BRESEMANN.R W Commonwealth Edison Co 83/12/31 29pp 22407 101 24X Fiche 50-000.83/12/31.8402280410
- Operating license stage documents & correspondence
- 312120029 Generic Ltr 83-39 to representatives of utils re voluntary survey of litensed operators Svc list encl EISENHUT.D Q Division of Licensing 83/12/08 Commonwealth Edison Co 12pp 22313 006 24X Fiche 50-000.83/12/08
- O Inspection reports. IE Bulletins & correspondence
- 8402060081 Forwards IE insp Rept 50-010/83-24 on 831209-840110 No noncompliance noted.

 SHAFER: N D Region 3. Office of Director 84/01/18 REED.C Commonwealth Edison Co 2pp 22088-240 24X Fiche 50-010.84/01/18. 8402060081
- --8402060085 IE Insp Rept 50-010/83-24 on 831207-840110 No noncompliance noted Major areas inspected, spent nuclear fuel shipments from Hest Valley, NY & transport unhitching incident TONGUE, T N. HALKER, R D. Region 3, Office of Director 84/01/13 5pp. 22088 242 24X Fiche 50-010.84/01/18,8402060081
 - R120153 LE Info Notice 84-06. "Bteam Binding of Auxiliary Feedwater unps." Svc list ancl
 ORDAN.E L Division of Emergency Preparedness & Engineering .esponse (Post 830103) 84/01/25 Consolidates Edison Co of New fork. Inc. 120pp 22057.249 24% Fiche 50-000.84/01/25.8312120153
- 402020341 Ack receipt of 840120 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/83-19. 50-227/83-27 & 50-249/83-27 NORELIUS.C E Division of Project & Resident Programs 84/01/27 REED.C Commonwealth Edison Co ip 22055 031 24X Fiche 50-010,84/01/27.8402020341.

- --8402020345 Responds to NRC 831221 ltr re violations noted in IE Insp Repts 50-010/83-19, 50-237/83-29 & 50-249/83-27 Corrective actions operational procedures will be revised by 840401 to clarify actions needed when APRM gain drifts. FARRAR, D L Commonwealth Edison Co 84/01/20 KEPPLER, J Q Region 3, Office of Director Spp 22055 032 24X Fiche 50-010,84/01/27,8402020341
- 8402170081 Forwards IE Insp Repts 50-010/83-22, 50-237/83-32 & 50-249/83-30 on 831118-840117 & notice of violation 8HAFER.W D Region 3, Office of Director 84/02/01 REED, C Commonwealth Edison Co 2pp 22300 014 24X Fiche 50-010, 84/02/01, 8402170081
- --8402170085 Notice of violation from insp on 831118-840119 SKAFER.W D Region 3. Office of Director. 84/02/01 2pt 22300 016 24X Fiche 50-010,84/02/01,8402170081
- --B4021700BB IE Insp Repts 50-010/B3-22,50-237/B3-32 & 50-249/B3-30 on B3111B-B40119 Noncompliance noted isolation condenser drain valve 2-480B-501 found in closed position but not chained & locked & failure to have employee conduct procedure TONGUE, T M , STASEK, B , ANDERSON, C D Region 3, Office of Director B4/01/31 20pp 22300 01B 24X Fiche 50-010,84/02/01,84021700B1
- B40i1900i6 JE Info Notice B4-07, "Design-Besis Threat & Review of Vehicular Excess Controls" Bvc list encl JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 630i03) B4/02/03 Consolidated Edison Co. of New York. Inc. 119pp 22114 179 24X Fiche 50-000,84/02/03,8401190016.
- 8401190017 IE Bulletin 84-01. "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEYDUNG, R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 156 24X Fiche 50-000,84/02/03,8401170017
- 8402150250 Forwards IE Insp Repts 50-010/83-23, 50-237/83-33 & 50-249/83-31 on 831107-10 & 1205-20 PAPERIELLO, C J Region 3, Office of Director 84/02/03 REED, C Commonwealth Edison Co 2pp 22250 261 24X Fiche 50-010,84/02/03,8402150250
- --8402150257 IE Insp Repts 50-010/83-23,50-237/83-33 & 50-249/83-31 on 831109-10 & 1205-20 Noncompliances noted failure to provide training & failure to control entry into high radiation area
 PAUL:R A , NICHOLSON,N A , GREGER,L R Region 3, Office of Director 84/02/02 11pp 22250 263 24X Fiche 50-010,84/02/03,8402130230
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Bys (10CFR30, App R) " Byc list enc!

 JORDAN, & L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13, Consolidated Edison Co of New York, Inc 124pp 22365 259 24X Fiche 50-000,844/02/13,8401190041
- B401190039 IE Info Notice 84~08, "10CFR50 7, 'Employee Protection '"

 Bvc list encl

 JBRDAN.E L. Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/02/14 Consolidated Edison Co of New

 York, Inc 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- B401190045 IE Info Notice 83-63, Suppl i, "Potential Failures of Wastinghouse Type 8A-1 Differential Relays " Svc list and. JURDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/15 Consolidated Edison Co of New York, Inc. 118pp 22366 142 24X Fichs 50-000,84/02/15,8401190045.
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl. JORDAN.E L Division of Emergency Preparedness & Enginteering Response (Post 830103) 84/02/21 Consolidated Edison Co. of New York, Inc 116pp 22366-024 24X Fiche 50-000,84/02/21,8401190062
- B401190066 IE Info Notice 84-11, "Training Program Deficiencies "
 Svc list encl
 JODDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/02/24 Consolidated Edison Co. of New
 York, Inc 115pp 22430:304 24X Fiche 50-000,84/02/24,8401190066
- B401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Beals "
 Svc list encl
 JORDANA EL Division of Emergency Preparadness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co. of New
 York, Inc. 120pp 22431 060 24X Fiche 50-000, 84/02/27, 8401190067

- DOCKET 50-20 MASSACHUSETTS INST OF TECH RES REACTOR

 K Utility Final Safsty Analysis Report (FBAR) & amends
- 8402080325 Forwards Rev 29 to SAR, MITNE--115 Rev deletes fabrication telepances on fuel dimensions to indicate dimensions number 1
- --B402080327 Rev 29 to 8AR.MITNE-115 * Massachusetts Institute of Technology, Cambridge, MA 82/05/06 2pp 22130 283 24X Fiche 50-020,84/02/03,8402080325

DOCKET 50-29 YANKEE-ROWE NUCLEAR POWER STATION

- F Security, medical, emergency & fire protection plans
- B402070370 Rev 1 to "Procedure Generation Package for Yankee Emergency Response Guidelines." in response to NUREO-0737.Suppl 1
 Event based procedures revised per NUREO-0660.Item I C 1
 W/B40202 ltr
 KAY.J.A Yankee Atomic Electric Co B4/01/25 CRUTCHFIELD.D
 Operating Reactors Branch 5 57pp 22099 125 24X
 Fiche. 50-029.B4/01/25.B402070370
- B402070208 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per Generic Ltr B1-27 M/o request entire plan will be placed in PDR & LPDR CRUTCHFIELD. D. Operating Reactors Branch 5 B4/02/02 KAY, J A Vankes Abumic Electric Co 2pp 22102 150 24X Fichs. 50-029, B4/02/02.8402070202
- 8402220186 Forwards response to Generic Ltr 81-12.describing review effort to determine consequences of fire in defined fire areas Capability of proposed safe shutdown sys also discussed. M/four oversize drawings Aperture cards in PDR KAY, J A Yankee Atomic Electric Co 84/02/15 CRUTCHFIELD.D Operating Reactors Branch 5 18pp 22334 331 24X Fiche. 50-029, 84/02/15, 8402220186.
- P. Operating license stage documents & correspondence
- B402160453 Suppl 5 to B10326 application for amend to License DPR-3, consisting of Proposed Change 139, amending Tech Specs to provide work changes & clarification.
 HEIDER, L. H. Yankes Atomic Electric Co. B4/01/23 Office of Nuclear Reactor Regulation, Director 13pp 22268 239 24X Fichs, 50-029, 84/01/23, 8402160453
- --8402160455 Proposed Tech Specs re reactivity control sys, instrumentation, main coolant sys, ECCS, plant sys, electrical power sys & administrative controls * Yankee Atomic Electric Co. 84/01/23 42pp. 22268 252, 24X Fiche. 50-029, 84/01/23, 8402160453
- 840206006B Discusses resolution of SEP Topic III-5 A. Itam 4 re effects of pipe whip interactions on loop compartment walls from postulated breaks in large main coolant sys piping Existing plant leakage detection sys acceptable Evaluation complete KAY, J. A. Yankee Atomic Electric Go. 84/01/25. CRUTGHFIELD, D. Operating Reactors Branch 5. 2pp. 22088 230 24X Fiche: 50-029, 84/01/25, 8402060068
- 8402060252 Responds to Generic Ltr 83-41 re fast cold starts of diesel generators, per NRC 831216 ltr No data available since emergency diesel generator battery started & maintained near operating temp w/use of water & 011 heaters KAY, J, A. Yankee Atomic Electric Co. 84/01/27 EISENHUT, D G Division of Licensing. 1p. 22088 135. 24X Fiche 50-029, 84/01/27, 8402060252
- 8402010410 Generic Ltr 84-04 to all operating PWR licensess, CP holders to applicants for CPs re-safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops. Svc 11st encl EIBENHUT, D. 9 Division of Licensing, 84/02/01, Consolidated Edison Co. of New York, Inc. 59p 22177:087. 24X Fiche. 50-000, 84/02/01, 8402010410
- 8402100028 Advises that 830719 application requasting rev to Tech Space deleting specific cycle-dependent variable figures denied. Reasons request denied listed. CRUTCHFIELD, D. Operating Reactors Branch 5 84/02/09 KAY, J. A Yankee Atomic Electric Cb 3pp. 22178:256. 24X Fiche 30-029,84/02/09,8402100028

- 8402210027 Forwards responses to 831130 SER on main steam line break analysis rept (YAEC-1361), demonstrating acceptability of reactor vessel modeling in RETARN (KAY, JA Yankse Atomic Electric Co 84/02/09 CRUTCHFIELD, D Operating Reactors Branch 5 Bpp 22317 246 24X Fiche 50-027.84/02/09.8402210027
- B402240110 Forwards Rev 15 to Operational GA Program YOGAP-I-A Rev addresses organization & programmatic changes BHEPARD.A M Yankee Atomic Electric Co 84/02/15 MURLEY.T E Region 1. Office of Director 1p 22374 001 24X Fiche 50-000.84/02/15.8402240110
- --B402240111 Rev 15 to Operational GA Program YOGAP-I-A PEYERSON, W K , BHEPARD, A M , MURPHY, W P Yankee Atomic Electric Co 84/02/15 137pp 22374 002 24X Fiche 30-000, 84/02/15, B402240110
- 8402280043 Forwards response to Generic Ltr 82-16 re MUREO-0737 Tech Specs Listed TMI Items addressed KAY, JA Yankee Atomic Electric Co 84/02/17 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 22401 118 24X Fiche 50-029, 84/02/17, 8402280043
- B402240137 Application to amend License DPR-3, revising Tech Specs to replace 36 fuel assemblies to refuel reactor for Core XVII operation HEIDER.L H Yankse Atomic Electric Co 84/02/21 Office of Nuclear Reactor Regulation, Director 3pp 22374 184 24X Fichs Do-029.84/02/21.8402240137
- --8402240140 Proposed Tech Spec changes replacing 36 fuel assemblies to refuel reactor for Core XVII operation * Yankee Atomic Electric Co 84/02/21 lipp 22374 187 24X Fiche 50-029,84/02/21.8402240137
- --B402240143 "Yankee Nuclear Power Station Core XVII Performance Analysis " BERGERON,P A , CACCIAPUTI,R , BCHULTZ,B P Yankee Atomic Electric Co YAEC-1397 B4/01/23 62pp 22374 199 24X Fiche 50-029,84/02/21,8402240137
- Q Inspection reports, IE Bulletins & correspondence
- 8402040420 Forwards IE Insp Rept 80-027/83-14 on 830901-1021 % notice of violation STAROBIECKI, R Division of Project & Resident Programs 84/01/18 HEIDER, L H Yankee Atomic Electric Co 2pp 22084 278 24X Fiche 50-027,84/01/18,8402040420
- --8402060423 Notice of violation from insp on 830901-1021 * Region 1, Office of Director. 84/01/18 2pp 22084 300 24% Fiche 50-029,84/01/18,8402060420
- ---B402060426 IE Insp Rept 30-027/83-14 on 830701-1021 Violations noted failure to control math released from radiation control eres & failure to evaluate recurrent Tech Byce violations & implement effective corrective actions COLLINS.8 J Region 1. Office of Director 83/11/10 18pp 22084 302 24X Fiche 30-027.84/01/18.8402060420
- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120133
- B401170016 IE Info Notice B4-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Syc list enc! JORDAN, E. L. Division of Emergency Freparedness & Engineering Response (Post 830103) B4/02/03. Consolidated Edison Co. of New York, Inc. 117pp 22114:179 24X Fiche 50-000.84/02/03.8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEYDUNG,R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 156 24X Fiche 50-000,84/02/03,8401190017
- B401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR30, App R) " Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering
 - encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/19 Consolidated Edison Co of New York, Inc 124pp 22365:259 24X Fiche:50-000.84/02/13,8401190041
- 8401170039 IE Info Natice 84-08, "10CFR50.7, 'Emplayee Protection '"
 Svc list encl.
 JORDAN, EL Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co. of New
 York, Inc. 115pp 22345.141 24X Fiche.50-000.84/02/14.8401170039

- E401190045 IE Info Notice 83-63. Suppl), "Potential Failures of Westinghouse Type 8A-1 Differential Relays" Svc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366 142 24X Fishe 50-000.84/02/15.8401190045
- 8402220272 Forwards SALP rept for May 1982 Aug 1983 Adequacy of radwaste facilities & transportation activities & effective plant event review analysis & corrective action methodology areas require continued mgt attention MURLEY.TE Region 1. Office of Director B4/02/16 HEIDER.LH Vankee Atomic Electric Co 3pp 22337 072 24X Fiche 50-029.84/02/16.8402220272
- --8402220277 SALP rept for May 1982 Aug 1983 * Region 1, Office of Director 83/08/31 41pp 22337 075 24X Fiche 50-029,84/02/16,8402220272
- --8402220283 Ack receipt of SALP rept.reviewed & discussed during 831109 meeting w/NRC at plant site No further comments offered KAY, J A Yankee Atomic Electric Co 84/02/01 MURLEY, T E Region 1, Office of Director 1p 22337 114 24X Fiche 50-029,84/02/16,8402220272
- --8402220287 Advises of 83:107 meeting at site to discuss SALP review conducted on 83:012 Plans to improve performance requested STAROSTECKI.R Division of Project & Resident Programs 83/10/24 HEIDER,L H Yantee Atomic Electric Co 2pp 22337 117 24% Fiche 50-029,84/02/14,8402220272
- 8402280159 Ark receipt of 840130 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-029/83-16 NRC records will be revised to reflect correct regulation violated MARTIN.T T Division of Engineering & Technical Programs HEIDER,L H Yaniee Atomic Electric Co 2pp 22400 259 Fiche 50-029,84/02/17.8402280159 04/02/17 24X
- --8402280171 Responds to NRC 840106 ltr re violations noted in IE Insp Rept 50-029/83-16 Corrective actions reassignment of responsibilities made within radiation protection dept & radwaste handler positions created & filled HEIDER.L H Yankee Atomic Electric Co 84/01/30 MURLEY.T E Region 1. Office of Director Spp 22400 261 24X Fiche 50-029,84/02/17.8402280159
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 114pp 22366 024 24X Fiche 50-000,84/02/21,8401190062
- 8401190066 IE Info Notice 84-11. "Training Program Deficiencies " Syc list enci JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 630103) 84/02/24 Consolidated Edison Co of New Yark, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,8401170046
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/27 Consolidated Edison Co. of New York, Inc. 120pp 22431 060 24X Fiche 50-000,84/02/27,840119067
- S Reportable occurrences. LERs & related correspondence
- 8402030297 LER 83-043/03L-0 on 831223.monthly surveillance missed for safety injection accumulator time delay relay actuation verification Caused by personnel error Surveillance performed 6 days late W/840120 ltr
- 8402270397 LER 84-001-00 on 840124, small amount of borated water 9022/039/ LER 84-001-U0 on 840124.small amount of borated water noted in brass drain box area Leak classified as degradation of primary conlant sys boundary Caused by through-wallpin hole leak Defective pipe replaced W/840223 ltr DRAMBRIDOE,8 L., ST LAWRENT,N N Yanker Atomic Electric Co 84/02/23 4pp 22391 191 24% Fiche 30-029.84/02/23.8402270397

- DOCKET 50-62 UNIV OF VIRGINIA RESEARCH REACTOR O Inspection reports, IE Bulletins & correspondence
- 8402280261 Ack receipt of 831103 ltr.in response to 831006 notice of violation & proposed imposition of civil penalty, informing NRC of steps taken to correct violations noted in IE Insp NRC of steps taken to converse Rept 50-062/83-02
 O'REILLY, J P Region 2, Office of Director 84/02/16
 BRENIZER, J S Virginia, Univ of, Charlottasville, VA 22398 297 24X Fiche 50-062, 84/02/16, 8402280261
- --8402280275 Responds to NRC 831006 ltr re violations & civil penalties noted in IE Insp Rept 50-062/83-02 Corrective actions procedures implemented requiring proper reactivity processores implemented requiring properties.

 WILLIAMSON.T Q., BRENIZER, J. 8. Virginia, Univ of,
 Charlottesville, VA. 83/11/03. Region 2, Office of Director
 6pp. 22398.299. 24X Fichs 50-062.84/02/16.8402280261
- --8402280282 Forwards IE Insp Rept 50-062/83-02 on 830402-03 & 0706-08 & notice of violation & proposed imposition of civil & Notice or Violation a p. Spinor of Director 83/10/06 penalty D'RFILLY, J P Region 2, Office of Director 83/10/06 BRENIZER, J S Virginia, Univ of, Charlottesville, VA 2pp 22398 305 24X Fiche 50-062,84/02/16,8402280261
- --8402280290 Notice of violation & proposed imposition of civil panalty in Amount of \$1.000 Violation noted control rods in use not callbr for core configuration & licensee had no reactivity balance procedure O'REILLY, J P Re 22398 307 24% F cedure P. Regian 2: Office of Director B3/10/06 24% Fiche 50-062:84/02/16:8402280261
- --8402280293 Forwards IE Insp Rept 50-062/83-02 on 830602-03 & 0706-08 LEWIS.R C Division of Project & Resident Programs 83/10/06 PRENIZER, J B Virginia. Univ of Charlottesvillo, VA 1p 22398 311 24% Fiche 50-062.84/02/16.8402280261
- --8402280300 IE Insp Rept 50-062/83-02 on B30602-03 & 0706-08 Violations noted failure to meet shutdown margin requirements & inadequate procedures for calculating estimated critical B402280261
- DUCKET 50-70 GENERAL ELECTRIC TEST REACTOR
- 8402070007 Confirms conversation w/Judge Linenberger Extension granted until 840210 to respond to petitioner revised contentions TURK.8 E Hearing Branch 1 84/02/02 FRVE.J H, FOREMAN.H, LINENBERGER, G Atomic Befety and Licensing Board Panel 1p 22102 322 24X Fiche 50-070.84/02/02.8402070007
- 8402080196 Notice of 840306 prehearing conference in San Francisco, CA to hear response of J Turk to arguments raised by GE & NRC re Turk contentions FRYE.J H Atomic Safety and Licensing Board Panel 84/02/06 1p 22130 149 24% Fiche 50-070,84/02/06.8402080176
- 8402220182 Response to petitioner J Turk initial & revised contentions Petitioner failed to present admissible contention & petition to intervene should be denied Certificate of Syc enci TURK/S E Hearing Branch 1 84/02/10. Atomic Safety and Licensing Board Panel 56pp 22340 237 24X Fiche 50-070,84/02/10, 8402220182
- 84021400B2 Notice that 840306 prehearing conference in 8am Francisco, CA rescheduled to 840305 FRYE.J H Atomic 8afety and Licensing Board Panel 84/02/13 lp 22217 262 24% Fiche 50-070, 84/02/13, 8402140082
- 8402240053 Notice of cancellation of prehearing conference scheduled for 840306 Conference will be rescheduled FRYELJ H Atomic Safety and Licensing Board Panel 84/02/22 1p 22374 360 24% Fiche 50-070,84/02/22,8402240053
- 8402270085 Memorandum & order requesting raply to listed issues of GE & staff responses to proposed contentions Response by 840330
 - requested FRYE.J H Atomic Bafety and Licensing Board Panel 84/02/28 TURK.J Turk. J 2pp 22428 096 24X Fiche 50-070,84/02/28, 8402270085

DOCKET 50-72 UNIV OF UTAH RESEARCH REACTOR

@ Inspection reports, IE Bulletins & correspondence

B4022R0274 Ack receipt of B30603 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 90-072/83-01 Revised info.including Tech Spec amend submittal date, requested within 30 days of ltr date OAGLIARDO.J E Region 4. Office of Director B3/11/10 JACOBS, HR Utah, Univ of, Salt Lake City, UT 1p 22337 069 24% Fiche 50-072.83/11/10,8402220274

--8402280274 Responds to NRC 830511 ltr re violations noted in IE Insp Rept 50-072/83-01 Corrective actions Tech Specs re surveillance tests will be amended as stated SANDQUIST.G M, JACOBS.H R Utah. Univ of, Salt Lake City. UT 83/06/03 Region 4, Office of Director 2pp 22337 070 24X Fiche 50-072.83/11/10.8402220274

DOCKET 50-83 UNIV OF FLORIDA TRAINING REACTOR

F Becurity, medical, emergency & fire protection plans

8402160367 Forwards proprietary resubmission of Rev 7 to physical security plan Rev withheld (ref 10CFR2 790)
VERNETBON.W 6 Florida. Univ of. Gainesville. Fl. 84/02/01
0/REILLY.J P Region 2. Office of Director 1p 22269 124 24)
Ficha 80-083.84/02/01.8402160367

DOCKET 50-87 WESTINGHOUSE CRITICAL EXPERIMENT

P. Operating license stage documents & correspondence

B402170467 Requests listed info on Westinghouse topical repts for generic topical rept program Response by 840219 requested THOMAS, C O Standardization & Special Projects Branch 84/02/09 RAHE, E P Westinghouse Electric Corp ip 22305 345 24% Fiche 30-087,84/02/09,8402170467

DOCKET 50-89 GENERAL ATOMIC CD

P Operating license stage documents & correspondence

B402230428 Responds to Hogan B31013 & 1111 ltrs re transfer of Licenses R-38 & R-67 from GA Co to GA Technologies, Inc Requests confirmation that personnel managing facility operations are predominately former GA personnel THOMAS.C O Standardization & Special Projects Branch B4/02/06 MDHRY,W R GA Technologies. Inc /General Abomic Co 4pp 22380 036 84X Fiche 50-089,84/02/06.8402230428

B402280496 Confirms that all former officers & employees of OA Co now employees of GA Technologies, in response to NRC 840206
Itr Organizational structure remains unchanged
MOMRY, WR GA Technologies, Inc./General Atomic Co 84/02/22
THOMAS, C G Standardization & Special Projects Branch 1p
22407 080 24X Fiche 50-089,84/02/22,8402280496

R. Periodic operating reports & related correspondence

8402240132 Annual rept for 1783 MUNRY, W R QA Technologies, Inc /General Atomic Co 84/02/22 THOMAS, C D Standardization & Special Projects Branch Spp 22373 343 24X Fichs 50-089, 84/02/22, 8402240132.

DOCKET 50-124 VIRGINIA POLYTECH INST TRAINING REACTOR

S Reportable occurrences, LERs & related correspondence

8402130345 RD on 840117.breaker which supplies nuclear instrument cabinet tripped Breaker shut, reenergizing SDLA which caused transient on uninterruptible power supply & voltage dropped enough to sound radiation alarm HDLIAN,P D. PARKINSON,T F Virginia Folytechnic Institute & State Univ., Blacksburg, VA 84/02/01 0'REILLY,J P Region 2, Office of Director 3pp 22197,278 24X Fiche 50-124,84/02/01,8402130345

DOCKET 50-128 TEXAS ALM UNIV RESEARCH REACTOR

F Security, medical, emergency & fife protection plans

8402070348 Advises that requirements of Category III physical security met fullowing shipment & transfer of 1.106 g U-235 in form of TRIGA FLIP elements, by Idaho Falls, ID Shipment completed in Aug 1983
FELTZ, D E Texas A&M Univ . College Station, TX 84/01/30
1HOMAS C 0 Standardization & Special Projects Branch 1p 22097 038 24X Fiche 50-128,84/01/30,8402070348

5 Reportable occurrences, LERs & related correspondence

8311030079 Forwards final rept of RD on 831004 re possible operation in excess of licensed power level FLUTZ.D E Texas A&M Univ. College Station, TX 83/10/28 MADSEN.O L Region 4. Office of Director ip 22376 034 247 Fiche 50-128.83/10/28.8311030097

--8402270367 Confirms 831013 telcom requesting that due date of final rept re 831006 occurrence be extended to 831027 FELTZ, D E Texas ABM Univ , College Station, TX 83/10/17 CROSSMAN, B Region 4, Office of Director 1p 22396 073 24% Fiche 50-128,83/10/28,8311030099

DOCKET 50-193 HUMDOLD1 BAY POWER PLANT, UNIT 3

G Adjudicatory correspondence

B402040042 Memorandum & order requesting comments on Joint Intervenors
B40124 documents re public involvement in docommissioning
plan & opposition to applicant request for deletion of
Item E(2)(e)
LAZO,R M Atomic Safety and Licensing Board Panel B4/02/02
Office of the Executive Legal Director 2pp 22088 223 24X
Fiche 50-133.84/02/02.8402040042

8402280197 Response to ASLB 840202 order for comments on two documents filed by Joint Intervenors on 840126 Certificate of Svcenci encl CRANC,P A Pacific Gas & Electric Co 84/02/21 Atomic Safety and Licensing Board Panel Spp 22400 072 24X Fiche 50-133.84/02/21.8402280197

8402270084 Comments on Joint Intervenors 840126 statement on public involvement in decommissioning plan & opposition to util request for deletion of Item E(2)(e) of OL Certificate of Svc encl VOUNO.M A Hearing Branch 4 84/02/22 8pp \$2387 271 24X Fiche 50-133,84/02/22,8402270084

P Operating license stage documents & correspondence

8402070234 Responds to 840105 Generic Ltr 84~01 re use of terms important to safety & safety-related Util participation in response will be through steering committee & chairman of util safety classification group SCHUYLER.J O Parific Oas & Electric Co 84/02/03 TAYLOR.J M Director's Office, Office of Inspection and Enforcement ip 22101 142 24X Fiche 50-000,84/02/03,8402070234

8402210082 Responds to 831101 Generic Ltr 83-36 re Tech Spec review against requirements of NUREG-0737 & application for license amends in noncompliance areas Amends to change OL to possession-only will be requested in early 1984 BCRUYLER, J D Pacific Gas & Electric Co 84/02/13 EISENHUF, D G Division of Licensing Ip 22317 332 24X Fiche 50-133,84/02/13,84/02/1082

8402170013 Forwards environ evaluation rept for disposal of 1.300 cubic ft oily water separator sludge Rept describes method & conditions of disposal topography, geology meteorology & groundwater & surface hydrology at Benicia site SCHUYLER: J D Pacific Oas & Electric Co 84/02/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 22300 278 24X Fiche 50-133.84/02/14.8402170013

O Inspection reports, IE Bulletins & correspondence

G312120153 IE Info Notice 84-06. "Steam Binding of Auxiliary Feedwater Pumps" Byc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 630103) 64/01/25 Consolidated Edison Co of New York, Inc. 120pp 22058 001 24X Fiche 50-000.64/01/25, 8312120153

- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co. of New York, Inc 119pp 22114 179 24% Fiche 50-000.84/02/03.8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Newders " Svc list encl DEVOUNG.R C Director's Office. Office of Inspection and Enforcement B4/02/03 Consolidated Edison Co of New York. Inc 102pg 22177
- 8401170041 IE Info Notice 84-07, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (100FR50, App R)" Syc list enc!

 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365 257 24% Fiche 50-000.84/02/13.8401170041
- 8401190039 IE Info Notice 84-08. "100FRSD 7. 'Employer Protection '"
 Swc list encl
 JURSBAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24X Fiche. 50-000.84/02/14.8401190039
- 8401190045 IE Info Notice 83-63. Suppl 1. "Potential Pailures of Hestinghouse Type SA-1 Differential Relays " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc 118pp 22366 142 24X Fiche 50-000.84/02/15, 8401190045
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Piche 50-000,84/02/21,8401190062
- B401190066 IE Info Notice 84-11, "Training Program Deficiencies "
 Svc list encl
 JORBANE L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B4/02/24 Connolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000.B4/02/24,B401190066
- 8401170067 LE Info Notice 84-12, "Failure of Soft Seat Valve Beals"
 Svc list enc!
 JORDAN, EL Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co. of New
 York, Inc. 120pp 22431 060 24X Fiche 50-000,84/02/27,8401170067
- 8 Reportable occurrences, LERs & related correspondence
- 8402070232 LER 84-001-09 on 840103, airflow through standby gas treatment sys observed to be above Tech Spec limits Caused by disengaged valve actuator & shaft Linkage reconnected W/840202 ltr NELSON, R T , SHIFFER, J D Patific Gas & Electric Co 84/02/02 3pp 22101 143 24% Fiche 50-133,84/02/02,8402070232
- X Onsite Storage of Low Level Waste
- B4022B0036 Forwards Figure 1, "Benicia Bite Location" & Figure 2, "Wind Rose for Benicia Site" inadvertently amitted from 840214 ltr re very low level radwaste disposal SCHYLER. O Pacific Qas & Electric Co 84/02/23 DENTON, M R Office of Nuclear Reactor Regulation, Director 3pp 22398 001 24% Ficha 50-133,84/02/23,8402280036
- DOCKET 50-139 UNIV OF MASHINGTON RESEARCH REACTOR

 R Periodic operating reports & related correspondence
- 8402050463 Annual operating rept for 1983.W/840130 ltr ROBKIN.M A Washington, Univ of, Seattle, WA 83/12/31 5pp 22083 124 24% Fiche 50-139,83/12/31,8402050463
 - *KET 50-142 UCLA TRAINING REACTOR

 Becurity, medical, emergency & fire protection plans
 - 2020135 Ack receipt of BA0110 ltr informing NRC of steps taken to orrect violations noted in JE Insp Rept 50-142/83-04 HENSLAHSKI,F A Region 5. Office of Director 84/01/30, WEGST,W F California, Univ of, Los Angeles, CA 1p 22056 170 24% Fiche 50-142.84/01/30,8402020135

- --B40202013B Responds to NRC 831205 ltr re violations noted in IE Insp Rept 50-142/B3-04 Corrective actions emergency drill conducted on B91220 WEGST, W.F. California, Univ. of, Los Angeles, CA. 84/01/10 SCARAND, R. A. Region 5, Office of Director. 4pp. 22056 171 24X Fiche 50-142, B4/01/30, 8402020135
- G Adjudicatory correspondence
- 8402020030 Response to ASLB 840118 order for proposed list of persons to be authorized access to protected info Certificate of Svc enci
 HDDDHEAD, C P Hearing Branch 4 84/01/25 Atomic Safety and Licensing Board Panel 5pp 22056 325 24% Fiche, 50-142, 84/01/25, 8402020030
- 8402010213 Response in opposition to Committee to Bridge the Gap 840109 motion to curtail licensee activities No factual or legal basis for motion exists Cartificate of Svc encl.
 HODDMEAD, C.P. Hearing Branch 4 84/01/26, Atomic Safety and Licenting Board Panel 22pp 22040 134 24X Fiche 50-142,84/01/26,8402010213
- 8402070237 Response objecting to release of certain protected info. Proposed sanitized portions of security plan should be released only to qualified witnesses Certificate of Syc encl CORMIFER. W H California, Univ of, Los Angelas, CA 84/01/31 Atomic Safety and Licensing Board Panel App 22101 032 24X Fichs 50-142,84/01/31,8402070237
- 8402070040 Objection to persons proposed by Committee to Bridge the Gap to be granted access to protected info re Contention XX Certificate of Svc encl WOODHCAD, C P Hearing Branch 4 84/02/01 Atomic Bafety and Licensing Board Panel 10pp 22103 001 24X Fiche 50-142,84/02/01,84020/0940
- 8402070256 Response objecting to applicant/NRC proposed witnesses & proposed mod to protected order Witnesses do not qualify as experts Declaration of Svc enc! HIRSCH.D Committee to Bridge the Oap 84/02/01 Atomic Safety and Licensing Board Panel opp 22101 184 24X Fichs 50-142.84/02/01.8402070256
- 8402080142 Informs of author self-recusal from further participation in OL renewal hearing, based on future discussions w/NRC & parties re possible conversion to low enriched U GLINSKY. V Commissioners 84/02/06 Office of the Executive Legal Director ip 22132 042 24X Fiche 50-142,84/02/06,8402080142
- 8402210167 Ack receipt of 840206 memorandum re recusal from further participation in renewal proceeding Addl clarification requested HIRECH.D Committee to Bridge the Oap 84/02/13 OILINSKY, V Commissioners 1p 22316 347 24X Fichs 50-142,84/02/13,8402210167
- 8402220137 Summary of 840206 site visit, including tour of control room, reactor room & fresh fuel storage facility
 TRUBATCH. B.L. NRC No Detailed Affiliation Given 84/02/15 NRC
 No Detailed Affiliation Given 1p 22337: 268 24X
 Fiche 50-142,84/02/15,8402220137
- 8402220162 Motion denying Committee to Bridge the Gap 740109 motion for reactor curtailment No factual or legal basis exists to support extreme remedy sought W/Certificate of Svc. CORNIER, M. H. California, Univ. of, Los Angeles, CA. 84/02/16. Atomic Safety and Licensing Board Panel 15pp 22338-006 24X Fiche 50-142,84/02/16,840222016R
- B40R220GAO Advises that review of shutdown analysis complete Complaint re timeliness of UCLA security plan defended HIRSCH D Committee to Bridge the Oap. 84/02/16 FRYE, LUEBKE, BRIOFT Atomic Safety and Licensing Board Panel. ip . 22335:343 24X Fiche 50-142.84/02/16.8402220360
- 8402280399 Order to serve on Committee to Bridge the Gap & ABLB description of physical security plan level of threat of sabotage & staff evaluation of level of threat. LUEBKE, E A . BRIGHT, 6 O . FRYE, J H. Atomic Safety and Licensing Board Panel 84/02/24 Office of the Executive Legal Director ip 22405 025 24% Fiche 50-142,84/02/24,8402280399
- 8402280450 Order requesting Univ of California & NRC indicate by B40309 extent of awareness re representations being made by counsels of approval & whether any corrections sought LUBME, E A . BRIGHT, 0 O . FRYE, J. H. Atomic Sefety and Licensing Board Panel 84/02/24 7pp 22406 354 24X Fiche 50-142,84/02/24,8402280450

- Q Inspection reports, IE Bulletins & correspondence
- 8402020135 Ack receipt of 840110 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-142/83-04
 WENSLAWEKI F A Region 5. Office of Director 84/01/30 WEOST.N F California, Univ of Las Angeles. CA 1p 22056 170 24X
 Fiche 50-142.84/01/30.8402020135
- --840202013B Responds to NRC 831205 ltr re violations noted in IE Insp Rept 50-142/83-04 Corrective actions amergency drill conducted on 831220 WEOBT, W F California, Univ of, Los Angeles, CA 84/01/10 BCARANO, R A Region 5, Office of Director 4pp 22056 171 24x Fiche 50-142,84/01/30,8402020135

8 Reportable occurrences, LERs & related correspondence

B402160059 RD during annual reactor calibr.two control blades exhibited prolonged drop times.one slightly exceeding acceptability limit Problem lies within core Steady viscous drag indicated possibly due to lubricant degradation ME097.W F Galifornia, Univ of. Los Angeles. CA 84/02/i3 NRC - No Detailed Affiliation Given ip 22276 246 24X Fiche 50-142.84/02/i3.8402160059

T Hearing transcripts on non-antitrust matters

8402150367 Transcript of 840209 prehearing conference in Los Angeles, CA re proposed renewal of OL Pp 3:173-3:366 * Atomic Safety and Licensing Board Panel 84/02/08 173pp 22242 145 24X Fiche 30-142,84/02/08,8402150367

8402190351 Transcript of 840209 prehearing conference in Los Angeles, CA re proposed renewal of OL Pp 3:367-3:408

* Atomic Safety and Licensing Board Panel 84/02/09 42pp
22244, 183 24X Fiche 50-142, 84/02/09, 8402150351

DOCKET 50-146 SAXTON NUCLEAR EXPERIMENTAL FACILITY

1, Financial information

8402060180 Forwards financial statement for 1983 MONTOOMERY.C R Sarton Nuclear Experimental Corp 84/01/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 22087.198 24X Fiche 30-146.84/01/30.8402060180

J Insurance & indemnity information

8402020240 Forwards Endorsements 80 & 81 to NELIA Policy NF-107 MONTODMERY, C. R. General Public Utilities - OPU Service Corp 84/01/17 Office of Nuclear Reactor Regulation, Director 3pp 22057 018. 24X Fichs 50-146.84/01/17,8402020240

R Periodic operating reports & related correspondence

B40R270074 "Annual Rept. 1983. Baxton Nuclear Experimental Corp "
W/840214 1tr
HEMARD, R. W. General Public Utilities - GPU Service Corp 83/12/31
THOMAS, C. E. Office of Nuclear Reactor Regulation, Director 9pp
22387 279 24X Fiche 50-146, 83/12/31, 8402270074

DOCKET 50-148 UNIV. OF KANEAS REBEARCH REACTOR

P Operating license stage documents & correspondence

8402040321 Forwards request for addl info re discrepancies arising during Dec 1983 visit to facility re renewal of OL, Response regulated within 20 days of reciept of 1tr.
THOMAS.C. D. Standardization & Special Projects Branch 84/01/24
NESLER,R Kansas State Univ of Agriculture & Applied Science App 22110:306 24X Fiche: 50-148,84/01/24,8402040321

V Operator Examinations

- 8402070166 Forwards revised requalification program for licensed operators. In response to CO Thomas 840116 ltr.
 MEGLER.R. B Kansas, Univ of, Lawrence, KB 84/01/31 CHU, A NRC
 No Detailed Affiliation Given ip. 22101:110. 24X
 Fichs 50-148.84/01/31.8402070166
- --B402070170 Revised requalification program for licensed operators. # Kansas, Univ. of. Lawrence, KB B4/01/31 4pp 22101 111 24X Fiche: 50-148, 84/01/31, 8402070166.

DDCKET 50-151 UNIV OF ILLINDIS RESEARCH REACTOR

R Periodic operating reports & related correspondence

8402190232 "Annual Rept.1983 " W/840208 ltr BECK.0 P . HOPKE, P K . MILEY.0 H Illinois, Univ of, Urbana, IL 83/12/31 8pp 22245 105 24% Fiche 50-151.83/12/31.8402150232

DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

8402220501 Revised emergency implementing procedures, including Rev 1 to App C, "Review & Rev of General Ofc Control Ctr/Emergency Operations Facility Emergency Implementing Procedure" & revised index 4/840217 ltr * Consumers Power Co 84/01/10 10pp 22333 298 24X Fiche 50-000.84/01/10.8402220501

8402150395 Rev 5 to "Controlled Copyholders List Ceneral Dfc Control Ctr/Emergency Operations Facility Emergency Implementing Procedures " W/840209 ltr * Consumers Power Co 84/01/26 Bpp 22242 O61 24X Fiche 50-000.84/01/26.8402150395

8402030412 Forwards Rev 41 to emergency plan implementing procedures, Vol 9A * Consumers Power Co 84/01/27 Office of Nuclear Reactor Regulation, Director 4pp 22048 307 24X Fiche 50-155, 84/01/27, 8402030412

8402070345 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per 830707 ltr W/o request entire plan will be placed in PDR. Distribution list encl CRUTCHFIELD. D Deparating Reactors Branch 5 84/02/06 VANDEMALLE, D J Consumers Power Co 3pp 22097 021 24 X Fichs 50-000,84/02/06,8402070345

B402170227 Informs that State of MI & Charlevoix & Emmet Counties will not participate in facility 840522 annual emergency exercise, per FEMA rule 4405R350 & encl FEMA instructions Exemption requested, per Info Notice 84-05 Related info encl VANDEWALLE, D J Consumars Power Co 84/02/13 CRUTCHFIELD, D Operating Reactors Branch 5 Bep 22299 326 24X Fichs 50-155,84/02/13,8402170227

B402290244 Forwards IE Insp Rept 50-155/83-19 on B31117-B40131. No noncompliance noted SHAPER. W D Region 3. Office of Director B4/02/15 DEWITT.R D Consumers Power Co 2pp 22427 309 24X Fiche 50-155.04/02/15. 6402270244

--8402270254 IE Insp Rept 50-155/83-19 on 831119-840131 No noncompliance or deviation noted Major areas inspected license action on previous insp findings, operational safety, maint, surveillance, LERs, TMI item review & fire protection MRIOHT, O C., BDYD, D C. Region 3. Office of Director 84/02/09 4pp 22427 311 24X Fiche 50-155,84/02/15,8402290244

8402270377 Requests FR publication of notice of consideration of Amend 65 to License DPR-6 & proposed NSHC determination & opportunity for hearing Amend approves changes to guard training & qualification plan CRUTCHFIELD, D. Operating Reactors Branch 5 84/02/17 MILLER, J R Operating Reactors Branch 3 2pp 22438 234 24X Fiche 50-155,84/02/17,8402270377

8402290382 Forwards Amends 65 to License DFR-6 & safety evaluation Amend deletes two types of shoulder weapons as guard response weapon from guard training & qualification plan. CRUTCHFIELD.D Operating Reactors Branch 5 84/02/17 VANDEHALLE,D Consumers Power Co 4pp 22498 225 24X Fiche 30-155.84/02/17.8402290382

---8402270385 Amend 65 to License DPR-6, deleting two types of shoulder weapons as guard response weapons from guard training & qualification plan
CRUTCHFIELD, D Operating Reactors Branch 5 84/02/17 3pp
22438 229 24X Fiche 50-155,84/02/17,8402270382

--B402290387 Bafety evaluation supporting Amend 65 to License DPR-6 * Office of Nuclear Reactor Regulation, Director 84/02/17 2pp 22438 231 24% Fiche 50-155,84/02/17,8402290382

BA02290076 Revised pages to emergency plan implementing Procedure EPIP-2 re facility actions during emergency W/840223 transmittel & receipt form * Consumers Power Co 84/02/21 Spp 22428 015 24X Fiche 50-155.84/02/21,8402290096

G Adjudicatory correspondence

- B402020024 Motion requesting right to file supplemental response to O'Neill proposed findings re south wall contention Cartificate of Svc encl GODDARD.R J Hearing Branch 3 BACHMANN,R G Hearing Branch 1 64/01/24 Atomic Safety and Licensing Board Panel 5pp 22006 337 24% Fiche 50-155,84/01/24,8402020024
- 8402030154 Response upposing J O'Neill 840123 motion for extension of time & apposing in part, NRC 840124 motion to file supplemental response to findings of fact Certificate of enc1 SVC BRC1 GALLD.J Consumers Power Co GALLO.J Isham, Lincoln & Beale 84/01/30 Atomic Safety and Licensing Board Famel App 22048 101 24x Fiche 50-155.84/01/30.8402030154
- 8402070194 Confirms that licenses 840127 motion for time extension & answer to D'Neill motion for further time extension withdrawn Documents superceded w/reply to motions for time extensions filed 840130

 COPELAND, V G lsham, Lincoln & Beals COPELAND, V G Consumers Power Co 84/01/31 BLOCK, P , PARIS, D H , SHDN, F J Atomic Safe and Licensing Board Fanel ip 22100 022 24%
 Fiche 30-155,84/01/31.8402070194 Atomic Safetu
- 8402030209 Motion for extension to B40210 to file reply to intervenor proposed findings of fact & conclusions of law Extension needed to allow licensee to respond to all proposed findings of fact in comprehensive manner Certificate of Svc encl COPELAND, V G Consumers Power Co COPELAND, V G Isham, Lincoln & Beale 84/02/02 Atomic Safety and Licensing Board Panel 4pp 22047 340 24X Fiche 50-155, 84/02/02, 8402030209
- --8402030212 Answer to J O'Neill motion for further extension beyond 840130 to file proposed findings of fact & conclusions of law Motion should be denied due to O'Neill already having sufficient time to respond COPELAND. V O Consumers Power Co COPELAND. V O [sham, Lincoln & Beale 84/02/02 Atomic Safety and Licensing Board Panel 2pp 22067 344 24X Fiche 50-155,84/02/02,8402030209
- 8402140202 Forwards staff proposed opinion findings of fact & conclusions of law re spent fuel pool mod J D'Neill proposed findings not received GDDDARD.R J Hearing Branch 3 BACHMAN,R G Hearing Branch 1 84/02/03 BLOCH.P B , SHON.F J , PARIS.D H Atomic Safety and Licensing Board Panel 2pp 22227 001 24X Fiche 50-155.84/02/03.8402140202
- --8402140210 NRC staff proposed findings & conclusions in mod of util proposed findings of fact & conclusions of law re several emergency planning subcontentions a Uffice of the Executive Legal Director. OALLO, J Consumers Power Co. 84/02/03 85pp 22229.003 24X Fiche 50-155.84/02/03, 8402140202
- --8402140215 NRC staff proposed spinion, findings & conclusions in mod of util draft spinion & proposed findings of fact & conclusions of law on south wall contention * Office of the Escutive Legal Director COPELAND, V G , OALLO, J Consumers Power Co 84/02/03 28pp 22229 093 24X Fiche 50-195,64/02/03,6402140202
- -8402140220 NRC staff proposed opinion, findings & conclusions in mod of util draft opinion & proposed findings of fact & conclusions of law on certain contentions. Certificate of * Office of the Erecutive Legal Director 84/0: 22229 123 24X Fiche. 50-155, 84/02/03, 8402140202
- .02140045 Proposed findings of fact & conclusions of law for Contention II-D re aircraft hazards d'NEILL.J O'Neill. J 84/02/07 44pp 22217 272 24X Fiche 50-155.84/02/07.8402140045
- 402:30259 Telecopy motion to strike P Yanev prafiled testimony slide exhibits & hearing testimony as irrelevant If denied motion should be considered as findings of fact & conclusions of Daw Related correspondence
 O'NEILL, JO'Neill, J 84/02/09 Atomic Safety and Licensing
 Board Panel Ip 22203 258 24X Fiche 50-155,84/02/09,8402130259
- |402150138 Findings of fact & conclusions of law on evacuation.makeup line & pool at elevated temp, shielding, crane & worker contention re south wall o'NEILL.J O'Neill.J J 84/02/07 19pp 22245 173 24X Fiche 50-155,84/02/07,8402150133

- --8402150147 Motion to strike testimony of P Yanev as irrelevant & inconclusive If denied, motion should be considered findings of fact & conclusions of law O'MEILL, J D'Neill, J 84/02/09 Atomic Safety and Licensing Board Panel 2pp 22245 192 24X Fiche 50-155,84/02/09,8402150133
- ---8402150153 Motion to submit testimony of A Schwarts re aircraft hazards as evidence if required O'NEILL.J O'Neill, J 84/02/09 Atomic Bafety and Licensing Beard Panel 1p 22245 194 24X Fiche 50-155,84/02/09, B402150133
- 8402160197 Motion to strike J O'Niell proposed findings on Contention II-D re aircraft hazards Certificate of Svc encl COPELAND, V G Consumers Power Co COPELAND, V G Isham, Lincoln & Beale 84/02/10 Atomic 8afesty and Licensing Board Panel 4pp 22275 273 24x Fichs 50-155.84/02/10,8402160197
- 8402210185 Comments on applicant 840210 motion to strike proposed findings of J O'Neill Good cause provided in motion to Atomic Safety and Licensing Board Panel 2pp 22316 328 24X Fich So-155,64/02/13,8402210185
- 8402210345 Forwards motion for leave to file out of time & reply to Christa-Maria & J Bier proposed findings of fact & conclusions of law re spent fuel pool mod GALLOJ Isham. Lincoln & Beale 9ALLOJ Consumers Power Co 84/02/14 BLOCH.P., PARIS.O H. SHON,F. J Atomic Safety and Licensing Board Pamel 2pp 22315 258 24% Fiche 50-155,84/02/14.
- --8402210347 Motion for leave to file out of time reply to Christa-Mario & J Bier proposed findings of fact
 @ALLO, J Consumers Fower Co GALLO, J Isham, Lincoln & Bedie 84/02/14 Atomic Bafety and Licensing Board Panel 2pp 22315 260 24X Fiche 50-155.84/02/14,8402210345
- --B402210353 Reply opposing Christa-Haria & J Bier B40i18 & 20 findings of fact & conclusions of law, respectively Centificate of Svc encl GALLO, J, COPELAND, V G Consumers Power Co GALLO, J, Ish Lincoln & Bealt B4/02/14
- 840223013B Forwards INPO evaluation rept & JL Bier affidavit re relationship of INPO findings on radiation practices & proposed installation of three spent fuel racks QALLO.J Isham. Lincoln & Beale GALLO.J Consumers Power Co 84/02/20 BLDCH.P.B., PARIS.O H., SHON.F.J Atomic Bafety and Licensing Board Panel 41pp 22361 233 24X Fiche 50-155,84/02/20. 8402230138
- --B402230141 Affidavit of JL Beer re INPO findings on radiation DESCRIPTION OF THE PROPERTY OF
- 8402280430 Response partially apposing J O'Neill 840209 motion to accept filings out-of-time & motion for extension of time Dbjects to motion to strike testimony of P Yanev Na good cause shown Certificate of Bvc encl
 COPELAND, V O Consumers Power Co COPELAND, V O Isham. Lincoln & Beale 84/02/22 Atomic Safety and Licensing Board Panel App 22403 023 24X Fiche 50-155.84/02/22.8402280430
- P Operating license stage documents & correspondence
- 8312120029 Generic Ltr 83-39 to representatives of utils re voluntary survey of licensed operators Svc list encl EISENHUT.D Q Division of Licensing 83/12/08 Commonwealth Edison Co 12pp 22313-006 24% Fiche 50-000.83/12/08.8312120029
- 8402070509 Requests remittance of add1 fee for review of licenses B10720 application for Amend 64 to License DRR-6.changing Tech Specs re mechanical snubbrs attached to depressurization sys Class III fee appropriate DIGGS.R. License Fee Management Branch 84/02/02 VANDEWALLE, Consumers Power Co ip 22141 275 24X Fiche 50-155,84/02/02.8402070509 VANDEWALLE, D. J
- B4020B0114 Forwards rept on issues for which resolution considered complete re integrated plant safety assessment (NUREG-0828) Info provided per B31107 commitment RICH: R M Consumers Power Co 84/02/02 CRUTCHFIELD, D Opera Reactors Branch 5 88pp. 22127 270 24X Fiche 50-155,84/02/02,8402080114 Operating

- 8402090084 Responds to Generic Ltr 83-36, "NUREG-0737 Tech Specs "
 Review of listed items indicates that either Tech Spec
 change requests submitted or NRC granted relief
 VANDEWALLE, D. J. Consumers Power Co. 84/02/06 CRUTCHFIELD, D.
 Operating Reactors Branch 3 3pp. 22160 215 24%
 Fiche 50-155,84/02/06,8402090084
- 8402160314 Forwards addi amend fee for Tech Spec change request dtd 810720 re mechanical snubber surveillance Request involved single safety issue as well as administrative change KRICH.R M Consumers Power Co 84/02/13 MILLER,W () License Fee Management Branch 1p 22277 021 24X Fiche 50-155,84/02/13,8402160314
- 6402220016 Notification of 840222 meeting w/util in Bethesda.MD to discuss 840202 update to expanded SEP integrated assessment EMCH.R L Operating Reactors Branch 5 84/02/17 CRUTCHFIELD.D Operating Reactors Branch 5 Spp 22326 015 24X Fiche 50-155.84/02/17.8402220016
- 8402290377 Requests FR publication of notice of consideration of Amend 65 to License DPR-6 & proposed NSHC determination & opportunity for hearing Amend approves changes to guard training & qualification plan CRUTCHFIELD.D Operating Reactors Branch 5 84/02/17 MILLER.J R Operating Reactors Branch 3 2pp 22438 234 24X Fiche.50-155.84/02/17.8402290377
- 8402270382 Forwards Amends 65 to License DPR-6 & Safety evaluation Amend deletes two types of shoulder weapons as guard response weapon from guard training & qualification plan CRUTCHFIELD, D. Operating Reactors Branch 5 84/02/17 VANDEWALLE, D. Consumers Power Co 4pp 22498 225 24X Fiche 50-155,84/02/17,8402270382
- --B402270385 Amend 65 to License DPR-6 deleting two types of shoulder weapons as guard response weapons from guard training & qualification plan GRUTCHFIELD, D Operating Reactors Branch 5 84/02/17 3pp 22438 227 24X Fiche 50-155.84/02/17.8402290382
- --84022903B7 Bafety evaluation supporting Amend 65 to License DPR-6 * Office of Nuclear Reactor Regulation, Director 84/02/17 2pt 2243B 231 24X Fiche 50-155.84/02/17,8402270382
- B402230012 Notifies of variance from requirements of NUREQ-0737 Recent review of stack gas monitors revealed that display capabilities not in accord w/NUREQ-0737, Item II F 1 1 VANDEWALLE, D.J. Consumars Power Co. 84/02/20 CRUTCHFIELD, D. Operating Reactors Branch 5 2pp 22362 058 24X Fichs 30-000,84/02/20.8402230012
- G Inspection reports, IE Bulletins & correspondence
- 8312120153 IE Info Notice 84~05. "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl. JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/25. Consolidated Edison Co of New York, Inc 120pp 22058:001 24X Fiche.50~000.84/01/25.8312120153
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114,179, 24X Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01. "Cracks in BWR Mark I Containment Vent Headers " Syc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement B4/02/03 Consolidated Edison Co of New York, Inc 102pp R2177
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Bafe Shutdown Bys (100FR50, App R)" Svc list encl.

 JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365:259, 24% Fiche.50-000.64/02/13.8401190041
- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '"
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22365,141 24X Fiche 50-000,84/02/14,8401190039
- B401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Fost B30103). B4/02/15 Consolidated Edison Co of New York, Inc. 118pp 22366 142 24X Fiche 50-000.84/02/15,8401190045

- 8402210091 Informs that ASME Nuclear Code pumps & spare parts mfg by Hayward Tyler Pump Co not used at facilities, in response to IE Bulletin 83-05
 JDHNSDN B D Consumers Power Co 84/02/15 CRUTCHFIELD, D Operating Reactors Branch 5 1p 22317 231 24X
 Fichs 50-000.84/02/15.8402210091
- 8402290244 Forwards IE Insp Rept 50-155/83-19 on B31119-840131 No noncompliance noted SHAFER: W D Region 3. Office of Director 84/02/15 DEWITT, R B Consumers Power Co 2pp 22427 309 24X Fiche 50-155,84/02/15, 8402290244
- --8402290254 IE Insp Rept 50-158/83-19 on 831119-840131 No noncompliance or deviation noted Major areas inspected license action on previous insp findings.operational safety, maint, surveillance, LERs. TMI item review & fire protection WRIGHT, 0 C , BOYO. D C Region 3. Office of Director 84/02/09 App 22427 311 24x Fiche 50-155,84/02/15,8402270244
- B401190062 IE Info Notice B4-10. "Notor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York. Inc 116pp 22366 024 24X Fiche 50-000.04/02/21,8401190062
- B401190066 IE Info Notice B4-11, "Training Program Deficiencies"
 Svc list encl
 JORDAN.BL Division of Emergency Preparedness & Engineering
 Response (Post B30103) B4/02/24 Consolidated Edison Co of New
 York, Inc 315pp 22430
- 8401190067 IE Info Notice B4-12, "Failure of Soft Seat Valve Seals "

 Bvc list enc!

 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc. 120pp 22431 060 24X Fiche 50-000.84/02/27,8401190067
- 8 Reportable occurrences, LERs & related correspondence
- 8402280372 PND-III-84-020 on 840282, during routine surveillance test, three of four reactor depressurization sys isolation valves failed to open Licensee contacted valve vendor for assistance in evaluating incident WRIGHT. 9. BDYD, D. SHAFER. W. Region G. Office of Director 84/02/23 ip R2405 018 24X Fichs 50-155.84/02/23, 8402280372

DOCKET DO-163 GENERAL ATOMIC CO

- P Operating license stage documents & correspondence
- B40223042B Responds to Hogan B3i013 & iiii ltrs re transfer of Licenses R-3B & R-67 from OA Co to OA Technologies, Inc Requests confirmation that personnel managing facility operations are predominately former OA personnel THOMAS, C O Standardization & Special Projects Branch B4/02/06 MDRRY, W R GA Technologies, Inc (Jeeneral Atomic Co 4pp 22380 036 24% Fiche 50-089, 84/02/06, 8402230428
- 8402280496 Confirms that all former officers & employees of GA Co now employees of GA Technologies. In response to NRC 840206 ltr Organizational structure remains unchanged MDMRY, M R GA Technologies, Inc / General Atomic Co 84/02/22 THOMAS, CO Standardization & Special Projects Branch 1¢ 22407 080 24% Fiche 50-089,84/02/22,8402280496
- R Periodic operating reports & related correspondence
- 8402270078 Annual operating rept for 1983 MDMRY.W R OA Technologies, Inc./General Atomic Co 84/02/22 THOMAB.C O Btandardization & Special Projects Branch 9pp. 22387.322 24X Fiche 50-163.84/02/22.8402270078

DOCKET 50-166 UNIV OF MARYLAND RESEARCH REACTOR

- B402010012 Requests addl info & clarification before completing review of "Reactor Operator Requalification Program for Maryland Univ Training Reactor"

 THUMAS, C O Standardization & Special Projects Branch 84/01/05

 IOLL J S Maryland Univ of College Park, MD 2ipp 22048 164

 B4X Fiche 50-166.84/01/05.8402010012
- B40R060431 Forwards response to request for clarification of licensee reactor qualification program
 TDLL,J B Maryland, Univ of, College Park, MD. 84/02/02
 THOMAS.C O Standardization & Special Projects Branch ip
 22083:236

- --8402060450 Responds to 840105 request for add1 info re reactor qualification program Students participate in one hands on lab session of 2 h duration each wk Relief from need for requalification lecture series requested BELCHER.R L . CADMAN.T W Maryland, Univ of College Park, MD 84/01/31 THOMAS,C O Standardization & Special Projects Branch 5pp 20083 237 24% Fiche 50-166.84/02/02.8402060431
- --8402060435 Rev 4 to "Reactor Operator Requalification Program for Univ of Maryland Training Reactor " * Maryland, Univ of. College Park, MD 84/02/01 16pp 22083 242 24X Fiche 50-126.84/02/02.8402080431

DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

G Adjudicatory correspondence

- B402140003 Forwards joint motion for approval of stipulation & withdrawal of intervenor, per B40203 telcon Transmittal of motion upon execution to licensee requested W/o enci TREBY, B A Hearing Branch i 84/02/09 ENTHISLE, E B Entwisle, E B ip 22217 355 24% Fiche 50-170,84/02/09,8402140003
- B402280314 Forwards joint motion for approval of stipulation & withdrawal of intervenor in license renewal proceedings RICKARD.D C Befanse, Dept of, Defense Ruclear Agency 84/02/24 HOYT.H Atomic Safety and Licensing Board Panel 1p 22399 056 24% Fichs 50-170,84/02/24.8402280314
- --8402280319 Joint motion for approval of stigulation & withdrawal of intervenor BACHMAN.R G Hearing Branch 1 ENTWISLE.E B Citizens for Nuclear Reactor Safety. Inc ENTWISLE.E B Entwisle. E B 84/02/24 Atomic Safety and Licensing Board Panel 3pp 22399 057 24X Fiche 50-170.84/02/24.8402280314
- ---8402280325 Joint stipulation resolving intervention by Citizens for Nuclear Reactor Safety ASLB may proceed u/summary disposition Certificate of Svc encl BACHMANN.R.Q Hearing Branch 1 ENTWISLE.E B Citizens for Nuclear Reactor Safety. Inc ENTWISLE.E B Entwiste. E B 84/01/17 7pp 22397 060 244 Fiche 50-170.84/02/24.8402280314
 - OCKET 50-171 PEACH BOTTOM ATCHIC POWER STATION, UNIT 1

Operating license stage documents & correspondence

- 402130013 Responds to FDIA request for two categories of documents ra IDCOR program Forwards App A & D documents Documents placed in FDR FELTON. JM Division of Rules and Records 83/12/21 SHOLLY, 8 C Union of Concerned Scientists 5pp 22282 004 24X Fiche 50-000.83/12/21,8402130013
- ~-8309260011 Summary of 830807-12 site visit & IDCOR meeting in Chicago.
 IL re status of data collection activity & containment capability
 BAGCHI.G Equipment Qualification Branch FIN A-6495 83/09/12
 Equipment Qualification Branch 5pp 22282 203 24X
 Fiche-50-000.83/12/21.84921300013
 - KET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR
 Advisory Committee on Reactor Bafeguards reports & correspondence
- 402010283 Summarizes ACRB 285th meeting on 840112-14 re license renewal & power increase Renewal of license at requested power level of 20 MN may be granted w/o undue risk to public health & safety EBERSOLE, J C ACRS Advisory Committee on Reactor Safeguards 84/01/17 PALLADINO.N J Commissioners 4pp 22044 336 24 Fiche: 50-184,84/01/17,8402010283
- 40205057; Forwards ACRS 840117 ltr re review of NBB application for license renswal & power increase ACRS concluded reasonable assurance reactor can operate at 20 MM w/g undue risk SSER supporting renewal can now be completed THOMAS:C G Standardization & Special Projects Branch 84/01/26 CARTER:R & Commerce. Dept of, National Bureau of Standards 2pt 22092 098 24% Fichs 50-184,84/01/26,8402060571

- DOCKET 50~192 UNIV OF TEXAS RESEARCH REACTOR
- P Operating license stage documents & correspondence
- 8402070482 Notification of 840201 meeting w/Univ of Texas in Bethesda, MD to discuss various aspects of CP & OL submissions for proposed reactor relocation & decommissioning BERNARD.H Standardization & Special Projects Branch 84/01/27 HHOMAS: C D Standardization & Special Projects Branch 2pp 22141 338 24% Fiche 50~192,84/01/27,8402070482

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

- O Adjudicatory correspondence
- 8402070128 Order extending time until 840213 for Commission to act to review Director's Decision DD-83-14 & extending 831029 decision denying Environ Policy Inst request to 840213 CHILK.S J Office of the Secretary of the Commission 84/02/03 Commissioners ip 22100 198 24X Fiche 50-000,84/02/03.8402070128
- 8402130195 Order extending time until 840221 for Commission to act to review Director's Decision DD-83-14 CHILK S J Office of the Secretary of the Commission 84/02/13 Commissioners ip. 22245 147 24X Fiche 50-000.84/02/13
- DOCKET 50-206 SAN ONDFRE NUCLEAR STATION, UNIT 1
 F Security, medical, emergency & fire protection plans
- 8402010016 Ack receipt of 831101 ltr transmitting notification of temporary change to physical security plan & addendum to change forwarded by 840113 ltr Changes do not degrade physical security plan & are consistent w/100FR90 54(p) SCHUSTER, H D Region 5, Office of Director 84/01/18 HAYNES, J C Southern California Edison Co 3pp 22048 153 24X Fiche 50-206,84/01/18,8402010016
- 8402070224 Forwards notification of temporary change to physical security plan Notification withheld (ref lOCFR73 21)
 HANNES, J O Southern California Edison Co 84/01/25 MARTIN, J B
 Region 5, Office of Director 1p 22096 166 24X
 Fiche 50~206,84/01/25,8402070224
- 8402140124 Forwards IE Insp Repts 50-206/84-01, 50-361/84-01 & 50-362/84-01 on 840107-12 No noncompliance noted BISHOP.T W Division of Resident, Reactor Project & Engineering Programs 84/01/31 849KIN,K B Southern California Edison Co 2pp 22218 233 24X Fiche 50-206,84/01/31,8402140124
- --8402140139 IE Insp Repts 50-206/84-01.50-361/84-01 & 50-362/84-01 on 840109-12 No noncompliance noted Major areas inspected fire protection computer sys, reactor coolant pump oil collection sys & LERs SCONN,K M Region 5, Office of Director 84/01/31 9pp. 22218 235 24X Fiche 50-206.84/01/31.8402140124
- 8402070207 Notifies of intention not to review emergency plans to delete privacy or proprietary into unless specific request received.per Generic Ltr 81-27 Entire plan will be placed in PDR & LPDR CRUTCHFIELD.D Operating Reactors Branch 5 84/02/02 BABKIN,K P Southern California Edison Co. Rpp. 22101 057 24X Fiche. 30-206.84/02/02.8402070207
- 8402130401 Responds to 831117 ltr re protection of safeguards info at util corporate records ctr Protection described. acceptable in accordance w/requirements of 10CFR73 21 & NURES-0794 KNIOHION, O W Licensing Branch 3 84/02/02. BASKIN, K. Bouthern California Edison Co HOLCOMBEJ C San Diego Qas & Electric Co 4pp 22216 181 24X Fiche 50-206.84/02/02.8402130401
- 8402150370 Supports NRC exemption for state & local govt participation in annual radiological preparedness exercise for facilities on 840229 KRIMN: Federal Emergency Management Agency. 84/02/08 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) ip 22242 135 24X Fiche 50-206,84/02/08,8402150370.
- 8402220565 Discusses IE Bafeguards Insp Repts 50-206/84-03.50-361/84-04 & 50-362/84-04 on 840124-26 No violations noted Major areas inspected selective exam of procedures & records & interviews w/personnel Insp repts withheld (ref lOCFR2 790) NORDERHAUG.L R Region 3, Office of Director 84/02/22. BASKIN.K B Southern California Edison Co 2pp 22333 336 24X Fiche: 50-206.84/02/22.8402220365

8402290180 Forwards revised integrated living schedule based on removing any SEP & fire protection safe shutdown backfits Outage schedules for three cycles of operation encl BASKIN, K P Bouthern California Edison Co 84/02/27 DENTON, H R Office of Nuclear Reactor Regulation, Director App 22419 175 24X Fiche 50-206,84/02/27,8402290180

I Financial information

- B402010454 FOIA request for review of Torrey Pines Technology study re ANI seismic design study & ANI & Insurance Svc Ofc last annual rept CALBOYAS, C D Affiliation Not Assigned 83/10/30 Region 5. Office of Director 4pp 22062 018 24X Fiche 50-206.83/10/30, 8402010454
- 8402010497 Responds to FOIA request for review of Torrey Pines Technology study re ANI seismic design Info contained in Feb 1982 Suppl 5 & June 1982 Suppl 6 to NUREG-0712, available in PDR FELTON, J M Division of Rules and Rocords 83/11/16 CALSOYAB, C D Affiliation Not Assigned 1p 22062 022 24X Fiche 50-206,83/11/16,8402010457

P Operating license stage documents & correspondence

- 8312120027 Generic Ltr 83-39 to representatives of utils re voluntary survey of liceneed operators Svc list encl EISENHUT.D G Division of Licensing 83/12/08 Commonwealth Edison Co 12pp 22313 006 24X Fiche 50-000.83/12/08.8312120029
- 840209040B Partial response to FDIA request for four categories of documents re NUREQ-75/087 (NUREG-0800), "SRP for Review of BARs for Nuclear Plants "Review of remaining documents incomplete Forwards App A documents FELTON, J M Division of Rules and Records 83/12/30 MADDEN, T J Kaye, Beholer, Fierman, Hays & Handler 4pp 22193 003 24X Ficher 30-000,83/12/30,8402090408
- --7903260077 Confirms 790301 teleon re interpretation of Tech Specs Section & 5 3 5a thall not impose requirements for reporting violations of Tech Specs beyond Section & 9 reporting requirements ZIEMANN,D L. Operating Reactors Branch 2 (Pre 790625) 79/03/0; DRAKE,J H Southern California Edison Co 2pp 22193 035 24: Fiche 50-000,83/12/30,8402090408
- 8402010136 Provides explanation why Amend 70 re exclusion of tritium from definition of E & addition of operational modes per STB should be Class II thange instead of Class III MEDFORD, M D Bouthern California Edison Co 84/01/30 DIGOS, R B License Fee Management Branch 2pp 22038 233 24X Fiche. 50-204, 84/01/30, 8402010136.
- 8402030211 Informs that add1 time required to process requested proposed Tech Spec 3 i 3 re RCS heatup & cooldown curves of Figures 3 i 32 & 3b Submittal can be made by 840315 MEDFORD, M O Southern California Edison Co 64/01/31 CRUTCHFIELD, D Operating Reactors Branch 5 ip 22067, 327 24X Fiche 50-206,84/01/31,8402030211
- 8402010410 Generic Ltr 84-04 to all operating PMR licensees, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Svc list enci EIBENHUT, D. O Division of Licensing 84/02/01. Consolidated Edison Co of New York, Inc. 59pp 22177 087 24X Fiche. 50-000,84/02/01,8402010410
- 8402080272 Summary of 840131 meeting w/util. Bethtel & IMPELL in Bathesda, ND re proposed reevaluation criteria for seismic ramplysis Main aspects of pipe support & structural member analyses discussed listed Related info encl MCKENNA, E M Derating Reactors Branch B 84/02/06 Operating Reactors Branch B 84/02/06 Operating Reactors Branch B 84/02/06, 84/02/06, 84/0280272
- 8402150383 Responds to Generic Ltr 84-01 re terms important to safety & safety-related As member of util safety classification group, supports further discussion on issue Ltr dtd 840126 sent requesting meeting MEDFORD, M O Southern California Edison Co 82/02/06 TAYLOR, J. M Director's Office, Office of Inspection and Enforcement ip 22242,088, 24X Fiche 50-206,84/02/06,8402150383
- 8402170061 Notification of B40210 meeting w/Transamerica Delaval, Inc (TDI) in Betheeda, MD to discuss program plan proposed by TDI Dwners Group to qualify diesel penerators CARUBO, R. Division of Licensing 84/02/06 BERLINGER, C. Division of Licensing. 2pp. 22312 339. 24X Fiche 50-000,84/02/06, 8402170061

- B402090064 Advises that extension of time required until B40229 to respond to B40106 request for addl info re Transamerica Delaval emergency diesel generators MRIEGER.R W Southern California Edison Co B4/02/07 CRUTCHFIELD.D Operating Reactors Branch 5 1p 22163 J24 24X Fiche 30-206.84/02/07.8402090064
- B402090172 Forwards "Eighty-fourth Percentile Vertical Response Spectrum for San Onofre Unit 1," per B31214 seismic reevaluation meeting & SEP Topic III-6 Spectra equal to two-thirds of horizontal response spectra appropriate for site MEDFORD.M O Southern California Edison Co B4/02/07 CRUTCHFIELD,D Deprating Reactors Branch 5 1p 22158 001 24x Fiche 50-206,84/02/07.8402090172
- --8402090174 "Eighty-fourth Percentile Response Spectrum for San Unofie Unit 1" * Sierra Geophysics, Inc 801-R-84-103 84/01/31 28pp 22158 QO2 24% Fiche 50-206,84/02/07,8402090172
- B402130350 Ack receipt of B40116 rept describing status of util efforts to locate items contaminated w/low levels of radioactive matl Conclusions reasonable WENSLAWSKI,F A Region 5, Office of Director B4/02/07 MCCARTHY.C B Southern California Edison Co ip 22203 300 24% Fiche 50-206,84/02/07.8402130350
- 8402100200 Forwards SER describing results of review of restart plan & identifying specific exception to criteria in 831223 proposal Plan acceptable DENTON.H R Defice of Nuclear Reactor Regulation, Director 84/02/08 BASKIN.K Southern California Edison Co 4pp 22178 259 24X Fiche 50-206,84/02/08,8402100200
- --8402100210 Safety evaluation re return to svc plan seismic reevaluation program Evaluation criteria adequate to assure hot standby capability in event of postulated SSE earthquake for short term * Office of Nuclear Reactor Regulation. Director 84/02/08 13pp 22178 263 24X Fiche 50-206,84/02/08.8402100200
- 8402210062 Declines participation in proposed BNL data gathering visit to operating reactors MEDFORD.M O Bouthern California Edison Co 84/02/13 CRUTCHTIELD.D Operating Reactors Branch 5 ip 22317 282 24X Fiche 50-206.84/02/13.8402210062
- 8402170224 Informs that electrical equipment anchorages reevaluated to 0 67g Housner as part of facility seismic reevaluation program for SEP Topic III-6.per util 810327, 820412 & 0628 ltrs Caiculation of disest generator cabinet encl HEDFORD.N O Bouthern California Edison Co 84/02/15 CRUTCHFIELD.D Operating Reactors Branch 5 14pp 22297 300 24x Fiche 50-206.84/02/15,8402170R24
- 8402170228 Forwards SER re valve operability reviews for 6-inch butterfly valves used for containment venturer util 791214, 800229 & 830909 ltrs Inrea demonstrating valve ability to close in event of LOCA requested within 30 days GRUTCHFIELD.D Operating Reactors Branch 5 84/02/16 BASKIN.K P Bouthern California Edison Co 3pp 22297.316 24X Fiche.50-206.84/02/16.8402170228
- ---B402170231 Safety evaluation re containment purge & vent valve operability (B-24) Info submitted did not demonstrate valve ability to close in event of LOCA WRIGHT, R. MCKENNALE Office of Nuclear Reactor Regulation.

 Director B4/02/16 5pp 22279 319 24X Fiche 50-206.84/02/16.8402170228
- B4022204B5 Forwards Amend 72 to License DPR-13 & mafety evaluation Amend increases pressurizer pressure-low trip setpoint in Tech Spec Table 3 5 5-2 CRUTCHFIELD, D. Operating Reactors Branch 5 84/02/17 BASKIN, K Bouthern California Edison Co. 2pp. 22340 06B 24X Fiche. 50-206, 84/02/17, 8402220485
- --B402220491 Amend 72 to License DPR-13, increasing pressurizer pressurelow trip setpoint in Tech Spec Table 3 5.5-2 from 1.685 psig to 1.735 psig & updating descriptive matl section CRUTCHFIELD, D. Operating Reactors Branch 5 84/02/17 12pp 22340:070 24X Fiche 50-206,84/02/17,8402220485.
- --B402220495 Bafety evaluation supporting Amond 72 to License DPR-13 PAULBON,W Office of Nuclear Reactor Regulation, Director, 84/02/17 3pp 22340,082 24% Fiche 50-206,84/02/17,8402220485
- 8402230121 Advises that Generic Item B-24 re containment purging/ venting during normal operations considered complete Disposition of four major components of NRC review provided CRUTCHFIELD.D Operating Reactors Branch 5 84/02/17 BADDIN K F Bouthern California Edison Co Bpp 2R361 207 24X Fiche: 50-206,84/02/17,8402230121

- 8402230134 Forwards Amend 71 to License DPR-13 & safety evaluation Amend approves loch Spec changes requiring manual valves CVB-301 & cys-313 of sphere purge air supply & air outlet lines, respectively, to be locked during Modes 1-4 CRUTCHFIELD.D Operating Reactors Branch 5 84/02/17 BASKIN, K Southern California Edison Co 3pp 22361 035 247 Fiche 50~206.84/02/17.8402230134
- --8402230136 Amand 71 to License DFR-13.approving Tech Spec changes requiring manual valves CV5-301 & CV3-313 of sphere purgs air supply & air outlet line, respectively, to be locked during Modes 1-4
 CRUTCHFIELD: D Operating Reactors Branch 5 84/02/17 5pp 22361 038 24X Fiche 50-206,84/02/17,8402230134
- --8402230137 Safety evaluation supporting Amend 71 to License DPR-13 * Office of Nuclear Reactor Regulation. Director 84/02/17 2pp 22361 043 24% Fiche 50-206.84/02/17,8402230134
- 8402240006 Forwards calculations performed to varify RCS peak pressure Analysis of effect of higher charging flow on overpressure mitigation sys will be provided by 840301 HEDFORD. M O Bouthern California Edison Co 84/02/21 CRUTCHFIELD. D Operating Reactors Branch 5 2pp 22375 188 24X Fiche 50-206.84/02/21,8402240006
- --8402240007 Procedure S0123-V-4 19. "SCNGS 1 Safety Injection. Nov 1983 "
 GCSSELING.S R Bouthern California Edison Co 83/12/14 33pp
 22375 190 24X Fiche 50-206.84/02/21.8402240006
- 8402270239 Forwards "Control of Heavy Loads (C-10), San Onofre Nuclear Generating Station, Unit 1," draft technical evaluation rept Addl info requested re listed areas within 45 days of itr receipt CRUTCHFIELD, D. Operating Reactors Branch 5 84/02/22 BASKIN, K.P. Bouthern California Edison Co. 3pp. 22386 237 247 Fiche 50-206,84/02/22,8402270239
- --8402270253 "Control of Heavy Loads (C-10).San Onofre Nuclear Generating Station.Unit 1," draft technical evaluation rept BOMBERGER,C., AHMED,N., SARGENT,I M. Franklin Institute/Franklin Research Center NRC-03-B1-130 TER-C5506-392 83/04/05 CLEMENSON,F. NRC ~ No Detailed Affiliation Given 41pp 22386 240 24X Fiche 50-206,64/02/22,8402270239
- 8402270154 Requests time extension for submitting addl info re NUREG-0737, Item II D 1 concerning performance testing of relief & safety valves, since unit out of svc since Feb 1782 KRIEGER, R M Sauthern California Edison Co 84/02/22 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 22428 146 24X Fichs 50-204,84/02/22,8402290154
- 8402280276 Forwards, add1 info.plans & schedules to perform analyses for SEP Topics II-f C.II-3 A.II-3 B.III-2.III-3 A.III-4 A. IV-2.V-5.VI-7 B.VI-7 C.2.VII-1 A & IX-5 W/three oversize figures Aperture cards are available in PDR MEDFORD. H D Southern California Edison Co 84/02/24 CRUTCHFIELD.B Operating Reactors Branch 5 109pp 22378 009 24% Ficha.50-206.84/02/24.8402280276
- 8402290180 Forwards revised integrated living achedule based on removing any SEP k fire protection safe shutdown bactfits. Outage schedules for three cycles of operation encl BASKIN.K P Southern California Edison Co B4/02/27 DENTON,H F Office of Nuclear Reactor Regulation. Director App 22419 175 24X Fiche 50-206.84/02/27,8402290180
- O Inspection reports, IE Bulletins & correspondence
- B312120153 IE Info Notice 84-04, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24% Fiche 50-000,84/01/25,8312120153
- 9402030263 Ack receipt of 840106 ltr informing NRC of steps taken to correct violations noted in 16 lasp Repts 90~206/83-21, 50~36/83-33 & 50~362/83-31
 91580916 T W Region 5, Office of Director 84/01/31 MCCARTHY, C B Bouthern California Edison Co 1p 22069 325 24X Fiche 50~206,84/01/31,8402030263
- -8402030271 Responds to NRC B31208 ltr re violations noted in IE Insp
 Repts 50-206/83-21.50-361/83-33 & 50-362/83-31 Corrective
 actions simulator training for operators modified to include
 plant situations requiring prompt action
 BA6KIN.K P Southern California Edison Co 84/01/06
 DEYOUNG.R C Director's Office. Diffice of Inspection and
 Enforcement 9pp 22049 326 24X Fiche 50-206.84/01/31.

- 8402140124 Forwards IE Insp Repts 50-206/84-01, 50-361/84-01 & 50-362/84-01 on 840109-12 No noncompliance noted BIBHUP.T W Division of Resident Reactor Project & Engineering Programs 84/01/31 BASKIN.K D Southern California Edison Co 2pp 22218 233 24X Fiche 50-206.84/01/31,8402140124
- --B402140139 IE Insp Repts 50-206/84-01.50-361/84-01 & 50-362/84-01 on B40109-12 No noncompliance noted Major areas inspected fire protection computer sys, reactor coolant pump oil collection sys & LERs SCOWN.K M . HOLLENBACH, D F . CANTER, H L Region 5, Office of Director B4/01/31 9pp 22218 233 24X Fiche 50-206.84/01/31, B402140124
- 8401190016 IE Info Notice 84-07. "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 30-000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl BEYDUNG.R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177
- 8402090321 Forwards safety evaluation re "Steam Generator Insp Program. Return to Power Rept for Sept 1982" Proposed license condition increasing insp interval from 6 to 12 months requested CRUTCHFIELD. D Operating Reactors Branch 5 84/02/07. BASKIN.K Bouthern California Edison Co 2pp 22160 258 24X Fiche 50-206.84/02/07.8402090321
- --8402070328 Safety evaluation re "Steam Generator Insp Program & Return to Power Rept for Sept 1982 " Proposed license condition increasing insp interval from 6 to 12 months requested * Office of Nuclear Reactor Regulation, Director 84/02/07 43pp 22160 260 24X Fiche 50-206.84/02/07,8402090321
- B401190041 IE Info Notice B4-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R)" Syc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post B30103) 84/02/13 Consolidated Edizon Co of New
 York, Inc. 124pp 22365 259 24X Fiche 50-000.84/02/13, 8401190041
- Yerk, Int. 124pp 22365 259 24X Fishe 50-000,04/02/13,840119004
- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/14 Consolidated Edison Co of New York, Inc. 115pp 22365 141, 24X Fiche 50-000,84/02/14,8401170039
- 8401190045 IE Info Notice 83-63, Suppl i, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Editon Co of New York, Inc. 118pp 22366 142 24X Fiche 50-000, 84/02/15, 8401190045
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Sat Below Manufacturer Recommended Value " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000,84/02/21,8401190062
- 8402220565 Discusses IE Safeguards Insp Repts 50-206/84-Q3, 50-361/84-04 & 50-362/84-Q4 on 840124-26 No violations noted Major areas inspected selective exam of procedures & records & interviews w/personnel Insp repts withheld (ref 10CFR2 790) NDRDERHAUG. R Region 5. Office of Director 84/02/22. BASKIN.K B Bouthern California Edison Co 2pp 22333 336 24X Fichs 50-206.84/02/22.8402220365
- 8402280245 Forwards corrected Page 2 to IE insp rept dtd 840207, for replacement Info describes power ascension transient testing & Unit 3 plant trips
 BISHOP,T W Division of Resident, Reactor Project & Engineering Programs 84/02/23 BABKIN.K P Southern California Edison Co 2pp 22397 876 24X Fiche 50-206,84/02/23,8402280245
- B401190046 IE Info Natice B4-11. "Training Program Deficiencies "
 Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B4/02/24 Consolidated Ediaon Co of New
 York, Inc 115pp. 22430,304 24X Fiche 50-000,84/02/24.8401190046
- 8401140067 JE Info Notice 84-12, "Failure of Soft Seat Valva Seals"
 Syc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co. of New
 York, Inc. 120pp 22431 060 24X Fiche 50-000,84/02/27,8401170067

- 8 Reportable occurrences, LERs & related correspondence
- B402080027 Responds to FOIA request for documents re facility hat functional testing problems, including broken thermowells, loose & broken reactor coolant pump parts & loose thermal sleeves Forwards App A documents Documents also in FDR FELTON, J M Division of Rules and Records 83/11/16 OARDE, B Government Accountability Project 3pp 22170 253 24X Fiche 50-000, 83/11/16, 8402080027
- --8402080036 List of hot functional testing exceptions Related info encl * Affiliation Not Assigned 83/11/16 19pp 22170 256 24X Fiche 50-000,83/11/16,8402080029
- 8402220154 Responds to FOIA request that 146 LERs be placed in PDR Forwards LERs listed on app Documents also available in PDR Remaining LERs were either canceled or not issued FELTON, J M Division of Rules and Records B3/11/30 JEFFERBON, G A Affiliation Not Assigned 2pp 22380 052 24X Fiche 50-000.83/11/30,8402220154
- 8402130346 Addendum to RD on 821222, Zone 4 hydrogen seal oil area fire spray/sprinkler sys removed from svc to prevent automatic actuation On 830130, fire detection sys for Zone 4 failed into constant alarm state & could not be reset HAYNES, J & Southern California Edison Co. 84/01/24 MARTIN, J B Region 5, Office of Director 2pp 22197 281 24X Fiche: 50-206,84/01/24,8402130346
- 8402070393 Requests that NRC investigate design reliability of emergency diesel generators supplied by Transamerica Delaval. Inc Engine problems have been experienced since delivery of first vessel in May 1981 Related info encl HDLINA, J C Falcon Carriers, Inc 84/02/01 DENTON, H R Office of Nuclear Reaction Regulation, Director 63pp 22096 087 24X Fiche: 50-000,84/02/01,8402070393
- 8401170053 Board Notification 84-020, forwards info re Transamerica Delayal, Inc emergency diesel generator problems Attendance list meeting handouts & slides encl EIBENHUT, D & Division of Licensing 84/02/13 PALLADING, OILINSKY, ROBERTS Commissioners 102pp 22332 202 24X Fiche 50-000,84/02/13,8401190053
- ---8402170137 Transcript of 840126 meeting in Bethesda, MD re Transamerica Delaval, Inc. diesel generators Pp 1-107 Supporting documentation encl. * Commissioners 84/01/26 RORPP 22332, 304 24X Fiche 50-000, 84/02/13, 8401190053
- B402220530 Part 21 rept re defective DBR & DBRV standby diesel generator turbocharger thrust bearing lubrication Deficiency not corrected by eys mod New recommendation will be sent to customers by 840330.
 BDYER.R E Transamerica Delaval, Inc 84/02/15 Director's Office, Deffice of Inspection and Enforcement 5pp 22332:182 24X Fiche: 50-000.84/02/15,8402220530
- B402230211 PNO-V-84-009 on B40215, limited number of workers treated following inhalation of fumes from unknown substance Cause helieved to be tear gas from Marine Corps training activities Emergency drill interrupted CARTER, H. L., KIRBCH, D. F. Region 5, Office of Director 84/02/15 ip. 22361:106, 24X Fiche. 50-206, 84/02/15, 8402230211.
- 8402270138 Supplemental LER 83-005 providing add1 info re incorrect analysis used to calculate low pressure mode setpoint for PORV Reanalysis of pressure transient underway Operating Instruction 801-4-6 changed HAYNES, J. 9 Southern California Edison Co 84/02/15 MARTIN, J B Region 5, Office of Director. 2pp 22426 091. 24X Ficher 50-206,84/02/15,8402270138.
- B402280701 Notification of B40308 meeting w/Transamerica Delaval, Inc (TDI) Guners group in Wading River, NY to discuss TDI proposed program to qualify diesel generators, CARUBO,R. Division of Licensing, 84/02/23, BERLINGER, C Division of Licensing, 2pp 22414:340, 24X Fiche 50-000,84/02/23, 8402280701

- DOCKET 50-213 HADDAM NECK PLANT
- F Security, medical, emergency & fire protection plans
- 8402010219 Forwards emergency plan implementing procedures, in response to NRC 830718 request re outstanding issues concerning post-accident sampling sys Capability of measuring reactor coolant dissolved oxygen will not be provided COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 94/01/12 COUNSIL W G NORTHEAST W G NO
- --8402010328 Emergency Plan Implementing Procedure EPIP 1 5-41, "Core Damage Estimate Procedure"

 * Connecticut Vankee Atomic Power Co 83/03/31 20pp 22039 283 24X Fache 50-000.84/01/12.8402010219
- --8402010232 Rev O to Empreency Plan Implementing Procedure EPIP 4221.
 "Gore Damage Estimate Procedure"
 MROCZKA: JAHORRNY, M Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/03/31 23pp 22039 303 24X
 Fiche 50-000.84/01/12.8402010219
- ---9402010237 Rev O to Emergency Plan Implementing Procedure EPIP 4222
 "Core Damage Estimate Procedure"
 MRCCZKA.E. JAMORSKY, M Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/03/31 22pp 22039 326 24X
 Fiche 50-000,84/01/12.8402010219
- 8402020150 Forwards IE Insp Rept 50-213/83-28 on 831205-08 & notice of violation MARTIN.T T Division of Engineering & Technical Programs 84/01/20 COUNSIL.W G Connecticut Yankee Atomic Power Co 2pp 22056 150 24X Fiche 50-213,84/01/20,8402020150
- --8402020154 Notice of violation from insp on 831205-08
 * Region 1, Office of Director 84/01/20 ip 22054 i52 24X
 Fiche 50-213,84/01/20,8402020150
- ---840202015B IF Insp Rept 50-213/83-28 on 831205-08 Violation noted failure to provide six emergency support staff members w/ required emergency response training/retraining prior to being placed on call w/radiopagers suring 830704-1204 SMITH.R H , WOLTMER.E Region 1. Office of Director CROCKER.H W Division of Engineering & Technical Programs 84/01/17 App R2054 153 24X Fiche 50-213,84/01/20,8402020150
- 8402150298 Revised emergency plan implementing procedures, including Roys 19 & 20 to Procedure EPIP 1 5-2 re notification & communication, Rev 4 to Procedure EPIP 1 5-14 re evacuation & assembly & Rev 5 to Procedure EPIP 1 5-28 M/A40130 ltr COUNSIL.W 0 Connecticut Vankse Atomic Power Co 84/01/30 EISENHUT.D 9 Division of Licensing 86pp 22250 324 24X Fiche 50-213,84/01/30,8402150298
- 8402070241 Ack receipt of B31228 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-213/83-22 MARTIN.T T Division of Engineering & Technical Programs, 84/02/01 COUNBILL W O Connecticut Yankee Atomic Power Co 2pp 22101 304 24X Fiche 50-213,84/02/01,8402070241
- --B402070246 Responds to NRC B31202 ltr re violations noted in IE Insp.
 Rept 50-213/83-22 Corrective actions operations Surveillance
 Procedure SUR 5 1-i17 revised to include Tech Spec 4 15 F i
 surveillances of safety-related fire dampers
 CDUNBILLN 9 Connecticut Yankee Atomic Power Co B3/12/28
 MARTIN TT Division of Engineering & Technical Programs 2pp
 22101 306 24X Fiche: 50-213,84/02/01,8402070241
- B402140135 Responds to NUREQ-0737. Suppl 1 re requirements for amergency response capabilities/emergency operations facilities Util intends to revise Section 7 i of emergency plan w/addition of listed wording COUNSIL. W 9 Connecticut Yankee Atomic Power Co COUNSIL. W 9 Connecticut Yankee Atomic Power Co COUNSIL. W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) 84/02/03 EISENHUT.D 9 Division of Licensing 2pp 22219.038 24X Fiche 50-000,84/02/03,8402140135
- B402070337 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per Generic Ltr Bi-27 W/o request, entire plan will be placed in PDR CRUTCHFIELD, D Operating Reactors Branch 5 84/02/06 CDUNSIL, W G Connecticut Yankes Atomic Power Co CDUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 22096 197 24X Fiche 50-000,84/02/06,8402070337

- 8402290204 Forwards IE Safeguards Insp Rept 50-213/84-01 on 840109-13 No violations observed MARTIN.T T Division of Engineering & Technical Programs 84/02/14 COUNSIL.W C Connecticut Yankee Atomic Power Co 2pp 22425 117 PAX Fiche 50-213.84/02/14.8402290204
- --8402290207 1E Safeguards Insp Rept 50-213/84-01 on 840109-13 No noncompliance noted Major areas inspected security organization, security program audit, testing & maint, physical barriers, security sys power supply & assessment aids HADDEN, W., JOYNER, J. H. Region 1. Office of Director 84/02/144pp 22425 119 24X Fiche 50-213,84/02/14,8402270204
- P Operating license stage documents & correspondence
- 8402070225 Informs that locking device installed on dc tie breakers physically prevents engaging breaker Rev 7 to Normal Operating Procedure NOP 2 16-1.per SEP Topic VI-7 C 1. Section 4 24 2 to NUREG-0826 resolves issue COUNSIL.W G Connecticut Yanke Atomic Power Co 84/01/17 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 22101 038 24X Fiche 50-213.84/01/17.8402070225
- ~-8402070228 Rev 7 to Normal Operating Procedure NDP 2 16-1, "AC & DC Distribution Normal Configuration"

 * Connecticut Yankee Atomic Power Co 83/11/12 9pp 22101 040 24X Fiche 50-213.84/01/17,8402070225
- 8402060417 Forwards add1 info in response to open items re SEP Topic III-6. "Seismic Design Considerations " Index of final repts on analyses of structures, RCS piping components & supports & analyses of mechanical & electrical equipment also enci COUNSIL, # 9 Connecticut Yankee Atomic Power Co 84/01/19 CRUTCHFIELD.D Operating Reactors Branch \$ 960 22085 130 24X Fiche 50-213.84/01/19.8402060417
- 8402020308 Responds to Generic Ltr 92-16 re NUREG-0737, Items I A 1 3 1 & II K 3 3 concerning limiting overtime for plant staff & reporting safety & relief valve failures, respectively CRUTCHFIELD.D Operating Reactors Branch 5 84/01/20 COUNSIL.W 6 Connecticut Vankee Atomic Power Co 4pp 22035 095 24X Fiche 50-213,84/01/30.8402020308
- 8402150009 Forwards revised Corporate Organization for Nuclear Incidents procedure manual, including Rev 7 to Procedure CONI 7 01 re manager of external communications W/a encl COUNSIL, W CONNECTOR OF COUNSIL, W CONTRACT CONTRACT COUNSIL, W COUNSIL COUNSIL
- B402070163 Forwards Amend 57 to License DFR-61 Amend deletes ETS 5 8-1 re transmission rights-of-way mgt requiring that herbicide usage conform to environ rept procedures W/o encl CRUTCHFIELD D Garrating Reactors Branch 5 84/01/31 CQUNSIL.W 0 Connecticut Yankee Atomic Power Co 9pp 22103 075 24X Fiche 50-213,84/01/31.8402070163
- 8402010410 Generic Ltr 84-04 to all operating PWR licensess, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dualing w/elimination of postulated pipe breaks in FWR primary main loops Svc list encl EISENHUT.D G Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc. 59pp 22177 087 24x Fiche 30-000,84/02/01.8402010410
- 8402220460 Provides justification for exemption from IOCFR170 22 fees for 831024 proposed Tech Spec changes to achieve consistency w/10CFR30 54(m) requirements.citing Generic Ltr 83-43 COUNSIL.W O Connecticut Yankee Atomic Power Co 84/02/06 11605-R M License Fee Nanagement Branch 3pp 22339 329 24X iche 50-213,84/02/06.8402220460
- 12280098 Requests appropriate application fee re deletion of ,ransmission rights-of-way mgt & meteorological monitoring programs
 MILLER, W O License Fee Management Branch 84/02/15 CDUNBIL, W Q Connecticut Yankee Atomic Power Co 2pp 22427 355 24X Fiche 50-213,84/02/15,8402280098
- O Inspection reports, IE Bulletins & correspondence
- B402020150 Forwards IE Insp Rept 50-213/83-28 on B31205-08 & notice of violation MARTIN.1 T Division of Engineering & Technical Programs B4/01/20 COUNSIL.W 6 Connecticut Yankee Atomic Pawer Co. 2pp 22036 150 24X Fiche 50-213,84/01/20,8402020150
- --8402020154 Notice of violation from insp on 831205-08 † Region 1, Office of Director 84/01/20 1p 22056 152 24X Fiche 50-213,84/01/20,8402020150

- --B402020158 IE Insp Rept 50-213/B3-2B on 831203-08 Violation noted failure to provide six emergency support staff members w/ required emergency response training/retraining prior to being placed on call w/radiopagers during 830706-1204.

 BMITH.R H , WDLTNER,E Region I, Deflice of Director CROCKER,H W Division of Engineering & Technical Programs 84/01/17 4pp 22056 153 24X Fiche 50-213,84/01/20,8402020150
- B402030251 Responds to IE Bulletin 81-02 re failure of gate type valves to close against differential pressure Valves CH-MOV-2928 & C on Loop 2 charging line in chemical & vol control sys fall into category but normally open during operation COUNSIL.N 0 Connecticut Yankee Atomic Power Co B4/01/24 MURLEV.T E Region 1. Office of Director 2pp 22069 337 24X Fiche 50-213.84/01/24.8402030251
- 8312120193 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list enci JDRDANE L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120153
- 8402080320 Forwards IE Insp Rept 50-213/83-27 on 831101-1231 No violations observed STAROSTECKI, R Division of Project & Resident Programs CDUNSIL, W C Connecticut Yankee Atomic Power Co 2pp 22130 285 24X Fiche 50-213.84/01/25.8402080320
- ~-8402080328 IE Insp Rept 50-213/83-27 on B31101-1231 No violations observed Major areas inspected control room, turbine bldg, primary auxiliary bldg, auxiliary feed pump room, activities/records, plant operations & radiation protection SMETLAND, P D Region 1, Dffice of Director ELSASSER, T C Division of Project & Resident Programs B4/01/24 10pp 22130 287 24X Fiche 50-213,84/01/25,8402080320
- 8402150005 Forwards IE Insp Rept 50-213/83-26 on 831114-18 & notice of violation MARTIN.T T Division of Engineering & Technical Programs 84/01/31 CDUNSIL.W G Connecticut Yankee Atomic Power Co 2pp 22247 296 24X Fiche 50-213.84/01/31.8402150005
- ~-8402150006 Notice of violation from insp on 831114-18 # Region 1, Office of Director 84/01/31 1p 22249 298 24X Fiche 50-213,84/01/31,8402150005
- ~~8402150007 IE Insp Rept 50-213/83-26 on B31114-18 Noncompliance noted failure to follow transuranic analysis procedure for solid raduaste MOTTAN, J J , STRUCKMEYER, R , PABCIAK, H J Region 1. Office of Director 84/01/16 4pp 22249 299 24X Fiche 50-213,84/01/31,8402150005
- 8402070241 Act receipt of B31228 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-213/83-22 MARTIN: T Division of Engineering & Technical Programs 84/02/01 COUNSIL: Q Connecticut Yankee Atomic Power Co 2pp 22101, 304 24X Fiche 50-213:84/02/01:8402070241
- ~-B402070246 Responds to NRC B31202 ltr re violations noted in IE Insp Rept 50-213/83-22 Corrective actions operations Surveillance Procedure SUR 5 1-117 revised to include Tech Spec 4 15 F 1 surveillances of safety-related fire dampers COUNSIL.N G Connecticut Yankee Atomic Power Co 83/12/28 MARTIN.T T Division of Engineering & Technical Programs 2pp 22101 306 24X Fiche 50-213,84/02/01.8402070241
- 8402160276 Forwards IE Insp Rept 50-213/83-24 on 831003,04,06 & 07 & notice of violation MARTIN.T T Division of Engineering & Technical Programs 84/02/02 COUNSIL.W G Connecticut Vankes Atomic Power Co 2pp. 22276 348 24X Fichs 50-213-84/02/02,8402160276
- ~-8402160283 Notice of violation from insp on 831003.04.06 & 07 * Region 1, Office of Director 84/02/02 ip 22276 350 24X Fiche 50-213.84/02/02.8402160276
- --B402160288 IE Insp Rept 50-213/83-24 on B31003,04,06 & 07. Violation noted failure to audit plant info rept corrective action sys MEYER, G W Region 1, Office of Director CAPHTON, D L Division of Engineering & Technical Programs B4/02/01 7pp 22276 351, 24X Fiche 50-213,84/02/08,8402160276
- B401190016 IE Info Notice B4~07, "Design-Basis Threat & Review of Vehicular Excess Controls" Svc list encl JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 30-000,84/02/03,8401190016

- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vant
 - Headers " Svc list encl
 DEYQUING,R C Director's Office, Office of Inspection and
 Enforcement 84/02/03 Consolidated Edison Co of New York, Inc
 102pp 22177 156 24x Fiche 30-000.84/02/03.8401190017
- B401170041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R) " Svc list
 - encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/13 Consolidated Edison Co of Now York, Inc 124pp 22345 259 24X Fiche 50-000.84/02/13,840(19004)
- 8401190039 IE Infa Natice 84-08, "10CFR50 7, 'Employee Protection '" Svc list encl
- JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/14 Consolidated Edison Co. of New York, Inc. 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- 8402270204 Forwards IE Safeguards Insp Rept 50-213/84-01 on 840109-13
- No violations observed

 MARTIN, T T Division of Engineering & Technical Programs 84/02/1

 COUNSIL, W Q Connecticut Yankee Atomic Power Co 2pp 22425 117

 24X Fiche 50-213, 64/02/14, 8402270204
- --8402270207 IE Safeguards Insp Rept 50-213/84-01 on 840109-13 No noncompliance noted Major areas inspected security organization, security program audit testing & maint, physical barriers, security sys power supply & assessment aids MADDEN, W., UDYNER, J. H. Region 1, Office of Director 84/02/1 4pp 22425 119. 24X Fiche 50-213/84/02/14/8402290204 84/02/14
- 8401190045 IE Info Notice 83-63. Suppl 1, "Potential Failures of Westinghouse Type BA-1 Differential Relays" Bvc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of Now York, Inc. 118pp 22366 142 24X Fiche 50-000.84/02/15.8401190045
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Bet Below Manufacturer Recommended Value " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co. of New York, Inc. 116pp 22366 024 24X Fiche 50-000,84/02/21,8401190062
- 8401190046 JE Info Notice 84-11, "Training Program Deficiencies
- 101190066 to anto nover ...
 Syc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 630103) 84/02/24 Consolidated Edison Co of New
 York, Inc. 115pp 22430 304. 24X Fiche 50-000,84/02/24.8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
- Byc list enci Jophan, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/27 Consolidated Edison Co 24X fiche 50-000, 84/02/27, 8401190067 120pp 22431 060
- 8 Reportable occurrences, LERs & related correspondence
- 8402220154 Responds to FOIA request that 146 LERs be placed in PDR 402220194 Responds to FOIA request that 146 LERs be placed in PDR Forwards LERs listed on app. Documents also available in PDR. Remaining LERs were either canceled or not issued FELTON.J M Division of Rules and Records 83/11/30 JEFFERBON,O A Affiliation Not Assigned 2pp 22380 052 24X Fiche 50-000,83/11/30,8402220154
- DOCKET 50-219 DYSTER CREEK NUCLEAR POWER PLANT
- F Security, medical, emergency & fire protection plans
- 8402030393 Notification of 840209 meeting w/OPU in Silver Spring, MD to discuss proposed 10CFR50 90 changes to physical security plan, including existing detection sys, interim measures & permanent sys mod LOMBARDO, J J Operating Reactors Branch 5, 84/01/31 CRUTCHTIELD. D, Operating Reactors Branch 5 3pp 22066 003 24 Fichs: 50-217,84/01/31,8402030393 22066 023 24X
- 8402090111 Forwards Rev 15 to physical security plan Rev withheld (ref 10CFR73 21) FIEDLER.P B General Public Utilities GPU Service Corp 84/6 Office of Nuclear Reactor Regulation, Director 1p 22157 3 24X Fiche, 50-219, 84/01/31, 8402090111 84/01/31 22157 356
- 8402070362 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licenses, per Generic Ltr 81-27. W/o request, entire plan will be placed in PDR CRUTCHFIELD. D. Operating Reactors Branch 5 84/02/02 FIEDLER. P. B. Quineral Public Utilities QPU Service Corp 2pp 22099, 324 24X Fichs. 50-219. 84/02/02, 8402070362

- 8402170159 Revs to emergency plan implementing procedures, including EPIP-26 re technical support ctr & EPIP-27 re operations support ctr W/840210 ltr FIEDLER, P B General Public Utilities GPU Service Corp 84/02/MURLEY, T E Region 1, Office of Director 2App 22299 077 24 Fiche 50-219,84/02/02.8402170159
- 8402080207 Forwards comments re detailed control room design review program plan Util will conduct review that meets intent of Buppl 1 to NUREO-0737 Concern expressed re appropriate identification of operator info in emergency CRUTCHFIELD. D. Operating Reactors Branch 5 84/02/06 FIEDLER, G. General Public Utilities 0PU Service Corp. Spp. 22130 115 2 Fiche 50-219.84/02/06.8402080207 FIEDLER, P D
- 8402130620 Requests for for 620630 application of alternate safe shutdown capability be remitted within 15 days of receipt of
 - ltr MILLER, H Ø License Fee Management Branch 84/02/08 FIED General Public Utilities GPU Service Corp ip 22214 294 Fiche 50-219.84/02/08.8402130620 FIEDLER, P B
- B402210196 Forwards fee for review of B20630 fire protection submittal KNUBEL, J General Public Utilities GPU Service Corp. 84/02/13 MILLER,W O Liconse Fee Management Branch 2pp. 22316 322 24X Fiche 50-219.84/02/13.8402210196
- J. Insurance & indemnity information
- 8402170130 Forwards Endorsements 89 & 90 to NELIA Policy NF-164 & Endorsements 69 & 70 to MAELU Policy MF-44 OFRETY, H F General Public Utilities GPU Service Corp 84/02/14 SALIZMAN, J F Office of Nuclear Reactor Regulation, Director Spp 22296 088 24X Fiche 50-219,84/02/14,8402170130
- 8402230131 Forwards Endorsement 4 to NELIA Policy N-13 & MAELU Policy CREATY.H F General Public Utilities ~ GPU Service Corp & SALTZMAN,J Office of Nuclear Reactor Regulation, Director R2361 202 R4X Fiche 50-219,84/02/17,8402230131 84/02/17
- P Operating license stage documents & correspondence
- 8402080009 FOIA request for correspondence between NRC. JCP&L & 402000009 FUIA request for correspondence between MML, JUFFEL &
 Rachester das & Electric re shipment of irradiated fuel from
 West Valley, NY & correspondence on route applications
 between listed labs & Savennah River Plant
 RIGHIKOFF, M Sierre Club E3/11/29 NRC - No Detailed
 Affiliation Given ip 22174 008 24X Fiche \$0-000, B3/11/29,
- B312120027 Generic Ltr 63-39 to representatives of utils re voluntary survey of licensed operators Svc list encl CISENHUT.D G Division of Licensing 83/12/08 Commonwealth Edison Co 12pp 22313 006 24% Fiche 50-000.83/12/08.8312120029
- B402010167 Forwards Amend 71 to License DPR-16 & safety evaluation Amend adds tenth range to intermediato-range munitors in neutron monitoring sys CRUTCHFIELD.D Operating Reactors Branch 5 84/01/30 FIEDLER. Osneral Public Utilities GPU Service Corp 3pp 22038 317 Fichs 50-217.84/01/30.8402010167 FIEDLER, P B
- --8402010175 Amend 71 to License DPR-16, changing Tech Specs by adding tenth range to intermediate-range menitors of neutron monitoring sys CRUTCHFIELD.D Operating Reactors Branch 5 84 22038 320 24X Fichs 50-217.84/01/30.8402010167 22038 320
- 8402060166 Forwards partial response to 831230 request for info re radwaste disposal methods, per Reg Guide 1 86 Outer 1/2 to 3/4 inch of radwaste bldg walls will be spalled & removed for shipment as radwaste per ALARA principle FIEDLER, P B General Public Utilities GPU Service Corp 84/0 GRUTCHFIELD. Departing Reactors Branch 5 3pp 22087 165 GRUTCHFIELD, D. Operating Reactors Branch 5 Fiche. 50-219, 84/01/30, 8402060166
- B402070120 Forwards addi supporting info to Tech Spec Change Request 103 Spec 3 5 D 1 i statem action to be take when secondary containment integrity not maintained FIEDLER,P.B General Public Utilities GPU Service Corp 84/02/0 Office of Nuclear Reactor Regulation, Director 3pp 82102 280 24X Fiche 50-219,84/02/01,8408070180
 - 64/02/01

- 8402090341 Informs that term "mechanically intact" redefined to mean that lower portion of torus shell up to normal operating water level has no openings & capable of holding water FIEDLER.P.B. General Public Utilities GPU Service Corp. 84/02/6 CRUTCHFIELD.D. Operating Reactors Branch 5 2pp. 22161 171 2 Fiche 50-219,84/02/03.8402090341 84/02/03
- B402:30329 Forwards info re BEP Topic III-3A. "Effects of High Water Level on Structure " Imposed soil loading values not reduced to account for buoyancy due to elevated water table
 NAGALY General Public Utilities - GPU Service Corp 84/02/03
 PERSHINKO P NRC - Na Detailed Affiliation Given 2pp 22197 1
 24X Fiche 50-219,84/02/03,8402130329 22197 193
- 8402070328 Forwards Amend 72 to License DPR-16 & safety evaluation Amend authorizes changes to Tech Specs ra operability of isolation valves for isolation condensers CRUTCHFIELD, D Operating Reactors Branch 5 84/02/06 FIEDLER. Openaral Public Utilities GPU Service Corp 3pp 22096 246 Fiche 50-219,84/02/06,8402070398 FIEDLER, P B
- --B402070333 Amend 72 to License DPR-16.changing Tech Specs re operability of isolation valves for isolation condensers CRUTCHFEELD.D Operating Reactors Branch 5 84/02/06 81 22096 249 248 Fiche 50-219.84/02/06.8402070328
- --8402070338 Safety evaluation supporting Amend 72 to License DPR-16 * Office of Nuclear Reactor Regulation. Director 84/02/06 3pp 22096 257 24% Fichs 50-219,84/02/06,8402070328
- 8402130231 Responds to 840125 request for info re presence of federally listed or proposed endangered & threatened species in vicinity of facility No endangered or threatened species exist in project impact area KULPIC J Interior. Bept of. Fish & Wildlife Service 84/02/07 CRUTCHIELD, D Operating Reactors Branch 5 2pp 22204 175 24X Fiche 50-219.84/02/07.8402130231
- 8402150285 Forwards add1 info re Teth Spec Change Request 108 re rev to 10CFR50 91. significant hazards analysis in response to telcon
- to telean FlEDLER.P B General Public Utilities GPU Service Corp B4, CRUTCHFIELD.D Operating Reactors Branch 5 3pp 22242 118 Fiche 50-219,84/02/08.8402150285 84/02/08
- D2[40244 Forwards response to NRC 831121 request for info re use of voltage regulators Tech Spec Change Request 88 re second level (degraded grid) undervoltage relays clarified FIEDLER,P B General Public Utilities GPU Service Corp 84/02/09 CRUTCHFIELD,D Operating Reactors Branch 5 9pp 22228 335 24X Ficha 50-219,84/02/09,8402140244 84/02/09
- 02170173 Updates 830520 ltr re installation schedule for post-accident sampling sys per NUREO-0737. Item II B 3 Hardware will be installed in mid-Aug & startup & testing will be Completed by mid-Sept
 FIEDLER:P B General Public Utilities - OPU Service Corp & Electrical Public Utilities - OPU Service Corp & Electrical Public Utilities - OPU Service Corp & Electrical Public Utilities - OPU Service Corp & Fische 50-219.84/02/10.8402170173
- 402170184 Notifies that Class III fee due for Amend 70 to License DPR-16 re insp of core spray spargers & repair dasemblies at each refueling outage DIGOS.R M License Fee Management Branch 84/02/10 FIEDLER.P B General Public Utilities GPU Service Corp ip 22313 274 24X Fiche 50-219.84/02/10.8402170186
- 02220286 Forwards "Drywell Coating Evaluation," technical data rept. per SEP Topic VI-1. "Organic Matls & Post-Accident Chemistry "FigDLER.F B General Public Utilities GPU Service Corp. 84/02/10 CRUTCHFIELD.D Operating Reactors Branch S 2pp. 22341 132 24x iche 50-219.84/02/10.8402220286
- '02220293 Rev O to "Drywell Coating Evaluation," technical data rept FREDERICK:A J General Public Utilities ~ OPU Service Corp TDR 903 ROO 83/12/21 35pp 22341.134 24X Fiche 50-219,84/02/10. \402220286
 - 0146 Forwards current list of endangered & threatened wildlife in of NJ in response to NRC request for info re unique or tive biota in area of facility
 NB.C D New Jersey, State of B4/02/14 HICKEY, C Ni
 led Affiliation Given 3pp 22318 135 24X
 50-219.84/02/14.8402210146 HICKEY, C NRC - No
 - Cancels Tech Spec Change Request 95.dtf 810331.based on of Amend 70.deleting requirement for replacing core during current rafueling outage
 Osneral Public Utilities ~ GPU Service Corp 84/02/14 Nuclear Reactor Regulation
 - 84/02/14

- 8402210075 Advises that design of new racks to be used in reracking of spent fuel storage pool is licensable Tach Spec change request will be required before 840331 CRUTCHFIELD, D Operating Reactors Branch 5 84/02/17 FIEDLER, P B General Public Utilities OPU Service Corp 2pp 22317 286 24% Fiche 50-219.84/02/17,8402210075
- 8402210138 Cancels Tech Spec change request to replace core spray sparger, per 840214 request Cancellation based on issuance of Amend 70 to License DPR-16 which deleted requirement for sparger replacement GRUTCHFIELD. D. Operating Reactore Branch 5 84/02/17 FIEDLEF General Public Utilities GPU Service Corp. 2pp 22317 166. Fiche 50-219.84/02/17,8402210138 22317 166. 24X
- 8402240131 Assesses operability of purge & vent valves in light of concerns outlined in SER Valves will be opened to no more than 30 degrees & will close from 30 degrees open position in event of DBA-LOCA
 FIEDLER, P. B. General Public Utilities QPU Service Corp. 84/06 TIEDLER, P B General Public Utilities - GPU Service Corp B4. MIRAGLIA.F. J Assistant Director for Bafety Assessment 4pp 22374 156 24X Fiche 50-219,84/02/21,8402240131 B4/02/21
- ~-8402240134 Rev O to "Btress Analysis for Demonstration of Operability of Purge & Vent Valves During DBAs "
 SHAO,A C General Public Utilities QPU Bervice Corp 81/05/21
 21pp 22374 163 24% Fiche 50-219.84/02/21:8402240131
- 8402270212 Forwards request for addl info re review of NUREG-0737, Item III D 3 4. "Control Room Habitability " Provision of info requested within 60 days of itr receipt CRUTCHFIELD.D Operating Reactors Branch 5 84/02/22 FIEDLER, P B General Public Utilities OPU Service Corp 3pp 22386 360 24X Fiche 50-219.84/02/22.8408270212
- 8402280286 Advises that 831114 response to Generic Ltr 83-28 re Item 3 i, "Post-Maint Testing," contains typographical error Hord inconsistent w/reactor protection sys logic in fifth paragraph should be replaced w/consistent KNUBEL, J General Public Utilities OPU Service Corp 84/02 LOMBAROL J NRC No Detailed Affiliation Given 2pp 22395 24X Fiche 50-219,84/02/22,8402280886 22399 204
- @ Inspection reports, IE Bulletins & correspondence
- 8402020320 Forwards IE Insp Rept 50-219/83-25 on 831017-21 & notice of violation

 HARTIN,T T Division of Engineering & Technical Programs B3/12/28

 FIEDLER,P B General Public Utilities - GPU Service Corp 2pp

 22055 099 24X Fiche 50-219,83/12/28,8402020320
- ~-8402030324 Notice of violation from insp on 831017-21 * Region 1, Diffice of Director 83/12/28 ip 22055 101 Fiche 50-219,83/12/28,8402020320
- --8402020326 IE insp Rept 50-219/83-25 on 831017-21 Violation noted failure to analyze monthly liquid effluent composites for MCGRIDE, M. DRAGGUN, T. SHANBAKY, M. Region 1. Office of Director 89/12/23 Spp. 22055 102 24% Fiche 30-219.83/12/28,8402020320
- 8402060036 Forwards IE Insp Rept 50~219/83~27 on 831129-1202 & notice of violation

 MARTIN, T T Division of Engineering & Technical Programs

 FIEDLER, P B General Public Utilities - GPU Bervice Corp

 22083 271 24X Fiche 50-219.84/01/17.8402060036 64/01/17
- --8402060040 Notice of violation from insp on 831129-1202. * Region 1, Office of Director 84/01/17 ip. 22083 273. 24X Fiche 50-219,84/01/17,8402060036
- 8312120153 IE Infa Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New Yark, Inc 120pp 22058 001 25% Fiche 50-000,84/01/25,8312120153
- 8402080362 Forwards IE Insp. Rept 50-219/83-28 on 831212-15 No violations noted MARTIN.T T Division of Engineering & Technical Programs 84/01/25 FIEDLER: P B General Public Utilities GPU Service Corp 22131 190 24X Fiche 50-219,84/01/25,8402080362

- --8402080367 IE Insp Rept 50-219/83-28 on 831212-15 No violations noted Major areas inspected raduaste program, including radioactive effluent releases-liquid & gaseous, records & repts of radioactive effluents & solid raduaste KOTTAN, J J. PASCIAK, M J. Region 1, Office of Director 84/01/23 4pp 22131 192 24X Fiche 30-219,84/01/25,8402080362
- 8401190016 IE Info Notice 84~07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark 1 Containment Vent Headers " 8vc list encl DEYGUNG.R C. Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 156 24X Fiche 50-000.84/02/03.8401190017
- 8402240044 Forwards IE Insp Rept 50-219/83-24 on 831012,17-21 & 27 & notice of violation

 MARTIN,T T Division of Engineering & Technical Programs 84/02/09

 FIEDLER:P B General Public Utilities GPU Service Corp 4pp

 22373 302 24X Fiche,50-219,84/02/09,8402240044
- --8402240047 Notice of violation from insp on 831012, 17-21 & 27 * Region 1, Office of Director 83/11/21 ip 22373 306 24X Fiche 50-219,84/02/09,8402240044
- --B402240050 IE Insp Rept 50-219/83-24 on B31012,17-21 & 27 Violation noted failure to document certain NUREQ-0737 design-related activities for containment monitors

 EAPEN,P K , NARROW, L , QREQQ,H I Region 1, Office of Director B3/12/12 14pp 22373 307 24X Fiche 50-219,84/02/09,8402240044
- 8402170186 Notifies that Class III fee due for Amend 70 to License DPR-16 re insp of core spray spargers & repair assemblies at each refueling outage DIOGB,R M License Fee Management Branch 84/02/10 FIEDLER,P B General Public Utilities GPU Service Corp 19 22313 274 24X Fiche: 50-217,84/02/10,8402170186
- B402240126 Responds to IE Bulletin 84-01, "Gracks in BWR Mark I Containment Vent Headers " Data sheet of vent header & nitrogen purge line insps encl Insp results show that no vent ring-header or main vent cracking experienced FIEDLER.P B General Public Utilities GPU Service Corp B4/02/10 MURLEY.T E Region 1, Office of Director App 22373 331 24X Fiche: 50-219,84/02/10,8402240124
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFRBO, App R) " Syc list enc!

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp. 22365 259 24X Fiche 50-000.84/02/13,8401190041
- 8401170037 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection.'"
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14. Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24X Fiche 50-000.84/02/14.8401170039
- 8401190045 IE Info Notice 83-63. Suppl 1: "Potential Failures of Westinghouse Type 6A-1 Differential Relays " Svc list encl JDRDAN, E. L. Division of Emergency Praparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp. 22366 142 24X Fiche 50-000,84/02/15,8401190045
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Buitches 8st Below Manufacturer Recommended Value." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co. of New York, Inc. 116pp 22366, 024 24X Fiche 50-000, 84/02/21, 8401190062
- B401190066 IE Info Notice 84-11, "Training Program Deficiencies"

 Byc-list encl

 JORDAN, EL Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/02/24 Consolidated Edison Co of New

 York, Inc 115pp 22430.304 24X Fiche 50-000.84/02/24.8401190066
- B401190047 IE Info Notice B4-12, "Failure of Boft Beat Valve Seals "
 Bvc list encl.
 JORDANNE.L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 040 24X Fiche 50-000,84/02/27,8401190067

- S Reportable occurrences, LERs & related correspondence
- 8402060118 LER 83-024/01T-0 on 831220 discovered torque switches set below recommended setpoint limits Caused by lack of knowledge re setpoint design basis Corrections made to torque setpoints W/P40113 ltr CUSTODIO.0 B . LAGOART.M W General Public Utilities GPU Service Corp 84/01/13 MURLEY.T E Region 1. Office of Director 2pp 22087 112 24X Fiche 30-217,84/01/13,8402060118
- 8402020305 LER 83-026/01T on B31223, discovered addition of lead of radiation shielding on fuel pool cooling HX could overstress foundation bolts Cause under investigation Followup rept expected by 840123, exceeding 14-day limit FIEDLER, P.B. General Public Utilities GPU Service Corp. 84/01/16 MURLEY, T.E. Region 1, Office of Director 1p. 22055 188 24X Fiche 50-219,84/01/16,8402020305
- B402150225 LER 83-026/01T-0 on B31223 discovered that addition of lead for radiation shielding on two of three spent fuel pool HXs would overstress foundation bolts during seismic event Caused by lack of procedural controls in past W/B40207 Itr CZAYA.P F. FIEDLER.P B General Public Utilities - GPU Service Carp B4/02/07 MWRLEP.T E Region 1, Office of Director 5pp 22244 308 24X Fiche 50-219.84/02/07.8402150225
- DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

 F Security, medical. emergency & fire protection plans
- B402150325 Forwards IE Insp Rept 50-220/B3-27 on 831114-18 No violations noted App B violation re upgrade of radiation protection program withdrawn MARTIN.T T Division of Engineering & Technical Programs 84/01/31 RHODE.6 K Niagara Mohawk Power Corp 3pp 22250 227 24X Fiche 50-220,84/01/31,8402150325
- --8402150328 IE Insp Rept 50-220/83-27 on 831114-18 No violations noted Major areas inspected health physics appraisal significant appraisal findings & licenses implementation of corrective actions reaction plan progress repts
 NIMITZ.R L , BICEHDUSE.H , COLLINS.D Region 1, Office of Director 84/01/25 20pp 22250 230 24X Fichs 50-220.84/01/31, 8402150325
- 8402060136 Reconfirms & updates implementation schedules for safety parameter display sys (SPDB) & emergency response facilities GPDB will be fully operational, including operator training, by end of 1986 refueling outage LEMPGES, T.E. Niagara Mohauk Power Corp. 84/02/01 VASSALLO, D.B. Operating Reactors Branch 2 2pp 22088 304 24X Fiche 50-220,84/02/01,8402060156
- 8402160405 Notification of 840208 meeting w/util in Bethesds,MD to discuss licensing action re upcoming refueling outage, technical support ctr & participation re integrated safety program HERMANN.R A Operating Reactors Branch 2 84/02/07 VASSALLO.D B Operating Reactors Branch R ip 22302 131 24X Fichs 50-220.84/02/07.8402160405
- 840E240130 Responds to 830824 itr re security & safeguards contingency plan changes Portions of revs unacceptable for reasons stated in encl Encl withheld (ref 10CFR73 21).

 MARTIN.T T Division of Engineering & Technical Programs 84/02/13 BUNSER.J J Niagara Mohawk Power Corp 3pp 22373 340 24X

 Fiche 50-220,84/02/13,8402240130
- H General correspondence
- B207170054 Requests responses re London Nuclear Con-Decon solution used on reactor coblant recirculation pumps during sys cleanup DREY, K. Affiliation Not Assigned 82/07/13 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 22393 361 24X Fiche 50-000,84/02/03.8209170034
- 8402240216 Final response to FOIA request for documents re replacement piping at facility. Forwards App A & B documents Documents also available in PDR FELTON. J M Division of Rules and Records. 84/02/03 BELL. N Nuclear Information & Resource Service 3pp 22393 230 24X Fiche. 80-040.84/02/03.8402240216
- P Operating license stage documents & correspondence
- 8402220127 FOIA request for documents re replacement of piping at facility
 BELL,N Nuclear Information & Resource Service 84/01/05 Diffice of Administration, 2pp 22363 233 24X Fiche 50-220,84/01/05,8402220127

- 8402050489 Forwards SER re NUREG-0737. Item II B 3: "Post-Accident Sampling Sys " Response to four remaining criteria identified in entl requested within 30 days VASSALLO.D B Operating Reactors Branch 2 84/01/12 RHODES.C K Niagara Mohawk Power Corp 11pp 22110 163 24X Fithe 50-220.64/01/12.8402050489
- 8402220130 Partial response to FDIA request for documents re replacement of piping at facility Foruards App B documents App A & B documents available in PDR FELTON.JM Davisson of Rules and Records 84/01/23 BELL.N Nuclear Information & Resource Service App 22363 235 24X Fiche 50-220.84/01/23.8402220130
- --9402220132 "Quarterly Task Person Rem Rept.Apr-June 1982 " W/B20730 Itr LEMPGES.T E Niagara Mohawk Power Corp 82/06/30 EIBENHUT.D G Division of Licensing 23pp 22363 239 24X Fichs 50-220.84/01/23.8402220130
- --B402220135 Summary of B20422 meeting w/util re decontamination of recirculation sys.ALARA considerations & removal & replacement of safe-ends Related info encl
 FDLK.F J Operating Reactors Branch 2 82/04/30 Operating Reactors Branch 2 82/04/30 Operating Reactors Branch 2 42pp 22363 262 24x Fithe 50-220.84/01/23.
- 8402030529 Requests remittance of add1 fee for review of 840109 application for Tech Spec change to increase min critical power ratio Class III fee determined appropriate 916GS.R M License Fee Management Branch 84/01/26 RHODE.6 K Niagara Mohaut Power Corp 1g 22082 194 24X Fiche 50-220,84/01/26.8402030529
- 8402060005 Notifies that torus attached piping analysis will be submitted by 840430 instead of 840131.per 83i110 ltr Completion of Mark I program will not be impacted by change LEMPGES.TE Naggara Mohawk Power Corp 84/01/30 VASSALLO.D & Operating Reactors Branch 2 ip 22087 i87 24X Fiche 50-220,84/01/30.8402060005
- 8402070146 Forwards application for amend to License DPR-63, revising Tech Spec Table 4.6 2a re surveillance requirements for instrumentation initiating scram NSHC analysis provided per 840502 Generic Ltr 83-9 LEMPGES, TE Niagara Mohawk Power Corp 84/01/30 VASSALLD, D 8 Operating Reactors Branch 2 1p. 22076 182 24X Fiche 50-220,84/01/30,8402070146
- --8402070150 Application for amend to License DPR-63 revising Tech Spac Table 4 6 2a re surveillance requirements for instrumentation initiating scram LEMPGES T E Niagara Mohawt Power Corp 84/01/30 2gp 22096 183 24X Fiche 50-220 84/01/30 8402070146
- --8402070134 Proposed Tech Spec 4 6 2a re instrumentation initiating stram + Niagara Hohawk Power Corp 84/01/30 6pp 22096 185 24X Fiche 50-220,84/01/30,8402070146
- B402040237 Forwards control room habitability study summary rept per NUREO-0737, item III D 3 4 & util 830606 ltr Results indicate that control room does guidelines of SRP satisfied i.EMP065.T E Niagara Nohawk Power Corp B4/01/31 VASSALLO.D B Operating Reactors Branch 2 6pp 22087 213 24X Fiche:50-220.84/01/31.8402060237
- 40209006B Forwards application for amend to License DPR-63, replacing listed Tech Spec pages re design features, administrative controls & mgt organization LEMPGES. T E Niagara Mohawk Power Corp 84/01/31 VASSALLO, D B Operating Reactors Branch 2 1p 22160 175 24x Fiche 50-220,84/01/31.8402090068
- --8402090073 Application for amend to License DFR-63, replacing listed Tech Spec pages re design features, administrative controls & mgt organization LCRPGES.T E. Niagara Mohawk Power Corp 84/01/31 2pp 22160 176 24X Fiche 50-220,84/01/31.8402090068
- --8402090075 Proposed Tech Boec re design features.administrative controls & mgt organization

 a Niagara Mohaek Power Corp 84/01/31 31pp 22160 178 24X Fiche 50-220,84/01/31.8402090068
 - 2080155 Forwards application for amend to License DPR-63, changing adiological effluent Tech Specs re radiological environ unitoring program
 LMPGES, T E Niagara Mohauk Power Corp 84/02/01 VASSALLO, D 8 perating Reactors Branch 2 2pp 22129 335 24X lche: 50-220, 84/02/01, 8402080155

- --8402080162 Application for amend to License DPR-63, changing radiological effluent Tech Specs re radiological environ monitoring program
 LEMPOES.TE Niagara Mohawk Power Corp 84/02/01 2pp 22129 337 24X Fiche 50-220,84/02/01,8402080158
- --8402080165 Proposed radiological effluent Tach Specs, changing radiological environ monitoring program
 * Niagara Hohawk Power Corp 84/02/01 90pp 22129 339 24X
 Fiche 50-220,84/02/01.8402080155
- B402170057 Forwards Amend 54 to License DPR-63, safety evaluation, EIA & notice of issuance/negative declaration Amend revises Tech Epecs to allow increase in spent fuel storage capacity to mas 2,774 assemblies
 HERMANN.R A Operating Reactors Branch 2 84/02/01 RHDDE, 9 K Niagara Mohawk Power Corp 2pp 22312 277 24X
 Fiche 50-220,84/02/01.8402170057
- --B402170063 Amend 54 to License DPR-63 revising Tech Specs to allow increase in spent fuel storage capacity to max 2,776 assemblies by use of neutron absorbing spent storage racks VASSALLO, D B Operating Reactors Branch 2 84/02/01 4pp 22312 279 24X Fiche 50-220,84/02/01,8402170057
- --8402170064 Safety evaluation supporting Amend 54 to License DPR-63.

 * Office of Nuclear Reactor Regulation, Director 84/02/01
 15pp 22312 283 24X Fiche 50-220,84/02/01,8402170057
- --B402170068 EIA supporting Amend 34 to License DPR-63
 * Office of Nuclear Reactor Regulation, Director 84/02/01
 lipp 22312 298 24X Fiche 50-220,84/02/01,8402170057
- ---B402170069 Notice of issuance of Amend 54 to License DPR-63 & negative declaration VASBALLO,D B Licensing Branch 2 B4/02/01 2pp 22312 309 24X Fiche 50-220.84/02/01.8402170057
- 8402150522 Forwards Amend 55 to License DPR-63 & safety evaluation Amend changes Tech Specs re use of term operable as applied to safety sys in power reactors HERNANN,R A Deprating Reactors Branch 2 84/02/02 RHODE.0 K Niagara Mchawk Power Corp 2pp 22259 293 24X Fiche 50-220.84/02/02.8402150522
- --B402190529 Amend 55 to License DPR-63, changing Tech Specs re use of term operable as applied to safety sys in power reactors VASSALLO, D B Operating Reactors Branch 2 84/02/02 5pp 22257 275 24X Fichs 50-220,84/02/02,8402150522
- --8402150531 Safety evaluation supporting Amend 55 to License DPR-63
 * Office of Nuclear Reactor Regulation. Director 84/02/03 2pp
 22259 300 24X Fiche 50-220,84/02/02,8402150522
- --840215053B "Definition of Operable, Nine Mile Point Nuclear Station, Unit 1" FARMER, F G , STAFFEL, J W EG&B, Inc FIN A-6429 EEG-EA-6360 B3/09/30 NRC - No Detailed Affiliation Given 7pp 22259 302 24X Fiche 50-220, 84/02/02, 8402150522
- 8402240216 Final response to FDIA request for documents re replacement piping at facility Forwards App A & B documents Documents also evailable in PDR FELTON.J M Division of Rules and Records 84/02/03 BELL, N Nuclear Information & Resource Service 3pp 28373 230 24X Fiche 50-000,84/02/03.8402240216
- --8205190430 Comments on evaluation of facility safe-end raplacement Licensee should implement certain reg guides in radiation protection program for use in ALARA HDUBTON.R W. Assistant Director for Radiation Protection 82/05/12 NDVAK.T M. Assistant Director for Operating Reactors ip 22394 001 24X Fichs 50-000,84/02/03,8402240216
- --B206:10034 Advises that review of man-rem exposure estimates for safe-end replacement indicates licensee has taken all appropriate steps to mitigate doses BER/EIA to be issued to allow licensee to proceed PDLK: P J Operating Reactors Branch 2 82/06/07 EISENHUT, D Q. Division of Licensing ip 22374 148 24X Fiche 50-000.84/02/03.8402240216
- --B206250092 Forwards Radiological Assessment Branch inputs to safety evaluation & EIA for safe-end replacement HOUSTON:R W Assistant Director for Radiation Protection B2/06/08 NOVAK.T M Assistant Director for Operating Reactors 18pp 22374 023 24X Fiche 50-000,84/02/03.8402240216

- --8209230151 Trip rept of 820813 site visit re replacement of recirculation sys piping CHENO,C Y Materials Engineering Branch 82/09/02 HAZELTON,W 9 Materials Engineering Branch 16pp 22393 345 24X Fiche 50-000,84/02/03,8402240216
- --B303160017 Identifies info required prior to June 1983 restart Restart contingent upon NRC review & acceptance of stress reanalysis of recirculation sys piping & nozzle 15 safe-end repair info VASSALLO, D G Operating Reactors Granch 2 B3/03/04 LIAN, B D Materials Engineering Branch 1 2 2394 045 24X Fiche 50-000, 84/02/03, 8402240216
- --8306030079 Forwards evaluation of recirculation sys piping replacementstress analysis,per licensee 830422 submittal Repair satisfactorily completed Restart recommended KNIOHT.JP Assistant Director for Comp & Structures Engineering (Pre 830201) 83/05/26 LAINAS.G C Assistant Director for Operating Reactors 3pp 22394 046 24X Fiche 50-000,84/02/03, 8402240216
- --8310060214 Amend 49 to License DPR-63 approving recirculation sys safe-end replacement program including cutting & welding of safe-ends & worker dose mitigation program Safety evaluation encl VASBALLO, D B Uperating Reactors Branch 2 82/04/18 4pp 22393 339 24X Fiche 50-000,84/02/03.8400240216
- --8310060224 Notice of issuance & availability of Amend 49 to License DPR-63 & negative declaration VASSALLO.D B Operating Reactors Branch 2 82/06/18 2pp 22394 OCR 24X Fiche 30-000.84/02/03.8402240216
- --8402240234 Summary of 820422 meeting w/util, Newport News, MPR, NES, GE, EPRI & London Nuclear re recirculation sys decontamination, ALARA considerations & safe-end replacement PDLK: P J Operating Reactors Branch 2 82/04/30 Operating Reactors Branch 2 82/04/30 Operating Reactors Branch 2 42pp 22374 049 24X Fiche 50-000, 84/02/03, 200720214
- --8402240239 Summary of 820813 meeting w/util at site re cracking & recirculation loop piping replacement plans
 GRAY.E H Region 1. Office of Director 82/09/08 Region 1. Office of Director 2pp 22394 105 24X Fiche 50-000, 84/02/03.
- --B402240241 Task interface agreement re RCS piping replacement Action plan listed
 HOLAHAN, Q Division of Fuel Cycle & Material Safety JORDAN, E Director's Office, Office of Inspection and Enforcement STAROBTECKI, R Region 1, Office of Director. B2/08/24 2pp 22394 122 24X Fiche 50-000.84/02/03,8402240216
- ---8402240244 Transfers responsibility for recirculation piping replacement to NRR Regional assistance requested STAROSTECKI.R Division of Project & Resident Programs 82/08/04 EISENHUT. 0 & Division of Litensing 1p 22374
- --BA02240245 Handwritten summary of meeting w/util.MPR.London Nuclear.GF & NEB in Bethesda.MD re stagnant decontamination of loops w/o plugs in vessel # Office of Nuclear Reactor Regulation. Director 82/04/22 Office of Nuclear Reactor Regulation. Director 16pp 22394 132 24X Fiche 50-000.84/02/03.8402240216
- --8402240249 Forwards const schedule for recirculation sys replacement W/o encl MGBIER, M G Affiliation Not Assigned 82/08/31 Affiliation Not Assigned 1p 22394·149 24X Fiche 50-000,84/02/03,8402240216
- B402090277 Responds to Generic Ltr B4-01 re use of terms, important to safety & safety-related Opportunity to discuss issue welcomed Participation will be through steering committee & chairman of util safety classification group.

 i.EMPGEB.T E Niagara Mohawk Power Corp 84/02/06 TAYLOR, J N Director's Office. Defice of Inspection and Enforcement 1p 22161 347 24% Fiche 50-220,84/02/06,8402090277
- 8402160405 Notification of 840208 meeting w/util in Bethesda.MD to discuss literasing action re upcoming refueling outage, technical support ctr & participation re integrated safety program HERMANN.R.A Operating Reactors Branch 2 84/02/07 VASSALLO,D,B Operating Reacturs Branch 2, 1p 22302 131 24X Fiche 50-220.84/02/07.8402160405

- 8402160404 Forwards revised Attachment D consisting of NBHC analysis to 840105 submittal or proposed Tech Spec amend re emergency condenser isolation logic LEMPGES, T E Niagara Mohawk Power Corp 84/02/09 VAESALLO, D 3 Operating Reactors Branch 2 2pp 22269 082 24X Fiche 50-220,84/02/09.8402160404
- 8402140335 Notifies that util will respond to Generic Ltr 83-36 re NUREG-0737 Tech Spers by 840331 Delay necessary to accommodate manpower requirements associated w/upcoming refueling outage LEMPGES.T E Niagara Mohawk Power Corp 84/02/10 VASSALLO.D B Operating Reactors Branch 2 ip 22227 144 24X Fiche 80-220.84/02/10.8402140335
- 84022403/6 Notification of 840227-29 meetings w/util in Oswegp.NY to discuss safety parameter display syn & control room review HERMANN,R A Operating Reactors Branch 2 84/02/17 VABSALLQ.D B Operating Reactors Branch 2 1p 22380 133 24Y Fiche 50-220.84/02/17,8402240376
- O Inspection reports, IE Bulletins & correspondence
- 8402020001 Forwards IE Insp Rept 50-220/83-26 on 831107-10 & notice of violation
 MARTIN T T Division of Engineering & Technical Programs 84/01/17 RHODE 6 K Niagara Mohauk Power Corp 2pp 22057 001 24X Fiche 50-220.84/01/19.8402020001
- ---8402020002 Notice of violation from insp on B31107-10
 * Region 1, Office of Director B4/01/19 2pp 22057 003 24x
 Fiche 50-220,84/01/19,8402020001
- --B402020003 IE Insp Rept 50-220/B3-26 on B31107-10 Violations noted failure to follow certificate of compliance requirements, to identify transport packages as part of GA program & to train personnel CLEMONS.P. HOGAN.R. PASCIAK.W. Region 1. Office of Director B4/01/09 App 22037 005 24X Fichs 50-220.84/01/19.8402020001
- B312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN,E L Division of Emergoncy Preparedness & Engineering Response (Post 830103) 64/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000.84/01/25,831212015 }
- B402150325 Forwards II Insp Rept 50-220/83-27 on B31114-18 No violations noted App B violation re upgrade of radiation protection program withdrawn MARTIN.T T Division of Engineering & Technical Programs 84/01/31 RHODE, G K Niagara Mohawk Power Corp 3pp 22250 227 24y Fichs 50-220,84/01/31,8402150325
- --8402150328 IE Insp Rept 50-220/83-27 on 831114-18 No violations noted Major areas inspected health physics appraisal significant appraisal findings & licensee implementation of corrective actions re action plan progress repts
 NIMITZ, R. L. BICEHOUSE, H. COLLINS, D. Region 1, Office of Director 84/01/25 20pp 22250 230 24% Fiche 50-220, 84/01/31.
- B401190016 IE Info Notice B4-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post E30103) B4/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 177 24X Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEYBUNG.R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp. 22177 156 24X Fiche 50-000,84/02/03,8401190017
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Bafe Shutdown Sys (10CFR30, App R) " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365 259 247 Fiche 50-000,84/02/13,8401190041
- B401190037 IE Info Notice B4-0B, "iOCFR50 7, 'Employee Protection '"
 Svc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/02/14 Consolidated Edison Co. of New
 York, Inc. 115pp 22365 14) 24X Fiche 50-000,84/02/14,8401170039
- B401190045 IE Info Notice B3-63. Suppl 1. "Potential Failures of Hestinghouse Type BA-1 Differential Relays " Bvc list encl JURDAN.E.L. Division of Emergency Prepareduses & Engineering Response (Fost 830103) B4/02/15 Consolidated Edison Co of New York, Inc 118pp 22366 142 24X Fiche 50-000.84/02/15.8401190045

- 8401190062 JE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Hanufacturer Recommended Value " Svc list encl JORDAN, E. t. Bivision of Emergency Preparedness & Engineering Response (Post B30103) 84/02/21 Consolidated Edison Co. of New York, Inc. 116pp 22366-024 24X Fiche 50-000.84/02/21,8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies" Svc list encl JORDAN, E 1. Division of Emergency Praparadness & Engineering Response (Post 830103) 84/02/24 Consolidated Edison Co of New York, Inc 115pp 22430 304 84X Fiche 50-000,84/02/24,8401190066
- B401190067 IE Info Notice 84-12. "Failure of Soft Seat Valve Seals "
 Svr list encl
 JORDAN,E L. Division of Emergency Preparadness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc. 120pp 22431 060 24X Fiche 50-000,84/02/27,8401190067
- R Periodic operating reports & related correspondence
- 8402160366 Monthly operating rept for Jan 1984 W/840210 1tr ROMAN.T W., LEMPSES, T.E. Niegara Mohawk Fower Corp. 84/01/31 6pp 22268 329 24% Fiche 50-220.84/01/31.8402160366
- 8402240216 Final response to FOIA request for documents re replacement piping at facility Forwards App A & B documents Documents also available in PDR FELTON.J M Division of Rules and Records 84/02/03 BELL.N Nuclear Information & Resource Service 3pp 22393 230 24% Fiche 50-000,84/02/03.8402240216
- --8402240220 "Personnel Whole Body Exposures for CY82 " H/830331 ltr LEMPGES,T E Nlagara Hohawk Power Corp 82/12/31 26pp 22393 311 24K Fiche 50-000.84/02/03.8402240216
- S Reportable occurrences. LERs & related correspondence
- B402140344 NPDEB noncompliance notifications for Jul-Sept 1983 Jul & Aug violations concern sewage treatment plan & result of natural algal growth in final process Violation dut Sept result of minor acid spill No enforcement actions taken LEMPGES, T E Niagara Rohawk Power Corp 64/01/16 MURLEY, T E Region 1. Uffice of Director 6pp 22220 113 24x Fiche 30-220, B4/01/18, 8402140344
- B402030236 Nonroutine environ operating rept re fish samples collected during May 1983 Eight of nine sample results for Sr-89 had sensitivities of greater than 80 pCi/kg-dry Caused by short half-lives of radionuclides
 MANDAN.C V Niagara Mchauk Fower Corp 84/01/24 MURLEY.T E
 Region 1. Office of Director Spp 22089 227 24X
 Fiche 50-220.84/01/24,6402030356
- 8402080227 LER 83-046/03L-0 on 831230,12 temporary change submittals re jumper block annunciator relay log not reviewed within 7-day Tech Spec limit Caused by Breakdown in paper flow Instructions revised W/840130 ltr SCHWEDT,A R. LEMPGES.T E Riagara Mohawk Power Corp 84/01/30 HURLEY,T E Region 1, Office of Director 3pp 22130 141 24X Fiche 56-220.84/01/30.8402080229
- 8402090283 Potential Part 21 rept re cable insulation damage found under outer jacket rework in one Class IE electrical cable investigation underway to determine safety significance & scope
 - TITLEHALES. 9 Rockbestos Co 84/02/03 Region 1, Office of Hirector 1p 22137 349 24X Fiche 50-220, 84/02/03, 8402070283
 - KET 50-223 UNIV OF LOWELL RESEARCH REACTOR
 Inspection reports, IE Bulletins & correspondence
- \$02240002 Forwards IE Insp Rept 50-223/83-02 on 831128-1201 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 84/02/09 BEGHIAN.L E Lewell, Univ of Lowell, HA 2pp 22375 223 24x Fiche 50-223,64/02/09,8402240002

28-120: Viplations noted neet quarterly, as at specified occours of Director -223.84/02/09,8402240002

- DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2

 F Becurity, medical, emergency & fire protection plans
- 8402130191 Rev O to Emergency Plan Implementing Procedure EOF-17, "Emergency Operations Facility Activation Facility Log " BERLIN, M D Commonwealth Edison Co 83/09/23 3pp 22199 283 24X Fiche 30-000,83/09/23,8402130191
- B402130213 Rev O to Emergency Plan Implementing Procedure EOF-10, "Nuclear Station Div Non-Edison Transportation Incident Assistance Procedure " * Commonwealth Edison Co 83/09/29 Spp 22204 078 24% Fiche B0-000,83/09/27,8402130215
- 8402100137 Revised emergency plan implementing procedures, including Procedures EPIP EGF-17 re emergency operations facility activation log, EPIP CC-12 re sup power dispatcher & EPIP EDF-12 re access control W/e40203 memo & receipt form MORRE, R D Commonwealth Edison Ca 83/11/09 DENTON, H R NRC No Detailed Affiliation Given 24pp 22181 288 24X Fiche 50-000,83/11/09,8402100137
- B402130220 Rev B to Emergency Plan Implementing Procedure CC-12, "Sys Power Dispatcher" MODRE,R D Commonwealth Edison Co 83/11/09 lipp 22200,108 24X Fichs 50-000,83/11/09,8402130220
- B402150358 Rev 2 to Generating Station Emergency Plan Implementing Procedure EOF-12. "Access Control to Emergency Operations Facility "W/831108 ltr & receipt form MCORE.R B . DUME, J R . MODRE.R D . Commonwealth Edison Co 83/11/30 Spp 82242 358 24X Fiche 50-000,83/11/30,8402150358
- 8402270040 F01A request for NRC emergency planning zone maps for Facilities KOHLENBERGER, 0 Mobil Oil Corp (subs Mobil Corp) 83/12/27 NORRY, P Office of Administration 1p 22407 337 24X Fichs 50-010.83/12/27,8402270040
- 8402060446 Forwards Rev 9 to Emergency Plan Implementing Procedure CC-1. "Corporate Command Ctr Director" Recovery manager priority notification table encl MOCRE.R D Commonwealth Edison Co 84/01/30 DENTON, H R Office of Nuclear Reactor Regulation, Director Zpp 22083 129 24X Fiche 50-000.84/01/30.8402060446
- --8402080464 Rev 9 to Emergency Plan Implementing Procedure CC-1, "Corporate Command Ctr Director," controlled copy MODRE,R D Commonwealth Edison Co 83/11/30 76pp 22083 [3] 24X Fiche 50-000, 84/01/30, 8402080446
- B402270036 Responds to FDIA request for NRC emergency planning tone maps for facilities Maps may be reproduced for listed costs or examined at Region III ofc FELTON.J M Division of Rules and Records 84/02/01 KOHLENBERGER, G Mobil Oil Corp. (subs Mobil Corp.) ip 22407 336 24X Fiche 50-010,84/02/01.8402270036
- B402070R02 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per B30709 itr W/n request, entire plan will be claced in PDR CRUTCHFIELD.D Operating Reactors Branch 5 84/02/02 FARRAR, D.L. Commonwealth Edison Co. 2pp. 22100 029 24X Fiche 50-010.84/02/02.8402070202
- 8402130447 Confirms 840219 enforcement conference at Region III oft to discuss recent security event at Dresden & health physics events at Zion NORELIUG, C E Division of Project & Resident Programs 84/02/02 REED. C Commo
- 8402100228 Forwards joint exercise rept of 830914 exercise of offsite radiological emergency preparedness plans for facilities Btate of IL & Grundy. Kendall & Will Counties participated KRIMW-R W Federal Emergency Management Agency 84/02/06 JORDAN-E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 22179 226 24X Fiche 50-010.84/02/06.8402100228
- --8402100233 Evaluation of Joint exercise rept of 830914 exercise of offsite radiological emergency preparedness plans for facilities # Federal Emergency Management Agency 83/12/13 35pp 22179 228 24X Fiche 50-010,84/02/06,8402100228

8402280395 Revised emergency plan implementing procedure, including Revito BZP 600-A4, "GSEP Telephone Directory"

* Commonwealth Edison Co 84/02/18 61pp 22404 158 24X
Fiche 50-000.84/02/18.8402280395

Q Adjudicatory correspondence

- 840207012B Order extending time until 840213 for Commission to act to review Director's Decision DD-83-14 & extending 831029 decision denying Environ Policy Inst request to 840213 CHILK. S J Office of the Secretary of the Commission 84/02/03 Commissioners 1p 22100 198 24% Fiche 50-000.84/02/03, 840207012B
- 8402130195 Order extending time until 840221 for Commission to act to review Director's Decision DD-83-14 CHILK.5 J Office of the Secretary of the Commission 84/02/13 Commissioners 1p 22245 147 24X Fiche 50-000.84/02/13.

I Financial information

8402280410 Annual Financial Rept 1983 W/840221 ltr O'CONNOR.J J , BRESEMANN.R W Commonwealth Edison Co 83/12/31 29pp 22407 101 24X Fiche 50-000,83/12/31,8402280410

P Operating license stage documents & correspondence

- B312120027 Generic Ltr 83-37 to representatives of utils re voluntary survey of licensed operators Svc list encl EIBENHUT, D G Division of Licensing B3/12/08 Commonwealth Edison Co 12pp 22313 006 24% Fiche 50-000, B3/12/08, B312120027
- 8402010061 Summary of 840126 meeting w/util.Wester,Bechtel,Bargent & Lundy & INEL in Bethesda.MD re equipment environ qualification review Agenda & list of specific equipment qualification deficiencies encl OLBERT.R A Operating Reactors Branch 5 B4/01/30 Operating Reactors Branch 5 36pp 22042 127 24X Fiche 50-000.84/01/30, 8402010061
- 8402140209 Forwards response to Generic Ltr 83-34 requesting licensees to submit Tech Specs or schedule for NUREG-0737 items scheduled after Bil231 All appropriate Tech Spec amend requests will be submitted by 840815

 BARNES, P. L. Commonwealth Edison Co. 84/02/09 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 9pp. 22227 341

 24X

 Fiche 50-000.84/02/09.8402140205
- 8402210238 Concurs w/NRC opinion that requirements of TMI Items II, K 3 30 & 31 met Updated FSAR scheduled for June 1984 will document reasons small break LOCA analysis not required after addition of Exxon fuel RYBAK.B Commonwealth Edison Co 84/02/10 DENTON, H R. Office of Nuclear Resctor Regulation, Director 1p 22315 358 24X Fiche 50-237,84/02/10,8402210238
- 8408240115 Application for amend to Licenses DPR-19 & DPR-23, revising Tech Specs re 125/250-volt batteries & iodine limits in reactor coolant for resolution of SEP Topics VI-7 C 1 & XV-16
 RYBAK.B Commonwealth Edison Co 84/02/10 DENTON, H R Office of Nuclear Reactor Regulation. Director 5pp 22373 261 24X
 Fiche 50-237.84/02/10.8402240115
- --8402240118 Proposed Tech Specs 3 9 & 4 9 re 125/250-volt batteries & iodine limits in reactor coolant * Commonwealth Edison Co 84/02/10 9pp 22373 266 24X Fitche 50-237.84/02/10.8402240115
- 840R160378 Forwards request for addl info to complete Mark I containment long-torm program plant-unique analysis rept structural evaluation Response requested within 45 days of ltr data CRUTCHFIELD, D. Operating Reactors Branch S. 84/02/14 FARRAR, D.L. Commonwealth Edison Co. 4pp. 22269*114 24X Fiche, 50-237, 84/02/14, 8402160378.
- 8402170259 Forwards Amends 80,72,86 & 81 to Licenses DPR-19, DPR-25, DPR-29 & DPR-30, respectively Amends approve Tech 8pec changes providing add1 limiting conditions for Class IE power monitoring sys CRUTCHFIELD D Operating Reactors Branch 5, 84/02/14 FARRAR, D t. Commonwealth Edison Co. 3pp. 22297 112 24X Ficher 50-000,84/02/14,8402170259
- --B402170276 Amends 80,72,86 & Bi to Licenses DPR-19,DPR-25,DPR-25 & DPR-30, respectively, approving Tech Bpec changes providing add1 limiting conditions for Class IE power monitoring sys CRUTCHFIELD,D Operating Reactors Branch 5 B4/02/14 28pp 2227 115 24X Fiche 50-000.84/02/14,B402170259

- B402270400 Forwards SER re corrective actions taken concerning tulus vacuum breaker leaks, per util B31007 ltr Containment boundary repairs acceptable & corrective actions to prevent recurrence adequate CRUTCHFIELD.D Opporating Reactors Branch 5 B4/02/24 FARRAR.D | Commonwealth Edison Co 2pp/ 22370 354 24X Fiche 50-237, B4/02/24,8402270400
- --B402270402 SER supporting corrective actions taken re torus vocuum breaker belimus leak * Defice of Nuclear Reactor Regulation, Director B4/02/24 Jp. 22390 356 24X Fiche 50-237.84/02/24.8402270400
- B402280457 Forwards Amends 81, 73, B7 & 82 to Licenses DPR-19, DPR-29, DPR-29 & DPR-30, respectively & safety evaluation Amends revise Tech Specs to require restoration of safety/relief valve inoperable position indication CRUTCHFIELD, D. Operating Reactors Branch 5 84/02/24 FARRAN, D. 1 Commonwealth Edison Co. 3pp 22405 315 24X Fiche 50-000, 84/03/21 8402280457
- --8402280492 Amends Bi.73.87 & B2 to Licenses DPR-19, DPR-25, DPR-29, DPR-30, respectively, changing leck Specs to require restoration of all safety/relief valve (noperable position indication prior to startup when in cold shutdown over 72 h CRUTCHFIELD, D. Operating Reactors Branch S. VASSALLD, D.B. Operating Reactors Branch S. VASSALLD, D.B. Operating Reactors Branch S. 22406 318 ,24% Fiche 50-000,84/02/24,8402280457
- --8402280531 Safety evaluation supporting Amends 81.73.87 & 82 to Licenses DPR-19.DPR-25.DPR-29 & DPR-30, respectively * Office of Nuclear Reactor Regulation. Director 84/02/24 **\psi_22406_334 24X Fichy 50-000.84/02/24,8402280457

G Inspection reports. IE Bulletins & correspondence

- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Foodwater Pumps " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/25 Consolidated Edison Co of Ner York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,831212/017
- B402020341 Ack receipt of B40120 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-010/B3-19, 50-237/B3-29 & 30-249/B3-27 NDRELJUS.C E Division of Project & Resident Programs 84/01/R/REED.C Commonwealth Edison Co 1p 22059 031 24X Fiche 50-010.84/01/27,8402020341
- --8402020345 Responds to NRC B31221 ltr re violations noted in It Insurepts 50-010/83-19,50-237/83-29 & 50-249/83-27 Corrective actions operational procedures will be revised by 840401 to clarify actions needed when APRM gain drifts FARRAR, D L. Commonwealth Edison Co. 84/01/20 KEPPLER, J Q Region 3, Office of Director 5pp. 22055 032 24x Fiche 50-010,84/01/27,8402020341
- B402170081 Forwards IE Insp Repts 50-010/83-22, 50-237/83-32 & 50-247/83-30 on B31118-840119 & notice of violation BHAFER. W D Region 3. Office of Director \$4/02/01 REED. C Commonwealth Edison Co. 2pp 22300 014 24X Fiche 50-010, 84/02/01
- --8402170085 Notice of violation from insp on 831118-840117 SHAFER.W D Region 3, Office of Director 84/02/01 2pp 22300 016 24X Fithe 50-010.84/02/01.8402170081
- --8402170088 IE Insp Repts 50-010/83-22, 50-237/83-32 & 30-249/83 (10 mm 83118-840119 Nuncompliance noted isolation condenser drain valve 2-4808-501 found in closed position but not chained & lacked & failure to have employee conduct procedure TONGUE, T M , 8TASEK, S , ANDERSON, C D Region 3, Office of Director 64/01/31 20pp 22300 018 24X Fiche 50-010.04/07/03 8402170081
- 8402080378 Forwards info nocessary to complete NRC review of IE
 Bullotin 80-11, "Masonry Wall Design " W/three oversize
 proprietary drawings Aperture cards are available in Central
 Files
 RYBAK, B Commonwealth Edison Co 84/02/02 DENTON, H R Office OF
 Nuclear Reactor Regulation, Director 33pp 22180 033 24X
 Fiche 50-000.84/02/02.8402080378
- --B40P0B03B5 Rev & to Procedures Manual OP-45. "Sampling & Testing of Hollow Concrete Masonry Units" LINDBTROM.R. KRAUSE.R. Wiss, Janney, Elstner & Associates, In: 82/07/22 13pp 22160 066 24X Fiche 50-000, B4/02/02:8402080.
- --84020B0394 Rev 2 to Procedures Manual OP-46, "Testing of Compression Cores Taken From Bolid Block Walls" LINDSTROW, R, KRAUSE, R Wiss, Janney, Elstner & Associates, Inc 82/06/24 lipp 22160 079 24X fiche 50-000, 84/02/02, 84080B0.J/i)

- --8402080401 Rev 2 to Procedures Manual OP-47, "Determination of Mortar
- --8402080409 Rev 7 to Procedures Manual OP-50, "In Situ Shear Test of
- --8402080414 "Studies of Dresden Mortars " HIME, W G . ERLIN.B Erlin, Hime Associates, Inc 22160 140 24X Fiche 50-000,84/02/02,8402080378 82/07/30 6pp
- --B4020B0419 "Masonry Wall Impact Tests " * Bechtel Corp 82/10/31 27pp 22160 146 24X * Bechtel Corp 82/10/31 27p
- B401190016 JE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineoring Response (Post B30103) B4/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24x Fiche 50-000.84/02/03.8401190016
- 8401190017 TE Bulletin 84-01. "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEVOUND.R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 156 24X Fichs 50-000,84/02/03,8401190017
- B402150250 Forwards IE Insp Repts 50-010/83-23.50-237/83-33 & 50-249/83-31 en 831109-10 & 1205-20 PAPERIELLO.C J Region 3. Office of Director B4/02/03 REED.C Commonwealth Edison Co 2pp 2250 261 24X Ficke 50-010.84/02/03.
- --8402150257 IE Insp Repts 50-010/83-23,50-237/83-33 & 50-249/83-31 on 831109-10 & 1205-20 Noncompliances noted failure to provide training & failure to control entry into high radiation AVELS A , NICHOLSON, N A , GREGER, L R Region G, Office of Birector 84/02/02 11pp 22230 263 24X Fiche 50-010.84/02/03.8402150250
- "402150210 Responds to 16 Bulletin 94-01 re insp of DWR Mark I MISO210 Responds to IR Bulletin M9-OI re inep of DAR Mark I containments currently in shutdown No cracks found during 'sual insp Through-wall crack on main vent & vent header sembly considered very unlikely insp details encl.

 BACK-B Commonwealth Edison Co 89/02/10 KEPPLER, J G Region Office of Director 3pp 22244 118 24X Fiche 30-237,84/02/10,02150210
 - 190041 IE Info Notice 84-09, "Lassons Learned From NRC Insps of re Protection Bafe Shutdown Bys (10CFRSO, App R) " Byc list Division of Emergency Preparedness & Engineering st 830103) 84/02/13 Compolidated Edison Co. of New 124pp. 22365 259 24% Fiche 50-000.84/02/13,8401190041 sponse (Post 830103) 124pp.
 - i90039 IE Info Notice 84-08, "10CFR50 7. 'Employee Protection '"
 list ancl
 RDAN.E.C. Division of Emergency Preparadness & Engineering
 sponse (Post 830103) 84/02/14 Consolidated Edison Co of New
 rk. Inc 115pp 22365.141 R4X Fiche 50-000.84/02/14.8401190039
 - 190945 IE Info Notice B3-63, Suppl 1. "Potential Failures of tinghouse Type BA-1 Differential Relays " Syc list encl toAM.E L Division of Emergency Preparedness & Engineering toAMSE (Post B30103) 84/02/15 Conspilidates Edison Co of New No. Inc. 118pp 22364 142 24X Fiche. 50-000.84/02/15. 8401190045
 - .90062 IE info Notice 84-10. "Motor-Operated Valve Torque Switches The Holam Manufacturer Recommended Value " Svc list encl 'ARAN.E L Division of Emergency Preparedness & Engineering exponse (Post 830103), 84/02/21 Consolidated Edison Cofor, Inc 116pp 22366 024 24X Fiche 30-000,84/02/21,8401 24X Fiche 50-000,84/02/21,8401190062
- Di190066 IE Info Notice of Section 1975.

 Byc list enci
 JDRDAN,E L Division of Emergency Proparedness & Engineering
 Response (Post 830103), 84/02/24 Consolidated Edison Co. of New
 York, Inc. 115pp 22430 304, 24X Fichs.50-000,84/02/24,8401190066 D1190046 IE Info Natice 84-11. "Training Program Deficiencies "
- 401190067 TE Info Notice 84-12, "Failure of Boft Beat Valve Seals " SVC list encl
 JORDAN,E t. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/27 Consolidated Edison Co of New
 York, Inc. 120pp. 22431 060 24X Fiche: 50-000,84/02/27,8401170067

- R Periodic operating reports & related correspondence
- 8402190362 Monthly operating repts for Jan 1984 W/840201 ltr SCHRDEDER, B A , SCOTT, D J Commonwealth Edison Co 84/01 SCHROEDER.B A , SCOTT, D J Commonwealth Edison C 22242 324 24X Fiche 50-237,84/01/31,8402150362 B4/01/31 17am
- 8 Reportable occurrences, LERs & related correspondence
- 8402030250 LER 83-084/03L-0 on 831230 primary containment oxygen sample from torus alarmed on low sample flow Caused by moisture in sample line due to heat trace leads being removed Line drained & leads reconnected W/840125 ltr IEROAN.6 W , BCDTT.D J Commonwealth Edison Co 84/01/25 KEPPLER.J G Region 3, Office of Director 2pp 22069 230 24X Fiche 50-237.84/01/25.8402030250
- 8402060133 LER 84-001-00 on 840102 two of four redundant main steam line low pressure switches tripped below Toch Spec limits Caused by instrument setpoint drift Switches recalibr
- 8402060396 Forwards investigative committee final rept re 840109 put-of-sequence shutdown event Rev to DGP 3-4 providing consistent method of designating sequence steps recommended RYBAN-B Commonwealth Edison Co 84/01/30 KEPPLER, J 9 Rep RYBAK, B Commonwer reside of Director Region 3, 24X Fiche 50-237, 84/01/30,
- --8402060398 Rev 4 to "Control Rod Sequence Package MAYNE, M Commonwealth Edison Co 83/12/27 RAX Fiche 50-237,84/01/20,8402060398 1800 22086 158
- 8402190233 LER 84-002-00 on 840117, standby gas treatment train B fan discharge damper 2/3-7507B control room indication found inoperative Caused by tripped breaker Breaker reset & control room indication restored W/840208 ltr ANANDAPA.A . SCOTT.D J Commonwealth Edison Co 84/02/07 2pp 22245 114 24X Fiche 50-237.84/02/07.8402150233
- 8402290219 Updated LER 83-062/01X-1 on 830819. HPCI motor gear unit NO2270219 Updated LER 83-062701x-1 on B30819,FRC1 motor gea moved between high & low speed stops w/o operator action Caused by failed HPCI sys controller operational amplifier Amplifier replaced Jumper installed W/040216 tr LEAHY.M. BCOIT,D J Commonwealth Edison Co 84/02/16 KEPPLIR.J G Region 3, Office of Director 4pp 22426 3 Fiche 50-237,84/02/16.8402270219 22426 309
- DOCKET 30-244 ROBERT SMMET GINNA NUCLEAR PLANT, UNIT 1 f Security, medical, emergency & fire protection plans
- B402020353 Forwards 1E Insp Rept 50-244/83-25 on 831115-18 No violations noted
 MARTIN.T T Division of Engineering & Technical Programs &
 MAIER.J E Rochester Gas & Electric Corp 2pp 22052:225
 Fiche.50-244.84/01/18.8402020353
- --8402020357 IE Insp Rept 50-244/83-25 on 831115-18 No violations noted. Major areas inspected emergency preparedness items from 811102-13 appraisal & public notification sys insp on 830607-19 COHEN, I CROCKE CROCKER.H W Region 1, Office of Director 84/01/09 952-227 24X Fiche: 50-244.84/01/18,8402020353
- 8402070380 Forwards rept comparing instrumentation listed in Rev 2 to Reg Quide i 97 & instrumentation available at facility Revised emergency procedures, developed to meet Suppl i to NUREO-0737 requirements, expected to be complete by Aug 1984 MAIER.J.E. Rochester Gas & Electric Corp 84/01/31 CRUTCHFIELD.I Operating Reactors Branch 5. Bpp 22094,354 24X Fiche 50-244,84/01/31,8402070380 CRUTCHFIELD, D
- 8402170284 Revised emergency plan implementing procedures, including Rev B to Procedure 80-606, "Specialized Notification List" & Rev 7 to Procedure SC-607, "Station Call List" W/840214 84/02/02 MURLEY, T. E.
 - KUBER,R W. Rochester Gas & Electric Corp. 84/02/02 Region 1, Dffice of Director 7pp. 22277 041. 24X Fiche 50-244,84/02/02.8402170284
- 8402070333 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per Generic Ltr 81-27. W/o request, entire plan will be placed in PDR GRUTCHFIELD. D Operating Reactors Branch 5 84/02/06. KOBER, R W. Rochester Oos & Electric Corp 2pp 22098:361 24X Fiche. 50-244, 84/02/06, 8402070353

- 8402140072 Notification of 840222 meeting w/vtil in Bethesda,MD to discuss alternative safe shutdown sys proposal & util request for schedular exemptions from 10CFR50 48(c)(4) DICK.O F Operating Reactors Branch 5 B4/02/10 CRUTCHFIELD.D Operating Reactors Branch 5 3pp 22217 248 24X Fiche 50-244.84/02/10.8402140072
- 8402290109 Requests that full-scale emergency exercise required by App E to 10CFR90 be held no later than 840930, well separated from refueling outage
 KOBER, R W Rochester Gas & Electric Corp. 84/02/24 CRUTCHFIELD, D
 Operating Reactors Branch 5 ip 22428 001 24x
 Fiche 50-244.84/02/24.8402290109

O Adjudicatory correspondence

- B402010218 Informs that M Blade will be placed on distribution list for all facility-related correspondence originating from Region I W/o encl Region I insp repts for 1983 & BALP repts for Jul 1980 May 1983 YDUNG M A Hearing Branch 4 B4/01/25 SLADE, M Affiliation No Assigned ip 22038 362 24X Fiche 50-244,84/01/25,8402010218 Affiliation Not
- B402060163 Advises that effective 840201. JE Maier will become senior vice-president operations & engineering RW Koher will become vice president electric & steam production & should replace Maier on Ext list VOIOT. H H LeBoeuf. Lamb. Leiby & MacRae VOIOT. H H Rochester & Electric Corp 84/01/31 GROBSMAN. H. COLE. R F., LUEBKE. E A Atomic Bafety and Licensing Board Panel 1p 22087 168 24X Fiche 50-244.84/01/31.8402060163 Rochester Gas
- --8402060169 Informs that util will not respond at present to SV Bollock 840124 ltr re notification of possible untimely filing of petition for leave to intervene Util reserves right to oppose petition if filed VOIGT.H H LeBoeuf, Lamb, Leiby & MacRae VOIGT.H H Rochester Gas & Electric Corp 84/01/31 @GROSMAN.H . COLER F. LUEBKE.E A Atomic Safety and Licensing Board Panel 1p 22087 169 24X Fiche 50-244,84/01/31,8402040163
- 8402100152 Forwards iOCFR2, "NRC Practice & Procedure," Digest 2 & Suppl 1 to Digest 2 W/o and Communication of Parel B4/02/09 BULLOCK B V Affiliation Not Assigned 2pp 22182 204 24x Fiche 50-244, 94/02/09, 8402100152
- ---B402100154 Requests copy of rules & rights for intervenors in upcoming full-term license hearings
 BULLOCK.B V Affiliation Not Assigned 84/02/02 GROSSMAN, H
 Atomic Safety and Licensing Board Panel 1p 22182 205 24X
 Fich

P Operating license stage documents & correspondence

- B402080009 FOIA request for correspondence between NRC, JGP&L & Rochester Gas & Electric re shipment of irradiated fuel from West Valley, NY & correspondence on route applications between listed labs & Bayannah River Plant REBNIKOFF, M Sierra Club 83/11/29, NRC No Datailed Affiliation Given ip 22174 008 24X Fiche 50-000,83/11/29, page 2000
- 8402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CMILK.8 J Office of the Secretary of the Commission 83/12/14 Public Decument Branch ip 22281 023 24X Fiche 50-000,83/12/14.8402160003
- -8402160259 Discusses SECY-82-226 re AO recommendation on steam generator tube rupture at plant
 CHILK.8 J Office of the Secretary of the Commission 82/06
 DIRCKS.W J Office of the Executive Director for Operations
 22281 200 24X Fiche 50-000.83/12/14.8402160003. 02/06/24
- B40201006B Forwards Amend 89 to License DPR-18 & safety evaluation Amend revises Tech Bpec Table 3 5-2 to indicate safety functions which have manually-initiated operating bypass CRUTCHFIELD, D. Operating Reactors Branch 5 84/01/30 MAIER, J. Rochester Oas & Electric Corp 3pp 22042 269, 24X Fiche B0-244:84/01/30.840201006B MAIER, J. E
- ---B402010075 Amend 59 to License DPR-iB, revising Tech Besc Page 3 5-5 re safety functions which have manually-initiated operating bypass CRUTCHFIELD, D Operating Reactors Branch 5 84, 22042 272 24X Fiche 50-244,84/01/30,8402010068 84/01/30, 4pp
- ---8402010083 Bafety evaluation supporting Amend 57 to License DPR-18 LI.H., DICK.0 Office of Nuclear Reactor Regulation, Director 84/01/30 3pp 22042 276 24X Fiche: 50-244,84/01/30,8402010068

- B402010410 Generic Ltr 84-04 to all operating PWR licensees, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Svc list encl EIGENHUT. D & Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc 39pp 22177 087 24X Fiche 50-000,84/02/01,8402010410
- 840207013B Updates actions taken to satisfy requirements of NUREO-0737. Item II B 2, "Plant Shielding " Consequences of accidents can be controlled w/o access to radueste control panel through recently installed remote monitor KDBER,R W Rochester Gas & Electric Corp 84/02/01 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 22100 165 24X Fiche 50-244,84/02/01.8402070138
- 8402100246 Forwards info in response to NRC 820902 ltr re NUREG-0737. Obstacting Reactions Branch 5 dapp 12204 327 24x

 Fichs 50-244,84/02/06.8402100246
- --8402100252 Rev 1 to Procedure EWR 2606, "Design Criteria Ginna Station Post-Accident Bampling Sys Implementation " MAMBRETTI, C. J. DAVIS, R. T. Rochester Cas & Electric Corp 82/07/20 28pp 22205 043 24X Fiche 50-244.84702/06,8402100246
- --8402100256 Rev O to Procedure PC-25 4, "Gwidance for Interpreting Post-Accident Sampling Results to Estimate Reactor Core Damage " ** Rochester Gas & Electric Corp 63/03/16 9pp 2RR05 071 24x
 Fiche 50-244,84/02/06,8402100246
- 8402100220 Forwards Amend 60 to License DPR-18 & safety evaluation NUMBRUSER FORWARDS AMEND OU TO LITERS OF MEMBERS AS A FEEL OF NEW AMEND Approves Tech Spec change to permit storage in Westinghouse 14X14 fuel assembly new & spent fuel racks CRUTCHFIELD, D Operating Reactors Branch 5 84/02/08 Rochester Gas & Electric Corp 3pp 22178 068 24X Fiche 50-244,81/02/08.8402100220 MAIER, J E
- --8402100224 Amend 60 to License DPR-18 approving Tech Specs to permit storage in Westinghouse 14X14 fuel assembly new & spent fuel racks CRUTCHFIELD, D. Operating Reactors Branch 5 84, 22178 071 24X Fichs 50-244,84/02/08,8402100220 84/02/0B App
- --8402100227 Safety evaluation supporting Amend 60 to License DPR-18
 * Office of Nuclear Reactor Regulation, Director 84/02/08 4;
 22178 077 24X Fiche 50-244.84/02/08.8402100220
- 8402140072 Notification of 840222 meeting w/util in Bethesda, MD to NOTION/2 Notification of B40222 meeting W/VEII betnesda, ND to discuss alternative safe shutdown sys proposal & util request for schedular exemptions from 10CFR30 48(c)(4. DICK.6 F Dperating Reactors Dranch 5 84/02/10 CRUTCHFIELD.D Dperating Reactors Branch 5 3pp 22217 248 24X Fiche 50-244.84/02/10.8402140072
- 8402150128 Requests exemption from requirement for two senior reactor operators (SRD) to be on shift except when in cold or refueling conditions & exemption from one SRD in control room except in cold or refueling conditions until 840703 KUBER, R W Rochester Gas & Electric Corp 84702/10 CRUTCHFIELD, I Operating Reactors Branch 5 3pp 22247 274 24% Fiche 50-244,84702/10,8402150128
- 8402290169 Forwards Westinghouse rept. "Dynamic Colleges of Steam Generator Tubes." per NRC request KDBER.R W Rochester Gas & Electric Corp 84/02/24 CRUTCHFIELD.D Dpersting Reactors Branch 5 1p 22425 243 24X Fiche 50-244.84/02/24.8402290169
- --8402270172 "Dynamic Coliapse of Steam Generator Tubes " PRIDEMORE:W H Westinghouse Electric Corp 82-7P4-EMVTL-R2 82/11/16 35pp 22425 244 24X Fiche 50-244.84/02/24.8402270169
- O Inspection reports. IE Bulletins & correspondence
- 8402020107 Forwards IE Insp Rept 50-244/83-23 on 831018-1118 & notice of violation BTAROSTECKI,R Division of Project & Resident Programs BI MAIER,J E Rochester Gas & Electric Corp 2pp 22056 239 Fiche 30-244,83/12/28,8402020107 83/12/26
- --8402020108 Notice of violation from insp on 831018-1118 * Region 1. Diffice of Director 83/12/28 3pp 220 Fiche 50-244.83/12/28.8402020107 22056 241

- --8402020112 IE Insp Rept 50-244/83-23 on 031018-1118 Noncompliance noted mod turnover control math storage control & failure to adhere to plant administrative controls for completing procedures for administrative controls ZIMMERMAN.R P Region i. Office of Director LAZARUS, W J, REYNOLDS.S D Division of Project & Resident Programs B3/12/09 11pp 22056 244 24X Fiche 50-244,83/12/28,8402020107
- 8402020390 Forwards IE Insp Rept 50-244/83-23 on 831018-1118 re allegation involving GA One Security Level IV & two Security Level V violations noted CRUTCHFIELD.D. Operating Reactors Branch 5 84/01/11 EDISON.G E Division of Licensing 21pp 22062 187 24X Fiche 50-244,84/01/11,8402020390
- --8402020393 Forwards lE Insp Rept 50~244/63-23 on 831018-1118 & notice of violation re allegation involving QA STAROBTECKI.R Division of Project & Resident Programs 64/01/11 MAIER.J & Rochester Qas & Electric Corp 2pp 22062 188 24X Fiche 50-244,84/01/11,8402020390
- --8402020374 Notice of violation from insp on 831018-1118 * Operating Reactors Branch 5 84/01/11 3pp 22062 190 24X Fiche 50-244,84/01/11,8402020390
- --8402020399 IE Insp Rept 50-244/83-23 on 831018-1118 Violations noted failure to adhere to plant administrative controls for completing procedures STAROSTECKI, R Division of Project & Resident Programs LAZARUS.W J . REYNDLOS.S D Region i. Office of Director 83/12/09 15pp 22062 193 24X Fiche 50-244,84/01/11,8402020390
- 8402020353 Forwards IE Insp Rept 50-244/83-25 on 831115-18 No violations noted MARTIN.T T Division of Engineering & Technical Programs 84/01/18 MAIER.J E Rochester Oas & Electric Corp 2pp 22052 225 24X Fiche 50-244.84/01/18.8402020353
- ---B402020357 IE Insp Rept 50-244/83-25 on B31115-IB No violations noted Major areas inspected emergency preparedness items from B1102-I3 appraisal & public notification sys insp on 830607-19 COHEN.I. CROCKER.H W Region 1. Office of Director B4/01/09 900 22052 227 24X Fiche 50-244.84/01/18.8402020353
- 312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps" Svc list entl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fithe 50-000,84/01/25,8312120153
- l01190016 IE info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Centrols" Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc. 119pp 22114 179 24X Fiche 50-000,84/02/03,8401190016
- ROI190017 IE Bulletin 84-01, "Cracks in BHR Mark I Containment Vent Headers " Svc list encl DEYDUNG.R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 156 24X Fichs 50-000,84/02/03,8401190017
- 402240096 Forwards 16 Insp Rept 50-244/83-24 on 831101-840115 & notice of violation
 STARGSTECKI, R Division of Project & Resident Programs 84/02/07
 MAIER, J E Rochester Cas & Electric Corp 2pp 22373 275 24X
 Fiche 50-244,84/02/07,8402240096
- --8402240097 Notice of violation from insp on 831101-840115 * Region 1, Diffice of Director 84/02/07. 1p 22373 277 24X Fiche 50-244.84/02/07,8402240094
- --8402240098 IE Insp Rept 50-244/83-24 on 831101-840115 Violation noted juding removal surveillance test performed on 831201 measured at 264 F. rather than 284 F. ZIMMERMAN, R P. COLLINS, S. J. Region j. Office of Director 84/02/01 11pp 22373 278 24X Fiche 50-244,84/02/07,8402240096
- 8401190091 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (IOCFR50, App R)" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/13 Consolidated Edison Co of New York Inc 124pp 22365 259 24% Fitche 50-000, 84/02/13, 8401190041
- York, Inc. 124pp. 22365 259 24% Fiche 50-000, 84/02/13, 840119004
- 9401190039 IE Info Notice 84-08, "10CFR50 7, "Employer Protection ""
 Svc list encl
 JDRDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc. 115pp 22365-141 24X Fiche 50-000,84/02/14,8401190039

- B401190045 IE Info Notice B3-63, Suppl 1, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc 118pp 22366 142 24X Fiche 50-000,84/02/15 8401190045
- B401190062 IE Info Notice B4-10, "Motor-Operated Valve Torque Switches Set Belaw Manufacturer Recommended Value " Svc list encl URDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/02/21 Consolidated Edison Co of New York, Int 116pp 22366 024 24X Fiche 50-000,84/02/21,8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies "
 Bvc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche, 50-000, 84/02/24, 8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals." Svc list encl JORDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/27 Consolidated Edison Co of New York, Inc 120pp 22431 060 24% Fiche 50-000,84/02/27,8401190067
- 9 Reportable occurrences, LERs & related correspondence
- 8402020255 LER 83-030/03L-0 on 831216 actual satpoint for permissive circuit P-10 found low at 8% rather than 10% full power Caused by conflicting Tech Spec requirements Rev proposed W/840113 ltr
 MAIER J E Rochester Gas & Electric Corp 84/01/13 MURLEY, T E Region 1, Office of Director 3pp 22055 340 24% Fiche 50-244,84/01/13.8402020255
- V Operator Examinations
- B402130063 Notification of Significant Licensee Meeting 84~13 on 840203 w/util in King of Prussia.PA to discuss NRC review of operator requalification program COLLING.8 J Region 1, Office of Director 84/02/01 COLLING.8 J Region 1, Office of Director 19 22213 314 24X Fiche 50~244.84/02/01.8402130063
- B402230236 Discusses 840210 exemption request re 10CFR50 54(m)(R) shift staffing requirements Request will be considered following evaluation of modified operator requalification program CRUTCHFIELD.D Operating Reactors Branch 5 84/02/22. KOBER.R W Ruchester Gas & Electric Corp 2pp 22352 361 24% Fiche 50-244.B4/02/22.8402230236
- 8402280707 Notification of Significant Licensee Meeting 84-21 on 840301 w/util in King of Prussia:PA to discuss intermediateterm itemsed operator requalification program CULLINS:S J Region 1. Office of Director 84/02/23 Region 1. Office of Director 94/02/23 Region 1. Begion 1
- DOCKET 30-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- B402010217 Forwards emergency plan implementing procedures, in response to NRC 830718 request re dustanding issues concerning post-accident sampling sys Capability of measuring reactor coolant dissolved oxygen will not be provided CDUNBIL. W 0 Connecticut Yankee Atomic Power Co CDUNBIL. W 0 Northeast Nuclear Energy Co (subs. of Northeast Utilities). CDUNBIL. W 0 Northeast Nuclear Energy Co (subs. of Northeast Utilities). CDUNBIL. W 0 Northeast Utilities 84/01/12 CRUYCHFIELD, D Operating Reactors Branch 3 3pp. 22039 280 24X Fiche 50-000.84/01/12,8402010217
- --8402010232 Rev O to Emergency Plan Implementing Procedure EPIP 4221,
 "Core Damage Estimate Procedure"
 MRCCZKA, E. JAMORSKY, M. Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/03/31 23pp 22039 303 24X
 Fiche 50-000, 84/01/12, 8402010219
- B402150182 Rev 93 to emergency plan implementing procedure index & Rev 4.Change 1 to Procedure OP-501. "Incident Assessment & Classification Unit 1" COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Northeast Utilities B4/01/30 E1BENHUT,D G Division of Licensing 10pp 22241 176 24X Fiche 50-245.84/01/30.8402150182

- 8402160005 Notifies of necessity to relocate technical support ctr (TBC) from Unit 1 computer room by Mar 1984 due to computer replacement program TBC proposed to be moved to new facility in May & to emergency operations facility in interim COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities). COUNSIL, W O Northeast Utilities 84/01/31 MILLER, J R Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 3 Page 184/01/31, 8402160005.
- 8402090108 Forwards Rev 2 to suitability, training & qualification plan
 Rev withheld
 MDFRIO. H D Northeast Utilities Service Co (subs of Northeast
 Utilities), 84/02/03 DENTON, H R Office of Nuclear Reactor
 Regulation, Director 1p 22163:314 24X Fiche 50-245,84/02/03,
 8402090108
- 8402140135 Responds to NUREO-0737, Buppl 1 re requirements for emergency response capabilities/emergency operations facilities, Util intends to revise Section 7 of emergency plan w/addition of listed wording COUNSIL, M.G. Northeast Utilities COUNBIL, M.G. Connecticut Yankee Atomic Power Co COUNBIL, M.G. Northeast Nuclear Energy Co (subs of Northeast Utilities), 84/02/03. EIRENHUT, D.G. Division of Licensing, 2pp 22217 038 24X Fiche 50-000,84/02/03,8402140135
- 8402070337 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licenses, per Generic Ltr B1-27 W/o request, entire plan will be placed in PDR.

 CRUTCHFIELD. D. Operating Reactors Branch 5. 84/02/06 COUNSIL, W C
- De pastes in FUR.

 GRUTCHRIELD.D. Operating Reactors Branch 5. 84/02/06 COUNSIL.W G.

 Connecticut Yankes Atomic Power Co COUNSIL.W G Northeast Nuclear

 Energy Co. (subs. of Northeast Utilities) 2pp. 22096:197 24X

 Fiche. 30-000:84/02/06:8402070337.
- 8402220268 Forwards IE Insp Repts 50-245/84-01 & 50-336/84-01 on 831218-840121. No violations observed ETAROSTECKI, R Division of Project & Resident Programs 84/02/06. COUNSIL, H.O. Northeast Nuclear Energy Co (subs. of Northeast Utilities) 2pp. 22337, 129 24X Fiche 50-245,84/02/06,8402220268
- --8402220273 IE Insp Repts 50-245/84-01 & 50-336/84-01 on 831218-840121 No violations identified Major areas inspected, plant operations, equipment alignments & readiness, radiation protection, physical security, fire protection & records, SMEDLOBKY, J. T. LIFINSKI, D. R., VITO, D. J. Region i, Office of Director, 84/02/01 20pp 22337.131, 24X Fichs 50-245,84/02/06,8402220268
- P. Operating license stage documents & correspondence
- B402160459 Forwards "Reactor Pressure Vessel Internals Seismic Load Assessment," per intergrated safety assessment rept (NUREO-0024) concerning SEP Topic III-6 "Seismic Design Considerations COUNBIL.H.O. Northeast Nuclear Energy Co. (subs of Northeast Utilities). COUNBIL.W.O. Northeast Utilities 84/01/23 CRUTCHFIELD.D. Operating Reactors Branch 5 3pp. 22277:041 24X Fiche: SO-245:84/01/23.8402160459.
- ---8402160462 "Reactor Pressure Vessel Internals Seismic Load Assessment LIU.A.S., HAABERG.E. General Electric Co. 83/07/31, 13pp R2277-044 24X Fiche, 50-245, 84/01/23, 8402160459
- 8402150009 Forwards revised Corporate Urganization for Nuclear Incidents procedure manual, including Rev 7 to Procedure CONI 7.01 re manager of external communications, W/o encl. COUNBIL, W. 9. Connecticut Yankee Atomic Power Co. COUNBIL, W. 9. Northeast Nuclear Energy Co (subs. of Northeast Utilities). COUNBIL, W. 9 Northeast Utilities. 84/01/30 EIBENBUT, D. 9. Division of Licensing. 2pp. 22249:217 24X Fiche: 50-000, 84/01/30, 84/02150009.
- 8402170044 Application to amend License DPR-21, changing Tech Specs re operability requirements of core spray aubsys whenever irradiated fuel is in reactor vassel.

 GDUNBIL, M. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNBIL, M. Q. Northeast Utilities. 84/01/30, GRUTCHFIELD, D. Operating Reactors Branch 5, 3pp. 22279:847. 24X Fiche: 50-245,84/01/30,8402170044.
- --8402170046 Proposed Tech Spacs changing operability requirements of core apray subsys whenever irradiated fuel is in reactor vessal.

 * Northeast Nuclear Energy Co. (subs. of Northeast Utilities)
 84/01/30 3pp. 22299:350. 24X Fiche 50-245,84/01/30,8402170044.

- B402100197 Addresses concern identified in NUREG-0824, "Integrated Plant Bafety Assessment," re electrical isolation in safety-related sys.per BEP Topic VII-1 A Probability of hot shorts of plus/minus 125-volts do or ac extremely remote GOUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W O Northeast Utilities B4/01/31 CRUTCHFIELD.D Descript Reactors Branch 5 2pp 22182 191 24 Fiche 50-245,84/01/31. B402100197
- 8402160385 Application to amend License DPR-21, incorporating changes re reactor bldg ventilation isolation Appropriate Class III license amend fee encl COUNBIL. W 0, BISHOP,R W Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL,W 0 Northeast Utilities 84/02/01 CRUICHTELD,D Departing Reactors Branch 5 3pp 22249 052 24X Fichs 50-245,84/02/01.8402160385
- ---8402160391 Proposed Tech Spec re reactor bidg ventilation isolation * Northeast Nuclear Energy Co (subs of Northeast Utilities) 84/02/01 4pp 22269 053 24X Fiche 50-245,84/02/01,8402160385
- 8402150307 Provides results of integrated evaluation in response to NUREO-0824, "Integrated Plant Safety Assessment," resulting from reviews of SEP Topics II-3 B, III-2, III-3 A & III-7 B COUNSIL.W 0, COUNSIL.W 0, Northeast Nuclear Energy Co (subs of Northeast Utilities) BISHOP,R W Northeast Utilities 64/02/02, CRUTCHFIELD, D Operating Reactors Branch 5, 4pp 22250 203 24X Fiche: 50-245,84/02/02,8402150307
- B402230103 Provides justification for NRC to refund util overpayment of 100FR170 fees re Tech Spec change on RCPB leakage monitoring COUNSIL. H G Northeast Nuclear Energy Co (subs of Northeast Utilities). COUNSIL. H G Northeast Utilities B4/02/04 HILLER, H O License Fee Management Branch 2pp 22362 132 24X Fiche 50-245, 84/02/04, 8402230103.
- B402240113 Requests NRC review of Sections 3 8 C & 4 8 C of 821122 proposed radiological ETB changes to eliminate ambiguity inherent in having two differing sets of liquid ETB CDUNSIL,N G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNSIL,N G Northeast Utilities COUNSIL,N G Northeast Utilities COUNSIL,N G Northeast Utilities Bervice Co (subs. of Northeast Utilities). B4/02/10 CRUTCHFIELD,D Operating Reactors Branch 5. 2pp 22373 361. 24X Fichs 50-245,84/02/10,8402240113
- G. Inspection reports, IE Bulletins & correspondence
- 8402020335 Forwards IE Insp Repts 50-245/83-19 & 50-336/83-27 on 831025-28 No violations noted MARTIN.T T Division of Engineering & Technical Programs 83/12/27 COUNSIL.W O Northeast Nuclear Energy Go (subs of Northeast Utilities) 2pp. 22055.015 24X Fiche.50-245,83/12/29,8402020335
- --8402020338 IE Insp Repts 50-245/83-17 & 00-336/83-27 on 631025-28 No violations noted Major areas inspected: QA program, including implementation of administrative controls for procurement & previously identified items
 NAPUDA-Q Region 1. Office of Director. CAPHTON, D L Division of Engineering & Technical Programs 63/12/20 App. 22055.017. 24X Fiche 50-245,83/12/29,8402020335
- 8312120133 IE Info Notice 84-04, "Steam Binding of Auxiliary Feedwater Pumps." Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25. Consolidated Edison Co. of New York, Inc. 120pp 22058.001 24X Fiche: 50-000,84/01/25,8312120133
- 8402080372 Forwards IE Insp Repts 50-245/83-20 & 50-336/83-20 on 831031-1104 & notice of violation.

 MARTIN.T. Division of Engineering & Technical Programs 84/01/25 COUNSIL W Q Northeast Nuclear Energy Co (subs. of Northeast Utilaties) 2pp. 22131.123. 24X Fiche: 50-245.84/01/25.8402080372
- --8402080376 Notice of violation from insp on 831031-1104.
 * Region 1, Office of Director 84/01/25 1p 22131-125 24X Fichs. 50~245, 84/01/25; 840R080372
- --8402080384 IE Insp Repts 50-245/83-20 & 50-336/83-28 on 831031-1104. Violation noted failure to review & approve new alarm setting method in Procedure CP 809A. "Liquid Waste Discharge."

 JANO, J C , BTRUCKMEYER, R , PASCIAK, W. J. Region 1, Office of Director 84/01/19 App. 22131:126. 24X Fiche 50-245,84/01/25,8402080372
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehiculan Excess Controls " Svc list encl.

 JDRDAN, E. L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co. of N York, Inc. 119pp 22114.179 24X Fiche 50-000.84/02/03.84011900

- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc IIst encl DEVOUNG,R C Director's Office, Office of Inspection and Enforcement B4702/03 Consolidated Edison Co of New York, Inc 102pp 22177
- 840222026B Forwards IE Insp Repts 50-245/B4-01 & 50-336/B4-01 on 831218-840121 No violations observed B1218-840121 No violations observed B1402/06 B140324617 Division of Project & Resident Programs 84/02/06 COUNSIL.N G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 22337 127 24X Fiche 50-245,84/02/06.8402220268
- ~-B402220273 IE Insp Repts 50-245/84-01 & 50-336/84-01 on B31218-B40121 No violations identified Hajor areas inspected plant operations, equipment alignments & readiness, radiation protection, physical security, fire protection & records SHEDLOSKY, J T , LIPINSKI, D R , VITO, D J Region 1, Office of B1/DECtor B4/02/01 20pp 22337 131 24X Fiche 50-245,84/02/06,8402220268
- 8401170041 IE Info Notice 84-09. "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R) " Syc list enc!
 - encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259 24X Fiche 50-000,84/02/13,8401190041
- 8401190037 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '"
 Svc list encl.
 JURBAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/02/14 Consolidated Edison Co of New
 York, Inc. 113pp 22365.141 24X Fiche 50-000,84/02/14,8401190039
- 8401190045 IE Info Notice 83-63. Suppl I, "Potential Failures of Westinghouse Type 9A-1 Differential Relays " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York Inc 118pp 22366 142 24X Fiche 50-000,84/02/15,8401190045
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Valve " Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/21 Consolidated Edison Co. of New York, Inc. 116pp 22366 024 24X Fiche 50-000.84/02/21.8401190062
- B401190066 IE Info Notice 84-11. "Training Program Deficiencies "
 Svc list encl
 JCRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Fost B30103) B4/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430-304 24X Fiche 50-000,84/02/24,8401190066
- 1401190067 IE Info Notice 84-12. "Failure of Boft Seat Valve Seals "
 Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Rasponse (Post 830103) B4/02/27 Consolidated Edison Co of New
 York. Inc 120pp 22431 060 24X Fiche 50-000.84/02/27,8401190067

Reportable occurrences, LERs & related correspondence

- 340214039B Requests add1 info re Part 21 rept dtd B3110B concerning waar ring failure in auxiliary feedwater pump furnished to facilities Info requested within 25 days P0TAPDVS,U Region 4. Office of Director B3/11/30 PATTY.D F Bingham-Hillamette Co ip 22221 250 24X Fiche 50-000, B3/11/30, 640214039B
- --B402140422 Supplemental Part 21 rept re wear ring failure in auxiliary feadwater pumps, per 831130 request for add1 info Wear rings will be replaced on returned units w/AIBI 420 wrought matl List of pumps in similar svc w/same wear ring enc! PATTY, D.F. Bingham-Hillamette Co. B3/12/20 Region 4, Office of Director 2pp. 22221 251 24X Fiche 50-000, B3/11/30, B402140398
 - **?030274 RO 50/245/50-336/83-04 on B31115, level of activity in jster samples exceeded control station average activity assed by refueling & maint outages which normally result n addl processing of liquid radwaste ***ROCZKA.E J Northeast Nuclear Energy Co (subs of Northeast tilities) ****MROCZKA.E J Northeast Utilities 83/12/22 URLEY.T E Region 1. Office of Director 3pp 22067:113 24X iche 50-245.83/12/22,8402030274

- DOCKET 50-247 INDIAN POINT STATION, UNIT 2
- F Security, medical, emergency & fire protection plans
- 8402130498 Responds to FOIA request for SECYs 83-268,271,278,281,299,305,306 & 307 Forwards SECY 83-271,83-278 & portions of five other SECYs as listed on App A Info partially withheld (ref Exemptions 5 & 7)
 FELTON,J M Division of Rules and Records 83/11/28 WEISS,E R Harmon & Weiss 4pp 22237 220 24X Fiche 50-000,83/11/28,80013048
- --8308050317 Responds to 830712 telcon request Util preparing employees to support staffing requirements of radiological emergency response interim plan Training scheduled for wk of 830808.

 BAYNE, J P Power Authority of the State of New York 83/07/12 KESTER, H Region 1, Office of Director ip 22237 338 24X Fiche 50-000,83/11/28,8402130498
- --8402130529 Submits add1 info to suppl 830701 ltr re valunteers for Rockland County field emergency response activities, per 830718 request O'TODLE, J D Consolidated Edison Co of New York, Inc 83/07/19 STAROBTECKI, R Division of Project & Resident Programs. 3pp 22237 335 24X Fiche 50-000,83/11/28,8402130498.
- 8402080369 Forwards IE Insp Rept 50-247/83-26 on 831201-840110. No violations noted STAROSTECKI, R Division of Project & Resident Programs B4/01/26 O'TOOLE, J D Consolidated Edison Co of New York. Inc 2pp. 22130, 203 24X Fiche: 50-247,84/01/26,8402080369
- --8402080377 IE Insp Rept 50-247/83-26 on 831201-840110,No violations noted Major areas inspected onsite activities & fire protection & mgt changes FOLEY,T , KOUTAY,P , NORRHOLM,L Region 1, Office of Director 84/01/24 12pp 22130 205 24X Fiche 50-247,84/01/26,8402080369
- 8402080161 Notifies that Town of Ossining voted on B30517 to remain in amergency response plan w/special appeal to Westchester County to establish municipal task force Discontent expressed re emergency communications sys FRATIANNI.B C Ossining, NY 84/01/30 CUCMC.M New York, State of App 22131 324 24X Fichs. 50-247, 84/01/30, 8402080161
- 8402080184 Charges Commission w/failure to fulfill responsibility of assuring public safety in event of emergency evacuation Shatters useless disabled forgotten & plan sadly deficient FLEIGHER, Z 8 West Branch Conservation Association 84/02/03. Commissioners 5pp 22128 319 24X Fichs 50-247,84/02/03, 8402080184
- 8402220095 Forwards draft "Detailed Control Room Design Review Program Plan:" per Suppl 1 to NUREO-0737 Meeting to discuss proposed actions requested O'TOOLE.J D Consolidated Edison Co. of New York, Inc. 84/02/14, EIBENHUT,D Q Division of Licensing, 1p. 22327 295 247 Ficks 50-247,84/02/14,8402220055
- --8402220059 Draft "Detailed Control Room Design Review Program Plan." * Consolidated Edison Co. of New York, Inc. 84/02/14 100pp. 22327 297. 24X Fiche 50-247.84/02/14.8402220055

Adjudicatory correspondence

- 8402070161 Comments on ASLB recommendations for evacuating school children
 RDRIGUEZ,F Parents Concerned About Indian Point. HOLT, J Public
 Interest Research Group, New York. 84/02/02 9pp. 22103.066. 24X
 Fichs. 50-247.84/02/02.8402070161
- 8402080130 Comments on recommendations of ASLB re continued operation of facility while problems util should correct remain unresolved or inconclusive ASLB urged to admit go-home plan leaves major problems w/protection of school children. RODRIGUEZ,P Parents Concerned About Indian Point HOLT, J. Public Interest Research Group, New York 84/02/02 9pp. 22132,128, 24X Ficha 30-247,84/02/02,8402080130.
- 8402070121 Forwards response to ASLB 831024 recommendations to Commission re safety issues Proposed Commission attendance at next smergency response drill would improve understanding of problems at state & local levels DELBELLO, A. B. New York, State of, 84/02/03, CHILK, S. J. Office of the Secretary of the Commission 1p. 22102; 266, 24x Fichs. 30-247, 84/02/03, 8402070121.

是一一一一大

- --B402070126 Comments responding to ASLB 831024 recommendations to Commission re-safety indust Commissioners invited to attend next emergency response drill DELBELLO, A B New York, State of 84/02/02 13pp 22102 267 24X Fichs 50-247,84/02/03,8402070121
- B4020B0184 Charges Commission w/failure to fulfill responsibility of assuring public safety in event of emergency evacuation Shelters useless disabled, forgotten & plan sadly deficient FLEIBHER, Z 8 West Branch Conservation Association 84/02/03 Commissioners 5pp. 22128 319 24X Fiche 50-247,84/02/03, B4020B0184.
- 8402080193 Comments on ASLP recommendations to Commission ABLP improperly placed burden of persuasion on plant opponents, failed to conduct thorough investigation & failed to conform conclusions w/findings of fact MDLT. J. Public Interest Research Group. New York 84/02/04 20pg 22129:209. 24X Fiche 50-247.84/02/04.8402080193
- B402070R67 Comments on ASLB recommendations re facilities Commission urged to focus on fact that serious release would be catastrophe of far greater dimensions than event at any other sites Certificate of Bvc entil HEIB9, E.R. Union of Concerned Scientists 84/02/06 Commissioners, 25pp. 22102.048 24X Ficher 50-247,84/02/06, 8402070R67.
- 8402080135 Addition to Parents Concerned About Indian Point 84020R comments on ABLE recommendations.
 HOLT, J. Public Interest Research Group, New York, 84/02/06 ip. 22132, 049 24% Ficher 50-247, 84/02/06, 8402080135.
- 8402070077 Responds to ABLB recommendations re smergency planning for facility & county. Facility should be closed due to inadequecy of emergency measures in event of major radiation release.

 KESBLER, J. Rockland Citizens for Bafe Energy. 84/02/06 PALLADING. N. J. Commissioners Opp 22160, 207 24X Fichs: 50-247, 84/02/06, 8402070077
- 8402070154 Comments on ASLB 831024 recommendations to Commission researcy planning.plant risk & comparative risk.Continued operation recommended Certificate of Svc encl.
 BRANDENBURG.B., MORGAN.C. Consolidated Edison Co. of New York, Inc. MORGAN.C. Power Authority of the State of New York, 84/02/06.65pp. 22157:223. 24X Fiche: 50-247.84/02/06.8402090154.
- B402140127 Forwards FEMA comments on ABLB decision MDDRE, J. E. Hearing Branch 1, B4/02/06 CHILK, B J. Office of the Becretary of the Commission 1p 22218, 249 24X Fiche: 50-247, 84/02/06, 8402140127

H. General correspondence

- E402130498 Responds to FOIA request for SECYs 83-268, 271, 278, 281, 299, 305, 306 & 307. Forwards SECY 83-271, 83-278 & portions of five other SECYs as listed on App A. Info partially withheld (ref Exemptions 5 & 7).
 FELTON, J. M. Division of Rules and Records 83/11/28 WEISB, E.R. Harmon & Weiss, 4pp, 22237; 220, 24X Fichs 50-000, 83/11/28, 8402130498.
- --8307060279 Requests, per County Resolution 302, immediate suspension of licenses based on FEMA rept findings. Resolution encl. PARRIS:M. Rockland County, NY. 83/05/13 Office of Nuclear Reactor Regulation, Director. 5pp 22237:315. 24X Ficha: 50-000, 83/11/28, 8402130498.
- 8402130265 Responds to 831212 request to address D Kraut concerns re possibility that plant located on fault line will explode. Plants designed to withstand DBE associated w/capable fault.
 DIRCKS, M. J. Office of the Executive Director for Operations 84/02/02. KENNEDV.E.M. Benate. Spp. 28216:203. 24X Fiche:50-003.84/02/02.8402100265.

- D Advisory Committee on Reactor Safeguerds reports & correspondence
- 8402270263 Responds to FOIA request for JC Mark 801204 memo to ACRS re hydragen burn w/igniters & documents concerning generation, combustion or control of hydrogen in reactor accidents Forwards App A documents App B documents in PDR FELTON, J M Division of Rules and Records 84/01/30 HIATT, B L Ohio Citizens for Responsible Energy 7pp 22412 051 24X Fiche 50-000,84/01/30,8402270263
- --8402270282 Summary of B00520 meeting w/natl labs.Westinghouse.NRC & utils in Bathasda.MD re hydrogen technology Meetings scheduled for B00603 & 0617 to discuss FVCS & care retention devices & containment structural responses respectively.

 QUITTSCHREIMER ACRS Advisory Committee on Reactor Safeguards B0/05/22 ACRS Advisory Committee on Reactor Bafeguards 3pp 22412 064 24X Fiche 50-000,84/01/30,8402270263
- P Operating license stage documents & correspondence
- 8402130498 Responds to FOIA request for SECYs 63-268,271,278,281,299, 305,306 & 307 Forwards SECY 83-271.83-278 & portions of five other SECYs as listed on App A Info partially withheld (ref Exemptions 5 & 7)
 FELTON, J M Division of Rules and Records 83/11/28 WE188,E R Harmon & Weiss 4pp 22237 220 24% Fiche 50-000,83/11/28, 8402130498
- --8307190353 Forwards Director's Decision 83-10 denying Rockland County 830409 2 206 request for immediate suspension of operations at facilities DEYOUND, R C Director's Office, Office of Inspection and Enforcement 83/04/29 SCHOENBERGER, I Rockland County, NY 1p 22237 320 24X Fichs 50-000,83/11/26,8402130498
- --8307190358 Director's Decision DD-83-10 denying Rockland County request for immediate suspension of operations at facilities DEYOUNG, R C Director's Dffice, Office of Inspection and Enforcement, 83/06/29 2pp 22237 321 24X Fiche 50-000,83/11/28,8402130478
- B402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILK, B J. Office of the Secretary of the Commission 83/12/14 Public Document Branch 10 22281 023 24X Fiche 50-000,83/12/14 B402160003
- --8402160043 Staff requirements memo re 830610 discussion & vote on facility order in Washington.DC CHILK.8 J Office of the Secretary of the Commission. 83/06/14 PLAINE.H H Diffice of the General Counsel. ip 22281.060 24X Fiche.50-000.83/12/14.8402160003
- --8402160368 Staff requirements memo discussing possible 821222 vote on actions re facility in Washington, DC.
 CHILK, 8 J. Office of the Secretary of the Commission 82/12/23.
 Office of the Secretary of the Commission 1p 22281: 248
 Fiche 50-000, 83/12/14, 8402160003
- --B402160446 Discusses BECY-B3-263 re Bunshine Act review of transcript of B30519 closed Commission mesting CHILK: B J Office of the Secretary of the Commission. B3/07/OB. PLAINE: H H Office of the General Counsel. ip 2281.304 24X Fichs 50-000, B3/12/14, B402160003.
- B40209040B Partial response to FOIA request for four categories of documents re NUREG-75/087 (NUREG-0800), "SRP for Review of SARs for Nuclear Plants" Review of remaining documents incomplets. Forwards App A documents re
- --8402100171 Recommends facility Tech Specs be reworded to require that licensee rept on extended maint contain justification for continuing operation & rept be submitted to Div of Reactor Licensing.

 LOW, L. D. Atomic Energy Commission 71/07/20 MORRIB.F. A. Atomic Energy Commission 2pp. 22193:026 24X Fiche 50-000.83/12/30, 8402090408.
- B312120136 Board Notification B4-011 discusses NRC use of terms "important to safety" & "safety-related" E18ENHUT.D.G. Division of Licensing B4/01/18. FALLADING, GLINBKY, ROBERTS Commissioners 72pp. 22241.008. 24X Fiche 50-000.84/01/18.8312120136

- B402090327 Requests add1 info on B11227 request for changes to Tech Specs re requirements of AVREO-0737. Items II F 1 1, "Noble Oas Effluent Monitor" & II F 1 2, "Effluent Monitoring of Radioiddines "

 VARGA, S A Operating Reactors Branch 1, B4/01/31 0/T00LE, J D Consolidated Edison Co of New York, Inc 3pp 22177 342 24X Fiche 50-247, B4/01/31, B402070327
- B402010410 Ceneric Ltr B4~D4 to all operating PWR licensees, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breats in PWR primary main loops Svc list encl EIBENHUT, D 6 Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc. 57pp 22177:087 24X Fiche 50-000,84/02/01,8402010410
- 840i190068 Board Notification 84-033 provides "Sys Interaction Program," task action plan for Unresolved Safety Issue A-17 Distribution list encl EIBENHUT,D 0 Division of Licensing 84/02/16 PALLADINO, GILINSKY, ROBERTS Commissioners Spp 22482 091 24X Fiche 50-000,84/02/16,8401190068
- 8402220066 Forwards inservice testing program summary for Jul 1984 to June 1994. Encl revised program reflects periodic updating necessary for conformance w/addends of ASME Boiler & Pressure Vessel Code. Section XI
 O'TODLE. J D Consolidated Edison Co. of New York, Inc 84/02/16 VARGA. B A Operating Reactors Branch 1 lp 22326:163 24X
 Fiche 50-247.84/02/16.8402220066
- --8402220068 Inservice testing program summary for Jul 1984 to June 1994 * Consolidated Edison Co of New York, Inc 84/02/29 242pp 22326:164 24X Fiche: 50-247.84/02/16.8402220066
- G Inspection reports: 1E Bulletins & correspondence
- 8402020182 Forwards IE Insp Rept 50-247/83-22 on 831005-07 & 11-14 & notice of violation
 MARTIN.Y T Division of Engineering & Technical Programs 83/12/2*
 D'TODLE, J D. Commonwealth Edison Co 2pp 22057 169 24X
 Fiche. 50-247. 83/12/29, 8402020182
- --8402020185 Notice of Violation from insp on 831005-07 & 11-14 * Region i, Office of Director 83/12/29 ip 22057 171 24X Fiche 50-247,83/12/29,8402020182
- --8402020190 IE Insp Rept 50-247/B3-22 on 831005-07 & 11-14 Violation noted failure to perform meaningful number of insps of routine maint activities NAPUDA, G. KENNY, T. J. Region 1. Office of Director, CAPHTON, D. L. Division of Engineering & Technical Programs 83/12/19 9pp 22097 172 24X Fiche-50-247,83/12/29,8402020182
- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feadwater Pumps " Bvc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120153
- 8402080369 Forwards IE Insp Rept 50-247/83-26 on 831201-840110 No violations noted STAROSTECKLR Division of Project & Resident Programs 84/01/26 0/TDDLE, J D. Consolidated Edison Co. of New York, Inc. 2pp. 22130:203 24X Fiche 50-247.84/01/26.8402080369
- ---8402080377 IE Insp Rept 50-247/83-26 on 831201-840110. No violations noted Major areas inspected onsite activities & fire protection & mgt changes FOLEY, T , KOLTAY, P , NORRHOLM L Region 1. Office of Director 84/01/24 12pp 22130:205 24X Fiche: 50-247,84/01/26,8402080369
- 8402070230 Notifies that operations assessment team insp will be conducted 840213-24 Insp will focus on design change & mods program & document control, procurement, maint & GC, Arrangements for unescented access requested.

 MARTIN.T T Division of Engineering & Technical Programs. 84/01/27 0'TODIE.J D Consolidate Edison Co of New York, Inc. ip. 22101:147 24X Fiche 50-247,84/01/27,8402070230.
- B401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehiculer Excess Controls." Svc list encl JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). B4/02/03 Consolidated Edison Co. of New York, Inc. 117pp. 22114-177 24X Fiche 50-000.84/02/03.8401190016
- 8401170017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers." Svc list encl DEYOUND:R C Director's Office, Office of Inspection and Enforcement 84/02/03. Consolidated Edison Co. of New York, Inc 102pp 22177 156 24% Fichs. 50-000.84/02/03.8401170017

- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Bys (100FRSD, App R) " Svc list enc!

 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259 24X Fichs 50-000,84/02/13,8401190041
- 8401190039 IE Info Notice 84-08, "10CFR30 7: 'Employee Protection '"

 Bvc list encl

 JGRDAN,E L. Division of Emergency Preparedness & Engineering

 Response (Post 830103). 84/02/14 Consolidated Edison Co of New

 York, Inc. 115pp 28365 141 248 Fiche 50-000,84/02/14,8401190039
- B401190045 IE Info Notice 83-63 Suppl 1. "Potential Failures of Westinghouse Type 8A-1 Differential Relays " 8vc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of Naw York, Inc 118pp 22366 142 24X Fiche 50-000,84/02/15,8401190045
- 8402220066 Forwards inservice testing program summary for Jul 1984 to June 1994 Encl revised program reflects periodic updating necessary for conformance w/addenda of ABME Boiler & Pressure Vessel Code. Section XI
 O'TOOLE, J D Consolidated Edison Co of New York, Inc 84/02/16. VAROA. B A Operating Reactors Branch 1 1p 22326 163 24X
 Fiche: 50-247.84/02/16.8402220066
- 8401190062 IE Info Notice 84-i0. "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl. JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co. of New York. Inc 116pp 22366 024 24X Fiche.50-000.84/02/21.8401190062
- 8401190066 IE Info Notice 84-11, "Treining Program Deficiencies," Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co. of New
 York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- R Pariodic operating reports & related correspondence
- 8402010140 Monthly operating rept for Dac 1983 W/840115 ltr.
 BLATT.M , O'TOOLE.J D Consolidated Edison Co of New York, Inc.
 83/12/31 MACDONALD, WE NRC NO Detailed Affiliation Olven 9pp
 22038 206 24% Fiche 50-247.83/12/31,8402010140
- 8 Reportable occurrences, LERs & related correspondence
- 8402270326 LER 83-042/03L-0 on 831123 during normal operation, electric heat trace circuit 468 found to have inoperable primary unit Primary heating element found to have open circuit Heating element replaced W/831223 ltr HINRICHS 6 , 0'TOOLE J D Consolidated Edison to of New York, Inc. 83/12/23 MVRLEY.T E Region 1, 0ffice of Director 2pp 22389-286 24% Fiche: 50-247, 83/12/23, 8402270326
- 8402270336 LER 83-044/031-0 on 831130 results from acoustic monitor calibr found operability criteria for acoustic valve flow monitoring sys for pressurizer code safety valves not met.

 Caused by alarm actuation point drift W/831230 ltr
 HINRICHS.0, GROSCUP.0 W Consolidated Edison Co of New York, Inc.
 83/12/30 MWRLEY.T E Region 1, Office of Director 2pp.
 22391:231 24X Fiche: 50-247,83/12/30,8402270336.
- B402140267 LER 83-046/03L-0.on B31217.during normal operation, Loop 1 T average spiked high.causing reduction in overpower, resulting in turbine run back.Caused by defective voltage to current converter Equipment repaired W/B40116 ltm MOONEY.JP. 0'TOOLE.J D Consolidated Edison Co. of New York, Inc 84/01/16 MMREY.T.E Region 1. Office of Director 2pp. 2227.166 24X Fiche' 50-247.84/01/16.8402140267
- B402030373 LER B3-047/03L-0 on 831219, during normal operation, splenoid operated valve (80V 1280) did not isolate during containment relief testing Cause not stated. Splenoid valve coil replaced & 80V tested & returned to avc W/840118 ltr HINRICHEG, 0 .0 0700LE J.D. Consolidated Edison Co. of New York, Inc. 84/01/18 MURLEY, T.E. Region 1, Office of Director 2pp. 22066.066 24X Fiche 50-247,84/01/18,8402030373

- 8402270318 LER 83-048/09L-O on 831220 during Surveillance Test PTM-46, normal supply breaker to 480-volt bus 2A opened causing rod drog trubine runback Caused by inadvertant operation of normal supply breaker Power restored W/840119 1tr MOONEY, J.P., 0'TODLE, J.D. Consolidated Edison Co. of New York, Inc. 84/01/19 MURLEY, T.E. Region 1, Office of Director 3pp 22389, 277 24x Fiche 50-247,84/01/19,8402270318
- 8402140247 LER 83-049/03L-O on 831221, during Surveillance Test PTM-12, steam generator 24 high steam flow safety injection bistable FC 449B satpoint found high Caused by setpoint drift Setpoint readjusted W/840120 ltr MODNEY, JP, 0'700LE, JD Consolidated Edison Co of New York, Inc 84/01/20 MMLREY, TE Region 1. Office of Director 2pp 22227 158 24X Fiche 50-247,84/01/20,8402140247
- 8402160382 PNO-I-84-013 on 840211 licensee commenced unscheduled outage to locate & repair steam generator 22 tube leak Plant placed in cold shutdown on 840214 Licensee plans to drain down primary sys to repair leak KIBTER: H. Region 1, Office of Director 84/02/13 ip 82269 0924X Fiche 50-847,84/02/13,8402160382

U Congressional/Executive Correspondence

- 8402010364 Further response to FOIA request for records re Ofc of Inspector & Auditor review of NRC investigation reported in NWRE0-0862 & other files concerning facilities. Forwards App B documents, App A B documents available in PDR. FELTON, J M Division of Rules and Records 83/11/22 REYNOLDS, J Center for Law in the Public Interest 4pp 22050 203. 24X Fiche 50-000,83/11/22,8402010364.
- --8402010384 Commends NRC for responsiveness in closing facilities due to emergency planning deficiencies Urges review of testimony presented at hearings Facilities should remain closed until adequate emergency plans in place QILMAN.8 A House of Rep. B3/05/25 PALLADINO.N J Cummissioners Rpp 22059:034. 24X Fiche.50-000.83/11/22, 8402010364
- E402290002 Responds to FOIA request for correspondence NRC received from Senstors J McClure, JB Johnston & P Laxalt during past 2 yrs Forwards App A documents Name of individual deleted from Documents & 8 & 9 of App A (ref FOIA Exemption 4) FELTON. J.M Division of Rules and Records, 83/11/30 KOLI, E Cable News Natwork, Inc. 6pp 22438 002 24X Fiche 50-000, 83/11/30,8402290002.
- --8402290280 Forwards NRC order re facility. Statements prepared by Chairman Palladino & Commissioners Ahearne'& Roberts also encl. Commissioners Ollinsky & Asselstine did not have prepared statements. Myo encls
 KAMMERER.C. Office of Congressionel Affairs. 83/05/05.
 SIMPSON.A. HART.G Senate. Environment & Public Works
 OTTINGER.R House of Rep., Energy & Commerce ip 22438 053
 24X Fiche. 80-000.83/11/30,8402290002.
- ---8402270282 Ack receipt of 830527 ltr re emergency preparedness plans for facility. Reply will be forwarded as soon as possible.

 KAMMERER. C Diffice of Congressional Affairs. 83/06/01

 JOHNSTON, J. B. Benate, Energy & Natural Resources 1p 22438 100
 24X Fiche. 50-000, 83/11/30, 8402270002.
- ---8402270285 Requests NRC to begin rev of regulations immediately to eliminate present abuses re vato power over emergency planning provided by NRC & FEMA regulations to state, NRC & FEMA should act forcefully to resolve crisis at facility JOHNSTON. J. B. Senate, Energy & Natural Resources, 83/05/27, PALLADING, N. J. Commissioners, 2pp 22438, 101 24X Fiche: 50-000, 83/11/30, 8402270002
- --B40B290303 Responds to B30527 ltr expressing concern re Commission contemplated shutdown of facility for emergency preparedness deficiencies. On B30610, Commission decided not take enforcement action Decision encl. W/o encl. KARMERER.C. Office of Congressional Affairs 83/06/20 JOHNSTON.J.B Benate, Energy & Natural Resources. ip. 22438-112 24X Fiche: 50-000,83/11/30,8402290002
- B40D240075 Requests evaluation of dangers involved w/corrosion of steam generator pipes & results of tests conducted to determine pipe integrity GILMAN, B.A. House of Rep. 84/02/15 PALLADING, N.J. Commissioners, 2pp. 22375; 117. 24X Fiche: 50-247, 84/02/15, 8402240075.

- V Operator Examinations
- 8402210448 Notification of Significant Licensee Meeting 84-14 on 840308 w/util at site to review suitability of simulator for future NRC operator license exams & ongoing improvements in capability through improved software HITAKER.L D Region 1. Office of Director 84/02/07 Region 1. Office of Director 2pp 22344 046 24X Fiche 50-247,84/02/07,8402210448
- DOCKET 50-249 DREADEN NUCLEAR POWER STATION, UNIT 3

 F Security, medical, emergency & fire protection plans
- 8402130191 Rev O to Emergancy Plan Implementing Procedure EOF-17, "Emergancy Operations Facility Activation Facility Log "BERLINM D Commonwealth Ediaco 83/09/23 3pp 22179 283 24X Fiche 50-000/83/09/23/8402130191
- 8402130215 Rev O to Emergency Plan Implementing Procedure EOF-18.
 "Nuclear Station Div Non-Edison Transportation Incident
 Assistance Procedure "
 * Commonwealth Edison Co 83/09/29 Spp 22204 078 24X
 Fiche 50-000,83/09/27,8402130215
- B402100137 Revised emergency plan implementing procedures, including Procedures EPIP EOF-17 re emergency operations facility activation log, EPIP CC-12 re sys power dispatcher & EPIP EOF-12 re access control W/840203 memo & receipt form MODRE, R D Commonwealth Edison CC B3/11/09 DENTON, H R. NRC No Detailed Affiliation Given 24pp 22181 288 24X Fiche 50-000,83/11/09,8402100137
- 8402130220 Rev 8 to Emergency Plan Implementing Procedure CC-12, "Sys Power Dispatcher" MODRE, R D Commonwealth Edison Co 83/11/09 11pp 22200 108 24X Fiche 50-000,83/11/09,8402130220
- B402150358 Rev 2 to Generating Station Emergency Plan Implementing Procedure EOF-12, "Access Control to Emergency Operations Facility " W/831108 itr & receipt form MODRER D Commonwealth Edison Co B3/11/30 5pp 22242 358 24% Fiche 50-000.B3/11/30.8402150358
- 8402270040 FOIA request for NRC emergency planning zone maps for facilities
 KOHLENBERGER, O Mobil Oil Corp (subs Mobil Corp.) 83/12/27, NORRY, P Office of Administration ip 22407, 937 24X
 Fichs: 50-010, 83/12/27, 8402270040
- 8402060446 Forwards Rev 9 to Emergency Plan Implementing Procedure CC-1, "Corporate Command Ctr Director "Recovery manager priority notification table encl.

 MODRER D. Commonwealth Edison Co 84/01/30. DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 22083 129 24x

 Fichs 50-000,84/01/30.8402060446
- --B402060464 Rev 9 to Emergency Plan Implementing Procedure CC-1, "Corporate Command Ctr Director," controlled copy, MDDRE.R D Commonwealth Edison Co 83/11/30, 76pp 22083 131 24X Fiche 50-000, 84/01/30, 8402060446
- 8402270034 Responds to FOIA request for NRC emergency planning zone maps for facilities. Maps may be reproduced for listed costs or examined at Region III ofc FELTON. J M Division of Rules and Records. 84/02/01 KOHLENBERGER. G Mobil 011 Corp (subs Mobil Corp). 1p 82407 336 24X Fiche. 50-249. 84/02/01. 8408270034
- 8402070202 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per 830709 ltr W/o request, entire plan will be placed in PDR CRUTCHFIELD. D. Operating Reactors Branch 5. 84/02/02 FARRAR.D L. Commonwealth Edison Co. 2pp 22100 029, 24X Fiche: 50-010,84/02/02,8402070202
- B402130467 Confirms B40215 enforcement conference at Region III ofc to discuss recent security event at Dresden & health physics events at Zion. NORELIUS, C.E. Division of Project & Resident Programs 84/02/02. REED, C. Commonwealth Edison Co. ip 22202'038. 24X Fiche: 50-000, 84/02/02, 8402130467.
- 8402100228 Forwards joint exercise rept of 830914 exercise of offsite radiological emergency preparedness plans for facilities State of IL & Grundy, Kendall & Will Counties participated KRIMM, R W. Federal Emergency Management Agency 84/02/06 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 2pp 22179-226 24X Fichs 50-010, 84 8402100228

- --8402100233 Evaluation of joint exercise rept of 830914 exercise of offsite radiological emergency preparedness plans for facilities

 + Federal Emergency Management Agency 83/12/13 35pp.
 22179 228 24X Fiche 30-010,84/02/04.8402100228
- B4022B0395 Revised emergency plan implementing procedure including Rev 1 to BZP 600-A4, "GSEP Telephone Directory" * Commonwealth Edison Co 84/02/18 dipp 22404 158 24X Fiche 50-000.04/02/18.8402B0395.

O Adjudicatory correspondence

- 8402070128 Order extending time until 840213 for Commission to act to review Director's Decision DD-83-14 & extending 831029 decision denying Environ Policy Inst request to 840213 CHILK'S J Office of the Secretary of the Commission 84/02/03 Commissioners 1p 22100 178 24X Fiche 50-000,84/02/03, 0000270198
- 8402130195 Order extending time until 840221 for Commission to act to review Director's Decision DD-83-14 CHILKS J Office of the Secretary of the Commission 84/02/13 Commissioners . ip 22245:147 24X Fiche: 50-000, 84/02/13, 0001818108

I Financial information

- B402280410 Annual Financial Rept 1983 W/B40221 ltr D'CORNOR, J , BREBEMANN.R. W Commonwealth Edison Co B3/12/31 29pg 22407 101 24X Ficht 50-000.B3/12/31.8402280410
- P. Operating license stage documents & correspondence
- 8312120029 Generic Ltr 83-39 to representatives of utils re voluntary survey of licensed operators Svc list encl. EISENHUT, D G Division of Licensing. 83/12/08 Commonwealth Edison Co 12pp 22313 004 24X Fiche 50-000,83/12/08.8312120029
- 8402010041 Summary of 840124 meeting w/util, Wester, Bechtel, Sargent & Lundy & INEL in Sethesda, MD re equipment environ qualification review. Agenda & list of specific equipment qualification deficiencies encl.

 OILBERT, R A Operating Reactors Branch 5. 84/01/30 Operating Reactors Branch 5 3App 22042 127. 24X Fiche 50-000, 84/01/30, 8402010061
- 8402140205 Forwards response to Generic Ltr 83-36.requesting licensees to submit Tech Specs or schedule for NUREG-0737 items scheduled after Bil231. All appropriate Tech Spec amend requests will be submitted by 84081%.

 BARNES.P L Commonwealth Edison Go 84/02/09. DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 22227 341. 24% Fiche 80-000.84/02/09.8602140205.
- B40221023B Concurs w/NRC opinion that requirements of TMI Items II K.3 30 & 31 met.Updated FSAR scheduled for June 1984 will document reasons small break LOCA analysis not required after addition of Exxon fuel RYBAK.B Commonwealth Edison Co. 84/02/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 22313 358 24x Fiche: 50-237,84/02/10,8402210238.
- B402240115 Application for amend to Licenses DPR-19 & DPR-25, revising Tech Specs re 125/250-volt batteries & indine limits in reactor coolant for resolution of SEP Topics VI-7. C i & XV-16

 RYBAK, B Commonwealth Edison Co 84/02/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 5pp 22373 261 24X

 Fiche: 50-237, 84/02/10, 8402240115.
- --8402240118 Proposed Tech Specs 3 9 & 4 9 rs 125/250-yolt batteries & iodine limits in reactor coolant & Commonwealth Edison Co. 84/02/10. 9pp. 22373 266 24X Fiche 50-237, 84/02/10.8402240115.
- B402160378 Forwards request for add1 info to complete Mark I containment long-term program plant-unique analysis rept structural evaluation. Response requested within 45 days of itr date CRUTCHFIELD. D Operating Reactors Branch 5 84/02/14, FARRAR.D L Commonwealth Edison Co 4pp. 22267 114. 24X Fiche 50-237,84/02/14,8402160378
 - 72170259 Forwards Amends 80,72,86 & 81 to Licenses DPR-19, DPR-25, PR-29 & DPR-30, respectively Amends approve Teth Spec hanges providing addl limiting conditions for Class IE own monitoring system (UTCHFIELD, D. Operating Reactors Brench 5 84/02/14 FARRAR, D. L. amenumeath Edison Co. Spp. 22297:112 24X Fiche: 50-000, 84/02/14, 102170259

- --B402170276 Amends 60,72,86 & 61 to Licenses DPR-19,DPR-25,DPR-29 & DPR-30, respectively, approving Tech Spec changes providing addiliniting conditions for Class IE power monitoring sys CRUTCHFIELD, D Operating Reactors Branch 5 84/02/14 28pp 22297.115 24X Fiche 50-000,84/02/14,8402170259
- 8402280345 Summary of 840215 meeting w/util.Nutech.Universal Festing Lab.Inc.TVA.PASHY.Bechtel & BNM. in Bethesda.MD to discuss issues re NDT of reactor coolant boundary welds Viewgraphs encl
 Off.BERT.R A Operating Reactors Branch 5 84/02/23 Operating Reactors Branch 5 62pp 22403 171 24X Fiche 50-249.84/02/23, 8402280345
- B402280457 Forwards Amends B1,73,87 & B2 to Licenses DPR-17, DPR-25, DPR-29 & DPR-30, respectively & safety evaluation Amends revise Tack Bapecs to require restoration of safety/relief valve inaperable position indication CRUTCHFIELD.D Operating Reactors Branch 5 84/02/24 FARRAR.D L. Commonwealth Edison Co 3pp 22406/315 24X Fiche 50-000,84/02/24, 8402280457
- --8402280492 Amends 81.73.87 & 82 to Licenses DPR-19.DPR-25.DPR-29 & DPR-30.respectively.changing Tech Specs to require restoration of all safesty/relief valve inoperable position indication prior to startup when in cold shutdown over 72 h CRUTCHFIELD.D Operating Reactors Branch 5 VABSALLO.D.B. Operating Reactors Branch 2 4402/24 16pp 22406 318. 24X Fiche 50-000.84/02/24.8402280457
- --8402280531 Safety evaluation supporting Amends 81,73,87 & 82 to Licenses DPR-19, DPR-29, DPR-29 & DPR-30, respectively * Office of Nuclear Reactor Regulation, Director. 84/02/24. 2pp 22406 334 24X Fiche: 30-000.84/02/24,8402280457
- @ Inspection reports, IE Bulletins & correspondence
- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120153
- 8402020341 Ack receipt of 840120 ltr informing NRC of steps taken to correct violations noted in IE Inep Repts 50-010/83-19, 50-237/83-29 & 50-249/83-27 NDRELIUS, C E Division of Project & Resident Programs 84/01/27, REED, C Commonwealth Edison Co 1p 22055 031 24X Fiche 50-010,84/01/27,8402020341
- --8402020345 Responds to NRC 831221 ltr re violations noted in IE Insp. Repts 50-010/83-19,50-237/83-29 & 50-249/83-27 Corrective actions operational procedures will be revised by 840401 to clarify actions needed when APRH gain drifts FARRAR: D L Commonwealth Edison Co. 84/01/20 KEPPLER, J C. Region 3, Office of Director 5pp. 22055 032 24X Fiche: 50-010,84/01/27,8402020341
- 8402170081 Forwards IE Insp Repts 50-010/83-22.50-237/83-32 k 50-249/83-30 on 83118-840119 & notice of violation SHAFER, W D Region 3. Office of Director 84/02/01 REED, C, Commonwealth Edixon Co 2pp 22300 014 24X Fiche 50-010,84/02/01. 8402170081.
- --B4021700B8 IE Insp Repts 50-010/83-22.50-237/83-32 & 50-249/83-30 on 831118-840119. Noncompliance noted isolation condenser drain valve 2-4808-301 found in closed position but not chained & locked & failurs to have amployes conduct procedure. TONGUE, T M , BTASEK, 8 , ANDERSON, C. D Region 3, Office of Birector 84/01/31 20pp. 22300 018 24X Fiche.50-010,84/02/01.
- 8402080378 Forwards info necessary to complete NRC review of IE Bulletin 80-11, "Masonry Wall Design " W/three oversize proprietary drawings Aperture cards are available in Central Files
 RYDAK.B Commonwealth Edison Co 84/02/02, DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 33pp 22160 033, 24X
 Fiche: 50-000, 84/02/02,8402080378
- --B402080385 Rev & to Procedures Manual OP-45, "Bampling & Testing of Hollow Concrete Masonry Units " LINDSTROM, R , KRAUSE, R Wiss, Janney, Elstner & Associates, Inc. 82/07/22 15pp. 22160-066 24X Fiche 50-000,84/02/02,8402080378
- --8402080374 Rev 2 to Procedures Manual OP-46. "Testing of Compression Cores Taken From Solid Block Walls " LINDSTROM,R., KRAUSE,R. Wiss, Jannay, Elstner & Associates, Inc. 82/06/24 11pp 22160 079 24X Fichs 50-000,84/02/02,8402080378

ł

- --8402080401 Rev 2 to Procedures Manual OP-47, "Determination of Mortar Type " LINDSTROM, R , KRAUSE, R Wiss, Janney, Elstner & Associates, Inc 82/06/24 38pp 22160 090 24% Fiche 50-000,84/02/02,8402080378
- --8402080409 Rev 7 to Procedures Manual OP-50, "In Situ Shear Test of Block Halls" KRAUSER, Hiss, Janney, Elsther & Associates, Inc. 82/08/11 12pp 22160 128 24X Fiche 50-000,84/02/02,8402080378
- ~~B4020B0414 "Btudies of Dresden Mortars "
 HIME, W Q . ERLIN.B Erlin, Hime Associates, Inc 82/07/30 App
 22160 140 24% Fiche 50-000,84/02/02,84020B0378
- --8402080419 "Masonry Wall Impact Tests " * Bechtel Corp 82/10/31 27pp 22160 146 24X Fichs 50-000,84/02/02,8402080378
- B401190016 IE Info Notice 84~07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50~000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers." Byo list encl DEYCMMG.R C Director's Office. Office of Inspection and Enforcement B4/02/03 Consolidated Edison Co of New York, Inc 102pp 22177
- 8402150250 Forwards IE Insp Repts 50-010/83-23, 50-237/83-33 & 50-249/83-31 on 831109-10 & 1205-20. PAPERIELLO,C J Region 3, Office of Director 84/02/03 REED,C Commonwealth Edison Co 2pp 22250 261 24X Fiche 50-010,84/02/03,8402150250
- --8402150257 IE Insp Repts 50-010/83-23,50-237/83-33 & 50-249/83-31 on 831109-10 & 1205-20 Noncompliances noted failure to provide training & failure to control entry into high radiation area PAUL, R. A. NICHOLSON, N. A., GREGER, L. R. Region 3, Office of Director. 84/02/02 11pp 22250 263 24X Fiche 50-010,84/02/03, 8402150250
- 8402070171 Notification of 840215 meeting w/util & NUTECH in Bethesda. MD to discuss data resulting from ultrasonic test inaps of RCS boundary piping OILBERT, R A. Operating Reactors Branch 5 84/02/07. CRUTCHFIELD, D Operating Reactors Branch 5 3pp 22163.124 24X Fichs 50-247.84/02/07.8402070191
- B402150210 Responds to 1E Bulletin B4-01 re insp of BMR Mark I containments currently in shubdown. No cracks found during visual insp. Through-wall crack on main vent & vent header assembly considered very unlikely Insp details and RYBACK, B. Commonwealth Edison Co. 84/02/10, KEPPLER, J G. Region 3, Office of Director Spp. 22244:118, 24X Fiche:50-237,84/02/10,8402150210.
- B401190041 IE Info Notice B4-09, "Lessons Learned" in NRC Insps of Fire Protection Bafe Shutdown Bys (10CFR50, App R) Bvc list snc1.

 URDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13. Consolidated Edison Co of New York, Inc. 124pp. 22366:259, 24X Fichs.50-000,84/02/13,8401190041
- 8401190039 IE Info Natice 84-08, "10CFR50 7; 'Employee Protection '"
 Svc list encl
 UDRDAN,E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103), 84/02/14. Consolidated Edison Co. of New
 York, Inc. 115pp 22365:141, 24X Fiche: 50-000, 84/02/14, 8401190039.
- 8401170045 IE Info Notice 83-63. Suppl 1, "Potential Failures of Westinghouse Type 8A-1 Differential Relays." 8vc list encl. JCRDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15. Consolidated Edison Co. of New York. Inc. 118pp. 22366:142. 24X Fiche.50-000.84/02/15.8401170045
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Ewitches Bet Below Menufacturer Recommended Valve," Svc list encl. JCRDAN,E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/21 Consolidated Edison Co., of New York, Inc 116pp 22366:024. 24X Fiche: 50-000,84/02/21,8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies."

 Byr list encl.

 JORDAN,E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24. Consolidated Edison Co. of New
 York, Inc. 115pp. 82430 304 84X Fichs.50-000.84/02/24.8401190066

- R Periodic operating reports & related correspondence
- B402150362 Monthly operating repts for Jan 1984 W/B40201 ltr SCHROEDER, B A , SCOTT, D J Commonwealth Edison Co B4/01/31 17pp 22242 324 24X Fiche 50-237,84/01/31,8402150362
- S Reportable occurrences, LERs & related correspondence
- 8402230347 Updates status rept on BWR pipe cracks & protection of upcoming licensee actions Insp results encl Evaluation & recommendations re interim & long-term remedial measures expected by May 1984
 DIRCKS.W J Office of the Executive Director for Operations SECY-84-009A 84/01/27 5pp 22377 047 24X Fiche 50-000, 84/01/27, 8402230347
- DOCKET 50-250 TURKEY POINT PLANT, UNIT 3

 F Security, medical, emergency & fire protection plans
- 8402010184 Forwards comments on detailed control room design review (DCRDR) program plan submittal per Suppl 1 to NUREG-0737 DCRDR summary repts submitted on B30930 & 1101 currently under review VARGA: B A Operating Reactors Branch 1 84/01/16 WILLIAMS: J W Fiche 50-000.84/01/16.8402010184
- 8402060316 Forwards revised rept re regulatory effectiveness review & vital area validation conducted at site on 830523-27 Review & comments requested by 840130 Rept withheld THOMAS, C D Standardization & Special Projects Branch 84/01/25 PARR, O D Auxiliary Systems Branch CLAYTON, H. B Protedures & 8ystems Review Branch 1p 22110 305 24X Fiche 50-250, 84/01/25, 8402060316
- 840R270399 Revised emergency plan implementing procedures, including Procedures 3100021E for 8t Lucie & 20101 for Turkey Point reduties of emergency coordinator & 1102 for Turkey Point concerning recovery manager duties. H/840221 ltr
 WILLIAMB, J, W Florida Power & Light Co 84/01/31 81pp
 22391,063 24X Fiche 50-000,84/01/31,8402270399
- 8402210168 Forwards Human Factors Engineering Branch draft SER re detailed control room design review, per Suppl 1 to NVREO-0737 Addl info needed to complete review VARQA: 8 A Operating Reactors Branch 1 84/02/02 WILLIAMS, J W Florida Power & Light Co 18pp 22346 029, 24% Fiche 50-000,84/02/02,8402210168
- --8402090330 "Evaluations of Detailed Control Room Design Reviews for St Lucie Units 1 & 2 & Turkey Point Units 3 & 4," technical evaluation rept
 # Science Applications, Inc. NRC-03-82-096 SAI-186-351-68 84/01/13. NRC No Detailed Affiliation Given 23pp 22346 047 24X Fichs 50-000,84/02/02,8402210168
- 8402270033 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per 810707 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR MCDDNALD, D 0 Operating Reactors Branch 1 84/02/07 WILLIAMS, J W Floride Power & Light Co 2pp 22407.330 24X Fiche. 50-250, 84/02/07, 8402270053
- B40RR10116 Notifies of inability to meet new schedular requirements of B11109 App R exemption Extension of date for installation of water storage tank diesel-driven fire pump & standpipes to B41231 requested.

 WILLIAMS.J.W Florida Power & Light Co B4/0R/10 EISENHUT, D G Division of Licensing 2pp. 22317:159 24X Fiche 50-250.84/02/10.8402E10116.
- B402170249 Modifies schedules provided in util 830415 ltr for safety parameter display sys & upgraded emergency operating procedures; per Suppl 1 to NUREO-0737. Procedures generation package will be submitted on 841001 HILLIAMB; J W Florida Power & Light Co 84/02/14 EISENHUT, D G Division of Licensing 2pp. 22296:150 24X Fiche 50-250, 84/02/14. B402170249
- 8402280470 Forwards license amend fees in response to 840201 ltr, covering App R exemptions, relief from inservice insprequirements & changes to ESF actuation WILLIAMS, J.W Florida Fower & Light Co 84/02/22, MILLER, W. O. License Fee Management Branch ip 22407, 072, 24X Fiche: 50-250, 84/02/22, 8402280490.

G Adjudicatory correspondence

- 8402140181 Answer opposing Ctr for Nuclear Responsibility, Inc & J Lorion 840125 amended potition to intervene Amended notices of appearances encl W/Certificate of Svc REIS, H F Florida Power & Light Co REIS, H F Steel, Hector & Davis 84/02/10 Atomic Safety and Licensing Board Panel #3pp 22230 107 24X Fiche 50-250.84/02/10,8402140181
- 8402220330 Objection to Ctr for Nuclear Responsibility 840125 discovery request & amended petition to intervene setting forth contentions for litigation Request premature Certificate of Svc encl Related correspondence YOUNG.M A Hearing Branch 4 84/02/15 3pp 22334 233 24X Fiche 50-250.84/02/15.8402220330
- 8402270006 Response supporting in partictr for Nuclear Responsibility. Inc & J Lorion 840129 amended petition to intervene Certificate of Svc ent! YOUNG M A Hearing Branch 4 84/02/17 Atomic Bafety and Licensing Board Panel 30pg 22388 101 24X Fiche 50-230,84/02/17,8402270006
- 8402290075 Response to Ctr for Nuclear Responsibility, Inc amended petition to intervene & request for 831104 hearing Petitioners should be admitted Notion for proceeding on core design should be denied W/Certificate of Svc YOUNG.M A Hearing Branch 4 84/02/17 Atomic Safety and Licensing Board Panel 30pp 22428 046 24% Fiche 50-250, 84/02/17. 8402290075
- B402270055 Forwards notice of appearance for 840228-27 prehearing conference in Homestead.FL W/o encl WOODNEAD.C P Hearing Branch 4 84/02/21 LAZO.R M . LUEBKE.E A . COLE.R F Atomic Safety and Licensing Board Panel. ip 22391 278 24X Fiche 50-250.84/02/21.8402270055

P Operating license stage documents & correspondence

- 8402280338 FOIA request for documents re proposed NSHC determination on proposed amends to DLs BELL. N Nuclear Information & Resource Service 83/12/02 Office of Administration 2pp 22430 005 24X Fiche 50-250, 83/12/02, 8402280338
- 8402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILK: 9 J Office of the Secretary of the Commission 83/12/14 Public Document Branch 1p 22281 023 24X Fiche 50-000,83/12/14,8402160003
- --8402160235 Discusses SECY-82-34 re Florida Power & Light Co CHILK, S.J. Office of the Secretary of the Commission 82/02/16 BICKWIT, L. Office of the General Counsel 1p 22281 154 24X Fiche 50-000,83/12/14,8402160003
- B402280116 Responds to FOIA request for copies of documents re proposed NSHC determination on proposed amends to OLs for facilities FELTON, J M Division of Rules and Records 84/01/05 BELL, N Nuclear Information & Resource Service 4pp 22430 001 24X Fishe 50-250,84/01/05,8402280116
- --B3071B0303 Requests FR publication of notice of consideration of issuance of amend to License DPR-43 & proposed NSHC & opportunity for hearing re-adding secondary water chemistry program
 VARCA, S.A. Operating Reactors Branch 1 B3/07/11 CLARK, R.A. Operating Reactors Branch 3 2pp 22430 036 24X Fiche 50-250, 84/01/05, 8402280116
- ---8310190334 Requests FR publication of notice of consideration of issuance of amend to Licenses DPR-31 & DPR-41 & proposed NSHC determination & opportunity for hearing on 830819 & 0909 requests to increase but channel limits VARGA: 8 A Operating Reactors Branch 1 83/10/26 MILLER, J. R. Operating Reactors Branch 2 1p 22430 038 24X Fiche 50-250.84/01/05.8402280116
- --8311300460 Forwards SER re Tech Spec changes for optimized fuel & wet annular burnable absorber rods Changes acceptable RUBENSTEIN,L S Assistant Director for Core & Plant Systems 83/1/21 LAINA6,0 C Assistant Director for Derating Reactors 16pp. 22430 057 24% Fiche 50-250.84/01/05.8402280116
- --8312020435 Forwards Core Performance Branch safety evaluation re proposed amend to Licenses DPR-31 & DPR-41 Tech Specs. Proposed changes re increase of hot channel factor acceptable RUBENSTEIN,L S. Assistant Director for Core & Plant Systems B3/11/21 LAINAS.O C Assistant Director for Operating Reactors 17pp 22430 040 24% Fiche 50-250,84/01/03,8402280116

- --8312160258 Requests FR publication of notice of issuance of Amends 98 & 92 to Licenses DPR-31 & DPR-41, respectively, changing Tech Specs to support planned fuel design mod during Cycles 9 & 10 & subsequent cycles
 VARCA.S A Operating Reactors Branch 1 83/12/09 MILLER, J R Operating Reactors Branch 3 2pp 22430 075 24X Fiche: 80-830, 84/01/05, 8402280116
- --8402280141 Submits daily highlight On 831107.Dfc of Secretary received request for hearing & patition to intervene re proposed amends to Licenses DRF-31 & DRF-41 MCDONALD.D O Operating Reactors Branch 1 83/11/08 DENTON, H, CASE, E, EISENHUT.D NRC No Detailed Affiliation Given 1p 22430 039 24% Fiche 50-250,88/01/08,8402280116
- --8402280155 Submits daily highlight Temporary restraining order filed by MH Hodder re reload amend request from util MCDONALD.0 G Operating Reactors Branch 1 83/11/30 DENTON,H, CARTER,J, EISENHUT,D NRC No Detailed Affiliation Given ip 22430 073 24X Fiche 50-250,84/01/05,8402280116
- --B402280158 Submits daily highlight On 831201, request for temporary restraining order filed by MH Hodder re reload amends. Request denied MCDONALD, D G Operating Reactors Branch 1 83/12/08 DENTON, H, CASE, E, CARTER, J NRC No Detailed Affiliation Given ip 22430 074 24X Fiche 50-250,84/01/05,8402280116
- 8402010293 Forwards request for add1 info re containment vent/purge valve operability to complete reviews of 830304 submittal re Rev 1 to Henry Pratt stress repts Info requested by 830330 VARGA: 8 A Division of Licensing 84/01/12 WILLIAMS, J W Florida Power & Light Co 5pp 22046 323 24X Fiche 50-250,84/01/12,8402010293
- 8402030517 Notification of 840208 & 09 meetings w/util in Bethesda.MD to discuss open items contained in Franklin Research Ctr technical evaluation repts re environ qualification of electrical equipment SELLS.D E Operating Reactors Branch 3 84/01/16 MILLER.J R Operating Reactors Branch 2 VAROA.B A Operating Reactors Branch 1 4pp. 22082 190 24X Fiche 50-000.84/01/16.8402030519
- B402010444 Responds to FOIA request for SECY-B3-288 & SECY-B3-443 to be placed in PDR SECY-B3-268 available in PDR SECY-B3-443 being placed in PDR Forwards SECY-B3-443 FELTON, J M Division of Rules and Records B4/01/17 YENOUSKAB, J. Newman & Holtringer Ip. 22041 272 24X Fiche 50-000, B4/01/17, B402010444
- --8402010453 Informs Commission of info obtained re flux reduction programs for pressurized thermal shock at lead plants, since 830225 interim rept (BECY 83-079)
 DIRCKB,W J Office of the Executive Director for Operations SECY-83-443 83/10/28 ijpp 22061 273 24X
 Fishe 50-000,84/01/17,8402010444
- 840217047B Requests permission to access ALARA data on 840207-10. Summary of contracts w/BNL to study occupational dose reduction encl Studies I & II involve collecting hard data on high exposure jobs & dose reduction mods VARGA: 8 A Operating Reactors Branch 1 83/01/19 WILLIAMS, J W Fiorida Power & Light Co 5pp 22305 335 24X Fichs 50-250,84/01/19,8402170478
- 8402140021 Submits corrective actions re coordination of site visits by Sandia Natl Lab as part of truck bomb threat contract Future site visits will be coordinated through Standardization & Special Projects Branch THOMAS.C O Standardization & Special Projects Branch EISENHUT.D O Division of Licensing 3pp 22251 313 24% Fiche 50~000,84/01/26.8402140021
- --8402060060 Requests NRR assistance in coordinating licensee interface necessary to accomplish RES project re truck bomb threat DAVIS.JO Office of Nuclear Material Safety & Safeguards, Director 83/12/23 DENTON, H R Office of Nuclear Reactor Regulation, Director ip. 22251 316 24X Fiche 50-000, 84/01/26, 8402140021
- --8402060050 Requests initiation of REB project re truck bomb threat analysis LASL or Sandia Lab should be tasked w/project due to availability of technical expertise & past experience DAVIS.J C. Office of Nuclear Material Safety & Safeguards, Director 83/12/12 MINOQUE, R. Office of Nuclear Regulatory Research, Director 3pp 22251-317 24X Fichs 50-000,84/01/26,8402140021

- --8402140027 Submits tentative schedule for site visits by Sandia Natl Lab to study destructive & safety consequences of explosive-laden vehicle used as weapon against nuclear facility, per truck bomb threat contract
 FLOYD, M. C. Human Factors & Safeguards Branch 84/01/13
 MCPEEK, 9. NRC No Detailed Affiliation Given 1p. 22251 320
 24% Fithe 50-000, 84/01/26, 8402140021
- --B401260470 Advises of Bandia request for site visit during wk of B40205 to study destructive & safety consequences of explosive-laden vehicle Data will be collected to identify structures & sys most vuinerable to truck-cmounted explosives FLOYD, H C Human Factors & Bafeguards Branch B4/01/10 REED, C Commonwealth Edison Co ip 22851 321 24X Fiche 50-000, B4/01/26, B402140021
- --8402140035 Discusses plans for 840131 & 0201 site visits by Bandia Natl Lab to study destructive & safety consequences of explosive-laden vehicle used as weapon against nuclear facility FLOYD, W C Human Factors & Bafeguards Branch 84/01/13 GAULDWELL, K L Florida Power & Light Co 1p 22251 322 24X Fiche 50-000.84/01/26,8402140021
- 8402030220 Provides status of planned responses to Generic Ltrs 83-10C & 83-10D.re post-TMI requirements concerning automatic trip of reactor coolant pumps (Item II K 3 5) Program completion date revised to 840501.

 WILLIAMS, J.W. Florida Power & Light Co. 84/01/30 EISENHUT, D 9 Division of Licensing 3pp. 22067 233 24X Fiche 50-250,84/01/30,8402030220
- 8402060466 Forwards revised Tech Spac Table 3 5-2, "EBF Actuation" & 3 5-4, "EBF Setpoints," per 820806.830103 & 0328 submittals re adequacy of station electric distribution voltages MILLIAMB.J.W Florida Power & Light Co 84/01/31 VAROA.8 A Operating Reactors Branch 1 2pp. 22089 117 24X Fiche:50-250.84/01/31.8402060466
- ---8402050469 Revised proposed Tech Spec Table 3 5-2, "ESF Actuation" & 3.5-4, "ESF Setpoints."

 * Florida Power & Light Co 84/01/31 5pp 22083.119 24X Fichs. 50-220.84/01/31,8402060466
- B402010410 Generic Ltr 84-04 to all operating PWR licensess, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops. Byc list encl EISENHUT.D Q Division of Licensing 84/02/01 Consolidated Edison Co. of New York, Inc 59pp 22177.087. 24X Fiche: 50-000, 84/02/01, 8402010410
- B402090558 Requests remittance of Class I & III fees for Bi0319, B31216 & 28 applications for listed amends. MILLER, W O License Fee Management Branch 84/02/01, UHRIG, R E Florida Power & Light Co 2pp 22188:340 24X Fiche: 50-250,84/02/01,8402090558
- 8402160148 Forwards pressurized thermal shock reactor vessel matls data summary, per 840117 discussion, Review & concurrence by 840801 requested. Direction of enalytical effort will be effected by results of review.

 HILLIAMS, J W Florids Power & Light Co 84/02/10 EISENHUT, D G Division of Licensing 5pp. 22276.247 24X Fichs. 50-250, 84/02/10, 8402160148.
- Q. Inspection reports, IE Bulletins & correspondence
- 8402140085 Provides supplemental response to IE Bulletin 83-06 re nonconforming metls supplied by Tube-Line Corp. Two 4-inch elbows in shield bldg ventilation sys discussed in 831206 ltr will be replaced.

 HILLIAMS.J.W. Floride Power & Light Co. 84/01/20, D'REILLY, J. P. Region 2. Office of Director. 1p. 22217:178, 24X

 Fichs: 50-000,84/01/20,8402140085.
- 8402140076 Provides supplemental response to IE Bulletin 83-06 re nonconforming matls supplied by Tube-Line Corp. Two 4-inch albows in shield bidg ventilation sys discussed in 831206 ltr will be replaced.

 WILLIAMS. J W Florids Fower & Light Co. 84/01/23 G'REILLY, J P Region 2. Office of Director. 1p. 22217.254 24X Fiche: 50-000, 84/01/23, 8402140076.
- B312120153 IE Info Notice B4-06, "Steam Binding of Auxiliary Feedwater Pumps," Svc list encl.

 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/25. Consolidated Edison Co. of New York, Inc 120pp, 22058:001. 24X Fiche 50-000,84/01/25,8312120153

- 8402060387 Forwards add1 info re masonry wall design, in response to NRC Dec 1983 request per IE Bulletin 80-11 covering arching methodology & applicability to facilities:
 WILLIAMS, J W Florida Power & Light Co 84/02/01 VARQA, S A Operating Reactors Branch 1 6pp 22086 322 24x
 Fiche 90-230, 84/02/01.8402060387
- 8402070356 Discusses IE insp on 83i018-21 & forwards notice of violation & proposed imposition of civil penalty O'REILLY, J P Region 2. Office of Director 84/02/02 WILLIMS, J W Florida Power & Light Co 4pp 22099 070 24X Fiche 50-250,84/02/02,8402070356
- --8402070360 Notice of violation & proposed imposition of civil penalty in amount of \$40,000 Violations noted failure to maintain keys to locked high radiation area under adequate administrative control to preclude unauthorized entry O'REILLY.J P Region 2, Office of Director 84/02/02 4pp 22099 074 24X Fichs 50-250,84/02/02.8402070356
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Byc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000/84/02/03.8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Bvc list encl DEYQUNO, RC Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 156 24X Fiche 30-000,84/02/03,8401190017
- B402280237 Ack receipt of 840123 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/83-36 & 50-251/83-36 LEWIS, R C Division of Project & Resident Programs 84/02/07 WILLIAMS, J W Florida Power & Light Co ip 28397 147 24X Fiche, 50-250, 84/02/07, 8402280837
- --8402280244 Responds to NRC 831216 ltr re violations noted in IE Insp. Repts 50-250/83-36 & 50-251/83-36 Corrective actions GC procurement procedures reviewed w/appropriate personnel WILLIAMB, J W Florida Power & Light Co 84/01/23 D'REILLY, J R Region 2. Office of Director 3pp 22399 148 24X Fiche 50-250,84/02/97,8402280237
- --8402280250 Forwards IE Insp Repts 50-250/83-36 & 50-251/83-36 on 831024-28 & notice of violation LEMIS.R C Division of Project & Resident Programs 83/12/16 WILLIAMS.J W Florida Power & Light Co 2pp 22399 151 24X Fiche 50-250,84/02/09,8402280237.
- --8402280252 Notice of violation from insp on 831024-28 * Region 2, Office of Director 83/12/16, ip, 22399 153 24X Fiche 50-250,84/02/09,8402280237.
- --8402280235 IE Insp Repts 30-230/83-36 & 50-251/83-36 on 831024-28 Nancompliance noted failure to provide procedures to control procurement activities BELIBLE,0 A Region 2, Office of Director, UPRIGHY,C. Division of Engineering & Operational Programs 83/12/13, 13pp. 22399 154 24X Fiche, 50-250, 84/02/09, 8402280237
- B401190041 IE Info Notice B4-09, "Lessons Learned From NRC Insps of Fire Protection Bafe Shutdown Bys (100FR50.App R) " Byc list enc1.

 JORDAN, E. L. Division of Emergency Preparadness & Engineering Response (Post B30103) B4/02/13. Consolidated Edison Co. of New York, Inc. 124pp. 28365 259. 24% Fiche 50-000.84/02/13.8401190041
- 8401190039 IE Info Notice BA-08, "10CFR80 7, 'Employee Protection.'"

 Bvc list encl.

 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103), 84/02/14. Consolidated Edison Co. of New
 York, Inc. 115pp 22365 141. 24X Fiche.50-000.84/02/14,8401190039
- B401170045 IE Info Notice B3-63, Suppl 1, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc. 118pp. 22366, 142 24X Fiche 50-000,84/02/15,8401170045
- 8401170062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Bet Below Manufacturer Recommended Value " Svc list encl. JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21. Consolidated Edison Co. of New York, Inc. 116pp. 22366 024. 24X Fichs.50-000,84/02/21,8401170062

- B4022B0490 Forwards license amend fees in response to 840201 ltr. covering App R exemptions relief from inservice insp requirements & changes to ESF actuation HILLIAMS.J H Florida Power & Light Co 84/02/22 MILLER.H O License Fee Management Branch 1p 22407 072 24X Fiche 50-250.644/02/22,84022B0490
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/24 Consolidated Edison Co of New York Inc 115pp 22430 304 24X Fiche 50-000 84/02/24, 8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals " Svc list encl

 JORDAN, E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/02/27 Consolidated Edison Co of New

 York, Inc 120pp 22431.060 24X Fiche 50-000,84/02/27,8401190067
- S. Reportable occurrences. LERs & related correspondence
- 8402010399 FOIA request for documents re incident at facilities described in Encl B.Page 2 of weekly info rept for whending 831007 BAJOU/ SHOLLY, S C Union of Concerned Scientists 83 Division of Rules and Records 1p 22042 023 Fiche 50-250,83/10/20,8402010399 83/10/20 FELTON.J M
- 8402010402 Partial response to FDIA request for documents re incident at facilities described in Encl B.Page 2 of weekly info rept for wk ending 831007 Forwards App A documents Info also available in FDR FELTON.J M Division of Rules and Records 83/11/16 SHOLLY,8 C Union of Concerned Scientists 2pp 22062 024 24X Fichs 50-250.83/11/16.8402010402
- --8402010404 Notification of 831021 IE enforcement conference w/util in Miami.FL to discuss inadvertent isolation of containment spray sys Related info encl * Region 2, Office of Director. 83/10/14 Region 2, Office of Director 12pp 22062 026 24X Fiche 50-200.83/11/16.8402010402
- --8402010407 RO 251-83-016 discovered containment spray pumps 4A & B on both manual discharge valves 4-891A & B locked in closed position investigation in progress Related info ent!
 HAYS.J K Florida Powar & Light Co 83/10/05 G/REILLY.J P
 Region 2. Office of Director lipp 22062 03B 24X
 Fiche 50-250,83/11/16.8402010402
- --8402010473 Submits daily highlights On 831004, discharge containment spray jump manual isolation valve locked in closed position Spray gump or emergency containment coder operation will provide heat removal capability.

 MCDUNALD, D 0 Derating Reactors Branch 1. B3/10/05. DENTON:H. CARTER, J, EIBENHUT, D, 0. NRC No Detailed Affillation Given 2pp 22062.057 24X Fiche.50-250.83/11/16.8402010402
- 8402170208 Second partial response to FOIA request for documents re incident described in Encl B.Page 2 of weekly info rept for wh ending 831007. App A info partially withheld (ref FOIA Exemption 6) & App B info withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 83/11/28 SHOLLY, 8 (Union of Concerned Scientists 4pp. 22319 350 24% Fichs: 50-250, 83/11/28, 8402170208 SHIDLLY, S. C.
- --- B402170212 Lists status of several items discussed in 831005 mgt IORIFORM Lists status of several items discussed in Glood mg. meeting re containment spray valve misalignment Info deleted Related info encl.
 YAEGER, N. E. Floride Power & Light Co. 83/10/07 HARRIB, K. N. Floride Power & Light Co. 95p. 22317 354 24X
 Fiche: 50-250, 83/11/28, 8402170208
- 8402220154 Responds to FOIA request that 146 LERs be placed in PDR Forwards LERs listed on app. Documents also available in FDR. Remaining LERs were either cenceled or not issued FELTON.J N Division of Rules and Records 83/11/30 JEFFERSON.O.A Affiliation Not Assigned 2pp 22380 052, 24X Fiche 50-000 83/11/30 8402220154
- 8402080019 Final response to FOIA request for documents re incident at 40200019 Final response to Fula request for documents the facilities described in weekly info rept for whe ending 831007 App A documents available in FDR. FELTON, J. M. Division of Rules and Records 83/12/08 Union of Concerned Scientists. Rpp. 22174:001. 24% Fiche: 50-250, 83/12/08, 8402080019 83/12/08 BHULLY, 8 C.
- 8402020271 EN-84-003:notice of violation & proposed imposition of civil penalty of \$40,000 will be issued approx 840202 Action based on failure to have Tech Spec implementing procedures for entry into locked high radiation area.
 FLACK.E., AXELRAD, J Director's Office, Office of Inspection and Enforcement, 84/01/30 2pp 22055 180 24X Fiche 30-250,84/01/30, page 22005018

- 8402100209 LER 84-002-00: on 840108, reactor trip occurred dus to initiation of safety injection. Caused by excessive steam usage in secondary sys & steam leakage through steam supply valves Equipment upgraded. W/840207 ltr. ROACH.P. A. WILLIAMS.J.W. Florida Power & Light Co. 84/02/07. 3pp. 22178 065. 24X Fiche 50-250,84/02/07.8402100209
- 8402130288 LER 84-001-00 on 840108, reactor tripped from approx 30% power during unit evolution hot shutdown to power operation Caused by spurious signal, resulting in closure of steam generator A feedwater flow control valve W/840207 ltr. ROACH.P A, WILLIAMS, J W Florida Power & Light Co 84/02/07 22204 072 24% Fichs 50-250,84/02/07,8402130288
- 8402130230 LER 84-003-00 on 840109, reactor trip occurred Caused by operator inadvertently tripping reactor trip breaker A w/bypass breaker A open instead of tripping reactor trip breaker B Procedure reviseed W/840208 ltr ARIAS. J. WILLIAMS. J W Florida Power & Light Co 84/02/08. 3pp. 22204 172 24x Fiche 50-250,84/02/08,8402130230.
- 8402150342 PND-II-84-012 on 840212 onsite power disruptions caused reactor trip Caused by personnel errors Unit 3 restarted. Licenses responding to media inquiries State of FL informed. ELROD.8 A , DANCE.M.C. Region 2, Office of Director 84/02/13 2pp. 22250 252. 24X Fichs 50-250.84/02/13.8402150342.
- 8402280424 Confirms 840217 enforcement conference at Region II to discuss 840212 loss of power event auxiliary feedwater pump control misalignment & mgt control of plant activities, per 840120 & 0214 telcons Proposed agenda encl 0'REILLY, JP Region 2, Office of Director 84/02/15 HILLIAMB, JW Florida Power & Light Co 2pp 22404 286 24X Fiche 50-250, 84/02/15, 8402280424
- 8402220053 PND-II-84-014 on 840216, electrical problems resulted in isolation of switchyard bus which feeds main feedwater pump, causing pump to trip & reactor trip Personnel error made while attempting repeira resulting in power disruption ELRDD, 8 A. pANCE. H C Region 2, Office of Director 84/02/16 2pp 22337:327. 24X Fiche 50-250,84/02/16,8402220053
- 8402280242 Confirms 840216 telcon re electrical sys design changes that occured between Oct 1982 & Jan 1984 & challenges to reactor protection sys Facilities will not be returned to power w/o NRC concurrence
 O'REILLY, J P Region 2, Office of Director 84/02/14,
 WILLIAMS, J W Florida Power & Light Co 1p 22379, 258 24X
 Fiche 50-250, 84/02/16, 8402280242,
- 8402270414 LER 83-026/03L-0 on 831215, util advised by const personnel of portable air compressor rolling down containment equipment hatch ramp & striking emergency diesel generator fuel oil transfer piping H/840222 ltr ARIAS. J , Williams, W Florica Power & Light Co 84/02/22 3pp, 22370 227 24% Fiche 50-250,84/02/22,8402270414
- 8402280038 LER 84-005-00 on 840125, reactor trip occurred Caused by accidental trip of 4160-volt bus feeder breaker by const worker Const stopped until administrative site procedure prepared, approved & implemented, W/840223 ltr ROACH.P A., WILLIAMS.J.W. Florida Power & Light Co 84/02/23, 3pp 22401 150 24X Fiche 50-250.84/02/23,8402280038

V Operator Examinations

- 8402280237 Ack receipt of 840123 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/83-36 & 50-251/83-36 50-201763-36 LENIB.R.C Division of Project & Resident Programs HILLIAMS.J W Florida Power & Light Co. 1p 22399 Fiche 50-250,84/02/09.8402280237. 22399, 147
- --8402280255 IE Insp Repts 50-250/83-36 & 50-251/83-36 on 831024-28
 Noncompliance noted failure to provide procedures to control
 procurement activities.
 BELISLE, O A Region 2, Office of Director. UPRIGHT, C. Divisio
 of Engineering & Operational Programs 83/12/13 13pp.
 22399-154 24X Fiche 50-250,84/02/09,8402280237 UPRIGHT, C. Division

DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

- F Security, medical, emergency & fire protection plans
- 8402010184 Forwards comments on detailed control room design review 402010194 Forwards comments on detailed control room design review (DCRDR) program plan submittal per Buppl 1 to NUREG-0737, DCRDR summary repts submitted on 830930 & 1101 currently under review VARQA, & A Operating Reactors Branch 1 84/01/16, WILLIAMS, J.W. Florida Fower & Light Co. 10pp. 22048 033 24X Fiche: 50-000, 84/01/16, 8402010184

- 8402060316 Forwards revised rept re regulatory effectiveness review & vital area validation conducted at site on 830323-27 Raview & comments requested by 840130 Rept withheld THOMAS.C O Standardization & Special Projects Branch 84/01/25 PARR.O.D Auxiliary Systems Branch CLAYTON.H B Procedures & Systems Review Branch 1p 22110 305 24X Fiche 50-250.84/01/25.8402060316.
- 8402270399 Revised emergency plan implementing procedures including Procedures 3100021E for St Lucie & 20101 for Turkey Point reduties of emergency coordinator & 1102 for Turkey Point concerning recovery manager duties W/840221 ltr WILLIAMS. J W Florida Power & Light Co 84/01/31 81pp 22391 063 24X Fiche 30-000,84/01/31,8402270399
- 8402210168 Forwards Human Factors Engineering Branch draft SER re detailed control room design review.per Suppl 1 to NUREO-0737 Add1 info needed to complete review VARGA.8.A Operating Reactors Branch 1 84/02/02 WILLIAMS, J W Fibrida Power & Light Co 18pp 22346 027 24X Fichs 30-000,84/02/02,8402210168
- ---B402090330 "Evaluations of Detailed Control Room Design Reviews for St Lucie Units 1 & 2 & Turkey Point Units 3 & 4," technical evaluation rept

 4 Science Applications, Inc NRC-03-82-096, BAI-186-351-68, B4/01/13 NRC No Detailed Affiliation Given 23pp 22346 047 24% Fiche, 50-000, 84/02/02, 8402210168
- 8402270033 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per 810709 Generic Ltr 81-27. W/o request, entire plan will be placed in PDR MCDONALD, D. 0. Operating Reactors Branch 1. 84/02/07. WILLIAMS, J W Florida Power & Light Co. 2pp. 22407 330 24% Fiche'50-250,84/02/07,8402270053
- 8402170249 Modifies schedules provided in util 830415 ltr for safety parameter display sys & upgraded emergency operating procedures, per Suppl 1 to NUREO-0737, Procedures generation package will be submitted on 841001.

 HILLIAMS, J. M. Florida Power & Light Co 84/02/14 EISENHUT, D G Division of Licensing 2pp 22276/150 24X Fiche 50-250,84/02/14,8402170249.
- B402280490 Forwards license amend fees in response to 840201 ltr. covering App R exemptions relief from inservice insprequirements & changes to ESF actuation HILLIAMS.J.W. Florida Power & Light Co 84/02/22 MILLER.W D. License Fee Management Branch. 1p 22407.072. 24X Fichs: 50-250,84/02/22,8402280490.

9. Adjudicatory correspondence

- 8402140181 Answer opposing Ctr for Nucléar Responsibility, Inc & J Lorion 840125 amended patition to intervene. Amended notices of appearances encl. W/Certificate of Bvc REIB, H.F. Florida Power & Light Co REIB, H.F. Steel, Hector & Davis. 84/02/10. Atomic Bafety and Licensing Board Panel 55pp 22230:107. 24X Fichs. 50-250, 84/02/10, 8402140181.
- 8402220330 Objection to Gtr for Nuclear Responsibility 840125 discovery request & amended petition to intervene setting forth contentions for litigation Request premature. Certificate of Byc encl. Related correspondence YOUNG, M A Hearing Branch 4 84/02/15 3pp. 22334 233. 24X Fiche: 50-250,84/02/15,8402280330.
- 8402270006 Response supporting, in part, Ctr for Nuclear Responsibility, Inc & J. Lorion 840125 emended patition to intervene Certificate of Syc encl YOUNG, M.A. Hearing Branch 4 84/02/17, Atomic Safety and Licensing Board Panel. 30pp 82388.101. 24X Ficher 50-250,84/02/17,8402270006,
- B402290075 Response to Ctr for Nuclear Responsibility, Inc amended petition to intervene & request for B31104 hearing Petitioners should be admitted Motion for proceeding on core design should be denied W/Certificate of Bvc.
 YOUNG, M.A. Hearing Branch 4, 84/02/17 Atomic Bafety and Licensing Board Panel 30pp. 22428:044, 24X Fiche: 50-250, 84/02/17, 8402290075
- 8402270035 Forwards notice of appearance for 840228-29 prehearing conference in Homestead, FL, W/o encl.

 MODDMEAD, C.P. Hearing Branch 4 84/02/21. LAZO, R.M., LUEBKE, E A., COLE, R.F. Atomic 84feby and Licensing Board Panel ip 22391, 278
 24X Fiche: 50-250, 84/02/21, 8402270055.

- P Operating license stage documents & correspondence
- B4022B033B FDIA request for documents re proposed NSHC determination on proposed amends to OLs
 BELL.N Nuclear Information & Resource Service 83/12/02 Office of Administration 2pp 22430 005 24X Fichs 50-250,83/12/02.
 BA022B033B
- 8402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILK.8 J Office of the Secretary of the Commission 83/12/14 Public Document Branch 1p 22881 023 24X Fiche 50-000,83/12/14.8402160003
- --8402160235 Discusses SECY-B2-34 re Florida Power & Light Co-CHILK, B J Office of the Secretary of the Commission 62/02/16 BICKHIT, L Office of the General Counsel 1p 22281 154 24X Fiche 50-000, B3/12/14, 8402160003
- B40R2B0116 Responds to FOIA request for copies of documents re proposed NBHC determination on proposed amends to OLs for facilities FELTON, J M Division of Rules and Records B4/01/05 BELL, N Nuclear Information & Resource Service 4pp 22430 001 24X Fiche 50-250,84/01/05.8402280116
- --B3071B0303 Requests FR publication of notice of consideration of issuance of amend to License DPR-43 & proposed NSHC & opportunity for hearing re-adding secondary water chemistry program
 VAROA, B A Operating Reactors Branch 1 B3/07/11 CLARK, R A Operating Reactors Branch 3 2pp 22430:036 24X Fichs 50-250, B4/01/05, B4022B0116
- --B310190334 Requests FR publication of notice of consideration of issuance of amend to Licensos DPR-31 & DPR-41 & proposed NSHC determination & apportunity for hearing on 830817 & 0709 requests to increase hot channel limits VARGA: 8 A Operating Reactors Branch 1 83/10/26 MILLER, J R Operating Reactors Branch 1 83/10/26 MILLER, J R Fiche 50-250, 84/01/05, 8402280116
- --831300460 Forwards SER re Tech Spec changes for uptimized fuel & wet annular burnable absorber rods Changes acceptable RUBENSTEIN.L B Assistant Director for Core & Plant Systems 83/11/21 LAIMAG, 0 C. Assistant Director for Operating Reactors 16pp. 22430,057 24X Fiche 50-250,84/01/05,8402280116
- --8312020436 Forwards Core Performance Branch safety evaluation reproposed amend to Licenses DPR-31 & DPR-41 Tech Specs.
 Proposed changes re increase of hot channel factor acceptable
 RUBENBTEIN, L 8 Assistant Director for Core & Plant Bystems
 83/11/21 LAINAS, C C. Assistant Director for Operating Reactors
 17pp. 22430.040, 24X Fiche 50-250/84/01/05.8402280116
- --8312160258 Requests FR publication of notice of issuance of Amends 98 & 92 to Licenses DPR-31 & DPR-41, respectively, changing Tech Epecs to support planned fuel design mod during Cycles 9 & 10 & subsequent cycles VARQA: B A Operating Reactors Branch 1 83/12/09 MILLER, J. R Operating Reactors Branch 3, 2pp 22430 075 24X Fiche 50-250, 84/01/05, 8402280116.
- --8402280141 Bubmits daily highlight On 831107,0fc of Becretary received request for hearing & patition to intervene re proposed amends to Liceness DPR-31 & DPR-41.

 HGDONALD, D. Q. Operating Reactors Branch 1 83/11/08 DENTON, H. GASE, E., EIBENHUT, D. NRC No Detailed Affiliation Given. 1p. 22430 039. 24X Fiche: 50-250,84/01/05,8402280116
- --B402280135 Bubmits daily highlight Temporary restraining order filed by MK Hodder re reload amend request from util.
 MCDDNALD-D.0 Operating Reactors Branch 1, 83/11/30 DENTDN.H . CARTER.J . EISEMHUT, D NRC No Detailed Affiliation Given. 1p. 22430.073 PAX Fiche 50-250.84/01/05.8402280116.
- ---B408280158 Submits daily highlight On B31201, request for temporary restraining order filed by MH Hodder re reload amends.

 Request denied

 MCDONALD, D. Q. Operating Reactors Branch i B3/12/08, DENTON, H, CABCE, C, CARTER, J NRC No Detailed Affiliation Given ip. 22430:074 24X Fichs. 50-250, 84/01/05, 8402280116.
- 8402010273 Forwards request for add1 info re containment vent/purge valve operability to complete reviews of 830304 submittal re Rev 1 to Henry Fratt stress repts. Info requested by 830330. VAROA, B A Division of Licensing, 84/01/12, WILLIAMS, J.W. F1--4-Power & Light Co. Spp. 22046:323. 24X Fiche: 50-250, 84/01/13 8402010293.

- B402030519 Notification of B40208 & 09 meetings w/util in Bethesda.MD to discuss open items contained in Franklin Research Ctr technical evaluation repts re environ qualification of electrical equigment SELLS.D E Operating Reactors Branch 3 84/01/16 MILLER, J R Operating Reactors Branch 3 VAROA.B A Operating Reactors Branch 1 4pp 22082 190 24X Fiche 50-000,84/01/16.8402030519
- 8402010444 Responds to FDIA request for SECY-83-288 & SECY-83-443 to be placed in PDR SECY-83-288 available in PDR SECY-83-443 being placed in PDR Forwards SECY-83-443 FELTON.J M Division of Rules and Records 84/01/17 YENOUSKAS.J Newman & Holtringer 1p 22061 272 24x Fiche 50-000, 84/01/17, 8402010444
- --BA02010453 Informs Commission of info obtained re flux reduction programs for pressurized thermal shock at lead plants, since 830825 interim rept (SECY 83-079)
 DIRCKS,W J Office of the Executive Director for Operations SECY-83-443 B3/10/28 lipp 22061 273 24X
 Fiche 50-000,84/01/17,8402010444
- 840217047B Requests permission to access ALARA data on 840207-10 Summary of contracts w/BNL to study occupational dose reduction entl Studies I & II involve collecting hard data on high exposure jobs & dose reduction mods VARGA: S A Operating Reactors Branch 1 83/01/19 WILLIAMS, J. W Florida Power & Light Co. 5pp. 22305, 335 24X Fiche: 50-250.84/01/19, 8402170478
- 8402140021 Submits corrective actions re coordination of site visits by Sandia Natl Lab as part of truck bomb threat contract Future site visits will be coordinated through Standardization & Special Projects Branch
 THOMAS.C D Standardization & Special Projects Branch
 EISENHUT.D Q Division of Licensing 3pp 22251 313 24X
 Fiche 50-000.84/01/26,8402140021
- --8402140027 Submits tentative schedule for site visits by Bandia Natl Lab to study destructive & safety consequences of explosive-laden vehicle used as weapon against nuclear facility, per truck bomb threat contract FLOYD, W C Human Factors & Bafeguards Branch 84/01/13.

 MCPEEX. 0 NRC No Detailed Affiliation Given 1p 22251 320 24X Fiche 50-000.84/01/26.8402140021
- --8402140035 Discusses plans for 840131 & 0201 site visits by Bandia Natl Lab to study destructive & safety consequences of orplosive-laden vehicle used as weapon against nuclear facility FLDYD.W C Human Factors & Safeguards Branch 84/01/13 CAULDWELL.K L Florida Power & Light Co ip 22251 322 24X Fiche 50-000,84/01/26.8402140021
- B402030220 Provides status of planned responses to Generic Ltrs 83-10C & 83-10D) re post-TMI requirements concerning automatic trip of reactor collent pumps (1tem II K 3 5). Program completion data revised to 840301 HILLIAMS, J W Florida Power & Light Co 84/01/30 EISENHUT, D 0 Division of Licensing 3pp 22067 233 24X Fiche. 50-250, 84/01/30, 8402030220
- 8402040466 Forwards revised Tech Spec Table 3 5-2. "ESF Actuation" & 3 5-4. "ESF Setpoints." per 820806.030103 & 0325 submittals re adequacy of station electric distribution voltages WILLIAMS.J N Florida Power & Light Co 84/01/31 VARQA.8 A Operating Reactors Branch 1 2pp 22083 117 24% Fiche 50-250.84/01/31.8402040464
- -84020A0469 Revised proposed Tech Spec Table 3 5-2, "ESF Actuation" & 3 5-4, "ESF Retpoints "

 * Florida Power & Light Co 84/01/31 5pp 22083 119 24x
 Fiche 30-250,84/01/31,8402060466
- i402010410 Generic Ltr 84-04 to all operating PWR licensees, CP holders & applicants for CPs re safety evaluation of Hestinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops. Byc list encl EIEENHUT, D 9 Division of Licensing 84/02/01 Consolidated EIGENHUT, D 9 Division of Licensing 84/02/01 Consolidated EIGENHUT, D 84/02/01, B402010410.
- 8402090558 Requests remittance of Class I & III fees for 810319, 831216 & 28 applications for listed amends HILLER, W D License Fee Management Branch 84/02/01 UHRIG, R, E Florida Power & Light Co Zpp 22188 360 24X Fiche 50-250, 84/02/01, 8402090558

- 8402160148 Forwards pressurized thermal shock reactor vessel matls data summary, per 840119 discussion Review & concurrance by 840501 requested Direction of analytical effort will be effected by results of review MILLIAMS.J W Florida Power & Light Co 84/02/10 EISENHUT.D 9 Division of Licensing 6pp 22276 247 24X Fiche 50-250,84/02/10,8402160148
- G Inspection reports, IE Bulletins & correspondence
- 8402140085 Provides supplemental response to IE Bulletin 83-06 re nonconforming matls supplied by Tube-Line Corp Two 4-inch albows in shield bidg ventilation sys discussed in 831206 lit will be replaced WILLIAMS.J W Florida Power & Light Co 84/01/20 O'REILLY,J,P Region 2. Office of Director ip 22217,178 24X Fiche 50-000.84/01/20.8402140085
- 8402140076 Provides supplemental response to IE Bulletin 83-06 re nonconforming matts supplied by Tube-Line Corp Two 4-inch elbows in shield bldg ventilation sys discussed in 831206 ltr will be replaced HILLIAMB, J W Florida Power & Light Co 84/01/23 C/REILLY, J P. Region 2, Office of Director 1p 22217 254 24X Fiche 50-000,84/01/23,8402140076
- B312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps" Byc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/25 Consolidated Edison Co. of New York, Inc. 120pp 22058 001 24% Fiche 50-000,84/01/25,8312120153
- 8402060387 Forwards add1 info re masonry wall design in response to NRC Dec 1983 request per IE Bulletin 80-11 covering arching methodology & applicability to facilities WILLIAMS.JW Florida Power & Light Co 84/02/01 VAROA.8 A Operating Reactors Branch 1 6pp 22086 322 24X Fiche 50-250,84/02/01,8402060387
- B402070334 Discusses IE insp on B31018-21 & forwards notice of violation & proposed imposition of civil penalty O'REILLY, J P Region 2: Office of Director 84/02/02 HILLIAMB, J W Florida Power & Light Co 4pp 22099 070, 24X Fiche 50-250,84/02/02,8402070354
- --8402070360 Notice of violation & proposed imposition of civil penalty in amount of \$40,000 Violations noted failure to maintain keys to locked high radiation area under adequate administrative control to preclude unauthorized entry O'REILLY, JP Region 2, Office of Director 84/02/02 4pp 22097 074 24X Fiche 50-250.84/02/02,8402070356
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fichs 50-000,84/02/03,8401190016
- B401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEYDUNG, RC Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 156 24X Fiche 50-000,84/02/03,8401190017.
- 8402280237 Ack receipt of 840123 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/83-36 & 50-251/83-36 LEHIS.R.C Division of Project & Resident Programs 84/02/09. WILLIAMS.J W Florida Power & Light Co 1p. 22399 147 24X Fichs 50-250.84/02/09.8402280237.
- --8402280244 Responds to NRC 831216 ltr re violations noted in IE Insp. Repts 30-250/83-36 & 50-251/83-36 Corrective actions, GC procurement procedures reviewed drappropriate personnel, HILLIAMS, J.W. Florida Power & Light Co. 84/01/23. D'REILLY, J.R. Region 2, Office of Director 3pp. 22379, 148 24X Fiche 50-250,84/02/09,8402280237
- --8402280250 Forwards IE Insp Repts 50-250/83-36 & 50-251/83-36 on 831024-28 & notice of violation, LEMIS.R.C Division of Project & Resident Programs. 83/12/16. WILLIAMS.J W. Florida Power & Light Co 2pp 22399 151. 24X Fi
- --8402280252 Notice of violation from insp on 831024-28 * Region 2, Dffice of Director 83/12/16 ip 22399-153 24X Fiche 50-250,84/02/09,8402280237

- --8402280255 IE Insp Repts 50-250/83-36 & 50-251/83-36 on 831024-28
 Noncompliance noted failure to provide procedures to control
 procurement activities
 BELISLE, G A Region 2, Office of Director UPRIGHT, C Division
 of Engineering & Operational Programs 83/12/13 13pp
 22399.134 24X Fichs 50-250,84/02/09,8402280237
- 3401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Bafe Shutdown Sys (10CFR50,App R) " Byc list
- enci. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 630103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365 259 24X Fiche 50-000,84/02/13,8401190041
- 9401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '" Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/14 Consolidated Edison Co of New York, Inc 115pp 22365 141 24X Fiche 80-000,84/02/14,8401170039
- 3401170045 IE Info Notice 83-63.8uppl 1, "Potential Failures of Wastinghouse Type 8A-1 Differential Relays " 8vc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc 118pp 22366 142 24X Fiche 50-000.84/02/15,8401170045
- 8401170062 IE Info Notice 84-10, "Motor-Operated Valve Torque Buitches Set Below Manufacturer Recommended Value " Evc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000,84/02/21,8401170062
- '402280490 Forwards license amend fees in response to 840201 ltr, covering App R exemptions, relief from inservice insprequirements & changes to EBF actuation
 WILLIAMB, J W Florida Power & Light Co 84/02/22 MILLER, W O
 License Fee Management Branch 1p 22407 072 24X
 Fiche 50-250,84/02/22,8402280490
- 401190066 IE Info Notice 84-11, "Training Program Deficiencies " Syc list encl. JURDAN,E.L. Division of Emergency Preparadness & Enginearing Response (Post 830103) 84/02/24 Consolidated Edison Co. of New York, Inc. 115pp 22430 304 24X Ficha 50-000,84/02/24,8401190066
- 40ii900A7 IE Info Notice 84-i2, "Failure of Boft Seat Valve Seals " Byc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830i03). 84/02/27. Consolidated Edison Co of New York, Inc. 120pp 22431:060 24X Fiche 50-000,84/02/27,8401190067
- . Reportable occurrences, LERs & related correspondence
- 402010407 RD 251-83-016. discovered containment spray pumps 4A & B on both manual discharge valves 4-891A & B locked in closed position investigation in progress Related info encl HAYBLJ. R Floride Power & Light Co 83/10/05. O'REILLY, J P. Region 2. Office of Director 11pp. 28062:038. 24X Fiche 30-280,83/11/16.842010402
- 402010399 FOIA request for documents re incident at facilities described in Encl 8,Page 2 of weekly info rept for wk ending 831007 B31007 SHOLLY,8 C Union of Concerned Scientists 83/10/20 FELTO
- SHOLLY.8 C Union of Concerned Scientists 83/10/20 FELTON, J M. Division of Rules and Records 1p. 22042, 023 24X Fiche. 50-250, 83/10/20, 8402010399.
- 102010402 Partial response to FDIA request for documents re incident at facilities described in Encl B.Page 2 of weekly info rept for wk ending 831007 Forwards App A documents. Info also available in PDR. FELTON. J.M. Division of Rules and Records. 83/11/16. BHOLLY, S C Union of Concerned Scientists. 2pp. 22062 024. 24X Fiche 50-250,83/11/16,8402010402
- -8402010404 Notification of 831021 IE enforcement conference w/util in Miami.FL to discuss inadvertent isolation of containment spray sys Related info encl a Region 2, Office of Director. 83/10/14 Region 2, Office of Director. 12pp 22062 026. 24X Fiche: 50-250.83/11/16,8402010402
- -8402010493 Submits daily highlights, Dn 831004, discharge containment spray pump manual isolation valve locked in closed position Spray pump or emergency containment cooler operation will provide heat removal capability MCDDNALD, D G. Operating Reactors Branch i 83/10/05. DENTON, H, CARTER, J. EIGENHUT, D. G. NRC No Detailed Affiliation Given 2pp 22062-057. 24X Ficha 50-250.83/11/16,8402010402.

- B402170208 Becond partial response to FOIA request for documents re incident described in Encl B.Page 2 of weekly info rept for wk ending 831007 App A info partially withheld (ref FOIA Exemption 6) & App B info withheld (ref FOIA Exemption 5) FELTON. J M Division of Rules and Records 83/11/28 SHOLLY.S (Union of Concerned Scientists 4pp 22319 350 24x Fiche 50-230.83/11/28,8402170208
- ---8402170212 Lists status of several items discussed in B31005 mgt meeting re containment spray valve misalignment Info deleted Related info encl YAEGER. H E Florida Power & Light Co 83/10/07 HARRIS, K N Florida Power & Light Co 9pp 22319 354 24X Fiche 50-250,83/11/28,8402170208
- 8408220134 Responds to FOIA request that 146 LERs be placed in PDR Forwards LERs listed on app Documents also available in PDR Remaining LERs were either canceled or not issued FELTON.J M Division of Rules and Records 83/11/30 JEFFERSON, 6 A Affiliation Not Assigned 2pp 22380 052 24X Fiche 50-000,83/11/30,8402220154
- 8402080019 Final response to FDIA request for documents re incident at facilities described in weekly info rept for wk ending 831007 App A documents available in PDR FELTON, J M Division of Rules and Records 83/12/08 SHOLLY, S C Union of Concerned Scientists 2pp 22/74 001 24% Fiche 80-250,83/12/08,8402080019
- 8402020291 EN-84-003 notice of violation & proposed imposition of civil penalty of \$40,000 will be issued approx B40202 Action based on failure to have Tech Spec implementing procedures for entry into locked high rediation area FLACK.E. AXELRAD.J Director's Office. Office of Inspection and Enforcement 84/01/30 2pp 22055 180 24X Fiche 50-250.84/01/30.240020009
- 8402130342 PNO-II-84-012 on 840212, onsite power disruptions caused reactor trip Caused by personnel errors Unit 3 restarted Licenses responding to media inquiries State of FL informed ELROD, S A., DANCS, H C Region 2, Office of Director 84/02/13 2pp 22250 252 24% Fiche 50-250,84/02/13,8402150342
- 8402220053 PND-II-84-014 on 840216, electrical problems resulted in isolation of switchyard bus which feeds main feedwater pump. causing pump to trip & reactor trip Personnel error made white attempting repairs resulting in power disruption ELROD, 8 A. DANCE, H C Region 2, Office of Director 84/02/16 2pp 22337 327, 24X Fiche 50-250,84/02/16,8402220053
- B402280242 Confirms B40216 telcon re electrical sys design changes that occured between Oct 1982 & Jan 1984 & challenges to reactor protection sys Facilities will not be returned to power w/o NRC concurrence.

 O'RETLLY, J P. Region 2. Office of Director B4/02/16
 WILLIAMS, J W Florida Power & Light Co 1p 22397 258 24X
 Fiche, 50-250, B4/02/16, 8402280242
- V Operator Examinations
- 8402280237 Ack receipt of 840123 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/83-36 & 50-251/83-36 LEMIS.R C Division of Project & Resident Programs 84/02/09 WILLIAMS,J W Florida Power & Light Co ip 22399 147 24X Fiche 50-250,84/02/09,8402280237.
- ---B402280255 IE Insp Repts 50-250/83-34 & 50-251/83-34 on B31024-28 Noncompliance noted, failure to provide procedures to control procurement activities BELIELE, Q A Region 2, Office of Director. B3/12/13 13pp 22399, 154. 24X Fiche, 50-250, 84/02/09, 8402280237
- DOCKET 50-254 QUAD CITIES STATION, UNIT 1
- F. Security, medical, emergency & fire protection plans
- B402100221 Rev 4 to emergency plan annex H/840113 ltr MDORE:R D Commonwealth Edison Co 83/04/30 DENTON, H R of Nuclear Reactor Regulation, Director 6ipp. 22178 OBI Fichs 50-254:83/04/30:8402100221. Office
- 8402130191 Rev O to Emergency Plan Implementing Procedure EDF-17, "Emergency Operations Facility Activation Facility Log." BERLIN, M D Commonwealth Edison Co 83/09/23 3pp 22199 283 24X Fichs 50-000 83/09/23 8402130191

- 8402130215 Rev O to Emergency Plan Implementing Procedure EOF-18, "Nuclear Station Div Non-Edison Transportation Incident Assistance Procedure" Commonwealth Edison Co. 83/09/29 Spp. 22204 078 24X Fiche. 50-000, 83/09/27, 8402130215
- 8402100137 Revised emergency plan implementing procedures, including Procedures EPIP EOF-17 re emergency operations facility activation log, EPIP CC-12 re sus power dispatcher & EPIP EOF-12 re access control W/840203 memo & receipt form MUDRE: R D Commonwealth Edison CO 83/11/09, DENTON, H R NRC No Detailed Affiliation Given. 24pp 22181 288 24X Fiche 50-000, 83/11/09, 8402100137
- 8402130220 Rev 8 to Emergency Plan Implementing Procedure CC-12, "Sys Power Dispatcher" MDDRE,R D Commonwealth Edison Co 83/11/09 11pp 22200 108 24X Fiche 50-000,83/11/09,8402130220
- 8402150358 Rev 2 to Generating Station Emergency Plan Implementing Procedure EOF-12. "Access Control to Emergency Operations Facility " #/831108 ltm & receipt form MODRE.R D . COMMONWEALTH Edison Co 63/11/30 5pp 22242 358 24X Fiche 50-000.83/11/30.8402150358
- B402140118 Rev 4 to "Amend of Generating Stations Emergency Plan Book MODRE R D Commonwealth Edison Co 84/01/13. 62pp 22219:070 24% Fiche 50-254 84/01/13,8402140118
- 84020&044& Forwards Rev 9 to Emergency Plan Implementing Procedure CC-1, "Corporate Command Ctr Director" Recovery manager priority notification table encl HODRE.R D Commonwealth Edison Co 84/01/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22083 129 24X Fiche 50-000.84/01/30,84020&044&
- --8402060464 Rev 7 to Emergency Plan Implementing Procedure CC-1, "Corporate Command Ctr Director," controlled copy HODER, R D Commonwealth Edison Co 83/11/30 76pp 22083 131 24X Fiche, 50-000, 84/01/30, 8402060446
- B402130377 Discusses FEMA B30702 itr & 0512 evaluations of offsite emergency preparadness exercise for facility Reasonable assurance exhibited that state & local govts have adequate capability to protect public PAPERIELLD.C J. Region 3, Office of Director, 84/02/07. REED.C Commonwealth Edison Co. 2pp 22197 001, 24X Fiche 50-254,84/02/07,8402130377
- 8402280395 Revised emergency plan implementing procedure, including Rev 1 to BZP 600-A4, "GBEP Telephone Directory" * Commonwealth Edison Co. 84/02/18 61pp 22404:158 24X Fiche 50-000,84/02/18,8402280395

I Financial Information

- 402280410 Annual Financial Rept 1983 W/840221 ltr O'CONNOR.J J Commonwealth Edison Co 83/12/31 29pp. 22407 101 24X Fiche 50-000.83/12/31.6402280410
- . Operating license stage documents & correspondence
- B402140021 Submits corrective actions re coordination of site visits by Sandia Netl Lab as part of truck bomb threat contract Future site visits will be coordinated through Standardization & Special Projects Branch THOMAS.C O Standardization & Special Projects Branch B4/01/26 EISEMHUT.D G Division of Licensing Spp. 22251.313 24X Fiche 50-000.84/01/26.8402140021
- --B402140027 Submits tentative schedule for site visite by Bandia Natl Lab to study destructive & safety consequences of explosive-laden vehicle used as weapon against nuclear facility, per truck bomb threat contract.
 FE.070.W C Human Factors & Bafeguards Branch B4/01/13 MCFEEK, C NRC No Detailed Affiliation Given. ip 22251 320 24% Fiche 50-000, 84/01/26, 8402140021.
- 8401260470 Advises of Bandia request for site visit during wk of 840205 to study destructive & safety consequences of explosive-laden vehicle. Data will be collected to identify structures & sys most volumerable to truck-mounted explosives.
 FLOYD, H C Human Factors & Safeguards Branch 84/01/10 REED, C Commonwealth Edison Co. ip 22251 321 24X Fiche 50-000.

- 8402010061 Summary of 840126 meeting w/util, Wester, Bethtel, Sargent & Lundy & INEL in Bethesda, MD re equipment environ qualification review Agenda & list of specific equipment qualification deficiencies encl GILBERT, R A Operating Reactors Branch 5 84/01/30 Operating Reactors Branch 5 36pp. 22042 127 24X Fiche 50-000,84/01/30,8402010061
- 8402140205 Forwards response to Generic Ltr 83-36 requesting licensess to submit Tech Specs or schedule for NUREO-0737 items scheduled after Hi1231 All appropriate Tech Spec amend requests will be submitted by 840815

 BARNES,P L Commonwealth Edison Co 84/02/07 DENTON, H. R Office of Nuclear Reactor Regulation, Director 9pp 22229 341, 24X Fichs 50-000,84/02/09,8402140205
- 8402210264 Provides add1 clarification re OE model improvements (NEDE-20366 P, NEDG-20366-1, Rev 1 & NEDG-20366-4, Rev 4), per NRC Bio204 & 831228 ltrs PCT for BMR/3s reduced by 130 F. TMI Action Items II k 3 30 & 31 unchanged & complete. RYBAK, B Commonwealth Edison Co 84/02/10 DENTON, H R Office of Nuclear Reactar Regulation, Director 1p 22314 354, 24% Fiche 50-254,84/02/10,8402210264
- 8402170259 Forwards Amends 80,72,86 & 81 to Licenses DPR-19,DPR-23, DPR-29 & DPR-30,respectively Amends approve Tech Spec changes providing add1 limiting conditions for Class IE power monitoring sus CRUTCHFISLD.D Operating Reactors Branch 5 84/02/14 FARRAR,D L Commonwealth Edison Co 3pp 28297 112 24X Fiche 50-000,84/02/14,8402170259
- --8402170276 Amends 80,72,86 & 81 to Licenses DPR-19, DPR-25, DPR-29 & DPR-30, respectively, approving Tech Spec changes providing add1 limiting conditions for Class IE power monitoring sys CRUTCHFIELD, D Operating Reactors Branch 5 84/02/14 28pp 22297 115 24X Fiche 50-000.84/02/14,8402170259
- B4022B0457 Forwards Amends 81.73.87 & 82 to Licenses DPR-17, DPR-23, DPR-27 & DPR-30, respectively & safety evaluation Amends revise Tech Specs to require restoration of safety/relief valve imporable position indication CRUTCHFIELD.D Operating Reactors Branch 5 84/02/24 FARRAR.D L. Commonwealth Edison Co 3pp 22406 315 24X Fiche 50-000, 84/02/24, 8402280457
- --B402280492 Amends Bi. 73.87 & 82 to Licenses DPR-19.DPR-25.DPR-29 & DPR-30.respectively, changing Tech Space to require restoration of all safety/relief volve imperable position indication prior to startup when in cold shutdown over 72 h CRUTCHFIELD.D Operating Reactors Branch 5 VASBALLO.D B Operating Reactors Branch 2 B4/02/24 16pp 22406 318 24X Fiche 50-000.84/02/24.8402280457
- --8402280531 Sarety evaluation supporting Amends 81,73,87 & 82 to Licenses DPR-19, DPR-25, DPR-27 & DPR-30, respectively * Office of Nuclear Reactor Regulation, Director 84/02/24 22406 334 24X Fiche 50-000.84/02/24,8402280457
- G Inspection reports, IE Bulletins & correspondence
- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps" 8vc list encl JORDANE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120153.
- B402230136 Forwards request for add1 info re IE Bulletin 80-11, "Masonry Wall Design," Info required within 40 days of receipt of 1tr.

 VASSALLO, D B Operating Reactors Branch 2 84/01/31 FARRAR, D. L. Commonwealth Edison Co 10pp 22379 204 24X Fiche 50-254, 84/01/31.8402230156
- 8402080378 Forwards info necessary to complete NRC review of IE
 Bulletin 80-11, "Masonry Hall Dosign " W/three oversize
 proprietary drawings Aperture cards are available in Central
 Filos
 RYBAK.B Commonwealth Edison Co 84/02/02, DENTON, H R. Office of
 Nuclear Reactor Regulation, Director 33pp 22160 033, 24X
 Fiche: 50-000, 84/02/02, 8402080378
- --8402080385 Rev & to Procedures Manual DP-45, "Bampling & Testing of Hallow Concrete Masonry Units" LINDBTROM, R. KRAUSE, R. Wiss: Janney. Eletner & Associates, Inc. 82/07/22, 13pp 22160 066 24X Fiche, 50-000,84/02/02, 8402080378.
- --8402080974 Rev 2 to Procedures Manual OP-46, "Testing of Compression Cores Taken From Solid Block Walls " LINDSTROM, R, KRAUSE, R Wiss, Janney, Elstner & Associates, Inc. 82/06/24 lipp 22160 079 24% Fiche 50-000,84/02/02,8402080378

- ---8402080401 Rev 2 to Procedures Manual OP-47, "Determination of Mortar Type " LINDSTROM,R , KRAUSE,R Wiss, Janney, Elstner & Associates, Inc 82/06/24 38pp 22160.090 24X Fiche 50-000,84/02/02,8402080378
- --B4020B0407 Rev 7 to Procedures Manual DP-50, "In Situ Shear Test of Block Walls " KRAUSE, R Wiss, Janney, Elstner & Associates, Inc 82/08/11 12Pp 22140 128 24X Fiche 30-000,84/02/02.8402080378
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03, Consolidated Edison Co. of New York, Inc. 119pp 22114 179 24X Fichs 50-000.84/02/03, 8401190016
- 8401170017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEYDUNO.R C. Director's Office, Dffice of Inspection and Enforcement 84/02/03 Consulidated Edison Co of New York, Inc 102pp 22177
- 8402130346 Forwards visual insp results in response to IE Bulletin B4-01 re Mark I containments. No cracks or abnormalities found. BARNES. P. L. Commonwealth Edison Co. 84/02/10 KEPPLER, J. Q. Regio 3, Office of Director 4pp 22230 108 24X Fiche 30-254, 84/02/10, 8402130344
- B402270426 Forwards IE Insp Repts 50-254/83-30 & 50-265/83-31 on B31205-840131.No nencompliance noted BHAFER,M.D. Region 3, Diffice of Director 84/02/10 REED,C Commonwealth Edison Co. 2pp. 22390 207 24X Fiche 50-254,84/02/10, B402270426.
- --8402270432 IE Insp Repts 50-254/83-30 & 50-245/83-31 on 831203-840131 No moncompliances or deviations identified, Major areas inspected, previous insp findings, operational safety, maint, surveillance, LERs, IE bulletin follows & reactor scrams CHRIBBOTIMOB, N. MORRONGIELLO, A. WALKER, R. D. Region 3, Office of Director 84/02/09, 12pp. 22390 209, 24X Fichs 50-254, 84/02/10, 8402270426
- 8401170041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sus (100FR50, App R)" Svc list oncl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/13 Consolidated Edison Co of New York, Inc. 124pp. 22365-259 24X Fiche. 50-000, 84/02/13, 8401190041
- B401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '"
 Bvc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/02/14 Consolidated Edison Co of New
 York, Inc. 115pp. 22365 141 24X Fiche 50-000,84/02/14,8401170037
- B401170045 IE Info Notice 83-63. Suppl 1: "Potential Failures of Westinghouse Type SA-1 Differential Relays." Syc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15. Consolidated Edison Co of New York, Inc. 118pp. 22366.142. 24X Fiche 50-000.84/02/15,8401170045
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/21. Consolidated Edison Co. of New York, Inc. 116pp. 22366.024. 24X Fiche 50-000,84/02/21,8401190062
- B401170066 IE Info Notice 84-11, "Training Program Deficiencies."

 Svc list encl.

 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/24 Consolidated Edison Co. of New
 York, Inc. 115pp. 22430:304. 24X Fiche: 50-000, 84/02/24, 8401170066
- 8402280296 Ack receipt of 840120 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-234/83-13 & 50-265/83-15. Completion of Task 1, "Multiplet Resolution & Feak Classification" should resolve open items. PAPERIELLO, C. J. Region 3, Office of Director. 84/02/24. RYBAK, B. Commonwealth Edison Co 1p. 22397:076. 24X Fichs: 50-254,84/02/24,8402280276.
- ---8402280302 Responds to NRC 1tr re violations noted in IE Insp Repts 50-284/82-13 & 50-265/82-15. Corrective, actions: three add1 tasks developed to enhance spectral analysis & improve parformence of AAIB RYBAK.B. Commonwealth Edison Co. 84/01/RO. PAPERIELLO.C.J Region 3. Office of Director. 2pp. 22399:077. 24X Fiche: 50-254, 84/02/24, 8402280296

- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
 Svc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060 24X Fiche 50~000.84/02/27.8401190067
- A Periodic operating reports & related correspondence
- B402220332 Monthly operating repts for Jan 1984 W/840201 ltr MISAK.A , KALIVIANAKIS.N Commonwealth Edison Co 84/01/31 21pp 22334 212 24X Fichs 50-254,84/01/31,8402220332
- 8 Reportable occurrences, LERs & related correspondence
- 8402030285 LER 83-048/03t-0 on 831229, results of chimney effluent radionuclide analysis found to be less than normal Caused by broken power cable to heat trace due to extreme subjero temps Power cable replaced W/840125 ltr
 REYNOLDS S KALIVIANAKIS.N Commonwealth Edison Co 84/01/25
 KEPPLER, J Region 3, 09fice of Director 4pp 22069 352 24X
 Fiche 50-254,84/01/25,8402030285

DOCKET 50-255 PALISADES NUCLEAR PLANT

- F Becurity, medical, emergency & fire protection plans
- 8402220501 Revised emergency implementing procedures, including Rev 1 to App C. "Review & Rev of General Ofc Control Ctr/Emergency Operations Facility Emergency Implementing Procedure" & revised index W/840217 ltr # Consumers Power Co 84/01/10 10pp 22333.278 24X Fiche.50-000.84/01/10.8402220501
- 8402150375 Rev 5 to "Controlled Copyholders List General Ofc Control Ctr/Emergency Operations Facility Emergency Implementing Procedures "W/840207 ltr ** Consumers Power Co 84/01/26 8pp 22242 061 24X Fiche 50-000.84/01/26
- 8402070345 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per 830709 ltr W/o request, entire plan will be placed in PDR Distribution list encl CRUTCHFIELD. D. Operating Reactors Branch 5, 84/02/06 VANDEMALLE: D J Consumers Power Co. 3pp 22097-021 24X Fiche. 50-000, 84/02/06, 8402070345
- 8402140007 Forwards Rev 9 to security plan & Attachment 1.containing Justification for Rev 9.Rev addresses findings made in IE Insp Rept 50-255/83-20 & commitments identified in NRC 831130 ltr. Rev withheld (ref 10CFR73 21) VANDEWALLE, D J Consumers Power Co. 84/02/06 KEPPLER, J. 9, Region 3, Office of Director ip 22217 358 24X Fiche. 50-255.84/02/06.8402140007
- 8402220083 Ack receipt of 840206 ltr transmitting Rev 9 to security plan. Changes consistent w/provisions of 10CFR30 54(p) & acceptable AXELSON, H. L. Division of Emergency Preparadness & Operational Support 84/02/16. VANDEWALLE, D. J. Consumers Power Co. Rpp 22338, 337. 24X Fiche, 50-255, 84/02/16, 8402220083
- H General correspondence
- 8402270532 Requests duplicate color negative of serial photograph of oblique 45 degree angle aerial shot of facility taken by EOAG in 1983 FARR.K M. Consumers Power Co. 83/12/21. NRC No Detailed Affiliation Given 1p. 22414-153. 24X Fiche.50-255.83/12/21, 8402270532
- 8402270535 Responds to FDIA request & forwards duplicate color negative of aerial photograph of facility. Wo encl. FELTON. J. M. Division of Rules and Records 84/01/13 FARR. K M Consumers Power Co. ip. 22414 154 24X Fiche: 50-255, 84/01/13, 8402270535
- P. Operating license stage documents & correspondence
- B312120029 Generic Ltr B3-39 to representatives of utils re voluntary survey of licensed operators Bvc list encl EIBEMHUT, D. © Division of Licensing B3/12/08 Commonwealth Edison Co. 12pp 22313 004 24X Fiche 50-000, 83/12/08, 8312120029

- 8402030259 Forwards add1 info in response to Generic Ltr 82-28 re inadequate core cooling instrumentation sys Final response, on reactor vessel level portion of inadequate core cooling instrumentation questions will be supplied in Apr 1984 JOHNSON, B D Consumers Power Co 84/01/30 CRUTCHFIELD, B Operating Reactors Branch 5 11pp 22069 313 24X Fiche 50-255, 84/01/30, 8402030259
- 8402010410 Generic Ltr 84-0A to all operating PKR licensees, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination or postulated pipe breaks in PKR primary main loops Svc list encl EISENRUT. D © Division of Licensing 84/02/01 Consolidated Edison Co of *New York. Inc. 59pp 22177 087 24X Fiche 50-000,84/02/01,8402010410
- 8402080222 Forwards response to Generic Ltr 83-28 re required actions based on generic implications of Salem ATWS events & Issues 4 2 3 & 4 2 4 on reactor trip sys reliability Encl describes design, operation & testing of reactor protection sys VANDEWALLE, D. J. Consumers Power Co. 84/02/03 EISENHUT, D. G. Division of Licensing 10pp 22130 123 24X Fiche 50-255,84/02/03,8402080222
- B402130446 Responds to Generic Ltr 83-37 re Tech Spec changes for various NUREG-0737 items Obstanding items listed Tech Spec change scheduled for submittal on B40515 JOHNSON.B D Consumers Power Co 84/02/08 CRUTCHFIELD.D Operating Reactors Branch 3 2pp 22201 149 24X Fichs 50-235, 64/02/08, 8402130466
- 8402140461 Forwards add1 info re environ protection plan Info consists of correspondence between util & State of MI.Dept of Natural Resources
 JOHNSON. B D Consumers Power Co B4/02/08 CRUTCHFIELD. D
 Operating Reactors Branch 5 94pp 22221 131 24X
 Fiche 50-255.84/02/08.8402140461
- B402150371 Notification of rescheduled B40221 meeting w/util in Bethesds.hD to discuss proposed steam generator plugging criteria & insp results PAULSON.W A Operating Reactors Branch 5 84/02/14 CRUTCHFIELD.D Operating Reactors Branch 5 40p 22242 140 24X Fiche 50-255.B4/02/14.B402150371
- 8402160381 Forwards SER re CESEC digital simulation of C-E NS98 CESEC-III acceptable computer program for use in licensing applications for calculating FSAR Chapter 15 events CRUTCHFIELD, D Operating Reactors Branch 5 84/02/14 VANDEWALLE, D J Consumers Power Co 3pp 22269 021 24X Fiche 50-255,64/02/14,8402160381
- --8402160387 SER re CESEC digital simulation of C-E NSSS CESEC-III acceptable computer program for use in licensing applications for calculating FEAR Chapter 15 events GUTTMAN.J. Operating Reactors Branch 5 83/160/27 28pp 22269 024 24X Fichs 50-255.84/02/14.8402160381
- 8402230240 Provides addi info re environ qualification of safetyrelated electrical equipment, per Franklin Research Ctr B21230 technical evaluation rept & SER requirement JOHNSON, B D Consumers Power Co 84/02/14 CRUTCHFIELD, D Operating Reactors Branch 5 34pp 22352 307 24X Fiche 50-255, 84/02/14,8402230240
- 84022:0109 Requests relief from ASME Boller & Pressure Vessel Code, Bection IX, Subsection IWP testing interval for safetyrelated pumps Testing on quarterly rather than monthly basis requested JDHNSON.B D Consumers Power Co 84/02/15 CRUTCHFIELD, D Operating Reactors Branch 5 24p 22317 164 24X Fiche 50-255.84/02/15.8402210105
 - 12230012 Notifies of variance from requirements of NUREO-0737 Recent review of stack gas monitors revealed that display applitities not in accord w/NUREO-0737. Item II F 1 1 /ANDEWALLE, D J Consumers Power Co 84/02/20 CRUTCHFIELD, D Jearating Reactors Branch 5 29p 22362 05B 24X Fiche 50-000,84/02/20,8402230012
- : Inspection reports, IE Bulletins & correspondence
- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater fumps" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co. of New York, Inc 120pp 22058 001, 24X Fishe 50-000,84/01/25,8312120153
 - 02100205 Furwards IE Insp Rept 50-255/83-27 on 831122 & 840117 No inicompliance noted ITTLE.W S Region 3. Office of Director 84/01/27 DEWITT,R B unsumers Power Co 2pp 22178 024 24X Fiche 50-255,84/01/27,40100008

- --B40210020B IE Insp Rept 50-255/83-27 on 831122 & 840117 No noncompliance noted Major areas inspected calculations re adequacy of heat removal capacity for fan coolers in engineered safeguards room referenced in LER 83-007 MUFFETT.J W., DANIELSON.D H. Region 3, Dêfice of Director 84/01/27 2pp 22178 026 24% Fiche 50-255,84/01/27.8402100205
- 8401190016 IE Info Notice 84-07, "Design-Hasis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 177 24X Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in 8WR Mark I Containment Vent Headers " Svc list encl DEYDUNG.R C Director's Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 156 24X Fiche 50-000,84/02/03.8401190017
- 8402070355 Notifies of 840224 enforcement conference to review circumstances surrounding recent station blackout event at site, per 840124 telcon NORELIUS, C.E. Division of Project & Resident Programs 84/02/03 DEWITT, R.B. Consumers Power Co. ip. 22094 362 24% Fiche 50-255, 84/02/03.8402070355
- 8402140007 Forwards Rev 9 to security plan & Attachment 1, containing justification for Rev 9 Rev addresses findings made in IE Insp Rept 30-255/83-20 & commitments identified in NRC 83130 ltr Rev withheld (ref 100FR73 21) VANDEHALLE, D J Consumers Power Co 84/02/06 KEPPLER, J 9 Region 3, Office of Director 1p 22217 358 24X Fiche 50-235,84/02/06,8402140007
- 8402100293 Submits add1 info in response to IE Bulletin 80-06. "ESF Reset Controls " Circuitry mods & testing completed on valves 8V-0825 8V-06078 JOHNSON, B D Consumers Power Co 84/02/07 CRUTCHFIELD, D Operating Reactors Branch 5 ip 22178 001 24X Fiche 50-255, 84/02/07, 8402100253
- 840227033B Forwards IE Insp Rept 50-255/84-01 on 840118-20 & notice of violation HND) J A Division of Radiological & Materials Bafety Programs 84/02/09 DEMITT.R B Consumers Power Co 2pp 22391.235. 24X Fiche 50-255.84/02/09.8402270338
- --8402270348 Notice of violation from insp on 840118-20 HIND, J A Ragion 3, Office of Director 84/02/09 2pp. 22391 237 24X Fiche 50-255.84/02/09.8402270338
- --8402270361 IE Insp Rept 50-255/84-01 on 840118-20 Noncompliance noted plant organization not in accordance w/Toch Specs re radwaste drum leaking during transport & noble gas effluent monitor not installed per NRC 830314 order LOVENDALE, P. C. GREGERLL. R. Region 3, Office of Director. 84/02/08 2pp 22391 239 24X Fiche. 50-255.84/02/09.8402270338
- 8402290193 Forwards IE Insp Rept 50-255/84-02 on 840103-31 No noncompliance identified SHAFER, W D Region 3, Office of Director 84/02/10 DEWITT, R B, Consumers Power Co 2pp 22425 152 24X Fiche 50-255,84/02/10, 8402290193
- B402270203 IE Insp Rept 50-255/84-02 on B40103-31. No noncompliance noted Major areas inspected action on previously identified items, plant safety, maint, reportable events & miscellaneous activities
 JORGENSEN, B L , BOYD, D C Region 3, Office of Director, 84/02/14, 10pp. 22425-154 24X Fiche 50-235,84/02/10,8402290193.
- 10pp. 22425-154 24X Fiche 50-255,84/02/10,8402290193.

 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R)" Byc list
- encl JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259 24X Fichs 50-000,84/02/13,8401190041.
- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection'" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/14 Consolidated Edison Co. of New York, Inc 115pp 22365 141 24X Fiche. 50-000, 84/02/14, 8401190039
- B402150371 Notification of rescheduled 840221 meeting w/util in Bethesda.MD to discuss proposed steam generator plugging criteria & insp resulte PAULSON, WA Operating Reactors Branch 5 B4/02/14, CRUTCHFIELD, D Operating Reactors Branch 5 4pp 22242 140, 24X Fiche 50-235,84/02/14,8402150371

- 8401190045 IE Info Notice 83-63. Suppl 1. "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc 1ist encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 11899 22366 142 24X Fiche 50-000.84/02/15,8401190045
- 8402210091 Informs that ASME Nuclear Code pumps & spare parts mfg by Hayward Tyler Pump Co not used at facilities, in response to 1E Bulletin 83-05
 JOHNBON, B D Consumers Power Co
 Operating Reactors Branch 5 1p
 Fiche: 50-000, 84702/15, 8402210091
- 8401190062 IE Info Notice 84-i0, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/21 Consolidated Edison Co of New York, Inc. 116pp 22366-024 24X Fiche 50-000,84/02/21,8401190062
- 8401190066 IE Info Notice 84-11. "Training Program Deficiencies "
 Svc list encl.
 JCRDAN:E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York: Inc 113pp 22430:304 24X Fiche 30-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
 Svc list encl,
 JORDAN,E L. División of Emergancy Preparedness & Engineering
 Response (Post 830103). 84/02/27 Consolidated Edison Co. of New
 York, Inc. 120pp 22431:060 24X Fiche 50-000.84/02/27.8401190067
- R Periodic operating reports & related correspondence
- 8401130193 Monthly operating rept for Dec 1983 W/840109 ltr DIENES,A.F. VANDENBERG,D. Consumers Power Co 83/12/31 NRC -No Detailed Affiliation Given. 5pp 21802,001 24X Fiche: 50-255,83/12/31,8401130193
- 8402140177 Monthly operating rept for Jan 1984.W/840207 ltr DIENEB, A F., VANDENDERG, D. Consumers Fower Co 84/01/31 5p 22230,207 24X Fiche: 50-255,84/01/31,8402140177
- 8402150297 Forwards "Reactor Internals Noise Monitoring Tests," 1983
 Results demonstrate that reactor core barrel tightly clamped
 w/no other anomalous vibrations occurring during testing
 period.
 JUHNSON, B D Consumers Power Co. 84/02/06. KEPPLER, J. G Region 3,
 Office of Director 1p. 22244:197 24X Fiche. 50~255, 84/02/06,
 B402150297
- --8402150301 "Reactor Internals Noise Monitoring Tests," 1983 * Consumers Power Co 83/12/31 36pp. 28244;178, 24X Fiche: 50-255,84/02/06,8402150297
- B. Reportable occurrences, LERs & related correspondence
- 8402030437 LER 83-079/03L-0 on 831230 trip settings for low primary coolant pump (PCS) flow for operation w/two PCS found below Tach Spec limit Caused by inadequate surveillance procedure Surveillance procedure revised M/840125 ltr JOHNSON, B. D. Consumers Power Co. 84/01/25, KEPPLER, J. Q. Region 3, Office of Director 2pp 22067; OSB 24X Fiche 50-255, 84/01/25, 8402030437.
- E402070355 Notifies of B40224 enforcement conference to review circumstances surrounding recent station blackout event at site per B40124 telcon NOAELIUB, C. E. Division of Project & Resident Programs 84/02/03 DEWITT, R. E. Consumers Power Co. 1p. 22094/362, 24X Fiche: 50-255,84/02/03,8402070355.
- B402)00235 LER 84-001-00: on B4010B, complete loss of all normal communication links between plant, NRC & state/local authorities occurred Caused by loss of ac power due to overheated tripped diesel Breaker installed, W/B40207 ltr R89EBS, D. W., JOHNSON, B. D., Consumers Fower Co., B4/02/07, 17pp, 22179: 277. 24X Fiche: 50-255, 84/02/07, 8402(00235.
- DOCKET 50-239 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 8402280411 Forwards IE Enforcement Conference Repts 50-259/83-58, 30-260/83-58 & 50-296/83-58 on 831216 Meeting held to discuse apparent security violation & operation w/underrated dissel generator HK.

 O'REILLY, J. P. Region 2, Office of Director 84/01/05 PARRIS, H. O Tennessee Valley Authority 2pp 22407:143, 24X
 Fiche' 50-259, 84/01/05, 8402280411

- 8402140180 Confirms NRC 840118 telcon to 840119 meeting in Region II ofc to discuss security activities LEMIS.R C Division of Project & Resident Programs 84/01/18 PARRIS.H G Tennessee Valley Authority ip 22230 299 24X Fiche 50-259.84/01/18.8402140180
- 8402040392 Forwards Rev 7 to generic security personnel training & qualification plan Rev withheld (ref 100FR73 21)
 MILLS,L M Tennesses Valley Authority 84/01/19 O'REILLY, J P Region 2. Office of Director 1p 22086 317 24X
 Fiche 50-000.84/01/19.8402040382
- 8402210301 Revised emergency plan implementing procedures, including Procedures BFN-REP re radiological emergency plan & BFN-IFD re implementing procedures document W/940210 1 tr MILLS.L K Tennessee Valley Authority 84/01/20 0'REILLY, J P Region 2. Dffice of Director 128pp 22315 076 24X Fiche 50-259,84/01/20,8402210301
- 8402140384 Forwards summary of 840113 meeting in Region II oft re emergency protective actions required by NUREG-0454 & clarified by IE Info Notice 83-28 VERRELLI, D.N. Division of Project & Resident Programs 84/01/24 PARRIS, H.G. Tennessee Valley Authority 4pp 22220 042 24X Fiche 50-000,84/01/26,8402140384
- 8402130316 Forwards Rev 8 to generic security personnel training & qualification plan Rev withheld MILLS.L M Tennessee Valley Authority 84/01/27 O'REILLY.J P Region 2. Office of Director 1p 22197 149 24X Fichs 50-000.84/01/27.8402130316
- 8402130490 Forwards rev to physical security plan Rev withheld (ref 10CFR73-R1) MILLB:L.M Tennessee Valley Authority 84/01/30 G'REILLY.JP Region 2: Office of Director ip 22200 256 24x Fichs 50-257:84/01/30:8402130490
- B402140295 Forwards summary of B40119 meeting w/util in Region II ofc re improvement of security effectiveness & other security related topics LEMIS.R G Division of Project & Resident Programs B4/02/01 PARRIB.H.G Tennessee Valley Authority 4pp 22228 271 24X Fiche:50-000,84/02/01,8402140295
- 8402R1027B Revs to Muscle Shoals emergency control ctr implementing procedures; including Procedure MSEC IP-1 is spatification of unusual event, alert or transportation accident & MSEC IP-2 is site emergency or emergency director W/840210 ltr MILLS, L.M. Tennessee Valley Authority, 84/02/02, 0'REILLY, J. P. Ragion 2, Office of Director, 76pp 22315 001 24% Fiche: 50-000, 84/02/02, 8402210278
- 8402130354 Ack receipt of util 831005 & 1121 ltrs transmitting rev to facility security plan. Rev consistent w/provisions of 100FR80 54(p) & acceptable.
 LEWIS, R C Division of Project & Resident Programs 84/02/08.
 PARRIS, H G Tannessee Valley Authority. 3pp. 82197-885 24X
 Fiche 50-259,84/02/08,8402130354
- 8402150221 Forwards evaluation of TVA radiological emergency preparadness plan for Browns Ferry for 831115-16 exercise State of AL & Lauderdale, Laurence, Limestone & Morgan Counties participated KRIMM, R.W. Federal Emergency Management Agency 84/02/08 JORDAN, E.L. Division of Emergency Preparadness & Engineering Response (Post 830103) 1p 22244 251 24X Fiche 50-259, 84/02/08, 8402150221.
- --8402150237 Evaluation of TVA radiological emergency preparedness plan for Drowns Farry for 831115-16 exercise + Federal Emergency Management Agency, 83/12/16 28pp 22244, 252 24X Fiche. 30-259,84/02/08,8402150821
- B400280489 Ack receipt of B40126 ltr informing NRC of add1 steps taken to correct violations noted in IE Insp Repts 50-259/83-33, 50-2260/83-33 & 50-276/83-33.

 LEWIB:R C. Division of Project & Resident Programs 84/02/15.

 PARRIS:H.G. Tennessee Valley Authority 1p 22407-001 24X

 Fiche 50-257,84/02/15,8402280489.
- --8402280552 IE Insp Repts 50-259/83-33.50-260/83-33 & 50-294/83-33 on 830724-0825 Noncompliance noted failure to have equipment installed in accordance w/drawings.follow leak detection monitoring procedures & update as-constructed drawings FAULKA L Region 2, Office of Director 83/09/20 14pp 22407-019. 24X Fiche 50-259.84/02/15.8402280489.

J Insurance & indemnity information

- 8402210231 Forwards Endorsements 71 & 72 to NELIA Policy NF-178 & Endorsements 60 & 61 to MARLU Policy MF-66 Amended site description also encl DUCK, J.R. Marsh & McLennan, Inc. 84/02/13 SALTZMAN, J. Assistant Director for State & Licensee Relations 7pp 22315 297 24X Fiche 50-259.84/02/13.8402210231
- P Operating license stage documents & correspondence
- 8402090310 "Browns Ferry Other Transients Failure Modes & Effects Analysia & Rejected Bys Justification Rept." preliminary rept BAXTER D E , BEAHM, D M , BRUGKE, S J EG&G, Inc FIN A-6477 EGG-EA-6296 DRFT B3/03/31 NRC - No Detailed Affiliation Given 68pp 22187 271 24x Fiche 50-259,83/05/31.8402090310
- 8402010408 Forwards notice of consideration of issuance of amends to Licenses BPR-33, BPR-52 & DAR-68 & proposed NSHC determination & apportunity for hearing re operation w/one recirculation loop out of svc CLARK, R. J. Operating Reactors Branch 2 B4/01/16 PARRIS, H.G. Tennessee Valley Authority 2pp 22062 001 24X Fiche 50-239,84/01/16.8402010408
- --B402010417 Notice of consideration of issuance of amend to Licenses DPR-33.DPR-52 & DPR-68 & proposed NSHC determination & apportunity for hearing Amends permit operation w/one recirculation loop out of svc VASSALLO.D B. Operating Reactors Branch 2 84/01/16 App 22062 003 24X Fiche 50-257.84/01/16.8402010408.
- 8402090303 Requests rev to pressure temp curves using conservative assumptions or demonstration that predicted neutron irradiation damage will be less than predicted for reactor vessel surveillance mat!

 VABSALLO.D 8 Operating Reactors Branch 2 84/01/23 PARRIS.H G Tennesses Valley Authority 3pp 22177 348 24%

 Fiche 50-259,84/01/23,8402090303
- 8402140392 Confirms 840130 mgt meeting in Atlanta. QA to discuss past & planned mgt changes.per 840123 telcon
 LEWIS.R C Division of Project & Resident Programs 84/01/24
 PARRIS.H O. Tennessee Valley Authority ip 22220 331 24X
 Fiche 50-259.84/01/24.8402140392
- 8402130541 Forwards errata to Amends 94,87 & 60 to Licenses DPR-33, DPR-52 & DPR-68, respectively, revising Tech Spacs sent on 831227 CLARK,R J Operating Reactors Branch 2 84/01/25, PARRIS, H G Tennessee Valley Authority 2pp. 22214:331 24X Firher 50-259,84/01/25,8402130541.
- --B402130552 Amends 74,87 & 60 to Licenses DFR-33,DPR-52 & DPR-68, respectively, revising errors in Yech Spacs sent on 831227 e NRC No Detailed Affiliation 64ven 84/01/25 12pp 22214 333 24X Fiche 30-259,84/01/25,8402130541
- 8402070204 Advises that date of 840321 acceptable for meeting w/NRC to discuss program plan for detailed control roum design reviews Concurrence on meeting date requested HILLS.L.M Tennessee Valley Authority. 84/02/01 ADENSAN.E. Licensing Branch 4 ip 22102 212 24X Fiche 50-000.84/02/01.
- 8402140451 Notifies that response to Reg Ouide 1 97 will be submitted by 840430 MILLS:L M Tennessee Valley Authority 84/02/06, DENTON, H R. Office of Nuclear Reactor Regulation, Director 1p 22227 111 24X Fiche 50-259.84/02/06.8402140451
- 8402170297 Requests submittel of addl fee for review of 830713 application to amend License DRR-33, changing Tech Specs recore reload & other plant mods performed during refueling outage
 DIQOS,R M License Fee Management Branch 84/02/10 PARRIS,H Q
 Tennessee Valley Authority 1p 22313-225 24X
 Fiche 50-259.84/02/10,8402170297
- B402210071 Informs NRC of need for specific Tach Spec rev for plant Reaphasizes concerns re overall backlog of Tech Spec requests outlined in 830627 ltr MELS,L N Tennessee Valley Authority, B4/02/13 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22317 284 24X Fiche 50-259,84/02/13,8402210071

٩

- 8402280224 Responds to RM Diggs 840210 ltr re determination of fees for facility Util agrees w/fee determination t will submit fee by wire transfer MILLS.L M Tennessee Valley Authority 84/02/23 MILLER.W O License Fee Management Branch ip 22399 233 24X Fiche 50-259.84/02/23.8402280224
- O Inspection reports, IE Bulletins & correspondence
- 8402140382 Forwards IE Insp Repts 50-259/83-54, 50-260/83-54 & 50-296/83-54 on B31212-16 No violations or deviations noted. VERRELLI, D M Division of Project & Resident Programs 84/01/03 PARRIS. H G Tennesses Valley Authority 2pp 22221 242 24X Fiche 50-259,84/01/03,8402140352
- --8402140338 IE Insp Repts 50-289/83-54,50-260/83-54 & 50-296/83-54 on 831212-16 No violations or deviations noted Major areas inspected independent reverification of inservice insp work activities & IE Bulletin 83-02 COLEY.J L. Region 2, Office of Director BLAKE,J J. Division of Engineering & Operational Programs 83/12/29 4pp 22221 244 24X Fiche 50-259,84/01/03,8402140352.
- 8402280411 Forwards IE Enforcement Conference Repts 50-297/83-58, 50-260/83-58 & 50-296/83-58 on 831216 Heating held to discuse apparent accurity violation & operation w/underrated discel generator HX O'REILLY, J P Region 2, Office of Director 84/01/05 PARRIS, H Q Tennessee Valley Authority 2pp 22407 143 24X Fiche 50-259, 84/01/05.8402280411
- --8402280417 IE Enforcement Conference Repts 50-257/83-58,50-260/83-58 i 50-296/83-58 on 831216 Major areas discussed acceptability of HX on dissel generator & mod to screm discharge instrument vol CANTRELL.F 8 Division of Project & Resident Programs 84/01/03 5pp 22407 145 24X Fiche 50-259,84/01/05,8402280411
- 8402060119 Forwards SER of masonry wall design, per IE Bulletin 80-11, Reevaluation of design of four unacceptable walls & proposed plans to upgrade walls requested within 120 days VASSALLO, D B Operating Reactors Branch 2 84/01/16 PARRIS, H Q, Tennessee Valley Authority 2pp 22103 194 24X Fiche, 90-259, 84/01/16, 8402060119
- --B402060144 Bafety evaluation re masonry wall design.per IE Bulletin 80-11 W/listed exceptions wall integrity & performance of required safety functions will not be impaired # Office of Nuclear Reactor Regulation, Director B4/01/16, 2pp 22103 198 24X Fiche 50-259,84/01/16,8402060119
- --8307270075 "Masonry Wall Design (8-57). TVA Browns Ferry Nuclear Plant, Units 1.2 & 3." technical evaluation rest LE,A K. Franklin Institute/Franklin Research Center NRC-03-61-130 TER-C5506-257 03/09/26 CHDKSHI.N C NRC Ng Detailed Affiliation Given Sipp 22111 203 24X Fiche. 50-259,84/01/16.8402050119
- B402140106 Ack receipt of B40107 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-52, 50-260/83-52 & 50-296/83-52 VERRELLI, D.M. Division of Project & Resident Programs 84/01/19. PARRIB, H G Tennessee Valley Authority ip 22217:040 24X Fiche: 50-259, 84/01/19, 8402140106
- --8402140112 Responds to NRC 831208 ltr re violations noted in IE Insp Repts 50-259/83-52,50-260/83-52 & 50-296/83-52. Corrective actions plant procedure for control room abandonment revised to require switches be checked for desired alignment. MILLS.L M Tennesses Valley Authority 84/01/09 0'REILLY, J.P. Region 2. Diffice of Director 4pp 22217, 041 24X Fiche 50-259,84/01/19,8402140106
- --8402140121 Forwards IE Insp Repts 50-259/83-52,50-260/83-52 & 50-296/83-52 on 831026-1125 & notice of violation, VERRELLI, D M Division of Project & Resident Programs, 83/12/08 PARRIS, H 9 Tennesses Valley Authority 2pp 22219-045, 24X Fiche: 50-259,84/01/19,8402140106
- --8402140126 Notice of violation from insp on 831026-1125.
 * Region 2, Office of Director 83/12/08 ip 22219-047. 24X
 Fichs 50-259,84/01/19,8402140106
- --8402140136 IE Insp Repts 50-239/83-52:50-260/83-52 & 50-296/83-52 on B31206-1125 Violations noted failure to perform annual review of industrial security program & failure to have procedure to align backup control switches. PAULK: G L., CANTRELL,F,S Region 2. Office of Director 7pp 22219:048 24X Fiche.50-259,84/01/19,8402140106

- 8402140243 Ack receipt of 831221 supplemental ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-12,50-260/83-12 & 50-296/83-12 O'REILLY, J P Region 2, Office of Director 84/01/20 PARRIS, H G Tennessee Valley Authority 1p 22220 298 24X Fiche 50-259,84/01/20,8402140243
- --8402140252 Responds to NRC 831115 ltr re violations noted in IE Insp Repts 50-259/83-12,50-260/83-12 & 50-296/83-12 Corrective actions radiological incident repts issued & employees instructed to comply w/requirements re dose rate instrument MILLS:L M Tennessee Valley Authority 83/12/21 0'REILLY,J P Repian 2, Office of Director 3pp 22220 299 24X Fiche 50-259,84/01/20,8402140243
- --B402140263 Ack receipt of B30B27 supplemental response to B30422 notice of violation in IE Insp Repts 90-259/83-12, 50-260/83-12 & 50-296/83-12. NRC continues to believe violations re dose rate instruments occurred O'REILLY, J P Region 2. Office of Director B3/11/15 PARTIS. H. Q Tennessee Valley Authority 2pp 22220 302 24X Fiche 50-259, 84/01/20, 8402140243
- --8402140271 Ack receipt of 830829 supplemental response informing NRC of steps taken to correct violations noted in IE Insp Rapts 50-259/83-12,50-260/83-12 & 50-276/83-12 Info being evaluated LEWIS.R C Division of Project & Resident Programs, 83/10/14 PARRIS.H Q. Tennessee Valley Authority ip 22220 304 24X Fiche 50-259,84/01/20,8402140243
- --8402140276 Forwards supplemental response to NRC 830729 ltr reviolations in IE Insp Repts 50-259/83-12, 50-260/83-12 & 50-276/83-12 & 50-276/83-12 & HLLS, L.M Tennesses Valley Authority 83/08/29 O'REILLY, J P Repian 2. Office of Director App. 22220 305 24X Fiche 50-259, 84/01/20, 8402140243
- 8312120133 IE Info Notice 84-04, "Steam Binding of Auxiliary Feedwater Fumps." Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co. of New York, Inc. 120pp 22058 001 24X Fichs.50-000.84/01/25,8312120133
- 8402140166 Forwards revised response to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators," per 830615 & 107 ltrs Valve integrity verification will be performed by disassambly MILLS, L.M. Tennessee Valley Authority 84/01/25 O'REILLY, J.P. Region 2, Office of Direct. 2pp 22219, 319 24X Fiche: 50-259, 84/01/25, 8402140166
- B402060261 Forwards supplemental response to NRC B30921 request for add1 info re insp & repair of pipe cracks in recirculation & RHR piping sys.per B31017 commitment.

 MILB.L M. Tennessee Valley Authority 84/01/30 DENTON, H R Dffice of Nuclear Reactor Regulation, Director 11pp 22088 114 24X Fiche 50-259, 84/01/30, 8402060261
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/03, Consolidated Edison Co. of New York, Inc. 119pp 22114 179, 24X Fiche. 50-000, 84/02/03, 8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vant Headers," Svc list encl. DEYOUNG.R.C. Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co. of New York, Inc 102pp. 22177.156 24X Fichs.50-000.84/02/03.8401190017.
- 8402140093 Ack receipt of supplemental 840123 Itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-44:50-260/83-44 & 50-296/83-44.

 O'REILLY, J. F. Region 2, Office of Director. B4/02/03. PARRIB, H. Q. Tennessee Valley Authority. 1p 22218, 218. 24X

 Fiche: 50-259,84/02/03,8402140093
- --8402140104 Supple response to NRC 831230 ltr re violations noted in IE Insp Repts 80-259/83-44, 50-260/83-44 & 50-296/83-44, Corrective actions monthly close program modified so correct month ending date assigned to each TLD badge.

 MILLS.L. M. Tennessee Valley Authority 84/01/23 O'REILLY, J. P. Region 2, Office of Director. 3pp 22218-217 24X Fiche: 50-259,84/02/03.8402140093.
- ---B402140110 Ack receipt of B31220 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-257/83-44, S0-260/83-44 & 50-254/83-44.

 D'REILLYJ, P. Region 2, Office of Director B3/12/30.

 PARRIS, H Q. Tennessee Valley Authority ip. 22218 222. 24X Fiche: 30-259, 84/02/03, 8402140093.

- --8402140132 Responds to NRC 831125 ltr re violations noted in IE Insp Repts 50-259/83-44, 50-260/83-44 & 50-276/83-44 Corrective actions Mgt 8ys Development Branch contacted to initiate software changes to prevent future occurrences MILLS.L M Tennessee Valley Authority 83/12/20 0'REILLY, J P Region 2. Office of Director 3pp 22218 223 24X Fiche 50-259, 84/02/03, 8402140073
- --B402140142 Forwards IE Insp Repts 50-259/83-44.50-260/83-44 & 50-276/83-44 on B31025-28 & notice of violation O'REILLY, J.P. Region 2, Office of Director B3/11/25 PARRIS, H G Tennessee Valley Authority 2pp 22218 226 24X Fiche 50-259,84/02/03,8402140093
- --8402140148 Notice of violation from insp on 831025-28 * Ragion 2, Office of Director 83/11/25 ip 22218 228 24X Fiche 50-289,84/02/03,8402140093
- --8402140164 IE Insp Repts 50-259/83-44,50-260/83-44 & 50-296/83-44 on 831025-28 Violation noted subcontractor employee received dose of 3,059 mrom whole body during Third Guarter 1983 PAULK, G L , BUTCHER, R C Region 2, Office of Director CANTRELL, F S Division of Project & Resident Programs 83/11/17 4pp 22218 229 24X Fiche 50-259,84/02/03,8402140093
- 8402140420 Ack receipt of 840110 ltr informing NRC of steps taken to correct deviation noted in IE Insp Repts 50-259/83-41, 50-260/83-41 & 50-296/83-41 VERRELLI.D M Division of Project & Resident Programs 84/02/03 PARRIB,H G Tennessee Valley Authority 1p 22221 224 24X Fiche 50-259,84/02/03,8402140420
- --B402140424 Responds to NRC B31202 ltr re deviation noted in IE Insp Repts 50-259/B3-41,50-260/B3-41 & 50-296/B3-41 Corrective actions Radiography Procedure N-RT-1 revised re layout control Technical std rev will be issued on B40402 MILLS,L M Tennessee Valley Authority B4/01/10 G'REILLY,J P Region 2. Dfpice of Director 2pp 22221 229 24X Fithe 50-259,84/02/03,8402140420
- --B402140429 Forwards IE Insp Repts 50-259/83-41.50-260/83-41 & 50-296/83-41 on 831025-28 & 1101-04 & notice of deviation VERRELLI.D M Division of Project & Resident Programs 63/12/02 PARRIS.H O Tennessee Valley Authority 2pp 22221 227 24X Fiche 50-259,84/02/03.8402140420
- --8402140433 Notice of deviation from insp on 831025-28 & 1101-04 * Region 2, Office of Director 83/12/02 ip 22221 229 24X Fiche 50-259,84/02/03,8402140420
- --B402140443 IE Insp Repts 50-259/83-41.50-260/83-41 & 50-276/83-41 on 831025-28 & 1101-04 Deviation noted failure to take action to proclude recurrence for Violation 81-36-04 re radiographic layout & grinding control GIRARD.E H . COLEY.J L Region 2. Office of Director BLAKE,J J Division of Engineering & Operational Programs 83/11/28 10pp 22221-230. 24% Fiche-50-259,84/02/03.8402140420
- B402280192 Confirms B40217 enforcement conference at Region II ofc to discuss bypassing of rod sequence control sys during shutdown & isolation of drywell to suppression pool differential pressure instruments.per B40207 talcon O'REILLY, J. P. Region 2. Office of Director B4/02/09 PARRIS, H. G. Tennesses Valley Authority 2pp 22400 256 24X Fiche: 50-259, 84/02/09, 8402280192
- B401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Bafe Shutdown Bus (100FR50, App R)" Svc list encl.

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Inc 124pp. 22365 259 24X Fiche. 50-000, 84/02/13, 8401190041.
- 8401190039 IE Info Notice 84-08. "10CFR50.7, 'Employee Protection '"
 Svc list encl.
 JORDAN.E.L Division of Emergency Preparadness & Engineering
 Response (Post 830103), 84/02/14. Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24% Fiche 50-000.84/02/14,8401170039
- 8401190045 JE Info Notice 83-63, Suppl 1, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl URDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22364-142. 24X Fiche 50-000,84/02/15,8401190045
- 8402280489 Ack receipt of 840126 ltr informing NRC of add1 steps taken to correct violations noted in IE Insp Repts 50-259/83-33, 50-260/83-33 & 50-276/83-33.

 LEWIG.R C Division of Project & Resident Programs 84/02/15 PARRIS.H. G. Tennessee Valley Authority ip 22407 001 24x Fiche: 50-259.84/02/15,8402280489

- --B402280498 Forwards supplemental response to NRC 830921 ltr re violations noted in IE Insp Repts 50-259/83-33, 50-260/83-33 & 50-296/83-33 W/o encl MILLS,L M Tennessee Valley Authority B4/01/20 D'REILLY,J P Region 2, Office of Director 1p 22407 002 24X Fiche 50-259,84/02/15,8402280489
- --B402280504 Suppls response to NRC 830781 ltr re violations noted in IE Insp Repts 50-259/83-33.50-260/83-33 & 50-276/83-33 Corrective actions Tech Spec amend request submitted for Units 2 & 3 re APRM gain adjustments XAMMER.D & Tennessee Valley Authority 84/01/26 O'REILLY, J P Region 2. Office of Director 2pp 22407 003 24X Fiche 50-259,84/02/15,8402280489
- --8402280512 Ack receipt of B31024 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-289/83-33, 50-260/83-33 & 50-296/83-33 Supplemental response requested for Item Cree AFRM gain settings

 LEMIS.R C Division of Project & Resident Programs B3/12/16

 PARTIS.H G Tennessee Valley Authority 2pp 22407 005 24X

 Fiche 50-259, 84/02/15, 8402280489
- ---8402280520 Ack receipt of 831024 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-289/88-33, 50-260/83-33 & 50-296/83-33 Response under review LEMIS.R C Division of Project & Resident Programs 83/11/09 PARRIS.H O Tennessee Valley Authority ip 22407 007 24X Fiche 50-259,84/02/15.8402280489
- --8402280530 Responds to NRC 830921 ltr re violations noted in IE Insp Repts 50-259/83-33.50-260/83-33 & 50-296/83-33 Corrective actions shift technical advisor log book modified to assure required info gathered & cable tray deficiencies corrected MILLS.L M Tennessee Valley Authority 83/10/24 O'REILLY.J P Region 2. Office of Director 7pp 22407 008 24X Fiche 50-259,84/02/15.8402280489
- --8402280540 Forwards IE Insp Repts 50-259/83-33,50-260/83-33 & 50-296/83-33 on 830726-0825 % notice of violation LEMIS.R C Division of Project & Resident Programs 83/09/21 PARRIS.H Q Tennessee Valley Authority 2pp 22407 015 24) Fiche 50-259,84/02/15,8402280489
- --8402280543 Notice of violation from insp on 830726-0825 * Region 2, Office of Director 83/09/21 2pp 22407 017 24X Fiche 50-259,84/02/15,8402280489
- --8402280352 IE Insp Repts 50-259/83-33.50-260/83-33 & 50-276/83-33 on 830726-0825 Noncompliance noted failure to have equipment installed in accordance w/drawings.follow leak detection monitoring procedures & update as-constructed drawings FAULK.G L Region 2. Office of Director CANTRELL.F S Division of Project & Resident Programs 83/09/20 14pp 22407 019 24X Fiche 50-259,84/02/15,8402280489
- 8402280022 Forwards response to IE Bulletin 84~01 re cracks in BWR Mark I containment vent headers Testing for cracks performed using differential pressure data No cracks observed MILLS.L M Tennessee Valley Authority 84/02/16 O'REILLY, J P Region 2, Office of Director 2pp 22401 110 24X Fiche 30-259.84/02/16.8402280022
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below ManuPacturer Recommended Value " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 114pp 22364 024 24X Fiche 50-000-84/02/21,8401190062
- 8402280132 Confirms 840224 enforcement conference at Region II ofc to discuss bypassing rod sequence control sys during shutdown to isolation of drywell to suppression pool differential pressure instruments, per 840217 telcon
 O'REILLY, JP Region 2, Office of Director 84/02/21 PARRIS, H G
 Tennessee Valley Authority 2pp 22400 290 24X
 Fiche 50-259,84/02/21,8402280132
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies" Svc list encl Svc list encl JURDANAE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/24. Consolidated Edison Co. of New York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Beat Valve Seals "
 Svc list encl
 JORDAN, EL Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp. 22431 060 24X fiche 50-000,84/02/27,8401190067

- R Periodic operating reports & related correspondence
- 8402070302 "NPDES Discharge Monitoring Rept.Oct-Dec 1983 " * Tennessee Valley Authority 83/12/31 54pp 22099 001 24X Fiche 50-259, 83/12/31, 8402070302
- S Reportable occurrences, LERs & related correspondence
- 8402100421 "Rept Concerning Effects of Control Bys Failures on Overfill & Overcooling Events at Browns Ferry." Interim rept
 BAXTER.D E . BRUSKE.S J . MORKEN.D J E0&G. Inc FIN A-6477
 EGG-EA-6333 83/10/31 Division of Safety Technology 157pp
 22211 168 24X Fiche 50-259.83/10/31.8402100421
- 8402020033 Partial response to FDIA request for documents re evaluation or review of design.comst, scheduling.comst & licensing of facilities from 1977 to present Forwards App A & B documents
 FELTUN.J M Division of Rules and Records 83/11/04 ZACK.A M Barris, Sott. Denn & Driker lipp 22079 208 24X
 Fiche 90-000.83/11/04.8402020033
- --8402020092 Submits 820112 daily staff notes re PND-II-82-006 & PND-II-82-007 & review of changes to GA organization at plant site & matters re ongoing soil settlement hearing Related info encl
 DIRCKS.W J Office of the Executive Director for Operations 82/01/13 PALLADING, GILINSKY, BRADFORD Commissioners 23pp 22081 118 24X Fiche 50-000.83/11/04.8402020033
- 8402140218 LER 83-071/03L-0 on 831212.analyst discovered broken vacuum pump belt on reactor & turbine vent monitor 1-RM-90-250 Caused by normal wear due to continuous operation 8td V-belt for Schwitzer Model 325 air pump replaced W/840110 ltr SHARPE,T J. COFFEY.J A Tennessee Valley Authority 84/01/10 O'REILLY.J P. Region 2. Office of Director 7pp 22229 350 24% Fichs 50-259.84/01/10.8402140218
- 8402030267 LER 84-002-00 on 840103 routine surveillance testing revealed that setpoints for pressure switches PS-64-57A-D not within Tech Spec limits Caused by pressure switch drift Surveillance test will be revised M/840124 ltr JUNES, 9 T Tennesser Valley Authority 84/01/24 4pp 22069 335 24X Fiche 50-239,84/01/24,8402030269
- 8402030471 LER 83-072/03L-0 on 831227, mean sea level wind speed recorder XR-90-104 read zero Caused by ice formation on wind speed sensor H/840125 ltr
 IRBY, 8 . COFFEY, J A Tennessee Valley Authority 84/01/24
 O'REILLY, J P Region 2. Office of Director 3pp 22066 263 24X
 Fiche 50-239,84/01/24,8402030471
- 8402060472 LER 84-004-00 on 840106, during manual shutdown of main turbine, control rods inserted to reduce power Reactor mode switch moved from run to startup resulting in half scram Caused by personnel stror Personnel counseled W/840127 ltr. JONES, G T Tennesses Valley Authority 84/01/27 3pp. 22083.106 24X Fichs 50-239.84/01/27,8402060472
- 8402130434 LER 84-003-00 on 840117.one of three standby gas treatment trains had flow below design Caused by manual discharge dampers on trains A & C being off marked positions Dampers returned to proper position W/840206 ltrs 8HITH.D L . JONES 9 T Tennessee Valley Authority 84/02/06. 3pp 22202 080 24X Fichs 50-239.84/02/06.8402130434
- 8402140415 LER 84-003-00.on 840117, during testing of standby gas treatment (880T) trains, one of three trains had flow below design due to misad justed discharge dampers on trains A & C Cause of misalignment unknown W/840206 ltr BHITH.D L . JUNES 9 T Tennessee Valley Authority 84/02/06 3pp 22227:113 24X Fiche 50-257,84/02/06,8402140415
- B402170142 LER BFRD-50-259/B4006 will not be used Event being combined w/LER 50-296/B4002

 JDNEB,0 T Tennessee Valley Authority 84/02/10 Record Services Branch (Document Control Desk) 1p 22299.008. 24X

 Fichs: 50-259,84/02/10,8402170142
- 84002210198 LER 84-005-00 on 840122, during surveillance testing, satpoints for pressure switches P8-64-560 & C not within Tech Spec 3 2 A limits Caused by setpoint drift. Procedures revised H/840213 ltr MORKIN.K M , JONES G T. Tennessee Valley Authority 84/02/13 4pp 22316 324 24X Fiche 50-259,84/02/13,8402210198
- 8402170274 PNO-TI-84-013 on B40214, inboard shutdown cooling suction valve 1-74-48 failed to open Gaused by electrical problems Licensee declared alert due to loss of shutdown cooling Drywell will be entered to manually open valve VERRELLI.D. LEWIS, R. Region 2. Office of Director 84/02/14. ip 22277 163 24% Fiche 50-259, 84/02/14, 8402170274

- 8402220059 PNO-II-84-013A on 840214, reactor remained stable in cold shutdown, w/reactor coolant temp at 199 F & reactor pressure atmospheric for repair of shutdown cooling suction valve Unit will remain in alert status VERRELLI.D M, LEWIS.R C Region 2. Office of Director 84/02/14 2pp 28337-325 24X Fiche 50-259,84/02/14,8402220059
- B402240147 LER 84-009-00 on 840130, factor Kf used in critical power ratio calculations by process computer in serror by approx 2 5% at recirculation flows of approx 75% Caused by loading core dump generated prior to factor correction w/840217 ltr 8HITH, D L., JONES, G T Tennessee Valley Authority 84/02/17 3pp 22374 343 24% Fiche 50-259,84/02/17,8402240147
- 8402240157 LER 84-007-00 on 840127, during routine checks, operator observed decrease of pressure on two containment atmospheric dilution tanks Caused by improper valve lineup Operating instruction revised to verify valve alignment W/840217 ltr WALKER, J B , JONES, O T Tennessee Valley Authority 84/02/17 3p 22374 348 24X Fiche 50-259, 84/02/17, 8402240157
- 8402270376 Updated LER 83-018/03L-1 on B30325, standby gas train B inoperable. Caused by erratic flow switch F8-65-42A Switch replaced Paddle type switches to be replaced w/differential pressure switches W/undated Itr CARTER, S. JONES, O.T. Tannessee Valley Authority 84/02/27 0'REXLLY, J.P. Region 2, Office of Director 3pp 22391 176 24X Fiche, 50-259, 84/02/27, 8402270376
- 840227041: Updated LER 83-029/03L-1 on 830604, during standby gas treatment sys operability test, train 8 discovered inoperable Caused by erratic McDonnel & Miller Model AF-1 flow switches Damper adjusted W/ondated ltr CARTER, 8 D., JONES, 0 T Tennessee Valley Authority 84/02/27 O'REILLY, J P Region 2. Office of Director 3pp 22390 241 24X Fithe 50-239, 84/02/27, 8402270411

V. Operator Examinations

- 8402010337 Notification of contract execution "Use of TVA Reactor Simulator Facilities at Chattanogas TN for Training on Browns Ferry, Sequoyah & Bellefonte Simulators " JESSUP, B Technical Assistance Contracts Branch FIN B-8717 83712/27 SHOWE, B K Director's Office, Office of Inspection and Enforcement, 1p. 22057 227 24X Fiche 50-000,83/12/27,8402010337
- --8402010346 Ltr Contract NRC-05-84-153, "Use of TVA Reactor Simulator Facilities at Chattanoga, TN for Training on Browns Forry, Bequoyah & Bellefonte Simulators," awarded to TVA.
 MORTON, K.V. Technical Assistance Contracts Branch FIN B-8717
 B3/12/27 JOHNSON, R. J. Tennessee Valley Authority. 6pp
 22059 230 24X Fiche, 50-000, 83/12/27, 8402010337
- B402140274 Confirms arrangements for NRC administration of requalification exams on 840316-19 Exams intended to evaluate effectiveness of actions taken to strengthen operator training program since 83118 requalification exam VERRELI, ID.M. Division of Project & Resident Programs 84/01/17 OREEN, H. J. Tennessee Valley Authority. 3pp 22228-191, 24X Fithe 50-259.84/01/17,8402140274.
- B402140474 Forwards summary of B40118 meeting w/util re plans for strengthening program for requalification of licensed operator & senior operator personnel Subjs discussed & meeting attendees provided LEMIS. R C Division of Project & Resident Programs B4/02/03 PARRIB. H Q. Tennessee Valley Authority 2pp 22221 106. 24X Fiche: 50-259, 84/02/03, 8402140494.
- B4022B0234 Informs of review of 1983 accelerated requalification training program lesson plans Plans based on Learning objectives show significant improvement over earlier plans NRC will not restrict scope of questions on exam. VERRELLI,D M Division of Project & Resident Programs 84/02/15 PARRIE,H Q, Tennesse Valley Authority 2pp. 22399,240 24% Fiche: 50-259,84/02/15,8402280234
- DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2
 F Becurity, medical, emergency & fire protection plans
- 8402280411 Forwards IE Enforcement Conference Repts 50-259/83-58, 50-260/83-58 & 50-276/83-58 on 831216 Meeting held to discuss apparent security violation & operation w/undernated discuss apparents HX O'REILLY, J.P. Region 2, Office of Director 84/01/05 PARRIS, H. G Tennessee Valley Authority 2pp. 22407, 143 24X Fiche: 30-259, 84/01/05, 8402280411.

- 8402140180 Confirms NRC 840118 telcon re 840119 meeting in Region II ofc to discuss security activities LEWIS.R C Division of Project & Resident Programs 84/01/18 PARRIS,H G Tennessee Valley Authority ip 22230 299 24x Fiche 50-259.84/01/18.8402140180
- 8402060382 Forwards Rev 7 to generic security personnel training & qualification plan Rev withheld (ref 10CFR73 21)
 MILLS,L M Tennessee Valley Authority 84/01/19 G'REILLY, J P
 Region 2, Office of Director 1p 22086 317 24X
 Fiche 50-000,84/01/19,8402060382
- B402210301 Revised emergency plan implementing procedures, including Procedures BFN-REP re radiological emergency plan & BFN-IPD re implementing procedures document W/B40210 1tr MILLS.L M Tennessee Valley Authority B4/01/20 O'ABILLY, J P Region 2, Office of Director 128pp 22315 076 24X Fiche 50-257,84/01/20,8402210301
- 8402140384 Forwards summary of 840113 meeting in Region II ofc re emergency protective actions required by NUREG-0654 & clarified by IE Info Notice 83-28 VERRELLI,D M Division of Project & Resident Programs 84/01/26 PARRISH G Tennessee Valley Authority 4pp 22220 042 24X Fichs 50-000,84/01/26,8402140384
- B402130316 Forwards Rev B to generic security personnel training & qualification plan. Rev withheld MILLs.L M Tennessee Valley Authority B4/01/27 D'REILLY.J P Region 2, Office of Director 1p 22197 149 24X Fiche 50-000.84/01/27.8402130316
- B402130490 Forwards rev to physical security plan Rev withheld (ref 10CFR73-21) MILLB,L M Temnessee Valley Authority 84/01/30 O'REILLY,J P Region 2, Office of Director ip 22200 256 24x Fiche 50-259,84/01/30,8402130490
- 8402140275 Forwards summary of 840117 meeting w/util in Region II ofc re improvement of security effectiveness & other securityrelated topics LEWIS:R C Division of Project & Resident Programs 84/02/01 PARRIS:H G Tennessee Valley Authority 4pp 22228 271, 24X Fiche 50-000-84/02/01.8402140275
- 8402210278 Revs to Muscle Shoals emergency control ctr implementing procedures including Procedure MSEC IP-1 re notification of unusual event, alert or transportation accident & MSEC IP-2 re site emergency or emergency director W/840210 ltr MILLB, L M Tennessee Valley Authority 84/02/02 O'REILLY, J P Region 2, Office of Director 76pp 22315.001 24X Fiche 50-000.84/02/02.8402210278
- E402130354 Ack receipt of util E31006 & 1121 ltrs transmitting rev to facility security plan Rev consistent w/provisions of 10CFR50 54(p) & scceptable LEWIG.R C Division of Project & Resident Programs E4/02/08 PARRIS.H G. Tennessee Valley Authority 3pp 22197 285 24x Fiche, 50-259, 84/02/08, 8402130354
- 840R15022i Forwards evaluation of TVA radiological amergency preparedness plan for Browns Ferry for 831113-16 exercise State of AL & Ludesrdals, Lawrence, Limestone & Morgan Counties participated KRIMM, R.W. Federal Emergency Management Apency 84/02/08 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 1p 22244 251 24X Fiche 50-257,84/02/08,8402150221
- --8402150237 Evaluation of TVA radiological emergency preparedness plan for Browns Ferry for 831115-16 exercise * Federal Emergency Management Agency. 83/12/16 28pp 22244 252 24X Fichs 50-259,84/02/08.8402150221.
- 8402280489 Ack receipt of 840126 ltr informing NRC of add1 steps taken to correct violations noted in IE Imap Repts 50-259/83-33; 50-260/83-33 & 50-276/83-33 LEMIB.R C. Division of Project & Resident Programs 84/02/15 PARRIS.H Q Temmessee Valley Authority ip, 22407 Q01 24X Fiche: 50-259:84/02/15.8402280489
- --B402280552 IE Insp Repts 50-259/83-33, 50-260/83-33 & 50-296/83-33 on B30726-0825, Noncompliance noted failure to have equipment installed in accordance w/drawings, follow leak detection monitoring procedures & update as-constructed drawings FAULK, G.L. Region 2, Office of Director B3/09/20 14pp 22407-019. 24X Fiche 50-259,84/02/15,8402280489

J Insurance & indemnity information

- 8402210231 Forwards Endorsements 71 & 72 to NELIA Policy NF-198 & Endorsements 60 & 61 to MAELU Policy MF-66 Amended site description also encl DUCK.JR Marsh & McLennan, Inc. 84/02/13 SALTZMAN, J. Assis Director for State & Licensee Relations 7pp 22315 299 24X Fiche 50-259.84/02/13.8402210231 ALTZMAN, J Assistant 22315 299 24X
- P Operating license stage documents & correspondence
- 8402090310 "Browns Ferry Other Transients Failure Modes & Effects Analysis & Rejected Bys Justification Rept," preliminary Analysis a nogerous - 5rept
 BAXTER, D E , BEAHH, D M , BRUSKE, B J EG&Q, Inc FIN A-6477
 EGG-EA-6296 DRFT. B3/05/31 NRC - No Detailed Affiliation Given
 68pp 22187 271. 24x Fiche.50-259,83/05/31,8402070310

- 8402010408 Forwards notice of consideration of issuance of amends to Licenses DPR-33,DPR-52 & DPR-68 & groposed NSHC determination & opportunity for hearing re operation w/one recirculation loop out of svc CLARK.R J Operating Reactors Branch 2 84/01/14 PARRIB.H G Tennessee Valley Authority 2pg 22062 001 24X Fiche 50-259.84/01/16.8402010408
- --8402010417 Notice of consideration of issuance of amend to Licenses DRR-3G, DRR-52 & DRR-468 & proposed NSHC determination & apportunity for hearing Amends permit operation w/one recirculation loop out of svc VASSALLO, D B Operating Reactors Branch 2 84/01/16 6pp 22062 003 24X Fiche 50-257,84/01/16,8402010408
- B402090303 Requests rev to pressure temp curves using conservative assumptions or demonstration that predicted neutron irradiation damage will be less than predicted for reactor vessel surveillance mat!

 VASSALLO, D B Operating Reactors Branch 2 84/01/23 PARRIS, H O Tennesses Valley Authority 3pp 22177 348 24X

 Fiche 50-259,84/01/23,8402090303
- 8402140392 Confirms 840130 mgt meeting in Atlanta. OA to discuss past & planned mgt changes, per 840123 telcon
 LEWIB.R C Division of Project & Resident Programs 84/01/24
 PARRISH O Tennessee Valley Authority ip 22220 331 24X
 Fiche 50-259.84/01/24,8402140392.
- 8402130541 Forwards strate to Amends 94,87 & 60 to Licenses DPR-33, BPR-52 & DPR-68, respectively, revising Tech Specs sent on CLARK, R J Operating Reactors Branch 2 84/01/25 PARRIS, H G Tennesse Valley Authority 2pp 22214 331 24X Fiche 50-259,84/01/25,8402130541
- ~-8402130552 Amends 94.87 & 60 to Licenses DPR-33, DPR-52 & DPR-68, respectively, revising errors in Tech Specs sent on 831227 * NRC No Batailed Affiliation Given 84/01/25 12pp 22214 333 24X Fiche 30-259,84/01/25.8402130541
- B402070206 Advises that date of B40321 acceptable for meeting w/NRC to discuss program plan for detailed control room design reviews Concurrence on meeting date requested MILLS, L. M. Tennassev 241eg Authority 84/02/01 ADENSAM.E. Licensing Branch 4 1p 32102 212 24X Fiche 50-000, 84/02/01,
- 8402140451 Notifies that response to Reg Quide 1.97 will be submitted 102140401 Notifies that response to the S04020.

 by 840430.

 billS.L M Tennessee Valley Authority 84/02/06 DENTON, H R. Dffice of Nuclear Reactor Regulation, Director ip 22227 111 Fiche 50-259, 84/02/06, 8402140451
- 8402210071 Informs NRC of need for specific Tech Spec rev for plant Reamphasizes concerns re overall backlog of Tech Spec requests outlined in 630627 1tr. MILLS.L.M. Tennessee Valley Authority. 84/02/13 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 22317 284. 24X Fiche-50-259,84/02/13,8402210071
- 3402280224 Responds to RM Diggs 840210 ltr re determination of fees for facility Util agrees w/fee determination & will submit fee by wire transfer facility util agrees 6.7.7
 by wire transfer
 MILLS.L M Tennesser Valley Authority 84/02/
 License Fee Hanagement Branch 1p 22399, 233
 Fiche 50-259, 84/02/23, 8402280224 84/02/23 MILLER, W O 24X

Q Inspection reports, IE Bulletins & correspondence

- 8402140352 Forwards IE Insp Repts 50-259/83-54, 50-260/83-54 & 50-276/83-54 on 831212-16 No violations or deviations noted VERRELLI, D M Division of Project & Resident Programs 84. PARRES, H G Tennessee Valley Authority 2pp 22221 242 Fiche 50-259,84/01/03,8402140352 B4/01/03
- --B402140358 IE Insp Repts 50-259/83-54,50-260/83-54 & 50-296/83-54 on 831212-16 No violations or deviations noted Major areas inspected independent reverification of inservice insp work activities & IE Bulletin 83-02 COLEY, J. Region 2, Office of Director BLAKE, J. Division of Engineering & Operational Programs 83/12/29, App 22221 244 24X Fiche 50-259,84/01/03.8402140352
- 402280411 Forwards IE Enforcement Conference Repts 50-259/83-58, 50-260/83-58 & 50-296/83-58 on 831216 Meeting held to Bistuss apparent security violation & operation w/underrated diesel generator HX O'REILLY, J P Region 2. Office of Director 84/01/05 PARRIS, H Q Tennesses Valley Authority 2pg 22407 143 24X Fiche 50-259,84/01/05,8402280411
- --8402280417 IE Enforcement Conference Repts 50-259/83-58,50-260/83-58 & 50-296/83-58 on 831216 Major areas discussed acceptability of HX on diesel generator & mod to scram discharge instrument vol CANTRELL,F S Division of Project & Resident Programs, 84/01/03 5pp 22407 145 24X Fiche 50-259,84/01/03,8402280411
- 8402050119 Forwards SER of masonry wall design.per IE Bulletin 80-11 Resvaluation of design of four unacceptable walls & proposed plans to upgrade walls requested within 120 days VASSALLO,D B Operating Reactors Branch 2 84/01/16, PARRIS,H G Tennessee Valley Authority 2pp 22103 176 24X Fiche 50-257,84/01/16,8402060119
- --8402060144 Safety evaluation re masonry wall design, per IE Bulletin 80-11 W/listed exceptions, wall integrity & performance of required safety functions will not be impaired * Office of Nuclear Reactor Regulation, Director 84/01/16 2pp 22103 198 24X Fiche 50-259.84/01/16.8402060119
- --8309270095 "Masonry Wall Design (B-59). TVA Browns Ferry Nuclear Plant, Units i.2 & 3," technical evaluation rept LE,A K Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-257 83/09/26 CHOKEHI,N C. NRC No Detailed Affiliation Given 31pp 22111 203 24X Fiche. 50-259, 84/01/16, 8402060119
- B402140106 Ack receipt of B40107 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-257/83-52, 50-260/83-52 & 50-296/83-52. VERRELLI.D M Division of Project & Resident Programs. 84/01/19, PARRIS.H 0 Tennessee Valley Authority 1p 22217:040 24X Fiche 50-259, 84/01/19, 8402140105
- --B402140112 Responds to NRC B31208 ltr re violations noted in IE Insp Repts 50-259/83-52,50-260/83-52 & 50-296/83-52 Corrective actions plant procedure for control room abandonment revised to require suitches be checked for desired alignment, MILLS, L M Tennesses Valley Authority, 84/01/09 O'REILLY, J, P, Region 2, Office of Director 4pp 22219 041 24X Fishe 50-259,84/01/19,8402140106
- -8402140126 Notice of violation from insp on 831026-1125 * Region 2, Office of Director 83/12/08, ip 22219-047, 24X Fiche 50-259,84/01/19,8402140106
- --8402140136 IE Insp Repts 50-259/83-52.50-260/83-52 & 50-296/83-52 on 831206-1125. Violations noted, failure to perform annual review of industrial security program & failure to have procedure to align backup control switches FAULK, Q L., CANTRELL.F S Region 2, Office of Director 83/12/07. 7pp. 22219 048. 24X Fiche: 50-259.84/01/19.8402140106 B3/12/07.
- 8402140243 Ack receipt of 831221 supplemental ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-12.50-260/83-12 & 50-296/83-12. O'REILLY, J.P. Region 2, Office of Director. 84/01/20, PARRIS, H. Q. Tennessee Valley Authority ip 22220 278 24X Fiche. 50-239, 84/01/20, 8402140243

- --8402140252 Responds to NRC B31115 ltr re violations noted in IE Insp Repts 50-259/B3-12.50-260/B3-12 & 50-296/B3-12 Corrective actions.radiological incident repts issued & employees instructed to comply w/requirements re dose rate instrument HILLB.L M Tennessee Valley Authority B3/12/21 O'REILLY.J P Region 2, Office of Director Spp 22220 299 24X Fiche 50-259, B4/01/20, B402140223
- --B402140243 Ack receipt of 830829 supplemental response to 830422 notice of violation in IE Insp Repts 50-259/83-12, 50-260/83-12 & 50-296/83-12 NRC continues to believe violations re dose rate instruments occurred O'REILLY, J.P. Region 2. Office of Director 83/11/15 PARTIS, H.O. Tennesses Valley Authority 2pp 22220 302 24X Fiche 50-259,84/01/20,8402140243
- --8402140271 Ack receipt of B30829 supplemental response informing NRC of steps taken to correct violations noted in IC Insp. Repts 50-259/83-12, 50-260/83-12 & 50-296/83-12 Info being evaluated LEMIS.R C Division of Project & Resident Programs 83/10/14 PARRIB.H G Tennessee Valley Authority ip 22220 304. 24X Fichs. 50-259, 84/01/20, 8402140243
- --8402140275 Forwards supplemental response to NRC 830727 ltr reviolations in IE Insp Rapts 50-259/83-12.50-260/83-12 & 50-294/83-12. MILLS.L.M. Tennessee Vallay Authority 83/08/29 0'REILLY.J P Region 2. Office of Director 4pp 22220 305 24% Fiche 50-259,84/01/20.8402140243.
- 8312120153 IE Info Notice 84-04. "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/01/25 Consolidated Edison Co. of New York, Inc. 120pp. 22058 001 24X Fiche 50-000,84/01/25,8312120193
- 8402140166 Forwards revised response to IE Bullstin 93-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators," per 830615 & 1107 ltrs Valve integrity verification will be performed by disassembly.
 MILLS.L. M. Tennessee Valley Authority 84/01/25, O'REILLY, J. P. Region 2, Office of Director 2pp. 22217;317 24%
 Fiche 50-259.84/01/25,8402140166
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list and JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc. 119pp. 22114 179 24X Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01, "Gracks in BWR Mark I Containment Vent Headers." Svc list encl DEYOUNG,R.C. Director's Office, Office of Inspection and Enforcement. 84/02/03. Consolidated Edison Co. of New York, Inc 102pp. 22177 156. 24X Fiche. 50-000. 84/02/03, 8401190017.
- 8402140073 Ack receipt of supplemental 840123 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-289/83-44, 50-280/83-44 & 50-296/83-44.

 D'REILLY, J P Region 2, Office of Director. 84/02/03 PARRIS, H O Tennessee Valley Authority. 1p 22218; 218. 24X Fiche: 50-259, 84/02/03, 8402140093.
- --8402140104 Supple response to NRC 831230 ltr re violations noted in IE Insp Repts 30-259/83-44,50-260/83-44 & 50-296/83-44 Corrective actions monthly close program modified so correct manth ending date assigned to each TLD badge MILLS; L M. Tennessee Valley Authority, 84/01/23, 0'REILLY, J P Region 2, Office of Director 3pp 22218,219, 24X Fiche 50-259,84/02/03,8402140093
- --8402140110 Ack receipt of 831220 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-44, 50-260/83-44 & 50-296/83-44 O'REILLY, J. P. Region 2, Office of Director. 83/12/30. PARRIS. H. O. Tennessee Valley Authority. 1p. 22218: 222 24X Fiche: 50-259, 84/02/03, 8402140093
- --8402140132 Responds to NRC 831125 ltr re violations noted in IE Insp. Repts 50-259/83-44,50-260/83-44 & 50-276/83-44. Corrective actions figt Bys Development Branch contacted to initiate software changes to prevent future occurrences.

 MILLS.L.M Tennessee Valley Authority, 83/12/20, 0'REILLY, J. P. Region 2. Office of Director. Spp. 22218'223, 24X Fichs: 50-259,84/02/03,8402140093
- --8402140142 Forwards IE Insp Repts 50-259/83-44.50-260/83-44 k 50-296/83-44 on 831025-28 & notice of violation O'REILLY, J. F. Region 2, Office of Director. 83/11/25. PARRIS, H. 9 Tennessee Valley Authority, 2pp 22218, 226, 24X Fiche: 50-259, 84/02/03, 8402140093.

- --8402140148 Notice of violation from insp on 831025-28 * Region 2, Office of Director 83/11/25 ip 22218 228 24X Fiche 50-259,84/02/03,8402140093
- --B402140164 IE Insp Repts 30-259/B3-44.50-260/B3-44 & 50-276/B3-44 on 831025-28 Violation noted subcontractor employee received dose of 3,059 mrem whole body during Third Guarter 19B3 PAULK, G L . BUTCHER, R C Region 2, Office of Director CANTRELL, F S Division of Project & Resident Programs 83/11/17 4pp 22218 227 24X Fiche 50-259,84/02/03,8402140093
- 8402140420 Ack receipt of 840110 ltr informing NRC of steps taken to correct deviation noted in IE Insp Repts 50-259/83-41, 50-260/83-41 & 50-296/83-41
 VERRELLI, D M Division of Project & Resident Programs 84/02/03 PARRIS. H 0 Tennessee Valley Authority ip 22221 224 24X
 Fichs 50-259,84/02/03.8402140420
- --B402140424 Responds to NRC 831202 ltr re deviation noted in IE Insp Repts 50-259/83-41.50-260/83-41 & 50-276/83-41 Corrective actions Radiography Procedure N-RT-I revised re layout control Technical std rev will be issued on 840402 MILLS:L M. Tennessee Valley Authority 84/01/10 0'REILLY.J P Repion 2. Office of Director 2pp 22221 225 24X Fiche 50-259,84/02/03,8402140420
- --8402140429 Forwards IE Insp Repts 50-259/83-41, 50-260/83-41 & 50-296/83-41 on 831025-28 & 1101-04 & notice of deviation VERRELLI.D M Division of Project & Resident Programs 83/12/02 PARTS.H Q Tennessee Valley Authority 2pp 22221 227 24X Fichs 50-259,84/02/03,8402140420
- --8402140433 Notice of deviation from insp on 831025-28 & 1101-04 * Region 2, Office of Director 83/12/02 ip 22221 R29 24% Fiche 50-259,84/02/03,8402140420
- --8402140443 IE Insp Repts 50-259/83-41,50-260/83-41 & 50-296/83-41 on 831025-28 & 1101-04 Deviation noted failure to take action to preclude recurrence for Violation 81-36-04 re radiographic layout & grinding control GIRARD,E H. COLEV, J. L. Region 2. Office of Director BLAKE, J. Division of Engineering & Operational Programs 83/11/28 10pp 22221 230 24% Fichs 50-259,84/02/03,8402140420
- 8402280192 Confirms 840217 enforcement conference at Region II ofc to discuss bypassing of rod sequence control sys during shutdown & isolation of drywell to suppression pool differential pressure instruments.per 840207 telcon. O'REILLY.J P Region 2. Office of Director. 84/02/09 PARRIS.H O Tannessee Valley Authority 2pp 22400.256 24X Fiche.50-239.84/02/09.8402280192
- B401170041 IE Info Notice 84-07, "Lessons Learned From NRC Insps of Fire Protection Bafe Shutdown Bys (IOCFR50. App R) " Svc list enc!

 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc. 124pp. 22365 259, 24X Fiche 50-000.84/02/13,8401170041
- 8401190039 IE Info Notice 84-08, "IOCFR30 7, 'Employee Protection '"

 8vc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103), 84/02/14, Consolidated Edison Co of New
 York, Inc. 119pp. 22365.141 24X Fiche 50-000.84/02/14, 8401170039
- 8401170045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Heatinghouse Type 8A-1 Differential Relays" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Goneolidated Edison Co of New York, Inc. 1189p 22366:142 24X Fiche: 50-000, 84/02/15, 8401170045
- B402280489 Ack receipt of 840126 ltr informing NRC of add1 steps taken to correct violations noted in IE Insp Repts 50-259/83-33, 50-226/83-33 & 50-296/83-33 LEWIB, R. C. Division of Project & Resident Progress 84/02/15 PARRIS: H 0. Tennessee Valley Authority 1p. 22407 001 24X Fiche. 50-259, 84/02/15, 8402280489
- --8402280498 Forwards supplemental response to NRC 830921 ltr reviolations noted in IE Insp Repts 50-259/83-33.50-260/83-33 & 50-260/83-33 M/o end:

 MILLS:L M. Tennessee Valley Authority 84/01/20 0'REILLY, J. P. Region 2. 06fice of Director 1p 22407.002, 24X Fichs 50-259, 84/02/15, 8402280489.
- --B402280504 Suppls response to NRC 830921 ltr re violations noted in IE Insp Repts 50-259/83-33, 50-260/83-33 & 50-296/83-33 Corrective actions Tech Spec amend request submitted for Units 2 & 3 re APRH gain adjustments HAMMER, D 8 Tennesses Valley Authority. B4/01/26 O'REILLY, J. P Region 2, Office of Director 2pp 22407'003 24x Fiche, 50-259, 84/02/15, 8402280489

- --8402280512 Ack receipt of 831024 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-259/83-33, 50-260/83-33 & 50-246/83-33 Supplemental response requested for Item C re APRH gain settings LENIG.R C Division of Project & Resident Programs 83/12/16 PARTB.H O Tennessee Valley Authority 2pp 22407 005 24X Fichs 50-259,84/02/15,8402280489
- --8402280520 Ack receipt of 831024 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-33, 50-240/83-33 & 50-296/83-33 Response under review LEMIS.R C Division of Project & Resident Programs 83/11/09 PARRIS.H G Tennessee Valley Authority 1p 22407 007 24% Fiche 50-259.84/02/15.8402280489
- --8402280530 Responds to NRC 830921 ltr re violations noted in IE Insp Repts 50-259/83-33.50-260/83-33 & 50-296/83-33 Corrective actions shift technical advisor log book modified to assure required info gathered & cable tray deficiencies corrected HILLGLL B Tennessee Valley Authority 83/10/24 0'REILLY, J P Resion 2. Defice of Birector 7pp 22407 008 24X Fishe 50-259,84/02/15.8402280489
- ~-8402280340 Forwards IE Insp Repts 50-259/83-33.50-260/83-33 & 50-294/83-33 on 830726-0825 & notice of violation LEWIS,R C Division of Project & Resident Programs 63/09/21 PARRIS,H G Tennessee Valley Authority 2pp 22407.013 24% Fiche 50-259.84/02/15.8402280489
- --8402280543 Notice of violation from insp on 830726-0825 * Region 2. Office of Director 83/09/21 2pp 22407 017 24x Fithe 50-259,64/02/15,840280489
- --8402280552 IE Insp Repts 50-289/83-33, 50-260/83-33 & 50-296/83-33 on 830726-0885 Noncompliance noted faiture to have equipment installed in accordance w/drawings follow lack detection monitoring procedures & update as-constructed drawings FAULK, 0 L Region 2, Office of Director, GANTRELL, F & Division of Project & Resident Programs 83/09/20 14pp 22407 019 24X Fiche 50-259,84/02/15,8402280489
- 8402280022 Forwards response to [E Bulletin 84-0] re cracks in BWR Mark I containment vent headers Testing for cracks performed using differential pressure data No cracks observed.

 MILLS.L.M. Tennessee Valley Authority 84/02/16 0'REYLLY, J.P. Region 2, Office of Director 2pp 22401 110 24X

 Fichs 50-259.84/02/16.8402280022
- 8401170062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Valve " Svc list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post #30103). 84/02/21. Consolidated Edison Co. of New York, Inc. 116pp 22366 024 24x Fiche 50-000.84/02/21,8401170062
- 8402280132 Confirms 840224 enforcement confirmed at Region II ofc to discuss bypassing rod sequence control sys during shutdown & isolation of drywell to suppression pool differential pressure instruments, per 840217 telcon 0'REILLY, J P. Region 2. Office of Director 84/02/21 PARRIS, H C Tennessee Valley Authority 2pp 22400.270 24X Fiche 50-259,84/02/21,8402280132
- 8401190056 IE Info Notice 84-11, "Training Program Deficiencies,"

 8vc list encl

 JORDAN, E.L. Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/02/24 Consolidated Edison Co of New

 York, Inc. 115pp. 22430 304 24X Fiche 50-000,84/02/24,8401170056
- 8401190067 IE Info Notice 84-12. "Failure of Soft Beat Valve Seals " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/27. Consolidated Edison Co. of New Yark, Inc. 120pp 22431-040 24X Fiche 50-000.84/02/27,8401190067
- R Pariodic operating reports & related correspondance
- 8402070302 "NPDES Discharge Manitoring Rept.Oct-Dec 1983." * Tennesses Valley Authority 83/12/31. 54pp. 22099:001 24x Ficha 50-259.83/12/31.8402070302
- B Reportable occurrences, LERs & related correspondence
- 8402100421 "Rept Concerning Effects of Control Sys Failures on Overfill & Overcolling Events at Browns Ferry: "interia rept BAXTER: D E , BRUSKE, S J , MORMEN, D J E626, Inc FIN A-6477 E62-EA-6393 83/10/31. Division of 8afety Technology 157pp. 22211.168 24x Fiche 50-257,83/10/31,8402100421.

- 8402020033 Partial response to FOIA request for documents re evaluation or review of design, const. scheduling.cost & litensing of facilities from 1977 to present Forwards App A & B documents
 FELYON.J M Division of Rules and Records 83/11/04 ZACK,A H Barris. Sott. Denn & Driker lipp 22079 208 24X
 Fiche 50-000.83/11/04.8402020033
- --84020200092 Submits 820112 daily staff notes of PNO-II-82-006 & PNO-II-82-007 & review of changes to GA organization at plant site & matters or ongoing soil settlement hearing Related info encl
 DIRCKS, M J Office of the Executive Director for Operations 82/01/13 PALLADINO, GILINSKY, BRADFORD Commissioners. 23pp 22081 118 24% Fiche 50-000.83/11/04,8402020033
- 8402220154 Responds to FOIA request that 146 LERs be placed in PDR Forwards LERs listed on app Documents also available in PDR Remaining LERs were either canceled or not issued FELTON. J M Division of Rules and Records 83/11/30 JEFFERSON. 9 A APPILIATION NOT Assigned 2pp 22380 052, 24X Fiche 50-000,83/11/30,8408220154
- 8402140426 LER 83-080/03L-0 on 831214.while performing 81 4 t A-0, transmitter LT-85-450 found operating above Tech Spac limits Cause unknown Transmitter replaced Faulty transmitter sent to vendor for analysis W/840112 itr CHAMBERS.6 T, COFFEY.J A Tennessee Valley Authority 84/01/12 0'/REILLY.J P. Region 2. Office of Director 6pp 22228 288 24; Fiche: 50-240, 84/01/12, 8402140426
- 8402020R22 LER 84-001-00 on 840108 during RCIC flow testing RCIC failed to reach rated flow in required 30 s Caused by probable setpoint drift Electronic governor control systecaliby W/840127 ltr
 WALKER, J B . JONES, O T Tennessee Valley Authority 84/01/R7. Sep 22057 080 24X Fichs 50-260.84/01/27.8402020222
- 8402030215 Updated LER 83-074/03X-2 on 831105 & 10.during HPC1 initiation.inner diaphragm ruptured Cause not determined Further investigation will be conducted & correct stop valve balancing chamber pressure verified W/840127 itr WIDICK.R. WALKER, J. B., COFFEY. J. A. Tennessee Valley Authority 84/01/27 D'REILLY. J. P. Region 2. Office of Director Spp 22066 247 24X Fichs: 50-260, 84/01/27,8402030215
- 8402080154 LER 83-083/03L-0 on 831229, during normal operation, bydrogen analyser B hydrogen sample inlet pump discovered inoperable Cauted by seized bearing due to improper bearing clearance in Metal Bellows Corp motor PN 25626 W/840127 let CARTER, B D , COFFEY, J A Tennessee Valley Authority 84/01/27, D'REILLY, J P Region 2. Diffice of Director 3pp 22132 266 24% Fiche: 50-260, 84/01/27, 8402080154
- 8402080287 LER 83-084/03L-0 on 831229, strainer on pump C3 became restricted by debris & all flow lost to north header Caused by river debrie, Strainer cleaned & pump returned to operability W/640127 ltr
 MCPHERBON,P R , COPFEY,J.A Tennessee Valley Authority 84/01/27 d'REILLY,J P. Region 2, Opfice of Director 3pp 22131 268 24) Fiche 50-260,84/01/27,8402080287
- 8402140257 LER 84-002-00 on 840121, during surveillance testing, aperator did not ensure channel 8 primary containment isolation systems to before testing channel C Caused by operator error Operator counseled, W/840208 ltr SMITH, D L . JONES, 0 T Tennessee Valley Authority, 84/02/08 3pp 22227:163 24X Fiche 50-240, 84/02/08, 8402140257

V Operator Examinations

- 8402010337 Notification of contract execution. "Use of TVA Reactor Simulator Facilities at Chattanoega: TN for Training on Browns Ferry. Sequoyah & Bellafonta Simulators."

 JESSUP. B Technical Assistance Contracts Branch. FIN B-8717
 83/12/29 SHOWE: S K Director's Defice. Office of Inspection and Enforcement ip 22059 229 24X Fiche 50-000.83/12/29,8402010337
- --8402010346 Ltr Contract NRC-05-84-153. "Use of TVA Reactor Simpleter Facilities at Chattanooga, TN for Training on Browns Ferry. Sequoyeh & Bellefonte Simpletore." awarded to TVA MORTON, K V. Technical Assistance Contracts Branch FIN B-8717. 83/12/29 JOHNSON, R J. Tennsster Valley Authority 6pp. 22059 230 24X Fiche 50-000.83/12/29,8402010337.
- B402i40274 Confirms arrangements for NRC administration of requalification exams on B403i6-19 Exams intended to evaluate effectiveness of actions taken to strengthen operator training program since B31iiB requalification exam VERRELLI,D M Division of Project & Resident Programs 84/01/17. GREEN,H J Tempesses Valley Authority. 3pp 22228, 191. 24X Fiche-50-259,84/01/17.8402140274

- 8402140494 Forwards summary of B4011B meeting w/util re plans for strengthering program for requalification of licensed operator & senior operator personnel Bubys discussed & meeting attendees provided LEWIS.R C Division of Project & Resident Programs 84/02/03 PARRIB.H O Tennessee Valley Authority 2pp 22221 106 24X Fiche 30-259,84/02/03.8402140494
- B402280234 Informs of review of 1983 accelerated requalification training program lesson plans Plans based on learning objectives show significant improvement over earlier plans NRC will not restrict scope of questions on exam VERRELLI.D M Division of Project & Resident Programs 84/02/15 PARRIB.H 9 Tennessee Valley Authority 2pp 22399 240 24X Fiche 50-259,84/02/15,8402280234
- DOCKET 50-261 H B ROBINSON PLANT, UNIT 2
- : Security, medical, emergency & fire protection plans
- B402030341 Forwards revs to emergency plan & procedures MDRDAN,R E Caroline Power & Light Co B4/01/25 O'REILLY,JP Region 2, Office of Director 5pp 22067 140 24X Fiche 50-261,84/01/25,8402030341
- 8402280001 Forwards IE Insp Rept 50-261/83-36 on 83;211-840110 No violations or deviations identified VERRELLI.D M Division of Project & Resident Programs 84/01/27 UTLEY, E.E. Carolina Power & Light Co. 2pp 22401 154 24X Fiche 50-261,84/01/27,8402280001
- --B402280002 IE Insp Rept 50-261/83-36 on 831211-840110 No violation or deviations identified Major areas inspected Tech Spec compliance.plant tour.operations performance.ROs.site security.IE notice followup & emergency lighting review WEISE.8 Region 2. Office of Director BEMIS.P.R Division of Project & Resident Programs 84/01/26 12pp 22401 156 24X Fiche 50-261.84/01/27.8402280001
- B402140500 Forwards errata to IE Insp Rept 50-261/83-12, consisting of corrected Pages 4 & 5 to rept details LEWIS.R. C. Division of Project & Resident Programs. 84/02/03 UTLEV.E E Carolina Power & Light Co. 3pp 22221 109. 24X Fiche: 50-261,84/02/03,8402140500
- --8402140507 Erreta to IE Insp Rept 50-261/83-12 re containment air recirculation unit fan cooler leek & pipe alley fire detection instrumentation ** Region 2. Office of Director 84/02/03 2pp 22221 112 24X Fiche 50-261,84/02/03,8402140500.
- 8402130244 Revised emergency plan implementing procedures, including Procedures PEP-2004 re personnel.PEP-2005 re federal, state & county agencies & PEP-2004 re police, fire & medical phone numbers W/840210 ltr
 GAINEY.D., MURGAN.R E Carolina Power & Light Co. 84/02/03 G'REILLY.J.P. Region 2, Office of Director 20pp 22245 116 24) Fichs. 50-261,84/02/03,8402130244.
- 8402290234 Forwards "Fire Protection App R Bection III 0 Supplemental Submittal," describing substitution of manual actions & repairs & revising shutdown method to reflect use of refueling water storage tank UTLEY, E E Carolina Power & Light Co 84/02/06 VARQA, S A. Operating Reactors Branch i. 2pp 22424, 338, 24X Fiche 50-261,84/02/06,8402270234
- --8402270237 "Fire Protection App R Bection III G. Bupplemental Submittel." * Caroline Power & Light Co. 83/11/30. 100pp 22424*340 24X Fiche: 50-241,84/02/06.8402270234
- P. Adjudicatory correspondence
- 3402020210 Forwards NRC testimony on Contention 3 re cost-banefit analysis
 BACHMANN,R G. Hearing Branch i. 84/01/20 MARQULIES,M.B.,
 HETRICK,D L., KLINE, J.R. Atomic Safety and Licensing Board Panel
 ip. 22057:074, 24% Fiche:50~261,84/01/20,8462020210
- -B402020212 Testimony of L Lois & PN Randall on Contention 3 re reactor yessel ambrittlement LOIS, L. Core Performance Branch RANDALL, P. N. Materials Engineering Enach. 84/01/20. 10pp. 22057:075. 24X Fiche: 50-261,84/01/20,8402020210
- -8402020216 Testimony of EN Fields on Contention 3 re cost-benefit analysis in FEB FIELDS E. N. Division of Engineering. 84/01/20 9pp. 22007 105 24X Fichs 50-261,84/01/20,8402020210

- --B402020219 Testimony of PR Bemis SP Weise & DO Myers on Hartsville Contentions is & 16 re steam generator violations Prof qualifications encl BEMISP R: WEISE 8 P , MYERS DO NRC - No Detailed Affiliation Given B4/01/20 32pp 22057 114 24X Fiche 50-261 B4/01/20, 8402020210
- 8402060145 Requests addition of JC Rooff as authorized representative in steam generator repair proceeding Authorization encl MATTHEMS B A Hertsville Group 84/01/31 MARQULIES, M B Atomic Safety and Licensing Board Panel 2pp 22087 060 24% Fichs 50-261,84/01/31,8402060145
- 8402070156 Notice of appearance in proceeding Certificate of Syc encl* RUGFF, J C Hartsville Group 84/02/01 3pp 22103 046 24X Fiche 50-261,84/02/01,8402070196
- B402140079 Order dismissing adjudicatory hearing on application of util to amend license to permit repair of steam generators by replacement of major components Hartsville Group withdraw three contentions & one contention dismissed MARGULIES, M B Atomic Safety and Licensing Board Panel 84/02/10 Carolina Power & Light Co 2pp 22217 196 24X Fiche. 50-261,84/02/10,8402140079
- P Operating license stage documents & correspondence
- 8402090316 "HB Robinson Steam Generator Overfill Transient Failure Mode & Effects Analysis & Rejected Sys Justification Rept," preliminary rept BAXTER, D.E., BRUSKE, S.J., STROMBERO, H.M. EQ&O. Inc. FIN A-6477 EGG-EA-6282 DRFT \$3/05/31 NRC No Detailed Affiliation Given 47pp 22190 159 24% Fichs 50-261.83/05/31.8402090316
- 8402090324 "HB Robinson Overcooling Transient Failure Mode & Effects Analysis & Rejected Sys Justification Rept," preliminary rept BAXTER, D E , BRUSKE, S J EG&G, Inc FIN A-6477 EGG-EA-6897 DRFT B305/31 NRC - ND Detailed Affiliation Given 45pp 22187 145 24X Fiche 50-261.83/09/31.8402090324
- 8312120029 Generic Ltr 83-39 to representatives of utils re voluntary survey of licensed operators 8vc list encl EIBENHUT, D G Division of Licensing 83/12/08 Commonwealth Edison Co 12pp 22313 006 24X Fiche 50-000, 83/12/08, 8312120029
- 8402010252 Forwards SER re TMI Action Item II K 2 17, "Potential for Voiding in RCS During Transients " Voids generated in RCS during anticipated transients will not result in unacceptable consequences VARQA.S A Operating Reactors Branch 1 84/01/16 UTLEY.E E Carolins Power & Light Co 10pp 22047 287 24X Fichs 50-261.84/01/16.8402010252
- 8402010444 Responds to FOIA request for BECY-B3-288 & SECY-B3-443 to be placed in PDR SECY-B3-288 available in PDR BECY-B3-443 being placed in PDR Forwards SECY-83-443 FELTON, J M Division of Rules and Records 84/01/17, YENDUSKAS, J Nawman & Holtringer 1p 22061 272 24X Fiche. 50-000, 84/01/17, 8402010444
- --8402010453 Informs Commission of info obtained re flux reduction programs for pressurized thermal shock at lead plants, since 830225 inter(m rept (BECY 83-077) DIRCKS,W J. Office of the Executive Director for Operations BECY-83-443 83/10/28, 11pp 22061.273, 24X Fiche 50-000,84/01/17,8402010444
- 8402070524 Requests add1 info rm adequacy of station electric distribution sys voltages Draft safety evaluation encl Response required within 45 days of ltr data VARGA, 8 A Operating Reactors Branch 1 84/01/19 UTLEY, E E Carolina Power & Light Co 11pp 22171 329, 24X Ficha 50-261,84/01/19,8402070524
- 8402010410 Generic Ltr 64-04 to all operating PWR licensees, CP holders & applicants for CPs re safety evaluation of Hestinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops 8vc 1ist enci EIGENHUT, D. G. Division of Licensing 84/02/01 Consolidated Edison Co of New York. Inc. 59pp 82177 087 84X Fichs 50-000.84/02/01.8402010410
- 8402130328 Documents add1 info provided on 840106 re NUREG-0737. Items II.F i 4, II F i 5 k II F i 6 concerning containment prassure, water level & hydrogen monitors, respectively ZIMMERMAN, S R. Carolina Power & Light Co 84/02/03 VARGA, S A Operating Reactors Branch i 2pp. 22197 II2 24X Fiche. 80-261, 84/02/03, 8402130328

- 8402130145 Requests concurrence to submit supplemental Tech Spec change for new valves addressing NRC Criteria 3 months prior to end of outage Tech Specs submitted 800620 should be withheld until supplemental Tech Specs submitted MCDUFFIE.M A Caralina Power & Light Co 84/02/07 VARGA.S A Operating Reactors Branch 1. ip 22201 139 24x Fiche 50-261.84/02/07.8402130195
- 8402140377 Application for amend to License DPR-23 revising Tech Specs 3 i i 4.Table 3 5-5 & Table 4.1-i.in response to Generic Ltr 83-37 re NUREG-0737. Items II B 1.II B 3.II E 1 1.II F 1 1. II F 1 3.II F 1 3.II F 1 3.II F 1 5 & II F 1 6. II F 1 5 & II F 1 6. GROUPFEE.M A Carolina Power & Light Co. 84/02/07. VARGA.S A Operating Reactors Branch 1 5pp R2220 031 24X Fiche 50-261.84/02/07.8402140377
- --8402140389 Froposed revs to Tech Specs 3 i i 4. Table 3 5-3 & Table 4 1-1 in response to Generic Ltr 83-37 re NURE9-0737, Items II B i iI B 3, II E i i II F i 1 II F i 2 II F i 3, II F i 4. II F i 5 II F i 4 & II F i 2 II F i 3, II F i 4. II F i 5 II F i 4 & II F i 2 II F i 3, II F i 5 II F i 4 & II F i 2 II F i 3, II F i 4 II F i 5 II F i 4 & II F i 2 II F i 3, II F i 4 II F i 5 II F i 6 II F i 6 II F i 6 II F i 7 II F
- B402140390 Supplemental request for amend to License DPR-23, revising radiological effluent Tech Specs Table 3 17-8 to ensure that acceptable varieties of fish be sampled No amend fee required Sections 4 18 4 20 renumbered MCDUFFIE.M A Carolina Power & Light Co 84/02/07 VARGA.S A Operating Reactors Branch i 2pp 22220 309 24X Fiche 50-261,84/02/07.8402140390
- --B402140394 Revised radiological effluent Tech Speca Table 3 17-8, ensuring that acceptable varieties of fish be sampled while not requiring one of sects species Sections 4 18 4 20 of 831025 submittal renumbered to Sections 4 17 4 21 * Carelina Power & Light Co 84/02/07 16pp 22220 311. 24X fiche 50-261,84/02/07,8402140390
- 8402270604 Approves priority ranking of DROP for Generic Issue 34 re RCS leak Encl prioritization evaluation will be incorporated into NUREG-0933. "Prioritization of Generic Bafety Issues " DENTON.H R Office of Nuclear Reactor Regulation. Director 84/02/07 THOMPSON.H L Division of Human Factors Safety 5pp 22414 017 R4X Fiche 50-261,84/02/07.8402270604
- 840228040? Provides status of util activities re seismic qualification of auxiliany feadwater sys per telcon concerning Generic Ltr B1-14 Recirculation line analysis will be completed by Jul 1984
 CUTTER.A B Carolina Power & Light Co 84/02/22 VAROA, S A Operating Reactors Branch 1 4pp. 22406 350. 24x
 Fiche: 50-261,84/02/22.8402280409
- G. Inspection reports, IE Bulletins & correspondence
- 840215023B Forwards IE Insp Rept 50-26i/84-01 on 840104-06.No violations or deviations identified VERRELLI,D M Division of Project & Resident Programs. 84/01/20. UTLEY.E E Carolina Power & Light Co 2pp R2245 010. 24X Fiche 50-261.84/01/20.840215023B
- --8402150243 IE Insp Rept 50-261/84-01 on 840104-06 No violation or deviations identified Major areas inspected, licensee action on previous anforcement matters, inspector followup items & status of preparation for steam generator outage ALBRIGHT.R M. Region 2, Office of Director BARR, K f Division of Engineering & Operational Programs 84/01/19, 7pp 22245 012 24X Fiche 50-261,84/01/20,8402130238
- 312120153 JE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/01/25. Consolidated Edison Co of New
 York
- 402260001 Forwards IE Insp Rept 30-261/83-36 on B31211-840110 No violations or deviations identified VERRELLI,D M Division of Project & Resident Programs 84/01/27. UTLEY.E E Carolina Power & Light Co. 2pp 22401:154 24X Fiche 50-261,84/01/27,8402280001
- --B4022B0002 IE Insp Rept 50-261/B3-36 on B31211-840110 No violation or deviations identified Major areas inspected: Tech Spec compliance; plant tour, operations performance, ROs, site security. IE notice followup & smergency lighting review.

 MEISE: S. Region 2. Office of Director BEMIS.P.R. Division of Project & Resident Programs B4/01/26. 12pp. 22401: 156 24X Fiths. 50-261, 84/01/27, 84022B0001

- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JARDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co. of New York, Inc. 119pp. 22114 179 24% Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Hødders" Syr list encl DEYOUND:R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 156 24X Fichs 50-000,84/02/03,8401190017
- 8402140500 Forwards errate to IE Insp Rept 50-261/83-12, consisting of corrected Pages 4 & 5 to rept details
 LEWIS.R C Division of Project & Resident Programs 84/02/03
 UTLEY.£ E Caroline Power & Light Co 3pp 22221 109 24x
 Fiche.50-261,84/02/03,840240500
- --8402140507 Errata to 1E Insp Rept 50-261/83-12 re containment air recirculation unit fan cooler leak & pipe alley fire detection instrumentation # Region 2, Office of Director 84/02/03 2pp 22221 112 24x Fiche, 50-261,84/02/03,8402140500
- 8402150252 Ack receipt of 840127 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/83-33 LEWIS.R C Division of Project & Resident Programs 84/02/08 UTLEY.E E Carolina Power & Light Co 1p 22250 121 24X Fiche 50-261.84/02/08.8402150252
- --8402150258 Responds to NRC 831227 ltr re violations noted in IE Insp Rept 50-26i/B3-33 Corrective actions underground cables for svc water pumps & valves repaired & returned to svc HORGAN, R E Carolina Power & Light Co 84/01/27 O'REILLY, J P Region 2. Office of Director 5pp 22250 122 24X Fiche 50-261.84/02/08.8402150252
- --8402150262 Forwards IE Insp Rept 50-241/83-33 on 831111-1210 & notice of violation LEMIS.R C Division of Project & Resident Programs 83/12/2 UTELY.E E Carolina Power & Light Co 2pp 22250 127 24X Fichs 50-261,84/02/08,8402150252
- ---B402150265 Notice of violation from insp on 831111-1210 * Region 2. Office of Director 83/12/29. 2pp 22250,129 24X Fiche 50-261,84/02/08,8402150252
- --8402150273 IE Insp Rept 50-261/83-33 on 831111-1210 Violations nated failure to implement procedures for clearence tags, failure to rept violations re PORV & failure to control excavation activities

 WEISE, 8 Region 2. Office of Director BEMIS, PR Division of Project & Resident Programs B3/12/19 16pp. 22250 131 24X Fiche 50-261,84/02/08,8802150252
- 8402280165 Ack receipt of 840131 supplemental ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-261/83-26 implementation of corrective actions will be examined during future insp.

 LEWIGHR C Division of Project & Resident Programs 84/02/07. UTLEY.E.E Carolina Power & Light Co ip 22400 267 24X Fichs. 50-261.84/02/07.8402280165
- --8402280170 Responds to NRC 831101 ltr re violations noted in IE [nsp Rept 80-261/83-26 Supplemental info to 831201 response to steam tube plugging will be provided by 840227 MDROAN,R.E. Carolina Power & Light Co. 84/01/31 O'REILLY, J P Region 2, Office of Director. 1p 22400.268 24X Fiche. 50-261,84/02/09,8402280165
- B401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (100FR50, App R) " Syc list enc!

 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Poet 830803) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp. 22365 259, 24X Fiche 50-000, 84/02/13, 8401190041
- B401190039 IE Info Natice 84-08, "10CFR50 7, 'Employee Protection '"
 Svc list encl
 JDRDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post B30103). B4/02/14. Consolidated Edison Co. of New
 York, Inc. 115pp. 22365:141. 24X Fiche 50-000,84/02/14,8401190039
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Eve list enel JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). B4/02/15 Consolidated Edison Co. of New York, Inc. 118pp. 22366, 142 24X Fiche: 50-000, 84/02/15, 8401190045.

- 8402280071 Submits updated plan & schedule for completion of all open items in response to 1E Bulletins 79-02 & 79-14 All inspa. as-built documentation, procedure changes & mod identification should be completed by 840630 MDROAN:R E Carolina Power & Light Cd 84/02/15 O'REILLY.J.P. Region 2, Office of Director 2pp 22401 140 24X Fiche 50-261.84/02/15.8402280071
- B402280264 Ack receipt of B40120 ltr informing NRC of steps taken to currect violations noted in IE Insp Rept 50-261/83-27
 Response meets requirements of 10CFR2 201
 LEWIS.R C Division of Project & Resident Programs 84/02/17
 UTLEY.E E Carbina fower & Light Co 1p 22403 236 24X
 Fiche 50-261,84/02/17,8402280264
- --B40228034B Ack receipt of B40120 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/83-27 LEWIS.R C. Division of Project & Resident Programs B4/02/08 UTLEV.E E Carolina Power & Light Co 1p 22403 237 24X Fichs 50-261.84/02/17.8402280264
- --B402280357 Responds to NRC B31221 ltr re violations noted in IE Insp Rept 30-261/83-27 Corrective actions new sample points established by documented uniform mixing test for various ventilation filter sys MORGAN.R E Carolina Power & Light Co B4/01/20 D'REILLY.J P Region 2, Office of Director 3pp 22403 238 24x Fiche 50-261,84/02/17.8402280264
- --8402280345 Forwards IE Insp Rept 50-261/83-27 on 831003-07 & notice of violation LEWIB.R C Division of Project & Resident Programs 83/12/21 UTLEY.E E Carolina Power & Light Co 2pp 22403 241 24X Fiche 50-261,84/02/17.8402280264
- --8402280369 Notice of violation from insp on 831003-07
 * Region 2, Office of Director 83/12/21 2pp 22403 243 24x
 Fiche 50-261,84/02/17,8402280264
- --8402280376 IE Insp Rept 50-261/83-27 on 831003-07 Violation noted tests demonstrating sys operability, performed prior to 83100B, of spent fuel handling bldg, control room & RHR compartment filter sys inadequate ALBRIGHT, R H Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 83/12/08 App 22403 245 24X Fiche 50-261.84/02/17.8402280264
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Bet Below Manufacturer Recommended Value " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000,64/02/21.8401190062
- B401170066 IE Info Notice 84-11, "Iraining Program Deficiencies"
 Byc list encl.
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/02/24 Consolidated Edison Co of New
 York, Inc. 115pp. 22430 304 24X Fiche 30-000,84/02/24.8401170066
- B401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
 SVc list encl
 JURDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/02/27 Cansolidated Edison Co of New
 York, Inc. 120pp 22431 060 24X Fiche 50-000,84/02/27.8401190067
- R Periodic operating reports & related correspondence
- B40217017B Monthly operating rept for Jan 1984 W/840214 ltr SCOTT.A E , MOROAN.R E Caroline Power & Light Co 84/01/31 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 3pp 22299: 038 24% Fiche 50-261.84/01/31,8402170178
- B Reportable occurrences. LERs & related correspondence
- 8402030279 LER 83-033/03L-0. on 831224, instrument lines to turbine first stage pressure & steam pressure transmitters & steam driven auxiliary feedwater pump discharge pressure switch froze.

 Gaussid by cold weather H/840123 ltr

 MRIGHT.C.L. MORGAN.R E Carolina Power & Light Co 84/01/23

 0/REILLY.J.P. Region 2, Office of Director 3pp 22047 104 24X

 Fiche 50-241,84/01/23,8402030279
- 8402080158 Discusses resolution of auxiliary feedwater (AFW) system backleakege problems, per recent talcons Check valves will be replaced during Jul 1984 steam generator outage. AFW pump room will be checked for backleakege deily CUTTER, A. B. Capolina Power & Light Co. 84/01/30 VARQA, S A Operating Reactors Branch i 2pp. 22132 281. 24X Fiche 80-261,84/01/30,8402080158

- 8402140439 PNO-II-84-008 on 840126.unit taken out of svc to locate & repair steam generator tube leak Steam generator will be replaced & unit restarted in Jul HARDIN.A K , VERRELLI.D M Region 2, Office of Director 84/02/07 ip 22227 185 24% Fiche 50-241,84/02/07.8402140439
- B402190327 PND-II-84-010 on 840207.NASLP terminated hearing on util license amond request to replace steam generators Issuance of license amend verbally authorized Written order expected within 10 days JUNES,8 W. OILLILAND,J.T. Region 2. Office of Director 84/02/10 2pp 22250 100 24X Fiche 50-261.84/02/10.8402150327
- B402270117 LER 84-001-00 on B40126, source range detector channel N-31 failed high, causing shutdown bank trip Caused by detector shorting out Detector replaced W/B40224 ltr WRIGHT, C. L., MORGAN, R. E. Carolina Power & Light Co. 84/02/24 2pp 22426 1/3 24X Fiche 30-261,84/02/24,8402290117
- T Hearing transcripts on non-antitrust matters
- B402020210 Forwards NRC testimony on Contention 3 re cost-benefit analysis
 BACHMANN,R O Hearing Branch 1 B4/01/20 MARGULIES,M B ,
 HETRICK,D L , KLINE,J R Atomic Safety and Licensing Board Pane1
 1p 22057 094 24X Fiche 50-261,84/01/20,8402020210
- --8402020212 Testimony of L Lois & PN Randall on Contention 3 re reactor vessel embrittlement LDIS.L Core Performance Branch RANDALL.P N Materials Engineering Branch 84/01/20 10pp 22057 095 24X Fiche 50-261,84/01/20.8402020210
- --8402020216 Testimony of EN Fields on Contention 3 re cost-benefit analysis in FEB FIELDS, EN Division of Engineering 84/01/20 9pp 22057 105 24X Fiche 50-261.84/01/20,8402020210
- --8402020219 Testimony of PR Bemis SP Weise & DD Myers on Hartsville Contentions is & 1b re steam generator violations Profiqualifications encl
 BEMIS, PR WEISE, SP, MYERS, DO NRC No Detailed Affiliation
 Given 84/01/20 32pp 22097 114 24X Fiche 50-261,84/01/20,8402020210
- 8402130055 Transcript of 840207 hearing in Hartsville.8C re steam generator repair through major component replacements Pp 92-270 Supporting documentation encl * Atomic Safety and Licensing Board Panel 84/02/07 441pp 2220
- 8402140449 Transcript of 84020B hearing in Hartsville,80 re steam generator repair Pp 291-503 * Atomic Safety and Licensing Board Panel 84/02/08 215pp 22227 304 24% Fiche 50-261,84/02/08,8402140449
- 8402170266 Transcript of 840209 hearing in Hartsville, SC re steam generator repair Pp 504-516 * Atomic Safety and Licensing Board Panel 84/02/09 17pp 22277 165 24x Fiche 50-261,84/02/09,8402170266
- X Onsite Storage of Low Level Waste
- 8402070377 Informs of methods to obtain staling factors for oil & irradiated components waste streams per 100FR61 Scaling factors for irradiated components taken directly from NURES-07B2 ZIMMERHAN, B R Carolina Power & Light Co 84/02/02 EISENHUT, D G Division of Licensing 3pp 22099 316 24X Fiche 50-000, 84/02/02, 8402070377
- DOCKET 50-R62 BRIGHAM YOUNG UNIV RESEARCH REACTOR
- O Inspection reports, IE Bulletins & correspondence
- B312120193 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058:001 24X Ficke 50-000.84/01/25,8312120153
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Evc list encl JORDAN E L Division of Emergency Preparedness & Enginebring Response (Post 830103) 84/02/03. Consolidated Edison Co of New York, Inc 119pp 22114 179 R4X Fiche 50-000.84/02/03.8401190016

- 8401190017 IE Bulletin 64-0), "Cracks in BWR Mark I Containment Vent Headers" Svc list encl DEYOUNG.R C Director's Office Office of Inspection and Enforcement 84/02/03 Consultdated Edison Co of New York, Inc 102pp 22177 154 24X Fiche 50-000,84/02/03,8401190017
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R) " Syc list
- ORCIAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365-259 24X Fiche 50-000.84/02/13.8401190041
- 8401198039 IE Info Natice 84-88, "10CFR50 7, 'Employee Protection '" 10119039 IE Info Nutite of the Sve list encl
 Sve list encl
 JORDAN: EL Division of Emergenty Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 Yurk, Inc 115ep 22345 141 24X Fiche 30-000,84/02/14,8401170039
- 8401190045 IE Info Notice B3-63.Suppl 1. "Potential Failures of Mestinghouse Type SA-1 Differential Relays " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/02/15 Consolidated Edison Co. of New York. Inc. 118pp 22366 142 24% Fiche 50-000.84/02/15.8401190045
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000.84/02/21,8401190062
- 8401170066 IE Info Notice 84-11, "Training Program Deficiencies " Olipoobb it into notice of the second of the
- 8401170067 IE info Notice 84-12, "Failure of Boft Seat Valve Seals " SVC list enc)
 JORDAN, E L Division (
 Response (Post 830103) Division of Emergency Preparedness & Engineering ost 830103) 84/02/27 Consolidated Edison Co of New 120pp 22431 060 24X Fiche 50-000.84/02/27,8401190067 120pp
- DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT
- F Security, modical, emergency & fire protection plans
- 8402070039 Final response to FOIA request for documents re emergoncy operation facilities located 10-20 miles from nuclear plants & info approving/denying location over 20 miles away forwards listed documents info also available in PDR FELTON, J M Division of Rules and Rocords 83/11/04 D'NEILL, J & Shaw, Pittman, Potts & Troubridge 1p 22142 148 24X Fiche-50-000,83/11/04,8402070039 1 D'NEILL, JH 24X
- ---B309120090 Recommends Commission agree w/approval of util position to establish common backup emergency operations facility for Prairie Island & Monticello nuclear generating plants DIRCKGS W J Office of the Executive Director for Operations SECY-B3-363 83/08/30 86pp 22142 151 24X Fiche 50-000,83/11/04,8402070039
- --B402070045 Advises of Commission approval of util decision to establish emargency operations facilities 45 & 55 miles from respective sites
 CHILM: 9 J Office of the Secretary of the Commission 63/09/26
 DIRCKS, W J Office of the Executive Director for Operations ip 22142 149 24X Fiche 50-000.83/11/04.8402070039
- 8402130278 Forwards IE Insp Rept 50-263/83-22 on 831203-840110 No ORISON FORWARD IE INSP Rept 50-263/83-22 on 831203-840110 No noncompliance noted SHAFER.W D Region 3. Office of Director 84/01/26 LARSON.C E Northern States Power Co 2pp 22200 326 24X Fiche 50-263.84/01/26.8402130278
- --B402130284 1E Insp Rept Rept 50-263/B3-22 on 831203-B40110 No noncompliance noted Major areas inspected operational safety verification to unsite review committee BROWN C H. WALKER, D. Region 3. Office of Director 84/01/20 3pp 22200 328 24x Fiche 50-263.84/01/26,8402130278
- B402060444 Forwards Rev 8 to Procedure A 2-001, "Emergency Organization." & Rev 1 to Procedure A 2-209, "Responsibilities of Radiological Emergency Coordinator "List of Current pages, dtd B40123, also enc1 FEY.F. L. Northern States Power Co. 84/02/02 Region 3, Offic Director Spp. 22083 207 24% Fiche 50-263, 84/02/02, 8402060444 Region 3, Office of

- --8402060449 Rev 8 to Procedure A 2-00; "Emergency Organization" & Rev 1 to Procedure A 2-209, "Responsibilities of Radiological Emergency Coordinator " Personal info deleted * Northern States Power Co 84/01/23 26pp 22083 210 24X Fiche 50-263,84/02/02.8402060444
- 8402140009 Requests remittance of Class III fee re 830616 & 0921 applications requesting exemption from certain requirements of 10CFRSO 4B & 10CFRSO, App R Fire protection review & approval fee protections provided in encl NRC 831205 ltr MILLER, W O License Fee Management Branch 84/02/07 MUSQLF, Northern States Power Co 1p 22251 344 24X Fiche 50-263, 84/02/07, 8402140009 MUSOLF, D M ,
- 8402160369 Forwards Rev 14 to physical security plan.rovising escurity mgt training requirements & clarifying badge access period Rev withheld (ref 10CFR73 21)
 LARSON.C E Northern States Power Co 84/02/07 KEPPLER.J Q
 Region 3. Office of Director ip 22268 328 24X Fiche 50-263,84/02/07,8402160369
- B402240011 Remits fees for B20630 amend application re App R, in NUSDLF, D Northern States Power Co 84/02/16 MILLER, W Cl Fee Management Branch 2pp 22375 241 24% Fiche 50-263,84 24X Fiche 50-263, 84/07/18,
- P Operating license stage documents & correspondence
- 840:2010382 Forwards notice of consideration of issuance of amend to License DPR-22 & proposed NSMC determination & opportunity for hearing re time delay setpoints in reactor protection sys NSHC available in Central Files only NICOLARAS. H Operating Reactors Branch 2 84/01/10 MUBDLF, B H Northern States Power Co ipp 22062 007 24X Fiche 50-263,84/01/10.8402010382
- --8402010386 Notice of consideration of issuance of amend to Licente DPR-22 & proposed NSHC determination & opportunity for hearing Amend increases time delay suppoints of reactor protection sys VASSALLO.D B Operating Reactors Branch 2 84/01/10 8pp 22062 011 244 Fiche 50-263.84/01/10,8402010382
- 8402030112 Forwards Amend 20 to License DPR-22 & safety evaluation Amend revises Tech Specs to allow source range monitor min count rate to fall below three counts per second during full core discharge & reload NICOLARAS.H Operating Reactors Branch 2 84/01/14 MUBDLF, 1) H Northern States Power Co Zpp 22090 323 24X Fiche 50-263, 84/01/16, 8402030112
- --B402030ii6 Amend 20 to License DPR-22, revising Tech Specs to allow source range monitor min count rate to fall below three counts per second during full core discharge & subsequent reloading reloading VASSALLD,D B Operating Reactors Branch 2 84// 22090 325 24X Fichs 50-263,84/01/16,8402030112
- --8402030121 Bafets evaluation supporting Amend 20 to License DFR-R2 * Office of Nuclear Reactor Regulation, Director 84/01/16 4; 22070 330 24X Fiche 50-263.84/01/16.8402030112
- 8402100341 Forwards Amend 21 to License DPR-22 & safety evaluation Amend changes Tech Specs to incorporate detailed definition of term operable as requested in 800410 ltr to power reactor NICHOLARDS,H Operating Reactors Branch 2 Northern States Power Co 2pp 22210 311 Fichs 50-263.84/01/23.8402100341 84/01/23 MU80LF, D N 24X
- 8402100346 Amend 21 to License DPR-22, changing Tech Specs to incorporate detailed definition of term operable as requested in 800410 ltr to all power reactor licensees VASBALLO. D B Operating Reactors Branch 2 84/01/23 5p 22210.313 24X Fiche 50-263,84/01/23,8402100341
- ---8402100349 Safety evaluation supporting Amend 21 to License BPR-22
 * Office of Nuclear Reactor Regulation, Director, 84/01/23 2
 22210 318 24X Fiche 50-263,84/01/23,8402100341
- ~~B402100352 "Definition of Operable Monticello Nuclear Generating Plant", informal rept
 FARMER.F G , STOFFEL.J W EGG, Inc FIN A-6429 EGG-EA-6399
 83/10/21 NRC No Detailed Affiliation Given Bpp. 22210:
 24X Fiche 50-263.84/01/23,8402100341

- 8402230410 Forwards SER re util 800530 & 0828 submittals re effects of dc power failures on ECCB performance ECCB will remain available following postulated failures VASSALLO,D B Operating Reactors Branch 2 84/01/31 MUSOLF,D M Northern States Fower Co 2pp 22380 042 24X Fiche 50-263.84/01/31.8402230410
- --8402230414 Safety evaluation re effects of dc power supply failures on ECCS performance ECCS will remain available following any postulated failures # Defice of Nuclear Reactor Regulation, Director 84/01/31 tp 22380 044 24X Fiche 50-263,84/01/31,8402230410
- 8402170072 Forwards Amend 22 to License DPR-22 & safety evaluation Amend revises Tech 8pecs to add new limiting conditions for operation & surveillance requirements for RHR in shutdown cooling mode NICOLARAS, H Operating Reactors Branch 2 84/02/02 MUSOLF, D M Northern States Power Co 2pp. 22312 347 24X Fiche 50-263,84/02/02,8402170072
- --8402170077 Amend 22 to License DPR-22, revising Tech Specs to add new limiting conditions for operation & surveillance requirements for RHR in shutdown cooling mode VASBALLO, D B Operating Reactors Branch 2 84/02/02 App 22312 347 24X Fiche 50-243,84/02/02,8402170072
- --8402170080 Safety evaluation supporting Amend 22 to License DPR-22 * Office of Nuclear Reactor Regulation, Director 22312 355 24% Fiche 50-263 64/02/02 8402170072
- 8402140009 Requests remittance of Class III fee to 830616 & 0921 applications requesting exemption from certain requirements of 100FR50.48 & 100FR50.App R Fire protection review & approval fee procedures provided in encl NRC 831205 ltr MILLER.W O License Fee Management Branch 84/02/07 MUSQLF, D Northern States Power Co 1p 22251 344 24X Fichs 50-263, 84/02/07.8402140009
- B402160473 Responds to Generic Ltr 84-01 re NRC use of terms important to safety & safety-related Meeting between NRC & Steering Committee of Util Safety Classification Group should be arranged to provide clarification of issue
 MUBOLF.D Northern States Power Co 84/02/09 Office of Nuclear Reactor Regulation, Director 1p 22269.001 24X
 Fiche: 50-000,84/02/09,8402160473
- 8402230238 Discusses resolution of SER open items re environ qualification of sefety-related electrical equipment, per 831212 meeting General methodology used to establish aging & radiation qualification enc. MUSOLF.D Northern States Power Co 84/02/10 Office of Nuclear Reactor Regulation, Director Sipp 22352, 276. 24X Fiche: 50-263.84/02/10.8402230238
- O Inspection reports, IE Bulletins & correspondence
- 8402130278 Forwards IE Insp Rept 50-263/83-22 on 831203-840110, No noncompliance noted SHAFER, W. D Region 3, Office of Director 84/01/26 LARBON, C E Northern States Power Co. 2pp. 22200 326 24X Fiche 50-263,84/01/26,8402130278
- --8402130284 IE Insp Rept Rept 50-263/83-22 on 831203-840110 No noncompliance noted Major areas inspected operational safety verification & onsite review committee BROWN, C. H., WALKER, R. D. Region 3, Office of Director 84/01/20 3pp. 22200-328. 24X Fiche 50-263.84/01/26.8402130278
- 8402060381 Ack receipt of check in payment of civil penalty proposed by NRC on 831122 Security Level III violation re release of radioactive matls in excess of DOT regulations appropriate. DEYGUNOR.C. Director's Office of Inspection and Enforcement 84/01/31 LARSON.C E Northern States Pawer Co 2pp 22110.302 24X Fiche 50-263,84/01/31,8402040381.
- 8402220056 Responds to IE Bulletin 84-01. "Cracks in BHR Mark I Containment Vent Headers " No cracks or indications noted in any weld or surface on vent header. LARBON.C. E. Northern States Power Co 84/02/06 KEPPLER, J. O. Region 3, Office of Director 3pp 22338, 317. 24x Fichs. 80-263, 84/02/06, 8402220056.
- B402130455 Ack receipt of 840130 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-263/83-23 SPEBBARD, R.L. Division of Emergency Preparedness & Operational Support. 84/02/07 LARSON, C.E. Northern States Power Co ip 22202.111 24X Fiche: 50-263, 84/02/07, 8402130455.

- --8402130462 Responds to NRC 831230 ltr re violations noted in IE Insp Rept 50-263/83-23 Corrective actions four AWI-1 7 litems will be further revised to specifically identify relay & instrument reset deadband when preparing design changes LARSON.C E Northern States Power Co 84/01/30 SPESBARD.R L Division of Emergency Preparedness & Operational Support 20p 82202 112 24X Fiche 50-263.84/02/07.8402130455
- 8402220415 Responds to IE Bulletin 83-06. "Nonconforming Matls Supplied by Tube-Line Corp Facilities at Long Island City, NY, Houston, TX & Carol Stream, IL." Six elbows supplied by Tube-Line never installed or used at facility

 LARSON, C E Northern States Power Co 84/02/07 KEPPLER, J G Region 3, Office of Director 3pp 22340 192 24X

 Fiche 50-263.84/02/07,8402220415
- B402240123 Forwards status rept on corrective steps taken re 830411 notice of violation & proposed imposition of civil penalty & schedule for completion of one item implementation of new mod control process expected by 850101 LARBON. C E Northern States Power Co 84/02/20 DEYOUNG. R C Director's Office, Office of Inspection and Enforcement 4pp 22373 324 24X Fiche 50-263,84/02/20,8402240123
- R Periodic operating reports & related correspondence
- 8402160080 Annual Operating Rept for 1983 W/840210 ltr LARBON.C E Northern States Power Co 83/12/31 3pp 22276 195 24X Fiche 50-263.83/12/31.8402160080
- B Reportable occurrences, LERs & related correspondence
- B402230347 Updates status rept on IWR pipe cracks & protection of upcoming licensee actions Insp results encl Evaluation & recommendations re interim & long-term remedial measures expected by May 1984
 DIRCKS.W.J. Office of the Executive Director for Operations SECY-84-009A 64/01/27 5pp 22377 047 24X Fiche 50-000, 84/01/27, 8402230347
- 8402130577 Forwards summary rept of toxic monitor spurious actuations \(^1\) description of measures taken to resolve problems \(^1\) u/emergency filtration train sys, installed per NUREO-0737, Item III D 3 4
 LARBON.C \(^2\) Northern States Power Co \(^2\) E4/02/01 KEPPLER, J G
 Region 3. Office of Director \(^2\) Pp 22201 175 24X
 Fiche 50-263,84/02/01,8402130577
- 8402080378 PNO-III-84-013 on B40203, reactor shutdown commenced to prepare for 30-uk outage to replace recirculation sys piping due to intergranular stress corrosion cracking Media informed GROBE.J., WALKER,R., SHAFER,W., Region 3, Office of Director-84/02/03 1p 22130 342 24X Fiche 50-243,84/02/03.8402080398
- 8402100020 LER 84-002-00 on 840107, control room HVAC sys automatically transferred to toxic chemical emergency mode due to spurious trip of hydrogen chloride monitor AT-9036 Gause unknown Investigation revealed no apparent cause W/840206 1tr HAMMER M F, MUSILF, D. Northern 8tates Power Co. 84/02/06 3pp 22178 253 24X Fiche 50-263.84/02/06.8402100020
- 8402140011 LER 84-003-00 on 840107, while performing HPC1 high steam flow sensor test & calibr, time delayed high steam flow isolation signal exceeded Tech Spec limit Probably caused by foreign matl between diaphraym exhaust W/840208 ltr WOJCHOUSKI, A V . MUSDLF, D Northern States Power Co 84/02/08 2pp. 22217 176 24X Fiche 50-263,84/02/08,8402140011
- 8402140382 LER 84-004-00 on 840110 emergency filtration train transferred to emergency mode in control room HVAC Caused by chlorine monitor tape cassette running out, resulting in tape break & spurious monitor trip H/840209 ltr HAMMER, M F., MUSQLF, D. Northern States Power Co. 84/02/09 3p; 22230-329 24X Fiche 50-263,84/02/09,8402140382
- 8402270420 PNG-III-84-017 on 840218, licensee identified cracks on loop jet pump A instrument seal line. Licensee evaluating whether to repair or replace cracked seal line on both loops A & B Region will follow licensee course of action MADISON. A., CHRISBOTIMOS, N. Region 3. Office of Director 84/02/21 ip 22389, 362 24X Fiche, 50-263, 84/02/21, 8402270420

DOCKET 50-265 QUAD CITIES STATION, UNIT 2

F Security, medical, smergency & fire protection plans

B402100221 Rev 4 to emergency plan annex W/840113 ltr MODRE:R D. Commonwealth Edison Co 83/04/30 DENTON, H R Office of Nuclear Reactor Regulation, Director Alpp 22178 081 24X Fiche: 50-254, 83/04/30, 8402100221

- 8402130191 Rev 0 to Emergency Plan Implementing Procedure EOF-17, "Emergency Operations Facility Activation Facility Log " . BERLIN. of D Commonwealth Edison Co 83/09/23 3pp 22199 283 24X Fiche 50-000.83/09/23.8402130191
- 8402130213 Rev 0 to Emergency Plan Implementing Procedure EDF-18. "Nuclear Statistic Div Non-Edison Transportation Incident Assistance Procedure "

 Commonwealth Edison Co 83/09/29 5pp 22204 078 24X Fiche 50-000.88/09/27.8402130215
- 8402100137 Revised emergency plan implementing procedures, including Procedures EPIP EOF-17 re emergency operations facility activation log.EPIP CC-12 re sus power dispatcher & EPIP EOF-12 re access control W/840203 mema & receipt form MOORE, R D Commonwealth Edison Co E3/11/09 DENTION, H R NRC No Detailed Affiliation Given 24pp 22181 288 24X Fiche 50-000.83/11/09.8402100137
- B402130220 Rev 8 to Emergency Pian Implementing Protedure CC-12. "Sys Power Dispatcher " MODRER D Commonwealth Edison Co 83/11/09 11pp 22200 108 24X Fiche 50-000,63/11/09.8402130220
- 8402150358 Rev 2 to Generating Station Emergency Plan Implementing Procedure EOF-12, "Access Control to Emergency Operations Facility " W/831108 ltr & receipt form HODRE, R D Commonwealth Edison Co 93/11/30 5pp 22242 358 24X Fiche 50-000.83/11/30,8402150358
- 8402140118 Rev 4 to "Amend of Generating Stations Emergency Plan Book" MCORE:R D Commonwealth Edison Co 84/01/13 42pp 22219 070 24X Fiche 50-254.84/01/13.8402140118
- 8402060446 Forwards Rev 9 to Emergency Plan Implementing Procedure CC-1, "Corporate Command Ctr Director " Recovery manager priority notification table enc! MDORE.R D Commonwealth Edison Co 84/01/30 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 28083 129 24X Fiche 50-000,84/01/30,8402060446
- --B402060464 Rev 9 to Emergency Plan Implementing Procedure CC-1.
 "Corporate Command Ctr Director," controlled copy
 MODRE, R D Commanuealth Edison Co 83/11/30 76pp 22083 131
 24% Fiche 90-600, 84/01/30, 8402060446
- B402130377 Discusses FEMA 830902 ltr & 0512 evaluations of offsite emergency preparedness exercise for facility Reasonable assurance exhibited that state & local govts have adequate capability to protect public PAPERIELLO, C. J. Region 3. Office of Director 84/02/07 REED, C. Commonwealth Edison Co. 2pp. 22197 001 24X Fiche 50-254, 84/02/07, RECO. 277
- 8402280395 Revised emergency plan implementing procedure, including Rev 1 to B2P 600-A4. "OSEP Telephone Directory" * Commonwealth Edison Co 84/02/18 61pp 22404 158 24X Fiche 50-000.84/02/18.8402280395

l Financial information

- 9402280410 Annual Financial Rept 1983 W/640221 1tr 0/CDNNOR.J J Commonwealth Edison Co 83/12/31 29pp 22407 101 24X Fiche 50-000.83/12/31.8402280410
- ' Operating license stage documents & correspondence
- |312120029 Generic Ltr 83-39 to representatives of utils re voluntary survey of licensed operators. See list encl
 EISENAUT, D @ Division of Licensing 83/12/08 Commonwealth
 Edison Co 12pp 22313 004 24% Fichs 50-000,83/12/08.8312120029
- 8402100324 Forwards Amend 80 to License DFR-30 & safety evaluation. Amend reduces current min critical power ratio operating limit to provide add operating margin during upcoming operating cycle
 BEVAN, R B Operating Reactors Branch 2 84/01/24 FARRAR, D. L. Commonwealth Edison Co. 2pp 22210 328, 24% Fichs 50-263, 84/01/24, 8402100324
- -8402100335 Amend 80 to License DPR-30, reducing current min critical power ratio operating limit to provide addl operating margin during upcoming operating cycle & changing pressure set points for safety-relief valves
 RODNEY, V L Operating Reactors Branch 2 84/01/24 7pp
 22210 330 24X Fiche 50-245,84/01/24,8402100324
- ~8402100337 Bafety evaluation supporting Amend B0 to License DPR-30 * Office of Nuclear Reactor Regulation, Director 84/01/24 4pp 22210 337 24% Fiche 50-265 84/01/24 8402100324

- 8402140021 Submits corrective actions re coordination of site visits by Bandia Natl Lab as part of truck bomb threat contract Future site visits will be coordinated through Standardization & Special Projects Branch
 THOMAS.C O Standardization & Special Projects Branch 84/01/26
 EISENHUT, D 9 Division of Licensing 3pp 22251 313 24X
 Fiche 50-000,84/01/26,8402140021
- --B402140027 Submits tentative schedule for site visits by Bandie Nati Lab to study destructive & safety consequences of explosiveladen vehicle used as weapon against nuclear facility, per truck bomb threat contract FLOYD, W C Human Factors & Bafeguards Branch B4/01/13 HOPEEK. O NRC - No Detailed Affiliation Given ip 22251 320 24X Fiche 50-000, 84/01/26, 8402140021
- --B401260470 Advises of Bandia request for site visit during wk of 840205 to study destructive & safety consequences of explosive-laden vehicle Data will be collected to identify structures & sys must vulnerable to truck-mounted explosives FLOYD, W.C. Human Factors & Bafeguards Branch 84/01/10 REED, C. Commonwealth Edison Co. ip. 22251-321 24X Fiche 50-000, 84/01/26,8402140021
- 840R010061 Summary of B40126 meeting w/util, Wester, Berhtel, Sargent & Lundy & INEL in Bethesda, MD re equipment environ qualification review Agenda & list of specific equipment qualification deficiencies encl
 GILBERT, R A Operating Reactors Branch 5 84/01/30 Operating Reactors Branch 5 36pp 22042 127 24X Fiche 50-000, 84/01/30, 8402010061
- 8402210307 Lists leakage munitoring commitments applicable over next operating cycle per discussions w/NRC Bubmittal will be sent within 30 days of start of next refueling outage RYBACK. B Communusalth Edison Co 84/02/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22314 357 24X Ficho 50-265.84/02/08,8402210307
- B402140205 Forwards response to Generic Ltr B3-36, requesting licensess to submit Tech Baccs or schedule for NUREO-0737 items scheduled after B11231 All appropriate Tech Bacc amend requests will be submitted by B40815
 BARNEB,P L Commonwealth Edison Co B4/02/09, DENTON,H R Office of Nuclear Reactor Regulation, Director 9pp 22229 341 24X Fiche 50-000,84/02/09,8402140205
- 8402210264 Provides add1 clarification re GE model improvements (NEDE-20566 P.NEDG-20566-1.Rev 1 & NEDG-20566-4.Rev 4).per NRC B10204 & B31228 ltrs.PCT for BMR/3s reduced by 150 F TMI Action Items II K 3 30 & 31 unchanged & complete RYBAK.B Commonwealth Edison Co B4/02/10, DENTON, H R. Office of Nuclear Reactor Regulation, Director ip. 22314 354 24% Fiche 50-254.84/02/10.8402210264
- 8402170259 Forwards Amends 80,72,86 & 81 to Licenses DPR-19, DPR-25, DPR-29 & DPR-30, respectively Amends approve Tach Spec changes providing additional for Class IE power monitoring sys CRUTCHFIELD D Operating Reactors Branch 5 84/02/14 FARRAR, D. L. Commonwealth Edison Co. 3pp 22297:112 24X Fiche: 50-000.84/02/14, 8402170259
- --8402170276 Amends 80,72,86 & 81 to Licenses DPR-19, DPR-25, DPR-29 & DPR-30, respectively, approving Tech Spac changes providing add1 limiting conditions for Class IE power monitoring sys. CRUTCHFIELD, D. Operating Reactors Branch 5 84/02/14 28pp. 22297 115 24X Fichs. 50-000,84/02/14,8402170259.
- 8402280457 Forwards Amends Bi, 73,87 & 82 to Licenses DPR-19, DPR-25, DPR-29 & DPR-30, respectively & safety evaluation. Amends revise Tech Specs to require restoration of safety/relief valve inoperable position indication CRUTCHFIELD.D. Operating Reactors Branch 5, 84/02/24 FARRAR, D.L. Commonwealth Edison Co. 3pp. 22406-315 24X Fiche. 50-000, 84/02/24, 8402280457.
- --8402280492 Amends B1.73.87 & 82 to Licenses DPR-19, DPR-25, DPR-29 & DPR-30, respectively, changing Tech Specs to require restoration of all safety/relief valve inoperable position indication prior to startup when in cold shutdown over 72 h. CRUTCHFIELD.D Operating Reactors Branch 5 84/02/24. 16pp R2406-318 R4X Fiche: 50-000.84/02/24: 8402280457
- --8402280531 Safety evaluation supporting Amends 81,73 & 87 & 82 to Licenses DPR-17.DPR-25.DPR-27 & DPR-30, respectively * Bffice of Nuclear Reactor Regulation, Director 84/02/24 299 22406:334 24X Fiche; 50-000.84/02/24.8402280457.

- G Inspection reports, IE Bullatins & correspondence
- 8312120153 IE Info Notice 84-06. "Steam Binding of Auxilianu Feedwater Pumps "Svc list encl
 JORDAN, E L Division of Emergency Praparedness & Engineering
 Mesponse (Post 830103) 84/01/25 Consolidated Edison Co of New
 York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120133
- 8402080035 Forwards final wald insp & repair results Final disposition of walds found w/crack indications, results of exam of plug removed from weld & radiographs of weld & modified repair Office of
 - program #180 encl RYBAK, B Commonwealth Edison Co 84/01/27 DENTON, H R Of Nuclear Reactor Regulation, Director App 22132 151 24X Fichs 50-265.84/01/27.840R080035
- ---8402080038 "Flaw Disposition Evaluation Basis " * NUTECH Engineers: Inc 84/01/18 3pp 22132 155 24X Fiche 50-265.84/01/27.8402080035
- --8402080040 Rev 2 to "Flaw Evaluation & Repair Plan " BUCHHOLZ, R H , GUSTIN.H L MUTECH Engineers, Inc. COM-75-001 RO2 84/01/31 19pp 22132 158 24X Fiche 50-245,84/01/27, д4/01/31 19pp В4020В0035
- --8402080045 Rev O to "Recirculation Sys Susceptibility Summary "
 * NUTECH Engineers, Inc CDM-71-020 ROO 84/01/31 15pp
 22132 177 24X Fiche 50-265,84/01/27,8402080035
- 8402230186 Forwards request for add1 info re 1E Bulletin 80-11.
 "Masonry Wall Design " Info required within 60 days of receipt of 1tr
 VASSALLO,D B Operating Reactors Branch 2 84/01/31 FARRA Commonwealth Edison Co 10pp 22377 204 24% Fiche 50-234.
 84/01/31,8402230186
 - FARRAR, D.I.
- 8402080378 Forwards info necessary to complete NRC review of IE Bullstin 80-11, "Masonry Wall Design," W/three oversize proprietary drawings Aperture cards are available in Central Files
 RYBAK, B Commonwealth Edison Co 84/02/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 33pp, 22140 033 24X
 Fiche 50-000,84/02/02,8402080378.
- --8402080385 Rev & to Procedures Manual OP-45, "Sampling & Testing of Hollow Concrete Masonry Units " LINDSTROM, R Hiss, Janney, Elstner & Associates, Inc 82/07/22 13pp. 22160.066 24X Fiche 50-000,84/02/02,8402080378
- --8402080394 Rev 2 to Procedures Manual OP-46, "Testing of Compression Cores Taken From Solid Block Walls " LINDSTROM, R Wiss, Janney, Elstner & Associates, Inc. 82/06/24 11pp. 22160 079 24% Fiche: 50-000, 84/02/02, 8402080378
- ---8402080401 Rev 2 to Procedures Menual DP-47, "Determination of Mortar Type "
 LINDSTROM.R. Wiss, Janney, Elstner & Associates, Inc. 82/06/24, 38pp. 22160-070 24X Fiche-50-000, 84/02/02, 8402080378.
- --8402080407 Rev 7 to Procedures Manual GP-50, "In Situ Shear Test of Block Walls " KRAUSE, R. Wiss, Janney, Elstner & Associates, Inc. 82/08/11 12pp 22140,128 24X Fichs.50-000,84/02/02,8402080378
- B401190016 IE Info Notice B4-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Bvc list encl JCRDANE L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/02/03 Consolidated Edison Co of New York, Inc 119pp 22114:179, 24X Fiche. 50-000, 84/02/03, 8401190016
- 3401170017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers." Svc list encl DEYDUNG,R C. Director's Office, Office of Inspection and Enforcement, 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177-156 24X Fiche. 50-000.84/02/03.8401190017
- 340,2150946 Forwards visual insp results in response to IE Bulletin 84-01 re Mark I containments No cracks or abnormalities found TOURIO

 BARNES, P. L. Commonwealth Edison Co. 84/02/10, KEPPLER, J 9 Region Director 4pp. 22250 108, 24% Fiche 50-254, 84/02/10, 84/02/10346
- M02270426 Forwards IE Insp Repts 50-254/83-30 & 50-265/83-31 on 831205-840131, No noncompliance noted 84AFER; W D Region 3, Office of Director. 84/02/10, REED, C Commonwealth Edison Co 2pp. 22390.207 24X Fiche.50-254,84/02/10,8402270426.

- --8402270432 IE Insp Repts 50-254/83-30 & 50-265/83-31 on 831205-840131
 No noncompliances or deviations identified Major areas
 inspected previous insp findings.operational safety, maint,
 surveillance.tens. IE bulletin followup & reactor scrams
 CHRIBSOTIMOS.N. MORRONOIELLO, A., WALKER, R. D. Region 3, Office of
 Director 84/02/09 12gp 22390 209 24X Fiche 50-254, 84/02/10,
 8402270426
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50.App R) " Syc list
 - encl JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New Yark, Inc 124pp 22345 259 24X Fiche 30-000,84/02/13,8401190041
- 8401190039 IE Info Natice 84-08, "10CFR50 7, 'Employee Protection '" Styles and Sycilst and Sycilst
- 8401190045 IE Info Notice 83-63. Suppl 1. "Potential Failures of Westinghouse Type BA-1 Differential Relays " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York. Inc. 118pp 22366 142 24X Fiche 50-000.84/02/15.8401190045
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Bvc list encl JDRDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000,84/02/21,8401190062
- 8401170066 IE Info Notice 84-11. "Training Program Deficiencies " NOI190066 IE Info Nutle Co. ...

 Byc list encl
 JDRDANE L Division of Emergancy Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- 8408280294 Ack receipt of 840120 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-254/83-13 & 50-268/83-15 Completion of Task 1. "Multiplet Resolution & Peak Classification" should resolve open items.

 PAPERIELLO.C J Region 3. Office of Director 84/02/24 RYBAK, B Commonwealth Edison Co ip 22379 076 24X Fiche 50-254,84/02/24, RESONABLE.
- --8402280302 Responds to NRC ltr re violations noted in IE Insp Repts 50-254/82-13 & 50-265/82-15 Corrective actions three add1 tasks developed to enhance spectral analysis & improve performance of AAIB
 RYBAK, B Commonwealth Edison Co 84/01/20 PAPERIELLD, C J
 Region G, Office of Director 2pp 22399.077 24X
 Fiche 50-254,84/02/24.8402280296
- 84011900A7 IE Info Notice 84-12, "Failure of Boft Seat Valve Seals " 101190047 IE Info Natice us-12, Table 10. Colors to Engineering Svc list encl
 JORDAN: E Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/27 Consolidated Edison Co of New York, Inc 120pp 22431 060 24X Fiche 50-000.84/02/27, 8401190067
- R. Periodic operating reports & related correspondence
- 8402220332 Monthly operating repts for Jan 1984, W/840201 ltr. MIBAK, A. KALIVIANAKIS, N. Commonwealth Edison Co. 84/01/31 Ripp 22334-212 248 Fichs 80-254, 84/01/51,840220332
- 8. Reportable occurrences, LERs & related correspondence
- 8402030230 LER 83-025/03L-0. on 831227; outboard check valve 402030230 LER 83-029/03L-0, on 831227; butboard check valve CV 2-3999-5160 & inboard check valve CV 2-3999-5160 found to lask excessively Caused by dirt buildup in valve internals Valves cleaned & reassembled W/840120 ltr COCHRAN.P: KALIVIANAKIB; N Commonwealth Edison Co. 84/01/25 KEPPLER; J 9. Region 3, Office of Director 2pp. 22067 160 24X Fiche 90-265,84/01/25,8402030230
- 8402070220 LER 84-002-00 on 840106, both distribution pamels NOX/ORZO LER 84-002-00 on Sequipos data distribution panels inadvertently deemergized simultaneously causing reactor scram. Causad by cognitive error on part of engineer Scram resat. No corrective action necessary. W/840127 1tr KAEPPEL-F., KALIVANAKIS, N. Commonwealth Edison Co 84/01/27 4pp 22101.166 24X Fiche 50-265.84/01/27.8402070220
- B402230347 Updates status rept on BWR pipe cracks & protection of upcoming licenses actions Inspresults encl Evaluation & recommendations re interim & long-term remedial measures expected by May 1984 DIRCKB, W.J. Office of the Executive Director for Operations SECY-84-009A, 84/01/27, 5pp 22377 047 24X Fiche: 50-000, 84/01/27, 8400230347 84/01/27,8402230347

- B402070303 LER 84-001-00 on 840103 t 05, reactor scrams occurred while teactor protection sys out of svc for circuit breaker maint Caused by intermediate range monitor 18 spiking due to faulty detector cable Cable replaced M/840130 ltr TIETZ,6 C . MALIVIANAKIS.N Commonwealth Edison Co. B4/01/30 4pp 22099 116 24X Fiche 50-265,84/01/30,8402070303
- 8402130383 Revised LER 63-014/03L-1 on 830906, MSIV 2-203-2A found leaking in excess of Tech Spec limit Caused by minute valve seat steam cutting Stat ground & polished & valve reassembled W/490330 ltr CAOLL.J, KALIVIANAKIS.N Commonwealth Edison Co 84/01/30 KEPPLER.J Region 3. Office of Director 2pp 22197 064 24X Fiche 50-265, 84/01/30, 8402130383
- 8402170202 Revised LER 83-018/01T-1 on 831011, discovered i-1/4 inch long, 20% through-wall linear indication in weld 128-527 Caused by intergranular stress corrosion cracking New welds & elbow installed 4/840202 ltr (LARK, D. KALIVIANAKIS,N Commonwealth Edison Co 84/02/08 KEPPLER, J Region 3, Office of Director 5pp 22299 283 24X Fiche 50-265,84/02/02,8402170202
- 8402270424 PND-III-84-018 on 840217.while pulling out third control rod to verify shutdown margin capability.reactor went critical at rod position 18 on 325 s period Test terminated by returning three rods to fully inserted position MADISON.A. CHRISSOTINOS.N. Region 3. Office of Director 84/02/22 ip 22340 221 24% Fiche 50-265,84/02/22,8402270424
- DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8402130076 Forwards schedule for spent fuel shipments from West Valley to facility Safeguards info withheld (ref 10CFR73 21) DANESE.F. L. Nuclear Assurance Corp. 84/01/09 GDDY.A. Region 1. Office of Director ip 22262 279 24X Fiche 50-266.84/01/09. 8402170774
- IOR140237 Forwards security plan changes & drawings & responses to IE Safeguards Insp Repts 50-266/83-22 & 50-301/83-21 Encis withheld (ref IOCFR73 21)
 BURSTEIN & Misconsin Electric Power Co B4/01/23 XEPPLER, J G Region 3, Office of Director 1p 20220 282 24X
 Fiche 50-266.84/01/23.8402140239
- 402070116 Revs to emergency plan manual.consisting of Rev 21 to EP 4.0. "Emergency Conditions" & EP 8 0. "Maintaining Emergency Preparedness." Rev 4 to App D. "Ltrs of Agraement" & App F. "Manitomoc County Nuclear " W/840131 ltr FAV.C W Wisconsin Electric Power Co 84/01/27 DENTON, II R Office of Nuclear Reactor Regulation. Director 20pp 22102, 283 24X Fiche 50-266,84/01/27,8402070116
- 8402140454 Ack receipt of 840123 ltr informing NRC of steps taken to correct noncompliance noted in 18 Insp Repts 50-266/83-22 & 50-201/83-21 AXELSON, W.L. Region 3. Office of Director 84/02/02 BURBTEIN, 8 Wisconsin Electric fower Co. ip 2227 107 24X Fiche 50-266,84/02/02,8402140456
 - 8402140464 Reaponds to NRC 831220 ltr re violations noted in IE Insp Repts 50-266/83-22 t 50-301/83-21 Corrective actions withheld (ref 10CFR73 21) EVRSTEIN/S Wistonsin Electric Power Co 84/01/23, KEPPLER, J Q Region 3, Office of Director ip 2227 110 24X Fiche 50-266,84/02/02,8402140454
- 402150368 Forwards SERS 50-266/83-25 & 50-301/83-23 & notice of deviation re review of revised emergency plan dtd 831111 PAPERIELLO,C J Region 3, Office of Director 84/02/02. DURSTEINS Misconsin Electric Power Co 3pp 22242 027, 24X Fiche 50-266,84/02/02,8402180368
- 8402150377 Notice of deviation from commitment to formalize agreement w/City of Two Rivers for ambulance svc # Region 3. Office of Director 94/02/02. 1p. 22242.032 24X Fiche 50-266.84/02/02.8402150368
- 40215038A SERs 50-266/83-25 & 50-301/83-23 Deviation noted emergency plan did not contain itr of agreement w/Bechtel nor itr formalising ambience see w/City of Two Rivers SMELL, N 9 & SMITH, N J , PHILLIPS, M P Region 3, Office of Director 84/02/01 28pp 22242 033 24X Fiche 50-266.84/02/02, 8402150268
- O2100222 Forwards revised emergency plan implementing procedures. FAY.C W Wisconsin Electric Power Co. 84/02/03 DENTON, H R. Office of Nuclear Reactor Regulation Director MILLER, J R. Operating Reactors Branch 3 3pp. 22178 143 24X Fiche 50~266.84/02/03,8402100222

- --8402100225 Revised emergency plan implementing procedures, including Rev 9 to Procedure EPIP 1 3 re estimation of source term. Rev 6 to EPIP 1 5 re procective action evaluation & Rev 5 to EPIP 2 3 re unusual event offsite agency notification witconsin Electric Power Co 84/01/27 100pp 22178 146 24X Fiche 30-266,84/02/03,8402100222
- B402100229 Advises that emergency plan revs meet 10CFR50 47(b) std; & 10CFR50. App E requirements Changes to emergency plan implementing procedures should be made per 10CFR50, App E. Section V PAPERIELLO, C. J. Region 3. Office of Director 84/02/07 BYRSTEIN. B. Wisconsin Electric Power Co. 1p. 22179 268 24% Fiche 50-266, 84/02/07, 8402100229
- --B402100234 Forwards revs to emergency plan manual & instruction & receipt form W/O revs
 FAY.C W Hisconsin Electric Power Co 84/01/31 DENTON.H R
 Office of Nuclear Reactor Regulation, Director MILLER, J. R
 Operating Reactors Branch 3 2pp, 22179 269 24X
 Fiche 50-266,84/02/07.8402100229
- 8402220544 Ack receipt of changes to modified amended security plan transmitted by 840123 ltr Changes consistent w/provisions of 10CFRSO 541p; & acceptable AXELSON.W L. Region 3. Office of Director 84/02/15 FAY.C W Wisconsin Electric Power Co. 2pp 22333 130 24X Fiche 50-266,84/02/15.8402220544
- G Adjudicatory correspondence
- 8402070128 Order extending time until 840213 for Commission to act to review Director's Decision DD-83-14 & extending 831029 decision denying Environ Policy Instructures to 840213 CHILMS J Depice of the Secretary of the Commission 84/02/03 Commissioners ip 22100 198 24X Fiche 50-000,84/02/03,8402070128
- 8402190175 Order extending time until 840221 for Commission to att to review Director's Decision DD-83-14 CHILK, S.J. Office of the Secretary of the Commission 84/02/13 Commissioners 1p 22245.147 24X Fiche 50-000.84/02/13;
- P Operating license stage documents & correspondence
- 0312120029 Openeric Ltr 83-39 to representatives of utils re voluntary aurvey of licensed operators 8vc list encl E(BENHUT, D 9 Division of Licensing 63/12/08 Commonwealth Edison Co 12pp 22313 006 24X Fiche 50-000,83/12/08,8312120029
- B402070490 Forwards safety evaluation re NUREQ-0737. Item II K 2 17, "Potential for Voiding in RCS During Transients." per B01223 & 820426 submittals & Westinghouse Owners Group Rept W00-57 Item satisfactorily resolved MILLER, J R Operating Reactors Branch 3 84/01/24 FAY, C W Wisconsin Electric Power Co 10pp 22141: 340 R4X Fishe 50-266.84/01/24.8402070490.
- B402090519 Summary of B40110 meeting w/util in Bethesda, MD re licensee requested exemptions from requirements of & extension to effective date of shift staffing rule, 10CFR50, 54 List of ottendees encl CCLBURN, T G Operating Reactors Branch 3 B4/01/24 MILLER, J R Operating Reactors Branch 3 B4/01/24 MILLER, J R Fiche 50-266, 84/01/24, 8402090519
- 8402060137 Bubmits info re add1 minor revs to plans & procedures during steam generator replacement, per 830909 ltr Single pipe out procedure used on hot leg & cold leg reactor coolant piping. FAY.C W. Wisconsin Electric Power Co 84/01/27 DENTON: H R Office of Nuclear Reactor Regulation, Director. MILLER, J. R Operating Reactors Branch 3 2pp. 22089 102 24% Fithe 50-266,84/01/27,8402060137
- B4020B0194 Application for amend to Licenses DPR-24 & DPR-27, consisting of Tech Spec Change Request 97 per Generic Ltr 83-43 reflecting revised reporting requirements FAY.C.W Wisconsin Electric Power Co B4/01/27 DENTON, H R. Office of Nuclear Reactor Regulation, Director, EIGENHUT, D Q Division of Licensing. 2pp 22129, 325 24X Fiche 50-264, 84/01/27, 8402080194
- ---8402080199 Proposed Tach Spec Change Request 97 per Generic Ltr 63-43 reflecting revised reporting requirements
 * Wisconsin Electric Power Co. 84/01/27 8pp 22129: 327 24x
 Fiche 50-264,84/01/27,8402080194

- 8402070186 Provides add1 info re status of auxiliary feedwater sys mods implemented in response to Generic Ltr 81-14 Last remaining mod involves replacement of battery rack support straps & should be completed by Oct 1984

 FAY.C W Wisconsin Electric Power Co 84/01/31 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 1p 22102 193 24X

 Fiche 50-266,84/01/31,8402070186
- 8402010410 Generic Ltr 84-04 to all operating PWR licentages, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Svc list encl EIGENHUT, D @ Division of Licensing 84/02/01 Consolidated Edison Co of Naw York, Inc 59pp 22177 087 24X Fiche 50-000,84/02/01,8402010410.
- 8402160588 Forwards Amends 82 & 86 to Licenses DPR-24 & DPR-27, respectively & safety evaluation Amends clarify limiting conditions for operation of steam generators & other DHR equipment only applicable when fuel loaded in core CDLBURN.T O. Operating Reactors Branch 3 84/02/02 FAY.C W Wisconsin Electric Power Co 2pp 22302 054 24X Fiche 50-264.84/02/02.8402160588.
- --8402160590 Amends 82 & 86 to Licenses DPR-24 & DPR-27, respectively, ORLOOSU Amende 62 & 86 to titeenses DPR-24 & DPR-27, respect: clarifying limiting condition for operation of steam generators & other DHR equipment, indicating conditions only applicable when fuel loaded in core.
 MILLER, JR Operating Reactors Branch 3 84/02/02 5pp 82302 036 24X Fiche 50-266,84/02/02,8402160588
- --8402160594 Bafety evaluation supporting Amends 82 & 86 to Licenses DPR-24 & DPR-27.respectively * Office of Nuclear Reactor Regulation, Director 84/02/02 2pp 22302-061 24X Fithe 50-266.84/02/02,8402160588
- 8402150261 Requests repast of 791130 & 800103 confirmatory orders re provisions for operation pertaining to steam generator tubes. Steam generator Lower assemblies replaced FAY.C.W Wisconsin Electric Power Co. 84/02/06 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 22250 283 24X Fichs 50-286.84/02/06.8402150261.
- B402130177 Application for mods to 831025 amend application, consisting of Tech Spec Change Request 94 incorporating changes to ment containment integrated leakage testing requirements of 10CRT80. App J.

 FAY.C W. Wisconsin Electric Power Co 84/02/07 DENTON, H R Deffice of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3. 3pp 22204: 146 24X Fiche: 50-266,84/02/07,8402130177
- --B402130187 Proposed changes to Tech Specs incorporating changes to meet containment integrated leak testing requirements of 10CFR50, App J. * Misconsin Electric Power Co. 84/02/07. 5pp 22204:149 24X Fiche 50-266,84/02/07.8402130177
- B402160181 Supple B31025 application for amend to Licenses DFR-24 & DFR-27, consisting of Tech Spec Change Request 94 re-criteria for Type A integrated leak rate testing FAY.C.M. Wisconsin Electric Power Co 84/02/07 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3, 110pp 22276 044 24X Fichs: 50-266,84/02/07,8402160181
- --8402160188 Proposed Tech Specs supplementing Tech Spec Change Request 94 re integrated leakage rate testing
 * Wisconsin Electric Power Co 84/02/07 5pp. 22276.047 24X Fiche: 50-286,84/02/07.8402160181.
- --8402160195 "Critaria for Determining Duration of Integrated Leakage Rate Tests of Reactor Containments." ROWLEY.C. W , RENTON.T E, , MARTIN.J.K. Quadrex Corp. EPRI NP-3400, 83/12/31. 100pp R2276:052 24X Fiche: 50-266, 84/02/07, 8402160181
- G Inspection reports, IE Bulletins & correspondence
- B402140239 Forwards security plan changes & drawings & responses to IE Safaguards Insp Repts 50-266/83-22 & 50-301/83-21, Encis withheld (yef 100FR79 21)
 BURSTEIN, B. Hisconsin Electric Power Ca. 84/01/23 KEPFLER, J Q Region 3, Office of Director ip 22220, 282 24X
 Fiche: 50-266, 84/01/23, 8402140239.
- B312120183 IE Info Notice 84-06, "Steam Binding of Auxiliary Faedwater Fumps." Svc list encl. JORDAN.E.L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co. of New York, Inc. 120pp 22058-001. 24X Fiche 50-000.84/01/25,8312120183

- B402140434 Ack receipt of 840123 itr informing NRC of steps taken to correct noncompliance noted in IE Imp Repts 50-266/83-22 & 50-301/83-21 AXELSON,W L Region 3. Office of Director 84/02/02 BURBTEIN,S Wisconsin Electric Power Co ip 22227 109 24x Fiche 50-266,84/02/02,8402140454
- --8402140464 Responds to NRC 831220 ltr reviolations noted in IE Insp Repts 50-266/83-22 & 50-301/83-21 Corrective actions withheld (ref LOCFR73 21) BURSTEIN'S Wisconsin Electric Power Co 84/01/23 KEPPLER, J G Region 3, Office of Director ip 22227 110 24X Fiche 50-266,84/02/02,8402140454
- 8402150368 Forwards SERs 50~266/83-25 & 50-301/83-23 & notice of deviation re review of revised emergency plan dtd 831111 PAPERIELLO.C J. Region 3. Office of Director 84/02/02 BURSIEIN.S Wisconsin Electric Power Co 3pp 22242 027 24 Fiche 50-266.84/02/02,8402150368 22242 029 24X
- --8402150377 Notice of deviation from commitment to formalize agreement w/City of Two Rivers for ambulance svc
 * Region 3, Office of Director 84/02/02, ip 22242 032 24X
 Fiche 50-266,84/02/02,8402150368
- --8402150386 SERs 50-266/83-25 & 50-301/83-23 Deviation noted emergency plan did not contain ltr of agreement w/Bechtel nor ltr formalizing ambulance svc w/City of Two Rivers BNELL, W 0 , SHITH, M J , PHILLIPS, M P Region 3, Office of Director 84/02/01 RBpp 22242 033 24X Fiche 50-266,84/02/02,8402150348
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vahicular Excess Controls "Svc list encl JURDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co. of New York Inc. 119pp 22114 179 24X Fiche 50-000.84/02/03.8401190016
- 8401190017 IC Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl. DEYBUNG.R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177,156 24X Fiche 50-000,84/02/03,8401190017
- 8402180261 Requests repeal of 791130 & 800103 confirmatory orders re provisions for operation pertaining to steam generator tubes Steam generator lower assemblies replaced.

 FAY.C W Wisconsin Electric Power Co 84/02/06 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 22250 283 24X Fiche. 50-266, 84/02/06, 8402150261
- 8401170041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection 8afe Shutdown 8gs (100FR50 App R)" Syc list encl. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp. 22365-259 24X Fiche 50-000,84/02/13,8401190041
- 8401190039 IE Info Notice 84-08. "IQCFR50 7, 'Employee Protection,'"
 Svc list encl
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co. of New
 York, Inc. 115pp. 22365 141 24X Fiche 50-000.84/02/14,8401190039
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Westinghouse Type 8A-1 Differential Relays," Svc list encl UDRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/15 Consolidated Edison Co of New York, Inc. 118pp 22366 142 24X Fiche 50-000, 84/02/15, 8401190045
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Bet Below Manufacturer Recommended Value " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp. 22366 024, 24X Fiche 50-000,84/02/21,8401190062
- 8401190066 IE Info Notice 84-ii, "Training Program Deficiencies " 401190060 IE INTO MENTER TO THE TRANSPORT OF THE PROPERTY PROPERTY & Engineering JORDAN, E. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/02/24. Consolidated Edison Co of New York, Inc 115pp 22430.304 24X Fiche 50-000, 84/02/24, 8401190066
- 8401170067 IE Info Notice 84-12, "Failure of Soft Seat Valve Beals " 101190067 IE Info Notice 69-18. Passage of Constitution of Sec list encl
 JORDAN: E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co. of New
 York: Inc. 120pp. 22431 060 24X Fichs 50-000/84/02/27, 8401190067

R Periodic operating reports & related correspondence

8402140227 Monthly operating repts for Jan 1984 W/840209 ltr FAY,C W Wisconsin Electric Power Co 84/01/31 10pp 22230 011 24X Fiche 30-266,84/01/31,8402140227

V Operator Examinations

8402210120 Revises 830730 submittal re licensed operator staffing Extension until 850301 for implementation date requested Util withdraws exemptions for second senior reactor operator & third operator when one unit running & second refueling FAY.C W Wisconsin Electric Power Co 84/02/14 DENTON H R Office of Nuclear Reactor Regulation. Director 3pp 22317 203 24% Fiche 50-266,84/02/14,8402210120

DOCKET 50-267 FORT BT VRAIN NUCLEAR GENERATING STATION F Security, medical, emergency & fire protection plane

8402010151 Forwards "Safety Parameter Display Sys Program Plan" & responds to NRC 831205 ltm re control room design review in-progress audit Audit proposed to take place during whof 840312 BREY. H L. Public Bervice Co. of Colorado 84/01/20 COLLINS, J Reyen 4, Office of Director 2pp 22038 261 24X Fishe 50-267.84/01/20.8402010151

--8402010137 "Safety Parameter Display Sys Frogram Flan," in response to Generic Ltr 82-33, Suppl 1 to NUREG-0737 * Public Service Co of Colorado 83/09/30 38pp 22038 263 24X Fiche 50-267, 84/01/20, 8402010151

8402170i33 Comments on 1983 BALP rept Rept should not infer violations more significant in 1983 Overell Tech Spec review planned in 1984 Recommends that water chemistry & radiochemistry be considered separate areas within SALP evaluation LEE, O.R. Public Service Co. of Colorado. 84/01/24 COLLING, J.T. Repion 4. Defice of Director. 14pp. 22296 112 24X Fiche 50-267.84/01/24.8402170133

P Operating license stage documents & correspondence

B312120029 Generic Ltr B3-39 to representatives of utils re voluntary survey of literaged operators Bvc list encl.
EISENHUT.D O Division of Licensing B3/12/08 Communwealth Edison Co 12pp 22313 004 P4X Fiche 50-000.83/12/08.8312120029

2010233 Requests FR publication of notice of issuance of Amend 39 o License DPR-34 modifying Tech Specs re upgraded equirements for hydraulic snubbers per NRC positions & new echanical snubber requirements.

ORNSON: E H Region 4, Office of Director BA/01/25, MILLER, J R perating Reactors Smach 1, 2pp. 22042, 255, 24% iche 50-247,84/01/25,8402010233

J2070366 Forwards Amend 39 to License DPR-34 & safety evaluation Amend revises Tech Spec requirements for safety-related shock suppressor (snubbars)

HANNER.P.C. Region 4, Office of Director 84/01/25 LEE.O.R.

Public Service Co. of Coloredo. 3pp. 22099,081 24x

Fichs 50-267,84/01/25,8402070366

---8402070357 Amend 39 to License DPR-34, revising Tech Spec requirements for safety-related shock suppressors (anubbers)
JDHNBON,E H Region 4, Dffice of Director, B4/01/25 26pp
22099.084 24% Fishe: 50-267,84/01/25,8402070366.

402070369 Safety evaluation supporting Amend 39 to License DPR-34 * Office of Nuclear Reactor Regulation, Director 84/01/25. Spp 22099:110 24% Fiche 50-267,84/01/25,8402070366

2060496 Notification of 840229 meeting w/util & INEL in Esthesia.MD o discuss future actions necessary to resolve outstanding saves re environ qualification of electrical equipment.
ARSCH.R.O. Operating Reactors Assessment Branch 84/01/30 OLAHAN.9 M. Operating Reactors Assessment Branch 2pp 22110:164 24X Fiche 50-267,84/01/30,8402060496

130148 Expresses concern re applicability of general source-term less for max risk to all operating reactors. Facility should considered.

REMBOURG.D.W Public Service Co. of Colorado. 84/01/30.

LLINB.J.T. Region 4, Office of Director, 1p. 22249:275, 24X che 50-267.84/01/30.8402150148.

- 8402140412 Advises that revs to Tech Specs not required, per review of request re completion of mode required for NUREQ-0737 Items
 11 B 1, 11 B 3, 11 E 1 1, 11 F.1, 11 F 2 & 111 D 3 4 (Qeneric Ltrs 83-07 & 83-34)
 MAREMBOURD, D W Public Bervice Co of Colorado 84/02/09.
 EISENHUT, D Q Division of Licensing 8pp 22275 122 24x
 Fiche: 50-267, 84/02/09, 8402140412
- --8309230347 Completes review of responses to questions re NUREG-0737, Item III D 3 4, "Control Room Habitability " Criteria met Item closed MADELN.O L Region 4. Office of Director B3/09/08 LEE.O.R Public Service Co of Colorado 2pp 22275 220 24X Fichs 50-267, 84/02/09.8402140412
- B402B10180 Advises that NRC has been informed that add1 clarifications & changes to radiological effluent Tech Specs will be requested Recommends that issue of functional testing requirements be considered for inclusion in request JDHNSON,E H Region 4, Office of Director B4/02/14, LEE,O R. Public Service Co of Colorado 2pp 22316 335 24X Fiche 50-267,84/02/14,8402210180
- 8402210212 Requests resubmittal of application for disposal of licensed math to include listed info Restrictions for math quantities & disposal methods should be proposed as Tech Spec limits

 JOHNSON, E H Public Service Co of Colorado 84/02/14. LEE, O R Region 4. Office of Director 2pp 82316 164 24X Fiche 50-267.84/02/14.8402210212

G Inspection reports, IE Bullstins & Correspondence

8402170133 Comments on 1983 SALP rept Rept should not infer violations more significant in 1983 Overall Tech Spec review planned in 1984 Recommends that water chemistry & radiochemistry be considered separate areas within SALP evaluation LEE, O R Public Service Co of Colorado 84/01/24 COLLING.J.T Region 4, Office of Director 14pp 22276:112 24X Fiche. 50-267.84/01/24.8402170139

83:222053 IE Info Notice 84-06. "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830:103) 84/01/25 Consolidated Edison Co. of New York, Inc 120pp 22058.001 24X Fiche 50-000.84/01/25.8312120153.

8402150185 Ack receipt of 831212 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-267/83-29, JOHNSON, E H Regison 4. Office of Director 84/02/01 LEE, O R Public Service Co of Colorado ip 22245 210, 24x Fiche: 50-267, 84/02/01.8402150185

8401190016 IE Info Notice 84-07, "Design-Dasis Threat & Review of Vehicular Excess Controls," Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/02/03 Consolidated Edison Co. of New York, Inc 119pp. 22114-179 24X Fiche 30-000,84/02/03,8401190016

B401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vant Headers." Svc list encl DEYOUNG.R.C Director's Office, Office of Inspection and Enforcement. B4/02/03, Consolidated Edison Co. of New York, Inc. 102pp 22177 156. 24X Fiche. 50-000. 84/02/03. 8401190017.

8402170048 Notifies of schedule change to test to qualify NP-1 splansif valves to min life of 8 yrs using ambient temp of 140 F. Replacement of coils will continue as before w/periodic replacement as necessary.

BREY.M.L. Public Service Co. of Colorado, 84/02/03, COLLINS,J Y. Region 4, Office of Director 2pp 22299 353 24X Fiche: 50-267, 84/02/03, 8402170048

8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Inspa of Fire Protection Safe Shutdown Sys (10CFR50, App R), " Syc list encl.

JCRDAN: E L. Division of Energency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc. 124pp. 22365, 259 24X Fichs: 80-000,84/02/13,8401190041

8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection.'"
Svc list encl
JURDAN,E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 84/02/14. Consolidated Edison Co of New
York, Inc 115pp. 22365 141 24X Fiche: 50-000,84/02/14,8401190039.

8401190045 IE Info Notics, 83-63, Suppl 1, "Potential Failures of Westinghouse Type 8A-1 Differential Relays." SVc list encl.

JDRDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366-142 24X Fiche. 50-000, 84/02/15, 8491190045

- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Buitches Set Below Manufacturer Recommended Value " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc. 116pp 22366 024 24X Fiche 50-000,84/02/21,8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies "
 - Oil90066 IE Info Notice 89-11, Training Frogram Services Services Seve list encl
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
 - Svc list enci JURDANN E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/27 Consolidated Edison Co of New York, Inc. 120pp. 22431 060 24X Fiche 50-000.84/02/27.8401190067
- R Periodic operating reports & related correspondence
- B402060129 Revised monthly operating rept for Nov 1983 W/B40131 ltr FULLER, C , WAREMBOURG, D W Public Service Co of Colorado 83/11/30 2pp 22089,017 24X Fiche 50-267,83/11/30,8402060129
- 8402210197 Monthly operating rept for Jan 1984 W/840213 ltr FULLER, C., WAREMBOURG, D. Public Service Co. of Colorado. 84/01/31 10pp 22316-171 24X Fiche-50-267,84/01/31,8402210197
- 8402280377 Forwards revised monthly operating repts for Oct, Nov & Dec 1983 & Jan 1984 Corrections concern calculation of unit forced outage rate. WAREMBOURG, D W. Fublic Bervice Co. of Colorado 84/02/23 Director's Office, Office of Inspection and Enforcement 1p 22402.224 24X Fiche 50-247,84/02/23,8402280377
- --B402280379 Revised monthly operating rept for Oct 1983 FULLER: C Public Bervice Co of Colorado. 83/10/31 22402 227. 24X Fiche.50-267.84/02/23.8402280377
- --8402280383 Revised monthly operating rept for Nov 1983 FULLER, C. Public Bervice Co of Colorado 83/11/30 22402 228 24X Ficher 50-267,64/02/23,8402280377.
- --8402280385 Revised monthly operating rept for Dec 1983 FULLER, C Public Service Co of Colorado. 83/12/31. 22402:229. 24X Fiche:50-267.84/02/23.8402280377
- --B402280389 Revised monthly operating rept for Jan 1984 FULLER, C Public Bervice Co of Colorado 84/01/31 22402, 230, 24X Fiche, 50-267, 84/02/23, 8402280377
- 8 Reportable occurrences, LERs & related correspondence
- 8402240086 Further response to FOIA request for 16 categories of documents. Item 9 limited, per 831005 telcon. Forwards Rev 7 to NUREQ-0525 & App A documents. Portions of App B documents withheld (ref FOIA Exemption 4) App B documents also in PDR FELTON. J. M. Division of Rules and Records. 83/12/12 SHDLLY, Union of Concerned Scientists 4pp. 22374:150. 24% Fiche: 50-000, 83/12/12, 8402240086. SHOLLY, B C.
- --8308170014 Security event rept re 830728 occurrence HAREMBOURG, D. W. Public Bervice Co. of Colorado, 83/08/01 COLLINS, J. T. Region 4, Office of Director. 2pp 22394 1 Fiche, 50-000, 83/12/12, 8402240086. 22394 157. 24X
- --8309200043 Security event rept re 830906 occurrence.
 WAREMBOURG D. W Public Bervice Co. of Colorado. 83/09/07.
 COLLINS.J.T Region 4. Office of Director. 2pp. 22394.163. 24X
 Fiche: 50-000, 83/12/12, 8402240086.
- 8402150204 LER 84-001-00.on 840101-10.radioactive gaseous effluent activity monitor alarm/trip setpoints not adjusted per offsite dose calculation manual. Implementation requirements not met. Setpoints adjusted. W/840131 ltr. NOVACHEK, F., WAREMBOURG, D. Public Bervice Co. of Colorado 84/01/31. COLLINS, J T. Region 4. Dffice of Director 7pp. 22245, 139. 24X Fiche 50-267, 84/01/31, 8402150204
- 8402220048 Forwards LER 84-001, W/o encl, MAREMBOURG, D. Public Service Co. of Colorado, 84/01/31. COLLINS.J.T. Region 4, Office of Director 1p 22335.362. 24X Fiche: 50-267, 84/01/31, 8402220048

X Onsite Storage of Low Level Waste

- 8402010153 Advises that response to Generic Ltr 81-39, "Storage of Low NOZOLOIDS Advises that response to Generic Ltr 81-38, "Si Level Radwaste of Power Reactor Sites," not required Evaluation per 10CFR50 59 should be completed by 840630 JDHNSUN.E H Region 4, Office of Director 84/01/27 Public Service Co of Colorado 2pp 22038 301 24X Fiche 50-267.84/01/27,8402010153
- DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8402210077 Application for proposed amend to Licenses DPR-38.DPR-47 & DPR-35.defining term accessible/accessibility & incorporating addl fire hose stations located in reactor blig
 TUCKER, H B Duke Power Co 84/02/13 DENTON, H R Off
 Nuclear Reactor Regulation, Director 3pp 22317 288
 Fiche 50-269, 84/02/13, 8402210077
- --8402210081 Proposed Tech Spec rev, defining term accessible/ accessibility, incorporating add1 fire hose stations & updating FBAR * Duke Power Co 84/02/13 39pp 22317 291 24X Fiche 50-269,84/02/13,8402210077
- B40222007: Forwards Rev 3 to Vols 1 & 2 to "Response to Suppl i, NUREO-0737 " Enc. rev includes control room review final & supplemental repts & safety parameter display sys safety analysis
 TutokeR: H B Duke Power Co B4/02/16 DENTON, H R Office of
 Nuclear Reactor Regulation, Director BTDLZ, J F Operating Reactors
 Branch 4. 3pp 22327.046 24X Fiche 50-269,84/02/16.8402220071
- --8402220077 Rev 3 to Vols 1 & 2 to "Response to Suppl 1; NUREG-0737 "

 * Duke Power Co 84/02/16 250pp. 22327 049 24%
 Fiche 50-269,84/02/16:8402220071
- J Insurance & indemnity information
- 8402210213 Forwards undorsements to NELIA & MAELU policies, including Endorsements 73 & 74 to NELIA Policy NF-182, Endorsements 57 & 58 to MAELU Policy MF-61 & Endorsement 4 to MAELU Policies M-22, M-23 & M-24 n-ex: n-e3 x n-e4 LANBDN,L.T Duke Power Co 84/02/15 BALTZMAN,J. NRC - No Detailed Affiliation Given 18pp 22316 277 24X Fiche.50-000:84/02/15.8402210213
- P Operating license stage documents & correspondence
- 8402080032 "RELAPS Thermal-Hydraulic Analysis of Pressurized Thermal Shock Sequences for Ocones-1 PWR " Belling to Ecologian Co., BOLANDER, M. A., STITT, B.D. Ecologian, C.F.IN A-6047. Ecol-NBM-6343 83/07/31 NRC No Detailed Affiliation Given 252pp 22173 003. 24X Fiche 50-269,83/07/31,8402080032
- 8402090608 "Failure Modes & Effects Analysis of Integrated Control Bys/ Non-Nuclear Instrumentation Electric Power Distribution Circuitry," interim rept * Science Applications, Inc 83/08/26 33pp 22189 304 24X Fiche 50-289
- 8402090306 "Failure Modes & Effects Analysis for Ocones 1 Nuclear Powe Station Makeup & Purification Sys." preliminary draft. # Science Applications, Inc. 83/10/03. 145pp 22187:001. 24X Fiche:50-269.83/10/03.8402090306.
- 8402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILK. B. J. Office of the Secretary of the Commission 83/12/14. Public Document Branch. 1p. 22281.023 24X Fiche 50-000,83/12/14. 8402160003
- --8402160177 Discusses SECY-81-579, ALAB-651 re transportation of spent NORLOGY/ Discusses Nuclear Station for storage at McQuire
 Nuclear Station
 CHILK: 3.1. Diffice of the Secretary of the Commission. 81/10/27
 BICKHIT, L. Diffice of the General Counsel 1p. 22281:117 24X
 Fiche. 50-000, 83/12/14, 8402160003
- 8402240309 Partial response to FOIA request for eight categories of documents re OL amends. Forwards App A documents. Documents also in PDR
 FELTON, J. M Division of Rules and Records. 83/12/14, BE
 Nuclear Information & Resource Service 4pp 22414 060.
 Fiche: 50-287, 83/12/14, 8402240309.

- --8402240353 Advises of issuance of Amends 123,123 & 120 to Licenses DPR-3G, DPR-47 & DPR-55, respectively, changing Tech Specs to authorize expansion of spent fuel pool to 825 storage locations
 SUERMANN, J. F. Operating Reacture Branch 4 B3/09/29 DENTON, H. F. NRC No Detailed Affiliation Given ip 22414 100 24X
 Fiche 50-287, 83/12/14, 8402240309
- --8402030045 Amends 125,125 & 126 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising radiological effluent Tech Specs for compliance w/App I of 100FR50 BTOL7.JF Gperating Reactors Branch 4 B4/01/16 74pp 22091 130 24X Fithe 50-269.84/01/16.8402030035
- --8402030065 Safety evaluation supporting Amands 125,125 & 126 to License DPR-38, DPR-47 & DPR-55, respectively * Diffice of Nuclear Reactor Regulation, Director 84/01/16 41pp 82091 204 24X Fiche 30-269,84/01/16,8402030035
- 8402070399 Notification of 840213-14 meetings w/util in Seneca.SC to review implementation of selected NUREG-0737 items SUERNANN.JF Operating Reactors Branch 4 39 22142-137 24X Fiche. 50-269.84/01/27.8402070399.
- B402150444 Forwards Amends 124, 126 & 123 to Licenses DPR-3B, DPR-47 & DPR-55, respectively & safety evaluation Amends revise Tach Specs to correct values for axial power shaping rod position limits after 385 EFPD for Unit 3. Cycle 7 operation STOLZ, J F Operating Reactors Branch 4 B4/01/30 TUCKER, H B Buke Power Co 2pp 22258 272 24X Fiche: 50-267, 84/01/30, B402150446
- --8402150452 Amends 126.126 & 123 to Licenses DPR-38,DPR-47 & DPR-55, respectively.revising Tech Specs to correct values for axial nower shaping rud position limits after 385 EFPD for Unit 3, Cycle 7 operation 8TDLZ,JF Operating Reactors Branch 4 84/01/30 9pp 22258.274 24X Fishs 30-247,64/01/30.8402130446
- --8402150457 Safety evaluation supporting Amends 126,126 & 123 to Licenses DPR-38, DPR-47 & DPR-55; respectively. * Office of Nuclear Reactor Regulation, Director 84/01/30 2pp 22298 303 24% Fiche 50-269, 84/01/30,8402150446
- 84D2010410 Generic Ltr 84-04 to all operating PHR licensess, CP holders & applicants for CPs re-safety evaluation of Westinghouse topical repts dealing w/slimination of postulated pipe breaks in PHR primary main loops Svc list encl EISENHUT, D. G. Division of Licensing. 84/02/01. Consolidated Edison Co of New York, Inc. 59pp 22177 087. 24X Fiche 50-000, B4/02/01, B402010410
- 8402130616 Advises that Class III license fee remitted w/830309 application requesting exemption from requirements of IOCFR50. App E. Section IV F will be refunded. Exemption authorized by law & is in public intenset MILLER. W. D License Fee Hanagement Branch 84/02/03 TUCKER. H B Duke Power Co Ip 22214 295 24X Fiche 50-000. 84/02/03. 8402130616
- B402100418 "TRAC Analyses of Severe Overcooling Transients for Oconee-1 PHR " BASSETT, B. BDYACK, B., BURKETT, M. Los Alamos Scientific Laboratory LA-UR-83-3182 84/02/04. Division of Accident Evaluation (Pre 840101) 237pp 22212:001 24X Fiche. 50-269, 84/02/04, 8402100418
- 8402230192 Summary of 840131 meeting w/util & INEL re equipment qualification program review List of attendees encl SUERMANN.J F Operating Reactors Branch 4. 84/02/08 Departing Reactors Branch 4. 4pp 22379:189, 24X Fiche: 50-269, 84/02/08, 8402230192
- 8402210077 Application for proposed amend to Licenses DPR-OB, DPR-47 & DPR-55, defining turn accessible/accessibility & incorporating addl fire hose stations located in reactor bldg.

 TUCKER: H. B. Dute Power Go 84/02/13 DENTON, H.R. Defice of Nuclear Reactor Regulation, Director. 8TOLZ.J F Operating Reactor Branch 4 Tan 1991 288 24X Fichs 50-269, 84/02/15, 8402210077

- --B402210081 Proposed Tech Spec revidefining term accessible/ accessibility.incorporating addl fire hose stations & updating FSAR * Duke Power Co 84/02/13 39pp 22317 271 24X Fichm 50-249, B4/02/13.8402210077
- 8402210174 Application for amend to Licenses DPR-3B, DPR-47 & DPR-35 re proposed Tech Spec change to core protection safety limits, protective sys max allowable setpoints & rod position limits

 TUCKER.H B Duke Power Co 84/02/13 DENTON.H R Office of Nuclear Reactor Regulation, Director STOLZ.J F Deprating Reactors, Branch 4 4pp 22317 033 24X Fiche 50-269,84/02/13,8402210174
- --8402210184 Proposed Tech Specs re core protection safety limits, protective symmax ellowable setpoints & red position limits * Duke Power Co. 84/02/13 73pp 22317 037 24X Fiche 50-269,84/02/13/8402210174
- --8402210191 "Cycle 8 Relaad Rept.Feb 1984 "

 * Duke Power Co DCP-RD-2003 84/02/29, 46pp 22317,110, 24x
 Fiche 50-269,84/02/13.8402210174.
- 8402220517 Application for amend to Licenses DPR-38, DPR-47 & DPR-55 revising Yech Specs to establish degraded mode for emergency condenser cooling water sys TUCKER. H B Duke Power Co 84/02/13 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4. 3pp 22331 314 24X Fichs 50-269,84/02/13,8402220517
- --8402220521 Proposed Tech Specs establishing degraded mode for emergency condenser cooling water sys * Duke Power Co 84/02/13 7pp 22331 317 24X Fiche 50-269,84/02/13.8402220517
- O Inspection reports, IE Bulletins & correspondence
- B402140203 Forwards IE Insp Repts 50-269/83-37, 50-270/83-38 & 50-287/83-37 on 831227-29 No violations or deviations noted, DANCE, H C Divisions of Project & Resident Programs 84/01/12 TUCKER, H B Dake Power Co Zpp. 22229 329, 24X Fiche 50-269,84/01/12.8402140203
- --B402140211 IE Insp Repts 50-269/83-37.50-270/83-38 & 50-287/83-37 on 831227-29 No violations or deviations noted Major areas inspected RCB leakage calculations BURNETT.P T. Region 2. Office of Director. JAPE.F. Division of Engineering & Operational Programs 84/01/11 9pp 22227.331 24X Fiche 50-849.84/01/12,8402140203
- 8402150012 Forwards IE Insp Repts 50-249/83-38 50-270/83-39 & 50-287/83-38 on 831219-22 No violations or deviations noted, DANCE H C. Division of Project & Resident Programs 84/01/17, TUCKER, H B Duke Power Co. 2pp 22249-225 24X Fiche 50-269.84/01/17,8402150012
- ---8402150017 IE Insp Repts 50-249/83-38 50-270/83-39 & 50-287/83-38 on 831219-22 No violations noted Major areas inspected radwaste procedures, radioactive effluent permits & repts & effluent radiation menitor alarm settings WEDDINOTON R. E Region 2, Office of Director. BARR, K. P Division of Engineering & Operational Programs. 84/01/13 6pp. 22247 228 24% Fiche 50-269,84/01/17,8402150012
- 8402150011 Forwards IE Insp Repts 50-269/83-39, 50-270/83-40 & 50-267/83-39 on 831228-29. No violations or deviations noted DANCE, H C Division of Project & Resident Programs 84/01/19, TUCKER, H B Dake Power Co. 2pp 22249, 303, 24X Fiche, 50-269, 84/01/19, 8402150011
- 8402150014 IE Imsp Repts 50-269/83-39, 50-270/83-40 & .50-287/83-39 on 831228-29 No violations or deviations noted Major areas inspected trip time testing of GE Type AKZ reactor trip breakers.
 GIBBUNS, T. D. Region 2, Office of Director. CONLON, T. E. Division of Engineering & Operational Programs. 84/01/18, 3pp. 22249:305 24X Fiche 50-269, 84/01/19, 8402150011
- 8312120153 IE Info Notice 64-06, "Steam Binding of Auxiliary Feedwater Pumps," Svc list enci JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/25 Consolidated Edison Co. of New York, Inc 120pp. 22058 001, 24X Fiche; 50-000, 84/01/25, 8312120153
- 8402280266 Forwards IE Insp Repts 50-269/84-01.50-270/84-01 & 50-287/84-01 on 840109-12 No violations or deviations identified.

 DANCE R C Division of Project & Resident Programs 84/01/26. TUCKER. H. B. Duke Power Co 2pp. 22399.186 24X Fiche: 50-269, 84/01/26, 8402280266

- --8402280270 IE Insp Repts 50-269/84-01, 50-270/84-01 & 90-287/84-01 on 840109-12 No violations or deviations identified Major areas inspected refueling physics tosting & reactivity balance calculations

 DAVENPORT, K E Region 2, Office of Director JAPE, F Division of Engineering & Operational Programs 84/01/24 Spp 22399 188 24% Fichs 50-269, 84/01/26, 8402280266
- B402280532 Forwards IE Insp Repts 50-269/83-40.50-270/83-41 & 50-287/83-40 on 83i211-840i10 No violations or deviations noted DANCE.H C Division of Project & Resident Programs 84/01/30 TUCKER,H B Duke Power Co 2pp 22406 172 24X Fiche 50-269, 84/01/30, 8408280532
- --8402280542 IE Insp Repts 50-267/83-40, 50-270/83-41 & 50-287/83-40 on 831211-840110 No violations or deviations noted Major areas inspected operations, surveillance, maint & offsite safety review board activities
 BRYANT.J, FALCOMER.D Region 2, Office of Director BROWNLEE, V Division of Project & Resident Programs 84/01/27 7pp 22406:174 24X Fiche 50-269, 84/01/30, 840R280532
- 8402140143 Ack receipt of 840106 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-249/83-33, 50-270/83-33 BANCE.H C. Division of Project & Resident Programs 84/01/31 TUCKER.H B Duke Power Co ip 22218 201 24X Fiche: 50-269.84/01/31,8402140143
- --8402140149 Responds to NRC 831208 ltr re violations noted in IE Insp Repts 50-269/83-33.50-270/83-33 & 50-287/83-33 Corrective actions.station program for identification & evaluation of nonroutine eyents revised TUCKER.M.B. Duke Power Co 84/01/06 O'REILLY, J.P. Region 2, Office of Director 2pp 22218 202 24X Fiche 50-269.84/01/31, 8402140143
- ---8402140153 Forwards IE Insp Repts 50-269/83-33, 50-270/83-33 & 50-287/83-33 on 831011-1110 & notice of violation DANCE, H C Division of Project & Resident Programs 83/12/08 TUCKER, H B Duke Power Co 2pp 22218 204. 24X Fichs: 50-269, 84/01/31, 8402140143.
- --8402140167 IE Insp Repts 50-269/83-33, 50-270/83-33 & 50-287/83-33 on 831011-1110 Violation noted Keowee hydro unit unavailable for maint longer than 72 h & degradation beyond Tech Space not subj to 831101 safety evaluation BRY4MT. J. FALCONER, D Region 2, Office of Director BROWNLEE, V Division of Project & Resident Programs. 83/12/07 11pp. 22218,207. 24X Fiche:50-269,84/01/31,8402140143
- --8402140157 Notice of violation from insp on 831011-1110 * Region 2, Office of Director 83/12/08 ip. 22218-206 24X Fiche. 50-269,84/01/31,8402140143
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls." Svc list encl.
 JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000, 84/02/03, 8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl. BEYOUNG,R C. Director's Office, Office of Inspection and Enforcement. 84/02/03 Consolidated Edison Co of New York, Inc 102pp. 22177:156. 24X Fiche:50-000,84/02/03,8401190017.
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection 8afe Shutdown 8ys (10CFR50, App R)." Syc list encl.

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/13. Consolidated Edison Co. of New York, Inc. 124pp. 22365-259 24X Fiche 50-000,84/02/13,8401190041
- 8401190039 IE Info Notice 84-08, "10GFR50.7, 'Employee Protection '"
 Byr list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Fost 830103). 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp. 22345:141 24X Fiche. 50-000, 84/02/14, 8401190039
- 8402230202 Forwards evaluation of relief request & notice granting relief from inservice insp requirements of Section XI of ABME Boiler & Pressure Vessel Code.

 BTOLZ.J.F. Operating Reactors Branch 4, 84/02/14, TUCKER, H. B Duks Power Co 3pp. 22379, 168, R4X Fiche 50-269,84/02/14, 04/02/2000

- --B402230212 Evaluation of relief request from inservice insp program
 Relief from preservice hydrostatic tests justifiable
 Alternative NDE program proposed by Duke Power Co,will
 provide acceptable level of structural integrity
 * NRC No Detailed Affiliation Given 64/04/14 13pp
 22379 171 24X Fiche 50-269.84/02/14,6402230202
- --8402230217 Notice of granting relief from ASME Code.Section XI Inservice insp requirements STOLZ.JF Operating Reactors Branch 4 84/02/14 2pp 22379 184 24X Fiche 50~269.84/02/14.8402230202
- B401190045 IE Info Notice B3-63.Suppl 1, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/02/15 Consolidated Edison Co of New York, Inc 118pp 22366 142 24X Fiche 30-000,84/02/15,8401190045
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Bvc list encl. JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consulidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000,84/02/21,8401190062
- 8401190066 IE Info Nutice 84-11, "Training Program Deficiencies "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc. 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice B4-12, "Failure of Boft Beat Valve Seals "
 Svc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060 24X Fiche 50-000,84/02/27,8401190067
- R Periodic operating reports & related correspondence
- 8402R10122 Monthly operating repts for Jan 1984 W/840215 ltr REAVIB.J A Duke Power Co 84/01/31 16pp 22317 185 24X Fiche 50-249.84/01/31.8402210122
- 8 Reportable occurrences, LERs & related correspondence
- 8402080205 LER 83-021/03L-0 on 831225 borate water storage tank level channel 1 failed low when moisture in instrument airlines froze, giving incorrect level indications Gauses by strip heaters deenergizing due to tripped breaker. W/840124 ltr. PETTY, J C . TUCKER, H B Duke Power Co 84/01/24 D'REILLY, J P. Region 2. Office of Director. 4pp 22130 085 24X Fiche 50-269.84/01/24,8402080205
- DOCKET 50-270 OCCINEE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls" Svc list and JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179, 24X Fiche 50-000,84/02/03,8401190016
- F Security, medical, emergency & fire protection plans
- 8402210077 Application for proposed amend to Licenses DPR-3B,DPR-47 & DPR-5B, defining term accessible/accessibility & incorporating addl fire hose stations located in reactor bldg.

 TUCKER, H B Duke Power Cp 84/02/13, DENTON,H R Office of Nuclear Reactor Regulation, Director. 3pp 22317 288, 24% Fiche, 50-269, 84/02/13, 8402210077
- --8402210081 Proposed Tech Spec rev.defining torm accessible/ accessibility,incorporating add1 fire hose stations & updating FSAR * Duke Power Co. 84/02/13, 39pp 22317 291 24X Fiche 50-269,84/02/13,8402210077
- 840222007i Forwards Rev 3 to Vols 1 & 2 to "Response to Suppl 1, NUREO-0737" Encl rev includes control room review final & supplemental repts & safety parameter display sys safety analysis
 TUCKER, H B, Duke Power Co 84/02/16 DENTON, H R Office of Nuclear Reactor Regulation, Director, STOLZ, J F Operating Reactors Branch 4 3pp, R2327'046 24X Fiche 50-269,84/02/16,8402220071,
- --8402220077 Rev 3 to Vols 1 & 2 to "Response to Suppl 1, NUREQ-0737 "
 * Duke Power Cp 84/02/16, 250pp, 22327 049, 24X
 Fiche 50-269, 84/02/16, 8402220071,

- J Insurance & indemnity information
- 8402210213 Forwards endorsements to NELIA & MAELU policies, including Endorsements 73 & 74 to NELIA Policy NF-182. Endorsements 57 & 38 to MAELU Policy NF-61 & Endorsement 4 to MAELU Policies N-22. M-23 & M-24 LANSON, L T Duke Power Co 84/02/15 SALTZMAN, J NRC No Detailed Affillation Given 18pp 22314 277 24x Fiche 50-000.84/02/15.8402210213
- P Operating license stage documents & correspondence
- B402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1983 Jul 1983 CHILK.S J Office of the Secretary of the Commission 83/12/14 Public Document Branch 1p 22281 023 24% Fiche 50-000.83/12/14.
- --8402160177 Discusses SECY-B1-579.ALAB-651 re transportation of spent fuel from Oconoe Nuclear Station for storage at McGuire Nuclear Station CHILK.S J Office of the Secretary of the Commission G1/t0/27 B1CKWIT.L Office of the Oeneral Counsel ip 22281 ti7 24X Fiche 55-000.B3/12/14.B402160003
- 8402240309 Partial response to FOIA request for eight categories of documents re OL amends Forwards App A documents Documents also in PDR FELTON. J M Division of Rules and Records 83/12/14 BELL, N Nuclear Information & Resource Service App 22414 060 24% Fiche 50-287,83/12/14,8402240309
- 8402030035 Forwards Amends 125,125 & 126 to Licenses DPR-38, DPR-47 & DPR-55, respectively & safety evaluation Amends revise Tech Specs to incorporate changes to radiological effluent Tech Specs for compliance w/App I of 10CFR50 STOLZ.J F Operating Reactors Branch 4 84/01/16 TUCKER, H B Buke Power Co Spp 22091 127 24X Fiche 50-269, 84/01/16, 8402030035
- ---8402030045 Amends 125 125 k 126 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising radiological effluent Tech Specs for compliance w/App 1 of 100FR50.
 STOL7.J F Deprating Reactors Branch 4 84/01/16 74pp 22071 130 24X Fiche 50-269,84/01/16,8402030035.
- --8402030065 Safety evaluation supporting Amends 125,125 & 126 to License DPR-3B, DPR-47 & DPR-55, respectively * DEfice of Nuclear Reactor Repulation, Director, 84/01/16 41pp, 22091 204 24% Fichs 50-269,84/01/16,8402030035
- 3402010444 Responds to FUIA request for BECY-83-288 & BECY-83-443 to be placed in PDR BECY-83-288 available in PDR BECY-83-443 being placed in PDR Forwards SECY-83-443
 FELTON.J H Division of Rules and Records 84/01/17 YENOUSKAS.J Neuman & Holtringer 1p 22061.272 24X Fiche 50-000.84/01/17, 8402010444
- --8402010453 Informs Commission of info obtained re flux reduction programs for pressurized thermal shock at lead plants, since 830285 interim rept (BECY 83-074) DIRCKS,W J Office of the Executive Director for Operations SECY-83-443 83/10/28 lipp 22061 273 24X Fiche 50-000,84/01/17,8402010444
 - 92070399 Notification of 840213-14 meetings w/util in Senece, SC to review implementation of selected NUREG-0737 items
 1UERMANN.J F Operating Reactors Branch 4. 84/01/27 STOLZ, J, F |
 1008748481 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 |
 100874848 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748 | 1008748
 - P150446 Forwards Amends 126,126 & 123 to Licenses DPR-38, DPR-47 & PR-55, respectively & safety evaluation Amends revise Tech pages to corract values for axial power shaping red position imits after 385 EFPD for Unit 3, Gycle 7 operation TGLZ.JF Operating Reactors Branch 4 B4/01/30 TUCKER, H B. uke Power Co 2pp 22258 292 24X Fiche: 50-269,84/01/30,

- --B402150452 Amends 126,126 & 123 to Licenses DPR-38, DPR-47 & DPR-55, respectively revising Tech Specs to correct values for axial power shaping rod position limits after 385 EFPD for Unit 3, Cycle 7 operation STDLZ.J F Decrating Reactors Branch 4 B4/01/30 9pp 22258 294 24X Fiche 50-269,84/01/30,8402150446
- --8402130457 Bafety evaluation supporting Amends 126,126 & 123 to Licenses DPR-3B.DPR-47 & DPR-55, respectively a Office of Nuclear Reactor Regulation, Director 84/01/30 2p 22288 303 24X Fiche 50-269,84/01/30,8402150446
- 8402010410 Generic Ltr 84-04 to all operating PHR licensess, CP holders & applicants for CPs re safety evaluation of Mestinghouse topical repts dealing w/elimination of postulated pips breaks in PHR primary main loops Svc list encl EISENHUI.D O Division of Licensing, 84/02/01 Consolidated Edison Co of New York, Inc. 57pp 22177 087 24X Fiche 50-000,84/02/01,8402010410
- 8402130616 Advises that Class III license fee remitted w/830309 application requesting exemption from requirements of iOCFR50. App E. Section IV F will be refunded Exemption authorized by law & is in public interest MILLER, WD License Fee Management Branch 84/02/03 TUCKER, H B Duke Power Co ip. 22214 295 24X Fiche 50-000, 84/02/03.
- 8402230192 Summary of B40131 meeting w/util & INEL re equipment qualification program review List of attendees encl SUERNANN.J F Operating Reactors Branch 4 84/02/08 Operating Reactors Branch 4 4pp R2379 189 24X Fichs. 50-269, 84/02/08,
- B402210077 Application for proposed amend to Licenses DPR-38.DPR-47 & DPR-35.defining term accessible/accessibility & incorporating addl fire home stations located in reactor bldg
 TUCKER, H B. Duke Power Co 84/02/13 DENTON, H R Office of Nuclear Reactor Regulation. Director BTDLZ, J F. Operating Reactors Branch 4 3pp. 82317 888 24X Fiche. 50-269, 84/02/13, 8402210077
- --84022100Bi Proposed Tech Spec rev.defining term accessible/ accessibility.incorporating addl fire hose stations & updating FSAR. * Duke Power Ce 84/02/13 39pp 22317:271 24X Fiche 50-269,84/02/13.8402210077.
- 8402210174 Application for amend to Licenses DPR-38, DPR-47 & DPR-55 reproposed Tech Spec change to core protection safety limits, protective sys max allowable setpoints & rod position limits.

 TUCKER, H B Duke Power Co. 84/02/13 DENTON, H R. Office of Nuclear Reactor Regulation, Director. STOLZ, J F Operating Reacters Branch 4 4pp 22317 033. 24X Fiche 50-269, 84/02/13, 8402210174
- --B402210184 Proposed Tech Specs recors protection safety limits, protective sys max allowable setpoints & rod position limits

 * Duts Power Co. B4/02/13, 73pp 22317;037. 24X Fiche: 30-269, 84/02/13, 8402210174.
- 8402220517 Application for amend to Licenses DRR-38, DPR-47 & DPR-55 revising Tech Specs to establish degraded mode for emergency condenser cooling water sys TUCKER, H. B. Duke Power Co. 84/02/13, DENTON, H. R. Office of Nuclear Reactor Regulation, Director STDLZ, J. F. Operating Reactors Branch 4. 3pp. 22331 314. 24X Fichs 50-269, 84/02/13, 8402220517.
- --8402220521 Proposed Tech Space establishing degraded mode for emergency condenser cooling water sys * Duke Power Co. 84/02/13, 7pp 22331,317 24X Fiche 50-269,84/02/13,8402220517
- O Inspection reports, IE Bulletins & correspondence
- 8402140203 Forwards IE Insp Repts 50-269/83-37.50-270/83-38 & 50-287/83-37 on 831227-29 No violations or deviations noted BANCE, H C. Division of Project & Resident Programs 84/01/12. TUCKER, H B. Duke Power Co 2pp. 22227.327. 24X Fiche. 50-269.84/01/12.8402140203.
- --B402140211 IE Insp Repts 50-269/83-37,50-270/83-38 & 50-287/83-37 of 631227-29 No violations or deviations noted, Major areas inspected, RCB leekage, calculations.
 BURNETT,P T Region 2, Office of Director, JAPE,F, Division of Engineering & Operational Programs 84/01/11, 9pp. 22229 331. 24% Fiche 50-269,84/01/12,8402140203

- 8402150012 Forwards IE Insp Repts 50-269/83-38.50-270/83-39 & 50-287/83-38 on 831219-22 No violations or deviations noted DANCE. H C Division of Project & Resident Programs 84/01/17 TUCKER. H B Duke Power Co 2pp 22249 225 24X Fiche 50-269.84/01/17.8402150012
- --8402150017 IE Insp Repts 50-269/83-38 50-270/83-39 & 50-287/83-38 on 831219-22 No violations noted Major areas inspected radwaste procedures radioactive effluent permits & repts & effluent radiation monitor alarm settings
 WEDDINOTON R E Region 2. Office of Director BARR K P Division of Engineering & Operational Programs 84/01/13 6pp 22249 228 24% Fichs 50-269.84/01/17,8402150012
- 8402150011 Forwards IE Insp Repts 50-269/83-39, 50-270/83-40 & 50-287/83-39 on 831228-29 No violations or deviations noted DANCE. H C Division of Project & Resident Programs 84/01/19 TUCKER, H. B. Duke Power Co 2pp 22249:303 24x Fiche: 50-269, 84/01/19.8402150011
- --B402150014 IE Insp Repts 50-267/83-37,50-270/83-40 & 50-287/83-39 on 831228-27 No violations or deviations noted Major areas Inspected trip time testing of GE Type AK2 reactor trip breakers
 GIBBONS,T D Region 2, Office of Director CONLON,T.E Division of Engineering & Operational Programs 84/01/18 3pp 22247 305 24X Fiche 50-267,84/01/19,8402150011
- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps." Bvc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Fost 830103). 84/01/25, Consolidated Edison Co. of New York, Inc. 120pp 22058:001 24% Fiche 50-000.84/01/25,8312120153
- B402150341 Responds to Items 2 & 4 of IE Bulletin B2-02 re cleaning of threaded fasteners of closure connections & submittal of unitten rept per Atomic Energy Act of 1954 Fasteners removed from once-through steam generator.

 TUCKER, H B Duke Power Co B4/01/26 O'REILLY, J P Region 2, Office of Director. 3pp. 22242.346 24X Fiche 50-270.84/01/26, B402150341
- 8402280266 Forwards IE Insp Repts 50-269/84-01, 50-270/84-01 & 50-287/84-01 on 840109-12 No violations or deviations identified.

 DANCE, H. C. Division of Project & Resident Programs. 84/01/26 TUCKER, H. B. Duke Power Co. 2pp. 22399 186. 24X Fichs: 50-269, 84/01/26, 8402280266
- ---8402280270 IE Insp Repts 50-269/84-01, 50-270/84-01 & 50-287/84-01 on 840109-12 No violations or deviations identified Major areas inspected refusing physics testing & reactivity balance calculations

 DAVENPORT. K.E. Region 2, Office of Director. JAPE, F Division of Engineering & Operational Programs 84/01/24, 5pp 22399, 188, 24% Fiche: 50-269, 84/01/24, 8402280266.
- 8402280732 Forwards IE Insp Repts 50-269/83-40,50-270/83-41 & 50-287/83-40 on 831211-840110 No violations or deviations noted.

 DANCE H. C. Division of Project & Resident Programs. 84/01/30, TUCKER, H. B. Duke Power Co. 2pp 22406 172. 24X Fiche 50-269,84/01/30,8402280532.
- ---B4022B0542 IE Insp Repts 50-269/83-40,50-270/83-41 & 50-287/83-40 on B3121i-8401i0, No violations or deviations noted Major areas inspected operations, survaillance, maint & offsite safety review board activities.

 BRYANT.J.: FALCOMER.D. Region 2, Office of Director BROWNLEE, V. Division of Project & Resident Programs, 84/01/27, 7pp. 22406:174, 24X Fiche, 50-269, 84/01/30, 8402280532.
- 8402140143 Ack receipt of 840106 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/83-33, 50-270/83-33 & 50-287/83-33.

 DANCE, H. C. Division of Project & Resident Programs 84/01/31, TUCKER, H. B. Duke Power Co. ip. 28218:201. 24X Fiche: 50-269,84/01/31,8402140143.
- --B402140149 Responds to NRC B3120B ltr re violations noted in IE Insp
 Répts 50-269/83-33.50-270/83-33 t 50-287/83-33 Corrective
 actions.station program for identification t evaluation of
 nonroutine events revised
 TUCKER.H.B Duke Power Co 84/01/06. O'REILLY, J P Region 2,
 Office of Director, 2pp. 22218:202 : 24X Fiche, 50-269, 84/01/31,
 8402140143
- --8402140153 Forwards IE Insp Repts 50-269/83-33, 50-270/83-33 & 50-287/83-33 on 831011-1110 & notice of violation, DANCE.H.C. Division of Project & Resident Programs 83/12/08, TUCKER.H.B. Duke Power Co. 2pp 22218:204. 24X Fiche:50-269,84/01/31,8402140143,

- --B402140167 IE Insp Repts 50-269/83-83,50-270/83-33 & 50-287/83-33 on B31011-1110 Violation noted Knowse hydro unit unavailable for maint longer than 72 h & degradation beyond Tech Specs not subj to B31101 safety evaluation BRYANT. J. FALCONER, D. Region 2. Office of Director BROWNLEE, V. Division of Project & Resident Programs B3/12/07 11pp 22218 207 24% Fiche 50-269,84/01/31,8402140143
- 8401190017 IE Bulletin 84-01. "Cracks in 8WR Mark I Containment Vent Headers " Svc list encl DEYOUNG,R C Director's Office Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR30, App R) " Syc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259 24X Fiche 50-000, 84/02/13, 8401190041
- 8401190039 IE Info Notice 84-08, "10CFR30 7, 'Employee Protection '"
 Svc list encl
 JORDAN'E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- 8402230202 Forwards evaluation of relief request & notice granting relief from inservice insp requirements of Section XI of ASME Boiler & Pressure Vessel Code
 STOLZ, J F Operating Reactors Branch 4 B4/02/14 TUCKER, H B
 Duke Power Co 3pp 22379 168 24X Fiche 50-269,84/02/14,
 B402230202
- --B402230212 Evaluation of relief request from inservice insp program
 Relief from preservice hydrostatic tests justifiable
 Alternative NDE program, proposed by Duke Power Co.will
 provide acceptable level of structural integrity
 * NRC No Detailed Affiliation Given 84/04/14 13pp
 22379 171 24X Fiche 50-269,84/02/14,8402230202
- --B402230217 Notice of granting relief from ASME Code, Section XI inservice insp requirements GTOLZ, JF Operating Reactors Branch 4 84/02/14 2pp 22379 184 24X Fiche 50-269,84/02/14,8402230202
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Westinghouse Type 8A-1 Differential Relays." Syc list encl. JGRBAN.E L. Division of Emergency Preparedness & Engineering Response (Post 833103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp. 22366 142. 24X Fiche 50-000,84/02/15,8401190045
- B401190062 IE Info Notice B4-10, "Motor-Operated Valve Torque Bwitches But Below Manufacturer Recommended Value " Svc list encl JURDAN,E.L Division of Emergency Freparedness & Engineering Response (Post B30103) B4/02/21 Consolidated Edison Co of New York, Inc 114pp 22366 024, 24X Fiche 50-000,84/02/21,8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies"

 Svc list ancl

 JORDAN, E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/02/24, Consolidated Edison Co of New

 York, Inc. 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- B401190067 IE Info Notice B4-12, "Failure of Soft Seat Valve Seals."
 Svc list encl.
 JURDAN: E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co. of New
 York, Inc. 120pp. 22431 060. 24X Fiche 50-000.84/02/27,8401190067
- R Periodic operating reports & related correspondence
- 8402210122 Monthly operating repts for Jan 1984 W/840215 ltr REAVIS.J.A Duke Power Co 84/01/31. 14pp 22317:185. 24X Fiche: 50-269:84/01/31:8402210122
- DOCKET 50-271 VERMONT VANKEE NUCLEAR POWER STATION

 F Security, madical. emergency & fire protection plans
- 8402150239 Forwards IE Insp Rept 50-271/83-33 on 831206-09 & notice of violation.

 MARTIN.T. T Division of Engineering & Technical Programs. 84/01/31 MURHY, W P Vermont Yankee Nuclear Fower Corp 2pp 22245-019, 24X Fiche.50-271.84/01/31.8402150239
- --8402150242 Notice of violation from inep on 831204-09
 * Region i, Office of Director 84/01/31 ip 22245 021 24X
 Fiche. 50-271, 84/01/31, 8402150239.

- --8402150245 IE Insp Rept 50-271/93-33 on 831206-09 Violation noted failure to provide radiation control procedure per Tech Spec 6 5 from 830907-1209 BICEHOUSE, M J. KOBRIDE, M . SHANBAKY, M Region 1. Office of Director 84/01/23 7pp 22245 022 24X Fiche 80-271,89/01/31. 6402150239
- 8402160296 Forwards IE Insp Rept 50-271/93-31 on 831101-1230 No violations noted
 STARDSTECKI.R Division of Project & Resident Programs B4/02/M
 NURPHY, W P Vermont Yankee Nuclear Power Corp 2pp 22274 210
 24X Fiche 50-271.84/02/01.8402160294 B4/02/01
- --8402160301 IE Insp Rept 50-271/83-31 on 831101-1230 No violations NO2160301 IE Insp Rept 50-271/83-31 on 831101-1230 No vi-noted Major areas inspected action on previous insp findings.plent power operations, including operating activities & records & plant physical security RAYMOND,W J. GALLO.R H. Region 1. Defice of Director 22pp 22274 212 24X Fiche 50-271.84/02/01.8402160296 94/01/30
- 8402130628 Requests fee for B31205 application re alternate safe shutdown capability be remitted within 15 days of receipt of ltr
- Itr MILLER, H D license Fee Management Branch 84/02/08 S Vermont Yankee Nuclear Power Corp ip 22214 293 24X Fiche 50-271,84/02/08,8402130628
- 84021&0176 Advises that 1984 emergency plan exercise will be conducted on 841114 Requests NRC defer Pederal response to exercise until 1985 exercise, based on util plans to establish new primary emergency operations facility in 1985.
 SINCLAIR.JB Vermont Yankee Nuclear Power Corp. 84/02/13 EISENNULD 0 Division of Licensing 2pp 22276 253 24X Fiche 50-271.84/02/13.84021&0176
- 8402210086 Forwards remittance for review & approval of alternate safe shutdown system NRC 831205 request SINCLAIR.J S Vermont Yankes Nuclear Power Corp 84/02/13 MILLER.W O License Fee Management Branch 1p 22317 331 24X Fiche 50-271.84/02/13.8402210086

H General correspondence

- B209170054 Requests responses re London Nuclear Con-Decon solution used on reactor comlant recirculation pumps during systilation used DREY.K Affiliation Not Assigned B2/09/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22393 341 24X Fiche 50-000.84/02/03.8209170054
- 8402240216 Final response to FDIA request for documents re replacement piping at Pacility Forwards App A & B documents Documents also available in PDR ELTON.J H Division of Rules and Records 84/02/03 BELL, N /clear Information & Resource Service 3pp 22393, 230 24X (the 50-000,84/02/03,8402240216

idvisory Committee on Reactor Safeguards reports & correspondence

- 2270263 Responds to FOIA request for JG Mark 801204 memo to AGRS reydrogen burn w/igniters & documents concerning generation, combustion or control of hydrogen in reactor accidents forwards App A documents App B documents in FDR FELTON, J M Division of Rules and Records 84/01/30 HIATT, 9 L Ohio Citizens for Responsible Energy 7pp 22412 051 24X Fiche 50~000,84/01/30,8402270263
- --8402270360 Forwards public & industry comments received on interim hydrogen control rule & advance notice of rulemaking on degraded core cooling GUITTSCHREIBER ACRE Advisory Committee on Reactur Bafeguards 81/02/23 KERR.W. OKRENT.D. HOELLER.D. ACRE Advisory Committee on Reactor Safeguards 8pp 22412 170 24X Fiche 50-000.84/01/30.8402270263

perating license stage documents & correspondence

- 120029 Generic Ltr B3-39 to representatives of utils re-voluntary rvey of licensed operators Bvc list encl SEMHUT.D.G Division of Licensing 83/12/08 Commonweelth ison Co 12pp 22313 006 24X Ficher 50-000.83/12/08.8312120029
- 060569 Summary of 840109 meeting w/util & Techmark re repair of isture-sensitive leak detection sys List of attendess meeting handouts encl
 DNEY, V Operating Reactors Dranch 2. 84/01/17 Operating actors Branch 2 12pp. 22092 103 24X Fiche 50-271,84/01/17,02060569

- B402010282 Application to amend License DPR-28, revising Tech Specs to reflect change in main steam line low pressure isolation setpoint while in run mode, from 850 to 800 paig per NUREG-0737, Item II X 3 16
 HEIDER, L. H. Vermont Yankee Nuclear Power Corp. 84/01/R3
 EISENHUT, D. G. Division of Licensing. 5pp. 22040 276. 24X
 Fiche 50-271,84/01/23,8402010282
- --8402010285 Proposed Tech Specs reflecting change in main steam line pressure isolation setpoint whole in run mode, from 850 to 800 psig a Vermont Yankee Nuclear Power Corp 84/01/23 7pp 22040 281 24X Fiche-50-271,84/01/23,8402010282
- --8402010287 Rev 1 to "Bafety Evaluation of MBIV Low Turbine Inlet Pressure Isolation Betpoint Change for Vermont Yankee Nuclear Power Station " CORNWELL, K F , HONO, F S General Electric Co NEDO-22243-1 83/05/31 17pp 22040 288 24X Fiche 50-271,84/01/23,8402010282
- 8402150160 Application to amend License DPR-28, consisting of Proposed Change 118 replacing Tech Spec Figure 3 & 1 Pages 111, 117 & 119 re reactor vessel pressure temp limits for operation through 1 15E8 MHhtt) Class III amend fee encl
 HEIDER, L H Vermont Yankes Nuclear Power Corp 84/02/07
 EISENHUT, D G Division of Licensing 7pp 22245 196, 24%
 Fiche 50-271,84/02/07,8402150160
- --8402150166 Replacement Pages 111.117 & 118 to proposed Tech Bpsc Figure 3 6 1 re reactor vessel pressure temp limits for operation through 1 1558 MWh(t).

 * Vermont Yankee Nuclear Power Corp 84/02/07 3pp 22245 200 24X Fiche 50-271.84/02/07.8402150160
- 8402150278 Application to amend License DPR-28, consisting of Proposed Change 117 to Tech Specs, replacing pages covering safety-related shock suppressors
 HEIDER, L. H. Vermont Yankoe Nuclear Power Corp. 84/02/07.
 EISENNUT.D.O. Division of Licensing App. 22250, 147 24X
 Fiche 50-271,84/02/07.8402150278
- ---B402150280 Proposed Change 117 to Tech Specs, replacing pages re limiting conditions for operation & surveillance requirements for safety-related shock suppressors # Vermont Yankee Nuclear Power Corp 84/02/07, 7pp. 22250 151 24% Firhe 50-271,84/02/07,8402150278
- B402150283 Application for Proposed Change 107 to Tech Brecs, revising Pages 38 & 52 & Tables 3 2 i & 4 2 i to reflect deletion of HPCI automatic suction transfer on high torus water level HEIDER, L M Vermont Yankee Nuclear Power Corp B4/02/07 EIBENHUT, D Q Division of Licensing 4pp 22242.111 24X Fiche 50-271, 84/02/07.8402150263
- * Vermont Vankee Nuclear Power Corp. 84/02/07. 2pp 22242, 113 24% Fiche 50-271, 84/02/07, 8402150283
- 8402240110 Forwards Rev 15 to Operational GA Program YOGAP-I-A Rev addresses organization & programmatic changes.

 SHEPARD: A M Yankse Atomic Electric Co 84/02/15 MURLEY, T E. Røgion 1. Office of Director ip 22374 001. 24X Fiche: 50-000, 84/02/15, 8402240110.
- --B402240111 Rev 15 to Operational QA Program YOQAP-I-A PETEREON.W K , SHEPARD.A M , MURPHY.W.P Yankee Atomic Electric Ca B4/02/15 137pp 22374.002. 24X Fiche: 80-000,84/02/15, B402240110
- B402240124 Forwards review of Tech Specs for NUREQ-0737 items schedule#
 after 811231 per Generic Ltr 83-36 Negotiation of reasonable
 schedule for development & submittal proposed.
 BINCLAIR. J B Vermont Vankes Nuclear Power Corp 84/02/22
 VABSALLO.D B. Operating Reactors Branch 2 3pp. 22373 328 24X
 Fiche: 50-271, 84/02/22, 8402240124
- 8402280054 Requests that 810109 order for license mod re BWR scram discharge sys be rescinded. Hydraulic coupling improved due to various scram discharge vol mods. HEIDER-L. H. Vermont Yankee Nuclear Power Corp. 84/02/23 EISENHUT. D. G. Division of Licensing. Spp. 28400, 285 24X Fiche 80-271, 84/02/23,8402280054
- Q Imspection reports, IE Bulletins & correspondence
- 0402080285 Forwards IE Insp Rept 50-271/83-32 on 831114-18 No violations noted MARTIN.T T Division of Engineering & Technical Programs. MURPHY. P. Vermont Yenkee Nuclear Power Corp. 22 24X Fiche. 50-271,84/01/13,8402080285. 84/01/13 22131 229

- ~~84020B0270 IE Insp Rept 50~271/83~32 on 831114~18 No violations noted Major areas inspected licensees licensed & nonlicensed training & requalification training programs BISSETT,P, CAPHTON,D L. Region 1, Office of Director 94/01/10 6pp 22131 231 24X Fiche 50~271,84/01/13,8402080285
- B312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " 8vc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 G01 24X Fiche 50-000,84/01/25,8312120153
- 9402150239 Forwards IE Insp Rept 50-271/83-33 on 831204-09 & hotice
- Obligation

 MARTIN, T T Division of Engineering & Technical Programs 84/01.

 MURPHY, W P Vermont Yankee Nuclear Power Corp 2pp 22245 019

 24X Fiche 50-271.84/01/31,8402150239
- ~-8402150242 Notice of violation from insp on 831206-09
 * Ragion 1, Office of Director 84/01/31 lp 2:
 Fiche 50-271,84/01/31,8402150239 22245 021 24X
- --B402150245 IE Insp Rept 30-271/B3-33 on 831206-09 Violation noted failure to provide radiation control procedure per Tech Spec 6 5 from 830907-1209 BICEHOUSE, H J, MCBRIDE, M, SHANBAKY, M Region 1, Office of Director B4/01/23 7pp 22245 022 24X Fiche 50-271,84/01/31. Director 84/01/23 8402150239.
- 8402040283 Discusses IE Insp Rept 50-271/83-30 on 830912 & forwards
- notice of violation
 MURLEY, T E Region 1, Office of Director 94/02/0:
 Vermont Yankee Nuclear Power Corp. 3pp 22088 109
 Fiche. 50-271:84/02/01.8402060283 84/02/01 MU MURPHY, M. P.
- --8402060289 Notice of violation from insp on 830912 Violations noted excessive radiation levels detected on external surface of spent resin package. Radioactive matl leaked from package onto external surface
 - * Region 1, Office of Director 84/02/01 2pp 22088 112 24X Fiche 50-271, 84/02/01 8402060283.
- 8402160296 Forwards IE Insp Rept 50-271/83-31 on 831101-1230 No violations noted.

 BTAROBTECKI.R Division of Project & Resident Programs 84/02/0
 HURPHY, W P Vermont Yankse Nuclear Power Corp Rpp 22274 210.

 24X Fichs 50-271.84/02/01.8402140296 H4/02/01
- --8402160301 IE Insp Rept 50-271/83-31 on 831101-1230 No violations noted Major areas inspected action on previous insp findings, plant power operations, including operating activities & records & plant physical security RAYMOND, W J. OALLO, R M. Region 1. Dffice of Director 84/01/30 22pp 22274-212. 24X Fiche, 50-271, 84/02/01, 8402160276.
- B4Dil90016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls." Svc list encl.

 JCRDAN, E. L., Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/03 Consolidated Edison Co. of New York, Inc., 119pp. 22114 179 24X Fiche 50-000.84/02/03.8401190016
- 8401190017 IE Bulletin 84-01. "Cracks in BWR Mark I Containment Vent Headers. " Svc list encl.
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement. 84/02/03 Consolidated Edison Co. of New York, Inc. 22177-156. 24X Fiche: 50-000,84/02/03,8401190017.
- 8401190041 IE Info Notice 84-09, "Lessone Learned From NRC Insps of Fire Protection Bafe Shutdown Sys (10CFR50, App R)." Svc list
- enci. JDRDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp. 22365-259 24X Fichs.50-000;84/02/13,8401170041
- 8401170037 IE Info Notice 84-08, "10CFR50.7, 'Employee Protection'" SUL list encl.

 JORDAN, E.L. Division of Emergency Preparedness & Engineering

 Response (Post 830103). 84/02/14 Consolidated Edison Co of New

 York, Inc. 115pp. 22365:141. 24X Fiche 50-000,84/02/14,8401190039
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Bvc list sncl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/15 Ofmsolidated Edison Co of New York, Inc. 118pp. 22366.142 24X Fiche 50-000,84/02/15,8401190045
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Bet Below Manufacturer Recommended Value " Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21. Consolidated Edison Co. of New York, Inc. 114pp. 22366.024 24% Fiche 50-000,84/02/21,8401190062

- 8401190066 IE Info Notice 84-11. "Training Program Deficiencies " Svc list encl JORDAN, E L OVC 11st enci JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/24 Consolidated Edison Co of New York, Inc 115pp 22430 304 24X Fiche 50-000.84/02/24,8401190066
- 8401170067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals " IOI190067 1E Info Navice GT.L.
 SVC list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of Naw
 York, Inc 120pp 22431 060 24X Fiche 50-000,84/02/27,8401190067
- R Periodic operating reports & related correspondence
- 8402170269 Monthly operating repot for Jan 1984 W/840210 ltr BURGER,F J , MURPHY,W P Vermont Yankee Nuclear Power Corp 84/01/31 7pp 22297 034 24X Fiche 50-271,84/01/31,8402170269
- S Reportable occurrences, LERs & related correspondence
- B402230347 Updates status rept on BWR pipe cracks & protection of upcoming licensee actions inspresults encl Evaluation & recommendations re interim & long-term remedial measures expected by May 1984 DIRCKS,W J Office of the Executive Director for Operations SECY-84-009A B4/01/27 5pp 22377 047 24% Fiche 50-000, B4/01/27.8402230347
- 8402070378 LER 84-001-00 on 840105 instability in turbine control sys generated pressure transient, resulting in reactor trip Instruments checked & one level transmitter found out of calibr Instrument calibr W/840203 It PELLETIER, J P Vermont Yankee Nuclear Power Corp 84/02 84/02/03 300 22099 319 24X Fithe 50-271,84/02/03,8402070376

V Operator Examinations

- 8402080285 Forwards IE Insp Rept 50-271/83-32 on 831114-18 No Violations noted
 MARTIN.T T Division of Engineering & Technical Programs 84/01
 MURPHY.N P Vermont Yankee Nuclear Power Corp 2pp 22131 229
 24X Fiche 50-271.84/01/13,8402080285 B4/01/13
- -8402080290 IE Insp Rept 50-271/83-32 on 831114-18 No violations noted Major areas inspected licensee licensed & nonlicensed training & requalification training programs BIBBETT.P. CAPHTON.D L. Region 1. Office of Director App 22:31 231 24X Fiche 50-271.84/01/13.8402080285
- DOCKET 50-272 BALEM NUCLEAR GENERATING STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 8402010135 Forwards Submittal & to contingency plan Submittal withheld (ref iOCFR73.21)
 LIDEN,E A Public Service Electric & Gas Co of New Jersey
 84/01/06 MURLEY.T Region 1, Office of Director ip 22038 260
 24X Fiche 50-272,84/01/06,8402010135
- 8402010139 Forwards security plan. Rev 8. Amend 3 Plan withheld ODDIO139 Forwards security planker B.Amend 3 Plan withheld (ref 10CR73.21) LIDEN.E.A Public Service Electric & Gas Co of New Jerssy B4/01/06 MURLEY.T Region 1, Office of Director 1p 2: 24X Fiche 50-272, B4/01/06, B402010139 22038: 232
- B402130374 Draft safety analysis & implementation plan for safety parameter display sys. W/840130 ltr LIDEN.E.A Public Service Electric & Gas Co of New Jersey 84/01/30 VARGA.B. Operating Reactors Branch 1 22pp 22203 24X Fiche. 50-272, 84/01/30, 8402130394. 22203 225
- 8402130174 Forwards supporting bases for 831228 & 840113 requests for exemption from 10CFR30.App R & two new exemption requests w/supporting bases.W/five oversize drawings Aperture cards are available in PDR.

 LIDEN.E A Public Service Electric & Gas Co of New Jersey.
 84701731. VARGA.B A Operating Reactors Branch 1 41pp 22198-282 24X Fishe 50-272.84/01/31.8402130174
- 8402070371 Forwards util 840130 ltr re safety analysis & implementation plan for emergency response capability, including attachments previously omitted.

 PAYNE: L Public Service Electric & Gas Co of New Jersey 84/02/01 VARGA: S. NRC No Detailed Affiliation Given 1p. 22099 182 24X Fiche 50-272.84/02/01.8402070371

- --B402070374 Forwards safety analysis & implementation plan for safety parameter display sys.per Generic Ltr B2-33 re requirements for emergency response capability LIDEN.E A Public Service Electric & Oas Co of New Jersey B4/01/30 VAROA.S Operating Reactors Branch i 22pp 22099 183 24X Fiche 50-272.84/02/01.8402070371
- 8402230005 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per 610709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR FISCHER. O C Operating Reactors Branch 2 84/02/07 UDERITZ.R A Public Service Electric & Gas Co of New Jersey 3pp 22379 342 24X Fiche 30-272,84/02/07,8402230005

J Insurance & indemnity information

- 8402160327 Forwards Endorsement 63 to NELIA Policy NF-230 & Endorsement 33 to MAELU Policy MF-90 COLDEN.M P Marsh & McLennan, Inc. 84/02/08 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 22277-011 24X Fiche 50-272.84/02/08.8402160327
- P Operating license stage documents & correspondence
- 8402060402 Notification of Bignificant Licensee Meeting 84-11 on 840201 w/util in King of Prussia.PA to discuss status of radiological safety & ALARA programs
 DRASOUN.T Region 1. Office of Director 84/01/26 Region 1.
 Office of Director 2pp 22086 180 24% Fiche 50-272.84/01/26.
 8402060402
- 8402080008 Notification of 840228 meeting w/util in Hancocks Bridge. NJ to discuss preventative maint program FISCHER.D C Operating Reactors Branch i 84/01/30 VARQA.S A Operating Reactors Branch i 2pp 22173 001 24X Fiche 50-272.84/01/30.8402080008
- 8402090603 Forwards SER detailing review of Item II K 2 17 re-potential for voiding in RCS during transients Steam void will not result in unacceptable consequences during anticipated transients
 VAROA, S A Operating Reactors Branch 1 84/01/30. UDERITZ, R A Public Service Electric & Gas Co of New Jersey 12pp 22189 337 24X Fiche 50-272:84/01/30.8402090603
- 8402010410 Generic Ltr 84-04 to all operating PWR licensees, CP holders & applicants for CPs re safety evaluation of Hestinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR grimary main loops 8vr list encl.
 EISENHUT, D G Division of Licensing 64/02/01 Consolidated Edison Co of New York, Inc. 59pp. 22177 087 24X
 Fiche 50-000,84/02/01,8402010410
- 8402130319 Forwards Tech Bpecs inadvertently omitted from 830328 amend parkage re containment sys LIBEN.E A Public Service Electric & Gas Co of New Jersey. 84/02/06 VARQA.B Operating Reactors Branch 1 3p 22197 182 74X Fiche 50-272.84/02/06.8402130319.
 - 30326 Tech Specs inadvertently omitted from H30328 amend package containment sys ?ublic Service Electric & Gas Co of New Jersey 83/03/28 22197 163. 24% Fiche 50-272,84/02/06,8402130319.
 - 312 Ack receipt of B31215 ltr transmitting resolutions to NRC rms identified in B31115 ltr re GA program description a Proposed change acceptable M.T.T Division of Engineering & Technical Programs B4/02/08 ITZ.R.A Public Service Electric & Gas Co of New Jersey 2pp 88 235 24X Fiche 50-272,84/02/08.8402140312

spection reports, IE Bulletins & correspondence

- 1020329 Forwards IE Insp Repts 50-272/83-36 & 30-311/83-36 on 3110-1205 No violations noted Artificial Programs 83/12/30 JDERITZ, R A Public Bervice Electric & Cas Co of New Jersey. 2pp 22052 236 24% Fiche 50-272,83/12/30,8402020329
 - 12020336 IE insp Repts 50-272/83-36 & 50-311/83-36 on B31110-1205 No foliations noted Major areas inspected review of periodic & pecial repts, LER review design changes & mods & operating wants Bone issues require further followup &/or resolution. INVILLE.J C. SUMMERS,R J. MENNY,T,J Region 1. Office of Director B3/12/28 12pp 22052 238 24X Fichs 50-272,83/12/30,8402020329.

- 8402070347 Forwards IE Insp Repts 50-272/83-38 & 50-311/83-37 on 831204-840110. No violations noted BTARDSTECKI, R Division of Project & Resident Programs 84/01/23 UDERITZ.R A Public Bervice Electric & Gas Co of New Jersey 2p 22097 024 24x Fiche 50-272.84/01/23.8402070347
- --B402070351 IE Insp Repts 50-272/83-38 & 50-311/83-37 on 831206-840 No violations noted Major areas inspected periodic & special repts.LERs.operational safety verification.surveillance & maint observations
 LINVILLE.J C , SUMMERS.R J Region 1. Office of Director NORRHOLN.L J. Division of Project & Resident Programs 84/01/1 12pp 22097 026 24X Fiche 50-272.84/01/23.8402070347
- 8312120153 IE Info Notice 84-06, "Steem Binding of Auxiliary Feedwat Pumps " Svc Bist encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of N York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,83121201
- B402090399 Forwards IE Insp Repts 50-272/83-35 & 50-311/83-35 on B3i1i4-18 No violations noted MARTIN,T T Division of Engineering & Technical Programs 84/01/ UDERITZ,R A. Public Service Electric & Oas Co of New Jersey 3 22161 096 24X Fiche 50-272,84/01/25,8402090359
- --B4020703A9 IE Insp Repts 50-272/83-35 & 50-311/83-35 on 83111A-18 violation noted. Major areas inspected training of security force preliminary review of post-accident sempling sys & licensee action on previous insp finding DRACOUN.T. WHITE.J. SHANBAKY.M Region 1, Office of Director, 84/01/10 4pp 22161 098 24X Fiche 50-272,84/01/25,840209035
- 8402070214 Ack receipt of 830127 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/82-32 & 50-311/82-30.

 8TAROSTECKI, R. Division of Project & Resident Programs 84/02/01

 UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey 2p 22102 174. 24% Fiche, 50-272,84/02/01,8402070214
- --8402070217 Responds to NRC 821229 ltr re-violations noted in IE In Repts 50-272/82-32 & 50-311/82-30 Corrective actions, supervisors reinstructed in responsibility to monitor personnel activities wi/increased surveillance UDERITZ,R A Public Hervice Electric & Qas Co of New Jersey 83/01/27 HAYNES,R C. Region i, Office of Director STARDSTECKI,R Division of Project & Resident Programs 2pp. 22102 176 24X Fiche 50-272,84/02/01.8402070214
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Revise of Vahicular Excess Controls " Byo list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of N York, Inc. 119pp. 22114 179. 24X Fiche, 50-000, 84/02/03, 84011900
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers." Svc list encl. DEYDUNG.R.C. Director's Office, Office of Inspection and Enforcement 84/02/03. Consolidated Edison Co of New York, In 10Rpp. 28177 156 24X Fiche 50-000,84/02/03,8401190017.
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown 8ys (10CR80, App R) " Syc list enc! JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of N York, Inc. 124pp. 22345, 259, 24X Fichs. 50-000, 84/02/13, 84011900
- 8401190037 IE Info Notice 84-08, "100FR50 7, Employee Protection "
 Syc list encl
 JURDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103), 84/02/14 Consolidated Edison Co. of N
 York, Inc 115pp 22365, 141 24X Fiche, 50-000, 84/02/14, 84011900
- B401190045 IE Info Notice 83-63. Buppl i, "Potential Failures of Hestinghouse Type BA-1 Differential Relays" Bvc list encl. JORDAN-E L Division of Emergency Preparedness & Engineering Response (Post 830103). B4/02/15 Consolidated Edison Co of Nyork, Inc. 118pp 22366-142. 24X Fiche: 50-000, B4/02/15, B4011909
- 8408280205 Ack receipt of 831121 & 840127 ltrs informing NRC of step taken to correct violations noted in IE Insp Repts 50-272/83-82 & 50-311/83-22 MARTIN.T.T. Division of Engineering & Technical Programs. 84/02/UDERITZ.R.A. Public Service Electric & Qas Co of New Jersey 2 22400-192 24X Fiche. 50-272. 84/02/17. 8402280205

- --B4022B0216 Responds to NRC 831021 ltr re violations noted in IE Insp Repts 50-272/83-22 & 50-311/83-22 Corrective actions controls specified for use of master key guidance provided for transfer & return of high radiation area keys LIDEN.E A Public Service Electric & Qas Co of New Jersey B4/01/27 MARTIN.T T Division of Engineering & Technical Programs 3pp 22400 194 24X Fiche 50-272.84/02/17.8402280205
- --8402280220 Responds to NRC 831021 ltr re violations noted in IE Insp Repts 50-272/83-22 & 50-311/83-22 Corrective actions training program instituted on 830912 & completed 831104 & training held to familiarize personnel w/changes LIDEN.E A Public Service Electric & Qas Co of New Jersey 83/11/21 MARTIN.T T pivision of Engineering & Technical Programs 12pp 22400 197 24X Fiche 50-272.84/02/17,8402280205
- 8401170062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Bet Below Manufacturer Recommended Value " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 114pp 22366:024 24X Fiche 50-000,84/02/21,8401170062
- 8401190066 IE Info Notice 84-1), "Training Program Deficiencies "
 Svc list encl
 JORDAN,E L Division of Emergency Preparadness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- B401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals' "
 Svc list enc!
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc. 120pp. 22431 060 24X Fiche 30-000,84/02/27,8401190067
- R Periodic operating reports & related correspondence
- 84020&0383 Advises that util has reestablished sampling for milk at Location 301 & discontinued sampling at Location 302 as part of radiological environ monitoring program
 LIDEN,E.A Public Service Electric & Gas Co of New Jersey
 83/12/27 MURLEY.T E Ragion 1. Office of Director 2pp
 22086,318, 24X Fiche 50-272,83/12/27,8402060383.
- 8402100201 Forwards NPDES discharge monitoring repts for Dec 1989 MILLER, L. K. Public Service Electric & Gas Co. of New Jersey 84/01/23 RADOW, E. New Jersey, State of Spp. 22178 274 24X Fiche. 50-272,84/01/23,840210020
- --8402100204 NPDES discharge monitoring repts for Dec 1783 MILLER, L. K Public Service Electric & Gas Co of New Jersey 83/12/31 19pp. 22178-279 24X Fiche-50-272,84/01/23,8402100201
- 8402210056 Monthly operating rept for Jan 1984 W/840210 ltr MILLER, L. K., ZUPKO; J. M. Public Service Electric & Qae Co. of New Jarrey, 84/01/31, 10pp, 22317:261 24X Fiche: 50-272,84/01/31, 8402210056
- 8402280311 Forwards response to first quarterly rept of Nuclear Oversight Committee transmitted to NRC on 840126, Set of performance indicators using INPO recommendations & info from other utils developed LIDEN. E.A. Public Service Electric & Gas Go of New Jersey 84/02/21. VARQA.S.A. Operating Reactors Branch 1 4pp. 22397 219 24X Fiche: 50-272, 84/02/21,8402280311.
- B. Reportable occurrences, LERs & related correspondence
- 840224008à Further response to FOIA request for 14 categories of documents Item 9 limited, per 831005 telcon Forwards Rev 7 to NUREQ-0528 & App A documents. Portions of App B documents withheld (ref FOIA Exemption 4). App B documents also in PDR. FELTON. J. M. Division of Rules and Records 83/12/12, SHOLLY, 8 C Union of Concerned Scientists. App. 22394:150 24% Fiche: 50-000, 83/12/12, 8402240086
- ---8305140003 Security event rept re 830504 bomb threat UDERITZ,R A. Public Service Electric & Gas Co. of New Jersey 83/05/09. Director's Office, Office of Inspection and Enforcement. 3pp. 22394:154. 24X Fiche. 50-000, 83/12/12, 8402240086.
- 8402020146 LER 83-063/03L-0 on 831214 axial flux difference recorder & monitor alarm not monitored & logged when removed from svc to perform routine change of tanget flux difference value. Caused by personnel error. W/840112 ltr. RUPP, J L., ZUPKO, J, M. Public Service Electric & Gas Co. of New Jersey. 84/01/13. MRLEY, F. Region 1, Dffice of Director. App 22036: 157. 24X Fiche. 50-272,84/01/13,8402020146

- 8402020250 LER 83-065/03L-0 on 831226, containment sump level menitoring mys indicated unsubstantiated leakage Steam generator 14 secondary handhole cover found leaking Cause not stated Cover repaired W/840112 ltr RUPF.J L . ZUPKO, J M Public Bervice Electric & Gas Co of New Jersey 84/01/13 MURLEY. T E Region 1, Office of Director 2pp 22057 011 24X Fiche 50-272,84/01/13,8402020250
- 8402020116 LER 83-067/03L-O on 831220 minor leak developed on diesel cooling water expansion tank Caused by bushing wear allowing radial shaft movement Leak repaired pump tosted & declared operable W/840118 ltr RUPP, J L , ZUPKO, J M Public Service Electric & Gas Co of New Jersey 84/01/18 MURLEY, T E Region 1, Office of Director 4pp 22056 227 24x Fiche 50-272.84/01/18.8402020116
- 8402030177 LER B3-073/03L-0 on B31223.during surveillance testing on embrgency diesel generator 1B. jacket water cooling leak from instrument line discovered Caused by elbou cracking due to engine vibration Datign change initiated W/840120 ltr RUPP, J L., ZUPRG, J M. Public Bervice Electric & Gas Co. of New Jersey 84/01/20 MRLEY, T E. Region 1, Office of Director 4p; 22048 131 24x Fiche 50-272.84/01/20,8402030177
- 8402030198 LER 83-071/03L-0 on 831222; containment fan coil unit (CFCV)
 14 removed from svc to repair flexible connector Connector
 temporarily repaired CFCU returned to operable status
 W/#40120 ltr
 RUPP, J. L., ZUPKD, J. M. Public Service Electric & Oas Co. of Naw
 Jersey 84/01/20 MURLEY, T. E. Ragion i. Office of Director App.
 22067 358 24X Fiche 50-272, 84/01/20, 8402030198
- B402030295 LER B3-068/03L-O on B31224, operator observed steam issuing from dissel fire suppression pump I cooling water expansion tank Caused by frozen diesel water cooling lines due to subzero temps Damper shut Lines thawed W/840120 ltr RUPP.J L. ZUPKO.J M Public Bervice Electric & Gas Co. of New Jersey B4/01/20 MRLEY.T E Region I. Office of Director 4pp 22087 338 24X Fiche 50-272, 84/01/20,8402030295
- B402030333 LER B3-070/03L-0 on B31221, exterior door of 100-ft elevation airlack exhibited excessive leakage during surveillance testing Caused by cut exterior door outer seal Seal replaced W/840120 itr.
 RUPP, J L , ZUPKO, J M Fublic Service Electric & Gas Co of New Jersey 84/01/20 MVRLEY, T E Region 1, Office of Director. Spp 22067 095 24X Fiche 50-272,84/01/20,8402030333
- 8402030189 LER 83-075/03L-0 on 831227, microprocessor memory lost for hydrogen analyser channel 12 & 13. Caused by voltage transient on vital instrument bus 28 making microprocessor lose constants. Constants reinstalled W/840125 ltr RUPP, J L , ZUPKO, J M Public Service Electric & Qas Co of New Jersey 84/01/25. MRLEY, T E Region 1, Defice of Director 4pp 22068 188 24X Fichs 50-272, 84/01/25,8402030189
- 8402030200 LER B3-039/03L-0 on B31226, fire protection header pressure drapped suddenly due to ruptured 4-inch alarm valve Caused by frozen water within valve, New valve ordered & will be installed upon receipt M/B40125 ltr.
 RUPP, J L , ZUPKO, J, M Public Barvice Electric & Oss Co of New Jersey 84/01/25, MURLEY, T E Region 1, Office of Director 5pp 22068:003 24X Fiche 50-272, 84/01/25,8402030200
- 8402070142 LER 83-074/03L-0. on 831230.due to Icing conditions at circulators, control RPI 2A3 & ICI exceeded 12 steps from group demand position for group, Caused by drift of sensor output Channels recalibr. W/Pa0107 ltr RUPP. J L. 7UPKO.J M Public Bervice Electric & Gas Co. of New Jersey 84/01/27. MRLEY.T E Region i. Office of Director. 4pp 22100.167. 24X Fiche 50-272.84/01/27,8402070142
- 8402070422 Forwards request for CMS review & supporting statement re required actions based on generic implications of Salem ATHS events NORRY.P 0. Office of Administration. 84/01/31, MACRAE, J B. Office of Management & Budget 23pp. 22142:103. 24X Fiche 50-272, 84/01/31.8402070422.
- 8402080371 LER 84-001-00 on 840101 reactor tripped during startup when power exceeded 10% w/turbine not latched, Caused by difficulty in controlling steem generator feed. Procedure & feed pump operating instrumentation revised W/840131 ltr RUPP. J. L., ZUPKO. J M. Public Service Electric & Oss Co. of New Jersey. 84/01/31. MRLEV. T.S. Region 1. Office of Director 4pp 22131:186. 24X Fiche. 50-272, 84/01/31. 8402080371
- 8402090433 Responds to 831114 request for extension to completion date for corrective action program Item C.B s. 4 Mod of 830506 order extending date to 840630 encl.
 VARQA.S A Operating Reactors Branch 1 84/01/31 UDERITZ.R A Public Service Electric & Oas Co. of New Jersey. 3pp. 22177:307 24X Fiche: 50-272,84/01/31,8402090433.

- --8402090435 Notice of mod to 830506 order extending completion date for Item C B a 4 of corrective action program re reactor trip circuit breakers to 840630 FURPLE:R A Division of Licensing 84/01/31 6pp 22177 310 24X Fiche 50-272.84/01/31,8402090433
- B402150234 LER B4-003-00 on B40110, turbine trip occurred due to high-high level in steam generator 14, resulting in reactor trip Caused by steam generator level error signal Level control tested for proper response & monitored W840209 ltr RUPP, J L , ZUPRO, J M Public Service Electric & Oas Co of Naw Jarsey B4/02/09 4pp 22245 006 24X Fichs 50-272, 84/02/09, 8402150234
- 8402220173 LER 84-005-00 on 840202 containment fan coil unit 15 declared inoperable when leak discovered on svc water vent line Caused by corrosion due to excessive welding during initial installation Vent line replaced H/840216 ltr RUPP.J L. ZUPKO,J M. Public Service Electric & Gas Co. of New Jersey 84/02/16 Spp. 22340 311 24X Fiche 50-272.84/02/16, 8402220173
- 8402240072 LER 84-004-00 on 840121, reactor trip occurred due to low-low water level in steam generator 13 Causad by valve intermittently binding while in shut position Valve adjusted W/840217 ltr RUPP, J. L., ZUPKO, J.M. Public Service Electric & Gas Co. of New Jersey 84/02/17 4pp 22374 144 24% Fiche 50-2/2, 84/02/17, 8402240072
- B40D2390009 Notification of Significant Licensee Heeting 84-09 on B40306 in Salem.NJ to discuss ATWS event corrective action program NORRHOLM.L J Division of Resource Management & Administration 84/07/21 Division of Resource Management & Administration 1p 22437 328 24X Fiche 50-272.84/02/21.8402290009
- 8402290276 PND-1-84-018 on 840224 unit tripped from 100% power due to main generator trip Caused by stator coil failure Estended outage may be required for ropairs LINVILLE, J. NORRHOLM. Region 1. Office of Director 84/02/27 1p 22426 302 24% Fiche 50-272.84/02/27.8402290296

U Congressional/Exacutive Correspondence

- B402290002 Responds to FDIA request for correspondence NRC received from Benators J McClure. JE Johnston & P Larait during past 2 yrs Forwards App A documents Name of individual deleted from Documents B & 9 of App A (ref FDIA Expaption 6) FELTON, J M Division of Rules and Records B3/11/30 KOLI, E Cable News Network. Inc. 6pp. 22438 002 24% Fichs 50-000, 83/11/30.8402290002
- --8402290226 Forwards rept of NRC fact-finding task force established to analyze 830225 ATMS event H/o encl
 KAMMERER, C Office of Congressional Affairs 83/03/23
 OTTINGER, R L House of Rep , Energy & Commute BIMPSON, HART
 Senate, Environment & Public Norks 1p 22438 051 24X
 Fiche 50-000,83/11/30,8402290002

Operator Examinations

2080016 Requests info re issue of periodic evaluation quizzes within 0 days Response to first issue re type of matl used in open opk quiz satisfactory
ARGA.9 A Operating Reactors Branch 1 84/01/24 UDERITZ.R A ubits Bervice Electric & Gas Co of New Jersey 4pp 22172 381 /4X Fiche 50-272.84/01/24.8402080016

JCKET 50-275 DIABLE CANYON NUCLEAR POWER PLANT, UNIT 1

- ā NRC Safety Evaluation Report (SER), supple & correspondence
- 8402020264 Forwards confirmation that capacitor in valve actuator same type as qualified by ITT General Controls Info should complete resolution of SBER 20.1 tem 5 SCHUYLER. J O Pacific Gas & Electric Co 84/01/20 KNIGHTON. O W Licensing Branch 3 Jpp 22055 246 24X Fiche 50-275.83/01/30.9402020264
 - 1240481 Provides add1 info to resolve SSER 20 Open Item 30 re cceptance criteria for compression members in frame type ipe rupture restraints Referenced rept contains info aquired to close Open Item 30 CHUYLER, J. Q. Pacific Gas & Electric Cb. 84/01/20 KNIOHTON, Q.W. icomsing Branch 3 ip. 21908 360 24% Fiche 50-275, 84/01/20, 1401240481

- 8402030258 Forwards response to Allegations 25.58 & 96 described in SEER 21 re expansion anchors Response to concern re HP Foley procedure governing installation of anchor bolts will be submitted next wk HICCH. J B Pacific Gas & Electric Co 84/01/27 MARTIN. J B Region 5. Office of Director 19pp 22069 208 24X Fiche 50-275, 84/01/27. 8402030258
- 8402060424 Advises that NSBS vendor (Westinghouse) completed review of all power ascension procedures Procedures acceptable Info completes Item I C 7 of SBER 14 SCHUYLER.J O Pacific Cas & Electric Co 84/02/01 KNIGHTDN, O M Licensing Branch 3 lp 22085 100 24X Fiche 50-275.84/02/01, 8402060424
- 8402070390 Informs that diesel generator intake/exhaust piping support & exhaust silencer mounting brace seismic mods completed, per SSER 21 Allegation 8 FBAR will be updated to reflect that listed components will perform after Hosgri event SCHUYLER, J D Pacific Gas & Electric Co 84/02/02 KNIGHTON, 0 F Licensing Branch 3 ip 22095 115 24X Fiche 50~275, 84/02/02, 8402070390
- 8402100001 Forwards Rev O to "Stress Analysis of Two Piping Sys & Supports, Diablo Camyon Nuclear Power Plant, Unit i," in response to SSER 20 Open Item 18. "Piping Analysis Rept "Rept shows that design criteria met for all evaluations SCHUYLER, J O Pacific Gas & Electric Co 84/02/03 KN10HTON, G H Litensing Branch 3 ip 22179 344 24X Fiche 30-275, 84/02/03, 8402/00001
- --8402100007 Rev O to "Stress Analysis of Two Piping Bys & Supports-Diable Canyon Nuclear Power Plant Unit 1 " * Robert L Cloud Associates, Inc 84/01/25 66pp 22179,348 24X Fiche 50-278,84/02/03.8402100001
- B402040345 Forwards summary of BSER 20 Followup Item 27 & BSER 21 Allegation 12 re jet impingement loads Evaluations complete SCHUYLER, J O Pacific Gas & Electric Co 84/02/06 KNIGHTON, O W Licensing Branch 3 6pp 22160 234 24X Fiche 50-275,84/02/06, B402090345
- 840209024: Forwards response to NRC questions concerning allegations listed in SBER 21 re design of small bore piping Questions discussed w/NRC on 840119 & 21 SCHUYLER. J D Pacific Gas & Electric Co 84/02/07. EISENHUT, D & Division of Licensing 52pp. 22159 125 24X Fiche 50-275.84/02/07.8402090241
- 8402090256 Forwards response to NRC questions concerning allegations listed in SBER 21 re installation of Class I squipment on Class II matl in cable spreading room SCHUYLER, J O Pacific Qas & Electric Co 84/02/07 MARTIN, J B Region 5, Office of Director 3pp 22161 342 24X Ficho 50-275,84/02/07,8402090256.
- 8402070279 Forwards welding program into in response to 840119 request resulting from investigations into allogations listed in 88ER 21 Potential weld requirement misinterpretations accounted for in design process SCHUYLER, J. D. Pacific Gas & Electric Co. 84/02/07 MARTIN, J. B. Region 5, Office of Director 130pp 22160;309 24X Fiche 50-275,84/02/07,840809020299
- B402070373 Forwards results of review of HP Foley Co Procedure GCP-9 reinstallation of expansion anchore & instructions prepared for util field sampling program in response to BBER 21, Allegations 25.58 & 96 Evaluation expected by 840213 BCHUYLER, J O Pacific Gas & Electric Co 84/02/07 MARTIN, J. B. Regian 5, Office of Director, 18pp. 22161 118, 24X Fiche 50-275,84/02/07,8402090373
- 8402140419 Forwards info re turbine bldg roof truss modeling studies, per SSER 20 Open I tem 11. Btudy validates use of generalized uniaxial members to obtain individual truss member responses
 8CHUYLER, J O Pacific Oas & Electric Co 84/02/10, KNIGHTON, G W. Licensing Branch 3 12pp 22227 118 24X Fichs 50-275,84/02/10.
- 8402210061 Forwards util commitment re development of snubber optimization program, per BSER 21 allegations SCHUYLER, J O Pacific Gas & Electric Co 84/02/15, MARTIN, J B Region 5, Office of Director, 2pp 22317 279 24X Fiche 50-275,84/02/15,8408210061.
- B40R210255 Forwards status of BSER 20 items requiring further action Items required to be finished before Hode 4 operation completed Justification re auxiliary feedwater level control valves & excerpt from SSER 9 encl SCRUYLER, J D Pacific Gas & Electric Co B4/02/15, KNIGHTON, Q W Licensing Branch 3 7pp 22314 323 24X Fichs 50-275,84/02/15, B402210235

- 8402220043 Informs that util will install RMR low flow alarm prior to entry into Mode i operation, per SSER 21, Allegation 45
 Listed administrative controls & procedures in effect during interim
 SCHUYLER.J.O Pacific Gas & Electric Co 84/02/15 KNIGHTON.G W Licensing Branch 3 2pp 22343 085 24X Fiche 50-275,84/02/15,840220043
- 8402240031 Provides info re Allegations 31 & 32 of SBER 21 Verification documentation available for all technical options of computer programs used by civil structural group All penetrations to containment shell structurally adequate SCHUVLER.J O Pacific Oas & Electric Co 84/02/17 KNIOHTON.OW Licensing Branch 3 2pp 22375 320 24% Fiche 50-275,84/02/17, 8402240031

F Security, medical, emergency & fire protection plans

- 84020203B2 Forwards public version of revised emergency response plan operating procedures, including Procedures III.01 resembles and serious director & III 02 re San Luis Obispo County sheriff dept W/240131 release memo SCHUYLER, J O Pacific Qas & Electric Co 84/01/19 MARTIN, J B Region 5, Office of Director 7pp 22074 040 24X Fiche. 50-275, 84/01/19, 8402020382
- --8402020385 Public version of revised amergency response plan operating procedures, including Procedures III Of re emergency svcs director & III O2 re San Luis Obispo County sheriff dept STILHELL, D. D. Pacific Qas & Electric Co. 83/07/07 1798pp 22074:047 24% Fiche:50-275,84/01/19,8402020382
- 8402090237 Forwards evaluation of PORE emergency preparedness plan for Diable Ganyon. MRIMM.R W Faderal Emergency Management Agency 84/02/02 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp. 22157 288 24X Fiche 50~275,84/02/02. 8402090237
- ---8402090247 Evaluation of PQ&E emergency preparedness plan for Diable Campon * Federal Emergency Management Agency 83/12/06 30pp. 22157 290 24X Fiche.50-275.84/02/02.8402090237
- 8402290365 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per 810707 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR MNIGHTON.O W. Licensing Branch 3 84/02/14 SCHUYLER, J O Pacific Gas & Electric Co 4pp 22438, 241. 24X Fiche. 50-275, 84/02/14, 8402290365

O Adjudicatory correspondence

- 8310130138 Response opposing Joint Intervenors 830709 suppl to motion to reopen record on const GA Info from Nuclear Svcs Corp audit neither timely nor compelling to justify reopening of record Certificate of Svc encl.

 CHANDLER. L. J. Hearing Branch 2 83/10/06. Atomic Bafety and Licensing Appeal Panel. 9pp 20724 119 24X Fiche 50-275,83/10/06.8310130158
- --8310130160 Affidavit of QH Hernandez Nuclear Bvcs Corp 770728 audit findings do not represent new info In many cases, findings similar to NRC reported insp findings.

 HERNANDEI.Q.H. Division of Resident Reactor Project & Engineering Programs, 83/10/04 123pp. 20724 128 24% Fiche 50-275, 83/10/06/8310130158
- B402010215 Memorializes telcon re NRC answer to Joint Intervenors & Governor Deukmejian petitions for review of ALAB-756.
 Responses may be filed by 840126.
 CHANDLER, L. J. Hearing Branch 2 B4/01/25. CHILK, B. J. Office of the Secretary of the Commission 2pp. 22038:360 24%
 Fiche.50-275,84/01/25.8402010215.
- 8402010220 Answer opposing Joint Intervenors & Governor Deukmejian 840107 & 11 respective petitions for review of ALAR-756 repetition to reopen hearing on issue of const GA. Important question of fact not established Certificate of Syc encl. CHANDLER, L. J. Hearing Branch 2. MCGURREN, H. J. Hearing Branch 184701726. Commissioners. 18pp 22040, 156 24X Fiche: 50-275, 84/01/26, 8402010220.
- 8402070058 Commends C Miller, C Costantino, PC Wang & AJ Philippacopoulos for time & effort put into testimony at Nov 1983 hearing CHANDLER, L.J Hearing Branch 2 84/02/01 REICH, M Brookhaven National Laboratory. 1p 22103 038 24X Fiche 50-275, 84/02/01, 8402070058,

- 8402070177 Motion for leave to file reply to util & NRC answers to Joint Intervenors 840107 patition for review of ALAB-754 REYNOLDS, J R Joint Intervenors - Diable Canyon REYNOLDS, J R Center for Law in the Public Interest 84/02/03 Commissioners 2pp 22102 213 24X Fiche 50-275.84/02/03.8402070177
- --8402070183 Reply to util & NRC answers to petition for review of ALAB-756 Reply corrects factual misstatements which if left uncorrected will mislead Commission as to true state of record Certificate of Svc enc.l
 REVNOLDS, J R Joint Intervenors -- Diablo Canyon REVNOLDS, J R Center for Law in the Public Interest 83/02/03 Commissioners ipp 22102 215 24X Fiche 50-275,84/02/03,8402070177
- 8402140223 Advises that ASLB & parties in proceeding will be notified re relevant results of staff review of allegations re small bore piping design activities CHANDLER, L. J. Hearing Branch 2 84/02/07 MODRE, T.S., BUCK, J.H., JOHNSON, W.R. Atomic Safety and Licensing Appeal Panel 2pp 22230 008 24X Fiche 50-275,84/02/07,8402140223
- 8402130251 Prepared statement of T Devine re plant GA Proposed violation item assessment encl DEVINE: T Joint Intervenors Diablo Canyon 84/02/10 18pp 22204 288 24% Fiche 50-275.84/02/10,8402130251
- 8402170053 Motion to augment or, in alternative, to reopen record refacility operation in light of Stokes & Cooper affidavits Motion timely filed & should be granted Certificate of Svcencl
 REYNOLDS, JR Joint Intervenors Diablo Canyon REYNOLDS, JR Center for Law in the Public Interest 84/02/14 Atomic Safety and Licensing Appeal Panel 24pp 22301 104 24x
 Fichs 30-275,84/02/14,8402170053
- 8402170041 Order extending time until 840313 for Commission to act to review ALAB-756 CHILK, S. J. Office of the Secretary of the Commission 84/02/15 Commissioners ip 22300 275 24X Fiche 50-275,84/02/15,
- 8402220279 Requests that Insp Rept 50-275/83-37 & related repts, studies & documents immediately be placed in POR & issued to svc list in proceeding REYNOLDS, J R Center for Law in the Public Interest REYNOLDS, J R Joint Intervenors Diablo Canyon 84/02/15 PALLADIND, N, OILINSKY, V, ROBERTS, T Commissioners 2pp 22337 055 24% Fiche 50-275,84/02/15,8402220279
- 8402210121 Confirms B40215 conversation re San Luis Dbispo Mothers for Peace petition BURNE, B G Regional Operations & Enforcement Division 84/02/17 DEVINE, T.M Government Accountability Project ip 22317 206 24X Ficher 50-275, 84/02/17, 8402210121
- 8402280454 Requests change of address as listed for svc list for matters re facility. Also requests addition to svc list for Rancho Seco Related correspondence HARRIS.T H Affiliation Not Assigned 84/02/22 CHILK Office of the Secretary of the Commission ip 22406 362 24X Fiche 50-275,84/02/22,8402280454
- 8402280333 Order directing svc of expurgated transcript of NRC staff 840125 private meeting w/C Btokes re QA allegations All parties shall be served by 840224 8HOEMAKER, C J Atomic Safety and Licensing Appeal Panel 84/02/23 Office of the Executive Legal Director 2pp 22399 0B3 24X Fiche 50-275,84/02/23,8402280333
- 8402290084 Notifies that draft IE Insp Repts 30-275/83-37 & 50-323/83-25 obtained General Counsel asked to determine whether documents should be served upon parties OLLINGKY, V Commissioners 84/02/28 ip 22426 042 24X Fichs 50-275,84/02/28,8402290084

H General correspondence

- 8402230089 Requests NRC update mailing labels on priority & free mail to reflect new ofc location CHAMBERLAIN,W California, State of 84/02/15. DI BILBESTRE, B. NRC "- NO Detailed Affiliation Given 2pp 22362 073 24X Fiche: 50-000, 84/02/15, 8402230089.
- O. Advisory Committee on Reactor Safeguards reports & correspondence
- 8402230028 Summarizes 285th ACRS meeting on 840209-11 w/PO&E & NRC re aperation of plant & on 840119 in Los Angeles.CA re safety significance of deficiencies found & corrected by IDVP & util internal design review effort EBERBOLE, J C ACRS - Advisory Committee on Reactor Safeguards 84/02/14 PALLADING, N J, Commissioners 2pp 22379 358 24X Fiche: 50-275,84/02/14,8402230028

- 8402290456 Forwards ACRS 840214 its summarizing 840209-11 magazings to review selected issues on application for OLs MNIGHTON O W Licensing Branch 3 84/02/16 8CHUYLER, J O Pacific Gas & Electric Co 4pp 22438 175 24X Fiche 50-275,84/02/16,8402290456
- P Operating license stage documents & correspondence
- 8402160003 Third partial response to FBIA request for infa re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILK, 8 J Office of the Secretary of the Commission 83/12/14 Public Document Branch 1p 22281 023 24X Fiche 50-000, 83/12/14, 8402160003
- --8402160047 Staff requirements memo re 830707 discussion of procedures for facility review in Washington.DC CHILK.8 J Office of the Secretary of the Commission 93/07/08 PLAINE,H H Office of the General Counsel ZERBE,J E Office of Policy Evaluations ip 22281 061 24X Fithe 50-000.83/12/14. 8402160003
- --8402160072 Staff requirements memo re 810910 discussion of low power OL in Washington, DC CHILK, 8 J Office of the Secretary of the Commission 81/09/16 BICKMIT, L Defice of the General Counsel ip 22281 029 24% Fiche 50-000, 83/12/14, 8402160003
- --B402160089 Staff requirements memo re Billi6 discussion of 670518 memo & seismic reverification plan in Washington.DC CHILK, S J Office of the Secretary of the Commission 81/11/20 Office of the Becretary of the Commission 1p 22281 033 24X Fiche 50-000,83/12/14,8402160003
- --8402160091 Staff requirements memo re 811119 continuation of discussion of Diablo Canyon order in Washington.BC.
 CHILK.S J Office of the Secretary of the Commission BI/12/01 BIRCKS.W J Office of the Executive Director for Operations. lp 22281 034 24X Fiche 50-000.83/12/14.8402160003
- --8402160110 Staff requirements memo re 820205 discussion of Phase I of facility rept in Hashington.DC CHILK.8 J Office of the Secretary of the Commission BR/02/09 BICKHIT.L Office of the General Counsel ip 22281'039 24x Fiche 50-000,83/12/14.8402160003
- --8402160420 Discusses SECY-82-81 to AO recommendation on telemic design errors CHILK:8 J Office of the Secretary of the Commission. 82/03/23 DIRCKS:N J Office of the Executive Director for Operations 1p 22281 170 24X Fiche 50-000.63/12/14.8402160003
- B4020303B5 Provides Commissioners w/info on status of staff resolution of allegations & concerns that may apply to Commission deliberations on licensing plant for criticality & low power testing BIRCKS, W J Office of the Executive Director for Operations SECY-84-003 84/01/04, 4pp 22089 342 24X Fiche 30-275,84/01/04,84020395
- E312120136 Board Notification 84-011 discusses NRC use of terms "important to safety" & "safety-related" EIGENHUT, D 0 Blyision of Litensing 84/01/18 PALLADINO Commissioners 72pp 22241 008 24X Fiche 50-000,84/01/18,8312120136
- B4020A0089 Staff requirements memo re B40112 affirmation/discussion & vote on final rulemaking 100FRI & proposed order denying Joint Intervenors B31031 request for stay of fuel loading & precriticality testing at facility CHILK.8 J. Defice of the Becretary of the Commission B4/01/23 HAYEB, B Office of Investigation PLAINER.H.E Office of the General Coursel 2pp 22110:059 24X Fiche 50-275,84/01/23, B4020A0089
- 3402030051 Staff requirements memo re 840123 discussion of pending investigations re treatment of allegations & concerns about design; const & operation of plant.
 CHILK, 3 defice of the Secretary of the Commission 84/01/26.
 DIRCKS, N J Difice of the Executive Director for Operations.
 HAYES, B B. Defice of Investigation ip 22091:080, 24x
 Fiche 50-275,84/01/26,8402030051.
- 3402060477 Notification of B40131 meeting w/util in Ban Francisco.CA to discuss preliminary results of NRC review & evaluation of small bore piping analyses
 BCHERLINO.H Licensing Branch 2 84/01/27. KNIOHTON.Q \(\text{Licensing Branch 3.}\) 4pp 22110 158. 24X Fichs 80-275.84/01/27.
 8402060497

- B402010410 Generic Ltr 84-04 to all operating PWR licentees. CP holdsrs & applicants for CPs re safety evaluation of Hestinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Bvc list encl EISENNUT.D O Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc 59pp 22177 087 24X Fiche 50-000,84/02/01,8402010410
- 8402060422 Discusses suppl to Nuclear Plant Administrative Procedure NPAP A-100 (81), "Administrative Program to Control Return to Power After Reactor Trip," in, response to Items 1-6 of Action Item i 1 of Generic Itr 83-28 SCHUYLER, J D Pacific Gas & Electric Co 84/02/01 EISENHUT, D Q Division of Licensing 1p 22085 099 24% Fiche 50-275, 84/02/01, 8402060422
- B40R070234 Responds to B40105 Owneric Ltr 84-01 re use of terms important to mafety & safety-related Util participation in response will be through steering committee & chairman of util safety classification group SCHUYLER.JO Pacific Gas & Electric Co 84/02/03 TAYLOR.J M Director's Office, Office of Inspection and Enforcement 1p 22101 142 24X Fiche 50-000.64/02/03.8402070234
- 8402070375 Forwards response to NRC 840131 meeting concerns re 10y9 verification of small bore piping & supports Response intended to clarify relationship between NRC issues & IDVP verification CLCUD,R i. Robert & Cloud Associates, Inc. 84/02/03 DENTON,H R Office of Nuclear Reactor Regulation, Director MARTIN,J B Regis 5, Office of Director MANRATIS,G M. Pacific Gas & Electric Co 107pp 22099 207 24% Fiche 50-275,84/02/03,8402070375
- B402270461 Issues exemption from requirements of 10CFR50, Section 50 71(e), extending submittal date of FBAR update to 840922 to reflect design of unit after completion of design verification program, per util 830823 & 1207 requests.

 KN10HTDN.6. W Licensing Branch 3 84/02/12. SCHUYLER, J. O. Patific Oas & Electric Co 4pp 22438 168 24X Fichs 50-275, 84/02/12, 840029041
- --B402290466 Exemption from requirements of 10CFR50, Section 50 71(s) granting extension to 840922 for FSAR update to reflect design of unit after completion of design verification program EISCANUT, D. G. Division of Licensing 84/02/12 Pacifit Oas & B402290461 Page 22436-172 PAX Fiche 50-275,84/02/12, B402290441
- 8401190040 Board Notification 84-027 provides RL Cloud submittal addressing preliminary concerns on small bore piping & supports raised at 840131 meeting w/PG&E EIBENHUT, D Q, Division of Licensing 84/02/13 PALADINO, OILINEXY, ROBERTS Commissioners 3pp. 22241:186 24X Fiche 50-275.84/02/13.8401190040
- 8401190059 Board Notification 84-032, provides addl info on environ qualification Submittal augments info in Board Notifications 84-004 & 84-009 EISENHUT. D 9 Division of Licensing 84/02/13, Atomic 84fety and Licensing Board Panel 10pp. 22314-204 24% Fiche: 50-000, 84/02/63, 8401190059
- --84021003/5 Forwards Bandia FY83 rept, "Equipment Qualification Insp. Program." Rept provides examples to highlight issues reised during Region IV Vendor Program Branch insps. for which Sandia provided consultant support
 DIRCKS.W.J. Diffice of the Executive Director for Operations
 84/02/02 PALLADING, GILINSKY.V., ROBERTS, T. Commissioners. 3pp. 22314-214 24X Fiche: 50-275,84/02/13,8401190059.
- --BAQ2100378 "Equipment Qualification Insp Program Annual Rept "
 BUSTARD-L D. BENSON, J. J., SALAZAR, S. A. Randia Laboratories, Fin
 A-1650 B3/12/31 Division of Vendor & Technical Programs,
 18pp 22314:217. 24% Fichs. 50-275, 84/02/13, 8401190059
- --8402210280 Provides Commission w/info developed by Bandis on equipment qualification & other matters
 DIRCKE W J Office of the Executive Director for Operations
 SECY-883-4578 84/01/10. 28pp. 22314:235 24X
 Fiche 50-000.84/02/13.8401190059
- --8402210282 Provides Commissioners w/info on status of resolution eq Sandia concerns about NRC equipment qualification program & other matters DIRCKB, W. J. Office of the Executive Director for Operations. SECY-83-457C. 84/01/18. 15pp 22314.263. 24X Fiche 50-275,84/02/13.8401190089

- B402160429 Notifies that util will provide formal proposal to submit remaining NUREO-0737 required Tech Spec changes by B40330, in response to Generic Ltr B3-37
 SCHUYLERJ D Pacific Gas & Electric Co B4/02/13 KNIGHTON, G W Licensing Branch B 1p R2268 315 24X Fiche 50-275, B4/02/13, B402160429
- 8402210216 Submits supplementary instructions for protection & retention of GA records, per 840131 meeting request All GA records are to be maintained & may not be removed from project files

 8CHUYLER.J D Pacific Gas & Electric Co 84/02/15 EISENHUT, D O Division of Licensing 2pp 22316 208 24X Fiche 30-275, 84/02/15.
- 8402210267 Forwards response to MRC questions re quality work performed by individuals allegedly involved in drug dealings or drug use at facility, per BECY-84-61, Items 71,73 & 183 W/o encl SCHUYLER, J O Pacific Gas & Electric Co 84/02/15 MARTIN, J B Region 5, Office of Director 1p 22314 319 24X Fiche: 50-275, 84/02/15, 8402210267
- B402220363 Bummarizes B40207 site visit conducted under ex parte rules Detailed account of tour provided TRUBATCH: S L NRC - No Detailed Affiliation Given B4/02/18 NRC - No Detailed Affiliation Given. 4pp 22335 298 24X Fiche. 50-275, 84/02/15, 8402220363.
- 8402240248 Staff requirements memo re 840210 comments by parties on facility criticality & low power operation Commission tentatively scheduled to discuss & possibly vote on subj on 840308.

 CHILK, 8, J Office of the Becretary of the Commission 84/02/15 Office of the Secretary of the Commission 1p 22381 277 24x Ficha. 50-275,84/02/15,8402240248.
- 8401190068 Board Notification 84-033 provides "Bys Interaction Program," task action plan for Unresolved Bafety Issue A-17. Distribution list encl EISENMUT,D 0 Division of Licensing 84/02/16. PALLADING Commissioners 8pp 82482.091 24X Fichs 90-000.84/02/16, 8401190068
- @ Inspection reports, IE Bulletins & correspondence
- B402010364 Further response to FOIA request for records re Ofc of Inspector & Auditor review of NRC investigation reported in NUREQ-0862 & other files concerning facilities. Forwards App B documents App A & B documents available in FDR. FELTON, J M Division of Rules and Records. B3/11/22 REYNOLDB, J Center for Law in the Public Interest App. 22058.203. 24X Fiche: 50-000.83/11/22,8402010364
- --B203150317 Submirs questions re inclusion of util comments & qualifications in RL Cloud Associates second draft of QA audit & misrepresentations to NRC re status of rept during period of util review.

 OTTINGER: House of Rep., Ensrgy & Commerce B1/12/18, PALLADINO, N. Commissioners. 7pp. 22059,036, 24x Fiche: 50-000,83/11/22,8402010364.
- --8402010372 Recommends transmittal of investigation review rept to Congress per R Ottinger 820204 ltr re inconsistencies in NUMEQ-0862 & M Udall 820208 request Related info encl KAMMERER. C Office of Congressional Affairs. 82/08/31 PALLADINO.N., GILINBRY.V., AMEARNE.J. Commissioners 150pp 22058: 207. 24X Fiche: 50-000.83/11/R2.8402010364
- --8402010378 Forwards review of NUREG-0862, "Insp Rept of Preliminary Rept, Seismic Revshification Program at Diablo Canyon Units i & 2 " Related info encl.

 BDULDEN.H., AMERBACH.M Office of Inspector & Auditor 83/11/22 CUMMINGB.J J Office of Inspector & Auditor 83/11/22 CUMMINGB.J J Office of Inspector & Auditor 37pp 22059, 357 24X Fiche: 50-000, 83/11/22, 8402010364
- B312120153 IE Info Notice 84-06. "Steam Binding of Auxiliary Feedwater Pumps." Syc list encl JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/25 Consolidated Edison Co. of New York. Inc. 120pp. 22058.001 24X Fiche: 50-000.84/01/25.8312120153
- 8402030375 Ack receipt of 840109 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-275/83-38 & 50-323/83-26,
 BISHOP.T.M. Division of Resident, Reactor Project & Engineering Programs, 84/01/31. SCHUYLER.J D Pacific Gas & Electric Co. ip 22066:057 24X Fiche 50-275.84/01/31.8402030375.

- --8402030381 Responds to NRC 831207 ltr re violations noted in IE Insp Repts 50-275/83-38 & 50-323/83-26 Corrective actions fuel handling personnel reinstructed to follow radiological control procedures & individual posted at controlled area 8CHUYLER, J D Pacifit Gas & Electric Co 84/01/07 MARTIN. J B Region 3. Office of Director App 22066 058 24X Fiche 50-275,84/01/31,8402030375
- 8402140466 Forwards IE Inap Rept 50-275/83-40 on 831213-20 & notice of violation 818HOP.T W Division of Resident.Reactor Project & Engineering Programs 84/01/31 SCHUYLER,J O Pacific Gas & Electric Co 2pp 22221 065 24X Fiche 50-275.84/01/31.8402140466
- --8402140468 Notice of violation from insp on 831213-20 CANTER.H L Region 5, Office of Director 84/01/31 1p 22221 067 24X Fiche 50-275,84/01/31,8402140466
- --B402140471 IE Insp Rept 50-275/83-40 on B31213-20 Violation noted inadequate preparation & maint of environ qualification evaluations & files MORRILL, P.J., CANTER. H.L. Region 5, Office of Director B4/01/25 10pp 22221 068 24X Fiche 50-275.84/01/31.8402140466
- 840R290455 Final response to FOIA request for records re anonymous allegations involving facilities submitted in D Fleischaker 1tr to D Eisenhut Bocument withheld (ref FOIA Exemptions 5 & 7).
 FELTON, J M Division of Rules and Records 84/01/31 REYNOLDS, J Center for Law in the Public Interest 2pp 22437 276, 24X Fiche 80-275,84/01/31.8402290455
- B401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " 8vc list encl JORDAN,E L. Division of Emergancy Preparedness & Engineering Response (Post 830103). 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179. 24X Fiche 50-000.84/02/03.8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers" Svc list encl. DEYDUNG.R C Director's Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co. of New York, Inc 102pp 22177 156. 24X Fiche 50-000.84/02/03.8401190017.
- B402140141 Forwards "Bostrom-Bergen/Meddco Metals Allegations Investigation," interim rept Status of investigation into allegations made by former employees of Bostrom-Bergen/Meddco Metals provided RAYMOND, WA Pacific Oas & Electric Co 84/02/10 MARTIN, J. B. Region 5, Office of Director 1p 22218, 007 24X Fiche 50-275, 84/02/10, 8402140141.
- --8402140146 "Bostrom-Bergen/Meddco Metals Allegations Investigation." interim rept # Pacific Cas & Electric Co. 84/02/10 205pp 22218 008 24X Fithe 50-275,84/02/10,8402140141
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CfR30, App R), " Syc list ent!

 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidate Edison Co of New York, Inc. 124pp 22365, 259 24% Fiche 50-000, 84/02/13, 8401190041
- 8401170037 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '"
 Syc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103), 84/02/14 Consolidated Edison Co. of New
 York, Inc. 115pp. 22365, 141, 24X Fiche; 50-000, 84/02/14, 8401170037
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/15 Consolidated Edison Co. of New York: Inc 118pp 22366 142 24X Fiche 50-000, 84/02/13, 8401190045
- B401170062 IE Info Notice B4-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value" Svc list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/02/21 Consolidated Edison Co of New York, Inc 116pp 22366-024, 24X Fiche 50-000,84/02/21,8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies,"
 Syc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/24 Consolidated Edison Co of Neu
 York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066

- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
 Svc list encl
 JORDAN.EL Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc. 120pp 22431 060 24X Fiche 50-000.84/02/27.8401190067
- R Periodic operating reports & related correspondence
- 8402020263 Forwards "Annual Summary Rept on Monitoring & Reporting Program at Diablo Canyon Power Plant During 1983" & "Thermal Effects Monitoring Program 1983 Annual Rept "
 THORNBERRY: R C Pacific Gas & Electric Co 84/01/30 JUNES. K R California, State of 2pg 22032 260 24% Fiche 50-275.84/01/30.8402020263
- --B402020265 "Annual Summary Rept on Monitoring & Reporting Program at Diablo Canyon Power Plant Buring 1983 " * Pacific Qas & Electric Co 83/12/31 51pp 22052.262 24% Fiche 50-275,84/01/30.8402020263
- --8402020272 "Thermal Effects Monitoring Program 1983 Annual Rept "
 W/two oversize maps Aperture cards are available in PDR
 * Patific Gas & Electric Co 83/12/31 260pp 22052 313 24X
 Fiche 80-279,84/01/30.8402020263
- S Reportable occurrences. LERs & related correspondence
- 8402080029 Responds to FDIA request for documents re facility hat functional testing problems including broken thermowells. Loose & broken reactor coolant pump parts & loose thermal sleeves Forwards App A documents Documents also in PDR FELTON. J H Division of Rules and Records 83/11/16 OARDE. B Government Accountability Project 3pp 22170 253, 24X Fiche 50-000, 83/11/16, 8402080029
- --B4020B0036 List of hot functional testing exceptions Related info encl # Affiliation Not Assigned B3/11/16 19pp 22170 236 24X Fiche 50-000, B3/11/16, 84020B0029
- 8402130477 RD on 831215. Fire barrier wall between containment penetration area & auxiliary bldg removed. Wall replaced w/concrete berrier for add1 strength in event of steam pipe leak prior to aperation SCHUYLER. J O Pacific Oss & Electric Co 84/01/23 MARTIN. J B Region 5. Dffice of Director ip 22201 174 24X Fiche 50-275.84/01/23.8402130477
- 8312120140 Board Notification 84-014 forwards H Hudson allegations re min wall thickness requirements in RCPB EIBENHUT,D G Division of Licensing 84/01/24 PALLADING, OfLINSKY, ROBERTS Commissioners 3pp 22241.080, 24X Fiche 50-275.84/01/24.8312120160
- --8402190323 Forwards add1 H Hudson allegations re facility GA qualifications JOOSTEN-J K Commissioners 84/01/13 DENTON,H Defice of Nuclear Reactor Regulation, Director 1p 22241 083. 24X Fiche 50-275,84/01/24,8312120160
- 8402150326 Forward: H Hudson 840102 memo re 840107 allegation interview in San Luis Obispo.CA.per 840110 telcon KIRSCH.D F Region 5. Office of Director. 84/01/10 GILINGKY.V Commissioners ip 22241 084 24X Fiche 50-275,84/01/24, 8312120160
- ---B402150327 Repts QA deficiencies in ultrasonic measurement of RCPB valves for min wall thickness requirements Supporting documentation enc!
 HUDSON.H Pullman, Inc. 84/01/02 GILINSKY, V Commissioners 91pp 22241 085. 24X Fiche 50-275.84/01/24.8312120160
- B40207036B LER 84-004-00 on 810921 & B31027. Inadvertent RCS residual heat pump suction valve closures occurred Caused by testing performed on analog channel, along w/inadequate surveillance test procedures Procedures modified W/840202 ltr 018CLON, J M . BHIFFER, J, D Pacific Oqs & Electric Co. 84/02/02 Jpp. 22099 1[3 24X Fithe 50-275, B4/02/02, B40207036B
- 402100245 LER 84-001-00 on 840106 inadvertent safety injection actuation accurred Caused by momentary grounding of ac supply to solid state protection sup blave relay circuit Operators reinstructed on procedures W/840206 ltr KELLY,N J. & MIFFER, D. Pacific Oas & Electric Ca 84/02/06 3pt 22177 341 24X Fichs: 90-275,84/02/06,8402100245

- 8402150356 RO on 831230.conduit installed through fire barrier wall in cable apreading room Un 840107.four fire doors removed & replaced w/heavy duty fire doors Un 840109.fire barrier penetrations nonfunctional due to mods SHIFFER.J D Pacific Gas & Electric Co 84/02/06 MARTIN.J B Region 5. Office of Director 2pp 22250 113 24X Fiche 50-275.84/02/06.8402150356
- 8402150255 LER 84-002-00 on B40107, both trains of control room ventilation sys powered by same 480-volt vital bus Caused by operator failure Operator trained & operating procedure revised W/840208 ltr
 KESSINGER, W W , SCHUYLER, J O Pacific Oas & Electric Co 84/02/08 4pp 22250 l17 24% Fiche SQ-275,84/02/08,8402150255
- 8402170195 PNS-V-84-003 on 840212, unauthorized individual entered protected area Individual observed by security at all times Individual arrested NRC will followup during next routine physical security insp 8CHMAN.c., FISH,R F. Region 5, Office of Director 84/02/13 ip 22297 282 24X Fiche 50-275,84/02/13,8402170195
- 8402210224 LER 84-005-00 on 840116 diesel generator 1-2 automatically started due to 4 kV startup power bus undervoltage Causad by operator inadvertently isolating startup transformer 12 from 4 kV vital bus feeder W/840215 ltr
 KEBSINGER.H. W. SHIFFER.J D Pacific Gas & Electric Co 84/02/15 4pp 22316 148 24X Fiche 50-275,84/02/15,8402210224
- 8402210243 LER 84-003-00 on 840116.plant experienced spurious safety injection actuation while in cold shutdown Caused by momentary voltage drop on instrument ac bus 1-1 No corrective actions planned. W/840215 ltr HINDS.J. SHIFFER.J D. Pacific 8as & Electric Co. 84/02/15 3pp 22315 352 24X Fiche 50-275.84/02/15.8402210243
- T Hearing transcripts on non-antitrust matters
- 8402030042 Transcript of 840123 Commission affirmation/discussion & vote in Washington, DC re SECY-84-1 Pp 1-5 W/supporting documentation * Commissioners 84/01/23 9pp 22071 118 24X Fiche 50-275,84/01/23,8402030042
- 8402030388 Transcript of Commission 840123 discussion in Washington, IX Pp 1-61 Supporting documentation entl * Commissioners 84/01/23 66pp 22070 126 24X Fiche: 50-275, 84/01/23, 8402030388
- 8401190019 Board Notification 84-022 forwards transcript of NRC meeting w/G Btokes re allegations concerning small bore piping Transcript identifies certain individuals by name & withheld from public disclosure EISENHUT, D 9 Division of Licensing 84/02/07 PALLADING, OILINSKY, ROBERTS Commissioners 3pp 22159 231 24X Fiche: 50-275, 84/02/07, 8401190019
- 8401190036 Board Notification 84-025 forwards transcript of 840131 meeting w/util re review of small bore piping analyses EISENHUT, D O Division of Licensing 84/02/08 PALLADINO, N J OLLINSKY, V . ROBERTS T Commissioners 3pp 22200 331 24X Fichs S0-275,84/02/08,8401170036
- ---B402130076 Transcript of 840131 meeting w/util in San Franciscs.CA ?#
 review of small bare piping analyses Pp i-128. Supporting
 documentation encl
 * Commissioners 84/01/31 162pp, 22200,334 24x
 Fiche 50-275,84/02/08,8401190036
- B402170519 Transcript of Commission 840210 public meeting in Washington DC re-comments by parties on Diable Canyon criticality & low power operation Pp 1-96. Supporting documentation encl # Commissioners B4/02/10 125pp 22305:201 R4X Fiche 50-275.84/02/10, B402170519
- U Congressional/Executive Correspondence
- 8402290002 Responds to FDIA request for correspondence NRC received from Senators J McClure, JB Johnston & P Laxalt during past 2 yrs Forwards App A documents Name of individual deleted from Documents B & 9 of App A (ref FDIA Examption 6) FELTON, J M Division of Rules and Records 83/11/30 KOL1, E Cable News Network, Inc . 6pp. 22438 002, 24X Fiche 80-000, 83/11/30,8402290002

Ρ...

- --B402290069 Forwards rept covering Phase 1 investigation into circumstances surrounding development of "Preliminary Rept. Saimic Reverification Program "Rept covering second phase due to Commission in Feb 1982 W/o encl KAMMERER. C Office of Congressional Affairs B2/01/27 DTTINGER. R. House of Rep. Energy & Commerce SIMPSON, A Benate. Environment & Public Works UDALL. M House of Rep Interior & Insular Affairs 2pp 22438 026 24% Fiche 50-000, B3/11/30, B402270002
- --8402290082 Forwards rept covering Phase 2 investigation into circumstances surrounding development of "Preliminary Rept, Beismic Reverification Program" W/o encl KAMMERER.C Office of Congressional Affairs 82/02/10 OTTINGER.R L. House of Rep , Energy & Commerce SIMPBON, A Beneto: Environment & Public Works UDALL, M House of Rep , Interior & Insular Affairs 2pp 22438 028 24% Fiche 50-000,83/11/30.8402290002
- --B402290iiB Discusses seismic design verification program for facilities, required by Commission Billi7 order NRC approved proposal of util to retain Teledyne to conduct independent audit KAMMERER, C Office of Congressional Affairs B2/04/01 KAMMERER, T House of Rep , Government Operations HATFIELD, M Senate, Appropriations BEVILL, T House of Rep , Appropriations ip 2243B 035 24X Fiche 50-000, B3/11/30, B402270002
- 8402070081 Further response to FOIA request for IE Insp Rept 79-19, associated hotice of proposed imposition of civil penalties, notice of violation & order to show cause Forwards App A documents Documents also available in PDR FELTON, J M Division of Rules and Records 83/12/20, HAMLIN, J B Bhaw, Pittman, Potts & Troubridge 4pp 22188 104 24X Fiche 50-000,83/12/20,8402090081
- --8402090127 Requests testimony on Commission position re adequacy of licensee GA programs at Subcommittee on Energy & Environ Bi1027 hearing on GA as applied to reactors under const UDALL.M.K House of Rep., Interior & Insular Affairs Bi/10/13 PALLADINO, N Commissioners Ip 22188 112 24X Fichs. 30-000, 83/12/20, 8402090081
- 8402010242 Requests thorough investigation of worker allegations about safety, poor quality, intimidation & falsification of records Investigation should be completed prior to allowing low power operation MCCURQUIDALE, D. California, State of 84/01/19, PALLADINO, N. Commissioners ip, 22040:359 24X Fiche 50-275,84/01/19,
- B402010078 Objects to authorization of plant operations prior to resolution of allegations. Independent audit of design review & comprehensive GC rethep & Ofc of Investigations review of GA/GC breakdown causes recommended ALATORRER California; State of 84/01/23 PALLADIND.V Commissioners ip 22042 186 24% Fiche 50-275,84/01/23,8402010078
- B402280335 Recommends that prior to decision re licensing for post-criticality testing & full power testing, Commission provide guidelines governing evaluation of allegations reconst GA deficiencies PANETTA, L. E. House of Rep. 84/02/08 PALLADIND, N. J. Commissioners, 2pp. 22402 275 24X Fiche 50-275, 84/02/08, 240-200354.
- B402280370 Requests listed info, including info re allegations on failure to parform pips support calculations & alleged instruction that inspectors did not inspect vendor-supplied matl welds Info requested by 840401
 UDALL, M.K. House of Rep., Interior & Insular Affairs 84/02/22
 PALLADING, N. Commissioners. 3pp. 22407:134 24X
 Fiche: 50-275,84/02/22,8402280370
- DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

 F Security, medical, emergency & Pire protection plans
- 8402210279 Forwards drawing of cables for HPCI sys.per 830601 meeting proposal, in response to Generic Ltr 81-12 re alternative shutdown sys HPCI sys will be used for primary elternative shutdown Related info encl. W/o drawing MCRLEY, 6 M. Philadelphia Electric Co. 83/08/08 GEARS, 9 NRC No Detailed Affiliation Given. 13pp 22315:307 24X Fiche 50-277,83/08/08,8402210279
- 8402080345 Forwards IE Insp Repts 50-277/83-34 & 50-278/83-34 on 831212-16 No violations noted MARTIN, T. T. Division of Engineering & Technical Programs. 84/01/25 DALTROFF: 8 L. Philadelphia Electric Co. 2pp. 22130 253 24X Fiche. 50-277.84/01/25,8402080345.

- --8402080348 iE Insp Repts 30-277/83-36 % 50-278/83-34 on 831212-16 No violations noted Major areas inspected radiation protection program, including in-plant radiation protection program implementation & high radiation area controls COLLING, D J. SHANBAKY, N M Region i. Office of Director 84/01/19 8pp 22130 255 24% Fiche 50-277,84/01/25,8402080345
- B402070514 Forwards SER accepting licensee proposed design for alternate safe shutdown capability as compliance w/fire protection requirements of 10CFR50. App R. Items III g 3 k III L BTOLZ, J F Operating Reactors Branch 4 B4/01/24 PAUER.E G Philadelphis Electric Co 2pp 22141 286 24X Fiche 50-277.84/01/26,8402070514
- --8402070313 SER accepting licensee proposed design for alternate safe shutdown capability as compliance w/fire protection requirements of IOCFR30.App R. Items III 0 3 & III L * NRC No Detailed Affiliation Given 83/12/22 17pp 22141 268 24X Fiche 50-277.84/01/26/8402070514
- 8402080391 Forwards IE Insp Repts 50-277/B3-33 & 50-278/B3-31 on B31128-1202 No violation noted MARTIN.T T Division of Engineering & Technical Programs 84/01/26 DALTROFF, S L Philadelphia Electric Go 2pp 22131 010 24X Fiche 50-277.84/01/26.8402080391
- --84020B0404 IE Insp Repts 50-277/83-33 & 50-278/83-31 on 831128-1202 No violation noted Major areas inspected followup of emergency preparedness items & prior public prompt notification image rept COHEN, I , HAWXHURBT, J , CROCKER, H W Region 1. Office of Director 84/01/20 14pp 22131 012 24X Fiche 50-277,84/01/26, 8402080391
- 8402030475 Requests response to NRC 830325 concerns re approved physical security plan Concerns relate to badge sys for newly assigned personnel & unescorted access STOL2, J F Operating Reactors Branch 4 84/01/30 BAUER, E Q Philadelphia Electric Co ip 22066 015 24X Fiche 50-277, 84/01/30,8402030475
- 8402220364 Ack receipt of 840117 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/83-34 & 50-278/83-32 BTAROSTECKI: R Division of Project & Resident Programs B4/02/09 DALTROFF, B L Philadelphia Electric Co ip 22335:302 24X Fiche 50-277.84/02/09,8402220364
- --B402220374 Responds to NRC B31222 ltr re violations noted in IE Insp Repts 50-277/83-34 & 50-278/83-32 Corrective actions plant penetration seals upgraded to meet IOCFR50, App R requirements DALTROFF, B L Philadelphie Electric Co 84/01/19 STAROSTECKI, R Division of Project & Resident Programs 7pp 22335 303 24x Fiche 50-277, 84/02/09, 8402220364
- 8402210096 Forwards FEMA final exercise rept for 831116 joint exercises of state & local radiological emergency preparedness plans for TMI-1 due to Category A deficiencies noted in three areas

 MARTIN, T T Division of Engineering & Technical Programs 84/02/10

 DALTHOFF, B. L Philadelphia Electric Co 3pp 22317 333 24X

 Fiche 50-000,84/02/10,8402210096
- --B402210102 Exercise evaluation rept of Commonwealth of PA & Dauphin, York, Lancaster, Cumberland, Lebanon, Berke, Schuykill, Snyder & Union Counties emergency preparedness plans * Federal Emergency Management Agency B3/12/20, 157pp 22317 336 24X Fiche 50-000,84/02/10,8402210096
- 8402220034 Provides current status & projected completion date of continuing penetration seal program & proposed schedule for specific cable rerouting, per App R to 10CFR90 BOYER, V 8 Philadelphia Electric Co. 84/02/10 EISENHUT, D G. Division of Licensing 4pp 22338.236 24% Fiche 30-277,84/02/10,84/0220034.
- J Insurance & indemnity information
- 8402210233 Forwards Endorsement 4 to MAELU Certificates M-8 & M-9 & NELIA Certificates N-8 & N-9 W/o MAELU Certificate M-8 & NELIA Certificate N-9 BRADLEY, E J. Philadelphia Electric Co 84/02/14 8ALTZMAN, J. Assistant Director for State & Licensee Relations. 3pp 22314 330 24X Fiche 30-277,84/02/14,8402210233.
- 8402210335 Forwards Endorsement 105 to NELIA Policy NF-140 & Endorsement 58 to MAELU Policy MF-67, BRADLEY, E. J. Philadelphia Electric Co. 84/02/14 SALTZMAN, J. Assistant Director for State & Licensee Relations 3pp 22314, 359 24X Fiche 50-277, 84/02/14, 8402210335

- P Operating license stage documents & correspondence
- 8402130013 Responds to FDIA request for two categories of documents re IDCUR program Forwards App A & B documents Documents placed in FDR FELTON, J M Division of Rules and Records 83/12/21 SHOLLY, S C Union of Concerned Scientists 5pp 22282 004 24X Fiche 50-000.83/12/21,8402130013
- --83092&001i Summary of 830807-12 site visit & IDCOR meeting in Chicago, IL re status of data collection activity & containment capability BAOCHI, G Equipment Qualification Branch FIN A-6495 83/09/12 Equipment Qualification Branch. 5pp 22282 203 24X Fiche 50-000,83/12/21.8402130013
- B402270487 Responds to FOIA request for SECY 83-292, BECY 83-299, BECY 83-311, SECY 83-333 & AEOD/E322 to be placed in PDR. AEOD/E322. SECY 83-292 & SECY 83-333 placed in PDR Portions of SECY 83-299 withheld (ref FOIA Exemption 5) FELTON, J H Division of Rules and Records 84/01/12 GRABER, L D NUS Corp 4pp 22414 194 24X Fiths 50-277, 84/01/12, 8402270487
- --8310060351 Forwards AEGD engineering evaluation rept. "Damage to Vacuum Breater Valves as Result of Relief Valve Lifting."
 Rept implies that qualification program for valves may be inadequate Transmittal to NRR recommended
 HSU.C Reactor Operations Analysis Branch 83/09/21
 SEVFRIT.K V Reactor Operations Analysis Branch 4pp 2241424X Fiche 30-277.84/01/12,8402270497 4pp 22414-198
- --83100A0353 "Damage to Vacuum Breaker Valves as Result of Relief Valve # Director's Office B3/09/16 6pp 22414 200 24X
 Fiche 50-277, 84/01/12, 8402270487
- 102050385 Discusses request for amend to Tech Specs re extension of local leak rate test interval for primary containment isolation valves improvement to maint program for MSIVs insufficient Request denied EISEMHUT, D 0 Division of Licensing 84/01/20 DAUER, E. 0 Philadelphis Electric Co 4pp 22110 293 24X Fiche 50-277,84/01/20,8402060386
- -B402050391 Forwards FR notice of denial of request for amend to License DPR-44 re extension of local leak rate test interval for primary containment isolation valves.

 * Operating Reactors Branch 4 B4/01/20. Bocketing & Services Branch 2pp 22110 297. 24X Fishe 50-277.84/01/20.8402060386
- --B402060394 Notice of denial of B31209 request for amend to License DPR-44, extending local leak rate test interval for primary containment isolation valves.

 STOL2.J F Operating Reactors Branch 4. 84/01/20 3pp 22110, 299 24x Fiche: 50-277, 84/01/20, 8402060386
 -)2170518 Forwards Amends 91 & 93 to Licenses DPR-44 & DPR-56, respectively & safety evaluation. Amends increase min number if required operable instrument channels for AFRM & Intermediate range monitor rod block trip sys 26ARS. O. Operating Reactors Branch 4 84/02/10 9AUER. E G initiatelylas Electric Co. 2pp. 22305 321. 24% icha 50-277.84/02/10,8402170518
 - 8402170524 Amends 91 & 93 to Licenses DPR-44 & DPR-56, respectively, increasing min number of required operable instrument channels for APRN & Intermediate range monitor rod block trip sys from two to four & three to six respectively.

 GTOL2, J F Operating Reactors Branch 4. 84/02/10 10pp.
 22305-323 24X Fiche.50~277.84/02/10.8402170318
- Inspection reports: IE Bulletins & Correspondence
- 112120153 IE Info Notice 84-05, "Steam Binding of Auxiliary Feedwater H2120153 IE Info Notice 84-06, "Steam singing of Notice y Pages " Syc list and JDRDAN.E L. Division of Emergency Preparadness & Engineering Response (Post 830103). 84/01/23. Consolidated Edison Co. of New York, Inc. 120pg 22058 001 24X Piche: 50-000,84/01/25,8312120153
- 02080345 Forwards IE Insp Repts 50-277/83-34 & 50-278/83-34 on B31212-16 No violations noted.

 MARTIN, T T. Division of Engineering & Technical Programs 84/01/25

 PALTROFF, B L Philadelphia Electric Co 2pp. 22130/253. 24X

 Ficher 50-277,84/01/25,8402080345

- --B402080348 IE Insp Repts 50-277/83-34 & 50-278/83-34 on 831212-16 No violations noted Major areas inspected radiation protection program including implant radiation protection program implementation & high radiation area controls CCLLINS.D J., SHANDAKY.M M Region 1, Office of Director 84/01/19 8pp 22130 255 24% Fiche 50-277,84/01/25.8402080345
- 8402080391 Forwards IE Insp Repts 50-277/83-33 & 50-278/83-31 on 83:128-1202 No violation noted MARTIN: T Division of Engineering & Technical Programs. 84/01/26 PALTROFF: 8 L Philadelphia Electric Co 2pp 22:31 010, 24x Fichs: 50-277.84/01/26.8402080391
- --8402080404 IE Insp Repts 50-277/83-33 & 50-278/83-31 on 831128-1202 Mg violation noted Major areas inspected, followup of emergency preparedness items & prior public prompt notification insp rept COHEN.I , HAMXHURBT. J , CROCKER, H W Region 1, Office of Director 84/01/20. 14pp 22131 012 24X Fiche 50-277,84/01/26,8402080391
- 8402160310 Forwards IE Insp Repts 50-277/83-35 & 50-278/83-33 on B31128-1202 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 84/02/01 DALTROFF.S L Philadelphia Electric Co 2pp 22269-125. 24X Fiche 50-277.84/02/01.8402160310
- --8402160303 IE Insp Repts 50-277/83-35 & 50-278/83-33 on 831128-1202
 No violations noted Major areas inspected implementation & status of NURE0-0737 Items II.B 3.II F 1 1-3 & III D 3.3
 re post-accident effluent monitoring & sampling
 HHITE.J R Region i. Office of Director HULL.A. KNOX.N
 Brookhaven National Laboratory 84/01/25 22pp 22269.127, 241
 Fichs 50-277.84/02/01.8402160310
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls" Svc list encl JORBAN.E.L. Division of Emergency Preparedness & Engineering Response (Poet 830103) 84/02/03 Consolidated Edison Co of New York, Inc. 119pp. 22114 179 24X Fiche 30-000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Notification in Bulletin 84-01, "Cracks in BWR Hark I Containment Vint Headers " Syc list enc!

 DEYQUING R. C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co. of New York, Int. 102pp 22177-106 24X Fiche 80-000.84/02/03.8401190017.
- 8402100432 Forwards request for add1 info re masonry wall design, par IE Bulletin 80-11. Structural & Geotechnical Engineering Branch position on use of joint reinforcing in qualifying unreinforced masonry walls shot STOL7.J.F Operating Reactors Branch 4, 84/02/07 BAVER, E 9 Philadelphia Electric Co App 22213 017 24X Fiche 50-277.84/02/07.8402100432
- B402220344 Ack receipt of 840119 itr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-277/83-34 & 50-278/83-32 BTAR081ECKI, R Division of Project & Resident Programs. B4/02/09 DALTROFF, S L Philadelphia Electric Co ip 22335 302 24X Fiche: 50-277, 84/02/09, 8402220364
- --B402220374 Responds to NRC 831222 ltr re violations noted in IE Insp. Repts 50-277/83-34 & 50-278/83-32. Corrective actions plant penetration scals upgraded to meet 10CFR50, App R requirements.

 DALTRUFF, B. L. Philadelphia Electric Co. 84/01/19, STAROSTECKI, R. Division of Project & Resident Programs, 7pp. 22335:303 24X Fiche 50-277, 84/02/09, 8402220344
- 8402240089 Forwards IE Insp Repts 50-277/83-32 & 50-278/83-30 on 831116-18 & notice of deviation.

 MARTIN T Division of Engineering & Technical Programs. 84/02/09 DALTRUFF, 8 L. Philadelphia Electric Co. 2pp 22375-013 24X Fiche 50-277.64/02/09.8402R40089
- -8402240091 Notice of deviation from insp on 831114-18
 * Region 1, Office of Director. 84/02/09 1p. 22
 Fichs 50-277,84/02/09,8402240089. 22375.015 24K
- ~-8402240095 IE Insp Repts 50~277/83-32 & 50~278/83-30 on B3116~18
 Deviation noted: QA records program not implemented in full
 conformance w/ANRI N45 2 9~1974 by June 1983
 NAPUDA: G Region 1: Office of Director CAPHTON, D L Bivision of
 Engineering & Technical Programs 83/12/30. 6pp 22375,016 20
 Fiche 50~277,84/02/09,8402240089
- 8401190041 IE Info Notice 84-09, "Lessont Learned From NRC Imaps of Fire Protection Bare Shutdown Sys (10CFR50, App R)," Syc list encl JJRDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365 259, 24% Fiche 80-000,84/02/13,8401190041

- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection "
 - NOTIFICATION OF EMBRESSION PROPERTY & Engineering Response (Post 830103) 84/02/14 Consolidated Edison Co of New York, Inc. 115pp 22345 141 24X Fiche 50-000,84/02/14,8401170039
- B401190045 IE Info Notice 83-63. Suppl 1. "Potential Failures of Hestinghouse Type 8A-1 Differential Relays " Svc list encl JDRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366 142 24X Fichs 50-000,84/02/15,8401190045
- 8402290305 Forwards IE Insp Repts 50-277/84-02 & 50-278/84-02 on 840116-20 & notice of violation MARTIN.J.S Division of Engineering & Technical Programs 84/02/15 DALTROFF,8 L Philadelphia Electric Co 2pp 22427 338 24X Fiche: 50-277.84/02/15.8402290305
- --B402290307 Notice of violation from insp on 840116-20 # Region 1, Office of Director 84/02/15 8pp 22427 340 24X Fiche 50-277,84/02/15,8402290305
- --8402270317 IE Insp Repts 50-277/84-02 & 30-278/84-02 on 840116-20 Violation identified inadequate controls & training in util violation identified inadequate controls & training in util mod activities.

 EAPEN,P K Region 1, Office of Director GODY,A T Division Engineering & Technical Programs 84/02/13 8pp 22427 342 Fiche: 80-277,84/02/15,8402270305. Division of
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valva Torque Switches Set Below Menufacturer Recommended Value " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (fost 830103) 84/02/21 Consolidated Edison Co of New York Inc. 114pp. 22366.024 24X Fiche 50-000.84/02/21,8401190062
- 8402240138 Forwards supplementary info to 830520 ltr re environ qualification of safety-related electrical equipment per IE Bulletin 79-018 Attachments summarize actions leading to resolution of Franklin Research Ctr 820803 SER DALTROFF, 8 L Philadelphia Electric Co 84/02/21, BTOLZ, J. F Operating Reactors Branch 4, 49pp 22375, 119, 24X Fiche: 50-277, 84/02/21, 8402240138
- 8402280714 Notification of Bignificant Licenses Meeting 84-17 on 840302 w/util in Delta,PA to discuss SALP
 TRIPP,L E Region i, Office of Director. 84/02/22 Region i,
 Office of Director. ip. 22414:348 24X Fiche:50-277,84/02/22,
 8402280714
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies."

 Byc list encl

 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103), 84/02/24, Consolidated Edison Co. of New
 York, Inc. 115pp. 22430-304, 24X Fiche: 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
 Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103), 84/02/27, Consolidated Edison Co. of New
 York, Inc. 120pp. 22431.060 RAX Fiche.50-000,84/02/27,8401190067
- R Pariodic operating reports & related correspondence
- B402030432 Monthly operating rapts for Nov 1983 H/840105 ltr ALDEN, W M., CODNEY, M J Philadelphia Electric Co 83/11/ 22066: 268 24X Fiche, 50-277, 83/11/30, 8402030432 83/11/30. 3pp.
- 8402170143 Monthly operating repts for Jan 1984. W/840210 ltr ALDEN, W. M., ULLRICH, W. T. Philadelphia Electric Co. 84/01/31. 10pp. 22299: 012. 24X Fiche: 50-277, 84/01/31, 8402170143
- B. Reportable occurrences. LERs & related correspondence
- 8402240086 Further response to FOIA request for 16 categories of documents Item 9 limited, per 831005 telcon. Forwards Rev 7 to NUREC-0525 & App A documents. Portions of App B documents withheld (ref FOIA Exemption 4). App B documents also in PDR. FELTON, J. M. Division of Rules and Records 83/12/12 8HOLLY. Union of Concerned Scientists 4pp 22394. 150 24X Fiche: 50-000, 83/12/12, 8402240086.
- --8309070010 Telecopy Security Event Rept 83-7 re 830811 occurrence. FLEISCHMANN,R, Philadelphia Electric Co. 83/08/16. MURLEY,T.E. Region 1, Office of Director. 2pp. 22394:159. 24X Fiche: 50-000,83/12/12,8402240086

- 8402140260 LER 83-027/03L-0 on 831215, main steam line temp element TE-4913D found to read low Caused by temp elument out of duct w/retaining bracket bent & one mounting screw broken Temp element reinstalled COONEY.M J Philadelphia Electric Co 84/01/13 MURLEY. Region 1. Office of Director ip 22228 234 24X Fiche 50-277.84/01/13.8402140260 MURLEY, T. F.
- 8402040254 RO on 831128, from 830830-1128, seismic monitoring sys inoperable Caused by personnel oversight Startup check-off list modified to require maint request CODNEY, H J Philadelphia Electric Co 84/01/16 MURLEY, T E Region 1. Office of Director 2pp 22088 133 24X Fiche 50-277.84/01/16.8402060254
- 8402070263 LER 83-028/03L-0 on 831223, while performing surveillance testing, HPSW pump 2B declared inoperable due to low flow Caused by internal wear to valve disc pin & arm Parts replaced replaced COONEY, M J Philadelphia Electric Co 84/01/20 MURLEY, T E Region 1, Office of Director 1p 22102 211 24x Fiche 50-277,84/01/20,8402070263
- 8402230347 Updates status rept on BWR pipe cracks & protection of upcoming licensee actions Insp results encl Evaluation & recommandations re interim & long-term remedial measures expected by May 1984
 DIRCKS:W J Office of the Executive Director for Operations 9ECY-984-009A 84/01/27 5pp 22377 047. 24% Fiche 50-000.84/01/27,8402230347
- DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3 F Security, medical, emergency & fire protection plans
- 8402210279 Forwards drawing of cables for HPCI sys,per 830601 meeting proposal, in response to Generic Ltr 81-12 re alternative shutdown sys HPCI sys will be used for primary alternative shutdown Related info encl W/o drawing.

 MORLEY, Q M Philadelphia Electric Co 83/08/08, GEARS, Q NRC 8 Detailed Affiliation Given 13pp 22315 307, 24X Fiche 50-277,83/08/08,8402210279 NRC - No
- 8402080345 Forwards IE Insp Repts 50-277/83-36 & 50-278/83-34 on 831212-16. No violations noted MARTIN: T Division of Engineering & Technical Programs 84/01/25 DALTROFF: B L Philadelphia Electric Co 2pp 22130 253 24X Fiche. 50-277, 84/01/25, 8402080345
- --8402080348 IE Insp Repts 50-277/83-36 & 50-278/83-34 on 831212-16 No violations noted. Major areas inspected radiation protection program including in-plant radiation protection program implementation & high radiation area controls.

 GOLLING.D J Region 1, Office of Director 84/01/19 8pp 22130 255 24X Fiche 50-277,84/01/25,8402080345
- 8402070514 Forwards SER accepting licensee proposed design for alternate safe shutdown capability as compliance w/fire protection requirements of IOCFRSO App R. Items III. 0 3 & III L STOLZ, J. F Operating Reactors Branch 4 84/01/26 BAUER, E G Philadelphia Electric Co 2pp 22141 266 24X Fiche 50-277,84/01/26,8402070514
- ~~8402070515 SER accepting licenses proposed design for alternate safe shutdown capability as compliance w/fire protection requirements of 10CFR50. App R. Itams III 0 3 & III L
 ** NRC No Detailed Affilation Given 83/12/22 17pp.
 22141 268 24X Fiche. 50-277.84/01/26.8402070514
- 8402080391 Forwards IE Insp Repts 50-277/83-33 & 50-278/83-31 on 831128-1202. No violation noted MARTIN.T.T Division of Engineering & Technical Programs 84/01/26 DALTROFF, B L Philadelphia Electric Co 2pp. 22131 010 24X Fiche. 50-277, 84/01/26.8402080391.
- -8402080404 IE Insp Repts 50-277/83-33 & 50-278/83-31 on 831128-1202 No violation noted Major areas inspected followup of emergency preparedness items & prior public prompt notification insp rept. COMEN.I. Region 1: Office of Director. 84/01/20 14pp 22131 012 24X Fiche 50-277.84/01/26,8402080391
- B402030475 Requests response to NRC 830325 concerns re approved physical security plan Concerns relate to badge sys for newly assigned personnel & unescorted access STOLZ, U. F. Operating Reactors Branch 4. 84/01/30 BAUER.E Q Philadelphia Electric Co. ip 22066:015 24X Fiche 50-277, 84/01/30,8402030475

- 8402220364 Ack receipt of 840119 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/83-34 & 50-278/83-32
 - STARGSTECKI.R Division of Project & Resident Programs 84/02/09 DALTROFF, S. L. Philadelphia Electric Co. 1p 22335 302 24X Fiche 50-277,84/02/09.8402220364
- ~-8402220374 Responds to NRC 831222 ltr re violations noted in 1E Insp Repts 50-277/83-34 & 50-278/83-32 Corrective actions plant penetration seals upgraded to meet 10CFR50.App R requirements
 - requirements
 DALTROFF,S L Philadelphia Electric Co 64/01/19 STAROSTECKI,F
 Division of Project & Resident Programs 7pp 22335 303 24X
 Fiche 30-277,84/02/09,8402220364
- 8402210096 Forwards FEMA final exercise rept for 831116 joint exercises of state & local radiological emergency preparedness plans for TMI-1 due to Category A deficiencies noted in three
 - MARTIN.T T Division of Engineering & Technical Programs 84/02/10 DALTROFF.S L. Philadelphia Electric Co 3pp 22317 333 24X Fiche 50-000,84/02/10,8402210096
- 8402220034 Provides current status & projected completion date of continuing penetration seal program & proposed schedule for specific cable rerouting, per App R to 100RR50 BDYER, V S Philadelphia Electric Co 84/02/10 EISENHUT.D Q Division of Licensing App 22038 256 24% Fiche 50-277.84/02/10.840220034
- J Insurance & indemnity information
- 402210233 Forwards Endorsoment 4 to MAELU Certificates M-B & M-9 & NELIA Certificates N-B & N-9 W/o MAELU Certificate M-B & M-9 & NELIA Certificate N-9 BRADLEY.E J Philadelphia Electric Co B4/02/14 BALTZMAN.J Assistant Director for State & Licensee Relations 3pp 22314 330 24X Fiche 50-277.84/02/14.8402210233
- 3402210335 Forwards Endorsement 105 to NELIA Policy NF-140 & Endorsement 58 to HAELU Policy NF-67 BRADLEY.E J Philadelphia Electric Co 84/02/14 BALTZMAN.J Assistant Director for State & Liconsee Relations 3pp 22314 359 24X Fiche 50-277.84/02/14.8402210335
- P Operating license stage documents & correspondence
- 8402130223 "Rept of Plant Startup Following Fifth Refueling Outage, Feb 1983 " W/840131 ltr FLEISCHHANN, R Philadelphia Electric Co 83/02/14 MURLEY, T. E Region 1, Office of Director 5pp 22178 R12 24X Fiche 50-278.83/02/14.8402130223
 - I2130013 Responds to FOIA request for two categories of documents re DCOR program Forwards App A & B documents Documents placed IN PDR FELTON, J M Division of Rules and Records, 83/12/21 SHOLLY, 8 C. Union of Concerned Scientists 3pp 22282 004 24X Fiche 50-000, 83/12/21, 8402130013
- -8309260011 Summary of 830807-12 site visit & IBCOR meeting in Chicago, IL re status of data collection activity & containment capability
 BACCHI.O Equipment Qualification Branch FIN A-6493 83/09/12
 Equipment Qualification Branch 5pp 22282 203 24%
 Fiche 50-000,83/12/21,8402130013
- 402170518 Forwards Amends 91 & 93 to Licenses DPR-44 & DPR-56, respectively & safety evaluation Amends increase min number of required operable instrument channels for APRN & intermediate range monitor rod block trip sys GEARE, 9 Operating Reactors Branch 4 B4/02/10 BAUER, E. O Philadelphia Electric Co 20p 22305, 321 24X Fiche 50-277,84/02/10,8402170518
- -8402170324 Amends 91 & 93 to Licenses DPR-44 & DPR-56, respectively, increasing min number of required operable instrument channels for APRN & intermediate range monitor rod block trip sys from two to four & three to siz, respectively STOLZ.JF Uperating Reactors Branch 4 84/02/10 10pp. 22305 323 24X Fiche 90-277,84/02/10,8402170518
- -8402170526 Bafety evaluation supporting Amends 91 & 93 to Licenses BPR-44 & DPR-56 respectively * Office of Nuclear Reactor Regulation. Director 84/02/10 2pp 22305 333 24X Fichs 50-277,84/02/10,8402170518

- O Inspection reports. IE Bulletins & correspondence
- 8402020355 Forwards inservice insp rept for 830212-1024 Rept summarizes refueling outage exame COONEY, M J Philadelphia Electric Co 84/01/18 MURLEY, T E Region 1, Office of Director 1p 22052 125 24X Fithe 50-279,84/01/18
- --8402020361 Inservice insp rept for 830212-1024.summarizing refuelles outage exams
 * Philadelphia Electric Co 84/01/16 91pp 22052 126 24x
 Fiche 50-278,84/01/18,8402020355
- 8312120133 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Bvc list encl JCRDANLE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of No. York
- 8402080345 Forwards IE Insp Repts 80-277/83-36 & 50-278/83-34 gn 831212-16 No violations noted MARTIN.T Division of Engineering & Technical Programs 84/01/2 DALTROFF.8 L Philadelphia Electric Co 2pp 22130 253 R4X Fichs 50-277, 84-01/25.8 8402080345
- --B4020B0348 1E Insp Repts 50-277/83-36 & 50-278/83-34 on 831212-16 No violations noted Major areas inspected radiation protection program. including in-plant radiation protection program implementation & high radiation area controls COLLINS.D J., SHANBAKY.M M Region 1. Defice of Director. B4/01/17 Bpp 22130 255 24X Fiche 50-277,84/01/25,84020B0345
- 8402080391 Forwards IE Insp Repts 50-277/83-33 & 50-278/83-31 on 831128-1202 No violation noted MARTIN.T T Division of Engineering & Technical Programs 84/01/25 DALTROFF, 8 L. Philadelphia Electric Co 2pp 22131 010 24X Fichs 50-277.84/01/25,8402080391
- --8402080404 IE Insp Repts 50-277/83-33 & 50-278/83-31 on 83:120-1202 Metaletion noted. Major areas inspected followup of smergency preparedness items & prior public prompt notification insprept COHEN. I. HAWXHURBI.J., CROCKER.H W. Region i. Office of Director 84/01/20 14pp 22:131 012 24X Fiche 50-277,84/01/26. 8402080391.
- 8402140310 Forwards IE Insp Repts 50-277/83-35 & 50-278/83-33 on 831128-1202 No noncompliance noted MARTIN.T.T Division of Engineering & Technical Programs 84/02/01 DALTROFF, B L Philadelphia Electric Co 2pp. 22259 125 24x Fiche 50-277.84/02/01.8402140310.
- --8402160333 IE Insp Repts 50-277/83-35 & 50-278/83-33 on 831120-1202
 No violations noted Major areas inspected implementation &
 status of NUREG-0737 Items II B. 3, II. F i i-3 & JII. D. 3 3
 re post-accident effluent monitoring & sampling.
 WHITELJ R Region i, Office of Director HULL.A. KNOX.W
 Brookhaven National Laboratory. 84/01/25 22pp 22269.127 24:
 Fiche. 50-277, 84/02/01:8402160310
- B401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORBAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/03. Consolidated Edison Co of New York, Inc 117pp 22114:179, 24X Fiche:50-000,84/02/03,840119016
- 8401190017 IE Bulletin 84-01, "Gracks in BWR Mark I Containment Vent Headers " Svc list encl DEYDUNG:R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co. of New York, Inc 102pp. 22177:156. 24X Fiche.50-000,84/02/03,8401190017.
- 8402100432 Forwards request for add1 info re masonry wall design.pst IE Bullstin 80-i1. Structural & Gaotechnical Engineering Branch position on use of joint reinforcing in qualifying unreinforced masonry walls encl. STOL2.J.F. Operating Reactors Branch 4. 84/02/07, BAUER, E. & Philadelphia Electric Co 6pp 22219, 017. 24X Fiche: 50-277, 84/02/07, 8402100432.
- B402220364 Ack receipt of B40117 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/B3-34 & 50-278/B3-32 STAROBIECKI, R Division of Project & Resident Programs. B4/02/07 DALTROFF, B. L Philadelphia Electric Co. ip. 22335-302 24X Fichs, 50-277, 84/02/07, 8402220364

- --8402220374 Responds to NRC 831222 ltr re violations noted in IE Insp Repts 50-277/83-34 & 50-278/83-32 Corrective actions plant penetration seals upgraded to mest 10CFR50. App R requirements
 - Pericaments

 BALTROFF'S L. Philadelphia Electric Co 84/01/19 BTAROSTECKI, R

 Division of Project & Resident Programs 7pp 22335 303 24X

 Fiche 50-277, 84/02/09, 8402220364
- 8402240089 Forwards IE Insp Repts 50-277/83-32 & 50-278/83-30 on 831116-18 & notice of deviation MARTIN,T T Division of Engineering & Technical Programs 84/02/09 DALTROFF,B L Philadelphia Electric Co 2pp 22375 013 24X Fiche 50-277,84/02/09,8402240089
- --8402240091 Notice of deviation from inep on 831116-18 * Region 1. Office of Director 84/02/09 ip 22375 013 24X Fichs 50-277.041/cs 0402240089
- --8402240095 IE Insp Repts 50-277/83-32 & 50-278/83-30 on 831116-18 Deviation noted GA records program not implemented in full conformance w/ANSI N45, 2 9-1974 by June 1983 NAPUDA, 0 Region i, Defice of Director CAPHTON, D L Division U Engineering & Technical Programs. 83/12/30 6pp 22375 016 24 Fiche 50-277,84/02/09,8402240089.
- 8401190041 IE Info Natice 84-09, "Lessans Learned From NRC Insps of Fire Protection Bafe Shutdown Bys (10CFR30, App R)." Byc list encl
 - enti JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc. 124pp. 22365-259 24X Fiche 50-000,84/02/13,8401190041
- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection " &vc list encl JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/14 Consolidated Edison Co of New York, Inc 115pp 22365:141 24X Fiche 50-000,84/02/14,8401190039
- B401190045 IE Info Notice B3-63 Buppl 1, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/07/15 Consolidated Edison Co of New York, Inc. 118pp 22366, 142. 24X Fiche: 50-000: 84/02/15, 8401190045
- 8402270305 Forwards IE Insp Repts 50-277/84-02 & 50-278/84-02 on

 840116-20 & notice of violation.

 MARTIN.J S Division of Engineering & Technical Programs 84/02/15

 DALTROFF,8.L Philadelphia Electric Co 2pp 22427 338 24X

 Fiche: 50-277.84/02/15,8402290305.
- --8402270309 Notice of violation from inap on 840116-20 * Region I. Office of Director 84/02/15 8pp 22427 340 24% Fiche: 50-277.84/02/15, 84022/9305
- --8402290317 IE Insp Repts 50-277/84-02 & 50-278/84-02 on 840116-20, Violation identified inadequate controls & training in util mod activities EAPENP, K. Region 1, Office of Director GODY, A T Division of Engineering & Technical Programs 84/02/13 Spp 22427-342 24 Fichs, 50-277, 84/02/15, 8402290305.
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value." Evc list encl. JCRDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc. 116pp. 22366-024, 24X Fiche 50-000,84/02/21,8401190062.
- 8402240138 Forwards supplementary info to 830520 ltm re environ qualification of safety-related electrical equipment per IE Bulletin 79-018 Attachments summarize actions leading to resolution of Franklin Research Ctr 820803 SER DALTROFF, S. L. Philadelphia Electric Co. 84/02/21. 8TOLZ, J. F. Operating Reactors Branch 4 49pp 22375.119, 24X Fiche: 50-277,84/02/21,8402240138.
- 8402280714 Notification of Bignificant Licensee Meeting 84-19 on 840302 w/util in Delta.PA to discuss BALP
 TRIPPL E Region 1, Office of Director. 84/02/22 Region 1, Office of Director. ip. 22414.348. 24X Fiche: 50-277, 84/02/22. 8402280714.
- 8401170066 IE Info Notica 84-11, "Training Program Deficiencies " Svc list encl. JORDAN,E.L., Division of Emergency Praparedness & Engineering Response (Post 830103) 84/02/24, Consolidated Edison Co of New York, Inc 115pp 22430.304 RAX Fiche 50-000.84/02/24.8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Beat Valve Saals."
 Svc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/27 Consolidated Edison Co. of New
 York, Inc. 120pp. 22431.060, 24X Fiche: 50-000, 84/02/27, 8401190067

- R Periodic operating reports & related correspondence
- 8402030432 Monthly operating repts for Nov 1983 W/840105 ltr ALDEN,W M . CUDMEY,M J Philadelphia Electric Co 83/11/30 3pp 22066 268 24X Fiche 50-277.83/11/30.8402030432
- 8402170143 Monthly operating repts for Jan 1984 W/840210 ltr ALDEN,W M , ULLRICH.W T Philadelphia Electric Co 84/01/31 10pp 22299 012 24X Fiche 80-277.84/01/31,8402170143
- S Reportable occurrences, LERs & related correspondence
- B402240086 Further response to FDIA request for 16 categories of documents Item 9 limited, per 831005 telcon Forwards Rev 7 to NUREQ-0525 & App A documents Portions of App B documents withheld (ref FDIA Exemption 4) App B documents also in PDR FELTON, J N Division of Rules and Records 83/12/12 SHOLLY, S C Union of Concerned Scientists 4pp 22374 190 24X Fiche 50-000.83/12/12,8402240086
- --8309070010 Telecopy Security Event Rept 83-7 re 830811 occurrence FLEISCHMANN.R Philadelphia Electric Co 63/08/16 MURLEY, T & Region 1. Office of Director 2pp 22394 159 24X Fichs 50-000, 83/12/12, 8402240086
- 8402060113 LER 83-020/03L-0 on 831123 discovered RCIC turbine steam supply low pressure isolation switch out of calibr Caused by setpoint drift Instrument recalibr & returned to syc COONEY, M J Philadelphia Electric Co 83/12/23 MURLEY, T E Region 1. Office of Director 1p 22089 137 24X Fiche 50-276,83/12/23,8402060113
- 8402070325 LER 83-023/03L-0 on 831213, while performing routine surveillance test, torus narrow-range level indicator found out of calibr Level indicator replaced, calibr & returned to svc on 831216
 COOMEY, M J Philadelphia Electric Co 84/01/12 MURLEY, T E Region 1, Office of Director 1p 22096 328 24X
 Fiche 50-278, 84/01/12, 8402070325
- B402140321 LER 93-022/03L-0 on B31207.4 kV emergency bus undervoltage relay IVA-127 failed to operate Caused by binding of relay rotating disk due to dust buildup Relays cleaned tested & returned to swc COUNEY, M J Philadelphia Electric Co 84/01/13 MURLEY, T E Region 1. Office of Director 1p 22227 171 24% Fiche 50-278.84/01/13.8402140321
- 8402060254 RO. on 831128, from 830830-1128, seismic monitoring sys inoperable Caused by personnel pyersight Startup check-off list modified to require maint request COONEY, M J Philadelphia Electric Co. 84/01/16. MURLEY, T E. Region 1. Office of Director 2pp 22088 133 24X Fiche, 50-277, 84/01/16. 8402060254
- B40B030438 LER 83-0R4/O3L-0 on B31219, moisture sensor in maisture monitoring sys failed Caused by defective Techmark Limited sensor Inoperable sensor will be replaced during next scheduled or forced outage COONEY, M J Philadelphia Electric Co 84/O1/18 MURLEY, T E Ragion i, Office of Director 1p 22069 030 24X Fiche, 50-278, 84/O1/18, 8402030438.
- 8402230347 Updates status rept on BWR pipe cracks & protection of upcoming licenses actions Insp results encl. Evaluation & recommendations re interim & long-term remedial measures expected by May 1984
 DIRCKB.W. J Diffice of the Executive Director for Operations SECY-84-009A 84/01/27. 5pp. 22377 047 24% Fiche.50-000.84/01/27.840230347
- DOCKET 50-280 BURRY POWER STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8402010445 Forwards Amends 93 & 92 to Licenses DPR-32 & DPR-37, respectively & safety evaluation Amends revise Tech Specs to reflect changes in upgrading & installation of fire protection sys NEIGHBORB, J D Operating Reactors Branch i 84/01/17 STEWART, W L Virginia Electic & Power Co 3pp 22061:138 24X Fiche:50-280,84/01/17,8402010445
- --8402010449 Amends 93 & 92 to Licenses DPR-32 & DPR-37, respectively, revising Tech Space to reflect changes in upgrading & installation of fire protection sys.
 VAR0A, B A Operating Reactors Branch i 84/01/17 2ipp, 22061.161. 24X Fiche, 50-280, 84/01/17, 8402010445

- -8402010455 Safety avaiuation supporting Amends 93 & 92 to Licenses PPR-32 & DPR-37. respectively * Office of Nuclear Reactor Regulation, Director 84/01/17 3pp 22061 182 24% Fiche 50-280.84/01/17.8402010445
- 6402090055 Requests add1 info to conduct detailed review of plant-specific technical guidelines portion of procedures generation package (PGF) Add1 info should be provided as rev to PGP per Suppl 1 to NUREO-0737 VAROA: S A Operating Reactors Branch I 84/01/25 STEMART. H L Virginia Electric & Power Co 4pp 22189 170 24X Fiche 50-000.84/01/25.8402070055
- 8402240010 Forwards amended pages to physical security plan PAges withheld (ref 10CFR73 21) STEWART.W L. Virginia Electric & Power Co 84/01/30 MCGUIRE. Division of Emergency Preparedness & Materials Safety 1p 22375 309 24x Fiche 50-280.84/01/30.8402240010 84/01/30 MCGUIRE, D.R.
- 8402070382 Forwards comparison study to evaluate facility design basis compliance to Reg Guide 1 97.per NUREG-0737. Suppl 1 Mads identified in encl will be completed by end of second refueling after Jul 1985 for each unit STEMART. W i. Virginia Electric & Power Co 84/01/31 DENTON. H R Office of Nuclear Reactor Regulation, Director. EISENHUT. D & Division of Licensing 47pp 22095 201 24x Fichs 50-280.84/01/31, 8402070382
- 6402100203 Rev 10 to Emergency Plan Implementing Procedure EPIP-1 01 W/140206 1tr W/140206 1tr WILSON, J , DEHANDEL, E P Vinginia Electric & Power Co 7pp 22178 017 24% Fiche 50-280, 84/02/02, 8402100203 B4/02/02
- 402240032 Rev 10 to Emergency Plan Implementing Procedure EPIP-1 01, "Emergency Manager Controlling Procedure " W/840217 ltr WILSON, J. STEWART, W.L. Virginia Electric & Power Co. 84/02/02 O'REILLY, J.P. Region 2, Office of Director Spp. 22375 256 24X Fiche 50-280.86/02/02.8402240032
- 3402160631 Advises that NRC will not review emergency plans to delete privacy or proprietary into unless specifically requested by licenses, per 810709 Generic Ltr 81-27 W/o requestienting plan will be placed in PDR NEIOHBORS, J D. Operating Reactors Branch 1 84/02/06 STEWART, W L. Virginia Electric & Power Co. 2pp. 22301 358 24X Fiche 50-280.84/02/06.8402160631 BYEWART, U.L.
- 8402170511 Forwards results of 830919-23 safeguards regulatory affectiveness review Comments requested by 840214 Encl effectiveness review Comments requested by 840214 Encl withheld THOMAS.C O Standardization & Special Projects Branch. 84/02/07 PARR.O D Auxiliary Systems Branch ITEMANN.D L Procedures & Systems Review Branch ip 22312.359 24X Fiche: 50-280, 84/02/07, 8402170511
- 02080169 Forwards "Bafety Parameter Display Bys SAR for MUREQ-0696 Computer Project North Anna & Surry Nuclear Power Stations."
 per 830415 response to NUREQ-0737. Buppl 1
 STEHART.N L. Virginia Electric & Power Co 84/02/08 DENTEN.H R
 Office of Nuclear Reactor Regulation. Director EIEENHUT.D Q
 Division of Licensing 2pp 22134 247 24X Fiche: 50-000, 84/02/08. Division of Licensing 2pp 8402080169
- -8402080181 "Safety Parameter Display Sys SAR for NUREG-0696 Computer Project North Anna & Surry Nuclear Power Stations " * Energy: Inc SAR-VEPCO-003 84/01/20 225pp 22134 249 24X Fiche 50-000, 84/02/08, 8402080169
- 402280419 Ack receipt of 840127 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/83-30 & 50-281/83-31
- 50-281/0-31 LEMIB.R C. Division of Project & Resident Programs STEWART.W L. Virginia Electric & Fower Co. ip. 2: Fiche.50-280,84/02/09.8402280419 22404: 245
- -9402280449 IE Insp Repts 50-280/83-30 & 50-281/83-31 on 830906-1007, Violation noted syc water valve pit flood control panel alarm ampunciated in control room.but no focumentation or response to alarm apparent
 BURKE.D J. DAVIS.H J. Region 2, Office of Director ELROD.8 A Division of Project & Resident Programs, 83/12/20 App 22404 275 24X Fiche 50-280.84/02/09,8402280419
 - 3280503 Confirms 840223 meeting at Ragion II ofc to discuss security ograms at facilities.per 840207 telcon HIB-R C Division of Project & Resident Programs. 84/02/22 EMART.W L. Virginia Electric & Power Co. 1p 22407:100. 24X che-50-000-84/02/22.8402280503

- 8402280453 Requests NRC review & approve use of installed reactor vessel level instrumentation sys.per requirements of Generic Ltr 82-33. Buppl 1 to NUREQ-0737 & TMI II F 2 STEMART.W L Virginia Electric & Power Co 84/02/23 DENTON,N & Office of Nuclear Reactor Regulation, Director EIBENHUT,D Q Division of Licensing App 22407 053 24X Fiche 50-280.84/02/23. 8402280453
- 8402280287 Ack receipt of 840130 transmittal of amended pages to 831003 ltr forwarding 830915 rev to physical security plan Amended pages consistent w/provisions of 10CFR50 54(p) & acceptable. LEHIS,R C Division of Project & Resident Programs 84/02/24 STEMART.W L Virginia Electric & Power Co 2pp 22399 074 24% Fiche 50-280,84/02/24,8402280287
- J Insurance & indomnity information
- 8402060246 Endorsement 48 to NELIA Policy NF-240 & Endorsement 37 MAELU Policy NF-96 # Virginia Electric & Power Co 84/01/13 2pp 22087,201 2&X Fiche. 50-000. 84/01/13. 8402060246
- P Operating license stage documents & correspondence
- 840R130013 Responds to FOIA request for two categories of documents ra 1DCOR program Forwards App A & B documents Documents placed in PDR FELTON, J. N Division of Rules and Records B3/12/21 SHDLLY, B C Union of Concerned Scientists 5pp 22282 004 24X Fiche 50-000,83/12/21,8402130013
- --8309260011 Summary of 830807-12 site visit & IDCOR meeting in Chicago.
 IL re status of data collection activity & containment capability
 BACCHI.0 Equipment Qualification Branch FIN A-6495, 83/09/12
 Equipment Qualification Branch 5pp 22282, 203 24X
 Fiche 50-000, 83/12/21, 8402130013
- 8402010093 Forwards Amends 91 & 92 to Licenses DFR-31 & DPR-32, respectively & safety evaluation Amends add new limiting conditions for operation & surveillance requirements which address filter & bottled air sys for main control room NEIOH9DRB. J D Operating Reactors Branch 1 84/01/17, 87EW Virginia Electric & Power Co. 3pp 22058 062 24x Fiche: 50-280,84/01/17,8402010093 84/01/17. STEHART-H L
- ---8402010099 Amends 91 & 92 to Licenses DPR-37 & DPR-32, respectively, adding new limiting conditions for operation & surveillance requirements which address filter & bottled air sys for main 84/01/17 30pp
- --B402010102 Sagaty evaluation supporting Amends 91 % 92 to Licenses BPR-37 % DPR-32, respectively e Office of Nuclear Reactor Regulation, Director 84/01/17, 12pp 22058 095 24X Fiche 50-280,84/01/17,8402010093.
- 8402010247 Forwards SER re NUREO-0737, Item II F. 2 & Generic Ltr B2-26. "Inadequate Core Cooling Bys " Addl info requested to complete review of 830512 submittal Generic Hastinghouse approach acceptable.

 VARQA-S, A Operating Reactors Branch 1 84/01/17. SYEMARY, W L Virginia Electric & Power Co 12pp. 22047.297. 24X Fichs. 50-280, 84/01/17, 8402010247
- 8402010445 Forwards Amenda 93 & 92 to Licenses DPR-32 & DPR-37, respectively & safety evaluation Amenda revise Tech Specs to reflect changes in upgrading & installation of fire protection sys.

 NEICHBORS J. D. Operating Reactors Branch 1. 84/01/17 STEM Virginia Electric & Power Co Spp 22061,158 Fiche 50-280,84/01/17,8402010445.
- --B402010449 Amends 93 & 92 to Licenses DPR-32 & DPR-37, respectively, revising Tech Specs to reflect changes in upgrading & installation of fire protection sys VAR94.B A Deparating Reactors Branch 1 84/01/17, Pipp. 22061 161 24X Fiche: 50-280,84/01/17,8402010445
- --8402010455 Safety evaluation supporting Amends 93 & 92 to Licenses DPR-32 & DPR-37. respectively. * Office of Nuclear Reactor Regulation, Director, 84/01/17. 3 22061,182. 24X Fiche 50-280,84/01/17,8402010445. Director, 84/01/17. 31#
- 8402090409 Forwards SER & notice of granting of relief from ABME Section XI inservice testing/insp requirements VAROA.B A Operating Reactors Branch i 84/01/24, STEWART.W L Virgina Electric & Power Co 2pp 22191-263 24X Fichs. 50-280.84/01/24.8402090409.

- --8402090422 Notice of granting of relief from ASME Section XI inservice insp/testing requirements VAROA.8 A Operating Reactors Branch i 84/01/24 2pp 22191 245 24X Fiche 50-280.84/01/24.8402090409
- --B402090431 Bafety evaluation re util 820921 requests for relief from inservice insp requirements
 e Operating Reactors Branch 1 84/01/24 42pp 22191 267 24X Fichs 50-280,84/01/24,8402090409
- 8402080503 Forwards Amends 94 & 93 to Licenses DPR-32 & DPR-37, respectively & safety evaluation Amends revise Tech Specs to remove eight snubbers from auxiliary feedwater sys & emergency diesel generator exhaust piping from Table 4 17-1 NEIGHBORS. J D Operating Reactors Branch 1 84/01/31 STEW Virginia Electric & Power Co 2pp 22174 068 24X Fiche 50-280.84/01/31.8402080503 STEWART W L
- --8402080506 Amends 94 & 93 to Licenses DPR-32 & DPR-37, respectively, revising Tech Specs to remove eight snubbers from auxiliary feedwater sys & emergency diesel generator exhaust piping from Table 4, 17-1.
 VAROA: B.A. Operating Reactors Branch 1 84/01/31 5pp 22174:070. 24X Fiche: 50-280,84/01/31,8402080503
- --8402080507 Bafety evaluation supporting Amends 94 & 93 to Licenses DPR-32 & DPR-37, respectively. * Office of Nuclear Reactor Regulation, Director 84/01/31 2pp 22174-079 24X Fichs 30-280.84/01/31,8402080503
- 8402010410 Demaric Ltr 84-04 to all operating PWR licensees.CP holders & applicants for CFs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops 8vc list encl.
 EISENHUT,D 9 Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc. 57pp 22177 087 24X
 Fiche: 50-000,84/02/01,8402010410
- 8402140383 Ack receipt of Ti. Wedgewood 831230 ltr Forwards payment of assessed penalty for discharge of oil into cooling water discharge canel.

 TAYLOR, J. A. Virginia Electric & Power Co. 84/02/02 U.S. Coast Quard, Transportation, Dept. of, 3pp. 22220.052, 24X

 Fiche. 50-280,84/02/02,8402140383
- B402100183 Forwards info re frequency of calibr, testing & training of operators for post-accident sampling sys.per 831216 BBER identifying open items in TMI Item II B 3 SEEWART.W L. Virginia Electric & Fower Co. 84/02/03 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. EISENHUT, D.O. Division of Licensing 4pp. 22182-184. 24X Fiche-50-000:84/02/03.8402100183.
- 8402130351 Forwards revised Tech Spec Page 6 6-12 re radioactive effluents per 840111 proposed change to radiological effluent Tech Specs Page 4.9-6 withdrawn from suppl STEWART.M. L. Virginia Electric Flower Co. 84/02/03 DENTON, Office of Nuclear Reactor Regulation, Director, VARGA, 8 A Operating Reactors Branch 1. 1p 22197:283, 24x Fiche: 50-280, 84/02/03, 8402130351
- ---B402130356 Revised Tech Spec Page 6 6-12 to 840111 proposed change to radiological effluent Tech Specs * Virginia Electric & Power Co 84/02/03. 1p. 22197 284 24X Fiche: 50-280, 84/02/03, 8402130351
- 8402150020 Suppl 1 to application for amend to Licenses DPR-32 & DPR-37, adding description of post-accident sampling program to Section 6 re administrative controls in fullfillment of requirements of NURSE-0737, Items II.F. 12 & II.B. 3. ETEMART, M.L. Virginia Electric & Power Co 84/02/09 DENTON, H.R. Opfice of Nuclear Reactor Regulation, Director. VAROA, S.A. Operating Reactors Branch 1. 3pp. 22249, 310, 24X Fiche, 50-280, 84/02/09, 8402150020
- --8402180022 Proposed Tech Spec change adding description of post-accident sampling program to Section 6 re administrative controls, in fullfillment of requirements of NUREG-0737, Items II. F. 12 II. 8, 3, 8 Virginia Electric & Power Co. 84/02/09, 4pp. 22249:313 24X Fichs: 50-280, 84/02/09, 8402150020.
- 8402160649 Forwards request for add1 info on NUREG-0737. Item II. D. 1. "Performance Testing of Relief & Safety Volves." Response within 60 days requested VARGA, S. A. Operating Reactors Branch 1. 84/02/09, STEWART. W L Virginia Electric & Power Co. Spp. 22302:007. 24X Fiche. 50-280, 84/02/09, 8402160649.

- 8402230143 Supplemental application for amend to Licenses DPR-32 & DPR-37, adding limiting conditions for operation & surveillance requirements for main control chlorine detection sys, per NUREQ-0737, Item III D 3 4
 STEMART.W L. Virginia Electric & Power Co 84/02/14 DENTON, H Office of Nuclear Reactor Regulation, Director VARGA, S A Operating Reactors Branch i 2pp 22361 033 24x
 Fiche 50-280,84/02/14,8402230143 DENTON, H. R.
- 8402280214 Reaffirms schedule for implementation of all Reg Guide 1 97 items by second refueling outage in Jul 1985 List of items, excluding in-core thermocouples requiring addl work to achieve compliance encl BTEWART, W. L. Virginia Electric & Power Co. 84/02/21 DENTON, H.R. Office of Nuclear Reactor Regulation, Director EISENHUT, D.Q. Division of Licensing 7pp 22400 185 24% Fiche 50-000,84/02/21, Division of Licensing 8402280214
- 8402280517 Suppls 840214 application for amend to Licenses DPR-32 & DPR-37 re control room chlorine detection sys per NVREO-0737. Item III D 3.4 Encl attachments inadvertently omitted from previous submittal STEWART, W L Virginia Electric & Power Co 84/02/21 DENTON, H R. Office of Nuclear Reactor Regulation, Director VAROA, 8 A Operating Reactors Branch 1 1p 22406 338 24X Fiche 50-280.84/02/21.8402280517
- ---8402280525 Proposed changes to Tech Specs re control room chlorine detection sys per TMI Item III D 3 4

 * Virginia Electric & Power Co 84/02/21 8pp 22406 339 24X
 Fiche 50-280,84/02/21,8402280517
- 8402280740 Advises that fee will be refunded, per 10CFR170 11(b), for second Class I duplicate fee for 830825 application re Tech Spec change to remove certain shubbers
 MILLER, W. O. License Fee Management Branch 84/02/21 STEHART, W. L. Virginia Electric & Power Co. ip 22414 342 24X
 Fiche: 50-280,84/02/21,8402280740
- G Inspection reports: IE Bulletins & correspondence
- 8402090409 Forwards SER & notice of granting of relief from ASME Bection XI inservice testing/insp requirements. VAROA.S A Operating Reactors Branch 1. 84/01/24 STEWART.W L Virginia Electric & Power Co 2pp 22191.263 24X Fiche 50-280.84/01/24.8402090409
- --B402070422 Notice of granting of relief from ABME Section XI inservice insp/testing requirements VARQA: 8 A Operating Reactors Branch i B4/01/24. 2pp. 22171 265 24X Fiche 30-280,84/01/24.8402090409
- --B402090431 Bafety evaluation re util 820921 requests for relief from inservice insp requirements * Operating Reactors Branch 1. 84/01/24. 42pp 22191.247 24X Fichs: 50-280.84/01/24.8402090409
- 8312120153 IE Info Notice 84-06. "Steam Binding of Auxiliary Feedwater JIZIZO153 IE Info Notice 84-05, "Steam Binging or Auxiliary resonancer Pumps " Svc list encl. JOBBAN E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc. 120pp 22088.001 24X Fichs 50-000.84/01/28,8312120153
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl, JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 803003) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche, 30-000, 84/02/03, 8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers." Svc list encl.
 DEYDUNG, R C Director's Office, Office of Inspection and
 Enforcement 84/02/03 Consolidated Edison Co. of New York, Inc
 102pp. 22177:106 24X Fiche 50-000,84/02/03,8401190017.
- 8402280419 Ack receipt of 840127 ltr informing NRC of staps taken to correct violations noted in IE Insp Repts 50-280/83-30 & 50-281/83-31 LEWIS,R C. Division of Project & Resident Programs. 84/02/ STEMART, W L. Virginia Electric & Power Co ip 22404*265 Fiche. 50-280: 84/02/09: 8402280419
- --B4022B0426 Responds to NRC B31229 ltr re violations noted in IE Insp Repts 30-280/83-30 & 50-281/83-31 Corrective actions importance of signtness to conditions adverse to quality stressed to operators. BTEMART, W. L. Virginia Electric & Power Co. B4/01/27 G'REILLY, J. P. Region 2, Office of Director. 5pp. 22404 266 24X Fiche, 50-280, 84/02/07, 8402280417

- -8402280434 Forwards IE Insp Repts 50-280/83-30 & 50-281/83-31 on 830906-1007 & motice of violation LEMIS.R C Division of Project & Resident Programs 83/12/29 STEMART.W L Virgina Electric & Power Co 2pp 22404 271 Fiche 50-280,84/02/09.8402280419
- -8402280438 Notice of violation from insp on 830906-1007 * Region 2, Office of Director 83/12/29 2pp 22 Fiche 50-280,84/02/09,8402280419 22404 273 24X
- --8402280449 IE Insp Repts 50-280/83-30 & 50-281/83-31 on 830706-1007 Violation noted svc water valve pit flood control panel alarm annunciated in control room, but no documentation or response to alorm apparent BURKE, D.J., DAVIS, M.J. Region 2, Office of Director E. Division of Project & Resident Programs BEJ/12/20 6pg 22404 275 24X Fiche 50-280,84/02/09,8402280419 ELRODIS A
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Inspa of Fire Protection Safe Shutdown Sys (100FR50.App R)" Syc list encl
 - onci JGRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc. 124pp 22345 259 24X Fiche 50-000.84/02/13.8401190041
- 8401190039 IE Info Notice 84-08. "10CFR80 7. 'Employee Protection '" Syc list enci JORDAN, E. L. Bivision of Emergency Preparedness & Engineering Response (Post 830103) 84/02/14 Consolidated Edison Co. of New York, Inc. 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- 8401170045 IE Info Notice 83-63 Suppl 1. "Potential Failures of Hestinghouse Type 5A-! Differential Relays " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 430103) 84/02/15 Consolidated Edison Co of New York. Inc 118pp 22366 142 24X Fiche 50-000.84/02/15,8401170045
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Delaw Manufacturer Recommended Value " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000,84/02/21,8401190062
- 1402280499 Ack receipt of 840120 ltr informing NRC of steps taken to correct violations noted in IE Imap Repts 50-280/83-34 & 50-281/83-36 50-28/783-36 LEWIB.R. C Division of Project & Resident Programs 84/02/21 STEWART.W.L Virginia Electric & Power Co 1p 22407 033 (Fiche.50-280:84/02/21,8402280499
- --8402280505 Responds to NRC 831221 ltr re violations noted in IE Insp Repts 50-280/83-34 & 50-281/83-36 Corrective actions: radiation work permits revised to provide addl precautions & guidance on evaluation of nonuniform radiation fields STEMART.W L Virginia Electric & Power Co 84/01/20. O'REILLY, JP Region 2. Office of Director 4pp 22407 034 24 Fichs 50-280,84/02/21,8402280499 22407 034 24X
- --8402280511 Forwards IE Insp Repts 50-280/83-34 & 50-281/83-36 on 831031-1104 & natices of violation & deviation LEWIS:R C Division of Project & Resident Programs 83/12/21 8TEWART:W L Virginia Ejectric & Power Co 2pp 22407 038 Fiche 50-280,84/02/21,8402280499
 - 402280518 Notice of violation from insp on 831031-1104 * Region 2, Office of Director 83/12/21 1p 22407.040 24X Fiche 50-280.84/02/21.8402280499
 - 402280522 Notice of deviation from insp on 831031-1104. * Region 2, Office of Director 83/12/21 ip 22407 041 Fiche: 50-280,84/02/21,8402280497
- -8402280529 IE Insp Repts 50-280/83-34 & 50-281/83-36 on 831031-1104 Violation noted failure to provide appropriate personnel monitoring equipment Deviation noted failure to modify procedure re use of sealed sources HOSEY.C.M. Region 2. Office of Director BARR.K.P. Division of Engineering & Operational Programs 83/12/13 Epp 22407 042 24% Fische 50-280,84/02/21,6402280499
- 8401190066 IE Info Notice 84-11. "Training Program Deficiencies "
 - #01190066 IL JAPA NOVICE C. ... Byc list encl JORDAN,E L. Division of Emergancy Preparedness & Engineering Response (Post 830103). 84/02/24 Consolidated Edison Co of New York, Inc. 115pp 22430 304 24X Fiche 50-000, B4/02/24, B401190066
- 8401190067 IE Info Notice 84-12, "Failure of Boft Seat Valve Seals " Stylist encl
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc. 120pp 22431 040 24% Fiche 30-000,84/02/27,8401190047

- S Reportable occurrences, LERs & related correspondence
- B402090136 FDIA request for documents re 831015 accident at facility killing control room operator WC Jones GARDE.9 P. STEINKOEN19.K. Government Accountability Project 83/11/04 FELTON.J M. Division of Rules and Records 2pp 22188 195 24% Fiche 50~280,83/11/04,8402090136
- B402100447 Responds to FOIA request for documents re NRC investigation of burst steam pipe accident Forwards documents Mat1 also available in PDR 63/11/30 (24X 204 24X FELTON, J M Division of Rules and Records #3/11/
 Government Accountability Project ip 22212 304
 Fiche 50-280, 83/11/30, 8402100447
- --B402100449 Headquarters operations officer log from B31015-16 re faisl injury due to high pressure feedwater drainline rupture * NRC No Detailed Affiliation Given B3210115 3pp 22212 305 24X Fiche 50-280,83/11/30,8402100447
- 8402220154 Responds to FOIA request that 146 LERs be placed in FDR Forwards LERs listed on app Documents also available in FDR Remaining LERs were either canceled or not issued FELTON.J M. Division of Rules and Records 83/11/30 JEFFERSON.G A Affiliation Not Assigned 2pp 22380 052 24X Fiche 50-000,83/11/30,8402220154
- --B402220165 LER 82-094/03L-O on B20815, reactor coolant hot leg semple trip valves TV-SS-106A & B failed to close after chemists completed taking RCS sample Cause not determined Manual isolation valve 1-85-116 closed W/B20914 ltr.
 WILSON.J L Virginia Electric & Power Co 82/09/14
 O'REILLY, J P Region 2, Office of Director 3pp 22380 ii6 245 Fiche 50-000, 83/11/30, 8402220154 22380 116 240
- B402090143 Responds to FDIA request for documents re NRC investigation of industrial accident involving burst steam pipe at facility Forwards App A documents. Documents also available an Pur FELTON, J.M. Division of Rules and Records 83/12/12 GARDE, A.P. Government Accountability Project 3pp 22188 197 24X Fiche 50-280,83/12/12,8402090143
- --8402090152 Informs of B31015 fatal accident involving HC Jones
 Expansion joint ruptured during high pressure drain pump
 valve operation
 WILBON,J L Virginia Electric & Power Co 83/10/17 Virginia
 Electric & Power Co 1p 22188-200 24X Fiche-50-280, 83/12/12-840-2014
- 8402070363 Part 21 rept re linear converter device w/possible generic defect Initially reported on 840116 Written notifications issued. Customer responses should be received by 840331 Final rept will be submitted by 840430 DOBSON. J.P. Pacific Air Products Co 84/01/30 Director's Office, Office of Inspection and Enforcement 2pp 22114 279 24: Fiche: 50-000, 84/01/30, 8402070365
- --8402070373 Part 21 rept re linear converter device w/possible generic defect Initially reported on 840116 Preliminary analysis indicates excessive wear of brass shaft guides. Next rept will be submitted within 90 days Supporting info encl DDDSON, J P Pacific Air Products Co 84/01/17 POTAPOVS, U. Regison 4, Office of Director 48pp. 22114 301. 24X Fiche 50-000, 84/01/30, 8402070365
- 8402140236 NPDES noncompliance notification on 840201, discovered that chlorine gas feed sys failed to supply chlorine to effluent Caused by false rate meter reading due to water pressure. Hypochlorite addition method substituted TAYLOR, J. A. Virginia Electric & Power Co. 84/02/03 JENKINS, R. Virginia. Commonwealth of. . 1p. 22230-300 24X Fiche 50-280, 84/02/03, 8402140236
- 8403140401 LER 84-001-00 on 840106, overtemp delta-T signal tripped reactor Caused by power surge during Gaitronics sys maint Gaitronics sys test will be written & performed & results will be used to develop procedure W/840203 ltr WILSON, J L Virginia Electric & Power Co 84/02/03 4pp 22220.346 24X Fiche 50-280,84/02/03,8402140401
- B402210095 NPDES noncompliance notification updates status of chlorination sys at sewage treatment plant. Malfunctioning gas feed sys reported in B40201 ltr returned to operation on B40203 B40203 TAYLDR,J A Virginia Electric & Power Co B4/02/09 JENKINB,R ft Virginia, Commonweelth of, ip 22317 233, 24X Fiche 50-280,84/02/09,8402210095

- g402220208 RD SPR-84-1 on 840106, specific activity sample of reactor coolant showed peak dose equivalent I-131 level exceeded Tech Spec limits Caused by known fuel element defects in core Tech Spec requirements implemented MILSON, J L Virginia Electric & Power Co 84/02/13 O'REILLY, J P Region 2, Office of Director 2pp 22339 227 24X Fiche 50-280,84/02/13,8402220208
- g402220435 LER 84-002-00 on 840118, control room indications & annunciators behaved erratically due to voltage spike Gaused by cable falling out of breaker due to loose screw Gable reconnected W/840213 ltr
 HILSON, J L Virginia Electric & Power Co 84/02/13 D'REILLY, J P Region 2, Office of Director 4pp 22340 153 24X
 Fiche 50-280,84/02/13,8402220435
- DOCKET 50-281 SURRY POWER STATION, UNIT 2
- F Becurity, medical, emergency & fire protection plans
- g402010445 Forwards Amends 93 & 92 to Licenses DPR-32 & DPR-37, respectively & safety evaluation Amends revise Tech Specs to reflect changes in upgrading & installation of fire protection sys
 NEIOHORS, J D Operating Reactors Branch 1 84/01/17 STEWART, W. L. Virginia Electric & Power Co 3pp 22061:158 24X
 Fiche: 50-280,84/01/17,8402010445
- --8402010449 Amends 93 & 92 to Licenses DPR-32 & DPR-37, respectively, revising Tech Specs to reflect changes in upgrading & installation of fire protection sys WARGA.S.A. Operating Reactors Branch 1 84/01/17. 2ipp 22061 161 24X Fiche 50-280,84/01/17,8402010445
- --8402010455 Safety evaluation supporting Amends 93 & 92 to Licenses DPR-32 & DPR-37.respectively * Office of Nuclear Reactor Regulation, Director 84/01/17 3pp 22061 182 24% Fiche: 50-280.84/01/17.8402010445
- 3402070055 Requests addl info to conduct detailed review of plantspecific technical guidelines portion of procedures generation package (PGP) Addl info should be provided as rev to POP ger Suppl i to NUREO-0737 VARGA. B. A Operating Reactors Branch i 84/01/25 STEWART, W. L Virginia Electric & Power Co 4pp 22187 170 24X Fiche: 50-000,84/01/25,8402070055
- 1402240010 Forwards amended pages to physical security plan Pages withheld (ref 100FR73 21)
 STEWART.W L Virginia Electric & Power Co. 84/01/30 MCOUIRE, D R Division of Emergency Preparadness & Materials Safety 22375:309 24X Fiche 50-280, 84/01/30, 8402240010
- I-402070382 Forwards comparison study to evaluate facility design basis compliance to Reg Quide 1.97, per NUREG-0737, Buppi i Mods identified in encl will be completed by end of second refueling after Jul 1985 for each Unit.

 STEWART, N L. Virginia Electric & Power Co 84/01/3i. DENTON, H R Office of Nuclear Reactor Regulation, Director. EISENHUT. D. Q. Division of Licensing 49pp. 22095-201 24X Fiche 50-280, 84/01/31, 8402070382
- 402100203 Rev 10 to Emergency Plan Implementing Procedure EPIP-1.01 W/B40204 ltm WILBON.J , DEWANDEL, E P Virginia Electric & Power Co. 84/02/02 7pp 22178-017 24% Fichs. 50-280, 84/02/02, 8402100203.
- 402240032 Rev 10 to Emergency Plan Implementing Procedure EPIP-1 0i, "Emergency Manager Controlling Procedure " W/840217 ltr. WILBON.J., 816WART.W.L. Virginia Electric & Pawer Co. 84/02/02 D'REILLY,J P. Region 2, 04fice of Director 8pp 22375 256 24X Fiche: 50-280,84/02/02,8402240032.
- 402160631 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licenses, per 810709 Generic Ltr 81-27. H/o request, entire plan will be placed in FDR NEIOHBORS, J. D. Operating Reactors Branch I 84/02/06. STEHART, W L Virginia Electric & Power Co. 2pp 22301:358 24X Fiche: 50-280,84/02/06.8402160631
- 102170511 Forwards results of 830919-23 safeguards regulatory affectiveness review Comments requested by 840214 Encl withheld.
 THOMAS C.O Standardization & Special Projects Branch. 84/02/07 PARR.O D Auxiliary Systems Branch ZIEMANN.D.L., Procedures & Systems Review Branch 1p 22312.359 24X Fichs 50-280,84/02/07,8402170511

- 8402080169 Forwards "Safety Parameter Display Bys SAR for NVREG-0696 Computer Project North Anna & Surry Nuclear Power Stations," per 830415 response to NVREG-0737. Suppl 1 STEWART, W.L. Virginia Electric & Power Co. 84/02/08 DENTON, H.R. Defice of Nuclear Reactor Regulation, Director EISENHUT, D.G. Division of Licensing 2pp 22134 247 24% Fiche 50-000,84/02/08,8402080169
- --8402080181 "Safety Parameter Display Sys SAR for NUREG-0676 Computer Project.North Anna & Surry Nuclear Power Stations " * Energy, Inc SAR-VEPCO-005 84/01/20 225pp 22134 249 24X Fichs 50-000.84/02/08.8402080169
- B4022B0419 Ack receipt of B40127 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-2B0/B3-30 & 50-2B1/83-31 LEWIB.R C Division of Project & Resident Programs B4/02/09 STEWART.W L Virginia Electric & Power Co ip 22404 265 24X Fiche 50-280.84/02/09.8402280419
- --8402280449 IE Insp Repts 50-280/83-30 & 50-281/83-31 on 830906-1007 Violation noted svc water valve pit flood control panel alarm annunciated in control room but no documentation or response to alarm apparent BURKE.D J Region 2, Office of Director 83/12/20 App 22404 275 24X Fichs 50-280,88/02/09.8402280419
- 8402280503 Confirms B40223 meeting at Region II ofc to discuss security programs at facilities, per 840207 telcon
 LEWIS, R C Division of Project & Resident Programs 84/02/22
 STEMART, W L Viginia Electric & Power Co 1p 22407 100 24X
 Fiche, 50-000, 84/02/22, 8402280503
- 8402280453 Requests NRC review & approve use of installed reactor vessel lavel instrumentation system requirements of Generic Ltr 82-03, Suppl 1 to NUREO-0737 & TMI II F 2 STEMART, W L Virginia Electric & Power Co 84/02/23 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENKUT, D Q Division of Licensing 4pp 22407 053 24X Fiche. 30-280, 84/02/23, 8402280483
- 8402280287 Ack receipt of 840130 transmittal of amended pages to 8310 ltr forwarding 830915 rev to physical security plan Amended pages consistent w/provisions of 10CFR50 54(p) & acceptable LEWIS, R C. Division of Project & Resident Programs 84/02/24 STEMART, W L. Virginia Electric & Power Co 2pp 22379 074 24X Fiche 50-280,84/02/24,8402280287
- J Insurance & indemnity information
- B402060246 Endorsement 48 to NELIA Policy NF-240 & Endorsement 37 MAE , Policy MF-96
 * Virginia Electric & Power Co
 Fiche 50-000: 84/01/13; 8402060244
- P. Operating license stage documents & correspondence
- 8402:330013 Responds to FOIA request for two categories of documents ri IDCOR program, Forwards App A & B documents Documents placed in PDR. FELTON, J. M. Division of Rules and Records B3/12/21 SHOLLY, 8 C Union of Concerned Scientists. 5pp 22282 004 24X Fiche 50-000:83/12/21:8402130013
- --8309R60011 Summary of 830807-12 site visit & IDCOR meeting in Chic IL re status of data collection activity & containment capability BAGCHI.G Equipment Qualification Branch FIN A-6495 83/09/11 Equipment Qualification Branch. Spp 22282 203 24X Fiche 30-000,83/12/21,8402130013
- B402010093 Forwards Amends 91 & 92 to Licenses DPR-31 & DPR-32, respectively & safety evaluation Amends add new limiting conditions for operation & surveilance requirements which address filter & bottled air sys for main control room.

 NEIGHBORB-J D Deprating Reactors Branch 1 84/01/17 BTEWART. Winglinia Electric & Power Co Spp 22058 062 24X

 Fiche. 50-280,84/01/17,8402010093
- --8402010099 Amends 91 & 92 to Licenses DPR-37 & DPR-32, respectively, adding new limiting conditions for operation & surveillance requirements which address filter & bottled air sys for main control room VARGA, 8 A Operating Reactors Brench 1. 84/01/17 30pp 22058.045 24X Fiche: 30-280,84/01/17,8402010093
- --8402010102 Sefety evaluation supporting Amends 91 & 92 to Licenses DPR-37 & DPR-32, respectively e Defice of Nuclear Reactor Regulation, Director 84/01/17, 12pp 22058.095 24X Fichs. 30-280, 84/01/17, 8402010093

- 8402010247 Forwards BER re NUREG-0737. Item II F 2 & Generic Ltr 82-28, "Inadequate Core Cooling Sys " Add1 info requested to complete review of 830512 submittal Generic Hestinghouse approach acceptable VARGA.S A Operating Reactors Branch 1 84/01/17 STEHART, W L Virginia Electric & Power Co 12pp 22047 297 24x Fiche 50-280,84/01/17,8402010247
- 8402010445 Forwards Amends 93 & 92 to Licenses DPR-32 & DPR-37, respectively & safety evaluation Amends revise Tech Specs to reflect changes in upgrading & installation of fire protection sys

 NEICHBORS, J D. Operating Reactors Branch 1 84/01/17 STEWART, W L. Virginia Electric & Power Co. 3pp. 22061 158 24X

 Fiche 50-280, 84/01/17, 8402010445
- --B402010449 Amends 93 & 92 to Licenses OPR-32 & DPR-37, respectively, revising Tech Specs to reflect changes in upgrading & installation of fire protection sys VARGA.8 A Operating Reactors Branch i 84/01/17 21pp 22061 161 24X Fichs 50-280,84/01/17,8402010445
- --8402010455 Safety evaluation supporting Amends 93 & 92 to Licenses DPR-32 & DPR-37, respectively * Office of Nuclear Reactor Regulation, Director B4/01/17 3pp 22041 182 24X Fiche 50-280, 84/01/17, 8402010445
- 8402080503 Forwards Amends 94 & 93 to Licenses DPR~32 & DPR~37, respectively & mafety evaluation Amends revise Tech Specs to remove eight snubburs from auxiliary Feedwater sys & emergency diesel generator schaust piping from Table 4 17~1 NEIGHBORS. J D Operating Reactors Branch 1 84/01/31 STEHART. H L Virginia Electric & Power Co 2pp 22174 068 24% Fichs 50-280.84/01/31,8402080503
- --8402080506 Amends 94 & 93 to Licenses DPR-32 & DPR-37, respectively, ravising Tech Specs to remove eight shubbers from auxiliary feedwater sys & emergency diesel generator exhaust piping from Table 4 17-1 VAROA. B A Operating Reactors Branch 1 84/01/31 Upp 22174 070 24X Fiche 50-280,84/01/31,8402080503
- --8402080507 Safety evaluation supporting Amends 94 & 93 to Licenses PPR-32 & DPR-37, respectively * Office of Nuclear Reactor Regulation, Director 84/01/31 2pp 22174 079 24% Fiche 50-280,84/01/31.8402080503
- 8402010410 Otheric Ltr 84-04 to all operating PMR licensess.CP holders & applicants for CPs re safety evaluation of Nestinghouse topical repts dealing w/elimination of postulated pipe breats in PMR primary main loops Svc list ench EISENHUT,D G Division of Licensing 84/02/01 Consolidated Edison Co of New York. Inc. 59pp 22177 087 24X Fiche 50-000,84/02/01,8402010410
- 8402140383 Act receipt of TL Wedgewood 831230 ltr Forwards payment of assessed penalty for discharge of oil into cooling water discharge canal TAYLOR, J A Virginia Electric & Power Co. 84/02/02 U, B Coast Guard, Transportation, Dept of 3pp. 22220 052 24X Fiche 50-280.84/02/02,8402140383
- 8402100183 Forwards into re frequency of calibr.testing & training of operators for post-accident sampling sys.per 831216 88ER identifying open items in THI Item II B 3 BTEHARTH L Virginia Electric & Power Co 84/02/03, Denton, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D. O. Division of Licensing App 22182:184 24% Fiche 50-000,84/02/03,8402100183
- ch Spec Page 4.6-12 re radioactive d change to radiological
 -6 withdrawn from suppl
 STEWART, W L. Virginia Electric & Power Co. B4/02/03 DENTON, H R
 Office of Nuclear Reactor Regulation, Director VARGA, S. A.
 Operating Reactors Branch i ip 22:97-283 24x
 Fiche: 50-280, 84/02/03, 8402130351
- --8402130356 Revised Tech Spec Page 6 6-12 to 840111 proposes change to radiological effluent Tech Specs * Virginia Electric & Power Co. 84/02/03, ip 22197: 284 24x Fiche 50-280,84/02/03,8402130351
- 8402130020 Suppl 1 to application for amend to Licenses DFR~32 & DFR-37, adding description of post-accident sampling program to Section 6 re administrative controls in fullfillment of requirements of NVREG-0737, Items II F 12 & II D, 3, STEWART, W.L. Virginia Electric Fower Co. 84/02/09, DENTON, H.R. Office of Nuclear Reactor Regulation, Director VARGA, S. A. Operating Reactors Branch I Jpp. 22249 310 24X Fiche, 50-280, 84/02/09, 8402150020

- --8402150022 Proposed Tech Spec change adding description of post-accident sampling program to Section 5 re administrative controls in fullfilment of requirements of NUREO-0737, Items II F. I & II B 3 virginia Electric & Power Co 84/02/09 4pp 22249.313 24% Fiche 50-280,84/02/09,8402150020
- 8402160647 Forwards request for add1 info on NUREG-0737, Item II.D 1, "Performance Testing of Relief & Bafety Valves " Response within 60 days requested VARGA:S A. Operating Reactors Branch 1 84/02/09 STEHART, W 1. Virginia Electric & Power Co Spp 22302 007 24% Fiche 50-280:84/02/09.8402160649
- B402230143 Bupplemental application for amend to Licenses DPR-32 & DPR-37, adding limiting conditions for operation & surveillance requirements for main control chlorine detection sus, per NUREO-0737, Item III D 3 4
 BIEWART, W L. Virginia Electric & Power Co. B4/02/14 DENTON, K R Office of Nuclear Reactor Regulation, Director VARGA, B A Operating Reactors Branch 1 2pp. 22361 033 24X
 Fiche: 50-280, 84/02/14, 8402230143
- 8402280214 Reaffirms schedule for implementation of all Reg Quide 1 9) items by second refueling outage in Jul 1985 List of items, excluding in-core thermocouples, requiring add1 work to achieve compliance encl
 STEWART, M. ... Virginia Electric & Power Co. 84/02/21 DENTON, K.R. Office of Nuclear Reactor Regulation, Director EISENHUT, D.O. Division of Licensing 7pp 22400 185 24X Fiche 50-000, 84/02/21, 8402280214
- 8402280517 Suppls 840214 application for amend to Licenses DPR-32 & DPR-37 re control room chlorine detection sys per NUREQ-0737. Item III. D 3 4 Encl attachments inadvertently omitted from previous submittal STEWART. H L Virginia Electric & Power Co 84/02/21 DENTON. H R Office of Nuclear Reactor Regulation, Director VARGA, B A Operating Reactors Branch 1 ip 22406-338 24% Fiche 50-280.84/02/21.8402280517.
- --8402280325 Proposed changes to Tech Specs re control room chloring detection sys per TMI Item III.D 3 4

 * Virginia Electric & Power Co 84/02/21 Spp 22406:339 241
 Fiche 50-280,84/02/21,8402280517.
- 8409280740 Advises that fee will be refunded, per 10CFR170.11(b), for second Class t duplicate fee for 830825 application re Tech Bper change to remove certain snubbers MILLER, W 0 License Fee Management Branch. 84/02/21 STEWART, W L. Virpinia Electric & Power Co 1p. 22414; 342 24X Fiche 80-280, 84/02/21, 8402280740
- G Inspection reports. IE Bulletins & correspondence
- B312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps," Byc list enci. JORDAN-EL. Division of Emergency Preparedness & Engineering Response (Post B30103). 84/01/25. Cansolidated Edison Co. of New York, Inc. 120pp 22058,001, 24X Fiche.50-000,84/01/25,8312120153
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls." Syc list and JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/03. Consolidate Edison Co. of New York: Inc. 119pp. 22114:179. 24X Fichs 50-000:84/02/03,8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers," Svc list encl.
 DEYDUNG, R. C. Director's Office, Office of Inspection and Enforcement. 84/02/03 Consolidated Edison Co of New York, Inc 102pp. 22177; 156. 24x Ficher 50-000, 84/02/03, 8401190017.
- 8402280419 Ack receipt of 840127 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/83-30 & 50-281/83-31 LEWIS,R C. Division of Project & Resident Programs 84/02/09. STEMART,H,L. Virginia Electric & Power Co ip. 22404:265 24X Fiche, 50-280, 84/02/09.
- ---8402280426 Responds to NRC 831229 ltr re violations noted in IE Insp. Rapts 50-280/83-30 & 50-281/83-31. Corrective actions: importance of altertnase to conditions adverse to quality stressed to operators
 BTEMART.W. L. Virginia Electric & Power Co. 84/01/27
 O'REILLY.J.P. Region 2.0 Office of Director. 5pp. 22404:265, 243
 Fiche: 50-280,84/02/09,8402280417
- --8402280434 Forwards I& Insp Repts 50-280/83-30 & 50-281/83-31 on 830906-1007 & notice of violation LEMIS:R C. Division of Project & Resident Programs. 83/12/29 BTEMART;W.L. Virginia Electric & Power Co. 2pp. 22404:271. 247 Fiths. 50-280,84/02/09,8402280419

- --8402280438 Notice of violation from insp on 830906-1007
 * Region 2, Office of Director 83/12/29 3pp 22404 273 24x
 Fiche: 50-280,84/02/09,8402280419
- --B402280449 IE Insp Repts 50-280/83-30 & 50-281/83-31 on B30906-1007 Violation noted svc water valve pit flood control panel alarm annunciated in control room, but no documentation or response to alarm apparent
 BURKE.D. J. DAVIS.M J. Region 2. Office of Director ELROD, 6 A Division of Project & Resident Programs B3/12/20 App 22404:275 24% Fiche 50-280,84/02/09,8402280419
- 8401190041 IE Info Notice 84-09. "Lessons Learned From NRC Insps of Fire Protection Bafe Shutdown Bys (10CFRSO, App R) " Svc list encl.
 JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84002/13 Consolidated Edison Co of New York, Inc 124pp 2265 259 24X Fiche 50-000.84/02/13.8401190041
- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '"
 Svc list encl.
 JURDAN: E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc. 115pp 22365.141 24X Fiche 50-000.84/02/14.8401190039
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Mestinghouse Type 8A-1 Differential Relays" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc. 118pp. 22366-142 24X Fichs 50-000,84/02/15,8401190045
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches 8st Below Manufacturer Recommended Value " 8vc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 114pp 22366 024 24X Fiche 50-000.84/02/21,8401190062
- 8402280499 Ack receipt of 840120 ltr informing NRC of steps taken to correct violations noted in IE Inep Repts 50-280/83-34 & 50-281/83-34 LEHIB, R C. Division of Project & Resident Programs. 84/02/21 BTEMART, W L. Virginia Electric & Power Co ip. 22407 033 24X Fiche; 50-280, 84/02/21, 8402280499.
- --8402280505 Responds to NRC 831221 ltr re violations noted in IE Insp. Repts 50-280/83-34 & 50-281/83-36 Corrective actions radiation work permits revised to provide addi precautions & guidance on evaluation of nonuniform radiation fields SIEWART.N.L. Virginia Electric & Power Co. 84/01/20 O'REILLY, U.P. Region 2, Office of Director 4pp 22407.034 24X Fichs 50-280,84/02/21,8402280479
- --8402280511 Forwards IE Insp Repts 50-280/83-34 & 50-281/83-34 on 831031-1104 & notices of violation & deviation LEWIB:R C Division of Project & Resident Programs. 83/12/21. 81EWART:W L Virginia Electric & Power Co. 2pp 22407.038 24X Fichs. 50-280,84/02/21,8402280499
- --8402280518 Notice of violation from insp on 831031-1104 * Region 2, Office of Director. 83/12/21. 1p. 22407.040 24X Fiche: 50-280, 84/02/21, 8402280499.
- --8402280522 Notice of deviation from insp on 831031-1104 * Region 2, Office of Director. 83/12/21. 1p. 22407:041. 24X Fichs.50-280,84/02/21.8402280499
- --B402280529 IE Insp Repts 50-280/83-34 & 50-281/83-36 on B31031-1104. Violation noted:failure to provide appropriate personnel manitoring equipment Deviation noted,failure to modify procedure re use of swaled sources HOSEY.C.M Region 2. Defrice of Director BARR.K.P. Division of Engineering & Operational Programs B3/12/19 Bpp 22407:042. 24X Fiche: 50-280, 84/02/21, 8402280499
- 8401190666 IE Info Notice 84-11, "Training Program Deficiencies" Byc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/24 Consolidated Edison Co of New York, Inc 115pp 22430:304 24X Fiche:50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Boft Beat Valve Bsals,"
 Bvc list encl,
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103), 84/02/27, Consolidated Edison Co. of New
 York, Inc. 120pp. 22431:060, 24X Fiche: 50-000;84/02/27,8401190067

- S Reportable occurrences, LERs & related correspondence
- 840B220154 Responds to FOIA request that i46 LERs be placed in PDR Forwards LERs listed on app Documents also available in PDR Remaining LERs were either canceled or not issued FELTON. J M Division of Rules and Records 83/11/30 JEFFERSON. O A Affiliation Not Assigned 2pp 22380 052 24X Fiche 50-000.83/11/30.8402220154
- B402070365 Part 21 rept re linear converter device w/possible generic defect Initially reported on B40116 Written nutifications issued Customer responses should be received by 840331 Final rept will be submitted by B40330 D0D80N.J P Pacific Air Products Co 84/01/30 Director's Office Office of Inspection and Enforcement 2pp 22114 297 24) Fiche 50-000,84/01/30,8402070365
- ---8402070373 Part 21 rept re linear converter device w/possible generic defect Initially reported on 840116 Preliminary analysis indicates excessive wear of brass shaft guides Next rept will be submitted within 90 days Supporting info encl DOBSON.JP Pacific Air Products Co 84/01/17 POTAPOVB.U Repion 4. Office of Director & Bapp 22114 301 24X Fiche 50-000,84/01/30,8402070365
- 8402140236 NPDES noncompliance notification on 840201, discovered that chlorine gas feed sys failed to supply chlorine to affluent Caused by false rate meter reading due to water pressure Hypochlorite addition method substituted TAYLOR, JA Virginia Electric & Power Co. 84/02/03 JENKINB, R Virginia, Commonwealth of, 1p 22230 300 24X Fiche 50-280,84/02/03,8402140236
- B402210075 NPDES nancompliance notification updates status of chlorination sys at sawage treatment plant Malfunctioning gas feed sys reported in B40201 ltr returned to operation on B40203
 TAYLOR, J A Virginia Electric & Power Co B4/02/09 JENKINS, R R Virginia. Commonwealth of, ip. 22317 233 24X
 Fiche 50-280,84/02/09,8402210095
- 8402220146 Forwards LERs 84-001-00.84-002-00 & 84-003-00 WILBON, J L Virginia Electric & Power Co 84/02/13 O'REILLY, J P Region 2. Office of Director ip 22337 345 24X Fiche.50-281.84/02/13.8402220146
- --8402220155 LER 84-001-00 on 840113.manual trip initiated upon closure of main steam trip valve A Unwarranted valve closure due to hairline crack in air line pipe nipple of valve actuator Possibly caused by mechanical fatigue. Nipple replaced WILSON, J L. Virginia Electric & Power Co. 84/02/13 3pp 22337 346 24X Fiche: 50-281,84/02/13.8402220146
- --8402220160 LER 84-002-00 on 840114.at 2% power following 840113 trip. during replacement of open coil in reactor trip relay, reactor trip breaker A deenergized when first coil lead removed, resulting in reactor trip Caused by personnel error WILBON.J L Virginia Electric & Power Co 84/02/13 3pp 22337.347 24% Fiche 50-281,84/02/13,8402820146,
- --B402320164 LER B4-003-00 on B40114, while at 23% power, feed flow to steam generator A increased to full flow Valve opened & steam generator A high level trip initiated turbine trip, tripping reactor, Caused by air supply piping damage WILBON, J L Virginia Electric & Power Co B4/02/13 3pp 22337:332 24% Fiche, 50-281, 84/02/13, 8402220144
- DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1 F. Becurity, medical, emergency & fire protection plans
- B402070039 Final response to FUIA request for documents re emergency operation facilities located 10-20 miles from nuclear plants & info approxing/denuing location over 20 miles away Forwards listed documents info also available in PDR FELTON.J M Division of Rules and Records 83/11/04, O'NEILL,J H Shaw, Pittmen, Potts & Trowbridge. ip 22142 148 24X Fiche: 50-000,83/11/04,8402070039
- --B309120090 Recommends Commission agree W/approval of util position to establish common backup emergency operations facility for Prairie Island & Monticello nuclear generating plants. DIRCKS:N J. Office of the Executive Director for Operations. BECY-83-863. 83/08/30 86pp 22142-131 24X Fiche 50-000,83/11/04,8402070039
- --8402070045 Advises of Commission approval of util decision to establish smergency operations facilities 45 & 55 miles from respective sites.

 CHILK.B.J. Office of the Secretary of the Commission. 83/09/26 DIRCKB.W.J. Office of the Executive Director for Operations is 22142:149. 24X Fiche 50-000.83/11/04.8402070039

- 8402160370 Rev 5 to emergency implementing procedures including Temporary Memo 84-05 re offsite dose calculation W/840206 Jtr
 STEMOOS.A A . FEY.F % Northern States Power Co 84/02/0% 5pp
 22289 323 24% Fithe 80~282.84/02/0% 8402160390
- 8402080311 Ack receipt of 831221 ltr forwarding objectives for 840313 emergency preparedness exercise Objectives anclude in-plant & orsite radiological monitoring post-accident sample analysis & environ sample routing PAPERIELLO.C J Region 3. Office of Director 84/02/03 LAREON.C E Morthern States Power Co ip 22131 295 24X Fiche 50-282.84/02/03.8402080311
- -8402080317 Forwards 840313 emergency plan exercise objectives & guidelines Document developed in coordination w/States of MN & WI & was reviewed jointly by NRC & FEMA at 831212 meeting FEV.F L Northern States Power Co B3/12/21. PATTERBON, J P Region 3. Office of Director 1p 22/31, 286 24x Fiche 50-282, 84/02/03, 8402080311
- --B4020B0317 Rev O to "Emergency Plan Evaluation Exercise B40313. Section II Exercise Objectives & Quidelines " * Northern States Power Co 84/02/03 7pp 22131 287 24X Fiche 50-282,84/02/03.8402080311
- 8402210492 Requests remittance of Class I & III fees for 820630 request for exemptions from certain requirements of App R of 10CFR50 M/o encl MILLER, W O License Fee Management Branch 84/02/13 MV80LF.D M Northern States Power Co ip 22343 341 24X Fichs 50-282, 84/02/13,8402210492
- P Operating license stage documents & correspondence
- 8312120029 Generic Ltr 83-39 to representatives of utils re voluntary survey of licensed operators Svc list encl EISENHUF. B G Division of Licensing B3/12/08 Communuealth Edison Co 12pp 22313 006 24X Fiche 50-000.83/12/08.8312120029
- 840207001k Responds to Generic Ltr B3-28, "Generic Implications of Salem ATHS Events." Improper undervoltage trip attachment replaced. Hodified procedures developed & issued for testing reactor trip switchgear MUSCLF.D Northern States Power Go 84/01/31 Office of Nuclear Reactor Regulation, Director 1p. 22102-319 24X Fiche 30-282.84/01/31.8402070011
 - 02070529 Advises util of NRC actions re add1 fee required for B30202 amend application re steam generator surveillance & auxiliary feedwaters sys & refund for B00506 & 14 applications
 D10605.R M License Fee Management Branch B4/01/31 MUSOLF, D M Northern Btates Power Co 2pp 22141 324 24X Fiche 50-282,84/01/31,8402070527.
- 3402100348 Forwards supplemental safety evaluation re relief requests for inservice testing program for pumps & valves Five requests granted & two requests denied MILLER.J B Operating Reactors Branch 3 84/01/31 MUSOLF.D M Northern States Power Co 4pp 22207 335 24X Fiche 50-282,84/01/31,8402100349
- --8402100358 Supplemental safety evaluation re relief requests for inservice testing program for pumps & valves Five requests granted & two requests denied # Office of Nuclear Reactor Regulation, Director 84/01/31 17pp. 22207 337 24X Fiche 50-282,84/01/31,8402100348.
 - D2010410 Generic Ltr 84-04 to all operating PWR licensees.CP holders kapplicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PMR primary main loops 8vc list enc) SIBENNUT.D O Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc. 39pp 22177 087 24X Fiche: 50-000.84/02/01.8402010410.
 - 32160473 Responds to Generic Ltr B4-01 re NRC use of terms important to safety & safety-related Meeting between NRC & Steering 'ommittee of Util Safety Classification Group should be rranged to provide clarification of issue JBCLF, D Northern States Power Co 84/02/09 Office of Nuclear sactor Regulation, Director, ip 22247, 001 24X iche 50-000,84/02/09,8402160473

- G Inspection reports, IE Bulletins & correspondence
- 8312120173 IE Info Notice 84-06. "Steam Binding of Auxiliary Feedwater 312120133 IE Info Notice 04-05.

 Pumps. " Byc list encl
 JORDAN, E L Division of Emergency Preparadness & Engineering
 Response (Post B30103) 64/01/25 Consolidated Edison Co of New
 York, Inc 120pp 22058 001 24% Fiche 50-000,84/01/25,8312120153
- B401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list enc! JORDAN:E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000.84/02/03,8401190016
- 8401190017 IE Bulletin 84-01. "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEYDUNG.R C Director's Office. Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York. Inc 102pp 22177
- 8402270387 Forwards IE Insp Repts 50-282/84-01 & 50-306/84-01 on B40117-20 No noncompliance identified PAPERIELLO.C J. Region 3. Office of Director 84/02/08 LARSON.C E. Northern States Power Co. 2pp. 22390 258. 24X Fiche 50-282.84/02/08.8402270387
- --8402270392 IE Insp Repts 50-282/84-01 & 50-306/84-01 on 840117-20 Ho noncompliance or deviations identified Major areas inspected radwaste systair cleaning systaudits & appraisals & reactor coolant water quality & appraisals & reactor coolant water quality GRANT.W B . NICHOLSON.N A . GREGER.L R Region 3. Office of Director B4/02/07 5pp 22390 260 24X Fiche 50-282,84/02/08,8402270387
- 8402150319 Ack receipt of 840203 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/83-19 & 50-306/83-20 SHAFER, W D Region 3. Office of Director. 84/02/10 LARSON, C E Northern States Power Co ip 22250 070 24X Fiche 50-282, 84/02/10.8402150319
- --8402150320 Responds to NRC 840106 ltr re violations noted in IE Insp. Repts 50-882/83-19 & 50-306/83-20 Corrective actions fill & vent procedure revised to provide multi-disciplinary review of plant mods
 LARSON.C E Northern Btates Power Co 84/02/03 KEPPLER, J. 6
 Region 3, Office of Director 2pp 22250 091 24X Region 3. Office of Director 2pp 22250 091 Fichs 50-282, 84/02/10, 8402150319
- 8402170101 Responds to IE Bulletin 83-08 No breakers of type described in use or planned for use in safety-related application other than reactor trip breakers at facility LARBON, C.E. Northern States Power Co. 84/02/10 KEPPLER, J. G. Region 3, Office of Director 2pp. 22301,086, 24X Fiche 50-282,84/02/10,8402170101
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Bafe Shutdown Sys (10CFR50, App R), " Svc list encl encl JORDAN.E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365 259, 24X Fiche 50-000,84/02/13,8401190041
- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '" Svc list encl, JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/14, Consolidated Edison Co of New York, Inc 115pp 22365.141, 24X Fiche 50-000,84/02/14,8401190039
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Hestinghouse Type 9A-1 Differential Relays " 8vc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366 142 24X Fiche 50-000, 84/02/15, 8401190045
- 8402220017 Advises that cooling water header turbine bldg check valve 2CL-42-1 will not be tested per previous responses to IE Bulletin 83-03 Request for relief from testing under Section XI will be submitted LARSON.C E. Northern States Power Co 84/02/15 KEPPLER, J G Region 3. Office of Director. 1p 22326-018 24X Fiche 50-282.84/02/15,8402220017
- 8401190062 JE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value," Svc list encl JORBAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/21 Consolidated Edison Co. of New York, Inc 114pp. 22366:024 24X Fiche 50-000,84/02/21,8401190062

- 8401190046 IE Info Notice 84-11, "Training Program Deficiencies"
 Svc list encl
 JDRDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000.84/02/24,8401190066
- 8401190047 JE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
- Svc list encl
 JDRDAN, E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060 24X Fiche 50-000,84/02/27,840117006/

R Periodic operating reports & related correspondence

- 8402270234 "Annual Operating Rept, 1783 " W/840220 ltr LARSON,C E Northern States Power Co 83/12/31 Ki Region 3. Office of Director 6pp 22386 325 24X Fiche: 30-282,83/12/31,8402270234 KEPPLER, J G
- 8402150183 Monthly operating repts for Jan 1984 H/840206 ltr DUGSTAD.D., MUSOLF.D Northern States Power Co 84/01/31 22245 230 24% Fiche: 50-282,84/01/31,8402150183

B Reportable occurrences, LERs & related correspondence

- 8402220134 Responds to FDIA request that 146 LERs be placed in PDR Forwards LERs listed on app Documents also available in PDR Remaining LERs were either canceled or not issued FELTON, J M. Division of Rules and Records 83/11/30 JEFFERBON, O A Affiliation Not Assigned 2pp 22380 052 24X Ficher 50-000,83/11/30,8402220154
- 840Z0B0Z07 Discusses Hills-McCanna REMCCM actuators per NRC 840126 notice of potential lapse of GC Preventive maint, surveillance.insp programs & corrective action.when problem identified.serves well as continuing qualification program WATZL.E.L. Northern States Power Co 84/01/30 KEPPLER.J 0 Region 3. Office of Director 13pp 22130 089 24X Fiche.80-282.84/01/30.8402080209
- 8402070358 LER 84-001-00. on 840103, after refueling at 10% power, while switching from feedwater bypass valves to main regulating valves reactor tripped on overpower Caused by control rod withdrawal due to RCS temp decrease W/840202 ltr RUNBTAD. A A. MUSDLF, D. Northern States Power Co. 84/02/02 3pp 22076-174 24X Fiche, 50-282, 84/02/02, 8402070358

DOCKET 50-285 FORT CALHOUN STATION, UNIT 1

F Security, medical, emergency & fire protection plans

- 8402270368 Forwards info addressing commitments discussed during 830919 enforcement conference re violations noted in IE Insp. Rept 50-285/83-17 Ceiling & anchorage eys for GA file room adequate W/two oversize drawings Aperture cards in FDR JONES.W C Omaha Public Power District 83/09/30 SEIDLE.W.C Region 4. Office of Director. 29pp 22396.075. 24X Fiche 50-285.83/09/30,8402270368
- --8402270373 "Rept on Gypsum Wallboard in Floor & Cailing Const * Underwriters Laboratory 64/02/07 12pp 22396 103 2: Fiche 50-285,83/09/30,8402270368
- 8402160371 Notifies of 831018 meeting w/uti1, FEMA & States of NE & IA is Dasha.NE.to discuss scenerio for 831207 rediological swergency response exercise Util should be prepared to discuss marrative & controller cards development SEIDLE.W. C Region 4. Office of Director 83/10/06 JUNES, W C Combas Public Power District 2pp 22269 122. 24X Fiche 50-285,83/10/06,8402160371.
- 8402150357 Forwards response to IE Insp Rept 50-285/83-26 re physical security & guard training & qualification plans Response withheld (ref IOCFR73 21)
 JONES.W C Omaha Public Power District 84/01/05, GAGLIARDD, J E Division of Resident, Reactor Project & Engineering Programs 1p 22250,115 24% Fiche 50-285,84/01/05,8402150359
- B402160408 Forwards IE Insp Rept 50-285/83-34 on 831205-08 No violations or deviations noted.

 9A9LIARDO.J E. Region 4, Office of Director 84/01/18 JONES,W C Dasha Public Power District 2pp 22269-071 24X Dmaha Public Power District 2pp Fiche, 50-285, 84/01/18, 8402160408

- --B402160419 IE Insp Rept 50-285/B3-34 on B31205-0B No violations or deviations noted Major areas inspected licensee performance & capabilities during exercise of emergency plans & procedures
 MONTGOMERY, J. Region 4, Office of Director HICKEY, E.E.,
 SMITH. A.L. Battelle Memorial Institute, Pacific Northwest
 Laboratory 84/01/13 9pp 22267 073 24% Fiche 50-285. procedures 84/01/18, 840216040B
- 8402220509 Forwards IE Insp Rept 50-285/83-33 on 831114-18 Ne violations or deviations noted GAGLIARDO, J. Region 4. Office of Director 84/01/18 JONES, W.C. Omaha Public Power District 2pp 22334 057 24X Fiche 50-285,84/01/18,8402220509
- --8402220518 IE Insp Rept 50-285/83-33 on 831114-18 No violations or deviations noted Major areas inspected compliance w/App B to 10CFR73 re guard training & qualification plan Details withheld (ref 10CFR73 21)

 EVANS.C A. KELLY, J A. JOHNSON, W D. Region 4. Office of Director 84/01/04 lp 22334 059 24X Fiche 50-285,84/01/18,8402220509
- 8402080100 Forwards Amend 76 to License DPR-40 & safety evaluation Amend incorporates administrative changes, corrects terminology & clarifies basis section for dissel generator fuel oil inventory & shock suppressors snubbers W/o encl TOURIONY.E 0 Operating Reactors Branch 3 84/01/26 JONES, W COmaha Public Power District 1p 22172-335 24X Fichs 50-285,84/01/26,8402080100

P Operating license stage documents & correspondence

- B312120029 Generic Ltr 83-39 to representatives of utils re voluntary survey of licensed operators Svc list encl EISENHUT, D 0 Division of Licensing 63/12/08 Commonwealth Edison Co 12pp 22313 006 24X Fiche 50-000.83/12/08.8312120029
- 8402010444 Responds to FDIA request for SECY-83-288 & SECY-83-443 to be placed in PDR SECY-83-288 available in PDR SECY-83-443 being placed in PDR Forwards SECY-83-443 FELTON, J M Division of Rules and Records 84/01/17 YENOUSKAS, J Nowman & Holtringer 1p 22061 272 24X Fiche 50-000, 84/01/17, 8402010444
- --B402010433 Informs Commission of info obtained re flux reduction programs for pressurized thermal shock at lead plants, since B30225 interim rept (BECY 63-079)
 DIRCKS.W J Office of the Executive Director for Operations BECY-83-443 B3/10/28 lipp 22061 273 24X
 Fiche. 50-000, 84/01/17, 8402010444
- 8402080100 Forwards Amend 76 to License DPR-40 & safety evaluation Amend incorporates administrative changes corrects terminology & clarifies basis section for diesel generator fuel oil inventory & shock suppressors snubbers W/o ancl. TOURIGNY.E @ Operating Reactors Branch 3 84/01/26 JUNES, W C Dmaha Public Power District 1p 22172 335 24X Fiche 50-285,84/01/26,8402080100
- 8402070276 Forwards response to questions raised by EQ Tourigny re license amend on reactor vessel surveillance capsules JONES.W C Omaha Public Power District 84/01/27 MILLER, J R. Operating Reactors Branch 3 7pp 22102 041 24X Fiche 50-285,84/01/27,8402070276
- B402060370 Advises that electrical equipment qualification review meeting scheduled for B40323 in response to B31122 ltr JONES:M.C Omahe Public Power District 84/01/31 MILLER, J.R. Operating Reactors Branch 3 ip 22086, 275 24X Fiche 50-285, 84/01/31, 8402060370
- 8402070229 Forwards response to 840117 questions re reload core analysis, methods & verification JONES, W C Umaha Public Power District 84/01/31 MILLER, J R Operating Reactors Branch 3 3pp 22101 146 24X Fichs. 50-285, 84/01/31, 8402070229
- 8402010410 Generic Ltr B4-04 to all operating PWR licensees.CP holders & applicants for CFs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in FWR primary main loaps 8vc list encl EIBENHUT.D 0. Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc. 59pp 22177.087 24X Fithe.50-000.84/02/01.8402010410
- 8402160414 Forwards justification for continued operation w/
 nonqualified limit switches on HCV-11078, HCV-11088, YCV-1045A
 & YCV-1045B.per 840116 telcon. Replacement of limit switches
 scheduled during next refueling outage to begin Mar 1984
 JONES, W C Omaha Public Power District 84/02/03 MILLER, J R
 Operating Reactors Branch 3 4pp 22268 319 24x
 Fiche 50-285, 84/02/03, 8402160414

- B402130277 Advises that installation of last new spent fuel pool rack completed B40124, per Amend 75 to License DPR-40 & 830909 request Tech Specs 16 & 4 4 2 re design features & spent fuel storage effective
 JONES.W C Omahe Public Power District 84/02/07 MILLER, J R Operating Reactors Branch 3 2pp 22198 254 24X
 Fiche 50-225.84/02/07.8402130277
- 8402140092 Forwards add1 info re util proficiency in use of CESEC-III computer code.per NRC 840126 request Encl info addresses Generic Ltr 83-11 & demonstrates validity of Cycle 8 to Cycle & comparisons JONES, W.C. Omaha Public Power District 84/02/08 Uperating Reactors Branch 3 12pp 22217 201 24 Fiche 50-285,84/02/08,8402140092 OB MILLER, JR 24X
- 8402230227 Requests addl info re statistical combination of uncertainties repts for fuel reloads Response requested within 30 days in order to maintain review schedule MILLER, J R Operating Reactors Branch 3 84/02/13 JONES, W C Dmaha Public Power District 4pp 22379 160 24% Fiche 50-285,84/02/13,8402230227
- 8402220499 Submits changes to scheduled completion dates for proposed corrective actions noted in WC Jones 820121 response to Section 2 2-2 4 of Encl 3 to NUREO-0612 re control of heavy Gener, W.C. Umaha Public Power District 84/02/14 MILLER, J.R. Operating Reactors Branch 3 4pp 22334 082 24X Fiche 50-285,84/02/14,8402220499
- 8402230144 Notification of 840217 meeting w/PNL in Bethesda. MD to discuse 2nd quarter progress rept for reliability study of containment isolation sys HUANG.Y Containment Systems Branch FIN 8-2526, 84/02/14 BUTLER.W R Containment Systems Branch Jpp 22379 243 24X Fiche 50-285.84/02/14,8402230144

O Inspection reports: IE Dulletins & correspondence

- B40227036B Forwards info addressing commitments discussed during 830919 enforcement conference re violations noted in IE Insp. Rept 50-285/83-17 Ceiling & anchorage sys for QA file room adequate W/two oversize drawings Apertors cards in FDR JDNES, W C Umaha Public Power District 83/09/30 SEIDLE, W C Region 4, Office of Director 29pp 22394 075 24X Fichs, 50-285, 83/09/30, 8402270368
- --8402270373 "Rept on Gypsum Wallboard in Floor & Ceiling Const * Underwriters Laboratory 64/02/07 12pp 22396 103 2 Fiche 50-285,83/09/30,8402270368
- 8402220505 Forwards IE Insp Rept 50-285/83-35 on 831101-30 & notice OPERATOR TOWARD ALL HAS ACTION OF THE PROPERTY OF THE PROPERTY
- --8402220806 Notice of Violation from insp on B31101-30 * Region 4, Office of Director. 83/12/23 ip 22333 310 24X Fiche 80-285.83/12/23,8402220505
- --8402220310 IE Insp Rept 50-285/83-35 on 831101-30 Violation noted failure to follow review & approvel steps of CGE piping Isometric Brawing B-4238 for hydraulic snubbers YANDELL, L A. JOHNSON, W D Region 4, Office of Director 83/12/17 App 22333,311 24X Fiche 50-285,83/12/23,8402220505
- 8402220237 Forwards IE insp Rept 50-285/83-27 on 831031-1104 No violations or deviations noted GAGLIARDO.JE Region 4. Office of Director 83/12/28 JONES.W C Omaha Public Power District. 2pp 22339 121 24X Smena Public Power District, 2pp Fiche 50-285,83/12/28,8402220237
- -8402220248 IE Insp Rept 50-285/63-27 on 831031-i104 No violations or deviations noted Major areas inspected radiological environ monitoring program & licenses actions on selected open CHANEY, H D . HURRAY, B , JOHNSON, W D Region 4, Office of Director B3/12/15 10pp 22339, 123 24% Fiche 50-285, 83/12/28, 8402220237
- B402150359 Forwards response to 1E Insp Rept 50-285/83-26 re physical security & guard training & qualification plans Response withheld (ref 10CFR73 21)

 JDNES,W C Unaba Public Power District 84/01/05 GAGLIARDD. J E Division of Resident, Reactor Project & Engineering Programs 1p 22250 115 24X Fichs 50-285.84/01/05.8402150359

- 8402220321 Forwards IE Insp Rept 50-285/83-31 on 831114-18 & notice of Violation OAOLIARDO.JE Region 4. Office of Director 84/01/05 JONES,W C Omaha Public Power District 2pp 22336 267 24X Fiche 50-285,84/01/05.8402220321
- --8402220323 Notice of violation from insp on 831114-18 * Region 4. Office of Director 84/01/05 1p 22336 269 Fiche 50-285,84/01/05,8402220321
- --8402220326 IE Inep Rept 50-285/83-3i on 831114-18 Violation noted weekly review of approx 14 standing radiation work permits not performed for Feb & May 1983
 HOLLEY, W L . MURRAY, B , JOHNSON W D Region 4, Office of Director 83/12/22 7pp. 22336 270 24X Fiche 50-285,84/01/05,8402220321
- 8402220337 Forwards IE Insp Rept 50-285/83-29 on 831116-18 & 1212-14 No violations or deviations identified OAGLIARDO, J E Region 4. Office of Director 84/01/10 JONES,W C Omaba Public Power District 2pp 22336 251 24X Fiche 50-285.84/01/10,8402220337
- --8402220341 IE Insp Rept 50-285/83-29 on 831116-18 & 1212-14 No violations or deviations identified Major areas inspected.

 design changes mod & maint program

 MURPHY, M E , JOHNSON, W D. Region 4. Office of Director.

 4pp 22336 253 24X Fiche 50-285.84/01/10.8402220337 B4/01/09
- 8402220168 Forwards revised pages to inservice inap 10-yr plan (1973-1983) All required weld & support exams either completed or awalting exemption request approval JUNES,W C Omaha Public Power District 84/01/16 OAGLIARDO, J E Region 4, Office of Director 3pp 22340 234 24X Fiche 50-285,84/01/16,8402220168
- B40216040B Forwards IE Insp Rept 50-285/83-34 on 831205-08 No violations or deviations noted.

 OAQLIARDD, J. E. Region 4, Office of Director 84/01/18 JONES, W.C. Omaha Public Power District 2pp 22269 071 24X

 Fiche 50-285
- ---B402160417 lE Insp Rept 50-285/83-34 on 831205-08 No violations or deviations noted Major areas inspected licensee performance & capabilities during exercise of emergency plans &
- 8402220509 Forwards IE Insp Rept 50-285/83-93 on 831114-18, No violations or deviations noted GAGLIARDD, J Region 4, Office of Director 84/01/18 JONES, W C Omaha Public Power District. 2pp 22334 057 24X Fiche 50-285,84/01/18,8402220509
- --B402220518 IE Insp Rept 50-285/83-33 on B31114-18, No violations or deviations noted Major areas inspected compliance w/App B to iOCFR73 re guard training & qualification plan Details withheld (ref 10CFR73 21) EVANS.C A : KELLY, J A , JOHNSON, W D Region 4, Office of Director B4/01/04 ip. 22334 059 24X Fiche 50-285, B4/01/18, B402220309
- 8402220448 Forwards IE Insp Rept 50-285/83-37 on 831201-31, No viciations or deviations noted GAGLIARDO, JE Region 4, Office of Director 84/01/20, JONES, W C Omaha Public Power District. 2pp 22339 318, 24X Fiche: 50-285, 84/01/20, 8402220448.
- --8402220455 IE Insp Rept 50-285/83-37 on 831201-31 No violations or deviations noted Major areas inspected; operational safety verification, surveillance testing, maint activities, cold weather preparations & followup of IE bulletins YANDELL, L A , JOHNSON, W. D. Region 4, Office of Director, 84/01/10 9pp. 22339 320 24% Fiche 50-285,84/01/20,8402220448
- 8402270366 Responds to NRC 831223 ltr re violations noted in IE Insp. Rept 50-285/83-35 Corrective actions. List of snubbers removed or replaced w/rigid restraints will be rechecked against applicable subsys drawings
 JONES-W C Omaha Public Power District 84/01/20 GAGLIARDO, J E. Region 4. Office of Director 3pp 22391; 186 24X
 Ficho 50-285,84/01/20,8402270366. '20 GAGLIARDO, J E. 24X
- B312120133 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps." Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/25 Consolidated Edison Co. of New York

- 8402150188 Ack receipt of 840105 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-285/83-26 Reply responsive to concerns raised in notice of violation QAQLIARDO, J. Region 4. Office of Director 84/01/31 JONES, W.C. Omaha Public Power District ip 22245 175 24X Fiche 50-285, 84/01/31,8402150188
- E401190016 IE Info Notice 84-07. "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post E30103) 84/02/03 Consolidated Edison Co of New York. Inc 119pp 22114 179 24X Fiche 50-000.84/02/03.8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Syc list ent! DEYOUNG,R C Director's Office, Office of Inspection and Enforcement. B4/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 156 24X Fiche 50-000,84/02/03,8401190017
- B402130615 Forwards request for add1 info re 830415 response to IE Bulletin BO-11, "Masonry Wall Design " Response requested within 30 days of ltr receipt. W/o encl MILLER. J R Operating Reactors Branch 3 84/02/06 JONES, W C Omaha Public Power District 1p 22214 276 24X Fiche 50-285, 84/02/06.8402130615
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Bafe Shutdown Sys (10CFR50, App R)," Syc list enc!

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Int. 124pp. 22365-257 24X Fiche 50-000.84/02/13,8401190041
- B401190039 IE Info Notice B4-0B, "10CFR50 7, 'Employee Protection'" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/14 Censolidated Edison Co of New York, Inc. 1[5pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- 8401190045 IE Info Notice 83-63. Suppl 1. "Potential Failures of Westinghouse Type 8A-1 Differential Relays " 8vc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366 142 24X Fiche: 50-000.84/02/15,8401190043
- 84011900A2 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Sat Below Manufacturer Recommended Value " Svc list enci JORDAN.E. L. Division of Emergency Preparedness & Engineering Response (Fost 830103). 84/02/21. Consolidated Edison Co. of New York, Inc. 116pp 22366-024, 24X Fiche 50-000,84/02/21,8401190062
- 8402270163 Ack receipt of 831014 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/83-17
 0A0LIARDO, J E Region 4, Office of Director 84/02/22, JONES, W C Danks Public Power District 1p 22388 202, 24X
 Fiche: 50-285, 84/02/22,8402270163
- --8402270171 Supple 830919 response to NRC 834819 & 0913 ltrs reviolations noted in IE Insp Rept 50-285/83-17. Corrective actions: compilence w/GA const record commitments in PBAR will be met by 840501.

 JONES, W. C. Omsha Public Power District 83/10/14 QAQLIARDO, JE Region 4. Office of Director 5pp 22388 203 24X Fiche: 50-285, 84/02/22, 8402270163
- B402270329 Ack receipt of 840120 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/83-35 Implementation of corrective actions will be reviewed during future insp.

 9AGLIARDOJE Region 4, Office of Director 84/02/22, JONES, W.C.
 - OAGLIARDO, J.E. Region 4, Office of Director 84/02/22. JONES, W.C. Daaha Public Power District ip 22370 250 24X
 Fiche 50-285, 84/02/22, 8402270329
- 8401170066 IE Info Notice 84-11. "Training Program Deficiencies "
 Svc list encl
 JORDAN, E L. Division of Emergancy Preparedness & Engineering
 Response (Post 830103). 84/02/24 Consolidated Edison Co of New
 York, Inc. 115pp 22430,304. 24X Fiche,50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Boft Beat Valve Beals" Bvc 11st enc1 JORDAN E.L. Division of Emergency Preparadness & Engineering Response (Post 830103), 84/02/27 Consolidated Edison Co of New York, Inc. 120pp 22431.060 24X Fiche 50-000,84/02/27,8401190067
- H. Periodic operating reports & related correspondence
- B401170226 Monthly operating rept for Dec 1983, H/840113 ltr MUNDERLOH, D. J., JONES, W. C., Dmaha Public Power District 83/12/31 DEVOUND, R. C. Director's Office Of Inspection and Enforcement. 11pp 21831 209 24X Fiche. 50-285, 83/12/31, B401170226

- 8402220061 Monthly operating rept for Jan 1984 W/840214 ltr MATTHEWB.T P., JONES,W C. Omeha Public Power District 84/01/31 DEYGUNG.R C. Director's Office, Office of Inspection and Enforcement 13pp 22337 312 24X Fiche 50-285.84/01/31, B402220061
- DOCKET 50-286 INDIAN POINT STATION, UNIT 3
- F Security, medical, emergency & fire protection plans
- 8402130498 Responds to FDIA request for SECYs 83-248.271.278.281.279.305.306 & 307 Forwards SECY 83-271.83-278 & portions of five other SECYs as listed on App A Info partially withheld (ref Exemptions 3 & 7)
 FELTON, J M Division of Rules and Records B3/11/28 WEISS.E R Harmon & Weiss 4pp 22237 220 24X Fiche 50-000.83/11/28, 8402130498
- --8308050317 Responds to 830712 telcon request Util preparing employees to support staffing requirements of radiological emergency response interim plan Training scheduled for wk of 830808 BAYNE.JP Power Authority of the State of New York 83/07/12 KIBTER.H Region 1. Office of Director 1p 22237 338 24X Fiche 30-000,83/11/28,8402130478
- --8402130533 Responds to B30708 telcon request Util prepared to support exercise of "Radiological Emergency Response Interim Plan for Implementing Compensating Measures for Rockland County," during wk of B30808

 BAYNE, J P Fower Authority of the State of New York 83/07/11
 PETRONE, F Federal Emergency Management Agency 1p 22237 339
 24X Fiche 50-000, 83/11/28, 8402130498
- 8402020195 Forwards IE Insp Rept 50-286/83-22 on 831116-1215 No violations noted STAROSTECKI.R Division of Project & Resident Programs 83/12/27 BRONS.J C Fower Authority of the State of New York 2pp 22087 136 24X Fiche 50-286.63/12/27.6402020195
- --B402020204 IE Insp Rept 50-286/83-22 on B31116-1215 No violations noted Major areas inspected radiological medical drill IE bulletin followup, shift logs & records, actions on previous insp findings, plant tour, surveillance & maint KENNY.T J. ROBSBACH.L W. Region i, Office of Director NORRHOLM.L Division of Project & Resident Programs 83/12/22 11pp 22057-158 24% Fiche 50-286/83/12/27,8402020195
- 8402030535 Ack receipt of Class II fee remitted w/840106 amend request re Rev B to physical security plan Class III fee appropriate Addl sum requested DIGOB, R M License Fee Management Branch 84/01/26 BAYNE, J P Power Authority of the Btate of New York 1p 22082, 184 24X Fiche. 50-286, 84/01/26, 8402030535
- 8402070093 Ark receipt of 830914 ltr informing NRC of steps taken to correct violations noted in IE Insp.Rept 50-286/83-06 Due to generic nature of issue.encl HR Denton 831219 ltr to TS Ellis sent to all licensees MARTIN.T T. Division of Engineering & Technical Programs 84/01/27 BRONS, U C Power Authority of the State of New York Spp. 22102 305 24X Fiche.50-286.84/01/27.8402070093
- --8402070076 Responds to NRC B30817 ltr re violations noted in IE Insp Rept 50-286/83-06 Corrective actions procedures re work requests; fire protection sys & housekeeping revised. BROMS, J. C. Power Authority of the State of New York 83/09/14 MARTIN, T T Division of Engineering & Technical Programs 2pp 22102 311 24X Fiche 50-286,84/01/27,8402070093
- 8402080161 Notifies that Town of Ossining voted on 830517 to remain in emergency response plan w/special appeal to Wastchester County to establish municipal task force Discontent expressed re emergency communications sys
- B402170506 Forwards exemption from requirements of iOCFRSO, App R, Bections III 9 2 & 3 re upper electrical penetration areas & cable tunnels & sump.pump & control rooms.

 EIBENHUT, D 0 Division of Licensing B4/02/02 BAYNE, J P Power Authority of the State of New York Spp 22319 001 24X Fiche 50-286,84/02/02,8402170506
- --B402170510 Exemption from 10CFR50, App R. Bections 111 0 2 & Gre upper electrical penetration areas & cable tunnels & sump.pump & control rooms
 EIBENHUT.P 0 Division of Licensing 84/02/02 Power Authority of the State of New York 8pp 22319 009 24X
 Fiche. 50-286,84/02/02.8402170506

- 8402170113 Revised emergency plan implementing procedures, including IP-1003 re obtaining meteorological data, IP-1005 re planned discharge of containment atmosphere & IP-1060 re personnel radiological check W/840213 transmittal notice RYAN. T Power Authority of the State of New York 84/02/08 35pp 22300 130 24% Fiche 50-286,84/02/08,8402170113
- 8402270017 Board Notification 84-026 forwards DG Eisenhut 840202 1tr to JP Bayne approving nine & denying 16 exemptions from 10CFR50.App R requirements EISENHUT, D G Division of Licensing 84/02/09 PALLADINO, OILLINSKY, ROBERTS Commissioners 2pp 22407 338 24X Fiche 50-286.84/02/09.8402270017

G Adjudicatory correspondence

- B402070161 Comments on ASLB recommendations for evacuating school children
 RODRIGUEZ, P Parents Concerned About Indian Point HOLT, J Public
 Interest Research Group, New York 84/02/02 9pp 22103 066 24X
 Fiche 50-247.84/02/02.8402070161
- 8402080130 Comments on recommendations of ABLB re continued operation of facility while problems util should correct remain unresolved or incomiclusive ABLB urged to admit go-home plan leaves major problems w/protection of school children RODRIGUEZ,P Parents Concerned About Indian Point HOLT, J Public Interest Research Group, New York 84/02/02 9pp 22132,128 24× Fichs 50-247.84/02/02,8402080130
- B402070121 Forwards response to ASLB 831024 recommendations to Commission re safety issues Proposed Commission attendance at next emergency response dwill would improve understanding of problems at state & local levels BELBELLO, A B New York, State of 84/02/03 CHILK, S J Office of the Secretary of the Commission ip 22102,266 24% Fiche 50-247.84/02/03.8402070121
- --B402070126 Comments responding to ABLB 831024 recommendations to Commission re safety issues Commissioners invited to attend next emergency response drill DELBELLO, A B. New York, State of. 84/02/02 13pp 22102-267 24X Fiche 50-247,84/02/03,8402070121
- 8402080184 Charges Commission w/failure to fulfill responsibility of assuring public safety in event of emergency evacuation. Shelters useless disabled forgotten & plan sadly deficient FLEISHER. I 8 West Branch Conservation Association 84/02/03 Commissioners 5pp 22128 319 24X Fiche 50-247,84/02/03,840-2008.64
- 8402080193 Comments on ABLP recommendations to Commission ABLP improperly placed burden of persuasion on plant opponents, failed to conduct thorough investigation & failed to conform conclusions w/findings of fact HOLT-J Public Interest Research Group, New York 84/02/04 20pp 22129 209 24X Fiche 50-247,84/02/04,8403080193
- 8402070267 Comments on ASLB recommendations of facilities. Commission urged to focus on fact that serious release would be catastrophe of far greater dimensions than event at any other sites Centificate of Eve encl
 MEISS,E R Union of Concerned Scientists 84/02/06
 Commissioners 25pp 22102 048 24X Fiche 50-247,84/02/06, 8402070267
- 8402080135 Addition to Parents Concerned About Indian Point 840202 comments on ABLB recommendations HOLT.J Public Interest Research Group, New York 84/02/06 1p. 22132 047 24X Fiche. 30-247.84/02/06.8402080135.
- 8402090077 Responds to ABLB recommendations re emergency planning for facility & county, Facility should be closed due to inadequacy of emergency measures in event of major radiation release KESSLER, J. Roctland Citizens for Safe Energy. 84/02/06 PALLADINO.N J. Commissioners. App. 22160-209-24X Fiche 50-247.84/02/06.8402090077.
 - '2090184 Comments on ASLB 831024 recommendations to Commission re ergency planning, plant risk & comparative risk Continued spation recommended Centificate of 8vc encl MNDENBURG.B., MORRAN.C. Consolidated Edison Co. of New York, Inc IGAN.C. Power Authority of the State of New York 84/02/06 pp. 22157 223 24X Fiche 50-247,84/02/06,8402090184
 - 140127 Forwards FEMA comments on ABLB decision NREJ E. Hearing Branch I, 84/02/06 CHILK,8 J Office of the retary of the Commission ip 22218 249 24x he 50-247,84/02/06,8402140127

- --8402140130 Comments on ASLB recommendations re-steam generators Commission acceptance of findings recommended MDDRE, J.E. Hearing Branch 1 84/02/06 30pp 22218 250 24X Fiche 50-247,84/02/06,8402140127
- --8402140133 Response to ASLB 831024 recommendation to Commission, * Federal Emergency Management Agency 84/01/30 110pp 22218 279 24X Fiche 50-247.84/02/04.8402140127

H General correspondence

- 8402130478 Responds to FOIA request for SECYs 83-268.271.278.281.279, 305.306 & 307 Forwards SECY 83-271.83-278 & portions of five other SECYs as listed on App A Info partially withheld (ref Exemptions 5 & 7)
 FELTON.J M Division of Rules and Records 83/11/28 WEISB, E R Harmon & Weiss 4pp 22237 220 24X Fiche 50-000.83/11/28,
- --B307060279 Requests, per County Resolution 302, immediate suspension of licenses based on FEMA rept findings Resolution encl PARRIS,M Rockland County, NY 83/05/13 Office of Nuclear Reactor Regulation, Director 5pp 22237, 315 24X Fiche 50-000, B3/11/28,0402130498
- 8402130265 Responds to 831212 request to address D Kraut concerns repossibility that plant located on fault line will explode Plants designed to withstand DBE associated w/capable fault
 DIRCMS.H J Defice of the Executive Director for Operations
 84/02/02 KENNEDY.E M Senate 5pp 22216 203 24X
 Fiche 50~003.84/02/02.8402130265
- --8402130269 Forwards constituent D Kraut 1tr expressing concerns rebatards of living near nuclear power plant
 KENNEDV.E M Benate 83/12/12 Office of Public Affairs 2pp
 22216 207 24X Fiche: 50-003/84/02/02/8402130265

J Insurance & indemnity information

- 8402070335 Forwards Endorsements 60 & 61 to MAELU Policy MF-77 & Endorsements 70 & 71 to NELIA Policy NF-208.

 GOLDEN:M P Morsh & McLennan, Inc 84/01/30 SALTZMAN, J Assistant Director for State & Licensee Relations Spp 22161:166
 24X Fiche 80-000.84/01/30,8402070335
- D Advisory Committee on Reactor Safeguards reports & correspondence
- 8402270263 Responds to FOIA request for JC Mark 801204 memo to ACRS rehydrogen burn w/igniters & documents concerning generation, combustion or control of hydrogen in reactor accidents Forwards App A documents App B ducuments in PDR FELTON, J M Division of Rules and Records 84/01/30 HIATT, B L Dhio Citirens for Responsible Energy 7pp 22412:051, 24X Fichs 50-000.84/01/30.84/02270263
- --8402270282 Summary of 800520 meeting w/natl labs. Westinghouse. NRC k utils in Bethesda. MD re hydrogen technology. Meetings scheduled for 800603 & 0617 to discuss FVCS & core retention devices & containment structural response. respectively.

 GUITTSCHREIBER ACRS Advisory Committee on Reactor Safeguards
 80/05/22 ACRS Advisory Committee on Reactor Safeguards
 22412 044 24X Fiche. 50-000.84/01/30,8402270263
- P. Dperating license stage documents & correspondence
- B40213049B Responds to FOIA request for SECYs 83-268,271,278,281.299, 305,306 & 307.Forwards SECY 83-271.83-278 & portions of five other SECYs as listed on App A Info partially withheld (ref Exemptions 5 & 7).
 FELTON.J M Division of Rules and Records 83/11/28 HEIS9,E R Harmon & Meiss. 4pp 22237.220 24X Fichs 50-000,83/11/26, 8402130498
- --8307190358 Director's Decision DD-83-10 denying Rockland County request for immediate suspension of operations at facilities. DEYDUNG.R C Director's Office Office of Inspection and Enforcement. 83/06/27 2pp 22237 321 24X Fiche 50-000.83/11/28.8402130498

- 8402160003 Third partial response to FOIA request for info re votes & attendance at Commission materings for Jul 1981 Jul 1983 CHILK.8. J Offsce of the Secretary of the Commission 83/12/14 Public Document Branch ip 22281 023 24X Fiche 50-000,83/12/14. Public Document Branch 8402140003
- --8402160043 Staff requirements memo re 830610 discussion & vote on facility order in Washington,DC CHILKS J Office of the Secretary of the Commission 83/06/14 PLAINE,H H Office of the General Counsel 1p 2228; 060 24 Fiche 50-000, 83/12/14, 8402160003
- 83/06/14
- --8402160368 Staff requirements memo discussing possible 821222 vote on actions re facility in Washington.DC
 CHILK.S.J Office of the Secretary of the Commission 82/12/23
 Office of the Secretary of the Commission 1p 22281 248 24x
 Fiche 50-000, 83/12/14, 8402160003
- --B402160446 Discusses SECY-83-263 re Sunshine Act review of transcript of 830519 closed Commission meeting
 CHILK: 3 J Office of the Secretary of the Commission B3/07/08
 PLAINE; H H Office of the General Counsel ip 22281 304 24X
 Fiche 50-000, 83/12/14, 8402160003
- 8402010080 Forwards Amend 48 to License DPR-64 & safety evaluation Amend allows operation w/max of 24% steam generator tubes plugged in any steam generator POLK.P J Operating Reacturs Branch 1 84/01/13, BAYNE, J P F Authority of the State of New York 3pp 22058 111 24% Fiche 50-286, 84/01/13,8402010080. BAYNE, J P Power
- ---8402010086 Amend 48 to License DPR-64, allowing operation w/max of 24/ steam generator tubes plugged in any steam generator VARGA, S A Operating Reactors Brench I 84/01/13 15pp gg058:114 24X Fiche 50-286,84/01/13.8402010080
- --8402010089 Bafety evaluation supporting Amend 48 to License DPR-64 * Office of Nuclear Reactor Regulation, Director 84/01/13 9 22058 129. 24% Fiche 50-286,84/01/13,8402010080
- 8312120136 Board Notification 84-011 discusses NRC use of terms "important to safety" & "safety-related" EIBENHUT.D.O Division of Licensing 84/01/18 FALLADINO. O(LINSKY, ROBERTS Commissioners. 72pp 22241 008 24X Fiche 50-000, 84/01/18,8312120136
- 8402010304 Forwards SER re Item II K 2 17, "Potential for Voiding in RCB During Transients " Steam void will not result in unacceptable consequences during anticipated transients. VARGA: 8.4 Operating Reactors Branch i 84/01/18 BAYNE, J P Power Authority of the State of New York 14pp 22046:298 24X Fichs. 50-286.84/01/18,8402010304
- 8402010410 Generic Ltr 84-04 to all operating PWR licensess, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/slimination of postulated pipe breats in PWR primary main loops Svc list encl EIBENHUT.D G Division of Licensing 84/02/01 Consolidated Edison Co. of New York, Inc. 59pp 22177, OB7 24X Fichs. 50-000, 84/02/01, 8402010410.
- H402130174 Forwards attachment sheet & revised Tach Spec pages for Amend 48 to License DPR-64 re core limits & reactor Amena was to License DPR-04 re core limits & reactor collant flow POLK.P J Operating Reactors Branch 1 84/02/02 E Authority of the State of New York 3pp. 22216-314 Fiche 50-284, 84/02/02, 8408130194 BAYNE, J P. Power 4 24X
- --8402130198 Errats to Amend 48 to License DPR-64, revising Tech Specs re core limits & reactor coolant flow ** NRC No Detailed Affiliation Given 84/02/02. 13pp 22216:317. 24X Fiche 50-286:84/02/02.8402130194
- 8402220180 Provides summary of pertinent environ data considered during evaluation re disposal of drums containing charcoal No radioactive impact anticipated
 BAYNE.J P. Power Authority of the State of New York 84/02/10
 VARGA.S.A. Operating Reactors Branch 1 3pp 22340 294 24X
 Fichs 50-284, 84/02/10, 8402220180.
- 840117006B Board Notification 84-033 provides "Bys Interaction Program" task action plan for Unresolved Safety Issue A-17 Distribution list encl EIBENHUT,D Q. Division of Licensing 84/02/16 PALLADING, GILINSKY, ROBERTS Commissioners Spp 22482 091, 24X Fiche 50-000.84/02/16.8401190068
- 8402230190 Forwards application to amend License DPR-64 in response to requirements of Generic Ltr 83-37 re NUREG-0737 Tech 8pscs MAYNEJ.P. Power Authority of the State of New York 84/02/17 EISENHUT, D. 9 Division of Licensing. 2pp 22361 055. 24% Fiche. 50-286. 84/02/17.8402230190

- --8402230196 Application to amend License DPR-64 changing Tech Specs in accordance w/requirements of Generic Ltr 83-37 BAYNE, J P Power Authority of the State of New York 84/02/17 4pp 22361 057 24% Fiche 50-286,84/02/17,8402230190
- --8402230199 Proposed Tech Spec changes in response to requirements of Genevic Ltr 83-37 * Power Authority of the State of New York 84/02/17 20pp 22361 061 24% Fiche 50-286.84/02/17.8402230190
- O Inspection reports, 1E Bulletins & correspondence
- 8402020195 Forwards IE Insp Rept 50-286/83-22 on 831116-1215 No violations noted STANOSTECKI.R Division of Project & Resident Programs BRONS.J C Power Authority of the State of New York 2 22057 156 24X Fiche 50-286.83/12/27,8402020175 83/12/27
- ---B402020204 IE Insp Rept 50-2B6/83-22 on B31116-1215 No violations noted Major areas inspected radiological medical drill. IE bulletin followup, shift logs & records, actions on previous insp findings, plant tour, surveillance & maint KENNY, T J , ROSSBACH, L W Region 1, Office of Director NORRHOLM.L Division of Project & Resident Programs 83/12/22 11pp 22057 158 24X Fiche 50-286, 83/12/27, 8402020195
- B312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps" Byc list encl JDRDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000.84/01/25, 8312120153
- B4020701B2 Ack receipt of B31229 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-286/B3-20, Violations re environ monitoring program audits withdrawn MARTIN.T T Region i Office of Director 84/01/26 BRONS.J C Power Authority of the State of New York 2pp 22102 188 24X Fiche 50-286.84/01/26.8402070182
- --8402070192 Responds to NRC 831129 ltr re violations noted in IE Insp. Rept 50-286/83-20 Corrective actions errata sections to 1980 & 81 annual repts re 8r-90 & I-131 results prepared BRONS, J C Power Authority of the State of New York 83/12/29 MARTIN, T T Division of Engineering & Technical Programs 3pp 22102 190 24X Fiche 50-286,84/01/26,8402070182
- 8402070235 Forwards IE Insp Rept 50-286/83-23 on 831216-840115 No violations observed STARDSTECKI.R Division of Project & Resident Programs BRONS.J C Power Authority of the State of New York 2 22159 219 24x Fiche 50-286, 84/01/26, 8402090235 84/01/26
- -8402090243 IE'Insp Rept 50-286/83-23 on 031214-840115 No violations 102090243 It Insp Rept 50-286/83-23 on 831216-840115 No Viola observed Major areas inspected shift logs & records, licensee actions on pravious insp findings review mods, followup on IE bulletin & review of reporting requirements (KENNY, T J , ROBBRACH, L W Region 1. Office of Director NORRHOLM, L Division of Project & Resident Programs 84/01, 10pp. 22159 221. 24X Fiche 50-286,84/01/26,8402090235 84/01/23
- B402070093 Ack receipt of 830914 ltr informing NRC of steps taken to correct violations noted in iE Insp.Rept 50-286/83-06 Due to generic nature of issuerenci HR Denton 831219 ltr to TS Ellis sent to all licensees MARTIN, Y T Division of Engineering & Technical Programs 84/01/2 BRONS, J C Power Authority of the State of New York 3pp 22102 305 24X Fiche 50-286,84/01/27,8402070093
- --8402070094 Responds to NRC 830819 ltr re violations noted in IE Insp Rept 50-286/83-06 Corrective actions procedures re work requests. Fire protection sys & housekeeping revised BRONS. J C Power Authority of the State of New York 83/09/14 MARTIN. T T Division of Engineering & Technical Programs 2pp 22102 311 24X Fiche 50-286.84/01/27.8402070093
- 8401170016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Cantrols " Bvc list encl
 JURDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/03 Consolidated Edison Co of New
 York, Inc 119pp 22114 179 24X Fiche 50-000.84/02/03.8401190016
- 8401190017 IE Bullstin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEYDUNG.R.C. Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp. 22177 156 24X Fiche 50-000.84/02/03.8401190017

- 8401190041 JE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50.App R) " Syc list
- enci JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365 239 24X Piche 30-000, 84/02/13, 8401190041
- 8401190039 IE Inea Natice 84-08, "10CFR50 7, 'Employee Protection '"
 - Svc list encl
 JORDAN.E C. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 Yark. Inc 115pp 22365 141 24X Fiche 50-000.84/02/14.8401190039
- B401190045 IE Info Notice B3-63. Suppl 1, "Potential Failures of Westinghouse Type BA-1 Differential Relays " Svr 1ist encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/15 Consolidated Edison Co of New York Inc 118pp 22366 142 24X Fiche 50-G00.84/02/15.8401190045
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Valve " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co. of New York, Inc. 116pp 22366-024 24X Fiche 50-000.84/02/21,8401190062
- 8401190046 lE Info Natice 84-11, "Training Program Deficiencies SVc | 15t encl | Svc | S
- 8401190067 IE into Notice 84-12. "Failure of Soft Seat Valve Seals "
- R Periodic operating reports & related correspondence
- 8402070182 Ack receipt of 831229 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-286/83-20 Violations re environ monitoring program audits withdrawn MARTIN.T T Region I. Office of Director 84/01/26 BRON9.J C Power Authority of the State of New York 2pp 22102 188 24X Fiche 50-286.84/01/26.8402070182
- --8402070192 Responds to NRC B31129 ltr re violations noted in IE Insp Rept 50-286/83-20 Corrective actions errata sections to 1980 % B1 annual repts re Sr-90 & I-131 results prepared BRONS.J C Power Authority of the State of New York B3/12/47 MARTIN.T T Bivision of Engineering & Technical Programs 3pp 22102 190 24X Fiche 50-286,84/01/26,8402070182
- 8402210058 Monthly operating rept for Jan 1984 W/840215 ltr XELLY,L. . DRONS, J C Power Authority of the State of New York 84/01/31 8pp 22317 271 24X Fiche 50-286,84/01/31,8402210058
- 8 Reportable occurrences, LERs & related correspondence
- 8402030440 LER 83-007/03-0 on 831205, several seismic snubbers did not meet acceptability criteria during Surveillance Test

 PPT-R39 Cause unknown Defective Bergen-Paterson anubbers to

 be repaired or replaced WP400104 to

 GUMBLE-F W. DRONS, J. C. Power Authority of the State of New York

 84/01/04 MURLEY.T E. Region 1, Defice of Director. 2pp

 22069 041 24X Fiche 50-286.84/01/04.8402030460
- U Congressional/Executive Correspondence
- 8402010364 Further response to FDIA request for records re Ofc of Inspector & Auditor review of NRC investigation reported in NUREG-0862 & other file's concerning facilities Forwards App D documents App A & B documents available in PDR FELTON, J M Division of Rules and Records 83/11/22 REYNOLDS Center for Law in the Public Interest. 4pp 22038 203 24X Fiche 50-000,83/11/22,8402010364 REYNOLDS, J
- --8402010384 Commends NRC for responsiveness in closing facilities due to emergency planning deficiencies Urges review of testimony presented at hearings Facilities should remain closed until adequate emergency plans in place OILMAN.8 A House of Rep 83/05/25 PALLADINO, N J Cammissioners 2pp 22059 034 24X Fiche 50-000,83/11/22,8402010364

- 8402290002 Responds to FOIA request for correspondence NRC received from Senators J McClure. JB Johnston & P Lazalt during past 2 yrs forwards App A documents Name of individual deleted from Documents B & 9 of App A (ref FOIA Exemption 6), FELTON. J M Division of Rules and Records 83/11/30 KGLI. E Cable News Network. Inc 6pp 22438 002 24% Fiche 50-000, 03/11/30.8402290002
- --B402290250 forwards NRC order refacility Statements prepared by Chairman Palladino & Commissioners Ahearne & Roberts also encl Commissioners Gilinsky & Asselstine did not have prepared statements W/O encls KAMMERER, C Office of Congressional Affairs 83/05/05 BIMPSON, A HART, G Senate, Environment & Public Works OTTINGER, R House of Rep . Energy & Commerce 1p. 22438.053 24X Fiche 50-000.83/11/30,8402290002
- --8402290282 Ark receipt of B30327 ltr re emergency preparedness plans for facility Reply will be forwarded as soon as possible.

 KAMMERER. C Office of Congressional Affairs B3/06/01.

 JJOHNSTON. J B Benate. Energy & Natural Resources lp 22438.100
 24X Fiche 50--000.83/11/30.8402290002
- --8402270285 Requests NRC to begin rev of regulations immediately to eliminate present abuses re veto power over emergency planning provided by NRC & FEMA regulations to state NRC & FEMA should act forcefully to resolve crisis at facility JCHNBTON J B. Benate. Energy & Natural Resources 83/05/27 PALLADING, N J. Commissioners 2pp 22438 101. 24X Fiche 50-000,83/11/30,8402270002
- ---B402290303 Responds to B30527 ltr expressing concern re Commission contemplated shutdown of facility for emergency preparedness deficiencies on B30610. Commission decided not to take enforcement action Decision encl W/o encl KAMMERIER.C Office of Congressional Affairs. B3/06/20 JOHNSTON J B Senate. Emergy & Natural Resources ip 22438:13 24X Fiche 50-000.83/11/30.8402290002 1p 22438 112
- B408240075 Requests evaluation of dangers involved w/corrosion of steam generator pipes & results of tests conducted to determine pipe integrity. GILMAN.B A House of Rep 84/02/15 PALLADING, N. J Commission 2pp 22375 117 24X Fiche 50-247.84/02/15,8402240075 Commissioners

DOCKET 50-287 DOONEE NUCLEAR STATION, UNIT 3

- F Security, medical, emergency & fire protection plans
- 8402210077 Application for proposed amend to Licenses DPR-38, DPR-47 & DPR-55, defining term accessible/accessibility & incorporating addl fire hose stations located in reactor bldg TUCKER.H.B Buke Power Co. 84/02/13, DENTON.H.R Office of Nuclear Reactor Regulation, Director 3pp. 22317-288, 24% Fiche.50-269,84/02/13,8402210077
- --8402210081 Proposed Tech Spec rev.defining term accessible/ accessibility,incorporating add1 fire hose stations & updating FSAR. # Duke Power Co. 84/02/13 39pp 22317.291 24X Fiche 50-249,84/02/13,8402210077
- 840222007; Forwards Rev 3 to Vois 1 & 2 to "Response to Suppl 1, NUREG-0737 " Encl rev includes control room review final & supplemental repts & safety parameter display sys safety
- --8402R20077 Rev 3 to Vols 1 & 2 to "Response to Suppl 1, NUREG-0737"

 * Duke Power Co. 84/02/16, 250pp 22327:049 24%
 Fiche 50-269, 84/02/16, 8402220071
- J Insurance & indemnity information
- 8402210213 Forwards endorsements to NELIA & MAELU policies, including Endorsements 73 & 74 to NELIA Policy NF-182, Endorsements 57 & 58 to MAELU Policy MF-61 & Endorsement 4 to MAELU Policies ## 30 to AMELO POILTY APPAR & ENGINEERS 4 to AMELO POILTY AMERICAN L T Duke Power Co 84/02/15 BALTZMAN, J NRC - No Detailed Affiliation Glyen 1899 28316, 277, 24X Fish 80-000, 84/02/15, 8402210213

- P Operating license stage documents & correspondence
- B402240304 FOIA request for eight categories of documents ry license amends to OLs issued for nuclear reactors, including B30623 SECY-B3-249, NRC memos re review of B30929 facility OL amend & notification of Congress of NBHC treatment for spent fuel BELL, N Nuclear Information & Resource Service B3/11/23 Office of Administration 2pp 22414 058 24X Fiche 50-287, B3/11/23, B302240304.
- 8402140486 Responds to FOIA request for 16 categories of documents radegradation of bolts, nots & studs at PWRs & BWRs Forwards
 App A documents App A & B documents available in PDR
 FELTON, J. M. Division of Rules and Records 83/12/02 BELL, N
 Nuclear Information & Resource Service 4pp. 22257,003 24X
 Fiche: 50-000,83/12/02,8402140486
- --8402140516 "Metallurgical, Btress & Fracture Mechanics Analyses of Cracked Steam Cenerator Manway Studs From Oconee Unit 3 of Duke Power Co " BURCK, L. H., FOLEY, H. J. Parameter, Inc. NRC-05-80-251 IE-123 81/04/17. Director's Office, Office of Inspection and Enforcement, 16pp. 22257:340 24X Fiche 50-000,83/12/02, 8402140486.
- --8402140520 Attachment 1 to "Stress Analysis of Failed Steam Generator Manway Studs From Oconne Unit 3. Duke Power Co."
 FOLEY, W. J., DEAN, R. S. Parameter, Inc. NRC-05-80-251. IE-123 ROI BI/04/17 Director's Office, Office of Inspection and Enforcement, 28pp 22257:356 24X Fiche: 50-000,83/12/02,8402140486.
- 8402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILK: B. J. Office of the Secretary of the Commission 83/12/14 Public Document Branch. 1p 22281 023. 24X Fiche 50-000,83/12/14,8402160003.
- 8402240309 Partial response to FOIA request for eight categories of decuments re OL amends. Forwards App A documents. Documents also in PDR.
 FELTON. J. M. Division of Rules and Records. 83/12/14 BELL. N. Ruclear Information & Resource Service 4pp 82414:060. 24X Fiche: 50-287.83/12/14.8402240309.
- --8305020051 Forwards inputs to SER & EIA re util 830310 request for apent fuel pool expansion.

 MULLER, D. R. Assistant Director for Radiation Protection.

 83/04/21. LAINAB, 9. C. Assistant Director for Operating Reactors

 App. 22414:064. 24X Fiche: 50-287.83/12/14,8402240309

- --B307250073 Forwards request for add1 info licensee B30310 request for spent fuel pool expansion mod. Info needed includes description of term "lift bag" & conformance w/NUREQ-0612 guidelines.

 PARR. O. D. Auxiliary Systems Branch, 83/07/18, 8TOL2, J.F. Operating Reactors Branch, 2pp. 22414:079 24% Fiche. 50-287, 63/12/14, 8402240309.
- --8307290197 Forwards BER on application to expand spent fuel storage facilities. Proposed installation acceptable.
 KNSBHT.J P. Assistant Director for Comp. & Structures Engineering (Post B30201), 83/07/20, LAINAS.Q.C. Assistant Director for Operating Reactors. 6pp. 22414:082. 24X Fichs: 50-287, 83/12/14, 8403240309.

- --8308050626 Forwards Auxiliary Sys Granch SER re spent fuel pool mod for increased storage capacity Proposed spent fuel pool expansion program acceptable RUBENSTEIN.L 8 Assistant Director for Core & Plant Systems 83/07/26 LAINAS.G C Assistant Director for Operating Reactors 10pp 22414 088 24% Fiche 50-287.83/12/14.8402240309
- --B308150030 Forwards inputs to EIA re spent fuel pool storage expansion.
 in response to util B30310 request
 MULLER.D R Assistant Director for Radiation Protection
 B3/08/01 LAINAS, C C Assistant Director for Operating Reactors
 2pp 22414 098 24X Fiche 50-287.83/12/14,8402240309
- --B402240337 Submits telcon responses to requests for addi info re spent fuel pool rerack BUERMANNJ F NRC - No Detailed Affiliation Given 83/07/15 NRC - No Detailed Affiliation Given 2pp 22414 077 24X Fiche 50-287,83/12/14.8402240309
- --8402240344 Submits info from B30720 telcon w/B Gill re upent fuel pool retack bridge crane
 SUERMANN,J. NRC No Detailed Affiliation Given B3/07/20
 CHAN,T NRC No Detailed Affiliation Given ip 22414 OBI 24X
 Fiche 50-287,83/12/14,8402240309
- --B402240353 Advises of issuance of Amends 123,123 & 120 to Licenses DPR-3B. DPR-47 & DPR-55, respectively, changing Tech Specs to authorize expansion of spent fuel poil to B25 storage locations

 SUERMANN, J F Operating Reactors Branch 4 B3/07/27

 DENTON, H R . CARTER, J , EIBENHUT, D NRC No Detailed Affiliation Given ip 22414·100 24X Fiche 50-287,83/12/14,8402240309
- 8402030035 Forwards Amends 125,123 & 126 to Licenses DPR-38, DPR-47 & DPR-55, respectively & safety evaluation Amends revise Tech Specs to incorporate changes to radiological effluent Tech Specs for compliance w/App I of 10CFR50 STOLZ, J. F. Operating Reactors Branch 4 84/01/16 TUCKER, H B Duke Power Co. Spp. 22091 127 24X Fiche 50-269,84/01/16,840020035
- --8402030045 Amends 128,125 & 124 to Licenses DPR-38, DPR-47 & DPR-35, respectively, revising radiological effluent Tech Specs for compliance w/App I of 10CFR30 STOLE/J.F Gperating Reactors Branch 4 84/01/16 74pp 22091 130 24X Fiche 50-269,84/01/16,8402030035
- ---8402030065 Safety evaluation supporting Amends 125,125 & 126 to License DPR-36.DPR-47 & DPR-55, respectively * Office of Nuclear Reactor Regulation, Director 84/01/16 41pp. 22091; 204 24% Fiche 50-269,84/01/16.8402030035
- 8402070399 Notification of 840213-14 meetings w/util in Seneca.SC to review implementation of selected NUREC-0737 items. BUERMANN.J F Operating Reactors Branch 4 84/01/27. BTOLZ.J F Operating Reactors Branch 4 3pp. 22142
- 8402150446 Forwards Amends 126,126 & 123 to Licenses DPR-3B, DPR-47 & DPR-55, respectively & safety evaluation Amends revise Tech Specs to correct values for axial power shaping rod position limits after 385 EFPD for Unit 3.Cycle 7 operation.

 8TOLZ, J.F. Operating Reactors Branch 4 B4/01/30 TUCKER, H B Duke Power Co. 2pp 22258 292. 24X Fichs. 50-269, 84/01/30, 8402150446.
- --8402150452 Amends 126.126 & 123 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising Tech Specs to correct values for axial power shaping rod position limits after 385 EFFD for Unit 3, Gycle 7 operation.
 STDLZ.JF Derating Reactors Branch 4 84/01/30 9pp 22258:274 24X Fichs 50-269,84/01/30,8402150446
- ---8402150457 Safety evaluation supporting Amends 126,126 & 123 to Licenses DPR-38, DPR-47 & DPR-55, respectively. * Office of Nuclear Reactor Regulation, Director, 84/01/30, 2pp 22258-303, 24% Fiche, 50-269,84/01/30,8402150446,
- B402010410 Generic Ltr 84-04 to all operating PWR licensess, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops. Svc list encl. EIBENHUT, D. 9. Division of Licensing, 84/02/01. Consolidated Edison Co. of New York, Inc. 59pp 22177'087. 24X Fiche' 50-000,84/02/01,8402010410
- 8402130616 Advises that Class III license fee remitted w/830309 application requesting exemption from requirements of 10CFR50 App E. Bection IV F will be refunded Exemption authorized by law & is in public interest HILLER, H. D. License Fee Management Branch. 84/02/03, TUCKER, H. B. Duke Power Co. 1p. 22214.295 24X Fiche 50-000, 84/02/03.

- 8402230192 Summary of 640131 meeting w/util & INEL re equipment qualification program review List of attendees encl SUERMANN, J F Operating Reactors βranch 4 B4/02/08 Operating Reactors Branch 4 4pp 22379 189 24X Fiche 50-269,84/02/08,840230192
- 8402210077 Application for proposed amend to Licenses DPR-38.DPR-47 & DFR-55.defining term accessible/accessibility & incorporating addl fire hose stations located in reactor bldg
 TUCKER.H B Duke Power Co 84/02/13 DENTON.H R Office of Nuclear Reactor Regulation, Director STOL2.J F Operating Reactor Branch 4 Spp 22317 288 24X Fiche 50~269.84/02/13.8402210077
- --B40221008t Proposed Tech Spec rev, defining term accessible/ accessibility, incorporating addl fire hose stations & updating FSAR B Dute Power Co 84/02/13 39pp 22317 291 24X Fiche 50-269,84/02/13,8402210077
- 8402210174 Application for amend to Licenses DPR-38.0PR-47 & DPR-35 re proposed Tech Spec change to core protection safety limits, protective sys mar allowable setpoints & rad position limits
 TUCKER.H B Duke Fower Co. 64/02/13 DENTON.H R Office of Nuclear Reactor Regulation. Director STOLZ.J F Operating Reactors Granch 4 4pp 22017 033 24X Fiche 50-249.84/02/13.8402210174
- --84022]0184 Proposed Tech Specs re core protection safety limits, protective sys max allowable setpoints & rod position limits.
 * Duke Power Co. 84/02/13 73pp 22317 037 24X Fiche 50-269,84/02/13,8402210174
- --8402210191 "Cycle B Reload Rept.Feb 1984 "
 * Duke Power Co DCP-RD-2003 B4/02/29 45pp 22317 110 24X
 Fiche 50-267,84/02/13,8402210174
- 8402220517 Application for amend to Licenses DPR-38, BPR-47 & DPR-55 revising Tech Specs to establish degraded mode for emergency condenser cooling water sys TUCKER, H B Duke Power Co. 84/02/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 570LZ, J F Operating Reactor: Dranch 4 3pp 22331 314, 24% Fiche 50-269, 84/02/13, 8402220317
- --8402220521 Proposed Tech Specs establishing degraded mode for emergency condenser cooling water sys * Duke Pawer Co 84/02/13 7pp 22331 317 24X Fiche 50-269, 84/02/13, 8402220517
- G Inspection reports, IE Bulletins & correspondence
- 8402140203 Forwards IE insp Repts 50-269/83-37.50-270/83-38 & 50-207/83-37 on 831227-27 No violations or deviations noted DANCE.H C Division of Project & Resident Programs 84/01/12 TUCKER.H. B Dake Power Co 2pp 22229 327 24X Fiche 50-269,84/01/12,6402140203
- --840214021) IE Insp Repts 50-269/83-37, 50-270/83-38 & 50-287/83-37 on 831227-29 No violations or deviations noted Major areas inspected RCS leakage calculations
 BURNETI.P T Region 2, Office of Director JAPE.F. Division of Engineering & Operational Programs 84/01/11, 9pp. 22229, 331
 24X Fiche 50-269, 84/01/12, 840240203
- 8402150012 Forwards IE Insp Rapts 50-269/B3-38 50-270/B3-39 & 50-287/B3-38 on 831219-22 No violations or deviations noted. DANCE, H. C. Division of Project & Resident Programs 84/01/17 TUCKER, H. B. Duke Power Co. 200 22249 225 24X Fiche, 50-269, 84/01/17, 8402150012
- --8402150017 IE Insp Repts 50-269/83-38 50-270/83-39 & 50-267/83-38 on 891219-22 No violations noted Major areas inspected radwaste procedures radioactive efficient permits & rapts & efficient radiation monitor alarm settings
 WEDDINOTON, R.E. Region 2, Office of Director BARR, K.P. Division of Engineering & Operational Programs 84/01/13 App 22247 228 24X Fichs, 50-269, 84/01/17, 8402150012
- 8402150011 Forwards IE Insp Repts 50-269/83-39,50-270/83-40 & 50-287/83-39 on 831228-29 No violations or deviations noted. DANCE, H C Division of Project & Resident Programs, 84/01/19. TUCKER, H B Dust Power Co 2pp Fiche 50-269,84/01/19.8462150011
 - -B402150014 IE Imsp Repts 50-269/83-39,50-270/83-40 & 30-287/83-39 on B31228-29 No violations or deviations noted Major areas inspected trip time testing of QE Type AK2 reactor trip breakers
 GIBBONS: TO Region 2. Office of Director. CONLOW, T.E. Division of Engineering & Operational Programs. 84/01/18 3pp. 22249.305
 24X Fiche 50-269,84/01/19,8402150011,

- 8312120183 [E Info Notice 84-06, "Steam Binding of Auxiliary Feed, Pumps" Syc list enti JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of York, Inc 120pp 22058 001 24% Fiche 50-000.84/01/25.831212
- 8402280266 Forwards IE Insp Repts 50-269/84-01,50-270/84-01 & 50-287/84-01 on 840109-12 No violations or deviations identified.

 DANCE,H C Division of Project & Resident Programs 84/01/26 TUCKER.H B Duke Power Co 2pp 22399 186 24X Fiche 50-269,88/01/26.8402280266
- ---B402280270 IE Insp Repts 50-269/84-01.50-270/84-01 & 50-287/84-01 840109-12 No violations or deviations identified Major areas inspected refueling physics testing & reactivity balance calculations
 DAVENDORTIKE Region 2. Office of Director JAPE, F. Division Companying & Compa
- 8402280532 Forwards IE Insp Repte 50-269/83-40, 50-270/83-41 & 50-287/83-40 on 831211-840110 No violations or deviations noted DANCE, H C Division of Project & Resident Programs 84/01/30 TUCKER: H B Duke Power Cp 2pp 22406*172 24X Fiche 50-269.84/01/30.4402280532
- --B402280542 IE Insp Repts 50-269/83-40.50-270/83-41 & 50-287/83-40 831211-840110 No violations or deviations noted Major areas inspected operations. surveillance, maint & offsite safety review board activities BRYANT.J. FALCOMER.D Region 2. Office of Director BROWNLES, Division of Project & Resident Programs 84/01/27 7pp. 22406 174. 24X Fiche 50-249.84/01/30.8402280532
- 8402140143 Ack receipt of 840106 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-269/83-33, 50-270/83-33 & 50-289/83-33

 DANCE, H.C. Division of Project & Resident Programs 84/01/31

 TUCKER, H.B. Duke Power Co. ip 22218-201 24X

 Fiche 50-269-84/01/31:8402140143
- --B402140149 Responds to NRC B31208 ltr re violations noted in 1E in Repts 50-269/83-33, 50-270/83-33 & 50-287/83-33 Corrective actions: station program for identification & evaluation of nonroutine events revised TUCKER, H. B. Duke Power Co. B4/01/06 O'REILLY, J.P. Region 2. Office of Director. 2pp. 22218 202. 24x Fiche 50-269, 84/01/31 8402140143
- --8402140153 Forwards IE Insp Repts 50-269/83-33.50-270/83-33 & 50-287/83-33 on 831011-1110 & notice of violation.

 DANCE H C. Division of Project & Resident Programs 83/12/08 TUCKER H B Duke Power Co 2pp 22218 204 24X Fiche 50-269, 84/01/31,8402140143
- --B402140167 IE Insp Repts 50-269/83-33,50-270/83-33 & 50-287/83-33 (
 931011-1110 Violation noted Reduce hydro unit Unavailable for maint longer than 72 h & degradation beyond Tech Specs not subj to B31101 safety evaluation.

 BRYANT, J. FALCONER, D. Region 2, Office of Director BRCHNLEE, V. L. Division of Project & Resident Programs. B3/12/01 11pp 22218-207. 24X Fichs 50-269,84/01/31,8402140149.
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/03. Consolidated Edison Co. of No York Inc 119pp. 22114 179. 24X Fiche 50-000,84/02/03,840119001
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEYOUND: R C. Director's Office, Office of Inspection and Enforcement. 84/02/03, Consolidated Edison Co. of New York, Inc 102pp. 22177 156 24X Fiche: 50-000, 84/02/03, 8401190017.
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection 8afe Shutdown 8ys (10CFR50, App R) " 8vc 1ist encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/19 Consolidated Edison Co of Nr. York, Inc 124pp. 22365 259 24X Fiche, 50-000, 84/02/13, 84011904
- 8401190039 IE Info Notice 84-08, "10CFR50 7, Employee Protection."
 Svc list encl.
 JORDAN.E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 484/02/14. Consolidated Edison Co. of No.
 York, Inc. 113pp 22345:141. 24X Fiche 50-000,84/02/14,8401190001

- B402230202 Forwards evaluation of relief request & notice granting relief from inservice insp requirements of Section XI of ABME Doller & Pressure Vessel Code BTGLZ.J F. Operating Reactors Branch 4 84/02/14 TUCKER.H B Duke Power Co 3pp 22379 168 24X Fichs 50-269,84/02/14, 8402230202
- --B402230212 Evaluation of relief request from inservice insp program
 Relief from preservice hydrostatic tests Justifiable
 Alternative NDE program, proposed by Duke Power Co, will
 provide acceptable level of structural integrity
 # NRC No Detailed Affiliation Given B4/04/14 13pp
 22379 171 24X Fiche 50-269,84/02/14.8402230202
- --8402230217 Notice of granting relief from ASME Code, Section XI inservice insp requirements STOLZ.JF Operating Reactors Branch 4 84/02/14 2pp 22379: 184 24X Fiche 50-269,84/02/14.8402230202
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Hestinghouse Type 8A-1 Differential Relays" Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc 118pp 22366 142 24X Fiche 50-000,84/02/15,8401190045
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches 8st Below Manufacturer Recommended Value " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000,84/02/21,8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies"
 Svc list encl
 JORDAN, EL Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc. 115pp. 22430 304 24X Fiche 50-000,84/02/24,8401170066
- 8401190067 IE Info Notice 84-12, "Failure of Boft Seat Valve Seals " Bvc list encl, JORDAN,E L, Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/02/27. Consolidated Edison Co of New York, Inc. 120pp 22431 040. 24X Fiche 50-000,84/02/27,8401190067
- R Periodic operating reports & related correspondence
- 8402210122 Monthly operating repts for Jan 1984 W/840215 ltr REAVIS.J A Duke Power Co 84/01/31, 16pp. RE317 185 24X Fiche 50-269,84/01/31,8402210122.
- 8 Reportable occurrences, LERs & related correspondence
- 8402080244 LER 83-014/03L-0 on B31226 discovered channel B reactor protective sys A hot leg temp instrument indicating more than 3 F lower than other channels. Caused by deficiency Resistance temp detector bridge calibr M/840125 ltr PETTY, J. C B., TUCKER, H B Duke Power Co 84/01/25 D'REILLY, J P. Region 2. Office of Director. App. 22130, 137 24% Fiche 50-287, 84/01/25, 8402080244
- 8402220352 LER 84-001-00, on 840105, discovered 3TE switchgear load shed source B fuse block not installed Cause unknown Fuse block reinstalled & station mod to install fuse blocks & add computer alarms will be completed M/840206 ltr PETTY-J.C., TUCKER-H B Duke Power Co 84/02/06 D'REILLY, J P Region 2, Office of Director. 4pp 22336 202 24X Fiche. 50-287, 84/02/06, 8402220352
- DOCKET 50-288 REED COLLEGE RESEARCH REACTOR
- F. Becurity, medical, emergency & fire protection plans
- 8402280196 Requests that 831110 security plan be considered as request for amend to License R-112. Items questioned in previous submissions addressed in complete rewrite of plan KAY, M A., CRONYN, M. W. Read College, Fortland, DR, 84/02/22 DENTON, H R, Office of Nuclear Reactor Regulation, Director 1p 22400.214 24% Fiche, 50-288, 84/02/22, 8402280196
- DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1
 F. Sacurity, medical, emergency & fire protection plans
- 8402010491 Responds to FOIA request for SECY-83-318 & AEOD/T314 to be placed in PDR Forwards documents. Info partially deleted (ref FOIA Examption 5). AEOD/T316 available in FDR. FELTON, J M Division of Rules and Records 83/11/15, QRABER, L. D NUS Corp. 2pp 22060. 339 24X Fiche: 50-289, 83/11/15, 8402010491

- --B402010494 Informs that ALAB-698 draft order reversed AGLAB decision requiring emergency support director at TMI-1 to authorize protective action recommendations -- MALSCH.M G Office of the General Counsel ZERBE, J E Office of Public Affairs SECV 83-318 83/08/04 3pp 22060 341 24X Fiche 50-289,83/11/15,8402010491
- B402030424 Responds to util 830603 & 0720 ltrs re Revs 17 & 18 to security plan Portions of revs unacceptable Safeguards info withheld (ref 10CFR73 21)
 MARTIN.T T givision of Engineering & Technical Programs 84/01/24
 HUXILL.H D General Public Utilities 9PU Bervice Corp 4pp
 22048 272 24X Fiche 50-289,84/01/24,8402030424
- B402030310 Rev 3 to Administrative Procedure 1035, "Maintaining Emergency Preparedness" NELEGIN. M., TOOLE, R., HUXILL, H. General Public Utilities GPU Service Corp. 84/01/25 26pp. 22089 279 24X Fiche 50-289,84/01/25,8402030310
- 8402060440 Provides info re TMI-1 safety parameter display sys.per 830804 commitment to provide NRC w/identification of addl instruments & schedule for implamentation in response to Opnoric Ltr 82-33 & NUREG-0737. Item I D 2 HUKILL.H D General Public Utilities - GPU Service Corp 84/02/01 6186NHUT.D O Division of Licensing Spp 22083 092 24X Fiche 50-289,84/02/01.8402040440
- B402080150 Forwards matls re adequoty of emergency planning at facility, including IE Insp Rept 50-289/83-35 which sets forth findings & conclusions of staff who observed exercise & INFO 831128 It re findings ZAHLER, R E Bhaw, Pittman, Potts & Trowbridge ZAHLER, R E Metropolitan Edison Co 840/20/03 CHILK, B J Office of the Secretary of the Commission 24pp 22132 231 24X Fiche 50-289.84/02/03.8402080190
- B402090001 Forwards plans & test rept re intrusion detection upgrading Attachments withheld (ref iOCFR73 21)
 HUKILL.H D Oeneral Public Utilities OPU Service Corp B4/02/03 DENTON, H Office of Nuclear Reactor Regulation. Director 22163 325 24X Fiche 50-289, 84/02/03, 8402090001
- 8402090336 Forwards evaluation of State of PA radiological emergency preparedness plan for TMI KRIMM.R W Federal Emergency Management Agency 84/02/07 JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 5pp 22161 173 24X Ficher 50-289,84/02/07-8402090334
- --8402070339 Evaluation of State of PA radiological emergency preparedness plan for TMI * Federal Emergency Management Agency, 83/12/20 16Opp 22/61 178 24X Fiche 50-289,84/02/07,8402090336
- 8402160359 Forwards FEMA final exercise rept re 831116 joint exercise of state & local radiological emergency preparedness plana. Five Category A deficiencies identified MARTIN,T T Division of Engineering & Technical Programs HUKILL.H D General Public Utilities GPU Service Corp 22273,001 24X Fiche 50-289,84/02/10,8402160359
- ---8402160362 Evaluation of State of PA & Counties of Daughin, York, Lancaster, Cumberland, Lebanon, Borks, Schuykill, Snyder & Union emergency preparedness plans for TM-1, * Federal Emergency Management Agency 63/12/20 161pp 22273:004 24X Fiche, 50-289, 84/02/10, 8402160359
- 8402210096 Forwards FEMA final exercise rept for 831116 joint exercises of state & local radiological emergency preparedness plans for TMI-1 due to Category A deficiencies noted in three areas MARTIN.T. T Division of Engineering & Technical Programs. 84/02/10 DALTROFF, 8 L Philadelphia Electric Co. 3pp 22317 333, 24X Fiche 50-000,84/02/10,8402210096
- --8402210102 Exercise evaluation rept of Commonwealth of PA & Dauphin, York, Lancaster, Cumberland, Lebanon, Berks, Schuykill, Snyder & Union Counties emergency preparadness plans, * Federal Emergency Management Agency 83/12/20 197pp 22317-336. 24X Fiche 50-000,84/02/10,8402210096
- 8402:70140 Clarifies fire protection plan rev implementation, per 840107 itr & IE Insp Rept 50-289/83-18. Current & new fire brigade members will be trained as listed.
 HUKILL, H. D. General Public Utilities GPU Service Corp. 84/02/13 STOLZ-J F. Operating Reactors Branch 4 MURLEY-T E. Region 1, Office of Director 2pp. 22299 006 24X Fiche 50-289, 84/02/13, 2800120140

- 8402210135 Requests NRC attendance at 840221 independent fire-rating test for Rockbestos fire proof cable Cable designed for use in lieu of 1 h fire barriers, per 1007850, App R WILSON, R F General Public Utilities OPU Service Corp 84/02/10 \$701.2, J F Operating Reactors Branch 4 3pp 22317 167 24X Fiche 50-289, 84/02/13, 8402210135
- 8402240036 Revs to Administrative Procedure 1014, "Administration of TMI-1 Onsite & Offsite Emergency Duty Roster" & Emergency Plan Implementing Procedure 1004 27, "Activation of Emergency Operation Facility"

 NELSON, M A , TOOLE, R J , HUMILL, H Ceneral Public Utilities GPU Service Corp 84/02/13 29pp 22375 279 24X

 Fiche 50-289, 84/02/13, 8402240036

9 Adjudicatory correspondence

- 8401050299 Order clarifying Item 2 of ASLAU B31222 order re subjs that parties should address at upcoming oral argument in proceeding Item 2 refers to preventive as well as corrective maint procedures
 TOMPRINS.B A Atomic Bafety and Licensing Appeal Panel 84/01/03 ip 21729 005 24X fiche 50-289,84/01/03.8401050299
- 8402010201 Response supporting util 840109 motion to dismiss TMI Alert Contentions 1 a, 1 b.i c & 2 b 1 re steam generator repair Adequate basis for contentions not provided Certificate of Svc encl RAMEDN.R J Hearing Branch 4 84/01/24 Atomic Safety and Licensino Board Pamel App 22040 345 24X Fiche 50-289,84/01/24. Licensing Board Panel App 8402010201
- 8402010203 Act receipt of 840116 proposed interrogatories & motion for production of documents re steam generator repair Interrogatories will be answered by NRC on voluntary basis MAGNER, M E Hearing Branch 4 84/01/24 BRADFORD, L. Three Mile Island Alert ip 22040 362 24X Fiche 50-289,84/01/24,8402010203
- 8402010226 Forwards 830902 rept. "Results of Fasgre & Benson Investigation of Allegations by T Quinn re GPU Nuclear Corp." W/o encl HAGNER, M E Hearing Branch 3 84/01/23 CLARK, P Oeneral Public Utilities GPU Bervice Corp 1p 22040 176 24x Fiche 50-289, 84/01/23, 8402010226
- 8402010064 Expresses objection to applicant 840119 submittal of rept. "Lessons Learned Hortshop" Document has no status in case, no evidentiary value no inherent reliability & is attempt to improperly influence decision of ABLAD WEISS, E.R. Harmon & Weiss HEISS, E.R. Union of Concerned Beientists 84701/30 EDLES, O.J. BUCK, J.H., XOHL, C.M. Atomic Safety and Licensing Appeal Fanel 2pp 22042 191 24X Fiche 50-289,84/01/30,8402010064
- - - 83 Forwards response to Joint Intervenors first set of og torwards response to Joint Intervenore first set on gatories re steam generator repair Proposed form for tive order enc!

 IILL.8 W Shaw, Pittman, Potts & Trowbridge CHURCH: olitan Edison Co. 84/01/31 AMMODT, N. LEE, J. Ammod: 3:138 24X Fiche 50-287.84/01/31.8402030183. CHURCHILL, B. W.
 - /030187 Response to Joint Intervenors interrogatories (Set 1) reteam generator repair info Certificate of Svc enc:
 8URKLEY.D E Metropolitan Edison Co BURKLEY.D E Shaw, Pittman,
 Potts & Troubridge, 84/01/31 Aamodts 41pp 22068:140 24X
 Fiche 50-289,84/01/31,8402030183
- 3402030287 Forwards 840126 press release announcing election of RV Laney to Board of Directors of OFV Nuclear Corp & 840130 press release announcing appointment of RP Fasulo as vice president of administration for GPU Nuclear.

 BAUSER, D B Shaw, Fittman, Potts & Trowbridge BAUSER, D B. Metropolitan Edison Co. 84/01/31 EDLES, G. J. BUCK, J. H. Atomic Safety and Licensing Appeal Panel KOHL, C N. Atomic Safety and Jiconsing Board Panel 9pp 22089, 325 24X Fiche 50-289, 84/01/31, 802030289
 - 02030166 Memorandum memorializing 840130 conference call w/parties on procedural motions re discovery. Prehearing conference scheduled for 840827 canceled WDLFE.8 J Atomic Safety and Licensing Board Panel 84/02/01 6pp 22068 117 24X Fiche 30-289, 84/02/01, 8402030166.

- 8402030170 Forwards five documents intended for transmittal w/util response to Joint Intervenors first set of interrogatories W/o encl W/svc list CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge CHURCHILL, B W Metropolitan Edison Co 84/02/01 AAMODT, N Aamodts 2gp. 22068 123 24x Fiche 50-289,84/02/01,8402030170 CHURCH ILL. B W
- B402060174 Forwards documents referenced in answer to TNI Alert first sat of interrogatories & request for production of documents which at time of filing were determined to contain proprietary info W/o enci W/svc list CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge CHURCHILL, B W Hatrogolitan Edison Co. 84/02/01 DORGSHOW, J Three Mile Island Alert 2pp 22087 163 24X Fiche 50-289.84/02/01,8402060174
- 8402070051 Notifies that NRC prepared to answer any of Lement al 840116 proposed interrogatories Responses will be provided by 840204 NRC will not voluntarily provide info in Interrogatories 3 & 8 through 18 HAGNER.M E Hearing Branch 4 84/02/01 AAMODT.N Awmodts ip 22103-025 24X Fiche 50-289,84/02/01.8402070051
- 8402080150 Forwards matts re adequacy of emergency planning at facility.including IE Insp Rept 30-289/83-35 which sets forth findings & conclusions of staff who observed exercise & INPO 831128 Itr re findings
 ZAHLER,R E Shaw, Pittman, Potts & Trowbridge ZAHLER,R,E Metropolitan Edison Co 84/02/03 CHILK,B J Office of the Secretary of the Commission 24pp 22132 231 24X
 Ficher 50-289.84/02/03,8402080150
- 8402070259 Notice of issuance of util press release identifying changes to GPU mgt & board of directors Svc list encl
 BAUSER.D.B Metropolitan Edison Co BAUSER.D.B Bhaw, Pittman.
 Potts & Trowbridge 84/02/06 Commissioners 4pp 22101 198 24X Fiche 50-289, 84/02/04, 8402070259
- 8402070274 Order granting licenses 840127 request for leave to reply to TMI Alert response to licenses motion to dismiss Contentions 1 a.1 b.1 c & 2 b 1 & denying licenses 840109 motion to dismiss Contentions 1 a.1 b.1 c & 2 b 1 HOLFE, 8 J Regulations Division 84/02/06 Metropolitan Edisen Co 5pp 22101 318 24X Fiche. 50-289, 84/02/06, 8402070274.
- 8402090125 Forwards motion for protective order & answer to TMI Altra motion for order compelling discovery Proprietary documents for which protection sought encl W/o proprietary documents. BURKLEY.D.E. Shaw, Pittman, Potts & Trowbridge BURKLEY.D.E. Matrapolitan Edison Co. 64/02/04 WOLFE, 8 J. LAMB.J.C., HETRICK.D.L. Atomic Safety and Licensing Board Panel 2pp. 22163 245 24X Fiche 50-289,84/02/06,8402090125
- --B402090129 Motion for protective order for confidential proprietary info & answer opposing TMI Alert motion for order compelling discovery of proprietary info Certificate of Bvc encl BURKLEY, D.E. Metropolitan Edison Co. BURKLEY, D.E. Shew, Pittem, Potts & Trowbridge, B4/02/04 Atomic Bafety and Licensing Bearf Panel 29pp. 22163 247 24% Ficher 50-289,84/02/06,8402090125
- 8402090137 Forwards documents referenced in licenses answers to TMI Alert first set of interrogatories & request for production of documents which were originally proprietary Proprietary info removed. M/svc list Related correspondence CHURCHILL.8 W Bhaw, Pittman, Potts & Troubridge CHURCHILL.8 N. Matropolitan Edison Co. 84/02/06, DORGEHON, J. Three Mile Island Alert. 2pp 22163 187 24X Fiche. 50-289, 84/02/06, 8402090137.
- --B402090141 Affidavit of JH Taylor re determining whether documents listed in Exhibit A contain proprietary info, Rept comprises info which affords B&W opportunity to obtain competitive advantage. TAYLOR, J. H. Babcock & Wilcox Co. 83/01/13, 9pp 22163:189 241 Taylor 50-289, 84/02/06,8402090137.
- --9402070195 Affidavit of JH Taylor re determining whether documents listed in Exhibit A contain proprietary info. TAYLOR.J H Babcock & Wilcox G. 84/02/05, 23pp 22163:197 24X Fiche 50-287,84/02/06,8402090137
- --B402070148 Affidavit of UH Taylor ra determination of whether documents listed in Exhibit A contain proprietary info. TAYLOR: J H Babcock & Wilcox Co. B3/10/23 15pp. 22163.218 24X Fiche: 50-287.84/02/06.8402090137
- 8402140120 Answer to Joint Intervenor 840116 interrogetories of NRC Staff (Set 1) Certificate of Svc encl. HAGNER: M E Hearing Branch 4. 84/02/06 Sipp 22219:132. 24X Fiche.50-289,84/02/06.8402140120.

١,

- E402150437 Transmits documents resteam generator proceeding for placement in PDR HAGNER, HE Diffice of the Executive Legal Director 84/02/04 MCKNIGHT, J. Record Services Branch (Document Control Desk) 163pp 22259 120 24X Fichs 50-289,84/02/06,8402150439
- 8402090130 Forwards OPU 840201 ltr to EH Stier re agreement to investigate conduct of reactor coolent inventory balance measurements & responses thereto Certificate of Svc encl BAUSER.D. B. Bhaw, Pittman, Potts & Troubridge DAUSER.D. B. Watropolitan Edison Co. 84/02/07 EDLES.G. J. DUCK.J. H., KOHL.C. N. Atomic Safety and Licensing Appeal Panel. 5pp. 22163 145 24X Fichs.50-287.84/02/07.8402070130
- 8402140174 Informs of intent to file motions for summary disposition to all subparts of remaining contentions of TMI Alert & Joint Intervenore.per ARLB 831127 memorandum & order MAGNER.M E Hearing Branch 4 84/02/07 WOLFE.8 J. HETRICK.D L. LANB.J C Atomic Safety and Licensing Board Panel ip 22230 205 24% Fiche 50-289,84/02/07,8402140174
- 8402100142 Notifies of licenses intent to file motion for summary disposition of every contention of TMI Alert & joint interveners on 640224 Certificate of Bvc encl, Related correspondence CHURCHILL Shaw, Pittman, Potts & Troubridge. CHURCHILL General Public Utilities 0PU Bervice Corp. 84/02/08 MOLFE, 8, J., HETRICK, P. L., LAMB, J. C. Atomic Safety and Licensing Board Panel 2pp. 22182 074. 24X Fiche, 50-289, 84/02/08, 8402100142
- 8402130185 Response opposing Aamodt 840124 motion for reopening to examine leak rate falsification Motion relies on exaggerated characterizations & is bereft of supporting documentation Certificate of Svc encl.

 BLAKE, E.L. Metropolitan Edison Co. BLAKE, E.L. Shaw, Pittman, Potts & Troubtridge. 84/02/08 Atomic Safety and Licensing Appeal Panel 10pp. 22204-159. 24% Fiche. 50-289.84/02/08,8402130185
- B402130253 Forwards DR Biarey 840208 notice of withdrawal of appearance & M Woelfling 840208 notice of appearance Certificate of Svc encl.

 MDELFING M Fennsylvania, Commonwealth of, 84/02/08 Docketing & Services Branch 6pp 22178 217 24X Fiche 50-289, 84/02/08, 8402130253.
- 8402130240 Forwards comments on list of integrity issues in restart proceeding, in response to 840120 memo MOELFING.M. Pennsylvania. Commonwealth of. 84/02/08 CHILK, 8 J Office of the Becretary of the Commission. 1p. 22204 039. 24X Fiche: 50-289,84/02/08.8402130260
- --8402130264 Comments on list of integrity issues in restart proceeding Competence & integrity of operators at facility directly & critically related to safety & welfare of public which is responsibility of Commission HOELFING. M. Fennsylvania. Commonwealth of, 84/02/08 3pp 22204:040 24X Fiche.50-289.84/02/08.8402130260
- 8402130305 Forwards ref Documents 27, 34, 42, 47, 48, 49 & proprietary version of Topical Rept 008, Rev 3 for in camera review. ilcenses request ltms & NRC result ltms approving request encl. Certificate of Byc also encl. CHURCHILL, B. W. Shaw, Pittman, Potts & Trowbridgs. CHURCHILL, B. W. Matropolitan Edison Co. 84/02/08, WOLFE, 8 J. Atomic Safety and Licensing Board Panel. 11pp. 22204 026. 24X Fichs: 50-289, 84/02/08, 8402130305
- 84022400Bi Partial response to FOIA request for records arising out of ineps of TMI-1 & 2 re detection of measurement of RCB leakage. App A documents available in PDR. Forwards App B documents Revise of add records sub; to request continuing. FELTON, J.M. Division of Rules and Records 84/02/08, MADDEN, T. J. Kaye, Bcholer, Fishman, Hays & Handler. App. 22394, 277 24X Fiche: 50-289, 84/02/08,840224008i
- ---8307080080 Forwards 8tW Exhibits 428 & 42? re PORV tailpipe temps re leakage from PORV Evaluation of analysis of thermocouple data in Exhibit 428 requested by 830916 EIBENHUT, D Q. Division of Licensing, 83/08/25 MATTSON, R J Division of Bystems Integration (post 811005). 61pp 22374:288, 24X Fiche: 50-289,84/02/08,8402240081.
- --B402240105 Discusses correspondence w/DGJ re NRC investigation of Hartman allegations At 830728 oral argument on reopening record of facility restart processing ASLAS requested info re agreement between Commission & DGJ.

 CUNNINGHAN. 0, H. Office of the Executive Legal Director. B3/08/27 CUMNINGHAN. 0, J. Office of Inspector & Auditor 1p. 22374: 287 24X Fiche: 50-287, 84/02/08, 8402240081.

- --8402240114 Discusses ASLAB reopening hearing on mgt issues based on Hartman allegations of mgt involvement in falsification of leak rate data ABLAB will take up appeals of mpt decisions & will issue order setting oral argument CUNNINGHAM, 0 H Office of the Executive Legal Director 83/09/02 DENTON.H Office of Nuclear Reactor Regulation, Director 2pp 22374 290 24X Fiche 30-289,84/02/08.8402240081
- 8402130190 Response opposing TMI Alert 840125 motion for appointment of special panel Certificate of 8vc encl CHURCHILL.B W Metropolitan Edison Co CHURCHILL.B W Shaw, Pittman. Potts & Troubridge 84/02/09 Atomic Safety and Licensing Board Panel Bpp 22204 126 24X Fiche 50-289,84/02/09.
- B402130248 Motion supporting Aamodt motion to reopen record to consider evidence of leak rate falsification Info could elicit unfavorable ABLAB ruling on mgt integrity issues Certificate of Svc encl
 MEISB.E.R Union of Concerned Scientists 84/02/09 Atomic Bafety and Licensing Appeal Penel App. 22200 242 24X
 Fiche 50-289.84/02/09.8402130248
- 8402130309 Forwards add1 copies of ref Documents 11,13,14,15,23 & 26 re steam generator repair H/o encis Certificate of Byc encl Related correspondence CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge, CHURCHILL, B W Metropolitan Edison Co 84/02/09 DOROSHOW, J, BRADFORD, L. Three Mile Island Alert 2pp 22204.037 24X Fiche 50-289,84/02/09,8402130309
- 8402140006 Answer to Aamodt 840124 motion for respending to examine leak rate felsification Certificate of Svc enci GOLDBERGJR Hearing Branch 2 84/02/09 Atomic Safety and Licensing Appeal Panel 12pp, 22217 162 24X Fiche 50-289, 84/02/09,8402140006
- 840222013B Requests reconsideration of decision to withhold transcripts of NRC meetings between 810821 & 830510 re restart Related correspondence MILBTEIN, H E Kohn, Milstein, Cohen & Hausfeld 84/02/13 CHILK, B J Office of the Secretary of the Commission ip 22037. 269 24X Fiche 50-289, 84/02/13, 840222013B
- 8402220243 Response opposing THI Alert 840125 motion for order compelling discovery Disclosure of proprietary info should be protected & TMI Alert motion should be denied Certificate of Syc encl WAQNER, M.E. Hearing Branch 4 84/02/14 Atomic Safety and Licensing Board Panel 8pp 22339:199. 24% Ficha 50-289.84/02/14.8402220243.
- 8402220253 Response opposing TMI Alart B40125 motion for appointment of special panel as "quasi-investigators, quasi-special masters" to evaluate safety of steam generator repairs Proposal contrary to established procedures. W/Certificate of Svc MAGNER, M & Hearing Branch 4 84/02/14 Atomic Safety and Licensing Board Panel 7pp 22337 025 24X Fiche 50-289,84/02/14. 8402220253
- B402220074 Forwards JH Taylor 840215 affidavit supporting util 840206 motion for protective order securing proprietary info. Proprietary documents listed W/svc list Related correspondence CHURCHILL.B W Shaw, Pittman, Potts & Trowbridge CHURCHILL.B.W Metropolitan Edison Co 84/02/15 WOLFE.S.J, LAMB.J.C. HETRICK, D.L. Atomic Safety and Licensing Board Panel 3pp. 22330 040. 24% Fiche 50-287,84/02/15,8402220074
- --840222008i Affidavit of JH Taylor re classification procedures for proprietary documentation TAYLOR, J.H. Babcock & Milcox Co. 84/02/15 17pp 22330, 043 24X Fichs. 50-289, 84/02/15, 8402220074.
- 8402220133 Forwards nonproprietary versions of documents referenced in answers to TMI Alert first set of interrogatories & request for production of documents W/o encls W/evc list Related correspondence CHURCHILLS W Shaw, Pittman, Potts & Trowbridge CHURCHILL, D. W Metropolitan Edward Co 84/02/15 DDROSHDW, J. BRADFORD, L. Three Mils Island Alert 3pp. 22338 279. 24X Fiche 50-289, 84/02/15.
- 8402210175 Request for extension of time until 840219 for filing initial review briefs of ALAB-729 MEISB.E.R. Union of Concerned Scientists. 84/02/16 Commissioners ip. 22316:337. 24% Fiche.50-289.84/02/16, 8802210175
- --8402210181 Comments on ALAB-727 re main steam line rupture detection sys. Certificate of Svc encl.
 WEI88,E.R. Union of Concerned Scientists B4/02/16, 9pp 22316:338 24X Fiche d0-289,84/02/16,8402210175

- 8402210209 Comments on proposed solution to main steam line rupture detection sys Switches located in containment will be environmentally qualified through replacement in June 1984 Certificate of Svc enci
 BAXTER.T A Metropolitan Edison Co BAXTER.T A Shaw, Pittman, Potts & Troubhidge 84/02/16 5pp 22316 295 24X
 Fiche 50-289,84/02/16,8402210209
- 8402220105 Forwards resolution unanimously passed by city council on 840214 requesting Commission reconsider decision to separate mgt issues from restart decision & resolve safety mgt issues mgt issues from restart decision & resolve safety mgt issues before making any decision SAGER: EH Lancaster. PA 64/02/17 PALLADIND, N Commissioners 2pp 2238 261 24% Fiche 50-289,84/02/17,8402220106
- 8402220260 Response to util second set of interrogatories & request for production of documents re steam generator repair Certificate of Svc encl BRADFORD, L. Three Hile Island Alert 84/02/17 17pp 22330 153 24X Fiche 50-289.84/02/17,8402220260
- 8402220272 Supplemental answer to THI Alert first set of interrogatories & request for production of documents Staff objects to info requested in definitions & instructions Certificate of Svc encl Rylated correspondence WAGNER.M E Hearing Granch 4 84/02/17 43pp 22336 131 Fiche 50-289,84/02/17,8402220272 43pp 22336 131. 24X
- 8402220158 Response to Commission 840120 memo listing integrity issues Hartman allegations & leak rate falsifications must be examined to understand functional company policy AAMDDT, N O . AAMDDT, M A Aamodts 64/02/18 Commissioners 42pp 22328 351 24% Fiche 50~289.84/02/18.8402220158
- 8402220357 Responses to third set of interrogatories & request for production of documents Certificate of Svc anci BRADFORD.L Three Mile Island Alent 84/02/18 Metropolitan Edison Co 3pp 2234 131 24% Fiche 50-289,84/02/18.8402220357
- 8402230111 Forwards supplemental affidavit of JR Taylor for Ref Document 18 Original affidavit did not adequately delineste proprietary info Certificate of Svc encl CHURCHILL, B W Shaw, Pittman. Fotts & Troubridge CHURCHILL. CHURCHILL, B W Bhaw, Pittman, Potts & Troubridge CHURCHILL, B W Hatropolitan Edison Co 84/02/20 MOLFE, S J . RETRICK, D L . LAMB, J C Atomic Safety and Licensing Board Panel 3pp 22361, 215 24X Fithe 50-269, 84/02/20, 8402230111
- --8402230117 Affidavit of JH Taylor re classification procedure for proprietary info Certifiata of Svc encl
 TAYLOR, J H Babcock & Milcox Co 84/02/07 12pp 22361 218
 24X Fiche 80-289,84/02/20,840223011
- B402220193 Comments on list of integrity issues in Chill B40120 memo re restart hearing, including operator cheating & mgt integrity.

 ASLAB should lift order suspending reopened hearing Cartificate of Svc encil

 HE188.E R Union of Concerned Scientists WE188.E R Harmon & Weiss B4/02/21 17pp 22338 273 24% Fiche 50-289, 84/02/21, 8400220153 8402220153
- 8402230087 Comments on list of integrity issues in restart proceeding Each issue must be resolved prior to restart Certificate of Syc enci DDROSHOW, J. BRADFORD, L. Three Mile Island Alert 84/02/21 49pp 22362:075, 24x Fiche 50-289,84/02/21,8402230087

- 8402230092 Forwards Attachment I to licensee 840206 filing.per 840214 request
 WOLFE, S.J. Atomic Safety and Licensing Board Panel 84/02/21
 CHURCHILL, B.W. Shaw, Pittman, Potts & Trowbridge in 22362
 24X Fiche 50-289,84/02/21,8402230092
- 8402230076 Comments on 840120 proposed list of integrity issues Status rept & Certificate of Svc encl
 BLAKE, E. L. Metropolitan Edison Co BLAKE, E. L. Shaw, Pittman, Patts & Trowbridge 84/02/21 90pp 22361 111 24X
 Fiche. 50-269.84/02/21.8402230076
- 8402270035 Comments on Commission 840120 list of integrity issues in restart proceeding Unresolved issues do not meet stds for reopening record Certificate of Svc encl GOLDBERGU, R Hearing Branch 2 84/02/21 35pg 22387 005 24X Fiche 50-289.84/02/21,8402270035
- 8402280180 Erreta for 840218 response to Commission 840120 memorandum AAMODT, M M Aamodts 84/02/21 ip 22400 271 24X Ficha.50-289,84/02/21,8402280180

- 8402280340 Response to UCS 840120 petition for order suspending OL unless & until emergency feedwater sys complies w/MRC rules Petition should have been directed to NRR & should he denied Certificate of Svc encl BAXTER.T A General Public Utilities GPU Service Corp. BAXTER.T A Shaw, Pittman, Potts & Trowbridge 84/02/23 Commissioners 10pp 82399 001 24X Fiche 50-289,84/02/23, 840280340 Commissioners 8402280340
- 8402280215 Response to licensee & NRC opposition to TMI Alert motion for appointment of special panel TMI Alert not asking for funds & not attempting to escape responsibilities as intervenor DORDSHOWLJ Three Mile Island Alert 84/02/24 Atomic Safety and Licensing Board Panel 2pp 22400 179 24X Fichs 50-289.04/02/24,
- 8403280310 Order granting UCS 840217 request to extend time until 840319 for all parties to file initial briefs & until 840403 to file reply briefs CHILK, 8 J Gefice of the Secretary of the Commission 84/02/2. Commissioners ip 22379 218 24X Fiche 50-289.84/02/24.
- 8402280343 Hotion for summary disposition of each of TMI Alart & Joint Intervenors contentions No genuine issue of matl fact exists & licensee entitled to favorable decision CHURCHILL, B W Metropolitan Edison Co CHURCHILL, B W Bhaw, Pittman, Potts & Troubridge 84/02/24 Atomic Safety and Licensing Board Panel 242pp 22405 027 24X Fichs 50-287. 84/02/24,8402280343
- --84022B0352 Affidavits of DO Slear, BD Elam, MJ Grahem, 8D Leshnoff & 76 Giacobbe in support of licensee motion for summary disposition of each of TMI Alert & Joint Intervenors contentions Certificate of Svc ancl SLEAR, D Q., ELAM, B D., ORAHAM, M J. Metropolitan Edison Co 84/02/24 110pp 22405 158 24X Fiche 50-287, 84/02/24, 8402280343
- 8408280384 Memorandum & order denying TMI Alert 840125 motion for appointment of special panel Proposal radical departure from Congressional & Commission mandates
 HOLFE.S J Atomic Safety and Licensing Board Panel 84/02/24
 Three Mile Island Alert opp 22402 246 24X Fiche 50-289, 84/02/24,8402280384,
- 8402290123 Motion for summary disposition of Joint Intervenors Contentions 2.3 & 5. No genuine issue of matl fact exists & NRC entitled to favorable decision HAGNER, ME Hearing Branch 3 84/02/24 Atomic Sefety and Licensing Board Fanel Tipp 22426, 105 24X Fichs, 50-289, 84/02/24 8402290123
- --B402290124 Statement of matl facts as to which there is no genuine issue to be heard (Joint Intervenors Contention 2).

 * Office of the Executive Legal Director B4/02/24 Atomic Safety and Licensing Board Fanel App 22426 116 24X Fiche 50-289,84/02/24,8402290123
- --8402290128 Affidavit of CE McCracken & S Kirslis in support of summing disposition of Joint Intervenors Contention 2 McCRACKEN, KIRBLIS, S. Division of Engineering. 84/02/24 6pp 22426 122 24X Fiche. 50-289,84/02/24;8402290123
- --8402270134 Statement of matl facts as to which there is no genuint issue to be heard (Joint Intervenors Contention 3) ** Office of the Eiscutive Legal Director 84/02/24. Atomic Safety and Licensing Board Panel 2pp 22426 128 24X Fichs 50-289,84/02/24,8402290123
- --8402270140 Affidavit of CE McKracken & L Frank in support of NRC metion for summary disposition of Joint Intervenors Contention G MCCRACKEN.6, E , FRANK, L Division of Engineering. 84/02/24 3pp 22425 130 24X Fiche: 50-287,84/02/24,8402290123.
- --8402270143 Statement of matl facts as to which there is no genuing issue to be heard (Joint Intervenors Contention 5) # Office of the Executive Legal Director 84/02/24 Atomic Safety and Licensing Board Panel 8pp 22426 133 24X Fiche 50-289, 84/02/24, 8402270123.
- ---B402290149 Affidavit of CE McCracken & PC Wu in support of summary disposition of Joint Intervenors Contention 5 Certificate of Svc encl
 MCCRACKEN.C.E., WU.P. Division of Engineering 84/02/24 10ff 22426 141 24x Fiche 50-289,84/02/24,8402290123

- -- 8402290162 Statement of matl facts as to which there is no genuine issue to be heard (TMI Alert Contention 1 a)

 F Office of the Executive Legal Director 84/02/24 Atomic 88/824 and Licensing Board Panel 5pp 22427 023 24X
 Fiche 50-289,84/02/24,8402290158
- -- 6402290168 Affidavit of CE McCracken & JR Rajan in support of summary disposition of TMI Alert Contention I a MCCRACKEN.C E . RAJAN.J R Division of Engineering 84/02/24 Tpp 22427 028 24X Fiche: 50-289,84/02/24,8402290158.
- --B402290179 Affidavit of CE McCracken & L Frank in support of summary disposition of TNI Alert Contention 1 b.
 MCCRACKEN.C.E., FRANK, L Division of Engineering 84/02/24 9pp 22427 043 24X Fiche: 50-289,84/02/24,8402290158
- --8402290184 Affidavit of F Orr in support of staff motion for summary disposition of TMI Alert Contention 1.b ORR.F. Division of Human Factors Bafety. 84/02/24 3pp 22427 052. 24X Fiche: 50-289.84/02/24.8402290158

- --8402290217 Statement of mat1 facts as to which there is no genuine -issue to be heard (TMI Alert Contention 1 d).

 * Office of the Executive Legal Director 84/02/24 Atomic Safety and Licensing Board Panel. 7pp. 22427 068, 24X Fiche: 50-289, 84/02/24, 8402270158
- THE 402270223 Affidavit of CE McCracken & PC Wu in support of summary disposition of TMI Alert Contention 1.d MCCRACKEN, C.E., WU.P Division of Engineering. 84/02/24. 11pp 22427:075. 24X Fiche: 50-287, 84/02/24, 8402270158.
- --8402290229 Statement of met1 facts as to which there is no genuine issue to be heard (TMI Alert Contention 2.a).

 † Office of the Executive Legal Director. 84/02/24. Atomic Safety and Licensing Board Pahel. 4pp 22427.086. 24X Fiche 50-289,84/02/24,8402290158.
- F402270235 Affidavit of CE McCracken & B Kirslis in support of summary disposition of TMI Alert Contention 2 a. McCracken, C E., KIRBLIS, B. Division of Engineering. 84/02/24 7pp 22427:090 24X Fiche. 50-289,84/02/24,8402270158.
- B 402290242 Statement of matl facts as to which there is no genuine issue to be heard (TMI Alert Contention 2.5.1).

 © Office of the Executive Legal Director, 84/02/24, Atomic Safety and Licensing Board Panel 2pp., 22427:097, 24X Fiche, 50-289, 84/02/24, 8402290138
- ### 402290246 Affidavit of CE McCracken & 8 Kirslis in support of summary disposition of TMI Alert Contention 2 b. i. McCRACKEN, C. E. / KIRSLIS, 8. Division of Engineering 84/02/24 Gpp 22427:099, 24X Fiche: 50-289,84/02/24,8402290158.

- --8402290251 Statement of matl facts as to which there is no genuing issue to be heard (TMI Alert Contention 2 b 2)

 ** Office of the Executive Legal Director 84/02/24 Atomic Safety and Licensing Board Panel 4pp 22427 102 24X Fiche 50-289,84/02/24,8402290188
- --8402290260 Affidavit of CE McCracken & S Kirelis in support of summary disposition of TMI Alert Contention 2 b 2 MCCRACKEN.C E , KIRELIS.S Division of Engineering 84/02/24 5pp 22427 106 24X Fiche 50-289.84/02/24.8402290158
- --8402290248 Statement of mati facts as to which there is no genuine issue to be heard (TMI Alert Contention 2 c)

 * Dffice of the Executive Legal Director 84/02/24 Atomic Sefety and Licensing Board Panel 3pp 22427 111 24X Fiche 50-289,84/02/24,8402290158
- --B40R290270 Affidavit of CE McGracken & P8 Wu in support of NRC staff motion for summary disposition of TMI Alert Contention 2 c Certificate of Svc encl MCCRACKEN, C E , WU, P S Division of Engineering, B4/02/24 App 22427 113 24X Fiche 50-289,84/02/24,8402290158
- 8402290079 Motion to file out-of-time response to licensee second set of interrogatories Interrogatories dtd 840124 misplaced by third party Related correspondence AAMODT.N D Joint Petitioners TMI 84/02/27 Atomic Bafety and Licensing Board Panel ip 22428 076 24% Fichs 50~289,84/02/27,8408270079
- --B4022700B0 Response to licenses second set of interrogatories Cartificate of Svc encl Related correspondence AAMDDT.N D Joint Petitioners - TMI 84/02/27, 18pp 22428 077 24X Fichs 50-289,84/02/27,8402270077
- P Operating license stage documents & correspondence
- B402060025 Followup appeal re denial of FOIA request for documents characterized as proprietary or commercial trade secrets re repairs to steam generator tubes
 DDROBHOM.J Three Mile Island Alert 83/08/04 RCED, C. A Division of Rules and Records 1p 22iii i44 24X Fiche 50-289.89/08/04, 8402060025
- 8402030443 Rev 11 to Administrative Procedure 1029. "Conduct of Operations" M/840131 ltr NELBON,M A, TOOLE,R J, HUKILL,H.D General Public Utilities - GPU Bervice Corp. 83/09/15. 870LZ.J F Decrating Reactors Branch 4 5pp 22069 031 24X Fiche 50-289:83/09/15;8402030443
- 8402070017 Further response to FOIA request for SECY-83-245 & BECY-83-247 & documents re training &/or testing program or cheating incidents at facility. No documents responsive to request located.
 FELTON, J M Division of Rules and Records 83/10/03 DORDSHOW, J. Three Mile Island Alert ip 28142 264 24X Fiche 50-289, 83/10/03, 8402070017.
- 8402060028 Further response to appeal re denial of FOIA request for documents concerning steam generator problems at facility. Forwards App A documents, App B documents partially withheld (ref FOIA Examption 4).

 DIRCKB, W. J. Office of the Executive Director for Operations 83/10/27 DOROBHOW, J. Three Mile Island Alert 7pp. 22/11/153 24X Fiche 50~289, 83/10/27, 8402060028
- ---B206210343 Forwards proposed program, schedule & level of technical affort required for accomplishing tentative work assignment J & evaluation of YMI-1, steam generator tube sealing program.

 FANDEY, B. Franklin Institute/Franklin Research Center.

 NRC-03-B1-130. 82/06/17 BAJWA, B B NRC No Detailed Affiliation Given. Sep R2112 143. 24X Fiche 30-289, 83/10/27, 8402040028
- --8206290608 Requests review of encl tentative work assignment J.

 "Evaluation of IMI-1 Steam Generator Tube/Tube Sheet
 Repair." notification as to whether proposed schedule can be
 met & estimate of required managemen resources
 BAJWAR-S.S. NRC No Detailed Affiliation Given. NRC-03-81-130
 B2/06/14 PANDY, B Franklin Institute/Franklin Research Genter
 4pp. 22112.139 24X Fiche.50-289.83/10/27.8402060028.
- --82070700028 Advises that once-through steam generator specs for facility have been sent to Franklin Research Ctr.per 820702 telcon.

 GRAMAM.M.J. General Public Utilities OPU Service Corp.

 82/07/06. MCCRACKEN.C. ARC No Detailed Affiliation Given ip

 22111:165 24X Fiche: 50-289,83/10/27,8402060028.

- --8207140125 Summary of 820621 meeting w/util, Foster Wheeler, B&W & Franklin Research Ctr in Livingston, NJ re steam generator tube tubesheet repair Details of kinetic expansion process expected to be finalized before NRC 820627 meeting RAJAN, J Hechanical Engineering Branch 82/06/28 BUBNAK, R Mechanical Engineering Branch 7pp 22112, 149 24X Fiche 50-289, 83/10/27, 840206028
- --820720044i Informs of General Public Utils tentative schedule for full-scale test on TMI-1 once-through steam generator at Mount Vernon, IN for who f 820726 JACOBS.R Operating Reactors Branch 4 B2/07/09 EISENHUT, D O Division of Licensing (p. 22112 260 24X Fiche 50-287, 83/10/27, 840PUADO28
- --B207300136 Discusses steam generator corrosion which makes thiosulphate theory suspect & makes explosion repair both suspect & dangerous Facts suggest cause of corrosion not thiosulphate Requests NRC not approve steam generator repair LEHIS, M T Lewis, M 82/07/27 DENTON, H R Office of Nuclear Reactor Regulation, Director Jpp 22112 157 24% Fiche 50-289, 83/10/27, 8402060028
- --8208090285 Informs of printing costs for TMI-1 steam generator tube destructive exam rept BENARDYAV Chemical Engineering Branch 82/08/03 MCVEAGH.H Division of Technical Information & Document Control 1p 22111 187 24X Fiche 50-289,83/10/27,8402060028
- --8208250400 Responds to 820723 ltr re insufficient util effort being focused on sulfur removal from surfaces at facility Desulfurization necessity & viability being determined Restart plans to be reviewed following 820819 meeting BENARDYA, V Chemical Engineering Branch 62/08/06 MACDONALD, D D Affiliation Not Assigned 2pp 22111 163 24X Fiche: 50-289, 83/10/27, 840208008
- --8208310181 "TM1-i Once-Through Steam Generator Repair Safety Analysis " Withheld (ref 100FR2 790) + General Public Utilities - 0PU Service Corp 82/08/20 36pp 2213-214 24X Fiche: 50-289,83/10/27,8402060028
- --B208310444 Provides schedular update & summary of 820805 full-scale expansion demonstration at Mt Vernon, IL & 820809 review of eddy current test program & results at TMI-1 Detailed meeting minutes will be provided by project manager MCCRACKEN.C Chemical Engineering Branch 82/08/17. BENARDYA, V Chemical Engineering Branch 92/08/17. BENARDYA, V Fiche 50-289, 83/10/27, 8402060028
- --B207280423 Provides status of steam generator repairs as discussed in 820825,0901-02 meetings Schedule of future meetings repairs listed Periodic insps will monitor for initiation of new defects & corresion rate MCCRACKEN.C. Chemical Engineering Branch 82/09/10 BENARDYA.V Chemical Engineering Branch 2211:190, 24X Fiche 50-289,83/10/27.8402060028.
- --B209280427 Comments on B&W Rept 77-1135317. "Evaluation of Tube Samples From TMI-1" Rept describes thorough & comprehensive evaluation of Inconel-600 tubes removed from steam generators subsequent to detection of lesks MACDONALD, D D Affiliation Not Assigned. B2/08/30 BENARDYA, V. Chemical Engineering Branch 4pp 22111 162. 24X Fiche 50-289,83/10/27,8402060028.
- --B210070023 Advises that safety evaluation necessary prior to restart to determine that licensee took proper steps to recover from once-through steam generator corrosion problem VOLLMER.R Division of Engineering 82/09/17. EISENHUT.D Division of Licensing 1p 22/11/201 24X Fichs-50-289,63/10/27,8402060028
- --8210130553 Revision 1 to "TMI-1 Steam Centrator Repair Bafety Evaluation." Mithheld (ref 100FR2 790) GRAMAN M J General Public Utilities - GPU Bervice Corp TR-004 R01. 82/09/30 38pp. 22113 259. 24X Fiche: 50-289, 63/10/27, 8402040038
- -8210290116 Requests fuller explanation of encl DG Eisenhut 820809 ltr re performence of repaired tubes in event of transients k/or accidents during operation LEMISM I Lewis, M 82/10/25, EISENHUT, D, Q Division of Licensing 1p. 22112.160 24X Fiche.50-289,83/10/27.8402060028
- 3211070598 Forwards BMI final rept on failure analysis of tubes removed from TMI-1 steam generators. Enci rept supple BtW rept distributed on 820819 Repts 4td 820520 on radwaste sys retainer suam being distributed W/o enci MCCRACKEN.C Chamical Engineering Branch. 62/10/27 HENARDYA.V Chamical Engineering Branch 1p. 22111 233 24X Fiche: 50-289, 83/10/27, 8402040028

- --B21110543 Notifies of untimely Battelle request for extension of period of performance to 830391 for evaluation of steem generator corresion assessment Extension deadline not met due to late request submittal WU.P Chemical Engineering Branch FIN B-2506. 82/10/26 VOLLMER,R H Division of Engineering ip 22111 202 24X Fichs 50-289,83/10/27,8402040028
- --B212150120 Revision 1 to SER. "Assessment of TMI-1 Plant Safety for Return to Svc After Steam Generator Repair " Withheld (ref 10CFR2, 790) MBRAN.T.M Babcock & Wilcox Co ODB R01 B2/12/07 115pp 22113:305 24X Fichs 50-289, 63/10/27, 8402060028
- --8301060232 Forwards licensee 821207 safety assessment re restart subsequent to once-through steam generator repairs, for review Technical evaluation repts due by 830225 W/o safety assessment MCCRACKEN.C Chemical Engineering Branch 82/12/20, MACDONALD,D Dhio, State of 2pp 22112 294 24X Fiche 50-289, 83/10/27, RACOOACE
- --B301250628 Proprietary "TMI Unit & Once-Through Steam Constator Repair, Kinetic Expansion Technical Rept " Withheld (ref LOCFR2 790) MOORE, J P Babcock & Wilcox Co BAW-1760 B2/11/30 96sp. 22112 304 24X Fiche 50-289, 63/10/27, 8402060028.
- --8302020052 Responds to 830113 request to review util safety evaluation for return of facility to svc after steam generator repair. Response to encl questions necessary for completion of BER & EIA.

 CONSEL.F J Radiological Assessment Branch 83/01/25 VABSALLD.D Deperating Reactors Branch 2 3pp 22112:128. 24% Piche: 50~289, 83/10/27, 8402060028
- --8302020181 Forwards significant hazards determination on Steam Generator Recovery Program & review of licensee 821210 assessment of plant safety for return to svc Causative agent & potential sources identified. Hazard does not exist. VOLLMER, R H Division of Engineering 83/01/24 EISENHUT, D Q Division of Licensing, 13pp 22112-115, 24X Fiche. 50-289, 83/10/27, 8402040028
- --8303110519 Provides schedule re preparation of restart BER, subsequent to once-through steam generator repairs, due 830510 MCCRACKEN: C Chemical Engineering Branch, 83/03/08 FRANK, L. Materials Engineering Branch 2pp 22112, 131 24X Fiche 50-289, 83/10/27, 8402060028
- --8303280015 Forwards revised draft technical evaluation rept. "TMI Will 1 Stram Generator Degradation & Repair "
 AUERBACH. C Brookhaven National Laboratory FIN A-3380.
 83/03/24 TUROULIN.8 NRC NO Datailed Affiliation Given. 1)
 22111 166. 24X Fiche.50-289,83/10/27,8402060028.
- --8303280024 "TMI Unit ! Steam Generator Degradation & Repair," draft technical evaluation rept. BANDY.R Brookhaven National Laboratory FIN A-2380. 83/03/23 NRC - No Detailed Affiliation Given 15pp 22:11:167. 24x Fiche.50-289,83/10/27,8402060028
- --8303300416 Comments on schedule for SER submittal re facility strangemerator. Current estimated date for SER issuance is 830509.
 EIBENRUT, D. 9. Division of Licensing. 63/03/25 VOLLMER: R
 Division of Licensing. 1p 22112 261. 24x Fiche: 50-289.83/10/27.
 8402040028.
- --B30401004B Notifies that BNML requires period of performance extensite due to late completion of licenses repairs & delay in scheduling of hearing for Contract FIN B-2506. "Evaluation of THI-1 Steam Generator Cornosion" UV, P Chemical Engineering Branch FIN B-2506. B3/03/25. VOLLMER.R H. Division of Engineering. 2pp. 22112, 167. 24% Fichs. 50-289, B3/10/27, B402060028
- --8304050473 Forwards 83033; itr to V Gilinsky re collusion at facility Response to 820701 questions re microstructural characteristics of once-through steam generator tube matinot fully addressed in 821005 itr. Addl response requested. LEE: J Aprilation Nat Assigned 83/04/01. DENTON: H R. NRC We Datailed Affiliation Given. ip. 22112.162 24X Fiche 50-289:83/10/27,8402060028.
- ~-B304050478 Discusses B30328 public forum re mismanagement violations NRC should investigate charges alleged by RD Parks (Bechtel angineer) concerning lack of cooperation in disseminating info within NRC LEE: J Affiliation Not Assigned, B3/03/31. OILINBKY.V. Commissioners. 2pp. 22112.163 24X Fiche 30-289, 83/10/27. 8402060028.

į.

- --8304130440 Proprietary Rev 2 to "Assessment of TMI-1 Plant Safety for Return to Svc After Steam Generator Repair " Withheld (ref 10CFR2 790) MRRAN.T M Babcock & Wilcox Co 00B R02 83/03/30 169pp 22113 038 24X Fiche 50-209.83/10/27.8402060028
- --8304140047 Discusses schedule for SER submittal on steam generator Completion of SER by 830507 dependent upon receipt of all necessary info from licensee by 830405 meeting Outstanding issues listed VOLLMER, R. Division of Engineering 83/04/04 EISENHUT, Division of Licensing 2pp 22112 169 24X Fiche 50-289, 63/10/27, 8402050028 83/04/04 EISENHUT, D G
- --8304250292 Proprietary Rev 1 to "TMI-1 Once-Through Steam Generator Repair Kinetic Expansion Technical Rept " Withheld (ref 100FR2 790) MUDREJ P Babcock & Wilcox Co BAW-1740 R01 63/03/31 199pp 22114:050 24X Fiche 50-289,83/10/27,8402060028

- --8304270219 Forwards SER for restart subsequent to once-through steam generator tube repairs Actions taken, including 100% insp, preventive plugging & staking of critical tubes provide reasonable assurance defective tubes identified for repair LIAM, B. D. Materials Engineering Branch 83/04/20 BENARGYA, V. Chemical Engineering Branch 83/04/20 BENARGYA, V. Fiche. 50-289, 83/10/27, 8402060028
- --8304270275 Requests response to 8 listed questions submitted re regulatory connection.leak rates & tube walls Addl names of persons to contact submitted HDSSLER, D.E. Affiliation Not Assigned. 83/04/24 STOLZ, J.F. Operating Reactors Branch 4 2pp 22112 165. 24X Fiche 30-289, 83/10/27, 8402060028
- ---8304270371 Requests draft inputs to once-through steam generator SER by 830425. Inputs needed to meet 830509 scheduled restart SER completion.

 MCCRACKEN, C. Chemical Engineering Branch 83/04/21 FRANK, L. Machanical Engineering Branch 22112.178 24X Ficha 80-289,83/10/27,8402060028.
- --8304270380 Trip rept of 830413 fifth third-party review meeting in Parsippane, NJ re steam generators, NDT acceptable Minor recommendations on startup & insp procedures provided, BENAROYA, V Chemical Engineering Branch 83/04/21 JOHNBTON, W V Assistant Director for Matls, Chem & Environ Technology (Post 830201), 2pp 2212:137, 24X Fiche. 50-289,83/10/27,8402060028
- ---830519033B Forwards 830421 ltr to J Stol; re allowable steam tube leak rates on 790301 & current allowable leak rate Response not yet received.

 HOBSLER, D. E. Affiliation Not Assigned 83/05/16. DENTON, H R Office of Nuclear Reactor Regulation, Director ip. 22112, 259 24% Fiche: 50-289, 83/10/27, 8402040028
- --8305240101 Bubmits status of steam generator repair review SER input requested by 630520 EIBENRUT, D. Division of Licensing, 83/05/17, VOLLMER, R. Division of Engineering, 2pp 22112, 274 24X Fiche: 50-289, 83/10/27, 84020
- --B306010054 Discusses status of steam generator tube rupture guidelines & procedures review. Hatl presented during 630428 site visit greliminary w/consistencies & handwritten corrections Overall strategy & options must be clarified CLAYTON. H. B. Procedures & Systems Review Branch. 83/05/09 8TOLZ, J. F. Operating Reactors Branch 4 ip. 22112, 148 24X Fiche: 50-289, 83/10/27, 8402060028
- --B30A010480 Forwards Chemical Engineering Branch draft safety evaluation based on review of licensee 830209 submittal re post-accident sampling sys Licenses meets five of 11 criteria in NNREQ-0737. Item II. B 3.
 JOHNSTON, W V. Assistant Director for Matls, Chem & Environ Technology (Post 830201), 83/05/23. LAINAS.9. Assistant Director for Querating Reactors 11pp 22112-180. 24X Fiche 50-289,83/10/27,8402060028.
- --8306020287 Advises that steam generator repair 8ER will be issued i day following receipt of third-party review from licensee VOLLMER, R. H. Division of Engineering. 83/05/23 EIBENHUT, D. G. Division of Licensing ip 2212:191 24X Ficher 50-289, 83/10/27. 8402060028
- --8306030387 Forwards safety evaluation for raturn to svc after repair of once-through steam generator corrosion W/o BER. Proposed license conditions encl JOHNSTON.N. V. Assistant Director for Matls. Cham & Environ Technology (Post 830201). 83/05/24 LAINA8.9 C Assistant Director for operating Reactors 65pp 22112.192. 24X Fiche: 50-289, 83/10/27.8402060028

- --8306150573 Initial no significant halards consideration determination & noticing action re 830509 application for Tech Spec change to permit steam generator repairs by plugging or any method approved by NRC SILVER.H NRC No Detailed Affiliation Given 83/05/19 3pp 22112 276 24X Fiche 50-289.83/10/27.8402060028
- --8307150063 Informs that SER input on steam generator repair will not be submitted by 830520 Review will commence as soon as licensee inforre tube rupture procedures received THOMPSON.H L Division of Human Factors Safety 83/05/19 EIBENHUT,D G Division of Licensing ip 22112 179 24X Fiche 50-289,83/10/27.8402040028
- --8402060076 Summarizes 821018-17 meetings in Bethesda, MD re steam generator repair DODD,C V Oak Ridge National Laboratory 82/10/27 MCCLUNG,R W Oak Ridge National Laboratory 2pp 22112 033 24X Piche 50-289,63/10/27,8402060028
- --B402060243 Requests input for steam generator tube rupture procedures & guidelines review by 830509 Rev 2 to GPU Topical Rept 008.

 Section X encl
 STOLZ.JF Operating Reactors Brench 4 B3/04/11 CLAYTON B H
 Procedures & Systems Review Brench 12pp 22112 262 24X
 Fiche 50-289,83/10/27,8402060028
- 8402130478 Responds to FOIA request for SECYs 83-268, 271, 278, 281, 279, 305, 306 & 307 Forwards SECY 83-271, 83-278 & portions of five other SECYs as listed on App A. Info partially withheld (ref Exemptions 5 & 7)
 FELTON, J M Division of Rules and Records 83/11/28 WEISS, E R
 Harmon & Weiss 4pp 22237 220 24X Fiche 50-000, 83/11/28, 8402130498 Harmon & Weiss 8402130498
- --8402130538 Recommends that transcript of Commission 830621 meeting on TMI-1 restart be withheld in entirety under Exemptions 5 & 10 of Suunking Act FITZGERALD. J A Office of the General Counsel SECY-83-305 83/07/28 1p 22237 340 24X Fiche 50-000,83/11/28,8402130498
- --8402130544 Recommends that transcript of Commission 830330 meeting on pending investigations & possible enforcement action at TMI-1 be withheld in entirety under Examptions 5 & 7 of Sunshine Act FITZOERALD, J. A. Office of the General Counsel SECY-83-306 83/07/28 1p #2237 341 #24X Fiche.50-000,83/11/28,8402130498
- ---B402130549 Recommends that transcript of Commission B30606 meeting on pending investigations at TMI-1 be withheld in entirety under Exemptions 5 & 7 of Bunshine Act FITZOERALD. J A Office of the General Counsel SECY-83-307. 83/07/28 3pp R2237 342 24X Fiche. 50-000.83/11/28,8402130498
- 8312120027 Generic Ltr 83-39 to representatives of utils re voluntary survey of licensed operators, 8vc list encl EISEMHUT.D. Q Division of Licensing 83/12/08. Commonwealth Edison Co 12pp. 22313 006. 24X Fiche 50-000.83/12/08.8312120029
- 8402160003 Third partial response to FUIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILK/8 J. Office of the Secretary of the Commission 83/12/14 Public Document Branch 1p. 2288 B402160003
- ---8402160079 Staff requirements memo re 811106 discussion of TMI-1 restart in Hashington.DC.
 CHILK.S J Office of the Becretary of the Commission 81/11/09 BICKMIT.L Office of the Gameral Counsel 1p. 22281 031 24X Fiche 50-000,83/12/14.8402160003
- --8402160076 Btaff requirements memo re Bi1207 discussion of scheduling matters concerning TMI-1 restart in Washington.DC. CHILK.B J. Office of the Secretary of the Commission B1/12/14. BICKWIT-L. Office of the Cemeral Counsel REMICK.F. Office of Policy Evaluations ip 22281 036. 24X Fiche 50-000,83/12/14. 8402160003
- --8402160102 Staff requirements mamo re Bi1222 Affirmation Session 81-47 on TMI-1 restart order in Washington.DC CHILK.S J. Office of the Secretary of the Commission 81/12/28, BICKWIT,L. Office of the General Counsel 1p 22281.037 24X Fiche 50-000,83/12/14,8402160003
- --8402160123 Staff requirements memo re 820310 discussion of TM1-1 restart proceeding in Washington.DC CHILK.S J Office of the Secretary of the Commission. 82/03/11 BICKMIT,L. Office of the General Counsel ip. 22281 042, 24X Fiche 50-000, 83/12/14, 8402160003

- --B402160143 Discusses SECY-81-628 final GAO rept entitled "Greater Commitment Negded to Solve Continuing Problems at TMI "
 CHILK, B J Office of the Secretary of the Commission B2/01/27
 DIRCKS, W J Office of the Executive Director for Operations 1p
 22281 157 24X Fiche 50-000.83/12/14
- ---B402160151 Discusses SECY-B1-643 re TM1-1 «cheduling order CHILK: B J Office of the Secretary of the Commission 81/11/27 BICKHIT.L Office of the General Counsel ip 22281 130 24X Fiche 50-000, B3/12/14, 8402160003
- --8402160166 Discusses SECY-81-660 re TMI-1 restort hearing stipulation on witness confidentiality CMILK.S J Defice of the Secretary of the Commission 81/12/02 BICKWIT.L Defice of the General Counsel ip 22881 133 24x Fiche 50-000,83/12/14.8402160003
- --8402160287 Discusses SECY-82-16A re TMI-1 psychological impact decision & litigation strategy CHILK,8 J Office of the Secretary of the Commission 82/02/25 BICKMIT.L Office of the General Counsel Ip 22281 160 24X Fiche 50-000.83/12/14.8402160003
- --8402160311 Discusses SECY-82-394 re oral presentations on TMI restart CHILK-5 J Office of the Secretary of the Commission 82/10/19 Office of the Secretary of the Commission 1p 22201 233 24X Fiche 50-000.83/12/14.8402160003
- ---8402160317 Discusses SECY-82-384 re status of TMI-1 NUREO-0737 items CMILK.S J Office of the Secretary of the Commission 92/10/19 DIRCKS.W J Office of the Executive Director for Operations 1p 22281 234 24X Fichs 50-000,83/12/14.8402160003
- --8402160376 Discusses BECY-83-147 re immediate effectiveness decision HOYLE, J.C. Office of the Secretary of the Commission B3/05/05 PLAINE, H. H. Office of the General Counsel 1p 22281 283 24X Fiche 50-000, B3/12/14, 840216003.
- --8402160393 Discusses SECY-82-384A re status of TMI-1 NUREG-0737 items CHILK.8 J Office of the Secretary of the Commission 83/01/05 DIRCRS W Office of the Executive Director for Operations 1p 22281 253 24X Fiche 50-000
- --B40RJ60407 Discusses SECY-B3-7 re immediate effectiveness decision in light of ALAB-708 CHILK, B J Office of the Secretary of the Commission B3/01/13 Office of the Secretary of the Commission ip 22281 256 24X Fiche 50-000, B3/12/14, B402160003
- ---B402160412 Discusses SECY-B3-10 re psychological stress, litigation strategy in Pane vs NRC
 CHILM 9 J Diffice of the Secretary of the Commission 83/01/14
 DIRCKS, W Office of the Executive Director for Operations
 ROTHBC
- 8402030047 Provides Commission w/info re detection of PDRV corresion & corrective actions PORV refurbished w/fully qualified noncorreded parts & is now acceptable DIRCKS.N J Office of the Executive Director for Operations BECY-94-010 84/01/09 4pp 22091 081 24% Fichs 50-289,84/01/09,
- 8402010444 Responds to FOIA request for SECY-83-288 & SECY-83-443 to be placed in PDR SECY-83-288 available in PDR SECY-83-443 being placed in PDR Forwards SECY-83-443 FELTON, J M Division of Rules and Records 84/01/17 YENDUSKAB, J Newman & Holtzinger ip 28061 272 24X Fishe 50-000, 84/01/17, 8402010444
- --8402010453 Informs Commission of info obtained re flux reduction programs for pressurized thermal shock at lead plants, since 830225 interim rept (SECY 83-077)
 DIRKKR, W J Office of the Executive Director for Operations SECY-93-443 83/10/28 IIpp 22061-273 24X
 Fiche 50-000,84/01/17,8402010444
- 8402030039 Staff requirements memo re 840116 discussion on corrosion in PORVs & corrective action Gommission audits ARC rept on need for PORVs in C-E plants & requests early estimate of rept availability GHILM-8 J Office of the Secretary of the Commission. 84/01/17 DIRCKS.W J Office of the Executive Director for Operations is 22091 091 24X Fiche 50~289.84/01/17.8402030039
- B312120136 Board Notification 84-011.discusses NRC use of terms "important to safety" & "safety-ruleted" EISENHUT.D G Division of Literating B4/01/18 PALLADING Commissioners 72pp. 22241.008 24X Fiche 50-000,84/01/18, 312120134

- B402010224 Requests add1 info re emergency feedwater flow indicators, per util B31623 ltr Info tracked under Restart Certification ltems 5 & 82
 STOLZ.J F Operating Reactors Branch 4 B4/01/18 HUKILL.H D General Public Utilities OPU Service Corp 5pp 22047:325 241 Fiche 50-289,84/01/18.8402010224
- 8402070232 Forwards application to amend License DPR-50, consisting of OL Change Request 133 removing 100 mCi limit on byproduct, source or SNA HUKILL, H D General Public Utilities OPU Service Corp. 84/01/26 81012, J F Operating Reactors Branch 4 1p 22101 190, 24% Fiche 50-289,84/01/26,8402070252
- --8402070237 Application to amend License DPR-50, consisting of OL Carp Request 133 removing 100 mCi limit on byproduct, source or SNM # General Public Utilities - GPU Service Corp R4/01/24 4ee
 - 4 General Public Utilities GPU Service Corp B4/01/26 4pp 22101 191 24X Fiche 50-289,84/01/26,8402070252
- --8402070260 Proposed Tech Spec change removing 100 mCi limit on byproduct.source or SNM * General Public Utilities OPU Bervice Corp. 84/01/26 lp 22101 195 24X Fiche 50-287.84/01/26,8402070252
- 8402030041 Notification of 840130-31 meetings w/util in Middletown.PA to review implementations of selected NUREO-0737 items VAN VLIET Operating Reactors Branch 4 84/01/27 STOLI, J F Operating Reactors Branch 4 2pp 22091
- B402030233 Forwards "Considerations in Low Operation of TMI-1." Whis proposes consideration of 48% of full power as praferred restart power level if initial lower power required HUKILL.H D General Public Utilities OPU Service Corp. B4/06/27 STOLZ.J F Operating Reactors Branch 4 ip 22067 164 24% Fiche 50-287.64/01/27.8402030233
- --8402030245 "Considerations in Low Power Operation of YMI-1" * # General Public Utilities GPU Service Corp 83/12/12 9pp 22067 165 24% Fiche 50-269.84/01/27,8402030233
- 8402070417 Ack receipt of 840120 2 206 petition requesting Commission action to suspend OL Unless emergency feedwater sys modified Request based on info re sys ability to mitigate DBE for which main feedwater sys unavailable DENTON.H R Office of Nuclear Reactor Regulation, Director 84/01/27 WEISS.E R Harmon & Weiss 6pp 22185 351, 24% Fiche 50-289,84/01/27,8402090417
- --8402090424 Notice of UCB request for action under 10CFR2.206.suspensive facility GL until emergency feedwater sys modified DENTON.H R. Office of Nuclear Reactor Regulation, Director. 84/01/27 ip 22:185:357 24X Fiche 50-289.84/01/27.8402090447
- 8402170181 Board Notification 84-002A forwards info re THI-1 restart hearing concerning cheating or preemployment psychological axams inadvartently emitted from Board Notification 84-002. EISENHUT. D @ Division of Licensing 84/01/30 PALLADINO, GILINSKY, ROBERTS Commissioners 7pp 22313 275. 24X Fichs 50-289,84/01/30,8402170181
- 8402080215 Forwards response to questions in detailed design description & intermediate sys design description per TMI I F.2 & "RCB Coolent Inventory Trending M/Reactor Coolent Pumps Operating " Encl withheld (ref 10CFR2.790). HUKILL.H B. General Public Utilities OPU Service Corp B4/01/31 STOLZ.J.F. Operating Reactors Branch 4 2pp. 22130:102. 24X Fiche 50-289.84/01/31.8402080215
- B402080232 Provides status of Commission paper on PORVs in C-E plants per 840116 briefing on corrosion in PORVs at TMI-1 Final rept will be sent to Commission by 840305 DIRCKS, W J. Office of the Executive Director for Operations. 84/01/31 CHILK.9 J Office of the Becretary of the Commission 3pp. 22169,005 24X Fiche 50-289,84/01/31,8402080232
- 8402010410 Generic Ltr 84-04 to all operating PWR licensess, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/ellmination of postulated pips breaks in PWR primary main loops 8vc list encl.

 EISENHUT: D 9 Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc. 59pp 22177.087 24X Fiche. 50-000, 84/02/01, 8402010410
- B402060388 Forwards corrected estimated schedule for util activities in response to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Balem ATMS Events " Typographical error in B31108 ltr corrected.

 HUKILL.H.D General Public Utilities GPU Bervice Corp. 84/02/01 E18EN.HUT.D 0 Division of Licensing. 2pp 22086,328 24X Fiche 50-289,84/02/01,8402060388

ŧ

1

- 840207029: Clarifies Topical Rept TR-008 re acceptability of steam generators to return to svc Conclusion that tubing left in svc acceptable for continued use, based on results of previously conducted addy current insps.

 HUKILL.H D Qeneral Public Utilities OFU Bervice Corp 84/02/02
 DEANTON.H R Qefice of Nuclear Reactor Regulation, Director 2pp 24X Fiche 50-289,84/02/02,8402070291
- 8402070350 Submits summary of background & bases for 831221 ltr reiterating request for approval to complete hot functional test program CLARK, P.R. General Public Utilities — OPU Service Corp. 84/02/02 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 22097-042. 24X Fiche 50-289,84/02/02,8402070350
- B402140340 Summarizes 840113 telcon re deletion of Tech Spec raquirement for operability of air intake tunnel deluge sys when Halon sys inoperable HUKILL-N D. General Public Utilities - GPU Service Corp 84/02/07 ETOLZ.J.F Operating Reactors Branch 4 2pp 22219 344 24X Fichs. 50-289, 84/02/07.8402140340
- 8402240199 Responds to FOIA request for SECY-83-404 to be placed in PDR. Forwards SECY Document also available in PDR FELTON, J M Division of Rules and Records 84/02/07 BUCKLEB.R NUS Corp ip 22381 289 24X Fichs 30-289, 84/02/07,8402240199
- --B402240200 Advises Commission of evaluation of thiosulfate contamination & PORV corrosion problem at TNI-1, as requested in 8 Chilk 830810 memo stemming from ALAB-724 DIRCKB.W.J Office of the Executive Director for Operations BECY-83-404, 83/09/30 2pp 22381-270 24X Fichs. 50-289, 84/02/07, 8402240199.
- 840224008: Partial response to FOIA request for records arising out of insps of TMI-1 & 2 re detection of measurement of RCS leakage. App A documents available in PDR Forwards App B documents. Review of add1 records subj to request continuing FELTON, J.M. Division of Rules and Records. 84/02/08 MADDEN, T. J. Kaye. Scholer, Fierman, Hays & Handler App 22394 277 24% Fiche, 50-289, 84/02/08, 8402240081.
- --8310200329 Forwards technical evaluation of OPU analysis of PORV tailpipe temps & PORV leakage, per B30825 request Analysis reasonable Evidence convincing that one safety valve leaking in Feb-Mar 1979 time frame MATTBON.R J. Division of Systems Integration (post 811005). 83/10/12. E18ENHUT.D 0 Division of Licensing. 4pp 22394-292 24X Fichs.50-289.84/02/08.8402240081
- --8402240099 Submits historical background of data accumulated & list of current action items.in response to NRC 800114 ltr re reactor bldg sump level & RCS makeup sys leakage. Table encl WILBON.R. F. Metropolitan Edison Co WILBON.R. F. General Public Utilities QPU Bervice Corp 84/02/08 COLLINS,J T TMI-2 Operations/8upport Task Force 3pp 22394 281 24X Fiche: 30-289,84/02/08,8402240081
- B402160014 Forwards application for amend to License DPR-50, consisting of Tech Spec Change Request 137 re installation of RCS vents per NUREO-0737, Item II. B. 1 & Generic Ltr 83-37 HUKILL, H D General Public Utilities GPU Service Corp 84/02/09 STOLZ, J. F Operating Reactors Branch 4 1p. 22275 222 24X Fiche: 50-289, 84/02/09, 8402160014
- --8402160023 Application for amend to License DPR-50, consisting of Tech Back Change Request 137 re installation of RCB vents per NAREQ-0737, Item II. B. 1 & Generic Ltr 83-37. HWRILL H.D General Public Utilities - GPU Service Corp. 84/02/09. 2pp. 22275-223. 24X Fiche 50-289,84/02/09,8402160014
- --B402160029 Proposed Tech Spec re installation of RCG vents per NUREQ-0737, Item II.B 1 & Generic Ltr 83-37 **Oeneral Public Utilities - OPU Service Corp 84/02/09 7pp. 22275-225. 24% Fiche. 50-289,84/02/09,8402160014.
- 8402160323 Requests backup or supporting info re IE evaluation of RCS lask rate test procedures & calculation methods at Racho Seco & Davis-Besse in use in 1978.

 HUM H.L. H D Qeneral Public Utilities QPU Service Corp. 84/02/10 DEYOUNG.R C Director's Office, Office of Inspection and Enforcement. 1p. 22277:007. 24X Fiche 50-289,84/02/10.8402160323
- 8402160395 Provides resolution & justification for continued operation w/defective components identified in NRC SER/technical evaluation rept dtd 821210 re environ qualification of electrical equipment.

 HUKILL, H D General Public Utilities GPU Service Corp. 84/02/10. STDL7.J.F. Operating Reactors Branch 4 12pp 22269.084, 24X Fiche. 50-289, 84/02/10, 8402140395.

- 8401190059 Board Notification 84-032 provides add1 info on environ qualification Submittal augments info in Board Notifications 84-004 & 64-007 EISENHUT, D © Division of Licensing 84/02/13 Atomic Safety and Licensing Board Panel 10pp 22314 204 24X Fiche 50-000.84/02/13.8401190059
- 8402240112 Forwards application to amend License DPR-50, consisting of Tech Spec Change Request 130 re backup in-core thermocouple display operability, per NUREG-0737. Item II F 2 HUKILL. H D General Public Utilities OPU Service Corp 84/02/13 STOLZ. J F Operating Reactors Branch 4 1p 22373 276 24X Fiche 50-289,84/02/13,8402240112
- --8402240116 Application to amend License DPR-50.consisting of Tech Spec Change Request 130 re backup in-core thermocouple operability HUXILLH D General Public Utilities - GPU Service Corp 64/02/13 2pp 22373 297 24X Fiche 50-289.84/02/13.8402240112
- --B402240122 Tech Spec Change Request 130 re current status of backup in-core thermocouples.per NUREO-0737.Item II F 2 HUKILL,H D General Public Utilities - GPU Service Corp 84/02/13 3pp 22373 297 24X Fiche 50-289.84/02/13.8402240112
- 8402270369 Further response to FOIA request for all 1982 SECY papers Forwards SECYs 82-16D, 82-49, 82-61, 82-113A & 82-131 Info partially withhold (ref FOIA Exemption 5) Documents also available in PDR.
 FELTON, J M Division of Rules and Records 84/02/13 WEISS, E R Union of Concerned Scientists Spp 22411 271 24x Fiche 80-000,84/02/13,8402270369
- --B402270375 Provides preliminary analysis of opinions issued on 820514 by DC Circuit in Pane vs NRC re psychological effects of restarting Pacility Info deleted MALSCH.M 6 Office of the General Counsel SECY-82-016D 82/05/24 100pp 22411 275 24X Fiche 50-000,84/02/13,8402270369
- B402230128 Advises that B&W transmitted info re pressurized thermal shock flux reduction fuel mgt to J Carew in 840202 ltr HUKILL, H D General Public Utilities - GPU Service Corp 64/02/15 BTOLZ, J F. Operating Reactors Branch 4 lp 22341 206 24X Fiche: 50-289, 84/02/15, 8402230128
- 840119006B Board Notification 84-033 provides "Bys Interaction Program," task action plan for Unresolved Bafety Issue A-17. Distribution list enci EIBENHUT.D 0 Division of Licensing 84/02/16 PALLADINO, GILINBKY, RUBERTS Commissioners 8pp 22482 091 24X Ficher 50-000.84/02/16.8401190068
- 8402230173 Furwards table showing status for submitting Tech Spec change request for long-term NUREO-0737 items, in response to Oeneric Ltr 83-37.

 HUKILL H D. General Public Utilities GPU Bervice Corp 84/02/16
 EIBENHUT.D 0 Division of Licensing 3pp 22361, 230. 24X

 Fiche 50-289,84/02/16.8402230173
- B40227002B Forwards results of avaluation of reactor bldg polar crans design & special lifting device design condenations Bchedule of actions taken & planned to resolve heavy loads issue encl HUKILL: H.D. General Public Utilities GPU Service Corp. 84/02/21 EISENHUT.D Q Division of Licensing 4pp 22388 001 24X Fiche 50-289.84/02/21.8402270028
- --B402270031 "Evaluation of Heavy Load Handling Operations at TMI-1.
 Responses to NRC Requests in Technical Evaluation Rept
 Transmitted Bilo21."
 HLADIK,M., GEORDE,H. Gansral Public Utilities -- GPU Service Corp
 84/01/04 94pp 22388,005 24X Fiche 50-289,84/02/21,8402270028
- 8402280275 Forwards justification for continued operation & revised Page 3 of Attachment II of 840210 submitted re environ qualification of electrical equipment inadventently omitted, HUKILL, H D. General Public Utilities OPU Service Corp. 84/02/22 STOLZ, J F. Operating Reactors Brench 4. 3pp. 22347 210 24X Fiche, 50-289, 84/02/22, 8402280275
- B4022803B7 Requests extension until B40227 to respond to NRC B40127
 Itr re UCB petition for show cause concerning emergency
 feedwater
 HUKILL,H D. General Public Utilities QPU Service Corp. 84/02/22
 BENTON,H R. Office of Nuclear Reactor Regulation, Director. 2pp.
 22402,255, 24X Fiche 50-287,84/02/22,8402280387

- 8402280391 Forwards results of emergency feedwater sys flow instrumentation oscillations at low flow condition, in response to 840118 ltr HUKILL.H D General Public Utilities ~ 0PU Service Corp 84/02/22 STOLZ.J F Operating Reactors Branch 4 3pp 22402.259 24X Fiche. 50-289,84/02/22,8402280391
- B402280381 Forwards revised master restart schedule, revised to include work on reactor coolant pump 18 prior to precritical non-nuclear hot functional testing HUKILL.W D General Public Utilities OPU Service Corp BA/02/23 DENTON.W Office of Nuclear Reactor Regulation, Director 22402 232 24% Fiche 50-289, 84/02/23, 8408280381
- G. Inspection reports. IE Bulletins & correspondence
- 8402240067 FOIA request for documents arising out of insps of THI-1 or 2 re detection or measurement of RCB leakage & compliance w/regulatory requirements concerning recordisepting MADDEN.T J Kaye, Scholer, Fierman, Hays & Handler 83/12/27 NDRRY,P © Office of Administration 2pp 22394 275 24X Ficha 50-289,83/12/27,8402240067
- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 630103) 84/01/25 Consolidated Edison Co of New York Inc 120pp 22058 001 RAX Fiche: 50-000.84/01/25.8312120153
- 8402070168 Ack receipt of 831219 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-289/83-28 Commitment to ravise Radiological Controls Procedure 1627 to include GC adequately addresses concerns MARTIN.T T Region 1. Office of Director 84/01/26 HUKILL.H D Caneral Public Utilities GPU Service Corp. 2pp 22101 103 24X Fiche 50-289.84/01/26.8402070168
- ---8402070175 Responds to NRC 831116 ltr re violations noted in IE Insp Rept 50-289/83-28 Corrective actions GA procedure for effluent monitoring will be revised to meet guidance in Reg Guide 4 15 HUKILL.H D General Public Utilities - GPU Service Corp 83/12/19 MURLEY, J E Region 1. Office of Director 5pp 22101 105 24X Fiche 50-289.84/01/86.8402070168
- B401190016 IE Info Notice B4-07, "Design-Basis Threat & Review of Vehicular Excess Controls." By: list encl.
 JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/03 Consolidated Edison Co. of New York, Inc. 119pp 22114 179. 24X Fiche; 50-000, 84/02/03, 8401190016
- B401190017 IE Bulletin B4-01, "Cracks in BWR Mark I Containment Vent Headers," Svc list encl DEYOUNG R C Director's Dffice, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Go of New York, Inc 102pp. 22177 156 24x Fiche: 50-000,84/02/03,8401170017.
- B402080150 Forwards maths re adequacy of emergency planning at facility, including IE Insp Rept 50-289/83-35 which sets forth findings & conclusions of staff who observed exercise & INPO 831128 It re findings.

 ZAHLER, R. E. Shew, Pittman, Potts & Thoubridge. ZAHLER, R. E. Netropolitan Edison Co 84/02/03 CHILK, 8 J Qefice of the Secretary of the Commission 24pp 22132 231. 24X Fichs 50-289,84/02/03,8402080150.
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection 8afe Shutdown 8ys (100FR50, App R) " Syc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Past 830103) 84/02/13. Consolidated Edison Co. of New York, Inc. 124pp, 22365 239 24% Fiche. 30-000.84/02/13, 8401190041
- 8402170140 Clarifies fire protection plan ray implementation, per 840107 ltr & IE Insp Rept 50-289/83-16 Current & new fire brigade mumbers will be trained as listed MUKILL.H.D. General Public Utilities GPU Service Corp. 84/02/13. 870LZ.J.F. Operating Reactors Branch 4 MURIEY.T.E. Region 1. Office of Director. 2pp 22299'006 24X Fiche: 50-289, 84/02/13. 8402170140.
- 8402210217 Ack receipt of 831222 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-289/83-30. Disputes util belief that further testing re Krypton gas floupath unnecessary.

 STAROSTECKIR. Division of Project & Resident Programs. 84/02/13 HUKILL, H D General Public Utilities GPU Service Corp. 2pp. 22316:108 24% Fiche: 80-289:84/02/13.8402210217.

- --8402210219 Responds to NRC 831129 ltr re violations noted in IE Insp. Rept 50-289/83-30 Corrective actions loap seals reestablished in leaking floor drains & drain line at bottom of elevator shaft will be permanently capped HUKILL.H D General Public Utilities GPU Service Corp 83/12/22 STAROSTECKI,R Division of Project & Resident Programs App 28314 110 24X Fiche 50-289,84/02/13.8402210217
- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '"
 Svc list encl
 JDRDAN-E L Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- B402270325 Forwards 1E Insp Rept 50-289784-03 on 840116-20 Deficiently identified re pust-accident sampling & analysis Conference will be held on 840223 to resulve deficiencies MARTIN, T T Division of Engineering & Technical Programs. HUXILLH B © General Public Utilities GPU Service Corp 22426-332 24X Fiche-50-289,84/02/14,8402290325
- --8402290028 IE Insp Rept 50-289/84-03 on 840116-20 Deficiencies identified re provision for post-accident sampling & analyses Major areas inspected post-accident sampling of reactor coolant & containment atmosphere MILLER.M T , SHANBAKY,M M Region 1, Office of Director. HULL,A P Brookhaven National Laboratory 84/02/09 20pp 22426 334 24X Fiche 50-289,84/02/14,8402290325
- 8401190045 IE Info Notice, 83-63 Suppl 1, "Potential Failures of Westinghouse Type 8A-1 Differential Relays" Svc list encl JURDAN, E L. Division of Emergency Preparedness & Engineering Response (Poet 830103) 84/02/15 Consolidated Edison Co of New York, Inc 118pp 22366 142 24X Fiche 50-000, 84/02/15, 8401190045
- B4022B0724 Notification of Significant Licenses Meeting 84-17 on B40223 w/util in Middletown,PA to discuss deficience is in post-accifent sampling & analysis sys identified in IE Insp Rept 50-289/84-03 MILLER,M Region i. Office of Director 84/02/15 Region i. Office of Director 3pp 22414 345 24X Fiche 50-289,84/02/15,8402280724
- 8401170062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl.

 JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc. 116pp 22366 024 24x Fiche 30-000.84/02/21,8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies,"

 Bvc list encl

 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Fost 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 1159. 22430 304 24X Fichs 50-000,84/02/24,8401190066
- B401190067 IE Info Notice B4-12, "Failure of Boft Beat Valve Semis"
 Bvc list and
 JORDANNE L Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/27. Consolidated Edison Co. of New
 York, Inc. 120pp 22431'060 24X Fiche.50-000.84/02/27.8401190067
- R Pariodic operating reports & related correspondence
- 8402030452 Provides quarterly status rept on steam generator tubing long-term corrosion tests Written update delayed to include encl Mestinghouse "Long-Term Corrosion Test Program of Nuclear Steam Generator Tubing Bamples From TMI-1."

 HUKILL, H D General Public Utilities QPU Service Corp. 84/01/31 STGLZ.J F Operating Reactors Branch 4 2pp 22045 180. 24X Fiche 30-289,84/01/31,8402030452
- ---8402030487 "Long-Term Test Program of Nuclear Steam Generator Tubing Bamples From TMI-1," first interim rept. * Westinghouse Electric Corp 83/10/31 184pp 22065.182. 24X Fichs.50-889.84/01/31,8402030452
- 8402230129 Monthly operating rept for Jan 1984.W/840215 ltr SMYTH.C W : HUKILL:H D General Public Utilities - OPU Service Corp 84/01/31 KCDDNALD:W C Record Services Branch (Document Control Desk). 11pp 22352:341, 24X Ficher 50-289.84/01/31.8402230129
- S Reportable occurrences. LERs & related correspondence
- B402010491 Responds to FOIA request for SECY-B3-318 & AEOD/TG16 to be placed in PDR. Forwards documents Info partially deleted (ref FOIA Exemption 5) AEOD/TG16 available in PDR FELTON, J M Division of Rules and Records. 83/11/15 GRABER, L. D NUS Corp Rpp. 22060 339. 24X Fiche. 50-289, 83/11/15,8402010491.

- --B306240184 Forwards AEOD/T316 "Thermal Nonrepeatability Problem W/Barton Model 763 & 764 Electronic Transmitters "Problem adequately addressed since manufacturer issued Part 21 repts to alert Users of transmitters & IE planning info notice CHIRAHALM Reactor Operations Analysis Branch 83/05/31 BEWERTI, KV Reactor Operations Analysis Branch 4pp 22060 344 24X Fiche 50-287,83/11/15.8402010491
- 8402030356 LER 83-041/99X-0 on 831025, while in cold shutdown, cracking observed on molded rubber seat ring of containment purge isolation valve AH-VIB Caused by insufficient adhesion between plies of seat mat1 W/840104 ltr 8TEPMENSON.C.J. HUKILL.H D General Public Utilities - OPU Service Corp 84/01/04 MURLEV.T E Region 1. Office of Director 9pp 22049 171 24X Fiche 50-289,84/01/04.8402030356
- 8402080246 LER 83-047/03L-0 on 83:219, two cable fire seals identified w/no fire barrier seal matl inside conduits Caused by procedure error Seals repaired W/840123 ltr SICZECH.R A , HUKILL,H D General Public Utilities GPU Service Corp 64/01/23 MURLEY.T E Region i. Office of Director 4pp 22134:R43 24X Fiche 80-289,84/01/23,8402080246
- 8402140323 Revised LER 83-046/01T-1 on 831214.nuclear safety-related circuit for make-up pump lube oil pressure trip found incorrectly routed Caused by design oversight Circuits for make-up pumps rerouted in raceways W/840131 ltr
 HUMILL.H D. General Public Utilities OPU Service Corp 84/01/31
 HUMILLYT E Region 1, Office of Director 4pp 22219 338 24X
 Fiche 50-289.84/01/31,8402140323

T Hearing transcripts on non-antitrust matters

- 8402090015 Requests clarification of NRC 830624 response to FOIA 83-320 request within 5 working days
 DETUEN, J Philadelphia Inquirer, Philadelphia, PA 83/08/10 FELTON, J M Division of Rules and Records 1p 22189 279 24X
 Fichs 50-289,83/08/10,8402090015
- 8402090010 Appeals denial of FOIA request for transcripts of NRC closed meatings held between 810827 & 830810 re restart.
 YANER, A C Kohn, Milstein, Cohen & Hausfeld 83/10/03 Office of the Secretary of the Commission 2pp 22187:274 24X
 Eicht 50-289,83/10/03,8402090010
- 8402090026 Responds to appeal re denial of FOIA request for transcripts of ARC meetings held between 810821 & 830510 concerning restart at TMI-1. Forwards portions of Transcript 18 CHILK, B. J. Office of the Becretary of the Commission 83/12/20 YAHNER, A. C. Kohn, Milstein, Cohen & Hausfeld 3pp 22189 282 24X Fiche: 50-289, 83/12/20, 8402090026
- ---8402090050, Transcript of Commission 830415 discussion in Washington, DC re steps on decision to restart TMI-1 Pp 1-16 Portions deleted.

 Commissioners. 83/04/15 17pp. 22189 285. 24X Fichs: 50-000, 83/12/20, 8402090026
- 8402090085 Trenscript of 840127 public hearing in Washington, DC repossible vote on memo on future steps in restart, Pp 1-18 Supporting documentation encl * Commissioners, 84/01/27 33pp 22189-145 24X Fiche 50-289, 84/01/27, 8402090085
- 8402100191 Commission determination statement releasing encl portions of B31208 closed meeting transcript re strategies for potential litigation on facility steam generators. Deleted portions withheld (ref 10CFR9, 108(a)(10)).

 CHILK, B. J. Office of the Secretary of the Commission 84/02/03 Public Document Branch. 1p 22205, 120 24X Fiche 50-289, 84/02/03, 8402100191.
- --8402100195 Transcript of 831208 closed meeting in Washington, DC restrategies for potential litigation on TMI-1 steam generators. Pp 1-62 Portions deleted (ref 10CFR9, 108(a)(10)). Commissioners 83/12/08 64pp 22205:121. 24X Fiche. 50-289, 84/02/03.8402100191
- 8402170007 Testimony of NJ Palladino to Subcommittee on Energy & Environ re NRC budgeting request for FV85. PALLABING.N.J. Commissioners. 84/02/09. 42pp 22319:158 24X Fiche:30-289.84/02/09.8402170007.
- --B402170024 Testimony of JK Asselstine to Subcommittee on Energy & Environ re need to extend NRC authority to issue temporary OLs & review no significant hazards determination for steam generator repairs at TMI-1.

 ASSELSTINE, J K. Commissioners 84/02/09. 4pp 22319-203 R4X Fiche: 50-289, 84/02/09, 8402170007

U Congressional/Executive Correspondence

- B402270002 Responds to FOIA request for correspondence NRC received from Senators J McClure, JB Johnston & P Laxait during past 2 yrs Forwards App A documents Name of individual deleted from Documents B & 9 of App A (ref FOIA Exemption 6) FELTON, J M Division of Rules and Records B3/11/30 KQLI, E Cable News Network, Inc 6pp 22438 002 24X Fiche 50-000. 83/11/30, 8402270002
- --B402290121 Forwards "Rept of Special Master in TMI-; Restart
 Proceeding " M/o enci
 KAMMERER: C Office of Congressional Affairs 82/04/29
 OTTINGER: R L House of Rep , Energy & Commerce BEVILL, T House
 of Rep , Appropriations HATFIELD, M Senate, Appropriations 1p
 22438 036 24X Fiche 50-000, 83/11/30,8402290002
- --B402290318 Forwards NRC orders re facility restart proceedings W/o encis
 KAMMERER.C Office of Congressional Affairs 83/10/07
 OYTINGER.R L House of Rep , Energy & Commerce BIMPSON Senate,
 Environment & Public Works UDALL House of Rep , Interior &
 Insular Affairs ip 22438 125 24X Fiche 50-000,83/11/30,
 R402290002
- 8402060111 Responds to 831216 ltr re constituent F Taylor concerns on factlity restant Issue of OPU mgt competence & integrity will be resolved to Commission satisfaction prior to restart
 DIRCKS,W J Office of the Executive Director for Operations 84/01/25 WALKER,R B House of Rep 3pp 22092 025 24X Fiche 30-289,84/01/25,8402060111
- --B402060116 Forwards repts on behalf of F Taylor, re new emergency feedwater flow instruments & mgt objectives on restart of facility Pertinent info requested WALKER, R B House of Rep 83/12/16 PALLADING, N Commissioners 2pp 22092 032 24X Fiche 50-289,84/01/25,8402060111
- --B402060120 Raises several issues re GPU request for Commission approval of facility restart Issues include util mgt competency & integrity UDALL, M K House of Rep , Interior & Insular Affairs 83/12/06 PALLADINO, N Commissioners 3pp 22092 041 24X Fiche 30-289,84/01/25,8402060111
- 8402280691 Responds to 840201 comments on UCS patition re emergency feedwater sys
 DIRCKS,W J Office of the Executive Director for Operations 84/02/22 WALKER,R B House of Rep 2pp 22700 228 24X
 Fiche 50-289,84/02/22,8402
- --840R280695 Forwards UCS 840120 petition for show cause re emergency feedwater sys Info re sys safety requested WALKER, R. 8 House of Rep 84/02/01 PALLADINO, N. Commissioners ip 22416-292 24X Fiche 50-289,84/02/22,840R280691

DOCKET 50-293 PiloRIM NUCLEAR POWER STATION, UNIT 1

F. Becurity, medical, emergency & fire protection plans

- B402020352 Forwards IE Safeguards Insp Rept 50-293/83-25 on 831114-10 No violations noted MARTIN,T T. Division of Engineering & Technical Programs. B3/12/30 MACCORMACK-E R Boston Edison Co 2pp 22052-118 24X Fiche: 50-293
- --8402020356 IE Bafeguards Insp Rept 50-273/83-25 on 831114-18. No violations noted. Major areas inspected communications, security program audit & organization, testing & maint, physical barriers, assessment aids & access control.
 BAILEY, R. J., MADDEN, W., GUDY, A. T., Region i. Office of Director 83/12/27. 5pp 22052 120 24X Fiche 50-273,83/12/30,8402020352
- 8402090253 Forwards Rev 14 to modified amended security plan Rev withheld (ref 10CFR73 21)
 HARRINGTON, W D. Boston Edison Co 84/01/30 MURLEY, T. E Region 1.
 Office of Director ip 22157 361 24X Fichs. 50-273, 84/01/30, 840
- 8402130341 Advises that incorrect Title 10 ref source provided in Paragraph 3 of 840112 ltr designating Encl 1 as safeguards info Proper ref should be 10CFR2 790(d)(1) HARRINGTON, W D. Boston Edison Co 84/02/08 VASSALLO, D B. Operating Reactors Branch 2 lp 22197 127 24x Fiche. 50-293, 84/02/08, 8402130341.

- 8402270271 Responds to Confirmatory Action Ltr 84-03 re contamination of personnel exceeding quarterly extremity dose limits Communications between health physics personnel improved as result of 840118 eversposure HARRINGTON.W D Boston Edison Co 84/02/15 8TAROSYECKI.R Division of Project & Resident Programs 21pp 22386-284 24X Fiche 50-293.84/02/15.8402270271
- 9 Adjudicatory correspondence
- 8402070003 Forwards suggestion of mootness between licensee, NRC &
- J Doherty CHAN,E I Hearing Branch 2 84/01/25 COTTER,B P , PARIS,O H , LINENBERGER,O Atomic Safety and Licensing Board Panel 1p 22102 328 24x Fiche 50-293,84/01/25,8402070003
- --8402070004 Suggestion of mootness & request for order dismissing proceeding Licenses will file new application for amend permitting one loop operation at power levels not to exceed 50/ Full page. permitting one loop operation of permitting one loop operation of permitting one loop operation of the permitting one loop operation of the permitting of the permitting
- J Insurance & indomnity information
- 8403210227 Forwards Endorsements 82.83.84 & 85 to NELIA Policy NF-188 & Endorsements 66,67.68 & 69 to MAELU Policy NF-38 SINISI.J M Marsh & McLennan, Inc. 84/02/14 SALTZMAN.J Assistant Director for State & Licensee Relations 9pp 22316 154 24X Fiche 50-273.84/02/14.8402210227
- P Operating license stage documents & correspondence
- 8402090182 Notifies of intent to submit TMI Tech Specs in Aug 1984 per NUREG-0737 Util involved in extensive affort to address intergranular stress corrosion issue during refueling outage. HARRINGTON.W.D. Boston Edison Co. 84/02/03, VABBALLD.D.B. Operating Reactors Branch 2 2pp. 22158 031 24% Operating Reactors Branch 2 2pp Fiche 50-293,84/02/03,8402070182
- 8402140309 Advises that revs & proposed changes to Vol II of 8A manual acceptable Concerns & request for addl info expressed in 830901 meeting adequately resolved.
 MARTINAT T Division of Engineering & Technical Programs. Fiche 50-293,84/02/07,8402140309
- 8402230145 Forwards Sev 1 to "GE BUR Supplemental Reload Licensing Submittal for Pilgrim Nuclear Fower Station, Unit 1, Reload 6 " Rev corrects error noted on Page 13 re plant response to MSIV closure HARRINGTON, W D Boston Edison Co 84/02/21 VASSALLO, D B. Operating Reactors Branch 2 Ip 22361 084 24% Fichs: 50-293.84/02/21, 8402230145
- Q Inspection reports, IE Bulletins & correspondence
- 8402020236 Forwards IE Insp Rept 50-273/83-21 on 830822-26 & notice of 00200236 Forwards 16 they neve so all violation violation MARTIN.T T Division of Engineering & Technical Programs HARRINGTON, H D Boston Edison Co 2pp 22037 023 24; Fiche 50-273.83/12/29.8402020236 83/12/29
- --8402020238 Notice of violation from insp on 830822-26
 * Region 1, Office of Director. 83/12/27, 29p 22057:025 24% Fiche:50-293,83/12/29,8402020236
 - 3402020242 IE Insp Rept 30-273/83-21 on 830822-26. Violations noted. failure to adequately plan external audits & failure to provide effective corrective action to audit findings. MEYER, 0 M Region 1. Office of Director CAPHTON, D L. Division of Engineering & Technical Programs 83/12/20, 9pp 22057 027, 24X Fiche 50-273,83/12/29,8402020236
- 02020352 Forward: IE Safeguard: Insp Rept 50-293/83-25 on 831114-18 No violations noted MARTIM.T T Division of Engineering & Technical Programs MACCOMACK, ER Boston Edison Co. 2pp 22052;118, 24 Fichs 30-293,83/19/20,840202032,
- 8402020356 IE Safeguards Insp Rept 50-293/83-25 on 831114-18 No violations noted Major areas inspected communications, security program audit & organization, testing & maint, physical barriers, assessment aids & access control.

 BAILEY.R J, MADDEN.H., GUDY.A T Region 1, Office of Director 83/12/27 5pp. 22052-120 24X Fiche 50-293,83/12/30,8402020352

- 8402030425 Forwards IE Insp Rept 50-293/81-14 on 810621-26 & summary of B3130 mgt meeting
 BTAROSTECKI,R Division of Project & Resident Programs,
 HARRINGTON, H D Boston Edison Co 6pp 22068 242, 24
 Fiche 50-273,84/01/12.8402030425
- ---8402030430 IE Insp Rept 50-293/81-14 on 810621-26 Noncompliance notes failure to establish procedures for radiological & chamical analysis of primary coplant sampler under accident ennditions
 - NIMITZ,R L , GREENMAN,E G Region 1, Office of Director, 82/05/04 24pp. 22068 248 24X Fiche 50-293,84/01/12,8402030425
- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps." Svc list and JDRDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/25 Consolidated Edison Co of New York, Inc 120pp. 22058 001 24X Fiche 50-000,84/01/25,8312[20153
- 8401190016 IE Info Notice 84-07. "Design-Basis Threat & Review of Vehicular Excess Controls." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc. 119pp 22114 179, 24X Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vant Headers " Svc list encl DEYBUNG.R C Director's Office, Office of Inspection and Enforcement 84/02/03. Consolidated Edison Co. of New York, Inc 102pp 22177 156 24X Fichs 50-000,84/02/03,8401190017
- E402140219 Ack receipt of E40119 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-293/83-21 MARTIN, T T Division of Engineering & Technical Programs. 64/02/6 HARRINOTON ND Boston Edison Ca 2pp 22221 034 24X Fiche: 50-293, 84/02/06, 8402140219 64/02/08
- --8402140234 Responds to NRC 831227 ltr re violations noted in IE [nsp Rept 50-293/83-21, Corrective actions, schedule for external audits compiled & formally issued on B31007 & personnel instructed in importance of audits
 HARRINOTON W D Boston Edison Co. 84/01/19. BTAROSTECKI, R. Division of Project & Resident Programs, Spp 22221.036, 24X Fiche 50-293,84/02/06,8402140219
- 8402240021 Forwards IE Insp Rept 50-293/83-27 on 831219-22, No Violations noted.

 MARTIN.T T Division of Engineering & Technical Programs.

 HARRINGTON.W.D. Boston Edison Co 2pp. 22375 312 24X

 Fichs 50-293,84/02/08.8402240021
- --8402240028 IE Insp Rept 50-293/83-27 on B31219-22. No violations noted Hajor areas inspected radiation protection program, including licenses action on previously identified thems & review of radiation protection program & outage planning.
 WHITE, J.R. MILLER, H.T., BHANBAKY, M. Region 1. Office of Director 84/02/06. 4pp. 22375.314. 24X Fiche 50-293,84/02/08,8402240021
- 8402130653 Requests Class 3 fee for 790724 application requesting relief from certain 100FR170 22 insp requirements based on proposed inservice insp program DI093 R.M. License Fee Management Branch 84/02/09, HARRINOTON, W. Hoston Edison Go. ip 22214; 290 24X Fichs 50-293,84/02/09,8402130653.
- 8402240034 Forwards IE Insp Rept 50-293/84-03 on 840120-27, Enforcement conference scheduled for 840221 to discuss radiation protection BTARUSTECKI, R. Division of Project & Resident Programs. 84/02/07 HARRINGTON, W D Boston Edison Co 2pp 22375.264. 24X Fiche. 50-293, 84/02/09, 8402240034
- --8402240038 IE Insp Rept 50-293/84-02 on 840120-27. Problems identifief NUMBER VOICE IN THE REPT DUMEYS/MEMOR DE BADIRO-27, Problems identififf failure to properly instruct workers as radiological' conditions & failure to properly label containers holding highly radioactive contents
 JOHNSON, J. MCSRIDE, M., HHITE, J. Region 1, Office of Director B4/02/09 13pp. 22375-266 24X Fichs. 50-293, B4/02/09, 8402240034
- 8402240039 Forwards IE Insp Rept 50-293/83-24 on 831108-1231 & notice of violation.
 STARDBTECKI, R Division of Project & Resident Programs. B4/02/09
 HARRINOTON, W D. Boston Edison Co. 2pp 22372:338. 24X
 Fiche 50-273,84/02/09,8402240039.
- --8402240042 Notice of violation from insp on 831108-1231. * Region 1, Office of Director. 84/02/09. 1p. 22372.340. 24% Fiche 50-293,84/02/09,8402240039

- --9402240046 IE Insp Rept 50-293/83-24 on 831108-1231 Noncompliance noted failure to log temps during reactor vessel coaldown & failure to implement Tech Spec requirements for water supplies w/torus drained
 JCHNBON,J . MCBRIDE,M . BORCHARDT,R Region 1, Office of
 B4/02/02 14pp 22372 341 24X Fiche 50-293,84/02/09,8402240039
- B402160423 Responds to IE Bulletin 84-01 re cracks in Mark I containment vent header All surfaces & welds accessible from catwalk visually examined & found acceptable HARRINGTON & D Boston Edison Co B4/02/10 MURLEY, T E Region 1. Office of Director 3pp 22268 316 24X Fiche 50-293,84/02/10,880348037 Office of Director 8402160423
- B4Dii90041 IE Info Notice B4-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (100FR50, App R) " Syc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of P York, Inc 124pp 22365 259 24X Fiche 50-000,84/02/13,84011900
 - 24X Fiche 50-000,84/02/13,8401190041
- B402210444 Notification of Bignificant Licensee Meeting 84-15 on 840221 w/util in King of Prussia,PA to conduct enforcement conference.

 GALLO.R M. Region 1. Office of Director 84/02/13 Region 1
 Office of Director 1p 22323 332 24X Fiche 50-293,84/02/13,8402210444
- 8401190039 IE Info Natice 84-08, "10CFR50 7, 'Employee Protection '* 101190039 IE ANTO NOVEL - .

 Byc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp. 22365 141 24X Fiche 50-000,84/02/14,8401190039
- B401190045 IE Info Notice:83-63 Suppl 1; "Potential Failures of Mestinghouse Type SA-1 Differential Relays " Svc list encl JORDAN.E. L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/02/15 Consolidated Edison Co of New York. Inc 118pp 22366:142 24X Fiche 90-000.84/02/15,8401190045
- 8402270271 Responds to Confirmatory Action Ltr 84-03 re contamination of personnel exceeding quarterly extremity dose limits Communications between health physics personnel improved as result of 84018 overexposure

 HARRINGION, W D. Boston Edison Co 84/02/15 STARDSTECKI, R
 Division of Project & Resident Programs 21pp. 22386 284 24X

 Fiche: 50-273,84/02/15,8402270271
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Bat Below Manufacturer Recommended Value " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co. of New York, Inc. 116pp. 22366 024 24X Fiche 90-000.84/02/21.8401190062 116pp.
- 8<01190046 IE Info Notice 84-11, "Training Program Deficiencies"
 Bvc list encl
 JCHDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York: Inc. 115pp 22430 304 24% Fiche 50-000,84/02/24,8401190066
- B401190067 IE Info Notice B4-12, "Failure of Soft Seat Valve Seals"
 Svc list encl
 JCRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co. of New
 York Inc. 120pp. 22431 060 24X Fiche 50-000,84/02/27,8401190067
- R Periodic operating reports & related correspondence
- 8402270202 "Number of Personnel & Man-Rem Exposure by Work & Job Function," annual rept for 1983 W/840210 ltr HARRINGTON, W.D. Boston Edison Co. 83/12/31, 4pp 22425 123 24X Fiche 50-293,83/12/31,8402270202
- 8402220010 Monthly operating rept for Jan 1984. W/840214 1tr HAMILTON, P., HARRINGTON Boston Edison Co. 84/01/31 7pp 22337.338 24X Fiche 50-293.84/01/31,8402220010 84/01/31 7pp
- B Reportable occurrences, LERs & related correspondence
- 8402050242 Confirms actions to be taken re radiation exposure to health physics technician on 840118, per 840125 telcon flequests ack within 24 h of 1tr receipt STAROSTECKI.R Division of Project & Resident Programs. 84/0 HARRINOTON, W D Boston Edison Co 2pp 22087/208, 24X Fiche: 50-273,84/01/25,8402060242 ams. 84/01/25 24X

- 8402080343 LER B3-066/03L-0 on B31230, while performing weekly fire TO BE STANDARD TO THE PROPERTY OF BALESON WHITE PETFORMING WEEKING FIFF PUMP tests electric fire pump would not start w/auto initiation logic Caused by frozen sensing lines Lines thawed W/840126 ltr HAMILTON, P. J. HAMRINGTON, W.D. Boston Edison Co. 84/01/26 2pp 22131 213 24X Fiche 50-293,84/01/26,8402080343
- B402230347 Updates status rept on BWR pipe cracks & protection of upcoming licensee actions Insp results encl Evaluation & recommendations re interim & long-term remedial measures expected by May 1784
 DIRCKS.W J Office of the Executive Director for Operations SECY-BA-CO9A 84/01/27 Spp 22377 047 24% Fiche 50-000, 84/01/27,8402230347
- 8402140460 Updated LER 82-033/03X-1 on 820819, nitrogen purge isolation NORINGADO Updated LER 82-033/03x-1 on 820819, hitrogen purge isolati valve A050338 did not meet Tech Spec closure requirements Caused by extended closing time of 3/8-inch solenaid air supply valve Valve replaced W/840130 ltr WHITNEY, 6 g. HARRINOTON, W D. Boston Edison Co. BECO 84-017 84/01/30 2pp 22221 104 24X Fiche 50-293, 84/01/30, 8402140460
- B402270277 Updated LER 83-020/01X-1 on 830429. Tech Specs 3 il D & 4 il D discovered not incorporated into facility Tech Specs Caused by personnel error Change to Procedure B A 23 made to incorporate surveillance W/840208 ltr WHITNEY. O C . HARRINGTON W D Boston Edison Co 84/02/08 4pp 22386 334 24X Fiche 50-293, 04/02/08, 8402270277
- 8402270465 Updated LER B1-009/03X-1 on 810319, inboard isolation valve NO22/0465 Updated LER BI-009/03x-1 on BIO319; inboard isolation va failed to open & HPCI sys declared inoperable Caused by incorrect min torque switch setting of motor operator & thermal binding Torque switch set at max value W/040200 ltr WHITNEY,0,0; HARRINGTON,W D Boston Edison Co 84/02/08 3pp 22389 267 24X Fiche 30-293,84/02/08,8402270465
- DOCKET 50-294 MICHIGAN STATE UNIV RESEARCH REACTOR F Security, medical, emergency & fire protection plans
- B402220312 Forwards IE Bafeguards Insp Rept 50-274/84-01 on 840123-24 & 0201 No noncompliance noted AXELSON.W L Region 3. Office of Director 84/02/16 TERRY, 8 H Michigan State Univ , East Lansing, MI lp 22336 259 24X Fiche 50-274,84/02/16,8402220312
- --8402220345 IE 88feguards Insp Rept 50-294/84-01 on 840123-0201 No noncompliance noted Major areas inspected matt control & accountability including organization & operation & security organization Details withheld (ref 10CFR2 790) STAPLETON.B W. CREED, J. R. Region G. Office of Director 84/02/15 1p 22336 260 24X Fiche 50-294,84/02/16,8402220312
- O Inspection reports. IE Bulletins & correspondence
- 8402220312 Forwards IE Bafeguards Insp Rept 30-294/84-01 on 840123-24 % 0201 No noncompliance noted AXELBON,W L. Region 3, Office of Director 84/02/16 TERRY, 8 H Michigan State Univ . East Lansing, MI. 1p 22336,259 24X Fiche 80-294,84/02/16,8402220312
- --B402220345 IE Safeguards Insp Rept 50-294/84-01 on B40123-0201 No noncompliance noted Major areas inspected mat1 control & accountability, including organization & operation & security organization Details withheld (ref 100FRZ 790)
 STAPLETON.B.W. CREED.J R Region 3. Office of Director B4/02/15 ip 22336.260 24X Fiche 50-294,84/02/16.8402220312
- R Periodic operating reports & related correspondence
- 8402100011 Summarizes experiments performed during 1783.per 10CFR50 59 WILKINSON,B W Michigan State Univ , East Lansing, MI 83/12/31 Director's Dffice, Office of Inspection and Enforcement 1p 22182 155 24X Fiche 50-274,83/12/31.8402100011
- DOCKET 50-295 ZION NUCLEAR POWER STATION: UNIT 1 F Security, medical, emergency & fire protection plans
- 8402130191 Rev O to Emergency Plan Implementing Procedure EDF-17.
 "Emergency Operations Facility Activation Facility Log"
 BERLIN: M D Commonwealth Edison Co 83/09/23 3pp 22199 283
 24X Fichs 50-000:83/09/23:8402130191
- 8402130215 Rev 0 to Emergency Plan Implementing Procedure EOF-18. "Nuclear Station Div Non-Edison Transportation Incident Assistance Procedure" # Commonwealth Edison Co. 83/09/29, 5pp. 22204 078 24x
 - Fiche 50-000,83/09/27,8402130215

- 8402100137 Revised emergency plan implementing procedures, including Procedures EPIP EUF-17 re emergency operations facility activation log, EPIP CC-12 re sys power dispatcher & EPIP EUF-12 re access control H/840203 memo & receipt form MOURE.R D Commonwealth Edison Co 83/11/09 DENTON.H R NRC No Detailed Affiliation Given 24pp 22181 288 24X Fiche 50-000,83/11/09,8402100137
- B402130220 Rev B to Emergency Plan Implementing Procedure CC-12. "Sys Power Dispatcher " MODRE,R D Commonwealth Edison Co B3/11/09 11pp 22200 108 24X Fiche 50-000.83/11/09.8402130220
- 8402150398 Rev 2 to Generating Station Emergency Plan Implementing Procedure EOF-12, "Access Control to Emergency Operations Facility "*H/83*|108 Itr & receipt form MODRE, R B Commonwealth Edison Co 63/11/30 5pp 22242 358 24X Fiche 50-000:83/11/30.8402150358
- B402140134 Rev 5 to Emergency Plan Implementing Procedure EP IP 550-3, "Radiological Supplies for Medical Emergencies" W/840126 transmittal ltr & receipt form GRAESBER, K L , PLIML, 0 Commonwealth Edison Co 84/01/25 8pp 22219 029 24X Fiche 50-295,84/01/25,8402140134
- 8402060444 Forwards Rev 9 to Emergency Plan Implementing Procedure CC-1. "Corporate Command Ctr Director " Recovery manager priority notification table encl MOGRE, R D Commentmenth Edison Co 84/01/30 DENTON, H R OFF of Nuclear Reactor Regulation, Director 2pp 22083 129 24X Fichs 50-000,84/01/30,8402060446 Office
- --B402060464 Rev 9 to Emergancy Plan Implementing Procedure CC-1,
 "Corporate Command Ctr Director;" controlled copy
 HOORE.R D Commonwealth Edison Co 83/11/30 76pp 22083 131
 24X Fiche 30-000.84/01/30.8402060446
- 8402130467 Confirms 840215 enforcement conference at Region III ofc 402130467 Confirms 840215 enforcement conference at Regit to discuss recent sacurity event at Dresden & health physics events at Zion NORELIUS.C E Division of Project & Resident Programs REED.C Commonwealth Edison Co ip 22202 028 24X Fiche 50-000.84/02/02.8402130467 84/02/02
- 8402080151 Reinforces commitment to meet requirements of 10CFR50 48 & App R Daily fire hazard inspectors proposed New combustible matts control procedure developed & implemented as interim compensatory measure to achieving full compilance LENTINE.F 9 Commonwealth Edison Co 84/02/03 DENTON.H R Defic of Nuclear Reactor Regulation, Director 18pp. 22132 255 24X Fiche.50-295.84/02/03.8402080151 Defice
- 8402130361 Ack receipt of 840129 ltm forwarding scope of participation & objectives for emergency preparedness evercise scheduled for B40417 Supporting objectives acceptable PAPERIELLO, C. J. Region 3. Office of Director 84/02/08. REED, C. Commonwealth Edison Co. ip 22201 144 24X Fiche 50-275.84/02/08.8402130361
- --8402130365 Forwards scope of participation & objectives for emergency response exercise to be conducted on 840417. In accordance w/NRC & FEMA requirements
 DNYER.R E Commonwealth Edison Co 84/01/29. HIND, J Division of Radiological & Materials Safety Programs 4pp 22201.145 24x Fiche: 50-275,84/02/08,8402130361
- 3402:50429 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licenses, per 810709 ltr W/o request, entire plan will be licensee.per BBD/07 15F W/O request, and a placed in PDR NORRIS, J. Operating Reactors Branch 1, 84/02/08, FARRAR, D L Commonwealth Edison Co 2pp 22263 309 24X Fiche 50-275,84/02/08,
- 3402210142 Forwards revised response re basis for selection of safety parameter display sys for facility.per Suppl 1 to NUREO-0737.

 BHARTZ.E.D. Commonwealth Edison Co. 84/02/10 DENTON.H R. Office of Nuclear Reactor Regulation, Director. 5pp. 22317-172-24X. Fiche 50-295.84/02/10.8402210142
- 8402220524 Rev 4 to emergency plan implementing Procedure EPIP 180-1, "Rad/Chem Director" * Commonwealth Edison Co 84/02/17 11pp 22024 039 24X Fiche 50-295,84/02/17,8402220524
- 402220528 Rev i to Emergency Plan Implementing Procedure EPIP 350-2, "Calculation of Post-Accident Noble Gas Release Rates Via Vent Stacks & Guick Estimate of Offsite Dose Using SPING Monitor RIA-FR49 Readings,"

 > Commonwealth Edison Co 84/02/17 10pp 22334 153, 24X Fiche 50-295,84/02/17.8402220529

- 840222055| Rev 9 to emergency plan implementing Procedure EPIP-110-1, "Station Director" + Commonwealth Edison Co 84/02/17 9pp 22333 134 24X Fiche 50-225.84/02/17,840222055|
- B402280395 Revised emergency plan implementing procedure, including R₁, 1 to B2P 600-A4, "GSEP Telephone Directory" + Commonwealth Edison Co 84/02/18 61pp 22404 158 24X Ficke-50-000, 84/02/18, 8402280395

G Adjudicatory correspondence

- B402160242 Submits petition to intervene in proceeding on issuance of amends re reactor containment leakage tasts GOGGLE Citizens Against Nuclear Power B4/02/13 Docksting 4 Services Branch 2pp 22274 333 24% Fiche 50-295,84/02/13.
- I Financial information
- 8402280410 Annual Financial Rept 1983 W/840221 ltr O'CONNOR.J Commonwealth Edison Co 83/12/31 29pp. 22407 101 24X Fichs 50-000,83/12/31.840280410
- D Advisory Committee on Reactor Safeguards reports & correspondence
- 8402090484 Summary of ACR8 Reliability & Probabilistic Assessment Subcommittee 820328-26 meetings in Washington DC re Zion probabilistic safety study a ACR8 Advisory Committee on Reactor Safeguards 82/03/26 ACR8 Advisory Committee on Reactor Safeguards 16pp. 22192 256 24X Ficte 50-295,82/03/26,8402090484
- 8408270263 Responds to FOIA request for JC Mark 801204 mamo to ACRS re hydrogen burn w/igniters & documents concerning generation, combustion or control of hydrogen in reactor accidents, Forwards App A documents App B documents in FDR FELYON, J. M. Division of Rules and Records, 84/01/30 HIATT. B L Ohio Citizens for Responsible Energy 7pp 22412 051, 24X Fiche 50-000,84/01/30,8402270263
- -8402270282 Summary of 800520 meeting w/natl labs.Westinghouse.NRC totils in Bethasda.MD re hydrogen technology Meetings scheduled for 800803 & 0617 to discuss FVCB & core retention devices & containment structural response, respectively GUITTECHREIBER ACRS Advisory Committee on Reactor Safeguards 80705/22 ACRS Advisory Committee on Reactor Safeguards. 3pj 22412 064. R4X Fiche.50-000.84/01/30.8402270263
- P Operating license stage documents & correspondence
- 8312120089 Ceneric Ltr 83-39 to representatives of utils re voluntary survey of licensed operators. Svc list encl. EISENHUT, D. Q. Division of Licensing 83/12/08. Commonwealth Edison Co. 12pp. 22313 006. 24% Fiche 50-000.83/12/08.8312120029
- 8402139013 Responds to FOIA request for two categories of documents for IDCOR program Forwards App A & B documents Documents placed in PDR in FBK. FELTON, J. M. Division of Rules and Records, 83/12/21 Union of Concerned Scientists 5pp. 22282-004 24X Fiche 50-000,83/12/21,8402130013 BHOLLY, R.C.
- --8402130054 Forwards draft feasibility study for containment perforant; under severe accident conditions for large dry PHR. in preparation for B31202 meeting Proposed agenda enci.
 ARLOTTO.0 A. Division of Engineering Technology. 83/11/21.
 BUHL.A.R. Tachnology for Energy Corp. 3pp. 22282 217. 24X
 Fichel 30-000.83/12/21.8402130013
- 8402010177 Forwards notice of consideration of issuance of amend to Licenses DPR-39 & DPR-48 & opportunity for prior hearing re 830808 request to amend Tech Specs re acceptance criteria for containment leakage tests VAROALS A Operating Reactors Branch i 83/12/23, FARRAR, D. L. Commonwealth Edison Co. 4pp. 22048,043 24X Fiche, 50-295, 83/12/23, 840020177
- --8402010181 Notice of consideration of issuance of amend to Licenses DPR-39 & DPR-48 & opportunity for prior hearing. VAROA.6 A Operating Reactors Branch 1 83/12/23 4pp. 22048 047 24X Ficher 50-295,83/12/23,8402010177.
- B402010192 Forwards notice of consideration of issuance of amend to Licenses DPR-39 & DPR-48 & opportunity for prior hearing re B31014 request to amend Tech Specs to allow extensive diesal generator maint VAROA; S.A. Operating Reactors Branch 1 84/01/05 FARRAR D.L. VAROA, B A Operating Reactors Branch 1 84/01/05 FARRAR, D.L. Commonwealth Edison Co Spp 22048.006 24X Fichs. 50-295, 84/01/05,

- --8402010199 Notice of consideration of issuance of amend to Licenses DPR-39 & DPR-48 & opportunity for prior hearing VARGA, S A Operating Reactors Branch 1 84/01/05 4pp 22048 009 24X Fiche 30-295,84/01/05.8402010192
- 8402020454 Notification of rescheduled 840125 meeting w/util in Bethesda.MD to discuss status of equipment environ qualifications NORRIS.J A Operating Reactors Branch 1 B4/01/13 VARGA.S A Operating Reactors Branch 1 pp 22062 169 24X Fichs 50-275.84/01/13.8402020455
- 8402010221 Discusses review of util 820108 submittal re NUREO-0737, Item II K 2 17, "Potential for Voiding in RCS During Transients," per Generic Ltr 81-21, "Natural Circulation Cooldown" Voids accounted for in present analysis models WARGALS A Operating Reactors Branch 1 84/01/16 FARRAR.D L Commonwealth Edison Co 11pp 22047 330 24X Fiche 50-295, 84/01/16,8402010221
- 8402070336 Reiterates 81090B request that confirmatory order dtd 800229 bs rescinded, based on listed reasons Practice of scheduling actions based aplely on perceived risk must be discontinued Rafs & status rept on each order item encl REED, C Commonwealth Edison Co 84/01/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 14pp 22096 199 24X Fiche 50-275,84/01/27,8402070336
- 8402020349 Requests mod to Item B 6 of B00229 Confirmatory Order rediesel generator testing & allowable outage times Bases for removal of outage time provision listing including Item B 6 massures, detrimental to diesel generator reliability LENTINE, F G. Commonwealth Edison Co 84/01/30 DENTON, H R Office of Nuclear Reactor Regulation, Director Spp 22055 052 24X Fiche, 50-295, 84/01/30, 8402020349
- 8402210021 APPLICATION OF THE BSMRP METHODOLOGY TO THE BEISMIC RISK AT THE ZION NUCLEAR POWER PLANT BOHN, M.P., SHIEHL C., WELLS, J.E. Lawrence Livermore Laboratory FIN A-0126 NUREO/CR-3428 84/01/31 Division of Engineering Technology 324pp Available at NRC, \$8 00 22322 001 24X Fiche 50-295,84/01/31,8402210021
- B402010410 Generic Ltr B4-04 to all operating PWR licensees, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Svc list encl EISENHUT.D G. Division of Licensing 84/02/01 Consolidated Edison Co of New York. Inc 59pp 22177 087 24X Fichs.50-000.84/02/01.8402010410
- 8402100476 Bummary of 840125 meeting w/util, Bechtel & Sargent & Lundy to discuss environ qualification of electrical equipment for Facilities. WIQQINTON, D L Operating Reactors Branch 1 84/02/03 Operating Reactors Branch 1 50pp. 22211 109 24X Fiche 50-295,84/02/03, 8402100476.
- Q Inspection reports. IE Bulletins & correspondence
- 8312120153 IE Info Notice 84-06. "Steam Binding of Auxiliary Feedwater Pumps." Byo list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co. of New York. Inc. 120pp 22058.001 24X Fiche 50-000.84/01/25.8312120133
- 84D1190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls." Bvc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co. of New York, Inc. 119pp. 22114 179 24X Fiche.50-000.84/02/03,8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement. 84/02/03 Consolidated Edison Co of New York, Inc 102pp. 22177:156. 24% Fiche. 50-000.84/02/03.8401190017.
- B401170041 IE Info Notice 84-09. "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Bys (100FR50, App R)." Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). B4/02/13 Consolidated Edison Co. of New York, Inc 124pp 22365 259. 24X Fiche 50-000,84/02/13,8401190041
- B401170039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection.'"
 By: 11st encl
 JORDAN,E.L. Division of Emergency Preparedness & Engineering
 Response (Post B30103), 84/02/14 Consolidated Edison Co of New
 York, Inc. 115pp 22365'141 24X Fiche 50-000,84/02/14,8401170039

- 8401190045 IE Info Notice 83-63. Suppl 1, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/15 Consolidated Edison Co of New York, Inc. 118pp 22364 142 24X Fiche 50-000,84/02/15,8401190045
- B402270441 Ack receipt of B40131 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/83-24 & 50-304/83-25 SHAFER, W D Region 3, Office of Director B4/08/17 REED, C Commonwealth Edison Co ip 223B9 336 24X Fithe 50-295,84/02/17
- --B40227044B Responds to NRC B31230 ltr re violations noted in IE Insp Repts 50-295/83-24 & 50-304/83 25 Corrective actions training session held w/maint dept personnel stressing importance of procedures involving safety-related equipment FARRAR, D L Commonwealth Edison Co 84/01/31 KEPPLER, J G Region 3. Defice of Director 3pp 22389 357 24X Fiche 50-295, 84/02/17, 8402270441
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Set Delow Manufacturer Recommended Value " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000,84/02/21,8401190062
- 8401190066 IE Info Notice 84-i1, "Training Program Deficiencies"
 Svc list encl
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24.8401190066
- 8401190067 IE Info Notice 84-12. "Failure of Soft Seat Valve Seals "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060 24X Fiche 50-000.84/02/27.8401190067
- R Periodic operating reports & related correspondence
- B402130439 Monthly operating repts for Jan 1984 W/840207 ltr AUSTIN.0 , GRAESER.K L Commonwealth Edison Co 84/01/31 13pp 22202 083 24X Fichs 50~295,84/01/31,8402130439
- S Reportable occurrences, LERs & related correspondence
- B402240086 Further response to FQIA request for 16 categories of documents Item 9 limited, per B31005 telcon Forwards Rev 7 to NUREG-0525 & App A documents Portions of App B documents withheld (ref FQIA Exemption 4) App B documents also in PDR FELTON, J M Division of Rules and Records B3/12/12 SHOLLY, S C Union of Concerned Bcientists App 22394 150 24X Fiche, 50-000, B3/12/12, 8402240086
- --8402240117 RD 83-72 on B30728, vital erea alarms lost Caused by loop error PC8 board replaced in mux. All affected zones tested & secured Info deleted YOUNG: A Commonwealth Edison CD B3/07/28 Region 3, Office of Director ip 22394 165 24X Fiche 50-000. B3/12/12, 8402240086
- --8402240125 RO 83-67 on 830722 alarm capabilities lost in all zones due to mux overheating Caused by extreme heat inside plant Central processing unit replaced & Code 10 performed w/positive results Info deleted YOUNG. A Commonwealth Edison Co 83/07/22 Region 3, Office of Director Ip 22394 166 24X Fiche 50-000,83/12/12,8402240085
- --B402240129 RD 83-52 on B30617, vital area door found physically unsecured & electric strike malfunctioned Cause not stated Electric strike replaced Info deleted YOUNG, A Commonwealth Edison Co B3/06/21 Region 3, Office of Director ip 22394 167 24X Fiche 50-000, 83/12/12, 8402240086.
- --B402240135 RO 83-40 on 830523, vital area door alarm lost Caused by misadjustment of supervisory line board Alarm repaired Info deleted YOUNG, A Commonwealth Edison Co B3/05/24 Region 3, Office of Director 1p 22374*168 24% Fiche 50-000.83/12/12:8402240086
- --B402240141 RO 83-40 on 830414, power flex to security equipment resulted in loss of alarm integrity Caused by fire Mux restored Info deleted

 * Commonwealth Edison Co 83/04/18 Region 3, Office of Director ip 22394.169 24X Fiche 50-000.83/12/12.8402240086

- 8402060135 LER 84-002-00 on 840102, unit operator reset incorrect relay, causing advertent safety imjection while returning eafoquards panel to normal Operator reinstructed to adhere to procedural details W/840119 ltr GRALBSER.K L Commonwealth Edison Co 84/01/19 3pp 22087 022 24X Fiche 50-225,84/01/19.8402060133
- 8402070127 LER 84-003-00 on B40124, leakage of cooling water to reactor containment fan cooler motor cooler 18 discovered Caused by pinhole perforations in flexible cooling water supply hose Hose replaced W/840202 ltr HARRECH R . GRAESER K L Commonwealth Edicon Co 84/02/02 Upp 22102 260 24x Fiche 50-275.84/02/02.8402070127
- 8402070172 LER 84-001-00 on 840105, reactor trip octurred due to signals from intermediate & source range bistables Coused by momentary loss of 120-volt power supply to nuclear instrumentation sys W/840202 ltr
 ORAESSER.K L Commonwealth Edison Co 84/02/02 3pp 22102 236 24X Fichs 50-295.84/02/02.8402070172
- B400220156 LER B4-004-00 on B40120.during RCB depressurisation.sys inadvertently safety injected Caused by operator not following operational procedures Operator reprimended W/640217 ltr WENNERHOLM J., GRAESSER.K.L. Commonwealth Edison Co. B4/02/1. 3pp 22337 355 24X Fiche 30-295.84/02/17,8402220156
- 0402220413 LER 84-005-00 on 840120, small reactor codant leak observed in seal table room Caused by bowed thimble between high pressure seal & thimble isolation valve Maint procedures revised to ensure proper seal makeup W/840217 ltr PETRAW, T 9 . GRAESSER, L. Commonwealth Edison Co 84/02/17 3pp 22340 193 24x Fiche 50-275, 84/02/17, 8402220413
- DOCKET 30-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3
- 8402280411 Forwards IE Enforcement Conference Repts 50-289/83-50, 50-260/83-58 & 50-296/83-58 on 831216 Meeting held to discuss apparent security violation & operation w/underrated discest generator HX O'REILLY, J.P. Region 2, Office of Director 84/01/05 PARRIB, H O Tennessee Value Autority 2pp 22407 143 24X Fishe 80-259,84/01/05,8402280411
- 8402140190 Confirms NRC 840118 tulcon re 840119 meeting in Region II oft to discuts security activities
 LEWIS R C Division of Project & Resident Programs 84/01/10
 PARRIS R O Tennessee Valley Authority 1p 22200 279 24X
 Fiche 50-259.84/01/18.8402140180
- 8402060382 Forwards Rev 7 to generic security personnel training & qualification plan Rev withhold tref 10CFR73 21)
 MILS.L H Tennessee Valley Authority 84/01/19 0'REILLY.J P
 Region 2. Office of Director ip 82086 317 24X
 Ficha 50-000.84/01/19.8408060382
- B402210301 Revised thergency plan implementing procedures including Procedures BFN-HEP re radiological emergency plan & DFN-HPD re implementing procedures document W/040210 ltr MillS.L M Tennessee Valley Authority 84/01/20 0/REJELY, J P Region 2. Defice of Director 128pp 22315,076 24x Fichs 50-259,84/01/20.9402210301
- 8402140384 Forwards summary of 840113 meeting in Region II ofc re emergency protective actions required by NVR69-0454 & clarified by IE Info Notice 83-28 VERRELLI,D M Division of Project & Resident Programs 84/01/2, PARRIS,K 0 Tennesses Vailey Authority 4pp 22220 042 24X Fiche 50-000,84/01/26,8402140384
- 8402130316 Forwards Rev 8 to generic socurity personnel training & qualification plan Rev withheld MTLLS.L H Tennesse Vailey Authority 84/01/27 O'REILLY, J P Region 2. Office of Director ip 22197:149 24X Fiche 50-000.84/01/27.8402130316
- 8402130490 Forwards rev to physical security plan Rev withheld (nef 10CFR73-21)
 MILLS.L H Tennessee Valley Authority 84/01/30 O'REILLY.J P Region 2. Office of Director 1p 22200 256 24X
 Fiche 50-259,84/01/30.8402130490
- B40B140295 Forwards summary of B40119 meeting w/util in Region II ofc re improvement of security effectiveness & other securityrelated topics LEMIG.RC Division of Project & Resident Programs B4/02/01 PARRIS.H O Jennessee Valley Authority 4pp 22228-271. 24x Fiche B0-000,84/02/01,B402140275

- 8402210278 Revs to Muscle Shoals emergency control ctr implementing pracedures; including Procedure MSEC 1P-1 re notification of unusual event, alert or transportation accident & MSEC 1P-2 re site emergency or emergency director W/840210 ltr MILLB.L M Tennessee Valley Authority 84/02/02 O'REILLY, J P Region 2, Office of Director 76pp 22315 001 24X
- BAOR130354 Ack receipt of util 831006 & 1121 ltrs transmitting rev to facility security plan Rev consistent w/provisions of 100FR50 54(a) & acceptable LEMIS.8 C Division of Project & Resident Programs 84/02/08 PARRIS.H 0 Tennessee Valley Authority 3pp 22197 285 24X Fiche 50-259,84/02/08,8402130354
- 0402150221 Forwards evaluation of TVA radiological emergency preparedness plan for Browns Ferry for 831115-16 exercise. State of AL & Lauderdale, Lawrence, Limestone & Morgan Counties participated KRIMM.R W Federal Emergency Management Agency 84/02/08 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 1p 22244 251 24X Fiche 50-259.84/02/08.04002150221
- --BA02150237 Evaluation of TVA radiological emergency preparedness plan for Browns Forry for B31115-16 exercise # Federal Emergency Management Agency 83/12/16 28pp. 22244 292 24X Fichs 50-259.84/02/08.8402190221
- 840/2280489 Ack receipt of 840126 ltr informing NRC of addl steps talen to correct violations noted in IE Insp Repts 90-259/83-33, 50-250/83-33 & 50-254/83-33 EBHS C Division of Project & Resident Programs 84/02/15 PARRIB.H G Tennessee Valley Authority in 22407 001. 24% Fiche 90-257,84/02/15,8402280489
- --8402280552 IE Insp Repts 50-289/83-33.50-260/83-33 to 50-296/83-33 or 830726-0825 Noncompliance noted failure to have equipment installed in accordance w/drawings.follow leak detection monitoring procedures to update as-constructed drawings. PAULK, G. L. Region 2, Office of Director 83/09/20 14pp. 22407 017 24X Fiche 30-259,84/02/15.8402280489
- J Insurance & indemnity information
- 8402210231 Forwards Endorsements 71 & 72 to NELIA Policy NF-19B & Endorsements 60 & 61 to MAELU Policy NF-66 Amended site doscription also encl BUCK. J.R. Marsh & McLennan. Inc. 84/02/13 SALTZMAN, J. Assistant Director for State & Licensee Relations 7pp. 22315 299. 24% Fiche 50-259.84/02/13.8402210231.
- P Operating license stage documents & correspondence
- B402070310 "Browns Ferry Other Transients Failure Modes & Effects Analysis & Rejected Sys Justification Rept." preliminary rept BAXTER, p. E , BEAHH, D. M , BRUSKES J E0&0, Inc FIN A-6477 E0G-EA-6276 DRFT 83/05/31 NRC - No Detailed Affiliation Diver 68pp 22187 271 24X Fiche 50-259,83/05/31,8402090310
- B402010408 Forwards notice of consideration of issuance of amends to Licenses DPR-33.DPR-52 & DPR-68 & proposed NBHC determination & apportunity for hearing re operation w/one recirculation loop out of svc CLARK.R.J Deparating Reactors Branch 2 84/01/16 PARRIS.H Q. Tennesses Valley Authority 2pp 22062 001. 24X Fiche 50-259.84/01/16.8402010408
- --8402010417 Notice of consideration of issuance of amend to Licenses DPR-33, DPR-52 & DPR-68 & proposed NBHC determination & apportunity for hearing Amends permit operation w/one recirculation loop out of svc VABSALLO, D 8. Operating Reactors Branch 2. 84/01/16 & 6pp. 22062 003 24% Fiche 50-259.84/01/16.8402010408
- B402090303 Requests rev to pressure temp curves using conservative assumptions or demonstration that predicted neutron irradiation damage will be less than predicted for reactor vessel surveillance matl VABBALLO, D B Operating Reactors Branch 2 84/01/23 PARRIS. H 9 Tempessee Valley Authority 3pp 22177 348 24X Ficher 50-257, 84/01/23, 8402090303
- B40R140392 Confirms 840130 mgt meeting in Atlanta, GA to discuss past & planned mgt changed, per 8401R3 telcon
 LEWIS.R C Division of Project & Resident Progress B4/01/24
 PARRIB, H G Tannesses Valley Authority ip 22220 331 24%
 Fiche: 50-239, 84/01/24, 840R140392

- 8402130541 Forwards errata to Amends 94,87 & 60 to Licenses DPR-33, DPR-52 & DPR-64, respectively, revising Tech Specs sent on 831227.

 CLARK.R.J Operating Reactors Branch 2 84/01/25 PARRIS.H G Tannessee Valley Authority 2pp 22214 331 24% Fiche 50-257,84/01/25.8402130541
- --8402130552 Amends 94.87 & 60 to Licenses DPR-33, DPR-52 & DPR-68, respectively, revising errors in Tech Specs sent on 831227 a NRC No Detailed Affiliation Given 84/01/25 12pp 2214 333 24X Fiche 50-259,84/01/25,8402130541
- 8402070206 Advises that date of 840321 acceptable for meeting w/NRC to discuss program plan for detailed control room design reviews. Concurrence on meeting date requested HILLS, L. K. Tennessee Valley Authority 84/02/01 ADENBAM, E. Licensing Branch 4 1p 22102 212 24X Fiche 50-000, 84/02/01, 8402070206
- 8402140451 Notifies that response to Reg Guide 1 97 will be submitted by 840430 MILLS,L K Tennessee Valley Authority 84/02/06 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 22227 iii 24X Fiche 50-259,84/02/06.8402140451
- 8402210071 Informs NRC of need for specific Tech Spec rev for plant Reemphasizes concerns re overall backlog of Tech Spec requests outlined in 830627 ltr
 MILLB.L M Tennessee Vallay Authority 84/02/13 DENTON.H R
 Office of Nuclear Reactor Regulation. Director 2pp 22317 284
 24X Fiche 50-259.84/02/13,8402210071
- 8402280224 Responds to RM Diggs 840210 ltr rp determination of fees for facility. Util agrees w/fee determination & will submit fee by wire transfer MILLBL M Tennessee Valley Authority 84/02/23 MILLER, W D License Fee Management Branch ip 22399, 233 24X Fiche. 50-259, 84/02/23, 8402280224

Q Inspection reports, IÆ Bulletins & correspondence

- 8402140352 Forwards IE Insp Repts 50~259/83-54,50~260/83-54 & 50~276/83-54 on 831212-16 No violations or deviations noted VERRELLI.D M. Division of Project & Resident Programs 84/01/03 PARTIB.H. 0 Tennessee Valleg Authority 2pp 22221 242 24X Fiche 80~259,44/01/03,8402140352
- --8402140358 IE Insp Repts 50-259/83-54,50-260/83-54 & 50-296/83-54 on 831212-16 No violations or deviations noted Major areas inspected:independent reverification of inservice insp work activities & IE Bulletin 83-02 CCLEY.J L Region 2, Office of Director BLAKE,J J Division of Engineering & Operational Programs 83/12/29, 4pp 22221 244 24X Fiche: 50-259,84/01/03,8402140352
- B402280411 Forwards IE Enforcement Conference Repts 50-289/83-58, 50-250/83-58 & 50-296/83-58 on 831216 Meeting held to discuse apparent security violation & operation w/underrated diesel generator HX D'REILLY, J.P. Region 2, Office of Director 84/01/05 PARRIS, H O Tennessee Valley Autority 2pp 22407-143 24X Fiche. 50-239, 84/01/05, 8402280411
- --B4022B0417 IE Enforcement Conference Repts 50-259/83-58, 50-260/83-58 & 50-294/83-58 on B31216 Major areas discussed acceptability of HX on dissel generator & mod to scram discharge instrument vol.

 CANTRELEF S Division of Project & Resident Programs B4/01/03 5pp. 22407.145 24X Fiche 50-259.84/01/05.84022B0411.
- 8402060119 Forwards BER of masonry wall design, per IE Bulletin 60-11 Resvaluation of design of four unacceptable walls & proposed plans to upgrade walls requested within 120 days.

 VASSALLD, D. B Operating Reactors Branch 2 84/01/16 PARRIS, H G Tennessee Valley Authority 2pp 22103 196 24X

 Fich: 50-259,84/01/16,8402060119
- ---B462060144 Safety evaluation re masonry wall design per IE Bulletin 80-11 W/listed exceptions, wall integrity & performance of required safety functions will not be impaired * Office of Nuclear Reactor Regulation, Director 84/01/16 2pp 22103.198, 24X Fiche 50-259,84/01/16,8402060119
- --B309290095 "Masonry Wall Design (B-59), TVA Browns Ferry Nuclear Plant, Units 1,2 & 3," technical evaluation rept.

 LE.A.K. Franklin Institute/Franklin Research Center NRC-03-81-130. TER-05506-257 83/09/26 CHOKSHI, N.C. NRC No Detailed Affiliation Given Sipp. 22111'203 24X Fiche 50-259, 84/01/16, 8402060119

- 8402140106 Ack receipt of B40109 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-52. \$0-286/83-52 & 50-296/83-52 VERRELLI,D M Division of Project & Resident Programs 84/01/19 PARRIS.H G Tennessee Valley Authority 1p 22219 040 24% Fiche 50-259.84/01/19.8402140106
- --8402140112 Responds to NRC 831208 ltr re violations noted in IE Insp Repts 50-259/83-52,50-260/83-52 & 50-296/83-52 Corrective actions plant procedure for control room abandonment revised to require switches be checked for desired alignment MILLS.L M Tennessee Valley Authority B4/01/09 O'REILLY, J P Region 2. Office of Director App 22219 041 24X Fiche 50-259,84/01/19.8402140106
- --8402140121 Forwards IE Insp Repts 30-259/83-52,50-260/83-52 & 50-296/83-52 on 831026-1125 & notice of violation VERRELLI, D M Division of Project & Resident Programs 83/12/08 PARRIS, H G Tennessee Valley Authority 2pp 22219 045 24X Fiche 50-259,84/01/19,8402140106
- --8402140126 Notice of violation from insp on 831026-1125 * Region 2, Office of Director 83/12/08 ip 22219 047 24X Fiche 50-259,84/01/19,8402140106
- ---8402140136 IE Insp Repts 50-259/83-52.50-260/83-52 & 50-276/83-52 on 831206-1125 Violations noted failure to perform annual review of industrial security program & failure to bave procedure to align backup control switches PAULK. G L . CANTRELL. F 8 Rejidn 2. Office of Director 83/12/07 7pp 22219 048 24% Fiche 50-259.84/01/19.8402140106
- 8402140243 Ack receipt of 831221 supplemental ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-297963-12, 50-240763-12 & 50-2797683-12 O'REILLY, J. P. Region 2. Office of Director 84/01/20 PARRIS, H. G. Tennessee Valley Authority ip 22220 298 24X Fiche 50-297, 84/01/20, 8402140243
- --8402140252 Responds to NRC 831115 ltr re violations noted in IE Insp Repts 50-259/83-12.50-260/83-12 & 50-276/83-12 Corrective actions radiological incident repts issued & employees instructed to comply w/requirements re dose rate instrument MILLBL M Tennessee Valley Authority 83/12/21 O'REILLY, J P Region 2, Office of Director 3pp 22220 299 24X Fiche 50-259,84/01/20,8402140243
- --B402140263 Ack receipt of 830829 supplemental response to B30422 notice of violation in IE Insp Repts 50-259/83-12, 50-260/83-12 & 50-296/83-12 NRC continues to believe violations re dose rate instruments occurred O'REILLY, J P Region 2, Office of Director 83/11/15 PARRIS, H G Tennessee Valley Authority 2pp 22220 302, 24% Fiche 50-259, 84/01/20, 8402140243
- --8402140271 Ack receipt of 830829 supplemental response informing NRC of steps taken to correct violations noted in IE Insp. Repts 50-259/83-12, 50-260/83-12 to 50-296/83-12 Info being evaluated LEHTB.R C Division of Project & Resident Programs 83/10/14 PARRIS,H G lennesses Valley Authority Ip 22220 304 24X Fichs 50-259,84/01/20,8402140243
- --8402140276 Forwards supplemental response to NRC 830727 ltr re violations in IE Insp Repts 50-257/83-12, 50-260/83-12 & 50-276/83-12 MILLS, L M Tennessee Valley Authority 83/08/27 O'REILLY, J P Region 2, Office of Director 4pp 22220 303 24X Fiche: 50-259, 84/01/20, 8402140243
- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps," 8vc list encl JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22038 001 24X Fiche 50-000,84/01/25,8312120153
- 8402140166 Forwards revised response to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Bys of Dissel Generators," per B30615 & 1107 ltrs Valve integrity verification will be performed by disassembly MILLS,L M Tennessee Valley Authority 84/01/29 O'REILLY,J P Region 2, Office of Director 2pp 22219 319 24X Fiche. 50-259,84/01/25,8402140166
- 8401190016 IE Info Notice 84-07. "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000,84/02/03.8401190016

- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEVOUNG:R C Director's Office Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 196 24% Fiche 50-000.84/02/03.8401190017
- 8402140093 Ack receipt of supplemental 840123 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/33-44, 50-260/83-44 & 50-256/83-44 O'REILLY, J P Region 2, Office of Director 84/02/03 PARRIS, H G Tennosser Vailey Authority 1p 22218 218 24X Fichs 50-259,84/02/03,8402140093
- --8402140104 Suppls response to ARC B31230 ltr re violations noted in IE Insp Repts 50-259/B3-44, 50-260/B3-44 & 50-296/B3-44 Corrective actions monthly close program modified so correct month ending date assigned to each TLD badge MILLS: I.M. Tennessee Valley Authority. 84/01/23 O'REILLY, J.P. Region 2. Office of Director 3pp. 22218 219 24% Fiche 50-259,84/02/03,8402140093
- --8402140110 Ack receipt of 831220 ltr informing NRC of steps taken to correct violations noted in IE Inep Repts 20-259/83-44, 50-260/83-44 & 50-296/83-44 BORELLY, J.P. Region 2, Defice of Director 83/12/30 PARRIS.H 0 Tennessee Valley Authority tp 22218 222 24X Fichs 50-259,84/02/03,8402140073
- --8402140132 Responds to NRC 831123 ltr re violations noted in IE Insp Repts 50-259/83-44.50-260/83-44 & 50-246/83-44. Corrective actions fly Sys Divelopment Branch contacted to initiate software changes to prevent future occurrences MILLS.L M Tennessee Valley Authority B3/12/20 O'REILLY, J P Region 2. Office of Director Spp 22218 223 24X Fiche 50-259,84/02/03.8402140093
- --B402140142 Forwards IE Insp Repts 50-259/83-44,50-260/83-44 & 50-296/83-44 on 831025-28 & notice of violation O'REILLY,J P. Region 2. Office of Director 83/11/25 PARRISH 9 Tennessee Valley Authority 2pp 22218 226 24X Fiche 50-259,84/02/03.8402140093
- 8402140148 Notice of violation from insp on 831025-28 * Region 2, Office of Director 83/11/25 ip 22218 228 24x Fiche 50-259,84/02/03.8402140093
- -8402140i64 IE Insp Repts 50-259/83-44, 50-260/83-44 & 50-296/83-44 on 83i025-28 Violation noted subcontractor employee received dose of 3.059 mrem whole body during Third Quarter 1983 PAULK, Q L. BUTCHERR C Region 2. Office of Director CANTRELL, F B Division of Project & Resident Programs 83/11/17 4pp 22218 229 24% Fiche 50-259.84/02/03.8402140093
- 8402140420 Ack receipt of 840110 ltr informing NRC of steps taken to correct deviation noted in IE Insp Repts 50-259/83-41, b0-260/83-41 & 50-296/83-41

 VERRELLI,D M Division of Project & Resident Programs 84/02/03 PARRIS,H 9 Tennessee Valley Authority ip 22221 224 24X Fiche 50-259,84/02/03,8402140420
 - HO2140424 Responds to NRC B31202 ltr re deviation noted in IE Insp Repts 50-299/83-41.50-240/83-41 & 50-296/83-41 Corrective actions Rediography Procedure N-RT-1 revised re layout control Technical std rev will be issued on 840402 MILLS,L M Tennessee Valley Authority B4/01/10 D'REILLY, J P Region 2: OPFice of Director 2pp 22221 225 24x Fiche 50-259,84/02/03,8402140420
- -8402140429 Forwards IE Insp Repts 50-259/83-41,50-260/83-41 & 50-296/83-41 on 831025-28 & 1101-04 & notice of deviation VERRELLI.D M Division of Project & Resident Programs. 83/12/02 PARTIS.H 0 Tennessee Valley Authority 2pp 2221 227 24X Fiche 50-259,84/02/03.8402140420
- -8402140433 Notice of deviation from insp on 831025-28 & 1101-04 * Region 2, Office of Director 63/12/02 &p 22221:227 24X Fiche 50-259,84/02/03,8402140420
- 8402140443 IE Insp Repts 30-259/83-41.50-260/83-41 & 50-296/83-41 on 831025-28 & 1101-04 Deviation noted failure to take action to preclude recurrence for Violation 81-36-04 re radiographic layout & grinding control GRARD.E H. COLEV.J L. Region 2. Office of Director BLAKE,J J Division of Engineering & Operational Programs 83/11/28. Lopp 22221 230 24% Fiche: 50-259,84/02/03.8402140420
- 02280192 Confirms 840217 enforcement conference at Region II ofc to discuss bypassing of rod sequence control sys during shutdown & isolation of drywell to suppression poot differential pressure instruments.per 840207 telcon O'REILLY, J P Region 2. Office of Director 84/02/09 PARRIS, H C Tennessee Valley Authority 2pp 22400 296 24X

- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (100FR30, App R) " Bvc list enc!

 JORBAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consulidated Edison Co of Naw York, Inc 124pp 22365 299 24% Fiche 50-000-84/02/13,8401190041
- B401190039 IE Info Natice B4-08, "10CFR50 7, 'Employee Protection 'Svc list encl JORDAN, EL Division of Emergency Proparedness & Engineering Response (Post B30103) B4/02/14 Consolidated Edison Co of New York, Inc 115pp 22365 141 24% Fiche 50-000, B4/02/14, B401190039
- B401190045 IE Info Notice 83-63, Suppl I. "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN, E. L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366 142 24X Fiche 50-000, 84/02/15, 8401190045
- 8402280489 Ack receipt of 840126 ltr informing NRC of addl steps taken to correct violations noted in IE Insp Repts 50-259/83-33, 50-260/83-33 & 50-296/83-33 LEWIS,R C Division of Project & Resident Programs. 84/02/15 PARRIES,H @ Temnessee Valley Authority ip 22407 001. 24X Fiche 50-239,84/02/15,8402280489
- --8402280498 Forwards supplemental response to NRC 630921 ltr reviolations noted in IE Insp Repts 50-259/83-33, 50-260/83-33 & 50-276/83-33 M/o encl
 MILLS,t. M. Tennessee Valley Authority 84/01/20 O'REILLY, J.P. Region 2, Office of Director ip 22407 002 24x
 Fiche 50-259, 84/02/15, 8402280489
- --8402280504 Supple response to NRC 830921 ltr re violations noted in IE Insp Repts 50-299/83-33,50-260/83-33 & 50-294/83-33 Corrective actions. Tech Spec amend request submitted for Units 2 & 3 re APRM gain adjustments, KAMMER.D S Tennessee Valley Authority 84/01/26 O'REILLY, J P Region 2, Opfice of Director 2pp 22407.003, 24X Fiche 50-259,84/02/15.8402280489
- --8402280312 Ack receipt of 831024 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-297/83-33. 50-250/83-33 \$50-296/83-33 Supplemental response requested for Item C re APRM pain settings LEMIS.R C Division of Project & Resident Programs. 83/12/16-PARTS.H G Tennessee Valley Authority 2pp 22407:005 24% Fichs 50-259, 84/02/15, 8402280489
- --8402280520 Ack receipt of 831024 ltr informing NRC of steps taten to correct violations noted in IE Inap Rapts 50-257/83-33, 50-260/83-33 & 50-276/83-33 Response under review LEHIS,R C Division of Project & Resident Programs 83/11/09 PARRIS,H C. Tennessee Valley Authority ip 22407.00° 24% Fiche 50-259, 84/02/15, 8402280489
- --84022B0530 Responds to NRC B30921 ltr re violations noted in IE Insp Repts 50-259/83-33,50-260/83-33 & 50-296/83-33 Corrective actions shift technical advisor log book modified to assure required info gathered & cable tray deficiencies corrected MILLS.L.M. Tennessee Valley Authority B3/10/24. O'REILLY, J.P. Region 2. Office of Director. 7pp 22407 008 24X Fische 50-259,84/02/15,8402280489.
- --8402280540 Forwards IE Insp Repts 50-259/83-33,50-260/83-33 & 50-296/83-33 on 830726-0825 & notice of violation LEWIB.R C Division of Project & Resident Programs 83/09/21 PARRIB.H O. Tennessee Valley Authority. 2pp. 22407 015. 24X Fiche 50-259,84/02/15,8403280489.
- --8402280543 Notice of violation from insp on 830726-0825 * Region 2, Office of Director 83/09/Ri. 2pp 22407 017. 24% Fiche:50-259,84/02/15,8402280489
- --8402280552 IE Insp Repts 50-259/83-33,50-260/83-33 & 50-296/83-33 on 830726-0825 Noncompliance noted failure to have equipment installed in accordance w/drawings, follow leak detection monitoring procedures & update as-constructed drawings. PAULK.9 L Region 2. Office of Director CANTRELL, F. B. Division of Project & Resident Programs 83/09/20 14pp. 22407.019. 24% Fiche 50-259.84/02/15,8402280489
- 8402280022 Forwards response to JE Bulletin 84-01 re cracks in SWR Harl I containment vent headers. Testing for cracks performed using differential pressure data No cracks observed.

 MILLS.L M Tennessee Valley Authority 84/02/16. O'REILLY, J. P. Region 2, Office of Director 2pp. 22401:110. 24%

 Fiche 50-259,84/02/16,8402280022.

- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 114pp 22366 024 24X Fiche 50-000,84/02/21,8401190062
- d402280132 Confirms 840224 anforcement conference at Region II oft to discuss bypassing rod sequence control sys during shutdown k isolation of drywell to suppression pool differential pressure instruments, per 840217 telcon
 D'REILLY, J.P. Region 2, Office of Director 84/02/21 PARRIS, H G
 Tennessee Valley Authority 2pp 22400 270 24X
 Fiche 50-259,84/02/21,8402280132
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies"
 Eve list ench
 JORDAN, E. L. Division of Emergency Preparadness & Engineering
 Response (Post 830103). 84/02/24 Consolidated Edison Co. of New
 York, Inc. 115pp 22430 304 24% Fiche 50-000.84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
 Svc list encl
 JORDANNE L Division of Emergency Preparedness & Engineering
 Response (Fost 830103). 84/02/27 Consolidated Edison Co of New
 York, Inc. 120pp 22431 060 24X Fiche 50-000.84/02/27, 8401190067
- A. Periodic operating reports & related correspondence
- 8402070302 "NPDES Discharge Monitoring Rept.Oct-Dec 1983" # Tennessee Vallay Authority 83/12/31 54pp 22099 001 24X Fiche 50-259.83/12/31.8402070302
- S Reportable occurrences, LERs & related correspondence
- B402i00421 "Rept Concerning Effects of Control Sys Failures on Overfill to Overcooling Events at Browns Forry," interim rept BAXTER, D. E. BRUSKE, S. J. MORKEN, D. J. EORO, Inc. FIN A-6477 EQG-EA-6333 83/10/31 Division of Safety Technology 197pp 22211-16B 24X Fichs 50-299, 83/10/31, 8402100421
- 8402020033 Partial response to FOIA request for documents re evaluation or review of design.const.scheduling.cost & licensing of facilities from 1977 to present Forwards App A & II documents
 FELTON.J.M Division of Rules and Records 83/11/04 ZACK.A M Barris, Bott, Denn & Driker 11pp 22079 208 24X Fiche 50-000.83/11/04.8402020033
- --B402020092 Submits B20112 daily staff notes of PNO-II-B2-006 & PNO-II-B2-007 & review of changes to GA organization at plant site & matters or anguing soil settlement hearing Related info encl
 DIRCKS.W J Defice of the Executive Director for Operations 82/01/13 PALLADINO, N Commissioners 23pp 22081/118 24) Fichar 50-000, 83/11/04, 8402020033
- 8402230347 Updates status rept on BWR pipe cracks & protection of upcoming licensee actions Insp results encl Evaluation & recommendations re interim & long-term remedial measures expected by May 1984.

 DIRCKS W J Diffice of the Executive Director for Operations BECY-84-009A 84/01/27 5pp 22377 047 24X Fiche 50-000, 84/01/27, 8402230347
- 8402220477 LER 84-002-00 on 840125.Div I logic initiated & secondary containment isolation alarms received Caused by primary logic relay failing in conservative direction. Relays replaced & div logic returned to svc W/840216 ltr. BMITH.D.L., JONES.G.T. Tennessee Valley Authority 84/02/16 3pp 22039:266. 24% Fiche:50-296,84/02/16,8402220477
- 8402280013 LER 84-003-00, on 840129, during transfer of 4 kV start bus 1B from alternate to normal feed, normal feed breaker failed to close, resulting in momentary loss of voltage & automatic start of diesel generators 3C & 3D W/840222 ltr.

 BMITH.D. L. JONES.O.T. Tennessee Valley Authority 84/02/22 3pp 22400-272 24X Fiche 50-276,84/02/22,8402280013

V. Operator Examination

B402010337 Notification of contract execution "Use of TVA Réactor Bimulator Facilities at Chattanooga, TN for Training on Browns Ferry. Bequoyah & Bellefonte Bimulators." JESBUP.B Technical Assistance Contracts Branch FIN B-8717 B3/12/27. SHOWE.B K. Director's Office. Office of Inspection and Enforcement. ip. 22059 229. 24X Fiche 50-000.83/12/29,8402010337

- --B402010346 Ltr contract NRC-05-B4-153, "Use of TVA Reacter Simulator Facilities at Chattanoogs TN for Trakning on Browns Ferry, Sequepah & Bellefonte Simulators:" awared to TVA MERTEN, K V Technical Assistance Contracts Branch FIN B-B717 B3/12/29 JUHNSUN.R J Tennessee Valley Authorite 6pp 22059 230 24X Fiche 50-000. B3/12/29, 8602610337
- 84021402/4 Confirms arrangements for NRC administration of requalification exams on 840316-19 Exams intended to evaluate effectiveness of actions taken to strengthen operator training program since 831118 requalification exam VERRELLI.D M Division of Project & Resident Programs 84/01/17 OREEN.H J Tennessee Valley Authority 3pp 22228 191 24X Fiche 50-237,84/01/17,8402140274
- 8402140494 Forwards summary of 840118 meeting w/util re plans for strengthering program for requalification of licensed operator & senior operator personnel Subje discussed & meeting attendees provided LEWIS.R C Division of Project & Resident Programs 84/02/03 PARRIS.H G Tennessee Valley Authority 2pp 22221 106 24x Fiche 50-259,84/02/03,8402140494
- B402280234 Informs of review of 1983 accelerated requalification training program lesson plans Plans based on learning objectives show aignificant improvement over earlier plans NRC will not restrict scope of questions on eram VERRELLI.D M Division of Project & Resident Programs B4/02/15 PARRIS.H 9 Tennessee Valley Authority 2pp 22399 240 24X Fiche 50-259,84/02/15,8402280234
- DOCKET 50-297 NORTH CAROLINA STATE UNIV PULSTAR REACTOR F Security, medical, emergency & fire protection plans
- 8402170440 Forwards Amend 7 to License R-120, incorporating latest requirements re-physical security plan
 THDMA9.C O Standardization & Special Projects Granch 84/02/10
 THDMA9.J L North Carolina State Univ , Raleigh, NC 3pp
 22313 159 24X Fiche 50-297,84/02/10,8402170440
- --8402170443 Amend 7 to License R-120, revising physical security plan THOMAS, C O Standardization & Special Projects Branch 84/02/10 2pp 22313 163 24X Fiche 50-297,84/02/10,8402170440

H General correspondence

- 8402140381 Informs that J Thomas resigned as chancellor of North Carolina State Univ to accept presidency of Univ of Alabama on 810630 New chancellor is BR Poulton BIMPSON.W H North Carolina State Univ, Raleigh, NC 84/02/06 THOMAS, C 0 Standardization & Special Projects Branch 1p 22220 055 24X Fichs 50~277,84/02/06.8402140381
- P Operating license stage documents & correspondence
- 8402170440 Forwards Amend 7 to License R-120, incorporating latest requirements re-physical security plan THOMAS.CO Btandardization & Special Projects Branch 84/02/10 THOMAS.U North Cerolina State Univ , Raleigh, NC 3pp 22313 157 24X Fiche 50-297,84/02/10,8402170440
- --B402170443 Amend 7 to License R-120, revising physical security plan THOMAB, C O Btandardization & Special Projects Branch 84/02/10 Rpp 22313-163, 24X Fiche 50-297,84/02/10,8402170440

DOCKET 90-298 COOPER NUCLEAR STATION

F. Security, medical, emergency & fire protection plans

- B402170287 Revised emergency plan implementing procedures, including corrected Procedure 5 7 5 re general emergency & Procedure 5 7 13 re personnel manitoring & decontamination W/840213 1tr
 PILANT, J Nebraska Public Power District 84/01/23 COLLINS, J T Region 4, Office of Director, 24pp. 22297:076 24x Fiche 50-298,84/01/23.8402170287.
- B402270228 Revs to emergency plan implementing procedures consisting of Rev 3 to EPIF 5 7 3, "Alert Implementing Procedure," Rev 3 to EPIF 5 7 8. "Activation of Operation Gupport Ctrs" & Rev 3 to EPIF 5 7.12, "Emergency . " W/840221 ltr WINDHAM,R, PILANT,J M Nebraska Public Power District. 84/02/11 COLLING.J T. Repion 4. Office of Director 20pp 22384:305 24x Fiche.50-278.84/02/11.8402270228

- B402210043 Act receipt of 831215 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-298/83-24
 JOHNSON, E H Region 4, Office of Director B4/02/13 PILANT, J M Nebraska Public Power District 2pp 22317 255 24X
 Fiche 50-298,84/02/13,8402210043
- --9402210047 Responds to NRC 831110 ltr re violations noted in IE Insp. Rept 50-298/83-24 Corrective actions Class 350 UL-rated file cabinets ordered to provide adequate fire protection PILANT.J M. Nobraska Public Power District 83/12/05 JOHNSON. & H. Region 4. Office of Director 2pp 22317 297 24X Fiche 50-298.84/02/13.8402210043
- P Operating license stage documents & correspondence
- B312120029 Generic Ltr B3-39 to representatives of utils re voluntary survey of licensed operators Evc list encl EJSERMUT.D 0 Division of Licensing 83/12/08 Commonwealth Edison Co 12pp 22313 004 24X Fiche 50-000.B3/12/08.B312120029
- 8402070458 Forwards safety evaluation re Mark I containment long-term program pool dynamic & structural load aspects VASSALLO.D B Operating Reactors Branch 2 84/01/20 PILANT, J M Nebraska Public Power District 3pp 22141 350 24x Fiche 50-298.84/01/20.8402070458
- -0402070460 Gafety evaluation supporting Mark I containment long-term program pool dynamic loads review + Office of Nuclear Reactor Regulation. Director 84/01/20 2pp 22141 330 24) Fiche 50-298.84/01/20.8402070458
- -8402070462 Bafety evaluation supporting Mark I containment long-term program structural review * Office of Nucloar Reactor Regulation, Director 84/01/20 3pp 22141 355 24% Fiche 50-298,84/01/20,8402070458
 - 310050311 "Technical Evaluation of Cooper Plant-Unique Analysis Rept "RANLET, J D Brookhaven National Laboratory FIN A-3713 ONL-04283 63/09/30 NRC No Detailed Affiliation Given 26pp 66797 135 24% Fiche 50-298.84/01/20.6402070458
- 301170355 "Audit for Mark I Containment Long-Term Program Structural Analysis for Operating Reactors Cooper Nuclear Station," technical evaluation rept SUBRAMONIAN, N Franklin Institute/Franklin Research Center NRC-03-81-190 TER-C5506-316 83/01/12 SHAW, H NRC No Detailed Affiliation 01/00 42pp 22142 022 24x Fiche 30-298,84/01/20,8402070458
- -8402070470 "Audit For Mark I Containment Long-Term Program Structural Analysis for Operating Reactors," supplementary technical evaluation rept E.A K. SUBRAMONIAN.N Franklin Institute/Franklin Research onter NRC-03-81-130 TER-05506-418 83/08/17 SHAW.H NRC -Detailed Affiliation Given 9pp 22142 064 24X che 50-298,84/01/20,8402070458
 - 0363 Forwards Amend B4 to License DPR-46 & safety evaluation dichanges Tech Specs to incorporate changes to inservice properm to conform to changes in regulations SGEL.B L. Operating Reactors Branch 2 84/01/20 PILANT, J M brasks Public Power District 2pp 22207 318 24% che 50-298.84/01/20.8402100363
 - D2100366 Amend 84 to License DPR-46 revising Tech Specs to incorporate changes to inservice lass program to conform to changes in regulations VASSALLO B Uperating Reactors Granch 2 84/01/20 9pp 22207 320 24% Fiche 50-298
 - 210037k Safety evaluation supporting Amend 84 to License DFR-46 Office of Nuclear Reactor Regulation, Director 84/01/20 2 22207 329 24% Fiche 50-298,84/01/20,8402100363
 - 20029 Application for amend to License DPR-46.consisting of posed Change 12.revising LER sys
 CL.L 9 Nebraska Public Power District 84/02/14 VASBALL stating Reactors Branch 2 Jap 22326 019 24X he 50-298.84/02/14.8402220029 84/02/14 VASSALLD, D B
 - 2220032 Proposed Tech Spec Change i2, revising LER sys Nebraska Public Power District 84/02/14 12pp R2326 022 4X Fiche 50-299,84/02/14,8402220029

- 9 Inspection reports. IE Bulletins & correspondence
- 8402030225 Forwards IE Insp Rept 50-298/83-25 on 830926-30 & motice JOHNSON, E.H. Region 4, Office of Director 83/12/00 PILANT, J. Nebraska Public Power District 2pp 22067 241 24X Fithe 50-298,83/12/09,8402030225
- --8402030228 Notice of violation from insp on 830926-30 * Region 4. Office of Director 83/12/08 3pp ; Fiche 50-298,83/12/08,8402030225 22067 243 241
- --8402030238 IE Insp Rept 50-298/83-25 on 830926-30 Violations noted failure to perform leak tests for contamination on 27 radioactive sources within 6-month interval Contract worker performed work in drywell w/a wearing monitoring devices
 BAER, R E , MURRAY. B , HUNNICUTT, D M Region 4, Defice of Director
 83/11/18 13pp 22067 246 24X Fiche 50-298,83/12/08,8402030225
- 8402220480 Forwards IE Insp Rept 50-278/83-30 on 831017-gi No violations or deviations identified JOHNSON.E H Region 4, Office of Director 83/12/23 PILANT, J M Nebrasta Public Pawer District 2pp 22340 111 24x Fiche 80-278.83/12/23,8402220480
- --8402220484 IE Insp Rept 50-278/83-30 on 831017-21 No violations or deviations noted Major areas inspected staffing/training program. licensee audits of radiochemistry activities, sample troatment & analysis & analysical procedures
 NICHQLAS.J J., WISE.R., MURRAY.B. Region 4. Office of Director 83/12/16 20pp 22340 113 24X Fiche 50-278,83/12/23,8402220480
- 8402220533 Forwards IR Insp Rept 50-298/83-32 on 831128-1201 No vialations or deviations identified JUMNSON, E H Region 4, Office of Director 83/12/23 PILANT, J M Nebraska Public Power District 2pp 22333 285 24x Fiche 50-298,83/12/23,8408/220533
- --B402220535 IE Insp Rept 50-298/83-32 on 831128-1201 No violations or deviations identified Major areas inspected training & requalification training JAUDON, J P. JOHNSON, W D., HUNNICUTT, D M. Region 4, Office of Director 83/12/19 Bpp 22333 287 24X Fiche 50-298,83/12/23,8402220533
- 8402220257 Forwards IE Insp Rept 50-298/83-33 on 831128-1202 No violations or deviations noted JUHNSON, E H Region 4. Office of Director 84/01/10 PILANT. J M Nebraska Public Pawer District 2pp 22335 188 24x Fiche 50-298
- --8402220261 IE Insp Rept 50-298/83-33 on 831128-1202 No violations or deviations noted Major areas inspected transportation activities, including mgt controls, indoctrination & training, audit program. GA & spent fluct shipments

 BAER.R E : MURRAY.B : HUNNICUTT.D M Region 4: Defice of Director 83/12/30 10pp 22335 170 24X Fiche 50-278,84/01/10.
- 8402070235 Forwards IE Insp Rept 50-278/83-34 on 831201-31 No violations or deviations noted JOHNBON,E H. Region 4. Defice of Director 84/01/20 PILANT, J M Nebroska Public Power District 2pp 22101.133 24X Fiche 50-278.84/01/20,8402070235
- -8402070238 IE Insp Rept 50-298/83-34 on 831201-31 No violations or deviations noted Major areas inspected operational safety vorifications, monthly surveillance & maint observations, plant trips & safety sys challenges
 DUBDIS, D L . HUNNICUTT, D M Region 4. Office of Director 84/01/19 7pp. 22101 135 24X Fiche 50-298,84/01/20,8402070235
- 8402100263 Forwards Amend 84 to License DPR-46 & safety evaluation Amend thanget Tach Spacs to incorporate changes to inservice insp propram to conform to changes in regulations SIEGEL, B L Operating Reactors Branch 2, 84/01/20 PILANT, J. M Nebraska Public Power District 2pp 22207, 318 24% Fiche 50-278, 84/01/20, 8402100363.
- --8402100366 Amend 84 to License DPR-46, revising Tech Specs to incorporate changes to inservice insp program to conform to changes in regulations VASSALLO.D. B. Operating Reactors Branch 2 84/01/20 9pp, 22207 320 24X Fiche. 50-298,84/01/20,8402100363
- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Fumps." Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Fost 830103). 84/01/25 Consolidated Edison Co. of New York, Inc 120pp 22058.001 24X Fiche 50-000,84/01/25,8312120133

- 8401190016 IE Info Notice 84-07. "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York. Inc 119pp 22114 179 24X Fiche 50-000.84/02/03,8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers." Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement B4/02/03 Consolidated Edison Co of New York, Inc 102pp 22177
- 8402100198 Ack receipt of 840105 ltr informing NRC of steps taken to correct violations & deviations noted in IE Insp Rept 50-298/83-26
 JCHNBON.E H Region 4, Office of Director 84/02/06 PILANT, J M Nebraska Public Power District 1p 22178 012 24X
 Fiche 50-298.84/02/06.8402100198
- --8402100202 Responds to NRC 831206 ltr re violations & deviations noted in IE Insp Rept 50-298/83-26 Corrective actions refresher training administered for design initiation & review of governing procedures for design changes
 PILANT.J M Nebraska Public Fower District 84/01/05
 JOHNSON.E H Region 4. Defice of Director 4pp 22178 013 24x
 Fiche 50-298,84/02/06,8402100198
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CR50, App R)" Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of Naw York, Inc. 124pp 22365 259 24X Fiche 50-000.84/02/13,8401190041
- 8402210043 Ack receipt of 831215 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-298/83-24 JBHN80N, EH Region 4. Defice of Director 84/02/13 PILANT, J M Nabraska Public Power District 2pp 22317 255 24X Fiche 50-298.84/02/13.8402210043
- --8402210047 Responds to NRC 831110 ltr re violations nated in IE Insp Rept 50-298/83-24 Corrective actions Class 350 UL-pated file cabinets ordered to provide adequate fire protection PILANT.J M Nebraska Public Power District 83/12/05 JOHNSON.E H. Region 4. Diffice of Director 2pp 22317 257 24X Fishs 50-298.84/02/13,8402210043
- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection'"
 Syc list encl
 JDRDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc 113pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- 8401170045 IE Info Notice 83-43, Suppl 1, "Potential Failures of Westinghouse Type 8A-1 Differential Relays" Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc 118pp 22346 142 24X Fiche 50-000,84/02/15,8401170045
- 8401170062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches 8st Below Manufacturer Recommended Value "Svc list encl. JURDAN, E L Division of Emergency Preparedness & Enginearing Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000,84/02/21,8401170062
- B4011900&6 IE Info Notice 84-11, "Training Program Deficiencies" Bvc list encl.

 JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/24 Consolidated Edison Co of New York, Inc 115pp 22430 304. 24X Fiche 50-000,84/02/24,8401190066
- E401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
 Syc list encl.
 JURDAN.E.L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27. Consolidated Edison Co of New
 York, Inc 120pp. 22431 060 24X Fiche 50-000.84/02/27,8401190067
- S Reportable occurrences, LERs & related correspondence
- 8402230347 Updates status rept on BWR pipe cracks & protection of upcoming licenses actions Insp results encl Evaluation & recommendations re interim & long-term remedial measures expected by May 1984
 DIRCKB.W J Dffice of the Executive Director for Operations SECY-98-009A 84/01/27. Spp 22377 047 24X Fiche, 50-000, 84/01/27, 8402230347

- 8402280355 LER 84-003-00 on 840130 high average power range monitor high flux reactor trip occurred causing reactor feedwater pump trip Caused by personnel errors Plant stabilited & personnel counseled W/840224 ltr BRUNGARDIR R THUMASON.P V Nebraska Public Power District B4/02/24 4pp 22402 271 24X Fiche 50-278.84/02/24,8402280355
- B4022B037B LER 84-001-00 on 840120 reactor vessel water level indicating switch NBI-LI8-101D failed to reset when simulated high level signal removed Caused by component end-of-life Microswitch replaced W/B40224 ltr KRAUBE:R W , THOMABON.P V Nebraska Public Power District 84/02/24 3pp 22405 022 24X Fiche 50-27B.84/02/24.8402280378
- 8402280474 LER 84-002-00 on 840129, piece of reactor bldg aluminum siding detached & blew onto 161 kV line.creating electrical short to startup transformer & causing eventual reactor scram Caused by high winds W/840224 ltr
 BRUNDARDT.R. THOMAEDN.P V Notraska Public Power District
 84/02/24 3pp 22404 357 24X Fithe 50-298.84/02/24,8402280474
- BOCKET 50-301 POINT DEACH NUCLEAR PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8402140239 Forwards security plan changes & drawings & responses to IE Safeguards Insp Repts 50-266/83-22 & 50-301/83-21 Encls withheld (ref 100FR73 21) BURSTEIN.8 Wisconsin Electric Power Co 84/01/23 KEPPLER, J G Region 3, Dffice of Director 1p 22220 282 24X Fiche 50-266.84/01/23.8402140239
- B402070116 Revs to emergency plan manual consisting of Rev 21 to EP 4 0, "Emergency Conditions" & EP 8 0, "Maintaining Congress," Rev 4 to App D. "Ltrs of Agreement" & App F. "Manitowoc County Nuclear " #/840131 ltr FAY.C W Wisconsin Electric Power Co Office of Nuclear Reaction Power Co Office of Nuclear Reaction Director 20pp 22102 283 24X Fiche 50-266:B4/01/27,8402070116
- 8402140454 Ack receipt of 840123 ltr informing NRC of steps taken to correct nancampliance noted in IE Insp Repts 50-266/83-22 & 50-301/83-21 AXELBON,W L Region 3. Office of Director 84/02/02 BURSTEIN.S Wisconsin Electric Power Co 1p 22227 109 24X Fiche 50-266,84/02/02,8402140454
- ---B402140464 Responds to NRC B31220 itr re violations noted in IE Insp Repts 50-266/B3-22 & 50-301/83-21 Corrective actions withheld (ref 10CFR73 21) BURSTEIN.S Misconsin Electric Power Co B4/01/23 KEPPLER, J Q Region 3, Defice of Director 1p 22227 110 24X Fiche 50-266.B4/02/02.B402140434
- B40215036B Forwards BERs 50-266/83-25 & 50-301/83-23 & notice of deviation re review of revised emergency plan dtd B31111 PAPERIELLO.C J Region 3. Office of Director 84/02/02 BURSTEIN.S Wisconsin Electric Power Co 3pp 22242 029 24) Fiche 50-266.84/02/02.840215036B
- --8402150377 Notice of deviation from commitment to formalize agreement w/City of Two Rivers for ambulance svc * Region 3, Office of Director 84/02/02 ip 22242 032 24X Fiche 50-266,64/02/02,8402150368
- --8402150386 SERs 50-266/83-25 & 50-301/83-23 Deviation noted emergency plan did not contain ltr of agreement w/Bechtel nor ltr formalizing ambulance svc w/City of Two Rivers SNELL,W 0 , PAPERIELLD,C J Region 3, Office of Director 84/02/01 28pp 22242 033 24X Fiche 50-266,84/02/02,8402150368
- 8402100822 Forwards revised smergency plan implementing procedures FAY.C W Misconsin Electric Power Co 84/02/03 DENTON, H R Office of Nuclear Reactor Regulation. Director MILLER, J R Operating Reactors Brench 3 3pp 22178
- --8402100229 Revised emergency plan implementing procedures, including Rev 9 to Procedure EPIP 1.3 re estimation of source term. Rev 6 to EPIP 1.5 re protective action evaluation & Rev 5 to EPIP 2.3 re unusual event offsite agency notification
 **Wisconsin Electric Power Co 84/01/27 100pp 22178:146 24X Fiche 50-266,84/02/03.8402100222
- 8402100227 Advises that emergency plan reve meet 10CFR50 47(b) stds & 10CFR50, App E requirements Changes to emergency plan implementing procedures should be made per 10CFR50, App E. Section V
 PAPERIELLO, C. J. Region 3, Office of Director 84/02/07 BURSTELLO, E. Wisconsin Electric Power Co. 1p. 22179, 268 24X
 Fiche 50-266, 84/02/07.8402100229

- -8402100234 Forwards revs to emergency plan manual & instruction & receipt form M/o revs
 FAY.C W Hisconsin Electric Power Co 84/01/3! DENTON.H
 Office of Ruclear Reactor Regulation. Director MILLER.J R
 Operating Reactors Branch 3 2pp 22179 269 24X
 Fiche 50-266.84/02/07.8402100229 DENTON, H. R.
- 8402220544 Ack receipt of changes to modified amended security plan transmitted by 840123 itr Changes consistent w/provisions of iOCFR5D 54(p) & acceptable AXELSON, W L. Region 3, Office of Director 84/02/15 FAY. C W Hisconsin Electric Fower Co. 2pp. 22333 i30 24% Fiche 50~266.84/02/15.8402220544

O Adjudicatory correspondence

- 8402070128 Order extending time until 840213 for Commission to act to review Director's Decision DD-83-14 & extending 831027 decision denying Environ Policy Inst request to 840213 CHILK, 5 J Office of the Secretary of the Commission 84/02/03 Commissioners 1p 22100 198 24X Fiche 50-000.84/02/03.
- 8402150195 Order extending time until 840221 for Commission to act to review Director's Decision DD-63-14 CHILKS J Office of the Secretary of the Commission 84/02/13 Commissioners 1p 22245 147 24X Fiche 50-000.84/02/13.
- P Operating license stage documents & correspondence
- B312120027 Generic Ltr 83-39 to representatives of utils re voluntary survey of licensed operators Svc list encl EISENHUT.D © Division of Licensing B3/12/0B Commonwealth Edison to 12pp 22313 005 24X Fichs 50-000.83/12/08.8312120029
- 8402070490 Forwards safety evaluation re NUREO-0737.1tem II K 2 17, "Potential for Voiding in RCS Buring Transiants." per 801223 to 820426 submittals & Nestinghouse Owners Group Rept WOG-57 Item satisfactorily resolved HILLER, J R Operating Reactors Branch 3 84/01/24 FAY, C W Hisconsin Electric Power Co 10pp 22141 340 24X Fiche 50-266.84/01/24.8402070490
- 8402090519 Summary of 840110 meeting w/util in Betheads. HD re licensee requested exemptions from requirements of & extension to effective date of shift staffing rule, ICCFR50 54 List of COLBURN.T G Operating Reactors Branch 3 84/01/24 MILLER.J R Operating Reactors Branch 3 5pp 22171 354 24X Fiche 50-266.84/01/24.8402090517
- 8402080194 Application for amend to Licenses DRR-24 & DRR-27, consisting of Tech Spec Change Request 97 per Generic Ltr 83-43 reflecting revised reporting requirements FAY.C W Wisconsin Electric Power Co 84/01/27 DENTON, H R Defice of Nuclear Reactor Regulation, Director EISENHUT, D 0 Division of Licensing 2pp 22129 325 24% Fiche 50-266, 84/01/27, 8402080194
 - 34020B0197 Proposed Tach Spec Change Request 97 per Caneric Ltr 63-43, reflecting revised reporting requirements * Wisconsin Electric Power Co 84/01/27 8pp 22127 327 24K Fiche 50-226,84/01/27.84020B0194
- 402070186 Provides add1 info re status of auxiliary feedwater sys mods implemented in response to Generic Ltr 81-14 Last remaining mod involves replacement of battery rack support straps & should be completed by Oct 1984

 FAY.C W Hisconsin Electric Power Co 84/01/31 DENTON.H 8

 Office of Nuclear Reactor Regulation, Director MILLER, J R

 Operating Reactors Branch 3 ip 22102 193, 24X

 Fiche 50-266,84/01/31,8402070186
- 4020104i0 Generic itr 84-04 to all operating PHR licensess, CP holders & applicants for CPs re safety evaluation of Mestinghouse topical repts dealing w/elimination of postulated pipe breaks in PHR primary main loops 8vc list encl EIBENHUT.D © Division of Licensing 84/02/01 Consolidated Edison Cc of New York, Inc 57pp 22:77 087. R4X Fishe 50-000.84/02/01.8402010410
- 402160588 Forwards Amends 82 & 86 to Licenses DPR-24 & DPR-27. respectively & safety evaluation Amends clarify limiting tonditions for operation of steam generators & other DHR quipment only applicable when fuel loaded in core CLBURN.T 9 Deprating Reactors Branch 3 84/02/02 F. lisconsin Electric Power Co. 2pp 22302:054 24X chs 50-266.84/02/02.8402160588 84/02/02 FAY, C W

- --B402160590 Amends 82 & 86 to Licenses DPR-24 & DPR-27, respectively, clarifying limiting condition for operation of steam generators & other DHR equipment, indicating conditions only applicable when fuel loaded in core MILLER, J R Operating Reactors Branch 3 84/02/02 bpp 22302 036 24X Fiche 50-266.84/02/02,8402160588
- ~-B402160594 Safety evaluation supporting Amends 82 & 86 to License, DPR-24 & DPR-27, respectively Office of Nuclear Reactor Regulation, Director 84/02/02 2;; 22302 061 24X Fiche 50-266.84/02/02.8402160588
- B402130177 Application for mods to 831025 amend application, consisting of Toch Spec Change Request 94 incorporating changes to meet containment integrated leakage testing requirements of 10CFR50.App J
 FAY.C W Wisconsin Electric Power Co 84/02/07 DENTON, H R Defice of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 3pp 22204 146 24X Fiche 50-266.84/02/07.8402130177
- --8402130187 Proposed changes to Tech Specs incorporating changes to see containment integrated leak testing requirements of 100FR50. App J # Wisconsin Electric Power Co 84/02/07 5pp 22204 149 24x Fithe 50-266,84/02/07,8402130177
- 8402160181 Supple 831025 application for amend to Licenses DPR-24 to DPR-27, consisting of Tech Spec Change Request 94 recriteria for Type 4 integrated leak rate testing PAys Wisconsin Electric Power Co 84/02/07 DENYON, H R Office of Nuclear Reactor Regulation, Director MILLER, J. R. Operating Reactors Branch 3 110pp 22276 044 24X Fiche 50-266,84/02/07,8402160181
- ---B402160188 Proposed Tech Specs supplementing Tech Spec Change Request 94 re integrated leakage rate testing ** Misconsin Electric Power Co 84/02/07 5pp 22276 047. 24% Fiche 50-266.84/02/07.8402160181
- O Inspection reports, IE Bulletins & correspondence
- 8402140239 Forwards security plan changes & drawings & responses to IE Bafeguards Insp Repts 50-266/83-22 & 50-301/83-21 Entls withheld (ref 10CFR/3 21) BURSTEIN/S Wisconsin Electric Power Co. 84/01/23 KEFPLER/J @ Region 3, Office of Director ip 22220 282 24X Fiche.50-266,84/01/23,8402140239
- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fichs 50-000,84/01/25,831212033
- 8402140474 Ack receipt of 840123 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Repts 50-266/83-22 & 50-301/83-21 30-30763-x1 AXELBON,W L Region 3, Defice of Director 84/02/02 BURDTEIN 8 Wisconsin Electric Power Co ip. 22227 109 24X Fiche: 50-266, 84/02/02, 8402140454
- --8402140464 Responds to NRC 831220 itr re-violations noted in 1E [asp. Repts 50-266/83-22 & 50-301/83-21 Corrective actions withheld (ref 10CFR73 21)
 BURBTEIN.S Wisconsin Electric Power Co. 84/01/23 KEFPLER.J © Region 3, Office of Director ip 22227,110 24X fishe.50-266,84/02/02,8402140454
- 840215036B Forwards SERs 50-266/83-25 & 50-301/83-23 & notice of deviation re review of revised emergency plan dtd 831111 FAPERIELLD.C J Region 3, Office of Director 84/02/02. BURSTEIN.S Wisconsin Electric Power Co 3pp 22242 027 24X Fiche 50-266,84/02/02,8402150368.
- --8402150377 Notice of deviation from commitment to formalize agreement w/City of Two Rivers for ambulance svc * Region 3, Office of Director 84/02/02 1p 22242-032 248 Fiche 50-266,84/02/02.8402150368
- --8402150386 BERs 50-266/83-25 & 50-301/83-23 Deviation noted: emergency plan did not contain ltr of agreement w/Bechtel nor ltr formalizing ambulance syc w/City of Two Rivers BRELL, H G., BMITH, N J., PHILLIPS, M P. Region 3. Optics of Director B4/02/01 28pp. 22242 033 24X Fichs 50-266.84/02/03.8402150368
- B401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls." Syc list encl JORDANIE 1. Division of Energency Preparadness & Engineering Response (Post 830103) B4/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche. 30-000. 84/02/03, 8401190016

- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers." Syc list encl DEYBUNG.R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp. 22177
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R) " Bvc list ancl.
- encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22265 259 24X Fiche 50-000,84/02/13,8401190041
- E401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '"
- Evc list encl

 JORDAN.E L Division of Emergency Preparedness & Engineering

 Response (Post B30103) B4/02/14 Consolidated Edison Co of New

 York, Inc 115pp 22365.141 24X Fiche 50-000.84/02/14.8401190039
- 8401190045 IE Info Notice 83-63. Buppl 1, "Potential Failures of Westinghouse Type 8A-1 Differential Relays" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15. Consolidated Edison Co of New York, Inc. 118pp 22366 142 24X Fiche 50-000,84/02/15,8401190045
- 8401170062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co. of New York, Inc. 116pp 22366 024 24X Fiche 50-000,84/02/21,8401170062
- 8402280433 Provides tabulated listing of plant first 10-yr inservice insp interval exams & applicable relief requests FAY.C W Misconsin Electric Power Co BA/OZ/AZ DENTON, H R. Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 39pp 22403 033 24X Fichs: 50-301.84/02/22.8402280433.
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies "
- |Oil90066 IE Info Notice of ...

 Byc list encl

 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 Yark, Inc 115pp 22430, 304, 24% Fiche 50-000, 84/02/24, 8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
- Svc list encl JORDAN, E. L. | BVC list enci. JGRDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/27 Consolidated Edison Co. of New Yark, Inc. 120pp 22431 060 24X Fiche 50-000.84/02/27,8401170067
- A. Periodic operating reports & related correspondence
- 8402140227 Monthly operating repts for Jan 1984 W/840209 ltr FAY.C W Wisconsin Electric Power Co 84/01/31 10pp 22230:011 24X Fiche: 50-266.84/01/31.8402140227.

V. Operator Examinations

- B402210120 Revises 830930 submittal re licensed operator staffing. Extension until 850301 for implementation date requested. Util withdraws exemptions for second senior reactor operator & third operator when one unit running & second refueling. FAY.C W Hisconsin Electric Power Co 84/02/14 DENTON.H R PAY, U. W. Wisconsin Electric Power Co. 84/02/14 DENTON, H. R. Diffice of Nuclear Reactor Regulation, Director. Spp. 22317.203 24% Fichs. 50-266, 84/02/14, 8402210120
- DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3
- F. Security, medical, emergency & fire protection plans
- 8402010186 Advises that Class II fee appropriate for 830414 application to revise Tech Specs re administration controls to modify addit frequencies of security, emergency & fire protection
 - plans, MILLER.W.O License Fee Management Branch, 84/01/20 WILQUB, k Florida Power Corp. 1p. 22048 032 24X Fiche 50-302,84/01/20, 8402010186. 84/01/20 WILQUE, W S.
- 8402060379 Forwards planned changes to modified amended security plan. Rev 2. Changes withheld (ref 10CFR73 21)
 HESTAFER: 0 R Florida Power Corp 84/01/23 O'REILLY, J. P Region 2. Office of Director 1p 22086:316 24X Fiche: 50-302, 84/01/23, 8402060379.
- 8402280442 Forwards IE Insp Rept 50-302/83-30 on 841130-1219. No Violations or deviations identified DANCE, H. C. Division of Project & Resident Programs. 84/01/26 WILOUS M. S. Florids Power Corp. 2pp. 22407 179 24X Fichs. 50-302, 84/01/26, 8402280442 84/01/26.

- --8402280446 IE Insp Rept 30-302/83-30 on 841130-1219 No violations or deviations identified Major areas inspected plant operations, security, radiological controls, action on IE Bulletin 83-05.LERS & nonconforming operations repts
 STETKA: T F Region 2. Office of Director PANCIERA.V W Division
 of Project & Resident Programs 84/01/25 9pp 22407 181 24X
 Fiche 50-302.84/01/26.8402280442
- 8402150199 Forwards application to amend License DFR-72, consisting of proposed Rev 4 to physical security plan, originally submitted 820506 WESTAFER, G R Florida Power Corp 84/02/06 STOLZ, J F Operating Reactors Branch 4 2pp 22245 250 24X Fichs 50-302, 84/02/06, 8402150199
- --8402150203 Application for amend to License DFR-72, consisting of proposed Rev 4 to security plan
 * Florida Power Corp 84/02/06 10pp 22245 252 24X Fiche 50-302,84/02/06 8402150159
- H General correspondence
- 8402130226 Requests that 8A Grandimore be removed from svc list All further document distribution should be forwarded to RW Neiser, senior vice-president & general counsel EVERTZ. H, A Florida Power Corp 84/01/31 INGRAM.R Operating Reactors Branch 4 2pp 22204 169 24X Fiche 50-302, 84/01/31, 8400130324
- P Operating license stage documents & correspondence
- B312120029 Generic Ltr 83-39 to representatives of utils re voluntary survey of licensed operators Svc list encl EISENHUT.D 0 Division of Licensing B3/12/08 Commonwealth Edison Co 12pp 22313 006 24% Fiche 50-000.83/12/08.8312120029 12pp
- 8402010186 Advises that Class II fee appropriate for 830414 application to revise Tech Specs re administration controls to modify audit frequencies of security, emergency & fire protection plans MILLER.W O. License Fee Management Branch 84/01/20. WILQUS,W 8 Florida Power Corp ip 22048 032 24X Fichs 50-302,84/01/20. 8402010186
- 8402070478 Notification of 840215-16 meetings w/util at plant site to discuss planning & implementation of various TMI action plan (NNRGe-0737) item HERNAN,R W Operating Reactors Branch 4 84/01/27 STOLZ,J F Operating Reactors Branch 4 3pp 22142 076 24X Fiche 50-302,84/01/27,8402070478
- 8402050435 Forwards description of mod details to ESF actuation sysproviding capability for on-line testing of instrumentation logic Mod installation scheduled for 850307 W/15 oversize drawings Aperture cards in PDR WESTAFER, 0 R Florida Power Corp 84/01/30 STOLZ, J F Operating Reactors Branch 4. 24pp 22083 046 24X Fiche. 50-302, 84/01/30, 8402050435.
- 8402060226 Supple S31104 response to Generic Ltr S3-28 re ac 2 % dc 4 control rod drive sys breaker preventative meint on 6-month interval Undervoltage trip attachment 2 clamp will be chacked for orientation % latch adjustment will be improved WESTAFER, 0 R Florida Power Corp 84/01/31 STGLZ.J F Operating Reactors Branch 4. 2pp. 22087 261 24X Fiche 50-302,84/01/31,8402060226 Operating
- 8402080021 Forwards minutes of 831215 meeting re equipment qualification issue resolution Minutes reflect results of 840124 telcon Response to IE Info Notice 79-22 considered in B40124 telcom Heapons to IE Info Notice 79-22 considered in Encl 3 methodology HEBTAFER, 9. R. Florida Power Corp. 84/01/31 BT0LZ, J.F. Operati Reactors Branch 4. 112pp. 22128, 095 24X Fiche 50-302, 84/01/31, 8402080021
- B40D010410 Generic Ltr B4-04 to all operating PWR licensees.CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Svc list encl. EISENHUT,D 0. Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc. 59pp 22177 087 24X Fiche.50-000.84/02/01.8402010410
- 8402080134 Supplemental application to amend License DPR-72, consisting of Tech Spec Change Request 96 re intake canal dimensions Requests amend be issued prior to June 1985 canal survey. MESTAFER, G.R. Florida Power Corp. 84/02/03. STOLZ.J F Opera Reactors Brench 4. 2pp 22:32 050 24X Fiche 50-302,84/02/03,84/02/03. B402080134.

- --8402080141 "Min Water Levels in Intake Cahal," engineering analysis a Florida Power Corp 83/08/12 76pp 22132 052 24% Fiche 50-302,84/02/03,8402080134
- u402150199 Forwards application to amend License DPR-72, consisting of proposed Rev 4 to physical security plan, originally submitted 820306 MESTAFER.9 R Florida Power Corp 84/02/06 STULZ, J F Operating Reactors Branch 4 2pp 22245 250 24X Fiche 50-302, 84/02/06, 8402150199
- --8402150203 Application for amend to License DPR-72, consisting of proposed Rev 4 to security plan
 # Florida Power Corp 84/02/06 10pp 22245 252 24X
 Fithe 50-302,84/02/06,8402150199
- 21402220210 Forwards preliminary Rev 2 to Procedure SP-5061. "Spec for Electric Transmitters" & add1 info re proposed inadequate core cooling instrumentation system NURES-0737. Item II F 2 H/two oversize drawings Aperture cards in FDR HESTAFER, G R Florida Power Corp 84/02/15 STGLZ, J F Decrating Reactors Branch 4 lipp 22335 216 24% Fiche 50-302,84/02/15,8402220210
- --8402220217 Preliminary Rev 2 to Procedure SP-5061. "Spec for Electric Transmitters."

 * Stone & Webster Engineering Corp. 84/02/13 57pp. 22335 227 24% Fiche 50-302.84/02/15.8402220210
- 8402230022 Requests fee for 840116 application re proposed Tech Spec Change Request ill on silicon controlled rectifiers associated w/control rod trip breakers for facility B1005,R M License fee Management Branch B4/02/15 WILGUS,W B Florada Power Carp ip 22379 335 24X Fiche 50-302,84/02/15. B40220022
- 8402220004 Application for amend to License DPR-72 revising Tech Specs to include add) DHR requirements Amend fee encl WESTAFER Florida Power Corp 84/02/16 DENTON; HR Defice of Nuclear Regulation, Director 4pp, 22337 276 24X Fiche 50-302;84/02/16;8402220004
- --8402220005 Proposed changes to Tech Specs re limiting conditions for operation & surveillance requirements for DHR

 * Florida Power Corp 84/02/16 14pp 22337 280 24X
 Fithe 50-302,84/02/16,8402220004
- O Inspection reports. IE Bulletins & correspondence
- 8312120133 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list entl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 630103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120153
- 8402280442 Forwards IE Insp Rept 50-302/83-30 on 841130-1219 No violations or deviations identified DANCE, H C Division of Project & Resident Programs 84/01/26 HILGUS, H S Florida Power Corp 2pp 22407,179 24X Fiche 50-302,84/01/26,8402280442
- --8402280446 IE Insp Hept 50-302/83-30 on 841130-1219 No violations or deviations identified Major areas inspected plant operations, security, radiological controls, action on IE Bulletin 83-05. LERs & nanconforming operations repts STETKA: T F Repton 2, Office of Director PANCIERA, V W Division of Project & Resident Programs 84/01/25 9pp 28407 IBI. 24% Fithe 50-302,84/01/26,8402280442
- 8401190016 IE Info Notice 84-07, "Design-Dasis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01. "Cracks in SWR Mark I Containment Vent Headers " Svc list encl DEYGUNO, R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 156 24X Fichs 50-000,84/02/03,8401190017
- 840119004; IE Info Notice 84-09, "Lesnons Learned From NRC Insps of Fire Protection Safe Shutdown Bys (10CFR50, App R)" Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York Inc 124pp 22365 259 24X Fiche 80-000,84/02/13,8401190041

- B402280195 Ack receipt of 840127 ltr informing NRC of steps taken to correct violations noted in IE Imap Rept 50-302/83-29 LEMIS.R C Division of Project & Resident Programs B4/02/13 H1LGUS N S Florida Power Corp ip 22400 225 24X Fiche. 50-302, 84/02/13, 8402280195
- ~-8402280200 Responds to NRC 831228 ltr re violations noted in IE lns Rept 50-302/83-29 Corrective actions operator verified closed position of valve DJV-54 & Procedure SP-349 changed to state in body of procedure direction of reading WESTAFER.0 R Florida Power Corp 84/01/27 D'REILLY. J P Region 2. Office of Director 4pp 22400 226 24x Fichs 50-302,84/02/13,8402280195
- --8402280203 Forwards IE Insp Rept 50-302/83-29 on 831028-1129 & notice of violation
 LEWIS.R C Division of Project & Resident Programs 83/12/28
 WILGUS.W S Florida Power Corp 2pp 22400 230 24X
 Fiche 50-302,84/02/13,8402280195
- --8402280206 Notice of violation from insp on 831028-1129. * Region 2. Office of Director 83/12/28 2pp 22400:232 24k Fiche 50-302.84/02/13.840280195
- --8402280212 IE Imap Rept 50-302/83-27 on 831028-1127. Violation noted completion of valve check list not finalized prior to emergency diesel generator operation & required horizontal vibration readings not taken
 STETKA: TF Region 2, Office of Director PANCIERA, V. Division of Project & Resident Programs 63/12/22 10pp 22400-234 248 Fiche 50-302,84/02/13,8402280195
- 8401190039 IE Info Notice 84~08, "10CFR50 7, 'Employee Protection 'Syc list encl
 JORDAN,C L Division of Emergency Preparedness & Engineering
 B4/02/14 Consolidated Edison Co. of Hy
 York, Inc. 115pp 22365 141 24X Fiche 50~000,84/02/14,8401190039
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl. JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 820103) 84/02/15 Consolidated Edison Co of Mry York, Inc 118pp 22366 142 24X Fichs 50-000,84/02/15,840119005
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Bwitches Set Below Manufacturer Recommended Value " Svt list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/21 Consolidated Edison Co of Ne York, Inc 116pp 22366 024 24X Fiche 50-000:84/02/21,840119002
- 8401190066 IE Info Notice 84-11. "Training Program Deficiencies "
 Eye list enel
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24. Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,840190066
- 8401190067 IE Info Notice 84-12, "Failure of Boft Seat Valve Seals "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 880103) 84/02/27 Consolidated Edison Co. of New
 York, Inc 120pp 22431 060 24X Fiche 50-000,84/02/27,840119087
- B Reportable occurrences. LERs & related correspondence
- 8402030416 RO Special Rept 84-01 on 840114, leak found in fire suppression water systemetring systemetrials. Caused by compliance w/Tech Specialisting condition for operation. Systemetrined to operable status on 840115
 WESTAFER: 8 Florida Power Corp. 84/01/23 O'REILLY, J. P. Region 2, Office of Director. 2pp. 22068, 276. 24X Fiche. 50-302, 84/01/23, 8402030416
- B402030409 Revised LER B3-039/03X-1 on B30329, 11 process instruments found out of calibr during Mode 5 surveillance testing. Caused by procedural inodequacy Procedures revised W/B40127 ltr BUFE.J L. CULLEN, D.P., WESTAFER.9 R. Florida Power Corp. 84/01/27 O'REILLY.J P. Region 2. Office of Director 5pp 22068:315 24X Fiche 50-302.84/01/27.8402030409
- 8402220335 LER 84-001-00 on 840113 during refueling outage, and cap in reactor containment bldg incorrectly cut off Caused by gersonnel failing to follow engineering procedures Engineering evaluation to be performed W/840210 ltr THOMPBON.R.H. MEGTAFER.O.R. Florida Power Corp. 84/02/10. 6/REILLY.J.P. Region 2. Office of Director. 3pp. 22334, 209. 241 Fiche, 50-302, 84/02/10, 8402220335

-

- B408220172 LER 84-002-00 on 840201. liquid release initiated w/o continuous recording of release flow rate & radioactivity On 840202, ogerater discovered chart recorder inoperable due to pailure in paper advance mechanism W/840217 ltr BANHAUER W K, WEBTAFER, G R Florida Power Corp 84/02/17 3pp 22339 263 24% Fiche 50-302,84/02/17,8402220172
- B402240121 NPDES noncompliance notification re rise in delta T temp to 3 h limit of 21 O F EPA 840206 ltr to util questioning util actions encl WESTAFER, G.R. Florida Power Corp. 84/02/20 DENTON, H.R. Office HEBIAFER. G R Florida Power Corp 84/02/20 DENTON, H R Nuclear Reactor Regulation, Director 3pp 22373 321 2 Fiche 50-302,84/02/20,8402240121

DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2 F Becurity, medical, emergency & fire protection plans

- 8402:30191 Rev O to Emergency Plan Implementing Procedure EOF-17, "Emergency Operations Facility Activation Facility Log "BERLIN.M.D Commonwealth Edison Co 83/09/23 3pp 22199 283 24x Fiche 50-000,83/09/23,8402130191
- 8402100137 Revised emergency plan implementing procedures including Procedures EPIP EOF-17 re emergency operations facility activation log. EPIP CC-12 re sys power dispatcher & EPIP EOF-12 re access control W/840203 memo & receipt form MODRE.R D. Commonwealth Edison Co 83/11/09 DENTON, H R NRC No Detailed Affiliation Given 24pp 22181 288 24x Fiche 50-000,83/11/09,8402100137
- 6402150358 Rev 2 to Generating Station Emergency Plan Implementing Procedure EOF-12, "Access Control to Emergency Operations Facility " W/831108 ltr & receipt form MODRER D. Commonwealth Edison Co 83/11/30 5pp 22242 358 Fiche 50-000,83/11/30,8402150358 83/11/30 5pp 22242 358 24X
- 8402140134 Rev 5 to Emergency Plan Implementing Procedure EPIP 550-3, "Radiological Supplies for Medical Emergencies" W/840126 transmittel ltr & receipt form GRAESER, K L. P. LIML, 0 Commonwealth Edison Co. 84/01/25 8pp 22217-029. 24X Fiche 50-275,84/01/25,8402140134
- B402060446 Forwards Rev 9 to Emergency Plan Implementing Procedure CC-1. "Corporate Command Ctr Director " Recovery manager priority notification table encl HOORE, R D Commonwealth Edison Co 84/01/30 DENTON, H R Office Nutlear Reactor Regulation, Director Rpp 22083 127 24X Fiche: 50-000, 84/01/30, 8402060446
- --B402060464 Rev 9 to Emergency Plan Implementing Procedure CC-1.
 "Corporate Command Ctr Director," controlled copy
 MOORE.R D. Commonwealth Edison Co B3/11/30 76pp 22083 131
 24% Fiche. 50-000.84/01/30.8402060446
- 8402130467 Confirms 840215 enforcement conference at Region III ofc 402130467 Confirms 840215 enforcement conference at Reg: ta discuss recent security event at Dresden & health physics events at Zion NORELIUB,C.E Division of Project & Resident Programs REED.C Commonuesath Edison Co ip 22202:038 24X Fiche.50-000.84/02/02.8402130467 84/02/02
- 8402080151 Reinforces commitment to meet requirements of 10CFR50 48 & App R. Daily fire hazard insps proposed New combustible mat1s cantrol procedure developed & implemented as interim compensatory measure to achieving full compliance.

 iENTINE, F G Commonwealth Edison Co 84/02/03, DENTON, H R Offic of Nuclear Reactor Regulation, Director lipp 22132, 255, 24X Fichs 50-295, 84/02/03, 8402080151. Office
- 8402130361 Ack receipt of 840127 ltr forwarding scope of participation 2 objectives for emergency preparedness exercise scheduled for 840417. Supporting objectives acceptable PAPER[ELLO, C. J. Region 3, Office of Director 84/02/08 REED, C. Commonwealth Edison Co. ip 22201 144 24X Fiche 50-275,84/02/08. B402130361.
- --84021303A5 Forwards scope of participation & objectives for emergency response exercise to be conducted on 840417.in accordance w/NRC & FEMA requirements

 DWYER.R E Commonwealth Edison Co 84/01/29, HIND, J Division of Radiological & Materials Bafety Programs 4pp 22201 145 24X Fiche 50-295,84/02/08,8402130361
- B402150427 Advises that NRG will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per B10707 ltr.W/o request, entire plan will be placed in FDR.
 NORRIBOJ Operating Reactors Branch 1 84/02/08 FARRAR, D L Commonwealth Edison Co 2pp 22263 307 24X Fiche 50-275,84/02/08,8402150427.

- 8402210142 Forwards revised response re basis for delection of safety parameter display sys for facility,per Suppl 1 to NURCO-0737
 - NURCO-0737 BWARTZ.E D Commonwealth Edison Co 84/02/10 DENION.H R O of Nuclear Reactor Regulation. Director 5pp 22317 172 24X Fiche 50-245:84/02/10:8402210142
- 0402220524 Rev 4 to emergency plan implementing Procedure EPIP 180-1,
- 8402220528 Rev & to Emergency Plan Implementing Procedure EPIP 350-2, "Calculation of Post-Accident Noble Gas Release Rates Via Vent Stacks & Guick Estimate of Offsite Dose Using SPING Monitor RIA-PR49 Readings" * Commonwealth Edison Co 84/02/17 10pp 22334 153 24X Fiche 50-275,84/02/17,8402220528
- B40D220551 Rev 9 to emergency plan implementing Procedure EPIP-110-1. "Btation Director" Commonwealth Edison Co 84/02/17 9pp 22333 134 24X Fiche 50-295, 84/02/17, 8402220551
- B402280393 Revised emergency plan implementing procedure, including Rev i to BZP 600-A4, "OBEP Telephone Directory " * Commonwealth Edison Co B4/02/18 61pp 22404 158 24X Fiche 50-000 B4/02/18, B402280395

G Adjudicatory correspondence

- B402160242 Submits petition to intervene in proceeding on issuance of amends re reactor containment leakage tests GOGOLE Citizens Against Nuclear Power 84/02/13 Dacketing & Services Branch 2pp 22274 333 24X Fichs 50-295,84/02/13.
- I Financial information
- 8402280410 Annual Financial Rept 1983 W/840221 ltr O'CONNOR,J J Gommonwealth Edison Co 63/12/31 24X Fiche 50-000,83/12/31,8402280410 63/12/31 29pp 22407 101
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8402090484 Summary of ACRS Reliability & Probabilistic Assessment Subcommittee 820325-26 meetings in Washington,DC re Zion probabilistic safety study * ACRS Advisory Committee on Reactor Bafeguards 82/03/26 ACRS Advisory Committee on Reactor Safeguards 16pp 22/192 256 24X Fiche 50-295,82/03/26.8402090484
- B402270263 Responds to FOIA request for JC Mark 801204 memo to ACRS re hydrogen burn w/igniters & documents concerning generation, combustion or control of hydrogen in reactor accidents Forwards App A documents App B documents in PDR FELTON.J M Division of Rules and Records 84/01/30 HIATT. B L Chio Citizens for Responsible Energy 7pp 22412 001 24X Fiche 50-000,84/01/30,8402270263
- --8402270282 Summary of 800520 meeting w/natl labs.Westinghouse, NRC & utils in Bethesda MD re hydrogen technology Meetings scheduled for 800403 & 0617 to discuss FVSS & core retention devices & containment structural response respectively QUITTECHREIBER ACRS Advisory Committee on Reactor Safeguards 80/05/22 ACRS Advisory Committee on Reactor Safeguards, 3pp 22412 064 24X Fiche, 50-000, 84/01/30, 8402270263
- P Operating license stage documents & correspondence
- 8312120029 Generic Ltr d3-39 to representatives of utils re voluntary survey of litensed operators Svc list encl EISENHUT, D o Division of Licensing 83/12/08 Commonwealth Edison Co 12pp 22313 006 24X Fiche 50-000.83/12/08.8312120029
- B402130013 Responds to FDIA request for two categories of documents re IDCOR program Forwards App A & B documents Documents placed in PDR In PDR FELTON, J.M Division of Rules and Records 83/12/21 SHOLLY, 9 C Union of Concerned Scientists 5pp 22282 004, 24X Fiche, 50-000:83/12/21,8402130013
- --B402130054 Forwards draft feasibility study for containment performance under severe accident conditions for large dry PWR in preparation for 831202 meeting Proposed agends encl ARLOTTO, 0 A Division of Engineering Tachnology 83/11/21 BUHL, A R. Technology for Energy Corp 3pp 22282 219 24% Fiche 50-000,83/12/21,8402130013

- 8402010177 Forwards notice of consideration of issuance of amend to Licenses DPR-39 & DPR-48 & opportunity for prior hearing re 830808 request to amend Tech Specs re acceptance critoria for containment leakage tests VAR9A: 8 A Operating Reactors Branch i 83/12/23 FARRAR. D t Commonwealth Edison Co. 4pp. 22048-043 24X Fiche 50-295,83/12/23,8402010177
- --8402010181 Notice of consideration of issuance of amend to Licenses DRR-39 % DPR-48 % opportunity for prior hearing VARGA, S.A. Operating Reactors Drench 1 83/12/23 4pp 22048 047 24% Fiche 50-295,83/12/23.8402010177
- B402010192 Forwards notice of consideration of issuance of amend to Licenses DPR-39 & DPR-48 & opportunity for prior hearing re B31014 request to amend Tech Specs to allow extensive diesel generator maint VARGA.S A Operating Reactors Branch 1 B4/01/05 FARRAR.D t. Communumealth Edison Co 3pp 22048 006 24X Fichs 50-295.84/01/05.840010192
- --B402010177 Notice of consideration of issuance of amend to Licenses DPR-39 % DPR-48 & opportunity for prior hearing VARGA,8 A Operating Reactors Branch 1 84/01/05 4pp 22048 009 24% Fiche 50-295,84/01/05,8402010192
- 8402020456 Notification of rescheduled B40125 meeting w/util in Bethesda.HD to discuss status of equipment environ qualifications NDRRIS.J A Operating Reactors Branch 1 84/01/13 VARGA.5 A Operating Reactors Branch 1 1p 22062 169 24X Fiche 50-299.84/01/13.8402020456
- 8402010221 Discusses review of util 820108 submittal re NUREG-0737. Item II K 2 17, "Potential for Voiding in RCB During Transients." per Generic Ltr 81-21. "Natural Circulation Cooldown " Voids accounted for in present analysis models VARGA: B A Operating Reactors Branch | 84/01/16 FARRAR.D t. Commonwealth Edison Co 11pp 22047 330 24% Fithe 30-275. 64/01/16.8402010221
- 8402070336 Reiterates 810908 request that confirmatory order dtd 800229 be rescinéed, based on listed reasons Practice of scheduling actions based solely on perceived risk must be discontinued Refs & status rept on each order item encl REED.C. Commonwealth Edison Co. 84/01/27 DENTON, H.R. Defice of Nuclear Reactor Regulation, Director 14pp. 22096 199 24X Fiche 50-295,84/01/27.8402070336
- 8402020349 Requests med to Item D 6 of 800229 Confirmatory Order redises I generator testing & allowable outage times Bases for removal of outage time provision listing, including Item U.6 measures, detrimental to diesel generator reliability LENTINE, F 0 Commonwealth Edison Co 84/01/30 DENTON, H R Office of Nuclear Reactor Regulation, Birector Spp 22035, 052 24X Fiche: 50-275, 84/01/30, 8402020349
 - 12210021 APPLICATION OF THE SEMRP METHODOLOGY TO THE SEISMIC RISK AT ME ZION NUCLEAR POWER PLANT
 HN.M P : SHIEHLL C : WELLS. J E Lawrence Livermore Laboratory,
 4 A-0126 Methology 3488 84/01/31 Division of Engineering hnology 324pp Available at NRC + 88 00 22322 001 24X hs 50-293,84/01/31.8402210021.
 - Di04iO Generic Ltr B4-04 to all operating PHR licensees.CP holders applicants for CPs re safety evaluation of Westinghouse prical repts dealing w/wlimination of postulated pipe reaks in PHR primary main loops Svc list encl IIEENHUT.D 9 Division of Licensing 84/02/01 Consolidated Eddison Co of New York, Inc. 59pp. 22177 GB7 24X Fither 50-000.84/02/01.8402010410
- 8402100474 Summary of 840125 meeting w/util, Bechtel & Bargent & Lundy to discuss environ qualification of electrical equipment for facilities HIGGINTON.D L Operating Reactors Branch 1 84/02/03 Departing Reactors Branch 1 50pp 22211-107 24X Fiche 50-295,84/02/03,8402100474
- G Inspection reports, IE Bulletins & correspondence
- #8312120153 IE Info Notice 84~06. "Steam Binding of Auxiliary Faedwater Pumps " Svc list encl JORDAN.E L. Bivision of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000.84/01/25, 8312120153
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl.
 JORDAN E L. Division of Emergency Preparadness & Engineering Response (Post 830102). 84/02/03. Cansolidated Edison Co. of New York: Inc. 119pp 22114-179, 24X Fiche 50-000,84/02/03,8401190016

- E401190017 IE Bulletin B4-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEVBUNO.R C Director's Office, Office of Inspection and Enforcement B4/02/03 Consolidated Edison Co of New York, Inc 102pp 22177
- B401190041 IE info Notice 84-09, "Lessons Learned From NRC Inspa of Fire Protection Bafe Shutdown Bys (10CFR50, App R) " Byc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365 259 24% Fiche 50-000,84/02/13,8401190041
- B401190039 IE into Notice 84-08, "10CFR50 7, 'Employee Protection '*
 Svc list encl
 JURDANNE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York Inc | 115pp | 22365 | 141 | 24X Fiche 50-000,84/02/14,8401190039
- B401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Bvc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366 142 24X Fiche 50-000,84/02/15.8401190045
- 8402270441 Ack receipt of 840131 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-275/83-24 & 50-304/83-25
 8HAFER, W D Region 3. Office of Director 84/02/17 REED, C. Commonwealth Edison Co 1p 22389 356 24X Ficher 50-275, 84/02/17, 8402270441
- --840227044B Responds to NRC 831230 ltr re violations noted in IE Insp. Repts 50-295/83-24 & 50-304/83-25 Corrective actions training session held w/maint dept personnel stressing importance of procedures involving safety-related squipment FARRAR.D L Commonwealth Edison Co 84/01/31 KEPPLER, J 0 Region 3, Office of Director 3pp 22389 357 24X Fiche 50-295.84/02/17,8402270441
- B401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches
 Set Bolow Manufacturer Recommended Value " Byc list encl.
 JORDANIE L Division of Emergency Preparedness & Engineering
 Response (Post 630103) B4/02/21 Consolidated Edison Co of New
 York Inc 116pp 22366 024 24X Fiche 50-000.84/02/21.8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies" Svc list encl JORDAN, E. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/02/24 Consolidated Edison Co. of New York, Inc. 115pp 22430.304. 24X Fiche 50-000,84/02/24,8401190065
- B401190067 IE Info Notice 84-12, "Failure of Boft Seat Valve Beals "
 Svc list encl
 JURDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060. 24X Fiche 50-000.84/02/27.8401190067.
- R Pariadic operating reports & related correspondence
- 8402130439 Monthly operating repts for Jan 1984 W/840207 ltr AUSTIN.G , GRAESSER.K L. Commonwealth Edison Co 84/01/31 13pp. 22202:083 24X Fiche 50-295,84/01/31,8402130439
- B Reportable occurrences, LERs & related correspondence
- B402240086 Further response to FOIA request for 16 categories of documents Item 9 limited per 831005 telcon Forwards Rev 7 to NUREG-0525 & App A documents Portions of App B documents withheld (ref FOIA Exemption 4) App B documents also in PDR FELTON, J M. Division of Rules and Records 83/12/12 SHOLLY:8 C. Union of Concerned Scientists. 4pp 22394.150 24x Fiche 50-000,83/12/12,8402240086
- --8402240117 RO 83-72 on 830728, vital area alarms lost Caused by loop error PCB board replaced in mux All affected zones tested & secured info deleted YOUNG A Commonwealth Edison Co 83/07/28 Region 3, Office of Director ip 22374 145 24X Fiche 50-000, 83/12/12, 8402240086.
- ---B402240125 RO 83-67 on 830722.alarm capabilities lost in all zones due to mux overheating Caused by extreme heat inside plant Cantral processing unit replaced & Code 10 performed w/positive results Info deleted YOUNO.A Commonwealth Edison Co. 83/07/22 Region 3, Office of Director. 1p. 22394:166 24X Fiche 50-000,83/12/12,8402240086

- ---B402240127 RO B3-52 on B30617, vital area door found physically unsecured & electric strike malfunctioned Cause not stated Electric strike replaced Info deleted YOUNG. A Commonwealth Edison Co B3/06/21 Region 3, Office of Director ip 22374 167 24X Fiche 50-000,83/12/12,8402240086
- --8402240135 RO 83-40 on 830523, vital area door alarm lost Caused by misadjustment of supervisory line board Alarm repaired info deleted.
 YOUND: A Commonwealth Edison Co 83/05/24 Region 3. Office Director. 1p. 22394 168 24X Fiche 50-000.83/12/12.8402240086
- --- 9402240141 RG B3-40 on B30414, power flex to security equipment resulted in loss of alarm integrity Caused by fire Mux restored Info deleted leted Commonwealth Edison Co 83/04/18 Region 3, Office of rector. 1p. 22394 169 24X Fiche 50-000.83/12/12,840224086
- 8402070157 LER 84-002-00 on 840107, overfeed condition on steam generators arose due to sluggish controls on feedwater pump 20; leading to reactor trip Caused by loose reset pot in pump control loop. Reset pot tightened W/840202 ltr QREBSER, K. L. Commonwealth Edison Co. 84/02/02 3pp 22103 049 24X Fishe 50-304, 84/02/02, 8402070157
- B402070164 LER B4-001-00 on 840106 reactor tripped Caused by SOZOVIJAA LEE B4-003-00 on Pation reactor tripped caused by indevertent opening of reactor trip breaker train A By-pass breakers on both trains racked in & open.both trip breakers racked in & closed W/840202 ltr GRAEBSER.K L Commonwealth Edison Co 84/02/02 3pp 22103 078 24X Fiche: 50-304,84/02/02,8402070164
- B402170204 LER 84-003-00. on B40116, feedwater pump 2B emergency oil pump test circuit actuated & pump tripped. Caused by pressure switch being out of calibr Trip switch setpoint calibr M/840214 ltr.

 BEINECKE, P. J., GRAESSER, L. Commonwealth Edison Co. B4/02/14 214 15T. CME.P J., GRAEBBER,K L. Commonwealth Edison Co. 84/02/14 22299,142 24X Fiche.50~304,84/02/14,8402170204
- 8402220205 LER 84-004-00 on 840120.util informed by Westinghouse that existing auxiliary feedwater valve setting may be insufficient to insure adequate RCS following loss of feedwater flow transient W/840217 ltr 6CHLT2.C. J. CHIN.R Y. GRAEBER.K. L. Commonwealth Edison Co 84/02/17 2pp. 22338:341 24X Fiche 50-304,84/02/17.8402220205
- DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT F. Security, medical, emergency & fire protection plans
- B402130213 Rev O to Emergency Plan Implementing Procedure EOF-18, "Nuclear Station Div Non-Edison Transportation Incident Assistance Procedure." Assistance Procedure."

 - Commonwealth Edison Co 83/09/29 5pp 22204.078 24X
 Fishe 50-000,83/09/27,8402130215.
- 8402130220 Rev 8 to Emergency Plan Implementing Procedure CC-12, "Sys Power Dispatcher."
 MOORE R. D. Commonwealth Edison Co 83/11/09. 11pp. 22200 108
 24% Fiche. 50-000.83/11/09.8402130220
- 8402030485 Responds to 830901 ltr re changes to security, contingency, training & qualification plans Certain portions inconsistent w/provision of 100FR50 54(p). Util should follow previously Approved plan, an Accordance Strunch 1, 84/01/30, GIEBLER, C W Wisconsin Public Service Corp 1p. 22066 018. 24X Fiche: 30-305,84/01/30,8402030485
- 8402070376 Forwards joint exercise rept of 831101 exercise of offsite radiological emergency preparadness plans for facility State of WA & Manitowor & Kewaunee Counties participated.
 FRIMM.R.W. Federal Emergency Management Agency 84/01/30
 JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103), 2pp. 22099-326 24X Fiche.50-305.84/01/30,8402070376
- ~-B402070379 Evaluation of offsite radiological emergency preparedness plan joint exercise rept for facility.

 **Federal Emergency Management Agency. B3/12/14 45pp 22099; 328 24% Fiche: 50-303; 84/01/80; 8402070376.
- 8402070329 Forwards radiological emergency response plan implementing procedures. QIEBLER, C. W. Wisconsin Public Service Corp. 84/02/01. DENTON. Office of Nuclear Reactor Regulation. Director. 1p. 22174.118. Pichs: 50-303.84/02/01.8402070329. DENTON, H R
- --8402070335 Revised index to emergency plan implementing procedures * Wisconsin Public Service Corp. 84/01/12. 5pp. 22174:119. 24X Fiche: 50-305.84/02/01.8402070329.

- --8402070339 Rev B to Emergency Plan Implementation Procedure EP-RET-3C
 "Post-Accident Deration of High Radiation Sample Room"
 * Wisconsin Public Service Corp * 84/01/12 24pp 22174 124
 24X Fichs 50-305,84/02/01.8402070329
- -8402070346 Emergency Plan Implementing Procedure EP-TSC-7, "Reactor Vessel Head Venting Time Calculation" # Wisconsin Public Bervice Corp B4/01/12 3pp 22174 148 24X Fiche 50-305, B4/02/01.8402070329
- 8402080235 Confirms 841023 as acceptable date for conducting next small-scale emergency preparedness exercise.per 840126 request
 PAPERIELLO,C J Region 3. Office of Director 84/02/03
 OIESLER,C W Wisconsin Public Service Corp 1p 22134 229 24X
 Fiche 50-305,84/02/03,8402080233
- --8402080239 Requests concurrence w/841023 date for next small-scale NAVOUCLY Requests concurrence with 1023 date for next small smergency preparedness exercise OIEBLER,C W Wisconsin Public Service Corp 84/01/26 H Division of Radiological & Materials Safety Programs 4pp 22134 230 24X Fiche 50-305.84/02/03.8402080235 HIND. I A
- 8402140455 Forwards revised pages to industrial security manual & security force training & qualification manual Pages withheld (ref 100FR73 21) GIEBLER.C W Wisconsin Public Service Corp 84/02/07 KEPPLER.J G Region 3. Office of Director 2pp 22221 099 24X Fiche 50-305.84/02/07.8402140455
- 8402270203 Advises that NRC will not review emergency plans to delete privacy or proprietary into unless specifically requested by licensee.per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR NEIGHBURS. J D Operating Reactors Branch 1 84/02/07 OIE Misconsin Public Bervice Corp 2pp 22407 319 Fiche 50-305, 84/02/07, 8402270203 84/02/07 GIESTER, C W
- 8402170086 Forwards Amend 52 to License DPR-43 & safety evaluation Amend changes wording of Tech Specs re fire hose hydraulic test & condensate storage tank water lovel GROTENHUIS.M Operating Reactors Branch i 84/02/09 GIESLER.C w Wisconsin Public Service Corp 3pp 82318 139 24X Fiche 80-305.84/02/09.8402170086
- --8402170090 Amend 52 to License DPR-43, changing wording of Tech Specs re fire hose hydraulic test & condensate storage tank water level VAROA.8 A Operating Reactors Branch 1 84/02/09, 2ipp 22318 142 24X Fiche 80-305,84/02/09,8402170086
- P Operating license stage documents & correspondence
- 8312120027 Generic Ltr 83-37 to representatives of utils re voluntary survey of licensed operators. Svc list encl EIBENHUT. D G Division of Licensing 83/12/08 Communwealth Edison Co 12pp. 22313 006 24X Fiche, 50-000, 83/12/08, 8312120029
- 8402080228 Application to amend License DPR-43, revising Tech Specs remain steam safety valves, turbine overspeed protection & refueling containment integrity & correcting Amend 50 Tech Spec pages Instruction sheet and OLEGLER.C W Wisconsin Public Service Corp 84/01/27 NEIGHBORS, D Office of Nuclear Reactor Regulation, Director 8pp 22134 191 24X Fiche 50-305.84/01/27,8402080228
- --8402080231 Proposed Tech Spets re basis for refueling ventilation requirements, refueling containment integrity, required main steam safety valves, turbine overspead protection & safety-related hydraulic shock suppressors # Misconsin Public Service Corp 84/01/27 30pp 22134 197 24X Fiche 50-305,84/01/27,8402080228
- 8402010410 Generic Ltr 84-04 to all operating PHR licensees CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Bvc list encl EISENHUT.D 0 Division of Licensing 84/02/01. Consolidated Edison Co of New York. Inc. 59pp 22/17 087 24X Fiche 50-000.84/02/01.8402010410
- 8402060460 Responds to NRC Generic Ltr 84-01 re use of terms important to safety & safety-related Util interested in participating in discussions on subj.

 OIEBLER.C W Wisconsin Public Service Corp 84/02/01 TAYLOR, J M Director's Office. Office of Inspection and Enforcement 1p. 22083 109. 24X Fiche 50-305,84/02/01,8402040440

- B402070279 Provides rev to safety parameter display sys implementation & trained operator schedule Safety parameter display sys expected to be fully operational by end of 1985 refueling outage GIESLER.C W Histonsin Public Service Corp 84/02/03 VARQA, S A
 - outage GIESLER.C W Histonsin Public Service Corp 84/02/03 VARQA,S A Operating Reactors Branch 1 2pp 22101 315 24X Fiche 50-305,84/02/03,8402070279
- 840215023D Requests relief from ASME requirements re hydrostatic testing & eitension of relief requests already granted until completion of 1965 refueling outage Related info encl OIESLER.C W Wisconsin Public Service Corp 84/02/08 E18EMHUT. D © Division of Licensing 27pp 22243 156 24% Fiche 50-305,84/02/08.8402150230
- B402170086 Forwards Amend 52 to License DPR-43 % safety evaluation Amend changes wording of Tech Specs re fire hose hydraulic test & condensate storage tank water level GROTENHUIS.M Derrating Reactors Branch 1 84/02/09 GIESLER.C W Wisconsin Public Service Corp 3pp 22318 139 24X Fiche 50-303.84/02/09.8402170086
- --B402170090 Amond 52 to License DPR-43, changing wording of Tech Specs re fire hose hydraulic test & concensate storage tank water lovel VARGA: S A Operating Reactors Dranch L 84/02/09 21pp 22318 142 24X Fiche 50-305,84/02/09,8402170086
- --8402170072 Safety evaluation supporting Amend 92 to License DPR-43 > Office of Nuclear Reactor Regulation, Director 84/02/07 26pp 22318 163 24X Fiche 50-305.84/02/09.8402170096
- B402170460 Forwards SER on B21223 response to Generic Ltr 82-16 NUREQ-0737. Items I A 1 1 3. "Shift Tochnical Advisor Training" & II E 4 1. "Dedicated Hydrogen Penetrations." identified as open VARGA-S A Operating Reacturs Branch 1 84/02/10 GIEGLER.C W Wisconsin Public Service Corp 7pp 22305 350 24X Fiche 50-305.84/02/10.8402170460
- B402220442 Forwards revised schedule for submittal of responses to listed NRC ltrs Rev due to large number of submittals & limited personnel available to respond Changes to Tech Specs.per Generic Ltr 83-43.will be sent by 840304 OIESLER.C W Wisconsin Public Service Corp 84/02/16 VARGA, B A Operating Reactors Branch 1 6pp 22340 OOI 24X Fiche 50-305.84/02/16.8402220442
- 8402270194 Application for Amend 56 to License DPR-43, revising Toch Spec undervoltage trip setpoints of primary 2 secondary level undervoltage relays for ESF electrical buses, 01EBLER, C W Histonsin Public Service Corp 84/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 22387 234 24X Fiche 50-305,84/02/22,8402270194
- --8402270202 Proposed Tech Specs 3 5-1 & 3 5-5, revising undervoltage trip subjoints of primary & second level undervoltage relays for ESF electrical buses * Wisconsin Public Service Corp 84/02/22 2pp 22387 238 24X Fiche 50-305,84/02/22,8402270194
- IOD280210 Clarifies commitment to performing NDE of all critical members & welds on reactor vessel head lifting rig in response to NUMEO-OGIE Exam will be performed prior to lifting reactor vessel head olester. C W Hisconsin Public Service Corp 84/02/24, VAROA, H A Operating Reactors Branch 1 ip 22377 278 24X Fiche 50-303,84/02/24,8402280210
- G Inspection reports, IE Bulletins & correspondence
- 8312120153 IE Info Notice B4-06, "Steam Binding of Auxiliary Feedwater Pumps" Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 30-000.84/01/25,8312120153
 - 02070341 Forwards final response to IE Bullstin 80-11, "Beismic Bullification of Masonry Walls " Response addresses NRC concerns & util resolutions GIESLER.C W Wisconsin Public Service Corp 84/01/31 VARGA.8 A Operating Reactors Branch 1 11pp 22096 170 24% Fiche 50-305,84/01/31,8402070341
- 101190016 IE Info Notice 84-07. "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York. Inc. 11999 22114 179 24X Fiche 50-000.84/02/03.8401190016

- 840:190017 IE Bulletin 84-01. "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177
- 8401190041 IE Info Nutice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Bys (10CFR50, App R) " Syc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22165 259 24X Fiche 50-000, 84/02/13,8401140041
- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '" Svc list encl JURDANAE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/14 Consolidated Edison Co of New York Inc 115pp 22365 141 24X Fiche 50-000, 84/02/14, 8401190039
- 8401190049 IE Info Notice 83-63. Suppl i. "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svt list encl JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366 142 24X Fiche 50-000,84/02/15,8401190045
- 8402270245 Ack receipt of 840203 ltr informing NRC of steps taken to correct yiolations noted in 1E Insp Rept 50-305/83-15 SHAFER.W D Region 3, Office of Director 84/02/17 OIESLER.C W Hisconsin Public Service Corp ip 22386 338 24x Fiche 50-305.84/02/17.8402270245
- ---8402270237 Responds to NRC 831228 ltr re violations noted in 1E Insp. Rept 50-305/83-15 Corrective actions administrative control directive changes initiated clarifying & defining tagging of equipment in controlled status GIEGLER.C W Wisconsin Public Service Corp 84/02/03 8HAFER.W D Region 3, Office of Director 4pp 22386 337 24% Fiche 50-305,84/02/17.8402270245
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value "Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000,84/02/21,8401190082
- B401190066 IE Info Notice 84-11, "Training Program Deficiencies "
 Svc list encl
 JDRDANAE L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B4/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000, B4/02/24, B401190066
- 8401190067 IE Info Notice 84-12, "Failure of Boft Seat Valve Beals "
 Svc list encl
 JORDANN E L Division of Emergency Prepareoness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co. of New
 York, Inc 120pp 22431 060. 24% Fiche: 50-000, 84/02/27, 8401190067
- R Periodic operating reports & related correspondence
- 8402140098 Monthly operating rept for Jan 1984 W/840210 ltr RVITCR, G H . GIESLER, C W Washington Public Pawer Supply System 84/01/31 5pp 22217 R38 24X Fiche 50-305, 84/01/31, 840R140098
- 8 Reportable occurrences, LERs & related correspondence
- 8402030374 LER B3-038/03L-0 on B31227 maint procedure to replace relay in reactor protective sys rack 133 caused inadvertent start of suviliary feedwater pump Procedure generated as result of work request W/640127 itr
 BERNHOFT, B L , OIEBLER, C W Wisconsin Public Service Corp.
 84/01/27 KEPPLER, J G Region 3, Office of Director. Rpp.
 22066 064. 24X Fiche 50-305,84/01/27,8402030374
- V Operator Examinations
- 8402070223 Confirms commitments made in 840105 meeting w/NRC re 830930 request for extension until 840401 for implementation of licensed operator staffing requirements GIEBLER, C W Wisconsin Public Service Corp. 84/02/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22101, 164 24X Fiche. 50-305, 84/02/03, 8402070223

- DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

 F Sectritu, medical, emergency & fire protection plans
- 8402070037 Final response to FDIA request for documents re emergency operation facilities located 10-20 miles from nuclear plants & info approving/denying location over 20 miles away Forwards listed documents Info also in PDR FELTON. J M Division of Rules and Records 83/11/04 0'NEILL, J H Bhaw. Pittman, Potts & Troubridge 1p 22142 148 24X Fiche 50-000.83/11/04.8402070039
- --8309120090 Recommends Commission agree w/approval of util position to establish common backup emergency operations facility for Prairie Island & Monticello nuclear generating plants DIRCKS.W J. Office of the Executive Director for Operations SECY-B3-363. 83/08/30 86pp 22142 151 24X Fiche. 50-000,83/11/04.8402070039
- --8402070045 Advises of Commission approval of util decision to establish emergency operations facilities 45 & 55 miles from respective sites
 CHILK.8 J Office of the Secretary of the Commission 83/09/26
 DIRCKG.W J Office of the Executive Director for Operations 1p 22142 149 24X Fiche 50-000,83/11/04,8402070039
- 8402160390 Rev 3 to emergency implementing procedures, including Temperary Memo 84-05 re offsite dose calculation W/840206 itr.

 BTEMOOS, A A., FEY, F L Northern States Power Co 84/02/01 5pp 28288 3R3 24X Fichs 50-282,84/02/01,8402160390
- B402080311 Ack receipt of B31221 ltr forwarding objectives for B40313 swergency preparedness exercise Objectives include in-plant & oneite radiological monitoring post-accident sample analysis & environ sample routing PAPERIELLO,C J. Region 3. Office of Director B4/02/03 LARSON,C.E. Northern States Power Go ip 22131 285 24X Fichs. 50-282.84/02/03.8402080311
- --8402080317 Forwards 840313 emergency plan exercise objectives & guidelines. Document developed in coordination w/States of MN t WI & wax reviewed jointly by NRC & FEMA at 831212 meeting FEY.F.L. Northern States Power Co 83/12/21 PATTERSON, J. P Region 3, Office of Director 1p. 22131, 286 24X Fiche: 50-282, 84/02/03, 8402080311
- --8402080319 Ray 0 to "Emergency Plan Evaluation Exercise 840313, Section II Exercise Objectives & Guidelines."

 * Northern States Power Co 84/02/03 7pp 22131 287, 24X Fiche: 50-282, 84/02/03, 8402080311
- B402210492 Requests remittance of Class I & III fees for 820630 request for exemptions from certain requirements of App R of IOCFR50 W/o enci.
 MILLER.W O. License Fee Management Branch 84/02/13 MUSOLF,D M Northern States Power Co ip 22343 341. 24X Fiche 50-282, 84/02/13,8402210492.
- P Operating license stage documents & correspondence
- B402140486 Responds to FOIA request for 16 categories of documents re degradation of bolts, nots & studs at PWRs & BWRs, Forwards App A documents, App A & B documents available in PDR FELTON, J. M. Division of Rules and Records. B3/12/02, BELL, N. Nuclear Information & Resource Service 4pp 22257.003 24X Fiche, 50-000, B3/12/02, B402140486
- --8402140489 Submits daily highlights re 830408 plant shutdown due to excessive primary coolant leak rate of 0.07 gpm.Cause of leakage at manuay covers undstermined Repairs in progress DIIANNI.D C Operating Reactors Branch 3. 83/06/10 DENTON,H CANTER.J., EISENHUT.D. NRC No Detailed Affiliation Given ip 22257:007. 24X Fiche: 50-000,83/12/02,8402140486
- --H402140492 Bubmits daily highlights re plant shutdown because of excessive primary coolant leak Cause of leaky manuay covers due to insufficient torquing of head bolts that prevented proper bottoming of bolts
 DIIANNI, D. C. Operating Reactors Brench 3 B3/06/17 DENTON, H. CARTER, J. EIBENHUT, D. NRC No Detailed Affiliation Given, ip 22257 009 24X Fiche: 50-000, 83/12/02, 8402140486
- B312120027 Generic Ltr 83-37 to representatives of utils re voluntary survey of licensed operators Svc list encl.
 EIBENAUT. D. O Division of Licensing 83/12/08 Commonwealth Edison Co. 12pp 22313 006 24% Fiche 50-000.83/12/08,8312120027

- 8402070011 Responds to Generic Ltr 83-28, "Generic Implications of Salem ATMS Events "Improper undervoltage trip attachment replaced Modified procedures developed & issued for testing reactor trip switchgear MUSGLF.D Northern States Power Co 84/01/31 Office of Nuclear Reactor Regulation, Director ip 22102 319 24X Fiche 50-282.84701/31,8402070011
- B402070529 Advises util of NRC actions re addl fee required for 830202 amend application re steam generator surveillance & auxiliary feedwaters sys & refund for 800506 & 16 applications
 DI905.R M License Fee Management Branch 84/01/31 MUBDLF.D M Northern States Power Co 2pp 22141 324 24X
 Fiche 50-282.84/01/31.8402070529
- 840210034B Forwards supplemental safety evaluation re relief requests for inservice testing program for pumps & valves Five requests granted & two requests denied MILLER.J B Operating Reactors Branch 3 84/01/31 MUSULF.D M Northern States Power Ca 4pp 22207 335 24X Fiche 50-282.84/01/31,840210034B
- --B402100358 Supplemental safety evaluation re relief requests for inservice testing program for pumps & valves Five requests granted & two requests denied # Office of Nuclear Reactor Regulation, Director B4/01/31 17pp 22207 339 24x Fiche 50-282,84/01/31.8402100348
- 8402010410 Generic Ltr 84-04 to all operating PWR licensees, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Svc list encl EISENHUT, D 0 Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc 59pp 22177 087 24X Fiche 50-000,84/02/01.8402010410
- 8402160473 Responds to Generic Ltr 84-01 re NRC use of terms important to safety & safety-related Meeting between NRC & Steering Committee of Util Bafety Classification Group should be arranged to provide clarification of Issue MUBOLF, D. Northern States Power Co. 84/02/07 Office of Nuclear Reactor Regulation, Director 19 22269 001 24X Fiche, 50-000, 84/02/09, 8402160473
- Q Inspection reports, IE Bulletins & correspondence
- B312120153 IE Info Notice 84-04, "Bteam Binding of Auxiliary Feedwater Pumps" Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/25 Consultdated Edison Co of New York, Inc 120pp. 22058 001 24X Fiche 50-000,84/01/25,8312120153
- 8401170016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls" Syc list encl JORDAN E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York Inc 119pp 22114 179 24X Fiche 50-000 84/02/03 8401170016
- B401190017 IE Bulletin B4-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list enc! DEYOUNO, R C Director's Office, Office of Inspection and Enforcement B4/02/03 Consolidated Edison Co of New York, Inc 102pp 22177:154, 24X Fiche: 50-000;84/02/03;8401190017
- 8402270387 Forwards IE Insp Repts 50-282/84-01 & 50-306/84-01 on 840117-20 No noncompliance identified PAPERIELLO.C J. Region 3, Office of Director 84/02/08 LARBON.C E. Northern States Power Co. 2pp 22370 258 24X Fiche 50-282,840/20/68,8402270387
- ---B402270392 IE Insp Repts 50-282/B4-01 & 50-306/84-01 on B40117-20 No noncompliance or deviations identified Major areas inspected radwaste sys, air cleaning sys, audits & appraisals & reactor coolant water quality GRANT. W B., NICHOLSON. N A , GREGER. L R Region 3, Office of Director B4/02/07 5pp 22390 260 24X Fiche 50-282,84/02/08,8402270387
- B402150319 Ack receipt of B40203 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/83-19 & 50-306/80-20 BHAFER, W D Region 3, Office of Director 84/02/10 LARBON, C E Northern States Power Co Ip 22250 090 24X Fiche 50-282, 84/02/10,8402150319
- --8402150320 Responds to NRC 840104 ltr re violations noted in IC Insp Repts 50-282/83-19 & 50-306/83-20 Corrective actions fill & yent procedure revised to provide multi-disciplinary review of plant mods LARSON: C E Northern States Power Co 84/02/03 KEPPLER, J O Region 3. Office of Director 2pp R2230 091 24X Fiche 50-282,84/02/10,8402150319.

- B402170101 Responds to IE Bulletin 83-08 No breakers of type described in use or planned for use in sefety-related application other than reactor trip breakers at facility LARSON.C E Northern States Power Co 84/02/10 KEPPLER.J G Region 3. Office of Director 2pp 22301 086 24X Fiche 50-282.84/02/10.8402170101
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown 84s (100FR50. App R)" Syc list ent!

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 64/02/13 Consolidated Edison Co. of Naw York, Inc. 124pp 22365 259 24X Fiche 50-000.84/02/13.8401190041
- B401190039 IE Info Notice B4~0B, "IOCFR\$0 7, 'Employee Protection '" Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/14 Consolidated Edison Co of New York, Inc 115pp 22363 141 24X Fiche 50-000,84/02/14,8401190039
- 8401190045 IE Info Notice 83~63. Suppl 1. "Potential Failures of Westinghouse Type BA-1 Differential Relays " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York. Inc. 118pp 22366.142 24X Fichs 50-000.84/02/15.8401190045
- 840222Q017 Advises that cooling water header turbine bldg check valve 2CL-42-1 will not be tested per previous responses to IE Builetin 83-03 Request for relief from testing under Section XI will be submitted LARSON, C E Northern States Power Co 84/02/15 KEPPLER, J O Region 3, Office of Director 1p 22326-018 24X Fiche 50-282,84/02/15.8402220017
- B401190062 IE Info Notice 84~10. "Motor-Operated Valve Torque Switches Bet Delow Manufacturer Recommended Value " Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co. of New York, Inc. 116pp 22366-024 24% Fiche 50-000.84/02/21.8401190062
- 8401190066 JE Info Notice 84~11, "Training Program Deficiencies." 8vc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/24. Consolidated Edison Co of New York, Inc 113pp 22430 304 24x Fiche.50-000.84/02/24.8401190066
- 840119067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals " Svc list enci JURRANNEL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/27 Consolidated Edison Co of New York, Inc 120pg 22431 060 24X Fiche 50-000.84/02/27.8401190067

R Periodic operating reports & related correspondence

- 8402270234 "Annual Operating Rept.1983" W/840220 ltr LARSUN.C E Northern States Power Co. 83/12/31 XEPPLER.J.O. Region 3. Office of Director. Opp 22386:325 24X Fiche 50-282.83/12/31.8402270234
- 8402190183 Monthly operating repts for Jan 1984 W/840206 ltr DUGSTAD.D. MUSQLF.D. Northern States Power Co. 84/01/31. 1p 22245 230 24% Fiche. 50-282, 84/01/31. 8402150183

5 Reportable occurrences: LERs & related correspondence

8402080209 Discusses Hills-McCanna REMCCM actuators per NRC 840126 notice of potential lapse of GC Preventive maint, surveillance.inap programs & corrective action, when problem identified, serves well as continuing qualification program HATZL,E L. Northern States Power Co. 84/01/30 KCPPLER, J G Region 3. Office of Director 13pp 22130.089 24X Fiche 50-282,84/01/30,8402080209

DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT

- F Security, medical, emergency & fire protection plans
- 8402070021 Requests exemption from 10CFR50, App E requiring annual fullscale emergency preparedness exercise to be conducted in conjunction by State & local govts. Consistency w/FEMA regulation on exercise frequencies recommended WHITTIER. 0 D Maine Yankee Atomic Power Co. 84/02/01 MILLER, J R Operating Reactors Branch 3, App 22102, 337, 24X iche 50-309, 84/02/01, 8402070021.

- 8402220604 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR HILLER.JR Operating Reactors Branch 3 84/02/06 GARRITY, J H Maine Yankee Atomic Power to 2pp 22363 090 24X Fiche 50-309, 84/02/06, 8402220604
- 8402280478 Revised emergency plan implementing Procedures 2 30 saries, including Rev 1 to Procedure 2 50 21, "Offsite Dosimetry Assistance" * Maine Yankes Atomic Power Co 84/02/17 6pp 22405 012 24X Fiche 30-309:84/02/17,8402280478
- 8409280030 Notifies that schedule for remaining info requested in Buppl i & to NUREG-0737 deferred to 850301 Revised schedule permits completion of plan to integrate five emergency response capability programs HITTIER.6 D Maine Yankee Atomic Power Co 84/02/23 HILLER.J R Operating Reactors Branch 3 ip 28400 279 28X Fiche 50-309,84/02/28.8402280090

G Adjusticatory correspondence

- 8408230427 Responds to FQIA request for SECYs 83-32,988,228,240,246 & 261 to be placed in PDR Forwards SECYs 83-228A,261 & 240 SECYs 83-228.240,266 & 261 partially withheld (ref FQIA Exemption 5) SECYs 83-32,988 & 228A available in PDR FELTON,J H Division of Rules and Records 83/12/07 QRABER,L D NUS Corp 4pp 22371 269 24X Fiche 50-000,83/12/07,8402230429
- --8402230424 Discusses Safe Power for Maine 821020 request for show cavis order re licensee alleged lack of financial qualifications MALBCH.M 0 Office of the General Counsel SECY-83-261 83/06/29 Spp 22371 286 24% Fiche 50-000.83/12/07.8402230429
- 8402220194 Advises of complete settlement between parties on spent full issue
 LESBY.R.P. Hearing Branch 3 84/02/16 LAZO,R M , MORRIS,P. A ,
 HAND.C H Atomic Safety and Licensing Board Panel 2pp 22341.170
 24X Fiche 50-309
- --B402220200 Joint motion of all parties for entry of order to consummate settlement agreement ploNAN.T G. GAD.R K. Maine Yankee Atomic Power Co. DIGNAN.T O. Ropes & Gray. B4/02/13 Atomic Bafety and Licensing Board Panel 7pp 22341 172 24X Fichs 50-309.84/02/16.8402220194
- --B402220214 Conditional motion for leave to withdraw contentions respent fuel pool. Proposed order encl
 AHRENSP / BTERN: Maine, State of 84/02/13 Atomic Bafett
 and Licensing Board Panel 6pp. 22341:179 24X
 Fithe 50-309,84/02/16,8402220194
- --8402220218 Confitional motion for leave to withdraw contentions on spent fuel pool Proposed order encl.

 MILLER: D 8 Sensible Maine Power MILLER: D 8. Miller: D.8

 84/02/16 Atomic Safety and Licensing Board Panel App

 22341: 185 24X Fichs 50-309,84/02/16,8402220194
- --8402220224 Conditional motion for leave to withdraw portion of application re spent fuel pool Proposed order encl.
 DIGNAN.T G., CAD.R.K. Maine Yankee Atomic Power Co. DIGNAN.T GRopes & Gray. 84/02/16. Atomic Safety and Licensing Board Panel Bpp. 22341*191 24X Ficher 50-309.84/02/16.8402220194.
- --8402220230 Agreement of all parties on spent fuel pool issue. Related info encl.
 TIERNEY, J E , AHRENS, P., BTERN, P. Maine, State of 84/02/13.
 25pp 22341 199 24% Fiche. 50-309, 84/02/14, 8402220194

H General correspondence

- 8402150503 Responds to 831209 itr re oversight of licensed activities Anomolous indications of unplanned radioactive releases & lack of NRC onsite presence during critical evolutions addressed MURLEY.T E Region 1. Office of Director 84/02/06 KING.E 8efe Power for Maine 2pp 22263:003. 24X Fiche: 50-309, 84/02/06. 8402150503
- --B402150506 Notifies that Commissioner Gilinsky requests response to E King 831209 1tr
 GOLDSMITH: R Commissioners, 84/01/04 REHM,T NRC No Detailed Affiliation Given. ip 22263.006 24X Fiche 50-309,84/02/06.8402150503
- --84021505i0 Notifies that Commissioner Gilinsky requested B31207 it if forwarded to NRC staff for review of info & response GOLDBHITH.R Commissioners 84/01/03 KING.E. Affiliation Not Assigned. ip. 22263.007. 24X Fiche 50-309, 84/02/06, 8402150503

- --8402150514 Expresses concern re indications of unplanned radioactive releases & lack of NRC onsite presence during critical evalutions "* Bafe Power for Maine 83/12/09 GILINSKY, V oners 1p 22263 008 24X Fiche 30-309,84/02/06, KING, E Safe F Commissioners 8402150503
- --B402150518 Requests concurrence or comments by phone re draft response to E King 831207 ltr re unplanned radioactive releases at facility REMM.T.A Office of the Executive Director for Operations Office of the Executive Director for Operations
 COLDEMITH, R NRC - No Detailed Affiliation Given ip
 24X Fiche 50-309,84/02/06,8402190503 64/01/25
- B402140285 Forwards AQ Cosser 840202 ltr protesting use of nonunion unstilled labor for huclear repairs during upcoming shutdown in Apr 1984 Onsition of 1984
 BRADFORD, P. A Maine, State of 84/02/10 DEYOUNG, R C Direct Office, Office of Inspection and Enforcement 2pp 22228 290 Fithe 50-309, 84/02/10,8402140285
- 8402220141 Forwards new address for NRC correspondence Related correspondence
 RANDAZZA.J B Maine Yankee Atomic Power Co B4/02/15 MILLER,J R
 Operating Reactors Branch 3 MURLEY.T.E Region 1, Office of
 Director. 2pp 22338 277 24X Fiche 50-307,84/02/15,8402220141
- 8402280447 Requests NRC provide response to encl list of individuals questioning experience & expertise of commissioned plumbing contractor scheduled to do repair at plant next month CONLEY. Q. P. Maine, State of 84/02/23 DEYOUNG, R C Director's Office. Office of Inspection and Enforcement 3pp 22407 206, 24% Fichs: 50-309, 84/02/23, 8402280447

P Operating license stage documents & correspondence

- 8402010444 Responds to FOIA request for SECY-83-288 & SECY-83-443 to be placed in PDR SECY-83-288 available in PDR SECY-83-443 being placed in PDR Forwards SECY-83-643
 FELTON.J M Division of Rules and Records 94/01/17 YENDUSKAS.J Newsan & Holtringer ip 22061 272 24% Fiche 50-000,84/01/17,8402010444.
- ---8402010453 Informs Commission of info obtained re flux reduction programs for pressurized thermal shock at lead plants, since 830225 interim rept (BECY 83-079)
 DIRCKS, H J Diffice of the Executive Director for Operations SECY-83-443 83/10/28 11pp. 22061,273 24X
 Fiche 50-000,84/01/17,8402010444
- 8402130442 Responds to util 830916 request for reconsideration of NRC position on placing limits for overtime in plant Tech Specs NRC position justified based on review of Commission action on matter.

 HILLER, J. R. Operating Reactors Sprench 3. 8401/26 QARRITY, J. H. Marchander Commission action of the commission of

Maine Yankee Atomic Power Co 2pp 22216; 135 Fiche, 50-309, 84/01/26, 8402130442

- 8402060235 Application to amend License DPR-36, revising Cycle 8 refueling outage Tech Spacs.
 RANDAZZALJ 8, Maine Yankee Atomic Power Co 84/01/27 MILLER, J R Desreting Reactors Branch 3 7pp 22087-263, 24X Fiche: 50-309,84/01/27,8402060235.
- --8402060241 Proposed Tech Specs re Cycle 8 refueling outage * Haine Yankee Atomic Power Co. 84/01/27. 30pp 2208 Fithe 50-309,84/01/27,8402060235. 22087, 270 24X
- --8402060245 "Gycle 8 Core Performance Analysis " BOLAN.9 M . CHEEN.C T., GORBKI, J P. Maine Yankee Atomic Power Co YAEC-1396, 84/01/23 175pp 22087, 301 24X Fiche 50-309,84/01/27,8402060235
- 8402060318 Forwards Amend 72 to License DPR-36 & safety evaluation.
 Amend changes Tech Specs to satisfy generic concerns on containment, purging & venting M/o encl
 HEITNER, K. L. Operating Reactors Branch 3, 84/01/31, GARRITY, J H
 Maine Yankee Atomic Power Co. 2pp 22111.066 24X
 Fiche: 30-307,84/01/31,8402060318
- E402010410 Generic Ltr B4-04 to all operating PWR licensess, CP holders & applicants for CPs re safety evaluation of Mestinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops. Svc list ancl EIBENHUT: D G Division of Licensing 84/02/01 Consolidated Edison Co. of New York, Inc. 59pp 22177:087 24X Fiche. 50-000, 84/02/01, 8402010410

- 8402220371 Notifies that add1 time required to develop proposed resolutions to open items of Criteria 5 & 10 of post-actident sampling sys (TMI Item II B 3) Description of postition will be submitted by 840501 WHITTIER:0 D Maine Yankee Atomic Power Co 84/02/01 MILLER.J R Operating Reactors Branch 3 1p 22334 297 24X Fiche 50-307.84/02/01.8402220391
- 840214032B Submits Phase II implementation schedule for control of heavy load review.per 831230 request Review essentially complete Rept will be submitted by 840307 WHITTIER, O D Maine Yankee Atomic Power Co 84/02/08 MILLER, J R Operating Reactors Branch 3 1p 22230 320 24X Fiche 50-309,84/02/08,8402140328
- 8402170431 Forwards tentative audit agenda to ald in preparing for audit of detailed control room design on 840213-17 MILLER, J R Operating Reactors Branch 3 84/02/08 GARRITY, J H Maine Yankee Atomic Power Co 5pp 22313 165 24X Fiche 50-307,84/02/08.8402170431
- 8402140078 Requests that encl "Seismological & Geological Studies, Miramichi Area,New Drunswick & Central New Hampshiro" be placed in PDR MAILLER, JR Operating Reactors Branch 3 84/02/10 BAILEY, I Record Services Branch (Document Control Desk) ip 22252 001 24X Fiche 50-309.84/02/10.8402140078
- --8309010095 "Seismological & Geological Studies, Miramichi Area, New Brunswick & Central New Hampshire," Vols 1 & 2 w Waston Geophysical Corp 83/08/31 533pp 22252 002 24X Fiche 50-309, 84/02/10, 8402140078
- 840222017B Notifies that vendor interface program for reactor trip sys components per Generic Ltr 83-28 will be submitted by 840701 B40701 WHITTIER, G D Maine Yankes Atomic Power Co 84/02/16 MILLER, J R Operating Reactors Branch 3 lp 22340 344 24X Fiche 50-309,84/02/16.8402220178
- 840R290304 Forwards proprietary "Evaluation of Maine Yankea Reactor Trip Breaker Configuration Re Reliability & Risk Significance " Rept withheld (ref 10CFR2 790) GARRITY, J H Maine Yankee Atomic Power Co 84/02/17 MILLER, J R, Operating Reactors Branch 3 MURLEY, T E Region 1, Office of Director, 2pp 22426 188 24X Fiche 50-309,84/02/17,8402290304
- --8402290308 Forwards proprietary "Evaluation of Maine Yankee Reactor Trip Breaker Configuration Re Reliability & Risk Significance " Rept withheld (ref 10CFR2 790) Affidavit GARRITY, J H Maine Yankee Atomic Power Co. 84/02/17 STELLO, V Regional Operations & Generic Requirements 3pp 22426 190 2 Fiche 50-309, 84/02/17, 8402290304
- B402270174 Forwards response to B40103 request for hours of operation for each cycle in hot shutdown & standby (Conditions 5 & 6) RCS temp, reactor power level & control room log book time entries used to generate operating conditions WHITTIER:0 D Maine Yankee Atomic Power Co B4/02/22 MILLER, J R Operating Reactors Brench 3 Ope 22384 046 24% Fiche 50-309,84/02/22,8408270174

G Inspection reports, IE Bulletins & correspondence

- B402140486 Responds to FDIA request for 16 categories of documents re degradation of bolts, nots & studs at PWRs & DWRs. Forwards App A documents App A & B documents available in PDR FELTON. J M Division of Rules and Records 83/12/02 BELL.N Nuclear Information & Resource Bervice 4pp 22257 003 24X Fiche 50-000.83/12/02,8402140486
- --8211060310 Advises that NRR portion of TIA-NRR-82-5, "Failed Steam Generator Manuay Studs at ME Yankes & Possibly Other PMR Reactors;" has been completed M/o encl EIBENHUT, D. Q. Division of Licensing 82/10/04 STAROSTECKI, R Division of Project & Resident Programs ip 22257 029 24X Fiche 50-000, 83/12/02, 8402140486
- -B402140499 Discusses task interface agreement re potential generic problem of failed steam generator manuay stude at facility & possibly at other FMRs Confirmation of action itr should be issued before restart.

 IPPOLITO, T, VOLLHER, R, NOVAK, T NRC No Detailed Affiliation Given 82/03/19. NRC No Detailed Affiliation Given. Rpp 222257.027 24X Fiche, 50-000, 83/12/02, 8402140486
- 9312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater 912120153 IE Anto Notice Group, Class State State State State Of Pumps." Syc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120153

- 8402140452 Forwards IF Insp Rept 50-309/83-19 on 831101-04 No violations observed MARTIN.T T Division of Engineering & Technical Programs 84/02/01 RANDAZZALJ B Maine Yanke Atomic Power Co 2pp 22268 307 24X Fiche 50-309.84/02/01.8402140452
- --8402160454 IE Insp Rept 50-309/B3-19 on 831101-04 No violation noted Major areas inspected licensee actions in response to IE Bulletins 79-02 & 79-14 & versfication of actions undertaken & work performed on mode affected by bulletins VARELA,A A. DVRR.J P Region 1. Office of Director 84/01/26 4pp 22268 309 24% Fiche 50-309,84/02/01.8402160452
- 8402230013 Forwards Structural & Geotechnical Engineering Branch request for add1 info re IC Bulletin 80-11 "Masonry Wall Design." per 930930 itr Response required within 60 days of ltr receipt MILLER. J. R. Operating Reactors Branch 3 84/02/01 GARRITY. J. H. Naine Vankee Atomic Power Co. 4pp. 22379 347 24X Fiche 50-309.84/02/01.8402230013
- B402070001 Ack receipt of 931223 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-309/83-15
 MARTIN. I T Division of Engineering & Technical Programs B4/02/02
 RANDAZAA, J B Maine Yankee Atomic Power Co 1p 22102 331 24X
 Fiche 50-309.04/02/02.8402070001
- --8402070002 Responds to NRC 831125 ltr re violations noted in IE Insp Rept 50-309/83-15 Corrective actions general employee training program revised to require written exam for employees w/access to controlled areas WHIITIER. 0 D Maine Yankee Atomic Power Co 83/12/23 MURLEY.T E Region 1. Office of Director 2pp 22102 332 24X Fiche 50-309.84/02/02.8402070001
- B401190016 IC info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Bvc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/02/03 Consolidated Edison Co of Naw York, Inc. 119pp 22114 1/9 24X Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletin 64-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEYCUNG.R C Director's Office Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 [56 24X Fiche 50-000,84/02/03,8401190017
- 8401190041 IE info Notice 84-09, "Lessons Learned From NRC Insps of Firs Protection Safe Shutdown Sys (1005R50.App R) " Swc list onel JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc. 124pp 22365 239 24% Fiche 50-000,84/02/13,8401190041
- 8402220316 Forwards IE Enforcement Conference Rept 50-309/83-18 on 831403 STAROSTECKI,R Division of Project & Resident Programs 84/02/13 RANDAZZA,J B Maine Yankee Atomic Power Co 2pp 22336 263 243 Fiche 50-307-84/02/13.8402220316
- --8402320318 IE Enforcement Conference Rept 30-309/83-18 on 831103 Major areas discussed violation of containment integrity HOLDEN, C. Region 1. Office of Director GREEMMAN.E @ Division of Project & Resident Programs 84/02/10 2pp 22336 265 24X Fiche 30-309,84/02/13,8402220316
- 840149039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection,'"
 Svc list encl
 JORDANNE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24X Fiche 50~000,84/02/14,8401190039
- B402270275 Forwards IE Insp Rept 50-309/83-21 on B31228-30 & notice of violation
 MARTINAT T Division of Engineering & Technical Programs B4/02/14
 RANDAZZA.J Haine Yankee Atomic Power Co 2pp 22427-143 24X
 Fithe 50-309.04/02/14.8402290295
- --8402290278 Notice of violation from insp on 831228-30 * Region 1, Office of Director 84/02/14 ip 22427 145 24X Fiche 50-309,84/02/14,8402270275
- -8402290302 IE Insp Rept 50-309/83-21 on 831228-30 Violation identified lack of verification that Model CNS 8-120 drain lines & access plugs plugged & sealed prior to transport CLEMONS.P. PASCIAK.W. Region 1. Office of Director 84/02/09 6pp 22427 146 24X Fiche 50-309.84/02/14.8402290275

- 8401190045 IE Info Notice 83-63. Suppl i, "Potential Failures of Westinghouse Type 8A-1 Differential Relays" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366 142 24X Fichs 50-000,84/02/15,8401190045
- 840119082 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Dolew Manufacturer Recommended Value " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 114pp 22366 024 24X Fiche 50-000.84/02/21,8401190062
- 8401190066 IE Info Notice 84-11. "Training Program Deficiencies "
 Evc list encl
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Rusponse (Post 830103) 84/02/24 Consolidated Edison Co. of New
 York, Inc. 115pp. 22430 304 24X Fiche 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals *
 Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc. 120pp. 22431 060 24X Fiche 50-000,84/02/27,8401190067
- S Reportable occurrences, LERs & related correspondence
- B402140486 Responds to FOIA request for 16 categories of documents redegradation of bolts, nuts & stude at PWRs & BWRs Forwards App A documents. App A & B documents available in PDR FELTON, V M Division of Rules and Records 83/12/02 BELL, N Nuclear Information & Resource Service 4pp 22257 003 24X Fiths 50-000.83/12/02, 8402140486
- --B211060310 Advises that NRR portion of TIA-NRR-B2-5, "Failed Bteam Generator Manway Studs at ME Yankee & Possibly Other FWR Reactors," has been completed W/o encl. EIBENHUT.D G Division of Licensing 82/10/04 BTAROSTECKI.R Division of Project & Resident Programs ip 22257 029 24X Fiche 30-000,83/12/02,8402140486
- --B402140497 Discusses task interface agreement re potential generic problem of failed steam generator manway stude at facility & possibly at other PWRs Confirmation of action ltr should be issued before restart IPPOLITO, T, VOLLMER, R, NOVAK, T NRC No Detailed Affiliation Given B2/03/19 NRC No Detailed Affiliation Given B2/03/19 NRC No Detailed Affiliation Qiven. 2pp 22257 027 24X Fiche 50~000,83/12/02,8402140486
- ---B402140504 Experience info, consisting of chronological list of activities at facility & diagrams of primary manuay cover stude for steam generator

 * NRC No Detailed Affiliation Given, 83/12/02 14pp, 22257.031 24X Fiche 50-000,83/12/02,8402140484
- B402030008 Updated LER 82-035/03X-3 on 821003, several recirculation actuation refueling water storage tank level switches found out of tolerance. Caused by instrument drift Surveillance Prequency increased W/840116 ltr MCGRATH: R Maine Yankes Atomic Power Co. 84/01/16 MURLEY: T E Region 1. Office of Director 4pp 22068 176 24X Fiche 50-307.84/01/16.8402030008
- 8402020321 LER 83-047/03L-0 on 831220 main control board slarm soundsé, indicating train B refueling water storage tank level off-scale high Caused by frozen suitches when maint worker left instrumentation on cabinet doors open W/840120 ltr LAFLANME. B J. WHITTIER, G D. Maine Yankse Atomic Power Co. 84/01/20 NWALEY, T E. Region 1. Office of Director, 3pp. 22058.155 24X Fiche 50-307.84/01/20,8402020321.
- B402210193 LER B4-001-00 on B40112.control element assembly dropped into core during control element drive sys alarm investigation. Caused by monitor circuit breaker or fuse failure within control drive element sys. W/840213 ltr.
 LAFLAMME.9 . WHITTIER.9 D Maine Yankee Atomic Power Co 84/02/13 4pp 22316:167 24X Fiche 50-309,84/02/13.8402210193
- 8402270421 LER 84-002-00 on 840125 remedial action of Tech Spec 3 20 entered to replace safety-related shock suppressors at power as part of extensive overhaul program. Bnubbers removed & replaced w/rebuilt units, W/840221 ltr
 NELSON.R H. WHITTIER.G D. Maine Yankes Atomic Power Co. 84/02/21 2pg 22389.360 24X Fiche 50-309,84/02/21,8402270421.

V Operator Examinations

B402010207 Grants extension until 840315 for implementation of new licensed operator staffing rule per 100FR50 54(m)(2) Tech Specs should be amended accordingly by 840315. EIBENHUT.D G. Division of Licensing 84/01/12. GARRITY.J H Haine Yanker Altomic Power Co Spp 22048 001, 24% Fiche 50-309.84/01/12. 8402010207

- --8402010212 Safety evaluation supporting extension until 840315 for implementation of revised control room shift staffing rule, per 10CFR00 54
 - per loctrou of * Dffsce of Nuclear Reactor Regulation, Director 84/01/12 2pp 22048 004 24% Fiche 50-309,84/01/12,8402010207
- DOCKET 50-311 SALEM NUCLEAR GENERATING STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 8402090003 Responds to FDIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel asetings Forwards App A.B & C documents
 FELTON.J M Division of Rules and Records 83/10/31
 RDSENBAUM.B M Technical Analysis Corp 19pp 22193 292 24X
 Fiche 30-000.83/10/31.8402090003
- --8402090169 Summary of 780726 meeting w/util on site re const completion plans & schedules, const status & scheduled fuel load date Related info encl
 BTRIGHT, R L Light Water Reactors Branch 3 78/08/02 Light Water Reactors Branch 3 5pp 22196 169 24X
 Fiche 50-000,83/10/31,8402090003
- F Security, medical, emergency & fire protection plans
- B402010135 Forwards Bubmittal 6 to contingency plan Submittal withheld (ref 100FR73 21)
 LIDEN,E A Public Service Electric & Gas Co of New Jersey
 B4/01/06 MWRLEY.T Region 1, Office of Director 1p 22038 260
 24X Fiche. 50-272, B4/01/06, 8402010135
- 8402010139 Forwards security plan, Rev B. Amend 3 Plan withheld (ref 10CFR73 21) LIDEN.E A Public Service Electric & Gas Co of New Jersey 84/01/06 KMRLEY, T Region 1, Office of Director ip 22038 232 24X Fiche 50-272, 84/01/06, 8402010139
- 8402130374 Draft safety analysis & implementation plan for safety parameter display sys W/840130 ltr
 LIDEN.E A Public Service Electric & Gas Co of New Jersey
 84/01/30 VARGA.S Operating Reactors Branch 1 22pp 22203 225
 24x Fiche 50-272,84/01/30.8402130394
- 8402130176 Forwards supporting bases for 831228 & 840113 requests for almostian from 100FR50.App R & two new exemption requests wisupporting bases M/five oversize drawings Aperture cards are available in FDR LIDEN.E A Public Service Electric & Gas Co of New Jarsey 84701/31 VARGA.S A Operating Reactors Branch 1 41pp. 22198-282 24X Fiche 50-272.84701/31.8402130176
- 8402070371 Forwards util 840130 ltr re safety analysis & implementation plan for amergency response capability, including attachments previously omitted PAYNE: L Public Bervice Electric & Gas Co of New Jersey 84/02/01 VAR9A, 8. NRC No Datailed Affiliation Given. 1p 22099 182 24X Fiche. 50-272, 84/02/01,8402070371
- --8402070374 Forwards safety analysis & implementation plan for safety parameter display sys.per Generic Ltr 82-33 re requirements for emergency response capability & LIDEN.E A Public Service Electric & Gas Co of New Jersey 84/01/30 VARGA.S Operating Reactors Branch 1 22pp 22099 183 24X Fiche 50-272,84/02/01.8402070371.
- B402230005 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by litensee, per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR FISCHER, D.C. Operating Reactors Branch i 84/02/07 UDERITZ, R.A. Public Bervice Electric & Gas Co. of New Jersey 3pp 22379 342 24X Fichs 50-272,84/02/07,8402230005
- J Insurance & indemnity information
- 8402160327 Forwards Endorsement 63 to NELIA Policy NF-230 & Endorsement 53 to MAELU Policy MF-90.

 GDLDEN.M P Marsh & McLennan, Inc 84/02/08 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp. 22277 011 24X Fiche, 50-272, 84/02/08, 8402160327

- P Operating license stage documents & correspondence
- B402060402 Notification of Significant Licensee Meeting 84-11 on 840201 w/util in King of Prussia.PA to discuss status of radiological safety & ALARA programs
 DRAGDUN, T Region 1. Office of Director 84/01/26 Region 1.
 Office of Director 2pp 22086 180 24X Fiche 50-272,84/01/26.
 8402060402
- B40210D403 Forwards Amend 23 to License DPR-75 & safety evalation Amend modifies schedular requirements for performance of visual snubber insps for Unit 2 to be consistent w/ requirements currently on Unit 1 f1SCHER.D Operating Reactors Branch i B4/01/27 UDERITZ,R A Public Service Electric & Oas Co of New Jersey 4pp 2220B 313 24X Fiche 50-311,84/01/27,8402100403
- --8402100405 Amend 23 to License DPR-75, modifying schedular requirements for performance of visual snubber insps for Unit 2 to be consistent w/requirements currently on Unit 1 VARGA, S A Operating Reactors Branch 1 B4/01/27 4pp 22208 317 24X Fiche 50-311,84/01/27,8402100403
- --8402100405 Safety evaluation supporting Amend 23 to License DPR-75 * Office of Nuclear Reactor Regulation, Director 84/01/27 2p 22208 321 24% Fiche 50-311.84/01/27.8402100403
- B4020B000B Notification of B4022B meeting w/util in Hancocks Bridge, NJ to discuss preventative maint program FIBCHER, D.C. Operating Reactors Branch 1 84/01/30 VAROA, S.A. Operating Reactors Branch 1 2pp 22173 001 24X Fichs 50~272,84/01/30.84020B000B
- B402090603 Forwards SER detailing review of Item II K 2 17 re potential for voiding in RCS during transients Steam void will not result in unacceptable consequences during anticipated transients
 VAROA, B A Operating Reactors Branch 1 B4/01/30 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 12pp 22189 337 24X Fiche 50-272, 84/01/30, 8402090403
- 8402010410 Generic Ltr 84-04 to all operating PWR licensees, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated plpe breaks in PWR primary main loops Svc list enci EISENHUT, D Q Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc 57pp 22177 0B7 24X Fiche 50-000,84/02/01,8402010410
- 8402130319 Forwards Tech Specs inadvertently omitted from B30328 amend package re containment sys LIDEN, E A Public Service Electric & Oas Co of New Jersey B4/02/06 VAROA, B Operating Reactors Branch 1 1p 22197 182 24X Fiche 50-272,84/02/06,8402130319
- --8402130326 Tech Specs inadvertently omitted from 830328 amend package re containment sys * Public Service Electric & Gas Co. of New Jersey 83/03/28 4pp 22197 183 24X Fichs: 50-272,84/02/06,8402130319
- 8402140312 Ack receipt of 831215 ltr transmitting resolutions to NRC concerns identified in 831115 ltr re 8A program description review Proposed change acceptable MARTIN.T T Division of Engineering & Technical Programs 84/02/08 UDERITZ.R A Public Service Electric & Gas Co of New Jersey 26p 22228 235 24X Fichs 50-272,84/02/08.8402140312
- G Inspection reports. IE Bulletins & correspondence
- B40R0R0329 Forwards IE Insp Repts 90-272/83-36 & 50-311/83-36 on B31110-1205 No violations noted STAROSTECKI R Division of Project & Resident Programs B3/12/30 UDERITZ RA Public Service Electric & Gas Co of New Jersey 2pp 22052:236 24X Fichs 50-272,83/12/30,8402020329
- ---B402020336 IE Insp Repts 50-272/B3-36 & 50-311/B3-36 on B31110-1205 No violations noted Major areas inspected review of periodic & special repts, LER review, design changes & mods & operating events Bome issues require further followsp &/or resolution LINVILLE, J.C., SUMMERG, R.J., KENNY, T.J., Region 1, Diffice of Director B3/12/28 12pp 22052 23B 24X Fiche 50-272, B3/12/30, B402020329
- B402070347 Forwards IE Insp Repts 50-272/83-38 & 50-311/83-37 on B31204-840110 No violations noted BTAR0BTECKI.R Division of Project & Resident Programs B4/01/23 UDERITZ.R A Public Service Electric & Gas Co of New Jersey 2pp 22097.024 24X Fiche 50-272.84/01/23.8402070347

- --BA02070351 IE Insp Repts 50-272/83-38 & 50-311/83-37 on B31206-840110
 No violations noted Major areas inspected periodic & special
 repts, LERs, operational safety verification, surveillance &
 maint observations
 LINVILLE, J C. SUMMERG, R J Region 1. Office of Director.
 NORRHOLM, L J Division of Project & Resident Programs 84/01/19
 12pp 22097 026 24X Fichs 50-272,84/01/23,8402070347
- 8312120153 IE Info Notice 84-06, "Steam Binding of Ausiliary Feedwater Pumps " Bvc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co. of New Yorks Inc. 120pp 22058 001 24X Fiche 50-000.84/01/25,8312120153
- 8402090359 Forwards IE Insp Repts 50-272/83-35 & 50-311/83-39 on B31114-18 No violations noted MARTIN,T T Division of Engineering & Technical Programs 84/01/25 UDERIYI.R A Public Bervice Electric & Gas Co of New Jersey 3pp 22161 096 24x Fichs 50-272.84/01/25.8402090359
- --8402090369 IE insp Repts 50-272/83-35 & 50-311/83-35 on 831116-18 No violation noted Major areas inspected training of security force, preliminary review of post-accident sampling sys & licensee action on previous insp finding DRACGON, F. WHITE, J. SHANDAKY, M. Region 1. Office of Director 84/01/10 4pp 22161 098 24X Fithe 50-272,84/01/25.8402090339
- 8402100403 Forwards Amend 23 to License DPR-75 & safety evalation Amend modifies schedular requirements for performance of visual snubber insps for Unit 2 to be consistent w/ requirements currently on Unit 1
 FISCHER, D. Operating Reactors Branch 1 84/01/27 UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey 4pp 22208.3i3 24X Fiche 50-3ii,84/01/27,8402100403
- --8402100405 Amend 23 to License DPR-75.modifying schedular requirements for performance of visual snubber insps for Unit 2 to be consistent w/requirements currently on Unit 1 VARGALS A Derating Reactors Branch 1. 84/01/27 4pp 22208 317 24x Ficha 50-311.84/01/27.8402100403
- --8402100406 Safety evaluation supporting Amend 23 to License DPR-75 * Office of Nuclear Reactor Regulation, Director 84/01/27 2pp 22208 321 24X Fichs 50-311.84/01/27,8402100403
- 8402070214 Act receipt of 830127 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/82-32 & 50-31/82-30 STAROSTECKI.R Division of Project & Resident Programs B4/02/01 UDERITZ.R A Public Service Electric & Oas Co of New Jersey Rpp 22102 174 24x Fiche 50-272, 84/02/01.8402070214
- --8402070217 Responds to NRC 821227 ltr re violations noted in IE Insp Repts 50-272/82-32 & 50-311/82-30 Corrective actions: supervisors reinstructed in responsibility to monitor personnel activities w/increased surveillance UDERITZ.R A Public Service Electric & Oas Co of New Jersey 83/01/27 HAYNES.R C Region 1. Defice of Director. STARROSTECKI.R Division of Project & Resident Programs. 2pp 22102 176 24X Fiche 50-272,84/02/01,8402070214
- B402070244 Ack receipt of B31031 & B40120 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-31/83-15
 STAROBTECKI.R Division of Project & Resident Programs 84/02/02 UDERTITAR.A Public Service Electric & Ons Co of New Jersey 1p 22101/243 24X Fiche 50-311,84/02/02.8402070244
- --B402070249 Responds to NRC 831031 ltr re violations noted in IE Insp Rept 50-311/83-15 Corrective actions: info directive issued requiring that planned ontry into action statements not be made until addi action requirements fulfilled LIDEN.E A Public Service Electric & Gas Co of New Jersey 83/11/28 STAROSTECKI, P. Division of Project & Resident Programs 3pp 22101 244 24% Fiche 50-311,84/02/02.8402070244.

103: |tr re violations noted in IE actions shift supervisors maint &/or testing not

t Gas Co. of New Jersey.
Tof Project & Resident Programs
I Gasocian Commons.

- B401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vant Headers " Svc list encl DEYGUNG.R C Director's Office Office of Inspection and Enforcement B4/02/03 Consolidated Edison Co of New York, Inc 102pp 22177
- 8401170041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R) " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Inc 124pp 22365 259 24X Fiche 50-000,84/02/13,840119041/
- 8401190037 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '*
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- 8401190045 IE Info Natice 83-63, Suppl 1. "Potential Failures of Wastinghouse Type 8A-1 Differential Relays" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22364 142 24X Ficher 50-000, 84/02/15, 8401190045
- B402280205 Ack receipt of B31121 & 840127 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-22 & 50-311/83-22 MARTIN.T T Division of Engineering & Technical Programs 84/02/17 UDERITZ.R A Public Service Electric & Gas Go of New Jersey 2pp 22400 192 24% Fichs 50-272,84/02/17.6402280205
- --8402280216 Responds to NRC 831021 ltr re violations noted in IE Insp. Repts 80-272/83-22 & 50-311/83-22 Corrective actions controls specified for use of master key guidance provided for transfer & return of high radiation area keys
 LIDEN,E A Public Service Electric & Qas Co. of New Jersey.
 84/01/27 MARTIN.T T Division of Engineering & Technical
 Programs 3pp 22400 194 24X Fichs 50-272.84/02/17.8402280205
- --8402280220 Responds to NRC 831021 ltr re violations noted in 1E lns;
 Repts 50-272/83-22 & 50-311/83-22 Corrective actions
 training program instituted an 830712 & completed 931104 &
 training held to familiarize personnel w/changes.
 LIDEN.E A Public Service Electric & Qas Co of New Jersey,
 63/1/21 MARTIN.T T Division of Engineering & Technical
 Programs 12pp. 22400 197 24X Fiche 50-272.84/02/17,8402280205
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co. of New York, Inc 116pp. 22366 024. 24X Fiche 50-000,84/02/21,8401190062
- 8401190066 IE Infq Notice 84-il. "Training Program Deficiencies "
 Svc list encl.
 JORDANIE L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co. of New
 York, Inc. 115pp. 22430 304 24X Fiche 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Beat Valve Smals."
 Svc list encl
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co. of New
 York, Inc. 120pp 22431.060 24X Fiche. 50-000, 84/02/27, 8401190057.
- R Periodic operating reports & related correspondence
- 8402060383 Advises that util has reestablished sampling for milk at Location 301 & discontinued sampling at Location 302 as part of radiological environ monitoring program LIDEN, EA Public Service Electric & Qas Co. of New Jersey B3/12/29, MURLEY, T E Region 1 Office of Director 2pp. 22086 318. 24X Fiche 50-272,83/12/29,8402060383
- B402100201 Forwards NPDES discharge monitoring repts for Det 1983 MILLER,L.K Public Service Electric & Oas Co of New Jersey. B4/01/23. RADON;E. New Jersey. Btate of 3pp 22178:276. 24X Fiche 50-272.84/01/23.8402100201
- --8402100204 NPDES discharge monitoring repts for Dec 1983 MILLER, L K Public Service Electric & Qss Co. of New Jerssy. 83/12/31. 18pp 22178-279 24X Fiche 50-272,84/01/23,8402100201
- B402210140 Monthly operating rept for Jan 1984 W/840210 ltr. HILLER, L. K. ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey 84/01/31 Spp. 22317.177 24X Fiche. 50-311, 84/01/31. 8402210140

- 8402280311 Forwards response to first quarterly rept of Nuclear Oversight Committee transmitted to NRC on 840126 Set of performence indicators using INPO recommendations & info from other utils developed LIDEN.E A Public Service Electric & Oas Co of New Jersey 84/02/21. VARGAS A Operating Reactors Branch 1 4pp 22399 219 24X Fiche. 50-272,84/02/21,8402280311
- B Reportable occurrences. LERs & related correspondence
- 8402240086 Further response to FOIA request for 16 catagories of documents Item 7 limited.per 831005 telcon Forwards Rev 7 to NUREO-0525 & App A documents Portions of App B documents sithheld (ref FOIA Exemption 4) App B documents also in PDR FELTON.J M Division of Rules and Records 83/12/12 SHOLLY.B C Union of Concerned Scientists 4pp 22374 150 24X Fiche 50-000,83/12/12.8402240086
- --8305160003 Becurity event rept re B30504 bomb threat
 UDERITZ.R A Public Service Electric & Gas Co of New Jersey
 B3/05/09 Director's Office, Office of Inspection and
 Enforcement 3pp 22394 154 24X Fiche 50-000,83/12/12,
 8402240084.
- B402030323 LER 83-066/03L-0 on 831220, common suction valve 2RH1 closed, resulting in loss of RHR flow. Caused by personnel error RHR pump 22 started & RHR flow reestablished within 22 minutes 4/240118 ltr RUPP.J L. ZUPKO, J M Public Bervice Electric & Gas Co. of New Jarsey, B4/01/18 MURLEY.T E Region 1, Office of Director 4pp 22067, 100 24X Fichs 50-311,84/01/18,8402030323
- B402070187 LER 83-047/03L-0 on 831231 during surveillance testing, dissel generator 28 experienced fuel oil leak on cylinder injector 8R Caused by fuel oil manifold to injector gasket testage. Casket replaced W/B40127 ltr RUPP. J L . ZUPKO. J M. Public Service Electric & Gas Co of New Jarsey. B4/01/27. MRLEY, T E Region i. Office of Director 4pt 22101 012. 24X Fiche 50-311,64/01/27,8402070189
- 8402090433 Responds to 831114 request for extension to completion date for corrective action program Item C 8 a 4 Mod of 830506 order extending date to 840630 enc1
 VARQA, S A Operating Reactors Branch 1 84/01/31 UDERITZ, R, A Public Service Electric & Qas Co. of New Jerssy. 3pp 22177, 307 24% Fiche 50-272, 84/01/31, 8402090433
- --8402090435 Notice of mod to 830506 order extending completion date for Item C 8 a 4 of corrective action program re reactor trip circuit breakers to 840630 PERPLEER A. Division of Licensing 84/01/31 App 22177 310 24X Fiche.50-272.84/01/31,8402090433
- B402150010 LER 84-001-00 on 840112, reactor coolant loop resistance temp detector bypass line 14 experienced low flow condition Caused by corrosion product blockage. Bypass line valves will be replaced Handwheels 22RC17 & 23RC24 removed W/940209 itr RUPPJ, L., ZUPAG, J. M. Public Service Electric & Oas Co. of New Jersey. 84/02/09 opp. 22249 219 24X Fiche 50-311,84/02/09,8402150010
- 8402290009 Notification of Bignificant Licensee Meeting 84-09 on 840306 in Balem, NJ to discuss ATWS event corrective action program NORRHOLMs. J Division of Resource Management & Administration B4702/21. pivision of Resource Management & Administration ip R2437 328 24X Fiche. 50-272, 84/02/21, 8402290009

V. Operator Examinations

- 8402080016 Requests info re issue of periodic evaluation quizzes within 30 days. Response to first issue re type of matl used in open book quiz satisfactory.

 VARQA. B. A. Operating Reactors Branch 1 84/01/24 UDERITZ, R A. Public Service Electric & Que Co of New Jersey, 4pp 22172, 351 24% Fiche 50-272, 84/01/24, 8402080016.
- DOCKET'50-312 RANCHO SECO NUCLEAR GENERATING STATION
 F. Becurity, medical, emergency & fire protection plans
- 8402090392 Forwards procedures generation package in response to Generic Ltr 82-33. Suppl 1 to NUREQ-0737. "Requirements for Emrgency Response Capability " Procedures include plant-specific technical guidelines RODRIGUEZ.R.J. Sacramento Municipal Utility District 84/01/31 BTOLZ-J.F Operating Reactors Branch 4 3pp. 22183-034 24X Fiche: 50-000, 84/01/31, 8402090392.

- --B402090396 Procedure 32-1106885-00, "Abnormal Transient Operating Guidelines Arkansas Nuclear One Unit 1 - Rancho Seco Sys Comparison " IRIOWNELL.R B Babcock & Wilcox Operating Plants Owners Group B1/07/16 27pp 22183 037 24X Fiche 50-G00.84/01/31,8402090392
- --B402090400 Rev i to Procedure AP 47, "Emergency Operating Procedures Writers Guide " * Sacramenta Municipal Utility District 83/09/16 17pp 22183 063 24X Fiche 50-000.84/01/31.8402090392
- ~-B402070402 "Verification & Validation Program Description for Rancho Suco Procedures Generation Package Submittal " * Bacramento Municipal Utility District 84/01/31 3pp 22183 080 24X Fiche 50-000.84/01/3i.8402070372
- --8402090405 "Training Plan for Implementation of Emergency Operating Procedures" * Sacramento Municipal Utility District 84/01/31 2pp 22183 083 24X Fiche 50-000.84/01/31.8402090392
- --8402070407 "Transient Info Document for Loss of Offsite/Onsite Power at Rancho Seco " HILTUNEN.E A Sacramento Municipal Utility District 86-1126637-00 81/10/08 167pp 22183 085 24X Fiche 50-000.84/01/31.8402070392
- ---8402090410 Procedure 84-1127307-00, "Abnormal Transient Operating Quidelines Excessive Main Feedwater Event Transient Info Document " BROWNELL,R B Babcock & Wilcox Operating Plants Duners Group B1/09/03 76pp 22183 252 24X Fiche 50-000,84/01/31,8402090392
- --8402090412 Procedure 86-1127426-00, "Abnormal Transient Operating Guidelines for Loss of Feedwater Transient Info Document " KWHR.E M Babcock & Wilcox Operating Plants Dwners Group 81/08/20 29pp 22183 328 24X Fiche 50-000,84/01/31,8402090392
- --8402070418 "Transient Info Document for Small Steam Line Break Event " SCHWENN, A S Babcock & Hilcox Operating Plants Owners Group 84-1127102-00 81/08/17 30p 22183 337 24X Fiche 50-000,84/01/31.8402090392
- ---8402090425 Procedure 74-1127469-00.Vol 1, "Abnormal Transient Operating Guidelines.Part I Procedural Guidelines " KELLY,J J Babcock & Wilcox Co 82/12/15 124pp 22184 024 24X Fiche 50-000,84/01/31,8402090392
- --8402090430 Procedure 74-1127469-00, Vol 1, "Abnormal Transient Operating Guidelines.Part II Fundamentals of Reactor Control for Abnormal Transients " * Babcock & Wilcox Co 82/10/08 311pp 22184 148 24X Fiche 50-000.84/01/31,8402090392
- --B40209043R Procedure 74-1127469-00.Vol 2, "Abnormal Transient Operating Quidelines.Part II Discussion of Belected Transients "Wiseven oversize encl Aperture cards are evailable in FDR # Dabcock & Milcox Co 82/10/08. 252pp 22185 099 24X Fiche 50-000.B4/01/31.B402090392

G Adjudicatory correspondence

B402030193 Advises that time for Commission to review ALAB-746 expired Commission declined review Decision became final agency action on B40131 Esparate view of Commissioner Gilinsky encl.

CHILK, B J Office of the Secretary of the Commission, B4/02/02 Atomic Safety and Licensing Board Panel 2pp 22068 001 24X Fiche, 50-312,8402/02,8402030193

H. General correspondence

- 8402230087 Requests NRC update mailing labels on priority & free mail to reflect new ofc location CHAMBERLAIN.W California, State of B4/02/15 DI SILBESTRE, B NRC NO Detailed Affiliation Given 2pp 22362 073 24X Fiche, 50-000, 84/02/15, 8402230087
- P. Operating license stage documents & correspondence
- BA02070012 Notification of 840207-10 site meetings w/util to review status/schedule & completeness of installation for selected NURGO-0737 items
 MINER, 9 Operating Reactors Branch 4 84/01/27. STOLZ, J F Operating Reactors Branch 4. 3pp 22142, 275 24X Fiche: 50-312, 83201/27, 8402070012

- B312120029 Generic Ltr B3-39 to representatives of utils re voluntary survey of licensed operators Svc list encl EISENHUT, D 0 Division of Licensing B3/12/08 Commonwealth Edison Co 12pp 22313 006 24X Fiche 50-000,83/12/09,8312120029
- E402010444 Responds to FOIA request for SECY-83-288 & SECY-83-443 to be placed in PDR SECY-83-288 available in PDR SECY-83-443 being placed in PDR Forwards SECY-83-443 FELTON, J M Division of Rules and Records 84/01/17 YENOUSKAS, J Neuman & Holtzinger 1p 22061 272 24% Fiche 50-000.84/01/17, B402010444
- --8402010493 Informs Commission of info obtained re flux reduction programs for pressurized thermal shock at lead plants. since 830225 interim rept (SECY 83-074). DIRCKS.W J Office of the Executive Director for Operations SECY-83-443 83/10/28 lipp 22041 273 24% Fiche 50-000,84/01/17.8402010444
- 8402060294 Forwards Amend 52 to License DPR-54, safety evaluation, EIA & notice of issuance & avoilability Amend revises Tech Specs to allow increase in storage capacity for fuel pool from 579 to 1.080 storage locations
 STOLZ.J F Operating Reactors Branch 4 84/01/20 RODRIQUEZ.R J Sacramento Municipal Utility District 3pp 22109 301 24X
 Fiche 50-312.84/01/20.8402060294
- --B402060278 Amend 52 to License DPR-54.revising Tech Specs to allow increase in storage capacity for fuel pool from 579 to 1.080 storage locations
 STOL2.J F Operating Reactors Branch 4 B4/01/20 4pp, 22109 304 24X Fiche 50-312,84/01/20,8402060294
- ~-8402060304 Safety evaluation supporting Amend 52 to License DPR-54 # Office of Nuclear Reactor Regulation, Director, 84/01/20 16pp 22109 308 24% Fiche 50-312.84/01/20.8402060294
- --8402060308 EIA supporting Amend 52 to License DPR-54

 # Office of Nuclear Reactor Regulation. Director 84/01/20
 11pp 22109 324 24% Fiche 50-312,84/01/20,8402060294
- --8402060312 Notice of issuance & availability of Amend 52 to Licenso DPR-54 STDLZ:JF Operating Reactors Branch 4 84/01/20 2pp 22109 335 24X Fiche 50-312,84/01/20,8402060274
- B402030087 Summary of 840112 meeting w/util re request to extend deadline for implementing licensed operator staffing rule (100FR50 54)
 NINERS Operating Reactors Branch 4 84/01/23 Operating Reactors Branch 4 84/01/23 Operating Reactors Branch 4 11pp 22091 026 24X Fiche 50-312,84/01/23
- 8401170012 Board Notification 84-013 forwards info re Transamerica Delaval Inc smergency diesal generators EISEMHUT D © Division of Licensing 84/01/24 PALLADINO, N . GLINSKY, V , ROBERTS, T Commissioners. 10pp. 22054, 346. 24x Fiche 50-000,84/01/24,8401190012
- ~-8312230127 Requests meeting during wk of 831212 to discuss Transamerica Delayal diesel generators List of proposed questions Ancl. NOVAK.T M Assistant Director for Licensing. 83/12/01 MATTHEMS.L B Transamerica Delayal, Inc. 18pp 22054 056 24% Fiche 50-312.84/01/24.8401190012.
- --8312200134 Forwards response to nine Users Group questions presented at 831130 meeting & forwarded by R Caruso 831127 ltr re standby diesel generators at nuclear power plants MATHEMS, C 8 Transamerica Delaval, Inc 83/12/16 NOVAK, T. M Assistant Director for Licensing 19pp 22054-358, 24X Fiche 50-000,84/01/24.8401190012
- B402060092 Forwards revised relief requests in response to request for add1 info re inservice testing of pumps & valves Summary of rovs listed RODRIGUEZ, R J Sacramento Municipal Utility District 84/01/25. STOLZ, J P. Operating Reactors Branch 4. App. 22089: 129 24X Fiche 50-312,84/01/25,8402060092

icense DPR-54 consisting of t to definition of

ility District 84/01/26 1p 22087 256 24X

inition of operable components.

District 84/01/26 4pp. /01/26.8402060231.

- 8401170015 Board Notification 84-018 provides info re failure experience of Transamerica Delaval emergency diesel generators in marine svc EISENHUT, D O Division of Licensing 84/01/27 FALLADIND, N J , OILINBKY, V. ROBERTS, T M Commissioners 385pp 22093:027 24x Fiche 50-000,84/01/27,8401190015
- 8402030295 Forwards 14 oversize drawings showing as-built reactor vessel dimensions in response to NRC 831228 request Apertura cards are available in PDR RODRIGUEZ.R.J Sacramento Municipal Utility District 84/01/31 87012.J F. Operating Reactors Branch 4 1p 22066 092 24x Fiche 50-312.84/01/31.8402030255
- 84020B0306 Forwards request for add1 info re Transamerica Delaval diesel generators Schedule for responses to questions in Encl 1 requested within 30 days of ltr data.

 8TOLZ.J F Operating Reactors Branch 4 84/01/31 RODRIQUEZ.R J Sacramento Municipal Utility District 4pp. 22172.225 24X Fiche.50-312.84/01/31.8402080306
- 8402010410 Generic Ltr 84-04 to all operating PWR licensees, CP holders & applicants for CPs re safety evaluation of Westinghouse topical regts dealing w/elimination of postulated pipe breaks in PWR primary main loops 8vc list encl EISENHUT.D G. Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc. 59pp #2177.087 24X Fiche.50-000.84/02/01.8402010410
- B402070209 Responds to 831202 request for info re plan for conducting detailed control room design review Revised plan will be submitted by end of Apr 1994 ROBRIQUEZ, R J. Secremento Municipal Utility District B4/02/02 BTGLZ, J F Operating Reactors Branch 4. ip. 22101 056, 24% Fiche. 50-312, 84/02/02, 8402070209.
- B402170061 Notification of B40210 meeting w/Transamerica Delawal Inc (TDI) in Bethesda MD to discuss program plan proposed by TDI Cumers Group to qualify dissel generators. CARUSO, R. Division of Licensing 84/02/06 BERLINGER.C. Division of Licensing 2pp. 22312.339. 24X Ficha 50-000,84/02/06, 8402170061
- 8402150502 Notification of 840307 meeting w/util in Bethesda. MD to discuss & resolve outstanding equipment environ qualification issues
 MINER, 8 Operating Reactors Branch 4 84/02/08 STULZ, J F Decrating Reactors Branch 4 2pp 22261 360 24X
 Fiche 50-312,84/02/08,8402150502
- 8402220177 Forwards elementary diagrams showing proposed design reautomatic reactor trip sys actuation of control rod drive breaker shunt trip, per commitment in response to Item 4 3 of generic Ltr 83-28 RODRIGUEZ, R. J. Bacramento Municipal Utility District, 84/02/13 E18ENHUT. D G. Division of Licensing 8pp 22340 299, 24X Fiche 50-312.84/02/13,8402220177
- 8408220378 Responds to 83:021 ltr re justification for not considering low temp overpressurization protection event Due to change of 830808 SER, scope of evaluation increased, Justification anticipated by 840413 RODRIGUEZ.R. J. Sacramento Municipal Utility District 84/02/15 STOLZ.J.F. Operating Reactors Branch 4. ip. 22334, 308 24% Fiche 50-312,84/02/15,8402220378
- O Inspection reports, IE Bulletins & correspondence
- 8312120153 IE Info Notice 84-04, "Steam Binding of Auxiliary Feedwater Pumps " Svt list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/25 Consolidated Edison Co. of New York, Inc. 120pp 22058 001 24% Fithe.50-000,84/01/25,8312120153
- B402030232 Informs that final rept on review of auxiliary fredwater pump per IE Bulletin 80-04, "Main Steam Line Break w/Continued Feedwater Addition" will not be ready for submitted until 840315 RODRIGUEZ.R J Sacramento Municipal Utility District, 84/01/27. STOLZ, J.F. Operating Reactors Branch 4. 1p. 22069-341. 24X Fiche 50-312,84/01/27.8402030252
- 8402130437 Requests clarification of JF Stolz 831028 ltr to JJ Mattimos re starting date of next 120-month inservice insp interval. RODRIGUEZ.R J. Bacramento Municipal Utility District 84/01/30 HINER, 8 NRC No Detailed Affiliation Given ip 22201 270 24X Fiche 50-312,84/01/30,8402130437
- 8401190016 IE Info Notice 84-07. "Design-Basis Threat & Review of Vehicular Excess Controls "Syc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). 84/02/03 Consolidated Edison Co. of New York, Inc. 119pp. 22114 179 24X Fiche: 50-000, 84/02/03, 8401190016

- B401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers." Svc list encl BEYOUND: A C Director's Office, Office of Inspection and Enforcement B4/02/03 Consolidated Edison Co of New York, Inc 102pp. 22177 156 24X Fiche 50-000.84/02/03.8401190017
- B401150041 IE Inpo Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R) " Syc list encl.
 - ORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc. 124pp 22365 259 24X Fiche 50-000,84/02/13,8401190041
- B401190050 Board Notification 84-021 provides rapts of Transamerica Delayal, Inc insps conducted from Mar 1979 to Oct 1983 EISENHUT, D G Division of Licensing 84/02/13 PALLADINO, OLLINSKY, ROBERTS Commissioners 5pp 22314 001 24X Fiche, 50-000, 84/02/13, 8401190050
- 8401190039 IE Info Notice 84-08, "IOCFR50 7, 'Employee Protection '"
 Svc list encl.
 JORDAN-E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York. Inc 115pp 22365 141 24X Fiche 50-000.84/02/14.8401190039
- 8401190045 IE Info Notice 83-63, Suppl 1. "Potential Failures of Hestinghouse Type 9A-1 Differential Relays " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15. Consolidated Edison Co of New York Inc. 118pp 22366 142 24X Fiche. 50-000, 84/02/15, 8401170045
- B4011900A2 IE Info Notice B4-10, "Motor-Operated Valve Torque Switches Bet Below Manufacturer Recommended Value " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc. 116pp 22366.024 24X Fiche 50-000,84/02/21,8401190062
- 8491190066 IE Info Notice 84-11, "Training Program Deficiencies"

 Syc list encl

 JORDAN, EL Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/24 Consolidated Edison Co of New
 York, Inc. 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Boft Seat Valve Seals"

 Syc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Fost 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431.060 24X Fiche 50-000,84/02/27,8401190067
- A. Periodic operating reports & related correspondence
- B402220350 Monthly operating rept for Jan 1984, W/840203 ltr. COLONBO, R., RODRIQUEZ, R. J. Bacramento Municipal Utility District. 84/01/31 7sp 22334:169 24X Fiche 50-312, 84/01/31, 8402220350
- 9 Reportable occurrences, LERs & related correspondence
- \$402030299 Part 21 rept re potential problem w/hattery ground detector relay 1TE 278. Portions of solid state circuitry can be overstressed under certain operating conditions. Users of relays will be notified List of users of relay encl.

 DUVALL,D. D. Brown Boveri Corp (subs of Brown Boveri & Co., Ltd)

 84/61/05. DEYOUNG,R.C. Director's Office. Upfice of Inspection and Enforcement. 3pp. 22067.122, 24X Fiche 30-000.84/01/05.8402030299
- 8402030355 LER 83-041/03L-0. on B31220 during plant tour, valve on 1/4-inch line supplying cooling water to auxiliary feadwater pump turbine bearings & governor found closed, Valva not included on lingups or in surveillances. W/840117 ltr ROBRIGUEZ, R. J., COLLOMBO, R. M. Sacramento Municipal Utility District, 84/01/20. MATIN, J. B. Region 5, Office of Director, Spp 22049-160. 24X Fiche. 50-312, 84/01/20, 8402030355
- 8402070393 Requests that NRC investigate design reliability of emergency dissel generators supplied by Transamerica Delayel, Inc. Engine problems have been experienced since delivery of first vessel in May 1981. Related info encl MOLINA, J.C. Falcon Carriers, Inc. 84/02/01. DENTON.H R. Office of Nuclear Reactor Regulation, Director 63pp 22096:057. 24X Fithe: 50-000, 84/02/01, 8402070393
- B402140141 LER B4-001-00. on 840105, fan EFA-18 bearing providing suction to post-accident sampling sys failed. Fan rebalanced & original type bearings reinstalled. W/840207 ltr.
 COLOMBO.R.W. RODRIGUEZ, R.J. Bacramento Municipal Utility District 84/02/07. MARTIN.J.B. Region 5. Office of Director 3pp 22276. 314. 24x Fiche 50-312, B4/02/07, B402140141

- 8402140388 LER 64-002-00 on 840107, GA audit revealed that results of inservice insp not submitted to NRC within 3 months of completion of insps Caused by Inspector error Rept not signed by authorized inspector until 84017 W/840207 ltr CDLCHBD.R W . RODRIGUEZ.R J Bacramento Municipal Utility District 84/02/079 MARTIN.J B Region 3. Office of Director 3pp 22220 048 24X Fithe 50-312,84/02/07,8402140388
- B401190053 Board Notification 84-020 forwards info re Transamerica Delayal, Inc emergency diesel generator problems Attendance list meeting handouts & slides encl EIBENHUT.D O Division of Licensing B4/02/13 PALLADIND, OILINSKY, ROBERTS Commissioners 102pp 22332 202 24X Fiche 50-000,84/02/13.8401190053
- B402220530 Part 21 rept re defective DSR & DBRV standby diesel generator turbocharger thrust bearing lubrication Deficiency not corrected by sys mod New recommendation will be sent to customers by 840330 BOYER,R E Transamerica Delaval, Inc 84/02/15 Director's Deffice, Office of Inspection and Enforcement 5pp 22332 182 24X Fiche 50-000,84/02/15,8402220530
- 8402230034 LER 84-005-00 on 840110 sirens did not respond during siren readiness test Caused by transmitter/encoder failure
 Transmitter/encoder repaired & sys declared operational W/840217 itr
 COLOMBO R N MELLOR, K Sacramento Municipal Utility District
 84/02/17 MARTIN J B Region 5 Office of Director 3pp
 22362-060 24X Fiche 50-312-84/02/17.8402230034
- 8408230206 LER 84-003-00 on B40117. Burveillance Procedure SP 210 01A change conflicted w/Tech Specs Problem w/flow transmitter design also discovered Caused by confesser vacuum causing sensing lines to drain Procedure revised W/B40217 itr CDLOMBO,R W . MELLOR, K Sacramento Municipal Utility District 84/02/17 MARTIN,J B Region 5, Office of Director 4pp 22352 356, 24X Fiche 50-312.84/02/17.8402R30206
- B4022B0701 Notification of B4030B meeting w/Transamerica Delaval, Inc (TDI) Dumers Group in Wading River, NY to discuss TDI proposed program plan to qualify dissel generators CARUSD, R Division of Licensing 84/02/23 BERLINGER, C Division of Licensing Rpp 22414 340 24X Fiche 50-000, 84/02/23, B4022B0701

V Operator Examinations

B402070109 Forwards best estimate schedule in response to Generic Ltr 83-40 re operator licensing exam schedule Revised or final dates will be provided when appropriate RODRIGUEZ.R J Secremento Municipal Utility District 84/01/25 EIBENHUT.D 0 Division of Licensing 2pp 22102 303 24% Fichs 50-312,84/01/25,8402070109.

DOCKET 50-313 ARKANBAS NUCLEAR ONE, UNIT 1

- A Application/construction stage documents & correspondence
- 8402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documents FELTON, J M Division of Rules and Records 83/10/31 RDBENBAUM, D M Technical Analysis Corp 19pp 22193 272 24X Fiche 50-000,83/10/31,8402090003
- F Security, medical, emergency & fire protection plans
- B402220578 Forwards IE Insp Repts 50-313/83-27 & 50-368/83-27 on B31001-1104 & notice of violation.

 GAGLIARDOJE Region 4. Office of Director 83/11/28

 GRIFFIN,J M Arkansas Power & Light Co 2pp 22332:167 24X

 Fiche: 50-313-83/11/28, 8402220578
- --B402220396 IE Insp Repts 50-313/83-27 & 50-348/83-27 on 631001-1104
 Noncompliance noted failure to complete job order form per
 procedural requirements & failure to maintain station
 hattery operable, per Tech Specs
 CALLAN.L.J., CUMMINS.J.E., EVANS.C.A. Region 4, Office of
 Director 83/11/22, 12pp 22332 170 24X Fiche 50-313,83/11/28,
 8402220578
- 8402220271 Forwards IE Insp Repts 50-313/83-31 & 50-368/83-31 on B31128-1202.No violations or deviations identified GAGLIARDD.J.E Region 4. Office of Director 84/01/10 GRIFFIN.J M Arkansas Fower & Light Co 2pp 22337 119 24X Fiche, 50-313, 84/01/10, 84022202271

- --8402220280 IE Insp Repts 90-313/83-31 & 50-369/83-31 on 831128-1202 No violations or deviations identified Major areas inspected fire protection/prevention program & program implementation & compliance to IOCFRBO. App R. Bections III J & III O MURPHY. M E , JUNNSON, W D Region 4. Office of Director 84/01/04 Bpp 22337 121 24% Fichs 50-313,84/01/10,8402220271
- 8402010127 Forwards IE imag Repts 50-313/83-27 & 50-368/83-27 on 831031-1104 No violations noted 0AGLIARDO.J E Region 4, Office of Director 84/01/12 0RIFFIN.J H Arkanasa Power & Light Co 2pp 22042 165 24X Fiche 50-313,84/01/12.8402010129
- --B402010132 IE Insp Repts 50-313/B3-29 & 50-348/B3-29 on B31031-1104 No violations noted Major areas inspected status of actions taken in response to emergency preparedness appraisal & routine insp findings
 HACKNEY.C A . BAIRD.J B . JDHNSON.W D Region 4. Office of Director B4/01/11 12pp 22042 167 24X Fiche 50-313.84/01/12.8402010129
- 8402220355 Forwards IE Insp Repts 50-313/83-30 & 50-368/83-30 on 831117-18 No violations or deviations noted GAGLIARDD.J E Region 4. Office of Director 84/01/18 GRIFFIN.J M. Ariansas Power & Light Co. 2pp 22335 340 24X Fiche 50-313-84/01/18-8402220355
- --BAG2220367 IE Insp Repts 50-313/83-30 & 50-368/83-30 on B31117-18 No violations or deviations noted Major areas inspected security plan & proposed changes Details withheid (ref LOCFR73 21)
 KELLY, J A , HALL, R E , JOHNSON, W D Region 4, Office of Director B4/01/17 ip 22335 342 24X Fiche 50-313,84/01/18,8402220355
- 8402130040 Forwards remittance for 10CFR170 fees for fire protection vevious & approvals.per NRC 831203 ltr MARBHALL.J R Arkansas Power & Light Co 84/01/30, MILLER, W O License Fee Management Branch 2pp 2204 083 24X Fiche 50-313,84/01/30.8402130040
- 8402090392 Forwards procedures generation package, in response to Generic Ltr 82-33. Suppl 1 to NUREG-0737, "Requirements for Emergency Response Capability "Procedures include plant-specific technical guidelines RODRIGUEZ, R J Sacramento Municipal Utility District 84/01/31 STULZ, J F Operating Reactors Branch 4 3pp. 22183 034. 24x Fichs 50-000,84/01/31,8402090392
- --8402090396 Procedure 32-ii06885-00, "Abnormal Transient Operating Quidelines Arkansas Nuclear One Unit I - Rancho Seco Sys Comparison " BROHMELL, R B Rabcock & Hilcox Operating Plants Owners Group 81/07/16 27gp 22183 037 24% Fichs 50-000.84/01/31,8402090392
- 9402210269 Revised emergency implementing procedures, including Procedures 2607 009 re sampling Unit 2 waste condensate tanks & 2607 021 re sampling waste condensate ion 'xchangers W/840202 transmittal form EVINE.J M Arkansas Power & Light Co 84/02/01, 9pp 22315 340 4X Fiche 30-313.84/02/01.8402210267
 - v2130636 Requests fee for BiO319 & 920701 applications re exemption from certain App R requirements & alternate safe shutdown apability be remitted within 15 days of receipt of itr ILLER.W O License Fee Management Branch B4/02/08 GRIFFIN.J.M Arkansas Power & Light Co. 1p 22214:292 24X Fiche 90-313.84/02/08.8402130636
- 402170428 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensesser 810709 Ceneric Ltr 81-27 W/o request.entire plan will be placed in PDR MILLER.J R Operating Reactors Branch 3. 84/02/08 GRIFFIN.J H Arkansas Power & Light Co. 2pp. 22313.172 24X Fiche 50-313.84/02/08.8402170428
- 2240265 Addresses Commissioner comments re emergency operations actility concerning feasibility & cost of upgrading grimary margency operations facility to radiation protection actor of five Response requested by 840302
 TOLZ-J F. Operating Reactors Branch 4. MILLER, J R. Operating eactors Branch 9. Arkanses Power & Light 3. 3pp 22381 266. 24X Fiche 50-313.84/02/14.8402240245

Insurance & indemnity information

02130186 Forwards Endorsement 5 to NELIA Centificates N-48 & N-68 & Endorsement 5 to MAELU Centificates M-48 & M-68 MARSHALL, J R Arkansas Power & Light Co. 84/02/06 DINITZ, I. 0ffice of Nuclear Reactor Regulation Director 5pp 22204:154 24% Fiche 50-313,84/02/06,8402130186

- 840213025B Forwards Endorsements 56 & 57 to NELIA Policy NF-210 & Endorsements 48 & 49 to MACLU Policy MF-74 MARSHALL, J R Arkansas Power & Light Co 84/02/06 DINITZ, I Office of Nuclear Reactor Regulation, Director 5pp 22198 227 24X Fichs 30-313.84/02/06.8402130258
- P Operating license stage documents & correspondence
- B402220060 Submits final routine status rept of drawing control progress progress Pilot program to redraw isometric drawing using computer aided drafting sys under evaluation MARSHALL, JR Arkansas Power & Light Co 83/12/01 QAGLIARDO, J.E./Division of Resident, Reactor Project & Engineering Programs 3pp 22338 320 24% Fiche 50-313,83/12/01.8402220060
- 8312120029 Generic Ltr 83-39 to representatives of utils re voluntary survey of litensed operators Bvc list encl EISENHUT, D 0 Division of Licensing 83/12/08 Communication Edison Co 12pp 22313 006 24% Fiche 50-000, 83/12/08, 8312120029
- 8402060331 Forwards BER re shunt trip attachment of control drive trip breakers Requests proposal for Tech Specs requiring independent verification of operability of shunt trip & undervoltage trip attachments
 BTOLZ, J F Operating Reactors Branch 4 84/01/24 GRIFFIN, J M Arkansas Power & Light Co 2pp R2111 001 R4X Fiche 50-313,84/01/24.8402060331
- ---B402060334 SER re util B3ii05 proposal re shunt trip attachment of control drive trip breakers Mod acceptable NRC No Detailed Affiliation Given B4/01/24 10pp 22111 003 24X Fichs 50-313.84/01/24.8402060331
- 8402060154 Requests schedule for submitting info re emergency feedwater sys seismic qualification concerns for all vent & drain lines within 15 days.

 STDLZ, J F Operating Reactors Branch 4 84/01/25. ORIFFIN, J H Arkansas Power & Light Co. 2pp 22107 011 24X Fiche: 50-313,84/01/25,8402060154
- 8402030458 Informs that response to 831219 ltr re station electrical distribution voltage verification test requested by 840128 will be delayed until 840227 due to licensing workload MARSHALL.JR Arkenses Power & Light Co. 84/01/27 SIDLI.JF Operating Reactors Branch 4 ip 22069-058 24X Fiche 50-313,84/01/27,8402030458.
- 8402070433 Discusses implementation of & Tech Specs for proposed shunt trip Paature of reactor trip breakers Schedule for submittal of proposed Tech Specs requested STOLZ.J F Operating Reactors Branch 4. 84/01/27. QRIFFIN.J M Arkansas Fower & Light Co. 2pp 22142 092 24X Fiche 50-313.84/01/27.8402070433.
- 8402080110 Notification of 840206 & 07 meetings w/util in Russellville. AR to discuss status/schodule & completeness of installation for selected NUREQ-0737 items identified in encl agenda. VISSINO, 0. Operating Reactors Branch 4. 84/01/27. STDLZ, J F Operating Reactors Branch 4. 3pp 22172 324 24X Fiche. 50-313,84/01/27,8402080110.
- 8402010410 Generic Ltr 84-04 to all operating PWR licensees, CP holders & applicants for CPs re safety evaluation of Hestinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Svc list encl.
 EISENHUT.D.O. Division of Licensing. 84/02/01. Consolidated Edison Co of New York, Inc. 57pp 22177,087 24X
 Fiche 50-000.84/02/01.8402010410
- 8402070570 Requests rev to Tech Specs re explosive gas mixture in radwaste gas sys, due to proposed hydrogen/oxygen concentration limits being above std radiological effluent Tech Spec limits Response requested within 45 days STOLZ, J.F. Operating Reactors Branch 4 MILLER, J.R. Operating Reactors Dranch 3, 84702/01 GRIFFIN, J.M. Ankansas Power & Light Co. 7pp 22186-343. 24X Fiche 50-313,84702/01,8402090570.
- 8402160581 Forwards Amends 82 & 52 to Licenses DPR-51 & NPF-6, respectively Amends revise Tech Specs to reflect reorganization of energy supply dept & plant functional organization.

 MILLER, J. R. Operating Reactors Branch 3 84/02/01 GRIFFIN, J. H. Arkansas Power & Light Co. 4pp. 22302.077. 24X
 Fiche 50-313.84/02/01.8402160581
- --8402160593 Amends 82 \$ 52 to Licenses DPR-51 & NPF-6, respectively, revising Tech Space to reflect reorganization of energy supply dept & plant functional organization.
 BTDL7.J.F. Operating Reactors Branch 4. 84/02/01, 39pp.
 22302 081 24X Fichs.50-313,84/02/01.8402160581

- 8402:60293 Responds to Generic Ltr E4-Oi re NRC use of terms important to safety & safety-related Participation in discussion will be through steering committee & chairman of util safety classification group MARBMALL.JR Arkansas Power & Light Co B4/02/13 TAYLOR.JM Director's Office, Office of Inspection and Enforcement Ip 22274:224. 224. 24X Fiche 50-313.84/02/13.8402160273
- 8402370482 Confirms 840210 telcon re inadequate core cooling issue Encs indicated that add1 justification for adequacy of systems core exit thermocouple sys to survive adverse environs would be provided in 2 wks.

 SYOLZ, J.F. Operating Reactors Branch 4 84/02/14 GRIFFIN.J M Arkansas Power & Light Co 2pp 22305 318 24X
 Fiche 50-313.84/02/14.8402170482
- 8402240035 Responds to 840125 request for schedule for submittal of addl info on seismic qualification of emergency feedwater sys Info will be submitted by 840316 MARBHALL.J R Arkansas Fower & Light Co 84/02/15 STOLZ, J F Operating Reactors Dranch 4 ip 22375 318 24X Fiche 50-313,84/02/15,8402240035

9. Inspection reports, IE Bulletins & correspondence

- 8402220578 Forwards IE Insp Repts 50-313/83-27 & 50-369/83-27 on 831001-1104 & notice of violation GAGLIARDD. J E Region 4, Office of Director 83/11/28. GRIFFIN. J M Arkansas Power & Light Co 2pp 22332 167 24X Fiche: 50-313, 83/11/28, 8402220578
- --8402220589 Notice of violation from insp on 831001-1104
 * Region 4. Office of Director 83/11/28 ip 22332 169 24X
 Fichs 50-313,83/11/28,8402220578
- ---8402220576 IE Insp Repts 30-313/83-27 & 50-368/83-27 on 831001-1104 Noncompliance noted failure to complete job order form per procedural requirements & failure to maintain station battery operable, per Tech Specs CALLAN, L. J., CUMMINS, J. E., EVANB, C. A. Region 4, Office of Director. 83/11/22 12pp 22332 170 24X Fiche 50-313,83/11/28,8402220578
- 8402030208 Forwards IE Insp Repts 50-313/83-28 & 50-368/83-28 on E31024-28 No violations or deviations noted GAQLIARDO, J E Region 4, Office of Director 83/12/05 GRIFFIN. J M Arkansas Power & Light Co 2pp 22066 237 24X Fiche: 80-313,83/12/05,8402030208
- --8402030221 IE Insp Repts 50-313/83-28 & 50-368/83-28 on 831024-28 No violations or deviations noted Major areas inspected radiation program during refueling, including advanced planning & preparation, training & exposure control BAER, A. E. HOLLEY, M. J. MURRAY, B. Region 4, 0ffice of Director B3/11/30. 8pp. 22066, 239. 24X Fiche 50-313,83/12/05,8402030208
- \$402030370 Forwards IE Insp Repts 50-313/83-26 & 50-368/83-26 on B30919-23 & notice of deviation OAGLIARDD, J. E. Region 4, Office of Director B3/12/09 ORIFFIN, J. M. Arkansas Power & Light Co. 2pp 22066 036 24X Fichs. 50-313, 83/12/09, 8402030370
- --8402030376 Notice of deviation from insp on 830919-23, * Region 4. Office of Director 83/12/09 ip 22066,038 24X Fiche, 50-313,83/12/09,8402030370
- --B402030383 IE Insp Repts 50-313/83-26 & 50-368/83-26 on 830919-23
 Deviation noted 3 of 16 radiochemistry technicians
 lacked 2-yr experience criteria in radiochemistry.
 NICHOLAS.B J., HIBE.R., MURRAY.B Region 4, Défice of Director
 83/12/05 16pp 22066-039 24X Fiche.50-313.83/12/09.8402030370
- 840222033B Forwards IE Insp Repts 50-313/83-32 & 50-368/83-32 on 831105-30 No violations or deviations identified eAQLIARDD, JE Region 4. Office of Director 83/12/23 eAIFFIN.J.M. Arkanses Power & Light Co 2pp 22334: 176 24X Fiche 50-313.83/12/23.8402220338
- --B402220339 IE Insp Repts 50-313/83-32 & 50-368/83-32 on 831105-30. No violations or deviations identified Major areas inspected LERs, surveillance, maint, cold weather preparation & security guard force strike CALLAN, L.U., CUMMINS, J. E., JOHNSON, W. D. Region 4, Office of Director. 83/12/17 lipp. 22334.198, 24X Fiche 50-313,83/12/23,8402220338
- 8402220271 Forwards IE Insp Repts 50-313/83-31 & 50-348/83-31 on B31128-1202 No violations or deviations identified OAOLIARDO.J.E Region 4. Office of Director 84/01/10 ORIFFEN.J.H Arkansas Power & Light Co 2pp 22337 (19 24) Fiche 50-313,84/01/10,8402220271.

- --8402220280 IE Insp Repts 50-313/83-31 & 50-368/83-31 on 831128-1202 No violations or deviations identified Major areas inspected fire protection/prevention program & program implementation & compliance to 10CFR50. App R. Sections III J & III D MURPHY. M E . JOHNSON. W D Region 4. Office of Director 84/01/06 8pp 22337 121 24X Fiche 50-313.84/01/10.8402220271
- 8402010129 Forwards IE Insp Repts 50-313/83-29 & 50-368/83-29 on 831031-1104 No violations noted GAGLIARDO.JE Region 4. Office of Director 84/01/12 GRIFFIN.JM Arkansas Power & Light Co 2pp 22042 145 24X Fiche 50-313,84/01/12,8402010129
- --B402010132 IE Insp Repts 50-313/83-29 & 50-348/83-29 on 831031-1104 No violations noted Major areas inspected status of actions taken in response to emergency preparedness appraisal & routine insp findings
 HACKNEY.C A , BAIRD.J B , JOHNSON.W D Region 4, Office of Director 84/01/11 12pp 22042 167 24X Fiche 50-313,84/01/12.8402010129
- 8402220355 Forwards IE Insp Repts 50-313/83-30 & 50-368/83-30 on B31117-18 No violations or deviations noted GAGLIARDO, J E Region 4, Office of Director 84/01/18 GRIFFIN.J M Arkansas Power & Light Ca 2pp 22335 340 24X Fiche 50-313.84/01/18.8402220355
- ~-8402220367 lE Insp Repts 50-313/83-30 & 50-368/83-30 on 831117-18 No violations or deviations noted Major areas inspected security plan & proposed changes Details withheld (ref 10CFR/73 21)
 KELLY,J A , HALL,R E , JOHNSON,W D Region 4, Office of Director 84/01/17 ip 22335 342 24X Fiche 50-313,84/01/18.8402220355
- 84/01/17 ip 22335 342 24% Fiche 50-313,84/01/18,8402220355
- 8402220478 Ack receipt of B31222 ltr requesting extension to 840130 to respond to violations noted in IE Insp Repts 50-313/83-27 & 80-369/83-27 Extension granted GAGLIARDO.J E Region 4. Office of Director 84/01/18 GRIFFIN.J M Arkansas Power & Light Co 1p 22340 098 24X Fiche 50-313,84/01/18,8402220478
- --8402220488 Responds to NRC 831128 ltr re violations noted in IE Insp Repts 50-313/83-27 & 50-368/83-27 Requests response date be extended to 840130 MARSHALL.J R Arkansas Power & Light Co 83/12/22 GAGLIARDO, J E Division of Resident, Reactor Project & Engineering Programs 1p 22340 099 24X Fiche 50-313,84/01/18,8402220478
- 8402220383 Forwards IE Insp Repts 50-313/83-34 & 50-348/83-34 on 831201-31 & notices of violation & deviation GAGLIARDO, J E Region 4, Defice of Director 84/01/20 ORIFFIN, J M Arkansas Power & Light Co 2pp 22337 008 24: Fichs 50-313,84/01/20,8402220383
- --B4022203B7 Notice of violation from insp on 831201-31 * Region 4, Office of Director. 84/01/20 3pg 22337 010 24X Fiche 50-313, 84/01/20, 84022203B3
- --8402220399 Notice of deviation from insp on B31201-31 * Region 4, Office of Director B4/01/20 ip 22337,013 24X Fiche 50-313,84/01/20,8402820383
- --8402220406 IE Insp Repts 50-313/83-34 & 50-368/83-34 on 831201-31
 Noncompliance noted use of test equipment w/o current
 calibr & failure to follow procedures for recording of
 measuring & test equipment
 CALLAN, L J , CUMMINS, J E , JOHNBON, W D,
 Director 84/01/14 10pp 22337 014 24X Fichs 50-313,84/01/20,8402220383
- 8312120133 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/23 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche, 50-000, 84/01/25, 8312120153
- B401190016 IE Info Notice B4-07. "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post B30102) B4/02/07 Consolidated Edison Co of New York, Inc 119pp 22114·179 24X Fiche 50-000.84/02/03.8401190016
- B401190017 IE Bulletin B4-01, "Cracks in BWR Mark I Containment Vent Headers." Bvc list encl. DEYQUNO,R C. Director's Office Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp. 22177 156. 24X Fiche 50-000.84/02/03.8401190017

- 8402220468 Ack receipt of 831031 & 840118 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-318/803-21 & 50-388/803-21 GAGLIARDO, J E Region 4, Diffice of Director 80/02/08 GRIFFIN. J M Arkansas Power & Light Co 1p 22339 270 24X Fiche 50-313.84/02/08-8402220468
- --8402220476 Responds to NRC 831130 ltr re violations noted in IE Insp Repts 30-313/83-21 & 50-368/83-21 Corrective actions Procedure 1025 05. Rev 0. issued 831111 to require log book be maintained for battery maint activities MARSHALLJR Arkansas Power & Light Co 84/01/18 GAQLIARDOJJE Division of Resident. Project & Engineering Programs 2pp 22339 291 24X Fiche 50-313.84/02/08.8402220468
- 8401190041 IE Info Natice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Bys (10CFR50, App R)" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365 299 24X Fithe 50-000.84/02/13, 8401190041
- 8401190039 IE Info Notice 84*08. "10CFR50 7. 'Employee Protection '"
 Svc list encl
 JORDAN, Et. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- 8401170045 JE Info Natice 83-63.Suppl 1. "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list entl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc. 118pp 22366 142 24X Fiche 50-000.84/02/15,8401170045
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Int 116pp 22366 024 24X Fiche 50-000,84/02/21,8401190062
- 8402270192 Ack receipt of 840129 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-27 & 50-386/83-27 GAGLIARDO, J E Region 4. Office of Director 84/02/22 GRIFFIN-J M Arkansas Power & Light Co 1p 22391 281 24X Fiche 50-313,04/02/22.8402270192
- --8402270158 Responds to NRC 831128 ltr re violations noted in IE Insp Repts 90-313/83-27 & 50-368/83-27 Corrective actions maint personnel reinstructed on post-maint testing MARSHALLJR Arkansas Power & Light Cq 84/01/25 GAGLIARDD, J E Division of Resident, Reactor Project & Engineering Programs 2pp 22391-282 24X Fiche \$0-313,84/02/22.8402270152
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies"
 Svc list enct
 JORDAN EL Division of Emergency Preparedness & Enginearing
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc. 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- B401190057 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc. 120pp 22431 060 24% Fiche 50-000,84/02/27,8401190067
- BOCKET 50-315 DONALD C COOK NUCLEAR POWER PLANT, UNIT !

 F Security, medical, emergency & fire protection plans
- B402010116 Forwards exemption to certain schedular requirements of 10CRR50 Submittal of info to support exemption required within 60 days of receipt of ltr VAROA.S A. Operating Reactors Branch 1 B3/12/23 DDLAN, J Indiana & Michigan Power Co DDLAN, J American Electric Power Service Corp 3pp 22048 320 24X Fiche 50-315,83/12/23, B402010116
- -B402010121 Examption from schedular requirements of 10CFR30 48 & App R to 10CFR50 EISENHUT.D g Divition of Licensing 83/12/23 Indiana & Michigan Power Co 12pp 22048 323 24X Fiche 50-315.83/12/23, 8402010116
- -8402010124 Safety evaluation supporting exemption request from schedular requirements of 100FR50 48 & App R to 100FR50 a Division of Licensing 83/12/23 15pp 22048 335 24x Fiche 50-315,83/12/23,8402010116

- B402030464 Rev 2 to Emergency Plan Procedure PMP 2080 EPP.014, "Personnel Injury"
 * Indiana & Michigan Electric Co 84/01/20 8pp 22066 277 24X Fiche 50-315,84/01/20,8402030464
- 8402230008 Advises that NAC will not review emergency plant to delete privacy or proprietary info unless specifically requested by licensee.ger 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR HIGGINTON.D L. Operating Reactors Branch 1 84/02/07 DOLAN, J Indiana & Michigan Electric Co. DOLAN, J. American Electric Power Gervice Corp. 2pp. 22379 345 24X Fiche 50-315, 84/02/07, 8402230008
- 8402150334 Ack receipt of 840112 changes to modified amended security plan Changes acceptable per 10CFR30 54f(p), except for enci items For unacceptable items, previously approved plan must be followed Encl withheld (ref 10CFR73 21) AXELSON.W. Region 3, Office of Director 84/02/09 ALEXICH.M.P. Indiana & Michigan Electric Co. ALEXICH.M.P. American Electric Power Service Corp. 3pp. 22250 102 24X Fiche 50-315.84/02/09, 84/02/50334
- B402140122 Provides commitment dates re emergency operating procedures upgrade program Table 1 of AEP NRC 0773D modified to reflect dates Revised table encl ALEXICH.M P Indiana & Michigan Electric Co. 84/02/10 DENTON.H & Office of Nuclear Reactor Regulation, Director 2pp 2217 163 24X Fiche 50-315.84/02/10.8402140122
- 8402150321 Notifies of NRC acceptance of use of proposed course of fire for semiautomatic rifle described in F Arsenault 831212 ltr Program change should be submitted in guard training & qualification program per 100FR30 54(p) AXELSON.W L Region 3. OPFice of Director 84/02/10 ALEXICH.M P Indiana & Michigan Electric Co ALEXICH.M P American Electric Power Service Corp 2pp 22280 088 24X Fiche 50-315.84/02/10, 8402150321.
- 8402270356 Forwards IE Insp Repts 30-315/84-01 & 50-316/84-01 on B40123-27 No noncompliance identified, however, weaknesses summarized in encl re emergency operations facility need corrective action PAPERIELLO, C. J. Region 3, Office of Director 84/02/10 DOLAN, J. E. American Electric Power Service Corp. DDLAN, J. E. Indiana & Michigan Flectric Co. 3pp. 22391 202 24X Fiche 50-315, 84/02/10, 8402270354
- --B402270370 1E Insp Repts 50-315/84-01 & 50-316/84-01 on \$40123-27 No noncompliance, deficiencies or deviations identified Major areas inspected key functions of emergency preparedness expective SNELL, N. CHRIBTOFFER, 9. PHILLIPS, M. Region 3. Defice of Director 84/02/10 25pp 22391 205 24X Fiche 50-315,84/02/10,8402270356
- B402240041 Rev 0 to Emergency Plan Procedure PMP 2081 EPP. 016
 "Collection & Analysis of Liquid & Gaseous Samples"
 GLISSMAN.M., WELCH, 8 E Indiana & Michigan Power Co 84/02/15.
 5pp 22372 355 24X Fiche 50-315.84/02/15,8402240041
- B402220249 Rev 0 to Procedure PMP 2081 EPP.030, "Damage Control Procedure" WELCH: 8 E Indiana & Michigan Electric Co 84/02/17 Epp 22339 171 24X Fiche 50-315,84/02/17,8402220249
- 8402220252 Rev 2 to Procedure PMP 2081 EPP 026, "Use of Stable loding for Thyroid Blocking During Radiation Emergency."
 HELCH-8 E Indiana & Michigan Electric 0 84/02/17 8pp
 22337:032 24X Fiche 50-315,84/02/17,8402220282
- B402280461 Revised emergency implementing procedures, including Rev 2 to Procedure PMP2081. EPP. 021. "Activation & Operation of Operations Staging Area (08A) & Personnel Accountability "CARTEAUX.F Indiana & Michigan Electric Co. 84/02/22. 10pp. 22407 062 24X Fiche 50-315,84/02/22,8402280461.
- P Operating license stage documents & correspondence
- B312120027 Generic Ltr 83-39 to representatives of utils re voluntary survey of licensed operators, Svc list encl.
 LISENRUF.D © Division of Licensing B3/12/08 Commonwealth
 Edison Co 12pp. 22313 006 24% Fiche 50-000, 93/12/08, B312120029
- 8402030316 Rev 2 to Procedure PMP 2081 EPP.004. "Protective Action Guides & Protective Actions " Document issue record encl. * Indiana & Michigan Electric Co 84/01/20 22pp 22069:181 24X Fiche: 50-315.84/01/20.8402030316

- 8402070500 Responds to util B31127 ltr proposing mod to previous amend request re licensing status of operations superintendent Tech Bec Section 6 3 does not require mod based on NRC interpretation of ANSI NIB 1 VARDA.5 A Gperating Reactors Branch 1 84/01/26 DDLAN.J Indiana & Michigam Electric Co 3pp 22141 335 24X Fiche 50-315.84/01/26.8402070500
- 8402030210 Updates status of emergency operating procedures submitted 830802 Latest target & commitment dates provided on Table 1 Hestinghouse will complete procedure writeup by Jul 1984 ALEXICH.M P Indiana & Michigan Electric Co 84/01/30 DENTON.H R Diffice of Nuclear Reactor Regulation. Director 5pp 22067 330 24% Fice:30-315.84/01/30.8402030210
- 8402030472 Forwards request for clarification re Tech Spec 3 9 10, on reactor vessel water level requirements for operation in Mode 6 issued w/Amends 59 & 78 ALEXICH. M P Indiana & Michigan Electric Co 84/01/30 DENTON. H R Dffice of Nuclear Reactor Regulation, Director 2pp 22066 266 24X Fiche: 50-315.84/01/30,8402030472
- 8402010410 Generic Ltr 84-04 to all operating PWR licensees, CP holders applicants for CPs re safety avaluation of Hestinghouse topical rupts dealing w/elimination of postulated pipe breaks in PWR primary main loops Bvc list encl EISEMHUT.D 0 Division of Licensing 84/02/01 Consolidated Edison Co. of New York, Inc. 59pp 22177 087 24X Fiche 50-000.84/02/01.8402010410
- 8402070124 Responds to Varga 831219 ltr requesting schedule for additinform inadequate core cooling instrumentation (ICCI) systic ICCI status rept will be made available in Jul 1984 ALEXICH.M P. Indiana & Michigan Electric Co 84/02/03, DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22102 263 24X Fiche 50-315.84/02/03,8402070124
- 8402210484 Responds to 840120 proposed Tech Specs for RCS vents, in Tesponse to Generic Ltr 83-37 Recommended mod requested within 30 days.

 VARGA, S. A. Dyerating Reactors Branch 1 84/02/09 DOLAN, J. Indiana & Michigan Electric Co. DOLAN, J. American Electric Power Service Corp. 3pp. 22343 352 24X Fichs 50-315,84/02/09,84022/084
- G Inspection reports, IE Bulletins & correspondence
- 8312120153 IE Info Notice 84-06. "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl. JORDAN,E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co. of New York
- B402040347 Ack receipt of B40120 ltr informing NRC of steps taken in response to confirmatory action 1tr dtd B31117 KEPPLER.J O Region 3, Office of Director 84/02/02 DDLAN, J. E American Electric Power Service Corp DDLAN, J. E Indiana & Michigan Electric Co ip 22086 265. 24X Fiche 50-315,84/02/02,8402060369
- --8402060373 Responds to NRC 831117 confirmatory action 1tr Corrective actions nuclear safety design review committee & subcommittee charters & procedures revised to ensure all commitments by requirement met ALEXICH.M P Indiana & Michigan Electric Co 84/01/20 KEPPLER.J Q Region 3, Defice of Director 29pp. 22086 266 24x Fiche:50-315,84/02/02,8402060369
- B401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list and JORDAN,E.L Division of Emergancy Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp. 22114 179 24X Fiche. 50-000, 84/02/03, 8401190016
- 8401190017 IE Burlletin 84-01, "Cracks in BWR Mark I Containment Vent Haadsrs " Svc list encl DEYOUNG.R.C. Director's Office. Office of Inspection and Enfarcement B4/02/03 Consolidated Edison Co of New York, Inc 102pp. 22177: 156. 24X Fiche 50-000.84/02/03.8401190017
- 8402170279 Forwards IE Insp Repts 50-315/83-21 & 50-316/83-22 on BJ1211-840120 & notice of violation SHAFER: W D Region 3. Office of Director 84/02/03 DDLAN, J E American Electric Power Service Corp. DDLAN, J E. Indiana & Michigan Electric Co. 2pp. 22297 102 24X Ficha 50-315,84/02/03,8402170277.
- ~8402170302 Notice of violation from insp on 831211-840120 9HAFER.W.D Region 3, Office of Director. 84/02/02 ip 22277 104. 24X Ficher 50-315,84/02/03,8402170299

- --8402170313 IE Insp Repts 50-315/63-21 & 50-316/83-22 on 831211-840120 Noncompliance noted failure to submit special rept when Halon sys declared inoperable & not returned to svc within 14 days SWANSON E R , HELLER.J K , BOYD.D C Region 3. Office of Director 84/02/02 Spp 2227 105 24X Fiche 50-315,84/02/03.8402170297
- 8402270356 Forwards IE Insp Repts 50-315/84-01 & 50-316/84-01 on B40123-27 No noncompliance identified, however, weaknesses summarized in enci re emergency operations facility need corrective action PAPERIELLO,C J Region 3, Office of Director B4/02/10 DOLAN,J F American Electric Power Service Corp DOLAN,J E Indiana & Michigan Electric Co 3pp 22391 202 24X Fiche 50-315,84/02/10,8402270356
- --8402270370 IE Insp Repts 50-315/84-01 & 50-316/84-01 on 840123-27 No nuncompliance, deficiencies or deviations identified Major areas inspected key functions of emergency preparedness exercise

 SNELL, W., CHRISTOFFER, Q., PHILLIPS, M., Region 3, Office of Director 84/02/10 25pp 22391 205 24X Fiche 50-315,84/02/10,8402270336
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Bafe Shutdown Bys (10CFR30, App R)" Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York. Inc 124pp 22365 259 24X Fiche 50-000.84/02/13.8401190041
- B401190039 IE Info Notice B4-08, "10CFR50 7, `Employee Protection '"
 Svc list encl
 JGRDAN.E.L. Division of Emergency Preparedness & Engineering
 Response (Post B30103) B4/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24X Fiche 30-000,84/02/14,8401190039
- 8402220469 Ack receipt of B40127 ltr informing NRC of steps taken to correct noncompliances noted in IE Insp Repts 50-315/83-18 & 50-316/83-19
 8PE89ARD.R L Division of Emergency Preparedness & Operational Bupport 84/02/14 DDLAN.J E Indiana & Michigan Electric Co DDLAN.J E American Electric Power Service Corp ip 22339 293 24X Fiche 50-315,84/02/14
- --B402220474 Responds to NRC B31230 ltr re violations noted in IE Insp Repts 50-315/83-18 & 50-316/83-19 Corrective actions charters & procedures of nuclear safety & design review committee revised to resolve nine of 10 noncompliance items ALEXICH.M P Indiana & Michigan Electric Co 84/01/27 KEPPLER.J O Region 3. Office of Director 16pp 22337 274 24X Fiche 50-315,84/02/14,8402220467
- 8401190045 IE Info Notice 83-63. Suppl 1. "Potential Failures of Mestinghouse Type 9A-1 Differential Relays." Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York. Inc. 118pp 22366 142 24X Fiche. 50-000. 84/02/15, 8401190045
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Bat Below Manufacturer Recommended Valve " Bvc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24% Fiche 50-000.84/02/21,8401190062
- 8402290192 Forwards updated Apps A.B & C of regulatory performance improvement program describing mgt organization. QA activities & organization of GA/GC program ALEXIGH. M P Indiana & Michigan Electric Co 84/02/23 KEPPLER.J Q Region 3, Office of Director Sipp 22425 164 24X Fiche. 50-315,84/02/23,8402290192
- B401190066 IE Info Notice 84-11, "Training Program Deficiencies "
 Byc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B4/02/24 Consolidated Edison Co. of New
 York, Inc. 115pp 22430 304 24X Fiche 30-000,84/02/24,8401170066
- 8401190067 IE Info Notice 84-12, "Failure of Boft Seat Valve Beals"
 Svc list encl
 JORDANA E. Division of Emergency Preparedness & Engineering
 Response (Post 830103), 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431:060 24X Fiche 50-000,84/02/27,8401190067
- 8 Reportable occurrences, LERs & related correspondence
- 8402240201 FDIA request for LER 83-83.dtd 830908 ORABER, L D NUS Corp 84/01/23 Division of Rules and Records 1p 22393 225 24X Fiche 50-315.84/01/23.8402240201

- B402030303 LER B3-131/97L-0 on B31231 several fire hoses discovered not inspected per 3-yr surveillance test frequency Caused by multitudinous factors, including inadvertent interchange of hoses during fire drill Procedure revised W/840127 ltr MCREE E A , SMITH.W G Indiana & Michigan Electric Co B4/01/27 KEPPLER J G Region 3, Office of Director 3pp 22067 090 24X Fiche 50-315.84/01/27,8402030303
- 8402130280 NPDES noncompliance notification high iron concentration found in heating boiler blowdown Boaler inactivity believed to be cause SMITH, H G Indiana & Michigan Electric Co 84/0i/31 KEPPLER, J G Region 3, Office of Director 20p 22198 278 24X Fichs 50-315,84/0i/31,8402130280
- 8402240214 Responds to FDIA request for LER 83-82 dtd 830908 Forwards document Document also available in PDR FELTON J M Division of Rules and Records 84/02/03 GRABER. L D NUS Corp ip 22393 226 24X Fiche 50-315.84/02/03.8402240214
- --8402240215 LER B3-083/03L-0 on B30817, source range Vitron flux monitor N-32 became erratic & declared inoperable Caused by N-32 D8 attenautor set low Attenuator adjusted & returned to svc W/830908 ltr
 PALMER, SMITH, W. G. Indiana & Michigan Electric Co. 83/09/08 KEPPLER, J. G. Region 3. Office of Director 3pp. 22393 227 24X Fiche 50-315, 84/02/03.8402240214
- 8402220089 Updated ter 83-117/03X-1 on 831115, during startup, feedwater flow differential existed between steam generator 1 channels 1 & 2 Caused by instrument drift Transmitter recalibr W/840214 1tr PALMER.R A , SMITH.W 9 Indiana & Michigan Electric Co 84/02/14 KEPPLER.J 9 Region 3, Office of Director 2pp 22337 245 24X Fiche 50-315.84/02/14.8402220089
- 8402270398 LER 84-001-00 on 840123 channel 1 (NFP-220) control room flow indication dropped to approx 70% followed by automatic reactor trip Caused by leaking equalizing valve Equipment tasks researched W/840222 ltr
 ELIND.A A . SMITH.W G Indiana & Michigan Electric Co 84/02/22 App 22391 144 24% Fichs 50-315.84/02/22.8402270398
- DOCKET 50-316 DONALD C CODM NUCLEAR POWER PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8402010114 Forwards exemption to certain schedular requirements of 10CFR50 Submittal of info to support exemption required within 60 days of receipt of ltr VAROA.8 A Operating Reactors Branch 1 83/12/23 DOLAN.J Indiana & Michigan Power Co DOLAN.J American Electric Power Service Corp 3pp 22048 320 24X Fiche 50-315,83/12/23,8402010116
- --B402010121 Exemption from schedular requirements of 100FR50 48 & App R to 100FR50 EISENUT.D 0 Division of Licensing 83/12/23 Indiana & Michigan Power Co 12pp 22048 323 24X Fiche, 50-315, 83/12/23, 84/2010114
- --8402010124 Safety evaluation supporting exemption request from schedular requirements of 10CFR50 48 t App 8 to 10CFR50, # Division of Licensing 83/12/23 15pp 22048 335 24X Fiche 50-315, 83/12/23, 8402010116
- 8402030464 Rev 2 to Emergency Plan Procedure PMP 2080 EPP 014, "Personnel Injury"

 * Indiana & Michigan Electric Co 84/01/20 8pp 22066 277 24X Fiche 50-315,84/01/20,8402030464
- 8402230008 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by ilcense, per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR WIGGINTON.D L Operating Reactors Branch 1. 84/02/07 DDLAN, J Indiana & Michigan Electric Co. DDLAN, J. American Electric Power Service Corp 2pp 22379 345 24X Fiche 50-315,84/02/07,8402230008
- 8402150334 Ack receipt of 840112 changes to modified amended security plan. Changes acceptable per 10CFR90 54f(p), except for encitiems for unacceptable items, previously approved plan must be followed Encl Withheld (ref 10CFR73 21)

 AXELSON, W.L. Region 3, Office of Director 84/02/09 ALEXICH, M.P. Indiana & Michigan Electric Co. ALEXICH, M.P. American Electric Paucer Service Corp. 3pp. 22250 102 24X Fiche 50-315,84/02/09,8402150334

- B402140122 Provides commitment dates re emergency operating procedures upgrade program Table 1 of AEP NRC 0773D modified to replect dates Revised table encl ALEXICH, M P Indiana & Michigan Electric Co 84/02/10 DENTOM H & Office of Nuclear Reactor Regulation, Director 2pp 22219 163 24X Fiche 50-315,84/02/10,8402140122
- B402130321 Notifies of NRC acceptance of use of proposed course of fin for semi-automatic rifle described in F Arsenault 831212 ltr Program change should be submitted in guard training to qualification program per 10CFRSO 54(p)

 AXELSON.W. L. Region 3, Office of Director 64/02/10 ALEXICH, X.P. Indiana & Michigan Electric Co. ALEXICH, M.P. American Electric Pauer Service Corp. 2pp. 22250 089 24X Fiche 50-315,84/02/10, 8402150321
- 8402270356 Forwards IE Insp Repts 50-315/84-01 & 50-316/84-01 on 840123-27 No noncompliance identified however, weeknesses summarized in enci re emergency operations facility need corrective action PAPERIELLO, C. J. Region 3, Office of Director 84/02/10 DOLAN, J. American Electric Fouer Service Corp. 3pp. 22391 202 24X Fiche 50-315.84/02/10.8402270354
- ~-8402270370 IE Insp Repts 50-315/84-01 & 50-316/84-01 on 840123-27 No noncompilance, deficiencies or deviations identified Major areas inspected key functions of emergency preparedness exercise SNELL-W Region 3, Office of Director 84/02/10 25pp. 22391 205 24X Ficha 50-315.84/02/10.8402270356
- 8408240041 Rev O to Emergency Plan Procedure FMP 2081 EPP 016 "Collection & Analysis of Liquid & Gaseous Samples." CLISEMAN.M. WELCH, 8 E Indiana & Michigan Power Co 84/02/15 5pp 22372 355 24X Fiche 50-315.84/02/15.8402240041
- 8402220249 Rev O to Procedure PMP 2081 EPP 030, "Damage Control Procedure " WELCH: 8 E Indiana & Michigan Electric Co. 84/02/17 Spp 22337 171 24X Fiche 50-315,84/02/17,8402220249
- B40B220252 Rev 2 to Procedure PMP 2081 EPP 026. "Use of Stable Inding for Thyroid Blocking During Radiation Emergency " WELCH. S E Indiana & Michigan Electric Co B4/02/17 Bpp 22337 032 24% Fiche 50-315.84/02/17.8402220252
- 8402280461 Revised emergency implementing procedures, including Rsv 2 to Procedure PMP2081 EPP 021, "Activation & Operation of Operations Staging Area (OSA) & Personnel Accountability "CARTEAUX, P Indiana & Michigan Electric Co. 84/02/22, 10pp 22407.062 24X Fiche 50-315.84/02/22,8402280461
- P Operating license stage documents & correspondence
- 8312120029 Generic Ltr 83-39 to representatives of utils re volunting survey of licensed operators 8vc list encl EISENHUT, D G Division of Licensing 83/12/08. Commonwealth Edison Co 12pp 22313 004 24X Fiche, 50-000, 83/12/08, 8312120029
- 8408030316 Rev 2 to Procedure PMP 2081 EPP 004. "Protective Action Ouides & Protective Actions " Document issue record encl. * Indiana & Michigan Electric Co 84/01/20. 22pp 22069:181 24 Fiche: 50-315.84/01/20.8402030316
- 8402070500 Responds to util 831129 ltr proposing mod to previous early request re licensing status of operations superintendent. Tech Spec Section 6 3 does not require mod based on NRC interpretation of ANSI N18 1 VARQA 8 A Operating Reactors Brench 1, 84/01/26, DOLAN, J Indiana & Michigan Electric Co Spp. 22141 335 24% Fiche 50-315,84/01/26,8402070500
- 8402030210 Updates status of emergency operating procedures subsitied 630802 Latest target & commitment dates provided on Table 1 Heatinghouse will complete procedure writeup by Jul 1984 ALEXICH.M P Indiana & Michigan Electric Co 84/01/30 DENTON.R.F Office of Nuclear Reactor Regulation. Director 5pp. 22067:330 24X Fiche 50-315.84/01/30.8402030210
- 8402030472 Forwards request for clarification to Tech Spec 3 9 10. on reactor vessel water level requirements for operation in Mode & issued w/Amends 59 & 78 ALEXICH, M P Indiana & Michigan Electric Co 84/01/30 DENTON. Uffice of Nuclear Reactor Regulation, Director, 2pp. 22064 266 24X Fiche 30-315,84/01/30,8402030472.

- MORDIO410 Generic Ltr 84-04 to all operating PWR licensees, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops 8vc list encl EISENHUT, D 0 Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc. 59pp 22177 087 24X Edison Co of New York, Inc 59 Fiche 50-000,84/02/01,8402010410
- 402070124 Responds to Varga 831219 ltr requesting schedule for addline or inadequate core cooling instrumentation (ICCI) sys ICCI status rept will be made available in Jul 1984 ALEXICH.M P Indiana & Michigan Electric Co 84/02/03 DENTON.H Bffice of Nuclear Reactor Regulation. Director 2pp 22102 243 24X Fiche 50-315.84/02/03.8402070124
- 402210484 Responds to B40120 proposed Tech Specs for RCS vents, in response to Generic Ltr B3-37 Recommended mod requested within 30 days.

 VAROA: B A Operating Reactors Branch 1 84/02/09 DOLAN, J Indiana & Michigan Electric Co DOLAN, J American Electric Power Bervice Corp 3pp 22343 352 24X Fiche 50-315,84/02/09, B402210484
- 402170189 Notifies that Class III fee due for review of data re ECCS sump performance. No add1 fee assessed for subsequent deletion, per 831215 request.
 MILLER, M.O. License Fee Management Branch 84/02/10 DULAN, J.E. American Electric Power Service Corp. 1p. 22313-273 24X American Electric Power Service Corp Fiche: 50-316, 84/02/10, 8402170187
- Inspection reports: IE Bulletins & correspondence
- 312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Svc list encl PUMPS, " SV JORDAN, E L JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Past 830103) 84/01/25 Consolidated Edison Co. of New Yark, Inc. 120pp. 22058 001 24X Fiche 50-000,84/01/25,8312120153
- 102040349 Ack receipt of 840120 ltr informing NRC of steps taken in response to confirmatory action ltr dtd 831117 KEPPLER.J Q. Region 3. Office of Director 84/02/02 DOLAN.J E American Electric Power Bervice Corp DOLAN.J E Indiana & Michig. Electric Co 1p. 22086 265 24X Fiche 50-315.84/02/02.8402040349
- 8402060373 Responds to NRC 831117 confirmatory action ltr Corrective actions; nuclear safety design review committee & subcommittee charters & procedures revised to ensure all committee the requirement met.

 ALEXICH, M.P. Indiana & Michigan Electric Co 84/01/20
 KEPPLER, J. & Region 3, Office of Director 27pp 22086 266, 24X
 Fiche 50-315,84/02/02,8402060369
- .01190016 IE Info Notice 84-07, "Design-Besis Threat & Review of Vehicular Excess Controls " Syc list and JOROAN, E.L. Division of Emergency Prepayedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co. of New York, Inc. 119pp 22114,179, 24X Fiche 50-000,84/02/03,8401190016
- 01170017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vant 01190017 IE Bulletin 84-01, "Greeks in John Bulletin 84-01, "Greeks in John Bulletin 84-01, "Greeks in John Bulletin 85-01 Inspection and Enforcement. 84/02/03. Consolidated Edison Co. of New York, Inc 102pp. 22177-156 24X Fiche. 50-000, 84/02/03, 8401190017
- 02170299 Forwards IE Insp Repts 50-315/83-21 & 50-316/83-22 on 838211-840120 & notice of viplation SMAPER, M.D. Region 3, Office of Director 84/02/03 DOLAN, J E Ambrican Electric Power Service Corp DOLAN, J E Indiana & Michig Electric Co 2pp. 22297-102 24X Fichs. 50-315, 84/02/03, 840217029 Indiana & Michigan
- B402170302 Notice of violation from insp on 831211-840120 SHAFER, W D. Region 3, Office of Director. 84/02/02 22277:104. 24% Fiche. 50-315, 84/02/03, 8402170279
- 3402179313 IE Insp Repts 50-315/83-21 & 50-316/83-22 on 831211-840120 Noncompliance noted failure to submit special rept when Halon sys declared inoperable & not returned to syc within
 - 14 days. 84M980N.E.R., HELLER, J.K., 80YD, D.C. Region 3, Office of Director 84/02/02 5pp. 22297.105. 24X Fiche 50-315.84/02/03.8402170299
- 2270356 Forwards IE Insp Repts 50-315/84-01 & 50-316/84-01 on 340123-27. No noncompliance identified however, weaknesses tuawartist in enci re emergency operations facility need corrective action "APERIELLO,C.J. Region 3, Office of Director 84/02/10 DOLAN, J. American Electric Power Service Corp DOLAN, J. E. Indiana & Stockholm Electric Co. Spp. 22391 202. 24X Fichs. 50-315, 84/02/10, 3402270356.

- --8402270370 IE Insp Repts 50-315/B4-01 & 50-316/B4-01 on B40123-27 No noncompliance, deficiencies or deviations identified Major areas inspected key functions of emergency preparedness exercise SNELL.W. CHRISTOFFER.G. PHILLIPS, M. Region 3, Office of Director 84/02/10 25pp 22391 205 24% Fiche 50-315,84/02/10.
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Bafe Shutdown Sys (10CFR50, App R) " Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365 259 24X Fiche 30-000,84/02/13,8401190041
- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '" Sor list encl
 Sor list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 84/02/14 Consolidated Edison Co of New
 York, Inc 113pp 22365 141 24x Fiche 50-000,84/02/14,8401190039
- 8402220469 Ack receipt of 840127 ltr informing NRC of steps taken to correct noncompliances noted in IE Inap Repts 50-315/83-18 & 50-316/83-19 BPEBBARD,R L Division of Emergency Preparedness & Operational Support 84/02/14 BOLAN.J E Indiana & Michigan Electric Co BOLAN.J E American Electric Power Service Corp 1p 22337 293 24X Fiche 50-315,84/02/14,8402220469
- --B402220474 Responds to NRC 831230 ltr re violations noted in IE Insp Repts 50-315/83-18 & 30-316/83-19 Corrective actions charters & procedures of nuclear safety & design review committee revised to resolve nine of 10 noncompliance items ALEXICH.M P Indiana & Michigan Electric Co B4/01/27 KEPPLER.J O Region 3. Office of Director 16pp 22339 294 243 Fiche 50-315,84/02/14.8402220449 22339 294 24X
- B401190045 IE Info Notice 83-63. Buppl 1. "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Evc list encl JDRDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc 118pp 22366 142 24X Fiche 50-000,84/02/15,8401190045
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Buitches But Below Manufacturer Recommended Value " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000,84/02/21,8401190062
- 8402270172 Forwards updated Apps A.B & C of regulatory performance improvement program describing mpt organization. QA activities & organization of QA/QC program ALEXICH, M P Indiana & Michigan Electric Co 84/02/23 KEPPLER.J Q Region 3. Office of Director 51pp 22425 144 24X Fichs 50-315,84/02/23,8402270172
- 8401170066 IE Info Notice 84-11, "Training Program Deficiencies" HOLLYOOSO IE Into Ruther Co. ...
 Byc list encl
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co. of New
 York, Inc. 115pp 22430 304 24X Fiche 50-000.84/02/24,8401190066
- 8401170067 IE Info Notice 84-12. "Failure of Soft Seat Valve Seals " 901490067 IE Info Novice C. . . . Byc list encl. JORDAN E L Division of Emergency Preparedness & Engingering Response (Post B30103) B4/02/27 Consolidated Edison Co of New York, Inc. 120pp 22431 060 24X Fiche 30-000,84/02/27,8401190067
- 8 Reportable occurrences, LERs & related correspondence
- B402030240 LER 83-126/99L-0 on 831231, several fire hoses discovered not inspected per 3-yr surveillance test frequency Caused by multiple factors, including inadvertent interchange of hoses during fire drills W/840127 ltr
 MDR8E.E A . 8MITH.W 9 Indiana & Michigan Electric Co B4/01/27
 KEPPLER.J 0 Region 3 Office of Director 3pp 22047:183 24X iche 50-316,84/01/27,8402030240
- 8402130280 NPDES noncompliance notification, high iron concentration found in heating boiler blowdown Boiler inactivity beliaved to be cause SMITH. H G Indiana & Michigan Electric Co 84/01/31 KEPPLER, J Region 3, Office of Director 2pp. 22198 278 24X Fiche 50-315,84/01/31,8402130280 84/01/31 KEPPLER, J 9
- 8402220065 LER 84-001-00 on 840117, boron injection tank diluted by ROZZZZOOSO LEM BA-001-00 on H4011/, baron injection tank diffusion primary water after equipment clearance permit released & sys realigned Caused by open untagged valve Individual responsible for restoration forms notified W/H40216 ltr KRAUSE, Dr , BMITH, W, G Indiana & Michigan Electric Co Spp. 22339, 246 24X Fiche 50-316, 84/02/16, 8402220065 84/02/16

- DOCKET 50-317 CALVERY CLIFFS NUCLEAR POWER PLANT, UNIT 1 F Security, medical, emergency & fire protection plans
- 8402130480 Informs that R Eberly of NRC will be at site on 840130 to attend general orientation training Parts I & II & tour parts of plant in connection w/ongoing fire protection DAFFE.D H Operating Reactors Branch 3 84/01/19 RUSSELL.L Baltimore Gas & Electric Co 2pp 22214 357 24X Fiche 50-317.84/01/19.8402130480
- B40209021A Notification of Significant Licensee Meeting 84-10 on 84020B w/util in Lusby, MD to discuss leasons learned from previous 10CFR50. App R safe shutdown insp PULLANI.S Region 1. Office of Director 84/01/25 DIRCKS, W J Office of the Executive Director for Operations 8TELLO.V Regional Operations & Generic Requirements DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 3pp 22:88 341 24X Fiche 50-317,84/01/25,8402090216
- 8402160457 Rev 0 to emergency response plan implementation Procedure 5 3 1 & Rev 10, Change 2, new Attachment 2 to emergency response plan implementation Procedure 4 1 17 W/840210 & 13 transmittal & raceipt ltrs
 USLV Baltimore 98s & Electric Co. 84/02/01 10pp 22268 294 24X Fiche 50-317,84/02/01,8402160457
- 8402160577 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, sper 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR MILLER, J R Operating Reactors Branch 3 84/02/06 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 22302 120 24X Fiche 50-317.84/02/06.8402160577
- 8402150156 Forwards request for exemption from 10CFR90, App E. Section IV F 1 a re 840911 electise Local & state govt agencies will not be represented in exercise W/o exemption request LUNDVALL. A E Baltimore Cas & Electric Co 84/02/09 MILLER. J R Operating Reactors Branch 3 1p 22249 195 24X Fiche 50-317,84/02/09.8402/50156
- B402270330 Advises that portions of Rev 13 to security plan, submitted on 830826, unacceptable as is Corrected pages due in 30 days Encl withheld (ref 100FR73 21)

 MARTINIT T Bivision of Engineering & Technical Programs B4/02/23

 BOWNAKER,N J Baltimore Gas & Electric Co 4pp 22389 305 24X Fiche 50-317,84/02/23,8402270330
- P Operating license stage documents & correspondence
- 8402130480 Informs that R Eberly of NRC will be at site on 840130 to attend general orientation training Parts I & II & tour parts of plant in connection w/angoing fire protection review
 JAFFELD H Operating Reactors Branch 3 84/01/19 RUSSELL,L
 Baltimore Gas & Electric Co 2pp 22214 357 24X
 Fiche 50-317,64/01/19,8402130480
- 8402130274 Forwards request for add1 info to complete review of C-E extended burnup rept CENFD-269 Info should be provided within 70 days
 MILLER.J R Operating Reactors Branch 3 84/01/24 LUNDVALL.A E. Baltimore Cas & Electric Co 4pp 22216 199, 24X
 Fiche 20-317.84/01/24.8402130274
- B402060234 Application to amend Licenses DPR-53 & DPR-69, revising Tech Specs to allow operation of hydrogen sample & hydrogen sample return containment isolation valves during testing under administrative control LUNDVALL.A E Baltimore Gas & Electric Cg 84/01/27 MILLER. Operating Reactors Branch 3 4pp 22087, 219 24X Ficher 50-317,84/01/27,8402040234 84/01/27 MILLER, J R
- --840205023B Proposed changes to Tech Specs allowing operation of hydrogen sample & hydrogen sample return containment isolation valves during testing under administrative - awasamore Gas & Electric Co 84/01/27 31pp 22087, 223 24X Fiche 50-317, 84/01/27, 8402040234
- B402010410 Generic Ltr 84-04 to all operating PMR licensees, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PMR primary main loops Svc list encl EISENHUT, D © Division of Licensing 84/02/01 Consolidated Edison Co of New York Inc 59pp 22177 087 24X Fiche 50-000.84/02/01.8402010410

- 8402080272 Requests relief from NRC 830316 order re add1 refueling cycle for installation of noble gas steam effluent monitor, per NUREG-0737, Item II F i 1 Feasibility of procuring & installing replacement monitor being investigated LUNDVALLA E Baltimore Gas & Electric Co 84/02/03 MILLER, J R Operating Reactors Branch 3 3pp 22131 282 24X Fiche 50-317,84/02/03,8402080272
- 8402100006 Responds to Generic Ltr 84-01 re use of terms important to safety & safety-related Further discussion will be through participation in util safety classification group LUNDVALL, A E Baltimore Gas & Electric Co 84/02/03 TAYLOR, J.M Director's Office, Office of Inspection and Enforcement 1p 22182 156 24X Fiche 50-317,84/02/03,8402100006
- B402170015 Forwards notice of consideration of issuance of amends to Licenses DPR-53 & DPR-69 & proposed NBHC determination & opportunity for hearing re control element assembly position indicator channels

 JAFFE.D H Operating Reactors Branch 3 84/02/09, LUNDVALL.A E Baltimore Oas & Electric Co 1p 22319 129 24X

 Fiche 50-317.84/02/09.8402170015
- --B40217001B Notice of consideration of issuance of amends to Licenses DPR-53 & DPR-69 & proposed NBHC determination & opportunity for hearing MILLER, J.R. Operating Reactors Branch 3 84/02/09 9pp 22319 130 24X Fiche 50-317,84/02/09,8402170015
- 8402270628 Forwards prioritization evaluation approving NRR actions necessary to resulve Generic Issue 36, "Loss of Svc Water (Calvert Cliffs Unit 1) " Evaluation will be incorporated (Calvert Cliffs Unit 1) " Evaluation will be incorporated into NUREG-0933 DENTON.H R GFFice of Nuclear Reactor Regulation, Director. 84/02/15 MATT6ON,R J Division of Systems Integration (post 811005) 18pp 22412 339 24X Fiche 50-317,84/02/15,8402270428
- 8402270454 Forwards Class III & I licensing fees, per 840203 request Mod of order re schedule for completion of NUREG-0737, Item II F 1 concering noble gas steam Operating Reactors Branch 3 1p Fiche: 50-317, 84/02/16, 8402270454.
- O Inspection reports, IE Bulletins & correspondence
- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN.E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120553.
- 8402080330 Forwards IE Insp Repts 50-317/83-34 & 50-318/83-34 on 83130-1205 No violations noted MARTIN.T.T Division of Engineering & Technical Programs 84/01/25 LUNDVALL, A E Baltimore Oas & Electric Co 2pp 22130, 270 R4X Fiche 50-317.84/01/25.8402080330
- --8402080333 IE Insp Repts 50-317/83-34 & 50-318/83-34 on 831130-1205 Ne noncompliance noted Major areas inspected startup physics testing program & precritical & post-critical tests following Unit i Cycle 7 refueling WEN.P C , BETTENHAUSEN.L Region 1, Office of Director 84/01/25 10pp. 22130,272 24X Fiche 50-317,84/01/25,8402080330.
- 8402070216 Notification of Significant Licenses Meeting 84-10 on 840208 w/util in Lusby, MD to discuss leasons learned from previous 10CFR50.App R safe shutdown insp PULLANI.8 Region 1. Office of Director 84/01/25 DIRCKS, W J Office of the Executive Director for Operations STELLO, V Regionat Operations & Generic Requirements DEYOUNO, R. C Director's Office. Office of Inspection and Enforcement 3pp 22188 341 24% Ficha 50-317.84/01/25.8402090216.
- 8402070361 Forwards IE Insp Repts 50-317/83-32 & 50-318/83-32 on 831114-18 No violations noted MARTIN T T Division of Engineering & Technical Programs. 84/01/27. LUNDVALL, A E Baltimore Gas & Electric Co. 2pp 22161:102 24x Fiche. 50-317.84/01/27.8402090361
- -8402090374 IE Insp Repts 50-317/83-32 & 50-318/83-32 on 831114-18 % noncompliance noted Major areas inspected testing program, precritical test, low power physics tests & power ascension tests WEN.P C , BETTENHAUSEN, L Region 1, Office of Director. 84/01/24 10pp 22161 104 24x Fiche 50-317,84/01/27,8402090361
- 8402160331 Forwards IE Insp Repts 50-317/83-14 & 50-318/83-14 on 831114-18. No violations observed MARTIN.T T Division of Engineering & Technical Programs. 84/02/01. LUNDVALL, A E Baltimore Cas & Electric Co 2pp 22268-335 24x Fiche 50-317-84/02/01,8402160331

- --8402160337 IE Imap Repts 50-317/83-14 & 50-318/83-14 on 831114-18 No violations identified Major areas inspected inservice inspactivities, licensee response to IE Bulletin 80-08 & licensee actions on previous insp findings MCBREARTY, RA , DURR, J P Region 1, Office of Director 84/01/30 5pp 22288 337. 24% Fiche 50-317,84/02/01,8402160331
- 8401190016 IE Info Notice 84-07, "Design-Dasis Threat & Review of Vehicular Excess Controls " Svc list entl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 117pp 22114 179 24X Fiche 50-000,84/02/03.8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEYOUNO, R. C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177:156 24x Fiche 50-000.84/02/03.8401190017
- B402240128 Forwards IE Insp Repts 50-317/83-31 & 50-318/83-31 on B3fil6-123f & notice of violation STAROBTER(I),R. Division of Project & Resident Programs 84/02/07 LUNDVALL,A E Baltimore Gas & Electric Co 2pp 22375 088 24X Fichs.50-317,84/02/07,8402240128
- --8402240133 Notice of violation from insp on 831114-1231 * Region 1, Office of Director 84/02/07 2pp 22375 090 24X Fiche 50-317.84/02/07.8402240128
- --8402240139 IE Insp Repts 50-317/83-31 & 50-318/83-31 on 831116-1231 Violations noted; initiation of alternate means of auxiliary featwater sys not established & sufficient measures not taken to prevent recurrence of excessive pressure ARCHITZEL, R. E., TRIMBLE, D. C., ELSASSER, T. C. Region 1, Office of Director 84/02/02 25pp 22375-092 24X Fiche 50-317,84/02/07,8402240123
- B402140326 Ack receipt of 840119 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/83-27 & 50-318/83-27 .

 ### Steps Repts 50-317/83-27 & 50-317/83-27 & 64/02/08
 #### LUNDYALL.A E Baltimore Gas & Electric Co 2pp. 22221 042 24X
 #### Ficha: 50-317, 64/02/08. 8402140326
- --840214032? Responds to NRC 831219 ltr re violations noted in IE Insp Repts 50-317/83-29 & 50-318/83-27 Corrective actions: sys implemented to better track accumulated work hours 1.WNDVALL, A. E. Beltimore Gas & Electric Go. 84/01/19 MARTIN:T T Division of Engineering & Technical Programs 2pp, 22221.044 24X Fiche 50-317.84/02/08.8402140326
- 840119004: IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Bafe Shutdown Sys (100FRSO App R) " Syc list encl.

 JORDAN: E. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc. 124pp. 22365-259 24X Fiche 30-000.84/02/13,8401190041
- 8402290287 Forwards IE Insp Repts 50-317/84-02 & 50-318/84-02 on 840109-13. No yielations observed MARTIN.T T. Division of Engineering & Technical Programs 84/02/13 SLAMPAULL.A E. Baltimore Oas & Electric Co 2pp. 22427 175 24X Fichs: 50-317/84/02/13.8402290287
- --8402290294 IE Insp Repts 50-317/84-02 & 50-318/84-02 on 840109-13 No violations identified Major areas inspected.licensee actions on previously identified items.high radiation area controls & in-plant radiation protection program CDLLINS.J., SHANBAKY.M.M. Ragion 1, Office of Director. 84/02/06 5pp. 22427,177 24X Fiche 50-317,84/02/13,8402290287
- 8401170039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection.'"
 Syc list encl
 JORDAN,E.L. Division of Emergency Preparedness & Engineering
 Résponse (Post 830103), 84/02/14, Consolidated Edison Co. of New
 York: Inc. 115pp 28365-141, 24X Fiche-50-000,84/02/14,8401170037
- B401170045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Mastinghouse Type 8A-1 Differential Relays" Bvc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp. 22366 142, 24X Fiche. 50-000, 84/02/15, 8401170045
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Bet Below Manufacturer Recommended Value." Svc list encl. JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21. Consolidated Edison Co of New York, Inc. 116pp. 22366.024, R4X Fiche. 50-000.84/02/21, 8401190062

- 8401190066 IC Info Notice 84-11. "Training Program Deficiencies "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,6401190066
- B401190047 IE Info Notice B4-12, "Failure of Soft Seat Valve Seals "
 Svc list encl
 JURDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 630103) B4/02/27 Consolidated Edison Co of New
 York, Int 120pp 22431 060 24X Fishe 50-000, 84/02/27, 8401190067
- R Periodic operating reports & related correspondence
- 8402270408 Number of personnel & man-rem by work & job function, 1983 W/840213 ltr TIERNAN.J A Baltimore Gas & Electric Co 83/12/31 MURLEY, T E Region i, Office of Director 3pp 22391 i49 24X Fiche 50-317.83/12/31.8402270408
- 8402220440 Monthly operating repts for Jan 1984 W/840213 ltr LUTITU.E M Baltimore Gas & Electric Co 84/01/31 13pp 22340 007 24% Fiche 50-317.84/01/31.8402220440
- B Reportable occurrences, LERs & related correspondence
- B402220154 Responds to FOIA request that 146 LERs be placed in PDR Forwards LERs listed on app Documents also available in PDR Remaining LERs where either canceled or not issued FELTON. J M Division of Rules and Records B3/11/30 JEFFERSON. 6 A Affiliation Not Assigned 2pp 22380 052 24X Fiche 50-000.8311/30.8402220154
- B4021404B6 Responds to FOIA request for 16 categories of documents re degradation of bolts, nuts & studs at PWRs & BWRs Forwards App A documents App A & B documents available in PDR FELTON, J M Division of Rules and Records 83/12/02 BELL, N Nuclear Information & Resource Service 4pp 22257 003 24X Fiche 50-000,83/12/02,8402140486
- --B402140524 Forwards LER 80-010 & LER 81-002/01 re stud corrosien * NRC - No Detailed Affiliation Given 81/05/15 NRC - No Detailed Affiliation Given ip 22258 039 24X Fiche 50-000, 83/12/02:8402140486
- 8402060123 RD during Nov 1983, oyster samples analyzed showed Ag-110m concentration of greater than 9 pCi/kg (net) Caused by tendency of oysters to bloconcentrate environ silver No threat to public health & safety noted FUHRMAN, 0 R Baltimore Oas & Electric Co 83/12/22 Region 1, Dffice of Director 2pp 22089 114 24X Fiche 50-317,83/12/22, 8402060123
- 8402060401 LER 83-072/01T-0 on 831222, reactor protection sys channels A & C for reactor coolant flow inoperable Caused by erratic indication & procedure inadequacy Transmitter repaired & new flow setpoint inserted W/840105 ltr PORTER, R J , SNYDER, J A , RUBSELL, L B. Baltimore Gas & Electric Co 84/01/05 MURLEY, T E Region i, Office of Director 3pp R2086 177 24X Fiche 50-317,84/01/05.8402060401
- 8402280144 Updated LER 83-032/03X-2 on 830523, containment isolation sys B logic module would not actuate Caused by defective electronic logic components U3 & U5 Module replaced W/840111 ltr.
 BABSO,L F, RUSBELL,L B Baltimore Gas & Electric Co 84/01/11 MURLEY,T E Region 1, Office of Director 2pp 22400.280 24X Fiche 50-317,84/01/11.8402280144
- 8402280051 LER 83-074/03L-0 on 831213; flow lost in saltwater subsystem Caused by operator failure to verify proper operation of 4 kV manual disconnect Standing instruction issued W/840112 ltr LOHR.JF. RUSSELL.L. B Baltimore Gas & Electric Co 84/01/12 MURLEY.T E Region 1, Dffice of Director 3pp. 22400 282 24X Fiche.50-317; 84/01/12, 8402280051.
- 8402030360 Updated LER 83-041/01X-1.on 830803.ECCS pump room exhaust ventilation sys charcoal filter inlet damper would not open when bypass damper shut Caused by incorrect connection of charcoal filter damper actuators W/840113 ltr
 JUNOE.M.A B . PAVIS.O S . RUSSEL.L B Baltimore Qas & Electric Co 84/01/13 MURLEY.T E Region I. Office of Director 4pp 22069 163 24X Fiche 50-317.84/01/13.8402030360
- 8409270285 Nonroutine radiological environ operating rept re review of observed levels of Ag-iiOm in oyster samples collected during 1983 Caused by tendency of oysters to highly bioconcentrate environ silver FUHRMAN, 9 R. Baltimore Gas & Electric Co. 84/01/17 Region 1. Office of Director. Spp 22391 308 24X Fiche 50-317,84/01/17,8409270285

- 8402080349 Updated LER 83-018/03x-1 on 830408.emergancy diesel generator 12 failed to start.Caused by governor adjustments allowing fuel oil from header to drain to clean oil drip tank Maint instructions revised W/840119 1tr
 JUNGE,M A. RUSSELL, B. ALLENAR R. Baltimore Gas & Electric Co. 84/01/18 MARLEY,T.E. Region 1. Office of Director 2pp 22130 251 24X Fiche 50-317,84/01/18.8402080349
- 8402020132 LER 83-069/03L-0 on B3122L during test of reactor trip circuit breaker (TCB) undervoltage (UV) devices response time of TCB 2 & 4 UV trip devices found too slow Caused by setpoint drift UV devices replaced W/840119 ltr PIERINGER,P. CRUNKLETON, J. RUSSELL,L B Baltimore Gas & Electric Co 84/01/19 MURLEY,T E Region 1. Office of Director 3pg 22054 175 24X Fiche 50-317,84/01/19.8402020132
- 840/2080351 Updated LER 83-064/03X-1 on 831103 during shutdown operation, HPSI balance test revealed individual injection leg flow rates outside allowable limits Maint procedures will be revised W/840124 ltr PIERINGER, P. 8ASSD, L. RUSSELL, L. B. Baltimore 0a & Electric Co 84/01/24 MURLEY, T. E. Region I. Office of Director 3pp 22131 210 24X Fiche 50-317,84/01/24,8402080351
- B4020B0397 Updated LER 83-043/01X-1 on 830804, reed switch position indication lost for all control element assemblies (CEA) Caused by short in CEA 32 reed stack position transmitter Transmitter replaced WA40126 ltr
 JUNDE, N A : RAYNOR. J W : RUSSELL, L B Baltimore Oas & Electric Co 84/01/25 HURLEY. T & Region 1. Office of Director 3pp. 22131 007 24X Fiche 50-317.84/01/25.8402080397
- B402070372 LER B3-076/03L-0 on B31230.auxiliary feedwater pump 13 outboard pump bearing drain found plugged w/metal filings, indicating bearing damage Caused by obstruction in bearing housing oil return passage distruction removed W/840126 itr LOHR. J F. FARRELL.E V. RUSSELL.L B Baltimore Cas & Electric Co 84/01/26 MURLEY,T E Region I. Office of Director. 2pp 22099 205 24X Fiche 50-317.84/01/26.8402070372
- 8402080266 Updated LER 83-086/03X-1 on 830521 erratic metrascope indication for control element assembly 18 & metrascope associated alarms identified failed red switch position stack. Cause undetermined Repairs made W/840126 ltr PIERINGER,P A , RAYNOR,J W . RUSBELL-L B Baltimore Cas & Electric Co 84/01/24 MURLEY.T E Region I. Optice of Director 3pp 22131 238 24X Fiche 50-317,84/01/26.8402080266.
- 8402080339 Updated LER 63-047/03X-1 on 830822, control room air conditioner compressor 12 failed to run w/start signal Caused by compressor trip due to high pressure High pressure switch reset W/840126 ltr
 JUNGE, N A . L'HEUREUX, R W . RUSSELL. L. B. Baltimore Gas & Electric Co 84/01/26 AURILEY, TE Region 1, Office of Director 2pp 22130 263 24% Fiche 50-317.84/01/26,8402080339
- B4020B0353 Updated LER 83-036/01X-1 on B30618, reef switch position indication lost for all control element assemblies (CEA) Caused by short on CEA 56 read stack position transmitter Transmitter replaced W/840128 ltr PiERINGER, P.A. RAYNOR, J. W. AUSSELL, L. B. Saltimore Gas & Electric Co. 84/01/26 MURLEY, T.E. Region 1, Office of Director, 3pp 22131 207 24X Fiche 50-317, 84/01/26, 8402080353
- 8402080373 Updated LER 83-008/01X-1.on 830205, control element assembly 26 reed switch position indication practic & declared inoperable Caused by failure of reed stack position transmitter Transmitter replaced W/840126 ltr JUNGE.M A. RAYNOR.J. W. RUSSELL, L. B. Baltimore Oas & Electric Co 84/01/26 MURELY.T.E Region 1. Office of Director 3pp 22130:354 24X Fiche 50-317,84/01/26,8402080373
- B402020006 LER B3-079/03L-0 on B31227, discovered reactor protection sys channel D for high power & thermal margin/low pressure (TM/LP) inoperable Caused by foreign mati on TM/LP power supply leads Leads & terminations cleaned W/B40119 ltr. PORTER, F J SNYDER, J A , RUSBELL, L B Baltimore Cas & Electric Co B4/01/27 MVBLEY, T E Region 1, Office of Director, 2pp. 22056 336 24X Fiche 50-317,84/01/27,8402020006
- 8402070384 LER 83-078/OSL-0 on 831229; pressurizer level decreased below 133 inches three times RGS temp swings of 10 F not uncommon during normal startup aperations. Pressurizer level program will be changed to prevent recurrence W/640127 ltr JUNGE, H A. RUSSELLI. B. Baltimore Gas & Electric Cg. 84/01/27 MURLEY, T E. Region 1. Office of Director. 2pp. 22095 199 24X Fichs 50-317.84/01/27,8402070384
- 8402270456 LER 83-077/04T-0 on 831231; Oyster samples collected during Dec 1783 from Camp Canoy indicated Ag-110 above ETS limits. Caused by natural tendency of oysters to bioconcentrate environ silver W/840202 ltr VDGEL,A.M., RUSSELL,L B Baltimore Oas & Electric Co 84/02/02 MURLEY,T E Region 1, Office of Director 2pp 22389:270 24X Ficha 50-317.84/02/02.8402270456

- E402280113 LER BA-001-00 on B40113, post-accident sempling aus feture to reactor coolant drain tank isolation valve discovered open Cause unknown Key switches for valve modified W/840210 ltr
 LOHR, J. RUSSELL, L. B. Baltimore Cas & Electric Co. B4/02/10 MURLEY.T E. Region 1, Office of Director. 4pp. 22401 103, 243 Fiche 50-317, 84/02/10, B402280113
- 840220290 Responds to 840120 telcon request for add1 info re ferent failures of control element assembly reed switch position indicators at facilities Failed transmitters will be sent to vendor for repeir TIERNAN, J A Baltimore Oas & Electric Co 84/02/13 MILLER, J R Operating Reactors Branch 3 1p 22335 344 24% Fithe 30-317,84/02/13.8402220290
- DOCKET 50-318 CALVERY CLIFFS NUCLEAR POWER PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8402130480 Informs that R Eberly of NRC will be at site on G40130 to attend general orientation training Parts I & II & tour parts of plant in connection w/ongoing fire protection review JAFFE, D H Operating Reactors Branch 3 84/01/19, RUSSELL.i. Baltimore Gas & Electric Co 2pp 22214 357 24X Fiche 50-317,84/01/19,8402130480.
- B402090216 Notification of Significant Licenses Meeting B4-10 on 84025 w/util in Lusby.MD to discuss leasons learned from previous 10CFR50.App R safe shutdown insp PULLANIS Region 1. Defice of Director 84/01/25 DIRCKS.W J Office of the Executive Director for Operations 3pp 22188 341 24X Fiche 50-317.84/01/25.8402090216
- 8402160457 Rev 0 to emergency response plan implementation fracedure 5 3 1 k Rev 10, Change 2, new Attachment 2 to emergency response plan implementation Procedure 4 1 17 W/840210 & 13 transmittal & receipt itrs
 USI.V Baltimore Gas & Electric Co 84/02/01 10pp 22868 244 24X Fiche: 50-317, 84/02/01, 8402160457
- B402160577 Advises that NRC will not review emergency plans to delete private or proprietary info unless specifically requested by licensee, set B10709 Generic Ltr B1-27 W/o request, entire plan will be placed in PDR MILLER, JR Operating Reactors Branch 3 84/02/06. LUNDVALL, A C Baltimore Oss & Electric Co 2pp 22302:120, 24x Ficher 50-317, 84/02/06, 8402160577
- 8402130156 Forwards request for exemption from 10CFR30, App E. Bection IV F 1 a re 840911 exercise Local & state govt agencies will not be represented in exercise H/o exemption request LUNDVALL, A E Baltimore Gas & Electric Co 84/02/09, HillEH. J R Operating Reactors Branch 3, 1p 22249 175 24X Fiche 50-317, 84/02/09, 8402130136
- 8402270330 Advises that portions of Rev 13 to security plan, submitted on 830826, unacceptable as is Corrected pages due in 30 days. Encl withheld (ref 100FR/3 21)

 MARTIN, TT Division of Engineering & Technical Programs. 84/02/23

 BOWMAKER, N J Baltimore Cas & Electric Co. 4pp 22387:305 241

 Fiche: 50-317, 84/02/23, 8402270330
- P Operating license stage documents & correspondence
- B402130480 Informs that R Eberly of NRC will be at site on B40100 to attend general orientation training Parts I & II & tour parts of plant in connection w/ongoing fire protection review JAFFE.D H Operating Reactors Branch 3. 84/01/19 RUSSELL.L. Baltimore Gas & Electric Co 2pp 22214 357 24X Fithe 50-317.84/01/19.8402130480
- 8402130274 Forwards request for add1 info to complete review of C-S extended burnup rept CENPD-269. Info should be provided within 90 days httl.ER.J.R. Operating Reactors Branch 3 84/01/24 LUNDVALL.A E Baltimore Gas & Electric Co. 4pp. 22216 199 24X Fiche 50-317.84/01/24.8402130274
- 8402040078 Suppl 1 to 831222 application for amend to License DPR-69 rechanges to Tech Specs resulting from determination that generic steam line break analysis performed for Unit 1 Cycle 7 applicable to Unit 2 LUNDVALLIA E Baltimore Oas & Electric Co 84/01/27, HILLER.JF Operating Reactors Branch 3 Spp 22087 117 24% Fiche 50-318.84/01/27.8402060098

- 8402040216 Notification of Significant Licensee Meeting 84~10 on 840208 w/util in Lusby.MD to discuss leasons learned from previous 10CFR50.App R safe shutdown insp FULLANI.S Region 1. Office of Director 84/01/25 DIRCKB,W J Office of the Executive Director for Operations STELLD.V Regional Operations & Ceneric Requirements DEYOUND.R C Director's Office. Dffice of Inspection and Enforcement 3pp 22188 341 24X Fichs 50-317.84/01/25.8402090216
- 8402090361 Forwards IE Insp Repts 50-317/83-32 & 50-318/83-32 on 831114-18 No violations noted MARTIN.T T Division of Engineering & Technical Programs 84 LUNDVALL.A E Baltimore Cas & Electric Co 2pp 22161 102 Fichs 50-317,84/01/27.8402090361 FI4/01/27
- --8402090374 IE Insp Repts 50-317/83-32 & 50-318/83-32 on 831114-18 No noncompliance noted Major areas inspected testing program, pracritical test, low power physics tests & power ascension tests
 HEN.P C , BETTENHAUSEN, L Region i, Office of Director 84/01/24 10pp. 22161 104 24X Fiche 50-317,84/01/27,8402090361
- 8402160331 Forwards IE Insp Repts 50-317/83-14 & 50-318/83-14 on B31114-18 No violations observed MARTIN T Division of Engineering & Technical Programs 84/ LUNDVALL,A E. Baitimore Qas & Electric Co 2pp 22268 335 Fiche 50-317,84/08/01,8402160331 84/02/01
- --B402160339 IE Inap Repts 50-317/83-14 & 50-318/83-14 on B31114-18 No violations identified Major areas inspected inservice inspactivities. licensee response to IE Bulletin 80-08 & licensee actions on previous insp findings MCBREARTY, R A . DURR.J P Region 1. Office of Director 84/01/30 5pp 22268 337. 24X Fiche 50-317.84/02/01.8402160331
- 8401190015 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc. 119pp. 22114 179 24X Fiche 50-000,84/02/03,8401190016
- 8401170017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent COLYMON, IE BULLETIN 84-01, "Cracks in BWR Mark I Containment Vent Headers " SVc list encl DEYCUNG, R. C Director's Office, Office of Inspection and Enfarcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp R2177:136 24% Fiche 50-000,84/02/03.8401190017
- 8402240128 Forwards IE Insp Repts 50-317/83-31 & 50-318/83-31 on 831114-1231 & notice of violation 8TAROSTECKI.R. Division of Project & Resident Programs 84/02 LUNDVALL.A E. Baltimore Oas & Electric Co 2pp 22375 088 Fiche: 50-317, 84/02/07,8408240128 84/02/07
- --8402240133 Notice of violation from Insp on 8J1116-1231 Region 1, Office of Director 84/02/07 2pp 22: Fiche 50-317,84/02/07,8402240128 22375 090 24X
- --B402240139 IE Imag Repts 50-317/B3-31 & 50-318/B3-31 on B31114-1231 Violations noted initiation of alternate means of auxiliary feedwater sys not established & sufficient measures not taken to prevent recurrence of excessive pressure ARCHITZEL, R. E. TRIMBLE, D. C. ELSASBER, T. C. Region 1, Office of Director B4/02/02 25pp 22375 092 24X Fiche 50-317, B4/02/07, B402240128
- 8402140326 Ack receipt of 840119 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/83-29 & 50-318/83-29. 84/02/08
 - BO-310/83-24.

 MARTIN,T T Division of Engineering & Technical Programs B4

 LUMDVALL,A. E Baitimore Cas & Electric Co 2pp 22221:042

 Fiche 30-317.84/02/08.8402140326
- ---8402140329 Responds to NRC 831219 ltr re violations noted in IE Insp. Repts 50-317/83-29 & 50-318/83-29. Corrective actions, systemplemented to better track accumulated work hours

 LUNDVALL.A.E Baltimore Cas & Electric Cn. 84/01/19. MARTIN.T T

 Division of Engineering & Technical Programs 2pp 22221:044

 24X Fiche: 50-317.84/02/08,8402140324
- B40119004) IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (1005R50, App R) " Syc list
- JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/13 Consolidated Edison Co. of New York: Inc. 124pp. 22365:257 24X Fiche 50-000.84/02/13,8401190041
- 8402270287 Forwards IE Insp Repts 50-317/84-02 & 50-318/84-02 on 840109-13 No violations observed. HARTIN.T.T Division of Engineering & Technical Programs 84/02/11 LURDVALL, A.E. Baltimore Oas & Electric Co 2pp 22427-175 24X 84/02/13 Fiche: 50-317,84/02/13,8402290287.

- --8402060106 Proposed Tech Specs permitting more negative moderator temp coefficient (MTC) & less restrictive shutdown margin requirement.accommodating more negative MTC & allowing negative finding under 10CFR90 59 for Cycle 6 * Baltimore Gas & Electric Co 84/01/27 3pp 22089 120 24x Fiche 50-318.84/01/27,8402060098
- 8402060234 Application to amend Licenses DPR-53 & DPR-69, revising Teth Specs to allow operation of hydrogen sample & hydrogen sample return containment isolation valves during testing under administrative control i.UNDVALL, A E Baltimore Gas & Electric Co 84/01/27 MILLER, Operating Reactors Branch 3 4pp 22087 219 24X Fiche 50-317.84/01/27.8402060234
- --8402060238 Proposed changes to Teth Specs allowing operation of hydrogen sample & hydrogen sample return containment isolation valves during testing under administrative tontrol

 ** Baltimore Qas & Electric Co 84/01/27 31pp 22087 223 24x

 **Fiche 50-317,84/01/27,8402060234
- 8402010410 Generic Ltr B4-04 to all uperating PMR licensees, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PMR primary main loops Svc list encl EISENHUT, D G Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc. 59pp 22177 087 24X Fiche 50-000,84/02/01.8402010410
- 8402080272 Requests relief from MRC 830316 order re add1 refueling cycle for installation of noble gas steam offluent monitor, per NUREO-0737. Item II F I Feasibility of procuring & installing replacement monitor being investigated LUNDVALL.A E Baltimore Oas & Electric Co 84/02/03 MILLER, J Operating Reactors Granch 3 3pp 22131 202 24X Fiche 50-317.84/02/03.8402080272 84/02/03 MILLER, J R
- 8402100006 Responds to Generic itr 84-01 re use of terms important to safety & safety-related Further discussion will be through participation in util safety classification group LUNDVALL, A E Daltimore Gas & Electric Co 84/02/03 TAYLOR, J M Director's Office of Inspection and Enforcement ip 22182 156 24% Fiche 50-317,84/02/03,8402100006
- B402170015 Forwards notice of consideration of issuance of amends to Licenses DPR-53 & DPR-69 & proposed NBHC determination & opportunity for hearing re-control element assembly position indicator channels

 JAFFE, D H Operating Reactors Branch 3 B4/02/09 LUNDVALL, A E
 Baltimore Cas & Electric Co 1p 22319 129 24X

 Fiche 50-317.84/02/09.8402170015
- --8402170018 Notice of consideration of issuance of amends to Licenses DPR-53 & DPR-69 & proposed NSKC determination & opportunity For hearing For hearing MILLER.J.R Operating Reactors Branch 3 84/02/09 9pp 22319 130 24X Fichs 50-317.84/02/09.8402170015
- B402270454 Forwards Class III & I licensing fees, per 840203 request Mod of order re schedule for completion of NUREO-0737, Item II F 1 concering noble gas steam installation requested LUNDVALL, A E Baltimore Oas & Electric Co 84/02/16 MILLER, J R Operating Reactors Branch 3 ip 22390 247 24X Fiche: 50-317, 84/02/16, 8402270454
- G. Inspection reports, IE Bulletins & correspondence
- 8312120153 IE Info Notice 84-06. "Steam Binding of Auxiliary Feedwater Pumps. "Bvc list encl
 JORDAN.E L Division of Emergency Proparedness & Engineering
 Response (Post 830103) 84/01/25 Consolidated Edison Co of New
 York, Inc. 120pp 22058 001 24X Fiche 30-000.84/01/25.8312120153
- 8402080330 Forwards IE Insp Repts 50-317/83-34 & 50-318/83-34 on 831330-1205 No violations noted MARTIN, T. Division of Engineering & Technical Programs 84 LUNDVALL, A.E. Baltimore Gas & Electric Co. 2pp 22130 270 Fichs 50-317,84/01/25,8402080330 B4701725
- --8402080333 IE Insp Repts 50-317/83-34 & 50-318/83-34 on 831130-1205 No noncompliance noted Major areas inspacted startup physics testing program & precritical & post-critical tests following Unit 1 Cycle 7 refueling WEN.P.C., BETTENHAUSEN,L. Region 1. Office of Director 84/01/25 10pp 22130,272 24X Fiche 50-317,84/01/25,8402080330

- --8402290294 IE Insp Repts 50-317/84-02 & 50-318/84-02 on 840109-13 No violations identified Major areas inspected licensee actions on previously identified items.high radiation area controls & in-plant radiation protection program CDLLING.J. SHANBARY,M M Region 1. Office of Director 84/02/06 5pp 22427 177 24X Fiche 50-317,84/02/13,8402290287
- 8401190039 IE Info Notice 84-08, "10CFR90 7, `Employee Protection '"
 Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc | 113pp | 22365 141 | 24X Fiche 50-000,84/02/14,8401190039
- 8401170045 IE info Notice 83-43, Suppl 1, "Potential Failures of Mestinghouse Type SA-1 Differential Relays " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc 118pp 22366 142 24X Fiche 50-000,84/02/15,8401190045
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000.84/02/21.8401190062
- B401190066 IE Info Notice 84-)1, "Training Program Beficiencies "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B4/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000.84/02/24,8401190066
- B401190067 IE Info Notice B4-12, "Failure of Soft Seat Valve Beals " Svc list encl JURDAN.E L Division of Emergency Proparedness & Engineering Response (Post 830103) B4/02/27 Consolidated Edison Co. of New York, Inc 120pp 22431 040 24X Fiche 50-000,84/02/27,8401190067
- R Periodic operating reports & related correspondence
- 8402270408 Number of personnel & man-rem by work & job function, 1983 W/840213 ltr TIERNAN.J A Daltimore Gas & Electric Co 83/12/31 MURLEY,T E Region 1, Office of Director. 3pp 22391 149 24X Fiche 50-317,83/12/31.8402270408
- 8402220440 Monthly operating repts for Jan 1984 W/840213 1tr LOTITO.E H Baltimore Cas & Electric Co 84/01/31 13pp 22340 007 24% Fiche 50-317.84/01/31.8402220440
- 8 Reportable occurrences, LERs & related correspondence
- 8402140486 Responds to FOIA request for 16 categories of documents re degradation of bolts, nuts & stude at PWRs & DWRs Forwards App A documents App A & B documents available in PDR FELTON, JM Division of Rules and Records 83/12/02 BELL, N Nuclear Information & Resource Service 4pp 23257 003 24X Fiche 50-000.83/12/02.8402140486.
- --8402140524 Forwards LER 80-010 & LER 81-002/01 rm stud corresion * NRC - No Detailed Affiliation Given 81/05/15 NRC - No Detailed Affiliation Given 1p 22258 039 24X Fiche 50-000,83/12/02.8402140486
- 8402060123 RD during Nov 1983, system samples analyzed showed Ag-110m concentration of greater than 9 pCi/kg (net). Caused by tendency of systems to bioconcentrate environ silver No threat to public health & safety noted.
 FUHRHAN. 6 R Daltimore Gas & Electric Co 83/12/22 Region i, Office of Director. 2pp 22089 114 24X Fiche 50-317.83/12/22, 8402060123
- 3402030413 Updated LER 83-057/03X-2 on B31017, during surveillance test procedures, excessive leak rate past containment personnel air lock outer door discovered Caused by degradation of gasket Casket & groove cleaned & lubricated W/840103 ltr JUNGE, M A. LYONS, W T., RUBBELLL B. Baltimore Oas & Electric Co B4/01/03 MURLEY, T E Region 2, Office of Director 2pp 22068-305 24X Fiche 50-316,84/01/03,8402030413
- 3402280147 LER 83-072/03L-0 on 831217.MSIV 21 inadvertently shut.Low pressure hydraulic line on MSIV 21 became disconnected & hydraulic fluid reservoir level decreased Caused by failure of Swagelok compression fitting Line replaced W/840112 ltr JUNGE A A DARLING, 8 8. RUSSELL.L B Baltimore Cas & Electric Co 84/01/12 MURLEY,T E Region 1. Office of Director 2pp. 22400 288 24X Fiche: 50-318.84/01/12.8402280147

- 8402020268 Updated LER 83-067/03L-1 on 831208, charging pump discharge relief valve 23 lifted Caused by damaged disc Disc replaced Further testing initiated to correct setpoint W/840113 ltr JUNGE M A , REID, K A , RUSSELL, L B Baltimore Gas & Electric Co 84/01/13 MWLEY, T E Region 1. Defice of Director 2pp 22055 244 24X Fiche 50-318,84/01/13,8402020248
- 8402030403 Updated LER 83-037/01X-1 on 830803.ECCS pump room exhaust ventilation sys charcoal filter inlet damper failed to open when filter bypass damper shut Caused by incorrect connection Damper operators mounted W/840113 ltr
 JUNGE, M. A., PAUS.O. 8. RUBSELL. B. Baltimore Gas & Electric Co. 84/01/13 MURLEY.T E. Region 1. Office of Director 4pp 22068 343 24X Fiche 50-318.84/01/13,8402030403
- 8402270283 Nonroutine radiological environ operating rept ra review of observed levels of Ag-110m in oyster samples collected during 1983 Caused by tendency of oysters to highly disconcentrate environ silver FUHRMAN, O R Baltimore Gas & Electric Co 84/01/17 Region 1, Office of Director 3pp 22391-308 24X Fiche 50-317,84/01/17, 8402270285
- 8402020270 LER 83-071/03L-0 on 831219, during return to full power, power dependent insertion limit (PDIL) for Group 4 rods found inoperable Caused by setpoints out of tolerance at SBX power PDIL readjusted 4/840118 ltr PIERINGER,P, SNYDER,J, RUSSELL,L B Baltimore Gas & Electric Co 84/01/18 KURLEY,T E Region 1, Office of Director 3pp 22055-241 24X Fiche 50-318,84/01/18,8402020270
- 8402020243 LER 83-074/03L-0 on 831223, main steam supply valve to steam driven auxiliary feedwater pumps failed open Caused by elongated actuator diaphragm casing bolt holes on 2-CV-4070 New diaphragm installed & valve cycled W/840119 ltr. PIERINGER, P. LYONS, W., RUSSELL, L. B. Baltimore Gas & Electric Co 84/01/19 MRLEY, T. E. Region 1, Office of Director 2pp 22086 361 24% Fiche 50-318, 84/01/19, 8402070243.
- 8402020304 LER 83-073/03L-O on 831220 reactor protection sys channel D for steam generator low pressure trip found inoperable Caused by faulty trip unit power supply Power supply replaced & channel returned to svc W/840119 ltr PORTER, R J , ANDROBIK, R , RUSSELL, L B Baltimore Gas & Electric Co 84/01/19 MRLEY, T & Region 1, Office of Director. 2pp 22054.337 24X Fiche 50-318,84/01/19,8402020304
- 84D2030309 Updated LER 82-031/03X-1 on 820619, while performing preventive maint test, diesel speed control 12 failed so that load could not be lowered or raised Caused by maladjusted governor, Adjustments made W/840119 1tr
 JUNGE, M. A. ALLEN, R. R. R. BUBBELL, L. B. Baltimore Oas & Electric Co. B4/01/19 MURLEY, T. E. Region 1, Office of Director 2pp 22069:360 24X Fiche 50-318,84/01/19,8402030309
- BAC2030337 LER B3-077/03L-O on B31221, during normal operation, leak discovered in charging header drain line Caused by failure of 3/A-inch socket weld due to line vibration & lack of restraint Restraint installed W/840119 ltr JUNGC, M A, GUTMBY.C H, RUSBELL, L B Baltimore Gas & Electric Co 84/01/19 MURLEY, T.E. Region 1, Office of Director. 2pp. 22067:093 24X Fiche 50-318,84/01/19,8402030337
- 8402080230 Updated LER 83-064/03X-1.on 831105, after obtaining results of Unit 1 HPBI flow balance test.six Unit 2 HPBI header isolation valves required adjustment Caused by inadequate procedures Naint procedures revised. W/840124 ltr BASBO.L F, RUSSELL.L.F Baltimore Qas & Electric Co 84/01/24 MURLEY, T E Region 1, Office of Director 3pp. 22130 082 24X Fiche 80-318.84/01/24,8402080230
- B4020703B7 LER B3-076/03L-0 on B31227, CEA-1 dropped into core & on B3122B, CEA-64 dropped into core. Cause under investigation Current traces will be evaluated during next scheduled test. H/F40126 ltr UUN9E,M . CRUNKLETON.J., RUBBELL, L B Baltimore Gas & Electric Co B4/01/26 MURLEY,T E Region 1, Office of Director 2pp. 22075 105 24% Fichs. 50-318, B4/01/26, B4020703B7
- 8402270455 Updated LER 83-074/03X-i on 831223, main steam supply valve to steam driven auxiliary feadwater (AFW) pumps failed, causing AFW pump 2i to start Caused by insufficient torque on casing cap screws New disphragm installed W/840207 itr PIERINGER,P. LYONS,W., RUSSELL,L. B. Baltimore Gas & Electric Co 84/02/07, MURLEY,TE Region i, Office of Director 2pp. 22389:327 24X Fiche 50-318,84/02/09,8402270455.
- 8402220270 Responds to 840120 telcon request for addl info re recent failures of control element assembly reed switch position indicators at facilities. Failed transmitters will be sent to yendor for repair.

 TIERNAN.J A. Baltimore Gas & Electric Co. 84/02/13. MILLER.J R Operating Reactors Branch 3 ip. 22335 344. 24X Fiche 80-317.84/02/13.8402220270

- DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8402020164 Forwards IE Insp Rept 50-320/83-20 on 831114-1231 No violatione noted BARRETT, L. H. TMI Program Office 84/01/18 KANGA, B. K. General Public Utilities - GPU Service Corp 2pp 22036 125 24X Fiche 50-320,84/01/18,8402020164
- --8402020169 IE Insp Rept 50-320/83-20 on 831114-1231 No violations noted Major areas inspected action on IE circulars. previously identified items of noncompliance unresolved items & radiological protection program garr. W. OELL, J. FASAND. A Region 1. Office of Director 84/01/13 8pp 22056 127 24X Fiche 50-320.84/01/18.8402020164
- 8402030424 Responds to util 830603 & 0720 ltrs re Revs 17 & 18 to security plan Portions of revs unacceptable Safeguards info withheld (ref 10CFR73 21)
 MARTIN,T T Division of Engineering & Technical Programs 84/01/24
 HURILL.H D General Public Utilities GPU Service Corp 6pp
 22068 272 24X Fithe 50-289,84/01/24,8402030424
- B402090336 Forwards evaluation of State of PA radiological emergency preparedness plan for TMI
 MRIMM.R W Federal Emergency Management Agency 84/02/07
 JOBDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 5pp 22161 173 24X Fiche 50-289,84/02/07,8402070334
- --8402070337 Evaluation of State of PA radiological emergency preparadness plan for TMI + Federal Emergency Management Agency 83/12/20 160pp 22161 178 24% Fiche 50-289.84/02/07/8402090336
- B402140113 Rev 2 to Emergency Plan Implementing Procedure 1054 20.
 "Personnel/Vehicle Monitoring & Decontamination"
 KANGA B K General Public Utilities 0PU Service Corp
 13pp 22219 056 24X Fiche 50-320,84/02/09,8402140113
- 8402220264 Preliminary revs to emergency plan implementing procedures, consisting of Rev 3 to 1054 2, "Alert," Rev 4 to 1054 3, "Bite Emergency" & Rev 4 to 1054 4, "General Emergency" BRAPY, JA General Public Utilities OPU Bervice Corp 84/02/14 94pp 22390 060 24X Fiche 50-320.84/02/14.8402220264
- B402220289 Forwards FEMA final exercise evaluation rept of exercise conducted on 83i16 Category A & O deficiencise identified MARIIN. T T. Division of Engineering & Technical Programs B4/02/15 KANGA, B K. General Public Utilities GPU Service Corp. 3pp 22330 172 24X Fiche 50-320,84/02/15,8402220259
- --8402220263 Emergency preparedness exercise evaluation rept of exercise conducted on 831116
 4 Federal Emergency Management Agency 83/12/20 158pp. 22330 175 24% Fiche 50-320,84/02/15,8402220259
- 8402220429 Revised emergency plan implementing procedures, including Procedure 1004,5 re communications & recordkeeping, Procedure 1034 6 re add assistance & notification & Procedure 1054 1 re unusual event.

 8 General Public Utilities GPU Service Corp. 84/02/17 7lpp 22337.154 24X Fiche 80-320.84/02/17,8402220429
- B402270364 Rev O to Procedure 4000-ADM-1300 O1, "Maintaining Emergency Praparednass *
 « General Public Utilities - GPU Service Corp 84/02/22 19pp 22391 157 24X Fiche 50-320,84/02/22,8402270364

O. Adjudicatory correspondence

- 8402290467 Responds to 830913 request that NRC postpone lifting reactor pressure vessel head based on concerns re-potential estatence of pyrophoric matis within vessel head Request danied.per encl Director's Decision DD-84-04 DENTON-H. R Office of Nuclear Reactor Regulation, Director 84/02/17 LEWIS, M Lewis, M 2pp 22438 126 24X Fiche.50-320.84/02/17.8402290467
- --8402270473 Decision DD-84-04 denying M Lewis request that Commission postpone lifting reactor pressure vessel head at TMI-2 Potential pyrophoric conditions do not pose significant hazard to head lift DENTON.H R Dffice of Nuclear Reactor Regulation, Director. 84/02/17 9pp. 82438.128 84X Fiche 50-320.84/02/17.8402870447

- --8402270477 Notification of issuance of Director's Decision DD-84-04 re M Lewis 830919 request that Commission postpone lifting reactor pressure vessol head DENTON, HR Office of Nuclear Reactor Regulation, Director 84/02/17 Pp 22438 137 24X Fiche 50-320,84/02/17,8402270467
- --8402290478 Forwards 830928 ltr supporting M Lewis objections to removal of reactor head of damaged TMI-2 reactor Paper on effects on oxygen initrogen & hydrogen methanical properties of zirconium also enci GULBRANSEN.E A Pittsburgh, Univ of, Pittsburgh, PA 83/11/01 Dffice of the Secretary of the Commission 3pp 22438 141 24: Fiche 50-320.84/02/17.8402290467
- ---8402270479 "Effect of Hydrogen, Oxygen & Nitrogen Gases on Mechanical Properties of Airconium & Zirconium Allogs " GULBRANSEN,E A Pittsburgh, Univ of, Pittsburgh, PA 83/11/01 15pp 22438 144 24X Fiche 50-320.84/02/17,8402290467

H General correspondence

- 8402010137 Requests 1:sted name be added to TMI weekly status repts mailing list GUILLEN,C E General Public Utilities - GPU Service Corp 84/01/18 BARRETT,L H TMI Program Office ip 22038 231 24X Fiche 50-320-84/01/18,8402010137
- 8402150266 Submits opposition to use of nuclear power for energy & recommends permanent shubdown of Unit 2

 GUERRISI,L T Affiliation Not Assigned 84/02/10 SNYDER,B TMI Program Defice 3pp 22250 273 24X Fiche 50-320,84/02/10, RM00150264
- 8402290262 Comments on NUREG-0683, Suppl 1 re dose reduction in EIB Practice of exception to regulation when encountering problem at TMI must be discontinued HERMAN.A A Affiliation Not Assigned 84/02/24 SNYDER.B J TMI Program Office 2pp 22427 216 247 Fiche 50-320,84/02/24,8402290262
- O Advisory Committee on Reactor Safeguards reports & correspondence
- B402270263 Responds to FOIA request for JC Mark 801204 memo to ACRS re hydrogen burn w/igniters & documents concerning generation, combustion or control of hydrogen in reactor accidents Forwards App A documents App B documents in PDR FELTON, J M Division of Rules and Records 84/01/30 HIATT. B L Ohio Citizens for Responsible Energy 7pp 22412 051 24X Fiche 50-000.84/01/30.8402270263
- --8012310432 Forwards Dupont info supporting position that hydrogen generated in TMI accident was more than 10 times less than generally accepted number SHEMMON.P G ACRS Advisory Committee on Reactor Safeguards 80/10/30 ACRS Advisory Committee on Reactor Safeguards 29pp 22412-090 24X Fiche 50-000,84/01/30.8402270263
- --Bi01270309 Advises that pressure spike at facility containment sys following accident was caused by hydrogen burn released by zirconjum-water reaction Interpretations & alternative conclusions diacussed MARK., C ACRE - Advisory Committee on Reactor Safeguards B0/04/09 ACRS - Advisory Committee on Reactor Safeguards 22412 058 24X Fiche 50-000.84/01/30.8402270263
- --8402270305 Discusses proposed ACRB Subcommittee on Class 9 Accidents 800828 meeting in Washington DC to consider hydrogen generation & control during degraded core accidents BESBETTE. D ACRB - Advisory Committee on Reactor Safeguards 80/09/03 ACRS - Advisory Committee on Reactor Safeguards 22412 074 24% Fiche 50-000.84/01/30.8402270263
- --B402270337 Forwards collation & discussion of HF Ring opinion that current NRC position overestimates hydrogen production during plant accident by factor of 20 & radiolysis may be major source of hydrogen ETHERINOTON, H ACRS Advisory Committee on Reactor Bafeguards B0/12/04 ACRS Advisory Committee on Reactor Safeguards 8pp 22412:119 24X Fiche 50-000.84/01/30,8402270263
- ---B402270344 Discusses hydrogen burn w/ignitors Related info encl MARK, J C ACRS -- Advisory Committee on Reactor Safeguards B0/12/04 ACRS -- Advisory Committee on Reactor Safeguards 27pp 22412 127 24X Fichs.50-000.84/01/30.8402270263.
- P Operating license stage documents & correspondence
- B312120029 Generic Ltr 83-39 to representatives of utils re voluntary survey of licensed operators Svc list encl EISENHUT, D G Division of Licensing 83/12/08 Commonwealth Edison Co 12pp 22313 006 24X Fiche 50-000,83/12/08,8312120029

- 8402160003 Third partial response to FGIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILK, S. J. Office of the Secretary of the Commission 63/12/14 Public Document Branch ip 22281 023 24% Fiche 50-000, 83/12/14, 8402150003
- --8402160143 Discusses SECY-Bj-628 final GAO rept entitled "Greater Commitment Needed to Solve Continuing Problems at TMI "CMILK.S.J. Office of the Secretary of the Commission B2/01/27 DIRCKS,W.J. Office of the Executive Director for Operations ip 22281 197 24X Fiche 50-000,83/12/14,8402140003
- 8402070425 Responds to request at advisory panel 840112 meeting for addlinfo re occupational dose estimates in draft supplement to programmatic EIS
 SNYDER.B J THI Program Bffice 84/01/26 COCHRAN,T Natural Resources Befeise Council 7pp 22142 128 24X
 Fiche 50-320,84/01/26.8402070425
- B402030435 Forwards amend to annual update to technical evaluation rept For once-through steam generator layup recirculation sys Amend provides util resolution to comment expressed in NRC 840104 ltr re tube leak movement KANOA, B K General Public Utilities OPU Service Corp 84/01/27 BARRETTL H TMI Program Office 3pp 22069 027 24X Fiche SO-320,84/01/27,8402030435
- 8402270046 Final response to FOIA request for three categories of documents recompletion of accelerated requalification program by facility supervisor of operations NRC has no further documents subj to request FELTON. J M Division of Rules and Records 84/01/27 MAUPIN. H Hunton & Williams ip 22407 332 24% Fiche. 50-320, 84/01/27, 8402270046
- 840203045; Forwards responses to NRC comments on first pass stud detensioning SER Decupational exposure of 15 man/rem calculated as result of removal of up to five studs KANOA.B K General Public Utilities - GPU Service Corp 84/01/30 SNYDER.O J TMI Program Office 5pp 22066 257 24X Fiche 50-320,84/01/30,840203045;
- 8402130118 Forwards Amend 23 to License DPR-73 & safety evaluation Amend consists of administrative changes to Section 5 5 4 to be consistent w/mods to proposed Tech Spec Section 6 0 SNYBER. B J TMI Program Defice 84/01/31, KANOA.8 K General Public Utilities GPU Service Corp 4pp 22213 276 24X Fiche 50-320.84/01/31.8402130118
- --8402130121 Amend 23 to License DPR-73 consisting of administrative changes to Section 5 5 4 to be consistent w/mods to proposed Tech Spec Section 6 0 SNYDER.B J TMI Program Office 84/01/31 3pp 22213 300 24X Fiche 50-320,84/01/31.8402130118
- --840R130123 Safety evaluation supporting Amend 23 to License DPR-73 * Office of Nuclear Reactor Regulation, Director 84/01/31. 3pp 22213 303 24% Fiche 50-320,84/01/31,8402130118
- 8402130146 Forwards Amend 24 to License DPR-73 & safety evaluation Amend deletes ref to Unit 1 monitoring, instrumentation & valves relating solely to Unit 1 operation SNYDER, B J TMI Program Office 84/01/31 KANGA, 8 J Ceneral Public Utilities GPU Service Corp 3pp 22216-274 24X Fiche 50-320,84/01/31,8402130146
- --8402130149 Amend 24 to License DPR-73, deleting ref to Unit 1 monitoring, instrumentation & valves relating only to Unit 1 operation SNYDER, B J TMI Program Office 84/01/31 2pp. 22216:277 24X Fiche 50-320,84/01/31.8402130146
- --8402130152 Safety evaluation supporting Amend 24 to License DPR-73 * Office of Nuclear Reactor Regulation. Director 84/01/31 24pp 22216 279 24X Fiche 50-320,84/01/31,8402130146
- 3402130484 Requests that updated major milestone schedule for TMI-2 cleanup be provided to NRC by 840301 Major technical & financial assumptions for CY84 & beyond requested SNYDER. B J TMI Program Office 84/01/31 KANOA, B K General Public Utilities OPU Service Corp. 2pp 22214 355 24X Fiche 50-320,84/01/31.8402130484
- M02130608 Requests FR publication of notice of issuance of Amend 23 to License DFR-73 revising administrative changes to wording of Section 5 5 4 of App B of Tech Specs re reviews by plant operations review committee POINDEXTER, TC TMI Program Office, B4/01/31 MILLER. J. R Operating Reactors Branch 3 2pp 22214, 304 24X Fiche 50-320, 84/01/31, 8402130608

- 0402140523 Requests FR publication of notice of issuance of Amend 24 to License DPR-73, deleting Unit 2 Tech Spec refs to Unit 1 monitoring instrumentation & valves that relate solely to operation of Unit 1 POINDEXTER, T C TMI Program Office 84/01/31 MILLER, J R Operating Reactors Branch 3 2pp 22251 3A0 24X Fiche 50-320,84/01/31,8402140523
- 84D2010410 Generic Ltr 84-04 to all operating PWR licensees, CP holders to applicants for CPs re-safety evaluation of Mestinghouse topical repts dealing w/climination of postulated pipe breaks in PWR primary main loops Svc list encl EISENRUTID 0 Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc. 99pp 22177 087 24X Fiche 50-000.84/02/01.8402010410
- 8402100177 Advises that proposal to conduct decontamination & dose reduction efforts acceptable Rationale for approval & discussion of SER for ampoing containment bldg decontamination & dose reduction activities enc!
 SNYDER:BJ TMI Program Office 84/02/03 KANQA,B K General Public Utilities ~ GPU Service Corp 9pp 22196 395 24X
 Fiche 50-320.84/02/03.8402100177
- 8402210328 Forwards transcript of Advisory Panel for Decontamination of TMI-2 840203 meeting MASNIK.M T TMI Program Office 84/02/06 Advisory Council for Becontamination of TMI Unit 2 5pp 22344 048 24X Fiche 50-320.84/02/06.8402210328
- --8402210336 Forwards "Cancer Risk Coefficient Applicable to TMI-2 Work Force." In response to questions raised at Advisory Committee on Cleanup of TMI-2 840112 meeting COCHRAN, T B Natural Resources Defense Council 84/02/03 NRC -- No Detailed Affiliation Given 2pp 22344 053 24X Fiche 50-320,84/02/06.8402210328
- --8402210460 "Cancer Risk Coefficient Applicable to TM1-2 Work Force "
 COCHRAN,T B Affiliation Not Assigned 84/02/03 10pp
 22344 055 24% Fiche 30-320.84/02/06.8402210328
- --8402210469 Transcript of Commission 840203 meeting w/Advisory Fanel on TMI-2 Cleanup in Washington DC Pp 1-47
 * Commissioners 84/02/03 52pp 22344 065 24X
 Fiche 50-320,84/02/06.8402210328
- B402130304 Forwards comments on draft Suppl 1 to programmatic EIS (NUREQ-0683) re decontamination & disposal of radioactive wastes resulting from 79032B accident MOLHOLT.B Bryn Mawr College 84/02/08 SNYDER, B J THI Program Dffice 13pp 22204 013 24X Fiche 50-320,84/02/08,8402130304.
- 84022400B1 Partial response to FOIA request for records arising out of imaps of TMI-1 & 2 re detection of measurement of RCB leakage App A documents available in PDR Forwards App B documents Review of addirecords sub, to request continuing FELTON. J M Division of Rules and Records 84/02/08 MADDEN.T J Kaye, Scholer, Fierman, Hays & Handler. 4pp 22394-277. 24X Fiche. 50-287.84/02/08.8402240081
- --8310200329 Forwards technical evaluation of OPU analysis of PDRV tailpips temps & PORV leakage.per 830825 request Analysis reasonable Evidence convincing that one safety valve leaking in Feb-Mar 1979 time frame MATTSON.R.J Division of Bystems Integration (post 811005) 83/10/12 EIEENHUT.D 0 Division of Licensing App 22394:292 24X Fiche 50-289.84/02/08.8402240081
- --8402240097 Submits historical background of data accumulated & list of current action items, in response to NRC 800114 ltr re reactor bldg sump level & RCS makeup sys laskage. Table encl WILSON.R F Metropolican Edison Co WILSON.R F. General Public Utilities CPU Service Corp 84/02/08 COLLINS, J T TMI-2 Operations/Support Task Force 3pp. 22394, 281 24X Fiche 50-289, 84/02/08, 8402240081
- 8402170491 Offers no comments on rev to technical evaluation rept update for once-through steam generator layup recirculation ups. Rev acceptable.

 BARRETT, L. H. THI Program Office 84/02/09. KANOA, B. K. General Public Utilities GPU Service Corp. 1p. 22312 360 24X Fiche 50-320,84/02/09,8402170491

- 8402230032 Btaff requirements memo re Advisory Panel on TMI-2 Cleanup 840203 meeting on cleanup allegations in Washington.DC Cosmission requested options for water disposal & results of scheduled meeting between EPA & Adivsory Panel CHILK-9 J Defice of the Secretary of the Commission 84/02/14 DIRCKS, H J Defice of the Executive Director for Operations 2pp 22379.340 24X Fiche 50-320.84/02/14.8402230032
- 8402230115 Responds to NRC 831114 ltr & Generic Ltr 81-38 reproceduralized practice in storage of solid radwaste Procedure change submitted to require compatability evaluation for packaging temporary storage KANGA.B K General Public Utilities GPU Service Corp 84/02/16 BARRETT.L H. TMI Program Office 3pp 22361 212 24X Fiche 50-320.84/02/16.8402230115
- 8402270086 Forwards comments on suppl to programmatic EIS redecontamination & disposal of radwaste resulting from 790328 strident. Cleanup should proceed as expeditiously as reasonably possible MAGETTE, T E Maryland, State of 84/02/17 SNYDER, 0 J TMI Program Office 3pp 22387 351 24X Fiche 50-320,84/02/17,8402270084
- 8402290350 Responds to 830929 safety evaluation & 840130 addi info ra first pass stud detensioning of 60 reactor pressure vessel studs Datensioning poses insignificant risk to occupational workforce or affisite public 8NYDER. 8. J TMI Program Office 84/02/17 KANGA. B K General Public Utilities GPU Bervice Corp 7pp 22438 262 24X Fiche: 50-320,84/02/17,8402290350
- 8402270359 Comments on Suppl 1 to NUREG-0683, programmatic EIS redscontamination & disposal of radwaste fistimates of worker exposure not addressed DOHERTY. JF Doherty, JF 84/02/18 NRC No Detailed Affiliation given 4pp 22391 153 24X Fiche 50-320,84/02/18,8402270359
- B402280388 Comments on programmatic EIB, Suppl 1, based on discussion at Tri-Caunty Regional Planning Commission 840223 meeting Site unsuitable as long-term repository for accident-generated radwaste
 IRITERS, J. R. Treasure Coast Regional Planning Council, FL 84/02/23 BNYDER, B. J. TMI Program Office ip 22402 257 24X Fiche: 50-320, 84/02/23,8402280388
- 8402240173 Comments on Dec 1983 draft Suppl 1 to programmatic RIS (MUREO-0583) Estimate of collective dose equivalent expected to occur during recovery operations should be increased FLEYCHER. J C TMI-2 Technical Assistance & Advisory Group 84/02/27 SNYDER.B J TMI Program Diffice 5pp 22375 079 24X Fiche. 50-320.84/02/27,8402240173
- u inspection reports, it bulletins & correspondence
- 8402240067 FOIA request for documents arising out of insps of TMI-1 or 2 re detection or measurement of RCS leakage & compliance w/regulatory requirements concerning recordkeeping MADDEN, T. J. Kayer Bcholer, Fiarman, Hays & Handler 89/12/27 NOHRY, P. O. Office of Administration 2pp 22394:275 24X Fiche: 50-289,83/12/27,8402240067
- B402020117 Forwards IE Insp Rept 50-320/83-18 on 831108-10 No violations noted.

 MARTIN.T.T Division of Engineering & Technical Programs. 83/12/29 XANGA: B K General Public Utilities QPU Service Corp 2pp 22056 215 24X Fiche 50-320.83/12/29.8402020119
- --8402020124 IE Insp Rept 50-320/83-18 on 831108-10 No noncompliance moted. Major areas inspected chemical & radiochemical generated program using std radiocative samples/eources & lab assistance provided by DDE JANO, J. C. PABCIAK, H. J. Region 1, Office of Director 83/12/15, 7pp. 22056-217. 24X Fiche. 50-320, 83/12/29, 8402020119
- 8402020164 Forwards IE Insp Rept 50-320/83-20 on 831114-1231 No violations noted.

 BARRETT, L. H TMI Program Office 84/01/18 KANOA, B. K General Public Utilities OPU Service Corp. 2pp, 22056 125 24X Fiche: 50-320, 84/01/18, 8402020164
- --8402020169 IE Insp Rept 50-320/83-20 on 831114-1231, No violations noted. Major areas inspected action on IE circulars, previously identified items of noncompliance, unresolved items & radiplogical protection program BARR, K. BELL, J., PABAND, A. Region 1, Office of Director 84/01/13, 8pp. 22036:127, 24X Fiche: 50-320,84/01/18,8402020164.

- B402070354 Forwards IE Insp Rept 50~320/83-19 on 831031-1211 & notice of violation
 BARRETT,L H TNI Program Office 84/01/23 KANGA,B K General Public Utilities GPU Service Corp 2pp 22079 095 24X
 Fiche 50-320.84/01/23.8402070354
- --8402070357 Notice of violation from insp on 831031-1211 * TMI Program Office 84/01/23 2pp 22099 057 24X Fiche 50-320,84/01/23,8402070354
- --8402070359 IE Insp Rept 50-320/83-19 on 831031-1211 Violations noted failure to adhere to radiological control Procedures 1618A re radioactive mati shipping & 1410-Y-17 re waste storage tonk
 - tonx MIEDE, J., BARR, K., MDSLAK, T. TMI Program Defice 84/01/11 11pp 22099 059 24X Fiche 50-320,84/01/23,8402070354
- B312120133 IE Info Notice B4-06. "Steam Dinding of Auxiliary Feedwater Pumps " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post E330103) B4/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000.84/01/25.8312120153
- B4020B0355 forwards IE Insp Rept 50-320/83-14 on 830906-09 & 12 & notice of deviation
 MARYINAT T Division of Engineering & Technical Programs 64/01/25
 KANOA, B K General Public Utilities GPU Service Corp 2pp
 22131 196 24X Fiche 50-320,84/01/25,8402080355
- --8402080357 Notice of deviation from insp on 830906-09 & 12 * Region i, Office of Director 84/01/25 ip 22131 198 24X Fiche 50-370,84/01/25,8402080355
- ---B402080360 lR Insp Rept 50-320/83-14 on B30906-09 & 12 Deviation nated inadequate independence in design verification process MEYER.0 W SHAUB.E T CAPHION.D L Region 1. Office of Director B4/01/20 Bpp 22131 199 24X Fiche 50-320.84/01/25.8402080355
- B402140427 Responds to IE Bulletin 83-0B "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys "Facility uses deenergized GE Type AK-2 circuit breakers KANGA.B K General Public Utilities GPU Service Corp 84/01/31 MURLEY,T E Region 1. Defice of Director 3pp. 22227 136 24% Fiche 50-320.84/01/31.8402140427
- 8402130002 Submits add1 details to 840126 telcon re performance appraisal insp on 830227-0323 Insp will focus on documentation & implementation of mgt control sys for listed areas MURLEY.T.E Region 1. Opfice of Director 84/02/01 KINTNER.E E General Public Utilities ~ QPU Service Corp 3pp 22247 208 24X Fiche: 50-320.84/02/01.8402130002
- 8401190016 IE Info Notice 84-07. "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc. 117pp 22114.179 24X Fiche 50-000.84/02/03.8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers" Byc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177
- B402130446 Forwards notice of violation based on investigation on B30325-0B10 re allegations raised by former sits operations personnel on procedural & mgt control activities re refurbishment work associated w/reactor bldg polar crane DEYDUNG:R C Director's Office Office of Inspection and Enforcement B4/02/03 CLARK, R Qeneral Public Utilities QPU Service Corp 2pp 22216 127 24X Fiche 50-320,84/02/03,
- ---8402130447 Notice of violation based on investigation conducted on B30325-0810 re allegations dealing w/procedural & mgt controls re refurbishment of polar crane. DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 84/02/03 4pp. 22216 131 24% Fiche 50-320,84/02/03,8402130446
- 8402140288 Informs NRC of insp of reactor vessel head & internals handling fixture welds as required Welds visually examined & magnetic particle tested No visual defects or indications noted during exam

 KANGA, B. K. General Public Utilities GPU Service Corp. 84/02/07 SNYDER: B. J. TMI Program Defice. 1p. 22221 248 24X

 Fiche 50-320,84/02/07.8402140288

- 840117004: IE Info Natice 84-07, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (JOCFRSO, App R) " Syc list enc l
 - UDRIDAN, E.L. Division of Emergency Preparodness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365 259 24X Fithe 50-000,84/02/13,8401190041
- 8401190039 JE Info Notice 84-08, "10CFR50 7, 'Employee Protection '"
 - Syr list enci JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/14 Consolidated Edison Co. of New York, Inc. 115pp 22365 141 24X Fithe 50-000,84/02/14,8401170039
- 8401190049 IE Info Notice 83-53 Suppl 1. "Potential Failures of Westinghouse Type SA-: Differential Relays " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc. 118pp 22366 142 24% Fiche 50-000:84/02/15,8401190045
- 8401190062 IE Info Notice 84-j0, "Motor-Operated Valve Torque Switches Bet Below Manufacturer Recommended Value " Svc list encl JORDAN,E L Divisson of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc. 116pp 22366-024 24X Fiche 50-000.84/02/21.8401190062
- 8401170066 IE Info Notice 84-11, "Training Program Deficiencies " Olifouch is annumental and appearance in the second of the
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals " #011900b/ IE into Novice C. ... Syr list encl JORDAN E L Division of Emergency Preparedness & Engineering Rosponse (Post 830103) 84/02/27 Consolidated Edison Co. of New York, Inc. 120pp 22431 060 24X Fiche 50-400,84/02/27,8401190067
- R Pariodic operating reports & related correspondence
- 8402010375 Forwards TNI Program Ofc weekly status rept for wk of
 - BADIUS-14
 BARRETT, L. H. TMI Program Office 84/01/16 DENTON, H. R. Office of Nuclear Reactor Regulation, Director SNYDER, B. J. TMI Program Office 9pp 22059 327 24X Fiche 50-320, 84/01/16, 8402010375
- 8402020198 Forwards TMI Program Ofc weekly status rept for wk of 840115-21
- 84015-21 BARRETT, L H TMI Program Office 84/01/23 DENTON, H R Office of Nuclear Reactor Regulation, Director SNYDER, D J TMJ Program Office 9pp 22062 239 24% Fiche 50-320, 84/01/23, 8402020198
- 8402090271 Forwards TMI Program Ofc weekly status rept for which B40122-28
- BARRETT.L H TMI Program Office 84/01/30 DENTON,HR Office of Nuclear Reactor Regulation, Director SNYDER,B J TMI Program Office 9pp 22188 344 24% Fiche 50~320,84/01/30,8402090271
- 8402100231 Forwards annual update of sys descriptions & technical evaluation repts Sys descriptions & technical repts which require no revs listed KANGALE K General Public Utilities GPU Service Corp 84/02/SNYDER, B J TM1 Program Office 2pp 22179 277 24X Fiche 50-320,84/02/06,8402100231 84/02/06
- 8402140487 Forwards TMI Program Oft weekly status rept for wk of
- BARRETT, L H THI Program Office 84/02/06 DENTON, H R Office of Nuclear Reactor Regulation, Director SNYDER, D J TMJ Program Office 10pp 22253 304 24% Fiche 50-320, 84/02/06, 8402140487
- 8402170246 Forwards TMI Program Ofc weekly status rept for wk of
- Office of
- 8402270462 Forwards TMI Program Ofc weekly status rept for wk of
- Office of
- 3 Reportable occurrences, LERs & related correspondence
- 3402020367 LER B3-063/03L-O.on E34222.following maint on auxiliary bldg (AB) exhaust filter train A.operator inadvertently closed train B inlet damper, tripping AB exhaust fan Filter trains opened W7490118 lt WELLS.R, KANOA.B K General Public Utilities - GPU Service Corp. 84701/18 MURLEY.T E Ragion 1. Office of Director 4pp 22052.218 24X Fiche 50-320.84/01/18.8402020267.

- 8402210236 RD on 840205, digital voltmeter test plug failed, causing incomplete monthly requisite surveillance checks Digital voltmeter test plug repaired & surveillance checks completed satisfactorily patisfactorily
 KANOA, B. X. General Public Utilities - GPU Service Corp. 8:
 MURLEY, T. E. Region 1, Office of Director. 2pp. 22315 359
 Fiche 50-320,84/02/07,8402210236 R4/02/07
- 8402220103 PNO-TMI-84-001 on 840215, initial preparations for load testing reactor bldg polar crane made Missile shields moved to load test frame to perform qualification load test Polar crane operated satisfactorily WIEBE, J. FASAND, A. DARRETT.L. TMI Program Office 84/02/15 1; 22338 260 24% Fiche 50-320,84/02/15,8402220103
- T Hearing transcripts on non-antitrust matters
- 8402140503 Transcript of Advisory Panel for Decontamination of TMI-2 840112 meeting in Harrisburg.PA Pp 1-108 Supporting documentation encl # Advisory Council for Decontamination of TMI Unit 2 84/01/12 118pp 22231 172 24X Fiche 50-320.84/01/12.8402140503
- 8402130144 Transcript of 840203 periodic maeting w/Advisory Panel for Decontamination of TMI-2 in Washington DC Pp 1-47 * Commissioners 84/02/03 51pp 22237 165 24X Fiche 50-320 84/02/03.8402130144
- 8402210328 Forwards transcript of Advisory Panel for Decontamination of IOM210328 FOOTGATES FRANKTIPS OF AGVISORY PAREL FOR DECONTAMINATION I TMI-2 840203 meeting MASNIK.M T TMI Program Office 84/02/06 Advisory Council for Decontamination of TMI Unit 2 5pp 22344 048 24X Fichs 50-320.84/02/06.8402210328
- --8402210469 Transcript of Commission 840203 meeting w/Advisory Pansl on TMF-2 Cleanup in Washington.DC Pp 1-47
 * Commissioners 84/02/03 52pp 22344 065 24X
 Fiche 50-320,84/02/04,8402210320
- 8402290342 Transcript of Advisory Panel for Decontamination of TMI-2 840209 meeting in Harrisburg, PA Pp 1-192 Supporting documentation encl # Advisory Council for Decontamination of TMI Unit 2 84/02/09 250pp 22436 158 24X Fiche 50-320,84/02/09,8402290342
- U Congressional/Executive Correspondence
- 840209008) Further response to FOIA request for IE Insp Rept 79-19, associated hotice of proposed imposition of civil panalties, notice of violation & order to show cause Forwards App A documents Documents also available in PDR FELTON, J M Division of Rules and Records 83/12/20 HAMLIN, J Shaw, Pittman, Potts & Trowbridge 4pp 22188 104 24X Fiche 50-000,83/12/20,8402090081 HAMLIN, J B
- --8402090198 Forwards chapter from final rept of NRC special inquiry group re financial disincentives to safety at TMI, in response to questions raised at Subcommittee on Oversight & Investigations 800923 hearing
 AHEARNE, J F Commissioners 80/11/13, ECKHARDT, B House of Rep. Interstate & Foreign Commerce 5pp. 22188 190. 24% Fiche 50-000, 63/12/20, 8402090081
- DOCKET 50-321 EDWIN I HATCH NUCLEAR PLANT, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8402140147 Forwards IE Insp Repts 50-321/83-36 & 50-366/83-39 on 831219-22 No violations or deviations noted DANCE: H C Division of Project & Resident Programs 84/01/17 KELLY: R J Georgia Power Co 2pp 22230 078 24X Fiche 50-321.84/01/17.8402140147
- --B402140154 IE Insp Repts 50-321/83-36 & 50-366/83-39 on 831219-22 No violations or deviations noted Major areas inspected health physics preparation activities re recirculation piping replacement project & followup review of LERs KAHLE, J B Region 2. Office of Director. BARR, K P. Division of Engineering & Operational Programs 84/01/13 Spp 22230:080 24X Fiche 50-321,84/01/17,8402140147
- 8402010160 Forwards "Evaluation of Georgia Power Co Emergency Preparedness Flan for El Hatch Electric Generating Plants" final rept KRIMNR W Federal Emergency Management Agency 84/01/24. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 22037 223 24X Fiche 50-321,84/01/24.8402010160

- --8402010165 "Evaluation of Georgia Power Co Emergency Preparedness Plan for EI Hatth Electric Generating Plant." final rept # Pederal Emergency Management Agency 83/10/28 55pp 22037 285 24X Fiche 50-321.84/01/24.8402010160
- 8402070236 Revised emergency plan implementing procedures, including Fracedures HNP-8157 re Victoreen electrometer Madel 500, HNP-8150 re Teledose Model 503A telemetry sys & HNP-4852 re offsite dose estimations W/840201 ltr SCRRELL,E C Georgia Power Co 84/02/01 76pp 22101 327 24x Fishe 50-321,84/02/01,8402070236
- 8402080331 Advises that Rev 5 to emergency plan implementing procedure transmittal & receipt form not received Notification of receipt of rev requested EHALD, 8 C Georgia Power Co 84/02/02 Office of Nuclear Reactor Regulation, Director ip 22130 320 24X Fiche 50-321,84/02/02, page 200331
- --8402080334 Rev 5 to emergency plan. App 1 W/840203 transmittal & receipt form PARKER, L. Appling County, OA 83/08/25 2pp 22130 321 24X Fiche 50-321, 84/02/02, 8402080331
- 8402130452 Rev iS to Procedure HNP-B00B, "Radiation Work Permit" & Rev 1 to Procedure HNP-B036, "Waste Classification & Manifest Reporting Resin Shipments " W/B40202 ltr 9 Georgia Power Ca B4/02/02 31pp 22201 354 24X Fiche 50-321.84/02/02.8402130452
- 8402130478 Emergency Implementing Procedure HNP-8143, "Low Vol Air Sampler Model H-807 V1 " W/840208 ltr - 9eorgia Power Co 84/02/02 9pp 22200 246 24X Fich: 50-321.84/02/02.8402130478
- B402150269 Ack receipt of B31214 & B40127 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/83-29.

 LEWIS: R C Division of Project & Resident Programs 84/02/06 KELLY: R J Georgia Power Co ip 22250 052 24X Fiche 50-346.84/02/06.8402150269
- --8402;50294 IE Insp Repts 50-366/83-29 & 50-321/83-27 on B30820-0930 Visiation identified improper plant review of ralief valve operability procedure, resulting in Tech Spec requirements not being implemented CRLENJAK.R V Region 2. Office of Director PANCIERA, V W Division of Project & Resident Programs. 83/11/08 11pp 22250 060 24X Fiche 50-366.84/02/06.8402150269
- 8402270419 Apvs to emergency procedures including HNP-4420 & 4430 reunusual event notification: HNP-4892; emergency equipment inventory: HNP-8013, airbonne radioactivity concentration determination & HNP-8016. W/840220 ltr SORRELL, E. C. Georgia Power Co. 84/02/16 76pp. 22390. 273 24X Fich: 50-321.84/02/16.8402270419
- 8402240055 Transmittal & title page of deleted Rev 2 to Emergency Plan Implementing Procedure HNP-8139, "Sentox II Oxygen/ Combustible Oas Monitor Operation & Calibr." W/840220 1tr GREENE.T., BORRELL, E C Georgia Power Co 84/02/20 3pp 22373:351 24X Fiche 50~321,84/02/20,8402240055
- 8402290100 Forwards response to NUREQ-0737, Suppl 1 & Generic Ltr 82-33 re comparison of existing plant sys or planned improvements w/positions of Reg Guide 1.97, Rev 2. GUCHALL T. Georgia Power Co. 84/02/21 STOLZ, J. F. Operating Reactors Branch 4. 336pp 22421 088 24X Fiche 50-321,84/02/21,8402290100
- 8402280024 Corrected Page 4 to Rev 15 to Emergency Plan Implementing Procedure HNP-8016. W/840224 ltr & transmittal notice BORRELL; E C Georgie Power Co. 64/02/24 3pp 22401 121. 24X Fiche: 50-321.64/02/24.6406280024

l Financial information

- 8402140453 Forwards Annual Financial Rept for 1982 & related financial qualification info,per 740628 application for amend to CPPR-108 & CPPR-109.
 VAZQUEZ,R.O., ADAMS,L.C Municipal Electrical Authority of Georgia 84/02/10 ADENSAM.E Q. Licensing Branch 4 4pp 22221'309 24X Ficha 50-000,84/02/10,8402140453.
- --8402140457 Annual Financial Rept for 1982 Related financial qualification info encl HANLEY, O. N., STOKLEY, D. L. Municipal Electrical Authority of Quergia. 82/12/31 683pp 22221;313, 24X Ficher 50-000,84/02/10,8402140453

P Operating license stage documents & correspondence

- 8402090408 Partial response to FOIA request for four categories of documents re NUREO-75/087 (NUREO-0800). "SRP for Review of SARs for Nuclear Plants " Review of remaining documents incomplete Forwards App A documents
 FELTON.J M Division of Rules and Records 83/12/30 MADDEN.T (Rayes 8660)er, Fierman, Hays & Handler 4pp 22173 003 24X
 Fiche 50-000,83/12/30,8402090408
- --8402090560 Recommends STS format be revised to require that licensees identify specific components to be covered & related threshold value criteria SNIEZEK.J H Diffice of Inspection & Enforcement, Office of the Director 75/05/13 STOLZ,J F Division of Reactor Licensing (NRR-1975 only) 2pp 22193 038 24X Fiche 50-000,83/12/30,8802090408
- 8402030046 Notification of 840207 meeting w/util in Bethesda,MD to discuss util 831024 & 1220 submittals re organization changes & related Tech Spec changes RIVENDARK.G W Operating Reactors Branch 4 84/01/25 STDLZ,J F Operating Reactors Branch 4 2pp 22091 085 24X Fiche 50-321,84/01/25.8402030046
- B402070054 Forwards SER & technical evaluation repts re NRC post-implementation audit review of facility plant-unique analysis rept for Mark I containment long-term program Mods acceptable per NUREO-0861 STOLZ.J F Operating Reactors Granch 4 84/01/25 BECKMAN.J T Georgia Power Co 3pp 22188 257 24X Fiche 50-321,84/01/25.8402070054
- --8402090069 Safety evaluation re Mark I containment long-term program pool dynamic loads review Mods acceptable per NUREG-0661 * Office of Nuclear Reactor Regulation, Director 64/01/25 2pp 22188 260 24% Fiche 50-321.84/01/23,8402090054
- --8310050295 "Technical Evaluation of Hatch Units 1 & 2 Plant-Unique Analysis Repts "
 RANLET, J D , ECONOMOS, C Brookhaven National Laboratory FIN A-3713 BNL-04243 83/09/30 NRC - No Detailed Affiliation Given 25pp 22188 263 24X Fiche 50-321,84/01/25,8402090054
- --B309290297 "Audit for Mark I Containment Long-Term Program Structural Analysis for Operating Reactors, EI Hatch Nuclear Plant Units 1 & 2: "technical evaluation rept BURRAHONIANN, N, TRIOLO, B . LE.A K Franklin Institute/Franklin Research Center NRC-03-BI-130 TER~C9506~329 83/09/27. SHAM, H NRC NO Detailed Affiliation Given. 44pp 22188 288 24X Fiche 50-321,84/01/25,8402090054
- 8402100179 Discusses time at which hydrogen monitoring is initiated Intent of TMI Item II F 1(d) is to ensure timely hydrogen monitoring in event of core uncovery during LOCA Definition for onset of LOCA Undefinable GUCWALL T Georgia Power Co 84/02/03 STGLZ. J F Operating Reactors Branch 4 2pp 22182 181 24X Fiche 30-321.84/02/03, 8402100179
- B402140436 Application for amend to License DPR-57.changing Tech Spec requirements for HPCI & RCIC syste require systeperability when reactor vessel pressure greater than 150 psig BECKHAM.J T Georgia Power CO 84/02/06 BTGLZ.J F Operating Reactors Branch 4 App 22217 323 24X Fiche 50-321, 84/02/06, 8402140436
- --8402140448 Proposed Tech Specs 3 5-6-8 % 3 5-16-17 re changes to HPCI % RCIC sys requirements * Georgia Power Co 84/02/06 5pp 22219 327 24X Fiche 50-321.84/02/06.8402140436
- ~~8402140456 "HPCI/RCIC Operability Limit EI Hatch Nuclear Plant ~ Unit 1 "
 9 General Electric Co 84/01/16 Spp. 22219 332 24X Fiche 50~321,84/02/06.8402140436
- 8402150197 Withdraws 831128 request for Tech Spec changes allowing plant operation w/o forced recirculation flow QUCWA, L.T. Georgia Power Co. 84/02/06 BTQLZ.J.F. Operating Reactors Branch 4. ip 22245.136 24X Fiche 50-321,84/02/06,8402150197
- 8402220514 Application for amend to Licenses DPR-57 & NPF-5, consisting of Tech Spec changes re APRM, rod block monitor & Tech Spec improvements program Affidavit and Tech Spec withheld (ref 10CFR2 790)

 BECKHAM, J T Georgia Power Co 84/02/06 STDLZ, J F Operating Reactors Branch 4 15pp 22331 324 24X Fiche 50-321,84/02/06,8402220514.

- 2140441 Informs that NRC has agreed to issue changed pages re emoval of ref to Tech Spec 4 7 E concerning 10CFR50, App J, er 840127 telcon UCMA, L T Georgia Power Co 84/02/07 STOLZ, J F Decrating eactors Branch 4 1p 22227 112 24X Fiche 50-321,84/02/07, 402140441
- 2160228 Forwards Rev 1 to Procedure HNP-4848, "Determination of xtent of Core Damage Under Accident Conditions." per NRC equest & NURFO-0737, Item II 8 3 UCWA, L T Georgia Power Co 84/02/10 STOLZ, J F Operating eactors Branch 4 1p 22276 317 24X Fiche 50-321,84/02/10,402160228
- 402160232 Rev I to Procedure HNP-4848. "Determination of Extent of Core Damage Under Accident Conditions" OREENE.T Georgia Power Co 83/10/12 12pp 22276 318 24X Fiche 50-321,84/02/10.8402160228
- 2240145 Forwards response to request for add1 justification for reposed completion schedule re NUREO-0737. Item II 8 3. Post-Accident Sampling Capability "Site verfication tests lil be completed by 840901 UCMAL T Georgie Power Co 84/02/20 STOLZ. JF Operating eactors Branch 4 5pp 22375 071 24X Fiche 50-321,84/02/20,402240145
- 2270215 Forwards containment post-accident profiles utilized in OCFR50 49 qualification program & extended drywell tamp nalysis Drywell temp analysis withheld (ref IOCFR2 770) JCHALT Georgia Power Co 84/02/24 STOLZ.J F Operating sactors Branch 4 2pp 22386 034 24X Fiche 50-321,84/02/24,802707012
- 1022/0240 "Post-Accident Temp & Pressure Profiles" GUIRK.J F Gaorgia Power Co 84/02/24 7pp 22386 036 24X Fiche 50-321,84/02/24.8402270215

inspection reports, IE Bulletins & correspondence

- 2140350 Forwards IE Insp Repts 50-321/83-34 & 50-366/83-36 on 31212-16 No violations or deviations noted NGE.H C Division of Project & Resident Programs 84/01/06 LLY.R J Georgia Power Co 2pp 22220 101 24X che 50-321.84/01/06.8402140350
- 102140356 IE 1nsp Repts 50-321/83-34 & 50-366/83-36 on 831212-16 No 102140336 IE Insp Repts 50-321/83-34 & 50-366/83-36 on 831212-16 violations or deviations noted Major areas inspected mgt & administrative controls & review of annual environ menitoring rept for period ending 821231 CUNNINGHAM. A L. Region 2. Office of Director MONTGOMERY.D M Division of Engineering & Operational Programs 84/01/05 8pp 22220 103 24X Fiche 50-321.84/01/06.8402140350
- 140147 Forwards IE Insp Repts 50-321/83-34 & 50-364/83-39 on 1219-22 No violations or deviations noted NCE: H C Division of Project & Resident Programs 84/01/17 LLY: R J Georgia Power Co 2pp 22230 078 24X che 50-321.84/01/17.8402140147
- 02140154 IE Insp Repts 50-321/83-36 & 50-366/83-39 on 831219-22 No violations or deviations noted Major areas inspected health physics preparation activities re recirculation piping replacement project & followup review of LERs KAHLE.J B Region 2. Office of Director BARR.K P Division of Engineering & Operational Programs 84/01/13 Spp 22230 080 24X Fiche 50-321.84/01/17.8402140147
- 120153 IE Info Notice 84-04, "Steam Binding of Auxiliary Feedwater mps" Svc list encl
 RDAN.E L Division of Emergency Preparedness & Engineering sponse (Post 830103) 84/01/25 Consolidated Edison Co of New rk. Inc 120pp 22058 001 24X Fiche 50-000.84/01/25.8312120153
- 280239 Forwards IE Insp Repts 50-321/83-37 & 50-366/83-40 on 1221-840120 No violations or deviations noted VGE.H C Division of Project & Resident Programs 84/01/31. LY.R J Georgia Power Co. 2pp 22379 267 24x che. 50-321.
- 12280246 IE Insp Repts 50-321/83-37 & 50-36/83-40 on 831221-840120 to violations or deviations noted Major areas inspected fech Spec compliance operator performance plant operations. He practices & mgt practices RREENJAK.R V , HOLMES-RAY.P. Region 2, Office of Director 'ANCIERA,V Division of Project & Resident Programs. 84/01/28 tpp 22399 271 24% Fiche 50-321,84/01/31,8402280239

- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls" Bvc list encl
 JURDANIE L Division of Emergency Preparedness & Engineering Response (Pust 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000.84/02/03.8401190016
- 8401190017 IE Bulletin 84-01. "Gracks in BWR Mark I Containment Vent Headers " Bvc list encl DEYDUNO,R C Director's Office, Office of Inspection and Enforcement B4/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 156 24X Fiche 50-000,84/02/03,8401190017
- 8402150269 Ack receipt of 831214 & 840127 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-366/83-29 SO-SECTOL-27
 LEWIS.R C Division of Project & Resident Programs
 KELLY.R J Georgia Power Co 1p 22250 052 24X
 Fiche 50-366 84/02/06 8402150269
- --8402150290 Forwards IE Insp Repts 50-366/83-29 & 50-321/83-27 on 830820-0930 & notice of violation LEMIS:R C Division of Project & Resident Programs B3/11/15 KELLY:R J Qeorgia Power Co 2pp 22250 057 24X Fiche 50-366.84/02/06.8402150269
- --8402150294 IE Insp Repts 50-366/83-29 & 50-321/83-27 on 830820-0930 Violation identified improper plant review of relief valve operability procedure.resulting in Tech 8psc requirements not being implemented CRLENJAK.R V , HOLMES-RAY.P , ROOSE, J F Region 2, Office of Director 83/11/08 11pp 22250 060 24X Fiche 50-366,84/02/06,8402150269
- 8402280405 Responds to IE Bulletin 84-01 re insp for cracks in Mark I containment tarus vent header No apparent cracking or relevant indications found on Unit 1 No add1 cracking found beyond original cracking on Unit 2

 BECKHAM.J T Georgia Power Co 84/02/10 O'REILLY, J P Region 2, Office of Director 2pp 22407 139 24X Fiche 50-321,84/02/10,8402280405
- 8401190041 IE Info Natice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R) " Svc list enclasses enci JARDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259, 24X Fiche 50-000,84/02/13,8401190041
- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '"
 Svc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24X Fiche 50-000,84/02/14,8401170039
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Bvc list encl JURDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366 142 24X Fiche 50-000,84/02/15,8401190045
- 8402280449 Ack receipt of 840208 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-366/83-38 LEWIS, R C Division of Project & Resident Programs 84/02/15 KELLY.R J Georgia Power Co ip 22403 009, 24X Fiche 50-366.84/02/15,8402280445
- --8402280466 Responds to NRC 840111 ltr re violations noted in IE Insp Repts 50-321/83-35 & 50-366/83-38 Corrective actions reserved air actuator air lines reinstalled properly & safety-related maint requirements examined GUCHA:L T Georgia Power Co 84/02/08 D'REILLY, J.P. Region 2: Office of Director 3pp 22403:010 24X Fiche 50-366,84/02/15; 8402280445
- -8402280473 Forwards IE Insp Repts 50-321/83-35 & 50-366/83-38 on 831121-1216 & notice of violation LEWIS.R C Division of Project & Resident Programs 84/01/11 KELLY.R J Georgia Power Co 2pp 22403:013 24X Fiche 50-366,84/02/15,8402280445
- ---B402280485 IE Insp Repts 50-321/83-35 & 50-366/83-38 on B31121-1216 Violation identified work on RHR sys testable check valve performed w/o documented instructions, procedures or drawings CRLENJAK, R.V., HOLMES-RAY, P., ROGGE, J. F. Region 2, Office of Director. 84/01/09 7pp 22403 016, 24X Fiche 50-366,84/02/15, B402280445,
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co. of New York, Inc. 116pp 22366 024 24X Fiche 50-000,84/02/21,8401190062

- 8401190046 IE Info Notice 84-11. "Training Program Deficiencies "
 Svc list encl
 JDRDAN.E L Division of Emorgency Proparadness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- 0401190067 IE Info Notice 84-12. "Failure of Soft Seat Valve Seals " Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060 24% Fiche 50-000,84/02/27,8401190067
- R Periodic operating reports & related correspondence
- 8402140334 Monthly operating repts for Jan 1984 W/840210 ltr RAFEED1E, D P . NIX. H C Georgia Power Co 84/01/31 14p 22220 860 24X Fiche 50-321,84/01/31,8402140334
- 8402150391 Forwards monthly operating repts for Jan 1984 NIX.H C Georgia Power Co 84/02/10 Division of Licensing 1p 22241 350 24X Fiche 50-321,84/02/10,8402150391
- V Operator Examinations
- 8402140316 Forwards summary of 840111 meeting w/util re training & certification of licensed operator candidates & results of recent NRC administered exams
 DANCE, H C Division of Project & Resident Programs 84/02/03
 KELLY, R J, Georgia Power Co 2pp 22228 245 24X
 Fiche 50-321,84/02/03,8402140316
- DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION
- A. Application/construction stage documents & correspondence
- 8402090003 Responds to FDIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A, B & C documents
 FELTON.J M Division of Rules and Records 83/10/31
 ROBENBAUM.D M Technical Analysis Corp 19pp 22193 292 24x
 Fiche 50-000,83/10/31,8402090003
- --8402090088 Marked-up trip rept of 820811-13 Caseload Forecast Panel site visits re const & preoperational testing status Related info encl info encl
 OllBERT.R.A Licensing Branch 2 83/10/31 Licensing Branch 2
 bp 22174 074 24% Fiche 50-000.83/10/31.8402090003
- --8402090187 Handwritten notes & calculations re const activities & fuel load preparation * NRC No Datailed Affiliation Given 80/05/08 4pp 22176:199 24X Fiche 50-000,83/10/31.8402070003
- --8402070190 Trip rept of Caseload Forecast Panel 820811-13 site visits restatus of const & preoperational testing evaluation Related info encl 9TLBERT,R A Licensing Branch 2 82/08/19 Licensing Branch 2 3pp. 22196 203. 24X Fiche 50-000.83/10/31.8402090003
- B402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILK.8 J Office of the Secretary of the Commission 83/12/14 Public Document Branch. 1p 22281 023. 24X Fichs 80-000,83/12/14. B4021A0003
- --8402160025 Staff requirements memo re 830415 discussion of facility order in Washington DC
 CHILK, B J Office of the Secretary of the Commission 83/0
 Office of the Secretary of the Commission in 22281 056
 Fiche 30-000.83/12/14.8402160003 83/04/15
- #312120136 Board Notification #84-011 discusses NRC use of terms "important to safety" & "safety-related" #1818HNUT.D O Division of Licensing #84/01/18 PALLADING Commissioners 72pp 22241-008 24% Fiche 50-000.84/01/18, #8312120136
- 8401190012 Board Notification 84-013. forwards info re Transamerica Delaval, Inc emergency diesel generators.
 EIBENHUT, D. G. Division of Licensing 84/01/24 PALLADINO, N. GLINSKY, V. ROBERTS, T. Commissioners. 10pp 22054 346 24.
 Fiche 30-000, 84/01/24, 8401190012

- B401190015 Board Notification 84-018 provides info re failure experience of Transamerica Delaval emergency diesel generators in marine svc EISENHUT.D G Division of Licensing 84/01/27 PALLADINO.N J GILINSKY, V., RODERTS.T N Commissioners 385pp 22093 027 2 Fiche 30-000.84/01/27.8401190015
- 8402170061 Notification of 840210 meeting w/Transamerica Delayal, Inc (TDI) in Bethesda, MD to discuss program plan proposed by TDI
 Owners Group to qualify diesel generators
 CARUSDA Division of Licensing 84/02/04 BERLINGER.C Division
 of Licensing 2pp 22312 339 24X Fiche 50-000,84/02/06,
- 8402160639 Forwards list of question re PRA for completion of review 1F response cannot be provided within 30 days of receipt of 1tr, schedule for response requested BCHWENCER, A Licensing Branch 2 B4/02/09 POLLOCK, M. 9 Long 191and Lighting Co. 10pp. 22301 348 24X Fiche 50-322,84/0P/09, B402160639
- 8402140091 Notifies that diesel generator 102 successfully completed 7-day endurance run Linear indications found on four exposed cylinder areas Info provided for 840222 hearing Related correspondence
 ELLIS,T S Hunton & Williams ELLIS,T S Long Island Lighting Co
 84/02/10 BIENNER,L , FERGUSON, C A , MORRIS,P A Atomic Safety and
 Licensing Board Panel 2pp 22217 234 24X Fiche 50-322,84/02/10. 8402140091
- B401190059 Board Notification 84-032 provides add1 info on environ qualification Submittal augments info in Board Notifications B4-004 & 84-007 EIBENNUT, D G Division of Licensing 84/02/13 Atomic Bafety and Licensing Board Panel 10pp 22314 204 24X Fiche 50-000,84/02/13.8401170059 Atomir Bafetu and
- 8401190068 Board Notification 84-033 provides "Sys Interaction Program," task action plan for Unresolved Safety Issue A-1/ Distribution list encl EISENHUT: D 0 Division of Licensing 84/02/16 PALLADINO Commissioners 8pp 22482 091 24X Fichs 50-000,84/02/16, 8401190068
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 8402130231 Forwards monthly status of equipment summary list, including balance-of-plant & NS69 equipment, per SER Issue B. "Dynamic Qualification " Rept forwarded to BNL, per RL Tedesco 810128 OFFICE OF Nuclear Reactor Regulation, Director 52pp 24X Fiche 50-328,84/02/08,8402150231
- F Security, medical, emergency & fire protection plans
- B402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 - Jul 1983
 CHILK, S J Office of the Secretary of the Commission 83/12/14
 Public Document Branch 1p 22281 023 24X Fiche 50-000.83/12/14 8402160003
- --8402160017 Staff requirements memo re 830405 briefing in Washington DC approving memorandum & order on emergency plan CHILK.B J Office of the Secretary of the Commission 83/04/08 PLAINE.H H Office of the General Coursel Ip 22281 054 24X Fiche 50-000, 83/12/14, 8402160003
- 8402060405 Forwards Rev 2 to Emergency Preparedness Implementing Frocedures 4-7, "Public Affairs Emergency Organization," incorporating changes resulting from administrative review Revised table of contents encl MCGAFFREY,8 R Long Island Lighting Co 84/01/20 DENTON,H R Office of Nuclear Reactor Regulation, Director. App 22086 18724X Fiche 50-322,84/01/20,8402060405
- --8402060407 Rev 2 to Emergency Preparedness Implementing Procedures 4-7. "Public Affairs Emergency Organization."

 * Long Island Lighting Co 83/12/21 44pp 22086 193 24X Fichs 30-322,84/01/20,8402060405
- 8402220463 Forwards IE Insp Rept 50-322/83-37 on 831205-09 No violations noted NARTIN, T T Divi MARTIN, T T Division of Engineering & Technical Programs 84, POLLOCK, M 8 Long Island Lighting Co 2pp 22339 274 24X Fiche 50-322,84/02/06,8402220463 84/02/06
- --8402220467 IE Insp Rept 50-322/83-37 on 831205-09 No violations noted Major areas inspected follows emergency preparedness items from 820823-0902 appraisal MOJNAB.E J. CROCKER.H W Region 1. Office of Director B 14pp 22339 276 24X Fichs 50-322.84/02/06.8408220463

- B402170405 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per 810709 Generic Ltr 81-27 Who request, entire plan will be placed in FDR SCHWENCER. A Licensing Branch 2 84/02/09 POLLACK. M 8 Long Island Lighting Co 3pp 22313 176 24X Fishe 50-322, 84/02/09, 84/02/09
- B402150119 Discusses review of util offsite emergency plan under request from NRC FEMA makes recommendations to NRC but ultimate judgement of sufficient level of planning & preparedness lies w/NRC W/Certificate of Svc JETI.0 W Federal Emergency Management Agency B4/02/10 BROWN H Kirkpatrick, Lockhart, Hill. Christopher & Phillips 4pp 22249 265 24% Fiche 50-322,84/02/10.8402150119
- 8402220198 Forwards Rev 3 to "Public Emergency Procedures Maps for Yone R" Nev includes improved maps addl info on classification of radiological emergencies & info for disabled & hearing impaired MCCAFFREY, B R Long Island Lighting Co 84/02/17 DENYON, H R Office of Nuclear Reactor Regulation, Director 3pp 22330 016 PAX Ficho 50-322,84/02/17,8402220198
- --8402220203 Rev 3 to "Public Emergency Procedures Maps for Zone R "
 * Long Island Lighting Co 84/02/17 22pp 22330 019 24X
 Fiche 50-322,84/02/17,8402220198
- G Adjubicatory correspondence
- 8402230429 Responds to FOIA request for SECYs 83-32,986,228,228A,240,246 & 261 to be placed in PDR Forwards SECYs 83-228A,261 & 240 SECYs 83-228.240,246 & 261 partially withheld (ref FDIA Exemption 5) SECYs 83-32,988 & 28A available in PDR FELTON.J M Division of Rules and Records 83/12/07 GRADER.L D NUS Corp 4pp 22371 269 24X Fiche 50-000,83/12/07.8402230429
- --8402230439 Discusses disposition of Suffolk County motion for Commission ruling on LiLCO emergency preparedness plan MALSCH.M G Office of the General Counsel SECY-83-240 83/06/20 53pp 22371 271 24X Fiche 50-000.83/12/07,8402230429
- B402090081 Further response to FOIA request for IE Insp Rept 79-19, associated notice of proposed imposition of civil penalties, notice of violation & order to show cause Forwards App A documents Documents also available in PBR FELTON.J H. Division of Rules and Records 83/12/20 HAMLIN,J B Shaw. Pittman. Potts & Troubridge 4pp 22186 104 24X Fiche 50-000.83/12/20,8402090081
- --8402090193 Responds to Chairman Ahearne 800923 request to provide info re Shoreham to Representative Lent June-Sept 1982 latest projected fuel load date CRANE.P Office of the General Counsel 80/10/09 SUERHANN, J Office of Congressional Affairs ip 22188 185 24X Fiche 80-000,83/12/20,8402090081
- B402010085 Order granting B3112B motions to strike testimony of FC Finlayson. GC Minor & EP Radford re Suffalk County Contentions 65,23 D t 23 H Testimony irrelevant to contentions
 LAURENSON, J A Atomic Safety and Licensing Board Panel 84/01/11
 Offlice of the Executive Legal Director 7pp 22042 179. 24X
 Fiche 50-322,84/01/11,8402010085
- 8402030201 Motion of Governor M Cuamo, representing State of NY, to submit testimany on Emergency Planning Contention 65 Motion should be granted based on timeliness & presentation of info not contained in record Cartificate of Sav encl PALCMINO, F G New York, State of 84/01/24 Atomic Safety and Licensing Board Panel 78pp 22067 259 24X Fiche 50-322,84/01/24.8402030201
- 8402020225 Requests that PF Righm be removed from svc list.
 EARLEY, A F Harmon & Weiss EARLEY, A F Utility Safety
 Classification Group 84/01/30 SHOEMAKER, C J Atomic Safety and
 Licensing Board Panel 1p 22057 078 24X Fiche 50-322, 84/01/30,
 8402020225
- 8402030145 Forwards response to LILCO & NRC objections to intervenor proposed emergency planning contentions modified to reflect Rsv 3 to LILCO plan Notification of issuance of order ruling on objections requested LETSCHE, K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips, LETSCHE, K J Suffolk County, NY 84/01/30 LAURENSON, J A . KLING, J. R., SHON, F J Atomic Safety and Licensing Board Panel ip 22068 024 24X Fichs 50-322,84/01/30.8402030145

- --B402030148 Response opposing LILCO & NRC objections to intervenor proposed emergency planning contentions modified to reflect Rev 3 to LILCO plan Certificate of Svc encl LETSCHE, K J Suffalk County, NY LETBCHE, K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips B4/01/30 Atomic Bafat, and Licensing Board Pamel 72pp 22068 025 24X Fiche 50-322,84/01/30,8402030145
- 8402080054 Requests that consultant PF Riehm be removed from svc list Related correspondence EARLEY.A F Hunton & Williams EARLEY.A F Utility Safety Classification Group 84/01/30 SHOEMAKER.C J Atomic Bafety and Licensing Appeal Panel 1p 22128 075 24X Fiche 50-322,84/01/30,6402080054
- 8402020235 Order confirming emergency planning proceeding schedule changes reached at 840127 hearing in Riverhead NY LAURENSON, J. A. Atomic Safety and Licensing Board Panel. 84/01/31 2pp 22037 036 24% Fiche 50-322,84/01/31 8402020235
- 8402030151 Corrected notice of appearance in proceeding Certificate of Svc encl PALOMINO.F G New York, State of 84/01/31 4pp 22068 097 24x Fiche 80-322.84/01/31.8402030151
- 8402070130 Forwards Speck 840125 ltr & Dircks 840126 response to FEMA review of util offsite emergency plan Certificate of Svc ent; BORDENICK, B M Hearing Branch 3 84/01/31 LAURENSON, J A ,
- BORDENICK.B M Hearing Branch 3 B4/01/31 LAURENSON, J A , KLINE, J R , SHON, F J Atomic Bafety and Licensing Board Panel 4pp 22100 201 24X Fiche 50-322,84/01/31,8402070130
- ~-8402070134 Inquires whether FEMA should continue, modify or terminate NRC review of util emergency plan given Governor Cuomo recent interpretation as to legal authority of util to implement plan SPECK, 8 W Federal Emergency Management Agency 84/01/25 DIRCKS, W J Office of the Executive Director for Operations App 22100 205 24% Fiche 50-322,84/01/31.8402070130
- ~-8402070139 Responds to 840125 ltr inquiring as to whether FEMA should continue, modify or terminate review of offsite emergency plan FEMA should continue review & submit results by previously agreed upon completion date of 840201 DIRCKS,N J Office of the Executive Director for Operations 84/01/26 SPECK,S W Federal Emergency Management Agency ip. 22100 209 24X Fiche 50-322,84/01/31,8402070130
- 8402060185 Forwards motion for leave to file rebuttal testimony on Contention 23,per ABLB 840127 orel order Rebuttal testimony will be served 840202 LETSCHE.K J Kirkpatrick, Lockhart, Hill. Christopher & Phillips LETSCHE.K J Suffolk County, NY 84/02/01. LAURENBON, J A . KLINE.J R . SHOWLF J A topic 849ety and Licensing Board Panel ip 22088 179 24% Fiche 50-322.84/02/01.8402060185
- --84020601BB Motion for leave to file rebuttal testimony of Contention 20 re evacuation shadow phenomenon Certificate of 8vc encl.
 LETSCHE, K. J. Suffolk County, NY LETSCHE, K. J. Kirkpatrick,
 Lockhart, Hill, Christopher & Philips 84/02/01 Atomic Bafety
 and Licensing Board Panel 9p. 22088 180 24X
 Ficho 5Q-322,84/02/01,8402060185
- 8402070006 Advises that NRC will not seek leave to file rebuttal testimony on Group I emergency planning contentions BORDENICK, B M Hearing Branch 3 84/02/01 LAURENSON, J A., SHON, F J , KLINE, J R Atomic Safety and Licensing Board Panel 22102 323 24X Fiche 50-322,84/02/01,8402070006
- 8402070033 Advises of intention not to seek leave to file rebuttal testimony on Group I emergency planning contentions BORDENICK, B M Hearing Branch 3 84/02/01 LAURENSON, J A , SHON, F J , KLINELJ R Atomic Safety and Licensing Board Panel 1, 22102 353 24X Fiche 50-322,84/02/01,8402070033
- 8402070060 Forwards S Schwart: 840201 memo re info on FEMA review of LILCO transition plan REPKA.D A Hearing Branch 3 84/02/01, LAURENSON.J.A. KLINE.J R. SHON.F J Atomic Safety and Licensing Board Panel 2pp. 22102 034 24X Fiche, 50-322,84/02/01,8402070040
- --B4020606i0 Informs that FEMA findings & determinations re review of offsite emergency plan will not be provided until 840301 FEMA region review of plan not expected until Mid-Feb BCHWARTZ. B Division of Emergency Preparedness & Engineering Response (Post 830103) 64/02/01 CHRISTENBURY. E Hearings Division 1p 22102 336 24X Fiche 50-322.84/02/01,0402070060

- 8402060071 Order requesting document discovery requests on Suffolk County proposed supplemental dissel generator contentions by 840217 Countsey notification encl
 BRENNER, L Atomic Safety and Licensing Board Penel 84/02/02 Office of the Executive Legal Director 5pp 22088 232 24X Fiche 50-322.844/02/02.8402060071
- B402060193 Requests that F Palomino & MB Ashare be added to svc list that DJ Gilmartin & D Wiles be deleted from svc list
 LAURENSON, J A Atomic Safety and Licensing Board Panel 84/02/02
 Docketing & Services Branch ip 22088 191 24X
 Fiche 50-382.84/02/02.8402060193
- B402070277 Notice of completion of training matls Certificate of Svc encl MONAGHAN, J A Long Island Lighting Co MONAGHAM, J A Hunton & Williams 84/02/02 7pp 22101 308 24X Fiche 50-322.84/02/02, 8402070277
- 8402070199 Statement by Governor Cuomo representing State of NY supporting Suffalk County motion for leave to file testimony on Contention 23 Certificate of Svc encl 24HNLEUTER, R. J., CUOMO. M., PALOMINO, F. G. New York, State of 84/02/03 Atomic Safety and Licensing Board Panel App 22100 024 24X Fiche 50-322,84/02/03,8402070199
- 8402070320 Memorandum & order ruling on intervenors proposed emergency planning contentions modified to reflect Rev 3 of util plan Util & NRC objections to contentions modified to reflect Rev 3 ruling as set forth in body of order LAURENBON, J A Atomic Bafety and Licensing Board Panel B4/02/03 Suffelk County, NY 14pp 22095 068 24X Fiche 50-322.84/02/03, 84002/03/02/0
- 8402080167 Requests NRC undertake complete insp of each of 24 cylinder heads installed in facility diesols for compliance w/applicable stds IE Insp Rept 30-322/83-25 re Transamerica Delaval.Inc diesel generators encl DYNNER.A.R. Kirkpatrick, Lockhert, Hill, Christopher & Phillips 84/02/03 DETONN.H R Office of Nuclear Reactor Regulation, Director 10pp 22128 207 24% Fiche 50-322,84/02/03,8402080167
- 8402070R64 Affidavit of SO Christenson re Suffolk County Contention 1 on emargency diesel generators Each generator at 4.890 horsepower & 3,500 kW is overrated & undersized to meet operating requirements of FSAR Section 8 3 1 1 5 CHRISTENBON.8 Suffolk County, NY 84/02/06 9pp 22101 016 24% Fiche 50-322.84/02/06.8402070264
- --B402070271 Affidavit of QD Eley re Buffolk County Contention I on amergency diesel generators Conclusions identical w/Christenson Certificate of Svc encl ELEY, Q D. Buffolk County, NY 84/02/06 3pp 22101 025 24X Fiche 50-322, 84/02/06 8402070264
- 8402090126 Answer apposing Buffolk County 840201 motion for leave to file rebuttal testimony on Contention 23 re evacuation shadow phenomenon Leave to file own rebuttal if ASLS accepts motion requested W/Certificate of Svc CHRISTMAN.J N. Long Island Lighting Co. CHRISTMAN.J N. Hunton & Williams 84/02/06 Atomic Sefety and Licensing Board Panel 12pp. 22161 349 24X Fiche 50-322.84/02/06.8402090126
- 8402070153 Memorializes 840203 telcon re-production of documents Request for expedited production of documents & motion to compel expedited production of documents for review of emergency plan encl Related correspondence IRWIN, D.P. Hunton & Williams IRWIN, D.P. Long Island Lighting Co. IRWIN, D.P. Utility Bafety Classification Group. 84/02/06 ZAHLEUTER, R.J. New York, State of 8pp 22157 198, 24X Fiche, 50-322, 84/02/06, 8402070153
- --8402090157 Request for expedited production of documents re State of NY review of LILCO offsite radiological emergency response plan, Documents requested by 840208
 IRWIN,D P Long Island Lighting Co IRWIN,D P Hunton & Williams 84/02/06 Atomic Safety and Licensing Board Panel Bpp. 22157:206 24X Fiche 50-322:84/02/06.8402090153
- --B402090163 Motion to compel expedited production of documents re State of NY review of offsite radiological emergency response plan, Certificate of Svc encl.
 IRWIN, D P. Long Island Lighting Co. IRWIN, D P. Hunton & Williams B4/02/06 Atomic Safety and Licensing Board Panel.
 7pp. 22157:214, 24X Fiche.50-322.84/02/06.8402090153.
- B402140095 Notifies that NRC has no objection to Suffolk County motion for leave to file rebuttal testimony on Contention 23 dtd B40201 Two county witnesses sponsoring rebuttal should appear immediately after four state witnesses on B40223 BRRDENICK, B. M. Hearing Branch 3 B4702/06 LAURENSON, J. A. KLINE, J. R., SHON, F. J. Atomic Safety and Licensing Board Panel 2pp 22217; 236 24X Fiche 50-322, 84/02/06, 8402140095

- 8402100025 Discusses need for immediate staff insp of cylinder heads at facility in light of Vendor Insp Program Repts 99900334/83-02 % 03 re nonconformances in implementation of QA program for production of replacement heads DYNNER. A R Kirkpatrick Lockhart Hill, Christopher & Phillips 84/02/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 53pp 22230 023 24X Fiche 50-322,84/02/07,8402100025
- B402100133 Response to Suffolk County motion to admit supplemental diesel generator contentions Litigation of diesel generator issues recommended Unerscuted affidavit of JC Kammeyer encl MINION.L E Long Island Lighting Co MINTON.L E Hunton & Williams 84/02/07 Atomic Bafety and Licensing Board Panel 67pp 22182 289 24X Fishe 50-322.64/02/07.8402100133
- --8402100135 Comments on insp of new rocker arm shaft bolts installed on diesel generators Concurrence that further insp unnecessary requested per ABLB 830827 order Certificate of Svc uncl ELLIS.T 5 Aunton & Williams ELLIS.T 5 Long Island Lighting Co 83/09/22 GODDARD.R Hearing Branch 3 DYNNER A R Kirkpatrick, Lockhart Hill. Christopher & Phillips 40pp 22182 356 24X Fiche 50-322.84/02/07.8402100133
- 8402100104 Notice of hearing on 840223 in Hauppauge, NY SHON, F. J. Atomic Safety and Licensing Board Panel 84/02/08 ip 22182 083 24% Fiche 50-322, 84/02/08, 8402100104
- 8402100123 Motion to change emergency planning schedule confirmed in ASLB 840201 order FEMA findings & determinations on plan uill not be available until 840301 Certificate of 8vc encl LANPHER.L C Suffolk County. NY LANPHER.L C Kirkpatrick. Lockhart. Hill. Christopher & Phillips 84/02/08 Atomic Safety and Licensing Board Panel 7pp 22182 076 24x Fiche 50-322.84/02/08.8402100123
- 8402100129 Order establishing 840213 as final date for submittal of response to LILCO motion to compel expedited production of documents re emergency planning 8HON-TJ Atomic Safety and Licensing Board Panel 84/02/08 N
- 8402100175 Motion for reconsideration of order scheduling document discovery requests on Suffolk County proposed supplemental diesel generator contentions Certificato of Bvc encl DYNNER, A R New York, State of DYNNER, A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips 84/02/08 Atomic Safety and Licensing Board Panel 10pp 22162 162 24X Fiche 50-322,84/02/09, 8402100175
- 8402:30165 Forwards executed affidavit of JC Kammeyer Affidavit replaces unexecuted copy attached to LILCO response to Buffolk County motion to admit supplemental diesel generator contentions

 EARLEY, A F Hunton & Williams EARLEY, A F Long Island Lighting Co 84/02/08 BRENNER, L, MORRIS, PA, FERGUSDN, QA Atomic Safety and Licensing Board Panel ip 22204 107 24X

 Fiche 50-322.84/02/08.8402130165
- --8402130170 Affidavit of JC Kammayer supporting LILCO response to Suffolk County proposed supplemental diesel generator contentions KAMMEYER, J C Long Island Lighting Co 84/02/07 14pp 22204 112 24X Fiche 30-322.84/02/08.8402130165
- 8402130135 Motion for leave to file response to LILCO answer opposing Suffolk County motion for leave to file rebuttal testimony on Contention 23 re emergency planning Certificate of Svcenci McMurray, C M Suffolk County, NY MCMURRAY, C M Kirkpatrick, Lockhart, Hill, Christopher & Phillips 84/02/08 Atomic Safety and Licensing Board Fanel 8pp 22249 279 24X Fiche 30-322.84/02/08.8402150135
- 8402150159 Advises that facility will be physically ready to load fuel in Mar 1984. Litigation over diesel generators will probably be completed before Summer 1984 REVELEY, W.T. Hunton & Williams REVELEY, W.T. Long Island Lighting Co. 84/02/08 BRENNER, L., FERGUSON, 9 A., MORRIS, P.A. Atomic Bafety and Licensing Doard Fanel 1p 22245 323 24X Fiche 50-322,84/02/08,8402150159
- B402150164 Response supporting Suffolk County 840127 motion to admit supplemental diesel generator contentions. Certificate of Bvc encl PALDMING, F 9 New York, State of 84/02/08 Atomic Safety and Licensing Board Panel 5pp 22245-339 24X Fiche 50-322,84/02/08,84/0150164

- 3402100167 Order for responses to Suffolk County motion for reconsideration of order scheduling document discovery requests on Suffolk County proposed supplemental dissel generator contentions W/countery notification MORRIS.P A Atomic Safety and Licensing Board Panel 84/02/09 Office of the Executive Legal Director 4pp 22:82 204 24X Fiche 50-322.84/02/09,8402100167
- 3402130240 Memorandum scheduling oral argument for 840327 in Bethesda MD Formal argument order will be issued early in Mar 1984 SHGEMAKER.C J. Atonic Safety and Licensing Appeal Panel 84/02/09 2pp 22200 223 24X Fiche 50-322.84/02/09.8402130240
- 3402150110 Response upposing Suffolk County 840208 motion to change schedule W/Certificate of Svc IRWIN.D P Hunton & Williams 84/02/09 Atomic Safety and Licensing Board Panel Spp 22249 324 24X Fiche 50-322,84/02/09,8402150110
- 3402(50)13 Objections to ASLB 840203 memorandum & order ruling on intervenors proposed modified emergency planning contentions Proposed mods to Contentions 15 E.24 P.61 C 2.
 71 A & 71 C should be admitted Certificate of Svc encl LETSCHE.K J Suffolk County, NY LETSCHE.K J Kirkpatrick, Lockhart. Will. Christopher & Phillips 84/02/09 23pp 22249 332 24X Fiche 50-322.84/02/09.8402(50)13
- 3402440047 Motion to admit supplemental testimony of MC Cordero, JA Weismantle, EB Lieberman & DS Mileti in response to State of NY testimony on Phase II emergency planning Contention 45 Related correspondence ZEUGIN. L B Long Island Lighting Co ZEUGIN. L B Hunton & Williams 84/02/10 Atomic Safety and Licensing Board Panel App 22217 203 24X Fiche 50-322,84/02/10,8402140047
- --8402140049 Notion to compel expedited production of State of Ny emergency preparedness plan IRWIN.D P Long Island Lighting Co IRWIN.D P Hunton & Williams 84/02/10 Atomic Safety and Licensing Board Panel 11pp 22219 207 24X Fichs.50-322.84/02/10.8402140047
- --8402140051 Request for production of State of NY emergency preparedness plan Certificate of Svc encl IRWIN.D P Long Island Lighting Co IRWIN.D P Hunton & Williams 84/02/10 New York. State of 4pp 22219 218 24x Fiche 50-322,84/02/10,8402140047
- --B40214005B Supplemental testimony of MC Cordard. JA Weismantle, EB Lieberman & BS Milett in response to State of NY testimony on Phase II emergency planning Contention 65 Certificate of Svc encl CORDARO.M C . WEISMANTLE, J A . LIEBERMAN, E B Long Island Lighting Co 84/02/10 30pp 22219,222 24% Fiche 50-322,84/02/10,8402140047
- 3402140075 Request to make change to Attachment A to util response to Buffolk County motion to admit supplemental diesel contentions Certificate of Svc encl EARLEY.A F Long Island Lighting Co EARLEY.A F Hunton & Williams 84/02/10 Atomic Safety and Licensing Board Panel 3pp 22217 172 24X Fiche 50-322.84/02/10.8402140075
- 1402140102 Motion to strike portions of State of NY direct testimony on emergency planning Contention 65 Certificate of Svc encl IRWIN.D P Long Island Lighting Co IRWIN.D P Hunton & Williams 84/02/10 Atomic Safety and Licensing Doard Panel 89pp 22217 264 24% Fiche 50-322.84/02/10.8402140102
- 3402150119 Discusses review of util offsite emergency plan under request from NRC FEMA makes recommendations to NRC but ultimate judgement of sufficient level of planning & preparedness lies w/NRC W/Certificate of Bvc JET1.9 W Federal Emergoncy Management Agency 84/02/10 BROWN.H Kirtpatrick. Lockhart. Hill. Christopher & Phillips 4pp. 22249 265 24X Fiche 30-322,84/02/10.8402150119
 - 12140247 Response supporting Suffolk County 840208 motion to change thedule for filing Group II testimony Certificate of Svc
 - INBERG, J D New York, State of 84/02/10 Atomic Bafety and censing Beard Panel 5pp 22276 343 24% Fiche 50-322,84/02/10-02160247
 - will not take position on util 840206 production of documents by State on to Suffalk County 840208 motion util answers anch 3 84/02/10 LAURENSON.J Λ . 'c Safety and Licensing Board Panel V/02/10.8402200289

- B402140254 Response to Suffalk County motion for reconsideration of ASLB B40202 order re submission of discovery requests Order should be modified to identify party & nonparty witnesses Certificate of Svc encl
 ELLIS.TS Long Island Lighting Co ELLIS.TS Hunton & Williams B4/02/11 Atomic Safety and Licensing Board Panel 20pp 28277 099 24% Fiche 50-322.84/02/11.8402160254
- 8402150104 Erratum correcting 840208 order establishing expedited response schedule Date established for filing Group II testimony in emergency planning proceeding is 840302, not 840307 LAURENBON, J A Atomic Safety and Licensing Board Panel 84/02/13 Long Island Lighting Co 1p 22249 261 24X Fiche 50-322, 84/02/13,8402150104
- 8402150124 Forwards reply to util opposition to County motion to change schedule, response to util motion to compel expedited production of documents & motion for leave to file new contentions re offsite emergency preparedness W/o encls MCMURRAY.C M Kirkpatrick, Lockhart, Hill, Christopher & Phillips MCMURRAY.C M Suffolk County, NY 84/02/13 LAURENSON.J A , KLINE.J R , SHON,F J Atomic Safety and Liconsing Board Panel 2pp 22249 269 24X Fiche 50-322,84/02/13.8402150124
- 8402150162 Reply opposing LILCO 840209 motion opposing Suffolk County motion to change schedule Substantial change in Group II schedule not sought Certificate of Svc encl LETSCHE.K J Suffolk County, NY LETSCHE.K J Kirkpatrick, Lockhart. Hili, Christopher & Phillips 84402/13 Atomic Safety and Licensing Board Panel 18pp 22249 177 24x Fiche 50-322,84/02/13,8402150162
- B402150171 Response opposing LILCO motion to compel expedited production of documents by State of NY Certificate of Svc enc!
 LETSCHE.K J Buffolk County, NY LETSCHE.K J Kirkpatrick, Lockbart, Hill, Christopher & Phillips 84/02/13 Atomic Bafety and Licensing Board Panel 4pp 22249 173 24X
 Fiche 50-322,84/02/13.8402150171
- 8402150180 Memorandum in apposition to LILCO 840206 motion to compel expedited production of documents by State of NY Certificate of Bvc encl PALOMIND.F G New York, State of 84/02/13 20pp 22249 083 24X Fiche 50-322.84/02/13.8402150180
- 8402150187 Joint statement on Suffolk County Contention 11 re passive machanical valve failure Certificate of Svc encl
 HILLER, M S Suffolk County, NY MILLER, M S Kirkpatrick, Lockhart,
 Hill. Christopher & Phillips 84/02/13 5pp. 22245 324 24X
 Fiche 50-322,84/02/13.8402150187
- B40R150193 Motion for leave to file new contentions re LILCO offsite emergency preparedness training program Proposed contentions & Certificate of Svc enci.

 MILLER.M S Suffolk County, NY MILLER.M S Kirkpatrick, Lockhart, Hill Christopher & Phillips B4/02/13 Atomic Safety and Licensing Board Panel. 22pp. 22245 149 24x Fiche 50-322,84/02/13, B402150193
- B402160245 Response supporting Suffolk County 840308 motion to change schedule for testimony on Group II contentions until FEMA submission re LTLCO emergency plan Certificate of Svc encl DOUGHERTY, J B Shoreham Opponents Combition DOUGHERTY, J B B4/02/13 Atomic Safety and Licensing Board Panel 3pp 22276 340 24X Fishe 50-322,84/02/13.8402160245
- 8402160278 Motion for leave to reply & reply to State of NY 840210 response in support of Suffolk County motion to change schedule Certificate of Svc encl
 IRWIN D P. Long Island Lighting Co IRWIN D.P. Hunton & Williams 84/02/13 Atomic Safety and Licensing Soard Panel '5pp 22274, 235. 24% Fiche. 50-322, 84/02/13, 8402160278,
- B402170114 Motion for summary disposition of Contention 24 B re ltrs of agreement w/DGE & Radiation Health Coordinator on Phase II emergency planning Related correspondence MCGLESKEY.K E. Long Island Lighting Co MCGLESKEY,K E. Hunton & Williams B4/02/13 Atomic Bafety and Licensing Board Panel 7pp 22297 184 24% Fiche 30-322,84/02/13,8402170114
- --8402170118 Affidavit of JA Weismantle in support of LILCO motion for summary disposition of Contention 24 B rs ltrs of agreement w/DDE & Radiation Health Coordinator WEISMANTLE, JA Long Island Lighting Co 84/02/10 26pp. 22297 191 24X Fichs 50-322,84/02/13,8402170114
- --8402170125 Motion for summary disposition of Phase II emergency planning Contention 33 re DOE-RAP monitoring team communications No genuine issue of met fact exists SISK.K D Long Island Lighting Go BISK.K D Hunton & Hilliams 84/02/13 Atomic Safety and Licensing Board Panel 6pp 22277 217 24X Fichs 50-322,84/02/13,8402170114.

- --B402170132 Affidavit of WF Renz in support of LILCO motion for summary disposition of Phase II Emergency Planning Contention 33 re DOE-RAP monitoring team communication RENZ.WF Long Island Lighting Co B4/02/10 2pp 22297 223 24X Fiche 50-322.84/02/13.8402170114
- --8402170139 Motion for summary disposition of Phase II Emergency
 Planning Contention 45 re designation of DOE personnel No
 genuine issue of matl fact exists
 MCCLESKEY, K E Long Island Lighting Co MCCLESKEY, K E Hunton
 Williams 84/02/13 Atomic Sefety and Licensing Board Panul
 7pp 2227 225 24X Fichs 50-322,84/02/13,8402170114
- --B402170144 Affidavit of WA Kerekes in support of LILCO motion for summary disposition of Phase II Emergency Planning Contention 45 re designation of DOE personnel KEREKES, WA Long Island Lighting Co B4/02/10 2pp 22297 232 24X Fiche 50-322,84/02/13,8402170114
- --B402170148 Affidavit of D Schweller in support of LILCB motion for summary disposition of Phase II Emergency Planning Contention 45 re designation of BNL personnel SCHMELLER D Energy Dept of 83/11/17 ip 22297 234 24X Fi
- --B402170153 Affidavit of JA Weismantle in support of LILCO motion for summary disposition of Phase II Emergency Planning Contention 45 re designation of DDE personnel WEISMANTLE, J A Long Island Lighting Co 84/02/10 65pp 22297 236 24X Fiche 50-322,84/02/13,8402170114
- --8402170161 Motion for summary disposition of Phase II Emergency
 Planning Contention 46 re continued availability of DDE-RAP
 resources No genuine issue of matl fact exists
 MCCLESKEY.K E Long Island Lighting Co MCCLESKEY.K E Hunton '.
 Milliams B4/02/13 Atomic Safety and Licensing Board Panel
 7pp 2227 301 24X Fiche 50-322.84/02/13.8402170114
- --8402170168 Affidavit of WA Kerekes in support of LILCO motion for summary disposition of Phase II Emergency Planning Contention 46 rs continued availability of DDE-RAP resources KEREKEB, W. A. Impell Corp. 84/02/10 2pp. 22297 308 24X Fiche 50-322,84/02/13,8402170114
- --8402170172 Affidavit of D Schweller in support of LILCO motion for summary disposition of Phase II Emergency Planning Contention 46 re continued availability of DDE-RAP resouces SCHMELLER, D. Energy, Dept of 83/11/17 2pp 22297 310 24) Fichs 50-322,84/02/13,8402170114
- --B402170180 Affidavit of JA Weismantle in support of LICCO motion for summary disposition of Phase II Emergency Planning Contention 46 rs continued availability of DDE-RAP resources HEISMANTLE, J. A. Long Island Lighting Co. 84/02/10 56pp 2227 312 24X Fichs 50-322,84/02/13,8402/70114
- --8402170188 Motion for summary disposition of Phase II emergency planning Contention 47 re dose assessment methods No genuine issue of matl fact exists
 MCCLESKEY, K E Long Island Lighting Co MCCLESKEY, K E Hunton ', Williams 84/02/13 Atomic Bafety and Licensing Board Fanel 8pp 22278 006 24X Fiche, 50-322, 84/02/13, 8402170114
- ---8402170233 Affidavit of D Schweller in support of LILCO motion for summary disposition of Phase II Emergency Planning Contention 49 re dose assessment methods Certificate of Syc enci SCHMELLER.D Energy, Dept of 83/11/17 46pp 22298 018 24x Fiche 50-322,84/02/13,8402170114
- --8402170194 Affidavit of CA Daverio in support of LILCO motion for summary disposition of Phase II Emergency Planning Contention 49 re dose assessment methods DAVERIO, CA. Long Island Lighting CO 84/02/10 4pp 22298 014 24% Fiche 50-322,84/02/13,8402170114
- 8402220215 Response supporting Buffolk County 840209 motion for reconsideration of 840202 order scheduling document discovery requests on proposed supplemental diesel generator contentions Certificate of Svc encl Related correspondence BORDENICK, B M Hearing Branch 3 84/02/13 Atomic Safety and Licensing Board Fanel Opp 22338 350 24X Fiche 50-322,84/02/13,8402220215,

- 8402160214 Response to util 8302(3 mution for leave to reply & reply to State of NY response in support of Suffalk County motion to change schedule Util reply irrelevant to issue before ASLB Contificate of Sur encl MCMURRAY, C M Suffolk County, NY MCMURRAY, C M Kirkpatrick, Lockhart, Hill, Christopher & Phillips 84/02/14 Atomic Safety and Licensing Board Panel 5pp 22275 298 24X Fiche 50-322,84/02/14,8402160214
- B402160219 Motion for leave to reply to LILCO B40207 response to Suffolk County motion to admit supplemental diesel generator contentions
 DYNNER, A R Suffolk County, NY DYNNER, A R Kirkpatrick, Lockhart Hill, Christopher & Phillips B4/02/14 Atomic Safety and Licensing Board Panel 2pp 22276 271 24X Fiche 50-322,84/02/14 8402160219
- --B402160223 Reply to LILCO B40207 response to Suffelk County motion to admit supplemental diesel generator contentions. Certificate of Svc encil DYNNER.A R Suffelk County, NY DYNNER.A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips B4/02/14 Atomic Safetu and Licensing Board Panel 24pp 22276 273 24x Fichs 50-322,84/02/14,8402160219
- 8402170022 Motion for leave to reply & to Governor Cuomo 840213
 memorandum apposing LILLO motion to compel expedited
 production of documents by State of NY
 IRWIN, D.P. Long Island Lighting Co. IRWIN, D.P. Hunton & Williams
 84/02/14 Atomic Safety and Licensing Board Panel 25pp
 22300 243 R4X Fiche 50-322,84/02/14,8402170022
- --8402170049 Motion to strike Suffolk County Unauthorized 840213 reply to LILCO apposition to motion to change schedule Reply not covered by request for leave to file Certificate of 8vc encl
 IRWIN.DP Long Island Lighting Co IRWIN.DP Harmon & Weiss 84/02/14 Atomic Safety and Licensing Board Panel 3pp 24300 268 24% Ficho 50-322,84/02/14,8402170022
- 8402170100 Memorandum in support of util motion for summary disposition on Phase II Emergency Planning Contentions 45.46 & 49 Adequacy of DDE-RAP program should not be litigated as licensing proceeding W/Certificate of Svc FALZONE.R R Hunton & Williams 84/02/14 Atomic Safety and Licensing Board Panel 13pp 22300 037 24% Fiche 50-322.84/02/14.8402170100
- 8402220254 Forwards 840214 response to Suffolk County motion to admit supplemental diesel generator contentions & unexecuted affidavit & prof qualifications of C Berlinger GODDARD, R J Hearing Branch J 84/02/14 BRENNER, L, FERGUSON, G A, MORRIS, P A Atomic Safety and Licensing Board Panel 2pp 22330 335 24X Fiche 50-322,84/02/14,8402220254
- --BA02220202 Response supporting Suffolk County BA0127 motion to admit supplemental contentions re Transamerica Delaval, Inc emergency dissel generators Establishment of litigation schedule opposed Certificate of Svc encl QODDARD, R. J. BORDENICK, D. M. Hoaring Branch 3 B4/02/14 Atomic Safety and Licensing Board Panel 25pp 22330 337 24X Fishe 50-322,84/02/14,8402220294.
- 8402210113 Forwards Comanche Peak ASLB 840131 memorandum on contention re GA of Transamerica Delaval diesel generators DUNNER, A R Kirkpatrick, Lockhart Hill, Christopher & Phillips DYNNER, A R Long Island Lighting Co 84/02/15 BRENNER, L J. MORRIG, P A , FERGUSON, O A Atomic Safety and Licensing Board Panel ip 22317 242 24X Fiche 50-322,84/02/15,8402210113
- 8402220238 Ack recript of util 840210 motion to compol expedited production of State of NY emergency proparedness plan No position taken on portion seeking order compelling production of state plan Related correspondence BORDENICK, B M Hearing Branch 3 84/02/15 LAURENSON, J A , KLINK, J R., SHON, F J Atomic Safety and Licensing Board Panel 2pp 22339 244 24X Fiche 30-322.84/02/15,8402220338
- B402220258 Forwards Region I morning repts for B40206.08,10 & 14 re emergency diesel generators GDDDARD,R J Hearing Branch 3 84/02/15 BRENNER.L., FERQUSDN,Q A, MORRIS,P A, Atomic Safety and Licensing Board Panel 6pp 22346 307 24X Fiche 50-322,84/02/15,8402220358
- 8402220123 Memorandum of Governor Cuomo in opposition to LILCO 840210 motion to compel expedited production of State of NY emergency preparedness plan Certificate of Svc encl ZAHNLEUTER: B New York, State of 84/02/16 7pp 22338 282 24X Fiche 50-322,84/02/16,8402220125

- 402220225 Advises that staff will take substantive position on LILCO B40210 motion to strike portions of State of NY direct testimony on emergency planning Contention &5 Responses allowed only from State of NY REPRAID A Hearing Branch 3 84/02/16 LAURENSON, J A, SHDN.F J. KLIRE, J R Atomic Safety and Licensing Board Panel 2pp 22338 358 24X Fiche 50-322,84/02/16.8402220225
- 402220245 Affidavit of C Berlinger re matters raised in support of NPC rasponse to Suffolk County motion to admit supplemental diesel generator contentions Certificate of Svc encl Related correspondence
 BERLINGER, C Division of Licensing 84/02/16 16pp 22339 147
 P4X Fiche 50-322,84/02/16,8402220245
- reserved Response of Governor Cuama opposing LILCO 840210 motion to strike direct testimony on emergency planning Contention 55 re evacuation time estimates Certificate of Svc encl ZANNLEUTER.R J New York, State of 84/02/17 Atomic Sefety and Litemsing Board Panel 12pp 22337 256 24X Fiche 50-322,84/02/17. 402220131 Response of Governor Cuomo opposing LILCO 840210 motion to
- 402220148 Response apposing util motion to strike partions of State of NY direct testimony on emergency planning Contention 65 W/Certificate of Svc W/Certificate of Svc WCMURRAY, C M Kirkpatrick, RCMURRAY, C M Kirkpatrick, Lockhart, Hill, Christopher & Phillips 84/02/17 Atomic Safety and Licensing Board Panel 4pp 22338 287 24% Fiche 50-322,84/02/17,8402220148
- 402220152 Request for production of documents Certificate of Svc encl EARLEY,A F Long Island Lighting Co EARLEY,A F Hunton & Williams 84/02/17 Suffolk County, NY 52pp 22328 300 24X Fiche 50-322.84/02/17.8402220152
- 402220302 Advises of 840215 & 16 discoveries of linear cracking in emergency diesel generator components
 DYNNER, A R. Kirkpatrick, Lockhart, Hill, Christopher & Phillips
 94/02/17 BRENNER, L J., MORRIS, P.A., FERGUSON, G.A. Atomic Safety
 and Licensing Board Panel 2pp 22339 350 24X
 Fiche 50-322,84/02/17,8402220302
- 402220311 Order describing info requested for each cross-examination plan in proceeding
 LAURENBON, J.A. Atomic Safety and Licensing Board Panel 84/02/17
 Office of the Executive Legal Director 2pp 22334 241 24X
 Fiche 50-322,84/02/17,8402220311
- 402220454 Proposed request for documents & list of probable deponents, per ASLB 840202 order & 840214 modified order Certificate of Syc enci EARLEY, A F Long Island Lighting Co EARLEY, A F Hunton & Williams 84/02/17 Suffolk County, NY 7pp 22339 311 24X Fiche 50-322,84/02/17,8402220454
- 402230097 Requests Oroup II testimony filing date be deferred to 840314 to allow discovery of new LILCO witnesses Certificate of Svc encl Related correspondence LANPHER, L Kirkpatrick, Lockhart, Hill, Christopher & Phillips LANPHER, L C Suffolk County, NY 84/02/21, LAURENSON, J A, KLINE, J R, SHON, F J Atomic Safety and Licensing Board Panel 14pp 22362 232 24x Fiche 50-322, 84/02/21, 8402230097
- 02280213 Motion for ASLB to enforce ASLB 830825 order compelling fiscovery from LILCO Occumentation re objective evidence requested Certificate of Svc encl Related correspondence DYNNER, A R Suffolk County, NY DYNNER, A R Kirkpatrick, Lockhart, fill, Christopher & Phillips 84/02/21 Atomic Safety and Licensing Board Panel 6pp 22400 056 24X Fishe 50-322.84/02/21.8402280213
- 402280375 Urges ASLB to maintain positive approach to early resolution of proceedings Catacosinos statement re util consideration to abandon project must not be taken out of rendered context Related correspondence
 BARRETILE M Long Island Lighting Co 84/02/21 BRENNER.L,
 MORRIS, P A, FEERGISON, O A Atomic Safety and Licensing Board Panel
 2pp 22405 019 24X Fiche 50-322.84/02/21,8402280375
- 40228023: Response opposing Suffolk County ltr motion for extension until 840314 to file Group II testimony List of affected contentions inaccurate Cartificate of Svc enc! Related
- correspondence
 IRMIN.D P Long Island Lighting Co IRMIN.D P Hur
 84/02/22 Atomic Safety and Licensing Board Panel
 22399 282 24x Fiche 50-322,84/02/22.8402280231 Hunton & Williams
- 102280322 Objections of Oovernor Cuomo to util B40206 motion to compel expedited production of documents by State of NY Util possesses complete document listing responsive to Town of Bouthampton Certificate of Svc encl Related correspondence ZAHNLEUTER: R J New York, State of 84/02/23 Atomic Bafety and Licensing Doard Panel 18pp 22399 104 24% Fiche 50-322,84/02/23.8402200322

- 8402280437 Response to Suffolk County motion to file new contentions re util offsite emergency preparedness training program & util objections to proposed training contentions Motion should be denied Certificate of Svc encl MONAGHAN, J A Long Island Lighting Co MONAGHAN, J A Hunton & Williams 84/02/23 Atomic Safety and Licensing Board Panel 28pp 22404 292 24X Fiche 50-322,84/02/23,8402280437
- 8402290092 Memorandum % order denying Suffolk County 840208 motion to change schedule Motion unauthorized % ASLO will not entertain unauthorized filings LAURENSON, J A Atomic Safety and Licensing Board Panel 7pp 22426 019 24% Fiche 50-322,84/02/28,8402290092
- O Inspection reports, IE Bulletins & correspondence
- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fithe 50-000,84/01/25,8312120153
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Syc list encl JORDAN E L Division of Emergency Proparedness & Engineering Response (Post 830)03) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01. "Cracks in BWR Mark I Containment Vent Headers " Svc list encl
 Headers " Svc list encl
 DEYGUNG, R C Director's Office, Office of Inspection and
 Enforcement 84/02/03 Consolidated Edison Co of New York, Inc
 102pp 22177 156 24X Fiche 30-000.84/02/03,8401190017
- B4020B0167 Requests NRC undertake complete insp of each of 24 cylinder heads installed in facility diserls for compliance w/applicable stds IE Insp Rept 50-322/B3-25 re Transamerica Delaval.inc diesel generators encl DYNNER.A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips B4/02/03 DENION.H R Office of Nuclear Reactor Regulation. Director 10pp 2212B 207 24X Fiche 50-322,84/02/03,8402080167
- 8402220463 Forwards IE Insp Rept 50-322/83-37 on 831205-09 No OZZZZNAL FORWARDS I INSP REPT 30-322/83-3/ BN 831203-09 NO violations noted NARTIN.T T Division of Engineering & Technical Programs 84, POLLDCK.M S Long Island Lighting Co 2pp 22339 274 24X Fiche 30-322.84/02/06.8402220463 84/02/06
- --B402220467 IE insp. Rept 50-322/83-37 on B31205-07 No violations noted Major areas inspected followsp emergency preparedness items from 820823-0702 appraisal WOUNDS,E J , GROCKER,H W Region 1. Office of Director 84/01/31
- 8402100025 Discusses need for immediate staff insp of cylinder heads at facility in light of Vendor Insp Program Repts 97900334/83-02 & 03 re noncomformances in implementation of GA program for production of replacement heads DYNNER, A R Kirkpatrick, Lockhart Hill, Christopher & Phillips 84/02/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22230 023 24X Fiche 50-32R, 84/02/07, 8402100025
- --8402130510 Forwards GA Program Insp Repts 99900334/83-02 & 99900334/83-03 on 830906-15 & 1017-21, respectively & notices of nonconformance of Director 84/01/17 MATHEWS, C Transamerica Delaval, Inc. 2pp 22230 027 24X Fiche 50-322, 84/02/07, 8402100025
- --8402130513 Notice of nonconformance from insp on 830906-15 * Region 4. Dffice of Director 64/01/17 5pp 22230 Fiche 50-322.84/02/07.8402100025 22230 029
- --8402130518 GA Program Insp Rept 99900334/83-02 on 830906-15
 Noncompliance noted GA program not imposed on exhaust
 sitencer manufacturer & insp stamps & dates on process
 sheats did not provide evidence of insp
 SUTTON.J W , BARNES.I Region 4, Office of Director 84,
 21pp 22230 034 24X Fiche 50-322,84/02/07,8402100025 B4/01/16
- ---8402130521 Notice of nonconformance from insp on 831017-21 * Region 4. Office of Director 84/01/17 4pp 22230 Fiche 30-322, 84/02/07, 8402100025
- ~-B402130524 GA Program Insp Rept 99900334/83-03 on B31017-21
 Noncompliance noted engineering spec sheets did not include
 IEEE stds invoked by customer specs & written instructions
 for insp/acceptance indication not provided to manufacturer
 SUITON.J W. BARNES.I Region 4. Office of Director B4/0:
 19pp 22230 057 24% Fiche 50-322,84/02/07,8402100085

- 8402240093 Forwards IE Insp Rept 50-322/83-38 on 831128-840122 No
 - violations noted
 STAROSTECKI,R Division of Project & Resident Programs
 POLLUCK,M S Long Island Lighting Co 2pp 22373 242
 Fiche 50-322,84/02/07,8402240093
- --8402240106 IE Insp Rept 50-322/83-38 on 631128-840122 No violations noted Major areas inspected IE Bulletin 79-24 & Circulars 77-12 & 80-02, control room human factors review, implementation of NUREO-0737 items & surveillance testing PETRUNE, C. SHEDLOSKY, J T , COOK. W Region 1. Office of Director 84/02/03 17pp 22373 244 24X Fiche 50-322,84/02/07,8402240093
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (1905R50, App R) " Syc list encl ...
- enci JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc. 124pp 22345 259 24X Fiche 50-000,84/02/13,8401170041
- 8401190000 Board Notification 84-021 provides repts of Transamerica Delaval, Inc insps conducted from Mar 1979 to Oct 1983 EIBENHUT,D 0 Division of Licensing 84/02/13 PALLADINO, GILINBKY, ROBERTB Commissioners 5pp 22314 001 24X Fiche 50-000,84/02/13,8401190050
- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '"
- Bvc list encl
 JURDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24X Fiche 50~000,84/02/14,8401170039
- 8401190045 IE Info Notice 83-63. Suppl 1, "Potential Failures of Westinghouse Type 8A-1 Differential Relays" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366 142 24X Fiche 50-000,84/02/15,8401170045
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc. 116pp 22366 024 24X Fiche 50-000.84/02/21,8401190062
- 8401170066 IE Info Notice 84-11, "Training Program Deficiencies " Bvc list anci
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103), 84/02/24 Consolidated Edison Co of New
 York, Inc. 115pp. 22430 304 24X Fiche 30-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seats "
 Svc list encl.
 JGRDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27. Consolidated Edison Co. of New
 York, Inc 120pp. 22431.060 24X Fiche 50-000.84/02/27.8401190067
- R Periodic operating reports & related correspondence
- 8402150176 Forwards data for Const Status Rept (NURES-0300) for Fourth 1021301/e rorwars- - Guarter 1983 Guarter 1983 MCCAFFREY,B R Long Island Lighting Co 84/01/19 Managamen Information Branch App 22249 147 24X Fiche 50-322,84/01/19
- 8 Reportable occurrences. LERs & related correspondence
- 8402010233 Part 21 rept re potential interference in full function of Bergen-Paterson strut easembly w/Pacific Scientific Commochanical shock arrestor Attempt to obtain corrective action from manufacturer unsuccessful BECKSTED.W.F. Bergen-Paterson Pipe Support Corp. 81/03/06 ORIER.B.H. Region i, Philadelphia. Office of the Director (81/03/01) 2pp 22040-203. 24X Fiche 50-000.81/03/06.8402010253
- 8402070393 Requests that NRC investigate design reliability of emergency diesel generators supplied by Transamerica Delawal. Inc Engine problems have been experienced since delivery of first vessel in May 1981 Related info encl MOLINA. J C. Felcon Carriers. Inc. 84/02/01 DENTON, H R. Nuclear Reactor Regulation, Director 63pp 22096:057 24 Fiche: 50-000,84/02/01,8402070393. Office of 24X
- 8401170048 Board Notification 84-006 provides info re alleged editybuse span Notification Ba-Oue provides into re alleged falsification of GC documents concerning const of safetyrelated HVAC units by Bahnson Co.Winston-Salem.NC
 EIBENHUT, DQ. Division of Licensing 84/02/09 PALLADIND,
 GILINBRY, ROBERTS Commissioners. 7pp 22332.187 24X
 Fiche 50-000.84/02/09.8401190048

- --8401090562 Forwards info to be considered for board notification of possible falsification of QC documents re const of safety-related HVAC units by Bahnson Co at listed facilities Facilities
 PARTLOW.J G Division of QA, Bafeguards & Inspection Programs
 (Post 830103) 83/12/29 EISENHUT.D Q Division of Licensing
 2ap 22332 194 24X Fiche 50-000.84/02/09.8401190048 Division of Licensing
- --8401090571 Forwards investigation rept of alleged falsification of GC documents re const of safety-related HVAC units by Bahnson Co Investigation supports conclusion that documents falsified W/n smcl HAYES, B B Office of Investigation B3/05/12 COLLINS, J T Region 4, Office of Director 2pp 22332 196 24X Fichs 50-000, B4/02/09, B40119004B
- --8401090977 Responds to JJ Cummings 830824 ltr re alleged violations by Bahnson Co employees Craminal prosecution declined due to inability to prove criminal intent LIPPE. L Justice. Dept of 83/10/18 HAYES, B B Office of Investigation ip 22332 198 24X Fiche 90-000,84/02/09,
- 84-01190053 Board Notification 84-020 forwards info re Transamerica Delaval Inc emergency diesel generator problems Attendance list meeting handouts & slides encl £IBENHUT.D 0 Division of Licensing 84/02/13 PALLADINO. GILINSKY, ROBERTS Commissioners 102pp 22332 202 24X Fiche 30-000.84/02/13.8401190053
- 8402220530 Part 21 rept re defective DSR & DSRV standby diesel generator turbocharger thrust bearing lubrication Deficiency not corrected by sys mod New recommendation will be sent to customers by 840330 BOYER, R E Transamerica Delaval, Inc. 84/02/15 Director's Office, Office of Inspection and Enforcement Spp. 22332 182 24x Fiche 50-000,84/02/15,8402220530
- 8403280701 Notification of 840308 meeting w/Transamerica Delaval. Inc (TDI) Owners Group in Wading River.NY to discuss TDI proposed program to qualify diesel generators CARUSO.R Division of Licensing 84/02/23 BERLINGER.C Division of Licensing 2pp 22414 340 24X Fiche 50-000.84/02/23. of Licensing 2pp 8402280701
- T Hearing transcripts on non-antitrust matters
- B40207017B Rebuttal testimony of S Cole & A Tyree on Contention 23 re evacuation shadow phenomenon Prof qualifications & Certificate of Svc encl COLE, S . TYREE, A Suffolk County, NY COLE, S New York, State Univ of, Stony Brook, NY 64/02/02 32pp 22101 071 24X Fiche, 50-322,84/02/02,8402070178
- B402140047 Motion to admit supplemental testimony of MC Cordaro, JA Weismantle,EB Lieberman & DB Mileti in response to State of NY testimony on Phase II emergency planning Contention 65. Related correspondence ZEUGIN.L B Long Island Lighting Co ZEUGIN,L B Hunton & Williams 84/02/10 Atomic Safety and Licensing Board Panel App. 22219 203 24X Fiche 50-322.84/02/10.8402140047
- --8402140058 Supplemental testimony of MC Cordaro, JA Weismantle, EB Lieberman & DS Mileti in response to State of NY testimony on Phase II emergency planning Contention 45 Cartificate of Eye encl CORDARO,M C, WEISMANTLE, J. A. LIEBERMAN, E B Long Island Lighting Co. B4/02/10 30pp 22219 222 24% Fiche 50-322,84/02/10, B402140047.
- 8402240082 Transcript of 840222 conference of parties in Bethesda, MD Pp 21, 439-21, 657 * Atomic Safety and Licensing Board Panel, 84/02/22 218pp 22373 001 24X Fiche 50-322, 84/02/22, 8402240082,
- B402280363 Transcript of B40223 hearing in Hauppauge, NY re amergency planning Pp 3.677-3.831 * Atomic Safety and Licensing Board Panel 84/02/23 217pp 22403.301 24X Fiche 50-322, 84/02/23.8402280363
- 8402280488 Transcript of 840224 hearing in Hauppauge, NY Pp 3,832-3,889 * Atomic Safety and Licensing Board Panel 84/02/24 85pp 22402 135 24X Fiche 50-322,84/02/24,8402280488

- DOKET 50-323 DIADLO CANYON NUCLEAR POWER PLANT, UNIT 2 Application/construction stage documents & correspondence
- |402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 ~ Jul 1983 CHILK.8 J Office of the Secretary of the Commission 83/12/14 Public Document Branch ip 2028
- --8402160047 Staff requirements memo re 830707 discussion of procedures for facility review in Washington.DC CHILK,SJ Diffice of the Secretary of the Commission 83/07/08 PLAINE, H H Office of the General Counsel 1p 22281 061 24X Fiche 50-000, 83/12/14, 8402160003
- --8402160072 Staff requirements memo re 810910 discussion of low power OLIN Washington DC
 CHILK, S J Office of the Secretary of the Commission 81/81CWIT.L Office of the General Counsel 1p 22281 029
 Fishs 50-000, 83/12/14,8402140003
- --8402160085 Staff requirements memo re Bill16 discussion of 670518 memo to seismit reverification plan in Washington, DC CHILK, S. U. Office of the Secretary of the Commission, 81/11/20 Office of the Becretary of the Commission ip 22281.033 24X Fiche 50-000.83/12/14,8402160003
- --8402160091 Staff requirements memo re 811119 continuation of discussion of Diablo Canyon order in Washington, DC
 CHILK.8 J Office of the Secretary of the Commission 81/12/01
 DIRKS, W J Office of the Executive Director for Operations 1p
 22281 034 24X Fiche 50-000.83/12/14,8402160003
- --8402160110 Staff requirements memo re 820205 discussion of Phase I of facility rept in Washington.DC.
 CHILK:S J Office of the Secretary of the Commission. 82/02/09 BICKWIT.L Office of the General Coursel. 1p 22281 039 24X Fiche 50-000,83/12/14,8402140003
- --8402140420 Discusses SECY-82-81 to AO recommendation on selemic design OHILK, S.J. Office of the Secretary of the Commission 82/03 DIRCKS, W.J. Office of the Executive Director for Operations 28281 170 24X Fichs 50-000,83/12/14,8402160003 82/03/23
- 8402030385 Provides Commissioners w/info on status of staff resolution of allegations & concerns that may apply to Commission deliberations on licensing plant for criticality & low power
- BECY-US-003 B4/01/04 4pp 22089 342 24X Fiche 50-275, B4/01/04,
- B312120136 Board Notification 84-011 discusses NRC use of terms "important to safety" & "safety-related "
 EISEN-UT.D G Division of Licensing 84/01/18, PALLADING Commissioners 72pp 22241.008 24X Fichs:50-000,84/01/18, B21212013A
- B402030051 Staff requirements memo re B40123 discussion of pending investigations re treatment of allegations & concerns about design const & operation of plant CHILK.S J Office of the Secretary of the Commission. 84/01/26 DIRCKS,W J Office of the Executive Director for Operations. HAYES,B B Office of Investigation 1p 22091.080 24X Fiche 50-275,84/01/26.8402030051. 84/01/DA
- B402050499 Notification of B40131 meeting w/util in Ban Francisco,CA to discuss preliminary results of NRC review & evaluation of small fore piping analyses
 SCHIERLING:H Licensing Branch 2 84/01/27. KNIGHTON.O W.
 Licensing Branch 3 4pp 22110 158. 24X Fiche 50-275,84/01/27,8402060499
- 8402060422 Discusses suppl to Nuclear Plant Administrative Procedure NPAP A-100 (81), "Administrative Program to Control Return to Power After Reactor Trip," in response to Items 1-6 of Action Item k 1 of Generic ktr 83-28 BCHUYLER, J O Pacific Gas & Electric Co 84/02/01, £18ENHUT, D G Division of Licensing 1p 22085 099 24X Fiche: 50-275, 84/02/01, 200304040 Division of Licensing 8402050422
- B402070234 Responds to B40105 Generic Ltr B4-01 re use of terms important to safety & safety-related Util participation in response will be through steering committee & chairman of util safety classification group BCHUYLER.J.O. Pacific Oas & Electric Co. 84/02/03 TAYLOR.J M Director's Dffice, Office of Inspection and Enforcement ip 22101:142 24% Fiche 50~000.84/02/03,8402070204.

- B401170040 Board Notification 84-027 provides RL Cloud submittel addressing preliminary concerns on small bore piping & supports raised at 840131 meeting w/PQ&E EIEENHUT.D O Division of Licensing 84/02/13 PALLADING, 01LINSKY, ROBERTS Commissioners 3pp 22241 186 24X Fiche 90-275.84/02/13.8401190040
- 8401190039 Board Notification 84-032 provides add1 info on environ qualification Submittal augments info in Board Notifications 84-004 & 64-007 EIBENNUT.D G Division of Licensing 84/02/13 Atomic Bafety and Licensing Board Panel 10pp 22314 204 24X Fiche 50-000,84/02/13,8401190039
- 8402210216 Submits supplementary instructions for protection & retention of GA records, per 840131 meeting request Ali GA records are to be maintained & may not be removed from project files
 SCHUYLER, J O Pacific Gas & Electric Co 84/02/15 EIRENHUT, D Q Division of Licenting 2pp 22316 208 24X Fichs 50-275,84/02/15,8402210216
- 8402220363 Summarizes 840207 site visit conducted under ex parta rules Detailed account of tour provided TRUBATCH 8 L. NRC No Detailed Affiliation Given 84/02/15 NRC No Detailed Affiliation Given 4pp 22335 298 24X Fiche 50-275,84/02/15,8402220363
- B40119006B Board Notification 84-033 provides "Sys Interaction Prugrams" task action plan for Unresolved Bafety Issue A-17. Distribution list enc! EIBENHUT.P 0 Division of Licensing 84/02/16 PALLADINO Commissioners. 8pp. 22482 091 24X Fiche 50-000.84/02/16. 840119006B
- E NRC Safety Evaluation Report (SER), supple & correspondence
- B402060424 Advises that NBSB vendor (Westinghouse) completed review of all power ascension procedures Procedures acceptable, Info completes Item I C 7 of 88ER 14
 8CHVLER.J O Pacific Gas & Electric Co 84/02/01 KNIGHTON, Q. W. Licensing Branch 3 ip 22085 100 24X Fiche 50-275, 84/02/01.
 840204024
- 8402070256 Forwards response to NRC questions concerning allegations listed in BBER 21 re installation of Class I equipment on Class II math in cable spreading room SCHUYLER, J. D. Pacific Qas & Electric Co. B4/02/07 MARTIN, J. B. Region 5, Office of Director. Spp. 22i61, 342, 24X Fiche: 50-275, 84/02/07, 8402090256
- F Security, medical, emergency & fire protection plans
- B4020203B2 Forwards public version of revised emergency response plan operating procedures, including Procedures III.01 resembles of the procedure of the proce
- --8402020385 Public version of revised emergency response plan operating procedures, including Procedures III, 01 re emergency svcs director & III 02 re Ban Luis Obispo Gounty sheriff dept. STILWELL, D. Pacific Oas & Electric Co. 83/07/07. 1798pp. 22074 047 24X Fichs. 50-275,84/01/19,8402020382
- 8402090237 Forwards evaluation of PORE emergency preparedness plan for Diablo Canyon. KRIMM.R W. Federal Emergency Management Agency 84/02/02. JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 22157:288 24X Fiche.50-275.84/02/02.
- --8402090247 Evaluation of POLE emergency preparedness plan for Diablo Canyon. # Federal Emergency Management Agency 83/12/06, 30pp. #2157 290 24X Fiche: 50-275.84/02/02.8402070237
- B402290365 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per B10709 Generic Ltr 81-27, H/o request entire plan will be placed in FDR KNIGHTON.0 W Licensing Branch 3 84/02/14, 8CHUYLER.J D Pacifi Oss & Riectric Co. 4pp. 22438:241 24X Ficher 80-275,84/02/14,8402270365 Pacific

9 Adjudicatory correspondence

- B31013015B Response apposing Joint Intervenors 830909 suppl to motion to reopen record on const QA Info from Nuclear Svcs Corp audit neither timely nor compelling to justify reopening of record Certificate of Svc encl
 CHANDLER.L J Hearing Branch 2 B3/10/06 Atomic Bafety and Licensing Appeal Panel 9pp 20724 119 24X Fiche 50-275.83/10/06.831013015B
- B402010215 Memorializes telcon re NRC answer to Joint Intervenors & Oavernor Deukmejian petitions for review of ALAB-756 Responses may be filed by B40126 CHANDLER: L J Hearing Branch 2 B4/01/25 CHILK: B J Office of the Commission 2pp 2203B 360 24X Fiche 50-275.84/01/25.8402010215
- 8402010220 Answer opposing Joint Intervenors & Governor Deukmejian BA0107 & 11 respective petitions for review of ALAB-756 re petition to reopen hearing on issue of const GA Important question of fact not established Certificate of Svc encl CHANDLER.L J Hearing Branch 2 MCGURREN.H J Hearing Branch 1 BA/01/26 Commissioners 18pp 22040 156 24% Fiche S0-275.84/01/26.8402010220
- B402070058 Commends C Miller, C Costantino, PC Wang & AJ Philippacopoulos for time & effort put into testimony at Nov 1983 hearing CHANDLER, L J Hearing Branch & B4/02/01 REIGH, M Broakhaven National Laboratory 1p 22103 038 24X Fiche 50-275,84/02/01, 8400270058
- B402070177 Motion for leave to file reply to util % NRC answers to Joint Intervenors B40109 petition for review of ALAB-756 REVNOLDB.JR Joint Intervenors Diablo Campon REVNOLDB.JR Center for Law in the Public Interest B4/02/03 Commissioners 2pp. 22102 213 24% Fichs 50-275.84/02/03.8402070177
- ~~8402070183 Reply to util & NRC answers to petition for review of ALAB-755 Reply corrects factual mistatements which if left uncorrected will mistad Commission as to true state of record Certificate of Buc ancl
 REYNOLDB.J R Joint Intervenors Diablo Canyon, REYNOLDB.J R Center for Law in the Public Interest 83/02/03 Commissioners 11pp 22102 215 24X Fiche 30-275.84/02/03,8402070177
- 8402140223 Advises that ABLB & partips in proceeding will be notified re relevant results of staff review of allegations re small bore piping design activities CHANDLER, L.J. Hearing Branch 2 84/02/07 MODRE, T.S., BUCK, J.H., JUHNBON, W.R. Atomic Safety and Licensing Appeal Fanel 2pp 22230.008 24X Fiche 30-275,84/02/07,8402140223
- 8402130251 Prepared statement of T Devine re plant GA Proposed violation item assessment encl DEVINE, T Joint Intervenors Diablo Canyon 84/02/10 18pp 22204:R88 24X Fiche 50-275,84/02/10.8402130251
- 8402170053 Motion to augment or, in alternative, to reopen record refacility operation in light of Stokes & Cooper affidavits
 Motion timely filed & should be granted Certificate of Bvcencl
 REYNOLDB, J R Joint Intervenors Diablo Canyon REYNOLDS, J R
 Center for Law in the Public Interest 84/02/14 Atomic Bafaty
 and Licensing Appeal Panel 24pp 22301.104. 24X
 Fiche.50-275,84/02/14,8402170053
- 8402170041 Order extending time until 840313 for Commission to act to review ALAB-756 CHILK:S J. Office of the Secretary of the Commission 84/02/15 Commissioners. ip 22300 275 24X Fiche 50-275.84/02/15. 8402170041
- 8402220279 Requests that Insp Rept 50-275/83-37 & related repts, studies & documents immediately be placed in PDR & issued to svc list in proceeding REVNOLDB, J R Center for Law in the Public Interest, REVNOLDS, J R. Joint Intervences Diablo Canyon 84/02/15, PALLADIND, N, GILINBKY, V., ROBERTS, T, Commissioners, 2pp 22337 055 24X Fiche. 50-275, 84/02/15, 8402220879
- 8402210121 Confirms 840215 conversation re Ban Luis Obispo Mothers for Peace petition BURNS:8.0 Regional Operations & Enforcement Division, 84/02/17 DEVINE, T. M. Guvernment Accountability Project ip 22317.206 24X Fiche.50-275,84/02/17.8402210121
- 8408280454 Requests change of address as listed for svc list for matters re facility Also requests addition to svc list for Rancho Seco Related correspondence HARRIS.T H Affiliation Not Assigned 84/02/22 CHILK Office of the Secretary of the Commission ip. 22406.362, 24X Fiche: 50-275.84/02/22.8402280454

- 8402280333 Order directing svc of expugated transcript of NRC staff 840125 private meeting w/C Stokes re GA allegations All parties shall be served by 840224 SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel 84/02/23 Office of the Executive Legal Director 2pp 22399 083 24X Fiche 50~275.84/02/23.8402280333
- 8402290084 Notifies that draft IE lnsp Repts 50-275/83-37 & 50-323/83-25 obtained General Counsel asked to determine whether documents should be served upon parties GLINSKY. V Commissioners 84/02/28 1p 22426 042 24x Fiche 50-275,84/02/28.8402290084

H General correspondence

- 8402230089 Requests NRC update mailing labels on priority & free mail to reflect new ofc location (MAMBERLARN.W California, State of 84/02/15 DI SILBESTRE, S NRC NO Detailed Affiliation Given 2pp 22362 073 24X Fiche 50-000.84/02/15.8402230089
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8402290456 Forwards ACRS 840214 ltr summarizing 840209-11 meetings to review selected issues on application for OLs KNIGHTON, G W Licensing Branch 3 84/02/16 SCHUYLER, J Q Pacific Gas & Electric Co 4pp 22438 175 24X Fiche 50-275, 84/02/16, 8402270456
- 0 Inspection reports, IE Bulletins & correspondence
- 8402010364 Further response to FOIA request for records re Ofc of Inspector & Auditor review of NRC investigation reported in NUREG-0862 & other files concerning facilities Forwards App B documents App A & B documents available in PDR FELTON, J M Division of Rules and Records 83/11/22 REYNOLDS, J Center for Law in the Public Interest App 22058 203 24X Fiche 50-000,83/11/22,8402010364
- --8402010372 Recommends transmittal of invostigation review rept to Congress per R Ottinger 820204 ltr re inconsistencies in NUREO-0862 & M Udall 820208 request Related info encl KAMMERER, C Office of Congressional Affairs 82/08/31 PALLADINO, N , GILINSKY, V , AFEARNE, J Commissioners 150pp 22058 207 24X Fiche 50-000.83/11/22.8402010364
- --B402010378 Forwards review of MUREO-0862. "Insp Rept of Preliminary Rept. Beismic Reverification Program at Diablo Canyon Units 1 & 2 " Related info encl BOULDEN.H , AUERBACH,M Office of Inspector & Auditor 83/11/22 CUMMINOS.J J Office of Inspector & Auditor 39pp 22038 337 24X Fiche 50-000, 83/11/22,8402010364
- 8312120153 IE Info Notice 84-06. "Steam Binding of Auxiliary Feedwater Pumps." Byo list encl JORDAN E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co. of New York, Inc. 120pp 22058 001 24% Fiche 50-000.84/01/25.8312120153
- 8402030375 Ack receipt aP 840107 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-275/83-38 & 50-323/83-26
 BIBHDP.T W Division of Resident, Reactor Project & Engineering Programs 84/01/31 SCHUYLER, J D Pacific Gas & Electric Ca ip 22066-057 24X Fiche 50-275, 84/01/31, 8402030375
- --8402030381 Responds to NRC 831209 ltr re violations noted in IE Insp Repts 50-275/83-38 & 50-323/83-26 Corrective actions fuel handling personnel reinstructed to follow radiological control procedures & individual posted at controlled area BCHUYLER.J O Pacific Qas & Electric Co 84/01/09 MARTIN.J B Region 5. Office of Director 6pp 22066 098 24X Fiche. 50-275.84/01/31,8402030375
- 8402290455 Final response to FOIA request for records re ananymous allegations involving facilities submitted in D Fleischaker 1tr to D Eisenhut Document withheld (ref FOIA Exemptions 5 t 7) FELTON-J M Division of Rules and Records 84/01/31 REYNOLDS, J R Canter for Law in the Public Interest 2pp 22437 276 24X Fiche: 50-275, 84/01/31, 8402290455
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Byc list encl JDRDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/03 Consolidated Edison Co of New York: Inc 119pp 22114 179 24x Fiche 50-000,84/02/03,8401190016

- 840(190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers "Svc list encl
 DEYGUNO.R C Director's Office, Dffice of Inspection and
 Enforcement 84/02/03 Consolidated Edison Co of New York, Inc
 102pp 22:77 156 24x Fiche 50-000,84/02/03,840:1900:17
- BA01190041 IE Info Notice B4-09. "Lessons Learned From NRC Inspa of Fire Protection Safe Shutdown Sys (10CFR50.App R) " Syc list encl
- 8401170039 JE Info Natice 84-08, "10CFR50 7, 'Employee Protection'"
- Svc list encl JORDAN, & L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/14 Consplidated Edison Co of New Yark, Inc 115pp 27345 141 24X Fiche 50-000,84/02/14,8401190039
- 8401190045 IE Info Notice B3-63. Suppl 1. "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN.S L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York. Inc. 118pp 22366 142 24X Fiche 50-000.84/02/15.8401190045
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDANN E L Division of Emergency Preparedness & Engineering REPUBLIAN E L Division of Emergency Preparedness & Engineering 840/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000,84/02/21,8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies | Svc list encl
 JORDAN,E L Division of Emergency Preparadness & Engineering
 Response (Post 830103) B4/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 30-000:84/02/24.8401170066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
- NOITHOUSE IS AND COLUMN TO THE PROPERTY OF T
- R Periodic operating reports & related correspondence
- 8402020263 Forwards "Annual Summary Rept on Monitoring & Reporting Program at Diablo Canyon Power Plant During 1983" & "Thermal Effects Monitoring Program 1983 Annual Rept "
 THORNBERRY, R C Pacific Gas & Electric Co B4/01/30 JONES, K R
 California, State of 2pp 22052 260 24X Fiche 50-275, 84/01/30, B4020202A3
 - -8402020265 "Annual Summary Rept on Monitoring & Reporting Program at Diablo Canyon Power Plant During 1963 " * Pacific Gas & Electric Co 83/12/31 51pp 22052.262, 24X Fiche 50-275.84/01/30.8402020263
- -8402020272 "Thermal Effects Monitoring Program 1783 Annual Rept "
 W/two oversize maps Aperture cards are available in FDR
 * Pacific Oas & Electric Co 83/12/31 260pp, 22052 313 24X
 Fiche 50-275.84/01/30.8402020243
- Reportable occurrences, LERs & related correspondence
- 120160 Board Notification 84-014 forwards H Hudson allegations re n wall thickness requirements in RCPB SENNUT.D 0 Division of Licensing 84/01/24 PALLADINO, LINSKY, ROBERTS Commissioners 3pg 22241 080, 24X che 50-275,84/01/24,8312120160
-)2150323 Forwards addl H Hudson allegations re facility @A ualifications

 OGSTEN.J K Commissioners 84/01/13 DENTON,H Office of Johan Reactor Regulation, Director 1,9 22241 083 24X che 50-275,84/01/24,8312120140
 - 5 Forwards H Hudson 840102 memo re 840109 allegation interview .uis Obispo.CA.per 840110 telcon 2 F Region 5. Office of Director 84/01/10 GILINSKY, V ioner ip 22241 084 24X Fiche 50-275,84/Q1/24,
 - 7 Repts QA deficiencies in ultrasonic measurement of RCPB for min wall thickness requirements. Supporting tation enci 4 Pullman. Inc 84/01/02 QILINSKY, V Commissioners 22241 085 24X Fiche 50-275,84/01/24.8312120160.

- T Hearing transcripts on non-antitrust matters
- 8402030042 Transcript of 840123 Commission affirmation/discussion & vote in Washington, DC re SECY-84-1 Pp 1-5 W/supporting documentation # Commissioners 84/01/23 9pp 22091 118 24X
- 8402030388 Transcript of Commission 840123 discussion in Washington.DC Pp 1-4i Supporting documentation encl # Commissioners 84/01/23 66pp 22090 126 24X Fiche 50-275.84/01/23,8402030388
- 8401190019 Board Notification 84-022 forwards transcript of NRC meeting w/C Stokes re allegations concerning small bore piping Transcript identifies certain individuals by name & withheld from public disclosure EISENHUT.D 0 Division of Licensing 84/02/07 PALLADING, GILINSKY, ROBERTS Commissioners 3pp 22139 231 24X Fiche 50-275,84/02/07,8401190019
- 8401190036 Board Notification 84-025 forwards transcript of 840131 meeting w/util re review of small bore piping analyses EIBENHUT.D 0 Division of Licensing 84/02/08 PALLADIND,N J , GILINSKY,V , ROBERTS.T Commissioners 3pp 22200 331 24X Fiche 50-275.84/02/08,8401190036
- -8402130076 Transcript of 840131 meeting w/util in San Francisco,CA re review of small bore piping analyses Pp 1-128 Bupporting documentation encl * Commissioners 84/01/31 162pp 22200 334 24X Fiche 50-275,84/02/08,8401170036
- 8402170519 Transcript of Commission 840210 public meeting in Washington, DC re comments by parties on Diable Canyon criticality & low power operation Pp 1-96 Supporting documentation encl 84/02/10 125pp 22305 201 24x Commissioners Fiche: 50-275, 84/02/10, 8402170519
- U Congressional/Executive Correspondence
- 8402270002 Responds to FOIA request for correspondence NRC received from Senators J McClure, JB Johnston & P Lexalt during past 2 yrs Forwards App A documents. Name of individual deleted from Documents 8 & 9 of App A (ref FOIA Exemption 6), FELTON, J M Division of Rules and Records, 83/11/30, KDLI, E, Cable News Network, Inc. App 22438 002 24X Fiche 50-000, 83/11/30, 8402270002
- --B402270067 Forwards rept covering Phase 1 investigation into circumstances surrounding development of "Freliminary Rept, Seismic Reverification Program " Rept covering second phase due to Commission in Fab 1982 W/o encl KAMMERER. C Office of Congressional Affairs 82/01/27 OTTINGER,R L House of Rep , Energy & Commerce. SIMPSON.A Benate, Environment & Public Works UDALL.M House of Rep , Interior & Insular Affairs 2pp. 22438:026, 24% Fiche 50-000,83/11/30.8402270002
- --8402290082 Forwards rept covering Phase 2 investigation into circumstances surrounding development of "Preliminary Rept, Beismic Reverification Program." W/o enc! KAMMERER, C. Défice of Congressional Affairs. 82/02/10 OTTINGER.R.L. House of Rep., Energy & Commerce. SIMPSON, A Benate. Environment & Public Works UDALL. M. House of Rep., Interior & Insular Affairs. 2pp. 22438-028 24% Fiche. 50-000, 83/11/30, 8402290002
- ---8402290118 Discusses seismic design verification program for facilities, required by Commission Billi7 order NRC approved proposal of util to retain Teledyne to conduct independent audit
 RAMMERER,C Opfice of Congressional Affairs 82/04/UI
 MOFFETT:T House of Rep., Government Operations, HATFIELD,M
 Senate, Appropriations BEVILL,T House of Rep., Appropriations
 ip. 22438:035 24% Fiche 30-000.83/ii/30.8402290002.
- 84020700B1 Further response to FOIA request for IE Insp Rept 77~17, associated notice of proposed imposition of civil penalties, notice of violation & order to show cause, Forwards App A documents. Documents also available in PDR FELTON. J M Division of Rules and Records 83/12/20 HAMLIN, J Shaw, Pitthan, Potts & Troubridge, 4pp 2218B:104 24% Fiche 50-000.83/12/20,84020700B1 HAMLIN, J B.
- --8402090127 Requests testimony on Commission position re adequacy of licenses GA programs at Subcommittee on Energy & Environ 811027 hearing on GA as applied to reactors under const.

 UDALL.M K House of Rep. Interior & Insular Affairs. Bi/10/13 FALLADING.N. Commissioners 1p. 22188, 112 24X
 Fiche 50-000,83/12/20,8402090081

- 8402010262 Requests thorough investigation of worker allegations about safety, poor quality, intimidation & falsification of records Investigation should be completed prior to allowing low power operation MCCORQUODALE, D California, State of 84/01/19 FALLADINO, N COMMISSIONERS 1p 22040 359 24X Fiche 50-275, 84/01/19, 8402010262
- 8402010078 Objects to authorization of plant operations prior to resolution of allegations Independent audit of design review & comprehensive GC reinsp & Offic of Investigations review of GA/GC breakdown causes recommended ALATORRE. R California, State of 84/01/23 PALLADINO, V Commissioners ip 22042 186 24X Fiche 50-275.84/01/23, 8402010078
- 8402280356 Recommends that prior to decision re licensing for post-criticality testing & full power testing. Commission provide guidelines governing evaluation of allegations reconst QA deficiencies

 FANETTA, L E House of Rep 84/02/08 PALLADING, N J
 Commissioners 2pp 22402 275 24% Fiche 30-275,84/02/08,8402280356
- 8402280370 Requests listed info, including info re allegations on failure to perform pipe support calculations & alleged instruction that inspectors did not inspect vendor-supplied matl welds Info requested by 8404061 UDALL.M K House of Rep., Interior & Insular Affairs 84/02/22 PALLADINO, N Commissioners 3pp 22407 134 24X Fiche 50-275,84/02/22,8402280370
- DOCKET 50-924 GRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

 F Becurity, medical, emergency & fire protection plans
- B402050487 Summary of B31207 meeting w/util in Sethesda.MD re review of outstanding items & progress on alternate shutdown capability assessment & mods per 10CFR50.App R MACKAY.S Operating Reactors Branch 2 84/01/17 Operating Reactors Branch 2 84/01/17 Setup 24X Fiche 50-324.84/01/17. B402060487
- 8402140241 Ack receipt of 840113 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-324/83-26 & 50-325/83-26 VERRELLI,D M Division of Project & Resident Programs 84/01/19 UTLEY,E E Carolina Power & Light Co ip 22220 283 24X Fiche 50-324,84/01/19,8402140241
- --B402140248 Supple response to NRC B30830 ltr re violations noted in IE Insp Repts 50-324/83-26 & 50-325/83-26 Corrective actions drawings & procedures revised & walkdown of fire protertion sys completed DIETZ, C R Carolina Power & Light Co B4/01/13 O'REILLY, J P Repion 2. Defice of Director ip 22220 R84 24X Fiche 50-324,84/01/19,8402140241
- 8402170232 Revised emergency plan implementing procedures, including Procedures PEP+02 2 re emergency control-unusual event, PEP-02, 3 re emergency control-slort & PEP-02 4 re emergency control-site emergency W/840213 ltr
 HGMEsP W Carolina Power & Light Co 84/01/26 0'REILLY. J P Region 2. Office of Director 150pp 22276 162 24X
 Fiche 50-324,84/01/26,8402170232
- 8402080278 Forwards App R fire protection alternative shutdown capability assessment, second quarterly rept HOME: P M. Carolina Power & Light Co 84/01/30 VASSALLO, D B Operating Reactors Branch 2 1p 22131 332 24X Fiche 50-324, 84/01/30, 8402080298
- --84020B0301 App R fire protection alternative shutdown capability assessment second quarterly rept
 + Carolina Power & Light Co 84/02/29 71pp 22131 333 24X Fichs 50-324, 84/01/30, 8402080278
- 8402130153 Forwards Rev 1 to position paper on Reg Ouide 1 97 & response to NUREG-0737. Suppl 1.Reg Guide 1 97 re swargency response facilities Rev supersedes 830930 submittal
 ZIMMERNAN.B R Carolina Power & Light Co 84/02/01 VASSALLO, D B Operating Reactors Branch 2 1p 22199 286 24X Fiche: 50-324.84/02/01,8402130153
- --B402130159 Rev 1 to "Position Paper on Reg Guide 1 97 " BROWN.W E Carolina Power & Light Co 83/10/26 120pp 22199 287 24X Fiche 50-324,84/02/01.8402130153

- B402130244 Forwards updated technical support ctr & emergency operations facility floor plans, route maps & tolephone listings * current personnel access document, per B30912 request ZIMMERMAN, S.R. Carolina Power * Light Co. 84/02/02 VASSALLO, D.B. Operating Reactors Branch 2 16pp 2P200 227 24X Fishe 50-324, 84/02/02, 8402130244
- B402150509 Summary of 840116 meeting w/util in Bethesda, MD re fire protection Util planning request for exemptions from App R to 10CFR50 re alternate shutdown capability Separate meeting held on 84020, to discuss exemptions MACKAY, S. Operating Reactors Branch 2 84/02/02 Operating Reactors Branch 2 650 324, 84/02/02, 840150509
- 8402230420 Requests remission of Class I & III fees re 821213 application proposing radiological effluent Tech Spec changes & 830502 request for exemption from IOCFR50.App R MILLER.W O License Fee Management Branch 84/02/07 UTLEY.E E Carolina Power & Light Co 2pp 22380 045 24% Fiche 50-324.84/02/07 8402230420
- 8402270270 Unit O embrgency response plan procedures.Vol YIII.Book 1.
 Rev 12.including Emergency Procedure PEP-01 0.Vol XIII.Rev
 7 W/840221 1ti
 BURTON.W. HOME,P W Carolina Power & Light to 84/02/14
 0'RETLLV.J P Region 2. Office of Director 60pp 22386 102 24x
 Fiche 50-324.84/02/14.8402270270
- 8402280467 Requests exemption from 10CFR50. App E. permitting State of NC & Counties of Brunswick & New Henover to conform to 44CFR350 9 & exempting entities from participation in emergency preparedness exercise scheduled for May 1984 HOME.P W Carolina Power & Light Co 84/02/21 VASSALLO,D B Operating Reactors Branch 2 3pp 22402 313 24X Fiche 50-324.64/02/21,8402280469
- H General correspondence
- B209170054 Requests responses re London Nuclear Con-Decon solution used on reactor coolant recirculation pumps during sys cleanup DREY.K Affiliation Not Assigned B2/09/13 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22393 361 24X Fiche 50-000.84/02/03.8209170054
- B402240216 Final response to FOIA request for documents re replacement piping at facility Forwards App A & B documents Documents also available in POR FELTON, J M Division of Rules and Records B4/02/03 BELL, N Nuclear Information & Resource Service 3pp 22393 230 24X Fiche 50-000.840/2/03.840240216
- P Operating license stage documents & correspondence
- B312120029 Generic Ltr B3-39 to representatives of utils re voluntary survey of licensed operators Svc list encl EISENHUT.D 0 Division of Licensing B3/12/08 Commonwealth Edison Co 12pp 22313 OOA 24% Fiche 50-000, B3/12/08, B312120029
- 8402090408 Partial response to FOIA request for four categories of documents re NUREO-75/087 (NUREO-0800). "SRP for Review of SARs for Nuclear Plants " Review of remaining documents incomplete Forwards App A documents FELTON.J M Division of Rules and Records 83/12/30 MADDEN.T J Kaye. Scholer, Fierman, Hays & Handler App 22193 003 24X Fiche 50-000.83/12/30,8402090408
- --B4021001B7 Identifies inconsistency in unidentified max primary sys leak rate NUREG-75/047 cited as guidance Recommends inconsistency be referred to NRR for resolution CANTRELL.F S Region 2. Atlanta. Office of the Director 76/11/23 LDNG.F J Region 3. Chicago, Office of the Director ip 22193 029 24% Fiche 50-000.83/12/30.8402090408
- 8402040280 Forwards request for add1 info re reload methodology, to complete review of NF-1583 04, "Verification of CPL Ref IWR Thermal-Hydraulic Methods Using FIBWR Code " Response requested within 60 days of ltr receipt VASBALLO.D B Operating Reactors Granch 2 84/01/17 UTLEY.E C Carolina Power & Light Co 4pp 22093 023 24X Fiche 50-324,84/01/17,8402040280
- 8402060070 Responds to 830929 amend request re feedwater & main turbine trip/bypass sys Based on preliminary analysis risk for operating facilities w/o reck Spors on surveillance of highwater level turbine trip/bypass sys small VASSALLO.D B Operating Reactors Branch 2 84/01/18 UTLEY.E E Carolina Power & Light Co 2pp 22110 061 24X Fiche 50-324.84/01/18,8402060070

- 8402080236 Advises that proposed Tech Spec revs for NURFG-0737 items, per Generic Ltr 83-36, will be submitted by B40302 ZINNERMAN.S R Carolina Power & Light Co 84/01/27 VASSALLO,D B Operating Reactors Branch 2 ip 22134 234 24X Fiche 50-324,84/01/27,8402080236
- 8402140509 Informs that 831209 request for relief from hydrostatic test requirements of IMA-4400 & IMA-5000 of ASME Code, Section XI
 - granted SER enc. 1
 VASSALLO.D B Operating Reactors Dranch 2 84/01/27 UTLEY, E Carolina Power & Light Co 2pp 22258 129 24X
 Fiche 50-324, 84/01/27, 8402140509
- --B40214050B Safety evaluation re util 831209 request for relief from hydrostatic pressure requirements of ASME Code, Section XI Request granted

 Office of Nuclear Reactor Regulation, Director B4/01/27 2pg 22258 831 24X Fiche 50-324,84/01/27,8402140509
 - B4/01/27 2pp
- B402060114 Submits summary of 831227 site meeting re events following failure of emergency battery 2A2 to pass 18-month load profile surveillance test Slides & matls presented at meeting encl
 CUTTER.A B Carolina Power & Light Co 84/02/02 VASSALLO,D B
 Operating Reactors Branch 2 17pp 22088 282 24X
 Fiche 50-324.84/02/02.8402060114
- 8402140606 Informs that info re NUREC-0737. Items II F & 4-6, not yet received per 820406 request Response to encl requests for add info or schedule for response requested within 30 days
- of its receipt VASSALLD D B or itt receipt
 VASSALLO,D B Operating Reactors Branch 2 84/02/02 UTLEY,E.E
 Carolina Power & Light Co 17pp 22256 300 24x
 Fiche 50-324.84/02/02,8402140606
- 8402230315 Forwards safety evaluation on NUREG-0737. Item II K 3 18 re automatic depressurization sys logic mods Maintaining sys w/o mod unacceptable Response requested within 30 days VASBALLO, D B Operating Reactors Branch 2 84/02/02 UTLEY, E E Carolina Power & Light Co 7pp 22371 224 24X Fiche 50-324.84/02/02.8402230315
- 3402130228 Forwards responses to draft technical evaluation rept open items re control of heavy loads.per 831103 ltr Crane operators trained per ANBI 830 2-1976 requirements installation of new fuel storage racks in progress ZIMMERMAN.9 R Carolina Power & Light Co 84/02/03 VA8SALLD.D B Operating Reactors Branch 2 10pp 22200 121 24X Fight Reactors Branch 2 10pp 22200 121 24X ZIMMERMAN, S.R. Carolina rower & Operating Reactors Branch 2 10 Fishs 50-324,84/02/03,8402130228
- 02130001 Requests exception to ANSI-B30 2-1976 Section 2-2 2 2 b(3), "Rated Load Test." per 821116 ltr re control of heavy loads Requirements unnecessary & too stringent Response requested prior to Mar 1984 Unit 2 outage ZIMMERMAN.S.R. Carolina Power & Light Co. 84/02/06" VASSALLO.D B Operating Reactors Branch 2 2pg 22204 090 24X Fiche 50-324,84/02/06.8402130001
- 3402130294 Forwards responses to B3090) request for add1 info re electrical distribution sys voltages, per B31130 commitment Worst case min grid voltage lower than data originally supplied to United Engineers & Constructors Information of Carolina Power & Light Co 84/02/06 VASEALLO, D B Operating Reactors Branch 2 11pp 22202 118 24% Fiche 50-324,84/02/06,8402130294
- 9402230420 Requests remission of Class I & III fees to 821213 application proposing radiological effluent Tech Spec changes & 830302 request for exemption from 10CFR50.App R. MILLER, W O License Fee Management Branch 84/02/07 UTLEY, E E Carolina Power & Light Co 2pp 22380 045 24X Fiche 50-324,84/02/07,8402230420
- 1402220430 Supple B40112 response to Generic Ltr 83-41 re fast cold starts of diesel generators Percentage of starts for surveillance & maint activities & actual demand did not change significantly for semester following 830531.

 ZIMMERMAN.S R Caroling Power & Light Co 84/02/09 VASSALLO, D Geneting Reactors Branch 2 3pp 22340 159. 24%

 Fiche 50-324,84/02/09,8402220430. VASBALLO, D. B.
- 402230077 Requests withdrawal of 820831 & 830929 requests for license amends re electrical power sys & limiting conditions for operation & surveillance requirements for feedwater/main turbine trip & actuation instrumentation, respectively. HOME.P W Carolina Power & Light Co 84/02/14, VASBALLO,D B Operating Reactors Branch 2 ip 22362 253 24X Fiche 50-324.84/02/14,8402230077

- 8402280537 Corrects error in 840203 response to open issues in draft technical evaluation rept re control of heavy loads Testing & maint program for spent fuel cask yolk in compliance w/spers ZIMMERMAN.S R Carolina Power & Light Co B4 Operating Reactors Branch 2 Ip 22406 314 Fiche 50-324,84/02/20,8402280537
- Q Inspection reports, IE Bulletins & correspondence
- 8402010027 Discusses IE insp on 830318-0415 & forwards notice of violation & proposed imposition of civil penalty O'REILLY, J P Region 2. Office of Director 84/01/10 UTLEY, E Carolina Power & Light Co 3pp 22048 114 24X Fiche 50-324,84/01/10,8402010027
- --B40201003B Notice of violation & proposed imposition of civil panelty in amount of \$40,000 Noncompliance noted Unit 1 deluge sys standby gos treatment sys trains 1A & B rendered inoperable when valve 1-WH-V207 shut from 830211-0313

 O'REILLY, JP Region 2. Office of Director B4/01/07 Spp 22048 117 24X Fiche 50-324.84/01/10.8402010027
- 8402140467 Suppls response to IE Bulletin 83-03 re valve insp program Util inspects valve internals verifying operability on two valves per yr periodicity Insp incorporated in Procedure NI-10-5211 HOME:P.W. Carolina Power & Light Co. 84/01/16 O'REILLY, J.P. Region 2. Office of Director ip 22221 098 24X Fiche 50-324.84/01/16.8402140467
- 8402140241 Ack receipt of 840113 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-26 & 50-325/83-26
 VERRELLI.D M Division of Project & Resident Programs 84/01/19
 UTLEY,E E Carolina Power & Light Co 1p 22220 283 24X
 Fiche.50-324,84/01/19,8402140241
- --B402140248 Buppls response to NRC B30B30 ltr re violations noted in IE Insp Repts 50-324/83-26 & 50-325/B3-26 Corrective actions drawings & procedures revised & welkdown of fire protection systemplated DIETZ.CR Carolina Power & Light Co 84/01/13 O'REILLY, J P Region 2. Office of Director ip 22220.284 24X Fiche 50-324,64/01/19,8402140241
- 8402140293 Ack receipt of 831230 supplemental itr informing NRC of steps taken to correct Significant Finding C noted in IE Insp Repts 30424/80-43 & 50-325/80-45
 VERRELLI.D M Division of Project & Resident Programs 84/01/19, UTLEY.E E Carolina Power & Light Co 1p 22228-256 24X
 Fiche 50-324,84/01/19,8402140293
- --B402140300 Responds to NRC ltr re Bignificant Finding C noted in IE Insp Repts 50-324/80-43 & 50-325/80-45 Corrective actions, improved sys for condensor pit releases will be completed by 840430
 DIETZ, C R Carolina Power & Light Co 83/12/30 O'REILLY, J P Region 2, Office of Director 1p 22228-257. 24X
 Fiche. 50-324,84/01/19,8402140293
- 8312120153 IE Info Notice 84-06, "Bteam Binding of Auxiliary Feedwater Pumps." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche.50-000,84/01/25,8312120153
- 8402140070 Discusses IE Insp Repts 50-324/80-43 & 50-325/80-45.
 Util request that Violation D re radiation area posting of reactor files be withdrawn denied Only posting entrance to reactor files fails to meet regulatory intent D'REILLY.J P Region 2. Office of Director 84/01/27. UTLEY, E E. Carolina Power & Light to 2pp 22217.179 24X
 Fiche 50-324,84/01/27.8402140070
- 8402140229 Ack receipt of 831222 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-05 & 50-325/83-05 Commitment to training by 831231 described in 830520 response acceptable VERRELLI
- --8402140232 Responds to NRC ltr re violations noted in IE Insp Repts 50-324/83-05 & 50-325/83-05 Corrective actions, required training will be completed by 831231.

 DIETZ, C R Caroline Power & Light Co 83/12/22, O'REILLY, J P Region 2, Office of Director. ip. 22230,024, 24X Fiche 50-324,84/01/31,8402140229

- B401190016 IE Info Notice 84-07. "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000.84/02/03.8401190016
- B401190017 IE Bulletin B4-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl BEYDUNG.R C Director's Office, Dffice of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp. 22177 156 24X Fiche 50-000.84/02/03.8401190017
- 8402150275 Forwards response to NRC 840110 notice of violation & proposed imposition of civil penalty & IE Insp Repts 50-324/83-11 & 50-325/83-11 Payment in amount of \$40,000 for proposed civil penalty also encl MCDUFFIE.M A Carolina Power & Light Co 84/02/09 DEYOUNO.R C Director's Office. Office of Inspection and Enforcement 11pp 22230 071 24X Fiche 50-324.84/02/09.8402150275
- BAC2220537 Forwards Rev 1 to "Design Rept for Weld Overlay Repairs at Brunswick Steam Electric Plant Unit 2," per B31128 commitment Weld joints containing intergranular stress corrosion cracking indications will be reinspected HOME,P W. Carolina Power & Light Co 84/02/10 VASSALLO,D B Operating Reactors Branch 2 7pp 22333 192 24X Fiche: 50-324, 84/02/10, 8402220537
- --8402220541 Rev 1 to "Design Rept for Weld Overlay Repairs at Brunswick Steam Electric Plant Unit 2 " OND, H J NUTECH Engineers, Inc CPL-13-104 RO1 89/12/31 84pp 22333 199 24X Fiche 50-324,84/02/10.8402220537
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (1005R50: App R) " Svc list ent!

 JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259 24X Fiche 50-000.84/02/13,8401190041
- 8402280048 Ack receipt of 840207 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-41 & 50-328/83-41 WERRELLI,D M Division of Project & Resident Programs 84/02/13 UTLEY,E E Carolina Power & Light Co ip 22401 124 24X Fiche 50-324/84/02/13.8402280048
- --8402280056 Responds to NRC 840111 ltr re violations noted in IE Insp Repts 50-324/83-41 & 50-325/83-41 Corrective actions technician given specific counseling re completion of Step VII 8 & disciplined per company policy HOWE.P W Capolina Power & Light Co 84/02/07 O'REILLY, J P Region 2. Office of Director 3pp 22401 125 24X Fiche 50-324,84/02/13.8402280048
- --8402280067 Forwards IE Insp Repts 50-324/63-41 & 50-325/63-41 on 831115-1215 & notice of violation VERRELLI, D.M. Division of Project & Resident Programs 84/01/11 UTLEY, E.E. Carolina Power & Light Co. 2pp 22401 128 24X Fiche. 50-324, 84/02/13, 8402280048
- --8402280073 Notice of violation from insp on 831115-1215 * Region 2. Office of Director 84/01/11 ip 22401 130 24X Fich: 50-324,84/02/13.8402280048
- --8402280081 IE Imap Repts 50-324/83-41 & 50-325/83-41 on 831115-1215 Violations noted steam jet air ejector radiation monitor calibr not implemented & GP-O1 inadequately established MYERS.D O, GARNER.L W Region 2. Office of Director BEMIS.F R Division of Project & Resident Programs 84/01/09 9pp 22401 131 24X Fiche 50-324.84/02/13.8402280048
- B401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '" Bvc list encl JDRDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/14 Consolidated Edison Co. of New York, Inc. 115pp 22365 141 24X Fiche.50-000,84/02/14,8401190039
- 8401190045 IE Info Notice 83-63, Suppl i, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN: E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York: Inc. 118pp 22366.142 24X Fiche 50-000,84/02/15,8401190045
- 8402280320 Informs that future integrated containment leakage rate tasts (ILRTs) will be scheduled based on date of performance of previous tast, w/exception of fourth test, to be performed coincident w/10-yr inservice inap HOME.P.W. Carolina Power & Light Co 84/02/16 VASSALLO.D B Operating Reactors Branch 2 2pp 22399:099 24X Fiche: 50-324, 84/02/16, 8402280320

- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value" Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc. 116pp 22366 024 24X Fiche 50-000,84/02/21,8401190062
- 8402280739 Ack receipt of 840209 ltr & payment of \$40,0000 for civil penalty proposed by NRC on 84010 Exam of corrective actions continuing AXELRAD. J A Director's Office, Office of Inspection and Enforcement 84/02/21 UTLEY.E E Carolina Power & Light Co 2pp 22414 343 24X Fiche 50~324,84/02/21,8402280739
- 8401190066 IE Info Notice 84-11, "Training Program Deficionates "

 Svc list enal
 JDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/27 Consolidated Edison Co of New York, Inc 120pp 22431 060 24X Fiche 50-000.84/02/27.840119006/
- R Periodic operating reports & related correspondence
- 8402080298 Forwards App R fire protection alternative shutdown capability assessment second quarterly rept HOWE.P W Carolina Power & Light Co 84/01/30 VASSALLO.D B Operating Reactors Branch 2 ip 22131 332 24x Fiche 50-324,84/01/30,8402080298
- --8402080301 App R fire protection alternative shutdown capability assessment second quarterly rept * Carolina Power & Light Co 84/02/29 7ipp 22131 333 24X Fiche 50-324,84/01/30,8402080298
- B402140364 Monthly operating repts for Jan 1984 W/840206 ltr HARRISON.F., DIETZ, C.R. Carolina Power & Light Co. B4/01/31 DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 13pp 22220 076 24X Fiche 50-324,04/01/31.
- 8 Reportable occurrences, LERs & related correspondence
- 840R030407 Updated LER B3-097/01T-1 on B31212, during testing, per IE Bulletin B3-02, crack indications discovered in 19 of 131 welds in reactor recirculation & reactor water cleanup sys Caused by stress corrusion cracking W/840124 ltr PASTVA, M J , DICTZ, C R Carolina Power & Light Co 84/01/24 O'REILLY, J P Region 2, Office of Director App 2206B 320 24X Fiche 50-324, 84/01/24, 8402030407
- 8402030450 RO on B31218. Fire barrier limiting condition for operation generated for single fire door on 50-ft elevation in diesel generator bldg Caused by high differential air pressure across door Problem under evaluation DIETZ.C.R. Carolina Power & Light Co. 84/01/24 O'REILLY. J. P. Region 2. Office of Director ip 22066 253 24X Fiche 50-324.84/01/24.8402030450
- 8402030276 Updated LER 83-078/03L-1 on 830807, operability testing of reactor recirculation sys jat pump performed ence during initial 24 h period during startup operational Mode 2, instead of in operational Mode 2 W/840125 ltr PABTVA, M J. DIETZ. C R Carolina Power & Light Co B4/01/25 D'REILLY, J P Region 2, Office of Director 2pp 22067 107 24X Fiche 50-324.84/01/25.8402030876
- B402030363 RO 2-B3-96 on B31226, augmented offgas bldg & diesel generator bldg fire hose stations rendered inoperable due to freeze-related failures of fire protection standpipe sys isolation valves investigation incomplete Rept by B40203 DIETZ.CR Carolina Power & Light Co 84/01/25 O'REILLY, J Region 2. Office of Director 1p 22046.077 24X Fiche 50-324,84/01/25,8402030363
- 8402230347 Updates status rept on BWR pipe cracks & protection of upcoming licensee actions Inspiresults encl Evaluation & recommendations re interim & long-term remadial measures expected by May 1984
 DIRCKS,W J Office of the Executive Director for Operations BECY-84-009A 84/01/27 5pp 22377 047 24X Fiche 50-000. 84/01/27.840230347

- 402140255 Updated LER 83-019/01T-1 on 830210, NRC Inspector observed instrument air tubing to safety relief & automatic depressurization says valve accumulators inadequately supported Addl supports installed W/840130 ltr PASTUA, M J Carolina Power & Light Co 84/01/30 G*REILLY, J P Region 2. Office of Director 3pp 22227 160 24X Fiche 50-324,84/01/30,8402140256
- 40214045B Forwards current status of investigation involving LER 2-83-95 re fire penetration seal deterioration & revised dates for submittal of action plan & completion of investigation
 DIETZ.C R Carolina Power & Light Co 84/01/31 O'REILLY.J P
 Region 2. Office of Director 3pp 22221 101 24X
 Fiche 50-324.84/01/31.840214045B
- 402130339 LER 83-096/03L-0 on 831826, augmented offgas bldg fire hose stations 2-AOG37 to 62 inoperable due to valve body crack rupturing Caused by low ambient outside air temp & lack of heat tracing Valves V901 & V904 replaced W/840203 itr PASTVA.H J. DIETZ.C R Carolina Power & Light Co 84/02/03 UTRELLY.J P Region 2. Office of Director 3pp 22198 209 24X Fiche 50-324,84/02/03,8402130339
- 402150344 RO on 840103, diesel driven fire pump inoperable Cause due to unavailability of replacement parts allowing 7-day time frame to be exceeded Starter motor repaired & diesel fire pump returned to svc on 840124
 DIETZ.C R Carolina Power & Light Co 84/02/07 D'REILLY, J P Region 2. Office of Director ip 22250 251 24X
 Fishe 50-324.84/02/07.8402150344
- 402220553 Updated LER 83-052/03L-i on 630526, alligator clip test leads connected across instrument test terminals of RHR sys flow transmitter accidently bumped & detached Caused by technician error due to anticontaminate dress W/840210 ltr PASTVA.M J. DIETZ.C R Carolina Power & Light Co 84/02/10 O'REILLY.J P Region 2. Office of Director 2pp 22333 150 24X Fiche 50-324,84/02/10.8402220553
- 402220886 Updated LER 82-123/03L-3 on 821010, loss of 4160-volt emergency bus E-3 occurred Caused by output breaker failing to close when unit availiary transformer output breaker opened New broaker installed W/840210 ltr PDULK,R M, DIETZ,C R Cerolina Power & Light Co 84/02/10 O'REILLY,J P Region 2, Diffice of Director 3pp 22391 383 24X Fishe 50-324,Q4/02/10.8402220586

Onsite Storage of Low Level Waste

- 402070377 Informs of methods to obtain scaling factors for pil & irradiated components waste streams per 100FR61 Scaling factors for irradiated components taken directly from NUREO-0782 TIMMERAN.S R Carolina Power & Licht Co 84/02/02 EISENRUT.
- NUMEG-0782
 ZINNERMAN,S R Carolina Power & Light Co 84/02/02 EISENHUT,D 9
 Division of Licensing 3pp 22099 316 24X Fiche 30-000,84/02/02,8402070377
- OCKET 50-325 GRUNSWICK STEAM ELECTRIC PLANT, UNIT 1
- Security, medical, emergency & fire protection plans
- 402060487 Summary of B31207 meeting w/util in Bethesda.MD re review of outstanding items & progress on alternate shutdown capability assessment & mods per 10CFRSO.App R
 MACKAY.S Operating Reactors Branch 2 84/01/17 Operating Reactors Branch 2 8pp 22110 194 24X Fiche 50-324,84/01/17,
- 402140241 Ack receipt of 840113 ltr informing NRC of steps taken to correct violations noted in 1E insp Repts 50-324/83-26 & 50-324/83-26 Netricular to the state of the state
- 50-325/83-26 VERRELLI,D M Division of Project & Resident Programs 84/01/15 UTLEY,E E Carolina Power & Light Co ip 22220 283 24X Fiche 50-324:84/01/19.8402140241
- -8402140248 Supple response to NRC 830830 ltr re violations noted in IE
 Insp Repts 50-324/83-26 & 50-325/83-26 Corrective actions
 drawings & procedures revised & welkdown of fire protection
 sys completed
 DIETZ.CR Carolina Power & Light Cn 84/01/13 O'RETLLY, J P
 Region 2. Office of Director ip 22220 284 24X
 Fiche 50-324,84/01/19.8402140241
- 402170232 Revised emergency plan implementing procedures, including Procedures PEP-02 R re-emergency control-unusual event, PEP-02 3 re-emergency control-alert & PEP-02 4 re-emergency control-site emergency W/840213 ltr
 HOME,P W Carolina Power & Light Co 84/01/26 D'REILLY,J P
 Region 2, Office of Director 150pp 22296 162. 24X
 Fiche 50-324,84/01/26,8402170232

- 8402080278 Forwards App R fire protection alternative shutdown capability assessment second quarterly rept HDWE.P W Carolina Power & Light Co 84/01/30 VASSALLD, D B Operating Reactors Branch 2 1p 22131 332 24X Fiche 50-324,84/01/30,8402080298
- --8402080301 App R fire protection alternative shutdown capability pssessment second quarterly rept

 « Carolina Power & Light Co. 84/02/29 71pp 22131 333 24X Fiche 50-324,84/01/30,8402080298
- B402130153 Forwards Rev 1 to position paper on Reg Guide 1 97 & response to NUREG-0737, Suppl 1,Reg Guide 1 97 response Facilities Rev supersedes 830930 submittal ZIMMERMAN, S R Carolina Power & Light Co 84/02/01 VASSALLO, D B Operating Reactors Branch 2 1p 22199 286 24% Fiche 50-324,84/02/01.4402130153
- --8402130159 Rev 1 to "Position Paper on Reg Guide 1 97 " BROWN.4 E Carolina Power & Light Co 83/10/26 120pp 22199 287 24X Fiche 50-324,84/02/01,8402130153
- 8402130244 Forwards updated technical support ctr & emergency operations facility floor plans, route maps & telephone listings & current personnel access document, per 830912 request ZIMMERMAN, B.R. Carolina Power & Light Co. 84/02/02 VABBALLO, D. B. Operating Reactors Branch 2 16pp 82200 227 24X Fiche 50-324, 84/02/02, 8402130244
- 8402150509 Summary of 840116 meeting w/util in Bethesda, MD re fire protection Util planning request for exemptions from App R to 10CFR50 re alternate shutdown capability Separate meeting held on 840202 to discuss exemptions MACKAY.8 Operating Reactors Branch 2 84/02/02 Operating Reactors Branch 2 6pp 22261 351 24X Fiche 50-324, 84/02/02, BAO2150509
- B402230420 Requests remisssion of Class I & III fees re 821213 application proposing radiological effluent Tech Spec changes & 830502 request for exemption from 10CFR50.App R MILLER.H O License Fee Management Branch 84/02/07 UTLEY,E E Carolina Power & Light Cp 2pp 22380 045 24X Fiche 50-324,84/02/07.8402230420
- B402270270 Unit O emergency response plan procedures,Vol XIII.Book i,
 Rev 12.including Emergency Procedure PEP-01 O,Vol XIII.Rev
 7 W/G40221 ltr
 BURTON,W , HOWE,P W Carolina Power & Light Co 84/02/14
 0'REILLY,J P Region 2. Office of Director 60pp 22386 102 24X
 Fiche 50-324,84/02/14,8402270270
- 8402280467 Requests exemption from 10CFR90, App E. permitting State of NC & Counties of Brunswick & New Hanover to conform to 4ACFR390 9 & oximpting entities from participation in emergency preparedness exercise scheduled for May 1784 HOWE.P 4 Carolina Power & Light Co 84/02/21 VASSALLO,D B Operating Reactors Branch 2 3pp 28402 913 24X Fiche 50-324,84/02/21,8402280469
- H General correspondence
- B209170054 Requests responses re London Nuclear Com-Decon solution used on reactor coolant recirculation pumps during sys cleanup DREY, K. Affiliation Not Assigned B2/09/13 DENTON, H. R. Office of Nuclear Reactura Regulation, Director 2pp 22393.341 24X Fichs 50-000, 84/02/03, 8209170054
- 8402240216 Final response to FDIA request for documents re replacement piping at facility Forwards App A & B documents Documents also available in PDR fELTON, J M Division of Rules and Records 84/02/03 BELL, N Nuclear Information & Resource Service 3pp 22393 230 24X Fiche 50-000, 84/02/03, 8402240216
- P Operating license stage documents & correspondence
- B312120027 Generic Ltr 83-37 to representatives of utils re voluntary survey of licensed operators Svc list encl.
 EIBENHUT.D G Division of Licensing B3/12/08 Commonwealth Edison Co 12pp 22313 OO6 24X Fiche 30-000.83/12/08.8312120029
- B402090408 Partial response to FOIA request for four categories of documents re NUREO-75/087 (NUREO-0800), "SRP for Review of BARs for Nuclear Plants " Review of remaining documents incomplete Forwards App A documents FELTON.J M Division of Rules and Records 83/12/30 MADDEN,T J. Kaye, Scholer, Fierman, Hays & Hendler App. 22193 003, 24X Fichs 50-000,83/12/30,8402090408

1

- --8402100187 Identifies inconsistency in unidentified max primary sys leak rate NUREO-75/067 cited as guidance Recommends inconsistency be referred to NRR for resolution CANTRELL.F S Region 2. Atlanta. Office of the Director 74/11/23 LONO.F J Region 3. Chicago. Office of the Director ip 22193 029 24X Fichs 50-000.83/12/30.8402090008
- 8402060280 Forwards request for addl info re reload methodology, to complete review of NF-1583 04, "Verification of CPL Ref BWR Thermal-Hydraulic Methods Using FIDWR Code "Response requested within 60 days of itr receipt VASSALLO.D B Operating Reactors Branch 2 84/01/17 UTLEY, E Carolina Power & Light Co 4pp 22073 023 24X Fiche 50-324,84/01/17,8402060280
- 84020A0070 Responds to 830929 amond request re feedwater & main turbine trip/bypass sys Based on proliminary analysis, risk for operating facilities w/o Tech Specs on surveillance of highwater level turbine trip/bypass sys small VASSALLO,D 8 Operating Reactors Branch 2 84/01/18 UTLEY,E E Carolina Power & Light Co 2pp 22110 061 24X Fiche 50-324.84/01/18.8402060070
- 8402030052 Summary of 831227 meeting w/util & Gould at site re problems w/battury 2A2 GROTENHUIS,M Operating Reactors Branch 2 84/01/20 Operating Reactors Branch 2 17pp 22091 043 24X Fiche 50-325,84/01/20, 8402030052
- B4020B0236 Advises that proposed Tech Spec reys for NUREG-0737 items, per Generic Ltr 83-36,will be submitted by 840302 ZIMMERMAN,8 R Carolina Fower & Light Co 84/01/27 VABBALLO,D B Operating Reactors Branch 2 ip 22134 234 24X Fiche,50-324,84/01/27,8402080236
- 8402040114 Submits summary of B31227 site meeting re events following failure of emergency battery 2A2 to pass 18-month load profile surveillance test. Blides & matls presented at meeting encl
 CUTTER: A B Carolina Power & Light Co 84/02/02 VASSALLO, D B Operating Reactors Branch 2 19pp 28088 282 24X
 Fichs. BO-324, 84/02/02, 8402060114
- 8402140606 Informs that info re NUREG-0737, Items II F. 1 4-6, not yet received, per 820406 request Response to encl requests for addl info or schedule for response requested within 30 days of ltr receipt.

 VABBALLO, D. B. Operating Reactors Branch 2 84/02/02 UTLEY, E. E. Carolina Power & Light Co. 17pp. 22256, 300. 24X

 Fiche 50-324, 84/02/02, 8402140606
- 8402230315 Forwards safety evaluation on NUREG-0737, Itsm II K 3 18 re automatic depressurization sys logic mods Maintaining sys W/o mod Unacceptable Response requested within 30 days, VASSALLO,D B Operating Reactors Branth 2 84/02/02 UTLEY,E E Carolina Power & Light Co 7pp 22371 224 24X Fichs 50-324,84/02/02,8402230315,
- 8402130228 Forwards responses to draft technical evaluation rept open items re control of heavy loads,par 831103 ltr. Crane operators trained per ANBI 830 2-1976 requirements. Installation of new fuel storage racks in progress ZIMMERMAN.8 R Carolina Power & Light Co 84/02/03 VABSALLO,D B Operating Reactors Branch 2 10pp. 22200.121 24X Fiche 50-324,84/02/03.8402130228
- 8402130001 Requests exception to ANSI-B30 2-1976 Section 2-2 2 2 b(3), "Rated Load Test," per 821116 ltr re control of heavy loads. Requirements unnecessary & too stringent Response requested prior to Mar 1984 Unit 2 outage ZIMMERMAN.S.R. Carolina Power & Light Co. 84/02/06. VASSALLO,D B Operating Reactors Branch 2 2pp. 22204.090 24X Fiche: 50-324.84/02/06.8402130001
- 8402130274 Forwards responses to 830901 request for add1 info re electrical distribution sys voltages.per 831130 commitment Horst case min grid voltage lower then data originally supplied to United Engineers & Constructors ZIMMERNAN.8 R. Caroline Power & Light Co 84/02/06 VASBALLO.D 8 Operating Reactors Branch 2, lipp 22202 118, 24X Firbe, 50~324, 84/02/06, 8402130294.
- 8402230420 Requests remission of Class I & III fees re 821213 application proposing radiological effluent Tech Spec changes & 830502 request for exemption from 100FR50.App R MILLER.W.O License Fee Management Branch 84/02/07. UTLEY.E E Carplina Power & Light Co. 2pp. 22380.045 24X Fiche: 50-324.84/02/07.0402230420

- 8402220430 Supple 840112 response to Generic Ltr 83-41 re fast cold starts of diesel generators Percentage of starts for surveillance & maint activities & actual demand did not change significantly for semester following 830831 ZIMMERMAN.S R Carolina Power & Light Co 84/02/09 VASSALLO, D B Operating Reactors Branch 2 3pp 22340 159 24X Fiche 50-324,84/02/09.8402220430
- 8402230077 Requests withdrawal of 820831 & 830929 requests for license amends re electrical power sys & limiting conditions for operation & surveillance requirements for feedwater/main turbins trip & actuation instrumentation, espectively HOME, P W Carolina Power & Light Co 84/02/14 VASSALLO, D B Operating Reactors Branch 2 ip 22362 253 24X Fichs 50-324,84/02/14,8402230077
- 8402280537 Corrects error in 840203 response to open issues in draft technical evaluation rept re control of heavy loads Testing & maint program for spent fuel cask yolk in compliance w/specs
 ZIMMERMAN, S. R. Carolina Power & Light Co. B4/02/20 VASALLO, D. B. Uperating Reactors Branch 2 lp 22406 314 24X
 Fiche 50-324, 84/02/20, 840280537
- G Inspection reports, IE Bulletins & correspondence
- B402010027 Discusses IE insp on B30318-0415 & forwards notice of violation & proposed imposition of civil penalty D'REILLY. J P Region 2. Office of Director 84/01/10 UTLEY.E E Carolina Power & Light Co 3pp 22048 114 24X Ficha 50-324.84/01/10.8402010027
- --B40201003B Notice of violation & proposed imposition of civil penalty in amount of \$40,000 Noncompliance noted Unit i deluge sys standby gas treatment sys trains 1A & I rendered inoperable when valve 1-WM-V207 shut from B30211-0313

 G'REILLY, J P Region 2, Office of Director 84/01/09, 5pp 22048 117 24X Fiche 50-324,84/01/10,8402010027
- 8402140467 Supple response to 1E Bulletin 83-03 re valve insp program Util inspects valve internals verifying operability on two valves per yr periodicity Insp incorporated in Procedure MI-10-5211 HOWELP W Carolina Power & Light Co 84/01/16 O'REILLY, J P Region 2, Office of Director 1p 22221 098 24% Fiche 80-324, 84/01/16, 8402140467
- B402140241 Ack receipt of 840113 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-26 & 50-325/83-26 VERRELLI.D M Division of Project & Resident Programs B4/01/19 UTLEY.E E Carolina Power & Light Co ip 22220 283 24X Fiche 30-324.84/01/17.8402140241
- --B402140248 Suppls response to NRC B30830 ltr re violations noted in IE
 Insp Repts 50-324/B3-26 & 50-325/B3-26 Corrective actions
 drawings & procedures revised & walkdown of fire protection
 sys completed
 DIETZ-C R Carolina Fower & Light Co B4/01/13 O'REILLY, J P
 Region 2, Office of Director ip 22820 284 24X
 Fiche 50-324,84/01/19,8402140241
- 8402140293 Ack receipt of 831230 supplemental ltr informing NRC of steps taken to correct Significant Finding C noted in IE Insp Repts 50-324/80-43 & 30-325/80-45 VERRELLI,D M Division of Project & Resident Programs 84/01/19 UTLEY,E E Carolina Power & Light Co ip 22228 256 24X Fiche 50-324,84/01/19,8402140293.
- --8402140300 Responds to NRC ltr re Bignificant Finding C noted in lE Insp Repts 50-324/80-43 & 50-329/80-45 Corrective actions improved sys for condensor pit releases will be completed by 840630 DIETZ.C R Carolina Power & Light Co 83/12/30 O'REILLY, J P Region 2. Office of Director ip 22228 257. 24X Fichs 50-324,84/01/19,8402140293
- B312120153 IE Info Notice 84-06. "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/25 Consolidated Edison Co. of New York, Inc. 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120153
- B402140090 Discusses IE Insp Repts 50-324/80-43 & 50-325/80-45
 Util request that Violation D re radiation area posting of reactor bldg be withdrawn denied Only posting entrance to reactor bldg fails to meet regulatory intent O'REILLY, J P Region 2, Office of Director 84/01/27 UTLEY, E E Carolina Power & Light Co 2pp 22217 199 24X
 Fiche 50-324,84/01/27,8402140090

- 102130160 Forwards response to concerns raised by NRC re quality of intergranular stress corrosion cracking (IGSCC) insps performed during Jan 1983 outage Welds w/IGSCC repaired w/weld averiage

 HOWELP W Carolina Power & Light Co 84/01/31 DENTON.

 of Nuclear Reactor Regulation, Director Spp 22204 092

 Fiche 50-325,84/01/31.8402130160 DENTON, N R Destan
- 102140229 Ack receipt of 831222 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-05 & 50-325/83-05 Commitment to training by 831231 described in 830520 response acceptable VERRELLI,D M Division of Project & Resident Programs 84/01/31 UTLEY,E E Carolina Power & Light Co 1p 22230 023 24X Fiche 50-324.84/01/31.8402140229
- -8402140232 Responds to NRC ltr re violations noted in IE Insp Repts 50-324/83-05 & 50-325/83-05 Corrective actions required training will be completed by 831231.

 DIETZ.C R Carolina Power & Light Co 83/12/22 O'REILLY, J P Region 2. Office of Director 1p 22230 024 24X Fiche 50-324,84/01/31.8402140229
- 401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls" Svc list encl JRDAN.E L Division of Emergenty Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000.84/02/03,8401190016
- 401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Bvc list encl BEYOUNG,R C Director's Office. Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 156 24% Fichs 50-000.84/02/03.8401190017
- 402150275 Forwards response to NRC 840110 notice of violation & groposed imposition of civil penalty & IE Insp Repts
 50-324/83-11 & 50-325/83-11 Payment in amount of \$40,000 for proposed civil penalty also enci
 MCDUFFIEM A Carolina Power & Light Co. 84/02/07 DEVOUNG.R C Director's Office, Office of Inspection and Enforcement 11pp
 22250 071 24X Fiche 50-324.84/02/07.8402150275.
- 31190041 IE Info Notice 84-09. "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50.App R) " Syc list rice Protection 2017 - American Preparedness & Engineering JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259 24X Fiche: 50-000,84/02/13,8401170041
- 102280048 Ack receipt of B40207 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-41 & 50-325/83-41 VERRELLI,D M Division of Project & Resident Programs 84/02/13 UTLEY,E E Carolina Power & Light Co ip 82401 | 124 24X Fiche 50-324,84/02/13,8402280048
- -B402260036 Responds to NRC B40111 ltr re violations noted in IE Insp Repts 50-324/B3-41 & 50-325/B3-41. Corrective actions technician given specific counseling re completion of Btep VII B & disciplined per company policy HOME.P W Carolina Power & Light Co 84/02/07 O'REILLY.J P. Region 2. Office of Director. 3pp 22401:125 24X Fiche 50-324.84/02/13.8402280048
- --8402280057 Forwards IE Insp Repts 50-324/83-41 & 50-325/83-41 on 83:115-1215 & notice of violation VERRELLI.D M Division of Project & Resident Programs. 84/01/11 UTLEY/E E Caroline Power & Light Co 2pp. 22401 128 24X Firbs. 50-324.84/02/13.8402280048
- --8402280073 Notice of violation from inap on 831115-1215. * Ragion 2, Office of Director. 84/01/11 ip 2246 Fiche 50-324.84/02/13,8402280048. 22401 130, 24X
- -8402280081 IE Insp Repts 50-324/83-41 & 50-325/83-41 on 831115-1215 Violations noted steam jet air ejector radiation monitor calibr not implemented & GP-01 inadequately established MYERS, D. D. GARNER, L. W. Ragion 2. Diffice of Director. BEMIS, P.R. Division of Project & Resident Programs 84/01/09, 9pp 22401.131 24% Fiche: 50-324,84/02/13,8402280048
- 1401170039 IE Info Notice 84-08, "100FR50 7, 'Employee Protection,'" Svc list encl. JORDAN:E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 64/02/14 Consolidated Edison Co. of New York, Inc. 115pp. 22365 141 24X Fiche 50-000,84/02/14,8401190039.
- 3401194045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Westinghouse Type BA-1 Differential Relays." Byo list encl.
 JORDAN E L. Division of Emergency Praparedness & Engineering
 Response (Post 830107) RA/02/15 Consolidated Edison Co. of New Che 50-003,84/02/15,8401190045.

- 8402280320 Informs that future integrated containment leakage rate OZEGIOGEO Informs that future integrated containment leakage rat teats (ILRTs) will be scheduled based on date of performance of previous test w/asception of fourth test to be performed conncident w/10-yr inservice insp HONE, P H Carolina Power & Light Co 84/02/16 VASSALLO, D B OBERTATING Reactors Branch 2 ZPP 22397 079 24X Fiche 50-724, B4/02/16,8402280320
- B4011900A2 IE Info Notice B4-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24% Fiche 50-000.84/02/21,8401190062
- 8402280739 Ack receipt of 840209 ltr & payment of \$40,0000 for civil penalty proposed by NRC on 840110 Exem of corrective actions penalty proposed by and on 340-12 Inspection and continuing AXELRAD, J A Director's Office, Office of Inspection and Enforcement 84/02/21 UTLEY, E E Carolina Power & Light Co 200 22414 343 24X Fichs 50-324,84/02/21,8402280739
- 8401170046 IE Info Notice 84-11, "Training Program Deficiencies " 401190066 IE Into Movice C. ... Svc list encl JORDAN: E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/24 Consolidated Edison Co. of New York, Inc. 115pp 22430 304 24X Fiche 50-000.84/02/24,8401170066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals " 10119006/ IE Info Notice 84-12, "hailure of Boft Seat Valve Seals " Svc list encl JURDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/27 Consolidated Edison Co of New York, Inc 120pp 22431 040 24X Fiche 50-000.84/02/27,8401190067
- A Periodic operating reports & related correspondence
- 8402160125 Corrected monthly operating rept for Dec 1983 W/840120 ltr HARRIBON.F, DIETZ,CR Carolina Power & Light Co. 83/12/31 DEYOUNO,R C Director's Office. Office of Inspection and Enforcement 2pp 22276 042 24% Fiche 50-325,83/12/31,8402160125
- 8402080278 Forwards App R fire protection alternative shutdown capability assessment, second quarterly rept HOME: PW Caroline Power & Light Co 84/01/30. VARBALLO, D B Operating Reactors Branch 2. 1p 22131 332 24X Fiche 50-324,84/01/30.8402080298
- --B4020B0301 App R fire protection alternative shutdown capability assessment, second quarterly rapt
 * Carolina Power & Light Co. B4/02/29 7ipp 22131.333 24X
 Fichs. 50-324.84/01/30.84020B0298
- 840Pi40364 Monthly operating repts for Jan 1984 W/840204 ltr HARRISON.F., DIETZ.C R Carolina Power & Light Co 84/01/31 DEYGUNO.R C Director's Office. Office of Inspection and Enforcement 13pp 22P20 076 24X Fiche 50-324,84/01/31.
- B Reportable occurrences, LERs & related correspondence
- 8402030357 Updated LER 83-044/03L-1'on 830917, high water generator OROGOSSY Updated LER 83-044/031-1 on 830917 high water set fluid drive temp tripped reactor recirculation pump set 18. Caused by temp control valve TCC-TV-608 breaking valve pin travel arm Arm replaced. W/840124 ltr ALLEN,N T, DIETZ,C R Carolina Power & Light Co 84/4 O'REILLY,J P. Region 2, Office of Director. 2pp 2204 Fiche: 50-325,84/01/24,8402030359 22067.120 24X
- 8402030482 Updated LER B3-045/03L-2 on B30919 & 24.inboard PCIV steam supply valve E81-F007 to RCIC sys would not completely reopen Caused by loose Limitorque motor operator spring pack W840124 ltr
 ALLEN.M T. DIETZ.C R Caroline Power & Light Co 84/01/24
 D'REILLY.J P. Region 2. Office of Director. 3pp 22066 012 24X
 Fiche 50-325,84/01/24,8402030482.
- B402140005 Updated LER 79-056/03L-1 on 790808 main steam line hi radiation monitor B found actuating at 3 95 times background, above allowable I lmit Caused by instrument drift. Munitor recalibr W/840131 ltr ALLENM T. DIETZ.C R Canolina Power & Light Co 84/01/31, 0'REILLY.J P. Region 2, Office of Director 2pp 22217 356, 24X Fiche 50-325,84/01/31,8402140005.
- 8402140458 Forwards current status of investigation involving LER 2-83-95 re fire penetration seal deterioration & revised dates for submittal of action plan & completion of investigation
 DIETI,C R Carolina Power & Light Co. 84/01/31 O'REILLY, J P.
 Regian 2. Office of Director. 3pp 22221 101 24X
 Fiche 50-324,84/01/31,8402140458

- 8402240101 NPDES noncompliance notification on 840116-24, facility operated w/one fine mesh screen in svc Caused by chloring lines frozen & cracked due to extremely cold temp on 831225 Repairs completed on 840124 & both screens returned to svc HOME, P W Carolina Power & Light Co 84/02/14 WAXILD.C North Carolina 8tate of 1p 22375 004 24X Fiche 50-325,84/02/14.
- B4022703B1 RO on 840119 discovered reactor shutdown cooling & suppression pool cooling modes of RHR sys inoperable Caused by failure of RHR syc water sys investigation & evaluation of event incomplets Next rept by 840309

 DIETZ.C R Carolina Power & Light Co 84/02/17 O'REILLY, J P Region 2. Office of Director 1p 22391 182 24X

 Fiche 50-325.84/02/17.8402270381

X. Onsite Storage of Low Level Waste

8402070377 Informs of methods to obtain scaling factors for oil & irradiated components waste streams per iOCFR61 Scaling factors for irradiated components taken directly from NUREG-0782

IIMMERMAN, S. R. Carolina Power & Light Co. 84/02/02 EISENHUT, D. G. Division of Licensing 3pp. 22099 316 24X Fiche 50-000, 84/02/02, 84/02/0377

DOCKET 50-327 SEQUOYAH NUCLEAR PLANT, UNIT 1

- F. Security, medical, emergency & fire protection plans
- B402060382 Forwards Rev 7 to generic security personnel training & qualification plan Rev withheld (ref 100FR73 21)
 HILLB.L.M. Tennessee Valley Authority 84/01/19 O'REILLY, J P
 Region 2. Office of Director ip 22086 317 24X
 Fiche 50-000,84/01/19.8402060382
- 8402140384 Forwards summary of 840113 meeting in Region II ofc re emergency protective actions required by NUREG-0654 & clarified by IE Info Notice 83-28 VERRELLI,D M Division of Project & Resident Programs 84/01/26 PARRIS,H.O Tennessee Valley Authority 4pp 22220 042 24X Fiche 50-000,84/01/26,8402140384
- B402130316 Forwards Rev B to generic security personnel training & qualification plan Rev withheld MILES.L.M Tennessee Valley Authority B4/01/27 G'REILLY.J P Region 2. Office of Director ip 22197 149 24X Fiche: 50-000, 84/01/27, 8402130316
- B402130380 Forwards rev to 840101 security plan Rev withheld (ref 100FR73 21).
 MILLS,L M Tempessee Valley Authority 84/01/30 O'REILLY,J P Region 2, Office of Director ip 22202 139, 24X
 Fiche: 50-327,84/01/30,8402130380
- 8402140275 Forwards summary of 840117 meeting w/util in Region II ofc re improvement of security effectiveness & other securityrelated topics. LEWIS,R.C. Division of Project & Resident Programs. 84/02/01 PARRIS,H G Tannessee Valley Authority 4pp 22228 271, 24X Fiche: 50-000,84/02/01,8402140275
- 8402210278 Revs to Muscle Shoals emergency control ctr implementing procedures, including Procedure MSEC IP-1 re notification of unusual event, afert or transportation accident & MSEC IP-2 re site emergency or emergency director W/840210 ltr MILLB.L H Tennessee Valley Authority 84/02/02 76pp 22315 001 24X Fiche 80-000,84/02/02,8402210278
- 8402220428 Forwards revised pages to 831103 rev to physical security plan Pages withheld (ref 10CFR73 21) MILLE,L M Tennessee Valley Authority 84/02/10 D'REILLY,J P Region 2. Office of Director. 1p 22340,162, 24X Fiche: 80-327,84/02/10.8402220428
- 8402170190 Ack receipt of 831230 itr transmitting rev to physical security plan, Compensatory actions should continue to be implemented until util notified by NRR of position re rev Encl withheld (ref 100FR73 21)

 LEMIS, R. C. Division of Project & Resident Programs 84/02/13. PARRIG, H. G. Tennessee Valley Authority Rpp 22279, 041 24X Fiche 50-327, 84/02/13. 8402170190
- 8402210148 Notifies that RCS vent procedure will not be implemented until complete set of emergency operating instructions implemented per Generic Ltr 82-33 Suppl i to NUREO-0737 & TMI Item II.8 i
 MILLS.L.M Tennessee Valley Authority 84/02/15 ADENSAM.E Licensing Branch 4. ip 22316-357 24X Fiche 50-327,84/02/15,8402210148.

- 8402220096 Rev 0 to Radiological Emergency Plan Implementing Procedure IP-6, "Activation of Technical Support Ctr" & Rev 7 to Procedure IP-17, "Lmergency Equipment & Supplies " 4/830217 ltr CRAMLEY.D., GAULT.O.W., MILLS.L.M. Tennessee Valley Authority 84/02/15 0'REILLY.J.P. Region 2. Office of Director 26pp 22329 046 24X Fiche 50-327,84/02/15.8402220098
- B4022B0519 Grants B40131 request for extension to respond to deficiency Item 08 until B40330 Concurs w/decision based on need to revise energency manitoring procedures for Browns Ferry & Watts Har as well as Sequoyah VERRELLI.D M Division of Project & Resident Programs B4/02/17 PARRIS, H & Tennessee Valley Authority 1p 22406 336 24X Fiche 50-327.84/02/17.8402280519
- --8402280928 Advises that emergency monitoring implementing procedures revised for other TVA plants to maintain consistency, per commitment in response to IE losp Repts 50-327/83-13 & 50-328/83-13 Completion expected by 840300 MILLS: L M Tennessee Valley Authority 84/01/31 g'REILLY; J P Region 2, Office of Director 1p 22406 337 24X Fiche 50-327,84/02/17,8402280519
- J Insurance % indomnity information
- B402160321 Forwards Endorsements 38 % 37 to NELIA Policy NF-247, Endorsement 32 to MAELU Policy MF-102 & Endorsement 33 to MAELU Policy MF-77 Amended site description also encl DUCK, J. R. Tennessee Valley Authority B4/02/06 BALTZMAN, J. Assistant Director for State & Licensee Relations App. 22277 014 24X Fiche 50-327,84/02/06,8402160321
- O Advisory Committee on Reactor Bafeguards reports & correspondence
- B402270263 Responds to FDIA request for JC Mark 801204 memo to ACRS re hydrogen burn w/ignitors & documents concerning generation. combustion or control of hydrogen in reactor accidents Forwards App A documents App B documents in PDR FELTON, J M Division of Rules and Records B4/01/30 HIATT, 8 L Ohio Citizens for Responsible Energy 7pp 22412 051 24X Ficho 50-000,84/01/30,8402270263
- ---8402270287 Discusses ACRS review of TVA request for authorization to operate at full power Reasonable assurance should be given that ice condenser containment would hold in event of serious accident
 GILINSKY, V Commissioners 80/07/10 PLESSET, N 8 ACRS ~
 Advisory Committee on Reactor Bafeguards 1p 22412 067 24X
 Fiche 50-000, 84/01/30, 8402270283
- --8402270297 Forwards draft NRR rept on hydrogen control measures
 Proposed ignition sys would effectively prevent
 overpressurization from hydrogen burn based on MARCH &
 CLASIX computer calculations
 DESBETTED ACRS Advisory Committee on Reactor Safeguards
 80/08/18 ACRS Advisory Committee on Reactor Safeguards
 122412 072, 24X Fiche 50-000,84/01/30,8402270263
- --8402270305 Discusses proposed ACRS Subcommittee on Class 9 Accidents 800828 meeting in Washington, PC to consider hydrogen generation & control during degraded core accidents BESSETTE.D ACRS Advisory Committee on Reactor Safeguards 80/09/03 ACRS Advisory Committee on Reactor Safeguards 3pp 22412 074 24% Fiche 30-000, 84/01/30, 8402270263
- --B402270351 Comments on NUREQ/CR-1762, "Analysis of Hydrogen Mitigation for Degraded Core Accidents in Sequoyah Nuclear Power Plant "Strong recommendation that ignitors at top of ice condensers be removed debatable MARK, J C ACRS - Advisory Committee on Reactor Safeguards B1/02/02 ACRS - Advisory Committee on Reactor Safeguards B2412.136 24X Fiche 50-000,84/01/30,8402270263
- --8402270374 "Comments Re Igniters in Upper Plenum of Ice Condenser of Bequoyah & McGuire Nucler Power Plents," prepared for ACRS Bubcommittee on Class ? Accidents BICHEL, M Michigan, Univ of, Ann Arbor, MI 81/08/17 20pp 22412 184 24X Fiche 50-000,84/01/30,8402270263
- P. Operating license stage documents & correspondence
- B402010155 Forwards "Analysis of Capsule T From TVA. Sequoyah Unit 1 Reactor Vessel Radiation Surveillance Program," No changes in Tech Spec pressure temp limit curves required MILLB, L M Tennessee Valley Authority 84/01/24 ADENSAM, E Licensing Branch 4 2pp, 22038 130 24X Fiche 50-327, 84/01/24, 8402010155

- 3402010162 "Analysis of Capsule T From TVA, Sequoyah Unit 1 Reactor Vessel Radiation Surveillance Frogram " MAGER, T R. YANICHKO, S E. ANDERSON, S L. Westinghouse Electric Carp MCAP-10340 83/05/31 76pp 22038 132 24X Fiche 50-327,84/01/24,8402010155
- O2070525 Advises util of NRC actions re util 821227 request for authorization to operate vol reduction sys to process low level radwasts & 831221 request for relief from hydrostatic test requirements of ASME Code. Section XI Addl fee required MILLER. W O License Fee Management Branch 84/01/31 PARRIS. Framessee Valley Authority 2pp 22141 331 24X Fiche 50-327.84/01/31.8408070525
- 02010410 Generic Ltr 84-04 to all operating PWR licensees, CP holders applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PMR primary main loops Svc list enct EISENHUT.D G Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc. 59pp 22177 087 24X Fiche 50-000,84/02/01,8402010410
- 02070206 Advises that date of 840321 acceptable for meeting w/NRC to discuss program plan for detailed control room design reviews Concurrence on meeting date requested HILLS.L M Tennessee Valley Authority 84/02/01 ADENSAM.E Licensing Branch 4 1p 22102 212 24x Fiche 50-000.84/02/01, 8402070206
- Oii90017 IE Bulletin 84-01, "Cracks in BWR Hark I Containment Vent Headers " Svc list enc! DEYOUNG R C Director's Office, Office of Inspection and Enforcement B4702/03 Consolidated Edison Co of New York, Inc 102pp 22177 156 24X Fiche 50-000.84/02/03.8401190017
- 02130279 Forwards Rev B to offsite dose calculation manual NILLS.L M Tennessee Vailey Authority 84/02/07 ADENSAM.E Licensing Brench 4 3pp 22198 256 24X Fiche 50-327,84/02/07, 8402130279
- 1402130282 Rev 8 to offsite dose calculation manual * Tennessee Valley Authority 84/02/07 19pp Fiche 50-327,84/02/07,8402130279 . 22198 259 24X
- 02130649 Requests fee for 831024 application proposing Tech Specchanges re snubbers be remitted within 15 days of receipt of lit
- ltt MILLER, W D License Fee Management Dranch 84/02/08 PARRIB, H G Tennessee Valley Authority 19 22214 291 24X Fiche 50-327,84/02/08.8402130649
- 02210110 Bubmits implementation date for requirements of Reg Guide 1 97.per Generic Ltr 82-33 Requirements will be complied by end of Unit 2, Cycle 4 outage scheduled for B70902 MILLS,L M Tennessee Valley Authority, 84/02/14 ADENSAM.E Licensing Branch 4 1p 22316 362. 24x Fiche 50-327,84/02/14, 8400210110
- 02280185 Forwards changes to BASES to support B30721 requested Tech Spec changes for operational limits associated W/pressurizer spray nozzle Changes (madvertently omitted in B30721 ltr MILLS: M Tennessee Valley Authority 84/02/22 ADENSAM.E A. Licensing Branch 4 lp 22403 233 24x Fiche 50-327,84/02/22,
- B402280361 Proposed Tech Spec changes to DASEB re operational limits associated w/pressurizer spray nozzle * Tennessee Valley Authority 84/02/22 2pp 22403 234 24X Fiche 50-227,84/02/22.8402280185
- 02280369 Discusses mods to License Conditions 2 c(23) f & 2 c(16) g for Units 1 & 2 respectively, as requested in 831123 & 1221 ltrs Completion of planned mods will satisfy requirements of
- DL conditions
 MILLS-L M Tennessee Valley Authority 84/02/22 ADENBAM.E
 Licensing Branch 4 2pp 22402 359 24X Fiche 50-327,84/02/22,8402280368
- Inspection reports. IE Bulletins & correspondence
- 12120193 IE Info Notice 84-06, "Stoam Dinding of Auxiliary Feedwater Pumps " Svc list encl JURDAN, E L Division of Emorgency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22098 CO1 24X Fiche 50-000,84/01/25,8312120133
- 02140246 Ack receipt of 840118 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/83-25 & 50-386/83-25 VERRELLI.D M Division of Project & Resident Programs 84/01/27 PARRIEL H G Tennussee Valley Authority ip 22228 317 24X Fiche 50-327.84/01/27.8402140246

- --8402140250 Responds to NRC 831217 ltr re violations noted in IE Insp Repts 50-327/83-25 & 50-328/83-25 Corrective actions Procedure TI-20 re chemical equipment & methods revised to delete sections covered by Procedure TI-11 MILLS,L M Tennessee Valley Authority 84/01/18 0'REILLY, J P Region 2, Office of Director 2pp 22228 318 24X Fiche 50-327,84/01/27,8402140246
- --8402140251 Forwards IE Insp Repts 50-327/83-25 & 50-328/83-25 on 831114-18 & notice of violation VERRELLID M Division of Project & Resident Programs, 83/12, PARRISH 0. Tennessee Valley Authority 2pp 22228 321 24) Fiche 50-327,84/01/27,8402140246
- -8402140255 Notice of viplation from insp on 831114-18 * Region 2. Office of Director 83/12/19 ip 22228 323 24x Fichs 50-327,84701/27,8402140244
- --8402140259 IE Insp Repts 50-327/83-25 & 50-328/83-25 on 831114-18
 Violation noted failure to follow procedures for calibr
 checks of chemistry lab instrumentation
 KUZO.6 B Region 2. Office of Director MONTGOMERY, D M Division
 of Engineering & Operational Programs. 83/12/14 12pp
 22228 324. 24X Fiche 50-327.84/01/27.8402140246
- 8402180291 Responds to IE Bulletin 83-03. Item 5 re check valve failures in raw water cooling sys of dissel generators Check valves on ERCH suppy side of dissel generators acceptable Three valves on discharge side needed mod MILLG.t. M Tennessee Valley Authority 84/02/02, G'REILLY.J P Region 2. Office of Director 2pp 22250 082 24X Fichs 50-327.84/02/02,8402190291
- B401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vahicular Excess Controls," Bvc list encl JORDAN, E L. Division of Emergency Proparedness & Engineering Response (Post 830103) B4/02/03 Consolidated Edison Co. of New York, Inc. 119pp 22114 179 24X Fiche 50-000, B4/02/03, B401190016
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Bys (10CFR50, App R)." Byc list enci, JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259 24X Ficha 50-000,84/02/13,8401190041
- 8401170037 IE Info Natice 84-08, "iOCFR50 7, 'Employee Protection '" 101190037 It into notice 2. -Syc list encl
 Syc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co. of New
 York, Inc. 115pp 22365.141 24X Fiche 50-000,84/02/14,8401190039
- 8401190045 IE Info Notice 83-63. Suppl 1, "Potential Failures of Heatinghouse Type 8A-1 Differential Relays" Svc list encl JORDAN, E.L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366 142 24X Fiche. 50-000.84/02/15.8401190045
- 840R280519 Grants 840181 request for extension to respond to deficiency Item OB until 840330. Concurs w/decision based on need to revice emergency monitoring procedures for Browns Farry & Watts Bar as well as Sequoyah VERRELLI.D M. Division of Project & Resident Programs 84/02/17 PARRIS.H G. Tempesse Valley Authority. 1p. 22406-336 24X Fichs. 50-327.84/02/17.8402280519
- --8402280528 Advises that emergency monitoring implementing procedures revised for other TVA plants to maintain consistency, per commitment in response to IE Insp Repts 50-327/83-13 & 50-328/83-13. Completion expected by 840330 MILLS.L M Tennessee Valley Authority 84/01/31 O'REILLY, J P Repton R, DfPtco of Director in 22406-337. 24x Fiche. 50-327, 84/02/17, 8402280519
- B401190062 IE Info Notice B4-10, "Motor-Operated Valve Torque Bwitches Set Below Manufacturer Recommended Value " Svc list ancl.

 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). B4/02/21 Consolidated Edison Co of New York, Inc. 116pp 22366.024 24X Fiche:50-000,84/02/21,8401190062.
- 8401190066 JE Info Notice 84-11, "Training Program Deficiencies,"

 Svc list encl.

 JORDANIS L. Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/02/24 Consolidated Edison Co. of New

 York, Inc. 115pp. 22430-304. 24X Fiche.50-000.84/02/24.8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals " Bvc list encl JORDAN, E L OVC 1354 enc.; JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/27 Consolidated Edison Co. of New York, Inc. 120pp 22431 060 24X Fiche 50-000,84/02/27,8401170067

8 Reportable occurrences, LERs & related correspondence

- 8402220154 Responds to FOIA request that 146 LERs be placed in PDR Forwards LERs listed on app Documents also available in PDR Remaining LERs were either canceled or not issued FELTON, J M Division of Rules and Records 83/11/30 JEFFERBON, O A Affiliation Not Assigned 2pp 22380 052 24X Fiche 50-000,83/11/30,8402220154
- 8402080220 LER 83-187/03L-0 on 831231, two ERCW radiation monitors declared inoperable Caused by failure of monitor sample pump due to wear & tear Motor replaced, checked & returned to evc W/840127 1tr
 DUGGIN.0 E , HARDING.M R , COFFEY.J A Tennessee Valley Authority 84/01/27 0'REILLY.J P Region 2, Office of Director 2pp 22130:112 24X Fiche 50-327,84/01/27,8402080220
- 8402060205 LER 84-001-00 on 840102.high radiation alarm actuated, causing containment vent isolation to occur Caused by spurious signals on radiation monitor Alarm reset & monitor returned to svc W/84013i ltr DUGGIN, 0 . MASON, C C Tennessee Valley Authority 84/01/31 3pp 22087 158 24X Fiche 50-327,84/01/31,8402060205
- 8402100212 LER 84-009-00 on 840109.cold leg accumulator 3 declared insperable due to high boron concentration Cause not stated Accumulator drained & diluted W/840206 ltr KIRK, 0 B. M860N.C. C. Tennessee Valley Authority 84/02/06 3p. 22178:297 24X Fiche 50-327.84/02/06.8402100212.
- 8402140010 LER 84-007-00 on 840110, unit experienced turbine & reactor trip Turbine trip caused by high-high level in steam generator 3 Reactor trip attributed to operator error Reactor power reduced to prevent reactor trip W/840208 ltr KIRM, G. B. MABON, C. C. Tennessee Valley Authority 84/02/08 3pp 22217-173 24X Fiche 50-327,84/02/08,8402140010
- 8402140206 LER 84-006-00 on 840110 unit experienced turbine & reactor trip Turbine trip caused by high-high level in steam generator 4 Reactor trip caused by low-low level in steam generator 2 W/840208 ltr
 KIRK. 9 B , MABON. C C Tennessee Valley Authority 84/02/08 3pp 22229-359 24X Fiche 30-327.84/02/08.8402140206
- B402140331 LER 84-002-00 on 840112 actuation of high radiation alarm caused auxiliary bldg ventilation isolation Caused by voltage spike generating electromagnetic interference w/ high radiation causing trip W/840208 ltr DUGGIN.9.E. MASON.C.C Tennessee Valley Authority 84/02/08 3pp 22227-145 24X Fiche 50-327.84/02/08.8402140331
- 8402140191 LER 84-004-00, on 840114, high radiation alarm actuated, causing control room isolation Caused by electromagnetic interference generated by switch actuation High radiation alarm reset & monitor returned to svc W/840210 ltr DUGGIN, G E , MASON, C C Tennessee Valley Authority 84/02/10 3pp 22223-324 24X Fiche 50-327,84/02/10,8402140191
- B402220161 LER 84-003-00 on 840120 high radiation alarm actuated, causing containment ventilation isolation to occur Caused by electromagnetic interference High radiation alarm reset & monitor returned to svc.W/840217 ltr.
 DU001N.0 , MASON.C C Tennessee Valley Authority 84/02/17 3pp 22337 251 24X Fiche 50-327.84/02/17.8402220161.
- 8402280367 LER 84-008-00 on 840124, high radiation alarm actuated, causing auxiliary bldg isolation to occur Caused by pressure in vol control tank & overflowing of condensate demineralizer waste evaporator Bldg cleaned M/840222 ltr DUGOIN G . MABON, C C Tennessee Valley Authority 84/02/22 App 22403: 254 24X Fiche 50-327, 84/02/22, 8402280367
- B40R280451 LER 84-011-00 on 840125.design review revaaled that during seismic event, various piping which penetrates control room habitability pressurization boundary could fail Design change initiated W/840224 ltr COOPER, M.R. MABON, C.C. Tennessee Valley Authority 84/02/24 3pp 22407 030 24X Fiche. 50-327,84/02/24,8402280451

V Operator Examinations

B402010337 Notification of contract execution aluse of TVA Reactor Bimulator Facilities at Chattanoga, TN for Training on Browns Ferry. Sequeyah & Bellefonte Bimulators."
JESBUP, B. Technical Assistance Contracts Branch FIN B-8717.
B3/12/29. SHOWE, S K Director's Office, Office of Inspection and Enforcement ip 22059:227 24X Fiche 50-000. B3/12/29, 8402010337

---8402010346 Ltr contract NRC-05-84-153, "Use of TVA Reactor Simulator Facilities at Chattanoppa, TN for Training on Browns Ferry, Sequoyah & Bellefonte Simulators," awarded to TVA MORTON, K V Technical Assistance Contracts Branch FIN B-8717 83/12/29 JDHNSON, R J Tennessee Valley Authority 6pp 2205 230 24% Fiche 50-000.83/12/29,8402010337

DDCKET 50-328 SEQUDYAH NUCLEAR PLANT, UNIT 2

f Security, medical, emergency & fire protection plans

- 8402060382 Forwards Rev 7 to generic security personnel training & qualification plan Rev withheld (ref 10CFR73 21)
 MILLS.L M Tennessee Valley Authority 84/01/19 O'REILLY.J P
 Region 2. Office of Director 1p 22086 317 24X
 Fiche 50-000.84/01/19.8402060382
- 8402140384 Forwards summary of 840113 meeting in Region II ofc re emergency protective actions required by NUREG-0634 & clarified by IE Info Notice 83-28 VERRELLI.D M Division of Project & Resident Programs 84/01/26 PARRIS.H 9 Tennessee Valley Authority 4pp 22220 042 24X Fiche 50-000.84/01/26.8402140384
- 8402130316 Forwards Rev 8 to generic security personnel training & qualification plan Rev withheld MILLS,L M Tennessee Valley Authority 84/01/27 D'REILLY,J P Region 2, Office of Director ip 22197 149 24% Fiche 50-000,84/01/27,8402130316
- 8402130380 Forwards rev to 840101 security plan Rev withheld (1 of 10CFR73 21) MILLB.L M Tennessee Valley Authority 84/01/30 0'REILLY, J P Region 2, Office of Director ip 22202 139 24X Fiche 50-327.84/01/30.8402130380
- 8402140295 Forwards summary of 840119 meeting w/util in Region II ofc re improvement of security effectiveness & other securityrelated topics LEMIS,R C Division of Project & Resident Programs 84/02/01 PARRIS,H G Tennessee Valley Authority 4pp 22228 271 24X Fiche 50-000,84/02/01,8402140295
- 8402210278 Revs to Muscle Shoals emergency control ctr implementing procedures: including Procedure MSEC IP-1 re notification of unusual event, alort or transportation accident & MSEC IP-2 re site emergency or emergency director W/840210 Itr MILLS.L M Tennessee Valley Authority 84/02/02 76pp 22315 00 24X Fiche 50-000.84/02/02.8402210278
- B40222042B Forwards revised pages to B31103 rev to physical security plan Pages withhold (ref 10CFR73 21)
 MILLS,L M Tennessee Valley Authority 84/02/10 0'REILLY, J P
 Region 2. Office of Director 1p 22340 162 24X
 Fiche 50-327.84/02/10,840222042B
- B402170190 Ack receipt of 831230 ltr transmitting rev to physical security plan Compensatory actions should continue to be implemented until util notified by NRR of position re rev. Encl withheld (ref 10CFR73 21)
 LEWIG.R C Division of Project & Resident Programs 84/02/13
 PARIS.H G Tennessee Valley Authority 2pp 22299 041 24X
 Fiche 50-327.84/02/13,8402170190
- 840221014B Notifies that RCS vent procedure will not be implemented until complete set of emergency operating instructions implemented per Generic Ltr 82-33.Buppl i to NUREG-0737 & TMT Item II B 1
 MILLS.L M Tennessee Valley Authority 84/02/15 ADENBAM.E Licensing Branch 4 1p 22316 357 24X Fiche 50-327.84/02/15, 84022/0148
- B402230096 Rev B to Radiological Emergency Plan Implementing Procedure IP-6. "Activation of Technical Support Ctr" & Rev 7 to Procedure IP-17. "Emergency Equipment & Supplies " W/B30217 ltr CRAMLEY, D , CAULT, G W , MILLS, L M Tennessee Velley Authority B4/02/15 0'REILLY, J P Region 2. Defice of Director 26pp 22329 046 24% Fiche 50-327. B4/02/19. B402220096
- B4022B0519 Grants B40131 request for extension to respond to deficiency Item OB until B40330 Concurs w/decision based on need to revise emergency monitoring procedures for Browns Ferry & Watts Bar as well as Sequeyah VERRELLI.D M Division of Project & Resident Programs B4/02/17 PARRIS.H @ Tennessee Valley Authority ip. 22406 336 24X Fiche 50-327,84/02/17.84022B0519

102280528 Advises that emergency monitoring implementing procedures revised for other TVA plants to maintain consistency, per commitment in response to IE Inap Repts 90-327/83-13 & 50-328/83-13 on percent by 840320 MILLS.L M Tennessee Valley Authority 84/01/31 D'REILLY, J.P. Region 2. Defice of Director 1p 22406 337 24x Fiche 50-327.84/02/17.8402280519

Insurance & indemnity information

2160321 Forwards Endorsements 38 & 39 to NELIA Policy NF-247, ndorsement 32 to MAELU Policy NF-102 & Endorsement 33 to AELU Policy NF-77 Amended site description also encl UCK, J R Tennessee Valley Authority 84/02/06 SALTZMAN, J saistant Director for State & Licensee Relations App 2227 4X Filhs 50-327, 84/02/06, 8402160321

Advisory Committee on Reactor Safeguards reports & correspondence

2270263 Responds to FDIA request for JC Hark 801204 memo to ACR8 re ydrogen burn w/igniters & documents concerning generation, ambustion or control of hydrogen in reactor accidents orwards App A documents App B documents in PDR ELTON, J M Division of Rules and Records 84/01/30 HIATT, S L hio Citizens for Responsible Energy 7pp 22412 051 24X iche 50-000,84/01/30,8402270263

402270289 Discusses ACRS review of TVA request for authorization to operate at full power Reasonable assurance should be given that ice condenser containment would held in event of serious accident GILINBKY,V Commissioners BO/07/10 PLESBET.MS ACRS -Advisory Committee on Reactor Safeguards 1p 22412 067 Fishe 50-000,84/01/30,8402270263

402270297 forwards draft NRR rept on hydrogen control measures
Proposed ignition sys would effectively prevent
overpressurization from hydrogen burn, based on MARCH &
CLASIX computer calculations
BESSETTE, D ACRS — Advisory Committee on Reactor Bafeguards
80/08/18 ACRS — Advisory Committee on Reactor Bafeguards ip
22412 072 24X Fiche 50-000,84/01/30.8402270263

402270305 Discusses proposed ACRS Subcommittee on Class 7 Accidents 800828 meeting in Washington, DC to consider hydrogen generation t control during degraded core accidents BESSETTE. D ACRS - Advisory Committee on Reactor Safeguards 80/09/03 ACRS - Advisory Committee on Reactor Safeguards 3pp 22412 074 24% Fiche 50-000.84/01/30.8409270263

402270351 Comments on NUREG/CR-1762. "Analysis of Hydrogen Mitigation for Degraded Core Accidents in Sequoyah Nuclear Power Plant "Strong recommendation that iquitors at top of ice condensers be removed debatable MARK, J.C. ACRS - Advisory Committee on Reactor Safeguards BI/02/02 ACRS - Advisory Committee on Reactor Safeguards Spp 27412 156 24X fiche 50-000,84/01/30,8402270263

402270374 "Comments Re Ignibers in Upper Plenum of Ice Condenser of Sequoyah & McGuire Nuclar Power Plants," prepared for ACRS Subcommittee on Class 7 Accidents SICHELM Michigan Univ of, Ann Arbor, MI 81/08/17 20pp 22412 184 24X Fiche 50-000,84/01/30.8402270263

Operating license stage documents & correspondence

2070525 Advises util of NRC actions re-util 821227 request for edvoice novices util of the actions results exize/ request uthorization to operate vol reduction sus to process low evel radwaste & 83:221 request for relief from hydrostatic est requirements of ASME Code. Section XI Addi fee required ILLER. W O License Fee Management Branch 84/01/31 PARF ennessee Valley Authority 2pp 22:141-331 24X iche 50-327.84/01/31.0402070525 PARRIE.H @

2010410 Generic Ltr 84-04 to all operating PMR licensees, CP holders applicants for CPs re safety evaluation of Mestinghouse opical repts dealing w/elimination of postulated pipe reaks in PMR primary main loops Svc list encl ISEN-UT.D 6 Division of Licensing 84/02/01 Consulidated itson Co of New York. Inc. 59pp 22177 087 24X (che 50-000.84/02/01.8402010410

2070206 Advises that date of 840321 acceptable for meeting w/NRC to iscuss program plan for detailed control room design eviews Concurrence on meeting date requested (LLS:L M Tennessee Valley Authority 84/02/01 ADENSAM, Eleansing Branch 4. ip 22102 212 24X Fichs 50-000, 84/02/01, 107070702 102070206

8401190017 IE Bulletin 84-01. "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEYGLUNG.R C Director's Office. Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York. Inc 102pp 22177 156 24X Fiche 50-000.84/02/03.8401190017

B402130279 Forwards Rev B to offsite dose calculation manual MILLS.L N Tennessee Valley Authority 84/02/07 ABENSAM.E Licensing Branch 4 3pp 22198 256 24X Fiche 50-327.84/02/07.8402130279

---8402130282 Rev 8 to offsite dose calculation manual * Tennessee Valley Authority 84/02/07 19pp 22198 259 24X Fiche 50-327,64/02/07,8402130279

8402130647 Requests fee for 831024 application proposing Tech Spec changes re snubbers be remitted within 15 days of receipt Of itr MILLER, W.O. License Fee Management Branch. 84/02/08 PARRIS, H.G. Tennessee Valley Authority 1p. 22214 291 24X Fiche 50-327, 84/02/08, 8402130649

B402210110 Submits implementation data for requirements of Reg Guide 1 97.per Generic Ltr 82-33 Requirements will be complied by and of Unit 2.0gite 4 outage scheduled for 870902 MILLSL X Tennesses Valley Authority. B4/02/14 ADENBAM.E Licensing Branch 4 1p. 22316 362 24X Piche 50-327,84/02/14, 8402210110

8402280185 Forwards thanges to BASES to support 830721 requested Tech Spec changes for operational limits associated w/pressurizer spray notale. Changes inadvertently omitted in 830721 ltr. MILLS,L M Tennessee Valley Authority 84/02/22 ADENBAM,E A Licensing Branch 4 1p 22403 233 24X Fiche 50-327.84/02/22, 8402280185

--B40228034i Proposed Tech Spec changes to BASES re operational limits associated w/pressurizer spray nozzle
* Tennessee Valley Authority 84/02/22 2pp 22403 234 24X Fiche 50-327,84/02/22,8402280185

8402280368 Discusses mads to License Conditions 2 c(23) f & 2 c(16) g for Units 1 & 2.respectively.as requested in 831123 & 1221 ltrs Completion of planned mads will satisfy requirements of OL conditions
OL conditions
MILLB:LB Tennessee Valley Authority 84/02/22 ADENBAM.E
Licensing Branch 4 2pp 22402 359 24X Fiche.50-327,84/02/22

O Inspection reports, IE Bulletine & correspondence

B312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list enc1

JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25. Consolidated Edison Co. of Naw York, Inc. 120pp 22058 001. 24X Fiche 50-000,84/01/25,8312120153

8402140246 Ack receipt of 840118 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/83-25 & 50-328/83-25. VERRELLI, D M Division of Project & Resident Programs 84/01/27. PARRIB, H G Tennessee Valley Authority 1p 22228 317 24X Fichs 50-327,84/01/27,8402140246

--B402140250 Responds to NRC B31217 ltr re violations noted in IE Insp Repts 50-327/83-25 & 50-328/83-25 Corrective actions Procedure T1-20 re chamical equipment & methods revised to delete sections covered by Procedure T1-11 MILLB.L M Tennessee Valley Authority. B4/01/18 O'REILLY, J.P. Region 2, OPFice of Director 2pp. 22228 318 24X Fiche 50-327, 84/01/27, 8402140246

-8402140251 Forwards IE Insp Repts 50-327/83-25 & 50-328/83-25 on B3ii14-18 & notice of Violation VERRELLI,D M Division of Project & Resident Programs 83/12/ PARRISH O Tenmessee Valley Authority. 2pp 22228:321, 24X Fiche 50-327,84/01/27,8402140246 83/12/19.

--8402140255 Notice of violation from insp on 831114-18
Region 2: Office of Director. 83/12/19 ip 2:
Fiche 50-327,84/01/27,8402140246 22226: 323 243

--B402140259 IE Insp Repts 50-327/83-25 & 50-328/83-25 on B31114-18.
Violation noted:failure to follow procedures for calibr checks of Chemistry Lab instrumentation
KUZO.9 B. Region 2: Office of Director MONTODMERY, D M. Division
of Engineering & Operational Programs B3/12/14 12pp
22228 324 24X Fiche 50-327,84/01/27,8402140246

- B402150271 Responds to IE Bulletin B3-03, Item 5 re check valve failures in raw water cooling sys of diesel generators Check valves on ERCW suppy side of diesel generators acceptable Three valves on discharge side needed mod MILLS.L M Tennessee Valley Authority 84/02/02 D'REILLY.J P Region R. Office of Director 2pp 22250 0B2 24X Fiche 50-327,84/02/02.8402150291
- 8401190016 IE Info Notice 84-07. "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Ca of New York, Inc 119pp 22114 179 24X Fiche 50-000,84/02/03,8401190016
- 8401170041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R)" Syc list enci.

 JURDAN, E i. Division of Emergency Preparedness & Engineering Rasponse (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259 24X Fiche 50-000.84/02/13.8401170041
- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '"

 8vc list encl

 JORDAN, EL Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- 8401190045 IE Info Notice 83-63. Suppl 1, "Potential Failures of Westinghouse Type BA-1 Differential Relays " Svc list encl JORDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York. Inc. 118pp 22366 142 24X Fiche 50-000.84/02/15,8401190045
- B402280519 Grants 840131 request for extension to respond to deficiency Itum OB until 840330 Concurs w/decision based on need to revise emergency monitoring procedures for Browns Ferry & Watts Bar as well as Bequoyah VERRELLI.D M. Division of Project & Resident Programs 84/02/17 PARRIS, H O Tennessee Valley Authority 1p 22406 336 24X Fiche 50-327,84/02/17,8402280519
- --B4022B0B2B Advises that emergency monitoring implementing procedures revised for other TVA plants to maintain consistency, per commitment in response to IE Insp Repts 50-0227/83-13 & 50-0229/83-13, Completion expected by 840030 MILLB, L M Tennessee Valley Authority 84/01/31 D'REILLY, J P Region 2, Office of Director ip 22406 337 24X Fiche. 50-327, 84/02/17, 8402280519
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/21. Consolidated Edison Co. of New York, Inc. 116pp 22366:024 24X Fiche 50-000,84/02/21,8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies" Byc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/24 Consolidated Edison Co of New York, Inc 115pp 22430 304 24X Fiche 30-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals"

 8vc list encl
 JCRDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27, Consolidated Edison Co. of New
 York, Inc 120pp 22431 060 24X Fiche 50-000,84/02/27,8401190067
- B Reportable occurrences, LERs & related correspondence
- B4020R0033 Partial response to FDIA request for documents re evaluation or review of design, const, scheduling, cost & licensing of facilities from 1977 to present Forwards App A & B documents

 FELTON. J M Division of Rules and Records, 83/11/04, ZACK, A M Barris, Bott, Denn & Driker. 11pp 22079 208 24%

 Ficher 50-000, 83/11/04, 8402020033.
- --8402020092 Submits 820112 daily staff notes re PNO-II-82-006 & PNO-II-82-007 & review of changes to GA organization at plant site & methers re ongoing soil settlement hearing Related info and DIRCKS.M.J. Office of the Executive Director for Operations. 82/01/13 PALLADINO.N Commissioners 23pp 22081 118 243 Fiche: 50-000,83/11/04,8402020033
- 8402220154 Responds to FOIA request that 144 LERs be placed in PDR Forwards LERs listed on app Documents also available in PDR Remaining LERs were either canceled or not issued FELTON, J. M. Division of Rules and Records, 83/11/30, JEFFERSON, G. A. Affiliation Not Assigned 2pp 22380 052, 24X Fiche: 50-000, 83/11/30, 8402220154.

- 8402030389 LER 83-191/03L-0 on 831227.rod C-11 declared inoperable due to Brratic behavior Caused by Faulty connection at reactor vessel head Low current 500-volt charge placed on cable Rod returned to svc M/840123 ltr ROGERS.H R . HARDING.M R . COFFEY.T A Tennessee Valley Authority 84/01/23 2pp 22066 031 24% Fiche 50-328.84/01/23.8402030389
- B402140391 LER B4-001-00 on B40105 containment ventilation isolation occurred when high radiation alarm actuated Gaused by voltage spike Isolation reset & flow switches mounted on shock absorbing rubber mounts W/B4020B ltr
 DUG01N, G E . MASON, C C Tennessee Valley Authority B4/02/08 4pp 22220 327 24X Fiche 50-328, B4/02/08, B402140391
- 8402280441 LER 84-002-00 on 840127, high radiation alarm actuated, causing containment ventilation isolation to occur Caused by inadvertent voltage spike Alarm reset & monitor returned to svc W/840224 ltr
 DUGGIN, G . MASON, C C Tennessee Valley Authority 84/02/24 App 22407 179 24X Fiche 50-328,84/02/24,8402280441

V Operator Examinations

- 8402010337 Notification of contract execution "Use of TVA Reactor Bimulator Facilities at Chattanoga. TN for Training on Browns Ferry, Sequoyah & Bellefonte Simulators" JEBBUP, B Technical Assistance Contracts Branch FIN B-8717 83/12/29 SHOWL, S K Director's Office, Office of Inspection and Enforcement 1p 22059 227 24X Fiche 50-000.83/12/29.8402010337
- --8402010346 Ltr Contract NRC-05-84-153, "Use of TVA Reactor Simulator Facilities at Chattanooga. TN for Training on Browns Ferry, Sequoyah & Bellefonte Simulators." awarded to TVA MORTON, K V Technical Assistance Contracts Branch FIN 8-8717 83/12/29 JOHNSON, R J Tennessee Valley Authority App 22059 230 24X Fiche 50-000.83/12/29,8402010337

DOCKET 50-329 MIDLAND PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8402020029 FOIA request for documents re evaluation or review of design const scheduling, cost & licensing of facilities from 1977 to present ZACK, A M Barris, Sott, Denn & Driker 83/09/29 FELTON, J M Division of Rules and Records 1p 22079 207 24X Fiche 50-329, 83/09/29, 8402020029
- B402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A,B & C documents
 FELTON, J M Division of Rules and Records, 83/10/31
 ROBENBAUM, D M Technical Analysis Corp 19pp 22193 292 24X
 Fiche 50-000,83/10/31,8402090003
- --8402070086 Comments on 770618 meeting re estimated fuel load date Util requested site visit & evaluation of const schedule & fuel load date as soon as possible Related info encl ** NRC No Detailed Affiliation Given 79/06/18 NRC No Detailed Affiliation Given 79/06/18 NRC No Detailed Affiliation Given Spp 22175 144 24X Fiche: 50-000, 83/10/31, 8402070003
- --8402070101 Summarizes 800613 meeting w/util re NRC review of OL application Related info encl.

 BRUNNER.J E Isham. Lincoln & Beale BRUNNER.J E Consumers Power Co 80/06/13 Isham. Lincoln & Beale 9pp 22195 154 24X Fiche 50-000.83/10/31.8402090003
- --B40209011B Handwritten charts, notes & calculations re const activities & estimated const completion Related info encl * NRC No Detailed Affiliation Given B0/08/04 5Opp 22195, 168 24X Fiche 50-000, 83/10/31, 8402090003
- --8402070122 Handwritten calculations re const activities Related info encl. * NRC - No Detailed Affiliation Given 61/08/26 80pp 22175 232 24X Fiche 50-000,83/10/31,8402090003
- --8402090135 Handwritten notes & calculations re const activities & fuel load preparation Related info encl. * NRC - No Detailed Affiliation Given. 83/04/19 27pp 22195 316 24X Fiche 50-000.83/10/31.8402090003
- --8402090142 Draft trip rapt of 780321-22 site visits ra const schedules & in-progress const activities observation. Fuel load dates for Units 1 & 2 are Nov 1981 & Nov 1980, raspectively Related info anci

 * NRC No Detailed Affiliation Given 83/10/31 NRC No Detailed Affiliation Given 83/10/31 NRC No Detailed Affiliation Fiven 11pp 22195 342 24% Fiche 50-000,83/10/31.840R090003

- --8402090192 Handwritten notes & calculations re const activities & Fuel inad date projection Related info encl
 8 NRC No Detailed Affiliation Olven 78/09/26 Spp 22195 083 24X Fiche 50-000,83/10/31.8402090003
- --8402090199 "Midland Startup Sequence " Related info encl # Consumers Power Co 83/10/31 23pp 22195 ii3 24) Fiche 90-000,83/10/31,8402090003
- 8402020033 Partial response to FOIA request for documents re evaluation or review of design.comst.schedulang.cost & licensing of facilities from 1977 to present Forwards App A & B documents
 FELTON.J M Division of Rules and Records 83/11/04 ZACK,A M Barris, Sott. Denn & Driker 11pp 22079 208 24X
 Ficho 50-000.83/11/04.8402020033
- --810B110074 Informs of tentatively scheduled B10825 visit by Caseload Forecast Panel to facility Reconfirmation of fuel load ostimats needed to develop NRC resource allocations, priority decisions & support findings necessary for CP extension TEDESCG.R L. Assistant Director for Licensing 81/08/03 EISCN!UT.D & Division of Licensing 1p 22081 020 24X Fiche 80-000,83/11/04,8402020033
- --8112220708 Summary of B11112 meeting w/util in Bethesda.MD re const schedules for foundation mods to auxiliary bldg Attended list & viewgraphs encl HODD.D Licensing Branch 4 81/11/23 Licensing Branch 4 8pp 22081 110 24x Fiche 50-000.83/11/04.8402020033
- --840202003B "Project Cost & Schedule, Forecast 4 "
 * Dechtel Corp 77/12/31 135pp 22079 R19 24X
 Fiche 50-000,89/11/04,8402020033
- ---04020200097 Agonda for 790618 meeting w/NRC to discuss facility const & licensing Related info encl + Consumers Power Co 79/06/18 Consumers Power Co 79p 22080 069 24X Fiche 50-000, 83/11/04, 8402020033
- --8402020068 Agenda for 790718-20 Caseload Forecast Panel site visit Related info encl * Consumers Power Co 79/09/14 Consumers Power Co 57pp 22080 122 24X Fiche 50-000,83/11/04.8402020033
- --0402020070 Agenda for 800727 Caseload Forecast Panel site visit Related info encl * Consumers Power Co 80/07/25 Consumers Power Co 145p 22080 180 247 Fiche 50-000,83/11/04.8402020033
- --8402020073 Forwards Project Schedule Change Notice 2 which finalizes Rev 11 dates under further study Related info encl RUTGERS.U A Bechtel Corp 81/07/15 CODM.U W Consumers Power Co 37pp 22080 345 248 Fiche 50-000:83/11/64:8402020033
- --84020200077 Agenda for 810825 meeting w/NRC Caseload Forecast Panel to conduct plant tour Related info encl * Consumers Power Co B1/08/24 Consumers Power Co 84pp 22081 026 24X Fiche 50-000,83/11/04.8402020033
- --8402020142 Handwritten notes w/attached calendar page re Midland hanger reinsp & pige whip restraints * NRC - No Detailed Affiliation Given 83/04/19 5pp 22081 184 24X Fiche 50-000,83/11/04/8402020033
- --BA02020145 Agenda For B30417-21 meetings w/MRC Caseload Forecast Panel * NRC - No Detailed Affiliation Given B3/04/19 NRC - No Detailed Affiliation Given 210pp 22081:189 24X Fiche 80-000, B3/11/04, 8402020033
- --8402020149 Computer printout entitled "Planning Schedule Rev 12 "
 Draft itrs encl
 * NRC No Detailed Affiliation Given 83/04/20 35pp
 22082 036 24X Fichs 50-000.83/11/04.8402020033
- --8402020159 Forwards Dow Chemical Co notice of termination & complaint for declaratory judgment due to util inability to meet commercial steam operation date Damages against util being sought
 FALAHEE, J B Consumers Power Co 83/07/15 KEPPLER, J Q Region 3, Office of Director 21pp 22082 098 24X
 Fithe 50-000.83/11/04.8402020033
- -- G402020213 Discusses 830702 telton re util request for followup meeting on Pacility const completion dates Util requested delayed meeting until essential related matters resolved Related into encl HODD, D. Licensing Branch 4 83/09/08 ADENBAN, E. G. Licensing Branch 4 46pp 22082 136 24X Fiche 50-000, 63/11/04, 8402020033.

- 8402060286 Further response to FOIA request for IE 800103 rept re review of mat) false statement at facility & all associated & supporting records to rept Forwards documents listed in App C App B documents available in PDR FELTON.J M Division of Rules and Records 83/11/15 WINSLOW, R Wall Street Journal 3pp 22111 068 24X Fiche 50-327.83/11/15, 8402060286
- --7904100117 Board notification Midland settlement problem Concurs w/ decision to inform QL Board of settlement of dissl generator bldg CP Board or Commission notification unnecessary VASSALLO, D B Assistant Director for Light Water Reactors 78/11/13 ENGELHARDT.TF Hearings Division 1p 22111 073 24X Fiche 50-327,83/11/15,002060286
- --7904100122 Board notification diesel generator foundations & bldg
 settlement at Midland Recommends that ltr of notification be
 prepared which would apprise appropriate Boards & Commission
 of sob; matter
 CLMSTEAD: W J Hearing Branch 4 78/11/03 VABSALLO.D B
 Assistant Director for Light Water Reactors 1p 22111 072 24X
 Fiche 50-329.83/11/15.8402060286
- --7910230546 Requests assistance to ensure that engineering branch positions re facilities soil settlement issues are documented & forwarded to applicant as soon as possible RUBENSTEIN, L. S. Light Water Reactors Branch 4 79/09/27 KNIGHT, J. P. Assistant Director for Engineering 2pp 22111 109 24% Fithe 50-327, 83/11/15.8402060286
- 840207002B FOIA request for records generated in connection w/TA Rehm 831117 ltr to BP Garde re Midland Caseload Forecast Panel GARDE. 5 P Government Accountability Project 83/11/26. Office of Administration 2pp P2142 248 24X Fiche. 50-329, 83/11/26, 8402070028
- 8402270491 FOIA request for documents re 831025 meeting between util & NRC concerning mgt audit & associated 10CFR2 206 request GARDE. B P Government Accountability Project 83/11/26 Office of Administration 2pp 22414 250 24% Fiche 50-327, 83/11/26, 8402270491
- B402100005 Partial response to FOIA request for documents prepared by OPc of Investigation re Zack Co Forwards App A documents.

 Documents also being placed in PDR Info partially withheld (ref FOIA Exemption 6)

 FELTON, J M Division of Rules and Records B3/11/28 PERRY, R A Affiliation Not Assigned. 7pp 22206 002 24X

 Fiche 50-000.83/11/28.8402100005
- B40E07003B Responds to FOIA request for records generated in connection w/TA Rehm B31117 ltr to BP Gards re Midland Caseload Forecast Fancel Forwards App, A document Eight dreft documents listed in App B withheld (ref FOIA Exemption 5) FELTON.J M Division of Ruise and Records B3/12/28 QARDE, B P Government Accountability Project Spp 22142 250 24X Fichs. 50-329, 83/12/28, 840207003B
- B312120136 Board Notification B4-011.discusses NRC use of terms
 "important to safety" & "safety-related"
 EISENHUT.D 0. Division of Licensing B4/01/18 FALLADING
 Commissioners 72pp 22241 008 24X Fiche 50-000,84/01/18,
 B312120136
- 8402030431 Forwards S&W 840118 ltr notifying that personnel listed on 840105.09.11.12.13 lists cleared to perform status assessment OLAMPE, D.L. Consumers Power Co. 84/01/20 HIERZED, O.A. Barbtal
- GUAME, D. L. Consumers Power Co. 84/01/20 HIERZER, G. A. Bechte Corp. 2pp. 22066-016. 24X Fiche 30-329,84/01/20,8402030481
- B402020118 Forwards electrical FCR/field change notice register.W/o encl REICHKL.N I Consumers Power Co 84/01/23 Btone & Webster, Inc. 1p 22056 224 24% Fiche 50-329,84/01/23,8402020118
- 8402020297 Informs that JE Kerr assigned site program manager for 8&W const implementation overview program effective 840112 AMORUSO, 4P. Stone & Webster, Inc. 84/01/23 QUAME, D.C. Consumers Power Co. 1p 22055 183 24X Fiche 50-329, 84/01/23, 84/02/297
- 8402030241 Submits response to S&W concern re high number of ravs & time taken to process ravs Proposed procedural rav raquest must be approved by initiator, supervisor, dept head & Field const manager
 HIERZER. 6. A Bechtel Corp 84/01/23 QUAMME, D Consumers Power Co 2pp 22067 205 24X Fiche 50-329, 84/01/23, 8402030241.

- B402060365 Forwards summary of remedial Soils % const completion program third-party assessment 840112 meeting LUCKS, A S . AMORUSO, A P Stone & Webster, Inc 84/03/23 HARRISON, J J Region 3. Office of Director 20pp 22086 128 24-Fiche 50-329,84/01/23.8402060365
- 8401170D12 Board Notification 84-013 forwards info re Transamerica Delaval, Inc emergency diseas generators EIBENHUE, D © Division of Licensing 84/01/24 PALLABIND, N Commissioners 10pp 22094 346 24X Fichs 90-000,84/01/24,
- 8402020276 Informs that as result of 840124 partial release of Stop Mork Order FSW-41 for instrumentation & control documents. Bechtel released for status assessment in Modules 340,102. 120,410 & 800 Documentation encl GUAMME, D. L. Consumers Power Co. 84/01/24 HIERZER, G. A. Bechtel Corp. 17pp. 22055 189 24X Fiche 50-329.84/01/24,8402020276
- 840203019; Forwards signed affidavits & resumes for KJ Butler & GA Carter & resume for WO Dick Personnel assigned to const implementation overview staff at facilities MARR.JE Stone & Webster. Inc 84/01/24 HARRISON.JJ NRC - No Detailed Affiliation Given 16pp 22068 008 24X Fiche 50-329.84/01/24.8402030191
- B402030282 Forwards B40126 update of pre~ & post-stop work order activities
 REICHEL,N I Consumers Power Co B4/01/24 Stone & Webstor, Inc 3pp 22071 070 24X Fiche 50-327:84/01/24.8402030282
- B402030271 Advises that sampling review of Phase I & II of field change requests/notices affecting instrumentation & control & civil documents completed MARR.J E Stone & Webster, Inc 84/01/24 QUAMME,D L Consumers Power Co ip 22069 358 24X Fiche 50-329,84/01/24,8402030271
- B402030276 Requests controlled distribution of index to Bechtel field procedures & instructions be sent to JJ Ridge KARR. J E Btone & Webster. Inc. 84/01/25 REICHEL, N Consumers Power Co ip 22049 359 24% Fiche 50-329,84/01/25,8402030296
- 8402030213 Forwards list of Bechtel personnel trained to commence status assessment
 REICHEL, N I Comsumers Power Co 84/01/26 Stone & Webster, Inc 2pp. 22067 328 24% Fiche 50-329,84/01/26,8402030213
- B402030236 Forwards BMO CCP assignments.per W Sienkiewic: request REICHEL, N I Consumers Power Co 84/01/26 Stone & Webster, Inc 2pp 22067 176 24X Fiche 50-329:84/01/26,8402030236
- 8402030335 Discusses release for status assessment in const implementation overview Hold Point Oil for electrical & MPBAD partial release of SMO 41 for electrical disciplines for Modules 340, 102, 120, 410 & 800 QUAMME, D L. Consumers fower to 84/01/26 HIERZER, G A Bechtel Corp 8pp 22047 132 24X Fiche 50-327,84/01/26,8402030335
- B402060244 Forwards open Const Implementation Overview Item/Hold Point Notifications 047 & 049 for action KARR.J E Btone & Webster, Inc B4/01/26 QUAMME, D L Consumers Power Co 3pp 22087 203 24X Fiche 50-329, 84/01/26, 8402060244
- 8402040427 Requests that const implementation overview be placed on controlled distribution for index to Bechtel field procedures & instructions Distribution should be made to JJ Ridgs.

 QUAHMED L Consumers Power Co 84/01/26 HIERZER, G A Dechtel Corp ip 22085 160 24X Fiche 30-327.84/01/26,8402060427
- 8401190015 Board Notification 84-018 provides info re failure experience of Transamerica Delaval emergency diesel generators in marine svc EIBENHUT, D @ Division of Licensing 84/01/27 PALLADINO, N J . 01LINSKY, V. ROBERTS, T M Commissioners 385pp 22093 027 24X Fiche, 50-000, 84/01/27, 8401190015
- B402060038 Informs that const implementation overview activities dependent upon receipt of registers from document control, approval of time required for preparation of sample plans & assignment of personnel.in response to 840120 ltr
 KARR.J E Bone & Webster. Inc. 84/01/27 GUAMME.D.L Consumers Power Co ip 22088 201 24X Fiche 50-329.84/01/27.8402060058
- 8402060230 Forwards resume & affidavit for AJ Benecchi assigned to const implementation overview team KARR, JE. Stone & Webster: Inc. 84/01/27 HARRIBON, J J Region 3. Office of Director 7pp 22083 033 24X Fiche 50-327,84/01/27,8402060230

- B40206036B Forwards project schedule hierarchy per G Dick request W/u cricl * Consumers Power Co 84/01/27 Stone & Webster, Inc 1p 22086 264 24% Fiche 50-329.84/01/27.8402060368
- 8402060377 Forwards partial response to Observation 037, Rept 24 refailure to remove leftover scaffolding boards from work area

 * Consumers Power Co. 84/01/27 Stone & Webster, Inc. 5pp.
 22086-308-24X Fiche 50-329,84/01/27,8402060377
- 8402030326 Authorizes listed remedial soils work activities for Feb 1984 Work activity list encl HARRISON.J J Region 3. Defice of Director 84/03/30 QUAMME.D L Consumers Power Co 3pp 22069 072 24X Fiche 50-389,84/01/30. 84
- --8402030331 Requests authorization to proceed w/listed remedial soils work QUAMME, D.L. Consumers Power Co. 84/01/26 HARRISON, J.J. Region 3, Office of Director 1p. 22069-075 24X Fiche 50-329,84/01/30 8002030326
- B4020&0464 Forwards open Const Implementation Overview Item 050 re Q t non-0 interfaces KARR, J E Btome t Webster, Inc. B4/01/30 QUAMME.D L Consumers Pawer Co 4pp 22083 100 24X Fiche 50-329, B4/01/30, 84020&0461
- B4020B0390 Responds to request for partial release of seven mechanical documents to allow pneumatic test Const implementation overvious review attributes listed RARR, J E Stone & Webster, Inc. 84/01/30 GUAMME.D L Consumers Power Co. 1p. 22130-359 24X Fiche 50-329,84/01/30,8402080390
- B402130471 Forwards B40126 list of Bechtel personnel trained to commence status assessment JOHNSON D Consumers Power Co B4/01/30 Stone & Webster, Inc 2pp 22202 048 24X Fiche 50-727,84/01/30.8404130471
- 8402080241 Forwards review of QC div personnel New Quality Action Request RT-00025 initiated for review of Soils Div & MVAC Assurance Branch insp personnel qualification & cortification records W/o enr! QUANNC, D L. Consumers Power Co. 84/01/31 KARR, J E. Stone & Webster, Inc. 1p. 22134 240 24X Fiche 50-329,84/01/31,8402080241
- B4020B03B7 Forwards response to tracked recommendation Item 047 re monthly review of work print sys REICHEL.N I Consumers Power Co 84/01/31 Stone & Webster, Inc 4pp 22130 230 24X Fiche 50-327,84/01/31.84020B03B7
- B402150140 Forwards const review of S&H CCP overview Item 047 re field work prints HIERZER.G A Bechtel Corp B4/01/31 QUANME.D L Consumers Power Co 4pp 22249 287 24% Fiche 50-329.84/01/31.8402150140
- 8402280431 Forwards remedial soils work activity list for Feb 1984 / supplemental work activity list for Mar 1984.per ASLB 820430 order Authorization to proceed work requested QUAMME, D.L. Consumers Power Co. 84/01/31 HARRISON, J.J. Region J. Office of Director 12pp 22405 274 249 Fiche 50-329.84/01/31, 8402280431
- 8402130459 Forwards response to tracked info Item 050 re Grinterface policy statement * Consumers Power Co 84/02/01 Stone & Webster, Inc 5pp 22202 053 24X Fichs 50-329,84/02/01,8402130459
- 8401170018 Board Notification 84-017 provides info re proceedings on lifting soils remedial stop work order, potential 10CRR50 55(e) involving differential settlement of diesel pedestals & diesel bldg & crack monitoring NDVAK, T M Assistant Director for Licensing 84/02/02 BECHIOEFER.C , HARBOURJ , CONAN, F Atomic Bafety and Licensing Board Panel 2pp 22178 248 24X Fiche 50-327,84/02/02,8401190019
- --B402100232 Provides recommendation for notification of ASLB re new info relevant & matl to facility proceedings WARNICK, R F. Region 3, Office of Director 84/01/25 EIBENHUT, D @ Division of Licensing 3pp 22170 250 24X Fich# 50-329,84/02/02,8401190018
- 8402130420 Forwards Const Implementation Overview Hold Point 015 re use of thermocauples & thermocauple extension wire MARR, J. E. Stone & Webster, Inc. 84/02/02 GUAMME, D. L. Consumers Power Co. Jpp. 22201 272 B4X Fiche: 50-329,84/02/02,8402130420
- 8402130475 Forwards 840131 list of Bechtel personnel trained to commence status assessment * Consumer Power Co 84/02/02 Stone & Webster Engineering Corp 2pp 22201 172 24% Fiche 50-327.84/02/02,8402130475

- 8402:30425 Forwards const implementation overview item/hold point notifications Item 051 re field procedures/receipt insp & Item 052 re Criterion XVIII site auditing KARR.J E Stone & Webster. Inc. 84/02/03 QUAMME.D L Consumers Power Co. 3pp 2220: 297 24X Fiche 50-329.84/02/03.8402:30425
- B402150276 Forwards, for info.list of Bechtel personnel trained to conduct status assessment * Consumers Power Ca B4/02/03 Stone & Webster, Inc 2pp 22249 360 287 Fiche 50-329.84/02/03.6402150276
- 8402090255 Responds to NRC B40112 confirmatory order re util commitment at B31025 meeting to provide independent appraisal of Midland project Proposal for independent appraisal util be submitted by 840307 CDDK.J W Consumers Power Co 84/02/06 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement App 22161 338 24% Fiche 50-329.84/02/06.8402070225
- 8402100188 Requests list of critical remodial soils work activities scheduled for Feb & Mar 1984 HARRISON.J J Region 3. Office of Director 84/02/06 GUAMME, D L Consumers Power Co 3pp 22182 071 24X Fiche 50-329,84/02/06. 3402100188
- B402130466 Notifies that sampling insps of const training records performed Results satisfactory Personnel cleared to perform status assussment KARR, J E Stone & Webster, Inc B4/02/06 QUAMME, D L Consumer: Power Co 1p 22202 037 24% Fishe 50-329, 84/02/06, 8402130466
- 8402130224 Advises that no response received on Transmittals GSC-7201. dtd 840120 & CSC-7275. dtd 840202 Status of personnel lists requested * Consumers Power Co 84/02/06 Stone & Webster, Inc ip 22244 152 24X Fiche 50-329,84/02/06.8402150224
- B40215024B Informs that results of const implementation overview sampling insps of personnel const training records satisfactory Personnel listed in encl cleared to perform status assessment W/o encl KARR.J E Stone & Webster, Inc. 84/02/07 (BLAMME.D L. Consumers Power Co. ip. 22250 260 24X Fithe 50~329,84/02/07,8402150248
- 8402190337 Forwards mechanical field change request/field change notice (FCR/FCN) registers & FCR/FCNs w/applicable resolution sheets H/G encl
 - sheets H/o encl
 REICHCL:N I Consumers Power Co 84/02/07 Btone & Høbster, Inc
 tp 22242 357 24X Fiche 50-327.84/02/07,8402150337
- 8402220384 Forwards 840207 listing of personnel cleared to perform status assessment QUANNE, D.L. Consumers Power Co. 84/02/07 HIERZER, G.A. Bachtel Corp. 2pp. 22334:129 24X Fiche 50-329:84/02/07.8402220384
- B402150287 Forwards for info sys & area engineer assignments W/a encl * Consumers Power Co 84/02/09 Stone & Wabster, Inc 1p 22242 341 24x Fiche 50-329.84/02/09.8402150287
- B402100330 Forwards QR Fotiades & E Kiehner affidavits & resumes KARR.JE Stone & Webster, Inc B4/02/09 HARRISON:JJ Region 3. Office of Director ip 22250 211 24X Fiche 50-329, 84/02/09, BA00150330
- --8402150331 Affidavit of G Fotiades re new appointment as procurement GA engineer, responsible for conducting third-party const implementation overview FOTIADES, G Stone & Webster, Inc. 84/01/31 4pp 22250:212 24X Fiche 50-329,84/02/09,8402150330
- --8402150338 Affidavit of E Kiehner re appointment as assistant ofc engineer, responsible for conducting thire-party const implementation overview KEHNER& E Stone & Wabster, Inc. 84/02/03 5pp 22250 216 24x Fithe 50-329,84/02/09.8402150330
- 8402160458 Forwards "Balance-DF-Plant Class 1,2 & 3 Piping, Pipe Supports & Valves," Vol IX, to seismic margin review.per B30204 ltr Lowest margin for pipe support is on DHR suction line & conservatively estimated to be 1 14 COOK-J W Consumers Power Co 84/02/09, DENTON, H R Office of Nuclear Reaction Pegulation, Director 3pp 22249 149 24x Fiche 50-329,84/02/09,8402160458
- --B402160460 "Balance-Of-Plant Class 1,2 & 3 Piping, Pipe Supports & Valves," Vol IX to seismic margin review KIPP. T R. CAMPBELL. R. D., SHEE. E. J. Structural Mechanica Associates SMA 13701 03R003 V07 84/02/09 250pp 28269 153 24X Fichs 50-329, 84/02/09, 8402160458

- 8402270474 Responds to FOIA request for documents re util mqt audit & associated iOCFR2 206 request Forwards App A documents App B documents withheld in entirety (ref FOIA Exemption 5)
 FELTON.J M Division of Rules and Records 84/02/09 GARDE.8 P Government Accountability Project 6pp 22414 252 24X
 Fiche 50-327,84/02/09.0402270494
- --B307180383 Refers Govt Accountability Project (OAP) 830613 10CFR2 206 ltr/petition to IE Resolution will require close coordination among IE.NRR & Region III Draft ltr to GAP encl LIEBERMAN, J Regional Operations & Enforcement Division 83/06/28 DEYDUNG, R C Director's Office, Office of Inspection and Enforcement DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 22414 271 24X Fiche 50-329,84/02/09,8402270494
- --B308040572 Forwards branch input for inclusion in Div of Licensing response to Guvt Accountability Project 830613 ltr reindependent third-party review of soil settlement issues LEAR.0 Structural & Geotechnical Engineering Branch 83/07/27 ADENSAM,E Licensing Branch 4 3pp 22414 278 24X Fiche 50-329,84/02/09.8402270494
- --8402270497 Draft outline, "Govt Accountability Project 2 206 Petition Request for Helief Factual Bases" Related info encl * NRC No Detailed Affiltation Given 84/02/09 13pp 22414 258 24X Fiche 50-329,84/02/09,8402270494
- 8402140194 Discusses modified approach to design & const verification effort Approach would allow design verification to be bifurcated from const verification Design verification could be completed by Jul 1984 LEVIN.H A TERA Corp 84/07/10 KEPPLER.J 9 Region 3, Dffice of Director EISENHUT,D 9 Division of Licensing COOK,J W Consumers Power Co 5pp 22223 327 24X Fiche 50-329.84/02/10, RAGOLAGISA
- B401190059 Board Notification 84-032 provides add1 info on environ qualification Submittal augments info in Board Notifications B4-004 & 84-007
 EIBENHUT, D & Division of Licensing B4/02/13 Atomic Bafety and Licensing Board Panel 10pp 22314 204 24X Fiche 50-000,84/02/13,8401170059
- 8402220515 Forwards 840210 list of Bechtel personnel trained to commence status assessment REICHEL, N I Consumers Power Co. 84/02/13 Stone & Webster, Inc. 3pp 82334 050 24X Fiche 50-329,84/02/13,8402220515
- 8402270379 Forwards complete response to Observation 035, Rept 22, including RA Wells 840206 ltr. Bechtel Ltrs BCCC-8985 & BCCC-8985 totil 840117 ltr & GAR RA-00062 W/D encl REICHEL, N I Consumers Power Co 94/02/14 Stone & Webster, Inc 1p 22391 179 24X Fichs 50-329,84/02/14,8402270379
- 84022801B1 Requests authorization to proceed w/Work Authorization Procedure 102950125 re installation of vertical movement monitoring instruments in control tower wall QUAMME.D L. Consumers Fower Co. 84/02/14 HARRISON.J.J Region 3. Office of Director 1p 22400-270 24X Fiche 50-329, 84/02/14, 8402280181
- 8402220179 Forwards "Unit 2 Turbine Roll Hilestone " NRC concurrence requested to pursue milestone Release of portions of required sys contained in modulos not currently released, but required to support milestone requested GUAMME.D.L. Consumers Power Co. 84/02/15, HARRISON, J. J. Region 3, Office of Director 2pp 22334 312 24X Fiche 50-327,84/02/15, 8402220179
- --8402220185 "Unit 2 Turbine Roll Milestone " W/eight oversize drawings Aperture cards are available in PDR * Consumers Power Co 84/02/27 17pp 22334 314 24X Fiche 50-329, 84/02/15,8402220179
- 8402280429 Forwards 840131 memo re use of registers in conjunction w/status assessment.840131 memo re work prints converted to status assessment prints & 830407 IE insp rept W/o encls.

 REICHEL.N I Carolina Power & Light Co 84/02/15 BROWN,D Stone & Webster, Inc ip 22404 288 24X Fiche 50-327,84/02/15,8402280429

- 8401190068 Board Notification 84-033 provides "Sys Interaction Program." task action plan for Unresolved Safety Issue A-17 Distribution 11st anci EIBENHUT.D 0 Division of Licensing 84/02/16 PALADIND Commissioners 8pp 22482 091 24X Fiche 50-000,84/02/16, 8401190068
- 8402240029 Forwards agendas for Independent Design & Const Verification 840229 & 0301 meetings to discuss open, confirmed & resolved item status & civil/structural status, respectively LEVIN, H A TERA Corp 84/02/21 KEPPLER, J O Region 3, Diffice of Director. EISENHUT, D G Division of Licensing CDOK, J W Gansumers Power Co 7pp 22375 245 24X Fiche 50-329,84/02/21, 8402240029
- 8402280518 Summary of 820315-19 meetings w/util & Bechtel in Ann Arbor. MI re audit preparations for proposed underpinning of svc water pump structure & review status of remedial plans Related documentation encl HOOD, D Licensing Branch 4 84/02/22 Licensing Branch 4 50pp 22427 083 24X Fiche 50-329,84/02/22,8402280618

F Security, medical, emergency & fire protection plans

- 8402220501 Revised emergency implementing procedures, including Rev i to App C, "Revise & Ray of General Ofc Control Ctr/Emergency Operations Facility Emergency Implementing Procedure" & revised index W/840217 ltr., # Consumers Power Co 84/01/10 10pp 22333 298 24X Fiche 50-000,84/01/10,8402220501
- 8402150395 Rev 5 to "Controlled Copyholders List General Ofc Control Ctr/Emergency Operations Facility Emergency Implementing Procedures " W/840209 1tr # Gonsumers Fouer Co 64/01/26 8pp 22242 061 24X Fiche 50-000,84/01/26,8402150395

9 Adjudicatory correspondence

- 8402010214 Forwards Sinclair Contention 2 re emergency planning.Part 2 of NRC regulations (ref Section 2 714 re late intervention) & two recent ASLAS decisions re late intervention W/o encl PATON.W.D Hearing Branch 2 84/01/25 BECKRUM.D Affiliation Not Assigned. 1p. 22038 359 24X Fichs 30-329.84/01/25.8402010214
- B402010091 Forwards proposed second supplemental findings of fact & conclusions of law for partial initial decision of GA issues & crass-reference to previously filed proposed findings & responses to proposed findings on GA LAUER, R J Isham, Lincoln & Beale LAUER, R J Consumers Power Co B4/01/27 COMAN, F P, HARBOUR, J, BECHHOEFER, C. Atomic Safety and Licensing Board Panel ip 22041 001 24X Fiche, 50-327, 84/01/27, 8402010091
- --8402010095 Forwards cross-reference to all util filed findings of fact & conclusions of law for partial initial decision on GA issues.

 LAUER.R J. Isham, Lincoln & Beale. LAUER.R J. Consumers Power Co. 84/01/27 Atomic Safety and Licensing Board Panel 44pp RZ041:002 24X Fiche 50-329,64/01/27,6402010091.
- --8402010098 Proposed second supplemental findings of fact & conclusions of law for partial initial decision on GA issues
 Certificate of Svc encl
 & Consumers Power Co 84/01/27 3lipp 22041.046, 24X
 Fiche 50-327,84/01/27,8402010091
- B402170036 Submits list of corrections to B40127 proposed second supplemental findings of fact & conclusions of law for partial initial decision on GA issues Certificate of Bvc encl.

 LAUER, R. J. Isham, Lincoln & Beale. LAUER, R. J. Consumers Power Co. B4/02/10, BECHHOEFER, C., HARBOUR, J., COMAN, F. P. Atomic Bafety and Licensing Board Panel 6pp 22301.128 24X Fiche 50-327,84/02/10,8602170034
- B402210111 Order extending time until 840327 for Commission to act to review Director's Decisions DD-83-16 t DD-84-2 CHILK, S J. Office of the Secretary of the Commission 84/02/17 Commissioners ip. 22317 241 24X Fiche. 50-327, 84/02/17, 8402210111
- 8402220369 Requests removal of WC Potter from svc list as atty for Dow Chemical Co.Related correspondence PDITER.W.C. Fischer, Franklin, Ford, Simon & Hogg. POTTER.W.C. Consumers Power Co. 84/02/17. Defice of the Secretary of the Commission ip, 22335.320 24X Fiche:50-329.84/02/17.8402220369

H General correspondence

- 8402020125 Forwards resume & affidavit for JE Karr, site program manager for const implementation overview program AMDRUSO.A P Stone & Webster, Inc 84/01/19 HARRISON, J J Region 3. Office of Director App 22036 189 24X Fiche 50-329,84/01/19. 8402020125
- 8402010316 Responds to 831230 request to prevent radioactive math discharge into Tittabawassee River because of synergistic effects between dioxin & radioactivity increasing incidence of cancer Effects miniscule DENION, H R Office of Nuclear Resctor Regulation, Director 84/01/20 400128.8 J Affiliation Not Assigned 3pp 22046 201 24X Fiche 50-329,84/01/20,8402010316
- --840201031B Requests cessation of radioactive matls discharge into Tittabawassee River Synergistic effect w/radioactivity increases cancer possibility GADLER,S J Affiliation Not Assigned B3/12/30 NRC No Detailed Affiliation Given 3pp 22046 204 24X Fiche 50-329,84/01/20,8402010316
- 8402220567 Requests assistance in obtaining controlled FSAR set KARR, J E Stone & Webster, Inc 84/02/13 QUAMME, D L Consumers Power Co 1p 22333 049 24% Fiche 50-329,84/02/13,8402220967

G Inspection reports, IE Bulletins & correspondence

- 8402060286 Further response to FOIA request for IE 800103 rept re review of mat) false statement at facility & all associated & supporting records to rept Forwards documents listed in App C App B documents available in FDR FELTON, J M Division of Rules and Records 83/11/15 WINSLOW, R Wall Street Journal 3pp 22111 048 24X Fiche 50-329,83/11/15,84020,60264
- --8402060297 Forwards insprepts & licensee repts re settlement of diesel generator bldg for referral to licensing board KEPPLER.J G Region 3. Chicago. Office of the Director 79/04/20 THORNBURG.H D Division of Reactor Construction Inspection 2pg 22111 074 24X Fiche 50-327.83/11/15.8402060284
- --8402060303 "Presentation of Investigation Findings of Settlement of Diesel Generator Bidg & Plant Area Fill "

 * Region 3, Chicago, Office of the Director 79/02/23 i6pp 221ii 076 24X Fithe 50-329.83/11/15.8402060286
- --B402060309 Forwards proposed ltr to util draft notice of violation & draft notice of proposed imposition of civil penalty Penalty recommended only for matl false statement KEPPLER.J O Region 3. Chicago. Office of the Director 79/10/29 GDWER.O C Executive Officer for Operations Support 17pp 24X Fiche 50-327.83/11/15.8402040286
- B402270536 FDIA request for agency records & info generated in connection w/or as result of T Novak visit to Region III ofc to discuss Ofc of Special Cases findings on facilities from Sept 1782 Doc 1783
 GARDE, B P Government Accountability Project B3/11/24 Office of Administration 2pp 22414 156 24X Fiche, 50-327, 83/11/26, 8402270534
- B402270331 Responds to FOIA request for records re T Novak visit to Region III ofc to discuss Ofc of Special Cases findings re facilities from Sept 1982 Dec 1983 No records subj to request located FELTON.J M Division of Rules and Records, 84/01/12 GARDE, B P Government Accountability Project 1p 22414 155 24X Fiche 50-387,84/01/12.8402270531
- 8402020168 Forwards 1E Audit Repts 50-327/84-01 & 50-330/84-01 on B40104-06 Audit conducted to evaluate upward bldg movements NRC should allow during underpinning of auxiliary bldg WARNICK, R F Region 3, Office of Director 84/01/18 COOK, J W Consumers Pawer Co 2pp 22057 183 24X Fiche 50-329, 84/01/18.8402020168
- --8402020178 IE Audit Repts 50-329/84-01 & 50-330/84-01 an 840104-06 Audit results, upward bldg movement limits proposed by licenses unacceptable. LANDBMAN.R.B. HARRISON.J.J. Region G. Office of Director 84/01/17 58pp 22057.185 24X Fiche 50-329,84/01/18,8402020168
- 8402020247 Forwards IE Insp Repts 50-329/63-26 & 50-330/63-27 on B31121-1231 No noncompliance noted WARNICK, R.F. Region 3, Office of Director 84/01/20 CDDK, J W Consumers Fower Co 2pp 22055 314. 24X Fiche 50-327, 84/01/20, 8402020247

- 3402020256 IE Insp Repts 50-329/83-26 & 50-330/83-27 on 831121-1231 No noncompliance noted Major areas inspected headquarters personnel document control stop work order, US Testing stop work & sits tours

 BURGESS.B L. COUK.R J. HARRISON.J J Region 3. Office of
 Director B4/01/19 Spp 22055 316 24X Fiche 50-329.84/01/20.
- 12120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Jumps " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Tesponse (Post 830103) 84/01/25 Consolidated Edison Co of New Jork, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120153
- 12060416 Forwards response to IE Bulletin 79-02. "Pipe Support Base late Designs Using Concrete Expansion Anchor Bolts " Imap if 100% accessible pipe support expansion anchors installed sefore 800530 complete ODK: J W Consumers Power Co 84/01/31 KEPPLER, J Q Region 3, 18fice of Director 6pp 22085 124 24% Fiche 50-329,84/01/31, 1402000414
- 01190016 IE Info Notice 84-07, "Design-Basis Threat & Review of 'ehicular Excess Controls " Svc list encl URDAN,E L Division of Emergency Preparedness & Engineering lespunse (Post 830103) 84/02/03 Consolidated Edison Co of New 'ork, Inc 119pp 22114 179 24X Fiche 50-000,84/02/03,8401190016
- 1190017 IE Bulletin 84-01, "Cracks in BWR Hark I Containment Vent leaders " Svc list enc) EYOUNG.R C Director's Office, Office of Inspection and nforcement 84/02/03 Consolidated Edison Co of New York, Inc 02pp 22177 156 24x Fiche 50-000,84/02/03,8401190017
- 2070125 Forwards IE Monthly Meeting Repts 50-327/84-02090 & 0-320/84-0209C on 840112 & weekly repts of independent sayssment of underpinning ARNICK.R F Region 3. Office of Director 84/02/03 COOK.J Wonsumers Power Co. 2pp. 22095 232 24% Fiche 50-329,84/02/03.402070125
- 402070131 IE Monthly Meeting Repts 50-329/84-0208C & 50-330/84-0208C on 840112 Major areas discussed description & status of major underpinning & const implementation overview program, crack mapping & review of work packages GARDNER-R N , HARRISON J J Region 3, Office of Director 84/02/02 8pp 22095 254 24X Fichs 50-329,84/02/03,8402070125
- 402070140 Forwards "Independent Assessment of Underpinning Weekly Rept 63" for 831127-1203 Minutes of daily meeting held during who between members of assessment team & site engineering const & GA personnel also encl LUCKG.A S Stone & Webster. Inc 83/12/08 COOK, R NRC No Detailed Affiliation Given 13pp 22095 288 24X Fiche 80-329,84/02/03,8402070125
- 102070144 Forwards "Independent Assessment of Underpinning Waskly Rept 64" for 831204-1210 Minutes of assessment toom & site engineering, const & GA personnel meeting also encl.
 LUCKS.A 8 Stone & Webster Inc 83/12/12 COOK, R NRC No Detailed Affiliation Given 16pp 22093 275 24X
 Fiche 50-327,84/02/03,8402070125
- 102070148 Forwards "Independent Assessment of Underpinning Weekly Rept 65" for B31811-1217 Minutes of daily meetings held during wk between members of assessment team & site engineering, const & GA personnel also encl.

 LUCKG, A S Stone & Webster, Inc. 83/12/28 CODK, R NRC No Detailed Affiliation Given 14pp 22075-311 24X

 Fiche 50-329,84/02/03,8402070125
- O2070155 Forwards "Independent Assessment of Underpinning Weekly Rept 66" for 831218-1224 Minutes of daily meeting held during wk between members of assessment team & site emergency, const & GA personnel also enc!

 LUCKS, A. S. Stone & Webster, Inc. 83/12/28 COOK, R. NRC No Detailed Affiliation Given 14pp 22095 325 24x

 Fiche, 50-329, 84/02/03, 8402070125
- 02070160 Forwards "Independent Assessment of Underpinning Weekly Rept 67" for B31225-31. Minutes of daily meeting held during we between members of assessment team & site engineering, const
- to A personnel also ent. Lucks, A. S. Stone & Mebster, Inc. 84/01/05 CDDK, R. NRC No. Debailed Affiliation Given. 12pp 22095, 337 24X Fiche 50-329, 84/02/03.8402070125
- 02070165 Forwards "Const Implementation Overview Rept 25" for 831128-1202 Rept includes evaluations of const completion program activities, matrices of observations, monconformance identification repts, hold points & affidavits
 IARANOW, 8 W Stone & Webster, Inc 83/12/05 KEPPLER, J 0 lepion 3, Office of Director 18pp. 22075 347. 24X
 Tiche 50-329, 84/02/03, 8402070125

- -8402070169 Forwards "Const Implementation Overview Rept 26" for B31205-09 Rept includes evaluations of const completion program activities, matrices of observations, nonconformance identification repts & affidavits

 BARANOW, 8 W Stone & Webster, Inc. 83/12/13 KEPPLER, J G Region 3, Office of Director 13pp 22096 005 24X Fiche 50-329,84/02/03,8402070125
- --B402070454 Forwards "Const Instrumentation Overview Weekly Rept 27" for B31252-16 Rept includes summary of activities for wk & open items.nonconformance identification repts & hold points INARANOW.S W Stone & Wobster, Inc 83/12/21 KEPPLER, J O Region 3, Office of Director 18pp 22096 018 24% Fiche 50-329,84/02/03,8402070125
- 8402190380 Forwards responses to NRC 840104-06 audit questions documented in 840117 IE Insp Rept 84-01 re auxiliary bldg underpinning W/33 oversize drawings Aperture cards are available in PDR MOUNEY, J A Consumers Power Co 84/02/08 HARRISON, J Region Office of Director 183pp 22271 180 24X Fiche 50-329, 84/02/08, 8402190380
- -8402150387 "Evaluation of Observed Cracks in Auxiliary Bldg at Elevation 685 Ft Control Tower Floor " CORLEY, W g , DEBTERLE, R g , MORGAN B J Construction Technology Laboratories 84/01/30 100pp 22271 258 24X Fiche 50-329,84/02/08,8402150380
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (1905R50, App R) " Syc list encl enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/13 Consolidated Edison Co of New York, Inc. 124pp 22365-239 24X Fiche 50-000,84/02/13,8401190041
- 8401190000 Board Notification 84-021 provides rept» of Transamerica Belaval.Inc insps conducted from Mar 1979 to Oct 1983 EIBENHUT.D G Division of Licensing 84/02/13 PALLADINO Commissioners 5pp 22314 001 24X Fiche 50-000,84/02/13, 8401190050
- 8401170039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection'" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/14. Consolidated Edison Co. of New York, Inc. 113pp. 22365 141 24X Fiche 50-000.84/02/14,8401170037
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Westinghouse Type BA-1 Differential Relays" Svc list encl.

 JDRDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15. Consolidated Edison Co of New York, Inc. 118pp 22346.142 24X Fiche 50-000,84/02/15,8401190045
- 8402270208 Forwards IE Insp Repts 50-327/84-03 & 50-330/84-03 on B40101-31 & notice of violation.

 MARNIGE, RF Region 3, Office of Director 84/02/15 CODK.J.K Consumers Power Co 2pp 22426 077 24X Fiche 50-327,84/02/15.
- B4/02/15. 1p
- --8402290221 IE Insp Repts 50-329/84-03 & 50-330/84-03 on 840101-31 Noncompliance noted failure to protect installed mechanical shubbers from physical damage during const GARDNER,R N. LANDSMAN,R B., BURGESS,B L. Region 3, Office of Birector 84/02/15 7pp 22426 082 24X Fiche 50-327,84/02/15,8402290208.
- 8408220424 Ack receipt of 840201 ltr providing further response to NRC notice of violation & proposed imposition of civil penalties sent w/880208 ltr & request for add1 info Request for extension granted in view of current stop work order HARNICK, R F. Region 3, Office of Director 84/02/17 CDOK, J W. Consumers Power Co. 2pp. 2234 181 24X Fiche. 50-329, 84/02/17, 8402220424
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Ewitches Bet Below Manufacturer Recommended Value " Svc list encl JORDAN,E L Division of Emprency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co. of New York, Inc 116pp 22366 024 24X Fiche. 50-000,84/02/21, 8401190062
- 8401190066 IE Info Natice 84-11, "Training Program Deficiencies,"
 Svc list encl.
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/24. Consolidated Edison Co. of New
 York, Inc. 115pp 22430.304 24X Fiche.50-000,84/02/24,8401190066

- 8401150057 IE Info Notice 84-12. Failure of Soft Seat Valve Seuls '
 Svc list encl
 JORGAN.E L. Division of Energency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of NeYork, Inc. 120pp 22431 060 24% Fiche 50-000.84/02/27.840119006
- R Periodic operating reports & related correspondence
- 8402020033 Partial response to FOIA request for documents re evaluation or review of design.const scheduling.cost & licensing of facilities from 1977 to present Forwards App A & B documents
 FELTON, J M Division of Rules and Records 83/11/04 ZACK.A M Barris. Sott. Denn & Driker 11pp 22079 208 24X
 Fiche 50-000.83/11/04.84020200033
- --B402020046 Forwards Feb project status repts MARTINEX.P A Bechtel Corp 78/03/15 COUNE.T C , KEELEY.G S . NENGEN.J F Bechtel Corp 1p 22080 004 24X Fache 50-000.B3/11/04.B402020033
- --8402020052 "Project Status.Feb 1978 " Related info encl * Bechtel Corp 78/02/28 61pp 22080 005 24x Fitch 50-000.83/11/04.8402020033
- --8402020061 Forwards "Project Status Rept.Jul 1979"
 RUTGERS.J A Bechtel Corp 79/09/07 KEELEY.G S Consumers
 Power Co ip 22080 077 24X Fiche 50-000.83/11/04.8402020033
- --8402020064 "Project Status Rept.Jul 1979 " Related info enc) * Bechtel Corp 79/07/31 45pp 22080 078 24X Fiche 50-000.83/11/Q4.8402020033
- 8402020161 Forwards 44th quarterly rept for Jan-Mar 1984.per ALAB-106 memorandum & order CODK.J W Consumers Power Co 84/01/20 DEYONG.R C Director's Office. Office of Inspection and Enforcement 6pp 22056 143 24/Fiche 50-327.84/01/20.8402020161
- 8402020292 Forwards weekly jobsite subcontract status rept for wk ending 840113 per R Scallon request W/o encl • Consumers Pdwer Co 84/01/23 Stone & Hebster, Inc ip 22055 182 24x Fiche 50-329,84/01/23,8402020292
- B402070125 Forwards IE Monthly Meeting Repts 50-327/B4-020SC & 50-330/B4-020SC on B40112 & weekly repts of independent assessment of underprinning WARNICK.R F Region 3. Office of Director 84/02/03 COOK.J W Consumers Power Co 2pp 22095 252 24X Fiche 50-329.84/02/03. B402070125
- --8402070140 Forwards "Independent Assessment of Underpinning Weekly Rept 63" for 831127-1203 Minutes of daily meeting held during wit between members of assessment team & site engineering const & GA personnel also enc!

 LUCKS.A S Stone & Webster, Inc 83/12/08 COOK, R NRC No Detailed Affiliation Given 13pp 22095-282 24x

 Fiche 50-329,84/02/03,8402070125
- ---B402070144 Forwards "Independent Assessment of Underpinning Weekly Rept 64" for B31204-1210 Minutes of assessment team & site engineering.const & GA personnel meeting also encl LUCKS.A S Stone & Webster, Inc. B3712/12 COOK,R NRC - No Detailed Affiliation Given 16pp 22095-295 24x Fiche. 50-329,84/02/03.8402070125
- --B402070148 Forwards "Independent Assessment of Underpinning Weekly Rept 65" for 831211-1217 Minutes of daily meetings held during we between members of assessment team & site engineering.const & GA personnel also encl LUCKS.AS Stone & Webster, Inc 83/12/28 CODK, R NRC - No Detailed Affiliation Given 14pp 22095 311 24X Fiche 50-329,84/02/03,8402070125
- --B402070155 Forwards "Independent Assessment of Underpinning Weekly Rept &6" for 831218-1224 Minutes of daily meeting held during who between members of assessment team & site emergency, const & GA personnel also encl LUCKS.A B Stone & Webster, Inc 83/12/20 CDDK,R NRC ~ No Datailed Affiliation Given 14pp 22095 325 24X Fiche 50-329,84/02/03.8402070125
- ---B402070160 Forwards "Independent Assessment of Underpinning Weekly Rept 67" for B31225-31 Minutes of daily meeting held during with between members of assessment team & site engineering.const & QA personnel also encl LUCKB; A B Stone & Webster, Inc. 84/01/05 CDOK,R NRC No Detailed Affiliation Given 12pp 22095 337 24X Fiche: 50-329,84/02/03,8402070125

- --B402070165 Forwards Const Implementation Overview Rept 25" for 83: 1202 Rept includes evaluations of const completion program activities natrices of obser ations nonconformance identification repts hold points & affidavits BARANOM.S W Stone & Webster. Inc B3/12/05 KEPPLER.J G Region 3. Office of Director 18pp 22095 349 24x Fiche 50-329 84/02/03 8402070125
- --84020/0169 Forwards Const Implementation Overview Rept 26" for 831205-09 Rept includes evaluations of const completion program activities matrices of observations, nonconformance identification repts & affidavits DARANOW.5 W Stone & Webster Inc 83/12/13 #EPPLER, J Q Region 3. Office of Director 13pp 22076 005 24x Ficht 50-329,84/02/03,8402070125
- --B402070454 Forwards 'Const Instrumentation Diverview Heekly Rept 27' B31212-16 Rept includes sum-any of activities for wilk open items, nonconformance identification repts & hold points DARANDH,S W. Stone & Hebster, Inc. B3/12/21 KEPPLER, J. G. Region 3: Office of Director 18pp 22096 018 24x Fiche 50-329,84/02/03.8402070125
- 8402130343 Advises that util response to Meeting Note D on Page 2 of Weekly Rept 25 re overview of const completion program satisfactory
 KARR.J E Stune & Webster, Inc. 84/02/03 QUAMME.D L Consumer Power Co. 2pp. 22203 297 24X Fiche 50-329,84/02/03 8402130343
- rower to app 22203 277 244 rithe 50-327, 84702703 8402130343
- 8402130427 Advises that response to Const Implementation Overview Ite 03B re check list procedures contained in Meeting Note D on Page 2 of Weekly Rept 25 acceptable KARR.J E Stone & Habster, Inc. 84/02/03 QUAMME,D L. Consumers Power Co. 42p. 22201 275 24X Fiche 50-329,84/02/03 8402130429
- 8402100194 Forwards status rept for Jan 1984 W/o encl WARNICK.R F Region 3. Office of Director 84/02/06 KEPPLER.J G Region 3. Office of Director 5p 22182 188 24% Fiche 3D-327.84/02/06.8402100194
- --8402100199 Forwards status rept for Jan 1984 Major areas discussed include document control stop work orders & remedial soils work activities CODK.R J Region 3. Office of Director 84/02/03 WARNICK.R F Region 3. Office of Director 2pp 22182 189 24x Fiche 50-329.84/02/06.8402100194
- B402210271 Forwards "Midland Independent Design & Const Verification Program Monthly Status Rept 9 for Jan 1984 " LEVIN-H A TERA Corp 84/02/15 KEPPLER, J G Region 3, Office of Director EISENHUT, D G Division of Licensing COOK, J W Consumers Power Co 3pp 22316 210 24% Fische 50-327,84/02/15. B402210271
- --8402210274 "Independent Design & Const Verification Program Monthly Status Rept 9 for Jan 1984 " DOUGHERTY.F A TERA Corp 84/02/15 64pp 22316 213 24X Fiche 50-329.84/02/15.8402210271
- S Reportable occurrences. LERs & related correspondence
- B40214039B Requests add1 info re Part 21 rept dtd 831108 concerr wear ring failure in auxiliary feedwater pump fornished to facilities Info requested within 25 days POTAPOVS,U Region 4, Office of Director 83/11/30 PATTY. Bingham-Willamette Co ip 22221 250 24x Fiche 50-000, B3 840214039B
- --8402140422 Supplemental Part 21 rept re wear ring failure i feedwater pumps, per 831130 request for add1 info Hear rin will be replaced on returned units w/AIST 420 wrought mat List of pumps in similar svc w/same wear ring encl PATTY, D.F. Bingham-Willamette Co. 83/12/20 Region of Director 2pp 22221 251 24X Fiche 50-000,83/11/3 8402140398
- 8402030286 Forwards listed nonconformance repts for info H/ REICHEL.N I Consumers Power Co 84/01/26 Stone & M 1p 22069 356 24% Fiche 50-329.84/01/26.8402030286
- 8402030461 Forwards response to Nonconformance Identifica 007, listing Bechtel gersonnel trained to indicated disciplines per W Sienkiewicz request * Consumers Power Co B4/01/26 Stone & Webster, In 22069 06B 24X Fiche 50-329,84/01/26,8402030461
- 8402060276 Advises that const implementation overview electrical field change requests/field change notic discrepant conditions noted in encl Nonconformanc' identification Rept 013 Corrective actions reque KARRIJE Stone & Webster. Inc 84/01/26 GVAI Power Co 15pp 22087 126 24X Fiche 50-327.8

- 8408060124 Interim deficiency rept re accident temp effects on containment level measurements Design being revised for Class IE steam generator level issued measurements Next rept by 840420 CODK.J W Consumers Pawer Co 84/01/27 KEPPLER, J & Region 3 Office of Director 3pp 22089 301 24X Fiche 50-329.84/01/27, 84020.60124
- 8402060249 Forwards listed open const implementation overview
 Nonconformance Identification Rept 014 for action/info
 KARR, J E Stone & Webster, Inc 84/01/27 8UAMME.0 L Consumers
 Power Co 2p 22088 141 24% Fiche 50-329,84701/27,8402060249
- 8402060371 Final deficiency rept re adequacy of sheer reinforcements at major containment penetrations Initially reported on 810515 Analyses of major areas concluded containment meets design requirements CODK, J & Consumers Power Co. 84/01/27 KEPPLER, J Q. Region 3. Defice of Director opp. 22086-276 24X Fiche 50-327,84/01/27,84020.6371
- '402060372 Forwards closed-out GAR RT-00024 in response to Nanconformance Identification Rept 013 W/o encl F Consumers Power Co. 84/01/27 Stone & Nebster, Inc. 1p 22085 302 24% Fiche 50-327,84/01/27,8402060372
- | IOZOGO454 Interim deficiency rept re differential settlement between diesel generator structure & diesel generator pedestal Design process under review Next rept by 840420 M/one oversite drawing Aperture card is available in PDR COUK, J W Consumers Power Co 84/01/30 KEPPLER, J G Region 3. Office of Director 4pp 22083 092 24X Ficha 50-329.84/01/30. 8402060454
- B402070365 Part 21 rept re linear converter device w/possible generic defect Initially reported on 840116 Written notifications issued Customer responses should be received by 840331 Final rept will be submitted by 840430 DDBSON, J P Pacific Air Products Co 84/01/30 Director's Office, Office of Inspection and Enforcement 2pp 22114 277 24% Fiche 30-280.84/01/30,8402070365
 - -8402070373 Part 21 rept re linear converter device w/possible generic defect Initially reported on B40116 Preliminary analysis indicates excessive wear of brass shaft guides Next rept will be submitted within 90 days Supporting info encl DDBSDN.J P Pacific Air Products Co B4/01/17 PDTAPDVS.U Region 4. Office of Director 69pp 22114 301 24X Fiche 50-000.84/01/30.8402070365
- 3402080237 Forwards Quality Action Request RT-00026 to provide tracking in MPGAD QUAIL sys per Nonconformance ldentification Rept 014

 * Consumers Power Co 84/01/31 Stone & Webster, Inc 5pp 22134 235 24X Fiche 50-329,84/01/31,8402080237
- 3402080324 Forwards rev to drawings listed in 840130 Ltrs CBC-7251 & SHMCP-023 Bechtel 840130 ltr re pitting in pack areas of MSIVs encl
 REICHEL.N I Consumers Power Co 84/01/31. Stone & Webster, Inc 3pp 22131 221 PAX Fiche 50-329,84/01/31,8402080324
- B402070361 Interim deficiency rept re small break/reactor coolant pump operation interaction Final rept re coolant pump trip issue expected in Apr 198A Next update expectes by 840601 COOK, J R Consumers Power Co 84/02/01, KEPPLER, J Q Region 3, Office of Director 3pp 22076 191 24X Fiche 50-329,84/02/01,8402070361
- 8402070393 Requests that NRC investigate design reliability of emergency diesel generators supplied by Transamerica Delaval. Inc Engine problems have been experienced since delivery of first vessel in May 1981 Related info encl MOLINAL C Falcon Carriers, Inc. 84/02/01 DEMTON.H R Office of Nuclear Reactor Regulation, Director 63pp 22096 057 24X Fiche 50-000.84/02/01.8402070393
- B402220404 Forwards status info re amended B30712 response to Region III 830523 ltr Extension for full compliance requested Delay due to error in manufacturer (TDI) insp procedures & current stop work orders CODK, J W Consumers Power Co 84/02/01 KEPPLER, J O Region 3, Office of Director 7pp 22337 001 24X Fiche 50-327,84/02/01, 84093010404
- 8402130473 Forwards Nonconformance Identification Repts 007 & 013 re review of electrical field change rapts & field change notices, respectively Two areas of noncompliance observed, per FID 2 400, Rev 3 & FFG-2 000, Rev 5 KARR, J E Stone & Webster, Inc. 84/02/02. QUAMME, D L Consumers Power Co 20pp 22201 151 24% Fiche 50-327,84/02/02,8402130473

- 8402080227 Interim deficiency rept re design embedments in concrete using shear lugs located in tension zones Embedment testing program almost completed Next rept will be submitted by 840224 CDDK.J W Consumers Power Co 84/02/03 KEPPLER,J 0 Region 3, Office of Director 3pp 22130 079 24X Fiche 50-329,84/02/03,8402080227
- 840Ri30463 Forwards Nonconformance Identification Rept 013 re review of clertrical field change repts & field change notices Eight discrepancies found KARR.J E Stone & Hebster, Inc 84/02/03 QUAMME.D L Consumers & Power Co 2pp 22202 035 24% Fiche 50-327.84/02/03,8402130463
- 840R220504 Interim deficiency rept to excessive voltage drop on auxiliary feedwater reversing valve actuator power cable Initially reported on 840106 Dosign calculation provides criteria for sizing cables CUDK.J W Consumers Power Co 84/02/03 KEPPLER.J G Region 3, Office of Director Bpp 22334 074 24X Fiche 50-327,84/02/03,820023334
- 8402190228 Forwards response to Tracked Info Item 049 re discrepancies in document control methods All controlled distribution will be issued from field document control ctr # Consumers Power Co 64/02/06 Stone & Webster, Inc 3pp 22244 313 24X Fiche 50-327.84/02/06.8402150228
- R402150276 Forwards signed response to Tracked Info Items 045 & 050 re G-interface canst work permits * Consumers Power Co 84/02/06 Stone & Webster, Inc 9pp 22250 157 24X Fiche 50-329,84/02/06,8402150296
- B402150299 Forwards complete response to Tracked Info Item 041 re Transamerica Uniaval: Inc emergency diesel generators * Consumers Power Co 84/02/07 Stone & Webster, Inc 3pp 22244 234 24X Fiche 50-329, B4/02/07, B402150299
- 8402130347 Forwards response to Tracked Action Item 048 re const implementation overview concerning inconsistency between spec requirements on specing between anchor bolts of different diameters

 * Consumers Power Co 84/02/07 Stone & Webster, Inc 3pp 22200 105 24% tiche 30~329,84/02/07.8402150347
- 8402150334 Considers revised response to Const Implementation Overview Item 036 re field change notice for G-work satisfactory Item closed KARR, J E Stone & Webster, Inc 84/02/07 GUAMME, D L. Consumers Power Co 1p 22242 355 24X Fiche 50-329,84/02/07,8402150354
- 8402220522 Forwards Mgt Corrective Action Rept 70 re discrepancies in electrical raceway & raceway supports Project Engineering will develop & implement plan to review cable tray support drawings for lack of specific design criteria * Consumers Power Co 84/02/07 Stone & Webster, Inc 3pp. 2233.245 24X Fiche 50-329.84/02/07,8402220822
- B402150322 Considers results of const implementation overview (CID) review of field change request/field change notice for mechanical discipline satisfactory CID Hold Point OII released in entirety KARR.JE Stone & Webster, Inc. 84/02/08 QUAMME.D.L. Consumers Power Co. 7pp. 22250 196. 24X Fiche 50-327,84/02/08,8402150322
- B402220111 Forwards QA Audit Finding Repts MBA-83-28-13F, Rev 1, MBA-83-22-01F, M9A-83-32-01F, Rev 1, MBA-83-32-01F, M9A-83-35-01U, Rev 1, M01-19-3-11F, M01-19-3-10F, & MSA-83-39-03F W/o encis
 * Consumers Power Co 84/02/08 Stone & Webster, Inc ip 22326 057 24% Fiche 50-32F, 84/02/08, 8402220111
- 8402220199 Forwards partial response to Const Implementation Overview Meekly Rept 4 Development of commitment mgt sys currently in initiation stages & will be completed in 8 to 12 months Project manpower requirements listed # Consumers Power Co 84/02/08 Stone & Webster, Inc 3pp. 22339 148 24% Fiche 50-329,84/02/08,8402220199.
- 8402220507 Advises that as result of 840208 Stap Work Order FSW-41 for mechanical discipline documents. Bechtel released for status assessment for Modules 340, 102, 120, 410 & 800. Fully trained personnel will conduct assessment * Consumers Power Co 84/02/09 HIERZER, 9 A Bechtel Corp 14pp 22334 040 24% Fiche 50-329, 84/02/09, 8402220507
- 8402130355 Forwards const implementation overview Open Item 051,
 "Field Procurement/Receipt Insp" & Item 052, "Criterion
 XVIII Site Auditing "
 KARR, J E Stone & Webster, Inc 84/02/09 QUAMME, D L Consumers
 Power Co 3pp 22203 301 24X Fiche 30-329, 84/02/09, 8402130355

- 8402130366 Forwards corrected first sheet of Nonconformance Identification Rept Old, "Review of Electrical FCRs & FCNs/ Document Control" Document Control "
 KARR.J E Stone & Webster, Int 84/02/09 QUAMME.D L Consume
 Power Co 2pp 22203 271 24X Fiche 30-329,84/02/09,8402139366 Consumers
- B402150316 Informs that Stop Work Order FSW 37 re Q-list drawings & specs released on B40208 Bechtel requested to formally advise B&W Const Co of release Order encl * Consumers Power Co B4/02/09 HIERZER. Q A Bechtel Corp 1: Consumers Power Co 22241 278 24X Fich Rechtel Coro 13nn 24X Fiche 50-329,84/02/09,8402150316
- 8402220012 Advises that encl Stop Work Order FSW 35 re G-listed work released, effective 840209 Related Bechtel correspondence also encl GUAMME, D L. Consumers Power Co. 84/02/09 HIERZER, G A. Bechtel Corp. 12pp. 22338 237 24% Fiche 50-329, 84/02/09, 8402220012
- B402220457 Requests that Zack Co be advised of 840207 release of Stop Hark Order FSW 33 re HVAC area problems Related info encl QUAMME.D L. Consumers Power Co 84/02/07 HIERZER,G A Bechtel Corp 11pp 22337 332 24X Fiche 30-327,84/02/09.8402220457
- 8402150318 Forwards closed Const Implementation Overview Item/Hold Point Notifications 008:009,032:033 & 041 for action/info KARR:JE Stone & Webster, Inc. 84/02/10 GUANME;D L. Consumers Power Co 7pp 22250 093 24X Fiche. 50-327:84/02/10:8402150318
- 8402220184 Forwards closed Const Implementation Overview Item/Hold Point Notification Oil re Phase II activities for action KARR. J E Stone & Webster, Inc 84/02/10 QUAMME, D L Consumers Power Co 6pp 22340 348 24% Fiche 30-329, 84/02/10, 8402220184
- 8402220193 Interim Deficiency Rept 83-093 re inconsistencies for processing field changes for project design documents. Program established & documented in field change request/ field change notice program Next rept by 840406 COOK, J. W. Consumers Power Co. 84/02/10 KEPPLER, J. O. Region 3, Office of Director 8pp. 22340 336 24X Fiche 50-329,84/02/10, 8403200193
- B402220202 Forwards complete response to Const Implementation Overview Hold Point Old re thermocouples + Consumers Power Co B4/02/10 Stons & Webster, Inc Spp 22339, 179 24X Ficher 50-329, 84/02/10, 8402220202
- 8402220206 Forwards RC Sember 840207 notification of rescheduled 840215 exit meeting for Audit MCA-83-38, field change notice/request syrview. Meeting originally scheduled for 831202 * Consumers Power Co 84/02/10 Stone & Webster, Inc 2pp 22338-356 24X Fichr 50-327,84/02/10,8402220206
- 8401190053 Board Notification 84-020 forwards info re Transamerica NULLYOUDE BOARD NOTIFICATION 84-020 forwards info re Transameri Delaval Inc emergency diesel generator problems Attendance list, meeting handouts & slides encl EIBENHUT, D O Division of Licensing, 84/02/13 PALLADINO Commissioners 102pp 22332-202. 24X Fiche-50-000,84/02/13, 8401190053
- 8401190055 Board Notification 84-023 provides supplemental info re nine stop work orders as result of design document GA/GC issues before ASLB, Field Stop Work Order (FSW) 38, re remedial soils work fully lifted NOVAK.T M. Assistant Director for Licensing 84/02/14 BECHHOEFER,C , HARBOUR, J , COHAN.F Atomic Safety and Licensing Board Panel. Spp. 22277.068, 24X Fichs.50-329.84/02/14,8401190055
- ---8402160469 Recommends Board notification to provide encl info re status of nine stop work orders as result of design control change problems relevant to facility DM/DL hearings MARNIGK.R.F. Region 3. Office of Director 84/01/31.

 EIBENHUT.D 9 Division of Licensing 3pp 22277 073, 24X Fiche, 50-329, 84/02/14, 8401190055
- 8402270015 Transmits listed audit findings repts & unresolved items W/o entis. JOHNSON D Consumers Power Co 84/02/14, Stone & Webster, Inc 1p. 22387.360 24X Fiche: 50-329,84/02/14,8402270015
- 8402270123 Forwards Nonconformance Identification Rept 012 re civil review Phase III field change request/field change nutice const implementation overview of ofc drawings stations NARR, J E Stone & Webster, Inc 84/02/14 GUAHME, D L Consumer Power Co 14pp. 22387-308, 24X Fiche. 50-329, 84/02/14, 8402270123
- 8402280364 Submits list of audit finding repts & unresolved items. * Consumers Power Co 84/02/14 Stone & Webster, Inc. 1p 22407.130 24X Fichs.50-329.84/02/14.8402280364.

- B402220530 Part 21 rept re defective DSR & DSRV standby diesel qenerator turbocharger thrust bearing lubrication Deficiency not corrected by sys mod New recommendation will be sent to customers by 840330 customers by 840330 MOYCR.R E Transamerica Delaval, Inc. 84/02/15 Director's Office, Office of Inspection and Enforcement 5pp 22332 182 24X Fichs 50-000,84/02/15.8402220530
- 8402270010 Forwards SCRE 19 per Landsman 840215 request W/o encl WELLO.R A Consumers Power Co 84/02/15 HARRISON, J J Regio Office of Director 1p 22387 361 24X Fiche 50-329, 84/02/15. 8402270010
- B402270315 Forwards closed const implementation overview hold point notification Items 045 & 038 re engineering documentation & mechanical sys status & completion, respectively KARR, J & Stone & Webster, Inc. B4/02/15 BUAMME,D L. Consumer Power Co. Spp. 22389 282 24X Fiche 50-329,84/02/15,8402270315 Consumers
- 8402270497 Forwards new index for const implementation overview procedures & instructions & Rev 3 to "Third-Party Cost Implementation Overview" Implementation Overview " KARR.JE Stone & Webster, Inc. 84/02/15 Stone & Webster, Inc 10pp 22390 192 24% fithe 50-329.84/02/15.8402270437
- 8402280435 Forwards response to Nonconformance Identification Rept Oil Conflict noted in implementation of Symbol R for retired field change reviews & natices for controlled architectural agniwarb * Consumers Power Co 84/02/15 Stone & Webster, Inc 4pp 22403 029 24% Fiche 50-329, 84/02/15, 8402280435
- 8402280577 Forwards Rev 1 to Audit Finding Rept MBA-B3-19-11F Verification of separate temp sensor & switch required Drawings should be revised to reflect location of temp switch & sensor JOHNSON, D. Consumers Power Co. 84/02/15 Stone & Websit 3pp 22406 272 24X Fiche 50-329: 84/02/15, 8402280577 Stone & Webster, Inc
- 8402270100 Forwards Const Completion Program Item 53 re team organization.team work scope & working schedules KARR.JE Stone & Webster, Inc 84/02/16 QUAMME.D L. Consume: Power Co 2pp 22391 275 224 Fiche 50-329:84/02/16,8402270100
- B402270452 Interim deficiency rept re high energy line break analysis pipe whip restraint designs Design drawings re requirement to postulate arbitrary intermediate breaks issued Next rept by 840320 CDOK, J.W. Consumers Power Co. B4/02/20 KEPPLER, J.O. Region 3, Office of Director 10pp 22387 333 24% Fiche 50-329,84/02/20, B402270452
- 8402280416 Forwards, for info.Audit Finding Repts MSA-83-17-18F,Rev 2, MSA-83-34-01F,MSA-83-34-02F,MO1-603-3-03 & Unresolved Item MO1-602-3-02 W/o encls REICHEL,N I Consumers Power Co 84/02/20 Stone & Webster, In ip 22407 168 24X Fiche 50-327.84/02/20,8402280416
- 8402280321 Forwards closed Nonconformance Identification Rept 011 re architectural review Phase III for 1nfo. KARR, J E Stone & Webster, Inc 84/02/21 QUANME, D L Consumers Power Co 3pp 28399 101 24X Fiche 50-329,84/02/21,8402280321
- 8402280336 Forwards open const implementation overview/hold point notifications for Items 088-060 re annual const audits KARR, J E Stone & Webster, Inc. 84/02/21 GUAMME.D L. Consumer Power Co. 6pp. 22399 086 24X Fiche 30-327,84/02/21,8402280336
- B4022B0440 Forwards Nonconformance Identification Rept 018 re nonmanual training records

 KARR, J E Stong & Webster, Inc 84/02/21 QUANNE, D L Consumers

 Power Co 2pp 22407 169 24X Fichs 30-329,84/02/21,8402280440
- 8402280581 Forwards open Noncomformance Identification Repts 015,016 & 017 re site auditing
 KARR.J E Stone & Webster. Inc 84/02/21 GUAMME.D.L Consume
 Power Co 4pp 22406.294 24X Fiche 50-329.84/02/21.8402280581
- 8402280584 Forwards Const Implementation Overview. Items 056 & 057 re Organization of impact of items on training & evaluation by first training classes requested KARR.J E Stone & Webster. Inc. 64/02/21 GUANNE,D L. Consumer Power Co. 3pp. 22406-291 24X Fiche 50-329.84/02/21.8402280584
- 8402290213 Forwards list of Bechtel personnel trained to accomplish * Consumers Power Co 84/02/21 Stone & Webster, Inc. 2pp 22425.075 24% Fiche 50-329,84/02/21.8402290213

- 840R290218 Forwards revised list of Bechtel personnel trained to accomplish status assessment Cross~trained personnel denoted
 - rs Power Co 84/02/21 Stone & Webster, Inc 3pp 24X Fiche 50-329,84/02/21,8402290218 22428 169
- 8402290191 Advises that unresolved Items MSA-B3-7-02U & MSA-B3-39-02U & audit finding Repts MSA-B3-32-04F & M01-07-3-04F closed * Consumers Power Co 84/02/22 Stone & Webster, Inc 1p 22426 362 24% Fiche 50-329, 84/02/22, 8402270151
- 8402290155 Forwards Rept 29 meeting note resolving arc strike issue.per SCN 14001 to Spec C-304. "Field Fabrication, Repair & Erection of Structural Steel & Metal " * Consumers Power Co 84/02/22 Stone & Webster, Inc 4pp 22428 142 24x Fiche 50-329,84/02/22,8402290155
- 8402290252 Forwards partial response to Hold Point OOI, Rept 6 re project plan for incorporation of redlines for large-bore pipe hangers 4 Consumers Power Co 84/02/22 Stone & Webster, Inc 2pp 22427 304 24% Fiche 50-329,84/02/22,8402290252
 - Stone & Webster, Inc. 2pp
- B408290256 Forwards for info Quality Action Request RT-00019 redeficiencies in const training records

 * Consumers Power Co 84/02/23 Stone & Webster, Inc 9pp 22427 237 24X Fiche 50-329.84/02/23,8402270256
- 8402290278 Forwards complete response to Tracked Action Item 053 W/o enci * Consumers Power Co 84/02/23 Stone & Webster, Inc. ip 22426 301 24% Fiche 50-329.84/02/23.8402290278
- DOCKET 50-330 MIDLAND PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- B402020027 FOIA request for documents re evaluation or review of design const, scheduling, cost & licensing of facilities from 1977 to
 - Present JACK, A M. Barris, Sott, Denn & Driker 83/09/29 Division of Rules and Records 1p 22079 207 2 Fiche 50-329,83/09/29,8402020029 FELTON: J M
- 02070003 Responds to FQIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A,B & C documents
 FELTON.J M Division of Rules and Records 83/10/31
 RDSENBAUM.D M Technical Analysis Corp 19pp 22193 292 24X
 Fiche 50-000.83/10/31
- B402090086 Comments on 790618 meeting re-estimated fuel load date Util requested site visit & evaluation of const schedule & fuel load date as soon as possible Related info encl.

 * NRC No Detailed Affiliation Given. 79/06/18 NRC No Detailed Affiliation Given Bpp. 22195 144. 24X Fiche 50-000, B3/10/31, 8402090003
- --8402070101 Bummarizes 800613 meeting w/util re NRC review of UL application Related info encl BRUNNER.J E Isham, Lincoln & Beale BRUNNER.J E Consumers Power Co 80706/13 Isham, Lincoln & Beale 9pp 22195-154. 24X Fiche 50-000.83/10/31.8402090003
- -8402090118 Handwritten charts, notes & calculations re const activities & estimated const completion.Related info encl.

 * NRC - No Detailed Affiliation Given B0/08/04 50pp
 22195 16B 24X Fiche 50-000,B3/10/31,B402090003
- --8402070122 Handwritten calculations re const activities Related info enci * NRC - No Detailed Affiliation Given. 81/08/26 22195 232 24X Fiche 50-000.83/10/31.8402090003
- --B402070135 Handurittan notes & calculations re const activities & fuel load preparation Related info encl # NRC - No Detailed Affiliation Given 83/04/19 27pp 22195 316 24X Fiche 50-000,83/10/31,8402090003
- --840R070142 Draft trip rept of 780321-22 site visits re const schedules & in-progress const activities observation Fuel load dates for Units 1 & 2 are Nov 1981 & Nov 1980, respectively Related info encl
 * NRC No Detailed Affiliation Given 83/10/31, NRC No Detailed Affiliation Given, lipp 22195 342, 24X Fiche 50-000, 63/10/31, 8402090003

- --B402090192 Handwritten notes & calculations re const activities & fuel load date projection Related info encl NRC -- No Datailed Affiliation Given 78/09/26 5pp 22195 083 24% Fiche 50-000,83/10/31,8402090003
- --8402090199 "Midland Startup Sequence" Related info encl * Consumers Power Co 83/10/31 23pp 22195 ii3 : Fiche 50-000,83/10/31,8402090003
- B402020033 Partial response to FOIA request for documents re evaluation or review of design.comst.scheduling.cost & licensing of facilities from 1977 to present Forwards App A & B documents FELTON, J M Division of Rules and Records B3/11/0 Barris, Satt. Denn & Driker lipp 22079 208 24X Fiche 50-000,83/11/04.8402020033
- --7906200195 Submits Caseload Penel estimate of const completion date KARI,S M Office of Management and Program Analysis 79/05/11 HODD,D Light Water Reactors Branch 4 1p 22080 067 24X Fiche 50-000,83/11/04,840202003
- --BiOB110074 Informs of tentatively scheduled BiOB25 visit by Caseload Forecast Panel to facility Reconfirmation of fuel load estimate needed to develop NRC resource allocations, priority decisions & support findings necessary for CP extension TEDESCO.R L Assistant Director for Licensing 81/08/03 GISENNUT.D & Division of Licensing ip 22081 020 24X Fiche 50-000,83/11/04,8402020033
- --Bit2220708 Summary of Billi2 meeting w/util in Bethesda, MD rp const schedules far foundation mods to auxiliary bldg Attendes list & visugraphs encl HODD, D. Licensing Granch 4 Bi/li/23 Licensing Branch 4 Bpp 220Bi 110 24X Fiche, 50-000, 83/11/04, 8402020033
- --8402020038 "Project Cost & Schedule: Forecast 4 "
 # Bechtel Corp 77/12/31 136pp 22079 219 24X
 Fiche 50-000:83/11/04:8402020033
- --8402020041 Recommends followup to board notification, w/detailed plant-specific analysis of const schedule BDVD.R B Division of Project Management 78/03/08 BASSETT, H B Office of Management and Program Analysis HARTFIELD.R.A NRC -No Detailed Affiliation Given 1p 22079 358 24X Fiche 50-000,83/11/04.8402020033
- --B402020059 Agenda for 790618 meeting w/NRC to discuss facility const & licensing Related info encl
 * Consumers Power Co 79/06/18 Consumers Power Co 9pp 22080 068 24X Ficher 50-000, 83/11/04-8402020033
- ---8402020068 Agenda for 790918-20 Caseload Forecast Panel site visit Related info encl * Consumers Power Co 79/09/14 Consumers Power Co 57pp. 22080 122. 24X Fiche 50-000,83/11/04.8402020033
- --8402020070 Agenda for 800729 Caseload Forscast Panel site visit. Related info encl * Consumers Power Co. 80/07/25 Consumers Power Co. 145pp 22080 180 24X Fiche 50-000,83/11/04,8402020033.
- --8402020073 Forwards Project Schedule Change Notice 2 which finalizes Rev 11 dates under further study Related info encl RUTGERS.J. A Bechtel Corp. 81/07/15 COCK.J.W Consumers Power Go 37pp 22080 345 24X Fiche 50-000,83/11/04,8402020033.
- --8402020079 Agenda for 810825 meeting w/NRC Caseload Forecast Panel to conduct plant tour.Related info enc! * Consumers Power Co. 81/08/24 Consumers Power Co. 84pp 22081 026 24% Fiche 50-000.83/11/04.8402020033
- --B402020142 Handwritten notes w/attached calendar page re Midland hanger reinsp & pipe whip restraints * NRC No Detailed Affiliation Given 83/04/19 5pp. 22081 184 24X Fiche 50-000,83/11/04,8402020033
- --8402020145 Agenda for 830419-21 meetings w/NRC Caseload Forecast Panel * NRC No Detailed Affiliation 61ven 83/04/19 NRC No Detailed Affiliation 61ven 210pp. 22081 189 24X Fiche 50-000,83/11/04,8402020033.
- --B402020149 Computer printout entitled "Planning Schedule, Rev 12 " Praft itrs enci.

 * NRC - No Detailed Affiliation Given 83/04/20 55pp 22082 036 24X Fiche, 50-000,83/11/04,8402020033,

- --B402020199 Forwards Dow Chemical Co notice of termination & complaint for declaratory judgment due to util inability to mout commercial steam operation date Damages against util being tought PALAHEE, J B Consumers Power Co 83/07/15 KEPPLER, J G Region 3, Office of Director 31pp 22082 098 24X Fiche 30-000, 83/11/04,8402020033
- --8402020213 Discusses 830702 telcon re util request for followup meeting on facility const completion dates Util requested delayed meeting until essential related matters resolved Related info encl
 HODD, D Licensing Branch 4 83/07/08 ADENSAM, E G Licensing Branch 4 46pp 22082 136 24X Fiche 50-000.83/11/04.8402020033
- 8402060286 Further response to FOIA request for IE 800103 rept re review of matl false statement at facility & all associated & supporting records to rept Forwards documents listed in App C App B documents available in PDR FELTON, J M Division of Rules and Records 83/11/15 WINSLOW, R Hall Street Journal 3pp 22111 068 24X Fiche 50-329,83/11/13,8403060394
- --7904100117 Board notification Midland settlement problem Concurs w/ decision to inform OL Board of settlement of diesel generator bldg CP Board or Commission notification unnecessary VASSALLO, D B Assistant Director for Light Water Reactors 79/11/13 ENGELHARDT, TF Hearings Division ip 22111 073 24% Fiche 50-327,83/11/15,8402060286
- ~-7904100122 Board notification diesel generator foundations & bldg settlement at Midland, Recommends that ltr of notification be prepared which would apprise appropriate Boards & Commission of sub) matter
 OLMSTEAD.W J Hearing Branch 4 78/11/03 VASSALO, D B Assistant Director for Light Water Reactors 1p 22111 072 24X Fiche. 50-329, 83/11/15,8402060286
- --7910230946 Requests assistance to ensure that engineering branch positions re facilities soil settlement issues are documented & forwarded to applicant as soon as possible RUBENSTEIN.L B Light Water Reactors Branch 4 79/09/27 KNIOHT.J P Assistant Director for Engineering 2pp 22111 109 24X Fiche 50-329,83/11/15,8402040286
- 8402070028 FOIA request for records generated in connection w/TA Rehm B31117 ltr to BP Carde re Midland Caseload Forecast Pahel GARDE B F Covernment Accountability Project. 83/11/26 Office of Administration. 2pp 22142 248. 24X Fiche 50-329,83/11/26, B402070028
- 840227049; FDIA request for documents re 831025 meeting between util & NRC concerning mgt audit & associated 10CFR2 206 request GARDE.B.P. Government Accountability Project 83/11/26 Office of Administration 2pp 22414 250 24X Fiche 50-329, 83/11/26, 840227049;
- 8402100005 Partial response to FDIA request for documents prepared by OPc of Investigation re Zack Co Forwards App A documents Documents also being placed in PDR. Info partially withheld (ref FOIA Exemption 6)

 FELTON, J M Division of Rules and Records 83/11/28 PERRY, R A Affiliation Not Assigned 7pp 22206 002 24X

 Fiche: 50-000, 83/11/28, 8402100005.
- 8402070038 Responds to FOIA request for records generated in connection w/TA Rehm 831117 ltr to BP Garde re Midland Caseload Forecast Penel Forwards App A document Eight dreft documents listed in App B withheld (ref FOIA Exemption 5) FELTON, J.M. Division of Rules and Records 83/12/28 OARDE, D P Oovernment Accountability Project 3pp 22142 250 24X Fiche 50-329,83/12/28,8402070038
- 8312120136 Board Notification 84-011 discusses NRC use of terms "important to safety" & "safety-related" EISENHUT.D 0 Division of Licensing 84/01/18, PALLADING Commissioners 72pp 22241 008. 24X Fichs 50-000,84/01/18,8012120136.
- 8402030481 Forwards 8&W 840118 ltr notifying that personnel listed on 840105,09,11,12,13 lists cleared to perform status
 - absessment. QUAMME.D L Consumers Power Co 84/01/20 HIERZER.Q A. Bechtel Corp. 2pp 22066 016 24X Fiche.50-329,84/01/20,8402030481
- 8402020118 Forwards electrical FCR/field change notice register.W/o encl, REICHEL.N.I Consumers Power Co 84/01/23 Stone & Webster, Inc Ip 22056.224 24% Fiche 50-329.84/01/23.8402020118

- 8402020297 Informs that JE Karr assigned site program manager for StW const implementation overview program, effective 840112 AMDRUSD. A P Stone t Webster, Inc 84/01/23 QUAMME, D L Consumers Power Co 1p 22055 183 24X Fiche 50-329, 84/01/23, 840202097
- 8402030241 Submits response to SZW concern re high number of revs & time taken to process revs Proposed procedural rev request must be approved by initiator, supervisor, dept head & field const manager
 HIERZER, 9 A Bechtel Corp 84/01/23 GUAMME, D Cansumers Power Co 2pp 22067 205 24% Fiche 50-329, 84/01/23, 8402030241
- 8402040365 Forwards summary of remedial soils & const completion program third-party assessment 840112 meeting LUCKS A S. AMBRUSO A P. Stone & Mebster. Inc. 84/01/23 HARRISON.J J. Region 3, Office of Director 20pp 22086 128 24X Fiche 50-329,84/01/23.8402060365
- B401190012 Board Notification 84-013 forwards info re Transamerica Delaval, Inc emergency diesel generators EISENHUT. D 6 Division of Licensing 84/01/24 PALLADING, N Commissioners 10pp 22054 346 24X Fiche 50-000.84/01/24, B401190012
- B402020276 Informs that as result of 840124 partial release of Stop Work Order FSW-41 for instrumentation & control documents, Bechtol released for status assessment in Modules 340,102, 120,410 & 800 Documentation encl GAMME.D L Consumors Power Co B4/01/24 HIERZER, 0 A Bechtel Corp 17pp 22085 187 24X Fiche 50-329,84/01/24,8402020276
- 8402030171 Forwards signed affidavits & resumes for KJ Butler & GA Carter & resume for MO Dick Personnel assigned to const implementation overview staff at facilities KARR, J E Stone & Webster, Inc 84/01/24 HARRISON, J J NRC No Detailed Affiliation Olven 16pp 22069 008 24X Fiche 50-329,84/01/24,8402030191
- 8402030282 Forwards 840126 update of pre- & post-stop work order activities
 REICHEL,N I Consumers Power Co 84/01/24 Stone & Webster, Inc 3pp 22071 070 24% Fiche 50-329,84/01/24,8402030282
- 8402030291 Advises that sampling review of Phase I & II of field change requests/notices affecting instrumentation & control & civil documents completed KARR.J E Btone & Webster, Inc 84/01/24 QUANNE,D L Consumers Power Co Ip 28069 358 24% Fiche 50-329,84/01/24,8402030291
- 8402030296 Requests controlled distribution of index to Bechtel field procedures & instructions be sent to JJ Ridge KARR.J E Stone & Hebster, Inc. 84/01/25 REICHEL, N Consumers Power Co ip 82069 359 24X Fiche 50-329, 84/01/25, 8402030296
- 8402030213 Forwards list of Bechtel personnel trained to commence status assessment REICHEL,N I Consumers Power Co 84/01/26 Stone & Webster, Inc 2pp 22067, 328 24% Fiche 50-329, 84/01/26, 8402030213
- 8402030236 Forwards SMO CCP assignments.per W Sienkiewic: request REICHEL,N I Consumers Power Co 84/01/26 Stone & Webster, Inc 2pp 22067 176 24% Fiche 50-329.84/01/26.8402030236
- 8402030335 Discusses release for status assessment in constitution overview Hold Point Oil for electrical & MPGAD partial release of SMO 4) for electrical disciplines for Modules 340,102,120,410 & 600 GUAMME, D L Consumers Power Co 84/01/26 HIERZER, G A Bechtel Corp 8pp 22067 132 24X Fishe 50-329,84/01/26,8402030335
- B402060244 Forwards open Const Implementation Overview Item/Hold Point Notifications 047 & 049 for action KARR.J E Stone & Webster, Inc. B4/01/26 QUAMME.D L Consumers Power Co 5pp 22087 203 24X Fiche 50-329 84/01/26,8402060244
- B402060427 Requests that const implementation overview be placed on controlled distribution for index to Bechtel field procedures & instructions Distribution should be made to JJ Ridge GUAMME.D L. Consumers Power Co B4/01/26 HIERZER.G A Bechtel Corp ip 22083 160 24% Fiche 50-329, B4/01/26, B402060427
- 8401170015 Board Notification 84-018 provides info re failure experience of Transamerica Delaval emergency diesel generators in marine svc. E19ENHUT.D 0 Division of Licensing 84/01/27 PALLADING.N J Commissioners 383pp 22073 027 24X Fiche 50-000,84/01/27, 8401170015

- 32050058 Informs that const implementation overview activities dependent upon receipt of registers from document control, approval of time required for preparation of sample plans & assignment of personnel in response to 840120 ltr AARR. J E Stone & Webster, Inc. 84/01/27 GUAMME.D L Consumers Power Co. 1p. 22088 201 24X Fishe 50-329,84/01/27,8402050058
- 02060230 Forwards resume & affidavit for AJ Benecchi assigned to const implementation overview team KARRJE Stone & Webster, Inc. 84/01/27 HARRISON, J.J. Region 3. Office of Director 7pp. 22083-033 24X Fiche 50-329,84/01/27. 8402060230
- 02060369 Forwards project schedule bierarchy per G Dick request W/o encl
- 02040377 Forwards partial response to Observation 037.Rept 24 refailure to remove leftoyer scaffolding boards from work
- ea Consumers Power Co 84/01/27 Stone & Hebster, Inc 186 308 24x Fiche 50-329,84/01/27,8402060377
- 0203032& Authorizes listed remedial solls work activities for Feb 1984 Work activity list encl HARRISON, J J Region 3, Office of Director 84/01/30 QUAMME.D L Consumers Power Co 3pp 22049 072 24% Fiche 50-329,84/01/30,8402030326
- 8402030331 Requests authorization to proceed w/listed remedial soils GUANNE, D L Consumers Fower Co 84/01/26 HARRISON, J. J. Region 3. Office of Director ip 22059 075 24X Fiche 50-329.84/01/30. 8402030326
- 102060461 Forwards open Const Implementation Overview Item 050 re 0 & non-0 interfaces KARR.J E Stone & Webster, Inc B4/01/30 GUAMME.D L Consume Power Co 4pp 22083 100 24X Fiche 50-329,84/01/30,8402050461 Cansymers
- 102030370 Responds to request for partial release of seven mechanical documents to allow pneumatic test Const implementation overview attributes listed KARR.J E Stone & Webster, Inc. 84/01/30 QUAMME.D L Consumers Power Co. 1p. 22130 359 24% Fiche 50-327.84/01/30,8402080370
- 10213047; Forwards 840126 list of Bethtel personnel trained to commence status assessment JOHNSON, D. Consumers Power Co. 84/01/30 Stone & Webster, Inc. 2pp. 22202 048 24% Fiche, 50-329, 84/01/30, 8402130471
- 402050241 Forwards review of QC div personnel New Quality Action Request RT-00025 initiated for review of Soils Div & HVAC Assurance Branch insp personnel qualification & certification records W/o enci GUAMME.D L Consumers Fower Co 84/01/31 MARR.J E Stone & Webster, Inc 1p 22134 240 24X Fiche 50-329,84/01/31,8402060241
- 402080387 Forwards response to tracked recommendation Item 047 re monthly review of work print sys REICHEL,N I Consumers Power Co. 84/01/31 Stone & Wabster, Inc 4pp 22130 230 24% Fiche 50-327.84/01/31.8402080387.
- 102150140 Forwards const review of B&W CCP overview Item 047 re field work prints HIERZER, G A Bechtel Corp 84/01/31. QUAMME, D L Consume Co App 22249 287. 24% Fiche, 50-329, 84/01/31, 8402150140. Consumers Power
- 402280431 Forwards remedial soils work activity list for Feb 1984 & supplemental work activity list for Mar 1984, per ASLB 820430 order Authorizablon to proceed www.ner requested QUAMME, D.E. Consumers Power Co. 84/01/31 HARRISON, J. J. Region 3, Office of Director 12pp 22405 274 24X Fiche 50-529,84/01/31,8402280431.
- 402130459 Forwards response to tracked info Item 050 re G-interface policy statement * Consumers Power Co 84/02/01 Stone & Webster, Inc. Spp. 22202.053. 24% Fiche 50-327,84/02/01,8402130459
- 401190018 Board Notification 84-019 provides info re proceedings on Diffing soils remedial stop work order potential

 10CFR50 55(e) involving differential settlement of dissel
 pedestals & diesel hidg & crack monitoring
 NOVAK: T M. Assistant Director for Licensing 84/02/02

 BECHHOEFER.C., HARBOUR.J., COWAN.F. Atomic Safety and Licensing
 Board Panel 2pp. 22178 248 24X Fiche 50-327,84/02/02,8401190018

- --B402100232 Provides recommendation for notification of ASLB re new info relevant & matl to facility proceedings HARNICK,R F Region 3, Office of Director 84/01/25 EISENHUT,D Q Division of Licensing 3pp 2217B 250 24X Fich
- 8402130420 Forwards Const Implementation Overview Hold Point 015 re use of thermocouples & thermocouple extension wire KARR.J E Stone & Webster. Inc 84/02/02 QUAMME.D L Consume Fower Co 3pp 22201 272 24% Fiche 50-329.84/02/02.8402130420
- 8402130475 Forwards 840131 list of Bechtel personnel trained to commence status assessment

 * Consumers Power Co 84/02/02 Stone & Webster Engineering
 Corp 2pp 22201 172 24% Fichs 50-329,84/02/02,8402130475,
- B402130425 Forwards const implementation overview item/hold point notifications Item 051 re field procedures/receipt insp & Item 052 re Criterion XVIII site auditing KARR.J E Stone & Webster. Inc B4/02/03 QUAMME.D L. Consume Power Co 3pp 22201 297 24X Fiche 50-329.84/02/03,8402130425
- 8402150276 Forwards, for info, list of Bechtel personnel trained to conduct status assessment

 * Consumers Power Co 84/02/03 Stone & Web
 22249 360 24X Fiche 50-329,84/02/03,8402150276 Stone & Webster, Inc. 2pp
- B402090R55 Responds to NRC B40112 confirmatory order re util commitment at B31025 meeting to provide independent appreciael of Midland project Proposal for independent appraisal will be submitted by B4030/
 CDOK.J W Consumers Power Co B4/02/04 DEYDUNO,R C Director's Office, Office of Inspection and Enforcement App 22161 338 24X Fiche 30-329,84/02/04,8402090255
- 8402100188 Requests list of critical remedial soils work activities scheduled for reb & Mar 1984 HARRISON, J.J. Region 3, Office of Director 84/02/06. QUAMME, D. Consumers Power Co. 3pp. 22182 071 24X Fiche 50-329, 84/08/06. 8402100188
- 8402130466 Notifies that sampling insps of const training records performed Results satisfactory Personnel cleared to perform status assessment KARR-J E Brone & Webster, Inc 84/02/06 QUAMME.D L Consumers Power Go 1p 22202 037 24X Fichs 50-329.84/02/06.8402130466
- B402150224 Advises that no response received on Transmittals CSC-7201. dtd 840120 & CSC-7275.dtd 840202 Status of personnel lists requested
- 8402150248 Informs that results of const implementation overview sampling insps of personnel const training records satisfactory Personnel listed in encl cleared to perform status assessment. W/o encl
 KARR.J E Stone & Webster, Inc. 84/02/07 GUAMME.D L Consumers Power Co. 19 22250 260 24x Fiche 50-329,84/02/07,8402150248.
- 8402190339 Forwards mechanical field change request/field change notice (FGR/FGN) registers & FGR/FCNs w/applicable resolution shocks M/o encl shocks M/o encl REICHEL, N I Consumers Power Co 84/02/07 Stone & Webster, Inc ip 22242 397, 24% Fiche 50-329,84/02/07,8402150339
- 8402220384 Forwards 840207 listing of personnel cleared to perform Status assessment

 QUAMME D. L. Consumers Power Co. 84/02/07 HIERZER, Q.A. BeCorp. 2pp. 22334 129 24X Fichs 30-329, 84/02/07, 8402220384 Bechtel
- 8402150287 Forwards, for info.sys & area engineer assignments W/o encl * Consumers Power Co 84/02/09 Stone & Webster, Inc ip. 22242 341 24X Fiche 50-327,84/02/09,8402150287
- B402150330 Forwards QR Fotiades & E Kishner affidavits & resumes. KARR, J E. Stone & Webster, Inc. 84/02/09. HARRISON, J J Repi Office of Director. ip 22850 211. 24X Fichs. 50-329, 84/02/09, B402180320 Region 3:
- --B402180331 Affidavit of 9 Fotiades re new appointment as procurement QA engineer, responsible for conducting third-party const implementation overview FOTIADES, 9 Stone & Webster, Inc. 84/01/31 App. 22280,212 24X Fiche 50-329,84/02/09,8402180330
- --B402150338 Affidavit of E Kiehner re appointment as assistant of E singineer, responsible for conducting third-party const implementation overview KIEHNER, E Stone & Wabster, Inc 84/02/03 Spp 2R250.216 24% Fiche 50-329,84/02/09.8402150330

- 8402160458 Forwards "Balance-Of-Plant Class 1,2 & 3 Piping, Pips Supports & Valves," Vol IX, to seismic margin review.per B30204 ltr Lowest margin for pipe support is on DHR suction line & conservatively estimated to be 1 14 COOK.J. Consumers Power Co 84/02/09 DENTON, H Office of Nuclear Reactor Regulation, Director 3pp 22269 149 24X Fiche 50-329, 84/02/09, 8402160458
- ---B402160460 "Balance-Df-Plant Class 1,2 & 3 Piping, Pipe Supports & Valves." Vol IX to saismic margin review
 KIPP.T R. CAMPBELL,R D. SHEE, E J Structural Mechanics
 Associates SMA 13701 057003 V09 84/02/09 250pp 22269 153
 24X Fiche 50-329,84/02/09,8402160458
- 8402270494 Responds to FDIA request for documents re util mgt audit & associated 10GFR2 206 request Forwards App A documents App B documents withheld in entirety (ref FDIA Exemption 5) FELTON.J M Division of Rules and Record 84/02/09 GARDE.B P Government Accountability Project 6pp 22414 252 24X Fiche 50~329, 84/02/09,8402270494
- --83071803B3 Refers Govt Accountability Project (GAP) 830613 10CFR2 206 Itr/petition to IE Resolution will require close coordination among IE,NRR & Region III Draft itr to GAP 80Cl
 LIEBERMAN, J. Regional Operations & Enforcement Division 83/06/29. DEYDUNG,R C. Director's Office of Inspection and Enforcement DENTON,H R. Office of Nuclear Reactor Regulation, Director 7pp 22414 271 24X Fiche 50-327,84/02/09,8402270474
- --8308040572 Forwards branch input for inclusion in Div of Licensing response to Govt Accountability Project 830613 ltr re independent third-party review of soil settlement issues. LEAR.C. Structural & Geotechnical Engineering Branch B3/07/27 ABENSAM, E Licensing Branch 4 3pp 22414 278 24% Fiche 50-329.84/02/09.8402270494
- --B402270497 Draft outline, "Oovt Accountability Project 2 206 Petition -Request for Relief Factual Bases " Related info encl * NRC - No Detailed Affiliation Given 84/02/09 13pp. 22414-25B. 24X Fiche 50-329,84/02/09.8402270494
- E402140194 Discusses modified approach to design & const verification effort Approach would allow design verification to be bifurcated from const verification Design verification could be completed by Jul 1984

 LEVIN; H A TERA Corp 84/02/10 KEPPLER; J Q Region 3, Office of Director. E186NHUT, D Q, Division of Licensing, CCOK; J H, Consumers Power Co 5pp 22223 387 24X Fiche 50-329,84/02/10,8402140194
- 8401170037 Board Notification 84-032 provides add1 info on environ qualification. Submittal augments info in Board Notifications 84-004 & 84-007.
 EIBENHUT, D G. Division of Licensing 84/02/13 Atomic Safety and Licensing Board Panel 10pp 22314 204 24X Fiche 50-000, 84/02/13, 8401170057.
- 8402220515 Forwards 840210 list of Bechtel personnel trained to commence status assessment REICHEL, N. I. Consumers Power Co 84/02/13 Stone & Webster, Inc 3pp. 22334 050. 24% Fiche 50-329,84/02/13,8402220515
- 8402270379 Forwards complete response to Diservation 035.Rept 22, including RA Wells 840206 ltr, Bechtel Ltrs 8000-8985 & BCCC-8985 b 480117 ltr & GAR RA-00062.W/a sncl. REICHEL, N. I. Consumers Power to 84/02/14 8tons & Webster, Inc 1p 22391: 179, 24X Fiche 50-329,84/02/14,8402270379.
- B402280181 Requests authorization to proceed w/Work Authorization Procedure 102980185 re installation of vertical movement monitoring instruments in control tower wall GUAMME, D. L. Consumers Power Co. 84/02/14 HARRIBON, J. J. Region 3. Office of Director ip 22400 270 24x Fiche: 50-329, 84/02/14, 8400901814
- 8402220179 Forwards "Unit 2 Turbina Roll Milestone " NRC concurrence requested to pursus milestone Release of portions of required sys contained in modules not currently released, but required to support milestone requested GUARME, D. L. Consumers Power Co. 84/02/15 HARRISON, J. J. Region 3, Diffice of Director 2pp. 22334:312 24X Fiche 50-329,84/02/15,8402220179
- ---8402220185 "Unit 2 Turbine Roll Milestone " W/sight oversize drawings Aperture cards are available in FDR.

 W Consumers Power Co. 84/02/29. 17pp 22334 314 24X Fiche: 50-329, 84/02/15.8402220179.

- B402280429 Forwards 840131 memo re use of registers in conjunction w/status assessment 840131 memo re work prints converted to status assessment prints & 830407 IE insp rept W/o encls REICHEL.N I Carolina Power & Light Co 84/02/15 BROWN.D Stone & Webster. Inc ip 22404 288 24X Fiche 50-329.84/02/15, 8402280429
- B402280573 Forwards, for info, approved Rev 3 to Bechtel training matrix W/a entl * Consumers Pawer Co 84/02/15 Stone & Webster, Inc 1p 22406 298 24X Fiche 50-329, B4/02/15, B402280573
- B401170068 Board Notification 84-033 provides "Sys Interaction Program," task action plan for Unresolved Safety Issue A-17 Distribution list encl EISENSHYT. D 0 Division of Licensing 84/02/16 PALLADING Commissioners Spp 22482 091 24X Fiche 50-000:84/02/16,
- 8402240029 Forwards agendas for Independent Design & Const Verification 840229 & 0301 meetings to discuss open confirmed & resolved item status & civil/structural status respectively LEVIN.H A TERA Corp 84/02/21 KEPPLER,J 9 Region 3, Office of Director EISENHUT,D 9 Division of Licensing COOK,J W Consumers Power Co 7pp 22375 245 24X Fiche 50-327,84/02/21,8402240029
- 8402280618 Bummary of 820316-17 meetings w/util & Bechtel in Ann Arbor. MI ra audit preparations for proposed underpinning of svc water pump structure & review status of remedial plans Related documentation encl HODD.D Licensing Branch 4 84/02/22 Licensing Branch 4 50pp 22427 083 24X Fiche 50-327,84/02/22,8402280618
- F Security, medical, emergency & fire protection plans
- 8402220301 Revised emergency implementing procedures, including Rev 1 to App C. "Review & Rev of General Ofc Control Ctr/Emergency Operations Facility Emergency Implementing Procedure" & revised index M/840217 ltr # Consumers Power Co E4/01/10 10pp 22333 278 24X Fiche 50-000.84/01/10.8402220301.
- O Adjudicatory correspondence
- 8402010214 Forwards Binclair Contention 2 re amergency planning, Part 2 of NRC regulations (ref Section 2 714 re late intervention) & two recent ABLAB decisions re late intervention W/o encl PATON.W D. Hearing Sranch 2 84/01/25 BECKROW, D. Affiliation Not Assigned 1p. 22038 359 24X Fichs 50-329,84/01/25,8402010214
- B402010071 Forwards proposed second supplemental findings of fact & conclusions of law for partial initial decision of QA issues & cross-reference to previously filed proposed findings & responses to proposed findings an QA LAVER, R J Isham, Lincoln & Beals, LAVER, R J Consumers Power Co 84/01/27, COMAN.F F, MARBOUR, J., BECHHOEFER, C Atomic Safety and Licensing Board Panel. 1p. 22041 001 24% Fichs 50-329,84/01/27,8402010091
- ---B402010075 Forwards cross-reference to all util filed findings of fact & conclusions of law for partial initial decision on GA issues.

 LAUER, R. J. Isham, Lincoln & Beais. LAUER, R. J. Consumers Power Co. 84/01/27 Atomic Safety and Licensing Board Panel 44pp 22041-002 24X Fiche 50-329,84/01/27,8402010091
- --8402010098 Proposed second supplemental findings of fact & conclusions of law for partial initial decision on QA issues, Certificate of 8vc encl.

 **Consumers Power Co 84/01/27. 311pp 22041 046 24X Fiche 50-329.84/01/27,8402010091
- B402170036 Submits list of corrections to 840127 proposed secons supplemental findings of fact & conclusions of law for partial initial decision on GA issues. Certificate of Svc encl.

 LAUER.R.J. Isham, Lincoln & Beale LAUER.R.J. Consumers Power Co 84/02/10 BECHHOEFER.C., HARBOUR.J. COHAN.F.P. Atomic Safety and Licensing Board Panel App 22301.128 24X Ficher 50~329.84/02/10.8402170036

- 2210111 Order extending time until 840327 for Commission to act to avieu Director's Decisions DD-83-16 & DD-84-2 HILK:8 J Office of the Secretary of the Commission 84/02/17 Commissioners Ip 22317 241 24X Fiche 50-329,84/02/17, 102210111
- 2220369 Requests removal of HC Potter from syc list as atty for ow Chemical Co Related correspondence DITER.W C Fischer: Franklin: Ford: Simon & Hogg POTTER.W C Donsymmrs Power Co 84/02/17 Office of the Secretary of the Ommission 1p 22035 320 24X Fiche 50-329.84/02/17.8402220369
- General correspondence
- 2020125 Forwards resume & affidavit for JE Karr, site program manager or comet implementation overview program 18RUSD, A P Stone & Webster, Inc 84/01/19 HARRISON, J A Region , Office of Director App 22054 189 24X Fiche 50-329,84/01/19, 102020125
- 2010316 Responds to B31230 request to prevent radioactive matl Ischarge into Tittabawassee River because of synergistic Ffects between dioxin & radioactivity increasing incidence f concer Effects miniscule ENTON, H R Office of Nuclear Reactor Regulation, Director. A/01/20 OADLERS J Affiliation Not Assigned 3pp 22044 201 4X Fiche 50-329,84/01/20,8402010316
- A02010318 Requests cessation of radioactive matls discharge into Tittabawassee River Synergistic effect u/radioactivity increases cancer possibility GADLER, B J Affiliation Not Assigned 83/12/30 NRC No Betailed Affiliation Given 3pp 22046:204 24X Fiche 50-329,84/01/20,8402010316
- 2220567 Requests assistance in obtaining controlled FBAR set ARR, J E Stone & Webster, Inc 84/02/13 QVANME, D L Consumers ower Co ip 22333 049 24X Fiche 50-329,84/02/13,8402220567
- Inspection reports. IE Bulletine & correspondence
- 2060286 Further response to FOIA request for IE 800103 rept response of math false statement at facility & all associated supporting records to rept Forwards documents listed in pc C App B documents available in PDR.

 SLTON, J M Division of Rules and Records, 83/11/15 HINGLOH, R all Street Journal 3pp 22111*068 24X Fiche: 50-327, 83/11/15, 802060284
- 102060297 Forwards inap repts & licensee repts re settlement of diesel generator bldg for referral to licensing board KEPPLER.J. G. Region 3. Chicago. Office of the Director 79/04/20 THORNSURE.H D. Division of Reactor Construction Inspection 2pp 22111 074 24X Fiche 50-329.83/11/15,8402060286
- 02060303 "Presentation of Invextigation Findings of Settlement of Dissel Generator Bldg & Plant Area Fill " * Region 3, Chitage. Office of the Director. 79/02/23. 169p 22111 076. 24X Fiche 50-329,83/11/15,8402060286.
- G2040309 Forwards proposed ltr to util, draft notice of viglation & draft notice of proposed imposition of civil penalty. Penalty recommended only for matl false statement KEPPLER, 9 Region 3. Chicago. Office of the Director. 79/10/29 GDWER, 8 C Executive Officer for Operations Support 17pp 22111-092 24X Fiche 50-329,83/11/15,8402060286
- 270536 FOIA request for agency records & info generated in neection w/or as result of T Novak visit to Region III ofc discuss Ofc of Special Cases findings on facilities from pt 1982 Dec 1983 RDE.B.P Government Accountability Project 83/11/26. Off Administration 2pp 22414:156 24X Fiche:50-329,83/11/26.
- Office
- 270531 Responds to FOIA request for records re T Novak visit to gion JII ofc to discuss Dfc of Special Cases findings re cilities from Sept 1982 Dec 1983 No records subj to quest located
 LTON-J.M. Division of Rules and Records 84/01/12. GARDE: B.P. vernment Accountability Project 1p. 22414 155 24% the 50-329,84/01/12,8402270531.
- D2016B Forwards IE Audit Repts 50-329/84-01 to 50-330/84-01 on D104-06 Audit conducted to symbols upward bldg movements C should allow during underpinning of auxiliary bldg. RNICK, R.F. Region 3, Office of Director. B4/01/18 COOK, J Winsumers Power Co. 2pp 22057:183 24X Fiche. 50-329,84/01/18,02020168

- --8402020178 IE Audit Repts 50-329/84-01 & 50-330/84-01 on 840104 A Audit results upward bldg movement limits proposed by licensee unacceptable LANDSHAILR B. HARRISON, J. J. Region 3, Office of Director 84/01/17 58pp 22087 185 24X Fiche: 50-329,84/01/18-8474 Lieb
- B402020247 Forwards IE Imap Repts 50-327/63-26 & 50-330/83-27 Cn 831121-1231 No noncompliance noted MARNICK,R F Region 3, Office of Director 84/01/20 CDDX, J w Consumers Power Co 2pp 22055 314 24X Fiche 50-329.84/01/a 8402020247
- --8402020256 TE Insp Repts 50-329/83-26 & 50-330/83-27 on B31121-1231 No., noncompliance noted Major areas inspected headquarters personnel, document control stop work order, US Testing stop work & site tours
 BURGESS, B L , COOK, R J., HARRISON, J J Region 3, Office of Director B4/01/19 Spp 22055 316 24X Fiche 50-329, 24/01 2 B402020247
- B312120193 IE Info Notice B4-06, "Steam Binding of Auxiliary Feedwatz"
 Pumps " Svc list encl.
 JORDAN E L Bivision of Emergency Pregaredness & Engineering
 Response (Post B30103) B4/01/25 Consolidated Edison Co of New
 York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25, 8312(2055)
- 8402060416 Forwards response to IE Bulletin 79-02. "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Inspof 100X accessible pipe support expansion anchors installed before 800030 complete CODK.J W Consumers Power Co 84/01/31 KEPPLER,J Q Regist 3 Defice of Director. 6pp 22085 124 24X Fichs 50-329.84/01/JI 8402060416
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list and J JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000,84/02/03,8401192016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEYOUNGER C. Director's Office, Office of Inspection and Enforcement. 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 156 24X Fight. 50-000,84/02/03,8401190017
- 8402070125 Forwards IE Monthly Meeting Repts 50-387/84-0208C & 50-330/84-0208C on 640112 & weekly repts of independent assessment of underprinding.

 HARNICK.R F Region 3, Office of Director. 84/02/03 COOK.J & Consumers Power Co. 2pp 22095.252. 24X Fiche 50-327,84/02/03.8402070125
- ---8402070131 IE Monthly Meeting Repts 50-329/84-02080 & 50-330/84 02090 on 840112 Major areas discussed description & status of major underpinning & const implementation overview program. crack mapping & review of work packages OARDNER, R. N. HARRISON, J. J. Region 3, Office of Director 84/02/02, 8pp 22095-254 24X Fichs 50-329,84/02/03.8402070125
- 8402150380 Forwards responses to NRC 840104-04 audit questions documented in 840117 IE Insp Rept 84-01 re auxiliary bidg underpinning. W/33 oversize drawings. Aperture cards are available in PDR MODNEY. J. A. Consumers Power Co. 84/02/08 HARRISON, J. J. Region 3. Diffice of Director 183pp 22271: 180 24X Fiche: 50-329, 84/02/08 8402150380
- --8402150387 "Evaluation of Observed Cracks in Auxiliary Bldg at Elevation 685 Ft Control Tower Floor," CORLEY, W. G., DEBTERLE, R. G., MORGAN, B. J. Construction Tachnology Laboratories, B4/01/30 100pp 22R71:258 24X Fichs 50-329,84/02/08,8402150380
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Inspa of Fire Protection Bafe Shutdown Bys (100FR50, App R) " Svc list encl
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/13 Consolidated Edison Co of New
 York, Inc. 124pp. 22365 259 24X Fiche 50-000,84/02/13.8401190041
- B401190050 Board Notification 84-021 provides rapts of Transamerica Delayal, Inc inspa conducted from Mar 1979 to Oct 1983 EISENHUT, D. G. Division of Licensing 84/02/13 PALLADING Commissioners 5pp. 22314:001. 24X Fiche: 50-000, 84/02/13, 8401190050.
- 8401190039 IE Info Nutice 84-08, "iOCFR50 7, 'Employee Protection '"

 Byc list encl,
 JDRDAN, E.L. Division of Emergency Preparedness & Engintering
 Response (Post 830103) 84/02/14 Consulidate Edison Co of New
 York, Inc 115pp 22365,141, 24X Fiche, 50-000, 84/02/14, 8401190039

- 8401190045 IE Info Notice 83-63. Suppl i, "Potential Failures of Hestinghouse Type 5A-1 Differential Relays" Svc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366 142 24X Fiche 50-000, 84/02/15, 8401190045
- 8402270208 Forwards IE Insp Repts 50-327/84-03 & 50-330/84-03 on 840101-31 & notice of violation MANNICK, RF. Region 9, Office of Director 84/02/15 COOK, J W Consumers Power Co 2pp 22426 079 24X Fiche 50-329,84/02/15,
- --8402290214 Notice of violation from insp on 840101-31 MARNICK.R.F Region 3. Office of Director 84/02/15 ip 22426 081 24X Fichs 80-329.84/02/15,840229020
- --S402270221 IE Insp Repts 50-329/84-03 & 50-330/84-03 on 840101-31 Noncompliance noted failure to protect installed mechanical anubbers from physical damage during const QARDNER/R N., LANDSMAN, R B. BURGESB, E. Region 3, Dffice of Director. 84/02/15 7pp 22426-082 24X Fiche 50-329,84/02/15,8409290208 Director, 84/02/15 8402290208,
- 8402220424 Ack receipt of 840201 ltr providing further response to NRC notice of violation & proposed imposition of civil penalties sent w/830208 ltr & request for addl info. Request for extension granted in view of current stop work order WARNICK,R F Region 3, Office of Director 84/02/17 COCK,J W Consumers Power Co 2pp 22334:181 24X Fiche 50-329,84/02/17,86032000404
- 8401170062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches 8st Below Manufacturer Recommended Value " Svc list ancl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 114pp. 22366 024 24X Fiche 50-000.84/02/21,8401170062
- 8401170066 IE Info Notice 84-11, "Training Program Deficiencies " Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/24 Consolidated Edison Co. of New York, Inc. 115pp 22430:304 24X Fiche 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
- R. Periodic operating reports & related correspondence
- B402020033 Partial response to FOIA request for documents re evaluation or review of design const, scheduling cost & licensing of facilities from 1977 to present Forwards App A & B documents FELYON, J. M. Division of Rules and Records 83/11/0-Barris, Bott, Denn & Driker 11pp 22079, 208. 24X Fiche. 50-000, 83/11/04, 8402020033. ZACK, A M 83/11/04
- --8402020046 Forwards Feb project status repts.

 MARTINEX.P.A. Bechtel Corp. 78/03/15. COOKE.T C , KEELEY.9 S , NEWOEN, J.F. Bechtel Corp. 1p. 22080'004 24X

 Fiche 50-000.83/11/04.8402020033
- --8402020052 "Project Status, Feb 1978 " Related info encl. + Bechtel Corp. 78/02/28 61pp. 22080: 005 24X Fiche: 50-000, 83/11/04, 8402020033.
- ---8402020061 Forwards "Project Status Rept.Jul 1979."

 RUTGERS.J.A. Bechtel Corp. 79/09/07. KEELEY.G.S Consumers

 Power Co 1p 22080.077. 24X Fiche: 50-000.83/11/04.8402020033.
- --8402020064 "Project Status Rept. Jul 1979, " Related info enci. * Bechtel Corp. 79/07/31, 45pp 22080:078, 24X Fichs:50-000,83/11/04,8402020033
- 8402020161 Forwards 44th quarterly rept for Jan-Mar 1984, per ALAB-106 memorandum & order. CDDK.J.W. Consumers Power Co. 84/01/20, DEYDNO,R C Director's Office, Office of Inspection and Enforcement opp. 22056:143 24X Fichs. 50-329.84/01/20,8402020161.
- B402020272 Forwards weekly jobsite subcontract status rept for wk ending B40113 per R Bcallon request M/o enci.
 4 Consumers Power Co 84/01/23. Stone & Webster, Inc. 1p. 22055: 182. 24% Fiche: 50-327, 84/01/23, 8402020292

- 8402070125 Forwards IE Monthly Meeting Repts 50-329/84-0208C & 50-330/84-0208C on 840112 & weekly repts of independent assessment of underpinning MARNICK R F Region 3. Office of Director 84/02/03 COOK, J W Consumers Power Co 2pp 22095 252 24X Fiche 50-329,84/02/03, 2000001078
- --B402070140 Forwards "Independent Assessment of Underpinning Weekly Rept 63" for 831127-1203 Minutes of daily meeting held during wk between members of assessment team & site engineering const & GA personnel also encl LUCKS, A S Stone & Webster, Inc B3/12/08 COOK, R NRC ~ No Detailed Affiliation Given 13pp 22095 282 24X Fiche 50-329,84/02/03,8402070125
- --B402070144 Forwards "Independent Assessment of Underpinning Weekly Rept 64" for B31204-1210 Minutes of assessment team & site engineering, const & GA personnel meeting also encl LUCKS, A B Stone & Webster, Inc B3/12/12, CDOK, R NRC No Detailed Affiliation Given 16pp 22095 295 24X Fiche 50-329,84/02/03,8402070125
- -8402070148 Forwards "Independent Assessment of Underpinning Weekly Rept 55" for 831211-1217 Minutes of daily meetings held during wk between members of assessment team & site engineering, const & GA personnel also enc 1, LUCKB.A 8 Stone & Webster, Inc 83/12/28 CDOK,R NRC No Detailed Affiliation Given 14pp 22075 311 24X Fiche 50-327,84/02/03,8402070125
- --B402070155 Forwards "Independent Assessment of Underpinning Weekly Rept 64" for 831218-1224 Minutes of daily meeting held during wk between members of assessment team & site emergency, const & GA personnel also encl. LUCKB, A S Stone & Webster, Inc 83/12/28 CDDK, R NRC -- No Datailed Affiliation Glyen, 14pp 22095 325 24X Fiche 50-329,84/02/03,8402070125
- --B402070160 Forwards "Independent Assessment of Underginning Weekly Rept 67" for 831225-31 Minutes of daily meeting held during wk between membars of assessment team & site engineering.const & QA personnel also send LUCKS.A B Stone & Webster, Inc. 84/01/05 COOK.R NRC No Detailed Affiliation Given 12pp. 22075 337 24X Fire 30-329-84/02/05.8402070125 Fiche 50-329,84/02/03,8402070125
- --8402070165 Forwards "Const Implementation Overview Rept 25" for 831128-1202 Rept includes evaluations of const completion program activities matrices of observations nonconformance identification repts hold points & affidavits BARANOW, 8 W. Stone & Webster, Inc. 83/12/05 MEPPLER, J. G. Region 3, Office of Director 18pp. 22095,349, 24X Fiche 50-329,84/02/03,8402070125
- --B402070169 Forwards "Const Implementation Overview Rept 26" for 831205-09 Rept includes evaluations of const completion program activities matrices of observations, nonconformance identification repts & affidavits BARANOW, B W Btone & Webster, Inc. 83/12/13 KEPPLER, J Q Region 3. Office of Director. 13pp 22076:005 24X Fiche 50-329,84/02/03.8402070125.
- -8402070454 Forwards "Const Instrumentation Overview Weeklu Rept 27" for 1020/0454 Forwards "Const Instrumentation Userview Weekly Rep 831212-16 Rept includes summary of activities for wk & open items.nonconformance identification repts & hold points. BARRANOW, S. W. Stone & Webster. Inc. 83/12/21. KEPPLER. J & Region 3. Office of Director 18pp 22096.018 24X Fiche 50-329.84/02/03.8402070125
- 8402130343 Advises that util response to Meeting Note D on Page 2 of Weekly Rept 25 re overview of const completion program satisfactory.

 KARR. J.E. Stone & Webster, Inc. 84/02/03, GUAMME, D.L. Consumer.

 Power Co. 2pp. 22203 297. 24X Fiche 50-329,84/02/03,8402130343.
- 8402130429 Advises that response to Const Implementation Ovarview Itam 038 re check list procedures contained in Meeting Note D on Page 2 of Weekly Rept 25 acceptable. KARR.J E Stone & Webster. Inc 84/02/03 QUAMME.D L. Consumers Power Co. 4pp 22201 275. 24X Fiche.50-329,84/02/03,8402130429
- 8402100194 Forwards status rept for Jan 1984 W/o ancl WARNICK,R.F. Region 3, Office of Director 84/02/06 KEPPLER,J 9, Region 3, Office of Director, 19 22182,188, 24X Fichs.50-329,84/02/06.8402100194.
- --8402100199 Forwards status rept for Jan 1984 Major areas discussed include document control stop work orders & remedial soils work activities COOK, R J Ragion 3, Office of Director, 84/02/03, WARNICK, R F. Region 3, Office of Director 2pp 22182 187, 24X Fiche, 50-329, 84/02/04, 8402100194

- 2210271 Forwards "Midland Independent Design & Const Verification regram Monthly Status Rept 9 for Jan 1984"

 EVIN:H A TERA Corp 84/02/15 KEPPLER.J G Region 3, Office of trector EIECMUT.D 9 Division of Licensing COOK.J W Onsumers Power Co 3pp 22316 210 24X Fiche 50-327.84/02/15, 1402210271
- |402210274 "Independent Design & Const Verification Program Monthly Status Rept 9 for Jan 1984 "
 | DOUGHERTY, F A TERA Corp 84/02/15 64pp 22316 213 24X Fiche 50-329,84/02/15,8402210271
- Reportable occurrences: LERs & related correspondence

3

- 1214039B Requests add1 info re Part 21 rept dtd 83110B concerning mar ring follors in auxiliary foedwater pump fornished to actilities Info requested within 25 days 10TAPOUS.U Region 4. Office of Director 83/11/30 PATTY, D F lingham-Willamotte Co 1p 22221 250 24X Fiche 50-000, 83/11/30, 10TAPOUS.
- I402140422 Supplemental Part 21 rept we wear ring failure in auxiliary feedwater pumps.per 831130 request for addl info Woar rings will be replaced on returned units W/AISI 420 wrought matl List of pumps in similar sec w/same wear ring encl PATTY.D F Bingham-Willamette Co 83/12/20 Region 4. Office of Director 2pp 23221 251 24X Fiche 50-000,83/11/30,880340398 8402140398
- 12030286 Forwards listed nonconformance repts for info W/o encl. !EICHEL.N I Consumers Power Co 84/01/26 Stong & Webster, Inc. 1p 22069 356 R4X Fiche 50-329,84/01/26,8402030286
-)2030461 Forwards response to Nonconformance Identification Rept)07. Histing Becktel personnel trained to indicated Histiplines per W Bienklewicz request > Consumers Pugwer Co B4/01/26 Btone & Webster, Inc 4pp)2067 068 24X Fiche: 50~329,84/01/26.6402030461
-)2060296 Advises that const implementation overview completed for ilectrical field change requests/field change notices Bix liscrepant conditions noted in encl Nonconformance identification Rept 013. Corrective actions requested (ARR, J. E. Stone & Webster, Inc. 84/01/26 @UAMME, D.L. Consumer lower Co. 15pp. 22087 126 24% Fiche 50-329;84/01/26,8402060276

- 12040249 Forwards listed open const implementation overview lonconformance Identification Rept 014 for action/info ARR.J E. Stone & Wester, Inc 84/01/27, QUANNER, D. L. Consume lower Co. 25p 22088 141 24X Fiche: 50-329, 84/01/27, 8402040249 Consumers
- 12050371 Final deficiency rept re adequacy of sheer reinforcements at layer containment penetrations Initially reported on 810515, malyses of Major areas Concluded containment meets design DĎK, J W
- ts Consumers Power Co 84/01/27 KEPPLEA, J G Region 3 Director App 22086:276 24X Fiche 80-329,84/01/27, ODK, J W COnsumer Office of Director
- 2060372 Forwards closed-out GAR RT-00024 in response to lonconformance Identification Rept 013 M/o encl. Consumers Power Co B4/01/27. Btone & Webster, Inc. 19 2086 302 24x Fiche: 30-329, 84/01/27, 8402060372
- 2040397 Requests partial release of Phase II mechanical controlled ocuments & work prints allowing preumatic drop leak test obe performed on MSIVs to resolve problem w/pitting in acking areas & assure no leakage in turbine roll.

 Consumers Power Co 84/01/30 Stone & Wabster, Inc 3pp 2085 095. 24x Fiche: 50-330, 84/01/30, 8402060397
- 2040404 Interim deficiency rept re differential settlement between issel generator structure & diesel generator pedestal easign process under review Next rept by 840420 W/one versize drawing Aperture card is available in PDR DDK.J.W. Consumers Power Co. 84/01/30 KEPPLER.J.O Region 3. Ffice of Director 4pp 22083:082 24X Fiche: 50-329, 84/01/30, 402060454

- 8402070365 Part 21 rept re linear converter device w/possible generic defect Initially reported on 840116 Written notifications issued Customer responses should be received by 840331 Final rept will be submitted by 840430 DUDBON.J P Pacific Air Products Co 84/01/30 Director's Office Office of Inspection and Enforcement 2pp 22114 299 24) Fiche 50-280.84/01/30.8402070365
- --84020703/3 Part 21 rept re linear converter device w/possible generic defect Initially reported on 840116 Preliminary analysis indicates excessive wear of bress shaft guides Next rept will be submitted within 90 days Supporting info encl DOBSON JP Pacific Air Products Co. 84/01/17 POTAPOVS,U Repin 4, Office of Director 48pp. 22114 301 24X Fiche 30-000,84/01/30,8402070365
- 8402080237 Forwards Quality Action Request RT-00026 to provide tracking in MPGAD QUAIL sys per Nonconformance Identification Rept 014 # Consumers Power Co 84/01/31 Stone & Webster, Inc. 5pp 22134 235 24X Fiche 50-329,84/01/31,8402080237
- 84020B0324 Forwards rev to drawings listed in 840130 Ltrs CBC-7251 & SWMCP-023 Beated 840130 ltr re pitting in pack areas 8MdDr-023 wetnes the state of M3103 encl REICHEL,N I. Consumers Power Co 84/01/31 Stone & Webster, Inc 3pp 22131 221 24X Fiche: 50-329,84/01/31,8402080324
- 8402070361 Interim deficiency rept re small break/reactor coolant properation interaction. Final rept re coolant pump trip issue expected in Apr 1784 Next update expected by 840601 CODM.J W Consumers Power Co 84/02/01 KEPPLER,J G Region 3. Office of Director 3pp 22076:191. 24x Fiche 50-327,84/02/01.
- 8402070393 Requests that NRC investigate design reliability of emergency diesel generators supplied by Transamerica Delaval. Inc Engine problems have been experienced since delivery of first vessel in May 1981 Related info encl MOLINAL C Falcon Carriers, Inc 84/02/01 DENTON, H. R. (Nuclear Reactor Regulation, Director 63pp 22096 057 24) Fiche 50-000.84/02/01.8402070393 Detice of
- 8402220404 Forwards status info re amended 830712 response to Region III 830523 ltr.Extension for full compliance requested Delay due to error in manufacturer (TDI) inap procedures & current stop work orders COUK.J W Consumers Power Co. 84/02/01. KEPPLER, J. Q. Region 3, Office of Director 7pp 22337:001. 24X Fichs 50-329,84/02/01. Office of Director 8402220404
- 8402130473 Forwards Nonconformance Identification Repts 007 & 013 rereview of electrical field change repts & field change notices, respectively Two areas of noncommitance observed, per FID 2 400, Nev 3 & FFG-2 000, Rav 3 KARR, J E Stone & Webster, Inc. 984/02/02 QUAMME, D L. Consumers Power Co. 20pp ` 22201, 151 24x Fichs, 50-327, 84/02/02, 8402130473,
- 8402080227 Interim deficiency rept re design embedments in concrete using shear lugs located in tension rones. Embedment testing program almost completed Next rept will be submitted by 840224, CODK, J. W
 - GODK.J.W Consumers Power Co. 84/02/03, KEPPLER,J G. Region C Office of Director. 3pp 22130:079. 24X Fiche 50-329,84/02/03, 8402000227
- 8402180443 Forwards Nonconformance Identification Rept 013 re review of electrical field change repts & field change notices, Eight discrepancies found. discrepa... KARR, J.E., Ston iss found. Stone & Hebster, Inc. 84/02/03 GUAMME,D L. Consumers App 22202 035 24X Fiche.50-329,84/02/03,8402130463.
- 8402220504 Interim deficiency rapt re excessive voltage drop on auxiliary feedwater reversing valve actuator power cable Initially reported on 840106 Design celculation provides criteria for sixing cables.

 COOK, J. W. Consumers Power Co. 84/02/03. KEPPLER, J. Q. Region 3 Office of Director. Spp. 2234:074 24X Fiche 50-329,84/02/03.8402220504.
- B40215022B Forwards response to Tracked Info Item 049 re discrepan in document control methods All controlled distribution will be issued from field document control ctr. # Consumers Power Co. 84/02/06 Stone & Webster, Inc. 3pp. 22244:313 24X Fiche: 50-329,84/02/06;8402150828.
- 8402150296 Forwards signed response to Tracked Info Items 045 & 050 re G-interface comet work permits. * Consumers Power Co 84/02/06 Stone & Webster, Inc. 9pp. 22250.159 24X Fiche, 50-329, 84/02/06, 8402150296.

- B402150297 Forwards complete response to Tracked Info Item 041 re Transamerica Delawal Inc amergancy diesel generators * Consumers Power Co 84/02/07 Stone & Webster, Inc 3pp 22244 234. 24X Fiche 50-329.84/02/07.8402150299
- 8402150347 Forwards response to Tracked Action Item 048 re const implementation overview concerning inconsistency between spec requirements on spacing between anchor bolts of different diameters # Consumers Power Co 84/02/07 Stone & Webster, Inc 3pp 22250.105 24X Fiche 50-329.84/02/07.9402150347
- 8402150354 Considers revised response to Const Implementation Overview Item 036 re field change notice for Q-work satisfactory Item
 - Stone & Hebster, Inc 84/02/07 QUAMME.D L Consum 1p 22242:355 24X Fiche 50-329,84/02/07,8402150354
- 8402220522 Forwards Not Corrective Action Rept 70 re discrepancies in MOZZEONZE FORWARDS Mgt Corrective Action Rept /O re discrepancie electrical raceway & raceway supports Project Engineering will develop & implement plan to review cable tray support drawings for lack of specific design criteria & Consumers Power Co. 84/02/07 Btone & Webster, Inc. 3pp. 22333:275 24X Fiche 50-329.84/02/07.8402220522.
- 8402150322 Considers results of const implementation overview (CID) review of field change request/field change notice for mechanical discipline satisfactory CIO Hold Point 011 released in entirety KARR, J E Btone & Webster, Inc 84/02/08 QUAMME, D L. Consumer Power Co 7pp. 22250 196 24X Fiche 50-329,84/02/08,8402150322
- 8402220111 Forwards QA Audit Finding Repts MSA-83-25-13F, Rev 1, MSA-83-32-01F, MSA-93-32-01F, Rev 1, MSA-83-32-01U, MSA-83-35-01U, Rev 1, M01-19-3-11F, M01-19-3-10F, & MSA-83-39-05F W/o encls.

 # Consumers Power Co 84/02/06 Stone & Mebster, Inc 1p 22326-059 24X Fiche 50-329:84/02/08,8402220111
- 8402220199 Forwards partial response to Const Implementation Overview Weekly Rept 4. Development of commitment mpt sys currently in initiation stages & will be completed in 8 to 12 months. Project menpower requirements listed # Consumers Power Co 84/02/08 Stone & Webster, Inc 3pp. 22339.168 24X Fiche.50-329.84/02/08.8402220199
- 8402220507 Advises that as result of 840208 Stop Work Order FSW-41 for mechanical discipline documents Bechtel released for status assessment for Modules 340, 102, 120, 410 & 800 Fully trained parsonnel will conduct assessment.

 * Consumers Power Co. 84/02/08, HIERZER, O. A. Bechtel Corp 14pp. 22334, 060 24X Fiche. 50-329, 84/02/08, 8402220507
- 8402130355 Forwards const implementation overview Open Item 051.

 "Field Procurement/Receipt Insp" & Item 052, "Criterion

 KVIII Bite Auditing "

 KARR, J E Btone & Webster, Inc. B4/02/09, QUAMME, D. L Consumer

 Power Co. 3pp 22203.301, 24X Fiche 50-329,84/02/09,8402130355.
- 8402130366 Forwards corrected first sheet of Nonconformance Identification Rept 013, "Review of Electrical FCRs & FCNs/ Document Control." Document Control."

 KARR, J E Stane & Webster, Inc 84/02/09 GUAMME, D L. Consume:
 Power Co. 2pp. 22203-271. 24X Fiche. 50-329.84/02/09.8402130366
- 8402150316 Informs that Stop Work Order FSW 27 re G-list drawings & space released on 840208 Bechtel requested to formally advise B&W Const Co of release. Order encl. * Consumers Power Co 84/02/09 HIERER, 0 A Bechtel Corp 13pp. 22241: 298 24X Fiche: 50-329, 84/02/09, 8402150316
- 8402220012 Advises that encl Stop Work Order FSW 35 re G-listed work released effective 840209 Related Sechtel correspondence also encl. QUAPPE, D. L. Consumers Power Co. 84/02/09, HIERZER, O.A. Bech Corp. 12pp. 2238-237, 24X Fiche, 50-329, 84/02/09,8402220012.
- 8402220457 Requests that Zack Co be advised of 840209 release of Stop Hork Order FSW 33 re HVAG area problems Related info encl. QUAMME, b.L. Consumers Power Co 84/02/09 HIERZER, G.A. Bechtel Garp. 11pp. 22339:332 24X Fiche 50-329,84/02/09,8402200457.
- 8402150318 Forwards closed Const Implementation Overview Item/Hold Point Notifications 008,009,032,033 & 041 for action/info. KARR,J.E. Stone & Webster, Inc. 84/02/10, QUANME,D.L. Consumers Fower Co. 7pp. 22250.073 24X Fiche 30-327,84/02/10.8402150318
- B402220184 Forwards closed Const Implementation Overview Item/Hold Foint Notification Oil re phase II activities for action. KARR.J.E. Stone & Hebster, Inc 84/02/10, GUAMME, D.L. Consumers Power Co. 6pp. 22340:348 24X Fiche: 50-327,84/02/10,8402220184

- 8402220193 Interim Deficiency Rept 83-093 re inconsistencies for processing field changes for project design documents Program established & documented in field change request/ field change notice program Next rept by 840404 CDOK.J W Consumers Power Co 84/02/10 KEPPLER.J G Region 3. Office of Director Bpp 22340 336 24X Fiche 50-329,84/02/10, 8402220193
- 8402220202 Forwards complete response to Const Implementation Overview Hold Point 015 re thermocouples * Consumers Power Co 84/02/10 Stone & Hebster, Inc. 8pp 22339 179 24x Fiche 50-329,84/02/10.8402220202
- 8402220206 Forwards RC Sember 840209 notification of rescheduled 840215 exit meeting for Audit MCA-83-38, field change notice/request overview Meeting originally scheduled for 831202 * Consumers Power Co 84/02/10 8tone & Webster, Inc 2pp 22338 356 24X Fiche 50-329,84/02/10,8402220206
- 8401190053 Board Notification 84-020 forwards info re Transamerica Delaval. Inc emergency diesel generator problems Attendance list, meeting handouts & slides encl EISENHUT.D 9 Division of Licensing. 84/02/13 PALLADING Commissioners 102pp 22332 202 24X Fichs 50-000,84/02/13,8401190053
- 8401190055 Board Notification 84-023; provides supplemental info re nine stop work orders as result of design document GA/GC (saues before ASLB Field Stop Work Order (FSW) 38; re remedial soils work, fully lifted work, Polly lifted NOVAK.T M Assistant Director for Licensing 84/02/14 BECHHDEFER.C., HARBOUR, J., COWAN.F Atomic Safety and Licensing Board Panel 5pp 22277 068 24% Fiche 50-329,84/02/14,8401190055.
- --B402160469 Recommends Board notification to provide encl info re status NOZIOUADY NECOMMENS BOARD notification to provide encl info to at nine stop work orders as result of design control change problems relevant to facility OM/OL hearings WARNICK, R. F. Region 3, Office of Director 84/01/31 EIEENHUT, D. G. Division of Licensing 3pp 22277 073 24X Fiche 50-329, 84/02/14.8401190055
- 8402270015 Transmits listed audit findings repts & unresolved items W/o encis JOHNBON, D. Consumers Power Co. 84/02/14 Stone & Webster, Inc. 1p. 22387-360 24X Fiche 50-329,84/02/14,8402270015
- 8402270123 Forwards Nonconformance Identification Rept 012 re civil review Phase III field change request/field change notice const implementation overview of ofc drawings stations KARR, J. E. Stone & Webster, Inc. 84/02/14 GUAMME, D. L. Consumer-Power Co. 14pp 22387 308 24X Fiche. 50-329, 84/02/14, 8402270123
- 8402280364 Submits list of audit finding repts & unresolved items * Consumers Power Co 84/02/14. Stone & Hebster, Inc ip 22407 130 24% Fiche. 50-329, 84/02/14. 8402280364
- 8402220330 Part 21 rept re defective DBR & DBRV stendby diesel generator turbocharger thrust bearing lubrication Deficiency not corrected by sys mod New recommendation will be sent to not corrected by sys mod New recommendation will be sent to customers by 840330
 BOYER,R E. Transamerica Delaval, Inc. 84/02/15 Director's Office, Office of Inspection and Enforcement 5pp 22332 182, 24X Fiche 30-000, 84/02/15,8402220530.
- 8402270010 Forwards BCRE 19 per Landsman B40215 request. W/o encl. WELLB,R A Consumers Power Co 84/02/15. HARRISON, J J Region 3: Office of Director. 1p. 22387.361. 24X Fiche.50-329.84/02/15.
- 8402270315 Forwards closed const implementation overview hold point notification Items 045 & 038 re engineering documentation & mechanical systatus & completion.respectively.

 KARR.J.E. Stone & Webster, Inc. B4/02/15 QUAMME,D.L. Consumers Power Gp. 5pp. 22389 282 24X Fiche 50-329,84/02/15,8402270315. Consumers
- 8402270437 Forwards new index for const implementation overview procedures & instructions & Rev 3 to "Third-Party Cost Implementation Overview"

 XARR.J.E. Stone & Webster, Inc. 84/02/15 Stone & Webster, Inc. 10pp. 22390.172 24X Fiche 50-329.84/02/15.8402270437
- 6402260435 Forwards response to Nonconformance Identification Rept Oil Conflict noted in implementation of Symbol R for retired field change reviews & notices for controlled architectural drawings Consumers Power Co 84/02/15. Stone & Webe 403 027 24% Fiche.50-329,84/02/15,8402280435. Stone & Webster, Inc. 4pp 22403 029

- |402280577 Forwards Rev | to Audit Finding Rept MSA-83-19-11F Verification of separate temp sensor & switch required Drawings should be revised to reflect location of temp switch & sensor
- Tenr Consumers Power Co 84/02/15 Stone & Webster, Inc 272 24X Fiche 30-329,84/02/15,8402280577 JOHNSON, D 22404 272
- 3402270100 Forwards Const Completion Program Item 53 rs team organization.team work scope & working schedules KARR.JE Stone & Webster. Inc. 84/02/16 QUAMME.D L Consume Power Co 2pp 22391 275 24X Fiche 50-329.84/02/16,8402270100 Consumers
- 3402270452 Interim deficiency rept re high energy line break analysis pipe whip restraint designs Design drawings re requirement to postulate arbitrary intermediate breaks issued Next rept by 840320 CDBK.J W Consumers Power Co 84/02/20 KEPPLER.J Q Region 3. Dffice of Director 10pp 22387 333 24% Fiche 50-329.84/02/20.8402270452
- 8402280416 Forwards, for info. Audit Finding Repts MBA-83-19-18F, Rev 2, MBA-83-34-01F, MBA-83-34-02F, M01-603-3-03 & Unresolved Item M01-602-3-02 W/o encis REICHEL, N I Consumers Power Co 84/02/20 Stone & Webster, In 1p 22407 168 24X Fiche 50-327, B4/02/20, B402260416
 - Stone & Webster, Inc
- 8402280321 Forwards closed Nonconformance Identification Rept 011 re architectural review Phase III for into KARR.JE Stone & Hebster. Inc. 84/02/21 GUAMME.D L. Consumers Power Co. 3pp. 22399 101 24X Fichs 50-329,84/02/21,8402280321
- 8402280336 Forwards open const implementation overview/hold point notifications for Items 058-060 re annual const audits KARR.J E Stone & Webster, Inc. 84/02/21. @UAMME.D L Consume: Power Co. 6pp. 22399 086 24X Fiche 50-329.84/02/21,8402280334
- 8402280440 Forwards Nonconformance Identification Rept 018 re nonmanual training records KARR.J E Stone & Webster, Inc 84/02/21 GUAMME.D L Consume Power Co. 2pp 22407 169 24X Fiche 50-329.84/02/21,8402280440 Consumers
- 8402280581 Forwards upen Nonconformance Identification Repts 015.016 & 017 re site auditing
 KARR.J E Btone & Webster, Inc 84/02/21 QVAMME.D L Consumers
 Power Go 4pp 22406 294 24X Fiche 50-329,84/02/21,8402280581
- 8402280384 Forwards Const Implementation Overview Items 056 & 057 re training classes Review of impact of items on training & evaluation by first training class requested KARR.J E Stone & Webster. Inc. 84/02/21 GUANME.D L.. Consumer Power Co Spp. 22406 291 24% Fiche 50-329,84/02/21,8402280584
- 8402290213 Forwards list of Bechtel personnel trained to accomplish
- 8402270218 Forwards revised list of Bechtel personnel trained to accomplish status assessment Gross-trained personnel denoted
 - Stone & Webster, Inc. 3pp 22428 169
- B402290151 Advises that unresolved Items MBA-B3-7-02U & MBA-B3-39-02U & audit finding Repts MBA-B3-32-04F & M01-07-3-04F clased * Consumers Power Co B4/02/22 Stone & Webster, Inc ip 22426 362 24% Fiche 50-329.84/02/22,8402290151
- 8402290135 Forwards Rept 27 meeting note resolving arc strike issue.per 9CN 14001 to Spec C-304. "Field Fabrication.Repair & Enuction of Structural Steel & Metal." * Consumers Power Co. 84/02/22 Stone & Webster, Inc. 4pp 22428 142 24X Fiche: 50-327.84/02/22,8402290155
- 8402290282 Forwards partial response to Hold Point 001. Rept 5 re project plan for incorporation of redlines for large-bore pipe hangers Consumers Power Co 84/02/22 Stone & Webster, Inc 2pp. \$27:304 24x Fiche 50-329.84/02/22,8402290252
- 840227027B Forwards complete response to Tracked Action Item 053. W/o .. Cunsumers Pawer Ca 84/02/23 Stone & Web 126 301 24% Fiche, 50-329, 84/02/23, 8402290278 Stone & Webster, Inc. ip

22426 301

- DOCKET 50-331 DUANE ARNOLD ENERGY CENTER
- F Becurity, medical, emergency & fire protection plans
- B402130330 Comments on FEMA 831205 1tm & final evaluations of 811028 & BEOTZEB emergency preparedness exercises No major deficiencies identified PAPERIELLO,C J Region 3, Office of Director Derittencies igentified
 PAPERIELLO,C J Region 3, Office of Director 84/02/07 LIU,L,
 Iowa Electric Light & Power Co ip 22197 198 24X
 Fiche 50-331,84/02/07,8402130330
- --B402130335 "Evaluation of Implementation of State & Local Radiological Emergency Response Plans " Exercise conducted on 820728 * Federal Emergency Management Agency 82/07/28 11pp. 22197 176 24X Fiche 50-331,84/02/07.8402130330
- 8402130433 Ack receipt of 840112 ltr re changes to modified amended security plan Changes consistent w/provisions of 100FR50 54(p) & acceptable AXELSON, H L Region 3, Office of Director 84/02/07 LIU, L. Iowa Electric Light & Power Co 2pp 22202, 107 24X Fiche 50-331,84/02/07,8402130483
- 8402290423 Forwards Amend 93 to License DPR-49 & safety evaluation OZE/1942 Formards Amend 73 to literate DRC-47 & sarety availation Amend revises Tech Specs to incorporate administrative changes & adds spec to fire protection sys repts THABANI,M C Operating Reactors Branch 2 84/02/14 LIU.L Iowa Electric Light & Power Co. 3pp 22438 194 24X Fiche, 50-331,84/02/14,8402290423
- --8402290432 Amend 93 to License DPR-49, revising Tech Specs to incorporate administrative changes & add spec to fire protection mys rapets VASSALLO,D B 0 Operating Reactors Branch 2 84/02/14 12/22438 197 24X Fichs 50-331,84/02/14,8402290423 B4/02/14 12pp
- J Insurance & indemnity information
- 8402020281 Forwards Endorsements 60 & 4 to NELIA Policies NF-214 & N-30 respectively Endorsements 49 & 4 to MAELU Policies MF-72 & M-90 respectively also encl.

 SHEA.K H Newman & Holtzinger 84/01/26 SALTIMAN.J D Assistant Director for State & Licenses Relations. 5pp 22055 158 24X Fiche 50-331.84/01/26.8402020281
- P Operating license stage documents & correspondence
- 8312120027 Generic Ltr 83-37 to representatives of utils re voluntary survey of licensed operators Svc list encl EISENHUT; D G Division of Licensing 83/12/08 Commonwealth Edison Co 12pp 22353:006 24X Fiche 50-000.83/12/QB.8312120027
- 8402090408 Partial response to FDIA request for four categories of documents re NUREO-73/087 (NUREO-0800), "SRP for Review of BARS for Nuclear Plants." Review of remaining documents incomplete. Forwards App A documents of FBLTON.J. M Division of Rules and Records 83/12/30 MADDEN.T Kays. Scholer, Fierman. Hays & Hendler 4pp. 22193 003 24X Fiche 50-000,83/12/30,8402090408. MADDEN, T J
- --8402090485 Requests NRR position on Tach Spec interpretation of operable based on util denial of noncompliance involving operablity of Duane Arnold emergency sys Problem may apply to all BHRs w/o STS
 CHRISBOTINDS.N Region 3, Office of Director 82/10/15.
 WALKERR D Region 3, Office of Director 3pp. 22193.032 24X Fiche 50-000,83/12/30.8402090408.
- B402060479 Forwards BER rs TMI Action Item II K 3 22, "Automatic Bwitchover of RCIC Bys Suction," Item resolved VAB9ALLO.D.B Operating Reactors Branch 2 B4/01/19 LIU.L. Iowa Electric Light & Power Co. 2pp. 82092.322 24X Fiche 50-331.84/01/13.8402060479
- 8402130196 Forwards Amand 92 to License DPR-49 & safety evaluation. Amend revises min critical power ratio operating limits to support turbine control valve mod required to reduce turbine blade & wheel damage on high pressure turbine THADANI, M C. Operating Reactors Branch 2 84/01/23 LIU, L. Iowa Electric Light & Power Co 2pp 22216 306. 24% Fiche 50-331:84/01/23,8402130196.
- --8402130202 Amend 92 to License DPR-49, changing Tech Specs to revise min critical power ratio operating limits to support turbine control valve mod required to reduce turbine blade & wheel damage on high pressure turbine VASBALLO.D. B Operating Reactors Branch 2 84/01/23 4pp 28216 308. 24% Fithe 50-331.84/01/23.8402130196.

- --8402130205 Safety evaluation supporting Amend 92 to License DPR-49
 * Dffice of Nuclear Reactor Regulation, Director 94/01/23 2
 22216-312 24X Fiche 50-331,84/01/23,8402130196
- B402020340 Application to amend License DPR-49, revising Tech Specs re scram discharge vol surveillance tests, per IE Bulletins BQ-17 & BQ-14 MCQAUGHY, R W Iowa Electric Light & Power Co BA/01/26 DENTON, H D#Fice of Nuclear Reactor Regulation, Director 3pp 22055 026 24% Fiche 50-331,84/01/26,8402020340
- --B402020346 Proposed Tech Spec Section 4 3 A 2 d re scram discharge vol long-term mod & addl surveillance requirements
 * Iowa Electric Light & Power Co 84/01/31 2pp 22055 029
 24X Fiche 50-331:84/01/26,840200340
- 8402030405 Application to amend License DPR-49, revising ETS to delete study on effects of cooling tower exhaust on nearby wagstation Fee encl.

 MCGAUGHY.R M. Iowa Electric Light & Power Co. 84/01/26

 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 3pp
 22068 339 24X Fiche 50-331,84/01/26,8402030405
- --8402030410 Proposed Tech Spec 4 1-6 re environ surveillance & special studies. Into deleted + Iowa Electric Light & Power Co 84/01/31 1p. 22068 342. 24% Fiche: 30-331,84/01/26,8402030405.
- 8402030329 Application for amend to License DPR-49, incorporating Tech Specs re limiting condition for operations & surveillance requirements for accident monitoring instrumentation, per NUREG-0737 & Generic Ltt 83-36 HCGAUCHY, R W. Iowa Electric Light & Power Co 84/01/27 DENTON, H Office of Nuclear Reactor Regulation, Director 4pp 22069 130, 24X Fichs: 50-331, 84/01/27, 8402030329
- --8402030334 Proposed Tech Spacs re limiting condition for operations & surveillance requirements for accident monitoring instrumentation; per NUREO-0737 & Generic Ltr 83-36.

 * Towa Electric Light & Power Co 64/01/27 18pp 22069 134 24X Fiche: 50-331, 84/01/27, 8402030329.
- B402030379 Suppl to 830720 application to amend License DPR-49, ravising Tech Specs re RHR syc water sys. Evaluation of change re 10CFRS0. 92 encl.
 MCOAUGHY. R. H. Iowa Electric Light & Power Co 84/01/27. DENTON, H Office of Nuclear Reactor Regulation, Director 2pp 22066.055 24X Fiche: 50-331.84/01/27, 8402030379
- 8402030427 Suppl to 830720 application to amend License DPR-49, consisting of Rev 1 to Proposed Change RTB-152 re min required flowrate for RHR syc water sys.

 HCGAUDHY.R.H. Iowa Electric Light & Power Co. 84/01/27. DENTON Office of Nuclear Reactor Regulation. Director. 5pp 22066.004. 24x Fiche, 50-331, 84/01/27, 8402030427. DENTON, H
- 8402230023 Discusses review of util 831013 response to NUREG-0737, Item II. E. 4.2, 7, "Frimary Containment High Radiation to Close Vent & Purge Valves " Requirements met YABBALLO, D B, Operating Reactors Branch 2 84/01/30, LIU, L Iowa Electric Light & Power Co. 2pp 22379.356, 24X Fichs. 50-331,84/01/30,8402230023.
- B402070119 Responds to B31222 request for commitment to leak test containment purpe sys isolation valves at 6-month intervals & within 72 h after purpe sys usage. Testing will be performed at 3-month intervals MCGAUGHY, R.W. IOWA Electric Light & Power Co. 84/01/31 DENTON. H.R. Office of Nuclear Reactor Regulation, Director 2pp. 22100:197. 24X Fiche: 50-331,84/01/31,8402070119.
- 8402130545 Notification of 840215 meeting w/util in Bethesda.MD to discuss 840112 submittal re inservice testing program siscuss D4012 submittal re inservice testing program responding to NRC SER.
 THADANI.M.C Operating Reactors Branch 2, 94/02/02. VASBALLO,D.B Operating Reactors Branch 2, 19 2228 305 24X
 Fichs/30~331.84/02/02.8402150545
- 8402150212 Responds to Generic Ltr 83-41 re number of times emergency dissel generators subj to starts w/o prelubrication & warmup from 821201 to 831201. No fast cold start occurred WATMOOP FOR BELLEVI to BSIZEVI NO FAST COLD STATE CECUPIES during ref time period. HCGAUGHY, R. M. Iowa Electric Light & Power Co. 84/02/03, DENTON: H Office of Nuclear Reactor Regulation, Director. 1p 22244.137. 24X Fichs: 50-331, 84/02/03, 8402150212.

- B402150305 Confirms verbal discussion re 840315 scheduled submittal of offsite dose assessment manual (QDAM) Submittal of manual only remaining open item re radiological effluent Tech Soec submittaï Spec submittal
 MCOAUGHY,R W Iowa Electric Light & Power Co 84/02/07
 DENTON.H R Office of Nuclear Reactor Regulation, Director ip
 22250 207 24X Fiche 50-331,84/02/07,8402150305
- DENTON, H 22226 214
- 8402160337 Forwards analytical-summary info re stress analysis of critical valve parts for purge/vent valves & related info, per 840120 telcon No-load closure time of 1-4 s represents per B40120 telcon No-load closure time of 1-4 s represents range for closure of all valves MCGAUGHY.R W Iowa Electric Light & Power Co 84/02/10 DENTON-H R Office of Nuclear Reactor Regulation, Director 22269 015 24X Fiche 50-331,84/02/10,8402160337
- 8402290423 Forwards Amend 93 to License DPR-49 & sefety evaluation Amend revises Tech Specs to incorporate administrative changes & adds spec to fire protection sys repts THADANI.M C Operating Reactors Branch 2 84/02/14 LIU.L lower Electric Light & Power Co 3pp 22438 194 24X Fiche 50-331.84/02/14.8402290423
- --8402290432 Amend 93 to License DPR-49, revising Tech Specs to incorporate administrative changes & add spec to fire protection sys repts VASBALLO, D B Operating Reactors Branch 2 84/02/14 12pp 22438 197 24X Fiche 50-331,84/02/14,8402290423
- ---8402290439 8afety evaluation supporting Amend 93 to License DPR-49 * Office of Nuclear Reactor Regulation, Director 84/02/14. 2pp 22438.209 24X Ficher 50-331,84/02/14,8402290423
- G Inspection reports: IE Bulletins & correspondence
- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps," Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Poet 830103). 84/01/25 Consolidated Edison Co. of New York, Inc. 120pp. 22058:001 24X Fiche 50-000,84/01/25,8312120153
- B402020340 Application to amend License DPR-49, revising Tach Specs rescram discharge vol survaillance tests, per IE Bulletins
 60-17 & 80-14
 HCGAUGHYR.W Iowa Electric Light & Powar Co 84/01/26, DENTON, H
 Office of Nuclear Reactor Regulation, Director 3pg. 22055 026
 24X Fiche 30-331.84/01/26,8402020340
- 8401190016 IE Ineo Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Syc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03, Consolidated Edison Co. of New York, Inc. 119pp 22114 179 24X Fiche 30-000.84/02/03.8401190016
- B401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers" Svc list encl. DEYOUND: R C Director's Office of Inspection and Enforcement B4/02/03 Consolidated Edison Co of New York, Inc 102pp. 22177-156 24X Fiche: 50-000, B4/02/03, B401190017
- 8402150263 Forwards IE Insp Rept 50-331/84-01 on 840109-13. No noncompliance noted PAPERIELLO, C. J. Res noncompliance hazed
 PAPERIELLÜ,C.J. Region 3. Office of Director E
 Town Electric Light & Pawer Co 2pp. 22250 274
 Fiche: 50-331.84/02/03.8402150263. 84/02/03 LIU, L.
- --8402150268 IE Insp Rept 50-331/84-01 on 840109-13 No noncompliance noted Major meas inspected, organization & mgt control, qualifications & training, external exposure control & personnel dosimetry & exposure control & assessment MUETER.L.J., ROZAK.B., OREOER.L.R. Region 3, Office of Director 84/02/02. 7pp 22250.276, 24X Fiche: 50-331,84/02/03,8402150263
- B401170041 IE Info Notice 84-07, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Bys (10CFR50, App R) " Svc list encl. enci. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365:259, 24% Fiche.30-000.84/02/13.8401190041
- 8401190039 IE Info Notice 84-08, "10CFR50, 7, 'Employee Protection, " Svc list encl
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp, 22365-141. 24X Fiche-50-000,84/02/14,8401170039

- B401170045 IE Info Notice B3-63 Suppl i. "Potential Faslures of Westinghouse Type SA-1 Differential Relays " Svc list encl JCRDAN.E L. Division of Emergency Preparedness & Engineering Response (Past B30103) 84/02/15 Consolidated Edison Co of New York, Inc. 118pp 22366 142 24X Fiche. 50-000.84/02/15.8401170045
- 8402270265 Responds to IE Bulletin 80-03 re emergency svc water check valve insp Valves added to ASME Baction XI inservice test program No problems identified that would affect valve operability MCGAUGHY.R W Iowa Electric Light & Power Co 84/02/17. KEPPLER.J G Region 3. Office of Director 1p 22427 213 24X Fiche 50-331,84/02/17,8402270265
- 8401190062 [E Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl. JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000,84/02/21,8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies" Byc list encl JORDAN,E L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/02/24. Consolidated Edison Co of New York, Inc. 115pp 22430 304 24% Fiche 50-000.84/02/24,8401190066
- 3401190067 IE Info Notice 84-12, "Failure of Boft Seat Valve Seals "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Editon Co. of New
 York, Inc 120pp 22431 060 24X Fiche 50-000.84/02/27, 8401190067
- R Periodic operating reports & related correspondence
- 9402230125 "Gemiannus1 Effluent Release Rept. Jul-Dec 1983 " W/840210 ltr MINECK.D L lows Electric Light & Power Co 83/12/31 9pp 22361 024 24x Fiche: 50-331,83/12/31,8402230125.
- 8402270200 "Semiannual Rept, Radioactive Effluent Releases, Jul-Dec 1983 " W/840210 ltr MINECK. D L lows Electric Light & Power Co 83/12/31 KEPPLER, J Region 3, Office of Director 9pp 22384 343 24X Fiche: 50-331,83/12/31:8402270200
- |402220006 Monthly operating rept for Jan 1784 N/840215 ltr. | KEITH.W., MINECK.D L | Iowa Electric Light & Power Co | 84/01/31 | Sept | 22337 294 | 24X Fiche: 50-331,84/01/31,8402220006
- 8 Reportable occurrences, LERs & related correspondence
- 8402030244 LER 8J-U45/U3L-0 on 831230, containment atmosphere monitor 8 (RE-81038) Seciared inoperable due to imadequate process line flow Caused by moisture problems w/Magnebellt flow switch Heat tracing rerouted W/840127 It rack tracing rerouted W/840127 It rack to Power Co. 84/01/27 KEPPLERIJ C. Region 3. Office of Director. 2pp 22067, 207. 24X Fiche: 50-331,84/01/27,8402030244.
- 3402040230 Forwards summary of damper sys evaluation, per 840124 telcon notifying that MAG damper actuators potentially deficient in meeting purchase spec GA program not in effect at actuator manufacturers facility MCQAUOHY, R W I Towa Electric Light & Power Co 84/01/27 KEPPLER, J Ragion 3, Office of Director 5pp. 22088 136 24X Fiche 50-331,84/01/27,8402040250.
- "402070013 LER 84-005-00 on 840102.RHR/core spray fill pump motor tripped by circuit breaker thermal overload relay Caused by pressure below 40 psig having potential for air ingress. Tech Spec amend requested & Pill pump rebuilt.H/840201 ltr. KEITH.W.. MINECK.D L Towa Electric Light & Power Co. 84/02/01 3pp 22102 316. 24X Fiche 50-331,84/02/01,8402070013
- O2070015 LER 84-003-00 on \$40102.04.06 & 16.auto-initiations of control bidg ventilation syst isolation mode, occurred from main inlet air low temp. Caused by inadequate circulation Daxaged coils removad for repair W/840201 ltr HAHEL. 5.8 + MINECK, D L lows Electric Light & Power Co. 84/02/01 Gpp 22102:313 24% Fiche 50-331.84/02/01.8402070015
- ORO70300 LER 84-002-00. on 840103.HPC1 inboard steam supply isolation valve declared inoperable Caused by technician mistakenly installing jumper across relay contact Jumper removed allowing valve to open & return to svc W/840202 itr HARRIS/N S., MINECK,D L. Iowa Electric Light & Power Co. 84/02/02 KEPPLER,J G. Region 3, 04fice of Director 3pp 22095:013 24X Fiche 50-331,84/02/02.8402070300.

- 8402150127 LER 84-001-00 on 840107, feedwater recirculation valve B, failed open, decreasing feedwater flow to vessel Caused by error in performing surveillance test procedure Both valves repaired Test procedure revised W/840206 ltr HARRIS, M S, MIMECK, D L. Iowa Electric Light & Power Co 84/02/06 Spp 28247 271 24% Fichs 50-331,84/02/06,8402150127
- 8402140447 LER 84-004-00. on 840110 & 11. normal control bldg ventilation sys isolated due to low inlet air temp & both trains of makeup air standby filter units failed to initiate properly Causa unknown Investigation under way W/840209 ltr MILLER, W J : HAMEL. D B.; MINECK, D L Iowa Electric Light & Power Co 84/02/09 5pp 22227 104 24X Fithe 50-331.84/02/09.8402140447
- 8402280332 LER 84-008-00 on 840123 facility experienced reactor scram while in normal run mode Caused by power supply failure Reactor maintained in hot shutdown until reactor startup corrected MILLER.W J. HINECK, D L. Iowa Electric Light & Power Co 84/02/22 4pp 28397 047 24X Fichs 50-331.84/02/22.840280332
- 8402280470 LER 84-006-00 on 840126, discovered Hills McCanna actuators mfg w/o having acceptable GA program Cause not stated Engineering activities continuing Updated rept will be provided by 840515, W/840224 ltr MILLER, W. J., MINECK, D. L. Iowa Electric Light & Power Co. 84/02/24 3pp. 22405 271 R4X Fiche 50-331.84/02/24.8402280470
- B4022B0339 LER 84-007-00 on B40127, invalid Group III automatically initiated on hi-hi radiation alarm Gaused by spurious electrical signal High radiation cable being inspected for possible damage H/B40226 ltr
 HARRIH, M B, MINECK, D. L. Idwa Electric Light & Power Co. 84/02/26
 3pp 22399 092 24X Fiche 50-331,84/02/26,8402280339
- DDCKET 50-333 JAMEB A FITZPATRICK NUCLEAR POWER PLANT
 F Security, medical, emergency & fire protection plans
- 8402130234 Supple 830415 & 0824 responses to Generic Ltr 83-33 re Suppl 1 to NUREO-0737 Control room design review program plan will be submitted by 841026. Schedule for implementation of Rev 2 to Rag Guide 1 97 will be submitted by 841201 BAYNE-J P Power Authority of the State of New York 83/11/15. VASBALLO,D B Operating Reactors Branch 2. 3pp 22204 285, 24X Fiche 50-333.63/11/15.8402130234.
- 8402130498 Responds to FOIA request for SECYs 83-268,271,278,281,299, 305,306 & 307 Forwards SECY 83-271,83-278 & portions of five other SECYs as listed on App A Info partially withheld (ref Exemptions 5 & 7)
 FELTON, J. H. Division of Rules and Records 83/11/28 WE183,E R. Harmon & Weiss, App. 22237 220 24X Fichs: 50-000,83/11/28, 880313/348
 - 8402130533 Responds to 830708 telcon request Util prepared to support exercise of "Radiological Emergency Response Interim Plan for Implementing Compensating Measures for Rockland County," during wk of 630808 BAYNE, J. P. Power Authority of the State of New York 83/07/11 PETRONE; F. Faderal Emergency Management Agency. 1p. 22237, 339, 24% Fichs. 50-000, 83/11/28, 8402130498.
- 8402080396 Forwards IE Insp Rept 50-333/83-25 on 831030-1104 No violations noted.

 MARTIN T.T Division of Engineering & Technical Programs. 84/01/25 MCNETLL.C A Power Authority of the State of New York 2pp. 22131 110. 24% Fiche 50-333,84/01/25,8402080386
- --B4020B0393 IE Insp Rept 50-333/B3-25 on 831030-1104 No violations noted Major areas inspected; radiation protection program, including external & internal exposure controls, calibr & maint of radiation survey instruments & audit. HCBRIDE.M.H., BICEHOUSE.H., BHANBAKY.M. Region 1, Office of Director. B4/01/12 lipp. 22131:112 24X Fiche 50-333,84/01/25,8402080386
- 8402230436 Forwards exemption from requirements of App R to 10CFR50 48 re reactor bldg cresent area & stairwells Exemption granted. VABSALLO.D.8 Operating Reactors Branch R. 84/02/01. BAYNE, J.P. Power Authority of the State of New York. 3pp. 22376 040. 24X Fiche: 50-333,84/02/01.8402230436.
- ---8402230438 Exemption from requirement of App R to 10CFR30 4B re reactor bldg cresent area & stairwells.

 EIBENHUT, D Q Division of Licensing, 84/02/01 Power Authority of the State of New York. 21pp 22376.043 24X Fiche 50-333,84/02/01,8402230436.

- B402070372 Ack receipt of B30727 ltr informing NRC of status of augmented offgas treatment sys,per IE Health Physics Appraisal Rept 50-333/80-20 MARTIN,T I Division of Engineering & Technical Programs 84/02/02 MCNEILL, C A Power Authority of the State of New York 1p 22075 250 24X Fiche 50-333,84/02/02,8402070372
- --B402070394 Provides current status of augmented offgas treatment sys, per IE Health Physics Appraisal Rept 50-33780-20 Mode to correct deficiencies will be implemented during 1984 outages
 MCNEILL.C A Power Authority of the State of New York 83/09/27
 MARTIN.T T Division of Engineering & Technical Programs 1p 22095; 251 24X Fiche 50-333,84/02/02,8402070392
- J Insurance & indemnity information
- 8402090335 Forwards Endorsements 60 & 61 to MAELU Policy MF-77 & Endorsements 70 & 71 to NELIA Policy NF-208

 ODLDEN, M. P. Marsh & McLennan, Inc 84/01/30 SALTZMAN, J Assistant Director for State & Licensee Relations 5pp 22161 166 24X Fiche 50-000, 84/01/30, 8402090335
- P Operating license stage documents & correspondence
- 8402010013 Forwards exemption from certain requirements of 10CFR50 44 (c)(3)(ii) re combustible gas control Response to request for permanent exemption from 10CFR50 44(c)(3)(ii) based on BHR Gunners Group studies expected in near future VASBALLO.D B. Operating Reactors Branch 2. 83/12/30 BAYNE, J. P. Power Authority of the State of New York 2pp. 22048 158 24X Fiche 90-333,83/12/30.8402010013
- --8402010021 Examption from certain requirements of 10CFR50 44(c)(3)(ii) re combustible gas control EISENHUT,D 0, Division of Licensing 83/12/30 Power Authority of the State of New York 4pp. 22048 160 24X Fichm 30-333,83/12/30,8402010013
- 84020&0474 Forwards request for add1 info re demonstration of containment purgs & vent valve operability. Until operability demonstrated valves must be sealed closed VABBALLD.D B Operating Reactors Branch 2 84/01/13 BAYNE, J P Power Authority of the State of New York 9pp. 22092 089 24X Fiche 50-333,84/01/13,8402040474
- B40207018B Forwards response to draft technical evaluation rept re control of heavy loads, per B21007 telcon BAYNE, J. P. Power Authority of the State of New York B4/01/31 VABSALLO, D. B. Operating Reactors Branch 2. 6pp. 22103.052 24X Fiche 80-333.84/01/31.8402070158
- 8402080415 Clarifies NUREG-0737, Item II E 4 i re dedicated hydrogen penetrations Flant design incorporates containment atmosphere dilution sys to control gases following DBE BAYNE, J. P. Power Authority of the State of New York 84/02/03, VASBALLO, D E Operating Reactors Branch 2, 2pp 22130.228, 24X Fiche. 50-333,84/02/03,8402080415.
- B4022100B3 Forwards request for add1 info on Tech Spec changes re inservice surveillance of safety-related hydraulic & mechanical snubbers Response requested within 30 days of receipt of ltr. VASBALLO.D.B. Operating Reactors Brench 2 84/02/03 BAYNE, J. P Power Authority of the State of New York 2pp 22323 274 24X Ficher 50-333, 84/02/03, 8402210083
- B402130184 Forwards analysis performed by Structural Integrity Assoc to determine impact of induction heating stress improvement on welds. Intergranular stress corrosion cracking indications will be evaluated for impact on piping structural integrity. BAYNE, J. P. Power Authority of the Btate of New York B4/02/09 VASSALLO, D. B. Operating Reactors Branch 2. 21pp. 22249; 103 24% Fichs: 50-333, 84/02/09, 8402150184
- 8402210107 Informs that util considers NUREG-0737, Itemv II K. 3.30 & 31 closed, as result of NRC 831213 acceptance of QE small break LOCA models.

 BAYNE, J. P. Power Authority of the State of New York 84/02/14 VABBALLO, D. B. Operating Reactors Branch 2. 2pp 22317 239, 24X Fiche-150-333, 84/02/14, 8402210107.
- B402240094 Forwards response to NRC B30511 request for add1 info re NUREO-0737. Item II K. 3. 28. "Qualification of Automatic Depressurization Bys (ADB) Accumulators " Util will replace ADB check valves wiqualified valves by B30629.
 BAYNE, J. P. Power Authority of the State of New York, B4/02/17 VABSALLO, D. B. Operating Reactors Branch 2. 7pp. 22373:289 24X Fiche. 50-333,84/02/17,8402240094

- 8402270327 Responds to util 831213 withdrawal of 830330 application for amend to Tech Specs & request for fee-refund Refund of fee inappropriate since safety evaluation prepared prior to withdrawal DIGOS,R M License Fee Management Branch 84/0R/17 BAYNE, J.P. Power Authority of the State of New York. 1p 22437 323 24X Fiche 50-333,84/02/17.8402290327
- @ Inspection reports, IE Bulletine & correspondence
- ## 8402020251 Forwards IE Insp Rept 50-333/B3-28 on 831107-1204 & notice of violation
 ## 8TAROBTECKI.R Division of Project & Resident Programs ## 84/01/17
 ## MCNEILL.C A Power Authority of the State of New York | 2pp | 22055 321 | 24% Fiche 50-333,84/01/17,8402020251
- --8402020253 Notice of violation from insp on 831107-1204 * Region 1, Office of Director 84/01/17 ip 22055 323 24X Fiche 50-333,84/01/17.8402020251
- --B402020260 IE Insp Rept 50-333/83-2B on B31107-1204 Violation noted failure to perform written safety evaluation re replacement of motor actuator of different design & rating DDERFLEINL T. Region 1, Office of Director COLLING, B J Division of Project & Resident Programs 84/01/13 lépp 22055 324 24X Fiche 50-333,84/01/17.8402020251
- B402030247 Responds to IE Bulletin B3-08 we GE AK-2 electrical circuit breakers w/undervoltage trip feature in use in safety-related applications other than reactor trip sys No breakers w/feature installed since original rept MCNEILL CA Power Authority of the State of New York 84/01/17 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 22067 215 24X Fichs 50-333.84/01/17,8402030247
- 8402070213 Forwards IE Insp Rept 50-333/83-29 on 831205-31 No violations noted STAROBTECKI.R Division of Project & Resident Programs 84/01/23 MCNEILL.C A Power Authority of the State of New York 2pp 22101 174 24X Fiche 50-333,84/01/23,8402070213
- --B402070221 IE Insp Rept 50-333/83-29 on 831205-31 No violations noted Major areas inspected licenses action on previous insp findings.LER review operational safety verification. survaillance observations & maint observations DOERFLEINL T Region 1. Office of Director COLLING.B J. Division of Project & Resident Programs 84/01/20 App 22101 176 24X Fiche 50-333.84/01/23.8402070213
- #312120153 IE Info Notice 84-04, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edizon Co of New York, Inc. 120pp 22058 001 24X Fichs 50-000, #4/01/25, #312120153
- 8402080386 Forwards IE Insp Rept 50-333/83-25 on 831030-1104 No violations noted MARTIN.T Division of Engineering & Technical Programs 84/01/25 MCNEILL,C A. Power Authority of the State of New York 2pp 22131*110 24X Fiche*50-333.84/01/25,8402080386
- --8402080393 IE Insp Rept 50-333/83-25 on 831030-1104.No violations noted Major areas inspected radiation protection program, including external & internal exposure controls, calibr & maint of radiation survey instruments & audit.

 HORRIDE, M H , BICHHOUSE, H , SHANBAKY, M Region 1, Office of Director. 84/01/12 11pp 22131-112 24X Fiche 50-333,84/01/25,8402080386
- 8402230353 Forwards safety evaluation re util requests for relief from ABME, Section XI inservice insp requirements Relief granted in part. & denied in part. VABBALLO, D B Operating Reactors Branch 2 84/01/31 BAYNE, J P Power Authority of the State of New York, 3pp. 22376 252 24X Fiche: 50-333,84/01/31,8402230353.
- --8402230359 Safety evalution supporting in part.& denying in part, request for relief from inservice insp requirements of Section XI of ASME Code & Office of Nuclear Reactor Regulation, Director, 84/01/31 17pp. 22376-255, 24X Fiche.50-333.84/01/31.8402230353
- B40B070392 Ack receipt of B30927 ltr informing NRC of status of augmented offgas treatment sys.per IE Health Physics Appraisel Rept 50-333/80-20 MARTIN:T T Division of Engineering & Technical Programs B4/02/02 MCNEILL,C.A Power Authority of the State of New York ip. 22095:250. 24X Fiche: 50-333.84/02/02,8402070392.

- --8402070394 Provides current status of augmented offgas treatment sysper IE Health Physics Appraisal Rept 50-333/80-20 Mods to correct deficiencies will be implemented during 1984 89/09/27
 - outages
 MCMEILL, C A Power Authority of the State of New York
 MARTIN, T T Division of Engineering & Technical Programs
 22095 251 24X Fiche 50-333,84/02/02,8402070392
- 8402130441 Ack receipt of 831110 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/82-24
 MARTIN.T T Division of Engineering & Technical Programs 84/02/0
 MCNELL.C A Power Authority of the State of New York 2pp 22202 061 24X Fiche 50-333.84/02/02.8402130441 84/02/02
- --BA02130445 Responds to NRC 830101 ltr re violations noted in IE Insp Rept 50-333/82-24 Corrective actions insp items re issuance of revised nuclear administrative policies & archival records vault/tretention rescheduled BAYNEJ P Power Authority of the State of New York B3/11/10 MMREFYTE Region 1. Office of Director 3pp 22202 063 24X Fiche 50-333, 84/02/02, 8402130441
- 8401190016 IE Inco Notice 84-07, "Design-Basis Threat & Review of 101190016 JE Info Notice 84-07. "Weign-basis inteat & Review or Vehicular Exces Controls "Sve list encl.
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Int 1199p 22114 177 24X Fiche-50-000,84/02/03.8401170016
- 3401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent 401190017 IE Bulletin 84-01, "Gracks in own new a social and Headers " Byc list encl
 DEYQUNO,R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc
 102pp 22177 156 24X Fiche 50-000,84/02/03,8401190017
- 8402210083 Forwards request for addl info on Tech Spec changes re inservice surveillance of safety-related hydraulic & mechanical snubbers Response requested within 30 days of receipt of itr VASSALLO.D B Operating Reactors Branch 2 84/02/03 BAYNE, J P Power Authority of the State of New York 2pp 22323 294 24X Fiche 50-333.84/02/03.8402210083
- 8402130059 Act receipt of 840125 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/83-27 STAROSTECKI,R Division of Project & Resident Programs. 84/02/06 FITZPATRICK.J Power Authority of the State of New York 2pp 22199 280 24X Fiche 50-333.84/02/06.8402130059.
 - 402130065 Responds to NRC B31217 itr re violations noted in IE Insp Rept 50-333/B3-27, Corrective actions individual involved counseled on need for care in researching & reporting info counseled on need for care in researching when the potential LERS.

 MCMEILL, CA Power Authority of the State of New York

 BTAROSTECKI, R Division of Project & Resident Programs
 22199 282 24X Fiche 50-333,84/02/06,8402130039
- 1402160336 Forwards inservice insp rept Vols 1 & 2 for June-Aug 1983 Rapt describes insps performed on pipe supports & weld & other pressure retaining component exams, per Rev 1 to NUREG-0313 & IE Bulletin 83-02 BAYNE.J P Power Authority of the State of New York 84/02/07 VASSALLO,D 8 Operating Reactors Branch 2 2pp. 22277,119 24X Fichs 50-333,84/02/07,8402160336.
- -8402160358 Inservice insp rept.Vols 1 & 2, for June-Aug 1983 Rept describes insps performed on pipe supports & weld & other pressure retaining component exams & susceptible stainless steel piping.per Rev 1 to NUREO-0313 & IE Bulletin 83-02. * Ebasco Services, Inc. (subs. of Enserch Corp.) 83/12/15 1,100pp 22277 121 24X Fiche 50-333,84/02/07,8402160336
- 401190041 IE Info Notice 84~09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (100FR50, App R)." Syc list and JORDAN, E.L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York: Inc. 124pp 22365 259 24X Fiche 50-000,84/02/13,8401190041
- 01190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection'" 01190037 IE INFO NATION OF Emergency Preparedness & Engineering JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/14 Consolidated Edison Co. of New York, Inc. 115pp 22365 141 24X Fiche: 50-000,84/02/14,8401170039
- 01190045 IE Info Notice 83-63. Suppl 1, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/15 Consolidated Edison Co of New York, Inc. 118pp 22366 142 24X Fiche 80-000,84/02/15,8401190045

- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list ancl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000,84/02/21,8401190062
- 8401170066 IE Info Notice 84-11, "Training Program Deficiencies '
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
 Svc list enc!
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060 24X Fiche 50-000,84/02/27,8401190067
- R Periodic operating reports & related correspondence
- 8402100258 Monthly operating rept for Jan 1984 W/840207 ltr COOK, J., MCNEILL, C.A. Power Authority of the State of New York 84/01/31 10pp 22178 002 24X Fiche 50-333,84/01/31,8402100258
- 9 Reportable occurrences LERs & related correspondence
- 8402020327 LER 83-065/03L-0 on 831216, while conducting surveillance (O202327 LEM 93-085/031-0 on 931216, unite conducting sur-testing of main steam line radiation monitors, setpoint of monitor 17-RM-251C found less conservative than Tech Spec Caused by instrument drift. Setpoint adjusted W/940113 ltr MCNEILL.C A Power Authority of the State of New York MURLEY, T E Region 1, Office of Director 2pp 22055 of Fiche 50-333,84/01/13,8402020327 B4/01/13 22055 093
- 8402020234 LER B3-067/03L-0 on B3122B, while conducting surveillance testing on RCIC turbine steam line high flow switch 13-DF1B-B4, setpoint found less conservative than required Caused by instrument drift Setpoint corrected W/840123 1tr KEITH.H N . MCNEILL.C A. Power Authority of the Btate of New York B4/01/23 MRLEY.T E. Region 1, Office of Director 2pp R2057 038 24X Fiche 50-033,84/01/23,8402020234
- 8402220405 LER 84-001-01 on 840118. RHR svc water pump C failed On 840130, after repairs, pump began to vibrate excessively Caused by impeller becoming disconnected from shaft due to worn collet W/840216 ltr LISEND, R. MCNEILL, C.A. Power Authority of the State of New York 84/02/16 3pp 22336 336 24X Fiche 50-333,84/02/16,8402220405
- 8402290255 LER 84-002-00 on 840130, emergency svc water breaker 8 tripped Caused by incorrect settings due to test equipment being out of calibr. Pump & breaker trip devices adjusted & pump returned to svc W/840223 itr LISENO, R T . MONEILLIC A Power Authority of the State of New York 84/02/23 3pp 22427 244 24% Fiche 30-333,84/02/23,8402290255

V Operator Examinations

- B402130258 Forwards updated schedule for NRC visits to conduct operator licensing exams for period ending 851231, per Generic Ltr 83-01 BAYNE, J P Power Authority of the State of New York B4/02/ VASSALLG, D. B. Operating Reactors Branch 2 3pp 22204, 069 Fiche 50-333,84/02/07,8402130268
- DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 8402030274 Responds to 830429.0627 & 1130 ltrs re physical security, contingency & training & qualification plan revs Portions unacceptable 8adeguards indo withheld (ref 100FR73 21) MARTIN.T.T. Division of Engineering & Technical Programs, 84/01/26. CAREY, J. J. Duquesna Light Co. 4pp 22087/334 24X Fiche 50-534.84/01/26.8402030274
- 8402240253 Advises that NRC will not review emergency plans to delete euzzquanu novises that NRC will not review emergency plans to del privacy or proprietary info unless specifically requested by licensee.per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR. TAM.P B Operating Reactors Branch 1 84/02/14 CAREY.J J. Duquesne Light Co. 3pp 22381 274 24X Fiche: 50-334, 84/02/14, 8402240253

- P. Operating license stage documents & correspondence
- 8402010194 Forwards exemption from 10CFR50 44(c)(3)(iii) re RCS high point vents, per NUREO-0737, "Clarification of TMI Action Plan Requirements," in response to 830825 request VAROA.S.A. Operating Reactors Branch i 84/01/12 CAREY, J Duquesne Light Co 7pp 22047 341 24X Ficher 50-334, 84/01/12, 8402010164
- --8402010178 Examption from 10CFR50 44(c)(3)(111) requirements re RCS high point vents E18ENHUT, D o Division of Licensing 84/01/12 Duquesne Light Co 4pp 22047 348 24X Fiche 50-334/84/01/12,8402010174
- 9402030125 Notification of 840301 meeting w/util in Bethesda, MD to discuss technical issues re reactor core exit thermocouples (TMI Item II F.2) TAM.F.S Operating Reactors Branch 1 84/01/25 VARGA, S A Operating Reactors Branch 1 2pp 22090 275 24X Fiche 50-334,84/01/25,8402030125
- 8402010410 Generic Ltr B4-04 to all operating PWR licenses, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Svc list encl ETSENHUT.D.G. Division of Licensing. 84/02/01 Consolidated Edison Co. of New York, Inc. 59pp 22177 087 24X Fiche 50-000,84/02/01,8402010410
- 8402100180 Responds to 831216 request for add1 info re proposed inadequate core cooling (ICC) instrumentation, per TMI Item II F.2. Meeting scheduled for 840301 in Bethesdaw MD to discuss technical issues re ICC instrumentation CAREY. J. J. Duquesne Light Co 84/02/03 VARQA: S A Operating Reactors Branch 1 1p. 22182-183. 24X Fiche 50-334,84/02/03.8402100180.
- B402160569 Responds to 831103 request for approval to eliminate radiological & nonradiological ETS Request may be resubmitted. For nonradiological ETS, by referencing 1983 soil sampling & aerial photographic results VARQA: E.A. Operating Reactors Branch 1. 84/02/07 CAREY, J. J. Duquesna Light Co. 4pp. 22302 126 24X Fiche. 50-334, 84/02/07, 8402160569.
- 8402160573 Notification of 840405 meeting w/util in Bethesda, MD to discuss outstanding environ qualification of electrical equipment issues.

 TAM, P 8 Operating Reactors Branch 1 84/02/08, VARQA, 8 A Operating Reactors Branch 1 2pp 22302 124 24x Fiche, 50-334, 84/02/08, 8402160573.
- 9. Inspection reports: IE Bulletins & correspondence
- 8402030317 Forwards IE Insp Rept 50-334/83-21 on 831003-07 No Violations noted MARTIN, T Division of Engineering & Technical Programs 83/12/29. CAREY, J. J. Duqueene Light Co. 2pp. 22055-145, 24X Fiche: 50-334,83/12/29,8402020317
- --8402020318 IE Insp Rept 50-334/83-21 on 831003-07 No violations noted Hajor areas inspected licensee actions in response to IE Bulletins 79-02 & 79-14 & verification of actions undertaken & work performed on mode affected by bulletins VARELA.A. A. MANOLY, K.A., DURR, J.P., Region 1. Office of Director 83/12/27, 5pp. 22055 147, 24X Fiche: 50-334,83/12/27,8402020317
- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps." Syc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/25 Consolidated Edison Co. of New York, Inc. 120pp. 22058:001. 24X Fiche 50-000,84/01/25,8312120153
- 8402150809 Forwards IE Insp Rept 50-334/83-30 on 831128-1202. No viblations noted.

 MARTIN, T.T. Division of Engineering & Technical Programs. 84/01/31 CAREY, J. J. Duquesne Light Co 2pp 22250-168 24X Fiche 50-334,84/01/31,8402150309
- --B402150314 IE Insp Rept 50-334/83-30 on 831128-1202 No violations nated. Major areas inspected: radiation protection program, including status of previously identified items, radiological control organization & personnel selection.
 NIMITZ.R.L., MILLER.H.T., SHANBAKY.M.M. Region i, Office of Director. 84/01/26 13pp 22250.170 24X Fiche 50-334,84/01/31,8402150307.

- B402140470 Requests relief from Class 3 pipe support inservice inspraguirements Best effort visual exam will be conducted to detect loss of support capability & inadequate restraints CAREY, J. J. Duquesne Light Co. 84/02/01 VARQA, 9 A. Uperating Reartors Branch 1 &pp 22221 078 24X Fiche 50~334,84/02/01,8402140490
- 8402160351 Forwards IE insp Rept 50-334/83-31 on 831212-15 No violations observed MARTIN: T Division of Engineering & Technical Programs 84/02/02 CAREYJ J Duquesne Light Co 2pp 22277 057 24X Fiche 50-334.84/02/02.8402160351
- ---8402140373 IE Insp Rept 50-334/83-31 on 831212-i5 No violations identified Major areas inspected onsite & offsite review committee & offsite support staff re GA program implementation NAPUDA: O Region i. Office of Director CAPHTON, D L Division of Engineering & Technical Programs 84/01/26 7pp 22277 059 24X Fiche 30-334, 84/02/02.8402160351
- B401170016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list entl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/03 Consolidated Edison Co. of New York, Inc. 117pp. 22114,179 24X Fiche 50-000,84/02/03,8401170016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headors." Bvc list encl BEYOUND,R C Director's Office. Office of Inspection and Enforcement 84/02/03, Consolidated Edison Co of New York, Inc 102pp 22177 156 R4X Fiche 50-000.84/02/03.8401190017
- B402220466 Notifies of intention to extend first 10-yr inservice inspinterval from B60930 to Jul 1988 per ABME Boiler & Pressure Vessel Code, Section XI, Subarticle IMA-2400(a) Bases for extension listed.

 CAREY, J J Duquesne Light Co. 84/02/09 VAR9A, B A. Operating Reactors Branch 1, 2pp. 22339 269 24X Fiche 50-334, 84/02/09.
- 8401170041 IE Info Notice 84-09. "Lessons Learned From NRC Insps of Fire Protection 88fe Shutdown 8ys (10CFR90.App R) " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259 24X Fiche 80-000.84/02/13,8401190041
- 8401190039 IE Info Notice 84-08, "IOCFRSO 7, 'Employee Protection'" Svc 11st encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/14 Consolidated Edison Co of New York, Inc 115pp 22865 141 24X Fiche 50-000,84/02/14,8401190039
- 8402290321 Forwards IE Insp Rept 50-334/84-01 on 840101-31 & notice of violation.

 87AROBTECKI:R Division of Project & Resident Programs 84/02/14 CAREY: J Duquesne Light Co 2pp 22426.313 24X Fiche: 50-334.84/02/14.8402290321
- --8402290324 Notice of violation from inep on 840101-31 * Region 1, Office of Director 84/02/14 ip 22426 315 24X Fiche 50-334,84/02/14,8402290321
- --8402270326 IE Insp Rept 50-334/84-01 on 840101-31 Violation noted river water pump inoperable due to not fully charging closure springs before connecting breaker to emergency bus. TROSMOSKI.W M . TRIPP.L E Region 1. Office of Director 84/02/10. 14pp 22426 316 24X Fiche 50-334,84/02/14.8402290321.
- 8401170045 IE Info Notice 83-63,8uppl i, "Potential Failures of Westinghouse Type 8A-1 Differential Releys." Svc liet encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp. 22366 142, 24X Fiche 50-000,84/02/15,8401190045
- 8401170062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Menufacturer Recommended Value " Byc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/21 Consolidated Edison Co. of New York, Inc 116pp 22366 024 24X Fiche: 50-000,84/02/21,8401170062
- 8402270242 Forwards fee re 840201 request for relief from inservice insp requirements of IMD-2600(c) for visual exam of five Class 3 pipe supports; per 100FR170. 22 SIEBER; J D Dugussne Light Co. 84/02/21 License Fee Management Branch 1p. 22391:301. 24X Fiche: 50-334,84/02/21,8402270242

- 8401190066 IE Info Notice 84-11. "Training Program Deficiencies"

 Svc list enc:
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co. of New
 York, Inc. 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Beat Valve Seals "
 Svc list encl.
 JORDANAE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc. 120pp 22431:040. 24X Fiche 50-000,84/02/27,8401190067
- S Reportable occurrences. LERs & related correspondence
- B40214037B Requests add1 info re Part 21 rept dtd 83110B concerning wear ring failure in auxiliary feedwater pump furnished to facilities Info requested within 25 days PDTAPOVS.U Region 4. Office of Director B3/11/30 PATTY.D F Bingham-Hillamette Co ip 22221 250 24% Fiche 50-000.83/11/30, B40214037B
- --B402140422 Supplemental Part 2: rept re wear ring failure in auxiliary feedwater sumps, per 83:130 request for add1 info Wear rings will be replaced on returned units w/AISI 420 wrought mat1 List of pumps in similar svc w/same wear ring enc1 PATTY, D F Bingham-Willametts Co 83:12/20. Region 4, Office of Director 2pp 22221 25: 24X Fiche 50-000, B3/11/30, BAD2140398
- 8402240086 Further response to FDIA request for 16 categories of documents. Item 9 limited.per 831005 telcon Forwards Rev 7 to NUREO-0525 t App A documents. Portions of App 8 documents uitakeld (ref FOIA Exemption 4) App B documents also in PDR FELTON, J M Division of Rules and Records 83/12/12, SHOLLY-8 C Union of Concerned Scientists 4pp 22374 150 24X Fiche 50-000,83/12/12,8402240086
- 8402020282 LER 83-042/03L-0 on 831225, during control board walkdown, steam flow indications for channel V on two separate steam lines indicated 0 3 mpph higher than other indications Caused by frozen censing lines Lines thawed W/840116 lfr LACEY.W B Duquesne Light Co. 84/01/16 MURLEY.T E Region 1, Office of Director 4pp 22054:337 24X Fiche:50-334,84/01/16,8402020282
- B402080359 LER B3-041/03L-0 on B31224 during surveillance test, subcooling monitor found to be reading unrealistic values of temp & pressure Caused by loose electrical input connector to PC cand Loose connector repaired WHAP0125 ltr.
 LACEY, W B Duquesne Light Co 84/01/25 MURLEY, T.E Region t. Dffice of Pirector App 22130 217 24X Ficher 50-334, 84/01/25, 8402080359
- B402080412 LER B3-043/03L-0: on B31227; main steam sarety valve effluent monitor declared inoperable. Cause unknown, Monitor left energized to ensure proper operation to returned to syc W/840127 ltr.

 LACEY, W. S. Duquesne Light Co. B4/01/27, MURLEY, T. E. Region 1, Office of Director App. 22100, 224 24X Fiche 50-334, 84/01/27, 8402080412
- 840223009B LER 84-001-00 on 840114 during performance of low bearing oil pressure trip, main turbing tripped Caused by pressure whitch on auto stop oil header actuating causing actuation of solenoid valve Buitch setpoint checked W/840214 ltr. DRUGA.R J. LACEY.W S Duquesne Light Co. 84/02/14, 5pp 22362-248 24X Fiche 50-334.84/02/14.8402230098
- 8402280366 LER 84-002-00 on 840125 during performance of reactor protection logic sys train A bimonthly test, train B manual safety injection pushbutton mistakenly depressed Caused by operator error Operator disciplined W/840223 ltr. DRUGALR J . LACEY.M.S. Duqueene Light Co. 84/02/23 3pp 22407:131 24X Fiche 50-334.84/02/23.8402280366.
- DOCKET 50-335 ST LUCIE PLANT, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8402130501 Emergency Plan Implementing Procedures 1101, 1102, 1103, 1104, 1105, 1105, 1106, 1107, 1201 & 1202 re duties of emergency control officer, recovery manager & emergency info manager W/840207 ltr.

 # Florida Power & Light Co B3/12/15 D'REILLY, J.P Region 2. Office of Director. 57pp 22201: RO1. 24X Fiche: 50-335,83/12/15, 8402130501.

- 8402080383 Revs to emergency plan implementing procedures, including Rev 15 to Procedure 31000216. Rev 25 to Procedure 31000256. Rev 8 to Procedure 31000356 Rev 8 to Procedure 31000356 W/840202 ltr WILLIAMS. J W. HARRIS. K N. SCHMIDT. A D Florida Power & Light Co. 84/01/09 O'REILLY. J P Region 2. Office of Director 84pp. 22131 026 24% Fiche 50-335, 84/01/09, 8402080383
- 8402010184 Forwards comments on detailed control room design review (DCROR) program plan submittel per Suppl 1 to NUREO-0737 DCRDR summary repts submitted on 830930 & 1101 currently under review VAROA.8 A Operating Reactors Branch 1 84/01/16 WILLIAMS, J. W Florida Power & Light Co lopp 22048 033 24X Fichs 50-000.84/01/16.8402010184
- B402130449 Forwards Rev 8 to physical security plan Rev withheld (ref 100FR73 21)
 WILLIAMS J W Florida Power & Light Co 84/01/31 O'REILLY, J P
 Region 2. Office of Director 1p 22202 103 24X
 Fiche 50-335.84/01/31.8408130449
- 8402140400 Ack receipt of 831222 ltr providing objectives for emergency exercise scheduled for Mar 1984 Emergency personnel will not arrive at Pacilities until arrival would have occurred on real-time basis

 BANCE, H C Division of Project & Resident Programs 84/01/31

 WILLIAMS, J W Florida Power & Light Co 1p 22220 345 24X

 Ficher 50-335,84/01/31,8402140400
- 8402270399 Revised emergency plan implementing procedures, including Procedures 31000RIE for St Lucie & 20101 for Turkey Point reduties of emergency coordinator & 1102 for Turkey Point concerning recovery manager duties W/840221 ltr WILLIAMS, J W Florida Pawer & Light Co 84/01/31 81pp 22391.069 24X Fichs 50-000.84/01/31,8402270399
- 8402070381 Forwards Revs 15, 25, 8 & 3 to Emergency Plan Implementing Procedures 3100021E, 3100023E, 3100033E & 3100035E, Taspectively, re emergency coordinator duties, emergency roster & offsite dose calculations.
 WILLIAMS.J W. Florida Power & Light Co. 84/02/02. O'REILLY, J P. Region 2. Office of Director. 1p 22075 116 24X
 Fiche 50-335,84/02/02,8402070381
- --8402070383 Rev 15 to Emergency Plan Implementing Procedure 3100021E.
 "Duties & Responsibilities of Emergency Coordinator"
 HARRIS, X N Florida Power & Light Co. 84/01/09 24pp.
 22095 117 24X Fiche. 30-335.84/02/02.8402070381
- --8402070385 Rev 25 to Emergancy Plan Implementing Procedure 3100023E.

 "Onsite Emergancy Organization & Roster"

 HARRIS,K N Florida Power & Light Co 84/01/09, 15pp
 22095,141 24X Fiche 50-335,84/02/02.8402070381
- --840207038B Rev 8 to Emergency Plan Implementing Procedure 3100033E, "Offsite Dose Calculations"

 BCHMIDT.A D Florida Power & Light Co 84/01/09 30pp 22095 156 24X Fithe 50~335,84/02/02,8402070381
- --B402070391 Rev 3 to Emargency Plan Implementing Procedure 31000355, "Offsite Radiological Monitoring "
 SCHMIDT;A D Florida Power & Light Co. 84/01/09 13pp, 22095 186 24% Ficha: 50~335,84/02/02,8402070381
- 8402080224 Forwards IE Insp Repts 50-335/84-01 & 50-389/84-02 on 840109-13 No violations noted. DANCE:H C Division of Project & Resident Programs 84/02/02 WILLIAMB:J W Florids Power & Light Co 2pp. 22130:221. 24X Fiche 50-335.84/02/02,8402080224
- --B402080479 IE Insp Repts 50-335/B4-01 & 50-389/B4-02 on 840109-13 No violations noted Major areas inspected security organization, security program audit physical barriers & detection aids Details withheld (ref 10CFR2 790 & 73, 21), HALL, B. L., MCGUIRE, D. R. Region 2. Office of Director. 84/02/02 ip 22i30, 223. 24X Fiche 50-335,84/02/02,8402080224.
- 840221016B Forwards Human Factors Engineering Branch draft SER to detailed control room design review.per Buppl 1 to NUREG-0737 Add1 info needed to complete review VARGA. 8. A Detating Reactors Branch 1. 84/02/02. WILLIAMS. J. H. Florida Power & Light Co. 18pp. 22346.027 24X Fiche 30-000.84/02/02, 8402210168
- --B402090330 "Evaluations of Detailed Control Room Design Reviews for St Lucie Units 1 & 2 & Turkey Point Units 3 & 4," technical systuation rapt # Beience Applications, Inc NRC-03-82-096, SAI-186-351-68 84/01/13 NRC No Detailed Affiliation Given 23pp. 22346-047 24% Fiche 50-000.84/02/02.8408210168.

- 8402130362 Forwards revised Emergency Implementing Procedures 1101 reduties of emergency control officer, 1102 reduties of emergency control officer, 1102 reduties of recovery manager. 1103 reduties of emergency security manager willLIAMS.JW Florida Power & Light Co 84/02/07 O'REILLY,JP Region 2, Office of Director 1p 22200 257 24X Fiche 50-335,84/02/07,8402130362
- --840213036B Revised emergency implementing procedures, including Procedure 1101 re duties of emergency control officer, Procedure 1102 re duties of recovery manager & Procedure 1103 re duties of emergency info manager * Florida Power & Light Co 83/12/15 59pp 22200 258 24X Fiche 50-335,84/02/07,8402130362
- B402160490 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licenses, per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR
 MILLER, JR Deprating Reactors Branch 3 84/02/07 WILLIAMS, JW Florida Power & Light Co 2pp 22292-349 24X
 Fiche 50-335,84/02/07,8402160690
- B402170258 Provides justification for revising schedule change for implementation of upgraded emergency operating procedures, per Suppl 1 to NUREQ-0737
 HILLIAMB.J.W Florida Power & Light Co B4/02/17 EISENHUT, D G Division of Licensing 2pp 22277 182 24X Fiche 50-335,84/02/17,8402170258,
- J Insurance & indemnity information
- B402020343 Forwards Endorsements 51 & 41 to NELIA & MAELU Policies NF-227 & MF-88, respectively DUCK.J R Marsh & McLennan, Inc 84/01/26 SALTZMAN, J. Assistant Director for State & Licensee Relations. 3pp 22055 047 24X Fiche. 50-335,84/01/26,8402020343
- O Advisory Committee on Reactor Bafaguards reports & correspondence
- 8402090533 Bummary of ACRB Fluid Dynamics Subcommittee 831208 meeting in Washington, DC re recent flow-related incidents resulting in Equipment damage in plant primary sys * ACRB Advisory Committee on Reactor Safeguards 83/12/13 ACRS Advisory Committee on Reactor Safeguards 26pp 22172 117 24X Fichs 50-000, 83/12/13, 8402090533.
- 8402090511 Submits rept on ACRS Fluid Dynamics Subcommittee 831208 meeting. Flow-related incidents have common origin in flow induced vibration due to vortex shedding or bulk flow oscillation
 TIEN.C L California, Univ of, Berkeley, CA TIEN.C L ACRS Advisory Committee on Reactor Safepurds 83/12/22 BDEHNERT, FA ACRS Advisory Committee on Reactor Safeguards 2pp 22192:308 24X Fiche:50-335,83/12/22,8402090511
- P. Operating license stage documents & correspondence
- 8402030519 Notification of 840208 & 09 meetings w/util in Bethesda, MD to discuss open items contained in Franklin Research Ctr technical evaluation repts re environ qualification of electrical equipment SELLS, D.E. Operating Reactors Branch 3 84/01/16 MILLER, J R Operating Reactors Branch 3, VARCA, S A Operating Reactors Branch 1 4pp. 22082: 170 84% Ficher 50-000, 84/01/16, 8402030519
- 8402130451 Requests review of encl EQ&O technical evaluation rept, "Conformance to NRR Generic Ltr 82-16.8t Lucie Plant.Units 1 & 2 " Response addressing deviations for Unit 1 requested within 30 days of ltr receipt MILLER.J.R. Operating Reactors Branch 3 84/01/30. WILLIAMS, J W Florida Power & Light Co 2pp 22216 107. 24X Fiche 50-335,84/01/30,8402130451
- --8402130457 "Conformance to NRR Generic Ltr 82-16.8t Lucie Plant, Units 1 & 2," preliminary rept.
 VANDERBEEK, R. EQ&Q. Inc FIN A-6600 EQQ-EA-6432 DRFT 83/10/31. NRC No Detailed Affiliation Given 20pp. 22216:109. 24X Fiche. 50-335,84/01/30,8402130451
- 8402010410 Generic Ltr 84-04 to all operating PMR licensees, CP holders & applicants for CPs re safety evaluation of Westinghouse topical rapts dealing w/elimination of postulated pipe breaks in PMR primary main loops 8vc list encl. EIBENHUT,D 9. Division of Licensing. 84/02/01. Consolidated Edison Go. of New York, Inc. 59pp. R2177 087, 24X Fiche 50-000,84/02/01,8402010410

- 8402150149 Forwards final version of, "Integrity & Stability of Internals-Conclusions & Findings," per plant recovery program WILLIAMS, J W Florida Power & Light Co 84/02/10 MILLER, J R Operating Reactors Branch 3 3pp 22243 183 24X Fiche \$0-335,84/02/10.8402150149
- --8402150154 Final version of, "Integrity & Stability of Internals-Conclusions & Findings " * Florida Power & Light Co 84/02/10 248pp 22243 186 24% Fiche 50-335,84/02/10,8402150149
- @ Inspection reports, IE Bullatins & correspondence
- B402140R42 Ack receipt of B31214 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-335/B3-34 & 50-3B9/B3-62 Implementation of corrective actions will be examined during future insps
 DANCE.H C Division of Project & Resident Programs 84/01/18
 HILLIAMB.J W Florida Power & Light Co Ip 22220 R85 24X
 Fiche 50-335.84/01/18.8402140242
- ---8402140253 Ack receipt of 831214 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-335/83-34 & 50-389/83-62.

 LEWIS, R C Division of Project & Resident Programs 83/12/28

 WILLIAMS, J W Florida Pawer & Light Co ip 22220 286 24X

 Fiche 50-335,84/01/18,8402140242
- --8402140266 Responds to NRC 831114 ltr re violations noted in IE Insp. Repts 50-335/83-44 & 50-389/83-62 Corrective actions, all motor operated valves on locked valve list verified to have locked wheels Procedure revised to include signature blanks WILLIAMS, J.W. Florida Power & Light Co. 83/12/14 D'REILLY, J.P. Region 2, Office of Director 2pp. 22220 287 24% Fiche 50-335,84/01/18,8402140242
- --8402140275 Forwards IE Insp Repts 50-335/83-34 & 50-397/83-42 on 830911-1010 & notice of violation DANCE, H C Division of Project & Resident Programs 83/11/14 WILLIAMS, J W Florida Power & Light Co 2pp 22220 289 24X Fiche 50-335,84/01/18,6402140242
- --8402140283 Notice of violation from inap on 830911-1010 * Region 2, Office of Director. 83/11/14 2pp 22220 291 24X Ficha. 50-335, 64/01/18, 8402140242
- --8402140303 IE Insp Repts 50-335/83-34 & 50-389/83-62 on 830911-1010 Noncompliance noted. Pailure to implement procedures revalves, locks & switches to implement procedures revalves, locks & switches ELROD, S A . BIBB.H.E Region 2. Office of Director LANDIS, K Division of Project & Resident Programs B3/11/10 5pp 22220 293 24X Fichs 50-335.84/01/18.8402140242
- 8402140085 Provides supplemental response to IE Bulletin 83-06 rs nonconforming matls supplied by Tube-Line Corp. Two 4-inch selbows in shield bldg ventilation says discussed in 831206 ltr will be replaced.
 HILLIAMS, J W Florida Power & Light Co 84/01/20 O'REILLY, J P Region 2, Office of Director. Ip 22217 198 24X Fiche 50-000,84/01/20,8402140085
- B402140076 Provides supplemental response to IE Bulletin 83-06 re nonconforming matls supplied by Tube-Line Corp Two 4-inch elbows in shield bidg ventilation sys discussed in B31206 ltr will be replaced.

 MILLIAMS, J.W. Florida Power & Light Co 84/01/23 Q'REILLY, J.P. Region 2, Office of Director. ip. 22217; 254 24X Fiche 50-000,84/01/23,8402140076.
- B312120153 IE info Notice B4-04. "Steam Binding of Auxiliary Feedwater Pumps." Svc list encl JURDAN,E L. Division of Emergency Preparadness & Engineering Response (Post B30103) 84/01/25. Consolidated Edison Co. of New York, Inc. 120pp. 22058:001 24X Fiche:50-000:84/01/25,8312120153
- 8402080224 Forwards IE Insp Repts 50-335/84-01 & 50-389/84-02 on 840109-13. No violations noted DANCE; H C. Division of Project & Rewident Programs 84/02/02, HILLIAMB. J. W. Florida Power & Light Co 2pp 22130; 221, 24X Fiche: 50-335,84/02/02,8402080224
- --B402080479 IE Insp Repts 50-335/B4-01 & 50-389/B4-02 on 840109-13 No violations noted Major areas inspected security programization.security program audit, physical barriers & detection aids. Details withhald (ref 10GFR2 790 & 73 21) HALL, B L , MCGUIRE, D R Region 2, Office of Director. 84/02/02. 1p. 22130 223 24% Fiche 50-335,84/02/02,8402080224

- 8401190016 IE Info Natice 84-07. "Design-Basis Throat & Review of Vehicular Excess Controls " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000.84/02/03.8401190016
- 8401190017 IE Gulletin 84-01, "Cracks in BWR Mark [Containment Vent Headers " Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidabed Edison Co of New York, Inc 102pp 22177
- 8402100321 Notification of 840209 meeting w/C-E in Bethesda.MD to discuss proposed C-E alternate reactor trip sys SELLS.D E decrating Reactors Branch 3 84/02/03 MILLER, J R Operating Reactors Branch 3 2pp 22205 [18 24X] Fiche 50-335.84/02/03.8402100321
- 8402280148 Ack receipt of 840123 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-335/83-41 & 50-387/83-69 DANCE H C Division of Project & Resident Programs 84/02/08 WILLIAMS, J W Florida Power & Light Co ip 22400 292 24X Fiche 10-335,84/02/08,8402280148
- --8402280156 Responds to NRC 831222 ltr re violations noted in IE lnsp Repts 50-335/83-41 & 50-389/83-69 Corrective actions condition of oil noted on both plant work orders Only preventive maint activities will be listed on work orders WILLIAMS.J W. Florida Power & Light Co 84/01/23 O'REILLY.J P Region 2. Office of Director 2pp 22400 293 24X Fiche 50-335,84/02/08.8402280148
- --8402280166 Forwards IE Insp Repts 30-335/83-41 & 50-389/83-69 on 831128-1203 & notice of violation DANCE:H C Division of Project & Resident Programs 83/12/22 HILLIAMS.J H Florida Power & Light Co 2pp 22400 295 24X Fir
- --8402280174 Notice of violation from insp on 831128-1203 * Region 2. Office of Director 83/12/22 1p 22400 297 24X Fiche 50-335,84/02/08,8402280148
- --8402280186 IE Insp Repts 50-335/83-41 & 50-389/83-49 on 831128-1203 Violation identified failure to follow maint procedures for primary containment internal pressure & RC8 safety injection tank
 JENISON.K M Region 2, Office of Director ELROD, 8 A Division of Project & Resident Programs 83/12/22 8pp 22400 298 24X Fiche 50-335,84/02/08,8402280148
- 8401190041 IE Info Notice 84-07. "Lessons Learned From NRC Insps of Fire Protection Safe Shutdoom Sys. (1905R50. App R)" Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Fost 630103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365 259 24X Fiche 50-000.84/02/13.8401190041
- 8401190039 IE Info Notice 84-0B. "10CFR80 7. 'Employee Protection '"
 Syc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 030103) 84/02/14 Consolidated Edison Co. of New
 York, Inc. 115pp 22365 141 24X Fiche 30-000.84/02/14.8401190039
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Hestinghouse Type 8A-1 Differential Relays " Bvt list encl JORDAN: EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Constituted Edison Co of New York, Inc 118pp 22364 142 24X Fiche 50-000.84/02/15,8401190045
- 8402220571 Withdraws 830429 request for relief from Tech Spec requirements for performing inservice inap WILLIAMS.J W Florida Power & Light Co 84/02/16 EISENHUT.D 0. Division of Licensing ip 22331 361 24% Fiche 50-235,84/02/16. 8402220571
- B401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches 8st Below Manufacturer Recommended Value " Bvc list encl JORDAN.E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp. 22366 024 24X Fiche 50-000,84/02/21,8401190062
- B401190066 IE Info Notice 84-11, "Training Program Deficiencies" Svc list encl. JORDANNEL Division of Emergency Preparedness & Engineering Response (Post B30103) B4/02/24 Consolidated Edison Co of New York, Inc. 115pp 22430 304 24X Fiche 50-000.84/02/24,8401190066

- 8401170067 IE Info Notice 84-12, "Failure of Soft Seat Valve Beals "
 Svc list encl
 JORDANE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060 24X Fiche 50-000.84/02/27,8401190047
- DOCKET 50-336 MILLSTONE AUCLEAR POWER STATION, UNIT 2
 F Security, medical: emergency & fire protection plans
- 8402010219 Forwards emergency plan implementing procedures, in response to NRC 83071B request re autstanding issues concerning past-accident ampling sys Capability of measuring reactor coolant dissolved oxygen will not be provided CDUNBIL.H G Connecticut Yanker Atomic Power Co CDUNBIL.H G Northeast Nuclear Energy Co (subs of Northeast Utilities) CDUNBIL.H G Northeast Utilities 84/01/12 CRUTCHFIELD,D Derenting Reactors Brench 3 MILLER.J R Operating Reactors Brench 3 3pp 22039 280 24X Fiche 30-000,84/01/12,8402010219
- --8402010237 Rev O to Emergency Plan Implementing Procedure EPIP 4222,
 "Core Damage Estimate Procedure"

 MRDCZMA,E , JAHGRSKY,M Northeast Nuclear Energy Co (subs of
 Northeast Utilities) 83/03/31 22pp 22037 326 24X
 Fiche 50-000.84/01/12.8402010217
- 8402030394 Discusses 831102 & 1216 responses to NRC 831020 transmittal re 830908 enforcement conference rept for proprietary review & violations noted in 1£ Insp Rept 50-336/83-19 on 830808-12
- MARTIN.T T Division of Engineering & Technical Programs 84/01/27 COUNSIL.W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 22069 008 24X Fiche 50-336.84/01/27.8402030394
- --B402030397 Forwards response to NRC 83iii6 ltr re violations noted in IE Insp Rept 90-336/83-19 on B30808-12 Safeguards info withheld (ref 10CFR73 21 & 2 790) COUNSIL.W 0 , SEARS.C F Northeast Nuclear Energy Co (subs of Northeast Utilities). COUNSIL.W 0 Northeast Utilities B3/12/16 MARTIN.T T Bivision of Engineering & Technical Programs 1p 22069:010 24X Fiche 50-336,84/01/27,8402030394
- --8402030402 Forwards response to 831020 ltr re 830708 unforcement conference rept Safeguards (nfo withheld (ref 10CFR73 21) CDUMBILN 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) CDUMBIL. W 0 Northeast Utilities 83/11/02 MARTIN.T T Division of Engineering & Technical Programs ip 22069 011 24X Fiche 50-336,84/01/27.8402030374
- B402150182 Rev 93 to emergency plan implementing procedure index & Rav 4. Change 1 to Procedure OP-501, "Incident Assessment & Classification Unit 1" COUNSIL, M. On Northeast Nuclear Engray Co (subs, of Northeast Utilities) COUNSIL, W. O. Northeast Utilities B4/01/30 EIBENHUT, D. Q. Division of Licensing 10pp 22241 176 24X Fiche 50-245, 84/01/30, 8402150182
- 8402160005 Notifies of necessity to relocate technical support ctr (TBC) from Unit 1 computer room by Mar 1984 due to computer replacement program TBC proposed to be moved to new facility in May & to emergency operations facility in interim COUNBIL, WO Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL, W O Northeast Utilities 84/01/31, MILLER, J R Operating Reactors Branch 3 CRUTCHFIELD, D. Operating Reactors Branch 5 2pp 22276 202 24% Fiche 50-245, 84/01/31, 8402160005
- 8402070108 Forwards Rev 2 to suitability, training & qualification plan
 Rev withheld
 MDFRID.M D Mortheast Utilities Service Co (subs of Northeast
 Utilities) 84/02/03 DENFON.H.R Office of Nuclear Reactor
 Regulation, Director ip 22163 314 24X Fiche 50-245,84/02/03,
 8402070108
- 8402140135 Responds to NUREG-0737, Suppl 1 re requirements for emergency response capabilities/emergency operations facilities Util intends to revise Section 7 1 of emergency plan w/addition of listed wording CDUNSIL, W.G. Connecticut Yankes Atomic Power Co COUNSIL, W.G. Connecticut Yankes Atomic Power Co COUNSIL, W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 84/02/03 EISENHUT, D.G. Division of Licensing 2pp 22219 038 24X Fichs 50-000, 84/02/03,8402140135.
- B402070337 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per Generic Ltr B1-27 W/o request, entire plan will be placed in PDR.

 CRUTCHFIELD.D Operating Reactors Branch 5 84/02/06 COUNSIL. W.O Connecticut Vankee Atomic Power Co COUNSIL. W.O Northeast Nuclear Energy Co (subs. of Northeast Utilities). 2pp. 22096 197 24X Fiche. 50-000.84/02/06.8402070337.

- 8402220268 Forwards IE Insp Repts 50-245/84-01 & 50-336/84-01 on 831218-840121 No violations observed 85408576CK1.R Division of Project & Resident Programs 84/02/06 COUNBIL.W Q. Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 22337 129 24X Fiche 50-245.84/02/06.8402220268
- --8402220273 IE Insp Repts 50-245/84-01 & 50-336/84-01 on 831218-840121
 No violations identified Major areas inspected plant
 operations, equipment alignments & readiness, radiation
 protection, physical security, fire protection & records
 SHEDLOSKY, J T , KINNEY, W W Region 1, Office of Director
 ELABSER, T C Division of Project & Resident Programs 84/02/01
 20pp 22337.131 24X Fiche 50-245,84/02/06,8402220268
- D Advisory Committee on Reactor Safeguards reports & correspondence
- 6402090533 Summary of ACRS Fluid Dynamics Subcommittee 831208 meeting in Washington, DC re recent flow-related incidents resulting in equipment damage in plant primary sys * ACRS Advisory Committee on Reactor Bafeguards 83/12/13 ACRS Advisory Committee on Reactor Safeguards 2opp 22192 119 24X Fichs. 50-000, 83/12/13, 8402090533
- P Operating license stage documents & correspondence
- 8402020420 Corrects 831230 ltr transmitting Amend 90 to License DPR-65 Amend correction provides add1 info & does not change substance of original amend MILLER, J. R. Operating Reactors Branch 3 84/01/16 COUNSIL W. O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 22062 185 24X Fiche 50-336,84/01/16,8402020420
- 8402150340 Application for amend to License DPR-65 revising Tech Specs re inservice insp of hydraulic & mechanical snubbers, COUNSIL, M.O. Northeast Nuclear Energy Co. (subs of Northeast Utilities) COUNBIL, M.O. Northeast Utilities. 84/01/18 MILLER, J.R. Operating Reactors Branch 3 2pp. 22250 298 24X Ficher 50-336, 84/01/18, 8402150340
- --8402150343 Proposed Tech Bpecs re snubber surveillance requirements * Northeast Nuclear Energy Co (subs. of Northeast Utilities) 84/01/31 24pp. 22250-300 24X Fiche 50-336.84/01/18,8402150340
- B40D160100 Application for amend to License DPR-65, revising Tech Specs re power distribution limit total plenar radial peaking factor CDUNBIL, W 9 Northeast Nuclear Energy Co. (subs. of Northeast Utilities). CDUNBIL, W, 9, Northeast Utilities B4/01/20 MILLER, J R Derasting Reactors Branch 3 4pp 22276 144 24X Fiche. No-336, 84/01/20, 8402160100
- 8402160437 Submits info on operator training program re natural circulation cooldown, in response to Generic Ltr 81-21 & NRC 831020 request. Program on RCS & upper vessel head voiding accomplished during accident matigation training CGUNSIL, W 9 Northeast Nuclear Energy Co, (subs. of Northeast Utilities). COUNSIL, W, 0, Northeast Utilities 84/01/24 MILLER, J. R. Operating Reactors Branch 3 3pp. 22268:304, 24X Fiche: 50-336,84/01/24,8402160437
- 8402160044 Application for amend to License DPR-65, changing Tech Specs by revising total planar peaking factor limits COUNSIL, M. 9. Northeast Nuclear Energy Co (subs of Northeast Utilities). COUNSIL, M. 9. Northeast Utilities. 84/01/25, MILLER, J R Operating Reactors Branch 3 5pp 22275; 232 24X Fiche: 50-336, 84/01/25, 8402160044
- ---8402160053 Proposed Tech Spec changes, revising total planer peaking factor limits

 8 Northeast Nuclear Energy Co (subs. of Northeast Utilities), 84/01/25, 4pp. 22275-237, 24X Fiche, 50-336, 84/01/25, 8402160044.
- 8402130151 Forwards Amend 91 to License DPR-65 & safety evaluation. Amend modifies Tech Specs re total planar peaking factor limits Changes cover power levels between 92.5% & 100X limits. HEITNER, K.L. Operating Reactors Branch 3 84/01/27 CDUNBIL, W O Northeast Nuclear Energy Co. (subs of Northeast Utilities). 2pp. 22216:330 24X Fiche:50-336,84/01/27,8402130151.
- --8402130154 Amend 91 to License DPR-65, modifying Tech Spacs re total planar peaking factor limits Changes cover power levels between 92 5% & 100% limits.

 HILLER, J. R. Operating Reactors Branch 3, 84/01/27, 9pp. 22216; 332, 24% Fiche; 50-336,84/01/27,8402130151.

- --8402130158 Safety evaluation supporting Amend 91 to License DPR-65 * Office of Nuclear Reactor Regulation, Director 84/01/27 3pp 22216 341 24% Fiche 50-336,84/01/27,8402130151
- 8402150009 Forwards revised Corporate Organization for Nuclear Incidents procedure manual, including Rev 7 to Procedure CONI 7.01 re manager of external communications W/o snc!
 COUNSIL, W G Connecticut Yankse Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities)
 COUNSIL, W G Northeast Utilities 84/01/30 EIGENAUT, D G
 Division of Licensing 2pp 22247 217 24X Fiche 50-000.84/01/30, 84002180009
- 8402010410 Generic Ltr 84-04 to all operating PHR licenses, CP holders & applicants for CPs re sefety evaluation of Westinghouse topical repts dealing w/mlimination of postulated pipe breaks in PHR primary main loops 8vc list enci EIBENHUT.D G Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc 59pp 22177 087 24X Fichs 50-000.84/02/01.8402010410
- B402160424 Forwards info & comments in response to B3i114 request for various confirmatory evaluations & Justification for analytical models utilized in Cycle 6 safety analyses CDUNBIL.W 0, DIGHICP.R W. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). CDUNBIL.W 0, Northeast Utilities. B4/02/01 MILLER, JR. Operating Reactors Branch 3. 7pp. 22267-005 24X Fiche: 50-336,84/02/01,8402160424
- B402140416 Advises that correct value for weld seam 9-203 is 0 30 weight percent copper per reactor pressure vessel mati surveillance program in response to 840104 & 771209 ltrs Embrithlement in weld 9-203 reduced COUNBIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNBIL, W. G. Northeast Utilities B4/02/03 MILLER, J. R. Derating Reactors Branch 3 ip 22227 116 24X Fiche 80-336, 84/02/03, 8402140416
- 8402220190 Advises that 7,896 operating hours spent at hot standby through Cycle 5,per NRC request CDUNBIL.W 9. SEARS.C F Northeast Nuclear Energy Co (subs of Northeast Utilities). CDUNBIL.W 9 Northeast Utilities Service Co (subs of Northeast Utilities) 84/02/07 MILLER,J R Operating Reactors Branch 3. 19. 22340:357 24X Fiche 50-336,84/02/07. 8402220190
- Q Inspection reports, IE Bulletins & correspondence
- 8402020335 Forwards IE Insp Repts 50-245/83-17 & 50-334/83-27 on 831025-28 No violations noted MARTIN.T T. Division of Engineering & Technical Programs 83/12/29 COUNSIL.W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 22055:015 24X Fiche 50-245/83/12/29/8402020335
- --8402020338 IE Insp Repts 50-245/83-19 & 50-336/83-27 on 631025-28 No violations noted Major areas inspected OA program, including implementation of administrative controls for procurement & previously identified items NAPUDA. O. Region 1. Office of Director CAPHTON, D L Division of Engineering & Technical Programs 83/12/20. App 22055.017 24X Fiche 50-245,83/12/27,8402020335
- B402160113 Forwards ABME Section III. Class 2 & 3 & ANSI B31 1 O Piping Analysis, "Ultrasonic Indications in Steam Generator Top Head Dome Weld." Evaluation varified structural integrity of 'plant steam generators, par NRC 831021 1tr COUNSIL, N 9 . SEARS, C F. Northeast Nuclear Energy Co (subs. of Northeast Utilities) COUNSIL, W 0. Northeast Utilities 83/12/30 MURLEY, T E Region 1, Office of Director. 1p 22276 297 24X Fiche 50-336,83/12/30,8402160113
- --8402160117 ABME Section III.Class 2 & 3 & ANBI B31 1 0 Piping Analysis.
 "Ultrasonic Indications in Steam Generator Top Head Dome
 Weld "ELY.J F Northwest Utilities Service Co (subs of Northwest
 - ELY, J F Northeast Utilities Service Co (subs of Northeast Utilities), PA 82-196 ROO 83/12/15 16pp 22276 298. 24% Fiche 50-336, 83/12/30, 8402160113
- 8402160002 Notifies that during 1983 refueling outage inservice insp. defects found in 2:163 steam generator tube ends All tubes either sleeved or plugged. HROCZKA:E J Northeast Nuclear Energy Co (subs. of Northeast Utilities). HROCZKA:E J Northeast Utilities 84/01/10 HURLEY.T.E Region 1: Office of Director 19 22276 201. 24X Fiche. 50-336, 84/01/10.8402160002
- 8402150340 Application for amend to License DPR-65, revising Tech Specs re inservice insp of hydraulic & mechanical snubbers COUNSIL, M. O. Mortheast Nuclear Energy Co (subs of Northeast Utilities). COUNSIL, M. O. Northeast Utilities 84/01/18. MILLER, J. R. Operating Reactors Branch 3 2pp 22250 278, 24X Fiche. 50-336, 84/01/18, 8402150340

- --8402150343 Proposed Tech Specs re snubber surveillance requirements * Northeast Nuclear Energy Co (subs of Northeast Utilities). 84/01/31 24pp 22280 300 24X Fiche 50-336.84/01/18.8402150340
- 8402020166 Forwards IE Insp Rept 50-336/83-31 on 831219-21 No violations noted BTAROSTECKI.R Division of Project & Resident Programs 84/01/20 COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 22037:244 24X Fiche.50-336,84/01/20,8402020166
- ~-8402020171 IE Imap Rept 50-336/83-31 on 831219-21 Deficienties noted failure to follow guidance in 0E Svc Advice Ltr 175-9 3 refrequency of breaker testing & inadequate guidance to maint personnel in procedures
 LUPTAK.A. LIPINSKI.D Region 1. Office of Director.
 EL6ASSER.T C. Division of Project & Resident Programs 84/01/18
 3pp 22037 246 24% Fiche 50-336.84/01/20.8402020166
- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc. 120pp 22058 001, 24% Fiche 50-000.84/01/25,8312120133
- 8402080372 Forwards IE Insp Repts 80~245/83~20 & 50~336/83-28 on 831031-1104 & notice of violation MARTIN.T T. Division of Engineering & Technical Programs 84/01/25 COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities), 2pp 22131 123. 24X Fichs 50~248.84/01/25,8402080372
- --B4020B0384 IE Insp Repts 30-245/83-20 & 30-336/83-28 on 831031-1104 Violation noted-failure to review & approve new alarm setting method in Procedure CP B07A. "Liquid Waste Discharge "
 JANO, J C STRUCKMEYER, R PASCIAK, H J Region 1, Dffice of Director 84/01/19 App. 22131 126. 24X Piche: 50-245, 84/01/25, 84020B0372
- 8402030394 Discusses 831102 & 1216 responses to NRC 831020 transmittal re 830708 enforcement conference rept for proprietary review & violations noted in IE Insp Rept 50-336/83-19 on 830808-12
 - MARTIN.T T Division of Engineering & Technical Programs. 84/01/27 CDUN91L.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp. 22069.008 24% Fiche 80-336,84/01/27.8402030394
- ---B402030397 Forwards response to NRC 831116 ltr re violations noted in IE Insp Rept 50-336/83-19 on 830808-12 Safeguards info withheld (ref 10CFR73 21 & 2 770) GUNBIL.W 0. BEARS.C F Northeast Nuclear Energy Co. (subs of Northeast Utilities). COUNBIL.W.O Northeast Utilities 83/12/16 MATIN.T T Division of Engineering & Technical Programs, 1p 22069 010. 24X Fiche.50-336.84/01/27.8402030394
- --8402030402 Forwards response to 831020 ltr re 830908 enforcement conference rept Safeguards info withheld (ref 10CFR/3,21), COUNBIL.N.G Northeast Nuclear Energy Co (subs. of Northeast Utilities). COUNBIL.N G. Northeast Utilities 83/11/02, MARTIN.T.T Division of Engineering & Technical Programs, 1p 22049 011. 24X Fiche: 50~336,84/01/27,8402030394.
- 8402080283 Provides followup response to Item 5 of IE Bulletin 83-03, "Check Valve Failures in Raw Water Gooling Bys of Diesel Generator "Inservice test program will be modified to reflect add1 insp to assess wear rates COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W.G. Connecticut Yankes Atomic Power Co. COUNSIL.W.G. Water By Counsil Water, T. E. Region 1. Office of Director. 2pp 22131:227 24X Fiche: 50-336,84/01/30,8402080283
- B401190016 IE Info Notice 84-07, "Design-Besis Threat & Review of Vehicular Excess Controls " Svc list ent; JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/02/03 Consolidated Edison Co. of New tork, Inc (19pp. 22114:177 24X Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01. "Cracks in BWR Mark I Containment Vent Headers " Syc list enc! DEYGUNG.R C. Director's Office, Office of Inspection and Enforcement. 84/02/03. Consolidates Edison Co. of New York, Inc 102pp. 22177-156 24X Fiche 50-000.84/02/03.8401190017
- B40222026B Forwards IE Insp Repts 50-245/84-01 & 50-336/84-01 on B31218-B40121, No violations observed Resident Programs. B4/02/06 STARGBIECKI, R Division of Project & Resident Programs. B4/02/06 COUNSIL, M G. Northeast Nuclear Energy Co (subs of Northeast Utilities). 2pp. 22337 127, 24X Fiche 50-245,84/02/06,8403220268

- --8402220273 IE Insp Repts 50-245/84-01 & 50-336/84-01 on 831218-840121 No violations identified Major areas inspected plant operations; equipment alignments & readiness; radiation protection, physical security, fire protection & records BHEDLOSKY, J. T., LIPINSKI, D R, VITO, D J Region 1, Office of Director 84/02/01 20pp 22337 131 24X Fiche 50-245,84/02/04,8402220248
- 8402210257 Provides final response to IE Bulletin 92-02, Action Items 2 & 4 re degradation of threaded fasteners in RCPB.per 830519 ltr No defects found in 20 pressurizer manuag closure studs inspected during Cycle 6 refueling outage COUNSIL.W O Northeast Utilities COUNSIL.W O BEARG, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) 84/02/08 MURLEY.T.E Region in Office of Director 2pp 22314-352 24X Fiche.50-336,84/02/08,8402210237
- 8401190041 IE info Notice 84-09. "Lessons Learned From NRC Insps of Fire Protection Bafe Shutdown Sys (100FRSO, App R) " Syc list enc!

 JORBAN, E. L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365-239 24X Fiche 80-000, 84/02/13 8401190041
- 8402290269 Forwards IE Insp Rept 50-336/84-02 on 840117-R7 Enforcement conference scheduled for 840215 to discuss apparent violation re improparly connected detector cables for power range linear instrument.

 STAROSTECKIR. Division of Project & Resident Programs. B4/02/13 CDUNCIL.H 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) Gpp. 22427 132 24X Fiche 30-336.84/02/13.8402290269.
- ~-8402290275 IE Insp Rept 50-336/84-02 on 840117-27. Violation noted failure to maintain required number of reactor protective sys channels operable.

 LIPINBKI.D.R Region 1, Office of Director. ELBASBER, T C. Division of Project & Resident Programs. 84/02/10 8pp 22427 155 24X Fiche 50-336,84/02/13,8402290249
- 8401190039 IE Info Notice 84-08, "10CFR50.7, 'Employee Protection '"
 Evc list encl.
 JORDANE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14. Consolidated Edison Co. of New
 York, Inc 115pp. 22365:141 24X Fiche: 50-000, 84/02/14, 8401190039
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Mestinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (fost 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp. 22366: 142, 24X Fiche 50-000, 84/02/15,8401190045
- 8401170062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below MenuPacturer Recommended Value." Evc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/21. Consolidated Edison Co. of New York, Inc. 116pp 22366:024 24X Fiche: 50-000, 84/02/21, 8401190052
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies,"

 Byc list encl.

 JORDAN,E L. Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/02/24. Consolidated Edison Co. of New

 York, Inc. 115pp. 22430:304 24X Fiche:50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Boft Seat Valve Seats."

 8vc list and J

 Division of Emergency Preparedness & Engineering Response (Fost 830103). 84/02/27. Consolidated Edison Co. of New York, Inc. 120pp. 22431:060 24X Fiche: 50-000, 84/02/27, 8401190067
- 8. Reportable occurrences, LERs & related correspondence
- 840214039B Requests add1 info re Part 21 rept dtd B3110B concerning wear ring failure in auxiliary feedwater pump furnished to facilities info requested within 25 days.
 POTAPQVB,U Region 4, Office of Director. B3/11/30 FATTY,D F, Bingham-Willemette Co ip. 22221:250. 24X Fiche. 50-000, 63/11/30, 640214039B.
- ~-8402140422 Supplemental Part 21 rept re wear ring failure in auxiliary feedwater pumps, per 831130 request for addl info, Wear rings will be replaced on returned units w/AIBI 420 wrought matl List of pumps in similar svc w/seme wear ring encl PATTY, D.F. Bingham-Willamette Co. 83/12/20. Region 4. Office of Director 2pp. 22221.251. 24X Fiche 50-000, 83/11/30, 8402140398

- 8402030274 RD 50/245/50-336/83-06 on 831115, level of activity in obstar samples exceeded control station average activity Caused by refueling & maint outages which normally result in add1 processing of liquid radwaste MROCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities). MROCZKA,E J Northeast Utilities 83/12/22 NURLEY,T E Region 1, Office of Director 3pp 22067 113 24X Fiche: 50-245,83/12/22,8402030274
- 8402070305 LER 84-003-00 on 840103, safety injection tanks 2 % 3 fell below min level During filling, valves closed Gaused by residual water collected in dry ref legs Tanks lowered, legs drained & instruments calibr W/840202 ltr BERGIN, J M. MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MROCZKA, E. J. Northeast Utilities 84/02/02 KURLEY, T. E., Region i. Office of Director 3pp. 22099 120 24% Fiche 50-336, 84/02/02, 8402070305
- 8402080251 LER 84-001-00, on 840106 & 09, random partial actuation occurred Cause unknown Operating parameters verified plant sys equipment restored to desired status W/840203 ltr DEBLANDEB, K D, MRDCZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MRDCZKA, E J Northeast Utilities 84/02/03 3pp 22130, 134 24X Fiche, 50-336, 84/02/03, 8402080251
- 8402100206 Updated LER 82-036/03X-1.on 820825, crack discovered in charging pump block A. Caused by high cycle fatigue failure. Destructive methods utilized & pump repacked W/B40206 ltr CRISCIONE, MROCZKA, E. J. Northeast Nuclear Energy Co (subs of Northeast Utilities). MROCZKA, E. J. Northeast Utilities. 84/02/06 3pp 22178.028, 24X Fiche 50-336, B4/02/06, 8402100206
- 8402150214 LER 84-002-00. on 840111; reactor tripped as level decreased to 38 5% & reached 37 2% During transient everage temp fell to 509 F & steam generator pressure fell to 740 psia Caused by freedwater regulating adjustments. W/840210 ltr 8TADNICK-8; MRCCZKA,E.J. Northeast Vuclear Energy Co (subs of Northeast Utilities) MRCCZKA,E.J. Northeast Utilities 84/02/10 3pp. 22241.005 24% Fichs 50-334.84/02/10,8402150214
- 8402150348 LER 84-002-00, on 840111, level in steam generator 1 increased Manual control initiated to stop increase & reactor tripped. Caused by adjustments made to new feedwater regulating control sys Valves closed W/840210 ltr.

 8TADNICK: 8. MRCCZKA, E. J., Northeast Nuclear Energy Co (subs of Northeast Utilities) MRCCZKA, E. J. Northeast Utilities 84/02/10 3pp. 22242,349 24X Fiche 50-336,84/02/10,8402150348
- B402170223 Updated LER 83-020/01x-1:on 830613,2,557 degraded tubes discovered on steam generator tubing. Cause undetermined. Tubes wiflews less than + or 40X through wall or eddy current probe restrications repaired W/840213 ltr.

 BLANCHARD.T. MROCZKA.E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MROCZKA.E.J Mortheast Utilities. B4/02/13 wpp. 22299:298 24X Fiche 50-336.84/02/13.84021/02/3.
- 8402220398 LER 84-004-00 on 840117, irregularities discovered in response of channels A & B of ex-core detectors Causad by reversed field inputs to detectors Both channels reversed, calibr & returned to svc. W/840216 ltr.
 FILBURN,T. Northeast Nuclear Energy Co (subs of Northeast Utilities), FILBURN,T., NROCKARE J Northeast Utilities 84/02/16. 3pp. 22334:303. 24X Fiche.50-336,84/02/16,8402220398

V. Operator Exeminations

8402160437 Submits info on operator training program re natural circulation cooldown, in response to Generic Ltr 81-21 & NRC 831020 request Program on RGS & upper vessel head voiding accomplished during accident mitigation training GOUNSIL,N G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL,N G. Northeast Utilities. 84/01/24. MILLER, J. R. Operating Reactore Branch 3, 3pp. 22268, 304. 24X Ficher 50-336, 84/01/24, 8402160437.

DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1

- F. Security, medical, emergency & fire protection plans
- 8402090033 Requests add1 info to conduct detailed review of plantspecific technical guidelines portion of procedures generation package (FOP) Add1 info should be provided as rev to POP per Suppl 1 to NUREC-0737 VAR9A:S A. Operating Reactors Branch 1. 84/01/25. STEWART,W L. Virginia Electric & Power Co. 4pp. 22189:190. 24X Fiche: 50-000: 64/01/25,8402090055.
- B402240084 Forwards amended pages to physical security plan Amended pages withheld (ref 10CFR73.21).

 STEMART, M. L. Virginia Electric & Power Co. 84/01/30 MCGUIRE, D.R. Division of Emergency Preparedness & Materials Safety.

 22375:009. 24X Fiche: 50-338, 84/01/30, 8402240084.

- 8402080062 Forwards "Reg Quide 1 97 Review," per NUREG-0737, Suppl 1
 Encl study performed to criteria of Reg Quide 1 97, Rev 3
 Mods identified in study will be completed by end of second
 refueling after Jul 1983
 STEMART, W L. Virginia Electric & Power Co 84/01/3; DENTON, H R
 Office of Nuclear Reactor Regulation, Director EISENHUT, D 0
 Division of Licensing 2pp 22128 002 24X Fiche 50-338,84/01/31,
 84020800062
- --8402080065 "Rag Guide 1 97 Revisu "
 * Virginia Electric & Power Co | 84/01/31 | 47pp | 22128 004 | 24X | Fiche 30-336, 84/01/31, 8402080062
- 8402080169 Forwards "Safety Parameter Display Sys SAR for NUREG-0576 Computer Project North Anna & Surry Nuclear Power Stations." per 830415 response to NUREG-0737, Suppl 1 STEWART, W. Virginia Electric & Power Co 84/02/08 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D Q Division of Licensing 2pp 22134 247 24% Fiche 50-000.84/02/08, 8402080169
- --8402080181 "Safety Parameter Display Sys SAR for NUREG-0676 Computer Project.North Anna & Surry Nuclear Power Stations " * Energy, Inc BAR-VEPCO-005 84/01/20 225pp 22134 249 24X Fiche 50-000.84/02/08.8402080169
- B402240012 Forwards changes to security personnel training k qualification program Changes withheld (ref 10CFR73 21) STEMART.W L Virginia Electric & Power Co. B4/02/08 MCOUIRE.D R Division of Emergency Preparedness & Materials Safety 22375 310 24X Fiche: 50-338, 84/02/08, 8402240012
- 8402280503 Confirms 840223 meeting at Region II ofc to discuss security programs at facilities, per 840207 telcon
 LEWIS,R C Division of Project & Resident Programs 84/02/22
 BTEWART,W L Virginia Electric & Power Co 1p 22407.100 24X
 Fiche: 50-000,84/02/22,8402280503
- 8402280241 Ack receipt of 840130 revised physical security plan Rev consistent w/provisions of 10CFR50 54(p) & acceptable LEWIB.R C Division of Project & Resident Programs 84/02/24 BTEMART.W L Virginia Electric & Power Co Spp 22397: 259. 24X Fiche 80-338,84/02/24,8402280241

O Adjudicatory correspondence

B402010222 Advises that SERs & impact appraisals in instant proceedings will be issued by end of Mar or early Apr 1784 due to delay in licensee response to request for addl info MCGURREN.H.J Hearing Branch 1 84/01/27. WDLFE.B.J. FERGUSON.G A, KLINE.J. Atomic Safety and Licensing Board Panel 1p. 22040 175 24X Fiche 50-338,84/01/27,8402010222

J. Insurance & indomnity information

- 8402060246 Endorsement 48 to NELIA Policy NF-240 & Endorsement 37 MAELU Policy MF-96. * Virginia Electric & Power Co. 84/01/13 2pp 22087·201. 24X Fiche.50-000.84/01/13.8402060246
- P. Operating license stage documents & correspondence
- 8402010274 Forwards "Conformance to NRR Generic Ltr B2-16, North Anna Power Station Units 1 & 2," technical evaluation rept Rept review indicates conformance to NUREQ-0737 item requirements. Amend will be issued within 14 days MILLER, J R Operating Reactors Branch 3 84/01/12 STEWART, W L Virginia Electric & Power Co 2pp. 22047: 258. 24% Fiche: 50-338, 84/01/12, 8402010276
- --8402010279 "Conformance to NRR Generic Ltr 82-16, North Anna Power Station Units 1 t 2." technical evaluation rept VANDERBEEK,R E0kG, Inc. FIN A-6600 E00-EA-6430 83/10/31 NRC No Detailed Affiliation Given 24pp. 22047 260 24X Ficha 50-338,84/01/12,8402010276
- 8402010277 Forwards evaluation of util response to Generic Ltr 82-28, "Inadequate Core Cooling Instrumentation Bys " Add1 info re existing core exit thermocouple & subcooling margin monitoring sys.per NUREG-0737 requested within 30 days. MILLER, J. R. Operating Reactors Branch 3 84/01/16. STEWART, W. L. Virginia Electric & Power Co 1ipp 22046-340. 24% Fiche. 80-338.84/01/16.8402010277.
- 8402130375 Forwards safety evaluation on NUREO-0737, Item II K 2, 17 re potential for voiding in RCS anticipated transients Issue of steam formation in RCS of Westinghouse plants adequately addressed Item resolved.

 MILLER, J R Operating Reactore Branch 3 84/01/24 BTEWART, W L. Virginia Electric & Power Co 9pp. 22216: 190 24X Fiche: 50-338,84/01/24,8402130375

- B402030444 Forwards response to NRC request for info re valve maint performed during 831007 & 1101 outage, consisting of list of exposures
 STEMARTIM L. Virginia Electric & Power Co 84/01/30 DENTON, H |
 - exposures STEWART.W.L. Virginia Electric & Power Co. 84/01/30 DENTON,H R Office of Nuclear Reactor Regulation. Director MELLER.J R Operating Reactors Branch 3 2pp 22066 275 24X Fiche 50-338.84/01/30.8402030444
- 8402030470 Responds to 840116 request for add1 info re imadequate core cooling instrumentation sys. Reactor vessel level instrumentation sys rept will be provided by 840222 Schedule to upgrade core exit thermocouples will be sent by 840323 STEMART,W L Virginia Electric & Power Co 84/01/30 DENTON.H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 1p. 22064 282 24X Fichs 90-338.84/01/30.8402030470
- 8402010410 Generic Ltr 84-04 to all operating PMR licensees, CP holders & applicants for CPs re safety evaluation of Hestinghouse topical repts dealing w/elimination of postulated pipe breaks in PMR primary main loops 8vc list encl EISENHUT. B D Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc. 57pp 22177.087 24X Fiche 50-000.84/02/01.8402010410
- 8402160600 Forwards Amends 50 & 34 to Licenses NPF-4 & NPF-7, respectively Amends reviso Tech Spec 6 2 2 re working hour guidelines to comply w/Generic Ltrs 82-02 & 82-12 ENQLE.1 B Operating Reactors Branch 3 84/02/01 STEWART, W L Virginia Electric & Power Co 3pp 22302 038 24X Fiche 50-338.84/02/01.8402160600
- --8402160605 Amends 50 & 34 to Licenses NPF-4 & NPF-7, respectively, revising Tech Spec 6 2.2 re working hour guidelines to comply w/deneric Ltrs 82-02 & 82-12 MILLER,J R Operating Reactors Branch 3 84/02/01 9pp 22302 041 24X Fichs 50-338,84/02/01.8402160600
- 8402150173 Forwards updated inservice testing programs for pumps & valves Addl update to be submitted by 840301. STEWART, W.L. Virginia Electric & Power Co. 84/02/02 DENTON, H.R. Office of Nuclear Reactor Regulation. Director MILLER, J.R. Operating Reactors Branch 3 172pp 22245, 344 24X Fichs-50-338, 84/02/02, 8402150173
- 8402100183 Forwards into re frequency of calibr.testing & training of operators for post-accident sampling sys.per 831216 BSER identifying open items in TM1 Item II B 3 STEMARTW L Virginia Electric & Power Co 84/02/03 DENTON: H R Defice of Nuclear Reactor Regulation, Director EISENHUT, D & Division of Licensing App 22182.184 24X Fiche 50-000.84/02/03, 8402100183
- 8402230405 Requests additinfore 831212 Tech Specifies for operability of turbine overspeed protection systeming volatile chemical treatment & systeming within monthly turbine valve testing envelops
 MILLER, J. R. Operating Reactors Branch 3 84/02/04 STEMART, W.L. Virginia Electric & Power Co. 2pp. 22380:040 24X
 Fiche 50-338,84/02/04.8402230405
- 8402170042 Porwards request for add1 info re 820701 & 0901 submittals per NUREO-0737. Item II D 1. "Performance Testing of Relief & Safety Velyes" Response requested within 60 days of ltr receipt W/o sncl
 MILLER, J R Operating Reactors Branch 3 84/02/08 STEWART. W L. Virginia Electric & Power Co ip. 22312 330 24X
 Fichs 50-338,84/02/08,8402170042
- 8402130267 Supple 830603 application to amend Licenses NPF-4 & NPF-7, adding description of post-accident sampling program to Section 6 re administrative controls; per NUREO-0737. Items II F I 2 & II B. 3
 BTEWART, W L Virginia Electric & Power Co 84/02/07 DENTON, H R Office of Nuclear Reactor Regulation. Director MILLER, J R Operating Reactors Branch 3 2pp. 22250.285 24X Fiche 80-338,84/02/09,8402150267.
 - 8402150279 Proposed Tech Spec changes adding description of post-accident sampling program to Section 4 re administrative controls, per NURES-0737, Items II F 1.2 & II.B 3
 - * Virginia Electric & Power Co 84/02/09 5pp 22250:287, 24X Fiche 50-338,84/02/09,8402150267.
 -)2280214 Reaffirms schedule for implementation of all Reg Guide 1 97 tems by second refueling outage in Jul 1985.List of items. Ixcluding in-core thermocouples, requiring add1 work to ichieve compliance encl.
 ITEWART.W L. Virginia Electric & Power Co. 84/02/21 DENTON, H R Iffice of Nuclear Reactor Regulation, Director. EISENHUT.D.0 ilyision of Licensing 7pp 22400-185 24X Fiche 50-000.84/02/21, 1402280214

- 8402280483 Provides supporting info to 831212 application to amend Licenses NFF-4 & NFF-7 re testing frequency of turbine overspeed protection sys.per NRC 840206 request Mestinghouse 1th recommending once per month surveillance encl STEWART.W L Virginia Electric & Power Co 84/02/21 DENTON, H R. Office of Nuclear Reactor Regulation Director MILLER.J R Operating Reactors Branch 3 6pp 22402 128 24X Fiche 50-338,84/02/21.8402280483
- B402270626 Notification of 840227 meeting w/util in Bethesda,MD to present bases for Tech Specs rev reducing number of flux mapping thimbles. ENGLE, B Licensing Branch 3 84/02/22 MILLER J R Licensing Branch 3 3pp 22412 357 24X Fiche 50-338,84/02/22,8402270626.
- O Inspection reports, IE Bulletins & correspondence
- B312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps" Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25. Consolidated Edison Co of New York Inc. 120pp 22058 001 24X Fiche 50-000.84/01/25.8312120153.
- B4D1190016 IE Info Notice B4-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Syr list and JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103), 84/02/03 Consolidated Edison Co. of New York, Inc. 117pp 22114 179, 24X Fichs 50-000.84/02/03.8401190016
- E401170017 IE Bullatin 84-01, "Cracks in BWR Mark I Containment Vent Headers" Bvc list encl. DEYRUND,R C Director's Office, Office of Inspection and Enforcement B4/02/03 Consolidated Edison Co of New York, Inc 102pp 22177
- B401190041 IE Info Notice B4-09. "Lessons Learned From NRC Inspa of Fire Protection Bafe Shutdown Bys (100FR50. App R) " Svc list uncl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/13. Consolidated Edison Co. of New York: Inc. 1245p. 22365-259 24X Fichs. 50-000.84/02/13, 8401490041
- B401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection.'"

 Svc list encl.

 JDRDAN.E.L. Division of Emergency Preparedness & Engineering
 Response (Post B30103) 84/02/14 Consolidated Edison Co of New

 York, Inc 115pp 22365,141 24X Fiche 50-000,84/02/14,8401190039.
- 8401170045 IE Info Notice 83-63, Suppl i, "Potential Failures of Hestinghouse Type 8A-1 Differential Helays," Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/15, Consolidated Edison Co. of New York Inc. 1389p, 22366 142, 24X Ficha 50-000,84/02/15,8401190045
- 8401170062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value," Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidate Edison Co. of New York, Inc. 116pp 22366:024 24X Fiche 50-000.84/02/21.8401190042
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies,"
 Bvc list encl.
 JURDANLE L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24. Consolidated Edison Co. of New
 York Inc 115pp 22430:304 24X Fiche 50-000 84/02/24, 8401190066.
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals." Svc list encl. JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/27. Consolidated Edison Co. of New York, Inc. 120pp. 22431:060 24X Fiche 50-000,84/02/27,8401190067
- S. Reportable occurrences, LERs & related correspondence
- 8402170317 Supplemental Part 21 rept re radiographic record evaluation, supplying add1 data to 830624 submittel Records show that 70 degree branch connections furnished to North Anna 1 & 2 jobsites, No nozzles supplied to Zimmer. Related info encl BORNES, R.P. Southwest Fabricating & Welding Co (subs. of IU International Corp.) 83/10/04. POTAPOUS U Region 4, Office of Director 6pp 22296;156, 24X Fiche. 50-000,83/10/04. 8402170317
- 8402170196 Final Part 21 rept re potential problem concerning radiography of brench connection welds covered by reinforcing pads Helds at Byron Braidwood & North Anna acceptable Weld 7 at Clinton reradiographed.
 BORNES.R P Southwest Fabricating & Welding Co. (subs. of IU International Corp.). 84/01/02 POTAPDYB.U. Region 4. Office of Director 2pp 22296.126 24X Fichs 50-000,84/01/02,8402170196

- 8402140186 Special Rept SP-NI-84-01 on B40109, following unit rampdown, I-131 dose equivalent specific activity exceeded 1 0 mcl/g Caused by minor fuel element defects in reactor core Reactor power change rates administratively limited HARRELL.E W Virginia Electric & Power Co 84/02/01 O'REILLY, J P Region 2. Office of Director App 22228 348 24% Fiche. 50-338.84/02/01.8402140186
- 8402140406 RD BP-NI-84-01 on 840109, I-131 dose equivalent specific activity exceeded Tech Spec limit Caused by minor fuel element defects in reactor core Primery coolant sampled & analyzed at accelerated frequency

 MARRELL, E.W. Virginia Electric & Power Co 84/02/01 0'REILLY, J.P. Region 2. Office of Director 16pp 22221 001 24X

 Fiche 50-338,84/02/01.8402140404
- 8402140277 LER 84-001-00 on 840109.plant shut down due to high RCS unidentified leakage Gaused by defective tubes & leaking tube plugs. Tubes plugged & leaking plugs repaired W/840208 ltr.

 HARRELL.E W Virginia Electric & Power Co 84/02/08 O'REILLY, J P Region 2, Office of Director 3pp 22227 168 24X Fiche: 50-338.84/02/08.8402140297
- 8402220009 LER 84-002-00 on 840118.RCS vented to containment atmosphere & single train inadvertent ECCB actuation occurred at 110 F during removal of solid state protection sys output fuses Caused by lack of procedural guidance W/840210 ltr. HARRELL, E W Virginia Electric & Power Co 84/02/10 3pp 2238.314 24X Fiche 50-338.84/02/10.8402220009.
- 8402220582 PNO-II-84-015 on 840216, workers clothing contaminated w/low rubidium levels when employees vented waste gas sys vol control tank Caused by waste gas compressor leak Morkers detained until rubidium activity decayed JENISON, K M . ELROD, 8 A. Region 2. Office of Director 84/02/16 p 22331.362 24% Fiche 50-338,84/02/16,8402220582
- B4022700B3 NPDEB noncompliance rept re 840214 oil spill Oil removed from lake w/ebeorbant matl No oil observed at containment boom scross cooling water discharge canal Caused by crack in weld of drive drain lubicant reservoir TAYLOR, J A. Virginia Electric & Power Co. 84/02/16 CHEWNING, R B Virginia, Commonwealth of, 2pp 22387: 349 24X Fiche. 50-338, 84/02/16, 8402270083.
- 8402280274 NPDES noncompliance notification on 840215.oil spill occurred near cooling water intake structure Caused by overflow.due to heavy rains.of tank containing oil used in fire fighting exercises. Cleanup underway TAYLOR.J A Virginia Electric & Power Co. 84/02/17 CHEHNING.R B Virginia, Comnonwealth of. 2pp 22397:072. 24X Fiche 50-338.84/02/17.8402280274
- DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2
- F Becurity, medical, emergency & fire protection plans
- B402090055 Requests addl info to conduct detailed review of plantspecific technical guidelines portion of procedures generation package (PGP).Addl info should be provided as rev to PGP per Buptl i to NUREO-0737 VARQA: 8.A. Operating Reactors Branch 1. 84/01/25 STEWART.W L Virginia Electric & Power Co. 4pp. 22187 170. 24X Fiche: 50-000.84/01/25.8402090055
- 8402240084 Forwards amended pages to physical security plan. Amended pages withheld (ref 10CFR73, 21)
 BTEMART. M. L. Virginia Electric & Power Co 84/01/30. MCGUIRE, D R. Division of Emergency Preparedness & Materials Bafety 1p 22375 009 24% Fiche 50-338, 84/01/30, 8402240084
- B402080062 Forwards "Reg Guide 1.97 Review," per NUREG-0737, Buppl 1 Encl study performed to criteria of Reg Guide 1 97, Rev 3. Mods identified in study will be completed by end of second refueling after Jul 1985 STEWART, W.L. Virginia Electric & Power Co B4/01/31, DENTON, H R. Office of Nuclear Reactor Regulation, Director EISENHUT, D G Division of Licensing 2pp 22128:002. 24X Fiche: 50-338, 84/01/31, B402080062
- --8402080045 "Reg Quide 1.97 Review."

 * Virginia Electric & Power Co 84/01/31. 47pg. 22128 004 24%
 Fiche: 50-338,84/01/31,8402080062
- 8402080169 Forwards "Safety Parameter Display Sys BAR for NUREG-0696 Computer Project, North Anna & Surry Nuclear Power Stations," per 830415 response to NUREG-0737, Suppl 1.

 STEMART, M L. Virginia Electric & Power Co. 84/02/08 DENTON, H.R. Office of Nuclear Reactor Regulation, Director Rpp 22134 247, 24% Fiche: 50-000, 84/02/08, 8402080169

- --8402080181 "Safety Parameter Display Sys SAR for NUREG-0696 Computer Project North Anna & Surry Nuclear Power Stations " * Energy, Inc SAR-VEPCO-005 84/01/20 225pp 22134 249 24X Fiche 50-000,64/02/08.8402080169
- B402240012 Forwards changes to security personnel training & qualification program Changes withheld (ref 10CFR73 21)
 BTEMART.W L Virginia Electric & Power Co 84/02/08 MCGUIRE, D R Division of Emergency Preparedness & Materials Safety 1p 22375 310 24% Fiche 50-33B, 84/02/08, 8402240012
- 8402280503 Confirms 840223 meeting at Region II ofc to discuss security programs at facilities.per 840207 telcon LEWIB, R C Division of Project & Resident Programs 84/02/22 STEMART.W L Virginia Electric & Power Co 1p 22407 100 24X Fiche 50-000,84/02/22,8402280505
- B402280241 Ack receipt of B40130 revised physical security plan Rev consistent w/provisions of 10CFR50 54(p) & acceptable LEWIS.R C Division of Project & Resident Programs 84/02/24 STEMART.W L. Virginia Electric & Power Co 3pp 22399 259 24X Ficho 50-338.84/02/24.8402280241

G Adjudicatory correspondence

- 8402010222 Advises that SERs & impact appraisals in instant proceedings will be issued by end of Mar or early Apr 1984 due to delay in licensee response to request for addl info MCGURREN, H J Hearing Branch 1 84/01/27 WULFE, 8 J, FERGUSON, 9 A, KLINE, J Atomic Safety and Licensing Board Panel 1p 22040 175 24X Fiche 50-33B,84/01/27,8402010222
- J Insurance & indemnity information
- 8402060246 Endorsement 48 to NELIA Policy NF-240 & Endorsement 37 MAELU Policy MF-96 * Virginia Electric & Power Co 84/01/13 2pp 22087 201 24X Fichs 50-000.84/01/13.8402060246
- P Operating license stage documents & correspondence
- B402010276 Forwards "Conformance to NRR Generic Ltr 82-16.North Anna Power Btation Units 1 & 2." technical evaluation rept Rept review indicates conformance to NURGE-0737 item requirements Amend will be issued within 14 days MILLER, J R Operating Reactors Branch 3 84/01/12 STEWART, W L Virginia Electric & Power Co 2pp 22047 258 24X Fichs 50-338.84/01/12,8402010276
- --8402010279 "Conformance to NRR Generic Ltr E2-16.North Anna Power Station Units 1 & 2." technical evaluation rept VANDERBEEK.R EG&O, Inc FIN A-6600 EGG-EA-6430 B3/10/31 NRC No Detailed Affiliation Given 24pp 22047 260 24X Fiche 30-338,84/01/12.8402010276
- B402010277 Forwards evaluation of util response to Deneric Ltr B2-28, "Inadequate Core Gooling Instrumentation Sys " AJd1 info re existing core exit thermocouple & subcooling margin monitoring sys.per NOREG-0737 requested within 30 days MILLER. J. R. Operating Reactors Branch 3 84/01/16 STEWART. W.L. Virginia Electric & Power Co. 11pp. 22046-340 24X Fiche 50-338.84/01/16,8402010277
- 8402130375 Forwards safety evaluation on NUREO-0737. Item II K 2 17 repotential for voiding in RCB anticipated transients Issue of steam formation in RCB of Westinghouse plants adequately addressed Item resolved MILLER, J R Operating Reactors Branch 3 84/01/24 BTEWART, W L Virginia Electric & Power Co 9pp 22216 190 24X Fiche: 50-339,84/01/24,8402130375
- 8402030470 Responds to 840116 request for add1 info re inadequate core cooling instrumenation sys Reactor vessel level instrumentation sys rept will be provided by 840222 Schedule to upgrade core exit thermocouples will be sent by 840323 STEWART, W. Virginia Electric & Power Co 84/01/30 DENTON, H R Operating Reactor Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 p 22066-262 24% Fiche: 50-338,84/01/30,8402030470
- 84020i04i0 Generic Ltr 84-04 to all operating PWR licensees. CP holders & applicants for GPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Svc list encl EISENHUT.D O Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc 59pp 22177 087 24X Fichs. 50-000, 84/02/01, 8402010410

- B402160600 Forwards Amends 50 & 34 to Licenses NPF-4 & NPF-7, respectively Amends revise Tech Spec & 2 2 re working hour guidelines to comply w/Generic Ltrs B2-02 & 82-12 ENGLE, L B Operating Reactors Branch 3 B4/02/01 STEWART, W L Virginia Electric & Power Co 3pp 22302 038 24X Fiche 50-338.84/02/01,8402160600
- --8402160605 Amends 50 & 34 to Licenses NPF-4 & NPF-7, respectively, revising Tech Spec 6 2 2 re working hour guidelines to comply w/deneric Ltrs 82-02 & 82-12 MILLERIJ R Operating Reactors Branch 3 84/02/01 9pp 22302 041 24X Fiche-50-338,84/02/01.8402160600
- 8402150173 Forwards updated inservice testing programs for pumps & valves Addl update to be submitted by 840301 STEWART.W L. Virginia Electric & Power Co. 84/02/02 DENTON.H R Office of Nuclear Reactor Regulation. Director MILLER.J R Operating Reactors Branch 3 172pp 22245 344 24X Fiche 50-338.84/02/02,8402150173
- 8402100183 Forwards info re frequency of calibr testing & training of operators for post-accident sampling sys, per 831216 SSER identifying open items in TMI Item II B 3 STEWART.W L Virginia Electric & Power Co 84/02/03 DENTON.H R Office of Nuclear Reactor Regulation. Director 4pp 22182 184 24X Fiche 50-000.84/02/03.8402100183
- B402230405 Requests addl info re 83:212 Tach Spac revs for operability of turbine overspeed protection sys using volatile chemical treatment & sys falling within monthly turbine valve testing envelope
 MILLER, J R Operating Reactors Branch 3 84/02/06 STEWART, W L Virginia Electric & Power Co 2pp 22380 040 24X
 Fiche 50-338,84/02/06,8402230405
- B402170042 Forwards request for addi info re 820701 & 0901 submittals per NUREO-0737. Item II D 1, "Performance Testing of Relief & Bafaty Valves " Response requested within 60 days of ltr receipt W/o encl HILLER. J R Operating Reactors Branch 3 84/02/08 STEWART, W L Virginia Electric & Power Co 1p 22312 330 24X Fiche 50-338, 84/02/08,8402170042
- 8402150267 Supple 830603 application to amend Licenses NPF-4 & NPF-7, adding description of post-accident sampling program to Section 6 re administrative controls per NUREG-0737. Items II F. 1 2 & II B 3 STEWART. W L Virginia Electric & Power Co 84/02/09 DENION, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 2pp 82250 285 24X Fiche 50-338,84/02/09.8402150267
- --8402150279 Proposed Yech Baec changes adding description of post-accident samoling program to Section 6 re administrative controls, per NUREG-0737, Items II F | 2 & II B. 3 w Virginia Electric & Power Co 84/02/09 5pp 22250 287 24X Fiche 50-338, 84/02/09, 8402150267
- 8402280214 Resffirms schedule for implementation of all Reg Quide 1 97 items by second refueling outage in Jul 1985 List of items. excluding in-core thermocouples, requiring add1 work to achieve compliance encl 8TEWART.W.L. Virginia Electric & Power Co 84/02/21 DENTON.H R. Dffice of Nuclear Reactor Regulation, Director 7pp 22400-185 24X Fiche 50-000,84/02/21,8402280214
 - O2280483 Provides supporting info to B31212 application to amend Licenses NPF-4 & NPF-7 re testing frequency of turbine overspeed protection system NRC 840206 request Westinghouse libr recommending once per month surveillance encl STEWART.W.L. Virginia Electric & Power Co. B4/02/21 DENTON.H R Office of Nuclear Reactor Regulation, Director MILLER, J. R Operating Reactors Branch 3 opp. 22402 128 24X Fiche, 50-338, 84/02/21, 8402880483
- 8402270526 Notification of 840227 meeting w/util in Bethesda. MD to present bases for Tech Specs rev reducing number of flux mapping thimbles ENGLE.L B Licensing Branch 3 84/02/22, MILLER J R. Licensing Branch 3 3pp 22412 357, 24X Fiche.50-338.84/02/22.8402270626.
- G. Inspection reports, IE Bulletins & correspondence
- 8312120133 IE Info Notice 84-04, "Steam Binding of Auxiliary Feedwater Pumps" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/01/25 Consolidated Edison Co of New York, Inc i20pp 22058 001 24X Fiche 50-000,84/01/25,8312120153

- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JURDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York Inc 119pp 22114 179 24X Fiche 50-000,84/02/03,8401190016
- B401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc 11st encl BEYDUNO,R C Director's Office, Office of Inspection and Enforcement B4/02/03 Consolidated Edison Co of New York, Inc 102pp. 22177 156 24X Fiche 50-000,84/02/03,8401190017
- 8401170041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Bafe Shutdown Bys (1007850, App R) " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Cb. of New York Inc 124pp 22365 259 24X Fiche 50-000.84/02/13.8401170041
- 8402280467 Ack receipt of 840120 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-339/83-34 DANCE: H C Division of Project & Resident Programs 84/02/13 STEMART: W L. Virginia Electric & Power Co 1p 22405 001 24X Fiche. 50-339. 84/02/13. 8402280467
- --8402280472 Responds to NRC 831222 ltr re violations noted in IE Insp. Rept 50-337/83-34 Corrective actions individuals involved in startup physics testing counseled Procedures will be modified by 840515
 STEMART.W L Virginia Electric & Power Co 84/01/20
 D'REILLY.J P Region 2, Office of Director 3pp 22405 002, 24x Fiche 50-339,84/02/13,8402280467
- --8402280477 Forwards 1E Insp Rept 50-339/83-34 on 831128-1202 & notice of violation
 DANCE H C Division of Project & Resident Programs 83/12/22 STEMART W L Virginia Electric & Power Cp 2pp 22405 005 24X Fiche 50-339,84/02/13,8402280467
- --9402280480 Notice of violation from insp on 831128-1202
 # Division of Project & Resident Programs 83/12/22 1
 22405 007 24X Fiche 90-339,84/02/13,8402280467
- --8402280484 IE Insp Rept 50-339/83-34 on 831128-1202 Violation notef boron sampling & rod worth measurement calculations not recorded as required DAVENPORT. K. E. Region 2. Office of Director JAPE, F. Division of Engineering & Operational Programs 83/12/20, 4pp 22405,008 24X Fiche 50-339,84/02/13,8402280467
- 8401170037 IE Info Notice 84-08, "100FR50 7, 'Employee Protection '"
 Svc list encl.
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14, Consultated Edison Co. of New
 York, Inc. 115pp 22365 141, 24X Fiche, 50-000, 84/02/14, 8401170039.
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Heatinghouse Type SA-1 Differential Relays " Svc list encl.
 JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc 118pp 22366 142, ZAX Fiche 50-000,84/02/15,8401190045
- 8401170062 IE Info Notice 84-10, "Motor-Derated Valve Torque Switches Bat Below Manufacturer Recommended Value " Svc list encl. JURDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co. of New York, Inc. 116pp 22366 024 24% Fiche 50-000.84/02/21,8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies"
 Svc list encl
 JOROAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co. of New
 York, Inc. 115pp 22430:304 24X Fiche. 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals." Eve list enc1 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/27 Consolidated Edison Co. of New York, Inc 120pp. 82431.060. 24X Fiche. 50-000.84/02/27, 8401190067.
- 9 Reportable occurrences, LERs & related correspondence
- 8402170317 Supplemental Part 21 rept re radiographic record evaluation, supplying add1 date to 830624 submittal Records show that 70 degree branch connections furnished to North Anna 1 & 2 jobsites No norzies supplied to Zimmer Related info encl.

 BORNES.R.P. Southwest Fabricating & Welding Co (subs of IU International Corp.) 83/10/04. POIAROUS.U. Region 4. Office of Director 6pg 22276 156 24X Fiche 50-000,83/10/04,8402170317

- 8402220154 Responds to FOIA request that 146 LERs be placed in PDR Forwards LERs listed on app Documents also available in PDR Remaining LERs were either canceled or not issued FELTON, J. M. Division of Rules and Records 83/11/30 JEFFERSON, 9 A Affiliation Not Assigned 2pp 22380 052. 24X Fiche 50-000, 63/11/30, 6402220154
- 8402170196 Final Part 21 rept re potential problem concerning radiography of branch connection welds covered by reinforcing pads Helds at Byron, Braidwood & North Anna acceptable Held 7 at Clinton reradiographed BDRNESS.R.P. Southwest Fabricating & Welding Co. (subs. of IU International Corp.) 84/01/02. POTAPDVS.U. Region 4, Office of Director 2pp 22276 126 24X Fiche 50-000.84/01/02.8402170196
- 8402220392 PNO-II-84-015 on 840216, workers clothing contaminated w/low rubidium levels when employees vented waste gas sys val control tank. Caused by waste gas compressor leak Morters detained until rubidium activity decayed JENIBON. K M . ELROD. 9 A Region 2. Office of Director 84/02/16 ip 22331 362 24X Fiche 50-338,84/02/16,8402220582
- 8402270083 NPDES noncompliance rept re 840214 oil spill Dil removed from lake w/absorbant mat! No oil observed at containment boom across cooling water discharge canal Caused by crack in weld of drive drain lubicant reservoir TAYLOR, J A Virginia Electric & Power Co 84/02/16 CHEWNING, R B Virginia, Commonwealth of, 2pp 22387 349 24x Fiche: 50-338.84/02/16.8402270083
- 8402280274 NPDES noncompliance notification on 840215.cil spill occurred near cooling water intake structure Caused by overflow due to heavy rains, of tank containing oil used in fire fighting exercises Cleanup underway TAYLOR, J A Virginia Electric & Power Co 84/02/17 CHEWNING, R B Virginia, Commonwealth of. 2pp 22399 072 24X Fiche: 50-338,84/02/17,8402280274
- DOCKET 50-941 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8402090003 Responds to FDIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel asetings Forwards App A.B & C documents
 FELTON.J M. Division of Rules and Records 83/10/31
 ROBENBAUM.D.M. Technical Analysis Corp 17pp. 22193 272 24X
 Fiche: 50-000,83/10/31,8402090003
- ---B402090147 Trip rept of Caseload Forecast Panel 810929-1001 site visits re const status observation & scheduled completion date Related info encl
 KINTHER.L. L. Licensing Branch 1 81/11/24 Licensing Branch 1 Bpp. 22194.297. 24X Fiche:50-000.83/10/31,8402090003
- 8402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILK. B. J Office of the Secretary of the Commission 83/12/14 Public Document Branch 1p 22281.023 24X Fiche 50-000,83/12/14,8402160003.
- --8402160384 Staff requirements memo re 821216 discussion/possible vote on contested issues in full-power proceeding in Washington, DC CHILK, S. J. Office of the Secretary of the Commission 82/12/20 ZERBE, J E Office of Policy Evaluations, BICKWIT, L. Office of the General Counsel, 1p 22281.251 24X Fiche 50-000, 83/12/14, 8402160003.
- 8402010263 Requests add1 info re proposed implementation of independent safety engineering program YCKROBLOOD, B J. Licensing Branch i, 84/01/17 TAUBER, H Detroit Edison Co. 2pp 22046 357. 24X Fiche 50-341/84/01/17/8402010263
- 8402100167 Resubmits Nov 1982 draft offsite dose calculation manual for revise Response by 840227 requested JENS, W.H. Detroit Edison Co. 84/02/06 YOUNGBLOOD, R.J. Licensing Branch 1, 2pp. 22182 210, 24X Fiche: 50-341, 84/02/06, 8402100169.
- --8402100174 Draft "Offsite Dose Calculation Manual "

 Detroit Edison Co 82/11/30, 78pp 22182 212, 24x
 Fichs: 50-341,84/02/06,8402100169
- 8402210143 Forwards add1 info re environ qualification submittal of harsh environ safety-related electrical equipment, in response to NRC B31201 request. JENS.W.H. Datroit Edison Co. 84/02/14 YOUNGBLOOD, 8 J. Licensing Branch 1. 5pp 22317:212 24X Fiche, 50-341, 84/02/14, 8402210143.

- 8402220038 Informs that util has modified plans for radchem staffing Structure of radchem organization described in Section 13 1 4 3 & Figure 13 1-4 of FSAR Info supersedes commitments in 810603 ltr
 JENS.W H Detroit Edison Co 84/02/16 YOUNGBLOOD, B J Licensing Branch 1 lp 22337 241 24X Fiche 50-341,84/02/16,8402220038
- 8402270090 Forwards revised pages to Vols 1-5 of long-term program plant-unique analysis rept Approval documented in SSER 3 JENS.W H Detroit Edison Co 84/02/21 VQUNGBLOOD.B J Licensing Branch 1 3pp 22387 090 24X Fiche 50-341/84/02/21/8402270090
- --8402270096 Rev 1 to Vol 1 to. "Plant-Unique Analysis Rept, General Criteria & Load Methodology " EDMARDS,N V . STEINERT, L D NUTECH Engineers, Inc. DET-04-028-1 R01 83/11/30 10pp 22387 093 24X Fiche 50-341,84/02/21, 8402270090
- --8402270098 Rev O to, "Response to NRC Questions on Fermi 2 Plant-Unique Analysis Rept " STEINERT, D , BASKIN.J L , KUMAR.V J NUTECH Engineers, Inc DET-04-028-14 ROO 83/11/30 107pp 22387 113 24X Fiche 50-341.84/02/21.8402270090
- --8402270103 Rev i to Vol 2, to "Plant-Unique Analysis Rept, Suppression Chamber Analysis " EDWARDS, N W, STEINERT, L D NUTECH Engineers, Inc DET-04-028-2 RO1 83/11/30 lipp 22387 209 24% Fiche 50-341,64/02/21, 8402270090
- --8402270106 Rev 1 to Vol 3, to "Plant-Unique Analysis Rept.Vent Sys Analysis" EDWARDS, N W , STEINERT, L D NUTECH Engineers, Inc DET-04-028-3 RO1 83/11/30 12pp 22387 220 24X Fiche 50-341,84/02/21,8402270090
- --8402270109 Rev 1 to Vol 5.to "Plant-Unique Analysis Rept, Safety Relief Valve Piping Analysis " EDWARDS.N W., STEINERT, L. D. NUTECH Engineers, Inc. DET-20-015-5 RO1 83/11/30 App. 22387 232 24X Fiche 50-341,84/02/21, 8402270090
- 8402290406 Forwards Amend 3 to CPPR-87, safety evaluation & notice of issuance & availability Amend reflects change in shares of ownership between util & Woolverine Power Supply Cooperative, Inc EIBENHUT, D 9 Division of Licensing 84/02/21 JENS, W Detroit Edison Co 3pp 22438 211 24X Fiche 50-341,84/02/21,8402290406
- --8402290408 Amend 3 to CPPR-87, reflecting change in shares of ownership between util & Woolverine Power Supply Cooperative, Inc EISENHUT, Do Division of Licensing 84/02/21 2pp 22438:214 24X Fiche 50-341.84/02/21.84022
- --B402290409 Befety evaluation supporting Amend 3 to CPPR-87. LYNCH, M D., YOUNGBLOOD, B J. Licensing Branch 1 84/02/06 3pp 22438 216 24% Fiche 50-341.84/02/21.8402290406
- ---8402290413 Notice of issuance & availability of Amend 3 to CPPR-87 YOUNGBLOOD.B.J Licensing Branch 1 84/02/21 2pp 22438:217 24X Ficha 50-341,84/02/21,8402290406
- 8402230132 Forwards Amend 53 to amended & substituted application for licenses, consisting of Amend 53 to FBAR LANDGRAF, L. C. LeBoeuf, Lamb, Leiby & Hackae 84/02/22 DENTON: H. Office of Nuclear Reactor Regulation, Director 1p. 22366, 262. 24X Fiche 50-341,84/02/22,8402230152
- --8402230159 Amend 33 to amended & substituted application for licenses HEIDEL.C M Detroit Edison Co 84/02/13 ip. 22366 263. 24X Fiche: 50-341,84/02/22,8402230152
- E NRC Safety Evaluation Report (SER), supple & correspondence
- B402270090 Forwards revised pages to Vols 1-5 of long-term program plant-unique analysis rept Approval documented in SBER 3 JENG. H Betroit Edison Co 84/02/21 VOLNGBLOOD, B J Licensing Branch 1 3pp 22387 090 24X Fiche 50-341.84/02/21,8402270090
- F Becurity, medical, emergency & fire protection plans
- 8402070333 Responds to util 830414 & 0627 ltrs requesting exception for distance of backup or alternate emergency operations facilities Util position acceptabls EIBENHUT.D 9 Division of Licenseing 84/01/31 JENS, W. Detroit Edison Co 2pp 22141.322 24X Fiche 50-341,84/01/31,8402070533

- 8402060006 Forwards IE Safeguards Insp Rept 50-341/84-02 on 840110-13 No nuncompliance noted AXELSBN.W L Region 3. Office of Director 84/02/01 WELLS,D A Detroit Edison Co 2pp 22087 188 24X Fiche 50-341,84/02/01,8402060006
- ---8402060009 IE Safeguerds Insp Rept 50-341/84-02 on 840110-13 No noncompliance noted Mayor areas inspected security plan & implementing procedures, security organization -- mgt & security program audit Details withheld (ref 10CFR73 21) MADEDA,T J, STAPLETON,I W, CREED,J R. Region 3, Office of Director 84/02/01 2pp 22087 190 24X Fiche 50-341,84/02/01,8402060006
- 8402060390 Ack receipt of 840105 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Rept 50-341/83-24 PAPERIELLO.C J Region 3. Office of Director 84/02/01 WELLS.D A Detroit Edison Co 2pp 22087 078 24% Fiche 50-341.84/02/01. Ban2bA0390
- --B402060395 Responds to NRC B3112B ltr re violations noted in IE
 Emergency Preparedness Appraisal Rept 50-341/B3-24
 Corrective actions 30 & 60 minute augmentation of emergency
 personnel will be satisfactorily demonstrated
 JENS.W H Detroit Edison Co B4/01/O4 PAPERIELLO.C J Region
 3. Dffice of Director 46pp 22087 080 24X
 Fiche 50-341.84/02/01.8402040390
- B402160874 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per 810709 Generic Ltr 81~27 W/o request, entire plan will be placed in PDR VOUNDBLOOD, B J Licensing Branch 1 84/02/07 JENS, W Detroit Edison Co 2pp 22302 122 24X Fiche 50-341,84/02/07,8402160574
- B402280327 Revised radiological emergency response preparadness implementing procedures, including Procedure EP-210-2 re offsite radiological emergency team Cancelled Procedures EP-202-1 & 2 should be destroyed W/840224 ltr
 JENS.W H Detroit Edison Co B4/02/09. YOUNOBLOOD, B J. Licensing Branch 1 41pp 22398 222 24X Fiche 50-341,84/02/09,8402280327
- 8402270243 Forwards responses to items requiring resolution resulting from NRC review of radiological emergency response preparedness plan published in Suppl 3 of NUREG-0798 Items reviewed w/F Kantor of NRC, in 840201 telcon JENS, W H Detroit Edison Co 84/02/23 YOUNDBLODD, B J Licensing Branch I 28pp 22386 196 24X Fiche 50-341,84/02/23,8402270243
- J. Insurance & indemnity information
- 8402030427 Forwards Endorsement 104 to NELIA Policy NF-72 HATHAMAY.O H Detroit Edison Co 84/01/31 DINTIZ.I Office of Nuclear Reactor Regulation, Director 2pp 22068 361 24X Fiche, 50-341, 84/01/31, 8402030427
- M Utility Final Safety Analysis Report (FSAR) & amends
- 8402230152 Forwards Amend 53 to amended k substituted application for licenses, consisting of Amend 53 to FBAR.
 LANDGRAF, L. C. LeBbeuf, Lamb, Leiby & MacRae 84/02/22 DENTON, H Office of Nuclear Reactor Regulation, Director 1p 22366 R62, 24% Fiche 50-341,84/02/22,8402230152
- --8402230187 Amend 53 to amended & substituted application for licenses, HEIBEL, C M Detroit Edison Co 84/02/13 ip 22366; 263 24X Fiche 50-341, 84/02/22, 8402230132
- --8402230166 Amend 53 to FBAR. # Detroit Edison Co 84/02/29. 418pp. 22366 264 24X Fiche 50-341.84/02/22,8402230152
- G Inspection reports, IE Bulletins & correspondence
- 8402020254 Forwards IE Insp Rept 50-941/83-28 on 831128-840105 & notice of violation STREETER, J. F. Region 3, Office of Director 84/01/18, WELLS, D.A. Detroit Edison Co. 2pp. 22055 289, 24X Fiche. 50-341, 84/01/18, 8402020254
- --8402020258 Notice of violation from insp on 831128-840105. STREETER, J. F. Region 3, Office of Director 84/01/18, ip. 22055, 291. 24X Fiche: 50-341,84/01/18,8402020234.

- --8402020267 IE Inap Rept 50-341/83-28 on 831128-840105 Noncompliance noted failure to preclude repetition of intrusion of foreign matl into GA Level 1 piping sys & Preoperational Procedure 83100 001 inappropriate DUPONT.S.O. REYESL. A Region 3, Office of Director 84/01/17 7pp 22055 292 24X Fichs 50-341,84/01/18,8402020254
- 8312120153 IE Info Notice 84-06. "Steam Binding of Auxiliary Feedwater Pumps " Bvc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25.8312120153
- 8402080338 Requests extension of final reporting data for response to IE Bulletin 63-04 re Tubeline products to 840430 Add1 time needed to complete in-depth search & review No evidence of Tubeline products found to date WELLS.D A Detroit Edison Co 84/01/30 KEPPLER, J Q. Region 3, Office of Director 2pp 22130 323 24X Fiche 50-341,84/01/30, 8402080338
- 8402060006 Forwards IE Bafeguards Insp Rept 50~341/84~02 on 840110~13 No noncompliance noted. AXELEDN: W.L. Region 3. Office of Director 84/02/01 WELLS, D. A Detroit Edison Co 2pp 22087 188 24X Fiche 50~341, 84/02/01, 8402060006
- --8402060007 IE Bafeguards Insp Rept 50-341/84-02 on 840110-13 No nancomplience noted Major areas inspected security plan & implementing procedures, security organization mpt & security program audit, Details withheld (ref 10CFR73 Z1) MADEDA: J J STAPLETON, B W CREED. J R Region 3. Office of Director 84/02/01 2pp. 22087 170 24X Fiche 50-341,84/02/01,8402060006
- B402040390 Ack receipt of 840105 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Rept 50-341/83-24 PAPERIELLO, C. J. Region 3, Office of Director 84/02/01, HELLB, D. A. Detroit Edison Co. 2pp. 22087 078 24X Fiche 50-341,84/02/01, 8402060390
- --8402060898 Responds to NRC 831128 ltr re violations noted in IE
 Emergency Preparedness Appreisal Rept 50-341/83-24
 Corrective actions:30 % 60 minute augmentation of emergency
 personnel will be satisfactorily demonstrated.
 JENN.W H Detroit Edison Co 84/01/04 PAPERIELLO, C. J. Region
 3, Office of Director 46pp 22087.080 24X
 Fiche. 50-341,84/02/01,8402060390
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls," Svc list encl.
 JORDAN,E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co. of New York, Inc. 119pp. 22114-179. 24X Fiche 30-000,84/02/03,8401190016
- 8401170017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers." 8vc list encl DEYOUND.R.C Director's Office, Office of Inspection and Enforcement. 84702/03 Consolidated Edison Co of New York, Inc 108pp 82177.156. 24X Fiche.50-000.84/02/03,8401170017
- 8402080204 Forwards SALP Rept 50-341/83-32 for Oct 1982 Bept 1983. Negative indications identified in preoperational testing program KEPPLER.J Q Region 3. Office of Director 84/02/06 WELLS.D.A Detroit Edison Ca. 2pp 22130-162. 24X Fiche: 50-341, 84/02/06. 8402080204.
- --8402080208 BALF Rept 50-341/85-32 for Oct 1982 Bept 1983. % Region 3, Office of Director 84/02/06 26pp 22130,164. 24X Fiche: 50-341,84/02/06,8402080204.
- --B4020B0210 Forwards preliminary BALP rept & summary of significant findings. H/o BALP rept.
 HIND. J A Division of Radiological & Materials Bafety Programs.
 83/12/07 HeLLS, D A Detroit Edison Co 3pp. 22130:190. 24X
 Fiche 50-341.84/02/06.8402080204
- --8402080213 Forwards comments on SALP 4 rept & on discussions w/BALP Board during 831214 meeting in Glen Ellyn, IL. WELLS.D.A. Detroit Edison Co. 83/12/29. HIND, J.A. Division of Radiological & Materials Bafety Programs. 5pp. 22130:193. 24X Ficher 50-341,84/02/06,8402080204
- B401190041 IE Info Notice 84-09. "Lessons Learned From NRC Insps of Fire Protection Bafe Shutdown Bys (100FR50, App R)." Byc list encl.

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). B4/02/13 Consolidated Edison Co of New York Inc. 124pp. 22345:259. 24X Fichs. 50-000.84/02/13.8401190041.

- 8401170037 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection "
 - Byc list encl
 JORDAN, Et. Division of Emergency Preparedness & Engineering
 Rasponse (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp. 22365-141 24X Fiche-80-000,84/02/14,8401190039
- 8401190045 IE Info Natice 83-63, Suppl 1: "Potential Failures of Westinghouss Type SA-1 Differential Relays." Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York. Inc. 118pp 22366 142 24X Fiche 50-000,84/02/15,8401190048
- 8402220433 Ack receipt of 840206 ltr informing NRC of steps taken to correct violations moted in IE Imap Rept 50-341/83-21

 BPEBBARD.R L Division of Engineering 84/02/15 WELLS.D A Datroit Edison Co 1p. 22339:001 24% Fiche 50-341.84/02/15.
- --B40222043B Responds to NRC B31021 ltr re violations noted in IE Insp Rept 50-341/83-21 Corrective actions BA/GC support improved by reassigning GC inspectors to shifts to provide 24 h coverage of preoperational testing JENS,W H. Detroit Edison Co. 84/02/06 BPESBARD,R L Division of Engineering. 117pp. 22339 002 24X Fiche 50-341.84/02/13, 8402220433.
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switchss Bet Below Manufacturer Recommended Value " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp. 22366 024 24X Fichs 50-000,84/02/21,8401190062
- 8402280564 Ack receipt of 840209 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-341/83-20 NORELIUS: C E. Division of Project & Resident Programs 94/02/23 HELLS, D.A. Detroit Edison Co. ip 22406-279. 24X Fiche: 50-341,84/02/23,8402280564
- --8402280568 Forwards amended response to NRC 831104 ltr re violations noted in IE Insp Rept 50-341/83-20 Corrective actions Btartup Instruction B I B. 4, 2, 03 revised to require that prerequisities be verified prior to supplemental testing WELLB, D A. Detroit Edison Co. 84/02/09 NORELIUS, C E. Division of Project & Resident Programs. 14pp 22406 300 24X Fiche 30-341,84/02/23,8402280544
- 8402290222 Ack receipt of 840217 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-341/83-28 BTREETER, J. F. Region 3, Office of Director 84/02/23 WELLS, D.A. Detroit Edison Co. 1p 22425,277 24X Fiche 50-341,84/02/23,8402290222
- --8402290228 Responds to NRC 840118 ltr re violations noted in IE Insp. Rept 80-941/83-28. Corrective actions testing terminated & Test Exception Disposition Rept 29 initiated deferring testing of applicable procedure until air line reconnected JENS, H. H. Detroit Edison Co. 84/02/17 BTREETER, J. 9 Region 1, Office of Director, 7pp. 22425:280 24X Fiche. 50-341, 84/02/23, 8402290222.
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies"
 Byc list encl.
 JOHDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103), 84/02/24. Consolidated Edison Co. of New
 York, Inc. 115pp. \$2430:304, 24X Fiche 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Besls "
 Svc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/27. Consolidated Edison Co. of New
 York, Inc. 120pp. 22431:060. 24X Fiche 50-000.84/02/27,8401190067
- S. Reportable occurrences, LERs & related correspondence
- 8402130444 Final deficiency rept, Item 93 re RHR HX calculation arror Initially reported on 830406. Contractor completed mod & reworked beffle plates of HX to achieve required design Flow. HeLLS,D A. Detroit Edison Co. 84/02/02 REPPLER.J G Region 3 Office of Director. Spp. 22202.058, 24X fiche: 50-341,84/02/02,8402130444.
- 8402130443 Deficiency rept. Item 109 re broken valve stem on 24-inch glabe valve & pilot pin. Initially reported on 840103 New parts ordered Next rept will be submitted when further info ALEBBI.T, A Detroit Edison Co. 84/02/03, KEPPLER, J Q. Region 3, Office of Director, 3pp. 22202-100 24X, Fiche. 50-341, 84/02/03.

- B402270018 Interim deficiency rept. Item 111 rs design defect on RHR reservoir freeze over Initially reported on 840104 Util assessing situation & will add any squipment instructions & pracedures necessary to prevent ice buildup MELLS, D A Detroit Edison Co B4/02/06 KEPPLER, J G Region 3, Office of Director Jpp 22391 272 24X Fiche 50-341.84/02/06, 8402270018
- 8402150259 PNO-III-84-015 licenses evaluating potential problem re use of commercial grade equipment in safety-related applications Procedures may be developed to test & qualify mati VANDEL.T E , HUNTER.D R , STREETER.J F Region 3, Office of Director 84/02/10 ip 22250 ii4 24% Fiche 50-341,84/02/10, 8402150259
- 8402270286 Final deficiency rept. Item 87 re Reactor Controls. Inc control rod drive installation measurements Initially reported on 830311 Caused by measurements recorded incorrectly or measurements exceeding tolerance HELLS.D A Detroit Edison Co 84/02/10 KEPPLER.J O Region 3. Office of Director 2pp 22427 182 24X Fiche 50-341.84/02/10.8402270286
- 8402290187 Interim Deficiency Rept. Item 110 re linear cracking in side-to-back bends in struts mfg by Unistrut Initially reparted on 840104 Test results provided by Unistrut under review Corrective actions will be sent when info available WELLS.D A Detroit Edison Co. 84/02/17 KEPPLER.J G Region RELLS DA Detroit Edison Co 84/02/17 KEPPLER, J G Region 3 Office of Director 2pp 22428 156 24% Fiche 50-341.84/02/17, 8402290157
- 8402270248 Interim deficiency rept. Item 107 re broken valve stem on 24-inch globe valve & pilot pin Initially reported on 840103 Breakage may be due to fatigue failure Evaluation in progress.
 WELLS, D H Detroit Edison Co 84/02/17 KEPPLER, J 0 Region 3, Office of Director 2pp 22427 306 24X Fiche 50-341,84/02/17,
- 8402290267 Deficiency rept. Item 112 re poor quality of vendor crimped wiring connections in emergency diesel generator control panel Initially reported on 840113 Insp of connections being performed & documented WELLS.D A Detroit Edison Co 84/02/17 KEPPLER.J Q Region 3. Office of Director 2pp. 22424 287 24% Fiche 50-341.84/02/17.8402290267
- T Hearing transcripts on non-antitrust matters
- B402270302 Partial response to FOIA request for five categories of documents re mothballed nuclear const projects App A documents being placed in PDR. Document as listed on App B already available in PDR, Bearch continuing.
 FELTON, J M Division of Rules and Records 64/01/20 BELL, N Nuclear Information & Resource Bervice 3pp 22395 200 24X Fichs. 50-000, 84/01/20, 8402270302
- --8402270321 Testimony of JB Martin before Subcommittee on Energy Conservation & Power re nuclear power plants being constructed by WPPBS Related info encl MARTIN J B. Region 3. Office of Director 83/09/14, 86pp 22395 104 24X Fichs 50-000.84/01/20,8402270302.

DOCKET 50-344 TROJAN NUCLEAR PLANT

- F Becurity, medical, emergency & fire protection plans
- 8402270001 Further response to FOIA request for NRC records resscurity violations & safeguards events at nuclear facilities Forwards App A documents App B documents partially withheld (raf FOIA Exemptions 3,4 & 6) App A documents also in PBR FELTON.J M Division of Rules and Records 83/12/12, GOLDENBERG, G. Scripps-Houard Newspapers App 22413 098 24X Fiche 50-344,83/12/12,8402270001
- --8402270024 IE Insp Rept 50-344/79-IB on 791107-09 No noncompliance noted Major areas inspected physical security including access controls lock & key security & review of investigation efforts re controlled substances.

 BCHUSTER.M D., SHACKLETON.O.C Region 5. San Francisco. Office of the Director NORDERHAUG, L R Region 5. San Francisco. Bafeguards Branch 79/11/21 Spp 22413 106, 24X Fiche 50-344.83/12/12.
- --8402270027 Requests Bargent GS Merkovich upcoming evaluation of physical security at plant & 791105 rept of arrests of facility guards involved w/narcotics ENGELKEN, R H NRC No Datailed Affiliation Given 79/11/21 WILLIAMB, J. C. Oragen, State of ip 22413 111 24X Fiche 50-344, 83/12/12, 8402270001

- --B402270043 Forwards undercover officer rept on evaluation of security at plant Repts dealing w/criminal prosecution will not be released w/o sanction of Columbia County District Atty News articles encl
 WILLIAMS.J C Dregon. State of 79/12/04 ENGELKEN.R H Region 5. Ban Francisco. Office of the Director 7pp 22413 112 24X Fiche 50-344.83/12/12,8402270001
- --8402270054 Forwards Oregon State Police officer 791121 rept re facility security sys W/o rept Related info encl SCHUGIERM D Region 5, San Francisco, Office of the Director 79/12/07 CHAPELL.D R Division of Safeguards Inspections 2p; 22395 091 24X Fiche 50-344,83/12/12,8402270001.
- --8402270080 IE Insp Rept 50-344/79-20 on 791126-1212 Noncompliance noted failure to control access to protected & vital areas of site Info deleted (ref 10CFR2 790) MORTENBEN.H P , 8CHUSTER.H D , 8CHASEFER.D W Region 5, San Francisco. Office of the Director 80/02/15 30pp 22413 127 24X Fiche 50-344,83/12/12,8402270001
- --B402270091 Notice of violation from insp on 791125-30 & 1211-12 Burns employee granted visitor unauthorized access to protected areas on 791014 Info deleted (ref 10CFR2 790) ** NRC No Datailed Affiliation Given 80/02/13 2pg 22413 161 24X Fiche 50-344,83/12/12.8402270001.
- --8402270105 Forwards samitized responses to notice of yielation & notice of proposed imposition of civil penalties WILLIAMS. J. Portland General Electric Co 80/03/07. STELLO, V Office of Inspection & Enforcement, Office of the Director 9pp. 22413-164 24X Fiche 50-344,83/12/12,8402270001.
- --8402270126 Forwards Region V memo describing several safeguards problems at facility Licensee failed to complete installation of security equipment by dates previously accepted by NRR Requests to be informed of plans, CHAPELL, D. R. Division of Bafeguards Inspections 80/01/31, NCCORMLE, O. W. Physical Security Licensing Branch 19. 22413 179 24X Fiche:50-344,89/12/12,8402270001
- --8402270136 Forwards proposed civil penalty enforcement package resulting from unannounced physical security insp on 791126-30 & 1211-12. Security enforcement history & proposed press release also forwarded. M/o and ENGELKEN.R H Region 5. San Francisco, Office of the Director 79/12/31 HOMARDLE M Division of Safeguards Inspections. 2pp 22375 093 24% Fichs. 50-344,83/12/12,8402270001.
- -8402270146 Advises that licentee adjusted expected completion detes for portions of approved security plan NRR-approved schedula located in App B of security plan info dejeted Three-up enforcement history encl MDRTENSEN.
- 3402070285 Forwards listed features re design of new emergency operations facility consistent w/Suppl 1 to NUREG-0737, Item III.A 1 2 Facility will be completed a operational by 861231
 WITHERS, 8 D Portland General Electric Co 84/01/27 EIBENHUT, D. Q Division of Licensing 2pp 22079 123. 24X Fiche: 50-344,84/01/27,8402070285
- 402130318 Revised emergency implementing procedures, including Rev 7 to Procedures EP-16 re drill & exercises & EP-18 re fire fighting.

 OLMSTEAD, C A Portland General Electric Co. 84/01/30 32pp
 22197 150. 24X Fiche: 50-344:84/01/30.8402130318.
- 8402220431 Forwards Rev 8 to security plan, deleting assistant vice-president position & indicating responsibility for background security acreening transferred to corporate security dept Rev Withheld (ref 100FR73, 21)
 WITHERS, B D Portland General Electric Co 84/02/01, MARTIN, J B, Region 5, Office of Director, 2pp 22340-157, 24X
 Fiche, 50-344, 84/02/01, 8402220431
- 8402230333 Advises that NRC will not review emeragnacy plans to delete privacy or proprietary info unless specifically requested by licenses, per 810709 Ceneric Ltr 81-27 W/o request, entire plan will be placed in FDR MILLER, J R. Deparating Peactors Branch 3. 84/02/06. WITHERS, 8 D Portland Ceneral Electric Co. 2pp. 22371 233. 24X Fiche 50-344,84/02/06.8402230333.

9 Adjudicatory correspondence

- 8402010195 Answer supporting Coalition for Safe Power 840105 request for hearing & petition for leave to intervene re spent fuel pool amond request Commission and under 10CFR2 714 satisfied Certificate of Svc encl GOLDBERG, J R Hearing Branch Q 84/01/24 Atomic Bafety and Licensing Board Panel 10pp 22042 259 24X Fiche 50-344,84/01/24,8402010196
- 8402010204 Answer to State of GR petition for leave to intervens & request for hearing re add1 spent fuel pool storage State of GR should be made full party to proceeding contingent upon submission of at least one admissible contention GOLDSERG, J. R. Hearing Branch & 84/01/24 Atomic Bafety and Licensing Board Panel 10pp 22040 335 24X Fiche 50-344,84/01/24,8402010204
- B402010254 Notice of appearance in proceeding. Certificate of Svc encl ODLDBERO, J. R. Hearing Branch 2. B4/01/24 ip. 22041 361 24X Fichs 50-344,84/01/24,8402010254
- 8402140214 Forwards 840206 ltm from licensee to J Hiller reconsiderations which affect schedule for application to expand spent fuel storage Certificate of Svc encl JOHNSON, R. W. Portland General Electric Co 84/02/09, SMITH, I.W., MORRIS, P.A., PARIS, D.H. Atomic Bafety and Licensing Board Pansl. App. 22200 003 24X Fiche 50~344,84/02/09,8402140214
- 8402150131 Memorandum & order that petitioners, State of QR & Coalition for Safe Power, file respective supplemental & amended petitions & that licensee & NRC staff file respective answers MCRRIS.P A , PARIS.O H., SMITH.I W Admic Bafety and Licensing Board Panel 84/02/13 Portland General Electric Co. 7pp 22250 001. 24x Fiche 50-344,84/02/13.8402150131
- 8402240076 Amend to svc list, adding LK Marbet & changing address for E Rosolie Certificate of Svc encl ROSOLIE, E. Coelition for Safe Power 84/02/17 2pp 22374,151, 24X Fiche 50-344,84/02/17,8402240076.
- 840224004B Memorandum on licensee 840209 ltr re licensee duty to notify ABLB on issues relevant to proceeding BMITH.I.W. Atomic Bafety and Licensing Board Panel 84/02/22 3pp. 22372:360 24% Fichs 50-344, 84/02/22, 840224004B

J Insurance & indemnity information

- B402210237 Forwards Endorsement 33 to MAELU Policy NF-86 & Endorsement 63 to NELIA Policy NF-225
 WIECHMANN, B M Fortland General Electric Co. 84/02/14 SALTZMAN, J
 Assistant Director For State & Licensee Relations Spp. 22316 033.
 24X Fiche 50-344,84/02/14,8402210237
- 8402230219 Forwards Endorsement 4 to MAELU Policy M-57 & NELIA Policy N-57 HIRCHHANN, 8 M Portland General Electric Co 84/02/14. 9ALTZMAN, J Assistant Director for State & Licensee Relations. 4pp. 22361.107. 24X Fiche 50-344.84/02/14,8402230219.
- P Operating license stage documents & correspondence
- B312120029 Generic Ltr 83-39 to representatives of utila re voluntary survey of licensed operators. Byc list encl, EIBENHUT, D. O Division of Licensing 83/12/08. Commonwealth Edison Co. 12pp 22313 006 24% Fiche 50-000, 83/12/08, 8312120029.
- 8402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983. CHILK.8. J. Office of the Becretary of the Commission 83/12/14 Public Document Branch 1p. 22281 023 24X Fiche 50-000,83/12/14,8402160003
- --8402160422 Discusses SECY-83-199 re emergency operations facility CHILK, B J Dffice of the Secretary of the Commission. 83/04/09, DIRCKS, W Office of the Executive Director for Operations 1p. R2281:293 24X Fichs. 50-000, 83/12/14/8402160003
- 8402030442 Forwards add1 info re snubber Tech Specs & changes to License Change Application 73, Rev 1, based on agreements reached during 830823 & 24 meetings.
 WITHERE, B.D. Portland General Electric Co. 83/12/22, MARTIN, J. 8 Region 5, Office of Director. 4pp. 22066; 271. 24X
 Fiche 50-344,83/12/22,8402030442

- B402030155 Advises that based on review of B31116 & 1212 submittals re NUREQ-0737, Item II. B 3, "Post-Accident Bampling Sys." all 11 review criteria satisfied Item complete HILLER. J. R Operating Reactors Branch 3 84/01/26 WITHERS. B D Portland General Electric Co. 1p 22089 360 24x Fiche. 50-344. 84/01/26. 8402030155
- 8402030448 Forwards Class III payment for Amend 84 to License NPF-1, in response to NRC 840104 ltr HITHERS.B.D Portland General Electric Co 84/01/26 DIGGS.R M License Fee Management Branch 2pp 22069 037 24X Fiche: 50-344,84/01/26.8402030448
- 8402130364 Forwards supplemental safety evaluation re resolution of three open items on override of containment purge isolation. Item on qualification of hydrogen vent valves remains to close out containment purging & venting issue MILLER, J.R. Operating Reactors Branch 3 84/01/26 WITHERS, B.D. Portland Consent Electric Co. 2pp. 22216 185 24% Fiche. 50-344, 84/01/26, 8402130384
- --B402130388 Supplemental safety evaluation re open items on override of containment purge isolation Mods committed to by licensee to remove all override capability from containment ventilation isolation sys acceptable, pending ESF reset concerns w NRC No Datailed Affiliation Given 84/01/26 3pp 2226:187. 24% Fiche 50-344.84/01/26.8402130384
- 8402010410 Generic Ltr 84-04 to all operating PWR licensess, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Svc 11st encl EIBENRUT, D. G. Division of Licensing 84/02/01 Consolidated Edison Co. of New York, Inc. 59pp. 22177 087. 24X Fiche 50-000,84/02/01,8402010410
- 8402090439 Forwards BER on responses to Generic Ltr 82-28 & NUREG-0737, Item II F. 2 re inadequate core cooling instrumentation (ICCI) & request for add1 info re conformance of components in ICCI sys to MUREG design requirements. W/o encl MILLER, J R Operating Reactors Branch 3 84/02/02 WITHERS, B D Portland General Electric Co 2pp 22177 314 24X Fiche \$0-344,84/02/02,8402090439.
- 8402130181 Provides addl info re current reracking schedule for proposed spent fuel storage capacity increase. Following receipt of license amend, util will authorize fabrication to begin in June 1984 to ensure new racks prior to 1986 WITHERB, B. D. Portland General Electric Co. 84/02/06 MILLER, J.R. Operating Reactors Branch 3. 200 22201:137 24X Fiche: 50-344,84/02/06.8402130181.
- 8402210137 Responds to Generic Ltr 83-41 re fast cold starts of diesel generators from 821201-831201 & assessment of effects of fast cold starts on generator reliability Generators prejubricated & prewarmed to eliminate degrading effect, HITHERS, B. D. Portland General Electric Co. 84/02/14, EISENHUT, D G. Division of Licensing 1p 22317 168, 24X Fiche 30-344, 84/02/14, 8402210137.
- 8402280622 Notification of 840223 meeting w/util, USOB & Bimons, Li & Assoc in Bethesda, MD to discuss analyses of flood potential breakout of Spirit Leke on Mount St Helens TRAMMELL, C. M Operating Reactors Branch 3. 84/02/17 MILLER, J R Operating Reactors Branch 3. 84/02/17 MILLER, J R The State of State o
- G Inspection reports, IE Bulletins & correspondence
- 8402270001 Further response to FOIA request for NRC records re security violations & safeguards events at nuclear facilities Forwards App A documents App B documents partially withheld free FOIA Exemptions 3,4 & 6). App A documents also in PDR. FELTON, J.M. Division of Rules and Records 83/12/12 COLDENBERG, 9 Scripps-Howard Newspapers. 4pp. 22413 098 24X Fichs. 50-344, 83/12/12, 8402270001.
- ---B402270024 IE Insp Rept 50-344/79-18 on 791107-09 No noncompliance noted. Major areas inspected, physical security, including access controls, lock & key security & review of investigation efforts re-controlled substances.

 BCHUSTER.M.D., SHACKLETON, D. C. Region 5. San Francisco, Office of the Director NORDERHAUG, L.R. Region 5. San Francisco, Safeguards Branch 79/11/21 5pp. 22413-106 24X Fiche: 50-344.83/12/12, B402270001.
- --8402270069 Discusses 791126 conversation w/P Hunt of Congressman Dingle ofc re-potential use of L8D by facility security guards.

 Insp rept will be sent to Hunt.

 NORDERHAUGILR. Region 5, San Francisco, Office of the Director.

 79/11/28 Region 5, San Francisco, Office of the Director.

 28413:121. 24X Fiche: 50-344,83/12/12,8402270001.

- --8402270080 IE Insp Rept 50-344/79-20 on 791126-1212 Noncompliance noted failure to control access to protected & vital areas of site Info deleted (ref 10CFR2 790)
 MORTENSEN, W.P., SCHUSTER, M.D., SCHAEFER, D.W., Region 5, San Francisco, Office of the Director 80/02/15 30pp 22413 129 24X Fiche 50-344,83/12/12,8402270001
- --8402270091 Notice of violation from insp on 791124-30 & 1211-12 Burns employee granted visitor unauthorized access to protected areas on 791014 Info deleted (ref 10CFR2 790)

 * NRC No Dataited Affiliation Given 80/02/15 2pp
 22413 161 24X Fichs 50-344,83/12/12,8402270001
- --8402270105 Forwards samitized responses to notice of violation & notice of proposed imposition of civil penalties
 WILLIAMS, J. Portland General Electric Co. 80/03/07 STELLD, V. Dffice of Inspection & Enforcement. Office of the Director. 9pp 22413 164 24X Fiche 50~344.83/12/12,8402270001
- --B402270il4 Forwards recommended response to util B00307 reply to NRC B00215 notice of violation & notice of proposed imposition of civil penalties ENGELKEN, R H Region 5, Ban Francisco, Office of the Director B0/03/17 STELLD, V Office of Inspection & Enforcement, Office of the Director ip 22413 173 24X Fichs 50-344.83/12/12, B402270001
- --B402270136 Forwards proposed civil penalty enforcement package resulting from unannounced physical security insp on 791126-30 & 1211-12 Becurity enforcement history & proposed press release also forwarded M/o encl
 ENGELKEN.R H Region 5, Ban Francisco, Office of the Director 79/12/31. HOWARD,E M Division of Safeguards Inspections 2pp 22395 093 24X Fiche 50-344,83/12/12,8402270001
- B312120153 IE Info Notice 84-06, "Bteam Binding of Auxiliary Feedwater Pumps " Bvc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120153
- 8402140372 Forwards IE Mgt Mesting Rept 50-344/84-01 on 840111 to discuss roles of PO&E.ITT Barton & Hestinghouse in identification.assessment & resolution of errors in Barton transmitters used in safety-related applications.

 MARTIN.J B. Region 5. Office of Director 84/01/25 WITHERB.B D Fortland General Electric Co. Zpp 22220 063, 24% Ficha.50-344.84/01/25.8402140372
- --8402140379 IE Mgt Mesting Rept 50-344/84-01 on 840111 Major areas discussed responses to defects identified & reported by Barton in Model 763/764 transmitters used in safety-related applications at facility CREWS.J L. JOHNSON,A.D., MARTIN.J B Region 5, Office of Director 84/01/25 9pp 22220 065 24X Fiche 50-344,84/01/25,8402140372.
- 8402030086 Ack receipt of 840119 ltr forwarding payment of civil penalty imposed by 831219 order. Corrective actions will be examined during future insp AXELRAD, J. A Enforcement Staff 84/01/26. WITHERS, B D Portland General Electric Co 2pp 22091 037 24X Fiche 50-344,84/01/26,8402030086
- 8402140228 Forwards IE Insp Rept 50-344/83-33 on 831212-16 No noncompliance noted.
 WENSLAMSKI,F A. Region 5, Office of Director. 84/01/27
 WITHERS, B. D. Portland General Electric Co. ip. 22227.148 24X
 Fiche. 50-344.84/01/27.8402140228.
- --8402140233 IE Insp Rept 50-344/83-33 on 831212-16, No noncompliance or deviations noted Major areas inspected implementation of NUREO-0737. Action Items II. 8. 3 & II F. 1 CILLIB.M , WENSLAWBKI, F. A. Region 5. Office of Director 84/01/27 9pp. 22227-149. 24X Fiche 50-344,84/01/27,8402140228
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls," Svc list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co. of New York, Inc. 119pp. 22114.179. 24X Fiche 50-000.84/02/03,8401190016
- B401190017 IE Bulletin B4-01, "Cracks in BHR Mark I Containment Vent Headers." Svc list encl. DEYOUNG.R.C. Director's Office, Office of Inspection and Enforcement B4/02/03 Consolidated Edison Co of New York, Inc 10Rpp. 22177-156 24X Fiche 50-000,84/02/03,8401190017

- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (100FR50, App R) " Syc list ent!

 JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York Inc 124pp 22365 259 24% Fichs 50-000,84/02/13,8401190041
- 8401190039 IE Info Notice 84-08. "IOCFR50 7. 'Employee Protection '"
 Svc list encl
 JERDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc. 115pp 22365 141 24X Fiche 50-000.84/02/14.8401190039
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Wastinghouse Type 8A-1 Differential Relays" Svc list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc. 118pp 22366 142 24X Fichs 50-000, 84/02/15,8401190045
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc. 116pp 22366 024 24X Fiche 50-000.84/02/21,8401190062
- B401190066 JE Info Notice 84-11, "Training Program Deficiencies"
 Svc list and
 JORDAN, S. t. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co. of New
 York, Inc. 115pp 22430 304 24X Fiche: 50-000, 84/02/24, 8401190066
- 8401170067 IE Info Notice 84-12, "Failure of Soft Seat Valve Beals "
 Svc list entl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co. of New
 York, Inc 120pp 22431 060 24X Fiche 50-000,84/02/27,8401170067
- 8 Reportable occurrences, LERs & related correspondence
- 8402140378 Requests addl info re Part 21 rept dtd B31108 concerning wear ring fallure in auxiliary feedwater pump furnished to facilities Info requested within 25 day;
 PGTAPDVS.V Region 4. Office of Director B3/11/30 PATTY.D.F.
 Bingham-Hillamette Co ip 22221 250 24X Fiche 30-000.83/11/30, 8402140398
- --8402140422 Supplemental Part 21 rept re wear ring failure in auxiliary feedwater pumps, per 831130 request for addl info Hear rings will be replaced on returned units w/AISI 420 wrought matl. List of pumps in similar svc w/same wear ring encl PATTY, D.F. Bingham-Willamette Co. 83/12/20 Region 4, Office of Director 2pp 22221 251 24X Fiche 50-000,83/11/30,8402140398
- 8402220154 Responds to FDIA request that 146 LERs be placed in PDR Forwards LERs listed on app Documents also available in FDR Remaining LERs were either canceled or not issued FELTON.J M Division of Rules and Records 83/11/30 JEFFERBON,G A Affillation Not Assigned 2pp 22380 052 24X Fiche: 50-000,83/11/30,8402220154
- 8402030368 LER B3-021/03L-0 on B31220, control rods failed to respond to demand for rod motion while in manual control Caused by failed master pulser card in rod control sys Card replaced W/840119 ltr
 SCHMITT.R P. YUNDT,C.P Portland General Electric Co 84/01/19 MARTIN.J B Region 5, Office of Director. 4pp. 22066,068 24X Fiche 30-344,84/01/19,8402030368.
- 8402130287 LER B3-023/03L-0 on B31229, underfrequency relay 201-2/1 on bus H-2 found to have sluggish response & erratic satpoint around Tech Byer I imit Caused by dirty components within relay Unit cleaned & retested 4/840127 ltr BAIR.0 0. YUNDT, C P Portland General Electric Co B4/01/27, MARTIN, J B Region 5. Office of Director 3pp 22204:075, 24X Fiche 50-344.64/01/27,8402130267
- 8402130340 LER 83-022/03L-0 on 840193, train A steam driven auxiliary feedwater pump failed to start Caused by component failure due to excessive grease buildup on torque switch Valve cleaned & listed W/840127 ltr.

 BAIN.9 G. YUNDT.C P Portland General Electric Co. 83/01/27 HARTIN.J B Region 5. Defice of Director 4pp 22197 274 24X Fichs.50-344.84/01/27,8402130340
- 8402150213 PNO-V-84-005 on 840206, At St Helens crupted Minor landslide occurred Plant has taken precautionary measures should fallout occur DODDS: R : BISHOP, T Region 5, Office of Director 84/02/07. 1p. 22244 138. 24% Fiche 50-344.84/02/07.8402150213

- 8402180350 PNO-V-84-007 on 840207.licensee reported that during 840203 annual requalification exam.licensed operator admitted cheating Operator removed from licensed duties & voluntarily resigned On 840210.Region V will assess licensee action. HILLER.L. # BISHOP.T Region 5. Office of Director 84/02/08 lp 22243 122 24X Fiche 30-344.84/02/08.8402150360
- 8402270122 LER 83-024/03L-0 on 831207, during routine testing, train B fiesel fuel oil storage transfer pump falled to start Caused by loose printed circuit card connection Card tightened & storage sys tested for proper operation W/840208 ltr BAIR.G G. YUNDT.C P. Portland General Electric Co. 84/02/08 MARTIN.J B. Region 5. Office of Director 4pp 22426,101 24% Fiche 50-344,84/02/08,8402270122
- 8402170255 LER 84-D01-00 on 840112, discovered surveillance testing on ESF actuation circuitry not performed for several yrs Caused by inadequate procedures Procedures revised W/840209 ltr BAIR, 0, YUNDT, C P Portland General Electric Co 84/02/09 4pg 22297 013 24X Fiche 50-344,84/02/09,8402170255
- B4022B0344 Discusses 84070B ltr re problems associated w/operablility of control room ventilation sys ammonia detectors.per NUREO-0737, item III D 3 4 Replacement detectors will be obtained, installed & operating by B41231 HITHERB, B D Portland General Electric Co 84/02/24 EISENAUT, D & Division of Licensing ip. 22403 170 24X Fiche 50-344, 84/02/24.
- DOCKET 50-246 DAVIB-BESSE NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8402140105 Rev 3 to Emergency Plan Administrative Procedure AD 1827.18.
 "Search & Rescum" & Emergency Plan Health Physics Procedure
 HP 1604.02, "Area & Equipment Decontamination " W/840201
 transmittal & receipt form & Rev 201 to rev index,
 8086878.3 0, MURRAY.T.D Toledo Edison Co 84/01/24 19pp
 22217 214 24X Fichs 50-346.84/01/24.8402140105
- 8402050354 Forwards Temporary Mods T-7644 & T-7690 to Rev 20 to industrial security plan Mods withheld (ref 10CFR73 21). CROUSE, R P Toledo Edison Co 84/01/27 Region 3, Office of Director ip 22085 106 24% Fiche 50-346, 84/01/27, 8402060354
- 8402160679 Summary of 831208 meeting w/util at site re resolution of fire protection deficiencies Next meeting scheduled for 840125 Attendess list & agenda encl VISBING. O Operating Reactors Branch 4 84/02/01 Operating Reactors Branch 4 18pp 22301 311 24X Fiche. 50-346,84/02/01, 8402160679.
- 8402220305 Ack receipt of 840127 ltr re changes identifies as Temp Mods T-7644 & T-7690.to industrial security plan Changes consistent w/provisions of 10CFR50 54(p) & acceptable AMELSON.W L Region 3. Office of Director 84/02/17 CROUSE, # P Toledo Edison Co 2pp 22335.360 24X Fiche.50-346,84/02/17,8402220305
- B402220117 Rev 7 to Emergency Plan Bupporting Procedures HP 1602 OL.IP 1604 01:HP 1604 02:AD 1827 01 through AD 1827 17 & AD 1850 04 through AD 1850 06 re emergency offsite dose estimates Tolefo Edison Co 84/02/28 25pp 22326.034. 24X Fichs 50-346.84/02/28.8402220117.
- 8402170151 Temporary Mod Request T-7722 to Rev & to Emergency Plan Implementing Procedure EI 1300 01. "Emergency Plan Activation " W/Rev 36 to index & 640213 transmittal ltr. # Toledo Edison Co 84/02/29 3pp 22279 068 24X Fiche 50-346 84/02/29.8402170151.
- J Insurance & indomnity information
- B40202D109 Forwards Endorsements 37 & 47 to MAELU Policy ME-92 & NELFA Policy NF-236, respectively ODLOEN, H P Harsh & McLennan, Inc. 84/01/26, BALTZMAN, J Assistant Director for State & Licensee Relations, 3pp. 22036 236
- P Operating license stage documents & correspondence
- B312120029 Ceneric Ltr 83-39 to representatives of utils re voluntary survey of licensed operators Svc list and EIBENHUT, D 9 Division of Licensing, 83/12/08. Commonwealth Edison Co. 12pp 22313 006 24X Fiche 50-000,83/12/08,8312120029

- 8402010265 Notification of contract execution, Mod 3 to "Radiation Monitoring Program Requirements" Contractor State of OH UMBEL, D Technical Assistance Contracts Branch FIN 8-8450 84/01/13 SCHLOSSER, L A Division of Resource Management & Administration GESTMANN.H J NRC No Detailed Affiliation Given ip 22046 354 24% Fiche 50-346,84/01/13,8402010265
- --B402010273 Mod 3, providing funds for CYB4 & incorporating environ monitoring at Davis-Besse, to "Radiation Monitoring Program Requirements" JACKBON,D L Uhio, State of GUSTAVE,R P Division of Contrac FIN B-8450 84/01/13 2pp 22046 355 24X Fiche 50-346,84/01/13,8402010265
 - Division of Contracts
- 8402130440 Forwards Amend 66 to License NPF-3 & safety evaluation Amend deletes Tech Specs 3 6 4 2 & 4 6 4 2 re containment recirculation sys STOLE, J F Operating Reactors Branch 4 84/01/20 CROUSE, R P Toledo Edison Co. 2pp 22263 247 24X Fiche 50-346,84/01/20,8402370440
- --8402150444 Amend 66 to License NPF-3, deleting Tech Specs 3 6 4 2 & 4.6 4.2 re containment recirculation sys BTOLZ, J F Operating Reactors Branch 4 84/01/20 6pp 22265 251 24X Fichs 50-346/84/01/20,8402150440
- --B402150448 Bafaty evaluation supporting Amend 66 to License NPF-3 + Office of Nuclear Reactor Regulation, Director 84/01/20 + 22263 260 24X Ficher 50-346.84/01/20, 8402130440
- B402030242 Forwards degraded grid voltage test voltage analysis tabulation.per util 830223 itr.in response to NRC 830217 ltr transmitting Amend 82 All test values are above analytical values indicating analysis conservative GROUSE.R P Toledo Edison Co 84/01/23 8TOL7.J F Operating Reactors Branch 4 2pp. 22067 186 24X Fiche 50-346,84/01/23,8402030242
- B402030311 Responds to Q Vissing verbal request re compensatory measures for TMI Lessons Learned Items II F 1 i & II, F, 1 2 First channel of Kaman vent stack monitor declared operable on B40125 Becond channel should be operational by B40331. GROUSE, R P Toledo Edison Co 84/01/26 BTOLZ, J F Operatin Reactors Branch 4 1p. 22069 180 24% Fiche 50-346,84/01/26, B402030311
- 8402080495 Notification of 840203,06 & 07 meetings w/util in Gak Harbor, OH to raview status/schedule & completeness of installation for NUREQ-0737 items. Agenda for 840207 mesting entl.
 VISBING. G. Operating Reactors Branch 4 84/01/27 STOLZ, J. F. Operating Reactors Branch 4 3pp. 22174 063 24X
 Fiche: 50-346, 84/01/27, 8402080495
- 8402010410 Ceneric Ltr 84-04'to all operating PWR licensees.CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Svc list encl EIBENHUT.D 0 Division of Licensing 84/02/01. Consolidated Edison Co. of New York. Inc. 57pp. 22177.087. 24X Fiche'50-000.84/02/01.8402010410
- 8402150207 Forwards application for Amend to License NPF-3 Amend deletes safety features actuation sys signal to containment sample isolation valves for post-accident sampling sys GROUBE.R P. Toledo Edison Co. 84/02/07 BTOL7.J F. Operating Reactors Branch 4 1p. 22244.104 24X Fiche 50-346,84/02/07. B402150207
- --8402150217 Application for amend to License NPF-3, deleting sefety features actuation sys signal to containment sample isolation valves for post-accident sampling sys CROUSE.R P Tolado Edison Co 84/02/07 App 22244 105 24X icha. 50-346, 84/02/07, 8402150207
- --8402150223 Proposed Tech Spec changes deleting safety features actuation mys signal to containment sample isolation valves for post-accident sampling mys * Toledo Edwson Co 84/02/07 7pp 22244 iii. 24X Fiche: 50-344,84/02/07,8402150207.
- 8402140385 Forwards summary of activities being developed by util to address Generic Ltr 83-28, equipment classification & vendor interface program requirements for reactor trip sys, in response to NRC 830708 ltr. CR6U8E,R.P Toledo Edison Co. 84/02/10 STOLZ, J.F. Operating Reactors Branch 4 2pp 22220.046 24X Fiche 50-346,84/02/10, 8402140385.

- 8402240056 Forwards response to Items 4.5,9.10 & 12 of 830906 ltr re instrumentation to detect inadequate core cooling Response to Item 1 expected by 840309 CRQUSE.R P. Toledo Edison Co 84/02/10 STOLZ.J F Operating Reactors Branch 4 7pp 22373 354 24X fiche 50-346.84/02/10.8402240056
- 8402240014 Corrects 840117 ltr Attachment 1 containment design pressure should be 36 psig as indicated in FBAR, not 47 psig CROUSE, R P Toledo Edison Co 84/02/17 STOLZ, J F Operating Reactors Branch 4 1p 22375 243 24X Fiche 50-346,84/02/17,8402240014
- 8402290115 Forwards application for amend to License NPF-3, revising Tech Specs to reflect axial power shaping rod withdrawal & coastdown at end of Cycle 4 CRUUSE, R P Totedo Edison Co 84/02/17 SYOLZ, J F Operating Reactors Branch 4 1p 22425 270 24X Fiche 50-346,84/02/17,8402270115
- --8402290120 Application for amend to License NPF-3, revising Tech Specs to reflect axial power shaping rod withdrawal & coastdown at end of Cycle 4 GROUSE.R P Toledo Edison Co 84/02/17 5pp 22425 271 24X Fiche 50-346, 84/02/17, 8402290115
- --B402290132 Rev i to "Davis-Nesse Nuclear Power Station Unit 1. Cycle 4 --Reload Rept." # Babcock & Wilcox Co BAW-1783 RO1 83/10/31 78pp 22425-276 24X Fiche 50-346,84/02/17,8402270115
- 8402170430 REVIEW OF THE DAVIS-BESSE UNIT NO 1 AUXILIARY FEEDWATER SYSTEM RELIABILITY ANALYSIS YOUNGBLODD, R , FAPAZOLOU, I A Brookhaven National Laboratory NUREO/CR-3530 84/02/29 Division of Safety Tachnology 17pp Available at NRC \$3.75 22318 317 24% Fiche 50-346, 84/02/27, 8402170430
- O Inspection reports, IE Bulletins & correspondence
- 8402060228 Forwards IE Insp Rept 50-346/83-21 on 830909-840104 No noncompliance meted
 NORELIUS.C E Division of Project & Resident Programs
 CROUSE,R P. Toleda Edison Co. 2pp 22083;258 24X
 Fiche 50-346,84/01/20,8402060228
- ---B402060233 IE Insp Rept 50-346/83-21 on 830909-840106 No noncompliance noted Major areas inspected special insp of LER 03-012 re insperable ECG9 room codlers discovered in 1980 RIGERS,W 0 , JACKIW,I N Region 3, Office of Director 84/01/19 3pp. 22083:260 24X Fiche 50-346:84/01/20.8402060228
- 831212015J IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN,E L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co. of New York, Inc. 120pp 22058 001. 24X Fiche 50-000.84/01/25,8312120153
- 8401190016 JE Info Notice 84-07, "Design-Dasis Threat & Review of Vehicular Excess Controls " But list entl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/03 Compolidated Edison Co. of New York, Inc. 119pp 22114, 179 24X Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01. "Cracks in BWR Mark I Containment Vent Headers " Svc list encl. DEYOUNG'R.C. Director's Office. Office of Inspection and Enforcement. 84/02/03 Consolidated Edison Co. of New York, Inc. 102p 22177 156 24X Fiche 50-000.84/02/03.8401190017
- 8402040362 Ack receipt of 840123 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Rept 50-346/83-01 NDRELIUS.C.E. Division of Project & Resident Programs 84/02/03, CROUSE, R P Toledo Edison Co 1p, 22084, 112 24X Fiche: 50-346, 84/02/03, 8402040362
- --8402060367 Responds to NRC B30308 ltr re noncompliance & violations noted in IE Insp Rept 50-346/B3-01 Corrective actions control group established to manage & maintain drawing activities & task force created to improve drawing sys. CROUSE,R.P. Toledo Edison Co. 84/01/23 NDRELIUS,C Region 3. Office of Director 14pp. 22086 113 24X Fiche 50-346,84/02/03,840060362. 8402060362
- B402280291 Forwards IE Inep Rept 50-346/83-24 on B31119-840112 & notice

- --8402280298 Notice of violation from insp on 831117-840112 SHAFER,W D Region 3, Office of Director 84/02/07 2pp 22398 345 24X Fiche 50-346.84/02/07.8408280271
- --8402280307 I& Insp. Rept 50-346/83-24 on 831139-840112 Noncompliance noted failure to follow respirator qualification procedure & control design document ROGERS.W G. JACKIW.I N. Region 3, Office of Director 84/01/31 Spp. 22398 347 24X Fiche 50-346,84/02/07,8402280291.
- 8401190041 IE Info Notice 84-07, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (100FR50.App R) " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259 24% Fiche 50-000.84/02/13.8401190041
- 8401190039 IE Info Notice 84-08, "10CFR30 7, 'Employee Protection '"
 Syc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc. 113pp 22365 141 24% Fiche 50-000,84/02/14,8401190039
- 8401190045 IE Info Notice 83-63. Suppl 1. "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc. 118pp 22366 142 24X Fiche 50-000.84/02/15,8401190045
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Bet Below Manufacturer Recommended Valve " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366.024 24X Fiche 50-000,84/02/21,8401190062
- 8401190065 IE Info Notice 64-11, "Training Program Deficiencies" Svc list encl JURDAN,E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/02/24. Consolidated Edison Co. of New York, Inc. 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
 Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/27 Consolidated Edison Co. of New
 York, Inc. 120pp 22431 060 24X Fiche 50-000.84/02/27,8401190067
- R Periodic operating reports & related correspondence
- 8402230093 "Effjuent & Weste Disposal Semiannual Rept, Jul-Dec 1983 "
 W/840213 ltr
 HURRAY, T D Toledo Edison Co 83/12/31 KEPPLER, J G. Region 3,
 Office of Director 87pp 22362 145. 24X Fiche: 50-346, 83/12/31,
 8402230093
- 8402220334 Wastewater rept, Jan 1984 W/840215 ltr MURRAY, T D Toledo Edison Co 84/01/31 9pp 22336.232 24X Fiche 50-346,84/01/31,8402220334
- B Reportable occurrences. LERs & related correspondence
- 8402130308 Revised LER 82-045/03X-3 on 820904, auxiliary featwater pump introduced button valve FW786 closed w/o operator touching close button Cause unknown Valve reogened Burveillance test performed W/840116 [tr LON9.J.W. NURRAY.T.D. Toledo Edison Co. 84/01/16 [KEPPLER, J. O Region 3. Office of Director 6pp 22197.143 24X Fiche 50-396.84/01/16.8402130308
- 8402130405 LER 83-074/03L-0-on 831224, operators received burated water storage tank hi fail alarm for safety features actuation sys Channel 1 Caused by improperly installed freeze protection heat trace on piping W/840123 Itr ISLEY, T. MURRAY, T D Tolede Edison Co. 84/01/24, KEPPLER, J Q Region 3. Office of Director. Spp. 22203 254 24X Fiche 50-346,84/01/24,8402130405
- 8402220019 LER 84-001-00 on 840108 reactor tripped Caused by automatic insertion of axial power shaping rods. Faulty sys logic card repaires W/840207 ltr
 BMARTJ J D , MURRAY, T D Yoledo Edison Co 84/02/07 KEPPLER, J G Region 3, Office of Director 3pp 22338 232, 24X Ficher 50-346,84/02/07,8402220019
 - 12240152 LER 84-002-00, on 840117, fuel transfer tube 1-1, drein 8F69 pened & uncapped & tube 1-2, drain 8F68 partially opened & uncapped Caused by defective procedures Capped valves eavatuated & change request imposed W/840217 ltr 18810.D & MRRAY.T.D Toledo Edison Co. 84/02/17 4pp. 1374 337 24X Fiche 50-346.84/02/17.8402240152

- DOCKET 50-348 JOSEPH M FARLEY NUCLEAR PLANT, UNIT :
 F. Security, medical, emergency & fire protection plans
- 8402010327 Grants exemption from certain requirements of App R.Bection III 0 2 to 10CFR\$0 Existing protection for containment bldg areas provides equivalent level of protection WARGA.S A Operating Reactors Branch 1 83/12/30 CLAYTON.F.L Alabama Power Co. 5pp 22059 290 24X Fiche 50-348,83/12/30,8402010327.
- --8402010336 Exemption from requirements of App R.Section III 9 2 to 10CFR50 re fire protection of safe shutdown cables & aquignment located inside containment bldg EIBENNUT.D 9 Division of Licensing 83/12/30 Alabama Power Co 4pp 22059 276 24X Fiche 50-348,83/12/30.8402010327
- ---8402010409 Safety evaluation supporting exemption from 10CFR50, App R respectific fire protection measures for protection of safe shutdown cables & equipment located inside containment bldg Worldown Cables & equipment located inside containment bldg 22059 300 24X Fiche 50-348, 83/12/30, 8402010327
- B402140139 Forwards IE Insp Repts 50-348/83-32 & 50-364/83-30 on 831212-16 No violations or deviations identified VERRELLI-D M Division of Project & Resident Programs 84/01/12 MCDONALD-R, P. Alabama Power Co 2pp. 22217;264 24X Fiche, 50-348,84/01/12,8402140139
- --B402140165 IE Insp Repts 30-348/83-32 & 50-364/83-30 on 831212-16 No violations or deviations noted Major areas inspected redioactive matl shipping, low level radwaste storage bldg, effluent monitoring & health physics operations DEBS, B T. Region 2, Office of Director. BARR, K, P Division of Engineering & Operational Programs 84/01/10 opp 22219 266 24X Fiche 50-348,84/01/12,8402140159
- 8402030382 Revs to Emergency Plan Implementing Procedures FNP-0-EIP-26, "Offsite Notification," FNP-0-EIP-17, "General Emergency" & FNP-0-EIP-9, "Radiation Exposure Estimation & Classification of Emergencies," Transmittal & receipt form encl.

 * Alabama Power Co 84/01/27, 142pp 22066:094 24X Fiche. 50-348, 84/01/27, 8402030382
- B402140307 Forwards summary of B40112 meeting w/util, Bouthern Bycs Co & Bechtel in Region II ofc re application of 10CFR50 48 & 10CFR50.App R fire protection at facilities.

 LEMIS.R C. Division of Project & Resident Programs. B4/01/27 MCDDNALD.R P Alabama Power Co. 4pp 22228 252 24X Fiche: 50-348, 84/01/27, 8402140307
- 8402030399 Rev 0 to Procedure 90-EIP-120, "Ref Quidance for Recovery Manager" W/B40130 1tr MUDD.C.H Alabama Power Co. 84/01/30. 14pp 22068:347 24X Fiche.50-348,84/01/30,8402030399.
- 8402030406 Rev 3 to procedure 60-EIP-114, "News Release Coordination & Distribution " W/840130 1tr MUDD.C H Alabama Power Co 84/01/30 1ipp, \$2068.324, \$24X Fiche:50-348.84/01/30.8402030406
- 8402070080 Revs to Emergency Implementing Procedures FNP-0-EIF-009, "Radiation Exposure Estimation & Classification of Emergencies" & FNP-0-EIP-019, "General Emergency," W/840202 ltr & 840201 transmittal & receipt form MUDSPETHJ B. Alabama Power Co. 84/02/02 MCKN10HT, J. Record Services Branch (Document Control Desk) 9pp. 22163:315 24% Fiche. 30-348, 84/02/02, 8402070080
- 8402130015 Requests extension of 22 wks to provide final response to Sactions 2.2 1 & 3 2 of Generic Ltr 83-28.per 831104 præliminary response, due to activities associated w/upcoming Unit i refueling outage & Suppl I to NUREG-0737 CLAYTON.F.L Alabama Power Co. 84/02/06. VAROA.S A. Office of Nuclear Reactor Regulation. Director. 1p. 22204:086. 24X Fiche-50-348:84/02/06,8402130015
- B402150142 Temporary change notice for Rev 5 to Emergency Plan Implementing Procedure 90-EIP-111, "Corporate Activation & Notification Procedure" MUSD, C H Alabama Power Co 84/02/07, 9pp 22250-022 24X Fiche. 50-348, 84/02/07, 8402150142.
- 8402170023 Forwards Amends 42 & 33 to Licenses NPF-2 & NPF-8, respectively & safety evaluation Amends correct two tables listing fire hose stations & sprinklers for Unit 2 & delete "during shutdown" from surveillance test for both units. REEVES,E A Operating Reactors Branch 1 84/02/09, CLAYTON.F L. Alabama Power Co. 5pp. 22312,313, 24X Fiche.50-348,84/02/09,8402170023

- --8402170026 Amends 42 & 33 to Licenses NPF-2 & NPF-8, respectively, correcting two tables listing fire hose stations & sprinklers for Unit 2 & deleting "during shutdown" from surveillance test for both units VARGA: S A Operating Reactors Branch i 84/02/09 10pp 22312 318 24X Fiche 50-348,84/02/09,8402170023
- B402170326 Lists possible exemptions to NRC interpretations of iOCFR50, App R (Osneric Ltr B3-33), per 840112 meeting, including automatic sprinkler protection, 20-ft safe shutdown cable separation criteria & small component protection CLAYTON, F L Alabama Power Co 84/02/10 EISENHUT, D O Office of Nuclear Rescutar Regulation, Director 2pp 22297 110 24X Fiche 80-348,84/02/10,8402170326
- 8402160461 Clarifies 840210 response to Guestion 471 1 for 10CFR20, App A Footnots (c) exemption request re iodine filter respiratory protection Reactor vessel head venting inaccurately referred to as normal shutdown evolution CLAYTON, F.L. Alabama Power Co. 84/02/13 VARGA, 8 A. Office of Nuclear Reactor Regulation, Director 2pp 22276 361 24X Fiche 50-348, 84/02/13, 8402160461
- 8402240238 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR REEVES.E.A Operating Reactors Branch 1. 84/02/14 CLAYTON, F. L. Alabama Power Co 2pp 22381.269 24X Fiche 50-348.84/02/14, 8402240258
- 8402270344 Responds to fee requirements of 10CFR170 reaction pertaining to fire protection requirements of 10CFR50. Fee required for 810319 & 830520 exemption requests from requirements of 10CFR50 MILLER. W O License Fee Management Branch. 84/02/21 CLAYTON, F L Alabama Power Co 3pp. 22437 358 24X Fiche 50-348,84/02/21,8402270344.
- P Operating license stage documents & correspondence
- 83:2120027 Generic Ltr 83-39 to representatives of utils re voluntary survey of licensed operators 8vc list encl EISENHUT, D 9 Division of Licensing 83/12/08 Commonwealth Edison Co. 12pp 22313 006 24X Fiche 50-000.83/12/08.8312120029
- 8402090071 Forwards revised SER & FR notice granting relief from ABME Section XI requirements for inservice testing program for pumps & valves. VAR9A: B. A. Operating Reactors Branch 1 84/01/26 CLAYTON, F.L. Alabama Power Co 2pp 22189 179. 24X Fiche 50-348,84/01/26, 8402090071
- --8402070078 Notice of granting relief from ABME Bection XI inservice testing requirements for pumps & valves.
 VARIGA.B.A. Operating Reactors Branch 1. 84/01/26, 2pp
 22189:181 24X Fiche 50-348.84/01/26,8402090071
- ---8402090083 Revised SER granting relief from ABME Section XI inservice testing requirements for pumps & valves.

 * Offics of Nuclear Reactor Regulation, Director 84/01/26 7pp 22189:183, 24X Fiche 50-348.84/01/26,8402090071.
- 8402030176 Application for amend to Licenses NPF-2 & NPF-B, revising float voltage surveillance requirement to 2 02 & 2,07 volts Add1 info re connector resistance for svc water bldg batteries & auxiliary bldg dc distribution limits submitted, CLAYTON: F.L Alabama Power Co 84/01/27 VARQA, B.A. Office of Nuclear Reactor Regulation, Director 4pp. 22067-348, 24% Fiche: 50-348, 84/01/27, 8402030196
- ~~B402030203 Proposed Tech Specs revising float voltage surveillance requirement to 2.02 % 2 07 volts for auxiliary % svc water bldg dc distribution sus.

 * Alabama Power Co. B4/01/27 App. 22067:352 24X Fiche: 50-348.84/01/27.8402030176.
- B402100393 Forwards Amends 41 & 32 to Licenses NPF-2 & NPF-8, respectively & safety evaluation Amends change Tech Specs re turbine valve testing & modify sxisting surveillance requirements for turbine overspeed protection sys REEVES.E.A. Operating Reactors Branch 1 B4/01/27 CLAYTON, F.L. Alabama Power Go. 6pp 22211:333. 24X Fiche: 50-348, 84/01/27, 8402100393.
- --8402100397 Amends 41 & 32 to Licenses NPF-2 & NPF-8, respectively, changing Tech Specs re turbine valve testing & modifying existing surveillance requirments for turbine overspeed protection sys.
 VAROA, S. A. Operating Reactors Branch 1 84/01/27, 10pp R2211:339 24X Fiche:50-348,84/01/27,8402100393

- --8402100401 Safety evaluation supporting Amends 41 & 32 to Licenses NPF-2 & NPF-B.respectively * Office of Nuclear Reactor Regulation, Director 84/01/27 App 22211 349 24X Fiche 30-348.84/01/27.8402100393
- 8402030419 Forwards Page 3 of Rev 4 to Administrative Procedure FNP-0-EIP-19 Page inadvertently omitted from original procedure HUDSPETH.J B Alabama Power Co 84/01/30 MCKNIGHT.J Documen Management Branch 3pp 22068 289 24X Fiche 50-348,84/01/30.040030410
- 8402010410 Generic Ltr 84-04 to all operating PMR licensees, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PMR primery main loops 8vc 11st encl EIBENHUT.D 0 Division of Licensing. 84/02/01 Consolidated Edison Co of New York. Inc 59pp 22177 087 24X Fiche 50-000.84/02/01.8402010410
- 8402140342 Application for amend to Licenses NPF-2 & NPF-8, incorporating NRC suggested Tach Spec changes contained in Generic Ltr 83-43 re reporting requirements of lOCFR50 72 & lOCFR50 73 CLAYTON, F.L. Alabama Power Co. 84/02/03 VAROA, 8 A. Office of Nuclear Reactor Regulation, Director. Spp. 22228 194 24X Fiche 30-348.84/02/03.8402140342
- --8402140347 Proposed Tech Specs revising administrative control & definitions sections incorporating regulation changes, per Generic Ltr 83-43 * Alabama Power Co 84/02/03 29pp. 22228 199. 24X Fiche: 50-348,84/02/03,8402140342
- B402170079 Forwards request for add1 info re B30113 request for exemption from 10CFR20, "Protection Factors for Respirators," allowing credit for radioiodine protection factor while employing MSA 466220 GRR-1 canister VARGA, B A Operating Reactors Branch 1 B4/02/0B CLAYTON, F L Alabama Power Co. Spp 22312 342 24X Fiche 50-348,84/02/0B, B402170079
- 8402170023 Forwards Amends 42 & 33 to Licenses NPF-2 & NPF-B, respectively & safety evaluation Amends correct two tables listing fire hose stations & sprinklers for Unit 2 & delete "during shutdown from surveillance test for both units REEVEB, E. A. Operating Reactors Branch | 84/02/09, CLAYTON, F. L. Alabama Power Co. Spp. 22312-313 24X Fichs. 50-348, 84/02/09, 8402170023
- --B402170026 Amends 42 & 33 to Licenses NPF-2 & NPF-B, respectively, correcting two tables listing fire hose stations & sprinklers for Unit 2 & deleting "during shutdown" from surveillance test for both units VARGA:8 A. Operating Reactors Branch 1 84/02/09 10pp 22312,318. 24X Fiche 50-348,84/02/09,8402170023
- --8402170028 Bafety evaluation supporting Amends 42 & 33 to Licenses NPF-2 & NPF-B, respectively # Office of Nuclear Reactor Regulation, Director 22312 328, 24% Fiche 50-348,84/02/09,8402170023
- 8402140132 Forwards response to Radiological Assessment Branch 840208 request for add1 info re 840113 application for exemption from 100FR20, App A concerning iodine filter respiratory protection.

 CLAYTON F L Alabama Power Co 84/02/10, VAR9A, S A Office of Nuclear Reactor Regulation, Director 8pp 22230 094 24X Fiche 50-348,84/02/10,8402140152
- 8402170220 Advises of util review of facility Cycle & core reload design & plans re implementation Refueling outage scheduled to commence on 840210 No unreviewed sefety questions defined by 10CFR90.89 involved whreload CLAYTON.F.L. Alabama Power Co 84/02/10 Office of Nuclear Reactor Regulation, Director 3pp 22299-336 24X Fiche 50-348,84/02/10,8402170220
- 8402220487 Responds to Generic Ltr 83-35 & NUREG-0737, Items II K.3 30 & II K 3.31 re small break LOCA enalysis. Westinghouse Owners Group program will demonstrate that NOTRUMP predicts lower temps than WFLABH CLAYTON.F L. Alabama Power Co 84/02/10 VARGA.8 A. Office of Nuclear Reactor Regulation, Director. 2pp. 22340-046 24X Fiche: 50-348,84/02/10,8402220487
- 8402210278 Forwards final response to Generic Ltr 83-28 rs NRC position on Salem ATWS events, per 831104 ltr. Development & control of info handling sys used to identify safety-related components & subcomponents described CLAYTON.F.L Alabama Fower Co. 84/02/15. VAROA.B.A Office of Nuclear Reactor Regulation, Director. 8pp. 22315.204 24X Fiche 50-348,84/02/15,8402210278

- 3402220331 Responds to B31215 request for add1 info re position on two of il NUREO-0737. Item II B 3 criteria Licensee should provide procedure to estimate extent of core damage based on radionuclide concentrations CLAYTON, F.L. Alebama Power Co 84/02/17 VARGA, 8 A Office of Nuclear Reactor Regulation, Director 4pp 22336-225 24X Fiche 50-348,84/02/17,8402220331
- 340222051i Application for amend to Licenses NPF-2 & NPF-8; revising Tech Spec to rod control sys Detailed description & justification for proposed change & Class III & I amend
 - CLAYTON F L. Alabama Power Co. 84/02/17 VARGA, B A. Office of Nuclear Reactor Regulation. Director 17pp 22333 317 24X Fiche 50-348,84/02/17,8402280511
- -8402220315 Revised proposed Tech Spec changes to rod control sys * Alabama Power Co 84/02/17 3pp 22333 333 24X Fiche: 50-348, 84/02/17, 8402220511
- 402270257 Requests that schedule for upgrading environ quelification of accident monitoring equipment, per Reg Guida 1 97 & 10CFR50 49(p), be extended to sixth refueling outage, but no later than 851130 to 10 t
- Inspection reports, IE Bulletins & correspondence
- 102140157 Forwards IE Insp Repts 50~348/83~32 & 50~364/83~30 on 831212~16 No violations or deviations identified VERRELLI.D M plvision of Project & Resident Programs 84/01/12, MCDDNALD.R P Alabama Power Co 2pp 22217-264 24X Fiche 50~348,84/01/12,8402140157
- 8402140165 IE Insp Repts 50-348/83-32 & 50-364/83-30 on 831212-16 No violations or deviations noted Major areas inspected radioactive math shipping, low level radwaste storage bldg, affluent monitoring & health physics operations
 DEDB: B T. Region 2. Office of Director. BARR: K P Division of Engineering & Dperational Programs 84/01/10 App. 22219 366 24X Fiche: 50-348, 84/01/12, 8402140159
- O2140182 Forwards IE Insp Repts 30-348/83-31 t 50-364/83-29 on 831213-16 No violations or deviations noted VERRELLI, D M Division of Project t Resident Programs 84/01/4CDONALD, R P. Alabams Power Co 2pp 22223 355, 24X Fichs 50-348,84/01/12,8402140182.
- 1402140183 IE Insp Repts 50-348/83-31 & 50-364/83-27 on 831213-16 No violations noted Major areas inspected electrical & instrumentation preventive & corrective maint activities, maint records & training of maint personnel.

 OIBBONS.T D . MERRHWEATHER.N. Region 2. Office of Director.

 CONLON.T E Division of Engineering & Operational Programs.
 84/01/10 5pp. 22223-357. 24X Fishe 50-348.84/01/12.8402140182
- 2120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater UMPS "Svc list encl.

 UMPSAN, E L. Division of Emergency Preparedness & Engineering esponse (Post B30103). 84/01/25 Consolidated Edison Co of New ork. Inc. 120pp. 22059 001 24X Fisher 50-000: 84/01/25, 8312120153
- 1190016 IE Info Notice 84-07, "Design-Basis Threat & Review of shicular Excess Controls" Bvc list and ORDAN E L Division of Emergency Preparadness & Engineering esponse (Post 830103), 84/02/03 Consolidated Edison Co of New ork, Inc. 119pp. 22114 179, 24X Fichs 50-000,84/02/03,8401190014
- 1190017 IE Bulletin 84-01, "Cracks in SWR Mark I Containment Vent JATOGE A LE BUILEVAN BETOU. "CTREAR IN DMK MATK I CONCAIRMENT VERNE BEAGERS" BYC 11st enci EYOUNGER G Director's Office, Office of Inspection and nforcement 84/02/03 Consolidated Edition Co of New York, Inc 32pp. 22177:156. E4X Fiche, 50-000,84/02/03,8401190017
- 2230017 Forwards request for add1 info re response to IE Bulletin D-1; "Masonry Wall Design " Info requested by 840315, NROA,S.A. Operating Reactors Branch 1. 84/02/09, CLAYTON,F L. Labama Power Co. 3pp. 28379 352 24X Fiche 50-848,84/02/09, 102230017.
- *170444 Forwards SER which delineates results of review of 830128 & 10123 requests for relief from inservice insp requirements.

 'Section XI of ASME Code for certain components & systice of granting of relief also encingos. A Operating Reactors Brench i 84/02/10 CLAYTON.F. Labame Power Co. 3pp. 22320-270 24X Fichs 50-348,84/02/10. 02170464

- --8402170466 SER supporting request for relief from inservice insprequirements of Section XI of ABME Code for certain components & sys ** Materials Engineering Branch 84/01/16 17pp 22320 293 24X Fichs. 50-348,84/02/10,8402170464
- --B402170472 Notice of granting of relief from Section XI of ABME Code inservice insp requirements VARQA.B A Operating Reactors Branch 1 B4/02/10 2pp. 22920 310 24X Fiche 30-348,84/02/10,8402170464
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Bys (10CFR50.App R)." Byc list encl enci JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365-259 24X Fiche 50-000,84/02/13,8401190041.
- 8401190039 IE Info Notice 84-08. "10CFR50 7. 'Employee Protection'" NOTIFOLDY E INTO NOTICE 84-05. INCORROW 7. Employee Protection ...
 SUC list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/14 Consolidated Edison Co of New
 York, Inc. 113pp 22365 141 24X Ficher 50-000, 84/02/14, 8401190039.
- 8401190045 IE Info Notice 83-63. Suppl 1, "Potential Failures of Westinghouse Type 8A-1 Differential Relays." 8vc list encl.

 JCRDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366 142 24X Fichs 50-000,84/02/15,8401190045
- 8401190062 JE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN, E.L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/02/21, Consolidated Edison Co of New York, Inc 1169p 22366.024 24X Fiche 50-000,84/02/21,8401190062. 22366.024 24X Fiche 50-000,84/02/21,8401190062,
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies "
 Svc list and!
 JORDAN: EL. Division of Emergency Preparedness & Engineering
 Response (Post 830103), 84/02/24 Consolidated Edison Co. of New
 York, Inc. 115pp 22430.304. 24X Fiche 90-000.84/02/24.8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals." Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/27. Consolidated Edison Co of New York, Inc 120pp 22431.060 24X Fiche 50-000,84/02/27,8401190067.
- R. Periodic operating reports & related correspondence
- 8402170127 Monthly operating rept for Jan 1984.W/840210 ltr. HAIRSTON.W.O., CLAYTON.F.L. Alabama Power Co. 84/01/31 22299.355. 24% Fiche 50-348.84/01/31.8402170127
- S. Reportable occurrences, LERs & related correspondence
- 8402030439 Forwards LERs 83-093/03L-0.83-094/03L-0. & 83-095/03L-0. CLAYTON.F.L. Alabama Power Co. 84/01/24 Region 2. Office of Director. 1p. 22059-012. 24X Fiche-50-348.84/01/24.8402030439.
- --8402030447 LER 83-093/03L-0 on 831225, diesel generator 18 declared inoparable when svc water supply header inlet & outlet isolation valves closed. Caused by frozen switch due to cold weather Valves opened manually.

 HATRBTON.M.G. Alabama Power Co. 84/01/24 2pp. 22067:013 24X Fiche: 50-348, 84/01/24, 8402030439.
- ---8402030453 LER 83-094/03L-0 on 831226, train 8 control room emergency air cleanup sys declared inoperable when air conditioner compressor failed to start Gaussd by hi/ld oil pressure Compressor Parts of Start Course by 1770 of pressor tripping Switch reset. HAIRSTON, W Q Alabama Power Co. 84/01/24 1p. 22069 015. 24X Fiche, 50-348, 84/01/24, 8402030439
- -8402030456 LER 83-075/03L-0. on 831226, loop 1 overtemp delta temp instrumentation channel declared inoperable when temp indicator TI-412C failed low Caused by failed summing ampers card Card replaced.

 HAIRSTON, W G. Alabama Power Co. 84/01/24 1p. 22069:016. 24X Fiche: 50-348,84/01/24,8402030439.
- 8402060360 RD: on 840112 & 14, plant vent stack effluent monitors R-278, declared inoperable when four of nine detectors failed, Failed detectors replaced CLAYTON.F L. Alabama Power Co. 84/01/30. D'REILLY, J. P. Regio Office of Director 1p. 22085, 119 24X Fiche 50-348, 84/01/30, 8402060360

- 8402040433 Forwards LERs 83-076/03L-0.83-047/03L-0.8.83-048/03L-0 CLAYTON,F L Alabama Power Co 84/01/30 Region 2, Office of Director 1p 22083 040 24X Fiche 50-348,84/01/30,8402060433
- --B4020&0438 LER B3-076/O3L-O on B31230 & 31 train A air conditioner compressor tripped Control room emergency air cleanup sys declared inoperable Caused by low freon Unit refilled & high pressure valve tightened
 HARRHTON W G Alabama Power Co B4/O1/30 2pp 22083 041 24X Fichs 50-348.84/01/30,84020&0433
- --8402060442 LER 83-067/03L-0 on 831231, high voltags power supply spiked low Power range monitor N-44 instrumentation channel declared inoperable Cause undetermined Instrumentation channel stabilized HAIRSTON, H o Alabama Power Co 84/01/30 lp 22083 043 24% Fichs: 50-348, 84/01/30, 8402060433
- --8402050448 LER 83-058/03L-0 on 831230, diesel generator 28 declared inoperable when valve G2P16V536 closed Caused by motor operator drawing excessive current Operator cleaned, design change evaluated & personnel counseled HALRBTON, W. G. Alabama Power Ce 84/01/30 2pp 22083 044, 24% Fiche, 50-348,84/01/30,8402060433
- B402060067 Informs that diesel generators declared inoperable on 10 occasions since change approved to Tech Spec 3/4 8 1, re diesel generator operability testing.per NRC 840120 request for info. Change decreased frequency of testing & maint CLAYTON.F L Alabama Power Co 84/01/31 VAROA.S A. NRC No Detailed Affiliation Given. 3pp 22088.227. 24X Fiche. 50-348.84/01/31,8402060067
- B402080350 LER B4-001-00: on 840109, reactor tripped due to low-low level in steam generator 18 Caused by low bearing oil pressure tripping pump 1A. Automatic rod control to be repaired & source range detectors replaced W/840203 ltr CLAYTON.F. L. Alabama Power Co 84/02/03 3pp 22130 351 24% Fiche: 50-348.84/02/03,8402080350
- DOCKET 50-052 LIMERICK GENERATING STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documents
 FELTON.J.M. Division of Rules and Records 83/10/31
 ROSENBAUM.D.M. Technical Analysis Corp. 19pp. 22193 292 24X
 Fiche 50-000:83/10/31,8402090003
- --B402090178 Handwritten graphs & notes re const activities, **NRC - No Detailed Affiliation Given B3/04/14 4pp. 82195:050. 24X Fichs 50-000,82/10/31,8402090003
- 8402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHLK, 8 J. Office of the Secretary of the Commission 83/12/14. Public Document Branch 1p. 22281.023 24X Ficha 50-000,83/12/14. 8402160003.
- ---8402140316 Discusses SECY-83-36 re director's denial of 10CFR2 206 patition on CPs.

 GHILK, 8. J Office of the Secretary of the Commission 83/02/28 PLAINE, H. H. Office of the General Counsel 1p. 22281: 268. 24) Fiche: 50-000, 63/12/14, 8402160003
- 84021704&1 FOIA request for minutes of second corporate mgt meeting on 831018 re facility supplemental cooling availability, 8U9ARMAN.R.J Sugarman & Denworth. 83/12/14 STAROBTECKI.R Division of Project & Resident Programs 2pp. 22305 348. 24X Fiche: 50-352.83/12/14.8402170461
- 8402240275 FOIA request for three categories of documents re facilities. SUGARMAN.R.J. Bugarman & Denworth. B3/12/20 Division of Rules and Records. 2pp. 22374-276. 24X Fiche.50-352.83/12/20,8402240275.
- 8402230391 FDIA request for IE Bulletin 83-06, in connection w/831214 request for documents re supplemental cooling water sys BUGARHAN, R. J. Sugarman & Denworth 84/01/09 BTAROSTECKI, R Division of Froject & Resident Programs 1p. 22378 102 24X Fiche. 50-352, 84/01/09, 8402230391.

- --8402230395 FOIA request for documents re supplemental cooling water sys, in connection w/831018 second corporate mgt meeting concerning proposals for supplemental cooling water sys availability SUGARMAN.R J Sugarman & Denworth 63/12/14 STAROSTECKI,R Division of Project & Resident Programs 2pp 22378 103 24X Fiche 50-352,84/01/09,8402230391
- B312120136 Board Notification B4-011 discusses NRC use of terms "important to safety" & "safety-rolated" EISENHUT. D 9 Division of Licensing 84/01/18 PALLADINO Commissioners 72pp 22241 008 24X Fiche 50-000,84/01/18,831212
- 8402020452 Notification of 840126 meeting w/util in San Franciso.,CA to review capability of plant structures to withstand overpressures from external accidents involving explosions MARTIN.R E Licensing Branch 2 84/01/20 SCHWENCER.A Licensing Branch 2 4pp 22062 171 24X Fiche 50-352.84/01/20,8402020452
- 8401300328 Forwards K Shiu 840106 memo re single failures in facility PRA Memo satisfies contractual obligations for Task 1 of Project 4 in FIN A-3393 Related info encl PAPAZOBLOU, I A Brookhaven National Laboratory FIN A-3393 84/01/23 CHELLIAH.E Reliability & Hisk Assessment Branch 8pp 22221 235 24% Fiche 50-352.84/01/23,8401300328
- 8402070475 Addresses concerns stated by 8 Everett during 831018 limited appearance before ASLB re release of liquid or gaseous effluents from plant & use of Schuylkill River DES & SER. Section 11 encl W/o encls SCHWENGER. A Licensing Branch 2 84/01/26 EVERETT. B Affiliation Not Assigned 4pp 22142 079 24X Fichs 50-352, 84/01/26, 8402070475
- B402070481 Addresses concerns stated by W Andrews during B31018
 limited appearance before ABLE re potential hazard to
 Phoenixville potable water supply, evacuation plan & handling
 waste matis SER & DES encl W/o encls
 SCHWENCER.A Licensing Branch 2 84/01/27 ANDREWS, W Affiliation
 Not Assigned 4pp 22142 072 24% Fiche 50-352, B4/01/27,
 8402070481
- 8402170465 Responds to FOIA request for minutes of second corporate mpt meeting on 831018 re supplemental cooling water sys for facility NRC has no documents subj to request FELTON.J M Division of Rules and Records 84/01/27 SUGARMAN.R J Sugarman & Denworth. 1p 22305 347 24X Fiche 50-352,84/01/27,8402170465
- 8402240277 Responds to FOIA request for three categories of documents re facilities. Forwards App A Documents 1-4 Documents 5-9 provided previously via avc list FELTON. J M Division of Rules and Records 84/01/27 SUGARMAN, R J SUGARMAN & Denworth 2pp. 22374 298 24X Fiche 50-000, 84/01/27, 8402240277
- --8402240275 Section 5 0, "Startup Addenda," to monthly project status rept * Philadelphia Electric Co * Bechtel Corp 83/12/01 79pp 22394 355 24% Fiche 50-000,84/01/27.8402240277
- 8402020277 Forwards Amend &1 to OL application, Rev 7 to design assessment rept available in FDR (Category A), Rev 8 to embrygency plan (Category F) & Rev 28 to FGR (Category K) BRADLEY, E J Philadelphia Electric Co 84/01/31 DENTON, H R Office of Nuclear Reactor Regulation, Director, 3pp 22053 252 24X Fich. 50-352, 84/01/31, 8402020277.
- --840202020388 Amend 61 to OL application re changes to FSAR reflecting accurately facility design, Rev 8 to emergency plan & Rev 7 to design assessment rept.
 BOYER, V S. Philadelphia Electric Co 84/01/31 App 22053 254 24X Fichs 50-352,84/01/31,8402020277.
- --8402020293 Rev 7 page changes to design assessment rept * Philadelphia Electric Co 84/01/31 53pp 22053 260. 24X Fiche 50-352,84/01/31,8402020277
- 8402130128 Notification of 840222 & 24 meetings w/util in Linfield, PA to discuss status of const & completion schedules for facilities Agenda encl.

 MARTIN, R E Licensing Branch 2 84/02/03 SCHWENCER, A Licensing Branch 2, 8pp 22237 157, 24% Fiche 50-352, 84/02/03, 8402130128
- B402150430 Forwards "Control of Heavy Loads at Nuclear Power Plants, Limerick Generating Station Units 1 & 2 (Phase II)," draft technical evaluation rept. Response to remaining concerns identified in Sections 2 3 t. 6.2 3 2 6 & 2.3 3 6 requested. SCHWENCER, A. Licensing Branch 2. FIN A-6457 64/02/06 BAUER, E 9 Philadelphia Electric Co 3pp. 22263 276 24X Fiche 50-352,84/02/06.8402150430

- --8402150435 "Control of Heavy Loads at Nuclear Power Plants, Limerick Generating Station Units 1 & 2 (Phase II), " draft technical evaluation rept FRIEDERICHS, 9 , STICKLEY, T H EQ&G, Inc FIN A-6437. 83/10/30, NRC No Datailed Affiliation Given 29pp 22263 279 24X Fiche 50-352, 84/02/06, 8402150430
- 8402210001 Summary of 840126 meeting w/util & Bechtel in Ban Francisco, CA re blast overpressure effects on strutures MARTIN. R E Licensing Branch 2 84/02/08 Licensing Branch 2 34pp 22322-328 24X Fiche 50-352.84/02/08.8402210001
- 8401190059 Board Notification 84-032 provides add1 info on environ qualification Submittal augments info in Board Notifications 84-004 & 84-007 EISENHUT. D O Division of Licensing 84/02/13 Atomic Safety and Licensing Board Panel 10pp 22314 204 24% Fiche 50-000.84/02/13.8401190059
- 8402210437 Redistributes and 1 NRC 840110 ltr to util re design verification program to ensure receipt by all parties on facility avo list

 9CHWENCER: A Licensing Branch 2 84/02/13. GAUER: E G. Philadelphia Electric Co 1p 22323 333 24X Fiche 50-332-84/02/13.8402210437
- 8402170117 Forwards draft FBAR changes modifying Section 14 2 reinstrument air cleanliness & responses to request for addition of requestions 410 73 & 410 74 Info will be incorporated in FBAR rev scheduled for Feb 1984.

 BRADLEY, E. J. Philadelphia Electric Co. 84/02/15 8CHHENCER, A. Licensing Branch 2. 7pp. 22300 002. 24% Fiche 50-352,84/02/15,8402170117
- B4011900AB Board Notification 84-039 provides "Bys Interaction Program," task action plan for Unresolved Bafety Issue A-17 Distribution list and EBERHVITD © Division of Licensing 84/02/16 PALLADIND COMMISSIONERS, Bpp 22482 091. 24X Fiche 50-000,84/02/16,84011900AB
- 8402230084 Forwards add1 info requested per 840206 telcon in affort to enhance review of facility equipment qualification rept App B & E will be incorporated in rev scheduled for Apr 1784 M/o encl KEMPER.J B Philadelphia Electric Co 84/02/16 SCHWENGER, A. Licensing Brench 2, 3pp 28361.285 24X Fiche 30-332,84/02/16, 8402230084
- 8402240364 Responds to 840109 & 0126 requests re clarification of scheduling terms & current schedule for facility const completion & fuel loading. ABLE initial decision on OL application not expected until Jan 1985 FIBENHUT, D 9 Division of Licensing 84/02/16, SUOARMAN.R. J. SUGARMAN & Denworth, 1p, 22380; 138. 24X Fiche. 50-352. 84/02/16, 8402240364
- D NRC Draft/Fine: Environmental Statements, supple & correspondence
- 8402060080 Forwards responses to DOI 830826 water-related comments on BES. Clarification on listed water resource issues requested. HANSLER, Q. M. Delaware River Basin Commission. 64/01/21. Division of Licensing. 53pp 22089:138. 24X Fiche 50-352,84/01/21. 8402060080
- B402010143 Offers no comments on DES. DAVIB,V W Agriculture, Dept. of 84/01/27 SCHWENCER.A Licensing Branch 2. 1p 22038 216 24X Fiche 30-352,84/01/27. 8402010143
- 8402070340 Forwards technical comments based on review of Suppl 1 to DEB NRC should consider risks associated w/range of events expected to occur offsite. Documents rated as ER-2. BRUBAKER, H P Environmental Protection Agency 84/02/03 MARTIN, R. E. Office of Nuclear Reactor Regulation, Director. Spp. 22096-329. 24X Fiche: 50-352, 84/02/03, 8402070340.
- E402080022 Forwards comments & concerns re Suppl 1 to DES (NUREQ-0974) re operation of facilities BOYER, V. S. Philadeiphia Electric Co 84/02/06 EISENHUT, D. C. Bivision of Licensing 11pp 22126 079. 24X Fiche, 50-352, 84/02/06, 8402080022
- 402140130 Forwards State of PA Dept of Health comments on Suppl 1 to DEE Cancer misk, even in worst case situation, acceptable, loss safety during evacuation longs. 3 J fennsylvania. Commonwealth of, 84/02/06. SCHWENCER, A icensing Branch 2, 2pp 22230:076. 24X Fiche. 50-332,84/02/06,

- 8402220477 Comments on Suppl 1 to DES for facilities Consequences of severe accidents on Schuukill River not clarified & adverse affects on fish & wildlife not considered.

 BLANCHARD. B Interior. Dept of 84/02/08 Division of Licensing 2pp 22340 064 24X Fichs 50-352,84/02/08,8402220497
- 8402290253 Forwards original typescript of revised comments dtd Feb 1984 to be appended into FEB Corrected version supersedes Jan 1984 version HANSLER, J M Delaware River Basin Commission. 84/02/27 Division of Licensing
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 840224030B FOIA request for SBER & Tech Specs re facility. SUCARMAN,R J Sugarman & Denworth, 84/01/25 NRC - No Detailed Affiliation Given Ip 22381 343 24X Fiche 50-352,84/01/25, 8402240308
- 8402020300 Forwards FSAR page changes modifying response to NRC Request for Add1 Info 271 2 re Equipment Qualification Branch BER Open Item 6 FSAR changes will be incorporated in rev scheduled for Feb 1994
 BRADLEY.E J Philadelphia Electric Co. 84/01/30 BCHWENCER.A. Licensing Branch 2 4pp 22035 184 24X Fiche 50-352,84/01/30,8802020300
- 8402130609 Forwards request for add1 info re results of control sys failure study in two repts entitled, "Control Sys Failure Evaluation Rept" & "Common Sensor Failure Evaluation Repts," to complete BER outstanding issue SCHWENCER: A Licensing Branch 2. 84/02/01 BAUER, E @ Philadelphia Electric Co. 7pp. 22214 297 24X Ficha: 50-352,64/02/01.8402130609.
- 8402240315 Responds to FOIA request for SSER & Tech Space re facility Requested documents available in FDR FELTON. J M Division of Rules and Records 84/02/07 BUGARNAN.R J BUGARNAN & Denworth 1p 22381 344 24X Fiche. 50-352
- 8402170074 Summary of 840131 meeting w/util re status of fire protection analyses & proposed mod to mitigate fires Items 35-57 in SER (NAMEG-0991) satisfactorily addressed KINTMER, L. L. Licensing Branch i B4/02/08. Licensing Branch i. 13pp. 22318:168 24X Fichs:50-352,84/02/08.8402170074.
- 8402210145 Forwards FBAR page changes modifying response to Hatls Engineering Branch request for addl info re details of preservice insp program.per 840203 telcon & SER Confirmatory Item 12 Info will be incorporated in next FBAR BRADLEY.E J Philadelphia Electric Co. 84/02/15, BCHWENCER.A. Licensing Branch 2 4pp 22317:155, 24X Fiche.50-352,84/02/15,8402210145
- 8402270005 Informs that administrative & implementing procedures for fire protection plan will include listed controls.per Confirmatory Issue 37 of SER (MUREG-0991) Procedures will be issued prior to fuel load.

 KEMPER.J 8 Philadelphia Electric Co. 84/02/21. SCHWENCER.A. Licensing Branch 2. 3pp. 22391 284 24% Fiche 50-352,84/02/21. 8402270005.
- 8402270166 Forwards dreft FSAR changes to appear in Feb FSAR rev re BER (NUREG-0991) Section 4, 4 6, "Loose Parts Monitoring Sys."

 Table 4 1 Addl info requested in Table 4 1 should satisfy SER Confirmatory Issue 11

 KEMPER.J.S Philadelphia Electric Co 84/02/21. SCHWENCER, A. Licensing Branch 2 21pp. 22386 043 24X Fiche: 50-352, 84/02/21. 8402270166
- F. Security, medical, emergency & fire protection plans.
- 8402020239 Responds to NRC Bi0811 request re quarterly updates of const completion date Echedule for implementing Suppl 1 to NUREQ-0737 will permit fuel loading by 840801. KEMPER, J S Philadelphia Electric Co. 83/12/27 EISENHUT, D G. Division of Licensing. 2pp. 22057 021 24% Fiche 50-352.83/12/27, 8402020239
- B402010332 Notification of 840131 meeting w/util in Bethasda, MD to discuss fire protection measures. KINTNER, L L Licensing Branch 1. 84/01/16, SCHWENCER, A. Licensing Branch 2. 4pp 22037:305. 24X Ficher 50-352, 84/01/16, 8402010332.

- 8402010244 Forwards FEMA 840130 1tr to ASLB & FEMA 840111 memo providing responses to offsite emergency planning questions raised at 831017-18 limited appearance sessions in Phoenisville/PA Phoenixville, PA
 VDQLER, B. H. Hearing Branch 2 84/01/30 BRENNER, L. COLE, R. F.,
 MCRRIS, P. A. Atomic Safety and Licensing Board Panel 5pp
 22040 187 24% Fiche 50-352,84/01/30,8402010244
- 8402020277 Forwards Rev B to emergency plan BRADLEY.E J Philadelphia Electric Co 84/01/31 Office of Nuclear Reactor Regulation. Director 3p 24X Fiche 50-352.84/01/31.8402020277 DENTON, H R Зрр 22053 252
- --9402020294 Rev 8 to emergency plan * Philadelphia Electric Co 84 Fiche: 50-352, 84/01/31, 8402020277 84/01/31 28pp 22053 312 24X
- 8402100027 Forwards proposed numerical designation for 840131 offsita smargency planning contentions, supplementary basis info for Contentions VIII-27 & VIII-42 & discussion of Catawba balancing test requirements Cortificate of Svc encl. IIIZER, P. Limerick Ecology Action 84/02/05 BREINHER, L., COLE, F. HORRIB, P. A Atomic Safety and Licensing Board Panel 12pp. 22182 084 24X Ficher 50-352.84/02/05,8402100029
- 8402170074 Summary of B40131 meeting w/util re status of fire protection analyses & proposed mod to mitigate fires Items 35-57 in SER (NUREO-0791) satisfactorily addressed KINTNER, L. L. Licensing Branch 1 84/02/08 Licensing B13pp. 22318: 148 24X Fiche 50-352, 84/02/08, 8402170074 Licensing Branch 1
- 8402170193 Forwards requests for add1 info re fire protection program Response by 840229 requested.

 8CHMENCER.A. Licensing Branch 2 84/02/09 BAUER.E 0 Philadelphia Electric Co 5pp 28313.268 24X
 Fiche 50-352.84/02/09.8402170193
- B402170401 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per B10709 Generic Ltr B1-27 W/o request entire plan will be placed in PDR BCHWENCER: A Licensing Branch 2 84/02/09 BAVER: E Q Philadelphia Electric Co 3pp 22313 179 24X Fichs. 50-352, 84/02/09, 8402170401
- 8402270005 informs that administrative & implementing procedures for fire protection plan will include listed controls, per Confirmatory Issue 37 of SER (MUREG-0971) Procedures will be issued prior to fuel load, KEMPER, J B. Philadelphia Electric Co 84/02/21 SCHWENCER, A. Licansing Branch & 3pp 22391 284 24X Fiche 50-352, 84/02/21, 8402270005.

O. Adjudicatory correspondence

- 8402010208 Forwards documentation re status of investigations into applicant use of products mfg by Hayward Tyler Pump Co. Tubs-Lina Co & Ray Miller, Inc. Documentation includes IE Bullstin 83-07. Bulletin 83-07.
 HODDODN, A. Hearing Branch 2 84/01/23. BRENNER, L., COLE, R.F.,
 HORRIB.P. A. Atomic Safety and Licensing Board Panel. 100pp.
 22042:001. 24X Fiche. 50-352, 84/01/23, 8402010208.
- 8402030R34 Forwards util responses to Air & Water Pollution Patrol sixth, seventh & eighth sets of interrogatories re GA/welding contention. Requested info available for perusal near util
- Neadquarters,
 NETTERHAHN, H J, Conner & Wetterhahn, 64/01/27 ROMAND, F R
 Romano, F, 1p, 22069, 280 24X Fishe, 50-352, 84/01/27, 8402030254
- --8402030270 Answer to sixth set of interrogatories on GA/welding contention BOYER, V 8 Philadelphia Electric Co. 84/01/25, Air and Water Pollution Patrol. 7pp. 22067-281 24X Fiche.50-382,84/01/27. B402030254.
- --B402030275 Answer to seventh set of interrogatories re GA/welding Contention.
 BOYER, V B. Philadelphia Electric Co. 184/01/25, Air and Water Pollution Patrol. 3pp. 22069:288 24X Fiche: 50-352,84/01/27,
- ---8402030277 Answer to seventh set of interrogatories re GA/welding contention Certificate of 8vc ancl BOYER, V S. Philadelphia Electric Co. 84/01/25 Air and Water Pollution Patrol 19pp. 22069:291. 24X:Fiche. 50-352,84/01/27,8402030254.

- 8402010205 Response to Del-Aware 840111 motion for admission of Contentions V-35 & V-36 Motion should be dismissed for lack of jurisdiction Jurisdiction lies w/ASLAR Certificate of Svc ancl MILCOVE,M N Hearing Branch 2 84/01/30 Atomic Safety and Licensing Board Panel 10pp 22040 305 24% Fiche 30-352,84/01/30, 8402010205
- 8402010R06 Filing of issues of concern to City of Philadelphia.per ASLB 8401R0 memorandum & order Vtil & state should be required to revise smergency plans Certificate of Svc encl 8MDLEN.H Philadelphia.PA 84/01/30 13pp 2R042 114 24X Fiche 50-352,84/01/30.8408010R06
- 8402010225 Response opposing M Lawis 831224 motions re Contention I-62 No significant new info presented No nexus between proposed scenarios & contended issues shown Certificate of Svc encl HRIGHT.N A Hearing Branch 2 84/01/30 Atomic Safety and Licensing Board Panel 13pp 22040 172 24X Fiche 50-352, 84/01/30, 8402010225.
- 8402010235 Forwards A Schwencer response to ASLI 831028 request for supporting analysis per exemption from requirements of QDC 36 re containment isolation for hydrogen recombiner W/o encl
 WooleRr B H Hearing Branch 2 84/01/30 BRENNER, L , COLE, R F .
 MORRIB: P A Atomic Safety and Licensing Board Panel 2pp
 22042 257. 24X Fiche 50-352, 84/01/30, 8402010235
- 8402010244 Forwards FEMA 840130 ltr to ASLB & FEMA 840111 memo providing responses to offsite emergency planning questions raised at 831017-18 limited appearance sessions in Phoenixville, PA PhoenixVIIIe.PA
 VOOLER.B H Hearing Branch 2 84/01/30 BRENNER.L , COLE.R F ,
 MORRIS.P A Atomic Bafety and Licensing Board Panel Spp
 R2040-187 R4X Fiche.50-352,84/01/30,8402010244
- 8402020229 Statement of issues re offsite emergency planning Util must update evacuation time estimate study for station plume exposure pathway emergency planning zone Certificate of Syc FERKIN, Z G Pennsylvania, Commonwealth of, B4/01 Bafety and Licensing Board Panel App 22037 042 Fiche 50-352,84/01/30,8402020229
- 8402030197 Notice of withdrawal of appearance in proceeding Certificate of Bvc encl LAVERTY.J H Philadelphia Electric Co LAVERTY.J H Conner & Watterhahn 84/01/30 Spp. 22067 335 24% Fiche: 50-352, 84/01/30, 8402030197.
- 8402020217 Order re Air & Water Pollution Patrol (AMPP) 840126 motion for extension of time for discovery on Contention VI-1 Unilateral request for extension of discovery period does not operate to extend time AMPP response must be timely BRENNERs. . Atomic Bafety and Licensing Board Panel 84/01/31 Air and Water Pollution Fatrol. Spp. 22054 317 24X Ficha 50-352.84/01/31.8402020217
- 840R060173 Forwards offsite emergency planning contentions per ASLB 830516:1122 & 840120 orders ZITZER:P Limerick Ecology Action 84/01/31 BRENNER; L. COLE:R.F. MORRIS:P.A. Atomic Safety and Licensing Deard Panel 3pp 22088 312 24X Fiche, 50-352:84/01/31;8402060173
- --B402060176 Offsite emergency planning contentions based on currently available draft radiological emergency response plan Certificate of Svc encl # Limerick Ecology Action 84/01/31. Atomic Bafety and Licensing Board Panel 64pp. 22088:313 24% Fiche:50-352,84/01/31.8402060173.
- 8402080188 Forwards responses to questions re emergency planning.per ABLE directive during 831017-18 prehearing conference FERKIN, Z. Pennsylvania, Commonwealth of, 84/01/31 BRENNER, L., GOLE, R. F., MORRIS, P. A., Atomic Bafety and Licensing Board Panel. ip 22129-184 24X Ficher 50-352, 84/01/31, 8402080188
- --8402080190 Responses to questions re offsite emergency planning.
 Reception ctrs sole purpose is to serve as pass-through
 point Certificate of Bvc encl.
 FERKINZ. Pennsylvania, Commonwealth of, 84/01/31. 15pp
 22129.185 24X Fiche 50-352,84/01/31,8402080188
- 8402150420 Ack receipt of Del-Aware 2.206 patition requesting NRC reopen CP proceedings re facilities Circumstances surrounding alleged const impacts do not require action at present time. Notice of publication encl. DENTON, HR Office of Nuclear Reactor Regulation, Director 84/01/31. LOCKE, R.T. Sugarman & Denworth 7pp 22263 335 pfiche: 50-332,84/01/31,8402150420.

- --B402150423 Notice of request for action under 10CFR2 206 seeking reopening of CP proceedings for facilities DENTON.H R Office of Nuclear Reactor Regulation, Director B4/01/31 ip 22263 341 24x Fiche 50-352.B4/01/31.B402150420
- 3402060131 Forwards Pennsylvania Public Util Commission ruling on exceptions, issued on 840113 by Judge Kranzel re Bradshaw Reservoir pumphouse RADER, R M Conner & Wetterhahn RADER, R M Philadelphia Electric Co 84/02/01 BRENNER, L Atomic Safety and Licensing Board Panel 8pp 22089 104 24X Fiche 50-352,84/02/01,8402060131 Co 84/02/01 8pp 220--
- 3402060164 Forwards answers to applicant second set of interrogatories & request for production ad documents on Contention VI-1 Certificate of Syc encl Related correspondence ROMANO.FR Air and Water Pollution Patrol 84/02/01 Atomic Safety and Licensing Board Panel 1p 22068 306 24X Fiche 50-352.84/02/01.8402060164
- -8402060168 Answer to applicant second set of interrogatories & request for production of documents on Contention VI-1 Related correspondence
 ROMANDER Air and Water Pollution Patrol 84/02/01
 Philadelphia Electric Co 5pp 22088 307 24x
 Fiche 50-352,84/02/01,8402060164
- 402070327 Forwards rev to City 840130 emergency planning filing Revs consist of elimination of 830715 date in caption.correction of typographical error on Page 5 & rev of Section III. Paragraph 2 on Page 9.

 BUSH, M W Philadelphia. PA 84/02/01 BRENNER, L Atomic Bafety and Licensing Board Panel 1p 22074 260 24X

 Fiche 50-332,84/02/01.8402070327
- -8402070331 Revised filing of issues of concern per ASLB 840120 memorandum & order confirming rulings made at hearing Stated issues & concerns should be included in scope of instant proceeding Certificate of Svc ancl SMOLEN.H Philadelphia, PA 84/02/01 Atomic Safety and Licensing Board Panel 13pp 22096 261 24X Fichs 50-352,84/02/01,8402070327
- 402060059 First set of interrogatories & request for production of documents re Limerick Ecology Action onsite emergency planning contentions Certificate of Svc encl CONNER.T B Philadelphia Electric Co CONNER.T B Conner & Metterhahn 84/02/02 Limerick Ecology Action 21pp 82088 2 24X Fiche 50-352,84/02/02,8402060059 22088 202
- 102060217 Forwards applicant appeal to State of PA Public Util Commission from ruling of Judge Krantel on exceptions filed CONNER.T B Conner & Wetterhahn. CONNER.T B Philadelphia Electric Co 84/02/02 DRENNER.L. MORRIS.P.A. COLE.R F Atomic Safety and Licensing Board Panel 5pp 22087 142 24% Fiche 50-352, 84/02/02, 8402040219
- IO2070242 Transmittal of util testimony re ability of safety-related structures to withstand effects of postulated debunation resulting from ruptures of ARCO & Columbia Gas transmission pipelines & request to set schedule.
 WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner Metterhahn 64/02/03 2pp 22101 254 24X Fiche BO-352,84/02/03,8402070242
- 3402070251 Testimony of HW Vollmer, D Marang, KP Buchert, AK Wong, AUROVICED TESTANDY OF HW VOLLMET, D MATAND, MP SUCHET, AK Wong,

 JW Benkert, R Palaniswamy & GK Ashley re ability of
 safety-related structures to withstand effects of postulated
 detonation Wyrosf quelifications & Certificate of Svc
 VOLLMER, H W, MARAND, D., BUCHERT, K P Philadelphia Electric Co
 84/02/03 48pp 22101 256 24X Fiche 50-952, 84/02/03, 8402070242
- 02070282 First set of interrogatories & request for production of documents on Contention 1-42 METTERHAMN.M.J. Philadelphia Electric Co. METTERHAMN.M.J. Conn. Metterham 8402/03 Philadelphia, PA. 11pp 22095 026 2: Fiche.50-352,84/02/03,8402070282
- 3402070287 Becond set of interrogatories & request for production of documents on Contention I-42
 WETTERHANN.M J Philadelphia Electric Co. WETTERHANN.M J Conner & Wetterhahn B4702/03 Limerick Ecology Action 2pp. 22095 037. 24X Fiche 50-352,84/02/03,8402070282
- 02070272 First set of interrogatories & request for production of documents on Contention 1~41 WETTERHAHN.M.J. Philadelphia Electric Co. WETTERHAHN.M.J., Conne & Wetterhahn B4/02/03, Philadelphia, PA. 9pp, 22095; 039, 24X Ficha 50-352, 84/02/03, 8402070282.

- --8402070309 First set of interrogatories & request for production of documents on Contention I-41 Certificate of SVc ancl WETTERHANN, M J Philadelphia Electric Co WETTERHANN, M J Conner & Wetterhahn 84/02/03 Limerick Ecology Action 12pp 22095 048 24X Fiche 50-352,84/02/03,8402070282
- 8402070286 forwards response to Air & Water Pollution Patrol tenth, Bleventh & twelfth set of interrogatories & requests for documents re Contention VI-1 WETTERHAHN, M J. Conner & Wetterhahn WETTERHAHN, M J. Philadelphia Electric Co. 84/02/03 ROMAND.F.R. Air and Water Pollution Patrol 1p. 22076 132 24% Fiche 50-352,84/02/03,8402070286
- --8402070312 Answers to tenth set of interrogatories on QA/welding contention (Discovery 25) BOYER, V S Philadelphia Electric Co 84/02/01 Air and Water Pollution Patrol 7pp 22096 133 24% Fiche 50-352,84/02/03, 9402070286
- --8402070317 Answers to eleventh sat of interrogatories on GA/welding contention (Discovery 23)

 + Philadelphia Electric Co 84/02/01 Air and Water Pollution Patrol 4pp 22094 140 24X Fiche 50-352,84/02/03,8402070284
- --8402070322 Answers to twelfth set of interrogetories on GA/welding contention (Discovery 24) Certificate of Svc encl, * Philadelphia Electric Co 84/02/01 Air and Water Pollution Patrol 22pp 22096 144 24X Fiche 50-352,84/02/03,8402070286
- 8402080139 Forwards Interrogatories 14-30 Related correspondence BUSH.M.W Philadelphia, PA 84/02/03 VOQLER,8 H Hearing I 2 WETTERHAHN.M Conner & Wetterhahn 1p 22132 043 24X Fiche 50-352,84/02/03.8402080139 Hearing Branch 043 24X
- --8402080145 Interrogatories 14-21 re environ qualification * Philadelphia, PA 84/02/03 Philadelphia Electric Co 3pp 22132 044 24X Fiche 50-352,84/02/03,8402080139
- ~-8402080146 Interrogatorias 22-30 re environ qualification * Philadelphia, PA 84/02/03 Office of the Executive Legal Director 2pp 22132 047 R4X Fiche 50-352,84/02/03,8402080139
- 8402100029 Farwards proposed numerical designation for 840131 offsite ORLOWER PINANCES proposed numerical obsignation for H40/31 orn smergency planning contentions supplementary basis info for Contentions VIII-27 & VIII-42 & discussion of Catawba balancing test requirements Cortificate of Svc enc ZITZER, P. Limerick Ecology Action 84/02/05 BRENNER, L., COLE.R F. MORRIS, P.A. Atomic Bafety and Licensing Board Panel 12pp 22/02/084. 24X Fiche 50-352,84/02/05,8402100029
- 8402100140 Interrogatories & request for production of documents of City of Piladelphia to util re-sus interaction H/Certificate of Bvc Related correspondence
 BUBH-M.W. Philadelphia, PA 84/02/06 Philadelphia Electric Co
- 8402100178 Responds to applicant first set of interrogatories re Contention I-42 Certificate of Svc encl Related Contention and Content of the Conten
- 8402140175 Forwards proposed prehearing schedule re environ qualification of equipment & sus interaction, for concurrence Related correspondence BUSH.M W Philadelphia, PA 84/02/08, WETTERHAHN, M Conner & Wetterhahn 2pp 22230 206, 24X Fiche 50-352,84/02/08,8402140175.
- 8402180074 Answer opposing Air & Water Pollution Patrol 840126 motion for extension of discovery time & other relief based on new info Motion devoid of any concrete support for relief requested Certificate of 8vc encl WETTERHAHN, N. J. Philadelphia Electric Co. WETTERHAHN, M. J. Conner Wetterhahn, 84/02/09 Atomic 8afety and Licensing Board Panel. 7pp. 22249 317 24% Fiche: 50-352,84/02/09,8402150094 Conner &
- 8402220317 Forwards motion for deposition of named individuals, new tontantion re ask motion for apposition of named individuals containtion re askestos contamination & motion to compel applicant to pracisely answer interrogatories. W/Gertificate of Svc Related correspondence
 ROMAND,F R Air and Water Pollution Patrol 84/02/10
 Safety and Licensing Board Panel 1p 22334 236 24X
 Fiche 50-352/84/02/10/8402220317 Atomic
- --8402220320 Motion for deposition of named individuals in applicant 831205 answer to first set of interrogatories Means for completeness of record for same individuals re broomstick affair should be suggested ROMANO, F.R. Air and Water Pollution Patrol. 84/02/11, Atomic Safety and Licensing Board Panel ip 22334-237 24X Fiche 50-352,84/02/10,8402220317 Atomic

- --8402220324 Motion to admit new contention re asbestos contamination ROMAND, F R Air and Water Pollution Patrol 84/02/15 Atomic Safety and Licensing Board Panol 1p 22334 238 24X Fiche 50-352,84/02/10,8402220317
- --8402220327 Motion to compel answers to listed interrogatories ROMANO,FR Air and Water Pollution Patrol B4/02/10 Philadelphia Electric Co 2pp 22334 237 24X Fiche 30-352,84/02/10,8402220317
- B402160264 Answer to Limerick Ecology Action, City of Philadelphia & State of PA contentions re offsits emergency planning Cartificate of Svc encl CONNER, T. B. Philadelphia Electric Co. CUNNER, T. B. Conner & Hetterhahn B4/02/13 Atomic Safety and Licensing Board Panel
 - /13 Atomic Bafety and Licensing Board Panel 24X Fiche 50-352,84/02/13,8402160264 22274 138
- 8402220228 Forwards GJ Bradley 840124 cover 1tr to util application to store fuel onsite Application will be forwarded under
 - separate cover VOOLER, B. H. Hearing Branch 2 84/02/13 BRENNER, L., MORRIS, P.A., COLE, R. F. Atomic Safety and Licensing Board Panel 3pp 22340 149 24X Fiche 50-352,84/02/13.8402220228
- 850222250 Responds to 840202 itr referencing 840127 telcon requestions on supplemental cooling water source Caseload forecast panel rept & Commission rept to Subcommittee on Energy & Water Development encl HODODON, A P Hearing Branch 2 84/02/13 SUGARMAN, R J Bugarmal Denworth 17pp 22339 210 24X Fiche 50-352,84/02/13,8402220250 Energy & WE. HODODON, A P He Sugarman &
- 8402160209 Rept to ABLB re Contentions I-41, I-42 & onsite emergency planning Limerick Ecology Action. City of Philadelphia, State of PA & NRC staff agree w/rept, w/exception of listed items Certificate of Syc encil CONNER, T B. WETTERHAHN, M. J. Philadelphia Electric Co CONNER, T Conner & Wetterhahn 84/02/14 10pp 22276 261 24X Fiche: 50-352, 84/02/14, 8402160209 Co CONNERT B
- 8402160238 Transmittal of addl matl re Contentions V-3a & V-3b concerning ability of tafety-related structures to withstand effects of postulated detonation resulting from pipeline ruptures Certificate of Svc encl METTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner Wetterhahn 84/02/14 5pp 22274 319 24X Fiche 50-352,84/02/14,84/03/14 Conner &
- B402210277 Issues of concern w/Suppl 1 of DES Impact statement acceptable Cartificate of Svc encl BUSH.M W Philadelphia, PA 84/02/14 20pp 22315 320 24X Fiche: 50-352.84/02/14.8402210277
- 8492170974 Forwards 9M Hurst B40207 limited appearance ltr.to be served on all parties.

 LANE, V. M. Atomic Bafety and Licensing Board Panel 84/02/15 CLEMENTS, W. Docketing & Services Branch 1p 22299 360 24X Fiche, 50-352,84/02/15,8402170094
- --B402170076 Advises that Upattinas School not originator of draft evacuation plan, as previously indicated Proper evacuation of area impossible HURST, S M Affiliation Not Assigned B4/02/07 DRENNER, L. Atomic Safety and Licensing Board Panel 1p. 22279 361 24X Fiche 50-352, 84/02/15, 8402170074
- B402220247 Fbrwards util B40206 application under 10CFR70 to amend license to store fuel onsite Related correspondence VOLGER, B H Hearing Branch 2 84/02/15 BRENNER, L. MORRIS, P A COLE, R F. Atomic Safety and Licensing Board Panel 4pp 22339 : 24X Fiche 50-352,84/02/15,8402220247
- B40222008B Proposed findings of fact & conclusions of law in form of partial initial decision on Contention V-4 re carburetor icing Notice of appearances & Certificate of Bvc encl HETTERHAHN, M J. NICHOLEN N Philadelphia Electric Co. HETTERHAHN, M J. Conner & Wetterhahn 84/02/16 45pp 22326 118 24X Fighe, 50-352, 84/02/16, 8402220088
- 8402220143 Contentions on environ assessment of severe accidents as discussed in DEG. Suppl 1 DEB does not include consideration of whole range of accident scenarios necessary to produce cost-benefit analysis W/Certificate of Svc.
 ELLIOT, G. W Limerick Ecology Action 84/02/16. Atomic Bafety and Licensing Board Panel 16pp 22327.030 24X Fiche. 50-352, 84/02/16, 8402220143.
- 8402220221 Response to City of Philadelphia 840131 request for info re DES, Suppl 1 Executed affidavit of S Acharya & Cartificate of Svc encl. Related correspondence HUDSDON, A. P. Hearing Branch 2, 84/02/16 Atomic Safety and Licensing Board Fanel, Spp. 22340 139 24X Fiche 50-352,84/02/16, 8402220221

- 8402220331 Proposes alternative plan for DES prehearing conference in Mar 1984 ASLB assessment on 840307 of length of structural analysis hearings recommended BUSH, M w Philadelphia, PA 84/02/16 BRENNER, L Atomic Safety and Licensing Board Panel ip 22336 201 24% Fiche 50-352,84/02/16,8402220351
- 8402220067 Memorandum & order confirming denial of Friends of the Earth B40213 motions to extend testimony schedule & strike applicant testimony BRENNER, L Atomic Safety and Licensing Board Panel B4/02/17 3pp 22338 323 24X Fiche 50-352,84/02/17,8402220067
- 8402220113 Motion to reopen partial initial decision proceeding & address supplemental cooling water needs Issues should be discussed at hearing to be held after completion of appropriate DES Certificate of Svc encl
 SUGARMAN, R J Del-Aware Unlimited, Inc SUGARMAN, R J Sugarman & Denworth 84/02/17 Atomic Sefety and Licensing Board Panel
 22pp 22326 060 24X Fiche 30-352,84/02/17,8402220113
- 8402220116 Forwards applicant responses to info requests of City of Philadelphia, PA, designated Discovery 26
 WETTERHAHN, M J Conner & Wetterhabh WETTERHAHN, M J Philadelphia Electric Co B4/02/17 BUSH, M W Philadelphia, PA 10
 22329 072 24X Fiche 50-332,84/02/17,8402220116
- ~-B402220118 Responses to info requests of City of Philadelphia.PA. 02220118 Response. Discovery 26 BOVER.V S Philadelphia Electric Co 84/02/16 Com 25pp 22329 073 24% Fiche 50-352.84/02/17.8402220116 Commissioners
- --B402220122 Witness responsibility breakdown for Contentions V-30 & V-36 for 840305 hearing re ability of safety-related structures to withstand effects of postulated detonation resulting from assumed ruptures of pipelines Certificate of Svc encl METTERHAHN.M J Philadelphia Electric Co METTERHAHN.M J Conner & Wetterhahn 84/02/16 3pp R2327 099 24X Fiche, 30-332,84/02/17,8408280116
- 8402220233 Response opposing Air & Water Pollution Patrol 840128 motions for extension of discovery time based on new info Certificate of Svc encl Related correspondence HODODON, A P Hearing Branch 2 84/02/17 Atomic Safety and Licensing Board Panel App 22340 217 24% Fiche 30-352,84/02/17,8402220233
- B402220251 Memorandum re dates established in 840216 conference call to resolve conflicts revealed in applicant 840214 rept re schadules for litigating Contentions 1-41, I-42 & ansite emergency planning contentions W/Certificate of Svc HODODON, A P Hearing Branch 2 84/02/17 Atomic Safety and Licensing Board Panel Spp 22337 040 24% Fiche 50-352,84/02/17,8402220251
- 8402230033 Order modifying staff 840217 memorandum re dates established in 840214 conference call for Contentions I-41 & I-42 Courtesy notification encl BRENNER, L. Atomic Safety and Licensing Board Panel 84/02/21 Office of the Executive Legal Director 3pp 22341 275 24X Ficha 50-352.84/02/21.8402230033
- B402230036 Order suspending answers to Del-Awars 840217 motion to reopen partial initial decision proceeding Courtesy notification encl
 BRENNER, L Atomic Sefety and Licensing Board Panel 84/02/21
 Office of the Executive Legal Director 4pp 22362 063 24x
 Fichs 50-352,84/02/21,8402230036
- 8402270003 Forwards 840124 amended application to store fuel on site Certificate of Svc encl Related correspondence VOGLER.8 H Hearing Branch 2 84/02/21 BRENNER, L, MORRIS, P.A., CDLE, F. Atomic Bafety and Licensing Board Panel 115pp 22389:114 24% Fiche 50-352.84/02/21.8402270003
- 8402270068 Forwards 840207 proposed rule, "Analysis of Potential Pressurized Thermal Shock Events " Related correspondence WRIGHT:N A Hearing Branch 2, 84/02/21. DRENNER.L., MCRRIS.P.A., COLE.F Atomic 88fety and Licensing Board Fanel 11pp 22387 331 24X Fiche 50-352,84/02/21.8402270068
- B402280393 Motion for extension of discovery period re Contention VI-1 Records needed on logs & welds involved w/broomstick issue Related correspondence 1840 Related correspondence ROMANO,F R. Air and Water Pollution Patrol 84/02/21 BREN MORRIE,F; CDLE,R Atomic Safety and Licensing Board Panel 22402 248 24X Fiche 50-352.84/02/21,8402280393 BRENNER, L ,
- 8402240077 Requests that TR Campball, director of dept of emergency syes, be added to sye list.Related correspondence VUGLER, D H Hearling Branch 2 84/02/22 BRENNER, L MORRIB, P A , COLE, R F Atomic Bafety and Licensing Board Panel 2pp 22374 148 24X Fichs 50-352,84/02/22,8402240077.

- 8402270082 Forwards documents used by ND Romney as ref math in testimony re margins of structural capability of Category I structure to resist blast overpressure & mode of couling towers structure failure H/o entls Related correspondence VOQLER, B H Hearing Branch 2 84/02/22 ANTHONY, R L Friends of the Earth 2pp 22391 265 24X Fiche 50-392,84/02/22,8402270082
- B402280476 Forwards answers to City of Philadelphia interrogatories (Discovery 27) Confirms B40213 telcon re interrogatories & limitation and Contention I-42 Related correspondence WETYERHAIN, M J Conner & Wetterhahn B4702/22 BUSH, H U Philadelphia, PA 2pp 22402 289 24% Fiche 50-352,84/02/22, B402280476
- --B402280479 Answers to City of Philadelphia interrogatories (Discoverg 27) Certificate of Svc encl * Philadelphia Electric Co 84/02/21 Philadelphia. PA 22pp 22402 R91 24X Fiche 50-352.84/02/22.8402280476
- B4022B0328 Response opposing Limerick Ecology Action (LEA) contentions & City of Philadelphia issues re Suppl 1 to DES Certificate of Svc encl Related correspondence METTERHAHN, M J. Philadelphia Electric Co METTERHAHN, M J. Conner & Hetterhahn 84/02/23 Atomic Safety and Licensing Board Panel 34pp 22398 243 24X Fiche 50-352,84/02/23,8402280328
- 8402280335 Confirms arrangements for HMM Assoc to perform evacuation time study Skydy expected to be completed by 840331 Rejeted correspondence.

 CONNER, T B. Conner & Metterhahn CONNER, T B Philadelphia Electric Co. 84/02/24 HIPPERT, R J Pennsylvania, Commonwealth of, 1p 22399 085 24X Fiche. 50-352, 84/02/24, 8402280335
- B402280463 Informs of recently discovered error on June 1983 evacuation plan map for Berks, Chester & Montgomery Counties Correct scale on map should read 1 mile equals .588 inches. Map will be regulatished & changes made Related Correspondence BELSCR, A. L. Pennsylvania, Commonwealth of . 84/02/24 BRENNER, L. MORRIS, P. A. COLE, R. F. Atomic Safety and Licensing Board Panel Spp. 22403 001 24X Fichs 50-352,84/02/24.8402280463
- 8402270003 Response to Limerick Ecology Action 840131 offsite emergency planning contentions Certificate of Svc encl.
 VDQLER.B H. WRIGHT.N A. Rearing Branch 2 84/02/24 Atomic Safety and Licensing Board Panel 35pp 22428.107 24X
 Fiche 50-352,84/02/24,8402270003
- 8402270104 Response to City of Philadelphia interrogatories un Contention I-42 re environ qualification of electrical squipment & 840120 memorandum & order establishing 840204 as last day of filing M/Certificate of Svc. HODDDON:A P. Hearing Brench 2 84/02/24, Philadelphia: PA 26pp. 22426 053, 24x Fiche 50-352,84/02/24,8402290104
- 8402290071 Order scheduling answers to Friends of the Earth 840223 contentions based on 100FR70 application to store fuel master BRENNER: L. Atomic Rafety and Licensing Board Penel 84/02/27 Office of the Executive Logal Director Spp 22480 030, 24X Fiche. 50-303. 84/02/27.8402290071.
- 8402270076 Forwards 840223 memo relating results of Region I insp re application to store fuel on site to ASLB & parties VOGLER, B H Hearing Branch 2 84/02/27 BRENNER, L COLE, R F , MORRIS P A Atomic Safety and Licensing Board Penel 3pp 22428:104 24X Fiche: 50-352,84/02/27,84022970076
 - 12270070 Memorandum & order denying 840124 mution for extension of liscovery time & appointment of private detective on lontantion VI-1 re welfing improprieties Courtesy otipication and RENNER.L. Atomic Safety and Licensing Board Panel 84/02/28, ir and Water Pollution Patrol 7pp 22428,023 24X che. 50-352.84/02/28,8402270090.
 - Itility Final Bafety Analysis Report (FBAR) & amends
 - ORO277 Forwards Rev 28 to FSAR ADLEY, E J Philadelphia Electric Co. 84/01/31 DENTON, H H Fice of Nuclear Reactor Regulation, Director Opp. 22053.255 X Fichs 50~352.84/01/31.8402020277
 - 02020299 Rev 28 to F8AR
 * Philadelphia Electric Co. 84/01/31 319pp 22053,340 24X
 Fithe 50-252,84/01/31,8402020277
 - 116 Forwards Certificate of Svc re distribution of Rev 28 to
 - Y.E.J. Philadelphia Electric Co. 84/02/23 DENTON.H.R e of Nuclear Reactor Regulation: Director 3pp. 22390, 251 Fighe: 50-352, 84/02/23, 84/02/20316

- O Inspection reports. IE Bulletins & correspondence
- 8402020322 Forwards IE Mgt Meeting Rept 50-352/83-22 on 831206 re status of radiological protection program & radwaste sys & Region I Radiation Protection Branch preoperational & startup activities MARTIN.T T Division of Engineering & Technical Programs 84/01/17 KEMPER.J S Philadelphia Electric Co 2pp 22055 174 24X Fiche 50-352,84/01/17,8402020322
- ---B402020334 IE Mgt Meeting Rept 50-352/83-22 on 831206 Major areas discussed preoperational radiation protection program & raduate sys re NRC insp programs MILLER.M T. KUTTAN, J. Region 1, Office of Director 84/01/09 4pp 22055 176 24X Fiche 50-352/84/01/17,8402020322
- 8312120153 IE Info Notice 84-06. "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York Inc 120pp 22058 001 24X Fiche 50-000.84/01/25.8312120153
- 8402100332 Natification of Significant Licensee Meeting 84-12 on 840224 in Limerick PA to review SALP CONNER: E Region i, Office of Director 84/02/01 Region i, Gffice of Director 1p 22207 360 24% Fiche 50-352, 84/02/01, escalor323
- 8402160392 Forwards IE Insp Rept 80-352/83-20 on 831114-18 No violations noted MARTIN.T T Division of Engineering & Technical Programs 84/02/01 KEMFER.J. S Philadelphia Electric Co 2pp 22269 061 24X Fiche 90-352,84/02/01,8402160392
- --B402160377 1E Insp Rept 50-352/B3-20 on 831114-18 No violations noted Major areas inspected review of activities re installation of instrumentation equipment, mechanical equipment, IE bulletins, info notices & previously identified items.

 FINKEL: A E , GREGG: H I . ANDERSON. C J Region 1. Office of Director B3/12/19 8pp 22269.063 24X Fiche 50-352,84/02/01,8402160392
- B401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls." Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 8301031, 84/02/03 Consolidated Edison Co of New York, Inc. 119pp 22114,179 24X Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Hunders" Svc list encl DEVOUNG.R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co. of New York, Inc. 102pp 22177 154 24X Fiche 50-000,84/02/03,8401190017
- 840:190041 IE Info Natice 84-09, "Lessons Learned From NRC Insps of Fire Protection 8afe Shutdown Bys (100FR50, App R) " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259 24X Fiche; 50-000, 84/02/13, 8401190041.
- 8401190039 IE Info Natice 84-08, "10CFR50 7, 'Employee Protection '"

 Bvc list encl

 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co. of New
 York, Inc., 115pp 22365 141 24X Fiche, 50-000, 84/02/14, 8401190039
- B402290237 Forwards IE Insp Rept 50-352/84-04 on 840110-16 & 19-20 No violations noted MARTIN.T T Division of Engineering & Technical Programs 84/02/14 KEMPER.J S Philadelphia Electric Co 4pp. 22427 326 24X Fiche 50-352,84/02/14,8402290239
- ---8402270247 IE Insp Rept 50-352/84-04 on 840110-16 & 17-20. No violations noted Major areas inspected followup of previous insp finding, presperational test procedure review & verification & preoperational test witnessing BRIOGS.L. BETTENHAUSEN.L. Region i. Office of Director. 84/02/10 4pp 22427.330 24X Fiche 50-352.84/02/14.8402290239.
- 8401190045 IE Info Natice 83-63. Suppl 1, "Potential Failures of Westinghouse Type 5A-1 Differential Relays" Evolist encl. JUNDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 64/02/15 Consolidated Edison Co of New York, Inc. 118pp 22366.142 24X Fiche 50-000,84/02/15,8401190045

- 8402210145 Forwards FSAR page changes modifying response to Matls Engineering Branch request for addl info re details of preservice insp program, per 840203 telcon & SER Confirmatory Item 12 Info will be incorporated in next FSAR BRADLEY, E. J. Philadelphia Electric Co. 84/02/15 SCHNENCER, A. Licensing Branch 2 4pp 22317 155 24X Fiche 50-352,84/02/15,8402210145
- 8402220346 Ack receipt of 840203 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-352/83-17
 MARTIN, T T. Division of Engineering & Technical Programs 84/02/15
 KEMPGR, J B Philadelphia Electric Co 2pp 22334 176 24X
 Fiche: 50-352,84/02/15,8402220346
- --8402220348 Responds to NRC 840105 ltr re violations noted in IE Insp Rept 50-352/83-17 Corrective actions resident engineering means will no longer be used for Class 1 & non-Class 1 design interface KEMPER, J S Philadelphia Electric Co 84/02/03 MURLEY, T E Region 1, Office of Director 3pp. 22334 178 24X Fiche: 50-352,84/02/15,8402220346
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Bet Below Manufacturer Recommended Value " Svc list encl. JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/21 Consolidated Edison Co of New York, Inc. 116pp 28366,024. 24X Fiche 50-000.84/02/21.8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies" Bw: list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/24 Consolidated Edison Co of New York, Inc. 115pp 22430 304 24X Fiche 50-000.84/02/24,8401190066.
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals" Eve list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/02/27 Consolidated Edison Co of New York, Inc. 120pp 22431 060 24X Fiche, 50-000,84/02/27,8401190067
- R Periodic operating reports & related correspondence
- B402020237 Responds to NRC 810Bil request re quarterly updates of const completion date Echedule for implementing Suppl 1 to NUREG-0737 will permit fuel loading by 840B01 KEMPER, J S Philadelphia Electric Co. B3/12/27 EIBENHUT, D Q Division of Licensing 2pp. 22057.021 24X Fiche: 30-332,83/12/27,8402020239.
- B Reportable occurrences. LERs & related correspondence
- 8402020358 Final Bignificant Deficiency Rept BDR 126 re feadwater/ sefeguard fill sys check valves installed backwards Initially reported on 831219. Revensed check valves cut out, arismbed correctly & reinstalled REMPER J. B Philadelphia Electric Co 84/01/19 MURLEY, T E Region 1. Office of Directon. 3pp. 22052; 222. 24X Fiche 50-352,84/01/19,8402020358
- 8402070389 Discusses potentially generic issue re Comsip. Inc gas analyter catalyst bad qualification life Vendor recommends replacement of std configuration catalyst bads Region I awaiting IE & AEOD reply 81AR0STECKI.R. Division of Project & Resident Programs. 84/01/30 JCRPAN.E.L Director's Office, Office of Inspection and Enforcement 5pp. 22075:107. 24X Fiche: 50-000, 84/01/30, 8402070389.
- 8402270401 Final Bignificant Deficiency Rept 74 re contact alignment & spring compression in Westinghouse Type W 125/250-volt dc sotor control ctr auxiliary contacts. Initially reported on B31115 Auxiliary contacts adjusted.

 KEMPER. J B Philadelphia Electric Co. 84/02/02 MURLEY, T E Region 1, Office of Director 3pp 22390 358. 24X Fich: 50-352,84/02/02,8402270401
- T Hearing transcripts on non-antitrust matters
- 8402070242 Transmittal of util testimony re ability of safety-related structures to withstand effects of postulated detonation resulting from ruptures of ARCO & Columbia Gas transmission pipelines & request to set schedule HETTERHAHN, M.J. Philadelphia Electric Co. WETTERHAHN, M.J. Conner & Wetterhahn, 84/02/03, 2pp 22101:254 24X Fiche:50-352,84/02/03,8402070242.

- B402220296 Forwards staff testimony for 840306-07 hearing Testimony sent to affected parties on 840216 Related correspondence VGOLER, B H. Hearing Branch 2 84/02/17 BRENNER, L. COLE, R F. MGRRIS, P A Atomic Safety and Licensing Board Panel 2pp 22334 243 24% Fiche 50-352,84/02/17.8402220276
- --8402220300 Testimony of CM Farrell on blast overpressures at facility Related correspondence FERRELL.C M Site Analysis Branch 84/02/17 20pp 22334 245 24X Fiche 50-352,84/02/17.8402220296
- --8402220306 Testimony of WT LeFave re flooding effects on safety-related equipment from cooling tower collapse at facility Prof qualifications encl Related correspondence LAFAVE, WT Auxiliary Bystems Branch 84/02/14 5pp 22334 265 24X Fiche 50-352.84/02/17.8402220296
- --8402220307 Testimony of PT Kuo & ND Romney re margins of structural capability of Category 1 structure to resist blast overpressure & mode of structural failure to cooling towers Prof qualifications encl Related correspondence KUO.P T. ROMNEY.N D Structural & Geotechnical Engineering Branch 84/02/12 19pp 22334 270 24X Fiche 50-352,84/02/17,8402220296
- --B402220313 Testimony of RQ Wescott re hydrologic effects of cooling towar collapse at facility Prof qualifications encl Related correspondence
 WESCOTT,R 9 Division of Engineering 84/02/17 5pp 22334 289 24X Fiche 50-352
- U Congressional/Executive Correspondence
- 8402240277 Responds to FDIA request for three categories of documents re facilities Forwards App A Documents 1-4 Documents 8-9 provided previously via svc list FELTON, J M Division of Rules and Records. 84/01/27 SUGARMAN, R J Bugarman & Denworth 2pp 22374 278 24X Fiche. 50-000, 84/01/27, 8402240277
- --8308090022 Forwards second quarterly status rept for 1983 on actions taken he operating reactors & licensing reviews of new facilities
 ABBELSTINE J K Commissioners 83/07/21 BEVILL, T. House of Rep , Appropriations lipp 22394 300 24% Fiche 50-000. 84/01/27,8402240277
- DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- B402160003 Third partial response to FOIA request for infd re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILK, B J. Defice of the Secretary of the Commission B3/12/14 Public Document Branch ip. 22281.023 24X Fiche 50-000,83/12/14,84013-40003
- --8402160316 Discusses SECY-83-36 re director's denial of 10CFR2 206 petition on CPs Petition on CPs Petition on CPs Petition of CPs Petition of the Secretary of the Commission 83/02/28 PLAINE, H H Office of the General Counsel 1p 22281 268 24X Fiche 50-000,83/12/14,8402160003
- 8402240275 FDIA request for three categories of documents re facilities. 8UQARMAN.R J Bugarman & Denworth. 83/12/20. Division of Rules and Records. 2pp. 22394.296. 24X Fiche; 50-352,83/12/20,8402240275
- 8312120136 Board Notification 84-011 discusses NRC use of terms "important to safety" & "safety-related" EISENHUT, D © Division of Licensing 84/01/18 FALLADING Commissioners 72pp 22241;008 24X Fiche 50-000,84/01/18,8312120136.
- 8402020452 Notification of 840126 meeting w/util in 8an Franciso, CA to review capability of plant structures to withstand overpressures from external accidents involving explosions MARTIN, R E Licensing Branch 2. 84/01/20. SCHMENCER: A Licensing Branch 2 4pp. 22062.171. 24X Ficher 50-352,84/01/20,8402020452
- 840130032B Forwards K Bhiu 840106 memo re single failures in facility PRA. Memo satisfies contractual obligations for Task i of Project 4 in FIN A-3393 Related info encl PAPAZOGLOU, I A Brookheven National Laboratory FIN A-3393 84/01/23 CHELLIAH, E. Reliability & Risk Assessment Branch, Spp 22221:255 24X Fiche: 50-352, 84/01/23,8401300328

- 8402070475 Addresses concerns stated by B Everett during 831018
 Ithited appearance before ASLB re release of liquid or
 gaseous effluents from plant & use of Schuqlkill River DE9
 & SER. Section il encl W/o encls
 BCHWENCER. A Licensing Branch 2 84/01/26 EVERETT, B Affiliation
 Not Assigned 4pp 22142 079 24X Fiche 50-352,84/01/24,
 8402070475
- 8402070481 Addresses concerns stated by W Andrews during 831018
 Ilmited appearance before ASLD re potential hasard to
 Phoenixville potable water supply, evacuation plan k handling
 waste matls SER & DES encl W/o encls
 SCHWENCER A Licensing Branch 2 84/01/27 ANDREWS, W Affiliation
 Not Assigned 4pp 22142 072 24X Fiche 50-352,84/01/27,
 8402070481
- 0402240277 Responds to FOIA request for three categories of documents re facilities Forwards App A Documents 1-4 Documents 5-9 provided previously via svc list FELTON. JM Division of Rules and Records 84/01/27 SUGARMAN.R J Sugarman & Donworth 2pp 22394 298 24X Fiche 50-000.84/01/27. 8402240277
- ---B402240295 Bection 5 O. "Startup Addenda," to monthly project status rept 4 Philadelphia Electric Co • Bechtel Corp 83/12/01 79pp 22394 396 24% Fiche 50-000,84/01/27,8402240277
- 8402020277 Forwards Amené 61 to OL application. Rev 7 to design assessment rept available in PDR (Category A). Rev 8 to emergency plan (Category F) & Rev 28 to F6AR (Category K) BRADLEY.E J Philadelphia Electric Co 84/01/31 DENTON. H R Office of Nuclear Reactor Regulation. Director 3pp 22053. 252 24x Fiche 50-352.84/01/31.8402020277
- --8402020288 Amend &1 to GL application re changes to FSAR, reflecting accurately facility design. Rev 8 to emergency plan & Rev 7 to design assessment rept BOYER, V S Philadelphia Electric Co 84/01/31 App 22053 254 24X Fiche 50-352, 84/01/31, 8402020277
- --8402020273 Rev 7 page changes to design assessment rept * Philadelphia Electric Co 84/01/31 53pp 22053 260 24X Ficha 50-352,84/01/31,8402020277
- 8402130128 Notification of 840222 & 24 meetings w/util in Linfield, PA to discuss status of const & completion schedules for facilities Agenda enci NARTIN, R E Licensing Branch 2 84/02/03 SCHWENCER, A Licensing Branch 2 8pp 22237 137 24X Fiche 50-352, 84/02/03, 8402130128
- 8402180430 Forwards "Control of Heavy Loads at Nuclear Power Plants, timorick Generating Station Units 1 & 2 (Phase II)," draft technical evaluation rept Response to remaining concerns identified in Sections 2 3 1 C, 2 3 2 C & 2 3 3 C requested SCHMENGER, A Licensing Symant 2 FIN A-6457 84/02/06 BAUER, E 9 Philadelphia Electric Co 3pp 22263 276 24X Fiche 50-352,84/02/06,8402150430
- --8402130435 "Control of Heavy Loads at Nuclear Power Plants, Limerick Generating Station Units I & 2 (Phase II)," draft technical evaluation rept FRIEDERICHS, 8, STICKLEY, TH EQ&G, Inc FIN A-6457 83/10/30 NRC - No Detailed Affiliation Given 29pp 22253 279 24X Fiche, 50-352, 84/02/06, 8402150430
- 0408210001 Summary of 840124 meeting Woutil & Bechtel in San Francisco. CA re blast overpressure effects on strutures MARTIN.R E Licensing Branch 2 84/02/08 Licensing Branch 2 34pp 22322 328 24% Fiche 50-352.84/02/08,8402210001
- 840119089 Board Notification 84-032 provides add1 info on environ qualification Submittal augments info in Board Notifications 84-004 & 84-007 ETBENHUT. D. Q Division of Licensing 84/02/13 Atomic Safety and Licensing Board Panel 10pp 82314 204 24% Fiche 50-000,84/02/13,86019 80098
- 8402170117 Forwards draft FSAR changes modifying Section 14 2 re instrument mir cleanliness & responses to request for additinfo re Guestions 400 73 & 410 74 Info will be incorporated in FSAR rev scheduled for Feb 1984 BRADLEY.E J Philadelphia Electric Co 84/02/15 ScHMENGER, A Licensing Branch 2. 7pp. 22300 002 24% Fiche 50-352,84/02/15, 8402170117
- 10119006B Board Notification 84-033 provides "Sys Interaction Program." task action plan for Unresolved Bafety Issue A-17 Distribution list enci EIBERHUT. O Division of Licensing 84/02/16 PALLADING Commissioners. Spp 22482 071 24X Fiche: 50-000,84/02/16,840119006B

- 8402230084 Forwards additinfo requested per 840206 telcon in effort to enhance review of facility equipment qualification rept App B & E will be incorporated in rev scheduled for Apr 1984 M/o encl
 KEMPER. J B Philadelphia Electric Co 84/02/16 BCHWENCER, A Licensing Branch 2 3pp 22361 285 24X Fiche 50-352,84/02/16, 8402230084
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8402060080 Forwards responses to DDI 830826 water-related comments on DES Clarification on listed water resource issues requested HANSLER, 6 M Delaware River Basin Commission 84/01/21 Division of Licensing 53pp 22089 138 24X Fiche 50-352,84/01/21,8402060080
- 8402010143 Offers no comments on DES DAY18.V W Agriculture, Dept of 84/01/27. SCHWENCER, A. Licensing Branch 2 ip 22038 216 24% Fiche 50-352,84/01/27, 8402010143
- 8402070340 Forwards technical comments based on review of Suppl 1 to DES NRC should consider risks associated w/range of events expected to occur offsite Documents rated as ER-2 BRUBAKER, H P Environmental Protection Agency 84/02/03. MARTIN, R E Defice of Nuclear Reactor Regulation, Director 5pp 2209A 327 24X Fiche 50-352,84/02/03.8402070340
- 84020B0022 Forwards comments & concerns re Suppl 1 to DE8 (NUREO-0974) re operation of facilities
 BOYER V 8 Philadelphia Electric Co 84/02/06 EIBENHUT, D 0
 Division of Licensing 11pp 22128 079 24X Fithe 50-352,84/02/06,84020B0022
- 8402140150 Forwards State of PA Dept of Health comments on Suppl 1 to DES Cancer risks even in worst case situation, acceptable Questions safety during evacuation gONTZ.B J Pennsylvania. Commonwealth of 84/02/06, SCHHENCER, A Licensing Branch 2 2pp 22230,076 24X Fiche 50-352,84/02/06, B402140150
- 8402220477 Comments on Suppl 1 to DES for facilities Consequences of severe accidents on Schupkill River not clarified & adverse effects on fish & wildlife not considered BLANCHARD. B. Interior. Dept. of 84/02/0B Division of Licensing 2pp 22340 064 24X Fiche 50-352.84/02/08.8402220497.
- 8402290253 Forwards original typescript of revised comments dtd feb 1984 to be appended into FES Corrected version supersedes Jan 1984 version HANSLER.O M Delaware River Basin Commission 84/02/27 Division of Licensing 55pp 22427 250 24X Fiche 50-352,84/02/27, 8800200253
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 840224030B FDIA request for SSER & Tech Specs re facility.
 SUGARNAN, R J Bugarman & Denworth 84/01/25, NRC No Datailed Affiliation Given ip 22381-343 24X Fiche 50-352,84/01/25,
- 840E020300 Forwards FSAR page changes modifying response to NRC Request for Add1 Info 271 2 re Equipment Qualification Branch SER Open Item 6 FSAR changes will be incorporated in rev scheduled for Feb 1984 BRADLEY.E J Philadelphia Electric Co 84/01/30 SCHWENCER, A Licensing Branch 2 4pp 22055.184 24X Fiche 30-352,84/01/30, 8402020300
- 8402130609 Forwards request for add1 info re results of control sysfailure atudy in two repts entitled. "Control Sys Failure Evaluation Rept" & "Common Bensor Failure Evaluation Repts," to complete SER outstanding lessle.

 BCHMENCER, A Licensing Branch 2 84/02/01 BAUER, E 0 Philadelphia Electric Co. 7pp. 22214 297 24X

 Fiche: 50-392, 84/02/01, 8402130609
- 8402240315 Responds to FOIA request for SBER & Tech Specs re facility.
 Requested documents available in FDR
 FELTON, J M Division of Rules and Records, 84/02/07, 8UGARMAN.R.J.
 SUGARMAN & Denworth. 1p 22381 244 24X Fiche 50-352,84/02/07,
 8402240315
- B402170074 Summary of B40131 meeting w/util re status of fire protection amalyses & proposed mod to mitigate fires. Items 33-59 in SER (NUREG-0991) satisfactorily addressed KINTRER, L. Licensing Branch 1 84/02/08. Licensing Branch 1. 13pp 22318.168 24x Fichs 50-352.84/02/08.8402170074.

- 8402210145 Forwards FSAR page changes modifying response to Matls Engineering Branch request for addl info re details of preservice insp program.per 840203 telcon & SER Confirmatory Item 12 Info will be incorporated in next FSAR BRADLEY, E. J. Philadelphia Electric Co. 84/02/15 SCHWENCER. A. Licensing Branch 2 App. 22317 155 24X Fiche 30-352.84/02/15, 8402210145
- 8402270005 Informs that administrative & implementing procedures for fire protection plan will include listed controls.per Confirmatory Issue 37 of SER (NURES-0971) Procedures will be issued prior to fuel load REMPER.J S Philadelphia Electric Co 84/02/21 SCHMENCER, A Licensing Branch 2 3pp 22391 284 24x Fiche 50-352.84/02/21, 8402270005
- 8402270166 Forwards draft FBAR changes to appear in Feb FBAR rev re SER (NMRG9-0991) Section 4 4 6, "Loose Parts Monitoring Sys."

 Table 4 i Addl info requested in Table 4 1 should satisfy SER Confirmatory Issue 11, KEMPER.J.B. Philadelphia Electric Co 84/02/21 SCHWENCER, A Licensing Branch 2. 21pp 22386 043 24X Fiche 50-352,84/02/21,8402270166
- F. Becurity, medical, emergency & fire protection plans
- 8402010332 Notification of 840131 meeting w/util in Bethesda, MD to discuss fire protection measures KINTNER, L L. Licensing Branch 1. 84/01/16 SCHWENCER, A Licensing Branch 2 4pp 22059 305 24X Fiche 50-352,84/01/16,8402010332
- 8402010244 Forwards FEMA 840130 ltr to ASLB & FEMA 840111 memo providing responses to offsite emergency planning questions raised at 831017-18 limited appearance sessions in Phoenixville, PA VOQLER, B. H. Haaring Branch 2 84/01/30 BRENNER, L. Atomic Safety and Licensing Board Fanel 5pp 22040-187 24X Fiche: 50-352, 84/01/30, 8402010244
- B402020277 Forwards Rev B to emergency plan BRADLEY, E. J. Philadelphia Electric Co B4/01/31 DENTON, H R D#ffice of Nuclear Reactor Regulation, Director 3pp 22053, 252 24X Fiche: 30-352, 84/01/31, 8402020277
- --8402020294 Rev 8 to emergency plan * Philadelphia Electric Co 84/01/31, 28pp 22053:312, 24X Fiche: 50-352, 84/01/31, 8402020277
- B402100029 Forwards proposed numerical designation for H40131 offsite emergency planning contentions, supplementary basis info for Contentions VIII-29 & VIII-42 & discussion of Catauba balancing test requirements, Certificate of Bvc encl IIIIER,P Limerick Ecology Action B4/02/05 BRENNER, L Atomic Bafety and Licensing Board Panel. 12pp. 22182,084 24X Fiche. 50-352,84/02/05,8402100029
- 8402170074 Buamary of 840131 meeting w/util re status of fire protection analyses & proposed mod to mitigate fires Itams 35-59 in SER (MUREO-0991) satisfactorily addressed KINTNER, L.L. Litensing Branch : 84/02/08, Licensing Branch : 10pp 22318:168 24X Fiche: 50-352,84/02/08,8402170074
- 8402170193 Forwards requests for add1 info re fire protection program Response by 840229 requested.

 8CHMENCER, A Licensing Branch 2 84/02/09 BAUER, E G. Philadelphia Electric Co. 5pp. 22313.268, 24X

 Fiche: 50-352, 84/02/09, 8402170193.
- 8402170401 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licenses, per 810707 Generic Ltr 81-27. M/o request entire plan will be placed in PDR.

 8CHMENCER, A Licensing Branch & 84/02/07 BAVER, E @
 Philadelphia Electric Co 3pp. 82313: 177. 24X
 Fiche: 50-352, 84/02/07, 8402170401.
- 8402270005 Informs that administrative & implementing procedures for fire protection plan will include listed controls per Confirmatory Issue 37 of BER (NUREO-0971). Procedures will be issued prior to fuel load.

 KEMPER.J. 8. Philadelphia Electric Co. 84/02/21 SCHWENCER, A Licensing Branch 2. 3pp 22391 284. 24X Fiche. 50-352, 84/02/21, 8402270005

G Adjudicatory correspondence

- 8402010208 Forwards documentation re status of investigations into applicant use of products mfg by Hayword Tyler Pump Co. Tube-Line Co & Rag Miller.Inc Documentation includes IE Bulletin 83-07
 HODGDON.A Hearing Branch 2 84/01/23 BRENNER.L., COLE.R F. HORRIS.P A Atomic Safety and Licensing Board Panel 100pp 22042 001 24X Fiche 30-352,89/01/23,8402010208
- B402030254 Forwards util responses to Air & Water Pollution Patrol sixth seventh & nighth sets of interrogatories re GA/welding contention Requested info available for perusal near util headquarters METTERHENIN M J Conner & Wetterhahn B4/01/27 RBMANO, F R RBMANO, F 10, 22069 280 24X Fiche 50-392,84/01/27,8402030254
- --BA0203D27D Answer to sixth set of interrogatories on GA/welding contention BOYER.V8 Philadelphia Electric Co 84/01/25 Air and Water Pollution Patrol 7pp 22049.281 24X Fithe 90-352.84/01/27, 8402030254
- --8402030275 Answer to seventh set of interrogatories re QA/wolding contention BOYER, V B Philadelphia Electric Co 84/01/25 Air and Water Pollution Patrol Spp 22047 286 24X Fighe 50-352,64/01/27, 8402030254
- --B402030277 Answer to seventh set of interrogatories re GA/welding contention Certificate of Svc encl
 BDYER.V B Philadelphia Electric Co 84/01/25 Air and Water
 Pollution Fatrol 19pp 22069 291. 24% Fiche 50-352.84/01/27,
 B402030254
- B402010205 Response to Del-Aware B40111 motion for admission of Contentions V-35 & V-36 Motion should be dismissed for lack of jurisdiction Jurisdiction lies W/ABLAB Certificate of Svc encl
 WILCOVE, M N Hearing Branch 2 B4/01/30 Atomic Bafety and Licensing Board Panel 10pp. 22040 305 24X Fiche 50-352,84/01/30.8402010205
- 8402010206 Filing of issues of concern to City of Philadelphia, per ASLI 840120 memorandum & order Util & state should be required to revise emergency plans Cartificate of Svc encl 8MCLEN, H Philadelphia, PA 84701/30 13pp 22042 114 24X Fiche 50-352,84/01/30.8402010206
- 8402010225 Response opposing M Lewis B31224 motions re Contention I-62 No significant new info presented No nexus between proposed scenarios & contended issues shown Certificate of 8vc encl. WRIGHT, NA Hearing Branch 2 84/01/30 Atomic Bafety and Licensing Board Panel 13pp 22040 192 24X Fiche 50-352,84/01/30,8402010225.
- 8402010235 Forwards A Schwencer response to ASLD 831028 request for supporting analysis per exemption from requirements of ODC 56 re containment isolation for hydrogen recombiner W/a encl VOGLER, B H Hearing Branch 2 84/01/30 DRENNER, L, COLE, R f. MORRIB, P. A. Atomic Bafety and Licensing Board Panel 2pp 22042 257 24X Fiche, 50-352, 84/01/30, 8402010235
- 8402010244 Forwards FEMA 840130 ltr to ASLE & FEMA 840111 memo providing responses to offsite emergency planning questions raised at 831017-18 limited appearance sessions in Phoenix ville-PA.

 VOQLER B ff Hearing Branch 2. 84/01/30 BRENNER, L , COLE, R F , MORRIE, P A Atomic Safety and Licensing Board Panel 5pp. 22040-187. 24X Fiche 50-352,84/01/30,8402010244
- B402020227 Statement of issues re offsite emergency planning Util must update evacuation time estimate study for station plume exposure pathway emergency planning rone Certificate of Svc enc!
 FERKIN, Z O Pennsylvania. Commonwealth of. 84/01/30 Atomic Bafaty and Licensing Board Panel 4pp 22057 042 24X
 Fiche: 50-352, 84/01/30, 8402020229
- 8402030197 Notice of withdrawal of appearance in proceeding Certificate of Syc and.

 LAVERTY, J H Philadelphia Electric Co LAVERTY, J H Conner & Hetterhahn 84/01/30 Spp 22067: 335. 24X Fiche: 50-352, 84/01/30, 8402030197.
- 84020R0217 Order re Air & Water Pollution Patrol (AMPP) 84012A motion for extension of time for discovery on Contention VI-1 Unilateral request for extension of discovery period does not operate to extend time AMPP response must be timely. BRENNER, L. Atomic Bafety and Licensing Board Panel 84/01/31 Air and Water Pollution Patrol 5pp 22054 319 24X Fiche 50-352,84/01/31,8402020217.

- B402060173 Forwards offsite emergency planning contentions per ASLB B30516,1122 & 840120 orders. ZITZER,P Limerick Ecology Action B4/01/31 BRENNER,L, COLE,R F. MORRIS,P A Atomic Safety and Licensing Board Panel 3pp 22088
- --8402060176 Offsite emergency planning contentions based on currently available draft radiological emergency response plan Certificate of Svc encl
 * Limprick Ecology Action 84/01/31 Atomic Safety and Literating Board Panel 64pp 22088 315 24X
 Fiche 50-352,84/01/31,8402060173
- 8402080188 Forwards responses to questions re emergency planning.per ASLB directive during 831017-18 prehearing conference FERKIN.Z Pennsylvania, Commonwealth of. 84/01/31 BRENNER.L. CGLE.R F. MORRIS.P A. Atomic Safety and Licensing Board Panel 1; 22129 184 24X Fichs 50-332.84/01/31.8402080188
- --B402080190 Responses to questions re offsite emergency planning Reception ctrs sole purpose is to serve as pass-through point Certificate of Svc encl FERUIN.Z Pennsylvania, Commonwealth of, 84/01/31 15pp 22129 185 24X Fiche: 50-352,84/01/31,8402080188
- 8402150420 Ack receipt of Del-Aware 2 205 petition requesting NRC reopen CP proceedings re facilities Circumstances surrounding Alleged const impacts do not require action at present time. Notice of publication encl DENTON, H R Office of Nuclear Reactor Regulation, Director 84/01/31 LDCMG, R T Sugarman & Denworth 7pp 22263:335 24X Fiche: 50-352,84/01/31,8402150420
- --B402150429 Notice of request for action under 10CFR2 204 seeking redpening of CP proceedings for facilities DENTON, H R. Diffice of Nuclear Reactor Regulation. Director 84/01/31 ip 22243 341 24x Fiche: 50-352, 84/01/31, 8402150420
- 8402060131 Forwards Pennsylvania Public Util Commission ruling on exceptions, assued on 840113 by Judge Krantel re Bradshaw Reservoir pumphouse RADER.R.M Conner & Wetterhahn RADER.R.M Philadelphia Electric Co 84/02/01 DRENNER.L Atomic Safety and Licensing Board Panel Bpp 22089 104 24X Fiche 50-352.84/02/01.8402060131
- 84020&0164 Forwards answers to applicant second set of interrogatories & request for production of documents on Contention VI-1 Certificate of Svc encl Related correspondence ROMANO,FR Air and Water Pollution Patrol 84/02/01 Atomic Bafety and Licensing Board Panel 1p. 22088 306 24X Fiche 50-352,84/02/01,8402060464
- --B402060168 Answer to applicant second set of interrogatories & request for production of documents on Contention VI-1. Related correspondence ROMANO,F.R. Air and Hater Pollution Patrol. B4/02/01 Philadelphia Electric Co. 5pp 22088, 307 24X Ficher 30-38, 84/02/01, 8402060164
- 8402070327 Forwards rev to City 840130 emergency planning filing Revs consist of alimination of 830915 date in caption correction of typographical error on Page 5 & rev of Bection III, Paragraph 2 on Page 9 BUSH.M.W Philadelphie, PA 84/02/01 BRENNER, L. Atomic Safety and Licensing Board Panel 1p 22096 260, 24X Fiche: 50-352,84/02/01,8402070327
 - 8402070331 Revised filing of issues of concern per ASLB 840120 memorandum & order confirming rulings made at hearing. Stated issues & concerns should be included in scope of instant proceeding Certificate of Svc encl.

 SMOLENH Philadelphia, PA 84/02/01 Atomic Safety and Licensing Board Panel 13pp. 22096 261 24X

 Fiche 50-352,84/02/01,8402070327
- 402060039 First set of interrogetories & request for production of documents re Limerick Ecology Action onsite emergency planning contentions. Certificate of Byc encl COMMER.T B. Philadelphia Electric Co COMMER.T B. Conner & Wetterhahn 64/02/02 Limerick Ecology Action. 21pp 22088 202 24X Fiche: 50-352.64/02/02.8402060059.
- 8402060219 Forwards applicant appeal to State of FA Public Util Commission from ruling of Judge Kranzel on exceptions filed by applicant.

 CONNER, T. 8 Conner & Wetterhahn CONNER, T. 8 Philadelphia Electric Co. 84/02/02, SRENNER, L. MORRIS: P.A., COLE, R.F. Atomic Safety and Licensing Board Fanel. 5pp. 22087:142, 24X Fiche: 50-352,84/02/02,8402060219

- 8402070242 Transmittal of util testimony re ability of safety-related structures to withstand effects of postulated detonation resulting from ruptures of ARCO & Columbia Gas transmission pipelines & request to set schedulo HETTERHARN M J Philadelphia Electric Co WETTERHARN M J Conner & Metterhahn B4/02/03 2pp 22101 254 24X Fiche 50-352.84/02/03, 8602070242
- 8402070282 First set of interrogatories & request for production of documents on Contention I-42 WETTERHAHN.M J Philadelphia Electric Co WETTERHAHN.M J Conner & , Wetterhahn 84/02/03 Philadelphia, PA 11pp 22095 026 24X , Fiche 50-352,84/02/03,8402070282
- --8402070287 Second set of interrogatories & request for production of documents on Contention I-42
 WETTERHAKN.M J Philadelphia Electric Co WETTERHAKN.M J Conner & Wetterhahn 84/02/03. Limerick Ecology Action 2pp 22075 037 24X Fiche 50-352,84/02/03,8402070282
- --8402070272 First set of interrogatories & request for production of documents on Contention I-41
 HETTERHANN,M J Philadelphia Electric Co WETTERHANN,M J Connex & Wetterhahn B4/02/03 Philadelphia, PA 9pp 22095 039
 24X Fiche 50-352,84/02/03,8402070282.
- --8402070307 First set of interrogatories & request for production of documents on Contention I-41 Certificate of 8vc encl METTERHAHN.N J. Philadelphia Electric Co. METTERHAHN.N J. Conner & Wetterhahn 84/02/03. Linerick Ecology Action 12pp. 22075 048 24X Fiche 50-352.84/02/03.8402070282
- 8402070284 Forwards response to Air & Water Pollution Patrol tenth, eleventh & twelPth set of interrogatories & requests for documents re Contention VI-1
 WETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J, Philadelphia
 Electric Co 84/02/03 RDMAND, F R Air and Water Pollution Patrol
 1p 22096:132 24X Fiche 50-332,84/02/03,8402070286
- --8402070312 Answers to tenth set of interrogatories on GA/welding contention (Discovery 25)
 BOYER, V 8 Philadelphia Electric Co 84/02/01 Air and Water Pollution Patrol 7pp 22096.133 24X Fiche 50-352,84/02/03,8402070886
- --8402070317 Answers to eleventh set of interrogetories on GA/welding contention (Discovery 23)

 * Philodelphia Electric Co 84/02/01 Air and Water Pollution Patrol 4pp. 22096;140 24X Fiche, 50-352,84/02/03,8402070286
- ---B402070322 Answers to twelfth set of interrogatories on GA/welding contention (Discovery 24) Certificate of Bvc encl.

 * Philadelphia Electric Co B4/02/01 Air and Water Pollution Patrol 22pp 22096 144 24X Ficher 50-352, 84/02/03.8402070286.
- 8402080137 Forwards Interropatories 14-30 Related correspondence BUSH.M W Philadelphia. PA 84/02/03. VOGLER.B.H. Hearing Branch 2 WETTERHAHN.M Conner & Wetterhahn. 1p. 22132.043. 24X Fiche 50-332.84/02/03.8402080139.
- --8402080145 Interrogatories 14-21 re environ qualification * Philadelphia, PA 64/02/03 Philadelphia Electric Co 3pp 22132 044 24X Fiche: 50-352,84/02/03,8402080139,
- --8402080146 Interrogatories 22-30 re environ qualification. + Philadelphia, PA 84/02/03. Office of the Executive Legal Birector. 2pp 22132 047. 24X Fiche 50-352,84/02/03,8402080139.
- B402100029 Forwards proposed numerical designation for 840131 offsite emergency planning contentions supplementary basis info for Contentions VIII-29 & VIII-42 & discussion of Catauba balancing test requirements. Certificate of Svc encl ZITZER, P Limerick Ecology Action 84/02/05 SRENNER, L, CGLE, R, F, MORRIS, P, A Atomic Bafety and Licensing Board Panel, 12pp 22182 084 24% Fiche. 50-352,84/02/05,8402100029
- 8402100140 Interrogatories & request for production of documents of City of Piladelphia to util re sys interaction W/Certificate of Byc. Related correspondence.
 BUBH. M W. Philadelphia, PA 84/02/06 Philadelphia Electric Co. 12pp. 22181.329. 24X Fiche 50-352.84/02/06.8402100140.
- 8402100178 Responds to applicant first set of interrogatories re Contention I-42 Certificate of Svc encl.Related correspondence ZTTIER:P. Limerick Ecology Action 84/02/06 Philadelphia Electric Co 9pp. 22182.172 24X Fiche 50-352,84/02/06,8402100178

- BA02140175 Forwards proposed prehearing schedule re environ qualification of equipment & sys interaction, for concurrence Related correspondence BUBH.M. M Philadelphia, PA B4/02/08 WETTERHAHN, M Conner & Hetterhahn 2pp 22230 206 24X Fiche 50-352.84/02/08.8402140175
- 8402150094 Answer opposing Air & Water Pollution Patrol 840126 motion for extension of discovery time & other relief based on new info. Motion devoid of any concrete support for relief requested Certificate of Svc encl
 WETTERHARN.M J Philadelphia Electric Co WETTERHARN.M J Conner Wetterhahn 84/02/09 Atomic Safety and Licensing Board Panel 7pp 20249 317 24X Fiche 50-352,84/02/09,8402150094
- 8402220317 Forwards motion for deposition of named individuals, new contention re asbestos contamination & motion to compel applicant to precisely answer interrogatories W/Certificate of Svc Related correspondence ROMANO, F.R. Air and Water Pollution Patrol 84/02/10 Atomic Bafety and Licensing Board Panel 1p 22334-236 24X Fiche: 50-352,84/02/10,8402220317
- --8402220320 Motion for deposition of named individuals in applicant 831205 answer to first set of interrogatories Means for completeness of record for same individuals re broomstick affair should be suggested ROMANO,F.R. Air and Water Pollution Patrol 84/02/11 Atomic Bafety and Licensing Board Panel ip 22334 237 24X Ficher 80-352,84/02/10,8402220317
- --8402220324 Motion to admit new contention re asbestos contamination ROMANO, F. R. Air and Water Pollution Patrol 84/02/15 Atomic Safety and Licensing Board Panel 1p 22334 238 24X Ficha 50-332,84/02/10,840220317
- --8402220327 Motion to compel answers to listed interrogatories ROMAND.F.R. Air and Water Pollution Patrol. 84/02/10. Philadelphia Electric Co 2pp. 22334 239 24X Fiche 50-352.84/02/10.8402220317
- B402160264 Answer to Limerick Ecology Action, City of Philadelphia & State of PA contentions re offsite emergency planning Certificate of Svc encl.
 CDNNER, T B. Philadelphia Electric Go CONNER, T B Conner & Metterhahn 84/02/13 Atomic Safety and Licensing Board Panel 72pp. 22274 138 24X Fiche 50-352, 84/02/13, 8402160264
- 8402220228 Forwards GJ Bradley 840124 cover ltr to util application to store fuel onsite. Application will be forwarded under separate cover.

 YOOLER, B H Hearing Branch 2 84/02/13 BRENNER, L., MORRIS, P.A., COLER, F. Atomic Safety and Licensing Board Panel 3pp 22340 149 24X Fiche. 50-352, 84/02/13, 8402220228
- 8402220250 Responds to 840202 ltr referencing 840127 telcon requestions on supplemental cooling water source Caseload forecast panel rept & Commission rept to Subcommittee on Energy & Hater Development encl HODPDON, A. P. Hearing Branch 2. 84/02/13. 8U0ARMAN, R J Bugarman & Denworth. 17pp. 22399:210 24X Fichs. 50-352.84/02/13.8402220250.
- 8402150209 Rept to ABLB re Contentions I-41, I-42 & onsite emergency planning, Limerick Ecology Action. City of Philadelphia. State of PA & NRC staff agree w/rept, w/exception of listed items Certificate of Bvc encl.
 CONNER, T. B. , METTERHARM, M. J. Philadelphia Electric Co. CONNER, T. B. CONNER, T. B. CONNER, T. B. CONNER, Wetterhahn B4/02/14, 10pp. 22276, 261 24X Fiche: 50-352.84/02/14, 8402160209.
- 8402160238 Transmittal of add1 matl re Contentions V-3a & V-3b concerning ability of safety-related structures to withstand effects of postulated detonation resulting from pipeline ruptures. Certificate of Svc encl.
 HETTERHARN, M. J. Philadelphia Electric Co. HETTERHARN, M. J. Conner & Hetterhahn, B4/02/14 Spp. 22274, 319, 24x Fiche. 50-352, 84/02/14, B402160238
- B402210277 Issues of concern w/Buppl 1 of DES. Impact statement acceptable Certificate of Syr encl BUSH M. M. Philadelphia, PA B4/02/14 20pp 22315-320. 24X Fiche: 50-382, 84/02/14, 8402210277.
- B402170074 Forwards SM Hurst 840207 limited appearance ltr.to be served on all parties.

 LANE.V.M. Atomic Safety and Licensing Board Panel. 84/02/15
 CLEMENTS.W L. Docketing & Bervices Branch 1p. 22299:360, 24X
 Fiche: 80-352,84/02/15,8402170094.

- ---8402170094 Advises that Upattines School not originator of draft evacuation plantas previously indicated Proper evacuation of area impossible HURBY, B.M. Affiliation Not Assigned 84/02/07 BRENNER, L. Atomic Safety and Licensing Board Panel 1p 22299 361 24X Fiche 50-352,84/02/15,8402170094
- B402220247 Forwards util 840206 application under 10CFR70 to amend license to store fuel ensite Related correspondence VOLGER, B H Hearing Branch 2. 84/02/15 BRENNER, L, MORRIS, F A, CDLE, R F Atomic Bafety and Licensing Board Panel 4pp 22339 164 24X Fiche 50-352.84/02/15.8402220247
- B40222008B Proposed findings of fact & conclusions of law in form of partial initial decision on Contention V-4 re carburetor icing Notice of appearances & Certificate of Svc encl HETTERHAHN.M.J., NICHOLS.N.N. Philadelphia Electric Co. HETTERHAHN.M.J. Conner & Wetterhahn 84/02/16 45pp 22326 118 247 Fichs 30-352.84/02/16.8402220088
- 8402220143 Contentions on environ assessment of severe accidents as discussed in DES. Suppl 1 DEB does not include consideration of whole range of accident scenarios necessary to produce cost-benefit analysis W/Certificate of Svc ELLIOT, C W Limerick Ecology Action 84/02/16 Atomic Sefety and Licensing Board Panel 16pp 22327 030 24X Fiche 50-352.84/02/16. B402220143
- 8402220221 Response to City of Philadelphia 840131 request for info re DEB, Suppl i Executed affidavit of S Acharya & Certificate of Svc encl Related Correspondence HODGDON, A P. Hearing Branch 2 84/02/16 Atomic Safety and Licensing Board Panel Spp 22340 139 24X Fiche 50-352,84/02/16, 8402220221
- 840222033 Proposes alternative plan for DES prehearing conference in Mar 1984 ASLB assessment on 840307 of length of structural analysis hearings recommended.
 BUSH, M W Philadelphia. PA 84/02/16 BRENNER, L Atomic Safety and Licensing Board Panel 1p. 22336 201 24X
 Fiche 50-332,84/02/16,8402220331
- 8402220067 Memorandum & order confirming denial of Friends of the Earth 840213 motions to extend testimony schedule & strike applicant testimony BRENNER: L Atomic Bafety and Licensing Board Panel 84/02/17 3pp 22338, 323 24X Fiche: 50-352, 84/02/17,8402220067
- 8402220113 Motion to reopen partial initial decision proceeding & address supplemental cooling water needs issues should be discussed at hearing to be held affer completion of appropriate DES Certificate of Svc encl.
 SUGARMAN: R.J. Del-Aware Unlimited, Inc. SUGARMAN, R.J. Sugarman & Denworth 84/02/17 Atomic Sefety and Licensing Roard Panel 22pp 22326:060 24X Fiche 50-352:84/02/17:8402220113
- B402220116 Forwards applicant responses to info requests of City of Philadelphia, PA, designated Discovery 26
 WETTERHAMNN J Conner & Wetterhahn WETTERHAMN, M J Philadelphia
 Electric Co 84/02/17 BUBH, M W Philadelphia, PA 1p
 22329 072 24X Fiche 50-352,84/02/17,8402220116
- --8402220118 Responses to info requests of City of Philadelphia, PA. Discovery 26 BOYER, V. 8 Philadelphia Electric Co. 84/02/16 Commissioners 25pp. 22329 073 24X Fiche, 50-352, 84/02/17, 8402220116.
- --8402220122 Witness responsibility breakdown for Contentions V-30 & V-36 for 840305 hearing re ability of safety-related structures to withstand affects of postulated detonation resulting from assumed ruptures of pipelines Certificate of Svc enci WETTERHAHN.M. J Philadelphia Electric Co WETTERHAHN.M. J Conner & Wetterhahn. 84/02/16 5pp 22329 099 24X Fiche: 50-352,84/02/17,8402220116.
- 8402220233 Response opposing Air & Water Pollution Patro) 840128 motions for extension of discovery time based on new info. Certificate of Syc encl Related correspondence HODGDON, A. P. Hearing Branch 2. 84/02/17 Atomic SePety and Licensing Board Panel. App. 22340 217. 24X Fiche. 50-352, 84/02/17. 8402220233
- 8402220251 Memorandum re dates established in 840216 conference call to resolve conflicts revealed in applicant 840214 rept re gchedules for litigating Contentions 1-41.1-42 & onsite emergency planning contentions. W/Certificate of Svc HODODON, A P Hearing Branch 2. 84/02/17. Atomic Bafety and Licensing Board Panel. 5pp. 22937.040 24X Fiche 50-352,84/02/17. 8402220251.

- 8402230033 Order modifying staff 840217 memorandum re dates established in 840216 conference call for Contentions I-41 & I-42 Courtesy motification encl
 BRENNER.L Atomic Safety and Licensing Board Panel 84/02/21 Office of the Executive Legal Director 3pp 22361 295 24X Fichs 50-352,84/02/21,8402230033
- 8402230036 Order suspending answers to Del-Aware 840217 motion to reopen partial initial decision proceeding Courtesy notification and
 - notification encl
 BRENNER.L Atomic Safety and Licensing Board Panel 84/
 Office of the Executive Legal Director 4pp 22362 063
 Fiche 50-352,84/02/21,8402230036 84/02/21
- 8402270003 Forwards 840124 amended application to store fuel on site Certificate of Syc encl Related correspondence VOGLER, B.H. Hearing Branch 2 84/02/21 BRENNER, L., MORRIB, P.A., CDLE, F. Atomic Safety and Licensing Board Panel 115pp 22389 114 24X Fiche.50-352,84/02/21,8402270003
- B40227006B Forwards 840207 proposed rule, "Analysis of Potential Pressurized Thermal Ehock Events " Related correspondence WRIGHTIN A Hearing Branch 2 84/02/21 BRENNER, L. MORRIS, F COLE, R Atomic Safety and Licensing Board Panel. 11pg 22387.331 24% Fiche 50-352,84/02/21,840227006B MORRIS, PA,
- 3402280393 Motion for extension of discovery period re Contention VI-1 Records negded on logs & welds involved w/broomstick issue Related correspondence.
 RBMAND.F R Air and Water Pollution Patrol B4/02/21 BRENNER.L , MORRIDS.P , COLE,R Atomic Safety and Licensing Board Panel 2pp 22402 268 24% Fiche 50-352,84/02/21,8402280373
- 3402246077 Requests that TR Campbell director of dept of emergency sycs, be added to syc list Related torrespondence VOOLER.B H Hearing Branch 2 84/02/22 BRENNER.L., MORRIB, P.A. COLE.R.F. Atomic Safety and Licensing Board Panel 29p 22374 1 24X Fiche 50-352.84/02/22.8402240077
- 3402270082 Forwards documents used by ND Romney as ref mati in testimony re margins of structure! capability of Category I structure to resist blast overpressure & mode of cooling towers structure failure W/o encls Related correspondence.

 VOOLER, B. H. Hearing Branch 2 84/02/22 ANTHONY, R L. Friends of the Earth 2pp 22391-245 24% Fiche 50-352,84/02/22,8402270082
- 3402280476 Forwards answers to City of Philadelphia interrogatories (Discovery 27), confirms 840213 telcon re interrogatories & limitation of Contention I-42, Related correspondence. WETTERHAHN, M. J. Conner & Wetterhahn 84/02/22 803H, M. W. Philadelphia, PA. 2pp 22402:289 24X Fichs 50-352,84/02/22,8402280476
- -8402280477 Answers to City of Philadelphia interrogatories (Discovery 27) Certificate of 8vc encl * Philadelphia Electric Co 84/02/21. Philadelphia, 22402.291 24% Fithe 50-352,84/02/22,8402280476 Philadelphia, PA 22pp
- 2280328 Response opposing Limerick Ecology Action (LEA) contentions City of Philadelphia issues re Suppl I to DES Certificate f Svc encl Related correspondence ETTERHANN'N J Philadelphia Electric Go METTERHANN'N J Conner steerhaln 84/02/23. Atomic Bafety and Licensing Board Panel 14pp. 22378 263 24X Fiche: 50-352. 84/02/23. 8402280328
-)2280315 Confirms arrangements for HMM Assoc to perform evacuation ,ime study Bindy expected to be completed by 840331 Related ,prrespondence :
 | ONNER'T B Conner & Hetterhahn CONNER'T B, Philadelphia Electric Co 84/02/24, HIPPERT'R J Pennsylvania, Commonwealth of, ip
- 24. HIPPERT.R J. Pennsylvania, Commonweelth of,. ip 24x Fiche 50-352.84/02/24,8402280335
- 402280463 Informs of recently discovered error on June 1983 evacuation plan map for Berks, Chester & Montgomery Counties Correct veals on map should read in mile equals 588 inches Map will error published & changes made, Relabed correspondence | ELSER, A L Pennsylvania, Commonwealth of, 84/02/24 BRENNER, L, | IDRRIS, P. A., COLE, R. F. Atomic Safety and Licensing Board Panel. | Ipp 22403 001 24X Fiche 50-352,84/02/24,8402280463.
 - 2290003 Response to Limerick Ecology Action 840131 offsite emergency lanning contentions Certificate of Svc encl.

 GGLER, B. H., MRIGHT, N. A., Hearing Branch 2 84/02/24 Atomic afety and Licensing Board Panel 35pp. 22428
 - 290104 Response to City of Philadelphia interrogatories on ntention I-42 re environ qualification of electrical uipment & 840120 memorandum & order establishing 840206 last day of filling W/Certificate of Byc GDDN, A.P. Hearing Branch 2 84/02/24 Philadelphia, PA p. 22426,053 24X fichs, 50-352,84/02/24,8402290104

- 8402270071 Order scheduling answers to Friends of the Earth 840223 contentions based on 100FR70 application to store fuel
 - Onsite
 BRENNER.L Atomic Safety and Licensing Board Panel 84/02/27
 Office of the Executive Legal Director 5pp 22428 030 24X
 Fiche 50-352.84/02/27.8402290071
- 8402290076 Forwards 840223 memo relating results of Region I insp re application to store fuel on site to ASLB & parties VOGLER.B H Hearing Branch 2 84/02/27 BRENNER.L. COLE.R F, MORRIS.P A Atomic Safety and Licensing Board Panel 3pp 2242B 104 24X Fiche 50-352.84/02/27.8402290076
- B402290090 Memorambum & order denying B40126 motion for extension of discovery time & appointment of private detective on Contention VI-1 re welding improprieties Courtesy
- Internation and Safety and Licensing Board Panel 84/02/28 Air and Water Pollution Patrol 7pp 22428 023 24X Fiche 50-332.84/02/28,8408290090
- K Utility Final Bafety Analysis Report (FBAR) & amends
- B402020277 Forwards Rev 28 to FSAR BRADLEY/E J Philadelphia Electric Co. B4/01/31 DE Office of Nuclear Reactor Regulation, Director Spp 24X Fiche 50-352,84/01/31.8402020277 DENTON, H.R.
- --8402020297 Rev 28 to FSAR # Philadelphia Electric Co 84/ Fiche 50-352,84/01/31,8402020277. 84/01/31 319pp 22053:340, 24X
- 8402270316 Forwards Certificate of Svc re distribution of Rev 28 to BRADLEY,E J Philadelphia Electric Co 84/02/23 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 22390;251 24X Fiche 50-332,84/02/23,84022/0316
- O Inspection reports, IE Bulletine & correspondence
- 8402010208 Forwards documentation re status of investigations into applicant use of products mfg by Hayward Tyler Pump Co. Tube-Line Co & Ray Miller, Inc. Documentation includes IE Bulletin 93-07 HODODON:A Hearing Branch 2 84/01/23 BRENNER,L., COLE,R,F., MORRIS,P.A Atomic Safety and Licensing Board Panel 100pp 22042.001 24X Fiche: 80-352,84/01/23,8402010208
- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feetwater Pumps " Byc list encl.
 JURDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103), 84/01/25 Consolidated Edison Co. of New
 York, Inc. 120pp 22058.001. 24X Fichs. 50-000, 84/01/25, 83;2120153 Pumps " Syl
- 8402100332 Notification of Significant Licensee Meeting 84-12 on 8402R4 in Limerick:PA to review SALF CONNER.E Region 1. Office of Director 84/02/01 Region 1. Office of Director 1p 22207-360 24X Fiche 50-352,84/02/01. 840210033R.
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Bvc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co. of New York, Inc 119pp. 22114:179 24X Fichs:50-000.84/02/03.8401190016
- 8401190017 IE Bullstin B4-Q1, "Gracks in BWR Mark I Containment Vent NOITY OUT? IE BUILTED BA-OF, "Gracks in SWR Hark I Containment vent Headers " Svc list encl. DEYOUNG,R C Director's Office. Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp. 22177.156 24X Fichs, 50-000,84/02/03.8401190017
- 8401190041 IE Info Notice 84-09, "Leasons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R)," Svc list Division of Emergency Preparadness & Engineering ost 830103) 84/02/13 Consolidated Edison Co of New 124pp. 22365:259 24X Fiche:50-000;84/02/13,8401190041 JORDAN, E.L. Division (Response (Post 830103) York, Inc
- 8401190039 IE Info Notice 84-08. "10CFR50 7, 'Employee Protection.'"

 Byc list encl

 JORDAN-E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) , 84/02/14 Consolidated Edison Co. of New
 York, Inc 115pp. 22365 141. 24X Fichs 50-000.84/02/14,8401190039
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Westinghouse Type 8A-1 Differential Relays." Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366, 142 24X Fichs 50-000, 84/02/15, 8401190045

- 8402210145 Forwards FSAR page changes modifying response to Matls Engineering Branch request for addl info re details of preservice insp program, per 840203 telcon & SER Confirmatory Item 12 Info will be incorporated in next FSAR BRADLEY, E. J Philadelphia Electric Co 84/02/15 SCHWENCER, A Licensing Branch 2 4pp 22317 155 24X Fiche 50-352,84/02/15,8402210145
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp. 22366 024 24X Fiche 50-000,84/02/21,8401190062
- B402280459 Ack receipt of B31011 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-353/76-06
 MARTIN.T T. Division of Engineering & Technical Programs 84/02/22
 KEMPER, J B. Philadelphia Electric Co 2pp 22403 004 24X
 Fiche: 50-353, 84/02/22, 8402280459
- --8402280444 Suppls response to NRC 76i110 ltr re violations noted in IE
 Insp Rept 50-353/76-06 Corrective actions welding records in
 areas other than structural steel reviewed
 KEMPER.J B Philadelphia Electric Co 83/10/11 MURLEY.T E
 Region i, Office of Director 2pp. 22403 006 24X
 Fiche 30-353,64/02/22,8402280459
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies"
 Swc list encl
 JURDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- 6401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
 Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Rasponse (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc. 120pp 22431 060 24X Fiche 50-000,84/02/27,8401190067
- 8 Reportable occurrences. LERs & related correspondence
- 840202035B Final Significant Deficiency Rept SDR 126 re feedwater/ safeguard fill sys check valves installed backwards Initially reported on B31219 Revensed check valves cut out, orisneed correctly & reinstalled, KEMPER, J B. Philadelphia Electric Co. 84/01/19, MURLEY, T E Region 1, Office of Director 3pp 22032, 222, 24X Fiche, 50-332, 84/01/19, 840202035B,
- 8402070389 Discusses potentially generic issue re Comsip, Inc gas analyzer catalyst bed qualification life Vendor recommends replacement of std configuration catalyst bads. Region I awaiting IE & AEOD reply BTAROBTECKIR Division of Project & Resident Programs B4/01/30, JORDAN, E.L. Director's Office, Office of Inspection and Enforcement Spp. 22095 107 24X Ficher 50-000, 84/01/30, 8402070389.
- 8402270401 Final Significant Deficiency Rept 94 re contact alignment & spring compression in Westinghouse Type W 125/250-volt dc motor control ctr auxiliary contacts Initially reported on G31115 Auxilary contacts adjusted KEMPER.J. S. Philadelphia Electric Co 84/02/02 MURLEY.T E Region i. Office of Director. Spp. 22370.358 24X Fiche 50-352,84/02/02,8402270401.
- T. Hearing transcripts on non-antitrust matters
- 8402070242 Transmittal of util testimony re ability of safety-related structures to withstand effects of postulated detonation resulting from ruptures of ARCD & Columbia Gas transmission pspalines & request to set schedule.
 WETTERHAIN.M J. Philadelphia Electric Co 84/02/03 2pp 22101:254. 24X Fiche 30-352,84/02/03,8402070242
- --8402070251 Testimony of HW Vollmer, D Marano, KP Buchert, AK Wong, JH Benkert, R Palaniswamy & QK Ashley re ability of safaty-related structures to withstand effects of postulated detonation. M/prof qualifications & Certificate of Bvc VOLLMER, H. W., MARAND, D., BUCHERT, K. P. Philadelphia Electric Co 84/02/03, 48pp 22101.256 24X Fiche. 50-352,84/02/03,8402070242.
- 8402220276 Forwards staff testimony for 840306-09 hearing Testimony sent to affected parties on 840216, Related correspondence VOOLER, B. M. Hearing Branch 2. 84/02/17 BRENNER, L., COLE, R. F., MORRIB, F. A. Atomic Safety and Licensing Board Panel Rpp 22334, 243. 24X Fiche: 50-352, 84/02/17, 8402220296
- --B402220300 Testimony of CM Farrell on blast overpressures at facility Related correspondence. FERRELL, C M. Bite Analysis Branch. 84/02/17 20pp. 22334,245 24% Fiche: 50-332,84/02/17,8402220296

- --8402220306 Testimony of MT LeFave re flooding effects on safety-related equipment from cooling tower collapse at facility Prof qualifications encl Related correspondence LAFAVE.WT Auxiliary Systems Branch 84/02/14 5pp 22334 265 24X Fiche 50-352,84/02/17.8402220296
- ~-8402220307 Testimony of PT Kuo & ND Romney re margins of structural capability of Category 1 structure to resist blast overpressure & mode of structural failure to cooling towers Prof qualifications encl Related correspondence KUO.P T . ROMNEY.N D Structural & Geotechnical Engineering Branch 84/02/12 19pp 22334 270 24X Fiche 30-352,84/02/17.8402220276
- --B402220013 Testimony of RQ Wescott re hydrologic effects of cooling tower collapse at facility Prof qualifications encl Related correspondence HESCOTT.R O Division of Engineering 84/02/17 5pp 22334 289 24X fiche 50-352.84/02/17.8402220296
- U Congressional/Executive Correspondence
- 8402240277 Responds to FDIA request for three categories of documents re facilities Forwards App A Documents 1-4 Documents 5-9 provided previously via svc list FELYON, J M Division of Rules and Records 84/01/27 SUGARMAN, R J Sugarman & Denworth 2pp 22374 278 24x Fiche 50-000, 84/01/27, 8402240277
- --8308090022 Forwards second quarterly status rept for 1983 on actions taken re operating reactors & licensing reviews of new facilities
 ABBELBTINE. J. K. Commissioners 83/07/21 BEVILL, T. House of Rep. Appropriations lipp 22374 300 24X Fiche 50-000, 84/01/27,8402240277
- DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B402070003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing stimates based on inclusion of Caselead Forecast Panel meetings Forwards App A, 8 & C documents
 FELTON, J M Division of Rulee and Records 83/10/31
 ROBENBAUM, D M Technical Analysis Corp 19pp 22193 292 24X
 Fiche 50-000,83/10/31.8402090003
- --8402090165 Handwritten notes & calculations re const activities * NRC - No Detailed Affiliation Given 83/04/05 Spp 22195 006 24X Fiche, 90-000, 83/10/31, 8402090003
- 8401230422 Forwards response to requests for add1 info contained in NRC 831121 & 1207 ltrs, general revs to FSAR & 711 oversize drawings Responses & revs will be incorporated into Amend 4 to FBAR Aperture cards are available in FDR MITTLER L. Public Service Electric & Gas Co of New Jersey 84701718 SCHWENCER, A Licensing Branch 2 1.897pp 21875 197 24X Fiche 50-354,84701718,8401230422
- 8402010157 Forwards one oversite site arrangement drawing corresponding to FBAR Figure 1 2-1. In response to NRC 831219 request Aperture card is available in FDR MITTL.R.L. Public Service Electric & Gas Co of New Jersey, 84/01/20 SCHMENCER, A Licensing Branch 2 ip 22040 361 24X Fiche 50-354,84/01/20,8402010159.
- B40209047B Notification of B40202 meeting w/util in Betheads, MD to discuss control room design review MAGNER, D H .i.censing Branch 2. B4/01/25 SCHWENGER, A Licensing Branch 2 3pp 22177 345 24X Fiche 50-354: 84/01/25, 8402090478
- 8402070326 Forwards responses to Category I target date items re structural/geotechnical review.per 840110-12 meeting agreements MITTL-R.L. Public Bervice Electric & Gas Co. of New Jersey 84/01/26 SCHWENCER.A. Licensing Branch 2 52pp 22096 274 24X Fiche-50-334.84/01/26.8402070326
- 8402230095 Forwards Vols 1-6 of plant-unique analysis rept.resolving applicable requirements of NUREG-0661. "SER Ro Mark I Containment Long-Term Program "
 MITTL:R t. Public Service Electric & Gas Co of New Jersey, B4/02/10, BCHMENCER:A Licensing Branch 2 ip 22347 101 24% Fiche 50-354.84/02/10,8402230095.
- --8402230101 Rev O to Vol 1 to plant-unique analysis rept. "General Criteria & Loads Methodology "
 LEHNERTIR A . EDMARDS, N. W. SANCHEZ, R A NUTECH Engineers, Inc BPC-01-300-1 VOl ROO 84/01/31. 202pp 22349 102 24X Fichs. 50-354,84/02/10,8402230095

- ~-8402230108 Rev O to Vol 2 to plant-unique analysis rept. "Suppression Chamber Analysis."
 - Onamber Analysis "
 QUINN,R D , EDWARDS,N W , YIN,Y C NUTEC
 BPC-01-300-2 V02 R00 84/01/31 150pp
 Fichs 50-354.64/02/10,8402230095 NUTECH Engineers, Inc
- --B402230113 Rev O to Vol 3 to plant-unique analysis rept, "Vent Sys Analysis" GUINN.R D , EDHARDS,N W , YIN,Y C NUTECH Engineers, Inc BPC-01-300-3 VO3 ROO B4/01/31 189pp 22350 094 24X Fiche 50-354,84/02/10,8402230095
- --8402230116 Rev O to Vol 4 to plant-unique analysis rept, "Internal Structures Analysis " QUINN.R D , EDWARDS,N W , YIN.Y C NUTECH Engineers. Inc BPC-01-300-4 Vo4 ROO B4/01/31 35pp 22350 283 24X Fiche 50-354,84/02/10,8402230095
- --8402230120 Rev 0 to Vol 5 to plant-unique analysis rept, "Safety Relief Valve Discharge Piping Analysis" BASKIN.J L., EDMARDS,N W., LCHNERT,R A. NUTECH Engineers, Inc BPC-01-200-5 VoS ROO 64/01/31 150pp 22350 318 24X F1che 50-354,84/02/10,8402230095
- --8402230126 Rev O to Vol 6 to plant-unique analysis rept. "Torus Attached Piping & Suppression Chamber Penetration Analysis " BASXIN.J L. EDMARDS,N W. MCNG.C T NUTECH Engineers. Inc BPC-01-300-6 Vols ROO 84/01/31 150pp 22351 108 24X Fiche 30-354,84/02/10,8402230095
- 840222033 Notifies of willingness to consent to applicant motion to dismiss Contention IV re environ impacts from operation of cooling tower Motion for protective under Forbidding deposition of Rodriguez will be filed W/Certificate of Svc PDITER.R W New Jersey, State of 84/02/16 MILLER,M E , MORRISE A Atomic Safety and Licensing Board Panel 3pp 22336 229 24% Fiche 50-354,84/02/16.8402220333
- 8402240269 Summary of B40110-13 meetings w/util·Bechtel & GE in San Francisco.CA re instrumentation & controls sys Supporting documentation encl tation enci D. Licensing Branch 2 84/02/17 Licensing Branch 2, 22392-197 24% Fiche 50-354,84/02/17,8402240269 WAGNER, D
- 8402280312 Forwards response to questions re structural/geotechnical topics, per 840110-12 meetings Two alternate methods for natabilishing soil damping values described MITTLIR L. Public Service Electric & Gas Co of New Jersey 84/02/17 86HEMCER.A. Literasing Branch 2 104pp 22398:118 24X Fiche: 50-354.84/02/17.8402280312
- B Utility Preliminary Safety Analysis Report, amends
- B402060376 Forwards amend to PSAR.consisting of GA program description update of Figure 16 1-2 MARTIN.T J Public Service Electric & Gas Co of New Jersey 83/10/21 MVRLEY.T E Region 1. Office of Director 1p 22086 304 24x Fiche 50-354.83/10/21.8402060376
- --B4020603B0 Updated PBAR Figure 16 1-2 re quality stds for ABME Builer & Pressure Vessel Code & reg guide compliance * Public Service Electric & Oas Co of New Jersey B3/10/21, Spp 22086 305 24X Fiche 50-354/83/10/21, B4020603/5
 - Utility Environmental Report (ER), amends & correspondence
- 02230002 Forwards list of ref documents being transmitted to DRM. to facilitate review of environ rept MITTL-R L Public Service Electric & Gas Co of New Jersey 84/02/14 SCHERDER: A Licensing Branch 2. 4pp 22341-297 24X Fiche 50-354,84/02/14.8402230002
-) NRC Draft/Final Environmental Statements, supple & correspondence
- 8402160615 Requests site tour on 840215 to assist in preparation of DEB Areas of interest include svc water intake Structure, Delaware River shoreline, barge ship, sedimentation goods, storm drainage sys & cooling touer

 8CHMENGER.A Licensing Branch 2. 84/02/03 MITTL,R L. Public Bervice Electric & Ges Co of New Jersey 2pp 22302 018 24X

 iche 50-354.84/02/03.8402160615
 - RC Bafety Evaluation Report (SER), supply & correspondence
 - 4070541 Forwards draft SER inputs for Section 13 6 re physical security & Section 16 0 re Tech Spacs 11RAGLIA-F.J Assistant Director for Safety Assessment 84/01/30 JVAX, TM Assistant Director for Licensing 4pp 22141 308, 24 1che: 50-354-84/01/30-8402070541

- F Security, medical, emergency & fire protection plans
- 8402090547 Bummary of 831207 meeting w/util & Bachtel in Bethesda.MD re fire protection plan Vieugraphs encl HAGNER.D H Licensing Branch 2 84/01/27 Licensing Branch 2 33pp 22191 144 248 Fiche 50-354.84/01/27.8402090547
- B402070541 Forwards draft SER inputs for Section 13 & re physical security & Section 16 O re Tech Space MIRAGLIA.F J Assistant Director for Safety Assessment 84/01/NUVAN.T M Assistant Director for Licensing 4pp 22141 308. Ficher 50-354,84/01/30,8402070541 84/01/30
- 8402030327 Forwards Rev i to emergency plan Resolution of NRC comments on emergency plan also encl
 MITTL.R L Public Service Electric & Oas Co of New Jersey
 84/01/31 SCHWENCER.A. Licensing Branch 2 22pp 22063 001. 24X
 Fiche 50-354.84/01/31.8402030327
- -8402030332 Rev 1 to emergency plan BURGE,C A , SALVESEN,R S Public Bervice Electric & Gas Co Jersey 84/01/16 350pp 22063:023 24% Fiche 50-354,84/ Jerseg 8 8402030327 24X Fiche 50-354,84/01/31,
- 8402160664 Requests listed addl info on 830223 amargancy plan. Sections 7 & 10 re vertical temp gradient & sigma theta Response within 30 days requested SCHENCER. A Licensing Branch 2 84/02/09 MITTL.R. L Public Service Electric & Oas Co of New Jersey 3pp 22292 354 24X Fiche: 50-354, 84/02/09, 8402160664
- 8402170425 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR SCHMENCER.A Licensing Branch 2 84/02/09 MITTL, R L. Public Service Electric & Qas Co of New Jersey 2pp 22313 188 24X Fiche 50-354,84/02/09,8402170425
- B402240154 Responds to B30810 ltr re security training & qualification plan Addl mods required Appropriate page changes should be submitted per enci comments Comments withheld (ref 100rR73 21)
 BCHMENCER.A Licensing Branch 2, 84/02/21, MITTL,R L. Public Bervice Electric & Gas Co of New Jersey 2pp 22374,346 24X
 Fiche 80-354,84/02/21,8402240184
- G Adjudicatory correspondence
- 8402060148 First set of interrogatories & request for production of documents Certificate of Svc encl RDDRTGUEZ, J H New Jersey, State of 84/02/02, Public Service Electric & Gas Co of New Jersey 9pp 22087 170, 24X Fiche 50-354,84/02/02,8402060148. от 84/02/02. Public Service Ярр 22087 170. 24X
- 8402080118 Forwards motion to strike Contention 4 re long-term scological effects on cropland & groundwater of salt deposition due to cooling tower operation W/O transcript of RR Parizek & GW Petersen 840113 depositions.

 RADER:R M Conner & Wetterhahn RADER:R M. Public Service Electric & Gas Co of New Jersey. 84/02/03. MILLER:M.E.: MORRIS:P.A., CARPENTER:J.H. Atomic Safety and Licensing Board Panel 2pp 22132-204 24X Fithe. 50-354.84/02/03.8402080118
- --8402080124 Motion to strike Contention 4 re long-term ecological effects on cropland & groundwater of salt deposition due to cooling tower operation Certificate of Bvc encl. CONNER: T.B. Public Service Electric & Qas Co. of New Jersey. CONNER: T.B. Conner & Wetterhahn. 84/02/03 Atomic Sefety and Licensing Board Panel 23pp 2R192 208. 24x Fiche 50-354,84/02/03,8402080118
- 8402130300 Nutifies that deposition transcript will be returned by 840214 Requiring interrogatories from State of DE contradicts previous position Related correspondence. DELANEY.C.E Delaware, State of, 84/02/08 RADAR.R.M. Conner & Hetterhahn 1p 22204.012 24X Fiche 50-354,84/02/08.8402130300.
- 8402130276 Notice of JH Rodriguez 840222 deposition in Newark, NJ re Contentions 1, 2 & 3 Certificate of Svc encl. Related correspondence.
 CONNERT.B Fublic Bervice Electric & Gas Co. of New Jersey
 CONNERT.B Conner & Wetterhahn. 84/02/09 App. 22198 250 24X
 Fiche 50-354,84/02/09,8402130276
- 840214006B Ack receipt of 84020B ltr re receipt of applicant preliminary set of initial interrogatories Perceived contradictions do not exist. Related correspondence. RADER, RM Conner & Wetterhahn RADER, RM, Public Service Electric & Gas Co of New Jersey. 84/02/10 DELANEY, C. Delaware, State of 2pp 22217 246 24X Fiche 50-354,84/02/10,840214006B.

- 8402220115 Forwards response to public advocate of State of NJ first set of interrogatories & request for production of documents Certificate of Svc entl Related correspondence FRYLING, R Public Service Electric & Gas Co of New Jersey 84/02/14 POTTER, R W New Jersey, State of 3pp 22326 082 24x Fiche.50-354,84/02/14,8402220115
- --8402220120 Response to JH Rodriguez.public advocate of NJ, first set of interrogatories & request for production of documents rewelding Certificate of Svc encl
 MARTIN.T J Public Service Electric & Gas Co of New Jersey
 84/02/13 33pp 22326 085 24X Fiche 50-354.84/02/14.8402220119
- 8402220336 Consent to util 840203 motion to dismiss Contention IV repotential environ impact of facility operation Util crude, creationist-inspired.sleight-of-hand attempts to rewrite history should be ignored Certificate of Svc encl POTTER, R. W. New Jersey, State of 84/02/17 Atomic Bafety and Licensing Board Panel 10pp 22336 241 24X Fiche 80-354,84/02/17,8402220336.
- 8402230050 Order dismissing State of DE Contention IV re-potential environ impacts from cooling tower & granting applicant 840203 motion to dismiss contention MILLER. M. E. Atomic Safety and Licensing Board Panel 84/02/21 Delaware. State of 2pp 22362 137 24X Fiche. 50-354.84/02/21.840230050.
- 8402240051 Order extending time until 840308 for Commission to act to review ALAB-759 CHILK,8 J Office of the Secretary of the Commission 84/02/23 Commissioners 1p. 22374:359 24X Fiche 50-354,84/02/23, 8402240051
- K Utility Final Safety Analysis Report (FSAR) & amends
- B402080185 Forwards Amend 4 to FBAR Amend responds to NRC 831121 & 1207 requests for add1 info HITTLIR L. Public Service Electric & Gas Co of New Jersey B4/02/06. SGHENCER: A Licensing Branch 2 2pp 22135 114 24X Fiche 50-354.84/02/06.8402080185
- --8402080189 Amend 4 to FSAR * Public Service Electric & Qas Co of New Jersey 84/02/06 2148pp 22135:116 24X Fiche 50-354.84/02/06.8402080185
- 840223007B Forwards affidavit certifying that distribution of Amend 4 to FBAR made in accordance w/10CFR2.10i.
 MITTL:R L Public Service Electric & Gas Co of New Jersey
 84/02/09. SCHWENCER.A. Licensing Branch 2 4pp 22362.141. 24X
 Fiche: 50-354:84/02/09.840223007B
- O Inspection reports, IE Bulletins & correspondence
- 83121R0153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co. of New York, Inc 120pp. 22058.001 24X Fiche 50-000,84/01/25,831R120153
- 8402070327 Forwards IE Insp Rept 50-354/83-17 on 831220-23 No violations noted.
 MARTIN, T. Division of Engineering & Technical Programs 84/01/27
 MARTIN, T. J. Public Service Electric & Oas Co. of New Jersey 2pp. 22160:303 24X Fiche: 50-354,84/01/27,8402070327
- ---8402090337 IE Insp Rept 50-354/83-17 on B31220-23 No violations noted Major areas inspected. Chicago Bridge & Iron program status, procedure review & observations of work in progress REYNOLDB, & D. DURR. J. P. Region 1. Office of Director 84/01/26 App. 22160,305 24X Fiche 50-354.84/01/27,8402090329
- B402150163 Forwards IE Insp Rept 50-354/83-18 on 831204-840105 & notice of violetion.
 STAROSTECKIR, Division of Project & Resident Programs. 84/01/30 MARTIM T. J. Public Bervics Electric & Gas Co of New Jersey Rpp. 22245:329. 24X Fiche: 50-354, 84/01/30, 8402150163
- --8402150168 Notice of violetion from Insp on 831204-840105 * Region 1, Office of Director. 84/01/30 ip 22245-331 24X Fiche 50-354,84/01/30,8402150163.
- --8402150170 IE Insp Rept 50-354/83-18 on 831204-840105 Violation noted GC failure to identify improper weld preparation for T-joints.

 BATEMAN. W. H., MCGABE, E. C. Region 1. Office of Director 84/01/16 7pp. 22245-332. 24X Fiche 50-354-84/01/30-8402150163.

- B401190016 IE Info Notice B4-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/02/03 Consolidated Edison Co of New York, Inc 119pp. 22114 179 24X Fiche 50-000,84/02/03,8401190014
- B401190017 IE Bulletin B4~01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement B4/02/03 Consolidated Edison Co of New York, Inc 102pp 22177
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50.App R)" Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Past 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22345 259 24X Fiche 50-000,84/02/13,8401190041
- 8401190037 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '"
 Svc list encl
 JDRDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co. of New
 York, Inc 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- 8401190045 IE Info Natice 83-63.8uppl 1, "Potential Failures of Wastinghouse Type 8A-1 Differential Relays" 8vc list encl JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc 118pp 22366 142 24X Fiche 50-000.84/02/15.8401190045
- B40119006R IE Info Notice B4-10, "Motor-Operated Valve Torque Switches Bat Balow Manufacturer Recommended Value " Svc list encl. JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp. 22366 024 24X Fiche 50-000,84/02/21,8401190062
- 8401190066 IE Info Notice 84-ii, "Training Program Deficiencies."
 Swc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co. of New
 York, Inc. 115pp 82430 304, 24X Fiche 50-000,84/02/24,8401190046
- 8401190067 IE Info Notice 84-12. "Failure of Soft Seat Valve Seals "
 Svc list enc!
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co. of New
 York, Inc 120pp 22431 060 24X Fiche 50-000,84/02/27,8401190067
- R Periodic operating reports & related correspondence
- 8402210202 Submits monthly status rept for Dec 1983 Fuel load date for Unit 1 is Jan 1986 Unit 2 const abandoned in Dec 1981 Const progress approx B1.14% complete LANDRIEU,P R Public Service Electric & Oas Co. of New Jersey 84/01/03 MCCABE,E C. Division of Project & Resident Programs. ip. 22314 321 24% Fichs.50-354.84/01/03.8402210202
- S Reportable occurrences, LERs & related correspondence
- 8402020261 Interim potential const deficiency rept re Agastat time delay relays Initially reported on 831207 Four defective relays identified. Mext rept by 840125 MARTIN.T.J. Public Service Electric & Gas Co. of New Jersey. 84/01/06 MURELY.T E. Region I. Office of Director 2pp. 22055 239 24X Fiche: 50-354,84/01/06,8402020261
- 8402030387 Interim deficiency rept re failure of OE Type AKR-30 circuit breakers to operate properly Initially reported on 831223 Caused by inadequate mechanical loading of closing spring Investigation in progress Next rept by 840321 MARTIN.T J. Public Service Electric & Oas Co of New Jersey. 84071718, MRLEY.T E Region 1 Office of Director 2pp 22066 033 24X Fiche 50-354,84/01/18,8402030387.
- 8402080271 Final significant const deficiency rept re Agastat Model E-7000 time delay relays supplied by Bechtel Initially reported on 831207, Defective relays replaced w/acceptable relays.

 HARTIN, T J. Public Bervice Electric & Oas Co, of New Jersey 84/01/25 MURLEY, T E. Region i, Office of Director 2pp. 22/31 280 24% Ficher 50-354,84/01/25,8402080271.
- 8402290073 Part 2i rept re reportable defects on certain AKR-30 & AKR-50 low voltage power circuit breakers delivered for use at facility Breakers currently under repair, reinsp & receptification DIXON.D. J. General Electric Co 84/02/24, DEYOUNG, R C Director' Defice, Office of Inspection and Enforcement. 6pp. 22426:031 24X Fiche:50-354,84/02/24,8402290093.

- DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2
- R Periodic operating reports & related correspondence
- 8402210202 Submits monthly status rept for Dec 1983 Fuel load date for Unit 1 is Jan 1986 Unit 2 const abandoned in Dec 1983 Const progress approx 81 14% complete LANDRIEU.PR Public Service Electric & Gas Co of New Jersey 84/01/03 MCCABE.E C Division of Project & Resident Programs 1p 22314 321 24% Fiche 50-354,84/01/03,8402210202
- S Reportable occurrences, LERs & related correspondence
- 8402020261 Interim potential const deficiency rept re Agastat time delay relays Initially reported on 831207 Four defective relays identified Next rept by 840125 MARTIN.T J. Public Service Electric & Gas Co. of New Jersey 84/01/06 MURELY.T E. Region 1. Office of Director 2pp 22055:239 24X Fiche 50-354,84/01/06,8402020261
- 8402030387 Interim deficiency rept re failure of GE Type AXR-30 circuit breakers to operate properly. Initially reported on 831223 Caused by inadequate mechanical loading of closing spring Investigation in progress Next rept by 840321 MARTIN.T J Public Service Electric & Oas Co of New Jersey 84/01/18 MARLEY.T E Region 1. Office of Director 2pp 22066-033 24X Fiche 50-394.84/01/18.8402030387
- 840R29G093 Part 21 rept re reportable defects on certain AKR-30 & AKR-30 low voltage power circuit breakers delivered for use at facility Breakers currently under repair, reinsp & recertification
 DIXON,D J General Electric Co 84/02/24 BEYGUNO,R C Director's
 Office, Office of Inspection and Enforcement App 22426 031. 24X
 Fiche' 50-394,84/02/24,8402290093
- DOCKET 50-358 WILLIAM H ZIMMER NUCLEAR STATION, UNIT 1
- A. Application/construction stage documents & correspondence
- 8402090003 Responds to FDIA request for const completion dates for OWNUMENT PLANTS CUrrently under const & analyses containing estimates based on Inclusion of Caseload Forecast Panel meetings Forwards App A. B & C documents
 FELTON.J M Division of Rules and Rocords 83/10/31
 ROBENBAUM.D M Technical Analysis Corp 19pp 22193-292 24X
 Fichs 50-000.83/10/31.8402090003
- -B402090175 Trip rept of Caseload Forecast Panel site visit re const status review & projected fuel load date Related info encl PELTIER, I.A. Light Water Reactors Branch I BOURNIAA Light Jater Reactors Branch 3 78/08/09 Light Water Reactors Branch I 24pp 22175.020 24X Fiche 50-000.83/10/31.8402090003
- -8402090307 Handwritten notes & calculations re const activities & fuel load preparation * NRC - No Detailed Affiliation Given 81/02/24. App 22196:331 24X Fiche 50-000,83/10/31.8402090003
- 8402080406 FDIA request for documents not available in PDR re informal & formal investigation pending by NRC concerning Cincinnati Oas & Electric Co &/or Facility CRMAN.K B Berger & Montague 83/11/07 NRC No Datailed Affiliation Givan 2pp 22168 212 24X Fiche 50-358, 83/11/07, 8402080406
- 8402080403 Responds to FDIA request for documents re informal 4/or formal investigations pending by NRC concerning facility W/O encl FELTON, J M Division of Rules and Records 83/12/12 ORMAN, K & Berger & Montague ip 22168 211 24X Fiche 50-358,83/12/12,8402080403. ORMAN, K. Ø
- 402160003 Third partial response to FDIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983. CHILKS J. Defice of the Secretary of the Commission 83/12/14 Public Document Branch ip 22281.023 24% Ficher 50-000.83/12/14.
- --8402160355 Staff requirements memo re 821112 discussion of Commission action in Washington, DC.
 CHILK-S J. Office of the Secretary of the Commission 82/11/18
 DIRCKS.W J. Office of the Executive Director for Operations ip 22281:244 24X Fiche, 50-000, 83/12/14, 8402160003
 - 12120136 Board Notification 84-011, discusses NRC use of terms "important to safety" & "safety-related "
 EISENHUT.D.O Division of Licensing 84/01/18 PALLADIND
 Commissioners 72pp 22241.008 24X Fiche 50-000.84/01/18.
 3312120136

8402160003

- B402030240 Informs of B40120 agreement to cease const of facility as nuclear plant & convert plant to coal-fired facility
 EJ Wagner designated responsible for closing out nuclear activities at facility activities at facility
 DIGMHONER, W H Cincinnati Gas & Electric Co 84/01/27
 KEPPLER, J G Region 3, Office of Director 1p 22069 324 24X
 Fiche 50-358,84/01/27,8402030260
- B401190057 Board Notification B4-027 provides util 840127 ltr informing, NRC that const of facility stopped & applicant intends to convert plant to coal-fired unit EISENHUT, DO Division of Licensing 84/02/13 PALLADIND, GILINBKY, ROBERTS Commissioners ip 22277 066 24X Fiche 50-359,84/02/13,8401190057
- 8401170039 Board Notification 84-032 provides add1 info on environ qualification Submittal augments info in Board Notifications 84-007 & 84-007 EISENHUT. D © Division of Licensing 84/02/13. Atomic Bafety and Licensing Board Panel 10pp 22314 204 24X Fiche 50-000,84/02/13. Licensing Board Panel 8401190099
- 8402270272 Confirms 840202 telcon understanding that, pending final Commission action for withdrawal of application, no need exists to continue previously required submittals to NRC. WAGNER, E. J. Cincinnati Gas & Electric Co. 84/02/16 KEPPLER, J. Rugion 3, Office of Director 2pp. 22391-302, 24X Fiche 50-358,84/02/16,8402270272
- 8402270310 Forwards revised organization chart effective as of 840217 Organizational changes due to decision to convert station from nuclear to coal-fueled generating facility.

 BICKHONER.W H Cincinnati Gas & Electric Co 84/02/17 KEPPLER.J O Region 3, Office of Director 4pp 22390 254 24X Fiche 50-358,84/02/17,8402270310
- F Becurity, medical, emergency & fire protection plans
- B402220159 Forwards IE Insp Rept 50-358/84-02 on 840109-13 & 16-20 No noncompliance identified MARNICK.R F Region 3, Office of Director 84/02/07 WAONER, E. J Cincinnati Gas & Electric Co 2pp 22339 251 24X Fiche 50-358,84/02/07,8402220159
- --B402220166 IE Insp Rept 50-35B/B4-02 on B40109-13 & 16-20 No numcompliance or deviations identified Major areas inspected licenses action on previously identified items, IE bulletins, IE circulars & nonconformance repts BCHEIBELHUT, C., ELSBERGAB, V.J., OWYNN, T.P. Region 3, Office of Director B4/02/07 10pp 22339 253 24X Fiche 50-358,84/02/07,8402220159
- 0. Adjudicatory correspondence
- 8402020044 Response opposing Miami Valley Power Project (MVPP) 831231 proposed issues & support for MVPP contentions Filing does not make compelling showing Certificate of Bvc sncl TREBY.S A Hearing Branch 1 84/01/20. Atomic Bafety and Licensing Board Panel 35pp 22056 270 24X Fiche 50~358.84/01/20. 8402020044.
- 8402090119 Order extending time until 840308 for Commission to act to review Director's Decisions DD-83-19 & DD-84-03 CMILK.B J Office of the Secretary of the Commission 84/02/07. Commissioners ip 22161 348 24X Fiche 50-358,84/02/07. 8402090119
- H General correspondence
- 8402100226 Forwards motion & Resolution R/18-1984 approved by City of OZIOWEM FORWARDS MOTION & MERGILUTION K/16-1949 Approved by C Cincinnati Council. In view of util announcement to cease const at facility as nuclear plant, NRC plans no action on either motion or resolution KEPPLER.J Q Region 3, Office of Director 84/02/06, POSEY Cincinnati, OH 2pp. 22179-220 24X Fiche 50-358,84/02/06, 8402100226 POSEY, W W.
- --8402100236 Notifies of 840105 adoption of motion advising NRC that limiting public participation to "time permitting" at 840111 meeting not in best interest of City of Cincinnati 840111 meeting nee an order or citizens.

 POSEY, W W Cincinnati, DH. 84/01/10 KEPPLER, J @ Ragion 3,

 Office of Director 2pp 22179 222, 24X Fiche; 50~358, 84/02/06,
- --8402100240 Notifies of approval of Resolution R/18-1984 expressing City of Cincinnati Council dissatisfaction over NRC failure to require third-party independent review of facility Resolution enci POBEY. W.W. Cincinnati, DM 84/01/13 KEPPLER, J. G. Region 3, Office of Director 2pp 22179 224, 24X Fiche, 50-358, 84/02/04, RA05100224 8402100226

Ø Inspection reports, IE Bulletins & correspondence

- B402020078 Forwards IE Insp Rept 50-358/83-26 on 831206-840106 No noncompliance noted WARNICK, R F Region 3, Office of Director 84/01/20 HILLIAMS, J Cincinnati Qas & Electric Co 2pp 22056 260 24% Fiche 50-358,84/01/20,8402020078
- --8402020086 IE Insp Rept 50-358/83-26 on 831206-840106 No noncompliance noted Major areas inspected licensee action on previous insp findings & IE circulars, quality confirmation program, nonconformance rept review & plant tours
 OMYNN.T P. NICHTINGALE, E. HILL, W. M. Region 3, Office of Director 84/01/18 8pp 22036-262 24X Fiche 50-358,84/01/20,8402020078
- B312120133 IE Info Notice 84-06. "Steam Binding of Auxiliary Fredwater Pumps " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co. of New York, Inc. 120pp. 22058 001 24X Fiche 50-000,84/01/25,8312120153
- 8402050393 Forwards comments on Reactor Controls, Inc (RCI) 830915 response to draft IE info notice re const deficiencies, per 83037 request. Work orders for lateral restraint beams not issued to RCI MACNER, E. J. Cincinnati Oes & Electric Co. 84/01/30 KEPPLER, J. G. Region G. Office of Director. Bpp. 22083 283 24% Fiche: 50-358,84/01/30,8402040393.
- 8402150174 Forwards IE Insp Rept 80-358/83-28 on 831227-30 No noncompliance noted LITTLE.W S Region 3. Office of Director 84/02/01 WAGNER, E. J Cincinnati Qas & Electric Co 2pp 22249 151 24X Fiche: 50-358,84/02/01,8402150174
- --8402150181 IE Insp Rept 50-358/83-28 on 831227-30 No noncompliance noted Major areas inspected review of action on 10CFR50 35e items.previously identified findings.quality conformance program insp & observation of installed electrical panels NALDU.K. CHRIBTNOT.E., FALEVITS, Z. Region 3. Office of Director 84/01/25 7pp 22249 153 24X Fiche 50-358.84/02/01.8402150174
- E4D1190016 IE Info Notice B4-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl.

 JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/02/03 Consolidated Edison Co. of New York, Inc. 119pp 22114 179 24X Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl. DEYOUNG, R C Director's Office. Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177:186. 24X Fiche 50-000.84/02/03.8401190017
- 8402220159 Forwards IE Insp Rept 50-358/84-02 on 840109-13 & 16-20 No noncompliance identified MARNICK, R F Region 3, Office of Director 84/02/07 WAGNER, E J Cincinneti Osa & Electric Co. 2pp 22339 251 24X Fiche: 50-358,84/02/07,8402220159
- --B40222D166 IE Insp Rept 50-358/B4-02 on B40107-13 & 16-20 No noncompliance or deviations identified Major areas inspected licensee action on previously identified items. IE bulletins. IE circulars & nonconformance repts BCHEIBELHUT, C., ELSBERGAB, V. J., GHYNN, T. P., Region 3, Office of Director B4/02/07 10pp 22337 253 24X Fichs. 50-358, B4/02/07, B402220157
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Bys (100FR50, App R)." Suc list snc!

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/13. Consolidated Edison Co. of New York. Inc. 124pp 22365, 299, 24X Fiche 50-000.84/02/13.8401190041
- 8401190039 IE Info Notice 84-08. "100FR30.7, 'Employee Protection'" Syc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/14 Consolidated Edison Co of New York, Inc. 113pp. 22365:141. 24X Fiche: 50-000,84/02/14,8401190039
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/15 Consolidated Edison Co of New York, Inc. 118pp. 22366, 142 24X Fiche: 50-000, 84/02/15, 8401190045

- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Set Belaw Manufacturer Recommended Value " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co. of New York, Inc. 114pp 22366 024 24X Fiche 50-000,84/02/21,8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies"
 Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12. "Failure of Soft Seat Valve Seals "
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060 24X Ficke 50-000,84/02/27,8401190067
- R Periodic operating reports & related correspondence
- 8402270004 Forwards monthly status rept for Jan 1984 DIRCKS,W J Diffice of the Executive Director for Operations 84/02/15 PALLADINO Commissioners 5pp 22408 031 24X Fiche 50-358,84/02/15.8402270004
- S Reportable occurrences, LERs & related correspondence
- 8402170317 Supplemental Part 21 rept re radiographic record evaluation, supplying add1 data to 830624 submittal Records show that 70 degree branch connections furnished to North Anna 1 & 2 jubsites No nozzles supplied to Zimmer Related info enci DURNES, R P Southwest Fabricating & Welding Co (subs of IU International Corp). 83/10/04 PDTAPUS.U Region 4. 0ffice of Director 6pp 28296 156 24% Fishe 50-000.83/10/04.8402170317
- 8402170196 Final Part 21 rept re potential problem concerning radiography of branch connection welds covered by reinforcing pads Welds at Byron Braidwood & North Anna acceptable. Weld 7 at Clinton reradiographed BORNES, R P Southwest Fabricating & Welding Co. (subs of IU International Corp). 84/01/02 POTAPUS. U Region 4, Office of Director. 2pp 22296 126 24X Fishe 50-000,84/01/02,8402170196
- 8402080389 Final deficiency rept. Item E-58 re flammability control unit motor control terminal cabinets Initially reported on 840104, Deficiency determined not reportable per 10CFR50 55(e).

 WAGNER, E J Cincinnati Cas & Electric Co 84/02/03 KEPPLER, J G Region 3. Office of Director 2pp 22130:357 24X Fiche 50-358,84/02/03,8402080389
- B40117004B Board Notification 84-006 provides info re alleged falsification of GC documents concerning const of safety-related HVAC units by Bahason Co.Winston-Balem.NC EIBENHUT.D 0 Division of Licensing B4/02/07 PALLADING Commissioners 7pp 2232 187 24X Fiche: 80-000,84/02/09,8401170048
- 8402150284 PNO-111-84-014 on 840207.contractor security guard accidentally discharged revolver on refueling floor of reactor bldg when removing pistol from holester Guard terminated by licensee No one injured CREED, J R . AXELSON. M L Region 3. Office of Director 84/02/10 ip 22242 117 24X Fiche 50-358,84/02/10,8402150284
- 8402220064 Final Deficiency Rept 8-18 re structural steel beam nonconformances Initially reported on 840113 Due to plan to convert facility to coal-fired power plant, no further action or correspondence planned on item HAONER.E J Cincinnati Gas & Electric Co. 84/02/10 KEPPLER, J Q Region 3. Office of Director 2pp 22337 239 24% Fiche 50-358.84/02/10.8402220064
- T Hearing transcripts on non-antitrust matters
- 8402270469 FOIA request for two categories of documents re facility HICKEY.J E Shaw, Pittman, Potts & Trombridge 83/11/23 GRIMSLEY,D H Division of Rules and Records 2pp 22395 096, 24X Fiche 50-358.83/11/23.8402270469
- B402270437 Partial response to FOIA request for two categories of documents re facility Review of add1 documents subj to request in progress. Transcript of Commission B31115 closed meeting withheld (ref FOIA Exemptions 5 & 7)
 FELTON, J M Division of Rules and Records 84/01/11 HICKEY, J P Bhaw, Pittman, Potts & Trowbridge. 1p 22375 075 24X
 Fiche 50-358.84/01/11.8402270457

- U Congressional/Executive Correspondence
- 8402270002 Responds to FOIA request for correspondence NRC received from Senators J McClure, JB Johnston & P Lazalt during past 2 yrs Forwards App A documents Name of individual deleted from Documents B & 9 of App A (ref FOIA Exemption 6) FELTON, J M Division of Rules and Records 83/11/30 KOLI, E Cable News Network, Inc. 6pp 22438 002 24X Fiche 50-000. 83/11/30, 8402270002
- --8402290137 Forwards ASLB 820621 initial decision in OL proceeding Decision does not address Miami Valley Power Project 820518 motion seeking admission of eight new contentions re OA & corporate competence

 MARMERER, C Dffice of Congressional Affairs 82/06/24
 OTTINGER, R L House of Rep., Energy & Commerce SIMPSON, A Senate, Environment & Public Works UDALL, M House of Rep., Interior & Insular Affairs 2pp 22438 041 24X
 Fiche 50-000,63/11/30,8402290002

DOCKET 50-361 SAN DNOFRE NUCLEAR STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8402070003 Responds to FDIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documents
 FELTON.J M Division of Rules and Records B3/10/31
 RDSENBAUM.D M Technical Analysis Corp 19pp. 22193 292. 24X
 Fiche 30-000,83/10/31,8402070003
- --8402090173 Trip rept of Caseload Forecast Panel 800909-11 site visits re const schedule review R000:H Licensing Branch 3 80/10/06 Licensing Branch 3 2pp 22196 174 24% Fiche 30-000:83/10/31:8402090003
- --8402090177 Corrected trip rept of Caseload Forecast Panel 791119 site visit re const status & schedule & startup test program RODD.H Light Water Reactors Branch 2 80/01/21 Light Water Reactors Branch 2 2pp 22196 177 24X Fiche 50-000.83/10/31. 8402090003
- F Security, medical, emergency & fire protection plans
- 8402010016 Ack receipt of 831101 ltr transmitting notification of temporary change to physical security plan & addendum to change forwarded by 840113 ltr Changes do not degrade physical security plan & are consistent w/10CFR30 54(p) SCHUSTER.M D Region 5, Defice of Director 84/01/18 HAYNES,J C Bouthern California Edison Co. 3pp. 22048 153 24X Fiche, 50-206, 84/01/18, 8402010016
- 8402070224 Forwards notification of temporary change to physical security plan Notification withhold (ref 10CFR73 21)
 HAYNEG, J G Bouthern California Edison Co 84/01/25 MARTIN, J B
 Region 5, Office of Director 1p 22096 166 24X
 Fiche: 50-206, 84/01/25, 8402070224
- B402020362 Forwards Rev O to "Control Room Design Review Plan" & Rev O to "Control Room Design Review Rept," in response to B307(2 telcon re Generic Ltr 82-33 (Suppl 1 to NUREO-0737) MEDFORD, M D Southern California Edison Co. 84/01/31, KNIGHTDN, G W Licensing Branch 3 2pp 22047 001 24X Fiche 50-341.84/01/31,8402020362
- ~-8402020364 Rev 0 to Procedure M37327, "Control Room Design Review Plan. Ban Onofre Nuclear Generating Station Units 2 & 3 " * Southern California Edison Co * San Diego Gas & Electric Co 84/01/31 23pp 22049-003 24% Fiche 50-361.84/01/31,8402020362
- ---8402020364 Rev 0 to "Control Room Design Review Rept, San Onofre Nuclear Generating Station Units 2 & 3 "
 * Southern California Editon Co * San Diego Gas & Electric Co M3738 ROO 84/01/31 230pp 22049 027 24X Fichs 50-361,84/01/31,8402020362
- 8402140124 Forwards IE Insp Regts 50-206/84-01, 50-361/84-01 & 50-362/84-01 on 840109-12. No noncompliance noted BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 84/01/31. BASKIN, M B Southern Callfornia Edison Co 2pp 22218 233 24% Fiche, 50-206, 84/01/31. 8402140124
 - 8402140139 IE Insp Repts 50-206/84-01.50-361/84-01 & 50-362/84-01 on 840109-12 No noncompliance noted Major areas inspected fire protection computer systemator coalant pump oil collection sys & LERs SCOMN. M. Region 5. Office of Director. 84/01/31 9pp 22218 235 24X Fiche 30-206.84/01/31.8402140124.

- 8402130401 Responds to 831117 ltr re protection of safeguards info at util corporate records ctr Protection described, acceptable in accordance w/requirements of 10CR73 21 & NUREO-0794 KNIGHTON.6 W Licensing Branch 3 84/02/02 BABKIN, K Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co 4pp 22216 181 24X Fiche 50-206,84/02/02,8402130401
- 8402150370 Supports NRC exemption for state & local govt participation in annual radiological preparedness exercise for facilities on 840229 KRIMM.R Federal Emergency Management Agency 84/02/08 JURDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) ip 22242 135 24X Fiche 50-206.84/02/08,8402150370
- 8402240211 Advises that NRC will not review emergency plans to delets privacy or proprietary info unless specifically requested by licensee, per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR KNI0HIDN: O W Licensing Branch 3 84/02/14 BASKIN, K P Bouthern California Edison Co HOLCOMBE. J C San Disgo Oas & Electric Co 3pp 22381 282 24% Fiche 50-361.84/02/14,8402240211
- 8402170252 Advises that updated fire hazards analysis will be submitted by 840316 MEDFORD M O. Bouthern California Edison Co 84/02/15 KNIGHTON.Q W Licensing Branch 3 ip 22297 073 24X Fiche 30-361.84/02/15.8402170252
- 8402220565 Discusses IE Safeguards Insp Repts 50-206/84-03.50-361/84-04 & 50-362/84-04 on 840124-26 No violations noted Major areas inspected selective exam of procedures & records & interviews w/personnel. Insp repts withheld (ref 10CFR2.790). NORDERHAUG, L R Region 5, Office of Director. 84/02/22 BASKIN, K B Southern California Edison Ca 2pp 22333 336 24X Fiche 50-206,84/02/22,8402220565.
- I Financial information
- 8402010454 FOIA request for review of Torrey Pines Technology study re ANI seismic design study & ANI & Insurance SVc Ofc last annual rept CALSOYAS, C D Affiliation Not Assigned 83/10/30, Region 5, Office of Director 4pp 22062,018 24X Fiche, 50-206,83/10/30, 8402010454
- 8402010457 Responds to FOIA request for review of Torrey Pines Technology study re ANI seismic design Info contained in Feb 1782 Suppl 5 & Jone 1782 Suppl 6 to NUREG-0712, available in FOR.
 FELTON.J M Division of Rules and Records 83/11/16 CALBOYAB.C D Affiliation Not Assigned 1p 22062.022 24X
 Fiche: 50-206.83/11/16.8402010457.
- K Utility Final Bafety Analysis Report (FBAR) & amends
- 8402170338 Forwards updated FBAR for San Onofre Nuclear Generating Station, Units 2 & 3, Vols 1-22. Update submitted as complete new FBAR; removing amend numbers from text & corresponding margin & change bars & repaginating pages

 BABKIN, K P Bouthern California Edison Co 64/02/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. Bpp 22450-001.
- --8402170337 Updated FBAR for San Onofre Nuclear Generating Station.Units 2 t 3. Vols 1-22
 * Southern California Edison Co. 84/01/31 7.766pp. 22450.009. 24X Fiche 50-361.84/02/10.8402170338
- --B402170435 App 2 58 to Ban Unofre Nuclear Generating Station.Units 2 & 3 updated FBAR (no title)
 * Southern California Edison Co. 84/01/31. 41pp. 22456 302.
 224 Fiche 30-361.84/02/10.8402170338
- --B402170341 Chapter 1 to San Onofre Nuclear Generating Station.Units 2 & 3 updated FSAR. "Introduction & General Description of Plant"

 * Southern California Edison Co 84/01/31. 200pp. 22450:044. 24X Fiche. 30-361.84/02/10.8402170338
- ---8402170344 Chapter 2 to San Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR, "Site Characteristics " W/22 oversize figures Aperture cards are available in PDR.
 * Southern California Edison Co. 84/01/31 1.300pp 22450-302 24X Fiche 50-361,84/02/10,8402170338
- --8402170345 App 2.3J to 8an Onofre Nuclear Generating Station.Units 2 & 3 updated FSAR. "Diurnal Wind Variation Tables for 10 Meter Level at San Onofre Plant Site " * Southern California Edison Co. 84/01/31 27pp 22452.083 24X Fiche: 50-361,84/02/10,8402170338

- ---B402170347 App 2 3A to Ban Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR. "Study of CA Tornadues" * Bouthern California Edison Co B4/01/31 15pp 22451 157 24X Fiche 50-361, B4/02/10. 8402170338
- --8402170348 Chapter 9 to San Onofre Nuclear Generating Station.Units 2 & 3 updated FBAR. "Auxiliary Sys" * Bouthern California Edison Co 84/01/31 600pp 22468 274 24X Fiche 50-361.84/02/10.8402170338
- --8402170350 App 2 3K to Ban Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR, "Diurnal Wind Variation Tables for 36 6/40 Meter Levels at Ban Onofre Plant Site "

 8 Southern Californis Edison Co 84/01/31, 27pp 22452 110 24X Fiche 50-361,84/02/10,8402170338
- --B402170351 App 2 38 to San Unofre Nuclear Generating Station, Units 2 & 3 updated FSAR. "Annual Joint Frequency Wind Speed-Wind Direction Summaries for Pasquill Stability Categories at 10-Meter Level & 36 6- & 40-Meter Level "

 * Southern California Edison Co 84/01/31 15pp 22451:172 24X Fiche 50-361,84/02/10,8402170338
- --B402170352 Chapter 10 to San Onofre Nuclear Generating Station, Units 2 & 3 updated FBAR, "Steam & Power Conversion Sys" # Southern California Edison Co B4/01/31 225pp 22470 308 24X Fiche 30-361,84/02/10,8402170338
- --8402170353 Chapter 3 to San Onofre Nuclear Generating Station.Units 2 & 3 updated FBAR. "Design of Structures.Components.Equipment & 8ys." W/15 oversize figures Aperture cards are available in FDR.

 # Southern California Edison Co 84/01/31 1,468pp 22456 355 24% Fiche 50-361,84/02/10,8402170338
- --B402170354 App 2 3L to San Onofre Nuclear Generating Station,Units 2 & 3 updated FBAR, "Diurnal Variation & Persistence of Pasquill Stability Categories & Low Level Inversions at San Onofre Plant Site "
 - Plant Site "
 * Bouthern California Edison Co 84/01/31 27pp 22452 137
 24X Fichs 50-361,84/02/10,8402170338
- --B402170355 App 2.3C to 8an Onofre Nuclear Generating Station.Units 2 & 3 updated FBAR, "Annual Joint Frequency Wind Speed-Wind Direction Summaries by Pasquill Statility Category For San Diego,CA (Period of Record 1955-64) From Star Program " * Bouthern California Edison Co 64/01/31 9pp 22451 187 24X Fiche 50-361,64/02/10,8402170338
- --B402170357 Chapter 11 to San Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR. "Radwaste Mgt" a Southern California Edison Co 84/01/31 225pp 22471:127 24X Fichs. 50-361, 84/02/10. 8402170338
- --B402170358 App 2 4A to 8an Onofre Nuclear Generating Station,Units 2 & 3 updated FBAR. "Rept on Pumping Test" * Bouthern California Edison Co. 84/01/31 49pp 22452 295. 24X Fiche: 50-361, 84/02/10, 8402170338
- --B402170359 App 2 3D to 8an Onofre Nuclear Generating Station, Units 2 k 3 updated FBAR. "Annual Joint Frequency Wind Speed-Wind Direction Summaries by Pasquill Category for Los Angeles, CA (Pariod of Record 1955-64) From Star Program " * Southern California Edison Co B4/01/31 9pp 22451 196 24X Fiche: 50-361,84/02/10,8402170338
- --B402170361 App 2 5A to 8an Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR. "Soil Liquefaction" a Southern California Edison Co 84/01/31 125pp 22454 084, 24X Fiche 30-361, 84/02/10, 8402170398.
- ---B402170362 App 3 6A to Ban Onofre Nuclear Generating Station,Units 2 & 3 updated FSAR. "High Energy Pipe Break Analysis."

 Bouthern California Edison Co B4/01/31 300pp 22457 330 24X Fiche: 30-361,84/02/10.8402170338
- --B402170363 App 2.3E to San Onofre Nuclear Generating Station, Units 2 & 3 Updated FBAR. "Annual Joint Frequency Wind Speed-Wind Direction Summaries by Pasquill Stability Category for Ban Diego & Los Angeles, CA (Period of Record 1973-74). "

 * Southern California Edison Co. B4/01/31. 17pp 22451 205 24X Fiche. 50-361, B4/02/10, 8402170338
- --B402170364 App 11.1A to San Unofre Nuclear Generating Station, Units 2 & 3 updated FSAR, "Derivation of Residence Times " # Bouthern California Edison Co 84/01/31, 125pp, 22471:169, 24X Fichs. 50-361, 84/02/10, 8402170338

- --8402170365 App 2 50 to San Onofre Nuclear Generating Station.Units 2 & 3 updated FSAR, "Chronology of Development of DNE Response Spectrum"
 - apectrum " * Southern California Edison Co 84/01/31 208pp 22454 256 24X Fiche 50-361,84/02/10,8402170338
- --8402170366 App 2 3F to San Onofre Nuclear Generating Station.Units 2 & 3 updated FBAR. "Monthly Joint Prequency Wind Speed-Wind Direction Summaries by Pasquill Stability Category at 10-Meter Wind Level for Plant Site "
 * Southern California Edison Co 84/01/31 BApp 22451 222 24X Fiche 50-361.84/02/10.8402170338
- --B402170367 App 3 68 to San Onofre Nuclear Cenerating Station.Units 2 & 3 updated FSAR. "Moderate-Energy Pipe Break Outside Containment" # Southern California Edison Co. 84/01/31 11po 22458 130
 - * Southern California Edison Co 84/01/31 11pp 22458 130 24X Fiche 50-361,84/02/10,8402170338
- --B402170368 App 2 3C to San Onofre Nuclear Generating Station.Units 2 & 3 updated FSAR. "Soil Borings"

 * Southern California Edison Co 84/01/31 App 22455 101 24X
 Fiche 50-361.84/02/10.8402170338
- --8402170369 App 3 7A to Ban Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR. "Seismic Response Spectra" # Southern California Edison Co 84/01/31 107pp 22458 326 24X Fiche 50-361, 84/02/10.8402170338
- --8402170370 Chapter 12 to San Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR, "Radiation Protection " W/21 oversize figures Aperture cards available in PDR * Southern Callfornia Edison Co. 84/01/31. 300pp, 22471 331 24X Fiche 50-361,84/02/10.8402170338
- --B402170372 App 2 3G to San Onofre Nuclear Generating Station,Units 2 & 3 updated FBAR. "Monthly Joint Frequency Wind Speed-Wind Direction Summaries by Pasquill Stability Category at Upper Wind Levels (36 6 m & 40 m) for Plant Site " # Southern California Edison Co 64/01/31. 84pp 22451 307 24X Fiche 50-361,84/02/10,8402170338
- --8402170373 App 2 5D to Ban Onofre Nuclear Generating Station.Units 2 & 3 updated FBAR, "Lab Testing & Soil Property Evaluation " * Southern California Edison Co 84/01/31 App 22455:107 24X Fiche. 50-361,84/02/10.8402170338
- --B402170375 App 2 SH to San Onofre Nuclear Generating Station, Units 2 & 3 updated FBAR, "Annual & Monthly Joint Frequency Wind Speed-Wind Direction Summaries at 10 Meter & 36 6/40 Meter Wind Levels for San Onofre Plant Site..."

 ** Southern California Edison Co 84/01/31 27pp 22452 027 24X Fiche 50-361,84/02/10,8402170338
- --B402170376 Chapter 13 to Ban Onefre Nuclear Generating Station, Units 2 & 3 updated FSAR, "Conduct of Operations " W/one oversize figure Aperture card available in PDR.

 * Southern California Edison GC 84/01/31 100pp. 22472 187 24X Fiche 50-361,84/02/10,8402170338
- --8402170377 App 2 5E to San Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR, "Dynamic Switchyard Slope Stability Confirmation"

 * Southern California Edison Co 84/01/31 96pp. 22455 111
 24X Fiche 50-361.84/02/10,8402170338
- ---8402170379 App 3 78 to San Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR. "Seismic Analysis of Piping Sys."

 * Southern California Edison Co 84/01/31. 20pp, 22459 070 24X Fiche 50-361.84/02/10.8402170338
- --8402170380 App 2 3I to San Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR. "Annual & Monthly Wind Direction Persistence (Duration) Summaries at 10 Meter & 36 6/40 Meter Wind Levels for Ban Onefre Plant Site . "

 # Southern California Edison Co 84/01/31 28pp, 22452 054 24X Fichs 50-361, 84/02/10, 8402170938
- --8402170381 App 13 1A to San Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR, "Resumes."

 # Southern California Edison Co 84/01/31 60pp 22472, 247
 24X Fichs 50-361, 84/02/10, 8402170338
- --8402170383 App 3 7C to Ban Onofre Nuclear Generating Station, Units 2 & 3 updated FBAR, "Boil-Structure Interaction Parameters" * Bouthern California Edison Co 84/01/31. 125pp 22459 090 24X Fiche 50-361,84/02/10,8402170338

- --8402170384 App 2 SF to Sen Onofre Nuclear Generating Station.Units 2 & 3 updated FSAR. "Geologic Rept on Area Adjacent to San Onofre Nuclear Generating Station Northwestern San Diego County.CA " W/six oversize figures Aperture cards in PDR * Southern California Edison Co 84/01/31 56pp 22455 207 24X Fiche 50-361.84/02/10.8402170338
- --B402170385 Chapter 14 to San Dnofre Nuclear Generating Station, Units 2 & 3 updated FSAR, "Initial Test Program" * Southern California Edison Co B4/01/31 100pp 22472.303 24X Fiche 50-361,64/02/10.8402170338
- ~~8402170388 App 3 7D to San Dnofre Nuclear Generating Station.Units 2 & 3 updated FSAR, "Setsmic Margin Analysis of Piping Sys " # Southern California Edison Co 84/01/31 5lpp 22457 214 24X Fiche 30-361.84/02/10.8402170338
- --8402170389 Chapter 15 to San Under Nuclear Generating Station, Units 2 & 3 updated FSAR. "Accident Analyses"
 * Southern California Edison Co 84/01/31 800pp 22473 114 24% Fiche 50-361,84/02/10,8402170338
- --8402170390 App 2 50 to San Dhofre Nuclear Generating Station, Units 2 & 3 updated FSAR, "Generalized Subsurface Study, Capistrano Area, Orange County, CA, Nov 1975 " Wiseven oversize figures Aperture cards are available in PDR * Southern California Edison Co 84/01/31 26pp 22455 257 24X Fiche 50-361, 84/02/10, 8402170338
- --8402170391 App 3 8A to San Enofre Nuclear Generating Station.Units 2 & 3 updated FSAR, "Visual Insp Criteria for Structural Steel & Miscellaneous Metal Welding to Meet Design Requirements " e Southern California Edison Co 84/01/31 8pp 22460 176 24X Fiche 50-361,84/02/10,8402170338
- --B402170373 App 2 BH to Ban Unofre Nuclear Generating Station.Units 2 & 3 updated FSAR. "Suppl to Generalized Subsurface Geological & Geophysical Study Capistrano Area. Drange County.CA. Jan 1979 " W/12 oversize figures Aperture cards in PDR * Southern California Edison Co B4/01/31. 30pp 22455 277 24X Fiche 50-361.84/02/10.8402170338
- ---8402170374 App 15A to San Dnofre Nuclear Generating Station,Units 2 & 3 updated FSAR, "Spec of Limiting Condition for Reactor Operation on Required Margim to DNB"

 # Bouthern California Edison Co 84/01/31 8pp 22475 291 24X Fiche: 50-361,84/02/10,8402170338
- --8402170376 App 150 to San Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR, "Dose Models Used to Evaluate Environ Consequences of Accidents "

 * Bouthern California Edison Co 84/01/31 22pp. 22475 299 24X Fiche 50-361,84/02/10,8402170338
- --B402170397 App 2 51 to San Onofre Nuclear Cenerating Station, Units 2 & 3 updated FBAR, "Presentation to NRC/USCC, Sept 1980 "
 + Southern California Edison Co B4/01/31 125pp 22455 296
 24% Fishe 50-361,84/02/10,8402170338
- --8402170399 App 15C to San Onofre Nuclear Cenerating Station.Units 2 & 3 updated FBAR. "Info Required by NRC for Dose Calculations " # Bouthern California Edison Co 84/01/31 13pp 22475 321 24X Fiche 50-361.84/02/10.8402170338
- --B402170400 App 3 9A to San Onofre Nuclear Generating Station.Units 2 & 3 updated FSAR, "Dynamic Sys Analysis of RCS Reactor Internals. ECCS Piping & Control Element Drive Mechanism Under Faulted Conditions."

 **Bauthern California Edison Co 84/01/31 35pp. 22461:090 24X Fichs 30-361.84/02/10/8402170338
- --B402170402 App 3 98 to Ban Onofre Nuclear Generating Station,Units 2 5 3 updated FBAR. "Reactor Vessel Thermal Shock Considerations for Small Break LOCAs " * Southern California Edison Co 84/01/31 2pp. 22461 126. 24X Fiche 50~361.84/02/10.8402170338
- 8402170403 App 2 5J to San Onofre Nuclear Generating Station. Units 2 & 3 updated FSAR. "Analysis of Post-1975 Earthquake Activity " * Southern California Edison Go 84/01/31 lapp 22456 143 E4X Fiche: 50-361.84/02/10.8402170338
- 3402170406 App 13D to San Onofre Nuclear Generating Station.Units 2 & 3 update6 FSAR, "Responses to IE Bulletins 79-27 & 80-06.IE Info Notice 79-22 & Multiple Control Sys Failure Evaluation "

 ** Southern California Edison Co 84/01/31 28pp 22475.334 24X Fiche 50-361.84/02/10.8402170338

- --8402170407 App 2 SK to San Dnofre Nuclear Generating Station,Units 2 & 3 udated FSAR. "Extent of Rose Canyon Fault Zone" # Southern California Edison Cn 84/01/31 7pp 22456 160 24X Fiche 50-361.84/02/10.8402170398
- --B40217040B App 3 10A to San Onofre Nuclear Generating Station,Units 2 t 3 updated FSAR, "Criteria for Seismic Qualification of Seismic Category I Equipment" * Southern California Edison Co 84/01/31 1App 22461 133 24% Fiche 50-361.84/02/10.8402170338
- --B402170407 App 15E to San Onofre Nuclear Generating Station.Units 2 & 3 updated FSAR. "Methodologies Used in Analyses of Large Steam Line Breaks "

 * Bouthern California Edison Co B4/01/31 57pp 22476 001 24X Fiche 50-361.84/02/10.8402170338
- --B402170411 App 3 10B to Sam Gnofre Nuclear Generating Station,Units 2 to 3 updated FSAR. "Results of Seismic Tests & Analyses Beismic Category 1 Instrumentation & Electrical Equipment "
 # Southern California Edison Co B4/01/31 17pp 22461 150 24X Fiche 50-361.84/02/10.8402170338
- --9402170412 Chapter 16 to Ban Dnofre Nuclear Generating Station, Units 2 & 3 updated FSAR. "Tech Specs" * Southern California Edison Co B4/01/31 ip 22476 058 24X Fichs 50-361.84/02/10,8402170338
- --8402170413 App 3A to San Dnofre Nuclear Generating Station, Units 2 & 3 updated FSAR. "Companison of Design W/NRC Reg Guides "
 * Bouthern California Edison Co 84/01/31 57pp 22461 2R3 24X Fiche 50-361.84/02/10,8402170338
- --B402170414 App 2 5L to San Onofre Nuclear Generating Station,Units 2 & 3 updated FBAR. "Baja & CA Continental Border Faults" # Southern California Edison Co B4/01/31 4ipp 22456 167 24% Fiche 50-361.84/02/10.840217038
- --8402170415 Chapter 17 to San Onofre Nuclear Generating Station Units 2 & 3 updated FBAR. "GA " * Bouthern California Edison Co 84/01/31 20pp 22476 059 24% Fiche: 50-361,84/02/10,8402170338
- --8402170416 App 30 to Sen Onofre Nuclear Generating Station.Units 2 & 3 updated FBAN. "Functional Evaluation of Components of Bys Shared by Two Units "

 * Southern California Edison Co 84/01/31 lipp 22461 280 24X Fiche 50-361.84/02/10.8402170338
- --8402170418 App 3C to San Onofre Nuclear Generating Station, Units 2 & 3 updated FBAR, "Computer Programs Used in Structural Analysis"

 * Southern California Edison Co 84/01/31 150pp 22461 291 24% Fiche 50-361,84/02/10,8402170338
- --8402170417 App 2 5M to 8an Chofre Nuclear Generating Station.Units 2 & 3 updated FSAR. "Mupothesized Offshore Zone of Deformation " * Southern California Edison Co 84/01/31 lopp 22456.208 24X Fichs 50-361.84/02/10.8402170398.
- --BA02170420 App 2 5N to Ban Onofre Nuclear Generating Station,Units 2 & 3 updated FSAR (no title) * Sputhern California Edison Co 64/01/31 18pp 22456 218 24X Fichs 50-361.84/02/10.8402170338
- ---8402170421 Chapter 4 to 8an Onofre Nuclear Generating Station.Units 2 k 3 updated FBAR. "Reactor "

 * Southern California Edison Ce 84/01/31 200pp 22462 104 24X Fiche 50-361,84/02/10,8402170338
- --8402170422 App 2 80 to 8an Onofre Nuclear Generating Station,Units 2 & 3 updated FSAR, "Faults W/Quarternary Movement Within 25 Miles of Ean Onofre" # Southern California Edison Co. 84/01/31 2pp 22456:236 24X Fiche 50-361,84/02/10,8402170338
- ---8402170423 Chapter 5 to San Dnofre Nuclear Generating Station,Units 2 & 3 updated FSAR, "RCS & Connected Sys" # Southern California Edison Co 84/01/31 350pp 22463 081. 24X Fiche: 50-361, 84/02/10,8602170338
- --8402170424 App 2 5P to San Onofre Nuclear Generating Station,Units 2 & 3 updated FSAR. "Coronado Banks & Palo Verde Faults " # Bouthern California Edison Co 84/01/31 4pp 22456:238 24X Fichs 50-34:84/02/10.8402170338

- --8402170426 App 3 2A to San Onofre Nuclear Generating Station, Units 2 & 3 updated FBAR, "Overpressure Protection for C-E 3,410 MWt Pressurized Reactors "

 * Southern California Edison Co 84/01/31 150pp 22463 334 24X Fich * 30-361,84/02/10,8402170338
- --8402170427 App 2 50 to San Dnofre Nuclear Generating Station, Units 2 5 3 updated FSAR, "Rose Canyon & Cristianitos Fault Zones " W/one oversize figure Aperture card is available in PDR # Southern California Edison Co 84/01/31 28pp 22456 242 24X Fiche 50~361,84/02/10,8402170338
- --8402170432 App 2 5R to 8an Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR, "Evaluation of Max Earthquake on Hypothesized Offshore Zone of Deformation " * Southern California Edison Co 84/01/31 31pp 22456 271 24X Fiche 30-361,84/02/10,8402170338
- --8402170433 Chapter 6 to San Onofre Nuclear Generating Station, Units 2 & 3 updated FBAR, "ESF " W/10 oversize figures Aperture cards available in PDN # Bouthern California Edison Co 84/01/31 600pp 22464 216 24X Fiche: 50-361, 84/02/10, 8402170338
- --8402170434 App 6 2A to San Onofre Nuclear Generating Station, Units 2 & 3 updated FBAR. "Local Leak Rate Testing " # Bouthern California Edison Co 84/01/31 50pp 22465 311 24X Fiche: 50-361, 84/02/10, 8402170338
- --8402170437 App 2.5T to San Onofre Nuclear Generating Station, Units 2 & 3 updated FBAR. "Oround Motion Analysis " # Southern California Edison Co 84/01/31 12pp 22456,343 24X Fiche.30-361,84/02/10,8402170388
- --8402170441 App 6 28 to 8an Onofre Nuclear Generating Station, Units 2 & 3 updated FBAR, "Containment Atmosphere Mass Releases
 Through Minipurge Bys Following LOCA"
 # Bouthern California Edison Co 84/01/31 150pp 22466:007
 24X Fiche 50-361,84/02/10,8402170338
- ---8402170442 Chapter 7 to San Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR. "Instrument & Controls " W/one oversize figure. Aperture card available in PDR " 8 Outhern California Edison Co 84/01/31 400pp 22466 234 24X Fichs 50-361, 84/02/10, 8402170338
- --8402170446 Chapter 8 to Ban Onofre Nuclear Generating Station, Units 2 & 3 updated FBAR: "Electric Power" # Southern California Edison Co 84/01/31 125pp 22468.117 24X Fiche. 50-361: 84/02/10, 8402170338.
- --8402170450 App B 2A to Ban Onofre Nuclear Generating Station.Units 2 & 3 updated FBAR: "Bulk Power Transmission Sys Reliability Criteria." W/two oversize figures Aperture cards available in PDR.

 B Bouthern California Edison Co 84/01/31 100pp 22468 158 24K Fiche: 50-361, 84/02/10, 8402170338
- P. Operating license stage documents & correspondence
- B312120029 Generic Ltr 83-39 to representatives of utils re-voluntary survey of licensed operators Svc list encl EIBENHUT, D 9. Division of Licensing. 83/12/08 Commonwealth Eddson Co. 12pp. 22313 006 24X Fiche 50-000,83/12/08,8312120029
- 8402030441 Responds to 831118 ltr.Continued transmittal of correspondence re facilities requested.
 HHARTON,R J. Wharton, R.J. B3/12/15 KNIOHTON,O W Licensing Branch 3. 1p. 22066 003. 24x Fichs.50-361,83/12/15,8402030441.
- 8401030275 Forwards response to T Chandresekaran comments on process control program, w/Rev O to Health Physics Procedure BD23-VII-8 5.1, "Process Control Program for San Onofre Units 2 & 3 " HEDFORD, M D. Southern California Edison Co 83/12/29 KNIGHTON, O. H Licensing Branch 3, 6pp 21680 174 24X Fiche: 50-361. 83/12/29. 8401030278
- B40213040B Forwards notice of consideration of issuance of amend to Licenses NFF-10 & NFF-15 & proposed NBHC determination & opportunity for hearing on 840103 request re number of hours per yr containment purge sys may be in operation RB00.H Licensing Branch 3 84/01/30 BASKIN.K P. Southern Catlfornia 561son Co. HDLCOMBE.J C San Diego Ges & Electric Co. 3pp. 22263.351 24X Fiche: 50-361,84/01/30,8402150408

- --8402150412 Notice of consideration of issuance of amends to Licenses NPF-10 & NPF-15 & proposed NSHC determination & opportunity for hearing NRIGHTON-0 W Licensing Branch 3 84/01/30 7pp 22263 354 24X Fiche 50-361,84/01/30,8402150408
- 8402010410 Generic Ltr 84-04 to all operating PWR licensees, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Svc list encl EISENHUT.D 9 Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc. 57pp 22177 087 24X Fiche 50-000,84/02/01,8402010410
- 8402040248 Suppl to 840125 application for Amends 23 & 9 to Licenses NFF-10 & NFF-15, respectively Affidavit re distribution of amend application encl NANDY.F R Southern California Edison Co 84/02/02 KNIGHTON.O W Licensing Branch 3 4pp 22087 177 24X Fiche 50-361,84/02/02.8402060248
- B4021503B3 Responds to Generic Ltr 84-01 re torms important to safety & safety-related As member of util safety classification group, supports further discussion on issue Ltr dtd B40126 sent requesting meeting MEDFORD, M D Bouthern California Edison Co 82/02/06 TAYLOR, J M Director's Office Office of Inspection and Enforcement 1p 22242 088 24X Fiche: 50-206. B4/02/06. B4021503B3
- 8402130350 Ack receipt of 840116 rept describing status of util efforts to locate items conteminated w/low levels of radioactive math Conclusions reasonable MENSLAMSKI.F A Region 5. Office of Director 84/02/07 MCCARTHY. C B Southern California Edison Co 1p 22203 300 24X Fiche 50-206.84/02/07.8402130350
- B40B210103 Discusses 840103 & 25 Tech Spec change requests to increase use of 8-inch containment purge sys NRC approval restricted to end of core life Justification of permanent increase in purge limit being developed MEDFORD, M O Southern California Edison Co 84/02/16 KNIGHTON, G W Licensing Branch 3 2pp 22317 236 24X Fiche 50-361,84/02/16,8402210103
- Q Inspection reports, IE Bulletins & correspondence
- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Fredwater Pumps" Syc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25, Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120153
- 8402030263 Ack receipt of 840106 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-206/83-21, 50-361/83-33 & 50-362/83-31
 BISHOP.T. W Region 5, Office of Director 84/01/31 MCCARTHY.C B Boutbern California Edison Go 1p 22069,325 24X
 Fiche: 50-206,84/01/31,8402030263
- --8402030271 Responds to NRC 831208 ltr re violations noted in 1E Insp Repts 50-206/83-21.50-361/83-39 & 50-366/83-31 Corrective actions:simulator training for operators modified to include plant situations requiring prompt action BASKIN,K.P. Bouthern Galifornia Edison Co 84/01/06 DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 9pp 22069 326 24X Fichs 50-206,84/01/31, 8402030263
- 8402140124 Forwards IE Insp Repts 50-206/84-01, 50-361/84-01 & 50-362/84-01 on 840109-12 No noncompliance noted BIBHOP, T W Division of Resident Reactor Project & Engineering Programs 84/01/31 NABKIN, K B Southern California Edison Co 2pp. 22218 233, 24% Fiche 50-206,84/01/31,8402140124
- --B402140137 IE Insp Repts 50-206/84-01, 50-361/84-01 & 50-362/84-01 on 840109-12. No noncompliance noted Major areas inspected, fire protection computer systreactor coolant pump oil collection sys & LERs.

 BCOMN, K. M. . HOLLENBACH, D. F. . CANTER, H. L. Region 5, Office of Director. 84/01/31 9pp 22218 235 24X Fiche 50-206, 84/01/31, 8402140124
- 8401190016 IE Info Notice 84-07, "Design-Dasis Threat & Review of Vehicular Excess Controls." Svc list encl JDRDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114:179 24X Fiche 80-000.84/02/03, 8401190016
- B401190017 IE Bullstin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl. DEYDUNG, RC Director's Office, Office of Inspection and Enforcement B4/02/03 Consolidated Edison Co of New York, Inc. 102pp 22177 156, 24X Fichs 50-000,84/02/03,8401190017

- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (2006R50.App R)," Syc list
- UDRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365 259 24% Fithe 50-000,84/02/13,8401190041
- 8401190039 IE Info Notice 84-08, "10CFR50 7. 'Employee Protection '"
 Svc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co. of New
 York, Inc. 115pp 22365 141 24X Fiche 50-000.84/02/14.8401190039
- 8401190045 IE Info Notice 83-63, Suppl 1. "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list entl JORDAN.F. L. Division of Emergency Praparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp. 22366 142 24X Fiche 50-000.84/02/15,8401190045
- 8401190063 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svr list encl JBRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 11609 22366 024 24% Fiche 50-000.84/02/21.8401190068
- 8402220563 Discusses IE Safeguards Insp Repts 50~206/84~03,50~361/84~04 & 50~362/84~04 on 840124~26 No violations noted Major areas inspected selective exam of procedures & records & interviews W/personnel Insp repts withheld (ref 100FR2 790) NORDERHAUD, L. R. Region 5, Office of Director 84/02/22 BASKIN & B. Southern California Edison Co. 2pp. 22333 336 24X Fiche 50~205.84/02/22,8402220565
- 8402280245 Forwards corrected Page 2 to 1E insp rept dtd 840209, for replacement Info describes power ascension transient testing & Unit 3 plant trips BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 84/02/23 BASMIN, K P. Southern California Edison Co 2pp 22399 276 24X Fiche 50~204, 84/02/23, 8402280243
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/24 Consolidated Edison Co of New York, Inc 115pp 22430 304 24X Fiche 30-000.64/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
 Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Past 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc. 120pp 22431 080 24X Fiche 50-000.84/02/27, 8401190067
- 9 Reportable occurrences, LERs & related correspondence
- 8402080027 Responds to FOIA request for documents re facility hot functional testing problems, including broken thermowells, loose & broken reactor coolant pump parts & loose thermal sleeves Forwards App A documents Documents also in FDR FELTON, J H Division of Rules and Records 83/11/16 QARDE, B Government Accountability Project 3pp 22170 253 24X Fiche 50-000,83/11/16,8402080027
- --8402080036 List of but functional testing exceptions Related info encl * Affiliation Not Assigned 63/11/16 19pp 22170, 256 24X Fiche 50-000, 83/11/16, 8402080029
- B402220154 Responds to FOIA request that 146 LERs be placed in PDR Forwards LERs listed on app Documents also available in FDR Remaining LERs were either canceled or not issued FELTON, J M Division of Rules and Records 83/11/30 JEFFERSON, G A APPILIATION NOT Assigned. 2pp 22380 052 24X Fiche 50-000,83/11/30,8402220154
- |402030366 LER B3-145/03L-0-on B31220.plant protection sys channel C ex-core safety channel linear power signal varied from CPC channel C Calibr linear power signal by 10%. Caused by unadjusted signal. Channel calibr W/880118 ltr HAYNES. J O Bouthern California Edison Co B4/01/18 HARTIN, J. B Region 5. Office of Director 3pp 22066 072 24% Fiche 50-361,84/01/18.8402030366
- iOZO30420 RD listed fire doors found inoperable during Dec surveillances Caused by incorrect design Design change packages being implemented to update door latches & closure mechanisms MAYNES, J @ Southern California Edison Co. 84/01/18 MARTIN, J B, Region 5. Office of Director App 22068 283 24X Fiche 80-361, P4/01/18, 8402030420

- 8402030273 LER 83-155/03L-0 on 831221, control element assembly calculator (CEAC) i inoperable due to spurious position indication on control element assembly 20 Cause undetermined Test performed satisfactorily W/840119 ltr MAYNES, J & Southern California Edison Co 84/01/19 MARTIN, J & Region 5. Office of Director 3pp 22069 203 24x Fiche 50-361,84/01/19,8402030273
- 8402130387 LER 83-156/03L-O on 831222, snubber 82-8T-017-H-009 determined to be binding in compression mode Caused by inadequate administrative controls Engineering Procedure 80123-V-5 1 revised W/880124 ltr HAYNES, J 9 Southern California Edison Ca 84/01/24 MARYIN, J 8 Region 5, Office of Director 5pp 22197 068 24X Fiche 50-361,84/01/24,8402130387
- B402130333 RO re fire protection cable separation criteria Intent of License Condition 2 Q discussed w/NRR & util submitted request for license amend to revise reporting requirements HAYNES, J Q Southern California Edison CO 84/01/26 MARTIN. J B Region 5, Office of Director 2pp 22197 265 24X Fiche 50-361,84/01/26,8402130333
- 8402160386 RD on 840111.facility outside design basis, rendering high pressure safety injection trains inoperable for approx 25 minutes Incident reviewed by station mgt Analysis of occurrence discussed W/NRC resident inspector HAYNES.J 9 Southern California Edison Co 84/02/10 Record Services Branch (Decument Control Desk). 2pp 22267 059 24X Fiche 50-361,84/02/10.8402160386
- 8402210244 Informs that 840111 notification of incident unnecessary in that only one train of MPSI rendered inoperable MAYNES.J. 6 Southern California Edison Co 84/02/10 Record Services Branch (Document Control Desk) 2pp 22315;350 24X Fiche 50-361.84/02/10.8402210244
- 8402210245 LER 84-001 on 840111 preparation of fire hazard analysis & review of fire protection surveillance results identified deficiencies in fire protection program, Review in progress Complets rept will be submitted by 840228 W/840213 ltr HAYNES, J 9 Southern California Edison Co 84/02/13 2p 22314 320 24% Ficher 50-361,84/02/13,8402210245
- B402220530 Part 2: rept re defective DSR & DSRV standby dissel generator turbocharger thrust bearing lubrication Deficiency not corrected by sys mod New recommendation will be sent to customers by 840330

 SOYER, R E Transamerica Delaval, Inc 84/02/15, Director's Office, Office of Inspection and Enforcement 5pp 22332 182 24x Fiche: 50-000, 84/02/15, 8402220530
- 8402230148 LER 84-004-00 on 840116, train A containment purgs isolation sys spuriously actuated Caused by subgroup relay actuation voltage transient on EBF bus. No corrective action planned as minor transients expected in test W/840215 ltr. HAYNES, J G Sauthern California Edison Co 84/02/15 3pp 22361 081. 24X Fiche 50-361,84/02/15,8402230148
- 8402230211 PNO-V-84-009 on 840215, limited number of workers trasted 'following inhalation of fumes from unknown substance, Cause believed to be tear gas from Marine Corps training activities. Emergency drill interrupted CARTER, H. L. KIRSCH, D. F. Region 5, Office of Director 84/02/15 ip 22361:106 24X Fiche, 50-206, 84/02/15, 8402230211
- 8402280413 LER 84-003-00: on 840122, containment purge isolation *## actuated when gasgous activity alarm setpoint reached train A containment airborne monitor 2RT7804 Caused by increase in containment background radiation W/840221 Itr. HAYNES, J & Bouthern California Edison Co 84/02/21. 3pp 22407 155. 24X Fichs 50-361.84/02/21.8402280413
- DOCKET 50-362 SAN ENDFRE NUCLEAR STATION, UNIT 3
 F Bacurity, medical, emergency & fire protection plans
- 8402010016 Ack receipt of 831101 ltr transmitting notification of temporary change to physical security plan & addendum to change forwarded by 840113 ltr Changes do not degrade physical security plan & are consistent w/100FR80, 54(p) SCHUBTER, M D Region 5, Office of Director 84/01/18 HAYNES, J C Southern California Edison Co. 3pp 22048 153, 24X Fiche. 50-206, 84/01/18, 8402010016
- 8402070224 Forwards notification of temporary change to physical security plan Notification withheld (ref 10CFR73, 21) HAYNES.J G. Sauthern California Edison Co. 84/01/25 MARTIN.J B Region 5. Office of Director 1p. 22076

- 8402020362 Forwards Rev O to "Control Room Design Review Plan" & Rev O to "Control Room Design Review Rept." in response to 830912 telcon re Generic Ltr B2-33 (Suppl 1 to NUREG-0737) HEDFORD.M D Bouthern California Edison Co 84/01/31 KNIOHTON.O W Licensing Branch 3 2pp 22049.001 24X Fiche 50-361.840/01/31.8402020362
- --8402020364 Rev O to Procedure M37327, "Control Room Design Review Plan. Ban Onofre Nuclear Generating Station Units 2 & 3 " * Bouthern California Edison Co * Ban Diego Gas & Electric Co 84/01/31 23pp 22049 003 24% Fiche 50-361,84/01/31.8402020362
- --8402020366 Rev 0 to "Control Room Design Review Rept, San Onofre Nuclear Generating Station Units 2 & 3 " * Southern California Edison Co * San Diego Gas & Electric Co M37328 ROO 84/01/31 230pp 22049 027 24X Fiche: 50-361,84/01/31,8402020362
- B402140124 Forwards IE Insp Repts 50-206/84-01,80-361/84-01 & 50-362/84-01 on 840109-12 No noncompliance noted BIBHOP. T W Division of Resident, Reactor Project & Engineering Programs. 840/1/31 BAGKIN, K B Southern California Edison Co 2pp 22218 233 24X Fiche 50-206,84/01/31,8402140124
- --8402140137 IE Insp Repts 80-206/84-01.50-361/84-01 & 50-362/84-01 on 840107-12.No noncompliance noted Major areas inspected fire protection computer sys, reactor coolant pump oil collection SUS & LERS SCOWN, K M Region 5, Office of Director 84/01 22218: 235 24X Fiche 50-206,84/01/31,8402140124
- 8402130401 Responds to 831117 ltr re protection of safeguards info at util corporate records ctr Protection described, acceptable in accordance w/requirements of 10CFR73 21 & NUREO-0794 NURGE-0794
 KNIGHTON,0 W Licensing Branch 3 84/02/02 DABKIN,K Bouther:
 California Edison Co HOLCOMBE,J C San Diego Pas & Electric Co
 4pp 22216 181. 24X Fiche 50-206,84/02/02,8402130401. Bouthern
- 8402150370 Supports NRC exemption for state & local govt participation in annual radiological preparedness exercise for facilities on 840227 RIMM. Federal Emergency Management Agency, 84/02/08, JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) ip 22242 133 24X Fiche 50-206, 84/02/08, 8402150370
- B402240211 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per B10707 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR KNIGHTON.G W Licensing Branch 3 84/02/14 BASKIN, K.P Southern WHIGHTON, C W Licensing Branch 3 84/02/14 BASKIN, K.P Southe California Edison Co HOLCOMBE, J C. San Diego Cas & Electric Co. 3pp. 22381 282 24X Fiche 50-361, 84/02/14, 8402240211 Southern
- 8402170252 Advises that updated fire hazards analysis will be submitted by B40316.

 MEDFORD, M O Southern California Edison Co 84/02/
 KNIQHTON, G W, Licensing Branch 3 lp. 22277.073

 Fiche: 50-361.84/02/15.8402170252 84/02/15
- B402220565 Discusses IE Safeguards Insp Repts 50-206/84-03,50-361/84-04 & 50-362/84-04 on B40124-26 No violations noted Major areas inspected selective exam of procedures & records & interviews w/personnel Insp repts withheld (ref iOCFR2,790) NORDERHAUG, L. R. Region 5. Office of Director B4/02/22. BABKIN, K B Southern Celifornia Edison Co 2pp 22033,036 24X Fiche: 50-206,84/02/22,8402220565

I Financial information

- 8402010454 FOIA request for review of Torrey Pines Technology study re ANI seismic design study & ANI & Insurance Svc Ofc last annual rept. CALSOYAB.G D. Affiliation Not Assigned 93/10/30 Region 5. Office of Director. 4pp. 22062 018 24X Fiche 50-206,83/10/30, 8402010454.
- 8402010457 Responds to FOIA request for review of Tarrey Pines Technology study re ANI seismic design Info contained in Feb 1982 Buppl B & June 1982 Buppl B to NUREO-0712, available in PDR Revision of Rules and Records. B3/11/16 CALBOYAB.C.D Affiliation Not Assigned 1p 22062 022 24X Fiche 30-206.83/11/16.8402010457

- K Utility Fina) Safety Analysis Report (FSAR) & amends
- 8402170338 Forwards updated FBAR for San Onofre Nuclear Generating Station, Units 2 & 3, Vols 1-22 Update submitted as complete new FBAR: removing amend numbers from text & corresponding margin & change bars & repaginating pages BASKIN, K P Southern California Edison Co 84/02/10 DENTON, H R Office of Nuclear Reactor Regulation, Director Bpp 22450 001 24X Fiche 50-361, 84/02/10, 8402170338
- --8402170339 Updated FSAR for San Onofre Nuclear Generating Station, Units # 2 & 3, Vols 1-22 # Southern California Edison Co 84/01/31 9,964pp 22450 009 24X Fiche 50-361,84/02/10,8402170338
- --8402170433 App 2 38 to San Onofre Nuclear Generating Station, Units 2 & 3 updated FBAR (no title) * Bouthern California Edison Cu 84/01/31 41pp 22456 302 24X Fiche 50-341,84/02/10.8402170338
- --8402170341 Chapter 1 to San Onofre Nuclear Generating Station, Units 2 & 3 updated FBAR. "Introduction & General Description of Plant" 84/01/31 200pp 22450 044 # Bouthern California Edison Co 8/ 24% Fiche 50-361,84/02/10,8402170338
- ---B402170344 Chapter 2 to 8an Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR. "Site Characteristics " W/22 oversize figures Aperture cards are available in FDR # Sauthern California Edison Co B4/01/31 1,300pp 22450 302 24X Fiche 50-361,84/02/10,8402170338
- --8402170345 App 2 3J to San Onofre Nuclear Generating Station.Units 2 & 3 updated FBAR. "Diurnal Wind Variation Tables for 10 Meter Level at San Onofre Plant Site "
 * Southern California Edison Co 84/01/31 27pp 22452 083 24X Fiche 50-361.84/02/10.8402170338
- --8402170347 App 2 3A to Ban Onofre Nuclear Generating Station.Units 2 & 3 updated FBAR. "Study of CA Tornadoes "
 * Bouthern California Edison Co 84/01/31 15pp 22451 157 24X Fiche. 50-361, 84/02/10, 8402170338
- --8402170348 Chapter 9 to San Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR, "Auxiliary Sys" * Southern California Edison Co 84/01/31 600pp 22468 274 24% Fiche 50-361, 84/02/10, 8402170338
- --9402170350 App 2 3K to San Onofre Nuclear Generating Station. Units 2 & 3 updated FSAR. "Diurnal Wind Variation Tables for 36.6/40 Meter Levels at San Onofre Plant Site "

 * Bouthern California Edison Co. 84/01/31 27pp 22452 110 24X Fiche 50-361.84/02/10.8402170338
- ---8402170351 App 2 38 to San Onofre Nuclear Generating Station.Units 2 5 3 updated FSAR. "Annual Joint Frequency Wind Speed-Wind Direction Summaries for Pasquill Stability Categories at 10-Meter Level & 36 6- & 40-Meter Levels " * Southern California Edison Co 84/01/31 15pp 22451 172 24X Fiche 80-361.84/02/10.8402170338
- --B402170352 Chapter 10 to Ban Onofre Nuclear Generating Station,Units 2 & 3 updated FSAR, "Steam & Power Conversion Sys " * Bouthern California Edison Co B4/01/31 225pp 22470 308 24X Fiche 50-3ai, B4/02/10,8402170338
- ---B4021703B3 Chapter 3 to Ban Onofre Nuclear Generating Station.Units 2 & 3 updated FBAR, "Design of Structures.Components.Equipment & Bys " W/ID oversize figures Aparture cards are available & 3 upd & Sys " in PDR. Bouthern California Edison Co 84/01/31 1,469pp 22456 355 24X Fiche: 50-361, 84/02/10, 8402170338
- --B402170354 App 2 3L to San Dnofre Nuclear Generating Station, Units 2 & 3 updated FBAR, "Diurnal Variation & Persistence of Pasquill Stability Categories & Low Level Inversions at San Onofre Plant Site " * Southern California Edison Co 84/01/31, 27pp 22452 137 24X Fiche 50-361,84/02/10,8402170338
- --8402170355 App 2.3C to Ban Onofre Nuclear Generating Station, Units 2 & 3 updated FBAR, "Annual Joint Frequency Wind Speed-Wind Direction Summaries by Pasquill Stability Category for San Diago, CA (Period of Record 1955-64) From Btar Program."

 * Southern California Edison Co 84/01/31 9pp 22451:187 24X Fiche:50-361,64/02/10,6402170336
- --8402170397 Chapter 11 to San Dnofre Nuclear Generating Station.Units 2 & 3 updated FSAR, "Radwaste Mgt " # Southern California Edison Co 84/01/31 225pp 22471:127 24X Fiche 50-361.84/02/10.8402170338

- --B402170358 App 2 4A to San Onofre Nuclear Generating Station,Units 2 & 3 updated FSAR, "Rept on Pumping Test"

 * Southern California Edison Co 84/01/31 49pp 22452 295 24X Fiche 50-361, B4/02/10, B402170338
- --8402170359 App 2 3D to San Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR, "Annual Joint Frequency Wind Speed-Hind Direction Bummaries by Pasquill Category for tos Angeles, CA (Period of Record 1953-64) From Star Program "

 8 Gouthern California Edison Co B4/01/31 9pp 22451 196 24X Fiche 50-361, 84/021/03.8402170338
- --8402170351 App 2 5A to San Onofre Nuclear Generating Station.Units 2 5 3 updated FSAR. "Soi) Liquefaction" * Southern Califernia Edison Co 84/01/31 125pp 22454 084 24X Fiche 50-361.84/02/10,8402170338
- --B402170362 App 3 6A to San Onofre Nuclear Generating Station.Units 2 & 3 updated FSAR. "High Energy Pipe Break Analysis "
 # Southern California Edison Co B4/01/31 300pp 22457 330 24X Fiche 50-361.84/02/10.8402170338
- --8402170363 App 2 3E to San Unofre Nuclear Generating Station.Units 2 & 3 updated FBAR. "Annual Joint Frequency Wind Speed-Wind Direction Summaries by Pasquill Stability Category for San Diego & Los Angeles.CA (Period of Record 1973-74) "
 # Southern California Edison Co 84/01/31 17pp 22451 205 24X Fiche 50-361.84/02/10,8402170338
- --8402170364 App 11 1A to Ban Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR, "Derivation of Residence Times " # Bouthern California Edison Co 84/01/31 125pp 22471 169 24% Fiche 50-361,84/02/10,8402170338
- --8402170365 App 2 5B to San Gnofre Nuclear Generating Station Units 2 & 3 updated FSAR. "Chronology of Development of DBE Response Spectrum"

 * Southern California Edison Co B4/01/31 208pp 22454 256 24X Fiche 50-061, 84/02/10, 8402170338.
- --B402170366 App 2 SF to San Dnofre Nuclear Generating Station.Units 2 & 3 updated FSAR. "Monthly Joint Frequency Wind Speed-Wind Direction Summaries by Pasquill Stability Category at 10-Meter Wind Level for Plant Bite ,"

 **Southern California Edison Co B4/01/31 B4pp 22451 222 24X Fiche 50~361.84/02/10.8402170338
- --0402170367 App 3 6B to Ban Dnofre Nuclear Generating Station.Units 2 & 3 updated FSAR. "Moderate-Energy Pipe Break Outside Containment" # Southern California Edison Co 84/01/31 (1pp 22458 130 24X Fiche 50-361.84/02/10.8402170338
- --8402170368 App 2 SC to San Onofre Nuclear Generating Station.Units 2 & 3 updated FSAR, "Soil Borings" * Bouthern California Edison Co 84/01/31 App 22455 IO1 24X Fichs 50-361.84/02/10,8402170338
- -8402170369 App 3 7A to San Chofre Nuclear Generating Station Units 2 & 3 updated FBAR. "Seismic Response Spectra."
 * Southern Collifornia Edison Co. 84/01/31 107pp 22488 326
 24X Fiche "80-361.84/02/10.8402170338
- -8402170370 Chapter iZ to San Gnofre Nuclear Generating Station, Units Z & 3 updated FSAR, "Radiation Protection " W/21 oversize figures Aperture cards available in FDR * Southern California Edison Co 84/01/31 300pp 22471 331. 24X Fiche 30-341.84/02/10.8402170338
- -BA02170372 App 2 30 to San Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR. "Monthly Joint Frequency Wind Speed-Wind Direction Summaries by Pasquill Stability Category at Upper Wind Levels (36,6 m & 40 m) for Plant Sits " # Southern California Edison Co. 84/01/31 BApp. 22451 307 24X Fiche 50-361, 84/02/10, 8402170338
- -B402170373 App 2 3D to San Unofre Nuclear Generating Station, Units 2 & 3 updated FBAR. "Lab Testing & Soil Property Evaluation."

 * Bouthern California Edison Co 84/01/31 App 22455,107 24X Fiche: 50-361,84/02/10,8402170338
- -8402170375 App 2 3H to San Dnofra Nuclear Generating Station.Units 2 & 3 updated FSAR. "Annual & Monthly Joint Frequency Wind Speed-Wind Direction Symmaries at 10 Mater & 36 6/40 Meter Wind Levels for San Onofra Plant Bite . "
 * Southern California Edison Co 84/01/31 27pp. 22452 029. 24X Ficha 50-361,84/02/10,8402170338

- --8402170376 Chapter I3 to San Onofre Nuclear Generating Station, Units 2 & 3 updated FBAR. "Conduct of Operations " W/one oversize figure Aperture card available in PDR 8 Southern California Edison Co 84/01/31 100pp 22472 187 24X Fiche 50-361,84/02/10,8402170338
- --8402170377 App 2 5E to San Unofre Nuclear Generating Station.Units 2 & 3 updated FSAR.' "Dynamic Switchyard Slope Stability Confirmation" # Southern California Edison Co 84/01/31 94pp 22455 111 24X Fiche 50-361.84/02/10.8402170338
- ---84021703/9 App 3 78 to 8an Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR. "Seismic Analysis of Piping Sys "
 * Southern California Edison Co 84/01/31 20pp 22459 070
 24X Fiche 50-361.84/02/10.8402170338
- --8402170380 App 2 31 to San Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR, "Annual & Monthly Wind Direction Persistence (Duration) Summeries at 10 Meter & 36 6/40 Meter Wind Lavels for San Onofre Plant Site " # Southern California Edison Co 84/01/31 28pp 22452:056, 24X Fiche 50-361.84/02/10.8402170338
- ~-8402170381 App 13 1A to San Unofre Nuclear Generating Station,Units 2 & 3 updated FSAR, "Resumes " # Southern California Edison Co 84/01/31 60pp 22472.247. 24X Fiche 50-361,84/02/10,8402170338
- --8402170383 App 3 7C to San Onofre Nuclear Generating Station, Units 2 k 3 updated FBAR. "Soil-Structure Interaction Parameters" * Southern Californie Edison Co 84/01/31 125pp. 22459.090. 24X Fiche 50-36t.84/02/10.8402170338
- --8402170384 App 2 3F to Ban Unofre Nuclear Generating Station, Units 2 k 3 updated FSAR, "Geologic Rept on Area Adjacent to Ban Onefre Nuclear Generating Station Northwestern San Diego County, CA " W/six oversize figures, Aperture cards in PDR a Bouthern California Edison Co 84/01/31 56pp 22455 207 24X Fiche 50-361, 84/02/10, 8402170338
- --8402170385 Chapter 14 to San Unofre Nuclear Generating Station, Units 2 & 3 updated FSAR, "Initial Test Program,"

 * Bouthern California Edison Co. 84/01/31 100pp 22472.303.
 24X Fiche 50-361.84/02/10.8402170338
- --8402170388 App 3 7D to San Onofre Nuclear Generating Station.Units 2 & 3 updated FBAR. "Beismic Margin Analysis of Piping Sys " Southern California Edison Co 84/01/31 5ipp. 22459 214. 24X Fiche 50-361.84/02/10.8402170338
- --B4021703B9 Chapter 15 to Ham Ondfre Nuclear Cenerating Atation, Units 2 & 3 updated FBAR. "Accident Analyses" # Bouthern California Edison Co 84/01/31 800pp 22473 114 24% Fiche 50-361.84/02/10.8402170338
- --8402170390 App 2 50 to 8an Dnofre Nuclear Generating Station, Units 2 & 3 updated FSAR. "Generalized Subsurface Study, Capistrano Area, Grange County, CA, Nov 1975 " W/seven oversize figures Aperture cards are available in FDR # Southern California Edison Co 84/01/31 26pp. 22455:257. 24% Fiche 50-361, 84/02/10, 8402170338.
- ~-8402170391 App 3.8A to San Omofre Nuclear Generating Station.Units 2 to 3 updated FSAR. "Visual Insp Criteria for Structural Steel & Miscellaneous Metal Welding to Meet Design Requirements." * Southern California Edison Co 84/01/31. 8pp. 22460:176. 24X Fiche 50-361.84/02/10.8402170338.
- --8402170393 App 2.3H to 8an Onofre Nuclear Generating Station.Units 2 to 3 updated FBAR. "Suppl to Generalized Subsurface Geological to Geophysical Study Capistrano Area Grange County.CA. Jan 1979." M/12 oversize figures Aperture cards in PDR * Southern California Edison Co 84/01/31 30pp 22455.277 24% Fichs 30-351.84/02/10.8402170338
- --B402170394 App 15A to Ban Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR, "Spec of Limiting Condition for Reactor Operation on Required Margin to DNS."

 * Southern California Edison Co 84/01/31. Spp 22475.291. 24X Fiche, 50-361, 84/02/10, 8402170338.
- --8402170396 App 13B to Ban Unofre Nuclear Generating Station.Units 2 & 3 updated FBAR. "Dose Models Used to Evaluate Environ Consequences of Accidents."

 **Southern California Edition Co 84/01/31. 22pp. 22475.299
 24X Fich# 50-361.84/02/10.8402170338

- --B402170397 App 2 5I to San Onofre Nuclear Generating Station, Units 2 & 3 updated FBAR, "Presentation to NRC/USGC, Sept 1980 "

 + Bouthern California Edison Co 84/01/31 125pp 22455 296
 24X Fiche 50-361,84/02/10,8402170338
- ---B402170379 App 15C to Ban Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR, "Info Required by NRC for Dose Calculations" * Bouthern California Edison Co B4/01/31 13pp 22475 321 24% Fishs 30-361, 84/02/10, 8402170338
- --B402170400 App 3 9A to San Onofre Nuclear Denerating Station, Units 2 & 3 updated FSAR, "Dynamic Sys Analysis of RC8, Reactor Internals, ECCS Piping & Control Element Drive Mechanism Under Faulted Conditions"

 * Bouthern California Edison Co 84/01/31 35pp 22461 090 24X Fiche 50-361, 84/02/10, 8402170338
- --8402170402 App 3 9B to 8an Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR. "Reactor Vessel Thermal Shock Considerations for Small Break LOCAs "

 * Southern California Edison Co 84/01/31 2pp 22461 126 24X
 - Fiche 50-361, 84/02/10, 8402170338
- --8402170403 App 2 5J to San Gnofre Nuclear Generating Station.Units 2 & 3 updated FSAR, "Analysis of Post-1975 Earthquake Activity " # Southern California Edison Co 84/01/31 16pp 22456 143 24% Fiche.50-361.84/02/10,8402170338.
- --840217040A App 15D to 8an Onofre Nuclear Generating Station, Units 2 & 3 updated FBAR, "Responses to IE Bulletins 79-27 & 80-0A.IE Info Notice 79-22 & Multiple Control Sys Failure Evaluation."
 - mvasuation." * Southern California Edison Co 84/01/31 28pp, 22475 334 24X Ficha 50-361.84/02/10.8402170338
- --8402170407 App 2 5% to San Onofre Nuclear Generating Station, Units 2 & 3 udated FSAR. "Extent of Rose Canyon Fault Zone" # Southern California Edison Co 84/01/31 7pp 22456 160 24% Fiche 50-361, 84/02/10, 8402170398
- --8402170408 App 3 10A to Ban Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR, "Criteria for Beismic Qualification of Beismic Category I Equipment" # Southern California Edison Co. 64/01/31 16pp 22461:133 24X Fiche: 50-361.84/02/10.8402170338
- ---B402170409 App 15E to San Onofre Nuclear Generating Station, Units 2 & 3 updated FBAR, "Mathodologies Used in Analyses of Large Steam Line Breaks & Feedwater Line Breaks "

 * Southern California Edison Co. 84/01/31. 57pp 22476.001
 24X Fiche.50-361,84/02/10,8402170338
- --B402170411 App 3 108 to San Önofre Nuclear Generating Station,Units 2 & 3 updated FSAR, "Results of Seismic Tests & Analyses Beismic Category I Instrumentation & Electrical Equipment" # Bouthern California Edison Co. B4/01/31 17pp 22461,130 24X Fichs 50-361,84/02/10,8402170338
- --8402170412 Chapter 16 to Ban Onofre Nuclear Generating Station. Units 2 & 3 updated FBAR. "Tech Specs" # Bouthern California Edison Co. 84/01/31 ip 22476:058 24X Fiche. 80-361, 84/02/10, 8402170338.
- --8402170413 App 3A to San Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR, "Comparison of Design W/NRC Reg Guides " # Southern California Edison Co 84/01/31 57pp 22461:223 24X Fiche 50-361;84/02/10,8402170338
- --8402170414 App 2.5L to 8an Onofre Nuclear Generating Station.Units 2 & 3 updated FSAR, "Baja & CA Continental Border Faults." # Southern California Edison Co. 84/01/31. 41pp 22456:167 24X Fichs: 50-361:84/02/10,8402170338
- --8402170415 Chapter 17 to San Onofre Nuclear Generating Station, Units 2 & 3 updated FBAR, "GA " # Southern California Edison Co 84/01/31 20pp 22476:059 24X Fiche: 50-361; 84/02/10, 8402170338.
- --8402170416 App 38 to San Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR, "Functional Evaluation of Components of Sys Shared by Two Units."

 * Southern California Edison Co 84/01/31, lipp 22461:280 24X Fiche: 50-361, 84/02/10, 8402170338.
- Analusis " musayeas " * Bouthern California Edison Co. 84/01/31. 150pp 22461.291 24X Fiche 30-361,84/02/10,8402170338.

- --8402170417 App 2 5M to San Onofre Nuclear Generating Station, Units 2 % 3 updated FSAR, "Hypothesized Offshore Zone of Deformation" # Southern California Edison Co 84/01/31 10pp 22456 208 24X Fiche 50-361,84/02/10,8402170338
- --8402170420 App 2 9N to Ban Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR (no title)

 * Southern California Edison Co 84/01/31 18pp 22456 218
 24X Fiche 50-361.84/02/10.8402170338
- --8402170421 Chapter 4 to San Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR. "Reactor"

 # Sputhern California Edison Co 84/01/31 200pp \$2462 104
 24% Fiche 50-361.84/02/10.8402170338
- --8402170422 App 2 50 to San Onofre Nuclear Generating Station.Units 2 & 3 updated FSAR. "Faults W/Quarternary Movement Within 25 Miles of San Onofre" * Southern California Edison Co 84/01/31 2pp 22456 236 24X Fiche 50-361,84/02/10,8402170338
- -8402170423 Chapter 5 to San Onofre Nuclear Generating Station, Units 2 & 3 updated FBAR. "RCS & Connected Sys "

 * Southern California Edison Co 84/01/31 350pp 22463 081 24% Fiche 50-361.84/02/10,8402170338
- --9402170424 App 2 5P to San Onofre Nuclear Generating Station,Units 2 & 3 updated FBAR, "Coronado Banks & Palo Verde Faults " * Bouthern California Edison Co 84/01/31 4pp 22456 238 24X Fiche 50-361,84/02/10.8402170338
- --8402170426 App 5.2A to San Onofre Nuclear Generating Station,Units 2 5 3 updated FBAR, "Overpressure Protection for C-E 3,410 MHt Pressurized Reactors" * Bouthern California Edison Co 84/01/31 150pp 22463 334 24X Fiche 50-361.84/02/10,8402170338
- --B402170427 App 2 50 to San Onofre Nuclear Generating Station,Units 2 & 3 updated FSAR, "Rose Canyon & Cristianitos Fault Zones " W/one dversize figure Aperture card is available in FDR * Bouthern California Edison Co 84/01/31 28pp 22456.242 24X Fiche 50-361.84/02/10.8402170338
- --8402170432 App 2 5R to San Onofre Nuclear Generating Station, Units 2 & 3 updated FSAR, "Evaluation of Max Earthquake on Hypothesized Offshore Zone of Deformation"

 ** Bouthern California Edison Co 84/01/31 31pp 22456 271 24X Fiche 50-361,84/02/10,8402170338
- ---8402170436 App 6 2A to Ben Unofre Nuclear Generating Station, Units 2 & 3 updated FSAR, "Local Leak Rate Testing " * Southern California Edison Co 84/01/31 50pp 22465 311 24X Fiche 50-361,84/02/10.8402170338
- --8402170437 App 2 5T to San Onofre Nuclear Generating Station, Units 2 & 3 updated FBAR, "Ground Hotion Analysis"
 * Bouthern California Edison Co 84/01/31 12pp 22456, 343 24X Fiche 50-361,84/02/10,8402170338
- --8402170441 App 6 28 to San Onofre Nuclear Generating Station, Units 2 & 3 updated FBAR, "Containment Atmosphere Mass Releases Through Minipurge Sys Following LOCA"

 * Bouthern California Edison Co 84/01/31 150pp 22466 007

 24X Fiche 50-361,84/02/10,8402170338
- --B402170442 Chapter 7 to Ban Unofre Nuclear Generating Station, Units 2 & 3 updated FBAR. "Instrument & Controls " W/one oversize figure Aparture card available in PDR " > Bouthern Callfornia Edison Co B4/01/31 400pp 22466 234 24X Fiche 50-361,84/02/10,8402170338
- -8402170446 Chapter 8 to Ban Onofre Nuclear Generating Station, Units 2 & 3 updated FBAR, "Electric Power."

 # Bouthern California Edison Co 84/01/31 125pp 22468 117
 24X Fiche 30-361 84/02/10 8402170338
- -8402170450 App B RA to Ban Onofre Nuclear Generating Station,Units 2 & B updated FBAR, "Bulk Power Transmission Sys Reliability Criteria " W/two oversize figures Aperture cards available ** Bauthern California Edison Co 84/01/31 100pp, 22448 158 24X Fiche: 50-361,84/02/10,8402170338

- P Operating license stage documents & correspondence
- 8312120029 Generic Ltr 83-39 to representatives of utils re voluntary survey of licensed operators Svx list encl EISENHUT,D G Division of Licensing 83/12/08 Communuealth Edison Co 12pp 22313 006 24X Fiche 50-000.83/12/08.8312120029
- B402030441 Responds to B3111B ltr Continued transmittal of correspondence re facilities requested HHARTON.R J Hharton. R J B3/12/15 KNIGHTON.G W Licensing Branch 3 1p 22065 003 24X Fiche 50-361-83/12/15,8402030441
- 8401030275 Forwards response to T Chandrasekaran comments on process control program.w/Rev 0 to Health Physics Procedure SD23-VII-8 5 1, "Process Control Program for San Dnofre Units 2 & 3"
 MEDFORD,M D Southern California Edison Co 83/12/29
 KNIGHTON,G W Licensing Branch 3 6pp 21680 174 24X
 Ficha 50-361.83/12/29.8401030275
- --B401030277 Rev 0 to Health Physics Procedure 8023-VII-8 5 1, "Process Control Program for Sam Onofre Units 2 & 3 " KNAPP.P J Southern California Edison Co B3/10/20 46pp. 21680 180 24% Fiche 50-361,83/12/29,8401030275
- 8402190408 Forwards notice of consideration of issuance of amend to Licenses NPF-10 & NPF-13 & preposed NSHC determination & opportunity for hearing on 840103 request re number of hours per yr containment purge sys may be in operation ROOD, H Licensing Branch 3 84/01/30 BASKIN.K P. Bouthern California Edison Co HOLCOMBE.J C Ban Diego Gas & Electric Co 3pp 22263 351 24X Fiche 50-261.84/01/30.8402150408
- --8402130412 Notice of consideration of issuance of amends to Licenses NPF-10 & NPF-15 & proposed NSHC determination & opportunity for hearing KNIQHTON, 6 W Licensing Branch 3 84/01/30 7pp 22263 354 24% Fiche 50-361,84/01/30,8402150408
- 8402010410 Generic Ltr 84-04 to all operating PNR licensess, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/plimination of postulated pipe breaks in PNR primary main loops Svc list encl EISENHUT, D G Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc. 59pp 22177 087 24X Fiche 50-000,84/02/01,8402010410
- 8402060248 Suppl to 840125 application for Amends 23 & 9 to Licenses NPF-10 & NPF-15, respectively Affidavit re distribution of amend application encl NANDY, FR Southern California Edison Co 84/02/02 MNIGHTON, G W Licensing Branch 3 App 22097 197 24X Fiche 50-361, 84/02/02, 8402060248
- 402150383 Responds to Generic Ltr 84-01 re terms important to safety & safety-related As member of util safety classification group, supports further discussion on issue Ltr dtd 840126 sent requesting meeting HEDFORD.H O Southern California Edison Co 82/02/06 TAYLOR, J M Director's Diffice. Diffice of Inspection and Enforcement. 1p 22242 088 24X Fichs 50-206, 84/02/06, 8402150383
- 8402130350 Ack receipt of 840115 rept describing status of util efforts to locate items contaminated w/low levels of radioactive matl Conclusions reasonable HENSLAMBRIJF A Region 5, Office of Director MCCARTHY, CB Southern California Edison Co ip 22203-300 24x Fichs 50-206.84702707.8402130350.
- 8402210103 Discusses 840103 & 25 Tech Spec Change requests to increase use of 8-inch containment purge sys.NRC approval restricted to end of core life Justification of permanent increase in purge limit being developed MEDFORD, M O Southern California Edison Co 84/02/14 KNIGHTON, 0 W Licensing Branch 3 2pp 22317 236 24X Fichs 50-361,84/02/16,8402210103
- O Inspection reports, 1E Bulletins & correspondence
- B312120153 IE Info Notice 84-06, "Steem Binding of Auxiliary Feedwater Pumps" Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche, 50-000, B4/01/25, B312120153
- 8402030R63 Ack receipt of 840106 ltr informing NRC of stops taken to correct violations noted in IE Insp Repts 50-206/83-21, 50-361/83-33 & 50-362/83-31
 818H0F,T W Region 5, Office of Director 84/01/31, McCARTHY,C.B Southern California Edison Co ip 22069 325 24X
 Fichs 50-206/84/01/31,8402030R63

- --B402030271 Responds to NRC 831208 ltr re violations noted in IE Insp Repts 50-206/83-21,50-361/83-33 & 50-362/83-31 Corrective actions simulater training for operators modified to include plant situations requiring prompt action BASKIN.K P Southern California Edison Co 84/01/06 BEYDUNG.R C. Director's Office, Office of Inspection and Enforcement 9pp 22069 326 24X Fichs 50-206,84/01/31, 8402030263
- 8402140124 Forwards IE Insp Repts 30-206/84-01.50-361/84-01 & 50-362/84-01 on 840109-12 No noncompliance noted BIBHOP.T W Division of Resident, Reactor Project & Engineering Programs 84/01/31 DABKIN, K B Southern California Edison Co 2pp 22218 233 24X Fithe 50-206,84/01/31,8402140124
- --8402140139 IE Insp Repts 50-206/84-01.50-361/84-01 & 50-362/84-01 on B40109-12 No noncompliance noted Major areas inspected fire protection computer systreactor coolant pump oil collection sys & LERS SCOMN.K M , MOLLENBACH.D F , CANTER.H L. Region 5, Office of Director B4/01/31 Ppp 22218.235 24X Fiche 50-206.84/01/31, 8402140124
- 8401190014 IE Info Notice 84-07, "Design-Basis Threat & Review of Vohicular Excess Controls " Svc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co. of New York, Inc. 119pp 22114 179 24X Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl BEYDUNG.R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc. 102pp 22177-156 24X Fiche 50-000-84/02/03,8401190017
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Inspa of Fire Protection Safe Shutdown Sys (10CFR50, App R) " Syc list snc!

 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365-259, 24X Fichs 30-000,84/02/13,8401190041
- 840119039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '"
 Svc list encl.
 JURDAN,E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/14 Consolidated Edison Co. of New
 York, Inc. 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- 8401190045 IE Info Notice 83-65, Suppl 1: "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366 142 24X Fiche, 50-000, 84/02/15, 8401190045
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Byc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co. of New York, Inc 114pp 22366 024 24X Fiche 50-000.84/02/21.8401190062
- 8402220545 Discusses IE Safeguerds Insp Repts 50-204/84-03.50-361/84-04 & 30-362/84-04 on 840424-26 No violations noted Major areas inspected. selective eram of procedures & records & interviews w/personnel. Insp repts withheld (ref 100FR2 790) NORDERHAUG. R Region 5. Office of Director 84/02/22. BABKIN & B. Bouthern California Edison Co. 2pp. 22333 336, 24X Fiche 50-206.84/02/22.8402220345
- 8402280245 Forwards corrected Page 2 to IE insp rept dtd 840207, For replacement Info describes power ascension transient testing & Unit 3 plant trips.
 BISHOP, T W. Division of Resident, Reactor Project & Engineering Programs 84/02/23 BASKIN, K. P. Bouthern California Edison Co. 2pp. 22397-276. 24X Fiche 50-206.84/02/23,8402280245
- 8401190066 IE Info Notice 84-11. "Training Program Deficiencies."
 Svc list encl.
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/24 Consolidated Edison Co. of New
 York. Inc. 115pp. 22430:304. 24X Fiche:50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Spat Valve Seals" Byc list encl.
 JURDBAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/27 Consolidated Edison Co. of New York. Inc. 120pp 22431:060. 24X Fiche:50-000,84/02/27,8401190067

- 8 Reportable occurrences. LERs & related correspondence
- 8402080029 Responds to FOIA request for documents re facility hot functional testing problems, including broken thermowells, labse & broken reactor coolant pump parts & loose thermal siseves.Forwards App A documents Documents also in PDR FELTON, J M Division of Rules and Records 83/11/16 OARDE, B Covernment Accountability Project 3pp 22170 253 24X Fichs.50-000.83/11/16,8402080029
- --8402080036 List of hot functional testing exceptions Related info encl # Affiliation Not Assigned 83/11/16 19pp 22170 256 24x Fiche: 50-000, 83/11/16, 8402080029
- 8401040360 LER 83-103/03L-0 on 831119, both main feedwater pumps 901040360 LER 83-103/03L-0 on 831117-both main feedwater putripped due to low suction pressure Caused by high water demand placed on condensate storage tank 3T-121 Tech Spec proposed re min level requirements W/83127 ltr HAYNES-J O. Bouthern California Edison Co 83/12/19 M/Regian 3. Office of Director. 3pp 21706 132 24X Fiche 80-362,83712/19.8401040360 MARTIN-J B
- 8402030420 RO listed fire doors found inoperable during Dec surveillances Caused by incorrect design Design change packages being implemented to update door latches & closure machanisms. HAVNER, J. O Southern California Edison Co 84/01/18 MARTIN, J B Ragion 5, Office of Director App. 22068 283 24X Fichs. 50-361.84/01/18.8402030420
- 8402030398 Revised LER 83-097/03L-1. on 831029 & 30, control element assembly (CEA) 57 dropped more than 19 inches & CEA 61 dropped more than 19 inches on 831101 Caused by sluggishness of CEA grippers W/840120 itr.
 HAYNES, J. Q Bouthern California Edison Co 84/01/20 MARTIN, J Region 5, 0fice of Director 3pp 22049 001 24X
 Fiche: 50-342,84/01/20:8402030398. 84/01/20 MARTIN, J B
- 8402130440 LER 83-i19/03L-0. on 831227, core protection calculator channel A feiled Caused by multipurpose acquisition & control sys Error Code 10 No corrective action taken since failure espected to occur occasionally HAYNES, J. 2 Sauthern California Edison Co 84/01/24 MARTIN, J B Region 5, Office of Director, 4pp 22202 096, 24% Fichs, 50-362, 84/01/24, 8402130440
- 8402130509 LER 83-118/03L-0, on 831229. DNBR outside allowable limits Caused by core operating limit supervisory sys being out of svc. 8µs returned to svc. W/840124 ltr
 HAYNES, J. 9. Bouthern California Edison Co 84/01/24 MARTIN, B. Region 5. Office of Director. 4pp 22201 197. 24X
 Fiche 50-362.64/01/24.8402130509
- B402130333 RD re fire protection cable separation criteria. Intent of License Condition 2, 0 discussed w/NRR & util submitted request for license amend to revise reporting requirements HAYNES, J. 9. Southern California Edison Co. 84/01/26. MARTIN, J.B. Region B. Office of Director. 2pp. 22197, 265. 24X Fiche 50-361,84/01/26,8402130333.
- 8402130279 LER 83-116/13X-0 on 831230, during reactor trip breaker (RYB) surveillance testing, undervoltage trip device of RTB 7 exhibited procedurally unacceptable response time Trip device removed from svc. Cause not determined W/840130 ltr. HAVNES, J 0. Southern California Edison Co 84/01/30, MARTIN, J. B Region 5, Office of Director. 3pp 22202, 127. 24X Fiche: 50-362, 84/01/30, 8402130297
- 8402050361 LER 84-001-00 on 840101.precautionary penetration & radwasts bldgs evacuation initiated when Units 2 & 3 area radiation monitors & plant vant stack monitors alarmed, Caused by routine draining of weste gas header line W/840131 ltr HAYNES, J. 9 Bouthern California Edison Co 84/01/31. 4pp 22085:120. 24x Fiche: 50-362,84/01/31.8402060361
- B402150218 LER B3-091/01X-1. on B31017, 28 & 31, undervoltage armatures for reactor trip breakers 5 & 8 found not to be fully picked up Caused by interference between armature & copper shading ring around coil core. Adjustments required. W/840131 itr. HAYNES, J 9 Bouthern California Edison Co. 84/01/31. MARTIN, J. B Region 5, 0ffice of Director. App 22244: 139. 24X Fiche. 50-362,84/01/31,8402150218.
- 8402030459 LER 83-111/03L-0; on 831222, RGB specific activity exceeded NUROSCORPY LER 83-111/03L-0; on BS1222, RGB specific activiti.
 1.0 mci/g dose equivalent I-131. Gaused by iodine spiking following power changes associated w/two reactor trips. Purification flow increased, W/040123 ltr. HAYNES, J. C. Bouthern California Edison Co. 84/01/23 / Region 5, Office of Director. 9pp 22049.059, 24X Fiche: 50-362,84/02/03,8402030459 MARTIN, J B

- 8402150396 Recommends that licensee be requested to appraise NRC of current situation at plant to determine cause of higher incidence of fuel failures Changes to startup or power ascension program plan not recommended RUBENSTEIN L S Assistant Director for Core & Plant Systems 84/02/03 NOVAK, T M Assistant Director for Licensing 2pp 22263:361 24X Fiche 50-362,84/02/03,8402150396
- 8402130166 LER 84-005-00 on 840106 following reactor trip for testing, RCB sample analysis indicated that RCB specific activity succeeded 1 0 uCi/g dose equivalent Cause indicative of iodine spiking following power change W/840206 ltr HAYNES, J G Southern California Edison Co 84/02/06 App 22204 112 24X Fiche 50-362,84/02/06,8402130166
- 8402i30169 LER 84-002-00 on 840107.penetration bldg airborne iodine of noble gas concentrations increased above precautionary level Cause under investigation Engineering evaluation will determine corrective actions W/840206 ltr
 HAYNES, J G Bouthern California Edison Co 84/02/06 3pp 22201.134 24X Fiche 80-362.84/02/06.8402130169
- 8402140163 LER 84-003-00 on 840107 while in Mode 3 at zero power, during planned reactor shutdown, control element assembly (CEA) 64 slipped 30 inches Caused by sluggish operation of CEA drive mechanism Vendor requested to review event W/840206 ltr HAYNEB, J G. Bauthern Callfornia Edison Co 84/02/06 3pp 22219 316 24X Fiche 50-362,84/02/06,8402140163
- 8402220530 Part 21 rept re defective DSR & DSRV standby diesel generator turbocharger thrust bearing lubrication Deficiency not corrected by sys med New recommendation will be sent to customers by 840330

 BOYER.R E Transamerica Delaval, Inc 84/02/15 Directed Defice, Office of Inspection and Enforcement Spp 22332 in Fiche 50-000,84/02/15,8402220530
- B40R2302ii PNO-V-84-009 on B40215, limited number of workers treated following inhalation of fumes from unknown substance Cause believed to be tear gas from Marine Corps training activities Emergency drill interrupted CARTER, H. L. Region 5, Office of Director B4/02/15 ip 22361 106 24X Fiche, 50-362, 84/02/15, 8402230211

DOCKET 50-364 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 2

- A. Application/construction stage documents & correspondence
- 8402090903 Responds to FOIA request for const completion dates for NULL PARTIES CUPTERTLY Under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A,8 & C documents
 FELTON, J M. Division of Rules and Records B3/10/31
 ROBENBAUN, D M Technical Analysis Corp 19pp 22173 292. 24X
 Fiche, 30-000,83/10/31,8402090003
- --7908160043 Discusses 790612 meeting woutil re estimated const completion date Targeting for May 1980 but author suggests late 1980 as possible date Critical areas are electrical work & hangers KART,8 M Office of Management and Program Analysis 79/06/29 VASSALLO, D B Division of Project Management 2pp 22194 294 24X Fiche, 50-000, 83/10/31, 8402090003
- F. Becurity, medical, emergency & fire protection plans
- 8402010327 Grants examption from certain requirements of App R. Bection III. Q. 2 to 10CFR50. Existing protection for containment bldg areas provides equivalent level of protection VARQA.8. A Operating Reactors Branch 1 83/12/30 CLAYTON.F. L. Alabama Pawer Co 5pp 22059 290. 24X Fiche. 50-348, 83/12/30,
- --8402010336 Examption from requirements of App R.Section III 0 2 to 10CFR50 re fire protection of safe shutdown cables & equipment located inside containment blog EIBENHUT, D 9 Division of Licensing 83/12/30, Alabama Power Co. 4pp. 22059:276 24X Fichs 50-348,83/12/30,8402010327.
- --8402010409 Safety evaluation supporting exemption from 100FR50, App R respectfic fire protection measures for protection of safe shutdown cables & equipment located inside containment bldg. * Office of Nuclear Reactor Regulation, Director. 83/12/30. App 22059 300. 24X Fiche: 50~348,83/12/30,8402010327.
- 8402140159 Forwards IE Insp Repts 50-348/83-32 & 50-364/83-30 on 831212-16 No violations or deviations identified VERRELLIJD M. Division of Project & Resident Programs 84/01. MCDUNALD.R.F. Alabama Power Co. 2pp. 22219,264 24X Fiche: 50-348,84/01/12,8402140159 84/01/12

- --B402140165 IE Insp Repts 50-348/83-32 & 50-364/83-30 on B31212-16 No violations or deviations noted Major areas inspected radioactive mat! shipping: low level radwasts storage bidg, effluent monitoring & health physics operations DEBS, B % Region 2, Office of Director B4/01/10 6pp 22219 266 24% Fiche 50-348,84/01/12,8402140159
- 8402030302 Revs to Emergency Plan Implementing Procedures FNP-O-EIP-26, "OPfsite Notification," FNP-O-EIP-19, "General Emergency" & FNP-O-EIP-7, "Radiation Exposure Estimation & Classification of Emergencies "Transmittal & receipt form encl # Alabama Power Co 84/01/27 142pp 22066 094 24X Fiche 50-345.84/01/27,8402030382
- 8402140307 Forwards summary of 840112 meeting w/util. Southern Svcs Co & Bechtel in Region II oft re application of 100FRSO 48 & 100FRSO App R fire protection at facilities LEWIS,R C Division of Project & Resident Programs 84/01/27 MCDONALD.R P Alabama Power Co 4pp 22228 252 24X Fiche 50-348,84/01/27,8402140307
- 8402030379 Rev O to Procedure GO-EIP-120: "Ref Ouidance for Recovery Manager" W/840130 Itr MUDD: C H Alabama Power Co 84/01/30 14pp 22068 347 24X Fiche 50-348.84/01/30.8402030399
- 8402030406 Rev 3 to procedure 90-EIP-114, "News Release Coordination & Distribution " W/840130 ltr.
 MUDD.C H Alabama Power Co 84/01/30 lipp 22068 324 24X
 Fiche 50-348,84/01/30.8402030406
- 8402090080 Revs to Emergency Implementing Procedures FNP-0-EIP-009. "Rediation Exposure Estimation & Classification of Emergencies" & FNP-0-EIP-019. "General Emergency " W/840202 ltr & 840201 transmittel & receipt form HVD8#ETH.JB Alabama Power Co 84/02/02 MCKN19HT.J Record Services Branch (Document Control Desk) 9cp 22163 315 24X Fiche 50-348.84/02/02.8402090080
 - 321300i5 Requests extension of 2 Wks to provide final response to 3actions 2 2 1 & 3 2 of Generic Ltr 83-20 per 831104 preliminary response, due to activities associated w/upcoming Unit i refueling outage & Suppl 1 to NURES-0737 CLAYTON.F.L. Alabama Power Co. 84/02/06 VARGA,8 A. Office of Nuclear Reactor Regulation, Director 1p 22204 086 24X Fiche 50-348,84/02/06.8402:30015
- 8402130142 Temporary change notice for Rev 5 to Emergency Plan Implementing Procedure 90-EIP-111, "Corporate Activation & Notification Procedure " NUDD, C.H. Alabama Power Co. 84/02/07 9pp 22250.022 24X Fiche. 50-348, 84/02/07, 8402150142
- 8402170023 Forwards Amends 42 & 33 to Litenses NPF-2 & NPF-8, respectively & safety evaluation Amends correct two tables listing fire hose stations & sprinklers for Unit 2 & delete during shutdown" from surveillance test for both units EEVEB.E A Degrating Reactors Branch 1 B4/02/07 CLAYTON.F.L labama Power Co 5pp 22312 313 24X Fiche 50-348,84/02/09, 40917093
 - 8402170026 Amends 42 & 33 to Licenses NPF-2 & NPF-8, respectively, correcting two tables listing fire bose stations & sprinklers for Unit 2 & deleting "during shutdown" from surveillence test for both units VAROA.8 A Operating Reactors Branch 1 84/02/07 10pp 22312 318 24% Fiche 50-348,84/02/07,8402170023
- |402170326 Lists possible exemptions to NRC interpretations of iOCFR50: App R (Generic Ltr 83-33).per 840112 meeting, including automatic sprinkler protection, 20-ft safe shutdown cable separation criteria & small component protection CLAYION, F L. Alabama Power Co 84/02/10 EIEENHUT, D Q Office of Nuclear Reactor Regulation, Director 2pp. 22277 110 24X Fiche 50-348,84/02/10,8402170326
- 402160461 Clarifies 840210 response to Guestion 471 1 for 10CFR20, App A Footnote (c) exemption request re indine filter respiratory protection Reactor vessel head venting inaccurately referred to as normal shutdown evalution. CLAYTON.F L Alabama Power Co 84/02/13 VAROA, 8 A Office of Nuclear Reactor Regulation, Director 2pp 22276 361. 24X Fiche 50-248, 84/02/13, 8402160461.
- 102240258 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per 810707 Generic Ltr 81-27 W/o request.entire plan will be placed in PDR REEVES.E A Operating Reactors Branch 1 84/02/14 CLAYTON.F L Alabama Power Co. 2pp 22381:269 24X Fiche 50-348,84/02/14.

- 8402290344 Respands to fee requirements of 10CFR170 relation pertaining to fire protection requirements of 10CFR30 Fee required for 810319 & 830520 exemption requests from requirements of 10CFR30 MILLER, W O License Fee Management Branch 84/02/21 CLAYTON, F L Alabama Power Co. 3pp 22437 358 24X Fichs 50-348, 84/02/21, 8402290344
- P Operating license stage documents & correspondence
- B312120027 Generic Ltr B3-37 to representatives of utils re voluntary survey of licensed operators Svc list encl EIBENHUT.D 0 Division of Licensing 03/12/08 Commonwealth Edison Co 12pp 22313 Ooá 24X Fiche 50-000.83/12/08.8312120027
- 8402070071 Forwards revised SER & FR notice granting relief from ASHE Section XI requirements for inservice testing program for pumps & valves.

 VARQA, S A Operating Reactors Branch 1 84/01/26 CLAYTON, F L Alabama Power Co 2pp 22189 179 24X Fiche 50-348, 84/01/26, 8402070071
- --8402070078 Notice of granting relief from ASME Section XI inservice testing requirements for pumps & valves VAROA.8 A Operating Reactors Branch 1 84/01/26 2pp. 22187 181. 22X Fiche 50-348,64/01/26,8402070071
- --8402070083 Revised SER granting relief from ASME Section XI inservice testing requirements for pumps & valves + Office of Nuclear Reactor Regulation, Director 84/01/26 7pp 22187-183 24X Fichs 30-348.84/01/26,8402090071
- B402030196 Application for amend to Licenses NPF-2 & NPF-8 revising float voltage surveillance requirement to 2 02 & 2 07 volts Addl info re connector resistance for svc water blog batteries & auxiliary blog dc distribution limits submitted CLAYTON, F L Alabama Power Co 84/01/27 VAR9A, S A Office of Nuclear Reactor Regulation, Director 4pp 22047-348 24% Fiche 50-348,84/01/27,8402030194
- B402100393 Forwards Amends 41 & 32 to Licenses NPF-2 & NPF-B, respectively & safety evaluation Amends change Tech Bpecs re-turbine valve testing & modify existing surveillance requirements for turbine overspeed protection sys.

 REEVEB, E. A. Operating Reactors Branch 1. 84/01/27 CLAYTON; F. Alabama Power Co. 6pp. 22211 333 24X Fiche 50-348,84/01/27, 8402100393
- --8402100397 Amends 41 & 32 to Licenses NPF-2 & NPF-8, respectively, changing Tech Space re turbine valve testing & modifying existing surveillance requirments for turbine overspeed protection sys VAROA. 8 A. Operating Reactors Branch 1 84/01/27 10pp 22211 337 24X Fichs 50-348,84/01/27,8402100393
- --8402100401 Safety evaluation supporting Amends 41 & 32 to Licenses NPF-2 & NPF-8, respectively. * Office of Nuclear Reactor Regulation, Director 84/01/27 App 22211:349, 24X Fiche 50-348.84/01/27,8402100393.
- 840B030417 Forwards Page 3 of Rsv 4 to Administrative Procedurs FNP-0-EIP-17 Page inadvertently omitted from original gracedure HUDBPETH.J B Alebama Power Co. 84/01/30 MCKNIGHT.J. Document Management Branch 3pp 22068 289. 24X Fichs. 50-348,84/01/30, 8402030419
- 8402010410 Generic Ltr 84-04 to all operating PWR licensess.CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops 8vc list encl EISENHUT.D.9 Division of Licensing 84/02/01. Consolidated Edison Co of New York, Inc. 89pp. 22177.087. 24X Fiche 50-000.84/02/01.8402010410
- 8402140342 Application for amend to Licenses NPF-2 & NPF-8, incorporating NRC suggested Tech Spec changes contained in Gameric Ltr 83-43 re reporting requirements of 10CFR30, 72 & 10CFR30, 73, GLAYTON, F L. Alabama Power Cp. 84/02/03 VAROA, 8 A. Office of Nuclear Reactor Regulation, Director, 5pp. 22228 194, 24X Fiche 50-348,84/02/03,8402140342

- --8402140347 Proposed Tech Specs revising administrative control & definitions sections incorporating regulation changes.per Qeneric Ltr B3-43 # Alabama Power Co. 84/02/03 29pp 22228 199 24X Ficha 50-348,84/02/03,8402140342
- 8402170079 Forwards request for add1 info re 830113 request for exemption from 10CFR20, "Protection Factors for Respirators." allowing credit for radiofodine protection factor while employing MSA 466220 GMR-I canister VARGA. S A Operating Reactors Branch 1 84/02/08 CLAYTON, F L Alabama Power Co Spp 22312 342 24X Fiche 50-348,84/02/08,
- B402170023 Forwards Amends 42 & 33 to Licenses NPF-2 & NPF-8, respectively & safety evaluation Amends correct two tables listing fire hose stations & sprinklers for Unit 2 & delete "during shutdown" from surveillance test for both units REEVES.E.A Operating Reactors Branch 1 84/02/09 CLAYTON,F L Alabama Power Co Spp. 22312 313 24X Fiche 50-348.84/02/09, B402170023
- ---B402170026 Amends 42 & 33 to Licenses NPF-2 & NPF-8, respectively, correcting two tables listing fire hose stations & sprinklers for Unit 2 & deleting "during shutdown" from surveillance test for both units.

 VARCA, 8. A. Operating Reactors Branch 1 84/02/09 10pp 22312,318 24% Fiche 50-348,84/02/09,8402170023
- B402140152 Forwards response to Radiological Assessment Branch 840208 request for add1 info re 840113 application for exemption from 100FR20.App A concerning indine filter respiratory protection.

 CLAYTON.F L. Alabama Power Co. 84/02/10. VARGA.S.A. Office of Nuclear Reactor Regulation. Director 8pp. 22230 094 24X Fichs: 50-348.84/02/10.8402140152
- 8402160088 Application for amend to License NPF-8, changing Tech Space re RCS pressure & temp requirements.
 CLAYTON.F.L. Alabama Power Co. 84/02/10 VAROA.B A Office of Nuclear Reactor Regulation. Director 2pp 22275.187. 24X Fiche: 30-364.84/02/10.8402160088.
- --8402160092 Proposed Tech Specs re RCS pressure & temp requirements * Alabama Power Co. 84/02/10. 6pp 22276 189 24X Fiche: 50-364, 84/02/10, 8402160088
- 8402170243 "Alabama Power Co JM Farlay Nuclear Plant Unit 2. Cycle 3 Startup Test Rept " W/840210 ltr CLAYTON.F.L. Alabama Power Co 84/02/10 VAROA.8 A Office of Nuclear Reactor Regulation. Director 23pp 22277.050. 24X Fiche: 50-364, 84/02/10, 8402170243.
- 8402220487 Responds to Generic Ltr 83-35 & NUREG-0737, Items II.K 3 30 & II.K. 3.31 re small break LCCA enalysis Westinghouse Gwnere Group program will demonstrate that MOTRUMP predicts lower tamps than MTLASH CLAYTON, F.L. Alabama Power Co 84/02/10, VAROA, 8 A Office of Nuclear Reactor Regulation, Director. 2pp 22340 066, 24X Fiche 50-348,84/02/10,8402220487
- 8402210278 Forwards final response to Generic Ltr 83-28 re NRC position on Salem ATMS events, per 831104 ltr. Development & control of info handling sys used to identify safety-related components & subcomponents described CLAYTON, F.L. Alabama Power Co. 84/02/15 VAROA, S.A. Office of Nuclear Reactor Regulation, Director. 8pp. 22315 204, 24X Fiche 50-348,84/02/15,8402210298
- 8402220331 Responds to 831215 request for add1 info re position on two of 11 NARE0-0737. Item II.B.3 criteria.Licensee should provide procedure to estimate extent of core damage based on radionuclide concentrations CLAYTON, F.L. Alabama Power Co. 84/02/17 VAR9A, 8.A. Office of Nuclear Reactor Regulation. Director 4pp 22336:225 24X Fichs: 50-348,84/02/17,8402220331.
- 8402220011 Application for amend to Licenses NPF-2 & NPF-8, revising Tech Spec to rod control sus Detailed description & Justification for proposed change & Class III & I amend fees ancl.

 GLAYTON F.L. Alabama Power Co. 84/02/17. VAR9A, 8.A. Office of Nuclear Reactor Regulation. Director. 17pp. 2233 317. 24X Fiche: 50-348, 84/02/17, 8402220511.
- --8402220516 Revised proposed Tech Spec changes to rod control sys * Alabema Power Co. 84/02/17, 3pp 22333 333, 24X Fiche: 50-348, 84/02/17, 8402220511.

G Inspection reports, IE Bulletins & correspondence

- 8402140159 Forwards IE Insp Repts 50-348/83-32 & 50-364/83-30 on 831212-14 No violations or deviations identified VERRELLI, D M Division of Project & Resident Programs 84/01/12 MCDONALD, R P. Alabama Power Co 2pp 22219 264 24X Fiche 50-348,84/01/12,8402140159
- --8402140165 IE Insp Repts 50-348/83-32 & 50-364/83-30 on 831212-16 No violations or deviations noted Major areas inspected radioactive math shipping, low level radwaste storage bldg, effluent monitoring & health physics operations DEBS, B T Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 84/01/10 6pp 22217 266 24X Fichs 50-348,84/01/12,8402140159
- 8402140182 Forwards IE Insp Repts 50-348/83-31 & 50-364/83-29 on 831213-16 No violations or deviations noted VERRELLI, D M Division of Project & Resident Programs 84/01/12 MCDDNALD, R P Alabama Power Co 2pp 22223 355 24X Fiche 50-348, 84/01/12, 8402140182
- --8402140183 IE Insp Repts 50-348/83-31 & 50-364/83-29 on 831213-16 No violations noted Major areas inspected electrical & instrumentation preventive & corrective maint activities, maint records & training of maint personnal GIBBONS.T D . MERRIWEATHER: N Region 2. Office of Director CONCON.T E Division of Engineering & Operational Programs 84/01/10 Spp 22223 357. 24% Fichs 50-348,84/01/12,8402140182
- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl UDRDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103). 84/01/25 Consolidated Edison Co of New York
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114,179 24X Fichs 50-000.94/02/03,8401190016
- 8401170017 IE Bulletin 84-01. "Cracks in BWR Mark I Containment Vent Headers." Svc list encl DEYGUNG.R.C Director's Office. Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177
- B401170041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Bys (10CFR50, App R)," Svc list snc1.

 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). B4/02/13 Consolidated Edison Co of New York, Inc. 124pp. 22365 257 24% Fiche 50-000, 84/02/13, 8401190041
- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '"
 Svc list encl
 JDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc. 115pp. 22345 141 24X Fiche 50-000,84/02/14,8401190039
- 8401170045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 630103), B4/02/15 Consolidated Edison Co of New York, Inc 1188p 22366, 142 24X Fiche 50-000, 84/02/15, 8401170045
- B401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches
 Set Below Manufacturer Recommended Value " Svc list encl
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/02/21 Consolidated Edison Co of New
 York, Inc. 116pp. 22366,024. 24X Fiche 50-000,84/02/21,8401190062.
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies."
 Bvc list encl.
 JDRDAN,E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/24 Consolidated Edison Co. of New
 York, Inc. 115pp. 22430-304 24X Fiche 50-000,84/02/24,8401190066.
- 8401190067 IE Info Notice 84-12, "Failure of Boft Seat Valve Seals "
 Byc list encl.
 JORDAN,E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27. Consolidated Edison Co. of New
 York, Inc. 120pp. 22431,060. 24X Fishs 50-000,84/02/27,8401190067
- R. Periodic operating reports & related correspondence
- 8402170087 Monthly operating rept for Jan 1984.W/840210 ltr HAIRSTON.W 9 . CLAYTON.F. L. Alabama Power Co 84/01/31 5pp. 22301.099. 24X Fiche: 30-344.84/01/31.8402170089

- S Reportable occurrences, LERs & related correspondence
- 8402050350 RD on 840112 & 14, plant vent stack effluent monitors R-298, declared inoperable when four of nine datectors failed failed detectors replaced.

 CLAYTON, F L Alabama Power Co 84/01/30 O'REILLY, J P Region 2 Office of Director ip 22085 119 24X Fiche 50-348, 84/01/30, 8402060360
- 8402060433 Forwards LERs 83-096/03L-0.83-067/03L-0.83-068/03L-0 CLAYTON.F.L. Alabama Power Co. 84/01/30 Region 2, Office of Director 1p 22083 040 24X Fiche 50-348.84/01/30,8402060433
- ---8402060442 LEA 83-067/03L-O on 831231, high voltage power supply spiked low Power range monitor N-44 instrumentation channel declared inoperable Cause undetermined Instrumentation channel stabilized HAIRBTON, W Q Alabama Power Co 84/01/30 ip 22083·043 24X Fiche 50-348,84/01/30,8402060433
- --8402060448 LER 83-068/03L-0 on 831230, diesel generator 28 declared inoperable when valve 02P16V336 closed Caused by motor operator drawing excessive current Operator cleaned, design change evaluated & personnel counseled HAIRSTON.W 0 Alabama Power Co 84/01/30 2pp 22083 044 24X Fiche 50-348,84/01/30,8402060433
- 8402060067 Informs that diesel generators declared inoperable on 10 occasions since change approved to Tech Spec 3/4,8 i,re diesel generator operability testing, per NRC 840120 request for info Change decreased frequency of testing & maint CLAYTON,F L Alabams Power Co 84/01/31 VAROA,S A NRC No Detailed Affiliation Given 3pp 22088 227 24X Fiche 50-348,84/01/31.8402060067
- 8402170192 LER 84-001-00 on 840118, reactor tripped Caused by personnel allowing steam generator 28 level to reach hi-hi setpoint while operating feedwater sys manually Personnel counseled re steam generator maint W/840210 ltr
 HAIRSTON,N 9, CLAYTON,F L Alabame Power Co 84/02/10 5pp
 22279 277 24X Fiche 50-364.84/02/10,8402170192
- 8402270262 LER 84-002-00 on 840123, determined that hourly firewatch patrol in train 8 auxiliary bldg battery charger room not performed Causes by personnel error Firewatch patrol immediately performed W/840223 ltr HAIRSTÜN, W G , CLAYTON, F L Alabama Power Co 84/02/23. 3pp 22086 331 24% Fiche 50-364, 84/02/23, 8402270262
- OCKET 50-366 EDWIN : HATCH NUCLEAR PLANT, UNIT 2 Security, medical, emergency & fire protection plans
- 3402140147 Forwards IE Insp Repts 50-321/83-36 & 50-366/83-39 on 831219-22. No violations or deviations noted DANCE: R C Division of Project & Resident Programs, 84/01/17. KELLV:R. J Georgie Power Co Zpp. 22230 078 24X Fiche: 50-321,84/01/17.8402140147
- --8402140154 IE Insp Repts 50-321/83-36 & 50-366/83-39 on 831219-22 No violations or deviations noted Major areas inspected health physics preparation activities re recirculation piping replacement project & followup review of LERs KAHLE, J B Region 2, Office af Director 84/01/13 8pp 22230 080 24X Fiche.50-321,84/01/17,8402140147
- 402010160 Forwards "Evaluation of Georgia Power Co Emergency Pregendness Plan for EI Hatch Electric Generating Plant," final rept KRIMH:R W Federal Emergency Henagement Agency. 84/01/24 JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 22037-223 24X Fiche 50-321.84/01/24.8402010160.
- -8402010165 "Evaluation of Opergia Power Co Emergency Preparedness Plan for EI Hatch Electric Generating Plant," final rept. # Federal Emergency Management Agency, 83/10/28 35pp 22037 225 24X Fiche 50-321.84/01/24.8402010160.
- 102070236 Revised emergency plan implementing procedures, including Procedures HNP-8159 re Victoreen electrometer Model 500, HNP-8160 re Teledose Model 503A telemetry sys & HNP-4852 re offsite dose estimations, H/840201 ltr SORRELL, E.C. Georgia Power Cd. 64/02/01 76pp 22:01 327 24X Fiche: 50-321,84/02/01,8402070236

- 8402080331 Advises that Rev 5 to emergency plan implementing procedure transmittal & receipt form not received Notification of receipt of rev requested

 EWALD.8 C Georgia Power Co 84/02/02 Diffice of Nuclear Reactor Regulation, Director 1p. 22130 320 24X Fiche 50-321,84/02/02, 24002080331
- --8402080334 Rev 5 to emergency plan. App 1 W/840203 transmittal & receipt form PARKER, L. Appling County. GA 83/08/25 2pp 22130 321 24X Fiche 50-321,84/02/02,8402080331
- 8402130492 Rev 18 to Procedure HNP-8006. "Radiation Work Permit" & Rev i to Procedure HNP-8036. "Waste Classification & Manifest Reporting Resin Shipments " W/840202 ltr * Georgia Poder Co. 84/02/02 31pp 22201,356 24X Fiche 50-321,84/02/02,8402130452
- 8402130478 Emergency Implementing Procedure HNP-8143, "Low Vol Air Sampler Model H-809 VI " 4/840208 ltr * Georgia Power Co 84/02/02 9pp 22200.246 24X Fiche 50-321,84/02/02.8402130478
- 8402150249 Ack receipt of 831214 & 840127 ltrs informing NRC of steps taken to correct violations noted in 15 Insp Rept 50-364/83-29 LEMIS, R C Division of Project & Resident Programs 84/02/06. KELLY, R. J Georgia Power Co. 1p 22290 052 24X Fiche: 50-366.84/02/06. 8402190269
- --B402150294 IE Insp Repts 50-366/83-29 & 50-321/83-27 on B30820-0930 Violation identified.improper plant review of relief valve operability procedure resulting in Tech Spec requirements not being implemented CRLENJAK.R.V. HOLMES-RAY.P., ROGGE.J.F. Region 2, Office of Director B3/11/0B, 11pp 22250 060 24X Fiche 50-366/84/02/06.8402150269.
- 8402270419 Revs to amergency procedures, including HNP-4420 & 4430 reunusual event notification; HNP-4892, emergency equipment inventory; HNP-8013, airborne radioactivity concentration determination & HNP-8016, W/840220 ltr. EURRELL, E. C. Georgia Power Co. 84/02/16 76pp 22390*273, 24X Fichs 50-321, 84/02/16, 8402270419
- 8402240055 Transmittal & title page of deleted Rev 2 to Emergency Plan Implementing Procedure HNP-8139, "Sentox II Oxygen/ Combustible Gas Monitor Operation & Calibr." W/840220 ltr. GREENE, T. BORRELL, E. G. Georgia Power Co. 84/02/20 3pp 22373,351. 24X Fiche 50-321,84/02/20,8402240055
- B402290100 Forwards response to MUREO-0737, Buppl 1 & Generic Ltr 82-33 re comparison of existing plant sys or planned improvements who positions of Reg Quide 1, 77, Rev 2 OUCHA.L T Georgia Power Co. B4/02/21 BTOLZ.J.F Operating Reactors Branch.4. 336pp. 22421.088 24X Fiche 50-321,84/02/21,8402290100.
- B402280024 Corrected Page 4 to Rev 15 to Emergency Plan Implementing Procedure HNP-8016 M/840224 1tr & transmittal notice SDRRELL.E.C. Quorgie Power Co. 84/02/24 3pp 22401:121, 24X Fiche, 50-321,84/02/24,8402280024.
- I Financial information
- B402140453 Forwards Annual Financial Rept for 1982 & related financial qualification info.per 740628 application for amend to GPPR-109 & GPPR-109 VAZQUEZ, R. O Municipal Electrical Authority of Georgia 84/02/10 ADENSAM, E. 9 Licensing Branch 4. 4pp 22221 309 24X Fiche 50-000, 84/02/10, 8402140453.
- --8402140459 Annual Financial Rept for 1982 Related financial qualification info encl.

 MANLEY.G.N Municipal Electrical Authority of Georgia. 82/12/31.

 483pp. 2222:313. 24X Fiche: 50-000,84/02/10,8402140453.
- P. Operating license stage documents & correspondence
- 8402030046 Notification of 840207 meeting w/util in Bethesda, MD to discuss util 831024 to 1220 submittals re organization changes & related Tech Spec changes.
 RIVENBARK, Q. W. Operating Reactors Branch 4. 84/01/25. BTOLZ, J F Operating Reactors Branch 4. 22091.085 24X Fichs. 50-321.84/01/25, 8402030046.

- B402090054 Forwards SER & technical evaluation repts re NRC post-implementation audit review of facility plant-unique analysis rept for Mark I containment long-term program Mods acceptable per NUREC-0661
 BTOLZ, J F Operating Reactors Branch 4 84/01/25 BECKMAN, J T Georgia Power Co 3pp 22188 257 24X Fichs 50-321,84/01/25.840290054
- ---8402090069 Bafaty evaluation re Mark I containment long-term program pool dynamic loads review Mods acceptable per NUREQ-0661 * Office of Nuclear Reactor Regulation, Director 84/01/25 2pp 22188, 260 24X Fiche 50-321,84/01/25,8402090054
- --8310050295 "Technical Evaluation of Hatch Units i & 2 Plant-Unique Analysis Repts " RANLET, J D , ECONDMOS, C Brookheven National Laboratory FIN A-3713. BNL-04243 83/09/30 NRC -- No Detailed Affiliation Given 25pp 22188 263 24X Fichs 50-321,84/01/25,8402090054
- --8309270297 "Audit for Mark I Containment Long-Term Program Structural Analysis for Operating Reactors.EI Hatch Nuclear Plant Units 1 k 2," technical evaluation rept SUBRAMONIAN, N, TRIOLO, S, LE, A K Franklin Institute/Franklin Research Center. NRC-03-81-130, TER-C5506-329 83/09/27 SHAW, H NRC NO Detailed Affiliation Given 44pp 22188 288 24X Fiche. 50-321, 84/01/25, 8402090054
- 8402100179 Discusses time at which hydrogen monitoring is initiated Intent of TMI Item II F 1(6) is to ensure timely hydrogen monitoring in event of core uncovery during LOCA Definition for onset of LOCA undefinable GUCWALL T Georgia Power Co 84/02/03, STOLZ, J F Operating Reactors Branch 4 2pp 22182/181 24X Fiche 50-321,84/02/03,8402100179
- 8402150197 Withdraws 831128 request for Tech Spec changes allowing plant operation w/o forced recirculation flow OUGHAL T. Georgia Power Co 84/02/06. STOLZ, J F. Operating Reactors Branch 4 ip. 22245, 136 24X Fichs 50-321, 84/02/06, 8402150197.
- 8402220514 Application for amend to Licenses DPR-57 & NPF-5, consisting of Tech Spec changes re APRM rod block monitor & Tech Spec improvements program Affidayit encl Tech Spec withhald (ref 10cFR2.790)

 BECKHAH, J. T. Georgia Power Co 84/02/06. STGLZ, J. F. Operating Reactors Branch 4 15pp 22331:324 24X Fiche 50-321, 84/02/06, 8402220514.
- 8402160228 Forwards Rev 1 to Procedure HNP-4848, "Determination of Extent of Core Damage Under Accident Conditions," per NRC request & NUREQ-0737, Item II B.3 GUCHALLT Georgia Power Co. 84/02/10 GTOLZ, J. F. Operating Reactors Branch 4. ip 22276-317, 24X Fiche, 50-321, 84/02/10, 8402160228,
- --8402160232 Rev 1 to Procedure HNP-4848, "Determination of Extent of Core Demage Under Accident Conditions."

 OREENE, T. Georgia Power Co. 83/10/12 12pp. 22276-318 24X Fiche: 50-321, 84/02/10. 8402160228.
- 8402240145 Forwards response to request for add1 justification for proposed completion schedule re NUREG-0737, Item II B 3, "Post-Accident Sampling Capability " Site Verfication tests will be completed by 840501 GUCHA-L.T Georgia Power Co. 84/02/20 STOLZ, J.F Operating Reactors Branch 4. 5pp 22375:071. 24X Fiche 50-321.84/02/20, 8402240145.
- 8402270219 Forwards containment post-accident profiles utilized in 10CFR50. 47 qualification program & extended drywell temp analysis withheld (ref 10CFR2,770). QUCMA-L.Y Georgia Power Co 84/02/24, 8TOL7.J F. Operating Reactors Branch 4. 2pp. 22386.034. 24X Fiche 50-321,84/02/24,840270348
- ~-8402270240 "Post-Accident Temp & Pressure Profiles."
 QUIRK, J. F. Qeorgia Power Co. 84/02/24 7pp. 22386:036. 24X
 Fichs. 50-321, 84/02/24, 8402270215
- G. Inspection reports, IE Bulletins & correspondence
- 8402140350 Forwards IE Insp Repts 50-321/83-34 & 50-366/83-96 on 831212-16. No violations or deviations noted. BANCE H.C. Division of Project & Resident Programs, 84/01/06. KELLYR, J. Georgia Power Co. Zpp 2220:101. 24X Fiche: 50-321:84/01/04.8402140350

- --8402140356 IE Insp Repts 50-321/83-34_k 50-366/83-36 on 831212-16 No violations or deviations noted Major areas inspected mgt & administrative controls & review of annual environ monitoring rept for period ending 821231 CUNNINCHAM.A L Region 2. Office of Director MCNTGOMERY.D M Division of Engineering & Operational Programs 84/01/05 Bpp. 22220 103 24% Fiche 50-321.84/01/06.8402140350
- 8402140140 Forwards IE Insp Rept 50-366/83-37 on 831213-16 No violations or deviations hoted BANCE:H C Division of Project & Resident Programs 84/01/11, KELLY:R J Georgia Power Co 2pp 22218 001 24X Fiche 50-366.84/01/11.8402140140
- --8402140145 IE Insp Rept 50-366/83-37 on 831213-16 No violations or deviations noted Major areas inspected preplanning for replacement of reactor recirculation piping & review of contractor 4A manual MCFARLAND, C R Region 2, Office of Director UPRIGHT, C M Division of Engineering & Operational Programs 84/01/10 4pp 22218 003 24X Fiche 50-366.84/01/11.8402140140
- 8402140147 Forwards IE Insp Repts 50-321/83-36 & 50-366/83-39 on 831219-22 No violations or deviations noted DANCE: H C Division of Project & Resident Programs 84/01/17 KELLyr, U. Georgia Power Co 2pp 22230:078 24X Fichs 50-321,84/01/17.8402140147
- --8402140154 IE Insp Repts 50-321/83-36 & 50-366/83-39 on 831219-22 No violations or deviations noted Major areas inspected health physics preparation activities re recirculation pipsing replacement project & followup review of LERs KAHLE, J B Ragion 2, Office of Director BARR, K P Division of Engineering & Operational Programs 84/01/13 Bpp 22230 OBO 24X Fiche 50-321,84/01/17,8402140147
- 8312120133 IE Info Notice 84-06. "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York. Inc 120pp 22058 001. 24X Fiche 50-000.84/01/25.8312120153
- B40215040? Responds to notice of violation & proposed imposition of civil panelties &td B31227 Reduction in amount of penalty requested. Fee ancl BECKHAM, J T Georgia Power Co 84/01/25 DEYOUNG, R. Director's Office. Office of Inspection and Enforcement. 16pp 22242:071 24% Fiche. 50-366,84/01/25,8402150407
- 8402280239 Forwards IE Insp Repts 50-321/83-37 & 50-366/83-40 on B31221-840120. No violations or deviations noted DANCE:H C Divisson of Project & Resident Programs 84/01/31 KELLY:R, J. Georgis Power Co 2pp. 22399-269, 24X Fiche, 50-321, 84/01/31, 8402280239
- --8402280246 IE Insp Repts 50-321/83-37 & 50-366/83-40 on 831221-840120 No violations or deviations noted Major areas inspected Tech 8pec compliance, operator performance, plant operations, QA practices & mgt practices CRLENJAK:R V., HOLMES-RAY.P. Region 2. Office of Director. PANOIERA:V Division of Project & Resident Programs. 84/01/28. 4pp 22399, 271. 24X Fiche 50-321.84/01/31.8402280239.
- 8401190016 IE Info Notice 84-07. "Design-Basis Threat & Review of Vehicular Excess Controls." Byo list encl JORDAN E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/03 Consolidated Edison Co. of New York, Inc. 119pp. 22114 177. 24X Fiche. 50-000.84/02/03,8401190016.
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers." Svc list encl. DEYDUNG,R C. Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc. 102pp. 22177:156 24X Fiche 50-000.84/02/03.8401190017
- 840R150269 Ack receipt of 831214 & 840127 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-366/83-29 LEMIS.R.C Division of Project & Resident Programs 84/02/06 KELLY.R.J Gaorgia Power Co. 1p 22250.052. 24X Fiche 50-366.84/02/06.8402150269
- --8402150277 Clarifies 831214 response to NRC 831115 ltm re violations noted in IE Insp Rept 50-366/83-29 Corrective actions plant review board members & dept managers made aware of need for carsful review of procedure changes.

 OUCHA, L. T Georgie Power Co. 84/01/27 D'REILLY, J. P. Region 2, Dffice of Director ip 22250 053 24X Fichs 50-366,84/02/06,84/02/50269.

- --8402150282 Ack receipt of 831214 ltr informing NRC of steps taken to correct violations noted in IE Into Rept 90-366/83-29 LEWIS-R C Division of Project & Resident Programs 84/01/06 KELLY-R J Georgia Power Co. 1p 22250 054 24X Fiche 50-366.84/02/06.8402150269
- --B402150288 Responds to NRC 831115 ltr re violations noted in IE Insp. Rept 50-366/83-29 Corrective actions relief valve operability procedure revised to return to Tech Spec testing requirement & plant review board will conduct closer review OUCHA, L.T. Georgia Power Co. 83/12/14 G'REILLY, J.P. Region 2, Office of Director 2pp 22250 055 24X Fiche 50-366,84/02/06,8402150267
- --B402150290 Forwards IE Insp Repts 50-366/83-29 & 50-321/83-27 on B30820-0930 & notice of violation LEMIS.R C Division of Project & Resident Programs B3/11/15 KELLY.R J Georgia Power Co 2pp 22250 057 24% Fiche 50-366.84/02/06.8402150269
- --8402150292 Notice of violation from insp on 830820-0930 * Region 2, Office of Director B3/11/15 1p 22250 059 24X Fiche 50-366.84/02/05.8402150269
- --8402150294 IE Insp Repts 50-366/83-27 & 50-321/83-27 on 830820-0930 Violation identified improper plant review of relief valve operability procedure, resulting in Tech Spec requirements not being inplemented CRLENJAK, R V , HOLMES-RAY, P , ROOSE, J F Region 2, Office of Director 83/11/08 11pp 22250.060 24X Fiche 50-366,84/02/06,8402150269
- 8402280405 Responds to IE Bulletin 84-01 re insp for cracks in Mark I containment torus vent header No apparent cracking or relevant indications found on Unit 1 No add1 cracking found beyond original cracking on Unit 2

 BECKMAN.J T Georgia Power Co 84/02/10 0'REILLY, J. P Region 2: Defice of Director 2pp 22407 139 24x Fiche 50-321.84/02/10, 8402280405
- B401190041 IE Info Natice 84-09, "Lessons Learned From NRC Inaps of Fire Protection Bafe Shutdown Sys (10CFR30, App R) " Syr list eact URDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259 24X Fiche 50-000,84/02/13.8401190041.
- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection'"

 Svc list encl

 JORDAN,E L. Division of Emergency Proparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc. 115pp 22365-141 P4x Fiche 50-000,84/02/14,8401190039
- 8402170486 Ack receipt of payment of civil penalty imposed on 831227. Request for reduction of penalty to \$64,000 unwarranted. DEYOUND, R C Director's Office. Office of Inspection and Enforcement #4702/14 KELLY, R J Georgia Power Co 2pp 22313.360 24X Fiche 50-366,84/02/14.8402170486
- 8401170045 IE Info Notice 83-63. Suppl 1. "Potential Failures of Westinghouse Type SA-1 Differential Relays" 8vc list encl JORDAN.E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/02/15 Conspikated Edison Co. of New York. Inc. 118pp 22366 142 24X Fiche 50-000.84/02/15.8401170045.
- B402280445 Ack receipt of 840208 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-366/83-38 LEWIS.R C Division of Project & Resident Programs 84/02/15 KELLY.R J Georgia Power Co ip 22403 007 24X Fichs 50-366,84/02/15,8402280445
- --8402280466 Responds to NRC 840111 ltr re violations noted in IE Insp. Repts 50-321/83-35 & 50-366/83-38 Corrective actions reserved air actuator air lines reinstalled properly & safety-related maint requirements examined.

 GUCWA,L T Georgia Power Co. 84/02/08 O'REILLY,J P Repion 2. Office of Director 3pp 22403'010, 24X Fiche 50-366.84/02/15, 8402280445
- --8402280473 Forwards IE Insp Repts 50-321/83-95 & 50-366/83-38 on 831121-1216 & notice of violation.

 LEWIS.R C. Division of Project & Resident Programs, 84/01/11 KELLY,R J Georgia Power Co 2pp 22403-013, 24X Fiche. 50-366,84/02/15,8402280445.
- --8402280475 Notice of violation from insp on 841124-1216. * Region 2, Office of Director 84/01/11 ip 22403:015 24X Fiche 50-366,84/02/15,8402280445

- --8402280485 IE Insp Repts 50-321/83-35 & 50-366/83-38 on 831121-1216 Viplation identified work on RHR sys testable check valve performed w/o documented instructions, procedures or drawings CRLENJAK,R V , HOLMEB-RAY,F , ROGGE,J F Region 2, Office of Director 84/01/09 7pp 22403 016 24X Fiche 50-366,84/02/15, 8402280445
- 8401190062 IE InPo Notice 84-10. "Motor-Operated Valve Torque Switches Set Below Hampfacturer Recommended Value " Svc list enci JORDAN, E L Division of Emergency Preparedness & Engineering Response (fost 830103). 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000.84/02/21,8401190082
- 8401190066 IE Info Notice 84-11. "Training Program Deficiencies." 8vc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/24 Consolidated Edison Co of New York, Inc 115pp. 22430 304 24X Fiche 50-000.84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals,"
 Svc list encl
 JORDAN, E. L. Division of Emergency Preparadness & Engineering
 Response (Post 830103). 84/02/27, Consolidated Edison Co. of New
 York, Inc. 120pp 22431:060 24% Fiche 50-000,84/02/27,8401190067
- R Periodic operating reports & related correspondence
- 8402140334 Monthly operating rapts for Jan 1984 W/840210 ltr RAFEEDIE.D P . NIX.H C Georgia Power Co. 84/01/31 14pp 22220 260 24X Fiche 50-321,84/01/31,8402140334
- 8402150391 Forwards monthly operating repts for Jan 1984 NIX.H C Georgia Power Co 84/02/10 Division of Licensing, 1p. 22241 350 24X Fiche 50-321,84/02/10,8402150391
- 8. Reportable occurrences: LERs & related correspondence
- 8402090569 Forwards technical review rept for 830714 control rod mismanipulation event Assessment of event does not support AD classification. MOLF.TR Program Technology Branch 83/12/02. SEYFRIT.K.V Reactor Operations Analysis Branch 1p 22189 358 24X Fiche: 50-366.83/12/02.8402090569
- --8402090571 "Evaluation of Control Rod Mismanipulation Event at Hatch Unit 2" " Director's Office AEOD/T340 83/12/02 4pp 22187 359. 24% Fiche 50-366,83/12/02,8402090569.
- 8402030414 LER 83-149/03L-0: on 831229, while transporting injured person, both doors of airlock for reactor blig were opened, rendering secondary containment inoperable Caused by personnel error Airlock doors reclased W/840127 ltr.
 TIPPE, 8.8., NIX, H C Georgia Power Co. 84/01/27 D'REILLY, J P. Region P. Office of Director App 22048 301. 24X
 Fiche. 50-366.84/01/27.8402030414
- 8402230347 Updates status rept on BMR pipe cracks & protection of upcoming licenses actions Insp results encl Evaluation & recommendations re interim & long-term remedial measures expected by May 1984.

 DIRCKE, W J Office of the Executive Director for Operations SECY-84-009A. 84/01/27. 3pp 22377.047 24X Fiche. 50-000, 84/01/27, 8402230347.
- 8402130321 Updated LER 83-134/03X-1 on 831129, during control panel walkdown, hydrogen peroxide enalyzer 8 found inoperable. Caused by component failure due to miscellaneous failed parts. Analyzers repaired. W/840202 ltr TTPPB: 8 B , NIX, M, C Georgia Power Co. 84/02/02, D'REILLY, J, P Region 2, Dffice of Director 4pp. 22201, 140 24X Fiche. 50-366.84/02/02,8402130321
- B402140171 PNO-II-B4-006 on 840203 during routine insp of torus interior.licenses found open crack around circumference of torus vent header. Util working w/gE & Bechtel to demonstrate integrity of torus vent header of Unit 1
 PANCIERALV. W. ROGGEL J. F. Region 2. Office of Director. 84/02/03.
 2pp 22230 088. 24X Fiche 50-366.84/02/03.8402140171
- 8402140446 PNO-II-84~006A, on 840203, crack found in torus vent header. Investigation of cause in progress Cause appears to be brittle type failure caused by significant temp changes due to introduction of nitragen PANCIERALV. W. HERDT. A.R. Region 2, Office of Director. 84/02/06 2pp 22227-183. 24X Fiche 50~366,84/02/06,8402140446

- 8402270093 LER 84-003-00 on 840115, reactor water cleanup sys outboard isolation valve 2031-F004 Pailed to close Caused by incorrectly installed reactor water cleanup dump Plow transquitter Transmitter reinstalled W/840214 ltr TIPPS 8 B , NIX,H C Georgia Power Co 84/02/14 App 22391 288 24X Fichw 50-366.84/02/14,8402270093
- 8402270i15 LER 84-004-00 on 840i17 & 20 during primary containment periodic Type B & C leakage tests excessive leakage found in MBIVs: inboard isolation valve & testable check valve Valves will be repaired W/840214 ltr TIPPS. B B. NIX.H C Georgia Power Co 84/02/14 7pp 22388 195 24K Fichs 50-366,84/02/14,8402270115

V. Operator Examinations

8402140316 Forwards summary of 840111 meeting w/util re training & certification of licensed operator candidates & results of recent NRC administered exams
DANCE, H, C Division of Project & Resident Programs 84/02/03
XELLY, R J Oworgia Power Co 2pp 22228 245 24X
Fichs. 50-321,84/02/03,8402140316

DOCKET 50-367 BAILLY GENERATING BYATION

O. Adjudicatory correspondence

B402280218 Requests ruling on 820604 application for award of attys fees under Equal Access to Justice Act in light of Comptroller General 830727 ruling Related correspondence HHIGHER, J M Businessmen for the Public Interest 84/02/22 PLAINE, H H Office of the General Counsel. 2pp 22400.181, 24X Fiche. 50-367.84/02/22,8402280218

DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2

A Application/construction stage documents & correspondence

- 8402070003 Responds to FDIA request for const completion dates for nuclear plants currently under const & analyses containing astimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documenta
 FELTON.J.M Division of Rules and Records 83/10/31
 ROSENBAUH.D M. Technical Analysis Corp 19pp 22173: 292 24X
 Fiche: 50-000,83/10/31,8402090003
- 8402090408 Partial response to FOIA request for four categories of documents re NUREO-75/087 (NUREO-0800), "BRP for Review of SARs for Nuclear Plants." Review of remaining documents incomplete Forwards App A documents
 FELTON, J M Division of Rules and Records. 83/12/30, MADDEN.T.J. Kaye. Bcholzr, Firman, Hays & Handler App 22193,003 24X
 Fiche: 50-000,83/12/30,8402090408.
- --B402090471 Provides guidance on acceptable locking devices & control of devices for manual switch & automatic operated components, in response to 770718 request.
 RIEBLAND, J I Division of Reactor Operations Inspections.
 77/08/26 MADBEN, 9 L Region 4, Dallas, Office of the Director 2pp. 22193-023 24X Fichs:50-000,83/12/30,8402090408

F. Security, medical, emergency & fire protection plans

- 8402220578 Forwards IE Insp Repts 50-313/83-27 & 50-368/83-27 on 831001-1104 & notice of violation 9A0LIARDOJ E. Region 4, Office of Director. 83/11/28, 9RIFFIN.J.M. Ankansas Power & Light Co. 2pp 22332 167. 24X Fiche: 50-313,83/11/28,8402220578.
- ---8402220576 IE Insp Repts 50-313/83-27 & 50-368/83-27 on 831001-1104 Noncompliance noted failure to complete job order form per procedural requirements & failure to maintain station battery operable; per Tech Spacs.

 CALLAN, L. U., JAUDON, J. P., KELLY, U. H. F. Region 4, Office of Director 83/11/22, 12pp 22332, 170, 24X Fiche 50-313,83/11/28,8402220578.
- 8402220271 Forwards IE Insp Repts 50-313/83-31 & 50-348/83-31 on 831128-1202 No violations or deviations identified. GAGLIARDOJ E Region 4, Office of Director 64/01/10. GRIFFIN.J.M. Arkansas Power & Light Co. 2pp. 22337:119. 24X Fiche: 50-313,84/01/10,8402220271.
- --B402220280 IE Insp Repts 50-313/83-31 & 50-368/83-31 on 831128-1202 No violations or deviations identified, Major areas inspected fire protection/prevention program & program implementation & compliance to 10CFR50, App R. Sections III. J & III O. MURPHY. M E Region 4. Office of Director. 84/01/06 3pp 22337:121 24X Fiche: 50-313,84/01/10,8402220271

- 8402010129 Forwards IE Insp Repts 50-313/83-29 & 50-368/83-29 on 831031-1104 No violations noted GABLIARDO JE Region 4. Office of Director 84/01/12 GRIFFIN.J M Arkansas Power & Light Co 2pp 22042 165 24X Fiche 50-313,84/01/12,8402010129
- --8402010132 IE Insp Repts 50-313/83-27 & 50-368/83-27 on 831031-1104 No violations noted Major areas inspected status of actions taken in response to embrgency proparedness appraisal & routine insp findings HACKNEY, C A Region 4, Office of Director 84/01/11 12pp 22042 167 24X Fichs, 50-313,84/01/12,8402010129
- B402220355 Forwards IE Insp Repts 50-313/B3-30 & 50-368/B3-30 on B31117-18 No violations or deviations noted GAGLIARDO, J E Region 4. Office of Director B4/01/18 GRIFFIN, J M Arkansas Power & Light Co 2pp 22335 340 24X Fiche 50-313,84/01/18,8402220355
- ---8402220367 IE Insp Repts 50-313/83-30 & 50-368/83-30 on 831117-18 No violations or deviations noted Major areas inspected security plan & proposed changes Details withheld (ref 10CFR73 21)
 KELLY, J. A. Region 4, Office of Director 84/01/17 ip 22335 342 24X Fiche 50-313,84/01/18,840220355
- 8402130040 Forwards remittance for 10CFR170 fees for fire protection reviews & approvals, per NRC 831203 ltr MARSHALL, J.R. Arkansas Power & Light Co. 84/01/30 MILLER, W.D. License Fee Management Branch 2pp 22204 083 24X Fiche 50-313,84/01/30,8402130040
- 8403210269 Revised emergency implementing procedures, including Procedures 2607 009 re sampling Unit 2 waste condensate tanks & 2607 021 re sempling waste condensate ion exchangers W/B40202 transmittal form iEVING.J M Arkansas Power & Light Co B4/02/01 9pp 22315 340 24X Fiche 30-319, B4/02/01 B402210269
- B402130636 Requests fee for B10319 & B20701 applications re exemption from certain App R requirements & alternate safe shutdown capability be remitted within 15 days of receipt of itr.
 MILLER, W. O. License Fee Management Branch B4/02/0B GRIFFIN, J M Arkansas Power & Light Co. 1p. 22214 292 24X
 Fiche 50-313.84/02/08.8402130636
- 8402170428 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR MILLER, JR Operating Reactors Branch 3 B4/02/08 ORIFFIN, JH Arkansas Power & Light Co 2pp 22313 172 24% Fiche. 30-313,84/02/08,8402170428.
- B402240265 Addresses Commissioner comments re emergency operations facility concerning feasibility & cost of upprading primary emergency operations facility to radiation protection factor of five Response requested by 840302

 BTOLZ, J.F. Operating Reactors Branch 4 MILLER, J.R. Operating Reactors Branch 3. 84/02/14. 091FFIN. J.M. Arkansas Power & Light Co. Opp. 22381 266 24X Fiche: 50-313,84/02/14.8402240265

J Insurance & indomnity information

- 8402130186 Forwards Endorsement 5 to NELIA Certificates N-48 & N-68 & Endorsement 5 to MAELU Certificates N-48 & M-68 M-68 MARBHALL.J R Ariansas Power & Light Co 84/02/06 DINITZ.I. Office of Nuclear Reactor Regulation, Director 5pp. 22204:154. 24X Fichs 50-313.84/02/06.8402130186
- B402130288 Forwards Endorsements 56 & 57 to NELIA Policy NF-210 & Endorsements 48 & 49 to MAELU Policy MF-74.
 MARBHALL, J R Arkansas Power & Light Co 84/02/06 DINITZ, I.
 Office of Nuclear Reactor Regulation, Director 5pp 22198 227 24X Fichs 50-313,84/02/06,8402130258
- P Operating license stage documents & correspondence
- B402220060 Submite final routine status rept of drawing control program progress Pilot program to redraw isometric drawing using computer aided drafting sys under evaluation.

 MARSHALL, J. R. Arkansas Power & Light Co. B3/12/01 GA9LIARDG, J E Division of Resident, Reactor Project & Engineering Programs 3pp 22338; 320. 24x Fiche; 50-313, 83/12/01, 8402220060
- 8402080381 Further response to FDIA request for CYB1-83 operating reactor event memos & current version of NRR ofc ltrs to be placed in PDR Forwards app documents Info also available in PDR. FELTON, J. M. Division of Rules and Records. 83/12/05. SHOLLY, S.C. Union of Concerned Scientists. 2pp. 22168, 147—24X Fiche. 50-368, 83/12/05, 8402080381

- --8103270357 Operating Reactor Event Memorandum 81-30 re flow blockages in essential equipment caused by Asian clams Clams caused Arkansas Nucleur Dne. Unit 2 800904 shutdown Heat treatment most effective remedy EIEERNHUT.D O Division of Licensing 81/03/10 VOLLMER, R H Division of Engineering 5pp 22168 153 24X Fiche 50-368,83/12/05.8402080381
- B312120029 Generic Ltr 83-39 to representatives of utils re voluntary survey of licensed operators Svc list encl EISENHUT, D 0 Division of Licensing 83/12/08 Commonwealth Edison Co 12pp 22313 006 24% Fiche 90-000,83/12/08.8312120029
- 8402220091 Submits summary evaluation of design of core for fourth cycle of operation at 100% rated core power of 2,815 MHt No unreviewed safety questions exist as result of third cycle reload Cycle 4 core map encl
 MAREHALLJR Arkansas Power & Light Co 83/12/30 GAGLIARDD D Division of Resident, Reactor Project & Engineering Programs 3pp 22337-242 24% Fiche 50-368,83/12/30,8402220091
- 8402010499 Responds to 831117 request for exemption from schedular requirements of 10cFR50 48.4 rom Jan 1984 to 840330 for installation of source range flux monitoring copability. Proposed installation completion date acceptable MILLER, J. R. Operating Reactors Branch 3 84/01/23 ORIFFIN, J. M. Arkansas Power & Light Co. 2pp. 22061 345 24X Fiche 50-368.84/01/23.8402010495
- 8402060107 Informs that submittal of response to Generic Ltr 83-10 re reactor coolant pump trip will be delayed until 840315 Delay due to late receipt of C-E analytical work MARSHALL.J R Artansas Power & Light Co 84/01/27 MILLER.J R Operating Reactors Branch 3 lp 22087 179 24X Fiche 50-368.84/01/27.8402060107
- 8402010410 Generic Ltr 84-04 to all operating PWR licensees. CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Svc list encl EISCHHUT, D 0 Division of Licensing 84/02/01. Consolidated Edison Co of New York, Inc. 59pg 22177 087 24X Fiche 50-000,84/02/01.8402010410
- B402090590 Requests rev to Tech Brecs re explosive gas mixture in radwaste gas sys, due to proposed hydrogen/oxygen concentration limits being above std radiological effluent Tech Brec limits Response requested within 45 days PTOLZ, J.F. Operating Reactors Branch 4 MILLER, J.R. Operating sactors Branch 9. 84/02/01. 071FFIN. J.M. Arkansas Pawer & Light o 7pp. 22184 343 24% Fiche 50-313.84/02/01.8402090590
 - 2140381 Forwards Amenda 82 & 52 to Licenses DPR-51 & NPF-6, espectively Amends revise Tech Specs to reflect sorganization of energy supply dept & plant functional reganization of energy supply dept & plant functional reganization (ILLER, J R Operating Reactors Branch 3 84/02/01 GRIFFIN, J, M irkansas Power & Light Co 4pp 22302, 077 24X Fiche 50-313, 84/02/01, 8402160581
 - 8402160893 Amends 82 & 32 to Licenses DRR-51 & NPF-6, respectively, ravising Tech Specs to reflect reorganization of energy supply dept & plant functional organization STOLZI.J.F Operating Reactors Branch 4. 84/02/01 39pp. 82302 001 244 Fithe: 50-013,849/02/01.8402160581.
- 402160293 Responds to Generic Ltr 84-01 re NRC use of terms important to safety & safety-related Participation in discussion will be through steering committee & chairman of util safety classification group MARBHALLIJR Arkansas Power & Light Co 84/02/13 TAYLOR, J M Director's Office, Office of Inspection and Enforcement. ip. 22274: 234. 24X Fiche 50-313,84/02/13,8402160293
- 3 Inspection reports, IE Bulletins & correspondence
- 3402070308 Submits second monthly rept on progress of regulatory response & commitment control program Program on schedule & achieving Fesults desired by NRC & util Next status rept util be issued on B30414.

 MARSHALL, J R Arkansas Power & Light Co B3/03/14 COLLINS, J T Region 4, Office of Director 4pp 22075'062 24X Fichs: 50-368.83/03/14.8402070308
- 402220578 Forwards IE Insp Repts 30-313/83-27 & 50-368/83-27 on 831001-1104 & notice of violation 9AGLIARDDJ E. Region 4. Office of Director 83/11/28. GRIFFIN, J H Arkansas Power & Light Co 2pp. 22332:167 241 Fiche 50-313,83/11/28,8402220578.

- --8402220596 IE Insp Repts 50-313/83-27 & 50-368/83-27 on 831001-1104 Noncompliance noted failure to complete job order form per procedural requirements & failure to maintain station battery operable, per Tech Specs CALLAN, L J , CUMMINS, J E , EVANS, C A Region 4, Office of Director 83/11/22 12pp 22332 170 24X Fichs 50-313,83/11/28,8402220378
- 8402030208 Forwards IE Insp Repts 50-313/83-28 & 50-368/83-28 on BB1024-28 No violations or deviations noted GAGLIARDD. J E Region 4. Office of Director B3/12/05 GRIFFIN. J M. Apkansas Power & Light Co 2pp 22066, 237. 24X Fiche 50-313.83/12/05.8402030208
- --8402030221 [E Insp Repts 50-313/83-28 & 50-368/83-28 on 831024-28 No violations or deviations noted Major areas inspected: radiation protection program during refueling, including advanced planning & preparation, training & exposure control. RAER, R E . HOLLEY, W L , MURRAY, B . Region 4, Office of Director. 83/11/30. 8pp 22066 237 24X Fiche 50-313,83/12/05,8402030208
- 8402030370 Forwards IE Insp Repts 50-313/83-26 & 50-368/83-26 on 830917-23 & notice of deviation 0A6LLARDO.J.E. Region 4. Office of Director 83/12/09, 0RIFFIN.J M. Arkansas Power & Light Co. 2pp 22066 036, 24X Fiche 50-313.83/12/09.8402030370
- --8402030376 Notice of deviation from insp on 830719-23,
 # Region 4, Office of Director 83/12/09 ip 22066:038 24%
 Fiche 30-313,83/12/09,8402030370
- --8402030383 IE Insp Repts 50-313/83-26 & 50-368/83-26 on 830919-23
 Deviation noted:13 of 16 radiochemistry technicians
 lacked 2-yr experience criteria in radiochemistry
 NICHOLAS, B. J. WISE, R. MURRAY, B. Region 4, Office of Director.
 83/12/05 16pp 22066 039 24X Fiche 50-313,83/12/09,8402030370
- 8402220338 Forwards IE Insp Repts 50-318/83-32 & 50-368/83-32 on 831105-30 No violations or deviations identified. 9AGLIARDD.J E Region 4. Office of Director. 83/12/23. ORIFFIN.J.M. Arkensas Power & Light Co. 2pp. 22334-194. 24X Fiche. 50-313.83/12/23.8402220338
- --8402220339 IE Imap Repts 50-313/83-32 & 50-368/83-32 on 831105-30. No violations or deviations identified Major areas inspected: LERE, surveillance, mainticold weather preparation & security guard force strike.

 CALLAN, L. J., CUMMINS, J. E., JOHNSON, W. D. Region 4, Office of Director 83/12/17, 11pp. 22334 198 24X Fiche: 50-313,83/12/23,8402220338.
- 8402220271 Forwards IE Insp Rapts 50-313/83-31 % 50-368/83-31 on 831128-1202 No violations or deviations identified 8AQLIARDO, J E Region 4, Orfice of Director. 64/01/10 ORIFFIN, J M. Arkansas Power & Light Co 2pp. 22337.119. 24X Fichs 50-313,64/01/10,8402220271
- --8402R20R80 IE Insp Repts 30-313/83-31 & 50-368/83-31 on 831128-1202 No violations or deviations identified Major areas inspected. fire protection/prevention program & program implementation & compliance to 10CFR50.App R. Bections III J & III O MURPHY. M. E. JUHNSON, W. D. Region 4. Office of Director. 84/01/05 Bpp. 2R337 121 24X Fiche.50-313,84/01/10,8402220271.
- 84020101R9 Forwards IE Insp Repts 50-313/83-29 & 50-368/83-29 on 831031-1104 Ng violations noted GAGLIARDOJ E Region 4, Office of Director 84/01/12 GRIFFIN.J.M Arkaneas Power & Light Co. 2pp 22042:165 24X Fichs 50-313,84/01/12,8402010129.
- --8402010132 IE Insp Repts 50-313/83-27 & 50-368/83-29 on 831031-1104.No violations noted Major areas inspected status of actions taken in response to emergency preparedness appraisal & routine insp findings HACKNEY.C.A.: RAIRD.J.B.; JOHNBON.W.D. Region 4. Office of Director 84/01/11. 12pp 22042-167. 24X Fiche: 50-313.84/01/12, 8402010129
- 8402220355 Forwards IE Insp Repts 50-313/83-30 & 50-368/83-30 on 831117-18 No violations or deviations noted. 8A0LIARDOJJE. Region 4. Office of Director. 84/01/18 9RIFFIN.J.M. Arkaness Power & Light Co. 2pp. 22335 340. 24X Fiche: 50-313,84/01/18,8402220355
- --8402220367 IE Insp Repts, 50-313/83-30 & 50-368/83-30 on 831117-18. No violations or deviations noted Major areas inspected security plan & proposed changes Details withheld (ref 10CFR73 21) KELLY, J A : HALL, R E ; JOHNBON, W. D. Region 4, Office of Director 84/01/17. ip 22335, 342, 24X Fiche: 50-313, 84/01/18, 8402220355.

- 8402220478 Ack receipt of B31222 ltr requesting extension to 840130 to respond to violations noted in IE Insp Repts 50-313/83-27 to 50-368/83-27 Extension granted QAQLIARDO.JE Region 4, Office of Director 84/01/18 QRIFFIN.J M Arkansas Power & Light Co 1p 22340 098 24X Fichs 50-313.84/01/18.8402220478
- --8402220488 Responds to NRC 831128 Itr re violations noted in IE Insp Repts 30-313/83-27 & 50-366/83-27 Requests response date be extended to 840130 MARSHALL, J R Arkansas Power & Light Co 83/12/22 QAQLIARDD. J E Division of Resident. Reactor Project & Engineering Programs 1p 22340 099 24X Fiche 50-313,84/01/18,8402220478
- B40201047B Confirms insp of facility on B40124-25 re removal of IAEA surveillance camera from containment to place seals on strategic locations around reactor vessel Insp also involves servicing of surveillance camera in spent fuel pool area MILLER, JR Dperating Reactors Branch 3 B4/01/20 GRIFFIN, JM Arkansas Power & Light Co ip 22061 344 24X Fiche 50-368,84/01/20,8402010498
- B402220383 Forwards IE Insp Repts 50-313/83-34 & 50-368/83-34 on B31201-31 & notices of violation & deviation. GAGLIARDG,J E Region 4. Office of Director 84/01/20 GRIFFIN,J M Arkansas Power & Light Co 2pp 22337 008. 24X Ficher 50-313,84/01/20,8402220383
- --8402220387 Notice of violation from insp on 831201-31. * Region 4, Office of Director 84/01/20 3pp 22337 010. 24X Fiche, 50-313,84/01/20,8402220383.
- --8402220406 IE Insp Repts 50-313/83-34 & 50-368/83-34 on 831201-31 Noncompliance noted use of test equipment w/o current calibr & failure to follow procedures for recording of measuring & test equipment CALLAN. L J , CUMMINS. J. E , JOHNSON. W D Region 4. Office of Director. 84/01/14 10pp 22337 014 24% Fiche 50-313,84/01/20,8402220383
- B312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JCRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/25. Consolidated Edison Co. of New York, Inc. 120pp. 22058.001 24X Fiche 50-000.84/01/25.8312120153
- B401190016 IE Info Notice B4-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/02/03, Consolidated Edison Co of New York, Inc. 119pp. 22114:179 24X Fiche 50-000,84/02/03,8401190016
- 84Q1190Q17 IE Bylletin 84-01, "Cracks in BWR Mark I Containment Vent Headers." Syc list encl DEYOUNO, R. C. Director's Office, Office of Inspection and Enforcement, 84/02/03, Consolidated Edison Co. of New York, Inc. \$02pp. 22177:156. 24X Fiche 50-000,84/02/03,8401190017.
- B40222046B Ack receipt of B31031 & B4011B ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-21 & 50-368/83-21.

 GAGLIARDO.J.E Region 4. Office of Director B4/02/0B GRIFFIN, JM Arkansas Power & Light Co ip. 22339:290. 24X Fiche: 50-313.84/02/0B, B40222046B
- --B402220476 Responds to NRC 831130 ltr re violations noted in IE Insp Repts 50-313/83-21 & 50-368/83-21. Corrective actions Procedure 1025 05, Rev O, issued 831111 to require log book be maintained for battery maint activities. MARSHALL.J.R. Ankansas Power & Light Co. 84/01/18 QAQLIARDD.J.E. Division of Resident, Reactor Project & Engineering Programs. 2pp. 22337:271 24X Fiche 50-313.84/02/08.8402220468
- - PROBANE L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365 259, 24X Fiche 50-000,84/02/13,8401190041.
- 8401190039 IE Info Notice 84-08, "10CFR50.7, 'Employee Protection.'"
 Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/14. Consolidated Edison Co. of New
 York, Inc. 115pp. 22365:141. 24X Fiche 50-000,84/02/14,8401190039.
- 8401170045 IE Info Notice 83-63, Suppl i, "Potential Failures of Westinghouse Type 5A-1 Differential Relays." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/15. Consolidated Edison Co. of New York, Inc. 118pp 22366:142 24X Fiche 50-000, 84/02/15, 8401190045.

- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches 8st Below Manufacturer Recommended Value " Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000.84/02/21,8401190062
- 8402270152 Ack receipt of 840125 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-27 & 50-348/83-27 GAGLIARDD, J E Region 4. Office of Director 84/02/22 GRIFFIN, J M Arkansas Power & Light Co 1p 22391 281 24X Fiche 50-313,84/02/22.8402270152
- --8402270158 Responds to NRC 831128 ltr re violations noted in IE Insp Repts 50-313/83-27 & 50-368/83-27 Corrective actions maint personnel reinstructed on post-maint testing MARSHALL, J.R. Arkenses Power & Light Co. 84/01/25 GAGLIARDD, J.E. Division of Resident, Reactor Project & Engineering Programs 2pp 22391 282 24X Fiche 50-313,84/02/22,8402270152
- B401190066 IE Info Notice 84-11, "Training Program Deficiencies"
 Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430-304 24X Fiche 50-000.B4/02/24.8401190066
- B4022B0400 Notifies that final results of fuel insp will not be submitted until 840330 due to add1 time required for compilation of results MARBHALL.JR Arkansas Power & Light Co B4/02/24 MILLER,JR Operating Reactors Branch 3 ip 22405 026 24X Fiche: 50-366.84/02/24.84022B0400
- B401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals"
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York Inc 120pp. 22431 060 24X Fiche 50-000.84/02/27.8401190067
- R Periodic operating reports & related correspondence
- B40207030B Submits second monthly rept on progress of regulatory response & commitment control program Program on schedule & achieving results desired by NRC & util Next status rept will be issued on B30414
 MARSHALL.JR Arkansas Power & Light Co 83/03/14 COLLINS.J T Region 4, Office of Director. 4pp. 22095 062 24X
 Fiche: 50-368.83/03/14,8402070308
- S Reportable occurrences. LERs & related correspondence
- 8402220181 LER 83-044/01T-0: on B31212, personnel determined that during Oct 1982 18-month test, not all containment penetration conductor overcurrent protection devices tested per Tech Spec 4.8 2 5 a 2
 LEVINE.J M Arkansas Power & Light Co 83/12/13 COLLINS.J T Region 4. Office of Director ip 22340.293. 24X
 Fiche: 50-368.83/12/13.8402220181.
- 8402010147 Revised LER 83-044/01X-1 on 830926, battery 2D11 failed quarterly surveillance tests Caused by normal aging & insufficient duration of previous equalizing charges. Surveillance procedures will be revised, 4/840117 tr. MOEGOENBERG, D. MARSHALL, J. R. Arkanses Power & Light Co. 84/01/19 OGGLIARDD, J. E. Region 4. Office of Director 5pp. 22038 224 24% Fichs: 50-368.84/01/19,8402010147.
- 8402060407 Revised LER 83-045/03X-8. on 830916, special insprevealed deficient fire barriers Causes for each deficiency listed Roving fire inspector program implemented W/840121 itr ROGENB,P. MARSHALL.J R Arkansas Power & Light Co 84/01/21 QAQLIARDD, T. E. Region 4, Office of Director 21pp 22086 242 24X Fiche: 50-368, 84/01/21: 8402060407
- 8402280236 Updated LER 83-045/03X-7 between 830916 & 840115, multiple fire protection deficiencies occurred Causes & corrective actions listed Complete fire protection sys walkdown inspin progress W/840210 ltr ROGERS, P. MARSHALL, J.R. Arkansas Power & Light Co. 84/02/10 DENIBE, R.P. Division of Resident, Reactor Project & Engineering Programs, 23pp. 22397.290 24X Fiche 50-368,84/02/10,8402280236

- DOCKET 50-369 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8402090003 Responds to FDIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Gaseload Forecast Panel meetings Forwards App A.B & C documents FELTON.J M Division of Rules and Records 83/10/31 ROSENBAUM.D M Technical Analysis Corp 19pp 22193 292 24X Fiche 50-000,83/10/31.8402090003
- --B402090192 Handwritten notes & calculations re const activities & fuel load date projection Related info encl * NRC - No Detailed Affiliation Given 78/09/26 5pp 22195 083 24X Fiche 50-000,83/10/31.8402090003
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8402230106 Discusses installation of insp ports in each steam generator prior to startup after first refueling.per Item 5 3 1 in 85ER 4, NUREG-0422 Steam generator monitoring & testing programs in effect & acceptable alternative planned TUCKER, H B Duke Power Co 84/02/14 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENBAB, E G Licensing Branch 4 2pp 22362 134 24% Fishe 50-369, 84/02/14, 8402230106
- F Security, medical, emergency & fire protection plans
- 8402160374 Forwards Rev 6 to training & qualification plan Rev withheld (ref 10CFR73 21)
 TUCKER, H D Duke Power Co 84/01/25 O'REILLY, J P Region 2,
 Office of Director ip 22269 121 24X Fiche 50-369, 84/01/25,
 0402140774
- 3402140278 Advises that review of Rev 12 to facility radiological emergency plan completed Plan meets planning stds of 10CFR50 47 & requirements of App E to 10CFR50 DANCE.H C Division of Project & Resident Programs 84/01/26 TUCKER.H B Duke Power Co 1p 22228 292 24X Fiche 50-369,84/01/26,8402140278
- 8402140527 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per 810707 Generic Ltr 81-27 M/o request, entire plan will be placed in PDR ADENSAM E 0 Licensing Branch 4 84/02/06 TUCKER, H B Duke Power Co 2pp 2223-302 24% Fiche 50-369, 84/02/06, 84/02140529
- 8402220325 Forwards Rev 2 to util response to Suppl 1 to NUREG-0737.
 including control room review final rept & supplemental
 rept Rev does not include implementation schedule for
 control room mods
 TUCKER, H. B. Duke Power Co. 84/02/14 DENTON, H. R. Defice of
 Nuclear Reactor Regulation, Director ADENBAN, E. G. Licensing Branch
 4 2pp 22338 022 24% Fiche 50-369, 84/02/14, 8402220325
- --8402220328 Rev 2 to "Response to Buppl 1 to NURE9-0737"
 * Duke Power Co 84/02/16 200pp 22338:024 24X
 Fiche 50-369.84/02/16:6402220325
- 3402220493 Discusses util 83111B request for exemption from Section III J of 10cFR50.App R Util will place battery-powered hand lanterns in control room for emergency use, in response to NRC request for addl assurance for backup lighting TUCKER.H B Duke Power Co. 84/02/20 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM,E Q Licensing Branch 4 ip 22340 063 24X Fiche 50-369.84/02/20,8402220493
- Insurance & indemnity information
- Advisory Committee on Reactor Bafeguards reports & correspondence
- D2270263 Responds to FDIA request for JC Mark B01204 memo to ACRB re hydrogen burn w/igniters & documents concerning generation, combustion or control of hydrogen in reactor accidents forwards App A documents App B documents in PDR, FELTON, J M Davision of Rules and Records. B4/01/30, HIATT, B L Ohio Citiesns for Responsible Energy 7pp 22412 051 24X Fiche 50-000,84/01/30,8402270263

- --B402270371 Forwards portion of ASLB transcript re hydrogen control measures at facilities & Duke Power comments on Sandia concerns Opinion on whether Sandia comments on placement of hydrogen igniters justifiable requested W/o encl QUITTECHREIBER ACRS Advisory Committee on Reactor Bafeguards 81/04/08 BICHEL,M ACRS Advisory Committee on Reactor Safeguards ip 22412 178 24X Fiche 50-000,84/01/30,8402270263
- --B402270374 "Comments Re Ignitars in Upper Plenum of Ice Condenser of Sequoyah & McGuira Nuclar Power Plants," prepared for ACRB Bubcommittee on Class 9 Accidents BICHEL,M Michigan, Univ of, Ann Arbor, MJ 81/08/17 20pp 22412 184 24X Fiche 50-000,84/01/30,8402270263
- P Operating license stage documents & correspondence
- 8402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983. CHILK B J Office of the Escretary of the Commission 83/12/14. Public Document Branch ip 22281 023 24X Fiche 50-000,83/12/14. 8402160003
- --8402140145 Discusses SECY-Bi-447, ALAB-447 re Duke Power Co CHILK.S J Office of the Secretary of the Commission 61/08/25 BICKWIT.L Office of the General Counsel 1p 22281 084 24X Fiche 50-000, 63/12/14, 8402140003
- --8402160177 Discusses SECY-Bi-579, ALAB-651 re transportation of spent fuel from Oconee Nuclear Station for storage at McQuire Nuclear Station CHILK.S J. Office of the Secretary of the Commission 81/10/27 BICKWIT).L. Office of the General Counsel ip 22281 117 24X Fichs 50-000,83/12/14.8402160003
- B402010410 Generic Ltr 84-04 to all operating PWR licensees, CP holders & applicants for CPs re safety evaluation of Hestinghouse topical repts dealing w/elimination of postulated pipe breaks in FWR primary main loops 8vc list encl.
 EISENHUT, D © Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc. 59pp 22177.087 24X
 Fiche 50-000.84/02/01.8402010410
- 8402070395 Forwards response to Section 2 2 1 5 of Generic Ltr 83-28.
 "Required Actions Dased on Generic Implications of Salem
 ATMS Events." re design verification & qualification
 testing for procurement of safety-related squipment
 TUCKER.H B Duke Power Co 84/02/01 EISENHUT.D.Q Division of
 Licensing 4pp 22161 114 24X Fiche 50-369.84/02/01.8402070395
- 8402130616 Advises that Class III license fee remitted w/B30309 application requesting exemption from requirements of 10CR50.App E. Section IV F will be refunded Exemption authorized by law & is in public interest HILLER.W O License Fee Management Branch 84/02/03 TUCKER, H B. Duke Power Co 1p 22214 295 24% Fiche 50-000.84/02/03.
- 8402130561 Forwards Amends 28 & 9 to Licenses NPF-9 & NPF-17, respectively.FR notice of availability, safety evaluation & NSHC Amends change Tech Specs re min RCB rate for Unit 2 NBHC available in Central Files.
 ADENSAM
- --8402130564 Amends 28 & 9 to Licenses NPF-9 & NPF-17, respectively, revising Tech Specs re min RCS rate for Unit 2. ADENSAM,E 0. Licensing Branch 4 84/02/04 22pp. 22216:014 24% Fichs 50-369, 84/02/04, 8402130561
- --8402130567 Rafety evaluation supporting Amends 28 & 9 to Licenses NPF-9 & NPF-17, respectively * Office of Nuclear Reactor Regulation, Director #2216-036 24% Fiche 50-369,84/02/04,8402130561
- --B402130571 Notice of consideration of issuance of amends to Licenses NPF-9 & NPF-17 & proposed NBHC & opportunity for hearing ADENSAM, E 0 Licensing Branch 4 B3/12/27 7pp, 22216 040. 24X Fiche 50-369, B4/02/04-B402130561.
- 8402230146 Application for amend to Licenses NPF-9 % NPF-17, allowing spent fuel pool storage capacity expansion from 500 to 1.463 spaces for each spent fuel pool. Supporting documentation encl
 TUCKER. H B Duke Fower Co B4/02/17 DENTON. H.R. Office of Nuclear Reactor Regulation, Director ADENBAM. E 0, Licensing Branch 4 65pp 22352 206. 24X Fiche 50-369, 84/02/17, 8402230146

- 8402270185 Revs to 831212 application for amond to Licenses NPF-9 & NPF-17, changing Tech Specs re plant operating limitations Rev corrects time constants utilized in lead-lag controllor for Unit /Cycle 2 TUCKER: H. B Duke Power Co 84/02/20 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E G Licensing Branch 2pp 22391 197 24% Fiche 50-369, 84/02/20, 8402270185
- --9402270195 Proposed Tech Spec Pages 2-9 & B 2-4 re reactor trip sys instrumentation trip setpoints & limiting safety sys settings: respectively. Fuel assembly design parameters encl & Duke Power Co 84/02/20. 3pp 22391 179 24X Fiche: 50-349,84/02/20. 8402270185
- @ Inspection reports. IE Bulletins & correspondence
- 8402140362 Forwards IE Insp Repts 50-369/83-46 & 50-370/83-53 on 831212-14. No violations or deviations noted DANCE, H. C Division of Project & Resident Programs 84/01/11 TUCKER, H. B Duke Fower Co 2pp 22220 089 24X Fiche 50-369, 84/01/11, 8402140362
- 8312120133 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list ancl JORDAN, EL Division of Emergency Preparedness & Engineering Rasponse (Fost 830103) 84/01/25 Consolidated Edison Co of New York, Inc. 120pp. 22058-001 24X Fiche.50-000,84/01/25,8312120133
- B401170016 IE Info Notice B4-07, "Design-Basis Threat & Raview of Vehicular Excess Controls." But list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Fost 830103). B4/02/03 Consolidated Edison Co. of New York, Inc. 117pp 22114,179. 24X Fiche 50-000,84/02/03,8401190016.
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers." Svc list encl DEYCNINO, R C. Director's Office, Office of Inspection and Enforcement. 84/02/03, Consolidated Edison Co. of New York, Inc. 102pp. 22177:156. 24X Fiche-50-000.84/02/03.8401190017.
- 8402280177 Advises that Westinghouse Type DB or DB or GE Type AK-2 circuit breakers not used in any safety-relayed applications at facilities, in response to IE Bulletin 83-08 TUCKER, H. B. Duke Power Co 84/02/10 D'REILLY, J.P. Region 2, Office of Director, ip. 22400 269 24X Fiche, 50-369, 84/02/10, 8402280177.
- B401190041 IE Info Notice B4-07, "Lessons Learned From NRC Insps of Fire Protection Bafe Shutdown Sys (10CFR50, App R) " Svc list encl.

 UCRDAN, E. L. Division of Emergency Preparedness & Engineering Remponse (Post B30103) 84/02/13. Consolidated Edison Co. of New York, Inc. 124pp. 22345:259, 24X Fiche 50-000, 84/02/13, 8401190041.
- B401190039 IE Info Notice B4-08, "10CFR50.7, 'Employee Protection '"
 Svc list encl.
 JORDAN E L. Division of Emergency Preparedness & Engineering
 Response (Post B30103). 84/02/14. Consolidated Edison Co. of New
 York, Inc. 1155p. 22365 141. 24X Fiche 50-000,84/02/14,8401190039
- 8402230106 Discusses installation of insp ports in each steam generator prior to startup after first refueling.per Item 5.3.1 in BEER 4. NUREO-0422. Steam generator monitoring & testing programs in effect & acceptable alternative planned. TUCKER. H. B. Duke Power Co. 84/02/14 DENTON. H. R. Office of Nuclear Reactor Regulation. Director. ADENSAM.E. G. Licensing Branch 4. 2pp. 22362 134 24X Fiche 50-369.84/02/14.8402230106
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Heatinghouse Type 86-1 Differential Relays" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/15 Consolidated Edison Co. of New York, Inc 118pp. 22366:142 24X Fiche: 50-000, 84/02/15, 8401190045.
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Menufacturer Recommended Value " Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/21. Consolidated Edison Co. of New York, Inc. 116pp. 22366:024 24X Fiche 50-000.84/02/21.8401190062
- B401190066 IE Info Notice 84-11, "Training Program Deficiencies"
 Svc list encl
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/24, Consolidated Edison Co of New
 York, Inc 115pp 22430; 304 24X Fiche 50-000, 84/02/24, 8401190056

- 8401190067 IE Info Notice B4-12, "Failure of Soft Seat Valve Seals "
 Svc list encl
 JURDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060 24X Fiche 50-000,84/02/27,8401190067
- 8 Reportable occurrences, LERs & related correspondence
- 8402140398 Requests addl info re Part 21 rept dtd 831108 concerning wear ring failure in auxiliary feedwater pump furnished to facilities Info requested within 25 days POTAPOV8. U Region 4. Office of Director 83/11/30 PATTY.D F Bingham-Willametts Co 1p 22221 250 24X Fiche 50-000,83/11/30,8402140398
- --8402140422 Supplemental Part 21 rept re wear ring failure in auxiliary feedwater pumps, per 831130 request for add1 info Mear rings will be replaced on returned units w/AFBI 420 wrought matl List of pumps in similar svc w/same wear ring encl PATTY.D F Bingham-Willamette Co 83/12/20 Region 4, Office of Director 2pp 22221 251 24X Fiche 50-000,83/11/30,8402140398
- 8402030218 LER 83-115/03L-0 on 831129, annulus ventilation train A unable to mest required vacuum decay time & declared insperable Caused by poor sealing on annulus doors Beals replaced, shimmed & adjusted, W/840113 ltr NARDSCI,P. B. TUCKER,H B. Duke Power Co. 84/01/13 0'REILLY, J. P. Region 2. 06fice of Director. Spp. 22067 228 24X Fiche 50-369,84/01/13,8402030218
- 8402030391 LER 83-117/03L-O on 831209, speed control of feedwater pump B lost & pump manually tripped, initiating automatic runback to 30% power. Cause not stated Control reds withdrawn & boron added to RCS. W/P40120 ltr.
 NARDGCI,F B : TUCKER.H.B. Duke Power Co 84/01/20 D'REILLY, J P Region 2. Defice of Director. 4pp 22064 026 24% Fichs 50-369,84/01/20.8402030391
- 8402030449 LER 83-120/03L-O on 831221, fire retardant packing of fire barrier penetration discovered missing Cause unknown New packing installed & penetration tested & declared operable W/840120 ltr
 NARDOCI.P B , TUCKER, H B Duke Power Co, 84/01/20 O'REILLY, J P Region 2. Office of Director 2pp, 22069 039 24X
 Fiche 50-369,84/01/20,8402030449
- B402140016 LER B3-121/03L-0 on B31231, while in Mode 1, invalid fire alarm for fire detection Zone EFA 116 received in control room, Caused by carbon dust on detector Detector cleaned & alarm reset. W/840130 ltr
 NARDOCI.P B . TUCKER, H B Duke Power Co 84/01/30 O'REILLY, J P Region 2. Office of Director 2pp 22217 357 24X
 Fiche: 50-367, 84/01/30, 8402140016
- 8402270101 LER 84-001-00 on 840109 unauthorized removal of safety injection main Feedwater & component cooling sys support/restraints reinstalled, repaired or deleted as appropriate W/840215 ltr NARDICI.P B : TUCKER.H.B Duke Power Co 84/02/15 4pp 22388.191 24X Fiche 50-369,84/02/15,8402270101.
- B4022B0422 LER 84-0D1-00, on 840109, valve support clamp found removed & support moved from normal position under valve IKC-51A Dn B31016 % 1021, tour pipe support restraints found removed. Caused by unauthorized removal W/840215 1tr TUCKER, H. B. , NARDOCI, P. B Duke Power Co 84/02/15 4pp. R2407:171 24X Fichs: 50-369, 84/02/15, 84022B0422
- DOCKET 80-370 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- B402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caselaad Forecast Fanel meetings Foreards App A, B & G documents.

 FELTON, J. M. Division of Rules and Records. 83/10/31 ROSENBAUM, D M Technical Analysis Corp 19pp. 22193-292 24X Fichs. 50-000, 83/10/31, 8402090003.
- B402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 GHILK, S. J. Office of the Secretary of the Commission 83/12/14, Public Document Branch. 1p. 22281 023, 24X Ficher 50-000, 83/12/14, 8402160003
- --8402160145 Discusses SECY-81-447, ALAB-647 re Duke Power Co CHILM.8.J Office of the Secretary of the Commission 81/08/25 BICKWIT.L Office of the General Counsel, ip 22281.084 24X Fiche, 50-000, 83/12/14, 8402160003.

- -8402160177 Discusses SECY-81-579.ALAB-651 re transportation of spent fuel from Oconee Nuclear Station for storage at McGuire Nuclear Station NULLEAR STATEON
 CHILK.S J Defice of the Secretary of the Commission St
 BICKWIT,L Office of the General Counsel ip 22281 117
 Fiche 50-000,83/12/14,8402160003 B1/10/27

F Security, medical, emergency & fire protection plans

- 8402160374 Forwards Rev & to training & qualification plan Rev withheld (ref 10CFR73 21)
 TUCKER, H B Duke Power Co 84/01/25 D'REILLY, J P Region 2, Defice of Director 1p 22269 121 24X Fiche 50-369,84/01/25,8402160374
- B402140278 Advises that review of Rev 12 to facility radiological energency plan completed Plan meets planning stds of 10CFR50 47 & requirements of App E to 10CFR50 BANCE, N C Division of Project & Resident Programs 84/01/26 TUCKER, H B Duke Power Co 1p 22228 292 24X Fiche 50-369.84/01/26.8402140278
- 8402140327 Advises that NRC will not review emergency plans to delete NO2140324 Advises that NRC WIN not review emergency plans to privacy or proprietary info unless specifically requested by licensee per 810709 Generic Ltr 81-27 H/o request, entire plan will be placed in PDR ADENSAME G Licensing Branch 4 84/02/04 TUCKER, H B CU 2pp 22253 302 24X Fichs 50-349.84/02/06.8402140529 Duke Power
- 8402220325 Forwards Rev 2 to util response to Suppl 1 to NUREG-0737, including control room review final rept & supplemental rept Rev does not include implementation schedule for control room mods
 TUCKER.H B Duke Power Co 84/02/16 DENTON.H R Office of
 Nuclear Reactor Regulation, Director ADENSAM.E G Licensing Branch
 4 2pp 22338 022 24% Fiche 50-369.84/02/16.8402220325
- --8402220328 Rev 2 to "Response to Suppl 1 to NUREG-0737" * Duke Power Co. 84/02/16 200pp 22338 024 24X Fiche 50-369,84/02/16,8402220325.
- 8402220493 Discusses util 831118 request for exemption from Section III J of 100FRSD. App R Util will place battery-powered hand lanterns in control room for emergency use. In response to NRC request for addl assurance for bactup lighting TUCKER. H B Duke Power Co 84/02/20 DENTON. H Office of Nuclear Reactor Regulation, Director ADENSAM. G Licensing Branch 4 Ip 22340 063 24% Fiche 50-369.84/02/20,8402220493

J Insurance & indemnity information

- 8402210213 Forwards undersaments to NELIA & MAELU policies including Endorsements 73 & 74 to NELIA Policy NF-182 Endorsements 37 & 38 to MAELU Policy NF-61 & Endorsement 4 to MAELU Policies # 35 to macto Policy Remain a consequent 4 to Macto Policies
 # -22.hr-23 & h-24
 LAUSON, L T. Buke Power Co 84/02/15 8ALTZMAN, J NRC - No
 Detailed Affiliation Given 18pp 22316 277. 24X
 Piche 50-000, 84/02/15,8402210213
- D Advisory Committee on Reactor Safeguards reports & correspondence
- 8402270263 Responds to FOIA request for JC Mark 801204 memo to ACR8 re hydrogen burn w/ignitars & documents concerning generation. combustion or control of hydrogen in reactor accidents. Forwards App A documents. App B documents in PDR FELTON, J M Division of Rules and Records 84/01/30 HIATT, 8 L Ohio Citizens for Responsible Energy 7pp. 22412 051 24X Fichs 50-000,84/01/30,8402270263
- ~-8402270371 Forwards portion of ASUB transcript re hydrogen control measures at facilities & Duke Power comments on Bandia concerns. Opinion on whether Sandia comments on placement of hydrogen igniters justifiable requested W/o encl.

 GUITTECHREIEER ACRS ~ Advisory Committee on Reactor Bafeguards
 BI/04/08. SICHEL, M ACRB ~ Advisory Committee on Reactor Safeguards
 Safeguards 1p. 22412 178 24X Fishe 50-000, 84/01/30, 8402270263.
- --8402270374 "Comments Re Igniters in Upper Plenum of Ice Condenser of Sequoyah & AcQuire Nuclar Power Plants," prepared for ACRS Subcommittee on Class 9 Accidents SICHEL.M Michigan, Univ of, Ann Arbor, MI 81/08/17 20pp, 22412.184 24X Fichs 50-000.84/01/30.8402270243

P Operating license stage documents & correspondence

- 8402010410 Generic Ltr 84-04 to all operating PWR licensees, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Svc list encl EISENNUT, D 0 Division of Licensing 84/02/01 Consolidated Edison Co. of New York, Inc. 59pp 22177 087 24X Fiche: 50-000, 84/02/01,8402010410
- 8402090395 Forwards response to Section 2.2 i 5 of Generic Ltr 83-28, "Required Actions Based on Generic Implications of Balem ATMS Events," re design verification & qualification stating for procurement of safety-related equipment TUCKER, H. B. Duke fower Co. 84/02/01 EISENNUT. D. Q. Division of Licensing 4pp 22i61 i14 24X Fiche 50-367, 84/02/01, 8402090395
- 8402130616 Advises that Class III license fee remitted w/830309 NO2130016 ADVISES that Class III license ree remitted winducapplication requesting exemption from requirements of 1006R50.App E.Section IV F will be refunded Exemption authorized by law & is in public interest HILLER.W O License Fee Management Branch 84/02/03 TUC Duke Power Co ip 22214 295. 24X Fiche 50-000.84/02/03, 8402130616 TUCKER, R B
- 8402130561 Forwards Amends 28 & 9 to Licenses NPF-9 & NPF-17, respectively, FR notice of availability, safety evaluation & NBHC Amends change Tech Spacs re min RCS rate for Unit 2 NSHC available in Central Files ADENSAM, E 9 Licensing Branch 4, 84/02/04 TUCKER, H, B (Co 2pp 22216:013 24X Fiche 50-369, 84/02/04, 8402130561. Duke Pour
- --8402130364 Amends 28 & 9 to Licenses NPF-9 & NPF-17, respectively, revising Tech Bpacs re min RCS rate for Unit 2 ADENSAM, E 0 Licensing Branch 4 84/02/04 22pp 22216:014 24X Fiche: 50-369, 84/02/04, 8402130361
- --8402130567 Safety evaluation supporting Amends 28 & 9 to Licenses NPF-9 & NPF-17, respectively * Office of Nuclear Reactor Regulation, Director 84/02/04, App. 22216 036, 24X fichs, 30-369,84/02/04,8402130561
- --8402130571 Notice of consideration of issuance of amends to Licenses NPF-9 & NPF-17 & proposed NSHC & opportunity for hearing ADENSAM, E. O. Licensing Branch 4 83/12/27, 7pp 22216,040. 24X Fichs. 50-369,84/02/04.8402130561.
- 8402230146 Application for amend to Licenses NFF-9 & NPF-17, allowing spant fuel pool storage capacity expansion from 500 to 1.463 spaces for each spent fuel pool. Supporting documentation encl tation encl H B. Duke Power Co 84/02/17 DENTON,H R. Office of Reactor Regulation, Director ADENSAN.E Q Licensing Branch p 22352:206, 24X Fiche.50~369.84/02/17,8402230146 TUCKER, H. B.
- -8402230149 Proposed Tech Space allowing spant fuel pool storage capacity expansion from 500 to 1,463 spaces for each spant fuel pool which proposed the spant fuel pool 800 pool 500 pool 500 pool 500 pool 500 pool 500 po * Duke Power Co. 84/02/17. 5pp. 22352.271 24X Fiche: 50-369, 84/02/17, 8402230146
- 8402270185 Revs to 831212 application for amend to Licenses NFF-9 & NFF-17. changing Tech Specs re plant operating limitations. Rev corrects time constants utilized in lead-leg controllor for Unit 1/Cycle 2.
 TUCKER.H.B Duke Power Co 84/02/20. DENTON.H.R Office of Nuclear Reactor Regulation, Director ADENBAM E G. Licensing Branch 4. 2pp 22391:197. 24X Fiche: 50-369, 84/02/20, 8402270185
- --B402270195 Proposed Tech Bpec Pages 2-9 & B 2-4 re reactor trip sys instrumentation trip setpoints & limiting safety sys settings, respectively. Fuel assembly design parameters encl. * Duke Power Co 84/02/20. 3pp 22391:199 24% - Duxa Power Co 84/02/20, 3pp Fiche 50-369, 84/02/20, 8402270185
- G. Inspection reports, IE Bulletins & correspondence
- B402140362 Forwards IE Insp Repts 50-369/83-46 & 50-370/83-58 on 831212-14 No viplations or deviations noted.

 DANCE, H. C. Division of Project & Resident Programs, 84/01/11 TUCKER, H B Duke Power Co. 2pp 2220.089 24X 100MER: H B Duke Power Co. 2pp 22220,089 Fiche: 50-367,84/01/11,8402140362.
- --8402140366 IE Insp Repts 50-369/83-46 & 50-370/83-53 on 831212-14 Na Violations or deviations noted Major areas inspected reactor coolant leak rate calculations & followup of LERs.

 BURNETT, P. T. Region 2, Office of Director. JAPE, F. Division of Engineering & Operational Programs 84/01/06. App 22220-091 24X Fiche 50-369.84/01/11,8402140362.

- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater
 - Pumps " Bvc list anci
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/01/25 Consolidated Edison Co of New
 York: Inc. 120pp 22058 001 24X Fiche 50-000.84/01/25.8312120153
- B401190016 IE Info Notice B4-07, "Design-Basis Threat & Review of Vehicular Excess Controls" Svc list encl
 JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000,84/02/03,8401190016
- E401170017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headars " Syc list encl DEVOUNG, R C Director's Défice, Office of Inspection and Enforcement B4/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 156 24x Fiche 50-000.84/02/03,8401170017
- 8402280177 Advises that Westinghouse Type D8 or D8 or QE Type AX-2 circuit breakers not used in any safety-related applications at facilities, in response to IE Bulletin 83-08 TUCKER, H. B. Duke Power Co. 84/02/10 D'RETLLY, J. P. Region 2, Office of Director ip 22400 269 24X Fiche 50-369, 84/02/10, 8402280177
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (100FR50, App R) " Syc list BREI JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365 259 24X Fiche 50-000,84/02/13,8401190041
- B401190039 IE Info Notice 84-08, "10CFR50 7, 'Emplayee Protection '"
 Svc list encl.
 JURDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 630103), 84/02/14 Consolidated Edison Co. of New
 York, Inc. 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039.
- 8401190045 IE Info Notice 83-63 Suppl 1. "Potential Failures of Mestinghouse Type SA-1 Differential Relays " Svc list encl JORDAN, E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366 142 24X Fiche 50-000,84/02/15,8401190045
- B401190062 IE Info Notice B4-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103). B4/02/21 Consolidated Edison Co of New York, Inc. 116pp. 22366 024 24X Fiche. 50-000, 84/02/21, 8401190062
- 0401190066 IE Info Notice 84-11, "Training Program Deficiencies." Svc list encl
 JORDAN,E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/24 Consolidated Edison Co. of New
 York, Inc. 115pp. 22430 304 24% Fiche 50-000,84/02/24.8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals " **Bor List encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/27 Consolidated Edison Co. of New York, Inc. 120pp 22431 060 24X Fichs. 50-000, 84/02/27, 8401170067
- B. Reportable occurrances, LERs & related correspondence
- 8402140398 Requests add1 info re Part 21 rept dtd 831108 concerning wear ring failurs in auxiliary feedwater pump furnished to facilities. Info requested within 25 days POTAPOVS. U. Region 4, Office of Director 83/11/30, PATTY. DF Bingham-Hillamette Co. 1p 22221 250 24X Fiche 50-000, 83/11/30, 8402240378.
- --B402140422 Supplemental Part 21 rept re wear ring failure in auxiliary feedwater pumps.per 831130 request for add1 info Waar rings will be replaced on returned units w/AISI 420 wrought matl List of pumps in similar svc w/same wear ring encl PATTY.D F Bingham-Willamette Co. B3/12/20 Region 4. Office of Director 2pp. 22221 251 PAX Fiche 50-000, 83/11/30, 8402140398
- 8402030245 Updated LER 83-057/01X-1 on 831009, fire protection sue valve IRF987 found closed instead of locked open. Caused by procedural deficiency due to erroneous requirement to lock valve. Valve positioned & procedure revised W/840116 1tr NARDOCI, P. B., TUCKER, H. B. Duke Power Co. 84/01/16 0'REILLY, J. P. Region 2. Office of Director. 4pp 22067:209 24X Fiche: 50-370,84/01/16.8402030245.

- 8402030223 LER 83-088/03L-0 on 831217, invalid fire alarm for Fire Detaction Zone EFA 12B received in control room & alarm would not reset Caused by draft from open lab door Alarm reset WARDC1.P B , TUCKER.H B Duke Power Co 84/01/18 D'REILLY, J P Region 2, Defice of Director 2pp 22067 236 24X Fiche 50-370.84/01/18,8402030223
- 8402030284 LER 83-089/03L-0 on 831222:120-volt ac vital instrument & control power sys battery inverter 2EVID tripped upon being energized & declared inoperable Caused by numerous component failures Components replaced W/840120 ltr NARDUCI.P B. TUCKER.H B. Duke Power Co. 84/01/20 O'REILLY.J P. Region 2, Office of Director 2pp 22069 350 24X Fiche 50-370,84/01/20,8402030284
- 8403030897 RO 370/83-90 on 831223, onsite power distribution requirements not met investigation of incident & preparation of rept incomplete Rept with be submitted by 840203 TUCKER.H B Duke Power Co 84/01/20 O'REILLY.J P Region 2. Office of Director ip 22049 357 24X Fiche 50-370.84/01/20, 8402030287
- 8402030349 LER 83-091/03L-0 on 831224, while in Made 4, invalid fire 102030349 LER 83-091/03L-0 on 831224.while in Mode 4.invalid fire alarm received Caused by dust accumulation in detector due to maint activities Detector replaced W/840123 ltr
 NARDOCI.P B , ORDERS.W T Duke Power Co 84/01/23 D'REILLY.J P
 Region 2. Office of Director. 2pp 22069 125 24X
 Fiche 50-370,84/01/23.8402030349
- 8402140185 RO 370/83-92 on 831231, during cold skutdown, RCS loops not filled investigation of incident & preparation of rept incomplete Rept expected by 840208
 TUCKER, H B Duke Power Co 84/01/30 D'REILLY, J. P. Region 2, Dfflie of Director in 22223 362 24X Fiche 50-370, 84/01/30, B402140185
- B402140184 LER 89-090/03L-0 on B31223; isolation transformer for circuit containing generator 2A breaker synchronization check relays overheated Caused by short in synchronization check relays Relay replaced M/B40203 ltr NARD0C1, P B , TUCKER-H B Duke Power Co 84/02/03, D'REILLY, J P Region 2: Dfice of Director 2pp 22229 357, 24X Fiche 50-370,84/02/03,8402140184
- 8402280507 LER 83-092/03L-O on 831231 during RCB draining operations, RHR pump 8 observed to have zero discharge flow & train 8 declared inoperable Caused by procedural deficiencies Flow restored H/B40208 ltr
 NARDOCI,P B : TUCKER,H B Duke Power Ca 84/02/08 D'REILLY, J.P. Region 2, Office of Director 2pp 22402-283 24X
 Fiche 50-370,84/02/08,8402280507
- 8402270117 RO 50-370/84-02, on 840115. Train A & D RHR pumps discovered w/o suction supply due to suction valves inadvertently closed Cause unknown. Investigation ongoing Rept will be submitted on 840226.

 TUCKER, H B Duke Fower Co. 84/02/14. Record Services Dranch (Document Control Desk) 1p 22391.261 24% Fiche 50-370.84/02/14. 8402270119
- 8402270304 LER 84-001-00 on 831231, RHR NP pump B observed to have zero discharge flow On 840109, computer alarm for NP pump A discharge pressure received. Caused by procedural deficiencies due to inadequate guidelines W/840215 ltr NARDOCI, P B , TUCKER, H B Duke Power Co. 84/02/15 5pp 223901233 24X Fichs.50-370,84/02/15,8402270304

U. Congressional/Executive Correspondence

- 8402240277 Responds to FOIA request for three categories of documents re facilities Forwards App A Documents 1-4. Documents 5-7 provided previously via svc list FELTON, J M. Division of Rules and Records 84/01/27 8UGARMAN.R Sugarman & Denworth 2pp 22394.298 24X Fiche 50-000.84/01/27, 8402240277.
- --8308090022 Forwards second quarterly status rept for 1983 on actions taken re-operating reactors & licensing revisus of new facilities ASBELBTINE, J. K. Commissioners B3/07/21 BEVILL, T. Hous Rep , Appropriations 11pp. 22374 300 24X Fiche 50-000, 84/01/27, 8402240277

- DOCKET 50-373 LASALLE COUNTY STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A:B & C documents FELTON.J H Division of Rules and Records 83/10/31 ROSENBAUH.D M Technical Analysis Corp 19pp 22193 292 24X Fiche 50-000.83/10/31.8402090003
- --8402090167 Trip rept of Caselond Forecast Panel 800326-2/ site visits re const status observation & const completion & fuel load schedules BOURNIA.A Light Water Reactors Branch 3 80/04/09 Light Water Reactors Branch 3 2pp 22195 013 24X Fiche 50-000,83/10/31,8402070003
- --8402090170 Responds to DH Hayes request for projected fuel load date evaluation Licensee projected fuel load date is 790701.while NRC Caseload Forecast Panel projects Dec 1979 as date KONKLIN.J E. NEISLER.J.H. Region 3. Chicago. Office of the Director 79702/13 KNDP.R C. Region 3. Chicago. Office of the Director 4pp 22190 015 24X Fiche 50-000.83/10/31.8402090003
- --8402090175 Trip rept of Caseload Forecast Panel sits visit re const status review & projected fuel load date Related info encl PELTIER, I A Light Water Reactors Branch i BOURNIAA Light Water Reactors Branch 3 78/08/09 Light Hater Reactors Branch 1 24pp 22175 020 24X Fiche 50-000.83/10/31.8402090003
- F Security, medical, emergency & fire protection plans
- B402270319 Revised emergency implementing procedures, including Rev 2 to Procedure LZP-1330-8. "Sampling Liquid Process Monitors Puring Liquid Monitor High Radiation Alarm Conditions " * Commonwealth Edison Co 83/07/01 7pp 22391 253 24X Fishe 50-373,83/07/01,8402270319.
- B402130191 Rev O to Emergency Plan Implementing Procedure EOF-17, "Emergency Operations Facility Activation Facility Log "BERLIN, N D Commonwealth Edison Co 83/09/23 3pp 22197 283 24X Fiche. 50-7000:63/09/23.8402130171
- B402130215 Rev O to Emergency Plan Implementing Procedure EOF-18, "Nuclear Station Div Non-Edison Transportation Incident Assistance Procedure" # Commonwealth Edison Co 83/09/27 5pp 28204 078 24% Fiche 50-000,83/09/27,8402130215
- 8402100137 Revised emergency plan implementing procedures, including Procedures EPIP EOF-17 re emergency operations facility activation log, EPIP CC-12 re sys power dispatcher & EPIP EOF-12 re access control. W/840203 memo & receipt form MODRER D Commonwealth Edison Co. 83/11/09 DENTON, H R NRC No Detailed Affiliation Given 24pp 22181-288 24x Fiche: 50-000, 83/11/09, 8402100137
- 8402130220 Rev 8 to Emergency Plan Implementing Procedure CC-12, "Sys Power Dispatcher,"
 MDDRE,R.D Commonwealth Edison Co 83/11/09 11pp 22200:108
 24X Fiche 50~000.83/11/09,8402130220
- 8402130358 Rev 2 to Generating Station Emergency Pien Implementing Procedure EGF-12, "Access Control to Emergency Operations Facility " W/831108 Itr & receipt form.
 MORE, R.D. Commonwealth Edison Co. 83/11/30 5pp. 22242,358 24X Fiche 50-000,83/11/30,8402150388
- 8402020162 Requests meeting to discuss NRC position re-fire protection reviews per IE Insp Regts 50-373/83-44 & 50-374/83-38 Imposed requirements for discussion listed Util position encl.

 REED.C. Commonwealth Edison Co 84/01/27 DENTON.H R. Diffice of Nuclear Reactor Regulation, Director 8pp 22056-135 24X Fiche 50-373,84/01/27,8402020162
- 8402060446 Forwards Rev 9 to Emergency Plan Implementing Procedure CC-1, "Corporate Commans Ctr Director." Recovery manager priority notification table encl MODRE, R. D. Commonwealth Edison Co. 84/01/30 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 22083 129, 24X Fiche: 50-000,84/01/30,8402040446
- --8402060464 Rev 9 to Emergency Plan Implementing Procedure CC-1, "Corporate Command Ctr Director," controlled capy MODRER D. Commanusalth Edison Co 83/11/30 76pp 22083:131 24X Fiche 50-000,84/01/30,8402060446

- 8402030315 Ack receipt of FEMA 840106 final exercise evaluations of offsite emergency preparadness exercise on 830712 Deficiencies noted do not detract from overall ability to protect public in event of radiological emergency PAFERIELD, C. J. Region 3, Office of Director 84/01/31 REED, C. Commonwealth Edison Co. 2pp. 22089 261 24X Fiche 50-373,64/01/31,8402030315
- 8402140039 Revised emergency plan implementing procedures, including Rev 3 to LZP-1330-23. "Determination of Reactor Coolant pH High Radiation Sampling Sys" & Rev 1 to LZP-1370-3, "First Aid Contaminated Casualties" commonwealth Edison Co 84/02/02 40pp 22274 204 24X Fiche 50-373,84/02/02,8402160039
- 8402170410 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR BCHWENCER, A Licensing Branch 2 84/02/09 FARRAR, D L Commonwealth Edison Co 2pp 22313 174 24X Fiche 50-373, 84/02/09, 8402170410
- 8402210251 Forwards deviation rept history for diesel firm pumps from B20417 to 840101, per B31123 commitment Rept meets requirements of Lisense Condition 2 C (15) (F) SCHROEDER, C W Commonwealth Edison Co 84/02/09 DENTON, H R Office of Nuclear Reactor Regulation. Director 27pp 22316 031 24X Fiche 50-373,84/02/09,8402210281
- 8402280395 Revised emergency plan implementing procedure, including Riv 1 to BZP 600-A4. "GEEP Telephone Directory " + Commonwealth Edison Co 84/02/18 61pp 22404 158 24X Fiche 50-000.84/02/18,8402280395
- 8402290074 Forwards evaluation of station fire protection water distribution & standpipe sys, in response to 831216 License NPF-18.CW Schroeder 831123 ltr & IE Insp Repts 50-373/83-44 & 50-374/83-48 Rept closes listed items SCHMENCER.A Commonwealth Edison Co 84/02/22 DENTON.H. R Office of Nuclear Reactor Regulation. Director 3pp 22417 001. 24X Fiche 50-373,84/02/22.8402290074
- --8402290078 "Evaluation of LaBalle County Station Fire Protection Water Distribution & Standpipe 80; " * Commonwealth Edison Co 6854-31 84/02/29 800pp. 22417 004 24X Fiche 50-373,84/02/22,8402290074
- 8402270266 Forwards complete FEMA final exercise rept of 830712 radiological emergency preparedness exercise PAPERIELLO, C. J. Region 3, Office of Director 84/02/23 REED, C. Commonwealth Edison Co. 1p 22386.069 24X Fiche 50-373, 84/02/23.
- I Financial inversition

ĺ

- 8402250410 Annual Financial Rept 1983 W/840221 1tr. 0'CONNOR, J J Commonwealth Edison Co 83/12/31 29pp 22407 101 24X Fiche 50-000.83/12/31,8402280410
- P Operating license stage documents & correspondence
- 8402100005 Partial response to FOIA request for documents prepared by Ofc of Investigation re Zack Co.Forwards App A documents Documents also being placed in PDR. Info partially withheld (ref FOIA Exemption 6)
 FELTON.J M Division of Rules and Records. 83/11/28 PERRY.R A Affiliation Not Assigned 7pp 22206 002. 24%
 Fichs 50-000.83/11/28,8402100005
- --8402100040 Forwards audit trend analysis rept Vendor requested to respond to trends identified within summary & conclusion, indicating corrective actions to prevent reoccurrence Dates when corrective actions will be completed also requested QUAXA, T. E. Commonwealth Edison Co. 80/08/20 THOMPSON, E. Zect. Co. ip 22206, 126 24% Fiche 50-000, 83/11/28, 8402100005.
- --8402100042 "Audit Trend Analysis " Related info enc1 * Commonwealth Edison Co 80-402 80/08/18 153pp 22206 127 24% Fichs 50-600,83/11/28,8402100005
- B312120029 Generic Ltr B3-39 to representatives of utils re voluntary survey of licensed operators Svc list encl EISENHUT.D. 9 Division of Licensing B3/12/08 Commonwealth Edison Co 12pp 22313.006 24X Fiche 50-000.83/12/08.8312120029

- B312120110 Board Notification 84-001 forwards EM Ongol B31127 petitions for emergency relief & NRR B31216 ack ltr Petitions allege inadequacy in conduct of integrated leak rate testing NGVAK, T M Assistant Director for Licensing 84/01/12 Atomic Bafaety and Licensing Board Panel 3pp 22012 323 24X Fichs: 50-000.84/01/12.8312120110
- --8312220267 Petition for emergency relief concerning unsafe conditions re integrated leak rate testing for US nuclear power reactor containments Bevere errors, defects & loopholes exist in current methodology OCOOL.E M Affiliation Not Assigned 83/11/29 PALLADINO, N Commissioners 4pp 22012 326 24X Fiche 50-000,84/01/12, 221213010
- --8312220269 Patition for emergency relief re primary containment leak rate at facilities Unsafe condition exists re ability of primary containment to fulfill design function QQQOL,E M Affiliation Not Assigned 83/11/29 KEPPLER, J G. Region 3, Office of Director 4pp. 22012 334 24X Fiche 50-000,84/01/12,8312120110
- B402090290 Forwards unsigned offsite notification forms, Set 96-105, for controlled procedure manual, returned to util. Seamonwealth Edison Co. 84/01/16. Office of Nuclear Reactor Regulation, Director Spp. 22157 350 24X Fiche 50-373, 84/01/16.8402090290
- B4020700&6 Forwards Amend 15 to License NPF-11 & safety evaluation Amend exempts applicability of Tech Spec 3 0 4 when control rod inoperable for causes other than being stuck. BCHMENCER, A Licensing Branch 2 84/01/17 FARRAR, D L. Commonwealth Edison Co. 2pp 22141.107 24X Fiche 50-373,84/01/17.8402070066
- --B402070071 Amend 15 to License NPF-i1, exempting provisions of Tech Bpec 3, 0.4 when control rod inoperable for causes other than being stuck SCHWENGER.A. Licensing Branch 2 84/01/17 5pp 22141:109 24X Fiche:50-373,84/01/17,8402070066
- --8402070076 Safety evaluation supporting Amend 15 to License NPF-11
 * Office of Nuclear Reactor Regulation, Director 84/01/17 2pp.
 22141:114 24% Fiche 50-373,84/01/17,8402070066
- 8402130245 Forwards FR notice of consideration of issuance of amend to facility DL & proposed NBHC determination & opportunity for haaring reflect Bpec changes concerning requirements for fast starts on diesel generators

 8CHMENCER, A Licensing Branch 2 84/01/27. FARRAR, D L
 Commonwealth Edison Co 2pp 22216-265 24X Fiche 50-373, 84/01/27, 8402130245
- --8402130254 Notice of consideration of issuance of amend to License NPF--11 & proposed NSHC determination & opportunity for hearing.

 SCHMENCER, A Licensing Branch 2 84/01/27 ip 22216-267. 24X Fiche: 50-373,84/01/27,8402130245
- 8402210265 Bubmits info re primary containment isolation following reset of isolation signals per 831128 & 1207 ltrs. Valves to be modified prior to startup after first refueling outage listed.

 80:HRDEDER, C. W. Commonwealth Edison Co 84/02/04 DENTON, H R. Office of Nuclear Reactor Regulation. Director. 2pp 22314 355 24X Fiche 30-373.84/02/04.8402210265
- 8402:30428 Provides results of drywell thermal measurements program w/sensible heat present Drywell air flow settings produced acceptable temps w/augmented air ducted into upper drywell regions. Bulk temp remained acceptable.

 8CHROEDER.C. W. Commonwealth Edison Co. 84/02/07, KEPPLER.J G Region 3. Office of Director. Spp. 22202 073. 24X
 Fiche: 50-373:84/02/07,8402130428.
- 8402140205 Forwards response to Generic Ltr 83-34 requesting licensees to submit Tech Specs or schedule for NUREO-0737 items scheduled after 811231. All appropriate Tech Spec amend requests will be submitted by 840815.

 BARNES, P.L. Commonwealth Edison Co. 84/02/07, DENTON, H.R. Office of Nuclear Reactor Regulation, Director 9pp 22229 341. 24% Fiche: 50-000, 84/02/09, 8402140205.
- 8402210450 Act receipt of 84010A addendum to petition for emergency relief citing 830707 F0IA request for all documentation re integrated leak rate testing at LaSalle & Byron Ltr being treated as supplemental F0IA request Meeting summary encl DENTON. H R. Office of Nuclear Reactor Regulation, Director 84/02/09. G6001.E.M. Affiliation Not Assigned ip 22344 014. 24X Fiche: 50-000, 84/02/09. 8402210450

- --8402210457 Summary of B40104 meeting w/I Reytblatt at plant re available data base for 10CFR50.App J containment integrated look tests BCHWENCER.A Licensing Branch 2 84/01/17 Licensing Branch 2 5pp 22344 016 24X Fiche 50-000.B4/02/09.B402210450
- B402210253 Informs that request for amend to License NPF-11 incomplete w/respect to compliance w/requirements of 10CPR30 91 Resubmittal of request required per B40209 discussion BCHMENCER. A Licensing Branch 2 B4/02/15 FARRAR. D L. Commonwealth Edison Co. 2pp 22343 249 24X Fiche 30-373,84/02/15.8402210233
- O Inspection reports. IE Bulletins & correspondence
- 8402070215 Forwards IE Insp Rept 50-373/84-01 on 840110 No noncompliance noted LITTLE,W S Region 3. Office of Director 84/01/23 REED.C Commonwealth Edison Co 2pg 22101 170 24X Fiche 50-373,84/01/23,8402070215
- --8402070216 IE Insp Rept 50-373/84-01 on 840110 No noncompliance noted Major areas inspected repairs made to pipe restraints in response to damage caused by water hammer as reported in LER 83-120/03L-0 MUFFETT, J W , O'DHYER, Q F , DANIELSON, D H Region 3, Office of Director, 84/01/20 2pp 22101 172 24X Fiche 50-373.84/01/23.8402070215
- B312120153 IE Info Notice 84-04, "Steam Binding of Auxiliary Fredwater Pumps" Byc list enci JORDAN, E L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120153
- 8402020162 Requests meeting to discuss NRC position re fire protection reviews per IE Insp Repts 50-373/83-44 & 50-374/83-38 Imposed requirements for discussion listed Util position encl
 REED.C Commonwealth Edison Co 84/01/27 DENTON.HR Diffice of Nuclear Reactor Regulation. Director Spp 22056 135 24% Fiche. 50-373,84/01/27,8402020162
- 8402170207 Forwards IE Insp Repts 50-373/83-53 & 80-374/83-56 on B31217-840113 & notice of violation 84/87-8401/30 REED,C Commonwealth Edison Co 2pp 22276 340, 24X Fiche 50-373,84/01/30,8402170207
- --B402170211 Notice of violation from insp on 831217-B40113. SHAFER, W D Region 3, Office of Director 84/01/30 2pp 22294 342 24K Fiche 50-373.84/01/30,8402170207
- ---B402170242 IE insp Repts 50-373/83-53 & 80-374/83-56 on B31217-B40113
 Violations noted, failure to update control room tag board
 following completion of individual steps on nuclear
 component transfer list during Unit 2 fuel load.
 GULDEHOND, M., GUTHRIE, B., EVANE, D. Region 3, Office of Director
 B4/01/30, 15pp 22296 344 24X Fiche, 50-373,84/01/30,8402170207
- 8401170016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excass Controls " Byo list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co. of New York, Inc 117pp 22114 179 24X Fiche. 50-000, 84/02/03, 840;190016
- 8401170017 IE Bullstin 84-01, "Cracks in BWR Mark I Containment Vent Headers." Svc list encl DEYQUNG.R.C. Director's Office, Office of Inspection and Enforcement. B4/02/03 Consolidated Edison Co. of New York, Inc 102pp. 82177 156 24% Fiche 50-000.84/02/03,8401170017
- 8402230364 Ack receipt of 840118 ltr & payment of civil penalties proposed in 840118 ltr AKELRAD.J.A Director's Office, Office of Inspection and Enforcement 84/02/08 O'CONNOR.J J Commonwealth Edison Co 2pt 22376.241 24X Fichs 50-373,84/02/08,8402230364
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Inaps of Fire Protection Safe Shutdown Sys (100FR30, App R) " Syc list and JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York Inc 124pp 22965 239, 24X Fichs 30-000.84/02/13,8401190041
- 8401190039 IE Info Notice 84-08, "10CFR50.7, 'Employee Protection'"
 Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc. 115pp 22365 141 24X Fiche 50-000.84/02/14,8401190039

- 8401190045 IE info Notice 83-63, Suppl 1, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl JURDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc 118pp 22366 142 24% Fiche 50-000,84/02/15,8401190045
- 8402220266 Ack receipt of 840210 ltr informing NRC of steps taten to correct violations noted in IE Imap Repts 50-373/83-51 & 30-374/83-50 STREETER, J F Region 3, Office of Director 84/02/15 REED.C Commonwealth Edison Co 1p 22334 349 24X Fiche 50-373,84/02/15.
- ~-8402220270 Responds to NRC 840113 ltr re violations noted in IE Insp Repts 50-373/83-51 & 50-374/83-50 Corrective actions Test Procedure LTS 300-3 will be revised to require test engineer to review flow recording after specified test FARRAR: B L. Commonwealth Edison Co. 84/02/10 KEPPLER: J Q Region 3. Office of Director 2pp 22334 350 24X Fiche 50-373.84/02/15.8402220266
- 8402220410 Ack receipt of 840131 ltr informing NRC of steps taken & planned in response to 831128 confirmatory action ltr. Item E re ethylene-propylene seats on feedwater check valves SPESSARD.R L Division of Engineering 84/02/17 REED.C Commonwealth Edison Co ip 22940 189 24X Fiche 50-373,84/02/17,8400200410
- --B40222041& Responds to NRC B31128 confirmatory action ltr re soft seats inboard feedwater check valves URL-F010 A & B Planned actions Dupont Kalrer & Perker Seal Aflas considered for testing as alternate matls
 BCHROEDER.C W Commonwealth Edison Co B4/01/31 KEPPLER.J 0
 Region 3. Office of Director 2pp. 22340 170 24X
 Fiche 50-373,84/02/17.8402220410
- 8402270147 Ack receipt of 840203 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/83-49 & 50-374/83-32 SHAFER, W D Region 3, Office of Director 84/02/17 REED, C Commonwealth Edison Co Ip 22087 345 24X Fiche 50-373,84/02/17,840027147
- --B402270133 Responds to NRC B40105 ltr re violations noted in IE Insp Repts 50-373/83-49 & 50-374/83-52 Corrective actions Procedures LOB-NR-N1 & LOB-NR-H2 inserted into general station surveillance program & verified FARRAR, D L. Commonwealth Edison Co. B4/02/03 KEPPLER, J G Region 3. Office of Director. 3pp. 22387 346 R4X Fiche 50-373,84/02/17,8402270147
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value" Svc list encl JQRDANE L. Division of Emergency Preparedness & Engineering Tesponse (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc. 114pp 22366 024 24X Fiche, 50-000, 84/02/21, 8401190062
 - 02240144 Forwards rev to baseline insp rept per ASME Code, Section XI lev addresses insp of hangers & supports to elements as part of preservice insp rept 3GHRGEDER, C W Commonwealth Edison Co 84/02/22 DENTUN, H R Dffice of Nuclear Reactor Regulation, Director 33pp 22375.038 24X Fich 50-373,84/02/22.8402240144
- 02270279 Forwards addendum to IE Insp Rept 50-373/83-40 dtd 831104, consisting of analyses of beta emitters in liquid sample collected during insp Open Item 4 closed PAPERIELLO.C J Region 3. Office of Director 84/02/22 REED.C Commonwealth Edison Co ip 22391 311. 24% Fiche 50-373.84/02/22.8402270279
- -8402270286 Addendum to IE Insp Rept 50-373/83-40 dtd 831103.consisting of comparative analyses of beta emitters in liquid sample taken during insp * Region 3. Office of Director 84/02/22 Ep 22391 312 24X Fiche 50-373,84/02/22.8402270279
- 8402290074 Forwards evaluation of station fire protection water distribution & standpipe sys, in response to 831216 License NPF-18, CM Schroeder 831123 ltr & 1E Insp Repts 50-373/83-44 & 50-374/83-48 Rept closes listed items BCHMENGER, A. Commonwealth Edison Co 84/02/22 BENTON, H R Office of Nuclear Reactor Regulation, Director, 3pp 22417 001 24% Fichs 50-373,84/02/22,8402270074
- --8402290078 "Evaluation of LaBalle County Station Fire Protection Water Distribution & Standpipe Sys " * Commonwealth Edison Co 6854-31, 84/02/29 600pp 22417 004 24X Fiche 50-373,84/02/22,8402290074

- 8401190066 IE Info Notice 84-11. "Training Program Deficiencies "
 Svc list encl
 JORDAN E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000.84/02/24.8401190066
- 8401190067 IE Info Notice 84-12. "Failure of Soft Seat Valve Seals "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060 24X Fiche 50-000,84/02/27,8401190067
- S Reportable occurrences, LERs & related correspondence
- 8402030224 LER 83-195/03L-0 on 831229.util informed by Sargent & Lundy that engineering change notice forthcoming re overload bypass circuit design on RHR min flow bypass valves Mod immediately implemented & completed on 831230 W490123 Itr HOUSTON,R W. DIEDERICH.9 J Commonwealth Edison Co 84/01/23 KEPPLER,J G Region 3, Office of Director 3pp 22067 238 24% Fishe 50-373,84/01/23.840203024
- 8402220559 LER 84-001-00 on 840183, sample flow alarm annunciated following start of radwaste discharge. Caused by frozen line Line thawed out & proper flow verifies Procedures revised to verify proper flow during source check W/840125 ltr KLIKA, J C . DIEDERICH, 0 J Commonwealth Edison Co 84/01/25 5pp 2233 338 24X Fiche 50-373,84/01/25,8402220559
- 8402030217 LER 83-156/03L-0 on 831229, during LES-MS-101, MSIV 1821-F022A reactor protection limit switch 4 setpoint exceeded Tech Spec limits Cause undetermined Limit switch readjusted W/840127 ltr HOUSTON, R. W., DIEDERICH, O. J. Commonwealth Edison Co. 84/01/27 KEPPLER, J. O. Region 3, Office of Director. 3pp. 22067:225, 24% Fiche 50-373,84/01/27,8402030217
- BA02230347 Updates status rept on BMR pipe cracks & protection of upcoming licenses actions Insp results encl. Evaluation & recommendations re interim & long-term remedial measures expected by May 1984
 DIRCKB, H J Office of the Executive Director for Operations. SECY-84-009A 84/01/27 5pp 22377 047 24X Fiche 50-000. 84/01/27, 8402230347
- 8402080041 LER 84-002-00 on 840106, unit scrammed on low water level following trip of turbine driven reactor feed pump on high seal temp. Caused by failed flow controller which regulates seal water temp Controller replaced W/840202 ltr WESTPHAL, 8 S. DIEDERICH, 0 J. Commonwealth Edison Co 84/02/03 4pp 22132 147 24X Fiche 80-373,84/02/03,8402080041
- 8402160334 LER 84-003-00 on 840113, main generator tripped, resulting in reactor scram Caused by power/load unbalance Unit restarted w/o incident W/840206 ltr. SETTLES, A. DIEDERICH.O.J. Commonwealth Edison Co. 84/02/06. 3pp 22269-012 24X Fiche 50-373,84/02/06,8402160334
- 8402130352 Supplemental RO between 831216 & 840101.diesel generator rooms & U-2 Div i switchgear room temp outside Tech Spec limits. Caused by leakage around exhaust ducts & failure of outside air suction damper Temps returned to normal DIEDERICH.O J Commonwealth Edison Co. 84/02/08 KEPPLER.J @ Region 3. Office of Director 3pp. 22242 352 24X Fiche 50-373,84/02/08.8402150352
- 8402150376 RO on 840111-13 & 21-23, diesel generator O,1A, & 18 room tamps discovered outside Tech Spec limits. Between 840109-13, switchgear Div I room tamps outside Tech Spec limits Gaused by use of addl heaters & failed damper-respectively DIEDERICH, O J Commonwealth Edison Co 84/02/08 KEPPLER, J Q. Region J. Office of Director 3pp 22242 008 24X Fiche 50-373,84/02/08.8402150376
- 8402210251 Forwards deviation rept history for diesel fire pumps from 920417 to 940101.per 831123 commitment Rept meets requirements of License Condition 2 C (15) (F).

 8CHROEDER: C W Commonwealth Edison Co. 84/02/07 DENTON, H R.

 Defice of Nuclear Reactor Regulation, Director. 29pp. 22316'001.

 24X Fichs 50-373,84/02/09,8402210251
- --8402210257 RO on 820623 during diesel fire pump weekly surveillance, diesel fire pump 08 observed to have "pegged high" temp indication Open svc water tie valves maintained fire protection sys Caused by failed solenoid operated valve. HOLYDAK, R H Commonwealth Edison Co. 82/07/06 KEPPLER, J G. Region 3. Opice of Director 1p 22316.030 24X Fiche 50-373,84/02/09.8402210251

- --B402210261 RD on 831004, diesel fire pump OB Jacket water coolant observed to have high temp Open svc water tie valvos maintained fire protection sys Caused by operator not in continuous attendance at control switch DIEDERICH.0 J Commonwealth Edison Ca 83/10/21 KEPPLER, J O Region 3, Office of Director 1p 22316 032 24X Fiche 30-373,84/02/07.8402210251
- 8402220001 LER 84-004-00 on 840118, reactor bldg ventilation sys shut down fallowing receipt of Unit 2 primary containment isolation signal Caused by accidental movement of relay 2821H-K66 by const personnel W/840210 ltr DIEDERICH, 0 J Commonwealth Edison Co 84/02/10 3pp 22337 303 24X Fiche 50-373,84/02/10,8402220001
- 8402220049 PNO-III-84-015 on 840213, unit tripped as result of low condenser vacuum Caused by failure of feedwater heater 14A extraction steam expansion joint Unit will be brought to cold shutdown & repairs completed GULDEMOND, W., WALKER, R. Region 3, Office of Director 84/02/13 p. 22334 362 24X Fiche 50-373,84/02/13,8402220049
- 8402220557 PNO-III-84-016 on 840213, while at 90% power, unit tripped Caused by feedwater heater 14A extraction steam expansion joint failure, resulting in low condenser vacuum Repairs scheduled for cold shutdown GULDEMOND, W. MALKER, R. Region 3, Office of Director 84/02/13 ip 22333 132 24% Fiche 50-373, 84/02/13, 8402220557
- 8402220284 LER 84-005-00 on 840116, reactor protection sys initiated reactor scram when turbine generator tripped due to low vacuum caused by ruptured rubber boot seal Boot seal replaced & extraction steam line capped W/840215 ltr HEBTPHAL, 8 S. DIEDERICH, 0 J. Commonwealth Edison Ca 84/02/15 Spp 22337 048 24X Fiche 50-373,84/02/15,8402220284
- 8402220013 RO on 840119; insps of electrical sealed fire penetrations not completed Caused by new acceptance criteria established during Unit 2 license review & imposed upon Unit 1 electrical firestops during 18-month surveillance DIEDERICH, 0 J Commonwealth Edison Co 84/02/16 KEPPLER, J Q Region 3, Office of Director. 1p 22338-247 24X Fiche 50-373.84/02/16.6402220013
- 8402220176 LER 84-006-00 on 840121 during startup APRM channels B & F read lower than expected Caused by defective operational amplifiers in four APRM channels due to normal aging Amplifiers replaced W/840217 ltr.

 WILBON, L. B , DIEDERICH, G J Commonwealth Edison Co 84/02/17 3pg 22340 307 24X Fiche 50-373,84/02/17,8402220176

U Congressional/Executive Correspondence

- 8402290002 Responds to FOIA request for correspondence NRC received from Benators J McClure, JB Johnston & P Laxalt during past 2 yrs Forwards App A documents Name of individual deleted from Documents B & 9 of App A (ref FOIA Exemption 6) FELYON, J M Division of Rules and Records 83/11/30 KOLL, E Cable News Network, Inc App 22438 002 24X Fiche 50-000, 83/11/30.8402290002
- --9402270163 Informs that Region III completed investigation into allegations re const inadequacies No technical issues remain to preclude operation above 0% power KAMMERER, C Office of Congressional Affairs 92/07/23 OTTINGER, R. L House of Rep . Energy & Commerce BEVILL, T House of Rep . Appropriations HATFLELDM Senate, Appropriations ip 22438:044 24X Fiche. 50-000,83/11/30,8402270002

DOCKET 50-374 LABALLE COUNTY STATION, UNIT 2

A Application/construction stage documents & correspondence

- 8402090003 Responds to FDIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings. Forwards App A.B & C documents.
 FELTON.J.M Division of Rules and Records 83/10/31 ROSENBAUM.D M Technical Analysis Corp 19pp 22193 292 24X Fiche 50-000.83/10/31.8402090003
- --B402090167 Trip rept of Caseload Forecast Panel 800326-27 sits visits re const status observation & const completion & fuel load schedules.

 BOURNIA, A Light Water Reactors Branch 3 80/04/07 Light Water Reactors Branch 3. 22193-013 24X
 Fiche: 30-000, 83/10/31,8402090003

- --B402090175 Trip rept of Caseload Forecast Panel site visit re const status review & projected fuel load date Related info encl PELTIER, I A Light Water Reactors Branch 1 78/08/09 Light Water Reactors Dranch 1 24pp 22195 020 24X Fiche 50-000,03/10/31,8402090003
- 8402100005 Partial response to FOIA request for documents prepared by Ofc of Investigation re Zack Co Forwards App A documents Documents also being placed in PDR Info partially withheld (ref FOIA Exemption 6)
 FELTON, J M Division of Rules and Records 83/11/28 PERRY, R A Affiliation Not Assigned 7pp 22206 002 24X
 Fiche 50-000, 83/11/28, 8402100005
- --E402100040 Forwards audit trend analysis rept Vendor requested to respond to trends identified within summary & conclusion, indicating corrective actions to prevent reoccurrence Dates when corrective actions will be completed also requested QUAKA, T E Commonwealth Edison Co B0/08/20 THOMPSON, E Zack Co 1p 22206 126 24x Fiche 50-000,83/11/28,8402100005
- --8402100042 "Audit Trend Analysis " Related info encl * Commonwealth Edison Co 80-402 80/08/18 183pp 22206 127 24X Fiche 50-000,83/11/28,8402100005
- F Security, medical, emergency & fire protection plans
- 8402270319 Revised emergency implementing procedures, including Rev 2 to Procedure LZP-1330-8, "Sampling Liquid Process Monitors During Liquid Monitor High Radiation Alarm Conditions " * Commonwealth Edison Co 83/07/01 7pp 22391 293 24X Fiche 50-373.83/07/01,8402270319
- 8402130171 Rev O to Emergency Plan Implementing Procedure EOF-17.
 "Emergency Operations Facility Activation Facility Log "
 BERLIN.M D Commonwealth Edison Co 83/09/23 3pp 22179 283
 24X Fiche 50-000, 83/09/23, 8402130191
- 8402130215 Rev O to Emergency Plan Implementing Procedure EOF-18, "Nuclear Station Div Non-Edison Transportation Incident Assistance Procedure" * Commonwealth Edison Co 83/09/29 5pp 22204 078 24X Fiche 50-000,83/09/27,8402130215
- B402100137 Revised emergency plan implementing procedures, including Procedures EPIP E0F-17 re emergency operations facility activation log, EPIP CC-12 re sys power dispatcher & EPIP E0F-12 re access control W/840203 memo & receipt form MODRE, R D Commonwealth Edison Co 83/11/09 DENTON, H R NRC No Detailed Affiliation Given 24pp 22181 288 24X Fiche, 50-000, 83/11/09, 8402100137
- 8402130220 Rev 8 to Emergency Plan Implementing Procedure CC-12. "Sys Power Dispatcher" MODRER D. Commonwealth Edison Co 83/11/09 11pp 22200 108 24X Fichs 50-000, 83/11/09, 8402130220
- 8402150358 Rev 2 to Generating Station Emergency Plan Implementing Procedure EOF-12: "Access Control to Emergency Operations Facility "W/831108 ltr & receipt form MOURE, R D Commonwealth Edison Co 83/11/30 5pp 22242 358 24: Fiche 50-000, 83/11/30, 8402150358
- E402020162 Requests meeting to discuss NRC position refire protection reviews per IE Insp Repts 50-373/83-44 & 50-374/83-36 Imposed requirements for discussion listed Util position encl
 REED.C Commonwealth Edison Co 84/01/27 DENTON, H R Office of Nuclear Reactor Regulation, Director Bpp 22056 135 24X Fiche 50-373,84/01/27,8402020162
- 8402060444 Forwards Rev 9 to Emergency Pian Implementing Procedure CC-1, "Corporate Command Ctr Director " Recovery manager priority notification table and HODRE,R D Commonwealth Edison Co 84/01/30 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22083 127 24X Fiche 50-000,84/01/30,8402060446
- --B402060464 Rev 9 to Emergency Plan Implementing Procedure CC-1, "Corporate Command Ctr Director," controlled copy MOORE,R D. Commonwealth Edison Co 83/11/30 76pp 22083 131 24X Fiche 30-630,84/01/30,8402060446
- B402030315 Ack receipt of FEMA 840106 final exercise evaluations of offsits emergency preparedness exercise on 830712 Dafficiencies noted do not detract from overall ability to protest public in event of radiological emergency PAPERIELLO.C J. Region 3. Office of Director 84/01/31 REED, C Commonwealth Edison Co. 2pp 22089 261 24X Fiche 50-373.84/01/31.8402030315

- 8402140039 Revised emergency plan implementing procedures, including Rev 3 to LZP-1330-23. "Dotermination of Reactor Coolent pH High Radiation Sampling Sys" & Rev 1 to LZP-1370-3. "First Aid Contaminated Casualities"
 * Commonwealth Edison Co 84/02/02 40pp 22274 204 24X Fiche 50-373.84702/02.8402140039
- 8402170410 Advises that NRC will not review emergency plans to delete privaty or proprietory info unless specifically requested by licensee.per 810707 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR SCHWENCER.A Licensing Branch 2 84/02/09 FARRAR, D L Commonwealth Edison Co 2pp 22313 174 24X Fiche 50-373,84/02/09.8402170410
- 8402210251 Forwards deviation rept history for diese; fire pumps from 820417 to 840101.per 831123 commitment Rept meets requirements of License Condition 2 C (15) (F) 8CHRDEDER,C M Commonwealth Edison Co 84/02/09 DENTON,H R Office of Nuclear Reactor Regulation. Director 29pp 22316 OO1 24X Fiche 50-373,84/02/09,8402210251
- 8402220409 Forwards Rev 1 to "Fire Pump Flow Test" & Attachments 1,2 & 3 indicating required actions per fire protection program Conditions 20(15)(a)-(d) addressed SCHROEDER:C W Commonwealth Esison Co 84/02/17 DENTON, H R Office of Nuclear Reactor Regulation. Director 7pp 22340 338 24X Fiche 50-374,84/02/17,8402220409
 - 8402220412 Rev 1 to "Fire Pump Flow Test" * Commonwealth Edison Co LTS-J000-34 R01 84/02/14 129pp 22341 003 24X Fiche 50-374.84/02/17.8402220409
 - 02280375 Revised emergency plan implementing procedure, including Rev I to BIP 600-A4, "GSEP Telephone Directory" * Commonwealth Edison Co 84/02/18 61pp 22404 i58 24X Fichs 30-000,84/02/18.8402280375
- B402270074 Forwards evaluation of station fire protection water distribution & standpipe sys.in response to B31216 License NPF-18.CW Schroeder B31123 ltr & IE Insp. Repts 50-373/83-44 & 30-374/83-48 Rept closes listed items SCHMENCER.A Communusalth Edison Co B4/02/22 DENTON.H R Dffice of Nuclear Reactor Regulation. Director 3pp 22417 001 24X Fiche 50-373.84/02/22.8402290074
- --8402290078 "Evaluation of LaBalle County Station Fire Protection Water Distribution & Standpipe Sys " * Commonwealth Edison Co 6834-31 84/02/29 800pp 22417 004 24X Fiche 30-373,84/02/22,8402290074
- 12270266 Forwards complete FEMA final exercise rept of 830712 adiological emergency preparedness exercise AFERIELLO, C J Region 3, Office of Director 84/02/23 REED, C commonwealth Edison Co ip 22386 069 24X Fiche 50-373, 84/02/23, 34022/0266

Financial information

- 402280410 Annual Financial Rept 1983 W/840221 ltr 0/CDNNOR.J J Commonwealth Edison Co 83/12/31 29pp 22407 101 24X Fiche 50-000.83/12/31.8402280410
- Insurance & indemnity information
- 3402020110 Forwards Endorsements 1 & 2 to MAELU Certificate M-B3 & Endorsements 1 & 2 to NELIA Certificate N-83
 OBTER, J Commonwealth Edison Co B4/01/26 BALTZMAN, J Assistant Director for State & Licensee Relations 5pp 22056 231 24X
 Fiche 30-374.84/01/26.8402020110
- P Operating license stage documents & correspondence
- 8312120029 Ceneric Ltr 83-39 to representatives of utils re voluntary survey of licensed pperators Svc list encl EISENHUT, D G Division of Licensing 83/12/08 Commonwealth Edison Co 12pp 22313 006 24X Fiche 30-000,83/12/08,8312120029
- 8312120110 Board Notification 84-001 forwards EM Gogol 831129 setitions for emergency relief & NRR 831216 ack ltr Petitions allege inadequacy in conduct of integrated leak rate testing NOVAK.T M Assistant Director for Licensing 84/01/12 Atomic 8afety and Licensing Board Panel 3pp 47138 186 24X Fiche 30-000,84/01/12,8312120110

- --8312220267 Petition for emergency relief concerning unsafe conditions re integrated leak rate testing for US nuclear power reactor containments Severe errors, defects & loopholes exist in current methodology GDGOL, E M Affiliation Not Assigned 83/11/27 PALLADINO, N Commissioners 4pp 22012 326 24% Fiche 50-000, 94/01/12, 9312120110
- ~~8312220269 Petition for emergency relief re primary containment leat rate at facilities Unsafe condition exists re ability of primary containment to fulfill design function GUGDL.E M Affiliation Not Assigned 83/i1/29 KEPPLER.J o Region 3. Office of Director 4pp 22012 334 24X fiche.50-000.84/01/12.8312120110
- 8402070270 Forwards unsigned offsits notification forms. Bet 76-103, for controlled procedure manual, returned to util # Commonwealth Edison Co 84/01/16 Office of Nuclear Reactor Regulation. Director 8pp 22157 350 24X Fiche. 50-373, 84/01/16, 84/0090
- 8402070151 Forwards P&ID & electrical drawings,per 831214 telcon recentrol rod drive charging water low pressure scram Both physical separation & electrical independence established hemispherically.

 8CHROEDER: C W Commonwealth Edison Co 84/02/04 DENTON,H R Office of Nuclear Reactor Regulation, Director 9pp 22100 011 24X Fiche 50-374,84/02/04,8402070151
- 8402210263 Submits info re primary containment isolation following reset of isolation signals, per 831128 & 1207 Itrs Valves to be modified prior to startup after first refueling outage listed SCHROEDER, C. W. Commonwealth Edison Co. 84/02/04 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 22314 355, 24% Fiche 50-373, 84/02/04, 8402210265
- 8402140205 Forwards response to Generic Ltr 83-36, requesting licensees to submit Tech Specs or schedule for NUREG-0737 items scheduled after B11231, All appropriate Tech Spec amend requests will be submitted by 840815

 BARNES, P. L. Commonwealth Edison Co. 84/02/09, DENTON, H.R. Office of Nuclear Reactor Regulation, Director 9pp. 22229 341

 Fiche: 50-000, 84/02/09, 8402140205
- B402210450 Ack receipt of B40106 addendum to petition for emergency relief citing B30707 FOIA request for all documentation re integrated leak rate teating at LaBelle & Byron Ltr being treated as supplemental FOIA request Meeting summary encl DENTON. H R Office of Nuclear Reactor Regulation, Director B4/02/07. G0GCL,E.M. Affiliation Not Assigned 1p. 22344.014 24% Fiche.50-000,84/02/07.8402210450
- --B402210457 Bummary of B40104 meeting w/Z Reytblatt at plant re available data base for 100FR50, App J containment integrated leak tests BCHMENCER.A. Licensing Branch 2 B4/01/17. Licensing Branch 2 Spp 22344 016 24X Fiche 50-000, 84/02/09, 8402210450.
- G. Inspection reports. IE Bulletins & correspondence
- B312120133 IE Info Notice 84-06, "Stwam Binding of Auxiliary Feedwater Pumps," Svc list enci JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103), 84/01/25 Consolidated Edison Co. of New York, Inc. 120pp. 22058,001. 24X Fiche 50-000,84/01/25,8312120153.
- 8402020162 Requests meeting to discuss NRC position re fire protection reviews per IE Insp Repts 50-373/83-44 & 50-374/83-38. Imposed requirements for discussion listed. Util position encl.

 REED. C. Commonwealth Edison Co 84/01/27 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 8pp. 22056, 135 24% Ficher 50-373-84/01/27.8402020162.
- B402170207 Forwards IE Insp Repts 50-379/83-53 & 50-374/83-56 on B31217-B40113 & notice of violation. BHAFER:W D. Region 3: Office of Director 84/01/30 REED.C. Commonwealth Edison Co 2pp. 22296 340. 24X Fiche.50-373:84/01/30: B402170207
- --8402170211 Notice of violation from insp on 831217-840113 SHAFER,W D Region 3, Office of Director. 84/01/30, 2pp. 22296:342 24X Fiche 50-373,84/01/30,8402170207
- --B402170242 IE Insp Repts 50-373/83-53 & 50-374/83-56 on B31217-840113. Violations noted failure to updata control room tag board following completion of individual steps on nuclear component transfer list during Unit 2 fuel load. GULDEMOND, W. GUTHRIE.S. EVANS.D. Region 3. Office of Director. B4/01/30 15pp. 22296 344 24X Fiche 50-373,84/01/30,8402170207.

- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vahicular Ercass Controls " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000, 84/02/03, 8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl
 DEYGUNG,R C Director's Office, Office of Inspection and
 Enforcement 84/02/03 Consolidated Edison Co of New York, Inc
 102pp 22177 136 24X Fiche 50-000,84/02/03,8401190017
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R) " Syc list encl
- enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259 24X Fiche 50-000,84/02/13,8401190041 Resonnse (Post 830103)
- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '" Styl list enci
 JORDANN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- 8401170045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Hestinghouse Type SA-I Differential Relays " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc 118pp 22366 142 24X Fiche 50-000,84/02/15,840119045
- B402220266 Ack receipt of B40210 ltr informing NRC of steps taken to Correct Violations noted in IE Insp Repts 50-373/83-51 & 50-374/83-50.

 STREETER.J.F. Region 3. Defice of Director 84/02/15 REED, C. Commonwealth Edison Co. 1p. 22334 349 24X Fiche 50-373,84/02/15. Commonwealth Edison Co 8402220266
- --8402220270 Responds to NRC 840113 ltr re violations noted in IE Insp Repts 50-373/83-51 & 50-374/83-50 Corrective actions Test Procedure LT8 300-3 will be revised to require test engineer to revise flow recording after specified test FARRAR.D L Commonwealth Edison Co 84/02/10 KEPPLER, J Q Region J, Office of Director 2pp 22334 350 24X Fichs: 50-373,84/02/15,8402220846
- 8402220410 Ack receipt of 840131 ltr informing NRC of steps taken & planned in response to 831128 confirmatory action ltr. Item E re ethylene-propulene seats on feedwater check valves BPESSARD.R.L. Division of Engineering 84/02/17 REED.C Commonwealth Edison Co. ip. 22340 189 24X Fiche 50-373,84/02/17. R402220410
- --84022204i6 Responds to NRC 831128 confirmatory action itr re soft seats inboard feedwater check valves 821-F010 A & B.Planned actions:Dupont Kairez & Panker Seal Aflas considered for testing as alternate matis

 8CHROEDER: C W Commonwealth Edison Co. 84/01/31 KEPPLER: J 0 Region 3. 0ffice of Director 2pp 22340.170. 24X

 Fiche 50-373:84/02/17:8402220410.
- 8402270147 Ack receipt of 840203 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/83-49 & 50-374/83-52. SMAFER, W D Region 3. Office of Director 84/02/17 REED, C Communealth Edison Co 1p 22387 345 24% Fiche 50-373,84/02/17,8402270147.
- ---B402270153 Responds to NRC B40104 ltr re violations noted in IE Insp. Repts 50-373/83-49 & 50-374/83-52 Corrective actions: Procedures LOB-NR-WI & LOB-NR-WI inserted into general station surveillance program & verified FARRAR.D.L. Commonwealth Edison Co. 84/02/03. KEPPLER, J G. Region 3. Office of Director. 3pp. 22387,346. 24X Fichs: 50-373,84/02/17,8402270147
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl. JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21. Consolidated Edison Go of New York, Inc. 116pp 22366.024. 24X Fiche.50-000.84/02/21.8401190062
- 8402290074 Forwards evaluation of station fire protection water distribution & standpips sys, in response to 831216 License NFF-1B.CW Behroeder 831123 ltr & IE Insp Repts 50-373/83-44 & 50-374/83-48, Rept closes listed items 8CHWENCER.A Commonwealth Edison Co 84/02/22 DENTON, H R of Nuclear Reactor Regulation, Director 3pp 22417 001. 2: Fiche: 50-373,84/02/22,8402290074

- 8408290216 Ack receipt of 831230 & 840202 ltrs informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-374/83-36 LITTLE.W S Region 3, Office of Director 84/02/23 REED,C Commonwealth Edison Co ip 28428 141 24X Fithe 50-374,84/02/23
- --B402290225 Provides addl info re violations noted in IE Insp Rept 50-374/83-36 in response to 840123 telcon Operations personnel performed periodic surveillance to check equipment condition & complete specified tests FARRAR.D L Commonwealth Edison Ca 84/02/02 KEPPLER.J 9 Region 3. Office of Director 2pp 22428 162 24X Fiche 30-374,84/02/23,8402290216
- --B402290232 Responds to NRC 830830 & 1021 ltrs re violations noted in JE Insp Rept 50-374/83-36 Corrective actions SBLC systemminations on terminal blocks in main control room & local panel will be reviewed FABRAR.D L. Commonwealth Edison Co. B3/12/30 KEPPLER, J & Region 3. OFFice of Director 5pp. 22428 164 24% Fiche 50-374,84/02/23,8402290216
- 8401190066 IE Info Notice 84-11. "Training Program Deficiencies "
 - OlifoOob IE into nuclea C.

 Svc list encl

 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24% Fiche 50-000.84/02/24.8401170065
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
- 8 Reportable occurrences, LERs & related correspondence
- 8408230347 Updates status rept on BWR pipe cracks & protection of upcoming licensee actions Insp results encl Evaluation & recommendations re interim & long-term remedial measures expected by May 1784
 DIRCKS, W J Office of the Executive Director for Operations SECY-84-009A 84/01/27 5pp 22377 047 24X Fiche 30-000, 84/01/27,8402230347
- 8408080055 LER 84-001-00 on 840105, during initial fuel loading, reactor acram occurred from intermediate range monitor (IRM) E Caused by instrument mechanic bumping into monitor cable & connector Investigation continuing W/840131 ltr DIEDERICH, Q L Commonwealth Edison Co 84/01/31 3pp 22128 072 24X Fichs 50-374,84/01/31,8402080055
- 8402150376 RD on 840111-13 & 21-23, diesel generator O.1A.& 18 room temps discovered outside Tech Baec limits. Between 840107-13, suitchgear Div 1 room temps outside Tech Bpec limits Caused by use of add heaters & failed damper.respectively DIEDERICH, G J. Commonwealth Edison Co 84/02/08 KEPPLER, J G Ragion 3, Office of Director 3pp 82242 008 84X Fiche 50-373.84/02/08.8402150376
- B402210251 Forwards deviation mept history for diesel fire pumps from B20417 to B40101, per B31123 commitment Rept meets requirements of License Condition R C (15) (F) BCHROEDER, C W Commonwealth Edison Co B4/02/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 27pp R2316 001 24X Fiche 50-373, B4/02/09, 8402210251
- 8402160284 LER 84-002-00 on 640113 reactor scram initiated spurious high intermediate range monitor (IRM) spike on Channel C Caused by loose IRM cable connector fittings IRM cable connectors will be replaced W/840210 ltr WESTPHAL, B S, DIEDERICH, G J Commonwealth Edison Co B4/02/10 app 20269 002 24X Fiche 50-374,84/02/10,8402140294

- DUCKET 50-382 WATERFORD GENERATING STATION, UNIT 3 A Application/construction stage documents & correspondence
- 8402240064 Forwards Amend 1 to CEN-239, Suppl 2, "Probabilistic Risk Assessment of Effects of PORVs on Depressurization & DHR." updating rept submitted 830627, in response to NRC 820327 request k/o ancl DRUNMOND, F J Louisiana Power & Light Co 83/09/20, KNIGHION, O W Licensing Branch 3 ip 22374 143 24X Fiche 50-382,83/09/20, 8402240064

- 8402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documents
 FELTON, J M Division of Rules and Records 83/10/31
 ROSENBAUM, D M Technical Analysis Corp 19pp 22173 292 24X
 Fiche 50-000,83/10/31,8402090003
- --7903230241 Recommends that review schedule be based on 810918 prospective decision date, which also should be used as basis for fuel load date Summary of 790228 telcon w/applicant encl
 BENEDICT,R A Light Water Reactors Branch 2 77/
 BERKUW.H N Division of Project Management 3pp
 Fiche 50-000.83/10/31.8402090003 79/02/28 22176 260 24X
- --8402090230 Handwritten notes, calculations & graphs re const activities & fuel load date preparation # NRC No Detailed Affillation Given. 78/09/19 | Itpp 22174 264 24X Fiche 50-000,83/10/31,8402090003
- --8402090238 Requests comments on encl draft rept of Caselpad Forecast Panel 810113-15 site visits re facility const status * NRC No Detailed Affiliation Given 81/01/27 NRC No Detailed Affiliation Given 8pp 22195:277 24X Fiche, 50-000, 83/10/31, 8402090003
- --8402090240 Trip rept of Caseload Forecast Panel 790925 site visit to review & discuss const progress Related info encl BENEDICT,R A Light Water Reactors Branch 2 79/11/30 Light Hater Reactors Branch 2 3pp 22196 237 24X Fiche 50-000,83/10/31.8402090003
- B408240:03 Responds to FOIA request for documents re B30714 inquiry team rept on facility QA allegations & insp & util response to rept Forwards App B documents App A & B documents available in PDR FELTON, J M Division of Rules and Records 83/12/09 Q/ Government Accountability Project 4pp 22394 172 24X Fiche 50-382,83/12/09.8402240153 GARDE, B P
- --8309300031 Requests assistance in identifying roles for NRR.IE & Region IV to complete review of Harstead Engineering Assoc.Inc 830919 rept. "Analysis of Cracks & Water Esepage in Foundation Hati"

 CHRISTEMBURY, E Hearings Division 83/09/22 EISENHUT.D G Division of Licensing 2pp 22394:197 24X Fiche: 50-382, 83/12/09,8402240133
- --8311140287 Informs that NRR has lead responsibility for coordination & development of NRC position on cracks & water seepage in foundation mat Review of matl to establish safety significance will be completed by 831115
 EISENHUT, D. G. Division of Licensing 83/10/28 CHRISTENBURY, E. Haarings Division 2pp 22394:199 24X Fiche: 50-382, 83/12/09, 8408240153
- --8402240163 Informs of B30620 teleph re GA info relayed to JK Jossten by R Ridenhour of Qambit Publications Ridenhour expressed concern that NRC knew about cracks in containment basemat MULEV, GA Office of Inspector & Auditor 83/06/22.

 CUMMINGS, J. Office of Inspector & Auditor. 1p 22394 183 24X Fiche 50-382,83/12/07.8403240153
- --8402240166 Forwards 830825 meeting agenda re issues in NRC 830804 ltr to util concerning GA concerns. CUMMINGS.J. J. Office of Inspector & Auditor 83/07/07. GARNER,D., MILHOAN,J., CHESTNUT, 9 NRC No Detailed Affiliation Given 10pp 22394.187 24X Fiche: 50-382,83/12/09,8402240153
- ---8402240170 "Compatibility of Large Mat Design to Foundation 102290170 "Company 11122y - - - - Conditions."

 Conditions."

 EMASI, J. L., LIU.P. C. Ebasco Services, Inc. (subs. of Enserch Corp.), 83/12/09, 56pp. 22394;219, 24X Fiche: 50-382,83/12/09,

- 8402140003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILK, S. J. Office of the Secretary of the Commission 83/12/14 Public Document Branch ip 22281 023 24% Fiche 50-000,83/12/14,
- --8402160012 Staff requirements memo re 830304 discussion/possible vote on contested issues in facility full power proceeding in Washington, DC CHILK, 6 J Office of the Secretary of the Commission 83/03/08 IERBE, J E Office of Policy Evaluations ip 22281 051 24% Fiche 50-000, 83/12/14, 8402160003
- 8402290198 Forwards Decision Mgt Co.Inc Jan 1984 "Rept on Waterford 3/ Qrand Oulf Study Prepared for State of LA PSC " LEDDICK,R S Louisiane Power & Light Co 84/01/10 COLLING.J.T Region 4. Office of Director ip 22419 189 24X Fiche 30-000.84/01/10.8402290198
- -8402270205 "Rept on Waterford 3/Grand Gulf Study Prepared for State of LA PSC LA PSC **
 Decision Management Co , Inc. 84/01/31 800pp, 22417 190 24X Fiche 50-000,84/01/10,8402290198
- 8402080507 Notification of 840126 meeting w/util % Ebasco in Bethesda, MD to discuss component cooling water to reactor coolant pump designs WILEDN.J H Licensing Branch 3, 84/01/17 KNIGHTON.G W, Licensing Branch 3 3pp 22174 045 24X Ficha 50~382.84/01/17,8402080509
- 8312120136 Board Notification 84-011 discusses NRC use of terms "important to safety" & "safety-related" EISENHUT. D 0 Division of Licensing 84/01/18 PALLADING Commissioners 72pp 22241 008 24X Fichs. 50-000, 84/01/18,
- B402160467 Forwards request for add1 info re core bypass flow to complete review of core design Info should be provided by 840217 840217 KNIGHT, 9 W Licensing Branch 3 84/02/01 LEDDICK, R. 8 Loui Power & Light Co 3pp 22302 163 24X Fiche 50-382,84/02/01,8402160467
- 8402100013 Informs that response to Item 4 5 1 of Generic Ltr 83-28 re reactor trip sys reliability (sys functional testing) provided in revised Procedure OP-903-006, "Manual Reactor Trip Test "
 COOK.K.W. Louisiens Power & Light Co 84/02/06. KNIOHTON, O. W Licensing Branch 3 1p 22182 154 24X Fiche 50-382, 84/02/06, 8402100013
- 8402100237 Forwards description of facility capability for assessing sequence of evapts & analog variable time history both pre- & post-trip, in response to Item 1 2 in Generic Ltr 83-28 CODK.K W. Louisiana Power & Light Co. 84/02/06 KNIGHTON, 0. W Licensing Branch 3 14pp. 22179, 296. 24X Fiche. 50-382, 84/02/06, 840210237
- 8402100243 Forwards response to Generic Ltr 83-28, Item 1.1 requesting description of program ensuring that unscheduled reactor shutdowns analyzed. Util employs post-trip review for diagnosing unscheduled reactor trips.

 GOOK, K. W. Louisians Power & Light Co. 84/02/06. KNIGHTON, 0 W Licensing Branch 3 10pp 22179.323 24X Fiche 50-382,84/02/06,8402100243.
- B402140261 Confirms agreement w/NRC re revised submittal schedule for taxic chemical survey results. Entire survey & subsequent analyses will be completed prior to fuel load. New survey will be conducted every 4 yrs COOK. K. W. Louisiana Power & Light Co. 84/02/07. KNIGHTUN, 9 W Licensing Branch 3. 1p 22228 316. 24X Fiche 50-382, 84/02/07, 8402140261
- 8402160106 Forwards rev to seismic qualification of equipment completion schedule Rev supercedes 830805 transmittel Minor questions will be resolved prior to fuel load, GOOK-K.W Louisiana Power & Light Co. 84/02/10. MNIGHTON.C.W. Licensing Branch S. 4pp 22275:269 24X Fiche: 50-382,84/02/10.8402160106
- B401190059 Board Notification 84-032 provides add1 info on environ qualification Submittal augments info in Board Notifications 84-004 & 84-007 EISENHUT.D 9. Division of Licensing 84/02/13 Atomic Safety and Licensing Board Panel. 10pp. 22314.204. 24% Fiche 50-000,84/02/13.8401190059

- 8402170235 Documents telcon w/Peranich re approval of extension request for submittal of independent safety engineering group rept of GA practices at facility Rept will be submitted by 840222 COOK, K W Louisiana Power & Light Co 84/02/15 DEYQUNG, R C Director's Office, Office of Inspection and Enforcement ip 22296 148 24% Fiche 50-382,84/02/15.8402170235
- 8401190068 Board Notification 84-033 provides "Sys Interaction Program," task action plan for Unresolved Safety Issue A-17 Distribution list encl EIBENHUT.D 0 Division of Licensing 84/02/16 PALLADIND Commissioners 8pp 22482 071 24X Fiche 50-000,84/02/16,
- B402220044 Forwards response to questions raised at 840117 meeting in Bethesda. MD re review of B31223 submittal on emergency feedwater control sys COOK. K W Louisiana Power & Light Co B4/02/16 KNIOHTON. G W Licensing Branch 3 App 22337 332 24X Fiche 50-382.84/02/16, 8402220044
- 8402220298 Summary of 840201 meeting w/util in Region IV ofc re steps taken to assure facility would be ready for fuel load per util schedule. Visugraphs encl JOHNSON.E H Region 4. Office of Director 84/02/16 COLLINS, J T Region 4. Office of Director 43pp 22336 073 24X Fiche 50-382,84/02/16,8402220298
- 8402220336 Forwards info re changes to component cooling water sys to ensure cooling to reactor coolant pump seals in event of inadvertent safety injection actuation signal Info includes summary.safety evaluation & marked-up FSAR pages COOK.K.W. Louisiana Power & Light Co 84/02/16 KNIGHTON.G W Licensing Brench 3 37pp 22333 155 24X Fiche 50-382.84/02/16.8402220536
- 8402230001 Responds to Generic Ltr 83-28. Item 4 i re reactor trip sys reliability No recommended breaker mods issued by GE Vendor interface being set up for reactor trip sys components in compliance w/Item 2 i COOK. K M. Louisiana Power & Light Co 84/02/14 KNIGHTON, C W Litensing Branch 3 ip 22361 303 24X Fiche 50-382, 84/02/16, 8402230001
- E402270648 Notification of 840228 meeting w/util & Ebasco in Bethesda, MD to review emergency feedwater control sys HILBON, J H Licensing Branch 3 84/02/16 KNIOHTON, 0 W Licensing Branch 3. 3pp 22408-360 24X Fichs 50-382, 84/02/16, 8402270648
- 8A02270325 Forwards clarification & info re Independent Safety
 Engineering Group rept prepared to address GA concerns in
 NRC 830804 ltr.in response to NRC 840116 request
 LEDDICK.R. 8 Louisiana Power & Light Co 84/02/20 DEYOUNG.R C
 Director's Office, Office of Inspection and Enforcement 218pp
 22391 330. 24X Fiche 50-382.84/02/20.8408270325
- 8402280515 Forwards proprietary Procedures STD-P-05-004, 003, STD-P-03-002, 005, HTD-R-03-002, STD-D-03-009, 008 & RW-2-210 re redwaste solidification process control programs Procedures withheld (ref 10CFR2 790) COCK, K W Louisians Power & Light Co 84/02/21 KN10HTON, 0 W Litensing Brench 3 2pp 22406 139 24X Fiche 50-382, 84/02/21, 8402280513
- B402240062 Forwards proprietary & nonproprietary versions of CEN-275(c)
 "Response to NRC Guestion on Waterford-3 Bypass Flowrats."
 per 840201 request for addl info on FBAR Bections 4 4 1.4 &
 4.4.2.6 i.Proprietary version withheld (ref 10CFR2 790)
 COOK.K. W. Louistana Power & Light Co 84/02/22 KNIGHTON.6 W
 Licensing Branch 3. 7pp 22375 169 24X Fiche 50-382,84/02/22.
- ---8402240065 Nonpropristary, "Response to NRC Question on WaterFord-3
 Bypass Flowrate "
 * Combustion Engineering, Inc. CEN-275(C)-NP 84/01/16 13pp.
 22375 176 24X Fiche: 50-382,84/02/22,8402240062
- 8402280227 Forwards seismic qualification review team comments from audit rept followed by util response re seismic & environ qualification Specific example of how qualification will be maintained encl CODK, K. W Louisiana Power & Light Co 84/02/23, XNIOHTON, O. W Licensing Branch S. Spp 22379 243 24X Fiche 50-382, 84/02/23, 8402280227.

- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8402060208 Forwards complete list of safety-related mechanical equipment per SSER 5 & util B30302 ltr All safety-related age-sensitive matis demonstrated fully qualified w/o use of manufacturer data sheets

 CODK.K W Louisiana Power & Light Co 84/01/30 KNIGHTDN.0 W

 Licensing Branch 3 110pp 22086 330 24X Fiche 50-382,84/01/30.8402060208
- 8402150311 Provides clarification re special lifting devices for control of heavy loads, per NUREG-O612 Phase I requirements of NUREG-O612 requested to be closed out in next SSER CDDK, K W Louisiana Power & Light Co 84/02/09 KNIGHTON, G W Licensing Branch 3 3pp 22250 183 24X Fiche 50-382,84/02/09, 8402150311
- --8402150313 Suppl 1 to "Response to NRC Draft Technical Evaluation Rept for Waterford 3 SES on Control of Heavy Loads " * Louisiana Power & Light Co 83/11/30 9pp 22250 186 24X Fiche 50-382,84/02/99,8402150311
- 8402160159 Forwards updated Tab K to environ qualification audit for closing out open items contained in App 3B to SSER 5 COOK, K W Louisiana Power & Light Co 84/02/10 KNIGHTON, G W Licensing Branch 3 61pp 22275 306 24X Fiche 50-382,84/02/10,8402160159
- B402160353 Forwards relief requests resulting from preservice insp program hanger/hanger support visual exams per BBER 5 Bection 5 2 4 & signed NIS-1 form for eddy current test rept CODK.K W Louisiana Power & Light Co 84/02/10 KNIGHTON, 0 W Licensing Branch 3 19pp 22277 022 24X Fiche 50-382,84/02/10,8402140353
- 8402220189 Forwards response to SSER 5. Section 13 items re licensee qualifications Regular planned meetings will be held at least every 3 menths for all brigade members to review changes in fire protection program CODK, K W Louisiana Power & Light Co 84/02/16 KNIGHTON, G W Licensing Granch 3 3pp 22340 354 24% Fiche 50~382,84/02/16,8402220189
- B4022B0219 Forwards description of fire protection training program which will be included in next FBAR amend Info adequate to close out BER issue re licensee qualification COOK.K.W Louisiana Power & Light Co 84/02/23 KN10HTON.G W Licensing Branch 3 5pp 22399 234 24X Fiche 50-382.84/02/23, 8402280219
- F Security, medical, emergency & fire protection plans
- 8402090258 Public version of Rev & to emergency plan & Rev 3 to smergency plan implementing procedures, including Procedures EP-1-001 re recognition & classification of emergency conditions & EP-1-020 re alert LEDDICK.R B Louisiana Power & Light Co 84/01/30 Office of Nuclear Reactor Regulation, Director App 22164 260 24X Fiche 50-382,84/01/30,8402070258
- --8402090263 Public version of Rev 6 to emergency plan ALLEMAN 8 A , BARKHURBT,R P Louisiana Power & Light Co 84/01/30 390pp 22164 266 24X Fiche 50-382,84/01/30, 8402090288
- --8402090267 Public version of Rev 3 to emergency plan implementing procedures, including Procedures EP-1-001 re recognition & classification of emergency conditions, EP-1-020 re alert & EP-1-040 re general & mergency at LEMAN, 8. A., BARKHURST, R.P. Louisians Power & Light Co 84/01/11 930pp 22165 296 24X Fiche 50-382, 84/01/30, 8402090258
- 8402150332 Forwards 830916 interim finding on util 831227 addendum to interim finding comments on EL Quarantelli rept & response to civil defense concerns, per NRC 830325 request Test plan exercise scheduled for 840206 KRIMM.R W Federal Emergency Management Agency 84/02/07 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 72pp 82251 122 24X Fiche 50-382, 84/02/07,8402150332.
- 8402130358 Evaluation of LAPL & State of LA emergency preparedness exercise on 840208 for Waterford Unit 3 * Federal Emergency Management Agency 84/02/08 281pp 22197, 288. 24x Fiche 50-362,84/02/08.8402130358

- 8402220187 Forwards response to SSER 5. Section 13 items re licensee qualifications Regular planned meetings will be held at least every 3 months for all brigade members to review changes in fire protection program COUK.K w Louisiana Power & Light Co 84/02/16 KNIGHTON.G W Licensing Branch 3 3pp 22340 354 24% Fiche 50-382.84/02/16, pageson set
- B4022B0219 Forwards description of fire protection training program which will be included in next FSAR amend Info adequate to close out SER issue re licensee qualification CODK.K W Louisiana Power & Light Co 84/02/23 KNIGHTON.G W Licensing Branch 3 5pp 22399 234 24x Fiche 50-382.84/02/23.84022B0219
- G Adjudicatory correspondence
- 8402280346 Expresses concern re NRC policy for consideration of recent allegations re quality of plant const Assistance requested in disclosing nature of allegations so util can take necessary action in timely manner CAIN.J M Louisiana Power & Light Co 84/02/16 PALLADINO.N J Commissioners 2pp 22398 007 24X Fiche 50-382,84/02/16,8402260346
- 8402280468 Mption to open GA contention based in part on encl article re doctored records Certificate of Svc encl BURBIEIN, C H Joint Intervenors Waterford 84/02/20 Atomic Safety and Licensing Board Panel 8pp 22402 350 24X Fiche 50-382.84/02/20.8402280468
- 8402220127 Order extending time until 840320 for Commission to act to review ALAB-753
 CHILK-8 J Office of the Secretary of the Commission 84/02/21
 Commissioners ip 22338 236 24X Fiche 50-392.84/02/21,
- 8402270107 Forwards staff motion for further extension of time & affidavit of JT Collins & WA Crossman
 TURK S E Hearing Branch 1 84/02/24 KOHL, C N , JOHNSON, W R ,
 WILEER, H A Atomic Safety and Licensing Appeal Panel 1p
 22427 350 24% Fiche 30-382,84/02/24,8402290107
- --8402270112 Motion for further extension of time until 640413 in which to respond to Joint Intervenors 831212 amended & supplemental motion to reopen Contention 22. Affidavit of JT Collins & MA Crossman encl Certificate of 6vc encl TURK, 8 E Hearing Branch 1 84/02/23 Atomic Safety and Licensing Appeal Panel 9pp 22427 354 24X Fiche 50-382, 84/02/24, 8402270107
- 1402270105 Memorandum & order denying Joint Intervenors 840222 motion to open GA contention & setting deadline of \$40330 to file properly documented motion SHDEMAKER.C J Atomic Safety and Licensing Appeal Panel. 84/02/28 Joint Intervenors Waterford 5pp 22426 176 24X Fiche 50-382.84/02/28.8402270105
- G Inspection reports. IE Bulletins & correspondence
- 840224014B FOIA request for documents re 830714 inquiry team rept on facility GA ellegations & insp & util response to rept GARDE.B F . BERNABEL.L Government Accountability Project 83710724 Office of Administration 2pp 22394 J70. 24X Fichs 50-382.83/10/24.8402240148
- 8402240153 Responds to FOIA request for documents re 830714 inquiry team rept on facility GA allegations & insp & util response to rept forwards App B documents App A & B documents available in PDR FELTON, J M Division of Rules and Records 83/12/09 QARDE, E P Government Accountability Project App 22394*172 24X Fiche, 30-382, 83/12/09, 8402240153
- --8402240160 Forwards case summary of Insp 83-65 re facility GA allegation AHEARNE, J F Commissioners 83/06/13 CUMMINGS NRC - No Detailed Affiliation Given 2pp 22374:181 24X Fiche 50-382,83/12/07.8402240153
- 8402220388 Forwards IE Insp Rept 50-382/83-32 on 831219-22. No violations or deviations identified JOHNSON,E.H. Region 4, Defice of Director 84/01/16 LEDDICK,R.S Louisiana Power & Light Co 2pp 22334 123 24X Ficher 50-382,64/01/16,8402220388

- ---8402220393 IE Insp Rept 50-382/83-32 on 83/219-22 No violations or deviations identified Major areas inspected completed instrumentation slectrical cable terminations & transmitter installations & review of GC records & GA audits MULLIKIN,R P, JAUDON,J P, CROSSMAN,W A Region 4, Office of Director 84/01/12 4pp 22334 125 24X fiche 50-382,84/01/16,8402220388
- 8402220344 Forwards IE Insp Rept 50-382/83-33 on 831128-1202 No violations or deviations identified JOHNSON, E. H. Region 4, Office of Director 84/01/19 LEDDICK, R. 8 Louistana Power & Light Co. 2pp. 22336 042 24X Fiche 50-382,84/01/19,8402220344
- --8402220349 IE Insp Rept 50-382/83-33 on 831128-1202 No violations or deviations noted Major areas inspected chemistry/ radiochemistry program, including review of outstanding items.organization & staffing qualifications
 NICHOLAS.J B . MURRAY.B . CROSSMAN.W A Region 4. Office of Director 84/01/12 9pp 22336 064 24X Fiche 50-382.84/01/19, 8402220344
- 8402070149 forwards IE Insp Rept 50-382/83-36 on 831201-31 No violations noted JDHNSON.E H Region 4. Office of Director 84/01/20 LEDDICK,R 8 Louisiana Power & Light Co 2pp 22102 249 24X Fichs 50-382,84/01/20,8402070149
- --8402070162 IE Insp Rept 50-382/83-36 on 831201-31 No violations noted Major areas inspected preoperational test witnessing, IE bulletin.circulan & info notice review.mgt meeting, emergancy operating procedures & Tech Spec review CONSTABLE. G. L., FLIPPO.T. A., CROSSMAN. W. A. Region 4, Office of Director 84/01/19 9pp 22102 251 24X Fiche 50-382.84/01/20, 8402070149
- 8312120133 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps." Bvc list encl JDRDAN;E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22088 001 24% Fiche 50-000,84/01/25,8312120153
- 8402270051 Further response to FOIA request for five categories of documents re facility Forwards App A documents App C documents partially withheld & App D documents entirely withheld (ref FOIA Exemption 7) FELTON: J H Division of Rules and Records 84/01/26 LYON: V. F Lyon & Kur: 5pp 22411 171 24X Fiche 50-382:84/01/26
- --8105120144 Forwards input to facility safety evaluation Review incomplete due to NRC low level staffing & mgt HANAUER, 8 H Division of Human Factors Bafety 81/05/07 TEDESCO, R L. Assistant Director for Licensing 27pp 22411:178 24% Fiche 50-382,84/01/26,8402270051
- --8209290283 Comments on encl draft IE Insp Rept 50-382/82-14 & snfprcement action Plant is ideal candidate for const team insp HARPSTER.T L. Quality Assurance 82/08/31 LIEBERMAN.J. Enforcement Branch (Fre 820201) 19pp 22411:210 24X Fiche 50-382.84/01/26.8402270051
- --8402270067 Discusses Inquiry Case File 64-83-017 re facility. Inquiry closed & Investigation 4-83-014 opened DRIBKILL, D.D. Region 4, Office of Director 83/07/26. Region 4, Office of Director ip 22411 270 24X Fiche, 50-382, 84/01/26, 8402270051
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls" Evc list encl JORDANN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000.84/02/03.8401190016
- 8401170017 IE Builetin 84-01. "Cracks in BWR Mark I Containment Vent Headers " Svc list enc! DEYDUNG.R C Director's Office. Office of Inspection and Enforcement B4/02/03 Consolidated Edison Co of New York, Inc. 102pp 8217
- B402160333 Forwards relief requests resulting from preservice insp program hanger/hanger support visual exams, per SBER 5 Section 5 2 4 & signed NIS-1 form for eddy current test rept . CDOK, & Louisiana Power & Light Co 84/02/10, KNIGHTON, 0 W Licensing Branch 3 17pp 22277 022 24X Fich# 50-382.84/02/10, 8402160333

- 8401190041 IE Info Notice 84-D9, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR30, App R) " Syc list encl.
- anci. JGRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365-259 24% Fiche 80-000,84/02/13,8401190041
- B402210200 Ack receipt of 830719 & 1207 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 30-382/83-17 Addl info needed re American Bridge records on election & insp of MSIVs JOHNSON, E H Region 4, Office of Director 84/02/13 LEDDICK, R S Louistana Power & Light Co 1p 22316 318 24X Fiche 50-382,84/02/13,8402210200
- --8402210207 Responds to NRC 830728 ltr re violations noted in IE Insp Rept 50-382/83-17 Corrective actions Ebasco Force Account will implemment program to provide complete QA documentation of safety-related records QERRETS.T F Louisiana Power & Light Co 83/12/07 JDHNSDN,E Region 4. Office of Director 2pp 22316 317 24X Fiche 50-382,84/02/13,8402210200
- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '"
 - Byc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/14 Consolidated Edison Co. of New York, Inc. 115pp. 22365 141 24X Fiche 30-000, 84/02/14, 8401190039
- 840i190045 IE Info Notice 83-63, Suppl 1: "Potential Failures of Hestinghouse Type SA-1 Differential Relays." Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co 22366 142. 24X Fiche 50-000,84/02/15,8401190045 118pp
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Bet Below Manufacturer Recommended Value " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21. Consolidated Edison Co of New York, Inc. 116pp 22366 024 24X Fiche 50-000.84/02/21.8401190062
- 8401190066 IE Info Natice 84-11, "Training Program Deficiencies "
 - Syc list encl
 JORDAN, E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc. 115pp 22430 304 24X Fiche 50-000,84/02/24,8401170046
- 8401190067 RE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
- R. Periodic operating reports & related correspondence
- 8402280462 Forwards near-term OL rept & delineates status of util readiness for operation as of 840116 Final detailed open item list will be forwarded 1 month prior to OL issuance DENIBE, R P. Division of Resident, Reactor Project & Engineering Programs 84/02/23 EIBENHUT, D Q Division of Licensing, 24pp 22404:326 24X Fiche, 50-382, 84/02/23, 8402280462
- S Reportable occurrences, LERs & related correspondence
- 8402010253 Part 21 rapt re potential interference in full function of Bergen-Paterson strut assembly w/Pacific Scientific Co mechanical shock arrestor Attempt to obtain corrective action from manufacturer unsuccessful BECKBTED, N. F. Bergen-Paterson Pipe Support Corp 81/03/06 GRIER, B. N. Region 1, Philadelphia, Office of the Director (B1/03/01). 2pp 22040-205 R4X Fiche 50-000, 81/03/06, 8402010253
- 8402240153 Responds to FOIA request for documents re 830714 inquiry team rept on facility GA allegations & insp & util response to rept. Forwards App B documents App A & B documents available in PDR.
 - Available in DM. FELTON.J M Division of Rules and Records. B3/12/09 G Government Accountability Project. App. 22394:172. 24X Fiche: 50-382,83/12/09,8408240153 GARDE, B P
- --B402240136 Forwards news article re NRC concern w/GA One area previously unspecified now identified as potential significant deficiency Incident 8 re common foundation mat radial cracks inside ring wall. RIDENHOUR, R. Gambit, 83/05/03. FORT, J. Louisiana Power & Light Co. 5pp. 22394.176. 24X Fiche 50-382,83/12/09,8402240153

- 8402010088 Advises that final significant const Deficiency Rept 75 re station battery squalizing charge voltage exceeding coil ratings will be submitted on 840330 Corrective action for amend to FBAR under way GERRETB.T F Louisiana Power & Light Co 84/01/20 COLLINS.J T Region 4. Defice of Director Rpp 22042 163 24X Fiche. 50-382.84/01/20.8402010088
- B402010148 Amended response to final potential Deficiency Rept 130 re loss of annulus vacuum control Original breaker sizes adequate & would not adversely affect safety if left uncorrected Deficiency not reportable per 10CFR50 55(e) GERRETS.TF Louisiana Power & Light Co 84/01/20 COLLINS, J T Region 4. Office of Director 2pp 22038 229 24% Fichs 50-382.84/01/20.8402010148
- 8402040418 Ninth interim significant const Deficiency Rept 37, "Temp Detector (RTD) Failures " Interim or final status rept will be provided by 840330 OERRETS.T F Lauisians Power & Light Co 84/01/24 COLLINS.J T Region 4. Office of Director 290 22085 139 24% Fiche 50-382.84/01/24.8402040418
- 8402060468 First interim rept re Bignificant Const Deficiency 97 concerning diesel generator B turbocharger fatlure Initially reported on 831222 Cooper Energy Svcs preparing rept was cause of failure Final rept will be submitted by 840302 OERRETS.T.F Louisiana Power & Light Co 84/01/24 COLLINS. Region 4. Office of Director 3pp 22083 114 24X Fiche 50-382.84/01/24.8402060468 COLLINS, J T
- B402020315 Part 21 rept re unsecured wire terminations on Knox fuse blocks Two separate single 14 tab terminal wire terminals found loose in cubicles Recommends tab terminals be relocated from lower clamp to upper clamp area of connector DWYER.P W General Electric Co 84/01/26 DEYOUNG.R Director's Office, Office of Inspection and Enforcement 25pp 22035 120 2: Fichs. 50-382,84/01/26,8402020315
- 8402140272 First interim rept re Significant Const Deficiency 98 on measuring & test equipment usage sheets not forwarded to proper organization or not posted against test equipment use records Initially reported on 831212 Next rept by 840316 GERRETS.T.F. Laudsiana Power & Light Co. 84/01/31 CGLLINS.J.T. Region 4. Office of Director 3pp. 22228 282 24X Fichs: 50-382,84/01/31.8402140272
- 8402140375 Bixth interim Significant Const Deficiency Rept 7B re American Bridge structural steel defects Addl work required to complete two nonconformance repts Final rept will be to complete two noncorromance repts final rept will be submitted on 84/0307
 GERRETB.T F Louisiana Power & Light Co 84/01/31 COLLINS, J T Region 4. Office of Director 2pp 22220 332 24X
 Fichs: 50-382,84/01/31.8402140395
- 8402140431 Bignificant Const Deficiency Rept 42-R1 re HMA auxiliary relays Initially reported on 831213 Electrical outage scheduled in Feb 1784 to complete corrective actions Next rept will be submitted on 840224 GERRETS, TF Louisiana Power & Light Co 84/01/31 CDLLINS, J T Region 4. Office of Director 2pp 22221 291 24X Fiche. 50-382,84/01/31.8402140431
- 8402140056 Third interim Deficiency Rept 92 re HP9I sys performance Initially reported on 831215 Final rept will be submitted by 840224 GRUETH.T F. Louisiana Power & Light Co 84/0 Region 4, Office of Director 2pp 22219 258 Fiche: 50-382,84/02/03,8402140056 84/02/03 COLLINS, J T 258 24X
- 8402140060 Seventh interim Deficiency Rept 32 re stress analysis for welded supports not performed prior to fabrication Final rept will be submitted by 840309 GERETS.T F Louisiana Power & Light Co 84/02/03 COLLINS, J T Region 4. Office of Director 2pp 22219 260 24X Fichs 50-382.84/02/03.8402140060
- 8402140319 Final Deficiency Rept 141 re QE switchgear terminations Initially reported on 831222 Preinsulated lugs modified to accommodate terminals Condition determined not reportable per 10CRNSO, 55(e) QERRETS, T. F. Louisiana Power & Light Co. 84/02/03 COLLING, J. DERRETS, T.F. Louisians Power & Light Co. 84/02/03 COLLING, J.T. Region 4, Office of Director 2pp. 2228 243, 24X Fiche 50-382,84/02/03,8402140319
- 8402170019 Final Deficiency Rept 142 re dry cooling tower A freeze damage, Initially reported on 840104 Condition not reportable per 100FR50 55(s). Addl freeze damage problems not identified GERRETS T. F. GERRETB, T. F. Louisiana Power & Light Go 84/02/09. CDLLINB, J T Region 4. Office of Director. 3pp 22300 240 24X Fiche: 50-382, 84/02/09. 8402170019

- 8402170229 Final Deficiency Rept 145 re 13 nonconformance repts requiring further evaluation not reported to NRC Evaluation of Ebasco documentation indicates condition nut reportable per 10CFR50 55(e)
 OERRETS.TF Louisiana Power & Light Co 84/02/09 COLLINS.J T Region 4. Office of Director 2pp 22279 324 24% Fiche 50-382.84/02/09.8402170229
- 8402280017 Second interim rept re Significant Const Deficiency 90 Concerning overstressed electrical conduit Due to extended analysis & accessibility to implement corrective action. completion scheduled for 840330 Next rept by 840413 GERRETS.TF Lauisiana Power & Light Co 84/02/15 COLLINB, J T Region 4, Dffice of Director 2pp 22400 277 24x Fiche 50-382,84/02/15,8402280017
- 8402280292 Seventh interim rept on Significant Const Deficiency 57 re inadequate instrumentation & control installations & turnover decumentation Review of corrective actions in progress Final rept will be submitted on 840406 GERRETS. T F Louisiana Power & Light Co 84/02/15 COLLINS. J. T Region 4. Office of Director 2pp 22399 208 24X Fiche 50-382.84/02/15.8402280292
- 8401190064 Board Notification 84-030 forwards NRC 840202 memo re finding that potential single failures exist in C-E auxiliary pressurizer spray sys Requests initiated to C-E applicants addressing NRC concerns EIBENHUT. D @ Division of Licensing 84/02/16 PALLADING, GILINSKY, ROBERTS Commissioners ip 22352 252 24X Fiche \$0-000.84/02/16,8401190064
- --8402230244 Requests that licensing boards associated w/PWRs designed by C-E be notified of concerns re reliance on auxiliary pressurizer spray sys which may have single failure vulnerabilities
 MATTSON,R J Division of Systems Integration (post 811005)
 84/02/02 EISENHUT.D C Division of Licensing Jpp 22352 353
 24% Fiche 50-000,84/02/14,8401190064

♥ Congressional/Executive Correspondence

- 8402270002 Responds to FOIA request for correspondence NRC received from Senators J McGlure, JB Johnston & P Laxalt during gast 2 yrs Forwards App A documents Name of individual deleted from Documents 8 & 7 of App A (ref FOIA Exemption 6) FELTON, J M Division of Rules and Records 83/11/30, KOLI, E. Cable News Network, Inc. 6pp 22438 002 24X Fiche: 50-000, 13/11/30, 8402270002
 - ISOB180043 Responds to 830719 ltr re cracks in common foundation mat Incidents of water seepage, engineering studies, NRC monitoring & review of studies discussed DIRCKS, W.J. Office of the Elecutive Director for Operations 83708709 JOHNSTON, J.B. Senate 2pp 22438 115 24X Fiche 50-000,83/11/30,8402290002
 - B308180641 Requests findings & views re encl ltr from concerned constituent JUHH8170N.J B. Benate B3/07/19 Office of Congressional Affairs 2pp 2243B 113 24X Fiche 50-000.83/11/30.8402290002
 - 402290098 Forwards announcement of ACRS 820303 technical meeting at site W/o encl.

 KAMMERER.C Office of Congressional Affairs. 82/02/LB

 OTTINGER.R L House of Rep., Energy & Commerce SIMPSON, A

 Senate, Environment & Public Works UDALL, M House of Rep.,

 Interior & Insular Affairs 1p. 22438 031 24X

 Fiche 50-000,83/11/30,8402290002
 - 2290201 Forwards announcement of ASLB scheduled hearing to begin on 30208 in New Orleans, LA
 WHMERER.C Office of Congressional Affairs 83/01/27
 TINGER.R House of Rep. Energy & Commerce SIMPSON, A., HART
 nate, Environment & Public Works, 1p 22438,050 24X
 he 50-000,83/11/30,8402290002
 - 70241 Forwards announcement that ASLAB will hear oral argument on 117 in New Orleans,LA
 1ERER.C Office of Congressional Affairs. 83/04/05.
 INDER.R L House of Rep , Energy & Commerce SIMPSDN, HART
 ats. Environment & Public Works 1p 22438 052 24X
 the 50-000,83/11/30,8402290002

- DOCKET 50-387 SUBQUEHANNA STEAM ELECTRIC STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documents
 FELTON.J M Division of Rules and Records 83/10/31
 ROBENBAUM.D M Technical Analysis Corp 19pp 22193 292 24X
 Fiche 50-000,83/10/31.8402090003
- --8402070226 Handwritten calculations re const activities & schedule * NRC - No Detailed Affiliation Given 79/05/16 ip 22196 24 24X Fiche 50-000,83/10/31,8402090003
- --8402070231 Trip rept of 780504-05 site visits re const acheduling & preoperational testing & const status observation Related info enc!
 MINER: S Light Water Reactors Branch 3 78/08/22 Light Hate Reactors Branch 3 4pp 22196 246 24X Fiche 50-000.83/10/31,
- 8402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILKS J Diffice of the Secretary of the Commission 83/12/14 Public Document Branch 1p 22281 023 24X Fiche 50-000.83/12/14 8402160003
- --B402160144 Staff requirements memo re B20707 discussion & possible on contested issues in QL proceeding in Washington, DC CHILK, B J Office of the Secretary of the Commission B2/07/13 BICKNIT, L. Office of the General Counsel 2pp 22281 047 243 Fiche 50-000, 83/12/14, 8402160003
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- B402170237 Provides status of control room design review program.per App F of SSER 5 & Suppl 1 to NUREG-0737 CURTIS,N W Pennsylvania Power & Light Co 84/02/13 BCHWENCER.A Licensing Branch 2 3pp 22296 359 24X Fiche 50-387,84/02/13, 8402170237
- F. Security, medical, emergency & fire protection plans
- 8402030426 Rev 3 to Procedure EP-IP-007. "Personnel Assembly & Accountability," Rev 35 table of contents to Emergancy plan implementation procedure manual & 840127 controlled document transmittal & ack encl * Pennsylvania Power & Light Co 84/01/25 22pp 22068-220 2 Fiche 50-387.84/01/25.8402030426
- 8402070200 Provides revised scheduled completion date for safety parameter display sys of no later than 840701 Extending completion date will not reduce ability to deal w/emergency CURTIS,N W Pennsylvania Power & Light Co 84/02/01 SCHMENCER,A Licensing Branch 2 ip 22100 028 24X Fiche 50-087,84/02/01,8402/010
- 8402140031 Forwards BER & technical evaluation rept providing NRC review of detailed control room design review. Program plan acceptable, however, summary rept does not show that detailed control room design meets Suppl 1, NUREG-0737 requirements BCHWERNER, A. Licensing Branch 2 84/02/02 CURTIB, N W Pennsylvania Power & Light Co 21pp 22301, 258 24X Fiche 50-387, 84/02/02, 8402140031
- --8402030532 "Evaluation of Detailed Control Room Design Review for Busquehanna Steam Electric Station." technical evaluation rept * Science Applications, Inc. NRC-03-82-096 BAI-186-351-73 84/01/25 NRC - No Detailed Affiliation Given 279p 22301 279 24X Fiche 50-387,84/02/02,8402160031
- 8402170429 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per 810709 Generic Ltr 81-27 W/o requestrenting plan will be placed in PDR SCHMENCER: A Licensing Branch 2 84/02/09, CURTIB,N W. Pennsylvania Power & Light Co 2pp 22313.170 24X Fiche 50-387,84/02/09,8402170429
- 8402170237 Provides status of control room design review program, par App F of SSER 5 & Suppl i to NUREO-0737. CURTIS.N W Pennsylvania Power & Light Co 84/02/13. SCHWENCER, A Licensing Branch 2. 3pp 28296 359 24X Fiche 50-387,84/02/13, B402170237.

- B402220453 Ack receipt of 840203 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-387/83-23 Corrective actions will be examined during future insp BTARDSTECKL; R Division of Project & Resident Programs 84/02/13 KENYON, B D Pennsylvania Power & Light Co ip 22339 343 24X Fiche: 50-387,84/02/13,8402220493
- --8402220436 Responds to NRC 840104 ltr re violations noted in IE Insp Rept 50-387/83-23 Corrective actions withheld (ref 10CFR2 770) KENYON.B D Pennsylvania Power & Light Co 84/02/03 4 /70/ Pennsylvania Power & Light Co 84/02/03 I.R Division of Project & Resident Programs 1p · 24X Fiche 50-387,84/02/13,8402220433 STARDSTECKI, R
- B40221037B Notification of rescheduled 840227 meeting w/util in Bethesda.MD to discuss Rev 7 to emergency plan Meeting originally scheduled on B40221 FERCH.R L Licensing Branch 2 84/02/14 SCHWENCER, A Licensing Branch 2 2pp 22363 081 24% Fiche 50-387.84/02/14.8402210378
- --8402210382 Notification of 840221 meeting w/util in Bethesda,MD to discuss Rev 7 to emergency plan PERCH.R L Licensing Branch 2 84/02/13 8CHWENCER.A Licensi Branch 2. 2pp 22363 082 24X Fiche 50-387.84/02/14.8402210378
- B402220322 Revised emergency plan implementation procedures, including TOTAL PROPERTY PLAN INDICATION PROCESSING STREET PROCESSING SEPTIF-012, "One-tie Emergency Monitoring" & EP-IP-02, "Heackup Emergency Operation Facility " W/840215 ltr # Pennsylvania Power & Light Co 84/02/14 BCHWENCER. A NRC - No Detailed Affiliation Given 57pp 22336 277 24X Fiche. 50-387,84/02/14.8408220322
- 8402270252 Ack receipt of 840120 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-387/83-17

 HARTIN.T T. Division of Engineering & Technical Programs 84/02/3

 KENYDN. B D. Pennsylvania Power & Light Co 2pp 22387 001 24)

 Fiche: 90-387,84/02/16,8402270252 B4/02/16
- --8402270261 Responds to NRC 831222 ltr re violations noted in IE Insp Rept 50-387/83-17 Corrective actions health physics foreman will review routine survey schedules weekly for time completions & violation posted.per 10CFR19 KENYON.B.D Pennsylvania Power & Light Co 84/01/20 MARTIN.T T Division of Engineering & Technical Programs 2pp 22387 003 24X Fiche 50-387,84/02/16,8402270R52
- 8402280354 Forwards Change R to physical security plan Change withheld (ref 10CFR2,790), MENYON, B D. Pant RenyOn, B D. Pennsylvania Power & Light Co 8/ Region 1, Office of Director 2pp 22402 361 Fiche, 50-387,84/02/21,8402280384 84/02/21 MURLEY, T E
- P Operating license stage documents & correspondence
- 83:2120029 Generic Ltr 83-39 to representatives of utils re voluntary survey of licensed operators 8vc list encl EISENHUT, D. G. Division of Licensing 83/12/08 Commonwealth Edison Co. 12pp 22319 006 24X Fichs 50-000.83/12/08.8312120029
- 8402070196 Discusses dynamic qualification of standby liquid control explosive valve Statement in Section 2 2 of PLA-1978 that valve qualified by analysis in error Required g-levels for Unit 2 valve are 1.11 g horizontal & 0 8 g vertical GURTIB.N M. Pennsylvania Power & Light Co 84/02/01 SCHWENCER. Licensing Branch 2 ip 22100 023 24% Fiche 50-387,84/02/01,8402070196 84/02/01 SCHWENCER,A
- 8402070243 Rasponds to Generic Ltr 84-01 re use of terms, important to safety & safety-related Meeting w/NRC requested to astablish necessary dialogue for achieving resolution, CURTIS, N W Pennsylvania Power & Light Co. 84/02/02 TAYLOR J M Director's Office, Office of Inspection and Enforcement, ip R2101 253 24X Fiche 50-387,84/02/02,8402070243
- 8402070270 Responds to inquiry re feedwater piping outside reactor bldg. Mein steam piping runs through turbine bldg mein steam pipe tunnel, resulted in total separation from feedwater piping in Area CURTIB,N W. Pennsylvania Power & Light Co 84/02/03 SCHWENCER.A Licensing Branch 2 ip 22101-317 24X Fiche 50-387.84/02/03, 8402070270,
- 8402150501 Forwards 831026,1122 & 840126 FR monthly notices # Office of Nuclear Reactor Regulation, Director. 84/02/07 CURTIS, N.W. Pennsylvania Power & Light Co. 57pp 22263 195 24X Fishe: 50-387,84/02/07,8402150501

- 8402130214 Informs that analysis to fast scram hydrodynamic loads on control rod drive sys complete Plant-specific analysis in final stages & will be transmitted following util mgt review anticipated for Jul 1984
 CURTIS,N W Pennsylvania Power & Light Co. 84/02/08 BCHWENCER, A Licensing Branch 2 ip. 22200 120 24X Fiche 50-387, 84/02/08, 8402130214
- 8402270077 Submits add1 info re proposed 42-inch Transco pipeline Analysis of steel structure showed that time for steel to reach 1,000 F is in excess of 60 s,while estimated burn time of gas cloud order of magnitude loss CURTIS.N W. Pennsylvania Power & Light Co. 84/02/21 SCHWENCER Licensing Branch 2 2pp. 22387-354 24X Fiche 50-387,84/02/21.8402270077 SCHWENCER, A
- 8402270342 Forwards updated application for plan approval/permit for concrete batch plant originally submitted on 840213.in response to 840217 telcon FIELDS, J B Pennsylvania Power & Light Co 84/02/22 PATEL, B H Pennsylvania, Commonwealth of, 9pp 22389 309 24x Fichs 50-387,84/02/22,8402270342
- B402270429 Discusses mod of automatic depressurization sys logic.per NUREO-0737. Item II K 3 18 Proposes that NRC allow bypassing inhibit switch on Unit 2 until first refueling outage on
- CORTIES N W Pennsylvania Power & Light Co 84/02/22 BCHWENCER, A Licensing Branch 2 2pp 22387 344 24X Fiche 50-387, 84/02/22, 8402270429
- B402280243 Rev 3 to application for Amend 36 to License NPF-14, changing Tach Specs re secondary containment integrity CURTIS, N W Pennsylvania Power & Light Co 84/02/23 SCHWENCER, A Licensing Branch 2 3pp 22399 251 24X Fiche 50-387,84/02/23, 8402280243
- --8402280248 Proposed Tech Spec re-secondary containment integrity * Pennsylvania Power & Light Co 84/02/23 4pp 22377 254 24X Fiche 50-387,84/02/23,8402280243
- G Inspection reports, IE Bulletins & correspondence
- 8402020245 Forwards IC Insp Repts 50-387/83-25 & 50-388/83-24 on 831107-1218 & notice of violation 84001720 BTAROSTECKIR Division of Project & Resident Programs 84/01/20 KENYON, B D Pennsylvania Power & Light Co 2pp 22035 277 24X Fiche 50-387,84/01/20,8402020245
- --8402020246 Notice of violation from insp on 831107-1218

 * Region 1, Office of Director 84/01/20 1p 22055 301
 Fiche 50-387,84/01/20,8402020245
- --B402020292 IE Insp Repts 50-387/83-25 & 50-388/83-24 on 831107-1218 Noncompliance noted failure to maintain average reactor coolant temp less than or equal to 140 F while in Condition coolant temp less than or equal to the remission of trefueling)
 RHOADS, 6 , PLISCO.L. Region 1, Office of Director
 Division of Project & Resident Programs B3/12/29
 22055 302 24X Fiche. 50-387, 84/01/20, 8402020245 MCCABE, E C
- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Byc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24% Fiche 50-000,84/01/25,8312120153
- 8402080366 Forwards IE Insp Repts 50-387/83-30 & 50-388/83-25 on B31128-1802, notice of violation & listing of licenses strengths & weaknesses MARTIN.T T Division of Engineering & Technical Programs 84, KCNYON.B D Pennsglvania Power & Light Co 3pp 22131 135 Fiche: 50-387, 84/01/24, 8402080366
 - 84/01/24
- --8402080370 Notice of violation from insp on 831128-1202 Apps 8 & C re licenses strengths & weaknesses, respectively, encl * Region 1, Office of Director 84/01/26 5pp 22131 138 24X Fiche 50-387, 84/01/26, 8402080366
- --8402080374 IE Insp Repts 50-387/83-30 & 50-388/83-25 on 831128-1202 Violations noted failure to provide training to personnel, to control temporery setpoint changes & to assess affectiveness of GA program audits EAPEN.P K , MEYER. 0 , SHAUB.E T Region 1, Office of Director 84/01/06 31pp 22131 143 24x Fiche 50-387,84/01/26,8402080366
- 8402090348 Forwards IE Insp Repts 50-387/83-31 & 50-388/83-31 on B31219-23 & notice of violation. MARTIN, T.T Division of Engineering & Technical Programs 84, KENYON, B D Pannsylvania Power & Light Co 2pp 22140 240 Fiche: 50-387,84/01/27,8402090348 84/01/27

- --8402090351 Notice of violation from insp on 831219-23 * Region 1, Office of Director 84/01/27 ip 22160 242 24x Fiche 50-387,84/01/27,8402090348
- --8402090357 IE Insp Repts 50-387/83-31 & 50-388/83-31 on 831219-23
 Violation noted failure to follow GA/GC interface procedures
 in nonconformance reporting areas
 EAPEN.P K , SHAUB.E T Region 1. Office of Director CAPHTON.D &
 Division of Engineering & Technical Programs 84/01/25 9pp
 22160 243 24X Fiche 50-387.84/01/27.8402090348
- 8401190016 IE Info Notice 84-07. "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York Inc 119pp 22114 179 24X Fiche S0-000.84/02/03.8401190016
- 8401190017 IE Builetin 84~01. "Cracks in BWR Mark I Containment Vent Headers" Svc list encl BEYOUNG, R C Director's Office. Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177
- 8402150366 Confirms 840213 insp of diesel generators by State of PA Dept of Environ Resources FIELDS: J.S. Pennsylvania Power & Light Co. 84/02/07 FATEL: 8 H Pennsylvania: Commonwealth of: 2pp 22242:138 24X Fiche 50-387.84/02/07.8402150366
- 8402240019 Forwards IE Insp Repts 50-387/83-27 & 50-389/83-26 on 831128-1202 & notice on violation Response to deviations from analytical chemistry procedures requested MARTIN.T T Division of Engineering & Technical Programs 84/02/08 KENYON.B D Pennsylvania Power & Light Co 2pp. 22375:328 24X Fiche 50-387.84/02/08.8402240019
- --8402240023 Notice of violation from insp on 831128-1202 * Region I, Diffice of Director 84/02/08 ip. 22375 330 24X Fiche 80-387,84/02/08,8402240019
- --8402240025 IE Insp Repts 50-387/83-27 & 50-388/83-24 on 831128-1202
 Noncompliance noted failure to follow procedures for liquid radwaste monitor calibr
 JANG, J C , PASCIAK, J Region 1, Office of Director 84/01/05
 6pp 22375 331 24X Fiche 50-397,84/02/08,8402240019
- 8402240070 Forwards IE Insp Repts 50-387/83-28 & 50-388/83-30 on 831212-16 No violations observed MARTIN,T T. Division of Engineering & Technical Programs 84/02/08 KENYON,B D Pannsylvania Power & Light Co 2pp 22373-222 24X Fiche 50-387.84/02/08.8402240090
- --B402240092 JE Insp Repts 50-387/83-26 & 50-388/83-30 on B31212-16 No violations identified Major areas inspected radiation protection & radwaste mgt program for Unit 2 & circumstances & actions following contaminated water spill in Unit 1 NIMITZ.R L. DRAGOUN.T F. SHANBAKY.M M Region 1, Office of Director B4/02/01. 18pp 22373 224 24X Fiche 50-387,84/02/08,8402240990
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown 8ys (100FR50, App R)" Svc list enc!

 URDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259. 24X Fichs 50-000.84/02/13, 8401190041
- 8402220453 Act receipt of 840203 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-387/83-23 Corrective actions will be examined during future insp STARGSTECKI, R. Divisiom of Project & Resident Programs 64/02/13 KENYON, B D Pennsylvania Power & Light Co ip 22339;343 24X Fiche: 50-387,84/02/13,8402220453
- --8402220456 Responds to NRC 840104 ltr re violations noted in IE Insp Rupt 50-387/83-23 Corrective actions withheld (ref 10CRR2 790). KENYON B D Pennsulvania Power & Light Co 84/02/03. BIAROSTECKI,R Division of Project & Resident Programs. ip. 22339-344. 24X Fiche 50-387.84/02/13,8402220453
- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection.'" 8vc list encl. JORDAN-E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/14 Consolidated Edison Co of New York, Inc 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039.
- B401190045 IE Info Notice 83-63. Suppl 1. "Potential Failures of Westinghouse Type BA-1 Differential Relays " Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). B4/02/15 Consolidate Edison Co of New York, Inc. 118pp 22366 142 24X Fiche 50-000.B4/02/15.B401190045

- 8402290188 Forwards IE Insp Repts 50-387/84-03 & 50-388/84-04 on 840111 No violations noted MARTIN.T T Division of Engineering & Technical Programs. 84/02/13 KENYON,B D Pennsylvania Power & Light Co 2pp 22419 182 24X Fiche 50-387.84/02/15.8402290188
- --8402290195 IE Insp Repts 50-387/84-03 & 50-388/84-04 on 840111. No violations noted Major areas inspected action on improper relief valve setting deficiencies & piping design temps & pressures identified in Spec M-199 MAMOLY. K. DURR. J. P. Region I. Office of Director 84/02/09 5pp 22419 184 24X Fiche 50-387.84/02/15,8402290188
- B402270252 Ack receipt of 840120 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-387/83-17 MARTIN. T Division of Engineering & Technical Programs 84/02/16 KENYON.B D Pennsylvania Power & Light Co 2pp 22387 001 24x Fiche 50-387.84/02/16.8402270252
- --8402270261 Responds to NRC 831222 ltr rs violations noted in IE Insp. Rept 50-387/83-17 Corrective actions health physics foreman will review routine survey schedules weekly for time completions & violation posted per 100FR17 KENYON-B.D Pennsylvania Power & Light Co 84/01/20, MARTIN,T T Division of Engineering & Technical Programs 2pp 22387 003 24X Fiche 50-387.84/02/16,8402270252
- 8401170062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 114pp 22366 024 24X Fiche 50-000.84/02/21,8401170062
- 8402270418 Ack receipt of 840213 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/83-25 k 50-388/83-24 Monitoring trands in plant perameters per established reactor coalant temp limits acceptable STAROSTECKI:R Division of Project & Resident Programs 84/02/23 KENYON.B D Pennsylvania Power & Light Co 2pp 22390.222. 24X Fiche 50-387.84/02/23,8402270418
- --8402270423 Responds to NRC 840120 ltr re violations noted in IE Insp Repts 50-387/83-25 & 50-386/83-24 Corrective actions amount of bypass flow around RHR HX reduced, increasing amount of cooling flow in shutdown cooling sys KENYON, B D Pennsylvania Power & Light Co 84/02/13 9TARUSTECKI, R Division of Project & Resident Programs 2pp. 22370, 224 24X Fichs. 50-387,84/02/23,8402270418
- 8401190066 IE Info Notice 84-11. "Training Program Deficiencies" Svc list and Jungahn E Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/24 Consolidated Edison Co of New York, Inc 115pp 22430:304 24X Ficha 50-000,84/02/24,8401190066
- B401190067 IE Info Notice 84-12, "Failure of Boft Seat Valve Seals."

 Evc list encl

 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/02/27 Consolidated Edison Co. of New
 York, Inc 120pp 22431 060 24X Fiche 50-000, B4/02/27, 8401190967
- R Periodic operating reports & related correspondence
- 8402150264 "Drinking Water (NIPDMR) Monitoring Rept for Jan 1984." W/840208 ltr. FIELDS, J & Pennsylvania Power & Light Co 84/01/31 2pp. 22242 069 24% Fiche 50-387,84/01/31,8402150264
- 8 Reportable occurrences, LERs & related correspondence
- 8402030231 RO. confirms 831230 verbal rept re incomplete safety parameter display sys for emergency response ctr.in violation of License Condition 2 C(28)(g)(1). Followup rept will be submitted within 14 days
 KEISER.H W Fennsylvania Power & Light Co 84/01/03, MURLEY, T. E. Region 1. Office of Director ip 20047 162. 24X
 Fiche 50-387.84/01/03.8402030231
- 8402030214 Updated LER 83-109/03X-1 on 830724.RCIC becometric condenser condensate vacuum pump tripped during spray pond testing Cavied by mechanical failure of pump motor commutator. Condensate motor replaced WA40113 1tr WILKS.8 L., XEIEER.H.W Pennsylvania Power & Light Co 84/01/13 NURLEY.T E Region 1. Office 94 Director Spp. 22067.188 24X Fiche: 50-387.84/01/13.8402030214

- 8402060237 Updated LER 83-088/03x-1 on 830530,RCIC pump discharge valve failed to open Caused by gaps between breaker male & female stab clips investigations revealed lack of cleanance in GE 7700 control ctrs Procedures revised W/840116 ltr WILKS,B L . KEISER,H W Pennsylvania Power & Light Co 84/01/16 WIRLEY,T E Region 1, Office of Director 3pp 22087 210 24X Fiche 50-387,84/01/16,8402060239
- 8402030267 RQ on 841102, reactor scram occurred Caused by main steam line high radiation signal Response to transient included automatic HPCI initiation & injection KEISER, H W Pennsylvania Power & Light Co 84/01/18 MURLEY, T E Ragion 1, Dffice of Director 1p 22069 206 24X Fiche 50-387,84/01/18,8402030267
- B402030261 RO on 831214, seal penetration X21-6-D20 violated to implement cable pulling for mod Fire watch established per Tech Spec G 7 7 a & maintained until seal replaced & declared operable on 831221 KEISER, H W Pennsylvania Power & Light Co 84/01/20 MURLEY, T E fiegion 1, Dffice of Director ip 22069 207 24X Fiche 50-387,84/01/20,8402030261
- B402020117 Updated LER 83-166/03x-1 on 831129, LIS 14221D setpoint found out of calter by 1 2 inches, resulting in limiting condition for operation Causad by setpoint drift LIS recalibr W/840123 ltr WILKE, B L , KEISER, H W Pennsylvania Power & Light Co 84/01/23 HURLEY, T E. Region 1, Office of Director 2pp 22056 225 24X Fiche: 50-387, 84/01/23, 8402020117
- B402140204 Followup deficiency rept re mod of RHR globe valves F017A & F017B to enable valves in shutdown cooling mode to perform w/o adverse cavitation & vibration at low flow rates Initially reported on 811112 Valves replaced CURTIG.N W Fennsylvania Power & Light Co 84/01/25 MURLEY.T E Region 1, Office of Director. 3pp 22223 343 24X Fiche: 50-387.84/01/25.8402140204
- B402020120 PNO-I-B4-011 on 840126, two spills discovered onto turbine bldg Elevation 656, below grade floor beneath main turbine hall Initial contamination surveys indicated max values of 500,000 dpm per 100 CM2 on floor JACOBS, R., EHANBAKY, H. Region 1, Office of Director 84/01/27 2pp 22056 213 24X Fiche 50-387, 84/01/27, 8402020120
- B402080242 LER 83-172/03L-0 on 831230, reactor protection sys B motor generator set electrical protection assembly (EPA) breakers tripped, resulting in loss of shutdown cooling Gouse under investigation Circulation reestablished W/840127 ltr KUCZYNSKI, L A , KEISER, H W Pannsylvania Power & Light Go 84/01/27. MURLEY, T E Region 1, Office of Director 2pp. 22134 241 24X Fishe 50-387,84/01/27,8402080242
- 8402230347 Updates status rept on BWR pipe cracks & protection of upcoming licensee actions Insp results encl Evaluation & recommendations re interim & long-term remedial measures expected by May 1984
 BIRGKS,W J Office of the Executive Director for Operations 8ECY-84-009A 84/01/27 5pp 22377 047 24X Fiche 50-000, 84/01/27,8402230347
- B402070389 Discusses potentially generic issue re Commip. Inc ges analyser catalyst bed qualification life. Vendor recommends replacement of std configuration catalyst beds Region I awaiting IE & AEOD replay 91 STARDSTECKI.R. Division of Project & Resident Programs, 84/01/30 JORDAN, E.L. Director's Office, Office of Inspection and Enforcement 5pp. 22095 107 24X Fichs. 50-000.84/01/30.8402070389
- B402070364 LER 84-001-00 on 840103 hydrogen diaxide analyzers in containment atmosphere monitoring sys inoperable Caused by design deficiency Catalyst will be replaced on 840201 for Unit 1 k on 840215 for Unit 2 W/840202 ltr HILKS R L . KEISER: H W Pennsylvania Power & Light Co 84/02/02 3pp. 22099 078 24X Ficha 50-387.84/02/02.8402070364
- 840207032; LER 84-002-00 on 840106; emergency svc water (ESM) Bi spray network inlat valve leaked past seat & spray risers & could not be pumped down. ESM pumps ran intermittently Spray distribution arms broke off riser assemblies W/840202 ltr. MUCIYMSKI, L A , KEISER; H W Pennsylvania Power & Light Co 84/02/03 3pp 22098 358 24X Fiche: 50-387,84/02/03,8402070321
- B402070352 LER 84-003-00 on 840106 discovered 27 signal isolators may mot provide adequate electrical isolation between Class IE & non-IE circuits HPGI inoperable pending corrective actions W/840203 ltr WILKS:8 L., KEISER:H W. Pennsylvania Power & Light Co 84/02/03. 3pp. 22098:355 24X Fiche 50-387.84/02/03.8402070352

- B402150333 LER 84-004-00 on 840113, two level switches on condensate storage tank found inoperable due to freezing Caused by deenergized heat tracing heat tracing on affected instrument lines & switches restored W/840210 ltr WUCZVMSKI,L A . KEJSER,H W Pennsylvania Power & Light Co 84/02/10 3p 22250 208 24X Fiche 50-387,84/02/10,8402150333
- B402220169 PNO-I-84-016 on B40216, emergency diesel C failed 18-month surveillance test Caused by turbotharger thrust bearing trouble Thrust bearing replaced & turbocharger reassembled Licensee investigating cause of problem PLISCO. L. MCCABE. E Region 1. Offfice of Director 84/02/17 ip 22340 138 24X Fiche 50-387,84/02/17,8402220169
- 8402280120 LER 84-006-00 on B40125 discovered that performance of weekly source & intermediate range monitors w/unit in Mode 5 constitutes core alteration Core alterations prohibited per Tech Specs Tech Bpec change in progress W/840224 ltr MUCZYNBKILL A , KEIGER, H W Pennsylvania Power & Light Co B4/02/24 3pp 22401 107 24X Fiche 50-387.84/02/24.8402280120
- 8402280227 LER 84-005-00 on 840127, svc water grab sample not taken during day shift Caused by sample being missed during turnover between day & afternoon shifts Procedural change issued M/840224 ltr
 KUCZYNSKI,L A, KEISER,H W Pennsylvania Power & Light Co
 84/02/24 3pp 22399 279 24X Fiche 50-387,84/02/24,8402280227
- DOCKET 50-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8402070003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documents
 FELTON, J M Division of Rules and Records 83/10/31
 ROSENBAUM, D M Technical Analysis Corp 19pp 22193 292 24X
 Fiche 30-000,83/10/31.8402070003
- --B402090224 Handwritten graph re const schedule * NRC - No Detailed Affiliation Given 83/05/26 ip 22196 240 24X Fiche 50-000, 83/10/31,8402090003
- --8402070231 Trip rept of 780504-05 site visits re const scheduling & preoperational testing & const status observation Related info encl
 MINER.8 Light Water Reactors Branch 3 78/08/22 Light Water Reactors Branch 3 4pp 22176 246 24X Fiche 50-000,83/10/31, 8402070003
- 8402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILK, 8 J Office of the Secretary of the Commission 82/12/14 Public Document Branch ip 22281
- --B402160144 Staff requirements memo re 820707 discussion & possible vote on contested issues in QL proceeding in Washington DC CHILK, 8 J Office of the Secretary of the Commission 82/07/13, BICKWIT, L. Office of the General Counsel 2pp 22281 047 24X Fiche 50-000,83/12/14,8402160003
- 840R070196 Discusses dynamic qualification of standby liquid control explosive valve Statement in Section 2 2 of PLA-1998 that valve qualified by analysis in error Required g-levels for Unit 2 valve are 1 il g horizontal & 0 8 g vertical. CURTIS:N W Pennsylvania Power & Light Co 84/02/01 8CHWENCER.A Licensing Branch 2 1p 22100.023 24X Fiche 50-387,84/02/01.8402070196
- 8402070243 Responds to Generic Ltr 84-01 re use of terms, important to safety & safety-related Heeting w/NRC requested to establish necessary dialogue for achieving resolution. CURTIS.N W Pennsylvania Power & Light Co 8402/02. TAYLOR J M Director's Office, Office of Inspection and Enforcement ip 22101:233 24X Fiche 50-387,84/02/02.8402070243
- B402070270 Responds to inquiry re feedwater piping outside reactor bldg Main steam piping runs through turbine bldg main steam pipe tunnel, resulted in total separation from feedwater piping in area GURTIS.N W Pennsylvania Power & Light Co 84/02/03 BCHWENCER, A Licensing Branch 2 ip. 22101 317. 24X Fiche 50-387,84/02/03,8402070270
- 8402130501 Forwards 831026,1122 & 840126 FR monthly notices * Office of Nuclear Reactor Regulation, Director 84/02/07 CURTIS,N W Pennsylvania Power & Light Co 59pp 22263 195 24X Fiche. 50-387, 84/02/07, 8402150501

- 8402130214 Informs that analysis re fast scram hydrodynamic loads on control rod drive sys complete Plant-specific analysis in final stages & will be transmitted following util mgt review anticipated for Jul 1984 GURTIS. N W Pennsylvania Power & Light Co 84/02/08 SCHHENCER. A Licensing Branch 2 ip 22200 120 24% Fiche 50-387, 84/02/08, 8409130214
- 8402140452 Forwards application to amend CPPR-102 extending const completion date to 840930 Class II amend fee encl SNAPP.B A Pannsylvania Power & Light Co 84/02/10 Office of Nuclear Reacture Regulation. Director 1p 22227
- --8402140457 Application to amend CPPR-102, extending const completion date to 840930 * Pennsylvania Power & Light Co 84/02/10 6pp 22227 177 24X Fiche 30-388, 84/02/10, 8402140452
- B402270077 Submits add1 info re proposed 42-inch Transco pipeline Analysis of steel structure showed that time for steel to reach 1.000 F is in excess of 60 s, while estimated burn time of gas cloud order of magnitude less CURTIS.N W Pennsylvania Power & Light Co 84/02/21 SCHWENCER. A Licensing Branch 2 2pp 22387 354 24X Fiche 50-387,84/02/21, 8402270077
- 8402270342 Forwards updated application for plan approval/permit for concrete batch plant originally submitted on 840213 in response to 840217 telcon FIELDS: J S Pennsylvania Power & Light Co 84/02/22 PATEL, B H Pennsylvania, Commonwealth of, 9pp 22369 309 24X Fiche 50-387,84/02/22,8402270342
- 8402270429 Discusses mod of automatic depressurization sys logic.per NUREO-0737.item II K 3 18 Proposes that NRC allow bypassing inhibit switch on Unit 2 until first refueling outage on Unit 1 CURTIS,N W Pennsylvania Power & Light Co 84/02/22 SCHWENCER, A Licensing Branch 2 2pp 22389 344 24X Fiche.50-387,84/02/22, 8402270429
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 8402070254 Provides info to resolve one proposed license condition re vendor review of NSSS procedures per SBER 5 CURTIS,N W Pennsylvania Power & Light Co B4/01/31 SCHWENCER. A Licensing Branch 2 3pp 22101 213 24X Fiche 50~388,84/01/31, B402070254
- 8402070349 Provides proposed dates to close proposed license conditions Safety parameter display sys will be completed by 840701 Procedure for core damage estimation to incorporate SBER 3 requirements will be submitted by 841201 CURTIS,N W Pennsylvania Power & Light Co 84/02/02 SCHWENCER, A Licensing Branch 2 3pp 22097 039 24X Fiche 50-388,84/02/02,8402070349
- 8402170237 Provides status of control room design review program, per App F of SSER 5 & Suppl 1 to NUREO-0737 CURTIS,N W Pennsylvania Power & Light Co 84/02/13 BCHWENCER, A Licensing Branch 2 3pp 22276-359 24X Fiche 50-387,84/02/13,8402/10237
- F Security, medical, emergency & fire protection plans
- B402030426 Rev 3 to Procedure EP-IP-007, "Personnel Assembly & Accountability," Rev 35 table of contents to emergency plan implementation procedure manual & 840127 controlled document transmittal & ack enci

 * Pennsylvania Pawer & Light Co 84/01/25 22pp. 22068 220 24x
 Fiche 50-387.84/01/25,8402030426
- B402070200 Provides revised scheduled completion date for sefety parameter display sys of no later than 840701 Extending completion date will not reduce ability to deal w/emergency CURTIS,N H Pennsylvania Power & Light Co 84/02/01, 80HHENCER,A Licensing Branch 2 ip 22100 028 24X Fichs, 50-387, 84/02/01, 8402070200
- 840214003) Forwards SER & technical evaluation rept providing NRC review of detailed control room design review Program plan acceptable, however, summary rept does not show that detailed control room design meets Suppl I, NUREG-0737 requirements. SCHWENCER: A Licensing Branch 2. 84/02/02 CURTIS, N W Pennsylvania Power & Light Co. 2ipp. 22301 258 24X Fiche: 50-387, 84/02/02,8402140031

- --8402030932 "Evaluation of Detailed Control Room Design Review for Susquehanna Steam Electric Station," technical evaluation rept * Science Applications, Inc. NRC-03-82-096 9AI-186-351-73 84/01/25 NRC - No Detailed Affiliation Given 27pp 22301 279 24X Fiche 50-387.84/02/02.8402160031
- 8402170427 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per Blo709 Generic Ltr 81-27 W/o request.entire plan will be placed in PDR SCHMENCER.A Licensing Branch 2 84/02/09 CURTIS,N W Pennsylvania Power & Light Co 2pp 22313 170 24X Fiche 50-387.84/02/09.8402170429
- B402170237 Provides status of control room design review program, per App F of SSER 5 & Suppl 1 to NUREG-0737 CURTIE, N W Pennsylvania Power & Light Co 84/02/13 BCHHENCER, A Licensting Branch 2 3pp 22296 359 24X Fiche 50-387, 84/02/13, 8402170237
- 8402210378 Notification of rescheduled 840227 meeting w/util in Bethesde, MD to discuss Rev 7 to emergency plan Meeting originally scheduled on 840221 PERCH, R L Licensing Branch 2 84/02/14 SCHWENCER, A Licensing Branch 2 2pp 22363 081 24X Fiche 50-387,84/02/14,8402210378
- --8402210382 Notification of 840221 meeting w/util in Bethesda.MD to discuss Rev 7 to emergency plan PERCH.R L. Licensing Branch 2 84/02/13 8CHWENCER,A Licensing Branch 2 2pp 22363 GB2 24X Fiche 50-387.84/02/14,8402210378
- 8402220322 Revised emergency plan implementation procedures, including EP-IP-012, "Onsite Emergency Monitoring" & EP-IP-052, "Barkup Emergency Operation Facility " W/840215 ltr * Pennsylvania Power & Light Co. 84/02/14 SCHWENCER, A NRC No Detailed Affiliation Given 57pp 22336 277 24X Fichs 50-387,84/02/14,8402220322
- G Inspection reports, IE Bulletins & correspondence
- 8402020275 Forwards IE Insp Rept 50-388/83-22 on 831024-1104 No violations observed MARTIN,T.T Division of Engineering & Technical Programs 84/01/18 KENYON,B D Pennsylvania Power & Light Co 2pp 22054 324 24K Fiche 50-388,84/01/18,8402020275
- --8402020280 IE Insp Rept 50-388/83-22 on 831024-1104 No violation observed Major areas inspected structural integrity test, containment integrated leak rate test, evaluation of test results & facility tours CHVM3.J W. HON.P. ESHEYER, 8 D. Region 1. Office of Director 84/01/12 11pp 22054 326 24X Fiche 50-388.84/01/18,8402020275
- 8402020245 Forwards IE Insp Repts 50-387/83-25 & 50-388/83-24 on 831107-1218 & notice of violation STARDSTECKLE Division of Project & Resident Programs 84/01/20 KENYON, B D Pensylvania Power & Light Co 2pp 22055,297 24X Fichs 50-387,84/01/20,8402020245
- --8402020252 IE Insp Repts 50-387/83-25 & 50-388/83-24 on 831107-1218
 Noncompliance noted failure to maintain average reactor
 coolant temp less than or equal to 140 F while in Condition
 5 (refueling)
 RHOADS, 9 , FLISCO. L Region 1. Office of Director MCCABE. E C
 Division of Project & Resident Programs 83/12/29 12pp.
 22055 302 24X Fiche 50-387.84/01/20,84020202045
- B312120153 IE Info Notice B4-06, "Steam Binding of Auxiliary Feedwater Pumps" Svc list encl.
 JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/01/25 Consolidated Edison Co. of New York
- 840208036B Forwards IE Insp Rept 50-388/83-23 on 83:114-17 No violations noted MARTIN.T T Division of Engineering & Technical Programs. 84/01/25 KENYON.B.D Pennsylvania Power & Light Co 2pp 22:31 174, 24X Fichs 50-388,84/01/25,8402080368
- --8402080375 IE Insp Rept 50-388/83-23 on 831114-17 No noncompliance noted Major areas inspected propprational test program, including implementation, procedure review & verification, results evaluation & witnessing NICHOLAS, H H , FLOREK, D J , BETTENHAUSEN, L Region 1, Office of Director 84/01/25 10pp 22131-176 24X Fiche 50-388, 84/01/23, 8402080368.

- B402080366 Forwards IE Insp Repts 50-387/83-30 & 50-388/83-25 on 831128-1202 notice of violation & listing of licenses strengths & weaknesses
 - ecrengths & weaknesses
 MARTIN.T Division of Engineering & Technical Programs 84/01/26
 KENYON.B D Pennsylvania Power & Light Co 3pp 22/31 135 24X
 Fiche 50-387.84/01/26.8402080366
- --BA02080370 Notice of violation from insp on 831128-1202 Apps 8 & C re licensee strengths & weaknesses, respectively, encl * Region 1, Office of Director 84/01/26 Spp 22131 138 24X Fichs 50-387,84/01/26.8402080366
- --8402080374 IE Insp Repts 50-387/83-30 & 50-388/83-25 on 831128-1202 Violations noted failure to provide training to personnel, to control temporary setpoint changes & to assess effectiveness of GA program audits EAPEN, P K. MEYER, G. BHAUB, E T Region 1, Office of Director 84/01/06 31pp 22131 143 24X Fiche 50-387,84/01/24,8402080366
- B402070348 Forwards IE Insp Repts 50-387/83-31 & 50-388/83-31 on B31219-23 & notice of violation MARTIN.T T. Division of Engineering & Technical Programs 84/01/27 KENYON, B D Pannsylvania Power & Light Co 2pp 22140 240 24x Fiche 50-387,84/01/27,8402070348
- --8402070351 Notice of violation from insp on 831217-23 * Region 1, Office of Director 84/01/27 ip 22160 242 24% Fichs 50-387,84/01/27,8402070348
- --8402090357 IE Insp Repts 50-387/83-31 & 50-388/83-31 on 831219-23 Violation noted failure to follow GA/GC interface procedures in nonconformance reporting areas EAPEN, F K , SHAUB, E T Region 1, Office of Director CAPHTON, D L Division of Engineering & Tachnical Programs 84/01/23 9pp 22160 243 24X Fiche 30-387,84/01/27,8402090348
- E402160477 Forwards IE Insp Rept 50-388/83-28 on 831127-1230 No violations observed MARTIN,T T. Division of Engineering & Technical Programs 84/02/0 KENYON,B D Pennsylvania Power & Light Co 2pp 22277 076 24X Fiche: 50-388,84/02/02,8402160477
- --8402160481 IE Insp Rept 50-388/83-28 on 831127-1230 No noncompliance noted Major areas inspected preoperational test program, including test program implementation, test procedure review & verification, test results evaluation & test witnessing NICHOLAS H H., FLOREK, D J. BETTENHAUSEN, L Region 1, Office of Director 84/01/30 21pp 22277 078 24X Fiche 50-388,84/02/02,8402160477
- B401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl BEYOUNG.R.C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Go of New York, Inc 102pp. 22177 156 24X Fiche. 50-000,84/02/03,8401190017
- B402150366 Confirms 840213 insp of diesel generators by State of PA Bept of Environ Resources FIELDB, J. 8 Pannsylvania Power & Light Co 84/02/07 PATEL, B H Pannsylvania, Commonwealth of. 2pp 22242 138 24X Ficha: 50-387, 84/02/07, 8402150366
- 8402240019 Forwards IE Insp Repts 50-387/83-27 & 50-388/83-26 on 83128-1202 & notice on violation Response to deviations from analytical chemistry procedures requested MARTIN.T T. Division of Engineering & Technical Programs 84/02/08 KENYON.B D. Pannsylvania Power & Light Co 2pp 22375 328, 24% Fiche. 50-387.84/02/08.8402240019.
- 8402240090 Forwards IE Insp Repts 50-387/83-28 & 50-388/83-30 on 831212-16 No violations observed HARTIN.T. Division of Engineering & Technical Programs. 84/02/08 KENYON.B.D. Pennsylvania Power & Light Co. 2pp 22373-222 24X Fiche: 50-387,84/02/08,8402240090.

- --8402240072 IE Imap Repts 50-387/83-28 & 50-388/83-30 on 831212-16 No violations identified Major areas inspected radiation protection & radwaste mgt program for Unit 2 & circumstances & actions following contaminated water spill in Unit I NIMITZ.R L , DRAGGUN.T F , SHANDAKY,M M Region I, Office of Director 84/02/01 18pp 22373 224 24X Fiche 50-387,84/02/08,8402240090
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Bys (100FR50.App R)" Byc list encl
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Røsponse (Post 830103) 84702/13 Consolidated Edison Co of New
 York, Inc. 124pp 22365-259 24X Fiche 50-000,84702/13,8401190041
- 8401190039 IE Info Nutice 84-08, "10CFR30 7, 'Employer Protection " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/14 Consolidated Edison Co of New York, Inc 115pp 22365 141 24% Fiche 50-000,84/02/14,8401190039
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Westinghouse Type 9A-1 Differential Relays" Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc 118pp 22366 142 24X Fiche 50-000,84/02/15,8401190045
- 840227018B Forwards IE Insp Repts 50-387/84-03 & 50-388/84-04 on B40111 No violations noted MARTIN, T T Division of Engineering & Technical Programs 84/02/15 KENYON, B D Pennsylvania Power & Light Co 2pp 22419 182 24X Fiche 50-387,84/02/15,8402270188
- --8402270195 IE Insp Repts 50-387/84-03 & 50-388/84-04 on 840111 No violations noted. Major areas inspected action on improper relief valve setting deficiencies & piping design temps & pressures identified in Spec M-197 MANOLY.K., DURR.J.P. Region 1. Office of Director 84/02/09 5pp 22419 184 24X Fiche 50-387.84/02/13,8402290188
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Bet Below Manufacturer Recommended Value" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co. of New York, Inc. 116pp 22366-024 24X Fiche 50-000.84/02/21,8401190062
- 8402270418 Ack receipt of 840213 ltr informing NRC of steps taken to correct violations noted in IE Imap Repts 50-387/83-25 & 50-388/93-24 Monituring trends in plant parameters per established reactor coolent temp limits acceptable STARDSTECKI.R Division of Project & Resident Programs 84/02/23 KENYON B D Fennsylvania Power & Light Co 2pp 22390 222 24X Fiche: 50-387,84/02/23.8402270418
- --8402270423 Responds to NRC 840120 ltr re violations noted in IE Insp. Repts 50-387/83-25 & 50-388/83-24 Corrective actions amount of bypass flow around RHR HX reduced, increasing amount of cooling flow in shutdown cooling sys KENYON, B D Pennsylvania Power & Light Co 84/02/13. STAROSTECKI, R Division of Project & Resident Programs 2pp 22390 224 24X Fiche 50-387,84/02/23,8402270418
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies" Byc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals"

 8vc list encl,

 JORDAN, EL Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060 24% Fiche 50-000,84/02/27,8401190067
- R Periodic operating reports & related correspondence
- 8402150264 "Drinking Water (NIPDWR) Monitoring Rept for Jan 1984 " W/840208 Itr FIELDS.J.S Pennsylvania Power & Light Co 84/01/31 Ppp 22242 069 247 Fiche. 50-387, 84/01/31, 8402150264
- B Reportable occurrences, LERs & related correspondence
- B402030313 Interim deficiency rept re GE reactor mode switch Proposed redesign of mode switch by GE rejected based on results of testing conducted at Franklin Inst Research Lab Alternate switch ordered through Electroswitch Final rept by Apr 1784 CURTISN W Pennsylvania Power & Light Co 84/01/12 MURLEY, T. E Region 1. Office of Director 5pp 22/067 125 24X Fiche 50-388,84/01/12,8402030313

- 6402140204 Followup deficiency rept re mod of RHR globe valves F017A & F017B to enable valves in shutdown cooling mode to perform w/o adverse cavitation & vibration at low flow rates Initially reported on 811112 Valves replaced CURTIS.N W Pennsylvania Power & Light Co 84/01/25 MURLEY,T E Region 1. Office of Director 3pp 22223 343 24% Fiche 50-387,84/01/25.8402140204
- B402230347 Updates status rept on BMR pipe cracks & protection of upcoming licensee actions Insp results encl Evaluation & recommendations re interim & long-term remedial measures expected by May 1984

 DIRCKS.W.J. Diffice of the Executive Director for Operations SECY-84-007A 84001/27 5pp 22377 047 24% Fiche 50-000, 84/01/27, 8402200347
- 8402070387 Discusses potentially generic issue re Comsip. Inc. gas analyzer catalyst bed qualification life Vendor recommends replacement of std configuration catalyst beds Region I awaiting IE & AEOD reply STAROSTECKI.R Division of Project & Resident Programs 84/01/30-JCRDANA E.L Director's Office. Office of Inspection and Enforcement 5pp 22095 107 24% Fiche 50-000.84/01/30.8402070389
- E402270255 Interim deficiency rept re safety parameter display sys Model 156 isolators mfg by Technology for Energy Corp (TEC) Initially reported on 840106 All TEC isolators reviewed for corrective actions Also reported per Part 21 CURTIS,N W Pennsylvania Power & Light Co 84/02/06 MURLEY,T E legion 1. Office of Director 3pp 22386 281 24X Tiche 50-388,84/02/06,8402270255
 -)2270186 Final deficiency rept re Bechtel failure to accomplish design verification of safety-related power & control cables Caused by failure to complete required cable length verification Deficiency not reportable per 10CFR50 55(e) CURTIS.N W Pennsylvania Power & Light Co 84/02/13 MURLEY.T E Region 1. Office of Director 5pp 22391 323 24X Fiche 50-388,84/02/13,8402270186
- 8402270349 Final deficiency rept re hydrogen catalyst used in Comsip Custom Line Model K-IV containment gas monitoring panels Initially reported on 840113 Comsip redesigned catalyst will be installed Also reportable under Part 21 CURTIS,N W Pennsylvania Power & Light Co 84/02/13 MURLEY,T E Region 1. Office of Director 4pp 22391 231 24X Fiche 50-388,84/02/13,8402270349
 - DOKET 50-389 ST LUCIE PLANT, UNIT 2
 - Application/construction stage documents & correspondence
- 402070003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documents
 FELTON, J M Division of Rules and Records 83/10/31
 ROSENBAUM. D M Technical Analysis Corp 19pp 22193 292 24X
 Fiche 50-000,83/10/31.8402090003
- -8402070201 Handwritten calculations & graphs re const schedule * NRC - No Detailed Affiliation Given 83/10/31 2pp 22176 217 24% Fiche 50-000,83/10/31,8402070003
- Security, medical, emergency & fire protection plans
- 8402130501 Emergenty Plan Implementing Procedures 1101.1102.1103.1104. 1105.1106.1107.1201 & 1202 re duties of emergency control officer.recovery manager & emergency info manager W/840207 its
- tr + Florida Power & Light Co 83/12/15 O'REILLY, J.P. Region & Diffice of Director 57pp 22201 201 24X Fiche 50-335,83/12/15.8402130501
- 9402080383 Revs to emergency plan implementing procedures, including Rev 15 to Procedure 31000218. Rev 25 to Procedure 31000238. Rev 8 to Procedure 31000338 & Rev 3 to Procedure 31000358. W/840202 1tr
- NILLIAMS, J W , HARRIS, K N , SCHMIDT, A D Florida Power & Light Co 84/01/09 O'REILLY, J P Region 2, Office of Director 84pp. 22131 026 24% Fiche 50-335,84/01/09,8402080383
- 8402010184 Forwards comments on detailed control room design review (DCRDR) grogram plan submittal per Suppl 1 to NUREG-0737 DCRDR summary repts submitted on 830930 & 1101 currently under review
 - VARGA,S A Operating Reactors Branch 1 84/01/16 WILLIAMS, J W Florida Power & Light Co 10pp 22048 033 24X Fiche 50-000,84/01/16,8402010184

- 8402130373 Forwards IE Insp Rept 50-389/84-01 on 840104-05 No violations or deviations noted DANCE: H C Division of Project & Resident Programs 84/01/18 WILLIAMS. J W Florida Power & Light Co 2pp 22241 330 24X Fiche 50-389,84/01/18,8402150373
- --8402150378 IE Insp Rept 50-389/84-01 on 840104-05 No violations or deviations noted Major areas inspected fire protection MILLER, W H. Region 2, Office of Director CONLON. T E. Division of Engineering & Operational Programs 84/01/12 App 22241 332 24X Fichs 50-389, 84/01/18, 8402150373
- 8402130449 Forwards Rev 8 to physical security plan Rev withheld (10f 10CFR73 21) WILLIAMB, J W Florida Power & Light Co 84/01/31 O'REILLY, J P Region 2, Office of Director ip 22202 103 24X Fiche 50-335,84/01/31,8402130449
- B402140400 Ack receipt of 831222 ltr providing objectives for emergency exercise scheduled for Mar 1984 Emergency personnel will not arrive at facilities until arrival would have occurred on roal-time basis

 DANCE.FI C Division of Project & Resident Programs, 84/01/31

 HILLIAMB.J W Florida Power & Light Co 1p 22220 345 24X

 Ficho 50-335,84/01/31.8402140400
- 8402270399 Revised emergency plan implementing procedures, including Procedures 3100021E for 8t Lucie & 20101 for Turkey Point reduties of emergency coordinator & 1102 for Turkey Point concerning recovery manager duties W/840221 ltr WILLIAMS.J W Florida Power & Light Co 84/01/31 81pp 22371 063 24X Fiche 50-000.84/01/31.8402270399
- 8402070381 Forwards Revs 15,25,8 & 3 to Emergency Plan Implementing Procedures 3100021E,3100032E & 3100035E, respectively, re emergency coordinator duties, emergency roster & offsite dose calculations WILLIAMS, J W Florida Power & Light Co 84/02/02 O'REILLY, J P Region 2, Offsite of Director ip 22095 116 24% Fiche 50-335,84/02/02,8402070381
- --B4020703B3 Rev 13 to Emergency Plan Implementing Procedure 3100021E, "Duties & Responsibilities of Emergency Coordinator" HARRIS,K N Florida Power & Light Co 84/01/09 24pp 22095 117 24X Fiche 50-335.84/02/02.84020703B1
- --8402070385 Rev 25 to Emergency Plan Implementing Procedure 3100023E.
 "Onsite Emergency Drganization & Rostor"
 HARRIS,K N Florida Power & Light Co 84/01/09 15pp
 22095 141 24X Fiche. 50-335, 84/02/02,8402070381
- --840207038B Rev B to Emergency Pian Implementing Procedure 3100033E, "Offsite Dose Calculations" SCHMIDT, A D Florida Power & Light Co 84/01/09, 30pp. 22075 156 24% Fiche 50-335,64/02/02,8402070381
- ~-B402070391 Rev 3 to Emergency Plan Implementing Procedure 3100035E.
 "Offsite Radiological Monitoring"
 SCHMIDT.A D Florida Power & Light Co B4/01/09 13pp
 22095 186 24X Fiche 50-335.B4/02/02.B402070381
- 8402080224 Forwards IE Insp Repts 50-335/84-01 & 50-389/84-02 on 840109-13 No violations noted DANCE:H C Division of Project & Resident Programs 84/02/02 HILLIAMS.J W Florida Power & Light Co Rpp 22130:221 24X Fiche 50-335,84/02/02,8402080224
- --B4020B0479 IE Insp Repts 50-335/84-01 & 50-389/84-02 on 840109-13 No violations noted. Major areas inspected security organization, security program audit, physical barriers & detection aids, Details withheld (ref 10CFR2 790 & 73 21) HALL.8 L Region 2, Office of Director 84/02/02 ip 22130 223 24X Fiche 50-335,84/02/02,84020B0224
- 840221016B Forwards Human Factors Engineering Branch draft BER redetailed control room design review par Suppl 1 to NUREO-0737 Add1 info needed to complete review VAROA S A Operating Reactors Branch 1 84/02/02 WILLIAMS, J W Florida Power & Light Co 18pp 22346 027 24X Fiche 50-000,84/02/02,8402210168
- --8402090330 "Evaluations of Detailed Control Room Design Reviews for St Lucie Units 1 & 2 & Turkey Point Units 3 & 4," technical evaluation rept * Science Applications, Inc NRC-03-82-096 SAI-186-391-68 84/01/13. NRC No Detailed Affiliation Given 23pp. 22346 047 24% Fiche 50-000,84/02/02,8402210168

- 840R080405 Forwards sys checkout & functional tast rept for qualified safety parameter display sys Bys tasted satisfactorily WILLIAMS, J W Florida Power & Light Co 84/02/03 EISENHUT. D C Office of Nuclear Reactor Regulation, Director Spp 22130 001 24X Ficha 50-389,84/02/03.8402080405
- 8402130362 Forwards revised Emergency Implementing Procedures 1101 reduties of emergency control officer. 1102 reduties of recovery manager. 1103 reduties of emergency info manager & 1104 reduties of emergency security manager WILLIAMS. J W Florida Power & Light Co 84/02/07 O'REILLY. J PRegion 2. Office of Director 1p 22200 257 24X Fiche 50-335.84/02/07.8402130362
- --B40213036B Revised emergency implementing procedures, including Procedure 1101 re duties of emergency control officer, Procedure 1102 re duties of recovery manager & Procedure 1103 re duties of emergency info manager * Frorida Power & Light Co 83/12/15 59pp 22200 25B 24X Fiche 50-335,84/02/07,8402130362
- B402160670 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per 810707 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR MILLER.JR Operating Reactors Branch 3 84/02/07 WILLIAMS, JW Florida Power & Light Co 2pp 22272 347 24% Fiche 50-335,84/02/07.8402160690
- B40217025B Provides justification for revising schedule change for implementation of upgraded emergency operating procedures, per Suppli to NUREG-0737 MILLIAMS.J.W Florida Power & Light Co 84/02/17 EISENHUT.D 6 Division of Licensing 2pp 22297 182 24X Fiche 50-335.84/02/17.84.0217025B
- J Insurance & indemnity information
- B402020343 Forwards Endorsements 51 & 41 to NELIA & MAELU Policies NF-227 & MF-88, respectively DUCK, J. R. Marsh & McLennan, Inc. 84/01/26 SALTZMAN, J. Assistant Director for Batak & Licensee Relations 3pp 22055, 047 24X Fiche' 50-335, 84/01/26, 8402020343
- D Advisory Committee on Reactor Safeguards reports & correspondence
- 8402090511 Bubmits rept on ACRS Fluid Dynamics Subcommittee 831208 meeting Flow-related incidents have common origin in flow induced vibration due to vortex shedding or bulk flow oscillation.

 TIEN, C L California, Univ of, Berkeley, CA TIEN, C L ACRS Advisory Committee on Reactor Safeguards 83/12/22 BUEHNERT, P A ACRS Advisory Committee on Reactor Safeguards 2pp 22192 308 24x Fichs 30-335,83/12/22,8402070511
- P Operating license stage documents & correspondence
- 8402060490 Environ protection plan (nonradiological)
 # Florida Power & Light Co 83/04/30 10pp 22110 169 24X
 Fiche.50-389:83/04/30:8402060490.
- 8402130451 Requests review of encl E0&0 technical evaluation rept.
 "Conformance to NRR Generic Ltr 82-16.8t Lucie Plant, Units 1
 & 2." Response addressing deviations for Unit 1 requested within 30 days of ltr receipt
 MILLER.J R. Operating Reactors Branch 3 84/01/30 WILLIAMS, J W Florida Power & Light Co 2pp 22216:107. 24X
 Fiche: 50-335.84/01/30,8402130451
- --8402130487 "Conformance to NRR Generic Ltr 82-14.8t Lucie Plant,Units 1 & 2." preliminary rept, VANDERBEEK,R. 6080, Inc. FIN A-6600. EGG-EA-6432 DRFT 83/10/91. NRC - No Detailed Affiliation Given 20pp 22216 109. 24X Fiche 50-335,84/01/30.8402130451
- 8402010410 Generic Ltr 84-04 to all operating PMR licensees.CP holders & applicants for CPs re safety evaluation of Mastinghouse topical repts dealing w/elimination of postulated pipe breats in PMR primary main loops Svc list encl.
 ETBENHUT.D.9 Division of Licensing 84/02/01. Consolidated Edison Co. of New York, Inc. 59pp. 22177 087. 24X
 Fiche: 50-000,84/02/01,8402010410.

- @ Inspection reports, IE Bulletins & correspondence
- 8402140242 Ack receipt of 831214 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-335/83-34 & 50-389/83-62 Implementation of corrective actions will be examined during future insps
 DANCE, H C Division of Project & Resident Programs 84/01/18 WILLIAMS, J W Florida Power & Light Ca 1p 22220 285 24X Fiche 50-335,84/01/18,8402140242
- --8402140253 Ack receipt of 831214 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/83-34 & 50-389/83-62 LEWIS.R C Division of Project & Resident Programs 83/12/28 WILLIAMS.J W Florida Power & Light Co 1p 22220 286 24X Fiche 50-335.84/01/18.8402140242
- --8402140266 Responds to NRC 831114 ltr re violations noted in IE Insp Repts 50-335/83-34 & 50-389/83-62 Corrective actions all motor operated valves on locked valve list verified to have locked wheels Procedure revised to include signature blanks WILLIAMS.J W Florida Power & Light Co 83/12/14 O'REILLY, J P Region 2. Office of Director 2pp 22220 287 24X Fiche 50-335,84/01/18,8402140242
- --8402140275 Forwards IE Insp Repts 50-335/83-34 & 50-389/83-62 on 830911-1010 & notice of violation DANCE.H C Division of Project & Resident Programs 83/11/14 WILLIAMS.J W Florida Power & Light Co 2pp 22220 289 24X Fiche 50-335,84/01/18,8402140242
- --8402140283 Notice of violation from insp on 830911-1010 * Region 2. Office of Director 83/11/14 2pp 22220 291 24X Fichs 50-335,84/01/18,8402140242
- --B402140303 IE Insp Repts 50-335/B3-34 & 50-369/B3-62 on B30911-1010 Noncompliance noted failure to implement procedures re valves, locks & switches ELROD, S A , BIOB, H E Region 2, Office of Director LANDIS, K Division of Project & Resident Programs 83/11/10 5pp 22220 293 24X Fiche, 50-335, 84/01/18, 8402140242
- 8402150373 Forwards IE Insp Rept 50-387/84-01 on 840104-05 No violations or deviations noted DANCE, H C Division of Project & Resident Programs 84/01/18 WILLIAMS, J W Florida Power & Light Co 2pp 22241 330 24X Fichs 50-387,84/01/18,8402150373
- --8402130378 IE Insp Rept 50-389/84-01 on 840104-05 No violations or deviations noted. Major areas inspected fire protection MILLER.W H Region 2. Office of Director CONLON.T E Division of Engineering & Operational Programs 84/01/12 4pp 22241 332 24X Fiche 50-387,84/01/18,8402130373
- 8402140085 Provides supplemental response to IE Bulletin 83-06 re nonconforming matls supplied by Tube-Line Corp Two 4-inch elbous in shield bldg ventilation sys discussed in 831206 Itr will be replaced WILLIAMS.JW Florida Power & Light Co 84/01/20 O'REILLY,JP Region 2. Offices of Director ip 22217 198. 24X Fiche 50-000.84/01/20.8402140085
- 8402140076 Provides supplemental response to IE Bulletin 83-06 re nonconforming matts supplied by Tube-Line Curp Two 4-inch albows in shield bldg ventilation sys discussed in 831206 ltr will be replaced WILLIAMB.JW Florida Power & Light Co. 84/01/23 0'REILLY.JP Region 2. Office of Director ip 22217 254 24X Fiche: 50-000,84/01/23.8402140076
- 8312120153 IE Info Notice 84-06, "Steem Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). B4/01/25 Consolidated Edison Co of New York, Inc 120pp. 22058 001 24X Fiche 50-000.84/01/25,8312120153
- 8402080224 Forwards IE Insp Repts 50-335/84-01 & 50-389/84-02 on 840107-13 No violations noted DANCE.H C Division of Project & Resident Programs 84/02/02 WILLIAMS., W Florida Power & Light Co 2pp 22130 221 24X Fiche, 50-335,84/02/02,8402080224
- --8402080477 IE Imap Repts 50-335/84-01 & 50-389/84-02 on 840109-13 No violations noted Major areas inspected security organization, security program audit, physical barriers & detection aids Details withheld (ref 10CFR2 790 & 73 21) HALL, B. L., MCGUIRE, D. R. Region 2, Office of Director 84/02/02 1p 22130:223 24X Fiche 50-335,84/02/02,8402080224,

- 8401190016 J£ Info Notice 84-07. "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York Inc 119pp 22114 179 24X Fiche 50-000.84/02/03.8401190016
- 8401170017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEYQUNG.R C Director's Office. Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177
- 8402100321 Notification of 840209 meeting u/C-E in Bethesda, MD to discuss proposed C-E alternate reactor trip sys SELLS, D E Operating Reactors Branch 3 84/02/03 MILLER, J R Operating Reactors Branch 3 2pp 22205 118 24X Fiche 50-335,84/02/03,8402100321
- 8402140353 Advisos that, due to administrative error, IE insp rept dtd 831219 incluéed incorrect rept number Correct rept number is 50-389/83-68 DANCE, M C Division of Project & Resident Programs 84/02/03 WILLIAMS, J W Florida Power & Light Co Ip 22220 100 24X Fiche 50-387,84/02/03,8402140393
- 8402280148 Ack receipt of 840123 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-335/83-41 & 50-389/83-69 JOSOF BOTO TO STATE THE STATE OF PROJECT & Resident Programs WILLIAMS, J W Florida Power & Light Co ip 2240 Fiche 50-335,84/02/08,8402280148 22400 292
- --8402280156 Responds to NRC 831222 ltr re violations noted in IE Insp Repts 50-335/83-41 & 50-389/83-69 Corrective actions condition of oil noted on both plant work orders Unly preventive maint activities will be listed on work orders WILLIAMS.J. & Florida Power & Light Co. 84/01/23 D'REILLY.J.P. Region 2. Office of Director 2pp 22400 293 24X Fiche 50-335.84/02/08.8402280148
- --8402280166 Forwards IE Insp Repts 50-335/83-41 & 50-389/83-69 on 831128-1203 & notice of violation DANCE.H C Division of Project & Resident Programs 83/12/22 WILLIAMS.J W Florida Power & Light Co 2pp 22400:295 24) Fiche 50-335,84/02/08.8402280148
- --8402280174 Natice of violation from insp on 831128-1203 * Region 2, Office of Director 83/12/22 ip 2240 Fiche 50-335,84/02/08,8402280148 22400 297 24X
- --8402280186 IE Insp Repts 50-335/83-41 & 50-389/83-49 on 831128-1203 Violation identified failure to follow maint procedures for primary containment internal pressure & RCS safetu injection vanx JENISON.K M Region 2. Office of Director ELROD.S A Div of Project & Resident Programs 83/12/22 8pp 22400 298 Fiche 50~335.84/02/08.8402280148 Division
- 840119004i IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (100FR50.App R) " Syc list encl JURDAN,E L Division of Emergency Preparedness & Engineering
 - UDRDAN, E.L. Division of Emergency Preparadness & Engineering Response (Past 830103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365-259 24% Ficher 80-000,84/02/13,8401190041
- 8401190039 IE Info Notice 84-08, "IOCFRSO 7, 'Employee Protection " Syc list enc1

 JORDAN, E L Division of Emergency Preparedness & Engineering

 Mesponse (Post 830103) 84/02/14 Consolidated Edison Co. of New

 York, Inc. 115pp 22365-141 24X Fiche.50-000,84/02/14,8401170039
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Westinghouse Type SA-1 Differential Relays." Svc list encl JDRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830(03), 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366, 142 24% Fiche 50-000, 84/02/15, 8401190045
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN,E E. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/21 Consolidated Edison Co. of New York, Int 116pp 22366.024 24% Fiche 50-000.84/02/21.8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies" MO1190066 IE Info Nuvice Land...
 Syc list enc!
 JDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/02/24 Consolidated Edison Co of New
 York, Inc. 119pp. 22430 304 24% Fiche 50-000,84/02/24,8401190066

- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals " #0119006/ is into house 2. --Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/27 Consolidated Edison Co of New York, Inc 120pp 22431 060 24X Fiche 90-000,84/02/27,8401190067
- S Reportable occurrences, LERs & related correspondence
- 8402140475 RO on 840120 discovered that qualified safety parameter display sys functional test rept due 840115 had not been submitted Caused by personnel error Personnel counseled WILLIAMS.J W Florida Power & Light Co 84/02/03 O'REILLY, J P Region 2. Office of Director 2pp 22221 115 24X Fiche 50-389,84/02/03,8402140495
- 8402270236 LER 84-001-00 on 840119.while at 100% power turbine & reactor tripped Caused by generator ground & potential transformer drawer disconnect contacts misaligned, Contacts realigned W/840221 ltr MCLAUGHLIN.L., WILLIAMS, J W Florida Power & Light Co 84/02/18 2pg 22367 232 24% Fiche 50-387,84/02/18,8402270238
- U Congressional/Executive Correspondence
- 8402240277 Responds to FOIA request for three categories of documents NUZZ402// Responds to FUIA request for three categories of documents re facilities Forwards App A Documents 1-4 Documents 5-9 provided previously via svc list FELTON. J M Division of Rules and Records 84/01/27 8UGARMAN.R Sugarman & Denworth 2pp 22394 298 24X Fiche 50-000.84/01/27, 8402240277
- --8308090022 Forwards second quarterly status rept for 1983 on actions taken re operating reactors & licensing reviews of new facilities facilities ABSELBTINE, J K Commissioners 83/07/21 BEVILL, T House of Rep , Appropriations 11pp 22394 300 24% Fiche 50-000, 84/01/27,8402240277
- DOCKET 50-370 WATTS BAR NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8402090003 Responds to FOIA request for const completion dates for NUMBER OF THE PROPERTY OF THE
- --8402070250 Handwritten notes & calculations re const schedule activities & fuel load preparation Related info encl * NRC No Detailed Affiliation Oiven E3/10/31 10pp 22176 287 24X Fiche 50-000,63/10/31,8402090003
- E402140144 Forwards summary of 840112 meeting w/util in Atlanta, GA re program for control of welding filler matl during AWS Di 1 welding of safety-related structures
 LEWIS.R C Division of Project & Resident Programs 84/01/23.
 PARRIS.H O Tennossee Valley Authority 4pp 22218 245 24X
 Fiche 50-390.84/01/23.8402140144
- 8402030076 Notification of 840127 meeting w/util in Bethesda,MD to discuss util use of structural Welding Code AMS D 1-1 at facilities KENYON,T J Licensing Branch 4 84/01/25 ADENSAM,E G. Licens Branch 4 3pp 22091 115 24X Fiche 50-390,84/01/25,8402030076
- B40216006B Application for amend to CPPR-91, revising Tech Spec surveillance requirements for amergency diesel fuel impurity level tests MILLS.L M Tennessee Valley Authority 84/01/31 ADENBAM.E Licansing Branch 4 ip 22275 241 24X Fiche 50-390,84/01/31, 8402160068
- 8402070206 Advises that date of 840321 acceptable for meeting w/NRC to discuss program plan for detailed control room design reviews Concurrence on meeting date requested MILLS;L.M. Tennessee Valley Authority 84/02/01, ADENBAN,E Licensing Branch 4 1p 22102 212 24X Fiche, 50-000, 84/02/01, 8492070206
- 8402090578 Requests offsite dose calculation manual be submitted at earliest possible date to support final approval of radiological effluent Tech Spect ADENBAM.E Licensing Branch 4 84/02/03 PARRIG.H 9 Tennesser Valley Authority 2pp 22187:347 24X Fiche 50-390.84/02/03.0402090878

- 8402090325 Forwards response to Section 2 1 of Generic Ltr 81-07 re NUREG-0612. 'Control of Heav, Loads at Nuclear Power Plants 'Response to Sections 2 2.2 3 & 2 4 will be provided 6 months before rirst fuel load MILLS.L. H. Tennessee Valley Authority 84/02/06 ADENSAM.E Licensing Branch 4 179pp 22162 001 24x Piche 50-390 84/02/06.8402070325
- 8402/30113 Notification of rescheduled 840210 meeting U/util in Bethesda.MD to discuss how util utilizes Spec G-29C to modify AMS D I-I KEMYON, T J Licensing Branch 4 84/02/06 ADENSAM E G Licens Branch 4 Jpp 22213 306 24X Fische 50-390,84/02/06.8402130113
- 8402140195 Submits requested info describing how limiting tank concentration value determined as specified in Tech Spec Limiting Condition for Operation 3 11 1 4 Limiting tank concentration is 9,171 MILLS,C. M. Tennessee valley Authority 84/02/07 ADENSAM.E. Licensing Branch 4 2pp. 22223 332 24X Fiche 50-390,84/02/07.8402140195
- B402130541 Notification of 840214-16 meetings w/util in Knoxville & Sumetwater. Th to audit equipment qualification program KENVON, I J Licensing Branch 4 B4/02/07 ADENSAM E Licensing Branch 4 3pp 22258 314 24X Fiche 50-390.84/02/07.8402150541
- B402160294 "TVA Watts Bar Nuclear Plant Auxiliary Feedwater Sys Independent Review, 'supplementary Fept & App A describing followup data # Black & Veatch 84/02/07 1678pp 22264 001 24X Fishe 50-390,84/02/07.8402160294
- 8402170112 "Offsite Dose Calculation Manual " W/840208 ltr MILLS,L M Tennessee Valley Authority 84/02/08 ADENSAM.E Licensing Branch 4 77pp 22300 051 24X Fithe 50-370,84/02/08, 8402170112
- 8402170031 Forwards facility staffing surveys in response to 840112 ltr Addl info requested during 840126 meeting currently in preparation MILLS, L. M. Tennessee Valley Authority 84/02/07 ADENBAM. E. Licensing Branch 4. 8pp. 22J01 077 24X Fiche 50-000,84/02/07,8402170031
- B402240037 Advises that six vol supplementary rept re independent review of auxiliary feedwater sys shipped via United Pacel Svc ZIDZIUNAS,W J. Black & Veatch B4/02/I3 ADENSAM,E Licensing Branch 4 ip 22375 308 24X Fiche 50-370, 84/02/I3, 8402240037
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- B402130461 Forwards SSER 2 W/o encl NOVAK.T M Assistant Director for Licensing 84/01/30 PARRIS.H G Tennesses Valley Authority 2pp 22216 051 24X Fiche 50-390,84/01/30,8402130461
- B402100502 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF WATTS BAR NUCLEAR PLANT, UNITS 1 AND 2 Docket Nos 50-370 And 50-371 (Tennessee Valley Authority) Pulyision of Licensing NuREC-0847 502 84/01/31 379P Available at NRC 3 75 22213 107 24% Fiche 50-370, 84/01/31, 8402100502
- B402140397 Forwards updated status on certain SER fire protection items & updated info on miscellaneous commitments
 MILLS.L M Tennessee Valley Authority 84/02/09 ADENSAM.E
 Licensing Branch 4 5pp 22220 335 24X Fiche 50-390.84/02/09.
 8402140397
- 8402280259 Forwards indication of responsibility for each outstanding & confirmatory SER item re action required for receipt of OL & detailed info including schedules NRC review of 34 items needed to support June 1984 fuel load date NRC review of Republic NRC review of 34 items needed to support June 1984 fuel load date NRC Republic NRC Repu
- F Security, madical, emergency & fire protection plans
- 8402150220 Forwards IE Insp Rept 50-390/83-55 on 831212-16 No violations or deviations identified VERRELLIO M Division of Project & Resident Programs 84/01/17 PARRIS, H G Tennessee Valley Authority 2pp 22244-074 24X Fiche 50-390,84/01/17,8402190220

- --B402150229 IE Insp Rept 50-390/B3-55 on B31212-16 No violations or deviations identified Hajor areas Inspected const status & as-built configuration of gaseous radwaste sys & preoperational testing of gaseous radwaste sys HOBEY C M Region 2 Office of Director BARR. K P Division of Engineering & Operational Programs B4/01/10 7pp 22244 076 24X Fiche 50-390,84/01/17,8402150220
- B402060382 Forwards Rev 7 to generic security personnel training & qualification plan Rev withheld (ref locfR73 21)
 MILLS-L M Tennessee Valley Authority 84/01/19 D'REILLY. J P
 Region 2. Office of Director 1p 22086 317 24X
 Fiche 50-000-84/01/19.8402060382
- 8402140384 Forwards summary of 840113 meeting in Region 11 ofc re energency protective actions required by NUREG-0654 & clarified by IE Info Notice 83-28 VERBELLI, D.M. Division of Project & Resident Programs 84/01/26 PARRIS.H. G. Tennessee Valley Authority 4pp 22220 042 24X Fiche 50-000,84/01/26,8402140384
- B402130316 Forwards Rev 8 to generic security personnel training & qualification plan Rev withheld MILLSiL M Tennessee Valley Authority 84/01/27 D'REILLY, J F Region 2. Dffice of Director ip 22197 149 24X Fiche 50-000.84/01/27.8402130316
- B40203018B Forwards rev to physical security plan & responses to NRC comments, per B30524 request Encls withheld (ref 10CFR73 21) MILLS.L M Tennessee Valley Authority B4/01/30 DENTON.H R Defice of Nuclear Reactor Regulation. Director 1p 22057 362 243 Fiche 50-390.84/01/30.8402030188
- B402100214 Forwards "Rept on Ejectrical Circuit Protective Matls
 Under Classification Program," per 830726 commitment to
 provide UL test rept for 1 h fire rated barriers used to
 separate redundant safe shutdown circuits
 MILLS.L M Tennessee Valley Authority B4/01/30 ADENSAM, E
 Licensing Branch 4 1p 22179 049 24X Fiche 50-390, B4/01/30.
 B402100214
- --B402100216 "Rept on Electrical Circuit Protective Matls Under Classification Program" * Underwriters Laboratory 83/10/19 175pp 22179 050 24X Fiche 50-390,84/01/30,8402100214
- 8402160089 Forwards response to requirements of Rev 2 to Reg Guide 1 97.per Section 6 2 of Suppl 1 to NVREG-0737 (Generic Ltr 82-33) & util 830415 ltr re gost-accident monitoring to assess plant & environs during accident MILLS.L M Tennessee Valley Authority 84/01/30 ADENSAM.E Licensing Branch 4 35pp 22276 152 24x Ficha 50-390.84/01/30.8402160089
- 8402160642 Requests submittal of changes to physical security plan identifying onsite water sources required for EDCS as vital equipment-per NRC 840113 ltr Measures to protect sources should be described ADENSAM.E G Licensing Branch 4 84/02/06 PARRIS.H G Tennesse Valley Authority 3pp 22301 345 24X Fiche 50-390, 84/02/06. 8402160642
- B402140397 Forwards updated status on certain SER fire protection its & updated info on miscellaneous commitments HILLS,L M Tennesses Valley Authority 84/02/09 ADENSAM.E Licensing Branch 4 5pp 22220 335 24% Fiche 50-390.84/02/09.8402140397
- 840221027B Revs to Muscle Shoals emergency control ctr implementing procedures, including Procedure MSEC IP-1 re notification of unusual event alert or transportation accident & MSEC IP-2 re site emergency or emergency director V/840210 ltr MILLS/L M Tennessee Valley Authority 84/02/02 76pp 22315 OX 24X Fiche 50-000,84/02/02,840221027B
- B402230207 Forwards add1 info re radiological emergency plan (REP) emergency action levels.per B31216 request & draft REP revs Radiation monitors set to alarm before reaching Tech Spec limits MILLS,L H Tennessee Valley Authority B4/02/15 ADENSAM.E Licensing Branch 4 37pp 22351 267 24X Fiche 50-390. 84/02/15, B402230207
- J Insurance & indemnity information
- 8402160343 Forwards Endorsement 24 to NELIA Policy NF-256 Amended site description also entl DUCK.J R Marsh & McLennan, Inc 84/02/06 SALTZMAN.J Assista Director for State & Licenses Relations 3pp 22268 348 24X Fiche 50-390

- R Utility Final Safety Analysis Report (FSAR) & amends
- 8402060232 Forwards affidavit certifying Amend 49 % suppl to Amend 49 of FSAR served upon listed individuals on 840126 MILLS L M Tennessee Valley Authority 84/01/30 ADENSAM.E Licensing Branch 4 2pp 22087 254 24x Fiche 50-390,84/01/30,8402060232
- O Inspection reports, IE Bulletins & correspondence
- 8402140077 Forwards IE Insp Repts 30-390/83-52.50-391/83-41, 50-438/83-32 & 50-439/83-32 on 831212-15 No violations or deviations noted VERRELLI.D M Division of Project & Resident Programs 84/01/09 PARRIS.H 0 Tennessee Valley Authority 2pp 22217 255 24X Fiche 50-000.84/01/09.8400140077
- --8402140084 IE Insp Repts 50-370/83-52.50-371/83-41.50-438/83-32 & 50-437/83-32 on 831212-15 No violations or deviations noted Major areas inspected licensee action on previous enforcement matters

 HRIGHT.R W Region 2. Office of Director UPRIGHT.C M Division of Engineering & Operational Programs 84/01/04 5pp 22217 257 24X Fiche 50-000,84/01/09.8402140077
- 8402140197 Forwards IE Insp Repts 50-390/83-53 & 50-391/83-42 on 831212-16 No violations or deviations nated VERRELLIPM Division of Project & Resident Programs 84/01/16 PARRISH 9 Tennessee Valley Authority 2pp 22223 334 24X Fiche 50-390,84/01/10,8402140197
- --BA02140198 JE Insp Repts 50-390/83-93 & 50-391/83-42 on 831212-16 No violations or deviations noted Major Breas inspected licensee action on const deficiency repts & fullowup on NRC inspector identified problems JACK80N.L H Region 2. Office of Director UPRIGHT.C M Division of Engineering & Operational Programs 84/01/09 4pp 22223 336 24X Fiche 50-390.84/01/10.8402140197
- 8402150220 Forwards IE Insp Rept 50-390/83-55 on 831212-14 No violations or deviations identified VERRELLI.D M Division of Project & Resident Programs 84/01/17 PARRISH G Tennessee Valley Authority 2pp 22244 074 24X Fichs 50-370.84/01/17.8402190220
- --8402150229 IE Insp Rapt 50-390/83-55 on 831212-16 No violations or deviations identified Major areas inspected const status & as-built configuration of gaseous raduaste sys preoperational tosting of gaseous raduaste sys HOSEY, C M Region 2. Office of Director BARR, K P Division of Engineering & Operational Programs 84/01/10 7pp 22244 076 24X Fiche 50-390.84/01/17,8402150220
- 1402150134 Forwards IE Insp Repts 50-390/83-54 & 50-391/83-43 on 831128-1224 No violations or deviations noted VERRELLI,D M Division of Project & Resident Programs 84/01/23 PARRIS.H G Tennéssee Valley Authority Rpp 22250 008 24X Fiche 50-390.84/01/23.8402150134
- 8402150143 IE Insp Repts 50-390/83-54 & 50-391/83-43 on 831128-1224 No violations or deviations noted Major areas inspected presperational testing preparation & procedures, review of Tech Specs & independent insp #ffort SHAN.W B. HOLLAND.W E. Region 2. Office of Director JULIAN.C A Division of Project & Resident Programs 84/01/23 9pp 22250 010 24X Fiche 50-390.84/01/23.8402150134
- 2120153 IE Info Notice 84~04, "Steam Binding of Auxiliary Feedwater Jumps " Svc list encl INDAN,E L Division of Emergency Preparedness & Engineering sponse (Post 830103) 84/01/25 Consolidated Edison Co of New rk, Inc 120pp 22058 001 24X Fichs 50~000,84/01/25,8312120153
- OO23 Forwards IE Insp Repts 50-390/84-02 & 50-391/84-02 on 10-13 No violations or deviations noted ELLI,D M Division of Project & Resident Programs 84/01/26 PARKIEL M G Tennessee Valley Authority 2pp 22401 112 24X Fiche 50-390,84/01/26,8402280023

- 8402150355 Updates 831122 response to IE Bulletin 83-04 re nonconforming matts supplied by Tube-Line Corp Subj matts supplied to facilities by Capitol Pipe & Steel Products Co MILLS, L M Tennessee Valley Authority 84/02/02 O'REILLY, Jr, Region 2. Office of Director 118pp 22243 001 24X Fiche 50-000.84/02/02.8402150355
- B401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York. Inc 119pp 22114 179 24X Fiche 50-000,84/02/03.8401190016
- B401190017 JE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers" Bvc list encl DEYDUNG:R C Director's Office Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177.156 24X Fiche 50-000,84/02/03,8401190017
- B4Dil90041 IE Info Notice 84-09. "Lessons Learned From NRC Insps of Fire Protection Bafe Shutdown 89s (10CFR50: App R). " Svc list enc!

 URDAN: E L Division of Emergency Preparedness & Engineering Response (fost B30103) 84/02/13 Consolidated Edison Co. of New York, Inc 124pp. 22369 259. 24X Ficha 50-000.84/02/13.8401190041
- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection'" 8vc list entl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/14 Consolidated Edison Co of New York, Inc 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- 8401190045 IE Info Notice 83-43, Suppl 1. "Potential Failures of Weatinghouse Type 84-1 Differential Relays " Svc list encl JURDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp. 22366 142 24X Fiche 50-000,84/02/15,8401190045
- B401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 8 8)1013 84/02/21 Consolidated Edison Co. of New York, Inc 116pp R2366 024, 24% Fiche 50-000,84/02/21,8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies." Svc list encl. JORDANE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/24 Consolidated Edison Co. of New York, Inc. 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals," Svc list encl, JURDAN, EL Division of Emergency Preparedness & Engintering Response (Post 830103) 84/02/27 Consolidated Edison Co of New York, Inc 120pp. 22431 060 24X Fiche 50-000,84/02/27,8401190067
- 8 Reportable occurrences, LERs & related correspondence
- 8402030226 First interim deficiency rept re calculated peak containment temp. Initially reported on 831227 Coinvestigation w/
 Hestinghouse continuing Next rept will be submitted by 840330
 MILLS.L.M Tennessee Valley Authority 84/01/27 0'REILLY, J.F.
 Region 2, Office of Director 2pp 22067 147 24X
 Fichs 50-390,84/01/27,8402030226
- B402140371 Third interim deficiency rept re loading on dissel generator for LOGA & blackout causing unacceptable frequency transient. Initially reported on 831007 Morris-Knudsen evaluating item Next rept by 840309
 MILLS,L M Tennesse Valley Authority 84/02/02 D'REILLY,J P Region 2, Office of Director. Ip 22220 074 24X
 Fiche: 50-390, 84/02/02, 8402140371
- 8402220007 First interim deficiency rapt re temp of IE medium voltage cables in cable trays Initially reported on 840118 Htudy to determine if cables will exceed max continuous copper temp of 90 C in progress Next rapt will be submitted by 840307.
 MILLGL M Tennessee Valley Authority 84/02/15 O'REILLY, J P. Region 2. Office of Director 2pp 22338 312 24X
 Fiche: 50-390, 84/02/15, 8402220007
- 8402220014 Third interim deficiency rept re control room pressurization boundary loss through floor & equipment drains, Initially repurted on 831221 Next rept expected by 840402.

 MILLS,L.M Tennessee Valley Authority, 84/02/15 p'REILLY,JP Region 2, Office of Director. 2pp 22337:274 24X Fiche: 80-070.84/02/15,8402220014

- B402270191 First interim deficiency rept re damage to control wiring on Hestinghouse Type DB low voltage circuit breakers Initially reported on B40117 Causad by wires routed across sharp edges of breaker frame MILLS.L M Tennessee Valley Authority 84/02/16 D'REILLY, J P Region 2, Office of Director 2pp 22391 328 24X Fiche 50~000.84/02/16,8402270171
- 8402280556 Revised final deficiency repts re insp requirements & GA program for pipe insulation Initially reported on 811007 & 821008 Rev to Mechanical Design Guide DG-Mi8 O 1 issued to describe general documentation & insp requirements MILLB,L M Tennesses Valley Authority 84/02/21 O'REILLY,J P Region 2, Office of Director 2pp 22406 283 24X Fiche 50-390,84/02/21,8402280556

V Operator Examinations

B40215017B Confirms B4020A telcon re B4020B mgt meeting at Region III ofc to discuss discrepancies identified in operator training records at facility Proposed agenda encl.

LEWIB.R.C Division of Project & Resident Programs 84/02/07 PARRIB.H Q Tennessee Valley Authority 2pp 22245 137 24X Fiche 50-390,84/02/07,840215019B

DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- 8402070003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A,B & C documents FELTON.J M Division of Rules and Records 83/10/31 ROSENBAUN.D M. Technical Analysis Corp 19pp 22193-292 24X Fiche 50-000-83/10/31,8402070003
- --8402070230 Handwritten notes & calculations re const schedule activities & fuel load preparation, Related info encl
 * NRC No Detailed Affiliation Given 83/10/31 10pp 22176/289 24X Fiche 50-000, 83/10/31,8402090003
- 8402140144 Forwards summary of B40112 meeting w/util in Atlanta, GA re program for control of welding filler matl during AWS D1 i welding of safety-related structures
 LEWIB.R. C. Division of Project & Resident Programs 84/01/23
 PARRIS.H 0 Tennessee Valley Authority 4pp. 22218-245 24X
 Fiche. 50-390, B4/01/23, B402140144.
- B402030076 Notification of B40127 meeting w/util in Bethesde.MD to discuss util use of structural Welding Code AMS D 1-1 at facilities KENYON.T.J Licensing Branch 4 84/01/25, ADENBAM.E 0 Licensing Branch 4 3pp 22091 115 24X Fiche 50-390.84/01/25,8402030076
- 8402070206 Advises that date of 840321 acceptable for meeting w/NRC to discuss program plan for detailed control room design reviews Concurrence on meeting date requested.

 MILLS.L. M Tennessee Valley Authority 84/02/01 ADENBAM.E
 Licensing Branch 4 1p. 22102.212 24X Fiche 50-000,84/02/01,8402070206
- 8402090598 Requests offsite dose calculation manual be submitted at earliest possible date to support final approval of radiological effluent Tech Specs.

 ADENBAM.E Licensing Branch 4, 84/02/03, PARRIB.H G, Tennesses Valley Authority. Rpp 22189 349 24X Fichs.50-390,84/02/03,8402090598
- B402090325 Forwards response to Bection 2 i of Generic Ltr Bi-07 re NUREO-O6i2, "Control of Heavy Loads at Nuclear Fower Plants." Response to Bections 2 2, 2 3 & 2 4 will be provided 6 months before first fuel load.

 MILLS:L.M Tennessee Valley Authority. 84/02/06 ADENBAM.E Licensing Branch 4 479pp. 22162 001 24X Fiche. 50-390, 84/02/06. B402090325.
- 8402130113 Notification of rescheduled 840210 meeting w/util in Bathesda.MD to discuss how util utilizes 8pec 0-270 to modify AWS D 1-1.
 KENYON,T.J. Licensing Branch 4. 84/02/04. ADENSAM.E 9 Licensin Branch 4. 3pp. 22213
- B402150541 Notification of 840214-16 meetings w/util in Knoxville & Sweetwater, TN to audit equipment qualification program. KENYON, T J. Licensing Branch 4 84/02/07 ADENBAM. E. Licensing Branch 4. 3pp. 22258:314 24X Fichs.50-390, B4/02/07, 8402150541

- 8402160294 "TVA Watts Bar Nuclear Plant Auxiliary Feedwater Sys Independent Review: "supplementary rept & App A describing followup data * Black & Veatch 84/02/07 1678pp 22264 001 24X Fishe 50-390, 84/02/07, 8402160294
- B402170112 "Offsite Dose Calculation Manual " W/B4020B ltr MILLS.L M Tennessee Valley Authority B4/02/0B ADENSAM, E Licensing Branch 4 77pp 22300 051 24X Fiche 50-390, B4/02/0B, 8402170112
- 8402170051 Forwards facility staffing surveys in response to 840112 ltr Addl info requested during 840126 meeting currently in preparation MILLS.L M Tennessee Valley Authority 84/02/09 ADENBAM.E Licensing Branch 4 8pp 22301 077 24X Fiche 50-000.84/02/09, 8402170051
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8402130461 Forwards SSER 2 W/o entl NDVAK.T M Assistant Director for Licensing 84/01/30 PARRIS,H G Tennesse Valley Authority 2pp 22216 051 24X Fiche 50-390.84/01/30.6402130461
- B402100502 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF WATTS BAR NUCLEAR PLANT.UNITS 1 AND 2 Docket Nos 50-390 And 50-391 (Tennessee Valley Authority)

 * Division of Licensing NURE0-0847 SO2 B4/01/31 39pp Available at NRC 3 75 2213 109 24X Fiche 50-390, 84/01/31, B402100502
- 8402140397 Forwards updated status on certain SER fire protection items & updated info on miscellaneous commitments MILLS.L M Tennessee Valley Authority 84/02/09 ADENSAM.E Licensing Branch 4 5pp 22220 335 24X Fiche 50-390.84/02/09.8402140397
- 8402280259 Forwards indication of responsibility for each outstanding & confirmatory SER item re action required for receipt of GL & detailed info including schedules NRC review of 34 items needed to support June 1984 fuel load date MILLS, L M Tennessee Valley Authority 84/02/21 ADENSAM, E Licansing Branch 4 6pp 22399 136 24X Fiche 50-390, 84/02/21, 8402280259
- F Security, medical, emergency & fire protection plans
- 8402060382 Forwards Rev 7 to generic security personnel training & qualification plan Rev withheld (ref 10CFR73 21)
 MILLS.L M Tennesse Valley Authority 84/01/19 0'REILLY, J P
 Region 2. Office of Director 1p 22086:317 24X
 Fiche. 50-000, 84/01/19, 8402060382
- 84021403B4 Forwards summary of 840113 meeting in Region II ofc re emergency protective actions required by NVREG-0654 & clarified by IE Info Notice 83-28 VERRELLI,D M Division of Project & Resident Programs 84/01/26 PARRIB,H 9 Tennessee Valley Authority 4pp 22220 042 24X Fichu 50-000,84/01/26,8402140384
- B402130316 Forwards Rev B to generic security personnel training & qualification plan Rev withheld MILLS.L M Tennessee Valley Authority 84/01/27 O'REILLY, J P Region 2. Office of Director. 1p 22197 149 24X Fiche. 50-000
- B402030iBB Forwards rev to physical security plan & responses to NRC comments.per B30524 request Encls withheld (ref 10CFR73 21)

 MILLB.L M Tennessee Valley Authority B4/01/30 DENYON, H R Office of Nuclear Reactor Regulation, Director 1p 22067 362 24X Fiche 50-390, B4/01/30, B402030168
- 8402100214 Forwards "Rept on Electrical Circuit Protective Matls Under Classification Program." per 830726 commitment to provide UL test rept for 1 h fire rated barriers used to separate redundant safe shutdown circuits MILLB.L M Tennessee Valley Authority. 84/01/30, ADSNSAM.E Licensing Branch 4 ip 22179 049 24X Fiche 50-390,84/01/30,8402100214
- 8402160089 Forwards response to requirements of Rev 2 to Reg Guide 1,97, per Section 6 2 of Suppl 1 to NUREG-0737 (Generic Ltr 82-33) & util 830415 ltr re post-accident monitoring to assess plant & environs during accident MILLS,L. M Tennessee Valley Authority 84/01/30 ADENSAM.E Licensing Branch 4 35pp 22276 152 24X Fiche 50-390.84/01/30, 8402160089.

- 8402160642 Requests submittal of changes to physical security plan identifying onsite water sources required for ECCS as vital equipment, per NRC 840113 ltr Measures to protect sources should be described ADENSAM.E G Licensing Branch 4 84/02/06 PARRIS.H G Tennes Valley Authority 3pp 22301 345 24X Fiche 50-390.84/02/06.
- Tennessee Valley Authority 8402160642
- B402140397 Forwards updated status on certain SER fire protection items & updated info on miscellaneous commitments
 MILLS.L M Tennessee Valley Authority B4/02/09 ADENSAM.E
 Licensing Branch 4 5pp 22220 335 24X Fiche 50-390,84/02/09,
 B402140397
- 8402210278 Revs to Muscle Shoals emergency control ctr implementing procedures, including Procedure MSEC IP-1 re notification of unusual event, elect or transportation accident & MSEC IP-2 re site emergency or emergency director W/840210 ltr MILLS, L. M. Tennessee Valley Authority 84/02/02 76pp 22315 (24X Fiche 50-000, 84/02/02, 8402210278
- 8402230209 Forwards addl info re radiological emergency plan (REP) emergency action levels per 831216 request & draft REP revs Radiation monitors set to alarm before reaching Tech Spec
 - limits
 MILLB.L M Tennessee Valleg Authority 84/02/15 ADENBAM.E
 Licensing Branch 4 37pp 22351 267 24x Fiche 50-390.84/02/15.8402230209

Insurance & indemnity information

- 2160343 Forwards Endorsement 24 to NELIA Policy NF-256 Amended Ite description also enci JCK, J R Marsh & McLeenan, Inc 84/02/06 SALTZMAN, J Assistant Iractor for State & Licensee Relations 3pp 22268 348 24X tchs 50-390,84/02/06,8402160343
- Utility Final Safety Analysis Report (FSAR) & emends
- .02060232 Forwards affidavit certifying Amend 49 & suppl to Amend 49 of FBAR served upon listed individuals on 840126 MILLS.L H Tennessee Valley Authority 84/01/30 ABENSAM, E Licensing Branch 4 2pp 22087 254 24% Fiche 50-390,84/01/30,8402060232
- O Inspection reports, IE Bulletins & correspondence
- 402140077 Forwards IE Insp Repts 50-390/83-52,50-391/83-41, 50-438/83-32 & 50-439/83-32 on 831212-15 No violations or aviations noted

 ERRELLID M Division of Project & Resident Programs &
 ARRIS, H G Tennessae Valley Authority 200 22217 255

 iche 50-000,84/01/09.8402140077
 - 64/01/09
 - 402140084 IE Insp Repts 50-390/83-52.30-391/83-41.50-488/83-32 & 50-439/83-32 on 831212-15 No violations or deviations noted Major areas inspected licenses action on previous enforcement matters WRIGHT, R W. Region 2. Office of Director UPRIGHT, C M. Division of Engineering & Operational Programs 84/01/04 5pp 22217 257 24X Fiche 30-000,84/01/09,8402140077
- 402140197 Forwards IE Insp Repts 50-390/83-53 & 50-391/83-42 on E31212-14 No violations or deviations noted VERRELLI,D M Division of Project & Resident Programs 84/01/10. PARRIS, H O Tennessee Valley Authority 2pp 22223 334 24X Fichs 50-390.84/01/10.8402140197
- --8402140198 IE Insp Repts 50-390/83-53 & 50-391/83-42 on 831212-14 No violations or deviations noted Major areas inspected licensee action on const deficiency repts & followup on NRC inspector identified problems ACKBONL H, Region 2, Opfice of Director UPRIGHT, C M Divisio of Engineering & Operational Programs B4/01/09 App. 22223 336 24X Fiche 50-390.84/01/10,8402140197 Division
- 1402150134 Forwards IE Insp Repts 50-390/83-54 & 50-391/83-49 on 831128-1224 No violations or deviations noted VERRELLI, D M Division of Project & Resident Programs 84/01, PARRISH 9. Tennessee Valley Authority 2pp 22250 008 24) Fiche 50-390,84/01/23,8402150134 B4/01/23
- --B402150143 IE Insp Repts 50-390/83-54 & 50-391/83-43 on B31128-1224 No violations or deviations noted Major areas inspected preoperational testing preparation & procedures, review of Tach Specs & independent insp sefort.

 BHAN, H B , HOLLAND, H E Region 2, Office of Director, JULIAN, C A Division of Project & Resident Programs. 84/01/23 9pp 22250 010 24X Fiche 50-390,84/01/23,8402130134.

- 8312120153 IE Info Natice 84-04. "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 84/01/25 Consolidated Edison Co of New
 York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120133
- 8402280023 Forwards IE Insp Repts 50-390/84-02 & 50-391/84-02 on 840110-13 No violations or deviations noted VERRELLID M Division of Project & Resident Programs (PARRIB, H O Tennessee Valley Authority 2pp 22401 112 Fiche 80-390,64/01/26,6402280023
- --8402280033 IE Insp Repts 50-390/84-02 & 50-391/84-02 on 840110-13 No M22B0033 It lash Mepter 30-39704-02 at 30-39724-02 on 44010-1 violations or deviations noted Major areas inspected preoperational test procedure review witnessing & followup of previously identified insp findings
 THOMAS.M Region 2, Office of Director JAPE, F Division of Engineering & Operational Programs 84/01/25 4pp 22401 11
 24% Fichs 50-390,84/01/26.8402280023
- 8402130355 Updates 831122 response to IE Bulletin 83-06 remontonforming maths supplied by Tube-Line Corp Sub, maths supplied to facilities by Capitol Pipe & Steel Products Co MILLS.L M Tennessee Valley Authority 84/02/02 O'REIL Region 2, Office of Director 118pp 22243 001 24X Fiche 30-000.84/02/02.8402150355 O'REILLY, J P
- B401190016 IE Info Notice 84-07: "Design-Basis Threat & Review of Vehicular Excess Controls" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 117pp 22114 179 24X Fiche 50-000,84/02/03.6401190016 117рр
- B401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Bvc list encl DEYCUNG.R C Director's Office. Office of Inspection and Enforcement. B4/02/03 Consolidated Edison Co of New York, Inc 102pp 2217
- B401170041 IE Info Notice 84-09. "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR30, App R) " Syc list encl encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp. 22365-259 24X Fiche 50~000,84/02/13,8401190041
- 8401190039 IE Info Natice 84-08, "10CFR50 7, 'Employee Protection '" Syc list encl
 JURDAN, E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc. 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- B401190045 IE Info Notice B3-63, Suppl 1, "Potential Failures of Westinghouse Type BA-1 Differential Relays " Svc list encl JOROAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/15 Consolidated Edison Co of New York, Inc 118pp 22366 142 24X Fichs 50-000, 84/02/15, 8401190045
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Spt Below Manufacturer Recommended Value." Svc list sncl.
 JORDAN.E L Division of Emergency Preparadness & Engineering
 Response (Post B30103) B4/02/21 Consolidated Edison Co of New
 York, Inc. 116pp 22366-024, 24X Fichs 50-000.84/02/21,8401190062
- 8401170066 IE Info Notice 84-11, "Training Program Deficiencies,"
- 8401190067 IE info Notice 84-12, "Failure of Soft Seat Valve Seals " UNC DIST enci.

 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103). 84/02/27 Consolidated Edison Co. of New
 Yerk, Inc. 120pp 22431.060 24X Fiche 50-000.84/02/27,8401170067.
- 8 Reportable occurrences. LERs & related correspondence
- 8402030226 First interim deficiency rept re calculated peak containment temp. Initially reported on 831229. Coinvestigation w/ Hestinghouse continuing Next rept will be submitted by MILLS, L M Tennessee Valley Authority 84/01/27 Region 2: Office of Director 2pp 22067:147 2 Fichs.50-390:84/01/27:8402030226. n'REILLY, J P

- B402140370 Tenth interim deficiency rept re qualification of epoxy grout for safety-related applications Initially reported on B10827 Util in process of revising drawings under Engineering Change Notice 3487 Next rept expected by 840608 MILLS.L M Tennessee Valley Authority 84/02/01 D'REILLY.J P Region 2. Office of Director ip 2220 056 24X Fiche 50-391,84/02/01.8402140370
- B402140371 Third interim deficiency rept re loading on diesel generator for LOCA & blackout causing unacceptable frequency transient Initially reported on 831007 Morris-Knudsen evaluating item Next rept by B40309 MILLS.L M Tennessee Valley Authority 84/02/02 G'REILLY, J P Region 2. Office of Director 1 p 22220 074 24X Fiche 50-390.84/02/02.8402140371
- B402220219 Revised final deficiency rept re high pressure fire protection pipe not setsmically supported over safety injection sys pump Initially reported on 830711 Piping will be seismically supported for pressure boundary integrity MILLS.L M Tennessee Valley Authority B4/02/13 0'REILLY,J P Region 2. Office of Director 3pp 22338 360 24X Fiche: 50-391,84/02/13,8402220219
- 8402220007 First interim deficiency rept re temp of IE medium voltage cables in cable trays Initially reported on 84018 Study to determine if cables will exceed max continuous copper temp of 90 C in progress Next rept will be submitted by 840307 MTLLS.L M Tennessee Valley Authority 84/02/15 0'REILLY, J P Region 2, Defice of Director 2pp 28338 312 24X Fiche 50-390.84/02/15.84082820007
- 8402220014 Third interim deficiency rept re control room pressurization boundary loss through floor & equipment drains Initially reported on 831221. Next rept expected by 840402 MILLS.L.M. Tennessee Valley Authority 84/02/15 O'REILLY, J.P. Ragion 2. Office of Director 2pp 22337 274 24X Fiche 50-370,84/02/15,8402220014
- 8402270191 First interim deficiency rept re damage to control wiring on Mestinghouse Tupe D8 low voltage circuit breakers Initially reported on 84019 Caused by wires routed across sharp edgas of breaker frame MILLB.L.M Tennessee Valley Authority 84/02/16 O'REILLY,J P Region 2, Office of Director 2pp. 22391 328 24% Fiche 50-000,84/02/16,8402270191
- 8402280556 Revised final deficiency repts re insp requirements & GA program for pipe insulation Initially reported on Bil009 & 821008 Rev to Mechanical Design Guide DQ-M18 0.1 issued to describe general documentation & insp requirements MILLS.L.M Tennesses Valley Authority. 84/02/21 O'REILLY, J. P Region 2. Office of Director 20p 22406 283 24X Fiche: 50-390,84/02/21,8402280556

DOCKET 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1 A. Application/construction stage documents & correspondence

- 8402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel mestings. Forwards App A,B & C documents
 FELTON.J.M. Division of Rules and Records 83/10/31
 RDSEMBAUM.D M. Technical Analysis Corp 19pp 22193 292 24X
 Fiche 50-000.83/10/31.8402090003.
- --8402070220 Handwritten notes & calculations re const schedule & fuel load preparation. Related info anci * NRC - No Detailed Affiliation Given, 79/10/15, 55p 22176 232 24X Fiche 50-000.83/10/31,8402070003
- F. Becurity, medical, emergency & fire protection plans
- E402140200 Advises of approval of Rev 11 of emergency plan & Rev 3 to corporate emergency mgt plan Emergency plans meet planning stds of 10CFR50, 47(b) & requirements of App E to 10CFR50. VERRELLI,D,M Division of Project & Resident Programs, 84/01/26 DIXON,O,W Bouth Carolina Electric & Qas Co. 2pp. 22223 340 24X Fiche 50-395,84/01/26,8402140200.
- 8402060430 Forwards Rev 10 to physical security plan Rev withheld (ref 100FR2.790).
 DIXON.D.W. South Carolina Electric & Gas Co 84/01/27. DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22085 270 24X Fiche 50-395,84/01/27,8402060430
- 8402060001 Forwards IE Safeguards Insp Rept 50-395/84-04 on 840109-13 No violations or deviations noted. VERRELLIDM. Division of Project & Resident Programs. 84/01/31 DIXON.O.W. Bouth Carolina Electric & Gas Co. 2pp. 22083 268. 24X Fiche: 50-395/84/01/31/8402060001.

- --8402060002 lE Safeguards Insp Rept 50~395/84-04 on 840109-13 No violations noted Major areas inspected security organization, physical barriers, access control & detection aids Rept details withheld (ref 10CFR73 21 & 2.790) ENNIS.JD Region 2, Office of Director MCGUIRE.DR Division of Emergency Preparedness & Materials Safety 84/01/30 1p 22083 270 24X Fiche 50~395,84/01/31,8402060001
- 8402070386 Forwards revs & changes to Emergency Plan Procedures EPP-002 & EPP-005 DIXON.O W South Carolina Electric & Gas Co 84/02/02 DENTON,H R Office of Nuclear Reactor Regulation, Director 23pp 22095 082 24X Fiche 50-395,84/02/02,8402070386
- B40214000B Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per 810709 Generic Ltr 81-27 W/o request entire plan will be placed in PDR ADENSAM, E O Licensing Branch 4 84/02/06 DIXON, O W South Carolina Electric & Oas Co 2pp 22251 348 24X Fiche 50-395,84/02/06,840214000B
- B402180137 Forwards request that full-scale participation by affected local govts & substantial participation by State of 8C not be required FEMA will support exemption from 10CFR90, App E, Bection IV F I
 KRIMM.R Federal Emergency Management Agency B4/02/0B
 JURDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 3pp 22250 017 24X Fiche 50-379,84/02/08,
- P Operating license stage documents & correspondence
- 8312120029 Generic Ltr 83-39 to representatives of utils re-voluntary survey of licensed operators Svc list encl EISENHUT, D 0 Division of Licensing 83/12/08 Commonwealth Edison Co 12pp 22313 006. 24X Fiche 50-000, 83/12/08, 8312120029
- 8402030080 Summary of 840111 meeting w/util in Bethesda,MD re existing & proposed cold overpressure protection sys Viewgraphs encl HOPKINS,J Licensing Branch 4 84/01/23 Licensing Branch 4 14pp 22091 099 24% Fiche 50-395
- 8402010410 Generic Ltr 84-04 to all operating PWR licensees, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops 8vc list enri EISENHUT.D 0 Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc. 57pp 22177 087 24X Fiche. 50-000.84/02/01.8402010410
- 8402060470 Advises that design description of cold overpressure protection sys reevaluated & changed to circumvent single failure problem & use of power lockouts during sys operation, per NRC concerns raised during 840111 meeting DIXDN:O W South Carolina Electric & Gas Co 84/02/02 DENTON:H R Office of Nuclear Reactor Regulation, Director 4pp 22083 088 24X Fiche 50-395.84/02/02.8402060470
- 8402170073 Forwards Amend 21 to License NPF-12, safety evaluation & NSHC determination & noticing action Amend changes Tech Specs to transfer surveillance requirements from svc water sys to reactor cooling water sys NSHC available in Central Files ADENBAM, E. G. Licensing Branch 4 84/02/03 DIXON.O W. Bouth Carolina Electric & Gas. Co. 2pp. 22313 288 24X Fiche 30-395,84/02/03,8402170073
- --8402170075 Amend 21 to License NPF-12, changing Tech Specs to transfit surveillance requirements from svc water sys to reactor cooling water says
 ADENBAN, E Q Licensing Branch 4 84/02/03 opp 22313 289 24 Fichs 50-395,84/02/03,8402170073
- --8402170078 Bafety evaluation supporting Amend 21 to License NPF-12 * Office of Nuclear Reactor Regulation, Director 84/02/03 2pt 22313:275 24X Fiche 50-395,84/02/03,8402170073
- 8402240107 Responds to request for add1 info re NUREO-0737. Item II F 2 concerning reactor coolant inventory tracking, core exit thermacouple & subcooling margin monitor us Westinghouse subcooling margin monitor meets NUREO-0587 requirements DIXON.O W Bouth Carolina Electric & Oas Co 84/02/17, DENTON.H R Office of Nuclear Reactor Regulation, Director. 3pp 22375 005 24X Fiche 50-395,84/02/17,8402240107
- 8402270174 Forwards marked-up Tech Specs incorporating revised reporting requirements per Generic Ltr 83-43, "Reporting Requirements of 100FR50, Sections 50 72 & 50,73 & 878"
 DIXON, D W. South Cerolina Electric & Ges Co 64/02/22, DENTON, H
 Office of Nuclear Reactor Regulation, Director. 27pp 22425:216

- Q Inspection reports. IE Bulletins & correspondence
- B402140435 Forwards IE Insp Rept 50-395/83-37 on 831212-16 No violations or deviations noted VERRELLI.D M Division of Project & Resident Programs 84/01/13 DIXON.O W South Carolina Electric & Gas Co 2pp 22221 263 24 Fiche 50-395,84/01/13,8402140435
- --8402140437 IE Insp Rept 50-395/83-37 on 831212-16 No violations or deviations noted Major areas inspected plant water chemistry & inservice testing of pumps & valves ROSS.W J Region 2. Office of Director BLAKE, J J Division of Emergency Preparedness & Materials Safety 84/01/09 12pp 22221 265 24X Fiche 50-395,84/01/13,8402140435
- 8402150379 Forwards IE Insp Rept 50-395/83-39 on 831204-09 No violations noted VERRELLI.D M Division of Project & Resident Programs. 84/01/18 DIXON.O M South Carolina Electric & Gas Co 2pp 22242 002 24) Fiche.50-395,84/01/18,8402150379
- --8402150384 IE Insp Rept 50-395/83-39 on 831206-09 No violations noted Major areas inspected procedures, ALARA, training, exposure control, respiratory protection program, posting & controls, surveys & records & observations
 PEERY, W W Region 2. Office of Director BARR, K P Division of Engineering & Operational Programs 84/01/05 4pp 22242 004 24X Fiche 50-395,84/01/18,8402150379
- B312120153 IE Info Notice 84-05, "Steam Binding of Auxiliary Feedwater Pumps" Svc list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post B30103) B4/01/25. Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120153
- 8402060001 Forwards IE Bafeguards Insp Rept 30-395/84-04 on 840109-13 No violations or deviations noted VERRELLI.0 M Division of Project & Resident Programs 84/01/31 DIXON.0 H South Carolina Electric & Gas Co 2pp 22083 268 24) Fiche 50-395/84/01/31/8402060001
- --8402060002 IE Bafeguards Insp Rept 30-395/84-04 on 840109-13 No violations noted Major areas inspected security organization, physical barriers, access control & detection aids Rept details withheld (ref 10CFR73.21 & 2 790)
 ENNIS, J D Region 2, Office of Director MCGUIRE, D R Division of Emergency Preparedness & Materials Safety. 84/01/30 ip 22083 270 24X Fiche 50-395.84/01/31.8402060001
- 8402150179 Advises that rev to operational GA plan will be issed by B40215 Rev will correct inadequaties cited in Items A & B of notice of violation contained in IE Insp Rept 50-995/83-27
 DIXON.O W Bouth Carolina Electric & Gas Co B4/01/31
 D'REILLY,J P Region 2, Office of Director 1p 22245 239 24X Fichs 50-395.84/01/31.8402150179
- 8401190016 IE Info Notice B4-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Syc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Fost B30103) B4/02/03 Consolidated Edison Co. of New York, Inc. 119pp. 22114 179 24X Fiche 50-000.84/02/03.8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl. DEYOUND, R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 2217
- 8402190013 Informs that IE Insp Rept 50-395/83-36 contained two Page 4s Util should destroy Page 4 which contained injured employee name.

 VERRELLI, D.M. Division of Project & Resident Programs 84/02/06

 DIXON, D.W. South Carolina Electric & Gas Co. 2pp. 22247 308 24X

 Fiche 50-395.84/02/06.8402180013
- 8401190041 IE info Notice B4-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR30, App R) " Syc list enci.
 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/13 Consolidated Edison Co of New York, Inc. 124pp 22365 259 24X Fiche 50-000,84/02/13,8401170041
- 8401170039 IE Info Notice 84-09, "10CFR50.7, 'Employee Protection ("
 Svc list encl
 JORDAN, EL Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/14. Consolidated Edison Co of New
 York, Inc. 115pp. 22365.141 24X Fiche 50-000,84/02/14,8401170039

- B401190045 IE Infa Notice 83-63, Buppl 1, "Potential Failures of Mestinghouse Type SA-1 Differential Relays" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/15 Consolidated Edison Co of New York, Inc. 118pp 22366 142 24X Fiche 50-000, 84/02/15, 8401190045
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Bet Below Manufacturer Recommended Value " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/21 Consolidated Edison Co of Nau York, Inc. 114pp 22346 024 24X Fiche 50-000,84/02/21,8401190062
- B401190066 IE Info Notice B4-11, "Training Program Deficiencies "
 Svc list enc]
 JDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/02/24 Consolidated Edison Co of New
 York, Inc. 115pp 22430 304 24X Fiche 50~000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
 Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060 24X Fichs 50-000,84/02/27,8401170067
- R Periodic operating reports & related correspondence
- 8402060392 "Environ Monitoring Rept.1982 " W/B40202 ltr * Dames & Moore DIXDN.O W South Carolina Electric & Qas Co 82/12/31 DENTON.H R Office of Nuclear Reactor Regulation, Director 200pp 22085 272 24% Fiche 50-395,82/12/31.8402060392
- 8402130272 Forwards "Seismic Activity Near VC Summer Nuclear Station," Guarterly Technical Rept 83-3 for Jul-Sept 1983
 DIXON.O.W South Carolina Electric & Gas Co 84/02/07 DENTON, H R
 Office of Nuclear Reactor Regulation, Director ip 22198 232
 24X Fiche 50-395, 84/02/07, 8402130272
- --8402130275 "Seismic Activity Near VC Bummer Nuclear Station," Quarterly Technical Rept 83-3 for Jul-Sept 1983 TALWANI.P South Carolina, Univ of, Columbia, BC 83/09/30 17pp 22198:233 24X Fiche 50-395,84/02/07,8402130272
- S Reportable occurrences. LERs & related correspondence
- 840214037B Requests add1 info re Part 21 rept dtd 83110B concerning wear ring failure in auxiliary feedwater pump furnished to facilities Info requested within 25 days POTAPDVB.U Region 4. Office of Director. 83/11/30 PATTY.D.F. Bingham-Willamette Co ip 22221 250 24X Fiche.50-000.83/11/30, 840214039B
- --8402140422 Supplemental Part 21 rept re wear ring failure in auxiliary feedwater pumps, per 831130 request for add1 info Wear rings will be replaced on returned units w/AISI 420 wrought matl List of pumps in similar svc w/same wear ring encl PATTY, D.F. Bingham-Hillamette Co. 83/12/20 Region 4, Office of Director 2pp 22221.251 24X Fichs. 50-000, 83/11/30, 8402140378
- 8402070210 LER 84-001-00 on 831223-27 & 27, daily grab samples of every effluent not taken Caused by personnel error. Individual disciplined Separate list of daily, weekly & monthly Tech Spec requirements being generated W/840130 ltr BOUKNIGHT.R J., DIXON.D W. South Carolina Electric & Cas Co 64/01/30. 0'REILLY, J.P. Region 2, Office of Director 2pp 22101:182 24% Fichs 50-375,84/01/30,8402070210
- 8402140001 LER 84-002-00 on 840111, hourly roving fire watch petrol for auxiliary bldg not performed during previous 8 h per Tech Spec. Caused by personnel error Roving fire watches now verifying required checks w/shift supervisor. W/840202 ltr 80UMNIGHT.R J. DIXON.O.W. Bouth Carolina Electric & Gas Co 84/02/02 0 (REILLY, J. P. Region 2, Office of Director 2pp 22217 117 24X Fiche 50-395,84/02/02.8402140001.
- B402150120 LER 84-003-00 on 840112.24% of main plant vent exhaust RM-A3 & 66% of reactor bldg purge RM-A4 quarterly composite samples found missing Cause attributed to personnel error Procedures revised M/840208 ltr BLUE, L A . DIXON. D. W South Carolina Electric & Gas Co. 84/02/08 2pp 22249, 353. 24x Fiche 50-395,84/02/08,8402150120.

- 8402140235 Special Rept SPR 84-001 on 840110, licensee entered action statement of Tech Spec 3 7 10 by opening fire doors to chilled water pump rooms Evaluation determined enough cross ventilation would occur to ensure cooling SIXON.O W South Carolina Electric & Oas Co 84/02/09 Record Services Branch (Document Control Desk) 2pp 22221 039 24X Fiche 50-395,84/02/09,8402140235
- 8402220227 RO SPR 84-001 on 840110.licensee voluntarily entered action statement of Tech Spec 3 7 10, "Fire-Rated Assemblies," by opening fire doors to chilled water pump rooms Further calculations & documentation being accomplished DIXON.O & South Carolina Electric & Qas Co 84/02/09 2pp 22340 147. 24X Fiche 50-395,84/02/09,8402220227
- B402220070 LER 84-005-00 on 840117.steam generator B low level caused feedwater flow low reactor trip Caused by personnel error Surveillance test procedures under rev W/840215 ltr HODOMARD.K W. DIXON.O W. South Carolina Electric & Gas Co 84/02/15. 2pp 22337 237 24X Fiche 50-395,84/02/15.8402220070
- 8402220075 LER 84-004-00 on 840117, two cable junction boxes found not wrapped w/Kaowool & one cable run had damaged Kaowool in three areas Caused by const & maint activities in area Discrepancies repaired W/840215 ltr KOON.A R., DIXON.O W 80uth Carolina Electric & Gas Co 84/02/15 2pp. 22337 235. R4X Fiche 50-395,84/02/15,8402220075

DOCKET 50-396 UNIV. OF VIRGINIA CAVALIER REACTOR

P Operating license stage documents & correspondence

- 8402160692 Advises of 840730 expiration of OL & provides guidance for renewal of license Liet of required documentation submitted Renewal package encl W/o encl THOMAS.C O. Standardization & Special Projects Branch 84/02/06 BRENIZER, J. Virginia, Univ. of. Charlottesville. VA 3pp 22292 346 24X Fiche 50-396,84/02/06,8402160692
- DOCKET 50-397 WPPBB NUCLEAR PROJECT, UNIT 2

A Application/construction stage documents & correspondence

- 840:170065 Partial response to FOIA request for six categories of documents re facilities Forwards documents listed in Apps A & B Documents also available in FDR W/o App A documents FELTON, J. M Division of Rules and Records, 83/10/24 ANDERSON, 6 I Garvey, Schubert, Adama & Barer. 4pp 21838:003, 24x Fiche 50-397,83/10/24,8401170065
- --8401170071 Advises of results of NRC Caseload Forecast Panel visit to plant site during 811021-23. Estimated const completion date for Unit 1 is Feb 1986. Unit 4 not included in evaluation TEDESCO.R.L. Assistant Director for Licensing 81/12/08 FERQUEON.R.L. Heshington Public Power Supply System 3pp. 21838.007 24% Fiche 50-397,83/10/24,8401170065
- --840i170073 Forwards final agenda for NRC Casaload Forecast Panal BO0122-24 site visit GOODMAN A. Washington Public Power Supply System 80/02/21 Washington Public Power Supply System. 7pp 21838-015 24X Ficha: 50-397.83/10/24.8401170065
- --9401170077 Bummary of Caseload Forecast Panel 780613-15 site visits CDX, T H Light Water Reactors Branch 3, 78/09/28 Light Water Reactors Branch 3, 18pp 21838 023, 24X Fichs 50-377,83/10/24, 840177048
- --8401170083 "Level i Mgt Info Rept " Related info encl * Washington Public Power Supply System 80/01/30. 72pp 21838-106. 24X Fiche-50-397,83/10/24,8401170065
- --8401170089 "Project Status Rept for WNP-1,2,3,4 & 5."

 4 Washington Public Power Supply System. 78/04/30 299:
 21838.178 24X Fiche 50-397.83/10/24,8401170065
- --8401170092 "Project Trend Analysis Manpower Progress Schedule," Relâted info encl + Mashington Public Power Supply System 78/04/30 135pp. 21838: 207 24X Fiche: 50-397,83/10/24,8401170065
- 8402090003 Responds to FDIA request for const completion dates for nuclear plants currently under const & enalyses containing satimates based on inclusion of Castload Forecast Panel meetings Forwards App A:B & C documents.

 FELTON:J M Division of Rules and Records, 83/10/31
 ROSENBAUM,D M Technical Analysis Corp 19pp. 22193, 292, 24X
 Fiche:50-000,83/10/31,8402090003

- --Bill230250 Summary of 811019-21 caseload forecast panel meetings w/util at site re progress of engineering & const AULUCK.R Licensing Branch 2 Bi/11/05 Licensing Branch 2 ip 22196 317 24% Fiche 50-000,83/10/31,8402090003
- ~-8402070273 Trip rept of Caseload Forecast Panel 780613-15 site visits re const status assessment & projected completion date svaluation Related info encl COX.TH Light Water Reactors Branch 3 78/09/28 Light Water Reactors Branch 3 6pp 22196 311 24X Fiche 50-000, 83/10/31, 8402090003
- --8402090287 Handwritten notes re estimated & official fuel load dats * NRC - No Detailed Affiliation Given 81/10/17 ip 82176 318 24% Fiche 50-000.83/10/31.8402090003
- --B402090279 Trip rept of Caseload Forecast Panel B00226 site visits re factors affecting const schedule & const activity observation Related info encl LYNCH.M D Light Water Reactors Branch 4 80/04/24 Light Water Reactors Branch 4 App 22196 319 24X Fiche 90-000.83/10/31.8402090003
- 8402080430 Forwards, for info, "Rept to Governor J Speliman of State of MA & Governor V Atigeh of State of DR "Rept provides recommendations for solution to major problems involving or arising from WPPSS SDREMSEN.G C Washington Public Power Supply System 83/12/08 EISENHUT.D 0 Division of Licensing 1p 22148 284 24X Fiche 50-397.83/12/08.8402080430
- 8402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILK'S J Office of the Secretary of the Commission 83/12/14 Public Document Branch ip 22281 023 24% Fiche \$0-000,83/12/14,800150002
- --8402160402 Discusses SECY-82-476 re FOIA Appeal 82-A-23 on Commission consideration of requests for hearing on extension of CPs CHILM,8 J Office of the Secretary of the Commission 83/01/12 Office of the Secretary of the Commission 19 22281 255 24X Fiche 50-000,83/12/14,8402160003
- E NRC Bafety Evaluation Report (BER), supple & correspondence
- B402130002 Bubmits status of emergency preparedness license requirements for operation exceeding 3% gower, including TMI Item I D i re emergency response capability & offsite emergency preparedness, per BER & SEER 4
 SORENBEN. C Washington Public Power Supply System 84/02/03 SCHMENCER, A Licensing Branch 2 3pp 22204 087 24% Fiche: 50-377, 84/02/33,8402130002
- F Security, medical, emergency & fire protection plans
- 8402030265 Forwards IE Safeguards Insp Rept 50-397/84-02 on 840117-19 No/noncompliance noted Rept withheld (ref 100FR73-21 & 100FR2, 790)
 NORDERHAUD, L.R. Region 5, Office of Director 84/01/31
 BORENSEN, O.C. Hashington Public Power Supply System 2pp. 22067:111 24% Fiche 50-397, 84/01/31, 8402030265
- 8402130002 Submits status of emergency preparedness license requirements for operation exceeding 5% power, including TMI Item I D I re emergency response capability & offsite amargency preparedness, per 8ER & SBER 4 SORENSEN. O C. Washington Public Power Supply System 84/02/03 8CHWENCER, A. Licensing Branch 2 3pp 28204 087. 24X Fiche. 50-397, 84/02/03, 8402130002
- 8402230225 Forwards "Function & Task Analysis of Emergency Operating Procedures" & "Control Room Design Review Program Plan "
 BORENSEN, 0, C Washington Public Power Supply System 84/02/17 BCHWENGER, A Licensing Branch 2 ip 22352 123 24x Fiche: 50-397, 84/02/17, 8402230225.
- --8402230229 "Function & Task Analysis of Emergency Operating Procedures" * Washington Public Power Supply System 84/02/17 13pp. 22352 124 24X Fichs. 50-397,84/02/17,8402230225.
- --8402230232 "Control Room Design Review Program Plan"
 DEVALLE, R. G. Washington Public Fower Supply System 84/02/29
 68pp. 22352, 137 24X Fiche 50-397, 84/02/17, 8402230225.

- P Operating license stage documents & correspondence
- 8402070277 Advises that as-built stress analysis of RMR sys piping & evaluation of Burns & Roe floor response amplification analysis, not included in util final assessment rept, appear satisfactory Mods to previous conclusion unnecessary LANEY, R V Technical Audit Associates, Inc. 84/01/27 MAZUR, D W Washington Public Pawer Supply System 2pp 22095 011 24X Fichs 50-397,84/01/27,8402070297
- 8402070612 Requests resubmittal of request for amend to License NPF-21 Request must be in full conformance w/10CFR50 91 BCHWENCER.A Licensing Branch 2 84/01/27 SORENSEN.G C Washington Public Power Supply System 2pp 22187 360 24X Fiche 50-397.84/01/27.8402090612
- 0402130145 Expresses appreciation for staff efforts in timely execution of responsibilities such that issuance of license not critical item for fuel load SDRENSEN. O C Washington Public Power Supply System 04/02/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22200 047 24X Fichs 50-397,84/02/07.8402130145
- 8402160417 Forwards significant hazards analysis re proposed fech Spec change noted in 840120 request for license amend SOREMBEN. © C Washington Public Power Supply System 84/02/08 SCHMENCER, A Licensing Branch 2 4pp 22269 110 24X Fiche 50-397,84/02/08.8402160417
- 8402160447 Mod to 840120 application to amend License NPF-21, revising Yoch Specs to allow flexibility to perform more than one dissel generator cold start test per 184 days
 SCRENSEN.O C Mashington Public Power Supply System 84/02/08
 SCHWENCER.A Licensing Branch 2 3pp 22273-164 24X
 Fiche 50-397,84/02/08.8402160447
- --840R160450 Proposed Yech Spec 3/4 8 1 re electrical power sys,allowing flexibility to perform more than one diesel generator cold start test per 184 days
 * Washington Public Power Supply System 84/02/08 37pp
 22273 167 24X Fiche 50-397,84/02/08.8402160447
- 8402160449 Submits final summary of induction heating stress improvement program.per Rev 1 to NUREG-0313 & util 830914
 1tr Total of 214 welds in reactor recirculation & RHR reviewed
 SDREMBEN.g C Washington Public Power Supply System 84/02/08
 SCHNENCER.A Licensing Branch 2 2pp 22268 313 24X
 Fiche 50-397,84/02/08.8402160449
 - O2220015 Requests authorization to use ASNE Code Case N-362 for pressure testing of containment items.per 840210 telcon SURENBEN.9 C Washington Public Power Supply System 84/02/10 SCHMENCER.A Licensing Branch 2 2pp 22398 250 24X Fiche 50-397.84/02/10.8402220015
- i Inspection reports, IE Bulletins & correspondence
- 3402220137 FOLA request for Feb 1982 IE Insp Rept 50-397/82-05 & related documents concerning Sechtel review of generic problem areas
 BELL.N Coalition for Safe Power 83/11/01 Office of Administration 1p 22363 304 24X Fiche 50-397,83/11/01,8402220139
- --8402220142 Requests thorough file check for IE Insp Rept 50-397/82-05 & related info concerning Bechtel review of NRC repts NRC may have retained rept or portion of rept BELL, N Coalition for Safe Power 63/11/01 FELTON, J M Office of Administration 1p 22363 305 24X Fiche: 50-397, 83/11/01, 8402220139
- 3402220144 Responds to FDIA request for IE Insp Rept 50-397/82-05 & related documents concerning Bethtel review Forwards App A documents
 FELTON, J M Division of Rules and Records 83/12/07 BELL, N Cualition for Safe Power 2pp. 22363:306 24X
 Fiche 80-397.85/12/07.8402220144
- -8402220147 Except from GVP overview rept, Vol I, Book 1 of 1 Related info enc!
 * Bechtel Corp 83/12/07, 150pp 22343 308 24%
 Fiche 50-397,83/12/07,8402220144
- 402080027 Responds to appeal re denial of FDIA request for certain portions of five records on alterations by ITT Orinnell Corp of radiographs of welds in spining subassemblies Forwards Documents 10-14 of App A to Felton 830916 ltr DIRCKS, W J Dffice of the Executive Director for Operations 83/12/27 FDUALD M Wallace, Hibburn, Clayton, Calhoon & Forster, Ltd 1p 22173 312 24X Ficher 50-397, 83/12/27, 8402080027,

- --8402080058 Responds to IE Bulletin 82-01 re Associated Piping & Engineering radiographs for piping welds less than 1/2 inch in thickness Previous contractor will be notified & applicable radiographs will be reviewed JORDAN, R L Johnson Controls, Inc. 82/07/06 COLLINS, J T, Region 4. Defice of Director 2pp 22173 314 24X Fiche 50-397,83/12/29,8402080027
- 8402140279 Forwards IE Insp Rept 50-397/83-61 on 831227-30 No noncompliance noted BISHOP.T W Region 5. Office of Director 84/01/23 SORENSEN, G C Washington Public Power Supply System 1p 22228 285 24x Fiche 50-397,84/01/23,8402140279
- --B402140284 IE insp Rept 50-397/83-61 on B31227-30 No noncompliance or deviations noted Major areas inspected fuel loading activities, procedure review Tech Spec compliance, surveillance testing & independent insp WILLETT, D. J. DODDS, R. T. Region 5, Office of Director B4/01/23 4pp 22228 286 24% Fiche 50-397, B4/01/23, 8402140279
- 8312120183 IE Info Notice 84-04, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120153
- 8402140434 Forwards IE Insp Rept 50-397/83-58 on 831128-1220 86ARAND.R A Division of Radiological Safety & Safeguards Program 84/01/25 SURENSEN,O C Washington Public Power Supply System 2pp 22221 277 24% Fichs 50-397,84/01/25.8402140434
- --8402140445 IE Insp Rept 50-397/83-58 on 831128-1220 Noncompliance noted failure to include applicable acceptance criterion, to foilow test procedures for 10CFR50.App B, XI & to place radioactive piping in shielded trunk YUHAB.G F, MENELANEKI.F A Region 5. Office of Director 84/01/25 12pp 22221 279 24X Fiche 50-397.84/01/25.8402140434
- B402030287 Ack receipt of B31230 ltr informing NRC of add1 steps taken to correct violations noted in IE Insp Rept 50-397/83-37 BISHOP.T W Region 5. Office of Director B4/01/31 CARLISLE.C 8 Washington Public Power Supply System 1p. 22069 310 24% Fiche 50-397.84/01/31.8402030287
- --8402030262 Responds to NRC 831104 ltr re violations noted in IE Insp Rept 50-397/83-37 Corrective actions math, equipment, parts & supplies procurement procedure revised to preclude ordering obsolete spars parts SORENSEN, 0 C Hashington Public Pawer Supply System 83/12/30 MARTIN.J B Region 5, Office of Director Rep 22069, 311 24X Fiche 50-397,84/01/31,8402030257
- 8402030265 Forwards IE Safeguards Insp Rept 50-397/84-02 on 840117-19. No/noncompliance noted. Rept withheld (ref 10CFR73-21 & 10CFR2 790)
 NORDERHAUO, L. R. Region 5, Office of Director, 84/01/31. BURENERN, C. Washington Public Power Supply System 2pp 22067 111 24X Fiche 50-397.84/01/31.8402030265
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN: EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co. of New York, Inc 119pp 22114 179 24X Fiche. 50-000.84/02/03.8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers" Syc list encl DEYDUNG.R C. Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp. 22177 156 24X Ficher 50-000, 84/02/03, 8401190017
- 840117004: IE Info Notice 84-07, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (100FR50, App R) " Syc list enc!

 JORDÁN-E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365 207 24% Fithe 50-000,84/02/13,8401190041.
- 8401170039 IE Info Notice 84~08, "10CFR50.7. 'Employee Protection '"
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co. of New
 York, Inc 115pp 22365 141 24X Fishe 50-000,84/02/14,8401170039
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Westinghouse Type 8A-1 Differential Relays," Svc list encl. JORDAN.E.L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366 142 24X Fiche 50-000,84/02/15,8401190045

- 8401190062 IE Info Notice 84~10. "Motor-Operated Valve Torque Switches Bet Below Manufacturer Recommended Value " Bvc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc. 116pp 22366 024 24X Fiche 50-000,84/02/21,8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies "
- Svc list encl
 JORDAN: E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B4/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- 8401190967 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
- 401190067 it into musice 07-12.

 Syc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York. Int 120pp 22431 060 24% Fiche 50-000.84/02/27.8401190067
- R Periodic operating reports & related correspondence
- 8402020141 Monthly operating rept for Dec 1983 W/840110 1tr COWAN.K D , MARTIN.J D Washington Public Power Supply System 83/12/31. Office of Resource Management, Director App 22034 163 24X Fiche 50-397.83/12/31.8402020141
- B Reportable occurrences, LERs & related correspondence
- 8402080029 Responds to FOIA request for documents re facility hot SOZOBOURY Responds to FDIA request for documents re facility functional testing problems, including broken thermowells, loose & broken reactor coolant pump parts & loose thermal slewws. Forwards App A documents Documents also in PDR FELTON.J M Division of Rules and Records 83/11/16 QA QBVernment Accountability Project 3pp 22170:233 24X Fiche: 50-000:83/11/16.8402080029 GARDE, B
- --8402080036 List of hot functional testing exceptions Related info encl * Affiliation Not Assigned B3/11/16 19pp 22170 236 24x Fiche 50-000,83/11/16,8402080029
- 8402030357 Forwards LERs 83-002/03L-0.83-003/03L,83-004/03L,83-005/03L, 83-006/03L,83-007/03L,83-008/03L & 83-009/03L MARTIN.J D. Washington Public Power Supply System 84/01/20, MARTIN.J.B. Region 5, Office of Director 1p 22066 083 24X Fiche: 50-397,84/01/20.8402030357
- --8402030364 LER 83-002/03L-0 on 831231, discovered fire protection storage water level in FP-TK-100 less than 280,000 gallons Caused by air binding of filter effluent pump while FP-P-107 in manual mode due to inadequate procedural instructions COLEMAN.L. F Washington Public Power Supply System. 84/01/20 ip. 22046.084 24X Fiche 50-377,84/01/20,8402030337
- -B402030371 LER 83-003/03L: on 831222, walk down revealed that fire dampers WMA-FD-1, 2, 7, 8, 7, 10, 11, 14, 15, 18 & DRA-FD-34-1 did not comply w/U. fire rating Caused by vendor cutting dampers to required size CATLOW, R. D. Washington Public Power Supply System 84/01/20 22066 085 24X Fiche 50-397, 84/01/20, 8402030357 Washington Public Power Supply System 84/01/20 1p
- --B402030378 LER 83-004/03L on 831222; loss of fire detection instrumentation occurred at 606-ft elevation of reactor hldg Caused by condensation shorting out detection sys Power supply replaced & condensation source being corrected.

 GATLOW, R D Mashington Public Power Supply Bystem 84/01/20 ip 22066 086 24X Fiche. 30-397,84/01/20,8402030337
- --B402030380 LER 83-003/03L on 831223. fire-rated seals removed to perform const work causing loss of fire boundary integrity, per Tach Specs. Caused by plant mod Beals will be replaced after const completed ork completed ATLOW.R.D Washington Public Power Supply System 22066 087. 24% Fiche 50-397.84/01/20.8402030357. CATLOU. R. N.
- --8402030386 LER 83-006/03L on 831222, firs-rated Door D-104 violated, causing loss of fire boundary integrity Caused by fire-rated door closing, pinching welding lead & melting hole in door. Door replaced. CATLOW.R D Weshington Public Power Bupply System, 84/01/20 PATLOM: R D. Washington Public Power Bupply System, 84/01/20, ip 22066 088, 24% Fiche: 50-397,84/01/20,8402030357
- --B402030392 LER 83-007/03L.on 831222, fire hydrant FP-HT-10 did not drain 102030372 Ltm 83-007/03L. on 8312221119 hydrant rr-H1-10 old not or:

 4 froze during cold weather. Caused by contractor
 inadvertently blocking drain port for hydrant while pouring
 concrete Hydrant repaired.
 CATLOM. R. D. Washington Public Power Supply System 84/01/20. ip
 22046:089. 24X Fiche. 50-397.84/01/20.8402030357

- ---8402030375 LER 83-008/03L on 831222, damper WOA-SMD-1B malfunctioned Outlottine damper binded in track & was left in open position Cause unknown CATLOW-R D Washington Public Power Supply System 84/01/20 lp 22066 090 24X Fiche 50-397,84/01/20,8402030357
- --B402030401 LER B3-009/03L on B31222, fire damper NDA-SMD-1A manually propped open Caused by link holding damper open fusing due to influx of dust to activating detector Now link installed CATLOW.R D Washington Public Power Supply System B4/01/20 ip 22066 091 24X Fiche 50-397,84/01/20,8402030357
- 8402160377 LER 84-002-00 on 840111 control room outside air radiation monitors associated high radiation alarms tripped Caused by excessive electrical noise induced into radiation monitoring BARBEE, R J . M/ 84/02/10 3pp
- 8402220389 LER 84-003-00 on 840120 during initial low power shysics testing, intermediate range monitors A.B & D did not respond to increasing neutron flux, causing reactor to be shut down Caused by personnel error W/840216 ltr KASSAKATIS.L D . MARTIN.J D. Washington Public Power Supply System 84/02/16 3pp 22334 120 24X Fiche 50-397,84/02/16,8402220389
- 8402220512 LER 84-004-00 on 840119, intermediate range monitor channels A,B & D inoperable after initial criticality achieved Gaused by short electrical connection between signal cable & detector & failed electronic component W/B40216 itr KABBAKATIB,L D. MARTIN.J D Washington Public Power Bupply Bystem B4/02/16 4pp 22334 053 24X Fiche 50-397,84/02/16,8402220312
- 8402290111 LER 84-005-00 on 840123 & 0208 inadvertent auto start of HPCS diesel generator DG-1C occurred Caused by failure to properly tag out unit for maint activity Personnel strained W/B40222 1tr retrained W/B40222 ltr KA88AKATIS,L D., MARTIN.J D Washington Public Power Supply System 84/02/22 3pp 22427 350 24X Fiche 50-397,84/02/22,8402290111
- 8402290125 LER 84-004-00 on 840125 circuit breaker which supplies THE TRANSPORT OF THE PROPERTY OF THE PROPERTY
- 8402290131 LER 84-008-00 on 840128, suppression pool level exceeded Tech Bpec limits Caused by water in ref leg Burveillance procedures modified to insure that level transmitter atmospheric ref leg periodically drained W/840224 ltr KASBAKATIB, L D , MARTIN, J D Washington Public Power Supply System 84/02/24. 3pp 22426 170. 24X Fiche 50-397,84/02/24,8402290131
- 8402290293 LER 84-007-00 on 840127 & 31, reactor protection sys tripped Caused by personnel failing to correctly identify ref & variable leg of transmitter Red caution tags installed to prevent misidentification W/840224 1tr
 KASBAKATIS,L D , MARTIN,J D Washington Public Pawer Supply System 84/02/24 3pp. 22427 165 24X Fiche 50-397,84/02/24,8402290293
- T Rearing transcripts on non-antitrust matters
- 8402270302 Partial response to FDIA request for five categories of documents to mothballed nuclear const projects App A documents being placed in PDR Document as listed on App 8 already available in PDR. Bearch continuing FELTON.J M Division of Rules and Records 84/01/20 BELL, N Nuclear Information & Resource Service 3pp 22395 200 24% Fiche: 50-000, 84/01/20, 8402270302
- --8402270321 Testimony of JB Martin before Bubcommittee on Energy Conservation & Power re nuclear power plants being constructed by WPPSS Related info encl MARTIN. J B Region 5. Office of Director 83/09/14 86pp 22395.104 24% Fiche 50-000,84/01/20.8402270302
- DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1 A Application/construction stage documents & correspondence
- B402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing setimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documents.
 FELTON. J M Division of Rules and Records 83/10/31
 ROSENBAUM. D M Technical Analysis Corp 17pp 22193 272 24X
 Fichs 50-000.83/10/31.8402090003

- --8402090162 Handwritten notes & calculations re const activities * NRC - No Detailed Affiliation Given 83/02/17 10pp 22174.354 24X Fiche 50-000,83/10/31,8402090003
- 8402060525 Notification of 840207 meeting w/util in Bethesda.MD to discuss functional capability of Class 1 auxiliary piping sys
 - sys BUCKLEY.B C licensing Branch 3 84/01/27 KNIGHTON,O W Licensing Branch 3 4pp 22092 312 24X Fiche 50-400,84/01/27, 8402060529
- 8402010410 Generic Ltr 84-04 to all operating PWR licensees, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Svc list encl EISENHUT.D G Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc 59pp 22177 087 24X Fiche 50-000.84/02/01.8402010410
- 8402160474 Forwards request for addl info re Transamerica Delaval.Inc emergency diesel generators Requests that answers be specific for Transamerica Delaval.Inc diesel engine by ref to either owners group or plant-specific repts KNICHT.6 W Licensing Branch 3 84/02/06 UTLEY.E E Carolina Power & Light Co 3pp 22302 153 24X Fiche 50-400,84/02/06, 8402160474
- 340217006i Notification of B40210 meeting w/Transamerica Delaval, Inc (TDI) in Bethes6a-MD to discuss program plan proposed by TDI (Juners Group to qualify diesel generators CARUSULR Division of Licensing B4/02/06 BERLINGER, C Division of Licensing 2pp 22312 339 24X Fiche 50-000, 84/02/06, 840217006i
- .02150293 Forwards distribution list denoting correct number of documents listed individual supposed to receive ROMLEY-L W North Carolina, State of. 84/02/07 MNIGHTON, G. W Licensing Branch 3 4pp 22250 084 24X Fiche 50-400, 84/02/07, 8402150293
- 8402240001 Notification of date & time change to 840216 meeting w/util in BethesdarMD to discuss functional capability of Class 1 auxiliary piping sys
 BUCKLEY, B C Licensing Granch 3 84/02/10 KNIGHTON, G W
 Licensing Branch 3 4pp 22381 311 24X Fiche 50-400, 84/02/10, 8402240001

5 NRC Bafety Evaluation Report (BER), supple & correspondence

- 40213033B Forwards add1 info re SER Open Item 4 concerning min wall thickness of Class 1.2 & 3 piping sys Response clarifies design procedures used to control min wall thickness & responds to specfic NRC concerns MCDUFFIE.M A Carolina Power & Light Co 84/02/07 DENTON, HR Office of Nuclear Reaction Regulation. Director 7pp 22197-267 24X Fiche 50-400,84/02/07.8402130338
- 02290165 Submits add1 info in response to SER Open Item 8 re fire rotaction. Info includes listing of sys required for safe outdown backup info for auxiliary feedwater pump separation temption request & info on charging pump exemption request. DUFFIE:M A Carolina Power & Light Co 84/02/24 DENTON, H R. fice of Nuclear Reactor Regulation. Director 87pp 22419 068 X Fiche 50-400,84/02/24,8402290165

ecurity, medical, emergency & fire protection plans

- 140404 Ack receipt of 840113 itr informing NRC of steps taken to trect violations noted in IE Insp Rept 50-400/83-33, RRELLID.M Division of Project & Resident Programs 84/01/30 LEY, E & Carolina Power & Light Co Ip 22221 273 24% che 50-400,84/01/30,8402140404
- 2140450 IE Insp Repts 50-400/83-33 & 50-401/83-33 on 831020-1120 iolation noted inadequate corrective action on Deficiency & isposition Rept (DDR) 1916 re electrical genetrations AXMELL.Q F. PREVATTE.R L Region 2. Office of Director. EMIS.P R Division of Project & Resident Programs 83/12/13 pp 22221 301 24% Fiche 50-400,84/01/30,8402140404
- 90397 Advises that NRC will not review emergency plans to delete vacy or proprietary info unless specifically requested licenses, per BI0709 Generic Ltr BI-27 W/o request, entire an will be placed in PDR IGHTON, O. W. Licensing Branch 3. 84/02/14, UTLEY, E. E. Carolina wer & Light Co. 4pp. 22438 254 24X Fiche 50-400, 84/02/14, 402290387

B402290165 Submits addl info in response to SER Open Item 8 re fire protection Info includes listing of sys required for safe shutdown-backup info for auxiliary feedwater pump separation exemption request & info on charging pump exemption request MCDUFFIE.M A Carolina Power & Light Co 84/02424 DENTON-H R Uffice of Nutlear Reactor Regulation, Director 87pp 22419 068 24X Fishe 50-400,84/02/24,8402290165

G Adjudicatory correspondence

- 8402010191 Forwards summary of ACRS 285th meeting on 840112-14 re OL application & W Eddleman 840113 ltr re compromised plant safety NRC response to ACRS will be forwarded to ASLS & parties
 BARTH.C A Hearing Branch 1 84/01/20 KELLEY.J L., CARPENTER.J H., BRIGHT.O O. Atomic Safety and Licensing Board Panel 7pp 22039 348 24% Fiche 50-400.84/01/20.8402010191
- 8402010223 Response to intervenor W Eddleman 840103 request for order to require early filing of NRC responses to motions for summary disposition Request should be denied Certificate of Svc encl
 MODRE. J E Hearing Branch i 84/01/20 Atomic Safety and
 Licensing Board Panel 6pp. 22039 357 24X Fiche 50-400,84/01/20,8402010223
- 8402010190 Response supporting applicant 840103 motion to resume discovery on Joint Intervenors Contentions I & VII Discovery need not await resumption of environ hearings Certificate of Svc encl BARTH, C A Hearing Branch i 84/01/23 Atomic Safety and Licensing Board Panel 5pp. 22038 353 24X Fiche 30-400,84/01/23,2402310380
- 8402010193 Response opposing Eddleman 840103 proffered Contentions 169, 170,171 & 172 re safety parameter display sys Contentions do not comply whrequirements Certificate of Svc encl MOORE, J. E. Hearing Branch 1 84/01/30 Atomic 8efety and Licensing Board Panel 14pp 22038 337, 24X Fiche 50-400,84/01/30,8402010193
- 8402020227 Interrogatories & request for production of documents (fifth sat) BAUGER,D B Carolina Power & Light Co BAUSER,D B, Shaw, Pittman, Potts & Trowbridge, 84/01/30 Wilson,R Bpp 22037*054 24X Fiche 50~400,84/01/30,8402020227
- --8402020230 Interrogatories & request for production of documents (sixth set) Certificate of Svc encl.

 BAUBER, D B Carcoline Power & Light Co. BAUBER, D B Shaw,
 Pittman, Potts & Trombridge 84/01/30. Joint Intervenors Shearon Harris. 16pp 22057.062 24X Fiche 50-400,84/01/30,
 8402020227
- B402030306 Response to applicant motion for protective order ASLB should not enter proposed protective order but support approve Eddleman listed voluntary commitments EDDLEMAN.W Eddleman.W B4/01/30 Atomic Safety and Licensing Board Panel 10pp 22069 OB2, 24X Fiche 50-400,84/01/30, B402030306
- --B402030312 Motion for extension of time to respond to summary disposition on Eddleman Contention 65 re concrete problems until second round of discovery completed Certificate of negotiations encl
 EDDLEMAN.W Eddleman, W. 84/01/30 Atomic Safety and Licensing Board Panel, 2pp. 22069.092 24X Fiche 50-400,84/01/30.
- --8402030317 Motion to require svc of staff summary disposition responses which are in nature of motions for summary disposition on expedited schedule & motion to allow filing of motion.

 Certificate of Svc encl

 EDDLEMAN.W Eddleman.W 84/01/28 Atomic Safety and Licensing Board Panel 2pp. 22047:094 24X Fiche 50-400,84/01/30,84/02030304.
- --8402030320 General Interrogatories & interrogatories on Contention 65 to applicents.et al (seventh set)
 EDDLEMAN.W Eddleman, W 84/01/30 Carolina Power & Light Co 26pp. 22069 076 28% Fiche 50-400,84/01/30,8402030306
- --8402030321 Second round discovery to staff on Eddleman Contention 65 EDDLEMAN, W., Eddleman, W. 84/01/30 Atomic Safety and Licensing Board Panel, 2pp. 22069 122 24X Fiche, 50-400, 84/01/30, 8402030304
- --8402030324 Motion for order requiring svc of util rept required by IE Bulletin 83-08 re safety circuit breakers EDDLEMAN.W Eddleman, W 84/01/28 Atomic Safety and Licensing Board Panel ip 22069 124, 24X Fiche 50-400,84/01/30,8402030306

- B402030175 Advises that draft offsite emergency response plans should be available by mid-Feb 1984 Util filing for further info on Contentions 151 & 197 also expected by mid-Feb 1984 RIDGMAY, D. A. Shaw, Pittman, Potts & Troubridge RIDGMAY, D. A. Carolina Power & Light Co. RIDGMAY, D. A. North Carolina Municipal Atomic Safety and Licensing Board Panel 4pp 22068 125 24X Ficha 50-400,84/01/31,8402030175
- 8402040213 Forwards itr of agreement between util & Hammer, Vaughn & Johnson re onsite treatment of injured personnel.per ASLB 831101 memorandum & order on Eddleman Contention 151 Svc list entl
 RIDQWAY, D.A. Bhaw, Pittman, Potts & Trowbridge RIDGWAY, D.A. Cardina Power & Light Co. RIDGWAY, D.A. North Cardina Municipal Power Agencies 84/02/01 KELLEY, J.L., CARPENTER, J.H., BRIGHT, O.D. Atomic 8afety and Licensing Board Panel 5pp 22087 152 24X Fiche 50-400, 84/02/01,8402060213
- B402070031 Response supporting applicant 840113 motion for protective order re Eddleman Contention 41 Certificate of Svc enc!
 BARTH, C A Hearing Branch 1 B4/02/02 Atomic Safety and
 Licensing Board Panel 6pp 22102 347 24X Fiche 90-400, 84/02/02, 8402070031
- B402090047 Answer to N Eddleman motion for further deferral of parts of Contantion 107 & Eddleman new contentions & amended deferred contentions in response to NRC SER ABLB should deny motion & reject new SER contentions Certificate of Svc encl BAXTER.T.A Carolina Power & Light Co BAXTER.T.A Bhaw, Pittman, Potts & Trowbridge 84/02/06 Atomic Safety and Licensing Board Panel 69pp 22159 234 24X Fiche 50-400,94/02/04,8402090067
- 8402130314 Response to ASLB 840130 order re summary disposition of Joint Contention II EDDLEMAN.W. Eddleman, W. EDDLEMAN,W. Joint Intervenors - Bhearon Harris 84/02/06 Atomic Bafety and Licensing Board Panel 4pp 22197 073 24X Fiche 30-400,84/02/06,8402130314
- --B402130317 Request for clarification & objections to ASLB 840127 order re Eddleman Contentions 37A, 37B & BF2 Certificate of 8vc encl EDDLEMAN, W Eddleman, W 84/02/06 Atomic Safety and Licensing Board Panel 6pp 22197 077 24X Fiche 50-400,84/02/06, 84/02/30314
- --8402130322 Response to 840206 summary disposition on Joint Contention IV & discovery update to Joint Contention IV re TLD Certificate of Svc encl.
 EDDLEMAN, W Joint Intervenors Shearon Harris EDDLEMAN, W Eddleman, W 84/02/06 Atomic Safety and Licensing Board Panel 28pp. 22197:083 24X Fiche 50-400.84/02/06.8402130314
- 8402130233 Motion for summary disposition of Eddalman Contention 83/848 No genuine issue of matl fact exists & util entitled to favorable decision CARROW, H. Carolina Power & Light Co. CARROW, H. North Carolina Municipal Fower Agencies. 84/02/07 Atomic Bafety and Licensing Board Panel 11pp 22204,177 24X Fiche 30-400,84/02/07,8409180233.
- --B402130238 Statement of matl facts as to which there is no genuine issue CARROW.H Carolina Power & Light Co CARROW.H North Carolina Municipal Power Agencies 84/02/07 Atomic Safety and Licensing Board Panel, 50pp. 22204 188 24X Fiche 50-400.84/02/07. 8402130233
- --8402130246 Affidavit of WT Hogarth in support of summary disposition of Eddelman Contention 83/648 Applicants have adequately addressed health effects of chlorinated discharges from plant Certificate of 8vc encl HOGARTH, W T, Carolina Power & Light Co 84/02/06 35pp. 22204 244 24X Fiche 50-400,84/02/07,8402130233
- B402130266 Forwards proposed schedule for adjudicating security plan contentions Schedule agreed upon by parties in B40203 meeting Svc list enc!

 GARROH-H. Capolina Power & Light Co B4/02/0B KELLEY, J L ,
 BRIGHT, G D , CARPENTER, J H Atomic Safety and Licensing Board Panel Opp 22204 066 24X Fiche 30-400,84/02/08,8402130266
- 8402140061 Request for expedited ruling on timeliness of applicant B40207 motion for summary disposition of Eddleman Contention 83/848. Certificate of Svc encl Related correspondence EDDLEMAN.W Eddleman, W. 84/02/08 Atomic Barety and Licensing Board Panel 2pp. 22217:243 24X Fiche: 50-400, 84/02/08, 8402140061

- 8402150219 Comments on Board tentative schedule for evidentiary hearing on environ issues & for prehearing conference Schedule of 840605 presents difficulties as schedule relates to Joint Contention II(a) H/Certificate of Svc BAXTER, T A Carolina Power & Light Co BAXTER, T A North Carolina Municipal Power Agencies BAXTER, T A Shaw, Pittman, Potts & Troubridge 84/02/10 App 22244 143 24X Fiche 50-400,84/02/10,8402150219
- 8402160226 Motion to reconsider & admit Contention 58 re financial qualifications of co-applicants Certificate of Svc encl EDDLEMAN,W Eddleman,W 84/02/13 Atomic Safety and Licensing Board Panel 7pp 22274 307 24x Fiche 50-400.84/02/13.8402160226
- 8402220275 Response in support of applicant 840118 motion for summary disposition of W Eddleman Contention 65 No matl facts in dispute before ASLB Motion should be granted Certificate of Svc encl Related correspondence BARTH.C A Hearing Branch 1 84/02/13 15pp 22336 116 24X Fiche 50-400,84/02/13,8402220295
- 8402160201 Answer to W Eddleman 840130 motion for extension of time to respond to summary disposition on Eddleman Contention A5 until second round of discovery completed Motion should be denied & W Eddleman directed to file answers by 840228 BAXTER. T A Carolina Power & Light Co BAXTER. T A Shaw, Pittman, Putts & Trowbridge 84/02/14 Atomic 8afety and Licensing Board Panel 15pp 22275 277 24X Fichs 50-400,84/02/14,8402160201
- --B402160207 Motion for extension of time to respond to Eddleman discovery requests on Contention 65 unless & until ABLB serves order granting W Eddleman motion for extension to respond to summary disposition W/Certificate of Svc BAXTER.T A Carolina Power & Light Co BAXTER.T A Ghaw, Pittman. Potts & Trowbridge B4/02/14 Atomic Safety and Licensing Board Panel App 22275 272 24X Fiche 50-400, B4/02/14 B402160201
- B402160233 Response opposing W Eddleman 840128 motion for ASLB order requiring sec of applicant rept to NRC re safety circuit breakers Certificate of Sec encl O'NEILL. J H Carolina Power & Light Co Pittman. Potts & Troubridge 84/02/14 Atomic Bafety and Licensing Board Penel 6pp 22276 330 24X Fiche 50-400.84/02/14.
- B402170103 Certification to applicant B40118 motion for summary disposition of Eddjeman Contention 45 Motion Identifies one instance of honsycombing or voids in containment base matestreior walls & done Certificate of Svc encl DAXTER: T A Carolina Power & Light Co BAXTER: T A Bhaw, Pittman, Potts & Trombridge B4/02/15 Atomic Safety and Licensing Board Panel App 22301 088 24X Fichs 50-400,84/02/15.8402170103
- B402210115 Motion to withdraw Contention III re mgt capability, Cartificate of Svc encl WILBON, R Wilson, R 84/02/15 Commissioners 2pp 22317 151 24X Fiche 30-400,84/02/15.8402210115
- 8402220234 Response opposing W Eddleman 840217 motion for further deferral of parts of Contention 107 % motion for denial of admission of said parts of Contention 107 re deficient SER Certificate of Sec encil BARTH.C A Hearing Branch 1 84/02/16. Atomic Bafety and Licensing Board Panel 9pp 22340 223 24X Fiche 50-400.84/02/16.8402220234
- 8402220235 Response to W Eddleman 840117 new contentions re NRC SER Eddleman proposed Contentions 107-X,Y & Z & proposed Contentions 173-177,180 & 181 should be rejected Staff has no objection to Contentions 178 & 179 W/Certificate of Bvc MOORE,J E Hearing Branch 1 84/02/16 Atomic Safety and Licensing Board Panel 19pp 22340 198 24X Fiche 50-400,84/02/16,8402220235
- 8402220267 Forwards "Summary of Design Btds & Criteria for Technical Bupport Ctr Encompassing Human Factors Engineering," per Eddleman proposed Contention 157 Contention should be rejected Related correspondence HOLLAR, D E. Carolina Power & Light Co 84/02/17 KELLEY, J L. BRIGHT, G O. CARPENTER, J H. Atomic Safety and Licensing Board Panel 2pp. 22335 200 24% Fiche 50-400,84/02/17,8402220267
- --8402220267 "Summary of Design Stds & Criteria for Technical Support Ctr Encompassing Human Factors Engineering " * Carolina Power & Light Co 84/02/14 lipp 22335 202 24X Fiche 50-400,84/02/17.8402220267
- B4002B0226 Notice of withdrawal of 840130 motion to require syc of rept on D8-416 circuit breakers, based on 840216 conversation w/applicant Related correspondence EDDLEMAN.W Eddleman.W 84/02/20 ip 22400 064 24X Fiche 50-400.84/02/20,8402280226

- 8402279056 Response to Eddleman 840129 further interrogatories re Contention 65 Affidavit of PR Demis encl Related Correspondence
 - Correspondence
 BARTH.C A Hearing Branch 1 84/02/21 Eddleman, W 7pp
 22388 161 24X Fiche 50-400,84/02/21,8402270056
- --8402270060 Response opposing W Eddleman motion to require svc of applicant rept to NRC re safety circuit breakers Motion is most & applicant will serve Chapel Hill Anti-Nuclear Group Effort Related correspondence
 DARTH, C A Hearing Branch 1 84/02/21 Atomic Bafety and Licensing Board Panel 2pp 22388 168 24x Fiche 50-400, 84/02/21, 8402270056
- --8402270065 Response opposing W Eddleman 840128 motion to require svc of staff summary disposition responses on expedited schedule Certificate of Svc encl Related correspondence BARTH, C A Hearing Branch i 84/02/21 Atomic Safety and Licensing Board Panel 2pp 22388 170 24% Fiche 50-400, 84/02/21,8402270056
- 8402280323 Response to applicant motion for reconsideration of Security Contantion 4 Encl withheld (ref 10CFR73 21) Certificate of Svc encl
 - BVc encl RUNKLE.J Joint Intervonors - Shearon Harris 84/02/22 Atomic Safety and Licensing Board Panel 3pp 22399 122 24X Fiche 50-400,84/02/22,8402280323
- 8402280420 Response to Eddleman 840208 request for expedited ruling on timeliness of applicants 840207 motion for summary disposition of Eddleman 83/840 Nature of Eddleman request objected to W/Certificate of 6vc Related correspondence CARROW, H Carolina Power & Light Co 84/02/22 Atomic Safety and Licensing Board Panel 3pp 22404 281 24X Fiche 50-400.84/02/22. 8402280420
- 0402280425 Response to applicants sixth set of interrogatories (Joint Contentions I & VII) Relatef correspondence EOBLEMAN.W Eddleman, W 84/02/22 18pp 22403 283 24X Fiche 30-400,84/02/22.8802280425
- B402280223 Interrogatories & request for production of documents to applicant on Joint Contention 1 (first set).Related correspondence PAYNE.M T Kudiu Alliance PAYNE.M T Edelstein & Payne B4/02/23 Carolina Power & Light Co 102pp 22400 077 24X Fiche 30-400.84/02/23.8402280223
- 8402280362 Motion for reconsideration or clarification of ASLB 840127 memorandum & order on hoaith effects contentions ASLB misapplied legal std & has run afoul of several Commission rules & decisions Certificate of Suc enc 18AXTER. T A Caroline Power & Light Co BAXTER. T A Shaw, Pittman. Potts & Troubridge 84/02/24 Atomic Safety and Licensing Board Panel 30pp 22404 229 24x Fiche 50-400,84/02/24.8402280362
- 8402290097 Response supporting R Wilson 840215 motion to withdraw Contention (II re mgt qualification, Certificate of Svc encl BARTH, C A Hearing Branch i 84/02/24 Abomic Safety and Licensing Board Panel 3pp 22428 005 24X Fiche 50~400,84/02/24,8402290097
- 8402270099 Response to ASLB 840127 order ruling on motions for summary disposition of health effects contentions Joint Contention II & Eddleman Contentions 378.85(1) & 85(2) Gofman should not be called as witness W/Certificate of Svc BARTH. C.A. Hearing Branch 1 84/02/24 7ps 22428 008 24X Fiche 50-400.84/02/24,8402290099

M Antitrust correspondence

- 840222017A Forwards add1 info requested for antitrust review in connection w/OL application info prepared per Reg Guide 9.3 Response to Reg Guide 9.3 also filed on behalf of North Carolina Eastern Municipal Power Agency HCDUFFIE,M A Carolina Power & Light Co 84/02/16 TOALSTON, A L Division of Engineering 62pp 22341 224 24X Fiche 50-400,84/02/16,840222017A
- 3 Advisory Committee on Reactor Safeguards reports & correspondence
- 3402060201 Forwards ACRS 840316 ltr re review of application for OL during 283th meeting on 840112-14

 KNIQHTON, Q W Licensing Branch 3 84/01/23 UTLEY, E E Carolina Powers & Light Co 3pp 22103.186 24X Fichs 50-400, 84/01/23. 8402060201

- @ Inspection reports, IE Bulletins & correspondence
- B312120153 IE Info Notice 84-06. "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fichs 50-000.84/01/25.8312120153
- 8402140404 Ack receipt of 840113 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-400/83-33 VERRELLI.D M Division of Project & Resident Programs 84/01/30 UTLEY, E E Carplina Pauer & Light Cø ip 22221 273 24x Fiche 50-400:84/01/30,8402140404
- --B402140411 Notifies that util B40113 response (NRC-165) to NRC reviolations noted in IE Insp Rept 50-400/83-33 inadvertently omitted date from itr Ltr should be dtd 840113 PARSONS.R M Carolina Power & Light Co 84/01/17 D'REILLY.J PRegion 2. Office of Director ip 2221 294 24X Fiche 50-400.84/01/30.8402140404
- --8402140417 Responds to NRC 831214 ltr re violations noted in IE Insp Rept 50-400/83-33 Corrective actions new TP-28 exhibits issued for each penetration reviewed by const inspector supervisor prior to initiation of wark PARSONS.R r Carolina Power & Light Co 84/01/13 D'REILLY, J P Region 2. Office of Director 3pp 22221 275 24X Fiche 50-400,84/01/30,8402140404
- --8402140440 Forwards IE Insp. Repts 50-400/83-33 & 50-401/83-33 on 831020-1120 & notice of violation VERRELLI, D.M. Division of Project & Resident Programs 83/12/14 UTLEY, E.E. Carplina Power & Light Co. 2pp. 22221 298 24X Fiche 50-400,84/01/30,8402140404
- ~~8402140444 Notice of violation from insp on 831020-1120 * Region 2, Office of Director 83/12/14 ip 22221 300 24X Fiche 50-400,84/01/30.8402140404
- --8402140450 IE Imap Repts 50-400/83-33 & 30-401/83-33 on 831020-1120 Violation noted inadequate corrective action on Deficiency & Disposition Rept (DDR) 1916 re electrical penetrations MAXWELL,0 F, PREVATYE.R L. Region 2. Office of Director BEMIS.P R Division of Project & Resident Programs 83/12/13 Epp 22221 301 24X Fiche 50-400.84/01/30.8402140404
- 8402280009 Forwards IE Insp Rept 50~400/84-01 on 840110-13 No violations or deviations identified VERRELLIID M Division of Project & Resident Programs 84/02/01 UTLEY, EE Carolins Power & Light Co 2pp 22402 114 24X Fiche: 50~400,84/02/01,8402280009
- --H4UR280011 IE Insp Rept 50-400/84-01 on 840110-13 No violations or deviations identified Major areas inspected cable installation & general housekeeping HUNT.N D Region 2. Office of Pirector CONLON.T E Division of Engineering & Operational Programs 84/01/30 4pp 22402.116 24X Fiche 50-400.84/02/01.8402280009
- B401190016 IE Info Notice B4-07, "Design-Basis Threat & Review of Vehicular Excess Controls" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/03 Consolidated Edison Co. of New York, Inc. 119pp 22114 179 24X Fiche 50-000,84/02/03,840[190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers" Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co. of New York, Inc 102pp 22177-156 24X Fiche 50-000.84/02/03.8401190017.
- B4022B0125 Ack receipt of 840201 supplemental ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-400/83-29 LEWIG.R C Division of Project & Resident Programs, 84/02/09 UTLEY.E E Carolina Power & Light Co ip 22405 290 24X Fiche.50-400.84/02/09.8402280125
- ---8402280127 Responds to NRC 831110 ltr re violations noted in IE Insp Rept 50-400/63-27 Corrective actions site specs revised to allow substitution of bolts marked std practice PARSONS.R M Carolina Power & Light Co. 84/02/01 O'REILLY. J P Region 2. Office of Director 1p 22405 291 24X Fiche. 50-400, 84/02/09, 8402280125
- B402280182 Ack receipt of B31230 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/83-31 & 50-401/83-31 WERRELLI,D M Division of Project & Resident Programs. B4/02/10 UTLEY,E E Carolina Power & Light Co ip 22400,244 24X Fiche 50-400,84/02/10,8402280182

- --B4022B0187 Responds to NRC B31206 ltr re violations noted in IE Insp Repts 30-400/B3-31 & 30-401/B3-31 Corrective actions cable reals stored properly & hold tag labels specify proper storage levels PARSONB.R M Carolina Power & Light Co 83/12/30 O'REILLY, J P Region 2. Office of Director 2pp 22400 245 24X Fiche 50-400, B4/02/10, B4022B01B2
- --B402280194 Forwards IE Insp Repts 50-400/83-31 & 50-401/83-31 on 831107-10 & notice of violation VERRELLI,D M Division of Project & Resident Programs 83/12/06 UTLEY,E E Carolina Power & Light Co 2pp 22400 247 24X Fiche 50-400.84/02/10.8402280182
- ---8402280199 Notice of violation from insp on 831107-10 * Region 2. Office of Director 83/12/06 1p 22400 249 24X Fiche 50-400,84/02/10,8402280182
- --8402280204 IE Insp Repts 30-400/83-31 & 50-401/83-31 on 831107-10 Violation noted failure to follow or revise instructions specified on GA hold tags prior to performing actions RUFF. A B Region 2. Office of Director CONLON. T E Division of Engineering & Operational Programs 83/12/02 6pp 22400 250 24X Fiche 50-400.84/02/10.8402280182
- 8401170041 IE Info Notice 84-07, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R) " Syc list onc!

 JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc. 124pp 22365:259 24X Fiche 30-000,84/02/13,8401170041
- 8401190039 IE Info Notice 84-08, "10CFR30 7, 'Employee Protection '"
 Byc list encl
 JDRDAN, E. L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- B401170043 IE Info Notice B3-63, Suppl 1, "Potential Failures of Mestinghouse Type BA-1 Differential Relays " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/15 Consolidated Edison Co of New York, Inc 118pp, 22366-142 24X Fiche 50-000, B4/02/15, B401170045
- 8402280249 Confirms 840223 enforcement conference at Region II ofc to discuss GA program relative to vendor supplied matis & svcs. per 840215 telcon O'REILLY, J. F. Region 2, Office of Director 84/02/17 UTLEY, E. Carolina Power & Light Co. ip 22399 275 24X Fiche 50-400,84/02/17,8402280249
- 8402280407 Responds to request for add1 info re insp intervals on low pressure turbine rotors. New partial integral rotors purchased & undergoing evaluation. One-half critical crack depth for shrunk-on discs exceeds 50 yes MCDUFFIE.M A Carolina Power & Light Co. 84/02/20 DENTON.H R Office of Nuclear Reactor Regulation. Director 1p 22404.262 24X Fiche 50-400.84/02/20.8402280407
- 8401170062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Bet Below Manufacturer Recommended Value " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000,84/02/21,8401170062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies "
 Syc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/24 Consolidated Edison Co of New
 York, Inc. 115pp 22430-304 24X Fiche 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Boft Seat Valve Seals"
 Svc 11st encl
 JORDANA, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp. 22431 060 24% Fiche. 50-000, 84/02/27, 8401190067
- S Reportable occurrences, LERs & related correspondence
- 8402170005 Part 21 rept re fabrication of piping subassemblies having wall thickness less than required by design specs. Cause & extent of incident under review Nuclear isometric drawings will be reviewed by 831028 BARNES.R F. GOODMIN.B J. Southwest Fabricating & Welding Co. (subs of IU International Corp.) 83/10/17 POTAPOVS.U. Region 4. Office of Director. 3pp. 22301 134 24X Fiche 50-400.83/10/17.8402170005

- B402170279 Part 21 rept re fabrication of piping subassemblies w/wall thickness less than required design specs No addit deviations found incident considered closed BORNES.R P. ODODMIN.B J. Southwest Fabricating & Welding Co. (subset IV International Corp.) B3/10/25 POTAPOVS.U Region 4. Office of Director 2pp. 22296 086 24% Fiche 50-400.83/10/25.8402170279
- 8402080192 Third interim deficiency rept. Item 103 re main control board weld defects Initially reported on 830310 Deficient welding repaired & inspected by vendor on site Next rept will be submitted by 840430 PAR9IONS.R M Carolina Power & Light Co 84/01/30 O'REILLY, J P Region 2. Office of Director 4pp 22129 205 24% Fiche 50-400.84/01/30.8402080192
- 8402140413 Final deficiency reptiltem 122 re Class IE 480-volt motor control ctr protective grommets supplied by Gould, Inc Initially reported on 830425 Corrective action completed Also reported per Part 21 PARSONS: R M Carolina Power & Light Co B4/01/31 O'REILLY, J P Region 2. Office of Director 4pp 22230 332 24X Fiche 50-400,64/01/31.8402140413
- 8402070393 Requests that NRC investigate design reliability of emergancy diesel generators supplied by Transamerica Delawal. Inc Engine problems have been experienced since delivery of first vessel in May 1981 Related info encl MOLINA.J C Falcon Carriers, Inc 84/02/01 DENTON.H R Office of Nuclear Reactor Regulation, Director 63pp 22096 057 24X Fiche 50-000.84/02/01.8402070393
- 8402150388 Deficiency rept, Item 140 re hanger sketch incorrectly identifying field welds as shop welds Initially reported on 840206 Item evaluated & determined not reportable per 10CFR50 55(e)
 CHIANGI.N J Carolina Power & Light Co 84/02/07 O'REILLY, J P Region 2, Office of Director 1p 22242 001 24X
 Fiche 50-400.84/02/07.8402150388
- 8401190053 Board Notification 84-020 forwards info re Transamerica Belaval.Inc emergency diesel generator problems Attendance list.meeting handouts & slides encl EISENHUT.D 0 Division of Licensing 84/02/13 PALLADIND Commissioners 102pp 22332 202 24X Fiche 50-000,84/02/13, 8401170053
- 8402220330 Part 21 rept re defective DSR & DSRV standby diesel generator turbocharger thrust bearing lubrication Deficiency not corrected by sys mod New recommendation will be sent to customers by 840330
 BOYER: R E Transamerica Delaval, Inc 84/02/15 Director's Office, Office of Inspection and Enforcement 5pp 22332 182 24X Fiche 50-000,84/02/15,8402220330
- 8402270131 Final deficiency & Part 21 repts. Item 134 re defective engine mounted electrical cables on emergency diesel generators supplied by Transamerica DeLaval Intitially reported on 831114 Cable replacement completed 840124 PARSONS: R M Carolina Power & Light Co. 84/02/17 O'REILLY, J P Region 2. Office of Director App 22391 294 24X Fiche 50-400.84/02/17,8402270131
- B4022B0701 Notification of 840308 meeting w/Transamerica Delayal, Inc (TDI) Dumers Onoup in Wading River, NY to discuss TDI proposed program plan to qualify diesel generators CARUBO, R Division of Licensing 84/02/23 BERLINGER, C Division of Licensing 2pp 22414 340 24X Fiche 50-000, 84/02/23, 84022B0701
- T Hearing transcripts on non-antitrust matters
- B402210240 Transcript of 840216 telephone conference in Bethesda, MD Pp 734-750
 * Commissioners 84/02/16 17pp 22314 333 24X
 Fiche 50-400, B4/02/16, 8402210240
- DOCKET 50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App As & C documents FELTON, J M. Division of Rules and Records 83/10/3; ROBENDADUM, D M Technical Analysis Corp 19pp 22193 292 24X Fiche 50-000,83/10/31,8402090003
- --8402090162 Handwritten notes & calculations re const activities * NRC - No Detailed Affiliation Given B3/02/17 10pp 22194,354 24% Fiche 50-000,83/10/31,8402090003

- B402170061 Notification of B40210 meeting w/Transamerica Delaval.Inc (TDI) in Bethesda.MD to discuss program plan proposed by TDI Comers Group to qualify diesel generators CARUSO.R Division of Licensing B4/02/06 BERLINGER.C Division of Licensing 2pp \$2312 339 24X Fiche 50-000.84/02/06.
- B402150293 forwards distribution list denoting correct number of documents listed individual supposed to receive ROMLEY.L W North Carolina, State of 84/02/07 KNIGHTON,G W Licensing Branch 3 4pp 22250 084 24X Fiche 50-400,84/02/07, 8402150293
- F Security, medical, emergency & fire protection plans
- 8402140404 Ack receipt of 840113 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-400/83-33 VERRELLI.D M Division of Project & Resident Programs 84/01/30 UTLEY.E E Carolina Power & Light Co 1p 22221 273 24X Fiche 50-400,84/01/30,8402140404
- --8402140450 IE Insp Repts 50-400/83-33 & 50-401/83-33 on 831020-1120 Violation noted inadequate corrective action on Deficiency & Disposition Rept (DDR) 1916 re electrical penetrations MAXMELL.G F. Region 2. Office of Director 83/12/13 8pp 22221 301 24X Fiche 50-400,84/01/30.8402140404
- G Adjudicatory correspondence
- 8402010191 Forwards summary of ACRS 285th meeting on B40112-14 re DL application & W Eddleman 840113 ltr re compromised plant safety NRC response to ACRS will be forwarded to ASLB & parties
 BARTING A Hearing Branch 1 84/01/20 KELLEY, J L .
 CARPENTER, J H , BRIGHT, G D Atomic Safety and Licensing Board Panel 9pp 22039 348 24% Fiche 50-400.84/01/20.8402010191
- 8402010223 Response to Intervenor W Eddleman 840103 request for order to require early filing of NRC responses to motions for summary disposition Request should be denied Certificate of Svc encl MOORS. J E Hearing Branch 1 84/01/20 Atomic Befety and Licensing Board Panel 6pp 22039 337 24X Fiche 50-400.84/01/20.840210223
- Licensing soard Panel Opp 22039 357 24% Fiche 50-400/64701/20 8402010223 402010190 Researce supporting Applicant 840103 motion to resume
- 8402010170 Response supporting applicant 840103 motion to resume discovery on Joint Intervenors Contentions I & VII Discovery need not await resumption of environ hearings Certificate of Svc encl BARTH, C A Hearing Branch i B4/01/23 Atomic Safety and Licensing Board Panel App 22038 353 24X Fiche 50-400,84/01/23,8402010170
- 8402010193 Response opposing Eddleman 840103 proffered Contentions 169, 170, 171 & 172 re safety panameter display sys Contentions do not comply w/requirements Certificate of 8vc encl MORE. J E Hearing Branch 1 84/01/30 Atomic Sefety and Licensing Board Panel 14pp 22038 337 24X Fiche 50-400,84/01/30, 8402010193
- 8402020227 Interrogatories & request for production of documents (fifth set) BAUSER,D B Carolina Power & Light Co BAUSER,D B Shaw, Pittman, Potts & Trombridge 84/01/30 Wilson, R Bpp 22037 054 24X Fiche 50-400.84/01/30.8402020227
- --8402020230 Interrogatories & request for production of documents (sixth set) Certificate of Bvc encl
 BAUSER,D B Carolina Power & Light Co BAUSER,D.B Shaw,
 Pittman, Potts & Trowbridge 84/01/30 Joint Intervenors -Shearon Harris 16pp 22057 062 24X Fiche 50-400,84/01/30,
 B402020227
- 8402030306 Response to applicant motion for protective order ASLB should not enter proposed protective order but support approve Eddleman listed voluntary commitments EDDLEMAN.W Eddleman.W 84/01/30 Atomic Safety and Licensing Board Panel. 10pp 22069 082. 24% Fichs 50-400.84/01/30, B402030306
- --8402030320 General interrogatories & interrogatories on Contention 65 to applicants, et al (seventh set) EDDLEMAN, W Eddleman, W 84/01/30 Carolina Power & Light Co 26pp 22069 076 24X Fiche 50-400, 84/01/30, 8402030306

- 8402030175 Advises that draft affsite emergency response plans should be available by mid-Feb 1984 Util filing for further info on Contentions 151 b 157 also expected by mid-Feb 1984 RIDGMAY, D A Shaw, Pittman, Potts & Trowbridge RIDGMAY, D A Carolina Power & Light Co RIDGMAY, D A North Carolina Municipal Power Agencies 84/01/31 KELLEY, U L. CARPENTER, J H., BRIGHT, & D Atomic Safety and Licensing Board Panel 4pp 22048 125 24X Fiche 50-400,84/01/31.8402030175
- B402060213 Forwards ltr of agreement between util & Hammer, Vaughn & Johnson re onsite treatment of injured personnel.per ASLO B31101 memorandum & order on Eddlemen Contention 151 Svc list encl RIDGHAY, D A Shaw, Pittman, Potts & Trowbridge RIDGHAY, D A Carolina Power & Light Co RIDGHAY, D A North Carolina Municipal Power Agencies 84/02/01 KELLEY, J L , CARPENTER, J H , BRIGHT, Q. O Atomic Safety and Licensing Board Panel Spp 22087 152 24X Fiche 50-400,84/02/01,8402060213
- B402070031 Response supporting applicant 8401t3 motion for protective order re Eddleman Contention 41 Certificate of 8vc encl BARTH, C.A. Hearing Branch 1 84/02/02 Atomic Safety and Licensing Board Panel App. 22102 347 24X Fiche, 50-400, 84/02/02, 8402070031
- 8402090057 Answer to W Eddleman motion for further deferral of parts of Contention 107 & Eddleman new contentions & amended deferred contentions in response to NRC SER ASLB should deny motion & reject new SER contentions Certificate of Svc encl HAXTER: TA Carolina Power & Light Co BAXTER: TA Shaw, Pittman, Potts & Trowbridge 84/02/06 Atomic Safety and Licensing Board Panel 69pp 22139 234 24X Fiche 30-400.84/02/06.8402090067
- 8402130233 Motion for summary disposition of Eddelman Contention B3/848 No genuine issue of matl fact exists & util entitled to favorable decision CARROW.H Carolina Power & Light Co CARROW.H North Carolina Municipal Power Agencies 84/02/07 Atomic Safety and Licensing Board Panel 11pp 22204 177 24X Fiche 50-400.84/02/07, 8402130233
- ---8402130238 Statement of matl facts as to which there is no genuine issue CARROW. H Carolina Power & Light Co CARROW. H North Carolina Municipal Power Agencies 84/02/07 Atomic Safety and Licensing Board Panel 50pp 22204
- --8402130R46 Affidavit of NT Hogarth in support of summary disposition of Eddelman Contention 83/848 Applicants have adequately addressed health effects of chlorinated discharges from plant. Certificate of Svc encl HOGARTH.N T Carolina Fower & Light Ca 84/02/06 35pp 22204 244 24X Fiche 50-400.84/02/07.840R130233
- B40213D266 Forwards proposed schedule for adjudicating security plan contentions Schadule agreed upon by parties in 840203 meeting Svc list encl
 CARRON-H Carolina Power & Light Co 84/02/08. KELLEY, J. L.,
 BRIGHT, G. D., CARPENTER, J. H. Atomic Safety and Licensing Board Panel
 3pp 22204 066 24% Fiche 30-400.84/02/08.8402130266.
- 8402150217 Comments on Board tentative schedule for evidentiary hearing on environ issues & for prehearing conference Schedule of 840605 presents difficulties as schedule relates to Joint Contention II(a) W/Certificate of Svc BAXTER, T A Carolina Power & Light Co BAXTER, T A North Carolina Municipal Power Agencies BAXTER, T A Shaw, Pittman, Potts & Trowbridge 84/02/10 6pp 22244 143 24X Fiche 50-400,84/02/10,8402150219
- 8403220295 Response in support of applicant 840118 motion for summary disposition of W Eddleman Contention 65 No matl facts in dispute before ASLB Motion should be granted Certificate of Svc encl. Related correspondence BARTH, C A Hearing Branch 1 84/02/13 15pp 22336 116 24X Fiche 50-400,84/02/13,8402220275
- 8402160201 Answer to W Eddleman 840130 motion for extension of time to respond to summary disposition on Eddleman Contention 65 until second round of discovery completed Motion should be denied & W Eddleman directed to file answers by 840228 BAXTER, T A Caroline Power & Light Co BAXTER, T A Shaw, Pittman, Potts & Troubridge 84/02/14 Atomic Safety and Licensing Board Panel 15pp 28275 277 24X Fichs 50-400,84/02/14,8402140801.
- --8402160207 Motion for extension of time to respond to Eddlemen discovery requests on Contention 65, unless & until ABLB serves order granting M Eddleman motion for extension to respond to summary disposition W/Certificate of BVC.
 BAXTER:TA Carolina Power & Light Co BAXTER:TA. Bhaw, Pittman. Potts & Troubridge 84/02/14 Atomic Bafety and Licensing Board Panel 6pp 22275 292 24X Fiche 50-400, 84/02/14,8402160201.

- 8402160233 Response opposing W Eddleman 840128 motion for ASLB order requiring svc of applicant rept to NRC re safety circuit breakers Certificate of Svc encl

 O'NEILL, J H Carolina Power & Light Co
 Pittman, Potts & Trowbridge 84/02/14 Atomic Safety and
 Licensing Board Panel App 22276 330 24X Fiche 50~400,84/02/14,8402160233
- 8402170103 Certification to applicant B40118 motion for summary disposition of Eddleman Contention 65 Motion identifies one instance of honeycombing or voids in containment base mat. sxterior walls & dome Certificate of Svc encl
 BAXTER, T A Carolina Power & Light Co BAXTER, T A Shew, Pittman, Potts & Troubridge 84/02/15 Atomic Bafety and Licensing Board Panel 6pp 22301 088 24X Fiche 50~400,84/02/15,8402170103
- 8402210115 Motion to withdraw Contention III re mgt capability Certificate of Svc encl WILSON,R Wilson, R B4/02/15 Commissioners 2pp 22317 161 24X Fiche 50-400.84/02/15,8402210115
- B402220234 Response opposing W Eddleman B40217 motion for further deferral of parts of Contention 107 & motion for denial of admission of said parts of Contention 107 re deficient SER Cartificate of Svc encl
 BARTH.C.A Hearing Branch 1 84/02/16 Atomic Bafety and Licensing Board Panel 7pp 22340.223 24X Fiche 50-400.84/02/16.8402220234
- 8402220235 Response to W Eddleman 840117 new contentions re NRC SER Eddleman proposed Contentions 107-X.Y & Z & proposed Contentions 170-177, 180 & 181 should be rejected Staff has no objection to Contentions 178 & 177 W/Certificate of Svc MOORE, J E Hearing Branch 1 64/02/16 Atomic Bafety and Licensing Beard Panel 17pp. 22340:178 24X Fiche 50-400,84/02/16,8402220235.
- 8402220267 Forwards "Summary of Design Stds & Criteria for Technical Support Ctr Encompassing Human Factors Engineering," per Eddleman proposed Contention 157 Contention should be rejected Related correspondence HOLLAR.D. E Carolina Power & Light Co 84/02/17 KELLEY.J L , BRIGHT, G. D. CARPENTER.J H Atomic Safety and Licensing Board Panel 2pp 22335-200. 24X Fiche-50-400.84/02/17,8402220267,
- --8402220269 "Bummary of Design Btds & Criteria for Technical Support Ctr Encompassing Human Factors Engineering " * Carolina Power & Light Co 84/02/14 ilpp 22335 202 24X Fichs 50-400,84/02/17,8402220267
- 8402270056 Response to Eddleman 840127 further interragatories re Contention 65 Affidavit of PR Bemis encl Related correspondence. BARTH, C.A. Heering Branch 1 84/02/21 Eddleman, W 7pp 22388 161 24X Fiche. 50-400, 84/02/21, 8402270056
- --8402270060 Response opposing W Eddlemen motion to require svc of applicant rept to NRC re safety circuit breakers Motion is moot & applicant will serve Chapsi Hill Anti-Nuclear Group Effort Related correspondence BARTH, C. A Hearing Branch 1 84/02/21, Atomic Safety and Licensing Board Panel 2pp. 22388 168, 24X Fiche 50-400, 84/02/21, 8402270056,
- --8402270065 Response opposing W Eddleman 840128 motion to require svc of staff summary disposition responses on expedited scheduls. Certificate of Svc encl Related correspondence BARTH.C A. Hearing Branch i 84/02/21 Atomic 8afety and Licensing Board Panel 2pp. 22388 170, 24% Fiche: 50~400, 84/02/21,8402270056
- B4022B0323 Response to applicant motion for reconsideration of Security Contention 4 Encl withheld (ref 10CFR73 R1) Certificate of Svc encl.
 RVMKLE, J Joint Intervenors Shearon Harris 84/02/22 Atomic Bafety and Licensing Board Panel 3pp 22399'122 24X Fiche.50-400,84/02/22,8402280323
- 8402280420 Response to Eddleman 840208 request for expedited ruling on timeliness of applicants 840207 motion for summary disposition of Eddleman 83/848 Nature of Eddleman request objected to WCertificate of 8vc. Related correspondence. GARROW, H Carolina Power & Light Co. 84/02/22 Atomic Sefety and Licensing Board Panel 5pp 22404.281. 24% Fiche.50-400.84/02/22, 8402280420.
- B402280362 Motion for reconsideration or clarification of ASLB 840127 memorandum & order on health effects contentions. ASLB misapplied legal std & has run afoul of several Commission rules & decisions. Certificate of Svc encl.
 BAXTER, T.A. Carolina Power & Light Go BAXTER, T.A. Shaw, Pittman, Potts & Trowbridgs. 84/02/24 Atomic Bafety and Licensing Board Panel. 30pp. 22404:229 24X Fiche: 50-400,84/02/24,8402280362

- 8402290097 Response supporting R Wilson 840215 motion to withdraw Contention III re mgt qualification Certificate of Syc encl BARTH.C A Hearing Branch i 84/02/24 Atomic Safety and Licensing Board Panel 3pp 22428 005 24X Fiche 50-400.84/02/24.8402290097
- 8402290099 Response to ASLB 840127 order ruling on motions for summary disposition of health effects contentions Joint Contention II & Eddleman Contentions 370.8F(1) & 8F(2) Gofman should not be called as witness M/Certificate of Svc BARTH.C A Hearing Branch i 84/02/24 7pp 22428 008 24X Fiche 50-400.84/02/24.8402290099
- Q Inspection reports: IE Bulletins & correspondence
- 8402140404 Ack receipt of 840113 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-400/83-33 VERRELLI,D M Division of Project & Resident Programs 84/01/30 UTLEY,E E Carolina Power & Light Co
- --8402140440 Forwards IE Insp Repts 30-400/83-33 & 50-401/83-33 on B31020-1120 & notice of violation VERRELLI,D M Division of Project & Resident Programs 83/12/14 UTLEY,E E Carolina Power & Light Co 2pp 22221 298 24X Fiche 30-400,84/01/30,8402140404
- --B402140450 IE Insp Repts 50-400/83-33 & 50-401/83-33 on B31020-1120 Violation noted inadequate corrective action on Deficiency & Disposition Rept (DDR) 1916 re electrical penetrations MAXMELL, G F , PREVATTE, R L Region R, Office of Director BEMIS.P R Division of Project & Resident Programs 83/12/13 Bpp 22221 301 24X Fiche 50-400.84/01/30.8402140404
- 8402280182 Ack receipt of 831230 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/83-31 & 50-401/83-31 VERRELLI, D M Division of Project & Resident Programs 84/02/10 UTLEY, E E Carolina Power & Light Co ip 22400 244 24% Fiche 50-400.84/02/10.8402280182
- --8402280189 Responds to NRC 831206 ltr re violations noted in IE Insp Repts 50-400/83-31 & 50-401/83-31 Corrective actions cable raels stored properly & hold tag labels specify proper storage levels PARSONS.R M Carolina Power & Light Co 83/12/30 O'REILLY, J P Region 2, Office of Director 2pp 22400 245 24X Fiche 50-400, 84/02/10,8402280182
- --8402280194 Forwards IE Insp Repts 50-400/83-31 & 50-401/83-31 on B31107-10 & notice of violation VERRELLI,D M Division of Project & Resident Programs 83/12/96 UTLEY,E E Carolina Power & Light Co 2pp 22400 247 24X Fiche 50-400,84/02/10.8402280182
- --8402280199 Notice of violation from insp on 831107-10

 * Region 2, Office of Director 83/12/06 lp 22400 249 24X
 Fichs 50-400,84/02/10.8408280182.
- --8402280204 IE Insp Repts 50-400/83-31 & 50-401/83-31 on 831107-10 Violation noted failure to follow or revise instructions specified on QA hold tags prior to performing actions RUFF, A B Region 2, Office of Director CDNLON, T E Division of Engineering & Operational Programs 83/12/02 6pp 22400 250 24X Fichs 50-400,84/02/10,8402280182
- 8 Reportable occurrences, LERs & related correspondence
- 8402070393 Requests that NRC investigate design reliability of emergency diesel generators supplied by Transamerica Dalaval Inc Engine problems have been experienced since delivery of first vessel in May 1981 Related info encl MDLINA, J C Falcon Carriers, Inc 84/02/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 63pp 22096 057, 24X Fiche 80-000,84/02/01,8402070393
- 8401190033 Board Notification 84-020 forwards info re Trensamerica Delaval, Inc emergency diesel generator problems Attendance list westing handouts & slides enci EISENHUT, D. G. Division of Licensing 84/02/13 PALLADINO Commissioners 102pp 22332 202 24X Fiche 50-000,84/02/13, 8401190053
- 8402220330 Part 21 rept re defective DSR & DBRV standby diesel generator turbocharger thrust bearing lubrication Deficiency not corrected by sys mod New recommendation will be sent to customers by 840330 BOYER.R.E Transamerica Delaval, Inc 84/02/15, Director's Office, Office of Inspection and Enforcement 5pp 22332 182 24X Fiche 50-000.84/02/15,8402220530

402280701 Notification of 840308 meeting w/Transamerica Delaval.Inc (TDI) Owners Croup in Wading River.NY to discuss TDI proposed program plan to qualify diesel generators CARUSO.R Division of Licensing 84/02/23 BERLINGER.C Division of Licensing 2pp 22414 340 24X Fiche 50-000.84/02/23.

Hearing transcripts on non-antitrust matters

- 402210240 Transcript of 840214 telephone conference in Bethesda.MD Pp 734-750 = Commissioners 84/02/14 17pp 22314 333 24X Fiche 50-400.84/02/14.8402210240

OCKET 50-407 UNIV OF UTAH RESEARCH REACTOR

Periodic operating reports & related correspondence

- 402220477 "Univ of Utah TRIGA Reactor Annual Operating Rept, Jul 1982 June 1983 " W/830901 ltr CRAMFORD.K. JACOOS, H R Utah, Univ of, Balt Lake City, UT 83/06/30 SEIDLE.W C Region 4, Office of Director App 22340 133 24x Fithe 50-407,83/06/30,8402220479

DCKET 50-409 LA CROSSE BOILING WATER REACTOR

Security, medical, emergency & fire protection plans

- 402050332 Further response to FOIA request for documents re security violations & safeguards events at nuclear facilities Forwards AGBWR insp rept on firearms qualification falsification info partially deleted (ref FOIA Exemption 7) FELTON.J M Division of Rules and Records 83/11/08 GDLDENBERG, G Scripps-Howard Newspapers ip 22110:310 24X Fiche 50-409.83/11/08.8402060332
- -B402060342 Forwards IE Investigation Rept 50-409/77-07 on 770425-27 & 0502, suggesting possible violation arising from mat) misrepresentations by Wisconsin Security Bureau re training of contract security guards MCTIERNAN T J Office of Inspector & Auditor 77/09/07 CIVILETTI, B R Justice, Dept of. 3pp 22110 313 24X Fiche 50-409,63/11/06,8402060332
- -8402040348 IE Investigation Rept 50-409/77-07 on 770425-27 & 0502.

 Noncompliance noted security guard qualification records falsified by guard ave contractor by backdating Infopartially deleted FOSTER, J E , MADEDA, T J , HIND, J A Region 3, Chicago, Office of the Director 77/05/31 40pg 22:10 314 24x

 Fiche 50-409.63/11/08.8402060332

- 02040429 forwards "LACBUR Detailed Control Room Design Review Final Rept." as required by Generic Ltr 62-33 re emergency response capability & committed to in B20408, 830408 & 1205 ltrs in response to NUREG-0737.Action Item I D.1
 LINDER.F Dairyland Power Cooperative 84/01/26 EISENHUT, D 0 Division of Licensing. 1p. 22083 165 24X Fiche 50-409,84/01/26,8402060429
- B402040432 "LACBUR Detailed Control Room Design Review Final Rept "GODDMAN.L S Dairyland Power Cooperative. LAC-TR-123 84/01/31 60pp 22085.166 24% Fichs 50-409,84/01/26.8402040429.
- 02170078 Issue 5 to Emergency Plan Implementing Procedure EPP-5, "Estimate of Offsite Dose" W/B40210 ltr LINDER: F Dairyland Power Cooperative. B4/01/27 CRUTCHFIELD, D Operating Reactors Branch 5 Spp. 22301:074 24X Fiche: 50-407.84/01/27,8402170078
- 02070010 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless requested, per 810709 Generic Ltr 81-27 Unless stipulated, entire plan will be placed in PDR CRUTCHFIELD. Deprating Reactors Branch 5. 84/02/02 LINDER, F Dairyland Power Cooperative 2pp. 22102 320 24X Fiche 50-409,84/02/02,8402070010
- 02150172 Forwards response to request for add1 info on 820928, 830223 & 1114 ltrs re rewrite & clarification of Section 8 of fire protection rule
 LINDER, F. Dairyland Power Cooperative. 84/02/06. CRUTCHFIELD, D
 Operating Reactors Branch 5 4pp. 22245; 214. 24X
 Fiche 50-409, 84/02/06, 8402150172
- 8402150177 "Rept of 1 H Fire Endurance Testing of Pyrotenax Mineral Insulated Power Cable " * Affiliation Not Assigned, BO/12/17, 12pp 22245-218, 24X Fiche:30-409,84/02/06,8402180172

- 8402210169 Submits new results, methodology & assumptions of study of airborne dose to control room occupants during postulated max credible accident, in response to Generic Ltr 82-33, Suppl 1 to NUREG-0737 & Post-TMI Item III D 3 4
 LINDER; F Dairyland Power Cooperative 84/02/09 EISENHUT, D 6
 Division of Licensing 5pp 22316 330 24X Fiche 50-409,84/02/09,8402210169
- B402170244 Ack receipt of B40120 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-409/83-20 Further discussions of swergency preparedness exercise Weaknesses 1,2,3,6 & 10 provided in enc! PAPERIELLO,C J Region J. Office of Director B4/02/14 LINDER,F W Dairyland Power Cooperative App 22297 O01 24x Fiche 50-409.84/02/14,8402170244
- --B402170231 Responds to NRC B31213 ltr re violations noted in IE Insp Rept 50-409/83-20 Corrective actions NAMAS sys telephone lines repaired & Procedure EPP-2 will be modified to specifically address emergency class LINDER. F. Dairyland Power Cooperative B4/01/20 PAPERIELLO, C J Region 3, Office of Director Epp 28297 005 24X Fiche 30-409,84/02/14,8402170244
- 8402230109 Advises that Natl Weather Svc be contacted from technical support ctr & emergency operations facility, per Generic Ltr 82-33 (Suppl 1 to NUREG-0737) re requirements for emergency response capability
 LINDER.F Dairyland Power Cooperative 84/02/16 EISENHUT, D Q Division of Licensing 1p 22361 205 24X Fiche 50-409,84/02/16,8809270109
- 8402230204 Forwards FR notice of issuance of order confirming licensee commitments on emergency response capability schedules, per Generic Ltr 82-33 Order based on 830408,0811 & 1205 ltrs CRUTCHFIELD. O Operating Reactors Branch 5 84/02/22 LINDER,F Dairyland Power Cooperative App 22361 045, 24X Fiche, 50-409,84/02/22,8402230204
- --8402230214 Notice of issuance of order confirming licensee commitments on emergency response capability.per Suppl 1 to NUREQ-0737 & Generic Ltr 82-33 ETEENBUT.D 0 Division of Licensing 84/02/22 6pp 22361.049. 24X Fiche 50-409.84/02/22.8402230204
- 8402280251 Confirms 840221 telcon re audit of detailed control room design review per Suppl 1 to NUREO-0737 Audit scheduled for 840305-07 CRUTCHFIELD, D Operating Reactors Branch 5 84/02/24 LINDER, F. Dairyland Power Cooperative 2pp. 22399 315 24X Fichs 50-409,84/02/24,8402280251
- J. Insurance & indemnity information
- 8402020207 Forwards Endorsements 52 & 53 to NELIA Policy NF-217 DEVINE: H F Dairyland Power Cooperative. 84/01/27. DINITA: I Office of Nuclear Reactor Regulation. Director 3pp 22057 1: 24X Fiche 50-407, 84/01/27, 8402020207.
- P. Operating license stage documents & correspondence
- 8312120027 Generic Ltr 83-39 to representatives of utils re voluntary survey of licensed operators, 8vc list encl.
 EIBENHUT, D G. Division of Licensing 83/12/08 Commonwealth Edison Co. 12pp 22313 004. 24X Fiche: 50-000, 83/12/08. 8312120029
- 8402020289 Application for amend to License DPR-45 addressing items identified in NUREG-0737, in response to 831101 ltr to all BWRs LINDER, F Dairyland Power Cooperative 84/01/30 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 22055 163 24X Fiche: 50-409, 84/01/30, 8402020289,
- ---8402020295 Proposed Tech Specs addressing items identified in NUREO-0737. * Dairyland Power Cooperative. 84/01/30 3pp. 22055:166 24% Fichs 50-409,84/01/30,8402020289
- 8402030330 Discusses three SEP issues to be covered through consequence study as part of integrated plant safety assessment (NUREO-OB27). Issues are saismic design considerations, tornado missiles & wind & tornado loadings.
 LINDER.F Dairyland Power Cooperative, 84/01/30, CRUTCHFIELD.D Operating Reactors Branch 5, 2pp 22069, 345, 24X Fiche: 50-409, 84/01/30, 8402030330

- 8402080363 Informs that containment isolation operable valve test demonstrated operability of both vent header valves External vent header valve will be returned to open position upon NRC concurrence on valve operability per TMI tem II E 4 2 LIMDER, F Dairyland Power Cooperative 84/02/01 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 22131 132 24X Fiche 50-409,84/02/01.8402080363
- B402070203 Forwards SER concluding that requirements of TMI Action Items II K 3 30 & II K 3 31 on small break LOCA analysis met CRUTCHFIELD.D Operating Reactors Branch 5 84/02/02 LINDER, I
- met CRUTCHFIELD.D Operating Reactors Branch 5 84/02/02 LINDER,F Dairyland Power Cooperative 4pp 22102 207 24X Fiche 50-407,84/02/02,8402070203
- B402160290 Forwards "Reactor Containment Bldg Integrated Leak Rate Test for LACBWR," Nov 1983 LINDER, F Dairyland Power Cooperative B4/02/07 CRUTCHFIELD, D Operating Reactors Branch 5 ip 22274 240 24X Fiche 50-409,84/02/07,8402160290
- --8402160275 "Reactor Containment Bldg Integrated Leak Rate Test for LACBUR: "Nov 1983 GOODMAN, L. 8 Dairyland Power Cooperative LAC-TR-124 83/11/30 61pp 22274 Z41 24X Fiche 50-409, 84/02/07, 8402160290
- B402220236 Discusses containment bldg floor response spectra, per SEP Topic III 6 Input time history accelerations used by EG&O adaquately envelope site spectra in X & Z directions Acceleration in Y direction deviates from NRC criteria LINBER, F Dairyland Power Cooperative 84/02/08 CRUTCHFIELD, D Derating Reactors Branch 5 2pp 22339:119 24X Fichs 50-409,84/02/08,8402220236
- B4022204Bi Submits info on oil storage room, in response to NRC 83i229 ltr & BEP Topic IX-5, "Ventilation Bys " Room built & equipped per NFPA stds for explosive atmospheres LINDER, F Dairyland Power Cooperative 84/02/09 CRUTCHFIELD, D Operating Reactors Branch 5 ip 22340 092 24X Fichs 50-407,84/02/09,84022204Bi
- 8402220093 Informs that offsite dose calculation manual will be resubmitted by 840330.per 840119 commitment LINDER.F. Dairyland Power Cooperative. 84/02/15 CRUTCHFIELD.D Operating Reactors Branch 5 ip 22337 247. 24X Fiche.50-409.84/02/15.8402220093
- 8402220379 Summary of 840216 meeting w/util & INEL in Bethesda, MD re environ qualification of electrical equipment Licensee committed to provide written submittal by 840402 DUDLEY, R. Operating Reactors Branch 5 84702/21 Operating Reactors Branch 5, Spp. 22334-309 24X Ficha. 50-409, 84702/21, BAD020379
- Q. Inspection reports, 1E Bulletins & correspondence
- 8402040332 Further response to FOIA request for documents re security violations & safeguards events at nuclear facilities Forwards LACBUR insp rept on firearms qualification falsification Info partially deleted (ref FOIA Exemption 7) FELTON, J. M. Division of Rules and Records 83/11/08 QULDENBERG, Q. BCripps-Howard Newspapers 1p. 22110-310 24X Fiche: 50-409, 83/11/08. 8402040332
- ---B402060342 Forwards IE Investigation Rept 50-409/77-07 on 770425-27 & OSO2, suggesting possible violation arising from mat1 misrepresentations by Misconsin Becurity Bureau re training of contract security guards.

 MCTIERNAN.T J Office of Inspector & Auditor 77/09/07 CIVILETTI.B.R. Justice, Dept of. Spp 22110,313 24X Fichs 50-409, 83/11/08,8402060332
- --B40206034B IE Investigation Rept 50-409/77-07 on 770425-27 & 0502 Noncompliance noted security guard qualification records falsified by guard svc contractor by backdating. Info partially delated FOBTER, J.E., MADEDA, T. J., HIND, J.A. Region 3, Chicago, Office of the Director 77/05/31 43pp 22110:316 24X Fiche: 80-409,83/11/08,8402060332
- B312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Fumps." Svc list encl JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/25 Consolidated Edison Co of New York, Inc. 120pp. 22058:001. 24X Fiche 50-000.84/01/25.8312120153
- B402130263 Forwards IE Insp Rept 50-407/83-22 on 831118-840118 & notice of violation SHAFER; W D. Region 3, Office of Director 84/01/25 LINDER, F W. Dairyland Power Cooperative. 2pp. 22204 054 24X Fiche: 50-409, 84/01/25, 8402130263

- --8402130267 Notice of violation from insp on 831118-840118 SHAFER.W D Region 3. Office of Director 84/01/25 1 22204 056 24X Fiche 50-409,84/01/25,8402130263
- --B402130273 IE Insp Rept 50-409/B3-22 on B3iii8-B40ii8 Nuncompliance noted failure to calibr static trip device test set or stop watches
 CLARDY,L S , HARTMANN,P L , JORDAN,M J Region 3, Office of Director B4/01/25 9pp 22204 057 24X Fiche 50-409,84/01/25,8402130263
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls" Bvc list encl JORDAN, E. L. Division of Emergency Prepareforess & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletín 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEYDUNG, RC Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 156 24X Fiche 50-000,84/02/03,8401190017
- 8402170076 Forwards response to IE Bulletin 83-08. "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Two breakers utilizing undervoltage feature identified LINDER, F Dairyland Power Cooperative 84/02/09 KEPPLER, J G Region 3, Office of Director 3pp 22300 009 24X Fichs 50-409,84/02/09.8402170076
- 8401170041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R) " Syc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259 24X Fiche 50-000,84/02/13,8401170041
- B401190037 IE Info Notice 84-08, "IOCFR50 7, 'Employee Protection '"
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/02/14 Consolidated Edison Co of New
 York, Inc. 115pp 22365 141 24X Fiche 50-000.84/02/14,8401190039
- 8402170244 Ack receipt of 840120 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-409/83-20, Further discussions of emergency preparedness exercise Weaknesses 1,2,5,6 & 10 provided in encl PAPERIELLO.C J. Region 3, Office of Director 84/02/14 LINDER, F. W. Dairyland Pawer Cooperative 4pp 22297 001 24X Fiche 50-409,84/02/14,8402170244
- --8402170231 Responds to NRC 831213 ltr re violations noted in IE Insp Rept DO-409/83-20 Corrective actions NAHAS sys telephone lines repaired & Procedure EPP-2 will be modified to specifically address emergency class LINDER, F Dairyland Power Cooperative 84/01/20 PAPERIELLO, C J Region 3, Office of Director Spp 22297 003 24X Fichs 50-409,84/02/14,8402170244
- B401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Hestinghouse Type SA-1 Differential Relays" Bvc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366 142 24X Fiche 50-000,84/02/15,8401190045
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Syc list enc! JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/21 Consolidated Edison Co. of New York, Inc. 116pp 22366 024 24X Fiche, 50-000, 84/02/21, 8401190062
- 8401190066 IE Info Notice B4-11, "Training Program Deficiencies"

 Byc list encl
 JURDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B4/02/24. Consolidated Edison Co of New
 York, Inc 115pp. 22430-304 24X Fiche 50-000:84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
 Svc list encl
 JORDAN:E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060, 24X Fiche 50-000,84/02/27,8401190067

- S Reportable occurrences, LERs & related correspondence
- B402070219 Special Rept 83-02 on 830707.16 & 0827.reactor thermal power changed by more than 15% of rated thermal power within 1 h Bampling & analysis for I-131.133 & 135 following incidents listed LINDER.F Dairyland Power Cooperative 83/10/05 KEPPLER.J G Region 3. Office of Director 7pp 22101 049 24% Fishe 50-407.83/10/05.8402070219
- 8402220154 Responds to FOIA request that 146 LERs be placed in PDR Forwards LERs listed on app Documents also available in PDR Remaining LERs were either canceled or not issued FELTON.J M Division of Rules and Records 83/11/30 JEFFERSON.O A Affiliation Not Assigned 2pp 22300 052 24X Fiche 50-000.83/11/30.8402220154
- 8402080221 Updated LER B3-008/01X-1 on B31110, alternate core spray check valves & reactor coolant post-accident sampling sys discharge isolation check valve exhibited leakage Caused by dirt Valves relapped & cleaned W/840127 ltr GOODMAN.L S , LINDER, F Dairyland Power Cooperative 84/01/27 KEPPLER, J O Region 3, Office of Director 3pp 22130 144 24X Fiche 50-409,84/01/27,8402080221
- 8402090291 LER 84-001-00 on 840107 during plant startup, essential bus main feed breaker 1A 480-volt opened Emergency diesel generator started & assumed load Reactor scrammed Caused by pickup voltage set high Voltage reset W/840131 ltr GOUDMAN.L S , LINDER, F Dairyland Power Cooperative 84/01/31 4pp 22159 194 24X Fiche 50-409,84/01/31.8402090291
- 402160267 LER 83-002-00 on 840117, reactor partial scram occurred due to low gas pressure on control rod drive mechanism Caused by failure of transducer O-ring. Ring replaced W/840213 ttr. GUDDMAN, L. S. LINDER, F. Dairyland Power Cooperative 84/02/13 3pp 22275, 108 24% Fiche 50-409, 84/02/13, 8402140267
- OCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2

 Application/construction stage documents & correspondence
- I402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documents
 FELTON.J M Division of Rules and Records B3/10/31
 ROSENBAUM.D M Technical Analysis Corp 17pp. 22173 292 24X
 Fiche 50-000.83/10/31.8402090003
- 8303240052 Advises that caseload forecast panel project completion date is Nov 1986, 7 months after official load date. Mgt meeting should be held in near Puture NOVAK.T M Assistant Director for Licensing 83/03/18 EISENHUT.D g Division of Licensing. 1p 22195 360. 24X Fiche 50-000, 83/10/31,8402070003.
- -8305110172 Forwards guidance on review schedule for OL application Resolution of const completion schedule differences requested prior to finalizing review schedule EISENKUT.D Q. Division of Licensing 83/04/04. NOVAK.T Assistant Director for Licensing. 3pp 66775 190 24% Fiche: 50-000.83/10/31.8402070003
- -8402090059 Hendwritten graph & calculations re const activities * NRC - No Detailed Affiliation Given 83/02/22. 3pp. 22196-012 24X Fishe 50-000.83/10/31,8402090003
- 8402090061 Marked-up draft summary of trip rept of Caseload Forecast Panel 830282-24 meetings re const progress review & mgt decision on allocation of staff resources during licensing review HAUGHEY: M Licensing Branch 2.
- 8402070063 Draft trip rept of Cassload Forecast Panel 830222-24 site visits re const progress review & estimating resource needs for licensing activities HAUGHEY, M. Licensing Branch 2 83/10/31 Licensing Branch 2 4pp 22176-015 24X Fiche 50-000,63/10/31,8402070003
- D2010004 Notification of 840120 meeting w/util in Bethesda, MD to discuss GA program -AUQHEV, MF Licensing Branch 2 84/01/13, BCHWENCER, A Licensing Branch 2, 3pp 22048 172 24X Ficher 50-410, 84/01/13, 8402010004
-)2100445 Notification of 830207 & OB meetings w/util & S&W in Therry Hill: NJ to discuss instrumentation & control. AddRey, M F Liconsing Branch 2. 84/02/03 SCHWENCER: A Liconsing Iranch 2. 3pp. 22213 033 24% Fichs 50-410.84/02/03.8402100445.

- B402160606 Requests revised response to B30812 request for addl info re PMP, per FSAR, Amend 7 Response should include rate determined in accordance w/Hydrometeorology Repts 51 & 52 Response requested by B40515 NDVAK, T M Assistant Director for Licensing B4/02/03 RHODE, G K Niegara Mohawk Power Corp 3pp 22302 030 24X Fiche 50-410,84/02/03.8402160606
- B402070277 Responds to Generic Ltr 84-01 re use of terms, important to safety & safety-related Opportunity to discuss issue welcomed Participation will be through steering committee & chairman of util safety classification group LEMPOES, TE Niegara Mohawk Power Corp 84/02/06 TAYLOR, J M Director's Office Office of Inspection and Enforcement ip 22161 347 24X Fiche 50-220,84/02/06,8402090277
- 8402100186 Advises that 830920 request for add1 info re FBAR Sections 13 5 2 & 15 8 amitted info for 640 36 re conformance to Reg Guide 1 33 Amend to FSAR.including corrected form & revised response requested SCHWENCER.A Licensing Branch 2 84/02/06 RHODE, O K Niagara Mohauk Power Corp 2pp 22205 185 24X Fiche 50-410,84/02/06,84/02/08
- 8402170458 Forwards request for addl info re use of ABME Code cases in const of sys & components Info should be submitted as FSAR amend by 840515

 9CHWENCER.A Licensing Branch 2 84/02/09 RHODE.O K Niagera Mohawk Power Corp 5pp 22313 353 24X Ficha 50-410,84/02/09,8402170458
- 8402150345 Forwards proprietary & nonproprietary structural audit open issue close out info Affidavit requesting proprietary status for info enci Proprietary info withheld LEMFGES.T E Niagara Mohawk Power Corp 84/02/10 9CHMENCER.A Licensing Branch 2 27pp 22243 129 84X Fiche 50-410.84/02/10. 8402150345
- 8402270137 Summary of B31212-16 meetings w/util & S&W Engineering in Cherry Hill: NJ re performance of structural audit Audit guidelines & list of attendees encl HAVOHEY, M F. Licensing Branch 2 84/02/16 Licensing Branch 2. 12pp 22408 036 24% Fiche 50-410.84/02/16.8402270137
- 8402270364 Forwards schedule for responding to open items identified during 831212-16 meetings w/util & S&M Engineering for structural design audit SCHIENCER, A Licensing Branch 2 84/02/16 RHODE.G K Niegara Mohauk Power Corp 2pp 22431 348 24X Fiche 50-410,84/02/16,84/02/054
- 8402240260 Notification of 840224 meeting w/util in Bethesda.MD to discuss administrative matters re closing out open items on facility HAUGHEY,M F Licensing Branch 2 84/02/17 SCHWENCER,A Licensing Branch 2 3pp 22381 263 24% Fiche 50-410,84/02/17,8402240260
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8402080439 Forwards draft SER input for Section 13 6 re physical security & Section 16 0 re Tech Specs Certain portions of security plan require add1 info Tech Specs acceptable MIRAGLIA,F J Assistant Director for Safety Assessment 84/01/30 NOVAK.T H Assistant Director for Licensing App 22168 282 24% Fiche 50-410,84/01/30,8402080439
- 8402130605 Forwards request for add1 info re radiological assessment, to complete review of draft SER Response required by 840515 in order to meet present licensing schedule SCHWENCER. A Licensing Branch 2 84/02/02 RHODE. 6 K Niegara Mohawk Power Corp 3pp 22214 306 24X Fiche 50-410, 84/02/02. 8402130605
- F Security, medical, emergency & fire protection plans
- 8402020473 Summary of 840112 meeting w/util at facility re fire brigade training F8AR will be revised to include specific areas listed in SRP (NUREG-0800) HAUGHEY.M F Licensing Branch 2 84/01/19 Licensing Branch 2 4pp 22062.157, 24X Fiche 50-410-84/01/19-8402020473,
- 8402080439 Forwards draft BER input for Section 13 6 rs physical security & Section 16.0 re Tech Specs Certain portions of security plan require add1 info Tech Specs acceptable.
 MIRAGLIA,F J. Assistant Director for Bafety Assessment 84/01/30 NDVAN.T M Assistant Director for Licensing 4pp 22168 282 24X Fiche 50-410.84/01/30.8402080439

- B402160644 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR SCHNENCER, A Licensing Branch 2 84/02/09 RHODE, O K Niagara Mohawk Power Corp 2pp 22301 309 24X Fiche 50-410, 84/02/09, 8402160644
- K Utility Final Safety Analysis Report (FSAR) & amends
- B402020359 Forwards Amend 8 to F5AR

 MANNO.6 F Niagara Mohawk Power Corp 84/01/25 EISENHUT.D Q

 Bivision of Licensing 2pp 22050 218 24x Fiche 50-410.84/01/25.

 8402020359
- --B402020363 Amend 8 to FSAR
 * Niagara Mohauk Power Corp 84/01/31 613pp 22050 220 24x
 Fiche 50-410,84/01/25,8402020359
- 8402060425 Forwards Affidavit of Svc indicating that Amend 8 to FBAR.DL stage provided to appropriate parties on encl distribution list, per 830329 ltr RNDDE.0 K Niagara Mohawk Power Corp 84/02/02 EISENHUT.D G Bivision of Licensing 3pp 22085 101 24X Fiche 50-410.84/02/02, 8402060425
- O Inspection reports. IE Bulletins & correspondence
- 8402020180 Forwards IE Insp Rept 50-410/83-16 on 831011-1202 & notices of violation & deviation BTAROSTECKI,R Division of Project & Resident Programs 83/12/30 RHODE,G.K., BEIDERT,C.R Niegara Mohawk Power Corp 2pm 22054 297 24X Fiche 50-410/83/12/30/8402020180
- --8402020183 Notice of violation from insp on 831011-1202 * Region 1, Office of Director 83/12/30 ip 22054 301 24X Fiche 50-410,83/12/30,8402020180
- --8402020187 Notice of deviation from insp on 831011-1202
 * Ragion 1, Office of Director 83/12/30. 1p 22054 302 24x
 Fiche 50-410,83/12/30,8402020180
- --8402020191 IE Insp Rept 50-410/83-16 on 831011-1202 Noncompliance noted failure to identify nonconforming weld configuration & improper acceptance of configuration & failure to compy w/ FBAR commitments & stds for structural steel installation GRAMM,R A Region i. Office of Director COLLINS,B J Division of Project & Resident Programs 83/12/28 16pp 22034 303 24; Ficher 50-410,83/12/30,8402020180
- B312120153 IE Info Notice 84-06, "Bteam Binding of Auxiliary Feedwater Pumps." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25. Consolidated Edison Co of New York
- 8402140339 Forwards IE Const Appraisal Insp Rept 50-410/83-18 on B31107-19 & 28-1209 DEYOUNG.R C Director's Office, Office of Inspection and Enforcement. 84/01/31 RHODE.G K Niagara Mohawk Power Corp 14pp 22220 119. 24X Fiche 50-410,84/01/31,8402140339
- B401170016 IE Info Notice 84-07. "Design-Basis Threat & Review of Vehicular Excess Controls " Bvc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co. of New York, Inc 119pp. 22114 179 24X Fiche 50-000,84/02/03,8401190016
- B401190017 IE Bulletin 84-01, "Cracks in BHR Mark I Containment Vent Headers " Svc list encl DEYOUNG,R C. Director's Office Office of Inspection and Enforcement. B4/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 136. 24X Fiche 50-000,84/02/03.8401190017
- 8401190041 IE Info Notice 84-09. "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R) " Syc list encl. JORDAN, E. L. Division of Emprescy Preparedness & Engineering
- enci. JORDAM: E.L. Division of Emergency Preparadness & Engineering Response (Post 830103), 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp. 22365-259, 24X Fiche: 50-000,84/02/13,8401190041

- 8401190039 IE Info Notice 84-08, "iOCFR5D 7, 'Employee Protection '" Svc list encl JORDANNE L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/02/14 Consolidated Edison Co of New York, Inc 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- B401190045 IE Info Nutice 83-63.Suppl 1. "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/15 Consolidated Edison Co of New York, Inc. 118pp 22366 142 24X Fiche 50-000.84/02/15, 8401190045
- 8401190062 IE Info Notice B4-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JDRDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/21 Consolidated Edison Co of New York: Inc 116pp 22366 024 24X Fiche 50-000, B4/02/21, B401190062
- 8402280168 Forwards SALP rept for Oct 1982 Sept 1983 List of attenders at BAO111 meeting re SALP also encl Areas needing add1 mgt attention include GA & piping sys & supports MURLEY.TE Region 1. Office of Director 84/02/23 RHODE,G K Niagara Mohawk Power Corp 5pp 22399 011 24X Fichs 50-410,84/02/23,8402280168
- --8402280172 SALP rept for Oct 1982 Sept 1983 * Region 1, Office of Director 83/12/12 33pp 22399 016 24X Ficha 50-410,84/02/23,8402280169
- --8402280177 Discusses SALP Board 831212 review Results documented in encl rept Meeting scheduled for 840111 in Philadelphia,PA to discuss assessment 81AROSTECKI,R. Division of Project & Resident Programs 83/12/29 RHDDE,G K Niagara Mohawk Power Corp 2pp 22399: 049 24X Fiche 50-410,84/02/23,8402280168
- --8402130353 Discusses reorganization of plant const & GA mgt Mgt
 Analysis Corp personnel will be fused into key mgt positions
 & util & S&H will be actively involved in improved
 performance of ITT Grinnell GA program
 RHDDE, O K Ningara Mohawk Power Corp 84/01/27. MURLEY, T &
 Region 1. Office of Director 4pp 22399 052 24x
 Fiche 50-410,84/02/23,8402280168
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies"

 Svc list encl

 JDRDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc. 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
 Svc list encl
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp. 22431 060 24X Fiche 50-000,84/02/27,8401190067
- 8 Reportable occurrences, LERs & related correspondence
- 8402060224 Interim deficiency rept re MJ Woolley CO GA documentation Initially reported on 830504 Final rept expected by 840630 DISE:DP Niagara Mohawk Power Corp 83/12/20 STARGSTECKI.R Division of Project & Resident Programs ip 22087 141 24X Fiche 50-410.83/12/20.8408060224
- 8402020126 Final deficiency rept re Agastat relay bases not tightened to metal channels in power generation control complex per GE instructions Initially reported on 830811 All bases will be inspected & replaced as needed by 840601

 DISE.D.F Niagara Mohauk Power Corp 84/01/16 BTARGSTECKI.R Division of Project & Resident Programs 3pp 22056 186 24X Fiche: 50-410.84/01/16.8402020126
- 8402070365 Part 21 rept re linear converter device w/possible generic defect Initially reported on 840116 Hritten notifications issued Customer responses should be received by 84033; Final rept will be submitted by 840430
 DDDSON, J P Pacific Air Products Co 84/01/30. Director's Office, Office of Inspection and Enforcement 2pp 22114 299. 24X Fiche, 50-000, 84/01/30, 8402070365
- --8402070373 Part 21 rept re linear converter device w/possible generic defect Initially reported on 840116. Preliminary analysis indicates excessive wear of brass shaft guides Next rept will be submitted within 90 days Supporting info encl DODSON. JP Pacific Air Products Co 84/01/17 POTAPQVS, U. Region 4. Office of Director & Bapp 22114 301 24X Fichs. 50-000, 84/01/30, 8402070365

- 8402150205 Deficiency rept re Kerite Control cable Final rept submittal
 - extended to 840731
 RHODE,G K Niagara Mohawk Power Corp 84/01/31 STAROSTECKI
 Division of Project & Resident Programs 1p 22245 144 24X
 Fiche 50-410,94/01/31,8402150205 STAROSTECKI, R
- B40224G0B0 Interim deficiency rept re GH Bettis actuators in safety-related dampers in HVAC sys supplied by Pacific Air Products Co Initially reported on B40104 Problem under investigation Next rapt by B40316 Also reported per Part 21 RHODE, G K Niagara Mohawk Power Corp B4/02/01 STARDSTECKI, R Division of Project & Resident Programs 2pp 22374 154 24X Fiche 50-410.84/02/01.8462240080
- 8402090283 Potential Part 21 rept re table insulation damage found under nuter jacket rework in one Class IE electrical cable investigation underway to determine safety significance &
- BA02240146 Interim deficiency rept re undersized structual steel shop welds Initially reported on BA0110 Reinsp program for welds will be developed Next rept will be submitted by B40330 LEMPGES, T E Niagara Mohauk Power Corp B4/02/06 STARDSTECKI.R Bivision of Project & Resident Programs 2pp 22374 341 24X Fiche 50-410.84/02/06.8402240146
- DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8305180559 Forwards FSAR & environ rept (filed in PDR Category C) for Beaver Valley Power Station, Unit 2 "Failure Modes & Effects Analysis" also encl HDDLEVER,E J Duquesne Light Co 83/03/16 DENTON,H F Nuclear Reactor Regulation, Director 2pp 22246 156 Fiche 80-412,83/05/16.8305180539 DENTON, H R Office of
- --8402140160 "Failure Modes & Effects Anaysis." Books 1 & 2 * Duquesne Light Co 83/05/16 1,004pp 22246 159 24X Fiche 50-412,83/05/16,8305180559
- 8402090003 Responds to FDIA request for const completion dates for nuclear plants currently under const & analyses containing astimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documents
 FELTON, J M Division of Rules and Records B3/10/31
 ROSENBAUM, D M Technical Analysis Corp 19pp 22193 292 24X
 Fiche 50-000.83/10/31.8402090003
 - 8402090092 Forwards revised NRC estimates for reactor const completion (fuel load) as of Jul 1983 Review & concurrence requested Related info encl
 SCROPOINS.R M Office of Resource Management, Director 83/07/26
 EISENHUT.D 0 Division of Licensing 18pp 22194 097 24X
 Fiche 50-000,83/10/31.8402090003
- 3402030057 Forwards request for add1 info re Unresolved Safety Issue A-43. "Containment Emergency Sump Performance " Meeting should be arranged w/licensing project manager to discuss request & schedule for formal response submittal KNIGHTON, 6 W licensing Branch 3 84/01/07 HOOLEVER, E J Duquesne Light Co 4pp 22091 059 24X Fiche 50-412,84/01/09, 8402030057
- 8402060270 Forwards "Control of Heavy Loads at Nuclear Power Plants, Beaver Valley Nuclear Power Plant Unit 2 (Phase I)." draft technical evaluation rept based on responses to NUREO-0612 SER on subj will be issued on 840728 KNIGHTON, 6 W Licensing Branch 3 84/01/17, WOOLEVER, E J Duquesna Light Co 3pp 22109 253 24X Fiche 50-412,84/01/17,8402060270
- --8401190528 "Control of Heavy Loads at Nuclear Power Plants, Beaver Valley Nuclear Power Plant Unit 2 (Phase I)," draft technical evaluation rept. FRIEDERICHS, 8 EGEG, Inc. FIN A-6457 83/11/30 NRC No Detailed Affiliation Given 45pp 22109.256 24x Fiche 50-412,84/01/17,8402060290
- 8401240177 Updates status of Westinghouse Dumers Group responses to Generic Ltr 83-10C. Reactor coolant pump trip criterion included in plant-specific emergency operating procedures to assure trip for all losses of primary coolant WDDLEVER, E. J. Duquesne Light Co. 84/01/19 EISENEUT, D. Q. Division of Licensing 3pp 21908 347 24% Fiche 50-412,84/01/19, 840-20177 of Licensing 8401240177

- B402160584 Responds to util B31026 ltr re Tech Specs Clarifies any misunderstanding as to procedure NRC follows in preparing Tech Specs KNIOHTGN, G W Licensing Branch 3 84/02/01 CAREY, J J , MODLEVER, E J Duquesne Light Co 4pp 22302 073 24X Fiche 50-412,84/02/01.8402160584
- 8402210037 Notification of B40215 meeting w/util in Bethesda.MD to continue discussion of certain items not closed out at previous meeting Branch 3 84/02/08 KNIGHTON, G W Licensing Branch 3 84/02/08 KNIGHTON, G W Licensing Branch 3 4pp 22331 357 24% Fiche 50-412,84/02/08,8402210059
- 8402170496 Forwards request for add1 info re FSAR Section 3 6 2.3 9 1-3 9 3 & 3 9 6 Meeting during wk of 840227 to discuss requests & schedule for formal submittal of responses suggested KNIGHTON, G W Licensing Branch 3 84/02/09 WOOLEVER, E J Duquesne Light Co 12pp 22319 017 24X Fiche 50-412,84/02/09, 8402170494
- 8402150389 Forwards correspondence of facilities use of heavy-wall pipe fittings at facilities Requests info re uses of heavy pips fittings & effects on piping design analyses & what NRC has done re stiff pipe clamps at facilities HIATT.S L Ohio Citizens for Responsible Energy 84/02/10 STEFANU.J J Division of Licensing ip 22241 311 24X Fiche 50-000.84/02/10.8402150389
- --8402130394 Forwards staff evaluation of effect of over thickness in pipe fittings in various facilities KNIGHTON.0 W Licensing Branch 3 B4/01/27 WOOLEVER,E J 8402150389
- --B402150402 Staff evaluation of effect of over thickness in pipe fittings Based of resolution of identified concerns, (asua re use of oversize pipe fittings can be acceptably resolved * NRC No Datailed Affiliation Given B4/01/27 15pp 22241 315 24X Fiche 50-000,84/02/10,8402150389
- 8402240155 Forwards proprietary "Recirculation Spray Bys Pump NPSH Requirements," proprietary "Installation Operation & Maint Manual" & sevem proprietary oversize drawings Info withheld (ref iOCFR2 790) Aperture cards in Central Files MODLEVER: E J Duquesne Light Co 84/02/21 LAZO, L Licensing Branch 3 1p \$2374 318 \$24X Fichs 50-412,84/02/21,8408240155
- 8402270238 Forwards responses or schedule for providing responses to 28 items identified during 840131-0203 NRC structural design audit Audit agendan notes of conference & list of items developed by NRC reviewers. D Jeng & KC Leu, also encl WOOLEVER. E J Duquesne Light Co 84/02/27 KNIGHTON, 0 W Litemsing Branch 3 30pp 22424 287 24X Fichs 50-412,84/02/27,8402270238
- C Utility Environmental Report (ER), amends & correspondence
- 8402130046 Forward: Amend 4 to environ rept OL.consisting of responses to NRC 831020 request for add1 info Complete yr of meteorological data in NRC format & correspondence w/Btate Historic Preservation will be submitted separately WOOLEVER.E J Duquesne Light Co. 84/02/09 DENTON,H R. O. Nuclear Reactor Regulation, Director 4pp 22217 004 24X Fiche 50-412.84/02/09.8402130046
- --8402130048 Amend 4 to environ rept DL
 # Stone & Webster Engineering Corp
 # Duqueene Light Co
 B4/02/27 108pp 22217,007 24X Fiche 50-412,84/02/07,
 B402130046
- 8402130470 Forwards response to 831020 request for add1 info re environ rept acceptance review questions Requested info listed WOOLEVER, E.J. Duquesne Light Co. 84/02/09 DENTON, H. R. Office of Nuclear Reactor Regulation, Director KNIGHTON, Q. NRC No Detailed Affiliation Given 9pp 22202 039 24x Fiche. 50-412, 84/02/09, 8402130470
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8402270008 Forwards draft SER input for Sections 13 6, "Physical Security" k 14 0, "Tech Specs," in response to 830729 memo. Security plan rays still under review MIRAGLIA,F J Assistant Director for Safety Assessment, 84/02/13 NOVAK,T M Assistant Director for Licensing 3pp 22408,028, 24 Fiche: 50-412,84/02/13,8402270008.

- F Security, medical, emergency & fire protection plans
- 8402160558 Forwards comments on detailed control room design review program plan, submitted per Suppl 1 to NUREO-0737 & NUREO-07700 & 0801. Plan does not address verification that improvements will provide correction of discrepancies KNIGHTON, 0 W Licensing Branch 3 84/01/23 WOOLEVER, E J Duquesne Light Co 14pp 22301 327 24X Fichs 50-412,84/01/23,8402160658
- 8402270008 Forwards draft SER input for Sections 13 6, "Physical Security" & 16 0, "Tech Specs." in response to 830729 memo Security plan revs still under review MIRAGLIA: T J Assistant Director for Safety Assessment 84/02/13 NOVAK: T M Assistant Director for Licensing 3pp 22408 028 24X Fiche 50-412.84/02/13.8402270008
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8402130184 Forwards Amend 3 to FSAR, consisting of responses to questions re initial test program, containment sys, auxiliary sys & revised text matl HOQLEVER, E J Duquesne Light Co 84/02/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 22224 001 24X Fiche 50-412,84/02/09,8402130184
- --8402130188 Amend 5 to FSAR * Duquesne Light Co. 84/02/27 827pp 22224 005 24X Fichs 50-412,84/02/09,8402130184
- G Inspection reports, IE Bulletins & correspondence
- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps." Bvc list encl JDRDAN,E L. Division of Emergency Proparedness & Engineering Response (Post 830103). 84/01/25 Consolidated Edison Co. of New York, Inc. 120pp. 22058 001 24X Fiche 50-000.84/01/25.6312120153
- 8402130302 Forwards IE Insp Rept 50-412/83-17 on 831201-840114 No violations noted STAROSTECKI.R Division of Project & Resident Programs. 84/01/31 MDQLEVER.E J Duquesne Light Co 2pp 22244 237 24X Fiche, 50-412, 84/01/31
- ~~8402150306 IE Insp Rept 50~412/83~17 on 831201~840116 No violations noted Major areas inspected previously identified unresolved items, info notices, IE bulletins, NDE & hydrostatic test.

 WALTON, Q A Region 1, Office of Director. TRIPP, L E Division of Project & Resident Programs 84/01/27 10pp 22244 237 24X Fiche 50~412,84/01/31,8402150302
- 8402070180 Ack receipt of 831223 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-412/83-01 MARTIN.T. Division of Engineering & Technical Programs 84/02/02 WOOLEVER.E J Duquesne Light Co 2pp. 22102.178 24X Fiche 50-412,84/02/02.8402070180
- --8402070184 Responds to NRC 830210 ltr re violations noted in IE Insp. Rept 50-412/83-01 Corrective actions grinding phase of rework on cold leg steam generator nozzles will be completed by 840131. Weld repair will be completed by 840731. WOOLEVER, E. J. Duquesne Light Co. 83/12/23 STARDSTECKI, R. Division of Project & Resident Programs 3pp. 22102:180 24X Fiche: 50-412,84/02/02,8402070180
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Bvc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Poet 830103) 84/02/03 Consolidated Edison Co of New York, Inc. 119pp. 22114 179 24X Fiche 50-000,84/02/03,8401190016.
- 8401190017 IE Bulletin 8A-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list enct DEYOUNG.R C Director's Office, Office of Inspection and Enforcement. B4/02/03 Consolidated Edison Co. of New York, Inc 102pp 22177 156. 24X Fiche 50-000,84/02/03,8401190017.
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown 8ys (10CFR50: App R) " Svc list ancl.
 JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Inc 124pp 22365:259, 24X Fiche 50-000,84/02/13,8401190041
- 8401190039 IE Info Notice 84-08, "IOCFRSO.7, 'Employee Protection '"

 Byc list encl.

 JDRDAN.E L. Division of Emergency Preparedness & Engineering

 Response (Post 830103), 84/02/14. Consolidated Edison Co. of New

 York, Inc. 115pp 22349:141 24X Fiche 50-000,84/02/14,8401190039

- 8401190045 IE Info Notice 83-63, Suppl 5: "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JURDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc. 118pp 22366 142 24X Fiche 50-000, 84/02/15, 8401170045
- B401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value" Bvc list encl JDRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 630103) 84/02/21 Consolidated Edison Co. of New York, Inc. 116pp 22366 024 24X Fiche 50-000,84/02/21,8401190062
- 8401190066 IE Info Notice 84-11. "Training Program Deficiencies "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000.84/02/24.8401190086
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
 Svc list encl
 JURDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/02/27 Consolidated Edison Co of New
 York, Inc. 120pp 22431 060 24X Fiche 50-000.84/02/27.8401190067
- 9 Reportable occurrences, LERs & related correspondence
- 8402140398 Requests add1 info re Pert 21 rept dt8 831108 concerning wear ring failure in auxiliary feedwater pump furnished to facilities Info requested within 25 days PUTAPOV8.U Region 4. Office of Director 83/11/30 PAYTY.D F Bingham-Willamette Co ip 22221 250 24% Fiche 50-000,83/11/30.8402140398
- --B402140422 Supplemental Part 21 rept re wear ring failure in auxiliary feedwater pumps, per 831130 request for addi info Wear rings will be replaced on returned units w/AISI 420 urought matl List of pumps in similar svc w/same wear ring encl PATTY, DF Hingham-Willamette Co 83/12/20 Region 4, Office of Director 2pp 22221 251 24X Fiche 50-000.83/11/30, 8402140398
- 8402240086 Further response to FDIA request for 16 categories of documents Item 9 limited.per 831005 telcon Forwards Rev 7 to NUREO-0325 & App A documents Portions of App B documents withheld (ref FDIA Exemption 4) App B documents also in PDR FELTON.J M Division of Rules and Records 83/12/12 SHOLLY.S C Union of Concerned Scientists 4pp 22394 150 24% Fiche 50-000.83/12/12,8402240086
- 8402030467 Final Bignificant Deficiency Rept 83-03 re potential for misoperation of BB-416 reactor trip switchgear undervoltage attachments. Four replacement undervoltage attachments to be installed prior to initial operation MODLEVER, E J Duquesne Light Co 84/01/05 BTARGBTECKI, R Division of Project & Resident Programs App 22066 019 24X Fiche 50-412,84/01/05.8402030467
- DOCKET 50-413 CATAWBA NUCLEAR BYATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caselbad Forecast Panel meetings Forwards App A.B & C documents
 FELTON.J M Division of Rules and Records 83/10/31
 RDSENBAUM.D M Technical Analysis Corp 19pp 22193 292 24X
 Fiche 50-000.63/10/31.8402090003
- --B402090102 Handwritten notes & graph re tests concerning const activities & fuel load dates * NRC - No Detailed Affiliation Given 83/08/01 2pp 22194 156 24X Fiche 50-000,83/10/31,8402090003
- --B402070105 Handwritten notes & calculations re fuel load preparation & const activities

 * NRC No Detailed Affiliation Given 81/08/13 ip 22194 180 24% Fiche 50-000, 83/10/31, 8402070003
- --8402070107 Handwritten notes & calculations re const & fuel load preparation

 * NRC No Detailed Affiliation Given 80/04/23 4pp, 22174 162 24X Fiche. 50-000.83/10/31,8402090003
- --B402090124 Handwritten notes & calculations re facility const Related info enc! * NRC - No Detailed Affiliation Given 83/10/31, 48pp 22194 200 24X Fiche 50-000.83/10/31,8402090003.

- 8312120134 Board Notification 84-011 discusses NRC use of terms "important to safety" & "safety-related" EISENHUT.D 9 Division of Licensing 84/01/18 PALLADING Commissioners 72pp 22241 008 24% Fithe 50-000,84/01/18,8312120136
- B401190012 Board Notification 84-013 forwards info re Transamerica Delaval, Inc emergency diesel generators EISENHUT,D 6 Division of Licensing 84/01/24 PALLADIND,N Commissioners 10pp 22054 346 24% Fiche 50-000,84/01/24, B401190012
- 8402060612 Notification of contract execution, Mod 2 to "Radiation Monitoring Program Requirements" Contractor State of BC UMBEL.D Technical Assistance Contracts Branch FIN B-8403 84/01/26 MALEY.R J Region 2. Office of Director MONTGOMERY.D M NRC No Detailed Affiliation Given | Ip 22092 083 24X Fiche 50-413.84/01/26.8402060612
- --8402060618 Mod 2 providing add1 funds for CY84 & incorporating environ monitoring for period Jan 1984 Dec 1985 to "Radiation Monitoring Program Requirements" * South Carolina, State of GUSTAVE.R P Division of Contracts FIN 8-8403 84/01/26 ip 22092 084 24% Fiche 30-413.84/01/26.
- B402070310 Amend 30 to application for OLs, consisting of Rev 8 to FSAR to include deletion of boron injection tank, revised fuel enrichment & reduced ice weight analysis
 TUCKER, H B Dute Power Co B4/01/26 DENTON, H R Office of uclear Reactor Regulation, Birector ADENBAM, E 6 Licensing Branch 2pp 22097 045 24% Fiche 50-413,84/01/26,8402070310
 - 1190015 Board Notification 84-018 provides info re failure experience of Transamerica Delaval emergency diesel generators in marine svc EISENHUT, D 0 Division of Licensing 84/01/27 PALLADING, N J Commissioners 385pp 22093 027 24X Fiche 50-000, 84/01/27, 8401190015
- B402010195 Forwards 840103 rev to License BNM-1920, authorizing possession & use of small amounts of SMM for use as nuclear detecting devices & testing of instruments No action required by ASLB re issuance of license JOHNSON, 0 E Haaring Branch 4 B4/01/27 KELLEY, J L , PURDOM, P W , FOSTER, FF Atomic Safety and Licensing Board Panel 21pp 22040 315 24X Fiche 50-413,84/01/27.8402010195
 - 20701B1 Forwards add1 info describing design verification & Jalification testing for procurement of safety-related quipment in response to Generic Ltr 83-28 Enc1 info suppls \$1104 response JCKER.H B Duke Power Co B4/02/02 EISENHUT.D 9 Division of Icensing 5pp 22102 183 24X Fiche 50-413,84/02/02:84020701B1
 - 2130616 Advises that Class III license fee remitted \(\omega/\text{830309}\)
 \(\text{upplication requesting exemption from requirements of 10CFR50.App E.Section IV \(\nabla\text{uill}\) be refunded Exemption authorized by law & is in public interest
 \(\text{MILLER,W O License Fee Management Branch } \text{84/02/03} \) TUCKER,H B
 \(\text{Duke Power Co 1p 22214 275 } \text{24X Fiche 50~000,84/02/03}\),
- 02:100429 Notification of 840208 meeting w/util in Bethesda, MD to discuss program for environ qualification of equipment JABBOUR, K N Licensing Branch 4 84/02/06 ADENBAM, E 0 Licensing Branch 4 1p 22212 321 24K Fichs 50-413, 84/02/06, 8402100429
- 402100474 Notification of 840207 meeting w/util.Sandia Natl Lab & EG&G in Bethesda, MD to discuss environ qualification of DG O'Brien genetrations

 JABBOUR, K N Licensing Branch 4 84/02/06 ADENSAM, E 9 Licensing Branch 4 2pp \$2213 047 24% Fiche 50-413,84/02/06,8402100474
- 8402160601 Requests add1 info re onsite audit of seismic & dynamic qualification of equipment & pump & valve operability program List of equipment selected for 840313-16 review & audit encl Response requested by 840217.

 ADENSAM, E.G. Litensing Branch 4 84/02/06, TUCKER, H. B. Duke Power Co. 4pp. 22272 297 24% Fiche 50-413,84/02/06,8402160401
- B402170061 Notification of 840210 meeting w/Transamerica Delaval. Inc (TDI) in Bethesds. MD to discuss program plan proposed by TDI Owners Group to qualify dissel generators GARUSO.R Division of Licensing 84/02/06 BERLINGER.C Division of Licensing 2pp 22312 339 24X Fiche 50-000.84/02/06, 8402170061

- B402130417 Forwards Procedure AP/1/A/5500/31: "Estimate of Failed Fuel Based on I-131 Concentration," in response to MRC request to complete review of MREG-0737.1tem II B 3 TUCKER, H B Duke Power Co 84/02/07 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAME & Licensing Branch 4 7pp 22201 281 24x Fiche 50-413,84/02/07.8402130417
- --8402130422 Procedure AP/1/A/5500/31, "Estimate of Failed Fuel Dased on I-131 Concentration"

 * Duke Power Co 84/02/07 Bpp 22201 288 24X Fiche 50-413.84/02/07, 8402130417
- B402130459 Forwards response to Item 9 of B30303 request for add1 infore onviron qualification of safety-related electrical equipment, covering containment isolation valves & boric acid transfer pumps

 TUCKER, H D Duke Power Co B4/02/07 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM.E G Licensing Branch 4 55pp 22201 303 24X Fiche 50-413, B4/02/07, B402130467
- B402070251 Responds to NUREG-0588 demonstrating that electrical equipment required to perform safety-related function in harsh environ appropriately qualified TUCKER.H B Duke Power Co 84/02/08 DENTON, HR Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 294pp 22163 326 24% Fiche 50-413,84/02/08,8402090251
- B401190099 Board Notification 84-032 provides add1 info on environ qualification Submittal augments info in Board Notifications 84-004 & 84-007 EISENHUT.D 0 Division of Licensing B4/02/13 Atomic Safety and Licensing Board Panel 10pp 22314 204 24% Fiche 50-000.84/02/13.8401190099
- 8402170292 Provides supplemental info supporting 841i18 submittal re elimination of arbitrary intermediate pipe breaks, in response to NRC 840207 request W/19 oversize drawings, including one illegible Aperture cards are available in PDR TUCKER, H B Duke Power Co 84/02/15 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E O Licensing Branch 4 16pp 22296 129 24X Fiche 50-413,84/02/15,8402170292
- 8401190068 Board Notification 84-033 provides "Sys Interaction Program," task action plan for Unresolved Safety Issue A-17 Distribution list encl EISENHUT.DO Division of Licensing 84/02/16 PALLADIND Commissioners 8pp 22482 091 24X Fiche 50-000.84/02/16. 8401190068
- 840,2220564 Advises of plans to perform approved mod on Unit 2 Model D5 steam generators & provides plant-specific details required by NUREO-1014 Mods to Unit 1 steam generators will be completed prior to fuel loading date of 840501 TUCKER.H B Duke Power Co 84/02/20 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENBAN.E G Licensing Branch 4. 7pp 22333 143 24X Fiche 50-413,84/02/20,84022205564
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 8402060077 Informs of actions taken to complete Confirmatory Issue 25 discussed in BER. Section 7 3 2 1 Steam generator overfill protection sys installed, eliminating issue of single channel failure causing high-high level trip TUCKER.H B Dute Power Co 84/02/01 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENBAN.E O Licensing Branch 2 2pp 22088 237 24% Fiche 50-413.84/02/01.8402060077
- 8402060087 Responds to SER. Section 4 4 3 4. Open Item & reinstrumentation for inadequate core cooling detection (TMI Item II F 2) Phase i complete Control room displays will be modified upon completion of control room design review TUCKER. H B Duke Power Co 84/02/01 DENTON. H R Office of Nuclear Reactor Regulation, Director ADENSAM. E 0 Licensing Branch 4 10pp 22088 261 24% Fiche 50-413,84/02/01.8402060087
- 8402040273 Forwards rayised Section 2 4 2 3 re effect of local intense practitation for FSAR, in response to SER Confirmatory Itam 1 W/four oversize figures Aperture cards are available in FDR Matl will be incorporated in Rev 9 to FSAR TUCKER, H B Duke Power Co 84/02/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 30pp 22083 001 24% Fische, 50-413,84/02/01,8402060279
- B402140470 Forwards inlet & discharge piping info omitted in 831026
 Lit in response to SER Section 3 7 3 2 & NUREO-0737, Item
 II D 1.
 TUCKER, H B Duke Power Co B4/02/03 DENTON, H R Office of
 Nuclear Reactor Regulation, Director ADENSAM, E. G Licensing Branch
 4 3pp 82236 207 24X Fiche 50-413, 84/02/03, 8402140470

- 8402130337 Forwards revised response to Question 440 48 of SER, Confirmatory Item 36 re flooding of electrical equipment due
 - TOCKER, H B Duke Power Co 84/02/07 DENION, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 App 22197 120 24X Fiche 50-413,84/02/07,8402130337
- 8402220538 Forwards add1 info needed to complete SER Info includes procedures used to measure value of critical parameters, method of recording & managing data & identification of interpretation of data & sequence in timing TUCKER.H B Duke Power Co 84/02/15 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E O Licensing Branch 4 3pp 22331 001 24X Fiche 50-413,84/02/15,8402220538
- --8402220539 Change 1 to Procedure CP/D/A/8100/01, "Chemistry Procedure for Determination of pH"

 EVANS.L D . CHAUST.R H , TUCKMAN,M S Duke Power Co 80/07/18

 2pp. 22331 004 24% Fiche 50-413.84/02/15.8402220338
- -B402220542 Change O to Procedure CP/O/A/8100/42. "Chemistry Procedure for Determination of Chloride Belective Ion Electrode " BOLIN.C W. FAINTER.R L , COX.J W Duke Power Co B3/11/11 12pp 22331:097 24X Fiche 50-413.84/02/15.8402220538
- --8402220546 Change O to Procedure CP/O/A/8100/01, "Chemistry Procedure for Determination of pH" CHAUST,R H, EVANS.L D, COX.J W Duke Power Co 80/01/28 18pp 22331.006 24X Fiche 50-413.84/02/15,8402220538
- --B402220547 Change O to Procedure CP/O/B/B150/03, "Chemistry Procedure for Determination of Bodium Auto Analyser "
 DICKEY, C , EVANS, L D , TUCKMAN, M S Duke Power Co, B3/05/12
 17pp. 2231 109. 24X Fiche 50-413.B4/02/15.B40222053B
- --8402220548 Change 0 to Procedure CP/D/B/8100/17, "Chemistry Procedure or Determination of Hydrazine"
 DICKEY,C 8, EVANS,L,D, TUCKMAN,M 8 Duke Power Co 83/09/30
 7pp 22331 024 24x Ficher 50-41g,84/02/15,8402220338
- -8402220547 Change O to Procedure CP/O/B/B100/52, "Chemistry Procedure for Determination of Sodium Furnace AA " PAINTER.R L., EVANS.L D., CDX.J W Duke Power Co 83/11/14 9pp 2231.126 24X Fiche-50-413.84/02/15,840220538
- --8402220552 Change 1 to Procedure CP/O/B150/05, "Chemistry Procedure for Determination of Hydrazine: Auto-Analyzer."
 BOLIN,C.W., EVANS,L.D., TUCKMAN.M S Duke Power Co 83/10/20
 2pp. 22331 031 24% Fiche. 50-413, 84/02/15, 84/02/2038
- --8402220554 Change O to Procedure CP/O/B/B150/04, "Chemistry Procedure for Determination of Dissolved Oxygen Auto Analyzer." PAINTER,R L , EVANS,L D , TUCKMAN,M S Duke Power Co 82/12/11 12pp. 22331 155 24x Fiche 50-413,84/02/15,840220538
- --8402220555 Change O to Procedure GP/O/8/8150/05, "Chemistry Procedure for Determination of Hydrazine, Auto-Analyzer"
 PAINTER.R.L., EVANS.L.D., TUCKMAN.M S Duke Power Co., 82/11/18
 4pp 22331 033 24X Fiche, 30-413, 84/02/15, 8402220558
- --8402220560 Change O to Procedure CP/D/B/B150/02. "Chemistry Procedure for Determination of Conductivity. Auto-Analyzer "
 DICKEY, C B., PAINTER, R L., TUCKHAN, M B. Duke Power Co. 92/11/17.
 7pp. 22331 039. 24X Fiche 30-413.64/02/15.8402220538
- --8402220561 Change O to Procedure CP/O/A/8100/11, "Chemistry Procedure for Determination of Dissolved Dxygen" CHAUST,R H., EVANS,L,D, TUCKMAN,M B Duke Power Co 79/08/14 14pp. 22331:147, 24X Fiche 50-41d,84/02/15.8402220538.
- --8402220563 Change 1 to Procedure CP/O/B/8100/02, "Chemistry Procedure for Determination of Specific Conductivity " BOLIN,C., PAINTER, R. L., TUCKMAN, M. B. Duke Power Co. 82/11/14 9pp 22331 048 24X Fiche: 80-413.84/02/15.8402220538
- --B402220566 Change O to Procedure CP/O/D/Bi00/07, "Chemistry Procedure for Determination of Buspended Solids Millipore Filters "PAINTER.R.L., EVANB.L D., TUCKMAN,M S. Duke Power Co 83/07/15 11pp 22331 161. 24x Fiche 50-413,84/02/15.8402220538
- --8402220569 Change & to Procedure CP/D/A/8100/05, "Chemistry Procedure for Determination of Chloride (Manual Method)" MCNEILL.B., CHAUST.R H, COX.J.W Duke Power Co 84/01/06 ip. 22331 057. 24X Fiche 50-413.84/02/15.8402220538
- --8402220572 Change 4 to Procedure CP/D/A/8100/05, "Chemistry Procedure for Determination of Chloride (Manual Method)" MCNEILL,B., EVANB,L.D., CDX, JW. Duke Power Co 83/12/30 3pp 22331:058 24X Fiche 50-413.84/02/15.8402220538

- --8402220573 Change 2 to Procedure CP/D/B/B100/08, "Chemistry Procedure for Determination of Bilica (Manual Method) " BOLIN, C W, CHAUST, R H, TUCKMAN, M S Duke Power Co 82/06/29 3pp 22331 172 24% Fiche 50-413.84/02/15.8402220538
- --8402220575 Change 0 to Procedure CP/D/B/B100/13, "Chemistry Procedure for Determination of Copper Furnace AA " PAINTER.R L , EVANB,L D , COX, J W Duke Power Co B3/11/14 9pp 22331 212 24X Fiche 50-413, 84/02/15, 8402220558
- --8402220579 Change 3 to Procedure CP/D/A/B100/05, "Chemistry Procedure for Determination of Chioride (Manual Method) "
 PAINTER, R L , EVANS, L D , TUCKMAN. M S Duke Power Co 83/05/31
 1p 2231 041 24X Piche 30-413,84/02/15,8402220538
- --B402220580 Change 1 to Procedure CP/0/B/8800/05, "Chemistry Procedure for Recording & Mot of Data" PAINTER.R L , EVANS.L D , COX.J W Duke Power Co 83/12/29 1p 22331 221 24X Fiche 50-413.84/02/15.8402220538
- --8402220581 Change 0 to Procedure CP/0/B/B100/08, "Chemistry Procedure for Determination of Bilica (Manual Method)" PAINTER,R L , EVANS,L D , TUCKMAN,H S Duke Power Co 82/05/28 lipp 22331 175 24% Fiche 50-413,84/02/15,8402220338
- --8402220583 Change 2 to Procedure CP/O/A/8100/05, "Chemistry Procedure for Determination of Chloride (Manual Method) "
 MCAFEE,C, CHAUST, R H, TUCKHAN, M S Duke Power Co 82/12/03
 2pp 22331 062 24% Fiche 50-413.84/02/15.8402220538
- --B402220585 Changs O to Procedure CP/O/B/8800/05, "Chemistry Procedure for Recording & Mgt of Data " PAINTER,R L , EVANS,L D , TUCKMAN,M S Duke Power Co 83/11/07 42pp 22331 222 24X Fiche 50-413,84/02/15,8402220538
- --8402220587 Change O to Procedure CP/D/B/8100/51, "Chemistry Procedure for Datermination of Iron Furnace AA" PAINTER:R L , EVANS,L D , COX.J W Duke Power Co 83/11/14 9pp 22331 186 24X Fiche 50-413.84/02/15.8402220538
- --8402220588 Change i to Procedure CP/O/A/B100/05, "Chemistry Procedure for Determination of Chloride (Manual Method) "PAINTER,R L , CHAUST,R H , TUCKHAN,M 8 Duke Power Co 81/02/25 2pp 2233 064 24% Fithe 50-413.84/02/15
- --8402R20590 Procedure AP/D/8/5500/34, "Abnormal Procedure for Becondary Chemistry Parameters Out of Spec " # Duke Power Co 84/02/15 4pp 22331 264 24X Fichs 50-413,84/02/15,840222038
- --840222059; Change O to Procedure CP/D/A/8100/05, "Chemistry Procedure for Determination of Chloride (Manual Method) " CHAUST,R H , EVANS,L D , COX,J W Duke Power Co. 80/06/27 19pp 22331 066 24X Fiche 50-413,84/02/15,84022053B
- --8402220593 Change 0 to Procedure CP/D/8/8100/RO, "Chemistry Procedure for Determination of Ammonia" BDLIN,C W, EVANS,L D, TUCKMAN,H S Duke Power Co 83/10/06 17pp. 22331 175 24X Fiche 50-413,84/02/15,8402220538
- --8402220594 Change 1 to Procedure CP/O/A/8150/07, "Chemistry Procedure for Determination of Chioride Auto-Analyzer "CRISP, A : CHAUST, R H. ; COX. J W Duke Power Co 83/12/06 1p 22/31 085 24X Fiche 50-413.84/02/15.8402220538
- --8402220595 Change O to Procedure CP/O/A/Bi50/07. "Chemistry Procedure for Determination of Chioride Auto-Analyzer."
 BOLIN.C.H., PAINTER.R.L., COX.J.W. Dute Power Co. 82/07/29.
 11pp. 22331 086 24% Fiche 50-413,84/02/15,840220538
- B402220359 Forwards description of reactor coplant pump motor oil NOWEWELDS Y FORWARDS description of Feattr contant pump motor oil collection sys, per Section 7 5 1 of SER which discusses

 Open Item 14, "Fire Protection Program " W/one oversize drawing, Aperture card is available in PDR

 TUCKER, H B Duke Power Co 84/02/20 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E 9 Licensing Branch 4 3pp. 22337, 151 24X Fiche 50-413, 84/02/20, 8402220357
- 8402220385 Forwards revised historical earthquake data implementation schedule.per Section 18 2 of SER Dpen Item 18. "Control Room Design Review "Implementation of identified historical earthquake data solutions acceptable.
 TUCKER.H.B. Duke Power Co 84/02/20 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E. Q Licensing Branch 4 Bpp R2335 270 24X Fichs 50-413.84/02/20.8402220385.

- F Security, medical, emergency & fire protection plans
- 8402010243 Forwards comments on public info brochure & fire protection site audit summary Applicant should verify that fire protection program will be completed by fuel load Response requested by 840221

 ADENSAM. E 0 Licensing Branch 4 84/01/20 TUCKER.H B Duke Power Co 10pp 22047 307 24X Fiche 50-413.84/01/20.8402010243
- B402090323 Forwards Rev 3 to util response to Suppl 1 to NURE9-0737 Correcting Section J re physical changes, Section II re surface enhancements to Page 6-7 re emergency procedure training TUCKER, H B Dute Power Co B4/01/30 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E O Licensing Branch 4 App 22160 252 24X Fiche 50-413, 84/01/30, 8402090323
- 8402060100 Forwards revised response to FSAR Question 430 91 re seismic qualification status of temp detectors in diesel room fire protection sys Detectors seismically qualified by Hyle Labs TUCKER.H B Duke Power Co 8402/02 DENTON.H R Office of Nuclear Reactor Regulation. Director ADENSAN.E G Licensing Branch 4 3pp 22087 180 24X Fiche 50-413.84/02/02.8402060100
- B402140338 Forwards changes per Suppl I to NUREO-0737 to implementation schedule for historical earthquake data solutions to be completed by end of first refueling outage TUCKER.H B Duke Power Co B4/02/07 DENTON.H R Office of Nuclear Reactor Regulation. Director ADENSAM, E G Licensing Branch 4. Opp 22220 254 24X Fiche 50-413, 84/02/07, 8402140338
- 8402130409 Forwards response to NRC fire protection site audit numbers for facility TUCKER.H B Duke Power Co 84/02/10 DENTON,H R Office of Nuclear Reactor Regulation. Director ADENSAM.E & Licensing Branch 4 10pp 22203 239 24x Fiche 50-413,84/02/10,8402130409
- 8402220359 Forwards description of reactor coolant pump motor oil collection sys.ger Section 9 5 i of SER which discusses Open Item 14. "Fire Protection Program " Wome oversize drawing Aperture cand is available in PDR TUCKER.H B Dute Power Co 84/02/20 DENTON.H R Office of Nuclear Reactor Regulation. Director ADENSAM.E O Licensing Branch 4 3pp 22337 151 24X Fiche 50-413.84/02/20.8402220359
- 840-2240085 Forwards response to questions re vital areas/equipment identification Response withheld (ref 10CFR73 21) TUCKER.H B Duke Power Co 84/02/20 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22375 010 24% Fiche 50-413,84/02/20,8402240085

Adjudicatory correspondence

- 3402010175 Forwards 840103 rev to License SNM-1920, authorizing possession & use of small amounts of SNM for use as nuclear datecting devices & testing of instruments No action required by ASLB re issuance of license JOHNSON, 0 E Hearing Branch 4 84/01/27 KELLEY, J. L., PURDOM, P. W., FOSTER, R. F. Atomic Safety and Licensing Board Panel 21pp 22040 315 24X Fiche 50-413.84/01/27,8402010175
- B402010249 Requests that S Perry of FEMA be placed on proceeding svc list JOHNSON.GE Hearing Branch 4 84/01/27 KELLEY.JL, FDSTER.R F Atomic Safety and Licensing Board Panel 1p 22041 340 24X Fiche 50-413.84/01/27.8402010249
- B402070046 Response opposing applicant 840112 patition for directed cartification & reversal of ASLB admission of Contention il re emergency planning zone Cartificate of Svc encl JOHNSON, G E Hearing Branch 4 84/02/01 Atomic Bafety and Licensing Appeal Panel 14pp 22103 011 24X Fithe 50-413, 84/02/01.8402070046
- 1402060204 Request to all parties to add 9 Perry to svc list KELLEY, J.L. Atomic Safety and Licensing Board Panel 84/02/02 ip 22097 141 24X Fiche 50-413;84/02/02:8402040204
- I4020B0171 Centinues B40131 discussion on whether applicant provised Palmetto Alliance & Carolina Environ Study Group w/cepies of control room design review Certificate of Svc encl MCGARRY. J M. Bishop. Liberman. Cook. Purcell & Reynolds. MCGARRY. J M. Duke Power Co. B4/02/02 KELLEV.J.L., PURDOM.P W., FUSIER. F. Atomic Safety and Licensing Board Panel App. 2212B-246 24X Fiche 50-413.84/02/02.8402080171

- B402080203 Response apposing applicant motion to bifurcate hearing resumrgency plan contentions Bifurgation would inhibit development of adequate record on emergency plan issues Affirmation of Svc encl RILEY, J. L. Gavernment Accountability Project 84/02/02. Atomic Safety and Licensing Board Panel 76P 22130 155 24X Fiche 50-413, 84/02/02. 8402080203
- B402070153 Affidavit of MF Lowe in response to W Dwen B4011B affidavit re delay of fuel load & testing activities Certificate of Bvc encl LOWE/M F Palmetto Alliance 84/02/03 4pp 22103 042 24X Fiche 80-413,84/02/03,8402070153
- 8402140138 Forwards intervenors interrogatories in proceeding W/o encl MCGURREN.H J Hearing Branch i 84/02/03 PERRY, S Affiliation Not Assigned ip 22219 263 24x Fiche 50-413, 84/02/03, 8402140158
- 8402080164 Notice of intent to take deposition of JL Riley on 840208 re future administrative hearings on Carolina Environ Study Group/Palmetto Alliance emergency planning contentions Certificate of Svc enci Related correspondence NCGARRY, JM Buke Power Co MCGARRY, JM Bishop, Liberman, Cook, Furcell & Reynolds 84/02/04. 4pp 22130 198 24X Fiche 50-413,84/02/04,8402080164
- 8402090150 Notice of appearance in proceeding Certificate of Svc encl CALVERT, M Duke Power Co CALVERT, M Bishop, Liberman, Cook, Purcell & Reynolds 84/02/06 3pp 22163.142 24X Fiche 50-415,84/02/06,8402090150
- 8402130235 Responses to second round of interropatories re emergency planning Contentions 1,3,6,7,8,9,11,15 & 18 Certificate of Svc encl Related correspondence.
 RILEY, J L Palmetto Alliance RILEY, J L Carolina Environmental Study Group 84/02/06 Duke Power Co 33pp 22200 192 24X
 Fiche 50-413,84/02/06,8402130235
- 8402150178 Forwards listed documents,per 840125 discovery request Related correspondence SHEARIN,R V Duke Fower Co 84/02/07 RILEY,J L Garolina Environmental Study Group 23pp 22249 124 24X Fiche 30-413,84/02/07,8402150178
- B402100125 Proposed findings of Pact & conclusions of law in form of partial initial decision, Vol 1 MOGARRY, J M Duke Power Co CALVERT, M B , MCGARRY, J M Bishop, Liberman, Cook, Purcell & Reynolds B4/02/08 154pp. \$2180.050 24X Fiche 50-413,84/02/08,8402100125
- 8402100145 Proposed findings of fact in form of partial initial decision. Vol II. M/Gertificate of Svc McGARRY. JM Bishop. Liberman. Cook. Purcell & Reynolds MCGARRY. JM Duke Power Co 84/02/08 421pp 22180 204 24X Fiche 50-413.84/02/08.8402100145.
- B402150201 Memorandum & order denying util motion for interlocutory review of admission of revised Palmetta Alliance Contention 11 to proceeding BHOEMAKER, C. J. Atomic Bafety and Licensing Appeal Panel. 84/02/1 Duke Power Co. 3pp 22245 247 24X Fiche 30-413,84/02/14,8402150201.
- 8402160130 Response to 840126 interrogatories re emergency planning contentions Affidavits & Certificate of Syc encl MCGURREN, H J Hearing Branch I 84/02/14 Carolina Environmental Study Group 35pp 22276 005. 24% Fiche: 50-413,84/02/14, 8402160130
- B402160260 Motion for extension of time for filing partial proposed findings from 840222 to 840307 Consolidation will obviate need for cross-referencing Certificate of Syc enci.

 GUILD.R Palmetto Alliance 94/02/14 Atomic 8efg by and Licensing Board Panel 6ρp 22274 325 42X Fiche 50~413,84/02/14, 8402160250
- 8402220842 Forwards HJ McGurren affidavit of nondisclosure, per 840203 telcon. M/p encl Related correspondence.

 JOHNSON: G E Høering Branch 4. 84/02/17, KELLEY, J L. Atomic 8afety and Licensing Board Panel ip 22399 163. 24X Fiche: \$0-413,84/02/17.8402220242
- B40R2R0275 Natifies of occurrences re Transamerica Delaval diesel generators Minor amount of cylinder head leakage & slight crack noted Flaws in welds joining ball to pipe of generator i-A pushrods discovered No matters significant MCOARRY.J M Bishop, Liberman, Cook, Purcell & Reynolds, MCOARRY.J M. Duke Power Co. B4/02/17. KELLEY,J L, FOSTER.R.F., PURDOM.P W Atomic Safety and Licensing Board Panel 2pp. 22337:067 24% Fiche: 50-413, 84/02/17, 8402220275

- B402230070 Memorandum & order on applicant motion to bifurcate emergency planning proceeding KELLEY, J L Atomic Safety and Licensing Board Panel 84/02/3pp 22362 068 24% Fiche 50-413.84/02/21.8402230070 B4/02/21
- 8402280208 Order informing that memorandum of parties on listed questions re referral of oral rollings on intervenors three-part contention on reliability of diesel generators should the filed no later than 840209 SHOEMAKER, C. J. Atomic Bafety and Licensing Appeal Panel 84/02/23 pp. 22400 183 24% Fiche 50-413.84/02/23,8402280208
- 8402280414 Order referring to ASLAB, rulings rejecting two parts of three-part contention re reliability of diesel generators W/o early appellate consideration & coordination of issues, delays & expenses to public could be considerable KELLEY. J L Atomic Safety and Licensing Board Panel 84/02/23 20pp 22403 263 24X Fiche 50-413,84/02/23,8402280414
- 8402270075 Forwards PM Harrison affidavit of nondisclosure re in camera testimony W/o encl JDHN80N.O Hearing Branch 4 84/02/24 KELLEY, J L Atomic Safety and Licensing Board Panel ip 22426 026 24X Fiche 50-413,84/02/24,8402290095
- 8402280358 Memorandum & order admitting ASLB contention re certain diesel generator problems & rejection of two generic contentions re Transamerica Delaval. Inc diesel generators KELLEY, J.L. Atomic Safety and Licensing Board Panel 84/02/27 3pp 22402 277 24X Fiche 50-413,84/02/27,8402280358
- -8402280373 Informs of incidents which have occurred w/respect to one Cylinder head, one or more valve pushrods, one of two turbochargers on engine & fuel oil injection pump nozzle during long-term durability test of diesel generator MCGARRY, J M Bishop, Liberman, Cook, Purcell & Reynolds MCGARRY, J M Palmetto Alliance 84/02/17 KELLEY, J L , FOSTER, R F , PURDOM, P W Atomic Safety and Licensing Board Panel 2pp 22402 281 24X Fiche 50-413,84/02/27,8402280358
- 8402290113 Notice of ASLB constitution MD Margulies, chairman & RM Lazo & FF Hopper members
 COTTEN.B P Atomic Safety and Licensing Board Panel 84/02/27
 2pp 22426:186. 24% Fiche: 50-413,84/02/27,8402290113
- 8402290087 Memorandum & order on scheduling of hearing on emergency planning Hearing to commence in mid-Apr or early-May MARGULIES,M B Atomic Safety and Licensing Board Panel 84/02/28 Office of the Executive Legal Director. 3pp 22428 098 24X Fiche.50-413,84/02/28,840229087

K. Utility Final Bafety Analysis Report (FBAR) & amends

- 8402070310 Amend 30 to application for DLs, consisting of Rev B to FSAR to include deletion of boron injection tenk, revised fuel enrichment & reduced ice weight analysis TUCKER, H B Duke Power Co B401/26 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E. Q Licensing Branch 4 2pp 22097.045. 24X Fichs 50-413, 84/01/26, 8402070310
- --B402070316 Rev 8 to FBAR. W/four oversize drawings Aparture cards are available in FDR # Duke Power Co 84/01/26. 668pp 22097 047 24X 668pp 22097 047 24X Fiche, 50-413, 84/01/26, 8402070310

P. Operating license stage documents & correspondence

- B402010410 Generic Ltr B4-04 to all operating PWR licensess, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Bvc list sncl EIBENHUT, D 0 Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc 59pp 22177:087 24X Fiche.50-000,84/02/01.8402010410
- Q. Inspection reports, IE Bulletins & correspondence
- 8402270301 FOIA request for documents re investigation of allegations raised by welding inspectors at facilities COTTINOHAM.A.M. Debevoise & Liberman 83/08/16, FELTON, J M Division of Rules and Records. ip 22413 001 24X Fiche: 50-413,83/08/16,8402270301
- B402140306 Ack receipt of B40104 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-413/83-46 DANCE, H C. Division of Project & Resident Programs 84/01/17, TUCKER, H B. Duke Power Co. 1p 22221

- --B402140311 Responds to NRC 831206 ltt re violations noted in IE Insp Rept 50-413/83-46 Corrective actions Const Procedure CP-371 revised to add requirements of ANSI N45 2 2 Hanger foremen instructed to take precautions to prevent snubber damage TUCKER.H B Duke Power Co 84/01/04 0'REILLY, JP Region 2, Office of Director 2pp 22221 023 24X Fiche 50-413,84/01/17, 8402140306
- ~-8402140314 Forwards IE Insp Rept 50-413/83-46 on B31114-17 & notice of Violation
 DANCE.H C Division of Project & Resident Programs 83/12/06
 TUCKER,H B Duke Power Co 2pp 22221 025 24X
 Fiche 50-413,84/01/17,8402140306
- ---8402140315 Notice of violation from insp on 831114-17 * Region 2. Office of Director 83/12/06 ip 2 Fiche 50-413, 84/01/17, 8402140306 22221 027 24X
- --8402140320 IE Insp Rept 50-413/83-46 on 831114-17 Violations noted Const Procedure 37% had no provision for requirements of Paragraph 6 3 2:ANSI N45 2 2 & heavy structural matl stored raragraph of 22 Annal N43 22 & Heavy Structural mati stored around & on top of mechanical snubbers ANG, W P Region 2. Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/11/29 App 22221 028 24X Fiche 50-413,84/01/17,8402140306
- B402130246 Forwards IE Insp Rept 50-413/83-54 on B31227-30 No violations or deviations identified DANCE.H C Division of Project & Resident Programs B4/01/19 TUCKER.H B Duke Power Co 2pp 22250 040 24X Fiche 50-413.84/01/19.8402150246
- --8402150253 IE Insp Rept 80-413/83-54 on 831227-30 No violations or deviations identified Major areas inspected integrated hot functional testing reactor protection sys test procedure review, maint procedure program review & plant tour TAYLOR.P A Region 2, Office of Director JAPE.F Division of Engineering & Operational Programs 84/01/16 4pp 22250 042 24X Fiche 50-413.84/01/19,8402150246
- 8402190152 Forwards IE Insp Repts 50-413/84-02 & 50-414/84-02 on B40104-06 No violations or deviations identified DANCE,H C Division of Project & Resident Programs B4/01/20 TUCKER,H B Duke Power Co 2pp 22245 289 24X Fiche 50-413,84/01/20,8402150152
- --8402150157 IE Insp Repts 50-413/84-02 & 50-414/84-02 on 840104-04 No violations or deviations identified Major areas inspected selected monitoring/surveillance stations & status review of preoperational monitoring program CUNNINGHAM,A L Region 2, Office of Director MONTGOMERY,D M Division of Engineering & Operational Programs B4/01/20 4pp 22245 291 24X Fiche 50-413.84/01/20.8402150152
- 840R150236 Forwards IE Insp. Repts 50-413/83-47 & 50-414/83-37 on B31115-16 & 1213-16 No violations or deviations identified DANCE, H C Division of Project & Resident Programs 84/01/20 TUCKER. H B Duke Power Co 1p 2R250 046 24X Fiche 50-413.84/01/20.8402150236
- --8402150256 IE Insp Repts 50-413/B3-47 & 50-414/B3-37 on B31115-16 & 1213-16 No violations or deviations identified Major areas inspected soils & concrete, cable tray installation, structural steel & licenses identified items HUNT; M. D. ; HARRISJ R. Region 2. Diffice of Director CONLON; T E Division of Engineering & Operational Programs B4/01/17 5pp 22250 047 24X Fiche 50-413,84/01/20,8402190236
- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000.84/01/25,8312120153
- 8402140262 Ack receipt of 840113 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/83-40 & 50-414/83-34 50-414/83-36
 EEWIS.R C Division of Project & Resident Programs 64/01/26
 TUCKER.H B Duke Power Co. 1p 22228 301 24X
 Fiche: 50-413.84/01/26.8402140262

--B402140269 Responds to NRC B31201 ltr re violations noted in IE Insp Repts 50-413/83-40 & 50-414/830-34 Corrective actions design drawing revised to incorporate as-built configuration of plates Full compliance will be achieved by B40215 TUCKER, H B. Duke Fower Co B4/01/13 O'REILLY, J P Region 2. Office of Director 5pp 22228 302 24X Fiche 50-413, B4/01/26, B402140262

- --840214028D Advises that response to NRC 831201 ltr re violations noted in IE Insp Repts 50-413/83-40 & 50-414/83-34 will be delayed until 840113 due to schedular interruptions
 TUCKER.H B Duke Power Co 83/12/30 O'REILLY.J P Region 2.
 Defice of Director ip 22228 307 24X Fiche 50-413.84/01/26.
 8402140262
- --8402140286 Forwards IE Insp Repts 30-413/83-40 & 50-414/83-34 on 831101-04 & notice of violation LEWIS.R C Division of Project & Resident Programs 83/12/01 TUCKER.H B Duke Power Co 2pp 22228 308 24X Fiche 50-413,84/01/26,8402140262
- --8402140290 Notice of violation from insp on 831101-04 * Region 2, Office of Director 83/12/01 ip 22228-310 24X Fiche 50~413.84/01/26.8402140262
- --8402140274 IE Insp Repts 50-413/83-40 & 50-414/83-34 on 831101-04 Violation noted failure to follow procedure for hanger installation & insp LIU.W C Region 2. Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/11/22 Spp 22228 311 24X Fiche 50-413.84/01/26,8402140262
- 8402280082 Forwards IE Insp Repts 50-413/84-01 & 50-414/84-01 on 840103-06 No yighations or deviations noted DANCE.H C Division of Project & Resident Programs 84/01/27 TUCKER.H 8 Dake Power Co 2pp 22401 142 24% Fiche.50-413.84/01/27.8402280082
 - 9402280093 IC Insp Repts 50-413/84-01 & 50-414/84-01 on 840103-06 No violations or deviations noted Major areas inspected ansite design activities.10CFR21 insp.verification of as-builte & corrective actions
 JACKSON.H , MCFARLAND.C R , UPRIGHT.C M Region 2, Office of Director 84/01/25 App 22401-144 24X Fiche 50-413,84/01/27,8402280082
- .402280277 Forwards IE Insp Repts 50-413/84-06 & 50-414/84-05 on 840109-13 No violations or deviations identified DANCE, H C Davision of Project & Resident Programs 84/01/30 TUCKER, H B Duke Power Co 2pp 22399 194 24X Fiche 50-413.84/01/30.8402280277
- --B402280285 IE Insp Repts 50-413/84-06 & 50-414/84-05 on 840109-13 No violations or deviations identified Major areas inspected instrumentation components & sys.nonconformance control. GA audits, OA records & trending MERRINEATHER, N Region 2, Office of Director CONLON, T E Division of Engineering & Operational Programs 84/01/26 6pp 22399 198 24X Fiche 50-413,84/01/30,8402280277
 -)2270306 Responds to FOIA request for documents re investigation of illegations raised by welding inspectors at facilities orwards App B documents entirely withheld ref FOIA Exemption 7) Into also available in FDR ELTON.J M Division of Rules and Records 84/02/01 LOTTINGHAM A W Dubevoise & Liberman 6pp 22413 002 24X Fiche 50-413.84/02/01.8802270306
- -8402270312 Discusses allegations re facility GC welding inep Bome degree of record falsification & inspector harrassment occurred No hardware discrepancies identified Region II review requested Related info enci
 VAN DODRN.P K NRC No Detailed Affiliation Given 84/02/01 VORSE, J Y NRC No Detailed Affiliation Given 100pp 22413 008 24X Fiche 50-413.84/02/01.8402270306
- 1402280135 Forwards IE Insp Rept 50-413/84-10 on 840116-19 No violations or deviations noted DANCE:H C. Division of Project & Resident Programs 84/02/01 TUCKER:H B Duke Power to 2pp 22400 306 24x Fiche 50-413,84/02/01.8402280135
- --8402280138 IE Insp Rept 50-413/84-10 on 840116-17 No violations or deviations noted. Major areas inspected training, liquid, gasedus & solid radwaste sys. shielding, new fuel receipt & 10CFR61 compliance preparation WRAY, J R Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 84/01/27. App. 22400 308 24X Fiche 50-413,84/02/01,6402260135
- 3402280003 Forwards IE Insp Rept 50-413/84-08 on 840116-20 No violations or deviations identified DANCE, H C Division of Project & Resident Programs 84/02/07 TUCKER, H B Date Power Co 2pp 22402 120 24X Fiche 50-413,84/02/02,8402280003

- --8402280004 IE Insp Rept 50-413/84-08 on 840116-20 No violations or deviations identified Major areas inspected preoperational test program implementation, preoperational test results evaluation & reactor protection sys
- B402280506 Forwards IE Insp Repts 50-413/84-04 & 50-414/84-04 on B40103-06 No violations or deviations identified DANCE.H C Division of Project & Resident Programs B4/02/02 TUCKER,H B Duke Power Co 2pp 22407 216 24X Fiche 50-413,84/02/02,8402280506
- --8402280516 IE Insp Repts 50-413/84-04 & 50-414/84-04 on 840103-06 No violations or deviations identified Major areas inspected GA program for tests & experiments SMITH.C F Region 2, Office of Director UPRIGHT.C Division of Engineering & Operational Programs 84/01/31 5pp 22407 218 24% Fiche 50-413,84/02/02.8402280506
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BHR Mark I Containment Vent Headers " Svc list encl DEYGUND, R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 156 24X Fichs 50-000,84/02/03,8401190017
- 8402150274 Ack receipt of 831215 & 840123 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/83-34 & 50-414/83-31 DANCE.H C Division of Project & Resident Programs 84/02/06 TUCKER.H B Dute Power Co ip 22242 089 24X Fiche 50-413,84/02/06.8402150274
- --8402150300 Forwards corrected revised response to violations noted in IE Insp Repts 50-413/83-36 & 50-414/83-31 re inadequate QA controls Previous submittal sent w/incorrect attachment TUCKER: H B Doke Power Co 84/01/23 O'REILLLY.J P Region 2. Office of Director 3pp 22242 090 24X Fiche 50-413.84/02/06, 8402150274
- --8402150304 Forwards revised response to violations noted in IE Insp Repts 50-413/83-36 & 50-414/83-31 Corrective actions GA Procedure GA-140 revised to specify that pratical exams administered by Level III examiner TUCKER: H B Duke Power Co 84/01/13 O'REILLY, J P Region 2, Office of Director 2pp 22242 093 24X Fiche 50-413,84/02/06, 8402150274
- --8402150308 Responds to NRC B31115 1tr re violations noted in IE Insp Repts 50-413/83-36 & 50-414/83-31 Corrective actions eye exams will be performed annually & welding procedures separated into ASME & AMB TUCKER.H B Duke Power Co 83/12/15 O'REILLY, J P Region 2. Office of Director 4pp 22242 095 24X Fiche 50-413.84/02/06. 8402150274
- --8402150310 Forwards IE Insp Repts 50-413/83-36 & 50-414/83-31 on 831004-07 & 12-14 & notice of violation LEWIS.R C Division of Project & Resident Programs 83/11/15 TUCKHER.H B Duke Power Co 2pp 22242 099 24X Fiche 50-413,84/02/06,8402150274
- --8402150312 Notice of violation from insp on 831004-07 & 12-14 * Region 2, Office of Director 83/11/15 2pp 22R42.101 24X Fiche 50-413.84/02/06.8402150874
- --B402150315 IE Insp Repts 50-413/83-36 & 50-414/83-31 on 831004-07 & 12-14 Violations noted GC implementing Procedures GCI-2001-CNS, Rev O & GCI-9 001, Rev O contained no provisions for annual eye exams for inspectors

 ECONOMOS N Region 2. Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/11/09 7pp 22242 i03
 24X Fiche 50-413.84/02/06,8402150274
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Bafe Shutdown Sys (10CFR50, App R) " Syc list encl JORBAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 239 24X Fiche, 50-000, 84/02/13, 8401190041
- 840119000 Board Notification 84-021 provides repts of Transamerica Delaval, Inc insps conducted from Mar 1979 to Oct 1983 EISENHUT, D 6 Division of Licensing 84/02/13 PALLADINO Commissioners 3pp 22314 001 24x Fichs 50-000,84/02/13, 8401170050

- 8401170037 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '"
- IO1190037 IE into Notice 3. 05.

 Syc list encl

 JORDAN E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/02/14 Consolidated Edison Co of New

 York, Inc 115pp 22365 141 24X Fiche 50-000, 84/02/14, 8401170039
- 8401190045 IE Info Notice B3-63, Suppl 1, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/15 Consolidated Edison Co of New York, Inc 118pp 22366 142 24% Fiche 50-000,84/02/15,8401190045
- 8401190062 IE Info Notice 84~10, "Motor-Operated Valve Torque Switches Bet Below Manufacturer Recommended Valve "Svc list encl JONDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000,84/02/21,8401190062
- 8401190066 IE Info Natice 84-11. "Training Program Deficiencies " 101190066 IE Info Notice C. ...
 Syc list encl
 JORDAN: E. Division of Emergency Preparadness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000.84/02/24,8401190066
- 8401170047 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals " 101190007 IE INFO NOTICE 8-12. FRITTE ST SUFF SEE SEE VALUE SEEVEL SEEVE

S Reportable occurrences, LERs & related correspondence

- 8402140398 Requests addl info re Part 21 rept dtd 831108 concerning wear ring feilure in auxiliary feedwater pump furnished to facilities. Info requested within 25 days POTAPOUS.U Region 4. Office of Director 83/11/30 PATTY.D F Bingham-Willamette Co 1p 22221 250 24X Fiche 50-000.83/11/30.
- --8402140422 Supplemental Part 21 rept re wear ring failure in auxiliary feedwater pumps, per 831130 request for add1 info Wear rings will be replaced on returned units w/AISI 420 wrought matl List of pumps in similar svc w/same wear ring encl PATTY,D F Bingham-Willamstte Co 83/12/20 Region 4, Office of Director 2pp 22221-251 24X Fiche 50-000,83/11/30, 2402140388
- 8402070365 Part 21 rept re linear converter device w/possible generic defect Initially reported on 840116 Written notifications issued Customer responses should be received by 840331 Final rept will be submitted by 840430 DDDSON, J F Pacific Air Products Co 84/01/30 Director's Office of Inspection and Enforcement 2pp 22114 299. 24X Fiche 50-280,84/01/30,8402070365
- --8402070373 Part 21 rept re linear converter device w/possible generic defect Initially reported on 840116 Preliminary analysis indicates excessive wear of brass shaft guides Next rept will be submitted within 90 days Supporting info encl DOBSON.J P Pacific Air Products Co 84/01/17 POTAPOVS,U Repion 4, Office of Director 68pp 22114 301 24X Fichs 50-000,84/01/30,8402070345
- B402070393 Requests that NRC investigate design reliability of emergency diesel generators supplied by Transamerica Delavel. Inc Engine problems have been experienced since delivery of first vessel in May 1981 Related info encl MOLINA. J. C Falcon Carriers. Inc 84/02/01 DENTON. H Of Nuclear Reactor Regulation, Director 63pp. 22096 057 24X Fiche 50-000,84/02/01,8402070393. Office of
- 8402140230 Interim Bignificant Deficiency Rept BDR 82-07 re replacement of undersize motor operators for Westinghouse valves. Completion delayed until 840401 due to add1 delivery problems.
 TUCKER H B Duke Power Co 84/02/01 D'REILLY, J P Region 2, Dffice of Director 1p 22221 041. 24X Fiche: 50-413, 84/02/01, 8402140230
- 8402150324 Deficiency rept re damaged diesel generator stator iB Rebuilt stator will not be returned to facility site until 840401. Full completion of action will not take place until 840901. Final rept will be submitted by 840401 TUCKER, H. B. Duke Power Co 84/02/02 O'REILLY, J. P. Region 2, Office of Director ip 22250 175. 24X Fiche: 50-413, 84/02/02, 9402182024
- 840119004B Board Notification 84-006 provides info re alleged falsification of QC documents concerning const of safety-related HVAC units by Bahnson Co.Winston-Balem, NC, EIBENHUT, D. Q Division of Licensing 84/02/07. PALLADIND. GILINBKY, ROBERTS Commissioners 7pp 22332 187 24X Fiche: 50-000, 84/02/09, 840119004B

- 8401190053 Board Notification 84-020 forwards info re Transamerica 401190093 Board Notification 84-020 forwards info re Transameri Delaval Inc emergency diesel generator problems Attendance list meeting handouts & slides encl EISENHUT.D O Division of Licensing 84/02/13 PALLADINO Commissioners 102pp 2232 202 24X Fiche 50-000, 84/02/13, 8401170053
- 8402220051 Interim Significant Deficiency Rept SD 413/84-01 re leaking ocception and significant periciency kept \$413/44-of release socket weld in RHR sys Initially reported on B40113 Test procedure to identify vibration problems being developed Next rept expected by B40B13
 TUCKER, H B Duke Power Co B4/02/13 O'REILLY, J P Region 2, Office of Director 3pp 22337 329 24x Fiche 50-413, B4/02/13. TUCKER.H B Duke Power Co 84/02/13 Office of Director 3pp 22337 329 8402220051
- 8402220530 Part 21 rept re defective DSR & DSRV standby diesel generator turbocharger thrust bearing lubrication Deficiency not corrected by sys mod New recommendation will be sent to customers by 840330 BOYER, R & Transamerica Delaval, Inc 84/02/15 Director's Defice. Office of Inspection and Enforcement 5pp 22332 182 Fiche 50-000,84/02/15,8402220530
- 8402290307 Forwards procedures. "Diesel Electric Generating Units" & "Extended Operation Test of Diesel Generator 1A." in response to 831230 request Procurement GA & operational experience u/diesel generators 1A & 1B discussed TUCKER.H B Duke Power Co 84/02/22 DENTON.H R OPFice of Nuclear Reactor Regulation. Director ADENSAM.E O Licensing Branch 4 4pp 82422.064 24X Fiche 50~413.84/08/22.8402270307
- --8402270312 Procedure CNS-i301 00-2, "Diesel Electric Generating Units "
 * Duke Power Co 84/02/07 225pp 22422 068 24%
 Ficho 50-413,84/02/22,8402270307
- --8402270314 Procedure "Extended Operation Test of Diesel Generator 1A" * Duke Power Co 84/02/29 200pp 22422 308 24X Fiche 50-413,84/02/22,8402270307
- 8402280701 Notification of 840308 meeting w/Transamerica Delaval Inc (TDI) Guners Group in Wading River NY to discuss TDI progosed program plan to qualify diseal generators CARUBOR Division of Licensing 84/02/23 BERLINGER C Division of Licensing 2pp 22414 340 24X Fiche 50-000.84/02/23, 8800280701
- T Hearing transcripts on non-antitrust matters
- 8402030340 Transcript of 840130 hearing in Charlotte,NC Pp 11,922-12,257 * Duke Power Ce 84/01/30 338pp 22073 062, 24X Fiche 30-413.84/01/30.8402030340
- 8402030478 Transcript of 840131 hearing in Charlotte,NC Pp 12,260-7721 Atomic Safety and Licensing Board Panel 84/ 966 285 24% Fiche 50-413,84/01/31,8402030478 84/01/31 163nn
- B402080212 Transcript of B40203 telephone conference in Washington DC Pp 12,422-12,505 * Duke Power Co 84/02/03 83pp 22134 105 24X Fiche 50-413,84/02/03,8402080212
- 8402210192 Transcript of 840216 telephone conference in Bethesda, MD Pp 12, 504-12, 535 * Atomic Safety and Licensing Board Panel 84/ 22317 001 24% Fiche 50-413,84/02/16,8402210192 B4/02/1A 31 na
- 8402220577 Transcript of 840217 telephone conference in Bethesda, MD Pp 12, 536-12, 579 * Atomic Safety and Licensing Board Panel 84/02/17 46pp 22331-268 24X Fiche 50-413, 84/02/17, 8402220377

V Operator Examinations

8402130332 Forwards revised pages to FSAR Section 13 2 clarifying various aspects of operator training program.per 840126 meeting w/B Wilson Revised pages will be included in Rev 9 to FSAR to FBAK TUCKER.H B Duke Power Co B4/02/10 O'REILLY,J P Region 2, Office of Director 3pp 22197 114 24X Fiche 50-413,84/02/10, 8402130332

- DOCKET 50-414 CATAWDA NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8402090003 Responds to FOIA request for const completion dates for ACAYOUGS Responds to FDIA request for const completion dat nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Fanel meetings Forwards App A.B & C documents FELTON.J M Division of Rules and Records 63/10/31 RGSENBAUM.D M Technical Analysis Corp 19pp 22193 292 Fiche 50~000.B3/10/31.B402090003 22193 292 24X
- --8402070105 Handwritten notes & calculations re fuel load preparation & const activities

 * NRC - No Detailed Affiliation Given 81/08/13 ip 22194 180
- --8402090107 Handwritten notes & calculations re const & fuel load - No Dotailed Affiliation Given 80/04/2 52 24X Fiche 50-000,83/10/31,8402090003 80/04/23 4pp NRC 22174 162
- --8402090124 Handwritten notes & calculations re facility const Related Info encl # NRC - No Detailed Affiliation Given B3/10/31 PRIP4 200 24X Fiche 50-000,83/10/31,8402090003
- D312120136 Board Notification 84-011 discusses NRC use of terms "important to safety" & "safety-related" EISENDUT. D © Division of Licensing 84/01/18 PALLADING Commissioners 72pp 22241 008 24X Fiche 50-000.84/01/18.
- 8401190012 Board Notification 84-813 forwards info re Transamerica Dulayali Inc emergency diesel generators EISENHUT.D G Division of Licensing 84/01/24 PALLADIND,N Commissioners 10pp 22054 346 24% Fiche 90-000,84/01/24, 0401190012
- 0402060612 Notification of contract execution, Mod 2 to "Radiation Monitoring Program Requirements" Contractor State of SC UMBEL.D Technical Assistance Contracts Branch FIN B-B403 84/01/24 MALEY.R J Region 2, Office of Director MONTOMERY, D M NRC No Detailed Affiliation Given ip 22092-083 24X Fiche 30-413, 84/01/24, 8402040612
- 2070310 Amend 30 to application for DLs, consisting of Rev 8 to FSAR a include deletion of boron injection tank, revised fuel invictment & reduced ice weight analysis
 TUCKER, H B Duke Power Co 84/01/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22097 045 24X
 Fiche 50-413, 84/01/26, 8402070310
- 40119001\$ Board Notification 84-018 provides info re failure experience of Transamerica Delaval emergency diesel penerators in marine svc EIBENHUT, D O Division of Licensing B4/01/27 PALLADING, N J Commissioners 385pp 22093 027 24X Fiche 50-000, 84/01/27, 22093 027
- 102010195 Forwards 840103 rev to License SNM-1920, authorizing possession & use of small amounts of SNM for use as nuclear detecting devices & testing of instruments No action required by ABLO re issuance of license JOHNBON O E Hearing Branch 4 84/01/27 KELLEY, J. Atom Safety and Licensing Board Panel. 21pp 22040 315 24% Fiche 50-413,84/01/27.8402010195
- 1402010410 Generic Ltr B4-04 to all operating PWR licensess, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Bvc list encl EISENHUT. D O Division of Licensing G4/02/01 Consolidated Edison Co of New York, Inc 59pp 22177 087 24X Fiche 50-000, B4/02/01. B402010410
- ORO70181 Forwards add1 info describing design verification & qualification testing for procurement of safety-related equipment in response to Generic Ltr 83-28 Enci info suppls HAI104 response TUCKER, H B Duke Power Co 84/02/02 EISENHUT, D 0 Division of Licensing 5pp 22102 183 24X Fiche 50-413, 84/02/02, 8402070181

- 8402130616 Advises that Class III license fee remitted w/830309 application requesting exemption from requirements of IOCFR50.App E. Section IV F will be refunded Exemption authorized by law & is in public interest MILLER.W D License Fee Management Branch 84/02/03 TURDUKE Paper Co IP 22214 295 24X Fiche 50-000.84/02/03. TUCKER, H R Duke Power Co 8402130616
- 8402100438 Notification of 840207 meeting w/util in Bethesda, MD to discuss util 831118 submittal re arbitrary intermediate oreass JABBOUR,K N Licensing Branch 4 84/02/06 ADENSAM,E G Licen Branch 4 2pp 222/3 041 24X Fiche 50-414,84/02/06,8402/004/8
- 840@100474 Notification of 840@09 meeting w/util.Sandia Natl Lab & EG&G in Bethesda.MD to discuss environ qualification of DG in Bethesda, MD to discuss with a constraint of C'Brien penetrations
 JABBOUR, K N Licensing Branch 4 84/02/06 ADENBAM, E Q Licen
 Penetr 4 2pp 22213 047 24% Fiche 50-413, 84/02/06, 8402100474
- B402170061 Notification of B40210 meeting w/Transamerica Delaval, Inc (TDI) in Bethesda, MD to discuss program plan proposed by TDI Dumers Group to qualify dissel generators GARUSD.R Division of Licensing 84/02/06 BERLINGER, C Division of Licensing 2pp 22312 337 24X Fichs 50-000, B4/02/06, B402170061
- 8402130417 Forwards Procedure AP/1/A/5500/31, "Estimate of Failed Fuel Based on I-131 Concentration," in response to NRC request to complete review of NVREO-0737. Item II B 3 TUCKER.H B Duke Power Co 84/02/07 DENTON.H R Defice of Nuclear Reactor Regulation, Director ADENSAM.E 9 Licensing Branch 4 7pp 22201 281 24X Fiche 50-413,84/02/07.8402130417
- --8402130422 Procedure AP/1/A/5500/31, "Estimate of Failed Fuel Based on I-131 Concentration" * Duke Power Co 84/02/07 Apr 22201 288 24X Fighe 50-413, 84/02/07, 8402130417
- B402130449 Forwards response to Item 9 of B30303 request for add1 info re environ qualification of safety-related electrical equipment, covering containment isolation valves & boric equipment covering containment assument assument actid transfer pumps actid transfer pumps to 84/02/07 DENTON HR Office of TUCKER. HB Duke Power Co 84/02/07 DENTON HR Office of Nuclear Reactor Regulation, Director ADENSAM E 9 Licensing 4 SSpp 22201 303 24% Fiche 50-413,84/02/07,8402130469 Licensing Branch
- 8402090251 Responds to NUREG-0588 demonstrating that electrical equipment required to perform safety-related function in harsh environ appropriately qualified TUCKER.H B Duke Powar Co. 84/02/08 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM, E. G. Licensing Branch 4 294pp 22163 326 24X Fiche 50-413,84/02/08,8402090251
- 8401198089 Board Notification 84-832 provides addl info on environ qualification Submittal augments info in Board Notifications 84-004 & 84-007 EISENHUT, D. G. Division of Licensing 84/02/13 Atomic S // Division of Licensing 84/02/13 Atomic Safety and d Panel 10pp 22314 204 24X Fiche 50-000.84/02/13. Licensing Board Panel 8401170059
- 8402170272 Provides supplemental info supporting 841118 submittal re elimination of arbitrary intermediate pipe breaks, in response to NRC 840207 request W/19 oversize drawings, including one illegible Aperture cards are available in PDR TUCKER.H B Duke Power Co 84/02/15 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM.E O Licensing Bran A 16pp 28296 129 24% Fiche 50-413,84/02/15,8402170272 Licensing Branch
- B401170068 Board Notification 84-033 provides "Bys Interaction Program." task action plan for Unresolved Safety Issue A-17 Distribution list encl EISENHUT. DO Division of Licensing B4/02/16 PALLADINO Commissioners Bpp 224B2 091 24X Fichs 50-000.84/02/16, G401170068
- 8402220364 Advises of plans to perform approved mod on Unit 2 Model D5 steam generators & provides plant-specific details required by NUREO-1014 Mods to Unit i steam generators will be completed prior to fuel loading date of 840501 TUCKER,H B Duke Power Co 84/02/20 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENBANK,G Licensing Branch 4. 7pp 22333 143 24X Fiche 50-413.84/02/20.84022205644.
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8402060077 Informs of actions taken to complete Confirmatory Issue 25 discussed in SER, Bection 7, 3 2 1 Steam generator overfill protection sys installed eliminating issue of single channel failure causing high-high level trip TUCKER, H B Duke Power Co 84/02/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAME, G Licensing Branch 2 2pp 22088 237 24X Fiche, 50-413, 84/02/01, 8402060077

- 8402060087 Responds to SER. Section 4 4 3 4. Open Item & reinstrumentation for inadequate core cooling detection (TMI Item II F 2) Phase i complete Control room displays will be modified upon completion of control room design review TUCKER. H B Date Power Co 84/02/01 DENTON. H R Office of Nuclear Reactor Regulation. Director ADENSAN. E C Licensing Branch 4 10pp 22088 261 24X Fichs 50-413.84/02/01.8402060087
- 8402060273 Forwards revised Section 2 4 2 3 re effect of local intense precipitation for FSAR, in response to SER Confirmatory Item i H/four oversize figures Aperture cards are available in PDR. Matl will be incorporated in Rev 9 to FSAR TUCKER, H B Duke Power Co B4/02/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E 9 Licensing Branch 4 30pp 22083 001 24X Fiche 50-413,84/02/01,8402060273
- B402140470 Forwards inlet & discharge piping info omitted in 831026 1tr in response to SER, Section 3 9 3 2 & NUREO-0737, Item II, D. 1 TUCKER, H B Duke Power Co 84/02/03, DENTON, H R Diffice of Nuclear Reactor Regulation, Director ADENSAM, E Q Licensing Branch 4 3pp 2226 207 24X Fiche 50-413, 84/02/03, 8402140470
- B402130337 Forwards revised response to Question 440 48 of SER, Confirmatory Item 36 re flooding of electrical equipment due to LOCA TUCKER.H B Duke Fower Ca 84/02/07 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM.E G Licensing Branch 4 dpp 22197.120 24X Fiche 50-413,84/02/07,8402130337
- 8402220338 Forwards add1 info needed to complete BER Info includes procedures used to measure value of critical parameters, method of recording & managing data & identification of interpretation of data & sequence in timing TUCKER.H B Duke Power Co 84/02/15 DENTON,H R Office of Nuclear Reactor Regulation, Director, ADENSAM.E Q Licensing Branch 4 3pp 22331 001 24X Fiche 50-413,84/02/15,8402220538
- ---8402220539 Change 1 to Procedure CP/D/A/8100/01, "Chemistry Procedure for Determination of pH" EVANS, L D , CHAUBT, R H , TUCKMAN. M S Duke Power Ca 80/07/18 2pp. 22331 004 24X Fiche. 80-413,84/02/15,8402220538
- --B402220542 Change O to Procedure CP/O/A/BiOO/42, "Chemistry Procedure for Determination of Chloride Belective Ion Electrode " BOLIN, C W., PAINTER, R L., COX, J W Duke Power Co B3/11/11 12pp. 22331 097 24X Fiche 50-413, 84/02/19, 840220538.
- --8402220546 Change O to Procedure CP/O/A/8100/O1, "Chemistry Procedure for Determination of pH"
 CHAUBT,R H , EVANS,L D , COX,J W Duke Power Co 80/O1/28. 18pp 22331 006 24% Fishe 50-413.84/O2/15.8402220538
- ---8402220547 Change O to Procedure CP/O/b/Bi50/03, "Chemistry Procedure for Determination of Sodium Auto Analyzer" pICKEY, C., EVANS, L. D., TUCKMAN, M 8 Duke Power Co 83/05/12 17pp. 2231:109 24X Fiche 50-413,84/02/15,8402220538.
- ---8402220548 Change O to Procedure CP/0/B/8100/17, "Chemistry Procedure or Determination of Hydraxine"
 DIGKEY, C B, EVANS, L, D, TUCKMAN, M B Duke Power Co 83/09/30
 7pp. 2231:024 24X Fiche: 50-413,84/02/15,8402220538
- ---8402220549 Change O to Procedure CP/O/B/8100/52, "Chemistry Procedure for Determination of Sodium - Furnace AA " FAINTER, R L , EVANS, L D , COX, J W. Duke Power Co 83/11/14 9pp 22331:126 24X Fiche: 50-41d: 84/02/15
- ---BAGG2220552 Change 1 to Procedure CP/O/B150/05, "Chemistry Procedure for Determination of Hydnaithe.Auto-Analyzer" BOLIN.C W , EVANS.L D , TUCKMAN.M B Duke Power Co B3/10/RO SPP 22331.031 24X Fiche.50-413,84/02/15,8402280538
- --8402220554 Change O to Procedure CP/0/B/B150/04, "Chemistry Procedure for Determination of Dissolved Daygen Auto Analyzer "PAINTER,R L., EVANS,L D., TUCKMAN, M & Duke Power Co 82/12/11 12pp 22331 135, 24X Fiche 50-413,84/02/15,8402220538
- --B402220555 Change O to Procedure CP/O/B/B150/O5, "Chemistry Procedure for Detarmination of Hydrazine, Auto-Analyzer,"
 PAINTER.R.L. 1, EVANS.L.D., TUCKMAN.M.S. Duke Power Co 82/11/18
 6pp 22331.033 24X Fiche 50-413.84/02/15.8402220538.
- --8402220560 Change O to Procedure CP/D/B/8150/02, "Chemistry Procedure for Determination of Conductivity, Auto-Analyser,"
 DICKEY,C S., PAINTER,R,L., TUCKMAN,M. 8 Duke Power Co. 82/11/17
 9pp. 22331:039 24X Fiche 50-413.84/02/15.8402220538.

- --8402220361 Change O to Procedure CP/O/A/8100/[1. "Chemistry Procedure for Determination of Dissolved Oxygen " CHAUST,R R. EVANS,L D., TUCKHAN,M S. Duke Power Co. 79/08/14 14pp 22331 147 24X Fiche 50-413,84/02/15,8402220538
- --8402220563 Change 1 to Procedure CP/D/8/8100/02, "Chemistry Procedure for Determination of Specific Conductivity " BOLIN.C., PAINTER, R. L., TUCKMAN, M. S. Duke Power Co. 82/11/16 7pp 22331 048 24X Fiche 50-413,840/22/15,8402220538
- --8402220566 Change O to Procedure CP/D/D/B100/07, "Chemistry Procedure for Determination of Suspended Solids Millipore Filters " PAINTER.R L , EVANS,L D . TUCKMAN.M S Duke Power Co 83/07/15 ilpp 22031 161 24X Fiche 30-413.84/02/15.8402220538
- --8402220567 Change A to Procedure CP/D/A/Bi00/05, "Chemistry Procedure for Determination of Chlonide (Manual Method)" MCNEILL.B , CHAUST.R H , COX, J H Duke Power Co 84/01/06 1p 22331 057 24X Fiche 50-413,84/02/15,8402220538
- --8402220572 Change 4 to Procedure CP/O/A/8100/05, "Chemistry Procedure for Determination of Chlorade (Manual Method)" MCNEILL,B . EVANS,L D . COX.J W Duke Power Ce 83/12/30 3pp 22331 058 24X Fiche 50-413,84/02/15,8402220538
- ---8402220573 Change 2 to Procedure CP/O/B/B100/OB, "Chemistry Procedure for Determination of Silica (Manual Method)"
 BOLIN, C W , CHAUST, R H , TUCKMAN, M S Duke Pawer Co 82/06/29
 3pp 22331 172 24% Fiche 50-413,84/02/15,8402220538
- --B402220575 Change O to Procedure CP/O/B/B100/13, "Chemistry Procedure for Determination of Copper - Furnace AA" PAINTER,R L , EVAN9,L D , COX,J W Duke Power Co 83/11/14 9pp 22331 212 24X Fiche 50-413,84/02/15,8402220538
- --8402220579 Change 3 to Procedure CP/D/A/Bi00/05, "Chemistry Procedure for Determination of Chloride (Memual Method)" PAINTER,R L , EVANS.L D . TUCKMAN:M S Duke Power Co 83/05/31 ip 22331 061 24% Fiche 50-413.84/02/15
- --B402220580 Change 1 to Procedure CP/0/B/8800/05, "Chemistry Procedure For Recording & Mgt of Data " PAINTER,R L . EVANS,L D . COX.J W Duke Power Co 83/12/29 1p R2331.221 24X Fiche 50-413.64/02/15.8402220838
- --B402220581 Change O to Procedure CP/O/B/8100/08, "Chemistry Procedure for Determination of Silica (Manual Method) " PAINTER,R L., EVANS,L D., TUCKMAN.M S. Duke Power Co. 82/05/28 11pp. 22331 175 24X Fiche 50-413,84/02/15,8402220538
- --8402220583 Change 2 to Procedure CP/D/A/8100/05. "Chemistry Procedure for Determination of Chloride (Manual Method)" MCAFEE, C. CHAUST, R. H.: TUCKMAN, M.S. Duke Power Co. 82/12/03 2pp. 22331.062 24% Fiche 50-413.84/02/15.8402220538
- --8402220885 Change O to Procedure CP/D/B/8800/05, "Chemistry Procedure for Recording & Mgt of Data" PAINTER,R L . EVANB,L D . TUCKMAN:M S Duke Power Co 89/11/07 42pp 22331. 222 24X Fiche: 50-413: 84/02/15: 8402220538
- --8402220587 Change 0 to Procedure CP/0/B/8100/51, "Chemistry Procedure for Determination of Iron - Furnace AA " PAINTER,R L , EVANS,L D , COX,J W Duke Power Ca 83/11/14. 9pp 22331 186 24X Fiche 50-416,84/02/15,840220538
- --B4022205BB Change 1 to Procedure CP/0/A/B100/05, "Chemistry Procedure for Determination of Chloride (Manual Mathod)"
 PAINTER,R L, CHAUST,R H, TUCKMAN,M S Duke Power Co 81/02/25
 2pp 22331 064 24% Fiche 50-413,84/02/15,840222053B
- --8402220590 Procedure AP/U/B/5500/34, "Abnormal Procedure for Secondary Chemistry Parameters Dut of Spec " * Duke Power Co 84/02/15 4pp 22331 264 24X Fiche. 50-413.84/02/15.8402220538
- ---8402220591 Change O to Procedure CP/O/A/8100/05. "Chemistry Procedure for Determination of Chioride (Manual Method)" CHAUST, R.H., EVANS.L.D., COX.J. W. Duke Power Co. 80/06/27, 19pp 22331 066 24% Fiche 50-413.84/02/15.8402220538
- ---8402220593 Change 0 to Procedure CP/0/8/8100/20, "Chemistry Procedure for Determination of Ammonia" BOLIN, C. N., EVANB, L. D., TUCKMAN, M.S. Duke Power Co. B3/10/06 17pp 22331 195 24% Fiche 50-413,84/02/15.8402220538
- --8402220594 Change I to Procedure CP/D/A/8150/07. "Chemistry Procedure for Determination of Chloride Auto-Analyzer." CRISP.A.: CHAUST.R H . COX.J W. Duke Power Co 83/12/06 lp. 22331 085 24X Fiche: 50-413.84/02/15.840220538

- --B402220595 Change O to Procedure CP/O/A/B150/O7. "Chemistry Procedure for Determination of Chloride - Auto-Analyzer " BOLIN. C W. PAINTER.R L., COX.J W Duke Power Co 82/07/29 11pp 22331 086 24X Fiche 30-413.84/02/15.8402220538
- 8402220359 Forwards description of reactor coolant pump motor oil collection sys,per Section 9 5 1 of SER which discusses Open Item 14. "Fire Protection Program" W/one oversize drawing Aperture card is available in PDR TUCKER,H B Dute Power Co 84/02/20 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 Jpp 22337 151 24X Fishs 50-413,84/02/20.8402220359
- 8402220385 Forwards revised historical earthquake data implementation schedule.per Section 18 2 of SER Open Item 18. "Control Roum Design Review" Implementation of identified historical earthquake data solutions acceptable TUCKER.H B Duke Power Co 84/02/20 DENTON.H R Office of Nuclear Reactor Regulation. Director ADENSAM,E 0 Licensing Branch 4 8pp. 22335 270 24X Fiche 50-413.84/02/20.8402220385
- F Security, medical, emergency & fire protection plans
- 8402010243 Forwards comments on public info brochure & fire protection site audit summary Applicant should verify that fire protection program will be completed by fuel load Response requested by 840221

 ADENSAM, E 0 Licensing Branch 4 84/01/20 TUCKER, H B Duke Power Co 10pp 22047 309 24X Fiche 50-413,84/01/20,8402010243
 - 2070323 Forwards Rev 3 to util response to Suppl 1 to NUREG-0737 arrecting Section I re physical changes. Section II re urface enhancements to Page 6-7 re emergency procedure raining JUCKER, H B Duke Power Co. 84/01/30 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ADENSAM, E. Q. Licansing Branch 4 6pp 22160 252 24X Fiche 50-413,84/01/30,8402070323.
- #402060100 Forwards revised response to FSAR Question 430 91 re seismic qualification status of temp detectors in diesel room first protection sys Detectors seismically qualified by Myle Labs TUCKER.H B Duke Power Co 84/02/02 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E 0 Licensing Branch 4 3pp 22087 180 24% Fiche 50-413.84/02/02.8402060100.
- 8402130409 Forwards response to NRC fire protection site audit summary for facility TUCKER.H B Duke Power Co 84/02/10 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENBAM,E 0 Licensing Branch 4 10pp 22203 259 24% Ficha 50-413.84/02/10.8402130409.
 - 02220359 Forwards description of reactor coolant pump motor oil collection sys.per Section 9 5.1 of SER which discusses Jpsn Item 14. "Fire Protection Program " Myone oversize frewing Aperture card is available in PDR TUCKER.H B Duke Power Co 84/02/20 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 22337 151. 24X Fiche 50-413,84/02/20,8402220359
- 102240085 Forwards response to questions re vital areas/equipment identification Response withheld (ref 10CFR73 21)
 TUCKER-H B Duke Power Co. 84/02/20 DENTON,H R. Office of Nuclear Reactor Regulation, Director 2pp 22375 010 24X
 Fiche 50-413,84/02/20,840224085

Adjudicatory correspondence

- 402010195 Forwards 840103 rev to License SNM-1920, authorizing possession & use of small amounts of SNM for use as nuclear detecting devices & testing of instruments No action required by ASLB re issuance of license JOHNSON, O E Hearing Branch 4 84/01/27. KELLEY, JL , PURDOM, PW , FOSTER, FF Akonic Safety and Licensing Board Panel 21pp 22040 315 24X Fiche 50-413,84/01/27.8402010195
- 3402010249 Requests that 8 Perry of FEMA be placed on proceeding syclist
 JOHNSON, G E Hearing Branch 4 84/01/27 KELLEY, J. L., FOSTER, R F
 Atomic Safety and Licensing Board Panel ip 22041 360, 24X
 Fiche 50-413, 84/01/27, 8402010249
- 1402070046 Response opposing applicant 840112 petition for directed certification & reversal of ASLB admission of Contention II re emergency planning zone Certificate of Svc encl.
 JOHNSON, G E Hearing Branch 4 84/02/01, Atomic Safety and Licansing Appeal Panel 14pp 22103 011 24X Fiche 50-413.
 84/02/01,8402070046
- B402040204 Request to all parties to add S Perry to syc list KELLEY, J L Atomic Safety and Licensing Board Panel, 84/02/02 ig 22087 141 24X Fiche 30-413,84/02/02,8402040204

- B402080171 Continues B40131 discussion on whether applicant provided Palmetto Alliance & Carolina Environ Study Group w/copies of control room design review Certificate of Svc encl MCGARRY.J M Bishop. Liberman, Cook, Purcell & Reynolds MCGARRY.J M Duke Power Co B4/02/02 KELLEY.J L, PURDOM.P W, FOSTER.R F Atomic Eafety and Licensing Board Panel 4pp 22128 246 24X Fiche 50-413.84/02/02.8402080171
- B402080203 Response opposing applicant motion to bifurcate hearing re emergency plan contentions Bifureation would inhibit development of adequate record on emergency plan issues Affirmation of Svc encl RILEY, J L Government Accountability Project B4/02/02 Atomic Safety and Licensing Board Panel 7pp 22130 155 24X Fiche 50-413,84/02/02.8402080203
- 8402070153 Affidavít of MF Lowe in response to W Owen 840118 affidavít re delay of fuel load & testing activíties Certificate of Svc encl LGME: M F Palmetto Alliance 84/02/03 4pp 22103 042 24X Fiche 50-413.84/02/03.8402070153
- B40214015B Forwards intervenors interrogatories in proceeding W/o encl MCGURREN.H J Hearing Branch 1 84/02/03 PERRY, 8 Affiliation Not Assigned 1p 22219 243 24% Fiche 50-413,84/02/03,840214015B
- 8402080164 Notice of intent to take deposition of JL Riley on 840208 re future administrative hearings on Carolina Environ Study Group/Palmetto Alliance emergency planning contentions Cartificate of Syc enci Related correspondence MCGARRY, J M Duke Power Co MCGARRY, J M. Bishop, Liberman, Cook, Purcell & Reynolds 84/02/04 4pp 22130-178 24X Fiche 50-413.84/02/04.8402080164
- B402090150 Notice of appearance in proceeding Certificate of Bvc encl CALVERT.M Duke Power Co CALVERT.M Bishop, Liberman, Cook, Purcell & Reynolds 84/02/06 3pp 22163 142 24X Fiche 50-413,84/02/06.8402090150
- 8402130235 Responses to second round of interrogatories re emergency planning Contentions 1,3,6,7,8,9,11,15 & 18 Certificate of Svc encl Related correspondence RILEY, J L Palmetto Alliance RILEY, J L Caroline Environmental Study Group 84/02/06 Duke Power Ca 33pp. 22200;192, 24% Fichs. 50-413,84/02/06.8402130235
- 840215017B Forwards listed documents, per 840125 discovery request Related correspondence BHEARIN,R V Duke Power Co 84/02/07 RILEY, J. L. Caroline Environmental Study Group 23pp 22249 124 24X Fiche 50-413,84/02/07.840215017B
- B402100125 Proposed findings of fact & conclusions of law in form of partial initial decision, Vol 1 MCGARRY, J M Duke Power Co CALVERT, M B, MCGARRY, J M, Bishop, Liberman, Cook, Purcell & Reynolds 84/02/08 154pp 22180.050. 24X Fichs: 50-413,84/02/08,8402100125
- B402100145 Proposed findings of fact in form of partial initial decision, Vol II. W/Certificate of Svc McGARRY, J M Bishop, Liberman, Cook, Purcell & Reynolds McGARRY, J M Buke Fower Co 84/02/08 42ipp 22180 204, 24X Fiche 50-413,84/02/08,8402100145
- 8402150201 Memorandum & order denying util motion for interlocutory review of admission of revised Palmetto Alliance Contention 11 to proceeding SHCEMAKER, C. J. Atomic Safety and Licensing Appeal Panel, 84/02/14 Duke Power Co. 3pp. 22245 247. 24X Fiche 50-413,84/02/14,840218021
- 8402160130 Response to 840126 interrogatories re emergency planning contentions Affidavits & Certificate of Syc encl MCGURREN.H.J Hearing Branch 1. 84/02/14 Carolina Environmental Btudy Group 35pp. 22276 005. 24X Fiche 50-413,84/02/14, B402160130.
- 8402140260 Matian for extension of time for filing partial proposed findings from 840222 to 840307 Consolidation will obviate need for cross-referencing Certificate of Bvc encl GUILD: R Palmetto Alliance. 84/02/14. Atomic Safety and Licensing Board Panel 6pp 22274 325 24X Fiche: 50-413.84/02/14. 8402160260.
- B402220242 Forwards HJ McGurren affidavit of nondisclosure, per 840203 telcon W/o encl. Related correspondence
 JOHNBON: G E Hearing Branch 4. 84/02/17 KELLEY, J L Atomic
 Bafety and Licensing Board Panel. 1p. 22339 163. 24X
 Fiche: 50-413:84/02/17,8402220242

- 8402220279 Notifies of occurrences re Trensamerica Delaval diesel generators Minor amount of cylinder head leakage & slight crack noted Flaws in welds joining ball to pipe of generator I-A pushrods discovered No matters significant MCGARRY.J M Dishop, Liberman, Cook, Purcell & Reynolds MCGARRY.J M Duke Power Co 84/02/17 KELLEY,J L., FOSTER,R F., PURDDM,P W Atomic Safety and Licensing Board Panel 2pp 22337 067 24X Fiche 50-413.84/02/17.8402220275
- B402230070 Memorandum & order on applicant motion to bifurcate smergency planning proceeding XELLEY, J L Atomic Safety and Licensing Board Panel B4/02/2 5pg 22362 068 24% Fiche 50-413,84/02/21,8402230070
- EA02280208 Order informing that memorandum of parties on listed questions re referral of oral rulings on intervenors three-part contention on reliability of diesel generators should be filed no later than 840307 SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel 84/02/23 2pp 22400 183 24X Fiche 50-413,84/02/23,8402280208
- 8402280414 Order referring to ASLAB, rulings rejecting two parts of three-part contention re reliability of diesel generators W/o early appellate consideration & coordination of issues, delays & expenses to public could be considerable KELLEY, J. L. Atomic Safety and Licensing Board Panel 84/02/23 20pp 22403 263 24X Fiche 50-413,84/02/23,8402280414
- 8402290075 Forwards PM Harrison affidavit of nondisclosure re in camera testimony W/o encl
 JOHNSON, 0 Hearing Branch 4 84/02/24 KELLEY, J L. Atomic Safety and Licensing Board Panel 1p 22426 026 24X
 Fiche 50-413,84/02/24,8402290075
- E402280358 Memorandum & order admitting ASLB contention re certain diesel generator problems & rejection of two generic contentions re Transamerica Delaval.Inc diesel generators KELLEY, J.L. Atomic Safety and Licensing Board Panel 84/02/27 Jpp 22402 277 24x Fiche 50-413,84/02/27,8402280358
- --8402280373 Informs of incidents which have occurred w/respect to one cylinder head, one or more valve pushrods, one of two turbochargers on engine & fuel oil injection pump nozzle during long-term durability test of diesel generator MCGARRY, J M Bishop, Liberman, Cook, Purcell & Reynolds MCGARRY, J M Palmetto Alliance 84/02/17 KELLEY, J L , FOSTER, R F , PURDOM, P W Atomic Safety and Licensing Board Panel 29p 22402 281 24X Fiche 50-413,84/02/27,8402280358
- 8402270113 Notice of ASLB constitution MB Margulies, chairman & RM Laro & FF Hooper, members COTTER, B P Atomic Safety and Licensing Board Panel 84/02/27 2pg 22426 186 24X Fiche 80-413,84/02/27,8402290113
- B402290087 Memorandum & order on scheduling of hearing on emergency planning Hearing to commence in mid-Apr or serly-May MARQULIES, M B Atomic Safety and Licensing Board Panel 84/02/28 Office of the Executive Legal Director 3pp 22428 098 24X Fiche 50-413.84/02/28,8402290087
- K Utility Final Bafety Analysis Report (FBAR) & amends
- 8402070310 Amend 30 to application for OLs, consisting of Rev B to FBAR to include deletion of boron injection tank, revised fuel enrichment & reduced ice weight analysis

 TUCKER, H. B Duke Power Co 84/01/26 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E Q Licensing Branch 4 2pp 22097 045 24X Fiche 50-413, 84/01/26, 8402070310
- --8402070316 Rev 8 to FSAR W/four oversize drawings Aperture cards are available in PDR * Duke Power Ca 84/01/26 668pp 22097 047 24X Fiche 50-413,84/01/26,8402070310
- O Inspection reports, IE Bulletins & correspondence
- B402270301 FOIA request for documents re investigation of allegations raised by welding inspectors at facilities COTTINGHAMA A Debevoise & Liberman B3/0B/16, FELTON, J. H Division of Rules and Records ip 22413,001 24X Fiche, 50-413,83/0B/16,8402270301
- 8402140207 Ack receipt of 831215 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-414/83-16 DANCE: H C. Division of Project & Resident Programs 84/01/17 TUCKER: H B Duke Power Co ip 22230.001 24X Fiche 50-414,84/01/17,8402140207

- --8402140216 Responds to NRC B30811 ltr re violations noted in IE Insp Rept 30-414/83-16 Random analysis of past M-2As conducted Errors led to discovery of one area outside original parameter Requests add 90 days to perform investigation TUCKER.H B Duke Power Co B3/12/15 O'REILLY, J P Region 2, Office of Director 1p 22230 002 24X Fiche 50-414.84/01/17, B402140207
- 8402150152 Forwards IE Insp Repts 90-413/84-02 & 90-414/84-02 on 840104-06 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/01/20 TUCKER.H B Duke Power Co 2pp 22245 269 24X Fiche 50-413.84/01/20.8402150152
- --8402150137 IE Insp Repts 50-413/84-02 & 50-414/84-02 on 840104-06 No violations or deviations identified Major areas inspected selected monitoring/surveillance stations & status review of preoperational monitoring program CUNNINGHAM.A L Region 2. Office of Director MONTGOMERY, D M Division of Engineering & Operational Programs 84/01/20 4pp 22245 271 24X Fiche 50-413,84/01/20,8402150132
- B402150236 Forwards IE Insp Repts 50-413/83-47 & 50-414/83-37 on 831115-16 % 1213-16 No violations or deviations identified DANCE,H C Division of Project & Resident Programs B4/01/20 TUCKER,H B Duke Power Co ip 22250 046 24% Fichs 50-413.84/01/20.8402150236
- --8402150256 IE Insp Repts 50-413/83-47 % 50-414/83-37 on 831115-16 % 1213-16 No violations or deviations identified Major areas inspected soils & concrete, cable tray installation, structural steel & licensee identified items HUNT: M D . HARRIS, J R Region 2. Office of Director CONLON, T E Division of Engineering & Operational Programs 84/01/17 5pp 22250 047 24X Fiche 50-413.84/01/20.8402150236
- B312120193 IE Info Notice B4-06, "Steam Binding of Auxiliary Feedwater Pumps" Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 630103) B4/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120153
- 8402140262 Ack receipt of 840113 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/83-40 & 50-414/83-34 LEMIS.R C Division of Project & Resident Programs 84/01/26 TUCKER.H B Duke Power Co ip 22228 301 24X Fichs 50-413,84/01/26.8402140262
- --B402140269 Responds to NRC B31201 ltr re violations noted in 1E Insp Repts 50-413/83-40 & 50-414/830-34 Corrective actions design drawing revised to incorporate as-built configuration of plates Full compliance will be achieved by B40215 TUCKER.H B Duke Power Co 84/01/13 O'REILLY, J.P. Region 2, Office of Director Spp 22288 302 24X Fiche 50-413,84/01/26, 8402140262
- --B402140280 Advises that response to NRC B31201 ltr re violations noted in IE Insp Repts 50-413/83-40 & 50-414/83-34 will be delayed until 840113 due to schedular interruptions TUCKER, H B Duke Power Co 83/12/30 0'REILLY, J P Region 2, Office of Director ip 2228 307 24X Fiche 50-413,84/01/26, ganglanger.
- --8402140286 Forwards IE Insp Repts 50-413/83-40 & 50-414/83-34 on 831101-04 & notice of violation LEWIB.R C Division of Project & Resident Programs 83/12/01 TUCKER.H B Duke Power Co 2pp 22228 308 24X Fiche 50-413,84/01/26,8402140262
- ~-B402140274 IE Insp Repts 50-413/83-40 & 50-414/83-34 on B31101-04 Violation noted failure to follow procedure for hanger installation & insp LIU.W C Region 2. Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/11/22, 5pp 22228 311 24X Fiche 50-413,84/01/26,8402140262
- 8402280082 Forwards IE Insp Repts 50-413/84-01 & 50-414/84-01 on 840103-06 No violations or deviations noted DANCE,H C Division of Project & Resident Programs 84/01/27 TUCKER,H B Duke Power Co 2pp 22401 142 24X Fiche,50-413,84/01/27,8402280082

- 402280277 Forwards IE Insp Repts 50-413/84-06 & 50-414/84-05 on 840109-13 No violations or deviations identified DANCE, H C Division of Project & Resident Programs 84/01/30 TUCKER, H B Suke Power Co 2pp 22399 196 24X Ficha 30-413,84/01/30,8402280277
- -8402280285 IE Insp Repts 50-413/84-06 & 50-414/84-05 on 840109-13 No violations or deviations identified Major areas inspected instrumentation components & sys.πonconformance control. GA audits OA records & trending MERRIWEATHER.N Region 2. Office of Director CONLON, T E Division of Engineering & Operational Programs 84/01/26 App 22379 198 24X Fiche 50-413,84/01/30.8402280277
- 402270306 Responds to FOIA request for documents re investigation of allegations raised by welding (aspectors at facilities Forwards App A documents App B documents entirely withheld (ref FOIA Exemption 7) Info also available in PDR FELTON, J M Division of Rules and Records 84/02/01 COTTINGNAM, A W Debevoise & Liberman 6pp 22413 002 24% Fiche 80-413,84/02/01,8402270306
- -8402270312 Discusses allegations re facility QC welding insp Some degree of record falsification & inspector harrassment occurred No hardware discrepancies identified Region II review requested Related info encl
 VAN DUORN.P K NRC No Detailed Affiliation Given 84/02/01
 VORSES.J Y NRC No Detailed Affiliation Given 100pp
 22413 008 24X Fiche 50-413,84/02/01.8402270306
- 402280506 Forwards IE Insp Repts 50-413/84-04 & 50-414/84-04 on 840103-06 No violations or deviations identified DANCE:HC Division of Project & Resident Programs 84/02/02 TUCKER:HB Duke Power Ca 2pp 22407 216 24% Fiche 50-413.84/02/02.8402280506
- -8402280316 IE Insp Repts 50-413/84-04 & 50-414/84-04 on 840103-06 No violations or deviations identified Major areas inspected GA program for tests & experiments SMITH.C F. Region 2. Office of Director UPRIGHT, C Division of Engineering & Operational Programs 84/01/31 Spp 22407 218 24X Fiche 50-413,84/02/02,8402280306
- A01190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 80103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000.84/02/03,8401190016
-)1190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent teaders " Svc list encl)EVOUNO.R C Director's Office, Office of Inspection and nforcement 84/02/03 Consolidated Edison Co of New York, Inc 02pp 22177 156 24X Fiche.50-000.84/02/03.8401190017
- 02150274 Ack receipt of 831215 & 840123 ltrs informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-413/83-36 & 50-414/83-31 DANCE,H C Division of Project & Resident Programs 84/02/06 TUGKER,H D Duke Power Co 1p 22242 087 24X Fiche 50-413,84/02/06,8402:50274
- 8402150300 Forwards corrected revised response to violations noted in IE Insp Repts 50-413/83-36 & 50-414/83-31 re inadequate QA controls Previous submittal sent w/incorrect attachment TUCKER, H B Duke Power Co 84/01/23 0'REILLLY, J. P Region 2, Office of Director 3pp 22242 090 24X Fiche 50-413,84/02/06,8402150274
- -8402150304 Forwards revised response to violations noted in IE Insp Repts 50-413/83-36 & 50-414/83-31 Corrective actions: 9A Procedure 0A-140 revised to specify that pratical exams administered by Level III examiner TUCKER: H B Dute Power Co 84/01/13 O'REILLY, J P Region 2, Office of Director 2pp 22242.093 24X Fiche 50-413,84/02/06, 8402150274
- -8402150308 Responds to NRC 83i115 ltr re violations noted in IE Insp Repts 90-413/83-36 & 50-414/83-31 Corrective actions eye exams will be performed annually & welding procedures separated into ASME & AMS TUCKER, H B Duke Power Co. 83/12/15 O'REILLY, J P Region 2, Office of Director 4pp. 22242 075 24X Fiche 50-413,84/02/06, 8402150274
- -8402130310 Forwards IE Insp Repts 50-413/83-36 & 50-414/83-31 on 831004-07 & 12-14 & notice of violation LEWISLR C Division of Project & Resident Programs B3/11/15 TUCKHERLH B Duke Power Co. 2pp 22242 099 24X Fiche 50-413.84/02/06.8402130274

- --8402130312 Notice of violation from insp on 831004-07 & 12-14 * Region 2, Office of Director 83/11/15 2pp 22242 101 249 Fiche 50-413,84/02/04.8402150274
- --B402150315 IE Insp Repts 50-413/83-36 & 50-414/83-31 on 831004-07 & 12-14 Violations noted QC implementing Procedures GCI-2001-CNS, Rev 0 & GCI-9 001.Rev 0 contained no provisions for annual eye exams for inspectors
 ECONDMOS.N Repion 2. Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/11/07 7pp 22242 103 24X Fishe 50-413.84/02/06.8402150274
- B401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR90, App R) " Svc list encl JGRDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 257 24X Fiche 50-000,84/02/13,8401190041
- 8401190050 Board Notification 84-021 provides repts of Transamerica Delaval.Inc insps conducted from Mar 1979 to Oct 1983 EISENNUT.D 0 Division of Licensing 84/02/13 PALLADIND Commissioners 5pp 22314 001 24X Fiche 50-000,84/02/13, 8401190050
- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '" Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/14 Consolidated Edison Co of New York, Inc 115pp 22365:141 24X Fiche 50-000,84/02/14,8401190039
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Westinghouse Type 8A-1 Differential Relays" Svc list and JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366 142 24X Fiche 50-000.84/02/15.8401190045
- B401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Sat Belpt Manufacturer Recommended Valve " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000.84/02/21.8401190062
- B401170066 IE Info Notice 84-tl, "Training Program Deficiencies"
 Svc list enc1
 JORDAN,E L Division of Emergency Proparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430.304 24% Fiche 50-000.84/02/24.8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "

 Bvc list encl

 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co. of New
 York, Inc 120pp 22431.060 24X Fiche 50-000.84/02/27.8401190067
- B Reportable occurrences. LERs & related correspondence
- 8402140398 Requests add1 info re Part 21 rept dtd 831108 concerning wear ring failure in auxiliary feedwater pump furnished to facilities info requested within 25 days POTAFOVB, U Region 4. Office of Director 83/11/30 PATTY, DF Bingham-Willamette Co 1p 22221 250 24X Fiche 50-000, 63/11/30, 8402140398
- --8402140422 Supplemental Part 21 rept re wear ring failure in auxiliary feedwater pumps.per 831130 request for add1 info Wear rings will be replaced on returned units w/AISI 420 wrought matl List of pumps in similar svc w/same wear ring encl PATTY.DF Bingham-Willamette Co. 83/12/20 Region 4, Office of Director 2pp 22221 251 24X Fiche 50-000,83/11/30, 8402140398
- 8402070365 Part 21 rept re linear converter device w/possible generic defect Initially reported on 840116 Written notifications issued Customer responses should be received by 840331 Final rept will be submitted by 840430 DDBBON.J.P. Pacific Air Products Co 84/01/30 Director's Office Office of Inspection and Enforcement 2pp 22114 279 24X Fiche 50-280.84/01/30.8402070365
- ---B402070373 Part 21 rept re linear converter device w/possible generic defect. Initially reported on 840116. Preliminary analysis indicates excessive wear of brass shaft guides Next rept will be submitted within 90 days Supporting info encl.

 DODBON.J P Pacific Air Products Co 84/01/17 POTAPOVS.U.

 Region 4. Defice of Director 68pp 22114 301 24X

 Fichs 50-000, 84/01/30.8402070345

- 8402070393 Requests that NRC investigate design reliability of emergency diesel generators supplied by Transamerica Delawal.Inc Engine problems have been experienced since delivery of first vessel in May 1981 Related info encl MGLINA.J C Falcon Carriers, Inc 84/02/01 DENTON.H R Defice of Nuclear Reactor Regulation, Director 63pp 22096 057 24X Fiche 50-000,84/02/01.8402070393
- 8402140230 Interim Bignificant Deficiency Rept SDR 82-09 re replacement of Undersits motor operators for Westinghouse valves Completion delayed until 840401 due to add1 delivery problems
 TUCKER, H B Duke Power Co 84/02/01 D'REILLY, J P Region 2, Office of Director 1p 22221 041 24X Fiche 50-413, 84/02/01, 8402140230
- 8402150324 Deficiency rept re damaged diesel generator stator 18 Rebuilt stator will not be returned to facility site until 840601 Full completion of action will not take place until 840901 Final rept will be submitted by 840601 TUCKER.H B Duke Fower Co 84/02/02 C'REILLY.J P Region 2, Office of Director 1p 22250 175 24X Fiche 50-413,84/02/02.
- 8402150357 Interim Bignificant Deficiency Rept 414/83-17 re welding boss restrictors Pipe work required for remaining item will be completed by 840330 Training of appropriate personnel completed on 840116

 TUCKER, H B Duke Power Co 84/02/03 O'REILLY, J P Region 2, Office of Director ip 22250 ii2 24X Fiche 50-414,84/02/03,84021505357
- 8401190048 Board Notification 84-006 provides info re alleged falsification of GC documents concerning const of safety-related HVAC units by Bahnson Co. Hinston-Salem.NC EIBENHUT, D. G. Division of Licensing 84/02/09 PALLADING Commissioners 7pp 22332-187 24X Fiche 50-000.84/02/09,8401990048
- 8401190053 Board Notification 84-020 forwards info re Transamerica Delaval, Inc emergency diesel generator problems Attendance list meeting handouts & slides encl EIBENHUT, D 0 Division of Licensing 84/02/13. FALLADING Commissioners 102pp 22392, 202. 24X Fiche 50-000,84/02/13, 8401190053.
- 8402220530 Part 21 rept re defective DSR & DBRV standby diesel generator turbocharger thrust bearing lubrication Deficiency not corrected by sys mod New recommendation will be sent to customers by 840330

 BOYER, R E Transamerica Delayal, Inc 84/02/15 Director's Defice, Office of Inspection and Enforcement 5pp. 22332 182 24x Fiche 50-000.84/02/15.8402220530
- 8402290307 Forwards procedures, "Diesel Electric Generating Units" & "Extended Operation Test of Diesel Generator IA," in response to 831230 request Procurement, GA & operational experience u/diesel generators IA & IB discussed TUCKER.H B Duke Power Co 84/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director, ADENBAM, E G Licensing Branch 4 App 22422:064 24X Fichs 50-413,84/02/22,8402290307.
- --8402290312 Procedure CNS-1301 00-2, "Diesel Electric Generating Units "
 * Duke Power Co. 84/02/09 225pp 22422 068 24X
 Fiche:50-413,84/02/22,8402290307
- --8402290314 Procedure "Extended Operation Test of Diesel Generator 1A." * Duke Power Co. 84/02/27 200pp 22422 308 24X Ficha 50-413,84/02/22,8402290307
- 8402280701 Notification of 840308 meeting w/Transamerica Deleval, Inc (TDI) Owners Group in Wading River, NY to discuss TDI proposed program plan to qualify diesel generators GARUSO, R. Division of Licensing 84/02/23, BERLINGER, C Division of Licensing, 2pp. 22414 340, 24X Fiche 50-000,84/02/23, 8402260701.
- T Hearing transcripts on non-antitrust matters
- 8402030340 Transcript of 840130 hearing in Charlotte, NC Pp 11,922-12,259.

 ** Duke Power Co. 84/01/30 338pp. 22073 062 24X
 Fiche. 50-413,84/01/30,8402030340
- B402030478 Transcript of 840131 hearing in Charlotte, NC Pp 12, 260-12, 421. * Atomic Safety and Licensing Board Panel, 84/01/31, 163pp 22066; 285, 24% Fiche 50-413, 84/01/31, 8402030478.

- 8402080212 Transcript of 840209 telephoñe conference in Washington.DC Pp 12.422-12.505 # Duka Power Co 84/02/03 83pp 22134 105 24X Fiche 50-413.84/02/03.8402080212
- 8402210192 Transcript of 840216 telephone conference in Bethesda.MD Pp 12,506-12-335 * About Safety and Licensing Board Panel 84/02/16 31pp 22317 001 24X Fiche 50-413,84/02/16.8402210192
- 8402220577 Transcript of 840217 telephone conference in Bethesda.MD Pp 12.536-12.579 * Atomic Safety and Licensing Board Panel 84/02/17 46pp 22331 268 24X Fiche 50-413.84/02/17.8402220577
- V Operator Examinations
- 8402130332 Forwards revised pages to FSAR Section 13 2 clarifying various aspects of operator training program, per 840126 meeting w/B Wilson Revised pages will be included in Rev 9 to FSAR TUCKER, H. B. Duke Power Co. 84/02/10 C/REILLY, J.P. Region 2, Office of Director. Spp. 22197 114 24X Fiche 50-413,84/02/10,8402130332
- DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B402070003 Responds to FDIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Gaseload Forecast Panel meetings Forwards App A.B. & C documents
 FELTON.J M Division of Rules and Records B3/10/31
 ROSENBAUM.D M Technical Analysis Corp 17pp 22173 272 24X
 Fiche, 50-000, 83/10/31, 8402070003
- --8402070124 Handwritten notes & calculations re facility const Related info encl

 NRC No Detailed Affiliation Given 83/10/31 48pp 22194 200 24% Fiche 50-000.83/10/31.8402090003
- --8402070159 Handwritten notes & calculations re const activities & fuel load preparation * NRC - No Detailed Affiliation Given 79/08/22 9pp 22194 340 24X Fiche 50-000,83/10/31.8402090003
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8402150369 Forwards "Degraded Core Accident Hydrogen Control Program," quarterly status rept for quarter ending 830930, in response to request in SBER 4 (NUREO-0831)

 DALE, L. F. Mississippi Power & Light Co 84/02/09 DENTON, H R Office of Nuclear Reactor Regulation. Director lipp 22242:121

 24X Fiche: 50-416,84/02/09,8402150369
- F Security, medical, emergency & fire protection plans
- 8402220246 Revised emergency plan implementing procedures, including Emergency Plan Procedure 10-8-01-06 rs notification of offsite agencies & Corporate Emergency Plan Procedure 6 13 rs offsite dose calculations W/840214 ltr MCGAUGHY, JP Mississippi Power & Light Co 84/01/16. 0.REILLY, JP Region 2. Office of Director, 65pp. 22329:283 24X Fiche: 50-416.84/01/16.8402220246
- 8402140138 Confirms 840118 teleon re 840127 mgt meeting in Atlanta, GA to discuse proposed changes to security plan LEWIS,R C. Division of Project & Resident Programs. 84/01/23. RICHARD, J. B Mississippi Power & Light Co ip 22219, 322 24X Fiche: 50-416,84/01/23,8402140138.
- B402030445 Requests review of encl vital area barrier locations to determine whether upgrading required Encl withheld (ref 100FR79 ZI)

 BCHWENCER, A Licensing Branch 2 B4/01/30 MCOAUGHY, J.P., Missiasippi Power & Light Co

- 8402140359 Forwards summary of 840127 meeting w/util in Atlanta GA re proposed 10CFR50 54(p) change to physical security plan Changes re intrusion detection, access control & vehicle escarting require review LEWIS.R C Division of Project & Resident Programs 84/02/03 RCCHARD.J B Mississippi Power & Light Co 3pp 22220 097 24X Fiche 50-416.89/02/03.8402140359
- B402170395 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per B10709 Generic Ltr B1-27 W/o request, entire plan will be placed in PDR SCHMENCER. A Licensing Branch 2 84/02/09 MCGAUGHY, J P Mississippi Power & Light Co 2pp 22313 182 24X Fiche 50-416,84/02/09,8402170395

9 Adjudicatory correspondence

- 8402060143 Notice of appearance in proceeding Certificate of Svc encl LAVERTY.J H Mississippi Power & Light Co LAVERTY.J H Conner & Wetterhahn 84/02/02 3pp 22099 057 24X Fiche 50~416.84/02/02. 8402060143
- 8402150175 Suppl to 731117 request for hearing & patition for leave to intervene Jacksonians United for Livable Energy Policies Contentions 1,2 & 3 submitted Certificate of SVc encl STEWART, C A Jacksonians United for Livable Energy Policies 84/02/13 Atomic Safety and Licensing Board Panel App 22245 240 24X Fichs 50-416,84/02/13.8402150175
- 8402280347 Answer opposing Jacksonians United for Liveble Energy Policies 8402;3 supplemental request for hearing & petition for leave to intervene Proposed contentions speculative, vague & unspecific Certificate of Svc encl CONNER, T B Mississippi Power & Light Co CONNER, T B Conner & Hetterhahn 84/02/21 Atomic Safety and Licensing Appeal Panel 15pp 22403 155 24X Fiche 50-414,84/02/21,8402280347
- 8402240054 Forwards corrected 840221 answer to Jacksonians United for Livable Energy Policies request for hearing & petition for leave to intervene LAVERTY.J H Mississippi Power & LAVERTY.J H Gonner & Wetterhahn LAVERTY.J H Mississippi Power & Light Co 84/02/22 OROSSMAN,H . CARPENTER.J H . MCRRIS.P A Atomic Safety and Licensing Board Panel ip 22375 022 24X Fiche 50-416.84/02/22,8402240054
 - 8402240057 Answer opposing suppl to Jacksonians United for Livable Energy Policies 83:211 amended petition for leave to intervene Certificate of Bvc encl CONNER, T 8. Mississippi Power & Light Co CONNER, T, B Conner & Wetterhahn 84/02/21 Atomic Safety and Licensing Board Panel 15pp 22375 023 24x Fiche 50-416.84/02/22.8402240054
 - 2270072 Response to 840213 suppl to Jackosonians United for Livable .nergy Policies request for hearing & petition to intervene.
 All three contentions inadmissable & must be rejected Certificate of 8 yec encl WAGNER.M E Hearing Branch 4 84/02/24 Atomic Safety and Licensing Board Panel 11pp 22428 035 24X Fiche 50-416,84/02/24,8402290072

General correspondence

- 3402060083 Informs that HJ Green appointed advisor to vicepresident - nuclear of util Resume of HJ Green encl DALE.L F Hississippi Power & Light Co. 84/01/25 DENTON.H R Office of Nuclear Reactor Regulation. Director 4pp 22089 129 24X Fiche 50-416.84/01/25.8402060083
- 8402230089 Requests NRC update mailing labels on priority & free mail to reflect new ofc location CHAMBERLAIN.W California, State of 84/02/15 DI SILBESTRE, S NRC No Detailed Affiliation Given 2pp 22362 073, 24X Fiche. 50-000, 84/02/15, 8402230089.
- P Operating license stage documents & correspondence
- 8312120029 Generic Ltr 83-37 to representatives of utils re voluntary survey of licensed operators Svc list encl EISENHUT.D. O Division of Licensing 83/12/08 Commonwealth Edison Co 12pp 22313-006 ZAX Fiche 50-000, B3/12/08, B312120029
- 8402270178 Forwards Decision Mgt Co. Inc Jan 1984 "Rept on Waterford 3/ Orand Quif Study Prepared for State of LA PSC " LEDDICK.R. S Louisiana Power & Light Co. 84/01/10 COLLINS. J. T Region 4, Office of Director ip 22417 189. 24X Fiche. 50-000. 84/01/10.8402270198

- --8402290205 "Rept on Waterford 3/Grand Gulf Study Prepared for State of LA PSC" * Decision Management Co , Inc 84/01/31 800pp 22419 190 24X Fithe 50-000.84/01/10,8402290198
- B401190012 Board Notification 84-013 forwards info re Transamerica Delaval. Inc emergency diesel generators E18EMHUT.D G Division of Licensing B4/01/24 FALLADIND.N.. GILINBKY.V. ROBERTS.T Commissioners 10pp 22054 346 24X Fiche 50-000,84/01/24,8401190012
- 8402060172 Confirms 840124 telcon re ES Fuente 840112 ltr forwarding Amend 10 to License NPF-13 k accompanying safety evaluation M/o encl SCHWENCER, A Licensing Branch 2 84/01/26 FUENTE. E 8 Mississippi. State of 2pp 22106 315 24X Fiche 50-416,84/01/26,8402060172
- 8402140301 Forwards summary of GA program B40110 site meeting re addl info needed for review of program description, per B30923 ltr Ack util commitment to submit formal response by 640301 LEMIS.R C Division of Project & Resident Programs B4/01/27 RICHARD.J B Mississippi Power & Light Co 3pp 22227 172 24X Fichs 50-416.84/01/27.8402140301
- 8402040084 Forwards add1 info in support of control room inleakage following DBA issue re elimination of post-accident 0-2 minute unfiltered containment release from dose model DALE,L F Mississippi Power & Light Co 84/02/02 DENTON,H R Office of Nuclear Reactor Regulation, Director 14pp 22088 24: 24X Fiche 50-416.84/02/02.8402060084
- B402060103 Forwards description of implementation of listed NUREO-0737 items per Generic Ltr 83-36 Current Tech Specs consistent w/requirements for NUREQ-0737, Items II B 1, II B 3, II F 1 & II B 3 4

 DALE, L F Hississippi Power & Light Co B4/02/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 2208B, 277 24X Fiche 50-416, 84/02/02, 8402060103
- 8402090594 Forwards info requested per 840113 memo re procedures used for preparation of Tech Specs & how procedures applied to facilities

 DIRCKS, W J Office of the Executive Director for Operations, 84/02/02 GILINSKY, V Commissioners App 22191 132 24X Fiche 50-416,84/02/02.8402090594
- 8402160647 Ack receipt of 840111 ltr re proposed revs to startup test program Revs acceptable SCHKENGER.A Licensing Branch 2 84/02/03 MCOAUGHY, J P Mississippi Power & Light Co 2pp 22301 343 24% Fiche 50-416.84/02/03.8402160647
- 8402080279 Forwards "Physical Modelling of Contaminant Concentrations at Control Room Grand Gulf Nuclear Station," conducted in support of higher control room in-leakage values Commitment to provide info by 84030i fulfilled DALE, L. F. Mississippi Power & Light Co. 84/02/06, DENTON, H. R. Office of Nuclear Reactor Regulation, Director App. 22132-288 24X Fiche 50-416,84/02/06,8402080279
- --8402080282 "Physical Modelling of Contaminant Concentrations at Centrol Room " CERMAR, J & PETERKA, J A. NEFF, D E Colorado State Univ , Ft Collins, CO 83/11/30 90pp 22132 295 24X Fiche 50-416,84/02/06.8402080279
- --8402080286 "Physical Modelling of Contaminant Concentrations at Control Room: Apps " GERMAK.J E., PETERKA.J.A., NEFF.D.E Colorado State Univ., Ft Collins, CO 83/11/30 311pp 22133 024. 24X Fiche 50-416.84/02/06.8402080279
- 8402070196 Requests exemption from 10CFR50 71(e) which requires updated FSAR to be submitted within 24 months of QL Request based on involvement in full power licensing & startup testing.

 DALE, L F Mississippi Power & Light Co 84/02/06 DENTON: H R Office of Nuclear Reactor Regulation. Director. 4pp 22163,120 24% Fiche 50-416,84/02/06,8402070176
- E402170061 Notification of 840210 meeting w/Transamerica Delavai, Inc (TDI) in Bethesda.MD to discuss program plan proposed by TDI Owners Group to qualify diesel generators CARUSO.R Division of Licensing, 84/02/06 BERLINGER.C Division of Licensing 2pp 22312.339 24X Fiche.50-000,84/02/06, 8402170061

- 8402230363 Responds to 840123 request that proceedings re issuance of facility OL be expedited & any possible delays eliminated All necessary NRC resources have been & will continue to be applied to remaining outstanding safety issues
 DENTON.H.R. Diffice of Nuclear Reactor Regulation. Director 84/02/08 TAYLOR.O B Bouth Mississippi Electric Power Association 7pp 22376 243 24% Fiche 50-416.84/02/08.8402230363
- --B402230347 Requests that NRC expedite proceedings re issuance of facility OL & aliminate any possible delays, to avoid outstanding interest cost being paid by consumers TAYLOR.0 B South Mississippi Electric Power Association 84/01/23 FALLADINO.N Commissioners 3pp 22376 249 24X Fichs 50-416.84/02/08.8402230363
- B402220401 Advises that containment, liner & penetrations capable of withstanding 5 psid negative internal pressure due to hydrogen combustion, per NRC request DALE/L F. Mississippi Power & Light Co 84/02/09 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22334 304 24X Fiche 50-416.84/02/09,8402220401
- B402210447 Forwards request for add1 info re ultimate capacity for containment under external or negative pressure, inadvertently unitted from NRC 831208 request for add1 info concerning hydrogen control Response requested by 840401 8CHWENCER. A Licensing Branch 2 84/02/13 MCGAUCHY, J P Mississippi Power & Light Co 3pp 22323 329 24% Fiche 50-416,84/02/13,8402210447
- 8402270034 Forwards "Control of Heavy Loads at Nuclear Power Plants Grand Gulf Nuclear Station Unit 1, (Phase II), "draft technical eveluation rept ECHWENGER, A. Licensing Branch 2 84/02/14 MCQAUGHY, J P Mississippi Power & Light Co 2pp 20408 308 24X Fiche 50-416.84/02/14.8402270034
- ---B402170216 Draft "Control of Heavy Loads at Nuclear Power Plants, Grand Gulf Nuclear Station Unit 1, (Phase II) " SEKOT, J P Eg&g, Inc. FIN A-6457 84/01/31 50pp 22408 310 24X Fiche 50-416,84/02/14,8402270034.
- 8402270430 Notification of 840302 meeting w/Hydrogen Control Dwners Group in Bathesda, MD to discuss status of Hydrogen Control Owners Group 1/4-scale testing program & response to request for addl info received from NRC in Dec 1983 HOUSTON.M D. Licensing Branch 2 84/02/16. BCHWENCER, A Licensing Branch 2 7pp 2243B 187 24% Fiche 50-000,84/02/16,8402270430.
- 8402240030 Requests extension for submittal of ECCS reliability amalysis for Agastat relay test intervals until 840302, to enable further resolution of internally generated comments on 9E analysis.

 DALE, L. F. Mississippi Power & Light Co 84/02/17 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 22375 322 24X Fiche 50-416, 84/02/17, 8402240030
- 8402240323 Submits util draft shift advisor rept. Advisors maintain awareness of unit operation at all times so experience can best be utilized by shift mpt in properly responding to plant conditions.

 NDVAK: T NRC No Detailed Affiliation Given 84/02/21.

 EIBENHUT.D Q. NRC No Detailed Affiliation Olven. 2pp 22360: 148
 24% Fiche 50-416,84/02/21,8402240323
- B402270079 Notification of time & location change for 840221 meeting w/util in Bethosda,MD to discuss reliability of onsite power.
 - power. HOUSTON, M D Licensing Branch 2. B4/02/21 BCHWENCER, A Licensing Branch 2 4pp. 22408.048 24X Fiche 30-414,84/02/21,8402270099
- 8402290012 Application for amend to License NPF-13, changing Tech Specs re APRM setpoint MCGAUGHY,J.P. Mississippi Power & Light Go. 84/02/27. DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 22426.048, 24X Fiche 50-416,84/02/27,8402290012
- --8402290013 Proposed Tech Spec changes is APRM setpoint.
 # Mississippi Fauer & Light Co 84/02/27. ip. 22426:052 24X
 Fiche 30-416,84/02/27,8402290012
- G. Inspection reports: IE Bulletins & correspondence
- B402140019 Advises that due to administrative errors, IE Insp Rept 50-416/83-53 was assigned instead of correct number of 50-416/83-57. VERRELLI,D M. Division of Project & Resident Programs 84/01/12 RICHARD,J,B Mississippi Power & Light Co ip. 22219:256. 24X Fichs: 50-416,84/01/12,8402140019

- 8402280578 Informs that drywell bypass leakage test results per IE Insp Rept 50-416/83-11 failed to meet Tech Spec 3 & 2 2 limit Forwards NRR 831031 statement of concurrence LEWIS.R C Division of Project & Resident Programs 84/01/13 RICHARD.J B Mississippi Power & Light Co ip 22404 275 24X Fiche 50-416-84/01/13.8402280578
- 8312120153 IE Info Notice 84~06, "Steam Binding of Auxiliary Feedwater Pumps" Svc list encl JORDAN: E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co. of New York, Inc. 120pp 22058 001 24% Fiche 50-000,84/01/25,8312120153
- 8402010166 Responds to violations noted in IE Insp Repts 50-416/83-45 & 50-416/83-56 Corrective actions temporary starting air connection removed & Plant Quality Deficiency Rept 097-83 dispositioned Payment of civil penalty pen EA-83-133 encl DALE.L F Mississippi Power & Light Co 84/01/26 DEYOUNG,R C Director's Office Of Pispection and Enforcement 8pp 22038 308 24X Fiche 50-416,84/01/26,8402010166
- B402140322 Responds to IE Bulletin B3-06, "Nanconforming Matls Supplied by Tube-Line Corp Facilities at Long Island City,NY,Houston, TX & Carol Stream,IL " ASNE Code matl not received from vendor MCGAUGHY,JP Mississippi Fower & Light Co 84/01/30 0'RETLLY,JP Region 2, Office of Director 3pp 22228 240 24X Fiche. 50-416, 84/01/30, 8402140322
- 8402280575 Informs that ASME Code matl not received from Tube-Line Corp.per IE Bulletin 83-06 Carbon steel Tube-Line flanges purchased from Consolidated Pipe & Supply for nonsafety-related applications Corrected copy MCGAUGHY. JP Mississippi Power & Light Co 84/01/30 B'REILLY.JP Region 2. Office of Director 3pp 22406 269 24X Fiche 50-416.84/01/30.8402280575
- B402070322 Ack receipt of B40124 ltr submitting \$12.000 in payment of civil penalties proposed in NRC B31221 ltr
 AXELRAD. J A Director's Office Office of Inspection and Enforcement. B4/02/01 RICHARD. J B Mississippi Power & Light Co 2pp 22141 333 24X Fiche 50-416.84/02/01.8402070522
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 117pp 22114 179 24X Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01. "Cracks in BWR Mark I Containment Vent Headers." Syc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/02/03. Consolidated Edison Co of New York, Inc 102pp. 22177-136 24X Fiche 50-000.84/02/03.8401190017
- 8401190041 IE Info Notice 84-07, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R)" Syc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/13 Consolidated Edison Co of New York, Inc. 124pp 22365 259 24X Fiche 50-000,84/02/13,8401190041
- 8401190050 Board Notification 84-021 provides repts of Transamerica Delaval, Inc insps conducted from Mar 1979 to Oct 1983 EIBENHUT, D @ Division of Licensing 84/02/13, PALLADINO, GILINBKY, ROBERTS Commissioners 5pp. 22314
- 8408280418 Ack receipt of 830826,840105 & 0206 itrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-416/83-30
 LEWIG.R C. Division of Project & Resident Programs 64/02/13
 RICHARD.J B. Mississippi Power & Light Co. 1p 22404 321 R4X
 Fiche. 50-416,84/02/13,8402280418
- --8402280421 Suppls response to NRC 830727 ltr re violations noted in IE Insp Rept 50-416/83-30. Corrective actions MNCR 714-83 initiated to resolve generic issue of banana test jacks & safety evaluation performed DALE.L.F Mississippi Power & Light Co 84/02/06. O'REILLY, J P Region 2. Office of Director 2pp 22404-322. 24% Fichs 50-416,84/02/13.8402280418
- --8402280427 Suppls response to NRC 830727 itr re violations noted in IE Insp Rept 50-416/83-30 Corrective actions.MNCR 714-83 initiated to resolve generic issue of benana test jacks & safety evaluation performed DALE, L.F. Mississippi Fower & Light Co. 84/01/05 O'REILLY, J.P. Region 2. Office of Director. 2pp 22404, 324 24X Fiche. 50-416, 84/02/13, 8402280418

- 8401190039 IE Info Natice 84-08, "10CFR50 7, 'Employee Protection '" 8vc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Respanse (Post 830103) 84/02/14 Consolidated Edison Co of New York, Inc 113pp 22365 141 24X Fiche 50-000.84/02/14,8401190039
- B402280415 Ack receipt of 840120 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-416/83-53 LEWIS,R C Division of Project & Resident Programs B4/02/14 RICHARD, J B Mississippi Power & Light Co Ip 22406 141 24X Fiche 50-416,84/02/14,8402280415
- ~-8402280423 Responds to NRC 831220 ltr re violations noted in IE Insp Rept 50-416/83-53 Corrective actions candidates who passed exam will be required to complete addl qualification card prior to assuming licensed duties (Corrected copy) DALE, L. F. Mississippi Power & Light Co. 84/01/20 D'REILLY, J. P. Region 2. Office of Director App. 22406 142 24X Fiche 50-416,84/02/14,8402280415
- --8402280428 Responds to NRC 831220 ltr re violations noted in IE Insp Rept 50-416/83-53 Corrective actions candidates who passed exam will be required to complete addl qualification cand prior to assuming licensed duties DALE, L F Mississippi Power & Light Co 84/01/20 O'REILLY, J P Region 2. Office of Director App 22406 148 24X Fishe 50-416,84/02/14,8402280415
- --8402280432 Forwards IE Insp Rept 50-416/83-53 on 831031-1104 & notices of violation & deviation CEWIS-R C Division of Project & Resident Programs 83/12/20 RICHARD, J B Mississippi Power & Light Co 2pp 22406 154 24X Fiche 50-416/84/02/14/8402280415
- --8402280436 Notice of violation from insp on 831031-1104 * Region 2, Office of Director 83/12/20 ip 22406:196. 24X Fiche 50-416,84/02/14,8402280415
- --8402280444 Notice of deviation from Insp on 831031-1104 * Region 2, Office of Director 84/02/14 ip 22406.157 24X Fiche 50-416.84/02/14.8402280415
- --8402280570 IE Insp Rept 50-416/83-53 on 831031-1104 Deviations noted failure to complete qualification cards per FSAR commitments & failure of operator training evaluation committee to conduct records review of candidate training WILBON.B A. JULIAN.C A. MUNRO.J F. Region 2. Office of Director. 83/12/14 14pp 22406 158 24X Fiche 50-416.84/02/14, 8402280415.
- 8401190045 IE Info Notice 83-63. Suppl 1, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc. 118pp 22366 142 R4X Fiche 50-000.84/02/15.8401190045
 - 2280262 Ack recript of 840209 ltr informing NRC of steps taken to orrect violations noted in IE Insp Rept 50-416/83-36 ... EWISB.R C Division of Project & Resident Programs 84/02/17 RICHARD.J B Mississippi Power & Light Co 1p 22398.318 24X Fichs 50-416,84/02/17.8402280262
- --8402280265 Responds to NRC 840107 ltr re violations noted in IE Insp Repts 30-416/83-56 & 50-416/83-43 Corrective actions shift supervisor advised to consult Tech Specs when declaring equipment inoperable DALE, F. Hississippi Power & Light Co 84/02/09 O'REILLY, J P Region 2, Office of Director 5pp 22398 319 24X Fiche 50-416,84/02/17,8402280262
- --8402280272 Responds to NRC 831221 & 840107 ltrs re violations noted in IE Insp Repts 50-416/83-43 & 30-416/83-56 Corrective actions personnel involved counseled & made aware of proper procedures for performing temporary alterations DALE, L. F. Mississippi Power & Light Co 84/01/26 DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement, 9pp. 22398 324 24X Fiche. 50-416.84/02/17,8402280262
- --8402280278 Forwards IE Insp Rept 50-416/83-56 on 83\$116-1213 & notice of violation Violations similar to violations identified in NRC 831221 notice of violation & proposed imposition of civil penalty Response should address 831221 notice. LEMIS.R C Division of Project & Resident Programs 84/01/09 RICHARD.J B. Mississippi Power & Light Co 2pp 22398,333 24X Ficher 50-416,84/02/17.8402280262
- --8402280280 Notice of violation from insp on 831114-1213. * Region 2, Office of Director 84/01/09 ip 22398-335 24X Fiche 50-414,84/02/17,8402280262

- --8402280284 IE Insp Rept 50-416/83-56 on 831116-1213 Violations noted failure to document Tech Spec limiting conditions for aperation when both diesel generators inoperable & failure to follow administrative procedures
 WAONER, A G Region 2, Office of Director JULIAN, C A Division of Project & Resident Programs 84/01/05 7pp 22378 336 24% Fiche 50-416,84/02/17,8402280262
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Buitches Set Below Manufacturer Recommended Value " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000.84/02/21.8401190062
- B401190066 IE Info Notice 84-11, "Training Program Deficiencies "
 Svc list and
 JORDANS L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
 SVc list enci
 JDRDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co. of New
 York, Inc. 120pp 22431 060 24X Fiche 50-000,84/02/27,8401190067.
- R Periodic operating reports & related correspondence
- 8402150369 Forwards "Degraded Core Accident Hydrogen Control Program," quarterly status rept for quarter ending 830930, in response to request in 88ER 4 (NUREG-0831)

 DALE, L. F. Mississippi Power & Light Co. 84/02/09 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 11pp 22242 121, 24X Fiche 50-416,84/02/09,8402150369
- B402240059 Forwards quarterly rept for Last Quarter 1983, "Degraded Core Accident Hydrogen Control Program"

 DALE, L F Mississippi Power & Light Co B4/02/22, DENTON, H R. Office of Nuclear Reactor Regulation, Director 1p 22374, 138 24K Fiche 50-416, 84/02/22, B402240059
- --8402240060 Quarterly status rept for Last Quarter 1983, "Degraded Core Accident Hydrogen Control Program" DALE.L F Mississippi Power & Light Co 83/12/31 4pp 22374 139 24X Fiche 50-416,84/02/22,8402240059
- B Reportable occurrences, LERs & related correspondence
- B402210206 Forwards "Reactor Vessel Drainage," technical review rept SALAH,8 Reactor Operations Analysis Branch 93/10/07.
 BEYFRIT,K V Reactor Operations Analysis Branch 1p 22346:142
 24X Fiche 50-416,83/10/07.8402210206
- --8402210210 "Reactor Vessel Drainage," technical review rept SALAH.8 Reactor Operations Analysis Branch 83/10/07 3pp 22346 143 24% Fiche 50-416.83/10/07.8402210206
- 8402030342 LER 83-193/03L-0 on B31227, butboard suction valve closed during instrument surveillance Caused by tip breaking off mini-test clip Surveillances reviewed for points requiring test connections & banana Jacks installed W/840126 ltr. PARKER, J., DALE, L. F. Mississippi Power & Light Co. 84/01/26 O'REILLY, J. P. Region 2, Office of Director, 2pp. 22069, 152 24X Fiche: 50-416, 84/01/26, 8402030342
- 8402070393 Requests that NRC investigate design reliability of emergency diesel generators supplied by Transamerica Delaval. Inc Engine problems have been experienced since delivery of first vessel in May 1981 Related info smcl MOLINALJ C Falcon Carriers, Inc 84/02/01. DENTON, H. R. Office of Nuclear Reactor Regulation, Director 63pp 22096-057 24X Fiche 50-000.84/02/01.8402070393
- 8402130389 Updated LER 83-083/01X-2 on 830716, during 18-month emergency diesel generator functional test, standby svc water valves did not reposition & LPCI injection valve did not open. Caused by Agastat relay failure W/840201 itr BVRD.R , DALE.L.F. Mississippi Power & Light Co. 84/02/01. D'REILLY.J P. Region Q. Office of Director. Spp 22203 288 24% Fiche: 50-416.84/02/01.8402130389
- B402130450 Updated LER 63-163/03X-1. on B31013, turbine trip throttle valve falled to reset Caused by failed transistors in optical isolator card. Gard replaced W/840201 ltr.
 BYRD.R., DALE,L.F. Hississippi Power & Light Co. B4/02/01
 D'REILLY,J.P. Region 2. Office of Director 3pp. 22202 104 24X
 Fiche 50-416.84/02/01.8402130450

- 8402130430 RO 83-116/O on 831220, smake detectors in Zone 2-7 & 1-4 alarmed & would not reset Caused by dust particles on ionization detectors Iones reset & restored to operability on 840106 & 09 DALE/L F Mississippi Power & Light Co 84/02/02 O'REILLY, J P Region 2, Office of Director 2pp 22201 279 24X Fiche 50-416, 84/02/02, 8402130430
- 8402140410 Suppl to final deficiency rept re failure of qualified cables on Transamerica Deleval generators to pass IEEE flams test due to inadequate temp rating for cable insulation Initially reported on 821214 Also reported per Part 21 MCGAUGHY. J P Mississippi Power & Light Co 84/02/02 O'REILLY, J P Region 2. Office of Director 5pp 22220 358 24: Fiche. 50-416.84/02/02.8402140410
- 8402220126 LER 84-001-00 on 840103. Div 2 power supply tripped Caused by battery charger squalizing potentiomster set higher than normal Procedure revised, instructing technicians to adjust charger output to 1401 +/-1 volts dc W/840202 ltr BYRD.R. DALE, L. F. Mississippi Power & Light Co. 84/02/02 3pp 22337 248 24X Fiche 50-416.84/02/02.8402220126
- 8402140013 LER 84-002-00 on 840107.09.11.14.19 & 20.reactor protection sys bus breaker trips resulted in loss of shutdown cooling Cause undetermined. Investigation continuing W/840206 ltr. BYRD.R., DALE,L F Mississippi Pawer & Light Co 84/02/06 2pp 22221-253, 24X Fiche 50-416.84/02/06.8402140013
- 8402220069 Updated LER 83-164/03X-1 on 831016, channel 8 containment hydrogen monitor failed monthly calibr Caused by faulty hydrogen analyzar cell Cell replaced W/840207 ltr PARKER, J., DALE, L. F. Mississippi Power & Light Co. 84/02/07 O'REILLY, J. P. Region 2, Office of Director Spp. 22337 228 24X Fiche 50-416.84/02/07.8402220069.
- 8402220119 Updated LER 83-167/03X-1 on 831022, leak developed in fuel oil filter differential pressure instrument line. Diesel declared inoperable. Caused by rupture in tubing due to vibration Tubing replaced W/840207 ltr
 BYRD.R., DALE, L.F. Mississippi Power & Light Co. 84/02/07
 0/REILLY, J.P. Region 2, Dffice of Director. 4pp 22337, 358, 24X
 Fichs. 50-416, 84/02/07, 8402220119
- 840:170053 Board Notification 84-020. forwards info re Transamerica Delaval, Inc emergency diesel generator problems Attendance list, meeting handouts & slides encl EIBERHUT.D 9 Division of Licensing. 84/02/13. PALLADIND Commissioners 102pp 22332 202 24X Fichs 50-000,84/02/13, 8801190053
- 8402170171 RO 84-003/O on 840112, standby diesel generator 12 tripped on reverse power while running parallel w/offsite power during retest following maint Gaused hu mat/function of rectifier diode in voltage regulator Update rept by 840312 DALE: L.F. Mississippi Power & Light Co. 84/02/13 Record Services Branch (Document Control Desk). 2pp. 22299.071. 24X Fiche: 50-416,84/02/13,8402170171
- 8402220037 Updated LER 83-031/99X-3: on 830113, Fire-Rated Door OC104 blocked open to route temporary discharge hose from hot machine shop sump to turbine bidg floor drain sys Caused by failure of hot machine shop sump W/840213 itr ARRAHAN, W B., DALE, L. F. Mississippi Power & Light Co. 84/02/13 0'REILLY, J. P. Region D. Dffice of Director 3pp 22337.223 24X Fiche: 50-416,84/02/13,8402220037
- 8402220080 Updated LER 83-170/03X-1 on 831026.attempts to secure RCIC turbine via trip pushbutton failed Caused by infrequent operation resulting in oxidation of closs tolerance parts. On 831101.turbine tripped on overspeed, M/840213 ltr PARKER, J. DALE, L. F. Mississippi Power & Light Co. 84/02/13, D'REILLY, J. P. Region 2. Office of Director 4pp. 22337, 231 24X Fiche: 50-416, 84/02/13, 8402220080
- 8402220329 RO 84-001/0 on 840105. Listed fire barriers opened to implement design change packages Fire watches established until barriers restored DALE.L F. Mississippi Power & Light Co 84/02/13 O'REILLY, J P. Region 2, Office of Director 2pp 22335-346 24X Fiche: 50-416, 84/02/13, 8402220329.
- 8402270144 Updated LER 83-177/03X-1 on 831027,1102 & 06, water collected in offgas pretreatment monitor, resulting in improper flow through monitor. Caused by accumulation of condensation Heat tracing instelled on piping. W/840213 ltr FARKER. J., DALE, L.F. Mississippi Fower & Light Co. 84/02/13 O'REILLY, J.P. (Region 2, Office of Director 3pp. 22387;342. 24X Fiche: 50-416,84/02/13,8402270144

- 8402220331 Updated RO 83-067/2 on 830712 accelerographs used for seismic monitoring discovered damaged Caused by over-hanging Design Tech Specs & FSAR revised to delete instruments to increase range DALE: L F Mississippi Power & Light Co 84/02/14 O'REILLY, J P Region 2. Office of Director 2pp 22333 153 24X Fiche 50-416,84/02/14.8402220331
- 8402220570 Updated LER 83-143/01X-1 on B3092B, component cooling water process radiation monitor sample pump discovered inoperable Caused by pump switched off Radiation monitor sys flow check added to auxiliary bldg shift rounds log W/840214 ltr BYRD,R, DALE,L F Mississippi Power & Light Co 84/02/14 D'REILLY,J P Region 2. Office of Director 4pp 22331 356 24X Fiche 50-416,84/02/14,8402220570
- 8402270085 LER 84-004-00 on 840114, shutdown cooling suction valve isolated Caused by fuse failure during technician panel work Fuse replaced W/840213 ltr BYRD.R. DALE, L.F. Mississippi Power & Light Co. 84/02/14 3pp 22391 247 24X Fiche 50-416,84/02/14,8402270085
- 8402270323 Updated LER 83-109/03X-2 on 830727, spurious RHR room high area temp or dulta temp signal caused inboard shutdown cooling valve F009 closure Caused by loose plug connection on Riley temp switch W640214 Itr BYRD.R , DALE, L F Mississippi Power & Light Co 84/02/14 D'REILLY, J P Repion 2, Office of Director 3pp 22389 279 24X Fiche 50-416,84/02/14.8402270323
- 840222030 Part 21 rept re defective DBR & DBRV standby diesel generator turbocharger thrust bearing lubrication Deficiency not corrected by sys mod New recommendation will be sent to customers by 840390
 BOYER R E Transamerica Delaval. Inc 84/02/15 Director's Office. Office of Inspection and Enforcement 5pp 22332 182 24X Fiche 50-000.84/02/15,8402220530
- 8402270159 RO 84-002/O on 840109, Fire-Rated Door 1A314 to RPV vibration monitor room on Elevation 139 ft in auxiliary bldg blocked open to support maint activities Fire watches established until door restored on 840118

 DALE, L F Mississippi Power & Light Co 84/02/15 O'REILLY, J P Region 2, Office of Director 2pp 22591-279 24X

 Fiche 50-416,84/02/15,8402270159
- 8402270227 Special Rept B4-004/0 on 840111, listed penetrations opened for planned maint activities. Firs watches established within I h & maintained for duration of activities Work task completion expected by 840430

 DALE: F. Mississippi Power & Light Co. 84/02/17 o'REILLY, J. P. Region R. Office of Director 2pp. 22391. 298. 24X

 Fiche. 50-416. 84/02/17. 8402270227
- 8402270404 Final deficiency rept for Unit 1 & interim deficiency rept for Unit 2 re cracked push rod balls on Transamerica Delaval diesel generators Initially reported on 840216 Also reported par Part 21 for Unit 1 Next rept expected by 840707 MCGAUGHY, J P Mississippi Power & Light Co. 84/02/17 O'REILLY, J P. Region 2, Office of Director. 5pp 22391 058 24X Fiche: 50-416,84/02/17.8402270404
- 8402270407 Updated LER 83-180/03X-1 on 831107.drywell floor drain sump lavel & flow monitoring leak detection sys discovered inoperable Cause undetermined. Bys monitored for 2 wks w/o repeating problem W/840217 ltr PARKER.J., DALE.L.F Mississippi Power & Light Co 84/02/17 U'REILLY,J P. Region 2, Office of Director 3pp. 22391 030 24X Fichs 30-416.84/02/17.8402270407
- 8402230228 Forwards "Comprehensive Rept on Standby Diesel Generators Bignificant Activities to Enhance & Verify Reliability "
 Rept describes util program to verify reliability & performance of Transamerica Delaval diesel generators MCGAUGHY, J.P. Mississippi Power & Light Co. 84/02/20 DENTON, H. R. Défice of Nuclear Reactor Regulation, Director App. 22361 304 24X Fiche 30-416.84/02/20,8402230228
- --8402230234 "Comprehensive Rept on Standby Dissal Generators --Bignificant Activities to Enhance & Verify Reliability," * Mississippi Power & Light Co 84/02/29. 108pp 22361 310 24% Fiche 50-416,84/02/20,8402230228
- B402280550 LER 84-003-00 on 840117, during performance of special test of drywell purge compressor A logic relays, compressor inadvertently started Cause unknown Maint order initiated to reperform test & troubleshoot circuit, W/840220 ltr BYRD.R, W. DALE, L. F. Mississippi Power & Light Co 84/02/20 2pp 22406 280 24X Fiche 50-446.84/02/20.8402280550

- 8402280701 Notification of 840308 meeting w/Transamerica Delaval.Inc (TDI) Owners Group in Wading River.NY to discuss TDI proposed program to qualify diesel generators CARUSD.R Division of Licensing 84/02/23 BERLINGER.C Division of Licensing 2pp 22414 340 24X Fiche 50-000.84/02/23, 8402280701
- B402270194 Confirms discussions & commitments made in 840221 meeting w/NRC Emphasizes substantial evaluation insp.maint & testing efforts accomplished to address problems & verify reliability of Transamerica Delavalinc diesel generators MCGAUGHY, J.P. Mississippi Power & Light Co. 84/02/26 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 27pp 22425 127 24X Fiche 50-416,84/02/26,8402290194

V Operator Examinations

- 8402140494 Confirms 840131 mgt site meeting w/util to discuss program for training monlicensed staff.per 840123 telcon LEWIG.R C Division of Project & Resident Programs 84/01/24 RICHARD. J B Mississippi Power & Light Co ip 22221 114 24X Fiche.50-416.84/01/24.8402140496
- 8402280415 Ack receipt of 840120 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-416/83-53 LEWIS.R C Division of Project & Resident Programs 84/02/14 RICHARD.J D Mississippi Power & Light Co. 1p. 22406 141. 24% Fiche: 50-416. 84/02/14.8402280415
- -8402280423 Responds to NRC 831220 ltr re violations noted in IE Insp Rept 50-416/83-53 Corrective actions candidates who passed eram will be required to complete addl qualification card prior to assuming licensed duties (Corrected copy) BALE.L F Mississippi Power & Light Co. 84/01/20 O'REILLY, J P Region 2. Office of Director App 22406 142 24X Fiche 50-416,84/02/14.8402280415
- --B402280428 Responds to NRC 831220 ltr re violations noted in IE Inap Rept 50-416/83-53 Corrective actions candidates who passed exam will be required to complete add1 qualification card prior to assuming licensed duties UALE.L.F. Mississippi Power & Light Co. 84/01/20 O'REILLY, J. P. Region 2, Office of Director App. 22406 148 24X Fiche 50-416.84/02/14.8402280415
- --8402280444 Notice of deviation from insp on 831031-1104 * Region 2, Office of Director 84/02/14 lp 2240 Fiche 50-416,84/02/14,8402280415 2240A 157 24X
- --8402280570 IE Insp Rept 50-416/83-53 on 831031-1104 Deviations noted failure to complete qualification cards per FBAR commitments & failure of operator training evaluation committee to conduct records review of candidate training WILSON.B.A., ULLIAN.C.A., MUNRO.J.F. Region 2. Office of Director, 83/12/14. 14pp 22406-158 24X Fichs.50-416,84/02/14, page 22406-158 24X Fichs.50-416,84/02/14. WILSON, B. A., JULIA B3/12/14, 14pp B402280415

DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

- 8402090003 Responds to FOIA request for const completion dates for NUMBER PLANTS CUrrently under const & analyses containing estimates based on inclusion of Gaseload Forecast Panel muetings Forwards App A.B & C documents
 FELTON.J M Division of Rulea and Records 83/10/31
 ROSENBAUM.D M. Technical Analysis Corp. 19pp. 22173 292 24X
 Fiche 30-000,83/10/31,8402070003
- --8402090124 Handwritten notes & calculations re facility const Related info encl * NRC - No Detailed Affiliation Given 83/10/3 22194: 200 24% Fiche 50-000,83/10/31,8402090003 83/10/31
- --B402070156 Handwritten notes & calculations re const & fuel load preparation

 DALE, L NRC - No Detailed Affiliation Given. 78/05/31 10pp.
 22194 326. 24X Fiche 50-000,83/10/31,8402090003.
- --8402090159 Handwritten notes & calculations re const activities & fuel 79/08/22 9nn 22174 340
- 8402290198 Forwards Decision Mgt Co. Inc Jan 1984 "Rept on Waterford 3/ Grand Gulf Study Prepared for State of LA PSC " LEDDICK.R S Louisiana Power & Light Co 84/01/10 CDLLINS.J T. Region 4. Office of Director. Ip 22417:189 24X Fichs: 50-000,84/01/10,8402290198

- --8402270205 "Rept on Waterford 3/Grand Gulf Study Prepared for State of LA PSC " # Decision Management Co , Inc 84/01/31 800pp 22419 190 24X Fiche 50-000.84/01/10.8402290198
- 8402060084 Forwards add1 info in support of control room inleakage following DBA issue re elimination of post-accident 0-2 minute unfiltered containment release from dose model DALE.L F Mississippi Power & Light Co 84/02/02 DENTON.H R Office of Nuclear Reactor Regulation. Director 14pp 22088 247 24X Fiche 30-416.84/02/02.8402050084
- 8402050103 Forwards description of implementation of listed NUREO-0737 , items per Generic Ltr 83-36 Current Tech Specs consistent w/requirements for NUREG-0737, Items II 8 1, II 8 3, II F 1 & 11 D 3 4

 DALE,L F Mississippi Power & Light Co 84/02/02 DENTON,H R

 Office of Nuclear Reactor Regulation, Director 3pp 22088 277

 24X Fiche 50-416,84/02/02,8402060103
- 8402090594 Forwards info requested per 840113 memo re procedures used for preparation of Tech Specs & how procedures applied to facilities
 DIRCKS: H J Office of the Executive Director for Operations PACIFICATION OF THE EXECUTIVE DIRECTOR FOR Operations 84/02/02 GILINSKY, V Commissioners App 22191 132 24 Fiche 50-416,84/02/02,8402090594
- 8402080279 Forwards "Physical Modelling of Contaminant Concentrations at Control Room Grand Quif Nuclear Station," conducted in support of higher control room in-leakage values Commitment to provide info by 840301 fulfilled DALE.L F Mississippi Power & Light Co 84/02/06 DENTON.H R DALE, E # #1851851pp; Fower & Light Co 84/02 Office of Nuclear Reactor Regulation, Director 24% Fiche 50-416,84/02/06,8402080279 600
- --8402080282 "Physical Modelling of Contaminant Concentrations at Control Koom " CERMAK.JE , PETERKA.JA, NEFF.DE Colorado State Univ , Ft Collins, CO 83/11/30 90pp 22132 295 24X Fiche 50-416.84/02/06.8402080279
- --84020BOR86 "Physical Modelling of Contaminant Concentrations at Control Room Apps "
 CERMAK.J E., PETERKA,J A., NEFF,D E. Colorado State Univ., Ft
 Collins, CO. 83/11/30 311pp 22133,024. 24X
 Fiche 50-416,84/02/06,8402080279
- 840217006: Notification of 840210 meeting w/Transamerica Delaval, Inc (TDI) in Bethesda, MD to discuss program plan proposed by TDI Owners Group to qualify dissel generators CARUSD, R Division of Licensing 84/02/06 RERLINGER, C Division of Licensing 2pp. 22312:339 24X Fiche 50-000, 84/02/06, 8402170061
- 8402220401 Advises that containment, liner & penetrations capable of withstanding 5 psid negative internal pressure due to hydrogen combustion, per NRC request DALE, L F Mississippi Power & Light Co 84/02/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp. 22354:306-24X Fiche 50-416,84/02/09,8402220401.
- 8402210447 Forwards request for add1 info re ultimate capacity for containment under external or negative pressure, inedvertently emitted from NRC 831208 request for add1 info concerning hydrogen control Response requested by 840401 8CHMENCER.A Licensing Branch 2 84/02/13 MCOAUCHY.J.P. Mississippi Power & Light Co 3pp 22323 327 24X Fiche 50-416,84/02/13,8402210447
- 8402240030 Requests extension for submittal of ECCB reliability analysis for Agastat relay test intervals until 840302, to enable further resolution of internally generated comments on GE analysis. DALE:L.F. Mississippi Power & Light Co 84/02/17 DENTON:H.R. Office of Nuclear Reactor Regulation, Director 2pp 22375.322 24X Fiche. 30-416.84/02/17.8402240030
- 8402240323 Submits util draft shift advisor rept Advisors maintain awareness of unit operation at all times so experience cen best Se utilized by shift mpt in properly responding to plant conditions
 NOVAK.T. NRC No Detailed Affiliation Given 84/02/21
 EIBENHUT.D G NRC No Detailed Affiliation Given, 2pp 22980°148
 24X Fiche 50-416,84/02/21,8402240323
- 8402270099 Notification of time & location change for 840221 meeting w/util in Bethesda, MD to discuss reliability of onsite

power HOUSTON,M D. Licensing Branch 2. 84/02/21, SCHHENCER,A. Licen Branch 2. 4pp. 22408 048. 24X Fiche 50-416,84/02/21,8402270099

- E NRC Bafety Evaluation Report (SER), supply & correspondence
- 840215D369 Forwards "Degraded Core Accident Hydrogen Control Program," quarterly status rept for quanter ending 830930.in response to request in SEER 4 (MNREG-OBE)

 DALE.L F Mississippi Power & Light Co 84/02/09 DENTON.H R
 Office of Nuclear Reactor Regulation. Director 11pp 22242 121
 24% Fiche 50-416.84/02/09.8402150369
- F Security, medical, emergency & fire protection plans
- 8402220246 Revised emergency plan implementing procedures, including Emergency Plan Procedure 10-8-01-06 re notification of offsite agencies & Corporate Emergency Plan Procedure 6 13 re offsite dose calculations W/840214 lbr MCGAUGHY. JP Mississippi Power & Light Co 84/01/16 0'REILLY. JP Region 2. Offsice of Director 65pp 22327 283 24X Fiche: 50-416.84/01/16.8402220246
- B402170395 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licenses, per 810709 Generic Ltr 91-27 W/o request, entire plan will be placed in FOR SCHWENCER, A Licensing Branch 2 84/02/09 MCGAUGHY, J F Mississippi Power & Light Co 2pp 22313 182 24X Fichs: 50-416, 84/02/09, 8402170395
- Q Adjudicatory correspondence
- B402150175 Suppl to 73:117 request for hearing & petition for leave to intervane Jacksonians United for Livable Energy Policies Contentions 1,2 & 3 submitted Certificate of Svc encl.

 HTEMART.C A Jacksonians United for Livable Energy Policies B4/02/13 Atomic Safety and Licensing Board Panel App 22245:240 24X Fiche 50-416,84/02/13,8402:50175
- 8402240054 Forwards corrected 840221 answer to Jacksonians United for Livable Energy Policies request for hearing & petition for leave to intervene.
 LAVERTY, J H. Conner & Wetterhahn LAVERTY, J H. Mississippi Power & Light Co. 84/02/22 GROSSMAN.H., CARPENTER.J H., MORRIS, P. A. Atomic Safety and Licensing Board Panel 1p. 22375 022 24X Fiche'50-416.84/02/22,8402240054
- --8402240057 Answer opposing suppl to Jacksonians United for Livable Energy Policies 83:211 amended patition for leave to intervene Cartificate of Svc encl GONNER, T B Mississippi Power & Light Co CONNER, T B. Conner & Watterhahn. 84/02/21 Atomic Safety and Licensing Board Panel 15pp 22375 023. 24% Fiche 50-416,84/02/22,8402240054
- 8402270072 Response to 840213 suppl to Jackosonians United for Livable Energy Policies request for hearing & petition to intervene. All three contentions inadmissable & must be rejected Certificate of 8vc enc! WAGNER, ME Hearing Branch 4 84/02/24 Atomic Gafety and Licensing Board Panel. 11pp 22428-035 24X Fichs 50-416.84/02/24, 8402270072.

H General correspondence

- 8402060083 Informs that HJ Green appointed advisor to vicepresident - nuclear of util Resume of HJ Green encl DALE, L. F. Mississippi Power & Light Co 84/01/25, DENTON, H, R Diffice of Nuclear Reactor Regulation, Director App 22089 129, 24X Fiche 50-416,84/01/25,8402060083
- G Inspection reports, IE Bulletine & correspondence
- B312120153 IE Info Notice 84-06, "Bteam Binding of Auxiliary Feedwater Pumps." Svc list encl JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/01/25. Consolidated Edison Co. of New York. Inc. 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120153
- 8402140322 Responds to IE Bulletin 83-06, "Nonconforming Metls Supplied by Tube-Line Corp Facilities at Long Island City, NV, Houston, TX & Carol Btream, IL " ABME Code matl not received from vendor, MC9AUGHY, J.P Missission; Power & Light Co 84/01/30
 - Vendor.
 MCGAUGHY.J.P Mississippi Power & Light Co 84/01/30
 O'REILLY,J.P Region 2, Office of Director. 3pp. 22228-240 24X
 Fiche: 50-416.84/01/30.8402140322
- 8402280375 Informs that ASME Code met1 not received from Tube-Line Corp.per IE Bullstin 83-06. Carbon steel Tube-Line flanges purchased from Consolidated Pipe & Supply for nonsefety-related applications. Corrected copy MCGAUGHY. J. P. Mississippi Power & Light Co. 84/01/30 O'REILLY. J P. Region 2. Office of Director. 3pp 22406: 269. 24% Fiche: 50-416.84/01/30.8402280375

- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R) " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259 24X Fiche 50-000,84/02/13,8401190041
- 8401190039 IE Info Notice 84-08, "100FR50 7, 'Employee Protection '"
 Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- B401190045 IE Info Notice B3-63. Suppl 1, "Potential Failures of Westinghouse Type BA-1 Differential Relays " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/02/15 Consolidated Edison Co of New York. Inc 11Bpp 22366 142 24X Fiche 50-000, 84/02/15, 8401190045
- B401190066 IE Info Notice B4-11, "Training Program Deficiencies "
 Svc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/02/24 Consolidated Edison Co. of New
 York, Inc. 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84~12, "Failure of Boft Seat Valve Seals "
 Svc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060 24% Fiche 50-000,84/02/27,8401190067
- R Pariodic operating reports & related correspondence
- B40R190369 Forwards "Degraded Core Accident Hydrogen Control Program," quarterly status rept for quarter ending 830930.in response to request in 95ER 4 (NUREG-0B31)

 DALE, L. F. Mississippi Fower & Light Co. 84/02/09 DENTON, H. R. Office of Nuclear Reactor Regulation. Director 11pp 22242 121 24X Fiche 50-416.84/02/09.8402150369
- 8402240059 Forwards quarterly rept for Last Quarter 1983, "Degraded Core Actident Hydrogen Control Program"

 DALE/L F Mississippi Power & Light Co 84/02/22 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 1p 22374 13B 24X
 Fiche 50-416, 84/02/22, 8402240059
- --8402240060 Quarterly status rept for Last Quarter 1983, "Degraded Core Accident Hydrogen Control Program" DALE, L F Mississippi Power & Light Co B3/12/31 4pp 22374.139 24X Fiche 50-416.84/02/22.8402240009
- S Reportable occurrences. LERs & related correspondence
- 8402070393 Requests that NRC investigate design reliability of emergency diesel generators supplied by Transamerica Delaval-Inc Engine problems have been experienced since delivery of first vessel in May 1981 Related info encl MDLINA.J C Falcon Carriers, Inc 84/02/01 DENION.H R Office of Nuclear Reactor Regulation. Director 43pp 22094 037 24X Fiche 50-000,84/02/01.8402070393
- B402140410 Suppl to final deficiency rept re failure of qualified cables on Transamerica Delaval generators to pass IEEE flame test due to inadequate temp rating for cable insulation initially reported on B21214 Also reported por Part 21 MCQAUGHY, J P Mississippi Fower & Light Co 84/02/02 07/BEILLY, J P Region 2. Office of Director 5pp 22220 358 24X Fighs 50-416,84/02/02,8402140410
- 8401190033 Board Notification 84-020 forwards info re Transamerica Delaval. Inc emergency diesel generator problems Attendance list meeting handouts & slides encl EIBENHUT.D 0 Division of Licensing 84/02/13 PALLADINO Commissioners 102pp 22332 202. 24X Fiche 50-000, 84/02/13, 8401190053.

- B402220530 Part 21 rept re defective DSR & DSRV standby diesel generator turbocharger thrust bearing lubrication Deficiency not corrected by sys mod New recommendation will be sent to customers by B40330 BOYER.R E Transamerica Delavai. Inc 84/02/15 Director's Office. Office of Inspection and Enforcement 5pp 22332.182 24X Fiche 50-000.84/02/15.8402220530
- B402270404 Final deficiency rept for Unit 1 & interim deficiency rept for Unit 2 re cracked push rod balls on Transamerica Delaval diesel generators. Initially reported on B40216 Also reported per Part 21 for Unit 1 Next rept expected by B40707 MCGAUGHY, JP Mississippi Power & Light Co B4/02/17 O'REILLY, JP Region 2, Office of Director 5pp 22371.058 24X Fiche 50-416,84/02/17,8402270404
- 8402230228 Forwards "Comprehensive Rept on Standby Diesel Generators Significant Activities to Enhance & Verify Reliability "
 Rept describes util program to verify reliability & performance of Transamerica Delaval diesel generators MCGAUCHY. J P Mississippi Power & Light Co 84/02/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 22361 304 24% Fiche 30-416,84/02/20,8402230228
- --8402230234 "Comprehensive Rept on Blandby Diesel Generators -Significant Activities to Enhance & Verify Reliability " * Mississippi Power & Light Co 84/02/29 108pp 22361 310 24X Fiche. 50-416.84/02/20.8402230228
- 8402280701 Notification of 840308 meeting w/Transamerica Delavak, Inc (TDI) Owners Group in Wading River, NY to discuss TDI proposed progrem plan to qualify dissal generators CARUSO.R Division of Licensing 84/02/23 BERLINGER, C Division of Licensing 2pp 22414 340 24X Fichs 50-000, 84/02/23, 8402280701
- DOCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing satimates based on inclusion of Caseload Forecast Fanel meetings Forwards App A.B & C documents
 FELTON, J ff Division of Rules and Records, 83/10/31
 ROGENBAUN, D M Technical Analysis Corp 19pp 22193 292 24X
 Fiche 50~000.83/10/31.8402090003
- -8402070142 Braft trip rept of 780321-22 site visits re const schedules & in-progress const activities observation. Fuel load dates for Units 1 & 2 are Nov 1781 & Nov 1780, respectively Related info encl # NRC No Detailed Affiliation Given 83/10/31. NRC No Detailed Affiliation Given 22175-342 24% Fiche 50-000,83/10/31.8402070003
- 8402010410 Generic Ltr 84-04 to all operating PWR licensees, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops. Eve list encl EISENHUT, D 9 Division of Licensing, 84/02/01. Consolidated Edison Co. of New York, Inc. 39pp 22177 087 24X Fiche 50-000,84/02/01.8402010410.
- 9402100239 Forwards responses to requests for add1 info re loop bypass valves & RCPB, Responses will be included in Feb 1984 Amend 7 to FSAR.

 GOUNSIL, M. G., BISHOP, R. W. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities 84/02/01 YOUNGBLOOD, B. J. Licensing Branch 1 13pp. 22179 310 24X Fiche 30-423,84/02/01,8402100239
- 402220486 Forwards summary of Geosciences Branch 840105 meeting & related info re util position on New Brunswick Earthquake CGUNGIL.W G., BISHOP.R W. Northeast Utilities Service Co. (subs. of Northeast Utilities 84/02/01 YOUNGBLOOD, B. J. Licensing Branch 1. 11pp 22340 100 24X Fiche 50-423,84/02/01,8402220486
- 02130390 Requests comments on preliminary rept, "Review of Millstons 3 Probabilistic Safety Study," dtd 840123 Written response requested by 840306 YOUNGBLOOD, B. J. Licensing Branch i 84/02/03 COUNBL.W Q Northeast Nuclear Energy Co (subs of Northeast Utilities). 2pp. 22261:114 24X Fiche 50-423,84/02/03,8402150390
- -8402150392 "Review of Millstone 3 Probabilistic Bafety Btudy," incomplete preliminary draft # Lawrence Livermore Laboratory, 84/01/25, 200pp. 22261.116 24X Fichs. 50-423.84/02/03,8402150090

- 8402080247 Forwards responses to 840106 request for add1 info re probabilistic safety study Info suppls util 831107 & 840110 responses Min safety injection flow sufficient to maintain vessel mixture level core GDUN91L.W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) CDUN91L.W 9 Northeast Utilities 84/02/06 YDUN08L00D.B J Licensing Branch 1 111pp 22133 335. 24X Fichs 50-423, 84/02/06.8402080247
- B402230178 Notification of 840214 meeting w/util in Bethesda.MD to discuss util response to 241 0 series safety review questions

 DOGLITTLE.E.L. Licensing Branch i 84/02/10 YOUNOBLOOD.B.J. Licensing Branch i 3pp 22379 176 24X Fiche 50-423.84/02/10, 8402230178
- 8402230249 Notification of 840221 meeting w/util in Bethesda,MD to discuss program for maintaining safe shutdown capability BOOLITTLE, E. L. Licensing Branch i 84/02/10 YOUNGBLOOD, B. J. Licensing Branch i 3pp 22380 017 24X Fiche 50-423,84/02/10,8402230249
- B402240005 Forwards probabilistic safety study input listings for listed computer codes/cases W/o encl COUNBIL.W G Northeast Nuclear Energy Co. (subs of Northeast Utilities) COUNBIL.W G Northeast Utilities 84/02/10 YOUNOBLOOD, B J Licensing Branch 1 ip 22375 240 24X Fiche 50-423.84/02/10,8402240005
- 8402240017 Forwards boron dilution analysis, per Reg Quide 1 70 & NUREQ-0880, for failures in chemical & vol control sys, based on Westinghouse 918 setpoints & limits No design changes recommended or implied W/o encl CQUNSIL, W 0 Northeast Utilities 84/02/10 YQUNQBLQQD, B, J Licensing Branch 1 ip 22375 244 24X Fiche 50-423, 84/02/10, 8402240017.
- 8402240240 Forwards info requested in second facility staffing questionnaire distributed at NRC 840126 meeting w/OL applicants CDUNSIL.W G Northeast Utilities 84/02/10 YOUNGBLOOD, B J Licensing Branch i 4pp 22374 328 24X Ficher 50-423,84/02/10,8402240240
- 8402230384 Notification of 840223-24 meetings w/util in Bethesda.MD to discuss responses to 430 0 series safety review questions DOOLITTLE, E. L. Licensing Branch 1 84/02/14 YOUNDBLOOD, B. J. Licensing Branch 1 3pp 22376.170. 24X Fiche 50-423,84/02/14,8402230384
- B4022303B6 Notification of B40227 meeting w/util & 8&W in Boston,MA to discuss structural design & to conduct site tour.

 DOOLITTLE,E L Licensing Branch i 84/02/14 YOUNDBLOOD,B J Licensing Branch 1. 5pp 22376 164 24X Fiche.50-423,84/02/14,8402230386
- 8402280294 Forwards Westinghouse topical rept, "Use of Process Noise Measurements to Determine Response Characteristics of Protection Sensors in US Plants:" for review & approval. COUNSILM.9, Northeast Nuclear Energy Co (subs. of Northeast Utilities) COUNSILM 9, Northeast Utilities 84/02/15 YOUNGBLOOD, 8. J Division of Licensing. 2pp 22405 292. 24X Fiche 50-423.84/02/15:8402280294
- C. Utility Environmental Report (ER), amends & correspondence
- 8402020132 Forwards Amend 5 to environ rept OL stage, in response to NRC 831007 request for add1 info COUNSIL.W @ Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL.W @ Northeast Utilities. 84/01/20 YDUNGSLOOD, B J Licensing Branch 1 2pp 22055, 343 24% Fiche 50-423,84/01/20,8402020152
- --8402020156 Amend 5 to environ rept OL stage * Mortheast Nuclear Energy Co. (subs of Northeast Utilities) 84/01/31 140pp 22055, 345. 24% Fichs 50-423,84/01/20,8402020152.
- E NRC Bafety Evaluation Report (BER), suppls & correspondence
- 8402220417 Forwards schedule of meetings to resolve 831220 draft SER open items Schedule will be supplemented as necessary to support development of remaining NRC SER input.
 COUNSIL. M. O. Northeast Utilities 84/01/30, VOUNOBLOOD, B. J. Licensing Branch 1, 2pp 22340.031, 24X Fiche 80-423, 84/01/30, 8402220417

- 8402230186 Notification of 840216 meeting w/util in Bethesda.MD to discuss response to fire protection unresolved items in draft 88R Section 9 5 1 DODLITTLE.E L Licensing Branch 1 84/02/10 YOUNGBLOOD.B J Licensing Branch 1 3pp 22379 193 24X Fiche 30-423,84/02/10.840223018A
- 8402230371 Notification of 840214 & 15 meetings w/util in Waterford.CT to discuss response to draft SER Chapter 12 unresolved items & to tour facility DOGLITTLE.E L Licensing Branch 1 84/02/10 YOUNGBLOOD.B J Licensing Branch 1 3pp 22376 173 24X Fiche 50-423.84/02/10, 8402230371
- F. Becurity, medical, emergency & fire protection plans
- B402020351 Forwards corrected response to Question 420 6 previously submitted w/831216 ltr re clarification of emergency response capabilities per Buppl 1 to NUREG-0737 (Generic Ltr B3-33)
 CDUNBIL, W.O. Northeast Nuclear Emergy Co (subs of Northeast Utilities) B4/01/13 YOUNOBL.00D.B J Licensing Branch 1 37pp 22053 213 24X Fiche 50-423, B4/01/13, 8402020351
- 8402090108 Forwards Rev 2 to suitability, training & qualification plan Rev withheld MDFRIO, M.D. Northeast Utilities Service Co (subs of Northeast Utilities) 84/02/03 DENTON, HR Office of Nuclear Reactor Regulation, Director ip 22163 314 24X Fiche 80-245,84/02/03,
- 8402140135 Responds to NUREQ-0737. Suppl 1 re requirements for emergency response capabilities/emergency operations facilities Util intends to revise Section 7 1 of emergency plan whaddition of listed wording CDUNSIL, W Q Northeast Utilities 84/02/03 EISEN-UT.D Q Division of Licensing 2pp 22219 038 24X Fiche 50-000,84/02/03.8402140135
- B402230186 Notification of 840216 meeting w/util in Bethesda, MD to discuss response to fire protection unresolved items in draft SER Section 9 5 1 DDOLITTLE, EL Licensing Branch 1 84/02/10 YOUNGBLOOD, B. J Licensing Branch 1 3pp. 22379 193 24X Fiche 50~423,84/02/10,8402230186
- G Inspection reports, 1E Bulletins & correspondence
- B312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl. JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co. of New York
- 8402080335 Forwards IE Insp Rept 50-423/83-19 on 831017. No violations observed MARTIN.T. Division of Engineering & Technical Programs 84/01/26 COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 22130 265 24X Ficher 50-423,84/01/26,8402080335.
- 8402070334 Forwards IE Insp Rept 50-423/83-20 on 831030-1210.No violations observed.

 STAROSTECKI.R. Division of Project & Resident Programs 84/01/27.

 COUNSIL.W G. Northeast Nuclear Energy Co (subs of Northeast Utilities). 2pp. 22161 085 24X Fiche 50-423.84/01/27.8402090334
- --8402090344 IE Insp Rept 50-423/83-20 on 831030-1210 No violation observed Major areas inspected potential significant deficiencies, containment liner fire damage repairs, & corrective actions on previous insp findings REBELOWSKI,T A Region i, Office of Director. ELSABSER.T. Division of Project & Resident Programs, 84/01/25 9pp. 22161 087. 24X Fichs: 50-423,84/01/27,8402090334.
- 8402160270 Forwards IE Insp Rept 50-423/83-21 on 831128-1202. No violations observed MARTIN.T T Division of Engineering & Technical Programs 84/02/01 COUNSIL.W G. Northeast Nuclear Energy Co (subs of Northeast Utilities). 2pp. 22275-111. 24X Fiche.50-423.84/02/01.8402160270
- --8402160282 IE Insp Rept 50-423/83-21 on 831128-1202 No violations identified Major areas inspected; actions on previous inap findings & observation & evaluation of work performance resafety-related piping, structural steel & supports GRAY, E. H., MANOLY, K. A., VARELA, A. A. Region i. Office of Director 84/01/27 9pp. 22275:113. 24X Fiche: 50-423,84/02/01.8402160270

- B401190016 IE Info Notice B4-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000.B4/02/03,8401190016
- 8401170017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers" Bvc list encl DEYDUNG.R C Director's Office Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177
- 8401170041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R) " Svc list enc! JDRDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365 259 24X Fiche 50-000,84/02/13,8401190041
- B401190039 IE Info Natice B4-08, "10CFR30 7, 'Employee Protection '"
 Svc list encl
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B4/02/14 Consolidated Edison Co of New
 York, Inc. 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- 8401170045 IE Info Notice 83-63, Suppl 1. "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JDRDAN, F. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp. 22366 142 24X Fiche 50-000.84/02/15, 8401170045
- 8402290297 Forwards IE Insp Rept 90-423/83-22 on 831211-840121 No violations noted STARRSTECKI, R Division of Project & Resident Programs 84/0R/15 COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 22427 828 24X Fichs 50-483.84/02/15.8408290257
- --B402270264 IE Insp Rept 50-423/83-22 on 831211-B40121 No violation noted Major areas inspected licensee action on previous insp findings, repts of potential significant deficiencies, fuel blig concrete void repair & svc water tests REBELOHBKI,T A Region 1, Office of Director ELBABER, T Division of Project & Resident Programs B4/02/15 7pp 22427 230 24X Fiche 50-423,84/02/15,8402290257
- 8401170062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc. 116pp 22366 024 24% Fiche 50-000.84/02/21,8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies" Syc list encl.
 JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/24 Consolidated Edison Co of New York, Inc. 118pp. 22430:304 24X Fichs 50-000,84/02/24,8401190066
- 8402290210 Confirms 840305-16 const team insp in areas of GA.design control.project mgt,const control & procurement MARTIN.T T Division of Engineering & Technical Programs 84/02/24 COUNSIL.W O Northeast Nuclear Energy Co (subs. of Northeast Utilities) 2pp 22425 113 24X Fiche 50-423,84/02/24,8402290210
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
 Syc list encl.
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp. 22431:060 24X Fiche 50~000.84/02/27,8401190067
- S Reportable occurrences. LERs & related correspondence
- 8402140378 Requests add1 info re Part 21 rept dtd 831108 concerning wear ring failure in auxiliary feedwater pump furnished to facilities info requested within 25 days POTAPOVS.U Region 4. Office of Director 83/11/30 PATTY.D F. Bingham-Willamette Co. ip 22221 250 24X Fiche 50-000,83/11/30,8402140378
- --8402140422 Supplemental Part 21 rept re wear ring failure in auxiliary faedwater pumps, per 831130 request for addl info Wear rings will be replaced on returned units w/AISI 420 wrought matl List of pumps in similar svc w/same wear ring encl. PATTY, D. F. Bingham-Willamette Co 89/12/20 Region 4, Office of Director 2pp 22221 251. 24X Fiche 50-000, 83/11/30, 3400240208

- 8402060211 Significant Deficiency Rept 5D-38 re containment liner stud spacing Initially reported on 830617 Calculations forwarded for review GOUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W O Northeast Utilities 84/01/24 MCRLEY, T E Region 1, Office of Director 1p, 22087 157 24X Fiche 50-423,84/01/24,8402060211
- 840R280233 Potential Significant Deficiency Rept SD-50 re
 phase-to-phase electric fault in motor control ctr Initially
 reported on 840116 Engineering evaluation by SEW continuing
 Next rept will be provided by 840S15
 COUNSIL, W O Northeast Utilities 84/02/15 MVRLEY, T E Region I
 Office of Director 2pp 22399 313 24X Fiche 50-423.84/02/15,
 8402280233

V Operator Examinations

- B402230245 Notification of B40222 meeting w/util in Bethesda.MD to discuss simulator exam & training programs Proposed agenda enc!

 DODLITTLE.E.L. Licensing Branch | 84/02/10 YOUNGBLOOD, B J Licensing Branch | 4pp 22380 020 24% Fiche 50-423,84/02/10, B402230245
- DOCKET 50-424 VOOTLE ELECTRIC GENERATING PLANT
- A Application/construction stage documents & correspondence
- 8402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A, B & C documents FELTON, J M Division of Rules and Records 83/10/31 ROSEMBAUN, D M Technical Analysis Corp 17pp 22193 292 24X Fiche 50-000, 83/10/31, 8402090003
- ---8402090234 Handwritten graph & calculations re presperational testing & const activities

 * NRC No Detailed Affiliation Given, B3/05/17. 4pp
 22176 253 24% Fiche 50-000/83/10/21/8402090003
- B402030071 Notification of 840206 meeting w/util in Waynesboro, QA to allow staff to view parts of site related to hydrologic area of licensing review
 MILLER, MA Licensing Branch 4 84/01/25 ADENSAM, E 0. Licensing Branch 4 3pp 22091 049 24X Fiche 50-424,84/01/25,8402030071
- 8402070526 Forwards request for add1 info re hydrologic engineering safety review Info should be provided by 840715 ADENSAM.E O Licensing Branch 4 84/01/26 FOSTER.D Georgia Power Co 5pp 22141 326 24% Fiche 50-424, 84/01/26, 8402070526
- 8402030400 Amend to DL application, consisting of Amend 3 to FSAR, correcting errors in cross-references, typographical errors, incorrect units of measure, table column & row alignment FOSTER, D O Georgia Power Co 84/01/27 DENTON, H R. Office of Nuclear Reactor Regulation, Director, 7pp 22070 068 24X Fiche 50-424.84/01/27,8402030400
- B402140336 Confirms B40202 mgt meeting at site to discuss QA measures to improve subcontractor performance, per B40126 telcan Proposed Itinerary enci.

 O'REILLY, J.P. Region 2, Office of Director B4/01/31 KELLY, R.J. Georgia Pawer Co. 2pp. 22219 342 24X Fiche 50-424, B4/01/31, B402140336
- B402010410 Generic Ltr B4-04 to all operating PWR licensees, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Svc list encl. EIBENNUT, D. Division of Licensing. B4/02/01. Consolidated Edison Co. of New York, Inc. 57pp. 22177 087 24X Fichs 50-000.84/02/01.8402010410
- 8402149012 Advises that B31025 Westinghouse application requesting portions of RCS primary loop pipe breaks rept be withheld from public disclosure approved per 10CFR2 790 ADENGAME G Licensing Brench 4. 84/02/04. FOBTER D D. Georgia Power Co 2pp 22251.342. 24X Fiche 50-424,84/02/04.8402140012
- 8402170061 Notification of 840210 meeting w/Transamerica Delavat.Inc (TDI) in Bethesda:MD to discuss program plan proposed by TDI Owners Group to qualify diesel generators CARUSO:R Division of Licensing 84/02/06 BERLINGER.C Division of Licensing 2pp 22312 339 24X Ficks 50-000.84/02/06. 8402/70061

- 8402140238 Forwards revised procedure for clarification re compaction around pipes in Category 1 backfill Static cone penetrometer reading of 200 will be used to decide on concrete sand fill in limited spaces
 FGSTER.D D Georgia Power Co. 84/02/07 ADENSAM, E. G. Licensing Branch 4 2pp 22221 020 24X Fiche 50-424, 84/02/07, 8402140238
- 8402160396 Amend to application for DL.consisting of Amend 1 to environ rept - DL stage FOGTER.D O Georgia Power Co 84/02/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22273 224 24X Fiche 50-424.84/02/10.8402160396
- BA02230029 Forwards Amend 4 to CPPR-108 & CPPR-109, safety evaluation & notice of issuance & availability Amends transer ownership interests in facilities from Georgia Power Co to Municipal Electric Authority of Georgia ADENSAM, E. G. Licensing Branch 4 84/02/13 FOSTER, D. Georgia Power Co 4pp 22380 001 24X Fiche 50-424,84/02/13,8402230029,
- --8402230038 Amend 4 to CPPR-108 & CPPR-109, tranferring ownership interests in Pacilities from Georgia Power Co to Municipal Electric Authority of Georgia EIEENHUT.D @ Licensing Branch 4 84/02/13 4pp 22380 005 24X Fichs 50-424,84/02/13,8402230029
- ---8402230071 Bafety evaluation supporting Amend 4 to CPPR-108 & CPPR-109 * Office of Nuclear Reactor Regulation, Director 84/02/13 2pp 22380 009 24% Fiche 50-424,84/02/13,8402230029
- --B402230075 Notice of issuance & availability of Amend 4 to CPPR-108 & CPPR-109 ADENBAM,E 0 Licensing Branch 4 84/02/13 2pp 22380 011 24X Fiche 50-424,84/02/13,8402230029
- C Utility Environmental Report (ER), amends & correspondence
- 8402160376 Amend to application for OL, consisting of Amend 1 to environ rept — OL stage FOBTER, D. O georgia Power Co 84/02/10 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 22273 224 24X Fiche 50-424,84/02/10,8402160376
- --8402160410 Amend 1 to environ rept OL stage * Georgia Power Co 84/02/29 272pp 27273 226 24) Fiche 50-424,84/02/10.8402160396
- 8402160478 Forwards addl info in response to NRC 831128 acceptance review of environ rept W/three oversize maps. Aperture cards are available in FDR FORTER, D O Georgia Power Co 84/02/10. DENTON, HR Office of Nuclear Reactor Regulation, Director 6pp. 22273.001 24% Fiche 50-424,84/02/10,8402160498
- --8402160497 "Vegetation Map & Decision of Site in Burke County, GA for Environ Rept - OL Stage " CANDLER, W J Georgia Power Co 83/03/31, 60pp. 22273.006, 24X Fiche 30-424, 84/02/10,8402160498
- --B402160502 "Terrestrial Invertebrate Survey Burke County, GA: Jan-Nov 1981 Environ Rept - OL Btage Technical Document, " GUILL, © N Georgia Power Co B2/12/31 46pp 22293; 066 24X Fiche 50-424, B4/02/10, B402160498
- --8402160506 "Amphibian & Reptile Survey, Surke County, GA From Oct 1980 Aug 1981 Environ Rept OL Stage Technical Document " HILTZ, J W Georgia Power Co. 82/10/31, 22pp 22293, 112, 24X Fiche: 50-424, 84/02/10, 8402160498
- --8402160511 "Small Mammals Burvey, Burke County, GA From Nov 1980 -Aug 1981 Environ Rept - OL Stage Technical Document " WILTZ, J W Georgia Fower Co. 82/10/31, 17pp. 22293 134 24X Fichs 50-424, 84/02/10,8402160498.
- --8402160517 "Small Game Mammals & Furbearers Burveys, Burke County, QA From Nov 1780 - Bept 1781 Environ Rept - CL Stage " CANDLER, M. J. Georgia Power Co. 83/01/31. 11pp. 22293.151 24X Fiche 30-424.84/02/10.8402160498
- --B402160820 "White-Tailed Deer Cansus Environ Rept OL Stage Technical Document "
 BREECE, 6 A Oscraje Power Co 83/07/31 3ipp 22273.162 24%
 Fichs 50-424,84/02/10.8402160498.
- --B402160522 "Bird Study, Burke County, QA From Dec 1977 Through Sept 1981 for Environ Rept - OL Stage Technical Document " ALLEN, J.R., CANDLER, W.J., Georgia Power Co. 83/03/31. 303pp. 22273 193 24X Fiche: 50-424, 84/02/10, 8402160498.

- --8402160526 "Macroinvertebrate Survey of Bavannah River Burke County, GA Jan-Nev 1981 Environ Rept - CL Stage Technical Document " QUILL, 9 N Georgia Power Co 83/03/31 89pp 22294 144 24X Fiche. 30-424, 84/02/10, 8402160498
- --8402160328 "Impact of Const of Vogtle Electric Generating Plant on Aquatic Macroinvertebrate Populations of Beaverdam Creek, Jul 1973 Through June 1978 Environ Rept - OL Stage Technical Document " STAATB:A A , HOLDER:S D , NICHOLS:M C Georgia Power Co 83/04/30 17pp 22294 233 24X Fiche 50-424.84/02/10.8402160498
- --8402140531 "Beaverdam Creek Anadromous Fish Study, Burke County, GA From Mar 1977 Through May 1978 Environ Rept OL Stage Technical Document "
 WILTZ, J W Georgia Power Co 82/10/31 44pp 22294 273 24X
 Fiche, 50-424, 84/02/10, 8402160498
- --8402160336 "Beaverdam Crask Resident Fish Study, Burks County, GA From Jan 1977 Through Dec 1978 Environ Rept IL Stage Technical Document "
 WILTZ, J W Georgia Power Co 82/10/31 40pp 22294 317 24X Fiche: 50-424, 84/02/10,8402160498
- --8402160537 "Survey of Feeding Habits of Fishes in Savannah River, Burke County, GA From Oct 1980 Through Bept 1981 Environ Rept -OL Stage Technical Document " MIRACLER D Georgia Power Co 82/10/31 48pp 22275 001 24X Fiche 50-424, 84/02/10, 8402160498
- --9402160344 "Survey of Drifting Macroinvertebrates of Savannah River, Burke County, GA From Sept 1980 Through Aug 1981 Environ Rept - OL Stage Technical Document " NICHOLB.M C Georgia Power Co 63/05/31 15pp 22295 049 24X Ficha: 50-424, 84/02/10, 8402160498
- ---B402140545 "Burvey of Plankton Community of Savannah River, Burke County, OA From Jan-Sept 1981 Environ Rept - OL Stage " CDLLINS,T D Georgia Power Co 83/02/28 31pp 22295 064 24X Fiche: 80-424, 84/02/10, 8402160498
- --8402160550 "Action Plan for Burke County," final rept
 # Battelle Mamorial Institute, Columbus Laboratories. 83/01/31
 tRipp. R2275:120 24X Fiche 50-424,84/02/10.8402160498
- --8402160552 "Final Rept on Assessment of Syc Needs for Burke & Richmond Counties "

 Battelle Mamorial Institute: Columbus Laboratories 82/01/06 250pp 22275,241 24% Fiche: 50-424,84/02/10:8402160498

O Adjudicatory correspondence

- 8402020231 Notice of ASLB constitution COTTER, B.P. Atomic Safety and Licensing Board Panel 84/01/31 2pp. 22057 040 24X Fiche 50-424,84/01/31,8402020231
- B402:30227 Notifies that FSAR & environ rept re licensing proceeding to be transmitted by early nest wk
 JOINER, J. E. Troutman, Banders, Lockerman & Ashmore JOINER, J. E
 Georgia Power Co B4/02/09, STANGLER, C Georgians Against Nuclear
 Energy 1p. 22244:151, 24X Fiche 50-424, 84/02/09, 8402150227
- 8402150150 Answer to petitions for leave to intervene & requests for hearing Notices of appearance & Certificate of Svc encl BLAME, E. L. Georgie Power Co. BLAME, E. L. Blaw. Pittman. Potts & Trombridge. 84/02/10. Atomic Safety and Licensing Board Panel 13pp 22249:160 24X Fiche.50-424,84/02/10.8402150150.
- 8402150155 Requests that license hearings be held in Burke County or in Augusta, 9A Affected citizens should not be made to travel great distances

 DELAIGLE, R. Burks County, 9A. 84/02/10 Office of the Secretary of the Commission 1p 22245:322 24X Fiche. 50-424,84/02/10,8402150155
- 8402150167 Requests public hearing to intervene in activation & operation of facility be held in Waynesboro vicinity in order that people directly affected by plant may attend.

 BELOACH, & L Affiliation Not Assigned 84/02/10 Office of the Recretary of the Commission ip 22245,213. 24X

 Fiche: 50-424,84/02/10,8402150167
- B402220240 Response to petitions for leave to intervene & requests for hearing of Campaign for Prosperous Georgia, Georgians Against Nuclear Energy & Coastal Citizens for Clean Environ Cartificate of Svc encl PERLIB.R 0. Hearing Branch 3, 84/02/15, Atomic Safety and Licensing Board Panel 14pp. 22337 133 ,24X Ficher 50-424,84/02/15,8402220240.

- 8402240073 Requests withdrawal of 840126 petition to intervene KIRKLAND.D Georgia, State of 84/02/20 Office of the Secretary of the Commission ip 22374 150 24% Fiche 50-424.84/02/20. 8402240073
- B40223005B Recommends that ASLB establish dates for filing of contentions, for replies thereto & for holding of special prehearing conference Prehearing conference should be set 30 days after reply filing Certificate of Svc enci TROWBRIDGE, G.F. Shaw. Pittman, Potts & Trowbridge TROWBRIDGE, G.F. Georgia Power Co. B4/02/21 MARGULIES, M.B. PARIS, O.H. LINEMBERGER, G. Atomic Safety and Licensing Board Fanel 2pp 22362 130 24X Fiche 50-424.84/02/21,8402230058
- 8402280401 Requests that hearings on contentions be held in Atlanta rather than in Waynesboro or Augusta to accommodate local residents Certificate of Svc encl JOHNSON, T Campaign for Prosperous Georgia 84/02/24 Atomic Safety and Licensing Board Panel 3pp 22404 259 24x Fiche 50-424,84/02/24,8402280401

I Financial information

- 8402140453 Forwards Annual Financial Rept for 1782 & related financial qualification info.per 740428 application for amend to CPPR-109 & CPPR-109 VAZQUEZ.R O. ADAMS.L C Municipal Electrical Authority of Georgia 84/02/10 ADENBAM.E C Licensing Branch 4 4pp 22221 309 24X Fichs 50-000,84/02/10,8402140453
- --8402140459 Annual Financial Rept for 1982 Related financial qualification info encl MANLEY.O N . STOKLEY.D L Municipal Electrical Authority of Georgia 82/12/31 683pp 22221 313 24X Fiche 50-000.84/02/10. 8402140453

K Utility Final Bafety Analysis Report (FSAR) & amends

- 8402030400 Amend to DL application, consisting of Amend 3 to FSAR, correcting errors in cross-references, typographical errors, incorrect units of measure, table column & row alignment FOSTER, D O Georgia Power Ca 84/01/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 22070 068 24X Fiche 30-424, 84/01/27, 8402030400
- --B402030417 Amend 3 to FSAR * Georgia Power Co 84/01/31 354pp 22070 076 24X Fiche 50-424.84/01/27.8402030400

M Antitrust correspondence

- 8402140480 Forwards purchase, amend, assignment & assumption agreement between util & Municipal Electric Authority of Georgia FOBTER, D. Q. Georgia Power Co Branch 4 75pp 22226 112 24X Fiche 50-424,84/02/09,8402140480
- G Inspection reports, IE Bulletins & correspondence
- 8312120153 IE Info Notice 84-06. "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24% Fiche 50-000.84/01/25.8312120153
- B402140493 Ack receipt of 840116 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-424/83-21 & 50-425/83-21 LEWIS.R C Division of Project & Resident Programs 84/01/26 KELLY.R J Georgia Power Co 1p 22221 117 24X Fiche 50-424,84/01/26.8402140493
- --B40214049B Responds to NRC B31213 ltr re violations noted in IE Insp. Repts 50-424/83-21 % 50-425/83-21 Corrective actions drawing change notice issued to correct thermal movement data for pipe support VI-1204-197-H00B.Rev 1
 FOBTER, D G Georgia Power Co. B4/01/16 LENIS.R C Region 2. Defice of Director 3pp 22221 118 24X Fiche 50-424, B4/01/26, B402140493
- ---8402140501 Forwards IE Insp Repts 50-424/83-21 & 50-425/83-21 on 831114-17 & notice of violation LEWIS, C Division of Project & Resident Programs 83/12/13 KELLY, R J Georgia Power Co 2pp 22221 121 24X Fiche 50-424,84/01/26,8402140493
- --8402140506 Notice of violation from insp on 831114-17 * Region 2, Office of Director 83/12/13 2pp 22221 123 24X Fiche 50-424,84/01/26,8402140493

- --8402140512 IE Insp Repts 50-424/83-21 & 50-425/83-21 on 831114-17 Violations noted failure to follow procedures for hanger
 - insp LIU.W C Region 2. Office of Director BLAKE, J J Division of Emergency Preparedness & Materials Safety 83/12/Q6 App 22221 125 24X Fichs 50-424,84/01/26,8402140473
- 8401190016 IE info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 630103) 84/02/03 Consolidated Edison Go of New York, Inc 117pp 22114 177 24X Fiche 50-000,84/02/03,8401190016
- RAD1190017 IF Bulletin R4-01. "Cracks in BWR Mark I Containment Vent
 - Headers "Svc list encl Headers "Svc list encl DEYQUNO,R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 136 24% Fichs 50-000.84/02/03,840119g017
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Bafe Shutdown Sys (10CFR50, App R) " Syc list encl
- JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc. 124pp 22365 259 24X Fiche 50-000,84/02/13,8401190041
- 840:1190039 IE Info Notice 84~08, "10CFR50 7, 'Employee Protection '"

 8vc list encl

 JORDAN,E L. Division of Emergancy Preparedness & Engineering

 Response (Post 8300:03) 84/02/14 Consolidated Edison Co of New

 York Inc 115gp 22365-141 24X Fiche 50~000,84/02/14,840:1190039
- 8401170045 IE Info Notice 83-63. Suppl i, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc 118pp 22366:142 24X Fiche 50-000.84/02/15,8401170045
- 8402280008 Summarizes 840202 mgt meeting at site re GA measures taken to improve subcontractor performance Attendee list onci 6'REILLY, JP Region 2, Office of Director 84/02/16 KELLY, R J Georgia Pawer Co 3pp 22402 111. 24X Fiche 50-424,84/02/16.
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pg 22366:024 24X Fiche 50-000,84/02/21,8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies"

 8vc list encl

 JORDAN.E.L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/02/24 Consolidated Edison Co of New

 York, Inc 115pp 22430:304 24X Fiche, 50-000,84/02/24,8401190066
 - 01190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals,"
 - vc list encl Division of Emergency Preparedness & Engineering septime (Post 830103) 84/02/27 Consolidated Edison Co. of New ork, Inc. 120pp 22431 060 24X Fichs, 50-000, 84/02/27, 8401170067
 - Reportable occurrences, LERs & related correspondence
 - D2030299 Part 21 rept re potential problem w/battery ground detector relay ITE 278 Portions of solid state circuitry can be overstressed under certain operating conditions. Users of relays will be notified List of users of relay encl.

 DUVALL, D D Brown Boveri Corp. (subs. of Brown Boveri & Co., Ltd.)

 34/01/05 DEYGMOR C. Director's Office. Office of Inspection and Enforcement Opp R2067:1R2 24X Fiche 50-000,84/01/05.8402030299
- 32070393 Requests that NRC investigate design reliability of J2070373 Requests that NRC investigate design residuality or emergency diesel generators supplied by Transamerica emergency diesel generators supplied by Transamerica delivery of first vessel in May 1981 Related info encl MOLINAJ C Falcon Carriers, Inc 64/02/01 DENTON, M.R. D. Nuclear Reactor Regulation, Director 63pp 22096:057, 24X Office of Fiche 50-000,84/02/01.8402070393
- B40215024i Interim deficiency repts re unverified computer code for main feedwater pipe supports. Issue expected to be resolved to final rept submitted by 840309 FOBTER, P. O., Georgia Power Co. B4/02/07 O'REILLY, J. P. Ragion 2 Office of Director. Zpp. 22244, 149 24X Fiche. 50-424, 84/02/07, 840215024i
- 402150405 Deficiency rept re engineering evaluation of Pullman Power Products hanger reinsp findings Reportability will be determined when engineering avaiuation completed on 840518 FOBTER D O Georgia Power Co 84/02/07, Region 2, Office of Director, ip 22242 087 24X Fiche: 50-424,84/02/07,8402150405

- B401190033 Board Notification B4-020 forwards info re Transamerica Delaval, Inc emergency diesel generator problems Attendance list meeting handouts & slides encl E18ENHUT, D & Division of Licensing 84/02/13 PALLADINO Commissioners 102pp 22332 202 24% Fiche 50-000, 84/02/13, 8401170053
- 8402220530 Part 21 rept re defective DBR & DBRV standby diesel generator turbocharger thrust bearing lubrication Deficiency not corrected by Bys mod New recommendation will be sent to customers by 840330 BOYER, R E Transamerica Delaval, Inc 84/02/15 Director Office, Office of Inspection and Enforcement Spp 22332 in Fiche 50-000,84/02/15,8402220530 15 Director's 5pp 22332 182 24x
- 8402280378 Final deficiency rept re failure of embed plate base metal Initially reported on 831219 Investigation of sampling of installed plates & supports concluded event isolated & not reportable per 10CFR50 55(a) & Part 21 FORTER, D O Georgia Power Co 84/02/15 O'REILLY, J P. Region 2, Office of Director 1p 22402 231 24X Fiche 50-424,84/02/15, Office of Director 8402280378
- 8402280701 Notification of 84030B meeting w/Transamerica Delaval.Inc (TDI) Gumers Group in Wading River.NY to discuss TDI proposed program plan to qualify diesel generators CARUSO,R Division of Licensing 84/02/23 BERLINGER,C Division of Licensing 2pp 22414 340 24X Fiche 50-000,84/02/23, B402280701
- DOCKET 50-425 VOGILE ELECTRIC GENERATING PLANT
- A Application/construction stage documents & correspondence
- 8402090003 Responds to FOIA request for const completion dates for vuctor plants currently under const & analyses containing sstimates based on inclusion of Caseload Forecast Panel mestings Forwards App A.B & C documents FELTON, J M Division of Rules and Records 83/10/31 RDSENBAUM, D M Technical Analysis Corp 17pp 22193 292 Fichs 50-000,83/10/31,8402090003 19pp 22193 292 24x
- --8402070234 Handwritten graph & calculations re preoperational testing & const activities

 * NRC No Datailed Affiliation Given 83/05/17 4pp
 22196 253 24% Fiche 50-000,83/10/31,8402090003
- B402030071 Notification of B40206 meeting w/util in Waynesboro, 0A to allow staff to view parts of site related to hydrologic area of licensing review MILLER, MA Licensing Branch 4 84/01/25 ADENBAM, E Q Licensing Branch 4 3pp 22091 049 24X Firhe 50-424, 84/01/25, 8402030071.
- B402070526 Forwards request for add1 info re hydrologic engineering safety review Info should be provided by B40715
 ADENBAME 0 Licensing Branch 4 B4/01/26 F08TER, D Georgia Fower Co 5pp 22141 326 24X Fiche 50-424,84/01/26,8402070526.
- B40R030400 Amend to OL application consisting of Amend 3 to FBAR, correcting errors in cross-references typographical errors, incorrect units of measure, table column & row alignment FDSTER.D O Georgia Power Co 84/01/27 DENTON, HR Office of Nuclear Reactor Regulation, Director 7pp 22070 068 24% Fiche 50-424,84/01/27,8402030400
- 8402140336 Confirms 840202 mgt meeting at site to discuss GA measures to improve subcontractor performance.per 840126 telcon. Proposed filnerary encl O'REILLY.J P Region 2. Office of Director 84/01/31 KELLY.R J Georgia Power Co 2pp 22219 342. 24X Fiche 50-424,84/01/31,8402140336
- B402010410 Generic Ltr 84-04 to all operating PWR licensees, CP holders & applicants for CPs re-safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Bvc list encl EIBENHUT, D. O Division of Licensing, B4/02/01 Consolidated Edison Co. of New York, Inc. 59pp 22177-087 24X Fiche: 50-000,84/02/01,8402010410
- 8402140012 Advises that 831025 Westinghouse application requesting portions of RCS primary loop pipe breaks rapt be withheld from public disclosure approved per 100FR2 770 ADENSAM, E 0 Licensing Branch 4. 84/02/06 FOSTER, D D. Georgia Power Co 2pp 22251 342, 24X Fiche 50-424, 84/02/06, 8402140012
- 8402170061 Notification of 840210 meeting w/Transamerica Delaval, Inc (TDI) in Bethesda. MD to discuss program plan proposed by TDI Owners Group to qualify dissel generators CARUBO.R Division of Licensing 84/02/06. BERLINGER, C. Division of Licensing 2pp 22312:337 24X Fiche 50-000,84/02/06,

- B40214023B Forwards revised procedure for clarification re compaction around pipes in Category 1 backfill Static cone penetrometer reading of 200 will be used to decide on concrete sand fill in limited spaces.

 FDSTER.D C Georgia Power Co 84/02/07 ADENSAM.E Q Licensing Branch 4 2pp 22221 020 24X Fiche 50-424.84/02/07,840214023B
 - 5bb
- 8402160396 Amend to application for OL, consisting of Amend 1 to environ rept OL stage FORTER, D O Georgia Power Co 84/02/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22273 224 24% Fiche: 50-424, 84/02/10, 8402160396
- 8402230027 Forwards Amend 4 to CPPR-108 & CPPR-109, safety evaluation & notice of issuance & availability Amends transfer ownership interests in facilities from Georgia Power Co to Municipal Electric Authority of Georgia ADENGAM.E 0 Licensing Branch 4 84/02/13 FOSTER, D Georgia Power Co 4pp 22380 001 24X Fiche 50-424.84/02/13.8402230029
- --8402230038 Amend 4 to CPPR-108 & CPPR-109, tranferring ownership interests in facilities from Georgia Power Co to Municipal Electric Authority of Georgia
 Electric Authority Granch 4 84/02/13 4pp 22380 005 24% Fiche 50-424,84/02/13,8402230029
- --8402230071 Safety evaluation supporting Amend 4 to CPPR-108 & CPPR-109
 # Office of Nuclear Reactor Regulation, Director 84/02/13, 2pp
 22380.009 24X Fiche 50-424,84/02/13,8402230029
- --B402230075 Notice of issuance & availability of Amend 4 to CPPR-108 & CPPR-109 ADENBAM.E G Licensing Branch 4 B4/02/13. 2pp 22380'011 24X Fiche: 50-424, 84/02/13.8402230029
- C Utility Environmental Report (ER), amends & correspondence
- 8402160396 Amend to application for OL.consisting of Amend i to environ rept OL stage FOSTER.D.O Georgia Power Co. 84/02/10 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22273 224 24X Fiche: 50-424,84/02/10:8402160396
- --8402160410 Amend 1 to environ rept OL stage * Georgia Power Co 84/02/29, 272pp 22273 226 24X Fiche. 50-424, 84/02/10, 8402160396
- 8402160498 Forwards add1 info in response to NRC 831128 acceptance review of environ rept.W/three oversize maps Aperture cards are available in PDR. FDSTER.D D. Georgia Power Co 84/02/10 DENTON,H R. Office of Nuclear Reactor Regulation, Director App 22293 001 24X Fiche: 50-424,84/02/10,8402160498
- --8402160499 "Vagetation Map & Decision of Site in Burke County, GA for Environ Rept OL Stage " CANDLER, W J Georgia Power Co 83/03/31, 60pp 22293 006 24X Fiche 80-424, 84/02/10, 8402160498
- --8402160502 "Terrestrial Invertebrate Survey Burks County, QA, Jan-Nov 1981 Environ Rept DL Stage Technical Document " GUILL. Q.N Georgia Power Co 82/12/31 46pp. 22293.066 24X Fiche 50-424,84/02/10.8402160498.
- --8402160506 "Amphibian & Reptile Burvay, Burke County, GA From Oct 1980 Aug 1981 Environ Rept OL Stage Technical Document,"
 WILTZ.J.W. Georgia Power Co 82/10/31 22pp 22293, 112 24X
 Fichs: 50-424, 84/02/10, 8402160498.
- --8402160511 "Small Mammals Burvey, Burke County, 9A From Nov 1980 -Aug 1981 Environ Rept OL Stage Technical Document " WILTZ, J W. Georgia Fower Co. 82/10/31 17pp 22293; 134 24X Ficha 50-424, 84/02/10.8402160498
- --8402160517 "Small Came Mammals & Furbearers Burveys, Burke County, CA From Nov 1980 Sept 1981 Environ Rept DL Stags, " CANDLER, N. J. Georgia Power Co., 83/01/31, 11pp. 22293 151 24X Fichs: 80-824, 84/02/10, 8402160498
- ---8402160520 "White-Tailed Deer Census Environ Rept DL Stage Technical Document." BREECE.C.A. Georgia Power Co. 83/07/31 31pp 22293 162 24X Fiche: 50-424,84/02/10,8402160498.
- --8402160522 "Bird Study, Burke County, OA From Dec 1977 Through Bapt 1981 for Environ Rept OL Stage Technical Document."
 ALLEN, J. R.: CANDLER, W. J. Georgia Power Co., 83/03/31 303pp 22293 193 24% Fiche. 50-424, 84/02/10. 8402160498

- ~-8402160526 "Macroinvertebrate Survey of Savannah River Borke County, GA Jan-Nov 1981 Environ Rept Dt. Stage Technical Document " GUILL, G N Georgia Power Co 83/03/31 89pp 22294 144 24X Fiche 50-424, 84/02/10. 8402160498
- --8402160528 "Impact of Const of Vogtle Electric Generating Plant on Aquatic Macroinvertebrate Populations of Beaverdam Creek, Jul 1973 Through June 1978 Environ Rept OL Stage Technical Document" BITAATS, A A , HOLDER, S D , NICHOLS, M C Georgia Power Co 83/04/30 17pp 22294 233 24% Fiche 50-424.84/02/10.8402160498
- ---8402160531 "Beaverdam Creek Anadromous Fish Study, Burke County, GA From Mar 1977 Through May 1978 Environ Rept OL Stage Technical Document " Document " WILTZ.J W Georgia Pawer Ca 82/10/31 44pp 22294 273 24% Fiche 50-424,84/02/10,8402160498
- --8402160536 "Beaverdam Craek Resident Fish Study. Burke County, GA From Jan 1977 Through Dec 1978 Environ Rept OL Stage Technical Document " Dacument " WILTZ.JW Georgía Power Co 82/10/31 40pp 22294 317 24X Ficho 50-424,84/02/10,8402160498
- -8402160539 "Survey of Feeding Habits of Fishes in Savannah River,Burke County,GA From Oct 1980 Through Sept 1981 Environ Rept -OL Stage Tachnical Document." HIRACLE,R D Georgia Power Co 82/10/31 48pp 22295 001 24x Fiche 50-424,84/02/10,8402160498
- --8402160544 "Burvey of Drifting Macroinvertebrates of Savannah River, Burke County, GA From Sept 1980 Through Aug 1981 Environ Rept OL Stage Technical Document " NICHOLB.M C Georgia Power Co 83/05/31 15pp 22295 049 24X Fiche 50-424,84/02/10.8402160498
- ~~8402160545 "Survey of Plankton Community of Savannah River, Burke County, 0A From Jan-Sept 1981 Environ Rept DL Stage " COLLINS, T D Georgia Power Co 83/02/28 31pp 22295 064 24X Fiche 50-424,84/02/10,8402160498
- --8402160580 "Action Plan for Burke County," final rept
 # Battelle Memorial Institute, Columbus Laboratories
 121pp 22275, 120 24X Fiche 80-424, 64/02/10, 8402160498 83/01/31
- --8402140552 "Final Rept on Assessment of Svc Needs for Burke & Richmond Counties Battelle Memorial Institute, Columbus Laboratories Opp 22275 241 24X Fiche 30-424,84/02/10,8402160498 82/01/04

9 Adjudicatory correspondence

- 8402020231 Notice of ASLB constitution COTTER.B P Atomic Safety and Licensing Board Panel 2pp 22007 040, 24x Fiche 30-424.84/01/31.8402020231
- 8402150227 Notifies that FSAR & environ rept re licensing proceeding to be transmitted by early next wk JUINER, J E Troutman, Sanders, Lockerman & Ashmore JUINER, J E Opengia Power Co. 8402/09 STANOLER, C Georgians Against Nuclear Energy ip 22244 151 24X Fiche 50-424, 84/08/09, 8402150227
- 8402150150 Answer to petitions for leave to intervene & requests for hearing Notices of appearance & Certificate of Svc encl BLAKE, E. L. Georgia Power Co. BLAKE, E. L. Shaw, Pittman, Fotts & Troubridge 84/02/10 Atomic Safety and Licensing Board Panel 13pp. 22249 160 24X Fiche 50-424,84/02/10.8402150150.
- 8402150155 Requests that license hearings be held in Burke County or in Augusta, GA Affected citizens should not be made to travel great distances

 DELATOLE.R. Burke County, GA 84/02/10 Office of the Secretary of the Commission. 1p 22245 322 24X Fiche 50-424,84/02/10.

 8402150155
- 8402150167 Requests public hearing to intervent in activation & operation of facility be held in Waynesboro vicinity in order that people directly affected by plant may attend DELOACH. Q L Affiliation Not Assigned. 84/02/10. Office of Secretary of the Commission ip 22245 213. 24X Fichs: 50-424.84/02/10.8402150167 Office of the
- 8402220240 Response to petitions for leave to intervent & requests for hearing of Campaign for Prosperous Georgia, Georgians Against Nuclear Energy & Goastal Citizens for Clean Environ Certificate of Syc encl PERLIB, R O Hearing Branch 3 84/02/15, Atomic Bafety and Licensing Board Panel 14pp 22339 133 24X Fiche 50-424, 84/02/15, 8402220240

- 8402240073 Requests withdrawal of 840126 petition to intervene KIRKLAND, D Georgia, State of 84/02/20 Office of the Secretary of the Commission ip 22374 L50 24% Fiche 50-424,84/02/20.
- B40223005B Recommends that ASLB establish dates for filing of contentions: for replies thereto & for holding of special prehearing conference Prehearing conference should be set 30 days after reply filing Certificate of Suc encl
 TROWBRIDGE.0 F Shaw. Pittman, Putts & Trowbridge TROWBRIDGE.0 F Georgia Power Co. 84/02/21 MARGULIES.M B, PARIS.O H,
 LINENDERGER.0 Atomic Safety and Licensing Board Panel 2pp
 22362 130 24X Fiche 50-424,84/02/21,8402230058
- B402280401 Requests that hearings on contentions be held in Atlanta rather than in Waynesbord or Augusta to accommodate local residents Certificate of Svc and Johnson, T Campaign for Prosperous Georgia 84/02/24 Atumic Safety and Licensing Board Panel 3pp 22404 259 24X Fiche 50-424,84/02/24.8402280401

I Financial information

- 8402140453 Forwards Annual Financial Rept for 1982 & related financial qualification info.per 740628 application for amend to CPPR-108 & CPPR-109
 - CPPR-108 & CPPR-109
 VAZQUEZ.R O. ADAMS,t. C. Municipal Electrical Authority of Georgia
 84/02/10 ADEN84M,E G. Litensing Branch 4 App. 22221 307 24X
 Ficha 50-000,84/02/10,8402140453
- ---8402140459 Annual Financial Rept for 1982 Related financial qualification info encl MANLEY, G. N., STOKLEY, D. L. Municipal Electrical Authority of Georgia 62/12/31 483pp 22221 313 24X Fiche 50-000,84/02/10,8402140453
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8402030400 Amend to DL application.comsisting of Amend 3 to FSAR. correcting errors in cross-references.typographical errors. incorrect units of measure.table column & row alignment FOSTER.D O Georgia Power Co 84/01/27 DENTON.H R Office of Nuclear Reactor Regulation. Director 7pp 22070 048 24% Ficha 50-424.84/01/27,8402030400
- --8402030417 Amend 3 to FSAR * Gargie Power Co 84/01/31 354pp 22070 076 24X Fiche 50-424,84/01/27,8402030400
- M Antitrust correspondence
- 8402140480 Forwards purchase amend assignment & assumption agreement between util & Municipal Electric Authority of Georgia FOBYER: D O Georgia Power Co 84/02/09 ADENSAM, E G Licensing Branch 4 95pp 22226 112 24X Fiche 50-424.84/02/09.8402140480
- @ Inspection reports, IE Bulletins & correspondence
- B312120153 IE Info Notice 84-04, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000.84/01/25, 8312120153
- 8402140493 Ack receipt of 840116 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-424/83-21 & 50-428/803-21

 LEWIB.R C Division of Project & Resident Programs 84/01/26, KELLY,R J Georgia Power Co ip 22221 117. 24X

 Fiche 50-424,84/01/26.8402140493
- --8402140498 Responds to NRC 831213 ltr re violations noted in IE Insp Ropts 50-424/83-21 & 50-425/83-21 Corrective actions drawing change notice issued to correct thermal movement data for pipe support VI-1204-199-H009.Rev 1 POBTER.D O Georgia Power Co 84/01/16 LEHIS.R C Region 2, Office of Director 3pp. 22221 118 24X Fiche 50-424,84/01/26, 8402140493
- 8402140501 Forwards IE Insp Repts 50-424/83-21 & 50-425/83-21 on B31114-17 & notice of violation LEWIS.R C Division of Project & Resident Programs 83/12/13 KELLY.R'J Georgia Power Co 2pp 22221 121 24X Fiche 50-424,84/01/26,8402140493

- --B402140312 IE Insp Repts 50-424/83-21 & 50-425/83-21 on 831114-17 Violations noted failure to follow procedures for hanger insp
 - INSP LIU.W C Region 2. Office of Director BLAKE, J J Division of Emergency Preparedness & Materials Safety 83/12/06 App 22221 125 24% Fiche 50-424,84/01/26,8402140493
- B401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/03 Consolidated Edison Co of Nau / York, Inc 119pp 22114 179 24X Fiche 50-000.84/02/03, B401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEYDUNG.R C Director's Office Office of Inspection and Enforcement B4/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 156 24X Fiche 50-000.84/02/03.8401190017
- B401190041 IE Info Natice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R) " Swc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 23365 259 24X Fiche 50-000.84/02/13,8401190041
- B401190039 IE Info Nutice B4-08, "10CFR50 7, 'Employee Protection '"

 Svc list encl

 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B4/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24X Fiche 50-000, B4/02/14, B401190039
- 840i190045 IE Info Natice 83-63. Suppl 1. "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl.
 JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York. Inc. 118pp 22366 142 24X Fiche 50-000.84/02/15, 8401190045
- 8402280008 Summarizes 840202 mgt meeting at site re GA measures taken to improve subcontractor performance Attendee list encl
 O'REILLY.J P Region 2. Office of Director 84/02/16 KELLY.R J
 Georgia Power Co 3pp 22402 iii 24X Fiche 50~424,84/02/16,8402280008
- 8401190042 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN,E L. Division of Emeryency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000.84/02/21,8401190052
- 8401190066 IE Info Notice 84-11. "Training Program Deficiencies "
 8vc list encl
 JURDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B4/02/24 Consolidated Edison Co. of New
 York, Inc 1156p 22430 304 24X Fiche 50-000.84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Boft Seat Valva Seals "
 Svc list encl
 JORDANNE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060 24X Fiche 30-000.84/02/27, 8401190067
- 5 Reportable occurrences, LERs & related correspondence
- 8402030279 Part 21 rept re potential problem w/battery ground detector relay ITE 278. Portions of solid state circuitry can be overstressed under certain operating conditions Users of relays will be notified List of users of relay enci.

 DUVALL. D D. Brown Boveri Corp (subs of Brown Boveri & Co., Ltd.)

 84/01/05 DEYOUNG, R C Director's Office. Office of Inspection and Enforcement 3pp 22067 122 24% Fiche 50-000, B4/01/05, B402030279
- 8402070393 Requests that NRC investigate design reliability of emergency diesel generators supplied by Transamerica Delaval.Inc. Engine problems have been experienced since delivery of first vessel in May 1981 Related info encl MOLINA, J C Falcon Carriers. Inc 84/02/01 DENTON, H R Office of Nuclear Reactiar Regulation, Director 63pp. 22096 057 24X Fiche 50-000,84/02/01,8402070393
- B402190241 Interim deficiency repts re unverified computer code for main feedwater pipe supports Issue expected to be resolved & final rept submitted by 840309 FDBTER.D D Georgia Power Co 84/02/07 O'REILLY, J P Region 2, Office of Director 2pp 22244 149 24X Fiche 50-424, 84/02/07, 8402150241
- B402150405 Deficiency rept re engineering evaluation of Pullman Power Products hanger reinsp findings Reportability will be determined when engineering evaluation completed on 840518 FORTER.D D Georgia Power Co 84/02/07 Region 2. Office of Director 1p 22242 087 24X Fiche 50-424.84/02/07.8402150405

- 8401190053 Board Notification 84-020 forwards info re Transamerica Delaval. Inc emergency diesel generator problems Attendance list, meeting handouts & slides encl EISENHUT. D 0 Division of Licensing 84/02/13 PALLADINO Commissioners 102pp 22332 202 24X Fiche 50-000,84/02/13, 8401190083
- 8402220330 Part 21 rept re defective DSR & DBRV standby diesel generator turbocharger thrust bearing lubrication Deficiency not corrected by sys mod New recommendation will be sent to customers by 840330

 BOYER.R E Transamerica Delaval. Inc 84/02/15

 Defice. Office of Inspection and Enforcement 5pp 22332 182 24x

 Fiche 50-000:84/02/15.8402220330
- 8402280378 Final deficiency rept re failure of embed plate base metal Initially reported on 831219 Investigation of sampling of installed plates & supports concluded event isolated & not reportable per 10cFR50 55(e) & Part 21 FOBTER, D.O. Georgia Power Co. 84/02/15 D'REILLY, J.P. Region 2, Office of Director ip 22402 231 24x Fiche 50-424, 84/02/15, 8402280378
- B4022B0701 Notification of B4030B meeting w/Transamerica Delaval Inc (TDI) Owners Group in Wading River, NY to discuss TDI proposed program plan to qualify disel generators CARUBOR Division of Licensing 84/02/23 BERLINGER.C Division of Licensing 2pp 22414 340 24X Fiche 50-000, 84/02/23, 84022B0701
- DOCKET 50-433 UC-SANTA BARBARA RESEARCH REACTOR
- R Periodic operating reports & related correspondence
- 8402020302 "Annual Rept of Operations, 1983 " W/840130 ltr PROFID A E , KROES, R J California, Univ of, Santa Barbara, CA 84/01/24, 5pp 22055 169 24% Fiche 50-433,84/01/24,8402020302
- 8402240235 Forwards 1982 annual rept of reactor operations RDDEB.R J California, Univ of, Santa Barbara, CA 84/01/26 NRC - No Detailed Affiliation Given 1p 22374 322 24X Fiche: 50-433, 84/01/26, 8402240235
- DOCKET 50-434 SURRY POWER STATION, UNIT 3
- S Reportable occurrences, LERs & related correspondence
- 8402070345 Part 21 rept re linear converter device w/possible generic defect Initially reported on 840114 Written notifications issued Customer responses should be received by 840331 Final rept will be submitted by 840430 DDDBON. J.P Pacific Air Products Co 84/01/30 Director's Defice. Office of Inspection and Enforcement 2pp. 22114.299 24X Fiche 50-280.84/01/30.8402070365
- --B402070373 Part 21 rept re linear converter device w/possible generic defect. Initially reported on 840116 Preliminary analysis indicates excessive wear of brass shaft guides Next rept will be submitted within 90 days Supporting info sncl DOBSON. J P Pacific Air Products Co 84/01/17. PDTAPOVS, U. Ragion 4, Office of Director ABPP 23114 301 24X Fiche 50-000, 84/01/30, 8402070365.
- DOCKET 50-435 SURRY POWER STATION, UNIT 4
- 8 Reportable occurrances. LERs & related correspondence
- B402070345 Part 21 rept re linear converter device w/possible generic defect. Initially reported on B40116 Written notifications issued Customer responses should be received by 840331. Final rept will be submitted by 840430.

 DDB0N, J P Pacific Air Products Co B4/01/30 Director's Defice. Office of Inspection and Enforcement 2pp 22114 299 24X Fiche: 50-280.84/01/30.8402070365
- -B402070373 Part 21 rept re linear converter device w/possible generic defect. Initially reported on 840116 Preliminary analysis indicates excessive wear of brass shaft guides Next rept will be submitted within 90 days Bupporting info encl DODSON. J P Pacific Air Products Co 84/01/17 POTAPOVS, U Region 4. Office of Director ESPP. 22114 301 24X Fiche. 50-000, 84/01/30, 8402070365.

- DOCKET STN-50-437 FLOATING NUCLEAR PLANT
- O Inspection reports, IE Bulletins & correspondence
- 8312120153 IE Info Notice 84-04, "Steam Binding of Auxiliary Feedwater Pumps" Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120153
- 8401190016 IE Info Notice 84-07. "Design-Basis Threat & Review of Vehicular Excess Controls " Byc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830102) B4/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000,84/02/03,8401190016
- B401190017 JE Bulletin B4-01. "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 84/02/03 Cansolidated Edison Co of New York, Inc 102pp 22177
- 8401190041 JE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50.App R) " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New Yorks Inc 124pp 22365 259 24X Fiche 50-000.84/02/13,8401190041
- 8401190039 IE Info Notice 84-08, "10CFR50 7, `Employee Protection '"
 Svc list encl
 JORDAN,E L Division of Emproency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- 8401170045 IE Info Nutice 83-63, Suppl 1, "Potential Failures of Westinghouse Type 5A-1 Differential Relays " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc 118pp 22366 142 24X Fiche 50-000, 84/02/15, 8401170045
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Bet Below Manufacturer Recommended Value " Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co. of New York, Inc. 116pp. 22366 024 24% Fichs 50-000,84/02/21,8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies"

 Evc list encl

 JORDAN,E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/02/24 Consolidated Edison Co of New

 York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- B401170067 IE Info Notice B4-12, "Failure of Boft Seat Valve Seals "
 Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060 24X Fiche 50-000.84/02/27.8401190067
- DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT I
- A Application/construction stage documents & correspondence
- 840/2070003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caselaad Forecast Panel meetings Forwards App A, B & C documents
 FELTON, J M Division of Rules and Records 83/10/31
 ROSENBAUM, J M Technical Analysis Corp 17pp 22193 272 24X
 Fiche: 50~000.63/10/31.8402090003
- --8402070090 Handwritten notes re facility fuel load preparation * NRC - No Detailed Affiliation Given 83/10/31 7pp 22194 090 24X Fiche 50-000, B3/10/31, 8402090003,
- --8402090094 Handwritten notes re fuel load preparation & const activities * NRC - No Detailed Affiliation Given 78/04/12 7pp 22194 127 24X Fiche. 50-000, 83/10/31.8402090003
- --B402090114 Forwards T Abell notes re SD Freeman ltr.T Abell marked-up ltr & 780427 trip rept Realistic fuel load date forecast important HALLER.N M Office of Management and Program Analysis 78/06/06 GOBBICK.L V Office of the Executive Director for Operations Spp. 22194 18B 24% Fiche 30-000/83/10/31.8402090003

- --B402090117 Requests meeting in June to discuss regulations or methods of operation changed to improve schedules & costs of nuclear plants w/o sacrificing safety concerns Meeting on 780412~13 re estimated fuel load date summarized FREEMAN.8 D Tennessee Valiey Authority 78/05/25 HENDRIE, J M NRC ~ No Detailed Affiliation Given 3pp 22194 190 24X Fiche 50-000,83/10/31,8402090003
- --8402090120 Summary of 780412-13 meetings at site w/util re const scheduling & observation of in-progress const activities Projected fuel load dates are Jul 1981 & 1982 for Units 1 & 2.respectively PIKE.W J Office of Management and Program Analysis 78/04/27 Office of Management and Program Analysis 7pp 22174 193 243 Fiche 30-000.83/10/31.8402090003
- 8402010410 Generic Ltr B4-04 to all operating PMR licensees.CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PMR primary main loops Svc list encl EISENHUT.D G Division of Licensing 84/02/01 Consolidated Edison Co of New York. Inc 57pp 22177 087 24X Fiche S0-000.84/02/01/04/02010410
- 8402070206 Advises that date of B40321 acceptable for meeting w/NRC to discuss program plan for detailed control roum design reviews Concurrence on meeting date requested MILLS.L M Tennessee Valley Authority 84/02/01 ADENSAM, E Licensing Branch 4 ip 22102 212 24X Fiche 90-000, 84/02/01, 8402070206
 - 02070211 Forwards response to Items 2 1 & 2 2 of Generic Ltr 61-21.

 'Natural Circulation Cooldown ' Natural circulation cooldown an be accomplished w/a violating other pressure-temp inits Response to Item 2 3 will be submitted on 850301

 IILLB.L M Tennessee Valley Authority B4/02/03 ADENSAM, E icensing Branch 4 22pp 22102 152 24X Fiche 50-439, 84/02/03, 3402070211
- 402170061 Notification of 840210 meeting w/Transamerica Delaval Inc (TDI) in Bethesda.MD to discuss program plan proposed by TDI Cumers Group to qualify diesel generators CARUSO.R Division of Licensing 84/02/06 DERLINGER.C Division of Licensing 2pp 22312 339 24X Fiche 50-000,84/02/06,8402170061
- 8402170051 Forwards fecility staffing surveys in response to B40112 itr Addl info requested during 840126 meeting currently in preparation MILLS, L M Tennessee Valley Authority 84/02/09 ADENSAM. E Licensing Branch 4 8pp 22301 077 24X Fiche 50-000, 84/02/09, 8402170051
 - 02170152 Forwards revised responses to environ Questions 290 7 & 290 9. per 831i18 ltr Eight ERCW pumps located in intake pumping station Sound pressure level data encl MILLS.L M Tennessee Valley Authority 94/02/14 ADENSAM.E. Licensing Branch 4 5pp 22299 063 24X Fiche 50-43B.84/02/14,8402/70152
- 2 Utility Environmental Report (ER), amends & correspondence
- 3402080226 Forwards responses to environ questions, per 831108 ltr Responses re safety aspects will be provided in upcoming FBAR amends Updated environ rept will be provided by late 1783 MILLS, L M Tennessee Valley Authority 84/01/31 ADENSAM: E Licensing Branch 4 12pp 22130-067 24X Fiche 50-438,84/01/31, 8402080226
- F Security, medical, emergency & fire protection plans
- 8402060382 Forwards Rev 7 to generic security personnel training & qualification plan Rev withheld (ref 10CFR73 21)
 MILLB,L M Tennesses Valley Authority 84/01/19 O'REILLY,J P
 Region 2. Office of Director ip 22086 317 24X
 Fiche 50-000,84/01/19,8402060382
- B402130316 Forwards Rev B to generic security personnel training & qualification plan Rev withhold MKLLS.L M Tennessee Valley Authority. B4/01/27 O'REILLY, J P Region 2. Office of Director 1p 22197 149 24X Fiche 50-000.84/01/27.8402130316
- J Insurance & indemnity information
- 8402210242 Forwards Endorsement 22 to NELIA Policy NF-258 Amended site description also encl DUCK, J. R. Marsh & McLennan, Inc. 84/02/13, SALTZMAN, J. Assistant Director for State & Licensee Relations 3pp. 22315-355 24X Fiche 50-438,84/02/13,8402210242

- Q Inspection reports. IE Bulletins & correspondence
- B402140077 Forwards IE Insp Repts 50-370/83-52.50-371/83-4i. 50-438/83-32 & 50-439/83-32 on 831212-15 No violations or deviations noted VERRELLI.D M Division of Project & Resident Programs 84/01/09 PARRIS.H G Tennessee Valley Authority 2pp 22217 255 24X Fiche 50-000.84/01/09.8402140077
- --8402140084 IE Insp Repts 50-3970/83-52,50-391/83-41,50-438/83-32 & 50-439/83-32 on 831212-15 No violations or deviations noted Major areas inspected licensee action on previous enforcement matters
 WRIOHT,R W Region 2, Office of Director UPRIOHT,C M Division of Engineering & Operational Programs 84/01/04 5pp 22217 237 24X Fiche 50-000,84/01/09,8402140077
- B312120153 IE Info Notice B4-0A, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN:E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 64/01/25 Consolidated Edison Co. of New York, Inc. 120pp 22058 001 24% Fiche 50-000:84/01/25,8312120153
- 8402280157 Forwards IE Insp Repts 50-438/83-33 & 50-439/83-33 on 831206-31 No violations or deviations noted VERRELLI.D M Division of Project & Resident Programs 84/01/27, PARRIS,H G Tennessee Valley Authority 2pp 22400 216 24X Fiche 50-438,84/01/27.8402280157
- ---8402280161 IE Insp Repts 50-438/83-33 & 50-437/83-33 on 831206-31 No violations or deviations noted Major areas inspected const surveillance, licensee identified items & actions on previous enforcement matters
 YORK, J W . BRANCH, M W . Region 2, Office of Director JULIAN, C A Division of Project & Resident Programs 84/01/26 4pp 22400.218 24X Fiche 50-438,84/01/27.8402280157
- 8402150355 Updates B31122 response to IE Bulletin B3-06 re nonconforming matts supplied by Tube-Line Corp Subj matts supplied to facilities by Capitol Pipe & Steel Products Co MILLB,L M Tennessee Valley Authority B4/02/02 O'REILLY,J P. Region 2, Office of Director 118pp 22243 001 24X Fiche 50-000,84/02/02,8402150385
- 8401170016 IE Info Notice 84-07. "Design-Basis Threat & Review of Vehicular Excess Controls " 8vc list encl JORDAN.E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000.84/02/03.8401170016
- 8401190017 IE Bulletin 84-01. "Gracks in BWR Mark I Containment Vent Headers " Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 156. 24X Fiche 50-000.84/02/03.8401190017
- B401190041 IE Info Notice 84~09. "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50.App R) " Svc list encl. JORDAN.E L Division of Emergency Preparedness & Engineering
 - encl. JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc. 124pp 22365 259 24X Fiche 50-000,84/02/13,8401190941
- 8401190037 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection'" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/14 Consolidated Edison Co. of New York, Inc. 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- B401190045 IE Info Notice B3-63, Suppl 1, "Potential Failures of Westinghouse Type BA-1 Differential Relays " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post B 830103) 84/02/15 Consolidated Edison Co of New York, Inc 118pp 22366 142. 24X Fiche 50-000.84/02/15,8401190045
- 8402230223 Forwards Rev i to Technical Instruction BLTI-PSI-i.
 "Preservice Insp Program, Bellefonte Nuclear Flant Unit i."
 per NRC 800414 ltr
 MILLS.L.M Tennessee Valley Authority 84/02/15 ADENSAM.E
 Licensing Branch 4 2pp 22051:304 24% Fiche:50-438,84/02/15,8402230223
- --B402230233 Rev 1 to Technical Instruction BLTI-PBI-1, "Preservice Into Program Bellefonte Nuclear Plant Unit 1." GUALLS, A M Tennessee Valley Authority 83/11/04 175pp 22351-304 24X Fiche, 50-438.84/02/15.8402230223
- B401170062 IE Info Notice B4-10, "Motor-Operated Valve Torque Buitches Set Below Manufacturer Recommended Valve." Bvc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21. Consolidated Edison Co. of New York, Inc. 116pp 22366 024 24X Fiche 50-000,84/02/21,8401170062

- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies"
 Svc list encl
 JORDAN, EL Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- 84011900A7 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
- Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/27 Consolidated Edison Co. of New York, Inc. 120pp 22431 060 24% Fiche 50-000.84/02/27,8401190067
- 9 Reportable occurrences, LERs & related correspondence
- B40214037B Requests addl info re Part 21 rept dtd 83110B concerning wear ring failure in auxiliary feedwater pump furnished to facilities Info requested within 25 days POTAPOVB, U Region 4. Office of Director 83/11/30 PATTY, D F Bingham-Willamette Co ip 22221 250 24% Fiche 50-000, 83/11/30, 840214037B
- --B402140422 Supplemental Part 21 rept re wear ring failure in auxiliary feedwater pumps, per B31130 request for add1 info Wear rings will be replaced on returned units w/AISI 420 wrought matl List of pumps in similar svc w/same wear ring encl PATTY.DF Bingham-Willamette Co 83/12/20 Region 4, Office of Director 2pp 22221 251 24X Fiche 50-000,83/11/30,8402140398
- 8401050474 First interim deficiency rept re orientation of Automatic Switch Co solenoid-operated valves Initially reported on 83130 Safety-related pneumatic control valves will be reviewed Next rept by 841017
 MILLB.L M Tennessee Valley Authority 83/12/28 D'REILLY, J P Region 2, Office of Director 2pp 21727 340 24X
 Fiche 50-438,83/12/28,8401050494
- 8402030011 First interim Deficiency Rept NCR 2494 re omitted shim in cable splices Initially reported on 831228 Investigation under way. Next rept will be submitted by 840801 MILLS.L M Tennesses Valley Authority 84/01/26 O'REILLY, J. P Region 2, Office of Director 2pp 22068 194 24X Fiche: 50-438,84/01/26,8402030011
- 8402030013 Pirst interim Deficiency Rept NCR 2684 re length of in-core monitoring sys piping & gauge Initially reported on 831230 Bequence control chart submitted to B&W for review Next rept will be submitted by 840709 MILLS, L.M Tennessee Valley Authority 84/01/26, 0'REILLY, J P Region 2. Office of Director. 2pp. 22068 192, 24X Fiche 50-438,84/01/26,8402030013
- B402080200 Third interim deficiency rept re lack of Bingham-Williamette Co QA program for spere parts Initially reported on 830307. Corrective actions narroused to two listed options Next rept by 850114 Also reported per Part 21 MILLS, L.M. Tennessee Valley Authority B4/01/30, D'REILLY, J.P. Region 2, Office of Director. 2pp 22130 152 24X Fiche, 50-438,84/01/30,8402080200
- B402080197 Fourth interim deficiency rept re deficient pipe supports Initially reported on B11215 Support design lead drawings w/zero in thermal movement column in unrestrained direction revised to remove zeros Next rept by 840731 MILLS.L.M. Tennessee Valley Authority 84/01/31, 0'REILLY.J P Region 2. Office of Director. 2pp. 22130 150 24X Fiche. 50-438.84/01/31,8402080197.
- 8402070393 Requests that NRC investigate design reliability of emergency diesel generators supplied by Transamerica Delaval, Inc Engine problems have been experienced since delivery of first vessel in May 1981 Related info enci MOLINA, J C. Falcon Carriere, Inc. 84/02/01 DENTON.H.R (Nuclear Reactor Regulation, Director 63pp 22096 057 24) Fiche 50-000,84/02/01,8402070393. Office of 24X
- 8402140432 Becond supplemental deficiency rept re bonnet studs improperly torqued on DHR valves. Initially reported on 81222 Completion not expected until 840915 due to missing bonnet studs. Also reportable per Fart 21.

 MILLS.L.M Tennesses Valley Authority 84/02/01. O'REILLY, J P Region 2. Office of Director ip. 22227:140 24X Fiche: 50-438,84/02/01.8402140432
- 8402140351 Second interim deficiency rept re missing O-ring seals on flexible conduit Initially reported on 830906, Procedure BNP-GCP-3 32 prepared to verify compliance of field installed flexible conduit connectors. Next rept by 841107, MILLS.L.M. Tennessee Valley Authority 84/02/02 O'REILLY, J. P. Region 2, Office of Director. 2pp 22220 111, 24% Ficha: 50-438,84/02/02,8402140351.

- 8402140071 Final deficiency rept re inability to identify grade of nuts due to orientation Initially reported on 830126 Random sampling identified 60 rejectable nuts Remaining nuts acceptable as installed MILLS.L M Tennessee Valley Authority 84/02/03 D'REILLY.J P Region 2. Office of Director 2pp 22217 189 24X Fiche 50-438.84/02/03.8402140071
- 8402130397 First interim deficiency rept re lengths of flex conduit extensions not as specified Initially reported on 840112 Installation info will be provided Next rept will be submitted by B40B13
 MILLS, L M Tennessee Valley Authority 84/02/07 MILLS, L M Tennessee Valley Authority 84/02/07 MILLS, L M Tennessee Valley Authority 84/02/07 AV Fiche 50-438.84/02/07.8402130397 D'REILLY, J P
- 8401190053 Board Notification 84-020 forwards info re Transamerica Delawal. Inc emergency diesel generator problems Attendance lists meeting handouts & slides encl EIBENHUT.D G Division of Licensing 84/02/13 PALLADINO Commissioners 102pp 22332 202 24% Fiche 50-000, 84/02/13, 8401190053
- 8402220031 Sixth interim deficiency rept re potentially overstressed embedded plates Embedded plate sample now being reviewed Naxt rept expected by 840619
 MILLS,L M Tennessee Valley Authority 84/02/14, O'REILLY,J P Region 2, Office of Director Ip 22337 273 24X
 Fiche 50-438,84/02/14,8402220031
- 8402220128 Fourth interim deficiency rept re lack of environ qualification of equipment in auxiliary bldg due to potential failure of startup & recirculation sys Initially reported on 820422 Drawings revised Next rept by 850603 MILLS,L M Tennessee Valley Authority 84/02/14 G'REILL Region 2. Office of Director 2pp. 22337 254. 24X Fiche 50-438,84/02/14,8402220128 O'REILLY, J P
- 8402220175 Fifth interim deficiency rept re nonconservative calculation method for general Const Spec G-32 violations Initially reported on 820528 Sampling data review in progress Next rept will be submitted by 840619
 MILLS,L. M. Tennessee Valley Authority 84/02/15 0'REILLY.J P Region D. Diffice of Director ip 22340 310 24X
 Fiche. 50-438,84/02/15,8402220175
- 8402220315 First interim deficiency rept re global coor max pipe movements Initially reported on 840118. Util presently revisoing all isometric drawings & skewed nonglobal coordinate sys Next retravected by 850424 MILLS, L M Tannessee Valley Authority 84/02/15 0 Region 2, Office of Director 2pp 22336 261 24X Fiche: 50-438, 84/02/15, 8402220315 5 G'REILLY, J P. 24X
- 8402220330 Part 21 rept re defective DBR & DSRV standby diesel generator turbocharger thrust bearing lubrication Deficiency not corrected by sys mod New recommendation will be sent to customers by 840330

 BOYER R E. Transamerica Delaval, Inc 84/02/15. Director Defice, Office of Inspection and Enforcement 5pp 22932 16 Fiche 50-000.84/02/15,8402220530
- 8402270087 First interim deficiency rept re use of nonconservative valve & pipe fitting adjustment factors for insulation weight calculations initially reported on 840124 Analysis verification checklist will be revised Next rapt by 850515 MILLS, L M Tennessee Valley Authority 84/02/16 D'REILLY, J. P. Region 2. Office of Director 2pp 22391 267 24X Fiche 50-438,84/02/16,8402270087
- B402270020 Third interim deficiency rept re GA on valve purchase orders by Atwood & Merrill, Initially reported on 830901 Valves not shipped Release of valves subj to favorable util insp rept results
 MILLS,L.M Tennessee Valley Authority. 84/02/17
 MILLS,L.M Tennessee Valley Authority. 84/02/17
 Region 2. Offics of Director 2pp 22387 358. 24X
 Fiche 50-438.84/02/17.8402270020 O'RETLLY, J. P
- 8402270357 Second interim deficiency rept re deficient squere root extractor modules for reactor protection sys mfg by Bailay Meter Co. initially reported on 831114. BMH requested to determine root cause Also reportable per Part 21 MILLS.L.M. Tennessee Vallay Authority 84/02/17 G'REILLY, J.P. Region 2. Office of Director 2pp. 22390.361. 24X Fichs 50-438,84/02/17.8402270357

- 8402270373 Third interim deficiency rept re defective B&W welds on baffle plates in core support assembly Initially reported on B30302 Results of joint inspenci Next rept by 850111 Also reparted per Part 21 MILLG.L M Tennessee Valley Authority B4/02/17 O'REILLY.J P Region 2. Office of Director 4pp 22391 026 24X Fiche: 50-438.84/02/17. 8402270393
- 8402270395 First interim deficiency rept re overtorqued conduit & conduit box support bolts Initially reported on 840124 Review in progress to datermine extent of problem Next rept will be submitted by 840504 MILLS.L M Tennessee Valley Authority 84/02/17 D'REILLY.J P Region 2. Office of Director 2pp 22391 184 24X Fiche 50-438.84/02/17.8402270395
- 8402270403 First interim deficiency rept re Levels A & B storage temp below 40 F limit Initially reported on 840124 Affected storage areas will receive addl heating & insulation Next rept will be submitted by 840316 MILLS.L M Tennessee Valley Authority 84/02/17 D'REILLY.J P Region 2, Office of Director 2pp 22391 180 24X Fiche 50-438.84/02/17,8402270403
- B4022B0701 Notification of B40300 meeting w/Transamerica Delaval, Inc (TDI) Owners Group in Mading River.NY to discuss TDI proposed program plan to qualify diesel generators CARUSO,R Division of Licensing. 84/02/23 BERLINGER,C. Division of Licensing 2pp 22414 340 24X Fiche 50-000,84/02/23, 84022B0701

V Operator Examinations

- 8402010337 Notification of contract execution "Use of TVA Reactor Simulator Facilities at Chattanooga, TN for Training on Browns Ferry, Sequeyah & Bellefonte Simulators " JESSUP, B Technical Assistance Contracts Branch FIN B-8717 83/12/27 SHOWE, 8 K Director's Office, Office of Inspection and Enforcement Ip 22059 229 24X Fiche 50-000, 83/12/27, 8402010337
- --8402010346 Ltr Contract NRC-05-84-153, "Use of TVA Reactor Simulator Facilities at Chattanooga, TR for Training on Browns Ferry, Sequoyah & Bellefonte Simulators: "awarded to TVA.
 MORTON, K.V Technical Assistance Contracts Branch FIN 8-8717
 83/12/29, JOHNSON, R. J. Tennessee Valley Authority App. 22059 230 24X Fiche 50-000.83/12/29,8402010337
- DOKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

Application/construction stage documents & correspondence

)2090003 Responds to FDIA request for const completion dates for nuclear plants currently under const & analyses containing istimates based on inclusion of Caseload Forecast Panel asetings. Forwards app A.B & C documents
'ELTON, J M Division of Rules and Records 83/10/31.
RGBENBAUM, D M Technical Analysis Corp 17pp 22193 292 24X Fiche. 50-000, 83/10/31. 8402090003

- 8402090090 Handwritten notes re facility fuel load preparation * NRC - No Detailed Affiliation Given 83/10/31 7pp. 22194 090 24X Fiche 50-000,83/10/31,8402090003
- B402070094 Handwritten notes re Fuel load preparation & const activities * NRC - No Detailed Affiliation Given 78/04/12 7pp. 22194 127 24X Fiche 50-000,83/10/31,8402090003
- 8402090114 Forwards T Abell notes re SD Freeman ltr:T Abell marked-up ltr & 780427 trip rept Realistic fuel load date forecast important HALLER:N M Office of Management and Program Analysis 78/06/06 GD891CK:L V Office of the Executive Director for Operations 5pp. 22194,188 24X Fichs 50-000.63/10/31.8402090003
- I402090117 Requests meeting in June to discuss regulations or methods of operation changed to improve schedules & costs of nuclear plants w/o sacrificing safety concerns Meeting on 780412-13 re estimated fuel load date summarfied FREEMAN.B D. Tennessee Valley Authority, 78/05/25. HENDRIE.J M NRC NO Detailed Affiltation Given 3pp. 22194.190 24X Fiche.50-000.83/10/31.8402090003.
- 402090120 Summary of 780412-13 meetings at site w/util re const scheduling & observation of im-progress const activities Projected fuel load dates are Jul 1981 & 1982 for Units 1 & 2:respectively PIKE, W J Défice of Management and Program Analysis. 78/04/27 Defice of Management and Program Analysis 7pp 22194.193. 24X Fiche. 50-000,83/10/31:8402090003

- 8402010410 Generic Ltr 84-04 to all operating PWR licensees, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Bvc list encl EISENHUT, D G Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc. 59pp 22177 087 24X Fiche 50-000.84/02/01,8402010410
- 8402070206 Advises that date of 840321 acceptable for meeting w/NRC to discuss program plan for detailed control room design reviews Concurrence on meeting date requested MILLS.L M Tennessee Valley Authority 84/02/01 ADENSAM.E Licensing Branch 4 lp 22102 212 24X Fiche 50~000,84/02/01. 8402070206
- 8402070211 Forwards response to Items 2 1 & 2 2 of Generic Ltr 81-21, "Natural Circulation Cooldown " Natural circulation cooldown can be accomplished w/o violating other pressure-tamp limits Response to Item 2 3 will be submitted on 850301 MILLS,L M Tennesses Valley Authority 84/02/03 ADENBAH.E Licensing Branch 4 22pp 22102 152 24X Fiche 50-438,84/02/03, 8402070211
- B402170061 Notification of 840210 meeting w/Transamerica Delaval, Inc (TDI) in Betheada. MD to discuss program plan proposed by TDI Cluners Group to qualify diesel generators GARUSO,R Division of Licensing 84/02/06 BERLINGER.C Division of Licensing 2pp 22312 339 24X Fiche 50-000,84/02/06,8402170061
- B40217005: Forwards facility staffing surveys in response to 840112 ltr Add1 info requested during 840126 meeting currently in preparation MILLS.L M Tennessee Valley Authority 84/02/09 ADENSAM.E Licensing Branch 4 Bpp 22301 077 24X Fiche 50-000,84/02/09,8402170051
- B402170152 Forwards revised responses to environ Questions 290 7 & 290 7, per 831118 itr Eight ERCW pumps located in intake pumping station Bound pressure level data enti MILLS.L. M Tennessee Valley Authority B4/02/14 ADENSAM, E Licensing Branch 4 5pp 22279 063 24X Fiche 90-438,84/02/14, ADENSAM, E 1400170157
- C Utility Environmental Report (ER), amends & correspondence
- B4020B0226 Forwards responses to environ questions.per 831108 ltr Responses re safety aspects will be provided in upcoming FSAR amends Updated environ rept will be provided by late 1985 MILLS.L M Tennessee Valley Authority 84/01/31 ADENSAM.E Licensing Branch 4 12pp 22130 067 24X Fiche 50-438.84/01/31. 84020B0226
- F Becurity, medical, emergency & fire protection plans
- 8402050382 Forwards Rev 7 to generic security personnel training & qualification plan Rev withheld (ref 10CFR73 21)
 MILLS.L.M Tennessee Valley Authority 84/01/19 D'REILLY, J P
 Region 2, Office of Director 1p 22086 317 24X
 Fiche 50-000.84/01/19,8402060382
- B402i303i4 Forwards Rev B to generic security personnel training & qualification plan Rev withheld MILLS.L M Tennessee Valley Authority B4/01/27, D'REILLY.J P Region 2. Office of Director 1p 22197.149 24X Fiche 50-000,84/01/27,8402i303i6
- J Insurance & indemnity information
- B402210242 Forwards Endorsement 22 to NELIA Policy NF-258 Amended site description also encl
 DUCK.J R. Marsh & McLennan, Inc 84/02/13 BALTIMAN, J Assistant
 Director for Btate & Licensee Relations 3pp 22315 355 24X
 Fiche 50-438.84/02/13.8402210242
- Q Inspection reports, IE Bulletins & correspondence
- 8402140077 Forwards IE Insp Repts 50-390/83-52,50-391/83-41, 50-438/83-32 & 50-439/83-32 on 831212-15 No violations or deviations noted VERRELLI, D M Division of Project & Resident Programs 84/01/09 PARRIS, H O Tennesse Valley Authority 2pp 22217-255 24X Fiche 50-000,84/01/09,8402140077
- --8402140084 IE Insp Repts 50-390/83-52, 50-391/83-41, 50-438/83-32 & 50-439/83-32 on 831212-15 No violations or deviations noted. Major areas inspected licenses action on previous enforcement matters WRIGHT.R W Region 2, Office of Director 84/01/04, 5pp 22217-237 24X Ficher 50-000,84/01/09,8402140077

- B312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New "--
- 8402280157 Forwards IE Insp Repts 50-438/83-33 & 50-439/83-33 on 831206-31 No violations or deviations noted VERRELLI.D M Division of Project & Resident Programs 84/01/27 PARRISH 0 Tennessee Valley Authority 2pp 22400 214 24X Fichs: 50-438,84/01/27,8402280157
- --8402280161 IE Insp Repts 50~438/83-33 & 50-439/83-33 on 831206-31 No violations or deviations noted Major areas inspected const surveillance, licensee identified items & actions on previous enforcement matters
 YORK.J W. BRANCH,H W. Region 2, Office of Director JULIAN,C A Division of Project & Resident Programs 84/01/26 4pp 22400 218 24X Fiche 50-438.84/01/27,8402280157
- B402150355 Updates 831122 response to IE Bulletin 83-06 re nonconforming matls supplied by Tube-Line Corp Subj matls supplied by Capitol Pipe & Steel Products Co MILLB.L.M Tennessee Valley Authority B4/02/02 O'REILLY, J.P. Region 2. Office of Director 118pp. 22243 001. 24X Fiche 50-000.84/02/02.8402150355
- B401170016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl URDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103). B4/02/03 Consolidated Edison Co. of New York, Inc. 119pp 22114 179 24X Fiche 50-000.84/02/03.8401170016
- 8401190017 IE Bullatin 84-01, "Gracks in BWR Mark I Containment Vent Headers." Svc list encl DEYDUNG.R C Director's Office, Office of Inspection and Enforcement B4/02/03 Consolidated Edison Co of New York, Inc 102pp 22177·156, 24X Fiche 50-000.84/02/03.8401190017
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R)" Syc list enci JDRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259 24X Fiche 50-000,84/02/13,8401190041
- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '"
 Svc list encl
 JORDAN,E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103), 84/02/14 Consolidated Edison Co of New
 York, Inc. 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- 8401170045 IE Info Notice 83-63, Suppl i: "Potential Failures of Mestinghouse Type 8A-1 Differential Relays " Bvc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc. 118pp 22366 142 24X Fichs 50-000,84/02/15,8401190045
- B401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Bet Below Manufacturer Recommended Value " 8vc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York. Inc 116pp. 22366:024 24X Fiche 50-000.84/02/21,8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies"
 Svc list encl.
 JORDAN, E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/24. Consolidated Edison Co. of New
 York, Inc. 115pp. 22430 304. 24X Fiche.50-000.84/02/24.8401190066
- B401170067 IE Info Notice 84-12, "Failure of Soft Seat Valve Beals" Swc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/27 Consolidated Edison Co of New York, Inc. 120pp 22431.060 24X Fiche. 50-000.84/02/27,8401190067
- 9 Reportable occurrences, LERs & related correspondence
- 8402140378 Requests addl info re Pert 21 rept dtd 831108 concerning wear ring failure in auxillary feedwater pump furnished to facilities Info requested within 25 days POTAPDVB.U Region 4, Office of Director 83/11/30 PATTY.D.F Binghem-Willematte Co ip 22221.200 24X Fiche 50-000, 83/11/30, 8402140378
- --8402140422 Supplemental Part 21 rept re wear ring failure in auxiliary feedwater pumps.per 83i130 request for add1 info. Wear rings will be replaced on returned units w/AISI 420 wrought mat1 List of pumps in similar svc w/same wear ring enc1 PATTY, D. F. Bingham-Willamatte Co. 83/12/20 Region 4, Office of Director 2pp 22221:231 24X Fiche 50-000, 83/11/30, 8402140279

- 8401030474 First interim deficiency rept re orientation of Automatic Suitch Co solenoid-operated valves Initially reported on B31130 Safety-related pneumatic control valves will be reviewed Next rept by 841019
 MILLS.L.M. Tennessee Valley Authority B3/12/28 O'REILLY.J.P. Region 2. Office of Director 2pp 21729 360 24X
 Fiche 50-438.83/12/28.8401050494
- 8402030011 First interim Deficiency Rept NCR 2494 re omitted shim in cable splices Initially reported on 831228 Investigation under way Next rept will be submitted by 840801 MILLS.L M Tennessee Valley Authority 84/01/26 O'REILLY, J P Region 2. Office of Director 2pp 22068 194 24X Fiche 50-438,84/01/26,8402030011
- 8402080200 Third interim deficiency rept re lack of Bingham-Williamette Co QA program for spare parts Initially reported on 830307 Corrective actions marrowed to two listed options Next rept by 85014 Also reported per Part 21 MILLS, L M Tennessee Valley Authority 84/01/30 O'REILLY, J P Region 2, Office of Director 2pp 22130 152 24X Fiche 50-438,64/01/30,8402080200
- 8402080197 Fourth interim deficiency rept re deficient pipe supports Initially reported on 811215 Support design load drawings w/tero in thermal movement column in unrestrained direction revised to remove zeros Next rept by 840701 MILLS.L M Tennessee Valley Authority 84/01/31 O'REILLY, J P Region 2. Office of Director 2pp 22130 150 24X Fiche: 50-438,84/01/31,8402080197
- 8402070393 Requests that NRC investigate design reliability of samengency diesel generators supplied by Transamerica Delaval, Inc Engine problems have been experienced since delivery of first vessel in May 1981 Related info encl MOLINAL J C Falcon Carriers, Inc 84/02/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 43pp 22076 057 24% Fiche 50-000,84/02/01,8402070393
- 8402140432 Second supplemental deficiency rept re bonnet studs improperly torqued on DHR valves Initially reported on Bi1222 Completion not expected until 840915 due to missing bonnet studs Also reportable per Part 21 MILLS, L M Tennessee Valley Authority 84/02/01 O'REILLY, J P Region 2. Office of Director ip 22227 140 24X Fiche 50-438,84/02/01,8402140432
- 8402140351 Becond interim deficiency rept re missing D-ring seals on flexible conduit Initially reported on 830706 Procedure BNP-GCP-3 32 prepared to verify compliance of field installed flexible conduit connectors Next rept by 841107 MILB.L.M Tennessee Valley Authority 84/02/02 0'REILLY, J.P. Region 2, Office of Director Rep 22220 111. 24X Fiche.50-438,84/02/02,8402140351.
- 8402140071 Final deficiency rept re inability to identify grade of nuts due to orientation. Initially reported on 830126. Random sampling identified 60 rejectable nuts. Remaining nuts acceptable as installed.

 MILLS.L.M Tennessee Valley Authority 84/02/03 G'REILLY, J.P. Region 2. Office of Director 2pp 22217 189 24X
 Fiche 50-438,84/02/03,8402140071
- 840R130397 First interim deficiency rept re lengths of flex conduit extensions not as specified Initially reported on 840112 Installation info will be provided Next rept will be submitted by 840815 HILLS, L. M Tennessee Valley Authority 84/02/07 D'REILLY, J P Region 2, Office of Director 2pp 22203, 293, R4X Fiche 50-438, 84/02/07, 8402130397.
- 8401190053 Board Notification 84-020 forwards info re Transamerica Delawai, Inc emergency diesel generator problems Attendance list meeting handouts & slides encl EISENHUT.D G Division of Licensing 84/02/13 PALLADINO Commissioners 102pp 22332 202 24% Fiche 50-000,84/02/13, 8401190053
- 8402220031 Sixth interim deficiency rept re potentially overstressed subsedded plates Embedded plate sample now being reviewed Next rept expected by 840619 MILLS.L M Tennessee Valley Authority 84/02/14 G'REILLY.J P Region 2, Office of Director. 1p 22337-273 24X Fiche 50-438,84/02/14,8402220031
- 8402220128 Fourth interim deficiency rept re lack of environ qualification of equipment in auxiliary bldg due to potential failure of startup & recirculation sys. Initially reported on 820422 Dreadings revised Next rept by 850403.
 MILLS.L.M Tennessee Valley Authority 84/02/14 O'REILLY, J P Region R. Office of Director 2pp 22337 254 24X Fiche 50-438.84/02/14.8402220128

- B402220175 Fifth interim deficiency rept re nonconservative calculation method for general Const Spec 0-32 violations Initially reported on B20528 Sampling data review in progress Next rept will be submitted by B40619
 MILLS.L. M. Tennesse Vallay Authority B4/02/15 O'REILLY, J.P. Region 2. Office of Director ip 22340-310 24X
 Fiche 50-438.84/02/15.8402220173
- 8402220315 First interim deficiency rept re global coordinates of max pipe movements Initially reported on 840118 Util presently reviewing all isometric drawings & skewed nonglobal coordinate sus Next rept expected by 850426 MILLES.L M Tennessee Valley Authority 84/02/15 O'RETLLY, J P Region 2. Office of Director 2pp 22336 261 24X Fiche 50-438.84/02/13.8402220315
- 8402220530 Part 21 rept re defective DBR & DBRV standby diesel generatur turbocharger thrust bearing lubrication Deficiency not corrected by sys mod New recommendation will be sent to customers by 840330

 80YER.R E Transamerica Delaval, Inc 84/02/15 Director's Office. Office of Inspection and Enforcement 5pp 22332:182 24X Fiche 50-000,84/02/15,840220530
- 8408270087 First interim deficiency rept re use of nonconservative valve & pipe fitting adjustment factors for insulation usight calculations initially reported on 840124 Analysis verification checklist will be revised Next rept by 850515 MILLSL M Tennessee Valley Authority 84/02/16 D'REILLY, J. P Region 2. Office of Director 2pp 22391-267 24X Fiche. 50-438, 84/02/16, 8402270087
- 8402270191 First interim deficiency rept re damage to control wiring on Westinghouse Type DS low voltage circuit breakers Initially reported on 840119. Caused by wires routed across sharp edges of breaker frame.

 MILLBL M. Tannessee Valley Authority 84/02/16 O'REILLY, J P Region 2. Office of Director 2pp 22391 328 24X Fiche 50-000,84/02/16.8402270191.
- B402270020 Third interim deficiency rept re GA on valve purchase orders by Atbood & Merrill Initially reported on B30901 Valves not shipped Release of valves sub, to favorable util insprept results MILLS.L M Tennessee Valley Authority, B4/02/17 O'REILLY,J PRegion 2. Office of Director 2pp 22387 358 24% Fiche. 50-438,84/02/17,8402270020
- B402270357 Second interim deficiency rept re deficient square root extractor modules for reactor protection sys mfg by Beiley Meter Co. Initially reported on B3:114 BW requested to determine root cause Also reportable per Part 21.
 MILLS.L M Tennessee Valley Authority B4/02/17 D'REILLY, J P Region 2. Office of Director 2pp 22390:361 24X Fiche 50-438.84/02/17.8402270357.
 - 102270395 First interim deficiency rept re overtorqued conduit & conduit fox support boits Initially reported on B40124, Review in progress to determine extent of problem Next rept will be submitted by 840304 MILLS.L M Tennessee Vailey Authority, 84/02/17, D'REILLY, PRegion 2. Office of Director, 2pp 22391:184 24X Fiche 50-438,84/02/17,8402270395.
- 8402270403 First interim deficiency rept re Lavels A & B storage temp below 40 F limit initially reported on 840124. Affected storage areas will receive addl heating & insulation Next rept will be submitted by 840516. MILLS.L.M. Tennesses Valley Authority, 84/02/17 0'REILLY,J P Region 2. Office of Director. Zpp 22391:180, 24X Fichs 50-438,84/02/17,8402270403
- 8402280701 Notification of 840308 meeting w/Transamerica Delaval, Inc (TDI) Owners Oroup in Wading River.NY to discuss TDI proposed program plan to qualify diseal generators. CARUSD.R Division of Licensing 84/02/23 BERLINGER, C. Division of Licensing 2pp. 22414:340 24X Fiche 50-000,84/02/23,8402280701.

V. Operator Examinations

- 8402010337 Notification of contract execution "Use of TVA Reactor Binulator Facilities at Chattanonga TN for Training on Browns Ferry, Sequoyah & Bellefonte Simulators " JESSUP, B Technical Assistance Contracts Branch FIN 8-8717 83/12/29 \$MOME.S K Director's Office; Office of Inspection and Enforcement. 1p. 22059: 229. 24X Fiche: 50-000, 83/12/29, 8402010337
- --8402010346 Ltr Contract NRC-05-84-153, "Use of TVA Reactor Simulator Facilities at Chattanooga.TN for Training on Browns Ferry, Bequoyah & Bellefonte Simulators." awarded to TVA, MORTON.K.V Technical Assistance Contracts Dranch. FIN B-8717 83712/29 JOHNSON.R.J Tennessee Valley Authority. 6pp 22059.230 24X Fiche 50-000.83/12/29,8402010337

- DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 8402070003 Responds to FDIA request for const completion dates for nuclear plants currently under conat & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documents FELTON, J M Division of Rules and Records 83/10/31 ROSENBAUM, D M Technical Analysis Corp 17pp 22193 272 24X Fichs 50-000,83/10/31.8402070003
- --8402090087 Handwritten graphs re const activities Related info encl * NRC - No Detailed Affiliation Given 83/06/28 4pp 22196 035 24X Fiche.50-000.63/10/31,8402090003
- ---8402090091 Handwritten notes & calculations re const activities & fuel load preparation ** NRC No Detailed Affiliation Given. 81/10/07 5pp 22196 042 24X Fiche 50-000,83/10/31,8402090003
- --8402090095 Summary of 790322 meeting w/util in Bethesda.MD re estimated fuel load date for Unit i Related info encl LYNCH.M D Light Water Reactors Branch 4, 79/04/02 Light Water Reactors Branch 4 61pp 22196 050 24X Fiche 50-000.83/10/31.8402090003
- --8402090124 Handwritten notes & calculations re facility const Related info encl # NRC - No Detailed Affiliation Given 83/10/31 48pp 22174.200 24X Fiche 50-000,83/10/31,8402090003
- 8402290425 FDIA request for documents re const assessment team visit to facility in Aug & Sept 1983
 HIATT. B L. Obio Cittiens for Responsible Energy 83/11/16
 FELTON, J M Division of Ruips and Records ip 22437 iii 24X
 Fiche. 50-440, 83/11/16, 8402290425
- 8402270431 Partial response to FOIA request for documents re const assessment team visit to facility in Aug & Bept 1983, Forwards App A documents Search for addl documents continuing FELTON, J. H Division of Rules and Records 84/01/17, Ohio Citizens for Responsible Energy 2pp 22437 i12 24X Fiche 50-440,84/01/17,8402290431
- 8312120136 Board Notification 84-011 discusses NRC use of terms "important to safety" & "safety-related" EIBENHUT,D 9, Division of Licensing 84/01/18, PALLADIND Commissioners, 72pp 22241 008 24X Fiche 50-000,84/01/18,8312120136
- B401190012 Board Notification 84-013 forwards info re Transamerica Delaval Inc emergency diesel generators EIBENHUT,D 9 Division of Licensing, B4/01/24 PALLADIND,N, Commissioners 10pp 22054:346 24X Fiche:50-000,84/01/24, 8401190012
- 8401190015 Board Natification 84-018: provides info re failure experience of Transamerica Delaval emergency diesal generators in marine svc EIBENHUT, D. O. Division of Licensing 84/01/27 PALLADING, N. J. Commissioners 385pp 22093.027 24X Fiche. 50-000, 84/01/27, 20018018018
- 84020&0048 Responds to B31221 ltr requesting add1 info re drywell purge, containment leakags testing & containment isolation for facility Responses to Guestions 480,50(b), (c) & 480 51 will be incorporated in future FBAR amend EDELMANIM R Claveland Electric Illuminating Co. 84/01/31 YOUNDBLODD,8 J. Licensing Branch 1 3pp 22088,193, 24X Fiche 50-440,84/01/31,84020&0048.
- B402070503 Notification of B40306-08 meetings w/util at site to review progress in design, engineering & const. Agenda encl STEFANO.J J Licensing Branch 1 B4/01/31 YDUNGBLOOD, B. J. Licensing Branch 1 9pp 22141 299 24X Fichs 50-440, 84/01/31, 8402070503
- 8402170061 Notification of 840210 meeting w/Transamerica Delaval, Inc (TBI) in Bethesda, MD to discuss program plan proposed by TBI Owners Group to qualify diesel programors. CARUBO. R Division of Licensing 84/02/04 BERLINGER, C. Division of Licensing 2pp 22312 339. 24X Fiche 50-000,84/02/06.

- 8402130389 Forwards correspondence re facilities use of heavy-wall pipe fittings at facilities Requests info re uses of heavy pipe fittings & effects on piping design analyses & what NRC has done re wtiff pipe clamps at facilities
 HIATT.S L Ohio Citizens for Responsible Energy 84/02/10
 STEFAND, J J Division of Licensing 1p 22241 311 24X
 Fiche 50-000.84/02/10.8402150389
- 840119059 Board Notification 84-032 provides add1 info on environ qualification Submittal augments info in Board Notifications 84-007 EIBENHUT. O Division of Licensing 84/02/13 Atomic Safety and Licensing Board Panel 10pp 22314 204 24X Fiche 50-000.84/02/13.8401190059
- 8402270287 Forwards Equipment Qualification Branch 840214 rept of 840117-19 environ equipment qualification audit Response should address exceptions taken by staff in generic evaluation of GE environ equipment qualification program YOUNGRLOOD.B J Licensing Branch 1 84/02/14 EDELMAN.M R Cleveland Electric Illuminating Co 2pp 22377 358 24X Fichs 50-440.84/02/14.8402270287
- ---840227029; Comments on 840;16-20 audit of equipment qualification files Observations & comments made at 840;19 exit interview listed. Evaluation of program will be provided as input to future SBER NOONAN, V S Equipment Qualification Branch 84/02/14 YOUNGH_COD.B J. Licensing Branch 1 App 67195 203. 24X Fiche-50-440,84/02/14,8402270287
- 8401190068 Board Notification 84-033 provides "Sys Interaction Program," task action plan for Unresolved Safety Issue A-17 Distribution list encl EISENHUT.D 0 Division of Licensing, 84/02/14 PALLADINO Commissioners Spp 22482.091 24X Fichs 50-000,84/02/14.
- 8402270430 Notification of 840302 meeting w/Hydrogen Control Cwners Group in Bathesda.MD to discuss status of Hydrogen Control Owners Group 1/4-scale testing program & response to request for add1 info received from NRC in Dec 1983 HOUSTON.M.D Licensing Branch 2 84/02/16 SCHWENCER.A Licensing Branch 2 7pp 22438 187 24X Fiche 50-000,84/02/16,8408270430
- E NAC Safety Evaluation Report (SER), supple & correspondence
- B402010306 Forwards emergency preparedness evaluation addressing SER Outstanding Issue 19 Findings will be documented in Feb 1784 BBER 4
 YOUNGBLOOD, B J Licensing Brench I 84/01/17 EDELMAN, M, R Cleveland Electric Illuminating Co 49pp 22046 240 24X Fiche's 50-440, 84/01/17, 8402010306.
- B4D2080083 Requests info we pressure leak testing of pressure isolation valves per SER Section 3 7 6. NRC position on pressure leak testing encl Response requested within 5 days of ltr receipt.

 YDUNGBLODD, B. J. Licensing Branch 1 84/01/25 EDELMAN, M R Cleveland Electric Illuminating Co 3pp 22172 338 24X Fiche: 50-440, 84/01/25, 8402080083
- 8402060105 Responds to NRC 831213 ltr on evaluation findings re BER Outstanding Issue 12 on manual initiation/termination of EBF sys Blue indicating light will be installed above control switches for LPCI & LPCS injection valves.

 EDELMAN, M R. Cleveland Electric Illuminating Co 84/01/31 YQUNGBLOODS J Licensing Branch 1. ip 22089 116 24X Fichs. 50-440,84/01/31,8402040105
- 8402150424 Forwards 88ER 4 (NUREO-0887) re facility operation W/o encl YOUNGBLOOD B J Licensing Branch i. 84/02/08, EDELMAN.M.F Cleveland Electric Illuminating Co. 2pp 22263 312 24X Fiche. 30-440.84/02/08.8402150424
- 8402240381 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF PERRY NUCLEAR POWER PLANT, UNITS 1 AND 2, Docket Nos. 50-440 And 50-441 (Claveland Electric Illuminating Company) + Division of Licensing, NURSC-0887 S04 84/02/28 142pp 22381,118 24% Fiche 50-440,84/02/28,8402240381
- F. Security, medical, emergency & fire protection plans
- 8402010306 Forwards amergency preparedness evaluation addressing BER Outstanding Issue 19. Findings will be documented in Feb 1984 SHER 4.

 YOUNGBLOOD, B. J. Licensing Branch i 84/01/17. EDELMAN, M. R. Glaveland Electric 111uminating Co 49pp 22046, 240, 24X Fichs. 30-440. 84/01/17. 8402010306

- 8402140528 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR YDUNO8L00D, B. J. Licensing Branch 1 84/02/03 EDELMAN, M.R. Cleveland Electric Illuminating Co. 2pp 22253 300 24X Fiche 50-440,84/02/03,8402140528
- B402130140 Notification of B40210 meeting w/util in Bethesda,MD to discuss & clarify unresolved items addressed by NRC B40110 ltr re Revs 1 & 2 to emergency plan BTEFAND,JJ Licensing Branch 1 B4/02/06 YDUNOBLODD,B J Licensing Branch 1 3pp 22216 344 24X Fiche 50-440,84/02/06, B402130140
- B402230284 Summary of B40207 meeting w/util in Bethesda,MD re detailed control room design review per Suppl 1 to NUREO-0737 List of participants encl
 STEFANO,J J Licensing Branch i B4/02/16 YOUNOBLOOD,B J
 Licensing Branch i 5pp 223BO 026 24X Fiche 50-440.84/02/16, 8402230284
- B402290452 Summary of B40210 meeting w/util in Bethesda.MD re NRC comments on emergency plan provided by util B40117 ltr Revised plan expected by 840430 STEFANO.J J Licensing Branch i B4/02/17 YOUNGBLOOD.B J Licensing Branch i 3pp 22438 IBI 24X Fiche 50-440.B4/02/17.8402270452
- G Adjudicatory correspondence
- 8402010197 Response to ASLB 831223 request for briefs on regulations & guidance applicable to Contention 16 re reliability of diesel generators Contificate of Svc encl MDODHEAD, C.P. Hearing Brench 4 84/01/20 Atomic 8afety and Licensing Board Panel 8pp 22040.351 24X Fiche 50-440.84/01/20, 8402010197
- 8402010187 Ack 840125 agreement re deferment of 10th set of interrogatories until issuance of board notifications & 840125 meeting w/Transamerica Delaval. Inc (TDI) & util owners Ltr notifying TDI owners of meeting encl HDDDHEAD.C P Hearing Branch 4 84/01/25 HIATT, S Ohio Citizens for Responsible Energy 30pp 22037 173 24x Fiche 50-440, 84/01/25,8402010187
- B402010035 Confirms 840130 telcon w/Judge Bloch, granting extension of time until 840227 for filing supplemental responses to Dhio Citizens for Responsible Energy interrogatories on Issues 6.8 & 15
 BWIGER, M.A. Shaw, Pittman, Potts & Trowbridge SWIGER, M.A. Cleveland Electric Illuminating Co. 84/01/30 BLOCH, P.B., KLINE, J.R., BRIGHT, O. Atomic Bafety and Licensing Board Panel 3pp. 22042 251 24X Fichs 30-440,84/01/30,8402010055
- 8402070037 Forwards applicant response to notice of violation reserveral safety-related cables exiting cable tray Sections 1839 & 1840 which violated min training radius requirements WOODHEAD, C P Hearing Branch 4 84/02/01 BLOCH, P B , BRIGHT, Q D , KLINE, J R Atomic Safety and Licensing Board Panel ip 22102 356 24X Fiche 50-440,84/02/01,8402070037
- 8402070036 Advises of intention not to respond to Uhio Citizens for Responsible Energy & Council on Energy Independence briefs on regulations re-diesel generators HODDHEAD, C.P. Hearing Branch 4 84/02/03 BLOCH, P.B., DRIOHT, G.D., KLINE, J.R. Atomic Safety and Licensing Board Panel 1p 22102, 355 24X Fiche 50-440,84/02/03,8402070036
- 8402070122 Order extending time until 840221 for Commission to act to review 831115 director's decision.
 CHILK-B J Office of the Secretary of the Commission 84/02/03 Commissioners ip 22102 265 24% Fiche 50-440.84/02/03.
 8402070122.
- 8402070188 Order extending time until 840210 for Commission to act to review Director's Decision DD-84-1.

 CHILK, B. J. Office of the Secretary of the Commission 84/02/03.

 Commissioners 1p. 22093 025 24X Fiche 50-440.84/02/03.

 8402070188.
- B402070233 Reply to NRC & Ohio Citizens for Responsible Energy 840120 & 16 respective briefs on NRC regulations & guidance applicable to Issue 16 re reliability of diesel generators Certificate of Bvc encl
 BHIGER, M. A. Cleveland Electric Illuminating Co SWIGER, M. A. Shaw, Pittman, Potts & Troubridge 84/02/03 Atomic Safety and Licensing Board Panel 18pp 22101 115 24X Fiche 50-440,84/02/03.8402070233.

- B402080053 Motion to reopen discovery on Issue 1 re emergency planning Certificate of Svc enci Related correspondence
 LDDGE,T J Sunflower Alliance B4/02/03 Atomic Safety and
 Licensing Board Panel 3pp 22128 076 24X Fiche 50-440,84/02/03.
 8402080053
- 8402080170 Reply to NRC & applicant briefs re regulations & guidance applicable to Issue 16 ASLO should adopt OCRE stds & Issue 16 ASLO should adopt OCRE stds & Issue 16 Certificate of Svc encl HATT.S L Chio Citizens for Responsible Energy 84/02/03 Atomic Safety and Licensing Board Panel 4pp 22128 242 24X Fichs 50-440-84/02/03.8402080170
- B402130190 Answers to Ohio Citizens for Responsible Energy tenth set of interrogatories re Issue 14 Certificate of Svc encl SWIGER, M A Cleveland Electric Illuminating Co 84/02/OB 27pp 22245 275 24X Fiche 50-440, 84/02/08
- B402150107 Forwards corrected affidavit of EC Christiansen attached to B40208 answers to Ohio Citizens for Responsible Energy tenth set of interrogatories re Issue 16 Svc list encl SWIGER.M A Shaw. Pittman. Potts & Troubridge SWIGER.M A Cleveland Electric Illuminating Co 84/02/10 Docketing & Services Branch 3pp R2249 262 24X Fiche 50~440,84/02/10. B402150107
- B402170108 Order establishing schedule for briefing on Sunflower Alliance appeal of ASLB 831202 partial initial decision on GA Brief due by 840321 SHOEMAKER.C J Atomic Eafety and Licensing Appeal Panel 84/02/15 2pp R2301
 - 2220136 Brief in support of Sunflower 840214 motion to readmit saus 12 ASLB urged to readmit Issue 12 & permit liberal isscovery due to dismissal before interrogatories answered prifficate of Svc encl
 1ATT, B. L. Ohio Citizens for Responsible Energy 84/02/17 5; 2346 302 24X Fiche 50-440, 84/02/17, 8402220136
 - 02220239 Brist in support of Sunflower Alliance 840203 motion to vazzavan brief in support of authorizer Alliance 640203 mbts reapen discoverg on Issue i re emergency planning Bosument proffered as addi support of motion Certificate of Eve encl Related correspondence HIATT. S. Unio Citizens for Responsible Energy 84/02/17, 22337 187 24X Fiche 50-440,84/02/17,8402220239 BA/02/17, 10op
- 8402220353 Eleventh set of interrogatories on Issue i& re diesel generators Certificate of Svc encl Related correspondence HIATT, 8 L Obio Citizens for Responsible Energy 84/02/17 Cleveland Electric Illuminating Co App 22934 163 24X Fiche 50-440,84/02/17,8402220353
- M02220163 Order extending time until 840228 for Commission to act to review 831115 Director's decision CHILK.8 J Lang Island Lighting Ca 84/02/21 Suffalk County, NY ip 22337230 24% Fiche 50-440.84/02/21.8402220163.
- 402230054 Answer apposing Sunflower Alliance, Inc 840203 motion to reopen discovery on Issue 1 re emergency planning Motion fails to show need for addl discovery Certificate of Syc
- BHIGER,M A Cleveland Electric Illuminating Co SWIGER,M A Shaw, Pittman, Potts & Troubridge 84/02/21 Atomic Safety and Licensing Board Panel 7pp 22361 288 24X Fiche 50-440.84/02/21.
- 402270039 Serves BSER 4 W/o encl Related correspondence HDDDHEAD.C P Hearing Branch 4 84/02/21 BLDCH,P 8, BRIGHT.G.O., KLINE.J R Atomic Safety and Licensing Board Panel 1p 22391 277 24X Fiche 50-440.84/02/21.8402270059
- 40227008B Response to Sunflower Alliance 840203 motion to reopen discovery of Contention i re emergency planning Add1
 discovery will be more appropriate & effective after rev of
 offsite plans completed W/Certificate of Svc
 WOODHEAD: CP Hearing Branch 4. 84/02/23 Atomic Bafety and
 Litensing Board Panel 5pp 22426 043 24X Fiche 50-440,84/02/23,
 AADSDOADER 84022200BB
- 102280337 Forwards 840221 press release announcing that completion of Unit 1 planned for late 1985 Svc list encl Related
- Unit 1 planner yer level correspondence
 Correspondence
 BILBERG, J E Bhaw, Pittman, Potts & Trowbridge, BILBERG, J E
 Cleveland Electric Illuminating Co B4/02/24 BLOCH, P. B.,
 KLINE, J R., BRIGHT, 0 O Atomic Bafety and Licensing Board Panel
 App 22398 359, 24X Fiche 50-440, B4/02/24, B4022B0337
- 102290101 Memorandum & order granting Sunflower Alliance, Inc motion to reopen discovery on emergency planning contention, Issue 1 BLOCH.P B . KLINE.J R . BRIGHT, G. O. Atomic Safety and Licensing Soard Fanel 84/02/28 Sunflower Alliance 4pp 22426.037 24X Fiche: 50-440,84/02/28,8402290101

- K Utility Final Safety Analysis Report (FSAR) & amends
- 8402020312 Forwards Amend 13 to FSAR EDELMAN, M R Cleveland Electric Illuminating Co 84/01/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 28049 254 24X Fiche 50-440,84/01/31,8402020312
- --8402020314 Amend 13 to FBAR * Cleveland Electric Illuminating Co 84/01/31 22049 257 24X Fiche 50-440,84/01/31,8402020312 84/01/31 32100

M Antitrust correspondence

- 8402140518 Orants request for 30-day extension to respond to FR notice of initial finding of no significant antitrust changes
 DENTON.H R Office of Nuclear Reactor Regulation, Director 84/02/02 OOLDBERG, R Goldberg, Fieldman & Letham, P C. 1p
 22251 362 24X Fiche 50-440,84/02/02,8402140518
- 8402070222 Motion for clarification & correction of finding of NRR re OL antitrust review Util cannot be expected to mend ways if allowed to violate license conditions w/impunity Certificate at Svc encl OCLDBERO,R Cleveland, OH GDLDBERO,R Goldberg, Fieldman & Lethem, PC 84/02/06 Commissioners 14pp 22102 134 24X Fiche 90-440,84/02/06.8402070222
- 8402140179 Forwards finding of no significant antitrust changes. per telcon VOGLER.B H Hearing Branch 2 84/02/06 GDLDBERG.R Cleveland Electric Illuminating Co 86pp 22230 214 24X Fiche 50-440.84/02/06.8402140179
- 8402220231 Forwards City of Cleveland 840206 motion for clarification Nocaves) rorwards City of Cleveland E40206 motion for clar & correction of finding re OL antitrust review & Chairman Palladino B40131 ltr to DOJ re determination not to impose civil penalties W/o encls Related correspondence VOGLER. B H Hearing Branch 2 B4/02/13 ZAHLER.R E Sh Pittman, Potts & Troubridge ip 22340 152 24X Fiche 30-440.84/02/13.8402220231 ZAHLER, RE Shaw.
- B402220244 Forwards Palladino 840131 ltr to McGrath, Assistant US Atty Opneral, advising of NRC determination not to impose civil penalties against util VDGLER, B H Hearing Branch 2 84/02/13 ODLDBERG, R Goldberg, Fieldman & Letham, P C 3pp 22339 207 24X Fiche 30-440, 84/02/13, 840220244.
- 8402240052 Requests reconsideration of 840131 decision re imposition of civil penalty for util violation of License Condition 3 Penalty should be imposed & City of Cleveland 840206 motion should be considered in decision GCLDBERG.R. Goldberg. Fieldman & Letham, P C GOLDBERG.R Cleveland, OH B4/02/22 PALLADING.N J Commissioners. Spp. 22374-351 24X Fiche 50-440.84/02/22,8402240052
- O Advisory Committee on Reactor Bafeguards reports & correspondence
- 8402090492 Proposed summary of ACRS Subcommittee on Perry 820628-29 meetings in Cleveland, OH re util DL application Proposed schedule encl * ACRS Advisory Committee on Reactor Safeguards 82/07/28 ACRS Advisory Committee on Reactor Safeguards 20pp 22192, 220 24X Fiche 50-440, 82/07/28, 8402090492
- B402010191 Forwards summary of ACRS 285th meeting on B40112-14 re OL application & W Eddleman B40113 ltr re compromised plant safety NRC response to ACRS will be forwarded to ASLB & parties BARTH, C A PARTH. C A Hearing Branch 1 84/01/20 KELLEY, J L., CARPENTER, J H., BRIGHT, G O Atomic Safety and Licensing Board Panel Ppp 22039 348 24X Fiche 50-400,84/01/20,8402010191
- G Inspection reports, IE Bulletins & correspondence
- 8312120153 IE Info Notice 84-04, "Steam Binding of Auxiliary Feedwater Pumps " Svc list and 1
 JORDANN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/01/25 Consolidated Edison Co of New
 York, Inc 120pp 22058 001 24X Fiche 50-000.84/01/25.8312120153
- B4021303R3 Forwards IE Insp Repts 50-440/83-38 & 50-441/83-36 on B31101-1231 No honcompliance noted KNDP.R C Region 3, Office of Director 84/01/25 EDELMAN, M R Cleveland Electric Illuminating CO Rpp R2197 187 24X Fiche 50-440.84/01/25.8402130323

- --8402130327 IE Insp Repts 50-440/83-38 & 50-441/83-36 on 831101-1231 No noncompliance noted Major areas inspected plant housekeeping practices, equipment maint, followup on previous insp findings & 10CFR50 55(e) items
 GILDNER, M L , KONKLIN, J & Region 3, Office of Director 84/01/25 4pp 22197 189 24X Fiche 50~440,84/01/25,8402130323
- B402100213 Forwards IE Insp Repts 50-440/83-37 & 50-441/83-35 on 83130-1215 & notice of violation LITTLE, W 8 Region 3, Office of Director 84/01/27 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 22179 028 24X Fiche: 50-440, 84/01/27, 8402100213
- --B402100217 Notice of violation from insp on 831130-1215 LITTLE,W 5 Region 3, Office of Director B4/01/27 2pp 22179:030 24X Fiche 50-440,84/01/27,8402100213
- --8402100223 IE Insp Repts 50-440/83-37 & 50-441/83-35 on 831130-1215
 Nancompliance noted failure to establish adequate
 qualification procedures & failure to implement design
 controls
 NAIDU.K R : FALEVITS, Z : CHRISTNOT, E. Region 3, Office of
 Director 84/01/26 17pp 22179 032 24X Fiche 50-440,84/01/27,
 8402100213
- 8402070037 Forwards applicant response to notice of violation reserveral safety-related calles exiting cable tray Sections 1839 & 1840 which violated min training radius requirements WODDHEAD, C P. Hearing Branch 4 84/02/01 BLOCH, P. D., BRIGHT, O. O. KLINE, J. R. Atomic Safety and Licensing Board Panel 1p 22102 354 24% Fichs: 50-440, 84/02/01.8402070037
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co. of New York, Inc. 119pp. 22114 177 24X Fiche 50-000,84/02/03,8401190016
- B401170017 IE Bullstin 84-01, "Cracks in BWR Mark I Containment Vent Headers," Svc list encl, DEVOUND.R C. Director's Office. Office of Inspection and Enforcement B4/02/03 Consolidated Edison Co of New York, Inc 102pp 22177,156 24X Fiche 50-000.84/02/03,8401170017
- 8402070247 Ack receipt of 840122 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 30-440/83-31 & 50-441/83-30
 NORELIUB,C E. Division of Project & Resident Programs 84/02/03
 EDELIMAN.M.R Claveland Electric Illuminating Co ip 22101 216
 24X Fiche.50-440,84/02/03,8402070247
- --8402070250 Responds to NRC 831223 ltr re violations noted in IE Insp Repts_50-440/83-31 & 50-441/83-30 Corrective actions duct covers installed in ductways & separation of raceway in accordance w/installation drawing. EDELMAN.M.R. Claveland Electric Illuminating Co. 84/01/22 KEPPLER.J.O. Region 3, Office of Director. 25pp. 22101 217, 24X Fichs.50-440,84/02/03,8402070247.
- B40:190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Bus (100FR50, App R)" Bvc list encl.

 JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103), B4/02/13 Consolidated Edison Co of New York, Inc. 124pp. 22365 259 24X Fiche 50-000.84/02/13,8401190041
- B401190050 Board Notification B4-021 provides repts of Transamerica Delayal, Inc insps conducted from Mar 1979 to Oct 1983 EIBENHUT, D. Q. Division of Licensing B4/02/13 PALLADING Commissioners. Spp. 22314 001. 24X Fiche 50-000, 84/02/13.
- 8401190037 IE Info Notice 84-08, "10CFR30 7, 'Employee Protection '"
 Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14, Consolidated Edison Co of New
 York, Inc. 115pp 22365 141 24X Fiche. 50-000, 84/02/14, 8401170039
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Westinghouse Type BA-1 Differential Relays" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp. 22366.142 24X Fiche 50-000.84/02/15,8401190045
- B401190062 IE Info Notice 84-10, "Motor-Operated Velve Torque Switches Set Below Menufacturer Recommended Value." Syc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Rasponse (Post 830103) 84/02/21 Consolidated Edison Co. of New York, Inc 116pp. 22366.024 24X Fiche 50-000,84/02/21,8401190062

- B401190066 IE Info Notice B4-11, "Training Program Deficiencies"
 Bvc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B4/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000, B4/02/24, 8401170066
- 8401190067 JE Info Notice 84-12, "Failure of Soft Seat Valve Swals "
 Svc list encl
 JURDANNE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060 24X Fiche 50-000,84/02/27,8401170067
- B Reportable occurrences, LERs & related correspondence
- 8402140107 Provides update on reportable events re RCIC sys equipment room cooler & automatic restart of chiller Safe shutdown sys review to assess sys interaction to assure automatic or manual start complete
 SAILER, W F Gilbert Associates, Inc 83/12/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement lp RR217 332 24X Fiche 50-440, 83/12/13, 8402140107
- 8402030248 Final significant deficiency rept re defect in antirotational setscrew of Anchor Darling globe valves supplied by GE Initially reported on 831227 Setscrew will be staked to stem collar threads Unit i valves completed 840111 EDELMAN, M R Cleveland Electric Illuminating Co 84/01/27 KEPPLER. J G Region 3, Office of Director 2pp 22067 213 24X Fiche 50-440.84/01/27.8402030248
- B402060338 Final deficiency rept re shop welds on some safety-related pipe supports supplied by Pawer Fiping Co Initially reported on 830921 Bite Nonconformance Rept NDS-024 dispositioned to direct rework or repairs on 30 welds w/completion by 840630 EDELMAN.M R Cleveland Electric Illuminating Co 84/01/30 KEPPLER.J G Region 3. Office of Director 3pp 22085 115 24x Fiche 50-440.84/01/30.8402060338.
- 8402060359 Suppl to 830831 Interim deficiency rept re unrepresentative radiographs for two Borg-Warner valve assemblies Due to delays in installation & review of radiographs for Unit 1, final rept now scheduled for 840501 EDELMAN.M.R. Cleveland Electric Illuminating Co. 84/01/30 KEPPLER.J Q. Region 3, Office of Director 1p. 22085 118. 24X Fiche 50-440,84/01/30,8402060359
- B402060400 Supplemental final deficiency rept re Transamerica Delaval, Inc standby diesel generator sys IEEE 383 failure in Class IE circuit wiring Due to shipment problem installation scheduled to be completed 840316 EDELMAN, M.R. Cleveland Electric Illuminating Co 84/01/30 KEPPLER, J.G. Region 3, Office of Director 1p 22086 176 24X Fiche 50-440.84/01/30.8402050400
- B402060411 Updated final deficiency rept re bracket welds for main steam & recirculation sys pipe whip restraints Review of installation documentation will not be complete until 840316.
 EDELMAN.M R Clevelans Electric Illuminating Co 84/01/30 KEPPLER, J O Region 3. Office of Director 1p 22085.098 24X Fiche 50-440-84/01/30.8402060411
- 8402060500 Final Deficiency Rept RDC 78(83) re exhaust line back pressures exceeding manufacturers recommendations on diesel generators for HPCS sys Initially reported on 830805 Reported per Part 21 by Gibert Assoc on 830727 EDELMAN, M R Cleveland Electric Illuminating Co 84/01/30 KEPPLER, J. 0 Region 3, Office of Director 2pp 22083 112, 24X Fithe 50-440, 84701/30-8402060500
- 8402060507 Final Deficiency Rept RDC 84(83) re Transamerica Delaval, Inc engine mounted fuel oil line on diesel generator engines Initially reported on 831011. Rework on lines will be completed by 840601 Also reported per Part 21 by vendor EDELMAN, M R Cleveland Electric Illuminating Co 84/01/30 KEPPLER, J Q Region 3, Office of Director 2pp 22083 110 24X Fiche 50-440, 84/01/30, 8402040507
- 8402070365 Part 21 rapt re linear converter device w/possible generic defect Initially reported on 840116 Written notifications issued. Customer responses should be received by 840331. Final rept will be submitted by 840430 DDDSON, J P Pacific Air Products Co. 84/01/30 Director's Defice, Office of Inspection and Enforcement 2pp 22114 279 24X Fiche 50-280,84/01/30,8402070365
- --8402070373 Part 21 rept re linear converter device w/possible generic defect Initially reported on 840116 Preliminary analysis indicates excessive wear of brase shaft guides Next rept will be submitted within 90 days Supporting info encl DODSON, J P Partic Air Fraducts Co 84/01/17 POTAPOVS, U Region 4, Office of Director. 60pp 22114 301 24X Fiche 50-000,84/01/30,8402070365

- 8402060378 Final deficiency rept re damage to dryer/separator strongback initially reported on 830916 Polar crane recebled w/certified cable Util amended previous acceptance of handling & lifting procedure EDELMAN, M R Cleveland Electric Illuminating Co 84/01/31 KEPPLER, J G Region 3, Office of Director 3pp 22086 313 24X Fiche 50-440,84/01/31,8402060378
- B402070393 Requests that NRC investigate design reliability of emergency diesel generators supplied by Transamerica Delaval Inc Engine problems have been experienced since delivery of first vessel in May 1981 Related info encl MOLINAL C Falton Carriers. Inc B4/02/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 63pp 22096 057 24X Fiche 50~000, 84/02/01, 8402070393
- 8402170039 Interim deficiency rept re operator stem keys for motor operated valves supplied by Borg-Warner Initially reported on 840111 Key retainers will be repaired or replaced Final rept will be submitted by 840615 EDELMAN.M R Cleveland Electric Illuminating Co 84/02/10 KEPPLER.J G Region 3, Office of Director 1p 22300 274 24X Fiche 50-440.84/02/10.8402170039
- 8402170149 Final deficiency rept re piping installation contractor ASME Gode procurement problems Initially reported on 840112 Pullman Power Products revised Procedures 10-34. "Site Purchasing" & VII-1. "Vendor Qualification" EDELMAN, M R Cleveland Electric Illuminating Co 84/02/10 KEPPLER, J & Region 3, Office of Director 2pp 22297 023 24X Fiche 50-440,84/02/10,8402170149
 - D2170273 Interim deficiency rept re matl for ASME Section III, Class 2 & 3 supports & hangers installed in Class 1 supports
 Initially reported on B4012 Receipt insp program revised
 Vext rept by B40430
 EDELMAN.M R Cleveland Electric Illuminating Co 84/02/10
 KEPPLER.J 0 Region 3, Office of Director Rpp 22297 074 24X
 Fichs 80-440,84/02/10,8402170273
- (01190053 Board Notification 84-020 forwards info re Transamerica Delaval.Inc emergency diesel generator problems Attendance list meeting handouts & slides encl EISENHUT.D Q Division of Licensing 84/02/13 PALLADINO Commissioners 102pp 22332 202 24X Fiche 50-000,84/02/13,8401190053
- 02220330 Part 21 rept re defective DSR & DSRV standby diesel nerator turbocharger thrust bearing lubrication Deficiency corrected by sys mod New recommendation will be sent to tomers by 840330 ER.R E Transamerica Delaval, Inc. 84/02/15 Director's ice, Office of Inspection and Enforcement Spp. 22332 182 2 he 50-000,84/02/15.8402220530
- 2270307 FNO-III-84-019 on 840221.licensee announced inability to set scheduled fuel load date of Dec 1984 Delay caused by enger than planned time to install piping & electronic untrol circuitry Unit 2 date remains Third Guarter 1988 ARADITO.R. KOMMLIN.J. Region 3. Office of Director 84/02/22 p. 22391 260 24% Fiche 50-440.84/02/22.8402270307
- 2280701 Notification of 840308 meeting w/Transamerica Delaval, Inc FDI) Duners Group in Mading RiversNY to discuss TDI roposed program plan to qualify dissel generators MRUBO, R Division of Licensing 84/02/23 BERLINGER, C Division F Licensing 2pp 82414 340 24% Fiche 50-000,84/02/23,102280701
- 12290166 Final deficiency rept re defective capstan springs used in todal PSA 1 & PSA 3 mechanical snubbers Initially reported in 831020 Snubbers inspected & capstan springs replaced corrective action will be completed by 840800 DELMAN.M R. Cleveland Electric Illuminating Co 84/02/23 LEPPLER, J G. Region 3, Office of Director 2pp 22427 122 24X iche: 50-440.84/02/23,8402290164
- 2290392 Discusses diesel generator testing program NRC position light change due to questionable reliability of Transamerica laval diesel generators. Acceptability will be addressed in xt SSER

 NOGBLOODS J. Licensing Branch 1 84/02/23 EDELMAN.M.R.

 'veland Electric Illuminating Co 2pp 22438 223 24X
 he 50-440.84/02/23.8402290392

- DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8402070003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documents
 FELTON, J M Division of Rules and Records 83/10/31
 ROSENBAUM, D M Technical Analysis Corp 19pp 22173 292 24X
 Fiche 50-000.83/10/31,8402070003
- --8402070087 Handwritten graphs re const activities Related info encl * NRC - No Detailed Affiliation Given 83/06/28 4pp 22176 035 24X Fiche 50-000.83/10/31.8402070003
- --8402070091 Handwritten notes & calculations re const activities & fuel load preparation * NRC No Detailed Affiliation Given 81/10/07 5pp 22196 042 24X Fiche 50-000,83/10/31,8402090003
- --8402090095 Summary of 790322 meeting w/util in Dethesda,MD re estimated fuel load date for Unit 1 Related info encl LYNCH,MD Light Water Reactors Branch 4 79/04/02 Light Water Reactors Branch 22196 050 24X Fiche 50-000,83/10/31,8402090003
- ---8402070124 Handwritten notes & calculations re facility const Related info encl
 * NRC No Detailed Affiliation Given B3/10/31 48pp 22174 200 24X Fiche 50-000, B3/10/31, B402070003
- 8402290425 FOLA request for documents re const assessment team visit to facility in Aug & Sept 1983 HIATT,S L Obio Citizens for Responsible Energy 83/11/16 FELTON.JH Division of Rules and Records 1p 22437 111 24X Fiche 50-440.83/11/16,8402290425
- 8402270431 Partial response to FOIA request for documents re const assessment team visit to facility in Aug & Sept 1783 Forwards App A documents Search for add1 documents continuing FELTON. J M Division of Rules and Records 84/01/17 HIATT, 8 Ohio Citizens for Responsible Energy 2pp 22437 112 24X Fiche 30-440.84/01/17.8402270431
- 8401190012 Board Notification 84-013 forwards info re Transamerica Delayal: Inc emergency diesel generators. EISENHUT.D @ Division of Licensing 84/01/24 PALLADING, N Commissioners 10pp 22054 346 24X Fiche 50-000,84/01/24, BA01190012
- 8401190015 Board Notification 84-018 provides info re failure experience of Transamerica Delaval emergency diesel generators in marine svc EIBENHUT.D G Division of Licensing 84/01/27 PALLADING.N. Commissioners 383pp 22093 027 24X Fichs 50-000,84/01/27,8401190015.
- 8402060048 Responds to 831221 ltr requesting add1 info re drywell purge, containment leakage testing & containment isolation for facility Responses to Questions 480 50(b), (c) & 480 51 will be incorporated in future FSAR amend EDELMAN, M.R. Cleveland Electric Illuminating Co 84/01/31, YDUNGBLOOD, B.J. Licensing Branch i 3pp 22088, 193, 24X Fiche 50-440,84/01/31,8402060048
- B402070503 Notification of 840306-08 meetings w/util at sits to review progress in design, engineering & const. Aganda encl BTEFANO, J. Licensing Branch 1 84/01/31, YOUNGBLOOD B. J. Licensing Branch 1 9pp 22141-279 24X Fichs 50-440,84/01/31, 8402070503
- B402170061 Notification of 840210 meeting w/Transamerica Delayal, Int (TDI) in Betheade, MD to discuss program plan proposed by TDI Owners Group to qualify discal generators CARUSO.R Division of Licensing. 84/02/06 BERLINGER, C Division of Licensing 2pp 22312-337 24X Fiche. 50-000, 84/02/06, 860127064
- B4021503B7 Forwards correspondence re facilities use of heavy-wall pipe fittings at facilities Requests into re uses of heavy pipe fittings & effects on piping design analyses & what NRC has done re stiff pipe clamps at facilities.
 HIATT, B L Obio Citizens for Responsible Energy 84/02/10, BTEFAND, J, J Division of Licensing ip 22241.311 24X Fiche: 50-000, 84/02/10, 84021303B9.

- B401190059 Board Notification B4-032 provides add1 info on environ qualification Submittal augments info in Board Notifications 34-004 & B4-007 EIBENHUT.D O Division of Licensing 84/02/13 Atomic Safety and Licensing Board Panel 10pp 22314 204 24X Fiche 50-000,84/02/13. B401190059
- 8402270287 Forwards Equipment Qualification Branch 840214 rept of 840117-19 environ equipment qualification audit Response should address exceptions taken by staff in generic evaluation of GE environ equipment qualification program YOUNO8LOOD.B J Licensing Branch 1 84/02/14 EDELMAN.M R Claveland Electric 111uminating Co 2pp 22397 358 24X Fiche 50-440,84/02/14,8402270287
- --840227027i Comments on 840116-20 audit of squipment qualification files Observations & comments made at 840117 exit interview listed Evaluation of program will be provided as input to future SEER NOONAN, V S Equipment Qualification Branch 84/02/14 YQUNGBLOOD, B J Licensing Branch 1 App 67195 203 24X Fichs 30-440, 84/02/14, 8402270287
- B40119006B Board Notification 84-033 provides "Bys Interaction Program," task action plan for Unresolved Safety Issue A-17 Distribution list encl EIBENHUT,D 0 Division of Licensing 84/02/16 PALLADIND Commissioners Spp 22482 091 24X Fiche 50-000, 84/02/16, 8401190068
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- B402010306 Forwards emergency preparedness evaluation addressing SER Outstanding Issue 19 Findings will be documented in Feb 1984 SSER 4.
 YOUNOBLOOD, B J Licensing Branch 1 84/01/17 EDELMAN, M R Cleveland Electric Illuminating Co 49pp 22046 240 24X Fiche: 50-440, 84/01/17, 8402010306
- 8402080083 Requests info re pressure leak testing of pressure isolation valves per SER Bection 3 7 4 NRC position on pressure leak testing encl Response requested within 5 days of ltr receipt.
 YOUNOBLOOD, B J. Licensing Branch 1, 84/01/25 EDELMAN, M R Cleveland Electric Illuminating Co. 3pp. 22172.338, 24X Fiche: 50-440, 84/01/25, 8402080083
- B402060105 Responds to NRC 831213 ltr on evaluation findings re SER Outstanding Issue 12 on manual initiation/termination of ESF eys. Blue indicating light will be installed above control switches for LPCT & LPCB injection values EDELMAN, M.R. Claveland Electric Illuminating Co. B4/01/31. YOUNGELOOD, B J. Licensing Branch 1 ip. 22089 116 24X Ficher 50-440, 84/01/31, 8402060105
- B402130424 Forwards SBER 4 (NUREG-OBS7) re facility operation W/o encl YOUNGBLGOD,B J. Licensing Branch i 84/02/08 EDELMAN.M P Cleveland Electric Illuminating Co Rpp. 22263 312 24X Fiche 50-440,84/02/08.8402150424
- B402240381 BAFETY EVALUATION REPORT RELATED TO THE OPERATION OF PERRY NUCLEAR POWER PLANT, UNITS 1 AND 2, Docket Nos 50-440 And 50-441, (Cleveland Electric Illuminating Company) * Division of Licensing, NUREO-0807 804. 84/02/28, 142pp 22381:118 24X Fiche: 50-440,84/02/28,8402240381.
- F Security, medical, emergency & fire protection plans
- 840201030& Forwards emergency preparedness evaluation addressing BER Outstanding Issue 19 Findings will be documented in Feb 1984 BBER 4.
 YOUNOBLOOD, B. J. Licensing Branch I 84/01/17. EDELMAN, M.R. Gleveland Electric Illuminating Co 49pp 22046, 240. 24X Fiche, 50-440, 84/01/17, 8402010306
- 8402140528 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per 810709 generic Ltr 81-27 W/o request, entire plan will be placed in PDR YOUNGBLOOD B. J. Licensing Branch 1 94/02/03 EDELMAN, M.R. Clevelend Electric Illuminating Co. 2pp. 22253.300 24% Fiche. 50-440,84/02/03,8402140528.
- 8402130140 Notification of 840210 meeting w/util in Bethesda.MD to discuss & clarify unresolved items addressed by NRC 840110 ltr re Revs 1 & 2 to emergency plan 8TEFAND, J J Licensing Branch 1 84/02/06, YOUNDBLOOD, 8 J Licensing Branch 1, 3pp. 22216 344 24X Fiche 50-440,84/02/06,8402130140

- 8402230284 Summary of 840207 meeting w/util in Bethesda,MD re detailed control room design review per Suppl I to NUREG-0737 List of participants encl
 STEFANO.JJ Licensing Branch I 84/02/16 YOUNGBLOOD.B J
 Licensing Branch I 5pp 22380 026 24X Fiche 50-440.84/02/16,
 8402230284
- 8402290432 Summary of 840210 meeting w/util in Bethesda, MD re NRC comments on emergency plan provided by util 840117 ltr Revised plan expected by 840430 STEFAND. J J Licensing Branch 1 84/02/17 YOUNGBLOOD B J Licensing Branch 1 3pp 22438 181 24X Fiche 50-440, 84/02/17, 8402270452
- G Adjudicatory correspondence
- 8402010197 Response to ABLB 831223 request for briefs on regulations & guidance applicable to Contention 16 re reliability of diesel generators Certificate of 8vc encl HOODHEAD.C P Hearing Branch 4 84/01/20 Atomic Safety and Licensing Board Panel 8pp 22040 351 24X Fiche 50-440,84/01/20.8402010197
- 8402010187 Ack 840125 agreement re deferment of 10th set of interrogatories until issuance of board notifications & 840126 meeting w/Transamerica Delaval.inc (TDI) & util owners et tr notifying TDI owners of meeting encl HOODHEAD.C P. Hearing Branch 4 84/01/25 HIATT.S Ohio Citizens for Responsible Energy 30pp 22039 193 24X Fiche 50-440, 84/01/25, 8402010187
- B402010055 Confirms B40130 telcon w/Judge Bloch, granting extension of time until B40227 for filing supplemental responses to Ohio Citizens for Responsible Energy interrogatories on Issues 4. B & 15
 BHIGER, M A Bhaw, Pittman, Potts & Troubridge BHIGER, M A Cleveland Electric Illuminating Co B4/01/30 BLUCK, P B , KLINE, J R , BRIGHT, O O Atomic Safety and Licensing Board Panel 3pp 22042 251 24x Fichs 30-440.84/01/30.8402010055
- B402070037 Forwards applicant response to notice of violation re several safety-related cables exiting cable tray Bections 1837 & 1840 which violated min training radius requirements WOODHEAD, C P Hearing Branch 4 B4/02/01 BLOCH.P B , BRIGHT, C O . KLINE, J R Atomic Bafety and Licensing Board Panel ip 22102 356 24X Fiche 50-440.84/02/01.8402070037
- B402070036 Advises of intention not to respond to Chio Citizens for Responsible Energy & Council on Energy Independence briefs on regulations re diesel generators
 MOODHEAD, CP Hearing Branch 4 B4/02/03 BLOCH, PB, BRIGHT, GD. KLINE, JR Atomic Bafety and Licensing Board Panel 19 22102 355 24X Fiche 50-440.84/02/03,8402070036
- 8402070122 Order extending time until 840221 for Commission to act to review 831115 director's decision.

 CHILK, S. J. Office of the Secretary of the Commission. 84/02/03 Commissioners 1p. 22102 265 24% Fiche 50-440,84/02/03,8802070122
- 8402070233 Reply to NRC & Dhio Citizens for Responsible Energy 840120 & 16 respective briafs on NRC regulations & guidance applicable to Issue 16 re reliability of diesel generators Certificate of Seve encl.

 SWIGER, M. A. Cleveland Electric Illuminating Co. SHIGER, M. A. Bhaw. Pittman, Potts & Trombridge 84/02/03 Atomic Safety and Licensing Board Panel 18pp 22101 115 24X Fiche 50-440,84/02/03,8402070233
- 84020B0033 Motion to reopen discovery on Issue 1 re emergency planning Certificate of Svc encl Related correspondence LDDGE, T J, Sunflower Alliance 84/02/03 Atomic Safety and Licensing Board Panel Spp 22128 076 24X Fiche 50~440, 84/02/03, 840020053
- B402080170 Reply to NRC & applicant briefs re regulations & guidance applicable to Issue 16 ASLB should adopt OCRE stds & interpretations as controlling stds for littigation of Issue 16. Centificate of Bvc encl HIATT. B t Ohio Citizens for Responsible Energy B4/02/03 Atomic Safety and Licensing Board Panel 4pp 22128 242 24x Fiche 50-440.84/02/03.8402080170
- 8402130107 Forwards corrected affidavit of EC Christiansen attached to 840208 answers to Uhio Citizens for Responsible Energy tenth set of interrogatories re Issue 16 Svc list encl.

 SHIGER, M. A. Shaw, Pittman, Potts & Troubridge SHIGER, M. A. Cleveland Electric Illuminating Co. 84/02/10 Docketing & Services Branch Spp. 22249 262 248 Fiche 50-440,84/02/10,8402150107

- 8402170108 Order establishing schedule for briefing on Sunflower Alliance appeal of ASLB 831202 partial initial decision on GA Brief due by 840321 SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel 84/02/15 2pp 22301
- B402220136 Brief in support of Sunflower 840214 motion to readmit Issue 12 ASLB urged to readmit Issue 12 & permit liberal discovery due to dismissal before interrogatories answered Certificate of Svc encl HIATT.8 L Dhio Citizens for Responsible Energy 84/02/17 Spp 22346 302 24X Fiche 50-440.84/02/17.8402220136
- 8402220239 Brief in support of Sunflower Alliance 840203 motion to respen discovery on Issue 1 re emergency planning Document proffered as addl support of motion Certificate of Svc encl Related correspondence

Related correspondence
HIATT, S.L. Ohio Citizens for Responsible Energy 84/02/17 10pp
22339 187 24X Fiche 30-440,84/02/17,8402220239

- 8402220353 Eleventh set of interrogatories on Issue 16 re diesel generators Certificate of Svc encl Related correspondence HIATT.8 L Ohio Citizens for Responsible Energy 84/02/17 Cleveland Electric Illuminating CO 6pp 22334 163 24X Fiche 50-440.84/02/17.8402220353
- 8402220163 Order extending time until 840228 for Commission to act to review 831115 Director's decision CHILK.S J Long Island Lighting Co 84/02/21 Suffolk County, NY 1p 22337 230 24X Fiche 50-440.84/02/21.8402220163
- 8402230054 Answer opposing Sunflawer Alliance, Inc 840203 motion to reopen discovery on Issus 1 re emergency planning Motion fails to show need for add1 discovery Certificate of Svc encl
 SWIGER.M A Cleveland Electric Illuminating Co SWIGER.M A Sh

encl
SWIGER.M A Cleveland Electric Illuminating Co SWIGER.M A Shaw,
Pittman, Potts & Troubridge 84/02/21 Atomic Safety and
Licensing Board Panel 7pp 22361 28B 24X Fiche 50-440,84/02/21,
8402230054

- 8402270059 Serves SSER 4 W/o encl Related correspondence WDDDHEAD.C P Hearing Branch 4 G4/02/21 BLUCH,P B , BRIGHT,Q O , KLINE,J R Atomic Safety and Licensing Board Panel 1p 22391 277 24X Fiche 50-440.84/02/21.8402270059
- 8402290088 Response to Sunflower Alliance 840203 motion to reopen discovery on Contention 1 re emergency planning Add1 discovery will be more appropriate & effective after rev of affeite plans completed W/Certificate of Svc WOODHEAD.C P Hearing Branch 4 84/02/23 Atomic Safety and Licensing Board Panel Spp 22426 043 24% Fichs 50-440,84/02/23,840229088
- M02280337 Forwards 940221 press release announcing that completion of Unit 1 planned for late 1985 Svc list encl Related correspondence SILBERG, J E Shaw, Pittman, Potts & Trowbridge SILBERG, J E Cleveland Electric Illuminating Co B4/02/24 BLOCH, P B , KLINE, J R , RRIGHT, 9 D Atomic Safety and Licensing Board Panel 4pp 22398 359 24% Fiche 50-440,84/02/24,8402280337
- 8402270101 Memorandum & order granting Sunflower Alliance, Inc motion to reopen discovery on emergency planning contention, Issue i BLOCH, P B . KLINE, J R . BRIGHT, C D Atomic Safety and Licensing Board Panel 84/02/28 Sunflower Alliance 4pp 22424 037 24% Fiche 50-440,84/02/28,8402290101
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8402020312 Forwards Amend 13 to F9AR EDELMAN.H R Cleveland Electric Illuminating Co 84/01/31. BENTON.H R Office of Nuclear Resutor Regulation, Director. 3pp 22049 234 24X Fiche 50-440,84/01/31,8402020312
- --B402020314 Amend i3 to FSAR * Cleveland Electric Illuminating Co 84/01/3i 321pp 22049 257 24X Fiche 50-440.84/01/31.8402020312
- M Antitrust correspondence
- 8402070222 Motion for clarification & correction of finding of NRR re GL antitrust review Util cannot be espected to mend ways if allowed to violate license conditions w/impunity Certificate at Svc oncl GOLDBERG, R Goldberg, Fieldman & Letham, P C 84/02/06 Commissioners 14pp 22102 134 24x Ficha 30-440,84/02/06,8402070222

- B402140179 Forwards finding of no significant entitrust changes, per telcon VOGLER, B H Hearing Branch 2 84/02/06 GOLDBERG, R Cleveland Electric Illuminating Co 86pp 28230 214 24X Fiche 50-440,84/02/06.8402140179
- B402240052 Requests reconsideration of B40131 dacision re imposition of civil penalty for util violation of License Condition 3 Femalty should be imposed & City of Cleveland 840206 motion should be considered in decision GOLDBERG, R Goldberg, Fieldman & Letham, P C GOLDBERG, R Cleveland. OH 84/02/22 PALLADINO, N J Commissioners 8pp. 22374 351 24X Fiche 50-440,84/02/22,8402240052
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8402090492 Proposed summary of ACRS Subcommittee on Perry 820628-29 meetings in Cleveland, OH re util OL application Proposed schedule encl

 * ACRS Advisory Committee on Reactor Safeguards 82/07/28 ACRS Advisory Committee on Reactor Safeguards 20pp 22192:220 24X Fisches 50-440, 82/07/28, 8402090492
- 8402010191 Forwards summary of ACRS 285th meeting on 840112-14 re OL, application & W Eddleman 840113 ltr re compromised plant safety NRC response to ACRS will be forwarded to ASLB & parties

 BARTH.C A Hearing Branch 1 84/01/20 KELLEY, J L Atomic Safety and Licensing Board Panel 9pp 22039 348 24X

 Fiche 50-400.84/01/20.8402010191
- G Inspection reports, IE Bulletins & correspondence
- B312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120153
- 8402130323 Forwards IE Insp Repts 50-440/83-38 & 50-441/83-36 on B31101-1231 No noncompliance noted KNOP:R C Region 3. Office of Director 84/01/25 EDELHAN, M R Cleveland Electric Illuminating Ca 2pp 22197 187 24X Fiche 50-440.84/01/25.8402130323
- --8402130327 IE Insp Repts 50-440/83-38 & 50-441/83-36 on 831101-1231 No nancompliance noted Major areas inspected plant housekeeping practices equipment maint followup on previous insp findings & 10CFR50 55(e) items GILDNER.M L. KONKLIN.J E Region 3, Office of Director 84/01/25 4pp 22197 189 24X Fiche 50-440,84/01/25,8402130323
- 8402100213 Forwards IE Insp Repts 50-440/83-37 & 50-441/83-35 cn 831130-1215 & notice of violation LITTLE.W 5. Region 3. Office of Director 84/01/27 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 22179 028 24X Fiche 50-440.84/01/27.8402100213
- --8402100217 Notice of violation from insp on 831130-1215 LITTLE.W 8 Region 3. Office of Director 84/01/27. 2pp 22179 030 24X Fiche 50-440.84/01/27.8402100213
- --8402100223 IE Insp Repts 50-440/83-37 & 50-441/83-35 on 831130-1215 Noncompliance noted failure to establish adequate qualification procedures & failure to implement design controls NAIBU, K R , FALEVITB, Z , CHRISTNOT, E Region 3, Office of Director 84/01/26 17pp 22179 032 24X Fiche 50-440,84/01/27. 8402100213
- 8402070037 Forwards applicant response to notice of violation reserveral safety-related cables exiting cable tray Sections 1839 & 1840 which violated min training radius requirements WDODHEAD, C.P. Hearing Branch 4 84/02/01 BLOCH, P.B. Atomic Bafety and Licensing Board Panel 1p 22102 356 24X Fiche 50-440,84/02/01,8402070037
- 8401170016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114.179 24X Fiche 50-000,84/02/03,8401170016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers." Svc list encl. DEYOUNG.R C. Director's Office. Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 156 24X Fiche. 50-000, 84/02/03, 8401190017.

- B402070247 Ack receipt of 840122 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50~440/83-31 & 50~441/83-30
 - NORELIUS.C E Division of Project & Resident Programs
 EDELMAN.M R Cleveland Electric Illuminating Co ip
 24X Fiche 50~440.84/02/03.8402070247 10 22101 216
- --B402070280 Responds to NRC B31223 ltr re violations noted in IE Insp Repts 50-440/83-31 & 50-441/83-30 Corrective actions duct covers installed in ductways & separation of raceway in accordance w/installation drawing EDELMAN.M R Cleveland Electric Illuminating Co 84/01/22 KEPPLER.J G Region 3. Office of Director 25pp 22101 217 24: Fiche 50-440,84/02/03,8402070247 22101 217 24x
- 8401170941 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Bys (10CFR30.App R) " Svc list
 - UORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc. 124pp 22365 259 24X Fiche 50-000,84/02/13,8401190041
- 8401190050 Board Notification 84-021 provides repts of Transamerica Delaval, Inc insps conducted from Mar 1979 to Oct 1983 EIBENHUT, D 0 Division of Licensing 84/02/13 PALLADINO Commissioners 5pp 22314 001 24X Fiche 50-000,84/02/13, 8401190050
- 8401170037 IE Info Notice 84-08. "10CFR50 7. 'Employee Protection '"
- 301190039 IE Info Notice of Co. Svc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/14 Consolidated Edison Co. of New York, Inc. 115pp 22365 141 24% Fiche 50-000,84/02/14,8401190039
- B401190045 IC Info Notice B3-63. Suppl 1, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc 118pp 22366 142 24X Fiche 50-000.84/02/15.8401190045
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Buitches Set Below Manufacturer Recommended Value " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co. of New York, Inc. 116pp 22366 024 24% Fiche 50-000,84/02/21,8401190062
- 8401190066 IE Info Notice 84-11. "Training Program Deficiencies " Byc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/24 Consolidated Edison Co of New York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Beals " |Oli90067 | Elinfo Notice of the Syclistence of the Syclistence | Syclistence | Syclistence | Syclistence | Sychology | Sychol
- 8 Reportable occurrences, LERs & related correspondence
- 8402140107 Provides update on reportable events re RCIC sys equipment room cooler & automatic restart of chiller Safe shutdown sys review to assess sys interaction to assure automatic or manual start complete SAILER. W F Oilbert Associates, Inc 83/12/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p 22217:352 24X Fiche 50-440,83/12/13,8402140107
- 8402030248 Final significant deficiency rept re defect in anti-rotational setscrew of Anchor Darling globe valves supplied by GE. Initially reported on 831229 Setscrew will be staked to stem collar threads Unit i valves completed 840111 EBELMAN.M R Claveland Electric Illuminating Cp 84/01/27 KEPPLER, J G Region 3, Office of Director 2pp 22067 213 24X Fiche 50-440,84/01/27.8402030248
- B402060338 Final deficiency rept re shop welds on some safety-related pipe supports supplied by Power Piping Co Initially reported on 830921 Site Nonconformance Rept NB-04 dispositioned to direct rework or repairs on 30 welds w/completion by 840630 EDELMAN.M R Cleveland Electric Illuminating Co 84/01/30 KEPPLER, J Q Region 3, Office of Director 3pp 22085 115 24% Fiche: 50-440, 84/01/30, 8402060388
- 8402060359 Suppl to 830831 interim deficiency rept re unrepresentative radiographs for two Borg-Warner valve assemblies Dus to delays in installation & review of radiographs for Unit 1. final rept now scheduled for 840801

 EDELMAN, M R Cleveland Electric Illuminating Co 84/01/30 MEPPLER, J G Region 3, Office of Director ip 22085 118 24X Fichs 50-440,84/01/30,8402060359

- 8402060400 Supplemental final deficiency rept re Transamerica Delaval, inc standby diesel generator sys IEEE 383 failure in Class IE circuit wiring Due to shipment problem instaliation scheduled to be completed 840316 EDELMAN, M R Cleveland Electric Illuminating Co 84/01/30 KEPPLERIJ G Region 3, Office of Director ip 22086 176 24X Fiche 50-440,84/01/30,8402060400
- 840206041i Updated final deficiency rept re bracket welds for main steam & recirculation sys pipe whip restraints Review of installation documentation will not be complete until B40316 EDELMAN.M R Claveland Electric Illuminating Co B4/01/30 KEPPLER.J G Region 3. Office of Director ip 22085 098 Ficho 50-440.84/01/30.8402060411
- 8402060500 Final Deficiency Rept RDC 78(83) re exhaust line back pressures exceeding manufacturers recommendations on diesel generators for HPCS sys Initially reported on 830805 Reported per Part 21 by Gilbert Assoc on 830727 EDELMAN. H R Cleveland Electric Illuminating Co 84/01/30 KEPPLER, J G Region 3. Office of Director 2pp 22083 112 Fiche 50-440,84/01/30,8402050500 55083 115
- 8402060507 Final Deficiency Rept RDC 84(83) re frameamerica Delaval. Inc engine mounted fuel oil line on diesel generator engines Initially reported on 831011 Rework on lines will be completed by 840A61 Also reported per Part 21 by vendor EDELMAN.M R Cleveland Electric Illuminating Co 84/01/30 KEPPLER, J G Region 3, Office of Director 2pp 22083 110 24X Fiche 50-440.84/01/30,8402060507
- 8402070345 Part 21 rept re linear converter device w/possible generic defect Initially reported on 840116 Written notifications issued Customer responses should be received by 840331 Final rept will be submitted by 840430

 DOBBON, J P Pacific Air Products Co 84/01/30 Director's Office, Office of Inspection and Enforcement 2pp 22114 299 24' Fiche 50-280,84/01/30,8402070365
- --8402070373 Part 21 rept re linear converter device w/possible generic defect Initially reported on 840116 Preliminary analysis indicates excessive wear of brass shaft guides Next rept will be submitted within 90 days Supporting info encl DODSON, J P Pacific Air Products Co 84/01/17 POTAPDVS, U Region 4, Office of Director 60pp 22114 301 24X Fichs 50-000, 84/01/30.8402070365
- 8402060378 Final deficiency rept re damage to dryer/separator strongback Initially reported on 830916 Polar crane recabled u/certified cable Util amended previous acceptance of handling & lifting procedure EDELMAN.M R Cleveland Electric Illuminating Co 84/01/31 KEPPLER, J G Region 3, Office of Director 3pp 22086:313 24X Fiche 50-440.84/01/31.8402060378
- 8402070393 Requests that NRC investigate design reliability of emergency diesel generators supplied by Transamerica Delawal. Inc Engine problems have been experienced since delivery of first vessel in May 1981 Related info encl MOLINA.J C Falcon Carriers, Inc 84/02/01 DENTON.H R ON Nuclear Reactor Regulation, Director 63pp 22076 057 24x Fiche 50-000,84/02/01.8402070393
- B402150190 Answers to Ohio Citizens for Responsible Energy tenth set of interrogatories re Issue 16 Certificate of Syc encl SWIGER, M A Cleveland Electric Illuminating Co B4/02/08 27pp 22245.295 24X Fiche 30-440.84/02/08.8402150190
- 8402170037 Interim deficiency rept re operator stem keys for motor operated valves supplied by Borg-Warner Initially reported on 840111 key retainers will be repaired or replaced Final rept will be submitted by 840615 EDELMAN.M R Cleveland Electric Illuminating Co 84/02/10 KEPPLER, J G Region 3, Office of Director 1p 22300 274 24X Fiche 50-440.84/02/10,8402170039
- 8402170149 Final deficiency rept re piping installation contractor ASME Code procurement problems Initially reported on 840112 Pullman Power Products revised Procedures IV-34, "Bite Purchasing" & VII-1, "Vendor Qualification" EDELMAN.M R Cleveland Electric Illuminating Co 84/02/10 KEPPLER.J G Region 3, Office of Director 2pp 22299 023 24X Fiche 50-440.84/02/10,8402170149
- 8402170273 Interim deficiency rept re math for ASME Section III, Class 2 & 3 supports & hangers installed in Class 1 supports
 Initially reported on 840112 Receipt insp program revised
 Next rept by 840430
 EDELMAN.M R Cleveland Electric Illuminating Co 84/02/10
 KEPPLER.J G Region 3, Office of Director 2pp 22297 074 24X
 Fiche 50-440,84/02/10,8402170273

- 8401190053 Board Notification 84-020 forwards info re Transamerica Delayal. Inc emergency diesel generator problems Attendance list meeting handouts & slides encl EISENHUT.DO Division of Licensing 84/02/13 PALLADIND Commissioners 102pp 22332 202 24% Fiche 50-000.84/02/13, 8401190053
- 8402220530 Part 21 rept re defective DSR & DSRV standby diesel generator turbocharger thrust bearing lubrication Deficiency not corrected by sys mud New recommendation will be sent to customers by 840330 BOYER:R E Transamerica Delaval, Inc 84/02/15 Director's Office, Office of Inspection and Enforcement 5pp 22332 182 24x Fiche 50-000,84/02/15,8402220330
- B4022B0701 Notification of B4030B meeting w/Transemerica Delaval.Inc (TDI) Duners Group in Wading River.NY to discuss TDI proposed progrem plan to qualify diesel generators CARUSO.R Division of Licensing 84/02/23 BERLINGER.C Division of Licensing 2pp 22414 340 24X Fiche 50-000.84/02/23. 8402280701
- 8402290166 Final deficiency rept re defective capstan springs used in Model PSA 1 & PSA 3 mechanical snubbers Initially reported on 831020 Snubbers inspected & capstan springs replaced Corrective action will be completed by 840630 EDELMAN.M R Cleveland Electric Illuminating Co 84/02/23 KEPPLER, J Q Region 3, Office of Director 2pp 22427, 122 24X Fiche 50~440,84/02/23,8402279166
- 8402270372 Discusses diesel generator testing program NRC position might change due to questionable reliability of Transamerica Delaval diesel generators Acceptability will be addressed in next SBER YOUNGELOOD. B. J. Licensing Branch | 84/02/23 EDELMAN, M. R. Cleveland Electric Tiluminating Co. 2pp. 22438 223 24X Fichs 50-440,84/02/23.8402270372
- DOCKET 50-443 BEABROOK NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8402010471 FOIA request for data & findings compiled as result of aerial survey of background radiation levels conducted by NRC in area surrounding facilities DOUGHTY, J. Seacoast Anti-Pollution League 83/10/20 NRC No Datalled Affiliation Given 1p 22061 351 24% Fiche 50-443,83/10/20.8402010471
 - 1070003 Responds to FOIA request for const completion dates for iclear plants currently under const & analyses containing stimates based on inclusion of Caseload Forecast Panel setings Forwards App A,B & C documents
 LTON.J M Division of Rules and Records, B3/10/31
 BENBAUM.D M Technical Analysis Corp 19pp 22193 292 24% (che 50-000.B3/10/31.8402090003
 - 8111170178 Summary of B10915 NRC caseload forecast panel meeting & site visit to assess const completion date WHEELER, L. L. Licensing Branch 3 81/10/29 Licensing Branch 3 2pp 22194 071 24% Fiche 50-000.83/10/31.8402090003
- 8402090079 Comments on review schedule Results expected for release in mid-Nov 1982 Projected fuel load date is Nov 1983 WHEELERL L Licensing Branch 3 82/09/22 EISENHUT.D 0. Division of Licensing 2pp 22194 069 24% Fiche 30-000. 63/10/31.8402090003
- --8402090181 Handwritten graphs, calculations & notes to const & preoperational testing activities & fuel load preparation * NRC No Detailed Affiliation Given 82/11/14 Bpp 22194 182 24X Fiche. 50-000,83/10/31,8402090003
- 8402010476 Responds to FOIA request for data & findings compiled as result of Aerial survey of background radiation levels conducted by NRC in area surrounding facilities Aerial survey not performed due to budget constraints FELTON.J M Division of Rules and Records 83/11/16 DOUGHTY.J Seacoast Anti-Pollution League 1p 22061 352 24X Fichs.50-443.83/11/16.8402010476
- B402150003 Third partial response to FBIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILK,S J Office of the Secretary of the Commission B3/12/14. Public Document Branch ip 22281 023 24% Fiche 50-000,83/12/14. 8402160003
- --8402160104 Discusses SECY-81-492 re director's denial of petition under 10CFR2 206 CHILKS J Office of the Secretary of the Commission 81/09/18 BICKWIT.L Office of the General Counsel. 1p 22281 103 24X Fithe 50-000,83/12/14,8402160003

- B312120136 Board Notification 84-011 discusses NRC use of terms "important to safety" & "safety-related" EISENHUT.D © Division of Liconsing B4/01/18 PALLADING Commissioners 72pp 22241 008 24X Fiche 50-000.84/01/18, 8312120136
- B402160479 Forwards Amend 6 to CPPR-135 & CPPR-136 & safety evaluation in response to B31017 application Amend grants permission to transfer current ownership share EISENHUT, D 0 Division of Licensing B4/01/27 TALLMAN, W C Public Service Co of New Hampshire 5pp 22302 133 24X Fiche 50-443,84/01/27,8402160479
- --B402160480 Amend & to CPPR-135 & CPPR-136 granting permission to transfer dwnership share EISENHUT, D.G. Division of Licensing 84/01/27 App 22302-138 24X Fiche 50-443.84/01/27,8402160479
- --8402160483 Safaty evaluation supporting Amend 6 to CPPR-135 & CPPR-131 granting permission to transfer current ownership share * Division of Licensing 84/01/27 2pp 22302 142 24X Fiche 50-443,84/01/27,8402160479
- ---B4021604B5 Notice of issuance of Amend 6 to CPPR-135 & CPPR-136 KNIGHTON, 0 W Licensing Branch 3 B4/01/27 3pp 22302 144 24X Fiche 50-443,84/01/27,8402160479
- 8402070255 Forwards "Seabrook Station Probabilistic Bafety Assessment,"
 Vols 1-6 & summary rept
 DEVINCENTIB.J Yankee Atomic Electric Co DEVINCENTIB.J Public
 Bervice Co of New Hampshire 84/01/30 KNIGHTON, 0 W Licensing
 Branch 3 3pp 22:15 132 24X Fiche 50-443,84/01/30.8402070255
- --8402070262 "Seabrook Station Probabilistic Safety Assessment," Vols 1-6 Summary rept encl GARRICK.J Pickard, Lowe & Garrick, Inc PLG-0300 84/01/30 4454pp 22115 136 24x Fiche 50-443,84/01/30,8402070255
- B402010410 Oeneric Ltr B4-04 to all operating PWR licensees, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in FWR primary main loops GVc list encl EIBENHUT, D 9 Division of Licensing B4/02/01 Consolidated Edison Co of New York. Inc. 59pp 22177 097 24X Fiche 50-000, 84/02/01.8402010410
- B4021606B1 Confirms rescheduled date für Caseload Forecast Panel 840303 visit in order to ensure most recent data available to Panel KNIGHTON.0 W Liconsing Branch 3 B4/02/01 HARRISON.R J Public Bervice Co of New Hampshire 3pp 22292 343 24X Fichs.50-443,88/02/01.84021606B1
- 8402160476 Forwards request for add1 info re facility flow measurement uncertainties & fuel rod bowing in Chapter 4.4 of FBAR KNIGHTON O W Licensing Branch 3, 84/02/06 HARRIBON R J, Public Service Co of New Hampshire App Fiche 50-443,84/02/06,8402160476
- 8402210066 Notification of Caseload Forecast Panel 840313-15 meetings w/util in Beabrook,NH to review const progress to obtain info for input to OL review scheduling process Agenda encl NERSES,V Licensing Branch 3 84/02/07 NNIGHTON,0 W. Licensing Branch 3 9pp 22321 348 24% Fiche 50-443,84/02/07,8402210066
- 8402140808 Forwards notes from 830727 meeting w/Lonergan Valve Co & United Engineers & Constructors in Philadelphia. PA to discuss Markowitz allegations re reliaf valves DEVINCENTIB. J Yankee Atomic Electric Co DEVINCENTIB. J Public Bervice Co of New Hampshire 84/02/08 KNIGHTON. 0 W Licensing Branch 3 7pp 22230 301 24% Fiche 50-443.84/02/08.8402140208.
- 8401190059 Board Notification 84-032 provides add1 info on environ qualification Submittal augments info in Board Notifications 84-04 & 64-007 EISENHUT, D. O. Division of Licensing, 84/02/13 Atomic Sefety and Licensing Board Panel 10pp 22314 204 24X Fiche 50-000,84/02/13,8401190059.
- 8402210262 Ack receipt of B40106 request to remove proprietary status from two vol rept. "Seismological & Geological Studies. Miranchi Area, New Brunswick & Central NH " Rept made publicly available KNICHTON. 9 W Litensing Branch 3, 84/02/13 HARRISON.R J Public Bervice Co of New Hampshire 2pp 22343-254 24X Fiche 50-443.84/02/13,8402210262

- 8402230004 Notifies of NRC Caseload Forecast Panel 840313-i5 visit to facility to obtain info re status of const of Unit 1 & components common to both units Meeting notice & agenda
 - enci enci KNIGHTCN.O W Licensing Branch 3 84/02/13 HARRISON R J Public Bervice Co of New Hampshire 4pp 22371 352 24X Fiche 50-443,84/02/13,8402230004
- B40119006B Board Notification B4-033 provides "Sys Interaction Program," task action plan for Unresolved Safety Issue A-17 Distribution list encl EISENHUT, D G Division of Licensing B4/02/16 PALLADINO Commissioners Spp 22482 091 24X Fiche 50-000,84/02/16,8401190068
- 8402170503 REVIEW OF SEABROOK UNITS 1 AND 2 AUXILIARY FEEDWATER SYSTEM RELIABILITY ANALYBIS FREECD, A. YOUNOBLOOD, R., PAPAZOGLOU, I. A. Brookhaven National Laboratory FIN A-3933 NUREG/CR-3531 B4/02/29 Division of Bafety Technology 194pp Available at NRC \$6.00 22304 320 24X Fiche 50-443,84/02/29,8402170503

F. Security, medical, emergency & fire protection plans

- B402210127 Revised radiological emergency plan, consisting of ltr of agreement between util & Seabrook Fire Dept & table of contents. W/840213 ltr THOMAS. 0 . DEVINCENTIB. J Public Service Co of New Hampshire DEVINCENTIB. J. Yankee Atomic Electric Co B4/02/06 KNIGHTON. 6 W Licensing Branch 3 5pp 22317 207 24X Fiche 50-443. B4/02/06. B402210129.
- 9. Adjudicatory correspondence
- 8402020223 Informs that 840109 ltr & four page statement to Commission served on all parties in proceeding Svc list & rules of practice enci H/o enci HOYT.H F Atomic Bafety and Licensing Board Panel 84/01/26 TYE.M J. Tufts Univ . School of Medicine 1p 22057 077 24X Fiche 50~443.84/01/26.8402020223
- 8402060200 Requests all filings of Dignan & Gad rs ALAB-75B DOHERTY, J F Doherty, J F B4/01/28 ROSENTHAL, A S , WILBER, H A , EDLES, G J Atomic Safety and Licensing Appeal Penel ip 22087 162 24X Fiche. 50-443, 84/01/28, 8402060200
- 8402130283 Forwards stipulation re withdrawal of contention on manual reactor trip testing & transmittal ltr in event that ASLB & other parties did not receive original submittal &AD,R K. Ropes & Gray GAD,R K Public Bervice Co of New Hampshire 84/02/08 HDYT,H , HARBOUR,J , LUEBKE,E A Atomic Safety and Licensing Board Panel. 2pp 22204 001 24X Fichs 50-443,84/02/08,8402130283
- --8402130286 Forwards stipulation re withdrawal of New England Coalition on Nuclear Pollution Contention 1 D 2 re manual trip testing.

 GAD, R K Ropes & Gray, GAD, R. K Public Service Co of New Hampshire. 84/01/27 HOYT. H. HARBOUR, J., LUEDKE, E. A. Atomic 8afety and Licensing Board Panel 2pp 22204 003 24X Fiche 50-443,84/02/08,8402130283
- --8402330270 Stipulation re withdrawal of contention re manual reactor trip testing Based on applicants representations in stipulation, New England Coalition on Nuclear Pollution, Inc withdraws Contention I.D. 2
 CURRAN, D. New England Coalition on Nuclear Pollution, DIONAN, T.O., OAD, R.K., Public Service Co. of New Hampshire 84/01/27
 4pp. 22204 005 24X Fiche 50-443,84/02/08,8402130283
- 8402140151 Motion for reconsideration of 820713 denial of Seacoast Anti-Pollution League (SAPL) Contention 5 ASLS should reverse decision & admit SAPL supplemental Contention 5 on basis util financially unqualified. Certificate of Svc encl. BACKUS-R.A Seacoast Anti-Pollution League BACKUS-R A Sactus. Shea & Meyer 84/02/10 Atomic Safety and Licensing Board Panel 4pp 22230.070 24X Fiche 50-443,84/02/10.8402140151
- 8402160189 Order delaying decision of matters raised by ALAB-748, ALAB-749, ALAB-751 & ALAB-757, affirming denial of motions to disqualify Judge HF Hout from presiding at ABLB hearings. CHILK, B. J. Office of the Secretary of the Commission 84/02/14 5pp R2276*255 24X Fiche 50-443,84/02/14,8402160189.
- B402220282 Offers no objection to New England Coalition on Nuclear Pollution proposal to withdraw Contention I D. 2 re manual reactor trip testing.
 PATTERSON,H.F. Hearing Branch 3 B4/02/14. HOYT.H., LUEBKE.E.A., HARBOUR.J. Atomic Safety and Licensing Board Panel 2pp 22337.033 24X Fiche: 50-443,84/02/14,8402220282

- 8402220110 Appeal of ASLB 840113 denial of motion to dismiss application for Unit 2 OL ASLB did not ack or examine significant changes recently occurring which impact ability to assess compliance Certificate of Svc encl BACKUS,R A Seacoast Anti-Pollution League BACKUS,R A Backus, Shea & Meyer 84702/17 Atomic Safety and Licensing Appeal Panel 14pp 22338 263 24X Fiche 50-443.84/02/17,8402220110
- 8402280330 Memorandum & order accepting New England Coalition on Nuclear Pollution stipulation & proposed withdrawal of Contention I D 2 re manual reactor trip testing HDYT.HF Atomic Safety and Licensing Board Panel 84/02/23 2pp 22397 081 24X Fiche 50-443.84/02/23.8402280330
- 8402280330 Answer to Seacoast Anti-Pollution League (SAPL) 820420 motion for reconsideration of denial of SAPL Supplemental Contention 5 Motion should be denied on merits as SAPL has stated no adequate basis Certificate of Svc ancl DIGNAN, T 0 Public Service Co of New Hampshire DIGNAN, T G Ropes & Gray 84/02/24 Atomic Safoty and Licensing Board Panel 10pp 22403 145 24X Fiche 50-443,84/02/24.8402280350
- 8402280394 Order denying Beacoast Anti-Pollution League (SEAC) appeal from ABLB 840113 order & establishing filing to be treated as motion for directed certification SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 84/02/24 Office of the Executive Legal Director 1p 22402 270 24% Fiche 50~443.84/02/24,8402280394
- H General correspondence
- 84022203BD Requests removal of name from distribution list LEWIS.N D Washington, State of 84/02/15 KNIGHTON.Q W Licensing Branch 3 lp 22335 286 24X Fiche 50-443,84/02/15, 8402203040
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8402270231 Forwards Amend 52 to FSAR, consisting of revised responses to NRC requests for add1 info.miscellaneous & minor editorial revs & responses to NRC licensing review open items

 JOHNSON, W.P. Public Service Co. of New Hampshire. 84/02/15

 KNICHTON, G.W. Licensing Branch 3. 3pp. 22396 115 24X

 Fiche 50-443,84/02/15,8402270231
- --8402270233 Amend 82 to FSAR * Public Service Co of New Hampshire 83/12/31 467pp 22396 118 24X Fiche 30-443,84/02/15.8402270231
- G. Inspection reports, IE Bulletins & correspondence
- 8402020121 Forwards IE Insp Repts 50-443/83-17 & 50-444/83-13 on 831017-1205 & notice of deviation STAROSTECKIR Division of Project & Resident Programs 83/12/27 HARRISDN.R J Public Service Co of New Hampshire 2pp 22056 196 24X Fiche 50-443,83/12/27,8402020121
- --8402020123 Notice of deviation from insp on 831017-1205 * Region i, Office of Director 63/12/27 App 22054 198 24X Fiche 50-443,83/12/27,8402020121
- --8402020127 IE Inep Repts 50-443/83-17 & 50-444/83-13 on B31017-1205 Deviation noted leak chase channels around containment penetrations X60 & X61 not connected to piping sys which vents leak chases through concrete to containment CERNE,A C , WESCOTT,H M , GRANT,J M Region 1, Office of Director 83/12/19 13pp 22056 200 24X fiche 50-443,83/12/27, 8402020121
- 84Q2010145 Intorim deficiency rept & response to IE Bulletin 83~06, "Nonconforming Matls Supplied by Tube-Line Corp " Preliminary review of test results indicates matl meets United Engineers & Constructors specs Next rept by 84Q301 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/12/30 MURLEY, T E Region 1, Office of Director. 3pp. 22038 218 24X Fiche 50~443,83/12/30, 8402010145
- 8312120153 IE Info Notice 84-06. "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/01/25 Consolidated Edison Co. of New York, Inc. 120pp, 22058-001 24X Fiche 50-000,84/01/25,8312120153
- 8402080354 Forwards IE Insp Repts 50-443/83-18 & 50-444/83-14 on 831114-18 No violations noted MARTIN.T T Division of Engineering & Technical Programs 84/01/25 HARRIBOUR,E J Public Bervice Co of New Hampshire 2pp 22130 237 24X Fiche 50-443,84/01/25,8402080354.

- --8402080361 IE insp Repts 50-443/83-18 & 50-444/83-14 on 831114-18 No violations noted Major areas inspected action on previous insp findings & piping & pipe support weldment NDE results for Unit 1 & safety-related concrete records for Unit 2 NARROW, L., GRAY, E.H., HARRIER, R.H. Region 1, Office of Director 84/01/25 12pp 22130 239 24% Fiche 50-443,84/01/25,8402080354
- 8402150003 Forwards IE Insp Repts 50-443/83-19 & 50-444/83-19 on B31128-1201 No violations noted
 MARTIN: T Division of Engineering & Technical Programs
 HARRISON: R J Public Service Co of New Hampshire 2pp
 22249 211 24X Fiche 50-443:84/01/26:8402150003 R4/01/26
- --B402150004 IE insp Repts 50-443/B3-19 & 50-444/B3-19 on B3112B-1201 No violations noted Major areas inspected licenses findings of Unit 1 reactor pressure vessel safe and radiographs KERCH.H W. DURR.JP Region 1. Office of Director B4/01/26 4pp 22249 213 24X Fiche 50-443/B4/01/26.B402150003
- 8402160312 Forwards IE Insp Rept 50-443/83-21 on 831219-22 No violations observed MARTIN T T Divisi HARTIN T Division of Engineering & Technical Programs
 HARRISON,R J Public Service Co of New Hampshire 2pp
 12277 001 24% Fiche 30-443.84/02/02.8402160312 84/02/02 22277 001
- --6402160315 IE Insp Rept 50-443/83-21 on 833219-22 No violations identified Major areas inspected preoperational & acceptance test procedure review & facility tour BRIGGS.L. BETTENHAUSEN.L Region 1. Office of Director B4/01/25 4pp 22277 003 24X Fiche 50-443.84/02/02.8402160312
- B401190015 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/03 Consolidated Edison Co. of New York, Inc. 119pp 22114 179 24X Fiche 50-000, B4/02/03, 8401190016 119pp
- 8401190017 IE Bulletin 84-01. "Cracks in BWR Mark I Containment Vent Network I Bullet Headers " Svc list encl DEYQUNG R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 156 24% Fiche 30-000 84/02/03,8401190017
- B402150361 Ack receipt of B31215 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-443/83-15 & 50-444/83-12

 STARGSTECKI, R Division of Project & Resident Programs HARRISGN, R J Public Service Co of New Hampshire ip 2243 123 24X Fichs 50-443,84/02/07,8402150361
 - 3402150365 Responds to NRC 831116 ltr re violations noted in IE Insp Repts 50-443/83-15 & 50-444/83-12 Corrective actions welds reinspected for lamelar tearing & wraparound weld length reinspected for lameial measured
 measured
 DEVINCENTIS, J. Yankee Atomic Electric Co DEVINCENTIS
 DEVINCENTIS, J. Yankee Atomic Electric Co DEVINCENTIS
 BELLO CO OF New Hampshire 83/12/15 STAROSTECKI.R DEVINCENTIE: J Public.

DEVINER(15.). Yankee Atomic Electric Co BEYI Bervice Co of New Hampshire 83/12/15 STAROS1 of Project & Resident Programs 5pp 22243 124 Fithe 50-443.84/02/09.8402150361 Division

10:190041 IE Info Notice 84-07, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFRSO, App R) " Syc list encl

VIGROAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22345 259 24X Fiche 50-000,84/02/13,840117004)

101190039 IE Info Natice 84-08, "10CFR80 7, 'Employee Protection '" Svc list encl

JORDAN. EL. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/14. Consolidated Edison Co. of New York. Inc. 115pp 22365 141 24X Fiche 50-000,84/02/14.8401190039

- 140229030A Forwards IE Insp Rept 50-443/83-20 on 831219-22 & motice of violation
 ARRINA, M.T. Division of Engineering & Technical Programs H4/02/14
 HARRISON, R. J. Public Service Co. of New Hampshire 2pp
 82426 354 24x Fiche 50-443,84/02/14,8402290306 22424 354
- 8402270311 Notice of violation from insp on 831219-22 * Region 1, Diffice of Director 84/02/14 1p 2 Fiche 50-443,84/02/14,8402270306 1p 22426 356, 24X
- 8402290316 IE Insp Rept 50-443/83-20 on 831219-22 Violation identified failure to properly install safety-related equipment per drawing requirements
 filmXEL.A E . ANDERSON.C J Region J. Office of Director
 84/02/02 App. 22426 357 24X Fiche 50-443,84/02/14,8402290306

- 8401190045 IE Info Notice 83-63. Suppl 1. "Potential Failures of Wastinghouse Type SA-1 Differential Relays " Svc list encl JORDAN, E L Division of Emergency Praparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc. 118pp 22365 142 24X Fiche 50-000.84/02/15.8401190045
- 8402220473 Ack receipt of 840202 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-443/83-17 & 50-444/83-13 50-444/83-13 STAROSTECKI,R Division of Project & Resident Programs HARRISON.R J Public Service Co of New Hampshire 1p 24% Fiche 50-443,84/02/16,8402220473 22340 093
- --B402220482 Responds to NRC 831227 itr re violations noted in IE Imap
 Repts 50-443/83-17 & 50-444/83-13 Corrective actions FBAR
 Section 3 8 1 will be amended to reflect lack of backfitting
 re leak chase channels omitted in const
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
 Service Co of New Hampshire 84/02/02 BTARDSTECKI.R Division
 of Project & Resident Programs 4pp 22340 074 24X
 Fiche 50-443,84/02/16,8402220473
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Fest 830103) 84/02/21 Consolidated Edison Co. of New York, Inc. 116pp 22366 024 24% Fiche 50-000.84/02/21,8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies" 101190066 IK info Novice G. ...
 Svc list encl
 Svc list encl
 JDRDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Smale " #01190067 IK Into Novice - Byc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/27 Consolidated Edison Co of New Yark, Inc 120pp 22431 060 24X Fiche 50-000,84/02/27,8401190067
- R Periodic operating reports & related correspondence
- B402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings.Forwards App A. B & C documents
 FELTON.J M Division of Rules and Records B3/10/31
 RDSENBAUM.D M Tethnical Analysis Corp 19pp 22193 292 24X
 Fiche 30-000.83/10/31.8408090003
- --8402090037 Submits 129th project performance rept for Mar 1983 Related info enc. EBNER, A M United Engineers & Constructors, Inc. (subs. of Raytheon Co.) 83/04/20 DEVINCENTIS, J. Yankee Atomic Electric Co. 22pp. 22193 315 24X Fiche 50-000,83/10/31,8402090003
- --8402090042 Submits 123rd project performance rept for Sept 1982 Related info encl EBNER: A M Ur Raytheon Co), United Engineers & Constructors, Inc. (subs. of o.), 82/10/25 DEVINCENTIS, J. Yankes Atomic Electric 22193 336 24X Fiche 50-000,83/10/31,8402090003
- --8402090045 Project Performance Rept 109 for Jul 1981 Related info ancl * Public Service Co of New Hampshire 81/07/31, 24pp 22193 342 24X Fiche.50-000.83/10/31.8402090003
- S Reportable occurrences, LERs & related correspondence
- 8402030235 Final deficiency rept re tornado missile shields for fuel storage bldg Initially reported on 821110 Probability analysis performed, revealing acceptably low risk Appropriate FSAR sections will be reviewed DEVINCENTIS, J. Yankes Atomic Electric Co DEVINCENTIS, J. Public Bervice Co of New Hampshirs 83/12/27 BTAROSTECKI, R Division of Project & Resident Programs 4pp 28067:191 24X Fiche 50-443,83/12/29,8402030235
- 8402010145 Interim deficiency rept & response to lE Bulletin 83-06, "Nanconforming Matla Supplied by Tube-Line Corp "Preliminary review of test results indicates matl meets United Engineers & Constructors specs Next rept by 840301, DEVINCENTIB, J. Yankee Atomic Electric Co DEVINCENTIB, J. Public Service Co. of New Hampshire. 83/12/30 MURLEY, T E Region I, Office of Director, 3pp 22038 218 24X Fiche 50-443,83/12/30, 8402010145

- 8402030305 Interim deficiency rept re Westinghouse 7300 process protection sys NLP card heat sinks & NTC card relays Initially reported on 830216 Heat sinks will be replaced w/ new style sink & replacement relay developed DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 84/01/04 STAROSTECKI, R Division of Project & Resident Programs 3pp 22069 079 24X Fiche, 50-443, 84/01/04, 8402030305
- 8402030422 Interim deficiency rept re potential undetectable failures in solid state protection sys test circuits preventing ESF initiation Westinghouse will supply field kits to modify protective sys DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 84/01/04 STAROSTECKI, R Division of Project & Resident Programs 3pp 22068 280 24% Fiche. 50-443, 84/01/04.8402030422
- BAQ2060225 Interim deficiency rept re Pacific Scientific mechanical shock arrester cracked capstan springs Initially reported on 831024 Deficiency under evaluation based on independent metallurgical evaluation Next rept by 840225
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 84/01/13 STARGBTECKI, R Division of Project & Resident Programs 3pp 22083 280 24X
 Fiche 50-443.84/01/13.8402060225
- 8402080400 Interim deficiency rept re Class IE hydrogen analyser contaminated w/fission-fragment iodine Initially reported on 830708 Change order issued to Comstp for mod kit to upgrade std configuration catalyst bed DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 84/01/16 STAROSTECKI, R Division of Project & Resident Programs 3pp 22131 004 24X Fiche 50-443.84/01/16.8402080400
- B402070344 Part 21 rept re svc water & circulating water pump house structure defect Analysis & design of structural mode to compression members re shrinkage effects approx 75% complete Next rept will be provided by 840229 KREIDER.H G United Engineers & Constructors, Inc. (subs. of Raytheon Co.) 84/01/31 Director's Office, Office of Inspection and Enforcement 3pp 22096 167 24% Fiche 50-443,84/01/31, B402070344
- 8402280083 Interim deficiency rept re Titeflax Corp flexible hose assemblies Initially reported on 831019 Butt joint redesigned & hose assemblies being reworked Final rept will be submitted when assemblies installed DEVINCENTIS, J Public Service Co of New Hampshire 84/01/31 8174NOBITECKIR Division of Project & Resident Programs Spp 22400 319 24X Fiche 50-443,84/01/31.8402280083
- 8402150363 Interim deficiency rept re electrical cable tray support bolts which could be subj to slippage Initially reported on 810727 Cable tray & conduit supports modified Final rept will be submitted upon completion DEVINCENTIS, J Yankse Atomic Electric Co DEVINCENTIS, J Public Bervice Co of New Hampshire 84/02/01 STAROSTECKI, R. Division of Project & Resident Programs 3pp 22242 321 24X Fiche. 30~443,84/02/01,8402150363

DOCKET 50-444 BEABROOK NUCLEAR STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8402010471 FOIA request for data & findings compiled as result of aerial survey of background radiation levels conducted by NRC in area surrounding facilities
 DUGHTY, J. Saacoast Anti-Pollution League 83/10/20 NRC No Detailed Affiliation Given 1p 22061 351 24X
 Fiche 50-443,83/10/20,8402010471
- 8402090079 Comments on review schedule Results expected for release in mid-Nov 1982 Projected fuel load date is Nov 1983 WHEELER.L L Licensing Branch 3 82/09/22 EISENHUT, D 0 Division of Licensing 2pp 22194 069 24% Fiche 50-000,83/10/31,8402090003
- 8402010476 Responds to FDIA request for data & findings compiled as result of aerial survey of background radiation levels conducted by NRC in area surrounding facilities Aerial survey not performed due to budget constraints FELTON.J M Division of Rules and Records 83/11/16 DOUGHTY,J Seaccast Anti-Pollution League 1p 22061 352 24X Fiche. 50-443,83/11/16,8402010476
- B402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILKS J. Office of the Secretary of the Commission B3/12/14 Public Document Branch ip 22281 023 24X Fiche 50-000.83/12/14.8400136003

- ---8402160104 Discusses SECY-81-492 re director's denial of petition under 10CFR2 206
 CMTLK.5 J Office of the Secretary of the Commission 81/09/18
 BICKWIT.L Office of the General Counsel 1p 22281 103 24X
 Fiche 90-000,83/12/14,8402160003
- B312120136 Board Notification B4-011 discusses NRC use of terms "important to safety' & "safety-rolated "
 EIBENHUT, D & Division of Licensing B4/01/18 PALLADING Commissioners 72pp 22241 008 24X Fiche 50-000,84/01/18, B312120136
- 8402160479 Forwards Amend 6 to CPPR-135 % CPPR-136 % safety evaluation in response to 8J1017 application Amend grants permission to transfer current ownership share EISENHUT, D O Division of Licensing 84/01/27 TALLMAN, W C Public Service Co of New Hampshire 5pp 22302 133 24% Fiche 50-443,84/01/27,8402160479
- ~~B4021604B0 Amend & to CPPR-135 & CPPR-136, granting permission to transfer ownership share EISENHUT.D G Division of Licensing 84/01/27 App 22302 138 24% Fiche 50-443,84/01/27,8402160479
- ~~8402160483 Safety evaluation supporting Amend 6 to CPPR-135 & CPPR-136, granting permission to transfer current ownership share * Division of Licensing 84/01/27 2pp 22302 142 24X Fithe 50-443,84/01/27,8402160479
- --8402160485 Notice of issuance of Amend 6 to CPPR-135 % CPPR-136 KNIGHTON 0 W Licensing Branch 3 84/01/27 3pp 22302 144 24% Fiche 50-443.84/01/27,8402160479
- B402070235 Forwards "Beabrook Station Probabilistic Safety Assessment 'Vols 1-6 & summary rept
 DEVINGENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
 Bervice Co of New Hampshire B4/01/30 KNIGHTON, G W Licensing
 Branch 3 3pp 22115 132 24X Fiche 50-443,84/01/30,8402070255
- --8402070262 "Seabrook Station Probabilistic Safety Assessment," Vols 1-6 Summary rept encl GARTICK, J Pickard, Lowe & Garrick, Inc PLG-0300 B4/01/30 4454pp 22115 136 24X Fiche 50-443,84/01/30,8402070255
- B402010410 Generic Ltr 84-04 to all operating PWR licensees.CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Svc 11st enci EISENWUT.D Q Division of Licenseing 84/02/01 Consolidated Edison Co of New York, Inc 59pp 22177 087 24X Fiche 50-000.84/02/01,8402010410
- B4021606B1 Confirms rescheduled data for Caseload Forecast Panel B40301 visit in order to ensure most recent data available to Panel Panel KNICHTON, CW Licensing Branch 3 B4/02/01 HARRISON, RJ Public Service Co. of New Hampshire 3pp 22292 343 24X Fiche 30-443.84/02/01.84021606B1
- 8402160476 Forwards request for add1 info re facility flow measurement uncertainties & fuel rod bowing in Chapter 4 4 of FSAR KNIGHTON:6 W Licensing Branch 3 84/02/06 HARRIEON:R J Public Service Co of New Hampshire épp 22302 147 24% Fiche 50-443.84/02/06.8402160476
- B402R10066 Notification of Caseload Furecast Panel B40313-15 meetings w/util in Beabrack.NH to review tonst progress to obtain info for input to OL review scheduling process Agenda encl NERBES. V Licensing Branch 3 84/02/07 KNIOHTON.6 W Licensing Branch 3 9pp 2R321 348 24X Fiche 50-443,84/02/07.8402210066
- 8402140208 Forwards notes from 830727 meeting w/Lonergan Valve Co & United Engineers & Constructors in Philadelphia, PA to discuss Markouitz allegations re relief valves DEVINCENTIS, J Public Service Co of New Hampshire B4/02/08 KNIGHTON, G W Licensing Branch 3, 7pp 22230 301 24X Fiche 50-443,84/02/08,8402140208
- 8401190059 Board Notification 84-032 provides add1 info on environ qualification Submittal augments info in Board Notifications 84-004 & 84-007 EISENHUT, D © Division of Licensing 84/02/13 Atomic Bafety and Licensing Board Pahel 10pp 22314 204 24X Fiche 90-000, 84/02/13.8401190059
- 8402210262 Ack receipt of B40106 request to remove proprietary status from two vol rept. "Seismological & Geological Studies, Miranchi Area, Naw Brunswick & Central NH" Rept made publicly available.

 KNICHTON.O W Licensing Branch 3 84/02/13 HARRISON.R J Public Bervice Co of New Hampshire 2pp 22343/254 24X

 Fiche 50-443,84/02/13,8402210262

- 8402230004 Notifies of NRC Caseload Forecast Panel 840313-15 visit to facility to obtain info re status of comst of Unit 1 & components common to both units Meeting notice & agenda encl
 - KNIGHTON, G W Licensing Branch 3 84/02/13 HARRISON, R J Public Service Co of New Hampshire 49p 22371 332 24X Fiche 50-443, 84/02/13, 8402230004
- B4011700AB Board Notification 84-033 provides "Sys Interaction Program," task action plan for Unresolved Bafety Issue A-17 Distribution list encl EISENRUT.D.9 Division of Licensing 84/02/14 PALLADING Commissioners 8pp 22482 091 24X Fiche 50-000, 84/02/16, 8401170068
- 8402170303 REVIEW OF SEABROOK UNITS 1 AND 2 AUXILIARY FEEDWATER BYSTEM RELIABILITY ANALYSIS
 FRESCO, A. YOUNOBLOOD, R. PAPAZOGLOU, I A Broothaven National Laboratory FIN A-3933 NUREG/CR-3531 84/02/29 Division of 88fety Technology 194pp Available at NRC \$6.00 22304 320 24X Fiche 50-443,84/02/29,8402170503
- F Security, medical, emergency & fire protection plans
- B402210127 Revised radiological emergency plan, consisting of ltr of agraement between util & Beabrook Fire Dept & table of contents W/840213 ltr THOMAS, O D. DEVINCENTIS, J. Public Service Co. of New Hampshire DEVINCENTIS, J. Yankee Atomic Electric Co. 84/02/06 KNIGHTON, O. Licensing Branch J. 5pp. 22317 207 24X Fiche 50-443,84/02/06,8402210129
- O Adjudicatory correspondence
- 8402020223 Informs that 840109 ltr & four page statement to Commission served on all parties in proceeding Svc list & rules of practice encl W/o encl HOYT.H F Atomic Safety and Licensing Board Panel 84/01/26 TYE.M J Tufts Univ , School of Medicine 1p 22057 079 24X Fiche 50-443,84/01/26,8402020223
- B402060200 Requests all filings of Dignan & Gad re ALAB-758 DDHERTY, J F Doherty, J F B4/01/28 ROSENTHAL, A S , WILBER, H A , EDLES, G J Atomic Bafety and Licensing Appeal Panel 1p 22087 162 24x Fiche 50-443. B4/01/28.
- 9402130283 Forwards stipulation re withdrawal of contention on manual reactor trip testing & transmittal ltr in event that ASLB & other parties did not receive original submittal OAD.R K Ropes & Gray OAD.R K Public Service Co of New Hampshire 84/02/08 HOYT.H , HARBOUR.J , LUEDKE,E A Atomic Safety and Licensing Board Panel 2pp 22204-001 24X Fiche 50-443,84/02/08,8402130283
- -8402130286 Forwards stipulation re withdrawal of New England Committee on Nuclear Pollution Contention 1 D 2 re manual trip testing.
 GAD.R K Ropes & Gray GAD.R.K Public Service Co of New Hampshire B4/01/27 H0YT.H , HARBOUR.J , LUEBKE, E A Atomic Safety and Licensing Board Panel 2pp 22204 003 24X
 Fiche: 50-443,84/02/08,8402130283
- -8402130290 Stipulation re withdrawal of contention re manual reactor trip testing Based on applicants representations in stipulation. New England Coalition on Nuclear Pollution. Inc withdraws Contention I D 2 CURRAN.D New England Coalition on Nuclear Pollution DIGNAN.T G . 6AD.R K Public Service Co. of New Hampshire. 84/01/27 4pp 22204 005 24X Fichs 50-443.84/02/08.8402130283
- 8402140151 Motion for reconsideration of 820913 denial of Seacoast Anti-Pollution League (SAPL) Contention 5 ASLB should reverse decision & admit SAPL supplemental Contention 5 on basis util financially inqualified Certificate of Svc encl BACKUS, R. A. Sascoast Anti-Pollution League BACKUS, R. A. Backus, Shea & Hayer B4/02/10 Abomic Safety and Licensing Board Panel 4pp 22230 090) 24X Fiche 50-443,84/02/10,8402140151
- IO2160189 Order delaying decision of matters raised by ALAB-748. ALAB-749, ALAB-751 & ALAB-757, affirming denial of motions to disqualify Judge HF Hoyt from presiding at ASLB hearings CHILK, S. J. Office of the Secretary of the Commission 84/02/14. Spp. 22276 255 24X Fiche 50-443.84/02/14.8402160189
- O2220R82 Offers no objection to New England Coalition on Nuclear Pollution proposal to withdraw Contention I D 2 remanual reactor trip testing PATTERSON, H. F. Hearing Branch 3 84/02/14 HOYT, H., LUEBKE, E.A., HARBOUR, J. Atomic Safety and Licensing Board Panel. 2pp 22337.053 24X Fiche 50-443,84/02/14,8402220282

- 8402220110 Appeal of ASLB 840113 denial of motion to dismiss application for Unit 2 OL ASLB did not ack or examine significant changes recently occurring which impact ability to assess compliance Cortificate of Svc encl BACKUS,R A Beacoast Anti-Pollution League BACKUS,R A Backus, Shea & Reyer BAY02/17 Atomic Safety and Licensing Appeal Panel 14pp 22338 263 24X Fiche 50-443,84/02/17,8402220110.
- B4022B033D Hemorandum & order accepting New England Coalition on Nuclear Pollution stipulation & proposed withdrawal of Contention I D 2 re manual reactor trip testing f(DYT.H F Atomic Safety and Licensing Board Panel 84/02/23 2pp 22399 0B1 24X Fiche 50-443,84/02/23,8402280330
- 8402280350 Answer to Seacoast Anti-Pollution League (SAPL) 820420 motion for reconsideration of denial of SAPL Supplemental Contention 5 Motion should be denied on merits as SAPL has stated no adequate basis Certificate of Syc encl DIGNAN, T G Public Service Co of New Hampshire DIGNAN, T G Ropes & Gray 84/02/24 Atomic Safety and Licensing Board Panel 10pp 22403 145 24X Fiche 50-443.84/02/24.8402280350
- 8402280394 Order denying Beacoast Anti-Pollution League (BEAC) appeal from ASLB 840113 order & establishing filing to be treated as motion for directed certification SHOEMAXER.C J Atomic Bafety and Licensing Appeal Panel 84/02/24 Office of the Executive Legal Director ip 22402.270 24X Fiche 50-443,84/02/24,8402280394
- H General correspondence
- B402220380 Requests removal of name from distribution list
 LEMIS,N D Washington, State of 84/02/15 KNIGHTON,O W.
 Licensing Branch 3 lp 22335 286 24% Fiche 50-443,84/02/15,840220380
- K Utility Final Bafety Analysis Report (FBAR) & amends
- B402270231 Forwards Amend 52 to FSAR, consisting of revised responses to NRC requests for add1 info, miscellaneous & minor editorial revs & responses to NRC licensing review open items.

 JOHNSON.W P. Public Service Co. of New Hampshire B4/02/15.

 KNIGHTON.O W Licensing Branch 3 3pp 22396 115 24X Fiche. 50-443, B4/02/15, B402270231
- --8402270233 Amend 52 to FBAR * Public Service Co. of New Hampshire 83/12/31 467pp 22394 118 24X Fiche 50-443,84/02/15,8402270231
- O Inspection reports. IE Bulletins & correspondence
- 8402020121 Forwards IE Insp Repts 50-443/83-17 & 50-444/83-13 on 831017-1205 & notice of deviation 8TAROSTECKI.R Division of Project & Resident Programs 83/12/27 HARRESON.R J Public Service Co of New Hampshire 2pp. 22056 196 24X Fiche 50-443.83/12/27.8402020121
- --8402020123 Notice of deviation from insp on 831017-1205 * Region 1, Office of Director 83/12/27 App 22056.198 24% Fiche 50-443.83/12/27,8402020121
- --8402020127 IE Insp Repts 50-443/83-17 & 50-444/83-13 on E31017-1205 Deviation noted leak chase channels around containment penetrations X60 & X61 not connected to piping sys which vents leak chases through concrete to containment CERNE, A C., WESCOTT, H M., ORANT, J, M. Region, 1, Office of Director B3/12/19. 13pp 22056 200 24X Fiche: 50-443,83/12/27,8402020121
- 8402010145 Interim deficiency rept & response to IE Bullatin 83-05.

 "Nonconforming Matls Supplied by Tube-Line Corp "
 Preliminary review of test results indicates matl meets
 United Engineers & Constructors specs Naxt rept by 840301.

 DEVINCENTIBL J Yankee Atomic Electric Co. 83/12/30 MURLEY, T E
 Region 1. Office of Director 3pp 22038, 218, 24X

 Fiche, 50-443, 83/12/30, 8402010145
- 8312120153 TE Info Nobice 84-06, "Steam Binding of Auxiliary Feedwater Pumps." Bvc list enc! JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/01/25 Consolidated Edison Co. of New York
- 8402080354 Porwards IE Insp Repts 50-443/83-18 & 50-444/83-14 on 831114-18 No violations noted MARTIN T Division of Engineering & Technical Programs 84/01/25 HARRIBON R J Public Bervice Co of New Hampshire 2pp 22130 237 84% Fiche 50-443/84/01/25/8402080354.

- --8402080361 IE Insp Repts 50-443/83-18 & 50-444/83-14 on 831114-18 No violations noted Major areas inspected action on previous insp findings & piping & pipe support weldment NDE results for Unit 1 & safety-related concrete records for Unit 2 NARROWLL GRAYLE H , HARRISIR H Region J. Office of Director 84/01/25 12pp 22130 239 24X Fiche 50-443,84/01/25,8402080357
- B402130003 Forwards IF Insp Repts 50-443/83-19 & 50-444/83-19 on B31128-1201 No violations noted MARTIN.T T Division of Engineering & Technical Programs B4/01/26 HARRIBON.R J Public Service Co of New Hampshire 2pp B4/01/26
- --8402150004 IE Insp Repts 50-443/83-19 & 50-444/83-19 on 831128-1201 No violations noted Major areas inspected licensee findings of Unit I reactor pressure vessel safe and radiographs KERCH/H W. DURR. J P. Region I. Dffice of Director 84/01/26 4pp 22247 213 24X Fiche 50-443.84/01/26,8402150003
- 8401190016 IE Info Notice 84-07. "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000.84/02/03.8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headors" Svc list encl DEYOUNG.R C Director's Office Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 156 24X Fiche 50-000,84/02/03,8401190017
- 8402150222 Corrects insp rept number for insp performed on 831128-1201 to 50-444/83-16
 MARTIN: T Division of Engineering & Technical Programs 84/02/06
 HARRIBON: R J Public Service Co of New Hampshire 2pp
 22244 249 24X Fiche 50-444,84/02/06,8402150222
- 8402150341 Ack receipt of 831215 ltr informing NRC of steps taken to carrect violations noted in IE Insp Repts 50-443/83-15 & 50-444/83-12

 BTAROSTECKI.R Division of Project & Resident Programs B4/02/09

 MARRIEDN.R J Public Service Co of New Hampshire ip 24X Fiche 50-443, 84/02/09, 8402150361
- --B402150365 Responds to NRC B31116 ltr re violations noted in IE Insp Repts 50-443/83-15 & 50-444/83-12 Corrective actions welds reinspected for lamelar tearing & wraparound weld length measured DEVINCENTIS, J. Yankee Atomic Electric Co DEVINCENTIS, J. Public Service Co of New Hampshire B3/12/15 STAROSTECKI, R. Division of Project & Resident Programs 5pp 22243 124 24X Fiche 50-443,84/02/09,8402150361
- B401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Bafe Shutdown Sys (10CFR50.App R) " Syc list enc!

 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259 24X Fiche 50-000.84/02/13.8401190041
- B401170039 IE Info Notice 84-08, "IOCFR50 7, 'Employee Protection '"

 Bvc list encl

 JRRDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/02/14 Consolidated Edison Co of New
 York, Inc. 115pp 22365 141 24X Fiche 50-000.84/02/14,8401170039
- 8401190045 IE Info Notice 83-63. Suppl 1, "Potential Failures of Westinghouse Type 8A-1 Differential Relays" Svc list encl. JORDAN. E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc. 118pp 22366 142 24X Fichs. 50-000, 84/02/15, 8401190045
- 8402220473 Ack receipt of B40202 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-443/63-17 & 50-444/83-13.

 STAROBTECKIR. Division of Project & Resident Programs HARRISON,R J. Public Service Co. of New Hampshire ip 24X Fisha 50-443,84/02/16.8402220473
- --8402220482 Responds to NRC 831227 ltr re violations noted in IE Insp. Rapts 80-442/83-17 & 50-444/83-13 Corrective actions: FBAR Section 3.8 1 will be amended to reflect lack of backfitting re leak chase channels omitted in const. DEVINCENTIB, J. Yankee Atomic Electric Co. DEVINCENTIB, J. Public Service Co. of Npw Hampshire 84/02/02 STAROSTECKI, R. Division of Project & Resident Programs 4pp 22340.094 24% Fiche. 50-443, 84/02/14, 8402220473.
- B4011700A2 IE Info Notice B4-10. "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN E L Division of Emergency Properedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000,84/02/21,8401170062

- 8401190066 IE Info Natice 84-11, "Training Program Deficiencies"

 Svc list encl

 JORDANIE L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/02/24 Consolidated Edison Co of New

 York, Inc 115pp 22430 304 24X Fiche 50-000.84/02/24.8401190066
- 8401190067 IE Infg Notice 84-12, "Failure of Soft Seat Valve Seals "
 Svc list encl
 JORDANNE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060 24X Fiche 50-000,84/02/27,8401190067
- R Periodic operating reports & related correspondence
- 8402090003 Responds to FDIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & Couments
 FELTON.J M Division of Rules and Records 83/10/31
 ROSENBAUM.D M Technical Analysis Corp 19pp 22193 292 24X
 Fiche 50-000.83/10/31.8402090003
- --8402070037 Submits 129th project performance rept for Mar 1983 Related info encl
 EBNER, A M United Engineers & Constructors, Inc (subs, of Raytheon Co) 83/04/20 DEVINCENTIS, J Yankee Atomic Electric Co 22pp 22173 315 24X Fiche 50-000, 03/10/31,8402070003
- --B402090042 Submits 123rd project performance rept for Sapt 1982 Related info encl
 EBNER, A M United Engineers & Constructors, Inc. (subs. of Reytheon Co.) 82/10/25 DEVINCENTIS, J Yankee Atomic Electric Co. 6pp 22193 336 24X Fiche 50-000, 83/10/31, 8402090003
- --8402090045 Project Performance Rept 109 for Jul 1981 Related info encl * Public Service Co of New Hampshire 81/07/31 26pp 22193 342 24% Fiche 50-000.83/10/31.8402090003
- 8 Reportable occurrences, LERs & related correspondence
- 8402030235 Final deficiency rept re tornado missile shields for fuel storage bldg Initially reported on 821110 Probability analysis performed, revealing acceptably low risk Appropriate FSAR sections will be reviewed DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/12/29 STAROSTECKI, R Division of Project & Resident Programs App 22067 191 24X Fiche: 80-443,83/12/29,8402030235
- 8402010145 Interim deficiency rept & response to IE Bulletin 83-06,
 "Nonconforming Mat1s Supplied by Tube-Line Corp "
 Preliminary review of test results indicetes mat1 meets
 United Engineers & Constructors specs Next rept by 840301
 DEVINCENTIS.J Yantee Atomic Electric Co DEVINCENTIS.J Public
 Service Co of New Hampshire 80/12/30 MyRLEY,T E Region 1.
 Office of Director 3pp 22038 218 24X Fiche 50-443.83/12/30.
 8402010145
- 8402030303 Interim deficiency rept re Westinghouse 7300 process protection sys NLP card heat sinks & NTC card relays Initially reported on 830216 Heat sinks will be replaced w/ new style sink & replacement relay developed DEVINCENTIS.J Yankee Atomic Electric Co DEVINCENTIS.J Public Bervice Co of New Hampshire 84/01/04 BIANDSIECKI, R Division of Project & Resident Programs 3pp 22069 079 24% Fiche: 50-443,84/01/04,8402030305
- B402030422 Interim deficiency rept repotential undatectable failures in solid state protection sys test circuits preventing EBF initiation Westinghouse will supply field kits to modify protective sys DEVINCENTIS. J Yankee Atomic Electric Co DEVINCENTIS. J Public Bervice Co of New Hampshire 84/01/04 STAROSTECKI, R Division of Project & Resident Programs 3pp 22068 280 24X Fichs 30-443.84/01/04.8602030482
- BAG2060R25 Interim deficiency rept re Pacific Scientific mechanical shock arrester cracked capstan springs Initially reported on 831024 Deficiency under evaluation.based on independent metallurgical evaluation Next rept by 840R25
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 84/01/13 BTARDBTECKI, R Division of Project & Resident Programs 3pp 22083 280 24x
 Fiche: 50-443,84/01/13,8402060225.
- 8402080400 Interim deficiency rept re Class IE hydrogen analyzer contaminated w/fission-fragment iodine initially reported on 830709 Change order issued to Comsip for mod kit to upgrade std configuration catalyst bed DEVINCENTIS.J Yankee Atomic Electric Co DEVINCENTIS.J Public Service Co of New Hampshire 84/01/16 STARDSTECKI.R Division of Project & Resident Frograms 3pp 22131 004 24X Fiche 50-443.84/01/16.8402080400

- B402070344 Part 21 rept re svc water % circulating water pump house structure defect Analysis & design of structural mods to compression members re shrinkage effects approx 75% complete Next rept will be provided by 840227 KREIDER H G United Engineers & Constructors. Inc (subs of Raytheon Co) B4/01/31 Director's Office, Office of Inspection and Enforcement 3pp 22096 167 24% Fiche 50-443.84/01/31. and Enforcement 8402070344
- 8402280083 Interim deficiency rept re Titeflex Corp flexible hose assemblies Initially reported on 831019 Butt joint redesigned & hose assemblies being reworked Final rept will be submitted when assemblies installed DEVINCENTIS. J. Public Service Co. of New Hampshire 84/01/31 STARDSTECKI. R. Division of Project & Resident Programs 3pp 22400 319 24X Fiche 50-443.84/01/31.8402280083
- B402150363 interim deficiency rept re electrical cable tray support bolts which could be subj to slippage Initially reported on 810727 Cable tray & conduit supports modified Final rept will be submitted upon completion DEVINCENTIS.J Yankee Atomic Electric Co DEVINCENTIS.J Public Service Co of New Hampshire 84/02/01 STAROSTECKI, R Division Project & Resident Programs 3pp 22242 321 24X Fiche 50-443.84/02/01,8402150363 Division of
- DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA . UNIT : A Application/construction stage documents & correspondence
- 8402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A. B & C documents FELTON, J M Division of Rules and Records 83/10/31 ROSENBAUM, D M Technical Analysis Corp 17pp 22173 272 24X Fiche 50-000,83/10/31.8402090003
 - 8402090124 Handwritten notes & calculations re facility const Related info enc)

 NRC - No Detailed Affiliation Diven 83/10/31 48pp 22194 200 24X Fiche 50-000, B3/10/31, 8402090003
 - 8402070133 Trip rept of 780418-19 site visit re in-progress const activity observation, const & startup schedules & estimated fuel load date NAVENTI.R Light Water Reactors Dranth 4 78/06/09 Water Reactors Branch 4 2pp 22/94 248 24X Fiche 50-000,83/10/31,8402070003
 - 8402090138 Handwritten notes & calculations re const activities Related 0 enc1 NRC - No Detailed Affiliation Given BO/10/21 20pp 194 255 24X Fiche 50-000, B3/10/31, 8402090b03
 - .02070140 Handwritten notes & calculations re const activities * NRC No Detailed Affiliation Given E3/10/31 3pp 22174 281 24X Fiche 50-000,83/10/31,8402090003

22194 255

- 10207008B Forwards util 831220 memo to all personnel defining policy re intimidation, harassment or threats to or from employees Disciplinary action will include termination GARY, R J Texas Utilities Generating Co 83/12/21 COLLINS, J T Region 4, Office of Director 2pp 22103 039 24X Fiche 50-445,83/12/21,8402070088
- 02030540 Informs that proposed post-accident sampling sys design meets criteria specified in TMI Action Plan Item II p 3 & is acceptable Evaluation will be incorporated into next SER suppi YOUNGBLOOD, B J Licensing Branch 1 84/01/23 GARY, R J Texas Utilities Co 2pp 22082 182 24% Fiche 30-445,84/01/23, 8402030540
- 01170012 Board Notification 84-013 forwards info re Transamerica Delaval.Inc emergency dieset generators EISENHUT.D G Division of Licensing 84/01/24 PALLADINO.N Commissioners 10pp 22054 346 24X Fiche 50-000.84/01/24,
 - 190015 Board Notification 84-01B.provides info re failure serience of Transamerica Delavel emergency diesel terators in marine svc BENHUT.D 0 Division of Licensing 84/01/27 PALLADINO,N missioners 385pp 22093 027 24X Fiche 50-000,84/01/27,)1190015 PALLADINO, N J

- 8402010410 Generic Ltr 84-04 to all operating PWR licensess, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Svc list encl EISEMHUT, D 0 Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc 59pp 22177 087 24X Fiche 50-000.84/02/01.8402010410
- 8402160630 Advises that inconsistency found in Cyngna rept re independent assessment program Cyngna should confirm that control & interlock circuitry for valve 1-88118 consistent w/design description in FBAR Section 7 & 5 YOUNDBLOOD. B J Licensing Branch 1 84/02/06 CARY, R J T Utilities Generating Co 3pp 22301 360 24X Fiche 50-445, 84/02/06,8402160630
- B402170061 Notification of 840210 meeting w/Transamerica Delayal, Inc (TDI) in Bethesda.MD to discuss program plan proposed by TDI Owners Group to qualify diesel generators CARUSO.R Division of Licensing 84/02/06 BERLINGER.C. Division of Licensing 2pp 22312 339 24X Fiche 50-000,84/02/06, 8402170061
- 8402130156 Responds to NRC 831216 ltr requesting util to perform major study of all safety-related mechanical equipment located in areas of potentially harsh environs Request unwarranted & technically unjustified Meeting w/NRC requested OARY, R J Texas Utilities Generating Co 84/02/07 YOUNOBLOOD, B J Licensing Branch i Spp 22204 101 24X Fiche 50-445,84/02/07, 8402130156
- 8402170033 Summary of 831208 meeting w/Cygna Energy Svcs & util in Bethesda,MD re independent assessment program performance Bethesdam - & conclusions BURNELL, S. B. Licensing Branch 1 84/02/07 Licensing 4886 22312 227 24X Fiche 50-445,84/02/07,8402170033
- 840i190059 Board Notification 84-032 provides add1 info on environ qualification. Submittal augments info in Board Notifications 84-004 & 84-007 EISENHUT, D 9 Division of Licensing 84/02/13 Atomic Bafety and Licensing Board Panel 10pp 22314 204 24X Fiche 50-000,84/02/13,8401190059
- 840119006B Board Notification 84-033 provides "Sys Interaction Program," task action plan for Unresolved Bafety Issue A-17 Distribution list encl EISENHUT, D G Division of Licensing 84/02/16 PALLADING Commissioners 8pp 22482 091 24X Fiche 50-000, 84/02/16, 840119006B
- 0402220373 Forwards response to Items 1a & 1b.per NRC 840109 request reindependent assessment program performed by vendor Response to supplemental info supplied by 831227 ltr
 WILLIAMS.N H 'Cygna Energy Services 84/02/16 BURWELL.8 NRC ND Datailed Affiliation Given SCHMIDT.H Westinghouse Electric
 Corp 5pp 22334:294 24X Fiche 50-445.84/02/16,8402220373.
- 8402230009 Notifies that Hestinghouse developed NOTRUMP small break LOCA analysis code to address TMI Action Plan Item II K 3.30 & Generic itr 83-33 NOTRUMP SER to be released in Feb 1984 SCHMIDT.H C Texas Utilities Generating Co 84/02/17 EISENHUT.D 0 Division of Licensing Ip 22361 298 24X Fiche 50-445.84/02/17.8402230009
- B402230061 Responds to Generic Ltr B3-10C re plan for resolution of TMI Action Plan Item II K 3 5. "Automatic Trip of Reactor Coolant Pumps" Response will not be available on B40227 dum to delay in Westinghouse Gumers Group Study SCHMIDT.H C Texas Utilities Generating Co B4/02/17. YOUNGBLOODS J Licensing Branch 1 1p 22362 127 24X Fiche: 50-445,84/02/17,8402230061
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- B402020020 Forwards SSER on TMI Action Item I Q 1 re special low power test program, submitted by HC Schmidt 830707 ltr Program acceptable, SER Confirmatory Issue 11 resolved YCUNOBLOOD, B J Licensing Branch 1 84/01/23 GARY, R J Teras Utilities Genorating Co 3pp. 22042 314 24X Fiche 50-445, 84/01/23,8402020020
- 8402030540 Informs that proposed post-accident sampling sys design meets criteria specified in TMI Action Plan Item II B 3 & is acceptable. Evaluation will be incorporated into next SER suppl YOUNGBLOOD.B J Licensing Branch 1 84/01/23 GARY.R.J. Utilities Co 2pp 22082 182 24X Fiche 50-445.84/01/23. TRXAS Utilities Co 8402030540

- 8402060266 Forwards SSER re SER Outstanding Issue 1 re protection effects associated w/postulated rupture of piping outside containment Issue resolved YOUNOBLOOD, B. J. Licensing Branch 1 84/01/24 GARY, R. J. Texas Utilities Generating Co. 2pp. 22103 175 24% Fiche 50-445, 84/01/24,8402060266
- --B402060272 SSER re SER Outstanding Issue 1 on protection against sffects associated w/postulated rupture of piping outside containment Issue resolved

 * Auxiliary Systems Branch 84/01/24 7pp 22103 177 24X Fiche 50-445,84/01/24,8402060266
- 8402060568 Forwards list of unresolved SER issues requiring resolution prior to Unit 1 licensing List also identifies Tech Specs which need to be settled as well as new issues raised by NRC. Response due 60 days before licensing YOUNOBLOOD, B J Licensing Branch 1 84/01/24 GARY, R J Texas Utilities Generating Co 10pp 22092 115 24X Fiche 50-445,84/01/24,8402060568
- B402240149 Forwards schedule for response to BER unresolved issues identified in NRC B40124 ltr
 SCHMIDT.H C Texas Utilities Generating Co 84/02/16
 YOUNDBLODD, B J Licensing Branch 1 3pp 22374 332 24x
 Fiche 50-445,84/02/16,8402240149
- F Security, medical, emergency & fire protection plans
- 8402160203 Advises that emergency preparedness field exercise postponed from 831005 to 831214 due to rescheduling of emergency preparedness planning activities CLEMENTS, B.R. Texas Utilities Generating Co. 83/09/19 COLLING. J.T. Region 4. Office of Director 1p. 22276 260 24X Fiche 50-445, 883/09/19, 8402160203
- 8402160347 Forwards IE Insp Repts 50-445/83-46 & 90-446/83-21 on B31212-15 No violations or deviations identified JOHNSON,E H Region 4, Office of Director 84/01/23 GARY,R J Texas Utilities Generating Co. 1p 22268 351 24X Fichs 50-445,84/01/23,8402160347
- --8402160356 IE Insp Repts 50-445/83-46 & 50-446/83-21 on 831212-15 No violations or deviations identified Major areas inspected performance & capabilities during exercise of emergency plans & procedures MONTGOMERY, J L , WISNER, C E Region 4, Office of Director HERRINOTON, W N Battelle Memorial Institute, Pacific Northwest Laboratory 84/01/19 7pp 22268 353 24X Fiche 50-445, 84/01/23,8402160347
- B402060637 Approves request for 19 deviations from 10CFR50. App R re fire protection for safe shutdown sys SSER encl YOUNGBLOOD, B J. Licensing Branch 1 84/01/24 GARY, R J Texas Utilities Generating Co 3pp 22092 003 24% Fiche 50-445, B4/01/24, B402060637
- --8402060640 SSER approving fire protection program per 10CFR50,App R. w/listed deviations.
 YOUNGBLOOD. B J. Licensing Branch 1 84/01/24. 19pp 22072 006
 24% Fiche 50-445,84/01/24,8402060637
- 8402280514 Forwards IE Emergency Preparedness Appraisal Repts 50-445/83-33 & 50-446/83-17 on 830926-1007 Discussion of significant preparedness deficiencies in emergency preparedness program also encl JOHNSON, E. H. Region 4, Office of Director 84/02/08 GARY, R. J. Texas Utilities Generating Co 18pp 22407 223 24X Fiche. 50-445, 84/02/08, 8402280514
- --8402280536 IE Emergency Preparadness Appraisal Repts 30-445/83-33 & 50-446/83-17 on 830926-1007. Major areas inspected; emergency organization training, emergency facilities & equipment, procedures & coordination w/offsite groups & drills, MONTGOMERY, J L, ROHRER, D M, WISNER, C E Region 4, Office of Director 84/02/06 72pp 22407 241, 24X Fiche 50-445,84/02/08, 8402280514

G Adjudicatory correspondence

B402010230 Response opposing Citizens Assoc for Sound Energy 840103 motion for reconsideration of ABLB 831228 scheduling orders Motion unsubstantiated Certificate of Svc encl MIZUNO.0.S. Hearing Branch i. 84/01/26 Atomic Safety and Licensing Board Panel 11pp 22040 225 24X Fiche 50-445.84/01/26.8402010830

- B402010231 Response to applicant 840117 motion for reconsideration of ASLB 831226 memorandum % order to 0A for design Record insufficient Reconsideration of Walsh/Doyle concerns opposed Certificate of Svc encl MIZUNO.0 S Hearing Granch 1 84/01/27 Atomic Safety and Licensing Board Panci 10pp 22040 177 24X Fiche 50-445.84/01/27.0402010231
- 8402010209 Reply to Citizens Assoc for Sound Energy 831223 response to applicant certification of issues No further ASLB action required Certificate of Svc encl REYNOLDS:N S. HORIN: M. A. Texas Utilities Generating Co. REYNOLDS:N S. Dishop. Liberman. Cook. Purcell & Reynolds. 84/01/30 Atomic Safety and Licensing Board Panel. 40pp. 22040-236-24X Fiche 50-445.84/01/30,8402010209
- B40206013B Reply opposing Citizens Assoc for Sound Energy B31223 response to applicant identification of issues Certificate of Svc encl REYNOLDS.N S . KDRIN.N A Texas Utilities Generating Co REYNOLDS.N S Bishop, Liberman, Cook, Purcell & Reynolds 84/01/30 AOpp 22087 062 24X Fiche 50-445.84/01/30.8402060138
- 8402010210 Memorandum requesting util & NRC to file info re ability of GA program to detect design/const problems in Delaval generators. Fraquency of problems w/generators & assurance of public safety Sua sponte review inappropriate
 BLOCH.P B Atomic Safety and Licensing Board Panel 84/01/31 2pp
 22041 357 24X Fiche 50-445.84/01/31.8402010210
- 8402020221 Order continuing obligation to update interrogatories by 840229 BLOCH, P B Atomic Safety and Licensing Board Panel 84/01/31 ip 22057 083 24X Fiche 50-445,84/01/31,8402020221
- 9402030160 Answer apposing Citizens Assoc for Sound Energy (CASE) motion for reconsideration of ASLB 831228 memorandum & order re design GA CASE claims invalid, inappropriate & unfounded REYNOLDS:N S , HORIN.W A Texas Utilities Generating CO REYNOLDS:N S Bishop, Liberman, Cook, Purcell & Reynolds 84/02/01 Atomic Safety and Licensing Board Panel App 22048 107 24% Fiche 50-445,84/02/01,8402030160
- --B402030165 Affidavit of DH Wade re involvement of D Forg in independent design review & procedures applicable to communications Certificate of Svc encl WADE, D H Texes Utilities Generating Co 84/02/01 4pp 22068 113 24X Fiche 50-445,84/02/01,8402030160
- 8402040150 Answer apposing applicants & NRC 840117 motions for reconsideration of ASLB 831228 memorandum % order re GA for design ELLIS.J Citizens Association for Sound Energy 84/02/01 Atomic Safety and Licensing Board Panel 27pp 22089 191 24X Fiche 50-445,84/02/01.8402040150
- --8402060193 Forwards executed affidavits of J Doyle & M Walsh in support of Citizens Assoc for Sound Energy answer to applicant & NRC motions for reconsideration of ASLB memorandum & order re GA for design
 ELLIS, J Citizens Association for Sound Energy 84/02/01
 Docketing & Services Branch 3pp 22087 218 24X
 Fithe 50-445,84/02/01.8402060150
- --8402060158 Affidavit of J Doyle re applicant 840117 motion for reconsideration of memorandum & order on QA for design DOYLE.J Citizens Association for Sound Energy 84/01/28 15pg 22089 221 24X Fiche 50-445.84/02/01.8402060150
- --8402060161 Affidavit of MA Walsh re applicant QA program discussed in applicant motion for reconsideration of memorandum & order Certificate of Svc encl WALBH, M A Citizens Association for Sound Energy 84/01/30 21pp 22087 236 24X Fiche 50-445,84/02/01,8402060150
- 8402070056 Forwards applicant 840123 ltr.answer protesting civil penalty & response to notice of violation W/o encls HIZUNO. 9 8 Hearing Branch i 84/02/01 BLOCH.P B , JORDAN.W H , MCCOLLOM.K A Atomic Safety and Licensing Board Panel ip 22103 037 24X Fichs 50-445.84/02/01.8402070056
- B402070171 Sixteenth set of interrogatories & requests to produce listed documents re CYGNA rept Certificate of Svc encl ELLIB.J Citizens Association for Sound Energy 84/02/02 Texas Utilities Generating Co 8pp 22102 228 24X Fiche 50-445, 84/02/02,8402070171

- 8402140170 Response partially supporting Citizens Assoc for Sound Energy 831223 response to util identification of issues & 840116 motion for clarification of issues Certificate of Byc
 - MIZUNO, 0 9 Hearing Branch 1 84/02/02 Atomic Safety and Licensing Board Panel 33pp 22230 172 24X Fiche 50~445,84/02/02.8403140170
- 8402070227 Util plan to respond to ASLB 831228 memorandum & order re GA for design Independent design review will be conducted by Cygna Energy Sycs,per ASLB recommendations Certificate of
 - SYC enci REYNOLDS,N S Texas Utilities Generating Co REYNOLDS.N S Liberman, Cook, Purcell & Reynolds 84/02/03 12pp 22101 24X Fiche 50-445,84/02/03.8402070227 12pp 22101 152
- 8402090161 Order denying 840113 motion for reconsideration of 831228 & 840103 scheduling orders re site-visit discovery & motion to reopen record re firing of R Hamilton BLDCH,P B , JURDAN,W H , MCCDLLDM.W A Atomic Safety and Licensing Board Panel 84/02/06 Citizens Association for Sound Energy 10pp 22163 127 24X Fiche 50-445,84/02/06,8402090161
- 8402140168 Response to Citizens Assoc for Sound Energy 840117 motion for reconsideration of ASLB 831228 memorandum & order re QA for design Motion supported in part & apposed in part Certificate of Svc enci MIZUNO, 8 S Hearing Branch 1 84/02/06 Atomic Safety and Licensing Board Panel 12pp 22230 160 24X Fiche 50~445,84/02/06,8402140168
- 8402100066 Forwards prefiled testimony of J Doyle,W Walsh,H Stiner & D Stiner re CYGNA rept & associated welding matters,per ABLB 831928 memorandum & order, for 840220-24 hearings Certificate
 - of Svc enc: ELLIS, J Citizens Association for Sound Energy B4/02/07 TLOCH, P B , JORDAN, W H , MCCOLLOM, K A Atomic Bafety and Licensing Joand Panel 3pp 22178 300 24% Fiche 50-445,84/02/07,8402100066
 - J2090121 Memorandum A order responding to motion for reconsideration of Decision LBP B3-B1 re GA for design Footnote 37 will be ctruck
- ECTUEX
 BLOCK.P B., JORDAN.W H., MCCGLLOM.K A. Atomic Safety and Licensing
 Board Panel B4/02/08 Texas Utilities Generating Co. JBpp
 22163 276 24X Fiche 50-445, B4/02/0B, 8402070121
- 8402100111 Forwards proposed subposma to compel appearance of DD Hatley for deposition on 840215 re const & CYONA evaluation Notice of deposition encl
 HARTMAN.S.L. Bishop, Liberman, Cook, Purcell & Reynolds 84/02/08
 BLOCH, P. B. Atomic Safety and Licensing Board Panel 2pp
 22182 193 24% Fishe 50-445.84/02/08.8402100111
 - 8402100113 Subpoena directing DD Hatley to appear on 840215 in Fort Worth TX for deposition Certificate of Svc encl BLOCH P 8 Atomic Safety and Licensing Board Panel 84/02/08 HATLEY, D D Affiliation Not Assigned. Spp 22182 195 24X Fiche 50-445-84/02/08.8402100111
 - \$02100115 Notice of DD Hatley 840215 deposition in Fort Worth, TX reconst & CYONA evaluation Certificate of Bvc encl
 HARTMAN.5 L Texas Utilities Generating Co HARTMAN, S L Bishop,
 Liberman, Cook, Purcell & Reynolds 84/02/08 4pp 22182 200
 24X Fiche 50-445,84/02/08,8402100111. Bishop,
- 1021Q01B4 Forwards rebuttal testimony of applicant panel re welding & ABME & AMS Code provisions Encls will be introduced at hearings commencing on 840220 REYNBLDB,N S Bishop, Liberman, Cook, Purcell & Reynolds REYNBLDB,N S Texas Utilibies Generating Co B4/02/08 BLOCH,P B, JORDAN,W H, MCCOLLOM,K A Atomic Safety and Licensing Board Panel 4pp 22181 341, 24X Fiche, 50-445, 84/02/08, 8402100184
- 8402100190 Rebuttal testimony of WE Baler, CT Brandt, MD Muscente, FE Coleman, CR Brown, JD Green, JE Hallford, I Pickett, AM Braumuller & S Fernandez on Bitiner allegations re weave welding & welding of misdrilled holes
 BAKER, WE, COLEMAN, FE, DROWN, CR, Texas Utilities Generating
 Ca 84/02/08 56pp 22181:345 24X Fiche 50-445, 84/02/08, 860210084 8402100184
- 02140065 Notice of appearance in proceeding. Certificate of Svc enci HIGKS.R Texas, State of 84/02/09 3pp 22217 185 24X Ficher 50-445.84/02/09.8402140065
- 02130293 Forwards return on svc of subpoens served on DA Hatley in proceeding Related correspondence.

 #ARTMAN.S L Bishop, Liberman, Cook, Purcell & Reynolds 84/02/10
 Office of the Becretary of the Commission 2pp 22203 361 24X
 Ficha: 50-445,84/02/10,8402130293

- 8402140176 Memorandum requesting util comments on whether T Brandt erroneously interpreted H Stiner testimony re location of allegedly improper weave welds BLOCH.P B Atomic Safety and Licensing Board Panel 84/02/10 lp 22230 208 24X Fiche 50-445,84/02/10,8402140176
- 8402150097 Partial answer to applicant 840203 plan to respond to memorandum & order re GA for design Applicant proposal totally inadequate & nonresponsive to ASLB concerns ELLIS. J Citizens Association for Sound Energy 84/02/10 Safety and Licensing Board Fanel ilpp 22247 250 24X Fiche 50-445,84/02/10.8402150097 Atomic
- 8402130144 Motion for extension of time to 840305 to answer applicant B40203 plan to respond to memorandum & order re GA for design Certificate of Svc encl ELLIB, J Citizens Association for Sound Energy 84/02/10 Atom Safety and Licensing Board Panel 4pp 22249 271 24X Fichs 50-445,84/02/10,8402130144
- 840215020B Motion to late file testimony of new witness Hatley testimony contains substantive & pertinent matl necessary to complete record Certificate of Svc encl ELLIS, J Citizens Association for Sound Energy 84/02/10 Safety and Licensing Beard Panel 4pp 22244 084 24X Atomic Fichs 50-445, 84/02/10, 8402150208
- --8402150215 Testimony of D Hatley re documentation control at MALIDOLIS TESTIMONY OF D METERY PE UDCOMENTATION CONTYOL AT Facilities * Atomic Safety and Licensing Board Panel 84/02/07 14pp 22244 088 24% Fiche 50-445,84/02/10.8402150208
- B400220187 Forwards listed correspondence on admitted issues per B40112 telcon w/parties H/o encls Related correspondence MIZUNDO S Hearing Branch 1 84/02/13 BLOCH P B . JORDON, W H . MCCOLLOB, K A Atomic Bafety and Licensing Board Panel 2pp 22340 232 24% Fiche 50-445, 84/02/13, 8402220187
- 8402170119 Informs that MN Bressler will be replaced by RE Lorent: & JD Stevenson in testimony re allegations on AMS & ASME Code provisions Rebuttal testimony encl REYNOLDS, N 9 Bishop, Liberman, Cook, Purcell & Reynolds REYNOLDS, N 8 Texas Utilities Generating Co 84/02/15 BLOCH, P B , JDRDAN, W H , MCCOLLOM, K A Atomic Sefety and Licensing Board Panel 2pp 22300 328 24% Fiche 50-445,84/02/15,8402170119
- -8402170126 Rebuttal testimony of WE Baker, ND Muscents, JD Stevenson & POLITORIES REDUCTED TESTINGBY OF WE BAKET, BD BUSCENCE, DD BLE RE Lorents Te allegations involving AWS & ABME Code provisions BAKER, W.E., MUSCENTE, M.D., STEVENSON, J.D. Brown & Root Col (subs. of Halliburton Corp.) 84/02/15 37pp 22300 327 Fiche 50-445,84/02/15,8402170119 Brown & Root Corp
- 8402210220 Expected findings of fact re welding issues to be raised during 840220-24 hearings Certificate of Svc encl REYNOLDS.N S Texas Utilities Generating Co REYNOLDS.N S Bish Liberman. Cook. Purcell & Reynolds 84/02/16 Sipp 223:6 116 24X Fiche 50-445,84/02/16,8402210220 Bishop,
- 8402210340 Expected findings of fact re independent assessment program to be raised during 840220-24 hearings Certificate of Syc
 - REYNOLDS,N S , HORIN,W A Texas Utilities Generating Co REYNOLDS,N S Bishop, Liberman, Cook, Furcell & Reynolds 46pp 22315 212 24X Fiche 50-445,84/02/16,8402210340 84/02/16
- 8402220347 Expected findings of fact for 840220-24 hearings re welding issues Findings summarize principal arguments & give fair notice of position Certificate of Svc ancl ELLIB.J Citizans Association for Bound Energy 84/02/1 22336 174 24% Fiche 50-445,84/02/16.8402220347. 24x Fiche 50-445,84/02/16 B402220347.
- 8402270063 Proposed findings of fact on weld fabrication Certificate of Svc encl MIZUNO, 9 S Hearing Branch 1 84/02/16, 26pp 22387 039 24X Fiche 50-445,84/02/16,8402270063
- B402270073 Forwards staff corrections to testimony of LD Gilbert & Ro Taylor on plug welding, weavs welding, downhill welding & weld nod control Related correspondence MIZUND.0 S Hearing Branch I B4/02/17 BLOCH.P B , MCCGLLGM,K A , JORDAN.W H Atomic Safety and Licensing Spard Penel 3pp 22387-065 24x Fiche 50-445,84/02/17,8402270073
- ---8402270076 Corrected testimony of LD Gilbert & RG Taylor on plug-welding, weave welding, downhill welding & weld rod control Related correspondence GILBERT, LD, TAYLOR, RG Division of Resident, Reactor Project & Engineering Programs 84/02/17 22pp 22387 068 24X Fiche 50-445,84/02/17,8402270073

- B402230085 Notice of appearance in proceeding Certificate of Svc encl MODLDRIDGE,R A Teras Utilities Generating Co WODLDRIDGE,R A Worsham, Forsythe & Sampels 84/02/20 3pp 22362 126 24X Fiche 30-445,84/02/20,8402230085
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8402230122 Amend 46 to FSAR W/840216 ltr CLEMENTS.B R Texas Utilities Generating Co 84/02/10 DENTON.H R Office of Nuclear Reactor Regulation. Director 561pp 22347 001 24X Fiche 50-445.84/02/10.8400230122
- 8402220443 Forwards description of FSAR Amend 46.6td 840210 MARSHALL,J S Texas Utilities Generating Co 84/02/16 BURWELL,8 B Office of Nuclear Reactor Regulation, Director 7pp 22337 353 24X Fiche 50-445.84/02/16.8402220443
- O Imagection reports, IE Bulletins & correspondence
- 8402220425 Forwards IE Insp Rept 50-445/83-48 on 831217-22 No violations or deviations noted JOHNSON.E H Region 4. Office of Director 84/01/17 GARY, R J Texas Utilities Generating Co 2pp 22340 163 24X Fiche 50-445,84/01/17,8402220425
- --8402220437 IE Insp Rept 50-445/83-48 on 831219-22 No viplations or deviations noted Major areas inspected licensee chemistry/radiochemistry program, including organization, staffing, staff qualifications, training program & controls BLAIR.J, WISE,R, MURRAY.B Region 4, Office of Director 84/01/16 7pp 22340 165 24X Fiche 50-445,84/01/19,8402220425
- 8402100244 Forwards IE Insp Rept 50-445/83-44 on 831001-1130 No violations or daviations noted JOHNSDN,E H Region 4, Office of Director 84/01/23 GARY,R J Texas Utilities Generating Co 2pp 22179 333 24X Fiche 50-445,84/01/23,8402100244
- --8402100248 IE Insp Rept 50~445/83-44 on 831001-1130 No violations or deviations noted Major areas inspected initial startup procedures, plant tours & statuts, preoperational test performance & reevaluation of preoperational test results KELLEY, D. L., HUNNICUTT, D. M. Region 4. Office of Director 84/01/19 6pp 22179, 335 24X Fichs 50~445.84/01/23,8402100244
- 8402160347 Forwards IE Insp Repts 50-445/83-46 & 50-446/83-21 on 831212-15 No violations or deviations identified JHN80N.E H Region 4, Office of Director 84/01/23 GARY.R J Texas Utilities Generating Co ip 22268 351 24X Fiche: 50-445,84/01/23,8402160347
- --8402160336 IE Insp Repts 50-445/83-46 & 50-446/83-21 on 831212-15 No violations or deviations identified Major areas inspected performance & capabilities during exercise of emergoncy plans & procedures
 MONTQOMERY.J L , WISNER, C & Region 4, Office of Director
 HERRINGTON, W N Battelle Memorial Institute, Pacific Northwest
 Laboratory 84/01/19, 9pp 22268 353 24X Fiche 50-445,
- B402010144 Notification of significant licensee meeting on B40202 w/util & Brown & Root in Glen Rose.TX to discuss civil penalty action # Region 4. Office of Director B4/01/24 Region 4. Defice of Director. ip 22038 217 24X Fiche 50-445.84/01/24.8402010144
- 8312120153 IE Info Notice 84-06. "Steam Binding of Auxiliary Feedwater Pumps." Svc list encl JDRDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120153
- 8402070005 Ack receipt of 831121 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-445/83-40 JBHNBON.E H Region 4, Office of Director 84/02/01 GARY,R.J. Texas Utilities Generating Co 1p 22102 324 24X Fiche 80-445,84/02/01,8402070005.
- --8402070008 Responds to NRC 831025 ltr re violations noted in IE Insp Rept 50-445/83-40 Corrective actions records ctr personnel retrained per Station Administration Procedure STA-302 to ensure transmittal properly completed OARY,R J Texas Utilities Generating Co 83/11/21, JOHNSON,E H Region 4, Office of Director Spp 22102,325 24X Fiche 50-445,84/02/01,8402070005
- B402070054 Forwards applicant 840123 ltr.answer protesting civil penalty & response to notice of violation W/o encls MIZUNO.9 8. Hearing Branch 1. 84/02/01. BLUCK.P.B. JORDAN.W.H. MCCOLLOM.K.A. Atomic Safety and Licensing Board Panel 1p 22103.037 24X Fiche 50-445.84/02/01.8402070056.

- 8401190016 IE Info Notice 84-07. "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in IWR Mark 1 Containment Vent Headers " Svc list enc! DEYCUNG,R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177
- B4022B0514 Forwards IE Emergency Preparedness Appraisal Repts 50-445/B3-33 & 30-445/B3-17 on B3092b-1007 Discussion of significant preparedness deficiencies in emergency preparedness program also encl JDRNSON.E H Region 4. Office of Director B4/02/08 GARY.R J Texas Utilities Generating Co. 18pp. 22407 223 24X Fichs 50-445.84/02/08.84022B0514
- --B4022B0536 IE Emergency Preparedness Appraisal Repts 50-445/83-33 & 50-446/83-17 on B30926-1007 Major areas inspected emergency organization, training, emergency facilities & equipment, procedures & coordination w/offsite groups & drills MONTGOMERY, J. L., ROHRER, D. M., WISNER, C. E. Region 4, Office of Director B4/02/06 72pp 22407 241 24X Fiche 50-445, B4/02/08, B4022B0514
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (1000850, App R)" Suc list enc!

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc. 124pp 22365 259 24X Fiche 50-000.84/02/13.8401190041
- 840119050 Board Notification 84-021 provides repts of Transamerica Delaval, Inc. insps. conducted from Mar 1979 to Oct. 1983 EISENHUT, D.O. Division of Licensing 84/02/13 PALLADINO Commissioners Spp. 22314 001 24% Fiche 50-000,84/02/13, B401190050
- B401190039 IE Info Notice B4-08, "IOCFRSO 7, 'Employee Protection '"
 Syc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22348 141 24X Fiche 50-000,84/02/14,8401190039
- 8401190045 IE Info Notice 83-63. Suppl i, "Potential Failures of Mestinghouse Type 8A-1 Differential Relays" Svc list encl JORDAN, E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc i18pp 22364 142 24X Fiche 50-000, 84/02/15, 8401190045
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/02/21 Consolidated Edison Co of New York, Inc 114pp 22344 024 24X Fiche 50-000.84/02/21,8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies "
 Svc list encl
 JORDAN,E L. Division of Fmargency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000.84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/27, Consolidated Edison Co of New York, Inc 120pp 22431 060 24X Fiche 50-000,84/02/27,8401190067
- S Reportable occurrences. LERs & related correspondence
- 8402070393 Requests that NRC investigate design reliability of emergency diesel generators supplied by Transamerica Delaval. Inc Engine problems have been experienced since delivery of first vessel in May 1981 Related info encl MOLINA, J C Falcon Carriers, Inc 84/02/01 DENTON, H R Office of Nuclear Reactor Regulation. Director 63pp 22096 057 24X Fiche 30-000,84/02/01.8402070393
- B4021702B2 Interim deficiency rept re laminations & delaminations in cable tray support column in cable spread room Initially reported on B40111 Evaluation continuing Next rept expected by B40309 GARY, R. J. Texas Utilities Generating Co B4/02/07 JDHNBON, E H Region 4, Office of Director 1p 22277 162 24X Fiche 50-445,84/02/07,8402170282

- 8402220420 Deficiency Rept SDAR-126 re defective diesel generator engine push rods Defective push rods will be removed to acrapped to replacements requisitioned to installed before operation GARY, R. J. Teras Utilities Generating Co. 84/02/08 JDHNSON, E. Region 4. Office of Director 2pp. 22340 172 24X Fiche 50-445,84/02/08.8402220420 84/02/08 JOHNSON, E H 172 24X
- 8401190048 Board Notification 84-005 provides info re alleged falsification of QC documents concerning const of safety-related HVAC units by Dahnson Co. Winston-Salem. NC EISENHUT. D Q Division of Lizensing 84/02/09 PALLADIND Commissioners 7pp 22332 187 24% Fiche 50-000.84/02/09, 8401190048
- 8401190033 Board Notification 84-020 forwards info re Transamerica Belaval Inc emergency diesel generator problems Attendance list.moeting handouts & slides encl EISENHUT.D & pivision of Licensing 84/02/13 PALLADINO Commissioners 102pp 22332 202 24X Fiche 50-000,84/02/13, 8401190093
- 8402220033 Final deficiency rept re staimless steel tubing observed cracked Investigation complete Matter not reportable under 10CFR50 55(e)

 9ARY,R J Teras Utilities Generating Co 84/02/13 JDHN80N,E H Region 4. Diffice of Director 12. 22338 255 24X

 Fiche 50-445,84/02/13,8402220033
- 8402220171 Final deficiency rept re section modulus used in de pipe supports using tube steel Initially reported on 840118 Condition determined not reportable per 10CFR50-55(e) CARY.R.J Texas Utilities Generating Co 84/02/13 JDHNS0 Region 4. Defice of Director 1p 22340-137 24X Fiche 50-445.84/02/13.8402220171 design of JOHNBON, E. H.
- 402220545 Deficiency rept re failed inverters in NSSS Caused by grounded secondary winding of inverter ferroresonant output transformers Transformers will be returned to manufacturer for repair GARY,R J Towns Utilities Generating Co 84/02/13 JDHNSON.E H Region 4. Defice of Director 2pp 22331 132 24X Fiche 50-445.84/02/13.8402220545
- £ 102220530 Part 21 rept re defective DSR & DSRV standby diexel generator turbocharger thrust bearing lubrication Deficiency not corrected by sys mof New recommendation will be sent to customers by 840330 nOYER.R E Transamerica Delaval. Inc 84/02/15 Director Office. Office of Inspection and Enforcement 5pp 22532 18 Fiche 50-000.84/02/15.8402220530 500 22332 182 24X
- 102280268 Deficiency rept re error in tolerances used in calibr of adhesion tester Initially reported on 840116. Condition not reportable under 10CFR50 55(e) Evaluation continuing & completion anticipated by 840515
 GARY.R J Tayas Utilities Generating Co 84/02/15 JOHNSON, E. H Region 4. Office of Director ip 22399 071 24X
 Fiche 50-445.84/02/15.8402280268
- 402280493 Deficiency Rept SDAR-131 re lugs found w/bad crimps
 Initially reported on B40124 Evaluation continuing &
 completion anticipated by B40330.
 GARY.R J Texas Utilities Generating Co 84/02/20 JOHNSON, E J
 Region 4, Office of Director 1p 22407 074 24X
 Fiche 50-445,84/02/20,8402280493
- 102280701 Notification of 840308 meeting w/Transamerica Delaval.Inc (TDI) Duners Group in Wafing River.NY to discuss TDI proposed program plan to qualify dissel generators. CARUSO.R Division of Licensing 84/02/23 BERLINGER.C. Division of Licensing 2pp 22414 340 RAX Fiche. 50-000, 84/02/23, 8402280701

Hearing transcripts on non-antitrust matters

- 02100066 Forwards prefiled testimony of J Doyle, W Walsh, H Stiner & D Stiner re CYGNA rept & associated welding matters, per ABLB 631228 memorandum & order, for 840220-24 hearings. Certificate
- G31228 memorandum & order, for E40220-24 mearings. Cervs. Carder of Svc encl
 LLIS.J Citizens Association for Sound Energy 84/02/07.
 LOCH.P B , JORDAN, W H , MCCOLLOM, K A Atomic Safety and Licensing oard Panel 3pp 22:78:300 24% Fiche S0-445,84/02/07.8402100066
- 402100072 Testimony of J Doyle re CYGNA rept on pipes & pipe supports DOYLE, J. Citizens Association for Sound Energy 84/02/07. 16pp 22178 303 24X Fiche, 50-445, 84/02/07, 8402100066
- 3402100079 Testimony of MA Walsh on CYONA executive summery HALSH,M A Citizens Association for Sound Energy 84/02 24pp 22178 319 24X Fiche 50-445,84/02/07,8402100046

- ---B402100085 Testimony of D Stiner & H Stiner re open welding issues STINER.D . STINER.H Citizens Association for Sound Energy 84/02/07 47pp 22178 343 24X Fiche 50-445,84/02/07.840210066
- 8402100184 Forwards rebuttal testimony of applicant panel re welding & ASME & AMS Code provisions Encls will be introduced at hearings commencing on 840220 REYNOLDS, N S Bishop, Liberman, Cook, Purcell & Reynolds. REYNOLDS, N S Texas Utilities Generating Co 84/02/08 BLOCH,P S, JORDAN,W H, MCCGLLOM,K A Atomic Safety and Licensing Board Panel 4pp 22181 341 24X Fiche 50-445,84/02/08,8402100184
- --B402100190 Rebuttal testimony of WE Baker, CT Brandt, MD Muscente, FE Coleman, CR Brown, JD Green, JE Hallford, I Pickett, AM Braumuller & S Fernander on Stiner allegations re weave welding & welding of misdrilled holes
 BAKER, W. E. BRANDT, C. T. MUSCENTE, M. D. Texas Utilities Generating
 Co. 84/02/08 56pp 22181 345 24X Fiche 50-445, 84/02/08. 8402100184
- --B402100193 Rebuttal testimony of WE Baker.MD Muscente & MN Bressler ;; allegations involving AWS & ASME Code provisions BAKER.W E . MUSCENTE.M D . BRESSLER.M N Texas Utilities Generating Co 84/02/08 32pp 22182 039 24X Fiche 50-445,84/02/08.8402100184
- 8402140002 Testimony of LD Gilbert & RD Taylor on plug welding, weave welding, downhill welding & weld rod control re const quality Certificate of Svc encl GILBERT, L D , TAYLOR, R Q Division of Resident, Reactor Project & Engineering Programs 84/02/08 25pp 22217 119 24X Fiche 50-445,84/02/08,8402140002
- 8402140354 Transcript of 840210 telephone conference in Bethesda.MD Pp 9, 257-9, 278 * Atomic Safety and Licensing Board Panel 84/02/10 41pp 22219 349 24X Fiche 50-445, 84/02/10, 8402140354
- 8402190208 Motion to late file testimony of new witness Hatley testimony contains substantive & pertinent matl necessary to complete record Certificate of Svc encl ELLIS-J Cittzens Association for Sound Energy 84/02/10 Safety and Licensing Board Panel 4pp 22244 084 24X Atomic Safety and Licensing Board Panel Fishe 50-445, 84/02/10, 8402150208
- --8402150215 Testimony of D Hatley re documentation control at Pacilities

 * Atomic Safety and Licensing Board Panel 84/
 22244 088 24X Fiche 50-445,84/02/10,8402150208 B4/02/07 16pp
- 8402170119 Informs that MN Bressler will be replaced by RE Lorentz & OCTION INFORMS that AN Bressier will be replaced by ML Lorenti & JD Stovenson in testimony re allegations on AMS & ASME Code provisions Rebuttal testimony encl REYNOLDS.N S Dishop, Liberman, Cook, Purcell & Reynolds REYNOLDS.N S Texas Utilities Generating Co 84/02/15. BLOCH.P B. JORDAN.W H , MCCOLLOM.K A Atomit Safety and Licensing Board Panel 2pp 22300 325 24X Fiche 50-445,84/02/15,8402170119.
- --8402170126 Rebuttal testimony of WE Baker, MD Muscente, JD Stavenson k RE Lorent; re allegations involving AWS & ASME Code provisions. BAKER, W E . MUSCENTE, M D , STEVENSON, J D Brown & Root Corp (subs of Halliburton Corp) 84/02/15 37pp 22300 327 24X Fiche 50-445, 84/02/15, 8402170119
- 8402170183 Transcript of 840215 telephone conference in Washington &C Pp 9.279-9,336
 * Atomic Safety and Licensing Board Panel 84/02/15 40pp
 22299 102 24X Fiche 50-445,84/02/15,8402170183
- 8402270073 Forwards staff corrections to testimony of LD Gilbert & RG Taylor on plug welding, weave welding, downhill welding & weld rod control Related correspondence MIZUND, 9 S Hearing Branch i B4/02/17 BLOCH, PB, MCCDLLOM, KA, JORDAN, WH Atomic Safety and Licensing Board Panel 3pp. 28087 045 24X Fishe 50-445, 84/02/17, 8402270073
- --B402270076 Corrected testimony of LD Gilbert & RO Taylor on plug welding, weave welding, downhill welding & weld rad control.
 Related correspondence
 GILBERT, L. D., TAYLOR, R. Q. Division of Resident, Reactor Project & Engineering Programs 84/02/17 22pp 22387.068 24X
 Fiche 50-443,84/02/17,8402270073
- 8402240103 Transcript of 840220 hearing in Fort Worth.TX Pp 9.337-7.601 * Commissioners 84/02/20 337pp 22372 001 24x Fiche 50-445.84/02/20.8402240103

- 8402270409 Transcript of 840221 hearing in Fort Worth, TX Pp 9,402-9,844 Supporting documentation and * Commissioners 84/02/21 263pp Fiche 50-445,84/02/21,8402270409 22388 208 244
- 8402280341 Transcript of 840222 hearing in Fort Worth, TX Pp 9:845-9:911
 - + Commissioners 84/02/22 55pp 22403 077 24X Fiche 50-445,84/02/22,8402280341
- 8402290329 Transcript of 840223 hearing in Fort Worth, TX Pp 9,912-10,327 Supporting documentation encl * Commissioners 84/02/23 419pp * Commissioners 84/02/23 41 Fiche 50-445,84/02/23,8402290329 22423 173 24V
- 8402280561 Transcript of 840224 hearing in Fort Worth, TX Pp 10,328-
 - 349 Commissioners 84/02/24 47pp 22406 181 24x Fiche: 50-445, 84/02/24, 8402280561

U Congressional/Executive Correspondence

- 8402240277 Responds to FOIA request for three categories of documents re facilities Forwards App A Documents 1-4 Documents 5-9 provided previously via svc list FELTON. J M Division of Rules and Records 84/01/27 BUGARMAN, R J Sugarman & Denworth 2pp 22394 298 24X Fichs 50-000,84/01/27,8402240277
- --8308090022 Forwards second quarterly status rept for 1983 on actions taken re operating reactors & licensing reviews of new facilities
 ABSELSTINE. J K Commissioners 83/07/21 BEVILL, T House of Rep , Appropriations 11pp 22394 300 24% Fiche 50-000, 84/01/27,8402240277

V Operator Examinations

8402160612 Advises that Rev 3 to Training Procedure TRA-204, "Licensed Operator Requalification Training Program," acceptable YOUNGBLOOD, B J. Licensing Branch 1 84/02/03 GARY,R J. Texas Utilities Generating Co. 2pp. 22302 027 24% Fiche 50-445, 84/02/03,8402160612

DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA . UNIT 2

- A Application/construction stage documents & correspondence
- 8402090003 Responds to FOIA request for const completion dates for muclear plants currently under const & analyses containing estimates based on inclusion of Gaseload Forecast Panel meetings Forwards App A.9 & C documents
 FELTON.J M Division of Rules and Records 83/10/31
 ROSENBAUM.D M Technical Analysis Corp. 19pp 22193 292 24x
 Fiche 50-000.83/10/31,8402090003
- --- B402070124 Handwritten notes & calculations re facility const Related info encl * NRC - I # NRC - No Detailed Affiliation Given 83/10/31 \$22194 200 24% Fiche 50-000,83/10/31,8402090003
- --8402070133 Trip rept of 780418-19 site visit re in-progress const activity observation, const & startup schedules & estimated fuel load date FUEL load oate NAVENTI,R Light Water Reactors Branch 4 78/0 Water Reactors Branch 4 2pp 22194 248 24X Fiche 50-000,83/10/31,8402090003 78/06/09
- --8402090138 Handwritten notes & calculations re const activities Related - No Detailed Affiliation Given BO/10/21 22174: 255 24X Fiche: 50-000,83/10/31,8402090003
- --9402070140 Handwritten notes & calculations re const activities * NRC No Detailed Affiliation Given 83/10/31 3pp 22174 281 24% Fichs 50-000,83/10/31,8402070003.
- 840207008B Forwards util 831220 memo to all personnel defining policy re intimidation, harassment or threats to or from employees Disciplinary action will include termination OARY,R. J. Texas Utilities Generating Co. 83/12/21 COLLINS, J.T. Region 4. Office of Director 2pp 22103 039 24X Fiche: 50-445,83/12/21,8402070088.

- 8402030540 Informs that proposed post-accident sampling sys design meets criteria specified in TMI Action Plan Item II B 3 & is acceptable Evaluation will be incorporated into next SER SUPPLIFY THE SUPPL
- 8401190012 Board Notification 84-013 forwards info re Transamerica Delaval, Inc emergency diesel generators EISENHUT, D G Division of Licensing 84/01/24 PALLADING, N Commissioners 10pp 22054 346 24% Fiche 50-000, 84/01/24, 8401170012
- 8401190015 Board Notification 84-018 provides info re failure experience of Transamerica Delaval emergency diesel generators in manine svc EISENHUT, D 0 Division of Licensing 84/01/27 PALLADIND, N J Commissioners 385pp 22093 027 24X Fiche 50-000,84/01/27,8401190015
- 8402010410 Operate Ltr 84-04 to all operating PMR licensess CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Svc list encl ETBENNUT.D 0 Division of Licensing 84/02/01 Consulidated Edison Co of New York, Inc 59pp 22177 087 24X Fiche 50-000.84/02/01.8402010410
- 8402170061 Notification of 840210 meeting w/Transamerica Delaval, Inc (TDI) in Bothesda.MD to discuss program plan proposed by TDI Owners Group to qualify diesel generators CARUSO,R Division of Licensing 84/02/06 BERLINGER,C Division of Licensing 2pp 22312 339 24% Fiche 50-000,84/02/06, 8402170061
- 8402130156 Responds to NRC 831216 itr requesting util to perform major study of all safety-related mechanical equipment located in areas of potentially harsh environs Request unwarranted & technically unjustified Meeting w/NRC requested OARY.R J Texas Utilities Generating Co 84/02/07 Y0UNGSLOOD, B J Licensing Branch i 3pp 22204 101 24X Fiche 30-445,84/02/07.8402130154
- B401190059 Board Notification 84-032 provides add1 info on environ qualification Submittal augments info in Board Notifications 84-004 & 84-007 EISENHUT. D 9 Division of Licensing 84/02/13 Atomic Safety and Licensing Board Panel 10pp 22314 204 24X Fiche 50-000.84/02/13. Licensing Board Panel 8401170057
- 840117006B Board Notification 84-033 provides "Sys Interaction Program," task action plan for Unresolved Safety Issue A-17 Distribution list encl visersousion list encl EISERHUT,D 0 Division of Licensing 84/02/16 PALLADIND Commissioners Bpp 22482 091 24X Fichs 50-000.84/02/16. 84011900AB
- 8402230009 Notifies that Westinghouse developed NOTRUMP small break LOCA analysis code to address TMI Action Plan Item II K 3 30 & Generic Ltr B3-35 NOTRUMP SER to be released in Feb 1984 SCHMIDT.H C Texas Utilities Generating Co 84/02/17 EISENHUT,D Q Division of Licensing 1p 22361 278 24X Fiche 50-445,84/02/17,8402230009
- 8402230061 Responds to Generic Ltr B3-10C re plan for resolution of TMI Action Plan Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps" Response will not be available on B40227 due to delay in Westinghouse Owners Group Study SCHMIDT, H C Texas Utilities Generating Co B4/02/17 YOUNGB1000, B 1 Licensing Branch 1 1p 22362 129 24% Fiche 50-445,84/02/17,8402230061
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- 8402020020 Forwards SSER on TMI Action Item I 0 1 re special low power tast program submitted by MC Schmidt B30707 Itr Program acceptable SER Confirmatory Issue 11 resolved YOUNOBLOOD, B.J. Licensing Branch 1 84/01/23 GARY, R.J. Texas Utilities Generating Co. 3pp. 22062 316 24X Fiche 50-445, 84/01/23, 8402020020
- 8402030540 Informs that proposed post-accident sampling sys design meets criteria specified in TMI Action Flan Item II,B 3 & is acceptable Evaluation will be incorporated into mext SER

- 8402060266 Forwards SSER re SER Outstanding Issue 1 re protection effects associated w/postulated rupture of piping outside containment Issue resolved YOUNOSLOOP, B. J. Licensing Branch 1 84/01/24 GARY, R. J. Texas Utilities Generating Co. 2pp. 22103 175 24% Fiche 50-445, 84/01/24, 84/0206266
- ~~8402060272 SBER re SER Outstanding Issue 1 on protection against effects associated w/postulated rupture of piping outside containment Issue resolved 4 Aurillary Systems Branch 84/01/24 7pp 22103 177 24X Fiche 50-445,84/01/24,8402060266
- 8402060568 Forwards list of unresolved SER issues requiring resolution prior to Unit 1 liconsing List also identifies Tech Specs which need to be settled as well as new issues raised by NRC Response due 60 days before licensing YOUNGILOOD, B. J. Licensing Branch 1 84/01/24 GARY, R. J. Texas Utilities Generating Co. 10pp 22092 115 24X Fiche 50-445,84/01/24,8402060568
- 8402240149 Forwards schedule for response to SER unresolved issues identified in NRC 840124 ltr SCHMIDT.H C Teras Utilities Generating Co 84/02/16 YQUNGSLOOD, B J Licensing Branch 1 3pp 22374 332 24X Fiche 50-445,84/02/16
- F Security, medical, emergency & fire protection plans
- B402160203 Advises that emergency preparedness field exercise postponed from B31005 to B31214.dug to rescheduling of emergency preparedness planning activities CLEMENTS.B R Texes Utilities Generating Co 193/09/19. CULINS.J T Region 4. Office of Director 1p 22276 260 24X ithe 50-445.83/09/19.8402160203
 - 12160347 Forwards IE Insp Repts 50-445/B3-46 & 50-446/B3-21 on 131212-15 No violations or deviations identified DINBON,E H Region 4, Office of Director B4/01/23 GARY,R J Fexas Utilities Generating Co ip 2226B 331 24X Fiche 50-445,84/01/23,8402140347
- --8402160356 IE Insp Repts 50-445/83-46 & 50-446/83-21 on 831212-15 No violations or deviations identified. Major areas inspected performance & capabilities during exercise of emergency plans & procedures MONTGOMERY, J.L. Region 4, Office of Director SCHULTZ, D.H. Comex Corp STOETZEL, Q.A. Dattelle Memorial Institute, Pacific Northwest Laboratory, 84/01/19 9pp 22268 353 24X Fiche 50-445,84/01/23,8402160347
- 102060697 Approves request for 19 deviations from 10CFR50, App R re-fire protection for safe shutdown sys SSER encl YOUNDBLOOD, B J. Licensing Branch 1 84/01/24 9ARY, R J Texas Utilities Generating Co 3pp 22092 003 24X Fiche 50-445, 84/01/24,8402060637
- 402280514 Forwards IE Emergency Preparadness Appraisal Repts 50-445/83-03 & 30-446/83-17 on 830926-1007 Discussion of significant preparedness deficiencies in emergency preparedness program also encl UCHNBON.E H Region 4. Office of Director 84/02/08 GARY.R J Teras Utilities Generating Co 18pp 22407:223 24X Fiche: 50-445,84/02/08,8402280514
- -B402280536 IE Emergency Preparedness Appraisal Repts 50-445/83-33 & 50-446/83-17 on B30926-1007 Major areas inspected emergency organization, training, emergency facilities & equipment, procedures & coordination w/offsite groups & drills MONTOCHERY, J L : FAIROBENT, J E : BAIRD, J B Region 4, Office of Director B4/02/06 72gp 22407 241 24X Fiche 50-445,84/02/08,8402280514

) Adjudicatory correspondence

I402010230 Response opposing Citizens Assec for Sound Energy 840103 motion for reconsideration of ABLB 831228 scheduling orders Mation unsubstantiated Centificate of Bvc encl MIZUND, 0 S Hearing Branch 1 84/01/26 Atomic Safety and Licensing Board Panel lipp. 22040 225 24X Fiche 50-445,84/01/26,84/2010230

- 8402010231 Response to applicant 840117 motion for reconsideration of ASLB 831226 memorandum & order re GA for design Record insufficient Reconsideration of Malsh/Doyle concerns opposed Centificate of Svc enc!
 MIZUNO, GS Hearing Branch | 84/01/27 Atomic Safety and Licensing Board Panel | 10pp | 22040 177 | 24X Fichs 80-445, 84/01/27. 8402010231
- 8402010209 Reply to Citizens Assoc for Sound Energy 831223 response to applicant certification of issues No further ASLB action required Certificate of Svc encl REYNOLDS.N S. HORIN.W A. Texas Utilities Generating Co. REYNOLDS.N S. Bishop, Liberman, Cook, Purcell & Reynolds. 84/01/30 About 88/64y and Licensing Board Panel. 40pp. 22040-236-24X. Ficha 50-445,84/01/30,8402010209
- 840206013B Reply opposing Citizens Assoc for Sound Energy 831223
 response to applicant identification of issues Certificate
 of Svc encl
 REYNOLDS.N S. HORIN.W A. Toxas Utilities Generating Co.
 - or SVE enc. REYNOLDS,N S , HORIN.W A Texas Utilities Generating Co. REYNOLDS,N S Bishop, Liberman, Cook, Purcell & Reynolds B4/01/30 40pp 22087 062 24X Fishe 50-445,84/01/30,8402060138
- 8402010210 Memorandum requesting util & NRC to file info re ability of QA program to detect design/const problems in Delaval generators, frequency of problems w/generators & assurance of public safety Sua sponte review inappropriate
 BLDCH,F II Atomic Safety and Licensing Board Panel 84/01/31 2pp 22041 337 24X Fiche 30~445,84/01/31,8402010210
- B402020221 Order continuing obligation to update interrogatories by 840227 DLDCH.P B Atomic Safety and Licensing Board Panel 84/01/31 1p 22057 083 24% Fiche 50-445,84/01/31,8402020221
- 8402030160 Answer opposing Citizens Assoc for Bound Energy (CABE) motion for reconsideration of ABLB 831228 momorandum & order re design GA CASE claims invalid; inappropriate & unfounded REVNOLDS; N 5, HORIN, W A Texas Utilities Generating Co REYNOLDS; N 8 Bishop, Liberman, Cook, Purcell & Reynolds. 84/02/01 Atomic Safety and Licensing Board Panel App 22049 107 24X Fiche 50-443, 844/02/01.8402030160
- --8402030165 Affidavit of DH Wade re involvement of D Ferg in independent design review & procedures applicable to communications Certificate of Svc encl HADE, DH Texas Utilities Generating Co 84/02/01 4pp. 22068 113 24X Fiche 50-445,84/02/01,8402030160
- B402040150 Answer opposing applicants & NRC 840117 motions for reconsideration of ASLB 831228 memorandum & order re 0A for design ELLIB,J Citixens Association for Bound Energy 84/02/01. Atom Bafety and Licensing Board Panel 27pp 22089 191 24X Fiche 30-445.84/02/01.8402040150
- --B402060153 Forwards executed affidavits of J Doyle & M Walsh in support of Citizens Assoc for Sound Energy answer to applicant & NRC motions for reconsideration of ABLB memorandum & order re
- or Citizens Assoc for Sound Energy alswer to applicant & Nicomotions for reconsideration of ABLB memorandum & order re AA for design ELLIS.J Citizens Association for Sound Energy B4/02/01, Docketing & Services Branch 3pp. 22089 218. 24X Fiche 50-445, 84/02/01, 8402060150
- --8402040158 Affidavit of J Doyle re applicant 840117 motion for reconsideration of memorandum & order on GA for design. POYLE. J Citirens Association for Sound Energy 84/01/28 15pp 22087 221 24% Fiche 50-445.84/02/01.8402060150
- --B402060161 Affidavit of MA Walsh re applicant GA program discussed in applicant motion for reconsideration of memorandum & order Certificate of Svc encl WALSH,M A Citizens Association for Bound Energy. 84/01/30 21pp 82089 236 24% Fiche 50-445,84/02/01,8402060150.
- 8402070056 Forwards applicant 840123 ltr.answer protesting civil penalty & response to notice of violation H/o encls MIZUND.6 S Hearing Branch 1 84/02/01. BLOCH.P.B., JORDAN.H.B., MCCOLLOM,K A Atomic Bafety and Licensing Board Panel 1p 22103 037 24% Fiche 50-445.84/02/01.8402070056
- B402070171 Sixteenth set of interrogatories & requests to produce listed documents re CYGNA rept Certificate of Svc encl. ELLIG.J Citizens Association for Bound Energy. B4/02/02 Test Utilities Generating Co., Spp. 22102.228 24X Fiche 50-443, B4/02/02.8402070171

- B402140170 Response partially supporting Citizens Assoc for Sound Energy 831223 response to util identification of issues & 840116 motion for clarification of issues Certificate of Svc encl.
 - encl.

 MIZUNO, G S Hearing Branch i 84/02/02 Atomic Safety and
 Licensing Board Panel 33pp 22230 172 24X Fiche 50-445.84/02/02.

 84022140170
- 8402070227 Util plan to respond to ASLB 831228 memorandum & order re GA for design Independent design review will be conducted by Cygna Energy Sycs.per ASLB recommendations Certificate of
 - SVC encl REYNOLDS,N B Texas Utilities Generating Co REYNOLDS,N S Bishop, Liberman, Cook, Purcell & Reynolds 84/02/03 12pp 22101 152 24X Fiche 50-445,84/02/03,8402070227
- 8402090161 Order denying 840113 motion for reconsideration of 831228 & 840103 scheduling orders re site-visit discovery & motion to reopen record re firing of R Hamilton BLOCH, P B . JORDAN, W H . MCCOLLON, K A Atomic Safety and Licensing Board Panel 84/02/06 Citizens Association for Sound Energy 10pp. 22163 127 24X Fiche 50-445,84/02/06,8402090161
- B40214016B Response to Citizens Assoc for Sound Energy B40117 motion for reconsideration of ASLB B3122B memorandum & order re GA for Besign Motion supported in part & opposed in part Certificate of Svc encl NIZUNO, G B Hearing Branch 1 84/02/06 Atomic Gafety and Licensing Board Panel 12pp 22230 160 24X Fiche 50-445,84/02/06,840214016B
- 8402100066 Forwards prefiled testimony of J Doyle.W Walsh, H Stiner & D Btiner re CYONA rept & associated welding matters, per ASLB 831228 memorandum & order, for 840220-24 hearings Certificate of Svc encl
 ELLIB.J Citizens Association for Sound Energy 84/02/07
 BLOCH.P B Atomic Safety and Licensing Board Panel 3pp 22178 300 24% Fiche 50-445.84/02/07.8402100066
- B402090121 Memorandum & order responding to motion for reconsideration of Decision LBF 83-81 re QA for design Footnote 37 will be struct BLOCH.P D , JORDAN.W H , MCCDLLOM.K A Atomic Safety and Licensing Board Panel B4/02/08 Texas Utilities Generating Co 38pp 22163 276 24X Fichs 50-445,84/02/08,8402090121
- 8402100iii Forwards proposed subpoena to compel appearance of DD Hatley for deposition on 840215 re const & CYONA evaluation Notice of deposition encl
 HARTMAN, S L Bishop, Liberman, Cook, Purcell & Reynolds 84/02/08
 BLOCH, P B Atomic 84fety and Licensing Board Panel 2pp
 22182 173 24X Fiche 50-445,84/02/08,8402100111
- --8402100113 Subpoena directing DD Hatley to appear on 840215 in Fort Worth.TX for deposition Certificate of Svc encl BLOCH,P B Atomic Safety and Licensing Board Panel 84/02/08 HATLEY.D D Affiliation Not Assigned 5pp 22182 175 24X Fiche 50-445,84/02/08.8402100111
- --8402100115 Notice of DD Hatley 840215 deposition in Fort Worth,TX recanst & CYONA evaluation Certificate of 8vc encl
 HARTMAN, 8 L Texas Utilities Generating Co HARTMAN, 8 L Bishop,
 Liberman, Cook, Furcell & Reynolds 84/02/08 4pp 22182 200
 24X Fiche 50-445,84/02/08,8402100111
- 8402100184 Forwards rebuttal testimony of applicant panel re welding & ABME & AWB Code provisions Encls will be introduced at hearings commencing on 840220 REYNOLDS:N 8 Bishop, Liberman, Codk, Purcell & Reynolds 84/02/08 BLOCH.P 8 Atomic Safety and Licensing Board Panel 4pp 22181 341. 24X Fiche 50-445,84/02/08,8402100184
- B402140065 Notice of appearance in proceeding Certificate of 8vc encl HICKB.R Texas, State of 84/02/09 3pp 22217 i85 24X Fishe 50-445,84/02/09,8402140065
- E402130273 Forwards return on svc of subpoens served on DA Hatley in proceeding Related correspondence HARTMAN, B L Bishop, Liberman, Cook, Purcell & Reynolds 84/02/10 Office of the Secretary of the Commission 2pp 22203 361 24X Fiche. 50~445,84/02/10,8402130293
- 8402140176 Memorandum requesting util comments on whether T Brandt erroneously interpreted H Stiner testimony re location of allegedly improper weave welds 8100H.P B Atomic Safety and Licensing Board Panel 84/02/10 lp 22230-208. 24X Fiche 30-445,84/02/10,8402140176

- 8402150097 Partial answer to applicant 840203 plan to respond to momorandum & order re GA for design Applicant proposal totally inadequate & nonresponsive to ASLB concerns ELLIS.J Citizens Association for Sound Energy 84/02/10 Atomic Safety and Licensing Board Panel 11pp 22249 250 24% Fiche 50-448,84/02/10.8402150097
- 8402150144 Motion for extension of time to 840305 to answer applicant 840203 plan to respond to memorandum & order re GA for design Certificate of Svc encl ELLIS. J Citizens Association for Sound Energy 84/02/10 Atomic Safety and Licensing Board Panel App 22247 271 24% Fiche 50-445,84/02/10,8402130144
- 8402190208 Motion to late file testimony of new witness Hatley testimony contains substantive & pertinent matl necessary to complete record Certificate of Svc encl ELLIS. J Citizens Association for Sound Energy 84/02/10 Atomic Safety and Licensing Board Panel App 22244 084 24X Fiche 50~445,84/02/10,8402150208
- 8402220187 Forwards listed correspondence on admitted issues per B40112 telcon w/parties W/o enrls Related correspondence M1ZUNO.6 S Hearing Branch 1 84/02/13 BLOCH.P B. JURDON.W H. MCCOLLOM.K A Atomic Safety and Licensing Board Panel 2pp 22340 232 24X Fiche 50-445.84/02/13.8402220187
- 8402170119 Informs that MN Bressler will be replaced by RE Lorentz & JD Stevenson in testimony re allegations on AMS & ASME Code provisions Rebuttal testimony encl REYNOLDB,N S Bishop, Liberman, Cook, Purcell & Reynolds REYNOLDB,N S Texas Utilities Generating Co 84/02/15 BLOCH,P B , JDRDAN,W H , MCCOLLOM,K A Atomic Safety and Licensing Board Panel 2pp 22300 325 24X Fiche 50-445.84/02/15.8402170119
- 8402210220 Expected findings of fact re welding issues to be raised during 840220-24 hearings Certificate of Svc encl REYNOLDS:N S Texas Utilities Generating Co REYNOLDS:N S Bishop. Liberman: Cook, Purcell & Reynolds 84/02/16 31pp 22316 116 24X Fiche 50-445.84/02/16.8402210220
- 8402210340 Expected findings of fact re independent assessment program to be raised during 840220-24 hearings Certificate of Svc enc!

 REYNOLDB, N 8 . HGRIN.W A Texas Utilities Generating Co REYNOLDB, N 9 Hishop, Liberman, Cook, Purcell & Reynolds 84/02/16 46pp 22315 212 24x Fiche 80-445.84/02/16.8402210340
- B402220347 Expected findings of fact for B40220-24 hearings re welding issues Findings summarize principal arguments & give fair notice of position Certificate of Svc encl
 ELLIB, J Citizens Association for Sound Energy B4/02/16 27pp
 22336 174 24X Fiche 50-445, 84/02/16, B402220347
- B402270063 Proposed findings of fact on weld fabrication Certificate of Svc encl MIZUNO, 0 S Hearing Branch 1 84/02/16 26pp 22387 037 24X Fiche 50-445, 84/02/16, 8402270063
- 8402270073 Forwards staff corrections to testimony of LD Gilbert & RG Taylor on plug welding, weave welding, downhill welding & wild rod control Related correspondence MIZUNO, Q.S. Hearing Branch 1 84/02/17 BLDCH, P.B., MCCDLLOM, K.A., JDRDAN, W.H. Atomic Safety and Licensing Board Panel 3pp 22387*045 24X Fiche 30~445,84/02/17.8402270073
- 8402230085 Notice of appearance in proceeding Certificate of Svc encl WOOLDRIDGE.R A Texas Utilities Generating Co. WOOLDRIDGE.R A Worsham. Foreythe & Sampels 84/02/20. 3pp 22362 126 24X Fichs.50-445,84/02/20.8802230085
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 8402230122 Amend 46 to FBAR W/840216 ltr. CLEMENTS.B R Texas Utilities Generating Co 84/02/10 DENTON.H DFfice of Nuclear Reactor Regulation. Director 56ipp 22347 001 24% Fichs 50-445,84/02/10.8402230122
- 8402220443 Forwards description of FBAR Amend 46, dtd 840210 MARSHALL.J S Texas Utilities Generating Co 84/02/16 BURWELL,S B Defice of Nuclear Reactor Regulation. Director 7pp 22339:353 24X Fiche 30-445.84/02/16.8402220443
- @ Inspection reports, IE Bulletins & correspondence
- 8402160347 Forwards IE Insp Repts 50-445/83-46 & 50-446/83-21 on 831212-15 No violations or deviations identified JOHNBON, E H Ragion 4, Office of Director 84/01/23 GARY, R J Texas Utilities Generating Co 1p 22268 351 24X Fichs 50-445,84/01/23,8402160347

- --8402160356 IE Insp Repts 50-443/83-46 & 50-446/83-21 on 831212-15 No violations or deviations identified Major areas inspected performance & capabilities during exercise of emergency plans & procedures MONTGOMERY, J. L. WISNER, C. E. Region 4. Office of Director HERRINGTON, M. N. Battelle Memorial Institute, Pacific Northwest Laboratory 84/01/19 9pp 22268 353 24X Fiche 30-445, 84/01/23.8402160347
- B402010144 Notification of significant licenses meeting on B40202 w/util & Brown & Root in Glen Rose.TX to discuss civil penalty action * Region 4. Diffice of Director 84/01/24 Region 4. Office of Director 1p 22038 217 24X Fiche 50-445.84/01/24.8402010144
- 8312120153 IE Info Notice 84-05, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000.84/01/25,8312120153
- 8402070056 Forwards applicant 840123 ltr.answer protesting civil penalty % response to notice of violation W/o encls HIZUND:65 Hearing Branch 1 84702/01 BLCCH.PB Atomic Safety and Licensing Board Panel 1p 22103 037 24X Fiche 50-445.84702/01.8402070056
- 8401190016 IE Info Notice 84-07, "Design-Dasis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN.E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000,84/02/03,8401190016
 - 01190017 IE Bulletin 84-01. "Cracks in BWR Mark I Centainment Vent Headers " Svc list enci DEYOUND.RC Director's Office. Office of Inspection and Enforcement 84/02/03 Consultdated Edison Co of New York. Inc 102pp 22177 156 24X Fiche 50-000.84/02/03.6401190017
- 402280514 Forwards IE Emergency Preparedness Appraisal Repts 50-445/83-33 & 50-446/83-17 on 830926+1007 Discussion of significant preparedness deficiencies in emergency preparedness program also encl JUHNSON-E H Region 4, Office of Director 84/02/08 GARY, R J Teras Utilities Generating Co 18pp 22407 223 24X Fiche 50-445-84/02/08.8402280514
- -8402R80534 IE Emergency Preparedness Appraisal Repts 50-445/83-33 & 50-446/83-17 on B30726-1007 Major areas inspected emergency organization, training, emergency facilities & equipment, procedures & coordination w/offsite groups & drills MONTGOMERY, J. L., ROHRER, D. M., MISNER, C. E. Region 4, Defice of Director 84/02/06, 72pp 22407 241 24X Fiche 50-445,84/02/08,8402280514
- 01190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR30.App R) " Syc list enc!
 01000AN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259 24X Fiche 50-000.84/02/13,8401190041
- iOl190090 Board Notification 84-021 provides repts of Transamerica Delaval, Inc insps conducted from Mar 197° to Oct 1983. EISENHUT, D G Division of Licensing 84/02/13 PALLADIND Commissioners 5pp 22314 OO1 24X Fiche 50-000,84/02/13, 8401190050
- 01190039 IE Info Notice 84-08, "10CFR90 7, 'Employee Protection'" Svc list enc! JORDAN EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/14 Consolidated Edison Co of New York, Inc 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- 3401190045 IE Info Notice B3-63. Suppl 1, "Potential Failures of Westinghouse Type BA-1 Differential Relays " Svc list encl JDRDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/15 Consolidated Edison Co of New York, Inc 118pp 22366 142 24X Fiche 50-000, 89/02/15, 8401190045
- 1401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Bet Below Hamufacturer Recommended Value " Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24% Fiche 50-000.84/02/21,8401190062
-)ii90066 IE Info Notice 84-11, "Training Program Deficiencies"
 3vc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066

- 8401190047 IE Info Notice 84-12, "Failure of Soft Seat Valve Beals "
 Svt list encl
 JURDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 040 24X Fiche 50-000.84/02/27.8401190057
- S Reportable occurrences. LERs & related correspondence
- 8402140333 Interim deficiency rept re defective Delaval piston skirt castings for diesel generators Piston skirt castings will be replaced w/casting provided by supplier by May 1984 GARY.R J Texas Utilities Generating Co 84/01/30 JOHNSON, E R Region 4. Office of Director 2pp 22221 240 24X Fiche 50-446.84/01/30,8402140333
- E402070393 Requests that NRC investigate design reliability of emergency diesel generators supplied by Transamerica Delaval. Inc Engine problems have been experienced since delivery of first vessel in May 1981 Related info encl MOLINAL J C Falcon Carriers, Inc 84/02/01 DENTON. H R Office of Nuclear Reactor Regulation, Director 63pp 22096 037 24X Fiche 50-000,84/02/01.8402070393
- 8402170282 Interim deficiency rept re laminations & delaminations in cable tray support column in cable spread room Initially reported on 840111 Evaluation continuing Next rept expected by 840309 GARY, R J Texas Utilities Generating Co 84/02/07 JOHNSON, E R Region 4. Office of Director ip 22277 162 24X Fiche 50-445.84/02/07.8402170282
- 8403220420 Deficiency Rept SDAR-126 re defective diesel generator engine push rods Defective push rods will be removed & scrapped & replacements requisitioned & installed before operation OARY, R J Texas Utilities Generating Co 84/02/08 JDHN9DN.E H Region 4. Office of Director 2pp 22340 172 24X Fiche 50-445, 84/02/08.8402220420
- 8401190048 Board Notification 84-006 provides info re alleged falsification of GC documents concerning const of safetyrelated HVAC units by Bahnson Co. Winston-Balem. NC LISENHUT. D 9 Division of Licensing 84/02/09 PALLADING Commissioners 7pp 2232 187 24X Fiche 50-000, 84/02/09, 8401190048
- B401190003 Board Notification 84-020 forwards info re Transamerica Delaval. Inc emergency diesel generator problems Attendance list.meeting handouts & slides encl EISENHUT.D Q Division of Licensing 84/02/13 PALLADIND Commissioners 102pp 22332 202 24X Fiche 80-000,84/02/13,
- 8402220033 Final deficiency rept re stainless steel tubing observed cracked Investigation complete Matter not reportable under 10CFR50 55(e) OARY, ft J Texas Utilities Generating Co 84/02/13 JDHN80N.E. Region 4. Office of Director 1p 22338 255 24X Fiche: 50-445.84/02/13.8402220033
- 840222017: Final deficiency rept re section modulus used in design of pipe supports using tube steel Initially reported on 840118 Condition determined not reportable per 100FR50 55(e) OARY.R J Texas Utilities Generating Co 84/02/13 JUHNSON, E H Region 4, Office of Director in 22340 137 24X Fiche. 50-445, 84/02/13,8402220171
- B402220545 Deficiency rept re failed inverters in NBBE Caused by prounded secondary winding of inverter ferroresonant output transformers Transformers will be returned to manufacturer for repair GARY, R J Texas Utilities Generating Co 84/02/13 JDHNSDN, E H Region 4, Office of Director 2pp 22333 132 24X Fiche 90-445, 84/02/13.8402220545
- 8402220330 Part 21 rept re defective DSR & DSRV standby diesel generator turbocharger thrust bearing lubrication Deficiency not corrected by sys mod New recommendation will be sent to customers by 840330 BDYER, R.E. Transamerica Delaval, Inc. 84/0R/15 Director's Office of Inspection and Enforcement 5pp. 22332-182 24X Fiche 80-000.84/02/15,8402220330
- B402280268 Deficiency rept re error in tolerances used in calibr of adhesion tester Initially reported on 840116 Condition not reportable under 10CFR50 55(e) Evaluation continuing & completion anticipated by 84015 GARY.R J Texas Utilities Generating Co. 84/02/15 JOHNSON, E H Region 4, 0ffice of Director ip 22397 071 24X Fiche 50-445.84/02/15.8402280268

- 8402280493 Deficiency Rept SDAR-131 re lugs found w/bad crimps
 Initially reported on 840124 Evaluation continuing &
 completion anticipated by 840330
 GARY,R. J Texas Utilities Generating Co 84/02/20 JOHNSON,E J
 Region 4. Office of Director ip 22407 076 24X
 Fiche 30-445,84/02/20,8402280493
- B402280701 Notification of 840308 meeting w/Transamerica Delaval.Inc (TDI) Owners Group in Wading River.NY to discuss TDI proposed grogram plan to qualify diesel generators CARUSD,R Division of Licensing 84/02/23 BERLINGER.C Division of Licensing 2pp 22414 340 24X Fiche 50-000,84/02/23, 8402280701
- T Hearing transcripts on non-antitrust matters
- 8402100044 Forwards prefiled testimony of J Doyle, W Walsh, H Stiner & D Stiner re CYGNA rept & associated welding matters, per ASLO 831228 memorandum & order, for 840220-24 hearings Certificate of Syc encl ELLIB.J Citizens Association for Sound Energy 84/02/07 BLDCH.P B . JGRDAN,W H . MCCGLLOM,K A Atomic Safety and Licensing Board Panel 3pp 22178 300 24X Fiche 50~445,84/02/07,8402100066
- --8402100072 Testimony of J Doyle re CYGNA rept on pipes & pipe supports DOYLE, J Citizens Association for Sound Energy 84/02/07 16pp 22178 303 24X Fiche 90-449,84/02/07,8402100066
- --8402100079 Testimony of MA Walsh on CYGNA executive summary WALSH,M A Citizens Association for Sound Energy 84/02/07 24pp 22178 319 24X Fiche 50-445.84/02/07.8402100066
- --8402100085 Testimony of D Stiner & H Stiner re open welding issues STINER.D., STINER.H Citizens Association for Sound Energy 84/02/07 47pp 22178 343 24X Fiche 50~445,84/02/07,8402100046
- 8402100184 Forwards rebuttal testimony of applicant panel re welding & ASME & AMB Code provisions Encls will be introduced at hearings commencing on 840220 REYNOLDS,N 8. Bishop, Liberman, Cook, Purcell & Reynolds REYNOLDS,N 8. Texas Utilities Generating Co 84/02/08 BLOCH,P B JGRDAN,W H , MCCOLLOM,K A Abomic Safety and Licensing Board Panel 4pp 22181 341 24% Fiche 50-445,84/02/08.8402100184
- --8402100190 Rebuttal testimony of WE Baker, CT Brandt, MD Muscente, FE Coleman, CR Brown, JD Green, JE Hallford, I Pickett, AM Braumuller & S Fernandez on Stiner allegations re weave welding & welding of misdrilled holes
 BAKER, W E, BRANDT, C T, MUSCENTE, M D Texas Utilities Generating Co 84/02/08 56pp 22181 345 24X Fiche 50-445, 84/02/08, 9402100184
- --8402100193 Rebuttal testimony of WE Baker, MD Muscenta & MN Bressler re allegations involving AWS & ASME Code provisions BAKER, W E , MUSCENTE, M D , BRESBLER, M N Texas Utilities Qenerating Co 8402/08 32pp 22182 039 24x Fiche 50-445,84/02/08,8402100184
- 8402140002 Testimony of LD Gilbert & RD Taylor on plug welding, weave welding, downhill welding & weld rod control re const quality Certificate of Syc encl GILBERT, L D . TAYLOR, R O Division of Resident, Reactor Project & Engineering Programs 84/02/08 25pp 22217 119 24X Fiche 50-445,84/02/08,8402140002
- 8402140354 Transcript of 840210 telephone conference in Bathesda.MD Pp 9,257-9,298
 Atomic Safety and Licensing Board Panel 84/02/10 41pp 22219,349
 24X Fiche 50-445.84/02/10.8402140354
- 840215020B Motion to late file testimony of new witness Hatley testimony contains substantive & pertinent math necessary to complete record Certificate of Svc encl
 ELLIB.J Citizens Association for Bound Energy 84/02/10
 8aPety and Licensing Board Fanel 4pp 22244 084 24X
 Fiche 50-445,84/02/10,8402150208 Atomic
- --8402150215 Testimony of D Hatley re documentation control at Pacilities * Atomic Bafety and Licensing Board Panel 84/6 22244 088 24X Fiche 50-448,84/02/10,8402150208
- 8402170119 Informs that MN Bressler will be replaced by RE Lorentz & JD Stevenson in testimony re allegations on AWS & ASME Code provisions Rebuttal testimony encl REYNOLDS.N S Bishop. Liberman, Cook, Purcell & Reynolds 84/02/18 BLOCH.P.B Atomic Safety and Licensing Board Panel 2pp 22300:325 24X Fiche 50-445,84/02/15,8402170119

- ~-B402170126 Rebuttal testimony of WE Baker,MD Noscente,JD Stevenson * RE Lorent: re allegations involving AWS & ASME Code provisions BAKER, W.E., MUSCENTE, M.D., STEVENSON, J.D. Brown & Root Corp (subs of Halliburton Corp.) 84/02/15 37pp 22300 327 24X Fiche 50-445,84/02/15,8402170119
- B402170183 Transcript of 840215 telephone conference in Washington, DC Pp 9, 299-9, 336 * Atomic Safety and Licensing Board Panel 84/02/15 4Opp 22299 102 24% Fiche 30-445, 84/02/15, 8402170183
- 8402270073 Forwards staff corrections to testimony of LD Gilbert & RO Taylor on plug welding, weave welding, downhill welding & weld rod control Related correspondence MIZUNO.0 8 Hoaring Branch 1 84/02/17 BLOCH.P B Atomic Safety and Licensing Board Panel 3pp 22387 065 24X fiche 50-445.84/02/17.8402270073
- --B402270076 Corrected testimany of LD Gilbert & RG Taylor on plug welding, weave welding, downhill welding & weld red central Related correspondence OILBERT, LD, TAYLOR, RG Division of Resident, Reactor Project & Engineering Programs B4/02/17 22pp 22387 068 24% Fiche 50-445,84/02/17,8402270073
- 8402240103 Transcript of 840220 hearing in Fort Worth, TX Pp 9,337-7.801 * Commissioners 84/02/20 337pp 22372 001 24X Fiche 50-445,84/02/20,8402240103
- 8402270409 Transcript of 840221 hearing in Fort Worth.TX Pp 9.602-9.844 Supporting documentation encl * Commissioners 84/02/21 263pp 22388 208 24X Ficha 50-445,84/02/21,8402270409
- 8402280341 Transcript of 840222 hearing in Fort Worth.TX Pp 9.645-9.911
 * Commissioners 84/02/22 55pp 22403 07/ 24X
 Fiche 50-445.84/02/22.8402280341
- 8402290329 Transcript of 840223 hearing in Fort Worth,TX Pp 9,912-10.327 Bupporting documentation encl * Commissioners 84/02/23 415pp 22423 173 24X Fiche 80-445,84/02/23.8402290329
- 8402280561 Transcript of 840224 hearing in Fort Worth, TX Pp 10,328-70,947 * Commissioners 84/02/24 47pp 22406 181 24X Fiche 50-445,84/02/24,8402280561
- U Congressional/Executive Correspondence
- B402240277 Responds to FOIA request for three categories of documents re facilities Forwards App A Documents 1-4 Documents 5-9 provided previously via svc list FELTON.J M Division of Rules and Records B4/01/27 SUCARMAN,R Sugarman & Dønworth 2pp 22394 298 24X Fiche 50-000, 84/01/27, B402240277 SUGARMAN, R J
- --8308090022 Forwards second quarterly status rept for 1783 on actions taken re operating reactors & licensing reviews of new facilities Commissioners 83/07/21 BEVILL,T House of tions 11pp 22394 300 24x Fiche 50-000, ABBELSTINE, J K Rep . Appropriations 84/01/27,8402240277
- V Operator Examinations
- 8402160612 Advises that Rev 3 to Training Procedure TRA-204, "Licensed Operator Requalification Training Program," acceptable VOUNOBLOOD, B. J. Licensing Branch 1 84/02/03 GARY, R. J. Texas Utilities Generating Co. 2pp. 22302 027 24X Fiche 50-445, 84/02/03.8402160612

DDCKET STN-50-447 GESSAR-238

- A Application/construction stage documents & correspondence
- 8402080028 Forwards proprietary response to NRC B40126 request for additinfo re severe accident review of GESSAR II Rationale for treatment of fire & flood event uncertainty analysis & affidavit requesting info be withheld (ref 10CFRE 790) enct GUIRK.JF General Electric Co 84/02/01 EISENHUT,D G Division of Licensing 5pp 22128 070 24X Fiche 50-447.84/02/01, 84020028

- B402160596 Notification of 840209 meeting w/GE & BNL in Bethesda.MD to discuss ASTAU methodology considerations for GESSAR II severe accident review BCALETTI.D C Standardization & Special Projects Branch B9/02/07 Standardization & Special Projects Branch 2pp 22302 032 24X Fiche 30-447.84/02/07.8402160596
- F Security, medical, emergency & fire protection plans
- 8402080028 Forwards progrietary response to NRC 840126 request for additing reserves accident review of GESSAR II Rationale for treatment of fire & flood event uncertainty analysis & affidavit requesting inco be withheld (ref iOCFR2 790) encl GUTRK. J F General Electric Co 84/02/01 EISENHUT, D G Division of Licensing Spp 22128 090 24X fiche 50-447,84/02/01,
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 8402020323 Forwards proprietary draft amend to GESSAR II, supporting leak before break approach Submittal extends leak before break approach only to recirculation sys piping Affidavit enci Rept withhold (ref 10CFR2 790)

 GUIRK, J. F. General Electric Co. 84/01/31 THOMAS, C. G. Btandardization & Special Projects Branch 6pp 22055 057 24X Fiche 30-447,84/01/31,8402020323

DUCKET STN-50-454 BYRON STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 3402070003 Responds to FDIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documents FELTON.J M Division of Rules and Records 83/10/31 ROSENBAUM, D M Technical Analysis Corp 19pp 22193 292 24% Fiche 80-000,83/10/31,8402070003
- --8402090098 Graph re const activities * NRC No Datailed Affiliation Diven 83/10/3: 22194 136 24X Fichs 50-000,83/10/31,8402090003 93/10/31
- --8402090185 Handwritten notes & calculations re const activities * NRC No Detailed Affiliation Given 82/10/31 5pp 22195 067 24X Fiche 50-000.83/10/31,8402090003
 - 8402090189 Handwritten notes & calculations re const activities & fuel load preparation.

 * NRC - No Detailed Affiliation Given 77/02/27
 22195 074 24X Fiche 50-000.83/10/31.8402090003
 - 12:20110 Board Notification 84-00: forwards EM Gogol 83:127 petitions for emergency relief & NRR 831216 ack ltr Petitions allage inadequacy in conduct of integrated leak rate testing. NDVAK.T M Assistant Director for Licensing 84/01/12. Bafety and Licensing Board Panel 3pp 22012,323 24X Fiche 50-000,84/01/12.8312120110 Atomic
 - 312220267 Petition for emergency relief concerning unsafe conditions ro integrated leak rate testing for US nuclear power reactor containments Severe errors, defects & loopholes exist in concatingents Severy error of the control of the co
 - 12220269 Petition for emergency relief re primary containment leak rate at facilities Vnsafr condition exists re ability of primary containment to fulfill design function 0000L,E M Affiliation Not Assigned 83/11/29 KEPPLER, J. G Region 3, Office of Director App 22012 334 24X Fiche 50-000,84/01/12,8312120110
 - 120135 Board Notification 84-011 discusses NRC use of terms mportant to safety" & "safety-related"

 BENNUT, D G Division of Licensing 84/01/18 PALLADING, LINSKY, ROBERTS Commissioners 72pp 22241.008 24X che 50-000.84/01/18.8312120136
 - GiO410 Generic Ltr 84-04 to all operating PWR licensess, CP holders applicants for CPs re sefety evaluation of Westinghouse pical repts dealing u/elimination of postulated pipe eaks in PWR primary main loops 8vc list encl.

 SENHUT: D G Division of Licensing 84/02/01 Consolidated ison Co of New York. Inc. 59pp 22177 087 24x che: 50-000,84/02/01;8402010410

- 8402070511 Forwards comments on proposed Rev 5 to offsite dose calculation manual Comments clarify dose calculation & bases for particular valves Revised manual requested within 30 days YOUNOBLOOD, B. J. Licensing Branch 1 84/02/02 FARRAR, D. L. Commonwealth Edison Co. 10pp 22141 285 24% Fichs 50-454, Commonwealth Edison Co B4/02/02, B402070511
- B402140482 Responds to B40202 questions re Chicago Tribune article on safety problems Insp Findings published in NUREO-0400, Vol 4.Number 2
 DIRCKS,W J Dffice of the Executive Director for Operations B4/02/08 PALLADINO.N J Commissioners 3pp 22251 352 24X
 Fiche 50-434,84/02/08,8402140482
- --B4021404B4 Requests answers to encl questions re Chicago Tribune article on safety problems at facilities PALLADINO, N J Commissioners B4/02/02 DIRCKS, W J Office the Executive Director for Operations 2pp 22251 335 28x .mox8.W J Office of 22251 355 240 Fiche 50-454, 84/02/08, 8402140482
- 8402210450 Act receipt of 840106 addendum to petition for emergency relief citing 830707 FOIA request for all documentation reintegrated leak rate testing at LaSalle & Byron Ltr being treated as supplemental FOIA request Meeting summary encl DENTON.H R Office of Nuclear Reactor Regulation, Director 84/02/09 QUOCLE M Affiliation Not Assigned in 22344 014 24X Fiche 50-000,84/02/09,8402210450
- B402240120 Forwards supplemental info to resolve NUREG-0612, "Control of Heavy Loads " Info also addresses concerns in Phases 1 & 2 of draft technical evaluation rept W/51 oversize drawings Aperture cards are in PDR BARNES P L Commonwealth Edison Co 84/02/10 of Nuclear Reactor Regulation, Director 29pp Fiche 50-000.84/02/10.6802240120 DENTON, H R 22374 289 Offic+ 24x
- 8401190057 Board Natification 84-032 provides addl info on environ qualification Submittal augments info in Board Notifications 84-004 & 84-007 EISENHUT.D Q Division of Licensing 84/02/13 Atomic Safety and Licensing Board Panel 10pp 22314 204 24X Fiche 50-000,84/02/13, Board 1907,84 Atomic Safety and 8401190059
- 8401190068 Board Notification 84-033 provides "Bys Interaction Program," task action plan for Unresolved Bafety Issue A-17 Distribution its enc! EIBENHUT, D Q Division of Licensing 84/02/16 PALADIND Commissioners Bpp 22482 091 24X Fiche 50-000,84/02/16, 8401190068
- B402240108 Withdraws ED Ewartz 830B15 request for NRC approval for use of Winter 1983 addenda of ASME Boiler & Pressure Vessel Code Review of radiographs indicates penetrameter shims used as necessary to satisfy existing code TRAMM.T R Commonwealth Edison Co 84/02/17 DENTON.H R Office of Nuclear Reactor Repulation. Director 1p 22375 008 24X Fiche: 50-454, 84/02/17.8402240108
- E NRC Bafety Evaluation Report (BER), supple & correspondence
- 8402:30373 Forwards safeguards SER statement for review of Bection 4 C. "Identification of Vital Areas" Time spent on review should be reported under Planned Accomplishment 141415 Encl withheld withdest O Standardization & Special Projects Branch B PARR.O D Auxiliary Systems Branch ip 22281 022 24X Fiche 50-454,84/02/03,8402150393 84/02/03
- 8402280240 Forwards ODC 31 compliance review re RCPB components & cartified mat1 test repts for components Info should resolve SER Outstanding Item 4
 SWARTZ.E D Commonwealth Edison Co 84/02/22 DENTON, H R Of Nuclear Reactor Regulation, Director 7pp 22399 262 24x
 Fiche 50-000,84/02/22,8402280240
- F. Security, medical, emergency & fire protection plans
- B402130191 Rev O to Emergency Plan Implementing Procedure EDF-17, "Emergency Operations Facility Activation Facility Log " BERLIN.M D Commonwealth Edison Co B3/09/23 3pp 22199 283 24X Fiche 50-000, B3/09/23, 8402130191
- 8402130215 Rev O to Emergency Plan Implementing Procedure EOF-18, "Nuclear Station Div Non-Edison Transportation Incident Assistance Procedure."

 * Gommonwealth Edison Co 83/09/29 5pp 22204 078 24K Fiche 50-000,83/09/27,8402130215

- 8402100137 Revised emergency plan implementing procedures, including Procedures EPIP EDF-17 re emergency operations facility activation log.EPIP CC-12 re sys power dispatcher & EPIP EDF-12 re access control W/840203 memo & receipt form MODRE.R D Commonwealth Edison Co 63/11/09 DENTON, H R NRC No Detailed Affiliation Given 24pp 22181 288 24x Fiche 50-000.83/11/09.8402100137
- B402130220 Rev B to Emergency Plan Implementing Procedure CC-12, "Sys Power Dispatcher" MODRER D Commonwealth Edison Co 83/11/09 11pp 22200 10B 24X Fiche 50-000,83/11/09,8402130220
- 8402150358 Rev 2 to Generating Station Emergency Plan Implementing Procedure EOF-12, "Access Control to Emergency Operations Facility " W/831108 ltr & receipt form MODRE, R D Commonwealth Edison Co 83/11/30 5pp 22242 358 24X Fiche 50-000,83/11/30,8402150358
- 8402060446 Forwards Rev 9 to Emergency Plan Implementing Procedure CC-1, "Corporate Command Ctr Director "Recovery manager priority notification table encl MDDRE.R D Commonwealth Edison Co 84/01/30 DENTON, H R Diffiof Nuclear Reactor Regulation, Director 2pp 22083 127 24X Fiche 50-000,84/01/30,8402060446 Difice
- --8402060464 Rev 9 to Emergency Plan Implementing Procedure CC-1, "Corporate Command Ctr Director." controlled copy MODRER D Commonwealth Edison Co 83/11/30 76pp 22083 131 24% Fiche 50-000.84/01/30.8402060446
- 8402070060 Forwards interim finding on offsite radiological emergency planning State of IL & Ogle & Winnebago Counties offsite plans acceptable RRIMM.R W Federal Emergency Management Agency 84/02/01 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2ipp 22157 178 24X Fiche 50-454. 84/02/01.840780060
- 8402070204 Forwards evaluation of B31115 joint exercise of offsite radiological emergency preparedness plans State of IL & Ogle & Winnebago Counties participated KRIMM.R W Federal Emergency Management Agency 84/02/01 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 2pp 22163 150 24X Fiche 50-454,84/02/01,8402070204
- --8402070207 Evaluation of B31115 joint exercise of offsite radiological emergency preparedness plans
 Federal Emergency Management Agency 84/01/09 35pp
 22163 152 24X Fiche 50-454,84/02/01.8402090204
- 8402150240 Forwards IE Emergency Preparedness Appraisal Repts 50-454/83-56 & 50-455/83-39 on 831205-16 No noncompliances noted PAPERIELLO,C J Region 3. Office of Director 84/02/03 REED,C.
 Commonwealth Edison Co 7pp 22245 027 24% Fiche 50-454,84/02/03,8402150240
- --8402150247 IE Emergency Preparedness Appraisal Repts 50-454/83-56 & 50-455/83-39 on 831205-16 No noncompliances noted Major areas inspected administration of emergency preparedness grogram; emergency organization & training & retraining PLOSKI, T J, GLDERSEN, W P, CHRISTOFFER, Q Region 3, Office of Director 84/02/04 &3pp 22245 042 24X Fiche 50-454,84/02/03,8402150240
- 8402150393 Forwards safeguards SER statement for review of Section 4 O. "Identification of Vital Areas" Time spent on review should be reported under Planned Accomplishment 141415 Encl withheld.
 - THOMAS.C O Btandardization & Special Projects Granch B PARR.O D. Auxiliary Systems Branch ip 22281 022 24X Fiche 50-454.84/02/03.8402150393 B4/02/03
- 8402280395 Revised emergency plan implementing procedure, including Rev i to BZP 600-A4, "08EP Telephone Directory," * Commonwealth Edison Co 84/02/18 61pp 22404 158 24X Fiche. 50-000, 84/02/18, 8402280395
- 8402270413 Forwards IE Bafeguards Insp Rept 50-454/84-11 on 840208-10 No noncompliance identified AKELBON-N L Region 3. Office of Director 84/02/21 REED,C Commonwealth Edison Co 2pp 22390 230 24X Fiche 50-454,84/02/21 8402270413
- --8402270416 IE Safeguards Insp Rept 50-454/84-11 on 840208-10 No noncompliance noted Major areas inspected review of status of licensee approved training & qualification plan Details withheld (ref 10CFR73 21)

 BELANGER, J. L., MADEDA, T. J., CREED, J. R. Region 3, Office of Director 84/02/21 lp 22390 232 24X Fiche, 50-454, 84/02/21, 8402270413

- O Adjudicatory correspondence
- 8402060187 Forwards reinsp pregram rept.util 831028 preliminary reinsprept.NRC 831118 initial response % NRC 831228 insprept
 W/o encls Related correspondence
 BIELAMSKI.A P Isham, Lincoln & Beale BIELAMSKI.A P Commonwealti MILLAMBRIA P ISHAM, LINCOIN & Beale BIELAMSKI, A P Commonwealth Edison Co BA/O1/27 ROBENTHAL, A S, GOTCHY, R L, KUHL, C N Atomic Safety and Licensing Appeal Panel 2pp 22088 189 24X Fiche 50-454, B4/01/27, 8402040187
- B402060182 Informs of withdraual of D Thomas from svc list Certificate of Svc encl Related correspondence LEWIB.E League of Homen Voters of Rockford, IL 84/01/29 SMITH.I W. COLE.R F. CALLIHAN.A D Atomic Safety and Licensing Board Panel 2pp 22087 195 24X Fiche 50-454.84/01/29, 8402060182
- 8402010056 Memorandum & order adopting listed briefing schedule, sub) to possible later advancement of 840330 deadline for filing of third tier briefs & authorization of reply briefs on timely motion & for good cause shown SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel 84/01/31 3pp 22042 246 24X Fiche 50-454.84/01/31.8402010056
- 8402030194 Informs that on 840127.counsel for applicant furnished ASLAB w/840112 rept on reinsp as result of Noncompliance Items 50-454/82-05-19 & 50-454/982-05-19 Bocument accepted as fulfillment of obligation to keep ASLAB informed BHUEMAKER.C J Atomic Bafety and Licensing Appeal Panel 84/02/02 2pp 22047 346 24% Fiche 50-494/84/02/02.8402030194
- 8402080131 Motion to limit consideration of post-record submissions in applicant 840127 ltr Certificate of Svc encl WHICHER.JM League of Women Voters of Rockford, IL WHICHER.JM Whicher, JM 84702703 Atomic Safety and Licensing Appeal Panel App 22132 137 24X Fiche 50-454.84702703.8402080131
- 8402080195 Notifies that Board members unable to comment on matters other than through official issuences Initial decision of proceeding encl W/a encl
 SMITHI W Atomic Safety and Licensing Board Panel 84/02/06
 GILQY.E W Application Not Assigned ip 22130 147 24X Fiche: 50-454, 84/02/06, 8402080195
- --8402080198 Requests explanation for denial of OL GILOY, E.W. Affiliation Not Assigned 84/01/17 and Licensing Board Panel. 1p 22130 148 24x Fichs 50-434, 84/02/06.8402080195 Atomic Safety
- 8402100149 Motion for increase in page limitation to file brief up to 120 pages Certificate of Svc encl STEPTOE.P B Commonwealth Edison Co STEPTOE.P B Isham, Lincoln & Beale 84/02/04 Atomic Safety and Licensing Board Panel Spp 22182 157 24X Fiche 50-454.84/02/06.8402100149
- 8402070151 Memorandum & order granting in part.mation to appeal ASLE BA0113 initial decision denying (i. application Page limitation enlarged to B0 pages Request for refrain from review of B30807-10 transcript rejected SMGEMAKER.C J Atomic Bafety and Licensing Appeal Panel 84/02/08 Commonwealth Edison Co 3pp 22163 137 24X Fiche 50-454,84/02/08.8402090151
- 8402140251 Forwards documents pertinent to ASLB 840113 initial decision Document topics include enforcement actions, reinsp program audits & surveillances & special insp re worker program audits & surveillances & special inso re worker allegations W/o encl
 MILLER,M I. Isham, Lincoln & Beale MILLER,M I Commonwealth
 Edison Co. 84/02/10 ROSENTALLA B, GOTCHY,R L, KOHL,C N Atomic
 Bafety and Licensing Appeal Panel 5pp 22274 314 24X
 Fiche:50-454,84/02/10,8402160251
- 8402160222 Motion opposing ABLAB decision to deny issuance of OL Flawed legal & factual analysis leading to denial of application apparent & evidence demonstrates that util met GA obligations,
 MILLER.M I. Commonuealth Edison Co MILLER.M I Isham, Lincoln & Beals 84/02/13 Abomic Safety and Liconsing Appeal Panel 80pp 22274 835 24X Fiche 50-454,84/02/13,8402160222
- -8402160227 Motion for alternative to reopen record to receive further evidence Evidence described in encl LO George affidavit MILLER, M I Isham, Lincoln & Maller, M I Isham, Lincoln & Beale, 84/02/13 Atomic Safety and Licensing Board Panel. App 22275.090 24X Fiche 50-454,84/02/13,8402160222 Isham, Lincoln &
- --8402160231 Affidavit of LO George re date accumulated by reinspection program final rept Evaluation will clearly indicate that quality of work performed is satisfactory Certificate of Byc enci GEORGELL D. Commonweelth Edison Co 84/02/13 7pp 22275.097 24X Fich= 50-454,84/02/13,8402160222

- 8402170034 Notice of withdrawal of appearance in proceeding Certificate Of Svc enci WHICHER.J N Dekalb Area Alliance for Responsible Energy 3pp 28300 271 24/ Fiche 50-454.84/02/13:8402170034 84/02/13
- B40216024: Order directing other parties to file answers to applicant alternative motion to reopen evidentiary record at same time as briefs filed in response to applicant brief SHOERMAKER-C J Atomic Safety and Licensing Appeal Panel 84/02/14 ip 22274 332 24X Fiche 50-454,84/02/14.8402160241
- 8402210118 Advises that briefing or ruling on intervenor motion to limit consideration of post-record submissions unnecessary HHICHER.J M Businessmen for the Public Interest HHICHER.J M Bekalb Area Alliance for Responsible Energy 84/02/15 ROSENTHAL.A S. KOHL.C N., GOTCHY.R L. Atomic Safety and Licensing Appeal Panel 1p 22317 202 247 Fiche 50-454.84/02/15.8402210118
- 8402210171 Memorandum informing of intention to treat intervenor motion to limit consideration of post-record submission as withdrawn SHDEMAKER,C J Atomic Safety and Licensing Appeal Panel 84/02/16 10 22316 348 24% Fiche 50-454,84/02/16,8402210171
- B402230104 Responds to B40215 ltr re svc of ASLAB memoranda & orders for proceeding Official svc list serves representatives; DW Cassell & JM Whicher SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel B4/02/23 JDRNSON, B League of Homen Voters of Rockford, IL 2pp 22362 1324X Fiche 50-454.84/02/22.8402230104 64/02/22 22362 136
- --8402230107 Requests to correct omission from ASLAB svc list JOHNSON B League of Women Voters of Rockford, IL 84/02/15 SHOEHAKER.C J Atomic Safety and Licensing Appeal Panel 1p 22362 138 24X Fiche 50-454.84/02/22.8402
- 8402280471 Submits corrigends to 840213 brief Certificate of Svt encl BECKER.B D Isham Lincoln & Beale BECKER.B D Commonwealth Edison Co 84/02/22 ROSENTHAL.A S . GOTCHY.R L . KOHL.C N Atom Safety and Licensing Appeal Panel 4pp 22404 353 24X Fiche 50-454.84/02/22.8402280471 Atomic
- 8402270073 Memorandum forwarding Judge Rosskowski of Northern District of State of IL 840222 order re in camera presentations SMITH.I W Atomic Safety and Licensing Board Panel 84/02/27 Office of the Esecutive Legal Director 14pp 22421 074 24X Fische 50-454.84/02/27.8402270073

I Financial information

02280410 Annual Financial Rept 1983 W/840221 ltr 'CONNOR,J J Commonwealth Edison Co 83/12/31 29pp 22407 101 X Fiche 50-000,83/12/31,8402280410

repection reports. IE Bulletins & correspondence

120153 IE Info Notice 84-04, "Steam Binding of Auxiliary Feedwater aps " Syc list enc! (BAN.E.L. Division of Emergency Preparedness & Engineering aponse (Post 830103) 84/01/25 Consolidated Edison Co of New ht. Inc 120pp 22058 001 24% Fiche 50-000,84/01/25,8312120153

080275 Ferwards IE Insp Repts 30-454/84-01 & 50-455/84-01 en //0110-12 & 13 No noncompitance noted APERIELLO.C J. Region 3. Office of Director 84/01/27 REED.C ommonwealth Edison Co. 2pp 22131 294 24X Fiche 50-454.84/01/27.

302B0 IE Insp Repts 50-454/84-01 & 50-455/84-01 on B40110-12 & 13 incompliance noted Major areas inspected preoperational ogical environ monitoring program. Including entation & results, GA & mot controls NN.M J. BLAMINSKI, W J. SCHUMACHER, M Region 3, Office of B4/01/27 Spp 22131 296 24X Fiche 50-454,84/01/27. 0275

Forwards IE Insp Repts 50-454/84-02 % 50-455/84-02 un 40118 No noncompliance noted Region 3. Office of Director 84/01/20 REED.C *** Tdison Co. 2pp 22130 297 24% Fische 30-454,84/01/30.

18p Repts 50-454/84-02 & 50-455/84-02 on 930802-840118 Tap Mepts 50-434/64-06 & 30-435/64-06 ON SOURD tee noted Major areas inspected allegations re es & summary of 631122 Region III insp l reinsp program NAMOHITON, K. MOP.R C Region 3. Office of D1/28 20pp 22130 279 24X Fichs 50-454.B KNOP.R C Region 3. Office of 22130 279 24X Fiche 50-454.84/01/30.

- 8402080395 Deficiency Rept 83-14 re cable grip installation Initially reported on 831229 Also updates info re noncompliance nated in IE Insp Repts 90-454/83-49 & 90-455/83-35 Personnel retrained on proper cable grip installation TRANN.T R Commonwealth Edison Co 84/01/31 KEPPLER, J O Region 3, Office of Director 2pp 22130 360 24% Fiche 50-454,84/01/31. 8402080395
- 8402190364 Forwards IE Insp Repts 50-454/83-58 & 50-455/83-43 on 831208-840120 & notice of violation STREETER, J F Region 3, Office of Director 84/01/31 REED, C Commonwealth Edison Co 2pp 22241 336 24X Fiche 50-454.84/01/31,
- ~~8402130372 Notice of violation from insp on 831208-840120 STREETER, J F Region 3, Office of Director 84/01/31 22241 338 24X Fiche 50-454,84/01/31,8402150364
- --8402150382 IE Insp Repts 50-454/83-58 & 50-455/83-43 on 831208-840120
 Noncompliance noted while conducting Step 9 & 9 of RP-68 12.
 "Reactor Protection Logic Checks." recorded voltage fell
 outside specified range & no deficiency written
 RING.M., VANDENBURGH,C., WILLIAMS.D. Region 3, Office of Director
 84/01/30 8pp 22241 340 24X Fiche 50-454,84/01/31.8402150344
- B402150350 Forwards IE Insp Repts 50-454/B3-52 & 50-453/B3-37 on B31110 & 1208 No noncompliance noted LITTLE.W 5 Region 3. Office of Director 84/02/02 REED.C Commonwealth Edison Co 2pp 22250 254 24% Fichs 50-454.84/02/02. 8402150350
- --8402150353 IE Insp Repts 50-454/83-52 & 50-455/83-37 on 831110 & 1203 No noncompliance noted Major areas inspected previous insp findings MS.C. Region 3. Office of Director 24X Fiche 50-454.84/02/02,8402150350 R , WILLIAMS, C
- 840119006 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000,84/02/03,8401190016
- 8401140017 IE Bullstin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl Headers " Svc list encl DEVOUNG.R C Director's Office. Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 166 24% Fiche 50-000.84/02/03.8401190017
- 8402100017 Discusses 840127 meeting in Glen Etlyn, IL on status & results of reinsp program re certification of GC inspectors.

 NRC questions & comments from review listed
 SPESBARDLR L. Division of Engineering 84/02/03 REED, C
 Commonwealth Edison Co 3pp 22182 151 24X Fiche 50-454.84/02/03.
- 8402150240 Forwards IE Emergency Preparedness Appraisal Repts 50-454/83-56 & 50-455/83-37 on 831205-16 No noncompliances noted
 PAPERIELLO, C. J. Region 3, Office of Director. 84/02/03 REED, C. Commonwealth Edison Co. 7pp 22245 029 24% Fiche 50-454,84/02/03.8402150240
- ---8402150247 IE Emergency Preparadness Appraisal Repts 50-454/83-56 & 50-455/83-39 on 831205-16 No noncompliances noted Major areas inspected administration of emergency preparadness program emergency organization & training & retraining PLOBKI.T J, GLOERSEN.W.P. CHRIBTOFFER.0 Region 3. Office of Director 84/02/04 63pp 22245 042 24X Fiche 50-454,84/02/03.8402150240
- 8402170175 Forwards IE Insp Rept 50-454/84-03 on 840109-13. No noncompliance noted LITTLE,W S Region 3, Office of Director 84/02/03 REED,C Commanwealth Edison Co 2pp R2297 026 24% Fiche 50-454,84/02/03.
- --8402170187 IE Insp Rept 50-454/84-03 on 840109-13 No noncompliance
- B402130527 Ack receipt of 831219 & 30 & 840202 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-454/63-47 SPESSARD.R L Division of Emergency Preparedness & Operational Support 84/02/06 REED.C Communumealth Edison Co 2pp 22201 177 24X Fiche 50-454.84/02/06.8402130927

- --8402130531 Suppls 831219 response to NRC 831119 ltr re violations noted in IE Insp Rept 50-454/83-47 Corrective actions all permanently installed instruments used to collect acceptance criteria data in preoperational tests will be evaluated FARRAR, D.L. Commonwealth Edison Co. 84/02/02 KEPPLER, J.G. Region J. Office of Director 2pp 22201 179 24X Fiche 50-434,84/02/06,8402130527
- --8402130534 Suppls response to NRC 83il19 ltr re violations noted in IE Insp Rept 50-454/83-47 Corrective actions combination of acceptance criteria as response times for reactor trips & review of expected values fulfill FSAR commitment FARRAR, D L. Commonwealth Edison Co. 84/02/23 KEPPLER. J G Region 3, Office of Director 3pp 22201 181 24x Fiche 50-454,84/02/06,8402130527
- --8402130543 Responds to NRC 831119 ltr re violations noted in IE Insp Rept 50-454/83-47 Corrective actions qualification program for sys test engineers reviewed & found acceptable FSAR will be revised to address qualifications FARRAR, D L Commonwealth Edison Co 83/12/30 KEPPLER, J G Region 3, Office of Director App 22201 184 24X Fiche 50-454,84/02/06,8402130527
- --8402130854 Responds to NRC 831119 ltr re violations nated in IE Insp Rept 50-454/83-47 Response re sys test engineer qualifications to be provided within 2 wks Disagrees w/ noncompliance classification for Violations 3 & 4 FARRAR.D L Commonwealth Edison Co 83/12/19 KEPPLER, J G Region 3, Optice of Director 7pp 22201 170 24X Fiche 50-454,84/02/06.8402130527
- 840220584 Forwards IE Insp Repts 50-454/84-08 & 50-455/84-06 on B40117.19 & 20 No noncompliance noted LITTLE: W S Region 3. Office of Director 84/02/06 REED.C Commonwealth Edison Co 2pp 22331 346 24X Fiche 50-454/84/02/06
- ---B402220592 IE Insp Repts 50-454/84-08 & 50-455/84-06 on B40117.19 & 20 No noncompliance or deviations noted Major areas inspected followup on previously identified items re Sargent & Lundy internal technical GA audit
 YIN.I T , DANIELSON,D H Region 3. Office of Director 84/02/06
 5pp. 2233 348 24X Fiche 50-454.84/02/06.8402220584
- 8402170134 Forwards response to IE Bulletin 79-21, "Temp Effects on Level Measurements" Analysis of adequacy of steam generator law level setpoints encl
 BARNESP L Commonwealth Edison Co 84/02/09 KEPPLER, J G Regio 3, Office of Director Bpp 22299 339 24X Fiche 50-000,84/02/09,8402170134
- 8402270089 Forwards IE Insp Repts 30-454/84-05 & 50-455/84-04 on 840117-20 No noncompliance noted LITTLE: W S Region 3. Office of Director 84/02/09 REED. C Commanusealth Edison Co 2pp 22388 174 24% Fiche 50-454, 84/02/09.
- --8402270095 IE Insp Repts 50-454/84-05 & 50-455/84-04 on 840117-20 No noncompliance or deviations identified Major areas inspected allegations, licensee actions on previous insp findings & IE bulletins & 10CFR30 55(e) items WARD.K D. ENG.P L., O'DHYER.9 F Region 3. Office of Director 84/02/08 15pp 22388 176 24X Fiche 30-454.84/02/09,8402270089
- 8401170041 IE Info Notice 84-07. "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R) " Syc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/13 Consolidated Edison Co of New
 York, Inc. 124pp 22365-259 24X Fichs 50-000,84/02/13,8401190041
- 8402170278 Informs that special task force will reexamine SALP 3 ratings.per review of util 830712 response Final SALP 3 repts & assessments will be issued by 840320 Delay in review caused by higher priority efforts KEPPLER.J 0 Region 3, Office of Director 84/02/13 REED.C Commonwealth Edison Co 2pp 22276 146 24X Fiche 50-000.84/02/13, 8402170278
- B401190039 IE Info Notice 84-08, "100FR50 7, 'Employee Protection '"
 Syc list encl,
 JDRDAN: E L Division of Emergency Preparedness & Engineering SVC 11st encl. JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 030103) B4/02/14 Consolidated Edison Co. of New York, Inc. 115pp. 22365,141 24% Fiche 50~000,84/02/14,8401190039
- 8402270130 Forwards IE Insp Repts 30-454/84-06 & 50-455/84-03 on 840118-20 & 24-26 No honcompliance noted LITTLE: W 8 Region 3, Office of Director 84/02/14 REED, C Gammonwealth Edison Co 2pp 22426 155 24X Fichs 50-454.84/02/14, 8402290130

- --8402270135 IE Insp Repts 50-454/84-06 & 30-455/84-05 on 840118-20 & 24-24 No noncompliance noted Major areas inspected revised procedures & instructions, insp personnel records, welder requalifications & exam of installed HVAC equipment KEY, N. J. DANIELSON, D. H. Region 3. Office of Director 84/02/13 13pp 22426 157 24X Fiche 50-454, 84/02/14, 8402270130
- 8401190045 IE Info Notice 83-63. Suppl 1, "Potential Failures of, Westinghouse Type 5A-1 Differential Relays" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp. 22366 142 24X Fiche 50-000.84/02/15.8401190045
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Tolque Switches Set Below Manufacturer Recommended Value "Svc list encl JORDAN, E. L. Division of Emergency Preparedness % Engineuring Response (Post 830103) 84/02/21 Consolidate Edison Co. of New York Inc. 116pp 22366 024 24X Fiche 50~000,84/02/21.8401190062
- 8402270413 Forwards IE Safeguards Insp Rept 50-454/84-11 on 840208-10 No noncompliance identified
 AXELSDN,W.L. Region 3, Office of Director 84/02/21 REED.C
 Commonwealth Edison Co. 2pp. 22390 230 24% Fiche 50-454,84/02/21. B402270413
- --8402270416 IE Safeguards Insp Rept 50-454/84-11 on 840208-10 No 1022/0416 IE Safeguards Insp Rept 50-454/84411 on 04000-10 No noncompliance noted Major areas inspected review of status of licensee approved training & qualification plan Details withheld (ref 100FR/3 21) BELANDER.J L , MADEDA.T J , CREED.J R Region 3, Office of Director 84/02/21 ip 22390 232 24% Fiche 50-454,84/02/21, 8402270413
- 8402270433 Ack receipt of 821213 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-454/82-19 & 50-455/82-14 No basis found to withdraw Violations 1 & 2 Request denied
 LITTLE, H S Region 3, Office of Director 84/02/22 REED. C
 Commanuealth Edison Co 2pp 22389 346 24X Fiche 50-454,84/02/22,
 8402270433
- --0-002270442 Responds to NRC 821112 ltr re violations noted in IE Insp Repts 50-454/82-19 & 50-455/82-14 Corrective actions affected raceways will be redesigned if mod unacceptable Requests withdrawal of Violations 1 & 2 DELOEORGE, L D Commonwealth Edison Co 82/12/13 KEPPLER, J G Region 3, Office of Director Gpp 22389 348 24X Fiche 50-454,84/02/22,8402270433
- 8401190066 IE Info Notice 84-11. "Training Program Deficiencies"
 Svc list encl
 JDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000.84/02/24,8401190066
- 8401190067 IE Info Natice 84-12. "Failure of Soft Seat Valve Seals " Svc list encl JDRDAN, E L OVC 11st enc.
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co. of New
 York, Inc. 120pp 22431 060 24X Fiche 50-000.84/02/27.8401190067
- 8 Reportable occurrences, LERs & related correspondence
- 8402170317 Supplemental Part 21 rept re radingraphic record evaluation. supplying add1 data to 830624 submitted Records show that 90 degree branch connections furnished to North Anna i & 2 jubsites No noriles supplied to Zimmer Related info enci BORNES,R.P Southwest Fabricating & Welding Co (subs of 1U International Corp) 83/10/04 POTAPOUS,U Region 4. Office of Director 6pp 22296 136 24X Fiche 50-000,63/10/04,8402170317
- 8402170196 Final Part 21 rept re potential problem concerning radiography of branch connection welds covered by reinforcing pads Welds at Dyron, Braidwood & North Anna acceptable Weld 7 at Clinton reradiographed BORNES, R P Southwest Fabricating & Welding Co (subs. of IU International Corp.) 84/01/02, POTAPOVS, U Region 4, Defice of Director 2pp 22276 126 24X Fiche 50-000.84/01/02,8402170196
- 8402070365 Part 21 rept re linear converter device w/possible generic defect Initially reported on 84016 Written notifications issued, Customer responses should be received by 840331 Final rept will be submitted by 840430 DDBON, J.P. Pacific Air Products Co. 84/01/30 Director's Office, Office of Inspection and Enforcement 2pp 22114 279 24) Fiche 50-280,84/01/30,8402070365 PAY

6,		
B4	8402070373 Part 21 rept re linear converter device U/possible general defect Initially reported on 84016 Preliminary analysis indicates excessive wear of brass shaft guides Next rept will be submitted within 90 days Supporting info extended to BOBON, J. P. Pacific Air Products Co. 84/01/17 POTAPOVS, U. Region 4. Office of Director 68pp. 22114 301 24X Fiche 50-000,84/01/30.8402070365	8402070511 Forwards comments on proposed Rev 3 to affette total calculation manual Comments clarify dose calculation to bill for particular valves Revised manual requested within 30 days YOUNGBLOOD, 8 J Licensing Branch 1 84/02/02 FARRAR, 0 t Commonwealth Edison Co 10pp 22141 285 24% Fichs 50-454 84/02/02, 8402070511
94 1	8402080395 Deficiency Rept 83-14 re cable grip installation Initially reported on 831229 Also updates info re noncompliance noted in IE Insp Repts 50-454/83-49 & 50-455/83-35 Personnel retrained on proper cable grip installation TRAMM.TR Commonwealth Edison Co 84/01/31 KEPFLER, J G Region 3, Office of Director 2pp 22130 360 24X Fiche 50-454.84/01/31, 8402080395	B4021404B2 Responds to 840202 questions be Chicago Tribura artificing affety problems Insp findings published in NURFO-0400, Vol 4. Number 2 DIRCKS. W. J. Office of the Executive Director for Operation B4/02/08 PALLADINO. N. J. Commissioners. 3pp 20251 357 .c. Fiche 50-434, 84/02/08, 8402140482
84(1 1	T Hearing transcripts on non-antitrust matters B306010017 Transcript of B30525 hearing in Rockford, IL Pp 6,952-7,011	B402140484 Requests answers to encl questions re Chicago fail.4 article on safety problems at facilities PALLADIN,N J Commissioners 84/02/02 DIRCXY,N J [**/, the Executive Director for Operations 2pp 22/25; 353 % fiche 50-454,84/02/08,8402140482
1 64C , E S J	* Atomic Safety and Licensing Board Panel 83/05/25 60pp 18645 131 24% Fiche 50-454,83/05/25,8306010017 U Congressional/Executive Correspondence B402240277 Responds to FOIA request for three categories of documents re facilities Forwards App A Documents 1-4 Documents 5-9 provided previously via svc list FELION.J M Division of Rules and Records. 84/01/27 EUGARMAN.R J Sugarman & Denworth 2pp. 22374 298 24% Fiche 50-000,84/01/27,8402240277	8402240120 Forwards supplemental info to resolve NUNEO Color of Heavy Loads "Info also addresses concerns in Phase & 2 of draft technical evaluation rept W/91 oversity drawing Aperture cards are in FDR BARNES.P.L. Commonwealth Edison Co. 84/02/10 DFHIM.H.f. of Nuclear Reactor Regulation, Director 27pp 2/14 201 in Fiche SO-000.84/02/10,8402240120 8401190059 Board Notification 84-032 provides addl info en and qualification Submittal augments info in Board Notification 84-004 & 84-007
940; Bl	8308090022 Forwards second quarterly status rept for 1983 on actions taken re operating reactors & licensing reviews of new facilities ASSELBTINE.J.K. Commissioners 83/07/21 BEVILL.T House of	EISENHUT, D. G. Division of Litensing 84/02/13 Abstitute Litensing Board Panel 10pp 22314 204 24% I toke 55 65 pt 8401190059 8401190068 Board Notification 84-033 provides "Bys Enterection
E ₁ 54 F1	Rep . Appropriations 11pp 22394 300 24% Fiche 50-000. 84/01/27.8402240277	Program," task action plan for Unresolved Safety lawe A-() Distribution list encl EISENHUT.D 9 Division of Licensing 84/02/16 PA(ACIN) Commissioners 8pp 22482 091 24X Fiche.50~090.84/02/13 8401170068
0 Sh D# F1 F =	DOCKET SYN-50-455 BYRON STATION. UNIT 2 A Application/construction stage documents & correspondence 8402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A,B & C documents FELTON.J M Division of Rules and Records 83/10/31 ROSENBAUM.D M Technical Analysis Corp 19pp 22193 292 24X	9402240108 Nithdraws ED Swartz 830815 request for ARC systaple of Winter 1983 addends of ASMS Bolier & Pressure Vessel Code Review of radiographs indicates penetrameter shies used as necessary to satisfy existing code TRAMM-T.R. Commonwealth Edison Co. 84/02/17 DFMRethis of Nuclear Reactor Regulation, Director 1p R2,815 (8 pc Fiche 30-454,84/02/17,8402240108
0 11 	Fiche 50-000, 83/10/31, 8408090003 8402090098 Graph re const activities * NRC - No Detailed Affiliation Given 83/10/31 3pp 22194 136 24% Fiche 50-000, 83/10/31, 8402090003	E NRC Safety Evaluation Report (SER): supple & correspond of the supplementation of the sup
Pon JOS Ret Yoy	8402090185 Handwritten notes & calculations re const activities * NRC ~ No Detailed Affiliation Given. 82/10/31 Spp 22195 067 24% Fiche 50-000,83/10/31,8402090003	of Nuclear Reactor Regulation, Director. 7pp 22 PV 1:2 PF Fiche 50-000,84/08/22,8402280240 F Security, medical, emergency & fire protection plans
84020 840 PAP Com 840	BAO20901B9 Handwritten notes & calculations re const activities & fuel load preparation * NRC - No Detailed Affiliation Given 79/02/27 7pp 22195 074 24% Fiche 50-000.83/10/31.8402090003	B402130191 Rev 0 to Emergency Plan Implementing Procedure f.f. "Emergency Operations Facility Activation Facility Laz "BERLIN, M D Commonwealth Edison Co 83/07/23 349 3418 24X Fiche 80-000,83/09/23,8402130191
~~840 N r. ir Of D.	B312120110 Board Notification 84-001 forwards EM Gogol 831129 patitions for emergency relief & NRR 831214 ack ltr Patitions allage inadequacy in conduct of integrated leak rate testing NDVAK.T M Assistant Director for Licensing. 84/01/12 Atomic Bafety and Licensing Board Panel 3pp 22012 323 24X Fiche 50-000,84/01/12,8312120110	8402130215 Rev O to Emergency Plan Implementing Proceeds of 1 "Nuclear Station Div Non-Edison Transportation Intites a Assistance Procedure" # Commonwealth Edison Co 83/09/29 5pp 22204 0/# (4) Fiche 50-000,83/09/27,8402130215
84020f 8308 KNOF Comm 8404	8312120136 Board Notification 84-011:discusses NRC use of terms "important to safety" & "safety-rélated" EISENIUTD, De Division of Licensing 84/01/18 PALLADING Commissioners 72pp 22241:008 24X Fiche 50-000,84/01/18, 8312120136 B402010410 Generic Ltr 84-94 to all operating PWR licensess, CP holders	8402100137 Revised emergency plan implementing procedures: Procedures EPIP EOF-17 re emergency operations facility activation log. EPIP CC-12 re sus power dispatcher & EPIP EDF-12 re access control W/840203 memo & receipt fore Modre, R. D. Commonwealth Edison Co. 83/11/09 DEMICE. R. D. Commonwealth Edison Co. 83/11/09 DEMICE. S0~000, 83/11/09, 8402100137.
9402 Na ca ca HA	& applicants for CPs to safety evaluation of Mestinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Svc list enci. EIBENNUTID G Division of Licensing 84/02/01. Consolidated Edison Co. of New York, Inc. 57pp 22177 087. 24X Fiche, 50-000, 84/02/01, 8402010410.	8402130220 Rev B to Emergency Plan Implementing Projecting (C.11 Power Dispatcher "MODRE, R D Commonwealth Edison Co 83/11/09, 1139 2043 24X Fiche 50~000,83/11/09,8402130220
D1 84		8402150358 Rev 2 to Generating Station Emergency Plan Tagless Procedure EOF-12. "Access Control to Emergency Operations Facility "W/831108 its & receipt form MDORE.R D Commonwealth Edison Co 83/11/30 5// 2/24/3 Fiche.80-000.83/11/30.8402150358

- 8402040444 Forwards Rev 9 to Emergency Plan Implementing Procedure
 - CC-1. "Corporate Command Ctr Director " Recovery manager priority notification table encl MODRE.R D Commonwealth Edison Co 84/01/30 DENTON,H R Of pf Nuclear Reactor Regulation. Director 2pp 22083 129 24X Fiche 50-000,84/01/30,8402060446 Office
- --8402060464 Rev 9 to Emergency Plan Implementing Procedure CC-1.
 "Corporate Command Ctr Director." controlled copy
 MODRER D Commonwealth Edison Co 83/11/30 76pp 22083 131
 24% Fiche 50-000,84/01/30,8402060446
- B402090060 Forwards interim finding on offsite radiological emergency planning State of IL & Ogle & Winnebago Counties offsite plans acceptable XRIMM.R W Federal Emergency Management Agency 84/02/01
- plans acceptable KRIMM, R W Federal Emergency Management Agency 84/02/01 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 21pp 22157 198 24% Fiche 30-454, 84/02/01,8402490060
- 8402090204 Forwards evaluation of B31115 joint exercise of offsite radiological emergency preparedness plans State of IL & Ogle & Hinnebago Counties participated MRIMN:R W Federal Emergency Management Agency B4/02/01 JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 2pp 22163 150 24X Fiche 50-454.84/02/01. B402070204
- --8402090207 Evaluation of 831115 joint exercise of offsite radiological * Federal Emergency Management Agency 84/01/09 22163 152 24X Fiche 50-454,84/02/01,8402090204
- 8402130240 Forwards IE Emergency Preparedness Appraisal Repts 50-454/83-56 & 50-455/83-39 on 831205-16 No noncompliances noted PAPERIELLD,C J Region 3, Office of Director 84/02/03 REED.C Commonwealth Edison Co 7pp 22245 029 24X Fiche 50-454,84/02/03,8402130240
- --8402150247 IE Emergency Preparedness Appraisal Repts 50-454/B3-56 & 50-455/B3-39 on B31208-16 No noncompliances noted Major areas inspected administration of emergency preparedness program, emergency organization & training & retraining PLOBKI.T J. PHILLIPS.M P. PAPERIELLO, C. J. Region 3, Office of Director B4/02/04 63pp R2245 042 24X Fichs 50-454,84/02/03, 8402150240
- 8402280395 Revised emergency plan implementing procedure.including Rev 1 to NZP 600-A4. "OSEP Telephone Directory" * Commonwealth Edison Co 84/02/18 61pp 22404 158 24X Fiche 50-000.84/02/18.8402280395
- O Adjudicatory correspondence
- 8402060187 Forwards reinsp program rept.util 831028 preliminary reinsp rept. NRC 83118 initial response & NRC 831228 insp rept. W/o encls Related correspondence BIELAMBKI, A P Isham. Lincoln & Beale BIELAMBKI, A P Commonwealt/ Edison Co 84/01/27 ROBENTHAL, A S , COTCHY, R L , KOHL, C N Atomic Safety and Licensing Appeal Panel 2pp 22088 189. 24X Fiche 50~454,84/01/27.8402060187 Commonwealth
- 8402060182 Informs of withdrawal of D Thomas from svc list Cartificate of Svc enci Related correspondence
 LEMIS. E League of Momen Voters of Rockford, IL 84/01/27
 SMITH: I W , COLE.R F , CALLIHAN, A D Atomic Safety and Licensing
 Board Panel 2pp 22087 195 24X Fiche 50-454,84/01/29,8402060182
- B402010056 Memorandum & order adopting listed briefing schedule, subj to possible later advancement of 840330 deadline for filing of third tier briefs & authorization of reply briefs on timely motion & for good cause shown BHOEMAKER,C J Atomic Bafety and Licensing Appeal Panel 84/01/31 5pp 22042-246 24X Fiche 50~454,84/01/31,8402010056
- 8402030174 Informs that on 840127.counsel for applicant furnished ASLAS w/840112 rept on reinsp as result of Noncompliance Items 50-455/82-05-17 & 50-455/82-04-17 Document accepted as fulfillment of obligation to keep ASLAS informed BHOEMAKER, C J. Atomic Safety and Licensing Appeal Panel 84/02/02 2pg. 22067 346, 24% Fiche 50-454,84/02/02,8402030174
- B402080131 Motion to limit consideration of post-record submissions in applicant 840127 ltr Certificate of Svc encl WHICHER, J M League of Women Voters of Rockford, IL WHICHER, J M Whicher, J M 84/02/03 Atomic Safety and Licensing Appeal Panel App 22132 137 24X Fiche 50-454,84/02/03.8402080131

- 8402080195 Notifies that Board members unable to comment on matters other than through official issuances Initial decision of proceeding encl M/o encl SMITH, IN Atomic Safety and Licensing Board Panel 84/02/06 GILDY, E W Affiliation Not Assigned 1p 22130 147 24X Fiche 50-454,84/02/04,8402080195
- --B4020B019B Requests explanation for denial of OL GILDY.E W Affiliation Not Assigned 84/01/17 and Litensing Board Panel 1p 22130 148 24 Fithe 50-454,84/02/06,8402080195 Atomic Safetu
- 8402100149 Motion for increase in page limitation to file brief up to 120 pages Certificate of Svc encl STEPTOE.P B Commonwealth Edison Co STEPTOE.P B Isham, Lincoln 'Beale 84/02/06 Atomic Safety and Licensing Board Panel Spp 22182 157 24X Fiche 50-454,84/02/06,8402100149
- 8402090191 Memorandum & order granting in part.motion to appeal ASLB 840113 initial decision denying UL application Page 11mitation enlarged to 80 pages Request for refrain from review of 830809-10 transcript rejected SHDEMAKER.C J Atomic Safety and Licensing Appeal Panel 84/02/08 Commonwealth Edison Co 5pp 22163 137 24% Fiche 90-494,84/02/08,8402090151
- 8402160251 Forwards documents pertinent to ASLB 840113 initial decision Document topics include enforcement actions, reinsporgram audits & surveillances & special inspire worker allegations M/o encl MILLER, M I Isham, Lincoln & Beale MILLER, M I Communwealth Edison Co. 84/02/10 ROSENTHALAS , GOTCHY, R L , KOHL, C N / Safety and Licensing Appeal Panel Spp 22274 314 24% Fithe 50-454.84/02/10.8402160251
- 8402160222 Motion opposing ABLAB decision to deny issuance of OL Flawed legal & factual analysis leading to denial of application apparent & ovidence demonstrates that util met OA obligations MILLER, M I Commonwealth Edison Co MILLER, M I Isham, Lincoln & Beale 84/02/13 Atomic Safety and Licensing Appeal Panel BOpp 22274 335 24X Fiche 50-454,84/02/13.8402160222
- --8402160227 Motion for alternative to reopen record to receive further evidence Evidence described in encl LO George affidavit MILLER.M I Commonwealth Edison Co MILLER.M I Isham, Lincoln 5. Beale 84/02/13 Atomic Safety and Licensing Board Panel Opp 22275 090 24X Fiche 50-454,84/02/13,8402160222
- --8402160231 Affidavit of LO George re date accumulated by reinspection program final root Evaluation will clearly indicate that quality of work performed is satisfactory Certificate of Svc encl GEORGE:L O Commonwealth Edison Co 84/02/13 7pp 22275 097 24% Fiche 50-494,84/02/13,8402160222
- 8402170034 Notice of withdrawal of appearance in proceeding Certificate Of Svc encl WHICHER, J M DeKalb Area Alliance for Responsible Energy 84/02/13 3pp 22300 271 24% Fiche 50-434,84/02/13,8402170034
- B402160241 Order directing other parties to file enswers to applicant alternative motion to reopen evidentiary record at same time as briefs filed in response to applicant brief SHDEMAKER.C J Atomic Safety and Licensing Appeal Panel B4/02/14 ip 22274 332 24X Fichs 50~454.84/02/14.8402160241
- B40221011B Advises that briefing or ruling on intervenor motion to limit consideration of post-record submissions unnecessary WHICHER, J M Dusinessmen for the Public Interest WHICHER, J M DeKalb Area Alliance for Responsible Energy B4/02/15 ROSENTHAL, A B, KOPIL, C N, GOTCHY, R L. Atomic Safety and Licensing Appeal Panel ip 22317 202 24% Fiche 50~454, B4/02/15, 8402210118
- 8402210171 Memorandum informing of intention to treat intervenor motion to limit consideration of post-record submission as withdrawn withdrawn BHOEMAKER,C J Atomic Safety and Licensing Appeal Panel. B4/02/l6 1p 22314 34B 24X Fiche 50-454,84/02/16,8402210171,
- B402230104 Responds to 840215 ltr re svc of ASLAB memoranda & orders for proceeding Official svc list serves representatives.
 DW Gassell & JM Whicker
 SHOEMAKER, C J Atomic Bafety and Licensing Appeal Panel B4/02/22
 JDHNSDN, B League of Momen Voters of Rockford, IL 2pp. 22362 136
 24X Fiche 50-454,84/02/22,8402230104
- ---B402230107 Requests to correct omission from ABLAB syc list JOHNSON, B. League of Women Voters of Rockford, IL. B4/0 BHDEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 22362 138 24X Fiche 50-434,084/02/22,8402230104 84/02/15

- B4022B0471 Submits corrigenda to 840213 brief Certificate of Svc encl BECKER.B D Isham, Lincoln & Beale BECKER.B D Communealth Edison Co 8402/22 ROSENTHAL.A S , GOTCHY.R L , KCHL.C N Atomi: Safety and Licensing Appeal Panel 4pp 22404 353 24X Fiche 50~454.84/02/22.8402280471
- 8402290073 Memorandum forwarding Judge Rosskowski of Northern District of State of IL 840222 order re in camera presentations SMITH I W Atomic Safety and Licensing Board Panel 84/02/27 Office of the Erecutive Legal Director 14pp 22421 074 24X Fiche 50-454,84/02/27.8402290073

I Financial information

- 8402280410 Annual Financial Rept 1983 W/840221 ltr O'CONNOR, J J Commonwealth Edison Co 83/12/31 29pp 22407 101 24X Fiche 50-000,83/12/31,8402280410
- O Inspection reports IE Bulletins & correspondence
- B.312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps "Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) B6/01/25 Consolidated Edison Co of New York
- 8402080275 Forwards IE Insp Repts 50-454/84-01 & 50-455/84-01 on 840110-12 & 13 No moncompliance noted PAPERIELLO, C J. Region 3. Office of Director 84/01/27 REED, C Commonwealth Edison Co. 2pp 22131 294 24X Fiche 50-454,84/01/27. R802080275
- --8402080280 IE Insp Repts 50-454/84-01 & 50-455/84-01 on 840110-12 & 13 No nancompliance noted Major areas inspected preoperational radiological environ monitoring program, including implementation & results, 8A & mgt controls GESTMANN.M J. SCAMINSKI.M J. SCHUMACKER.M Region 3, Office of Director 84/01/27 Bpp 22131 296 24X Fiche 50-454,84/01/27,8402080275
 - 02080323 Forwards IE Insp Repts 50-454/84-02 & 50-455/84-02 on 830802-840118 No noncompliance noted KNDP, R C Region 3, Diffice of Director 84/01/30 REED, C Commonwealth Edison Co 2pp 22130 297 24X Fiche 50-454,84/01/30,
- -8402080326 IE Insp Repts 50-454/84-02 % 50-455/84-02 on 830802-840118
 No noncompliance noted Major areas inspected allegations reconst activities & summary of 831122 Region III insp
 concerning util reinsp program
 HAYES,D W. CONNAUGHTON,K., KNOP,R C. Region 3, Office of
 Director 84/01/28 20pp 22130 299 24X Fiche 50-454,84/01/30,8402080323
- 8402080395 Deficiency Rept B3-14 re cable grip installation Initially reported on 831229 Also updates info re noncompliance noted in IE Insp Repts 50-45483-49 & 50-455/83-35 Personnel retrained on proper cable grip installation IRAMM.T R Commonwealth Edison Co B4/01/31 KEPPLER.J G Region 3. Office of Director 2pp 22130 360 24% Fiche 50-454.84/01/31, 8402080395
 - 22150364 Forwards IE Insp Repts 50-454/83-58 & 50-455/83-43 on 331208-840120 & notice of violation STREETER.J F Region 3, Defice of Director 84/01/31 REED, C Commonwealth Edison Co 2pp 22241 336 24X Fichs 50-454.84/01/31.
 - 3402130382 IE Insp Repts 50-454/83-58 & 50-455/83-43 on 831208-840120 Noncompliance noted while conducting Step 7 & 9 of RP-68 12, "Reactor Protection Logic Checks." recorded voltage fell outside specified range & no defliciency written RING, M., VANDENBURGH, C., WILLIAMS, D. Region 3, Office of Director 84/01/30 8pp 22241 340 24X Fiche 50-454,84/01/31,8402180344
 - 7150350 Forwards IE insp Repts 30-454/83-52 & 50-455/83-37 on 31110 & 1208 No noncompliance noted TILE, W S Region 3, Office of Director B4/02/02 REED. C wamanwealth Edison Co 2pp 22250 254 24X Fiche. 50-494, 84/02/02. 02150380
 - 402150353 IE Insp Repts 50-454/83-52 & 50-455/83-37 on 831110 & 1208 No noncompliance noted Major areas inspected previous insp findings MENDEZ.R , WILLIAMS.C Region 3, Office of Director 84/02/02 4pp 22250 256 24X Fiche 50-434.84/02/02,8402150350

- B40il90016 IE Info Notice B4-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000, 84/02/03, 8401190016
- B401190017 IE Bulletin B4-01, "Cracks in BWR Mark I Containment Vent Headers" Svc list encl DEYQUNO.R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York. Inc 102pp 22177
- 8402130240 Forwards IE Emergency Preparedness Appraisal Repts 50-454/83-56 & 50-455/83-39 on 831205-16 No noncompliances noted PAPERIELLO, C J. Region 3, Office of Director 84/02/03 REED, C Commonwealth Edison Co. 7pp. 22245 029 24X Fiche 50-454,84/02/03,8402180240
- ---8402150247 IE Emergency Preparedness Appraisal Repts 50-454/83-56 & 50-455/83-39 on 831205-16 No noncompliances noted Major areas inspected administration of emergency preparedness program, emergency organization & training & retraining PLOSKI, T J , GLOERSEN, W P , CHRISTOFFER, Ø Region 3, Office of Director 84/02/04 63pp 22245 042 24X Fiche 50-454,84/02/03,8402150240
- B402220584 Forwards IE Insp Repts 50-454/84-08 & 50-455/84-04 on B40117.19 & 20 No noncompliance noted LITTLE,W S Region 3. Office of Director B4/02/06 REED,C Commonwealth Edison Co 2pp 22331 346 24X Fiche 50-454,B4/02/06,B402220584
- --8402220592 IE Insp Repts 50-454/84-08 & 50-455/84-06 on 840117,19 & 20 No noncompliance or deviations noted Major areas inspected followup on previously identified items re Bargent & Lundy internal technical OA audit YIN,1 T, DANIELSON,D H Region 3, Office of Director 84/02/06 5pp 22331 348 24X Fiche 50-454,84/02/06,8402220884
- B402170134 Forwards response to IE Bulletin 79-21. "Temp Effects on Level Measurements " Analysis of adequacy of steam generator low level setpoints and BARNES: L. Commonwealth Edison Co. B4/02/09 KEPPLER.J. G. Regtor 3. Office of Director. Bpp. 22299 339 24X Fiche 50-000, 84/02/09, B402170134
- 8402270089 Forwards IE Insp Repts 50-454/84-05 & 50-455/84-04 on B40117-20 No noncompliance noted LITTLE.W S Region 3. Office of Director 84/02/09 REED.C Commonwealth Edison Co 2pp 22388 174 24% Fiche 50-454.84/02/09, 8402270089
- --B402270095 IE Insp Repts 50-454/84-05 & 50-455/84-04 on 840117-20 No noncompliance or deviations identified Major areas inspected allegations, licensee actions on previous inspected dilegations, licensee actions on previous inspected dilegations, licensee actions on previous inspected dilegations, licensee actions of previous inspected findings & IE bulletins & 10CFR50, 55(e) items WARD, N D & ENGP L L D'DWYER, G F Region 3, Office of Director 84/02/08 15pp 22388 176 24X Fiche 50-454,84/02/09,8402270089
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R)" Svc list enc!

 JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of Man York, Inc 124pp 22365 259 24X Fiche: 50-000, 84/02/13, 8401193041
- 8402170278 Informs that special task force will resxamine BALP 3 ratings, per raview of util 830712 response Final BALP 3 repts & assessments will be issued by 840320 Delay in review caused by higher priority efforts
 KEPPLER, J 9 Region 3, Office of Director 84/02/13 REED, C Commonwealth Edison Co 2pp 22296 146 24X Fiche 50-000, 84/02/13-8402170278
- 8401190039 IE Info Notice 84-08, "IOCFR50 7, 'Employee Protection '"
 Svc list encl
 JORDAN,E i. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- B402270130 Forwards IE Insp Repts 50-454/B4-06 & 50-455/B4-05 on B4011B-20 & 24-26 No noncompliance noted LITHELY S Region 3, Office of Director 84/02/14 REED, C. Commonwealth Edison Co .2pp 22426 155 24X Fiche 50-454,84/02/14.
- --B402290135 IE Insp Repts 50-454/84-06 & 50-455/84-05 on 840118-20 & 24-26 No noncompliance noted Major areas inspected, revised procedures & instructions, insp personnel records, welder requalifications & exam of installed HVAC equipment KEY, W. J. DANIELSON, D. H. Region 3, Office of Director, 84/02/13 13pp 22426 157 24X Fiche 50-454.84/02/14,8402290130

- 8401190045 IE Info Notice B3-63.Suppl 1. "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/15 Consolidated Edison Co of New York, Inc 118pp 22366 142 24% Fiche 50-000.84/02/15.8401190045
- 8401190062 IE Info Notice 84~10. "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 30-000.84/02/21,8401190062
- B402270433 Ack receipt of 821213 ltr informing NRC of steps taken to correct violetions noted in IE Insp Repts 50-454/82-17 & 50-455/82-14 No basis found to withdraw Violations i & 2 Request denied
 LITLE, W S Region 3. Office of Director 84/02/22 REED, C Commonwealth Edison Co 2pp 22389 346 24X Fiche 50-454,84/02/22.8402270433
- --8402270442 Responds to NRC 821112 ltr re violations noted in IE Insp Repts 30-454/82-19 & 50-455/82-14 Corrective actions affected receways will be redesigned if mod unacceptable Requests withdrawal of Violations 1 & 2 DELOEORGE, L O Commonwealth Edison Co B2/12/13 KEPPLER, J G Region 3, Office of Director App 22389 348 24X Fiche 30-454,84/02/22,8402270433
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies"
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12. "Failure of Soft Seat Valve Seals "
 Svc list and
 JDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060 24X Fichs 50-000,84/02/27,8401190067
- 8 Reportable occurrences, LERs & related correspondence
- 8402170317 Supplemental Part 21 rept re radiographic record evaluations supplying add1 data to 830624 submittal Records show that 90 degree branch connections furnished to North Anna 1 & 2 jobsites No noizles supplied to Zimmer Related info encl BORNES, R P Southwest Fabricating & Welding Co (subs of IU International Corp) 83/10/04 POTAPUVS, U Region 4. Office of Director 6pp 22276 156 24X Fiche 30-000,83/10/04,8402170317
- 8402170196 Final Part 21 rept re potential problem concerning radiography of branch connection welds covered by reinforcing pads Welds at Byron, Braidwood & North Anna acceptable Weld 7 at Clinton reradiographed BORNES, R P Southwest Fabricating & Welding Co (subs of IV International Corp) 84/01/02 POTAPUS, U Region 4, Office of Birector. 2pp 22296 126 24X Fiche 50-000, 84/01/02,8402170196
- B402070365 Part 21 rept re linear converter device w/possible generic defect. Initially reported on 840116 Written notifications issued Customer responses should be received by 840331 Final rept will be submitted by 840430 DDBSDN.JP Pacific Air Products Co 84/01/30 Director's Office, Office of Inspection and Enforcement 2pp 22114 277 24X Fiche 50-280.84/01/30.8402070365
- --B402070373 Part 21 rept re linear converter device w/possible generic defect Initially reported on 840116 Preliminary analysis indicates excessive wear of brass shaft guides Next rept will be submitted within 90 days Supporting info encl DODSEN. J P Pacific Air Products Co 84/01/17 POTAPOVE, U Region 4. Office of Director 68pp 22114 301 24x Fiche: 50-000, 84/01/30, 8402070365
- 8402080395 Deficiency Rept 83-14 re cable grip installation. Initially reported on 831229 Also updates info re noncompliance noted in 1E Inter Repts 50-454/83-49 & 50-455/83-35 Personnel retrained on proper cable grip installation TRAMM.TR Commonwealth Edison Co 84/01/31 KEPPLER, J Q Region 3, Office of Director 2pp 22130 360 24X Fiche 50-454,84/01/31,8402080395
- T Hearing transcripts on non-antitrust matters
- B306010017 Transcript of 830525 hearing in Rockford, IL Pp 4, 952-7,011. * Atomic Safety and Licensing Board Panel 83/05/25 40pp 18465:131. 24X Fiche 50-454.83/05/25,8306010017

- U Congressional/Executive Correspondence
- 8402240277 Responds to FDIA request for three categories of documents re facilities Forwards App A Documents 1-4 Documents 5-9 provided previously via svc list FELTON. J M Division of Rules and Records 84/01/27 SUGARMAN. R J Sugarman & Denworth 2pp 22394 298 24X Fishe 50-000.84/01/27.
- --8308070022 Forwards second quarterly status rept for 1983 on actions taken re operating reactors & licensing reviews of new facilities
 ABSELSTINE, J. K. Commissioners 83/07/21 BEVILL, T. House of Rep. Appropriations 11pp 22394 300 24X Fiche 50-000. 84/01/27.840224027
- DOCKET STN-50-456 DRAIDWOOD STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B402220134 Responds to request for addl info re LK Comstock site activities & plans for improving performance as discussed at B31104 exit meeting at site WALLACE.M J Commonwealth Edison Co 83/11/17 SPESSARD.R L Division of Emergency Proparedness & Operational Support 2pp 22339 241 24x Fiche 50-456.83/11/17.8402220134
- B402010410 Generic Ltr 84-04 to all operating PWR licensees.CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/ellmination of postulated pipe breaks in FWR primary main loops Svc list encl EISENHUT, D 0 Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc. 59pp 22177 0B7 24X Fiche 50-000,84/02/01.8402010410
- 8402090347 Notifies that safety-related activities in design, engineering & const suspended & project activities concentrated in records retention & maint of matls & aquipment due to financial inability to finish const SHIELDS, SW Public Service Co of Indiana, Inc. 84/02/06 DENTON, HR Defice of Nuclear Reactor Regulation, Director 17pp 22159 177 24X Fiche 50-456,84/02/06,8402090349
- 8408210450 Ack receipt of 840106 addendum to petition for emergency relief citing 830707 FOIA request for all documentation re integrated leak rate testing at LaSalle & Byron Ltr being treated as supplemental FOIA request Meeting summary encl DENTON.H R Office of Nuclear Reactor Regulation, Director 84/02/09 0000LE M Affiliation Not Assigned 1p 22344 014 24X Fiche 50-000,84/02/09.8402210450
- B402240120 Forwards supplemental info to resolve NUREC-0612, "Control of Heavy Loads" Info also addresses concerns in Phases 1 & 2 of draft technical evaluation rept W/51 oversize drawings Aperture cards are in PDR BARNES, P. L. Commonwealth Edison Co. B4/02/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 27pp 22374 289 24X Fiche 50-000,84/02/10.8402240120
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8402010257 Forwards, for review & comment. DES. (NUREG-1026) & FR notice of evailability Comments due within 45 days after FR publication W/o DES YOUNGBLOOD. B J Licensing Branch i 84/01/16 WOOD. J M Commerce. Dept of. Natl Ceeaugraphic & Atmospheric Administration ip 82047 RB4 24X Fiche 50-456,64/01/16.8402010257
- --8402010260 Notice of availability of DES (NURE9-1026) YOUNOBLOOD, B J Licensing Branch 1 84/01/13 2pp 22047 285 24X Fiche 50-456-84/01/16.8402010257
- 8402010310 Forwards DES, (NUREG-1026) & FR notice of availability W/o DES YOUNGBLOOD, B J Licensing Branch 1 84/01/16 Illinois, State of 1p 22057 226 24X Fiche 50-456,84/01/16,8402010310
- 8402010465 Forwards DES (NUREO-1026) & FR notice of availability W/o DEB YOUNGBLODD, B. J. Licensing Branch 1 84/01/16 FARRAR, D. L. Commonwealth Edison Co. 1p 22057 314 24X Fiche 50-456,84/01/16, 8402010465
- 8402020196 Offers no comments on DES DAVIS.V W Agriculture, Dept of 84/01/27 YOUNGBLODD, B J Licensing Branch I ip 22057 155 24X Fiche 50-456.84/01/27, 8402020196

- 8402020160 Ack receipt of DES on 840116 Advises that 45-day comment period on DES should be extended until 840312
 HIRSCH.A Environmental Protection Agency 84/01/30
 YUUN08L000, B J Office of Nuclear Reactor Regulation. Director 1p
 22036 149 24% Fiche 50-456.84/01/30.8402020160
- 8402130222 Offers no comments on review of data for DES is operations of facilities

 ECKES.J J Agriculture. Dept of 84/02/04 YOUNGBLOOD.B J

 Licensing Branch I ip 22200 107 24X Fiche 50~456.84/02/06.

 B402130222
- 8402290362 Forwards corrected FR notice extending 45-day comment period on BE8 (NURSC-1026) to 840312 due to delay of delivery on B40113

 VOUNGBLOOD B J Licensing Branch t B4702/17 PERRIN, 8
 Environmental Protection Agency 1p 2243B 245 24X
 Fiche 80-456.84702/17.8402290362
- --8402290366 Corrected notice of availability extending comment period on DES (NUREC-1026) to 840332 YOUN9BLOOD, D J Licensing Granch 1 84/02/15 8pp 22438 246 24X Fiche 50-456,84/02/17,8408290362
- 8402270081 Forwards comments on DES WABHINGTON D.L. Illinois, State of 84/02/22 STEVENS J.A. Division of Licensing 4pp 22371 313 24% Fiche 50-456,84/02/22, BADD270081
- E NRC Safety Evaluation Report (SER), supple & correspondence
- B402280240 Forwards ODC 51 compliance review re RCP8 components & certified matl test repts for components Info should resolve SER Outstanding Item 4 SHARTZ.E D Commonwealth Edison Co 84/02/22 DENTON.H R Office of Nuclear Reactor Regulation. Director 7pp 22399 262 24X Fiche 50-000.84/02/22.8402280240
- F Security, medical, emergency & fire protection plans
- 8402130191 Rev O to Emergency Plan Implementing Procedure EOF-17. "Emergency Operations Facility Activation Facility Log "
 BERLIN.H D Commonwealth Edison Co 83/09/23 3pp 22179 283
 24X Fiche 50-000.83/09/23.8402130191
- 8402130215 Rev O to Emergency Plan Implementing Procedure EOF-18, "Nuclear Station Div Non-Edison Transportation Incident Assistance Procedure "

 * Commonwealth Edison Co 83/09/29 5pp 22204 078 24X Fiche 50-000.83/09/27.8402130215
- 8402100137 Revised emergency plan implementing procedures including Procedures EPIP EDF-17 re emergency operations facility activation log.EPIP CC-12 re sys power dispatcher & EPIP EOF-12 re access control W/840203 memo & receipt form MOORE.R D Commonwealth Edison Co 83/11/09 DENTON, H R NRC No Detailed Affiliation Given 24pp 22181 280 24% Fiche 50-000.83/11/09,8402100137
 - O2130220 Rev 8 to Emergency Plan Implementing Procedure CC-12, "Sys Power Dispatchor" MODRE, R D Commonwealth Edison Co 83/11/09 (1pp 22200:108 24X Fichs 50-000, 83/11/09, 8402130220
- J402150358 Rev 2 to Generating Station Emergency Plan Implementing Procedure EDF-12, "Access Control to Emergency Operations Factility " W/831108 Itr & receipt Form MODRER D Commonwealth Edison Co 83/11/30 5pp 22242 358 24X Fiche 50-000.83/11/30,8402150358
- I Financial information
- B402280410 Annual Financial Rept 1983 H/840221 1tr D'CONNOR.J J Commonwealth Edison Co 63/12/31 29pp 22407 101 24X Fiche 50-000.63/12/31.8402280410
- Inspection reports, IE Bulletins & correspondence
- 3312120153 IE Info Notice 84-06, "Steam Dinding of Auxiliary Feedwater Pumps " Svc list entl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche: 50-000.84/01/25, 8312120153.

- 8402100207 Forwards IE Insp Repts 50-456/83-18 & 50-457/83-17 on B31031-840113 & notice of violation Requests response retorquing requirements for mounting electrical equipment & schedule for closeout of insp & nonconformance repts SPESBARD. R L Division of Emergency Proparedness & Operational Support 84/01/27 REED. C Commonwealth Edison Co 2pp 22178 031 24X Fiche 50-456,84/01/27,8402100207
- ---8402100211 Notice of violation from insp on 831031-840113 SPESBARD.R L Division of Emergency Proparedness & Operational Support 84/01/27 3pp 22178 033 24X Fiche 50-456.84/01/27, a
- --8402100215 IE Insp Repts 50-456/83-18 & 50-457/83-17 on 831031-840113 Noncompliance noted failure to assure that activities affecting quality prescribed by procedures instructions or drawings LOVE, R S , MENDEZ, R , OAUTAM, A S Region 3, Office of Director 84/01/27 27pp 22178 036 24X Fiche 50-456.84/01/27, 8402100207
- B401190016 IE Info Notice B4-07. "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list entl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/02/03 Consolidated Edison Co of New York, Inc 117pp 22114 179 24X Fiche 50-000, 84/02/03, 8401190016
- B401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Isaders" Bvc list encl DEYOUNG, R C Director's Office Office of Inspection and Enforcement B4/02/03 Consolidated Edison Co. of New York, Inc 102pp 22177 156 24X Fiche 50-000,84/02/03,8401190017
- 8402170155 Forwards IC Insp Repts 50-456/83-17 % 50-457/83-16 on 831003-1216 % notice of violation KNOP, C Region 3, Office of Director 84/02/03 REED, C Commonwealth Edison Co 2pp 22296 093 24X Fiche 50-456,84/02/03,8400170135
- --8402170160 Notice of violation from insp on 831003-1216 KNOP.R C Region 3, Office of Director 84/02/03 5pp 22276 095 24X Fiche 50-456,84/02/03.8402170155
- --B402170164 IE Insp Repts 50-456/83-17 & 50-457/83-16 on B31003-12[6 Noncompliance noted failure to provide adequate GA program for safety-related equipment MCGREGURL 0 , MAYES, D W Region 3, Office of Director B4/02/01
- 8402170134 Forwards response to IE Bulletin 79-21. "Temp Effects on Lovel Measurements " Analysis of adequacy of steam generator low level setpoints encl BARNES.P.L. Commonwealth Edison Co. 84/02/09 KEPPLER.J G Region 3. Office of Director Spp. 22299 339 RAX Fiche 50-000.84/02/09. 8402170134
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R)" Syc list encl.

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc. 124pp 22365 259 24X Fiche 50-000,84/02/13,8401190041
- 8402170278 Informs that special task force will reexamine SALP 3 ratings,per review of util 930712 response Final BALP 3 repts & assessments will be insued by 840320, Delay in review caused by higher priority efforts
 KEPPLER, J G Region 3, Office of Director 84/02/13 REED, C Commonwealth Edison Co 2pp. 22276 146 24X Fiche 50-000, 84/02/13.
- 8401190099 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection."

 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp. 22365 141 24X Fiche 30-000,84/02/14,8401190039
- B401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Westinghouse Type BA-1 Differential Relays " Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366 142 24X Fiche 50-000, 84/02/15, 8401190045
- 8402220140 Forwards revised Page 3 of app to NRC 840127 ltr transmitting IE Imag Repts 50-456/83-18 & 50-457/83-17 SPESBARD.R L. Division of Emergency Preparedness & Operational Support 84/02/16 REED.C. Commonwealth Edison Co 2pp 22337-270 24X Fiche 50-456,84/02/16,8402220140.

- B402290240 Forwards IE Insp Repts 50-456/84-01 & 50-457/84-01 on 840208-10 No noncompliance identified LITTLE.W S Region 3. Office of Director 84/02/16 REED.C Commanwealth Edison Co 2pp 22427 317 24X Fiche 50-456.84/02/16. 8402270240
- --8402270247 IE Insp Repts 50-456/84-01 & 50-457/84-01 on 840208-10 No noncompliance or deviations identified Major areas inspected preservice insp.licensee action on IE bulletins, review of quality records & observation of welding WARD, K D . DANIELSON, D H Region 3. Office of Director 84/02/16 7pp 22427 317 24X Fiche 50-456/84/02/16/8402270240
- 8401190062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000.84/02/21.8401190062
- 8401170066 IE Info Notice 84-ii. "Training Program Deficiencies "
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24% Fiche 50-000,84/02/24,8401170066
- 8402280005 Confirms 840307 enforcement conference at Region III ofc to discuss insp findings in areas of piping, electrical & HVAC installations, per 840215 discussion NCRELIUS.C E Division of Project & Resident Programs 84/02/24 REED.C Commonwealth Edison Co 1p 22402 110 24X Fiche 50-454,84/02/24,8402280005
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/27 Consolidated Edison Co of New York, Inc. 120pp \$2431 060 24X Fichs 50-000,84/02/27,8401190067

8 Reportable occurrences. LERs & related correspondence

- 8402170317 Supplemental Part 21 rept re radiographic record evaluation, supplying addl data to 830624 submittal Records show that 90 degree branch connections furnished to North Anna 1 & 2 jobsites No norrles supplied to Zimmer Related info encl BORNES, P Southwest Fabricating & Welding Co (subs of IU International Corp) 83/10/04 PDTAPOVS, U Region 4, Office of Director App 22276 156 24% Fiche 50-000,83/10/04,8402170317
- 8402170196 Final Part 21 rept repotential problem concerning radiography of branch connection welds covered by reinforcing pads Welds at Byron Braidwood & North Anna acceptable Weld 7 at Clinton reradiographed BURNES, R P Southwest Fabricating & Welding Co (subs of IU International Corp) 84/01/02 POTAPUS, U Region 4, Office of Birector 2pp 22296 126 24% Fiche 50-000,84/01/02,8402170196
- 8402070365 Part 21 rept re linear converter device w/possible generic defect Initially reported on 840116 Written notifications issued Customer responses should be received by 840331 Final rept will be submitted by 840430 DDSDN, J P Pacific Air Products Co 84/01/30 Director's Office, Office of Inspection and Enforcement 2pp 22114 299 24X Fichs 50-280.84/01/30.8402070365
- --8402070373 Part 21 rept re linear converter device w/possible generic defect Initially reported on 840116 Preliminary analysis indicates excessive wear of brass shaft guides Next rept will be submitted within 90 days Supporting info encl DGBSON. J P Pacific Air Products Co 84/01/17 POTAPOVS.U Region 4, Defice of Director 68pp. 22114 301 24X Fiche 50-000,84/01/30,8402070365

T Hearing transcripts on non-antitrust matters

- 8402270302 Partial response to FOIA request for five categories of documents re mothballed nuclear const projects App A documents being placed in FDR. Document as listed on App B aiready available in FDR Search continuing FELTON, J M Division of Rules and Records 84/01/20. BELL, N Nuclear Information & Resource Service 3pp 22375, 200 24% Fiche: 50-000.84/01/20,8402270302
- ---B402270321 Testimony of JB Martin before Subcommittee on Energy Conservation & Power re nuclear power plants being constructed by WPPSS Related info encl MARTIN.J B Region 5. Office of Director. 83/09/14 86pp. 22395:104. 24X Fiche 50-000.84/01/20.8402270302

- DOCKET STN-50-457 BRAIDWOOD STATION: UNIT 2
- A Application/construction stage documents & correspondence
- 8402220134 Responds to request for add1 info re LK Comstock site activities & plans for improving performance, as discussed at 831104 exit meeting at site WALLACE, M J Commonwealth Edison Co 83/11/17 SPE65ARD, R L Division of Emergency Preparedness & Operational Support 2pp 22339 241 248 Fiche 80-450-83/11/17.090220134
- 8402010410 Generic Ltr 84-04 to all operating PMR licensees, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PMR primary main loops Svc list encl EISENHUT, D 9 Division of Licensing 84/02/01 Consolidated Edison Ca of New York, Inc. 59pp 22177 087 24X Fiche 50-000,84/02/01,8402010410
- 8402090349 Notifies that safety-related activities in design engineering & const 5uspended & project activities concentrated in records retention & maint of maths & equipment, due to financial inability to finish const SHIELDS, SW Public Service Co of Indiana, Inc. 84/02/06 DENTON, HR Office of Nuclear Reactor Repulation, Director 17pp 22159 177 24X Fiche 50~436,84/02/06.8402090349
- 8402240120 Forwards supplemental info to resolve NUREO-0612. "Control of Heavy Loads" Info also addresses concerns in Phases 1 & 2 of draft technical evaluation rept W/51 oversize drawings Aperture cards are in PDR BARNES.P L Commonwealth Edison Co 84/02/10 DENTON.H R Office of Nuclear Reactor Regulation, Director 27pp 22374 287 24X Fiche 50-000.84/02/10.8402240120
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8402010257 Forwards, for review & comment.DES.(NUREO-1026) & FR notice of availability Comments due within 45 days after FR publication W/o DES YOUNGHLOOD, B J Licensing Branch I B4/01/16 WODD, J M Commerce. Dapt of, Natl Greanographic & Atmospheric Administration 1p 22047 284 24X Fiche 50-456,84/01/16,8402010257
- --8402010260 Notice of availability of DEB (NUREQ-1026)
 YOUNGBLOOD,B J Licensing Branch | 84/01/13 2pp 22047-285
 24X Fiche 50-454,84/01/16,8402010257
- 8402010310 Forwards DES.(NUREG-1026) & FR notice of availability W/o DES
 YOUN9BLOOD,B J .i.censing Branch 1 84/01/16 filinois, State of 1p 22039 224 24% Fiche 30-456,84/01/16,8402010310
- 8402010465 Forwards DEB (NUREG-1026) & FR notice of availability W/o DEB YOUNGBLOOD, B J Licensing Branch 1 84/01/16 FARRAR, D L Commonwealth Edison Co 1p 22059 314 24X Fiche 50-456,84/01/16, 8402010465
- 8402020194 Offers no comments on DE9
 DAVIS, V W Agriculture, Dept of 84/01/27 YOUNGBLOOD, B J
 Licensing Branch 1 ip 22057 155 24% Fiche 50-456,84/01/27,8402020196
- 8402020160 Ack receipt of DES on 840116 Advises that 45-day comment period on DES should be extended until 840312 HIRECHA Environmental Protection Agency 84/01/30 YOUNGELOOD, B J Office of Nuclear Reactor Regulation, Director 1p 22056-147 24X Fiche 50-456,84/01/30.8402020160
- 8402130222 Offers no comments on review of data for DES re operations of facilities

 ECKES, J Agriculture, Dept of 84/02/06 YOUNOBLOOD, B J

 Licensing Branch 1 1p, 22200 107 24X Fiche 50~494, 84/02/06, 8402130222
- 8402270362 Forwards corrected FR notice extending 45-day comment period on DES (NUREG-1026) to 840312 due to delay of delivery on 840113 YOUNOBLOOD, B J Licensing Branch 1 84/02/17, PERRIN, S Environmental Protection Agency 1p 22438 245 24X Fiche: 50-456, 84/02/17, 8402270362
- --8402270366 Corrected notice of availability extending comment period on DES (NUREG-1026) to 840312 YUUNDBLOOD,B.J Licensing Branch i 84/02/15 8pp. 22438 246 24X Fiche 50-456,84/02/17,8402270362

- 8402270081 Forwards comments on DES
 WASHINGTON, D.L. Illinois, State of 84/02/22 STEVENS, J.A.
 Division of Licensing 4pp 22391 313 24x Fiche 50-456,84/02/22,
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8402280240 Forwards GDC 51 compliance review re RCPB components & certified mat1 test repts for components Info should resolve SER Outstanding Item 4
 SHARTZ, ED Commonwealth Edison Co 84/02/22 DENTON.HR Defice of Nuclear Reactor Regulation, Director 7ps 22399 262 24X
 Fiche 50-000.84/02/22.8402280240
- F Security, medical, emergency & fire protection plans
- 8402130191 Rev O to Emergency Plan Implementing Procedure EDF-17, "Emergency Operations Facility Activation Facility Log " BERLIN, N D Commonwealth Edison Co 83/09/23 Jpp 22199 283 24X Fiche 50-000,83/09/23,8402130191
- 8402130215 Rev O to Emergency Plan Implementing Procedure EOF-1B, "Nuclear Station Div Non-Edison Transportation Incident Assistance Procedure " * Commonwealth Edison Co 83/09/27 Spp 22204 078 24X Fiche 50-000.83/09/27.8402130215
- 8402100137 Revised emergency plan implementing procedures, including Procedures EPIP EOF-17 re emergency operations facility activation log, EPIP CC-12 re sqs power dispatcher & EPIP EOF-12 re access control W/840203 memo & receipt form MODRE, RD Commonwealth Edison Co. 83/11/09 DENTON, HR NRC Na Detailed Affiliation Given 24pp 22181 288 24X Fishe 50-000.83/11/09.8402100137
- 8402130220 Rev B to Emergency Plan Implementing Procedure CC-12. "Sys Power Dispatcher" MOURE R D Commonwealth Edison Co 83/11/09 11pp 22200 108 24X Fiche 50-000.83/11/09.8402130220
- 8402150358 Rev 2 to Generating Station Emergency Plan Implementing Procedure EOF-12. "Access Control to Emergency Operations Facility "W/831108 ltr & receipt form MOORE, R D Commonwealth Edison Co 83/11/30 5pp 22242 358 24% Fiche 50-000.83/11/30.8402150358
- I Financial information
- 8402280410 Annual Financial Rept 1983 W/840221 ltr C/CONNOR,J J Commonwealth Edison Co 83/12/31 29pp 22407:101 24% Fiche 50-000/83/12/31,8402280410
- Q Inspection reports, IE Bulletins & correspondence
- 8312120183 IE Info Notice 84-06. "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24% Fithe 50-000,84/01/25.8312120153
- 8402100207 Forwards IE Insp Repts 50-456/83-18 & 50-457/83-17 on 831031-840113 & notice of violation Requests response retorquing requirements for mounting electrical equipment & schedule for classout of insp & nonconformance repts SPESBARD.R L Division of Emergency Preparedness & Operational Support 84/01/27 REED, C Commonwealth Edison Co 2pp 22178 031 24X Fiche 50-456,84/01/27,8402100207
- --8402100211 Notice of violation from insp on 831031-840113 SPESSARD.R L Division of Emergency Preparedness & Operational Support 84/01/27 3pp 22178 033 24X Fiche 50-456, 84/01/27, 8402100207
- --B402100215 lE Insp Repts 50-456/83-18 & 50-457/83-17 on B31031-840113
 Noncompliance noted failure to assure that activities
 affecting quality prescribed by procedures instructions or
 drawings
 LUVE, R 8 : MENDEZ, R , GAUTAM, A S Region 3, Office of Director
 84/01/27 29pp 22178 036 24X Fiche 50-456,84/01/27,8408100207
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X fiche 50-000,84/02/03,8401190016

- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Meaders " Svc list encl DEYGUND.R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177
- 8402170155 Forwards IE Insp Repts 50-456/83-17 & 50-457/83-16 on 831003-1216 & notice of violation KNDP:R C Region 3, Office of Director 84/02/03 REED, C Cammonwealth Edison Co 2pp 22296 093 24X Fiche 50-456,84/02/03.
- --8402170160 Notice of violation from insp on 831003-1216, KNDP.R C Region 3. Office of Director 84/02/03 5pp 22296 095 24X Fiche 50-456.84/02/03.8402170155
- --8402170164 IE Insp Repts 50-456/83-17 & 50-457/83-16 on 831003-1216 Nancompliance noted failure to provide adequate GA program for safety-related equipment MCGREGOR. E G. HAYES, D W Region 3. Office of Director 84/02/03
- B402170134 Forwards response to IE Bulletin 79-21, "Temp Effects on Level Measurements" Analysis of adequacy of steam generator low level setpoints encl
 BARNES, P. L. Commonwealth Edison Co. B4/02/09 KEPPLER, J. C. Rugie:
 3, Office of Director Spp. 22299 339 24X Fichs 50-000, 84/02/09, 8402170134
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (100FR50, App R) " Syc list ent! JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/02/13 Consolidated Edison Cu of New York, Inc 124pp 22343 259 24X Fiche 50-000.84/02/13,8401190041
- 8402170278 Informs that special task force will reexamine BALP 3 ratings, per review of util 830712 response Final 8ALP 3 repts & assessments will be issued by 840320 Delay in review caused by higher priority efforts
 KEPPLER, J G Region 3, Office of Director 84/02/13 REED. C Commonwealth Edison Co 2pp 22276 146 24X Fiche 50-000, 84/02/13.
- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '"
 Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc 118pp 22366 142 24X Fiche 50-000,84/02/15,8401190045
- B402220140 Forwards revised Page 3 of app to NRC 840127 ltr transmitting IE Insp Repts 50-454/83-18 & 50-457/83-17 BFESSARD.R.L. Division of Emergency Preparathesa & Operational Support 84/02/16, REED.C Commonwealth Edison Co 2pp 22337 270 24X Fiche 50-456,84/02/16,8402220140
- 8402290240 Forwards IE Insp Repts 50-456/84-01 & 50-457/84-01 on 840208-10 No noncompliance identified LITTLE.W S Region G. Office of Director 84/02/16 REED, C Commonwealth Edison Co 2pp 22427 317 24X Fiche 50-456.84/02/16. 8402290240
- --8402290249 IE Insp Repts 50-456/84-01 & 50-457/84-01 on 840208-10 No noncompliance or deviations identified Major areas inspected preservice insp.licenses action on IE bulletins, review of quality records & observation of welding WARD, K D. DANIELSON.D H Region 3, Office of Director 84/02/16 7pp. 22427 319 24X Fiche 50-456,84/02/16,8402290240
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024, 24X Fiche 50-000.84/02/21.8401190062
- 8401170056 IE Info Notice 84-11, "Training Program Deficiencies "
 Svc list encl
 JORDAN E.L Division of Emergency Preparedness & Engineering
 Response (Post 830103) . 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,8401170066

- 84022B0005 Confirms 840307 enforcement conference at Region III ofc to discuss insp findings in areas of piping, electrical & HVAC installations, per 840215 discussion NORELIUS, C E Division of Project & Resident Programs 84/02/24 REED, C Commonwealth Edison Co ip 22402 110 24% Fiche 50-456,84/02/24,84022880005
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals"
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060 24X Fiche 50-000,84/02/27,8401190067
- S Reportable occurrences, LERs & related correspondence
- 8402170317 Supplemental Part 21 rept re radiographic record evaluation supplying add1 data to 830624 submittal Records show that 90 degree branch connections furnished to North Anna 1 & 2 jobsites No naziles supplied to Zimmer Related info enci BORNES, R P Southwest Fabricating & Welding Co (subs of IU International Corp) 83/10/04 PUTAPCUS, U Region 4, Office of Director 6pp 22296 156 24% Fishe 50-000.83/10/04.8402170317
- 8402170196 Final Part 21 rept re potential problem concerning radiography of branch connection welds covered by reinforcing pads Welds at Dyron Braidwood & North Anna acceptable Weld 7 at Clinton reradiographed BCRNES, R P Southwest Fabricating & Welding Co (subs of IV International Corp) B4/01/02 PDTAPOVS, U Region 4, Office of Director 2pp 22296 126 24% Fiche 50-000,84/01/02.8402170196
- B402070365 Part 21 rept re linear converter device w/possible generic defect Initially reported on B40116 Written notifications issued Customer responses should be received by 840331 Final rept will be submitted by 840430
 D0D90N.J F Pacific Air Products Co B4/01/30 Director's Office, Office of Inspection and Enforcement 2pp 22114 299 24) Fiche. 50-280.84/01/30.8402070365
- --8402070373 Part 21 rept re linear converter device w/possible generic defect. Initially reported on 840116 Freliminary analysis indicates excessive wear of brass shaft guides Next rept will be submitted within 70 days Supporting info encl DDDSQN.JP Pacific Air Froducts Co 84/01/17 POTAPOVS.U Region 4, Office of Director 68pp 22114 301 24X Fichs 90-000,84/01/30,8402070365
- T Hearing transcripts on non-antitrust matters
- B402270302 Partial response to FDIA request for five categories of documents re-mothballed nuclear const projects App A documents being placed in FDR Document as listed on App B already available in FDR Search continuing FELTON, J M Division of Rules and Records B4/01/20 BELL, N Nuclear Information & Resource Service 3pp 22395 200 24X Fiche 50-000, 84/01/20, 84/02270302
- --B402270321 Testimony of JB Martin before Subcommittee on Energy Conservation & Power re nuclear power plants being constructed by WPPBS Related info encl MARTIN.J B Region 5, Office of Director 83/09/14 86pp 22395.104 24X Fiche 50-000.84/01/20.8402270302
- DOCKET 50-458 RIVER BEND STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documents
 FELTON, J.M. Division of Rules and Records 83/10/31
 ROSENBAUM, D M Technical Analysis Corp 19pp 22193 292 24X
 Fiche 50-000,83/10/31,8402090003
- --8402070100 Responds to 820616 request for const schedule sxam NRC agrees w/1985 fuel load date Design work & site preparation substantially completed before actual const Related info encl
 REMICK, F J Office of Policy Evaluations 82/07/14 AMEARNE, J F Commissioners 5pp 22176 131 24X Fiche 50-000,83/10/31.
- --B402070134 Advises of 810303-05 Caseload Forerast Panel site visit results Const completion scheduled for Oct 1785 Related info encl. TEDEBCO,R L Assistant Director for Licensing 81/03/17 DRAPER,E L, Gulf States Utilities Co 10pp 22196.138 24X Ficher 50-000,83/10/31,8402070003

- --8402090166 Trip rept of \$30330-31 Caseload Forecast sité visits re current status of const & observation of in-progress activities Const progress will be reviewed at end of FYB3 WEINKAM.E.J. Licensing Branch 2 B3/10/31 Licensing Branch 2 13pp 22:96 156 24x Fiche 50-000.83/10/31.8402090003
- B402030174 Forwards responses to Geosciences Branch items identified during 830621 meeting & Guestion 231 15 in 831114 request for addl info W/one oversize figure Aperture card is in PDR BOOKER, J E Gulf States Utilities Co 84/01/20 DENTUN, H R Deffice of Nuclear Reactur Regulation. Director 64pp 22070 001 24X Fiche 50-458,84/01/20,8402030174
- 8402030093 Forwards NRC position re util drywell/containment purge sys & documents current & past licensing practice assuring required containment integrity Purging sys lacks small diameter purge lines SCHWENCER.A Licensing Branch 2 84/01/23 CAHILL.W J Oulf States Utilities Co 7.pp 22091 014 24X Fiche 50-458.84/01/23, 8402030093
- B402150398 Forwards Oulf States Utils Co. "Rept on Transmission Line Const Activities Within Port Hudson Natl Historic Landmark." in accordance w/Stipulation & from MDA SCHWENCER, A Licensing Branch 2 84/02/03 FINK, R Advisory Council on Historic Preservation 1p 22230 264 24X Fiche 50-438.84/02/03,8402150398
- 8402150507 Notification of 840215 meeting w/util in Bethesda,MD to discuss power sys review items WEINKAM,E J Licensing Branch 2 84/02/06 SCHWENCER,A Licensin Branch 2 3pp 22261 337 24X Fiche 50-458,84/02/06,8402150507
- B402170061 Notification of B40210 meeting w/Transamerica Delaval Inc (TBI) in Bethesda MD to discuss program plan proposed by TBI Dwners Group to qualify diesel generators CARUSO.R Division of Licensing B4/02/06 BERLINGER, C Division of Licensing 2pp 22312 339 24X Fiche 50-000.84/02/06, 8402170061
- 8402160326 Forwards response to Geosciences Branch Guestion 231 15 re
 41 unidentified seismic reflection profile lines within 5
 miles of site Response clarifies info submitted on 840120 &
 will be incorporated into FBAR
 BOOKER.J E Oulf States Utilities Co 84/02/07 DENTON. H R
 Office of Nuclear Reactor Regulation. Director 3pp 22277 00B
 24X Fichu 50-458.84/02/07.8402160326
- B402210204 Forwards supplemental responses to items identified by Matls Engineering Branch re Question 252 1 on base metal, heat affected zone & weld metal matl heat numbers used for reactor vessel test specimon BOOKER, J E Quif States Utilities Co B4/02/07 DENTON, H R Office of Nuclear Reactor Regulation. Director 16pp 22316 18 24X Fiche 50-458,84/02/07.8402210204
- 8402160415 Forwards responses to informal questions raised by reviewers of Procedure & Sys Review Branch re piping vibration Encl 1 & 2 contain changes to be included in next FBAR amend BOOKER, J E Gulf States Utilities Co 84/02/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 13pp 22269 097 24% Fiche 50-458,84/02/08,8402160415
- B402210104 Forwards supplemental response to Power Sys Branch request for add1 info re adequacy of electric distribution sys voltages
 BODKER, J & Quif States Utilities Co 84/02/10 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 40pp 22314 278
 24X Fiche 50-458,84/02/10,8402210104
- 8402210489 Approves 810825 request for withholding initial core fuel design info. Figures 4 3-3 through 4 3-6.4 3-12.4 3-13 through 4 3-18 through 4 3-18 to offgas systechnology info. Figures 11 3-1 to 11 3-2, per 10CFR2 790
 SCHMENCER, A Licensing Branch 2 84/02/13 CAHILL, W J Gulf States Utilities Co 3pp 22343 342 24X Fiche 50-458, 84/02/13, 84/02/13
- 8402220490 Forwards response to informal questions raised by reviewers from GA Branch based on util 831222 ltr to HR Denton re radioactive monitoring equipment & fabricated supports Changes to FSAR enci BOOKER, J E Gulf States Utilities Co 84/02/13 DENTON, H.R Office of Nuclear Reactor Regulation, Director 13pp 22340 050 24X Fiche 50~458.84/02/13.8402220490
- B402230080 Responds to 840105 Generic Ltr 84-01 re use of terms important to safety & safety-related Supports Util Safety Classification Group efforts Farticipation in discussions re use of terms will be through group BODKER, J E Gulf States Utilities Co B4/02/16 TAYLOR, J M Director's Office, Office of Inspection and Enforcement 1p 22361 201 24X Fiche 50-458, 84/02/16, 8402230080

- 8402270430 Notification of B40302 meeting w/Hydrogen Control Owners Group in Bethesda, MD to discuss status of Hydrogen Control Owners Oroup 1/4-scale testing program & response to request for addl info received from NRC in Dec 1983 HOUSTON.M D Licensing Branch 2 84/02/16 SCHWENCER.A Licensing Branch 2 7pp 22438 187 24X Fiche 50-000.84/02/16, B402290430
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8402080482 Summary of 840104 meeting w/util in Arlington. TX re mgt organization & training topics for Chapter 13 of SER List of meeting attendees encl WEINKAM.E. J. Licensing Branch 2 84/01/25 Licensing Branch 2 4pp 82174
- 8402070342 Forwards supplemental responses to questions & Structural & Geotechnical Engineering Branch draft SER open items, addressed in util 831007 & 1222 ltrs re fuel bldg & fuel racks Summary listing of items encl BOOKER.J E Gulf States Utilities Co 84/01/31 DENTON.H R Office of Nuclear Reactor Regulation, Director 12pp 22096 120 24X Fiche 50-458.84/01/31,8402070342
- 8402080125 Forwards responses to Auxiliary Sys Branch draft SER open items.including MSIV leak rate.compressed air supply testing & equipment to floor drainage sys indicated info will be included in next FSAR amend BOOKER, J E Gulf States Utilities Co 84/02/02 DENTON, H R Office of Nuclear Reactor Regulation. Director 21pp 22134 084 24X Fiche 50-458,84/02/02,8402080125
- 8402210112 Forwards supplemented responses to Radiological Assessment Branch additing requests & draft SER open items Summary listing of items being supplemented & response & ref matl for each supplemented item encl BDDKER.JE Gulf States Utilities Co 84/02/07 DENTON, HR Dffice of Nuclear Reactor Regulation, Director 12pp 22317 217 24X Fiche 50-458.84/02/07.8402210112
- 8402270087 Forwards response to informal questions re FSAR Chapter 13 raised by Licensee Qualification Branch based on review of 831202 ltr Info necessary to complete input to SER HOOKER. J E Gulf States Utilities Co 84/02/17 DENTON, H R Defice of Nuclear Reactor Regulation. Director 93pp 22426 193 24X Fiche 50-458,84/02/17.8402270087
- F Security, medical, emergency & fire protection plans
- 8402010174 Forwards request for add1 info re procedures generation package Request based on review of 830831 submittel in response to Generic Ltr 82-33. "Suppl 1 to NUREG-0737-Requirements for Emergency Response Capability " SCHWENCER.A Licensing Branch 2 84/01/18 CAHILL, J Gulf States Utilities Co 3pp 22048 051 24% fiche 50-458,84/01/18.8402010174
- B402090209 Forwards "Program Plan for Detailed Control Room Design Review," in response to Generic Ltr B2-33, "Suppl 1 to NUREG-0737 Requirements for Emergency Response Capability."

 B00KER, J.E. Guif States Utilities Co 84/01/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 19 22159 303 24X Fiche 50-458.84/01/31,8402090209
- --8402090213 "Program Plan for Detailed Control Room Design Review," * Gulf States Utilities Co 84/01/31 91pp 22159.304 24X Fiche 50-458.84/01/31,8402090209
- B402230279 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per 810709 Generic Ltr 81-27. W/o request.entire plan will be placed in PDR BCHWENCER. A Licensing Branch 2 84/02/06 CAHILL, W J Gulf Btates Utilities Co 2pp 22380, O31 24X Fiche 50-458.84/02/06.8402230279
- 8402170115 Forwards responses to Chemical Engineering Branch informal requests re missile doors, remote fate acquisition sys secondary power supply & fire protection program. Info will be included in next FSAR amend BOCKER, J E Quif States Utilities Co, 84/02/13. DENTON, H R. Office of Nuclear Reactor Regulation. Director 63pp 22300 164 24X Fichs 50-458,84/02/13.8402170115

O Adjudicatory correspondence

- B402220287 Advises that all parties in receipt of offsite radiological emergency response plans Mepting scheduled for B40221 in Baton Rouge. LA to discuss emergency planning contentions Related correspondence REPKA, DA Hearing Branch 3 84/02/13 COLE, RF, LINEBERGER. 6, COTTER. BP Atomic Safety and Licensing Board Panel 1p 2237 045 24X Fiche 50-458,84/02/13,8402220287
- B4022B033i Notice of withdrawal of appearance in proceeding. Certificate of Svc ancl FALKENHEINER, D. Louisiana Consumer's League, Inc. 84/02/21 2pp 22405 267 24% Fiche 50-458,84/02/21,84022B0331
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8402140064 Forwards Amend 11 to FSAR providing response or response schedule for items identified in draft SER Affidavit of Svc encl
 CAHILL.W J Gulf States Utilities Co 84/01/31 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 4pp 22230.336
 24X Fiche 50-458,84/01/31,8402140064
- ---8402140067 Amend 11 to FSAR * Gulf States Utilities Co 84/01/31 2,334pp 22230 340 24X Fiche 50-458,84/01/31,8402140064

M Antitrust correspondence

- 8402080148 Requests 2-wk extension until 840217 to file comments in OL application antitrust review.psr NRC 840104 notice RITES.F H Ely, Ritts, Pietrowski & Brittefield RITTS.F H Sam Rayburn O&T. Inc 84/02/03 TOALSTON, A Office of Nuclear Reactor Regulation, Director ip 22130 202 24X Fiche 50-458,84/02/03.8402080148
- 8402130207 Resubmits 800418 comments & NRC 800505 response re antitrust review of proposed purchase of facilities by Cajun Electric. IRVINO,5 M Irving. S M 84/02/03 Office of Nuclear Reactor Regulation, Director 1p 22200 102 24X Fichs 50-458,84/02/03,8402130207
- 8402140533 Discusses M Notatte of Sam Rayburn Generation & Transmission Cooperative request for extension for filing response to 840104 entitrust FR notice LAMBE, W Site Analysis Branch 84/02/03 Site Analysis Branch 1p 22251 312 24X Fiche 50~458.84/02/03.8402140533
- 8402210486 Responds to 840203 request for 2-wk extension to file comments on OL application antitrust review Comments up to 840217 & beyond will be considered time permitting TOALSTON-A L Site Analysis Branch 84/02/10 RITTS.F.H Ely. Ritts. Platrowski & Brickfield ip 22343 348 24X Fiche 50-438,84/02/10,8402210486
- B402210249 Informs that S Raybunn of O&T, Inc has signed agreement w/ Big Rivers Electric Cooperative to purchase 100 MW of firm power & energy RITTB.F H Ely, Ritts, Pietrowski & Brickfield 84/02/17. TOALSTON, A L Office of Nuclear Reactor Regulation, Director. 1p 22314 362 24% Fiche 50-458, B4/02/17, B402210249
- Q Inspection reports, IE Bullstins & correspondence
- 8402220365 Forwards IE Insp Rept 50-458/83-17 on 831114-18 & 1205-07 & notice of violation
 JOHNSON.E H Region 4, Office of Director 84/01/20 CAHILL.H J
 GUIF States Utilities Co 2pp 22335 310 24X
 Fiche: 50-458.84/01/20.8402220365
- --8402220348 Notice of violation from insp on 831114-18 & 1205-07. * Region 4, Dffice of Director 84/01/20 2pp 22335 312 24) Ficha 50-458,84/01/20,8402220365
- --8402220372 IE Insp Rept 50-458/83-19 on 831114-18 & 1205-07 Noncompliance noted failure to establish & execute insp program to verify socket weld size & failure to follow procedure for signing Oc hold points GILBERTL D., JOHNSON, W D., CROSSMAN, W A. Region 4. Office of Director 84/01/09 App 22335 314 24X Fiche 50-458,84/01/20-8402220365.
- 8312120153 IE Info Notice 84~06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc. 120pp 22058.001 24X Fiche.50~000,84/01/25,8312120153

- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vahicular Excess Controls " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers." Svc list encl DEYDUNG.R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177
- 8401190041 IE Info Notice 84-09: "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50: App R)" Syc list encl
 JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York: Inc 124pp 22365 259 24X Fiche 50-000: 84/02/13;8401190041
- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '"
 Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24X Fiche 50-000.84/02/14,8401190039
- B40ii90045 IE Info Notice 83-63. Suppl 1, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366 142 24X Fiche 50-000, 84/02/15, 8401190045
- B401190062 IE Info Notice B4-10. "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Bvc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche. 50-000, 84/02/21, 8401190062
- B401190046 IE Info Notice 84-11, "Training Program Deficiencies"

 Bvc list encl

 JORDAN, E. L. Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/02/24 Consolidated Edison Co of New

 York, Inc 115pp. 22430 304 R4X Fiche 50-000 84/02/24, 8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Beat Valve Seals "
 Svc list encl
 JORDAN.E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060 24X Fiche 50-000.84/02/27.8401190067
- S. Reportable occurrences: LERs & related correspondence
- E402070003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documents
 FELTON.J M Division of Rules and Records 83/10/31
 ROSENBAUM.D M Technical Analysis Corp 17pp 22173-272 24X
 Fiche. 50-000.83/10/31.8402070003
- ---B402090027 Submits draft rept of 830325 crane accident at plant site Crane collapsed while lifting 400-ton form assembly for containment shield bldg roof Cause undetermined Investigation in progress Related info encl
 CANILL.W J Gulf States Utilities Co 83/10/31 Gulf States
 Utilities Co 4pp 22193 311 24X Fiche 50-000.83/10/31,
- B402030299 Fart 21 rept re potential problem w/battery ground detector relay ITE 27B, Portions of solid state circuitry can be overstressed under certain operating conditions Users of relays will be notified. List of users of relay encl.

 BUVALL, D. D. Brown Boveri Corp (subs of Brown Boveri & Co., Ltd.)

 B4/01/05. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement.

 3pp. 22067 122 24X Fiche 50-000,84/01/05,8402030299
- 8401240381 Interim Deficiency Rept DR-121 re motor control ctr equipment supplied by ITE Gould Inc Investigation incomplete. Interim or final status rept will be provided by 840323.
- Incomplete, interim of file 1940323.
 BHOKER, J. E. Gulf States Utilities Co. 84/01/12 COLLINS, J 1 Region 4. Office of Director. 1p 21920.362 24X Fichd 50-458.84/01/12.8401240381
- 8401230407 Interim Deficiency Rept DR-136 re gouge in Class 1 feedwater sys pipe. Investigation incomplete. Next rept will be provided by 840417
 BORKER, J.E. Gulf States Utilities Co. 84/01/13. COLLINS, J T Region 4, Office of Director in 21879 081 24X
 Ficha: 50-458. 84/01/13. 8401230407.

- 8402060404 Final Deficiency Rept DR-144 re impact test coupons for main steem guide restraints Condition determined not reportable per IOCFRSD 55(e)
 IOOKER, J. E. Guif States Utilities Co. 84/01/26 COLLINS, J. F. Region 4. Defice of Director 1p. 22086 186 24X Fiche 50-458.8401/26.8402060400
- B402140017 Interim Deficiency Rept DR-75 re Ghosh-Wilson computer program used in reactor bldg hydrodynamic analysis
 Investigation incomplete Next rept will be submitted by B40630
 BGOKER, J E Gulf States Utilities Co B4/01/30 CDLLINS, J T Region 4, Office of Director 1p 22219 255 24X
 Fiche 50-458,84/01/30.B402140016
- 8402070393 Requests that NRC investigate design reliability of emergency diesel generators supplied by Transamerica Delaval. Inc Engine problems have been experienced since delivery of first vessel in May 1981 Related info encl MOLINA, J C Falcon Carriers, Inc 84/02/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 63pp 22096 097 24% Fiche 50-000.84/02/01.8402070393
- 8402140107 Interim Deficiency Rept DR-78 re installation & insp of fillet weld between structural member & embedment plate Investigation incomplete Interim or final status rept will be provided by 840404
 BODKER.J E Oulf States Utilities Co 84/02/02 COLLINS.J T Region 4, Office of Director 1p 22217 233 24X
 Fiche 50-458.84/02/02,8402140109
- 8402140369 Interim Deficiency Rept DR-103 re lifting lugs on containment dome Investigation ongoing Interim or final status rept will be submitted by 840316 BODKER, J E Gulf States Utilities Co 84/02/02 COLLING, J T Region 4, Office of Director ip 22230 328 24X Fiche 50-458,84/02/02,8402140369
- 8402170296 Interim Deficiency Rept DR-157 re ASME stock fittings Investigation still in progress Next rept by 840409 BOOKER.JE Gulf States Utilities Co 84/02/02 CDLLINB.JT Region 4, Office of Director ip 22276 152 24X Fiche 50-458.84/02/02.8402170256
- 8402140305 Interim Deficiency Rept DR-158 re ITE-32D relays supplied by Brown Boveri Investigation incomplete Next rept will be provided by 840418 BOOKERJJE gulf States Utilities Co 84/02/03 CDLLINS, J T Region 4, Office of Director ip 22227 175 24X Fiche 50-458,84/02/03,8402140305
- 8402140066 Interim Daficiency Rept DR-145 re implementation of design mod to beam welded to embedment plate in reactor bldg Investigation incomplete Interim on final status rept will be previded by 840321 BOOKER, J E Gulf States Utilities Co 84/02/06 CCLLINS, J T Region 4, Office of Director ip. 22217 245 24X Fiche 50-458,84/02/06,8402140066
- 8402140128 Interim Deficiency Rept DR-i26 re standby 480-volt load ctrs supplied by Powell Electric Investigation incomplete Interim or final status rept will be provided by 840403 BOOKER.JE Gulf States Utilities Co 84/02/07 COLLINS.JT Region 4, Office of Director ip 22219 028 24X Fiche 50-458.84/02/07.8402140128
- 8402170083 Interim Deficiency Rept DR-159 re fuses in explosive valve circuits of standby liquid control sys Investigation incomplete Next rept will be submitted by 840423 BOOKER, J E Gulf States Utilities Co 84/02/08 CDLLINS, J T Region 4, Office of Director 1p 22279 362, 24X Fiche 50-458,84/02/08,8402170083
- B402170169 Interim Deficiency Rept DR-146 re multi-pole circuit breakers mfg by ITE Electrical Products Siemens-Allis, Inc & supplied by Gould, Inc Investigation incomplets Next rept will be provided by B40417
 B00KER, J E Gulf States Utilities Co B4/02/08 COLLINS, J F Region 4, Dffice of Director 1p 22279 074 24X
 Fiche: 50-458,84/02/08,8402170169
- 8402170261 Interim Deficiency Rept DR-108 re Bergen-Paterson supplied pipe support components. Investigation still in progress Next rept by 840320 BOOKER, J E Quif States Utilities Co 84/02/08 COLLINS, J T Region 4, Office of Director ip 22274 362 24X Fiche, 50-458, 84/02/08, 8402170261
- 8401190053 Board Notification 84-020 forwards info re Transamerica Delaval, Inc emergency diesel generator problems Attendance list, meeting handouts & slides encl EISENHUT, D 0 Division of Licensing 84/02/13 FALLADINO Commissioners, 102pp 22332 202 24X Fiche 50-000, 84/02/13, 8401190053

- 8402220395 Interim Deficiency Rept DR-140 re transformer cable lead togs supplied by Gould Brown-Bover: Investigation continuing Nert rept usll be provided by 840423 BDOMER, J E Gulf States Utilities Co 84/02/13 COLLINS, J T Region 4, Office of Director 1p 22337 024 24X Fiche 50-458.84/02/13 8402220395
- 8402220530 Part 21 rept re defective DSR & DSRV standby diesel generator turbocharger thrust bearing Jubrication Deficiency nat corrected by sys mod Neu recommendation will be sent to customers by 840330 BUYER.R E Transamerica Delaval. Inc 84/02/15 Director's Office. Office of Inspection and Enforcement Spp 22332 102 24X Fiche 30-000.84/02/15.8402280530
- 8402280153 Finel Defitiency Rept DR-148 re proturement of GE spare parts Condition determined not reportable UDDKER. JE Oulf States Utilities Co 84/02/15 COLLINS, JT Region 4. Office of Director 1p 22400 215 24X Fishe 50-458.84/02/15.8402280153
- 840228037: Interim Deficiency Rept DR-87 re residual total elongation primary knife-type disconnect used on standby diesel generator investigation ongoing interim or final status rept will be provided by 840326 BOOKER, J E Quif States Utilities Co 84/02/16 COLLINS, J T Region 4, Office of Director ip 22404 362 24X Fiche 50-458.84/02/16.8402280371
- 8402280230 Final Deficiency Rept DR-96 re A500 Grade B tube steel supplied by Bergen-Paterson Condition not reportable per 10CFR50 55(e) BOOKER. J E Gulf States Utilities Co B4/02/17 COLLINS. J T Region 4. Office of Director 1p 22399 242 24X Fiche 50-438.84/02/17.8402280230
- 8402280486 Interim Deficiency Rept DR-103 re lifting lugs on containment done Condition determined not reportable under IOCFR50 55(e) BOOKER, J E Gulf States Utilities Co 84/02/17 COLLINS, J T Region 4, Office of Director Ip 22402 134 24X Fiche 50-438:84/02/17,8402820486
- B402280701 Notification of B40308 meeting w/Transamerica Delaval, Inc (TDI) Guners Group in Mading River, NY to discuss TDI proposed program plan to qualify diesel generators CARUSO,R Division of Licensing 84/02/23 BERLINGER, C Division of Licensing 24/02/23 BERLINGER, C Division of Licensing 2pp 22414 340 24X Fiche 50-000, 84/02/23, 8402280701

U Congressional/Erecutive Correspondence

- B402270002 Responds to FOIA request for correspondence NRC received from Senators J McClure, JB Johnston & P Laxalt during past 2 yrs Forwards App A documents Name of individual deleted from Cocuments B & 9 of App A (ref FOIA Exemption 6) FELTON, J M Division of Rules and Records 53/11/30 KOLI, E Cable News Nature, Inc. App. 22438 002 24% Fiche 50-000, 83/11/30,8402270002
- --8402290290 Forwards announcement of ASLB scheduled prehearing conference in DL application proceeding M/o announcement KAMMERER. C Office of Congressional Affairs 83/05/01 OTTINGER.R L House of Rep . Energy & Commerce SIMPSON, A Sanate. Environment & Public Works UDALL.M K House of Rep Interior & Insular Affairs 1p 22438 103 24% Fiche 50-000,83/11/30.8402270002
 - CMET 30-459 RIVER BEND STATION, UNIT 2

 Application/construction stage documents & correspondence
- 102090003 Responds to FDIA request for const completion dates for nuclear plants currently under const & analyses tentaining estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A, B & C documents
 FELTON, J M Division of Rules and Records 83/10/31
 RDSENBAUM, D M Technical Analysis Corp 17pp 22193 292 24x
 Fichs 50-000,83/10/31.8402090003
- |402030174 Forwards responses to Geosciences Branch items identified during 830521 meeting & Question 231 15 in 831114 request for add1 info M/one oversize figure Apenture card is in PDR BOCKER, JE Gulf States Uthlities to 84/01/20 DERTON.H R Diffice of Nuclear Reactor Regulation: Director 64pp 22070 001 24X Fiche 50-458,84/01/20,8402030174

- 8402170061 Notification of 840210 meeting w/Transamerica Delaval. Inc (1811 in Bethesda, MD to discuss program plan proposed by FDI Owners Group to qualify diseal generators CARUSOR Division of Licensing 84/02/06 BERLINGER, C Division of Licensing 24X Fiche 50-000, 84/02/06, 8402170061
- 8402160326 Forwards response to Geosciences Bronch Question 231 15 re
 41 unidentified seismic reflection profile lines within 5
 miles of site Response clarifies info submitted on 840120 &
 will be incorporated into FSAR
 BOOKER, J. E. Gulf States Utilities Co. 84/02/07 DENTON, M. R.
 Office of Nuclear Reactor Regulation. Director 3pp 22277 OCD
 24X Fiche 30-458.84/02/07,8402160326
- B402210204 Forwards supplemental responses to items identified by Matts Engineering Branch re Question 292 1 on base metal, heat affected rome & weld metal mat! heat numbers used for reactor vessel test specimen
 BUDKER. J E Gulf States Utilities Co 84/02/07 DENTON, H R
 Dffice of Nuclear Reactor Regulation. Director 1App 22316 181
 24X Fiche 30-458,84/02/07,8402210204
- 8402160415 Forwards responses to informal questions raised by reviewers of Procedure & Sys Review Branch re piping vibration Encl I & 2 contain changes to be included in next FSAR amend.

 800KER, J E Gulf States Utilities Co B4/02/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 13pp 22269 De7 24X Fiche 50-456,84/02/08,8402160415
- 8402210104 Forwards supplemental response to Power Bys Branch request for addl info re adequacy of electric distribution sys voltages BOOKER, JE Gulf States Utilities Co B4/02/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 40pp 22314 278 24X Fiche 50-458,84/02/10,8402210104
- 8402220490 Forwards response to informal questions raised by reviewers from QA Branch based on util 831222 ltr to HR Denton re radioactive monitoring equipment & fabricated supports Changes to FSAR encl 800KER.JE Gulf States Utilities Co 84/02/13 DENTON.H R Defice of Nuclear Reactor Regulation. Director 13pp 22340 050 24X Fiche 50-458,84/02/13,8402220490
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- 8402080125 Forwards responses to Auxiliary Bys Branch draft BER open items.including MSIV leak rate.compressed air supply testing & equipment & floor drainage sys Indicated info will be included in next FBAR amend BOOKER.J E Gulf States Utilities Co B4/02/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 21pp RRI34 OD4 24X Fiche 30-458,84/02/02,8402080125
- B402210112 Forwards supplemented responses to Radiological Assessment Branch addl info requests & draft SER open items Bummary listing of items being supplemented & response & ref matl for each supplemented item encl BOOKER.J.E. Gulf States Utilities Co. 84/02/07 DENTON.H R. Office of Nuclear Reactor Regulation, Director 12pp 22317 217, 24X Fichs 50-458,84/02/07,8402210112
- 8402290089 Forwards response to informal questions re FBAR Chapter 13 raised by Licenses Qualification Branch based on review of 831202 itr Info necessary to complete input to SER BUDNER, JE Gulf States Utilities Co 84/02/17 DENTON, H, R Office of Nuclear Reactor Regulation, Director 73pp 28484 173 24X Fiche 50-458,84/02/17,8402290089
- F Security, medical, emergency & fire protection plans
- 8402170115 Forwards responses to Chemical Engineering Branch informal requests to missile doors, remote date acquisition sys secondary power supply & fire protection program Info will be included in next FSAR amand BODKER, J E Guif States Utilities Co 64/02/13, DENTON, H R Office of Nuclear Reactor Regulation, Director, 63pp. 28300 164 24X Fiche 30-458,84/02/13,8402170115
- O Adjudicatory correspondence
- 8402220287 Advises that all parties in receipt of offsite radiological emergency response plans Meeting scheduled for 840221 in Batan Rouge, LA to discuss emergency planning contentions Related correspondence.

 REPKA, D A Hearing Branch 3 84/02/13 COLE, R F., LINEBERGER, Q , COTTER, B P Atomic Safety and Licensing Board Panel ip 22337 045 24X Fiche 50~458,84/02/13,8402220287

- 8402280331 Notice of withdrawal of appearance in proceeding Certificate of Svc encl FALRENMEINER, D. Louisiana Consumer's League, Inc. 84/02/21 2pp 22405 267 24X Fiche 50-458,84/02/21,8402280331
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8402140064 Forwards Amend 11 to FSAR providing response or response schedule for items identified in draft SER Affidavit of Syc enc! CAHILL, W J Gulf States Utilities Co. 84/01/31 DENTON, H R Office of Nuclear Reactor Regulation, Director App 22230 336 24X Fiche 50-458,84/01/31,8402140064
- --8402140067 Amend 11 to FSAR * Quif States Utilities Co 84/01/31 2,334pp 22230 340 24X Fiche 50-458.84/01/31,8402140064

M Antitrust correspondence

- 8402080148 Requests 2-wk extension until 840217 to file comments in OL application antitrust review.per NRC 840104 notice RITTS.F H Ely, Ritts, Pietrowski & Brickfield RITTB.F H Sam Rayburn Okt. Inc 84/02/03 TDALSTON.A Office of Nuclear Reactor Regulation, Director 1p 22130 202 24X Fiche 50-498,84/02/03.8402080148
- 8402130207 Resubmits 800418 comments & NRC 800505 response re antitrust review of proposed purchase of facilities by Cajun Electric IRVING.S M Irving. S M 84/02/03 Dffice of Nuclear Reactor Regulation, Director 1p 22200 102 24X Fiche 50-458,84/02/03.8402130207
- B402210486 Responds to 840203 request for 2-wk extension to file comments on OL application antitrust review Comments up to 840217 & beyond will be considered time permitting TOALSTON.A L Site Analysis Branch 84/02/10 RITTS.F H Ely. Ritts. Pietrowski & Brickfield ip 22343 348 24X Fiche 50-458.84/02/10.8402210486
- 8402210249 Informs that S Raybonn of G&T, Inc has signed agreement w/ Sig Rivers Electric Coopprative to purchase 100 MW of firm power & energy RITTS.F H Ely, Ritts, Pietrowski & Grickfield 84/02/17 TOALSTONA L Office of Nuclear Reactor Regulation, Director ip 22314 362 24X Fiche 50-458,84/02/17,8402210249
- G Inspection reports, IE Bulletins & correspondence
- 8312120153 IE Info Notice 84-06, "Steam Dinding of Auxiliary Feedwater Pumps " Bvc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120153
- 8401170017 IE Bulletin 84-01. "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement BA/02/03 Consolidated Edison Co of New York. Inc 102pp 82177
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Bafe Shutdown Sys (100FR50, App R)" Syc list encl
 JDRDAN, E. L. Division of Emergency Proparedness & Engineering
 Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259 24X Fiche 50-000.84/02/19,8401190041
- 9401170039 IE Info Notice 84-08, "10CFRSO 7, `Employee Protection.'" Svc list and JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/14 Consolidated Edison Co of New York Inc 115pp 22365 141 24X Fiche 50-000,84/02/14,8401170037
- B401190045 IE Info Notice B3-63. Suppl 1. "Potential Failures of Hestinghouse Type SA-1 Differential Relays " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/15 Consolidated Edison Co of New York, Inc. 118pp 22366 142 24X Fiche 50-000,84/02/15,8401190045
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value "Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co. of New York, Inc. 116pp. 22366-024 24X Fiche 50-000,84/02/21,8401190062

- 8401190066 IF Info Notice 84-11. Training Program Deficiencies "
 Svc list encl
 JORDANNE L Division of Emergency Preparedness & Engineering
 Rosponse (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- 8401190067 IC Info Notice 84-12. "Failure of Soft Seat Valve Seals "
 Svc list encl
 JDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060 247 Fiche 50-000,84/02/27,840119006?
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Eccess Controls " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 247 Fichs 50-000,84/02/03,8401190016
- S Reportable occurrences LERs & related correspondence
- B402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documents
 FELTON. Of Division of Rules and Records 83/10/31
 ROSENBAUM.D M Technical Analysis Corp 17pp 22193 292 24X
 Fiche 50-000.83/10/31.8402090003
- -8402070027 Submits draft rapt of 830325 crane accident at plant site Crane collapsed while lifting 400-ton form assembly for containment shield bldg roof Cause undetermined Investigation in progress Related info encl CANLLLW J Gulf States Utilities Co 83/10/31 Gulf States Utilities Co 84pp 22173 311 24X Fiche 50-000,83/10/31, 84073920003
- B402030299 Part 21 rept re potential problem w/battery ground detector relay ITE 27B Portions of solid state circuitry can be overstressed under certain operating conditions Users of relays will be notified List of users of relay encl DUVALL.D D Brown Boveri Corp (subs of Brown Boveri & Co., Ltd.) B4/01/05 DEYOUNG.R C Director's Office of Fixe of Inspection and Enforcement 3pp 22067 122 24X Fiche 50-000.84/01/05.8402030299
- E402070393 Requests that NRC investigate design reliability of emergency diesel generators supplied by Transamerica Delaval. Inc Engine problems have been experienced since delivery of first vessel in May 1981 Related info encl MULINA. J C Falcon Carriers. Inc 64/02/01 DENTON. R Office of Nuclear Reactor Regulation. Director 63pp 22096 057 24X Fiche 50-000.84/02/01.8402070393
- B401190033 Board Notification 84-020 forwards info re Transamerica Delaval. Inc emergency diesel generator problems Attendance list meeting handouts & slides entl EISEMBUT, D.G. Division of Liconsing 84/02/13 PALLADIND Cummissioners 102pp 22332 202 24X Fiche 50-000, 84/02/13, 8801190083
- 8402220530 Part 21 rept re defective DSR & DSRV standby diesel generator turbocharger thrust bearing lubrication Deficiency not corrected by sys mod New recommendation will be sent to customers by 840330

 BOYER R E Transamerica Dolaval. Inc 84/02/15 Director's Office of Inspection and Enforcement Spp 22332 182 24 Fiche 50-000.84/02/13.8402230530
- 8402280701 Notification of 840308 meeting w/Transamerica Delaval.Inc (TDI) Owners Group in Wading River.NY to discuss TDI proposed program plan to quality dissel generators CARUSO.R Division of Licensing 84/02/23 IERLINGER.C Division of Licensing 2pp 22414 340 24X Fichs 30 000.84/02/23, 8402280701
- U Congressional/Executive Correspondence
- 8402290002 Responds to FDIA request for correspondence NRC received from Senators J McClure. JB Johnston & P Laxalt during past 2 yrs Forwards App A documents Name of individual deleted from Documents 8 & 9 of App A (ref FDIA Exemption 6) FELTON. J M Division of Rules and Records 83/11/30 KOLI, E Cable News Network, Inc App 22938 GO2 24X Fiche 50-000, B3/11/30,8402290002
- --B402270270 Forwards announcement of ASLB scheduled prehearing conference in OL application proceeding W/o announcement KAMBERER, C. Office of Congressional Affairs 83/06/01 OTTINGER, R. House of Rep., Enorgy & Commerce SIMPSON, A Senate, Environment & Public Works UDALL, M.K. House of Rep., Interior & Insular Affairs ip 2243B 103 24X Fiche 50-000, 83/11/30, 8402290002

- DOCKET 50~460 WPPSS NUCLEAR PROJECT, UNIT 1
- A Application/construction stage documents % correspondence
- 8401170045 Partial response to FQIA request for six categories of documents is facilities Forwards documents listed in Apps A B B Documents also available in PQR W/o App A documents FELTON, J M Division of Rules and Records 93/10/24 ANDERSON, S I Garvey, Schubert, Adams & Garer 4pp 21838 003 24X Fithe 50-397,83/10/24,8401170045
- --8401170071 Advises of results of NRC Caseload Forecast Panel visit to plant site during 811021-23 Estimated const completion date for Unit 1 is Feb 1986 Unit 4 net included in evaluation

 TEDESCO.R L Assistant Director for Licensing 81/12/08 FERGUBON.R L Washington Public Power Supply System 3pp 21838 007 24X Fiche 90-397,83/10/24,8401170065
- --8401170073 Forwards final agenda for NRC Coselbad Forecast Panel 800122-24 site visit GBBMAN, A Washington Public Power Supply System 80/02/21 Washington Public Power Supply System 7pp 21838 015 24X Fiche 50-397.83/10/24,8401170065
- --8401170077 Summary of Caseload Forecast Panel 780413-15 site visits COX.T R Light Water Reactors Branch 3 78/09/28 Light Water Reactors Branch 3 12pp 21838 023 24X Fiche 50-397,83/10/24, B401170045
- --8401170083 "Level & Mgt Info Rept " Related info encl * Washington Public Power Supply System 80/01/30 72pp 21838 106 24X Fiche 50-397.83/10/24.8401170045
- --B401170089 "Project Status Rept for MNP-1.2.3.4 \$ 5 "

 * Washington Public Power Supply System 78/04/30 29pp
 21838 178 24X Fiche 50-397.83/10/24.8401170065
- ~-8401170072 "Project Trend Analysis Manpower Progress Schedule " Related info enc! * Washington Public Power Supply System 78/04/30 135pp 21838 207 24% Fiche 50-397.83/10/24,8401170065
- 8402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A, B & C documents

 FELTON.J M Division of Rules and Records 83/10/31

 ROSENDAUN.D M Technical Analysis Corp 19pp 22193 292 24X

 Fiche 50-000.83/10/31, 8402090003
- -8402090279 Trip rept of Caseload Forecast Panel 780613-15 site visits re const status assessment & projected completion date evaluation Related info encl COX.T H Light Water Reactors Granch 3 78/09/28 Light Water Reactors Branch 3 6pp 22194 311 24X Fiche 50-000.83/10/31, R402090803
- 1402080430 Forwards, for info, "Rept to Covernor J Spellman of State of WA & Governor V Atigeh of State of DR " Rept provides recommendations for solution to major problems involving or arising from WPRSS SORENSEN, 0 C Washington Public Power Fupply System B3/12/08 EISENHUT, D O Division of Licensing 1p 22168 286 24X Fishe 50-397.83/12/08.8402080430
 - 1402080435 "Rept to Governor J Spellman of State of MA & Governor V Atiyeh of State of DR " LUCE, C F CARLSON, E E, SCHWAB, H M Affiliation Not Assigned 83/11/30 68pp 22168 287 24X Fiche 50-397, 83/12/08, 8402080430
 - 140003 Third partial response to FDIA request for info re votes & andance at Commission meetings for Jul 1981 Jul 1983 LK.S J Office of the Secretary of the Commission 83/12/14 lic Document Branch 1p 22281 023 24% Fiche 50-000,83/12/14,140003
 - 60402 Discusses SECY-82-476 re FOIA Appeal B2-A-23 on Commission ilderation of requests for hearing on extension of CPs V.S J BFfice of the Secretary of the Commission B3/01/12 co of the Secretary of the Commission B3/01/12 to of the Secretary of the Commission ip 22281 255 24X 50-000, 83/12/14,8402160003

- G Adjudicatory correspondence
- 8402080132 Requests response re omission of ASLB & parties on svc list as recipients of Board Notifications 84-004 & 84-007 re environ qualification of equipment by Sandia Labs Related correspondence

 BELL, N. Coalition for Safe Pawer 84/01/27 DIRCKS, W. Office of the Executive Director for Operations ip 22132 144 24X

 Fichs 50-460,84/01/27,8402080132
- 8402030204 Order granting applicant & NRC motions for summary disposition & dismissing intervenor sole contention Proceeding terminated BRIGHT, G. D. HARBOUR, J., GROSSMAN, H. Atomic Bafety and Licensing Board Panel B4/02/01 Washington Public Power Supply System 20pp 22058 200, 24% Fiche 50-460.84/02/01,8402030204
- 8402240079 Notice that appeal will be filed on ASLB 840202 order Certificate of Svc encl BELL: N Coalition for Safe Power 84/02/17 2pp 22374 319 24x Fiche 90-460.84/02/17,8402240079
- 8402280326 Notifies of intent to file late filed contention re financial qualification of applicant pursuant to recent court decision overturning NRC elimination of financial qualification rule BELL,N Coalition for Safe Power 84/02/24 GROSEMAN,H , DRIGHT.0 U , HARDR,J Atomic Safety and Licensing Board Panel 1, 22399 127 24X Fiche \$0-460.84/02/24.8402280326
- 8402290126 Notice of ASLAB constitution GJ Edles, Chairman & WR Johnson & CN Kohlmembers SHDEMAKER.C J Atomic Safety and Licensing Appeal Panel, 84/02/27 ip 22426 154 24X Fiche 50-460.84/02/27,8402290126
- Q Inspection reports, IE Bulletins & correspondence
- 8402100219 Responds to IE Bulletin 83-08, "Electrical Circuit Breskers W/Undervoltage Trip Feature in Usa in Safety-Related Applications Other Than Reactor Trip Sys Protection "Undervoltage relays not utilized BORENSEN. 6 C Mashington Public Power Supply System 84/02/10 EIBENHUT. 0 Q Division of Licansing ip 22179 219 24X Fiche 50-460.84/02/10.8402100219
- 9 Reportable occurrences. LERs & related correspondence
- 8402080029 Responds to FOIA request for documents re facility hot functional testing problems including broken thermowells.

 laose & broken reactor coolant pump parts & loose thermal sleeves. Forwards App A documents Documents also in FDR FELTON. J M Division of Rules and Records 83/11/16 GARDE. 0 Government Accountability Project 3pp 22170 253 24X Fiche 50-000.83/11/16.8402080029
- ~-8402080036 List of hot functional testing exceptions Related info sect.
 # Affiliation Not Assigned 83/11/16 19pp 22170 236 24x
 Fiche, 50-000, 83/11/16, 8402080029
- 8402070393 Requests that NRC investigate design reliability of emergency diesel generators supplied by Transamerica Delaval, inc Engine problems have been experienced since delivery of first vessel in May 1981 Related into encl MDLINALJ C Falcon Carriers, Inc. 84702/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 63pp 22096 057. 24X Fiche 30-000,84/02/01,8402070393
- 840119004B Board Notification 84-006. provides info re alleged falsification of QC documents concerning const of safety—related HVAC units by Bahnson Co. Winston-Salem.NC. EIBENHUT, D G Division of Licensing B4/02/09, FALLADING Commissioners 7pp 22332 187 24X Fiche 50-000, B4/02/09, 840119004B
- 8401170053 Board Notification B4-020 forwards info re Transamerica Delaval, Inc embrgancy diesal generator problems, Attendance list meeting handouts & slides encl EIBENHUT, D G Division of Licensing 84/02/13, PALLADINO Commissioners, 102pp 22332 202, 24X Fiche 50-000, 84/02/13, 8401170053
- 8402220530 Part 21 rept re defective DSR & DSRV standby diesel generator turbocharger thrust bearing lubrication. Deficiency not corrected by sys mod. New recommendation will be sont to customers by 840330

 BDYER: R E Transamerica Delaval, Inc 84/02/15 Director's Office. Office of Inspection and Enforcement Spp. 22332:182 24x Fiche 50-000,84/02/15.8402220530.

T Hearing transcripts on non-antitrust matters

- 8402270302 Partial response to FOIA request for five categories of documents re mothballed nuclear const projects App A documents being placed in PDR Document as listed on App B already available in PDR Search continuing FELTON, J M Division of Rules and Records 84/01/20 BELL, N Nuclear Information & Resource Service 3pp 22395 200 24X Fichs 50-000,84/01/20,8402270302
- --8402270321 Testimony of JB Martin before Subcommittee on Energy Conservation & Power re nuclear power plants being constructed by WPFSB Related info encl MARTIN JB Region 5, Office of Director 83/09/14 86pp 22395 104 24X Fiche 50-000,84/01/20,8402270302

V Operator Examinations

8402220464 Suppls response to Generic Ltr 83-40 Operator license exams not planned at facilities SORENSEN.9 C Washington Public Power Supply System 84/02/15 Division of Licensing ip 22337 310 24X Fiche 30-460,84/02/15,840220464

DOCKET 50-461 CLINTON POWER STATION: UNIT 1

A Application/construction stage documents & correspondence

- B402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documents
 FELTON, J.M. Division of Rules and Records B3/10/31
 ROSENBAUM.D M Technical Analysis Corp 19pp 22173 292 24X
 Fiche: 50-000, 83/10/31,8402090003
- --8402090109 Trip rept of Caseload Forecast Panel 791127-30 site visits re const status Related info encl LICITRALE A Light Water Reactors Branch 3, 80/01/07. Light Water Reactors Branch 3 14pp 22194 166 24X Fiche. 50-000, 83/10/31, 8402090003.
- --8402090124 Handwritten notes & calculations re facility const Related info encl
 * NRC No Detailed Affiliation Given. 83/10/31 48pp 22194: 200 24X Fiche. 50-000, 83/10/31, 8402090003
- 8402070352 Forwards request for add1 info re facility HVAC structural design. Response schedule requested within 2 wks
 8CHMENCER, A Licensing Branch 2. 84/01/27 MULLER, Q Illinois
 Fower Co 3pp 22177.337. 24X Fiche 50-461,84/01/27,8402090352
- 8402160621 Advises that 831014 ltr unresponsive to concerns in NRC 830401 ltr re HPCS diesel generator qualification test requirements. Further reduction would compromise intent of test to demonstrate machine reliability. Meeting suggested. 8CHMENCER. A Licensing Brench 2 84/02/06 HERBORN. D I Illingis Power Co. Spp 22302 004 24X Fiche 50-461.84/02/06,8402160621
- 8402230088 Responds to 831219 Veneric Ltr 83-42 which indicated that guidelines of NUREO-O612 re single failure proof cranes may be deficient Review of diagrams indicates no single failure could result in uncontrolled motion of crane OBIER, J D. Illinois Power Co 84/02/10 BCHWENCER, A Licensing Branch 2 ip 28361-284. 24X Fichs 30-461,84/02/10.8402230088
- 8402290430 Notification of 840302 meeting w/Hydrogen Control Owners Group in Bethesda, MD to discuss status of Hydrogen Control Owners Group 1/4-scale testing program & response to request for addl info received from NRC in Dec 1986 HOWETON, M D. Licensing Branch 2 84/02/16 8CHWENCER, A Licensing Branch 2 7pp. 22438 187 24% Fiche. 80-000, 84/02/16, 8402290430
- 8402280235 Responds to NRC 840127 ltr requesting schedule for providing aidl info re Zack Co MVAC design criteria & duct work Info requested will be provided by 840315.

 HERBORN, D. I Illinois Power Co 84/02/17, 8CHWENCER, A Licensing Branch 2 1p 22399, 239 24X Fiche: 50-461, 84/02/17, 8402280235
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8402070152 Forwards presentation mat1 used at 830923 meeting re SER (NUREQ-0853) Dutstanding Issue 1 on transportation accident to close issue M/o encl. GEIER, J.D. Illinois Power Co. 84/01/31, BCHWENCER, A. Licensing Branch 2. ip. 22103 041, 24X Fiche 50-461,84/01/31,8402070152

- 8402150317 Forwards presentation matl used at 830923 meeting re SER (NUREG-0853) Outstanding Issue 1 on transportation accidents, inadvertently omitted from B40131 Its GEIER, J D Illinois Power Co 84/02/08 SCHWENCER, A Licensing Branch 2 1p 22231 050 24X Fiche 50-461,84/02/08,8402150317
- B402130336 Forwards 43 revised oversize elementary diagrams reflecting implementation of NUREO-0737.7MI Action Plan Items II K 3 13.1I K 3 15 & II K 3 18 Info closes out SER Confirmatory Issues 2B.45 & 46 Aperture cards in PDR GEIER.J D Illinois Power Co 84/02/07 SCHWENCER.A Licensing Branch 2 3pp 22217 001 24X Fiche 50-461.84/02/07,8402130336
- 8402240007 Forwards response to NRC 83i114 request for additinfo re SER issues concerning suppression pool dynamics Encl response should close out SER Outstanding Issue 9 & Confirmatory Issue 13 GEIER, J D Illinois Power Co 84/02/17 SCHWENCER, A Licensing Branch 2 60pp 22375 342 24X Fiche 50-461,84/02/17,8402240007

F Security, medical, emergency & fire protection plans

- 8402170392 Advises that NRC will not review emergency plans to delate privacy or proprietary info unlass specifically requested by licensee, per Bi0709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR SCHMENCER, A Licensing Branch 2 84/02/09 HERBORN, D I. Illinois Power Co 2pp 22313 184 24X Fiche 50-441, 84/02/09, 8402170392
- 8402170001 Forwards functional description of safety parameter display sys.per Generic Ltr 82-33 re compliance w/Suppl 1 to NUREG-0737 Enc] also provides results of review of verification & validation plan recommendations GEIER, J D Illinois Power Co 84/02/10 SCHWENGER, A Licensing Branch 2 42pp 22300 283 24X Fiche 50-461,84/02/10,8402170001
- 8402240385 Natification of 840228 meeting w/util in Clinton, IL to discuss emergency planning HARRISON, C Licensing Branch 2 84/02/16 SCHWENCER, A Licensing Branch 2 3pp 22380 130 24X Fiche 50-461,84/02/16,8402240385

Q Adjudicatory correspondence

- B402010200 Forwards NRC evaluation of issues presented by Prairie Alliance Contention III. Bubparts are Document discovery should commence by 640209, W/o encl GODDARD.R J Hearing Branch 3 84/01/30 WILLMAN.P L Illinois, State of 1p 22041 359 24X Fiche 50-461, 84/01/30, 8402010200
- 8402220343 Forwards documents to assist in determining whether to grant State of IL & Prairie Alliance request to dismiss Contentions III(f-j) re control room Admitted contention on emergency plan will be discussed on 840227 GODDARD:R J Hearing Branch 3 84/02/16 CLARK,H,K, FERGUBON:Q A., PARIS,O H Atomic Safety and Licensing Board Panel 19pp 22334 134 24X Fichs 50-461-84/02/16,8402220343
- 8402270106 Forwards requested documents on BWR core cooling instrumentation in ref to Contention (II(6) W/o encls GUDDARD,R J Hearing Branch G 84/02/27 HUBBARD,R MHB Technical Associates ip 22428 002 24X Fiche 50-461.84/02/27.8402270106

H General correspondence

8402270386 Informs that author assumed responsibilities for loss prevention/fire protection engineering activities, replacing RW Walden HAAQAR, E M Illinois Power Co 84/02/21 8CHWENCER, A Licensing Branch 2 2pp 22370 248 24X Fiche 50-461,84/02/21,8402270386

M Antitrust correspondence

- B402010320 Requests updated response to Guestions B 1 & B 2 of Reg Quide 7 3 re info needed in connection w/antitrust review of OL application REOAN M H Site Analysis Branch 84/01/12 KOCH.L J Illinois Power Co 2pp 22046, 187 24X Fiche 50-461, 84/01/12, 8402010320
- Q Inspection reports. IE Bulletins & correspondence
- 8402020007 Forwards IE 1nsp Rept 50-461/83-23 on 831205-15 & notice of violation.

 8PEBBARD, R L Division of Engineering 84/01/17 GERSTNER, W C 1111no1s Power Go. 2pp 22056 342 24X Fiche 50-461, 84/01/17, 8402020007
- --8402020009 Notice of violation from insp on 831205-15. SPE8SARD,R L Division of Engineering 84/01/17 2pp 22056-344 24X Fiche. 50-461,84/01/17,8402020007.

- --8402020010 IE Insp Rept 50-461/83-23 on 831205-15 Violations noted inadequate disposition on deviation rept & failure to document nonconforming conditions LOVE, R 5 · ENG.P L · HILLIAMS.C C Region 3, Office of Director 84/01/13 10pp 22056 346 24% Fiche 50-461.84/01/17.84020200007
- 8402020307 Forwards IE Insp Rept 50-461/83-24 on 831217 & 20 No nancompliance noted LITTLE.W S Region S. Office of Director 84/01/17 GERSTNER.W C Illinois Power Co 2pp 22052 250 24X Fiche 50-461,84/01/17.
- --840202031à IE Insp Rept 50-461/83-24 on 831219 & 20 No noncompliance or deviations noted Major areas inspected review of revised procedures & instructions, inspector training records & welder certifications for lifting of stop work orders XEY,W J. DANIELBON.D H. Region 3. Office of Director 84/01/13 8pp 22052 252 24X Fiche 50-461,84/01/17.8402020307
- 8312120153 IE Info Notice 84-06, "Bteam Binding of Auxiliary Feedwater Pumps" Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120153
- 8402130303 Forwards IE Inep Rept 50-461/83-22 on 831116-840115 & notice of violation NNDP,R C Region 3, Office of Director 84/01/27 GERSTNER,W C Illinois fower Co 2pp 22197 128 24x Fiche 50-461,84/01/27,8402130303
- --8402130306 Notice of violation from insp on B31116-840115 KNOP.R C Region 3, Office of Director 84/01/27 2pp 22197 130 24% Fiche 50-461.84/01/27,8408130303
- --8402130312 IE Imsp Rept 50-461/B3-22 on B31116-B40115 Noncompliance noted inadequate control of special process, defects in steel containment liner dome not reported to Region III & weld deficiencies not documented LIVERMORE H H . CHRISTIANBON, F . HAYES, D W Region 3, Office of Director 84/01/26 11pp. 22197 132. 24X Fiche 50-461,84/01/27,8402130303
- 8401190016 IE Info Notice 84-07. "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list and | JORDAN,E L Division of Emergency Preparefness & Engineering Response (fost 930103) 84/02/03 Consolidated Edison Co. of New York, Inc 119pp 22114 179 24X Fiche. 50-000, 84/02/03, 8401190016
- 8401190017 IE Bulletin 84-01. "Cracks in BWR Mark I Containment Vent Headers." Bvc list encl DEYBUNDAR C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177.156 24X Fiche 50-000.84/02/03.8401190017
- 8402270179 Forwards IE Insp Rept 80-461/84-01 on 840116-19 No noncompliance identified PAPERIELLO,C J Region 3, Office of Director 84/02/08, GERSTNER,W C Illimois Power Co. 2pp 22386:332 24X Fiche 50-461,84/02/08,8402270199
- --8402270226 IE Insp Rept 30-461/84-01 on 840116-19 No noncompliance or deviations identified Major areas inspected, radweste & radiation protection programs, including staffing, radwaste organization & status of test procedures PAUL, R A. GREGER, L R. Region 3. Office of Director 84/02/07 App. 22386-354 24X Fiche 50-461.84/02/08.8402270199
- 8402170163 Revises commitment to confirmation of action ltr dtd 820127 re method of implementing GA program HALL-D.P Illinois Power Co. 84/02/09. KEPPLER, J @ Region 3. Office of Director 2pp. 22299 075 24X Fiche 50-461.84/02/09. 8402170163
- 8401190041 IE Info Notice 84-09. "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR30, App R) " Syc list encl.
- entl. JDRDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365-259 24X Fiche 50-000,84/02/13,8401190041
- B401190039 IE Info Notice 84~08, "10CFR50 7, 'Employee Protection '"

 Bvc list encl.

 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14. Consolidated Edison Co. of New
 York Inc. 115pp 22365; 141 24X Fiche 50~000, 84/02/14, 8401190039
 - 01190045 IE Info Notice 83-63, Suppl 1: "Potential Failures of estinghouse Type SA-1 Differential Relays." Svc list encl RDAN.E L Division of Emergency Preparedness & Engineering spanse (Post 830103). 84/02/15 Consolidated Edison Co. of New k. Inc. 1186p. 22366.142 24X Fiche.50-000,84/02/15,8401190045

- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switchis Set Below Manufacturer Recommended Value " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc. 116pp 22366 024 24X Fichs 50-000.84/02/21,8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies"
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fishe 50-000,84/02/24,8401170066
- 8401170067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
 Svc list enc!
 JURDAN, E L Division of Emergency Preparedness & Engineering
 Reeponse (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060 24% Fiche 50-000.84/02/27.8401190067
- R Periodic operating reports & related correspondence
- 8402040052 Provides quarterly update re const schedule Target date for fuel load scheduled for 840103, w/commercial operation scheduled for B61101 HALL,D P Illinois Power Co 84/01/26 DENTON.H R Dffice of Nuclear Reactor Regulation, Director 1p 22088 200 24X Fiche 50-461.84/01/26.8402040052
- S Reportable occurrences, LERs & related correspondence
- 8402170317 Supplemental Part 21 rept re radiographic record evaluation, supplying add1 data to 830624 submittal Records show that 90 degree branch connections furnished to North Anna 1 & 2 jobsites No nozzles supplied to Zimmer Related info encl BORNES, R P. Bouthwest Fabricating & Welding Co (subs of IU International Corp) 83/10/04 POTAPOUS, U Region 4. Office of Director 6pp 22294 156 24% Fiche 50-000,83/10/04,8402170317
- 8402170196 Final Part 21 rept re potential problem concerning radiography of branch connection welds covered by reinforcing pads Welds at Buron, Braidwood & North Anna acceptable Weld 7 at Clinton reradiographed BORNES, R P Southwest Fabricating & Welding Co. (subs of IU International Corp) 84/01/02 POTAPUS, U Region 4, Office of Director 2pp 22296 126 24X Fiche 50-000,84/01/02,8402170196
- 8402030227 Interim Reportable Deficiency 55-83-07 re adequacy of shop welds on pips spools fabricated by Southwest Fabricating & Welding Co Initially reported on 830614 Final rept will be submitted upon completion of investigation HALL, D P Illinois Power Co. 84/01/25 KEPPLER, J G Region 3, Office of Director 4pp 22067 156 24X Fiche 50-461,84/01/25, 3402030227
- 8402060428 Final Deficiency Rept 55-81-04 re certification of HVAC matls Initially reported on 811002 Zack Co revised corporate a site GA manuals to enhance controls & describe programs re Installation Spec K-2710 for HVAC HALL, D P Illinois Power Co 84/01/30 KEPPLER, J. G. Region 3, Office of Director, 4pp 22085 161 24X Fiche, D0-461, 84/01/30, 8402060428
- B402070365 Part 21 rept rs linear converter device w/possible generic defect Initially reported on B40116 Written notifications issued Customer responses should be received by B40331. Final rept will be submitted by 840430 DIDSON, J P Pacific Air Products Co 84/01/30 Director's Office, Office of Inspection and Enforcement 2pp 22114 299. 24% Fichs 50-280,84/01/30,8402070365
- --B402070373 Part 21 rept re linear converter device w/possible generic defect Initially reported on B40116 Preliminary analysis indicates excessive wear of brass shaft guides. Next rept will be submitted within 90 days Supporting info encl DOBBON.JP Pacific Air Products Co. B4/01/17 POTAPOVS,U Region 4. Office of Birector & Spp. 22114, 301 24X Fiche. 50-000,84/01/30,8402070365
- 8402270021 Interim potential Deficiency Rept 55-84-03 re irregularities in installation of concrete expansion anchors Initially reported on 84011 Caused by creftsmen not instructed properly & failure to perform in-process GC inep HALL.D P Illinois Power Co 84/02/14 KEPPLER.J G. Region 3. Office of Director. 3pp 22391 317 24X Fiche 50-461,84/02/14, B402270021.
- 8402270025 Interim potential Deficiency Rept 55-84-02 re identification of electrical hanger matls installed by Baldwin Assoc Initially reported on 8401if. Caused by lack of consistency in adherence to procedural requirements. Procedures revised. HALL, D.P. Illinois Power Co. 84/02/14 KEPPLER, J.Q. Region 3, Office of Director. Sap. 22391 320 24X Fiche. 50-461,84/02/14,84/02/20025

- 8402270261 Interim Deficiency Rept 55-84-01 re potential problems w/ control of field initiated design changes between Sargent & Lundy & Baldwin Assoc Initially reported on B40111 Evaluation underway re scope & sefects on hardware HALL, D.P. Illinois Power Co. 84/02/21 KEPPLER, J.O. Region 3, 84fice of Director 3pp. 22427 218 24X Fiche 50-461,84/02/21,8402270261
- 8402290276 Interim deficiency rept re Potential Deficiency 55-82-11, concerning incorrect identification of base math & weld procedures on piping hanger travelers Final rept will be delayed add 30 days to complete & evaluate actions HALL, D.P. Illinois Power Co. 84/02/22 KEPPLER, J.O. Region 3, Office of Director ip 22427 204 24X Fiche 50-461.84/02/22, 8402290276

DOCKET 50-462 CLINTON POWER STATION, UNIT 2

- 8 Reportable occurrences. LERs & related correspondence
- 8402i703i7 Supplemental Part 21 rept re radiographic record evaluation, supplying addidata to B30624 submittal Records show that 90 degree branch connections furnished to North Anna 1 & 2 jobsites, No nozies supplied to Zimmer Related into enci SORNES, R P Southwest Fabricating & Welding Co (subs of IV International Corp.) 83/10/04 P0TAPOVS, U Region 4, Office of Director. 6pp 22296:156 24X Fiche 50-000,83/10/04,8402170317
- 8402070365 Part 21 rept re linear converter device w/possible generic defect Initially reported on 840116 Written notifications issued Customer responses should be received by 840331 Final rept will be submitted by 840430 DDBSON, J. P Pacific Air Products Co 84/01/30 Director's Office of Inspection and Enforcement 2pp 22114 299 24X Fichs 50-280,84/01/30.8402070365
- --8402070373 Part 21 rept re linear converter device w/possible generic defect Initially reported on 840116 Preliminary analysis indicates excessive wear of brass shaft guides Next rept will be submitted within 90 days Supporting info encl BOBBON; J P Pacific Air Products Co. 84/01/17 PDTAPQVB,U Region 4, Office of Director 6Bpp 22114 301 24X Fiche: 50-000, 84/01/30, 8402070345

DOCKET 50-463 FULTON GENERATING STATION, UNIT 1

O Adjudicatory correspondence

- 8402010189 Order to hold 840229 prehearing conference in Philadelphia, PA re applicant motion for summary decision & for typmination of proceeding COTTER, B P., Atomic Safety and Licensing Board Panel. 84/01/27 2pp. 22038
- 8402140162 Informs that staff does not object to applicant request for leave to reply to intervenors response to objections of NRC & applicant to proposed decision & order of ASLB & does not plan to file formal response TURK, B.E. Hearing Branch 1 64/02/06 COTTER, B.P., LINENBERGER, G., DEBYLVA, D.P. Atomic Bafety and Licensing Board Panel 1p. 22219:315 24x Fiche: 50-463,84/02/06.8402140162
- B4022900B6 Notice of reconstitution of board, Judge IW Bmith appointed in place of Judge DP de Sulva SHON, F. J. Atomic Bafety and Licensing Board Panel B4/02/28 2pp 22426;297 24X Fiche: 50-463:84/02/28;8402290086

DOCKET 50-464 FULTON GENERATING STATION, UNIT 2

G. Adjudicatory correspondence

- B402010187 Order to hold 840227 prehearing conference in Philadelphia, PA re applicant motion for summary decision & for termination of proceeding COTTER, B.P. Atomic Safety and Licensing Board Panel 84/01/27 2pp. 22038
- 8402140162 Informs that staff does not object to applicant request for leave to reply to intervenors response to objections of NRC 4 applicant to proposed decision & order of ASLB & does not plan to file formal response

 TURK, S.E. Hearing Branch 1 84/02/06 COTTER, B F , LINENBERGER, G , DEGYLVA, D, P. Atomic Bafety and Licensing Board Panel 1p.

 22219.31B. 24X Fiche, 50-463, 84/02/06, 8402140162
- 8402270086 Notice of reconstitution of board, Judge IW Smith appointed in place of Judge DP de Sulva SHON-F.J. Atomic Safety and Licensing Board Panel. 84/02/28 2pp 22426 277. 24X Fiche. 50~463.84/02/28,8402270086

- POCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT 1
- D Advisory Committee on Reactor Safeguards reports & correspondence
- 8402270263 Responds to FOIA request for JC Mark 801204 memo to ACRS re hydrogen burn w/igniters & documents concerning generation, combustion or control of hydrogen in reactor accidents Forwards App A documents App B documents in PDR FELTON, J M Division of Rules and Records 84/01/30 HIATT, S L Ohio Citizens for Responsible Energy 7pp 22412 051 24X Fiche 50-000.84/01/30.8408270263
- --8i10300iii Advises that review of post-accident inerting sys for facilities will continue during post-CP period Early review of work progress during Spring 1982 would be beneficial MATTSON,R J Division of Bystems Integration (post 8i1005) 81/10/07 FRALEY,R F ACRS Advisory Committee on Reactor Safeguards ip 22412 209 24X Fiche 50-000,84/01/30,8402270263

DOCKET 50-467 ALLENS CREEK NUCLEAR STATION, UNIT 2

- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8402270263 Responds to FOIA request for JC Mark 801204 memo to ACRS re hydrogen burn w/igniters & documents concerning generation, combustion or control of hydrogen in reactor accidents Forwards App & documents App B documents in PDR FELTON, J M Division of Rules and Records 84/01/30 HIATT, S L Ohio Citizens for Responsible Energy 7pp 22412 051 24X Fiche 50-000, 84/01/30, 84/2270263
- --8110300111 Advises that review of post-accident inerting sys for facilities will continue during post-CP period Early review of work progress during Spring 1982 would be beneficial MATTSON,R J Division of Bystems Integration (post 811005) 81/10/07 FRALEY,R F ACRS Advisory Committee on Reactor Bafeguards 1p 22412 209 24X Fiche 50-000,84/01/30,8402270263

DOCKET STN-50-470 CESSAR SYSTEM 80

- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8402220487 Forwards proprietary & nonproprietary "Comprehensive Vibration Assessment Program for Palo Verde, Unit 1 (Sys 80 Prototype)." per SER (NUREG-0832) Proprietary rept withheld (ref 100FR2 770) SCHERER, A.E. Combustion Engineering, Inc 84/02/16 EIBENHUT, D 0 Division of Licensing 5pp. 22333,057 24X Fiche 50-000,84/02/16,8402220487
- --8402220496 Nonproprietary "Comprehensive Vibration Assessment Program for Palo Verde Nuclear Generating Station.Unit ! (8ys BO Prototype)," preliminary evaluation of precore hot functional measurement & insp programs * Combustion Engineering, Inc CEN-263(V)-NP 84/02/16 66pp 2233 062 24X Ficher 50-000,84/02/16,8402220489
- DOCKET 50-471 PILORIM NUCLEAR POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8402280018 Further response to FOIA request for documents generated or received by NRC since 820331 re Hayward Tyler Pump Co Forwards App A documents, App A documents placed in FDR App B documents withheld (ref FOIA Exemption 5) FELTON.J. M Division of Rules and Records. 83/12/21 LODGE.8 Dallas Morning News. 3pp 22430 209 24X Fiche 30-471.83/12/21.8402280018
- ---B4022B0087 Forwards analyses of antirotation pin & impeller ring wear, par request Encl info should be treated as company-sensitive
 LYONE, B.P. Hayward Tyler Pump Co. 82/07/28. FORTUNA.R
 Director's Office. Office of Inspection and Enforcement App. 22430, 282 24X Fiche. 50-471,83/12/21,8402280018.

DOCKET STN-50-482 WOLF CREEK GENERATING STATION

- A. Application/construction stage documents & correspondence
- B402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing satimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documents
 FELTON, J. M Division of Rules and Records, B3/10/31 ROBENBAUM, D M Technical Analysis Corp 19pp 22193 292 24X Fichs 50-000,83/10/31.8402090003

- --8402090109 Trip rept of Caseload Forecast Panel 791127-30 site visits re const status Related info encl LICITRALE A Light Water Reactors Branch 3 80/01/07 Light Water Reactors Branch 3 14pp 22194 186 24X Fiche 50-000.83/10/31,8402090003
- --8402070250 Handwritten notes & calculations re const schedulp activities & fuel load preparation Related info encl * NRC - No Datailed Affiliation Given 83/10/31 10pp 22196 287 24X Fiche 50-000,83/10/31.8402090003
- --8402090261 Handwritten notes & calculations re const activities Related info encl * NRC - No Detailed Affiliation Given 80/10/31 3pp 22196 301 24X Fiche 50~000,83/10/31.8402090003
- 8312120136 Board Notification 84-011 discusses NRC use of terms "important to safety" & "safety-related" EISENHUT.D G Division of Licensing 84/01/18 PALLADIND Commissioners 72pp 22241 008 24X Fiche 50-000.84/01/18.8312120
- 8402010134 Forwards Rev 1 to "Rept on Control of Heavy Loads," updating areas of safe load path review & vendor analysis of reactor coolant pump motor lifting sling.per NUREO-0612 criteria PETRICK,N A Brandardized Nuclear Unit Power Plant System 84/01/27 DENYON,H R Office of Nuclear Reactor Regulation, Director 3pp 22038 235 24X Fiche: 50-000,84/01/27,8402010134
- --8402010149 Rev 1 to "Rept on Control of Heavy Loads"

 * Standardized Nuclear Unit Power Plant System 84/01/27. 22pp
 22038 238 24X Fiche 50-000,84/01/27.8402010134
- 8402010250 Forwards interim justification positions for seismic & environ qualification of differential pressure indicating Barton Switch 286A & in-core thermocouples, connectors & ref junction box, per NUREG-0588 Graph withheld FERRICK, N A Standardized Nuclear Unit Power Plant System 64/01/27 BENDON-H R Office of Nuclear Reactor Regulation, Director 133pp 22040 001 24% Fiche 50-000, 84/01/27. 8402010250
- 8402020259 Forwards info documenting compliance w/Position 1 of Reg Guids 1 63 consisting of description of calculation methodology & representative time-current curves for thermal capability of penetration assemblies PETRICK.N A Standardized Nuclear Unit Power Plant System 84/01/31 DENTON-N R Office of Nuclear Reactor Regulation, Director 24pp 22055 263 24X Fiche 50-000.84/01/31.8402020259
- 8402090364 Requests add1 info to complete evaluation of request to replace water bags for radiation shielding New shielding must meet listed conditions of SRP Section 6.2 1.2. "Bubcompartment Analysis"

 YOUNOBLOOD B J Licensing Branch 1 84/01/31 KOESTER, 0 L Kansas Cas & Electric Co. SCHWELL, D F Union Flettric Co 4pp 22177:303 24X Fiche 50-000,84/01/31,8402090364
- 8402010410 Generic Ltr 84-04 to all operating PWR licensees. CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing well-mination of postulated pipe breaks in PWR primary main loops Svc list encl EIBENHUT, D 0 Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc 59pp 22177 087 24X Fiche 50-000 84/02/01,8402010410
- 8402030314 Forwards Rev 2 to "Rept of Independent Review of Environ Qualification Programs to NUREG-0388." Rev incorporates util 830728 response re surface temp calculation methods. PETRICK:N A Standardized Nuclear Unit Power Plant Bystem. 84/02/01 DENTON.H.R. Diffice of Nuclear Reactor Regulation. Director 4pp 28071 073 24% Fiche 50-000,84/02/01.8402030314

fant Baufau of Environ

84/02/01. 709pp

of seismic 1205

_ystem egulation, /02,8402070159

nts on steam Tach Spac tors be

System. egulation: /02.8402090273

- --B4020902B5 Application for withholding rept, "BNUPP8 Steam Generator Tubs Plugging Margin Evaluation" (ref iOCFR2 790) WIESEMANN.R A Westinghouse Electric Corp 84/01/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 9pp 22160 220 24% Fiche* 50-000.84/02/02.8402090273
- 8402190397 Forwards proof & review Tech Specs for facility Results, identifying sections reviewed, requested by 840224 THOMAS. C 0 Standardication & Special Projects Branch 84/02/03 YDUN08LOOD. J Licensing Branch 1 HDLAHAN, O Operating Reactors Assessment Branch LIAM, B D Materials Engineering Branch 3pp 2220 001 24X Fichs 50-482,84/02/03,8402190397
- --8402130397 Proof & review Tech Spacs for facility * NRC - No Detailed Affiliation Given 84/02/03 470pp 22260 004 24X Fiche 50-482,84/02/03,8402150397
- 8402150515 Notification of 840216 meeting w/utils & SNUPP8 in Bethesds.MD to discuss Tech Spec requirements on slave relay testing HOLGNICH.JJ Licensing Branch i 84/02/07 YGUNGBLOGD.B J. Licensing Branch i 4pp 22261 347 24% Fiche BO-000.84/02/07. 8402150515
- B402230327 Notification of rescheduled 840217 meeting w/utils & SNUPPS in Bethesdar ND to discuss Tech Spec requirements on slave relay testing Meeting originally scheduled for 840216 HOLGNICH. J Licensing Branch | 84/02/07 YOUNGBLOOD, B J Licensing Branch | 84/02/07 YOUNGBLOOD, B J 6402230327
- B40214018B Forwards Rev 11 to initial test program, per F8AR Section 14 2 3 re testing equipment commitment availability 60 days before scheduled fuel load for initial startup test Rev will be included in next F8AR update.

 **WOESTERNO L. Kansas Gas & Electric Co 84/02/09 DENTON, H. R Office of Nuclear Reactor Regulation, Director COLLINS, J T. Region 4, Office of Director 2pp 22223 276 24% Fiche 50-482, 84/02/09, 84/02/40188
- --8402140192 Rev 11 to initial test program
 * Kanses Gas & Electric Co 83/08/31 46pp. 22223 278 24X
 Fiche. 50-482, 84/02/09, 8402140188
- 8401190059 Board Notification 84-032.provides add1 info on environ qualification Bubmittel augments info in Board Notifications 84-004 & 84-007.
 EISENHUT, D @ Division of Licensing 84/02/13 Atomic Bafety and Licensing Board Fanel 10pp 22314 204 24X Fiche 50-000, 84/02/13.8401190059.
- 8402240272 Forwards comments, for consideration on proposed offsite dose calculation manual for facility Comments should be incorporated in offsite dose calculation manual & revised version submitted by 840310
 YOUNBBLODD.
- 8401170068 Board Notification 84-033 provides "Bys Interaction Program," task action plan for Unresolved Safety Issue A-17 Distribution list enci EIBENHUT.D G Division of Licensine 84/02/16 PALLADINO Commissioners, 8pp 22482 091. 24X Fiche: 50-000. 84/02/16 B401170068.
- 8402280258 Reaponds to 840131 request for clarification of replacements for water bags for reactor cavity shielding Proposal to utilize rigid shielding contingent on conclusion that large break in RCS need not be postulated PETRICK, N A Standardized Nuclear Unit Power Plant System. 84/02/17. DENTON, H R. Office of Nuclear Reactor Regulation, Director. 2pp 22379, 134. 24X Fiche 50-000, 84/02/17, 8402280258
- B402270406 Forwards supplemental info to "Environ Qualification
 Justifications for Interim Operation" & presents two addi
 justifications re HE-1 & Reg Quide 1 97.Rev 2 equipment.
 Qualification parameters appropriate
 PETRICK.N A Btandardized Nuclear Unit Power Plant System
 B4/02/23 DENTON.H.R Office of Nuclear Reactor Regulation,
 Director 3pp 22391.033 24X Fiche 50-000,84/02/23,8402270406
- 8402280372 Forwards responses to Instrumentation & Control Sys Branch issues identified during audit of facilities, covering automatic test & indication sys & boron dilution mitigating sys.
 PETRICK, N A Standardized Nuclear Unit Power Plant System.
 84/02/23 DENTON, H.R. Office of Nuclear Reactor Regulation,
 Director. 7pp 22402, 261 24X Fiche 50-000, 84/02/23, 8402280392
- 8402280058 Forwards revised "Offsite Dose Calculation Manual "
 KOESTER, Q L. Kansas Gas & Electric Co. 84/02/24 DENTON, M.R.
 Office of Nuclear Reactor Regulation, Director. 2pp. 22399:318,
 24% Fichs 50-482,84/02/24,8402280058

- --B402280062 Revised "Offsite Dose Calculation Manual " W/three oversize maps Aperture cards are available in PDR KANSAS GAS & Electric Co 84/01/31 105pp 22079 320 24% Fiche 50-482,84/02/24,8402280058
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- B402020319 Forwards summary of two unresolved issues discussed in SER Section B 3 i 2 re undervoltage protection analyses corresponding to Sections 3 & 4 of Power Sys Branch Technical Position PSB-1
 PETRICK,N A Standardized Nuclear Unit Power Plant System 84/01/31 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 22055 152 24X Fiche 50-000,84/01/31,8402020319
- B4020A03B4 Forwards Rev 13 to FSAR Rev contains info meressary to resolve Licensing Confirmatory Issues 12 & B 13 identified in Gallaway & Wolf Creek SERs, respectively PETRICK, N A Standardized Nuclear Unit Power Plant System B4/02/02 DENTON, H Office of Nuclear Reactor Regulation, Director 1p 22083 291 24X Fiche 50-000,84/02/02,8402060384
- --8402060389 Rev 13 to FSAR * Standardized Nuclear Unit Power Plant System 84/02/29 281pp 22083 292 24X Fiche 50-000.84/02/02.8402060384
- 8402070136 Forwards add1 info re safe shutdown following loss of instrument bus in response to five items identified in SER Section 7 4 3 i PETRICK.N A Kansas Gas & Electric Co 84/02/02 DENTON.H R Office of Nuclear Reactor Regulation, Director 6pp 22100 159 24% Fiche 50-000,84/02/02,8402070136
- 8402070204 Forwards add1 info to resolve Power Sys Branch SER licensing confirmatory issues re physical separation of load shedder & emergency load sequencer panels, reliability of panels & separation of redundant offsite power sys circuits PETRICK,NA Standardized Nuclear Unit Power Plant System 84/02/02 DENTON.H R Diffice of Nuclear Reactor Regulation, Director 8pp 22101 059 24% Fiche 50-000,84/02/02,8402070204
- 8402070301 Forwards addl info to resolve SSER 4 outstanding items in NRC availation of environ qualification program for facilities
 PETRICK, N A Standardized Nuclear Unit Power Plant System
 84/02/02 DENTON, H R Office of Nuclear Reactor Regulation,
 Director 7pp 22095 016 24X Fiche 50-000,84/02/02,8402070301
- B402080030 Corrects 840222 itr forwarding results of monitoring diesel generator rocker arm lube oil temp during startup testing per BSER 4 Installation of rocker arm lube oil coaling sys not required Ltr issuance date corrected to 840202 PETRICK.N A. Btandardized Nuclear Unit Power Plant System 84/02/02 DETRON.H.R Office of Nuclear Reactor Regulation, Director 6pp 22132 200 24X Fiche 50-000,84/02/02,8402080030
- 8402170004 Forwards status & schedule for submitting documentation for open items; confirmatory items & license conditions reported in BERs.
 PETRICK, N A Standardized Nuclear Unit Power Plant System 84/02/14 DENTON; H R Defice of Nuclear Reactor Regulation; Director. 11pp 22300 227 24% Fiche 50-000.84/02/14.8402170004
- 8402070024 Forwards "Dissel Generator Rocker Arm Lube Gil Temp Test
 Rept 8ER Confirmatory Item 26 for Callaway & Item 8 26 for
 Holf Creek "Installation of rocker arm lube oil cooling sys
 not required for smergency dissels
 PETRICK.N A. Standardized Nuclear Unit Power Plant System
 84/02/22 DENTON.H R Office of Nuclear Reactor Regulation,
 Director 2pp 22102 341 24X Fiche 50-000.84/02/22,8402070024
- --8402070026 "Diesel Generator Rocker Arm Lube Dil Temp Test Rept SER Confirmatory Item 26 for Callaway & Item B R6 for Wolf Greek."

 ** Standardized Nuclear Unit Power Plant Bystem 84/02/27 4pp 22102:343 24X Fiche-50-000.84/02/22,8402070024
- F. Security, medical, emergency & fire protection plans
- 8402020460 Notification of 840207-09 meetings w/utils in Burlington,KS to audit site fire protection design HdLONICH,J J Licensing Branch 1. 84/01/18, YOUNOBLOOD,B J, Licensing Branch 1. 3pp 22062-166 24X Fiche: 50-482,84/01/18,8402020460
- B402070506 Requests submittal, within 30 days, of changes to physical security plan re designation of vital equipment for ECCS & RHR sys & employee screening program YUUN08L0DD, B. J. Licensing Branch 1. 84/01/27. KOESTER, O. L. Kansas & Electric Co 3pp 22141 R76 24X Fichs 50-482, 84/01/27, 8492070506

- 8402070114 Forwards "Detailed Control Room Design Review Summary Rept in response to NUREG-0737. Suppl 1 PETRICK.N A Standardized Nuclear Unit Power Plant System 84/02/02 DENTON, H R Office of Nuclear Reactor Regulation. Director 1p 22103 081 24X Fiche 50-000,84/02/02,8402070114
- --8402070117 "Detailed Control Room Design Review Summary Rept for SNUPPS," in response to Generic Ltr 82-33, NURE0-0737, Suppl 1 * Nuclear Products Co 84/02/02 92pp 22103 083 24% Fiche 50-000,84/02/02,8402070114
- B402090211 Forwards revised evaluation of State of KS radiological emergency preparedness plan for facility KRIMN.R W Federal Emergency Management Agency 84/02/02 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Fost B30103) 2pp 22158 033 24X Fichs 50-482,84/02/0.
- ~-8402070218 Revised evaluation of State of KS radiological emergency preparedness plan for facility * Federal Emergency Management Agency 84/01/05 26pp 22158 035 24X Fiche 50-482,84/02/02.8402090211
- 8402140524 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in FDR YOUNGBLOOD, B J Licensing Branch 1 84/02/03 KOESTER, G L Kansas Gas & Electric Co 2pp 22253 278 24X Fiche 50-482, 84/02/03.
- 8402220209 Forwards ltrs of agreement between util & Ransom Memorial Hosp & Coffey County Hosp Ambulance Svc re implementation of amergency plan Ltrs will be included in upcoming Rev 13 to FSAR KOEBTER, G L Kansas Oas & Electric Co 84/02/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 22338 344 24% Fichs 50-482, 84/02/16, 8402220209
- Q. Adjudicatory correspondence
- 8402080174 Interim findings on adequacy of radiological emergency response planning by state & local govts at facility
 No formal exercise of emergency response preparedness conducted Certificate of Svc encl
 GASSIDY. B P Federal Emergency Management Agency 84/01/05 27pp
 22128 263 24X Fiche 50-482.84/01/05.8402080174
- 8402070147 Answers to 840111 interrogatories & request for production of documents re emergency planning zone contention Certificate of Svc encl
 CHRISTY, W Christy, W SALAYA, M E Salava, M E , Intervenor 84/01/30 Kansas Gas & Electric Co 13pp 22100 171 24X
 Fiche 50-482,84/01/30,8402070147
- B402070197 Forwards applicants response to Nuclear Awareness Network, Inc patition for leave to intervene & request for hearing Attachments 2-5, although stamped confidential, should not be withheld from public disclosure Certificate of Svc encl.

 BAXTER, T. A Shaw, Pittman, Potts & Trowbridge BAXTER, T. A Kansas Gas & Electric Co 84/02/03 WOLFE, S. J. ANDERSON, G. C. PAXTON, H. C. Atomic Safety and Licensing Board Panel 7pp 22100 031 24X Fiche, 50-482, 84/02/03, 8402070197
- --8402070201 Responds to Nuclear Awareness Network, Inc 840119 petition for leave to intervene & request for hearing Petition untimetly unjustified & should be denied in entirety BAXTER.TA Kansas Qas & Electric Co BAXTER.TA Shaw, Pittman, Potta & Troubridge 84/02/03 Atomic Safety and Licensing Board Panel 22p 22100 038 24X Fiche 50-482,84/02/03,8402070197
- --B402070205 Affidavit of WJ Rudolph & GL Thero in support of response to Nuclear Awareness Network, Inc petition for leave to intervene & request for hearing Exhibits encl RUDDLPH.W J. THERO, D. Kansas Gas & Electric Co 84/02/03 99pp. 22100 060 24% Fiche 50-482, 84/02/03,8402070197
- B402090139 Forwards applicants & intervenors joint stipulation on contention adding City of Waverly to emergency planning zone
 BILBERG, J. E. Shaw, Pittman, Potts & Trowbridge SILBERG, J. E. Kansas Gas & Electric Co. 84/02/06 WOLFE, S. J., ANDERSON, G. C., PAXTON, H. C. Atomic Safety and Licensing Board Panel. Spp. 22163, 235 24X Fiche 50-482, 84/02/06, 8402090139
- --B402090144 Joint stipulation on contention including City of Waverly in plume exposure pathway emergency planning zone Certificate of Svc encl
 SIMPSON, J Christy, W BILBERO, J E Kansas Oas & Electric Co
 BILBERO, J E Shaw, Pittman, Potts & Troubridge 84/02/03 Opp
 821630-237, 24X Fiche 50-482,84/02/06.8402090139

- 8402130179 Forwards joint stipulation on Haverly contention Stipulation abvious 840208 filing of written direct testimony Contificate of Svc enci SILBERO.JE Shaw, Pittman, Potts & Trombridge SILBERO.JE Kansas Gas & Electric Co 84/02/08 WOLFE.S J. ANDERSON.0 C. PAXTON.H C. Atomic Safety and Licensing Board Panel 3pp 22204 139 24X Fithe 50-482.84/02/08.8402130179
- 8402140004 Response opposing Nuclear Awareness Network, Inc 840117 petition for leave to intervene & request for hearing re 84/02/08 (A/QC const practices Certificate of Svc encl KARMANIM Hearing Branch 1 (HANLE | Hearing Branch 2 84/02/08 Atomic Safety and Licensing Board Panel 18pp 22217 144 24X Fiche 50-492, 84/02/08, 8402140005
- 8402130295 Order for A Rodman to file written notice of appearance within 10 days & to file reply to applicant & NRC responses MOLFE.5 J Atomic Safety and Licensing Board Panel 84/02/09 2pp 22198 225 24% Fiche 50-482,84/02/09.8402130255
- 8402280201 Motion for addl 15 days within which to file reply & affidavits to ASLB 840207 order Notice of appearance & Certificate of Svc encl
 JORNSON.A R Nuclear Awareness Network 84/02/09 Atomic Safety and Licensing Board Fanel Spp 22400 207 24X
 Fiths 50-482,84/02/07,8402280201
- 8402280412 Motion to have status as intervenor & financial qualifications contention reinstated Certificate of Svcencl SIMPSON.J M Kansans for Sensible Energy 84/02/22 Atomic Safety and Licensing Board Panel 15pp 22407 150 24X Fiche 50-462,84/02/22.8402280412
- 8402290110 Memorandum & order holding in abequance Kansans for Sensible Energy 840222 motion for reinstatement of status as intervenor & financial qualifications contention SHUEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 84/02/28 Kansans for Sensible Energy 3pp 22426 016 24X Fiche 50-482,84/02/28.8402290110
- H General correspondence
- B402010057 Requests placement on mailing list for all NRC public documents, particularly documentation re Wolf Creek STEPHENG, 8 Nuclear Awareness Network 84/01/26 SCHAFFER, C NRC Nu Detailed Affiliation Given 2pp 22042 244 24x Fiche 90-482,84/01/26.8402010057
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8402060384 Forwards Rev 13 to FSAR Rev contains info necessary to resolve Licensing Confirmatory Issues 12 & B 13 identified in Calloway & Wolf Creek SERs, respectively PETRICK, N A Standardized Nuclear Unit Power Plant System 84/02/02 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 22083 291 24x Fiche 50-000.84/02/02.8402060384
- --8402060389 Rev 13 to FSAR
 * Standardized Nuclear Unit Power Plant System 84/02/29 281pp 22083 292 24X Fiche 50-000,84/02/02,8402060384
- O Inspection reports, IE Bulletins & correspondence
- 8402220469 Forwards corrected Pages 7 & 8 to IE Insp Rept 50-482/82-i9 SCIDLE,W C Region 4. Office of Director 63/04/21 KDESTER,G L Kansas Gas & Electric Co ip 22339 271 24% Fiche 50-482, B3/04/21.8402220465
- --8402220470 Corrected Pages 7 & 8 to IE Insp Rept 50-482/82-17 * Region 4, Office of Director 83/04/21 2pp 22339 272 24X Fiche 50-482,83/04/21,8402220465
- 8402220494 Forwards IE Insp Rept 50-462/83-38 on 831101-30 & notices of violation & deviation OACLIARDD, J E Region 4, Diffice of Director 83/12/29 NOESTER, 6 L Mansas Gas & Electric Co 2pp 22334 086 24% Fiche 50-482,83/12/29,8402220494
- --8402220498 Notice of deviation from insp on 831101-30 * Region 4, Office of Director 83/12/29 lp 22334 088 24X Fiche 50-482,83/12/29,8402220494
- --8402220500 Notice of violation from insp on 831101-30. * Region 4, Office of Director 83/12/29 2pp 22334 OB9 24X Fiche 50-482,83/12/29,8402220494

- --B402220503 IE Insp Rept 50-482/83-38 on 831101-30 Violation noted failure to properly control procedure rev & failure to follow meeting procedures Deviation noted failure to produce preoperational test procedures for review SCHUMM, W S , WHITTLESEY, K A , JOHNSON, W D Region 4, Office of Director 83/12/19 opp 22334 091 24X Fiche 50-482,83/12/29,8402220494
- 8402220471 Forwards 1E Insp Rept 50~482/83~35 on 831205~08 No violations or deviations noted GAGLIARDO, J E Region 4, Office of Director 84/01/05 KDESTER, 6 L Kansas Gas & Electric Co 2pp 22340 085 24X Fiche 50~482,84/01/05.8402220471
- --8402220475 IE Impp Rept 50-482/83-35 on 831205-08 No violations or deviations noted Major areas inspected instrumentation electrical cable terminations, electrical GC inspector qualification records & electrical nonconformance repts MULLIKIN.R P., JOHNSON.W D. Region 4. Office of Director 84/01/03 5pp 22340 087 24% Fiche 50-482,84/01/05,8402220471
- 8402220371 Ack receipt of B31223 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-482/83-33
 GAGLIARDD. J E Region 4. Office of Director 84/01/13
 KDESTER. 6 L Kansas Gas & Electric Co ip 22336
- --8402220377 Responds to NRC 83ii25 ltr re violations noted in IE Insp Rept 50-482/83-33 Corrective actions ltr issued designating superintendent of regulatory, quality & administrative svcs as alternate chairman until Apr 1784 KOESTER, G L Kansas Gas & Electric Co 83/12/23 GAGLIARDD, J E Region 4, Dffice of Director 3pp 22334 357 24X Fiche 50-482,84/01/13.8402220371
- B402220444 Ack receipt of 831222 Itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-482/83-25 GAGLIARDOJJE Region 4, Office of Director 84/01/13 KOESTER, G L Kansas Gas & Electric Co 1p 22337 347 24X Fiche 50-482,84/01/13-8402220444
- --B402220452 Responds to NRC B31122 ltr re violations noted in TE Insp Rept 50-462/B3-25 Corrective actions nonconformance rept generated to document identified welding concern & to provide appropriate controls KOESTER, 0 L Kansas Oas & Electric Co B3/12/22 OAGLIARDO, J E Region 4. Office of Director 3pp 22337 350 24X Fiche 50-482:64/01/13/8402220444
- 8402220441 Forwards IE Insp Rept 50-482/83-39 on 831201-31 & notice of violation GAGLIARDD, J E Region 4, Office of Director 84/01/23 KDESTER, G i Kansas Gas & Electric Co 2pp 22340 033 24K Fiche 50-482,84/01/23,8402220441
- --8402220445 Notice of Violation from insp on 831201-31 * Region 4, Office of Director 84/01/23 ip 22340.035 24X Fiche 50-482.84/01/23.8402220441
- B312120193 IE Info Notice 84-06. "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co. of New York, Inc. 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120153
- 8402100390 Notification of 840206 meeting w/util & SNUFPS in Bethesda.

 MD to discuss differences & similarities in design implementation process between Wolf Creek & Callaway O'CONNOR.P W Licensing Branch 1 84/02/02 YOUNGBLOOD, B J Licensing Branch 1 3pp 22210 359 24X Fiche 50-000, 84/02/02, 8402100390
- 8401190016 IE info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletín 84-01, "Cracks in BWR Mark I Containment Vent Hoaders," Syc list encl. DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 156 24X Fiche 50-000,84/02/03,8401190017.

- 8402100238 Ack receipt of 840111 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-482/83-34 GAOLIARDO, J E Region 4. Office of Director 84/02/06 MDESTER: 0 L Keneas Qas & Electric Co 1p 22178 244 24X Fiche 30-482,84/02/06,8402100238
- --8402100241 Responds to NRC B31212 ltr re violations noted in IE Insp Rept 50-482/83-34 Crrective actions procedures implemented to assure proper cable separation achieved when raceways completed KOESTER, 9 L Kansas Gas & Electric Co 84/01/11 GAGLIARDO, J E Region 4, Office of Director 3pp 22178 245 24x Fiche 50-482,84/02/04,8402100238
- 8402100230 Forwards request for relief from ASME Code, Section XI requirements for volumetric preservice insp of 18 branch connection welds in RGS Details supporting request, including identification of specific welds; encl
 BEIKEN, 8 J Standardized Nuclear Unit Power Plant System 84/02/07
 DENTOR, HR Diffice of Nuclear Reactor Repulation, Director opp
 22179 271 24X Fiche 50-000,84/02/07,8402100230
- B402220562 Ack receipt of 840127 ltr informing NRC of steps taken to correct violations & deviation noted in IE Insp Rept 50-482/83-38
 QAQLIARDO, J E. Region 4, Office of Director. 84/02/07.
 KDESTER, G L. Kansas Gas & Electric Co ip 22331 339. 24X
 Fiche. 50-482,84/02/07,8402220562
- --8402220568 Responds to NRC 831229 ltr re violations & deviation noted in IE Insp Rept 50-482/83-38 Corrective actions startup technical support group established to provide focus on preparation & approval of FSAR committed tests KOESTER, 0 L Kansas Gas & Electric Co 84/01/27 DENISE, R P Division of Resident, Reactor Project & Engineering Programs App 22331:340 24X Fiche 50-482,84/02/07,8402220562
- 8402130225 Submits info re preservice exam of HPSI sys, in response to 840125 request. Penetrant & ultrasonic test exam of 7-1/24 sampling of welds on suction side of HPBI sys will be provided for each plant REIMEN.S J Standardized Nuclear Unit Power Plant Bystem 84/02/08 DENTON, HR Office of Nuclear Reactor Regulation, Director 1p 22200:117 24X Fiche 50-000,84/02/08.8402130225
- B401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (100FR50.App R)" Syc list encl.

 JORDAN, E. L. Division of Emergency Preparedness. & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365 259 24X Fiche. 50-000, 84/02/13, 8401190041
- B402160077 Requests relief from Category 1 preservice insp requirements of Section XI re volumetric exam. Details supporting request for relief for weldments encl. Details supporting Categories 2 t 3 relief requests will be provided by 840331
 BEIKEN.B. J Standardized Nuclear Unit Power Plant System. 84/02/13
 DENTON, H.R Office of Nuclear Reactor Regulation, Director Spp 22276:198 24X Fiche 50-000, 84/02/13, 8402160077
- 8401190039 IE Info Notice 84-08. "10CFR50 7, 'Employee Protection ""
 Svc list encl
 JORDAN, E.L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14. Consolidated Edison Co. of New
 York. Inc 115pp 22365:141 24X Fiche 50-000,84/02/14,8401190039
- 8402170124 Forwards "Preservice Insp Program for RGS Piping Welds" PETRICK,N.A. Standardized Nuclear Unit Power Plant System. 84/02/14. DENTON,H R. Dffice of Nuclear Reactor Regulation, Diractor. 1p. 22298-054. 24X Fiche 50-000,84/02/14,8402170124
- --8402170135 "Freservice Insp Program for RCS Piping Halds " LEFEBURE,B.J. Westinghouse Electric Corp RATHBUN,Q P Kansas Gas & Electric Co 84/01/12 116pp 22298 055, 24X Fiche:50-000,84/02/14,8402170124
- --B402170141 "Preservice Insp Program for RCS Piping Welds."
 LEFEBVRE.B.J. Westinghouse Electric Corp. BTEPANORIC.D.M. Union
 Electric Co 84/01/24 200pp. 22278 163 24X
 Piche: 50-000, 84/02/14, 8402170124
- B401190045 IE Info Notice B3-63, Suppl 1. "Potential Failures of Westinghouse Type SA-1 Differential Relays." Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/15 Consolidated Edison Co of New York, Inc. 118pp. 22366,142. 24X Fiche 50-000.84/02/15,8401190045
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Menufacturer Recommended Value," Svc list encl. JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/21. Consolidated Edison Co. of New York, Inc. 116pp. 22366,024 24X Fiche.50-000.84/02/21,8401190062

- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies"

 Svc list encl

 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- B401190067 IE Info Notice B4~12. "Failure of Boft Seat Valve Seals "
 Svc list encl
 JURDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060 24X Fiche 50-000.84/02/27,8401190067
- B Reportable occurrences. LERs & related correspondence
- 8402010253 Part 21 rept re potential interference in full function of Bergen-Paterson strut assembly w/Pacific Scientific Comechanical shock arrestor Attempt to obtain corrective action from manufacturer unsuccessful BECKETED.WF Bergen-Paterson Pipe Support Corp 61/03/06 ORIER.B H Repion 1, Philadelphia. Office of the Director (81/03/01) 2pp 22040 205 24X Fiche 50-000.81/03/06.8402010253
- 8402220550 Interim deficiency rept re inadequate ducting installation in torsion restraint area initially reported on 831110 One elbow cut at corners & welded Welds of acceptable quality, but not authorized Evaluation will appear in monthly rept KOESTER. G L Kansas Gas & Electric Co 83/12/07 QAQLIARDO, J E Region 4, Office of Director 2pp 22333 343 24X Fiche 50-482,83/12/09,8402220550
- 8402060462 Final Bignificant Deficiency Rept (SDR) 83-12 re Class
 IE/HVAC duct combination supports located within Seismic
 Category i bldgs Supports reanalyzed using appropriate
 seismic accelerations
 8EIKEN, S.J. Standardized Nuclear Unit Power Plant System 84/01/20
 KEPPLER, J.O. Region 3, Office of Director COLLINS, J.T. Region 4,
 Uffice of Director 2pp 22083 i04 24X Fiche 50-000,84/01/20,
 8402060462
- 8402150235 PND-IV-84-003 on 840130, fire discovered in complex of trailers west of power block Local fire dept responded & fire extinguished on 840131 Licensee evaluating extent of damage JDHNSDN, W D . SCHUM, W S Region 4, Office of Director 84/01/21 p 22245 113 24% Fiche 30-482,84/01/31,8402150235
- 8402150400 Forwards monthly status rept on 10CFR50, 55(e)/Part 21 open items
 KDESTER, O.L. Kansas Gas & Electric Co 84/01/31 DENISE, R P
 Division of Resident, Reactor Project & Engineering Programs 18pp 2R242 011 24X Fiche 50-482, 84/01/31, 8402150400
- 8402130454 Final deficiency rept re undetectable failure of switch in relay testing circuits of Westinghouse solid state protection sym Initially reported on 820903 Equipment mods will be completed prior to fuel load at both plants PETRICK. N A Standardized Nuclear Unit Power Plant System 84/02/02 KEPPLER, J O Region 3. Office of Director 2pp 22202 109 24% Fiche 50-000, 84/02/02.8402130454
- 8402140475 Interim deficiency rept re safety-related field procurement by constructor not fully incorporating AE spacs Initially reported on 840103 Complete review of safety-related purchase orders initiated KOESTER, Q L Kansas Cas & Electric Co 84/02/02 GAQLIARDD, J E Region 4. Dffice of Director 2pp 22226 210 24X Fiche: 50-482,84/02/02,8402140475
- B40117004B Board Notification 84-006 provides info re alleged falsification of GC documents concerning const of safety-related HVAC units by Bahnson Co.Winston-Salem.NC EIBENHUT, D Q Division of Licensing 84/02/09 PALLADING Commissioners 7pp. 22332 187. 24X Fiche. 50-000.84/02/09, 840119046
- 8402170035 Interim deficiency rept re missing tapered pins on Fisher Control Co 24-inch butterfly valves Initially reported on 840110 Investigation continuing Next rept expected in 1 month.

 KDEBTER. J E Kansas Cas & Electric Go 84/02/07 GAGLIARDO, J E Region 4, Office of Director 2pp 22300 274 24X

 Fiche. 50-482, 84/02/07, 8402170035
- 8402170209 Final Deficiency Rept 84-01 re failure of Gould-Rundel fourposition selector switches Initially reported on 830824 & 840111, All defective switches will be replaced BEIKEN, B. J. Standardized Nuclear Unit Power Plant Bystem * Bechtel Corp. 84/02/09, KEPPLER, J. 9. Region 3, Office of Director COLLING, J. T. Region 4, Office of Director 10pp. 22299, 288 24X Fiche: 50-000, 84/02/09, 8402170209

- 02170286 Final Deficiency Rept 84-01 re Gould/Rundel selector switch failures Initially reported for Wolf Creek on 830824 & for Callaway on 830923 Generic failure results from design deficiency Manufacturer requested to rept per Part 21 SEIKEN.S J. Standardized Nuclear Unit Fower Plant System 84/02/09 KEPPLER.J. Q. Region 3. Office of Director COLLINS.J.T. Region 4. Office of Director 10pp 22297 149 24X Fiche 50-000.84/02/09.
- 02170157 Final deficiency rept re nuclear coatings in reactor bldg not applied per spec Initially reported on 800725 Coatings will be removed & reapplied on three structural steel members Addl acreen installed on truss KDESTER.G L Kansas Gas & Electric Co 84/02/10 QAGLIARDD.J E Region A, Office of Director 2pp 22299 043 24X Fiche 50-482,84/02/10.8402170157
- 9402170162 "Evaluation of Containment Coating Acceptance Tests " DARU,V C Bechtel Corp 83/12/31 18pp 22279 043 24X Fiche 50-482,84/02/10,8402170157
- 02220062 Interim Significant Deficiency Rept 8DR 83-13 re cracks in Limitorque valve operator limit switch rotors Final rept will not be available until 840331 BEIKEM, S. J. Standardired Nuclear Unit Power Plant System 84/02/13 KEPPLER, J. 9 Region 3, Office of Director COLLINS, J.T. Region 4, Office of Director ip 22337 311 24X Fiche 50-000,84/02/13, 8402220062
- 02280032 Interim deficiency rept re stainless steel pipe welded w/o filler matl Initially reported on 840120 Caused by discrepancies between purchase profess & specs KDESTER, G. Kansas Gas & Electric Co. 84/02/17 GAGLIARDO, J.E. Region 4. Office of Director 14 22401 102 24X Fiche 50-482,84/02/17,8402280032
- Hearing transcripts on non-antitrust matters
- 02220436 Trenscript of 840214 hearing in Emporie.K8 Pp 1,768-2,130 * Atomic Safety and Licensing Board Panel 84/02/14 150pp 22332 001 24X Fiche 50~482,84/02/14,8402220436
- 02220525 Transcript of 840215 hearing in Emporia, KS Pp 2,131-2,312 Atomic Bafety and Licensing Board Panel 84/02/15 181pp 22335:001 24X Fiche 50-482,84/02/15,8402220525
- 02220366 Transcript of 840216 hearing in Emporia.K8 Pp 2,313-2,371 4 Atomic Safety and Licensing Board Panel 84/02/16 60pp 22336,001 24% Fiche 30-482,84/02/16,8402220366
- KET STN-50-4B3 CALLAWAY PLANT, UNIT 1
- Application/construction stage documents & correspondence
- 02070003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel setings Forwards App A.B & C documents
 FELTON, J H Division of Rules and Records 83/10/31
 FUBENDAUM, D H Technical Analysis Corp 17pp 22173 272 24X
 Fichs 50-000,83/10/31,8402090003
- 1402090109 Trip rept of Caseload Forecast Panel 791127-30 site visite re const status Related info encl.
 LICITRA:E A Light Water Reactors Branch 3 B0/01/07 Light
 Water Reactors Branch 3 14pp 22194,146 24X
 Fiche 50-000,83/10/31,8402090003
- 12090261 Handwritten notes & calculations re const activities Related | 12070263 | Papersteen | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 10002 | 1000 80/10/31 3pp
- 120136 Board Notification 84-011.discusses NRC use of terms apprehent to safety" & "safety-related" SENHUT.D G Division of Licensing 84/01/18 PALLADING ammissioners 72pp 22R41 008 24X Fiche.50-000,84/01/18,
- 2010134 Forwards Rev 1 to "Rept on Control of Heavy Loads," updating reas of safe load path review & vendor analysis of reactor colant pump motor lifting sling.per NUREG-0612 criteria.
 ETRICK,N.A Standardized Nuclear Unit Power Plant System.
 4/01/27. DENTON:H R. Office of Nuclear Reactor Regulation,
 irector 3pp. 22038,235 24X Fiche 50-000,84/01/27,8402010134
- 402010149 Rev 1 to "Rapt on Control of Heavy Loads " * Standarfized Nuclear Unit Power Plant System 84/01/27 22pp. 22038.238 24% Fiche:50-000,84/01/27,8402010134

- 8402010230 Forwards interim justification positions for seismic & environ qualification of differential pressure indicating Barton Buitch 288A & incore thermocouples, connectors & ref junction box, per NURSE-058B Oraph withheld PETRICK, N A Standardized Nuclear Unit Power Plant System 84/01/27 DENTON, HR Diffice of Nuclear Reactor Regulation, Director. 133pp 22040 001 24X Fiche 50-000, 84/01/27.8402010250
- 8402020259 Forwards info documenting compliance w/Position 1 of Reg Ouide 1.43 consisting of description of calculation methodology & representative time-current curves for thermal capability of penetration assemblies FETRICK, N A Standardised Nuclear Unit Power Plant System. 84/01/31. BENTON, H R Office of Nuclear Reactor Regulation, Director 24pp 22055 263 24X Fiche 50-000, 84/01/31, 8402020239
- 8402060412 Forwards revised "Inservice Testing Program Callaway Nuclear Plant: " covering pumps & valves SCHNELL, D.F. Union Electric Cg 84/01/31 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 3pp 22084 322 24X Fiche 50-483,84/01/31,8402060412
- --8402040413 Revised "Inservice Testing Program, Callaway Nuclear Plant," covering pumps & valves
 WITT, W A , FAY, T D Union Electric Co 83/11/30 130pp.
 22084: 325 24% Fiche: 50-483, 84/01/31, 8402040412
- 8402090364 Requests additing to complete evaluation of request to replace water bags for radiation shielding New shielding must meet listed conditions of SRP Section 6.2.1.2. "Bubcompartment Analysis"
 YOUNGHLOOD, B J Licensing Branch i 84/01/31 KOEBTER, G L. Kansas
 Gas & Electric Co SCHNELL, D F Union Electric Co 4pp
 R2177.303 24% Fiche 50-000, 84/01/31, 8402090364
- B402010410 Generic Ltr 84-04 to all operating PWR licensees.CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing Wellimination of postulated pipe breaks in PWR primary main loops Svc list encl RIBENHUT.D 0 Division of Licensing. B4/02/01 Consolidated Edison Co of New York, Inc. 59pp 22177 087 24X Fiche 50-000,84/02/01,8402010410
- 8402030314 Forwards Rev 2 to "Rept of Independent Review of Environ Qualification Programs to NUREG-0588" Rev incorporates util 830728 response re surface temp calculation methods PETRICK: N A Standardized Nuclear Unit Power Plant Bystem. 84/02/01. DENTON:HR Office of Nuclear Reactor Regulation, Director. 4pp 22071:073 24X Fiche 80-000.84/02/01.8402030314.
- -8402030319 Rev 2 to "Rept of Independent Review of Environ Qualification Programs to NUREO-0588 " * Standardized Nuclear Unit Power Plant System. 84/02/01. 709pp. 22071:073. 24X Fichs.50-000.84/02/01.8402030314.
- 8402070159 Forwards additinfo in support of resolution of seismic qualification review team issues identified during 831205 audit Final NRC resolution achieved by program status audit Final NRC resolution achieved by program and to verification
 PETRICK.N A Standardized Nuclear Unit Power Plant Bystem,
 B4/02/02 DENTON.H R Office of Nuclear Reactor Regulation,
 Director Spp 22103.058 24X Fiche 50-000,84/02/02,8402070159.
- 8402090273 Forwards proprietary response to NRC comments on steam generator tube plugging requirements Requests that Tech Spec tube plugging limit for BNUPPB Model F steam generators be established Response withheld (ref 100FR2.790). PETRICK, N.A. Standardized Nuclear Unit Power Plant Bystem 84/02/02. Denton.H.R. Office of Nuclear Centror Regulation, Director 2pp. 22160,218 24X Fichs.50-000.84/02/02,8402090273
- --B4020902B5 Application for withholding rept. "SNUPPS Steam Generator Tube Plugging Hargin Evaluation" (ref 10CFR2 790). " WIESEMANN,R A. Westinghouse Electric Corp 84/01/20. DENTON, H R Office of Nuclear Reactor Regulation, Director. 9pp. 22160 220 24X Fiche: 50-000, 84/02/02, 8402090273
- 8402100426 Notification of 840215 meeting w/util in Reform: MO to discuss rays to GA program HOLONICH, J. J. Licensing Branch 1 84/02/06. YOUNGBLOOD, B. J. Licensing Branch 1 4pp 22211.161. 24X Fiche 50-483.84/02/06, 8402100426
- B402150515 Notification of 840216 meeting w/utils & ENUPPB in Bathesda, MD to discuss Tech Spec requirements on slave relay testing HOLONICH, J Licensing Branch 1, 84/02/07, YOUNGBLOOD, B, J. Licensing Branch 1, 4pp 22261 347 24X Fiche. 50-000, 84/02/07, 8402150515.

- 8402230327 Notification of rescheduled 840217 meeting w/utila & SNUPPS im Bethasda.MD to discuss Tech Spec requirements on slave relay testing Meeting originally scheduled for 840216 HOLONICH.J J Licensing Branch 1 84/02/07 YDUNOBLOOD.B J Licensing Branch 1 4pp 22371 173 24X Fiche 50-000.84/02/07.8402230327
- 8402270385 Notifies of intention to implement respiratory protection programs at facility MILTENBERGER Union Electric Ca 84/02/10 KEPPLER, J Region 3, Office of Director ip 22391 183 24% Fiche 50-483,84/02/10, 8402270385
- 8401190059 Board Notification 84-032 provides add1 info on environ qualification Submittal augments info in Board Notifications 84-004 & 84-007 EIBENHUT.D G Division of Licensing 84/02/13 Atomic Safety and Licensing Board Panel 10pp 22314 204 24X Fiche 50-000,84/02/13.
- B402240270 Forwards request for add1 info needed to complete evaluation of Rev 6 to FSAR Response requested within 30 days of ltr TREE 1915 YOUNGBLOOD, B. J. Licensing Branch I 84/02/14 SCHNELL, D.F. Union Electric Co. 15pp 22380 207 24X Fiche 50-483,84/02/14,
- 8401190068 Board Notification 84-033 provides "Sys Interaction Program," task action plan for Unresolved Safety Issue A-17 Distribution list encl EISENHUT.D Q Division of Licensing 84/02/16 PALLADINO Commissioners 8pp 22482 091 24X Fichs 50-000.84/02/16.

64011900AB

- B402230140 Forwards response to request for addl info on operational GA program. Response & associated text changes to FSAR Section 17.2 & App 3A will be incorporated into Rev 7 of FSAR site addendum addendum BCHNELL,D F Union Electric Co 84/02/17 DENTON,H R Office of Nuclear Reactor Regulation, Director 180pp 22362 254 24X Fiche 50-483,84/02/17,8402230140
- 840224006B Forwards responses to 840214 request for add1 info ra operational GA program Responses will be incorporated into Rev 7 to FSAR site addendum SCHNELL, D F Union Electric Co 84/02/17 DENTON, H R. Office of Nuclear Reactor Regulation. Director 191pp 22390 001 24X Fiche 50-483,84/02/17,8402240048
- 8402280258 Responds to 840131 request for clarification of replacements NUMBEROOD BY RESPONDS to BADISI request for clarification of replaceme for water bags for reactor cavity shielding Proposal to utilize rigid shielding contingent on conclusion that large break in RCS need not be postulated PETRICK,N A Standardized Nuclear Unit Power Plant System 84/02/17 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp R2399 134 24X Fiche 50-000,84/02/17,8402280258
- B402270406 Forwards supplemental info to "Environ Qualification Justifications for Interim Operation" & presents two add1 justifications re HE-1 & Reg Guide i 97. Rev 2 equipment Qualification parameters appropriate PETRICK.N A Blandardized Nuclear Unit Power Plant Bystem B4/02/23 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 22391 033 24X Fiche 50-000,84/02/23,8402270406
- 8402280392 Forwards responses to Instrumentation & Control Bys Branch issues identified during audit of facilities, covering automatic test & indication sys & boron dilution mitigating
- PETRICK, N A Standardized Nuclear Unit Power Plant System 84/02/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 22402 261 24X Fiche 50-000, 84/02/23, 8402280372
- E NRC Bafaty Evaluation Report (SER), suppls & correspondence
- 8402010216 Requests add1 info re enc1 condensed 8ER items requiring resolution. Info required by 840202 to support 840402 fuel load. List of license conditions enc1 YOUNDBLOOD, B J Licensing Branch 1 84/01/18, BCHNELL, D F Union Electric Co 9pp. 22047 352 24X Fiche 50-483,84/01/18,8402010216
- 8402020319 Forwards summary of two unresolved issues discussed in SER Bection 8.3 1.2 re undervoltage protection analyses corresponding to Sections 3 & 4 of Power Sys Branch Technical Position PSB-1
 PETRICK:N A. Standardized Nuclear Unit Power Plant Bystem
 84/01/31 DENTON.H.R Office of Nuclear Reactor Regulation,
 Director. 3pp 22055.152. 24X Fiche. 50-000, 84/01/31, 8402020319

- 8402060384 Forwards Rev 13 to FSAR Rev contains info necessary to 1020603944 Forwards Nev 13 to FSAR Nev contains info nocessary to resolve Licensing Confirmatory Issues 12 & D 13 identified in Callaway & Wolf Creek SERs, respectively PETRICK, N A Standardized Nuclear Unit Power Plant System 84/02/02 DENTON H R Office of Nuclear Reactor Regulation, Director 1p 22083 291 24x Fiche 50-000,84/02/02,8402060384
- ---8402060387 Rev 13 to FSAR * Standardized Nuclear Unit Power Plant System 84/02/27 281pp 22083 292 24X Fiche 50-000.84/02/02.8402060384
- B402070136 Forwards addl info re safe shutdown following loss of instrument bus in response to five items identified in SER Section 7 4 3 I PETRICK.N A Kansas Gas & Electric Co 84/02/02 DENTON.H R Office of Nuclear Reactor Regulation. Director App 22100 IS 24X Fiche 50-000.84/02/02.8402070136
- 8402070204 Forwards addl info to resolve Power Sys Branch SER licensing confirmatory issues re physical separation of load shedder & emergency load sequencer panels. rolliolility of panels & separation of redundant offsite power sys circuits PETRICK.N A Standardized Nuclear Unit Power Plant System 84/02/02 DENTON.H R Office of Nuclear Reactor Regulation. Director 8pp 22101 059 24X Fiche 50-000.84/02/02,8402070204
- 8402070301 Forwards addl info to resolve SSER 4 outstanding items in NRC evaluation of environ qualification program for facilities PETRICK.N A Standardized Nuclear Unit Power Plant System 84/02/02 DENION.H R Office of Nuclear Reactor Regulation. Director 9pp 22093 016 24% Fiche 50-000,84/02/02,8402070301
- 8402080030 Corrects 840222 ltr forwarding results of monitoring diesel generator rocker arm lube oil temp during startup testing per SBER 4 Installation of rocker arm lube oil cooling sys not required Ltr issuance date corrected to 840202 PETRICK.N A Standardized Nuclear Unit Power Plant System 84/02/02 DENTUN.H R Defice of Nuclear Corrected to 840202 DENTUN.H R Defice of Nuclear Reactor Regulation, Director 6pp 22132 200 24% Fiche 50-000.84/02/02.8402080030
- B402170004 Forwards status & schedule for submitting documentation for open items.confirmatory items & license conditions reported in BERs PETRICK.N A Standardized Nuclear Unit Power Plant System PETRICK, N A Standardized Nuclear Unit Power Plant System
 84/02/14 DENTON, H R Office of Nuclear Reactor Regulation,
 Director 11pp 22300 229 24X Fiche 50-000, 84/02/14, 8402170004
- 8402070024 Forwards "Diesel Generator Rocker Arm Lube Oil Temp Test
 Rept BER Confirmatory Item 26 for Callaway & Item B 26 for
 Wolf Creek " Installation of rocker arm lube oil cooling sys
 not required for emergency diesels
 PETRICK, N A Standardized Nuclear Unit Power Plant System
 84/02/22 DENTON, H R Office of Nuclear Reactor Regulation,
 Director 2pp 22102 341 24X Fiche 50-000.84/02/22,8402070024
- --8402070026 "Diesel Generator Rocker Arm Lube Dil Temp Test Rept SER Confirmatory Item 26 for Callaway & Item D 26 for Wolf Creek " ex ... Btandardized Nuclear Unit Power Plant System 84/02/29 4pp 02 343 24X Fiche 50-000,84/02/22,8408070024.
- F. Security, medical, emergency & fire protection plans
- 8401040143 Releases public version of revised emergency plan implementing procedures
 FELTON.J M Division of Rules and Records 83/12/28 Document
 Management Branch 1p 21744 306 24X Fiche 50~483,83/12/28,
 8401060163
- --B401060174 Forwards public version of Rev O to Emergency Plan Implementing Procedure EIP-ZZ-A0010, "Emergency Drills & Exercises" & Rev O to Procedure EIP-ZZ-A0020, "Maintaining Emergency Preparedness"

 KANYO.J P Union Electric Co B3/11/23 NRC No Datailed Affiliation Given 1p 21744 307. 24% Fiche 50-483,83/12/28, B80160142
- ---8401040174 Public version of Rev O to Emergency Plan Implementing Procedure EIP-ZZ-A0010, "Emergency Drills & Exercises" & Rev O to EIP-ZZ-A0020, "Maintaining Emergency Preparedness "WOLFE,R Union Electric Co 83/11/21 101pp 21744 308 24: Fiche 50-483,83/12/28,8401040143 101pp 21744 308 24X
- 8402070240 Revised emergency plan implementing procedures, including Procedures EIP-ZZ-00223 re field monitoring & EIP-ZZ-00250 re communications & recordkeeping W/840130 transmittal & receipt form # Union Electric Co 84/01/30 61pp 22102 073 24X Fiche 50-483,84/01/30,8402070240

- 8402030411 Forwards Rev 3 to physical security plan, safeguards contingency plan & security force training & qualification plan Revs withheld (ref 10CFR73 21 & 2 790) SCHNELL, D F Union Electric Co 84/02/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 22068 311 24X Fiche 50-483,84/02/01,8402030411
- 8402070114 Forwards "Detailed Control Room Design Review Summary Rept."
 in response to NUREG-0707.Suppl 1
 PETRICK.N A Standardized Nuclear Unit Power Plant System
 84/02/02 DENTON.H R Office of Nuclear Reactor Regulation,
 Birector 1p 22103 081 24X Fiche 50-000.84/02/02,8402070114
- --8402070117 "Datailed Control Room Design Review Summary Rept for SNUPPS," in response to Generic Ltr 82-33, NUREG-0737, Suppl 1

 * Nuclear Products Co 84/02/02 92pp 22103 083 24X Fiche 50-000, 84/02/02, 8402070114
- B402130163 Forwards revs to Vol 14 of emergency implementing procedures consisting of EIP index.Rev 0 to EIP-ZZ-00211, "Field Monitoring Activities & Assessment." Rev 1 to EIP-ZZ-00212, "Protective Action Recommendation" & Rev 1 to EIP-ZZ-01211

 # Union Electric Co 84/02/02 Record Services Branch (Document Control Desk) 1p 22200 049 24X Fiche 50-483,84/02/02, 8402130163
- --8402130167 Revised emergency plan implementing procedure inder * Union Electric Co 84/02/02 2pp 22200 050 24X Fiche 50-483,84/02/02,8402130163
- --8402130171 Rev 0 to Procedure EIP-ZZ-00211, "Field Monitoring Activities & Assessment " GRUNDSTROM.R Union Electric Co 84/02/02 14pp 22200 052 24X Fiche 50-483,84/02/02,8402130163
- --8402130173 Rev 1 to Procedure EIP-22-00212. "Protective Action Recommendations " QRUNDSTROM.R Union Electric Co 84/02/02 1App 22200 066 24% Fiche 50-483,84/02/02,8402130163
- --8402130178 Rev | to Procedure EIP-ZZ-01211, "Initial & Intermediate Dose Assessment " GRUNDSTROM,R Union Electric Co 84/02/02 20pp 22200 082 24X Fiche 50-483,84/02/02,8402130163
- 8402130498 Requests review changes to physical security plan identifying vital equipment onsite water resources required for ECGS within 30 days of itr receipt Bescription of measures used to protect sources also requested VOUNGBLOOD, 9 J Licensing Branch 1 84/02/02 SCHNELL, D. F Union Electric Co 2pg 22214 352 24X Fiche 50-483,84/02/02,8402130488
- B402220Bi3 Responds to B4020B request that NRC B00410 ltr describing NRC role in radiological emergency at plant be updated & reissued. NRC will respond to all significant incidents at power reactors per NUREO-072B & NUREO-0849 FAPERIELLO.C J Region 3. Office of Director B4/02/14 B6HNELL.D F Union Electric Co ip 22333 360 24% Fiche.50-483.84/02/14.8402220513
- --8402220520 Requests updated Ltr of Agreement similar in content & intent to encl NRC 800410 ltr re emergency planning SCHNELL.D F Union Electric Co 84/02/08 KEPPLER, J 9 Region 3. Office of Director 1p 22333 361 24X Fiche 50-483,84/02/14,8402220513
- ---8402220526 Describes NRC role in radiological emergency, per 800326 request. NRC plans to respond to all significant incidents at power reactors & other licensed facilities to review licensee actions, not provide assistance or resources KEPPLER, J G Region 3. Chicago, Office of the Director. 80/04/10 8CHMELL, D F Union Electric Co ip 22333 362 24X Fiche 50-483,84/02/14,8402220513
- 8402220035 Forwards responses to Youngblood 840105 ltr & detailed description of changes in Rev 6 to radiological emergency response plan, per DM Rohrer 840120 request SCHNELL, D F Union Electric Co B4/02/15 DENTON, H R Defice of Nuclear Reactor Regulation, Director 3pp 22328 042, 24% Fiche 50-483,84/02/15,8402220035
- --8402220039 Forwards response to 840105 questions raised during NRC reviaw of Rev 5A to radiological emergency response plan.
 BTILLER:M A Union Electric Co. 84/01/26 ROHRER:D M
 Director's Office. Office of Inspection and Enforcement 8pp
 22328:045 24X Fiche 50-483,84/02/15,8402220035

- --8402220041 Forwards detailed description of changes in Rev & to radiological emergency response plan.per 840120 request STILLER.M A Union Electric Co 64/01/25 ROHRER, D M Director's Office, Office of Inspection and Enforcement 37pp 22328 053 24X Fiche 50-483.84/02/15.8402220035
- 8402270440 Forwards IE Physical Protection Insp Rept 50-483/84-05 on B40130-0203 No nuncompliance identified AXELSON, W.L. Region 3, Office of Director 84/02/22 SCHNELL, D F Union Electric Co 2pp 22389 247 24X Fiche 50-483, 84/02/22, B402270440
- --8402270444 IE Physical Protection Insp Rept 50-483/84-05 on 840130-0203 No noncompliance identified Major areas inspected security plan & implementing procedures, security program audit & records Details withheld (ref 10CFR3 21)
 PIRTLE,G L , CREED.J R Region 3, Office of Director 84/02/22
 2pp 22389 249 24X Fiche 50-483,84/02/22,8402270440

O Adjudicatory correspondence

- B402100102 Order extending time until 840217 for Commission to act to review ALAB-740, -750A & -754 CHILKS J Office of the Secretary of the Commission 84/02/08 Commissioners 1p 22181 276 24X Fiche 50-483,84/02/08,840210102
- B402210101 Order extending time until 840227 for Commission to act to review ALAB-740, 750,750A & 754 CHILK: SJ Office of the Secretary of the Commission 84/02/17 Commissioners Ip 22317 235 24X Fiche 50-483,84/02/17, 8402210101
- 8402290077 Order extending time until 840305 for Commission to act to review ALAB-740.750.750A & 754 CHILK.S J Office of the Secretary of the Commission 84/02/27 Commissioners ip 22426 041 24X Fiche 50-483.84/02/27.8402290077

H General correspondence

- 8402170314 Requests tubing info from eddy current steam generator June, Jul. Aug & Sept 1783 insps DREY, K. Affiliation Not Assigned 84/02/13 DENTON, H. Dffice of Nuclear Reactor Repulation, Director 2pp 22276 154 24X Fiche 50-483.84/02/13.8402170314
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 8402060384 Forwards Rev 13 to FBAR Rev containt info necessary to resolve Licensing Confirmatory Issues 12 & B 13 identified in Callaway & Helf Creek BERN: respectively PETRICK,N A Standardized Nuclear Unit Power Plant System B4/02/02 DENTON: HR Office of Nuclear Reactor Regulation, Director ip 22083 291 24X Fiche 50-000.84/02/02.8402060384
- --8402040389 Rev 13 to FSAR * Standardized Nuclear Unit Power Plant System 84/02/29 281pp 22083 292 24X Fiche 50-000,84/02/02,8402060384

M Antitrust correspondence

- 8402100269 Informs NRC of efforts of Missouri Joint Municipal Electric Util Commission to obtain transmission agreement w/util BARNETT, B J. Missouri, State of 84/01/30, LAMBE, W NRC No Dotailed Affiliation Given 7pp 22205/327 24X Fiche 50-483,84/01/30,8402100269
- 8402130515 Forwards FR notice of finding of no significant antitrust changes & time for filing requests for reevaluation for filing & publication REGAN.W H Site Analysis Branch 84/02/06 STUCKY, S. W Docksting & Services Dranch ip 22214 285 24X Fiche 50-483, 84/02/06. B402130515
- --8402130517 Notice of finding of no significant antitrust changes 4 tist for filing requests for reevaluation Formal OL antitrust review not required REOAN.W H Site Analysis Branch 84/01/13, 3pp 22214 28& 24X Fiche 50-483,84/02/06,8402130515
- 8402130566 Advises that no significant antitrust changes in licensee activities or proposed activities have occurred subsequent to previous CP review Director's initial finding swb; to reevaluation if requested by public Notice of finding enci REGAN.W H Siting Analysis Branch 84/02/06 SCHNELL, DF Union Electric Co 52pp 22216.053 24X Fiche.50-483,84/02/06,840130564

- 8402230382 Forwards director findings & staff analysis re OL antitrust review Updated info re ongoing negotiations w/Union Electric Co requested W/o encl LAMBE, W Site Analysis Branch 84/02/08 BARNETT, 8 J Missouri, State of 1p 22376 176 24X Fiche 50-483,84/02/08,8402230382
- B402230389 Forwards director findings & staff analysis re OL antiturst review Updated info re ongoing negotiations w/Union Electric Co requested W/o enci LAMBE.W Site Analysis Branch B4/02/08 CARTER.R R Kirkwood Electric Light Dept 1p 22376 162 24X Fichs 50-483,84/02/08, 8402230389
- 8402220130 Forwards NRC staff finding of no significant antitrust changes & time for filing requests for reevaluation W/o encls
 VDQLER.B H Hearing Branch 2 84/02/13 MHEATLEY.C F Wheatl.
 Wolleson 1p 22337 272 24X Fiche 50-483.84/02/13.8402220130
- 4 Inspection reports, IE Bulletins & correspondence
- 8312120153 IE Info Notice 84-06. "Steam Dinding of Auxiliary Feedwater Pumps." Syc list ancl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co. of New York
- 8402100130 Forwards IE Insp Rept 50-483/83-27 on 831128-840107 & notice of violation STREETER. J F Region 3. Office of Director 84/01/26 8CHNELL, D F Union Electric Co 2pp 22181 312 24X Fiche 50-483,84/01/26,8402100130
- --8402100134 Notice of violation from insp on 831128-840107 STREETER,J F Region 3, Office of Director 84/01/26 2pp 22181 314 24X Fiche 50-483,84/01/26,8402100130
- --B402100138 IE Insp Rept 50-483/83-27 on 831128-B40107 Noncompliances noted failure to follow Temporary Administrative Procedure TAP-07 & to follow procedures for documentation of prependusites prior to resumption of preoperational testing WOHLD, P R , FARBERIM J , REYES, L A Region 3, Office of Director 84/01/24 11pp 22181 314 24X Fiche 50-483,84/01/26,8402100130
- 8402100370 Notification of 840206 meeting w/util & SNUPPS in Bethesda, MD to discuss differences & similarities in design implementation process between Wolf Creek & Callaway O'CONNOR.P.W Licensing Branch 1 84/02/02 YOUNGBLOOD, B J Licensing Branch 1 3pp 22210 359 24X Fiche 50-000, 84/02/02, 8402100390
- 8402180015 Forwards IE Insp Rept 50-483/83-23 on 831031-1101 & 840109-19. No noncompliance noted LITTLE.W B. Region 3. Office of Director 84/02/02 SCHNELL.D F Union Electric Co 2pp 22249 233 24X Fiche 50-483,84/02/02, 8402180015
- --B402150016 IE Insp Rept 50-483/B3-23 on 831031-1101 & 840109-19 No noncompliance noted Major areas inspected HPCI, containment spray.reactor coolant & essential svc water sys CILIMBERO, R L, KAUFMAN, P D, KEATING, D E Region 3, Office of Director 84/02/02 12pp 22249-235 24X Fiche 50-483,84/02/02,8402150015
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vahicular Excess Controls " Svc list encl JURDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche, 50-000, 84/02/03, 8401190016
- 8401190017 IE Bulletin 84-01. "Cracks in BWR Mark I Containment Vent Headers." Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co. of New York, Inc 102pp. 22177 156 24X Fichs 50-000.84/02/03.8401190017
- 8402100230 Forwards request for relief from ABME Code, Section XI requirements for volumetric preservice insplof 18 branch connection welds in RCB Details supporting request, including identification of specific walds, encl

 BEIKEN, 8. J Standardized Nuclear Unit Power Plant Bystem 84/02/07 DENTON, HR 0 Office of Nuclear Unit Power Plant Bystem 64/02/07 DENTON, HR 0 Office of Nuclear Plant Reactor Regulation, Director 6pp 22179:271 24X Fiche 50-000, 84/02/07, 8402100230
- 8402130225 Submits info re preservice exam of HPSI sys, in response to B40125 request Penetrant & ultrasonic test exam of 7-1/2% sampling of welds on suction side of HPSI sys will be provided for each plant SEIKEN, 5 J Standardized Nuclear Unit Power Plant System. B4/02/08 DENTON.H.R Office of Nuclear Reactor Regulation, Director ip 22200:119. 24% Fiche 50-000, 84/02/08, 8402130225

- 8402130367 Ack receipt of 840123 ltr informing NRC of steps taken to currect violations noted in IE Insp Rept 50-483/83-30 Revised Procedure 0S-22 re retention of air sampler calibr records will be examined in subsequent insp PAPERIELLO,C J Region 3. Office of Director 84/02/08 SCHNELL.D f Union Electric Co ip 22200 317 24X Fiche 50-483,84/02/08,8402130367
- ---8402130370 Responds to MRC 840107 ltr re violations noted in JE Insp Rept 50--483/83-30 Corrective actions revised Procedure 68-22. "Radiological Environ Monitoring Program." defining program mpt responsibilities 6CHNELL, D.F. Union Electric Co. 84/01/23 PAPERIELLO, C.J. Region 3. Office of Director 1p. 22200 318 24X Fiche 50--483. 84/02/08.8402130367
- --B402130372 Rev O to Procedure OS-22. "Radiological Environ Monitoring Program" * Union Electric Co 84/01/17 4pp 22200 319 24X Fiche 50-483,84/02/08,8402130367
- 8402270428 Forwards IE Insp Rept 50-483/84-03 on 840124-26 No noncompliance noted LITTLE:N S Region 3. Office of Director 84/02/09 SCHNELL.D F Union Electric Co 2pp 22389 319 24X Fiche 50-483.84/02/09. B402270428
- --B402270434 IE Insp Rept 50-483/84-03 on 840124-26 No noncompliance or deviations noted Major areas inspected previous insp findings & preservice insp activities, including reactor vessel intervals & structural steel & support records WARD. K D: DANIELSON, D H Region 3, Office of Director B4/02/09 Bpp 22387 321 24X Fiche 50-483,84/02/09.8402270428
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R) " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259 24X Fiche 50-000,84/02/13,8401190041
- 8402160077 Requests relief from Category 1 preservice insp requirements of Section XI re volumetric exam Datails supporting request for relief for weldments encl Details supporting Categories 2 & 3 relief requests will be provided by 840331 SEIKEN.B J Standardized Nuclear Unit Power Plant System 84/02/13 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 22276 178 24X Fiche 50-000,84/02/13,8402160077
- 8401190039 IE Info Notice 84-08, "10CFR50 7, `Employee Protection '"
 Svc list encl
 JORDAN: E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- 8402170124 Forwards "Preservice Insp Program for RCS Piping Welds"
 PETRICK.N A Standardized Nuclear Unit Power Plant System
 B4/02/14 DENTON,H R Office of Nuclear Reactor Regulation,
 Director ip 22298 054 24% Fiche 50-000,84/02/14,8402170124
- --8402170141 "Preservice Insp Program for RCS Piping Welds"
 LEFEBYRE. B J. Westinghouse Electric Corp STEPANORIC. D M Union
 Electric Co 84/01/24 200pp 22298 163 24X
 Fiche 50-000, 84/02/14, 8402170124
- B402220340 Ack receipt of 840130 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Rept 50-483/83-17
 Testing of 125-volt dc sys must be completed by fuel 104
 STREETER, J F. Region 3, Office of Director 84/02/14 8CHNELL, D F. Union Electric Ca ip 22334 190 24X Fiche 50-483,84/02/14,
- --8402220342 Responds to NRC 831110 ltr re violations noted in IE Insp. Rept 50-483/83-17 Corrective actions voltage & frequency regulation will be verified. Inverter output voltage readings will be taken at max & min dc imput voltage BCHNELL, D F Union Electric Co 84/01/30 STREETER, J F Region 3, Office of Director 5pp 22334 191 24X Fiche 50-483, 84/02/14,8402220340
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Mestinghouse Type SA-1 Differential Relays" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366 142 24X Fiche 50-000,84/02/15,8401190045.
- 8401170062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Bet Below Manufacturer Recommended Value " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc. 116pp 22366 024 24X Fiche 50-000,84/02/21,8401170062

- 8402270440 Forwards IE Physical Protection Insp Rept 50-483/84-05 on 840130-0203 No noncompliance identified AXELSON, W.L. Region 3. Office of Director 84/02/22 SCHNELL, D.F. Union Electric Co. 2pp. 22389 247 24X Fiche 50-483.84/02/22.8402270440
- --B402270444 IE Physical Protection Insp Rept 50-483/84-05 on 840130-0203 No noncompliance identified Najor areas inspected security plan & implementing procedures, security program audit & records Betails withheid (ref 10CFR/3 21) PIRTLE, 0 L. CREED, JR Region 3. Office of Director 84/02/22 2pp 22389 249 24% Fiche 50-483,84/02/22,8402270440
- 8401190066 IE Info Notice 84-11. "Training Program Deficiencies "
 Svc list encl
 JORDANNE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000.64/02/24, 8401190066
- 840;170067 IE Info Natice 84-12. "Failure of Soft Seat Valve Seals " Byr list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/27 Consolidated Edison Co of New York, Inc. 120pp 2243; 060 24X Fishe 50-000.84/02/27.8401170067
- S Reportable occurrences, LERs & related correspondence
- B402010253 Part 21 rept re potential interference in full function of Bergen-Paterson strut assembly w/Pacific Scientific Comechanical shock arrestor Attempt to obtain corrective action from manufacturer unsuccessful BECKSTED.W F Bergen-Paterson Pipe Support Corp 81/03/06 GRIER.B H Region 1. Philadelphia. Office of the Director (81/03/01) 2pp 22040 205 24X Fiche 50-000,81/03/06,8402010253
- B402060462 Final Significant Deficiency Rept (SDR) B3-12 re Class 1E/HVAC duct combination supports located within Seismit Category I bldgs Supports reanalyzed using appropriate saismic accelerations SEIKEN,5 J Standardized Nuclear Unit Power Plant System B4/01/20 KEPPLER,J G Region J. Office of Director COLLINS,J T Region 4. Office of Director 2pp 22083 104 24% Fiche 50-000,84/01/20, B402060462
- 8402130494 Final deficiency rept re undetectable failure of switch in relay testing circuits of Westinghouse solid state protection sys Initially reported on 820903 Equipment mode will be completed prior to fuel load at both plants PETRICK, N A Standardized Nuclear Unit Power Plant System 84/02/02 KEPFLER, J G Region 3, Defice of Director 2pp 2202 109 24X Fiche 50-000.84/02/02.8402130454
- 8401190048 Board Notification 84-006 provides info re allaged falsification of GC documents concerning const of safety-related HVAC units by Bahnson Go. Winston-Salem.NC FISENHUT.D 0 Division of Licensing 84/02/09 PALLADIND. GILINSKY, ROBERTS Commissioners 7pp 22332 187 24X Fiche 50-000.84/02/09.8401190048
- 8402170207 Final Deficiency Rept 84-01 re failure of Gould-Rundel fourposition selector switches Initially reported on 830624 & 84011 All defective switches will be replaced SEIKEN,S J Standardized Nuclear Unit Power Plant System * Bechtel Corp 84/02/07 KEPPLER,J 9 Region 3, Office of Director COLLINS,J T Region 4, Office of Director topp 22297 288 24X Fiche 50-000 84/02/07 8402170207
- 8402170286 Final Deficiency Rept 84-01 re Gould/Rundel selector switch failures Initially reported for Wolf Creek on 830824 % for Callaway on 830923 Seneric failure results from design deficiency Hanufacturer requested to rept ger Fart 21 SEIXEN S J Standardized Nuclear Unit Power Plant System 84/02/09 KEPPLER J & Region 3. Office of Director COLLINS J T Region 4. Office of Director 10pp 28297 149 24% Fiche 50-000.84/02/09. 8402170286
- 8402220062 Interim Significant Deficiency Rept 8DR 63-13 re cracks in Limitorque valve operator limit switch rotors Final rept will not be available until 840331
 SEIKEN, S J Standardized Nuclear Unit Power Plant System 84/02/13
 KEPPLER, J G Region 3, Diffice of Director COLLINS, J T Region 4, Office of Director 1p 22337 311 24X Fichs 50-000, 84/02/13, 84022062
- 8402240127 Part 21 rept re cracks in Limitorque limit switch molded components Cracks initially limited to component surface Recently discovered deeper cracis could affect component integrity Affected components should be replaced DENHAMIFK Limitorque Corp 84/02/21 Director's Defice, Office of Inspection and Enforcement 3pp 22373,337 24X Fichs 50-483,84/02/21.Ren2n4012

- DOCKET STN-50-486 CALLAWAY PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8402090003 Responds to FOIA request for const completion dates for puclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documents FELTON.J M Division of Rules and Records 63/10/31 ROSCHBAUM.D M Technical Analysis Corp 19pp 22193 292 24% Fichs 50-000.63/10/31.8402090003
- --B402070107 Trip rept of Caseload Forecast Panel 771127-30 site visil re const status Related info encl LICITRALE A Light Water Reactors Branch 3 B0/01/07 Light Water Reactors Branch 3 2194 166 24X Fiche 50-000,83/10/31.8402090003
- --8402090261 Handwritten notes & calculations re const activities Relation oncl
 * NRC No Detailed Affiliation Given 80/10/31 3pp
 22196 301 24X Fiche 50-000,83/10/31,8402090003
- S Reportable occurrences. LERs & related correspondence
- B402010253 Part 21 rept re potential interference in full function of Bargen-Paterson strut assembly w/Pacific Scientific Comechanical shock arrestor Attempt to obtain corrective action from manufacturer unsuccessful BECKSTED.W F Bargen-Paterson Pipe Support Corp 81/03/06 ORIER.B H Region i. Philadelphia. Diffice of the Director (B1/03/01) 2pp 22040 205 24X fiche 50-000.B1/03/06.8402010233
- DOCKET 50-496 MONTAGUE NUCLEAR POWER STATION, UNIT 1

 Q Inspection reports, IE Bulletins & correspondence
- B312120193 IE Info Notice 84-06, "Steam Binding of Auxiliary Faedwater Pumps" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc. 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120153
- B401170016 IE Info Notice B4-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000,84/02/03,8401190016
- B401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers "Svc list encl DEYQUNUR, R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co. of New York, Inc 102pp 2217 156 24X Fiche 50-000.84/02/03.8401190017.
- 8401170041 IE info Notice B4-07, "Lessons Learned From NRC Insps of Fire Protection Bafe Shutdown Sys (10CFR50, App R)" Svc list encl URDAN, E. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259 24X Fiche 50-000,84/02/13,8401170041
- 8401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '"
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc. 115pp. 22365 141 24X Fiche 50-000,84/02/14,8401170039
- 8401170045 IE Info Notice 83-63,8uppl 1, "Potential Failures of Mestinghouse Type SA-1 Differential Relays" Svc list encl JDRDAN-E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15, Consolidated Edison Co of New York, Inc 118pp 22366 142 24X Fiche 50-000,84/02/15,8401190045
- 8401190062 IE Info Notice 84-10. "Mator-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " 8vc list encl JURDANIE. L. Division of Emergency Preparedness & Engineering Response (Post \$30103) 84/02/21 Consolidated Edison Co. of New York, Inc. 116pp 22366 024. 24X Fiche 50-000,84/02/21,8401890062
- 8401190066 IE Info Notice 84-11. "Training Program Deficiencies "
 Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/24 Consolidated Edison Co of New
 York, Inc. 115pp. 22430 304 24X Fiche: 50-000,84/02/24,8401190086

- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals"
 Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 060 24X Fiche 50-000, 84/02/27, 8401190067
- DOCKET 50-497 MONTAGUE NUCLEAR POWER STATION, UNIT 2
- B312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York
- B401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp. 22114 179 24X Fiche 50-000,84/02/03,8401190016
- B401190017 IE Bullstin B4-01, "Cracks in BWR Mark I Containment Vent Headers." Byc list encl Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp. 22177 156 24X Fiche 50-000,84/02/03,8401190017.
- 8401190041 IE Info Notice 84-09, "Lassons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (100FR30, App R) " Syc list encl.

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp, 22365 259 24X Fiche 50-000,84/02/13,8401190041
- 8401190039 IE Info Notice 84-08, "10CFR50 7, `Employee Protection '"
 Svc list encl,
 JORDAN-E, L Division of Emergency Preparedness & Engineering
 Response (Post 830103), 84/02/14 Consolidated Edison Co of New
 York, Inc. 115pp 22345.141 24X Fiche 50-000,84/02/14,8401190039
- 8401190045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Mestinghouse Type SA-1 Differential Relays" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Egison Co. of New York, Inc. 118pp. 22366:142 24X Fiche 50-000,84/02/15,8401190045
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co. of New York. Inc 116pp. 22366:024 24% Fiche 50-000.84/02/21,8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies,"

 Byc list encl

 JORDAN, E. L. Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/02/24 Consolidated Edison Co. of New

 York, Inc. 115pp. 22430-304 24X Fiche 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals"
 Byc list and
 JDRDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/27. Consolidated Edison Co. of New
 York, Inc. 120pp. 22431.060 24X Fiche.50-000.84/02/27,8401190067
- DOCKET BTN-50-498 SOUTH TEXAS PROJECT, UNIT 1
- A. Application/construction stage documents & correspondence
- B402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing astimates based on inclusion of Cassicad Forecast Panel meetings, Forwards App A, B & C documents
 FELTON, J. M. Division of Rules and Records, 83/10/31, ROSEMBAUM, D.M. Tachnical Analysis Corp. 17pp 22173, 272, 24X Fiche. 50-000, 83/10/31, 8402090003
- --8402090195 Trip rept of 780405-06 sits visits re const schedule. Related info encl.
 COX.T. Light Water Reactors Branch 3, 78/08/09. Light Water Reactors Branch 3 7pp. 22196. 208. 24x Fiche: 50-000,83/10/31, 8402090003
- B402210003 Further response to FOIA request for documents re IE Insp Rept 79~19 & associated notice of proposed imposition of civil penalties notice of violation & order to show cause. Forwards App A documents. Add records being reviewed, FELTON, J M Division of Rules and Records, B3/11/29 HAMLIN, J. B. Basw, Pittman, Potts & Troubridge. 5pp. 22343:005. 24X Fiche: 50-498,83/11/29,8402210003.

- --8400210006 Notification of 800817 technical meeting w/util & Brown & Root, Inc in Bay City, TX to clarify util response to 800430 order to show cause why all safety-related work at const site should not be stopped Supporting documentation encl * NRC No Detailed Affiliation Given 83/11/29 NRC No Detailed Affiliation Given 47pp 22343 OII 24X Fiche 50-478, 83/11/27, 8402210003
- --B402210018 Forwards summary of addl commitments made at B00B19 public meeting w/util & Brown & Root Inc & correlation of util listing to NRC transcript of meeting, in response to show cause order
 HUBACEK,W G Region 4, Dallas, Office of the Director B0/07/25
 SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 2pp 22343 087 24X Fiche 50-498, 83/11/29, 8402210003
- --8402210046 Confirms 810129 telcon re substitution of ABME welding identified in 10-wk work plan sent to NRC on 801217 Welding identified in reactor containment blog will be delayed Attachment lists welding to be substituted OPREA: 0 W Houston Lighting & Power Co 81/02/12 SEYFRIT.K Region 4, Dalles, Office of the Director 5pp 22343 176 243 Fiche 50-478, 83/11/29, 8402210003
- ~-8402210048 Ack receipt of 810212 ltr transmitting documentation re substitution of ASME welding identified in 10-wk work plan, in response to NRC 800430 order to show cause SEIDLE, W C Region 4, Dallas, Office of the Director (81/03/01) 81/04/02 OFREA, Q W Houston Lighting & Power Co ip R2343 181 24X Fiche 50-498.83/11/29.8402210003
- --8402210049 Ack receipt of 810331 ltr transmitting documentation re resumption of safety-related ABME welding in response to NRC 800430 order to show cause SEIDLE.W C Region 4. Dallas. Office of the Director (81/03/01) 81/04/03 OFREA, 0 W Houston Lighting & Power Co ip 22343 183 24X Fiche 50-498.83/11/29.8402210003
- --B402210031 Requests immediate action to release ABME safety-related welding identified on Attachment 1 Work plan identifying ABME production welding will be initiated during 12-wk period Attachment 1 work will be started on B19330 DPREA: 0 M. Houston Lighting & Power Co 81/03/25 SEYFRIT, K Region 4, Dallas, Office of the Director (81/03/01) 3pp 22343 184 24X Fiche 50-498,83/11/29,8402210003
- --8402210064 Ack receipt of 810325 ltr transmitting documentation re
 12-wk work plan concerning ASME safety-related welding.in
 response to NRC 800430 order to show cause
 8EIDLE, M. C. Region 4, Dallas, Office of the Director (81/03/01)
 81/04/03 OPREA, 0 W. Houston Lighting & Power Co. 1p
 22343:187 24X Fichs 50-498,83/11/29,8402210003.
- --840221006B Forwards "Figual Rept of Review of Safety-Related Concrete."
 performed in response to Item 3(b) of NRC B00430 show cause
 order Four-phase program listed, W/o encl
 GPREA, G W Houston Lighting & Power Co B1/04/07 SEYFRIT, K
 Region 4, Dallas, Office of the Director (81/03/01) 4pp
 22343 196 24X Fiche, 50-498, 83/11/29, 8402210003
- 8402090081 Further response to FOIA request for IE Insp Rept 79-19, associated notice of proposed imposition of civil penalties, notice of violation & order to show cause Forwards App A documents. Documents also available in PDR FELTON, J M Division of Rules and Records. 63/12/20 HAMLIN, J B Ehaw, Pittman, Potts & Trowbridge App 22186:104 24X Fiche 50-000,83/12/20,8402090081
- --B009110548 Forwards request for add1 info re updating docksted GA program in response to 800430 show cause order Describes subj areas to be addressed in update description. Requests info be transmitted to util.

 HAABS.W P Quality Assurance Branch 80/08/25 80HWENCER, A Licensing Branch ip 22188 128 24X Fiche 50-000, 83/12/20, 20070000.
- ---8402070093 Requests that info re scope & significance of voids in concrete be coordinated & dispatched through L Underwood. DIRCKS.M.J. Office of the Executive Director for Operations 80/04/18. BRADFORD Commissioners ip 22188 109 24X Fiche. 50-000, 83/12/20, 8402070081
- --8402090099 Forwards Eckhardt question re facilities at Page 84 of unadited transcript, per 801016 request Comments & answers to questions at Pages 43 & 72 will be returned w/transcript by 801020.

 SUERMANN, J F Office of Congressional Affairs. 80/10/16
 BICKMIT,L. Office of the General Counsel 2pp 22188 110 24X Fiche: 50-000, 83/12/20, 8402090081

- --8402090164 Notifies that House Subcommittee on Oversight & Investigations 800729 hearing postponed to 800723 Chairman Ahearne, Stello & Thornburg scheduled as witnesses KAMMERER, C. Office of Congressional Affairs 80/09/17. AHEARNE, QILINSKY, HENDRIE Commissioners 1p 22188 166 24X Fiche 50-000,83/12/20,8402090081
- --8402090174 Forwards final testimony to be presented by Chairman Ahearne & Stello before House Subcommittee on Oversight & Investigations 800923 hearing W/o encl KAMMERER.C. Office of Congressional Affairs 80/09/23 AHEARNE, GILINSKY, HENDRIE Commissioners ip 22188 174 24X Fiche 50-000,83/12/20,8402090081
- --8402090180 Forwards unedited transcript of House Subcommittee on Oversight & Investigations 800923 hearing Corrections requested by 801016 W/o encl KAMMERER.C Diffice of Congressional Affairs 80/10/03 AHEARNE Commissioners STELLO Diffice of Inspection & Enforcement, Office of the Director SSYRIT Region 4. Dallas, Office of the Director SSYRIT Region 4. Dallas, Office of the Director SSYRIT Region 4. Dallas, Office of the
- --8402090184 Discusses info for record re 900923 hearing on facility Hearing transcript received too late to impact FYBI appropriation SUERMANN.J F Office of Congressional Affairs 80/10/16 Office of Congressional Affairs 180 24X Fiche 30-000,83/12/20.8402090081
- --840209018B Submits answers to questions at Pages 43.72 & 84 of transcript of facility hearing Matl re (mpact of continuing resolution for FYBO no longer necessary RAMMERER, C. Office of Congressional Affairs BD/10/17 AHEARNE Commissioners ip 2218B 183 24X Fiche 50~000.83/12/20, 8402090081
- 8402010033 Notification of contract execution, Mod 1 to "Review of Tornado Missile PRA South Texas Project " Contractor NBB, UMBEL, D Technical Assistance Contracts Branch FIN 8-8657 84/01/12 MATTBON, R J Division of Systems Integration (post 811005) SINGH, B. L. NRC No Datailed Affiliation Given. 1p 22048 109 24X Fight 50-498,84/01/12,8402010033.
- --8402010040 Mod 1, adding funds for FY84 & revising Article 3, to "Review of Tornado Missile PRA Bouth Texas Project."

 * Commerce, Dept. of, National Burrau of Standards. GUSTAVE.R P
 Technical Assistance Contracts Branch 84/01/12 lp 22048:110
 24X Fiche 50-498,84/01/12,8402010033
- 8402010410 Generic Ltr 84-04 to all operating PWR licensess.CP holders & applicants for CPs re safety evaluation of Wastinghouse topical repts dealing w/elimination of postulated pipe bracks in PWR primary main loops.Svc list encl EISENNUT.D G. Division of Licensing 84/02/01. Consolidated Edison Co. of New York. Inc. 59pp 22177.087 24% Fiche 50-000.84/02/01.8402010410
- 8402100022 Ack receipt of 831101 ltm transmitting description of Rev 5 to GA program
 JOHNBON.E H Region 4, Office of Director, 84/02/07 DPREA.G W
 Houston Lighting & Power Co ip 22182 149, 24%
 Fiche' 50-498,84/02/07.8402100022.
 - 12210080 Notification of 840301 & 02 meetings w/util in Houston & Bay ity.TX to discuss engineering assurance program & to nduct site tour ETTI.A Licensing Branch 3 84/02/10 KNIGNTON.6 Licensing anch 3 4pp 22321 339 24X Fiche 50-498,84/02/10,8402210080
 - 230299 Summary of 830825 meeting w/util in Bethesda, MD re F8AR and containing sail/structure (nteraction info ETTI.A Licensing Branch 3. 84/02/10 Licensing Branch 3. p. 22371-258 24X Fiche 50-498,84/02/10,8402230299
 - 2230277 Summary of 831215-16 meetings w/util. Hestinghouse & Bechtel n Bethesda. MD re TMI action plan requirements & emergency exponse facilities. Visugraphs & list of attendes and lIETTIA Licensing Branch 3 84/02/13 Licensing Branch 3. 176pp 22378-123 24X Fiche 50-498.84/02/13,8402230277.
- ang270369 Further response to FOIA request for all 1982 SECY papers wards SECYs 82-140.82-49,82-41.82-113A & 82-131 Info 'ally withheld (ref FOIA Exemption 5) Documents also able in FDM,

 M.J. H. Division of Rules and Records 84/02/13, WEISB,E R of Concerned Scientists 3pp 82411:271 24X .50-000,84/02/13,8402270369.

- --8402270380 Discusses delay in hearing schedule due to replacement of Brown & Root Inc as const contractor change of design engineer & const manager to Bechtel Inc & release of Guadrex Corp rept Info deleted FITZGERALD J A Defice of the General Counsel SECY-82-049, 82/02/04 13pp 22411 353 24X Fiche 50-000.84/02/13.84022703&
- B40227038B Summary of B30714 meeting w/util in Bethesda.MD re util engineering assurance program Program provides addl assurance re quality of design & is acceptable VIETTI.A Licensing Branch 3 84/02/13 Licensing Branch 3 4pp 22437 333 24X Fiche 50-498.84/02/13.840229038B
- --B308240400 Notification of B30914 meeting w/applicant in Bethes4a, M to present util engineering assurance program Agenda & proposed program encl VIETTI.A Licensing Branch 3 B3/08/10 KNIGHTDN, G W Licensing Branch 3 7pp 22437 337 24X Fichs 50-498.84/02/13.840227038
- F Security, medical, emergency & fire protection plans
- B402210072 Summary of B31130-1201 meetings w/util in Matagorda County, TX re physical security plan & to conduct site tour YEETTI.A Licensing Branch 3 84/02/10 Licensing Branch 3 3pp 22321 343 24X Fichs 50-498.84/02/10,8402210072
- 8402230277 Summary of B31215-16 meetings w/util.Westinghouse & Sachtel in Bathesda.MD re TMI action plan requirements & smergency response facilities Viewgraphs & list of attendese encl VIETTI.A Licensing Branch 3 84/02/13 Licensing Branch 3 176pp 22378 123 24X Fiche 50-498,84/02/13.8402230277
- 8402290405 Summary of 830909 meeting w/util in Bethesda.MD re safe shutdown scenarios & specific design features Applicant presented upgrades to RHR sys to perform cold shutdown based on Reg Guide 1 137 & Branch Technical Position 5-1 VIETTI.A Licensing Branch 3 84/02/13 Licensing Branch 3 4pp 22437 288 24X Fiche 50~498.84/02/13.8402290405
- --B308160549 Notification of 830909 meeting w/util in Bethesda. MD resals shutdown scenarios & specific design features Viewgrahs encl
 VIETTI.A Licensing Branch 3 83/08/09 KNIGHTON, G H Licensing Branch 3 30pp 22407 292 24X Ficher 50-498, 84/02/13, 8402290405
- G Adjudicatory correspondence
- 8402090081 Further response to FDIA request for IE Insp Rept 79-19, associated notice of proposed imposition of civil penalties, notice of violation & order to show cause Forwards App A documents abcoments also available in FDR FELTON.J M Division of Rules and Records 83/12/20 HAMLIN.J B Bhaw. Pittman, Potts & Troubridge 4pp 22188 104, 24X Fiche 50-000,83/12/20,8402090081.
- --8402070171 Forwards proposed rev to testimony for facility hearing. BICKHITL Defice of the General Counsel BO/09/22 AHEARNE Commissioners 3pp 22188 171 24X Fiche 50-000, 89/12/20, 8402090081
- --8402070193 Responds to Chairman Ahearne 800923 request to provide infore Bhoreham to Representative Lent June-Sept 1982 latest projected fuel load date CRANE, P. Office of the General Counsel 80/10/09. SUERMANN, J. Office of Congressional Affairs. 1p 22188, 185, 24X Fiche 50-000, 83/12/20, 8402090081
- 8402010044 Notification of contract execution, Mod 5 to "Expert Consultation & Witness Svc For Bouth Texas Project Hearings." Contractor. W Habasek PERLMAN. J Administrative Contracts Branch FIN 8-8506. 84/01/20 CGULINS. J T, CROBSMAN. W Region 4. Office of Director 1p. 22058:197 24X Fichs: 50-498.84/01/20.8402010044.
- --8402010048 Mod 5.extending period of performance at no add1 cost, to "Expert Consultation & Witness Svc for Bouth Texas Project Hearings."

 HUBACEK, N. G Hubacek, W. G HAGAN, T F Division of Contracts FIN 8-8506 84/01/20 ip 22038 200 24X Fichs 50-498.84/01/20.8402010044
- # General correspondence
- B402170489 Informs of cost to obtain NUREO/CR-2639 "Historical Extreme Winds for US Atlantic & Gulf of Mexico Coastlines "Request & payment may be sent to listed address VIETTI.A Licensing Branch 3 84/02/13 BUCHORN, K. Citizens for Equitable Utilities 1p 22312,361 24X Fiche 50-498,84/02/13, B002170489

M Utility Final Safety Analysis Report (FSAR) & amends

- E402220036 Forwards Amend 37 to FSAR, incorporating general update to FBAR Sections 12 1 & 12 2, revising responses to NRC question & adding miscellaneous FSAR test revs & editorial changes GDLDBERG, J H. Houston Lighting & Power Co. 84/02/17 DENTON, H. Office of Nuclear Reactor Regulation, Director. 3pp. 22328 090 24X Fiche 50-498,84/02/17.8402220036
- ---B402220037 Amend 37 to FSAR GOLDBERO, J H Houston Lighting & Power Co 84/02/17 207pp g2328 093 24X Fiche 50-498.84/02/17.8402220036
- B402280030 Forwards effective page listing, through Amend 37, for FBAR Listing will be updated on periodic basis HISEMBURG,M R Houston Lighting & Power Co 84/02/24 NOVAK,T M Assistant Director for Licensing 71pp 22400 322 24X Fiche 50-498,84/02/24,8402280030
- @ Inspection reports, IE Bulletins & correspondence
- E402210003 Further response to FOIA request for documents re IE Insp. Rept 79-19 & associated notice of proposed imposition of civil penalties, notice of violation & order to show cause Forwards App A documents Addl records being reviewed FELTON, J M Division of Rules and Records 83/11/29 HAMLIN, J B Shaw, Pittman, Potts & Trowbridge Spp 22343 005 24X Fiche 50-478,83/11/29,8402210003
- --8101130714 Discusses South TX Project Investigation 79-19 re QA programmatic breakdown & conducting extensive investigations Provides constructive comments to improve future NRC investigations
 PHILLIPS.H S Region 4. Dallas. Office of the Director 80/07/21
 SETDLE, W C Region 4. Dallas. Reactor Construction & Engineering Bupport Branch 5pp 22343 081 24X Fiche 50-478,83/11/29, R409210003
- --8402210012 Forwards S Phillips 800721 memo to Seidle re IE
 Investigation Rept 79-19, lessons learned S Phillips comments
 constructive & worthy of consideration
 SEYFRIT,X V Region 4, Dallas, Office of the Director 80/08/13
 STELLO, V Office of Inspection & Enforcement, Office of the
 Director 1p 22343 080 24X Fiche 50-498,83/11/29,8402210003
- --8402210017 Forwards info concerning assignment of responsibilities & priorities for Region IV followup of items re facilities show cause order W/o encl
 BEIDLE W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/09/12 SHEHMAKER, R. E NRC No Detailed Affiliation Given ip 22343 086 24X Fiche 50-498, 83/11/29, 8402210003
- --8402210020 Submits status rept for 800905-1017 of followup activities associated w/facility order.per 800624 mamo SEYFRIT.K V Region 4, Dallas. Office of the Director 80/10/20 THORNBURG.H D NRC No Detailed Affiliation Given 2pp 22343 131 24X Fiche 50-479.83/11/29.8402210003
- --8402210027 Submits four recommendations relative to closing open items & allowing restart of safety-related activities at facility, per 8how cause order PHILLIPS.H Region 4. Dallas. Office of the Director 80/10/23 SEYFRIT.K V NRC No Detailed Affiliation Given 3pp 22443,141 24X Fiche 50-478.63/11/27.8402210003
- --B402210031 Notifies that show cause items VA(2)(c) & VA(10) still open.per IE Insp 80-30. Addl info required TAPIA.J I. Region 4. Dallas, Office of the Director 80/11/20 HALL.R.E., CROSENAN, W. A., HUBACEK, W. G. Region 4. Dallas, Office of the Director 1p 22343 144 24X Fiche 50-498,83/11/29,
- --8402210036 Notifies that inquiries received re availability of investigation rept Investigation rept will be placed in facility LPDR Four extra copies of rept including enforcement package, should be sent to LPDR HAYEB.D.W Region 3, Chicago, Office of the Director 80/05/07 THORNBURG.H D Division of Reactor Construction Inspection ip 22343:145 24X Fichs.50-498,83/11/27,8402210003
- --8402210040 Submits status rept for 800721-0705 re foliowup activities associated w/facility show cause order in response to 800604 memo, Supporting details of followup described in encl.

 SEYFRIT,K V Region 4, Dellas, Office of the Director 80/09/10 THORNBURG H.D. Division of Reactor Construction Inspection, 10pp. 22343 152. 24X Fiche 50-478,83/11/29,8402210003.

- 8402090081 Further response to FDIA request for IE Insp Rept 79-19, associated notice of proposed imposition of civil penalties, notice of violation & order to show cause Forwards App A documents bocuments also available in PDR FELTON. J M Division of Rules and Records §3/12/20 HAMLIN, J B Shaw, Pittman, Patts & Troubridge 4pp 22188 104 24X Fiche 50-000.83/12/20.8402090081
- --B008210302 Recommends Ofc of Nuclear Reactor Regulation request licensee update SAR GA program, following IE Investigation Repts 50-499/79-14 & 50-499/79-14 REINMUTH, G W Division of Reactor Construction Inspection B0/08/01 HAASS.W P Quality Assurance Branch 1p 22188 124 24X Fiche 50-000,83/12/20,8402070081
- 8402080093 Add1 response to FOIA request for IE Imap Rept 79-19, notices of proposed imposition of civil penalties & violation & order to show cause App B Documents 1 & 5 partially withheld & Dacuments 2,3 & 4 withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records B3/12/23 HAMLIN, J 8 Shaw, Pittman, Potts 5 Troubridge 4pp 22172 240 24X Fiche 50-498, 83/12/23, 8402080093
- --8201300218 Forwards Citizens Concerned About Nuclear Power chronology of actions re alleged Guadrex conspiracy No significant conflict exists w/Region 4 chronology DIRCKS,W J Office of the Executive Director for Operations 82/01/11 PALLADINA J Commissioners 28pp 22172 246 24X Fiche 50-498,83/12/23,8402080093
- B312120153 IE Info Notice 84~06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JRRDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120153
- 8402070173 Forwards IE Insp Repts 50-498/83-24 & 50-499/83-24 on 831101-30 & notice of violation JOHN8ON, E H Region 4, Office of Director 84/01/30 OPREA, Q W Houston Lighting & Power Co 2pp 22102 239 24X Fiche 50-498,84/01/30,8402070173
- --8402070179 Notice of violation from insp on 831101-30 * Region 4, Office of Director 84/01/30 ip 22102 241 24X Fiche 50-498,84/01/30,8402070173
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " 8vc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers" Bvc list encl DEYUUNO.R C Director's Office Office of Inspection and Enforcement B4/02/03 Consolidated Edison Co of New York. Inc 102pp. 22177
- 8402270449 Forwards IE Insp Repts 50-498/84-03 & 50-499/84-03 on 840109-13 No violations or deviations identified JOHNSON, E H Region 4, Office of Director 84/02/09 OPREA, 8 W Houston Lighting & Power Co 2pp 22389 251 24X Fiche 50-498,84/02/09,8402270443
- --8402270446 IE Insp Repts 80-478/84-03 & 50-479/84-03 on 840109-13 No violations or deviations identified Major areas inspected const activities, including Brown & Root field-procured safety-related mat!
 BOARDMAN, J. R., CROSSMAN, W. A. Region 4, Office of Director 84/02/07 5pp 22389 253 24X Fiche 50-478,84/02/09.8402270443
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Bafe Shutdown Sys (100FR50, App. R)" Svc list encl.

 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365 259 24X Fiche 50-000, 84/02/13, 840119004)
- Yark, Inc 124pp 22365 259 24X Fiche 50-000, 84/02/13, 840119004)
 8401190039 IE Info Natics 84-08, "10CFR30.7, 'Employee Protection'"
- 8401190039 IE Info Notice 64-06, 1007-1007, Ampleograms Byc 11st encl
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24X Fiche 50-000,84/02/14.8401190039

- 8401190045 IE Info Notice 83-43. Suppl 1. 'Potential Failures of Hestinghouse Type SA-1 Differential Relays " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York Inc 118pp 22366 142 24x Fichs 50-000.84/02/15.8401190045
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list entl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York. Inc 116pp 22366 024 24X Fiche 50-000,84/02/21.8401190062
- 8401190066 fE Info Notice 84-11. "Training Program Deficiencies"

 Svc list encl

 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 64/02/24 Consolidated Edison Co of Neu
 Vori, Inc. 115pp. 22430 304 24x Fiche 50-000,84/02/24,8401190066
- 8401190067 IE Info Notice 84-12. "Failure of Soft Seat Valva Seals"

 Svc fist enc!

 JORDAN-E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/02/27 Cansolidated Edison Co of New

 York, Inc 120pp 22431 060 24X Fiche 50-000.84/02/27,8401190067
- 8402280572 Responds to NRC 840105 ltr re violations noted in IE Insp Repts 50-497/83-22 & 50-498/83-22 Corrective actions field fabrication of all safety-related & nonsafety-related anchor bolts & embed rods discontinued OPREA.G W Houston Lighting & Power Co 84/02/28 COLLINS, J T Region 4. Office of Director 13pp 22406 256 24X Fiche 50-498.84/02/28.8402280572

S Reportable occurrences, LERs & related correspondence

- B402140398 Requests add1 info re Part 21 rept dtd 831109 concerning wear ring failure in auxiliary feedwater pump furnished to facilities Info requested within 25 days PDTAPOVS.U Region 4. Office of Director 83/11/30 PATTY.D F Bingham-Willamette Co 1p 22221 250 24X Fiche 50-000.83/11/30,8402140398
- --B402140422 Supplemental Part 21 rept re wear ring failure in auxiliary feedwater pumps, per 831130 request for addl info Mear rings will be replaced on returned units w/AISI 422 wrought mat!
 List of pumps in similar svc w/same wear ring enc!
 PATTY.DF Bingham-Willamette Co 83/12/20 Region 4, Dffice of Director 2pp 22221 251 24X Fiche 50-000.83/11/30.
- 8402040385 First interim deficiency rept re pipe stress analysis design process Initially reported on B31228 Evaluation of concerns listed in engineering assurance program Design Assessment Review B3-3 continuing Next rept by 840301 DPREALO W Houston Lighting & Power Co 84/01/26 COLLINS, J T Region 4. Office of Director 2pp 22086 320 24% Fiche 30-498,84/01/26,8402040385
- B402040414 Interim deficiency rept re failure of auxiliary feedwater pump wearing rings initially reported on B31227 Written info from Bingham-Hillamette Co confirmed failure as isolated incident Item not reportable per 10CFR50 55(e) or Part 21 OPREA.G W Houston Lighting & Power Co 84/01/26 COLLINS, J T Region 4. Office of Director 2pp 22084 320 24X Fiche 50-498,84/01/26.840204041
- 8402280448 Final deficiency rapt to reactor vessel core support tolerance Initially reported on 830726 Evaluations disclosed that out-of-levelness condition on reactor vessel support ladge not reportable per 100FRSO 5516) OPREA.G W Houston Lighting & Power Co 84/02/16 COLLINS.J T Region 4. Office of Director. Spp 22407 209 24X Fiche 50-498.84/02/16.8402280448
- 840.2280149 Second interim deficiency rept re NSSS model used in seismic analysis Initially reported on 830727 Bechtel computing corresponding response spectra at attachment points within reactor coolant loop Next rept expected by 8400427 COLLINS, J T Region 4. Office of Director 5pp 22400 314 24X Fiche 50-498,84/02/17,8402280149

T Hearing transcripts on non-antitrust matters

8402090081 Further response to FOIA request for IE Insp Ropt 79-19, associated notice of proposed imposition of civil penalties, notice of violation & order to show cause Forwards App A documents Documents also available in PDR FELTON, J H Division of Rules and Records 83/12/20 HAMLIN, J B Shaw, Pittman, Potts & Trowbridge 4pp 22188 104 24X Fiche 50-000,83/12/20,8402090081

- --B402090146 Forwards draft testimony to be presented by chairman baf Subcommittee on Oversight & Investigations on 800729 Comments re testimony requested by 800722 KAMMERER.C Office of Congressional Affairs 80/07/18 AMEARME OILINSKY, HENDRIE Commissioners in 22188 135 24X Fiche 50-000,83/12/20,8402090081
- --B402070149 Forwards proposed final draft testimonies for Subcommitts on Sversight & Investigations hearing KAMMERER, C. Office of Congressional Affairs 60/07/29 AMEARME-GILINSKY, HENDRIE Commissioners 1p 22188 144 24X Fiche 50-000,83/12/20,84020900B1
- --8402090160 Draft statement of V Stello to House Subcommittee on Dversight & Investigations Pp 1-15 STELLO V Office of Inspection & Enforcement, Office of the Director 80/07/29 16pp 22188 151 24% Fiche 50-000,03/12/20
- ~-8402090168 Forwards draft addendum to Stello testimony for facility hearing Review & comments requested before 800919.

 KAMMERER, C Office of Congressional Affairs 80/09/18 AHEARNES OILINSKY, HENDRIE Commissioners 4pp 22188 167 24X Fichs 50-000, 83/12/20, 8402090081

U Congressional/Executive Correspondence

- 8402090081 Further response to FDIA request for IC Insp Rept 79-19, associated notice of proposed imposition of civil penalties, notice of violation & order to show cause forwards App A documents Documents also available in PDR FELTON.J M Division of Rules and Records 83/12/20 HAMLIN.J 3 Shaw. Pittman. Potts & Troubridge App 22188 104 24X Fiche 50-000,83/12/20,8402090081
- --B402090132 Requests that NRC be prepared to discuss QA problems at facilities at subcommittee 811117 hearing on QA
 UDALL.M K House of Rep . Interior & Insular Affairs. 81/10/30
 PALLADINO.N Commissioners 1p 22188 113 24X
 Fiche 50-000.83/12/20,8402090081
- 8402080093 Add1 response to FOIA request for IE Insp Rept 79-19, notices of proposed imposition of civil penalties & violation & order to show cause App B Documents 1 & 5 partially withheld & Bocuments 2.3 & 4 withheld (ref FOIA Exemption 5) FELTON. J M Division of Rules and Records 83/12/23 HAMLIN, J B Shaw. Pittman, Potts & Troubridge 4pp 22172 240 24% Fiche 50-498.83/12/23,8402080093
- --8402080103 Forwards revised version of proposed 1tr to Congressman Eckhardt re Absarns/Eckhardt discussion at hearing on facility Ltr clarifies major interest in Commission interaction whatate public util commissions W/o encl BICKNIT.L Office of the General Counsel 80/10/29 AHEARNE Commissioners in 22172 245 24X Fiche 50-478,83/12/23,8402080093
- 8402030487 Responds to 831208 ltr & AW Ogden 831111 ltr expressing views on nuclear power plant cost, faulty design & safety, NRC continual surveillance of facilities assures compliance w/Commission regulations W/o stated encis DIRCKS, W J Office of the Executive Director for Operations 84/01/24 BENTSEN, L Sanate Spp 22090 090 24X Fiche 50-498,84/01/24,8402030487
- --B402030489 Requests review of concerns expressed in encl AW Ogdøn ltr re facilities BENTSEN.L. Benete 83/12/08 KAMMERER, C C Office of Congressional Affairs 28pp 22090 097. 24X Fiche 30-498,84/01/24,8402030487

DOCKET STN-50-499 SOUTH TEXAS PROJECT, UNIT 2

- A Application/construction stage documents & correspondence
- 8402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caselbad Forecast Panel meetings Forwards App A.B & C documents FELTON, J M Division of Rules and Records 83/10/31 ROSENSAUM, D M Technical Analysis Corp 19pp 22193-292 24X Fiche 50-000,83/10/31,8402090003

- --8402090195 Trip rept of 780405-06 site visits re const schedule Related info encl COX.T Light Water Reactors Branch 3 78/08/09 Light Water Reactors Branch 3 7pp 22196 208 24X Fiche 50-000.83/10/31. 8402090003
- 8402210003 Further response to FDIA request for documents re IE Insp Rept 79~19 & associated notice of proposed imposition of civil penalties, notice of violation & order to show cause forwards App A documents Add1 records being reviewed FELTON, J M Division of Rules and Records 63/11/29 HAMLIN, J B Shaw, Pittman, Potts & Trowbridge 5pp 22343 005 24X Fiche 50-498,83/11/29,8402210003
- --8402210006 Notification of B00819 technical meeting w/util & Brown & Root, Inc in Bay City, TX to clarify util response to B00430 order to show cause why all safety-related work at const site should not be stopped Supporting documentation encl * NRC No Detailed Affiliation Given 83/11/29 NRC No Detailed Affiliation Given 47pp 22343 011 24X Fiche 50-478, 83/11/29, 8402210003
- --8402210018 Forwards summary of add1 commitments made at 800819 public meeting w/util & Brown & Root, Inc & correlation of util listing to NRC transcript of meeting, in response to show cause order HUBACEK, N G Region 4, Dallas, Office of the Director 80/09/25 BEIDLE, N C Region 4, Dallas, Reactor Construction & Engineering Support Branch 2pp 22043 087 24X Fiche 50-498, 83/11/29, 8402210003
- --8402210046 Confirms 810127 telcon re substitution of ASME welding identified in 10-wk work plan sent to NRC on 801217 Welding identified in reactor containment bldg will be delayed Attachment lists welding to be substituted OPREA, 0 W Houston Lighting & Power Co 81/02/12 SEYFRIT, K Region 4, Dallas, Office of the Director 5pp 22343 176 24X Fiche 50-478,83/11/29,8402210003
- --B40221004B Ack receipt of B10212 1tr transmitting documentation re substitution of ASME welding identified in 10-wk work plan, in response to NRC B00430 order to show cause SEIDLE, W C Region 4, Dallas, Office of the Director (B1/03/01) B1/04/0R OPREA, G W Houston Lighting & Power Co ip 22343 1B1 24X Fiche 50-498,83/11/29,8402210003
- --8402210049 Ack receipt of 810331 ltr transmitting documentation re resumption of safety-related ASME welding, in response to NRC 800430 order to show cause SEIDLE, W C Region 4, Dallas, Office of the Director (81/03/01) 81/04/03 OPREA, W Houston Lighting & Power Co 1p 22343:183 24X Fiche 50-498.83/11/29,8402210003
- --8402210051 Requests immediate action to release ABME safety-related welding identified on Attachment 1 Work plan identifying ABME production welding will be initiated during 12-wk period. Attachment 1 work will be started on 810330 DPREA.9 W Houston Lighting & Power Co 81/03/25 BEYFRIT, K Region 4, Dallas, Office of the Director (81/03/01) 3pp. 22343.184 24% Fiche 50-498,83/11/27.8402210003
- --8402210064 Ack receipt of 810325 ltr transmitting documentation re 12-wk work plan concerning ASME safety-related welding, in response to NRC 800430 order to show cause BEIDLE.H C Region 4, Dallas, Office of the Director (81/03/01) B1/04/03 OPREA, G.W Howston Lighting & Power Co ip. 22343.187 24X Fiche 50-498.83/11/29/8402210003.
- --8402210068 Forwards "Final Rept of Review of Safety-Related Concrete."
 performed in response to Item 3(b) of NRC 800430 show cause
 order Four-phase program listed W/o encl
 DPREA.0 W Houston Lighting & Power Co. 81/04/09. BEYFRIT.K
 Region 4. Dallas. Office of the Director (81/03/01) 4pp.
 22343 196 24X Fiche 50-498,83/11/29,8402210003
- 8402070081 Further response to FOIA request for IE Insp Rept 79-19, associated notice of proposed imposition of civil penalties, notice of violation & order to show cause Forwards App A documents Documents also available in PDR FELTON, J M. Division of Rules and Records 83/12/20 HAMLIN, J 8 Bhaw, Pittman, Potts & Trowbridge App 22188, 104 24X Fiche 50-000, 83/12/20, 8402090081
- --B00911054B Forwards request for add1 info re updating docketed GA program in response to 800430 show cause order Describes subj areas to be addressed in update description. Requests info be transmitted to util

 HAABB.W P Quality Assurance Branch. 80/08/25. BCHWENCER.A Licensing Branch 1 ip 22188.128 24X Fiche 50-000.83/12/20, B402090081

- --8402090093 Requests that info re scope & significance of voids in concrete be coordinated & dispatched through L Underwood DIRCKS,W J Office of the Executive Director for Operations 80/04/18 BRADFORD Commissioners ip 22188 109 24X Fiche 50-000.63/12/20.8402090081
- --B402090099 Forwards Eckhardt question re facilities at Page 84 of unedited transcript per 801016 request Commonts & answers to questions at Pages 43 & 72 will be returned w/transcript by 801020 SUERMANN.J F Office of Congressional Affairs 80/10/16 BICKWIT.L Office of the General Counsel 2pp 22188 110 24X Fiche 50-000.83/12/20.8402090081
- --8402070164 Notifies that House Subcommittee on Oversight & Investigations 800727 hearing postponed to 800723 Chairman Ahearne, Stello & Thornburg scheduled as uitnesses KAMMERER, C. Office of Congressional Affairs 80/09/17 AHEARNE, GILINSKY, HENDRIE Commissioners ip 22188 166 24X Fiche 50-000,83/12/20,8402090081
- --8402090176 Forwards final testimony to be presented by Chairman Ahearne & Stello before House Subcommittee on Oversight & Investigations 800923 hearing M/a encl KAMMERER, C Office of Congressional Affairs 80/09/23 AHEARNE, GLINSKY, HENDRIE Commissioners ip 22188 174 24X Fiche 30-000,83/12/20,8402099081
- --8402090180 Forwards unedited transcript of House Subcommittee on Oversight & Investigations 800923 hearing Corrections requested by 801016 M/o encl KAMMERER.C Office of Congressional Affairs 80/10/03 AHEARNE Commissioners STELLO Defice of Inspection & Enforcement, Office of the Director SEYFORT Region 4, Dallas, Office of the Director 1p 22188 179 24X Fiche 50-000,83/12/20,8402090081
- --B402070184 Discusses info for record re 800723 hearing on facility
 Hearing transcript received too late to impact FY81
 appropriation
 BUERMANN, J F Office of Congressional Affairs 80/10/16
 Office of Congressional Affairs 1p 22188 180 24X
 Fiche 80-000, 83/12/20, 8402070081
- ---8402090188 Submits answers to questions at Pages 43.72 & 84 of transcript of facility hearing Matl re impact of continuing resolution for IV80 no longer necessary KAMMERER: C Office of Congressional Affairs 80/10/17 AHEARNE Commissioners ip 22188 183 24X Fiche 50-000,83/12/20,8402090081
- B402010033 Notification of contract execution, Mod 1 to "Review of Turnado Missile PRA Bouth Texas Project" Contractor NBS UMBEL.D Technical Assistance Contracts Branch FIN 8-8637 B4/01/12 MATTSON, R. J. Division of Systems Integration (post B11005) BINGH.B.L. NRC Na Detailed Affiliation Given 1p 2204B 109 24X Fiche 50-478, B4/01/12, B402010033
- --8402010040 Mod 1,adding funds for FY84 & revising Article 3,to "Review of Tornado Missile PRA South Texas Project"

 * Commerce, Dept of, National Sureau of Standards GUSTAVE, R P
 Technical Assistance Contracts Branch, 84/01/12 ip 22048 110
 24X Fiche 50-498,84/01/12,8402010033
- 8402010410 Generic Ltr 84-04 to all operating PWR licensees, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe areaks in PWR primary main loops Svc list encl EISENHUT, D G Division of Licensing B4/02/01 Consolidated Edison Co of New York, Inc. 57pp 22177 087 24X Fiche 50-000,84/02/01.8402010410
- 8402100022 Ack receipt of 831101 ltr transmitting description of Rev 5 to GA program
 JOHNBON: H Region 4. Office of Director 84/02/07 OPREA G W
 Houston Lighting & Power Co 1p 22182 149 24X
 Fichs 80-498.84/02/07.8402100022
- 8402210080 Notification of 840301 & 02 meetings w/util in Houston & Bay City.TX to discuss engineering assurance program & to conduct site tour VIETTI,A Licensing Branch 3 84/02/10 KNIGNTON.6 Licensing Branch 3 4pp 22321,339 24X Fiche 50-498.84/02/10.8402210080
- 8402230279 Summary of B30825 meeting w/util in Bethesda, MD re FSAR amend containing soil/structure interaction info VIETTI, A Licensing Branch 3 84/02/10 Licensing Branch 3 4pp 22371 258 24X Fiche. 50-498.84/02/10.8402230297
- 8402230277 Summary of 831215-16 meetings w/util, Westinghouse & Bechtel in Bathesda, MD re TMI action plan requirements & emergency response facilities Visuographs & list of attendees encl VIETTI, A Licensing Branch 3 84/02/13 Licensing Branch 3 176pp. 22378:123 24% Fichs 50-498,84/02/13,8402230277

- 8402270369 Further response to FOIA request for all 1982 SECY papers Forwards SECYs 82-140,82-49,82-61,82-113A & 82-131 Info partially withheld (ref FOIA Exemption 51 Documents also available in PDR FELTON, J M Division of Rules and Records 84/02/13 WEISS, E R Union of Concerned Scientists 3pp 22411 271 24x Fiche 50-000,84/02/13,8402270369
- --8402270380 Discusses delay in hearing schedule due to replacement of Brown & Root Inc as const contractor, change of design engineer b const manager to Bechtel Inc & release of Quadres Corp rept info deleted FITZGERABLD, A Giffice of the General Counsel SECY-82-049 82/02/04 13pp 22411 383 24% Fache 50-000.84/02/13,8402270369
- 8402290388 Summary of 830914 meeting w/util in Bethesda, MD re util angineering assurance program Program provides additasurrance re quality of design & is acceptable VIETII.A Licensing Branch 3 84/02/13 Licensing Branch 3 4pp 22437 33 24X Fiche 50-498.84/02/13.8402290388
- --8308240400 Notification of 830914 meeting w/applicant in Bethesda.MD to present util engineering assurance program Agenda & proposed program encl
 VIETTI.A Licensing Branch 3 83/08/10 KNIGHTOK, Q W Licensing Branch 3 7pp 22437 337 24X Fiche 50-496.84/02/13.8402290388
- F Security, medical, emergency & fire protection plans
- 8402210072 Summary of 831130-1201 meetings w/util in Matagorda County TX re physical security plan & to conduct site tour VIETTI-A Licensing Branch 3 84/02/10 Licensing Branch 3 3pp 22321 343 24X Fiche 50-498.84/02/10,8402210072
- B402230277 Summary of B31215-i6 meetings w/util.Westinghouse & Bechtel in Bethesda.MD re TMI action plan requirements & emergency response facilities Viewgraphs & list of attendees enci VIETTI.A Licensing Branch 3 B4/02/13 Licensing Branch 3 176pp 22378 123 24x Fiche 50-498.84/02/13.8402230277
- 8402270403 Summary of 830707 meeting w/util in Bethesda.HD re safe shutdown scenarios & specific design features Applicant presented upgrades to RHR sys to perform cold shutdown based on Reg Guide 1 137 & Branch Technical Position 5-1 VIETTI-A Licensing Branch 3 84/02/13 Licensing Branch 3 4pp 22437 288 24X Fiche 50-498.84/02/13.8402290403
- --8308160549 Notification of 830909 meeting w/util in Bethesda.MD re-safe shutdown scenarios & specific design features Viewgrahs encl VIETTI.A Licensing Branch 3 83/08/09 KNIGKTCN.G W Licensing Branch 3 30pp 22437 292 24% Fiche 50-498.84/02/13,8402290409

G Adjudicatory correspondence

- 8402070081 Further response to FOIA request for IE Insp Rept 79-19, associated notice of proposed imposition of civil penalties, notice of violation & order to show cause Forwards App A documents Documents also available in PDR FELTON, J N Division of Rules and Records 83/12/20 HAMLIN, J B Shaw, Pittman, Potts & Troubridge App 22188 104 24X Fiche 50-000,83/12/20,8402090081
- --8402090171 Forwards proposed rev to testimony for facility hearing BICKMIT, L Office of the General Counsel 80/07/22 AMEARNE Commissioners 3pp 22188 171 24X Fiche 50-000,83/12/20,8402090081
- --8402070193 Responds to Chairman Ahearne 800923 request to provide info re Shoreham to Representative Lent June-Sept 1982 latest projected fuel load data GRAME.P Office of the General Counsel 80/10/09 SUERMANN, J Office of Congressional Affairs 1p 22188 185 24X Fiche 50-000, 83/12/20, 8402070081
- 8402010044 Notification of contract execution.Mod 5 to "Expert Consultation & Witness Syc for South Texas Project Hearings "Contractor W Habacek PERLMAN.J Administrative Contracts Branch FIN B-8504 84/01/20 CDLLINS.J T, CROSSMAN.W Region 4. Office of Director ip 22058 199 24X Fiche 50-498.84/01/20.8402010044
- --BA02010048 Mod 5.extending period of performance at np add1 cost, to
 "Expert Consultation & Mitness 8vc for Bouth Texas Project
 Hearings"
 HUBACEK, H G Hubacek, W G HA0AN, T F Division of Contracts
 FIN B-8306 84/01/20 1p 22058 200 24% Fiche 50-478, 84/01/20,
 R402010044

- H General correspondence
- 8402170489 Informs of cost to obtain NUREO/CR-2639 "Historical Extreme Winds for US Atlantic & Gulf of Mexico Coastlines " Request & payment may be sent to listed address VIETI.A Licensing Granch 3 84/02/13 BUCHORN.K Citizens for Equitable Utilities 1p 22312 361 24X Fiche 50-498,84/02/13, BAD2170889
- K Utility Final Bafety Analysis Report (FSAR) & Amends
- 8402220036 Forwards Amend 37 to FSAR, incorporating general update to FSAR Sections 12 i & 12 2. revising responses to NRC question & adding miscellaneous FSAR test revs & editorial changes GCLDBERG, J H. Houston Lighting & Power Co. 84/02/17 DENTON, H. Office of Nuclear Reactor Regulation. Director 3pp 22328 090 24X Fiche 50-498, 84/02/17, 8402220036
- --8402220037 Amend 37 to FSAR GOLDBERG.J H Houston Lighting & Power Co 84/02/17 207pp 23328 093 24X Fiche 50-498,84/02/17.8402220034
- 840228030 Forwards affective page listing through Amend 37, for FBAR Listing will be updated on periodic basis WIBENBURG, M R Houston Lighting & Power Co 84/02/24 NOVAK, T M Assistant Director for Licensing 71pp 22400 322 24X Fiche 50-498.84/02/24,8402280030
- Q Inspection reports, IE Bulletins & correspondence
- 8402210003 Further response to FDIA request for documents re IE Insp Rept 79-19 & associated notice of proposed imposition of civil penalties, notice of violation & order to show cause Forwards App A documents AddI records being reviewed FELTON, J II Division of Rules and Records 83/11/29 HAMLIN, J 8 Shaw, Pittman, Potts & Troubridge 9pp 22343 005 24X Fiche 50-478,83/11/29,8402210003
- --BI01130714 Discusses South TX Project Investigation 79-19 re GA programmatic breakdoun & conducting extensive investigations Provides constructive comments to improve future NRC investigations PHILLIPS, H B Region 4, Dallas, Office of the Director BO/07/21 BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch Spp 22343 081 24X Fiche 50-498,83/11/27,8402210003
- --8402210012 Forwards S Phillips 800721 memo to Seidle re IE Investigation Rept 79-19, lessons learned S Phillips comments constructive & worthy of consideration SEYFRIT.K V Region 4, Dallas, Office of the Director BO/08/13 STELLO, V Office of Inspection & Enforcement, Office of the Director 1p 22343 080 24X Fiche 50-498,83/11/29.8402210003
- --8402210017 Forwards info concerning assignment of responsibilities & priorities for Region IV followup of items re facilities show cause order W/o enc!
 SEIDLE.W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/09/12 SHEWMAKER.R E NRC No Detailed Affiliation Given 1p 22343 086 24% Fiche 50-498,83/11/29,8402210003
- --BA02210020 Submits status rept for B00905-1017 of followup activities associated w/facility order.per 800624 memo SEYPRIT, K V Region 4, Dallas. Office of the Director 80/10/20 THORNBURG.H D NRC No Detailed Affiliation Given 2pp 22343 131 24X Fiche 50-498.83/11/29.8402210003
- --8402210027 Submits four recommendations relative to closing open items & allowing restart of safety-related activities at facility, per show cause order PHILLIPS, H Region 4, Dallas, Office of the Director 80/10/23 SEYFRIT, K V NRC Na Detailed Affiliation Given 3pp. 22343 141 24X Fiche 30-498.83/11/29.8402210003
- --8402210031 Natifies that show cause items VA(2)(c) & VA(10) still open.per IE Insp 80-30 Addl info required TAPIA.J I Region 4, Dellas, Office of the Director 80/11/20 HALL.R E., CRUSSMAN.W A., HUBACEK.W O Region 4, Dallas, Office of the Director 1p 22343 144 24X Fiche 50-498.63/11/27, 8402210003
- --8402210034 Notifies that inquiries received re availability of investigation rept investigation rept will be placed in facility LPDR Four extra copies of rept.including enforcement package, should be sent to LPDR HAYES, b W Region 3, Chicago, Office of the Director 40/05/07 THURNBURG, H D Division of Reactor Construction Inspection ip 22343 145 24X Fiche 50-478,83/11/29,8402210003

- --8402210040 Submits status rept for 800721-0905 re followup activities associated w/facility show cause order in response to 800604 memo Supporting details of followup described in
 - encl
 BEYFRIT,K V Region 4, Dallas, Office of the Director 80/09/10
 THORNBURG.H D Division of Reactor Construction Inspection 10pp
 22343 152 24X Fiche 50-498 83/11/29,8402210003
- 8402090081 Further response to FOIA request for IE Insp Rapt 79-19, associated notice of proposed imposition of civil penalties, notice of violation & order to show cause Forwards App A documents also available in PDR FELTON. J M Division of Rules and Records 83/12/20 HAMLIN, J Shaw, Pittman, Potts & Troubridge App 22188 104 24X Fiche 50-000.83/12/20.8402090081
- --8008210302 Recommends Ofc of Nuclear Reactor Regulation request licenses update SAR GA program, following IE Investigation Repts 50-498/79-14 & 50-499/79-14 REINMUTH, O W Division of Reactor Construction Inspection 80/08/01 HAASS, W P Quality Assurance Branch ip 22188 124 24X Fiche 50-000, 83/12/20, 8402090081
- 8402080073 Addl response to FOIA request for IE Insp Rept 79-19, notices of proposed imposition of civil penalties & violation & order to show cause App B Documents 1 & 5 partially withheld & Documents 2.3 & 4 withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records 83/12/23 HAMLIN,J B Shaw, Pittman, Potts & Troubridge 4pp 22172 240 24X Fiche.50-498,83/12/23,8402080093
- --B201300218 Forwards Citizens Concerned About Nuclear Power chronology of actions re alleged Guadrex conspiracy No significant conflict sriets w/Region 4 chronology DIRCKB,W J Office of the Executive Director for Operations 82/01/11 PALLADINO,N J Commissioners 28pp 22172 246 24X Fiche 50-498,B3/12/23,8402080093.
- B312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps." Bvc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc. 120pp 22058 001 24X Fiche 50-000,84/01/25,8312120153
- B402070173 Forwards IE Insp Repts 50-498/83-24 & 50-499/83-24 on B31101-30 & notice of violation JOHNSON,E.H. Region 4, Office of Director 84/01/30 OPREA,O W Houston Lighting & Power Co 2pp 22102 239 24X Fiche: 50-498,84/01/30,8402070173
- ---8402070179 Notice of violation from insp on 831101-30 * Region 4. Office of Director 84/01/30 ip 22102 241 24X Fiche:50-498,84/01/30,8402070173
- --B402070191 lE Insp Repts 50-498/83-24 & 50-499/83-24 on 831101-30 Violation noted failure to follow std test method for soil samples w/max size of 3/B inch TOHLINSON,D P, TAPIA,J I, CROSEMAN,W A Region 4, Office of Director. 84/01/23 7pp 22102.242 24X Fiche 50-498,84/01/30, B402070173
- 8401190016 IE Info Notice 84-07. "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl.
 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). B4/02/03. Consolidated Edison Co. of New York. Inc. 119pp 22114 179 24X Fiche 50-000.84/02/03,8401190014
- 8401170017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers," Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement, 84/02/03 Consolidated Edison Co of New York, Inc 102pp. 22177:156 24X Fiche 50-000,84/02/03,8401170017
- 8402270443 Forwards IE Insp Repts 50-478/84-03 & 50-479/84-03 on 840109-13. No violations or deviations identified JOHNSON, E. H. Region 4, Office of Director. 84/02/09 OPREA, G W Houston Lighting & Power Co. 2pp. 22389 251 24X Fiche: 50-498,84/02/09,8402270443
- --B402270446 IE Insp Repts 50-498/84-03 & 50-499/84-03 on 840109-13 No violations or deviations identified Major areas inspected const activities, including Brown & Root field-procured safety-related matl BORDMAN, J R , CROSSMAN, W A Region 4, Office of Director 84/02/07 5pp. 22389 233 24X Fiche 50-498/84/02/07,8402270443
- B401190041 IE Info Notice B4-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Bys (10CFR50, App R)" Svc list encl.
 JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B30103). B4/02/13. Censolidated Edison Co. of New York, Inc. 124pp 22365, 259. 24% Fiche 50-000, 84/02/13, 8401190041

- B401190039 IE Info Notice B4-08, "10CFR50 7, 'Employee Protection '"
 Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 630103) B4/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24X Fiche 50-000,84/02/14,8401190039
- B401190045 JE Info Notice B3-63, Suppl 1, "Potential Fajiures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN, E 1. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc 118pp 22366 142 24X Fiche 50-000,84/02/15,8401190045
- B401190062 IE Info Notice B4-io. "Motor-Operated Valve Torque Switched Set Below Manufacturer Recommended Value" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830)03) B4/02/21 Consolidated Edison Co of New York, Inc 114pp 22366 024 24X Foche 50-000.84/02/21.8401190062
- 8401190066 IE Info Notice 84-11. "Training Program Deficiencies " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/24 Consolidated Edison Co of New York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,840119006
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
 Svc list encl
 JORDAN:E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp 22431 040 24X Fiche 50-000.84/02/27,8401190067
- 8402280572 Responds to NRC 840105 ltr re violations noted in IE Insp. Repts 50-498/83-22 & 50-498/83-22 Corrective actions field fabrication of all safety-related & nonsafety-related anchor bolts & embed rods discontinued OPREA.0 W Houston Lighting & Power Co 84/02/28 COLLINS.J T Region 4, Office of Director 13pp 22406 256 24X Fiche 50-498.84/02/28.8402280572
- B Reportable occurrences, LERs & related correspondence
- 8402140378 Requests add1 info re Part 21 rept dtd 831108 concerning wear ring failure in auxiliary feedwater pump furnished to facilities info requested within 25 days POTAPOVS, U Region 4, Office of Director 83/11/30 PATTY, D F Bingham-Willamette Co ip 22221 250 24% Fiche 50-000, 83/11/30, 8402140378
- ---B402140422 Supplemental Part 21 rept re wear ring failure in auxiliary feedwater pumps, per 831130 request for add1 info Wear rings will be replaced on returned units w/AIS1 420 wrought mat1 List of pumps in similar syc w/same wear ring encl PATTY.D F Bingham-Willamette Co 83/12/20 Region 4, Office of Director 2pp 22221 251 24X Fiche 50-000.83/11/30. B402140378
- 84020603B5 First interim deficiency rept re pipe stress analysis design process Initially reported on B31228 Evaluation of concerns listed in engineering assurance program Design Assessment Review 82-3 continuing Next nept by 840301 OPREA,0 W Houston Lighting & Power Co 84/01/24 COLLINS.J T Region 4, Office of Director 2pp 22086 320 24X Fiche 50-498.84/01/26.8402060385
- B402060414 Interim deficiency rept re failure of auxiliary feedwater pump wearing rings Initially reported on 831227 Written (nfo from Bingham-Willamette Co confirmed failure as isolated incident Item not reportable per 10CFR80 55(e) or Part 21 OPREA:0 W Houston Lighting & Power Co 84/01/26 COLLING.J T Region 4. Office of Director 2pp 22084 320 24X Fiche.50-498.84/01/26.8402060414
- 8402280149 Second interim deficiency rept re NBSB model used in seismic analysis Initially reported on 830727 Bechtel computing corresponding response spectra at attachment points within reactor cooland loop Next rapt expected by 840427 OPREA:0 W Houston Lighting & Power Co 84/02/17 COLLINS.J T Region 4, Office of Director 5pp 22400 314 24X Fiche 50-498,84/02/17.8402280149
- T Hearing transcripts on non-antitrust matters
- 8402090081 Further response to FOIA request for IE Insp Rept 79-19, associated notice of proposed imposition of civil penalties, notice of violation & order to show cause Forwards App A documents Documents also available in FDR FELTON.J M Division of Rules and Records 83/12/20 HAMLIN,J B Shaw, Pittman, Potts & Trowbridge App 22188 104 24% Fiche 50-000.83/12/20.8402090081

- --8402070144 Forwards draft testimony to be presented by chairman before Subcommittee on Oversight & Investigations on 800727 Comments re testimony requested by 800722 KAMMCHERIC Office of Congressional Affairs 80/07/18 AHEARNE. GILINSKY, HENDRIE Commissioners ip 22188 135 24% Fiche 80-000,83/12/20,8402090081
- --B402090149 Forwards proposed final draft testimonies for Subcommittee on Oversight & Investigations hearing KAMMERER, C. Office of Congressional Affairs 80/07/29 AHEARNE, OILINSKY, HENDRIE Commissioners ip 22188 144 24X Fiche 50-000,83/12/20,8402090081
- --8402070155 Draft statement of JF Ahearne to House Subcommittee on Gversight & Investigations Pp 1-5 AHEARNE.J F Commissioners 80/07/27 6pp 22188 145 24X Fiche 50-000.83/12/20.8402090081
- --8402090160 Draft statement of V Stello to House Subcommittee on Oversight & Investigations Pp 1-15 STELLO V Defice of Inspection & Enforcement. Office of the Director 80/07/29 16pp 22188 151 24% Fiche 50-000,83/12/20.
- --8402090168 Forwards draft addendum to Stello testimony for facility hearing Review & comments requested before 800919 KAMMERER, C. Office of Congressional Affairs 80/09/18 AHEARNE. GLLINSKY, HENDRIE Commissioners App 22188 147 24X Fiche 50-000.83/12/20.8402090081
- U Congressional/Executive Correspondence
- 8402090081 Further response to FOIA request for IE Insp Rept 79-19, associated notice of proposed imposition of civil penalties, notice of violation & order to show cause Forwards App A documents Documents also available in PDR FELTON.J M Division of Rules and Records 83/12/20 HAMLIN.J Shaw, Pittman, Potts & Troubridge 4pp 22188 104 24X Fiche 50-000,83/12/20,8402090081 HAMLIN J B
- ---8402090102 Requests that NRC be prepared to discuss OA problems at facilities at subcommittee Bill19 hearing on GA
 UDALL.M K House of Rep , Interior & Insular Affairs. B1/10/30
 PALLADING.N Commissioners 1p. 2218B 113. 24X
 Fiche 50-000,83/12/20,8402090081
- B402080093 Add1 response to FDIA request for IE Insp Rept 79-19, notices of projosed imposition of civil penalties & violation & order to show cause App B Documents I & 5 partially withheld & Documents 2,3 & 4 withheld (ref FDIA Exemption 5) FELTON, J M Division of Rules and Records B3/12/23 HAMLIN, J B Bhaw, Pittman, Potts & Troubridge 4pp 22172 240 24% Fiche 50-498.83/12/23,8402080093
- --8402080:103 Forwards revised version of proposed ltr to Congressman Eckhardt re Ahearne/Eckhardt discussion at hearing on facility Ltr clarifies major interest in Commission interaction w/state public util commissions W/o encl BICKNITL Office of the General Counsel 80/10/27 AHEARNE Commissioners ip 22172 245 24X Fiche 50-498,83/12/23, 8402080023
- B4020304B7 Responds to 831208 ltr & AW Ogden B31111 ltr expressing views on nuclear power plant cost, faulty design & safety NRC continual surveillance of facilities assures compliance w/Commission regulations H/o stated encis DIRCKB, M J. Office of the Executive Director for Operations 84/01/24 BENTSEN.L Senate. Bpp 22090 090 24X iche 50-498,84/01/24,8402030487
 - 3402030499 Requests review of concerns expressed in encl AW Ogden 1tr re facilities BENYBEN.L. Senate 83/12/08 KAMMERER, C.C. Office of Congressional Affairs 28pp 22090 097 24X Fiche 50-498,84/01/24.8402030487
 - CKET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3 Application/construction stage documents & correspondence
- 8401170065 Partial response to FOIA request for six categories of documents re facilities Forwards documents listed in Apps A & B Documents also available in PDR W/o App A documents. FELTON, J M Division of Rules and Records. 83/10/24. ANDERSON, S I. Garvey, Schubert, Adams & Barer. 4pp. 21838 003 24X Fiche 50-397,83/10/24,8401170065.
 - 101170083 "Level 1 Mgt Info Rept " Related info enci. * Washington Public Power Supply System. 80/01/30 21838 106 24X Fiche 50-397,83/10/24,8401170065 72pp.

- 8402090003 Responds to FOIA request for const completion dates for NO 2090003 Responds to FOLIA request for Const campletion data nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forscast Panel meetings Forwards App A.B & C documents FELTON.J M Division of Rules and Records 83/10/31 ROSENBAUM.D M Technical Analysis Corp 19pp 22193 292 Fichs 50-000.83/10/31.8402090003 22193 292 R4X
- --8402070301 Handwritten graph & calculations re const activities * NRC No Detailed Affiliation Given 82/09/01 3pp 22174 328 24X Fiche 50-000,83/10/31,8402070003
- 8402270295 FOIA request for five categories of documents re mothballed moclear const projects BELL:N Nuclear Information & Resource Service 83/11/23 Office of Administration 29p 22395 102 24X Fiche 50-508,83/11/23, 8402270295
- B402080430 Forwards, for info. "Rept to Governor J Spellman of State of WA & Covernor V Atiyeh of State of CR " Rept provides recommendations for solution to major problems involving or arising from WPPSS SCRENSEN. C Washington Public Power Supply System B3/12/OB E13ENNUT.D O Division of Licensing ip 22168 284 24X Fiche 50-397, B3/12/OB, B402080430
- --8402080435 "Rept to Governor J Spellman of State of WA & Governor V Atiyeh of State of OR"

 LUCE, C F , CARLSON, E E , SCHWAB, H M Affiliation Not Assigned 83/11/30 68pp 22168 287 24X Fiche 50-397,83/12/08,8402080430
- B402210453 Summary of 831025 meeting w/util in Bethesda.MD re licensing activities Program director & licensing project manager introduced VIETTI.A Licensing Branch 3 84/02/13 Licensing Branch 3 3pp 22344 114 24X Fiche 50-508.84/02/13.8402210453
- --8310270516 Notification of 831025 meeting w/util in Bethesda: MD to stuaronto Nottrication or B310x3 meeting w/util in Betheeda.MD to discuss licensing activities & introduce program director & licensing project manager VIETTI.A Licensing Branch 3 B3/10/17 KNIGHTON.0 W Licensing Branch 3 2pp 22344 11B 24X Fiche 50-50B,84/02/13,8402210453
- 8402230378 Summary of 830724-30 meetings w/util & Ebasco 8vcs, Inc in New York. NY re structural design audit, Audit findings transmitted to applicant by ltr dtd 831102 List of attenders & viewgraphs encl VIETI.A Licensing Branch 3 84/02/13 KNIGHTON.G W Licensing Branch 3 74pp 22376 066 24X Ficher 50-508.84/02/13.8402230398
- B402230444 Summary of 930B16 meeting w/util at site re structural design audit & to conduct tour of plant site Attendee list & viewgraphs encl VIETTI:A Licensing Branch 3 84/02/13 Licensing Branch 3 23pp 22371 197 24X Fiche 50-50B,84/02/13,8402230444
- --8308180790 Notification of 830816 meeting w/applicant in Sapsop,WA to familiarize structural reviewers w/site in preparation for structural design audit scheduled for wk of 830926. Agenda encl VIETTI,A Licensing Branch 3 83/08/09 KNIGHTON,6 H Licensin Branch 3 2pp. 22371 221 24X Fiche 50-508,84/02/13,8402230444 Licensing
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8402170010 Forwards DES DL stage for approval DES provides second assessment of environ impact associated w/facility DES scheduled for publication on 831223 W/o encl NDVAK.T M. Assistant Director for Licensing KNIGHTON.G W., VIETTI, A Licensing Branch 3 83/12/27, EISENHUT.D G Division of Licensing. 1p 22319 149 24X Fiche 50-508,83/12/27,8402170010
- 8402030054 Forwards DES & FR notice of availability Any design or other changes requiring rev to DES will be reviewed W/o Environmental Protection Agency. 3pp 22071 096 24X Fiche 50-508, 84/01/13, 8402030054.
- 8402020122 Ack receipt of DES for facility on 840116 Correct date for receipt of comments should be calculated from FR notice date of 840127 & extended until 840312 Ltrs should be sent to inform of correct date HIRSCH A Environmental Protection Agency 84/01/30 KNIGHTD Office of Nuclear Reactor Regulation, Director ip 22036 195 Fiche, 50-508, 84/01/30, 8402020122. KNIGHTON, O
- 8402270362 Submits comments on DES (NUREG-1033) re operation of facility Fuel cycle impact not completely described DDHERTY, J. F. Affiliation Not Assigned 84/02/19, VIETTI.A Division of Licensing, 2pp. 22391,189 24X Fiche 50-508,84/02/19,8400270360

F Security, medical, emergency & fire protection plans

- 8402210388 Summary of 830819 meeting w/util re physical security plan per BRP (NUREG-0800). Section 13 & No major safeguards issues identified VIETTI, A Licensing Branch 3 84/02/03 Licensing Branch 3 3pp 22363 075 24X Fiche 50-508.84/02/03,8402210388

O Adjudicatory correspondence

- B402080132 Requests response re omission of ABLB & parties on svc list as recipients of Board Notifications 84-004 & B4-007 re environ qualification of equipment by Sandia Labs Related correspondence
 BELL.N Coalition for Safe Power 84/01/27 DIRCKS,W Office of the Executive Director for Operations 1p 22132 144 24X
 Fiche 30-460.84/01/27.8402080132
- 8402070053 Response supporting Coalition for Safe Power 840110 suppl to petition for leave to intervene Certificate of Svc PRCI HABBELL, D F Hearing Branch 4 84/02/02 Atomic Safety and Licensing Board Panel 11pp 22103 026 24X Fiche 50-508.84/02/02.8402070053
- B402080057 Response opposing intervenor B40110 suppl to petition for leave to intervene Petitioner failed to establish solid basis. Certificate of Svc encl REYNOLDB, N 8 Hashington Public Power Supply System REYNOLDB, N 8 Bishop, Liberman, Cook, Purcell & Reynolds 84/02/06 Atomic Barety and Licensing Board Panel 21pp 22128 051 24X Fiche. 50-508, 84/02/06, 8402080057
- 8402280458 Notifies ASLB & parties of intent to file late-filed IO228040B Notifies ABLB & parties of intent to file late-filed contention on financial qualifications of applicant per court decision overturning NRC elimination of financial qualification rule Related correspondence BLLL, N Coalition for Safe Power B4/02/24 MARQULIES, M, BHON, F. J. CARPENTER, J Atomic Safety and Licensing Board Panel ip 22407 060, 24X Fiche 50-508,84/02/24,8402280458

Q Inspection reports, IE Bulletins & correspondence

- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps. Byr list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc. 120pp 22058,001 24X Fiche 50-000,84/01/25,8312120153
- B401190016 IE Info Notice B4-07. "Design-Basis Threat & Review of Vehicular Excess Controls " Bvc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co. of New York, Inc. 119pp 22114 179 24X Fiche. 50-000, 84/02/03, 8401190016
- B401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Haaders " 8vc list encl DEYOUNO.R C Director's Office, Office of Inspection and Enforcement. B4/02/03 Consolidated Edison Co. of New York, Inc 102pp. 22177 154. 24X Fiche 50-000.84/02/03.8401190017
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Bys (100FR50, App R) " Syc list encl. JDRDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103). B4/02/13 Consolidated Edison Co. of New York, Inc. 124pp 22365-259 24X Fiche:50-000.84/02/13.8401190041
- B401170037 IE Info Notice 84-08, "100FR50 7, 'Employee Protection '"

 Byc list encl

 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14, Consolidated Edison Co of New
 York, Inc. 115pp 22365 141 24X Fiche 50-000,84/02/14,8401170039
- 8401190045 IE Info Notice 83-63,8uppl 1, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15. Consolidated Edison Co. of New York, Inc 118pp. 22366.142, 24X Fiche 50-000,84/02/15,8401170045
- 840119062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21. Consolidated Edison Co of New York, Inc 116pp. 22366.024 24% Fiche 50-000,84/02/21,8401190062
- B40119066 IE Info Notice 84-11, "Training Program Deficiencies"
 Svc list encl,
 JORDAN,E L. Division of Emergancy Preparedness & Engineering
 Response (Post 830103), 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430:304 24X Fiche,50-000,84/02/24,8401190066

- 8401170067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals 901190067 IE Info Notice Detail.

 Syc list enc!

 JORDAN.E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/02/27 Consolidated Edison Co. of New

 York, Inc. 120pp 22431 060 24X Fiche 50-000.84/02/27,8401190067
- S Reportable occurrences, LFRs & related correspondence
- 8402:130432 Interim Deficiency Rept D/N 49 re nonconforming weld repair of beam cope burn cuts CB&T will complete investigation & forwards results to Ebasco by Apr 1984 Final rept expected hu 940615 oy 840613 KOHLER, A D Washington Public Power Supply System 84/01/31 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 20p 22202 071 24% Fiche 50-508,84/01/31,8402130432

T Hearing transcripts on non-antitrust matters

- 8402270302 Partial response to FOIA request for five categories of documents re mothballed nuclear const projects App A documents being placed in PDR Document as listed on App B already available in PDR Bearch continuing FELTON, J M Division of Rules and Records 84/01/20 BELL, N Nuclear Information & Resource Service 3pp 22395 200 24% Fiche 50-000.84/01/20.8402770302
- --8402270321 Testimonu of J8 Martin before Subcommittee on Energy Conservation & Power re nuclear power plants being constructed by WPPSS Related info encl

 MARTIN.J B Region 5, Office of Director 83/09/14 86pp
 22395 104 24% Fiche 50-000,84/01/20.8402270302

V Operator Examinations

B402220464 Guppls response to Generic Ltr 83-40 Operator license exams not planned at facilities
BGRENSEN, G C Washington Public Power Supply Bystem 84/02/15
Division of Licensing 1p 22337 310 24X Fiche 50-440.84/02/15. Division of Licensing 1p B402220444

DOCKET STN-50-509 WPPSS NUCLEAR PROJECT, UNIT 5

- A Application/construction stage documents & correspondence
- 8401170065 Partial response to FOIA request for six categories of documents re facilities Forwards documents listed in Apps A & B Documents also available in POR W/o App A documents FELTON, J M Division of Rules and Records 83/10/24 ANDERSON Garvey. Schubert, Adams & Darer 4pp 21838 003 24X Fiche 50-397,83/10/24,8401170065 4 ANDERSON.S I
- --8401170083 "Level 1 Mgt Info Rept" Related info encl * Washington Public Power Supply System 80/01/30 21838.106 24X fiche 50-397.83/10/24:8401170065 72pp
- --8401170089 "Project Status Rept for WNP-1,2,3,4 & 5 "
 * Washington Public Power Supply System 78/04/30
 21838 178 24X Fich* 50-397,83/10/24,8401170045
- B402170222 Becond partial response to FOIA request for six categories of documents re facility Review of addl documents incomplete FELTON, J H Division of Rules and Records 83/12/01 ANDERSON, S 01 ANDERSON, S I 24X Garvey, Schubert, Adams & Barer 1p Fiche. 50-000, 83/12/01, 8402170222 22313 252
- 84020B0430 Forwards, for info, "Rept to Governor J Spellman of State of WA & Governor V Atigeh of State of OR " Rept provides recommendations for solution to major problems involving or arising from WPPBB BURRNSEN.C.C Hashington Public Power Supply System 83/12/08 EISENHUT.D 0 Division of Licensing 1p. 22168 286 24X Piche: 50-397, 83/12/08.8402080430
- --8402080435 "Rept to Governor J Spellman of State of WA & Governor V Atigeh of State of DR "
 LUCE, C F. Affiliation Not Assigned 83/11/30 68pp 22169 001
 24% Fiche, 50-397, 83/12/08, 8402080430

T Hearing transcripts on non-antitrust matters

8402270302 Partial response to FDIA request for five categories of 1022/0302 Partial response to FullA request for five categories of documents re mothballed nuclear const projects App A documents being placed in PDR Document as listed on App B already available in PDR Bearch continuing FELTON, J M Division of Rules and Records 84/01/20 BELL.N Nuclear Information & Resource Service 3pp 22395 200 24X Fichs. 30-000.84/01/20,8402270302

---8402270321 Testimony of JB Martin before Subcommittee on Energy Conservation & Power re nuclear power plants being constructed by WPPSS Related info encl MARTIN. J B Region 5. Office of Director 83/07/14 86pp 22395 104 24X Fiche 50-000.84/01/20,8402270302

DOCKET 50-513 HPPSS NUCLEAR PROJECT, UNIT 4

A Application/construction stage documents & correspondence

B401170065 Partial response to FDIA request for six categories of documents re facilities Forwards documents listed in Apps A & B Documents also available in PDR W/o App A documents FELTON, J M Division of Rules and Records 83/10/24 ANDERSON, S I Garvey, Schubert, Adams & Barer 4pp 21838 003 24X Fiche 50-397.83/10/24.8801170065

--B40117007; Advises of results of NRC Caseload Forecast Panel visit to plant site during 811021-23 Estimated const completion date for Unit 1 is Feb 1986 Unit 4 not included in evaluation
TEDESCO,R L Assistant Director for Licensing B1/12/08
FERGUSON,R L Washington Public Fower Supply System 3pg 21838 007 24X Fiche 50-397.83/10/24,8401170065

--8401170073 Forwards final agenda for NRC Caseload Forecast Panel 800122-24 Site visit 800DMAN,W A Mashington Public Power Supply System 80/02/21 Washington Public Power Supply System 7pp 21838 015 24X Fiche 50-397,83/10/24,8401170065

--8401170083 "Level 1 Mgt Info Rept " Related info encl * Washington Public Power Supply System 80/01/30 72pp 21838 106. 24X Fiche 50-397.83/10/24.8401170065

--8401170089 "Project Status Rept for NNP-1,2,3,4 t 5 "

* Washington Public Power Supply System 78/04/30 29pp
21838 178 24X Fiche. 50-397,83/10/24,8401170065,

--8401170092 "Project Trend Analysis - Manpower Progress Schedule " Related info encl # Washington Public Power Supply System 78/04/30 135pp 21838 207 24% Fiche 50-397,83/10/24,8401170065

8402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing pstimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documents FELTON.J M Division of Rules and Records 83/10/31 ROSENRAUM.D M Technical Analysis Corp 19pp 22193 292 24X Fiche 50-000.83/10/31.8402090003

840R170R22 Second partial response to FOIA request for six categories of documents re facility Review of addl documents incomplete FELTON, J M Division of Rules and Records 83/12/01 ANDERSON, 8 (Garvey, Schubert, Adams & Barer | 1p. 22313 252 24X Fiche \$0-000.83/12/01.8402170222

8402080430 Forwards, for info, "Rept to Governor J Spellman of State of MA & Governor V Ativeh of State of OR " Rept provides recommendations for solution to major problems involving or arising from WPFSS
SORENSEN, O C Washington Public Power Supply System 83/12/08
EISENHUT, D @ Division of Licensing ip 22168 286 24x
Fiche 50-397.83/12/08.8402080430

8402080435 "Rept to Governor J Spellman of State of WA & Governor V Atiyah of State of UR." LUCE, CF Affiliation Not Assigned 83/11/30 68pp 22169 001 24X Fiche 50-397,83/12/08,8402080430

02230197 Forwards itemized expenditures as requested in 830923 ltr re review of OL epplication MILLER, W O License Fee Management Branch 84/02/15 SDRENSON, G C Washington Public Power Supply System 3pp 22379, 186 24X Fiche 50-313-84/02/15, 8402230197

Reportable occurrences, LERs & related correspondence

)ii9004B Board Notification 84-006 provides info re alleged falsification of GC documents concerning const of safety—selated HVAC units by Bahnson Co. Minston-Balem, NC ITSENNUT. D. 0 Division of Licensing 84/02/09 PALLADINO Jummissioners, 7pp 22332 187 24X Fiche 50-000,84/02/09,3401190048

T Hearing transcripts on non-antitrust matters

B402270302 Partial response to FOIA request for five categories of documents re mothballed nuclear const projects App A documents being placed in PDR Decument as listed on App B already available in PDR Search continuing FELFON. J M Division of Rules and Records 84/01/20 BELL. N Nuclear Information & Resource Service 3pp 22395 200 24% Fiche 50-000,84/01/20,8402270302

--8402270321 Testimony of JB Martin before Subcommittee on Energy Conservation & Power re nuclear power plants being constructed by WPPSS Related info encl MARTIN.J B Region 5, Office of Director 83/09/14 86pp 22395 104 24X Fiche 50-000.84/01/20,8402270302

DOCKET STN~50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1

T Hearing transcripts on non-antitrust matters

8402270302 Partial response to FOIA request for five categories of documents re muthballed nuclear const projects App A documents being placed in PDR Document as listed on App B already available in PDR Search continuing FELTON.J M Division of Rules and Records 84/01/20 BELL.N Nuclear Information & Resource Service 3pp 22975 200 24% Fiche 50-000.84/01/20.8402270302

--8402270321 Testimony of JB Martin before Subcommittee on Energy Conservation & Power re nuclear power plants being constructed by WPPSS Related info encl MARTIN.J B Region 5, Office of Director B3/09/14 86pp 22395 104 24X Fiche 50-000,84/01/20,8402270302

DOCKET STN-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2
T Hearing transcripts on non-antitrust matters

B402270302 Partial response to FOIA request for five categories of documents re mothballed nuclear const projects App A documents being placed in PDR Document as listed on App B already available in PDR Search continuing FELTON.J M Division of Rules and Records 84/01/20 BELL.N Nuclear Information & Resource Service 3pp 22395 200 24% Fithe 50-000.84/01/20.8402270302

--8402270321 Testimony of JB Martin before Subcommittee on Energy Conservation & Power re nuclear power plants being constructed by WPPSS Related info encl MARTIN.J B Region 5, Office of Director 83/09/14 BApp 22395 104 24% Fiche 50-000,84/01/20,8402270309

DOCKET 50-522 SKAQIT NUCLEAR POWER PROJECT, UNIT 1

G Inspection reports, IE Bulletins & correspondence

8312120153 IE Info Notice 84-04. "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp. 22058 001 24X Fiche 50-000,84/01/25,8312120153

B401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co. of New York. Inc. 119pp 22114 179 24X Fiche 50-000.84/02/03.8401190016

840:190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Syc list end! DEYGUNG,R C. Director's Office, Office of Inspection and Enforcement. 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22

8401190041 IE Info Notice 84-09, "Lessons Learned Fram NRC Insps of Fire Protection Safe Shutdown 8ys (10CFR50.App R) " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp. 22365 259 24X Fiche 50-000.84/02/13.8401190045

B401190039 IE Info Natice 84-08, "10CFR50 7, 'Employee Protection '"
Syc list encl
JORDAN,E.L. Division of Emergency Preparedness & Engineering
Response (Post B30103) B4/02/14 Consolidated Edison Co of New
York, Inc 115pp 22345 141 24X Fiche 50-000,84/02/14,8401190039

Ą

- 8401190045 IE Info Notice B3-63.Suppl 1. "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York Inc 118pp 22366 142 24X Fiche 50-000.84/02/15.8401190045
- 8401170062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co. of New York, Inc. 116pp 22366 024 24X Fiche 50-000,84/02/21,8401190062
- 8401190064 IE Info Notice 84-11. "Training Program Deficiencies "
 Svc list ancl
 JURDAN, E L Division of Emergency Preparedness & Engineering
 Rasponse (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24% Fiche 50-000.84/02/24,8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York Inc 120pp 22431 060 24X Fithe 50-000.84/02/27,8401190067
- DOCKET 50-829 SKAGIT NUCLEAR POWER PROJECT, UNIT 2
 O Inspection reports, IE Bulletins & correspondence
- 8312120153 IE Info Notice 84-06. "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York, Inc 120pp 22058 001 24X Fichs 50-000.84/01/25.8312120153
- B401190016 IE Info Notice 84-07; "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc. 119pp 22114 177 24X Fiche 50-000,84/02/03,8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers." Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement B4/02/03 Consolidated Edison Co of New York, Inc 102pp 22177
- 8401i90041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR30, App R) " Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259 24X Fiche 30-000,84/02/13,8401190041
- 8401170037 IE Info Notice 84-08, "10CFR50 7, 'Emplayee Protection '"
 Svc list encl
 JORDAN, EL Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co. of New
 York, Inc. 115pp 22365 141 24X Fiche 50-000,84/02/14,8401170039
- B401190045 IE Info Notice B3-63, Suppl 1, "Potential Failures of Westinghouse Type BA-1 Differential Relays " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366 142 24X Fiche 50-000.84/02/15.8401190045
- 8401170062 IE Info Notice 84-10. "Motor-Operated Valve Torque Switches Bet Below Menufacturer Recommended Value " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/21 Consolidated Edison Co of New York, Inc. 116pp 22366 024 24X Fiche 50-000.84/02/21.8401190062
- 8401170066 IE Info Notice 84-11. "Training Program Deficiencies "
 Swc list encl
 JORDAN E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24. Consolidated Edison Co of Naw
 York, Inc. 115pp 22430,304 24X Fiche 50-000,84/02/24,8401170066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals."
 Swc list encl
 JORDAN, E L Division of Emergency Preparadness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co of New
 York, Inc 120pp. 22431 060 24X Fiche 50-000,84/02/27,8401190067

- DOCKET STN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B402130005 Appeals denial of FDIA request for documents re R Gunderson & senior Bechtel manager allegations of electrical problems & deficiencies at facilities
 YDUNG.M C , BERNABELL Government Accountability Project
 83/05/13 NRC , ND Detailed Affiliation Given 2pp 22238 093
 24X Fiche 50-528-83/05/13.8402130005
- 8402090003 Responds to FOIA request For const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documents
 FELTON, J M Division of Rules and Records 83/10/31
 ROSENBAUM, D M Technical Analysis Corp 19pp 22193 292 24X
 Fiche 50-000,83/10/31.8402090003
- --8204070041 Trip rept of 820316-19 visit of caseload forecast panel to facility re determination of fuel load dates Load dates estimated to be Nov 1983. Nov 1984 & Nov 1985 for Units 1, 2 & 3. respectively
 MIRAGLIA.F J Derating Reactors Branch 3 82/03/30
 EISENHUT.D 0 Division of Licensing 4pp 22194 055 24X
 Fiche 50-000.83/10/31.8402090003
- --B402090070 Trip rept of B30622-24 Caseload Forecast Panel site visit re plant status review Projected fuel load date comparisons listed KNIGHTON.0 W Licensing Branch 3 B3/10/31 NDVAK, T M Assistant Director for Licensing 2pp 22194 039 24X Fiche 50-000.83/10/31,8402090003
- ~-8402090072 Handwritten graphs, calculations & notes re const activities & fuel load preparation Related info encl * NRC - No Detailed Affiliation Given 80/10/28 9pp 22196 021 24X Fiche 50-000, 83/10/318402090003
- ---8402090082 Handwritten notes & calculations re const activities & fuel load preparation * NRC - No Detailed Affiliation Given 79/04/25 2pp 22196 031 24X Fiche 50-000, 83/10/31,8402090003
- --8402090087 Handwritten graphs ra const activities Related info encl * NRC - No Datailed Affiliation Given 83/06/28 App 22196 035 24% Fiche 50~000.83/10/31,8402090003
- 8402130007 Responds to appeal re denial of FOIA request for documents concerning investigation of allegations at facility Forwards App A documents Documents completely & partially withhold (ref FOIA Exemptions 7 & 4)
 CHILK.S J Diffice of the Secretary of the Commission 83/11/10
 BERNABELL Government Accountability Project 44pp 22238 100
 24X Fiche. 50-528, 83/11/10, 8402130007
- --B304040543 Forwards list of items currently under insp/investigation which have recently been closed out, in response to 830318 memo No allegations should impact plant safety or current schedule for initial fuel loading DIRCKS, N J Office of the Executive Director for Operations 83/03/27 CHILK, B J Office of the Becretary of the Commission 3pp 28240.125 24X Fiche 50-528.63/11/10,8402130007
- --8402130010 Discusses 820525 Bechtel alleger telcon re allegations concerning defective electrical & const items at facilities Bpecific defects listed Related info encl BHACKLETON, D. C. Region 5. Dffice of Director 83/03/18 STERNBERG, D. M. Region 5. Office of Director 7pp 22238 144 24X Fiche 50-528,83/11/10.8402130007
- ~-8402130012 Lists three allegations of immediate concern, currently being investigated under Cases 5-82-006,009 & 011 Related info ent!

 8HACKLETON.O.C. Region 5, Office of Director 83/03/29

 DEMEYL B OFfice of the Executive Legal Director 18pp 22298 [51 24X Fiche 50-528,83/11/10.8402130007
- --8402130014 Submits info re 820525 allegations concerning electrical const deficiencies Portions deleted SHACKLETON, O.C. NRC No Detailed Affiliation Given 82/05/27 BISHOP, T.W. NRC No Detailed Affiliation Given 1p 22238 169 24X Fiche 50-528, 83/11/10, 8402130007
- --B402130016 Submits info re 820526 allegations concerning electrical const deficiencies BHACKLETON, O.C., NRC No Detailed Affiliation Given 82/05/27 BISHOP.T W NRC No Detailed Affiliation Given 3pp 22238 170 24X Fiche 50-528,83/11/10,8402130007

- --B402130019 Handwritten notes re death threats against alleger concerning const deficiencies Related info encl SHACKLETON,O C NRC No Detailed Affiliation Given B2/0 2pp 22238 1B7 24% Fiche 30-528.B3/11/10.B402130007 B2/05/24
- --B402130030 Forwards recipient signed sworn statement re 820602 allegations Results will be provided following investigation completion Related info encl
 SHACKLETON D C NRC No Detailed Affiliation Given 82/06/09 GUNDERSON R D Affiliation Not Assigned ip 22238 241 24X Fiche 50-528,83/11/10.8402130007
- --8402(30044 Discusses 820325 telcon from anonymous caller alleging DESCRIPTION UNSENSED GROUNDS teleon from anonymous caller alleging defective HPSI & LPSI sys at plant TEDFORD.C F Arizona. State of 82/03/26 VORDERBRUEGOEN Region 5. Office of Director 1g 22238 242 24X Fiche 50-528.69/11/10. B402130007
- --9402130047 Discusses allegations re electrical const deficiencies at facilities Case under investigation SHACKLETON, U.C. Region 5. Office of Director 82/07/22 NRC No Detailed Affiliation Given 2pp 22238 246 24X Fiche 50-528,83/11/10.8402130007
- --8402130053 "Investigations Status Rept " Related info encl * Office of Investigation 82/10/19 32pp 22238 254 Fiche 50-528.83/11/10.8402130007 24 X
- --8402:30:122 Informs of L Bernabel intention to make contention over RD Gunderson affidavit re allegations concerning facility const deficiencies Insp & anvestigations should be completed immediately SHACKLETON.O.C. Region 5, Office of Director 83/03/29 STERNBERO.D.M. Region 5, Office of Director 1p 22238 305 24x Fiche.50-528.83/11/10.8402130007
- --B402130127 Informs that RD Gunderson allegations that have not been investigated/inspected not presently within Ofc of Investigations purview Region V insp requested SHACKLETON O C Region 5. Office of Director 83/03/30 STERNBERG.D M Region 5. Office of Director 2pp 22238 306 24% Fiche 50-528,83/11/10.8402130007
- --B402130134 Informs that WR Royce allegation does not come under Ofc of Investigations jurisdiction Allegations submitted to Region V for followup Related info encl SHACKLETON.O C Region 5, Office of Director B3/03/30 STERNBERO, D M Region 5, Office of Director 242pp 22238 308 24X Fiche 50-528,83/11/10.8402130007
- --8402130143 Rev O to Procedure 40GA-OZZII, "Temporary Mods " Related EARDNER, B J Arizona Public Service Co 82/05/10 43pp 22239.190 24X Fiche 50-528,83/11/10,8402130007
- --B402130168 Forwards documents loaned from recipient re investigative rapt concerning radiographic operations Related info encl SHACKLETON.O C NRC No Detailed Affiliation Given B2/06/25 Affiliation Not Assigned 31pp 22240 047 24X Fiche. 50-528,83/11/10,8402130007
- ---B402130174 "Const Insp Planning for Concrete Replacement " Related info ent1 # Bachtel Corp JOS 10407 79/12/04 11pp 22240 089 24X Fiche 30-528,83/11/10.8402130007
 - 92 Provides Ofc of Policy Evaluation immediate effectiveness s of Palo Verde licensing board decision for Unit 1 info enci E. Office of Policy Evaluations 9ECY-83-065 83/02/15 22240 100 24X Fiche 50-528,83/11/10,8402130007

 - l Staff requirements memo re 830315 discussion/possible vote ested issues in Palo Verde full power proceeding
 B Office of Investigation 83/03/25 CHILK 8 J Office Secretary of the Commission 2pp 22240 128 24X
 - 9 Handwritten notes re allegations concerning facility Related info encl ion 5. Office of Director 92/05/25 15pp 22240 141 24x 50-528,83/11/10.8402130007
 - ral Discusses allegations from anonymous alleger from Bachtel re ral installations Related info encl
 ON.O.C. Region 3, Office of Director 82/07/22 Region e of Director 46pp 22240 156 24X
 528,83/11/10,8402130007

- --8402130232 Forwards documents discussed during 820707 telcon reallegation that wiring separation in main control panel violates code Related info encl SHACKLETON, D.C. Region 5, Office of Director 82/07/09 MORISON, J. Affiliation Not Assigned 6pp 22840 213 24x Fiche 50-528,83/11/10,8402130007
- --8402130237 Submits Inquiry Rept Q5-82-003 re WR Royce allegations concerning startup program Related info enci SMACKLETON D C Region 5, Office of Director 82/11/18 Ast 5, Office of Director 7pp 22/240 219 24X Ficho 50-520. 83/11/10.8402130007 Hegis"
- --8402130241 Discusses WR Royce allegations re startup program
 Handwritten Related info encl
 SMACKLETON,O C Region 5. Office of Director 82/11/17 v(M.F.) f
 Region 5. Office of Director 14pp 22240 235 24x
 Fiche 50-528,83/11/10,8402130007
- --8402130250 Summary of investigation to PL Hourihan allegations concerning electrical work Handwritten Related info encl SHACKLETON.O C Region 5. Office of Director 82/05/24 :37pp 22240 252 24X Fiche 50-528.63/11/10.8402130007
- --8402130262 Discusses anonymous allegations from Bechtel employee **
 electrical installations
 SHACKLETON, O.C. Office of Investigation 82/07/22 Office **
 Investigation 3pp 22240 328 24X Fiche 50-528, 83/11/10.
 8402130007
- 8402160003 Third partial response to FOIA request for info re voles & attendance at Commission meetings for Jul 1981 Jul 1983 (HILKES J. Office of the Secretary of the Commission 87/12/14 Public Document Branch 1p 22281 023 24X Fiche 50-000/07/12/14
- --8402160394 Discusses SECY-83-125 re immediate effectivomens decisis: 6 review of ALAB-713 CHILKS J Defice of the Secretary of the Commission. B.7/05/19 FLAINE, H Defice of the General Gounsel ip 22281 206 24 Fiche 50-000,83/12/14,8402160003
- 8402090097 Further response to FOIA request for records re problems encountered by util during hot functional testing Forwards App A documents Documents also available in PDR Bearch for addl documents continuing FELTON.J M Division of Rules and Records 83/12/22 QARDC. B Government Accountability Project 2pp 22189 084 24% Fiche 50-528.83/12/22.8402090097
- --840209012B Rev 1 to "Reactor Coolant Pump Operating Guidelines " Related info encl # Arizona Public Service Cn 83/12/22 21pp 22187 101 24K Fiche 90-528,83/12/22,8402090097
- 8402270072 Final response to FDIA request for Commissioner voting to attendance records from 810401 to present Forwards documents listed on App A Documents also available in FDR FELTON.J M Division of Rules and Records 83/12/22 KAMINAR, F C Washington Legal Foundation. 3pp 22410,109 24% Fiche 50-528,83/12/22,8402270072
- --B30404050 Advance copy of staff requirements memo re B30315 discussion to possible vote in Washington.DC on contested issues in full power proceeding CHILMS J Office of the Secretary of the Commission B3/03/16 DIRCKS.W J Office of the Executive Director for Operations is 22410 146 24X Fiche 30-328,83/12/22,8402270072
- 8402070431 Requests add1 info re proposed method for estimating gasts a effluent flow rates in lieu of direct measurements, demonstrating conservatism of flow rate values under alk ENGLITON, G W Licensing Branch 3 84/01/16 VAN BRUNT, C C Arizone Public Service Co 2pp 22142 095 24X Fiche, 50-528, 84/01/16, 8402070431
- B401270152 Forwards nonproprietary "Safety Injection Nozzle Thermat Liner" & "Resistance Temp Detector Thermowell," for docketing & distribution VAN BRUNT,E E Arizona Public Service Co 84/01/24 KNICHTCM. Q w Licensing Branch 3 ip 22038 001 24X Fiche 30~528.84/01/24. 8401270152
- --8402010433 Nonproprietary "Rept on Palo Verde Unit 1 Bafety Injection Nozzle Thermal Liner."

 * Combustion Engineering, Inc. CEN-264(V)-NP, 84/01/R4 U2pp 22038,002 24X Fiche. 50-528,84/01/24,8401270152,

- --B402D10437 Nonproprietary "Rept on Palo Verde Unit 1 Resistance Temp Detector Thermowell"
 - * Combustion Engineering, Inc 84/01/24 100pp 22038 034 24x Fiche 50-528,84/01/24,8401270152
- 84020A0240 Forwards nonproprietary "Interim Rept on Performance Evaluation of Palo Verde Control Element Assembly Shroud " VAN BRUNT, F.E. Arizona Public Service Co. 84/01/31 KNIGHTON, G Licensing Branch 3 1p 22084 213 24X Fiche 50-528, 84/01/31, 8402040240
- --8402060247 Nonproprietary "Interim Rept on Performance Evaluation of P41b Verde Control Element Assembly Shroud" * Combustion Engineering. Inc CEN-267(V)-NP 84/01/31 Bipp 22084 214 24X Fiche 50-528,84/01/31,8402060240
- B402010410 Generic Ltr 84-04 to all operating PWR licensees, CP holders & applicants for CPs re safety evaluation of Hestinghouse topical repts dealing w/elimination of postulated pipe breaks in PMR primary main loops Svc list encl EISENHUT.D G Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc 59pp 22177 087 24X Fiche 50-000.84/02/01.8402010410
- 8402160470 Forwards request for add1 info based on review of June 1983 data base values for facility core protection calculators & control element assembly Info should be provided within 2 wks
 **NIGHTON.6 H Licensing Branch 3 8402/06 VAN DRUNT, E E Arizona Public Service Co 3pp 22302 160 24%
 Fiche 50-528,84/02/06,8402160470
- 8402230341 Provides partial info re German reactor coolant pump (RCP) design, German design similar to RCP seal used in C-E KBB pump at Palo Verde
 JACKSON.JE Equipment Qualification Branch 84/02/07 NDONAN, V S
 Equipment Qualification Branch 2pp 22377 052 24X
 Fiche 50-528,84/02/07.8402230341
- 8402170241 Notifies that util response to NRC 840110 request for schedule re differences between facility control room design review & NRC detailed control room design review program will be provided by 840330 VAN BRUNT.E E Arizona Public Service Co 84/02/13 KNIGHTON.Q Licensing Branch 3 lp 22296 149 24X Fiche 50-528, 84/02/13, 8402170241
- B402170257 Trip rept of B31108 & 09 visits to Saint-Laurent-Des-Eaux plant & KBB Labs,Frankenthel,West Germany, respectively, replant orpanization & reactor coolant pump design KBB Labs provided reactor coolant pumps for Paio Verde NDVAK,T.M Assistant Director for Licensing 84/02/13 E15ENHUT,D Q Division of Licensing 4pp 22313 235 24x Fiche 50-528.64/02/13.8402170257
- B402160069 Forwards add1 info re impact of high energy line breaks on control sys.per B31205 & 13 telcon concerns re Guestion 222 03. VAN BRUNT, E E Arizona Public Service Co 84/02/14 KNIGHTON, O W Licansing Branch 3 5pp 22275 264 R4X Fiche 50-528,84/02/14, 8402160069
- 8402220489 Forwards proprietary & nonproprietary "Comprehensive Vibration Assessment Program for Palo Verde, Unit 1 (Bys 80 Prototype)," per BER (NURE9-0852) Proprietary rept withheld (ref 10CPR2 790) SCHERER, A E Combustion Engineering, Inc 84/02/16, EISENHUT, D. Q Division of Licensing 5pp 22333:057 24X Fiche 50-000, 84/02/16, 8400220489
- --8402230496 Nonproprietary "Comprehensive Vibration Assessment Program for Pale Verda Nuclear Generating Station, Unit 1 (Sys 80 Prototype)," preliminary avaiuation of pracore hot functional measurement & insp programs a Combustion Engineering, Inc. CEN-263(V)-NP 84/02/16 66pp 22339 062 24X Fiche 50-000,84/02/16,8402220489.
- 8403270635 Notification of 840302 meeting w/C-E in Windsor, CT to perform audit of results of Phase I & II testing Agenda encl.

 LICITRA, E A Licensing Branch 3 84/02/16 KNIGHTON, C W Licensing Branch 3. 4pp 82414, 022 24% Fiche 50-528, 84/02/16, 8402270635.
- 8402270383 Forwards util 840213 press release, "Palo Verde Unit 1 Fuel Loading to be Rescheduled" Add info re new schedule expected during wk of 840305 VAN BRUNT, E E Arizona Public Service Co 84/02/17 KNIGHTON, O Licensing Brench 3 3pp 22390 238 24% Fiche 50-328, 84/02/17, 8402270383.

- B402270340 Forwards response to NRC 831220 request for addl info re TMI Item II F 2, "Instrumentation for Detection of Inadequate Core Louling " VAN BRUNT, E E Arizona Public Service Co 84/02/23 KN10HTON.0 Licensing Branch 3 17pp 22387 288 24X Fiche 50-528.84/02/23.8402270340
- 8402290034 Forwards clarifications t justifications made to certain revs included in Amend 12 to FSAR

 VAN BRUNT, E E Arizona Public Service Co 84/02/24 KNIGHTON, G
 Licensing Branch 3 App 22/26 182 24% Fiche 50-528, 84/02/24, 84/02/2034
- 8402290068 Forwards preliminary description for RCS demonstration test Bpwcific aspects will be discussed at 840320 meeting VAN BRUNT.E E Arizona Public Service Co B4702/24 KN10HTON.0 Licensing Branch 3 10pp 22421 009 24X Fiche 50-928.84702/24, 8402290068
- 8402290177 Forwards proposed changes to Section 1 B of FSAR re Reg Quides 1 28 & 1 33 covering preoperational & startup testing Changes will be incorporated into future FSAR amend VAN BRUNT, E E Arizona Public Service Co 84/02/24 KNIOHTON, O Licensing Branch 3 8pp 22426 289 24X Fiche 50-528, 84/02/24, B402290177
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- E4020B0217 Forwards list of unsite emergency organization personnel as of 840101, per BSER 4 (NUREG-0857)

 VAN BRUNTLE E Arizona Public Service Co 84/01/27 KNIGHTON, G Licensing Branch 3 8pp 22130 104 24X Fiche 50-528, 84/01/27, 84020B0217
- 840R080332 Advises that design of atmospheric dump valve accumulators reevaluated.per NUREQ-0857 SER, Section 5 4 3 Design meets requirements info will be reflected in upcoming amend to FBAR VAN BRUNT, E.E. Arizona Public Service Co. 84/01/27 KNIGHTON, G. Licensing Branch 3. 5pp. 22131-216. 24X Fiche 50-528.84/01/27, 8402080332
- B402130175 Forwards add1 info on potential finding Repts 027,050 & 065, per 88ER 5 (NUREG-0857), Section 17 7 3 re independent GA evaluation VAN BRUNT, E E Arizona Public Service Co 84/02/06 KNIGHTON, G Licensing Branch 3 5pp 22204 134 24X Fiche 50-528, 84/02/06,
- 8402270495 Forwards revised pages to pump & valve testing program, categorizing pressure isolation valves as ac according to ABME Section XI.per Sec (NUREO-0687)

 VAN BRUNT, E E Arizona Public Service Co 84/02/17 KNIGHTON, G Licensing Dranck 3 App 22387 258 24X Fiche 50-520,84/02/17,8402270495
- F Security, medical, emergency & fire protection plans
- 8402160305 Revised emergency plan implementing procedures, including Procedures EPIP-01 re emergency organization, EPIP-03 re notification of unusual implementing actions & EPIP-04 re alart implementing actions W/840210 ltr BROWN B. A, CLYPE, M R, VAN BRUNT, E.E. Arizana Public Bervice Co 84/01/20 KNIGHTON, 9 Licensing Branch 3 126pp 22272 238 24X Fiche 50-528,84/01/20,8402160305
- 8402080217 Forwards list of onsite emergency organization personnel as of 840101, per BBER 4 (NUREG-0857)
 VAN BRUNT, E E Arizona Public Service Co 84/01/27 KNIGHTON, O Licensing Branch 3 Bpp 22130 104 24X Fiche 50-528,84/01/27, 8402080217.
- 8402160653 Responds to 830616 request to establish backup emergency operations facility in Palo Verde Inn approx 8 miles from plant Location acceptable EIBENHUT, D 0 Division of Licensing 84/01/31 VAN BRUNT, E Arizona Public Service Co 2pp 22292 357 24% Fiche 50-528,84/01/31,8402160453
- 8402150271 Advises that review of util maint program for valves & hydrants disclosed that sys surveillances still undeveloped & no preventive maint conducted Problem w/fire loops identified by Bechtel re amount of valve seat leakage VAN BRUNTLE E Arizona Public Service Co 84/02/08 MARTIN.J. B Region 5. Office of Director 2pp 22250 276 24X Fiche: 50-528.84/02/08.8402150271

- 8402220386 Submits supplemental response to 830728 Itr re independent source range neutron flux monitor at remate shutdown panel Design features & procedural guidance in existing design satisfy 100FR50, App A. Criterion 3. based on listed features VAN BRUNT, E. E. Arizona Public Service Co. 84/02/14 KNIGHTON, G. Licensing Branch 3. 3pp. 22335-287 24X Fishe 50-528, 84/02/14, 840220386
- B402290352 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licenses, per B10709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR KNIGHTON, 6 W. Licensing Branch 3 84/02/14 VAN BRUNT, E Arizona Public Service Co. 3pp. 22438 259 24X Fiche 50-528,84/02/14,8402290352

G Adjudicatory correspondence

- 8402130007 Responds to appeal re denial of FOIA request for documents concerning investigation of allegations at facility Forwards Ago A documents Documents completely 5 partially withheld (ref FOIA Exemptions 7 & 4) CHILK.S J. Office of the Secretary of the Commission B3/11/10 BERNABELL Covernment Accountability Project 44pp 22238 100 24X Fiche 50-930-83/11/10-8402130007
- --8402130024 Affidavit of RD Gunderson re allegations concerning electrical const deficiencies Related info encl GUNDERSON.R D Bechtel Corp 83/11/10 51pp 22238 190 24X Fiche 50-528,83/11/10,8402130907
- --8402130108 Forwards R Gunderson % W Royce affidavits & supporting exhibits re allegations concerning const deficiencies at facilities Problems evidenced not adequately addressed GARDE, B P. CLARK, L. HERNADELL, Overnment Accountability Project 89/02/28 FORTUNA, R Office of Investigation 2pp 22238 301 24X Fiche 50-528,83/11/10,8402130007

H General correspondence

- 8402060078 Informs of recont rev in util organizational structure B Ide replaced J Roedel as manager of corporate GA/GC WOODS, T G Arizona Public Service Co 84/01/31 KNIGHTON, G Licensing Branch 3 ip 22088 239 24X Fiche 50~528, 89/01/31, 8402060078
- 840213003B Informs that D Karner appointed assistant vice-president for nuclear uperations Karner will rept to EE Van Brunt & will provide addl mgt support during transition from const to operation

 VAN BRUNT, E E Arijona Public Sørvice Co 84/02/06 KNIGHTON, G Licensing Branch 3 tp 22204 085 24X Fiche 50-528, 84/02/06. B402130038

K Utility Final Bafety Analysis Report (FSAR) & amends

- 8402230119 Amend 12 to FSAR W/840221 ltr VAN DRUNT, E E Arizona Public Service Co 84/02/29 1241pp 22367-322 24% Fiche 50-528,84/02/29,8402230119
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8402090533 Summary of ACRS Fivid Dynamics Subcommittee 831208 meeting in Washington.DC re recent flow-related incidents resulting in equipment damage in plant primary sqs + ACRS Advisory Committee on Reactor Safeguards 83/12/13 ACRS Advisory Committee on Reactor Safeguards 26pp 22192 119 24X Fiche 50-000.83/12/13,8402090533

Inspection reports. IE Bulletins & correspondence

- 1402270555 FOIA request for all agency records & info re NRC const assessment team insp conducted from 830906-30 at facilities BERNABEI.L Government Accountability Project 83/10/07 Office of Administration 2pp 22414 144 24X Ficher 50-528,83/10/07, 8402270555
- 402270550 Appeals denial of FDIA request for documents re NRC const assessment team insp conducted from 830706-30 at facilities BERNABEI.L Government Accountability Project 83/12/05 Office of Administration 1p 22414 143 24X Fiche 50-528,83/12/05.8402270550
- 102270544 Responds to appeal re denial of FDIA request for documents re NRC const assessment team (nsp conducted from 830706-30 at facilities Rept provided on 831201 FELTON, J. M. Division of Rules and Records 84/01/12 BERNABEL, L. Government Accountability Project 1p 22414 142 24X Fiche 50-528,84/01/12,8402270544

- 8312120153 IE Info Notice 84-06, "Steam Binding of Auxiliary Fasdwith Pumps " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of No. York, Inc 120pp 27058 001 24X Fiche 50-000.84/01/25,8312120183
- 8402060406 Ack receipt of 840113 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-528/83-44 BISHOP: T W Division of Resident Reactor Project & Engineering Programs 84/01/30 VAN BRUNT: E Arizona Public Service Co IJ 22086 237 24X Fiche 50-528,84/01/30,8402060406
- --8402060410 Responds to NRC 831213 ltr re violations noted in 1E law Rept 50-528/83-44 Corrective actions control room operators will ensure proper flow path exists even for most routine action to prevent steam generator overfill VAN BRUNT. E. E. Arizona Public Service Co. 84/01/13 MARTIN. J. B. Region 5. Office of Director 4pp 22086 238 24X Fiche 50-528,84/01/30,8402060406
- 8402070133 Forwards responses to 831212 enforcement ltr & notice of violations Corrective actions detailed & violation for which \$40,000 penalty proposed denied based on inaccuracies in allegations & lack of safety significance
 VAN BRUNTLE E Arizona Public Service Co 84/01/31 Director's Office. Office of Inspection and Enforcement 160pp 22100 210 24X Fiche 50-528,84/01/31,8402070133
- 8402170459 Responds to appeal re denial of FOIA request for documents concerning R Gunderson & W Royce allegations Request denied Documents entirely withheld (ref FOIA Exemption 5) DIRCKS,W J Office of the Executive Director for Uperations 84/01/31 BERNABELL Government Accountability Project 1P 22313 358 24X Fiche 50-528.84/01/31,8402170459
- B401190016 IC Info Notice B4-07, "Design-Basis Threat & Review of Vehicular Ercess Controls " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (fost B30103) 84/02/03 Consolidated Edison Co of New York, Inc 819pp 22114 179 24X Fiche 50-000,84/02/03,8401190016
- B401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " 8vc list encl DEYQUNO.R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177
- B401170041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (100FRSO, App R)" Syc list enc!

 JDRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/13 Consolidated Edison Co. of New York Inc. 124pp 22365 259 24X Fiche 50-000, 84/02/13, 8401170041
- 8401190039 IE Info Nutice 84~0B, "IOCFR50 7, 'Employee Protection '"

 Bvc list encl
 JDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of New
 York Inc 115pp 22365 141 24X Fiche 50-000,84/02/14,840£190039
- 8401170045 IE Info Notice 83-63, Suppl 1, "Potential Failures of Hestinghouse Type 5A-1 Differential Relays" Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of Maw York, Inc. 11889 22366 142 24X Fiche 50-000,84/02/15,8401190045
- 8402230006 Ack receipt of 840113 response to 831207 notice of deviation re HEPA filtration & test criteria Response to both deviations unacceptable Issue should be reconsidered & response supplied within 30 days SCARAND, R A Region 5. Office of Director 84/02/17. VAN BRUNT, E Arizona Public Service Co 2pp 22362 056. 24X Fiche 50-528,84/02/17,8402230006
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Yorque Switches Set Below Manufacturer Recommended Value " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000,84/02/21,8401190082
- 8401190065 IE Info Notice 84-11, "Training Program Deficiencies."
 Svc list encl
 JORDAN-E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co. of New
 York, Inc 115pp. 22430 304 24X Fiche 50-000,84/02/24,8401190086
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals,"

 Svc list encl

 JORDAN, El Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/02/27 Consolidated Edison Co of New

 York, Inc. 120pp 22431 060 24X Fiche 50-000.84/02/27.8401190047

R Periodic operating reports & related correspondence

- 8402080029 Responds to FOIA request for documents re facility hot functional testing problems, including broken thermowells, loase & broken reactor coolant pump parts & loose thermal sleeves Forwards App A documents Documents also in PDR FELTON, J M Division of Rules and Records 83/11/16 QARDE, B Government Accountability Project 3pp 22170 253 24X Fiche 50-000,83/11/16,8402080029
- --8402080071 Preliminary Rev 1 to "Steam Cenerator Blowdown Sys Test." test results rept for 830611-15 BTEARNS.W Affiliation Nat Assigned 91HF-18C01 R01 3pp 22170 348 247 Fiche 50-000,83/11/16,8402080029
- --B402030077 Preliminary Rev O to "Atmospheric Dump Valve Hot Functional Test." test results rept for B30603-0822 GRIZZARD, T Affiliation Not Assigned 91HF-1SF02 ROO 83/08/25 ilpp 22170 351 24X Fiche 30-000 83/11/16.8402080029
- --8402080082 Preliminary Rev O to "Pre-Core Safety Injection Check Valve Test." test results rept for 830602 DDYLE,K A Affiliation Not Assigned 91HF-18101 ROO 83/09/14 App 22170 362 24% Fiche 50-000,83/11/16,8402080029
- ---2402080088 Draft 7 of preliminary Rev O to "Pre-Core Turbine Bypass Control Sys Test: "test results rept for 830601-0705 HENEAGE. J Affiliation Not Assigned 91HF-18703 ROO DR 07 83/09/17 20pp 22171 006 24X Fiche 50-000.83/11/16.8402080029
- --8402080095 Preliminary Rev O to "Pre-Core Chemical & Vol Control Bys Integrated Test," test results rept for 830404-0704 # Affiliation Not Assigned 91HF-1CHO1 ROO 83/09/19 5pp 22171 026 24% Fiche 50-000,83/11/16.8402088029
- --B4020B0101 Preliminary Rev O to "MSIV & Bypass Valves Hot Functional Test." test results rept for 830402-0703 CHILDRESS.E T Affiliation Not Assigned 91HF-1SQ01 R00 83/08/23 18pp 22171 031 24X Fiche 50-000.83/11/14,8402080029
- --B4020B0107 Preliminary Rev O to "Main Steam Traps & Drain Valves Hot Functional Test," test results rept for 830404-15 # Affiliation Not Assigned 91HF-1ED01 ROO 83/09/07 4pp \$2171 049 24% Fiche 50-000.83/11/16.8402080029
- --B4020B0111 Preliminary Rev D to "Pressurized Performance," test results rept for 830603-17 STEARNS, H Affiliation Not Assigned 91HF-1RC02 ROO B3/08/20 App 22171 053. 24X Fiche 50-000.B3/11/14,84020B0029
- --B4020B0116 Preliminary Rev O to "Loose Parts & Vibration Monitoring Bys Hot Functional," test results rept for B30506-0607 BCHMIDT, C R Affiliation Not Assigned 92HF-18V01 ROO 83/06/14 App. 2217 059. 24X Fiche-50-000.
- --B4020B0119 Preliminary Rev O to "Main & Auxiliary Transformer Backfeed," test results rept for 830420-0515 * Affiliation Not Assigned 93HF-1M405 ROO 83/07/21 5p 22171 063 24% Fiche 50-000,83/11/16,8402080029
- ---B4020B0i23 Preliminary Rev O to "RCS Expansion Measurements," test results rept for 8304i1-0715
 ** Affiliation Not Assigned 91HF-1RC01 R00 83/07/27 3pp 22171.048 24X Fichs 50-000,83/11/16.8402080029.
- --B4020B0127 Preliminary Rev O to "Pre-Core Emergency & Auxiliary Feedwater Bys Test," test results rept for 830503-0703. MORELAND, J. W Affiliation Not Assigned 91HF-1AF01 R00 83/10/15 15pp 22171:071 24X Fiche 50-000,83/11/16,8402080029
- --B4020B0136 Preliminary Rev O to "Pre-Core Instrumentation Correlation," test results rept for B30516-0701 RUTMAN, J. Apriliation Not Assigned. 92HF-1Z201 ROO. B3/10/05 31pp 22171'086 24X Fiche 50-000.83/11/16,8402080029
- S Reportable occurrences, LERs & related correspondence
- 8402170263 Final Part 21 rept re cable separations in control room panels. Separate imaps for other facilities scheduled prior to fuel load to identify & correct cabling separation not in compliance w/Spec 13-EN-306.
 FATTERSON.R L Bechtel Corp 83/10/05 COLLINS, J T Region 4, Office of Director 3pp 22296,073 24X Fiche 50-528,83/10/05,8402170263

- B4020B0026 FOIA request for documents re facility hot functional testing problems including broken thermowells, loose & broken reactor coolant pump parts & loose thermal sleeves
 BERNABEI, Convernment Accountability Project 83/10/17 Office of Administration 2pp 22170 251 24X Fiche 50-528,83/10/17,84020B0026
- 8402170146 Part 21 rept re wearing ring failure on auxiliary feed water pump Pumps w/potential for wearing ring problems being evaluated Eristing users should review application for possible replacement of rings PATTY.D F Bingham-Willamette Co 83/11/08 Region 4. Office of Director 1p 22279 022 24x Fiche 50-528,83/11/08.8402170146
- 8402080029 Responds to FOIA request for documents re facility hot functional testing problems. Including broken thermowells, loose & broken reactor coolant pump parts & loose thermal slaves Forwards App A documents Documents also in PDR FELTON, J M Division of Rules and Records 83/11/16 GARDE, B Government Accountability Project 3pp 22170 253 24X Fiche 50-000, 83/11/16, 8402080029
- --8310200052 Provides update on status of efforts for resolving anomalies found during hot functional testing involving RCS pumps, thermal sleeves, thermowells, C-E shroud assemblies & metal filings on upper support structure LTCITRA, E A Licensing Branch 3 83/10/11 NOVAK, T M Assistant Director for Licensing 2pp 22171 119 24X Fiche 50-000, 83/11/16, 8402080029
- --8402080036 List of hot functional testing exceptions Related info encl * Affiliation Not Assigned 83/11/16 19pp 22170 R56 24X Fithe 50-000,83/11/16,8402080029
- --8402080047 Task interface agreement action plan re RCB damage discovered during evaluation of hot functional testing HOLAHAN, G , VOLLMER,R NRC - No Detailed Affiliation Given BIBHDP,T Region 5. Office of Director B3/08/16 ip 22170 279 24X Fiche 50-000,83/11/16.8402080029
- ---8402080064 Forwards listed reactor coolant pump drawings per 830818
 FOIA Request 83-448 re pump problems
 BISHOP.T W Division of Resident/Reactor Project & Engineering
 Programs 83/09/16 VAN BRUNTE E Arizona Public Service Co
 11pp 22170 286 24% Fiche 50-000:83/11/16:8402080029
- ~-8402080143 Submits daily highlight re reactor coolant pump problems following Jul 1983 hot functional testing Util to meet w/ vendor to discuss course of action
 LICITRA,E A Licensing Branch 3 83/08/04 DENTON,H, CASE,E, EISENHUT,D NRC No Detailed Affillation Given 2pp 22171 117 24X Fiche 50-000,83/11/16,8402080029
- 840214039B Requests add1 info re Part 21 rept dtd 83110B concerning wear ring failure in auxiliary feedwater pump furnished to facilities info requested within 25 days POTAPOVB, U Region 4. Office of Director 83/11/30 PATTY, D F Bingham-Willamette Co ip 22221 250 24X Fiche 50-000, 83/11/30, 8402140398
- --8402140422 Supplemental Part 21 rept re wear ring failure in auxiliary feedwater pumps, per 831130 request for add1 info Mear rings will be replaced on returned units w/AISI 420 wrought matl List of pumps in similar svc w/same wear ring encl PATTY, D F Bingham-Willamette Co 83/12/20 Region 4, Office of Director 2pp 22221: 251 24X Fiche 50-000,83/11/30,8402140378
- 8402070097 Further response to FOIA request for records re-problems encountered by util during hot functional testing Forwards App A documents Documents also available in PDR Search for addl documents continuing FELTON.J M Division of Rules and Records 83/12/22 GARDE.B Government Accountability Project 2pp 22189 084 24X Fichs 50-528,83/12/22,8402090097
- --8402070114 Draft trip rept of 831114-16 site visit to C-E, in Newington, NH, to review mfg of C-E-KSB reactor coolant pump & current testing of modified pump as applied to facilities Related info encl
 JACKSON, J E Equipment Gualification Branch 83/12/22
 NODNAN, V S Equipment Gualification Branch 11pp 22187-088
 24X Fiche 30-328,83/12/22,8402070077
- 8402030302 Interim Deficiency Rept DER 82-76 re Target Rock valves failing to meet spec/test requirements Initially reported on B21124 Final rept will be delayed until 840223 due to sytemsive investigation & evaluation VAN BRUNTLE E Arizona Public Service Co 84/01/12 B18H0P, T W Division of Resident Reactor Project & Engineering Programs. 2pp 22069 077 24X Fiche 50-528,84/01/12.8402030302

- 8402030363 Interim Deficiency Rept DER 83-10 re main steam relief valve tests exceeding 3% blowdown limit Initially reported on 830228 Final rept will be delayed until 840301 due to extensive investigation & evaluation VAN BRUNT,E E Arizona Public Service Co 84/01/12 BISHOP,T W Division of Resident Reactor Project & Engineering Programs 2pp 22044 075 24% Fiche 50~528,84/01/12.8402030365
- 8402030318 Interim Deficiency Rept DER B3-66 re motor driven auxiliary feedwater pump internal problem» Initially reported on 831011 Due to extensive investigation & evaluation final rept will not be submitted until 840329 VAN BRUNT, E E Arizona Public Bervice Co 84/01/13 818HDP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 22067 130 24% Fiche 50-528,84/01/13,8402030318
- 8402030423 Interim Deficiency Rept DER B3-70 re wiring in ERF cabinets not in conformance w/IEEE-384 criteria Initially reported on B31011 Due to extensive evaluation, final regt will not be submitted until 840229 VAN BRUNT, E E Arizona Public Service Co 84/01/13 818HDP, T W Division of Resident. Reactor Project & Engineering Programs 2pp 22068.278 24x Fiche 50-528,84/01/13,8402030423
- 8402030176 Interim Deficiency Rept DER 83-61 re low pressure safety injection pump failure to start & to produce required head Initially reported on 830914 Due to extensive investigation, final rept will be delayed until 840223 VAN RRUNT,E E Arizona Publit Service Co 84/01/16 819HDP,T W Division of Resident,Reactor Project & Engineering Programs 2pp 22068 129 24x Fiche 50-528,84/01/16,8402030176
- 8402030362 Deficiency Rept DER 82-61 re gassible failure of reactor coolant pump diffuser ring-cap screws Initially reported on B21021 Final rept expected by 840222 instead of 840123 due to extensive evaluation required VAN BRUNT,E E Arisona Public Service Co 84/01/18 BISHOP,T W Division of Resident, Reactor Project & Engineering Programs 2pp 22046 081 24% Fiche 50-528,84/01/18,8402030362
- 8402030415 Interim Deficiency Rept DER 83-8B re identified QA failures/lack of procedures & programs for const, testing & startup activities Initially reported on 831223 Due to extensive evaluation, final rept delayed until 840415
 VAN BRUNTLE E Arisona Public Service Co 84/01/18 BISHOP, T W Division of Resident.Reactor Project & Engineering Programs. Jpp 22068 298 24X Fiche 50-528,84/01/18,8402030415.
- 8402030455 Rev 1 to final Deficiency Rept DER 82-51 re Pullman-Kellog pips line failure in essential cooling water sys. Initially reported on 820910 Rev restates reportability under 100FR21 VAN BRUNT, E E Arizona Public Service Co 84/01/19 BIBHOP, TW Bivision of Resident, Reactor Project & Engineering Programs 13pp 22069:043 24X Fiche 50-528,84/01/19,8402030455
- B402030216 Revised interim Deficiency Rept DER 83-57 re cracks in control element astembly shroud Final rept will be completed by B40615

 VAN BRUNT, E E Arizona Public Service Co B4/01/20 BIBHOP, T W Division of Resident Reactor Project & Engineering Programs Spp 22067 217 24X Fighe: 50-528.84/01/20.8402030216
- --B402030219 Forwards proprietary "Interim Rept on Performance Evaluation of Palo Verde Control Element Assembly Shroud." Encl withheld (ref 100FR2 790)
 FERGUSON.C Combustion Engineering. Inc. 84/01/19 VAN
 BRUNF.E E Arizona Public Service Co ip 22067 220 24x
 Fiche 50-528,84/01/20,8402030216
- -8402030222 Affidavit of AE Scherer requesting proprietary CEN-267(V)-P re performance evaluation of control element assembly shroud be withheld (ref 100FR2 790)
 SCHERER, A E Combustion Engineering, Inc. 84/01/19 4pp. 22067-221 24X Fiche 50-528,84/01/20,8402030216
- 8402130285 Deficiency Rept DER 83-85 re perimeter microwave detection sys w/generic mfg defect Initially reported on 831223 Condition determined not reportable per 100FR50 55(e) VAN BRUNT, E & Artiona Public Service Co. 84/01/23 BISHOP, T W Division of Resident Reactor Project & Engineering Programs 2pp 22178-280 24X Fiche 50-528.84/01/23,8402130285

B402130385 Interim Deficiency Rept DER 83-72 re auxiliary bldg undersized welds Initially reported on 831026 Due to extensive investigation & evaluation, final rept will not be submitted until 840227
VAN BRUNT, K E Arizona Public Service Co 84/01/23 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 256 22177 066 24X Fiche 50-528,84/01/23,8402130385

1

- B4021304il Interim Deficiency Rept DER 83-75 re improperly torqued bolts securing two panel filler assemblies supplied by foxbore Initially reported on B31102 Final rept expected by 840227
 VAN BRUNT.E E Aritona Public Service Co 84/01/23 BISHOP.T W Division of Resident.Reactor Project & Engineering Programs 2pp 22203 269 24% Fiche 50-528,84/01/23.8402130411
- 8402130444 Interim Deficiency Rept DER 83-87 re Borg-Warner valve w/handwheel adapter nut missing & rising stem longer than operating bridle Initially reported on 840103 Evaluation continuing Final rept expected by 840410 VAN BRUNT, E E Arizona Public Service Co 84/01/24 DISHOP, T W Division of Resident Reactor Project & Engineering Programs 3pp 22202 050 24X Fiche 50-528,84/01/24,8402130444
- 8402130406 Final Deficiency Rept DER 82-61 re C-E reactor coolant pway diffuser ring cap screw failure & damage to nump Initially reported on 821021 Listed mods implemented Condition determined not reportable per 10CFR80 55(e)

 VAN BRUNT, E E Arizona Public Service Co 84/01/25 BISHOP, T. H Division of Resident Reactor Project & Engineering Programs Spp 22203 304 24% Fiche 50-528.84/01/25,8402130406
- B402130391 Final Deficiency Rept DER 83-62 re core support barrel snubbers w/loose or missing cap screw retainer pins initially reported on 830919 Lost pins will be replaced Condition determined not reportable per 10CFR50 55(e) VAN BRUNT.E E Arizona Public Service Co 84/01/26 BISHOP.T W Division of Resident.Reactor Project & Engineering Programs. App 22202 140 24X Fiche 50-528.84/01/26.8402130391
- 8402130415 Interim Deficiency Rept DER 83-64 re failure of Target Rock pressure relief valves to meet prerequisite tests Initially reported on 830928 Due to extensive investigation & evaluation, final rapt expected by 840305 VAN BRUNT, E & Arisona Public Service Co 84/01/26 BIBHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 22202 078 24% Fiche 50-528,84/01/26,8402130415
- 8402130458 Final Deficiency Rept DER 83-86 re failure of C-E seismic analysis of shutdown HX to adequately address baseplate thickness Initially reported on 831223 One-inch plates will be added to base plates. Also reportable under Part 21 VAN RRUNT, E. E. Arizona Public Service C. 684/01/26 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs Spp 22202 115 24X Fiche 50-528, 84/01/26, 8492130458
- 8402130386 Rev i to interim Deficiency Rept DER 83-49 re impeller blades & diffuser bolts broken/loose in reactor coolant pumps Initially reported on 830715 Final rept will be submitted by 840615 Results of C-E review encl VAN DRUNT.E E Ariona Public Service Co 84/01/27 BIGHOP, T. W. Division of Resident.Reactor Project & Engineering Programs 7pp 22203 281 24X Fiche 50-528,84/01/27,8402130386
- 8402130426 Rev 1 to interim Deficiency Rept DER 83-50 re broken reactor coolant pump impeller blade Initially reported on 830718 Due to duplication of info & reporting, DER 83-50 being combined w/DER 83-49 Final rept expected by 840615
 VAN BRUNT, E & Artiona Public Service Cn 84/01/27 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 3pp 22201 300 24X Fiche 50-528,84/01/27,8402130426
- 8402130024 Interim Deficiency Rept DER 83-79 re ac interference spiks on 123-volt dc bus (diesel generator) exceeding spec. Initially reported on 831118 Due to extensive investigation & evaluation, final rept will not be submitted until 840320. VAN BRUNT, E Arisona Public Service Co 84/01/30 BISHOP, T. W Division of Resident Reactor Project & Engineering Programs. 2pp 22249, 247 24X Fiche 30-526, 84/01/30, 8402150024
- 8402150272 Final Deficiency Rept DER 83-40 re low pressure safety injection & containment spray pump motors w/defective welds & loaking oil Initially reported on 830629 Defective welds identified & repaired Also reported per Part 21.

 VAN BRUNT, E E Arizona Public Service Co 84/02/02, BISHOF, T. W. Division of Resident, Reactor Project & Engineering Programs 4pp 22242 342 24X Fichs 50-528.84/02/02.8402150272
- 8402290102 Interim Deficiency Rept DER 82-46 re ITT-Barton pressure transmitters supplied by C-E not meeting overpressure requirements Initially reported on 820824 Due to extensive investigation, info will not be finalized until 840315 VAN BRUNTLE E Arizona Fublic Service Co. 84/02/03, BIBHOP.T.H Division of Resident Reactor Project & Engineering Programs. 2pp 22428 003 24X Fiche 50-528.84/02/03.8402270102.

- 8402280351 Revised interim Deficiency Rept DER 83-84 re 3/8-inch bolts missing from seismic tie downs of floor frame assemblies for motor control ctrs Initially reported on 831206 Installation work in progress Next rept by 840515

 VAN BRUNT, E E Artiona Public Service Co 84/02/06 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 7pp 22404 219 24X Fiche 50-528, 84/02/06, 8402280351
- B402290207 Interim Deficiency Rept DER 83-80 re defect in Anchor/Darling main feedwater isolation valves Initially reported on 831122 Final rept delayed due to extensive investigation & evaluation & will be submitted by 840309 VAN BRUNT.E E Artions Public Service Co 84/02/06 BISHOP.T W Division of Resident, Reactor Project & Engineering Programs 2pp 22425 115 24X Fiche 50-528,84/02/06,8402290207
- B402290263 Interim Deficiency Rept DER B3-78 re lack of documentation in user test & controlling procedure for rock bolt expansion anchors Initially reported on B31209 Next rept delayed until 840316

 VAN BRUNT, E E Arizona Public Service Co B4/02/06 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 22427 214 24% Fiche 50-528,84/02/06,8402290263
- 8402280452 Final Deficiency Rept DER 83-68 re battery racks constructed w/nuts & bolts not meeting Tech Specs Initially reported un 830928 Nonconforming hardware replaced on battery racks & NCR SE-2783 dispositioned as rework VAN BRUNT, E E Arizona Public Service Co 84/02/09 BISHOP, J W Division of Resident. Reactor Project & Engineering Programs 4pp 22405 286, 24% Fiche 50-528,84/02/09,8402280452
- 8402280301 Interim Deficiency Rept DER 84-01 re apparent inadequacy of startup test program to track retests of preoperational tests. Initially reported on 840120 Final rept expected by 840409 VAN BRUNT, E E Arizona Public Service Co 84/02/13 BISHOP, T W Division of Resident.Reactor Project & Engineering Programs 3pp 22399, 213 24% Fiche 50-528, 84/02/13, 8402280301
- 84022B0456 Interim Deficiency Rept DER 63-56 re discrepancies w/MSIVs supplied by Anchor-Darling Initially reported on 830808 Next rept anticipated by 840316
 VAN BRUNT, E E Arizona Public Bervice Co. 84/02/14 BIBHOP, T W Division of Resident Reactor Project & Engineering Programs | Ip 22407 058 | 24X Fiche 50-528,84/02/14,8402280456
- B402280324 Interim Deficiency Rept DER 82-76 re Target Rock valves not meeting spec/test requirements Initially reported on 821124 Next rept will be submitted by 840413 VAN BRUNT, E. E. Arizona Public Bervice Co. 84702/15 BISHOP, T.W. Division of Resident, Reactor Project & Engineering Programs 2pp 22397 125 24X Fiche 50-528, 84702/15, 8402280324.
- 8402280360 Interim Deficiency Rept 84-b2 re excessive rust, scale & pitting in clevis & arm of several 81 & CH valves Initially reported on 840123 Evaluation in progress. Next rept will be submitted by 840327

 VAN BRUNTI E. E. Arizona Public Bervice Co. 920715 BISHOP, T W DIVISion of Resident. Reactor Project & Engineering Programs Gpp 22404 226 24X Fiche 50-528, 84/02/15, 8402280360
- 8402260481 Interim Deficiency Rept DER 83-61 re low pressure safety injection pump failure to start & to produce required head. Initially reported on 830914 Next rept delayed until 840417 VAN BRUNT, E.E. Arizona Public Service Co. 84/02/15 818HOP, T.W. Division of Resident, Reactor Project & Engineering Programs 2pp 22404, 360. 24% Fiche 50-528, 84/02/15, 8402280481
- T Hearing transcripts on non-entitrust matters
- 8402130007 Responds to appeal re denial of FOIA request for documents concerning investigation of allegations at facility Forwards App A documents, Documents completely & partially withheld (ref FOIA Exemptions 7 & 4)
 CHILK, B J Office of the Secretary of the Commission, 83/11/10
 BERNABEIL Government Accountability Project, 44pp 22238 100, 24X Fiche 50-528,83/11/10.8402130007
- --8402130270 Transcript of closed Commission 830315 meeting in Washington,DC re discussion/possible vote on contested issues in full power proceeding Pp 1-57 Portions deleted & Commissioners. 83/03/15. 32pp. 22240 331. 24X Fichm. 30-528,83/11/10,8402130007

- DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- B402i30D05 Appeals denial of FOIA request for documents re R Qunderson & senior Bechtel manager allegations of electrical problems & deficiencies at facilities
 YOUNG.M C Covernment Accountability Project 83/05/13 NRC No
 Datailed Affiliation Olven 2pp 2223B 093 24X
 Fiche 50-529, 83/05/13,840213B005
- 8402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Pape) meetings forwards App A.B & C documents
 FELTON.J M Divisson of Rules and Records 83/10/31
 ROSENBAUM.D M Technical Analysis Corp 19pp 22193 292 24X
 Fiche 50-000,83/10/31.8402090003
- --B204070041 Trip rept of 820316-19 visit of caseload forecast panel to facility re determination of fuel load dates load dates estimated to be Nov 1983, Nov 1984 & Nov 1985 for Units 1, 2 & 3-respectively MIRAGLIA.F J Operating Reactors Branch 3 82/03/30 EISENHUT, D G Division of Licensing App 22194 055 24X Fiche 50-000, 83/10/31, 8402090003
- --B402070070 Trip rept of B30622-24 Caseload Forecast Panel site visit re plant status review Projected fuel load date comparisons listed KNIGHTON.G W Licensing Branch 3 83/10/31 NOVAK, T M Assistant Director for Licensing 2pp 22194 059 24X Fiche. 50-000.83/10/31.8402090003
- --B4020700B2 Handwritten notes & calculations re const activities & fuel lead preparation

 * NRC No Detailed Affiliation Given 79/04/25 2pp
 22196-03i 24X Fichs 50-000, 83/10/31.B402090003
- --8402090087 Handwritten graphs re const activities Related info enc1 * NRC - No Detailed Affiliation Given 83706/28 4pp 22196-035 24% Fichs 50-000,83710/31.8402090003
- 8402130007 Responds to appeal re denial of FOIA request for documents concerning investigation of allegations at Pacility Forwards App A documents Documents completely & partially withheld (ref FOIA Exemptions 7 & 4)
 CHILK, B. J. Office of the Becretary of the Commission 83/11/10
 BERNADEI, L. Oovernment Accountability Project 44pp 22238, 100
 24X Fiche 90-529, 83/11/10, 8402130007
- --B304040543 Forwards list of items currently under insp/investigation which have recently been closed out in response to 830318 memo No allegations should impact plant safety or current schedule for initial fuel loading DIRCKB, W.J. Office of the Executive Director for Operations 83/03/29 CHILK, S.J. Office of the Secretary of the Commission 3pp 22240 125 24X Fiche 50-329,83/11/10,8402130007
- --8402130010 Discusses 820825 Benhtel alleger telcon re allegations concerning defective electrical & const items at facilities Specific defects listed Related info encl SHACKLETON, O.C. Region 5, Office of Director, B3/03/18 STERNBERG, D.M. Region 5, Office of Director 7pp 22238 144 24X Fiche: 50-527, 83/11/10, 8402130007
- --8402130012 Lists three allegations of immediate concern.currently being investigated under Cases 5-82-006.009 & 011 Related info encl.

 SHACKLETON, O C Region 5, Office of Director 83/03/29 DEWEY.L S Office of the Executive Legal Director 18pp 22238 181 24X Fiche:50-529,83/11/10.8402130007
- --8402130014 Bubmits info re 820525 allegations concerning electrical const deficiencies, Portions deleted SHACKLETON, O C NRC No Detailed Affiliation Given 82/05/27 BISHOP, T W NRC No Detailed Affiliation Given 1p 22238 167 24X Fiche: 50-529, 83/11/10, 8402130007
- --8402130016 Submits info re 820526 allegations concerning electrical const deficiencies.

 BHACKLETON.O C. NRC No Detailed Affiliation Given 82/05/27
 BISHAP.T W NRC No Detailed Affiliation Given 3pp 22238:170
 24X Fiche 50-529,83/11/10,8402130007
- --8402130019 Handwritten notes re death threats against alleger concerning const deficiencies Related info encl.

 SHACKLETON.O.C. NRC No Detailed Affiliation Olven 82/05/24
 2pp. 2228 187 24X Fiche 50-529.83/11/10.6402130007

- --8402130030 Forwards recipient signed, sworn statement re 820602 allegations Results will be provided following investigation completion Related info encl SHACKLETON.0 C NRC No Detailed Affiliation Given 82/06/09 QUNDERSON.R D Affiliation Not Assigned 1p 22238 241 24X Fiche 50-529.83/t1/10.8402130007
- --8402130044 Discusses 820325 telcon from anonymous caller alleging defective HPSI & LPSI sys at plant TEDFDRD.C F Arizona, State of 82/03/26 VORDERBRUEGOEN Region 5, Office of Director ip 22238 242 24% Fiche 50-529.83/11/10,8402130007
- --8402130047 Discusses allegations re electrical const deficiencies at facilities Case under investigation SHACKLETON, D C Region 5, Office of Director 82/07/22 NRC No Detailed Affiliation Given 2pp 22238 245 24X Fiche 50-529, B3/11/10, 8402130007
- --8402130053 "Investigations Status Rept " Related info encl * Office of Investigation 82/10/19 32pp 22238 254 24X Fiche 50-527, 83/11/10,8402130007
- --5402130122 Informs of L Bernabei intention to make contention over RD Gunderson affidavit re allegations concerning facility const deficiencies Insp & investigations should be completed immediately SHACKLETON.D C Region 5. Office of Director 83/03/27 STERNBERG, D M Region 5. Office of Director 1p 22238 305 24X Fiche 50-529,83/11/10,8402130007
- --8402130127 Informs that RD Gunderson allegations that have not been investigated/inspected not presently within OFc of Investigations purview Region V insp requested SHACKLEYON, O C Region 5. Office of Director 83/03/30 STERNBERG, D M Region 5. Office of Director 2pp 22238 306 24% Fiche 50-529,83/11/10,8402130307
- --8402130134 Informs that WR Royce allegation does not come under Ofc of Investigations jurisdiction Allegations submitted to Region V for followup Related info ancl SHACKLETUN,O C Region 5, Office of Director 83/03/30 STERNBERG,D it Region 5, Office of Director 242pp 22238 308 24X Fiche 50-529,83/11/10,8402130007
- --8402130143 Rev 0 to Procedure 909A-0ZZ11. "Temporary Mods " Related info encl GARDNER, B J Arizona Public Service Ca 82/05/10 43pp 22237 190 24X Fiche 50-529,83/11/10.8402130007
- --B402130174 "Const Insp Flanning for Concrete Replacement" Related info ent! * Bechtel Corp JDB 10407 77/12/04 11pp 22240 089 24X Fiche 50-529,83/11/10,8402130007
- --8402130182 Provides Ofc of Policy Evaluation immediate effectiveness analysis of Palo Verde licensing board decision for Unit 1 Related info encl ZERDE-J E Office of Policy Evaluations SECY-83-045 83/02/15 25pp 22240 100 24x Fiche 50-529.83/11/10.8402130007
- --8402130219 Handwritten notes re allegations concerning facility defects Related info enci * Region 5. Office of Director 82/05/25 15pp 22240 141 24% Fiche 50-529.83/11/10,8402130007
- --8402130221 Discusses allegations from anonymous alleger from Bechtel re electrical installations Related info encl SHACKLETON,O C Region 5. Office of Director 82/07/22 Region 5. Office of Director 46pp 22240 196 24X Fiche 50-529,83/11/10,8402130007
 - 3402130250 Summary of investigation re PL Hourihan allegations concerning electrical work Handwritten Related info encl. SHACKLETON.0 C Region 5, Office of Director 82/05/24 37gp 22240 252 24X Fiche 50-529,83/11/10.8402130007
 - 8402130262 Discusses anonymous allegations from Becktel employee ra electrical installations SHACKLETON.O C Office of Investigation 82/07/22 Office of Investigation 3pp 22240 328 24X Fiche 50-529,83/11/10, 8402130007
- 8402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILM,8 J Office of the Secretary of the Commission 83/12/14 Public Document Branch 1p 22281 023 24X Fiche 50-000,83/12/14, 240916003

- --B402160394 Discusses SECY-83-125 re immediate effectiveness decision & review of ALAB-713
 CHILK, S. J. Dffice of the Secretary of the Commission B3/05/19
 PLAINE, H. H. Dffice of the General Counsel 1p 22281 286 24%
 Fiche 50-000, 83/12/14, 8402160003
- B402270072 Final response to FOIA request for Commissioner voting & attendance records from 810401 to present Forwards documents listed on App. A Documents also available in PDR FELTON. J M Division of Rules and Records 83/12/22 KAMENAR, P. D. Washington Legal Foundation 3pp. 22410 109 24X Fiche 50-529, 83/12/22, 8402270072
- --B304040550 Advance copy of staff requirements memb re 830315 discuttion & possible vote in Washington, DC on contested issues in full power proceeding CHILK.S J Office of the Secretary of the Commission 83/03/18 DIRCKB
- 8402070431 Requests add1 info re proposed method for estimating gaseous effluent flow rates in lieu of direct measurements, demonstrating conservatism of flow rate values under all conditions KNICHTON, G W Licensing Branch 3 84/01/16 VAN BRUNT, E A Arizona Public Service Co 2pp 22142 095 24X Fiche 50-528.84/01/16,8402070431
- 8401270152 Forwards nonproprietary "Safety Injection Notile Thermal Liner" & "Resistance Temp Detector Thermowell," for docketing & distribution VAN DRUNT, E E Aritona Public Service Co 84/01/24 KNIGHTON, O W Licensing Dranch 3 ip 22038 001 24% Fiche 50-528,84/01/24. 8401270152
- 8402060240 Forwards nonproprietary "Interim Rept on Performance Evaluation of Palo Varde Control Element Assembly Shroud" VAN BRUNT, E E Arizona Public Service Co 84/01/31 KNIGHTON, Q Licensing Branch 3 ip 22084 213 24X Fiche 50-528,84/01/31, 8402060240
- ~~B402060247 Nonproprietary "Interim Rept on Performance Evaluation of Palo Verde Control Element Assembly Shroud" * Combustion Engineering, Inc CEN-267(V)-NP 84/01/31 81pp 22084 214 24X Fichs 50~528,84/01/31.8402060240
- 8402010410 Generic Ltr 84-04 to all operating PWR licensees, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Evc list encl ETSENHUT.D Q Division of Licensing 84/02/01. Consolidated Edison Co of New York. Inc 87pp R2177 087 24X Fiche 50-000.84/02/01.8402010410
- 8402160470 Forwards request for addl info based on review of June 1783 data base values for facility core protection calculators & control element assembly info should be provided within 2 wks
 KNICHTON,O W Licensing Branch 3 84/02/06 VAN BRUNT,E E
 Arizona Public Service Co 3pp 22302 160 24X
 Fiche 30-328,84/02/06.8402160470
- 8402230341 Provides partial info re German reactor coolant pump (RCP) design German design similar to RCP seal used in C-E K8B pump at Pato Verde
 JACKSON.J E Equipment Qualification Branch 84/02/07 NOGNAN.V S
 Equipment Qualification Branch 2pp 22377 052 24X
 Fiche 50-528,84/02/07.8402230341
- 8401i90039 Board Notification 84-032 provides add1 info on environ qualification Submittal augments info in Board Notifications 84-004 & 84-007 EIGENHUT, D. 0 Division of Licensing 84/02/13 Atomic Safety and Licensing Board Panel 10pp 22314 204 24% Fiche 50-000,84/02/13.8401190039
- 8402170241 Notifies that util response to NRC 840110 request for schedule re differences between facility control room design review & NRC detailed control room design review program will be provided by 840330

 VAN BRUNT, E E Arizona Public Service Co 84/02/13 XNIOHTON, Q. Licensing Branch 3 ip 22296 149 24X Fiche 50-528, 84/02/13, 8402170241
- 8402170257 Trip rept of 831108 & 07 visits to Saint-Laurent-Des-Eaux plant & KSB Labs, Frankenthal, Wast Germany, respectively, reglant organization & reactor coolant pump design KSB Labs provided reactor coolant pumps for Palo Verde, NOVAK, T M Assistant Director For Licensing 84/02/13 EISENHUT.D & Division of Licensing 4pp 22318 235 24% Fiche 50-528,84/02/13,8402170257

- 8402160069 Forwards addl info re impact of high energy line breaks on control sys.per 831205 & 13 telcon concerns re Guestion
 - VAN BRUNT, E. E. Arizona Public Service Co. 84/02/14 KNIGHTON, G W Licensing Branch 3 Spp. 22275 264 24% Fiche 50-528, 84/02/14, 8402160069
- 8401190068 Board Notification 84-033 provides "Sys Interaction Program." task action plan for Unresolved Safety Issue A-17 Distribution list encl EISENHUT.DO Division of Licensing 84/02/16 PALLADINO Commissioners Spp 22482 091 24X Fiche 50-000.84/02/16, 8401190068
- 8402270635 Natification of 840302 meeting w/C-E in Windsor, CT to perform audit of results of Phase I & II testing Agenda encl
 - EliCiTRA, E A Licensing Branch 3 84/02/16 KNIGHTON, G W Licensing Branch 3 4pp 22414 022 24% Fiche 50-528, 84/02/16, 8402270635
- 8402270340 Forwards response to NRC 831220 request for add1 info re TMI Item II F 2, "Instrumentation for Detection of Inadequate Core Cooling "

 VAN BRUNT, E E Arizona Public Service Co 84/02/23 KNIGHTON, G
 Licensing Branch 3 17pp 22389 288 24X Fiche 50-528, 84/02/23, 8402270340
- B402270034 Forwards clarifications & justifications made to certain revs included in Amend 12 to FSAR

 VAN BRUNT.E E Arizona Public Service Co 84/02/24 KNIGHTUN.G Licensing Branch 3 4pp 22426 182 24X Fiche 50-528, 84/02/24, 8402270034
- B40229006B Forwards preliminary description for RCS demonstration test Specific aspects will be discussed at 840920 meeting VAN BRUNT.E E Arizona Public Service Co 84/02/24 KNIGHTON.O Licensing Branch 3 10pp 22421 009 24X Ficha 50-528,84/02/24, B40229006B
- B402270177 Forwards proposed changes to Section 1 8 of FSAR re Reg Quides 1 28 & 1 33 covering preoperational & startup testing Changes will be incorporated into future FSAR amend VAN BRUNT.E E Arizona Public Service Co 84/02/24 KNIGHTON.G Cicensing Branch 3 8pp 22426 287 24X Fiche 50-528,84/02/24. 8402290177.
- E NRC Bafety Evaluation Report (SER), supply & correspondence
- 84020B0217 Forwards list of onsite emergency organization personnel as of 840101.per SSER 4 (NUREO-0857)

 VAN BRUNT, E E Arizona Public Service Co 84/01/27 KNIGHTON.9

 Licensing Branch 3 8pp 22130 104 24X Fiche 50-528, 84/01/27, 8402080217
- 8402080332 Advises that design of atmospheric dump valve accumulators reevaluated.per NUREO-0857 BER. Section 5 4 3 Design meets requirements info will be reflected in upcoming amend to FBAR
 - FBAR VAN BRUNT, E E Arizona Public Service Co 84/01/27 KNIGHTON, G Licensing Branch 3 5pp 82131 216 84% Fiche 50-528, 84/01/27, 8402080332
- E402130175 Forwards addi info on potential finding Repts 027,050 & 065, per SBER 5 (NUREO-0857), Section 17 7 3 re independent 0A evaluation

 VAN BRUNTLE E Arizona Public Service Co 84/02/06 KNIOHTON, 0

 Litensing Brench 3 5pp 22204 134 24X Fiche 50-528, 84/02/06, B402130175
- 8402270495 Forwards revised pages to pump & valve testing program, categorizing pressure isolation valves as ac according to ABME Bection XI.per BER (NUREG-0857)

 VAN BRUNTLE E Arizona Public Service Co 84/02/17 KNIGHTON. C

 Licensing Branch 3 6pp 22389 258 24X Fiche 50-528,84/02/17,8402270495
- F Security, medical, emergency & fire protection plans
- 8402160305 Revised emergency plan implementing procedures, including Procedures EPIP-01 re emergency organization. EPIP-03 re notification of unusual implementing actions & EPIP-04 re alert implementing actions W/840210 ltr BRCHN. B. A. CLYDE, M. R., VAN BRUNT, E. E. Arizona Public Service Co. B84/01/20, KNICHTUN, C. Licensing Branch 3 126pp 22272 238 24X Fiche 50-528;84/01/20,8402160305
- 8402080217 Forwards list of onsite emergency organization personnel as of 840101, per 85ER 4 (NUREO-0857)

 VAN BRUNT, E. E. Arizona Public Service Co. 64/01/27 KNIGHTON, G. Licensing Branch 3. 8pp. 22130 104 24x Fiche 50-528, 84/01/27, 8402080217

- 8402160653 Responds to 830616 request to establish backup emergency operations facility in Palo Verde Inn approx 8 miles from plant Location acceptable EISENHUT, D.G. Division of Licensing 84/01/31 VAN BRUNT, E.E. Arizona Public Service Co. 2pp. 22292 357 24X Fiche 50-528.84/01/31,8402160653
- 8402150271 Advises that review of util maint program for valves & hydrants disclosed that sys surveillances still undeveloped & no preventive maint conducted Problem w/fire loops identified by Bechtol re amount of valve seat leakage VAN BRUNT, E E Arizona Public Service Co 84/02/08 MARTIN, J D Region 5, Office of Director 2pp 2250 294 24X Fiche 50-528,84/02/08.8402150271
- 8402220386 Submits supplemental response to 930728 ltr re independent source range neutron flux monitor at remote shutdown panel Design features & procedural guidance in existing design satisfy 10CFR50, App A. Criterion 3. based on listed features VAN BRUNT, E. E. Arizona Public Service Co. 84/02/14 KNIGHTON, G. Licensing Branch S. 3pp. 22335-287 24X Fiche 50-528.84/02/14, G402220386
- 8402270352 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per 810709 Generic Ltr 81-27 W/o request entire plan will be placed in FDR KNIGHTON.O W Licensing Branch 3 84/02/14 VAN BRUNT.E E Arizona Public Service Co 3pp 22438 259 24X Fiche 50-528.84/02/14.84022790352

G Adjudicatory correspondence

- B402130007 Responds to appeal re denial of FDIA request for documents concerning investigation of allegations at facility Forwards App A documents Documents completely & partially withhold (ref FOIA Exemptions 7 & 4)
 CHILK, S J Office of the Secretary of the Commission 83/11/10
 BERNABEL, L Government Accountability Project 44pp 22238 100
 24X Fiche 90-529.83/11/10.8402130007
- --8402130024 Affidavit of RD Gunderson re allegations concerning electrical const deficiencies Related info enc! GUNDCREON.R D Bechtel Corp 83/11/10 Slpp 22238 190 24X Fichs 50-529,83/11/10,8402130007
- --8402130108 Forwards R Gunderson & W Royce affidavits & supporting prhibits re allegations concerning const deficiencies at facilities Problems evidenced not adequately addressed GARDE.0 P Government Accountability Project 83/02/28 FORTUNA.R Office of Investigation 2pp 22238 301 24X Fiche 30-529.83/11/10.8402130007
- B402010141 Ack receipt of Davis comments re modeling contentions DEWEY, L S Hearing Branch 3 84/01/27 BERLIN.K Winston & Strawn 1g 22038 215 24% Fiche 50-529,84/01/27,8402010141
- B402140116 Responds to West Valley B31116 outline of intent to withdraw source term & modeling contentions NRC supports request for withdrawal DEREY,L B. Hearing Branch 3. COLE.R F. Record Services Branch (Document Control Desk). HOURIHAN,L. Atomic Safety and Licensing Appeal Famel 84/02/08 BERLIN.K. Winston & Strawn FLATT.W. Smell & Wilmer 30pg. 22228 159. 24X Fiche 50-529,84/02/08,8402140116.
- 8402220241 Forwards 840206 daily highlight rept to low pressure cafety injection pumps, per staff agreement REIB.E J Hearing Branch 3 84/02/15 BERNABELL Government Accountability Project 2pp 22339 197 24% Fiche 50-529,84/02/15.840220241

ii General correspondence

- 8402060078 Informs of recent rev in util organizational structure B Ide replaced J Roedel as manager of corporate 0A/GC WOODS, T G Arizona Public Service Co 64/01/31 KNIGHTON, G Licensing Branch 3 ip 22088 239 24X Fiche 50-528, 84/01/31, 8402060078
- B40213003B Informs that D Karner appointed assistant vice-president for nuclear operations Karner will rept to EE Van Brunt & will provide add1 mgt support during transition from const to operation VAN BRUNT, E E Arizona Public Bervice Co 84/02/06 KNIGHTON, Q Licensing Branch 3 1p 22204 085 24X Fiche 50-528, 84/02/06, 84/02/3003B

- M. Utility Final Safety Analysis Report (FSAR) & amends
- 8402230119 Amend 12 to FSAR W/840221 ltr VAN BRUNT.E E Ariiona Public Service Co 84/02/29 1241pp 22367 322 24% Fiche 50-528-84/02/29.8402230119
- G Inspection reports, IE Bulletins & correspondence
- 8402270555 FOIA request for all agency records & info re NRC const assessment team imp conducted from 830906~30 at facilities BERNABEIL Government Accountability Project 83/10/07 Office of Administration 2pp 22414 144 24X Fiche 50-528.83/10/07, 8402270555
- 8402270550 Appeals denial of FBIA request for documents re NRC const assessment team insp conducted from 830906-30 at facilities DERNABELL Government Accountability Project 837/2705 Office of Administration Lp 22414 143 24X Fiche 50-529,83/12/05, 8402270550
- 8402270544 Responds to appeal re denial of FOIA request for documents re NRC const assessment team insp conducted from 830706-30 at facilities Rept provided on 831201 FELFON.J M Division of Rules and Records 84/01/12 DERNABEI, L Government Accountability Project ip 22414 142 24X Fiche 50-528-84/01/12.8402270544
- 8312120153 IE Info Notice 84~06. "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York Inc 120pp 22058 001 24X Fiche 50-000-84/01/25,8312120153
- B401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/03 Consolidated Edison Co of New York, Inc 119pp 22114 179 24X Fiche 50-000.84/02/03,8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl DEYDUNG.R C Director's Office. Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp 22177 156 24% Fishe 50~000.84/02/03.8401190017
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Inaps of Fire Protection Safe Shutdown Sys (10CFR50.App R) " Syc list encl JGRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York Inc 124pp 22365 259 24% Fache 50-000.84/02/13,8401190041
- 8401190039 IE Info Natice 84-08. "10CFR50 7. 'Employee Protection '"
 Svc list encl
 JURDAN.E L. Division of Emergency Proparedness & Engineering
 Response (Post 8301031 84/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24% Fishe 50-000.84/02/14.8401190039
- 8401190043 IE Info Notice 83-63, Suppl 1. "Potential Failures of Westinghouse Type SA-1 Differential Rolays " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of New York, Inc. 118pp 22366 142 24X Fiche 50-000.84/02/15,8401190045
- 8401190042 IE Info Notice 84~10. "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Svr list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of New York, Inc 116pp 22366 024 24X Fiche 50-000.84/02/21,8401190062
- 9401190066 IE Info Notice 84~11, "Training Program Deficiencies"
 Syc list enc)
 JURDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co. of New
 York, Inc. 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190046
 - 01190067 IE Info Notice 84-12: "Failure of Soft Seat Valve Seals" ive list encl
 IDROAN,E L Division of Emergency Preparedness & Engineering
 Personse (Post 830103) 84/02/27 Consolidated Edison Co of New
 ork, Inc 120pp 22431 060 24X Fiche 50-000,84/02/27.8401190067
 - Reportable occurrences. LERs & related correspondence
 - 170146 Part 21 rept re wearing ring failure on auxiliary feed ter pump Pumps w/potential for wearing ring problems ing evaluated Existing users should review application or possible replacement of rings ATTY.D. F. Bingham-H:1lamette Co. 83/11/08 Region 4, Office of irector 19 22297 022 24X Fiche 50-528,83/11/08,8402170146

- B402080027 Responds to FDIA request for documents re facility hot functional testing problems, including broken thermowells, loose & broken reactor coolant pump parts & loose thermal sleeves Forwards App A documents Documents also in PDR FELTON, J M Division of Rules and Records B3/11/16 GARDE. G Government Accountability Project Jpp 22170 293 24X Fishs 50-000.83/11/16.8402080029
- --B310200052 Provides update on status of efforts for resolving anomalist found during hot functional testing involving RCS pumps, thermal sleeves, thermowells, C-E shroud assemblies & metal filings on upper support structure
 LICITRA: EA Licensing Branch 3 83/10/11 NOVAX.T M Assistant'
 Director for Licensing 2pp 22171 119 24X
 Fishe 50-000,83/11/16,8402080029
- --8402080036 List of hot functional testing exceptions Related info and # Affiliation Not Assigned 83/11/16 19pp 22170 256 24% Fiche 50-000, 83/11/16, 8402080029
- B40214039B Requests addl info re Part 21 rept dtd B3110B concerning wear ring failurs in auxiliary feedwater pump furnished to facilities Info requested within 25 days PDTAPOVS.U Region 4. Office of Director B3/11/30 PATTY.D F. Bingham-Willamette Co ip 22221 250 24X Fiche 50~000.63/11/30.8402140398
- --8402140422 Supplemental Part 21 rept rs wear ring failure in auxiliary feedwater pumps, per 831130 request for add1 info Wear rings will be replaced on returned units w/AIS1 420 wrought matil List of pumps in similar svc w/same wear ring encl PATTY, DF Bingham-Willamette Co 83/12/20 Region 4, Office of Director 2pp 22221 251 24X Fiche 50-000.83/11/30, 8402140398,
- 8402090097 Further response to FOIA request for records re problems encountered by util during hot functional testing Forwards App A documents Documents also available in PDR Search for addl documents continuing FELTON. J M Division of Rules and Records 83/12/22 GARDE. B Government Accountability Project 2pp 22189 084 24X Fiche, 50-528, 83/12/22, 8402090097
- --8402090114 Draft trip rept of 831114-16 site visit to C-E, in Newington NH, to review mfg of C-E-KBB reactor coolant pump & current testing of modified pump as applied to facilities Related info enci JACKBON.J E Equipment Gualification Branch 83/12/22 NODNAN.V S Equipment Gualification Branch 11pp 22187 088 24X Fiche 50-528,83/12/22.8402070077
- 8402030302 Interim Deficiency Rept DER 82-76 re Target Roct valves failing to meet spec/test requirements Initially reported on 821124 Final rept will be delayed until 840223 due to extensive investigation & evaluation VAN DRUNT, E & Arizona Public Bervice Co 84/01/12 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 22069 077 24% Fiche 50-528,84/01/12,8402030302
- B402030365 Interim Deficiency Rept DER 83-10 re main steam relief valve tests exceeding 5% blowdown limit Initially reported on 830228 Final rept will be delayed until 840301 due to extensive investigation & evaluation VAN BRUNT.E E Arizona Public Service Co 84/01/12 BISMOP, T W Division of Resident, Reactor Project & Engineering Programs. 2pp 22065 075 24% Fiche 50-528, 84/01/12, 8402030365
- 8402030408 Deficiency Rept DER 82-73 rs ITT Grinnel pipe support clasps W/excess gap, resulting in improperly secured pipe Initially reported on 821124 Due to extensive investigation & evaluation.info will not be finalized until 840220 VAN BRUNT,E E Arizona Public Service Co 84/01/13 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 22068 337 R4X Fiche 50-529,84/01/13,8402030408
- 8402030423 Interim Deficiency Rept DER 83-70 re wiring in ERF cabinets not in conformance w/IEEE-384 criteria Initially reported on 831041 Due to extensive evaluation final rept will not be submitted until 840229 VAN BRUNT.E E Aricona Public Service Co 84/01/13 BISHOP.T.W Division of Resident Reactor Project & Engineering Programs. 2pp 22068.278. 24X Fiche 50-528,84/01/13,8402030423
- 8402030362 Deficiency Rept DER 82-61 re possible failure of reactor coolent pump diffuser ring-cap screws Initially reported on 821021 Final rept expected by 840222 instead of 840123 due to extensive evaluation required VAN BRUNT, E. E. Arizona Public Service Co. 84/01/18 BIBHOP, T. W. Arizona P

- 8402030415 Interim Deficiency Rept DER B3-B8 re identified QA failures/lack of procedures & programs for constitesting & startup activities Initially reported on B31223 Due to extensive evaluation, final rept delayed until 840415
 VAN BRUNT,E E Arizona Public Service Co 84/01/18 BISHOP,T W Division of Resident.Reactor Project & Engineering Programs Spp 22068 298 24x Fiche 50-528,84/01/18,8402030415
- 8402130285 Deficiency Rept DER 83-85 re perimeter microwave detection sys w/generic mfg defect initially reported on 831223 Condition determined not reportable per 10CFR50 55(e) VAN BRUNT, E Arizona Public Service Co 84/01/23 BISHOP, TW Division of Resident, Reactor Project & Engineering Programs 2pp 22198 280 24% Fiche 50-528,84/01/23,8402130285
- 8402130291 Final Deficiency Rept DER 83-67 re ex-core detector enclosures below design basis flood level Initially reported on 830928 Startup & control enclosures will be relocated above design basis flood level
 VAN BRUNT: E Ariona Public Service Co 84/01/23 BISHOP, T W DIVISION of Resident Reactor Project & Engineering Programs 3pp 22204 009 24% Fiche 50-528.84/01/23,8402130271
- 84021303B2 Final Deficiency Rept DER 83-65 re primary safety relief valves supplied by C-E discovered in poor condition whils preparing for cold-hydro Initially reported on 83122B Valves will be reconditioned Valves will be reconditioned VAN BRUNTLE E Afrona Public Bervice Co 64/01/23 BISHOP,T W Division of Resident Reactor Project & Engineering Programs 4pp 22203 277 24% Fiche 50-529,84/01/23,8402130382
- 8402130411 Interim Deficiency Rept DER 83-75 re improperly torqued bolts securing two panel filler assemblies supplied by Forboru. Initially reported on 831102 Final rept expected by 840229 VAN BRUNTLE E Arizona Public Bervice Co 84/01/23 BIBHOP, T W Division of Resident. Reactor Project & Engineering Programs 2pp 22203 269 24X Fiche 50-528.84/01/23.8402130411
- B402130406 Final Deficiency Rept DER 82-61 re C-E reactor coolant pump diffuser ring cap screw failure & damage to pump Initially reported on 821021 Listed mods implemented Condition datermined not reportable per 100FR90 55(e)

 VAN BRUNTLE E Arizona Public Service Co 84/01/25 BISHOP, T W Division of Resident Reactor Project & Engineering Programs 6pp 22203.304 24X Fiche 50-528,84/01/25,8402130404
- 8402130415 Interim Deficiency Rept DER 83-64 re failure of Target Rock pressure reliaf valves to meet prerequisite tests Initially reported on 830928 Due to extensive investigation & evaluation, final rept expected by 840305 VAN BRUNTLE E Arizona Public Service Co 84/01/26 BISHOP, T W Division of Resident Reactor Project & Engineering Programs 2pp 22202:078 24X Fiche 50-528,84/01/26,8402130415
- 8402130458 Final Deficiency Rept DER 83-86 re failure of C-E seismic analysis of shutdown HX to adequately address baseplate thickness Initially reported on 831223 One-inch plates will be added to base plates Also reportable under Part 21 VAN BRUNT, E.E. Arizona Public Service Co. 84/01/26 BISHOP, T. W Division of Resident Reactor Project & Engineering Programs 3pp 22202 115. 24X Fiche 50-528.84/01/26.8402130458
- 8402130394 Final Deficiency Rept DER 83-30 re failure of A Marathon ABTM A354 bolt during feedwater pump bolt torquing Initially reported on 830305 Torsion coefficient changed Condition determined not reportable per 100FR30 35(s)

 VAN BRUNTLE.E Arisona Public Service Co 84/01/30 BISHOP.T.W Division of Resident Reactor Project & Engineering Programs App 22203:247. 24X Fiche 50-529,84/01/30,8402130394
- 8402130024 Interim Deficiency Rept DER 83-79 re ac interference spikes on 125-yolt dc bus (diesel generator) exceeding spec Initially reported on 831118 Due to extensive investigation & avaluation.final rept will not be submitted until 840320 VAN BRUNT.E.E Arizona Public Service Co 84/01/30 818HOP.T W Division of Resident, Reactor Project & Engineering Programs. 2pp 22247:247 24X Fiche 50-528,84/01/30,8402150024.
- 8402150209 Final Deficiency Rept DER 82-75 re ITT Grinnell pipe support clamps in main steam supply sys having excess gap & not properly securing scope Initially reported on 831223 Replacement clamps installed Also reported per Part 21. VAN BRUNTLE E. Arizona Public Service Co. 84/01/31 818H0P.T W. Division of Resident Reactor Project & Engineering Programs 4pp. 22241:001. 24X Fiche 30-529.84/01/31.8402150209
- 8402130374 Interim Deficiency Rept DER 83-77 re concrete pour containing honey-combed concrete around vertical tendon sheath block outs. Initially reported on 831107 Final rept expected by 840518.

 VAN BRUNT. E E Arizona Public Bervice Co 84/02/01. BISHOP, T M. Division of Resident, Reactor Project & Engineering Programs 2pp 22242: 136 24X Fiche 50-529, 84/02/01. B402150374

- 8402290102 Interim Deficiency Rept DER 82-46 re ITT-Barton pressure transmitters supplied by C-E not meeting overpressure requirements Initially reported on 820824 Due to extensive investigation, info will not be finalized until 840315 VAN BRUNT.E E Arizona Public Service Co 84/02/03 BISHOP, T W Division of Resident. Reactor Project & Engineering Programs 2pp 22428 003 24X Fiche 50-528,84/02/03.8402290102
- B402290207 Interim Deficiency Rept DER 83-80 re defect in Anchor/Darling main feedwater isolation valves Initially reported on 831122 Final rept delayed due to extensive investigation & evaluation & will be submitted by 840309 VAN BRUNT. E E Arizona Public Service Co 84/02/06 DISHOP, T W Division of Resident Reactor Project & Engineering Programs 2pp 22425 115 24X Fiche 50-528.84/02/06.8402290207
- 8402290263 Interim Deficiency Rept DER 83-78 re lack of documentation in user test & controlling procedure for rock bolt expansion anchors Initially reported on 831209 Next rept delayed until 840516

 VAN BRUNT, E E Arizona Public Service Co 84/02/06 DISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 22427 214 24% Fiche 50-528, 84/02/06, 8402290263
- 8402280452 Final Deficiency Rept DER 83-68 re battery racks constructed w/nuts & bolts not meeting Tech Specs Initially reported on 830928 Noncomforming hardware replaced on battery racks & NCR 8E-2783 dispositioned as rewurk
 VAN BRUNTLE E Arizona Public Service Co 84/02/07 BISHOP, J W Division of Resident Reactor Project & Engineering Programs App 22405 286 24X Fiche 50-528,84/02/09,8402280452
- 8402280456 Interim Deficiency Rept DER 83-56 re discrepancies w/MSIVs supplied by Anchor-Danling Initially reported on 830808 Next rept anticipated by 840316 VAN BRUNT.E E Arizona Public Service Co 84/02/14 BISHOP, T W Division of Resident, Reactor Preject & Engineering Programs 19 22407 058 24X Fiche 50-528.84/02/14.8402280456
- 8402280324 Interim Deficiency Rept DER 82-76 re Target Rock valves not meeting spec/test requirements Initially reported on 821124
 Next rept will be soumitted by 840413
 VAN BRUNT, E E Arizona Public Service Co 84/02/15 BISHOP, T W
 Division of Resident, Reactor Project & Engineering Programs 2pp
 22397 125 24X Fiche 50-528, 84/02/15.8402280324
- 8402280360 Interim Deficiency Rept 84-02 re excessive rust, scale & pitting in clevis & arm of several SI & CH valves Initially reported on 840123 Evaluation in progress Next rept will be submitted by 840327

 VAN BRUNT, E E Arizona Public Service Co 84/02/15 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 3pp 22404 226 24% Fiche 50-528, 84/02/15,8402280360
- B401190064 Board Notification B4-030 forwards NRC B40202 memo re Finding that potential single failures exist in C-E auxillary pressurizer spray sys Requests initiated to C-E applicants addressing NRC concerns EIBENHUT, D 0 Division of Licensing B4/02/16 PALLADING, GILINBRY, ROBERTS Commissioners 1p 22352 252 24X Fiche. 50-000, 84/02/16, 8401190064
- ---B402230244 Requests that licensing boards associated w/FWRs designed by C-E be notified of concerns re reliance on auxiliary pressurizer spray sys which may have single failure vulnerabilities MATTBON.R J Division of Bystems Integration (post 811005) 84/02/02 EISEMHUT, D 0 Division of Licensing 3pp 22352.353 24X Fiche 50-000.84/02/16.8401190064
- T Hearing transcripts on non-antitrust matters
- B402130007 Responds to appeal re denial of FOIA request for documents concerning investigation of allegations at facility Forwards App A documents Documents completely & partially withheld (ref FOIA Exemptions 7 & 4)
 CHILK.S J Office of the Secretary of the Commission 83/11/10 BERNABELL Government Accountability Project 44pp 22238 100 24X Fiche 50-528.83/11/10.8402130007
- --8402130270 Transcript of closed Commission 830315 meeting in Washington, DC re discussion/possible vote on contested issues in full power proceeding Pp 1-57 Partions deleted * Commissioners 83/03/13 32pp 22240 331 24X Fiche 50-527, 83/11/10, 8402130007

- DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3

 A Application/construction stage documents & correspondence
- 8402130005 Appeals denial of FOIA request for documents re R Gunderson & senior Bechtel manager allegations of electrical problems & deficiencies at facilities
 YDUNG, N C Government Accountability Project 83/05/13 NRC No
 Detailed Affiliation Given 2pp 22238 093 24X
 Fiche 50-529,83/05/13,8402130005
- B402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A, B & C documents
 FELTON, J M Division of Rules and Records B3/10/3;
 ROBENBAUM, D M Technical Analysis Corp 19pp 22193 292 24X
 Fishe 50-000.083/10/31.8402090003
- --B204070041 Trip rept of B20316-19 visit of caseload forecast panel to facility re determination of fuel load dates Load dates estimated to be Nov 1983, Nov 1984 & Nov 1985 for Units 1, 2 & 3. respectively MIRAGLIA.F J Operating Reactors Branch 3 82/03/30 EISENHUT, D 0 Division of Licensing 4pp 22194 055 24X Fiche 50-000,83/10/31,8402090003
- --8402070070 Trip rept of B30622-24 Caseload Forecast Panel site visit replant status review Projected fuel load date comparisons listed MNIGHTON, PW Licensing Branch 3 83/10/31 NOWAK, TM Assistant Director for Licensing 2pp 22194 059 24X Fiche 50-000.83/10/31.8402090003
- --8402090076 Summary of 830622-24 Caseload Forecast Panel site visit re plant status review LICITRA:E A Licensing Branch 3 83/07/27 ticensing Branch 3 7pp 22194 Odi 24% Fiche 50-000.83/10/31.8402090003
- -9402070082 Mandwritten notes & calculations re const activities & fuel load preparation * NRC - No Detailed Affiliation Given 77/04/25 2pp 22194 031 24X Fiche 50-000.83/10/31.8402090003
- --8402070087 Handwritten graphs re const activities Related info encl * NRC - No Detailed Affiliation Given 83/06/28 4pp 22176 035 24X Fiche 50-000.83/10/31.8402070003
- 8402i30007 Responds to appeal re denial of FOIA request for documents concerning investigation of allegations at Facility Forwards App A documents Documents completely & partially withheld (ref FOIA Exemptions 7 & 4)
 CHILK, 9 J Office of the Secretary of the Commission 83/11/10
 BERNABELL Covernment Accountability Project 44pp 22238 100
 24x Fiche 50-529,83/11/10.8402130007
- --8304040543 Forwards list of items currently under insp/investigation which have recently been closed out in response to 630318 memo No allegations should impact plant safety or current schedule for initial fuel loading DIRCKB.W J Defice of the Executive Director for Operations 83703729 CHILK, S J Defice of the Secretary of the Commission 3pp 22240 125 24X Fichs 50-529.83/11/10,8402130007
- ~-8402130010 Discusses 620525 Bechtel alleger telcon re allegations concerning defective electrical & const items at facilities specific defects listed Related info encl ACKLETON.O.C. Region 5, Office of Director 83/09/18 ERNBERG.D.M. Region 5, Office of Director 7pp 22238 144 X Fiche 50-529,83/11/10,8402130007
 - LIBOOIR Lists three allegations of immediate concern, currently being vestigated under Cases 5-82-006.007 & 011 Related info cl
 4CMLETON.O C Region 5, Diffice of Director 83/03/29
 4EYLL 3 Office of the Executive Legal Director 18pp
 238 151 24% Fishe 50-329.83/11/10.8402130007

 - *02130016 Submits info re 820526 allegations concerning electrical onst deficiencies
 ACKLETON, O C NRC No Detailed Affiliation Given 82/05/27
 HGP, T W NRC No Detailed Affiliation Given 3pp 22238 170
 IX Fiche 50-529,83/11/10,8402130007

- --B402130017 Handwritten notes re death threats against alleger concerning const deficiencies Related info encl
 SHACKLETON, O. C. NRC No Detailed Affiliation Given 82/05/24
 2pp 2223B 187 24% Fiche 30-527,83/11/10,8402130007
- --8402130030 Forwards recipient signed, sworn statement re 820402 allegations Results will be provided following investigation completion Related info encl

 BHACKLETON. 0 C NRC No Detailed Affiliation Given 82/04/09 GUNDERSON. R D Affiliation Not Assigned 1p 22238 241 24X Fiche 50-529, 83/11/10, 8402130007
- --8402130044 Discusses 820325 telcon from anonymous caller alleging defective HPSI & LPSI sys at plant TEDFORD.C F Arizona, State of 82/03/26 VORDERBRUEGGEN Region 5. Office of Director 1p 22238 242 24X Fiche 50-529,83/11/10.8402130007
- --8402130047 Discusses allegations re electrical const deficiencies at facilities Case under investigation SHACKLETON.O C Region 5, Office of Director 82/07/22 NAC-NA Detailed Affiliation Given 2pp 22238 246 24X Fiche 50-529,83/11/10,8402130007
- --B402130053 "Investigations Status Rept " Related info encl * Office of Investigation B2/10/19 32pp 22238 254 24X Fichs 50-529, 83/11/10, 8402130007
- --B402130122 Informs of L Bernabel intention to make contention over RD Gunderson affidavit re allegations concerning facility const deficiencies Insp & investigations should be completed immediately SHACKLETON D C Region 5, Office of Director 83/03/29 BTERNRERS, D M Region 5, Office of Director 1p 22238 305 24K Fichs 50-529, 83/11/10,8402130007
- --8402130127 Informs that RD Gunderson allegations that have not been investigated/inspected not presently within Ofc of Investigations purview Region V insp requested SHACKLETON, O. C. Region 5, Office of Director 83/03/30 STERNBERG, D. M. Region 5, Office of Director 2pp 22238 306 24X Fiche 50-527,83/11/10.8402130007
- --B402130134 Informs that WR Royce allegation does not come under Off of Investigations jurisdiction Allegations submitted to Region V for followup Related info encl
 SHACKLETON, D.C. Region 5, Office of Director 83/03/30,
 STERNBERG, D.M. Region 5, Office of Director 242pp 22238 308
 24X Fiche 50-529,83/11/10,8402130007
- --8402130143 Rev O to Procedure 90GA-0ZZ11, "Temporary Mode" Related info encl GARDNER,B J Ariiona Public Service Co 82/05/10 43pp 82239 190 24X Fiche 50-529,83/11/10,8402130007
- --8402130174 "Const Insp Planning for Concrete Replacement " Related info enc! * Buchtel Corp JOB 10407 79/12/04, lipp 22240.089 24X Fiche 50-529, 83/11/10, 8402130007
- --8402130182 Provides Ofc of Policy Evaluation immediate effectiveness analysis of Pala Verde licensing board decision for Unit 1 Related info encl
 ZERBE, JE Office of Policy Evaluations SECY-83-065. 83/02/15
 25pp 22240 100 24X Fiche 50-527,83/11/10,8402130007.
- ---8402130219 Mandwritten notes re allegations concerning facility defects Related info encl * Region 3, Office of Director 82/05/25 15pp 22240 141 24X Fiche 50-529, 83/11/10, 8402130007
- ---B402130221 Discusses allegations from anonymous allegar from Bechtel to electrical Installations Related info encl SHACKLETON.O C. Region 5. Office of Director 82/07/22 Region 5. Office of Director 46pp 22240 156 24X Fiche 50-529,83/11/10,8402130007
- ---8402130250 Summary of investigation re PL Hourihan allegations concerning electrical work Handwritten Related info encl SHACKLETON.D C. Region 5. Office of Director 82/05/24 37pp 22240 252 24X Fiche 50-529.83/ii/to.8402130007
- --8402130262 Discusses enonymous allegations from Bechtel employee re electrical installations SHACKLETON, D.C. Office of Investigation 82/07/22 Office of Investigation 3pp 22240 328 24X Fiche 50-529, 83/11/10, 8402130007

- 8402160003 Third partial response to FOIA request for info re votes to attendance at Commission meetings for Jul 1981 Jul 1983 CHILK. S. J. Office of the Secretary of the Commission 83/12/14 Public Document Branch 19 22281 023 24X Fiche 50-000, 83/12/14 24X Fiche 50-000, 83/12/14
- ~-8402160394 Discusses SECY-83-125 re immediate effectiveness decision *
 review of ALAB-713
 CHILK,S J Office of the Secretary of the Commission 83/05/19
 PLAINE,H H Office of the General Counsel 1p 22281 286 24X
 Fiche 50-000,83/12/14,8402160003
- 8402270072 Final response to FOIA request for Commissioner voting & attendance records from 810401 to present Forwards documents listed on App A Documents also available in PDR FELTON. J M Division of Rules and Records 83/12/22 KAMENAR, P D Washington Legal Foundation 3pp 22410 109 24X Fiche 50-529,83/12/22,8402270072
- --8304040550 Advance copy of staff requirements memo re 830315 discussion & possible vote in Washington.DC on contested issues in full power proceeding CHILK.B J Office of the Secretary of the Commission B3/03/18 DIRCKS.W J Office of the Executive Director for Operations 1p 46730 028 24% Fiche 50-529,83/12/22.8402270072
- B402070431 Requests add1 info re proposed method for estimating gaseous effluent flow rates in lieu of direct measurements, demonstrating conservatism of flow rate values under all conditions conditions
 KNIGHTUN.0 W Liconsing Branch 3 84/01/16 VAN BRUNT, E E
 Arizona Public Service Co 2pp 22142 095 24X
 Fiche 50-528.84/01/16.8402070431
- B401270152 Forwards nonproprietary "Safety Injection Novile Thermal Liner" & "Resistance Tump Detector Thermowell." for dacketing & distribution VAN BRUNT.E E Arizona Public Service Co B4/01/24 KNIOHIDN.G VAN BRUNTLE E Arizona Public Service Co 84/01/24 KNIGHTON, G W Licensing Branch 3 lp 22038 001 24% Fiche 50-528, 84/01/24. 8401270152
- 8402060240 Forwards nonproprietary "Interim Rept on Performance Evaluation of Palo Verde Control Element Assembly Shroud " VAN BRUNT, E.E. Arizona Public Service Co. 84/01/31 KNIGHTON, Licensing Branch 3 1p 22084 213 24X Fiche 50-528,84/01/31, 8402060240 עאונמוµדרוא. מ
- --8402060247 Nonproprietary "Interim Rept on Performance Evaluation of Palo Verde Control Element Assembly Shroud " * Combustion Engineering, Inc CEN-267(V)-NP 84/01/31 8ipp 22084 214 24X Fiche 30-328.84/01/31.8402060240
- B402010410 Quneric Ltr 84-04 to all operating PWR licensees.CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Svc list encl EISENHUT.D 9 Division of Licensing 84/02/01 Consolidated Edison Co. of New York, Inc 59pp 22177 087 24X Fiche 50-000.84/02/01.8402010410
- B402160470 Forwards request for add1 info based on review of June 1983 data base values for facility core protection calculators & control element assembly info should be provided within
- Z Mrs. KNIGHTON,G W Licensing Branch 3 84/02/06 VA Aritona Public Service Co 3pp 22302 160 24X Fichs 50-528,84/02/06,8402160470 VAN BRUNTAE E
- B402230341 Provides partial info re German reactor coolant pump (RCP) design German design similar to RCP seal used in C-E K8B pump at Palo Verde
 JACKBON, J E Equipment Gualification Branch 84/02/07, NOONAN, V S 84/02/07, NOONAN, V S
 - pump at Faib verge JACKBON, J E Equipment Gualification Branch 84, Equipment Gualification Branch 2pp. 22377 052 Fithe 50-528,84/02/07.8402230341
- 8401190059 Board Notification 84-032 provides addl info on environ qualification Submittal augments info in Board Notifications
 B4-004 & 84-007
 EIBENHUT.D G Division of Licensing B4/02/13 Atomic Bafety and
 Licensing Board Panel 10pp 22314 204 24% Fiche 50-000,84/02/13,
 B401190059
- 8402170241 Notifies that util response to NRC 840110 request for schedule re differences between facility control room design review & NRC detailed control room design review program will be provided by 840330 VAN BRUNTLE E Arizona Public Service Co 84/02/13 KNIGHTON, Licensing Branch 3 ip 22296 149 24X Fiche 50-528,84/02/13,8402170241

- 8402170257 Trip rept of 931108 & 09 visits to Saint-Laurent-Des-Faur plant & KSB Labs. Franienthal. West Germany. respectively, replant organization & leactor coolant pump design KSB Labs provided reactor coolant pumps for Palo Verde NOVAK, T M. Assistant Director for Liconsing 84/02/13 EISENNUT.D G. Division of Licensing 4pp 22313 235 24X Fiche 50-528.84/02/13.8402170257
- 8402160049 Forwards add1 info re impact of high energy line breaks on control sys.per 831205 & 13 telcon concerns re Guestion PAR US TO SERVICE CO. B4/02/14 KNIGHION, G. W. Licensing Branch J. Spp. 22279 264 24X Fiche 50-528, 84/02/14, 8402160069
- 8401190068 Board Notification 84-033 provides "Sys Interaction Program." task action plan, for Unresolved Safety Issue A-17 Distribution list encl EISENHUT.DG Division of Licensing 84/02/16 PALLADINO Commissioners 8pp 22482 091 24X Fiche 50-000,84/02/16,8401190068
- 8402270635 Notification of 840302 meeting w/C-E in Windsor.CT to perform audit of results of Phase I & II testing Agenda encl
 LICITRA.E A Licensing Branch 3 84/02/16 KNIGHTON, 0 W Licensing Branch 3 4pp 22414 022 24X Fiche 50-528.84/02/16. B402270635
- 8402270340 Forwards response to NRC 831220 request for add1 info re TMI Item II F 2, "Instrumentation for Detection of Inadequate Core Cooling"

 VAN BRUNT, E E Artiona Public Service Co 84/02/23 KNIGHTON, G Licensing Branch 3 17pp 22389 288 247 Fiche 50-528,84/02/23.8402270340
- 8402290034 Forwards clarifications & justifications made to certain rays included in Amend 12 to FSAR
 VAN BRUNT, E E Arizona Public Service Co 84/02/24 KNIGHTDN, G Licensing Branch 3 4pp 22426 182 24X Fiche 50-528, 84/02/24, 8402290034
- 840229006B Forwards preliminary description for RCS demonstration test Specific aspects will be discussed at 840320 meeting VAN BRUNT.E E Arizona Public Service Co 84/02/24 KNIGHTGH.O Licensing Branch 3 10pp 22421 009 24X Fiche 50-528,84/02/24, 840229006B
- 8402270177 Forwards proposed changes to Section 1 8 of FSAR re Reg Ouides 1 28 & 1 33 covering preoperational & stantup testing Changes will be incorporated into future FSAR amend VAN BRUNT, E E Arizona Public Servica Co 84/02/24 KNIGHTUN. O Licensing Branch 3 8pp 22426 289 24X Fiche 50-528, 84/02/24, 8402270177
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8402080217 Forwards list of onaite emergency organization personnel as of 840101.per SSER 4 (NUREQ-OBS7)

 VAN BRUNT.C E Arizona Public Service Co 84/01/27 KN10HT0N.O Licensing Branch 3 Bpp 22130 104 24X Fiche 50-528.84/01/27, 8402080217
- B4020B0332 Advises that design of atmospheric dump valve accumulators resvaluated per NUREG-0857 BER, Section 5 4 3 Design meets requirements Info will be reflected in upcoming amend to FBAR FEAR VAN BRUNT,E E Arizona Public Service Co 84/01/27 KNIOHTON, O Licensing Branch 3 5pp 22131 216 24% Fiche 50-528,84/01/27, 8402080332
- 8402130175 Forwards addl info on potential finding Repts 027,050 & 065, per SSER 5 (NUREG-0897).Section 17 7 3 re independent QA VAN JRUNT, E E Arizona Public Bervice Co 84/02/06 KNIGHTON, G Licensing Branch J 5pp 22204 134 24X Fiche 50-528, 84/02/06, 8402130175
- 8402270493 Forwards revised pages to pump & valve testing program: categorizing pressure isolation valves as ac according to ABME Section XI,per SER (NUREO-0837)

 VAN BRUNTLE E Arizona Public Service Co 84/02/17 KNIGHTON, G
 Licensing Branch 3 opp 22389 238 24X Fiche 50-528, 84/02/17, 8402270495

F Security, medical, emergency & fire protection plans

- 8402160305 Revised emergency plan implementing procedures, including Procedures EPIP-01 re emergency organization. EPIP-03 re notification of unusual implementing actions & EPIP-04 re alert implementing actions M/840210 ltr BROWN, B.A. CLYDE, M.R. VAN BRUNT, E.E. Arizona Public Service Co. 84/01/20 KNJCHTON, O. Licensing Branch 3 126pp 22272 238 24 Fiche 90-528.84/01/20,8402160305
- 8402080217 Forwards list of unsite emergency organization personnel as of 840101,per 95ER 4 (NUREG-0857)
 VAN BRUNT, E.F. Artiona Public Service Co. 84/01/27 KNIGHTON, 0
 Licensing Branch 3 Spp. 22130 104 247 Fiche 50-528, 84/01/27, 8402080217
- 8402160653 Responds to 830616 request to establish backup emergency operations facility in Palo Verde Inn approx 8 miles from plant Location acceptable EISENHUT.D 0 Division of Licensing 84/01/31 VAN BRUNT.E E Arizona Public Service Co 2pp 22292 357 24X Fiche 50-528.84/01/31.8402160553
- B402150271 Advises that review of util maint program for valves & hydrants disclosed that sys surveillances still undeveloped & no preventive maint conducted Problem w/fire loops identified by Beckhel re amount of valve seat leakage VAN BRUNT, E E Arizona Public Service Co E4/02/09 MARTIN, J B Region 5. Office of Director 2pp 22250 276 24X Fiche 50-528,84/02/08.8402150071
- 8402220386 Submits supplemental response to 830728 ltr re independent source range neutron flux monitor at remote shutdown panel Dasign features & procedural guidance in eristing design satisfy 10CFR50, App A. Criterion 3, based on listed features VAN BRUNT. E E Arisona Public Service Co 84/02/14 KNIGHTON, Q Licensing Branch 3 3pp 22335 287 24X Fiche 50-528, 84/02/14, 8402220386
- 8402270352 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee per 8:0707 Generic Ltr 81-27 W/o request entire plan will be placed in PDR KNIGHTON O W Licensing Branch 3 84/02/14 VAN BRUNT, E E Aptiona Public Service Co 3pp 22438 259 24X Fiche 50-528,84/02/14,8402290352

G Adjudicatory correspondence

- 8402130007 Responds to appeal re denial of FDIA request for documents concerning investigation of allegations at facility Forwards App A decuments Documents completely & partially withheld (ref FDIA Exemptions 7 & 4) CHILK. 8 J Office of the Secretary of the Commission 83/11/10 BERNABELL Covernment Accountability Project 44pp 22238 100 24X Fiche 50-529,83/11/10,8402130007
- --8402130024 Affidavit of RD Gunderson re allegations concerning electrical const deficiencies Related info encl GUNDERSON.R D Bechtel Corp 83/11/10 5ipp 22238 190 24X Fiche 50-529,83/11/10,8402130007
- --8402130108 Forwards R Gunderson & W Royce affidavits & supporting exhibits re allegations concerning conet deficiencies at facilities Problems evidenced not adequately addressed GARDE.8 P Government Accountability Project 83/02/28 FORTUNA.R Office of Investigation 2pp \$2238 301 24x Fiche 50-529,83/11/10.8402130007
- 8402010141 Ack receipt of Davis comments re modeling contentions DEWEY.L 5 Hearing Branch 3 84/01/27 BERLIN.K Winston & Btrawn, Ip 22038 215 24X Fiche 50-529,84/01/27,8402010141
- 8402140116 Responds to West Valley 831116 outline of intent to withdraw source term & modeling contentions NRC supports request for withdrawal DEMEY.L 8 Hearing Branch 3. COLE,R F Record Services Branch (Document Control Desk) HOURIHAN.L Atomic Safety and Licensing Appeal Panel 84/02/08 BERLIN.K Winston & Strawn PLATT.W Snell & Wilher 30pp 22228 159 24X Fiche 50-529,84/02/08.8400140116
- 402220241 Forwards 840206 daily highlight rept re low pressure safety injection pumps, per staff agreement REISLE J Hearing Branch 3 84702/15 DERNABELL Government Accountability Project 2pp 22339 197 24X Fiche 50-529,84/02/15,4022/2024

H General correspondence

- 8402040078 Informs of recent rev in util organizational structure \$ 150 replaced J Reedel as manager of corporate QA/QC MODDS, T O Arizona Public Service Co 84/01/31 KN19HTON. 0 Licensing Branch 3 ip 22088 239 24% Ficha 50~528, 84/01/31, 8402040078
- B40213003B Informs that D Karner appointed assistant vice-president fit, nuclear operations Karner will rept to EE Van Brunt & will provide addl mgt support during transition from const to operation VAN BRUNT.E E Arizona Public Service Co B4/02/06 KNIGHTON.9 Licensing Branch 3 1p 22204 085 24X Fichs 50-528,84/02/06,8402130038

K Utility Final Safety Analysis Report (FSAR) & amends

- 8402230119 Amend 12 to FSAR W/840221 ltr VAN BRUNT.E E Arizona Public Service Co 84/02/29 1241pp 22367 322 24% Fiche 50-528.84/02/29.8402230119
- Q Inspection reports. IE Bulletins & correspondence
- B40R270555 FOIA request for all agency records & info re NRC const assessment team insp conducted from 830906-30 at facilities BERNABEL.L. Government Accountability Project B3/10/07 Office of Administration 2pp 22414 144 24X Fiche 50-528, 83/10/07.
- 8402270550 Appeals denial of FOIA request for documents re NRC conit assessment team insp conducted from \$30906-30 at facilities BERNABEI, L. Government Accountability Project 82/12/05 Office of Administration 19 22414 143 24X Fiche 50-528,83/12/05,8402270.550
- 8402270544 Responds to appeal re denial of fOIA request for documents re NRC const assessment team insp conducted from 830904-30 at facilities Rept provided on 83120; FELTON, J M Division of Rules and Records 84/01/12 BERNABELL Government Accountability Project ip 22414 142 24% Fiche 50-528.84/01/12.8402270544.
- B312120153 IE Info Notice 84-05, "Steam Binding of Auxiliary Feeduate Pumps " Svc list encl JURDAN, E. L Division of Emergency Preparedness & Engineering Response (Fost 830103) 64/01/25 Consolidated Edison Co of No. York, Inc. 120pp 22058 001 24X Fiche 50-000.84/01/25, 8312120131
- 8401190016 IE Info Notice 84-07. "Design-Basis Threat & Review of Vehicular Excess Controls" Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of Nie York, Inc. 119pp 22114 179 24X Fiche 50-000,84/02/03.8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in DWR Mark I Containment Vent Headers " Svc list encl. DEYDUNG.R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, let 102pp 22177, 156 24X Fiche 50-000, 84/02/03, 8401190017
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50, App R) " Syr list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of Re, York, Inc. 124pp 22365 259 24X Fiche 50-000.84/02/13.8491190041
- 8401190039 IE Info Notice 84-08, "IOCFR30 7, 'Employee Protection '"
 Svc list encl.
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of Nov York, Inc. 1158
- 8401190045 IE Info Notice 83-63. Suppl 1, "Potential Failures of Westinghouse Type 8A-1 Differential Relays" Svc list encl JORDAN, E. L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc. 1189p 22366 142 24X Fiche 50~000,84/02/15,8401190055
- 8401170052 IE Info Notice 84-10, "Motor-Operated Valve Torque Switchid Bet Below Manufacturer Recommended Value " Bvc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co of Meu York, Int 1169p 22366 024 24X Fiche 50-000.84/02/21.8401190062

- 8401170086 IE Info Notice 84-11. "Training Program Deficiencies "
- Svc list encl
 JORDAN-E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/02/24 Consolidated Edison Co of New
 Yari, Inc 113pp 22430 304 24X Fiche 50-000, 84/02/24, 8401190066
- 8401190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
- NOII90067 IE INFO NOVICE C. Eve list encl JORDAN E. L Division of Emergency Preparadness & Engineering Response (Post B30103) B4/02/27 Consolidated Edison Co of New York, Inc 120pp 28431 060 24X Fiche 50-000.B4/02/27.B401190067
- 8 Reportable occurrences, LERs & related correspondence
- 8402170146 Part 21 rept re wearing ring failure on auxiliary feed water pump Pumps w/potential for wearing ring problems being evaluated Existing users should review application for possible replacement of rings PATTY.D F Bingham-Willamette Co 83/11/08 Region 4, Dffice Director 19 22299'022 24X Fiche 50-528,83/11/08,8402170146 Office of
- 8402080029 Responds to FOIA request for documents re facility hot functional testing problems, including broken thermowells, loose & broken reactor coolent pump parts & loose thermal sleeves Forwards App A documents Documents also in FDR FELTON, J. M Division of Rules and Records 83/1/1/16 GARDE, B Gavernment Accountability Project 3pp 22170 253 24X Fiche 50-000.83/11/16,8402080029
- --8310200052 Provides update on status of efforts for resolving anomalies found during hot functional testing involving RGS pumps, thermal slesves, thermowells, C-E shroud assemblies & metal filings on upper support structure
 LICITRALE A Licensing Branch 3 83/10/11 NOVAK, T M Assistant Director for Licensing. 2pp 22171 119 24X
 Fiche, 50-000, 83/11/16, 8402080027
- --8402080036 List of hot functional testing exceptions Related info encl * Affiliation Not Assigned 83/11/16 19pp 22170 236 24X * Affiliation Not Assigned 83 Fiche 50-000,83/11/16,8402080029
- 8402140378 Requests addl info re Part 21 rept dtd 831108 concerning wear ring failure in auxiliary feedwater pump furnished to facilities. Info requested within 25 days POTAPOVS, U. Region 4, Office of Director 83/11/30 PATTY, D.F. Bingham-WIllemette Co. ip 22221 230 24X Fiche 50-000, 83/11/30, 8402140378
- ---8402140422 Supplemental Part 21 rept re wear ring failure in auxiliary feedwater pumps.per 831130 request for add1 info. Wear rings will be replaced on returned units w/AISI 420 wrought matl List of pumps in similar svc w/same wear ring encl PATTY.D. F Bingham-Hillamette Co 83/12/20 Region 4. Office of Director. 2pp 22221 251 24X Fiche. 50-000.83/11/30.8402140378.
- 8402070077 Further response to FOIA request for records re problems encountered by util during hot functional testing Forwards App A documents. Documents also available in FDR Bearch for addit documents continuing.

 FELTON. J M Division of Rules and Records 83/12/22 GARDE, B GOVERNMENT COUNTED HIS Project 2pp. 22187 084. 24X

 Fiche 50-528,83/12/22,8402070077
- -8402090116 Draft trip rept of 831114-16 site visit to C-E. in Newington, NH. to review mfg of C-E-JBB reactor coolant pump & current testing of modified pump as applied to facilities Related info encl JACKBON, J E. Equipment Qualification Branch 83/12/22. NOONAN, J E. Equipment Qualification Branch 11pp. 22187-088, 24X Fiche: 50-528, 83/12/22, 8402090097.
- 8402030302 Interim Deficiency Rept DER 82-76 re Target Rock valves failing to mest spec/test requirements, Initially reported on 821124. Final rept will be delayed until 840223 due to extensive investigation & evaluation.

 VAN SRUNTLE E. Arizona Public Service Co 84/01/12 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp. 220691077. 24X Fiche 50-528,84/01/12,8402030302
- 8402030365 Interim Deficiency Rept DER 83-10 re main steam reliaf valve tests exceeding 5% blowdown limit. Initially reported on 830228. Final rept will be delayed until 840301 due to extensive investigation & evaluation.

 VAN BRUNT.E.E. Arizona Public Bervice Co. 84/01/12 BISHOP,T W. Division of Resident. Reactor Project & Engineering Programs. 2pp 22066.075. 24% Fiche: 50-528.84/01/12.8402030365

- 8402030423 Interim Deficiency Rept DER 83-70 re wiring in ERF cabinets not in conformance w/IEEE-384 criteria Initially reported on B31011 Due to extensive evaluation, final rept will not be submitted until 840229 VAN IRUNT.E E Arizona Public Service Co 84/01/13 BIBHOP, T W Division of Resident.Reactor Project & Engineering Programs 2pp 22068 278 24X Fiche 50-528, 84/01/13, 8402030423
- 8402030362 Deficiency Rept DER 82-61 re possible failure of reactor coolant pump diffuser ring-cap screus Initially reported on 821021 Final rept expected by 840222 instead of 840123 due to extensive evaluation required

 VAN BRUNTLE E Arizona Public Service Co 84/01/18 BISHOP.T W Division of Resident.Reactor Project & Engineering Programs Zpp 22046 681 24X Fiche 50-326,84/01/18,8402030362
- B402130285 Deficiency Rept DER 83-85 re perimeter microwave detection sys w/peneric mfg defect Initially reported an 831223 Condition determined not reportable per 10CFR50 55(e) VAN BRUNT, E E Arizona Public Service Co 84/01/23 BISHQP, T W Division of Resident Reactor Project & Engineering Programs 2pp 22198 280 24x Fiche 50-528, 84/01/23, 8402130285
- 8402130291 Final Deficiency Rept DER 83-67 re ex-core detector enclosures below design basis flood level initially reported on 830928 Startup & control enclosures will be relocated above design basis flood level
 VAN BRUNT, E E Arizone Public Service Co 84/01/23 BISHOP, T W Division of Resident Reactor Project & Engineering Programs Opp 22204 009 24X Fiche 50-528,84/01/23,8402130291
- 8402130411 Interim Deficiency Rept DER 83-75 re improperly torqued bolts securing two panel filler assemblies supplied by Foxboro Initially reported on 831102 Final rept expected by 840227
 VAN BRUNT, E E Arizona Public Service Co 84/01/23 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs, 2pp 22203 269 24X Fiche 50-528, 84/01/23, 8402130411
- 8402130406 Final Deficiency Rept DER 82-61 re C-E reactor coolant pump diffuser ring cap screw failure & damage to pump. Initially reported on 821021 Listed mods implemented Condition determined not reportable per 10CFR30 53(s)

 VAN BRUNT, E E Arizona Public Service Co 84/01/29, BISHOP, T W Division of Resident. Reactor Project & Engineering Programs 6pp 22203.304 24% Fichs 50-528,84/01/25,8402130406
- 8402130415 Interim Deficiency Rept DER 83-64 re failure of Target Rock pressure relief valves to meet prerequisite tests Initially reported on 830928 Due to extensive investigation & evaluation, final rept expected by 840305.

 VAN BRUNT, E E Arizona Public Service Co 84/01/26 BISHDP, T. H Division of Resident, Reactor Project & Engineering Programs 2pp 22202.078. 24X Fiche 50-528, 84/01/26, 8402130415
- 8402130458 Final Deficiency Rept DER 83-86 re failure of C-E seismic analysis of shutdown HX to adequately address baseplate thickness Initially reported on 831223. Gne-inch plates will be added to base plates Also reportable under Part 21.

 VAN BRUNT, E E Arizona Public Service Co 84/01/26 BIBHOP, T W Division of Resident, Reactor Project & Engineering Programs Spp 22202 115. 24% Fiche 50-528,84/01/26,8402130458
- B402150024 Interim Deficiency Rept DER 83-79 re ac interference spikes on 125-volt do bus (diesel generator) exceeding spec Initially reported on 83ii18 Due to extensive investigation & evaluation. final rept will not be submitted until 840320 VAN BRUNT, E. E. Arizona Public Service Co. 84/01/30 BIBHOP, T. W. DIVISION OF RESIDENCE PROJECT & Engineering Programs 2pp 22249.247 24X Fiche 50-528,84/01/30,8402150024
- 8402270102 Interim Deficiency Rept DER 82-46 re ITT-Barton pressure transmitters supplied by C-E not meeting overpressure requirements. Initially reported on B20082 Due to systemsive investigation, info will not be finalized until 840315
 VAN BRUNT.E.E. Arizone Public Service Co. 84/02/03 BISHOP,T. W Division of Resident.Reactor Project & Engineering Programs 2pp 22428 003 24X Fiche 50-528,84/02/03,8402270102
- B40R290R07 Interim Deficiency Rept DER 83-80 re defect in Anchor/ Darling main feedwater isolation valves, Initially reported on 83122 Final rept delayed due to extensive investigation & evaluation & will be submitted by 840309 VAN BRUNT, E. E. Arizone Public Service Co. 84/02/06 BISHOP, T. W. Division of Resident, Reactor Project & Engineering Programs Rpp 22425:113. 24% Fiche 50-528, 84/02/06, 8402290207
- 8402290258 Rev 2 to interim Deficiency Rept DER 83-53 re embed plates not meeting WPP/GCI requirements. Initially reported on 830801 Defective embed plates will be corrected. Next rept by 840521 VAN BRUNT E. E. Arizona Public Service Co. 84/02/06 BIBHOP, T.W. Division of Resident Reactor Project & Engineering Programs. 2pp 22427: 222 24X Fiche: 50-530, 84/02/06, 8402270258

- 8402290263 Interim Deficiency Rept DER 83-78 re lack of documentation in user test & controlling procedure for rock bolt expansion anchors Initially reported on 831209 Next rept delayed up to 840516
 - antonry installa, reported to account advanced to the control of t
- 8402150206 PMD-V-84-006 on 840207, electricians found 22 instrumentation cables cut in upper spreading room Litensee posted 24 h guard in vicinity & is contemplating press release BODDS, R . BISHOF. T Region 5. Office of Director 84/02/07 ip 22244 083 24% Fiche 50-530,84/02/07,8402150206
- 8402;401:1 PNS-V-84-002 on 840207, 22 instrumentation cables in upper cable spreading room discovered deliberately cut Util & Bethtel Const Co conducting investigation Findings & further plans will be reviewed on 8402:13-14 BCHAEFER, D.W., NORDERHAUG, L.R. Region 5, Office of Director 84/02/07 ip 222:17 055 24x Fiche 50-530,84/02/09,8402:1401:11
- 8402280452 Final Deficiency Rept DER 83-48 re battery racks constructed w/nuts & boits not meeting Tech Specs Initially reported on 830920 Nonconforming hardware replaced on battery racks & NCR 98-2783 dispositioned as rework VAN BRUNT, E Artiona Public Service Co 84/02/07 BISHUP. J W Division of Resident. Reactor Project & Engineering Programs 4pp 22405 226 24x Fiche 50-528,84/02/09.8402280452
- 8402280456 Interim Deficiency Rept DER 83-56 re discrepancies w/MSIVs supplied by Anchor-Darling Initially reported on 830808 Next rept anticipated by 840316
 VAN BRUNT,E E Arizona Public Service Co 84/02/14 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 1p 22407 058 24x Fiche 50-328,84/02/14,8402280456
- 8402280324 Interim Deficiency Rept DER 82-74 re Target Rock valves not meeting spec/test requirements Initially reported on 821124
 Next rept will be submitted by 840413
 VAN BRUNT, E E Arizona Public Service Co 84/02/15 BISHOP, T W
 Division of Resident, Reactor Project & Engineering Programs 2pp.
 22397 125 24X Fiche 30-328, 84/02/15, 8402280324
- 8402280360 Interim Deficiency Rept 84-02 re excessive rust.scale & pitting in clevis & arm of several SI & CH valves Initially reported on 840123 Evaluation in progress Next rept will be submitted by 840327

 VAN BRUNT.E E Arizona Public Bervice Co 84/02/15 BISHOP.T W Division of Resident.Reactor Project & Engineering Programs 3pp 22404 226 24% Fichs 50-528,84/02/15,8402280360
- 8401190044 Board Notification 84-030 forwards NRC 840202 memo re finding that potential single failures exist in C-E auxiliary pressurizer spray sys Raquests initiated to C-E applicants addressing NRC concerns EISEMHUT, D 0 Division of Licensing 84/02/16 PALLADIND, GILINSKY, ROBERTS Commissioners 1p. 22352 252 24X Fiche 50-000,84/02/16,8401190064
- --B402230244 Requests that licensing boards associated w/PWRs designed by C-E be notified of concerns re reliance on auxiliary pressuriter spray sys which may have single failure vulnerabilities MATTSUN,R J Division of Systems Integration (post B11005) B4/02/02 EISENHUT,D 0 Division of Licensing 3pp 22352 353 24X Fiche 50-000 84/02/16.8401170064

T Hearing transcripts on non-antitrust matters

O2130007 Responds to appeal re denial of FOIA request for documents oncerning investigation of allegations at facility Forwards in Advances Documents Documents completely & partially withheld ref FOIA Exemptions 7 & 4) ILK.8 J. Office of the Secretary of the Commission B3/11/10. RNABELL. Government Accountability Project 44pp 22238 100 IX Fiche 50-530,83/11/10,8402130007

402130270 Transcript of closed Commission 830315 meeting in Washington, DC re discussion/possible vote on contested issues in full gover proceeding Pp 1-57 Portions deleted * Commissioners, 83/03/15 32pp 22240:331, 24% Fiche 50-529,83/11/10,8402130007

DCKET 50-537 CLINCH RIVER BREEDER REACTOR

A Application/construction stage documents & correspondence

*160003 Third partial response to FOIA request for info re votes & tendance at Commission meetings for Jul 1981 - Jul 1983 ILK.8.J Office of the Secretary of the Commission 83/12/14 lic Document Branch, 1p 22281 023 24% Fiche 50-000:83/12/14.2150003.

- --B402160007 Staff requirements memo re 830105 discussion/possible velon order in facility proceeding in Washington DC CHILK, S. J. Office of the Secretary of the Commission B3/01/07 OPfice of the Secretary of the Commission. Ip 22281 049 241 Fichs 50-000,83/12/14,8402160003
- --8402160030 Staff requirements mamo re 830422 discussion & possible with in Washington, DC on immediate effectiveness of LWA-1 CHILK, S. J. Office of the Becretary of the Commission 83/04/26 ZERBELJE Défice of Policy Evaluations 1p 22281 057 24x Fiche 50-000, 83/12/14, 8402140003
- B402290212 Forwards draft site redress plan in response to N Grace B31208 request Plan will be finalized for submission on B40302, following receipt of comments OAVIGAN.F X Energy, Dept of B4/02/27 KING.T Clinch River Breeder Reactor Program Office 1p 22425.077 24X Fichs 50-537,84/02/27,8402290212
- --8402290215 Draft "Bite Redress Plan" * Energy, Dept of 84/02/29 35pp 22425 078 24X Fiche 50-937,84/02/27,8402290212
- E NRC Bafety Evaluation Report (SER), suppls & correspond⊕nce
- 8402290002 Responds to FOIA request for correspondence NRC received from Benators J McClure, JB Johnston & P Laxalt during past 2 yrs Forwards App A documents Name of individual deleted from Documents B & 9 of App A (ref FOIA Exemption 6) FELTON, J M Division of Rules and Records 83/11/30 KOLI, E Cable News Natwork, Inc. 6pp 22438 002 24X Fiche 50-000. 83/11/30.8402290002
- --B402270273 Forwards SBER i.dtd May 1983 W/o encl * Dffice of Nuclear Reactor Regulation, Director 83/03/25 HATFIELD, M O Senate, Appropriations 4pp 22438,096 24X Fichs 50-000,83/11/30.8402290002
- --B402270277 Forwards SSER 2.dtd May 1783 H/o enc1 * Office of Nuclear Reactor Regulation, Director. 83/04/10 HATFIELD.M D Benatw. Appropriations ip 22438 108 24X Fiche 50-000.83/11/30.8402290002

9 Adjudicatory correspondence

- B402070185 Memorandum re corrections & additions to be made to ASLS B40120 memorandum of findings (CP phase) MILLER, M E Atomic Safety and Licensing Board Panel 84/02/03 4pp 22:101 067 24% Fichs 50-537,84/02/03,8402070185
- 8402080149 Brief im support of appeal of ASLB 840120 order re MRDC motion to intervene FINANDRE, B A. Natural Resources Defense Council FINANDRE, B A Hunton & Williams 84/02/06 7pp R2131 304 24X Fiche 50-537.84/02/06.8402080149
- --8402080152 Notice of appeal of ABLB 840120 notice denying NRDC setton to intervene FINAMORE.B. A. Natural Resources Defense Council. FINAMORE.B A. Hunton & Williams FINAMORE.B A. Sierra Club. B4/02/06 2pp 22131 311 24X Fiche 50-537.84/02/06.8402080147
- --B4020B0166 Brief of intervenors in support of appeal of ASLB B40120 order. Certificate of Svc encl FINAMORE, B.A. Natural Resources Defense Council FINAMORE, B.A. Hunton & Milliams FINAMORE, B.A. Sierra Club, B4/02/06. 7pp R2131:313. 24X Ficha 50-537,84/02/06,8402080149.
- 8402070131 Order requiring answers to NRDC appeals re Board decisions denying request for late intervention & authorizing NRDC to participate in 840314 conference-by 840221 SHGEMAKER.C J Atomic Safety and Licensing Appeal Panel. 84/02/07 2pp 22163.243 24X Fiche; 50-537, 84/02/07, 8402070131.
- 8402220084 Answer opposing NRDC & Sierra Club appeals to ASLB decisions. Certificate of Svc encl EDGAR, G L Project Management Corp LUCK, W D Energy, Dept. of. Francesee Valley Authority 84/02/21. Atomic Safety and Licensing Appeal Panel 13pp 22338 326 24X Fiche: 50-537. 84/02/21. 8402220084
- B402270032 Brief in opposition to NRDC appeal from ABLB order of motion to intervene & NRDC & Bierra Club 840206 appeal from ABLB 840120 notice of conference w/parties Certificate of Svc enc!
 TURK, 8, E Hearing Branch i 84/02/21 Atomic Safety and Licensing Appeal Panel 30pp 22388 131, 24X Fiche 50-537, 8402/21, 8402270032.

U Congressional/Executive Correspondence

- B402270002 Responds to FOIA request for correspondence NRC received from Benators J McClure. JB Johnston & P Laralt during past 2 yrs Forwards App A documents Name of individual deleted from Documents B & 9 of App A (ref FOIA Exemption 6) FELTON, J M Division of Rules and Records 83/11/30 KOLL.E Cable News Network, Inc. 6pp 22438 002 24X Fiche 50-000, B3/11/30.8402270002
- --B402270005 Notifies that Commission voted to deny DDE request for exemption from certain NRC regulations in connection w/CRBR site areporation activities

 KAMMERER.C Office of Congressional Affairs B2/03/05

 ALEXANDER.L Tennessee, State of RILEY,E L Affiliation Not Assigned SASSER.J Senate 2pp 22438 010 24X

 Fichs 50-000, 83/11/30. 8402290002
- --8402290024 Forwards NRC 820316 order denying DOE request for regulatory esemption to begin CRBR site preparation activities W/ separate views of Commissioners W/o encl KAMMERER.C Office of Congressional Affairs 82/03/17 OTTINGER.R L House of Rep., Energy & Commerce SASSER.J., GUAYLE.D Senate 2pp 22438 012 24X Fiche 50-000, 83/11/30, 8402290002

DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION: UNIT 1

A Application/construction stage documents & correspondence

- 84D2070003 Responds to FDIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documents
 FELTON, J M Division of Rules and Records 83/10/31
 ROSENBAUM.D M Technical Analysis Corp 19pp 22193 272 24X
 Fiche 50-000.83/10/31.8402070003
- --B402090185 Handwritten notes & calculations re const activities * NRC - No Detailed Affiliation Given 82/10/31 5pp 22195:067 24X Fiche 50-000.83/10/31.8402090003
- --9402070187 Handwritten notes & calculations re const activities & fuel load preparation * NRC - No Detailed Affiliation Given 79/02/27 7pp 22195-074 24X Fichs 50-000,83/10/31.8402090003
- B402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILK: B J Office of the Secretary of the Commission 83/12/14 Public Document Branch ip 22281 023 24X Fiche 50-000:83/12/14. B402160003
- --8402160253 Discusses SECY-81-445 re review of director's denial of 100FR2 206 petition CHILK, B.J. Diffice of the Secretary of the Commission 82/01/07 DIRCKS.W.J. Office of the Executive Director for Operations BICKWIT, L. Office of the General Counsel 1p 22281 146. 24X Ficha 50-000, 83/12/14,8402160003
- 8402010410 Generic Ltr 84-04 to all operating PWR licensess, CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Svc list encl EISENHUT, D G Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc 59pp 22177 087 24X Fichs: 50-000, 84/02/01, 8402010410
- C. Utility Environmental Raport (ER), amends & correspondence
- 8402010369 Approves 831028 request for withholding "Company Program to Calculate Annual Average Doses & Accident X/Qs (Annual IAP-AZAP)." per 10CFR2 790 Info submitted in response to NRC sawiren rept DL Guestion 470 7
 YQUNQBLODD.B J Licensing Branch 1 84/01/26 SHIELDB.B W Public Bervice Co. of Indiana. Inc. 3pp 20059 338 24X
 Fiche. 50-546.84/01/26.8402010369
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8402270187 Responds to 840118 request that NRC issue draft BER as is, so benchmark exists for licensee review process that has occurred Info now available to NRC would not support useful draft SER
 DENTON, HR Office of Nuclear Reactor Regulation, Director 84/02/21. SHIELDS, S W Public Service Co of Indiana, Inc. 3pp 22407:321 24X Fiche 50-546.84/02/21.8402270187

- --8402270193 Notifies of suspension of const Site work force reduced to less than 1.000 Action taken due to inability to finance project NRC should issue draft SER as is, so benchmark exists for licensing review process

 SHIELDS. B W Public Service Co of Indiana, Inc 84/01/18
 DENTON. H R Office of Nuclear Reactor Regulation, Director 3pp 22407 325 24% Fiche 50-546,84/02/21,8402270187
- @ Inspection reports. IE Bulletins & correspondence
- 8312120153 IE Info Notice 84-05, "Steam Binding of Auxiliary Feedwater Pumps " Svc list enci JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25 Consolidated Edison Co of New York
- 8401170016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co. of New York, Inc. 117pp 22114 179 24X Fiche 50-000.84/02/03,8401170016
- B401190017 IE Bulletin 84-01, "Cracks in BWR Mark 1 Containment Vent Headers " Svc list encl DEYDUNG-R C Director's Office, Office of Inspection and Enforcement B4/02/03 Consolidated Edison Co of New York, Inc 102pp 22177
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR30, App R) " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 257 24X Fiche 50-000,84/02/13,8401190041
- B401170039 IE Info Notice 84-08. "10CFR50 7. Employee Protection."

 Svc list encl

 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co. of New
 York, Inc. 115pp 22365 141 24X Fiche 50-000.84/02/14,8401170039
- 8401190045 IE Info Notice 83-63, Suppl 1. "Patential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JDRDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc. 118pp 22366 142 24X Fiche 50-000.84/02/15.8401190045
- B401170062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Below Manufacturer Recommended Value " Evc list encl JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidate Edison Co of New York, Inc 116pp. 22366-024 24% Fichs 30-000-84/02/21.8401170062
- 8401190056 IE Info Notice 84-11, "Training Program Deficiencies "
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- B401190067 IE Info Notice B4-12, "Failure of Soft Seat Valve Seals "

 Bvc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/02/27 Consolidated Edison Co. of New
 York, Inc. 120pp. 22431 060 R4X Fiche 50-000,84/02/27,8401190067
- 8 Reportable occurrences, LERs & related correspondence
- B402070365 Part 21 rept re linear converter device w/possible generic defect Initially reported on B40116 Written notifications issued Customer responses should be received by B40331 Final rept will be submitted by B40430
 DDD80N.J F Pacific Air Products Co B4/01/30 Director's Office, Office of Inspection and Enforcement 2pp 22114 297 24X Fiche 50-280,84/01/30.8402070365
- --B402070373 Part 21 rept re linear converter device w/possible generic defect initially reported on 840116. Preliminary analysis indicates excessive wear of brass shaft guides Next rept will be submitted within 90 days Supporting info encl DDDSON-JP Pacific Air Products Co 84/01/17 POTAPOVS. U Region 4. DFfice of Director 68pp 22114 301 24X Fiche 50-000.84/01/30.8402070365

- DOCKET STN-50-547 MARRIE HILL NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8402070003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documents
 FELTON, J M Division of Rules and Records 83/10/31
 ROSENBAUM, D M Technical Analysis Corp 17pp 22173 292 24X
 Fiche 50-000.83/10/31,8402070003
- --8402070185 Handwritten notes & calculations re const activities * NRC No Detailed Affiliation Given 82/10/31 5pp 22195 067, 24X Fiche 50-000.83/10/31,8402090003
- ~~8402090189 Handwritten notes & calculations re const activities & fuel 79/02/27 7pm
- 8402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILK. B J Office of the Secretary of the Commission 83/12/14 Public Document Branch 1p 2228 8402140003
- --8402160253 Discusses SECY-81-445 re review of director's denial of #QZ10U293 Discusses SECY-61-949 TE review of director's denial of IOCFR2 206 petition
 CHILK.S J Diffice of the Secretary of the Commission 62/01/07 DIRCKS W J Diffice of the Executive Director for Operations, BICKWIT.L Diffice of the General Counsel. Ip 22281 146 24X Fiche 50-000.63/12/14,8402160003
- 8402010410 Generic Ltr 84-04 to all operating PNR licensees. CP holders & applicants for CPs re safety evaluation of Hestinghouse topical repts dealing w/elimination of postulated pipe breaks in PHM primary main loops Svc list encl. EISENNUT. D @ Division of Licensing 84/02/01 Consolidated Edison Co of New York, Inc 59pp 22177 087 24x Fiche. 50-000. 84/02/01. 8402010410
- C Utility Environmental Report (ER), amends & correspondence
- B402010357 Approves 831028 request for withholding "Company Program to Calculate Annual Average Doses & Accident X/Qs (Annual ZAP-AZAP), "per 10CFR2 790 Info submitted in response to NRC environ rept OL Question 470.7
 YOUNOBLOOD B J Licensing Branch : 84/01/26 SHIELDS W Public Service Co of Indiana. Inc 3pp 22059 338 24X
 Fiche.50-546.84/01/26.8402010369. 84/01/26 SHIELDS:5 H Public 22057 338 24X
- E NRC Bafety Evaluation Report (SER), supply & correspondence
- 8402270187 Responds to 840118 request that NRC issue draft SER as is, so benchmark stists for licenses review process that has occurred Info now available to NRC would not support DENTIFIED INTO NOW SYSTEMS TO NAC SUBJECT TO NAC SU
- Q Inspection reports. IE Bulletins & correspondence
- B312120153 IE Info Notice 84~06, "Steam Binding of Auxiliary Feedwater Pumps " Svc list encl JDRDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/25, Consolidated Edison Co. of New York, Inc. 120pp R2058 001 24X Fichs 50-000:84/01/25,8332120153
- 3401190016 TE Info Notice B4-07, "Design-Basis Threat & Review of Vehicular Excess Controls " Byo list encl.
 JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp. 22114.179, 24X Fiche: 50-000, 84/02/03, 8401190016
- 1401190017 IE Bulletin 84-01, "Cracks in BHR Mark I Containment Vent Hydders " Svc list encl
 DEYOUNGAC Director's Office, Office of Inspection and
 Enforcement 84/02/03 Consolidated Edison Co. of New York, Inc 22177-156 24x Fich = 50-000, 84/02/03, 8401190017

- 8401190041 IE Info Natice 84-09, "Lessons Learned From NRC Insps of Fire Protection Safe Shutdown Sys (10CFR50.App R) " Syc list enck JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 820103) 84/02/13 Consolidated Edison Ca of Hey York, Inc 124pp 22365 259 24X Fiche 50-000,84/02/13,840119004
- B401190039 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection /" 10119039 IE Info Notice units of Emergency Preparedness & Engineering
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14 Consolidated Edison Co of Nay
 York, Inc. 115pp 22365 141 24% Fiche 50-000/84/02/14/8401190036;
- 8401190045 IE Info Notice 83~63. Suppl 1. "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co. of Meg York, Inc. 118pp 22366 142 24X Fiche 50-000. 84/02/15.8401190043
- 840119006R IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Bet Below Manufacturer Recommended Value " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co. of Hiw York, Inc. 116pp 22366-024 24X Fiche, 50-000, 84/02/21, 8401190052
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies. (01190066 IE into notice 0.... Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/24 Consolidated Edison Co. of New York, Inc 115pp 22430 304 24X Fiche 50-000, 84/02/24, 8401190066
- B401190067 IE Info Notice B4-12, "Failure of Soft Seat Valve Seals "
 Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/27 Consolidated Edison Co. of New
 York, Inc 120pp 22431 060 24X Fiche 50-000.84/02/27.8401190067
- S Reportable occurrences, LERs & related correspondence
- 8402070369 Part 21 rept re linear converter device w/possible generic defect Initially reported on 840116 Written notifications issued Costomer responses should be received by 840331 Final rept will be submitted by 840430 DODSON.J P Pacific Air Products Co 84/01/30 Director's Office, Office of Inspection and Enforcement 2pp. 22114.299. 24X Fiche 30-280, 84/01/30,8402070365
- --8402070373 Part 21 rept re linear converter device w/possible generic defect Initially reported on 840116 Preliminary analysis indicates excessive wear of brass shaft guides Next rept will be submitted within 70 days Supporting info encl DODSON. J P Pacific Air Products Co 84/01/17 PDTAPOVS. U Region 4, Office of Director 68pp 22114 301 24X Fiche 30-000, 84/01/30, 8402070365

DOCKET BIN-50-556 BLACK FOX STATION, UNIT 1

H General correspondence

8402130157 Requests deletion of GW Muench & RL Range from address Tabel, # Central Power & Light Co 84/02/03 Director's Office, Office of Inspection and Enforcement. 1p 22204 100 24X Fiche: 50-556, 84/02/03, 8402130157.

DOCKET STN-80-557 BLACK FOX STATION, UNIT 2

H General correspondence

8402130157 Requests deletion of GW Muench & RL Range from address label * Ce tape:

Central Power & Light Cg 84/02/03 Director's Diffice, Office of Inspection and Enforcement is 22204 100, 24X

Fiche 50-556,84/02/03,8402130157

DOCKET STN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1 T Hearing transcripts on non-antitrust matters

8402270302 Partial response to FOIA request for five categories of decuments re mothballed nuclear const projects App A documents being placed in PDR Document as listed on App B already available in PDR Search continuing FELTON, J M Division of Rules and Records 84/01/20 BELL.N. Nuclear Information & Resource Service 3pp 22375, 200 24% Fiche 50-000.84/01/20.8402270302

--B402270321 Testimony of JB Martin before Subcommittee on Energy Conservation & Power re nuclear power plants being constructed by WPPSS Related info encl MARTIN.J B Region 5, Office of Director 83/09/14 84pp 22395 104 24X Fiche 50-000.84/01/20.8402270302

DOCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2

- T Hearing transcripts on non-antitrust matters
- E492270302 Partial response to FOIA request for five categories of documents re mothbailed nuclear const projects App A documents being placed in FDR Document as listed on App B aiready available in FDR Search continuing FELTON, J M Division of Rules and Records 84/01/20 BELL, N Nuclear Information & Resource Bervice 3pp 22375 200 24% Fiche: 50-000, 84/01/20, 8402270302
- --B402270321 Testimony of JB Martin before Subcommittee on Energy Conservation & Power re nuclear power plants being constructed by WPPSS Related info encl MARTIN.J B. Region 5. Office of Director B3/09/14 86pp 22375.104 24X Fiche 50-000.84/01/20.8402270302

DOCKET STN-50-584 GIBBSAR, GIBBS & HILL

- A Application/construction stage documents & correspondence
- B402270225 Forwards revised organization chart dtd Jan 1984 Changes will be incorporated into next amend to Topical Rept @IBBAR-17A. KEDDIS:N N Gibbs & Hill: Inc (subs of Dravo Corp.) 84/02/21 Record Services Branch (Document Control Desk.) 1p 22389.111 24X Fiche: 50-584.84/02/21.8402270225

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 70-0008 BATTELLE MEMORIAL INSTITUTE, COLUMBUS, OH

- B402150249 Forwards IE Insp Repts 50-006/84-01 & 70-0008/84-01 on B40109-13 No noncompliance noted PAPERIELLO,C.J. Region 3, Office of Director 84/02/03 UNGAR.E W Battelle Memorial Institute, Columbus Laboratories 2pp 22250.031. 24X Fiche 50-006.84/02/03.8402150249
- ---8402150254 IE Insp Repts 50-006/84-01 & 70-0008/84-01 on 840109-13 No noncompliance noted. Major areas inspected, licensing status, operations review.criticality sefety, radiation protection & solid radwaste mgt
 MILLER,D E., FRANCE.O M., GREGER,L. R. Region 3, Office of Director. 84/02/03 7pp 22280 033 24X Fiche 50-006.84/02/03, 8402150249

"DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP., CANOGA PARK, CA

- 8402010334 Advises that Bldgs 001 & 131 & Yard Areas 507, 508 & 511 meet criteria for unrestricted use, based on 831221 survey, SNM shall not be used at locations w/o prior NRC approval CROM-W T Uranjum Fuel Licensing Branch 84/01/20 REMLEY, M E Rockwell International Corp ip 22059 304
- DOCKET 70-0027 BABCOCK & WILCOX CO . LYNCHBURG. VA
- 8402140403 Forwards IE Insp Rept 70~0027/83-30 on 831214-15. No violations or deviations noted.

 BTOHR. J. P. Division of Emergency Preparedness & Materials Safety 84/01/13. ECKERT.J. P. Babcock & Wilcox Co. ip. 22220 330
- --840R140407 IE Insp Rept 70-0027/83-30 on 831214-15 No violations or deviations noted Major areas inspected emergency preparedness.

 CLINE, N E., KREH, J L Region 2, Office of Director. JENKINB, Q. R Bivision of Emergency Preparedness & Materials Safety 84/01/05 6pp. 22220 351
- 8402140350 Notifies of extension of present unencapsulated matl access area by add1 325 square ft in filler press, Bay 2A area Drawing B1-10, Rev 10 to be replaced w/Drawing B1-10, Rev 20 Changes do not decrease effectiveness of security plan. REGANIN.A. Bebook & Wilcox Co 84/01/26, D'REILLY, J. P. Region 2, Office of Director ip. 22256.342

- DOCKET 70-0135 BABCOCK & WILCOX CD , APOLLO, PA
- 8402130310 Radioactive effluents discharged to unrestricted areas, Jul-Dec 1983 W/840203 ltr AUSTIN A Bahcock & Wilcox Co 83/12/31 MURLEY, T.E. Region 1, Office of Director 2pp 22200 323
- 8402100378 Forwards Amend 15 to License SNM-145 & replacement pages for license contained in 830817 & 0916 applications Amend revises organization & permits storage of low specific activity waste in outside storage area PAGE.R G Uranium Fuel Licensing Branch 84/02/07 AUSTIN,M A Babcock & Wilcox Co 2pp 22208 325
- --B402100400 Amend i5 to License SNM-145, revising organization & authorizing storage of low specific activity waste in outside storage area previously used for U hexafluoride storage PAGE, R G Division of Fuel Cycle & Material Safety 84/02/07 27pp 28280 325
- --8402100402 Submits review of licensee 830817,0916 & 1103 amend requests re organizational changes & storage of low specific activity waste in outside area Approval recommended NIXON,W A . CRUW, W T Uranium Fuel Licensing Branch 84/02/07 3pp 22208 352
- DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC , ERWIN, TN
- 8402070527 Ack receipt of IE Insp Rept 70-0143/83-46 No proprietary info QUINN,F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) 84/01/12 STDHR,J P Division of Emergency Preparedness & Materials Safety 1p 22141 208
- 8402140463 Ack receipt of IE Insp Rept 70-0143/83-46 dtd 831220 No proprietary info QUINN.F K Nuclear Fuel Services, Inc. (subs. of Getty Gil Co.) 84/01/12 STOHR.J P Division of Emergency Preparedness & Materials Safety ip 22221 249
- 8402100164 Application for amend to License SNM-123 Description of amend withheld (ref 10CFR9 5(e)(4) & 10CFR2 790)
 HENBLEY,K D Nuclear Fuel Services. Inc (subs of Getty Dil Co)
 84/01/17 BROWN,W R Diffice of Nuclear Material Safety &
 Bafeguards, Director 1p 22205 354
- 8402140425 Ack receipt of IE Insp Rept 70-0143/83-40 dtd 831130 No proprietary info QUINN,F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) 84/01/18 STOHR.J.P Division of Emergency Preparedness & Materials 8afety ip 22221 223.
- 8402140556 Forwards Rev 7 to site training plan Rev Incorporates organizational structure changes Encl withheld (ref 10CFR2 790) HENBLEY.K D. Nuclear Fuel Services. Inc. (subs. of Getty Gil Co.) 84/01/20 BROWN.W R. Fuel Facility Safeguards Licensing Branch 1p. 28255-341
- 8402100414 Forwards application to renew License SNM-124, due to expire on 840229 No increase in scope of presently licensed activities or current matl possession limits involved License fee for Category 1A renewal end.

 IDEKER, R L Nuclear Fuel Bervices, Inc (subs of Getty Dil Co) 84/01/23 Division of Fuel Cycle & Material Safety 3pp 22208 001
- --8402100416 Application to renew License BNN-124

 * Nuclear Fuel Bervices, Inc (subs of Getty Oil Co). 84/01/23
 225pp 22208 004
- B402140271 Forwards IE Insp Rept 70-0143/83-48 on 831209-30 No violations or deviations noted STOHR.J P Division of Emergency Preparedness & Materials Sefsty 84/01/25 GUINN.F K Nuclear Fuel Services, Inc (subs of Getty Oil Co.) 2pp 22228:275
- --8402140278 IE Imsp Rept 70-0143/83-48 on 831205-30 No noncompliance noted Major oreas inspected licensee action on previous insp findings & worker concerns Matl control & accounting areas & findings withheld (ref 10CFR2 790)
 LEG.T.D. MCALPINE, E. J. Region 2. Office of Director, 84/01/17 5pp. 22228, 277

- 8402150335 Forwards IE Insp Rept 70~0143/83-49 on 831220-21 No
 - violations noted
 STOHR,JP Divisson of Emergency Preparedness & Materials Bafety
 B4/01/25 GUINN,FK Nuclear Fuel Services, Inc (subs of Getty
 Dil Co) 2pp 22250 221
- ---B402i50337 IE Insp Rept 70-0143/83-49 on B3i220-21 No violations noted Major areas inspected operations & nuclear criticality safety re worker concerns CORYELL® P Region 2. Office of Director MCALPINE E J Division of Emergency Preparedness & Materials Safety 84/01/18 4pp 22250 223
- B402280685 Responds to NRC 840105 ltr re violations noted in IE Insp Rept 70-0143/83-47 Corrective actions onsite containers reinspected.procedures changed & identification sys modified QUINN:FK Nuclear Fuel Services. Inc. (subs. of Getty Oil Co.) 84/02/01 STOHR.J.P. Division of Emergency Preparedness & Materials Safety 3pp 22414-355
- 8402140156 PNO-11-84-007 on 840203, NFS reported inventory difference resulting from B31228 physical inventory U exceeded limit of error Investigation being conducted to determine cause MCALPINE.E J. Region 2, Office of Director 84/02/06 ip
- 8402280040 Ack receipt of IE Insp Rept 70-0143/83-49 on 840125 No proprietary info QUINN,F K Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 84/02/07 STOHR.J P Division of Emergency Preparedness & Materials Safety ip 22401 153
- 8403280299 Ack receipt of 831227 & 840116 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/83-39 STOURN, JP Division of Emergency Preparedness & Materials Safety B4/02/06 GUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) ip 22398 005
- --8402280303 Supplements response to NRC 831130 ltr re violations noted in 1E Insp Rept 70-0143/83-39 Corrective actions withheld (ref 100f82 790(d))
 GUINN, FK Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.)
 84/01/16 STOHR, P. Division of Emergency Preparedness & Materials
 Safety ip 28348 006
- 3402280523 Forwards IE Insp Rept 70-0143/84-01 on 840116-19 No violations or deviations noted STOHR, J P Division of Emergency Preparedness & Materials Safety 84/02/09, GUNNN.F.K Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp 22406 286
- **B402280534 IE Insp Rept 70-0143/84-01 on B40116-19 No violations or deviations noted Major areas inspected MC 852068 measurements & statistical controls (BCA-2 scrap/weste NDA measurement sys) Data(1s withheld (ref 10CFR2 790 & 73 21) CLAY, EL, MCALPINE, EJ Region 2, Office of Director 84/02/08 ip. 22406 288.
- B402280553 Confirms corrective actions re nuclear criticality safety violations.per B40208 telcon Employees instructed re requirements.daily audits on each shift established & findings used by mgt O'REILLY.JP Region 2. Office of Director B4/02/09 QUINN.F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) 1p 22404 129
- 9402170492 Confirms conversation to three deficiencies identified in 940123 application for renewal of License SNM-124 Listed nfor needed for initial review JBNG: A L Uranium Fuel Licensing Branch 84/02/11 IDEKER, R. clear Fuel Services. Inc. (subs. of Getty Oil Co.) 4pp 319 028

 - 280232 Confirms 840210 & 13 telcons re arrangements for 840216 iforcement conference in Atlanta, GA to discuss recurring vicicality safety violations (REILLV, J P. Region 2, Office of Director 84/02/13 QUINN, F. Uclear Fuel Services, Inc. (subs. of Getty Oil Co.) Ip.
- c402220304 Forwards IE [hsp Rept 70-0143/84-03 on 840131-0202 No violations or deviations noted STOHR, J P Division of Emergency Preparedness & Materials Safety 84/02/15. 001NN:F K Nuclear Fuel Services, Inc (subs of Getty Dil Co) 2pp 22335 357.

- --8402220307 IE Insp Rept 70-0143/84-03 on 840131-0202 No Vig1stions or deviations noted Major areas inspected security organisation, records, keys & access controls Details withheld TOBIN.W J Region 2, Office of Director MCGUIRE,D R of Emergency Preparedness & Materials Safety 84/02/15 22335 359 OINE, D.R. DIVISION 84/02/15 10
- 8402220540 Ack receipt of Rev 7 to site security training plan, contained in 840120 transmittal Change consistant w/provisions of 100FR70 32(e) & acceptable for inclusion into plan
 STOHR.J P Division of Emergency Preparedness & Materials Bafata
 B4/02/15 OUINN,F K Nuclear Fuel Services, Inc (subs of Catta
 Oil Co) ip 22333 284
- DOCKET 70-0221 GENERAL DYNAMICS CORP , GROTON, CT
- 8402020337 Discusses IE Insp Repts 30~03772/83-01 & 70~0221/83-01 en 831012 & Ferwards notice of violation MARTIN.T T Region 1. Office of Director 84/01/09 VELIGIIB,F I General Dynamics Corp 2pp 22055 023
- --8402020339 Notice of violation from insp on 831012 Violation note: failure of audible alarm on Co-60 permanent radiographic installation Lead Room 2 to sound upon testing * Region 1. Office of Director 84/01/07 ip 22055,025
- DOCKET 70-0364 BABCOCK & WILCOX CD , APOLLO, PA
- 8402060086 Forwards IE Insp Rept 70-0364/83-09 on 830523-24 & notice of violation MARTIN.T T Division of Engineering & Technical Programs. 83/12/23 CDLEMAN,W L Babcock & Wilcox Co 2pp 22083 263
- --B402060091 Notice of violation from insp on 830523-24 * Region 1, Office of Director 83/12/23 1p 22083 265.
- --8402060095 IE Insp Rept 70-0364/83-09 on 830523-24 Violation notes, failure to provide strong, tight packages for transport of waste shipment NS.P. PASCIAK.W. Region 1. Office of Director 83/12/23 22083 266 CLEMONS, P
- B402130310 Radioactive effluents discharged to unrestricted areas.Jul-Dec 1983 W/B40203 ltr AUSTIN:M A Babcock & Wilcox Co B3/12/31 MURLEY, T.E. Region I. Office of Director 2pp 22200 323,
- 8402090597 Issues Amend 22 to License SNM-414, revising organizational structure at Parks Township, PA Pu plant, per 830817 & 1103 applications Safety evaluation supporting amend encl. OREENMAN.E O Division of Project & Resident Programs 84/01/30 AUSTIN.M A Babcock & Wilcox Co 2pp 82189 351
- --8402090401 Safety evaluation supporting Amend 22 to License SNM-414.
 revising organizational structure at facility to allow
 efficient utilization of manpower resources at
 decommissioning facility
 * Region 1, Office of Director 84/01/30 4pp 22189 333
- --8402090604 Amend 22 to 8&W license 8NM-414, revising organizational structure at Parks Township, PA Pu plant, GREENMAN, E O Division of Project & Resident Programs 84/01/30 ip 22187 357
- 8402230142 Issues Amend 23 to License SNM-414, deleting & or revising license conditions due to phaseout of production operations & ensuring that license accurately reflects current site activities, per 830922 application SER & amend encl GREENMAN.E Q. Division of Project & Resident Programs 84/02/09 AUBTIN, M A Babcock & Wilcox Co 14pp 22379 246
- --8402230147 Application to amend License BNM-414, deleting & revising several license conditions due to decontamination & phaseout of Pu plant operations at Parks Township site. Amend fee --BTIN,M A Babcock & Wilcox Co B3/09/22 EL8ASBER,T C. Region Office of Director 3pp. 22379.260 AUSTINAM A
- B402220446 Ack receipt of B40117 ltr informing NRC of steps taken to correct violations noted IE Insp Rept 70-0364/83-09 MARTIN.T T Division of Engineering & Technical Programs. B4/02/13 COLEMAN.W L Babcock & Wilcox Co 1p 22339 345

1

- --8402220450 Responds to NRC 831223 ltr re violations noted in IE Insp space20450 Responds to NRC 831223 ltr re violations noted Rept 70-0364/83-09 Corrective actions design & const improvements of burial box made Special mgt audit team established to review radwaste shipments AUBTIN.M A Babcock & Wilcox Co 84/01/17 MARTIN,T of Engineering & Technical Programs 3pp 22339 344 MARTIN, T T Division
- DOCKET 70-0371 UNC NAVAL PRODUCTS, INC . UNCASVILLE, CT
- 8402020215 Forwards IE Safeguards Insp Rept 70-0371/83-12 on #331128-1202 No violations noted
 MARTIN,T T Division of Engineering & Technical Programs #3/12/30
 AMY.O D United Nuclear Corp 2pp #22057 0B4
- --8402020226 IE Safeguards Insp Rept 70-0371/83-23 on 831128-1202 No violations noted Major areas inspected measurement controls & inventory verification DELLA RATTA, A. ZIBULSKY, H., SMITH, O. Region i, Office of Director 83/12/27 Spp 22057 086 83/12/27 Bpp
- B402030431 Ack receipt of B30818 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0371/83-04 on B30404-07.
 BTARDSTECKI, R Division of Project & Resident Programs 84/01/24
- --8402030436 Responds to NRC 830707 ltr re violations noted in IE Insp Repts 70-0371/83-04 Corrective actions health physics technicians reminded of responsibility to review results & take specified actions AMY.0 O United Nuclear Corp 83/08/18, STAROSTECKI.R Division of Project & Resident Programs 4pp 22069 023
- 8402080243 Forwards IE Enforcement Conference Repts 70-0371/83-04 & 70-0371/83-00 on 830802-05 & notices of violation & deviation.

 STAROBTECKI, R Division of Project & Resident Programs 84/01/26
 AMY, G D United Nuclear Corp 2pp 22131 271
- --8402080247 Notice of violation from insp on 830802-05 * Region 1, Office of Director 84/01/26 1p 2: 22131.273
- --8402080253 Notice of deviation from insp on 830802-05
 * Region i, Office of Director, 84/01/26 ip 2: 22131, 274
- --8402080270 IE Enforcement Conference Repts 70-0371/63-04 & 70-0371/83-08 on 830802-05 Violations noted supervision did not assure that Regulation 3 followed prior to leaving controlled area ROTH J Region 1, Office of Director ELBABBER, T. C. D Project & Resident Programs, 83/01/04 5pp 22131:275 Division of
- 8402240022 Forwards IE Safeguards Insp Rept 70-0371/84-01 on 840116-20, No violabions noted MARTIN.T.T. Division of Engineering & Technical Programs 84/02/09 AMY.O.D. United Nuclear Corp 2pp. 22375 324
- ---B402240027 IE Safeguards Insp Rept 70-0371/84-01 on 840116-20 No noncompliance noted Major areas inspected physical iory. RATTA,A , SMITH,G., DUNLAP,J M Region i, Office of ior. 84/02/09 2pp 22375 326 Director.
- DOCKET 70-0487 UNION CARBIDE CORP , TUXEDO, NY
- 8402020342 Forwards IE Insp Rept 70-0687/83-04 on 831114-16 & notice of violation.
 STAROSTECKI, R. Division of Project & Resident Programs. 64/01/20.
 MCODVERN, J. J. Union Carbide Corp. 2pp 22035 037
- --8402020344 Natice of violation from insp on 831114-16. * Region 1, Office of Director 84/01/20 ip 22055 039
- -8402020348 IE Insp Rept 70-0487/83-04 on 831114-16 Violation noted. failure to post two 8NM storage areas w/criticality safety ROTH, J Region 1, Office of Director ELBASBER, T C Division of Project & Resident Programs 84/01/17 7pp. 22055 040.
- 8402030038 Forwards BER re emergency plan Plan acceptable W/o and TERRY, Q, A Uranium Fuel Licensing Branch, 84/01/25 ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch ip 22091:092
- 8402290445 Forwards JJ McGovern 831215 amend request, per 840125 telcon. RUZICKA, H. Q Union Carbide Corp. 84/01/26, TING, H NRC - No Detailed Affiliation Given ip 22437-361

- --8402270493 Requests emergency extension of License SNM-639 for 2 months to store recovered U shipping containers in gamma MCCOVERN.J J Union Carbide Corp 83/12/15 CLARK, A T NRC - No Detailed Affiliation Given 1p 22437 362
- DOCKET 70-0498 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA
- 8402070427 Discusses Westinghouse Waltz Mill site groundwater monitoring program Present program of search for source of contamination should be continued CROW.W T Uranium Fuel Licensing Branch 84/01/30 PAGE.R 9 Uranium Fuel Licensing Branch 3pp 22142 100
- B402130548 Discusses Westinghouse groundwater monitoring program Several wells & addl test holes still have high water concentrations Investigation of contamination recommended XETZLACHIN Uranium Fuel Licensing Branch 84701/31 BERNARI Standardization & Special Projects Branch 2pp 22214 312
- DOCKET 70-0710 MERRIMACK COLLEGE, NORTH ANDOVER, MA
- 8402060110 Advises of expiration of License SNM-648 & discusses actions
- DOCKET 70-0734 GA TECHNOLOGIES, INC . SAN DIEGO, CA
- B40207026B Application for amend to License SNM-696, authorizing performance of mpt review & audits once each CY w/no interval greater than 13 months Glossary of frequency definitions encl MOWRY W R GA Technologies, Inc /General Atomic Co 83/12/22 BROWN W B Fuel Facility Safeguards Licensing Branch 4pp 20177 258 22177 358
- DOCKET 70-0754 GENERAL ELECTRIC CO , PLEASANTON, CA
- 8402130427 "Effluent Monitoring Rept for Jul-Dec 1983" GEST.R E . CUNNINGHAM.G E General Electric Co 83/12/31 CUNNINGHAM.R E Division of Fuel Cycle & Material Safety. 1p
- B402090620 Advises that reporting requirements of 10CFR70 59 inapplicable to License BNM-960, Amend 20, which eliminated fuel processing, fabrication & U hexafluoride conversion ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch. B4/01/30 CUNNINGHAM, O E. General Electric Co. ip. 22187 359
- 8402070007 Confirms conversation w/Judge Linenberger Extension granted until 840210 to respond to petitioner revised contentions.

 TURK, S. E. Hearing Branch I. 84/02/02 FRYE, J. H. FOREMAN, H., LINENBERGER, G. Atomic Safety and Licensing Board Panel. 1p 22102 322 24x Fiche 50-070, 84/02/02, 8402070007
- B4022201B2 Response to petitioner J Turk initial & revised contentions
 Petitioner failed to present admissible contention &
 petition to intervene should be denied Certificate of Svc TURK, B. E Hearing Branch 1 84/02/10 Atomic Safety and Licansing Board Panel 56pp 22340 237 24X Fiche 50-070, 84/02/10, 840220182
- 8402220449 Forwards IE Bafeguards Insp Rept 70-0754/84-01 on 840112-13 No noncompliance noted
 NORDERHAUG.L R. Region 5. Office of Director 84/02/14.
 DARMITZEL.R W. General Electric Co. 2pp. 22340 047
- --B40222045B IE Bafeguards Insp Rept 70-0754/84-01 on 840112-13 No noncompliance noted Major areas inspected facility organization & operations & shipping & recuiving Details withheld (ref 10CFR2 790) WIEDER, A V. NELSON, G B., NORDERHAUG, L R. Region 5, Office of Director 84/02/10 ip 22340 049
- DOCKET 70-0820 UNITED NUCLEAR CORP . WOOD RIVER JUNCTION, RI
- 8402010361 Forwards status rept re ongoing evaluation & followup items per 831207 meeting concerning decommissioning of site Bldg areas known to require further decontamination listed MYNGARDEN, S D Uranium Fuel Licensing Branch 84/01/26 CRDW, W T Uranium Fuel Licensing Branch. 3pp 82059 341.

- 840213056B Forwards listed preliminary results of survey for radionuclide concentrations BOMELL-L L Oak Ridge Associated Univs 84/01/31 CROW,U Division of Fuel Cycle & Material Safety lipp 22257 341 1 CROW, W 22257 348
- 8402160476 forwards Dak Ridge Associated Univs 840131 ltr re preliminary results of surveys of United Nuclear Corp W/o
 - enc. BIDINGER, G H Uranium Fuel Licensing Branch 84/02/06 HELGESON, K United Nuclear Corp ip 22302 130
- DOCKET 70-0824 RANCOCK & WILCOX CO , LYNCHBURG, VA
- 8402140423 Forwards IE Insp Rept 70-0824/83-07 on 831212-13 No violations or deviation noted STOWALJ P Division of Emergency Preparedness & Materials Safety 84/01/12 ENGELDER.T C Dabcock & Wilcor Co 2pp 22227 130
- --8402140428 IE Insp Rept 70-0824/83-07 on 831212-13 No violations or deviations noted Major areas inspected emergency preparedness CLINE,N E., KHEH,J L. Region 2, Diffice of Director JENKINS,G R Division of Emergency Preparedness & Materials Safety 84/01/05 4pp 22227 132
- 8402280173 Discusses actions to be taken re shipment of radioactive matta from facility to Richland. WA burial site, per 840204 telcon Investigation to determine cause of holds in two waste druns will be initiated O'REJLLY, J P Region 2: Defice of Director 84/02 ENGELDER, T C Dabtock & Wilcox Co 1p 22400-246
- DOCKET 70-0925 KERR-MCGEE NUCLEAR CORP . OKLAHOMA CITY, OK
- 8402270546 FOIA request for listed documents re Kerr-McGee Cimmaran facility BARNES C Affiliation Not Assigned 83/12/11 Administration ip 22414 147
- 8402220422 "Radioactivity in Gaseous Effluents Second Half 1983." 102220464 THOUSENESS OF THE SHELLEY, W. J. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 83/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J.O. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLER, J. Region 3, SHELLEY, W. J. Kerr-McGee Corp. 82/12/31 KEPPLE
- DOCKET 70-1100 COMDUSTION ENGINEERING, INC , WINDSOR, CT
- 8402210094 "Airborne & Liquid Effluent Releases for Ju]-Dec 1983 "
 SHEERAN R E Combustion Engineering Inc 84/02/09 Region :
 Office of Director 1p 22317 238 Region 1,
- 8402270220 Forwards IE Insp Rept 70-1100/84-01 on 840107-12 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 84. LICHTENBERGER Combustion Engineering, Inc. 2pp 22421 019
- ---8402270224 Notice of Viglation from insp on 840109-12.
 * Region 1. Office of Director 84/02/13 ip 2 22421:021
- --8402270233 IE Insp Rept 70-1100/84-01 on 840107-12 Violation noted. Failure to conduct criticality safety evaluation of Unmeasured SNM authorized on pellet shop mezzanine on 840110 ROTHLU Region i. Office of Director ELSASSER.T.C. Di Project & Resident Programs 84/02/08 10pp 22421:022 Division of
- DOCKET 70-1113 GENERAL ELECTRIC CO . WILMINGTON, NO
- 3402140340 Application for amend to License SNM-1097, revising operating procedures to allow control of incinerator sys to be based on measured U-238 yailurs & enrichment of not less than 2 75% U-235 Justification encl VAUOHAN, C M General Electric Co B4/01/09 CRDW, W Y Uranium Fuel Licensing Branch 7pp 22256 346
- 8402100148 Application for amend to License SNM-1097 allowing introduction of SNM into U process mgt project facilities on 841001 Discussion of licensing action & demonstration of safety withheld (ref 100FR2 790)

 * General Electric Co. 84/01/25 CROW, W.T. Office of Nuclear Material Safety & Safeguards, Director 1p 22205-356

- B402010354 Summary of B40119,23 & 25 meetings w/Edlow Intl & QE re #;, at storage warehouse in IL.proposed storage of U hexafluoride, SNN & addl scrap & liquid waste treatment capabilities at Wilmington.DE PAGE.R G Uranium Fuel Licensing Granch B4/01/26 DAVIS,J Q Office of Nuclear Material Safety & Safeguards, Director 3pp 20058
- 840229033i Discusses 840208 meeting w/State of NC.Dept of Natural Resources & Community Development re affluent & environ monitoring requirements & 840208-10 meetings at GE fuel fabrication facility PAGE.R O Uranium Fuel Licensing Branch 84/02/16 DAVIS.J Q Office of Nuclear Material Safety & Safeguards.Director ip 22437 322
- DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA
- 8402070187 Forwards IE Insp Rept 70-1143/83-05 on 831205-14 No violations noted STAROSTECKI,R Division of Project & Resident Programs 84/01/23 JACOBI,W M General Electric Co 2pp 22:02 174
- --8402070190 IE Insp Rept 70-1149/83-05 on 831203-16 No violations neigh Major areas inspected decommissioned Pu fuels development lab confirmatory survey Approx 78 grid blocks contaminated in excess of NRC criteria In excess of NRC criteria MOTM, J Region 1, Office of Director ELBASSER, T C Di Project & Resident Programs 84/01/22 11pp 22102 196 Division of
- DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA
- B402100019 Effluent monitoring rept for Jul-Dec 1983 GODDWIN.W L Westinghouse Electric Corp B3/12/31 Direc Office. Office of Inspection and Enforcement 1p 22182 150 Director's
- B402070508 Forwards rev to upgraded fundamental nuclear mat1 control plan for review & approval Rev withheld (ref 100FR2 790(d))
 NARDLA J Westinghouse Electric Corp 84/01/09 BROWN. W B Furl Facility Bafeguards Licensing Branch ip 22141 225
- 8402140375 Forwards IE Insp Repts 70-1151/83-29 on 831213-16 No. violations or deviations noted STOHR.J P Division of Engineering & Operational Programs. 84/01/10 BRITTON, W Hestinghouse Electric Corp 2pp 22220 057
- --8402140380 IE Insp Rept 70-1151/83-29 on 831213-14 No violations of deviations noted Major areas inspected radiation protection procedures surveys, MPC-hour records, respirator maint & bioassay gragram
 ALBRIGHT, R H Region 2, Office of Director BARR, K P. Division of Engineering & Operational Programs 84/01/06 App. 22220 059
- 8402080010 Forwards request for add1 info re application for renewal of License SNM-1107.including ALARA rept.certification from local responsible govt agency concerning bldg codes & evidence of insurability BIDINGER.O.H Uranium Fuel Licensing Branch 84/01/26 NARDI.A J Westinghouse Electric Corp. 7pp 22172:355
- 8402270379 Submits question re renewal of License SNM-1107 pmitted fice comments & request transmitted on 840126 Reply should be provided w/response to 840126 itr BIDINGER, G. H. Uranium Fuel Licensing Branch 84/02/23. NARDI.A J Wastinghouse Electric Corp. 1p 22438 233
- DOCKET 70-1193 KERR-HOGES NUCLEAR CORP , DKLAHOMA CITY, DK
- 8402240184 FGIA request for 750116 DEB for mixed oxide fabrication plant in Logan County, OK & for 791207 PNO BARNES: C. Affiliation Not Assigned 83/12/06, Office of Afministration ip 22381 286
- 8402240180 Responds to FDIA requests for two documents by accession number on Kerr-McGee Cimerron facility & nine documents by accession number on Kerr-McGee West Chicago facility. Request sent to PDR for processing by PDR contractor FELTON. J M Division of Ruiss and Records 83/12/15 BARNES.C Affiliation Not Assigned ip. 22381 285.
- 8402220422 "Redicartivity in Gaseous Effluents Second Half 1783 " W/640214 ltr SHELLEY,W J Kerr-McGae Corp. 83/12/31 KEPPLER, J. C Region 3. Office of Director 3pp 22340.028

DOCKET 70-1201 BABCOCK & WILCOX CO , LYNCHBURG, VA

- B402150070 "Effluent Monitoring Rept.Jul-Dec 1983 " W/B40106 ltr SPEIGHT.C W Babcock & Wilcox Co 83/12/31 Region 2. Office of Director 2pp 82862 339
- 840214053B Application for amend to License SNM-1168, revising radiological contingency plan, Pages 1-1, 1-3, 1-4, 1-7, 4-2 & 5-16
- 5-16 FORD, J. T. Babcock & Wilcox Co. 84/01/10 PAGE, R.Q. Uranium Fuel Licensing Branch Epp. 22256-354
- 8402140059 Forwards IE Insp Rept 70-1201/83-14 on B31213 No violations or deviations noted BTOHM, J P Division of Emergency Preparadness & Materials Bafety 84/01/13. ALTO,R A Babcock & Wilcox Co 2pp 22217 179
- --B402140063 IE Insp Rept 70-1201/B3-14 on B31213 No violations or deviations noted Major areas inspected emergency preparedness CLINE M.E., JENKING, O.R. Division of Emergency Preparedness & Materials Safety KREH, J.L. Region 2. Office of Director B4/01/05 4pp 22217 181
- 8402100138 Application for amend to License SNM-1168 requesting proposed license condition re slightly enriched matl Proposed license condition & justification withheld (ref 10CFR2 790)
 FORD, J. T. Babcock & Wilcox Co 84/01/18 BROWN, W B Fuel Facility Bafeguards Licensing Branch 1p 22205 355

DOCKET 70-1257 EXXON NUCLEAR CD , INC , RICHLAND, WA

- 8402130418 Forwards application for amend to License SNM-1227, reflecting organization changes MALOPY, C W. Exxon Nuclear Co , Inc (subs of Exxon Corp) 83712705 CROW.W T. Uranium Fuel Licensing-Branch, ip 22216 163
- ~~8402140040 Application for amend to Licanse SNM-1227, reflecting organization changes * Exxon Nuclear Co., Inc (subs of Exxon Corp). 83/12/12 47pp 22236 235.
- 8402220408 Forwards IE Safeguards Insp Rept 70-1257/83-07 on 831108-17 & 1215-19 & notice of violation.

 NORDERHAUG.L R. Region 5 Office of Director 84/02/16 NILSON, R
 Excon Nuclear Co. Inc. (subs. of Excon Corp.) 2pp 22340 042
- --8402220418 IE Safeguards Insp Rept 70-1257/83-09 on 831108-17 to 1212-14. Noncompliance noted integrity of tamper seals applied to several U dioxide pouder buckets in 13A storage area not verified Details withheld (ref 10GFR2.790). NELSON. 9 B. WIEDER, A V. NORDERHAUG, L. R. Region 5. Office of Director. 84/02/14 ip 22340.046

DDCKET 70-1308 GENERAL ELECTRIC CO . BAN JOSE, CA

- 8402130431 Discusses schedule for shipments of irradiated PWR nuclear fuel from Morris, IL to Two Rivers, WI Safeguards info withheld (ref 10CFR73, 21) * General Electric Co 84/01/11 HILLMAN, CR. Office of Nuclear Material Safety & Bafeguards, Director 1p. 22216 137
- B402160610 Bubmits ninth notification re series of 109 shipments of irradiated PWR nuclear fuel from Morris, IL, to Wisconsin Electric Power Co in Two Rivers, WI Shipments scheduled at rate of three per wk Encl withheld (ref 10CFR73 21)

 4 General Electric Co. 84/02/02, HILLMAN, C.R. Division of Bafeguards, 1p. 22302-029
- B402270138 "Annual Rept of Radionuclides Released to Environ in Airborne & Waterborne Effluents: 1983."

 EGER: K. J General Electric Co 84/02/15 2pp. 22391, 195

- DOCKET 70-1362 HAHNEMANN MEDICAL COLLEGE & HOSP , PHILADELPHIA, PA
- 8402220354 Discusses IE Insp Repts 70-1362/83-01 & 30-02959/83-01 & forwards notice of violation Concern expressed reimplementation of mgt control sys MARTIN, T T Division of Engineering & Technical Programs 83/12/20 MILLS, L C Hannemann Medical College & Hosp , Philadelphia, PA 3pp 22333 050
- --8402220361 Notice of violation from insp on 830702 Violations noted licensed mat1 stored in labs unlocked & not under constant surveillance or immediate control of licensee & employees assigned janitorial duties not properly instructed * Region 1. Office of Director 83/12/23 4pp 22333 053

DOCKET 70-1389 ST FRANCIS HOBP , EVANSTON, 1L

- 8402190303 IE Insp Findings & Licensee Ack dtd 840207-08 of Licenses SNM-1426, 12-00763-02 & 12-00763-03 Insp findings records of personnel monitoring surveys not properly maintained.per License Condition 21 of License 12-00763-02 LYNCH.J L Region 3, Office of Director 84/02/08 ip 22250 250
- DOCKET 70-1465 BT ANTHONY HOSP , ROCKFORD, IL.
- 8402060374 IE Insp Findings & Licensee Ack dtd 840127 of Licenses 12-00351-03 & SNM-1431 Insp findings no violations observed, Corrective actions re violations identified during last insp verified, SHATTERLY,I. W Region 3, Office of Director 84/01/27 ip
- DOCKET 70-2077 SUBURBAN GENERAL HOSP / NORRISTOWN, PA
- 8402280404 Ack receipt of 831230 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-2077/83-01 & 30-031979/83-01 MARTIN,T T Division of Engineering & Technical Programs 84/02/23 ANDERSON, B Suburban General Hosp, Norristown, PA 1p 22407 137
- --B40228040B Responds to NRC B31222 ltr re violations noted in IE Insp Repts 70-2077/B3-01 & 30-03193/B3-01 Corrective actions: cumulative radiation exposure history will be increased by amount equal to average monthly dose for 3-month period ANDERBON.R B. Suburban General Hosp, Norristown PA. B3/12/30 GLENN, J.E. Region I, Office of Director ip 22407 138

DOCKET 70-2134 GRANDVIEW HOBP , DAYTON, OH

- 8402290230 IE Insp Findings & Licensee Ack dtd 840215 of License BNM-1603 Insp findings no violations observed * Region 3, Office of Director 84/02/15 ip 22425:288
- DOCKET 70-2362 BROCKTON HOSP , BROCKTON, MA
- 8402020143 Ack receipt of 831206 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-2362/83-01, 30-01860/83-01 & 30-00235/83-01 Brackton, T Division of Engineering & Technical Programs 84/01/09 HENRY, W M Brockton Hosp , Brockton, MA 1p 22056, 161
- --8402020148 Responds to NRC 831110 ltr re violations noted in IE Insp. Rept 30-01860/83-01 Corrective actions technologists reminded to perform daily surveys of elution preparation & injection areas.

 HENRY, W.M. Brockton Hosp., Brockton, MA 83/12/06 Region 1, Office of Director. 1p. 22056-162

DOCKET 70-2896 MCKAY-DEE HOSP CENTER. OGDEN, UT

8402210053 IE Insp Findings & Licensee Ack dtd 840118 of License 6NM-1847 Insp findings no violations observed 8HGPENN, M Region 4, Office of Director. 84/01/18 ip. 22317, 259

- DOCKET 70-2910 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN
- 8402090260 Application to extend License BNM-1861 to 850131 to accommodate const delays MILLS.L M Tennesace Valley Authority 84/01/10 CROW.W T Division of Fuel Cycle & Material Safety 1p 22188 339
- 8402060645 Issues Amend & to License SNM-1861.changing expiration date to 880131 or upon conversion of CPPR-91 to OL PAGE.R & Uranium Fuel Licensing Branch 84/01/27 MILLB.L M Tennessee Valley Authority 2pp 22092 001
- --8402060646 Safety evaluation approving Amend 6 to License SNM-1861 SERINI, B L Uranium Fuel Licensing Branch 84/01/27 ip 22092 002
- DOCKET 70-2932 TEXAS UTILITIES GENERATING CO . DALLAS, TX
- 8402100455 Application for amond to License SNM-1912, reflecting comparate reorganization of Texas Utils Co Affidavit encl GARY.R J Texas Utilities Concretating Co 84/01/13 Office of Nuclear Material Safety & Safeguards
- B402160602 Notifies of issuance of amend to License SNM-1912, reflecting corporate reorganization of Comanche Peak ownership Bafety evaluation & Amend I to Indomnity Agreement B-76 encl PAGE.R O Uranium Fuel Licensing Branch B4/02/09 GARY,R J Taxas Utilities Generating Co Ip 22302 034
- --8402160604 Bafety evaluation supporting amend to License 9NM-1912, reflecting corporate reorganization of Comanche Peak ownership KETZLACKIN Uranium Fuel Licensing Branch 84/02/09 3pp
- DOCKET 70-2946 LOUISIANA POWER & LIGHT CO , NEW ORLEANS, LA
- 8402140571 Marked-up application for amend to License SNM-1913, authorizing storage & use of ex-core detector assemblies ORUMMOND,F J Louisiana Power & Light Co 89/12/19 DAVIS, Uranium Fuel Licensing Branch 2pp 22256 336
- 8402070531 Provides add1 info re 831219 amend to License SNM-1913 containing provision to include storage & use of ex-core detector assemblies BRUMMOND,F.J Louisiana Power & Light Co 83/12/27, DAVIS,J Uranium Fuel Licensing Branch 2pp 22141 204
- DOCKET 70-2950 WASHINGTON PUBLIC POWER SUPPLY SYSTEM, RICHLAND, WA
- 8402090573 Advises that since CPPR-93 was converted into DL (NPF-21) on 831220, License BNM-1890 expired THOMAS:R D Region 5, Office of Director 84/01/12. PAGE:R Q. Uranium Fuel Licensing Branch. 1p 82186 362
- DOCKET 70-2995 EQLOW INTERNATIONAL CO . WASHINGTON. DC
- 8402150032 Application for amond to License BNM-1903, authorizing temporary storage of mat2 in different location on same site. Diagram encl EDLOMY Effour International Co 84/01/23 CROW, W T Office of luclear Material Safety & Bafeguards, Director 4pp 22262 344
 - 2010334 Summary of 640119, 23 & 25 meetings w/Edlow Intl & QE re fire t storage warehouse in IL, proposed storage of U exafluoride. SNM & addl scrap & liquid waste treatment spablitities at Wilmington, DE AGE, R. 9 Uranium Fuel Licensing Branch 84/01/26 DAVIS, J Q Ffice of Nuclear Material Safety & Safeguards, Director. Jpp 2059, 334
 - 2030092 Summarizes items of interest arising from 840117 & 23 leatings w/Eddow Intl re fire in storage warehouse & 840125 meeting w/6E re U process myt project List of meeting nutles encl
 PAGE.R O. Uranium Fuel Licensing Branch 84/01/26 DAVIS.J O Office of Nuclear Material Safety & Safeguards. Director Spp
 - GODANA Anna l'anna Chilliana Conthina la materiale anti-
 - 92050552 Amends License SNM-1903, Condition 10 authorizing outdoor torage of cylinders containing enriched U hexafivoride.

 VE.R O. Uranium Fuel Licensing Branch 84/01/27. EDLOW, J Edlow ternational Co. 4pp 82092 127

- --8402060553 SER approving 840123 application to authorize temporary outside storage of enriched U hexafluoride subj to listed conditions Relocation provides sufficient interim fire protection
 BIDINGER.G H Uranium Fuel Licensing Branch. 84/01/27. 5pp
- 8402060375 Discusses 840119 conference w/vendor re potential environ impacts from major fire where U hexafiluride cylinders stored New physical protection measures & continuous fire watches required PAGE.R.O Uranium Fuel Licensing Branch 84/01/31 CUNNINGHAM, 8 E/Division of Fuel Cycle & Material Safety 1p 22110 304.
- DUCKET 70-2960 KANSAS GAS & ELECTRIC CO . WICHITA, KS
- 8402130407 Forwards Rev 3 to application for SNM license. Rev changes date requested for license to 840402 & updates quantity of U in boron monitor fission counter KDESTER, D L Kansas Cas & Electric Co 84/01/R3 DAVIS, J G, Office of Nuclear Material Safety & Safeguards, Director 3pp 20214 140
- --8402130410 Rev 3 to application for SNM license Rev changes date requested for license to 840402, specifies number of area radiation monitors that will be located in fuel handling area during fuel movement & updates quantity of U

 + Kansas Gas & Electric Co 84/01/23 7pp 22216 172
- DOCKET 70-2986 WEBER STATE COLLEGE, DODEN, UT
- B402210228 IE Insp Findings & Licenses Ack dtd 840118 of License BNM-1931 Insp findings no violations observed BHOPENN, N M Region 4, Office of Director 84/01/18, 1p
- DOCKET 70-2988 PHILADELPHIA ELECTRIC CO , PHILADELPHIA, PA
- 8402150547 Forwards amended application for 8MM license, incorporating info previously submitted to NRC in response to requests for addl info.

 BRADLEY,E J Philadelphia Electric Co 84/01/24 DAVIS, J. Q. Office of Nuclear Material Bafety & Safeguards, Director 2pp 22259; 001
- --8402150548 Amended application for SNM license, incorporating info previously submitted to NRC in response to requests for add1 info W/one oversize drawing Aperture card is available in POR BAUER: E O., BRADLEY, E. J. Philadelphia Electric Co. 84/01/84 125pp. 22259,003
- B402280689 Application for amend to License BNM-1926, authorizing storage of 764 nuclear fuel bundles until issuance of license Issuance of amend by 840301 requested KEMPERJ B Philadelphia Electric Co. 84/02/06. CROW.W.T Uraniva Fuel Licensing Branch 2pp. 22414 349
- B402290372 Issues Amend 1 to License SNM-1926 revising Items 6.7 & 8. per B40216 discussion PA05.R Q. Uranium Fuel Licensing Branch B4/02/16 BAUER, E. Q. Philadelphia Electric Co ip. 22438: 238
- PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS
- DOCKET 71-0001 ANEFCO, INC
- 8402070517 Forwards title page for 831222 ANEFCO QA manual to replace original title page which was stamped w/proprietary statement.

 MURPHY D. J. Amerco, Inc. 84/01/17. MACDONALD, C. Transportation Certification Branch ip 22141.263
- --8402070519 Revised title page to Rev O to "GA Program for ANEFCD Shipping Packages for Radioactiva Matl," sacond edition * Anefco, Inc 83/12/22, ip. 22141-264.
- 8402130349 Forwards GA program approval for radioactive matl package ODO1.Rev 2 MACDDNALD.C E. Transportation Certification Branch. 84/02/01. MURPHY, J D. Anafoo, Inc. 1p. 22216:356

- --B402i3O364 GA program approval for radioactive matl package 0001.Rev 2 MACDONALD.C E Transportation Certification Branch 84/02/01 ip 22216 397
- DOCKET 71-0019 ROCHESTER GAS & ELECTRIC CORP
- 8402030301 Forwards QA program approval for Radioactive Matl Package 0019, Rev 2 MACBONALD: C E Transportation Certification Branch 84/01/24 MACBONALD: F Rochester Gas & Electric Corp ip 22089 349
- ---B40203030B GA program approval for Radioactive Matl Package 0019,Rev 2 MACDUNALD.C E Transportation Certification Branch, 83/01/24 ip 22089 350
- DOCKET 71-0085 NAVY, DEPT OF
- B402010122 Forwards GA program approval for Radioactive Matl Package OBB, Rev 2 MACDDNALD, C. E. Transportation Certification Branch 84/01/17. MCMANAHAN, V. L. Navy, Dept. of, Naval Bea Systems Command 1p 32048: 314

DOCKET 71-0103 NAVY, DEPT OF

- B402150418 Forwards endorsed request by Pearl Harbor Naval Shipyard re use of 20HC-4 overpack w/Spec-55 container for shipment of Type B quantities of Ca-137 HCMANAMAN, V.L. Navy, Dept of, 84/01/26 - GORDON Division of Fuel Cycle & Material Safety, 1p 22263.343
- --B402150421 Requests authorization to use 20HC-4 overpack w/Spec-55 containers for shipment of Type B quantities of Cs-137 QEORGE, J. D. Navy, Dept of, Pearl Harbor Naval Shipyard B4/01/12 GORDON, L. NRC No Detailed Affiliation Given ip, 22263, 344.
- B40Bi406i3 Forwards GA program approval for radjoactive matl package Gi33 Rev 2 MACDDNALD, G. E. MCKANAMAN, V. L. Navy, Dept. of, Pearl Harbor Naval Shipyard. ip.
- --8402140615 GA program approval for radioactive mat1 package 0133, Rev 2 HACDONALD, C. E. Transportation Certification Branch 84/02/08 1p 22258:142.
- B402240310 Advises that certification must be obtained from supplier of DOT Spec 20WC-4 overpack confirming that package was designed, constructed, maintained & repaired in accordance w/GA program approved by NRC.

 MACDONALD, C. E., Transportation Certification Branch 84/02/15

 MCMANAMAN, V. Navy, Dept of 1p 22380 150

DOCKET 71-0385 NAVY, DEPT OF

- B402010127 Forwards GA program approval for Radioactive Matl Package G385.Rev 2 MACDONALD, C. E. Transportation Certification Branch 84/01/24 MCMANAHAN, V. L. Navy, Dept of. 1p. 22048, 312.
- --8402010128 GA program approval for Radioactive Matl Package 0385,Rev 2. MACDONALD.C.E. Transportation Certification Branch. 84/01/24 ip. 22048,3ig
- DOCKET 71-0451 CHERNE CONTRACTING CORP.
- 8402140531 Forwards Rev 2 to GA program for transportation of radioactive matts.

 CORBEBIA.D.M Cherne Contracting Corp. 84/01/12 MACDONALD.C E Transportation Certification Branch 1p. 22258, 123
- --8402140535 Rev 2 to GA program for transportation of radioactive matls # Charms Contracting Corp 84/01/09. 4pp 22258 124.

- 8402130275 Forwards GA program approval for radioactive mat1 package O451.Rev 2 MACDDNALD.C E Transportation Certification Branch 64/02/01 CORBESIA.D M Cherne Contracting Corp 1p 22237 155
- --B402130302 GA program approval for radioactive mat1 package 0451.Rev 2 MACDONALD.C E Transportation Cortification Branch 84/02/01 1p 22237 156

DOCKET 71-0512 NUCLEAR ENERGY SERVICES

- 8402090575 Forwards Rev 7 to GA Manual 80A7002 MAYJ R Nuclear Energy Service, Inc 84/01/18 MACDONALD, C E Transportation Certification Branch 1p 22191 177
- --8402070581 Rev 7 to GA manual QALL, W B , ALLING, M E , MANION, W J Nuclear Energy Service, Inc 83/12/05 84pp 22171 180

DOCKET 71-0513 EDIOW INTERNATIONAL CO

- 8402140604 Forwards description of QA requirements for shipping & receiving radigactive matl per 10CFR71 51
 PODHURST.B W Edlow International Co 84/01/31 Office of Nuclear Material Safety & Safaguards.Director 1p 2225:353
- --8402140607 "EI Natural U Storage Facility," 10CFR71 QA program * Edlow International Co 84/01/31 3pp. 22253,354
- 8402140514 Forwards GA program approval for radioactive matl package OB13.Rev O MACDONALD, C E. Transportation Cortification Branch 84/02/06 PODHURST. B W Edlow International Co ip 22251 358
- --8402140519 0A program approval for radioactive matt package 0513, Rev O. MACDONALD, C. E Transportation Certification Branch 84/02/06 ip 22251 359

DOCKET 71-4909 MODEL GE-21PF-1, GENERAL ELECTRIC CO

- B402070429 Forwards comments on DOE B30512 ltr to DOT re proposed mods to DOT Spec 21PF-1 U hexaflubride overpacks to address water intestage for current & modified overpacks MACDDNALD, C E Transportation Certification Branch B4/01/27 RAWL, R Transportation, Dept of 3pp 22142 097
- DOCKET 71-4949 MODEL: UNC-1484. UNITED NUCLEAR CORP
- B402010495 Grants GE request to build add1 boT Spec 308 U hexafluoride cylinders to 1982 ANSI Std Ni4 1 rather than 1971 ANSI Std Ni4 1 Ni4 1 ANSI Btd Ni4 1 ANSI Btd Ni4 1 ANSI Btd Ni4 1 ANSI Btd Ni4 1 RAMLIR R. Transportation Certification Branch 84/01/24 RAMLIR R. Transportation Dept of 5pp 22061,299
- DOCKET 71-5026 MODEL: CNS 14-190, CHEM-NUCLEAR BYSTEMS, INC
- 8402070576 Application for amend to SAR for Certificate of Compliance 5026 for use of CNB 14-190 shipping cask Amend addresses contents description & potential generation of combustible gases POPPE, L. K. Chem-Nuclear Systems, Inc 84/01/18 MACDONALD, C E Transportation Cartification Branch App. 22186 350
- ---B402090579 Rev A to "SAR for Shipment of Radioactive Matl in CNS 14-190 Cask,"

 * Chem-Nuclear Systems, Inc B4/01/31 7pp 22184:354
- B402010438 Forwards Rev 10 to Certificate of Compliance 5026 for Model CNB-14-190.
 MACDDNALD.C.E Transportation Certification Branch 84/01/24 DEAL.R Chem-Systems, Inc. 3pp 22061:284
- --8402010442 Certificate of Compliance 5026, Rev 10, for Model CNB-14-190 MACDONALD, C. E. Transportation Certification Branch 84/01/24 5pp. 22061: 287.

- DOCKET 71-9450 HODEL RCC. ~1, ~2, -3, -4, WESTINGHOUSE ELECTRIC CORP
- 8402150414 Requests placement on list of users for Model RCC OLSEN.A F Babcock & Wilcox Co 84/01/31 Office of Nuclear Material Safety & Safeguards.Director 1p 22263 346
- 8402290370 Notification of registration as user of Model RCC.in response to 840131 request MACDONALD.C E Transportation Certification Branch 84/02/17 OLSEN.A F Babcock & Wilcox Co 1p 22438 239
- DOCKET 71-5607 MODEL T-2, ENERGY, DEPT OF
- 8402150001 Requests registration of Richland Operations Ofc as user of Model T-2 BRACKEN.H W Emprgy Dept of 84/01/31 MACDONALD.C E Transportation Certification Branch 1p 22263 001
- 8402290368 Notification of registration as user of Model T-2.in response to 840131 request MACDONALD.C E Transportation Certification Branch 84/02/17 PETERSEN.J M Energy, Dept of 1p 22498 240
- DOCKET 71-5800 MODEL DRNL TRITIUM TARGET CONTAINER
- 8402270608 Responds to DDE 831122 request for IAEA Certificate of Competent Authority for ORNL tritium target assembly Fackage satisfies containment & pressure limits of IAEA requirements for Type B(U) packaging MACDDNALD.C & Transportation Certification Branch 84/02/14 RAHL.R R Transportation. Dept of 2pp 22412 361
- DOCKET 71-5957 MODEL BMI-1. BATTELLE COLUMBUS LABORATORY
- B402070337 Forwards Rev 11 to Certificate of Compliance B987 for Model BNI-1 MCCDUNALD.C E Transportation Certification Branch B4/01/31 TOY,H L Battelle Memorial Institute. Columbus Laboratories 2pp 22141 312
- --8402070340 Certificate of Compliance 5957.Rev 11, for Model BMI-1 MACDONALD.C E Transportation Certification Branch 84/01/31 8pp 22141 314
- DOCKET 71-6058 MODEL 8-3, U 8 ECOLOGY, INC
- 8402130025 Application for amend to Certificate of Compliance 6058 for Model B3 shipping cask, authorizing contents of cask 83 to be packaged in any container meeting stds for Type A package RUZICKA, W G. Union Carbide Gorp 83/11/10 MACPONALD.C E Transportation Certification Branch 2pp 22262:352
- --8402150042 Responds to B31110 application for Amend to Certificate of Compliance 6058 allowing contents of Model 8-3 cask to be packaged in any Type A container Revised application showing that package me#ts 10CFR71 requirements requested MACDUNALD.C E Transportation Certification Branch 83/11/29 RUZICKA.W 0 Union Carbide Corp 2pp 22262,355
- --8402150048 Ack receipt of 831110 application to amend Certificate of Compliance 6058 Request requires major amend to certificate Payment of addl fee requested JACKBON.0 Licente Fee Management Branch 83/12/12 RUZICKA, W. O Union Carbide Corp 3pp 22262 357
- 8402130423 Application for rev to Certificate of Compliance 6058 for Model B3 cask, authorizing contents of cask to be packaged in polyathylene high integrity container & describing requirements for waste mati inside container RVICKA. W. 9. Union Carbide Corp 83/12/21. MACDONALD. C. E Transportation Certification Branch 18pp 22216 144.
- SOCKET 71-6206 HODEL B. BABCOCK & WILCOX CO
- 34D2100425 Forwards Rev 6 to Certificate of Compliance 6206 for Madel B MACCDNALD,C E Transportation Certification Branch, 84/02/06, ZEFF,D W Babcock & Wilcox Co 2pp. 22212/322

- ---8402100427 Certificate of Compliance 6206, Rev O6, for Model B MACDONALD, C E Transportation Certification Branch 84/02/06 3pp 22212 324
- DOCKET 71-6987 MODEL 60. BATTELLE MEM INST . PACIFIC NORTHWEST LAS
- B402i70178 Forwards Rev 9 to Certificate of Compliance 6387 for Model 60 MACDUNALD,C E. Transportation Certification Branch B4/02/09, RICHMOND,W D. Battelle Memorial Institute: Pacific Northwest Laboratory 2pp 22313 240
- --8402170205 Certificate of Compliance 6387, Rev 9, for Model 60 MACDDNALD, C E Transportation Certification Branch 84/02/09 ip 22313 262
- BOCKET 71-6574 MODEL HN-200, HITTMAN NUCLEAR & DEVELOPMENT CORP.
- 8402140609 Requests registration as user of Hittman Nuclear & Development Corp HN 200 radioactive matls shipping cask.
 KANGLEY, J P Northeast Nuclear Energy Co (subs of Northeast Utilities) 8401/30 Office of Nuclear Material Bafety & Safeguards, Director 1p 22256 334.
- 8402290355 Notification of registration as user of Model HN-200, in response to 840130 request MACDONALD, C E Transportation Certification Branch 84/02/21 CHEATHAM, A G Northeast Nuclear Energy Co (subs of Northeast Utilities) 1p 22438 258
- DOCHET 71-6601 MODEL CNB 8-120, CHEM-NUCLEAR BYSTEMS, INC.
- B402090442 Application to amend Certificate of Compliance 4601, for Model CNS 8-120 SAR for shipment of radioactive matl In CNS 8-120 cask encl POPPEL K Chem-Nuclear Bystems, Inc 84/01/18 MACDONALD.C.E Transportation Certification Branch Spp. 22177 319.
- --8402090444 Rev A to "SAR for Shipment of Redioactive Natl in CN9 8-129 Cask" * Chem-Nuclear Systems, Inc. 84/01/31, 8pp. 22177:322
- B402010070 Forwards Rev 13 to Cartificate of Compliance &601 for Model CNS 8-120 MACDONALD, C.E. Transportation Certification Branch DEAL, R. Chem-Nuclear Systems, Inc. 4pp. 22048.350
- ---B402010074 Certificate of Compliance 6601.Rev 13 for Hodel CNS 8-120 MACDUNALD.C.E Transportation Certification Branch. 84/01/24 5pp 22048:354
- 8402280573 Application for one-time variance from current limit of 20 thermal watts to 25 thermal watts for Certificate of Compilance 6501, Rev 12 MRGCZKA.E J Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MRGCZKA.E J Northeast Utilities 84/02/09 MCDONALD.C E Transportation Certification Branch. 3pp. 22416.355
- 8402150532 Forwards Rev 14 to Certificate of Compliance 6601 for Model CNB 8-120 MACDONALD.C.E Transportation Certification Branch. 84/02/10. CHEATHAM.A G Northeast Nuclear Energy Co (subs. of Northeast Utilities). 4pp. 22263.266.
- --8402150539 Certificate of Compliance 6601, Rev 14, for Model CNS 8-120 MACDONALD, C E Transportation Certification Branch. 84/02/10 App 22263 270.
- DOCKET 71-6679 MODEL: 6679, U S ECOLOGY, INC.
- BA02160507 Forwards Rev 7 to Certificate of Compliance 6679 for Model 6679 MACDONALD.C E Transportation Certification Branch. 84/02/07. BAUER,R E. U 8 Ecology, Inc. (formerly Nuclear Engineering. Inc.) 2pp 22302 064
- --8402160515 Certificate of Compliance 6679, Rev 7, for Model 6679. MACDONALD.C E. Transportation Certification Branch. 84/02/07 7pp 22302:066.

DOCKET 71-4717 MODEL 6717-B, GAMMA INDUSTRIES

8402010114 Notification of registration as user of Model 6717-8 in response to 840111 request MACDONALD.C E Transportation Transportation Certification Branch 84/01/18 Johnson Controls: Inc ip 22058 027

DOCKET 71-9001 MODEL IF-300, GENERAL ELECTRIC CO

8402070535 Application for amend to Certificate of Compliance 9001 to use IF-300 shipping cask for packaging solid nonfissile irradiated hardware for shipment DAHSON, D M Qeneral Electric Co 84/01/17 MACDONALD, C E Transportation Certification Branch 5pp 22141 200

DOCKET 71-9009 MODEL FL 10-1, GENERAL ELECTRIC CO

8402170522 Ack receipt of 840217 consolidated application for renewal of Certificate of Compliance 9009. Fee returned Addl fee not raquired.
JACKSON, 9 License Fee Management Branch 84/02/07 VAUGHAN, C M
General Electric Co ip 22313:018

--B402170525 Forwards consolidated application for renewal of Cartificate of Compliance 9007 for Model FL10-i shipping package, per NRC 830922 request Fee encl VAUGHAN, C M, General Electric Go 84/01/27 MACDONALD, C E Transportation Certification Branch 3pp 22313.019

--8402170327 Consolidated application for renewal of Certificate of Compliance 9007 for Model FLIO-1 shipping containse W/two oversite drawings. Aperture cards are available in PDR + General Electric Co. 84/01/27 200pp. 22313 021

DOCKET 71-9032 MODEL: 650, TECHNICAL OPERATIONS, INC.

B402090440 Requests registration as user of Models 660-UBA 9033/B & 650-UBA 9032/B.
FINGH.P.T Navy. Dept. of. 83/12/21 MACDDNALD.C.E SDU-UDA 7032/8.
FINCH.P.T Navy, Dept. of. 83/12/21 MACDONALD.C.E Transportation Certification Branch. 1p 22177'318

DOCKET 71-9033 MODEL: 660 & 660E, TECHNICAL OPERATIONS, INC.

8402090440 Requests registration as user of Models 660-UBA 9033/B & 650-UBA 9032/B, FINCH.P.T. Navu, Dept. of, 83/12/21. MACDONALD, C.E. 450-USA 9032/8, FINCH,P.T. Navy, Dept. of. 83/12/21. MACDONALD,∂E. Transportation Certification Branch 1p. 22177.318

DOCKET 71-9071 MODEL: AP-101, ANEFCO: INC.

B4D2070523 Forwards add1 info re amend to Certificate of Compliance 9071 for Model AP-101 shipping container MURPHY, J. D. Amefco, Inc. 84/01/17, ODEQARDEN, R. Transportation Certification Branch. 12pp, 22141-210.

DUCKET 71-9080 MODEL: HN-400, NUPAC 7-100 & CNS 7-100, HITTMAN NUCLEAR

8402140618 Application for Revs 5 & 8 to Certificates of Compliance 9089 & 9080.respectively, requesting 90 days to review acceptable leak testing methods & perform tests on packages DIMMICK, D. M. Hittman Nuclear & Development Corp. (subs. of Hittman Corp.). 83/12/06. MACDONALD, C. Transportation Cartification Branch. 2pp. 22858-134. of Hittman

--B402140621 Forwards fee for processing B31206 request for amends to Certifficates of Compliance 7089 & 7080.

DIMMICK.D M. Hittman Nuclear & Development Corp (subs of Hittma Corg) B3/01/04. McCDONALD.C Transportation Certification Branch. 1p. 22258:136

requested.

JACKSON.9 License Fee Management Branch. 89/12/23. DIMMICK.D M
Hittman Nuclear & Development Corp. (subs of Hittman Corp.).

2pp. 22258: 137.

8402140510 Summary of 840202 meeting w/Westinghouse & Hittman Nuclear-Inc in Silver Spring MD re leak testing of Type A packages UDEGAARDEN.R H Transportation Certification Branch 84/02/06 Transportation Certification Branch 2pp 22251 337

DOCKET 71-9089 MODEL HN-1008, HITTMAN NUCLEAR & DEVELOP CORP.

8402140618 Application for Revs 5 & 8 to Certificates of Compliance 9089 & 9080, respectively, requesting 90 days to review acceptable leak testing methods & perform tests on packages DMMICK, D M Hittman Nuclear & Development Corp (subs of Hittman Corp) 89/12/06 MACDONALD, C Transportation Certification Branch 2pp 22258 134

~~8402140621 Forwards fee for processing 831206 request for amends to Cortificates of Compliance 9089 & 9080
DIMMICK.D M Hittman Nuclear & Development Corp (subs of Hittman Corp) 83/01/04 MACDONALD.C Transportation Certification Branch 1p 22258 136

--8402140423 Ack receipt of 831205 request for amends to Certificates of Compliance 9080 & 9089 Addl administrative amend fee requested JACK80N.0 License Fee Management Branch 83/12/23 DIMMICK.D M Hittman Nuclear & Development Corp (subs of Hittman Corp) 2pp. 22258 137

840R1405i0 Summary of 840202 meeting w/Westinghouse & Hittman Nuclear, Inc in Silver Spring.MD re leak testing of Type A packages ODEGAARDEN.R H Transportation Certification Branch 84/02/06 Transportation Certification Branch 2pp 22251 357

DOCKET 71-9103 MODEL NLI-6502, MUCLEAR ASSURANCE CORP.

8402060012 Further response to FOIA request for three categories of documents Forwards App A documents FELTON, J. M. Division of Rules and Records 83/10/31 PUNTENNEY, J. Safe Energy Comlition 4pp 22091 250

--8402060041 Safety evaluation supporting Model NLI-6502 cask for shipment of fuel from AECL NRX & NRU Canadian reactors # Transportation Certification Branch 83/10/31 4pp. 22091 285

DUCKET 71-9107 MODEL 771, TECHNICAL OPERATIONS, INC.

B402030093 Notification of registration as user of Models 771 & 770 in response to 840103 request.
MACDONALD,C E Transportation Certification Branch 84/01/11
KRUZICR W Chicago Bridge & Iron Co ip 22091.013

DOCKET 71-9108 MODEL CNS 6-75, CHEM-NUCLEAR SYSTEMS, INC.

8402280663 Forwards revised drawings of CNS Cask 6-75 for Certificate of Compliance 9108 Revs correct errors in 831028 ltr POPPE, L K Chem-Nuclear Systems. Inc 64/01/27. McCDONALD, C E Transportation Certification Branch 5pp 22429.060

DOCKET 71-9143 MODEL, 920, TECHNICAL OPERATIONS, INC.

8402010117 Notification of registration as user of Modal 920 in response to 840106 request. MACDDNALD.C.E Transportation Certification Branch 84/01/17 RICHARDSON.C.A ABC Testing 1p. 22048 319

DOCKET 71-9148 MODEL 770, TECHNICAL OPERATIONS, INC.

8402030075 Natification of registration as user of Models 771 & 770 in response to 840103 request.
MACDUNALD, C. E. Transportation Certification Branch 84/01/11 KRUZIG, R W Chicago Bridge & Iron Co ip 22091:013.

DOCKET 71-9151 MODEL, HN-100, SERIES 3, HITTMAN NUCLEAR & DEV CORP

8402130424 Requests registration as user of Model NUB-14-170, Beries 1 shipping cask
MURPHY, H. P. Vermont Yankes Nuclear Power Corp. 84/01/19.
Transportation Gertification Branch 1p. 22216-142.

8402020040 Notification of registration as user of Hodels HN-100 Beries 3.CNS 14-170 III & NUS 14-170 I.in response to 831213 request MACDONALD.C E Transportation Cartification Branch 84/01/20

Toledo Edison Ca Ip 22062 305

DOCKET 71-9156 MODEL IR-SO, INDUSTRIAL NUCLEAR CO

8402130242 Forwards request for add1 info re 840116 application requesting amend to Model IR-50 packaging Date info will be provided requested within 30 days of 1tr receipt MACDDNALD.C E Transportation Certification Branch GATNES, T.M. Industrial Nuclear Co 2pp

DOCKET 71-9140 MODEL 20-VS & 40-VS, GULF NUCLEAR, INC.

B402090414 Forwards Rev 2 to application for Type B certification for 20-vs & 40-vs radiography camera W/o encl BEVILL.M Gulf Nuclear, Inc B4/01/21 MACDDNALD.C E Transportation Certification Branch ip 22188 358

DOCKET 71-9161 MODEL R. GULF NUCLEAR, INC.

8402150052 Application for Rev 2 to Certificate of Compliance 9161, authorizing Type B certification for Model R overpack for use in transporting radiography equipment BEVILLAM Ouif Nuclear, Inc. B 4/01/21 MACDONALD,C E Transportation Certification Branch 1p 22262 342

DUCKET 71-9148 MODEL: CNS 8-1208, CHEM-NUCLEAR SYSTEMS, INC.

8402280679 Forwards responses to 830210 questions re Model CNB 8-1208 shipping package W/o revised pages to SAR POPPE,L K Chem-Nuclear Systems, Inc 84/02/08 MACD&NALD,C E Transportation Certification Branch 9pp 22429 007

DOCKET 71-9175 MODEL CN96-808, NUCLEAR PACKAGING, INC

8402070510 Informs that addl info requested re CNBI 4-80B packaging will be provided by 840731
TENUS.C J. Pacific Nuclear Systems & Services. Inc. 84/01/19
MACDDNALD.C E. Transportation Certification Branch ip 22141: 22141 993

DOCKET 71-9181 MODEL PAS-2, NUCLEAR PACKAGING, INC.

8402140597 Notifies that info requested in 831123 ltr re Model PAS-2 will be provided by 840221 IEMUS.C J Nuclear Packaging, Inc. 84/01/27 MACDONALD.C E Transportation Certification Branch 2pp 22302:050

DUCKET 71-9184 MODEL. PAS-1, NUCLEAR PACKAGING, INC.

8402:40597 Notifies that info requested in 83:229 ltr rs Model PAS-1 will be be provided by 840228. TEMUS.C J Nuclear Packaging. Inc. 84/01/27 MACDQNALD.C & Transportation Cartification Branch 1p 22256 318

DOCKET 71-9186 MODEL. S-6213, ENERGY, DEPT OF

B402090865 Submits proprietary & nonproprietary version of "SAR for Model NUPAC XU-30" Application fee & affidavit for withholding proprietary version per iOCFR2, 790 encl W/o proprietary version SIMCHUK, J. D. Nuclear Packaging, Inc. 84/01/13 MACDONALD, C E Transportation Certification Branch 3pp 22186 001

~-B40207037B Forwards affidavit requesting withholding proprietary version of "BAR for Model NUPAC XU-30," per 10CFR2, 770
SIMCHUK.J D. Nuclear Packaging. Inc. B4/01/13 MACDONALD.C.E
Transgortation Cartification Branch. 3pp. 22186 004 MACDONALD, C. E.

--8402090584 "SAR for Model NUPAC XU-30," application for certificate af compliance, * Nuclear Packaging, Inc. 84/01/19 70pp 22184,011

B402130247 Forwards proprietary section of B40113 application for cartificate of compliance for Model UX-30 U hexafluorids packaging M/o and MACDONALD, C E Transportation Certification Branch 84/02/01 SIMCHUK. J D Nuclear Packaging, Inc ip 22215 362

DOCKET 71-9187 MODEL 865, TECHNICAL OPERATIONS, INC.

8402140619 Application for certificate of compliance for radioactive matls package Model 865 Type B(U) package-radiographic exposure device SAR & check encl MUNROLJ. T Technical Operations, Inc 83/12/27 MACDDNALD, C E Transportation Certification Branch 2pp 22253 176

--8402140622 Rev 0 to "BAR Tech/Ops, Inc Model 865 Type 8(U) Package US. 4 Technical Operations, Inc 83/11/17. 120pp 22253:178

LICENSING OF INDEPENDENT SPENT FUEL STORAGE

DOCKET 72-0001 MORRIS OPERATIONS, GENERAL ELECTRIC CO.

840213043i Discusses schedule for shipments of irradiated PMR nuclear fuel from Morris,IL to Two Rivers,WI Safeguards info withheld (ref 100FR73 21) * General Electric Co 84/01/11 HILLMAN,C R. Office of Nuclear Material Safety & Safeguards,Director 1p 22216 139

840R160610 Submits ninth notification re series of 109 shipments of irradiated PWR nuclear fuel from Morris, IL to Wisconsin Electric Power Co in Two Rivers, WI Shipments scheduled at rate of three per wk Encl withheld (ref 10CFR73 21) # General Electric Co 84/02/02 HILLMAN, C, R Division of Safeguards 1p 22302 029

8402270136 "Annual Rept of Radionuclides Released to Environ in Airborne & Waterborne Effluents, 1983 " EGER.K. J. General Electric Co 84/02/15 2pp 22391:195.

LOCER COMMISSION MEETING RECORDS

- 8402030039 Btaff requirements memo re 840116 discussion on corrosion in PORVs & corrective action Commission awaits NRC rept an need for PORVs in C-E plants & requests early estimate of rept availability.

 CHILK. S. J. Office of the Secretary of the Commission M840116A 84/01/17. DIRCKS, W. J. Office of the Executive Director for Operations ip 22091 091 24X Fiche 50-289.84/01/17,8402030039
- 8402030042 Transcript of 840123 Commission affirmation/discussion & vote in Washington DC re SECY-84-1 Pp 1-5. W/supporting documentation
- B402030031 Staff requirements memo re 840123 discussion of pending investigations re treatment of allegations & concerns about design, const & operation of plant GHILM, 8, J. Office of the Secretary of the Commission, M8401238 84/01/26, DIRCKS, W J. Office of the Executive Director for Operations, HAVES, 8 B. Office of Investigation ip 22091 080 24X Fiche 50-275,84/01/26,8402030051.
- 84020303BB Transcript of Commission 840123 discussion in Washington,DC Pp 1-61 EUpporting documentation encl.
 # Commissioners 84/01/23 66pp. 82090 126 24x
 Fiche: 50-275,84/01/23,84020303BB.
- B402030527 Btaff requirements memo re 840111 oral presentations on NRC concurrence/nonconcurrence in DOE waste repository siting guidelines. DOE agreed to provide into on foreign country actions re waste repositories CHILK.B J Office of the Secretary of the Commission. MB40111. B4/01/23. DIRCKB, W J Office of the Executive Director for Operations 3pp. 22082 224
- 8402060089 Staff requirements memo re 840112 affirmation/discussion & vote on final rulemaking 10CFR1 & prophsed order denying Joint Intervenors 831031 request for stay of fuel loading & precriticality testing at facility CHILK, S. J. Office of the Secretary of the Commission M8401128 E4/01/23. MAYES, B. B. Office of Investigation PLAINE, H. E. Office of the General Counsel 2pp 22110,059 24X Fiche: 50-279,84/01/23. B402060089.
- B4020604B1 Staff requirements memo re B40127 comments on implications of proposed rule re use of highly enriched U in domestic research reactors.List of presenters submitted CHILK, B.J. Office of the Berretary of the Commission. HB40127B B4/01/31 Office of the Secretary of the Commission. 1p DD110.00A
- 8402080232 Provides status of Commission paper on PORVs in C-E plants; per 840116 briefing on corrosion in PORVs at TMI-1 Final rept will be sent to Commission by 840305.

 DIRCKS:W J. Office of the Executive Director for Operations.
 84/01/31. CHILK:S J. Office of the Secretary of the Commission.
 3pp. 22169'005. 24X Fiche: 30-289,84/01/31,8402080232.
- 8402086490 Transcript of Commission 840126 affirmation/discussion & vote in Washington. DC re BECY-83-406 & 83-406A on review of ALAB-729 & ALAB-744 Pp 1-3, * Commissioners 84/01/26 7pp 22174.056,
- 8402090026 Responds to appeal re denial of FOIA request for transcripts of NRC meetings held between S10821 & 830510 concerning restart at TMI-1 Forwards portions of Transcript 15. CHILK.B.J. Office of the Secretary of the Commission. 83/12/20, YAHNER, A.C. Kohn, Milstein, Cohen & Hausfeld. 3pp. 22189:282

- --8402090050 Transcript of Commission 830415 discussion in Washington DC restart TMI-1 Pp 1-14 Portions deleted w Commissioners, 83/04/15 17pp 22189 285 24X Fiche 50-000,83/12/20,8402090026
- 84020900B5 Transcript of 840127 public hearing in Washington.DC re possible vote on memo on future steps in restart Pp 1-18 Supporting documentation encl * Commissioners 8401/27 33pp 22189 145 24X Fiche 50-289.84/01/27,8402090085
- 8402090112 Transcript of 840127 open meeting in Washington, DC re implications of proposed rule on use of highly enriched U in domestic research reactors Pp 1-40 Supporting documentation Commissioners 84/01/27 79pp 22189 001
- 8402100191 Commission determination statement releasing encl portions of 831208 closed meeting transcript re strategies for potential litigation on facility steam generators Deleted portions withheld (ref 100FR9 10B(a)(10)) CHILK, B. J. Defice of the Secretary of the Commission 84/02/03 Public Document Branch 1p 22205 120 24X Fishe 50-289,84/02/03,8402100191
- -9402100195 Transcript of 831208 closed meeting in Washington, DC re strategies for potential litigation on TMT-1 steam generators Pp 1-62 Portions deleted (ref 100FR9 108(a)(10)) * Commissioners 83/12/08 64pp 22205 121 24X Fiche 50-289, 84/02/03, 8402100191
- 8402100377 Transcipt of Commission 840202 affirmation/discussion & vote in Washington. DC re 8ECY-83-286, concerning 10CFR51 & related forming amends pp 1-8
 * Commissioners 84/02/02 iipp 22207 301
- 8402100388 Transcript of Commission 840202 briefing in Washington.DC re quarterly progress on safety goal evaluation rept & draft PRA document Pp 1-70 Supporting documentation enci
 * Commissioners 64/02/02 107pp 22211.001
- B402130007 Responds to appeal re denial of FOIA request for documents concerning investigation of allegations at facility. Forwards App A documents Documents completely & partially withheld (ref FOIA Exemptions 7 & 4) CHILK, B J Office of the Secretary of the Commission B3/11/10 BERNABEI, L Government Accountability Project. 44pp. 22238.100
- --B402130211 Staff requirements memo re B30315 discussion/possible vote on contested issues in Palo Varde full power proceeding HAYES, B B Office of Investigation B3/03/25 CHILK, B J Office of the Secretary of the Commission 2pp. 22240 128
- --B402130270 Transcript of closed Commission 930315 meeting in Washington DC re discussion/possible vote on contested issues in full power proceeding Pp 1-57. Partions deleted # Commissioners 83/03/15 32pp. 22240 331
- 8402130144 Transcript of 840203 periodic meeting w/Advisory Panel for Decontamination of TMT-2 in Washington.DC Pp 1-47 * Commissioners. 84/02/03 5ipp. 22237·165 24X Fiche 30-320,84/02/03.8402130144
- 8402:30537 Staff requirements mamp re 840:27 open briefing on intl implications of conversion of domestic research reactors to low level enriched U use No meeting requirements imposed. CHILK, S J Office of the Secretary of the Commission. M840:27D 84/01/31 Office of the Secretary of the Commission ip. 222:3 355
- 8402130575 Transcript of Commission 840206 discussion of low enriched U/high enriched U guidence in Washington, DC Pp 1-33 * Commissioners 84/02/06, 36pp 22214, 248,

- 8402150464 Transcript of Commission 840127 public meeting in Washington DC re discussion of intl implications of conversion of domestic research reactors to low enriched U use Pp 1-28 # Commissioners 84/01/27 3ipp 22263 213
- 8402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CMILKS J Office of the Secretary of the Commission 83/12/14 Public Document Branch 1p 22281 023 24X Fiche 50-000,83/12/14. B402160003
- --BA02160007 Staff requirements memo re B30105 discussion/possible vote on order in facility proceeding in Washington.DC CHILK, B J Office of the Secretary of the Commission MB30105B B3/01/07 Office of the Secretary of the Commission ip 22281 049 24% Fiche 60-000,B3/12/14,B402160003
- ~~8402160008 Staff requirements memo re 830203 discussion of proposed enforcement action in Washington.DC CHILK.S J Office of the Secretary of the Commission M830203 83702/16 Office of the Secretary of the Commission ip 22281 050 24X Fiche 50~000.83/12/14.8402160002
- --8402160012 Staff requirements memo re 830304 discussion/possible vote on contested issues in facility full power proceeding in Washington.DC CHILK.8 J Diffice of the Secretary of the Commission M830304B 83/03/08 ZERBE.JE Office of Policy Evaluations ip 22281 051 24X Fiche 30-000,83/12/14.8402160003
- --B402160015 Staff requirements memo re B30304 discussion/possible vote on ALAB-714 & ALAB-716 in Heshington DC CHILK.S J Office of the Becretary of the Commission. ALAB-714 B3/03/09 Office of the Secretary of the Commission ip 22281 052 24% Fiche 50-000/83/12/14/8402160003
- --8402160019 Staff requirements memo re 830405 briefing in Washington DC approving memorandum & order on emergency plan CHILK, 3 Defice of the Secretary of the Commission M830405A 83/04/08 PLAINE, HT Office of the General Counsel 1p 22281 054 24X Fiche 50-000,83/12/14,8402160003
- --8402160022 Staff requirements memo re B30411 discussion/possible vote on BECY-83-119, proposed response to UCS petition for rulemaking on emergency planning, in Washington, DC CHILK, B.J. Office of the Secretary of the Commission M830411 B3/04/11 PLAINE, H.H. Dffice of the Ceneral Counsel. ip 22281 055 24X Ficher 50-000, B3/12/14, B402160003.
- --8402160025 Staff requirements memo re 830415 discussion of facility order in Washington, DC.
 CHILK/S U Office of the Secretary of the Commission M830415A 83/04/15 Office of the Secretary of the Commission Ip. 22281 056 24X Fiche.50-000,83/12/14,8402160003.
- --B402160030 Staff requirements memo re 830422 discussion & possible vote in Washington, DC on immediate effectiveness of LWA-1 CHILK, S J Office of the Becretary of the Commission MB30422A 83704726 ZERBE, J E Office of Policy Evaluations. ip 22281 057 24X Ficher 50-000, B3/12/14, B402160003
- --R402160033 Staff requirements memo re 830504 discussion of possible enforcement action in Washington.DC
 CHILK.8 J Office of the Secretary of the Commission M830504B 83705706 DERCHS,W J. Office of the Executive Director for Operations ip 22281 050 24X Fiche 50-000.83/12/14,8402160003
- --8402160035 Staff requirements memo re 830511 review of NFB-Erwin settlement in Washington.DC.

 GHILK.S.J. Diffice of the Secretary of the Commission. M830511 83705712. PLAINE.H H. Diffice of the Seneral Counsel ip 22281 059 24X Fiche: 50-000.83/12/14.8402160003
- --8402160037 Staff requirements memo re 810716 discussion of draft itr to Senator Hatfield Cheirman Subcommittee on Energy & Water Development in Washington, DC CHILK S J Office of the Secretary of the Commission. M810716 81/07/20 Office of the Secretary of the Commission. 1p 22281:024 24X Fiche 50-000.83/12/14,8402160003
- --B402160041 Staff requirements memo re 810727 budget session (markup) in Washington, DC CHILK B J Office of the Secretary of the Commission MB10727, B1/08/03 DIRCKS, W J Office of the Executive Director for Operations ip. 22281 025, 24X Fiche 50-000, 83/12/14, 8402160003
- -8402160043 Staff requirements mamo re B30610 discussion & vote on facility order in Washington, DC CHILK.8 J Office of the Becretary of the Commission. MB30610B B3/06/14 PLAINE, H H Office of the General Counsel ip B2281 060. 24X Fiche: 50-000,83/12/14,8402160003.

- --8402160047 Staff requirements memo re 830707 discussion of preceives for facility review in Washington, DC CHILK, B J Office of the Secretary of the Commission MS307078 83/07/08 FLAINE, H H Office of the General Counsel ZEMBE, J I Office of Policy Evaluations ip 22281 061 24% Fichs 80-000, 83/12/14, 8402160003
- --8402160050 Staff requirements memo re 810811 discussion of enforcismi action implementation of plant early notification sys in Washington.DC MOVLE.J C Defice of the Secretary of the Commission 81/08/14 DIRCKS.W J Office of the Executive Director for Operations 1p 22281 026 24X Fiche 30-000.83/12/14.8402160003
- --8402160065 Staff requirements memo re 830715 discussion of possible enforcement action in Washington, DC CHILK.8 J Office of the Becretary of the Commission M8307158 83/07/25 Office of the Becretary of the Commission ip 22281 062 24X Fiche 50-000.83/12/14.8402160003
- --B402160066 Staff requirements memo re 820415 Affirmation Session 82-12 CHILK, 8 J Office of the Secretary of the Commission ALAB-65J 82/04/22 BICKWIT, Office of the General Counsel 3pp. 2281 063 24X Fiche 50-000.83/12/14.8402160003.
- --8402160067 Staff requirements memo re 810819 briefing on enforcement actions in Washington, DC CMILK: 3 J Office of the Secretary of the Commission 81/08/31 DIRCKG, W J Office of the Executive Director for Operations CUMMINGS, J J Office of Inspector & Auditor 1p 22291-027, 241 Fishe 50-000, 83/12/14, 8402160003
- --B402160070 Staff requirements memo re 810825 briefing on pending adjudicatory proceedings in Washington, DC
 CHILK.B J Office of the Secretary of the Commission MB10825
 B1707/01 B1CKWIT.L Office of the General Counsel ip.
 22281 028 Z4X Fiche 50-000,83/12/14,8402160003
- --B402160072 Staff requirements memo re 810910 discussion of low power OL in Washington.DC
 CHILKS J Office of the Secretary of the Commission B1/09/16 BICKWIT.L Office of the Ceneral Coursel. ip. 22281:027 24X Fishe 50-000,83/12/14,8402160003
- --B402160076 Btaff requirements memo re B11102 discussion of pending litigation in Washington,DC CHILK:S J Office of the Secretary of the Commission. HB11102A B1/11/03 Office of the Secretary of the Commission ip. 22281 030 24X Fichs 50-000.B3/12/14.B402160003
- --8402160079 Staff requirements memo re BillO6 discussion of TMT-1 restart in Washington.DC CHILK.S J Office of the Secretary of the Commission BI/11/09. BIGKMIT. Dffice of the Operal Counsel ip. 22281 031 24X Fiche 50-000.83/12/14.8402160003
- --84021600B1 Staff requirements memo re 811106 discussion of U mll1 tailings in Washington. DC CHILK.B J. Office of the Becretary of the Commission M8111063 81/11/07 DIRCKB.W J. Office of the Executive Director for Operations ip 22281.032 24X Fiche. 50-000.83/12/14,840216003
- --B4021600B5 Btaff requirements memo re Billi6 discussion of 670518 atta & seismic reverification plan in Washington, DC CHILK.8 J Diffice of the Becretary of the Commission, Bi/11/20, Diffice of the Secretary of the Commission ip. 222B1:033 24X Fiche 50-000,83/12/14.8402160003.
- --8402160091 Staff requirements memo re 811119 continuation of discussive of Diablo Canyon order in Washington, DC
 CHILK, 8 J Office of the Secretary of the Commission M811119
 81/12/01 DIRCKS, W J Office of the Executive Director for Operations. 1p. 22281 034 E4X Fiche, 30-000, 83/12/14, 8402160001
- --B402160094 Btaff requirements memo re 811124 discussion of pending litigation in Washington.DC CHILK.B.J Office of the Secretary of the Commission. MB11124C B1/12/01 Office of the Becretary of the Commission. 1p. 22281 035 24X Fiche 50-000.B3/12/14.B402160003
- --8402160076 Staff requirements mamo re 811207 discussion of schaduling matters concerning TMI-1 restart in Washington DC.
 CHILK, S. J. Office of the Secretary of the Commission. MB11207A
 B1/12/14. BICKHIT, L. Office of the General Counsel REMICK, F.
 Office of Policy Evaluations. 1p. 22281-036. 24X
 Fiche 50-000,83/12/14.8402160003
- --B402160102 Staff requirements memo re B11222 Affirmation Session 81-41 on TMI-1 restart order in Washington, DC.
 CHILK, S. J. Office of the Secretary of the Commission. MB11222B
 B1/12/28 B1CKWIT, L. Office of the General Counsel 1p
 22281 037. 24% Fiche 50-000,83/12/14,8402160003

- --8402160107 Staff requirements memo re 820121 discussion of enforcement satters in Washington, DC
 CHILK, S J Office of the Secretary of the Commission M820121A
 82/01/25 DIRCKS, W J Dffice of the Executive Director for Operations, Ip 22281 038 24X Fiche 50-000,83/12/14,8402160003
- --B402160110 Staff requirements memo re B20205 discussion of Phase I of facility rept in Washington, DC CHILK, B J Office of the Secretary of the Commission M8202058 82/02/09 BICKHIT. Office of the General Counsel 1p 22281 039 24X Fiche 50-000, B3/12/14, B402160003
- ---B402160116 Btaff requirements memo re B20204 briefing on proposed enforcement action in Washington.DC CHILM, B J Defice of the Becretary of the Commission MB20204D B2/02/12 DIRCKB, W J Defice of the Executive Director for Operations. 22281 040 24X Fiche 50-000,83/12/14,8402140003
- --8402160120 Staff requirements memo re 820226 discussion of revised licensing procedures in Washington.DC CHILK.B J. Office of the Secretary of the Commission M8202268 82/03/04. BICKMIT.L. Office of the General Counsel TOURTELLOTTE, J. NRC No Detailed Affiliation Given 1p 22281:041. 24X Fichs.50-000.83/12/14.8402160003
- --9402160123 Btaff requirements memo re 820310 discussion of TMI-1 restart proceeding in Washington, DC
 CHILK, S J Office of the Bernstary of the Commission MI
 82/03/11. BICKWIT, L Office of the General Counsel ip
 22281:042 24X Fiche, 50-000, 83/12/14, 8402160003 MB20310B
- --8402160126 Staff requirements memo re 820324 discussion of enforcement NOZIOUIZO BEAFF requirements memo re 800324 discussion or enronce action in Washington DC CHILK.8 J Office of the Secretary of the Commission M8203248 82/03/31 Office of the Secretary of the Commission 1p 22281.043. 24
- --8402160131 Staff requirements memo re 820520 discussion of enforcement action in Mashington.DC.
 CHILK.8.J. Office of the Secretary of the Commission. 82/03/26
 BICKWIT.L. Diffice of the General Counsel. ip 22281 044. 24X
 Ficha: 50-000, 83/12/14, 8402160003
- --BACRIAGIBA Staff requirements memo re 820528 discussion of enforcement action (subpoena authority) in Hashington.DC.
 CHILK.B.J Office of the Secretary of the Commission M8205288.
 82/05/28. DIRCKS,W.J. Office of the Executive Director for Operations. 1p. 22281:045. 24X Fichs.50-000.83/12/14.8402160003
- --8402160136 Staff : wquirements memo re final QAD rept, "Nued for Better Policy & Control Over Public Info Requests (QOD-81-70)."

 CHILK.8.J. Office of the Secretary of the Commission 881-476
 81/10/02, DIRCKS, W J Office of the Executive Director for Operations 1p. 22281:107. 24X Fiche. 50-000.83/12/14.8402160003
- ---8402140140 Staff requirements memo re 820611 discussion of status of shift manning requirements in Hashington, DC.
 CHILK, B. J. Office of the Secretary of the Commission. 82/06/15, DIRCKS, M. J. Office of the Executive Director for Operations ip 22281:046. 24X Fiche: 50-000, 83/12/14, 8402160003,
- ---8402140144 Staff requirements memo re 820707 discussion & possible vote on contested issues in OL proceeding in Washington, DC. CHILK, B. J. Office of the Secretary of the Commission, M8207078, 82/07/13 BICKHIT, L. Office of the General Counsel 2pp. 22281: 047. 24X Fiche. 50-000, 83/12/14, 8402140003.
- ---8402160355 Staff requirements memo re 821112 discussion of Commission action in Washington, DC.
 CHILK, S. J. Office of the Secretary of the Commission. M821112C.
 82/11/18 DIRCKS, W. J. Office of the Executive Director for Operations. 1p. 22261:244. 24X Fiche: 50-000, 83/12/14, 8402160003
- --8402160388 Staff requirements memo discussing possible 821222 vote on actions re facility in Hashington,DC CHILK,B,J. Office of the Becretary of the Commission. M821222C. 82/12/23. Office of the Secretary of the Commission, ip. 22281:248 24X Fiche: 50-000,B3/12/14,B402160003.
- --8402160384 Staff requirements memo re 821216 discussion/possible vote on contested issues in full-power proceeding in Washington, DC. CHILK, B. J. Office of the Becretary of the Commission. M8212169. 82/12/20. ZERBE, J. E. Office of Policy Evaluations. BICKWIT, L. Office of the General Counsel. 1p. 22281 251. 24X Ficha: SO-000, 83/12/14, 8402160003
- B402170020 Transcript, of Commission B40207 meeting w/Regional Administrators in Washington, DC. Pp 1-90. * Commissioners. 84/02/07, 94pp., 22319:032.

- B402170214 Staff requirements memo re 840207 meeting w/regional administration & EDD in Washington,DC re resident insp.mgt, allegation & transportation policy statement (BECV-B3-514) CHILK,S J Office of the Secretary of the Commission M8402078 B4/02/13 Office of the Secretary of the Commission 1p 22313 257
- 8402170221 Staff requirements memo re B40202 affirmation/discussion & vots in Washington, DC approving final rules which revise 10CFR51 to implement Section 102(2) of NEPA of 1769, as amended, per BECY-G3-208 delication of the Commission MB40202B GHILK, S. J. Office of the Becretary of the Commission MB40202B B4/02/10 DIRCKB, W.J. Office of the Executive Director for Operations FOUCHARD, J.J. Office of Public Affairs KAMMERER, C. Office of Congressional Affairs 2pp 22313 255
- B402170463 Staff requirements memo re Commission 840202 briefing in Washington.DC on quarterly progress on safety goal evaluation rept & draft PRA document rep: « grart rea governent Office of the Secretary of the Commission M840202A Office of the Secretary of the Commission ip CHILK, S J 84/02/08 22305 346
- 8402170519 Transcript of Commission 840210 public meeting in Washington, DC re comments by parties on Diablo Canyon criticality & low power operation Pp 1-96 Supporting documentation encl 84/02/10 125pp 22305 201 24x Commissioners Fiche: 50-275, 84/02/10, 8402170519
- 8402210106 Staff requirements memo re Commission 840209 vote of approval for publication of revised general statement of policy & procedure for enforcement actions w/listed mods & actions
 CHILK.8 J Office of the Becretary of the Commission M840209
 84/02/14 Office of the Becretary of the Commission. Ip 22321:333
- --8402210107 Discusses revised general statement of policy & procedure for enforcement actions re SECY-83-487 GHLK,8 J Office of the Secretary of the Commission 84/02/14 DIRCKS.WJ Office of the Executive Director for Operations 2pp
- 8402210328 Forwards transcript of Advisory Panel for Decontamination of TMI-2 840203 meeting MABNIK.H T. TMI Program Office 84/02/06 Advisory Council for Decontamination of THI Unit 2. 5pp. 22344.048 24X Fiche: 50-320.84/02/06.8402210328
- --8402210469 Transcript of Commission 840203 meeting w/Advisory Panel on TMI-2 Cleanup in Washington, DC Pp 1-47 * Commissioners 84/02/03 52pp. 22344 065 24x Fiche 50-320,84/02/06,8402210328
- B402230032 Staff requirements memo re Advisory Panel on TMI-2 Cleanup B40203 meeting on cleanup allegations in Washington.DC Commission requested options for water disposal & results of scheduled meeting between EPA & Adivsory Panel CHILM.B. J Office of the Secretary of the Commission MB40203 B4/02/14. DIRCKS.W.J Office of the Executive Director for Operations 2pp. 22379.360. 24X Fiche.50-320.84/02/14.8402230032
- 8402230297 Transcript of 840209 affirmation/discussion & vote in Hashington, DC to BECY-83-487 on statement on enforcement actions. Pp 1-19, * Commissioners 84/02/09, 23pp. 22371 235
- 8402230342 Transcript of 840214 briefing in Washington, DC re BWR pipe cracks status of plants Pp 1-71. Supporting documentation Commissioners 84/02/14 81pp, 22376 321.
- 8402240248 Staff requirements memo re 840210 comments by parties on facility criticality & low power operation Commission tantatively scheduled to discuss & possibly vate on subj on Tentratively scheduled to discuss & possibly vate on subj on 840308.

 CHILK.B. J. Office of the Secretary of the Commission M840210.

 22381:277. 24% Fiche 50-275.84/02/15.840240248
- 8402270072 Final response to FOIA request for Commissioner voting & attendance records from 810404 to present Forwards documents listed on App A. Documents also available in PDR. FELTON, J. M. Division of Rules and Records 83/12/22 KAMENAR, P. D. Hashington Legal Foundation Spp 22410 109. 24X Fiche: 50-528, 83/12/22, 8402270072

- --8304040550 Advance copy of staff requirements memo ra 830313 discussion & possible vote in Hashington, DC on contested issues in full power proceeding CHILK, 8 J Office of the Secretary of the Commission. M830315A B3/03/18 DIRCKS, H J Office of the Executive Director for Operations ip 22410 146. 24X Fiche 50-528, 83/12/22, 8402270072
- --B402270216 Staff requirements memo re SECY-82-462/462A on human factors program plan
 CHILKS J Office of the Secretary of the Commission B3/0;
 DIRCKS, W Office of the Executive Director for Operations B3/02/16

ACRE ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

- 8303310317 Forwards comments on FY84-85 ACRS rept.Section 2 4 re plant instrumentation & control BABDEKAS,D L Instrumentation & Control Branch 83/03/21 WENZINGER,E C Instrumentation & Control Spanch 4pp 22205 080
- 8402010278 Comments on quantification of seismic design margins Generic solution to concerns could best be obtained by four-part program involving NRC & Industry Seismic PRAs can contribute significantly EBERSOLE.J C ACRB Advisory Committee on Reactor Safeguerds 84/01/18 PALLADING.N J Commissioners ip 22047-256
- 8402010283 Summarizes ACRS 285th meeting on 840112-14're license renewal & power increase Renewal of license at requested power level of 20 MH may be granted w/o undue risk to public health & safety EBERSOLE, J. C ACRS - Advisory Committee on Reactor Bafeguards 84/01/17 PALLADINO.N J Commissioners 4pp 22046 336 2 Fiche 50-184.84/01/17.8402010283
- 8402010284 Recommends that NRC become knowledgeable & remain current on regulatory approaches to LWR safety in foreign countries EBERSOLE; J C ACRS Advisory Committee on Reactor Safeguards 84/01/17. DIRCKS, W J Office of the Executive Director for Operations 1p. 22046 334.
- 8402090104 Transcript of ACRS Subcommittee on Regulatory Policies & Practices 840207 mseting in Washington, DC Pp 1-52.

 * ACRS Advisory Committee on Reactor Safeguards 84/02/07 52pp 22159 069
- 8402070113 Transcript of ACRS Subcommittee on Human Factors 840207 meeting in Washington, DC Pp 1-236 Supporting documentation anci: * ACRB - Advisory Committee on Reactor Safeguards 84/02/07, 34lpp 22158-088
- 8402090454 Forwards ACR8 documents for listing on accession list ROBERTS B.J. ACR8 Advisory Committee on Reactor Safeguards 84/02/01 MCKNIGHT.J NRC No Detailed Affiliation Olven 3 22192 341
- 8402090465 Submits review of Generic Technical Activity 8-10 re resolution of Mark III issue Indications exist that suggest NRC relaxing criteria relevant to piping on case-by-case basis
 BUSH, B. H. Battelle Memorial Institute, Pacific Northwest Laboratory
 BUSH, B. H. ACRE - Advisory Committee on Reactor Safeguards
 BJEHNERT, P. A. ACRE - Advisory Committee on Reactor
 Safeguards 2pp 22172 358.
- 8402090469 Submits rept on ACRS/ECCS Subcommittee 831108-09 meetings re review of inservice testing program for BAW reactors Strong re-review of inservice testing program for BAW reactors Strong oversight mechanism must be established to provide overall guidance & coordination of various program elements SCHAGCK.V E California, Univ of, Berkeley, CA BCHROCK.V E ACRE - Advisory Committee on Reactor Safeguards. B3/11/28. BOEHNERT.P.A ACRE - Advisory Committee on Reactor Safeguards. 2pp 22192 S60.
- 8402070473 Comments on ECCS Subcomittee 831108-09 meetings re MIST, plant analyzer program, codes & App K rev BCHROCK,V E California, Univ of, Berteley, CA. BCHROCK,V E. ACRS Advisory Committee on Reactor Safeguards 83/11/23 BOEHNERT ACRS Advisory Committee on Reactor Safeguards 2pp 22192 362
- 8402090480 Bubmits rept re EPRI/AIF/Metals Properties Council 83:102-04 holting seminar in Knozville: TN re stress corrosion cracking baric acid corrosion & bolting preload control H/ agenda & handouts
 QALL, W.R. Gall, W.R. GALL, W.R. ACRS - Advisory Committee on
 Reactor Bafeguards B3/11/16, IONE, E ACRS - Advisory Committee on
 Reactor Bafeguards 5pp 22196 350.

- 8402070483 Requests NRC continued support of operation of regional networks under purview Dismay expressed at NRC proposed reduction in seismographic network funding targeted for
 - 1985
 PCMERDY,P W National Research Council POMERDY,P.W ACRS —
 Advisory Committee on Reactor Safeguards 83/12/01 DKRENT.D
 Advisory Committee on Reactor Safeguards 2pp. 22194:348
- 8402090484 Summary of ACRS Reliability & Probabilistic Assessment Subcommittee 820325-26 mestings in Washington, DC re Zion probabilistic safety study # ACRS Advisory Committee on Reactor Safeguards 82/03/26 ACRS Advisory Committee on Reactor Safeguards 16pp. 22192 236, 24% Fiche 30-295,82/03/26,8402090484
- 8402070488 Notifies of inability to attend ACRS 831207 meeting. Info re 831111 review of NDE & appropriateness of "factor of two" safety margin in sizing submitted THOMPSON, R B Ames Laboratory, Energy & Mineral Resources Res Institute. THOMPSON, R B ACRS Advisory Committee on Reactor Safeguards 83/12/01 IONE, A. Q. ACRS Advisory Committee on Reactor Safeguards 7pp 22176/341
- 8402070489 Summary of ACRB Bubrommittee on Class 9 Accidents B20528 meeting in Mashington,DC re NRC severe accident research plan List of attendeess.agenda & handouts encl # ACRB Advisory Committee on Reactor Safeguards, 82/06/24 ACRB Advisory Committee on Reactor Bafeguards, 16pp 2219 22172 240
- 8402090491 Forwards trip rept of attendance at IDCOR Phenomenology 831129-1201 meetings in Harpers Ferry, MV. Agenda & IDCOR presentations also encl. CORRADINI, M Hisconsin, Univ of, Madison, HI. CORRADINI, M. Advisory Committee on Reactor Befeguards. 83/12/07. KERR, H. Hichigan, Univ of, Ann Arbor, MI. 16pp 22204 317.
- 8402070492 Proposed summary of ACRS Subcommittee on Perry 820528-29 meetings in Cleveland. DH re util DL application. Proposed schedule encl # ACRS Advisory Committee on Reactor Safeguards. 82/07/28 ACRS Advisory Committee on Reactor Safeguards 20pp. 22192. 220. 24X Fiche. 50-440, 82/07/28, 8402090492
- 8402090494 Comments on SECY-83-267C re reinsp & repair of BMR piping. Plan appears to represent reasonable compromise between thoroughness & necessity to minimize exposure of insp personnel
 SHACK.W.J Acre - Advisory
 Committee on Reactor Safeguards. 83/12/09. SHEWMON, P. Affiliation
 Not Assigned. SHEWMON, P. ACRE - Advisory Committee on Reactor
 Safeguards. 2pp. R2192 339.
- 8402070496 Summary of ACRS Class 9 Accidents Subcommittee 821221 meeting in Washington, DC to NRR research on severe accident licensing theory & severe accident research plan FR notice Attendance list & agenda encl.

 # ACRS Advisory Committee on Reactor Safeguards, 83/01/26 ACRS Advisory Committee on Reactor Safeguards, 22pp. 22192: 22192: 198.
- 8402090479 Comments on Metal Components Subcommittee 83:207 meeting re BMR pips cracks Factors contributing to intergranular stress cracking include residual stress, metal susceptibility & water chamistry, Recommendations conservative.

 GALL.M.R. Call. M.R. GALL.M.R. ACRS Advisory Committee on Reactor Safeguards. 83:72/09 IOME.E. Q. ACRS Advisory Committee on Reactor Safeguards. 20, 22:92-337.
- B402090502 Summary of ACRS Advanced Reactors Subcommittee B31214 meeting in Washington,DC re review of NRC FY85-86 LMFBR research program for ACRS rept to Congress.

 * ACRS Advisory Committee on Reactor Safeguards. 83/12/17. ACRS Advisory Committee on Reactor Safeguards. 5pp. 22192: 5pp. 22192:332
- B402070503 Summary of ACRS Class 7 Accidents Subcommittee 831012 meeting in Washington, DC re proposed NRC paper, "Severe Accident Decisions for Existing Nuclear Power Plants "FR notice, agenda & list of attendees encl.

 * ACRS Advisory Committee on Reactor Safeguards, 83/11/21.
 ACRS Advisory Committee on Reactor Safeguards 16pp. 22172:182.
- 8402090504 Comments on 831207 meeting in Charlotte, SC re NRC approach to evaluation of BWR intergranular stress corrosion related pips cracks. Existence of cracks has not altered public risk pips cracks.Existence or cracks when we will be aposure axposure service. BENDER, M. ACRS - Advisory Committee on Reactor Safeguards. B3/12/10 SHEHMON, P. ACRS - Advisory Committee on Reactor Safeguards. App. 22192: 326.
- 8402090508 Summary of ACRS ECCS Subcommittee 831108-09 meetings w/BtW re review of joint MRC/BtW/EPRI integral test program. * ACRS Advisory Committee on Reactor Safeguerds. 83/12/05 ACRS Advisory Committee on Reactor Safeguerds. 20pp 22192:162

- 8402090509 "Comments re BHR Water Chemistry " BILLON.R L Battelle Memorial Institute, Pacific Northwest Laboratory DILLON.R L ACRS - Advisory Committee on Reactor Safeguards 83/12/06 16pp 22192 310
- 8402090511 Bubmits rept on ACRB Fluid Dynamics Bubcommittee 831208 meeting. Flow-related incidents have common origin in flow induced vibration due to vortex shedding or bulk flow oscillation
 TIEN.C L. California, Univ of, Berkeley, CA. TIEN.C L. ACRB —
 Advisory Committee on Reactor Bafeguards 83/12/22 BOEHNERT,P.A.
 ACRB Advisory Committee on Reactor Safeguards 2pp 22192 308
 24% Fichs 50-335,83/12/22,8402090511
- E402090517 Submits review of proposed rev to NRC SRP Section 2 5 2, "Vibratory Ground Motion " Subsections 2 5 2 5, "Seismic Wave Transmission Characteristics of Site" & 2 5 2 6, "Safe Shutdown Earthquake" addressed.

 LUCD, J E Affiliation Not Assigned LUCD, J E ACRS ~ Advisory Committee on Reactor Safeguards 83/12/19 SAVIO.R NRC No Detailed Affiliation Given. 2pp. 22192 306
- 8402090518 Summary of ACRS Bubcommittee on Regulatory Activities 831116 meeting in Washington, DC re Reg Guide 1 105, Rev 2, "Instrument Setpoints for Safety-Related Sys "

 ACRS Advisory Committee on Reactor Safeguards. 83/11/29
 ACRS Advisory Committee on Reactor Safeguards. 11pp 22192 151
- 8402090521 Comments on ACRS subcommittee 83:208-09 meetings in San Francisco.CA re earthquakes in eastern US Geological studies grovide fundamental regional structure & stress configurations which ultimately control faulting MAXWELL.J C. Maxwell. J C MAXWELL.J C. ACRS Advisory Committee on Reactor Safeguards. 83/12/19 DKRENT.D, ACRS Advisory Committee on Reactor Safeguards. 2pp 22:192 304.
- 8402070522 Comments on proposed rev to SRP Section 2 5 2, "Vibratory Ground Motion,"

 MAXWELL, J Maxwell, J.C. MAXWELL, J ACRS Advisory Committee on Reactor Bafeguards 83/12/20 NRC No Detailed Affiliation Given ip. 22192.303
- 8402090523 Summary of ACRS Advanced Reactors Subcommittee B31116 meeting in Washington, DC re review of NRC research programs in area of advanced reactors, particularly LMFBRs ** ACRS Advisory Committee on Reactor Safeguards. 83/11/19. ACRS Advisory Committee on Reactor Safeguards. 4pp. 22192-147
- B402090527 Comments on IDCOR/NRC 831129-1201 Meeting 1 in Harpers Ferry, MV re accident phenomena & containment loading Third IDCOR meeting will be devoted to plant analysis CATTON, I. ACRS - Advisory Committee on Reactor Safeguards 83/12/20, WANO, A. ACRS - Advisory Committee on Reactor Safeguards 7pp. 22192;296.
- 8402070527 Comments on proposed rev to SRP Section 2.5 2, "Vibratory Ground Motion," Improvements substantial & generally excellent.
 THOMPSON, 0. A Stanford Univ , Stanford, CA THOMPSON, Q. A. ACRS Advisory Committee on Reactor Safeguards. 83/12/22 OKRENT, D. ACRS Advisory Committee on Reactor Safeguards. 1p. 22192-295
- 8402090332 Comments on ACRS Metal Components Subcommittee 831207
 meeting in Charlotte, SC. Leak-before-break concept &
 BECY-B3-267C addressed
 RODABAUGH, E. C. E. C. Rodabaugh Associates, Inc. RODABAUGH, E. C. ACRS
 Advisory Committee on Reactor Safeguards 83/12/10, IGNE, E. G. ACRS Advisory Committee on Reactor Safeguards 4pp. 22192-291
- B402070533 Summary of ACRS Fluid Dynamics Subcommittee 831208 meeting in Washington.DG re recent flow-related incidents resulting in equipment damage in plant primary sys * AGRS Advisory Committee on Reactor Safeguards 83/12/13 ACRS Advisory Committee on Reactor Safeguards 25pp. 22192:117. 24X Fiche: 50-000.83/12/13,8402070833.
- 8402070534 Comments on ACRS Subcommittee on Metal Components 831213 meeting in Charlotte, 8C. Turbine disk cracking, piping design & availuation & bolting integrity position addressed. GALL, N. R. Gall, W. R. GALL, W. R. ACRS Advisory Committee on Reactor Safeguards 80/12/15, IGNE, E. G. ACRS Advisory Committee on Reactor Safeguards. 1p. 22192-290.
- B402090537 Comments on draft rev to NRC SRP Section 2 5.2. Draft procedure greatly improved over old procedure. Draft encl. FAGE.B.M Stanford Univ., Stanford, CA. PAGE.B.M ACRE Advisory Committee on Reactor Safeguards.

- 8402070540 Summary of ACRS Safety Philosophy, Technology & Criteria & Class 9 Accidents Subcommittee 820203 meeting in Mashington. DC alternate approach to serve accident rulemaking proposed in SECY-82-1 ACRS Advisory Committee on Reactor Safeguards SECY-82-1 82/03/02 ACRS Advisory Committee on Reactor Safeguards 12pp 22192 272
- 8402130124 Transcript of 284th ACR8 general meeting on 840209 in Washington DC Pp 1-214 Supporting documentation encl * ACR8 Advisory Committee on Reactor Safeguards 84/02/09 2155n 22198 203
- 8402140473 Transcript of 289th ACRS general meeting on 840210 in Washington.DC Pp 215-416 Supporting documentation encl * ACRS - Advisory Committee on Reactor Safeguards 84/02/10 249pp 22226-215
- 8402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILK, S. J. Office of the Secretary of the Commission B3/12/14 Public Document Branch ip 22281 023 24% Fiche 50-000,83/12/14,8402160003
- --B402160052 Discusses SECY-B1-36B re appointment of ACRB member CHILK, S J Dffice of the Secretary of the Commission B1/09/02 FRALEY, R F ACRB Advisory Committee on Reactor Safeguards 1; 22281:091 24% Fiche 50-000,83/12/14,8402160003
- --8402160249 Discusses SECY-82-302 re appointment of ACRS members CHILK.S J Office of the Secretary of the Commission 82/09/15 FRALEY.R F ACRS Advisory Committee on Reactor Bafeguards 1: 221 24% Fiche 50-000.63/12/14.8402160003
- --8402160345 Discusses SECY-83-73 re reappointment of ACR8 member CHILK, B J Office of the Secretary of the Commission, 83/03/30 FRALEY.R F ACR8 Advisory Committee on Reactor Safeguards 1p 22281 277 24% Fiche, 50-000, 83/12/14, 8402160003
- --8402160443 Discusses BECY-82-109 re forthcoming vacancy on ACR8 CHILK, S. J. Office of the Secretary of the Commission 82/03/30 FRALEY.R F ACR8 Advisory Committee on Reactor Safeguards 1, 22281 174 24% Fiche 30-000, 83/12/14, 8402160003
- 8402220011 Transcript of ACRB Subcommittee on Structural Engineering 840215 meeting in Los Alamos, NM Pp 1-145 * ACRB - Advisory Committee on Reactor Safeguards, 84/02/15 145pp. 22325 230
- B402220094 Transcript of ACRS Subcommittee on Structural Engineering B40216 meeting in Albuquerque,NM Pp 146-322. * ACRS - Advisory Committee on Reactor Safeguards 84/02/16 176pp 22329 104
- 8402230028 Eummarizes 284th ACRS meeting on 840209-11 w/PO&E & NRC resperation of plant & on 840119 in Los Angeles, CA resafety significance of deficiencies found & corrected by IDVP & util internal design review effort

 EBERBOLE, J C ACRS Advisory Committee on Reactor Bafeguards
 84/02/14 PALLADINO, N J Commissioners 2pp 22379 358 24X
 Fiche 50-275,84/02/14,8402230028
- 8402230235 Bummary of ACRS 286th meeting on 840209-11 w/NRC & EEI re establishment of de minimis values for radiation exposures Supports NRC efforts & encourages coordination w/other Federal agencies such as EPA, DOE & DDT EBERBOLE, J. C ACRS - Advisory Committee on Reactor Safeguards, 84/02/13 PALLADIND, N J Commissioners, 2pp 22380 024
- 8402270263 Responds to FDIA request for JC Mark B01204 memo to ACRS re hydrogen burn w/igniters & documents concerning generation, combustion or control of hydrogen in reactor accidents Forwards App A documents App B documents in PDR. FELTON, J M Division of Rules and Records 84/01/30, HIATT, S L Chia Citizens for Responsible Energy 7pp 22412-051 24X Fichs: 50-000, 84/01/30, 8402270263
- --B1092B0133 Forwards rept, "Status of Hydrogen Control Activities "
 Parts of rept will be discussed in NRC 810910 meeting w/
 ACRS
 RUBENSTEIN,L S Assistant Director for Core & Containment Systems
 B1/09/04 MARK,J C. ACRS Advisory Committee on Reactor
 Safeguards 2pp 22412-207
- --8402270327 Forwards list of ACRB meetings & ltrs re proposed interim amends to iOCFRBO concerning hydrogen control & certain degraded core conditions W/o encl.

 NORBERG.J A. Engineering Metholology Standards Branch 80/11/06
 SIEBB, C.P. ACRB Advisory Committee on Reactor Refeguards ip 22412.115

- --8402270331 Summary of ACRS Subcommittee on Class 9 Accidents 801121 meeting in Washington.DC or RES activities in support of degraded core cooling rulemaking BEBSETTE.D ACRS Advisory Committee on Reactor Safeguards BO/11/26 MERR.W ACRS Advisory Committee on Reactor Safeguards Safeguards 3pp 22412 116
- ~-B402270415 Discusses proposed interim rules re hydrogen control BEAL, S K ACRS - Advisory Committee on Reactor Safeguards B1/09/02 KERR. W ACRS - Advisory Committee on Reactor Safeguards 3pp 22412 204
- --8402270425 Forwards status rept for ACRG Class 9 Accidents Subcommittee generic safety issues Future work re proposed rule dealing w/ice condensers, Mark III & large dry containments will continue as part of TMI Action Flan Item II B 8 BUCCI, D ACRS Advisory Committee on Reactor Safeguards 83/03/15 KERR, W ACRS Advisory Committee on Reactor Safeguards Safeguards App 22412 214
- --R402270431 Forwards minutes of CROR Meeting 40 on B30601 re hydrogen control requirements rule Mods to rule, in response to CROR comments & recommendations, listed WANO.A ACRS Advisory Committee on Reactor Bafeguards 83/07/15 KERR.W ACRS Advisory Committee on Reactor Bafeguards ip 22412 222
- 8402280012 Transcript of ACRS Subcommittee on Reactor Radiological Effects 840224 meeting in Washington,DC Pp 1-222 Supporting documentation encil * ACRS - Advisory Committee on Reactor Safeguards 84/02/24 302pp 22401 168

ADVCM NRC ADVISORY COMMITTEE

- B402130144 Transcript of B40203 periodic meeting w/Advisory Panel for Decontamination of TMI-2 in Washington, DC Pp 1-47, # Commissioners 84/02/03 51pp 22237 165 24X Fiche 50-320, 84/02/03, 8402130144
- 8402140503 Transcript of Advisory Panel for Decontamination of TMI-2 B40112 meeting in Harrisburg, PA Pp 1-108 Supporting documentation enc! * Advisory Council for Decontamination of THI Unit 2 84/01/12 118pp 22251 192 24X Fichs. 50-320,84/01/12,8402140503
- 8402210328 Forwards transcript of Advisory Panel for Decontamination of TMI-2 840203 meeting MASNIK.M T TMI Program Office 84/02/06 Advisory Council for Decontamination of TMI Unit 2 3pp 22344 048 24x Fichs 50-320.84/02/06.8402210328
- --B402210336 Forwards "Cancer Risk Coefficient Applicable to TMI-2 Work Force," in response to questions raised at Advisory Committee on Cleanup of TMI-2 B40112 meeting. COCHRAN, T. B. Natural Resources Defense Council 84/02/03 NRC -- No Detailed Affiliation Given. 2pp 22344 053 24X Fiche 50-320, 84/02/06, 8402210328
- --8402210460 "Cancer Rist Coefficient Applicable to THI-2 Work Force "
 COCHRAN, T B Affiliation Not. Assigned 84/02/03, 10pp.
 22344 055 24X Fichs 50-320,84/02/06,8402210328
- --B402210469 Transcript of Commission 840203 meeting w/Advisory Panel on THI-2 Cleanup in Washington DC Pp 1-47.

 # Commissioners. 84/02/03 52pp 22344-065 24X
 Fiche 50-320,84/02/06.8402210328
- 8402230032 Staff requirements memo re Advisory Panel on TMI-2 Cleanup B40203 meeting on cleanup allegations in Washington, DC Commission requested options for water disposal & results of scheduled meeting between EFA & Advisory Panel CHILK.B J Office of the Secretary of the Commission M840203 B4002/14 DIRCKS, M.J Office of the Executive Director for Operations 2pp. 22379 360 24X Fiche 50-320,84/02/14.8402230032
- B402290342 Transcript of Advisory Panel for Decontamination of TMI-2 640209 meeting in Harrisburg, PA Pp 1-172 Supporting documentation encl. * Advisory Council for Decontamination of TMI Unit 2 84/02/09, 230pp. 22436 138 24X Fichs 50-320.84/02/09,8402290342

COMMISSION NRC COMMISSIONERS

- 8402010364 Further response to full request for records re Ofc of Inspector & Auditor review of NRC investigation reported in NUREO-0862 & other files concerning facilities Forwards App B documents App A & B documents available in POR FELTON. J M Division of Rules and Records 83/11/22 REYNOLDS. J Center for Law in the Public Interest App 22058 203 24% Fiche 50-000,83/11/22,8402010364
- --8402010393 Responds to 820409 ltr re lateness & inadequacy of MRC responses to requests for info displeasure at Commission decisions & list of outstanding subcommittee correspondence w/proposed response dates Requested list forwarded PALLADINON J Commissioners 82/04/21 OTTINGER, R L, House of Rep a Energy & Commerce 3pp 82/059 047
- 8402040345 Forwards NRC quarterly status rept to Congress in response to House Rept 97-850 Rept discusses activities re licensing new facilities taken during Fourth Quarter 1983 PALLADING, N J Commissioners 84/01/25 BEVILL, T House of Repappropriations 13pp 22204 306
- B402070D35 Forwards add1 document in response to Congressmen Udel1 & Markey B31108 request.W/o encl
 DIRCKS.W.J Office of the Executive Director for Operations
 84/02/02 PALLADINO, GILINGKY, ROBERTS Commissioners 10.
 22102
- 8402070081 Further response to FOIA request for IE Insp Rept 77-19, associated notice of proposed imposition of civil penalties, notice of violation & order to show cause Forwards App A documents Documents also available in PDR FELTON, J H Division of Rules and Records 83/12/20 HAMLIN, J & Bhaw, Pittman, Potts & Trowbridge 4pp 22188 104 24X Fiche 50-000.83/12/20,8402070081
- --8402070127 Requests testimony on Commission position re adequaty of licensee GA programs at Subcommittee on Energy & Environ 811027 hearing on GA as applied to reactors under const, UDALL-M K House of Rep : Interior & Insular Affairs. 61/10/13 PALLADINO.N Commissioners ip 22188 112 24X Fiche 50-000.83/12/20.8402070081
- --8402090132 Requests that NRC be prepared to discuss GA problems at facilities at subcommittee Biili9 hearing on GA UDALL-M K House of Rep. Interior & Insular Affairs. Bi/10/30 PALLABINO.N Commissioners ip 22188 ii3. 24X Ficher 50-000:83/12/20:8402090081
- ~-8402070198 Forwards chapter from final rept of NRC special inquirg group re financial disincentives to safety at TMI. in response to questions raised at Subcommittee on Oversight & Investigations 800723 hearing AMEARNE. J F Commissioners. 80/11/13 ECKHARDT, B House of Rep. Interstate & Foreign Commerce Spp. 22188.170 24X Fiche 50-000,83/12/20,8402070081
- 8402090415 Notifies of inability to attend 840304-09 seminar on low a medium power reactors for Latin American in Lima, Peru.
 Requests info summarizing main findings of meeting PALLADINO, N J Commissioners 84/01/23 BARREDA, J Peru. Govt of Ip. 22177 300
- --8402070419 Requests attendence at 840304-09 seminar in Lima, Peru to low & medium power reactors for Latin America SERREDA, J. Peru, Covt. of 83/12/09 PALLADINO, N J. Commissioners 2pp 22177-301.
- 8402090427 Forwards response to 831031 ltr expressing concern re resolution of Unresolved Safety Issues A-47 & A-47 re pressurized thermal shock & safety implications of control sys, respectively PALLADIND, N. J. Commissioners 84/01/27 MARKEY, E. J. House of Rep. Interior & Insular Affairs. 33pp. 22177:260
- 8402090644 Forwards NRC rept re proposed amends to regulations & regulations of puides in response to Section 306 of Nuclear Waste Polify Act of 1982 (Public Law 97-425) Proposed changes reduce unnecessary administrative burdens on utils. PALLADIND.N J. Commissioners. 84/01/20. 808H.O H.W Benate. President of the Sanate 5pp 22185-358
- 8402090647 Notifies of proposed amends to regulations & reg guides in response to Section 306 of Nuclear Waste Policy Act of 1982 (Public Law 97-425). Proposed changes reduce unnecessary administrative burdens on utils. PALLADING, N.J. Commissioners. 84/01/20 0'NEILL, T.P. House of Rep. 8 peaker of the House. ip. 22185-363

- 8402100266 Responds to 831117 ltr signed w/Fish & Gilman re NRC proposal concerning draft rulemaking on emergency preparadness PALLADING.N J Commissioners 84/01/23 OTTINGER,R L House of
 - 22212 262
- ---8402100272 Responds to 831117 ltr signed w/Fish & Ottinger re NRC proposal concerning draft rulemaking on emergency preparedness PALLADING, N. J
 - Commissioners 84/01/23 GILMAN.B House of Rep
- --8402100277 Responds to 831117 ltr signed w/Oilman & Ottinger re NRC proposal concerning draft rulemaking on emergency preparedness.
 PALCADINO.N J Commissioners 84/01/23 FISH.H House of Rep 2pp. 22212 266
- --B309150466 Requests possible revs to emergency planning rules needed in MOU between NRC & FEMA PALLADINO,N,J Commissioners 83/06/08 DIRCKS,WJ Office of the Executive Director for Operations ip. 22212 269
- --8401110109 Urges NRC to begin ray to regulations to eliminate present
- ---840[110113 Urges NRC & FEMA to quickly review & revise internal regulations being misused by some local officials reemergency preparedness plan Suspension of OLs or denial of licenses will cause adverse aconomic consequences to utils. LUJAN, M House of Rep., Interior & Insular Affairs 83/06/01 PALLADING, N J. Commissioners 2pp 22212:274
- --B309130467 Discusses regulations that require state/local govt to stop const or operation of power plant due to local govt refusal to participate in emergency planning Requiring util to fund effort is constructive regulatory approach LLOYD, M House of Rep. B3/05/31. PALLADINO, N J Commissioners 22212 276.
- --B307150471 Forwards Congressional ltrs re possible revs to emergency planning regulations.
 PALLADINO, N. J. Commissioners. 83/06/13 DIRCKB, W. J. Office of the Executive Director for Operations. 1p 22212 278.
- ---B309150474 Buggests rev to FEMA & NRC emergency planning regulations so state/local govts cannot prevent OL issuance or shut down plant due to local govt refusal to participate in emergency planning.
 SASSER, J. Senate B3/04/06. PALLADINO, N. J. Commissioners, 2pp. 22212:279.
- -8309150480 Forwards Congressional Record excerpt re local & state govt ability to prevent OL issuance or to shut down plant due to ability to prevent OL issuance or to shut down plant due to local govt refusal to participate in emergency planning. NEAL S.L. House of Rep. 83/06/06. PALLADING, N. J. Commissioners 2pp. 22212,221
- ---8309150464 Responds to Congressional concerns that FEMA & NRC regulations permit unintentional misuse since state or local govt refusal to prepare emergency plan may effectively prevent OL issuance or force plant shutdown DIRCKS M.J. Office of the Executive Director for Operations 83/07/Ot PALLADING, N.J. Commissioners 2pp. 22212, 286.
- ---B402100274 Comments on NRC proposal re draft rulemaking on emergency preparedness. Proposal should be resvaluated to limit nuclear industry sbility to "redefine" actual problems out of DTIINGERR.L., GILMAN, B., FIBH, H. House of Rep. 83/11/17. PALLADING, N. Commissioners. 3pp. 22212-288.
- 8402140482 Responds to 840202 questions re Chicago Tribune erticle on safety problems. Insp findings published in NURES-0400, Vol 4. Number 2.
 DIRCKG H. J. Dffice of the Executive Director for Operations. 84/02/08. FALLADING.N J. Commissioners. 3pp. 22251;352. 24X

Fiche: 50-454, 84/02/08, 8402140482

- --8402140484 Requests answers to encl questions re Chicago Tribune article on safety problems at facilities PALLADINO, N.J. Commissioners 84/02/02 DIRCKS, W.J. Office of the Executive Director for Operations 2pp 22251 355 24X Ficha 50-454,84/02/08,8402140482
- 8402170007 Testimony of NJ Palladino to Subcommittee on Energy & Environ re NRC budgeting request for FY85 PALLADIND, N J Commissioners 84/02/09 42pp 22317 158 24X Fiche 50-289, 84/02/09, 8402170007
- --8402170024 Testimony of JK Asselstine to Subcommittee on Energy & Environ re need to extend NRC authority to issue temporary Ois & review no significant bazards determination for steam generator repairs at TMI-1 ASSELSTINE. J K Commissioners 84/02/09 4pp 22319 203 24X Fiche 50-289,84/02/09.8402170907
- --B402170027 Testimony of V Gilinsky to Subcommittee on Energy & Environ re NRC budget & experience w/Commission Answers to questions from Udall 840123 itr & SRP encl 91LINSXY, V Commissioners. 84/02/07 120pp 22319 207
- 8402170387 Discusses refs made in Section 12 of Sholly amend reauthorizations for spent fuel pool expansion or reracking as significent hazards consideration
 PLAINE.H Office of the General Counsel CUNNINGHAM, G.H Office of the Executive Legal Director. B3/03/24 PALLADING, N
 Commissioners 2pp 22313 186
- 8402240290 Weekly info rept for wk ending 840210 REHM:T A Office of the Executive Director for Operations 84/02/16. 48pp 22380 154
- 840228001B Further response to FOIA request for documents generated or received by NRC since 820331 re Hayward Tyler Pump Co Forwards App A documents App A documents placed in PDR App B documents withheld (ref FOIA Exemption 5) FELTON. J. M. Division of Rules and Records 83/12/21 LODGE, B Dellas Morning News 3pp 22430 209 24X Fiche 50-471,83/12/21, 8402280018
- --8402280000 Reaffirms Committee on Interior & Insular Affairs belief that NRC investigation of Hayward Tyler Pump Co will not be compromised by media publicity CHENEY, D. COELHO, T. House of Rep. 82/06/24 PALLADING, N. J. Commissioners 1p. 22430.212
- --8402280027 Responds to 821110 request for answers to several questions left outstanding re subcommittee 820406 hearing concerning NRC investigation of Hayward Tyler Pump Go Responses to questions presented in Encl 1 M/o encl PALLADINO.N. J. Commissioners 82/11/24, MARKEY.E. J. House of Rep.: Interior & Insular Affeirs. 3pp. 22430.213.
- --B402280035 Requests concurrence t/or comments re proposed itr to Markey responding to B21110 questions left outstanding following B20404 subcommittee hearing concerning NRC investigation of Hayward Tyler Pump Co.
 CHILK, B J Office of the Becretary of the Commission CR-82-127 B2/12/14. PALLADING, GILINSKY, AMEARNE Commissioners ip 22430:217
- --8402280039 Informs of suicide of Hayward Tyler Pump Co GA manager. # Commissioners 83/01/06. NRC No Detailed Affiliation Given ip 22430:218
- --8402280042 Requests concurrence &/or comments on encl proposed response to Markey 830127 ltr requesting addl info re Hayward Tyler Pump Co investigation Response by 830224 requested CHILK, S. J. Office of the Secretary of the Commission CR-83-20 83/02/17, PALLADING, GILINSKY, AHEARNE Commissioners. 3pp. 22430-219
- ---B402280045 Requests five listed categories of documents for assistance in author investigation into NRC insp & investigation programs arising from controversy over Hayward Tyler Pump Co inquiry, MARKEY, E. J. House of Rep , Interior & Insular Affairs 83/03/17 PALLADINO, N. J. Commissioners. 2pp 22430 222
- -B40228006: Forwards info re NRC investigations, in response to 830317 request, Encls 2 & 3 contain lists of investigations completed by Ofc of Inspector & Auditor & Ofc of Investigations W/o encls.
 PALLADINO, N. J. Commissioners. 83/05/17, MARKEY, E, House of Rep., Interior & Insular Affairs ip 22430 224

- --9402280065 Advises that subcommittee 830520 hearing on Hayward Tyler Pump Co will be postponed due to Commission failure to respond in timely fashion to 830317 request for info Commission will be informed of new hearing date MARKEY.E J House of Rep , Interior & Insular Affairs 83/05/19 PALLADING.N J Commissioners Ip 22430 225
- --8402280049 Advises that contents of Ofc of Inspector & Audit Case Files 80-23,80-34,81-11,81-47 & 82-19 needed prior to subcommittee 830520 hearing re Mayward Tyler Case MARKEY,E J. House of Rep., Interior & Insular Affairs 83/06/07 PALLADINO,N J. Commissioners ip 22430 226
- --8402280090 Forwards final version of Chairman testimany on NRC investigation into allegations re Hayward Tyler Fung Co Tostimony will be presented before Subcommittee on diversight a Investigations of House Interior Committee on 820406 KAMMERER.C Office of Congressional Affairs 82/04/05, PALLADINO, OILINSKY, AHEARNE Commissioners ip 22430 286
- --8402280074 Forwards Commissioner Gilinsky separate views that should be added to Gittinger lit as last paragraph HANNINO.W J. Commissioners 82/05/27 REAMER.W , HARDINO.V , LAVERTY.J. NRC No Detailed Affiliation Given 2pp 22430-301
- 8402280713 forwards joint NRC/FEMA quarterly status rept on emergency preparedness for Oct-Dec 1983 Rept describes actions taken to upgrade emergency preparedness at sites PALLADINO,N J. Commissioners GIUFFRIDA,L. O. Federal Emergency Management Agency 84/02/14 SIMPSON,A K. Senate, Environment & Public Works Sipp 22414 282
- B402270002 Responds to FOIA request for correspondence NRC received from Senators J McClure, JB Johnston & P Laxalt during past 2 yrs Forwards App A facoments. Name of individual deleted from Documents & & 7 of App A (ref FOIA Exemption 6) FELTON, J M Division of Rules and Records B3/11/30. KOLI, E Cable News Natural Inc. App 22438 OO2 24X Fiche 50-000, 83/11/30. 8402270002
- ~-8304260267 Forwards responses to Nuclear Data Link issues raised by Congress NRC recommendation to release RFP for prototype evaluation approved PALLADINO.N J Commissioners 83/04/07 HATFIELD.M O Senate, Appropriations 35pg 22438 055
- ---B306140051 Requests reinstatement of \$700,000 reduction in requested funds for pay increases Funds to evaluate prototype of nuclear data link necessary PALLADINO.N J. Commissioners 83/09/19 HATFIELD.M D. Senate. Appropriations 1p 22438-054
- --840229005B Forwards resume of constituent interested in serving on ACRS Info deleted HCCLURE, J A Senate, Energy & Natural Resources 83/09/22 PALLADINO, N J Commissioners App 22438 017
- --9402290127 Informs that NRC upgrading investigative capabilities by consolidating NRC investigatory functions in new dfc of Investigation, PALLADINUS N J Commissioners 82/06/10 HATFIELD, M Senate, Appropriations ip 22438-038
- --8402270271 Requests approval to reprogram portion of FY83 available funds to compensate for 1982 pay raises & to increase efforts in GA & use of cost-benefit analysis. Proposed reprogramming adjustments, w/explanations, detailed in encl PALLADING, N J Commissioners 63/02/03 HATFIELD, N D Benate, Appropriations 6pp 22438;091
- ---8402270285 Requests NRC to begin rev of regulations immediately to sliminate present abuses re vato power over emergency planning provided by NRC & FEMA regulations to state NRC & FEMA should act forcefully to resolve crisis at facility, JCHANSTON.J B. Senate, Energy & Natural Resources 83/05/27 PALLADINO,N J. Commissioners 2pp 22438 101 24X Fiche 50-000,83/11/30,8402270002

CONTRACT NRC CONTRACTS AND MODIFICATIONS

8402010030 Notification of contract execution, Mod & to "Btudy of Regional Tectonics & Stiamicity for Nebraska" Contractor Univ of Nebraska - Lincoln.

UMBEL. D Technical Assistance Contracts Branch FIN 8-0774

NRC-04-76-215 83/12/13 BATSON, W Office of Nuclear Regulatory research, Director STEVER, N NRC - No Detailed Affiliation Given > 22048 112

- --8402010037 Ltr Contract NRC-04-76-315, Mod 6, deabligating funds, to "Study of Regional Tectonics & Seismicity for Nebraska." GUSTAVE, R P Technical Assistance Contracts Branch. FIN B-5774 NRC-04-76-315 83/12/02 BEHNE, M Nebraska, Univ. of. Ip 22048 113
- B402010033 Notification of contract execution, Mod 1 to "Review of Tormado Missile PRA South Texas Project " Contractor NBB UMBEL D Technical Assistance Contracts Branch FIN B-657, NRC-03-83-114 84/01/12 MATTBON, R J Division of Systems Integration (post 811005) SINGH, B.L NRC No Datailed Affiliation Oven 1p 22048 109 24X Fichs 30-498.84/01/12,8402010033
- --8402010040 Mod 1.adding funds for FY84 & revising Article 3. to *Apply of Tornado Missile PRA Bouth Texas Project "

 ** Commerce, Dept of, National Bureau of Btandards OUSTAVE, R P
 Technical Assistance Contracts Branch NRC-03-83-114 84/01/12

 1p 22048 110 24X Fiche 50-498,84/01/12,8402010033
- 8402010042 Notification of contract execution, Mod 2 to "Radiation Monitoring Program Requirements" Contractor State of HA. UMBEL, D Technical Assistance Contracts Branch FIN 8-8551 NRC-32-83-662 84/01/16 FRIGILLANALE B Region 5 Diffice of Director HAMADA, O NRC No Detailed Affiliation Given. 1p. 22058 201
- ~-8402010043 Mod 2 adding funds for CYB4 & changing 8&R number, to
 "Radiation Monitoring Program Requirements"
 * Washington: State of GUSTAVE, R P Technical Assistance
 Contracts Branch. FIN B-8551 NRC-32-83-482 84/01/14 ip.
 22058. 202.
- 8402010044 Notification of contract execution, Mod 5 to "Expert Consultation & Witness Svc for South Texas Project Hearings "Contractor W Habacek PERCMAN, J Administrative Contracts Branch FIN 8-8306 NRC-31-82-731 84/01/20 COLLINS, J T , CROSSMAN, W. Region 4. Office of Director ip 22058 199 24X Fiche 50-498, 84/01/20, 8402010044
- --B40201004B Mod 5.extending period of performance at no add1 cost,to
 "Expert Consultation & Witness Bvc for South Taxas Project
 Hearings"
 HUBACEK, W G Hubacek, H G HAOAN,T F Division of Contracts
 FIN B-6306 NRC-31-82-731. 84/01/20 ip 20058 200. 24X
 Fiche 50-498,84/01/20,8402010044.
- 8402010046 Notification of contract execution. Mod 2 to "Radiation Monitoring Program Requirements" Contractor, Environ Surveillance Leb UMBEL, D Technical Assistance Contracts Branch. FIN 8-8550, NRC-32-83-661. 84/01/17 FRIGILLANA: E Region 5, Office of Director HAMADA, Q NRC No Detailed Affiliation Given. 1p 22058 197
- ---8402010050 Med 2, adding funds for CYB4 & changing B&R number, to "Radiation Monitoring Program Requirements" # Environmental Burveillance Laboratory GUBTAVE, R. P. Technical Assistance Contracts Branch FIN B-8550, NRC-92-83-681.
- 8402010052 Notification of contract execution, Mod 2 to "Radiation Monitoring Program Requirements" Contractor, State of DR UMBEL, D Technical Assistance Contracts Branch. FIN 8-8554. NRC-028-83-865 84/01/17 FRIGILLANALE B Region 5, Office of Director HAMADA, O NRC No Detailed Affiliation Given. 1p. 22058, 175.
- --8402010054 Mod 2, adding funds for CY84 & changing B&R number to
 "Radiation Monitoring Program Requirements"

 * Oregon, Btata of QUSTAVER P. Technical Assistance Contracts
 Branch FIN B-8554 NRC-32-83-685 84/01/17. 1p. 22058-194
- 8402010058 Notification of contract execution, Mod 3 to "Reviewing Hydrogeologic Investigations of Nevada Test Site Project 8 " Contractor, GeoTrans. Inc FLEENOR, C Technical Assistance Contracts Branch FIN 8-7374-4 NRC-02-82-047. 84/01/06, DAVIS, J Office of Nuclear Material Safety & Safeguards. Director POHLE, J NRC No Detailed Affiliation Given, 1p 22058-172
- --8402010062 Mod 3.obligating funds.to "Reviewing Hydrogeologic Investigations of Nevada Test Site - Project B." ROSS,B. Geotrans, Inc GUBTAVE,R P. Tachnical Assistance Contracts Branch FIN B-7378-4 NRC-02-82-047 84/01/06 2pp 22058 193
- B402010059 Notification of contract execution. Mod 2 to "Radiation Monitoring Program Requirements" Contractor: State of CA.
 UMBEL.D. Technical Assistance Contracts Branch FIN B-8553
 NRC-32-83-844 84/01/16 FRIGILLANA.E.B. Division of Resource Management & Administration HAMADA.O NRC No Detailed Affiliation Given 1p. 22058: 190

- -8402010065 Mod 2, adding incremental funding & changing 8&R number, to "Radiation Monitoring Program Requirements" **California, State of GUSTAVE, RP Division of Contracts FIN 8-8553 NRC-32-83-684 84/01/16 Ip 22058 191
- 8402010071 Notification of contract execution, Mod 15 to "Structural Integrity of Water Reactor Boundary Components"
 Contractor ENSA, Inc
 PAGE, # Technical Assistance Contracts Branch FIN B-8133
 NRC-04-82-013 83/12/28 FOREMAND, W Office of Nuclear Regulatory
 Research, Director VAGINS, M NRC No Detailed Affiliation Given
 - 2204B 359
- --8402010073 Mod 15, extending period of performance, revising statement of work & adding funding to "Structural Integrity of Water Reactor Boundary Components" HAA9, M N ENBA, Inc QUSTAVE, R P Division of Contracts FIN 8-8133, NRC-04-82-013 83/12/28 4pp 22048 360
- 8402010072 Notification of contract execution. Mod 3 to "Radiation Monitoring Program Requirements" Contractor State of MO UMBEL.D Technical Assistance Contracts Branch FIN 8-8454 NRC-30-83-643 84/01/18 SCHLOBSEL.L A Division of Resource Management & Administration OESTMANN, M J NRG No Detailed 22048 122 Affiliation Given to
- --8402010081 Mod 3,providing funding,to "Radiation Monitoring Program Requirements" * Missouri, State of QUBTAVE,R P Division of Contracts FIN B-8454 NRC-30-83-643 84/01/18 1p 22048 123
- B402010105 Notification of contract execution, Mod 15 to "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents " Contractor Personnets Inc
- INCLUENTS CONTRACTOR PARAMETER, INC WOLLETT, S Technical Assistance Contracts Branch FIN 8-1302 NAC-05-82-249 84/01/18, BLAHA, J Director's Defice, Office of Inspection and Enforcement LAUDAN, W NRC No Detailed Affiliation Given. 1p. 22058 037
- --8402010110 Mod 15, issuing Task Order 57 & providing incremental funding, to "Technical Assistance to Suport NRC IE Personnel in Investigations of Incidents "
 LOFY, R A Parameter, Inc. GUSTAVE, R P Division of Contracts FIN B-1302, NRC-05-82-249 84/01/18 4pp 22058 058
- 8402010170 Notification of contract execution.Mod 2 to ". Review of Draft Rept Entitled 'Radionuclide Release Under LWR Epecific Accident Conditions' "Contractor W Kastenberg TOWNSEND.B L Purchasing Section FIN B-8990. NRC-04-83-015 84/01/17 BASECTIO E Division of Accident Evaluation (Pre B40101) JANKOWSKI.M W NRC No Detailed Affiliation Given ip
- --B402010180 Mod R. extending period of performance & increasing funding-to ". Review of Draft Rept Entitled 'Radionuclide Release Under LMR Specific Accident Conditions'." KASTENBERG, W. E. Kastenberg, W. E. REBELLO, J. E. Division of Contracts FIN B-8790 NRC-04-83-018 84/01/17 ip. 22048 059
- 8402010171 Notification of contract execution, Mod 3 to "Rediation Monitoring Program Requirements." Contractor State of MN.
 UMBEL.D. Technical Assistance Contracts Branch FIN B-8452
 NRC-30-83-645. 84/01/19 SCHLOSSER.L A Division of Resource Hamagement & Administration DESTMANN.M.J. NRC No Detailed Affiliation Given. ip 22048.056
- --8402010176 Mod 3, providing increase in funding, to "Radiation Monitoring Program Requirements." * Minnesota, State of GUBTAVE, R P. Division of Contracts FIN B-8452. NRC-30-83-645 84/01/19. ip. 22048:057
- 8402010265 Notification of contract execution, Mod 3 to "Radiation Romitoring Program Requirements." Contractor: State of OH UMBEL, D Technical Assistance Contracts Branch FIN 8-8450' NRC-30-84-646. 84/01/13 BCHLOBBER.L. A Division of Resource Hanagement & Administration DESTMANN.M.J NRC No Detailed Aprillation Given ip 22046.354 24% Fiche 50-346,84/01/13,8402010265.
- --8402010273 Mod 3, providing funds for CYB4 & incorporating environ monitoring at Davis-Basse, to "Radiation Monitoring Program Requirements,"

 JACKSDN, D. L. Chio, State of, QUSTAVE, R. P. Division of Contracts
 FIN 8-8450 NRC-30-83-646, 84/01/13 2pp. 22046 335 24X
 Fichs: 50-346, 84/01/13, 8402010265
- 8402010325 Notification of contract execution, Mod 5 to "Rediation Monitoring Program Requirements" Contractor, State of WI. UMBEL.D. Technical Assistance Contracts Branch FIN B-8453 NRC-30-83-647, 84/01/19, BCHL085ER,L.A. Division of Resource Management & Administration. DESTMANN,M.J NRC No Datailed Affiliation Given ip. 22059:312

- --8402010328 Mod 5.providing increased funding to "Radiation Monitoring Program Requirements "

 * Wisconsin, State of OUSTAVE,R P Division of Contracts FIN
 B-0453 NRC-30-63-647 B4/01/19 1p 22059 313
- 8402010331 Notification of contract execution, Mod 3 to "Radiation Monitoring Program Requirements" Contractor State of MI UMBEL, D Technical Assistance Contracts Branch FIN 8-8451 NRC-30-83-644 84/01/19 SCHLOSSER.L A Region 3, Office of Director OESTHANN.M J NRC No Detailed Affiliation Given ip 22059 309
- --8402010333 Mod 3.providing funding for CYB4.to "Radiation Monitoring Program Requirements" * Michigan. State of OVBTAVE.R P Division of Contracts FIN B-8451 NRC-30-83-644 84/01/19 1p 22059 310
- 8402010337 Notification of contract execution "Use of TVA Reactor Simulator Facilities at Chattanooga, TN for Training on Browns Ferry, Bequogah & Bellefonte Binulators" JESSUP. B Technical Assistance Contracts Branch FIN 8-8717 NRC-05-84-153 83/12/29 SHOME. S K Director's Office, Office of Inspection and Enforcement 1p 20059 229 24X Fiche 50-000.83/12/29.8402010337
- --8402010346 Ltr Contract NRC-05-84-153, "Use of TVA Reactor Simulator 102010346 Ltr Contract NRC-05-84-153, "Use of TVA Reactor Simulator Facilities at Chattanooga.TN for Training on Browns Ferry.

 Sequoyah & Bellefonte Simulators," awarded to TVA
 MORTON.K V Technical Assistance Contracts Branch FIN B-8717
 NRC-05-84-153 BS/12/29 JCHNSON.R J Tennessee Valley
 Authority App 22059 230 24X Fiche 50-000,83/12/29,8402010337
- B402010337 Notification of contract execution. Mod 1, to "Consultant Scvs of DR Budnitz to Review SEP Integrated Plant Safety
 Assessment Repts " Contractor Future Resources Assoc
 PAGE.M Technical Assistance Contracts Branch FIN B-8636
 NRC-03-83-099 84/01/20 EIBENHUT.D Division of Licensing
 GRIMES.C NRC No Detailed Affiliation Given ip 22061 332
- ~~B402010342 Mod i.extending period of performance to 840630, to "Consultant Sycs of DR Budnitz to Review SEF Integrated Plant Bafety Assessment Repts"

 BUDNITZ.R Future Resources Associates, Inc. GUSTAYE,R P. Division of Contracts FIN 8-8636 NRC-03-83-099 84/01/22061 333
- 8402010344 Notification of contract execution, Mod 2 to "Design, Programming, Testing, Training, Implementation & Documentation of Licensing Mgt Sys "Contractor Advanced Technology, Inc PERLMAN. J Administrative Contracts Branch FIN D-1007-3 NRC-33-83-464 B3/12/14 BASSETT, H Office of Resource Management, Director MACWILLIAMS, M NRC No Detailed Affiliation Given 1p R2059 359
- --B40201035: Mod 2, incorporating provisions for electronic transfer of funds. to "Design, Programming, Testing, Training, Implementation & Documentation of Licensing Mgt Bys "

 * Advanced Technology, Inc HARAN, T F Division of Contracts
 FIN D-1007-3 NRC-33-83-464 83/12/14 2pp 22059 360
- 8402010355 Notification of contract execution, Mod 2 to "Strategic Analysis of Safeguards Sys Feasibility Study " Contractor Maxima Corp DELOATCH: V Technical Assistance Contracts Branch. NRC-04-B3-001. B4/01/17 FOREHAND: W Office of Nuclear Reactor Regulation. Dijector BARNOLD: A NRC No Detailed Affiliation Given. ip 22059. 352.
- --8402010357 Mod 2.extending period of performance at no add1 cost until 840229.to "Strategic Analysis of Safeguards Sys Feasibility 8tudy." * Maxima Corp OUSTAVE.R P Division of Contracts NRC-04-83-001 84/01/17 1p. 22059
- B402010358 Notification of contract execution, Mod 7 to "Maint of Data General Computers & Peripheral Equipment " Contractor Data Consultants.Inc HAMKINS.D A Administrative Contracts Branch FIN B-1663 NRC-25-82-311, 84/01/20 BASETT.H R Division of Data Automation & Management Information JNHNSON.C R NRC No Detailed Affiliation Given 19, 22059, 346.
- ---8402010362 Mod 7.adding equipment being furnished under maint sycs, to "Maint of Data General Computers & Peripheral Equipment " BONNES, G. Data Consultants, Inc. HAGAN T F. Division of Contracts FIN 9-1663, NRC-25-82-311, 84/01/20 App 22059.347

- 8402010385 Notification of contract execution Mod 1 to "Radiation Program Monitoring Requirements" Contractor State of AL UMBEL.D Technical Assistance Contracts Branch Fin B-8405 NRC-29-83-626 84/01/23 MALEY, BJ Region 2. Office of Director MONTGOMERY, DM NRC No Detailed Affiliation Given 19 22059 317
- --8402010389 Mod 1, providing incremental funding, to "Radiation Monitoring Program Requirements" * A Alabama, State of GUSTAVE: R P Division of Contracts FIN D-8405 NRC-29-83-626 84/01/23 ip 22059 318
- 8402010436 Notification of contract execution Mod 3 to "Publications Bubscriptions" Contractor McGraw-Hill Inc HAKKINS.D Administrative Contracts Branch NRC-10-83-321 84/01/20 BESAW W Division of Technical Information & Document Control CONYNGHAM, NRC No Detailed Affiliation Given ip 22041 292
- --8402010439 Mod 3:extending period of performance to 841231 & increasing funds, to "Publications Subscriptions"
 MODRE.S J McGraw-Hill Publications Co HAGAN.T F Division of Contracts NRC-10-83-321 84/01/20 App 22061 293
- 8402020462 Notification of contract elecution, Mod 2 to "State Legislative Reporting Svcs " Contractor Public Affairs Info. Inc.
 - Inc PERLMAN, J. Administrative Contracts Branch NRC-06-83-266 83/12/14 KERR, H O Dffice of State Programs, Director LANDAU, M NRC - No Detailed Affiliation Given 1p. 22062 163
- --8402020465 Mod 2, incorporating provisions for electronic transfer of funds, to "State Legislative Reporting Svcs " * Public Affairs Information. Inc. HAGAN-T F. Division of Contracts NRC-06-83-266 83/12/14 2pp 22062 164
- 8402020468 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements" Contractor State of OA UMBEL.D Technical Assistance Contracts Branch FIN 8-8404 NRC-27-83-625 B4/01/20 MALEY.R J Region 2. Office of Director MONTGOMERY, D M NRC No Detailed Affiliation Oiven 1p 22062 (A)
- --B402020470 Mod i,adding incremental funding & incorporating environ monitoring,to "Radiation Monitoring Program Requirements" " Georgia, State of OUSTAVE,RP Division of Contracts FIN B-8404 NRC-29-83-625 84/01/20, ip 22062 162
- B402030062 Natification of cantract execution, Mod 14 to "Btudy of Boismicity & Tectonics of New England " Contractor Boston College JACOBB. A Technical Assistance Contracts Branch. FIN A-4056 NRC-04-74-288 B4701/20 BAT50N.W Office of Nuclear Regulatory Research, Director MURPHY. A NRC No Detailed Affiliation Given 1p 22091 052
- --8402030047 Mod 14, providing final funding action w/scope of work, to "Study of Seismicity & Tectonics of New England," SMITH, J.R. Boston College, Chestnut Hill, MA GUSTAVE, R.P. Division of Contracts FIN A-4056 NRC-04-74-238 64/01/30 5pp 22091,053
- B4020390B1 Notification of contract execution "Maint & Operation of LPDR," awarded to Univ of Wisconsin TOWNSEND.B L Administrative Contracts Branch NRC-10-84-233. B4/01/25. FELTON.J M Division of Rules and Records SOUDER,J.L. NRC No Detailed Affiliation Given 1p 22091:039
 - 8402030082 Contract "Maint & Operation of LPDR," awarded to Univ of Wisconsin BACKES,C J Wisconsin, Univ of, Green Bay, WI. RESELLO,J E Division of Contracts, NRC-10-84-253 84/01/25, 9pp 22091:040
 -)2030070 Notification of contract execution, Mod 1 to "Radiation lonitoring Program Requirements" Contractor State of HB MBEL. D Technical Assistance Contractor State of HB MBEL. D Technical Assistance Contracts Branch FIN B-8400 RC-29-83-621, 84/01/19. MALEY, R J. Region 2, Office of Director. CONTOUMERY, D M, NRC No Detailed Affiliation Given 1p 22091 024
 - -8402030076 Mod 1, providing incremental funding, to "Radiation Monitoring Program Requirements" * Mississippi, State of QUSTAVE.R Division of Contracts FIN B-8400. NRG-29-83-621 84/01/19 ip 22091 025
- 1402030100 Notification of contract execution.Mod 1 to "Hypocenter Determination of Regional Earthquakes/Spectral Techniques for Focal Depths." Contractor.Univ of Kentucky.
 NURPHY.L G Administrative Contracts Branch FIN 8-7000.
 NRC-04-83-024 84/02/18 ARSENAULT.F J Division of Health, Siting & Waste Management MURPHY.A J. NRC No Detailed Affiliation Given. 1p 22070.334.

- --B402030101 Mod 1.extending period of performance to 840701.to
 "Hypocenter Determination of Regional Earthquakes/Bpectral
 Techniques for Focal Depths"
 * Kentucky Univ of Lexington KY * Division of Contracta
 NRC-04-83-024 84/02/18 1p 22070 337
- 8402030104 Notification of contract execution, Mod 2 to "Environ Assessment re Proposed Deep Well Injection of Liquid Raffinate by Kerr-McGee U Hexafluoride Plant " Contractor: DL Warner, Inc MURPHY, L 9 Administrative Contracts Branch FIN 8-7387-3 NRC-02-83-038 84/01/24 BROWN, R 8 Program Support Branch WYNGARDEN, B D NRC No Detailed Affiliation Given 1p 22090,
- --8402030106 Mad 2.extending period of performance to 850131 at no cost.to "Environ Assessment re Proposed Deep Well Injection of Liquid Raffinate by Kerr-McGee U Hexafluoride Plant." Bon L Warner, Inc. * Division of Contracts. FIN 8-7367-3 NRC-02-83-038 84/01/24 1p 22070.335
- 8402030202 Notification of contract execution, Mod 3 to "State Legislative Reporting Svcs." Contractor Public Affairs Info. Inc PERLMAN, J Administrative Contracts Branch FIN 8-1592. NRC-04-83-266 84/01/06 KERR, W G. Office of State Programs, Director LANDAU, M NRC - No Detailed Affiliation Given 1p 22089 358,
- --8402030207 Mod 3, exercising option to extend period of performance 850106 & increasing amount of contract, to "State Legislative Reporting Svcs " * Public Affairs Information, Inc HAGAN, T F. Division of Contracts FIN 8-1592 NRC-06-83-266 84/01/06 1p 22089 3
- 8402030348 Notification of contract execution, Mod 2 to "Radiation Monitoring Program Requirements" Contractor Univ of Iowa UMBEL, D. Technical Assistance Contracts Branch FIN 8-8434 NGC-30-83-648 84/01/19. SCHLOBER, L. A. Division of Resource Management & Administration DESTERMANN, M. J. NRC No Detailed Affiliation Given ip 22089.356
- --8402030352 Mod 2 increasing funding to "Radiation Monitoring Progri Requirements "

 * lows Univ of lows City IA. GUSTAVE.R.P. Division of Contracts FIN 8-8456 NRC-30-83-648 84/01/19, ip. 22089 3
- B402030421 Notification of contract execution, Mod 2 to "Review, Abstract. Index & Guarterly Update Practice & Procedure Digest " Contractor. Aspen Sys. Inc., PERLHAN. J. Administrative Contracts Branch. FIN 8-1388. NRC-14-82-448 B4/01/24. CUNNINGHAN. @ Office of the Executive Legal Director GRAY, J. NRC No Detailed Affiliation Given is 22089-346.
- --8402030428 Mod'2, incorporating electronic transfer of funds. to "Review, Abstract, Index & Quarterly Update Practice & Procedure Digest"

 # Aspen Systems, Inc. HAGAN, T F Division of Contracts, FiH B-1588 NRC-14-82-448, 84/01/24, 2pp. 22089: 347.
- 8402060471 Mod 6, incorporating statement of work & extending period of performance to 850228.to "Conversion.Programming," implementation.Documentation & Acceptance Processing of IFNIS "

 * Technosociates, Inc HILL.D Small Business Administration HAGAN, T.F. Division of Contracts FIN 8-8172 NRC-10-81-359.

 84/01/04 6pp. 22110 287.
- 8402060122 Notification of contract execution, Mod 5 to "Environ Assessment of Groundwater Contamination in Wood River, Ri Contractor: DL Harner, Inc HOYLE: A Purchasing Section. FIN 8-6993-2. NRC-02-60-076. 84/01/23. BROWN, R 8. Program Support Branch. BHUM. E. NRC No Detailed Affiliation Given. ip \$2107.165
- 8402060177 Notification of contract execution, Mod 4, to "Furnish Band to Dust Data Base Occurrences for UB " Contractor: NOAA UMBEL, D. M. Tachnical Assistance Contracts Branch. FIN B-10748 NRC-01-7B-013 83/12/02. FOREHAND, W. Office of Nuclear Regulators Research, Director. KORNASIEWICZ, R. NRC No Datailed Affiliation Given. 1p. 22103.194.

- --B402050184 Mod 4, extending period of performance, to "Furnish Sand & Dust Data Base Occurrences for US" HOXIT.L R Commerce, Dept of Natl Oceanographic & Atmospheric Administration GUSTAVE.R P Division of Contracts FIN 8-10748 NRC-01-78-015 83/12/02 1p 22103 195
- 8402060465 Notification of contract execution, Mod 6 to "Conversion, Programming Implementation, Documentation & Acceptance Processing of IFMIS " Contractor SBA Subcontractor Technessociates, Inc SELEMENTS OF A PROPERTY OF THE PROPERTY OF T
- 8402040475 Notification of contract execution.Mod 7 to "Info Mgt Sys for NRC Operations Ctr " Contractor Phoenix Assoc, Inc GILDENHORM A J Administrative Contracts Branch FIN B-8709 NRC-05-83-218 84/01/26 BURDA, A J Program Support & Analysis Staff. BADINI, B NRC No Detailed Affiliation Given 1p 22110 277
- --8402060482 Mod 7, extending sys manager & facilities mgt requirements & adding option to increase contract amount, to "Info Mgt Sys for NRC Operations Ctr "
 FENSTERSTOCK, J Phoenix Associates, Inc HAGAN, T F Division of Contracts. FIN 8-8709 NRC-05-83-218 84/01/26 opp 22100:278.
- 8402060486 Notification of contract execution, Mod 2 to "Development of Automated Vendor Balaction Bys." Contractor Gasser Assoc HAHKINS.N.A. Administrative Contracts Branch FIN B-1214 NRC-05-80-253 84/01/26 COBB.L Director's Office, Office of Inspection and Enforcement, RUTHERFORD, W R NRC No Detailed Affiliation Given. 1p 22110 202
- --9402060498 Mod 2.incorporating final indirect rates, to "Development of Automated Vendor Selection Bys."

 QABBER.E R Qasser Associates HAGAN, T.F. Division of Contracts FIN B-1214 NRC-05-80-253 84/01/26. ip 22110 202
- 84020A0498 Notification of contract execution, Mod 1 to "Rediation Monitoring Program Requirements" Contractor, State of NE UMBEL, D. M. Technical Assistance Contracts Branch, FIN 8-8303, NRC-31-83-470 84/01/26, MEYERS, D M. Region 4, Office of Director NICHOLAS, J B, NRC No Detailed Affiliation Given 1p 22110 162
- --8402060502 Mod 3,providing funding & changing B&R number,to "Radiation Monitoring Program Requirements" * Nebraska, State of QUBTAVE,R.P Division of Contracts. FIN B-8503 NRC-31-83-670, 84/01/26, ip. 22110:163
- 8402060504 Notification of contract execution, Mod 7 to "Conversion, Programming, Implementation, Documentation & Acceptance Processing of IFMIB." Contractor: 88A Subcontractor: Technaesociates, Inc. OCIDENTION, A J. Administrative Contracts Branch MRC-10-81-359, 83/12/14 BABSETT, H. S. Division of Data Automation & Management Information. WRIGHT, C. NRC - No Detailed Affiliation Given 1p.
- --8402060539 Mod 7, incorporating provisions for electronic transfer of funds, to "Conversion, Programming, Implementation, Documentation & Acceptance Processing of IFMIE."

 * Technassociates, Inc. HogAdN.T.F Division of Contracts NRC-10-81-359, 83/12/14 2pp. 22092:320
- 84D20A0514 Natification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements." Contractor State of PA UHBEL.D. Technical Assistance Contracts Stanch. FIN B-B356, NRC-2B-B3-607 84/01/26 MCOSCAR,J. Region 1, Office of Director KDTTAN,J. NRC No Detailed Affiliation Given. 1p. 22092:081
- --8402060324 Mod 1, providing funds, changing B&R number & NRC authorized representative, to "Radiation Monitoring Program Requirements," Requirements,"

 Pennsylvants, Commonwealth of, QUSTAVE,R.P.
 Contracts. FIN B-8354, NRC-28-83-607. 84/01/2/ AVE,R.P. Division of 84/01/26, ip, 2209: 22072.082
- B402040515 Notification of contract execution; Mod 11 to "Card-Entry Access Control Bys." Contractor, Vikonics, Inc.
 OILDENHIORN, A. J. Administrative Contracts Branch NRC-10-B2-399
 84/02/18. BRADY, R. J. Division of Bscurity. FINGER, R. NRC -- No Detailed Affiliation Given, ip. 22092; 316,
- -8402060520 Mod 11.changing alarm delay times, increasing contract amount & extending period of performance to 840216, to "Card Entry Access Control Sys." BURNBAUM L. Vikonics. Inc HAOAN.T.F. Division of Contracts NRC-10-82-399 84/01/18. 2pp 22092:317

- B402060831 Notification of contract exécution.Mod 1 to "Radiation Monitoring Program Requirements" Contractor State of VT UMBEL.D Technical Assistance Contracts Branch FIN 8-8351 NRC-28-83-605 84/01/24 MCDSCAR.J Region 1, Office of Director KOTTAN,J NRC No Detailed Affiliation Given 1p. 22092-141
- --8402060534 Mod 1, providing funds, changing 8&R number & NRC representative, to "Radiation Monitoring Program Requirements" * Vermont, 8tate of GUSTAVE, R P Division of Contracts FIN 8-8351 NRC-28-83-605 84/01/26 1p 22092 142
- 8402060538 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements" Contractor State of MD UMBEL D Technical Assistance Contracts Branch FIN 8-83-53 NRC-28-83-608 84/01/26 MCOSCARJ Region 1. Office of Director KOTTAN. J NRC No Detailed Affiliation Givan ip 22072 137
- --8402060342 Mod 1, providing funds, changing B&R number & NRC authorized representative, to "Radiation Monitoring Program Requirements"

 * Maryland, State of GUSTAVE, R P Division of Contracts FIN B-8353 NRC-28-83-608 84/01/26 ip 22092 140
- B4020A0545 Notification of contract execution.Mod 7 to "Statistical Analysis Study." Contractor SL Wolfbein GILDERHORNA J. Administrative Contracts Branch. NRC-10-80-694 B3712/14 RAGAN.H A Office of the Executive Legal Director. DAMBLY.D NRC No Detailed Affiliation Given 1p 22092 136
- --8402060947 Mod 7, incorporating provisions for electronic transfer of funds to "Statistical Analysis Study" * Wolfbein, 8 L. HAGAN, T F Division of Contracts NRC-10-80-694 83/12/14 2pp R2092 137.
- B402060556 Notification of contract execution, Mod 12 to. "Bite Buitability Assessments Based on Seepage & Groundwater Conditions Associated w/U Recovery Operations " Contractor Williams & Assoc, Inc DELOATCH, V Technical Assistance Contracts Branch NRC-02-Bi-039 B4/01/30 DAVIB, J. Office of Nuclear Material Bafety & Bafeguards, Director. GARCIA, P. NRC - No Detailed Affiliation Given 22092 125
- --B4020A055B Mod 12.extending period of performance to B4022? at no addl cost, to "Bite Buitability Assessments Based on Beepage & Graundwater Conditions Associated W/V Recovery Operations." WILLIAMB; R E Milliams & Associates, GUBTAVE, R P. Division of Contracts. NRC-02-81-037 B4/01/30 ip 22072;126
- 8402050585 Notification of contract execution. Mod 1 "Radiation Monitoring Program Requirements." Contractor: State of TN UMBEL, D Technical Assistance Contracts Branch FIN 8-8401 NRC-29-83-622 84/01/19 MALEYR J Region 2. Office of Director MONTODMERY, D. M NRC No Detailed Affiliation Given 1p
- --8402060889 Mod i,providing funds for CY64 & changing consideration & payment, to "Radiation Monitoring Program Requirements"
 * Tennessee, State of GUSTAVE.R P Division of Contracts, FIN B-8401 NRC-29-83-622, 84/01/19 ip 22092 088
- 8402080612 Notification of contract execution, Mod 2 to "Radiation Monitoring Program Requirements," Contractor State of SC UMBEL, D Technical Assistance Contracts Branch, FIN B-8403 NRC-29-83-624 84/01/26, MALEY, R J Region 2, Office of Director. MONTOUMERY, D M NRC No Datailed Affiliation Given 1p 22092 083 24% Fiche 50-413,84/01/26,8402060612
- --B40206061B Mod 2, providing add1 funds for CYB4 & incorporating environ monitoring for period Jan 1984 Dec 1985, to "Radiation Monitoring Program Requirements."

 ** South Carolina, State of, GUBTAVE, R P Division of Contracts.
 FIN B-8403. NRC-29-83-624 84/01/26 ip. 22092 084 24X
 Fichs: 50-413, 84/01/26, 8402060612
- B402070104 Notification of contract execution, Mod 2 to "Radiation Monitoring Program Requirements" Contractor State of TX UMBEL.D M Division of Contracts FIN 8-8405 NRC-31-83-671 84/01/26. MEYERB.D M Region 4, Diffice of Director NICHOLAS.J B. NRC No Detailed Affiliation Given ip 22142 239.
- --8402070108 Mod 2,providing funding & changing B&R number, to "Radiation Monitoring Program Requirements" " Texas, Btate of QUETAVE.R.P. Division of Contracts. FIN B-8405 NRC-31-83-671 84/01/26. ip 22142,240
- 84G2G70115 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements." Contractor State of DE, UHBEL, D Tachmical Assistance Contracts Branch. FIN 8-8352 NRC-28-893-602. 847G1/26 MCGSGARJ Region 1, Office of Director KETTAN, J. NRC No Detailed Affiliation Given. 1p 22142, 237.

- ~-8402070123 Mod 1.providing funds, changing B&R number & NRC authorized representative, to "Radiation Menitoring Program Requirements" * Dalaware, State of GUSTAVE, R P Division of Contracts. FIN B-8352 NRC-28-83-602 84/01/26 1p 22142 238
- 8402070280 Notification of contract execution.Mod 1 to "Radiation Program Monitoring Requirements" Contractor State of CT UMBEL.D Technical Assistance Contracts Branck FIN B-8358 NRC-28-83-604 84/01/24 MCOSCARJ Region 1, Office of Direc KOTTAN,J NRC No Detailed Affiliation Given 1p 28148 140
- --8402070276 Mod 1, providing funds, changing B&R number & NRC authorized representative, to "Radiation Monitoring Program Requirements"

 * Connecticut, State of GUSTAVE.R P Division of Contracts.
 FIN 8-8358 NRC-28-83-604 84/01/26 1p 22142 141
- B40207029B Notification of contract execution, Mod I to "Radiation Monitoring Program Requirements" Contractor State of MA UMBEL, D M Technical Assistance Contracts Branch FIN B-8350 NRC-28-83-606 B4/01/26 MC05CAR, J Region I, Office of Director KOTTAN, J NRC No Detailed Affiliation Given. 1p 22142 146
- --8402070307 Mod 1, providing funds, changing B&R number & NRC authorized representative to "Radiation Monitoring Program Requirements"
 - everR P Division 64/01/26 in yuirements " Massachusetts, Commonwealth of GUSTAVE,R P Stracts FIN 8-8950 NRC-28-83-606 84/01/; 22142.147
- 8402070315 Notification of contract execution.Mod i to "Radiation Monitoring Program Requirements" Contractor State of NH UMBEL, D Technical Assistance Contracts Branch FIN B-9364 NRC-26-883-611 84/01/26 HCOSCAR, J Region 1, Office of Director KDTTAN, J NRC No Detailed Affiliation Given 1p 22142 142
- ---8402070323 Mod 1.providing funding, changing S&R number & NRC authorized representative to "Radiation Monitoring Program Requirements"
 - quirements " New Hampshirm: State of GUSTAVE,R.P V B-8364 NRC-28-83-611. 84/01/26 1 P Division of Contracts ip 22142 143
- 8402070334 Notification of contract execution.Mod i to "Radiation Monitoring Program Requirements" Contractor State of NC UMBEL.D Technical Assistance Contracts Stanch FIN 8-8406 NRC-27-83-627 84/01/23 MALEY.R J Region 2. Office of Director MONTGOMERY,D M NRC No Detailed Affiliation Oiven ip
- --B402070343 Nod 1, providing funds for CYB4 & changing Article V, to "Radiation Monitoring Program Requirements"

 + North Carolina, State of GUSTAVE, R P Division of Contracts FIN B-B406 NRC-29-83-627 B4/01/23, 1p. 22142 145
- 8402070403 Notification of contract execution. Mod 1 to "Radiation Monitoring Program Requirements" Contractor State of NJ, UMSEL, D Technical Assistance Contracts Syanch. FIN S-8354. NRC-28-83-609 84/01/26 MCDSCAR, J Region 1, Office of Director KOTTAN, J NRC ~ No Detailed Affiliation Given ip 22142 135.
- --8402070418 Mod 1.providing funds changing 8&R number & NRC authorized representative to "Radiation Monitoring Program Requirements"
 - uirements " New Jersey, State of GUSTAVE,R P Division of Contracts FIN 3354 NRC-28-83-607 84/01/26 ip 22142 136 B-8354 NRC-28-83-607
 - 208044B Notification of contract execution, Mod 3 to "Develop icensing Procedures, Performance Objectives & Technical riteria for Disposal of Low Level Haste " Contractor
 - nem-Nuclear Sgs. Inc. Jem-Nuclear Sgs. Inc.
 - 402080460 Mod 3.extending period of performance to 840430.to
 "Develop Licensing Procedures.Performance Objectives &
 Technical Criteria for Disposal of Low Level Waste"
 LEMIS.M S Cham-Nuclear Systems. Inc. QUSTAVE.R P. Division of
 Contracts NRC-02-81-046 83/12/13 Ip 22174 049.
- 3402090474 Notification of contract execution, Mod 2 to "Radiation Monitoring Program Requirements" Contractor: State of LA UMBEL. D M Technical Assistance Contracts Branch, FIN B-8502. NRC-91-83-669. 84/01/24, MEYERB.D. M. Region 2, Office of Director NICHOLAS, J B NRC No Detailed Affiliation Given 1p. 22174.050
 - io2080481 Mod 2, providing funds for CY84 & changing B&R number, to "Radiation Monitoring Program Requirements" *
 * Louisiana, State of GUSTAVE.R P Division of Contracts FIN B-8502 NRC-31-83-669 84/01/24 ip 22174:051,

- 8402080478 Notification of contract execution, Mod 2 to "Radiation Monitoring Program Requirements" Contractor: State of CO UMBEL. D M Technical Assistance Contracts Branch Fin 8-8301 NRC-31-83-668 84/01/26 MEYERS, D M Region 4, Office of Diricky NICHOLAS, J B NRC No Detailed Affiliation Given ip 22174 08
- ~-8402080499 Mod 2.providing funds for CY84 & changing B&R number.to
 "Radiation Monitoring Program Requirements "
 a Colorado, State of GUBTAVE.R P Division of Contracts Fix
 B-8501 NRC-31-83-468 84/01/26 ip 22174 067
- 8402070005 Natification of contract execution, Mod 1 to "Neotertonical Studies of Earthquake Zones in Eastern US " Contractor Univ of South Carolina EDGENORTH, P Division of Contracts FIN B-9287 NRC-04-84-119 B4701/04 BATSON, W Office of Nuclear Regulatory Research, Director SCHMITT, T NRC No Detailed Affiliation Given 19 22189 302
- -8402070013 Mod 1, correcting contract number, accounting data & obligation of funds, to "Neotectonics Studies of Earthquake Zones in Eastern US"
 BECKHAMIJ B South Carolina, Univ of, Columbia, BC, MCRTON.X V
 Bivision of Contracts FIN 8-8287 NRC-04-84-117 84/01/04 y 22187 303
- 8402070023 Notification of contract execution "Neotectonics Studie Earthquake Zones in Eastern US," awarded to Univ of South Carolina EDDEMORTH.P Division of Contracts FIN D-1150. NRC-04-84-116 B3/12/23 BATSON, W Office of Nuclear Regulatory Research. Director SCHMITT.T NRC No Datailed Affiliation Given. 19 20100 256 "Neotectanics Bludles of
- -8402090040 Contract "Neotectonics Studies of Earthquake Zones in Eastern US," awarded to Univ of South Carolina BECKHAM, J S South Carolina, Univ of Columbia, SC MORTON, K Division of Contracts FIN D-1150 NRC-04-84-116 83/12/23 17pp 22189 257 HORTON, K.V.
- 8402090513 Notification of contract execution. Mod 11 to "Field & Theoretical Investigations of Mass Energy Transport in Subsurface Mat1 at Waste Disposal Sites " Contractor Univ of Arizona Arizona Arizona Arizona Contracts Branch Fin 8-3750 NRC-04-78-275 B4/01/24 BATSON, W Office of Nuclear Regulatory Research, Director RANDALL, J NRC - No Detailed Affiliation Glysb 22187
- --B402090326 Mod 11, providing incremental funding action, to "Field & Theoretical Investigations of Mass Energy Transport in Subsurface Matis at Waste Disposal Bites."
 SWENBON, F. A. Arizona State Univ. GUSTAVE, R. P. Division of Contracts FIN 8-5753 NRC-04-78-275 84/01/24. 7pp. 22187 352.
- 8402090945 Notification of contract execution. Mod 1 to "Radiation Monitoring Program Requirements" Contractor. State of VA.
 UMBEL.D Technical Assistance Contracts Branch. FIN 8-8402
 NRC-29-83-623 84/01/19 MALEY.R J. Region 2. Office of Director MONTOUNERTY. D M NRC No Detailed Affiliation Given 1p.
 22191 360
- --B402090548 Mod 1.providing funds for CYB4.to "Radiation Monitoring Program Requirements "
 * Virginia, Commonwealth of.. QUBTAVE,R P Division of Contracts FIN B-8402 NRC-29-83-623, 84/01/19 Ip. 22191:361
- 8402090583 Notification of contract execution, Mod 7 to "Southern Appalachian Regional Spismic Network" Contractor Memphis State Univ JACOSB, A Technical Assistance Contracts Branch. FIN 8-6675. NRC-04-79-214 B4/01/30. BATSON W. Office of Nuclear Regulatory Research. Director, MURPHY, A NRC No Detailed Affiliation Givan ip. 22191:138
- --8402090592 Mod 7, providing incremental funding action & extending period of performance to 841130, to "Southern Appalachian Regional Seismic Network"

 CARPENTER, T. G. Hemphis State Univ., Memphis, TN. QUSTAVE, R. P. Division of Contracts, FIN 8-6675 NRC-04-79-214 84/01/30. Sep. 22191; 139
- B402100089 Notification of contract execution, Mod 2 to "Radiation Monitoring Program Requirements" Contractor State of AR. UMBEL. D M Technical Assistance Contracts Eranch FIN 8-8500. NRC-01-83-667. 84/01/26 MEYERS, D M Region 4, Office of Dir. NICHOLAS, J B NRC No Detailed Affiliation Given ip. 2220 # Director 22205.083
- --8402100093 Mod 2.providing funds for CY84 & changing B&R number.to
 "Radiation Monitoring Program Requirements."
 * Arkansas, State of OUSTAVE.R P Division of Contracts FIN B-8500 NRC-31-83-667 84/01/26 ip 22205,084.

- 8402100354 Notification of contract execution, Mod 7 to "Unsaturated Flow & Transport Through Fractured Rock " Contractor Univ of Arizona JACO85, A Technical Assistance Contracts Branch FIN 8-7291
- JACOBS: A Technical Assistance Contracts Branch FIN 8-7291 NRC-04-81-224 84/01/23 BATBON: W Office of Nuclear Regulatory Research, Director. NICHOLSON, T NRC - No Detailed Affiliation Given 1p 22207 333
- 84021003B0 Notification of contract execution, Mod 5 to "Definition of Bounding Physical Tests Representative of Transport Accidents Air & Marine " Contractor IIT Research Inst UMSEL, D. Technical Assistance Contracts Branch FIN B-7570 NRC-04-B1-203 84/01/30 FOREHAND B Office of Nuclear Regulatory Research, Director LAHS, W NRC No Detailed Affiliation Given ip 22207 299
- ---B402100382 Mod 5, extending period of performance to 840228 at no addl cost, to "Definition of Bounding Physical Tests Representative of Transport Accidents Air & Marine " * IIT Research Inst GUSTAVE, P Division of Contracts FIN B-7570 NRC-04-81-203 84/01/30 1p 22207 300
- 84021003B7 Notification of grant execution, Mod 4 to "Btructural Osology in Vicinity of Shawnestown Fault Zone, Southeastern IL." Grantss Univ of Illinois URBEL, D. Technical Assistance Contracts Branch FIN 0-101B NRC-0-04-BI-016 B4/02/02 BATEON, W Office of Nuclear Regulatory Research, Director, D'DONNELL, E NRC No Detailed Affiliation Given ip 82205-361.
- --8402100391 Mod 4, providing addl funds & extending period of performance to 850430, to "Structural Geology in Vicinity of Bhawneetown Fault Zone, Boutheastern IL "
 BAZZANI, C S. Illinois, Univ of, at Chicago Circle MURTON, K V
 Technical Assistance Contracts Branch FIN 9-1018
 NRC-9-04-81-016, 84/02/02 ip 22205,362
- 8402100411 Notification of contract execution, Mod 2, to "Monitoring Use of Equipment Purchased by NRC Under Contract NRC-04-74-187."
 Contractor, GARD, Inc
 HOLLETT, B Technical Assistance Contracts Branch NRC-04-82-023
 84/01/13 FOREHAND, B Office of Nuclear Regulatory Research,
 Director. MUSCARA, J NRC No Detailed Affiliation Given. 1p.
 22208: 309
- --B402100415 Mod 2, changing contractors name from Gard, Inc to GATX Corp. QARD Div & recognizing successor interest to "Monitoring Use of Equipment Purchased by NRC Under Contract NRC-04-74-187" BA10H.P A Gard, Inc GUSTAVE.R P Division of Contracts. NRC-04-B2-023. 84/01/13, 1p. 22208.310
- 8402100441 Notification of contract execution, Mod 4, to "Coordination of Cooperative Organizations Participating in Osological, Geophysical & Beismological Studies "Contractor Bt Louis Univ JACD89, A. Technical Assistance Contracts Branch. FIN B-7242 NRC-04-80-227 84/01/25. BASTON, W Office of Nuclear Reactor Regulation, Director. WASTLER, B NRC No Detailed Affiliation Given. 1p. 22213-038
- --B402100456 Mod 4, extending period of performance to B4110B, to "Coordination of Cooperative Organizations Participating in Gaological Geophysical & Beismological Studies" STAUDER, S. J. St. Louis Univ., St. Louis, MO. GUSTAVE, R. P. Division of Contracts FIN 8-7242 NRC-04-80-229, 84/01/2022pp. 22213:039.
- 8402100450 Notification of contract execution, Mod 8, to "Geotchnical Engineering Case Review" Contractor, US Dept of Army, Corps of Engineers
 DELOATCH, V. Technical Assistance Contracts Branch. NRC-03-79-167
 83/10/19 VOLLMER.R. H. Division of Engineering LEAR, G NRG No Detailed Affiliation Given 1p 22213, 036.
- --8402100462 Mod B. extending period of performance to 840330, to "Qeotechnical Engineering Case Review."
 RYAN, R. H. Army, Dept. of, Corps of Engineers GUSTAVE, R. P. Division of Contracts. NRC-03-79-167. 83/10/19 ip. 22213.037
- 8402100487 Nutification of contract execution, Mod 3, to "Panel Member & Documentation Review for Selected Meetings of Peer Review Group." Contractor W Kastenburg TOWNSEND.B. L. Furchasing Section FIN B-8990 NRC-04-83-015. 84/02/02. BASSETT, O E Division of Accident Evaluation (Pre 24001). JANKOWSKI, M. H. NRC No Detailed Affiliation Given. 1p 22213:043.

- --B402100493 Mpd 3.extending period of performance to 840301 & increasing funding, to "Panel Member & Documentation Review for Selected Maetings of Peer Review Oroup"

 KASTENBEROW Kastenberg, W E REBELLO, J E Division of Contracts FIN 8-8990 NRC-04-83-019 84/02/02 1p 22213 044
- 8402130037 Notification of contract execution.Mod 7, to "Demographic Projections & Regional Economic Impacts of Accidents "
 Contractor US Dept of Commerce.
 PAGE.M Technical Assistance Contracts Branch NRC-03-82-112
 84/01/13 VOLLMER.R H Division of Engineering SINISGALLI.A NRC
 No Detailed Affiliation Given 1p 22213 315
- --B402130041 Mod 7.madifying statement of work to revise rept delivery schedules,to "Demographic Projections & Regional Economic Impacts of Accidents" KNDX:H Commerce, Dept of, GUSTAVE,R P Division of Contracts NRC-03-B2-112 B4/01/13 1p 22213 316
- 8402130074 Notification of contract execution, Mod 18, to "Technical Assistance in Bupport of NRC Reactor Licensing Actions, Program 2 " Contractor Science Applications, Inc PAGE: M Technical Assistance Contracts Branch FIN 8-8011 NRC-03-82-094 84/01/27 EISENHUT, D Division of Licensing ip 22213 311
- --8402130087 Mod 18.providing incremental funding & changing performance avaluation board members, to "Technical Assistance in Bupport of NRC Reactor Licensing Actions.Program 2"

 * Science Applications, Inc. GUSTAVE, R P Division of Contracts FIN 8-8011 NRC-03-82-096 64/01/27, 2pp 22213 312
- 8402130078 Notification of grant exection.Mod 1.to "Study of Radionuclide Release from Severe Accidents at Nuclear Power Plants," Grantee APS UMBEL.D M Technical Assistance Contracts Branch FIN 0-1051. NRC-0-04-83-011 84/02/04 BATSON,W Office of Nuclear Regulatory Rosearch, Director, SILBERDERG,M NRC - No Detailed Affiliation Given ip 22213-307
- ---B402130104 Mod 1.increasing funds to "Btudy of Radionuclide Release from Bavere Accidents at Nuclear Power Plants" * American Physical Bociety MORTON, K V Technical Assistance Contracts Branch FIN 9-1051 NRC-9-04-83-011 84/02/04 ip
- 8402130130 Notification of grant execution, Mod 1, to "Geometric Analysis of Ensemble of Solutions in Two-Phase Flows & Complete Resolution of Problem Chocking " Grantee Brown Univ UffBEL, D Technical Assistance Contracts Branch FIN 8-1056 NRC-9-04-83-013 84/02/02 BATEON, W Office of Nuclear Regulatory Research, Director ZUBER, N NRC No Detailed Affiliation Given ip 22216 352
- --B402130141 Mod 1, adding funds for FYB4, to "Geometric Analysis of Ensemble of Balutions in Two-Phase Flows & Complete Resolution of Problem Chacking "

 * Brown Univ., Providence, RI MORTON, K V Technical Assistance Contracts Branch FIN B-1056 NRC-9-04-83-013 84/02/02 ip 22216 353
- B402130359 Notification of contract execution.Mod 1.to "Present Paper Entitled 'Biaxial Loading Effects on Growth of Cracks '" Contractor.Bhaffield Univ. TOWNSEND.B L Purchasing Bection FIN B-6995 NRC-04-83-166 B4/02/06 BASBETT.O Division of Accident Evaluation (Pre 840101) WALKER.T. J NRC - No Detailed Affiliation Given ip 22216 105
- --8402130562 Mod 1, providing for travel reimbursement, to "Present Paper Entitled 'Biaxial Loading Effects on Growth of Cracks '" BROWN.M W Sheffield, Univ of, Sheffield, UK RESELLO, J E Division of Contracts FIN 8-8975 NRC-04-83-166 84/02/06 ip 22216 106
- 840214003D Notification of contract execution "Maint & Operation of LPDR," awarded to Washington Univ HOPPER, A Purchasing Section NRC-10-84-252 84/02/06 FELTON, JM Division of Ruises and Records BOUDER, JL NRC No Detailed Affiliation Oiven 2pp. 22251 323
- --8402140034 Contract^{*} "Maint & Operation of LPDR," awarded to Washington Univ. POLMAR, B. K. Washington Univ. Bt Louis, MO REBELLO, J E Division of Contracts. NRC-10-84-252 84/02/04 14pp 22251 325
- 8402150415 Notification of contract execution "Disc Drive Upgrade Syc," awarded to Data Consultants, Inc COLEMAN, R Administrative Contracts Branch FIN B-8887 NRC-33-84-381 84/02/06 BASETT, H B Division of Data Automation & Management Information JOHNSON, C. NRC No Detailed Affiliation Given ip 22263, 314

- --9402150417 Solicitation.offer & award.of "Disc Drive Upgrade Svc" awarded to Data Consultants.Inc # Data Consultants, Inc MATTIA.M J Division of Contracta FIN B-8887 NRC-33-84-381 84/02/09 20pp 22263 315
- 8402180516 Notification of contract execution "Technical Assistance to Support IE Personnel in Integrated Design Insps." awarded to Wester Sycs.Inc EDGEWORTH.P Technical Assistance Contracts Branch NRC-05-84-151 84/01/24 MUR.A. Director's Office. Office of Inspection and Enforcement MILHOAN.J NRC No Detailed Affiliation Given. 1p 20298 240
- --8402150524 Ltr Contract NRC-05-84-151. "Technical Assistance to Support IE Personnel in Integrated Design Insps." awarded to Hestec Svcs.inc MORTON, K V Technical Assistance Contracts Branch. NRC-05-84-151 84/01/23 SARGENT, J H Westreco.Inc 2pp 22257 361
- 8402160026 Notification of contract execution Mod 25.to "Severe Accident Core/Vessel/Containment Interactions "Contractor Purdue Research Foundation FLEENOR,C Technical Assistance Contracts Branch FIN B-8634. NRC-03-83-093 84/01/19. MATTBON,R Division of Systems Integration (post 811005) HARDIN,W NRC No Detailed Affiliation Given 1p 22301:306
- --8402160063 Mod 25, increasing amount of funds obligated & incorporating provisions or authorization of certain direct costs, to "Severe Accident Core/Vessel/Containment Interactions "GREENKORN R A Purdue Research Foundation GUSTAVE: R P. Technical Assistance Contracts Branch FIN 8-8634 NRC-03-83-093 84/01/19 2pp 22301 307
- 8402140682 Notification of contract execution, Mod 3, to "Design Programming, Testing, Training, Implementation & Documentation of Licensing Mgt Bys " Contractor Advanced Technology, Inc PERLIAN, J Technical Assistance Contracts Branch FIN B-1007~3 NRC-33-83-464 84/02/08 BASSETT. Bly Sidn of Data Automation & Management Infermation, MACHILLIAMS.** NRC No Detailed Affiliation Given 1p. 22272 341
- --8402160683 Mod 3, adding adding over furnished property, to "Design Programming, Testing, Training, Implementation & Documentation of Licensing Mgt Bys"
 LOTITO, HA Advanced Technology, Inc HAGAN, T.F. Division of Contracts FIN 8-1007-3 NRC-33-83-444 84/02/08 ip
- B4021606B4 Notification of contract execution.Mod G.to "Review, Abstract, Index & Guarterly Update Practice & Procedure Digest "Contractor, Aspen Sys. Inc. PERLMAN, J. Technical Assistance Contracts Branch FIN B-1586 NRC-14-B2-44B B4/02/07 CUNNINGHAM, G H Office of the Executive Legal Director GRAY, J. NRC No Detailed Affiliation Given. 1p. 20290 338
- --8402140685 Mod 3, extending period of performance to 840227 & adding addl funds to "Review Abstract Index & Quarterly Update Practice & Procedure Digest."

 BRANNOCK, E. A. Aspen Systems, Inc. HAGAN, T. F. Division of Contracts. FIN B-1588 NRC-14-82-448. 84/02/07. 2pp. 22272, 339
- 8402160686 Notification of contract execution, "IM9/IBAS Bys Support" awarded to SBA Subcontractor Wilson Hill Assor, Inc. HA0EY,H A Technical Assistance Contracts Branch FIN D-1211. NRC-33-84-378 84/01/31. BABSETT-M.S. Management Information Branch. BADINI, J. B. NRC No Detailed Affiliation Given ip 22292-301
- ---B402160688 Contact: "IMB/IDAS Sys Support" swarded to SBA
 Subcontractor, Wilson Hill Assoc, Inc
 # Small Business Administration. # Hilson Hill Associates, Inc
 HATTIAN J Division of Contracts FIN D-1211 NRC-33-B4-378.
 84/01/31. 36pp 22272 302.
- 8402170008 Notification of contract execution. Hod 5 to "Sys Analysis & Program Support Sycs." Contractor SBA. Subcontractor Logical Technical Sycs Corp.
 MCLEAREN.T Administrative Contracts Branch. FIN D-8803
 NRC-33-83-453, 84/01/31 BARRY.L : HARVES.J. Office of Resource Hanagement, Director. 1p 22319:150
- --B402170012 Mod 5.extending period of performance to B50102, increasing contract calling & changing contracting officer authorized representative to "Sys Analysis & Progrew Support Sycs." ROSERS, A. A Small Business Administration GREENLES & Logical Technical Bervice Corp. HAGAN, T.F. Division of Contracts. FIN B-8803 NRC-33-83-453. B4/01/31 7pp 22319:151

- 8402170014 Notification of contract executive, Mod A to "Sys Analysis a Program Support Svcs " Contractor 88A Subcontractor:Logical Technical Svcs Corp MCLEAREN, T Administrative Contracts Branch NRC-33-83-459 84/01/02 BARRY, L, HARVEB, J Office of Resource Management, Director 1p 22319 139
- --8402170016 Mod 4.extending period of performance to 840202, to "Eyi Analysis & Program Support Eyes" ROBEE.E C. Small Business Administration QREENLEE.E A Logical Technical Envice Corp HAGAN, T F Division of Contracts NRC-33-83-453 84/01/02 2pp 22319 140.
- 8402170017 Notification of contract execution, Mod 4, to "Electrostatic Copying & Related Svcs " Contractor Literature Research Co. PERLMAN. J Administrative Contracts Branch NRC-10-83-318 84/02/08 BESAN.W J. BAGGETTM Division of Technical Information & Document Control 19 22319 127
- --8402170030 Hod 4.exercising option to extend period of performant; to 850209, to "Electrostatic Copying & Related Svcs" + Literature Research Co HAGAN.TF Division of Contracts NRC-10-83-418 84/02/08 ip 22319.128
- 8402170029 Natification of contract execution, Mod 1, to "Selection of Earthquake Resistant Design Criteria for Nuclear Power Plants, Methodology & Technical Bases "Contractor Structural & Earthquake Engineering Consultants, Inc JACOBS, A Technical Assistance Contracts Branch FIN 8-8290 NRC-04-83-022, 84/02/01 BATBON, W Office of Nuclear Regulatory Research, Director MURPHY, A NRC No Detailed Affiliation Glysh ip 22312 311
- --8402170031 Mod 1.increasing funding to "Belection of Earthquake Resistant Design for Nuclear Power Plants, Methodology & Technical Bases" LUCD, J.E. Structural & Earthquake Engineering Consultants QUBTAVE.R.P. Technical Assistance Contracts Branch FIN 8-8298 NRC-04-83-022, 84/02/01 1p 22312 312
- 8402170062 Notification of contract execution Mod 1 to "Reviewing Hydrogeologic Investigations of Badded & Dome Salt Basins Project A " Contractor Hilliams & Assoc FLEENOR, C. Technical Assistance Contracts Branch, NRC-02-83-031 84/01/17 DAVIS.J. Office of Nuclear Material Safety & Safeguards, Director CODKE, B NRC No Detailed Affiliation Given ip. 22312-357
- ~-B402170065 Mod 1, revising key personnel availability & appointing my project officer, to "Reviewing Hydrogeologic Investigations of Bedded & Dome Balt Basins Project A."

 WILLIAMS.R € Williams & Associates QUBTAVE, R. P Division of Contracts NRC-02-83-033 84/01/19 ip. 82312:358.
- B402170147 Notification of contract execution, Mod 8, to "Publication Distribution & Inventory 8vcs " Contractor Computer Data 8ys, Inc 07LDEMHORN, A J Administrative Contracts Branch. NRC-10-83-332 84/02/03 BESAN, W J Division of Technical Information & Document Control 8CHAEFFER, C NRC No Datailed Affiliation Given 19 22313:286
- --8402170150 Mod 8, extending period of performance to 850207 & increaling funds, to "Publication Distribution & Inventory Sycs "

 * Computer Data Systems: Inc HOSANT, F. Division of Contraction NRC-10-83-032 84/02/03 1p. 22303:287.
- 8402170154 Notification of contract secution, Mod 4, to "NRG Procurament Training for Project Officers " Contractor: Oraduate School, USBA PERLMAN, J. Administrative Contracts Branch. NRG-10-81-40R. B4/02/07 DORIE. W Office of Administration. BASBIN, C. NRC W Detailed Affiliation Given 1p 22313-282
- --8402170158 Mod 4, increasing funds & clarifying nature of orientation workshops in DOE agreements for sycs, to "NRC Procurement Training for Project Officers"

 VARNER, L B Agriculture, Dept. of HAGAN, T.F Division of Contracts. NRC-10-81-402. 84/02/07. 3pp 22313:283.
- B402170225 Notification of contract executive, Mod 3, to "Panel Hember be Documentation Review for Selected Meetings of Peer Review Group" Contractor, Rowe Assoc TOWNSEND, B. L. Purchasing Section FIN B-8968 NRC-04-83-007. B4702702 BASSETT, C. E. Division of Accident Evaluation (Preserved Medical). JANKOWSKI, M.W. NRC No Detailed Affiliation Given. 1) #2213-258.
- --B402170230 Mod 3, extending period of performance to B40301 & incressing funds, to "Panel Member & Documentation Review of Selected Meetings of Peer Review Group"
 ROME, D S Rowe Associates RESELLO, J E Division of Contracts
 FIN 8-8968, NRC-04-83-007, B4/02/02, ip. 22313 259

- 8402170239 Notification of contract execution.Mod 3, to "Panel Member & Documentation Review for Seclected Meetings of Peer Review Group." Contractor LR Zumwalt
- --8402170245 Mod 3, extending period of performance to 840301 & increasing funds, to "Panel Member & Documentation Review for Selected Mestings of Peer Review Group"
 ZUMMALT, I. R ZUMWALT, I. R REBELLO, J E Division of Contracts
 FIN 8-8784 NRC-04-83-007 84/02/02 1p 22313 251
- BAO2170253 Notification of contract execution "Telecommunications Evaluation, Operations Requirement & Specs for Various Communications Bys for NRC Region I," awarded to BDA Subcontractor KCH Bys. Inc FLYNN-H J Technical Assistance Contracts Branch NRC-10-84-254 B4701/31 CORLEY, J H Division of Facilities & Operations COHEN, 8 NRC No Detailed Affiliation Given ip 22320 271 NRC-10-84-254
- --8402170268 Contract "Telecommunications Evaluation, Operations Requirements & Specs for Various Data Communications Sysfor Region I 4 r Hagion I " Bmall Susiness Administration KOH.Y KOH Bystems, Inc LL.D Division of Contracts NRC-10-84-254 84/01/31 18pp 22320, 272
- B402170476 Notification of contract execution.Mod 1, to "Addl Tasks for Development of Automated Matl Accounting Statistics Sys (AMASS)." Contractor NUBAC Inc., JACOSS, A Technical Assistance Contracts Branch FIN B-7380-3 NRC-02-83-028, 84/02/09 DAVIS, J. Office of Nuclear Material Safety & Safeguards, Director. MILLER, M NRC No Detailed Affiliation Givan 1p. 22305 340.
- --B4021704B4 Mod 1, changing schedule of deliverables, to "Add1 Tasks for Development of Automated Mat1 Accounting Statistics Bys (AMABB)." (AMABB), " LUMB, R. F. NUBAC, Inc QUBTAVE, R P Division of Contracts, FIN B-7380-3, NRC-02-83-028 84/02/09 2pp 22305 341.
- 8402210002 Notification of contract execution, Mod 3, to "Nemaha Ridge Seismograph Network" Contractor, Univ of Oklahoma JACOBB, A Technical Assistance Contracts Branch, FIN B-8136 NC-04-82-006, 84/01/27, BATBON, W. Office of Nuclear Reactor Regulation, Director SURFLVEH, E NRC No Detailed Affiliation Given, 1p. 22323, 310,
- --B402210014 Ltr Contract NRC-04-B2-006-01, Mod 3, increasing funding to "Nemaha Ridge Beismograph Network."

 GUSTAVE, R P Technical Assistance Contracts Branch. FIN B-8136 NRC-04-B2-006 B4/01/27 ANTHONY.T C., GUINN.B Oklahoma. Univ. of. Norman, OK ip 22323 311.
- 8402210022 Notification of contract execution: "Btructural Integrity of LWR Boundary Components II," awarded to Matls Engineering
 - LWR Boundary Components 11, "awarded to matts engineering Assoc, Inc.
 EDGEMORTH, P. Technical Assistance Contracts Branch, NRC-04
 84/01/16, BATBON, W. Office of Nuclear Regulatory Research,
 Director, VADINS, M. NRC No Detailed Affiliation Oiven,
 22323-313,
- -8402210025 Ltr Contract NRC-04-84-102, "Structural Integrity of LWR Boundary Components II," awarded to Matls Engineering Assoc. Inc. MCRTON.X.V Technical Assistance Contracts Branch NRC-04-84-102 84/01/16 OREENBLATT, M Materials Engineering Associates, Inc 22323:314.
- 8402210030 Notification of contract execution, Mod 13, to "Technical Assistance in Respository Design " Contractor, Golder Assoc, Inc.
- UMBEL,D. Technical Assistance Contracts Branch, FIN B-6983, NRC-02-81-037, 84/02/06 DAVIS.J. Dffice of Nuclear Material Safety & Safeguards, Director. BUCKLEY,J NRC No Detailed Affiliation Given. ip. 22323;327.
- ---8402210039 Mod 13.providing addl funds to cover cost of labor overhead & rate adjustments, to "Technical Assistance in Repository Design." Design."
 PERFTZ.D.L. Golder Associates. MARTON.K.V. Division of Contracts
 FIN B-6983, NRC-02-81-037, 84/02/06, 1p. 22323;328,
- 8402210032 Notification of contract execution. "Fire Protection Review & Evaluation: " swarded to Factory Mutual Research. UMBEL.D. Technical Assistance Contracts Branch NRC-03-82-093-05 83/12/27. VOLLMER.R. Division of Engineering. FERGUSON, R. NRC No Detailed Affiliation Given is 22323:321.

- --- 8402210041 Contract "Fire Protection Review & Evaluation," awarded to Factory Mutual Research
 MARSH.W B Factory Mutual Research Corp MORTON.K V Division of
 Contracts NRC-03-82-093-05 83/12/27 5pp 22323 322
- 8402210037 Notification of contract execution, Mod 8, to "Performance of Engineered Barriers in Geologic Repository " Contractor Engineered Uarriers in Geologic Repository " Contractor Golder Assoc.Inc UMBEL,D Technical Assistance Contracts Branch B-6486-4 NRC-02-81-027 84/02/06 DAVIS.J Defice of Nuclear Material Safety & Bafeguards, Director FITTIGLIO.L NRC - No Detailed Affiliation Given ip 22323 319
- -8402210054 Mod B, obligating funds for overhead rate adjustments to "Performance of Engineered Barriers in Geologic Repository " PENTZ.D L Golder Associates MORTON, K V Division of Contrac
 - Galder Associates MORTON, K V Division of Contracts --4 NRC-02-81-027 84/02/04 10 22323 320 FIN B-6986-4
- 840221003B Notification of grant execution "Preliminary Procedures for Calibr of Bhort Circuit Currents in Electrical Penetration Assemblies," awarded to Tuskegee UMBEL. D UMBEL.D Technical Assistance Contracts Branch FIN 0-1059 NRC-0-04-04-003 84/02/13 BATSDN.W Office of Nuclear Regulatory Research, Director SULLIVAN.D NRC - No Detailed Affiliation Given ip 22323 316
- --8402210044 Grant "Preliminary Analysis of Procedures for Calibr of Short Circuit Currents in Electrical Penetration Assemblies," awarded to Tuskegee Inst WILLIAMS,L. A. Tuskegee Institute, Tuskegee, AL. MORTON,K.V. Technical Assistance Contracts Branch. FIN 0-1057 NRC-G-04-84-003 84/02/13 2pp 22323-317
- 8402210045 Notification of contract execution Mod 1, to "Licensing Assistance/Opotechnical & Hydrological Evaluations/URFD " Contractor, Opodson & Assoc. Inc UMBEL.D. Technical Assistance Contracts Branch FIN B-8507 NRC-31-83-673 84/02/13, SMITH.R D Uranium Recovery Field Office GARCIA.P NRC No Detailed Affiliation Given 1p 22321 361
- --8402210060 Mod i,changing contract & B&R numbers & adding addl funds for FY84,to "Licensing Assistance/Geotechnical & Hydrological Evaluations/URFO" * Goodson & Associates, Inc GUSTAVE,R P Division of Contracts FIN B-8507 NRC-31-83-673 84/02/13 ip. 22321,362
- 8402210085 Notification of contract execution "Effects of Mfg Processes on Failure of High Level Waste Containers," awarded to Mfg Sciences Corp BAISDEN.L Technical Assistance Contracts Branch FIN 8-7278 NRC-04-84-121. 84/02/13 BATSON.W Office of Nuclear Regulatory Research. Director MCNEIL, M NRC No Detailed Affiliation Given 1p 22323 161
- --8402210088 Contract "Effects of Mfg Processes on Failure of High Level Waste Containers," awarded to Mfg Briences Corp FLOYD, P R Manufacturing Sciences Corp MORTON, K V Division of Contracts FIN B-7278 NRC-04-84-121 84/02/13 27pp 22323:160
- 8402210195 Notification of grant execution, Mod 3, to "Thermal-Hydraulic Transients Behavior of Coolant in Simulated Reactor Coop " Grantee Univ of Maryland, UMBEL, D M Tachnical Assistance Contracts Branch Fin 9-1043, NRC-9-04-82-013 84/02/13 BATSON, W Office of Nuclear Regulatory Research, Director YOUNG, M NRC No Detailed Affiliation Given Research, Director 1p 22344 042
- ---8402210138 Mod 3.providing addl funds.to "Thermal-Hydraulic Transients Behavior of Coolant in Bimulated Reactor Coop " CABHMAN.D.C. Maryland, Univ of, Collage Park, MD MORTON,K V Technical Assistance Contracts Branch FIN 9-1043 NRC-9-04-82-013 84/02/13 1p 22344 043
- B402210166 Notification of grant execution, Mad 1.to "Criteria & Procedures for Low Level Radwasts Mgt " Grantse Conference of Radiation Control Program Directors.Inc.
 UMBEL.D Technical Assistance Contracts Branch FIN 9-1049,
 NRC-9-04-83-005 84/02/13. BATBON.W Diffice of Nuclear Regulatory Research, Director. KIM, K NRC No Detailed Affiliation Given 1p 22946 070.
- --8402210172 Mod 1.increasing funds for FYB4, to "Criteria & Procedures for Low Level Radwaste Mgt." HARDIN: C M Conference of Radiation Control Program Directors, Inc. MDRTON, K V Technical Assistance Contracts Branch. FIN G-1049. NRC-Q-04-83-005 84/02/13 ip. 22346-071

- 8402210347 Notification of contract execution, Mod 1, to "IMS/IDAS Bys Support," awarded to SBA Subcontractor Wilson Hill Assoc, Inc GILDENHORN, A J Administrative Contracts Branch FIN D-1211 NRC-33-84-378 B4/01/25 BASSETT, HS Division of Data Automation & Management Information BADINI, JB NRC No Detailed Affiliation Given to 22323 343
- --8402210351 Mod i, making administrative changes, to "IMS/IDAS 8ys Support" * Small Business Administration * Wilson Hill Associates, Inc HAGAN.TF Division of Contracts FIN D-1211 NRC-33-84-378 84/01/25 2pp 22323 344
- 8402210363 Notification of contract execution, Mod 3.to "Penel Member & Documentation Review for Selected Meetings of Peer Review Group "Contractor Univ of Virginia TOHNSEND.B L Purchasing Section FIN B-8783 NRC-04-83-010 84/02/02 BASSETT.O & Division of Accident Evaluation (Pre 840101) JANKOHSKI, M H NRC No Detailed Affiliation Given 1p 22323 341
- --8402210369 Mod 3.extending period of performance to 840301 & increasing funds, to "Panel Member & Documentation Review for Selected Neetings of Peer Review Group "
 REYNOLDS, A B. Virginia, Univ of, Charlottesville, VA
 REBELLO, J E Division of Contracts FIN B-8995 NRC-04-83-010
 84/02/02 ip 22323 342
- B40R2i04i9 Notification of contract execution, Mod 7, to "Assessment of Waste Retrieval Alternatives," Contractor Engineers Intl.
 Int
 FLEENOR, C Technical Assistance Contracts Branch NRC-02-82-03i
 84/01/26 DAVIS, J Office of Nuclear Material Safety &
 8afeguards, Director TikTINSKY, D NRC No Detailed Affiliation
 Given ip 22983 337
- --8402210439 Mod 7.extending period of performance to 840309 at no add1 cost, to "Assessment of Waste Retrieval Alternatives " 'SINGH.M N Engineers International, Inc. GUSTAVE.R P Division of Contracts NRC-02-82-031, 84/01/26 ip 22323,338.
- 8402210464 Notification of contract execution, Mod 4, to "Nemaha Ridge Beisnographic Network." Contractor Univ of Kansas. JACOBB. A Technical Assistance Contracts Branch FIN B-8272 NRC-04-82-006 84/01/31 BATSON.W Office of Nuclear Reactor Regulation, Director. SURFLUEH.E NRC - No Datailed Affiliation Given 1p 22344 044
- --B402210476 Ltr Contract NRC-04-82-006-02, Mod 3, increasing funding action, to "Nemaha Ridge Seismographic Network"
 GUSTAVER P Technical Assistance Contracts Branch FIN B-8272
 NRC-04-B2-006 84/01/31 HALLEMBECK, C, CROSS, C A Kanses State Univ , Hanhattan, KS 1p 22344 045
- 8402230269 Notification of contract execution, Mod 5, to "Model Documentation & In-House Training for Unsaturated Flow & Transport Modeling "Contractor. Hater, Waste & Land.
 FLEEMOR.C Tachnical Assistance Contracts Branch NRC-02-83-030. 84/01/24 DAVIS. J Dffice of Nuclear Material Sefety & Safeguards. Director WIDMAYER, D. NRC No Detailed Affiliation Given ip 22380 013
- --8402230272 Mod 5, extending period of performance to 840301 at no cost, to "Hodel Documentation & In-House Training for Unsaturated Flow & Transport Modeling."

 BAVIS: A Water, Waste & Land, Inc OUSTAVE, R Division of Contracts NRC-02-83-030 84/01/24 1p 22380 014.
- 8402230272 Notification of contract execution.Mod 5.to "Keypunch & Verification Svc." Contractor SBA Subcontractor Info Sys & Networks Corp BROMERG.B J Administrative Contracts Branch FIN B-8158 NRC-25-82-918 84/02/09 BASSETT.H Division of Data Automation & Management Information KING.M NRC No Detailed Affiliation Given ip. 22371 266
- --8402230293 Mod 5, increasing funds, to "Keypunch & Verification Byc "

 * Small Business Administration. * Information Bystems & Network Corp HAGAN, T. F. Division of Contracts FIN 8-8158 NRC-25-82-318 84/02/09. ip 22371 267
- 8402230294 Notification of contract elecution Mod 4, to "Reorganizing & Purging of Safety Reactor Files at FDR & ACRB " Contractor: SBA Bubcontractor: Lebat-Anderson.Inc MCLEAREN.T Administrative Contracts Branch. NRC-10-83-722 84/02/15. BESAM.W J Division of Technical Information & Document Control. ,8KOCZLAS.J NRC No Detailed Affiliation Given ip. 22371 264

- --8402230295 Mod 4, increasing total amount obligated under contract, to "Reorganizing & Purging of Safety Reactor Files at PDR & ACRS" * Small Business Administration * Labat-Anderson, Inc HAGAN, I F Division of Contracts NRC-10-83-722 84/02/15 15 22371 245
- 8402230445 Notification of contract execution, Mod 4, to "Long-Term Performance of Matls Used for High Level Waste Packaging." Contractor Battelle Columbus Labs PAGE,M Technical Assistance Contracts Branch FIN 8-6764 NRC-04-82-015 84/02/16 PATSON.W Office of Nuclear Regulatory Research, Director KIM,K NRC No Detailed Affiliation Given 1p 22376 064
- --8402230446 Mod 4 providing incremental funds to "Long-Term Performants of Matla Used for High Level Waste Packaging"

 * Battelle Memorial Institute. Columbus Laboratories
 OUSTAVE.R P Division of Contracts FIN 8-6764 NRC-04-82-015
 84/02/16 ip. 22376 065
- 8402240228 Notification of contract execution, Mod 4, to "Review, Abstract, Index & Guarterly Update Practice & Procedure Digest " Contractor Aspen 894, Inc. PERLIMAN.J Technical Assistance Contracts Branch. FOM 9-1588 NRC-14-82-448 84/02/16 CUNNINGHAM.Q H. Office of the Executive Legal Director GRAY, J NRC No Detailed Affiliation Given 19. 22381 278
- --8402240231 Mod 4-adding add1 funds, to "Revisu, Abstract, Index & Quarterly Update Practice & Procedure Digest."
 SHINTON D Aspen Systems, Inc. HAGAN, T F Division of Contracts
 FIN B-1888 NRC-14-82-448, 84/02/16. ip 22381,279.
- 8402240254 Notification of contract execution, Mod 18, to "PDR Micrographic Storage & Retrieval Sys " Contractor: Access Corp PERLMAN, J Technical Assistance Contracts Branch, FIN 3-1853, NRC-17-79-449 84/02/12 CHILK, B. J Office of the Secretary of the Commission SCATTOLINI, L NRC No Detailed Affiliation Given. Ip 22381 271
- --8402240254 Mod 18.exercising option through 840731, to "PDR Micrographic Storage & Retrieval Sus." BAKER, N D Access Corp HAGAN, T F Division of Contracts FIN B-8153 NRC-17-79-449 84/02/12 2pp. 22381; 272.
- B40224036B Notification of grant execution, Mod 1, to "Becond Intl Gorbicula Symposium" Orantes: Univ of Arkansas.
 UMBELD. Technical Assistence Contracts Branch. FIN Q-1040
 NRCQ-04-B2-010 B4/02/17 BATBON: W Office of Nuclear Regulatory
 Research: Director. SWANBERG, F. NRC No Detailed Affiliation
 Olven 1p 22380 134
- --8402240371 Mod 1.extanding period of performance to 841231 % changing NRC program officer, to "Second Intl Corbicula Symposium "

 * Arkansas: Univ of, Fayetteville, AR. MORTON, K V Technical Assistance Contracts Branch FIN 0-1040 NRCG-04-82-010.

 84/02/17 1p 22380 137
- 8402240372 Notification of contract execution. Mod 5, to "Definition of Bounding Physical Tests Representative of Transport Accidents Air & Marine." Contractor IIT Research Inst UMBEL, D Technical Assistance Contracts Branch FIN 8-7570, NRC-04-81-203 84/02/09 FOREMAND, B. Office of Nuclear Regulatory Research, Director, LAMS, W. NRC No Detailed Affiliation Given ip 22380:134
- ~~B402240379 Mod 3, extending period of performance to B40228 at no additional cost, to "Definition of Bounding Physical Tests
 Representative of Transport Accidents Air & Marine "
 PLONIS.T,R ITT Research Institute QUBTAVE.R.P. Division of Contracts. FIN B-7570 NRC-04-81-203. 84/02/09 1p. 22380 133
- 8402280578 Notification of grant execution, Mod 2, to "Condensation Rates at Highly Agitated Steam-Water Interfaces." Grantee, MIT. UHBEL, D. Technical Assistance Contracts Branch. FIN 9-1053. NRC-9-04-83-004. 84/02/13 BATSON, W. Office of Nuclear Regulators Research. Director LEE, T. NRC No Detailed Affiliation Given 1p. 22429:143
- --8402280604 Mod 2, providing incremental funding, to "Condensation Rata" at Highly Agitated Steam-Water Interfaces."

 DUMMER, O H Massachusetts Institute of Technology, Cambridge, MA. MORTON, K V Technical Assistance Contracts Branch, FIN 9-1053 NRC-9-04-83-004 84/02/13 ip 22429:144.

- 8402280633 Notification of contract execution.Mod 4.to "Reviewing Hydrogeologic Investigations of Nevada Test Site Project D " Contractor GeoTrans.Inc FLEENUR.C Technical Assistance Contracts Branch FIN 8-7378-4NRC-02-82-047 84/02/13 DAVIS.J Office of Nuclear Material Safety & Safeguards, Director POMLE.J NRC No Detailed Affiliation Given ip 22416 360
- ---B402280642 Mod 4.obigating funds.to "Reviewing Hydrogeologic Investigations of Nevada Test Site - Project D" ROSS.B Geotrans, Inc GUSTAVE.R P Division of Contracts FIN B-7378-4 NRC-02-82-047 B4/02/13 2pp 22416 361
- 8402280670 Notification of contract execution. Mod 14. to "Licensing Technical Assistance " Contractor Science Applications, Inc PAGE.M. Technical Assistance Contracts Branch FIN B-7397 NRC-02-B3-035 84/02/22 DAVIS, J Office of Nuclear Material Safety & Bafeguards, Director LOVSEN, P NRC No Detailed Affiliation Given 1p 22427 001
- --8402280482 Mod 14.definitizing Task Order 8 & increasing funde.to
 "Licensing Technical Assistance"
 FINDLEY, D & Science Applications, Inc GUSTAVE, R P Division of
 Contracts FIN 8-7397 NRC-02-83-035 84/02/22 5pp
 22429.002
- 8402280688 Notification of contract execution, Mod 1, to "In-Situ Stress Measurements in Earth Crust in Eastern US " Contractor Engineers Intl.Inc FLEENRY, C Technical Assistance Contracts Branch FIN 8-8272 NRC-04-83-016 84702/08 BATSON, W Office of Nuclear Material Safety & Safeguards, Director SCHMITT, T. NRC No Detailed Affiliation Given 1p 22414-352.
- --8402280692 Mod 1, providing incremental funding, to "In-Situ Stress Messurements in Earth Crust in Eastern US"

 * Engineers International, Inc. GUSTAVE, R.P. Division of Contracts FIN 8-8292 NRC-04-83-016 84/02/08 2pp 22414:353.
- 8402290376 Notification of grant execution. Mod 1, to "Eighth World Conference on Earthquake Engineering" Orantee Earthquake Engineering Research Inst UMBEL. D.M Technical Assistance Contracts Branch. FIN Q-1058 NRC-9-04-83-010. 84/02/13. BATRON Office of Nuclear Regulatory Research. Director COBTELLO, J NRC No Detailed Affiliation Given. 1p. 22438. 221
- --8402270417 Mod i.increasing funds.to "Eighth World Conference on Earthquake Engineering " PENZIEN.J Earthquake Engineering Research Institute MORTON, K V Technical Assistance Contracts Branch. FIN 9-1038. NRC-9-04-83-010 84/02/13 1p. 22438: 222
- FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES
- B209170054 Requests responses re London Nuclear Con-Dacon solution used on reactor coolant recirculation pumps during sys cleanup DREY, K. Affiliation Not Assigned. B2/09/13. DENTON, H.R. Office of Nuclear Resolution. Director. 2pp 22393, 361 24X Fiche: 50-000.84/02/03.8209170054
- 8401170065 Partial response to FDIA request for six categories of documents re facilities Forwards documents listed in Apps A & B. Documents also available in FDR. W/o App A documents. FELTON. J M Division of Rules and Records 83/10/24 ANDERSON, S I. Garvey, Schubert, Adems & Barer 4pp 21838 003 24X Fiche. 50-397, 83/10/24, 8401170065
- --B401170071 Advises of results of NRC Caseload Forecast Panel visit to plant site during B11021-23 Estimated const completion date for Unit 1 is Feb 1986, Unit 4 not included in evaluation.
 TEDESCO.R L Assistant Director for Licensing 81/12/08, FERGUSON.R L, Washington Public Fower Supply System, 3pp. 21838 007. 24X Fiche 50-397,83/10/24,8401170065.
- --8401170073 Forwards final agenda for NRC Caseload Forecast Panel B00122-24 site visit.

 GOODMAN.W A. Washington Public Power Supply System 80/02/21 Washington Public Power Supply System. 7pp 21838 015. 24X Fiche. 50-397
- --8401170077 Bummary of Caseload Forecast Panel 780613-15 site visits COX.T.H. Light Water Reactors Branch 3, 78/09/28 Light Water Reactors Branch 3, 12pp. 21838.023, 24X Fichs 50-397,83/10/24,8401170065
- --8401170083 "Level 1 Mgt Info Rept." Related info encl * Washington Public Power Supply System 80/01/30, 72pp, 21838.106. 24% Fiche: 50-397,83/10/24,8401170065

- --8401170089 "Project Status Rept for WNP-1,2,3,4 & 5 "

 * Washington Public Power Supply System 78/04/30 29pp
 21838 178 24X Fiche 50-397.83/10/24,8401170065
- ---8401170092 "Project Trend Analysis Manpower Progress Schedule " Related info encl * Hashington Public Power Bupply System 78/04/30 135pp 21838 207 24X Fiche 50-397,83/10/24.8401170065
- 8402010364 Further response to FOIA request for records re Ofc of Inspector & Auditor review of NRC investigation reported in NUREQ-0862 & other files concerning facilities Forwards App B documents App A & B documents available in PDR FELTON, J M Division of Rules and Records 83/11/22 REYNOLDS, J Center for Law in the Public Interest App 22038 203 24X Fiche 50-000,83/11/22,8402010344
- --B203180319 Submits questions re inclusion of util comments & qualifications in RL Cloud Associates second draft of GA audit & misrepresentations to NRC re status of rept during period of util review OTTINGER, R House of Rep. Energy & Commerce B1/12/18 PALLADINGIN Commissioners 7pp 22059.036 24X Fiche 50-000.83/11/22,8402010364
- --8402010372 Recommends transmittal of investigation review rept to Congress per R Ottinger 820204 ltr re inconsistencies in NURCO-0862 & M Udail 820208 request Related info encl KAMMERER.C Office of Congressional Affairs 82/08/31 PALLADINO.N , GILINSKY, V , AMEARNE, J Commissioners 150pp 22058 207 24X Fichs 50-000,83/11/22,8402010364
- --B40201037B Forwards review of NUREG-0862, "Insp Rept of Preliminary Rept, Beismic Reverification Program at Diablo Canyon Units 1 & 2 " Related info encl BOULDEN, H , AUERDACH, M Office of Inspector & Auditor 83/11/22 CUMMINGS, J J Office of Inspector & Auditor 39pp 22058 357 24X Fiche 50-000, 83/11/22, 8402010364
- ---84020103B4 Commends NRC for responsiveness in closing facilities due to emergency planning deficiencies Unges review of testimony presented at hearings facilities should remain closed until adequate emergency plans in place GILMAN.B A House of Rep 83/05/25 FALLADING.N J Commitssioners 2pp 22059 034 24X Fiche 50-000,83/11/22, BBD210344
- --8402010393 Responds to 820409 ltr re lateness & inadequacy of NRC responses to requests for info, displeasure at Commission decisions & list of outstanding subcommittee correspondence w/proposed response dates Requested list forwarded PALLADINO.N J Commissioners 82/04/21 OTTINGER.R L House of Rep.. Energy & Commerce 3pp 22059 047
- --8402010394 Ack receipt of 820204 ltr re enforcement action against PG&E.Reply will be forwarded as soon as possible KAMMERER.C Office of Congressional Affairs 83/11/22 GTTINGER.R House of Rep. Energy & Commerce 1p 22059 056
- 8402010399 FOIA request for documents re incident at facilities described in Encl B, Page 2 of weekly info rept for wk ending 831007 BHOLLY, 8 C. Union of Concerned Scientists 83/10/20, FELTON, J M Division of Rules and Records 1p 22062 023 24X Fiche: 50-250, 83/10/20, 8402010399
- 8402010402 Partial response to FOIA request for documents re incident at facilities described in Encl B.Page 2 of weekly info rept for wk ending 831007. Forwards App A documents Info also available in PDR FELTON.V. M Division of Rules and Records 83/11/16 SHOLLY.8 C Union of Concerned Scientists 2pp 22062 024 24X Fiche: 50-250,83/11/16,8402010402
- --8402010404 Notification of 831021 IE enforcement conference w/util in Miami,FL to discuss inadvertent isolation of containment spray sys. Related info encl # Region 2, Défice of Director 83/10/14 Region 2, Office of Director. 12pp 22062:026 24X Fiche 50-250,83/11/16,8402010402
- ---8402010407 RO 251-83-016, discovered containment spray pumps 4A & B on both manual discharge yelves 4-891A & B locked in closed position. Investigation in progress Related info encl HAYS.J K. Floride Power & Light Co PTP-0C-83-168, B3/10/05 O'REILLY.J P. Region 2, Office of Director lipp 22062,03B 24X Fiche 50-250,83/11/16,8402010402.

- B402210347 Notification of contract execution.Mod 1.to "IMS/IDAS Sys Support:" awarded to SBA Subcontractor Wilson Hill Assoc. Inc OILDENHORN.A J Administrative Contracts Branch FIN D-1211 NRC-33-84-378 B4/01/25 BASSETT.H S Division of Data Automation & Management Information BADINI.J B NRC - No Detailed Affiliation Oiven 1p 22020 343
- --8402210351 Mod 1.making administrative changes, to "IHS/IDAS 8ys Support " * Small Business Administration * Wilson Hill Associates, Inc HACAN, T F Division of Contracts FIN D-1211. NRC-33-84-378 84/01/25 2pp 22323 344
- 8402210363 Notification of contract execution, Mod 3, to "Panel Member & Documentation Review for Selected Meetings of Peer Review Group "Contractor Univ of Virginia TOWNSEND. B L. Purchasing Section. FIN 8-8985 NRC-04-83-010 84/02/02 BASSETT. O E Division of Accident Evaluation (Pre 840101) JANKOWSKI, M.W. NRC No Detailed Affiliation Given ip 22323 341
- --B402210349 Mod 3, extending period of performance to 840301 & increasing funds, to "Panel Member & Dacumentation Review for Selected Meetings of Peer Review Group."

 REYNOLDS.A B Virginia, Univ of, Charlottesville, VA REBELLO.J E Division of Contracts FIN 8-8995 NRC-04-83-010 84/02/02 Lp 22323 342.
- B402210419 Notification of contract execution.Mod 7.to "Assessment of Waste Retrieval Alternatives "Contractor Engineers Intl. Inc FLEENOR.C Technical Assistance Contracts Branch. NRC-02-82-031 84/01/26 DAVIS.J Office of Nuclear Material Safety & Safeguards, Director TIKTINSKY.D. NRC No Detailed Affiliation Given. ip 22323 337
- --8402210437 Hod 7.extending period of performance to 840307 at no add1 cost, to "Assessment of Waste Retrieval Alternatives."
 *SINGH.M.N Engineers International, Inc
 of Contracts NRC-02-82-031 84/01/26 ip 22323 338.
- 8402210464 Notification of contract execution, Mod 4, to "Nemaha Ridge Seismographic Network." Contractor Univ of Kansas JACOBS, A Technical Assistance Contracts Branch FIN 8-8272 NRC-04-82-006 84/01/31 BATSON, H Office of Nuclear Reactor Regulation, Director SURFLUEH, E. NRC No Detailed Affiliation Given ip 22344 044
- --8402210476 Ltr Contract NRC-04-82-006-02, Mod 3, increasing funding action, to "Nemaha Ridge Seismographic Network" OUSTAVE, R P Technical Assistance Contracts Branch FIN 8-8272. NRC-04-82-006 84/01/31 HALLEMBECK, C, CROSS, C, A Kansas State Univ , Manhattan, KS ip 22344 045.
- 8402230269 Notification of contract execution, Mod 5, to "Model Documentation & In-House Training for Unsaturated Flow & Transport Modeling." Contractor Water: Waste & Land. FLEENOR: C Technical Assistance Contracts Branch NRC-02-83-030 84/01/24 DAVIS.J. Office of Nuclear Material Bafety & Safeguards, Director WIDMAYER, D NRC No Detailed Affiliation Given 1p 22360 013
- --8402230272 Mod 5, extending period of performance to 840301 at no cost, to "Model Decumentation & In-House Training for Unsaturated Flow & Transport Modeling "DAVISIA Mater. Waste & Land, Inc. QUSTAVE.R Division of Contracts NRC-02-83-030, 84/01/24 ip 22380:014
- 8402230272 Notification of contract execution, Mod 3, to "Keypunch & Verification Svc " Contractor.SBA Subcontractor Info Sys & Networks Corp BACMBERG, B J Administrative Contracts Branch FIN 8-8158 NRC-25-82-318 84/02/09. BASSETF. H Division of Data Automation & Management Information KING, M. NRC No Detailed Affiliation Given ip 22371:266.
- --8402230293 Mod 3, increasing funds, to "Keypunch & Verification 8vc "

 # Smell Business Administration. * Information Systems & Network
 Curp HAGAN,T F Division of Contracts. FIN 8-8158.
 NRC-25-82-018 84/02/09 1p 22371 267.
- 8402230274 Notification of contract execution, Mod 4, to "Reorganizing & Furging of Bafety Reactor Files at FDR & ACRS " Contractor.

 8BA Subcontractor Labat-Anderson, Inc.

 NCLEAREN.T Administrative Contracts Branch NRC-10-83-722

 84/02/15, BESAW.W J Division of Technical Information & Document Control . SKOCZLAS, J NRC No Detailed Affiliation Oiven. 1p 22371: 264

- --8402230275 Mod 4, increasing total amount obligated under contract, to "Reorganizing & Furging of Safety Reactor Files at PDR & ACRS" + Emall Business Administration * Labat-Anderson, Inc. HAGAN, T F Division of Contracts NRC-10-83-722 B4/02/15 1p 22371 225
- B402230445 Notification of contract execution.Mod 4.to "Long-Tarm Performance of Matla Used for High Level Waste Packaging." Contractor Battelle Columbus Labs PAGE.M Technical Assistance Contracts Branch FIN B-4764. NRC-94-82-015 B4/02/16 PATSON.W Office of Nuclear Regulatory Research, Director KIM.K NRC - No Detailed Affiliation Given 1p 22374 064
- --B402230446 Mod 4.providing incremental funds to "Long-Term Performance of Matls Used for High Level Waste Packaging"

 * Battelle Memorial Institute, Columbus Laboratories.
 GUSTAVER P Division of Contracts FIN B-6764 NRC-04-82-015
 84/02/16 1p 22376 065
- 8402240228 Notification of contract execution, Mod 4, to "Review, Abstract. Index & Guarterly Update Practice & Procedure Digest" Contractor Aspen 89s. Inc PERLMAN. J Technical Assistance Contracts Branch FOM B-1588 NRC-14-82-448 84/02/16 CUNNINGHAM, O H Office of the Executive Legal Director GRAY, J NRC No Detailed Affiliation Given ip 22381 278
- --8402240231 Mod 4.adding add1 funds.to "Review.Abstract, Index & Quarterly Update Practice & Procedure Digest "
 GHINTON.D Aspen Systems, Inc HAGAN.TF Division of Contracts
 FIN 8-1588 NRC-14-82-448 84/02/16 ip 22381 279.
- B402240254 Notification of contract execution, Mod 18. to "PDR Micrographic Storage & Retrieval Bys " Contractor Access Gorp PERLMAN, J Technical Assistance Contracts Branch, FIN B-1853 NRC-17-79-449 64/02/12 CHILK, S J Office of the Secretary of the Commission SCATTOLINI, L NRC No Detailed Affiliation Given 19 223R1 271
- --8402240256 Mod 18, exercising option through 840731, to "PDR Micrographic Storage & Retrieval Sys." BAKER, N D Access Corp HAGAN, T F Division of Contracts. FIN B-8153 NRC-17-79-449 84/02/12, 2pp 22381.272
- B40224036B Notification of grant execution, Mod 1, to "Second Intl Conhicula Symposium" Orantee.Univ of Arkansas.
 UMBELD Technical Assistance Contracts Branch FIN Q-1040
 NRCQ-04-82-010 B4/02/17 BATBON, W. Office of Nuclear Regulatory
 Research, Director SWANBERG, F. NRC No Detailed Affiliation
 Qiven ip 22380 136
- --8402240371 Mod 1.extending period of performance to 841231 & changing NRC program officer, to "Second Intl Corbicula Symposium."

 * Arkansas, Univ of, Fayetteville, AR MORTON, K V Technical Assistance Contracts Branch FIN 9-1040 NRC9-04-82-010, 84/02/17 ip. 22380 137.
- 8402240372 Notification of contract execution, Mod 5, to "Definition of Dounding Physical Tests Representative of Transport Accidents Air & Marine " Contractor IIT Research Inst UMBEL D Technical Assistance Contracts Branch FIN B-7570 NRC-04-81-203, 84/02/09, FOREMAND B. Office of Nuclear Regulators Research, Director LAHS, W NRC No Detailed Affiliation Givan. Ip 22380 134
- --B402240379 Mod 5, extending period of performance to 840228 at no additions, to "Definition of Bounding Physical Tests
 Representative of Transport Accidents Air & Marins "
 PLDNIB-T R ITT Research Institute. GUSTAVE.R P. Division of
 Contracts FIN 8-7570 NRC-04-81-203 84/02/09 ip. 22380.135
- 8402280598 Notification of grant execution, Mod 2, to "Condensation Ratis at Highly Agitated Steam-Water Interfaces" Grantee MIT.

 UMBEL.D Technical Assistance Contracts Branch FIN Q-1053.

 NRC-Q-04-83-004 84/02/13 BATBON.W. Office of Nuclear Regulatory Research, Director LEE, T. NRC No Detailed Affiliation Given ip 22427 143
- ---B4022B0604 Mod 2, providing incremental funding, to "Condensation Rate: at Highly Agitated Speam-Water Interfaces."

 DUMMER, G. H. Massachusetts Institute of Tachnology, Cambridge, MA
 MORTON. K. V. Technical Assistance Contracts Branch. FIN 9-1033

 NRC-9-04-83-004 84/02/13 ip 22429:144.

- B4022B0633 Notification of contract execution, Mod 4, to "Reviewing Hydrogeologic Investigations of Nevada Test Site Project D " Contractor GeoTrans, Inc FLEENGR, C Technical Assistance Contracts Branch FIN 8-7378-4 NRC-02-82-047 B4/02/13 DAVIS.J Office of Nuclear Material Sefety & Safeguards, Director POHLE.J NRC No Detailed Affiliation Given ip 22416 360
- --B4022B0642 Mod 4. obigating funds, to "Reviewing Hydrogeologic Investigations of Nevada Test Site - Project D" RUBS, B Geotrans, Inc GUBTAVE, R P Division of Contracts FIN B-737B-4 NRC-02-B2-047 84/02/13 2pp 22416 361
- 8402280670 Notification of contract execution.Mod 14, to "Licensing Technical Assistance" Contractor Science Applications, Inc PAGE, M Technical Assistance Contracts Branch FIN 8-7397 NRC-02-83-035, 84/02/22 DAVIS.J Office of Nuclear Material Safety & Safeguards, Director LGYSEN, P NRC No Detailed Affiliation Given 1p 22429 001
- --8402280682 Mod 14.definitizing Task Order 8 & increasing funds.to "Licensing Technical Assistance." FINDLEY, D E Science Applications, Inc. GUSTAVE, R P Division of Gontracts FIN 8-7397 NRC-02-83-039 84/02/22 5pp
- 8402280688 Notification of contract execution, Mod 1, to "In-Situ Stress Heasurements in Earth Crust in Eastern US " Contractor Engineers Intl. Inc FLEEMOR, C Technical Assistance Contracts Branch. FIN 8-8272 NRC-04-83-016 B4/02/08 BATSON, W Office of Nuclear Material Bafety & Safeguards, Director SCHMITT, T NRC No Detailed Affiliation Given ip 22414 352.
- --8402280692 Mod i, providing incremental funding, to "In-Situ Stress Measurements in Earth Crust in Eastern US"
 # Engineers International, Inc QUETAVE, R. P Division of Contracts FIN 8-8292 NRC-Q4-83-Q16 84/Q2/OB 2pp 22414:353
- 8402290396 Notification of grant execution, Mod 1, to "Eighth World Conference on Earthquake Engineering" Grantee Earthquake Engineering Words Earthquake Engineering Research Inst UMBEL. D.H. Technical Assistance Contracts Branch. FIN 9-1058 NRC-9-04-63-010. 84/02/13. BATBON Office of Nuclear Regulatory Research. Director COBTELLO, J. NRC No Detailed Affiliation Given. 1p 22438.221
- --8402290417 Mod 1. increasing funds, to "Eighth World Conference on Earthquake Engineering"
 PENZIEN.J Earthquake Engineering Research Institute. MORTON, K V Tachnical Assistance Contracts Branch. FIN 9-1056
 NRC-9-04-83-010. 84/02/13. ip. 22438 222
- FOIA FREEDOM OF INFORMATION ACT REQUEBTS AND RELEASES
- BR09170054 Requests responses re London Nuclear Con-Decon solution used on reactor coolant recirculation pumps during sys cleanup DREY/N. Affiliation Not Assigned 82/09/19 DENTON, H.R. Office of Nuclear Reactor Regulation, Director, 2pp 22393, 361 24X Fiche: 50-000,84/02/03,8209170054.
- 8401170045 Partial response to FDIA request for six categories of documents re facilities Forwards documents listed in Apps A & B. Documents also available in PDR. W/o App A documents. FELTON, J. M. Division of Rules and Records 83/10/24 ANDERSON, B. I Carvey, Schubert, Adams & Barer 4pp. 21838.003 24X Fiche. 50-397, 83/10/24, 8401170065
- --940117007i Advises of results of NRC Caseload Forecast Panel visit to plant site during 811021-23 Estimated const completion dates for Unit 1 is Feb 1986. Unit 4 not included in evaluation.

 TEDESCO.R L. Assistant Director for Licensing 81/12/08. FERGUSON,R L. Washington Public Power Supply 8ystem. 3pp 21838.007. 24X Fiche: 50-397.83/10/24.8401170065
- --B4D1170073 Forwards final agenda for NRC Caseload Forecast Panel B00122-24 site visit. B00DMAN.W.A Washington Public Power Bupply System B0/02/21 Washington Public Power Bupply Bystem. 7pp. 21838 015. 24X Fiche.50-397,83/10/24,8401170065
- --8401170077 Summary of Caseload Forecast Panel 780613-15 sits visits COX.T.H. Light Water Reactors Branch 3, 78/09/28 Light Water Reactors Branch 3 12pp, 21838.023 24X Fichs 50-397,83/10/24,8401170063
- --8401170083 "Level 1 Mgt Info Rept." Related info encl * Washington Public Power Supply System, 80/01/30 72pp. 21838.106. 24X Fiche: 50-397,83/10/24,8401170065

- --8401170087 "Project Status Rept for WNP-1, 2,3,4 & 5 "

 * Washington Public Power Supply System 78/04/30 29pp
 21838 178 24X Fiche 50-397,83/10/24,8401170065
- --8401170092 "Project Trend Analysis Manpower Progress Schedule " Related info encl * Washington Public Power Supply System 78/04/30 135pp 21838 207 24X Fiche 50-397.83/10/24.8401170045
- B402010364 Further response to FOIA request for records re Ofc of Inspector & Auditor review of NRC investigation reported in NURLO-0862 & other files concerning facilities Forwards App B documents App A & B documents available in PDR FELTON.J M Division of Rules and Records 83/11/22 REYNOLDS, J Center for Law in the Public Interest 4pp 22058 203 24X Fiche 50-000, 83/11/22, 8402010364
- --8203150319 Submits questions re inclusion of util comments & qualifications in RL Cloud Associates second draft of GA audit & misrepresentations to NRC re status of rept during period of util review DTTINGER.R House of Rep , Energy & Commerce 81/12/18 PALLADING.N Commissioners 7pp 22039 036 24X Fiche 50-000,83/11/22,8402010364
- --8402010372 Recommends transmittal of investigation review rept to Congress per R Ottinger 820204 ltr re inconsistencies in NURCO-0862 & M Udail 820208 request Related info encl. KAMMERER.C Office of Congressional Affairs 82/08/31 PALLADINO.N , GILINSKY, V , AMEANNE.J Commissioners 150pp 22058 207 24X Fichs 50-000.83/11/22,8402010364
- --8402010378 Forwards review of MUREG-0862, "Insp Rept of Preliminary Rept. Seismic Reverification Program at Diablo Canyon Units i & 2 " Related info encl BOULDEN.H., AUERBACH.M Office of Inspector & Auditor 83/11/22 CUMMINGS.J J Office of Inspector & Auditor 37pp 22058 357 24X Fiche 50-000, 83/11/22, 8402010364
- --B4020103B4 Commends NRC for responsiveness in closing facilities due to emergency planning deficiencies Urges review of testimony presented at hearings Facilities should remain closed until adequate emergency plans in place GLMAN. B A House of Rep 83/05/25 PALLADING, N J Commissioners 2pp 22057 034 24X Fiche 50-000, B3/11/22, BA02010364
- --8402010393 Responds to 820409 ltr re lateness & inadequacy of NRC responses to requests for info, displassure at Commission decisions & list of outstanding subcommittee correspondence w/proposed response dates Requested list forwarded PALLADING.N.J. Commissioners 82/04/21 OTTINGER,R L. House of Rep., Energy & Commerce 3pp 22059-047
- --8402010396 Ack receipt of 820204 ltr re enforcement action against PG&E Reply will be forwarded as soon as possible KAMMERER.C Office of Congressional Affairs. 83/11/22 OTTINGER.R House of Rep., Energy & Commerce ip 22059 056
- 8402010399 FOIA request for documents re incident at facilities described in Encl B.Page 2 of weekly info rept for wk ending 831007
 8HOLLY.8 C. Union of Concerned Scientists 83/10/20 FELTON, J M Division of Rules and Records ip 22062 023 24X
 Fiche.50~250,83/10/20,8402010399
- 8402010402 Partial response to FOIA request for documents re incident at facilities described in Encl B.Page 2 of weekly info rept for wk ending 831007. Forwards App A documents Info also available in PDR FELTON, J M Division of Rules and Records 83/11/16 SHOLLY, 8 C Union of Concerned Scientists 2pp 22062 024. 24X Fichs. 50-250, 83/11/16, 8402010402
- --8402010404 Notification of 831021 IE anforcement conference w/util in Miami.FL to discuss inadvertent isolation of containment spray sys Related info encl * Region 2, Office of Director 83/10/14 Region 2, Office of Director. 12pp 22062:026 24X Fiche: 50-250, 83/11/16, 8402010402
- --8402010407 RO 251-83-016 discovered containment spray pumps 4A & B on both manual discharge valves 4-891A & B locked in closed position Investigation in progress, Related info encl. HAYB.J K. Florida Power & Light Co PTP-GC-83-168, 83/10/05 O'REILLY.J P. Region 2, Office of Director 11pp 22062,038 24X Fiche 50-250,83/11/16,8402010402

- --8402010493 Submits daily highlights On 831004.discharge containment spray pump manual isolation valve locked in closed position Spray pump or amergency containment cooler operation will provide heat removal capability

 MCDONALD.D G Operating Reactors Branch 1 83/10/03 DENTON, H .

 CARTER, J . EISENHUT.D G .NC. No Detailed Affiliation Given 2pp 28062 057 24X Fiche 50-250.83/11/16.8402010402
- 8402010413 FOLA request for SECY-83-311 "Proposed Insider Bafeguards Rules." including apps.annexes & other matls HARTIN.C J Association for Advancement of Psychology 83/09/28 Office of Administration ip 22060 001
- 8402010418 Responds to FOIA request for SECY-83-311 "Proposed Insider Safaguards Rules." including apps.annexes & other mati Document withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 83/11/18 MARTIN, C J Association for Advancement of Psychology 1p 22060 002
- 8402010423 Responds to FOIA request for SECY-B3-311 "Proposed Insider Safeguards Rules," including apps, annexes & other matl Forwards SECY-B3-311 & SECY-B3-311A COMBS.T Office of the Secretary of the Commission 83/11/28 MARTIN.C J Association for Advancement of Psychology 1p
- --8309120062 Forwards corrected Page 4 to SECY-83-311 re proposed insider safeguards rules 2 Office of the Secretary of the Commission 83/08 of the Secretary of the Commission 2pp 22060 004 83708/25
- 8402010441 FOIA request for SECY-83-288 & SECY-83-443 to be placed in PDR YENQUSKAS: J Nawman & Holtzinger 83/12/09 Administration 1p 22041 271 Office of
- 8402010444 Responds to FOIA request for SECY-83-288 & SECY-83-443 to be placed in PDR SECY-83-288 available in PDR SECY-83-443 being placed in PDR Forwards SECY-83-443 FELTON.J M Division of Rules and Records 84/01/17 YENOUSKAS.J Newman & Holtzinger 1p. 22041 272 24X Fiche 50-000,84/01/17, Newman & Holtzinger 8402010444
- --8402010453 8ECY-83-443
 Informs Commission of info obtained re flux reduction programs for pressurized thermal shock at lead plants, since 830225 interim rept (8ECY 83-079).
 DIRCKESN J Diffice of the Executive Director for Operations 83/10/28, 11pp 22061;273 24X Fiche 50-000.84/01/17,8402010444
- 8402010454 FDIA request for review of Torrey Pines Technology study re ANI seismic design study & ANI & Insurance Svc Ofc last Annual rept CALBOYAB.C D Affiliation Not Assigned B3/10/30 Region 5, Office of Director 4pp 22062 01B. 24x Fiche: 50-206, 83/10/30, 8402010454
- 8402010487 Responds to FOIA request for review of Torrey Pines Technology study re ANI seismic design Info contained in Feb 1982 Suppl 5 & June 1982 Suppl 6 to NUREG-0712, Feb 1768 coppl 5 % Come 1782 coppl 6 % INDEX-7/2: Available in PDR.
 FELTON-J.M Division of Rules and Records 83/11/16 CALSOYAB, C D
 Affiliadion Not Assigned 1p 22062: 022, 24X
 Fiche. 50-206, 83/11/16. 8402010457.
- 8402010466 FOIA request for Hoyt rept FORD,N. Affiliation Not Assigned. 83/11/03 NRC No Detailed Affiliation Given 1p 22061-383
- 8402010468 Responds to FOIA request for Mayt rept Rept available in PDR. FELTON, J.H Division of Rules and Records 83/11/09 FORD, N. Affiliation Not Assigned 1p 22061 354.
- 8402010471 FOIA request for data & findings compiled as result of abrial survey of background radiation levels conducted by NRC in area surrounding facilities.

 DUU0HTY, J Beacoast Anti-Pollution League 83/10/20 NRC Detailed Affiliation Given ip. 22061:351 24X

 Fichs. 50-443, 83/10/20, 8402010471
- B402010476 Responds to FOIA request for data & findings compiled as result of merial survey of background radiation levels conducted by NRC in area surrounding facilities. Aerial survey not performed due to budget constraints.
 FELTON.J M Division of Rules and Records B3/11/16 DOUGHTY, J Beacoast Anti-Pollution League. 1p 22061: 352, 24X Fiche 50-443,83/11/16,8402010476

- 8402010477 Appeals denial of FDIA request for access to SECY-82-466, "Preliminary Staff Analysis of Steam Generator Tube Rupture Risk" Risk "
 JORDAN, W 8 Harmon & Weiss 83/10/07 DIRCKS, W J Office of the
 Executive Director for Operations 3pp 22061 313.
- 8402010480 Responds to appeal re denial of FOIA request for GECV-82-466, "Preliminary Staff Analysis of Steam Generator Tubs Rupture Risk "Forwards requested document Document also available in PDR CHILK.S J Office of the Secretary of the Commission. 83/11/08 JORDAN: W S Harmon & Weiss ip 22061 320
- --B212130066 Draft Commission paper re B21118 Commission briefing on multiple steam generator tube ruptures Draft "Summary of Risk Analysis for Steam Generator Tube Rupture Events" encl. DIRCKS:W J Office of the Executive Director for Operations B2/11/24 15pp #2061 321
- 8402010483 FDIA request for list of nuclear power plant mishaps in US from 1981-83 & reason for mishaps PALEY.R Affiliation Not Assigned 83/10/31 Office of Administration 1p 22061.347.
- 8402010484 Responds to FOIA request for list of nuclear power plant mishaps in US from 1981-83 Forwards NUREG/CR-2000, per 831110 telcon M/o enci FELTON, U M Division of Rules and Records 83/11/10, PALEY, R
- FELTUN: On Divinion of Assigned 1p 22041 348
- 8402010488 FOIA request for SECY-83-318 & AEOD/T316 to be places in PDR. GRABER.L D NUS Corp CD-18-83-475 83/10/24, and Records 1p. 22060-338 Division of Rule
- 8402010491 Responds to FOIA request for SECY-83-318 & AEDD/T316 to be placed in PDR Forwards documents. Info partially deleted (ref FOIA Exemption 5), AEDD/T316 available in PDR FELTON, J M Division of Rules and Records 83/11/15, GRABER.L.D NUB Corp 2pp 22040.339 24X Fiche.50-289,83/11/15,8402010491
- --B306240184 Forwards AEOD/T316 "Thermal Nonrepeatability Problem W/Barton Model 763 & 764 Electronic Transmitters." Problem W/Barton Model 763 & 764 Electronic Transmitters." Problem adequately addressed since manufacturer issued Part 2: repts to alert users of transmitters & IE planning info motics CHIRAMAL.M Reactor Operations Analysis Branch. AEOD/T316 83/05/31 SEYFRIT.K V. Reactor Operations Analysis Branch 22060:344 24X Fichs. 50-289, 83/11/15, 8402010491.
- ~~B402010494 BECV 83-318 402010494 BECV 83-318
 Informs that ALAB-698 draft order reversed ABLAB decision requiring emergency support director at TMI-1 to authorize protective action recommendations.

 MALBCH.M O Office of the General Counsel. ZERBE.J E. Office of Public Affairs. B3/08/04. 3pp 22060;341 24X
 Fiche: 50-289,83/11/15,8402010491
- B402020029 FOIA request for documents re evaluation or review of design constructed directions of the state o present. ZACK, A. M ZACK.A.M Barris, Sott, Denn & Driker, 83/09/29, FELTON, J M Division of Rules and Records, 1p 22079, 207, 24X Fiche 50-329, 83/09/29, 8402020029
- 8402020033 Partial response to FOIA request for documents re evaluating or review of design, const, scheduling, cost & licensing of facilities from 1977 to present Forwards App A & B documents.
 - FELTON, J.M. Division of Rules and Records. 83/11/04, ZACK, A.K. Barris, Bott, Denn & Driker, 11pp 22079, 208 24X Fiche, 50-000, 83/11/04, 8402020033.
- ---7906200195 Submits Casaload Panel estimate of const complation 4sts KARI.S M Office of Management and Program Analysis. 79/05/1L HOOD, D Light Water Reactors Branch 4 1p 22080; 067. 241 Fichs: 50-000, 83/11/04, 8402020
- --BiOBiiOO74 Informs of tentatively scheduled BiOB25 visit by Casslood Forecast Panel to facility Reconfirmation of fuel load sestimate needed to develop NRC resource allocations, priority decisions & support findings necessary for CP extension. TEDEBCO.R L Assistant Director for Licensing, 81/08/09 EISENHUT, DC Division of Licensing, 1p. 22081:020. 24X Fiche. 50-000, 83/11/04.8402020033
- --Bii2220708 Summary of Biiii2 meeting w/util in Bethesda.MD re comits schedules for foundation mods to auxiliary bldg. Attendes list & viewgraphs encl.
 HODD, D. Licensing Branch 4. ISBUANCES OM. 81/11/29. Licensis Branch 4 Bpp. 22081.110. 24% Fiche: 50-000.83/11/04.8402020033

- --8402020038 "Project Cost & Schedule, Forecast 4 "
 # Bechtel Corp JOB 7220 77/12/31 136pp 22079 219 24X
 Fiche 50-000, 83/11/04, 8402020033
- --8402020041 Recommends followup to board notification, w/detailed plantspecific analysis of const schedule BOVD.R S. Division of Project Management 78/03/08 BASSETT.H S Office of Management and Program Analysis HARTFIELD.R A NRC -No Detailed Affiliation Given 1p 22079 358 24X Fishe 50-000.83/11/04.8402020033
- --8402020046 Forwards Feb project status repts
 MARTINEX.P A Bechtel Corp 78/03/15 COOKE.T C , KEELEY.G S ,
 NEWGEN, J F Bechtel Corp 1p 22080 004 24X
 Fitche 50-000,83/11/04,8402020033
- --8402020052 "Project Status.Feb 1978 " Related info encl * Bechtel Corp JOB 7220 78/02/28 61pp 22080 005 24X Fiche 50-000,83/11/04,8402020033
- --B402020061 Forwards "Project Status Rept.Jul 1977 "
 RUTGERS.J A Bechtel Corp BLC-B128 79/09/07 KEELEY.G 8.
 Consumers Power Co ip 22080 077 24X Fichs 50-000,83/11/04.
- --8402020064 "Project Status Rept. Jul 1979 " Related info encl * Bechtel Corp 79/07/31 45pp 22080 078 24X Fichs 50-000, 83/11/04, 8402020033
- --B402020068 Agenda for 790918-20 Caseload Forecast Panel site visit Related info enci # Consumers Power Co 79/09/14 Consumers Power Co 57pp 22080 122. 24X Fiche 50-000/83/11/04/8402020033.
- --8402020070 Agenda for 800727 Caseload Forecast Panel site visit Related info encl # Consumers Power Co 80/07/25 Consumers Power Co 145pp 22080 180 24X Fiche: 50-000,83/11/04,8402020033,
- --8402020073 Porwards Project Schedule Change Notice 2 which finalizes Rev il dates under further study Related info encl. RUTOERSJ A. Bechtel Corp BLC-11161 81/07/15 CODK. J.W Consumers Power Co 37pp 22080 345 24X Fiche 50-000, 83/11/04-8402020033
- --8402020079 Agenda for B10825 meeting w/NRC Cassload Forecast Panel to conduct plant tour Related info encl # Consumers Power Co B1/08/24. Consumers Power Co. 84pp 22081:026 24X Fiche 50-000.83/11/04.8402020033
- --8402020092 Submits 820112 daily staff notes to PNO-II-82-006 & PNO-II-82-007 & review of changes to GA organization at plant site & matters to engoing soil settlement hearing Related into encl
 DIRCKS:M J. Office of the Executive Director for Operations 82/01/13, PALLADINO, GILINSKY, BRADFORD Commissioners 23pp. 22081:118 24X Fiche, 50-000,83/11/04,8402020033
- --8402020142 Handwritten notes w/attached calendar page re Midland hanger reinsp & pipe whip restraints.
 * NRC No Detailed Affiliation Given 83/04/19, 5pp 22081:184 24X Fiche:50-000,83/11/04,8402020033
- --8402020145 Agenda for B30419-21 meetings w/NRC Caseload Forecast Panel * NRC - No Datailed Affiliation Given B3/04/19, NRC - No Detailed Affiliation Given, 210pp, 22081, 189, 24X Fichs 50-900, B3/11/04, 8402020033
- --B402020157 Forwards Dow Chemical Co notice of termination & complaint for declaratory judgment due to util inability to meet commercial steam operation date. Damages against util being sought.

 FALAHEE, J. B. Consumer Power Co. 83/07/15 KEPPLER, J. Q. Ragion 3, Office of Director, Sipp. 22082:098 24X Fiche: 50-000, 83/11/04, 8402020033.

- --8402020213 Discusses 830702 telcon re util request for followup meeting on facility const completion dates Util requested delayed meeting until essential related matters resolved Related info enci
 HOOD. D. Licensing Branch 4 83/07/08 ADENSAM.E G Licensing Branch 4 46pp 22082 136 24X Fiche 50-000,83/11/04.8402020033
- --8402020310 Requests responses re estimated const completion schedule SCHWENCER.A Licensing Branch 2 * Licensing Branch 3 80/08/18 Licensing Branch 2 2pp 22080 335
- B402060012 Further response to FQIA request for three categories of documents Forwards App A documents FELTON.J M Division of Rules and Records 83/10/31 PUNTENNEY, J Safe Energy Coalition 4pp 22091 250
- --B20A060003 Forwards correspondence from Jefferson County, NY Board of Supervisors re transportation of nuclear matl through county Review of resolution adopted by board requested MARTIN, D C. House of Rep., Interior & Insular Affairs 82/06/02 PALLADINO, N. Commissioners 3pp 22091 255
- ---8209150006 Advises that recent events in State of VT re spent fuel shipment into point out potential shortcomings in NRC procedures implementation requested to minimize future misunderstanding Response to Governor Snelling and PALLADING, N J Commissioners. 82/09/29 DIRCKS,W J Office of the Executive Director for Operations 1p 22091 316
- --B402060018 Forwards four categories of correspondence for Commissoner Ahearne Copies of any info sent to Commissioner Ahearne should be sent to N Haller W/o encl KERR, O W Defice of Btate Programs. Director 82/09/09 DAVIS, J NRC - No Detailed Affiliation Oiven 1p 22091 262
- ---8402060041 Safety evaluation supporting Model NLI-6502 cask for shipment of fuel from AECL NRX & NRU Canadian reactors # Transportation Certification Branch 83/10/31 4pp 22091 285
- --B402060046 Forwards notification of series of spent fuel shipments scheduled for State of VT per 820702 ltr DOE & AECL reached agreement on increasing number of scheduled shipments Author statement encl DANESE.F L Nuclear Assurence Corp FLD/82/106/ET8 82/08/13 MCCANDLESS.R Vermont. State of 7pp 22071 297.
- --8402060056 Advises that further NRC action re State of VI inquiry unwarranted Addl investigative effort not recommended. Subj matter should be closed w/response to Governor Enelling Draft ltr encl DIRCKS:W J Office of the Executive Director for Operations 82/09/20 PALLADINO, N J Commissioners 5pp 22071 311
- --8402060063 Advises that State of VT will not permit further shipments of spent fuel through state until federal agencies enforce uniform natl policy re shipments BNELLING,R A Vermont, State of 82/10/08 SCHUTT,P Nuclear Assurance Corp 2pp 22091 327
- --8402040049 Forwards inquiry from Representative D'Amours & DOE reply informing of referral action re transportation of nuclear wastes from Chalk River Canada OERTEL, 0 K. Energy, Dept of 82/11/08 KERR, 0 W. Office of State Programs, Director 3pp 22091 331
- ---B402060073 Requests rev to route approved by NRC on B20402 Rev required due to NY State Thruway Authority refusal to provide permit for transporting spent fuel on thruway, Related info encl DANEBE, F L Nuclear Assurance Corp FLD/82/141/ETS B2/09/14 Office of Nuclear Material Bafety & Bafeguards, Director 9pp 22091 334
- ---B402060079 Responds to 820927 ltr to ST Brewer of DOE re constituent concerns on transportation of spent fuel Explanation provided as to how routes chosen & criteria Used for selection.

 DIRCKB.W J. Office of the Executive Director for Operations B2/11/26. D'AMOURS.N E. House of Rep. 2pp. 22091.345
- 8402060025 Followup appeal re denial of FDIA request for documents characterized as proprietary or commercial trade secrets re repairs to steam generator tubes.

 DOROBHOW.J Three Mile Island Alert 83/08/04. REED, C. A Division of Rules and Records 1p 22111.144 24X Fiche 50-289.83/08/04, 8402060028

- 8402060028 Further response to appeal re denial of FDIA request for documents concerning steam generator problems at facility Forwards App A documents App B documents partially withheld (ref FDIA Exemption 4)
 DIRCKS.W J Office of the Executive Director for Operations 83/10/27 DOROSHOW, J Three Mile Island Alert 7pp 22111 153 24x Fiche 50-289.83/10/27.8402040028
- --B206210343 Forwards proposed program, schedule & level of technical effort required for accomplishing tentative work assignment J & evaluation of TMI-1, steam generator tube sealing program PANDEY, S Franklin Institute/Franklin Research Center NRC-03-BI-130 B2/04/17 BAJMA, S S NRC No Detailed Affiliation Given Spp 22132 143 24X Fiche 50-289, B3/10/27, B402040028
- --8206290608 Requests review of encl tentative work assignment J,
 "Evaluation of TMI-1 Steam Generator Tube/Tube Sheet
 Repair." notification as to whether proposed schedule can be
 met & estimate of required manpower resources
 BAUMA.S S NRC No Datailed Affiliation Given NRC-03-B1-130
 B2/06/14 PANDY,S Franklin Institute/Franklin Research Center
 4pp 22112 139 24X Fiche 50-289,83/10/27,8402060028
- --8207090028 Advises that once-through steam generator specs for facility have been sent to Franklin Research Ctr.per 820702 telcon GRAHAM M J General Public Utilities GPU Service Corp E&L 4438 82/07/06 MCCRACKEN.C NRC NO Detailed Affiliation Given ip 22111 165 24X Fiche 30-287.83/10/27.8402060028
- --B207140125 Summary of 820621 meeting w/util.Foster Wheeler, B&W & Franklin Research Ctr in Livingston,NJ re steam generator tube tubesheet repair Details of kinetic expansion process expected to be finalized before NRC 820527 meeting RAJAN. J Mechanical Engineering Branch 82/06/28 BOSNAK,R Mechanical Engineering Branch 7pp 22112 149 24X Fiche 50-289,83/10/27.8402050028
- --820720044i Informs of General Public Utils tentative schedule for full-scale test on TMI-1 once-through steam generator at Hount Vernon, IN for wh of 820726

 JACOBS.R Derating Reactors Branch 4 82/07/09 EIBENHUT, D G
 Division of Licensing 1p 22112 260 24% Fiche 50-287, 83/10/27, 8402060028
- --8207300124 Asks to be informed of any info sent to H Lewis re thiosulface theory & steam generator corrosion WHITE.J H Affiliation Not Assigned 82/07/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 22112 15
- --B207300136 Discusses steam generator corrosion which makes thiosulphate theory suspect & makes explosion repair both suspect & dangerous Facts suggest cause of corrosion not thiosulphate Requests NRC not approve steam generator repair LEMIS.H T Lewis, H B2/07/27 DENTON.H R Office of Nuclear Reactor Regulation, Director App 22112 157 24X Fiche 50-289, 83/10/27, 8402060028
- --B208070285 Informs of printing costs for TMI-1 steam generator tube destructive exam rept BENARDYA.V Chemical Engineering Branch B2/08/03 MCVEACH.H Division of Technical Information & Document Control 1p 22111 187 24X Fiche 50-289,83/10/27.8402040028
- --B208250400 Responds to B20723 ltr re insufficient util effort being focused on sulfur removal from surfaces at facility. Desuffuriation necessity & viability being determined. Restart plans to be reviewed following B20819 meeting BENAROYA.V. Chemical Engineering Branch B2/08/06 MACDONALD.D D Affiliation Nat Assigned 2pp 22111 163 24% Fiche 50-289,83/10/27.8402060028
- --B208310181 "TMI-1 Once-Through Steam Generator Repair Safety Analysis " Withheld (ref 100FR2 790) * General Public UeSlities - OPU Service Corp B2/08/20. JApp 22113 214 24X Fiche: 50-289, B3/10/27, B402040028
- ~-B20B310444 Provides schedular update & summary of 820B05 full-scale expansion demonstration at Mt Vernon.IL & 820B09 review of edg current test program & results at TMI-1 Detailed meeting minutes will be provided by project manager MCCRACKEN.C. Chemical Engineering Branch 82/08/17 BENAROYA.V Chemical Engineering Branch 92/08/17 BENAROYA.V Fiche.50-289.83/10/27.8402060028
- --B209280423 Provides status of steam generator repairs as discussed in 820825,0901-02 meetings Schedule of future meetings repairs listed Periodic insps will monitor for initiation of new defects to torrosion rate MCCRACKEN.C Chemical Engineering Branch 82/09/10. BENAROYA, U. Chemical Engineering Branch 7pp 22111 190. 24x Fiche 50-269,83/10/27,8402060028

- ---B209280427 Comments on B&W Rept 77-1135317, "Evaluation of Tube \$441 in From TMI-1" Rept describes thorough & comprehensive evaluation of Incons1-600 tubes removed from steam generators subsequent to detection of leaks MACDONALD, D D Affiliation Not Assigned. 82/08/30 BEHARGIA. V Chemical Engineering Branch 4pp 22111 182 24X Fiche 50-289,83/10/27,8402040028
- --8210070023 Advises that safety evaluation necessary prior to restart of determine that licensee took proper staps to recover from once-through steam generator corrosion problem VOLLMER, R Division of Engineering 82/09/17 EISEMENT, D Division of Licensing. 1p 22111 201 24X Fichs 30-209.83*(12 af 8402060028
- --8210130553 TR-006 R01
 Revision 1 to "TMI-1 Steam Generator Repair Safety
 Evaluation " Withheld (ref 10CFR2.790)
 GRAHAM.M J General Public Utilities GPU Service Corp
 82/09/30 38pp 22113 259 24% Fiche 50-289.83/10/27.84
- --8210290116 Requests fuller explanation of encl D9 Eisenhut B20907 15 re performance of repaired tubes in event of transients B/60 accidents during operation
 LEMIS.M I Lewis. M 82/10/25. EISENHUT.D 9 Division of Licensing ip 22/12/160, 24% Fiche 50-289,83/10/27.840228571
- ---8211090598 Forwards BMI final rept on failure analysis of twist ### "
 from TMI-1 steam generators Encl rept supple BMW rept
 distributed on 820819 Repts dtd 820520 on radwaste sys
 retainer exam being distributed W/o encl
 MCCRACKEN.C Chemical Engineering Branch. 82/10/27 PE:-WPGTA.V
 Chemical Engineering Branch 1p. 22111 233. 24x
 Fiche 50-289,83/10/27,8402040029
- --B2ili10543 Notifies of untimely Battelle request for extension of period of performance to B30331 for evaluation of steam generator corrosion assessment Extension deadline not mak due to late request submittal.

 HU:P Chemical Engineering Branch FIN B-2506 B2/10/26

 VOLLMER.R H Division of Engineering. 1p. 2211 202 241
 Fiche 50-289,83/10/27,8402040028.
- --B212150120 008 R01
 Revision 1 to BER, "Assessment of TMI-1 Plant Safety for Return to Svc After Steam Generator Repair." Withheld (ref 10CFR2 790)
 MDRAN.T M Babcock & Wilcox Co B2/12/07. 115pp B2113 304
 24% Fiche 50-289,83/10/27,8402040028.
- --B301060232 Forwards licenses 821207 safety assessment rs restart subsequent to once-through steam generator repairs, for review Technical evaluation repts due by B30225, W/o safety assessment HGCRACKEN.C Chemical Engineering Branch. 82/12/20 MACSOMMC Chio, State of 2pp 22112, 274. 24X Fichs 50-287, 83/10/27. B402040028
- --8301250628 BAM-1760
 Proprietary "TMI Unit i Once-Through Steam Generator
 Repair Kinetic Expansion Technical Rept " Withheld (ref
 10CFR2.790)
 MOGREJ P. Babcock & Wilcox Co. GPUN-TDR-007 B2/11/30 #648
 22112 304 24X Fichs 30-289,83/10/27,8402060028.
- --8302020052 Responds to 830113 request to review util safety evaluation for return of facility to svc after steam generator repair Response to encl questions necessary for completion of NER 6 EIA.

 CONNEL,F J Radiological Assessment Branch, 83/01/25 VASSALLO, D Operating Reactors Branch 2, 3pp. 22112:124 24 Fichs: 50-289, 83/10/27, 8402060028
- --8302020181 Forwards significant hazards determination on State Generator Recovery Program & review of licensee B21210 assessment of plant safety for return to svc Causative agent & potential sources identified Hazard does not effect VOLLMER: H Division of Engineering. 83/01/24. EIBCN:#UT.P 9 Division of Licensing 13pp 22112:115 24X Fichs 50-289,83/10/27,8402040028.
- --8303i10519 Provides schedule re preparation of restert BER. sweettws-1 to ence-through steam generator repairs, due 830510 MCCRACKEN.C Chemical Engineering Branch. 83/03/08, FRANK.L Materials Engineering Branch. 2pp 22112-131. 24X Fiche: 50-289, 83/10/27, 8402060028.
- --8303280015 Forwards revised draft technical evaluation rept. *[m] U.s.
 1 Steam Generator Degradation & Repair."
 AUERBACH.C. Brookhaven National Laboratory. FIN A-3360
 83/03/24 TUROULIN.B NRC No Detailed Affiliation Given is
 22111 166 24X Fiche: 50-289,83/10/27,8402060028.

- --8303280024 "TMI Unit 1 Steam Generator Degradation & Repair," draft technical evaluation rept BANDY:R Brookhaven National Laboratory FIN A-3380 83/03/23. NRC -- No Detailed Affiliation Given 15pp 22111 167 24X Fiche: 50-289:83/10/27,8402060028
- --8303300416 Comments on schedule for BER submittal re facility steam generator Current estimated date for BER issuance is 830509 EISENHUT.D 9 Division of Licensing 83/03/25 VDLLMER.R Division of Licensing 1p 22112 261 24X Fiche: 30-289.83/10/27. RADDAGODS
- ---B30401004B Notifies that BNML requires period of performance extension due to late completion of licensee repairs & delay in scheduling of hearing for Contract FIN B-2506, "Evaluation of TMI-1 Steam Generator Corrosion"

 WU.P. Chemical Engineering Branch FIN B-2506 83/03/25

 VOLLMER.R H Division of Engineering 2pp 22112 167 24X
 Fiche, 50-289, 83/10/27, 840206028
- --8304050473 Forwards 830331 itr to V Gilinsky re collusion at facility Response to 820901 questions re microstructural characteristics of once-through steam generator tube matl not fully addressed in 821005 itr.Addi response requested. LEE, J. Affiliation Not Assigned 83/04/01 DENTON, H.R. NRC No Detailed Affiliation Given. 1p 22112-142, 24X Ficha 50-289,83/10/27,8402060028
- --8304050478 Discusses 830328 public forum re mismanagement violations NRC should investigate charges alleged by RD Parks (Bechtel engineer) concerning lack of cooperation in disseminating info within NRC.

 LEE, J. Affiliation Not Assigned. 83/03/31, QILINSKY, V. Commissioners. 2pp. 22112 163 24X Fiche 50-289,83/10/27,8402060028
- --8304130440 008 R02
 Proprietary Rev 2 to "Assessment of TMI-1 Plant Safety for Return to Svc After Steam Generator Repair " Withheld (ref 10CFR2, 790).
 MCRAN.T M Babcock & Wilcox Co. 83/03/30, 169pp 22113 038 24X Fiche 50-289,83/10/27,8402060028.
- --8304140047 Discusses schedule for BER submittal on steam generator Completion of SER by 830509 dependent upon receipt of all necessary into from licensee by 830405 meeting Outstanding issues listed.

 VOLLMER.R. Division of Engineering 83/04/04 EIBENHUT.D Q Division of Licensing. 2pp. 22112:169 24X Fiche: 50-287, 83/10/27.8402060028
- --8304280292 BAN-1760 R01
 Proprietary Rev 1 to "TMI-1 Once-Through Steam Cenerator Repeat, Kinetic Expansion Technical Rept." Withheld tref 10CFR2 790).
 MORE, J.P. Bebcock & Wilcox Co. OPUN-TDR-007 83/03/31 199pp 22114:050 24% Fiche 50-289,83/10/27,8402060028
- --8304270219 Forwards SER for restart subsequent to once-through steam generator tube repairs. Actions taken, including 100% insp, preventive plugging & staking of critical tubes provide reasonable assurance defective tubes identified for repair LIAM, B D. Materials Engineering Branch 83/04/20 BENAROYA, V Chemical Engineering Branch, 7pp 22112 171 24X Fiche: 50-289, 83/10/27, 8402040028.
- --8304270275 Requests response to 8 listed questions submitted re regulatory connection, lask rates & tube walls, Addl names of persons to contact submitted HOSELER, D. E. Affiliation Not Assigned, 83/04/24. BTOLZ, J.F. Operating Reactors Branch 4 2pp. 22112; 165. 24% Fiche: 50-289, 83/10/27, 8402060028
- --8304270371 Requests draft inputs to once-through steam generator SER by 830425. Inputs needed to meet 830509 scheduled restart BER completion.
 MCCRACKEN, C. Chemical Engineering Branch 83/04/21 FRANK, L.
 Hechanical Engineering Branch 1p. 22112:178 24X
 Fiche: 50-289, 83/10/27, 8402040028.
- --B304270380 Trip rept of 830413 fifth third-party review meating in Parsippany,NJ re steam generators NDT acceptable. Minor recommendations on startup & insp procedures provided.

 BENARDYA.V. Chemical Engineering Branch. 83/04/21. JOHNBTON,W V. Assistant Director for Matle. Chem & Environ Technology (Fost 830201). 2pp. 22112-137. 24X Fiche. 50-289,83/10/27,8402040028
- --8305190338 Forwards 830421 ltr to J Stolz ra allowable steam tube leak rates on 790301 & current allowable leak rate. Response not yet received.
 HOSSLER, D. E. Affiliation Not Assigned. 83/05/16. DENTON, H R. Office of Nuclear Reactor Regulation, Director. ip 22112:259, 24X Fiche: 50-289, 83/10/27, 8402060028

- --B305240101 Submits status of steam generator repair review SER inpresented by 830520
 EIGENHUT.D Division of Licensing 83/05/17 VOLLMER.R
 Division of Engineering 2pp 22112 274 24X
 Piche 50-289,83/10/27.8402040028
- --8306010054 Discusses status of steam generator tube rupture guidel & procedures review. Mat1 presented during 830428 site visit preliminary w/consistencies & handwritten corrections Qverall strategy & options must be clarified CLAYTON. H B Procedures & Bystems Review Branch 83/05/09 BTOLZ. J F Operating Reactors Branch 4 ip 2212 148 24X Fiche 50-289,83/10/27,8402060028
- --8306010480 Forwards Chemical Engineering Branch draft safety evakt based on review of licensee 830207 submittal re post-accident sampling sys Licensee meets five of 11 criteria in NUREQ-0737. Item II B 3 JGHNSTON. W V. Assistant Director for Matls, Chem & Environ Technology (Post 830201) TAC 48284 83/05/23 LAINAS. Q Assistant Director for Operating Reactors 11pp 22112 180 ; Fiche 50-889,83/10/27,8402060028
- ~~8306020257 Advises that steam generator repair GER will be issued following receipt of third-party review from licenses VDLLMER.R H Division of Engineering. 83/05/23 EISENHUT.D O Division of Licensing. Ip 22112 171 24X Fiche 50-289,83/10.8402060028
- --830&030387 Forwards safety evaluation for return to see after republicans conditions and Johnston, W/o SER Proposed license conditions and Johnston, W/o SER Proposed license conditions and Johnston, W/O Assistant Director for Matls, Chem & Environ Technology (Post 830201) TAC 47484 83/03/24 LAINAB.G C Assistant Director for Operating Reactors 65pp 22112 192 : Fiche 50-289,83/10/27,8402060028
- --8306150573 Initial no significant hazards consideration determina noticing action re 830507 application for Tech Spec change to permit steam generator repairs by plugging or any method approved by NRC.

 8ILVER.H NRC No Detailed Affiliation Given 83/05/19 3pp 22112 276 24X Fiche 50-289,83/10/27,8402060028,
- --8307150063 Informs that BER input on steam generator repair will submitted by 830520 Review will commence as soon as licensee info re tube rupture procedures received THOMPSUN.H.L. Division of Human Factors Bafety 83/05/19 EIBENHUT:D Q Division of Licensing. Ip 22(12) 179, 24X Fiche 50-289,83/10/27,8402040028
- --8402060076 Bummarires 821018-19 meetings in Bethesda, MD re steam generator repair DDDD, C.V Oak Ridge National Laboratory 82/10/27 MCCLUNG, R Dak Ridge National Laboratory, 2pp. 22112 033 24X Fiche. 50-289, 83/10/27, 8402050028
- --84020A0243 Requests input for steam generator tube rupture proced guidelines review by 830509 Rev 2 to GPU Topical Rept 00B, Section X encl. 870LZ,J.F. Operating Reactors Branch 4 83/04/11 CLAYTON, B Procedures & Systems Review Branch. 12pp 22112 262 24X Fiche 50-289,83/10/27,840204002B.
- --BR06210343 Forwards proposed program, schedule & level of technical effort required for accomplishing tentative work assignment J & eveluation of TMI-1, steam generator tube sealing program PANDEY, 8. Franklin Institute/Franklin Research Center. NRC-03-81-130, 82/06/17 BAJHA: 8 S. NRC ND Detailed Affiliation Given. Spp. 22112 143 24X Fiche 50-289.83/10/2, 2440540020
- --820627060B Requests review of encl tentative work assignment J,
 "Evaluation of TMI-1 Steam Generator Tube/Tube Sheet
 Repair: Notification as to whether proposed schedule can be
 met & estimate of required manpower resources.
 BAJHA, B. B. NRC No Detailed Affiliation Given NRC-03-B1-13:
 B2/06/14. PANDY: B Franklin Institut/Franklin Research Cent
 4pp. 22112;139. 24X Fiche 50-289,83/10/27,8402060028.
- --8207090028 Advises that once-through steam generator spect for f have been sent to Franklin Research Ctr.per 820702 telcon, GRAHAM J. General Public Utilities - GPU Service Corp E&L:4408 B2/07/06, MCCRACKN,C NRC - No Batalled Affiliat Given. ip. 22111:165 24X Fiche.50-289,83/10/27,8402060028
- --8207140125 Summary of 820621 meeting w/util.Foster Whesler,8&W & Franklin Research Ctr in Livingston.NJ re steam generator tube tubesheet repair. Details of kinetic expansion process expected to be finalized before NRC 820627 meeting RAJAN.J Mechanical Engineering Branch 82/06/28 BOSNAK.R. Mechanical Engineering Branch 78p. 22112:149 24X Fiche 50-289,83/10/27,8402060028

- ~-B207200441 Informs of General Public Utils tentative schedule for fullscale test on TMI-1 once-through steam generator at Mount Vernon, IN for wk of B20726 JACDBS, R Operating Reactors Branch 4 B2/07/09 £ISENHUT, D O Division of Licensing ip 22112.260 24X Fiche 50-289,83/10/27, 8402060028
- --8207300124 Asks to be informed of any info sent to M Lewis re thiosulfate theory & steam generator corposion WHITE, J M Affiliation Not Assigned 82/07/27 PENTON, M R Office of Nuclear Reactor Regulation, Director 1p 22112 156
- r-B207300136 Discusses steam generator corrosion which makes thiosulphate theory suspect & makes explosion repair both suspect & dangerous Facts suggest cause of corrosion not thiosulphate Requests NRC not approve steam generator repair LEWIS:M Y Lewis, M 82/07/27 DENTON; H R Office of Nuclear Reactor Regulation, Director. 3pp 22112 157 24X Fiche 50-289,83/10/27.8402060028
- --B20B090285 Informs of printing costs for TNI-1 steam generator tube destructive exam rept
 BENARDYA.V Chemical Engineering Branch. B2/08/03 MCVEAGH, H
 Division of Technical Information & Document Control. 1p.
 22111 189 24X Fiche 50-289,83/10/27,8402040028
- --8208250400 Responds to 820723 ltr re insufficient util effort being focused on sulfur removal from surfaces at facility Desulfurization necessity & viability being determined. Restart plans to be revisued following 820819 meeting BENAROYA. V Chemical Engineering Brench 82/08/06 MACDONALD.D D Affiliation Not Assigned 2pp 22111.143 24X Fichm 50-289,83/10/27,8402060028
- --8208310181 "TMI-1 Once-Through Steam Generator Repair Safety Analysis " Withheld (ref 1005R2 790) * General Public Utilities - OPU Service Corp 82/08/20 36pp 22113,214 24X Fiche 30-289,83/10/27,8402060028
- --B20B310444 Provides schedular update & summary of 820B05 full-scale expansion demonstration at Mt Vernon. IL & B20B05 review of eddy current test program & results at TMI-I Detailed meeting minutes will be provided by project manager MCCRACKEN.C Chemical Engineering Branch 92/08/17 BENAROYA, V Chemical Engineering Branch 32/08/17 BENAROYA, V Fiche 50-289, 83/10/27, 8402040028
- --8209280423 Provides status of steam generator repairs as discussed in 820825,0901-02 meetings Schedule of future meetings retrepairs listed Periodic Insps will monitor for initiation of new defects & corrosion rate MCCRACKEN.C. Chemical Engineering Branch 82/09/10 BENARDYA.V. Chemical Engineering Branch 82/09/10 BENARDYA.V. Fiche 50-289,83/10/27,8402060028
- --8209280427 Comments on B&H Rept 77-1135317, "Evaluation of Tube Samples From TMI-1 " Rept describes thorough & comprehensive evaluation of Incomel-600 tubes removed from steam generators subsequent to detection of leaks MACDONALD, D D Affiliation Not Assigned 82/08/30 BENARDYA, V Chemical Engineering Branch 4pp. 22111:182 24X Fiche: 30-289, 83/10/27, 8402060028.
- ---8210070023 Advises that safety evaluation necessary prior to restart to determine that licenses took proper steps to recover from once-through steam generator corrosion problem VOLLMER, R Division of Engineering 82/09/17 EISENHUT, D. Division of Licensing ip 22/11/201 24X Fichs:50-289,83/10/27,8402060028
- --8210130553 TR-006 R01
 Revision 1 to "TMI-1 Steam Generator Repair Sefety
 Evaluation " Withheld (ref 10CFR2 790)
 GRAMAM N J General Public Utilities GPU Service Corp.
 82/09/30 38pp 22113 259 24X Fiche 50-289.83/10/27.8402050028
- --8210290115 Requests fuller explanation of encl B0 Eisenhut 820809 ltr re performance of repaired tubes in event of transients &/or accidents during operation. LEWIS: H I. Lewis: K 82/10/25. EISENHUT. D. Q. Division of Licensing. 1p 22112-160. 24X Fiche: 50-289, 83/10/27, 8402060028
- -821109059B Forwards BMI final rept on failure analysis of tubes removed from TMI-1 steam generators Encl rept supple B&W rept distributed on BZOB19. Repts ddd BZOB20 on radwaste systetainer exam being distributed, W/o encl. MCCRACKEN.C. Chemical Engineering Branch. 82/10/27. BENARDYA, V Chemical Engineering Branch. 82/10/27. BENARDYA, V Fiche: 50-289, 83/10/27, 8402060028

- --821(1)0542 Notifies of untimely Battella request for extension of period of performance to 830331 for evaluation of steam generator corrosion assessment Extension deadline not met due to late request submittal MU-P Chemical Engineering Branch FIN B-2506 B2/10/26, VOLLMER.R H Division of Engineering ip 22111 202 24K Fiche 50-289,83/10/27,8402060028
- --B212150120 008 R01
 Revision i to EER, "Assessment of TMI-! Plant Safety for
 Return to Svc After Steam Generator Repair " Withheld
 (ref JOCR2 770)
 MDRAN.T M Babcock & Wilcox Co 82/12/07 115pp 22113-306
 24X Fishe 50-289,83/10/27,8402040028
- --8301060232 Forwards licensee 821207 safety assessment re restart subtequent to once-through steam generator repairs, for review Technical evaluation repts due by 830225 W/o safety assessment.

 MCCRACKEN.C Chemical Engineering Branch 82/12/20 MACDONALD.D Ohio. State of 2pp 22112 294 24X Fiche 50-289.83/10/27.
- --8301250628 BAH-1760
 Proprietary "THI Unit 1 Once-Through Steam Generator
 Repair, Kinetic Expansion Technical Rept " Withheld (ref
 100FR2 790)
 MODRE. J P Babcock & Wilcox Co GPUN-TDR-007 82/11/30 96pp
 22112-304 24X Fiche 50-287, 83/10/27, 8402060028
- --8302020052 Responds to 830113 request to review util safety evaluation for return of facility to svc after steam generator repair. Response to sncl questions necessary for completion of SER & EIA CONGEL.F J Radiological Assessment Branch 83/01/25 VASSALLG.D Operating Reactors Branch 2 3pp 22112:128 24X Fichs 50-289,83/10/27,840206028
- --B302020181 Forwards significant hazards determination on Steam Generator Recovery Program & review of licensee B21210 assessment of plant safety for return to svc Gausative agent & potential sources identified Hazard does not exist VOLLMER.R H Division of Engineering 83/01/24 EISENHUT.D. Ø Division of Licensing 13pp 22112 115 24X Fiche.50-289.83/10/27.8402060028
- --8303i10519 Provides schedule re-preparation of restart 8ER, subsequent to once-through steam generator repairs, due 830510 MCCRACKEN.C. Chemical Engineering Branch. 83/03/08 FRANK, L Materials Engineering Branch 2pp 22112 131 24X Fiche 50-289, 83/10/27, 8402060028
- --8303280015 Forwards revised draft technical evaluation rept, "TMI Unit 1 Steam Generator Degradation & Repair " AUERBACH C Brookhaven National Laboratory FIN A-3380 83/03/24, TUROULIN, B NRC - NO Detailed Affiliation Given 1p 22111 166 24X Fiche 50-289,83/10/27,8402060028.
- --8303280024 "TMI Unit 1 Steam Generator Degradation & Repair." draft technical evaluation rept BANDY.R Brookhaven National Laboratory FIN A-3380 83/03/23 NRC No Datailed Affiliation Given, 15pp 22111-167 24X Fichs: 50-289, 83/10/27, 8402040028
- --8303300416 Comments on schedule for BER submittal refacility steps generator Current estimated date for BER issuance is 930507.5 EISENHUT, D © Division of Licensing 83/03/25 VOLLMERS. Division of Licensing ip. 22112-261. 24X Fiche 50-289,83/10/27,
- --8304010048 Notifies that BNWL requires period of performance extension due to late completion of licensee repairs & delay in scheduling of hearing for Contract FIN B-2506. "Evaluation of TMI-I Steam Generator Corrosion"

 MU-P Chemical Engineering Branch. FIN B-2506, 83/03/25, VOLLMER.R. H. Division of Engineering 2pp 22112 167, 24X Fiche 50-289,83/10/27,8402060028.
- --B304050473 Forwards 830331 ltr to V Gilinsky re collusion at facility Response to 820901 questions re microstructural characteristics of onca-through steam generator tube matinot fully addressed in 821005 ltr. Addl response requested. LEE, J. Affiliation Not Assigned. B3/04/01, DENTON, M.R. NMG No Detailed Affiliation Given ip 22112-162 24X Fiche 50-289,83/10/27,8402060028.
- --8304050478 Discusses 830328 public forum re mismanagement violations NRC should investigate charges alleged by RD Parks (Bechtel engineer) concerning lack of cooperation in disseminating info within NRC.

 LEE, J. Affiliation Not Assigned. 83/03/31 OILINSKY, V. Commissioners 2pp 22112 163 24X Fiche: 50-289, 83/10/27, 8402040028

- ---B304130440 00B R02
 Proprietary Rev 2 to "Assessment of TMI-1 Plant Safety for Return to Byc After Steam Generator Repair" Withheld (ref 10CFR2 790)
 MURAN.T H Babcock & Wilcox Co 83/03/30 169pp 22113 038 24X Fiche 50-289, 83/10/27, 8402060028
- --B304140047 Discusses schedule for SER submittal on steam generator Completion of SER by B30509 dependent upon receipt of all nacessary info from licensee by B30405 meeting Outstanding issues listed VOLLMER.R Division of Engineering B3/04/04 EIBENHUT.D 9 Division of Licensing 2pp 22112 167 24X Fiche 50-289, B3/10/27,8402060028
- --8304250292 BAW-1740 R01
 Proprietary Rev 1 to "TMI-1 Once-Through Steam Generator Repair.Kinetic Expansion Technical Rept " Withheld (ref 10CFR2 790)
 MODRE.J P Babcock & Wilcox Gq OPUN-TDR-007 83/03/31 199pp 22114:030. 24X Fiche 50-289.83/10/27,8402060028
- --8304270219 Forwards BER for restart subsequent to once-through steam generator tube repairs Actions taken, including 100% insp. preventive plugging & staking of critical tubes provide reasonable assurance defective tubes identified for repair LIAN-B D. Materials Engineering Branch 83/04/20 BENARDYA, V Chemical Engineering Branch 7pp 22112 171 24% Fiche 50-289,83/10/27,8402060028
- --B304270275 Requests response to 8 listed questions submitted re regulatory connection; leak rates & tube walls Addl names of persons to contact submitted MOSSLER, D. E. Affiliation Not Assigned, 83/04/24 STOLZ, J. F. Operating Reactors Branch 4 2pp. 22112 165 24X Fichs: 50-289, 83/10/27, 8402060028
- --B304270371 Requests draft inputs to once-through steam generator SER by B30425. Inputs needed to meet B30509 scheduled restart BER completion
 MCCRACKEN,C. Chemical Enginesring Branch. B3/04/21 FRANK, L
 Hechanical Engineering Branch. Ip 22112 178 24X
 Fiche: 30-289, B3/10/27, B402060028
- --8304270380 Trip rept of 830413 fifth third-party review meeting in Parsippany.NJ re steam generators NDT acceptable.Minor recommendations on startup & insp procedures provided BENARDYA.V Chemical Engineering Branch 83/04/21 JOHNSTON.W V Assistant Director for Matls, Chem & Environ Technology (Post 830201). 2pp 22112 137. 24X Fiche 50-289,83/10/27,8402060028
- --8305190338 Forwards 830421 ltr to J Stolz re allowable steam tube leak rates on 790301 & current allowable leak rate Response not yet received HOSBLER, D. E. Affiliation Not Assigned 83/05/16 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ip 22112 259, 24X Fiche 50-289, 83/10/27, 8402060028
- --8305240101 Submits status of steam generator repair review SER input requested by 830520.
 EISENHUT, D Division of Licensing 83/05/17 VOLLMER, R. Division of Engineering 2pp 22112, 274 24X Fichs 50-289, 83/10/27, 8402060028.
- --B30&010054 Discusses status of steam generator tube rupture guidelines & procedures review. Mat1 presented during 830428 site visit preliminary w/consistencies & handwritten corrections. Overall strategy & options must be clarified. CLAYTON. H B Procedures & Systems Review Branch 83/05/09 STOL7. J. F Operating Reactors Branch 4 ip. 22112-148 24X Fichs: 50-289, 83/10/27, 8402060028.
- --8306010480 Forwards Chemical Engineering Branch draft safety evaluation based on review of licensee 830209 submittal repost-accident sampling sys Licensee meets five of 11 criteria in NUREO-0737. Them II. B. 3.

 JOHNSTON, W. V. Assistant Director for Matls. Chem & Environ Technology (Post 830201). TAC 48884. 83/05/23. LAINAS. 0
 Assistant Director for Operating Reactors 11pp 22112:180. 24X
 Fichs. 50-289, 83/10/27, 8402060028
- --8306020257 Advises that steam generator repair SER will be issued 1 day following receipt of third-party review from licenses VOLLMER.R.H Division of Engineering 83/05/23 EIBENHUT, D 0 Division of Licensing ip. R2112-191, R4X Fiche-50-289, 83/10/27, 8402060028
- --B30A0303B7 Forwards safety evaluation for return to svc after repair of once-through steam generator corrosion. W/o BER. Propused license conditions encl.

 JOHNSTON. W. V. Assistant Director for Matls. Chem & Environ Technology (Post 830201). TAC 47484 B3/05/24 LAINAB. G. C. Assistant Director for Operating Reactors. 65pp. 22112:192 24X Fiche: 50-289, 83/10/27, 8402060028

- --8306150973 Initial no significant hazards consideration determination & noticing action re 830509 application for Tach Spec change to permit steam generator repairs by plugging or any method approved by NRC SILVER.H NRC No Detailed Affiliation Given 83/05/19 3pp 22112 276 24X Fiche 50-289,83/10/27,8402060028
- --8307150063 Informs that SER input on steam generator repair will not be submitted by 830520 Review will commence as soon as licensee info re tube rupture procedures received THOMPSON.H L Division of Human Factors Safety 83/05/19 EIBENHUT.D Q Division of Licensing ip 22112 179 24X Fiche 50-289,83/10/27,8402060028
- --8402060076 Summarites 821018-19 meetings in Bethesda, MD re steam generator repair DDDD.C V Oak Ridge National Laboratory 82/10/27 MCCLUNG, R W Oak Ridge National Laboratory 2pp 22112 033 24X Fiche 50-289, 83/10/27, 8402060028
- --B402060243 Requests input for steam generator tube rupture procedures & guidelines review by B30509 Rev 2 to GPU Topical Rept ODB.
 Bection X end:
 BTOLZ, J F Operating Reactors Branch 4 B3/04/11 CLAYTON, B H
 Procedures & Bystems Review Branch 12pp 22112 262 24X
 Fiche 50-289, B3/10/27, 8402060028
- 8402060043 Discusses possible unauthorized disclosure of safeguards info re recent shipments of spent fuel from Chalk River Nuclear Labs to DDE, Savannah River plant FITZGERALD, J A Office of Investigation 82/09/09 AHEARNE, J F Commissioners, 4pp 22091, 290
- 8402040284 Further response to FOIA request for IE 800103 rept re review of meth false statement at facility & all associated & supporting records to rept Forwards documents listed in App C App B documents available in FDR FELTON, J M Division of Rules and Records 83/11/15 WINBLOW, R Wall Btreet Journal 3pp 22111 068 24X Fiche 50-329, 83/11/15, 8402040284
- --7904100117 Board notification Midland settlement problem Concurs w/ decision to inform OL Board of settlement of diesel generator bldg CP Board or Commission notification unnecessary VASSALLO.D B Assistant Director for Light Water Reactors 78/11/13 ENGELHARDT.T F Hearings Division ip. 22111-073 24X Fiche 50-329.83/11/15.8402040284
- --7904100122 Board notification diesel generator foundations & hldg settlement at Midland Recommends that ltr of notification be prepared which would apprise appropriate Boards & Commission of subj matter. OLMSTEAD.N.J Hearing Branch 4 78/11/03 VASSALLO.D B Assistant Director for Light Water Reactors 1p 22111 072 24X Fiche 50-329,83/11/15.8402060286
- ---7910230546 Requests assistance to ensure that engineering branch positions re facilities soil settlement issues are documented & forwarded to applicant as soon as possible.
 RUBENSTEIN, L B Light Mater Reactors Branch 4. 79/09/27
 KNIGHT, J P Assistant Director for Engineering 2pp 22111 109
 24X Ficher50-329,83/11/15.8402060286
- --8402060297 Forwards insp repts & licensee repts to settlement of direct generator bldg for referral to licensing board KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/20 THORNBURG, H D Division of Reactor Construction Inspection. 2pp 22111.074, 24% Fiche 50-327.83/11/15.8402060286
- --8402060303 "Presentation of Investigation Findings of Bettlement of Diesel Generator Bldg & Plant Area Fill, " * Region 3, Chicago: Office of the Director 79/02/23 16pp 22111 076. 24% Fiche 50-329/83/11/15,8402060286.
- --8402060309 Forwards proposed ltr to util,draft notice of violation & draft notice of proposed imposition of civil penalty Panalty recommended only for math false statement.

 KEPPLER, J 9 Region 3. Chicago, Office of the Director 79/10/29 GOHER, G.C Executive Officer for Operations Support. 17pp 22111-092 24X Fiche, 50-329, 63/11/15, 8402060286
- 8402060325 Further response to FOIA request for documents re image intensified fluoroscope for immediate X-ray exam of suspect objects using radiation sources mag by Lixi. Inc Forwards documents Info partially withheld (ref FOIA Exemption 4) FELTON.J.M Division of Rules and Records 83/11/09 9HILTON,M G Amersham Corp 2pp. 22111.013

- --8402060329 Application for amend to Matl/Byproduct License 12-18213-01, authorizing changes in mart used in handle scope holder & electrical housing of Madel LE-80-x Liziscope & adding approval for medical device use SAVINI,R J LIXI, Inc 12543 B2/09/10 WRIGHT,E G Division of Fuel Cyrle & Material Safety 15pp 22111 016
- 840g050332 Further response to FOIA request for documents re security violations & safeguards events at nuclear facilities Forwards LACBHR inspirent on firearms qualification faistfication. Info partially deleted (ref FOIA Exemption 7) FELTON.J M Division of Rules and Records 83/11/08 OOLDENBERG, G Scripps-Howard Newspapers 1p 22110 316 24X Fiche 50-409.83/11/08.8402060332
- --B402060342 Forwards IE Investigation Rept 50-409/77-07 on 770425-27 \$
 0502.suggesting possible violation arising from math
 misrepresentations by Wisconsin Security Bureau re training
 of contract security guards
 MCTIERNAN.T J Office of Inspector & Auditor 77/09/07
 CIVILETTI.BR Justice. Dapt of 3pp 22110 313 24X
 Fiche 50-409.83/11/08.8402060332
- --8402060348 IE Investigation Rept 50-409/77-07 on 770425-27 & 0502 Noncompliance noted security guard qualification records fatsified by guard svc contractor by backdating Info partially deleted FOSTER.J E., MADEDA.T J., HIND.J A. Region G. Chicago, Office of the Birector 77/05/31 43pp 22110 316 24X Fiche 50-409, 83/11/08, 8402060332
- B402070017 Further response to FOIA request for SECY-83-245 & SECY-83-247 & documents re training &/or testing program or cheating incidents at fecility No documents responsive to request located FELTON, J M Division of Rules and Records B3/10/03 DOROSHOW, J Three Mile Island Alert ip 22142 264 24X Fiche 50-289,83/10/03,8402070017
- 8402070020 FOIA request for SECY-83-202, "Generic Lessons Learned From Completed Licensing Reviews." to be placed in NRC PDR ADATO.N Union of Concerned Scientists 83/12/08 FELTON.J M Division of Rules and Records ip 22142 235
- 8402070027 Responds to FOIA request for SECY-83-202, "Generic Lessons Learned From Completed Licensing Reviews," to be placed in PDR Forwards SECY-83-202 Document also placed in PDR FELTON, J M Division of Rules and Records 83/12/27 ADATO, M Union of Concerned Scientists Ip 22142 256
- --8402070032 SECY-83-202
 Responds to Commission request for views on generic lessons
 learned from completed licensing reviews of human factors
 areas
 DIRCKS, H U Office of the Executive Director for Operations.
 83/05/26 7pp 22142 207
- 8402070028 FOIA request for records generated in connection w/TA Rehm B31117 ltr to BP Oarde re Midland Caseload Forecast Panel. GARDE. B P Government Accountability Project B3/11/26 Office of Administration 2pp 22142 248 24X Fiche 50-329.83/11/26, 8402070028
- 8402070030 Responds to FOIA request for documents re Dow Chemical Couse &/or disposal of radioactive matls No records available pertaining to license authorizing deep well disposal of radioactive matls
 FELIDN.U H Division of Rules and Records 83/12/30 WILSON.A K Environmental Congress of Nid-Michigan 1p 22142 246.
 - --^^70034 FDIA request for documents re Dow Chemical Co use &/or sal of radioactive matls, excluding info pertaining to cineration of radioactive matls

 A K Environmental Congress of Mid-Michigan 83/12/03

 Division of Rules and Records ip 22142 247
 - 8 Responds to FOIA request for records generated in connection hm 831(17 ltr to 8P Garde re Midland Caseload t Panel Forwards App A document Eight draft documents in App 8 withheld (ref FDIA Exemption 5)

 J H Division of Rules and Records 83/12/28 GARDE, 8 P ment Accountability Project 3pp 22142.250 24X
 50-329.83/12/28.8402070038
 - 70044 "Plan for Developing Using & Updating NRC Independent actor Const Completion Estimates"
 NRC No Detailed Affiliation Given 63/12/28 2pp 142 293.

- 8402070039 Final response to FDIA request for documents re-emergery operation facilities located 10-20 miles from nuclear plants & info approving/denying location over 20 miles away Forwards listed documents Info also available in PDR FELTON, J M Division of Rules and Records 83/11/04 O'NEILL, J R Shaw. Pittman. Potts & Treubridge ip 22142 148 24% Fiche 50-000.83/11/04.8402070039
- --8309120090 SECY-83-363
 Recommends Commission agree w/approval of util position to establish common backup emergency operations facility for Prairie Island & Monticello nuclear generating plants DIRGKS.W J Office of the Executive Director for Operations 83/08/30 860P 22142 151 24X Fiche 50-000.83/11/04.840207073
- --8402070045 Advises of Commission approval of util decision to stablish emergency operations facilities 45 & 55 miles from respective sites
 CHILK, S.J. Office of the Secretary of the Commission. B3/09/26
 DIRCKS, W.J. Office of the Executive Director for Operations is 22142 149 24X Fiche 50-000,83/11/04,8402070039
- 8402070041 Responds to FOIA request for rept on Price-Anderson Att. mentioned in 830728 issue of Nucleonics Wk NUREO-0957, "Price-Anderson Act - Third Decade." encl.W/o encl FELTON, J M Dyvision of Rules and Records 83/12/28 WILSON.BK International Energy Associates, Ltd 1p 28142 278
- 8402070043 FOIA request for draft rept on Price-Anderson Act.mentions in B30728 issue of Nucleonics Wk
 WILSON, B K International Energy Associates, Ltd 83/12/14
 FELTON, J Office of Administration ip 22142 279
- B40207004B Responds to FOIA request for computer printout of all active NRC meth licensees & two sets of gummed peek-off mailing labels Computer printout & mailing labels completed FELTON J M Division of Rules and Records 83/12/27 DRIBCOLL&J Affiliation Not Assigned 1p 22142 R44
- 8402070049 FOIA request for computer printout of all active NRC satilizensees & two sets of gummed peel-off mailing labels
 DRISCOLL, W.J. Affiliation Not Assigned 83/11/29 Division of Rules and Records ip 22142 245
- 8402070050 Responds to FOIA request for documents re PUREX plant located in Hanford, WA PUREX plant not licensed by NRC, but is contractor for DOE No documents responsive to request located DOE should be contacted to obtain documents FELTON, J M Division of Rules and Records 83/12/30. TIERNEY, J ? Affiliation Not Assigned ip 22142 242
- 8402070055 FOIA request for documents re overall operation of PUREY plant located in Hanford WA TIERNEY, J.P. Affiliation Not Assigned 83/11/22 NRC - No Detailed Affiliation Given ip 22142 243
- 8402080007 Responds to FDIA request for correspondence between NRC. JCP&L & Rochester Cas & Electric re shipment of irradiated fuel from West Valley.NY Forwards App A documents FELTON:J M Division of Rules and Records 83/12/30, RESNIKOFF.M. Sierra Club 2pp 22174 006
- 8402080009 FOIA request for correspondence between NRC, JCPML & Rochester Gas & Electric re shipment of irradiated fuel from West Valley, NY & correspondence on route applications between listed labs & Savannah River Plant REBNIKOFF, M Sierra Club 83/11/29 NRC No Detailed Affiliation Given 1p 22174,008 24X Fiche 50-000,83/11/29, B402080009
- 8402080013 FQIA request for five categories of info re nuclear design because grojects for 740101-830601
 TRAINGR.E F. Cygna Energy Bervices 83/08/26 FELTON.J. NHC No Detailed Affiliation Given 2pp 22142 282
- B4020B0014 Appeals denial of FOIA request for certain documents realterations by ITT Grinnell Corp of radiographs of welds in piping subassemblies
 FUQUA.D.M Wallace, Hilborn, Clayton, Calhoon & Forster, Ltd
 83/10/18 Office of the Executive Director for Operations. ip.
 22173 306
- 8402080017 Further response to FOIA request for five categories of infare nuclear design & const projects for 740101-830601.
 Forwards computer printout of index to repts, per 10CFR50 55e & 10CFR21, in response to Items 4 & 5 of request.
 FELTON, J M Division of Rules and Records 83/12/14 TRAINOR, E F Cygna Energy Services 1p 22142 284

- B402080019 Final response to FDIA request for documents re incident at facilities described in weekly info rept for wk ending B31007 App A documents available in PDR FELTON, J M Division of Rules and Records 83/12/08 SHDLLY, S C Union of Concerned Scientists 2pp 22174 001 24X Fiche 50-250,83/12/08,8402080019
- 8402080026 FOIA request for documents re facility hot functional testing problems, including broken thermowells, loose & broken reactor coolent pump parts & loose thermal sleeves
 BERNABEI, L. Government Accountability Project 83/10/17 Office of Administration 2pp 22170 251 24% Fichs 50-528, 83/10/17, 8402080026
- B4020B0027 Responds to appeal re denial of FOIA request for certain portions of five records on alterations by ITT Orinnell Corp of radiographs of welds in piping subassemblies Forwards Documents 10-14 of App A to Felton B30916 ltr DIRCKS,W.J. Office of the Executive Director for Operations B3/12/29, F040W,D.M. Wallace, Hilburn, Clayton, Calhoon & Forster, Ltd. 1p. R2173 S12 24X Fiche 50-397,83/12/29,8402080027
- --B4020B003B Responds to IE Bulletin B2-01 re Associated Piping & Engineering radiographs for piping welds less than 1/2 inch in thickness Pravious contractor will be notified & applicable radiographs will be reviewed JORDAN.R L. Johnson Controls. Inc IEB-82-01 82/07/06 COLLING.J T Region 4, Dffice of Director 2pp 22173:314 24X Fiche 50-397,83/12/29,84020B0027
- --8402080070 Handwritten transcript of JM Thompson RA Dovickak & JJ
 Andrews 820316 statements in Kernersville, NC re allegations
 concerning alterations of radiographs of weld subassemblies
 THOMPSON, J M., DUVICSAK, R A., ANDREMS, J J ITT Grinnell Industrial
 Piping, Inc (subs of ITT) 82/03/16 8pp. 22173-317
- --B4020B005B Responds to IE Bulletin 82-01 re-Associated Piping & Engineering radiographs for piping welds less than 1/2 inch in thickness Previous contractor will be notified & applicable radiographs will be reviewed.

 JORDAN.R.L. Johnson Controls, Inc. IED-82-01 B2/07/06
 COLLING.J.T. Region 4, Office of Director. 2pp 22173 314. 24X Ficha: 50-397, 83/12/29, 84020B0027
- --8462080070 Handwritten transcript of JM Thompson.RA Doviceak & JJ Andrews 820316 statements in Kernersville.NC re allegations concerning alterations of radiographs of weld subassemblies. THOMPSON.J M., DOVICSAN.R.A. ANDREMS.J. J. ITT Grinnell Industrial Piping. Inc. (subs of ITT) 82/03/16 8pp 22170-317
- 8402080027 Responds to FDIA request for documents re facility hot functional testing problems, including broken thermowells, loose & broken reactor coolant pump parts & loose thermal sleaves. Forwards App A documents. Documents also in PDR FELTON. J.M. Division of Rules and Records 83/11/16 GARDE, B, Government Accountability Project 3pp. 22170 253 24X Fichs. 50-000, 83/11/16, 8402080027
- --B310200052 Provides update on status of efforts for resolving anomalies found during hot functional testing involving RCB pumps, thermal sizeves, thermostles C-E shroud assemblies & metal filings on upper support structure.
 LICITRALE A Licensing Branch 3. 83/10/11 NOVAK, T.M Assistant Director for Licensing. 2pp. 22171:119. 24X
 Fiche: 50-000, 83/11/16, 8402080029.
- --B4020B0047 Task interface agreement action plan re RCB damage discovered during evaluation of hot functional testing HOLAHAN.@ , VOLLHER;R. NRC No Detailed Affiliation Given BISHOP,T. Region 5. Office of Director. TAC 141435 B3/08/16 1p. 22170.279. 24X Fiche: 50-000.83/11/16,84020B0029
- ----8402080064 Forwards listed reactor coolant pump drawings per 830818 FOIA Request 83-448 re pump problems.

 \$18HOP.T.W. Division of Resident-Reactor Project & Engineering Programs. 83/09/16. VAN BRUNT.E.E. Arizona Public Service Co 11pp. 22170 286. 24X Fiche: 50-000, 83/11/16.8402080029

- --8402080077 91HF-18F02 ROO
 Preliminary Rev O to "Atmospheric Dump Valve Hot Functional
 Test:" test results rept for 830503-0822
 GRIZZARD, T. Affiliation Not Assigned 18078/09788 83/08/25
 11pp 22170 351 24X Fiche 50-000,83/11/16.8402080029
- --B4020800B2 91HF--18101 ROO
 Preliminary Rev O to "Pre-Core Safety Injection Check Valve
 Test: "test results rept for 830602
 DOYLE, K A Affiliation Not Assigned 83/09/14 6pp 22170 362
 24X Fiche 50-000,83/11/16,8402080029
- --8402080088 91HF-19F03 R00 DR 07 Draft 7 of preliminary Rev 0 to "Pre-Core Turbine Bypass Control Sys Test:" test results rept for 830601-0705 HENEAGE, J Affiliation Not Assigned 1797009788 83/09/17 20pp 22171 006. 24X Fiche 50-000,83/11/16,8402080029
- --8402080095 91HF-1CH01 R00
 Preliminary Rev O to "Pre-Core Chemical & Vol Control Sys
 Integrated Test," test results rept For 830604-0704
 * Affiliation Not Assigned 83/09/19 5pp 22171 026 24X
 Fichs 50-000, B3/11/16, 8402080029
- --8402080101 91HF-18001 ROO Preliminary Rev O to "MSIV & Bypass Valves Hot Functional Tast," test rasults rept for 830602-0703 CHILDRESS,E T Affiliation Not Assigned 18248/0978B 83/08/25 18ps. 22171 031 24X Fiche 50-000,83/11/16,8402080029
- --8402080107 91HF-1ED01 R00
 Preliminary Rev O to "Main Steam Traps & Drain Valves Hot
 Functional Test," test results rept for 830606-15
 * Affiliation Not Assigned 83/09/07 4pp 22171 049 24X
 Fiche 50-000,83/11/16,8402080029
- --8402080111 91HF-1RC02 ROO Preliminary Ray O to "Pressurized Performance," test results rept for 830603-17 STEARNS, W. Affiliation Not Assigned, 83/08/20 6pp 22171 053 24X Fiche 50-000,83/11/16,8402080029
- --8402080116 92HF-18V01 R00 Preliminary Rev O to "Loose Parts & Vibration Monitoring Bys Hot Functional," test results rept for B30506-0607 SCHMIDT, C R Affiltation Not Assigned B3/06/14 4pp 22171 059 24X Fiche 50-000.83/11/16.8402080029
- --8402080119 93HF-1MA05 ROO
 Preliminary Rev O to "Main & Auxiliary Transformer
 Backford," test results rept for 830420-0515
 * Affiliation Not Assigned 83/07/21 5pp. 22171 063 24X
 Fiche 50-000, 83/11/16,8402080029
- --8402080123 71HF-1RC01 R00
 Preliminary Rev O to "RCS Expansion Measurements," test
 results rept for 830411-0715
 * APFILIation Not Assigned, 83/07/27 3pp 22171 068 24X
 Fichs. 50-000, 83/11/16,8402080029
- --8402080129 91HF-1AF01 R00 Preliminary Rev O to "Pre-Core Emergency & Auxiliary Feedwater Sys Test," test results rept for 830503-0703 MORELAND, J W Affiliation Not Assigned, 83/10/15 i5pp. 22171 071 24X Fiche.50-000,83/11/16,8402080029
- --8402080136 92HF-12201 ROO
 Preliminary Ray 0 to "Pre-Core Instrumentation Correlation,"
 test results rept for 830516-0701
 RUTMAN, J. Affiliation Not Assigned DN-18218/09598, 83/10/05
 31pp 22171 OB6 24X Fiche 50-000, 83/11/16, 8402080029
- --B4020B0i43 Submits daily highlight re reactor coolent pump problems following Jul 1983 hot functional testing Util to meet w/vendor to discuss course of action LICITRA, E A Licensing Branch 3 63/08/04 DENTON, H, CASE, E, EISENHUT, D NRC No Detailed Affiliation Given 2pp. 22171, 117 24X Fiche. 50-000, 83/11/16, 8402080029.
- 8402080033 Further response to FOIA request for documents re cleanup & decision to close down U mill in Edgemont, 8D. Forwards listed document
 FELTON, J. M. Division of Rules and Records, 83/11/16 GARBUS, M Frankfurt, Garbus, Klein & Selz ip. 22172 347
- ---8402080037 Informs that NRC does not have authority to conduct cleanup activities of U mills at offsite locations in Edgement 8D NRC yearly authorization acts through FYSO do not grant NRC authorization BICKWIT-L. Office of the General Counsel 81/01/30 AHEARNE.J.F Commissioners. 2pp 22172 349

- 8402080039 Further response to FOIA request for documents re revised proposed rule on physical protection requirements for nonpower reactor licensees Forwards App A documents App B documents entirely withheld (ref FOIA Exemption 5) FELTON, J H Division of Rules and Records 83/11/04 AFTERGOOD, S Committee to Bridge the Gap 3pp 22172-269
- --B211270127 SECY-82-456
 Recommends that Commission approve publication for public comment of proposed amends to 10CFR73 Amends will establish physical protection requirements for nonpower reactor licensees possessing quantities of strategic GNM DIRCKS,W J Office of the Executive Director for Operations 82/11/16 29pp 22172 R87
- --8402080042 Disapproves SECY 82-456, "Physical Protection Requirements for Nonpower Reactor Licensees Possessing Formula Quantities of SSNR" Comments encl GILINSKY, V. Commissioners. 83/05/27 CHILK, S. Office of the Secretary of the Commission. 3pp. 22172 273
- --8402080044 Approves SECY 82-456. "Physical Protection Requirements for Nonpower Reactor Licensees Possessing Formula Quantities of SSMM." as modified ASSELSTINE, J Commissioners 63/06/02 CHILK,8 J Office of the Secretary of the Commission ip 22172 276
- --8402080044 Approves SECY 82-456. "Physical Protection Requirements for Nonpower Reactor Licensees Possessing Formula Quantities of SSNN," per Ofc of Policy Evaluation recommendation ROBERTS,T Commissioners 83/04/29 CHILK,S J Office of the Secretary of the Commission ip 22172 277
- --8402080049 Approves SECY 82-456, "Physical Protection Requirements for Nonpower Reactor Licensees Possessing Formula Quantities of SSMM: "as modified AHEARNE, J. Commissioners 83/03/18 CHILK.S.J. Office of the Secretary of the Commission Ip 22172 278
- --8402080051 Advises that State Dept should be contacted re intl implications of SECY-82-375 Related info encl AHEARNE, J Commissioners. 83/03/03 DIRCKS Office of the Executive Director for Operations 8pp 22172.279
- --B4020B0060 Responds to B30303 memo re coordination of rule on physical security of nonpower reactors (BECY-B2-156) w/Dept of State Dept of State has not taken position contrary to NRC, but intends to consider possible intl implication of provisions DIRCKS.W J Office of the Executive Director for Operations 83/03/17 AHEARNE, J Commissioners 2pp 22172-316
- ---B4020B0066 Advises that Commission approved SECY-B2-456. "Physical Protection Requirements for Nonpower Reactor Licensees Possessing Formula Quantities of SSNM." subj to listed items. Dissenting comments included. Related info enci CHILK.S J Office of the Secretary of the Commission 83/06/22 DIRCKS.J Office of the Executive Director for Operations Spp 22172 318
- --B4020B0048 Disapproves SECY-B2-436, "Physical Protection Requirements for Nonpower Reactor Licensees Possessing Formula Quantities of SBNM"
 PALLADINO,N J Commissioners B3/04/01, CHILK,S J. Office of the Secretary of the Commission 1p. 22172 323
- 8402080043 Further response to FOIA request for documents re cleanup & decision to close U mill in Edgement, SD Forwards App A, 8 & C documents.Review of remaining documents subj to request in progress FELTON, J. M Division of Rules and Records 83/11/01, GARBUS, M Frankfurt, Garbus, Klein & Belz 10pp, 22169 009.
- --7912180235 Discusses 791107 telcon re program to assess required offsite remedial action for Edgemont, SD. NRC has no objections to TVA procedures for soil sampling, TRACER.E A Uranium Recovery Licensing Branch 79/11/14 KALLEMEYN, V South Daiota, State of ip 22/69.259
- ---B003250487 Discusses working level measurements in Edgement, 9D. Bradford residence has highest working level determinations, Other manitored structures do not appear to be of immediate health risk concern EADIE.0 Uranium Recovery Licensing Branch B0/03/06 SCARANO, R A. Uranium Recovery Licensing Branch. 2pp. 22169:272
- --B402080048 Ack receipt of Feb 1981 monthly rept for Edgement cleanup action program "Proceedings of Workshop on Radiological Surveys in Support of Edgement Cleanup Action Program" will be Isaued as NUREO/CR-2083.

 EADIE, G C Uranium Recovery Licensing Branch FIN B-2217.

 B1/06/01 WOOMANN A Battelle Memorial Institute, Pacific Northwest Laboratory. 2pp. 22169.025.

- --8402080050 Discusses analysis of 8 B 2338 NRC FY81 Authorization Bill, Section Edgemont, SD Bill as reported on 800515, did not address responsibility for actual remediation work Major changes established by amends listed BRAUN, J G Licensing Process & Integration Dranch 80/08/28 MARTIN, J B Division of Waste Management 6pp 22169, 311.
- ~~8402080052 Discusses NRC program for Edgemont mill tailings, per 800929 meeting
 LOBLEY,D J Program Support Branch 80/09/30 DAVIS, J Q
 Office of Nuclear Material Safety & Bafeguards, Director, 1p
 22169 317
- --B402080036 Forwards data obtained on soils from Edgement school yard per 801027 telcon Data indicates that matl found at specific locations is primarily tailings HCOMAN,N A Battelle Memorial Institute, Pacific Northwest Laboratory 80/10/27 SCARANG,R A Office of Nuclear Meterial Safety & Bafeguards, Director 2pp 22169 318
- --8402080099 Draft "Radiological Surveys at Edgement, 5D, 1980 " * Dattelle Memorial Institute, Pacific Northwest Laboratory B0/12/31 15pp 22149 320
- --B4020B0061 Requests assistance in obtaining clarification from appropriation committees if problem exists in continuing Edgement cleanup program H/o stated encil MARTIN.J B Division of Waste Management FIN B-2217. JJB-6. Bi/01/09 KANMERER.C Office of Congressional Affairs 1p 22169 335
- --B402080063 Notifies that author assumed responsibilities of State
 Radiation Control Program director on 800918. Duties
 associated w/Edgement U mill. Edgement offsite cleanup
 project & general radiation activities
 BRICH-R South Dakota, State of B1/01/14. MCGRATH. J. Assistant
 Birector for State Agreements Programs 1p 22169 027
- --8402080067 Lists items to be discussed during meeting w/Senator McGovern re U mining & milling in State of BD CARPENTER, R. MCGOVERN Senate 79/06/14. SCARAND, R NRC - No Detailed Affiliation Given 2pp 22169 046.
- --8402080067 Submits third status rept re Edgemont cleanup, Summary of BNHL radiological surveys through Aug 1981 encl SCARAND, R A Uranium Recovery Licensing Branch WM-81-554 B1/10/15 MARTIN, J B. Division of Waste Management 5pp 22169 336
- --8402080074 Ack receipt of 761227 ltr re U mill tailings at Edgement.SI
 Phase II study must be conducted before further action
 taken Excerpts from "Evaluation of Impact of Mines
 Development, Inc" encl
 KNEIP,R F Bouth Dakota, State of 76/12/30 e0881CK, L. V
 Office of the Executive Director for Operations 3ipp. 22169 048
- --B402080075 Discusses status of contracted work. Summary of disequilibrium in Edgement soils almost complete Related info sncl HOGMAN.N A Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2216 2010B. B2/02/01 EADIE, Q Q. Uraniva Recovery Licensing Branch 9pp 22169-341.
- --8402080078 Discusses Governor Kneip 761108 concerns re Phase II studies If ERDA includes Edgement mill in Phase II studies. Kneip concerns will be resolved KERR. G W. Assistant Director for State Agreements Programs. 76/11/18 RYAN.R G Office of State Programs. Director 1p. 22169 079.
- --84020800B1 Draft "Edgement Remedial Action Program," annual Interia rept.1981. JACKSON.P D., YOUNG.J A., THOMAS.V.W. Battalle Memorial Institute. Pacific Northwest Laboratory, FIN 8-2217 82/05/31 NRC - No Detailed Affiliation Given Sipp 22169:350
- --B4020B0085 Requests Phase II designation for Edgement U mill Bupperting documentation encl KNEIP,R F Gouth Dakota, State of 76/11/08. GDSEIGK, L. D. Office of the Executive Director for Operations LIVERMAN, J. L. Energy Research & Development Admin (Presently DDE). Spp 22169.080
- --8402080089 FNL-4408-2
 "U Recovery Research Sponsored by MRC at BNML," quarterly progress rept for Jan-Mar 1983
 FOLEY, M. G., DEUTSCH, M. J., HARTLEY, J. N. Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2370. 83/04/30.
 NRC No Detailed Affiliation Given. Step. 22170 051.

- --B4020B0091 Discusses NRC 740B26 visit to Edgemont.SD U milling plant Tailings piles generated by past operations found in various stages of reclamation Detailed plan to stabilize loose sand tailings area requested by 741115
 ROUSE.L.C Fuel Process & Fab Branch (Pre 790727) 76/09/17
 WILLIAMS: Q Tennessee Vailey Authority 2pp. 22169 088
- --9402080097 "Edgement Remedial Action Program," monthly rept for Sept 1980 JACKGON, P. O., OLSEN, K. B., MAUCH, M. L. Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2217 80/09/30 NRC - No Detailed Affiliation Given 3pp 22170 106
- --H4Umr080099 Discusses interim stabilization of sand tailings at Edgamont, BD U mill.per 760901 conversation Concurs w/US Bureau of Mines article that combination chemical-vegetative method of stabilization best Related info encl CAMERON, R. E. Angonne National Laboratory 76/09/02 SCARAND, R Fuel Process. & Fab Branch (Pre 790727) 6pp 22169 090
- --94020B0104 "Edgement Remedial Action Program," monthly rept for Oct 1980 WQQNAN,N A. JACKBON,P.O., OLGEN,K B Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2217, 80/10/31 NRC - No Detailed Affiliation Given. 4pp 22170 109
- --8402080105 Ack receipt of 740811 transmittal of Governor Kneip ltr to Senator McGovern expressing concern re environ impact of tellings from past U milling operations at Edgemont 8D Mill status clarified GOSBICK.L. V Office of the Executive Director for Operations, 74/09/08 MURPHY.Q F Congress, Joint Committee on Atomic Energy 3pp. 22169 074.
- --8402080112 "Edgemont Remedial Action Program," 1tr rept for Nov 1980 MODRAN, N. A., JACKSON, P. O., THOMAS, V. M. Battelle Memorial Institute, Pacific Northwest Laboratory, FIN 8-2217 61/01/13 EADIE O. Q. Uranium Recovery Licensing Branch Spp. 22170 113
- --8402080115 Forwards Governor Kneip request that site of Mines Development, Inc U mill in Edgement, 8D be included in ERDA study list of inactive U mill sites. Appropriate action requested.
 ABOUREZK. J. Benate. 76/09/16 PASTORE, J Congress, Joint Committee on Atomic Energy. 4pp. 22169,099
- --8402080117 "Edgamont Remedial Action Program," monthly rept for Dec 1980 HOGMAN,N.A., JACKBON,P.D., OLBEN,K B. Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2217, B0/12/31, NRC - No Detailed Affiliation Given. App. 22170, 119
- --8402080120 Responds to 750805 itr re TVA mill at Edgemont, SD Since TVA is govt corp.mill would continue to operate under NRC license even though SD became Agreement State EIS must accompany issuance of license for U mill KERR, Q. W. NRC No Detailed Affillation Given. 75/09/12. NELSON, M. D. Bouth Dakota, State of. 1p. 22169-103.
- --8402080122 "Edgemont Remedial Action Program," ltr rept for Jan 1981. THOMAB, V W , WOOMAN, N. A Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2217-0 81/02/13. EADIE, 9 G Uranium Recovery Licensing Branch 7pp 22170.125.
- --8402080127 "Edgement Remadial Action Program," monthly rept for Feb 1981. HOOMAN, N A., JACKSON, P. O Battelle Memorial Institute, Pacific Northwest Laboratory. FIN 8-2217-0 81/02/28. NRC - No Detailed Affiliation Given 5pp 22170:132.
- ---B402080133 "Edgemont Remedial Action Program," monthly rept for May 1781. WOOMAN, N. A. JACKSON, P. O. Battelle Memorial Institute: Pacific Northwest Laboratory. FIN 8-2217-0 81/05/31 NRC - No Detailed Affiliation Given. Bpp. 22170.137
- ----9402080137 "Edgement Remedial Action Program," monthly rept for June 1981. WOOMAN, N. A., JACKBON, P. O. Battelle Memorial Institute, Pacific Northwest Laboratory. FIN B-2217-0. 81/06/30 NRC - No Detailed Affiliation Given. 7pp. 22170:145
- --8402080138 Responds to 750425 suggestion that TVA develop EIB for proposed U milling operation at Edgement, 8D TVA plans to submit smviron info by 750801.

 DIRCKS, M. J. Office of the Executive Director for Operations, 73/06/09. QREEN, J. A Environmental Protection Agency. 1p 22169:104.

- --8402080144 "Edgemont Remedial Action Program," 1tr rept for Jul 1981 JACKBON,P O. PERKINS,R W. WOGMAN,N A. Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2217 81/08/10 EADIE,G G. Uranium Recovery Licensing Branch 10pp 22170 152
- --8402080153 "Edgement Remedial Action Program," 1tr rept for Aug 1981 JACKBUN.P O , PERKINS.R W , WOGMAN.N A Battelle Memorial Institute, Pacific Northwast Laboratory FIN B-2217 81/09/11 EADIE.O O Uranium Recovery Licensing Branch 9pp 22170 162
- --B402080156 "Edgemont Remedial Action Program," ltr rept for Sept 1981 JACKBON.P O . PERKINS.R W . WOGMAN.N A Battelle Memorial Institute. Pacific Northwest Laboratory FIN B-2217 B1/10/07 EADIE, G O Uranium Recovery Licensing Branch 9pp 22170 171
- --8402080139 "Edgemont Remedial Action Program." Itr rept for Feb 1982 JACKBON,P D , PERKINS.R W , WOGMAN,N A Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2217 82/03/11 EADIE, Q G Uranium Recovery Licensing Branch 10pp 22170 180
- --B402080140 SA/TSB-18
 "Environ Evaluation of Mines Development, Inc & Vanadium
 Hillings Operations at Edgement, SD "
 * Environmental Protection Agency 73/04/30 46pp, 22169 105
- --6402080163 "Edgemant Remedial Action Program," monthly rept for May 1982 WOGMAN,N A. JACKSON,P O Batbelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2217 82/05/31 NRC - No Detailed Affiliation Given 15pp 22170.190
- --B40208016B "Edgement Remedial Action Program," 1tr rept for Jul 1982 JACKSON,P O . PERKINS,R W . W3GMAN,N A Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2217 92/08/17 FLORY,C.A Uranium Recovery Licensing Branch 12pp, 22170 219
- --8402080172 Discusses status of U mill site in Edgemont, 8D, per 810731 discussion w/G Eddie & F Anastasi Commission has no legal authority to conduct tailings removal or decontamination work MONTQDMERY, J. L. Region 4, Dallas, Office of the Director (81/03/01). 81/08/07 Region 4, Dallas, Office of the Director (81/03/01) 2pp 22167.131
- --8402080176 "Recommended Protocols for Radon Daughter Measurements in Bldgs in Edgemont " # Battelle Memorial Institute, Pacific Northwest Laboratory, FIN B-2217. 83/06/03 NRC - No Detailed Affiliation Given 10pp 22170 241
- "-8402080180 NUREG/CP-0021 DRFT
 Draft "Proceedings of Horkshop on Radiological Burveys in
 Bupport of Edgemont Cleanup Action Program," 810121-22,
 Denver, CO
 YOUNG, J. A. JACKBON, P.O., THOMAS, V. W. Battelle Memorial Institute,
 Pacific Northwest Laboratory FIN B-2216 PNL-3784 81/04/15
 100pp. 22169:160
 - --8402080202 "Indoor Radon Study at Edgement & Cottonwood, SD. 800204-08 "

 * NRC No Detailed Affiliation Given 80/02/08 11pp 22169 261
- --8402080204 Forwards revised data from soil samples taken in Edgement, 8D in Nov 1979.
 DONDVAN, T K. Tannesses Valley Authority, 80/04/04. THRALL, J
 Environmental Protection Agency 8pp 22169 273
- --84020802(1 Discusses radiation monitoring in Edgemont.8D by SD Dept of Health Measurements will utilize federal protocol.ss listed. BNITH.J Affiliation Not Assigned. 80/04/09 RICHARDBON.R Affiliation Not Assigned. 1p 22169 281.
- --8402080214 Forwards mamo from 8 Smith, SD Dept of Health, re radiation monitoring in Edgemont Memo outlines process established to provide necessary monitoring for EPA & HUD at request of local homeowners,
 RICHARDSON, J. R. South Dakota, State of, 80/04/17, MILLER, H. NRC -- No Detailed Affiliation Given. 1p. 22167-282.
- ---8402080216 Responds to 800321 request for add1 info re NRC request for DOE assistance in remedial action program in Edgemonts 8D DIRCKS, M.J. Office of the Executive Director for Operations, 80/04/30. FRANGUB, T. G. Energy, Dept. of. 4pp 22149, 283
- --8402080217 Forwards fact sheet prepared by NMSS re Sehate Authorization Committee designation of NRC as lead agency for coordinating cleanup of offsite locations at Edgemont. Two primary points listed, Related info encl.

 DAVIS.J. O NRC No Detailed Affiliation Given 80/05/22 KAMMERER, C. NRC No Detailed Affiliation Given 17pp

- 8402080079 FOTA request for 16 categories of documents SHOLLY, S.C. Union of Concerned Scientists 83/11/21 FELTON, J.M. Division of Rules and Records 2pp 22172 341
- 8402080087 Responds to FDIA request for 16 categories of documents App A documents available in PDR App B documents may be purchased from GPO & NTIS App C documents will be published PELTON, J M Division of Rules and Records 83/12/20 SHDLLY-8 C Union of Concerned Scientists 4pp 22172 343 later date
- 8402080092 FOIA request for plant manager & util executive mailing PEARCE W Center for Energy & Environmental Management 83/12/12 FELTON, J Division of Rules and Records ip 22172 336
- 8402080073 Addl response to FOIA request for IE Insp Rept 79-19, notices of proposed imposition of civil penalties & violation & order to show cause App B Documents 1 & 5 partially withheld & Documents 2,3 & 4 withheld (ref FOIA Exemption 5)
 FELTON.J M Division of Rules and Records 83/12/23 HAMLIN.J B Shaw. Pittman. Potts & Troubridge 4pp 22172 240 24X
 Fichs 30-498.83/12/23.8402080073
- --8201300218 Forwards Citizens Concerned About Nuclear Power chronology of actions re alleged Quadres conspiracy No significant conflict exists w/Region 4 chronology DIRCKS.N J Office of the Executive Director for Operations 82/01/11 PALLADING.N J Commissioners 28pp 22172 246 24X Fiche 50-498,83/12/23-8402080093
- --B402080103 Forwards revised version of proposed ltr to Congressman Ecthardt re Ahearne/Eckhardt discussion at hearing on facility Ltr clarifies major interest in Commission interaction w/state public util commissions H/o encl BICKMIT.L Office of the General Counsel 80/10/29 AHEARNE Commissioners. 1p 22172 245 24X Fiche 50-498,B3/12/23,R4020800093
- 8402080098 Responds to FOIA request for plant manager & util executive meiling lists Forwards requested lists W/o encl FELTON.J M. Division of Rules and Records 83/12/21 PEARCE, W Center for Energy & Environmental Management ip 22172 337
- 8402080109 Responds to appeal redenial of FOIA request for SECY-82-472 & correspondence between Commissioner Roberts & OPU Appeal denied Documents entirely withheld (ref FOIA Exemption 5). CHILK-S J Office of the Secretary of the Commission 83/12/22 JORDAN.H S Harmon & Weiss 2pp 82172 327
- 9402080121 Appeals denial of FOIA request for SECY-83-472 & Item 4 of Adata request re correspondence between Commissioner Roberts & OPU JORDAN.W S. Harmon & Weiss 83/10/28 DIRCKS.W J. Office of the Executive Director for Operations 3pp 22172 329
 - 02080308 F01A request for GW Reinmuth 800723 ltr re ANSI NAS 2 & daughter stds & responses & related correspondence to 800723 itr HAMLIN.J B Shaw, Pittman, Potts & Trowbridge 83/11/11 of Administration. 1g 22172 260
- B402080309 Responds to FOIA request for CM Reinmuth B00723 ltr & related correspondence Forwards app documents.
 FELTON, J H Division of Rules and Records. B3/12/01 HAMLIN, J, B Bhaw, Pittman, Potts & Trombridge 2pp 22172 261.
- --B009120138 Responds to B00609 memo re request for guidance on applicability of ANSI N45 2 & daughter stds 10CFR50.App 8 requires licensee to ensure via supply contracts that all requirements in SAR be contractually passed to suppliers. REINMUM.9 W. Division of Reactor Construction Inspection 80/07/29 POTAPOVS.U Region 4. Dallas, Vendor Inspection Branch Gpp 22172 263
 - 3009120145 Requests guidance as to whether ANSI daughter stds must be passed on to vendors if applicable to given procurement in addition to more general requirements of 10CFR50, App 8 or ANSI M45 2
 POTAPOVS, U. Region 4. Dallas, Vendor Inspection Branch. BO/06/09 REINMUTH.R W. Division of Reactor Construction Inspection 2pp 22172 264
 - 00912014B Requests clarification of NRC position re application of ANSI N45 2 A POTAPOVS, U ANNE NAT 2 6 POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch, 79/01/05 REINMUTH.0 H Division of Reactor Construction Inspection 1p

- 8402080313 FOIA request for abstract of Bid DIE-83-220 negotiated by H Hapsy ELLIDIT, B D Gearhiser, Peters & Horton 83/11/16 Bules and Records 1p 22174 033
- 8402080314 Responds to FOIA request for NRC abstract of bids for invitation for Bid OIE-83-220 in conformance w/federal rules of evidence Forwards abstract & certification intended to comply w/Rule 902(2) FELTON, J M Division of Rules and Records 83/12/05 ELLIOTF.6 b Gearbiser, Peters & Horton 1p 22174 034
- --8402080316 Forwards abstract of bids for invitation for Bid D1E-83-229 "Graphic Svcs"

 HAGEY,H A NRC - No Datailed Affiliation Qiven B3/18/01,

 - No Datailed Affiliation Qiven. 9pp 22174 035.
- 8402080318 FOIA request for 800508 generic 1tr re NUREQ-0545 on evaluation of feedwater transients & small break LOGA for Westinghouse-designed reactors & 711005 rev to NUREG-OBOG. Ref 4 on Page 15.7 4-6 to be placed in PDR PEDROJ NUS Corp CD-18-83-497. 83/10/31. Division and Records 1p 22168, 220. Division of Hules
- 8402080321 Responds to FOIA request for two categories of documents 1# be placed in PDR, All generic ltrs on file in PDR under specific docket number Forwards NUREO-0800, Ref 4 on Page 15 7 4-6 Info also available in PDR FELTON, J M Division of Rules and Records 83/12/05 PEDRO, J MS Corp 1p 22168, 221
- -8402080322 Revised "Evaluation of Fission Product Release & Transport for Fuel Handling Accident "
 BURLEY, G Atomic Energy Commission, Directorate of Licensing
 71/10/05 38pp. 22168.222
- 8402080380 FOIA request for CYB1-83 operating reactor event means to NRR ofc ltrs to be placed in FDR.

 SHOLLY, B C Union of Concerned Scientists 83/11/09. FELTON J B Division of Rules and Records. 1p. 22168, 146 83/11/09. FELTON J M
- 8402080381 Further response to FOIA request for CYB1-83 operating reactor event memos & current version of NRR ofc itrs to be placed in FDR. Forwards app documents. Info also available in FELTON, J. M. Division of Rules and Records. 83/12/05 Union of Concerned Scientists 2pp. 22168-147. 24% Fiche:50-368.83/12/05.8402080381
- --8103270357 Operating Reactor Event Memorandum Bi-GO re flow blockspanin essential equipment caused by Asian clams, Clams caused Arianses Nuclear One, Unit 2 800904 shutdown, Heat treatment most effective remedy
 EISERNUT.D 0. Division of Licensing. OREM-81-030 81/03/10.
 VOLLMER, H. Division of Engineering. Spp. 22168 153. 24x
 Fich: 50-368,83/12/05,8402080381
- 8402080388 Responds to FDIA request for latest NRC organization charts Rev 2 to NUREQ-0325, "UB NRC Functional Organization Charts," dtd 830101 available from NRC 0PD Sales Program. FELTUN.J.M. Division of Rules and Records. 83/12/07. LIPPMAN.H U S Organization Chart Service, Inc. 1p. 22168.218.
- 8402080392 FOIA request for latest NRC organization charts. LIPPMAN.M U.S. Organization Chart Service, Inc. 83/11/28 No Datailed Affiliation Given ip 22168:219. MRC -
- 8402080396 Responds to FOIA request for results of all radiologic tests, including passover tests & radin gas measurements on open rock faces: conducted at Riverdale Querry Co in Riverdale, NO HO, stated App A documents.

 FELTON, J. M. Division of Rules and Records. 83/12/07. LESTER. R M. New Jersey, State of 2pp. 22168:214.
- 8402080399 FUIA request for results of all radiologic tests, including passover tests & radon gas measurements on open rock faces; conducted at Riverdals Quarry Co in Riverdals,NJ.
 LESTER,R.M. New Jersey, Bitste of, 83/10/07. NRC No Detailed Affiliation Given. 2pp. 22168,216
- 8402080403 Responds to FOIA request for documents re informal t/or formal investigations pending by NRC concerning facility. H/O encl.
 FELTON J M Division of Rules and Records, 83/12/12 ORMAN, K. 8
 Barger & Montague. 1p. 22168:211 24X Fiche: 50-356, 83/12/12,
 8402080403

- 8402080406 FGIA request for documents not available in PDR re informal & formal investigation pending by NRC concerning Cincinnati Gas & Electric Co &/or facility GRNAN/K S Berger & Montague 83/11/07 NRC No Detailed Affiliation Given, 2pp 22168 212. 24X Fiche 50-358.83/11/07, BACORDROM
- 8402080410 FDIA request for records re incidents (other than TMI) since 1950 where nuclear reactor core approached point of burning through bottom of reactor YICKHAN-M. Affiliation Not Assigned 83/11/02 Office of Administration 1p 22174 086
- 8402080413 Responds to FOIA request for records re incidents since 1950 where nuclear reactor core approached point of burning through bottom of reactor Forwards one partial ORNL/N9I-176, describing selected accidents.

 FELTON, J. M. Division of Rules and Records 83/12/06 VICKMAN, W. Affiliation Not Assigned 2pp 22174 087.
- ---E402080418 ORML/NSI-176
 Partial "Description of Selected Accidents That Have Occurred at Nuclear Reactor Facilities"
 * Dak Ridge National Laboratory B0/04/30 29pp 22174 089.
- 8402080431 Partial response to FDIA request for all "Operating Reactor Event Nemos" issued in 1981, 1982 & 1983 & most current version of each NRR ofc ltr.re technical matters, to be placed in PDR, NRR ofc ltrs listed on app placed in PDR PDR, NRR ofc ltrs listed on app placed in PDR FELTON, J M Division of Rules and Records, 83/11/28 8HDLLY,8 C Union of Concerned Scientists Spp 22174-151
- --B10B190G47 Bubmits Ofc of Nuclear Reactor Regulation Ltr 34, discussing util commitments identifying future actions, Various ofc responsibilities delineated.
 DENTON.H.R. Office of Nuclear Reactor Regulation, Director B1/07/31. Office of Nuclear Reactor Regulation, Director 2pp 20174. DAM.
- --B202170355 Provides procedures for availability.retention & indexing of codes & stds.

 THOMPSON, M. i. Planning & Program Analysis Staff. 81/12/02
 Office of Nuclear Reactor Regulation. Director 2pp. 22174:267.
- --8205210017 NRR Ofc Ltr 2, Revision 2 re NUREG-0800 "SRP for Review of BARs for Nuclear Power Plants" Distribution, relationship of SRP to regulations & use of BRP in regulatory process discussed.

 DENTON: H. R. Office of Nuclear Reactor Regulation, Director. B2/04/28. Office of Nuclear Reactor Regulation, Director. 28pp 22174: 155.
- --8203240376 NRR Ofc Ltr 98 forwarding info re procedures for revisions to Tech Specs.

 DENTON.H. Office of Nuclear Reactor Regulation, Director.

 82/04/21. Office of Nuclear Reactor Regulation, Director. 4pp
- --8212290011 Discusses policy re increased communications w/regional ofcs dust to IE reorganization. Communication covers info exchange specific plant related meetings & resource or policy related matl. Chart highlighting policy encl.

 DENTON. H. R. Defice of Nuclear Reactor Regulation, Director 82/04/02, Defice of Nuclear Reactor Regulation, Director 4pg 22174:300.
- ---B212290017 Dutlines temporary sys for technical assistance requests.

 Div of Licensing established as contact point. Requests should define scope, purpose & scheduling needs. Bample task interface agreements encl.

 DENTON: H R. Office of Nuclear Reactor Regulation, Director, B2/03/15. Region 1, Office of Director, Spp. 22174:304
- --8303090697 Discusses Ofc Ltr 10.Rev 1 re procedures for handling non-regulatory site visit requests. Rev includes onsite visits or meetings involving contractor personnel or NRC at operating or const sites,
 FUNCHESIJ. Planning & Program Analysis Staff 82/11/05. Off of Nuclear Reactor Regulation, Director, 3pp. 22174:208.

- --8304140139 Provides NRR Ofc Ltr 16, Rev i re regulatory analysis guidelines EDO issued NRC-wide regulatory analysis guidelines (NUREQ/DR-005B) to replace value impact guidelines NRR-specific guidance encl DENTON.H R Office of Nuclear Reactor Regulation, Director 83/03/14 Office of Nuclear Reactor Regulation, Director 6pp 22/14 241
- --8305200042 Provides NRR Ofc Ltr 40 re mgt of proposed generic issues
 All generic safety or environ issues or regulatory impact
 issues, except for types listed, should be processed per encl
 procedure
 DENTON. H R Office of Nuclear Reactor Regulation, Director
 83/03/19 Office of Nuclear Reactor Regulation, Director
 7pp
 79:174 338
- --9402080434 NRR Ofc Ltr 3 re SRPs for environ & antitrust reviews RUSCHE, B C Office of Nuclear Reactor Regulation, Director 75/08/12 HEINEMAN.R., SCHROEDER, F Division of Technical Review (NRR-1975 only) OlAMBUSBO, A Division of Reactor Licensing (NRR-1975 only) 2pp 22174 183
- --8402080434 NRR Ofc Ltr 10 rs div responsibilities under Section 206 of Energy Reorganization Act of 1974, per revised Part 21 RUBCHE, B C Office of Nuclear Reactor Regulation, Director 74/07/30 BOYD, R. Division of Project Management DENTON, H R Division of Site Safety & Environmental Analysis HEINEMAN, R. Division of Systems Safety App 22174 200
- --B4020B0442 NRR Dfc Ltr 12 re attendance at ACRS committee meetings Quidance outlined. RUSCHE, B.C. Office of Nuclear Reactor Regulation, Director 77/01/14, BOYD,R.S. Division of Project Management DENTON,H R Division of Site Bafety & Environmental Analysis HEINEMAN,R.H Division of Systems Safety. 3pp 22174,205
- --8402080447 NRR Ofc Ltr 17.Rev 2 outlining procedures for handling requests for 10CFR2 206 actions
 THOMPBON.H L. Office of Nuclear Reactor Regulation, Director 81/03/30 Office of Nuclear Reactor Regulation, Director 17p
- --8402080452 NRR Ofc Ltr i8 providing guidance on procedure for handling Part 21 notifications Schamatic procedure encl CASE, E. O Office of Nuclear Reactor Regulation, Director 78/03/08 Office of Nuclear Reactor Regulation, Director. App
- ---B402080455 NRR Off Ltm 21 re-procedures on reporting of AOs, per Section 20B of Energy Reorganization Act of 1974
 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 78/08/09, Office of Nuclear Reactor Regulation, Director 7pp 22174-251
- ---9402080465 NRR Ofc Ltr 36 providing guidance & methodology for conflict identification & resolution, per L Josef 810120 study, "Conflict Rewolution." Forwards study. FUNCHES, J L. Planning & Program Analysis Staff 82/03/01 Office of Nuclear Reactor Regulation, Director 7pp 22174.269
- ---9402080468 "Conflict Resolution"
 JUBSF.1. R Genter for Applied Psychology, 81/01/20, Office of
 Nuclear Reactor Regulation, Director 24pp 22174 276.
- ---8402080477 NRR Dfc Ltr 39, Rev 1, providing pracedures for control & review of generic requirements. Related info encl.

 DENTON. H R. Office of Nuclear Reactor Regulation, Director 82/12/13. Dffice of Nuclear Reactor Regulation, Director. 15pp 22174. 313.
- 8402080487 Responds to FDIA request for two categories of records re Lixis Inc & Lixi Research Limited Pertnership, Records filled in PDR Folders FDIA 83-29 & 83-470 under names of Shilton & Caulk, Forwards two requests W/o encl. FELTON, J. M Division of Rules and Records. 83/12/22 QROBSMAN, L LIXIs Inc 1p. 22142 280
- 8402080491 FOIA request for two categories of records re Lixi, Inc & Lixi Research Limited Partnership GROSBMAN.L. LIXI, Inc. NRC 83/11/29. MCGANN.M Region 3, Office of Director ip. 22142-281.
- 8402070002 FGIA request for estimated const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings.
 ROBENBAUM, D. M. Technical Analysis Corp. 83/08/18, Office of Administration. 1p 22193; 271.

- --8402090053 Forwards Caseload Forecast Panel site visit schedule Schedule developed considering licensing review effort & const status, last panel site visit date & project manager inputs
 EIBENHUT, D. G. Division of Licensing 81/08/25 TEDESCO, R. L.
 Assistant Director for Licensing 2pp 22194 007
- --8402070058 Forwards updated listing of recommended Caseload Forecast Panel visits for CV82.per 811214 request Continued use of applicant date for Bevill schedule purposes expected Related info enc! EISENHUT.D G Division of Licensing 82/01/05 BASSETT.H S Office of Hanagement and Program Analysis 7pp 22194 009
- --8402090059 Handwritten graph & calculations re const activities. # NRC No Datailed Affiliation Given 83/02/22 3pp 22196-012 24X Fiche 50-000.83/10/31,8402090003
- ---8402070061 Marked-up draft summary of trip rept of Caseload Forecast Panel 830222-24 meetings re const progress review & mgt decision on allocation of staff resources during licensing review HAUGHEY.M Licensing Branch 2 83/03/18 Licensing Branch 2 4 016 24% Fiche 50-000:83/10/31:8402090003 22174 016
- --8402090063 Draft trip rept of Caseload Forecast Panel 830222-24 site visits re const progress review & estimating resource meeds for licemsing activities HAUGHEY,M Licemsing Branch 2 83/10/31 Licensing Branch 2 4pp 22196 015 24X Fiche 50-000,83/10/31,8402090003
- --B402070070 Trip rept of B30522-24 Caseload Forecast Panel site visit re plant status review Projected fuel load data comparisons listed RISTED NO. W Licensing Branch 3 83/10/31. NOVAK, T. Assistant Director for Licensing 2pp 22194'059 24 Fiche 50-000, 83/10/31,840209003
- --8402090072 Handwritten graphs calculations & notes re constactivities & fuel load preparation Related info encl * NRC No betailed Affiliation Given 80/10/28 9pp. 22196 021 24X Fiche 50-000.83/10/31.8402090003
- --8402090076 Summary of B30622-24 Caseload Forecast Panel site visit re plant status review LICITRA,E A Licensing Branch 3 83/07/27 Licensing Branch 3 7pp 22194 061 24X Fiche 50-000,83/10/31.8402090003
- --8402090079 Comments on review schedule Results expected for release in mid-Nov 1782 Projected fuel load date is Nov 1783 Projected fuel load date is Nov 1783 ENHIUT, D o, UNIVESION of Licensing Branch 3 82/09/22 EISENHUT, D o, B3/10/31.8402090003
- --8402090092 Handwritten notes & calculations re const activities & fuel load preparation * NRC - No Datailed Affiliation Given, 79/04/25 2ap. 22194:031 24X Fiche 80-000.83/10/31,8402090003
- --8402090086 Comments on 790618 meeting re estimated fuel load date Util requested site visit & evaluation of const schedule & fuel load date as soon as possible Related info sncl * NRC No Datailed Affiliation Given 79/06/18. NRC No Datailed Affiliation Given Bpp 22195/144. 24X Fiche 50-000,63/10/31,8402090003
- --B402090087 Handwritten graphs re const activities Related info and # NRC No Detailed Affiliation Given 83/06/28 App 22196.035 24X Fiche 50-000,83/10/31,8402090003
- ---B4020700BB Marked-up trip rept of B20Bil-13 Caseload Forecast Panel site visits re const & preoperational testing status Related info encl info encl
 OllBERT.R.A Licensing Branch 2 B3/10/31. Licensing Branch 2.
 6pp. 22194-074 24% Fiche 50-000/83/10/31/8402090003.
- --8402070070 Handwritten notes re facility fuel load preparation * NRC No Detailed Affiliation Given 83/10/31 7pp 22174 070 24X Fiche: 50-000, 83/10/31, 8402070003
 - 3402090091 Handwritten notes & calculations re comst activities & fuel 1000 preparation * NRC - No Detailed Affiliation Given 81/10/07. 5pp. 22196 042 24% Ficha. 50-000,83/10/31,8402090003.
 - 02090092 Forwards revised NRC estimates for reactor const completion 'fuel load' as of Jul 1983 Review & concurrence requested elated info encl.
 ROGGINSR.M. Diffice of Resource Management, Director 83/07/26.
 TISENHUT, D. O. Division of Licensing 18pp 22194-097, 24X cha. 50-000, 83/10/31, 8402090003.

- 8402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.B & C documents FELTON, J M Division of Rules and Records 83/10/31 RDSENSAUM, D M Technical Analysis Corp 19pp 22193, 292 24x Fichs 50-000,83/10/31,8402090003
- --7903230241 Recommends that review schedule be based on 810918 prospective decision date, which also should be used as basis for fuel load date Summary of 790226 telcon w/applicant BENEDICT, R A BEAKOW, H N 1 enci BENEDICT,R A Light Water Reactors Branch 2 79/02/28 BERKOW,H N Division of Project Management 3pp. 22196,260 241 Fiche 50-000,63/10/31,8402090003
- ~~7908160043 Discusses 790612 meeting w/util re estimated const completion date Targeting for May 1980 but author suggests late 1980 as possible date Critical areas are electrical work & hangers

 KARI.S M Defice of Management and Program Analysis 79/06/29

 VASBALLO,D B Division of Project Management 2pp 22194 294

 24% Fiche 50-000.83/10/31,8402090003
- --Biiii70178 Summary of Bi0915 NRC caseload forecast panel meeting kills visit to assess const completion date WHEELER, L. Licensing Branch 3 81/10/R7 Licensing Branch 3 2pp 22194 071. 24% Fichs 50-000,83/10/31,8402090003
- --Biil230250 Summary of Bii019-2: caseload forecast panel sectings w/will at sits re progress of engineering & const AULUCK:R Licensing Branch 2 Bi/11/05 Licensing Branch 2 ip. 22196 317 24X Fichs 80-000.83/10/31,8402090003.
- -8204070041 Trip rept of 820316-19 visit of caseload forecast panel to facility re-datemination of fuel load dates Load dates estimated to be Nov 1983, Nov 1984 & Nov 1985 for Units 1, 2 & 3. respectively
 MIRAGLIA.F J Operating Reactors Branch 3. B2/03/30
 EISENHUT.D Q Division of Licensing 4pp 22174:055. 24X
 Fiche 50-000, 83/10/31.8402097003
- --8303240052 Advises that caseload forecast panel project completion fals is Nov 1986; 7 months after official load date. Mgt meeting should be held in near future
 NOVAK.T M Assistant Director for Licensing. 83/03/18
 EIBENHUT.D O Division of Licensing ip 22193:360. 24X
 Fiche 50-000,83/10/31.8402090003
- --8303060126 Forwards revised NRC estimates for reactor const completion (fuel load) as of Apr 1983 Review & concurrence requested SCROGOINS,R M Office of Resource Management, Director. B3/04/18 EIBENBUT,D Q Division of Licensing 10pp. 22174-080
- ~~8305i10172 Forwards guidence on review schedule for DL application Resolution of const completion schedule differences requested prior to finalizing review schedule. EIBENHUT, D Q Division of Licensing, 83/04/04, NDVAK-T. Assistant Director for Licensing, 3pp. 66775:190, 24X Fiche 30-000,83/10/31,8402070003
- --8402070027 Submits draft rept of 830325 crane accident at plant site Crane collapsed white lifting 400-ton form assembly for containment shield bldg roof, Cause undetermined, Investigation in progress, Related info encl.

 CAHLL, H J Quif States Utilities Co. 83/10/31 Quif States Utilities Co. 4pp. 22173-311. 24X Fiche: 50-000,83/10/31, 8402070003
- --- 8402090037 Submits 129th project performance rept for Mar 1783 Related info enc1
 EBNER, A.M. United Engineers & Constructors, Inc (subs. of Raytheon Co). 88U-71775. 83/04/20. DEVINCENTIS, J. Yankee Atomic Electric Co 22pp 22193,315 24X Fiche 50-000,83/10/31. 8402090003
- --8402090042 Submits 123rd project performance rept for Sept 1982 Related EBNER. A M United Engineers & Constructors, Inc. (subs. of Raytheon Co). BBU-63342 82/10/25. DEVINCENTIS, J. Yankas Atomic Electric Co. 6pp. 22173 336 24X Fichs: 50-000, 83/10/31, 8402090003
- ---B402090045 Project Performance Rept 109 for Jul 1981, Related info anti * Public Service Co of New Hampshire, Bi/07/31, 25pp. 22193: 342. R4X Fichel 50-000, B3/10/31, 8402090003.
- ---8402090051 Forwards proposed schedule for Caseload Forecast Panel site visits. Schedule developed considering licensing review effort & const status & last panel site visit date EIBENHUT, D. Ø Division of Licensing, 81/07/30, YOUNGBLOOD, S. J. Licensing Branch 1 SCHWENCER, A. Licensing Branch 2. HIRAGLEA, F. Licensing Branch 3 2pp 22194-005.

- -8402070074 Handwritten notes re fuel load preparation & const
 - activities # NRC No Datailed Affiliation Given 78/04/12 7pp 22194: 127 24X Fiche 50-000:03/10/31:8402090003
- -8402090095 Summary of 790322 meeting w/util in Bethesda. MD re estimated fuml load data for Unit 1 Related info ancl LYNCH. M D Light Water Reactors Branch 4 79/04/02 Light Water Reactors Branch 4 Bipp 22195.050 24X Fiche: 50-000.83/10/31.8402090003
- --8402070078 Oraph re const activities * NRC No Detailed Affiliation Given 83/10/3: 22174 136 24X Fiche 50-000.83/10/31,8402070003 83/10/31 3pp
- --8402090100 Responds to 820616 request for const schedule exam NRC agrees w/1985 fuel load date Design work & site preparation substantially completed before actual const Related info enci. REMIGK.F.J. Office of Policy Evaluations 82/07/14 AHEARNE, J. F. Commissioners 5pp, 22194, 131 24% Fiche: 50-000, 83/10/31, 8402090003.
- --8402090101 Summarizes 800613 meeting w/util re NRC review of OL application Related info encl BRUNNER.J E Isham Lincoln & Beale BRUNNER.J E Consumers Power Co 80/06/13 Isham Lincoln & Beale 9pp 22195 1 24X Fiche: 50-000, 83/10/31, 8402090003.
- --- B402090102 Handwritten notes & graph re tests concerning const activities & fuel load dates * NRC - No Detailed Affiliation Given 83/08/01 2pp. 22194: 156. 24X Fichs 50-000.83/10/31.8402090003
- --8402090105 Handwritten notes & calculations re fuel load preparation & const activities

 * NRC No Detailed Affiliation Given 81/08/13 1p. 22194:180 24% Fichs:50-000.83/10/31.8402070003.
- --- \$402090107 Handwritten notes & calculations re const & fuel load preparation, a NRC - No Detailed Affiliation Given 80/04/23 4pp. 22174: 162 24X Fiche: 50-000: 83/10/31; 8402070003,
- ---8402090114 Forwards T Abell notes to 8D Freeman ltr.T Abell marked-up ltr & 780427 trip rept, Realistic fuel load date forecast
- ---B402070117 Requests meeting in June to discuss regulations or methods of operation changed to improve schedules & costs of nuclear plants w/o sacrificing safety concerns Meeting on 780412-13 re estimated fuel load date summarized FREEMAN.8.D. Tennessee Valley Authority. 78/05/25. HENDRIE, J M NRC No Detailed Affiliation Given. 3pp. 22194:190 24X Fiche: 50-000, 83/10/31, 8402090003.
- ~~8402070118 Handwritten charts, notes & calculations re const activities & estimated const completion. Related info encl * NRC ~ No Detailed Affiliation Qiven. 80/08/04. 50pp. 22195.168. 24X Fiche:50~000.83/10/31,8402070003
- -8402090120 Summary of 780412-13 meetings at site w/util re const scheduling & observation of in-progress const activities. Projected fuel load dates are Jul 1981 & 1982 for Units 1 & 2, respectively. PIKE, W. J. Office of Management and Progrem Analysis, 78/04/27. Office of Management and Progrem Analysis 7pp, 22194 193. 24X Fiche: 50-000,83/10/31,8402090003
- `-8402Ô90122 Handwritten calculations re const activities.Related info encl. * NRC - No Detailed Affiliation Given. 81/08/26, 80pp. 22195; 232. 24X Fiche: 50-000, 83/10/31, 8402090003
- ~8402090124 Handwritten notes & calculations re facility const. Related Info encl. * NRC - No Detailed Affiliation Given, 83/10/31, 48pp 22194: 200. 24X Fiche 50-000,83/10/31,8402090003.

- --B402090133 Trip rept of 780418-19 site visit re in-progress const activity observation const & startup schedules & estimated fuel load date roe. 1804 vate NAVENTI:R Light Water Reactors Branch 4 78/06/09 Water Reactors Branch 4 2pp 22194 248 24X Fiche 50-000,83/10/31,8402090003
- --8402090134 Advises of 810303-05 Caseload Forecast Panel site visit results Const completion scheduled for Oct 1985 Related info enci TEDESCO,R L Assistant Director for Licensing 81/03/17 DRAPER.E L Quif States Utilities Co 10pp 22196 138 24X Fiche 50-000,83/10/31,8402090003
- --B402090135 Handwritten notes & calculations re const activities & fuel luad preparation Related info encl * NRC - No Detailed Affiliation Given 83/04/19 27pp 22195 316 24X Fiche 50-000.83/10/31.8402090003
- --8402090138 Handwritten notes & calculations re const activities Related info and | NRC - No Detailed Affiliation Given B0/10/21 20pp 22194 255 24X Fiche 50-000,83/10/31,8402090003
- --B402090140 Handwritten notes & calculations re const activities * NRC No Detailed Affiliation Given 83/10/31, 3pp 22194.281 24X Fiche 50-000.83/10/31,8402090003
- --8402070142 Draft trip rept of 780321-22 site visits re const schedules & in-progress const activities observation Fuel load dates for Units 1 & 2 are Nov 1981 & Nov 1980, respectively Related info encl

 **NRC No Detailed Affiliation Given 83/10/31 NRC No Detailed Affiliation Given 11pp. 22195 342 Fiche 50-000.83/10/31.8402070003 244
- --8402090147 Trip rept of Caseload Forecast Panel 810929-1001 site visits re const status observation & scheduled completion data Related info encl
 KINTHER, L. Licensing Branch 1. 81/11/24 Licensing Branch 1 8pp 22194:297. 24X Fichs.50-000;83/10/31;8402090003.
- -- B402090156 Handwritten notes & calculations re const & fuel load preparation
 DALE, L. NRC - No Detailed Affiliation Diven 78/05/31 10pg
 22174: 326 24X Fiche: 50-000,83/10/31,8402090903
- --8402090159 Handwritten notes & calculations re const activities & fuel load preparation NRC - No Detailed Affiliation Given 79/08/22 9pp 22194:940. 24% Fiche-50-000:83/10/31:8402090003
- --8402090162 Handwritten notes & calculations re const activities. * NRC No Detailed Affiliation Given 83/02/17. 10pp. 22194 354. 24% Fiche: 50-000,83/10/31,8402090003
- --8402090165 Handwritten notes & calculations re const activities * NRC No Detailed Affiliation Given, 83/04/05 5pp. 22195:006 24X Fichs:50-000;83/10/31;8402090003
- --8402070146 Trip rept of 830330-31 Caseload Forecast site visits re current status of const & observation of in-progress activities. Const progress will be reviewed at end of FYB3. WEINKAM, E. J. Licensing Branch 2 83/10/31 Licensing Branch 2 13pp. 22176, 156 24X Ficher 50-000, 83/10/31, 8402090003
- --8402090167 Trip rept of Caseload Forecast Panel 800326-27 site visits re const status observation & const completion & fuel load schedules BOURNIA. A Light Water Reactors Branch 3 80/04/09. Light Water Reactors Branch 3 2pp 22195;013. 24X Fiche 50-000,83/10/31,8402090003
- --8402090169 Summary of 780726 meeting w/util on site re const completion plans & schedules, const status & scheduled fuel load date.
 Related info encl
 BTRIGHT,R.L. Light Water Reactors Branch 3. 78/08/02. Light
 Water Reactors Branch 3. 5pp. 22176:169. 24X
 Fichs 50-000,83/10/31,8402090003
- ---B402090170 Responds to DW Hayes request for projected fuel load date evaluation Licensee projected fuel load data is 790701, while NRC Caseload Forecast Panel projects Dec 1777 as date. KONKI.N.J E., NEISLER.J.H. Region 3. Chicago. Diffice of the Director. 79/02/13. KNOP.R C. Region 3. Chicago, Diffice of the Director. App. 22195:015. 24X Fiche: 50-000:83/10/31,8402090003
- ---8402090173 Trip rept of Caseload Forecast Panel 800909-11 site visits re const schedula review ROOD, H. Licensing Branch 3. 80/10/04. Licensing Branch 3. 2pp. 22196:174. 24X Fichs: 50-000:83/10/31,8402090003.

- --8402090175 Trip rept of Caselnad Forecast Panel site visit re const status review & projected Puel load date Related info encl PELTIER, I A Light Water Reactors Branch I DOURNIA.A Light Water Reactors Branch 3 78/08/07 Light Water Reactors Branch 1. 24pp 22195 020 24X Fiche 50-000.83/10/31,8402090003
- --B402090177 Corrected trip rept of Caseload Forecast Panel 791119 site visit re const status & schedule & startup test program ROOD, H Light Water Reactors Branch 2 B0/01/21 Light Water Reactors Branch 2 2pp 22194 177 24% Fiche 50-000,83/10/31, 8402090003
- --B40209017B Handwritten graphs & notes re const activities * NRC - No Detailed Affiliation Given 83/04/14 4pp 22195 050 24X Fiche 50-000.63/10/31.8402090003
- --8402070181 Handwritten graphs, calculations & notes re const & preoperational testing activities & fuel load preparation + NRC No Detailed Affiliation Given 82/11/16 8pp 22196 182 24X Fiche 50-000,83/10/31.8402090003
- --8402090185 Handwritten notes & calculations re const activities * NRC - No Detailed Affiliation Given 82/10/31 5pp 22195 067 24X Fiche 50-000.83/10/31,8402090003
- --8402090187 Handwritten notes & calculations re const activities & fuel load preparation * NRC - No Detailed Affiliation Given 80/05/08 4pp 22196 199 24X Ficha 50-000.83/10/31.8402090003
- --8402090189 Handwritten notes & calculations re const activities & fuel load preparation a NRC - No Detailed Affiliation Diven 79/02/27, 7pp 22195 074 24X Fiche 50-000.83/10/31.8402090003
- --B402090190 Trip rept of Caseload Forecast Panel 820811-13 site visits re status of const & preoperational testing evaluation Related info encl GILBERT,R A Licensing Branch 2 82/08/19 Licensing Branch 2 5pp 22194 203 24X Fiche:50-000.63/10/31.8402090003
- --8402070192 Handwritten notes & calculations re const activities & fuel load date projection Related info encl * NRC - No Detailed Affiliation Given 78/09/24 Spp 22195 083 24X Fiche 50-000.63/10/31.8402090003
- --8402070193 Trip rept of 780405-06 site visits re const schedule Related info encl COX.T Light Water Reactors Branch 3 78/08/09 Light Water Reactors Branch 3 7pp 22196 208 24X Fiche 50-000,83/10/31.
- --8402090199 "Midland Startup Sequence," Related info encl # Consumers Power Co 83/10/31 23pp 22195 113 24X Fiche 50-000:83/10/31:8402090003
- --8402090201 Handwritten calculations & graphs re const schedule * NRC - No Detailed Affiliation Given 83/10/31 2pp. 22176 217 24X Fiche 50-000.83/10/31.8402090003
- --8402070220 Handwritten notes & calculations re const schedule & fuel load preparation Related info encl. * NRC - No Detailed Affiliation Given 79/10/15 5pp 22176 232 24% Fiche 50-000.83/10/31.8402070003.
- --8402070224 Handwritten graph re const schedule * NRC - No Detailed Affiliation Given 83/05/26 ip R2196 240 24X Fiche 30-000,83/10/31,8402070003
- --8402090R26 Handwritten calculations re const activities & schedule * NRC - No Detailed Affiliation Given 79/05/16 1p. 22196 245 24X Fiche 50-000.83/10/31,8402090003
- --8402090230 Handwritten notes, calculations & graphs re const activities & fuel load date preparation * NRC No Detailed Affiliation Given. 78/09/19 11pp 22196-266 24X Fiche 50-000.83/10/31,8402090003
- --8402090231 Trip rept of 760504-05 site visits re const scheduling & preoperational testing & const status observation Related info encl MINER.S Light Water Reactors Branch 3 76/09/22 Light Water Reactors Branch 3. 4pp. 22196:246, 24X Fiche 50-000.83/10/31. RAN2090003
- 9402090234 Handwritten graph & calculations re preoperational testing & const activities.

 NRC No Detailed Affiliation Given 83/05/17 4pp. 22196:253. 24% Fiche 90-000.83/10/31.8402090003

- --B402090238 Requests comments on encl draft rept of Caseload Foretast Panel 810113-15 sits visits re facility const status, a NRC - No Detailed Affiliation Given B1/01/27 MRC - No Detailed Affiliation Given Bpp 22196 277 24X Ficha 50-000, B3/10/31, 8402090003
- --B402090240 Trip rept of Caseload Forecast Panel 790925 site visit to review & discuss const progress Related info encl BENEDICT R A Light Water Reactors Branch 2 79/11/30, Light Water Reactors Branch 2 3pp 22196 257 24X Fiche 50-000, 83/10/31, 8402090003
- --8402070250 Handwritten notes & calculations re const schedule activities & fuel load preparation Related info enc!

 e NRC No Detailed Affiliation Given. 83/10/31. 10pp 22196 289 24X Fiche 50-000,83/10/31,8402090003.
- ---8402070261 Hendwritten notes & calculations re const activities Relation info encl
 F NRC No Detailed Affiliation Given 80/10/31. 3pp 22176 301 24X Fiche 50-000,83/10/31,8402070003
- ---8402090275 Trip rept of Caseload Forecast Panel 780613-15 site visits re const status assessment & projected completion date symbostion Related info snci COX.T H Light Water Reactors Branch 3 78/09/28 Light Water Reactors Branch 3 78/09/28 Light Water Reactors Branch 3 78/09/28 Light Water Reactors Branch 3 6pp 22196 311 24X Fichs 50-000,83/10/31, 8402090003
- --8402090287 Handwritten notes re estimated & official fuel load (ats + NRC No Datailed Affiliation Given 81/10/19, ip 22196 316 24% Fiche 50-000, 83/10/31, 8402090003
- --B402090295 Trip rept of Caseload Forecast Panel 800226 site visits refactors affecting const schedule & const activity observation Related info encl.
 LYNCH,M D Light Water Reactors Branch 4. 80/04/24 Light Water Reactors Branch 4. 6pp 22196.319 24% Fiche 50-000,83/10/31,8402090003.
- --8402090301 Handwritten graph & calculations re const activities. * NRC - No Detailed Affiliation Given. 82/09/01 3pp 22196 328 24X Fichs 50~000,83/10/31.8402090003
- --B402090307 Handwritten notes & calculations re const activities & full load preparation.

 ** NRC No Datailed Affiliation Given. 81/02/24. App. 22196 331 24X Ficher 50-000, 83/10/31, 8402090003.
- 8402090010 Appeals denial of FOIA request for transcripts of NRC cloud meetings held between 810827 & 830510 re restart YAHNER, A C Kohn, Milstein, Cohen & Hausfeld. 83/10/03 Office of the Secretary of the Commission 2pp 22189.274 24X Fiche: 50-289, 83/10/03, 8402090010
- 8402070015 Requests clarification of NRC 830624 response to FGIA 83-320 request within 5 working days.

 DETJEN. J Philadelphia Inquirer, Philadelphia, PA 83/08/10 FELTON. J M Division of Rules and Records 1p. 22189:279.
- 8402090018 Responds to FOIA request for transcripts of closed commission meetings between 830427-0510 re restart Response will be extended until 830712 due to voluminous amount of mati.
 FELTON, J. M. Division of Rules and Records. 83/06/24 DETJEN, J. Philadelphia Inquirer, Philadelphia, PA. 1p. 22189.280.
- 8402070019 FOIA request for complete NRC license file on 8td Nuclear Consultants, Limited (License 12-20362-01) HUBER 8 A. Sten A. Huber Consultants, Inc. 83/11/23. Office of Administration ip. 22189, 194.
- B402090026 Responds to appeal re denial of FOIA request for transcripts of NRC meetings held between B10821 & B30510 concerning restant at TMI-1 Forwards portions of Transcript 15.
 GHILK: B J Office of the Secretary of the Commission. B3/12/20 YANNER: A. C Kohn, Milstein, Cohen & Hausfeld. Spp. 22187 282. 241 Fiche 50-287:83/12/20,8402070026.
- --8402090050 Transcript of Commission 830415 discussion in Washington K rs steps on decision to restart TMI-1.Pp 1-16.Portions deleted ** Commissioners 83/04/15 17pp. 22189; 285 24K Firhe: 50-000, 83/12/20, 8402090026.

- B402090029 Responds to FOIA request for complete NRC license file on Std Nuclear Consultants.Limited (License 12-20362-01) Forwards App A documents Portions of Documents 5 & 6 withheld (ref FOIA Exemption 6) FELTON, J. M. Division of Rules and Records 83/12/29 HUBER, 8 A Stan A. Huber Consultants, Inc. 2pp. 22189 175
- --8402070036 Matl/Byproduct License 12-20362-01 for JJ Mikowski, authorizing possession of sealed sources containing Co-60, Ba-133, Cs-137 & Am-241 to be used in tests for leakage &/or contamination & instrument calibr ADAM, H J Region 3, Office of Director 83/08/04 4pp 22189 197
- --8402090046 Amend 1 to Matl/Byproduct License 12-20362-01, changing Item 1 to read licensed matl be used by or under supervision of JJ Mikowski or S Buhr,per Condition 12 ADAM-M J Region 3, Office of Director 83/11/04 1p 22189 201
- --8402090049 Requests addl info re license request contained in 830331 application re wipe sample surveys & radiation levels in unrestricted areas Response requested within 30 days ADAM.H.J. Region 3. Office of Director. 07698 83/07/01 MIKOWSKI.J.J. Affiliation Not Assigned. 1p 22189 202
- --B402090052 Responds to NRC 830701 request for add1 info re license application Add1 changes from initial application re highest activity source in calibr survey instruments described. Diagram encl.

 MIKDWSKI, J. Affiliation Not Assigned, 07698 83/07/14 ADAM, 8 Region 3, Office of Director 4pp 22189, 203
- --8402070057 Forwards application for matl/byproduct license, authorizing possession & use of sealed sources for calibr radiation detection instrumentation, dose calibrators, survey maters & pocket dosimeters.
 MINOMENI.U.J Affiliation Not Assigned 07698 83/03/30 ADAM, B. Region 3, Office of Director 2pg 22189; 207.
- --8402090062 Application for matl/byproduct license, authorizing JJ Mikowski to use %/or supervise use of Co-60,Cs-137 & Sa-133 sealed sources in calibr dose calibrators, survey maters & pocket dosimeters MIKOMBKI, J, J Affiliation Not Assigned, 07698 83/03/31 38pp. 22189, 207.
- --B402090066 Application for amend to Matl/Byproduct License 12-20362-01, changing name of licenses to Std Nuclear Consultants, Limited & adding SW Buhr as authorized User of scaled sources, S Buhr resume forwarded, Info deleted.

 MIKOWSKI, J. J. Affiliation Not Assigned 83/09/29 ADAM, W J Region 3, Office of Director 3pp. 22187-247.
- --8402090074 Amend 1 to Matl/Byproduct License 12-20362-01. changing applicant/licensee in Item 1 to Std Nuclear Consultants, Inc & adding 8 Buhr under Condition 12. Related info encl. VACHERTON.P Division of Fuel Cycle & Material Safety 83/11/02. App 22189: 250.
- 8402070081 Further response to FOIA request for IE Insp Rept 79-19, associated notice of proposed imposition of civil panelties, notice of violation & order to show causa. Forwards App A documents, Documents also available in POR. FELTON, J. M. Division of Rules and Records 83/12/20, HAMLIN, J. B. Bhaw. Pittman. Potts & Troubridge. 4pp. 22188:104 24X Fichs: 50-000, 83/12/20, 8402070081.
- --8008210302 Recommends Ofc of Nuclear Reactor Regulation request licensee update SAR QA program following IE Investigation Repts 50-498/79-14 & 50-497/79-14 REINHUTH.0 W. Division of Reactor Construction Inspection. B0/08/01. NASS,WP. Quality Assurance Branch 1p. 22188;124. 24X Fiche: 50-000,83/12/20,8402090081.
- ---B00911034B Forwards request for addl info re updating docketed GA program in response to 800430 show cause order. Describes subj areas to be addressed in update description Requests info be transmitted to util HAASS, W P. Guality Assurance Brench, 60/08/25, SCHMENCER, A. Licensing Brench i. 1p. 22188, 128 24X Fiche 50-000, 83/12/20, 8402090081.
- --8402090093 Requests that info re stope & significance of voids in concrete be coordinated & dispatched through L Underwood.

 DIRCKS, W. J. Office of the Executive Director for Operations.
 08005. 80/04/16. BRADFORD Commissioners. 1p 22188.109, 24
 Fiche: 50-000.83/12/20.8402070081.

- --B402090099 Forwards Eckhardt question re facilities at Page 84 of unedited transcript.per 801016 request Comments & answers to questions at Pages 43 & 72 will be returned w/transcript by 801020.

 SUERMANN, J F Dffice of Congressional Affairs 80/10/16
 BICKWIT.L Office of the General Counsel 2pp 22188 ii0 24X Fiche 50-000,83/12/20,8402090081
- --8402090127 Requests testimony on Commission position re adequacy of licenses GA programs at Subcommittee on Energy & Environ 811027 hearing on GA as applied to reactors under const UDALL, M K House of Rep , Interior & Insular Affairs 81/10/13 PALLADING. N Commissioners ip 22188 112 24% Fiche 50-000,83/12/20,8402090081.
- --8402090132 Requests that NRC be prepared to discuss GA problems at facilities at subcommittee 811119 hearing on GA
 UDALL.M K House of Rep. Interior & Insular Affairs 81/10/30
 PALLADINO.N Commissioners ip 22188 113 24X
 Fiche 50-000.83/12/20.8402090081
- ---8402090146 Forwards draft testimony to be presented by chairman before Bubcommittee on Oversight & Investigations on 800729 Comments re testimony requested by 800722 KAMMERER, C. Office of Congressional Affairs 80/07/18 AHEARNE, GILINSKY, HENDRIE Commissioners 1p 22188 135 24X Fiche, 50-000,83/12/20,8402090081.
- --8402090149 Forwards proposed final draft testimonies for Bubcommittee on Oversight & Investigations hearing KAMMERER, C Office of Congressional Affairs B0/07/29 AHEARNE, GILINBKY, HENDRIE Commissioners Ip 22188 144 24X Fiche 50-000, B3/12/20, 84020900B1
- --8402090155 Draft statement of JF Ahearns to House Subcommittes on Oversight & Investigations Pp 1-5 AHEARNE, JF Commissioners 800/07/29 6pp 22188,145 24X Fiche 50-000,83/12/20,8402090081
- ---8402090160 Draft statement of V Styllo to House Subcommittee on Oversight & Investigations.Pp 1-15
 STELLO: V. Office of Inspection & Enforcement, Office of the Director 80/07/29 16pp 22188 151 24X Fiche 50-000,83/12/20,8402090081.
- --8402090i64 Notifies that House Bubcommittee on Oversight & Investigations 800729 hearing postponed to 800923 Chairman Ahearne. Stello & Thornburg scheduled as witnesses KAMMERER.C. Office of Congressional Affairs 80/09/17 AHEARNE. GILINGRY. HEADRIE Commissioners. 1p 22188, 166 24X Fiche 50-000, 83/12/20, 8402090081.
- ---8402090168 Forwards draft addendum to Btello testimony for facility hearing Review & comments requested before 800919
 KAMMERER, C. Office of Congressional Affairs 80/09/18
 GILINBKY, HENDRIE Commissioners. 4pp 22188 167 24X
 Ficha: 50-000, 83/12/20, 8402090081
- --B402070171 Forwards proposed rev to testimony for facility hearing BICKWIT, L Office of the General Counsel. 80/09/22 AHEARNE Commissioners 3pp 22180:171. 24X Fichs 50-000, 83/12/20, 324202008:
- --8402090176 Forwards final testimony to be presented by Chairman Ahearne & Stello before House Subcommittee on Oversight & Investigations 800923 hearing. W/o encl KAMMERER, C. Office of Congressional Affairs, 80/09/23. AHEARNE, GILINGRY, HENDRIE Commissioners ip 22188-174, 24X Fiche-50-000, 83/12/20, 8402090081
- --8402070184 Discusses info for record re 800923 hearing on facility Hearing transcript received too late to impact FY81 appropriation.
 SUERMANN.J.F. Office of Congressional Affairs. 80/10/14
 Office of Congressional Affairs. 1p 22188 180 24X
 Fiche 50-000,83/12/20,8402070081
- -8402090188 Submits answers to questions at Pages 43.72 & 84 of transcript of facility hearing. Mat1 re impact of continuing resolution for FV80 no longer necessary KAMMERER. C. Office of Congressional Affairs 80/10/17. AMEARNE Commissioners, 1p. 22188,183 24X Fiche 50-000,83/12/20,8402090081

- --840/2070173 Responds to Chairman Ahearne 800723 request to provide info re Shoreham to Representative Lent June-Bept 1782 latest projected fuel load date CRANE,P Office of the General Counsel 80/10/07 SUERMANN, J Office of Congressional Affairs ip 22188 185 24X Fiche 50-000, 83/12/20/8402070081.
- --840209019B Forwards chapter from final rept of NRC special inquiry group re financial disincentives to safety at TMI.in response to questions raised at Subtommittee on Oversight & Investigations 800923 hearing AHEARNE, J F Commissioners. 80/11/13 ECKHARDT, B House of Rep. Interstate & Foreign Commerce 3pp 22188-190 24X Fiche 50-000.83/12/20.8402090081
- 8402090097 Further response to FDIA request for records re problems encountered by util during hot functional testing Forwards App A documents Ducuments also available in PDR Search for addl documents continuing and Records 83/12/22 GARDE, D COVERNMENT ACCUMENTATION OF RULES and Records 83/12/22 GARDE, D COVERNMENT ACCUMENTATION PROPERTY PROPERTY APPLIES OF SUBJECT 289 22187 084 24X Fiche 50-528,83/12/22,8402090097.
- --B402070114 Draft trip rept of B31114-16 sits visit to C-E. in Newington.
 NH. to review mfg of C-E-KBB reactor coolant pump & current
 testing of modified pump as applied to facilities Related
 info encl
 JACKSON, J E Equipment Qualification Branch 83/12/22
 NODNAN, V S Equipment Qualification Branch 11pp 22189 088
 24X Fiche 50-528, 83/12/22, 8402090097.
- --B402090128 Rev 1 to "Reactor Coolant Pump Operating Guidelines " Related info enc! # Arizona Public Service Co 63/12/22 21pp 22189 101 24X Fiche 50-528,83/12/22,8402090097.
- 8402090136 FOIA request for documents re 831015 accident at facility killing control room operator WC Janes GARDE, B.P., STEINKOENIG.K. Government Accountability Project 83/11/04 FELTON.J M Division of Roles and Records 2pp 22188 195 24X Fiche 50-280.83/11/04,8402090136
- B402090143 Responds to FOIA request for documents re NRC investigation of industrial accident involving burst steam pipe at facility. Forwards App A documents Documents also available in PDR FELTON, J M Division of Rules and Records. B3/12/12 QARDE, B. P Government Accountability Project 3pp 22186 197 24X Fiche 30-280, 83/12/12, 8402090149
- --8402090152 Informs of 831015 fatal accident involving WC Jones.

 Expansion joint ruptured during high pressure drain jump valve operation

 WILSON, J. L. Virginia Electric & Power Co. 83/10/17. Virginia Electric & Power Co. 24X Fiche. 50-280, 83/12/12, 8402090143
- 8402070203 FOIA request for info re Lixi, Inc. Lixiscope of America, Inc & 8 Huber Assoc. Inc CAULK, O H Redistion Service Organization. 83/11/15 Division of Rules and Records ip 22170, 001
- B402090206 Partial response to FOIA request for info re Lixi, Inc.
 Lixiscope of America, Inc & BA Huber Consultants, Inc
 Forwards App A documents. Documents also available in PDR.
 Documents partially withheld (ref FOIA Exemption 6)
 FELTON, J M Division of Rules and Records B3/12/20 CAULK, Q, H
 Radiation Service Organization. 7pp 22190:002
- --7905G00623 Requests amend to Matl/Byproduct License 12-17303-01 to add Victoreen Model 6B1-A instrument calibrator.
 HUBERLS A Stan A Huber Consultants, Inc. 99667 79/04/24
 GUINN.P R Redicisotopes Licensing Branch (Pre 790501). ip. 67052-001

e 12-17503-01 authorizing addition istrument calibrator ources Anhang

/05/30.

application

- --7911130224 Mati/Byproduct License 12-17303-01 for Stan A Huber Consultants, Inc is amended in its entirety per 790530 application Amend 6 authorizes use of Co-60, Cs-137, Ba-133 & Am-241 for calibr of instruments JONES, J A Material Licensing Branch 79/10/11 4pp 67052 on
- --8102190624 Requests award of Matl/Byproduct License t2-17303-01 to add JJ Mikowski, JA Gibbs & TM Kumpuris as licensed users & delete JW Porter & JA Branding HUBER, B A Stan A Huber Consultants, Inc. 06359, 80/12/16 Material Licensing Branch 11pp 67052 001
- --BiQ4090747 Submits addl info requested by NRC 810309 telcom reapplication to amend Matl/Byproduct License 12-17503-01.
 Addition of D Fetterolf as user & controls of Lixiscope transportation & security described HUBER, S. A. Stan A. Huber Consultants, Inc. 0484 81/03/09 GUINN, P. Material Licensing Branch 21pp 67052 001.
- --8104210566 Requests amend of Matl/Byproduct License 12-17503-01 to incorporate Lixiscope training course & revised training certification HyBER: 8 A. Stan A Huber Consultants, Inc. 0583 81/03/28, GUINN, P.R. Material Licensing Branch 7pp 67052:001
- --B104280035 Provides info to Agreement States re licensing & training course certifications for nonmedical uses of Lixiscope Model LS-80-X containing I-125 sealed sources Reciprocity recognition of training course requested, HUBER.J E Stan A Huber Consultants, Inc. 0669 81/04/06 Affiliation Not Assigned 2pp 67052 001
- --Bi04280232 Matl/Byproduct License 12-17503-01 for Stan Huber Consultants, Inc is amended per 801214 ltr. Amend 7 adds I-125 sealed sources for possession storage & use in Lixiscope devices for demonstration & training purposes QUINN.P R. Material Licensing Branch 81/04/10 ip. 67052 00
- --8206110300 Ack receipt of 820520 ltr reporting theft of licensed all WIEDEMAN, D. O. Region 3, Office of Director. 82/06/08 HAMER, 8 & Sten A. Huber Consultants, Inc. 1p 22191125
- --B205110307 Informs of 820518 theft of five sealed sources used for calibrating nuclear instruments. Car window broken & ammo box containing sources stolen, No substantial hazard will result to persons in unrestricted areas
 HUBER.S. A. Stan A. Huber Consultants. Inc. 82/05/20. WIEDCHAM.O. Region 3. Office of Director. 13pp. 2219:112.
- --B40209020B Responds to B21013 request for add1 info re deficienties noted w/820924 application for medical devices & draft I-125 Lixiscope instruction manual. BAVINI.R.J LIXI. Inc. 82/11/06, DELMEDICD.J Division of feel Cycle & Material Safety 19pp. 22190.034
- --B402090210 Lists response to 770505 ltr re 770404 license format submission including elimination of privacy act statement & development of radioactive shipment receipt & notification procedure. HUBER, S. A. Stan A. Huber Consultants, Inc. 77/05/23, PROMAS,F.F. Radioisotopes Licensing Branch (Pre 790501) 22pp 22190; 202
- --B402090215 Forwards list of licenses names prepared w/new format/fir 770907 telcon,List of NRC licenses evaluated during month will be sent at end of each month.

 HUBER,B A. Stan A. Huber Consultants, Inc. 77/09/08 P80MA8.F.

 Radioisotopes Licensing Branch (Pre 790501), 3pp. 22190.304.
- ---B402090219 Discuses recent Lixi. Inc application for madical distribution license to distribute Lixiscops to group madical idensess. Lixiscops will fall into Group VI (use of sources & devices containing byproduct matl) .

 HALKER, W. J. Division of Fuel Gycle & Naterial Safety. B3/Q1/13 BRINER, W. Advisory Committee on Madical Uses of Isotopes. ALMOND.P. Advisory Council for Decontamination of TMI Unit 2 2pp. 22190.092.
- ---B402090221 Application for amend to License 12-17503-01, authorizing BA Huber, JW Porter, JB Atwood, SW Buhr or JA Lovelace to supervise use of licensed matl. HUBER, B. A. Stan A Huber Consultants, Inc. 77/10/01. 10pp 22190:307.
- ---B402090223 Forwards six labels used on Lixiscope. Five labels used an medical model & one used on veterinarian model BAVINI.R. J. LIXI, Inc. B3/03/01. DL MEDICO, J. Division of Puel Cycle & Material Safety 2pp 22190 094
- ---8402090227 IE Insp Findings & Licensee Ack dtd 771101 of Licensee 12-17503-01. Insp findings: no noncompliance noted. MOE: H F. Region 3, Chicago, Office of the Director 77/11/01 ip. 22190:317

- --8402070232 Application for License 12-17730-01 to cover sale of I-125 Lixiscope used for veterinary & nonmedical uses QROSSMAN,L LIXI, Inc 07668 81/04/18 15pp 22170 079
- --B402090233 Amend to License 12-17503-01 for SA Huber Consultants, Inc. authorizing BA Huber.JH Porter.JB Atwood.SH Buhr & JA Lovelace to supervise use of licensed met! HRIGHT.E.O Redictiotopes Licensing Branch (Pre 790501) 78/04/21. 1p. 22190 333
- --B402090236 License 12-19730-01 for Lixiscope of America, Inc authorizing I-125 Lixiscope demonstration & distribution to authorized individuals

 QUINN, P R Division of Fuel Cycle & Material Safety 81/06/01

 3pp. 22190 113
- --8402090242 Forwards application to amend License 12-19730-01.increasing isotope limit to 100, moving facilities & removing R Grossman as user NIEBELMAN, K LIXI, Inc. 13842 83/02/09 GUINN, P NRC No Detailed Affiliation Given 1p. 22190 116
- --8402090244 Foresees need to periodically update license emends unless basic structure modified to include small swaled source byproduct math for calibr & ref stds HWBER.8.A & Stan A. Huber Consultants, Inc. 78/04/03. HADE, L. Radioisotopes Licensing Branch (Pre 770501) 2pp 22170 358.
- --8402090246 Application for amend to License 12-17730-01, increasing I-125 isotope possession to 100, moving facilities & removing R Orossman as user, HIEBELHANK LIKI, Inc. 13842. 83/02/09 5pp 22190-117
- --B402090248 Application for amend to License 12-17503-01. changing address & increasing possession limit of Cs-137 Model 72602 sealed source Cs-137 solid & Ba-133 NEN Model NES-358 gamma ref sources.

 HUBER, S. A. Stan A Huber Consultants, Inc 97302 78/11/14 BABSIN, N Redicisotopes Licensing Branch (Pre 770501) 10pp. 22190:360
- --B402090249 Amend 1 to License 12-19730-01, authorizing address change HICKEY, J. W Division of Fuel Cycle & Material Safety. B3/04/01 ip. 22190-122.
- --8402090252 Forwards Amend 1 to License 12-19730-01 per 830207 request Written certification requested within 30 days stating that devices containing radioactive matl removad from Trans Lessing Intl W/o encl.
 HICKEY.J W Division of Fuel Cycle & Material Safety. 83/04/01 WIEBELMAN.K, LIXI, Inc. 1p. 22170 123.
- --B402090254 Certifies that devices containing radioactive matl not located at Trens Leasing Intl.per request. HIESELMAN.K. LIXI, Inc. B3/04/08. HICKEY, J W. Division of Fuel Cycle & Material Bafety. ip. 22190:124
- --B402090257 Forwards Amend 3 to License 12-17503-01.NRC unable to amend license to authorize possession of byproduct math referenced in Bection 32,14(d) of 10CFR35.Revised license amend requested BABSIN,M. Radioisotopes Licensing Branch (Pre 790501), 78/06/01 HUBER,S.A. Stan A. Huber Consultants, Inc. 19, 22191-008.
- --8402070237 Forwards application to amend License 12-17730-01 authorizing Lixiscope distribution & radiation safety training for Lixiscope users WIESELMAN, K. LIXI, Inc. 15464. 83/07/26. GUINN, P. NRC No Detailed Affiliation Given. 1p. 22170:125
- ---8402090262 Application for amond to License 12-19730-01, authorizing Lixiscope distribution & radiation safety training for Lixiscope Users.
 WIESELMANK, LIXI, Inc. 15464. 83/07/26. 4pp. 22190:126
- ---B402090265 Amend 3 to License 12-17503-01 for BA Huber Consultants, Inc authorizing use of Ba-133 for dose callbr instruments. BASSIN.N. Radioisotopes Licensing Branch (Fre 790501). 78/06/01 1p. 22191019.

- --8402090266 Requests status of 830726 application for amend to License 12-19730-01 WIEBELMAN.K LIXI, Inc Affiliation Given ip 83/09/02 GUINN,P NRC - No Detailed Affiliation Given ip 22190 130
- --B402090249 Amend 4 to License 12-17503-01 for SA Huber Consultants. Inc changing address & authorizing SA Huber. JW Porter. JA Atwood. SW Buhr. JA Lovelace. HJ Huber & JA Branding to supervise use of licensed math WRIGHT. E O Material Licensing Branch 79/01/29 ip 22191 020
- --8402090270 Requests listed addl info re 830726 application to amend License 12-19730-01 HICKEY.J W Division of Fuel Cycle & Material Safety 83/09/07 WIESELMAN.K, LIXI. Inc 2pp 22190 131
- --8402090272 Requests ltr to be used as direct ref re nuclear physician user listed on licenses HUBER, S A Stan A Huber Consultants, Inc 79/03/12 COOPER, J Region 3, Chicago, Office of the Director ip 22191 021
- ---B402090274 Discusses issues re licensing medical use of Lixiscope, including training requirements & opposition to specific licensing Lixiscope distribution authorized to broad licensed medical institutions HALKER, W. J. Division of Fuel Cycle & Material Safety B3/09/08 FARNER, B LIXI, Inc. 2pp. 22190 133
- ---8402070278 Discusses naming medicine physicians as authorized users of byproduct mat1 on mobile van licenses Physicians not named on license may approve procedure involving radiopharm administration & prescribe radiopharm COOPER.J W Material Licensing Branch 79/04/23 HUBER, S A Stan A Huber Consultants, Inc. ip. 22191-022
- --8402090279 Responds to inquiry re min training criteria for licensing use of Lixiscope Training & experience stds requiring total of less than 12 h for physiciens who do not meet Group VI criteria in preparation MILLER. V L Division of Fuel Cycle & Material Sefety 83/09/12 NUSSBAUMER, D A Assistant Director for State Agreements Programs 4pp, 22190,135.
- --8402070282 Responds to 8 Walker request to draft set of min training criteria for specific licensing for use of Lixiscope by health care professionals Proposed recommended medical users training for Lixiscope diagnostic device encl.

 BELL.8 W Division of Fuel Cycle & Material Safety 83/09/15
 CUNNINOMAM.R E Division of Fuel Cycle & Material Safety 4pp 20150 170
- --8402090284 Requests status of application for amend to License 12-19730-01 WIEBELMAN,K LIXI, Inc 83/09/22 GUINN,P NRC - No Detailed Affiliation Given ip 22190.143
- --8402070288 Supplemental application to amend License 12-19730-01, authorizing Lixiscope of America employees to train company representatives.
 WIESELMAN.K LIXI, Inc. 83/09/24 2pp 22170-144
- --8402070293 Lists considerations that amend to specific license of limited scope authorizing Lixiscope possession & use based on Considerations include specific training for Lixiscope user & adequate security controls. Related info encl HALKER, H. J. Division of Fuel Cycle & Material Safety. B3/09/27, QLENN, J. Region i. Office of Director. FOTTER, J. Region 2, Office of Director. MALLETT, B. Region 3, Office of Director. ip 22190 146
- --8402090296 Advises of submittal of addl amend fee for 790530 application to amend License 12-17503-01 per 100FR170, 31, Category 40 & Footnote 1(d) JACKBUN, 9. License Fee Management Branch 79/06/18 HUBER, 8. A Stan A Huber Consultants, Inc. 1p 22191 029,
- --8402090300 Forwards requested info re qualifications of Lixiscope of America personnel representative training requirements & personnel profile of representatives. WIESELMAN, K. LIXI. INC. 83/10/14. HICKEY, J. Division of Fuel Cycle & Material Safety, 7pp. 22190:148.
- --8402070304 Supplemental application for amend to License 12-17503-01, deleting Item 2 for classification of licensing fee schedule.

 HUBER, B.A. Stan A. Huber Consultants, Inc. 79/06/22. JACKBON, Q. License Fee Management Branch. 1p. 22171-030

- --8402090305 Amend to License 12-19730-01 for Lixiscope of America, Inc. authorizing use of Lixiscope imaging devices for training, demonstration & distribution to authorized individuals. RICKEY.J W Division of Fuel Cycle & Material Safety. 83/10/21 ip 22190 135
- --8402090309 Responds to 751218 telcon re handling of possible liability questions arising from 751020 application to amend License 12-12418-01, adding gamma survey instrument calibr Questions of liability satisfied.
 PIERDINOCK,P Thorek Hosp & Medical Center Chicago, IL 71197 75/12/22 HADE,L Material Licensing Branch 1p 22190 156
- --8402070311 Corrected Amend 5 to License 12-17503-01 for SA Huber Consultants, Inc authorizing use of Cs-137 sealed source for calistr JL Shephard Model 28-5 calibrator JONES, J A Material Licensing Branch 79/07/18 ip 22191 031
- --8402090312 Confirms 760322 telson re current licensure to calibr survey maters under License 12-12418-01 Author will apply for private-practice NRC license HUBER: 8 A Bian A Huber Consultants, Inc 71197. 76/03/23 VACCA
- --BA02090313 Requests add1 info re 790330 application for amend to License 12-17503-01 Anticipated max activity source should be used for calculations or radiation level measurements JONES.J A Material Licensing Branch 79/08/30 HUBER.S A Stan A Huber Consultants, Inc. 1p 22191 032
- --8402070315 Forwards application form re initial license application for use of Cs-137 sealed source in calibr of survey meters at temporary job sites Application should spacify transportation procedures H/o encl HUBER-8 A Stan A Huber Consultants, Inc. 76/03/23 VACCA,P Material Licensing Branch ip 22170-158
- ~-B402090317 Forwards application for mati/byproduct license.authorizing use of Cs-137 gamma survey instrument calibrator & dosimeter calibrator HUBER: 5 A Stan A Huber Consultants, Inc. 76/04/19 BASSIN.N Radioisotopes Licensing Branch (Pre 790501) 1p 22675:001
- --8402090319 Application for matl byproduct license, authorizing use of Cs-137 gamma survey instrument calibrator & dosimeter calibrator WHER: 8 A Stan A. Huber Consultants, Inc. 76/04/19 27pp 22190:160
- --B402090322 Requests addl info re 760419 revised application for license to identify manufacturer & model number of sealed source contained in Eon Corp Model 64-764 celibrator Info re Model 66-200 dosinater celibrator unavailable BASSIN:N Radioisotopes Licensing Branch (Pre 790501) 71197. 76/05/20. HUBER,S A Stan A Huber Consultants, Inc. 2pp 22190:187
- --B402090326 Responds to 760520 request for add1 info re application for byproduct mat1 license. Survey meter calibrator will be obtained from Victoreen Instrument Go instead of Eon Corp.
 HUBER, B.A. Stan A Huber Consultants, Inc. 71197 76/06/18.
 BASSIN N Radioisotopes Licensing Branch (Pre 790501) 18pp.
 22190 189.
- --B402090331 Forwards License 12-16960-01. Isotope Products Lab Model SK-125 desimeter calibrator not included due to lack of evaluation by State of CA Application for license amend may be submitted when device evaluated BASSIN,N Radioisotopes Licensing Branch (Pre 790501) 76/07/26 HUBER,S A Stan A Huber Consultants, Inc. 1p 22190, 207.
- -8402090333 License 12-16760-01 for SA Huber Consultants, Inc. authorizing use of Victoreen Model 681 instrument calibrator for instrument calibr.

 BASSIN:N Radioisotopes Licensing Branch (Pre 790501). 76/07/28
 3pp 22190 208
- --8402070340 Forwards info re Isotope Products Lab Model 04-200 dosimeter calibrator containing 70 uci Cs-137. GLABEER, M. Nuclear Associates, Inc. 76/08/11 BASSIN, N Radioisotopes Licensing Branch (Pre 790501) 4pp 22170 211
 - B402090346 Application for renswal of License 12-17903-01, authorizing use of listed elements, including Co-60 solid, Ca-137 solid, Ba-133 scales source, Cs-137 scaled source, Am-241 scaled source & I-125 scales source
 HUBER, S.A. Bitan A. Huber Consultants, Inc. 07662, 81/04/10
 Bpp 22191-081

- --B402090347 Application for amend to License 12-12418-01, covering Ci-137 survey meter calibrator Model 72602 scaled source w/max possession of one source of 100 mCi PIERDIMOCK.P, ROTHBART.F. Thorek Hosp & Medical Center Chicago.IL HUBER.B A Stan A Huber Consultants, Inc 76/09/LD BASBIN.N Radioisotopes Licensing Branch (Pre 790501). ip. 20190-215
- --B402090353 Application for amend to License 12-16960-01, authorizing use of Capinter. Inc dose calibrator std source set Related info enci
 HUBER.S A , KUMPURIS.T M Stan A Huber Consultants, Inc. 83603 r
 76/09/08 BASSIN,N Radioisotopes Licensing Branch (Pre 790301; 11pp. 22190 216
- ---8402090354 Ack receipt of application to renew License 12-17503-01 License will not expire until final action taken by NRC HICKEY. J W Material Licensing Branch. 81/05/04 HUBER. S. A Stan A Huber Consultants. Inc. 1p. 22191 099.
- --B402090358 Requests add1 info re 760908 application to amend License 12-16960-01 concerning Capintec dose calibrator std source set Isotope Products Lab Model 8K-125 dosimeter calibrator has not been evaluated by State of CA Related info encl. WRIGHTLE G. Radioisotopes Licensing Branch (Pre 790501) B3603 76/10/27 HUBER, 8 A Stan A Huber Consultants, Inc. 16pp 22190 227.
- --8402090363 Supplemental application for renewal of License 12-17503-01, authorizing performance of radiation surveys of industrial gauges containing radioactive matl & ref Item 110 & 12D to Conditions 11 & 12 on Item 8E list HUSER:8 A 8 tan A Huber Consultants. Inc 81/05/08. QUINN.P Radioisotopes Licensing Branch (Pre 790501) 4pp 22191:101
- --B402090365 Responds to 761029 itr re application to amend License 12-16960-01, authorizing use of Capinter dose calibrator std source set & Isotope Products Model SK-125 dosimpter calibrator. State of CA completed Model SK-125 review HUBER.5 A Stan A Huber Consultants, Inc. 76/11/04, MRIGHT, E Radioisotopes Licensing Branch (Pre 790501). 2pp. 22190-243.
- --8402090368 Amend to License 12-16960-01 for 8A Huber Consultants Inc. authorizing use of Co-60.Cs-137 solid & Cs-137 sealed source for calibr of dose calibrator instruments.

 BROWN, J M Radioisotopes Licensing Branch (Pre 790501). 76/12/17
 29p 22190 245
- --B402090370 Requests clarification re recent license condition in which NRC automatically grants permission to store radioactive matl to medical licensees, Main concern re hosp whose radioimmunpassay labs use greater than 200 uCi I-125, BURR, S W Stan A. Huber Consultants, Inc. 08789, 81/08/21, DELMEDICO, I. Material Licensing Branch 3pp., 22191:105.
- --8402070372 Responds to advise re revamping license application procedures for clients Sys, definitions & procedures developed to serve approx 90% of new license clients HUBER, S.A. 8tan A. Huber Consultants, Inc. 77/04/04. HADE, L. Radicisotopes Licensing Branch (Pre 790501). 28pp. 22190:247.
- --8402090376 Amend to License 12-17503-01 for SA Huber Consultants, Inc. authorizing use of Co-60 & Cs-137 solids & Ba-133, Cs-137, Am-241 & I-125 sealed sources in dosa calibrators, dosimeters & Lixiscope devices GUINN, P R. Material Licensing Branch. 81/11/24, 4pp. 22171 108
- --B402090377 Corrected License 12-17503-01 for BA Huber, authorizing use of Cs-137 seeled source for Victoreen Model 681 instrument calibrator for instrument calibr.
 BASSIN.N Radioisotopes Licensing Branch (Pre 790501). 77/04/25 3pp. 22190.275.
- ---8402090382 Corrected amend to License 12-17503-01 for SA Huber Consultants, Inc. authorizing use of Co-60, Cs-137 solid & Cs-137 seled source for calibr of dose calibrator instruments

 BASSIN,N Radioisotopes Licensing Branch (Pre 790501). 77/04/25
 2pp. 22190.278.
- --8402070383 Lists comments on 770404 submittal. Form for physician training should include 200 h supervised lab training in basic radioisotops handling techniques.
 PSOMAS.P.P. Radioisotopes Licensing Branch (Pre 770501).
 77/05/05 Stan A. Huber Consultants, Inc. 2pp. 22190:280.
- ---8402090387 Application for amend to License 12-17503-01, authorizing U¹⁸ of Cs-137 smaled source for instrument calibr.
 HUBER, 6 A Stan A Huber Consultants, Inc. 13323 82/12/13.
 GUINN, P. Material Licensing Branch. 2pp. 22191:126.

1

- --B402090390 Amend 7 to License 12-17503-01 for SA Huber Consultants, Inc. authorizing use of Cs-137 sealed source for instrument calibr HICKEY,J W Division of Fuel Cycle & Material Safety 83/01/31
 - tp. 22191 128
- --8402090393 Discusses need for generic description of acceptable calibrates & raf sources re license amend authorizing use of Pu-239 Generic qualifications listed HUBER, 8 A Stan A Huber Consultants, Inc 83/08/08 WANG, J Division of Fuel Cycle & Material Safety 2pp 22191 129
- --B402090397 Amend to License 12-17503-01 for SA Huber Consultants, Inc. authorizing use of Cs-137 sealed source & Pu-239 plated source for instrument calibr. WAND, J Division of Fuel Cycle & Material Safety 83/09/15 1p 22191.131.
- E402090404 FOIA request for four categories of documents re NUREG-0103.

 "BTB for B&H PHRs." BTB for C-E & Westinghouse PHRs,Reg
 quide 1.45 & NUREG 75/997 (NUREG-0800). "NRC BRP"

 #ADDEN.T.J Kage, Bcholer, Fierman, Hays & Handler B3/12/06
 NDRRY.P.O Office of Administration. 2pp 22193 001
- 8402090408 Partial response to FDIA request for four categories of documents re NUREG-75/087 (NUREG-0800). "SRP for Review of BARs for Nuclear Plants " Review of remaining documents incomplete Forwards App A documents FELTON.J M. Division of Rules and Records 83/12/30 MADDEN.T.J Xaye, Bcholer, Fierman, Hays & Handler. 4pp. 22193 003 24X Fichm: 50-000.83/12/30,8402090408
- --7903020085 Requests review & recommendations re encl Reg Quide i 16, proposed Revision 5 Provides outline of requested action & forwards suppl matl MORRISON.W M. Assistant Director for General Engineering Standards. 79/02/02 LEVINE,S Office of Nuclear Regulatory Research, Director 96pp. 22193.069
- --7903260077 Confirms 790301 telcon re interpretation of Tech Specs Baction 6 5 3 5a shall not impose requirements for reporting violations of Tech Specs beyond Section 6.9 reporting requirements.

 **IEMANN.D L Operating Reactors Branch 2 (Pre 790625). 79/03/0 DRAKE.J.H. Sauthern California Edison Co. 2pp. 22193-035 24 Fichs 50-000,83/12/30,8402090408.
- --7907050105 Responds to 770506 memo re Tech Spec action statements developed per Reg Quide 1.16
 QCK_LER.K.R. Division of Operating Reactors. 77/08/16
 BNIEZEK,J.H. Division of Reactor Operations Inspections Spp 22193
- ~-6002070305 Discusses NRC 791206 meeting re 8TB & operability & action statements. Recommends incorporation of requirement to verify operability or redundant counterparts when safety components & sys info STB & Tech Spacs.

 MCBELEY, N.C. Division of Reactor Operations Inspections 79/12/27. EISENHUT, D.G. Division of Operating Reactors 2pp 22193:238
- --8004230213 Responds to 800201 memo re operability requirements for pumps Tech Spec ACTION statement time period starts after pump determined inoperable When data is not within required action range, pump must be declared inoperable.

 BRYAN, S E. Division of Reactor Operations Inspections. 80/03/17 LEMIB, R C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 2pp. 22193/021
- --8005020327 Recommends revision of BTB G.O.G & individual Tech Specs Action required to identify NRC policy re time requirements for initiating hot standby & hot shutdown action statement requirements w/sys out of swc due to personnel error.

 BRYAN.B.E. Division of Reactor Operations Inspections. B0/02/21.

 GAMPLL.W.P. Assistant Director for Standard & Advanced Reactors 2pp. 22193:016
- --BOGSOROSSE Recommends change to BTB G O S to reflect licenses responsibility for ensuring facility remains within defined safe operating envelope.

 MCCABE, E.C. NRC Regional Offices. BO/01/23 BRYAN, S.E. Division of Reactor Operations Inspections. 3pp. 22193.018
- --BiQ4290034 Forwards revised Bection 5 2 5 of SRP.Revision clarifies BRP by amend of existing acceptance criteria, areas of raview & procedures & incorporation of implementation section. M/o ancis PARR.O.D. Auxiliary Systems Branch. 81/04/21. BKQVHOLT:D J. Licensing Guidance Branch ip. 22193-246

- --8201250042 Discusses licensee question as to NRC policy re whether or not licensee could voluntarily enter into conditions which would lead to operation in degraded mode as permitted Tech Spec action statements MARTIN.R A Operating Reactors Branch 3 81/12/29 CLARK.R A Operating Reactors Branch 3 3pp 22193 050
- --8304070059 Advises that licensee may initiate & complete reduction in operational modes in shorter time interval than required by allowable out-of-syc time & add unused time to time provided for operation in lower operation mode EIBENHUT.D Q Division of Licensing B3/03/23 NORELIUS.C E Division of Project & Resident Programs 2pp 22193 010
- --8304140324 Informs of NRR position on when action statement is entered as consequence of failure to perform required surveillance tests Action statement entered when items required operable by limiting conditions for operation are inoperable EISENHUT, D. 9. Division of Licensing 83703/11 NDRELIUS, C. E. Division of Project & Resident Programs 1p 22193 014
- --8402090411 Forwards draft summary of 780717 meeting re proposed rev to Reg Guide 1 16 on reporting of operating info Comments on corrections, additions or deletions requested promptly to meet 780818 issue date Commitment dates requested MEDEIROBM S NRC - No Detailed Affiliation Given 78/08/11 NRC - No Detailed Affiliation Given 18pp 22193 165
- --8402090413 Forwards summary of 780719 meeting re proposed rev to Reg Guide i 16 on reporting of operating info,per GAD feedback program recommendations ARLOTTO, G A Office of Nuclear Reactor Regulation, Director 78/08/31 STELLO, V , SNIEZEK, J , HALLER, N Office of Nuclear Reactor Regulation, Director 1p 22193 183
- --8402090416 Summarizes 780719 meeting in Rackville,MD re proposed rev to Reg Guide 1 16 on reporting of operating info Rev will proceed w/clarification of examples & simplification of language as goals No major changes in scope of reporting * NRC - No Detailed Affiliation Given 78/08/29 NRC - No Detailed Affiliation Given 12pp 22193 184
- --B402090420 Discusses changing NRC philosophy re operability demonstration of redundant sys (F20290H1) Interpretation of "immediate" as within 4 h-per 770427, cannot be generally applied BNIEZEK, J H Division of Reactor Operations Inspections 77/05/20 FIORELLI, 9 Region 3, Chicago, Office of the Director ip 22193,007
- --B402090423 Forwards comments re proposed ray to Reg Guide 1 16 on reporting of operating info HALLER, N.M. Office of Management and Program Analysis 78/09/14 ARLOTTO, O.A. Division of Engineering Standards 18pp 22193 19
- --8402090426 Forwards 780719 & 20 agenda for mestings re proposed ray to Reg Guide 1 16 on reporting of operating info ARLOTTO, 0 A Division of Engineering Standards 78/06/30 STELLO, V. Division of Operating Reactors GNIEZEK, J Division of Reactor Operations Inspections. HALLER, N Defice of Management and Program Analysis 7pp 22173-226
- ---B40209042B Recommends interpretation of Tech Bpecs "immediate" required action time to be 4 h,per QE BYS re operability demonstration of redundant sys Comments on acceptability \$/or legality of interpretation requested.
 FIORELLI, Q Region 3, Chicago, Office of the Director 77/04/27 SNIEZEK,J.H. Office of Inspection & Enforcement, Office of the Director Epp 22193.008
- --8402090429 Provides NRR position on shutdown time allowances when limiting condition for operation not met, per CE Norelius 830209 request. Licensee may complete operational mode reduction in less than required time. EIBENHUT.D. G. Division of Licensing 83/03/23 NORELIUS.C E Region 3. Office of Director 2pp. 22193-233
- ---8402090434 Describes position on 791206 meeting w/NRR re interpretation of operable/operability Continued operation under Tech Spec action statement never allowed unless protection svailable from at least one train of equipment
 BTREETER.J Region 3, Chicago, Office of the Director. 79/11/29
 RIEBLAND.J. Office of Inspection & Enforcement, Office of the Director 2pp. 22193 236
- --B402070436 Informs that no safety/safeguards requiremets exist specifically for changing operating modes, though other requirements tend to ameliorate problem.
 THOMAS.C O NRC No Detailed Affiliation Given B2/11/07
 MIRAGLIA.F. NRC No Detailed Affiliation Given ip. 22193 240

- --8402090437 Describes STB requirements for changing operating modes
 Surveillance requirements for sys required operable per
 limiting condition for speration must be performed within
 stated surveillance interval, per Spec 4 0 4
 BRINKHAN.D S Standardization & Special Projects Branch
 82/11/07 MRACLIA.F J Assistant Director for Safety Assessment
 3pp 22193 241
- --8402090438 Describes safeguards requirements for safety sys prior to changing modes No requirements specifically address subj.
 NUREO-0708, "Acceptance Criteria for Evaluation of Reactor Security Plant," contains guidelines for major maint MCPEEK.E W Bivision of Licensing 82/11/09 MERADLIA,F J Assistant Director for Safety Assessment 2pp 22173 244
- --8402090441 Forwards revised Section 5 2 5 of SRP,NUREG-0800 (formerly NUREG-75/087) Publication for comment unwarranted since changes either previously approved or clearly necessary Title page enc!

 MURLEY.T E Division of Safety Technology ERNST, M L Assistant Director for Technology Review BAER.R L Safety Program Evaluation Branch 81/05/28 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp. 22193 247
- --8402090443 Forwards info re rev to SAP SHERDN.B W Reactor Systems Branch 80/09/30 Reactor Systems Branch 44pp 22:93-249
- --8402090447 Requests NRR position on point when action statement is entered as consequence of failure to perform surveillance tests, per STS 4 0 3 NDRELUS, CE Division of Project & Resident Programs 83/01/31 EISENHUT, D 0 Division of Licensing 1p 22193 015
- --8402090451 Suggests that monthly rept requirements be uniformly revised to require submittal no later than 15th of month. Max use recommended for C Nelson generic safety svaluation to expedite preparation of amend package GOLLER.K R Division of Operating Reactors 77/12/02. SCHWENCER,A Operating Reactors Branch 1 (Pre 800428). DAVIS.D Operating Reactors Branch 2 (Pre 800428) LEAR, O Operating Reactors Branch 3 (Pre 800428) 2pp 22193:043
- ~~840,2090.453 Forwards draft ltr informing licensees that requirement for annual operating rept deleted & describes info meded in lieu of rept Ltr should be distributed by 770915 ODLLER, K R Division of Operating Reactors 77/09/09 ECHWENCER, A Operating Reactors Branch 1 (Pre 800428) DAVIS, D Operating Reactors Branch 2 (Pre 800428) LEAR, O Operating Reactors Branch 3 (Pre 800428) Jpp 22193 045
- --8402070456 Requests interpretation of Reg Guide 1 16 re reporting of operating info per Tech Specs
 GULLER,K R Office of Nuclear Reactor Regulation, Director 77/12/12 SMEZEK,J H Office of Nuclear Reactor Regulation, Director 2pp 22193 048
 - R402090462 Requests determination re possibility for licensee to avoid 30-day rept by entering into Tech Spec action statement andition regardless of cause Specific time limits suggested in Tech Specs for preventative maint visited by the Company of the irector 77/05/06 OGLIER, K & Office of Nuclear Reactor sgulation, Director 3pp 22193 056
 - 2090471 Provides guidance on acceptable locking fevices & control of evices for manual switch & automatic operated components, in assonse to 770718 request AIESLAND J. Division of Reactor Operations Inspections 77/08/26 MADSEN, G.L. Region 4. Dallas, Office of the Director 2pp 22193,023 24% fiche 50-000,83/12/30,8402090408.
- -8402070472 Summarizes reporting requirements for ROs & special repts, per current 875,App A
 MCGOUGH,J M Standard Technical Specification Group (Pre 791030).
 78/03/24, STELLO,V Division of Operating Reactors 2pp
 22193 045
 - 2090476 Discusses Tech Specs per 710720 memo Licensea desires to stand allowable out-of-sec time required to submit either squast for Tech Spec change or request for exemption Both Johnittals should be submitted to Div of Reactor Licensing JRRIS.P A Atomic Energy Commission 71/07/29. LOW.L D Atomic lergy Commission, ip 22173:025
 - *090477 Forwards comments re-proposed Rev 5 to Reg Quide 1 16. eporting of Operating Info:App A Tech Specs," per 790202 quest for review Comments largely editorial Format readily ideratod & change clarified W/o encl
 LLER, D R Division of Site Safety & Environmental Analysis, 703/01 MORRISON, W. M., Division of Operating Reactors 2pp 193 067

- --840/2070/481 Forwards NJ Chrissotimos 82:015 request for Tech Specinterpretation re operability.per 800/410 ltr redefining term for Tech Spec change Response requested by 830/415 NORELIUS.C E Division of Project & Resident Programs 83/02/16 EISENHUT.D 0 Division of Licensing 2pp 22:173 030
- --B4020904BB Requests NRR position on Tech Spac interpretation of operable based on util denial of noncompliance involving operability of Duame Arnold emergency sys Problem may apply to all BHRs w/o BTB CHRISBOITMOB,N Region 3, Office of Director B2/10/15 HALKER,R D Region 3, Office of Director 3pp 22193-032 241 Fiche 50-000, B3/12/30, 840209040B
- --B402090557 Informs of rev to generic BTS to eliminate problem re requirements for maint of records for facility components, in response to 750513 conterns MCGDUGH. J M Division of Reactor Licensing (NRR-1975 only). 75/05/27 SNIEZEK, J H Office of Inspection & Enforcement, Office of the Director 1p 22193 037
- --8402070560 Recommends STB format be revised to require that licenters identify specific components to be covered & related threshold value criteria SNIEZEK, J.H. Office of Inspection & Enforcement, Office of the Director 75/05/13 STOLZ, J.F. Division of Reactor Licensing (NRR-1975 only) 2pp 22193 038 24% Fiche. 50-000, 83/12/30, 840209408
- ~-8402070343 Concurs w/750712 understanding of STS Item & 10.1 re retention of sufficient records to permit plan status & condition determination for period of 5 yrs GILRAY, J W Division of Reactor Licensing (NRR-1975 only). 75/01/15 HALLIR E Office of Inspection & Enforcement, Office of the Director ip 22193 040
- --8402090366 Informs that most non-819 facilities not required to revise all ROs, in response to 760625 memo All Tech Specs being made consistent w/requirement to review 24 h AD rept Addl sys experience needed for further changes
 OULLER, K. R. Office of Nuclear Reactor Regulation, Director 76/79/19 SNIEZEK, J. D. Office of Inspection & Enforcement, Office of the Director 2pp 22193 041
- ---8402100137 Requests NRR position on shutdown time allowances when limiting condition for operation not mat Clarification needed on possible licensee addition of unused portions of allowable time to get to next descending shutdown condition. NORECLUS.C E Division of Project & Resident Programs. B3/02/07 EIBENHUT, D. O Division of Licensing 2pp 22193-012.
- --8402100171 Recommends facility Tech Specs be reworded to require that licensee rept on extended meint contain justification for continuing operation & rept be submitted to Div of Reactor Licensing LOWL D. Atomic Energy Commission. 71/07/20. MCRR19.F.A. Atomic Energy Commission. 2pp 22193 026 24X Fichs.50-000.83/12/30.8402090408
- --B402100182 Forwards F8 Centrell 761123 memo re inconsistency in unidentified sys lask rates. Recommends inconsistency in max primary sys lesk rates for Buffs be referred to NRR for Tech Spec resolution
 LONG.F. J. Region 2, Atlanta, Office of the Director. IEB-74-168
 76/12/10. SEYFRIT.K V. Office of Inspection & Enforcement. Office of the Director. 10 22193 028
- --B4021001B7 Identifies inconsistency in unidentified max primary system; leak rate NUREG-75/067 cited as guidance Recommends inconsistency be referred to NRR for resolution CANTRELL, F. B. Region 2, Atlanta, Office of the Director, 76/11/23, LONG-F. J. Region 3, Ghicago, Office of the Director ip. 22193-029 24X Fiche 50-000, 83/12/30, 8402090408.
- --8402090466 Disagrees w/790830 interpretation of 10cFR95, App A. BTG Reg Guide 1 88 & HABH-1283 re plant staff records retention. Records from requalification program must be retained for 2 yrs after event or for operator employment. GRIMES: B. K. Assistant Director for Engineers & Projects (fre 790625). 79/06/26. BRYAND, E. Division of Reactor Operations Inspections 2pp. 22193.063
- 8402100003 FDIA request for documents prepared by Dfc of Investigation re Zack Co PERRY.R.A Affiliation Not Assigned, 83/07/01. FELTON.J. Division of Rules and Records. 1p. 22206:001.
- 8402100005 Partial response to FOIA request for documents prepared by OFc of Investigation re Zack Co Forwards App A documents. Documents also being placed in PDR. Info partially withheld (ref FOIA Exemption 6).
 FELTON, J. M. Division of Rules and Records. 83/11/20 PERRY, R. A Affiliation Not Assigned. 7pp 22206.002 24X Fiche: 50-000, 83/11/28, 8402100005.

- ---B402100012 Notifies that AT Howard will assume position of document control supervisor GA training rept encl CALKING, DE Zack Co B1/11/05 Zack Co 2pp 22206 011
- ---8402100018 Affidavit of C Grant re problems of Zack Co in maintaining traceability of equipment supplied to nuclear power plants Related info ancl
 GRANT, C Government Accountability Project 82/07/23, 1760 QRANT.C Government Accountability Project 82/07/23, 17pp 22206:059
- --B402100026 Requests policy statements or regulations re personnel allowed during course of various insps or investigations & length of time Commission required to retain documents VANDE KAUTER, B Harvey L Walner & Associates, Ltd 82/09/08 FOSTER, J Region 3, Office of Director 6p 22206.089
- --B402100030 Rev 1 to Section 7 of GA manual for document control # Zack Co. 77/03/01. 9pp 22206.091
- -8402100036 Rev 1 to Section 9 of GA manual for mat1 control Related info encl ro enci Zack Co 77/03/01, 24pp, 22206[,]102
- --8402100040 Forwards audit trend analysis rept Vendor requested to respond to trends identified within summary & conclusion, indicating corrective actions to prevent reoccurrence Dates when corrective actions will be completed also requested QUAKA, T. E. Commonwealth Edison Co. QAL 2753. 80/08/20, THUMPSCN.E. Zack Co. ip. 22206; 124. 24X Ficher 50-000,83/i1/28,8402100003. 8402100005
- -- HA02100042 B0-402 42:00-042 00-402 *Audit Trend Analysis." Related info enci * Commonwealth Edison Co 80/08/18 153pp. 22206 127. 24X Fiche: 50-000, 83/11/28, 8402100005
- --B402100045 Informs that documents provided by recipient copied by Region III ofcs.Original documents not retained List of copies forwarded Related info encl. FORTER, J E Office of Investigation 82/08/04, HOWARD, A T. Affiliation Not Assigned. 20pp. 22206-280.
- 8402100447 Responds to FOIA request for documents re NRC investigation of burst steam pipe accident Forwards documents Math also available in PDR FELTON, J. M. Division of Rules and Records 83/11/30. GARDE, B P Covernment Accountability Project. 1p 22212:304. 24X Fiche: 50-280.83/11/30.8402100447.
- --8402100449 Headquarters operations officer log from 831015-16 re fatal injury due to high pressure feedwater drainline rupture w NRC No Datailed Affiliation Oiven. 83/10/15. 3pp 22212:305 24X Fiche:50-280.83/11/30.8402100447
- 8402100453 Responds to FOIA request for Contract NRC-33-84-380 Contract MORITOGOUS RESPONSE TO THE STATE OF T
- 8402100434 FOIA request for Contract NRC-33-84-380. FISHER.W.C. Rehab Group, Inc. NRC-33-84-380 E of Contracts. ip. 22212'301. 93/11/22. Division
- 8402100438 Responds to FOIA request for SECY-83-249 to be placed in PDR, SECY-83-249 available in PDR FELTON, J.M. Division of Rules and Records. 83/11/30. GRABER: L D. NUB Corp. 1p. 22210:336
- B402100439 FDIA request for SECY-83-249 to be placed in PDR.
 ORABER, L. D. NVB Corp. CD-18-83-327. 83/11/10. Division of Rules and Records. 1p. 22210, 337
- 8402100460 FOIA request for State of 8D Governor Janklow 831017 ltr & NRC response. PAY.D. Affiliation Not Assigned. 83/11/08. Administration. 1p. 22212:251 Office of
- 8402100461 Responds to FOIA request for Governor Janklow 831017 ltr & NRC response Forwards lirs. FELTON, J. H. Division of Rules and Records, 83/11/30 PAY, D Affiliation Not Assigned. 1p. 22212:252

- --8402100464 Requests info re State of SD adopting plan to comply w/Low Level Radwaste Policy Act State of SD legislature investigating available options JANKLOH.H J South Dakota. State of B3/10/19 KERR.G W Office of State Programs. Director 3pp 22212 233
- -8402100465 forwards response to 831019 request for info re low level radwaste compact formation NUREO-0762, describing state role in radwaste regulation per Low Level Radwaste Policy Act of 1980, encl W/a NUREO KERR, G W Office of State Programs. Director 83/11/16 JANKLOW, H J South Dakota, State of 5pp 22212 256
- 8402130004 Further response to FDIA request for four categories of documents Forwards App B & D documents Documents also available in PDR FELTON.J.M Division of Rules and Records 83/12/30 SHOLLY, 8 C Union of Concerned Scientists 2pp 22238 017
- --8311210028 Discusses status of Contract FIN A-3268. "Protective Action Decisionmaking " Funds shifted from FIN A-3271 to assist in completion of project Informal presentation of results due 840102 BADIOZ. NORBERO, J. A. Human Factors & Bafeguards Branch FIN A-326B 83/11/02 PERKINS.X Incident Response Branch 2pp 2223
- --B311210544 Notification of B31121 meeting in Rockville.MD to review BNL contract of protective action decisionmaking for nuclear power plant accidents MCGUIRE.S A Human Factors & Safeguards Branch 83/11/07 BLOND,R Reactor Risk Branch 2pp 22238 056
- --B402130006 Discusses desire to send staff to Taiwan central emergency response ctr which has data link-type connections w/four operating BMRs which will be connected to two PMRs R Barnero recently visted ctr
 LAFLEUR, J.D. Office of International Programs, Director
 83/11/16 JORDAN,E L. Division of Emergency Preparedness &
 Engineering Response (Post 830103) 1p. 22238 020.
- --8402130008 "Estimation of Source Terms for Severe Accidents in LWRs "
 BERNERO, R M Accident Source Term Program Office 83/12/30
 25pp 22238, 021
- --8402130009 Requests BNL authorization to execute FIN A-3268-3, "Protective Action Decisionmaking" & FIN A-3271-3, "Emergency Action Levels" GGLLER, K. R. Division of Facility Operations. FIN A-3268-3 83/08/30 BCHMELLER, D Energy, Dept of 1p 22238,046
- --B402i300iB Project & budget proposal for NRC work "Protective Action Declaramenting " Decisionmaking "
 KOUTS,H J , KATO,W.Y., PRATT,T. Brookhaven National Laboratory.
 FIN A-3268 83/10/25 7pp 22238 064
- --8402130021 "Protective Action Decisionmaking," program review
 * Brookhavan National Laboratory. FIN A-3268 83/11/21
 No Detailed Affiliation Given 22pp 22238:071 NRC -
- --B402130236 Btd Work Order 60-83-374* "Protection Action Decisionmaking" & "Emergency Action Levels," issued to BML GOLLER, K.R. Division of Facility Operations. FIN A-3268-3 60-83-374. 83/08/30 7pp. 22238 047.
- B402130005 Appeals denial of FDIA request for documents re R Gunderson & senior Bechtel manager allegations of electrical problems & deficiencies at facilities.
 YOUNGHIC: BERNABELL Government Accountability Project BUN05/13, NRC No Detailed Affiliation Given. 2pp. 22238.093 24X Fiche 50-528.83/05/13,8402130005.
- 8402130007 Responds to appeal re denial of FOIA request for documents concerning investigation of allegations at facility Forwards App A documents. Documents completely & partially withheld (ref FOIA Exemptions 7 & 4).

 CHILK, B, J Office of the Secretary of the Commission, B3/11/10.
 BERNABEI, L Government Accountability Project 44pp 22238 100 24X Fichs 50-528,83/11/10,8402130007.
- --8304040543 Forwards list of items currently under insp/investigation which have recently been closed out, in response to 830318 memo No allegations should impact plant safety or current schedule for initial fuel loading DIRCKS,W J Office of the Executive Director for Operations. 83/03/29. CHILK,S.J. Office of the Bacretary of the Commission. 3pp. 22240:125 24x Fiche 50-528.83/11/10,8402130007.

454

NONDOCKETED ITEMS

- --B402130010 Discusses 820525 Bechtel alleger telcom re allegations concerning defective electrical & const items at facilities Specific defects listed Related info encl SHACKLETON, O C Region 5. Office of Director B3/03/18 STERNBERG. DM Region 5. Office of Director 7pp 22238 144 24X Fiche 50-528.83/11/10.8402130007
- --8402130012 Lists three allegations of immediate concern currently being investigated under Cases 5-82-004,009 & 011 Related info enci SHACKLETON.O C Region 9, Office of Director 63/03/29 DEMEY, L S Office of the Executive Legal Director 189p 2223B IS1 24X Fiche 50-528,83/11/10,8402130007
- --8402130014 Submits info re 820525 allegations concerning electrical const deficiencies Portions deleted SHACKLETON O C NRC No Detailed Affiliation Given 82/05/27 BISHOP, T W NRC No Detailed Affiliation Given 1p 22238 169 24X Fiche 50-528 83/11/10 8402130007
- --8402130016 Submits info re 820326 allegations concerning electrical const deficiencies
 SHACKLETON,O C. NRC No Detailed Affiliation Given 82/05/27
 BISHOP,T W NRC No Detailed Affiliation Given 3pp 22238 170
 24X Fiche 50-528.83/11/10.8402130007
- --8402130019 Handwritten notes re death threats against alleger concerning const deficiencies Related info encl
 SHACKLETON, O C NRC No Detailed Apriliation Given 82/05/24
 2pp 22236 187 24% Fiche 50-528,83/11/10,8402130007
- --8402130024 Affidavit of RD Ounderson re allegations concerning electrical const deficiencies Related info encl OUNDERSON R D Bechtel Corp 83/11/10 51pp 22238 190 24X Fiche 50-528,83/11/10,8402130007
- --8402130030 Forwards recipient signed, sworn statement re 820602 allegations Results will be provided following investigation completion Related info entl SHACKLEYON.O C NRC No Betailed Affiliation Given 82/06/09 GUNDERSON.R D Affiliation Not Assigned ip 22238 241 24X Fichs 50-328,83/11/10,8402130007
- --8402130044 Discusses 820325 telcon from anonymous caller allsging defective HPSI & LPSI sys at plant TEDFORD, C F Arizona, State of 82/03/26 VORDERSRUEOGEN Region 5. Office of Director 19 22238 242 24X Fiche.50-528,83/11/10,8402130007
- --8402130047 Discusses allegations re Blectrical const deficiencies at facilities Case under investigation BHACKLETON G C. Region 5, Office of Director 82/07/22. NRC NO Detailed Affiliation Oiven 2pp. 22238 246 24% Fichs 50-528,83/11/10,8402130007.
- --8402130033 "Investigations Status Rept " Related info encl. # Office of Investigation. 82/10/19 32pp 22238 254 24X Fiche 50-528,83/11/10,8402130007
- --B402130108 Forwards R Gunderson & W Royce affidavits & supporting arbibits re allegations concerning const deficiencies at facilities Problems evidenced not adequately addressed GARDE, B P . CLARK, L . BERNABEI, L Government Accountability Project. 83/02/28 FORTUNAR. Office of Investigation. 2pp 22239 301 24X Fiche 50-528,83/11/10,8402130007
- --B402130122 Informs of L Bernabel intention to make contention over RD Gunderson affidavit re allegations concerning facility const deficiencies. Imap & investigations should be completed immediately
 SHACKLETON.D C Region 5. Office of Director 83/03/29
 STERNBERG.D M Region 5. Office of Director 1p. 22238-305 24X Fichs 80-328,83/11/10,8402130007.
- --8402130127 Informs that RD Gunderson Allegations that have not been investigated/inspected not presently within Ofc of Investigations purview Region V insp requested SHACKLETON, O. C. Region 5. Office of Director 83/03/30. SIERNBERG, D. M. Region 5. Office of Director. 2pp 22238 306 24X Fiche 50-528, 83/11/10, 8402130007.
- --B402130134 Informs that WR Royce allegation does not come under Ofc of Investigations jurisdiction. Allegations submitted to Region V for followup. Related info anci.

 BMACKLETON.O.C. Region 5, Office of Director 83/03/30, STERNBERG.D M Region 5, Office of Director 242pp 22238, 308, 24% Fiche: 50-528, 83/11/10, 8402130007.
- --8402130143 Rev 0 to Procedure 909A-02711, "Temporary Mods." Related info enci OARDNER.B J. Arizona Public Service Co 82/05/10. 43pp. 22239 190. 24X Fiche.50-528.83/11/10.8402130007

- --8402130150 Confirms telcon re AMP terminal markings Markings dictable by one or two approval agencies UL (UL486A) & UB Military (MIL-1-7928) Related info encl EISTER: W M AMP, Inc. 82/09/23 SHACKLETON, O C Region 5. Office of Director 173pp 22239 233
- --8402130168 Forwards documents loaned from recipient re investigative rept concerning radiographic operations Related info enc1 SHACKLETON 0 C NRC No Detailed Affiliation Given Affiliation Not Assigned 31pp 22240 047 24X Fiche 50-528,83/11/10.8402130007
- --8402130174 "Const Insp Planning for Concrete Replacement " Relate Miseral
 * Bechtel Corp JOB 10407 79/12/04 11pp 22240.089 24%
 Fiche 50-528,83/11/10,8402130007
- --8402130182 SECY-83-055
 Provides Ofc of Policy Evaluation immediate effectiveness analysis of Palo Verde licensing board decision for Unit 1 Related info encl
 ZERBE, J E Office of Policy Evaluations 83/02/15 25pp.
 22240 100 24X Fiche 50-528,83/11/10.8402130007
- --8402130211 Staff requirements memo re 830315 discussion/possible vation contested issues in Palo Verde full power proceeding.

 HAYEB, B B Office of Investigation 83/03/25 CHILK, B J Office of the Secretary of the Commission 2pp 22240:128 24X Fiche 50-528,83/11/10,8402130007
- --B402130219 Handwritten notes re allegations concerning facility defects Related info and
 + Region 5, Office of Director 82/05/25 15pp 22240 [41, 24] Fiche 50-528.83/11/10.8402130007
- --8402190221 Discusses allegations from anonymous allegar from Bachtel re electrical installations Related info anci BHACKLETON:0 C Region 5. Office of Director. 82/07/22. Region 5. Office of Director 46pp 22240 156 24X Fiche: 50-528,83/11/10,8402130007
- --8402:30227 Discusses exam of motor control ctr Unit 2-E-NHN-H0317 identified in allegations as having abnormally small cables. Handwritten Related info encl SHACKLETON.O.C. NRC No Detailed Affiliation Given, 82/08/25, NRC No Detailed Affiliation Given 8pp 22240 203.
- --8402130232 Forwards documents discussed during 820707 telcon reallegation that wiring separation in main control panel violates code Related into encl.

 BHACKLETON.O.C Region 5. Office of Director 82/07/09 MORRISON.J Affiliation Not Assigned App 22240:213. 24% Fiche 50-528,83/11/10.8402130007.
- --8402130237 Bubmits Inquiry Rept G5-82-003 re WR Royce allegations concerning startup program Related info encl.

 SHACKLETON.O C Region 5. Office of Director 82/11/18. Region 5. Office of Director 7pp 22240 219 24X Fiche: 50-528, 83/11/10,8402130007
- --8402130241 Discusses WR Royce allegations re startup program.
 Handwritten Related info encl
 BHACKLETON 0 C Region 5, Office of Director 82/11/17. YDUNO.T
 Region 5, Office of Director 14pp. 22240'235 24X
 Fichs 50-528,83/11/10,8402130007
- --8402130250 Summary of investigation re PL Hourihan allegation≤ concerning electrical work Handwritten Related info encl SHAGKLETON, O C Region 5, Office of Director 82/05/24, 37pp. 22240 252. 24X Fiche 50-528,83/11/10,8402130007
- --8402130262 Discusses anonymous allegations from Bechtel employee re alectrical installations 8HACKLETON.O C Office of Investigation. 82/07/22 Office of Investigation. 3pp. 22240.328 24X Fiche.50-528,83/11/10, 8402130007.
- --8402130270 Transcript of closed Commission 830315 meeting in Hashington, DC re discussion/possible vote on contested issues in full power proceeding. Pp 1-57, Portions deleted * Commissioners 83/03/15 3Epp. 22240,331 24X Fichs 50-528,83/11/10,8402(30007.
- --8304040543 Forwards list of items currently under insp/investigation which have recently been closed out in response to 830318 memo. No allegations should impact plant safety or current scheduls for initial fuel loading DIRCKS.W J. Diffice of the Executive Director for Operations. 83703/29 CHILK.B J. Diffice of the Secretary of the Commission 3pp 22240.125. 24X Fichs.50-528,83/11/10,8402130007

1

- --B402130010 Discusses 820525 Bechtel alleger telcon re allegations concerning defective electrical & const items at facilities Specific defects listed Related info encl BHACKLETON, O C Region 5, Office of Director B3/03/18 STERNBERG, D M Region 5, Office of Director 7pp 22238 144 24X Fiche 50-528, B3/11/10, 8402130007
- ---B402130012 Lists three allegations of immediate concern, currently being investigated under Cases 5-82-006,007 & 011 Related info enci SHACKLETON, O C Region 5, Office of Director B3/03/27 DEMEY, L B Office of the Executive Legal Director 18pp 22238-151 24% Fiche 50-526,83/11/10.8402130007
- ---B402130014 Submits info re B20525 allegations concerning electrical const deficiencies Portions deleted SHACKLETON,O C NRC No Detailed Affiliation Given B18HOP,T.W NRC No Detailed Affiliation Given 1p 22238 169 24X Fiche 50-528, 83/11/10, 8402130007
- --B402130016 Bubmits info re B20526 allegations concerning electrical const deficiencies SHACKLETON.O.C NRC No Detailed Affiliation Given 82/05/27 BIBMOP.T.W. NRC No Detailed Affiliation Given. 3pp. 22238.176 24X Fiche.50-528.83/11/10.8402130007
- ---BA02130024 Afridavit of RD Quaderson re allegations concerning electrical const deficiencies. Related info encl QUADERSON, R. D. Bechtel Corp. B3/11/10 51pp 22238.190 24X Fiche. 50-528, B3/11/10, 8402130007
- ----B402130030 Forwards recipient signed sworn statement re 820602 allegations, Results will be provided following investigation completion. Related info encl.

 BHACKLETON.O.C. NRC No Detailed Affiliation Given, 82/06/05

 GUNDERSON.R.D. Affiliation Not Assigned 1p 22238, 241 24)

 Fiche. 50-528, 89/11/10, 8402130007

- --8402130053 "Investigations Status Rept." Related info encl # Office of Investigation. 82/10/19 92pp 22238, 254. 24X Fiche: 50-528, 83/11/10, 8402130007.
- --8402130108 Forwards R Gunderson & W Royce affidavits & supporting arhibits re allegations concerning const deficiencies at facilities. Problems evidenced not adequately addressed. QANDE, B P , CLARK, L., BERNABEI, L. Government Accountability Project. 83/02/28 FORTUNA, R. Office of Investigation. 2pp. 22238:301. 24X Fichs. 50-528,83/11/10.8402130007
- --B402130127 Informs that RD Gunderson allegations that have not been investigated/inspected not presently within Ofc of Investigations purview. Region V insp requested SMACKLETON.O.C. Region 5, Office of Director. 83/03/30. STERNBERO, D H Region 5, Office of Director. 2pp. 22238.306. 24X Fichs: 50-528.83/11/10,8402130007
- --B402130134 Informs that WR Royce allegation does not come under Ofc of Investigations jurisdiction. Allegations submitted to Region V for followup Related info encl.
 BHACKLETON.O.C. Region 5, Office of Director. B3/03/30.
 BTERNBERG.D M. Region 5, Office of Director. 242pp. 22238:308
 24% Fiche: 50-528,83/11/10,8402130007
- --8402130143 Rev O to Procedure 909A-0ZZII, "Temporary Mods." Related info encl. QARDNER, B. J. Arizona Public Service Co. 82/05/10, 43pp. 22239.190, 24X Fiche: 50-528,83/11/10,8402130007.

- --8402130150 Confirms telcon re AMP terminal markings Markings dictated by one or two approval agencies UL (UL486A) & US Military (MIL-T-7928) Related info encl EISEER,W M AMP, Inc. 82/09/23 SHACKLETON,O C Region 5, Office of Director 173pp 22239 233
- --8402130168 Forwards documents loaned from recipient re investigative rept concerning radiographic operations Related info encl BHACKLETON,O C NRC - No Detailed Affiliation Given 82/06/25 Affiliation Npt Assigned 31pp 22240 047 24X Fiche 50-528,83/11/10,8402130007
- --8402130174 "Const Insp Planning for Concrete Replacement " Related info encl * Bechtel Corp. JDB 10407 79/12/04 11pp 22240 089 24X Ficha 50-528,83/11/10.8402130007
- --8402130182 SECY-83-065
 Provides Ofc of Policy Evaluation immediate effectiveness analysis of Palo Verde licensing board decision for Unit i Related info encl
 ZERRE, J E Office of Policy Evaluations, 83/02/15 25pp 22240 100 24% Fiche 50-528,83/11/10.8402130007
- --8402130211 Staff requirements memo re 830315 discussion/possible vote on contested issues in Palo Verde full power proceeding HAYES; B. B. Office of Investigation 83/03/25 CHILK: 8 J Office of the Becretary of the Commission 2pp 22240 128 24X Fichs: 50-528, 83/11/10, 8402130007
- ---8402130217 Handwritten notes re allegations concerning facility defects Related info encl ** Region 5, Office of Director 82/05/25 15pp. 22240 141 24X Fiche: 50-528.83/11/10,8402130007
- --8402130221 Discusses allegations from anonymous alleger from Bachtel re electrical installations Related info encl SHACKLETUN.O.C. Region 5, Office of Director. 82/07/22 Region 5, Office of Director. 46pp 22240 156 24X Fichs: 30-528, 83/11/10, 8402130007
- --B402130227 Discusses exam of motor control ctr Unit 2-E-NHN-M0317 identified in allegations as having abnormally small cables Handwritten Related info encl BHACKLETUN.0. NRC No Detailed Affiliation Given B2/08/25 NRC No Detailed Affiliation Given Bpp 22240 203
- --B402130232 Forwards documents discussed during 820707 telcon re allegation that wiring separation in main control panel violates code Related info entl SHACKLETON.O.C. Region 5, Office of Director 82/07/09. MORRISON.J. Affiliation Not Assigned 6pp. 22240 213. 24X Fiche. 50-528, B3/11/10, 8402130007
- --8402130237 Submits Inquiry Rept 05-82-003 re WR Royce allegations concerning startup program Related info encl BHACKLETON.O C Region 5, Office of Director 82/11/18 Region 5, Office of Director 82/11/18 Region 5, Office of Director 82/11/18 Region 83/11/10,8402130007
- --8402130241 Discusses WR Royce allegations re startup program.
 Handwrittem, Related info enci.
 BHACKLEYON.O C. Region 5. Office of Director 82/11/17 YOUND, T
 Region 5. Office of Director 14pp 22240:235 24X
 Fiche. 50-528, 83/11/10, 8402130007.
- --B402130250 Summary of investigation re PL Hourism allegations concerning electrical work. Handwritten. Related info encl BHACKLETON. D. C. Region 5, Office of Director 82/05/24, 37pp 22240 252, 24% Fiche: 50-528,83/11/10,8402130007
- --B402130270 Transcript of closed Commission B30315 meeting in Washington, DC re discussion/possible vote on contested issues in full power proceeding. Pp 1-57. Portions deleted * Commissioners 83/03/15. 32pp. 22240, 331. 24X Fichs: 50-528, B3/11/10, B402130007
- 8402130011 FDIA request for two categories of documents re IDCOR program BHOLLY, 8 C. Union of Concerned Scientists, 83/11/28, FELTON, J. M Division of Rules and Records 2pp 22282,002

- 8402130013 Responds to FOIA request for two categories of documents re IDCOR program Forwards App A & B documents Documents placed in PDR
 - FELTON, J M Division of Rules and Records 83/12/2) SHOLLY, S C Union of Concerned Scientists 5pp 22282 004 24x Fiche: 80-000, 83/12/21, 8402130013
- --8307210350 Discusses approach to addressing ateam spike containment loading issue in severe accident sequence, raised at BARP Senior Review Group 830607 masting SPEIS.TP Division of Safety Technology 83/07/05 RDSS.D F D
- --B309260011 Bummary of B30807-12 site visit & IDCOR meeting in Chicago, IL re status of data collection activity & containment capability
 BA9CHI.0 Equipment Gualification Branch FIN A-6495 B3/09/12
 Equipment Gualification Branch 5pp 22282 203 24X
 Fiche 50-000.83/12/21,8402130013
- --8310030612 Provides guidance re containment leak area estimata responsibilities for participating groups Study completion data remains end of Nov 1983 BAOCHI.G Equipment Gualification Branch 83/09/22 BURR.T EG&G, Inc. 6pp. 22202 197
- --8310210339 Forwards, for review & comment, second draft "Containment Performance Working Group Containment Leak Rate Estimates " NOONAN. V 8 Equipment Qualification Branch 83/10/13 VOLLMER, R Office of Nuclear Reactor Regulation, Director 109pp 22282 064
- --8310240142 Forwards input for Commission paper on severs accident issues. Comments by 831021 requested NOONAN.Y S Equipment Gualification Branch 83/10/14. MALARA, J C Regulatory Analysis Branch. 17pp 22282.180.
- --B311150394 Provides estimates for containment response under severe accident conditions.per RM Bernero B30312 request.Research needed to fund both E960 & BM. technical assistance contracts to prevent work stoppage.

 VOLLMERIR H Division of Engineering FIN A-3735 B3/11/07 ROSS.D F Office of Nuclear Regulatory Research. Director. 2pp 22282 208
- --8311230199 Forwards tone for R Matteon 831118 ACRS bristing & 831121 1000R meeting re severe accident policy status DENTON. H R Office of Nuclear Reactor Regulation, Director. 83/11/09 DIRCKB, W J Office of the Executive Director for Operations 2pp. 22282 338
- --8311300146 Requests submittal of revised input to severe accident issue papers by 831114, per DF Ross 831028 memo Comments should be submitted to 9 Bagchi of Equipment Gualification Branch. VOLLMEA, R H Division of Engineering 83/11/07 NOONAN.V. Equipment Gualification Branch 1p. 22282:210.
 - 8311300173 Discusses 830915 request that draft position papers be prepared for technical issues important to severe accident decisions for existing nuclear power plants Bummary of usakmesses needing correction or actions to avoid encl. ROBS: D Office of Nuclear Regulatory Research, Director. 83/10/28. BASETT, D. Office of Nuclear Regulatory Research, Director. 8pp 22282;211
- --B312050175 Comments on second draft of containment leak rate estimate rept. Rept appears to dismiss penetration failure due to temp effects as mode of early containment failure.

 SFEIS.T P Division of Safety Technology 83/11/23, NOONAN, V Division of Licensing, 1p. 22282.063
- --8312090072 Advises of 831129-30 & 1201 meetings w/IDCOR in Harpørs Ferry.WV to discuss accident phenomenology & containment loading Agenda and. SPEIB.T.P Division of Bafety Technology 83/11/14. TMEOFANOUS,T Purdue Univ.
 - 33ig190055 Summarizes comments re outline for source term rept, NUREG-0756, Chapter IV should include results of Containment Behavior Group & Containment Loading Group activities. Section on generalization of results should be added. NOONÁN.V.S. Equipment Qualification Branch. 83/11/28 /OLLMER.R.H. Division of Engineering. 3pp. 82282:173.
 - 2190179 Forwards revised outline incorporating comments received to sto for NUREO-0956: "Reassessment of Accident Bource Term aluation Methods to Assumptions " Div of Risk Analysis sistance required Production schedule encl INERO,R M Accident Bource Term Program Office, 83/11/02, P Review Group 4pp. 22282,176,

- --8402130017 Summarizes work re containment behavior in revised surgeterm estimates Directors advised to provide representatives w/containment behavior group Agenda listed for group H/o encl
 BERNERO, R M. Accident Source Term Program Office 83/06/15
 APLOTTICA A. Division of Engineering Tachnology BARRETT, D S
 - enci BERNERO, R M Accident Source Term Program Office 83/06/15 ARLOTTO, G A Division of Engineering Technology BAGBETT, D E. Division of Accident Evaluation (Pre 840101) ERNST, H L. Division of Risk Analysis 3pp 22282 022
- --8402130020 Submits desired format & schedule to follow re containent pailure models for severe accident source term estimates Source term effort calls for availability of containment response model by 631101 Questionnaire & Table 1 encl BERNERO, R M Accident Source Term Program Office. 83/03/12 VOLLMER, R Division of Engineering 4pp 22282-025
- ~~8402130022 Forwards questionnaire for containment loads, to be completed by 830627. Working group objectives & schedule listed TELFORD, J L Office of Nuclear Regulatory Research, Director, 83706/02 DERGENON, K, BERMAN, M Sandia Laboratories BOFE, H Los Alamos Scientific Laboratory 7pp, 22282 029
- --8402130025 Forwards comments on issue papers Technical issue into paper re potential for basemat penetration encl DENNINO.R.S. Battelle Memorial Institute. Columbus Laboratories 83/11/16 Battelle Memorial Institute. Columbus Laboratories inp. 22282:036
- --8402130027 Forwards comments on issue paper re characteristics & likelihood of leakage resulting from external events.

 Comments should be used w/discretion

 DENNING, R Battelle Memorial Institute, Columbus Laboratoriss

 83/11/15 Battelle Memorial Institute, Columbus Laboratories

 4pp 22282 059
- --840213003i Forwards schedule of key NRC/industry degraded core rulemaking technical exchange meetings on severe accidents. Comments on encl agenda/schedule requested by 831209 BERNERO, R. M. Accident Source Term Program Office. 83/11/25 Accident Source Term Program Office 6pp. 22282:047.
- ~~8402130033 Industry degraded core rulemaking (IDCOR) Bubtwak 3.3, "Eplaction of Dominant Sequences Update," final rept. * Energy: Inc 83/06/14 100pp 22286 097.
- --8402130036 Technical Rept 12.1, "Hydrogen Generation During Severe Core Damage Sequences." HENRY,R E Fauske & Associates, Inc BAKER,L Argonne National Laboratory, 83/06/30 115pp 22286:224
- --B402130043 "Hydrogen Distribution in Reactor Containment Bldgs (Subtask 12.1)." final rept.Vol i project overview HAUQH.J J. THOMPSON.L. B. Electric Power Research Institute. CLAYBROOK. S. H., Westinghouse Electric Corp. B3/04/30. 600pp 22286 340
- --8402130034 Forwards draft feasibility study for containment perforant under severe accident conditions for large dry PWR. In preparation for 831202 meeting. Proposed aganda encl ARLOTTO, Q.A. Division of Engineering Technology 83/11/21 BUHL-A R. Technology for Energy Corp. 3pp. 22282, 219. 24X Fiche 50-000, 83/12/21, 8402130013
- --8402130057 Submits draft info re process for closure of technical issues
 BUHL-A R Technology for Energy Corp 83/11/23, MATTBON.R.,
 ROSS.D. NRC No Detailed Affiliation Given 3pp. 22282:335
- --8402130060 Technical Rept 14.1B, "Key Phenomenological Hodels for Assessing Nonexplosive Steam Generation Rates," # Fauska & Associates, Inc 83/06/30, 116pp. #2289: 259.
- ---8402130064 Summary of industry degraded core rulemaking (IDCOR) 830512 info meeting w/Tschnology for Emergy Corp & EPRI in Rockville.MD re IDCOR planned product & NRC comments on planned product EABLEY,P. Accident Evaluation Branch. 83/05/18. HULMAN,L. 9 Accident Evaluation Branch. 1p 22283,033
- --B40213006B Forwards comments on Issue 1 3.6 re characteristics & likelihood of leakage resulting from internal missiles.

 BENNING.R. S. Battelle Memorial Institute, Columbus Laboratories B3/11/15 Battelle Memorial Institute, Columbus Laboratories 4pp. 22283 034
- --8402130070 "Analysis of In-Vessel Core Helt Progression (Subtask 15 i), Vol 1:Phenomenological & Modeling Background for PWR & BWR Core Heatup Codes," final rept. THOMAS, O. R., STUART, R., SEMAL, 9 R. Electric Power Research Institute 83/03/31. 87pp 22270:011.

- --8402130072 Forwards revised list of severe accident issue paper assignments proposed in 830915 memo Changes reflect discussions & agreements among NRC issue area leaders MALARO.J C Division of Risk Analysis 83709722 ROS8.D NRC No Detailed Affiliation Given 5pp 22283 038
- ---B402130073 "Assessment of Existing Data on Zirconium Oxidation Under Hypothetical Accident Conditions in LWRs " BAKER.L Argonne National Laboratory 83/12/21 118pp 22284:176.
- ---B402130077 Technical Rept 2 1, "Ground Rules for Industry Degraded Core Rulemaking Program " FONTANA: M Technology for Energy Corp 82/04/30 139pp 82284-294.
- --8402130080 Technical Rept 3 i. "Define Initial Likely Sequences"

 Technology for Energy Corp 82/06/30 150pp 22285 071
- --B4021300B1 "Analysis of In-Vessel Core Melt Progression (Subtask 15 1), Vol II User Manual & Modeling Datails for PMR Core Heatup Code," final rept, HAN.T Y, NAKAYAMA,P I Jaycor STUART,R 0 Electric Power Research Institute 83/06/30 136pp 22290 098.
- --8402130083 IDCOR Subtask 3 2, "Assess Dominant Sequences "
 * Energy, Inc 83/12/21, 200pp 22285 215
- --8402130089 "Analysis of In-Vessel Core Helt Progression (Bubtask 15 1). Vol III: User Hanual & Modeling Details for BWR Core Heatup Code." final rept OILLIB.J.C. B Levy, Inc. 83/06/30. 90pp 22290 233.
- ---8402130097 "Analysis of In-Vessi Core Meit Progression (Subtask 15 1), Vol IV' User Manual & Modeling Details for Fission Product Release & Transport Code: " final rept RINSHAM, M. R., HAN, T. Y., NAKAYAMA, P. I. Jaycor 83/06/30 134pp 22290: 319
- --8402130103 Technical Rept 15 1A, "In-Vessel Core Melt Progression Fhenomena." - Fauske & Associates, Inc. 83/07/31 76pp 22291:088
- --E402130107 Technical Rept 15.2A, "Effects of Hypothatical Core Melt Accident on PMR Vessel M/Top-Entry Instruments " ANDERSON, L. E. Electric Power Research Institute 83/06/30, 114pp. 2227:1:64.
- --8402:30115 Forwards final rept on industry degraded core rulemaking Subtack 15.3; "Core-Concrete Interactions," for comments. HENRY,R.E. Fauste & Associates, Inc. 83/07/11 FULLER.E.L. Technology for Energy Corp. 1p. 22291-269
- ---B402130117 Industry degraded core rulemaking Subtask 13,3,
 "Core-Concrete Interactions," final rept
 + Fauske & Associates, Inc. FAI/83-11, 83/03/31, 112pp
 22271:270
- --8402130131 Technical Rept 14.1A, "Key Phenomenological Models for Assessing Explosive Steam Generation Rates " HERRY, R.E., FAUSKE, H. K., HUTCHERSON, M N Fauske & Associates, Inc 83706/30. 154pp 22292:015.
- --8402130137 Technical Rept 15.28, "Debris Coolability, Vessel Fenetration & Debris Dispersal "
 # Fauske & Associates, Inc. 83/08/31, 120pp 22292 163.
- --8402140173 Forwards final rept for Bubtask 3.3, "Selection of Dominant Sequences Update."
 YOUNG, J. Energy, Inc. WCO-187-83, 83/06/14. ABBELIN, 8.V. Technology for Energy Corp., 1p. 22282,001.
- 8402130433 Responds to FOIA request for most recent NRC annual rept Rept available through NRO sales program, Forwards 1982 annual rept. W/o encl. FELTON, J. M. Division of Rules and Records. 83/12/14. 9099IN, A Affiliation Not Assigned. 1p. 22216.137.
- B4D2130436 FDIA request for most recent NRC annual rept GD9QIN.A. Affiliation Not Assigned B3/12/10 NRC - No Detailed Affiliation Given. 1p. 22216:138
- 8402130473 FOIA request for SECYs 83-268,271,278,281,299,305,306 & 307, on behalf of UCB. HE188,E,R. Harmon & Heiss. 83/08/15 FELTON,J. Division of Rules and Records. 1p. 22237:219.

- 8402130498 Responds to FOIA request for SECYs 83-268,271,278,281,299,305,306 & 307 Forwards SECY 83-271,83-278 & portions of five other SECYs as listed on App A Info partially withheld (ref Exemptions 3 & 7)
 FELTON. J M Division of Rules and Records 83/11/28 WE188.E R Harmon & Weiss 4pp 82237 220 24% Fiche 50-000,83/11/28,8402130498
- --8307060279 Requests, per County Resolution 302, immediate suspension of licenses based on FEMA rept findings Resolution encl PARRIS.M Rockland County, NY 83/05/13 Office of Nuclear Reactor Regulation. Director 5pp. 22237:315 24X Ficha 50-000,83/11/28,8402130498
- --8307190353 Forwards Director's Decision 83-10 denying Rockland County 830409 2 206 request for immediate suspension of operations at facilities DEYOUNG.R C Director's Office. Office of Inspection and Enforcement DD-83-10 83/06/29 SCHDENBERGER, I Rockland County, NY ip 22237 320 24X Fiche 50-000,83/11/28,8402130498
- --8307190358 Director's Decision DD-83-10 denying Rockland County request for immediate suspension of operations at Pacilities DEVOUNG, R C Director's Office, Dffice of Inspection and Enforcement DD-83-10 83/06/29 2pp. 22237 321 24X Fichs 50-000,83/11/28,8402130498
- ---B308030317 Responds to 830712 telcon request Util preparing employees to support staffing requirements of radiological emergency response interim plan Training scheduled for uk of 830808 BAYNE, J P Rower Authority of the State of New York JJK 63 83/07/12 KISTER, H Region 1. Office of Director 1p 22237 338 24% Fiche 50-000,83/11/28,8402130478
- --B402130529 Submits addl info to suppl 830701 ltr re voluntwers for Rockland County field emergency response activities, per 830718 request 0'100LE, J D Consolidated Edison Co of New York, Inc 83/07/19 87AROBTECKI, R Division of Project & Resident Programs, 3pp. 22237 335 24X Fiche 50-000,83/11/28,8402130498
- --E402130533 Responds to 83070B teleon request Util prepared to support exercise of "Radiciogical Emergency Response Interim Plan for Implementing Compensating Measures for Rockland County," during wk of 830808

 BAYNE.J P Power Authority of the State of New York JPE 42-83
 83/07/11 PETRONE.F Federal Emergency Management Agency, 1p
 22237:339. 24X Fiche 50-000,83/11/28,8402130498.
- --8402130538 BECY-83-305
 Recommends that transcript of Commission B30621 meeting on TMI-1 restart be withheld in entirety under Examptions 5 & 10 of Bunshine Act.
 FITZOERALD J A Office of the General Counsel 83/07/28, 1p. 22237.340 24% Fiche 50-000.83/11/28.8402130478.
- --8402130544 SECY-83-306
 Recommends that transcript of Commission 830330 meeting on pending investigations & possible enforcement action at TMI-1 be withheld in entirety under Exemptions 5 % 7 of Sunshine Act FITZGRALD, J. A. Office of the General Counsel 83/07/28, 1p. 22237:341, 24X Fiche 50-000,83/11/28,8402130498.
- --8402130549 BECY-83-307
 Recommends that transcript of Commission 830606 meeting on panding investigations at TMT-1 be withheld in entirety under Exemptions 5 & 7 of Sunshine Act FITAGERALD, J.A. Office of the General Course: 83/07/28 3pp 22237:342 24% Fiche 50-000,83/11/28,8402130498.
- 8402140015 FDIA request for all documents since 820331 re Hayward Tyler Pump Co. LODGE, B. Dallas Morning News. 83/07/27 FELTON, J.M Division of Rules and Records ip 22258:147.
- 8402140020 Further response to FOIA request for documents since 820331 re Hayward Tyler Pump Co Forwards App A documents Info also available in PDR.App B documents withheld (ref FOIA Exemption 5) FELTON.U.M Division of Rules and Records. 83/12/07 LODGE, B. Dallas Morning News 5pp. 22258: 148.

- --8402140029 Advises that response to Guestion 4 of Congressman Markey ltr to Palladino should relate only to disciplinary actions taken against employees at or above grade level of Collins & Beyfrit.per telcon w/J Parrish JACKSON, J NRC - No Detailed Affiliation Olven 83/12/07 NRC - No Detailed Affiliation Given 1p 22238 189
- --8402140033 Delegates authority to administer caths & affirmations, per Section 161c of Atomic Energy Act of 1954, in Hayward Tyler Pump Co investigation of allegations re faulty workmanship HAYNES:R C Region 1, Office of Director 82/05/03. MATAKAS,R Region 1, Office of Director 1p 22258:181.
- --8402140039 Forwards rept dtd 820323, "Inquiry into NRC Handling of Hayward Tyler Pump Co Insp/Investigation," in response to request Rept withheld (ref FDIA Exemptions 5 & 7) KAMMERER.C Office of Congressional Affairs 82/04/05, OTTINGER.R L House of Rep. Energy & Commerce 1p 22258 182
- --8402140044 Requests attendance at Eubcommittee on Oversight & Investigations 830408 hearing re NRC investigation of Hayward Tyler Pump Co Names of other members of NRC requested to attend listed MARKEY.E J House of Rep , Interior & Insular Affairs 83/03/11 PALLADING.N Commissioners 2pp 22258 183
- ~-B402140050 Suggests that NRC prepare to address other investigations & inspections in E21110.830127-28.0218 & 0317 ltms at subcommittee meeting re Hayward Tyler Pump Co allegations MARKEY.E J. House of Rep., Interior & Insular Affairs 83/05/03 PALLADING.N J. Commissioners 3pp. 22258 185
- ---8402140095 Testimony of NJ Palladino at Subcommitter on Oversight & Investigations 820620 hearing re NRC investigation into allegations concerning Hayward Tyler Pump Co PALLADINO.N J Commissioners 83/06/20 21pp. 2228
- --8402140062 Discusses Congressman Martey 830127 questions re Hayward Tyler Pump Co investigation. DFc of Investigations proposed policies on investigative & procedural guidance presently under Commission review FORTUNA, R A Office of Investigation 83/02/10, PARRIGH, R Office of the General Counsel 1p. 22258, 215.
- --8402140088 Forwards NRC investigation/insp documents & inventory of documents.Griginals or copies of several documents which form basis for findings of rept retained by NRC FORTUNA.R.A Director's Office. Office of Inspection and Enforcement 82/11/26 PARRIN.R Hayward Tyler Pump Co. 12pp 22258 216
- --8402140095 Forwards draft testimony for B30318 Markey hearing on Hagward Tyler W/o encl. SNIEZEK.J NRC - No Detailed Affiliation Given 83/03/14 REHM.T NRC - No Detailed Affiliation Given. 1p. 22238 226.
- ---8402140108 Forwards Commission testimony for 830520 Markey subcommittee hearing re Hayward Tyler Pump Co Comments requested by 830518 W/o encl KAMMERER.C. Office of Congressional Affairs. 83/05/17 PALLADING.N., GILINSKY, V., AMEARNE.J Commissioners. 1p
- --B402140119 Forwards transcript of NRC 830620 testimony before House Subcommittee on Oversight & Investigations of Committee on Interior & Insular Affairs, Comments requested by 830728.

 W/o enci
 KAMMERER, C Office of Congressional Affairs, 83/07/08, PALLADING, N, GILINSKY, V, ROBERTS, T Commissioners 2pp. 22028 220
- --8402140127 Forwards Sniezek suggested changes to Pages 21 & 28 of 830620 transcript re IE investigation/insp of Hayward Tyler Pump Co Wio encl DEYCUNG, R C Director's Office, Office of Inspection and Enforcement. 83/07/28, REHM.T. Office of the Executive Director for Operations. 1p. 22238 232,
- 8402140483 FOIA request for documents re integrity of bolts, nots & studs used in nuclear power plants, including documents in possession of NRC, repts & studies on degradation of bolts, nots & stude at PWRs caused by corrosion.

 BELL-N Nuclear Information & Resource Service 83/11/01 Office of Administration 2pp. 22257/001.
 -)2140486 Responds to FOIA request for 16 categories of documents re egradation of bolts, nuts & studs at PWRs & BWRs Forwards pp A documents. App A & B documents available in PDR. LTON, J M Division of Rules and Records. B3/12/02. BELL, N clear information & Resource Service 4pp 22257:003. 24X che:50~000.83/12/02.8402140486

- --8201800698 Discusses bolt failures in nuclear power plants.
 Investigative program recommended
 FRALEY, R. F. AGRB Advisory Committee on Reactor Safeguards
 81/10/20 DIRCKS, N. J. Office of the Executive Director for
 Operations 1p 22257 172 24X Fiche 50-000.83/12/02, 8402140486
- --8209210485 "Threaded Fastener Experience in Nuclear Power Plants '
 KOD, W H Operating Reactors Assessment Branch 82/06/30. 38pp
 22257 108 24X Fiche 50-000,83/12/02,8402140486,
- --B211060310 Advises that NRR portion of TIA-NRR-82-5, "Failed Steam Generator Manway Studs at ME Yankee & Possibly Other PHR Reactors," has been completed W/a encl EISENHUT, D. G. Division of Licensing IEB-82-02 82/10/04, STARDSTECKI, R. Division of Project & Resident Programs ip. 22237-029 24X Fiche 50-000,83/12/02,8402140486
- ~-B305140343 Discusses program action plan re-bolting degradation or failure in nuclear power plants, proposed Generic Issue 29, Improvements in design, matls, fabrication, installation & inspirecommended LIAM.B D. Materials Engineering Branch B3/04/25 VOLLMER, R X Division of Engineering Opp. 22258 079 24X Fiche 50-000, 83/12/02, 8402140486
- --8307150381 Summary of 830506 meeting w/B&W Owners Group in Bethesda. Re re issues raised by reactor vessel internal bolt failures at Rancho Beco & Crystal River. KADAMBI.N.P Operating Reactors Branch 4. 83/06/24 Operating Reactors Branch 4 38pp 22258-085 24X Fiche 50-000.83/12/02. 8402140486
- --8307180123 Summary of 830621 operating reactor events westing re-events which occurred since 830607 meeting Attendance list encl.

 MIRAGLIA,F J., Assistant Director for Safety Assessment.

 EISENHUT, D. 9 Division of Licensing. opp 22237 010 24X

 Fichs: 50~000, 83/12/02, 8402140486
- --8402140489 Submits daily highlights re 830608 plant shutdown due to excessive primary coolant leak rate of 0 07 gpm Cause of leakage at manway covers undetermined Repairs in progress. DIIANNI,D C. Operating Reactors Branch 3. 83/06/10. DENTON.H., CARTER.J., EISENHUT,D NRC No Detailed Affiliation Given 1p 22257 007 24% Fiche: 50-000.83/12/02.8402140486.
- --8402140492 Submits daily highlights re plant shutdown because of excessive primary coolant leak Cause of leaky manway covers due to insufficient torquing of head bolts that pravented proper bottoming of bolts.

 DITANNI, D. C. Operating Reactors Branch 3. 83/06/17 DENTON:H: CARTER:J. EISENHUT,D NRC No Datailed Affillation Given. Ip. 22287,009. 24X Fiche, 80-000,83/12/02:8402140486
- ~-B402140497 Discusses task interface agreement re-potential generic problem of failed steam generator manway stude at facility & possibly at other PMRs Confirmation of action ltr should be issued before restart.

 IPPOLITO, T , VOLLMER, R , NOVAK, T NRC No Detailed Affiliation Given. NRR-82-05. B2/03/19, NRC No Detailed Affiliation Given 2pp 22237-027 24X Ficher 50-000,83/12/02,8402140486
- --8402140504 Experience inforconsisting of chronological list of activities at facility & diagrams of primary manual cover stude for steam generator.

 **NRC No Detailed Affiliation Given 83/12/02 14pp 22257:031. 24X Fiche, 50-000,83/12/02,8402140486
- ---B402140516 IE-123
 "Metsilurgical, Stress & Fracture Mechanics Analyses of Cracked Steam Generator Manuay Studs From Ocones Unit 3 of Duke Power Co "BURCK, L. H. F. FOLEY, W. J. Parameter: Inc. NRC-05-80-251 NRC-IE-80/81 81/04/17 Director's Office, Office of Inspection and Enforcement 16pp. 22287:340 24X Fichs. 50-000, 83/12/02, 8402140486.
- --8402140520 IE-123 R01
 Attachment 1 to "Stress Analysis of Feiled Steam Generator Manuay Studs From Oconee Unit 3, Duke Fower Co."
 FOLEY, W J. DEAN, R S Parameter, Inc. NRC-05-80-251, NRC-IE-80/81 81/04/17, Director's Office, Office of Inspection and Enforcement, 28pp 22257:356 24X Fiche, 50-000, 83/12/02, 8402140486

; ;

- --8402140522 Discusses misuse of valve resulting in vibration & damage to valve assembly & pipe supports Bevere damage to LPCI sys injection valve related to RHR sys flow limitations IE info notice recommended
 HELTEMES.C J Director's Office 83/07/08 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) ip 22258 021
- --B402140524 Forwards LER 80-010 & LER 81-002/01 re stud corrosion # NRC - No Detailed Affiliation Given 61/05/15 NRC - No Detailed Affiliation Given 1p 22258 039 24X Fiche 50-000, B3/12/02. 8402140486
- 8402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILK.8 J Office of the Secretary of the Commission 63/12/14 Public Document Branch 1p 22281 023 24X Fiche 30-000.83/12/14, 8402160003
- --8402160007 Staff requirements memo re 830105 discussion/possible vote on order in facility proceeding in Washington DC CHILK:B J Office of the Secretary of the Commission M830105B 63701/07 0ffice of the Secretary of the Commission 1p 22281 049. 24X Fiche 50-000.83/12/14,8402160003
- --8402140008 Staff requirements memo re 830203 discussion of proposed enforcement action in Washington, DC
 CHILK, B J Office of the Secretary of the Commission MB30203
 B3/02/16 Office of the Secretary of the Commission 1p
 22281 030 24X Fiche 50-000, 83/12/14, 8402160003
- --B402160012 Staff requirements memo re B30304 discussion/possible vote on contested issues in facility full power proceeding in Washington, DC GHILK, BJ Office of the Secretary of the Commission, MB30304B B3/03/08 ZERBE, JE Office of Policy Evaluations. 1p R2281.051. R4X Fiche.50-000,83/12/14,8402160003
- --B402160015 Staff requirements memo re 830304 discussion/possible vote on ALAB-714 & ALAB-716 in Washington, DC CHILK, B. J. Office of the Secretary of the Commission. ALAB-714 B3/03/09 Office of the Secretary of the Commission. ip 22281 052 24X Fiche 50-000,83/12/14,8402160003
- --B402160019 Staff requirements memo re B30405 briefing in Washington.DC approving memorandum & order on emergency plan CHILK.B J Office of the Secretary of the Commission MB30405A B3/04/0B. PLAINE.H.H Office of the Ceneral Counsel. 1p. 22201.054. 24X Fiche 50-000.83/12/14.8402160003
- --8402i60022 Staff requirements memo re 830411 discussion/possible vote on BECY-83-ii9, proposed response to UCS petition for rubsmeting on emergency planning in Washington DC CHILK, 8 J. Office of the Secretary of the Commission MB30411. B3/04/11 PLAING, H H Office of the General Counsel, ip. 22281:055 24X Fiche 50-000, B3/12/14, 8402160003
- --8402160025 Staff requirements memo re 830415 discussion of facility order in Washington.DC
 CHILK.8 J Diffice of the Secretary of the Commission M830415A 83/074/15. Diffice of the Secretary of the Commission. 1p. 22281:056. 24X Fiche 50-000.83/12/14,8402160003
- --8402160030 Staff requirements memo re 830422 discussion & possible vote in Washington,DC on immediate effectiveness of LWA-1 CHILK.S J. Office of the Secretary of the Commission. M830422A 83/04/26. ZERBE,J.E. Office of Policy Evaluations ip 22281.037. 24X Fiche 50-000,83/12/14.8402160003.
- --B402160033 Staff requirements memo re 830504 discussion of possible enforcement action in Washington.DC CHILK.S.J. Office of the Bacretary of the Commission. M830504B. 83/05/06 DIRCKS.W.J. Office of the Executive Director for Operations. ip 22281:058. 24X Fiche.50-000.83/12/14,8402160003
- --8402160035 Staff requirements memo re 830511 review of NF8-Erwin settlement in Washington, DC CHILK, 8, J Office of the Secretary of the Commission M830511. 83/05/12 PLAINE, H Office of the General Counsel 1p 22281:059. 24X Fiche, 50-000, 83/12/14, 8402160003

- --8402160037 Staff requirements memo re 810716 discussion of draf Senator Hatfield Chairman, Subcommittee on Energy & Water Development in Washington, DC CHILK, S. J. Office of the Secretary of the Commission. M8107 81/07/20 Office of the Secretary of the Commission ip 22281 024 24X Fiche 50-000,83/12/14,8402160003
- ---8402160041 Staff requirements memo re 810727 budget session (ma Hashington.DC CHILK.S J Office of the Secretary of the Commission M8107 81/08/03 DIRCKS,W J Office of the Executive Director for Operations 1p 22281 025 24% Fiche 50-000.83/12/14.84021
- --B402160043 Staff requirements memo re B30610 discussion & vote facility order in Washington.DC CHILK, B J Office of the Secretary of the Commission M8306 B3/06/14 PLAINE.H H Office of the General Counsel 1p 22281 060 24X Fiche 50-000.83/12/14.8402160003
- --B402160047 Staff requirements memo re B30707 discussion of proc for facility review in Washington.DC CHILK.S J Office of the Secretary of the Commission H8307 83/07/08 PLAINE.H H Office of the General Counsel ZERBE Office of Policy Evaluations ip 22281 061 24X Fiche 50-000.B3/12/14.B402160303
- --8402160049 Discusses SECY-B1-470 re approval of proposed licens export low enriched U to Taiwan
 CHILK,S J Office of the Secretary of the Commission SB1-4
 B1/09/O1 DIRCKS, W J Office of the Executive Director for Operations 1p 22281 090 24% Fiche 50-000,83/12/14,84021
- --8402160050 Staff requirements memo re B10811 discussion of enfo action implementation of plant early notification sys in Washington DC HDYLE, J C. Office of the Becretary of the Commission 81/08 D1RCKS.W. J. Office of the Executive Director for Operations 22281 026 24% Fiche 50-000 83/12/14,8402160003
- --8402160052 Discusses BECY-Bi-368 re appointment of ACRB member CHILK, S.J. Office of the Bernetary of the Commission 81/09 FRALEY, R F Advisory Committee on Reactor Safeguards 22281 091 24X Fiche 50-000/83/12/14,8402160003
- --8402160055 Discusses SECY-Bi-482 re director's denial of 100FR2 relief.
 CHILK, B U Office of the Secretary of the Commission 581-481/09402 BICKHIT, L Office of the General Counsel 1p 22281.092, 24X Fiche 50-000.83/12/14.8402160003
- --8402160057 Discusses SECY-Bi-497 re proposed transfer of tunabl lasers to West Germany under 10CFR810 CHILK:8 J. Office of the Secretary of the Commission SBI-4 BI/09/03. DIRCKS: W. J. Office of the Executive Director for Operations 1p 22281 093 24X Fiche 50-000.83/12/14.84021
- --8402160060 Discusses SECY-81-484 re review of Director's Decisi DD-81-12 denying 10CFR2 206 petition CHILK:8 J. Office of the Secretary of the Commission 81/09/03 BICKHIT-L. Office of the General Counsel ip. 22281:095 24X Fiche: 50-000:83/12/14:8402160003
- --B402160064 Discusses BECY-B1-499 re proposed transfer of tunabl lasers to France. CHILK, B. J. Office of the Secretary of the Commission. S81-4 B1/09/04 DIRCKS, W. J. Office of the Executive Director for Operations. 1p. 22281-096. 24X Fiche 50-000.83/12/14,84021
- --8402160065 Staff requirements memo re 830715 discussion of poss enforcement action in Washington, DC. CHILK, B. J. Office of the Secretary of the Commission MB307 83/07/25. Office of the Secretary of the Commission lp 22281 062, 24X Fiche 50-000, 83/12/14, 8402160003
- ---B402160066 Staff requirements memo re 820415 Affirmation Session CHILK, S.J. Office of the Secretary of the Commission. ALAB-82/04/22 BICKWIT, L. Office of the General Counsel. 3pp 22281.063. 24% Fiche 50-000.83/12/14.8402160003
- --8402160067 Staff requirements memo re 810819 briefing on enforce actions in Washington, DC.

 CHILK.S J. Office of the Secretary of the Commission 81/08 DIRCKS, W.J. Office of the Executive Director for Operations CUMMINOS, J.J. Office of Inspector & Auditor ip 22281.027 Fichs: 50-000, 83/12/14, 8402160003
- --8402160070 Staff requirements memo re \$10825 briefing on pendir adjudicatory proceedings in Washington, DC CHILK, B J Office of the Secretary of the Commission. M8106 81/09/01. BICKHITLL Office of the General Counsel. ip 22281:028 24X Fichs 50-000,83/12/14,8402160003

- --8402160071 Discusses SECY-81-390. licensed fuel facility status rept.Vol
 1. Number 6. Jan 1981 jesue
 CHILK, 8 J Office of the Secretary of the Commission. S81-390.
 81/07/21 DIRCKS, W J Office of the Executive Director for
 Operations 1p 22281 068 24% Fiche 50-000.83/12/14.8402160003
- ---8402160072 Staff requirements memo to S10910 discussion of low power OL in Washington.DC
 CHILK,S J Office of the Secretary of the Commission MB10910A
 81/09/16 BICKWIT, L Office of the Ceneral Counsel | 1p
 22281-029 24X Fiche 50-000,83/12/14.8402160003
- --B402160073 Discusses SECY-B1-575 re review of ALAB-650.in matter of PBE&Q CHILK,8 J Office of the Secretary of the Commission. B81-575 B1/11/02 BICKNIT.L Office of the General Counsel. ip 22281 120 24X Fiche 50-000.83/12/14.8402160003
- --8402160074 Discusses SECY-BI-511 re approval of proposed license to export high enriched U to Federal Republic of Germany CHILK.S J Diffice of the Secretary of the Commission. 881-511 81/09/04 DIRCKS, W J. Office of the Executive Director for Operations. 1p 22281 097 24X Fiche 50-000.83/12/14.8402140003
- --8402160075 Discusses SECY-81-404 re assessment of waste retrieval alternatives
 CHILK, S. J. Office of the Secretary of the Commission S61-404
 81/07/27 DIRCKS, W. J. Office of the Executive Director for Operations 1p 22281:059 24X Fiche:50-000,83/12/14,8402160003
- ~-8402160076 Staff requirements memo re 811102 discussion of pending litigation in Hashington. DC
 CHILK: 9 Office of the Secretary of the Commission. MS11102A. 81711/03 Office of the Secretary of the Commission. ip 22281 030 24% Fiche 50-000,83/12/14,8402140003
- --8402150078 Discusses SECY-81-448 re technical assistance for design revious CHILK,8,J Office of the Secretary of the Commission 881-448 81/09/10 DIRCKS,W J Office of the Executive Director for Operations ip 22281 098. 24% Ficha 50-000,83/12/14,8402160003
- --8402160079 Staff requirements memo re 811106 discussion of TMI-1 restert in Washington, DC CHILK, 8 J Office of the Secretary of the Commission, MS11106A 81/11/09 BICKMIT, 6 Office of the General Counsel, 1p 22281 031 24X Fiche 50-000,83/12/14,8402160003
- --B4021600BI Staff requirements memo re Billio6 discussion of U mill tailings in Hashington, DC CHILK. B J Office of the Secretary of the Commission MB11106B. BI/11/09 DIRCKS, W J Office of the Executive Director for Operations 1p 22281:032 24X Fiche. 50-000, B3/j2/14, 8402160003
- --8402160092 Discusses SECY-B1-472 re borehole & shaft sealing performance criteria CHILK.8 J Office of the Secretary of the Commission 81/09/10 DIRCKS.W J. Office of the Executive Director for Operations. 1p 22281:099 24X Fiche: 50-000, 83/12/14, 8402160003
- ---8402140083 Discusses SECY-81-398. Section 208 re rept to Congress on AOs for Jan-Her 1981
 CHILK.8 J Office of the Secretary of the Commission. 81/07/24.
 DIRCKS.W J Office of the Executive Director for Operations ip 22281 072. 24X Fichs 50-000.83/12/14.8402140003.
- --8402160084 Discusses SECY-81-583 re proposed license to export natural U to EURATOM countries CHILK.S.J. Office of the Secretary of the Commission B81-583. 81/11/03 DIRCKS,W.J. Office of the Executive Director for Operations ip 22281.121. 24X Fiche 50-000.83/12/14,8402160003
- --8402160085 Staff requirements memo re diti16 discussion of 670518 memo & seismic reverification plan in Hashington, DC.
 CMILK, 8 J. Office of the Secretary of the Commission Meliliab Bi/1/20 Office of the Secretary of the Commission lp.
 R2281 033 24X Fiche, 50-000, 83/12/14, 8402160003.
- ---8402160086 Discusses SECY-81-480 re final GAO rept entitled, "Improvements in NRC Office of Inspector & Auditor," dtd 810709.
 CHILK, 8 J. Dffice of the Becretary of the Commission. 881-480 81/09/11. CUMINOS, J. J. Office of Inspector & Auditor. 1p. 22281 100 24X Fiche, 50-000, 83/12/14, 8402160003
 - '02160087 Discusses SECY-81-139 re RFF R8-D8D-81-003 entitled.
 'Penformance Testing of Radiobioassay Labs.'
 HILM,S.J Defice of the Secretary of the Commission. S81-139
 1/07/29. DIRCKS W.J. Diffice of the Executive Director for
 grations. 1p. 22281-073 24X Fiche-50-000-83/12/14,8402160003

- --8402160090 Discusses SECY-81-238 re NRC procedures for handling RM info
 CHILK, S J Office of the Secretary of the Commission B1/11/01
 DIRCKS, W J Office of the Executive Director for Operations 1;
 R2281 122 24X Fiche 50-000, 83/12/14,8402160003
- --8402160091 Staff requirements memo re 811119 continuation of discussion of Diablo Canyon order in Washington.DC CHILK.8 J Office of the Secretary of the Commission. MGILLIP BI/12/01 DIRCKS,W J Office of the Executive Director for Operations 1p 22281 034 24X Fichs 30-000.83/12/14.840216000

- --8402160095 Discusses SECY-82-5 re review of ALAB-651 in matter of Florida Power & Light Co (denial of antitrust intervention) CHILK:S J. Office of the Secretary of the Commission. 882-5. 82/01/20 BICKHIT.L Office of the General Counsel. ip 22281 156 24X Fiche. 50-000,83/12/14.8402160003.
- --8402160096 Staff requirements memo re 811209 discussion of schefuling matters concerning TMI-1 restart in Washington, DC. CHILK, S. J. Office of the Secretary of the Commission. M911209A. 81/12/14 BICKHIT.L. Office of the General Counsel AEMICK, F. Office of Policy Evaluations ip 22281:036 24K Fiche 50-000,83/12/14,8402160003
- --8402160097 Discusses SECY-81-147 re RFP RB-DBD-81-011 entitled.

 "Performance Testing for Health Survey Instruments "
 CHILK.B J Office of the Secretary of the Commission. B1/07/29
 DIRKRB.W J Office of the Executive Director for Operations 1)
 22281 074 24X Fichs. 50-000, 83/12/14.8402160003.
- ---B402160098 Discusses SECY-Bi-605 re proposed changes to Korean Mutire Regulatory Bureau/Ministry of Boience & Technology info exchange errangement.

 CHILK, B. J. Office of the Secretary of the Commission. 881-605.

 Bi/1i/03 DIRCKS, M. J. Office of the Executive Director for Operations. 1p. 22281-123 24X Fiche, 50-000, 83/12/14, 8402160003
- --B402160099 Discusses SECY-81-522 re proposed contract mad for continuation of conversion, programming implementation & documentation of NRC automated personnel ays.

 GHILK, S. J. Office of the Secretary of the Commission.

 NRC-10-80-370. SB1-522. B1/07/16 DIRCKS, M. J. Office of the Executive Director for Operations 1p. 22281:102 24X Fiche 50-000,83/12/14,8402160003
- --8402160102 Staff requirements memo re 811222 Affirmation 8sssion 81-47 on TMI-1 restart order in Washington, DC CMILK, 8. J Office of the Secretary of the Commission H8112229 B1/12/28. BICKMIT.L. Office of the General Counsel. Ip. 22281 037 24X Fichs 50-000, 83/12/14, 8402160003.
- --8402160103 Discusses SECY-81-423 re petition for review of ALAS-642 in matter of South Carolina Electric & Qas Co.

 CMILK.8 J Office of the Secretary of the Commission 881-423.

 81/07/29 BICKHITL Office of the General Counsel. 1p.
 22281:075 24X Fiche 50-000,83/12/14,8402160003.
- --B402160104 Discusses SECY-B1-472 re director's denial of patition under 100FR2 206 CHILK, B J Office of the Secretary of the Commission. BB1-472. B1/09/18 BICKWIT, L Office of the Qeneral Counsel ip. 22281 103. 24x Fiche 50-000,83/12/14,8402160003
- --B4D2160105 Discusses SECY-Bi-440 re nuclear power plant staff working hours. CMTLK,B,J. Office of the Becretary of the Commission. COMVQ-81-8 B1/11/04. DIRCKB,W J. Office of the Executive Director for Operations. ip 22281:124, 24X Fiche 50-000,83/12/14,8402160000
- --B402160107 Staff requirements mamo re B20121 discussion of enforcement matters in Washington DC CHILK, B. J. Office of the Secretary of the Commission MB20121A, B2/01/25 DIRCKB, W. J. Office of the Executive Director for Operations ip 22281-038 24X Fiche, 50-000, B3/12/14, B402160003

- --B402160109 Discusses SECY-B1-330A re low level waste vol reduction GHZLK.B J Office of the Secretary of the Commission 81/09/22 DIRCKB, W J Office of the Executive Director for Operations 1p 22281 104 24X Fiche 50-000,83/12/14/8402160003
- --B402160110 Staff requirements mamo re B20203 discussion of Phase I of facility rept in Washington.DC CHILK, 8 J Office of the Secretary of the Commission M8202038 B2602039, BICKWIT.L Office of the General Coursel 1p 22281 037 24X Fiche 50-000.83/12/14.8402160003
- --8402160112 Discusses SECY-81-227 re long-range research plan.
 NUREG-0740
 CHILK.8 J Dffice of the Secretary of the Commission 681-227
 81/07/31 DIRCKS.W J Office of the Executive Director for
 Operations 1p 22281 076 24X Fiche 50-000,83/12/14,8402160003
- --8402160114 Discusses BECY-81-602 re AA recommendation on overexposure in unrestricted area CHILK.8 J Office of the Becretary of the Commission 881-602 Bi/11/06 DIRCKS.W J Office of the Executive Director for Operations ip 22281.125 24X Fiche 50-000.83/12/14,8402160003
- --8402140115 Discusses BECY-81-519 re approval of proposed license to export high enriched U to Canada
 CMILM.B J Office of the Secretary of the Commission 81/09/22
 DIRCKS.M.J Office of the Executive Director for Operations ip 22281,105 24X Fiche 50-000,83/12/14,8402140003
- --B402160116 Btaff requirements memo re 820204 brisfing on proposed enforcement action in Washington.DC CHILK.8 J Office of the Secretary of the Commission M820204D 82/02/12. DIRCKS, W J Office of the Executive Director for Operations ip. 22281 040. 24X Fiche 50-000.83/12/14.8402160003
- --B40216011B Discusses BECY-41-410 re generic rulemaking for treatment of water quality matters in OL stage license actions
 CHILK, S. J. Office of the Secretary of the Commission SB1-410
 B1/09/03 DIRCKS, W. J. Office of the Executive Director for Operations 1p 22281:078. 24X Fiche 50-000.83/12/14.8402160003
- --8402160120 Staff requirements memo re 820226 discussion of revised licensing procedures in Washington.DC CHILK.B J Office of the Becretary of the Commission M8202268 82/03/04. BICKWITL Office of the General Counsel TOURTELLOTTE,J NRC No Datailed Affiliation Given. 1p 22281:041. 24X Fiche: 50-000,83/12/14.8402160003
- --8402160121 Discusses SECY-B1-608 re approval of proposed license to export high enriched U to France.
 CHILK.B J. Office of the Secretary of the Commission SB1-608 B1/11/25. DIRCKS,M.J. Office of the Executive Director for Operations. 1p. 22281:126. 24X Fiche: 50-000, 83/12/14, 8408160003
- --8402160122 Discusses SECY-B1-393 Te review of ALAB-640 CHILK, B.J. Office of the Secretary of the Commission. S81-410 81/08/20, BICKWIT, L. Office of the General Counsel. 1p. 22891.080. 24X Fiche. 50-000, 83/12/14.840
- --B402160123 Staff requirements mamo re 820310 discussion of TMI-1 restart proceeding in Washington, DC, CHILK, B. J. Office of the Secretary of the Commission. M8203108. B2/03/11 BICKMIT.L. Office of the General Counsel ip 22281.042. 24X Fiche: 50-000,83/12/14.8402160003
- ---8402160124 Discusses SECY-82-10B re approval of proposed license to export high & medium enriched U to Switzerland.

 CHILK.S. J Office of the Secretary of the Commission. 82/03/3i DIRCKS.M.J. Office of the Executive Director for Operations. 1p 22281:176. 24X Fiche 50-000.83/12/14.8402160003
- ---8402160126 Staff requirements memo re 820324 discussion of enforcement action in Washington, DC CHILK, B J Office of the Secretary of the Commission, M8203248 82/03/31 Office of the Secretary of the Commission, ip. 22281:043, 24X Fichs:80-000,83/12/14,8402160003
- --8402160128 Discusses SECY-81-614 re proposed export of research reactor & fuel to Morocco, CHILK.B. J. Office of the Secretary of the Commission. S81-614 81/11/25. DIRCKS.M. J. Office of the Executive Director for Operations. 19. 22281:127. 24X Fiche:50-000.83/12/14.8402160003

- --8402160127 Discusses SECY-81-368 re proposed contract award for publication distribution svc & related activities CHILK.S J Office of the Secretary of the Commission SB1-368 81/08/25 DIRCKS, W J Office of the Executive Director for Operations 1p 22281 081 24X Fiche 50-000,83/12/14.8402160003
- --8402160131 Staff requirements memo re 820520 discussion of enforcement action in Washington,DC CHILM: 9 J Office of the Secretary of the Commission 82/05/26 BICKWIT,L Office of the General Counsel to 22281 044 24X Fiche 50-000.83/12/14.8402160003
- --8402160132 Discusses SECY-82-125 re proposed retransfer of math for reprocessing from Switzerland to France
 CHILK: S J Office of the Secretary of the Commission 82/04/05
 DIRCKG: W J Office of the Secretary of the Commission 82/04/05
 22281 177 24X Fiche 50-000:83/12/14.8402160003
- --8402160133 Discusses SECY-81-509 re NUREG-0696 criteria for emergency operations facilities for nuclear power reactors CHILK, S. J. Office of the Secretary of the Commission S81-509 S1/09/30 DIRCKS, W. J. Office of the Executive Director for Operations Ip 22881 108 24% Fiche 50-000, B3/12/14, 8402160003
- --8402160134 Staff requirements mamo re 820528 discussion of enforcement action (subpoema authority) in Washington.DC CHILK.S J Office of the Secretary of the Commission. M8205288 82/05/28 DIRCKS.W J Office of the Executive Director for Operations. ip 22281 045 24% Fiche 50-000.83/12/14.8402140003
- ---8402160135 Discusses SECY-82-126, proposed export of low enriched U fuel to Malaysia.

 CHILK.5 J. Office of the Secretary of the Commission 82/04/05 DIRCKS, W J. Office of the Executive Director for Operations 1p 22281
- --84021&0136 Staff requirements memo re final OAD rept, "Need for Better Policy & Control Over Public Info Requests (GGD-B1-70) " CHILK. 8 J Office of the Secretary of the Commission S81-476 B1/10/02 DIRCKS, W J Office of the Executive Director for Operations 1p 22281 107 24X Fiche 50-000,83/12/14.8402160003
- --B40216013B Discusses SECY-Bi~607 re approval of proposed license to export high enriched U to France
 CHILK.B J Office of the Secretary of the Commission. S81-607
 B1/11/25 DIRCKB.W J Office of the Executive Director for
- --8402160140 Staff requirements memo re 820611 discussion of status of shift manning requirements in Washington, DC GHILK, S J Office of the Secretary of the Commission. 82/06/15 DIRCKS, W J. Office of the Executive Director for Operations 1p 22201 046 24X Fiche. 50-000, 83/12/14, 8402160003
- --8402160142 Discusses BECY-Bi-547; Section 208 rept to Congress on ADs for Apr-June 1981
 CHILK, B.J. Office of the Becretary of the Commission. SBI-547
 BI/10/06. DIRCKB, W.J. Office of the Executive Director for Operations. ip 22281/110. 24X Fiche. 50-000; B3/12/14; 8402160003
- ---8402160143 Discusses SECY-SI-628 final QAD rept entitled "Greater Commitment Needed to Bolve Continuing Problems at TMI."

 CHILK.S.J. Office of the Secretary of the Commission S81-628, S2/01/27 DIRCKS, M.J. Office of the Executive Director for Operations. 1p. 22281:157 24X Fiche 50-000.83/12/14,8402160003
- --8402160144 Staff requirements memo re 820707 discussion & possible vote on contested issues in OL proceeding in Washington, DC.
 CHILK.B J Office of the Secretary of the Commission M820707B
 B2/07/13 BICKWIT.L Office of the General Counsel 2pp.
 22281.047. 24X Fishs 50-000.83/12/14.8402160003.
- --8402160145 Discusses SECY-81-447.ALA8-647 re Duke Power Co CHILK.8 J Office of the Secretary of the Commission. S81-447 81/08/25. BICKWIT,L. Office of the General Counsel ip 22281-084. 24% Fiche, 50-000.83/12/14,8402160003
- ---8402160146 Discusses SECY-81-659 re release of Morgan rept to foreign govts CHILK.B J. Office of the Secretary of the Commission 881-659 81/11/25 DIRCMS.W.J Office of the Executive Director for Operations 1p. 22281-129 24X Fiche. 50-000.83/12/14.8402160003
- --8402160147 Discusses BECY-81-567 re proposed extension of Tokai-Mura agreement CHILM,S.J Office of the Becretary of the Commission. 81/10/07 DIRCKS.W J. Office of the Executive Director for Operations ip 22281:112 24X Fiche.50-000.63/12/14.8402160000

- ~-8402160150 Discusses SECY-82-119 re proposed retransfer of matl for reprocessing from Japan to United Kingdom CHILK.8 J Office of the Secretary of the Commission 82/04/05 DIRCKS.W J Office of the Executive Director for Operations 1p 22261 180 24X Fiche 50~000.83/12/14.8402140003
- ~-8402160151 Discusses SECY-81-643 re TMI-1 scheduling order CHILK,S J Office of the Secretary of the Commission S81-643 B1/11/27 BICKHIT.L Office of the General Counsel 1p 22281 130 24% Fiche 50-000.83/12/14.8402160003
- --8402160152 Discusses SECY-81-478 re proposed new US policy approach CMILK.S J Office of the Secretary of the Commission SBI-478 81/08/26 DIRCKS.H J Office of the Executive Director for Operations tp 22281 085 24X Fiche 50-000, 83/12/14, 8402160003
- --9402160153 Discusses SECY-BI-456 re suggested time periods for issuance of initial decisions
 CHILK-3 J Office of the Secretary of the Commission. 82/01/27
 COTTERS P Atomic Safety and Licensing Board Panel 1p
 22281 158 24X Fiche 50-000,83/12/14,8402160003
- --8402160155 Discusses SECY-BI-493 re proposed change to assumption concerning relative case of fabricating clandestine fission explosives
 CHILKS J Office of the Secretary of the Commission 881-495
 BI/10/09 DIRCKS, H J Office of the Executive Director for Operations 1p 22281 113 24% Fiche 50-000,83/12/14,8402160003
- --8402160156 Discusses SECY-81-645 rv AO recommendation on failure of HPSI sys CHILK'S J Office of the Secretary of the Commission S81-645 81/11/30 DIRCKS'W J Office of the Executive Director for Operations 1p 22281 131 24X Fiche 50-000,83/12/14,8402160003
- --B402160158 Discusses SECY-B1-413 re ETS or licensing actions CHILK.S J Dffice of the Secretary of the Commission 81/08/31 DIRCKS.W J Office of the Executive Director for Operations 1 22281 087 24% Fiche 50-000.83/12/14.8402160003
- --8402160160 Discusses SECY-81-661 re proposed transfer of mat1 to Argentina per 10CFR810 CHILK: 9 J Office of the Secretary of the Commission S81-661 B1/12/01 DIRCKS: W J Office of the Executive Director for Operations 1p 22281 132 24X Fiche 50-000:83/12/14,8402160003
- ---8402160161 Discusses SECY-81-383 re storage of low level radwaste at power reactor sites
 CHILK, S J Office of the Secretary of the Commission SB1-383
 81/10/09 DIRCKS, W J. Office of the Executive Director for Operations ip 22281 114 24X Fiche 50-000.83/12/14.8402160003
- --8402160162 Discusses SECY-82-237 re AO recommendation on diesel generator engine cooling sys failures.

 CHILK,S J Office of the Secretary of the Commission 82/07/08 DIRCKGH,J Defice of the Executive Director for Operations 1p 22281 208 24% Fiche 80-000,83/12/14.8402160003
- --8402160163 Discusses SECY-82-148 re proposed transfer of turnable diode lasers to West Germany.

 CHILK, 3 Office of the Secretary of the Commission 82/04/20.

 DIRCKS,W J Office of the Executive Director for Operations 1p. 22281 181 24X Fiche 50-000,83/12/14,8402160003
- ~8402160165 Discusses SECY-81-236 re proposed mechanism for recording decisions in emergency situations
 CHILK, S J Office of the Secretary of the Commission 81/10/09
 BICKWITL Office of the General Counsel. 1p. 22281 115 24X
 Fiche 50-000,83/12/14,8402160003
- -8402160166 Discusses SECY-81-660 re TMI-1 restart hearing stipulation on witness confidentiality.
 CHILK.8 J Dffice of the Secretary of the Commission 881-660 81/12/02. BICKNIT: L Office of the General Counsel 1p. 22281:133 24X Fiche-50-000.83/12/14.8402160003
- -8402160167 Discusses SECY-81-427 re approval of proposed license to export low enriched U to Philippines
 CHILK, B. J. Office of the Secretary of the Commission 581-427
 81/08/31 DIRCKS, W. J. Office of the Executive Director for Operations 1p 22281 088 24X Fiche, 30-000, 83/12/14, 8402160003
- -B402i40148 Discusses SECY-82-239 re delegation of subpoema authority CHILK, B J Office of the Secretary of the Commission 82/07/20 DIRCKS, W J Office of the Executive Director for Operations in 22281 209 24X Fiche 50-000.B3/12/14,8402160003
 - 402160169 Discusses SECY-82-151 re exports to South Korea CHILK, 8 J Office of the Secretary of the Commission. 82/04/20 URCKS, W J Office of the Executive Director for Operations 1: 2281 182 24X Fiche.50-000.83/12/14.8402160003

- --8402160171 Discusses SECY-81-294 re environ assessment policy for interim spent fuel storage CHILK,8 J Office of the Secretary of the Commission. 881-294, 81/10/13 BICKHIT.L Office of the General Counsel 1p 22281 116 24X Fiche 50-000.83/12/14.8402160003
- --8402160172 Discusses proposed civil penalty Enforcement Action EA-82-46 CHILK,S J Office of the Secretary of the Commission. EA-82-046 82/07/20 DIRCKS,W J Office of the Executive Director for Operations. 10 22281 210 24X Fiche 50-000,83/12/14.8402160003
- --8402160173 Discusses 8ECY-81-489, approval of proposed license to expert high enriched U to Federal Republic of Germany CHILK, B J Office of the Secretary of the Commission, 881-489 81/07/01 DIRCKS, W J Office of the Executive Director for Operations 1p 22281 089 24X Fiche 50-000, 83/12/14, 8402160003
- --B402160175 Discusses SECY-81-654 re AD recommendation on radiation exposures exceeding 10CFR20 limits
 CHILK,S J Office of the Secretary of the Commission 881-654
 B1/12/O2 DIRCKS,W J Office of the Executive Director for Operations 1p 22281 134 24X Fiche 50-000,83/12/14,8402160003
- ---8402160177 Discusses SECY-81-579, ALAB-651 re transportation of spent fuel from Oconee Nuclear Station for storage at McQuire Nuclear Station GHILK.S J Office of the Secretary of the Commission, ALAB-651 81/10/27 BICKWIT.L Office of the General Counsel 1p 22281 117 24X Fiche 50-000.83/12/14.8402160003
- --B402160178 Discusses SECY-B1-700,rs Section 208 rept to Congress on AGs for Jul-Sept 1981
 HOYLE,J C Defice of the Secretary of the Commission, 82/02/02, DIRCKS,W J Office of the Executive Director for Operations. 1p 22281 150 24X Fichs.50-000,83/12/14,8402160003
- --8402160179 Discusses SECY-82-110 re objective performance indications for evaluation of Agreement State radiation control programs CHICK.8 J Office of the Secretary of the Commission 62/04/27, DIRCKS.W J Office of the Executive Director for Operations 1p. 22281-184 24X Ficher 50-000.83/12/14.8402160003
- ---8402160182 Discusses SECY-Bi-671 re Commerce Dept proposed export of Zircaloy-4 sheet to India via Federal Republic of Germany for Tarapur Nuclear Power Plant CHILK.8 J. Office of the Secretary of the Commission. 891-671. 81/12/03 DIRGK8.H J Office of the Executive Director for Operations 1p 22281:135 24X Fiche.50-000.83/12/14.8402160003
- --8402160183 Discusses SECY-82-144 re proposed retransfer of mat1 for reprocessing from Spain to United Kingdom CHILK.8 J Office of the Secretary of the Commission 82/04/27 DIRCKS.W J Office of the Executive Director for Operations. ip 22281 185 24X Fiche.50-000,83/12/14.8402160003
- --8402160184 Discusses SECY-82-255 re AO recommendation on pressure transfents during shutdown at plant CHILK.8 J Office of the Secretary of the Commission. 82/07/21. DIRCKS.W J Office of the Executive Director for Operations. 1p. 22281:211. 24X Fiche 50-000.83/12/14.8402160003
- ---8402160183 Discusses SECY-B2-170 re seventh DDE/NRC annual rept on domestic safeguards.

 CHILK/8 J Office of the Secretary of the Commission. 82/04/30 DIRCK/8/W.J Office of the Executive Director for Operations ip 22281 186. 24X Fichs:50-000/83/12/14,8402160003.
- --BA021601B6 Discusses SECY-B1-549 re indemnification of licensess storing spent fuel at sites other than sites where fuel was irradiated CHILK.B J. Office of the Secretary of the Commission. SB1-549. B1/10/27 DIRCHS.H J Office of the Executive Director for Operations 1p 22281 118 24X Ficher 50-000, B3/12/14, B402160003
- --8402160187 Discusses SECY-B2-213 re review of ALAB-669 in matter of Duke Power Co.

 CHILK, B. J. Diffice of the Secretary of the Commission ALAB-669.

 82707/27. 81CKWIT, L. Diffice of the General Counsel ip.

 82281.212. 24% Fiche, 50-000, 83/12/14, 8402160003.
- --8402160190 Discusses SECY-82-22 re NRC adverse decision in personnel case on SEG conversion appeal
 HOYLE, C Office of the Secretary of the Commission. S82-22.
 82/02/03 BICKNITEL, Office of the General Counsel ip
 22281
- --8402160191 Discusses SECY-81-589 re ALAB-654. CHILK, S J. Diffice of the Secretary of the Commission 881~589. 81/10/28 BICKHITL Diffice of the General Counsel 1p. 22281,119. 24X Fiche 50~000.83/12/14.8402160003

- --8402160192 Discusses SECY-82-258 re review of director's decision on IOCFR2 206 petition
 CHILK, S. J. Office of the Secretary of the Commission 82/07/27
 BICKWIF, L. Defice of the General Counsel 1p 22281 213 24X
 Fiche 50-000.83/12/14,8402160003
- --B402160193 Discusses BECY-B2-154A re revised IO paper on plutonium use CHILK, S J Office of the Secretary of the Commission B2/05/11 DIRCKB, W J Office of the Executive Director for Operations ip 22281 187 247 Fiche 50-000.83/12/14.8402160003
- --8402160194 Discusses SECY-82-295, Section 208 rept to Congress on AOs For Jan-Mar 1982 HOYLE, J C. Office of the Secretary of the Commission 82/08/02 DJRCKS, W J Office of the Executive Director for Operations in 22281 214 24X Fiche 50-000.83/12/14.8402160003
- --8402160198 Discusses BECY-B2-232 re use of nonplant-specific simulators for initial, replacement & requalification exam for licensed reactor operators & senior operators
 HOYLE, J C Office of the Secretary of the Commission 82/08/03
 DIRCKS, W J Office of the Executive Director for Operations ip 22281 215 24X Fiche 50-000,83/12/14,8402160003
- --8402160197 Discusses SECY-B1-637 re review of director's decision on 10CFR2 206 petition
 CHILKS J Office of the Secretary of the Commission BB1-671
 B1/12/04 B1CKWIT.L Office of the Queral Counsel 1p 22281:136 24X Fiche 50-000.83/12/14.8402160003
- --B402160200 Discusses BECY-82-24 re review of ALAB-662 in matter of Puerto Rico Electric Power Authority
 HDYLE,J C Office of the Becretary of the Commission SB2-24
 B2702/03 B1CKWIT.L Office of the General Counsel 1p
 22281 152 24X Fiche 50-000 B3/12/14.8402160003
- --8402160202 Discusses SECY-82-317 re FOIA Appeal 82-A-7C on emergency planning CHILK, B.J. Office of the Secretary of the Commission 82/08/16 BICKWIT, L. Office of the General Counsel. 1p 22281 216, 24X Ficha 50-000,83/12/14,8402160003.
- --B402160204 Discusses SECY-82-142 re rept to Congress on AOs for Oct-Dec 1981 CHILK.B J Office of the Secretary of the Commission. 82/05/14 BIRCKS.W J Office of the Executive Director for Operations 1p 22281:188. 24X Fiche 50-000,83/12/14,8402150003
- --B402160205 Discusses SECY-82-321 re first circuit decision in license fee case. New England Power vs NRC CHILK, B. J. Office of the Secretary of the Commission. 82/08/16 DIRCKS. W. J. Office of the Executive Director for Operations BICKHIT, L. Office of the General Counsel. 1p 22281-217 24X Fiche 50-000, 83/12/14, 8402160003
- --8402160206 Discusses SECY-G1-638 re review of director's decision on 10CFR2 206 petition.
 CHILK.B.J Office of the Secretary of the Commission SB1-638 G1/12/07. BICKNIT.L Dffice of the General Counsel 1p 22281,137 24X Fiche 50-000,83/12/14,8402160003.
- --8402160208 Discusses SECY-82-182 re proposed license to export 3,000 kg deuterium oxide to 24 countries.

 CHILK, B. J. Office of the Becretary of the Commission 82/05/27 DIRCKB, H. J. Office of the Executive Director for Operations. 1p 22281,189, 24X Fiche 50-000,83/12/14,8402160003
- --8402160210 Discusses BECY-82-315 re proposed guidance for implementing SRP rule.
 CHILK, 8 J. Office of the Secretary of the Commission. 82/08/24
 DIRCKB, W J. Office of the Executive Director for Operations ip 22281 218.
- --B402160212 Discusses SECY-B2-171 re licensed fuel facility status rept & inventory difference data, NUREG-0430, Vol 2, No 1, Jan-June 1981. CHILK, B J Diffice of the Secretary of the Commission, 82/05/28 DIRCKB, W.J Office of the Executive Director for Operations, 1p 22281 190 24X fiche: 50-000, 83/12/14, 840216003.
- --8402140215 Discusses SECY-Bi-452 re Cohen FOIA Appeal Bi-A-11C CHILK, B J. Office of the Secretary of the Commission SBI-652 Bi/12/08 BICKWIT.L. Defice of the General Counsel ip. 22261:138 24% Fichs. 50-000, 83/12/14, 8402160003
- --8402160216 Discusses SECY-82-316 re delegation of authority to staff to process certain retransfers of matl to EURATOM countries for reprocessing.

 CHILK.S. J. Office of the Secretary of the Commission 82/09/03 DIRCKS.W. J. Office of the Executive Director for Operations. ip 22281-219. 24X Fiche. 50-000, 83/12/14, 8402160003

- --8402160218 Discusses SECY-82-18 re review of ALAB-657 in matter of Philadelphia Electric Co CHILK,S J Office of the Secretary of the Commission S82-18 82/02/04 BICKWIT.L Office of the General Counsel ip 22281 153 24X Fiche 50-000/83/12/14/8402160003
- --8402160220 Discusses SECY-80-39 re Section 401 of Energy Reorganization Act of 1974 & impact upon employment practices of NRC licenses & applicants for license CHILK,S J Office of the Secretary of the Commission 880-39 81/12/17. DIRCKS,W J Office of the Executive Director for Operations 1p 22281 139 24X Fiche 30-000,83/12/14,8402140003
- --8402160221 Discusses SECY-82-175 re review of ALAB-667 in matter of PSC of NH
 CHILK.5 J Diffice of the Secretary of the Commission ALAB-667
 82/06/02 BICKWIT.L Office of the General Counsel 19
 22281 191 24X Fiche 50-000,83/12/14,8402160003
- --BAD2160224 Discusses BECY-81-591 re amends to 10CFR140 on changes in nuclear emergy liability insurance policy CHILK, 3 Upfice of the Secretary of the Commission 81/12/18 DIRCKB, W J Office of the Executive Director for Operations ip 22281 140 24X Fiche 50-000,83/12/14,8402140003
- --8402160225 Discusses SECY-82-174 re review of ALAB-671 in matter of Houston Lighting & Power Co CHILK.S J Office of the Secretary of the Commission ALAB-671 82/06/02 BICKWIT.L Office of the General Counsel ip 22281 172 24X Fichs 50-000.63/12/14.8402160003
- --8402160227 Discusses SECY-81-592 re implementation of certain provisions of Public Law 94-197 on notification of Price-Anderson Act CHILK, 8 J Office of the Secretary of the Commission SBI-592 BI/12/18 DIRCKS, W J Office of the Executive Director for Operations 1p 22281 141 24X Fiche: 50-000, B3/12/14, 8402160003
- --B402i60230 Discusses SECY-B2-177 re director's denial of 10CFR2 206 relief in matter of petition requesting closedown of suspect reactors pending resolution of pressurized thermal shock nonconservatisms

 CHILK, B J Office of the Becretary of the Commission 82/06/02 BICKWIT, L Defice of the General Counsel 1p 22281,193 24X Fiche 50-000, B3/12/14, B402i60003
- --8402160234 Discusses AD recommendation re misalignment of high head safety injection isolation valva
 CHILK,8 J Office of the Secretary of the Commission. 81/12/21
 DIRKKB,W J Office of the Executive Director for Operations ip 22281 142 24X Fiche 50-000,83/12/14,8402160003
- ---8402160235 Discusses SECY-82-34 re florida Power & Light Co CHILK,S.J Office of the Secretary of the Commission. 82/02/16 BICKHIT/L Office of the General Counsel. 1p 22281 154 24X Fiche 50-000,83/12/14/8402160003
- --B402160236 Discusses SECY-82-207 re subsequent arrangement for reprocessing of Joyo fuel at chemical processing facility at Tokai-Mura.

 CHILK, B. J. Office of the Secretary of the Commission E2/06/11 DIRCKS, W. J. Office of the Executive Director for Operations in R22B1 195 24X Fiche 50-000,83/12/14,8402160003
- --8402160239 Discusses SEGY-82-211 re approval of proposed license to export high enriched U to Canada CHILK,8 J Office of the Secretary of the Commission 82/06/15 DIRKS,8 J J Office of the Executive Director for Operations ip 22281 196 24X Fiche: 50-000, 83/12/14, 8402140003
- --8402160240 Discusses BECY-81-677 re retransfers of matl from Switzerland to United Kingdom CHILK, S. J Dffice of the Secretary of the Commission 881-677 81/12/24 DIRCKS, M J Office of the Executive Director for Operations ip. 22281:143 24X Fiche 50-000,83/12/14,8402160003
- ---8402160243 Discusses SECY-82-10 re proposed NRC policy statement on use of high enriched U in research reactors
 CHILK.S.U. Office of the Secretary of the Commission 82/06/15
 DIRCKG.W.U. Office of the Executive Director for Operations. 1p
 22281 197 24X Fiche 30-000.83/12/14.8402160003
- --B402160244 Discusses SECY-82-304 re amend to 10CFR140 on removal of apps from regulations
 CHILK, B. J. Diffice of the Secretary of the Commission 82/09/15
 DIRCKS, W. J. Diffice of the Executive Director for Operations ip 22281.220 24X Fiche 50-000, 83/12/14, 8402160003

- --8402i60246 Discusses SECY-81-687 re designation of pressurized thermal shock as unresolved safety 19808 CHILK,S J Office of the Secretary of the Commission S81-687 81/12/28 DIRCKS,W J Office of the Executive Director for Operations 1p 22281 144 24X Fithe 50-000.83/12/14,8402160003
- --B402160248 Discusses SECY-B2-222 re proposed retransfer of mat1 for reprocessing from Sweden to France
 CHILK,S J Office of the Secretary of the Commission 82/06/16
 DIRCKS,W J Office of the Executive Director for Operations 1p
 22281 198 244 Fiche 50-000.83/12/14/8402160003
- --B402160249 Discusses SECY-82-302 re appointment of ACRS members CHILK.S J Office of the Becretary of the Commission 82/09/15 FRALEY.R F ACRS Advisory Committee on Reactor Safeguards 1p 22281 221 24X Fichs 50-000.83/12/14.8402160003
- --8402160250 Discusses SECY-B1-670 re licensed fuel facility status rept CHILK,8 J Office of the Spiretary of the Commission 81/12/29 DIRCKS,W J Office of the Executive Director for Operations 1, 22281 145 24X Fichs 50-000,83/12/14,8402160003
- ---8402160252 Discusses SECY-82-330 re NRC personnel security clearance program mods CHILKS J Diffice of the Secretary of the Commission 82/09/15 DIRCKS,H J Office of the Executive Director for Operations 1p 22281 222 24X Fiche 50-000,83/12/14.8402160003
- --B402160293 Discusses SECY-B1-445 re review of director's dehial of 10CFR2 206 petition
 CHILK,6 J Dffice of the Secretary of the Commission SB1-445
 B2/01/07 DIRCKS,W J Office of the Executive Director for Operations BICKWITL Office of the General Counsel 1p 22281 146 24X Fiche 50-000,83/12/14,8402160003
- --B402140235 Discusses SECY-B2-359 re license amend to increase quantity of high enriched U for export to Canada CHILK.8 J Office of the Becretary of the Commission B2/09/17 DIRCKS.H J Office of the Esecutive Director for Operations 1p 22281 223 24X Fiche: 50-000:83/12/14,8402160003
- --8402160256 Discusses SECY-B1-498 re routing policy for spent fuel shipments
 CHILK.S J Office of the Secretary of the Commission 81/09/30 DIRCKS.H J Office of the Esecutive Director for Operations 1, 22281 106 24X Fiche 50-000.83/12/14,8402160003
- --8402160257 Discusses SECY-81-646 re proposed agreement between NRC & State of MA per Section 274 of Atomic Energy Act of 1754 as amended CHILK, S J Office of the Secretary of the Commission 981-646 82/01/07 DIRCKS, W J Office of the Executive Director for Operations 1p 22281.147 24% Fiche 50-000.83/12/14,8402160003
- --8402160258 Discusses SECY-81-515 re plan for improving technical capability of licensee personnel
 CHILKS J Office of the Becretary of the Commission S81-515.
 B1/10/06 DIRKS, W J Office of the Executive Director for Operations IP 22281-111 24X Fiche 50-000,83/12/14,8402160003
- --8402160259 Discusses SECY-82-226 re AO recommendation on steam generator tube rupture at plant
 CHILK.S J Office of the Secretary of the Commission. 82/06/24
 DIRKKS,W J Office of the Executive Director for Operations 1p
 22281 200 24X Fiche: 50-000,83/12/14,8402160003
- --8402160261 Discusses SECY-92-135 re study of feasibility & value of licensing nuclear plant managers & senior licensee officers CHILK.8 J Office of the Secretary of the Commission B2/09/17. DIRCKS,N J Office of the Executive Director for Operations 1g 22281 224 24X Fichs 50-000.63/12/14.8402160003
- --8402160263 Discusses SECY-82-127 re reassertion of certain regulatory authority in State of NE
 CHILK.S J. Office of the Secretary of the Commission 82/04/20, DIRCKS,W.J. Office of the Executive Director for Operations ip 22281:201 24X Fiche, 50-000, 83/12/14, 8402160003
- ---840R160265 Discusses SECY-82-365 re proposed retransfer of 60 kg low enriched U from West Germany to Peru.

 CHILK, S. J. Office of the Secretary of the Commission 82/07/20 DIRCKS.W J. Office of the Executive Director for Operations. 1p 22281 225 24X Fiche 50-000,83/12/14,8402160003
- --8402160266 Discusses SECY-Bi-682 re Won Door Corp vs US,109-791,UB Court of Claims CHILKS J Diffice of the Secretary of the Commission. 82/01/08 DIRCKS,W J Office of the Executive Director for Operations. 1; 82881 148 24X Fiche 50-000,83/12/14,8402160003

- --8402160268 Discusses SECY-82-238 re approval of proposed licenses to export low enriched U to Taiwan CHILK:S J Diffice of the Secretary of the Commission 82/06/28 DIRCKS,W J Diffice of the Executive Director for Operations, 1, 22281 202 24X Fiche 30-000,83/12/14,8402160003
- --8402160269 Discusses SECY-82-344 re proposed license to export high enriched U to Greece CHILM.8 J Office of the Secretary of the Commission. 82/09/22 DIRCKS.W J Office of the Executive Director for Operations 1, 22281 226 24X Fiche 50-000,83/12/14.8402160003
- --8402160272 Discusses SECY-82-190 re performance appraisal team Inspergram
 CHILK:8 J Office of the Secretary of the Commission 82/06/28
 DIRCKS,N J Office of the Executive Director for Operations. 19
 22281 203 24X Fiche 50-000,83/12/14.8402160003
- --B402160273 Discusses SECY-B2-234 re proposed retransfer of matt for reprocessing from Switzerland to France
 CHILK:5 J. Office of the Secretary of the Commission B2/05/29
 DIRCKS:N J Diffice of the Executive Director for Operations if 22881 204 24X Fiche 50-000,83/12/14.8402160003
- --B402160274 Discusses SECY-82-368 re proposed rulemating to clarify procedures for appealing prehearing & special prehearing conference orders granting or denying intervention CHILK.S J Office of the Becretary of the Commission B2/09/28 DIRCKS W J Office of the Executive Director for Operations is 22281 228 24X Fiche 50-000,83/12/14.8402160003
- --8402140275 Discusses SECY-81-478 re revised Mark I containment long-term program CHILK,S J Office of the Becretary of the Commission 881-678 82/01/08 DIRCKS,W J Office of the Executive Director for Operations ip 22281 149 24X Fiche 50-000.83/12/14.8402160003
- --8402160279 Discusses GECY-82-259 re retransfer of spent fuel from Japan to France & to United Kingdom for reprocessing. CHILK, 8 J. Office of the Secretary of the Commission 82/04/29 DIRCKS, W. J. Office of the Executive Director for Operations 19 22281 205 24X Fiche 50-000.83/12/14.8402160003.
- --B4021602BO Discuspes SECY-82-386 re licensed fuel facility statut (1) inventory difference data NUREO-0430, Vol 2, No 2, Jul-Dec 1981 CHILK, B J Office of the Secretary of the Commission B2/09/27 DIRCKB, W. J Office of the Executive Director for Operations () 222B1 227. 24X Fiche 50-000, 83/12/14,8402160003
- --8402160281 Discusses SECY-82-244 re proposed retransfer of mat1 for reprocessing from Japan to France & United Kingdom CHILK,S J. Office of the Secretary of the Commission, 82/06/27 DIRCKS,W J. Office of the Executive Director for Operations () 22281:206 24X Fiche 50-000,83/12/14,8402160003
- --8402160285 Discusses SECY-BR-227 re approval of proposed license to export high enriched U to France for high-flux reactor in Orenoble CHILK,S J Office of the Secretary of the Commission 82/02/39 DIRCKS,W J Office of the Executive Director for Operations if 22281 207 24X Fiche 50-000,83/12/14.8402160003
- --B402160287 Discusses SECY-82-16A re TMI-1 psychological impact decision & litigation strategy CHILK, S J Office of the Secretary of the Commission B2/02/25 BICKMIT. Office of the Ceneral Counsel 1p. 22281,160 24X Fiche 50-000,83/12/14,8402160003
- ---B4021602B9 Discusses SECY-82-187 re revised guidelines for preparing value impact analyses.

 CHILK, 3 Office of the Secretary of the Commission. B2/09/30 DIRCKS W J Office of the Executive Director for Operations 19 22281 230 24X Fichs 50-000.B3/12/14.B402160003.
- --B402160291 Discusses SECY-B2-374 re approval of proposed license to export research reactor & SNM to Dangladesh CHILK, S. J Office of the Secretary of the Commission. 92/10/01 DIRCKS, M J Office of the Executive Director for Operations 1) 22281 R31 24X Fichs 50-000, 83/12/14, 8402140003
- --8402160277 Discusses SECY-83-28 re FOIA Appeal 82-A-20. CHILK, 8 J Office of the Secretary of the Commission. 83/02/04 MALSCH, M Office of the General Counsel 1p 22281 262 24% Fiche 50-000, 83/12/14, 8402160003
- --8402160300 Discusses SECY-83-33 re approval of proposed license to export high enriched U to Canada CHILK, S. J Office of the Secretary of the Commission. 83/02/07 DIRCKS. W J Office of the Executive Director for Operations. 13 22281-263 24X Fiche 50-000.83/12/14.8402160003

- --8402160302 Discusses SECY-83-18 re second FOIA Appeal 82-A-24 on rules for environ qualification CHILK.B J Office of the Secretary of the Commission 83/02/09 DIRCKS.W Office of the Executive Director for Operations MALSCH.M Office of the General Counsel ip 22281 264 24X Fichs 50-000,63/12/14.8402160003
- --B402160303 Discusses SECY-82-41 re proposed amended agreement between NRC & State of CO per Section 274 of Atomic Energy Act of
 - TYDA

 CHILK, S. J. Office of the Secretary of the Commission 882-41

 82/03/01 DIRCKS, W. J. Office of the Executive Director for Operations 1p 22281 162 24% Fiche 50-000,83/12/14,8402160003
- --- 8402160304 Discusses SECY-83-34 re proposed transfer of Swiss-owned Pu
 - NOTIONAL EURATOM
 within EURATOM
 CHILK,8 J Office of the Secretary of the Commission 83/
 DIRCAS, H Office of the Executive Director for Operations
 22281 265 24% Fiche 50-000,83/12/14.8402160003 83/02/08
- --8402160308 Discusses BECY-B2-283 re proposed mod of immediate effectiveness rule for CP decisions
 CHILLS J Office of the Secretary of the Commission 82/3
 BICXWIT,L Office of the General Counsel 1p 22281:232
 Fichs 50-000,83/12/14.8402160003 82/10/04
- ---8402160309 Discusses SECY-83-66 re proposed retransfer for reprocessing From Suitzerland to France.

 CHELK.S. J Office of the Secretary of the Commission 83/
 DIRCKS, W Office of the Executive Director for Operations
 22201 267 24% Fiche 50-000.83/12/14.8402160003
- --B402160311 Discusses BECY-82-394 re oral presentations on TMI restart CHILK.B J Diffice of the Secretary of the Commission B2/10/19 Office of the Secretary of the Commission ip 22281 233 24X Fiche.30-000, 83/12/14/8402160003
- --8402160313 Discusses SECY-B2-32 re proposed transfer of Bwiss
 Pu for use in Super Phoenix breeder reactor in France or SNR
 300 breeder reactor in Federal Republic of Germany
 CHILK, S J Office of the Secretary of the Commission 882-32
 82/03/02. DIRCKS, W J Office of the Executive Director for
 Operations 1p 22281 163 24X Fiche 50-000, 83/12/14, 8402160003
- -8402160316 Discusses SECY-83-36 re director's denial of 10CFR2 206 patition on CPs CHILK, S J. Office of the Secretary of the Commission, 83/02/28 PLANNE, H Office of the General Counsel 1p 22281 268 24X Fiche: 50-000, 83/12/14, 8402160003.
- --8402160317 Discusses GECY-82-384 re status of TMI-1 NUREQ-0737 items CHILK, B J. Office of the Secretary of the Commission. 82/10/19 DIRCKB, H J Office of the Executive Director for Operations. ip 22/281-234. 24% Fiche 50-000,83/12/14.8402160003
- --84021A0319 Discusses SECY-82-455/455A re items for NRC legislative OMICUSITY DISCUSSES SECT-ME-40074004 Te Items for NRC legislative program for 98th Congress CHILK.8 J Office of the Secretary of the Commission 83/03/02 PLAINE.H H Office of the Ceneral Counsel ip 22281.269 24 Fiche: 80-000, 83/12/14, 8402160003.
- ---8402160320 Discusses SECY-82-40 re Newhark inquiry.
 CHILK,8 J Diffice of the Becretary of the Commission SB:
 82/03/05 BICKNIT,L Diffice of the Ceneral Counsel 1p.
 22281 164. 24X Fiche 50-000,83/12/14,8402160003 882-40
- --B402i60322 Discusses BECY-81-653/B2-55 re export & import of nuclear equipment & mat1, proposed amends to NRC regulations, CHILK,B J. Office of the Escretary of the Commission 83/03/02 DIRCKB,W. Office of the Escretary of the Commission 93/03/02 2281.270. 24% Fiche 50-000,83/12/14,8402160003
- --8402160324 Discusses SECY-83-14 re draft policy statement on regionalization.

 CHILK 8.J. Office of the Becretary of the Commission 83/03/07 DIRCKS, W. Office of the Executive Director for Operations' JERBE, J.E. Office of Policy Evaluations 1p. 22281 271 24X Fiche 50-000, 83/12/14,8402160003. 83/03/07.
- --B402160325 Discusses SECY-82-434 re DOJ request for NRC views on Siliwood vs Kerr-McQee Corp. Supreme Court Case Si-2157.
 CHILK, S. J. Diffice of the Secretary of the Commission 82/11/02 DIRCKS, M. J. Office of the Executive Director for Operations. ip 22881 236 24X Fiche 50-000,83/12/14,8402160003.
- --840214032B Discusses SECY-82-68 re proposed retransfer of mat1 for reprocessing from Japan to United Kingdom & France GHILM. B. J. Office of the Secretary of the Commission. B1/03/15. D18CMS.M. J. Office of the Executive Director for Operations ip 82281, 165. 24X Ficha 50-000,83/12/14.8402160003

- --8402160329 Discusses SECY-83-49 re review of ALAB-705 in matter of Met CHILK.S.J. Office of the Secretary of the Commission 83/03/11 PLAINE.H H. Office of the General Counsel 22281 272 24% Fiche 50-000.83/12/14.8402140003
- --8402160330 Discusses SECY-82-298 re radioactive consumer product repts CHILK,8 J Office of the Secretary of the Commission 82/11/04 DIRKS,W J Office of the Executive Director for Operations 1p 22281 237 24X Fiche 50-000,83/12/14.8402160003
- --B402160332 Discusses SECY-B3-57 re MOU w/GAU CHILK.S J Office of the Secretary of the Commission B3/03/11 PLAINE.H H Office of the General Counsel 1p 22281 273 24 Fiche 50-000.83/12/14.8402160003
- --8402160335 Discusses SECY-82-1B re proposed Commission policy statement on severe accidents & related views on nuclear reactor
 - regulation

 CHILK-B J Office of the Secretary of the Commission 83/

 DIRCKG.W Office of the Executive Director for Operations

 22281 274 24% Fiche 50-000,83/12/14,8402160003
- --B40216033B Discusses SECY-83-104 re approval of proposed litense to export hatural U to EURATOM countries
 CHILK.B J Office of the Secretary of the Commission 83/03/29
 DIRCKS.W Office of the Executive Director for Operations 1p
 22281:275 24X Fiche 50-000.83/12/14.8402160003
- --8402160341 Discusses SECY-82-395 re proposed rule eliminating opportunity for hearings for operator license applicants who fail test CHILK.B J. Office of the Secretary of the Commission B2/11/04 DIRCKB.W J Office of the Executive Director for Operations, ip 28281 839 24X Fiche 50-000.83/12/14.8402140003
- --B402160342 Discusses SECY-B3-94 re FOIA Appeal B3-10 CHILK B.J Office of the Secretary of the Commission B3/03/30. PLAINE, H.H Office of the General Counsel. 1p 22281 276 24X Fitchs 50-000.83/12/14,8402160003
- ---B402160344 Discusses SECY-82-423 re proposed transfer of technology to Againosa Distusses octi-us-us-us is proposal and analysis of the Secretary of the Commission MCGREGOR, E W Office of the Becretary of the Commission B2/11/09 DIRCKS, W J Office of the Executive Director for Operations 1p 22281 240 24X Fiche 50-000,83/12/14,8402160003
- --8402160345 Discusses SECY-83-73 re reappointment of ACRS member CHILK,S J Office of the Secretary of the Commission 63/03/30 FRALEY,R F, ACRS Advisory Committee on Reactor Safeguards 1, 22281 277 24X Fiche 50-000,83/12/14,8402160003
- --8402160346 Discusses SECY-82-431 re review of Director's Decision DD-82-11 in matter of Rochester Gas & Electric Corp HdYLE, JC Office of the Secretary of the Commission. DD-82-11 B2/11/16 DICKWITL Office of the General Counsel ip R2281 241 24X Fiche 50-000.63/12/14.8402160003
- --8402160348 Discusses SECY-83-105 re energy technology comparability study
 CHILK, 8 J Office of the Secretary of the Commission 83/
 DIRCKS, W Office of the Executive Director for Operations
 22281, 278. 24% Fichs, 50-000, 83/12/14, 8402160003 83/04/04
- --8402160349 Discusses SECY-81-582 re NUREG-0737, Item II F 2 concerning addl instrumentation for detection of inadequate core cooling CHILK, 9 J Office of the Secretary of the Commission S81-582 81/11/16. DIRCKS, W. J Office of the Executive Director for Operations ip 22281, 242, 24% Fiche 50-000, 83/12/14, 8402160003
- --8402i60330 Discusses SECV-83-ii6 re approval of proposed license to export high enriched U to Japan CHILK, S.J. Office of the Secretary of the Commission. 83/04/i3 DIRCKS.W Office of the Executive Director for Operations ip 22281 279 24X Fiche: \$0-000,83/12/14,8402160003
- --8402160332 Discusses SECY-B2-446 re proposed retransfer of math for reprocessing from Japan to United Kingdom & France CHILK: B.J. Office of the Secretary of the Commission. 82/11/18 DIRCKB: W.J. Office of the Executive Director for Operations ip 22281 243 24X Fiche 50-000.83/12/14.8402160003.
- --8402160354 Discusses SECY-83-70 re FDIA Appeal 83-A-1 on Ofc of Inspector & Auditor rept on former Region III employee CHILK, S U Office of the Secretary of the Commission 83/04/18 PLAINE, H H. Office of the General Coursel 1p, 22281 280 24) Fiche: 50-000, 83/12/14,8402160003

- --8402160355 Staff requirements meno re 821112 discussion of Commission
 - action in Washington,DC CHILK,S J Office of the Secretary of the Commission H821112C 82/11/18 DIRCKS,W J Office of the Esscutive Director for Operations 1p 22281 244 24X Fiche 50-000,83/12/14.8402160003
- --8402160357 Discusses SECY-83-127 re interpretation of Commission 820630 rule suspending environ qualification deadline CHILK.S J Defice of the Secretary of the Commission 83/04/19 FLAINE.H H Office of the General Counsel 1p 22281 281 24 Fiche 50-000.83/12/14.8402160003
- --8402160360 Discusses SECY-82-417 re proposed rev to 10CFR810 CHILK.S J Office of the Secretary of the Commission 82/11 DIRCKS.W J Office of the Executive Director for Operations 22281 245 24X Fithe 50-000,83/12/14,8402160003 89711799
- --8402160361 Discusses SECY-82-375 re low enriched U reform amends CHILK.S J Office of the Secretary of the Commission 82/11/23 DIRCKS.W J Office of the Executive Director for Operations 1; 22281 246 248 Fiche 50-000.83/12/14.8402160003
- --8402160363 Discusses revised SECY-82-69 re proposed retransfer of matl for reprocessing from Spain to United Kingdom CHILKIS J Office of the Secretary of the Commission 82/03/15 DIRCKESW J Office of the Executive Director for Operations 1p 22281 166 24X Fiche 50-000.83/12/14/8402160003
- ~-8402160364 Discusses SECY-82-461 re FOIA Appeal 82-A-21 on rules for environ qualification CHILLS J Office of the Secretary of the Commission 82/12/08 BICKHIT.L Office of the General Counsel 1p 22281 247 24X Fiche \$0-000,83/12/14,8402160003
- --8402160365 Discusses SECY-83-112 re proposed 10CFR53, "Criteria & Procedures for Determining Adequaty of Available Spent Nuclear Fuel Storage Capacity"
 CHICKE, S. J. Office of the Secretary of the Commission 83/04/20 DIRCKS, N. Office of the Executive Director for Operations 1p 22281 282 24x Fiche 50-000.83/12/14,8402160003
- --8402160368 Staff requirements memo discussing possible 821222 vote on actions re facility in Washington.DC
 CHILK.S J Office of the Secretary of the Commission H821222C
 S2/12/23 Defice of the Secretary of the Commission ip
 22281 248 24X Fiche 50-000.83/12/14.8402160003
- --8402160375 Discusses SECY-82-93 re license amend for proposed exports of dispersed tritium to add1 destinations

 CHILK.S J Office of the Secretary of the Commission S82-93

 82/03/15 DIRCKS.W J Office of the Executive Director for

 Operations 1p 22281 167 24X Fichs 50-000,83/12/14,8402160003
- ~~8402160376 Discusses SECY-83-147 re immediate affectiveness decision HOYLE, J C Office of the Secretary of the Commission 83/05/05 PLAINE, H H Office of the General Counsel ip 22281 283 24X Fiche 50-000, 83/12/14,8402160003
- --840.2160.377 Discusses SECY-82-80 re review of ALAB-665 in matter of Florida Power & Light Co (denial of late antitrust intervention)
 CHILK.8 J Office of the Secretary of the Commission S82-80
 82/03/16 BICKWIT.L Office of the General Coursel ip 22281 168 24X Fiche 50-000,83/12/14,8402160003
- --8402160380 Discusses SECY-82-469 re planned reorganization of McDermott Inc.parent of 8%W CHILK, S J Office of the Secretary of the Commission 82/12/14 DIRCKS. W J Diffice of the Executive Director for Operations 1p 22281 250 24% Fiche 30-000,83/12/14.8402160003
- --8402160383 Discusses SECY-83-137 re proposed response to EPA on proposed environ stds mgt & disposal of high level spent nuclear fuel & transumante wastes CHILK.8 J Office of the Secretary of the Commission 83/03/12 DIRCKS.W Office of the Executive Director for Operations ip 22281 284 24X Fiche 50-000,83/12/14,8402160003
- --8402160384 Staff requirements memo re 821216 discussion/possible vote on contested issues in full-power proceeding in Washington, DC.

 CHILK, S. J. Office of the Secretary of the Commission M8212168 82/12/20 ZERBE, J.E. Office of Policy Evaluations BICKWIT, L. Office of the Seneral Counsel ip 22281 231, 24X Fiche 50-000, 83/12/14, 8402160003
- --8402160388 Discusses SECY-83-164 re approval of proposed license to 102100388 Discusses SeLY-63-10+ TF approval of proposed license to export low enriched U to Norway CHILK, S J Office of the Secretary of the Commission 83/05/17 DIRCKS. H Office of the Executive Director for Operations 1p 22281.285 24X Fiche 50-000.83/12/14.8402160003

- --8402160389 Discusses SECY-82-427 re Commission options in developing final technical criteria for disposal of high level waste in geologic repositories CHICK, S. J. Dffice of the Secretary of the Commission. B3/01/04 DIRCKS W Office of the Executive Director for Operations ip 22281 252 24X Fiche 50-000.83/12/14.8402160003
- ~-B402160393 Discusses SECY-B2-3B4A re status of TMI-1 NURCQ-0737 14166
 CHILK,S J Office of the Secretary of the Commission 83/01/03
 DIRCKS,W Office of the Executive Director for Operations 1p.
 2281 253 24X Fiche 50-000, 83/12/14, 8402160003
- --8402160394 Discusses SECY-83-125 re immediate effectiveness dactains review of ALAB-713
 CHILK,8 J Defice of the Secretary of the Commission ALAB-713
 83/05/19 PLAINE,H H Office of the General Coursel IP
 22281 286 24X Fiche 50-000,83/12/14,8402160003
- --8402140397 Discusses SECY-82-308 re Manual Chapter O502, "NRC Inchiral Response Plan"
 CHILK, S.J. Office of the Secretary of the Commission 83/01/05 DIRCKS, W. Office of the Executive Director for Operations 19 22881 254 24X Fiche, 50-000, 83/12/14, 8402160003.
- --8402i6039B Discusses SECY-83-172 re U mill tailings regulations on proposed suspansion of selected provisions CHILK, S.J. Defice of the Becretary of the Commission B3/05/20 DIRCKS, W. Office of the Executive Director for Operations is 22281 287 24X Fiche 50-000,83/12/14,8402160003
- --8402160401 Discusses SECV-83-68 re objective performance indicators for evaluation of Agreement State radiation control programs.

 GHILK.S J Office of the Secretary of the Commission. D3/05/26
 DIRCKS,W Office of the Executive Director for Operations 19
 22281 288 24X Fichs 50-000,83/12/14,8402160003
- --8402160402 Discusses SECY-82-476 re FDIA Appeal 82-A-23 on Committee consideration of requests for hearing on extension of CFs CHILK.8 J Office of the Secretary of the Committeion. BJ/01/12 Office of the Secretary of the Committeion. BJ/01/12 Fiche 50-000,83/12/14,8402160003
- --8402160406 Discusses SECY-83-44 re development of scope of guidelines to facilitate recovery efforts in event of nuclear-related accidents at operating power plants
 CHILK, 8 J Office of the Secretary of the Commission. 83/05/27
 DIRCKS, W Office of the Executive Director for Operations. 8p.
 22281 289 24X Fiche 50-000,83/12/14,8402160003.
- --8402160407 Discusses SECY-83-7 re immediate effectivemess decision in
- --8402160409 Discusses SECY-83-175 re FDIA appeal on misadminstration reporting rule
 CHILK, S J Office of the Secretary of the Commission. 83/06/01
 PLAINE, H H Office of the General Counsel, 1p. 22281:290 24
 Fiche 50-000.83/12/14,8402160003.
- --9402160411 Piscusses SECY-82-67 re proposed minor exports of 402160411 Discusses SEGY-8x-o/ re proposed minor to Brazil.
 CHILK:S.J. Office of the Secretary of the Commission. B82-67
 82/03/22 DIRCKS.H.J. Office of the Executive Director for
 Operations. Ip 22281,169, 24X Fichs: 50-000, B3/12/14, B402160003
- -8402140412 Discusses SECY-83-10 re psychological strees, litigation regions Discusses SECY-83-10 to psychological strates, little strates, in Park vs NRC
 CHILKS J Office of the Secretary of the Commission. 83.
 DIRCKS, W Office of the Executive Director for Operations.
 ROTHSCHILD. I B Office of the General Counsel 1p. 2228
 24X Fiche 50-000,83/12/14,8402160003.
- --B402160413 Discusses SECY-B3-187 re proposed licenses to export components to mixed oxide fuel fabrication facilities in Balgium & Federal Republic of Garmany.
 CHILK, U. Office of the Secretary of the Commission B3/06.
 DIRCKS, W. Office of the Executive Director for Operations 12281 291 24X Fichs 50-000,83/12/14,8402160003. 83/06/06
- --8402160416 Discusses SECY-83-9 re proposed transfer of reprecessing technology to Japan under 10CFR810

 CHILK, 8 J Office of the Secretary of the Commission. 83/01/24

 DIRCKS.W Office of the Executive Director for Operations. 19

 22281 258 24X Fiche 50-000,83/12/14,8402160003

- --8402160418 Discusses SECY-83-123 re proposed amends to 10CFR Parts 40.70 & 73 on implementing provisions of convention on physical protection of nuclear mat! CHILK, 3 J Office of the Becretary of the Commission 83/06/09 DIRCKB.W Office of the Executive Director for Operations 1p 22281 272 24X Fiche 50-000,83/12/14,8402160003
- --8402160420 Discusses SECY-82-81 re AO recommendation on seismic design errors CHILK, B.J. Office of the Secretary of the Commission 882-81 82/03/23 DIRCKS, W.J. Office of the Executive Director for Operations ip 22281
- --B402160421 Discusses SECY-82-477 re amend to 10CFR140 on removal of apps from regulations
 CHILK, S. J. Office of the Secretary of the Commission 83/01/31
 DIRCKS, M. Office of the Executive Director for Operations 1p
 22281 257 24X Fiche 50-000,83/12/14,8402160003
- --8402160422 Discusses SECY-83-179 re emergency operations facility CHILK.8 J Office of the Secretary of the Commission 83/06/09 DIRCKS,W Office of the Executive Director for Operations 1p 2281 273 24X Fichs 50-000,83/12/14,8402160003
- --8402160425 Discusses SECY-83-126 re amend to 10CFR90, Chapter I w/
 respect to employees who provide info
 CHILK, B J. Office of the Becretary of the Commission 83/06/13
 DIRCKS, W Office of the Executive Director for Operations ip
 22281 294 24X Fiche 50-000,83/12/14,8402160003
- --8402160426 Discusses SECY-82-498 re withdrawal of proposed rule to codify NUREQ-0737 requirements for OL applicants CHILK, 8. J Office of the Secretary of the Commission 83/02/01 DIRCKS, W Office of the Executive Director for Operations ip 22281 260 24X Fiche 50-000,83/12/14,8402160003
- --8402160427 Discusses SECY-82-96 re proposed retransfer of matl for reprocessing from Japan to United Kingdom CHILK.8 J Office of the Secretary of the Commission SB2-96 82/03/23. DIRCKS, J Defice of the Executive Director for Operations ip 22281 171 24X Fiche 50-000,83/12/14,8402160003
- --8402160428 Discusses SECY-83-141 re withdrawal of proposed rule eliminating opportunity for hearing for operator license applicants who fail test
 CHILK.8 J Office of the Secretary of the Commission 83/06/16
 DIRCKB,W Office of the Executive Director for Operations 1p
 22281 295 24X Fiche 50-000,83/12/14.8402160003
- ---B402160430 Discusses third FOIA Appeal 82-426 re environ qualifications CHILK, S J Dffice of the Becretary of the Commission 83/02/01 MALSCH, M Dffice of the General Counsel 1p 22281.261. 24X Fiche: 50-000, 83/12/14, 8402160003
- --B402160431 Discusses SECY-B3-153 re proposed amend to 10CFR50, App E on frequency of emergency preparedness exercises CHILK, B J Office of the Becretary of the Commission 83/06/23 DIRCKB, M. Office of the Executive Director for Operations 1p 22281:297 24X Fiche. 50~000, 63/12/14, 8402160003
- ---8402160434 Discusses SECY-82-100 or proposed retransfer of mat1 for reprocessing from Japan to France CHILK, B J. Office of the Secretary of the Commission. 682-100 82/03/23 DIRCKS, W J. Office of the Executive Director for Operations. 1p. 22281 172. 24X Fiche 50-000,83/12/14,8402160003
- --8402160435 Discusses SECY-83-201 re publication of revised Criterion 9 for guidance of states & NRC in discontinuance of NRC regulatory authority & assumption thereof by states through agreement.

 CHILK, S. J. Diffice of the Secretary of the Commission S2/06/28 DIRCKS, W. Office of the Executive Director for Operations. 1p. 22281.298. 24% Fiche 50-000,83/12/14.8402160003.
- --8402140436 Discusses licensed fuel facility status rept inventory difference data, NUREQ-0430, Vol 1, No 3, Jul 1982-Dec 1982 CHILK, B. J Diffice of the Secretary of the Commission 83/07/29 DIRCKS.W Office of the Executive Director for Operations. 1p 28281:279 24X Fichs. 50-000, 83/12/14, 8402160003
- ---8402160439 Discusses BECY-83-195 re staff comments on EPA proposed stds for U & thorium mill tallings at licensed commercial processing sites.

 CHILK, B J Office of the Secretary of the Commission 83/06/30 DIRCKS, W. Office of the Executive Director for Operations ip. 22281-300 24X Fiche: 50-000, 83/12/14, 8402160003.

- --8402140440 Discusses SECY-82-86 me nuclear power plant staff working hours
 CHILK, S J Defice of the Secretary of the Commission B2/03/26
 DIRCKS, W J Defice of the Executive Director for Operations 1p 22281 173 24X Fichs 50-000, B3/12/14, 8402140003
- --8402160441 Discusses SECY-82-487 re licensing of gunsights illuminated by byproduct mat!
 CHILK, B. J. Office of the Secretary of the Commission 83/06/30
 DIRCKS,W. Office of the Executive Director for Operations 1p
 22281 301 24X Fiche 50-000,83/12/14,8402160003
- ---8402160442 Discusses SECY-83-52A re final rulemaking concerning licensed operator staffing at nuclear power plants & draft policy statement of shift crew qualification CHILK.B J Office of the Secretary of the Commission 83/07/06 DIRCKS.H Office of the Executive Director for Operations ip 22281 302 24X Fiche 50-000, 83/12/14.8402160003
- --8402160443 Discusses SECY-82-109 re forthcoming vacancy on ACRE CHILK.S J Defice of the Secretary of the Commission 82/03/30 FRALEY.R F ACRS - Advisory Committee on Reactor Safeguards 1p 222B1 174 24X Fiche 30-000,83/12/14.8402160003
- --B402140444 Discusses SECY-B3-237 re life-of-reactor fuel export licenses CHILK, 8 J Office of the Secretary of the Commission, 83/07/06 DTRCKE, W Dffice of the Executive Director for Operations ip 22281 303 24X Fiche 50-000,83/12/14,8402140003
- --8402160445 Discusses SECY-82-44 re Oft of Inspector & Auditor CY82 audit plan chikk, B J Office of the Secretary of the Commission 82/03/31, CUMMINGS, J J Office of Inspector & Auditor ip 22281 175 24/ Fiche 50-000,83/12/14,8402160003
- --8402160446 Discusses SECY-83-263 re Sunshine Act review of transcript of B30519 closed Commission meeting CHILK,8 J Office of the Becretary of the Commission 83/07/08 PLAINE.H H Office of the General Counsel ip 22281 304 24% Fiche 30-000.83/12/14,8402160003
- --B40216044B Discusses BECY-83-262 re review of ALAB-720 in matter of GE GHILK, B J GPfice of the Becretary of the Commission ALAB-720 B3/07/22 PLAINE, H !! Office of the General Counsel 1p 242 Fiche 50-000.B3/12/14.8402160003
- B402170197 Responds to FDIA request for documents re 1983 enforcement correspondence addressed to George Washington Univ Medical Ctr. Mashington DC Info partially deleted (ref FDIA Exemption 6)
 FELTON. J M Division of Rules and Records 83/12/01 ERNSTTHAL, H Society of Nuclear Medicine 2pp 22320 130
- E402170200 FDIA request for 1983 enforcement correspondence to Osorga Mashington Univ Medical Ctr. Mashington. DC ERNSTTHAL.H Bocisty of Nuclear Redicine B3/10/12 Office of Administration 1p. 2320 152
- B402170208 Becond partial response to FDIA request for documents re incident described in Encl B.Page 2 of weekly info rept for wk ending B31007 App A info partially withheld (ref FDIA Exemption 6) & App B info withheld (ref FDIA Exemption 5). FELYON, J M Division of Rules and Records B3/11/28 BHOLLY, B C Union of Concerned Scientists App 22319 350 24% Fiche 50-250, 83/11/28, 8402170208
- --8402170212 Lists status of several items discussed in 831005 mgt mesting re containment spray valve misalignment Info deleted Related info encl YAEGER, H E Florida Power & Light Co 83/10/07 HARRIS, K N Florida Power & Light Co. 7pp 22319 354 24X Fiche 50-250,83/11/28,8402170208
- 8402170215 FOIA request for proceedings re alteration of radiographs of welds or other cases of fraud involving welding at nuclear reactors.

 ROMAND, F. R. Air and Hater Pollution Patrol 83/11/07 NRC No Detailed Affiliation Given ip 22320 248.
- 8402170217 Responds to FOIA request for proceedings re-alteration of radiographs of walds or other cases of fraud involving welding at nuclear reactors. Forwards App A documents Info also available in PDR FELTON, J M Division of Rules and Records 83/12/01 ROMANO, F R Air and Water Pollution Patrol. 2pp. 22320 249

- --8402170219 Forwards IE Bulletin 82-01, "Alteration of Radiographs of 90R170219 Forwards IE Bulletin 82-01, "Alteration of Radiographs o Welds in Piping Bubassemblies" JORDAN.E L Radiological Safety, Safeguards & General Programs Section IED-82-01 82/03/30 HAYNES,R C Region i, Office of Director O'REFLLY,J P Region 2, Office of Director MEPPLER,J G Region 3, Office of Director 3pp 22320 251
- 8402170222 Second partial response to FOIA request for six categories of documents re facility Review of addl documents incomplete FELTON. J M Division of Roles and Records 83/12/01 ANDERSON, S I Garvey, Schubert, Adams & Barer 1p 22313 252 24X Fiche 50-000.83/12/01,8402170222
- 8402170226 FDIA request for six categories of documents re facility, including const authorization application, NRC procedure to authorize const & hearing transcripts
 ANDERSON.S I Garvey, Schubert, Adams & Barer 83/09/28 Office of Administration 2pp 22313 253 24% Fiche. 50-000, 83/09/28, 8402170226
- B402170447 FUIA request for SECY-B3-339 & D Eisenhut B30819 EER re Westinghouse Owners Group generic reactor trip breaker shunt trip design FEDRO, J NVS Corp CD-18-83-014 B4/01/05 Division of Rule and Records 1p 22320
- 8402170449 Responds to FDIA request for SECY-83-339 & SER for Westinghouse Dwners Group generic reactor trip breaker shout trip design Forwards SER Request for SECY-83-339 undergoing Commission review to determine releasability FELTON, J M Division of Rules and Records 84/01/27 PEDRD, J NUS Corp Ip 22320 129
- --8307120033 Forwards SER on Westinghouse Owners Group generic design mod to provide automatic reactor trip sys actuation of breaker shunt trip attachments Design acceptable Plant-specific design info will be required for implementation. EISENNUT.D 0 Division of Licensing CL-83-28 83/09/10 SHEPPARD, J J Consumers Power Co 24pp. 22320 124
- B402170452 FOIA request for info re 1950s nuclear accident in Soviet Union.

 JOHNBON H Affiliation Not Assigned 83/01/16. NRC - No Detailed Affiliation Given 1p 22318:353
- 8402170454 Responds to FOIA request for info re 1930s nuclear accident in Soviet Union Documents available in FDR M/o stated encls FELTON.J M Division of Rules and Records 84/01/27 JOHNSON.H Affiliation Not Assigned ip 22318 354
- 8402170437 Appeals denial of FOIA request for documents re R Gunderson & M Royce allegations Agency may not maintain secret law & any rulings or legal opinions must be disclosed (ref 1990 "Taxation M/Representation v IRB")
 BERNABEIL Government Accountability Project 83/12/05
 FELTON, J M Division of Rules and Records, ip 22305:337
- 8402170459 Responds to appeal re denial of FOIA request for documents concerning R Quaderson & W Royce allegations Request denied, Documents entirely withheld (ref FOIA Exemption 5) DIRCKS, M. J. Office of the Executive Diractor for Operations 84/01/31. BERNABEI, L. Government Accountability Project 1p 22313 338 24% Fiche 50-528,84/01/31,8402170459
- 8402170461 FOIA request for minutes of second corporate mgt meeting on 831018 re facility supplemental cooling availability.
 8UGARHANARJ Sugarman & Denworth 83/12/14 STAROSTECKIA.
 Division of Project & Resident Programs 2pp 22305, 348. 24x
 Fiche 50-352,83/12/14,8402170461.
- 8402170465 Responds to FOIA request for minutes of second corporate mas meeting on 831018 re supplemental cooling water sys for facility.NRC has no documents subj to request FELTON. J M Division of Rules and Records. 84/01/27. 8U6ARMAN.R Sugarman & Denworth. 1p. 22005 347 24X Fiche: 50-352,84/01/27,8402170465 84/01/27, SUGARMAN, R J.
- 8402170470 FOIA request for three categories of documents re ECCS actuation. WEISS.E.R Union of Concerned Scientists 84. Division of Rules and Records 1p. 22305 344 84/01/04 FELTON, J
- B402170474 Responds to FOIA request for three categories of documents re ECCS Documents subj to request available in PDR. FELTONI JM Division of Rules and Records. IEB-79-06A 84/01/30 WEISS, E R Union of Concerned Scientists 1p. 22305 343

- B402210003 Further response to FOIA request for documents re IE Insp Rept 79-19 & associated notice of proposed imposition of civil penalties, notice of violation & order to show cause Forwards App A documents Addl records being reviewed FELTON, J M Division of Rules and Records B3/11/29 HAMLIN, J B Shaw, Fittman, Potts & Troubridge Dpp 22343 005 24X Fiche 50-498,83/11/29,8402210003
- --Si0ii30714 Discusses South TX Project Investigation 79-19 re GA programmatic breakdown & conducting extensive investigations Provides constructive comments to improve Threatigations Provides Constructive Comments to improve future NIC investigations PHILLIPS: H 8 Region 4, Dallas, Office of the Director. 80/07/21 SEIDLE: N C Region 4, Dallas, Reactor Construction & Engineering Support Branch 5pp 22343 081 24% Fiche 50-498, 83/11/29. Support Branch 8402210003
- --8402210006 Notification of B00819 technical meeting w/util & Root.Inc in Bay City, TX to clarify util response to 800430 order to show cause why all safety-related work at const site should not be stopped Bupporting documentation encl. * NRC No Detailed Affiliation Given. B3/11/29 NRC Detailed Affiliation Given 47pp 22343,011. 24X Fiche 50-498,83/11/29,8402210003
- --8402210012 Forwards 8 Phillips 800721 memo to Seidle re IE
 Investigation Rept 79-19, lessons learned, 8 Phillips comments
 constructive & worthy of consideration,
 SEYFRIT,K V. Region 4, Dallas, Office of the Director 80/08/13
 STELLO,V Defice of Inspection & Enforcement, Office of the
 Director ip, 22343,080, 24X Fiche, 50-498,83/11/29,8402210003
- --8402210017 Forwards info concerning assignment of responsibilities & priorities for Region IV followup of items re facilities show cause order W/a encl
 8EIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch. 80/09/12 SHEWMAKER, R E. NRC No Detailed Affiliation Given 1p 22343 OB6 24x Fiche 50-498,83/11/29,8402210003
- -8402210018 Forwards summary of addit commitments made at 800819 public meeting w/util & Brown & Root, Inc & correlation of util listing to NRC transcript of meeting, in response to show cause order HUBACEK, W @ Region 4, Dallas, Office of the Director. 80/09/25 SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 2pp 22343.087 24X Fiche.50-498,83/11/27,8402210003 Support Branch 8402210003
- --8402210020 Submits status rept for 800703-1017 of followup activities associated w/facility order.per 800624 memo SEYFRIT.K V. Region 4. Dallas. Office of the Director. 80/10/20 THORNBURGH D NRC No Detailed Affiliation Given 2pp 22343:131 24X Fiche:50-498,83/11/29,8402210003.
- --8402210027 Submits four recommendations relative to closing open item & allowing restart of safety-related activities at facility, per show cause order PHILLIPS, H. Region 4, Dallas, Office of the Director 80/10/23. SEYFRIT, K.V., NRC No Datailed Affiliation Given 3pp. 22343 i41. 24% Fiche: 50-498,83/11/29,8402210003.
- ---8402210031 Notifies that show cause items VA(2)(c) & VA(10) still open.per IE Insp 80-30 Add info required.
 TAPIA.J I Region 4. Dallas, Office of the Director 80/11/20 HALL.R E. CROSSMAN,W A. HUBACEK.W G. Region 4. Dallas, Office of the Director. 1p 22343:144 24X Fiche 50-498.83/11/29, 8402219003
- -B402210036 Notifies that inquiries received re availability of investigation rept. Investigation rept will be placed in facility LPDR four extra copies of rept. Including , enforcement package: should be sent to LPDR. HAYES.D.W. Region 3. Chicago. Office of the Director. 80/05 THORNBURG!H D. Division of Reactor Construction Inspection. 22343,145 24X Fiche 50-498,83/11/29,8402210003. 80/05/07.
- --8402210040 Submits status rept for 800721-0705 re followup activities associated w/facility show cause order, in response to 800604 memo, Supporting details of followup described in BEYFRIT, K V Region 4, Dellas, Office of the Director. 80/09/10 THORNBURG, H D Division of Reactor Construction Inspection, 10p; 22343,152 24X Fiche 50-498.83/11/29,8402210003.
- --B402210046 Confirms B10129 telcon re substitution of ABME welding identified in 10-wk work plan sent to NRC on B01217. Welding identified in reactor containment bldg will be delayed. Attachment lists welding to be substituted.

 DPREA.0 W Houston Lighting & Power Co. BT-HL-AE-621. B1/02/18EYERIT, M. Region 4, Dallas, Office of the Director 5pp. 22343, 176. 24X Fichs. 50-498, 83/11/29, 8402210003. 81/02/12

- --B40221004B Ack receipt of 810212 ltr transmitting documentation re substitution of ASME welding identified in 10-wk work plan, in response to NRC 800430 order to show cause SEIDLE, M.C. Region 4, Dallas, Office of the Director (81/03/01) B1/04/02 OPREA, 0 W Houston Lighting & Power Co 1p 22343.181 24X Fiche B0-498.B3/11/29,8402210003
- --B402210049 Ack receipt of 810331 ltr transmitting documentation re resumption of safety-related ASME welding, in response to NRC 800430 order to show cause SEIDLE, W C. Region 4, Dallas, Office of the Director (81/03/01) 81/04/03 OPREA, O W Houston Lighting & Power Co 1p 22343 183 24X Fiche 30-498,83/11/29,8402210003
- --B402210051 Requests immediate action to release ABME safety-related welding identified on Attachment 1 Work plan identifying ABME production welding will be initiated during 12-wk pariod Attachment 1 work will be started on 810330 OPREA: 0 W Houston Lighting & Power Co ST-HL-AE-642 81/03/25 BEVFRIT. K. Region 4. Dallas. Office of the Director (81/03/01) 3pp. 22343, 184 24% Fiche 50-478.83/11/27,8402210003
- --8402210064 Atk receipt of 810325 ltr transmitting documentation re 12-wk work plan concerning ASME safety-related welding, in response to NRC 800430 order to show cause SEIDLE, H C. Region 4, Dallas, Office of the Director (81/03/01) 81/04/03 DPREA, G W. Houston Lighting & Power Co ip. 22343:187. 24% Fiche, 50-498, 83/11/27, 8402210003
- --8402210048 Forwards "Final Rept of Review of Safety-Related Concrete," performed in response to Item 3(b) of NRC 800430 show cause order Four-phase program listed W/o encl.

 OPREA, O.W. Houston Lighting & Power Co. ST-HL-AE-650 81/04/09 BEYFRIT, K. Region 4, Dallas, Office of the Director (81/03/01) 4pp, 22343, 196, 24X Fiche 50~498, 83/11/29, 8402210003
- 8402220121 FOIA request for documents used by NRC in preparing chart, "Summary of Proposed Civil Penalties" & records disclosing why number of civil penalties proposed by NRC increased between 1977-80, Chart encl.

 BAMP, R. A. Bhaw, Pittman, Potts & Trowbridge, 84/01/18 FELTON, J M Division of Rules and Records. 3pp 22346 313
- 8403220123 Responds to FOIA request for documents used by NRC in preparing chart, "Summary of Proposed Civil Penalties" & records disclosing why number of civil penalties proposed by NRC increased between 1979-80 Forwards listing of penalties FELTON, J. M. Division of Rules and Records 84/02/09 SAMP, R. A. Bhaw, Pittman, Potts & Trowbridge 1p. 22346.316
- --B402220124 "Civil Penalties" e NRC - No Detailed Affiliation Given 84/02/09. 39pp 22346:317.
- 8402220127 FOIA request for documents re replacement of piping at facility.

 BELL,N. Nuclear Information & Resource Service, 84/01/05 Office of Administration, 2pp. 22363;233 24X Fiche: 50-220, 84/01/05, 8402220127.
- 8402220130 Partial response to FOIA request for documents re replacement of piping at facility. Forwards App B documents. App A & B documents available in PDR FELTON. J. M. Division of Rules and Records 84/01/23 BELL.N Nuclear Information & Resource Service. 4pp. 22363-235 24X Fiche: 50-220.84/01/23,8402220130
- ---8402220132 "Quarterly Task Person Rem Rept: Apr-June 1982 " W/820730 ltr. LEMP9E6: T. E. Niagara Mohawk Power Corp. 82/06/30 EISENHUT: D G. Division of Licensing. 23pp. 22363.239. 24X Fiche: 50-220,84/01/23,8402220130.
- --8402220135 Summary of 820422 meeting w/util re decontamination of recirculation sys.ALARA considerations & removal & replacement of safe-ands. Related info encl.
 FDLM.P J Operating Reactors Branch 2. 82/04/30 Operating R
- 8402220139 FDIA request for Feb 1982 IE Insp Rept 50-397/82-05 & related documents concerning Bechtel review of generic problem areas.

 BELLIN Committee for Bafe Power. 83/11/01 Diffice of Administration, 1p. 22363:304. 24X Fiche:50-397,83/11/01, 8402220139
- --B402220142 Requests thorough file check for IE Insp Rept 50-397/82-05 & related into concerning Bechtel review of NRC repts NRC may have retained rept or portion of rept:
 BELL.N Coalition for Bafe Power. 83/11/01. FELTON.J.M. Office of Administration. 1p. 22363:305 24X Fiche:50-397,83/11/01, B402220139.

- B402220144 Responds to FOIA request for IE Insp Rept 30-397/82-05 & related documents concerning Bechtel review Forwards App A documents
 FELTON, J M Division of Rules and Records 83/12/07 BELL, N Coalition for Safe Power 2pp 22363 306 24x
 Fiche 30-397,83/12/07.8402220144
- --8402220147 Excerpt from QVP overview rept, Vol 1, Book 1 of 1 Related info enc1

 * Bechtel Corp 83/12/07 150pp 22363 308 24X
 Fiche 50-397, 83/12/07, 8402220144
- 8402220149 FOIA request for listed LERs to be placed in PDR JEFFERSON, G A Affiliation Not Assigned 83/11/17 NRC No Detailed Affiliation Given 5pp 22380 047 24X Fiche 50-000, 83/11/17. 8402220149
- 8402220154 Responds to FOIA request that 146 LERs be placed in PDR Forwards LERs listed on app Documents also available in PDR Remaining LERs were either canceled or not issued FELTON, J M Division of Rules and Records 83/11/30.

 JEFFERSON, O A Affillation Not Assigned. 2pp 22380 052 24X Fiche 50-000,83/11/30,8402220154
- --B402220165 LER 82-094/03L-0 on 820815, reactor coolant hat leg sample trip valves TV-85-106A & B failed to close after chemists completed taking RGS sample Cause not determined Manual isolation valve i-85-16 closed W/820914 ltr WILSON.J L. Virpinia Electric & Power Co 82-066 82/09/14 0/REILLY.JP Region 2. Office of Director 3pp 22380 116 24X Fiche 50-000, 83/11/30, 8402220134
- B402230354 FOIA request for info re total expenditure on Contract FIN A-1123, beginning & termination date & breakdown of expenditures by major subcontracts & computer charges RILEV.J L. Affiliation Not Assigned FIN A-1123 83/09/13 FELTON.J M Division of Rules and Records 1p 22378 04B
- 8402230357 Responds to FOIA request for records which indicate total expenditure on Contract FIN A-1123, beginning & termination date of contract & breakdown of expenditures by major subcontracts & computer charges
 FELTONJ M. Division of Rules and Records FIN A-1123 84/01/31
 RILEY: J L Affiliation Not Assigned 1p 22378 049
- --B402230360 Forwards DDE Voucher 02821133 for review & signature Response requested within 5 days DAMDUI8,D B Financial Operations Brench, FIN A-1123-1. 82703708 MMLER,D Assistant Director for Environmental Technology (Fre B30201) 4pp. 22378 050,
- --8402230342 Forwards DOE Voucher 01820852 for review & signature Response requested within 5 days W/o encl DANDOIS,D 8 Financial Operations Branch FIN A-1123-1 82/03/02 MULLER,D Assistant Director for Environmental Technology (Pre 830201) 1p 22378 054
- --8402230365 Forwards DOE Voucher 12820386 for review & signature Response requested within 5 days.

 DANDOIR, D B Financial Operations Branch. FIN A-1123-1.

 82701722. MULLER, D. Assistant Director for Environmental Technology (Pre 830201) 3pp 22378.055
- --8402230368 Forwards DOE Voucher 11820209 for review & signature Response requested within 5 days

 pANDOIS, D B, Financial Operations Brench. FIN A-1123-1.
 82/01/19 MULLER:D Assistant Director for Environmental Technology (Pre 830201). 4pp. 22378 058
- ---8402230370 Forwards DDE Voucher 09813261 for review & signature Response requested within 5 days, DANDOIG, D B Financial Operations Branch FIN A-1123-1 81/11/30, MULLER D. Assistant Director for Environmental Technology (Pre 830201) 3pp 22378.062.
- --8402230372 Forwards DDE Voucher 08812410 for review & signature Response requested within 5 days. DANDDIG.D.B Financial Operations Branch. FIN A-1123-1 B1/07/18. MULLER.D Assistant Director for Environmental Technology (Fre 830201) 4pp 22378 045
- ---B402230374 Forwards DDE Voucher 07812136 for review & signature Response requested within 5 days DANDDIS, D B. Financial Operations Branch FIN A-1123-1. B1/07/18 MULLER.D. Assistant Director for Environmental Technology (Pre 830201). 3pp. 22378.069
- --8402230377 Forwards DOE Voucher OAB11743 for review & signature. Response requested within 5 days. DANDOIS, D B. Financial Operations Branch. FIN A-1123-1. B1/07/16 NRC - No Detailed Affiliation Given 4pp 22378-072

- --B402230379 Forwards DDE Vouther 03811556 for review & signature Response requested within 5 days DANDO(6, D. 8 Financial Operations Branch FIN A-1123-1 81/06/18 NRC - No Detailed Affiliation Given 4pp 22378 076
- --8402230383 forwards DDE Voucher 04811282 for review & signature Response requested within 5 days DANDOIS:D B Financial Operations Branch FIN A-(123-0 B1/06/09 MULLER:D R Assistant Director for Environmental Technology (Pre 830201) 3pp 22378 080
- --8402230387 Forwards DOE Voucher 03811061 for review & signature Response requested within 5 days DANDO18, D B. Financial Operations Branch FIN A-123-D 81/04/27 MULLER, D R Assistant Director for Environmental Technology (Pre 830201) 3pp 22378 083
- --8402230390 Forwards DDE Voucher 02810751 for review & signature Response requested within 5 days DANDOIS,D B Financial Operations Branch FIN A-1123-0 81/03/30 MULLER,D R Assistant Director for Environmental Technology (Pre 830201) 3pp 22378-086
- ~-8402230393 Forwards DOE Voucher 01810663 for review & signature Response requested within 5 days DANDOIS,D B. Financial Operations Branch FIN A-J123-0 B1/02/24 MULLER.D R Assistant Director for Environmental Technology (Fre 830201). App 22378 089
- --8402230394 Forwards DOE Voucher 12810359 for review & signature Response requested within 5 days DANDOIS.D B Financial Operations Branch FIN A-1123-0. 91/01/30 MULLER.D R Assistant Director for Environmental Technology (Pre 830801) 3pp 22378.093
- --8402230400 forwards DDE Voucher 12810361 for review & signature Response requested within 5 days PANDOIS, P 8 Financial Operations Branch FIN A-1123-0 81/01/30 MULLER, D R Assistant Director for Environmental Technology (Pre 830201) 3pp 22378 096
- ~-8402230402 Forwards DDE Voucher 11810102 for review & signature Response requested within 5 days DANDDIB;D B Financial Operations Branch FIN A-1123-0 81/01/30 MULLER;D R Assistant Director for Environmental Technology (Fre 830201) 3pp 22378 099
- 8402230391 FOIA request for IE Bulletin 83-06.in connection w/831214 request for documents re supplemental cooling water sys SUGARMAN.R J Sugarman & Denworth 84/01/09 STARDSTECKI.R Division of Project & Resident Programs 1p 22378 102 24X Ficher 50-352,84/01/09.8402230391
- --840.2230395 FOIA request for documents re supplemental cooling water mys, in connection w/831018 second corporate mpt meeting concerning proposals for supplemental cooling water system availability.

 BUOARMAN, R. J. Superman & Denworth 83/12/14. STAROSTECKI, R. Division of Project & Resident Programs 2pp. 22378 103 24X Fiche 50-352, 84/01/09, 8402230391
- 8402230399 Responds to FOIA request for IE Bulletin 83-06.R Starostacki responded to request on 840116
 FELTON, J M Division of Rules and Records 84/02/01 SUGARMAN.R. J
 Sugarman & Denwerth 1p 22378.105
- 8402230404 F01A request for documents re number of temporary & transient workers employed at nuclear facilities in 1981, 1982 or 1983 & quantitative & qualitative analysis of radiation doses workers received in 1981, 1982 or 1983 MAYBERRY, 8 Public Citizen Litigation Group. 83/10/26. FELTON, J Division of Rules and Records. 1p. 22378 106
- 8402230407 FOIA request for EL Jordan 800822 memo to all region chiefs re license power levels
 BUCKLES.R NUS Corp CD-LIS-83-021. 84/01/09. Division of Rules and Records 1p. 22379 154
- B402230408 Responds to FDIA request for EL Jordan 800822 memo to region chiefs re license power levels Forwards requested document. Document also available in PDR. FELTON-J M Division of Rules and Records 84/02/09 BUCKLES, R NUS Corp 1p. 22379 157.
- --8010160407 Outlines guidance IE will use re enforcement of max licensed power limits JORDAN,E L Division of Reactor Operations Inspections BO/08/22 BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch, 2pp 22379,158.

- 8402230411 Responds to FOIA request for four categories of documents Forwards marked-up excerpt from Vol 3 of NUREG-0713 re occupational radiation exposure partial NUREG-0714, Vols 2 & 3 & draft rept on termination W/o NUREG-0714 & draft rept FELTON, J M Division of Rules and Records 83/12/13 MAYBERRY, & Public Citizen Litigation Group 2pp 22376 107
- --B402230413 NUREG-0713 DRFT
 Marked-up excerpt from NUREG-0713, "Occupational Radiation Exposure at Commercial Nuclear Power Reactors 1981"
 * NRC No Datailed Affiliation Oiven 83/12/13 14pp. 22370 109
- 8403230423 Partial response to FOIA request for five categories of documents re nuclear design & const projects from 740101-830601 Forwards "NRC Nonconformance per Plant." & "NRC Nonconformance per Plant." & "NRC Nonconformance per Plant." & FELTON.J M Division of Rules and Records 83/12/12 FRAINOR.E F Cygna Energy Bervices ip 28377 057
- --8402230424 "NRC Nonconformance per Plant," computer printout * NRC - No Detailed Affiliation Given 83/12/12 343pp 22377 058
- --8402230427 "NRC Nonconformance per Plant/Annuel Summary by Honth of Ail Const Projects," computer printout * NRC - No Detailed Affiliation Given 83/12/12 5pp 22378 041
- 8402230425 FDIA request for SECYs 83-240,261,228,228A,246,988 & 32 to be placed in PDR Graperial December 2018 Corp CD-18-83-318 83/09/07 Division of Aulis and Records ip 22371 268
- 8402230427 Responds to FOIA request for SECYs 83-32,988,228,228A,240,246 & 261 to be placed in PDR Forwards SECYs 83-228A,261 & 240 SECYs 83-228,240,246 & 261 partially withheld (ref FOIA Exemption 5) SECYs 83-32,988 & 228A available in PDR FELTON.J M Division of Rules and Records 83/12/07, 9RABER, L D NUS Corp 4pp 22371 269 24X Fiche 50-000,83/12/07,8402230427
- ~-8402R3043R SECY-83-2R9A
 Discusses NRC suggestion to change policy & milou
 distribution of illuminated gunsights to general public.
 MALSCH.M 0 Office of the General Counsel 83/07/19 13pp
- --8402230434 SECY-83-261
 Discusses Safe Power for Maine 821020 request for show cause order re licenses alleged lack of financial qualifications MALSCH, M G Office of the General Counsel DD-83-03 83/06/29 Spp 22371 286 24X Fiche 50-000,83/12/07,8402230429
- ---B402230439 SECY-B3-240
 Discusses disposition of Suffolk County motion for Commission ruling on LILCO emergency preparedness plan. MALBCH.M 0 Diffice of the Owneral Counsel 83/06/20 53p 22371, 291 24X Fiche 50-000, 83/12/07, 8402230429
- 8402230441 FOIA request for documents re licensed research reactors, including NUREG-0020 on anticipated requests for licensing & relicensability of reactors BELL.N Nuclear Information & Resource Service 63/11/22 Offic of Administration 1p. 22371 345.
- 8402230442 Responds to FOIA request for three categories of documents re licensed research reactors Forwards list of licensed facilities including expiration dates Record also in PDR No documentation responsive to remaining requests located FELTON. J H Division of Rules and Records 83/12/12 BELL.N. Nuclear Information & Resource Service ip 22371 346
- --B402230443 List of licensed research reactors, including location, type expiration date * NRC No Detailed Affiliation Given 83/12/12 Spp 22371 186
- 8402240040 FOIA request for listed company purchase orders or departmental contracts for purchase or lease of ADP & word processing equipment or computer sys & purchase of ADP supplies, paripheral equipment & software programs NEMECEK, A D Affiliation Not Assigned 83/07/13 NRC No Detailed Affiliation Given 1p 22381.292
- 8402240043 Responds to FOIA request for purchase orders & contracts awarded to six listed companies Forwards six Terminals Unlimited, Inc.one DN Owens Co & six D Owens & Assoc, Inc purchase orders Documents also in PDR.

 FELTON, J M. Division of Rules and Records 83/12/09, NEMECEK, A. D Affiliation Not Assigned 2pp 82381-293.

- --8402240045 Submits Purchase Order DR-Bi-0871 for 24 IBM 1403 computer ribbons Related info encl
 PERLMAN.J NRC No Detailed Affiliation Given 81/03/30 SLOCUM.R Affiliation Not Assigned 13pp 22381 275
- 8402240067 FDIA request for documents arising out of insps of TMI-1 or 2 re detection or measurement of RCS leakage & compliance W/regulatory requirements concerning recordkeeping MADDEN.T J Kaye. Scholer, Fierman. Hays & Handler 83/12/27 NCRRY.P G. Office of Administration 2pp 22394 275 24X Fiche 30-287.83/12/27.8402240067
- 8402240081 Partial response to FOIA request for records arising out of Imaps of TMI-1 & 2 re detection of measurement of RCS lealage App A documents available in PDR Forwards App B documents Review of add1 records subj to request continuing FELTON, J H Division of Rules and Records 84/02/08 MADDEN, T J Kaye, 8choler, Fierman, Hays & Handler 4pp 22394 277 24X Fiche 50-289,84/02/08.8402240081
- ---B309080080 Forwards B&W Exhibits 428 & 427 re PORV tailpipe temps ro leakage from FORV Evaluation of analysis of thermocouple data in Exhibit 428 requested by 830916 EISENHUT.D G. Division of Licensing B3/08/25 MATTBON,R J Division of Egstems Integration (post B11005) 61pp 22394 288 24X Fiche 50-289.84/08/08.8402240081
- --B310200327 Forwards technical evaluation of GPU analysis of PDRV tailpips temps to PDRV leakage per B30825 request Analysis reasonable Evidence convincing that one pafety valve leaking in Fab-Mar 1979 time frame.

 MATTBONER J Division of Bystems Integration (post B11005) B3/10/12 E18ENHUT.D.0. Division of Licensing 4pp 22394 292 24X Fiche 50-289,84/02/08,8402240081
- --B402240097 Submits historical background of data accumulated & list of current action items in response to NRC 800114 ltr re reactor bldg sump level & RCB makeup sys leakage Table encl WILBON, R.F. Metropolitan Edison Co. WILBON, R.F. General Public Utilities GPU Bervice Corp. TLL 051 84/02/08, COLLINS, J.T. THI-2 Operations/Support Task Force. 3pp. 22394 281 24X Fichs. 30-289, 84/02/08, 8402240081
- --B402240105 Discusses correspondence w/DGJ re NRC investigation of Hartman Allegations At 830728 oral argument on reopening record of facility restart proceeding. ABLAB requested infore agreement between Commission & DGJ.

 CUNNINCHAM.O H Office of the Executive Lagal Director 83/08/25

 CUMNINGS.J J Office of Inspector & Auditor. 1p 22374, 289

 24% Fichs 50-289. B4/02/08, 8402240081
- --8402240114 Discusses ARLAB reopening hearing on mgt issues besed on Hartman allegations of mgt involvement in falsification of leak rate data ABLAB will take up appeals of mgt decisions & will issue order setting oral argument CUNNINGHAM.Q H. Office of the Executive Legal Director. ALAB-738 83/09/02. DENTON.H. Office of Nuclear Reactor Regulation. Director 2pp 22974.290 24X Fiche 50-289.84/02/08.8402240081
- 8402240086 Further response to FDIA request for 16 categories of documents. Item 9 limited, per 831005 telcon Forwards Rev 7 to NUMER-0528 & App A documents. Portions of App B documents withheld (ref FDIA Exemption 4), App B documents also in FDR. FELTON, J M Division of Rules and Records 83/12/12, SHOLLY, 8 C Unian of Concerned Scientists. 4pp 22394.150 24% Fiche.50-000.83/12/12,8402240086
- --8305160003 Security event rept re 830504 bomb threat
 UDERITZ,R A Public Service Electric & Gas Co of New Jersey.
 83705707 Director's Office, Office of Inspection and
 Enforcement. 3pp 22374 154 24X Fiche 50-000,83/12/12,
 8402240086
- --8308170014 Security event rept re 830728 occurrence, MAREMBOURG, D. W. Public Service Co. of Colorado, P-83265, 83/08/01 COLLINS, J. T. Region 4, Office of Director 2pp, 22394.157 24% Fiche, 50-000, 83/12/12, 8402240086
- --8309070010 Telecopy Becurity Event Rept 83-7 re 830811 occurrence, FLEISCHMANN, R Philadelphia Electric Co. RBPS-83-007 83/08/16 MURLEY, T. E. Region 1, Office of Director, 2pp. 22394, 159, 24X Fiche: 50-000, 83/12/12, 8402240086.
- --B309200043 Security event rept re 830906 occurrence HAREMBOURG, D. W. Public Service Co. of Colorado, P-83301. B3/09/07 COLLINS, J. T. Region 4. Defice of Director 2p 22374 163. 24X Fiche 30-000, B3/12/12, 8402240086.

- --8402240117 RO B3-72 on 83072B vital area alarms lost Caused by loop error PCS board replaced in mux All affected zones tested & secured Info deleted YOUNG.A Commonwealth Edison Co RD-83-72 B3/07/28 Region 3. Office of Director ip 22374 165 24% Fiche 50-000,83/12/12. 8402240086
- --8402240125 RO 83-67 on 830722, alarm capabilities lost in all zones due to mux overheating Caused by extreme heat inside plant Central processing unit replaced & Code 10 performed w/positive results Info deleted YOUNG. A Commonwealth Edison Co RO-83-67 83/07/22 Region 3. Office of Director 1p 22394 166 24X Fiche 50-000.83/12/12, 8402240086
- --8402240129 RD 83-52 on 830A17.vital area door found physically unsecured & electric strike malfunctioned Cause not stated Electric strike replaced Info deleted YOUNG.A Commonwealth Edison Co RO-83-52 83/06/21 Region 3, Office of Director ip 22394 167 24X Fiche 50-000,83/12/12,8402240086
- --8402240135 RO 83-40 on 830523, vital area door alarm lost Caused by misadgustment of supervisory line board Alarm repaired Info deleted YOUNG: A Commonwealth Edison Co RO-83-40 83/05/24 Region 3, Office of Director ip 22374 168 24X Fiche 50-000,83/12/12,8402340084
- --8402240141 RO 83-40 on 830414, power flex to security equipment resulted in loss of alarm integrity Caused by fire Mux restored Info deleted.

 * Commonwealth Edison Co RO-83-30 83/04/18 Region 3. Office of Director ip 22394 169 24X Fiche 50-000.83/12/12, 8402240086
- B40224014B F01A request for documents re B30714 inquiry team rept on Facility GA allegations & insp & util response to rept GARDE.B P., BERNABEI.L. Government Accountability Project B3/10/24 Defice of Administration 2pp 22374 170 24X Fiche 50-382,83/10/24,840224014B
- 9402240153 Responds to FDIA request for documents re 830714 inquiry team rept on facility GA allegations & insp & Util response to rept Forwards App D documents App A & B documents available in FDR FELTON, JM Division of Rules and Records 83/12/09 QARDE, B P Government Accountability Project 4pp 22394 172 24X Fiche 50-382,83/12/09,8402240153
- --8309300031 Requests assistance in identifying roles for NRR, IE & Region IV to complete review of Harstead Engineering Assoc, Inc 830919 rept. "Analysis of Cracks & Water Beepage in Foundation Matl"

 CHRISTERBURY, E Hearings Division 83/09/22 EISENHUT, D G Division of Licensing. 2pp 22394 197 24X Fiche 50-382. 83/12/09.8402240153
- --B311140289 Informs that NRR has lead responsibility for coordination to development of NRC position on cracks & water seepage in foundation mat Review of math to establish safety significance will be completed by B31115
 EIBENHUT: DO Division of Licensing B3/10/28, CHRISTENBURY, E Hearings Division 2pp 22394 199 24X Ficha 50-302, 83/12/09, 8402240153
- ---B402240136 Forwards news article re NRC concern w/GA One area previously unspecified now identified as potential significant deficiency Incident B re common foundation mat radial cracks inside ring wall RIDENHOUR, R Cambit 83/05/03 FORT, J Louisiana Power & Light Co 5pp 22394 176 24% Fiche 50-382.83/12/09.8402240153
- --8402240140 Forwards case summary of Insp 83-65 re facility QA allegation AMEARNE, J.F., Commissioners 83/04/13 CUMMINGS NRC - No Detailed Affiliation Given 2pp 22394 181 24X Fichs 30-382,83/12/09.8402240153
- --B402240163 Informs of B30620 telcon re GA info relayed to JK Jossten by R Ridenhour of Gambit Publications Ridenhour expressed concern that NRC knew about cracks in containment basemat MULLEY, G.A. Office of Inspector & Auditor 83/06/22 CUMMINOS. J., Office of Inspector & Auditor 1p 22374 183 24X Fiche 50-382, 83/12/07, 8402240183
- --8402240166 Forwards 830825 meeting agenda re issues in NRC 830804 ltr to util concerning GA concerns CUMMINOS, J. Office of Inspector & Auditor. 83/07/07, GARRER, D., MILHDAN, J. CHESTNUT. S. NRC - No Detailed Affiliation Olven 10pp 22374 187 24X Ficher 50-382,83/12/09,8402240153

- --8402240170 "Compatibility of Large Mat Design to Foundation Conditions" EHASZ,J L., LIU,P C Ebasco Services, Inc. (subs of Enserch Corp.) 83/12/09 56pp 22394 219 24x Fiche 50-382,83/12/09, 8402240153
- 8402240172 FOIA request for comparative evaluation of compliance w/TKI-2 accident lessons learned requirements (NUREO-0378 & NUREO-0737 & suppl) by individual nuclear plants WEIBS.ER Union of Concerned Scientists 83/12/21 FELTON, U Division of Rules and Records Ip 22382 001
- 8402240175 Responds to FDIA request for comparative evaluation of compliance by individual nuclear plants w/TMT-2 accident lessons learned requirements (NUREG-0578 & NUREG-0737 & suppl) Forwards App A documents Info also available in PDR FELTON, J M Division of Rules and Records 84/01/13 WEISS, E R Union of Concerned Scientists 2pp 22382 002
- --8402240178 List of licenses implementation of NUREG-0737 * NRC No Betailed Affiliation Given 83/01/01 98(22882 004
- --8402240196 Computerized list of technical assignment control sys multiplant issues rept TAM.P NRC - No Detailed Affiliation Given VARGA.6 Division of Licensing 83/08/12 292pp 22382 013
- --8402240197 Computerized list of imap of TMI action plan requirements for operating reactors

 * NRC -- No Detailed Affiliation Given 83/10/07 1169pp 22892 305
- 8402240180 Responds to FOIA requests for two documents by accession number on Kerr-McGee Cimarron facility & nine documents by accession number on Kerr-McGee Kest Chicago facility Request sent to PDR for processing by PDR contractor FELTON, JM Division of Rules and Records 83/12/15 BARNES, C Affiliation Not Assigned Ip 22381 285
- 8402240184 FOIA request for 750116 DES for mixed stide fabrication plant in Logan County, DK & for 791207 PNO BARNES, C Affiliation Not Assigned 83/12/06 Office of Administration ip 22381 286
- 8402240189 FOIA request for nine documents on facility DARNES,C Affiliation Not Assigned 83/12/06 Office of Administration 1p 22381 287
- 8402240178 FOIA request for SECY-83-404 to be placed in PDR BUCKLES:R NUS Corp CD-LIS-83-033 84/01/13 Division of Rules and Records ip 22381 288
- 8402240199 Responds to FOIA request for SECY-83-404 to be placed in PDR Forwards SECY Document also available in PDR FELTON, J M Division of Rules and Records 84/02/07 BUCKLES, R NUS Corp ip 23381 289 24% Fishe 50-289, 84/02/07, 8402240199
- --B402240200 SECY-83-404
 Advises Commission of evaluation of thiosulfate contamination & PORV corrosion problem at TMI-1, as requested in B Chilk 830810 memo stemming from ALAB-724
 DIRCKS J Office of the Executive Director for Operations ALAB-724
 83/09/30 2pp 22381 290 24X Fiche 50-289,84/02/07,8402240199
- 8402240201 FOIA request for LER 83-83.dtd 830908 9RABER.L D NUB Corp CD-LIS-83-048 84/01/23 Division of Rules and Records ip 22393 225 24% Fiche 50-315.84/01/23, 8402240201
- 8402240205 FOIA request for NUREO/CR-3121 (SANDB3-0013), "Jeneric Modeling Approach for LWR Sys Analysis," to be placed in PDR Full explanation should be provided if rept exempt from public disclosure for security reasons BHOLLV-S C Union of Concerned Scientists 83/10/26 FELTON.J M Division of Rules and Records 1p 22393 164
- 8402240207 Responds to FOIA request for NUREG/CR-3121 to be made available in PDR Forwards NUREG/CR-3121 Document also placed in PDR FELTON.J M Division of Rules and Records. 63/12/12 8HQLLY,8 C Union of Concerned Scientists 1p 22393 165
- --8402240209 "Generic Modeling Approach for LWR Bys Amalysis."
 GALLUP.D R , VARNADD.G B , DANIEL.S.L Sandia Laboratories FIN
 A-1060. 83/05/31 Division of Facility Operations 35pp.
 22393 166

- 8402240214 Responds to FOIA request for LER 83-82, dtd 830908, Forwards document Document also available in PDR FELTON, J M Division of Rules and Records 84/02/03 GRABER, L D NUS Corp ip 22373 226 24X Fiche 50-315, 84/02/03, 8402240214
- ~~8402240215 LER 83-083/03L-O on 830817, source range Vitron flux monitor N-32 became erratic & declared inoperable Caused by N-32 BB attenautor set low Attenuator adjusted & returned to svc W/83090B ltr PALMER, SMITH, W G Indiana & Michigan Electric Co 83/09/08 KEPPLER, J G Region 3, Office of Director 3pp 22393 227 24X Fishs 50-315,84/02/03.8402240214
- 8402240216 Final response to FDIA request for documents to replacement piping at facility forwards App A & B documents Documents also available in PDR FELTON.J M Division of Rules and Records 84/02/03 BELL.N Nuclear Information & Resource Service 3pp 22393 230 24% Fiths 50-000,84/02/03,8402240216
- --8205190430 Comments on evaluation of facility saferend replacement Licensee should implement certain reg guides in radiation protection program for use in ALARA HOUSTON.R W Assistant Director for Radiation Protection. 82/05/12 NDVAK,T M Assistant Director for Operating Reactors 1p 22394 001 24% Fiche 50-000.84/02/03.8402240216
- --8206110034 Advises that review of man-rem exposure estimates for takenend replacement indicates licensee has taken all appropriate steps to mitigate doses SER/EIA to be issued to allow licensee to proceed POLK/P J Operating Reactors Branch 2 82/06/07 EISENHUT, D 0 Division of Licensing 1p 22374 148 24X Fiche 50-000, 84/02/03, 8407240214.
- --8205250092 Forwards Radiological Assessment Branch inputs to safety evaluation & EIA for safe-end replacement HQUSTON,R W Assistant Director for Radiation Protection 82/05/08 NOVAK.T M Assistant Director for Operating Reactors 18pp 22394 023 24X Fiche 50-000,84/02/03,8402240216
- --8209230151 Trip rept of 820813 site visit re replacement of recirculation sys piping CHENO.C.Y Haberials Engineering Branch 82/09/02 HAZELTON.W B Haterials Engineering Branch 16pp 22393 345 24X Fiche 50-000.84/02/03.8402240216
- --8303160017 Identifies info required prior to June 1983 restart Restart contingent upon NRC review & acceptance of stress reamalysis of recirculation sys piping & nozzle 15 safe-end repair info VASSALLO, D B Derating Reactors Branch & 83/03/04. LIAW, B D Materials Engineering Branch ip 22394 045 24% Fiche 50-000,84/02/03.8402240216
- --8306030077 Forwards evaluation of recirculation sys piping replacementstress analysis.per licensee 830422 submittal Repair satisfactorily completed Restart recommended. KNIGHT.J P Assistant Director for Comp & Structures Engineering (Pre 830201) TAC 51434 83/05/26. LAINAS.G C. Assistant Director for Diperating Reactors 3pp 22394 046 24X Fiche 50-000.84/02/03.8402240216
- --B310060214 Amend 49 to License DPR-63, approving recirculation systems aferend replacement program including cutting & welding of saferends & worker dose mitigation program Safety evaluation enci
 VASSALLO, D B Operating Reactors Branch 2 B2/06/18 App 22393 339 24X Fiche 50-000, 84/02/03, 8402240216.
- --B310060224 Notice of issuance & availability of Amend 49 to License DPR-63 & negative declaration VABSALLO,D B Operating Reactors Branch 2 B2/06/18 2pp 22394 002 24X Fiche 50-000,84/02/03,8402240216.
- --B402240220 "Personnel Whole Body Exposures for CYB2," W/830331 ltr LEMPGES.T E Niagara Mohawk Power Corp 10CFR 020 407, B2/12/31 26pp 22393 311 24% Fiche 50-000.84/02/03.8402240216
- ---8402240234 Summary of 820422 meeting w/util, Newport News, MPR, NES, OE. EPRI & London Nuclear re recirculation sys decontamination. ALARA considerations & seferend replacement POLK, P.J. Operating Reactors Branch 2 82/04/30 Operating Reactors Branch 2 42pp 22394 049 24X Fiche: 50-000, 84/02/03-8402240216.
- --8402240239 Summary of 620813 meeting w/util at site re cracking & recirculation loop giping replacement plans GRAY, E.H. Region 1, Office of Director 82/09/08 Region 1. Office of Director 2pp 22394 105 24% Fiche 50-000, 84/02/03, 8402240216

- --8402240241 Task interface agreement re RCS piping replacement Action plan listed HDLAHAN. © Division of Fuel Cycle & Material Safety JORDAN. E Director's Office. Office of Inspection and Enforcement STARGETECKI.R Region 1. Office of Director TAC 48124 82/08/24 2pp 22394 122 24% Fiche 50-000,84/02/03.8402240216
- --B402240224 Transfers responsibility for recirculation piping replacement to NRR Regional assistance requested STAROSTECKI, R Division of Project & Resident Programs 82/08/04 EISENHUT, D G Division of Licensing Ip 22394 124 24X Fiche 50-000, R4/02/03, B402240216
- --8402240245 Handwritten summary of meeting w/util.MPR,London Nuclear,GE & NES in Bethesda,MD re stagnant decontamination of loops w/o plugs in vessel * Office of Nuclear Reactor Regulation, Director 82/04/22 Office of Nuclear Reactor Regulation, Director 16pp 22394 132 24X Fiche 50-000:84/02/03.8402240216
- --8402240249 Forwards const schedule for retirculation sys replacement W/o encl MOSIER.M G Affiliation Not Assigned 82/08/31 Affiliation Not Assigned 1p 22394 149 24X Fiche 50-000,84/02/03,8402240216
- B402240217 Appeals denial of FOIA request for JJ Cummings B30728 memo to H Plaine re Hartman allegations VDIOT, H H LeBoeuf, Lamb, Leiby & MacRae B3/11/21 CHILK, S J Office of the Secretary of the Commission 4pp 22373 148
- B402240219 Responds to appeal re denial of FOIA request for documents on investigation into Hartman allegations Forwards document Document partially withheld (ref FOIA Exemption 5)
 CHILK, B J Office of the Secretary of the Commission 84/02/03 VDIGT, H LeBoeuf, Lamb. Leiby & MacRae 7pp 22393 192
- --8402240223 Chronology of events, meetings & conversations between 800321 & 0528, addressing assertion by DOJ that in Mar/Apr 1980 time frame NRC was not requested to stop Hartman investigation but only to curb efforts somewhat * NRC No Detailed Affiliation Given 84/02/03 5pp 22393 154
- 8402240227 FOIA request for list of vendors requesting procurement source list or mailing list for "Support of High Frequency, UHF & VAF Equipment"
 STERN.A Al Stern Associates RS-ADM-84-237 B4/01/24
 HATTIA,M J, BAZIN,JP NRC No Detailed Affiliation Given 1p 22381 352
- 8402240263 Responds to FOIA request for list of vendors requesting procurement source list or mailing list or "Support of High Frequency, UHF & VHF Equipment" FELTON, J.M. Division of Rules and Records RS-ADM-84-237 84/02/03 STERN, A. Al Stern Associates ip 22381:353.
- --8402240267 List of vendors requesting procurement source list or mailing for "Support of High Frequency, UHF or VHF Equipment"

 ** NRC No Detailed Affiliation Given RS-ADM-84-239 84/02/03 3ps. 22381, 354
- B402240275 FOIA request for three categories of documents re facilities BUQARMAN.R J Bugarman & Denworth 83/12/20 Division of Rules and Records. 2pp 22374 276 24X Fiche 50~352,83/12/20,8402240275
- 8402240277 Responds to FDIA request for three categories of documents re facilities Forwards App A Documents i-4 Documents 5-9 provided previously via svc list FELTON, J M Division of Rules and Records 84/01/27 8UGARNAN, R J Sugarman & Denworth 2pp 22394-298 24X Fiche 50-000, 84/01/27, 8402240277
- --8308090022 Forwards second quarterly status rept for 1983 on actions taken re-operating reactors & licensing reviews of new facilities
 ASBELBTINE. J. K. Commissioners 83/07/21. BEVILL, T. House of Rep., Appropriations lipp 22394 300 24X Fiche: 50-000, 84/01/27.8402240277
- --8402240275 Bection 5 0, "Startup Addenda," to monthly project status rept # Philadelphia Electric Co # Bechtel Corp 83/12/01, 79pp 22394: 356 24X Fiche. 50-000,84/01/27.8402240277

- B402240279 FOIA request for agency records & info ro meetings between RC DeYoung & CPC attys or executives on violation of board order & meetings held at D'Hare Airport during Fall 1983 GARDE.B P Government Accountability Project B4/01/10 Defice of Administration 2pp 22301 349
- 8402240283 Partial response to FOIA request for agency records between RC DeYoung & CPC attys or executives re violation of board order & records of meetings held at O'Hare Airport in Fall 1993 Handout re crossings of freezewall placed in PDR FELTON, J M Division of Rules and Records 84/02/14 GARDE, B P Government Accountability Project ip 22381 351
- B4022402BB FOIA request for records re contracts entered into between Maywood Chemical Works, Maywood, NJ & US Govt From 1941-60 TYKULSKER, D Ball, Hayden, Kierman & Livingston B4/01/17 NRC No Detailed Affiliation Given 3pp 223B1 345
- B402240273 Responds to FOIA request for documents re contracts entered into between Maywood Chemical Works, Maywood, NJ & US Govt from 1941-60 No records subj to request located DOE should be contacted be contacted FELTON, J M Division of Rules and Records 84/02/14 TYKULSKER, D Ball, Hayden, Kiernan & Livingston 19 22381 348
- 8402240304 FOIA request for eight categories of documents re license amends to OLs issued for nuclear reactors, including 830623 SECY-83-247, NRC memos re review of 830927 Facility OL amend & notification of Congress of NSMC treatment for spent fuel BELL, N Nuclear Information & Resource Service 83/11/23 Office of Administration 2pg 22414 058 24% Fithe 50-287, 83/11/23, 8402240304
- 8402240308 FOIA request for SEER & Tech Specs re facility SUGARMAN, R J Sugarman & Denworth 84/01/25 NRC - No Detailed Affiliation Given ip 22381 343 24X Fiche 50-352,84/01/25, 8402240308
- 8402240309 Partiel response to FDIA request for eight categories of documents re OL amends Forwards App A documents Documents also in PDR FELTON, J M Division of Rules and Records 83/12/14 IELL, N Nuclear Information & Resource Service 4pp 22414 060 24X Fiche 50-287.83/12/14.8402240309
- ~~B305020051 Forwards inputs to BER & EIA re util 830310 request for spent fuel pool expansion
 MULLER.D R Assistant Director for Radiation Protection TAC 51031 83/04/21 LAINAS.G C Assistant Director for Operating Reactors 4pp. 22414.064 24X Fiche 50~287.83/12/14.8402240309
- --0306020182 Responds to util B30310 request to amend OL & Tech Bpecs re reracking of spent fuel pool in effort to expand storage capacity New racks designed to meet nuclear requirements Proposed Tech Spec revs approved BER enci RUBENSTEIN,L S Assistant Director for Core & Plant Systems TAC 51031 B3/05/25 LAINAB,G C Assistant Director for Operating Reactors. 4pp 22414/06B 24X Fiche 50-287.83/12/14,8402240309
- --B307250016 Provides info re proposed licensee actions on spent fuel pool expansion. Util planning receipt of GL amend by 830901 Old rack removal will not begin until receipt of license amend EIBENHUT, D.O. Division of Licensing 83/07/18 REHM, T.A. Office of the Executive Director for Operations ip 22414 101 24X Fiche 50-287, 83/12/14, 8402240309
- ---B307230073 Forwards request for add1 info licensee B30310 request for spent fuel pool expansion mod Info needed includes description of term "lift bag" & conformance w/NUREO-0612 guidelines.
 PARR: O D. Auxiliary Systems Branch TAC 51031 83/07/18 BTOL7.J F Operating Reactors Branch 4 2pp 22414 079 24X Fichs 50-287,83/12/14,8402240309
- --B307290197 Forwards SER on application to expand spent fuel storage facilities Proposed installation acceptable KNIGHT. J P Assistant Director for Comp & Structures Engineering (Post B30201), TAC 51031 83/07/20 LAINAS 6 C Assistant Director for Operating Reactors App 22414-082 24X Fiche 50-287, 83/12/14, 8402240309
- --8308050626 Forwards Auxiliary Sys Branch SER re spent fuel pool mod for increased storage capacity Proposed spent fuel pool gypansion program acceptable.

 RUBENSTEIN,L 8 Assistant Director for Care & Plant Systems TAC 51031 83/07/26 LAINAB.Q C. Assistant Director for Operating Reactors 10pp 22414 088. 24X Fiche 50-287.83/12/14.8402240309

- --8300150030 Forwards inputs to EIA re spent fuel peal storage expansion, in response to util 830310 request
 MULLER.D R Assistant Director for Radiation Protection TAC
 51031 83/08/01 LAINAS.0 C Assistant Director for Operating
 Reactors 2pp 22414 098 24X Fiche 50-287.83/12/14.8402240309
- --8402240337 Submits telcon responses to requests for add1 info re spent fuel pool rerack SUERMANN, JF NRC - No Detailed Affiliation Given TAC 51031 83707/15 NRC - No Detailed Affiliation Given 2pp 22414 077 24X Fiche 50-287, 83/12/14, 8402240309
- --B402240344 Submits info from 830720 telcon w/8 Gill re spent fuel pool retack bridge crane
 SUERMANN, J. MRC No Detailed Affiliation Given 83/07/20
 CHAN, T. MRC No Detailed Affiliation Given 19 22414 081 24X
 Fithe 50-287,83/12/14,8402240307
- --8402240353 Advises of issuance of Amends 123,123 & 120 to Licenses DPR-3B, DPR-47 & DPR-55, respectively, changing Tech Specs to authorize expansion of spent fuel pool to 825 storage locations SUERMANN, J F Operating Reactors Branch 4 83/09/29 DENION, H R , CARTER, J , EISEMUT, D NRC No Detailed Affiliation Given 1p 22414 100 24X fiche 50-287,83/12/14,8402240309
- 8402240315 Responds to FOIA request for SSER & Tech Specs re facility Requested documents available in PDR FELTON, J M Division of Rules and Records 84/02/07 BUGARMAN, R J Sugarman & Denworth 1p 22381 344 24X Fiche 50-352,84/02/07, 8402240315
- 8402240324 FDIA request for documents from INPO that describe analyze or evaluate JNPO role or procedures in reporting info to NRC
 TOTTEN.M Public Citizen Litigation Group 84/01/16 FELTON.J M Division of Rules and Records 3pp 22381 313
- 8403240328 Partial response to FOIA request for documents from INPO that describe analyse or evaluate INPO role or procedures in reporting info to NRC App A documents available in PDR Review of addl records sub, to request in progress FELTON, J M Division of Rules and Records 84/02/03 TOTTEN, M Public Citizen Litigation Group 2pp 22381 318
- --8402240333 "Preliminary Title List Rept." * Division of Technical Information & Document Control NRC-10-82-356 84/01/25 23pp 22381 320
- 8402240336 FOIA request for documents re Z Bartolome, Commissioner of Philippine AEC.1983 visit to US & meeting w/NRC BCHERR.8 J Natural Resources Defense Council 84/01/11 Division of Rules and Records 2pp 22372 188
- 8402240340 Responds to FOIA request for documents re Z Bartolome, Commissioner of Philippine AEC:1983 visit w/NRC Forwards listed documents FELTON.J M Division of Rules and Records 84/02/02. BCHERR, S J Natural Resources Defense Council 1p 22392 191.
- --8402240361 Notifies of 831017 meeting w/Z Bartolome, Commissioner of Philippine AEC LAFLEUR. D Office of International Programs, Director 83/10/11 CHILK.8 J Office of the Secretary of the Commission 1p 22392 192
- --8402240367 Forwards background into for use during 831017 meeting w/Z Bartolome.Commissioner of Philippine AEC LAFLEUR. J D. Office of International Programs. Director 83/10/13 CHILK.S J Office of the Secretary of the Commission 5ap 22392 195
- B402240359 FOLA request for reactor operator & senior reactor operator erams administered by NRC during past 3 yrs
 PETERSON, J J Professional Reactor Operator Society 84/01/20
 Office of Administration 1p 22381 357
- 8402240366 Responds to FOIA request for reactor operator & senior reactor operator exams administered by NRC during past 3 grs Documents entirely withheld (ref FOIA Exemption 2) FELTON-J M Division of Rules and Records 84/02/14 PETERBON-J J Professional Reactor Operator Society 2pp 22381-358
- 8402270001 Further response to FOIA request for NRC records re security violations & safeguards ovents at nuclear facilities Forwards App A documents App B documents partially withheld (ref FOIA Exemptions 3,4 & 6) App A documents also in PDR FELTON. J M Division of Rules and Records 83/12/12 GOLDENBERG, G 3cripps-Howard Newspapers 4pp. 22413 098 24% che 50-344,83/12/12,8402270001.

- ---8402270024 IE Insp Rept 50-344/79-18 on 791107-09 No noncompliance noted Major areas inspected physical security, including access controls, lock & key security & review of investigation efforts re controlled substances SCHUSTER.M D. BHACKLETON, O. C. Region 5, San Francisco, Office of the Director NORDERHAUG, L. R. Region 5, San Francisco, Safeguards Branch 79/11/21 5pp 22413 106 24X Fiche 50-344,83/12/12,8402270001
- --8402270029 Requests Sargent 98 Markovich upcoming evaluation of physical security at plant & 791105 rept of arrests of facility guards involved w/narcotics ENGELKEN, R H NRC No Detailed Affiliation Given 79/11/21 WILLIAMS, J C Oregon, State of 1p 22413 li1 24X Fiche 50-344,83/12/12,8402270001
- --8402270043 Forwards undercover officer rept on evaluation of security at plant Repts dealing w/criminal prosecution will not be released w/o sanction of Columbia County District Atty News articles encl
 WILLIAMS.J C Oregon, State of 79/12/04 ENGELKEN.R H Region 5, San Francisco, Office of the Director 9pp #2413 112 24X Fiche 50-344,83/12/12,8402270001
- --B402270054 Forwards Oregon State Police officer 791121 rept refacility security sys W/o rept Related info encl
 SCHUBTER.H D Region 5. San Francisco. Office of the Director
 79712/07 CHAPELL.D R Division of Safeguards Inspections 2pp
 22395 091 24X Fiche 50-344.83/12/12.8402270001
- ---8402270069 Discusses 791126 conversation w/P Hunt of Congressman Dinjle ofc re-potential use of LSD by facility security guards
 Insp rept will be sent to Hunt
 NDRDERHAUGL R Region 5. San Francisco, Office of the Director
 79/11/28 Region 5. San Francisco, Office of the Director
 22413 IRI 24X Fiche 50-344,83/12/12,8402270001
- --B402270080 IE Insp Rept 50-344/79-20 on 791126-1212 Noncompliance noted failure to control access to protected & vital areas of site Info deleted (ref 10CFR2 790)
 MORTENSEN.W P , SCHUSTER,M D , SCHAEFER.D W Region 5, San Francisco, Office of the Director B0/02/15 30pp 22413 129 24X Fiche 50-344,83/12/12.8402270001
- --8402270091 Notice of violation from insp on 791126-30 & 1211-12 Burns employee granted visitor unauthorized access to protected areas on 791014 Info deleted (ref 10CFR2 790)

 * NRC No Detailed Affiliation Given 80/02/15 2pp 22413 161 24X Fiche 50-344,83/12/12,8402270001
- --8402270105 Forwards sanitized responses to notice of violation & notice of proposed imposition of civil penalties WILLIAMS.J. Portland General Electric Co. 80/03/07. STELLG.V. Office of Inspection & Enforcement, Office of the Director . Ppp. 22413 164 24X Fiche.50-344.83/12/12.8402270001.
- --8402270114 Forwards recommended response to Util 800307 reply to NRC 800215 notice of violation & notice of proposed imposition of civil penalties ENGELKEN.R H Region 5. San Francisco. Office of the Director. 80/03/17 STELLG.V Office of Inspection & Enfarcement. Office of the Director ip 22413:173 24X Fiche. 50-344.83/12/12.
- --8402270126 Forwards Region V memo describing several safeguards problems at facility Licenses failed to complete installation of security equipment by dates previously accepted by NRR Requests to be informed of plans CHAPELL, D R Division of Safeguards Inspections. 80/01/31 MCCDRMLE, G W Physical Security Licensing Branch ip 22413 179 24X Fichs 50-344,83/12/12,8402270001
- --8402270136 Forwards proposed civil penalty enforcement package resulting from unannounced physical security inspiron 791126-30 & 1211-12 Security enforcement history & proposed press release also forwarded W/v encl.
 ENGELKEN.R H Region 5, San Francisco, Office of the Director. 79/12/31 HOMARD.E M Division of Safeguards Inspections 2pp 22395 093 24X Fiche 50-344.83/12/12.8402270001
- --B402270146 Advises that licenses adjusted expected completion dates for portions of approved security plan.NRR-approved schedule located in App B of security plan info deleted Three-yr enforcement history encl MORTERNEEN.W P Region 5, San Francisco, Office of the Director. 80/01/16 HOWARD,E M Division of Safeguards Inspections 10pp 22413 180 24X Fichè 50-344,83/12/12,8402270001
- 8402270009 Further response to FOIA request for four categories of documents Forwards documents listed in app Documents also available in PDR FELTON,J M Division of Rules and Records 84/02/02. SHOLLY: 8 C Union of Concerned Scientists 2pp 22407 336

475

- --B402270011 Trip rept of 830916-27 meetings in Japan & Taiwan re source term research, PRA research collaboration w/JAERI, severe accident issues. Taiwan PRA project, BWR-6 operational experience & Taiwan nuclear emergency preparedness BERNERO, R M Accident Source Term Program Office 83/10/20 MINOGUE, R B Office of Nuclear Regulatory Research, Director 5pp 22407 358
- ~-B402270013 Notifies of B30921-22 trip to Tokyo & Tokei to discuss development of scientific basis for revised estimates of reactor accident source terms severe accidents in water reactors & changes in regulations & PRA
 BERNERD, R M Accident Source Term Program Office B3/09/09
 OYAMA: A Japan. Govt of 3pp 22408.001
- --8402270016 Trip rept re 830923-27 visit to Taipei, Taiwan re PRA Viewgraphs encl BERNERO, R M Accident Bource Term Program Office 83/10/20 JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 24pp 22408 004
- 8402270036 Responds to FDIA request for NRC emergency planning zone maps for facilities Maps may be reproduced for listed costs or examined at Region III ofc FELYON, J. M. Division of Rules and Records 84/02/01 MOHLENBERGER, O. Mobil 011 Corp (subs Mobil Corp.) ip 22407 336 24X Fiche 50-010,84/02/01,8402270036
- B402270040 FDIA request for NRC emergency planning zone maps for facilities.

 NO4.EMERGER, O Mobil Oil Corp (subs Mobil Corp) 03/12/27 NDRRY, P Defice of Administration 1p. 22407 337 24X Fichs 50-010,03/12/27.0402270040
- 8402270846 Final response to FDIA request for three categories of documents re completion of accelerated requalification program by facility supervisor of operations NRC has no further documents subj to request FELTON, J M Division of Rules and Records 84/01/27 MAUPIN, M W Hunton & Williams 1p. 22407 332 24X Ficbe 50-320,84/01/27,8402270046
- 8402270031 Further response to FOIA request for five categories of documents re facility Forwards App A documents App C documents partially withheld & App D documents entirely withheld (ref FDIA Exemption 7) FELTON, J M Division of Rules and Records, 84/01/26 LYGN, V F Lyon & Kurz. 5pp 22411 171 24X Fichs 50-382,84/01/26,8402270051
- --BIO5120144 Forwards input to facility safety evaluation Review incomplete due to NRC low level staffing & mpt HANAUER, 8 H Division of Human Factors Bafety. Bi/05/07 TEDESCO, R L Assistant Director for Licensing 27pp 22411 178 24% Fiche: 50-382, 84/01/26, 8402270051.
- --8209290283 Comments on encl draft IR Insp Rept 50-382/82-14 & enforcement action. Plant is ideal candidate for const team insp
 HARPSTER, T.L. Quality Assurance. 82/08/31, LIESERMAN, J
 Enforcement Branch (Pre 820201) 19pp 22411*210 24X
 Fiche 50-382, 84/01/26, 8402270081
- --8402270062 Confidentiality agreement Related info encl Info deleted * Affiliation Not Assigned 83/07/22, 3pp 22411 254.
- --8402270064 Discusses complaint re mistreatment of people Related info encl Info delated e Office of Investigation 83/06/27 Office of Investigation. USP 22411-257
- --B402270067 Discusses Inquiry Case File G4-B3-017 re facility, Inquiry closed & Investigation 4-B3-014 opened.
 DRISKILL, D. D. Region 4, Office of Director, B3/07/26 Region 4, Office of Director 1p 22411 270 24X Fiche 30-382, B4/01/26, B402270051
- B402270072 Final response to FOIA request for Commissioner voting & attendance records from 810401 to present. Forwards documents 11sted on App A Documents also available in PDR. FELTON, J K Division of Rules and Records 83/12/22. KAMENAR, P D Washington Legal Foundation 3pp. 22410-107. 24X Fiche 50-528,83/12/22,8402270072
- --8304040850 Advance copy of staff requirements memo re B30315 discussion & passible vote in Washington, DC on contested issues in full power proceeding CHILK, S. J. Office of the Becretary of the Commission. MB30315A B3703718 DIRCKS, W. J. Office of the Executive Director for Operations. Ip 22410, 146. 24X Fiche: 50-528, B3712/22, B402270072

- --8402270092 Discusses SECY-81-359 re technical assistance in support of NRC reactor licensing CHILKS J Office of the Secretary of the Commission 581-359 B1/07/20 DIRCKS.W J Office of the Executive Director for Operations ip 22410 180
- --8402270107 Discusses SECY-Bi-397 re executive branch response on proposed export of tritium gas to Israel CHILK.S J Office of the Secretary of the Commission SB1-397 B1/07/24 DIRCKS.W J Office of the Executive Director for Operations ip 22410 164
- --8402270127 Discusses SECY-81-415 Te proposed license to export deuterium oxide to 22 countries
 CHILK-8 J Office of the Secretary of the Commission S41-415
 B1/08/03 DIRCKS-W J Office of the Executive Director for Operations. 1p 22410 170
- --B402270133 Discusses SECY-B1-385 re approval of proposed license & amends to export low enriched U to Spain HOYLE.J C Office of the Secretary of the Commission B1/08/14 DIRCKS.W J Office of the Executive Director for Operations ip 22410 172
- --8402270141 Discusses SECY-81-462 re approval of proposed license to export high enriched U to Sweden CHILK.S J Office of the Secretary of the Commission 81/08/25 DIRCKS W J Office of the Executive Director for Operations ip 22410 175
- --8402270149 Discusses SECY-BI-430 re approval of proposed license to export high enriched U to Federal Republic of Germany CHILK, B J Office of the Secretary of the Commission BBI-430 BI/09/03 DIRCKS, W J Office of the E
- --8402270154 Discusses SECY-82-13 re fire protection rule schedules & exemptions (duarterly Rept 4)
 CHILK,8 J Office of the Secretary of the Commission SB2-13
 82/02/08 DIRCKB, N J Office of the Executive Director for Operations ip 22410 252
- --8402270162 Discusses SECY-81-676 re delegation of rulemaking authority to EDO CHILK,S J Office of the Secretary of the Commission 82/02/18 BICKWIT,L Office of the General Counsel ip 22410 254
- --8402270165 Discusses SECY-82-42 re proposed amended agreement between NRC & State of TX per Section 274 of Atomic Energy Act of 1994, as amended CHILK, 8 J Office of the Secretary of the Commission 982-42 82/02/26 DIRCKS, WJ. Office of the Executive Director for Operations ip 22410 256
- --B402270170 Discusses SECY-82-134 re AD recommendation on blockage of combant flow to safety-related sys & components CHILK,8 J Office of the Secretary of the Commission 82/04/27 DIRCKS,W J Office of the Executive Director for Operations 1p 22410,279
- --B402270179 Discusses SECY-82-137 re AO recommendation on major deficiencies in mpt CHILK, 3 J. Diffice of the Secretary of the Commission 82/06/03 DIRCKS.N. J. Office of the Executive Director for Operations in 22410 290
- --8402270183 Discusses SECY-82-37A re procedures for controlling generic requirements on reactor licenses CHILK, 8 J Office of the Secretary of the Commission \$2/06/16 DIRCKS, W J Office of the Executive Director for Operations 1p 22410:275.
- --8402270192 Discusses SECY-81-615 re proposed schedule for license fees CHILK, B J Office of the Secretary of the Commission 82/09/24 DIRCKS, W J Office of the Executive Director for Operations ip 22410, 322
- --8402270198 Discusses SECY-82-380 re NRC releasting to amend 10CFR2 201 CHILK, 8 J Office of the Secretary of the Commission 82/10/20 DIRCKS, W J. Office of the Executive Director for Operations ip 22410 330
- --8402270204 Discusses SECY-82-434 re DOJ request for NRC views on Bilkwood vs Karr-NtGee Corp CHILK,8 J Defice of the Secretary of the Commission. 82/11/02 BICKWIT.L Defice of the General Counsel ip 22410 331.

- ~-B402270211 Discusses SECY-B2-111B re requirements for emergency response capability CHILK.6 J Diffice of the Secretary of the Commission 82/11/22 DIRCKS.W J Office of the Executive Director for Operations 1p 22410 344
- --8402270216 Staff requirements memb re SECY-82-462/462A on human factors program plan CMILK.S J Diffice of the Secretary of the Commission. 83/02/16 DIRCKS.W J Office of the Executive Director for Operations 19 2241 001
- --8402270221 Discusses SECY-B2-456 re physical protection requirements for nonpower reactor licensess possessing formula quantities of SSIM CHILKS J Office of the Secretary of the Commission B3/06/22 DIRCKS, H J Office of the Executive Director for Operations 1p 2241 031
- 8402270180 FDIA request for documents re Sandia Contract A-1123 & bibliography on consequence studies referenced in R Bernero ltr RUTLEDGE.P Carolina Environmental Study Group FIN A-1123 B3/10/27 FELTON, J M Division of Rules and Records 1p 22411 041
- B402270184 Partial response to FOIA request for documents re Sandia Contract A-123 & bibliography referenced by R Bernero Forwards App A documents info available at NRC ofcs in Bethesda, ND FELTON, J M Division of Rules and Records FIN A-1123 B3/12/14 RUTLEDDE. P Carolina Environmental Study Oroup 4pp. 22411 042
- --8104280266 Forwards std order for DOE work "Biting Rulemaking on Population & Offsite Maxerds," issued to Sandia Lab. VOLLMER,R # Division of Engineering 81/04/20 ROSER,H E Energy, Dept of 1p 22411,143
- ---8104280270 8td order for DDE work. "Siting Rulemaking on Population & Offsite Hazerds." issued to Bandia Lab GRENIER. B t. Technical Assistance Contracts Branch FIN A-1123-1 20-81-202 81/03/15. 2pp 22411 144
- --8307290458 "Variability of Site-Reactor Risk "
 MARQULIES.T S Reactor Risk Branch 83/07/15 15pp 22411 046
- --8402270189 SAND79-0095
 "Effact of Revised Evacuation Model on Reactor Safety Study
 Accident Consequences"
 ALDRICH D.C., RITCHIE, L.T., SPRUNG J.L., Sandia Laboratories FIN
 A-1042 79/02/28 25pp 22411 087
- --8402270196 Forwards Std Order for DOE Work 20-80-234, "Siting Rulemaking on Population & Offsite Hazards," issued to Sandia Natl Labs Proposal requested. VOLLMER;R H Division of Engineering FIN A-1123 80/07/08 ROSER;H E Energy, Dept of 2pp 22411:111
- --B402270201 Std Order for DOE Work 20-B0-234, "Site Rulbmaking on Population & Offsite Harands," issued to Bandia Nati Labs GRENIER.B L. Division of Engineering FIN A-1123-0 20-80-234 B0/07/08 7pp 22411:113
- --B402270206 Forwards Std Order for DOE Work 20-80-290, "Siting Rulemaking on Population & Offsite Hazards." Issued to Sandia Nati Labs. Proposal dtd B00801, acceptable VOLLMER, R H Division of Engineering. FIN A-1123-0 80/09/09 ROSER, H E Energy, Dept of. 2pp 22411 122
- --8402270208 Std Order for DBE Work 20-80-290, "Siting Rulemaking on Population & Offsite Harards," (seed to Sandia Natl Labs GRENIER.B L Division of Engineering FIN A-1123-0 20-80-290 80/09/08 lp 22411:124.
- --8402270214 Forwards Std Order for DGE Work 20-81-83, "Siting Rulemaking on Population & Offsite Hazards," issued to Sandia Natl Labs Proposal dtd 800801, acceptable VOLLMER, R H Division of Engineering FIN A-1123-0 81/01/13 ROSER, H E Energy, Dept of 2pp 82411-128
- --8402270217 8td Order for DOE Work 20-81-83, "Siting Rulemaking on Population & Offsite Hazards," issued to Sandia Natl Labs. GRENIER, B L. Division of Engineering FIN A-1123-1 20-81-83 BI/01/07 13pp 22411 130
- -8402270224 Forwards Std Order for DDE Work 20-81-375, "9iting Rulemaking on Population & Offsite Hazards:" issued to Sandia Natl Labs Order provides addl funds for completion of mod Revised graposal nat required VOLLMER.R H Division of Engineering FIN A-1123 81/08/14 CLARK, T.R Energy, Dept. of 1p 22411 146

- --8402270230 8td Order for DDE Work 20-81-375, "Siting Rulemaking on Population & Offsite Harards," issued to Sandia Nati Labs GRENIER, B L Division of Engineering FIN 8-1123-1 20-81-375 81/08/11 Spp 22411 147
- --8402270232 Forwards first rough draft siting rept Comments welcose W/s enc! STRIP.D R Sandia Laboratories 81/10/29 MDRRIB.J fliting Analysis Branch 1p 22411 150
- --8402270237 Questions R Blond role as principal author on rept Role thought to be one of providing guidance re direction of effort Related info encl REGAN.B NRC - No Detailed Affiliation Given 82/01/27 ALDRICH.D Sandia Laboratories 2pp 22411 151
- --B402270R41 Forwards voucher for suce rendered by DOE Billing appears within parameters of std order for DDE work
 DANDDIS.D 8 Division of Accounting & Finance 62/05/06.
 BLODD.R Office of Nuclear Regulatory Research, Director 2pp
 R2411 153
- --8402270244 Submits status rept of progress on budget for nuclear your plant siting program Tasks remaining for program completion outlined ALDRICH,D C Bandia Laboratories FIN A-1123 82/05/10 REGAN.W Siting Analysis Branch 3pp 22411 159
- --8402270248 Forwards vouchers for svcs rendered by DDG Billing within parameters of std order for DDE work
 DANDOIS.D B Division of Accounting & Finance. FIN A-1123-1
 82/05/08. SLDND, R Office of Nuclear Regulatory Research.
 Director 5pp 22411 158
- --8402270251 Forwards voucher for eves rendered by DQE Billing within parameters of std order for DQE work
 DANDOIS.D B Division of Accounting & Finance FIN A-1123-1
 82/06/25 BLCND,R Office of Nuclear Regulatory Research,
 Director ip 22411 163
- --8402270256 Forwards official project file re transfer of responsibility for FIN A-1123 Feb.Mar & Apr 1782 vouchers also encl Addl funds required for Bandia to complete project GRENIER: B L Plenning & Program Analysis Staff FIN A-1123 82/07/07 BLOND.R M Division of Risk Analysis 2pp 22411:164
- ---8402270260 Corrects severe misinterprotations by Washington Post articles & subsequent wire svc repts of reactor accident consequences. Likelihood of experiencing peak consequences is once in one billion yrs Related info encl

 BNYDER.A W Bandia Laboratories B2/11/12 PALLADINO.N J

 Commissioners 5pp 22411 166
- B402270246 FOIA request for copies of licenses & current ref supporting documents for companies & individuals licensed to perform radiation detection instrument calibr MIKOMSKI, J. Standard Nuclear Consultants, Ltd B4/01/04. SMITH, P. Region 3, Office of Director ip 22413:190
- B402270247 FOIA request for JC Mark B01204 memo to ACRB re hydrogen burn w/igniters & documents to or from ACRB concerning generation, combustion or control of hydrogen in reactor accidents MIATT, B L Ohio Citizens for Responsible Energy B4/01/02 FELTON, J M. Division of Rules and Records. 1p 22412:050.
- 8402270250 Responds to FOIA request for copies of licenses & current ref supporting documents for companies & individuals licensed to perform radiation detection instrument calibr. Forwards App A documents FELTON, J M Division of Rules and Records 84/02/08 MIKOWSKI, J Btandard Nuclear Consultants, Ltd 3pp. 22413 191
- --7909170149 Forwards add1 info requested by NRC 790427 ltr reapplication to renew Mat1/Byproduct License 12-09160-01 Includes copy of calibr procedure rept of transfer instrument calibr & instrument svc record RIVKIN.W.B. Health Physics Associates, Ltd 98998. 79/08/24. BROWN.J M Material Licensing Branch 44pp 22413-194
- --B001040264 Application for renewal of Matl/Byproduct License 34-16272-01 authorizing Co-60.Ba-133.Cs-137.Tc-99m & any byproduct matl w/atomic numbers 3-B3 for use in calibr. EARLY.P.J. Nuclear Medicine Associates, Inc., Cleveland, OH 01998 79/11/27 43pp 22413 327
- --8001090206 Forwards application for Matl/Byproduct License 24-18931-01 LARIMORE,E Larimore, R E. 02478 79/11/03, Material Licensing Branch 1p 22413 305

- --8001090209 Application for matl/byproduct license authorizing RE Larimore to use Cs-137.Ba-133.Cs-137 & Tc 99m in sealed sources for calibr LARIMORE, R E Larimore, R E 02478 79/11/01 17pp 22413 Larimore, R E 02478 79/11/01 17pp 22413 306
- --B002130492 Application for amend of Matl/Byproduct License 12-09160-01 Amend authorizes use of Am-241 sealed sources for calibr of radiation survey instruments RIVKIN.W B Health Physics Associates, Ltd 02921 80/01/17 3pp. 22413 239
- --8402270258 Forwards application for amend to License 12-09160-01 RIVKIN.W B Health Physics Associates, Ltd 80/01/17 Divi of Fuel Cycle & Material Safety 1p 22413 238 Division
- --B402270265 Application for renewal of Matl/Byproduct License 12-17162-02, authorizing R Dielman & L Zimmer to use Cs-137 sealed source in calibr of survey meters DIELMAN.R W Dielman Consultants. Inc B2/03/19 4pp
- --8402270268 Forwards requested info re renewal application for Suproduct matl license DIELMAN,R W Dielman Consultants, Inc 82/08/24 MCCANN,M Ragion 3, Office of Director 5pp 22413 246
- --8402270273 Matl/Byproduct License 12-17162-02 for Dielman Consultants.
 Inc.authorizing use of Cs-137 sealed source for calibr of
 radiation detection instruments (ref License 12-17162-01)
 MALLETT.B B Division of Fuel Cycle & Material Safety 82/09/16
 3pp 22413 251
- --B402270276 Application for amend to Matl/Byproduct License 12-17162-02.
 reflecting address change, telephone number, address where
 matl will be used & stored & change in calibr procedure
 DIELMAN, R Dielman Consultants, Inc 83/02/07 3pp 22413 254
- --8402270278 Amend 9 to License 12-17503-01, authorizing use of Cs-137 in Tech Ops Madel 773 calibrators for calibr of instruments HICKEY, U, W Division of Fuel Cycle & Material Bafety 83/01/24 ip 22413 287
- ---8402270283 Application for renewal of Matl/Dyproduct License 13-07215-01.authorizing JE Durlacher to use Co-57,Co-60, Sr-90,Ir-192 & Cs-137 sealed sources for calibr of survey DURLACHER, J.E. Durlacher, J.E. 78/02/28, App. 22413 289
- --8402270288 Provides add1 info re amend application, in response to 760108 request. Possession limit of 150 mc1 Cs-137 requested CURLACHER. J. E. Durlacher, J. E. 76/02/02 BASSIN, N Redicisotopes Licensing Branch (Pre 790501). 3pp 22413 293
- --8402270293 Amend 7 to License 13-07215-01, authorizing performance tests for leakage &/or contamination upon receipt of sealed sources containing licensed matl & calibr of instruments COMBS.F. G. Radioisotopes Licensing Branch (Pre 790501) 78/08/22 22413: 276
- --8402270296 Forwards response to telcon re application for matl byproduct license approving use of Cs-137 calibr source CARLEGN, R. A. Medical Physics Consultants, Inc. 81/05/22 COOPER, J. Material Licensing Section 2pp. 22413, 299
- ---8402270303 Matl/Byproduct License 21-20153-01 for Medical Physics Consultants, authorizing possession of Cs-137 in Victoreen Model 726 instrument calibrator for survey instrument calibr.
 CDOPER, J. W Division of Fuel Cycle & Material Safety 81/06/22 22413.301
- ---8402270308 Corrected Amend 1 to License 21-20153-01, authorizing Cs-137 sealed source to be used in Tech Ops Model 773 instrument calibrator for survey instrument calibr.

 ADAN & J. Region 3, Office of Director 83/11/17, ip 22413 303.
- --84022703ii Amend 1 to License 21-20133-01, authorizing Cs-137 sealed source to be used in Tach Ops Model 773 instrument calibrator for survey calibr.

 ADAM, M. J. Region 3. Office of Director 83/10/27 ip. 22413:304.

- --8402270322 Amend 4 to License 24-18831-01.authorizing use of Cs-137 & Ba-133 in leak test samples & wipe test samples for analysis & calibr of dose calibrator MCCANN.0 M Region 3, Office of Director 83/11/18 3pp 22413 323
- --8402270324 Forwards application for renewal of Matl/Byproduct License 1022/UG4+ Formarus application ... 34-16272-01 EARLY,P J Nuclear Medicine Associates, Inc., Claveland, OH 79/11/27 Division of Fuel Cycle & Material Bafety ip 22413 326
- --B402270335 Amend B to License 34-16272-01, authorizing use of Cs-137. Ba-133.Co-60 & Tc-97m to perform tests for leakage/ contamination on sources & devices specified in 810107 ltr MALLETT.B Division of Fuel Cycle & Material Safety 81/12/08 4pp 22414 008
- ~-B402270341 Responds to B10403 ltr re Matl/Dyproduct License 34-16779-01 & procedures for survey meter calibr CALLENDINE, O Callendine, G W 81/06/11 MALLETT, B 8 Material Licensing Section 2pp 22414 012
- ~-8402270347 Corrected Amend 1 to License 34-16779-01, authorizing Co-60. Sr-90 & Ba-133 wealed sources for calibr of radiation survey & measurement instruments MCCANN.C M Region 3. Office of Director 82/11/15 3pp MCCANN, 0 M 22414 014
- 6402270263 Responds to FOIA request for JC Mark BO1204 memo to ACRS re hydrogen burn w/igniturs & documents concerning generation, combustion or control of hydrogen in reactor accidents forwards App A documents App B documents in PDR FELTON, J M Division of Rujus and Records B4/01/30 HIATT, S L Ohio Citizens for Responsible Energy 7pp 22412 051 24X Fiche 50-000, 84/01/30, 8402270263
- --8012310632 Forwards Dupont info supporting position that hydrogen generated in TMI accident was more than 10 times less than generally accepted number BHEWHON.P G ACRS Advisory Committee on Reactor Safeguards 80/10/30 ACRE Advisory Committee on Reactor Safeguards 27pp 22412 090 24X Fiche 50-000.84/01/30.8402270263
- --8101270309 Advises that pressure whike at facility containment sys following accident was caused by hydrogen burn released by inconium-water reaction interpretations & alternative zirconium-water reaction Interpretations & alevernovive conclusions discussed MARK.J C ACRS - Advisory Committee on Reactor Safeguards 80/04/07 ACRS - Advisory Committee on Reactor Safeguards Acrs - Advisory Committee on Reactor Safeguards App 22412 058 24X Fiche 50-000,84/01/30,8402270263
- --8107280183 Forwards rept. "Status of Hydrogen Control Activities" Parts of rept will be discussed in NRC 810910 meeting w/ ACRS ACRB RUBENSTEIN,L S Assistant Director for Core & Containment Bystems 81/09/04 MARK,J C ACRS - Advisory Committee on Reactor 8afeguards 2pp 22412 207
- --8110300111 Advises that review of post-accident inerting sys for facilities will continue during post-CP period. Early review of work progress during Spring 1982 would be beneficial MATTSON,R J Division of Systems Integration (post 811005) 81/10/07 FRALEY,R F ACR8 Advisory Committee on Reactor Safeguards (p. 22412 207 24X Fithe 50-000.84/01/30,8402270263
- --8306290165 Responds to 830429 ltr re survivability of safety-related equipment if large amounts of hydrogen burned in large, dry PMR containments Current requirements provide high assurance of squipment survivability in hydrogen burn DIRCKS, M J Office of the Executive Director for Operations 83706707 EDERSOLE, J C ACRS Advisory Committee on Reactor Safeguards 6pp 22412 221
- --8402270282 Summary of 800520 meeting w/natl labs, Westinghouse, NRC & utils in Bethesda, MD re hydrogen technology Meetings scheduled for 800403 & 0617 to discuss FVCS & core retention devices & containment structural response, respectively GUITTSCHREIBER ACRS Advisory Committee on Reactor Safeguards 80/05/22 ACRS Advisory Committee on Reactor Safeguards. 3pp 22412-064. 24% Fiche. 50-000, 84/01/30, 6402270263.
- --840R270R89 Discusses ACRS review of TVA request for authorization to operate at full power Reasonable assurance should be given that ice condenser containment would hold in event of serious accident GILINSKY. V. Commissioners 80/07/10, PLESSET, M. 8 ACRI Advisory Committee on Reactor Safeguards 1p. 22412 067 Fiche 50-000,84/01/30,8402270263.

- --B402270297 Forwards draft NRR rept on hydrogen control measures
 Proposed ignition sys would effectively prevent
 overpressurization from hydrogen burn based on MARCH &
 CLASIX computer calculations
 BESSETTELD ACRS Advisory Committee on Reactor Safeguards
 B0/08/18 ACRS Advisory Committee on Reactor Safeguards
 122412 072 24X Fiche 50-000.84/01/30.8402270263
- --8402270305 Discusses proposed ACRS Subcommittee on Class 9 Accidents 800828 meeting in Washington-DC to consider hydrogen generation & control during degraded core accidents 8ESSETIE.0 ACRS Advisory Committee on Reactor Safeguards 80/09/03 ACRS Advisory Committee on Reactor Safeguards 3pp 22412 074 24X Fishe 50-000-84/01/30-8402270263
- ~~8402270327 Forwards list of ACRS meetings & Itrs re proposed interim amends to 10CFR50 concerning hydrogen control & certain degraded core conditions H/o encl NGRBERO, J A Engineering Metholology Standards Branch BO/11/06 SIESS.C P ACRS - Advisory Committee on Reactor Bafeguards 1p 22412 115
- --B402270331 Summary of ACRS Subcommittee on Class 9 Accidents B01121 meeting in Mashington,DC re RES activities in support of degraded core cooling rulemaking BESSETTE,D ACRS Advisory Committee on Reactor Safeguards B0/11/26 KERR:W ACRS Advisory Committee on Reactor Safeguards Sapp. 22412 116
- --8402270337 Forwards collation & discussion of HF Ring opinion that current NRC position overestimates hydrogen production during plant accident by factor of 20 & radiolysis may be major source of hydrogen ETHERINOTON, H ACRE Advisory Committee on Reactor Safeguards 80/12/04 ACRE Advisory Committee on Reactor Safeguards Spp 22412 i19 24X Ficher 50-000, 84/01/30, 8402270263
- --8402270344 Discusses hydrogen burn w/ignitors Related info encl MARK,J C ACRS - Advisory Committee on Reactor Safeguards 80/12/04 ACRS - Advisory Committee on Reactor Safeguards 29pp 22412 127 24X Fiche 50-C00: 84/01/30: 8402270263
- --8402270351 Comments on NUREG/CR-1762, "Analysis of Hydrogen Mitigation for Degraded Core Accidents in Sequerah Nuclear Power Plant " Strong recommendation that ignitors at top of ice condensers be removed debatable MARK.J C ACRS Advisory Committee on Reactor Safeguards 81/02/02 ACRB Advisory Committee on Reactor Safeguards Spp 22412 156 24X Fishe 50-900.84/01/30.8402270263
- --B402270360 Forwards public & industry comments received on interim hydrogen control rule & advance notice of rulemaking on degraded core cooling GUITT8CHREIBER ACRS Advisory Committee on Reactor Bafeguards B1/02/23 KERR.W., DKRENT.D., MDELLER.D. ACRS Advisory Committee on Reactor Safeguards Spp. 22412 170 24X Fiche: 50-000.84/01/30.8402270263
- -8402270371 Forwards portion of ASLB transcript re hydrogen control measures at facilities & Duke Power comments on Bandia concerns Opinion on whether Sandia comments on placement of hydrogen ignitors justifiable requested W/o encl OUITTSCHREIBER ACRS Advisory Committee on Reactor Bafeguards 81/04/08 BICHELM ACRS Advisory Committee on Reactor Bafeguards 91/04/09 BICHELM ACRS Advisory Committee on Reactor Bafeguards 12412-178 24X Fiche 50-000, 84/01/30, 8402270263
- --8402270374 "Comments Re Igniters in Upper Plenum of Ice Condenser of Sequoyah & McGuire Nuclar Power Plants," prepared for ACRS Subcommittee on Clase 9 Accidents. SICHELM Michigan, Univ of Ann Arbor, MI 81/08/17 20pp 22412 184. 24X Fiche 50-000,84/01/30,8402270263
- --B402270415 Discusses proposed interim rules re hydrogen control BEAL, 8 K ACRS - Advisory Committee on Reactor Bafeguards. Bi/09/02 KERR, W ACRS - Advisory Committee on Reactor Bafeguards 3pp. 22412 204.
- --B402270425 Forwards status rept for ACRS Class 9 Accidents Subcommittee gameric safety isques Future work re proposed rule dealing w/ice condensers. Mark III & large dry containments will continue as part of fMI Action Plan I them II B BUCCI.D ACRS Advisory Committee on Reactor Bafeguards 83/03/15 KERR, W ACRS Advisory Committee on Reactor Safeguards 6pp 22412:214
 - 840R270431 Forwards minutes of CROR Meeting 40 on 830601 re hydrogen control requirements rule. Mods to rule in response to CROR comments & recommendations, listed.

 WAND, A ACRS Advisory Committee on Reactor Safeguards 33/07/15, KERR W ACRS Advisory Committee on Reactor afeguards ip 22412,222

- 8402270284 Further response to FDIA request for all 1982 SECY papers Forwards SECY-02-140 Document also available in PDR SECY encls partially & entirely withheld (ref FDIA Exemptions 5 & 7) FELTON, J M Division of Rules and Records 84/02/09 WEISB, E R Harmon & Weiss WEISS, E R Union of Concerned Scientists 3pp 22395-214
- --8402270274 BECY-82-140
 Discusses FOIA Appeal 82-A-2c (Devine) re investigative
 jurisdiction of IE & Ofc of Inspector & Auditor Transmittal
 of proposed ltr (Attachment 4) recommended Info deleted &
 withheld
 BICKWIT.L Office of the General Counsel 82/04/05 5ipp
 22395 217
- 8402270895 FOIA request for five categories of documents re mothballed nuclear const projects BELL.N Nuclear Information & Resource Bervice. 83/11/23. Offic of Administration 2pp 22395 102 24X Fichs 50-508,83/11/23.
- 8402270301 FOIA request for documents re investigation of allegations raised by welding inspectors at facilities COTTINOHAM, A W Debevoise & Liberman 83/08/16 FELTON, J M. Division of Rules and Records ip 22413 001 24X Fiche 50-413,83/08/16,8402270301
- 8402270302 Partial response to FOIA request for five categories of documents re mothballed nuclear const projects App A documents being placed in PDR Document as listed on App B already available in PDR Search continuing FELTON. J M Division of Rules and Records 84/01/20 BELL, N Nuclear Information & Resource Service 3pp 22395 200 24X Fiche 50-000, 84/01/20, 8402270302
- --8402270321 Testimony of JB Martin before Subcommittee on Energy Conservation & Power re nuclear power plants being constructed by WPPSS Related info enci MARTIN.J B Region 5. Office of Director 83/07/14 BApp 22395 104 24X Fiche 50-000,84/01/20,8402270302
- --8402270363 Insp Procedure 92050, "Review of QA for Extended Const Dolay " * Director's Office, Office of Inspection and Enforcement DQASIP 83/01/01 11pp 22395 203
- 8402270306 Responds to FOIA request for documents re investigation of allegations raised by welding inspectors at facilities Forwards App A documents App B documents entirely withheld (ref FOIA Exemption 7) Info also available in FDR. FELTON, J M Division of Rules and Records 84/02/01, COTTINGHAN, A W Debevoise & Liberman App, 22413-002, 24X Fithe 50-413,84/02/01,8402270306
- --8402270312 Discusses allegations re facility GC welding insp Some degree of record falsification & inspector harrassment occurred No handware discrepancies identified Region II review requested Related info encl.

 VAN DORRN.P K NRC No Detailed Affiliation Given. B4/02/01 VORGE, J Y NRC No Detailed Affiliation Given 100pp. 22413 008 24X Fiche 50-413,84/02/01,8402270304
- ---8402270317 Discusses intimidation of inspectors, including threats, curses, humiliation & nonsupport, which could question independence & integrity Info deleted TOBIN, W. J. Affiliation Not Assigned 82/03/24 Affiliation hassigned ip 22413 092
- 8402270369 Further response to FOIA request for all 1982 SECY papers Forwards SECYs 82-160,82-49,82-61,82-13A & 82-13I. Info partially withheld (ref FOIA Exemption 5) Documents also available in PDR FELTON, J M Division of Rules and Records, 84/02/13 WEISB, E R Union of Concerned Scientists 3pp. 22411 271 24X Fiche 30-000,84/02/13,8402270369.
- ---B203060001 SECY-82-113A
 Informs of District Court opinion in City of West Chicago
 Vs NRC Important to prevail on jurisdictional questions
 to avoid litigation in several district courts
 BICKWIT, L. Office of the General Coursel 82/04/12 9pp.
 22412 015,

- --B402270375 SECY-82-016D
 Provides preliminary analysis of opinions issued on 820514
 by DC Circuit in Pane vs NRC re psychological effects of
 restarting facility Info deleted
 MALSCH,M @ Office af the General Counsel 82/05/24 100pp
 22411 275 24X fiche 50-000,84/02/13,8402270369
- --B4022703B0 BECY-82-049
 Discusses delay in hearing schedule due to replacement of Brown & Root Inc as const contractor, change of design engineer & const manager to Bechtel Inc & release of Guadrex Corp rept Info deleted FIT/GERALD, J Office of the General Counsel 82/02/04 i3pg 22411 353 24X Fiche 50-000,84/02/13,8402270369
- --B402270384 BECY-B2-061
 Discusses amends to rules re ex parte communications & separation of functions, proposed on 790301 Info deleted BICKWIT,L Office of the General Counsel B2/02/12 11pp 22412.004.
- 8402270459 Partial response to FOIA request for two categories of documents re facility. Review of add1 documents subj to request in progress Transcript of Commission 831115 closed meeting withheld (ref FOIA Exemptions 5 & 7) FELTON, J M. Division of Rules and Records 84/01/11 HICKEY, J P Shaw. Pittman. Potts & Trowbridge 1p 22395 095 24X Fiche: 30-358, 84/01/11.8402270459
- 8402270469 FOIA request for two categories of documents re facility HICKEY.J E. Shaw, Pittman, Potts & Trombridge 83/11/23 GRIMSLEY.D.H Division of Rules and Records, 2pp 22375 096 24X Fichs.50-358.83/11/23.8402270469.
- 8402270473 FOIA request for entire technical proposal submitted by Univ of South Carolina in response to RFP RS-RES-83-170, "Oeotectonic Studies of Earthquake Zones in Eastern US "CALDMELL.D.M Colder Associates. 84/01/30 FELTON, J. Division of Rules and Records ip 22412.243
- 8402270476 Responds to FOIA request for entire technical proposal submitted by Univ of South Caroline in response to RFP RE-RES-83-170 Forwards requested document Document also available in FDR FELTON, J M. Division of Rules and Records 84/02/09, CALDWELL, D M Colder Associates 1p 22412 244
- --B402270478 "Neotectonics Studies of Earthquake Zones in Eastern US," tschnical discussion, in response to RFP RS-REB-83-170. Personal info deleted.
 TALMANI,P. COLGUHOUN,D. J. South Carolina, Univ. of, Columbia, SC RFP-REB-83-170 84/02/09. 87pp 22412.245
- 8402270479 FOIA request for SECY 83-311, SECY 83-299, SECY 83-292, SECY 83-333 & AEOD/E322 to be placed in PDR 9RABER.L.D NVS Corp. CD-IS-83-478 83/10/24. Division of Rules and Records. Ip 22414, 193.
- 8402270480 F0IA request for documents re NRC duties, functions & background,
 0880RN,T. Affiliation Not Assigned 84/01/03, FELTON,J Office of Administration. ip 22395.099
- 8402270484 Responds to appeal re denial of FDIA request for documents released by J Cummings under Exemption 7(C) Appeal deniad Info withheld to protect identities of FBI personnel CHILK, 8, J. Office of the Secretary of the Commission 84/02/08 FMOMAND Wallace, Hilburn, Clayton, Calhoon & Forster, Ltd 2pp 22412 235.
- B402270485 Responds to FOIA request for documents re NRC. Forwards App A documents. M/o encl FELTON, J. M. Division of Rules and Records. 84/01/13. QSBORN. T Affiliation Not Assigned 2pp 22375. 100.
- 8402270487 Responds to FDIA request for SECY 83-292, SECY 83-299, BECY 83-311, BECY 83-333 & AEOD/E322 to be placed in FDR. AEOD/E322, BECY 83-292 & SECY 83-333 placed in FDR. Portions of SECY 83-297 withheld (ref FDIA Exemption 5) FELTON, J M. Division of Rules and Records, 84/01/12 GRABER, L.D. NUS Corp. 4pp. 22414, 194, 24X Fichs. 50-277, 84/01/12, 8492270487
- ---B30B100453 SECY-B3-292
 Informs of plans to notify all operating LWR licensees that 10CFR50 44 recombiner requirements not applicable to licensees not relient on installed safety-grade purge repressurization sys as primary means of hydrogen control DIRCKB, W. J. Office of the Executive Director for Operations, B3/07/19, 9pp. 22414.204.

- --B30B240177 SECY-B3-333
 Recommends approval of publication of final rulemaking to amend 10CFR2 200 & 10CFR2 201 granting NRC authority to issue notices of violation to nonlicensees & to delegate authority to regional administrators DIRCKG.W J. Office of the Executive Director for Operations 83/08/10 23pp 22414 215
- ~~8310040351 Forwards AEOD engineering evaluation rept. "Damage to Vacuum Breaker Valves as Result of Relief Valve Lifting "Rept implies that qualification program for valves may be inadequate Transmittal to NRR recommended HSU.C Reactor Operations Analysis Branch AEOD/E322 83/09/21 SEYRTIT, K.V. Reactor Operations Analysis Branch 4pp 22414 191 24X Fiche 50-277,84/01/12.8402270487
- --B310060353 "Damage to Vacuum Breaker Valves as Result of Relief Valve Lifting " * Director's Office AEOD/E322 83/09/16 App 22414 200 24X Fiche 50-277,84/01/12,8402270487
- 8402270491 FOIA request for documents re 831025 meeting between util to NRC concerning mgt audit & associated 10CFR2 206 request GARDE.8 P Government Accountability Project 83/11/26 Office of Administration 2pp 22414 250 24X Fiche 50-329,83/11/26,880/270/491
- 8402270494 Responds to FOIA request for documents re util mgt audit & associated 10CFR2 206 request Forwards App A documents App B documents withheld in entirety (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 84/02/09 GARDE, B P Government Accountability Project 6pp. 22414:232 24X Fiche 50-329.84/02/09.8402270494
- ---B307180383 Refers Govt Accountability Project (GAP) 830613 10CFR2 206
 Itr/petition to IE Resolution will require close
 coordination among IE.NRR & Region III.Draft ltr to GAP
 encl
 LIEBERMAN, J Regional Operations & Enforcement Division
 83/06/28 DEYOUNG.R C Director's Office of Inspection
 and Enforcement DENTON.H R Office of Nuclear Reactor
 Regulation, Director 7pp 22414 271. 24X Fiche 50-329.84/02/09,
 8402270494
- --8308040572 Forwards branch input for inclusion in Div of Licensing response to Quvt Accountability Project 830613 ltr reindependent third-party review of soil settlement issues LEAR, Q Structural & Geotechnical Engineering Branch 83/07/27 ADENSAM, E Licensing Branch 4. 3pp 22414 278 24X Fiche 30-329,84/02/09.8402270494
- --B402270497 Draft outline, "Govt Accountability Project 2 206 Petition -Request for Relief Factual Bases " Related info encl * NRC - No Detailed Affiliation Glvem B4/02/09 13pp 22414 258 24X Fiche.50-329,84/02/09,8402270494
- 8402270499 FOIA request for Boeing Computer Svcs Co proposal responding to NRC RFP R8-ORM-83-463 "Developing Automated Contractural Documentation Capability "PADEN, R C Control Data Corp. 83/12/15 NRC No Detailed Affiliation Given, ip 22414 158
- 8402270500 FDIA request for 16 categories of documents re intergranular stress corresion cracking in BMRs.
 BELL:N Nuclear Information & Resource Service 63/10/31. Office of Administration 3pp. 22408 032
- 8402270503 Responds to FDIA request for 16 categories of records re intergranular stress corrosion cracking in BMRs Forwards documents responsive to request FELTON.J.M Davision of Rules and Records. 84/02/09 BELL.N Nuclear Information & Resource Service. 2pp 22408 055.
- --8402270506 Revised project & budget proposal for NRC work "Evaluation & Acceptance of Welded & Weld-Repaired Stainless Steel for LWR 8vc"

 ATTERIDGE, D. G., PAGE, R. E., BRUEMMER, B. M. Battelle Hemorial Institute, Pacific Northwest Laboratory FIN 8-2449 83/06/30. MUSCARA, J. Materials Engineering Stanch. 19pp 22408 057

- --8402270513 Discusses corrective measures taken by Japanese utils against stainless steel stress corrosion cracking in piping of BMRs Forwards rept. "Outline of Countermeasures Against Stress Corrosion Cracking "
 LAFLEUR.J D Office of International Programs. Director 83/11/02 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 22408 161
- --8402270518 "Outline of Countermeasures Against Stress Corrosion Cracking in Austenitic Stainless Steel Piping of BWR Plants " * Tokyo Electric Power Co , Inc * Toshiba Corp * Ishiba Jima - Harima Heavy Industries Co ,Ltd 82/11/15 21pp 22408 163
- --8402270520 "Development & Qualification of Repair Procedures Against Stress Corrosion Cracking in Austentic Stainless Steel Piping " * Tokyo Electric Power Co , Inc * Toshiba Corp * Ishikawajima Harima Heavy Industries Co , Ltd 83/01/31 24pp 22408 184
- info encl Tokyo Electric Power Co / Inc 83/04/30 107pp. 22408 207
- 8402270504 Responds to FOIA request for Boeing Computer Svcs Co proposal responding to NRC RFP RB-DRM-B3-463 "Developing Automated Contractural Documentation Capability " Forwards proposal FELTON, J M Division of Rules and Records 84/01/12 PADEN, R C Control Data Corp 10 22414 159
- --8402270509 Revised "Developing Automated Contractual Documentation Capability," technical proposal Info deleted * Boring Computer Services, Inc (subs. of Boeing Co) RS-DRH-83-463 83/08/30 Division of Contracts 33pp 22414 160
- 8402270517 FOIA request for documents re 830908 meeting between NRC & Fansteel Hetals concerning processing columbian/tantalium one containing U thorium which requires NRC source matl HARMITT, H A FOI Services 3404 83/12/21 FELTON, J H Division of Rules and Records 1p 22412 332
- B402270323 Responds to FOIA request for documents re 830908 meeting between Fansteel Metals & NRC.Forwards App A document FELTON, J M Division of Rules and Records 84/01/16 HAMMITT, H A FOI Services 2pp 22412 333.
- ---B401190482 Summary of 830908 seeting w/licensee in Bilver Spring.MD replans for ultimate disposition of solid waste generated by treatment of liquid stream RHODES.M J Uranium Fuel Licensing Branch B3/09/14 Uranium Fuel Licensing Branch ip 22412 335 1 p
- 8402270531 Responds to FDIA request for records re T Novak visit to Region III ofc to discuss Ofc of Special Cases findings re facilities from Sept 1982 Dec 1983 No records subj to request located FELTON, J M DI request located
 FELTON, J M Division of Rules and Records 84/01/12 GARDE, B P
 Government Accountability Project, ip. 22414: 155 24X
 Ficke-50-329, 84/01/12, 8402270531
- 8402270532 Requests duplicate color negative of aerial photograph of oblique 45 degree angle aerial shot of facility taken by E080 in 1983
 FARR.K M Consumers Power Co KMF83*119 83/12/21 NRC No Datailed Affiliation Given 1p. 22414 153 24X
 Fiche. 50-255, 83/12/21, 8402270532.
- B402270535 Responds to FUIA request & forwards duplicate color negative of aerial photograph of facility M/o encl FELTON, J M Division of Rules and Records 84/01/13, FARR.K.M Consumers Power Co 1p 22414 154. 24X Ficha 50-255,84/01/13, 8402270535
- 8402270536 FOIA request for agency records & info generated in connection w/or as result of T Novak visit to Region III ofc to discuss Ofc of Spacial Cases findings on facilities from Sept 1782 Dec 1783 OARDE.B P Government Accountability Project 83/11/26 Off of Administration 2pp. 22414 156 24X Fiche. 50-329,83/11/26,8402270536
- B402270539 Further response to FOIA request that seven categories of documents re NRC regionalization program be placed in PDR Documents placed in PDR FELTON, J H Division of Rules and Records 84/01/11 LOWENTHAL, J Nuclear Information & Resource Service ip. 22414 150

- 8408270542 FOIA request for Contract NRC-33-452-02 w/Advanced Technology, Inc & Proposal COHEN, M Computer Data Bystems, Inc NRC-33-452-02 83/12/29 Division of Contracts 1p 22414 148
- 8402270543 Responds to FOIA request for 11 documents ra Kerr-McGee Cimmaron facility Correspondence dtd 670627-711011 not located Remaining records available in PDR FELTON. JM Division of Rules and Records 84/01/12 BARNER. C Affiliation Not Assigned ip 22414 146
- B402270544 Responds to appeal re denial of FOIA request for documents re NRC const assessment team insp conducted from 830706-30 at facilities Rept provided on 831201 FELTON.J M Division of Rules and Records 84/01/12 BERNABET.L. Government Accountability Project 1p 22414 142 24X Fiche 50-528.84/01/12.8402270544
- 8402270346 FOIA request for listed documents re Kerr-McCee Cimmaron DARNES, C Affiliation Not Assigned 83/12/11 Office of Administration ip 22414 147
- B40227054B Responds to FOIA request for Contract NRC-33-B3-452-02 awarded to Advanced Technology, Inc & proposal Contract available in PDR FELTON.JH Division of Rules and Records NRC-33-B3-452-02 B4/01/13 COMEN,M Computer Data Systems, Inc ip 22414:149
- B402270550 Appeals denial of FOIA request for documents rs NRC censt assessment team insp conducted from B30906-30 at facilities BERNABELL Government Accountability Project. B3/12/05 Office denialistration ip 22414 143 24X Fichs. 50-528, 83/12/05. 077164
- 8402270555 FOIA request for all agency records & info re NAC const assessment team insp conducted from 830904-30 at facilities. BERNABELL Government Accountability Project 83/10/07. Off of Administration 2pp 22414,144 24
- 8402270559 FOIA request for list of business or individuals licensed to hold radioactive matls or produce nuclear waste products in State of SD & license issued to Dale Electronics & related info DUFFY, M Yankton Daily Press & Dakotan, Yankton, 80, 83/12/19 NRC - No Datailed Affiliation Given. 1p 22414.108,
- 8402270548 Responds to FDIA request for records stating NRC policy on inspecting nuclear power plants under const where const suspended App A documents available in FDR FELTON.J M Division of Rules and Records 84/01/11. BELL.N Coalition for Safe Power. 2pp 22414 102
- 8402270373 Responds to FOIA request for list of nuclear waste licenses in State of SD & Dale Electronics-related documents. Forwards A documents. App A documents. FELTON,J H. Division of Rules and Records - 84/01/04 DUFFY.H. Yankton Daily Press & Dakotan, Yankton, SD. 2pp. 22414.109.
- --8402270588 License 40-16545-01E for Dale Electronics, Inc authorizing distribution of HS gas in electronic surge arrester spark gap tube Models LA-27 SI.

 COLLINS.D.M Division of Fuel Cycle & Material Safety. 75/04/28 LINS D. H. Division of Fuel Cycle & Material Safety. 75/04/28 22414 113.
- --B402270591 License 40-16545-01E for Dale Electronics, Inc authorizing distribution of H3 gas in electronic surge arrests spark gap tube Models LA-29 Si BUCHANAN, CR Division of Fuel Cycle & Material Safety, 75/06/03 ip 22414 114.
- --B402270599 Amend to License 40-16545-02 for Dale Electronics. Inc authorizing JJ Kostel to use & supervise Use of licensed matis. BASSIN.N Radioisotopes Licensing Branch (Pre 790501) 77/10/18 ip 22414·115
- --8402270603 Forwards application for renewal of Licenses 40-16545-01E & 40-16545-02 Application continues current program KOSTEL.J J Dale Electronics. Inc. 80/03/25. Division of Fuel Cycle & Material Safety ip 22414 116

- --8402270609 Application for renewal of Licenses 40-16545-01E & 40-16545-02, authorizing use of H3 in electronic surge arresters (spark gaps) for Models LA-29 31 K08TEL, J J Dais Electronics, Inc 80/03/25 Spp 22414 117
- --B402270617 Amend to License 40-16545-01E for Dale Electronics, Inc. authorizing distribution of H3 gas in electronic surge arrestor spark gap tube Models LA-29 - 31 QUINN.P.R Material Licensing Branch 81/06/29 ip 22414 12:
- -8402270619 Amend to License 40-16545-02 for Dale Electronics, Inc. authorizing use of H3 gas for mfg of electronic surge arrestors (spark gaps) QUINM.F.R. Material Licensing Branch 81/06/19 2pp 22414 123
- --B402270623 IE Insp Rept 30-11218/80-01 on 801001-02 No noncompliance noted. Major areas inspected previous noncompliance actions Related info encl BROPENN NRC No Detailed Affiliation Given 80/11/17 14pp 22414.125
- 8402270585 Requests explanation re lack of NRC documents available, addressing Items 1.2 & 3 in FOIA 83-515 request BELLN. Coelition for Safe Power 83/11/01 FELTON, J. Office of Administration 1p 22414.104
- 8402270637 FOIA request for Ref 2.3.4 & 9 of rept entitled. "Rept on Adequacy of Safety & Relief Valve Testing & Performance," to be placed in PDR PEDRO.J NUS Corp. CD-IS-83-665 83/12/29 Division of Rules and Records. in 22414 031
- 8402270639 Responds to FDIA request for Ref 2.3.4 & 9 of rept entitled, "Rept on Adequacy of Bafety & Relief Valve Testing & Performance." Documents placed in PDR FELTON.J.M. Division of Rules and Records 84/01/12 PEDRO,J NUS Corp. 1p. 22414:032.
- -8402270544 Safety evaluation supporting continued PMR operation w/ Dresser primary safety valves per TMI Item II.D 1 Related info encl. CARUBOM, CHERNY, F., ENCH, R. Dffice of Nuclear Reactor Regulation, Director 83/04/18, 25pp. 22414 033
- 8402280018 Further response to FOIA request for documents generated, or received by MRC since 820331 re Hayward Tyler Pump Co. Forwards App A documents App A documents placed in FDR App B documents withheld (ref FOIA Exemption 5) FELTON, J. M. Division of Rules and Records. 83/12/21, LODGE, B, Dallas Horping News Spp 22430, 209 24X Ficher 50-471, 83/12/21, 8402280018
- --B4022B002O Reaffirms Committee on Interior & Insular Affairs belief that NRC investigation of Hayward Tyler Pump Co will not be compromised by media publicity. CHENEY, D., COBELHO, T. House of Rep. B2/06/24, PALLADINO, N.J. Commissioners, Ip. 22430:212
- -8402280027 Responds to 821110 request for answers to several questions left outstanding re subcommittee 820406 hearing concerning MRC investigation of Hayward Tyler Pump Co Responses to questions presented in Encl 1. W/o encl.
 PALLADING.N.J. Commissioners 82/11/24 MARKEY,E J House of Rep.; Interior & Insular Affairs 3pp. 22430:213
- --B402280031 Opines that J Cummings 821127 memo transmitting Ofc of Inspector & Auditor review of recent investigation rept of Hayward Tyler Pump Co should be withheld until rept released.
 PARKISH, R. A. Office of the General Counsel, 82/12/14 COMES, T. R. Office of the General Counsel, 82/2/14 COMES, T. R.
- --8402280035 Requests concurrence %/or comments re-proposed ltr to Markey responding to 821110 questions left outstanding following 820406 subcommittee hearing concerning NRC investigation of Hayward Tyler Pump Co. CHILK, 8, J. Office of the Secretary of the Commission. CR-82-127. 82/12/14, PALLADING, GILINSKY, AHEARNE Commissioners. ip. 22430:217
- ---8402280039 Informs of suicide of Hayward Tyler Pump Co GA manager. + Commissioners. 83/01/06. NRC - No Detailed Affiliation 91van. 1p. 22430; 218.
- ~8402280042 Requests concurrence 4/or comments on enci proposed response to Markey 830127 itr requesting additinfo re Hauward Tyler Puep Co Investigation Response by 830224 requested. CHILK, B. J. Diffice of the Secretary of the Commission. CR-83~20. 83/02/17. PALLADINO, OILINSKY, AHEARNE Commissioners Spp. 22430:219.

- --84022B0045 Requests five listed categories of documents for assistance in author investigation into NRC insp & investigation programs arising from controversy over Hayward Tyler Pump Coinquiry,
 MARKEY, E. J. House of Rep., Interior & Insular Affairs. 83/03/17
 PALLADING, N. J. Commissioners. 2pp. 22430-222
- --84022800&i Forwards info re NRC investigations in response to 830317 request Encls 2 & 3 contain lists of investigations completed by Ofc of Inspector & Auditor & Ofc of Investigations W/o encls PALLADING.N J Commissioners 83/05/17 MARKEY.E House of Rep , Interior & Insular Affairs 1p 22430 224
- --8402280069 Advises that subcommittee 830520 hearing on Hayward Tyler Fump Co will be postponed, due to Commission failure to respond in timely fashion to 830317 request for info Commission will be informed of new hearing date MARKEY, E.J. House of Rep., Interior & Insular Affairs 83/05/19 PALLADING, N.J. Commissioners 1p 22430 225
- --8402RB0069 Advises that contents of Ofc of Inspector & Audit Case Files B0-23,80-34,81-11,81-47 & 82-19 needed prior to subcommittee 830620 hearing re Hayward Tyler Case MARKEY,E J House of Rep . Interior & Insular Affairs 83/06/07 PALLADINO,N J Commissioners. 1p 22430 226
- ---8402280074 Forwards Hayward Tyler Pump Co response to NRC insp/investigation rept Transmittal ltr requests that copies of response accompany release of rept Commission should decide whether to release response w/rept.

 AXELRAD. J. NRC No Detailed Affiliation Given 83/02/01 COMBS, F NRC No Detailed Affiliation Given 1p 22430 227
- --B402280077 Forwards B Lyons of Hayward Tyler Pump Co, response to NRC B21222 1th & attached repts & exhibits Response sent to Region IV on 830126 Hayward Tyler Pump Co does not claim eny confidential treatment over Exhibit B-D BGEBE.J T Fried. Frank. Harris, Bhriver & Kampelman 83/01/26 SNIEZEK,J H NRC No Detailed Affiliation Given. 19 22430 228
- --B402280080 Forwards responses to final NRC rept on subjinquiry.per DeYoung B21222 request Detailed responses encl as Apps A & 8. Corrective actions will be verified & commissioning test program will be completed Responses encl LVONG. B.P. Hayward Tyler Punp Co. B3/01/26 COLLINS. J.T. Region 4. Office of Director. 52pp. 22430.229
- ---8402280085 Forwards matls prepared by Hayward Tyler Pump Co re insp & investigation Documents should be returned immediately after review.

 80888.J T. Fried, Frank, Harris, Shriver & Kampelman 82/07/30 FORTUNA.R NRC No Detailed Affiliation Given ip 22430-281
- ---8402280087 Forwards analyses of antirotation pin & impeller ring wear, per request Encl info should be treated as company-sensitive.
 LYONS, B, P. Hayward Tyler Pump Co 82/07/28. FORTUNA: R
 Director's Office, Office of Inspection and Enforcement 4pp 22430 282. 24X Fiche, 50-471,83/12/21,8402280048.
- --8402280090 Forwards final version of Chairman testimony on NRC investigation into allegations of Hayward Tyler Fump Co Testimony will be presented before Subcommittee on Oversight & Investigations of House Interior Committee on 820406 KAMNERER.C. Office of Congressional Affairs 82/04/05. PALLADING, OILINSKY, AHEARNE Commissioners 1p. 22430.286
- ---8402280074 Forwards Commissioner Gilinsky separate views that should be added to Ottinger itr as last paragraph.

 MANNING: W. J. Commissioners. 82/05/27 REAMER: W. HARDING: V.,
 LAVERTY. J. NRC No Detailed Affiliation Given. 2pp. 22430-301
- 8402280116 Responds to FOIA request for copies of documents re proposed NBMC determination on proposed amends to OLs for Facilities FELTON J M Division of Rules and Records 84/01/05, BELL.N Nuclear Information & Resource Bervice. 4pp. 22430:001 24X Fiche.50-250,84/01/05,8402280116.
- ---B307180303 Requests FR publication of notice of consideration of issuance of amend to License DPR-43 & proposed NBMC & opportunity for hearing re adding secondary water chemistry program.

 VARQALS.A. Operating Reactors Branch 1 B3/07/11 CLARK,R A Operating Reactors Branch 3. App 22430 036. 24X Fiche: 50-250, 84/01/03, 8402280116

- --B310170334 Requests FR publication of notice of consideration of issuance of amend to Licenses DPR-31 & DPR-41 & proposed NSHC determination & opportunity for hearing on 830819 & 0907 requests to increase hot channel limits VAROA, S A Operating Reactors Branch 1 83/10/26 MILLER, J R Operating Reactors Branch 3 ip 22430 038 24% Fiche 50-250,84/01/05.8402280116 83/10/24 MILLER, JR
- --8311300460 Forwards SER re Tech Spec changes for optimized fuel & wet annular burnable absorber rods Changes acceptable. RUBENSTEIN,L S Assistant Director for Core & Plant Systems TAC 51793 83/11/21 LANAS,G C Assistant Director for Deparating Reactors 16pp 22430 057 24X Fiche:50-250,84/01/05,8402280116
- --8312020434 Forwards Core Performance Branch safety evaluation re proposed amend to Licenses DPR-31 & DPR-41 Tech Specs Proposed changes re increase of hot channel factor acceptable
 RUBENSTEIN.L 8 Assistant Director for Core & Plant Systems TAC
 52142 83/11/21 LAINAS.O C Assistant Director for Operating
 Reactors 17pp 22430 040 24X Fiche 50-250,84/01/05.8402280116
- --8312160258 Requests FR publication of notice of issuance of Amends 98 & 92 to Licenses DPR-31 & DPR-41, respectively, changing Tech Specs to support planned fuel design mod during Cycles 9 & 10 & subsequent cycles
 VARGA, S A Operating Reactors Branch 1 B3/12/09 MILLER, J R, Operating Reactors Branch 3 2pp 22430 075 24X
 Fiche 50-250, 84/01/05,8402280114
- --8402280119 Forwards revised interim SER on effects of fuel rod bowing on thermal margin calculations for LMRs ROSS, D F Office of Nuclear Regulatory Research, Director EIGENHUT, D O Division of Licensing 77/02/16 VASSALLO.D.B Assistant Director for Light Water Reactors GDLLER, K R Division of Facility Operations ip. 22430 007.
- --0402280126 Revised "Interim SER on Effects of Fuel Rod Bowing on Thermal Margin Calculations for LWRs " * Assistant Director for Reactor Bafety 77/02/16 28pp
- --8402280141 Submits daily highlight On B31107. Ofc of Secretary received request for hearing & petition to intervene re proposed amends to Licenses DPR-31 & DPR-41 MCDDNALD, D G Dperating Reactors Branch 1. B3/11/08. DENTON, H, CASE, E, EISENHUT, D NRC No Detailed Affiliation Given ip 22430 039. 24X Fiche 30-250,84/01/05.8402280116
- ---8402280155 Bubmits daily highlight. Temporary restraining order filed by MH Hodder re reload amend request from util MCDDNALD, D 9 Operating Reactors Branch I 83/11/30 DENTON, H . CARTER, J . EISENHUT. D NRC No Detailed Affiliation Given ip. 22430 073 24X Fiche: 50-250,84/01/05,8402280116.
- --B402280158 Submits daily highlight On 831201, request for temporary restraining order filed by NH Hodder re reload amends Request denied MCDONALD, D. O Operating Reactors Brench 1 B3/12/08 DENTON, H. CASE, E., CARTER, J. NRC No Detailed Affiliation Given. 1p 22430-074 24X Fiche 50-250,84/01/05,8402280116
- --8402280164 Submits daily highlight Hearing scheduled re request for restraining order concerning relead amends.

 MCDONALD, D. G. Operating Reactors Branch 1 83/12/01 DENTON, H. Office of Nuclear Reactor Regulation, Director. CARTER, J. NRC -- No Detailed Affiliation Given EISENRUT, D. Division of Licensing 1p. 22430 122
- B402280338 FDIA request for documents re proposed NSHC determination on proposed amends to OLs
 BELL-N Nuclear Information & Resource Service 83/12/02 Office of Administration 2pp. 22430 005. 24X Fiche 50-250, 83/12/02, 8402280338
- 8408280593 FDIA request for current NUS Corp byproduct mati license covering lab & waste storage activities & initial license application DAVIS,T Affiliation Not Assigned 83/12/09 FELTON, J M Division of Rules and Records. Ip 22428 172
- 8402280594 Responds to FOIA request for current byproduct matt license issued to NUS Corp covering lab & subsequent waste storage activities & initial license application Forwards App A documents.
 TELTON, J.M. Division of Rules and Records. 84/01/16 DAVIB, T. filiation Not Assigned 2pp 22428-173.
 - - 280596 Forwards application for buproduct matl License 37-17937-03. NWAY.T W NUS Corp. QEC-82-59(E5). 82/11/24. QLENN.J. Region Office of Director. 1p 22428 175

- --B402280600 Application for byproduct matl License 37-17937-03 authorizing acquisition of licensable matls from other licensees to perform various radiochemical analyses BTONE.J T NUS Corp B2/11/23 24pp 22428 176
- --8402280502 Rev O to Procedure P O 5.2 15 O. "GA in Radiological Lab -General Guidelines "
 MARCINKIEWICZ NUS Corp 82/05/05 9pp 22428.201
- --8402280605 Rev 1 to Procedure P G 5 2 15.1. "Radiological Lab Organization & Function " MARCINKIEWICZ NUS Corp 82/11/30 App 22428 210
- Training "
 MARCINKIEWICZ NUS Corp 82/05/05 App 22428 216
- ~-8402280611 Rev 0 to Procedure P 0 5 2.15 4. "Receipt of Radioactive Bources, Stds & Non-Environ Bamples" MARCINKIEWICZ NUS Corp 82/05/10 3pp 22428 232
- ---8402280614 Rev 0 to Procedura 2 0 5 2 15 7. "Preparation of Stds. Tracers & Carriers "

 * NUS Corp 82/05/01 5pp 22428 225
- --8402280615 Rev O to Procedure P D 5.2 15 300, "Radiation Protestion Program for NUB Radiological Lab " * NUS Corp 82/10/01 18pp 22/28 231.
- --8402280620 Rev O to Procedure P D 5 2 15 301, "TLDD Program Personnel & Area Monitoring " # NUS Corp 82/11/30 6pp 22428, 249.
- --B402280627 Rev 0 to Procedure P 0 5 2 15 303, "General Leb Protocol for Operations Involving Radioactive Matls " * NUS Corp 82/11/30, 4pp 22428 262
- --B402280631 Rev O to Procedure P.O 5 2.15 304, "Area Surveys & Monitoring " * NUS Corp 82/11/30 8pp 22428 266.
- --8402280636 Rev O to Procedure P O 5 2.15,305. "Portable Burvey Equipment Calibr & Maint " # NUS Corp 82/11/30, 5pp. 22428-274
- --8402280639 Ray O to Procedure P O 5 2 15.306. "Monthly Accountability of Radioactive Matis."

 + NUS Corp ' 82/11/30 4pp. 22428-279
- --8402280646 Rev O to Procedure P D 5 2 15 307, "Handling, Storage & Shipment of Radwaste " * NU8 Corp. 82/11/30 Spp. 22428.283
- Decontamination * NUS Corp 82/11/30 App. 22428.297
- --8402280457 Rev O to Procedure P.O. 5 2 15 310, "Equipment/Area Decontamination." * NUS Corp. 82/11/30, 29pp 22428 303
- -8402280690 Responds to 821209 request for add1 info re license application Four replies listed in correlation w/original item numbers. item numbers.

 MARCINKIEHICZ NUB Corp PRL-82-181. 82/12/28. JERMAN, P C
 Ragion i, Office of Director 2pp. 22428-333
- --8402280696 Rev O to Procedure P. D 5.2 15.311. "Requisition of Licensable Quantities of Radioactive Matls" MARCINKIENICZ NUS Corp. 82/12/31 20pp 22428.335.

- --8402280706 License 37-17937-03 for NUS Corp, authorizing use of listed byproduct mati including H-3, Am-241 & Cm-242 for stds, radiochemical analysis & R&D of new analytical methods JERMANN P C Ragion 1, Office of Director 83/01/06 3pp
- 8402290001 FDIA request for correspondence NRC received from Senators McClure, Johnston & Laxalt during past 2 years KDLI, E Cable News Natwork, Inc. 89/09/30 NRC - No Detailed Affiliation Given ip 22438 001
- 8402290002 Responds to FOIA request for correspondence NRC received from Senators J McClure, JB Johnston & P Laxalt during past 2 yrs Forwards App A documents Name of individual deleted from Documents B & 7 of App A (ref FOIA Exemption 6) FELTON, J M Division of Rules and Records 83/11/30 KOLI, E Cable Naws Network. Inc 6pp 22438 002 24X Fiche 50-000, 83/11/30. 8402290002
- --8207010516 Forwards NRC answers in response to questions submitted for record of 820324 hearing on Commission FY83 budget request KAMMERER.C Office of Congressional Affairs 82/05/06 HATFIELD.H O Senate. Appropriations ip 22438 037
- --B304260267 Forwards responses to Nuclear Data Link issues raised by Congress NRC recommendation to release RFP for prototype evaluation approved FALLADIMO.N J Commissioners 83/04/07 HATFIELD, M.O. Senate, Appropriations 35pp 22438 055
- --B306140051 Requests reinstatement of \$700,000 reduction in requested funds for pay increases Funds to evaluate prototype of nuclear data link necessary PALLADINO,N J. Commissioners 83/05/19 HATFIELD,M O. Benate, Appropriations 1p 22438-054
- --8308189043 Responds to 830717 ltr re cracks in common foundation mat Incidents of water seepage engineering studies, NRC annitoring & review of studies discussed DIRCKS, W J Office of the Executive Director for Operations 83/08/09 JQHN9TON, J Senate 2pp 22438 115 24X Fiche 50-000, 83/11/30,8402270002
- ---B30B1B0541 Requests findings & views re and 1 tr from concerned constituent.
 JORNSTON. J B Senete 83/07/19. Office of Congressional Affeirs 2pp 22438.113 24X Fiche 50-000.83/11/30.8402290002
- ~-B402270003 Notifies that Commission voted to deny DDE request for stemption from certain NRC regulations in connection w/CRBR sits preparation activities KATMERER. C Dffice of Congressional Affairs. 82/03/05 ALEXANDER. L. Tannesses, State of RILEY, E. L. Affiliation Not Assigned. SABSER, J Benate 2pp. 22438:010 24X Fiche. 50-000, 83/11/30, 8402270002
- --B402290024 Forwards NRC 820316 order denying DDE request for regulatory exemption to begin CRBR site preparation activities W/ separate views of Commissioners W/o encl.
 KAMMERER, C Office of Congressional Affairs 82/03/17
 OTTINGER, B L. House of Rep., Energy & Commerce SABSER, J,
 QUAYLE, D Senate Rpp 22438; 012 24X Fiche 50-000, 83/11/30,
 8402250002
- --3402290034 Forwards "Rulemaking on Storage & Disposal of Nuclear Watte" approved by Commission on 830516. H/o ancl KAPMERER, C Office of Congressional Affairs B3/05/17. OTTINGER,R. L. House of Rep., Energy & Commerce. SIMPEGN, A Sanata, Environment & Public Works UDALL, M House of Rep., Interior & Insular Affairs 1p. 22438 016
- ---8402290058 Forwards resume of constituent interested in serving on ACAS. Info deleted MCCLURE. J. A Senate. Energy & Natural Resources 83/09/22 PALLADINO.N.J Commissioners. 6pp. 22438-017.
- --8402290040 Ack receipt of 1tr recommending constituent as member of ACRB. Name entered as candidate for vacancy Info deleted KASMERER. C. Office of Congressional Affairs. B3/10/07. HCCLURE, J. A. Benate ip. 22438.023
- --8402270062 Forwards Chairman Palladino remarks before ANE 820126 seeting. M/o encl. KAMMERER.C. Office of Congressional Affairs 82/01/26 OFTINGER.R L. House of Rep., Energy & Commerce BIMPBON.A Senate, Environment & Public Works UDALL.M House of Rep., Interior & Insular Affairs 1p 22438,024.

- --8402270067 Forwards rept covering Phage 1 investigation into circumstances surrounding development of "Preliminary Rept, Seismic Reverification Program " Rept covering second phase due to Commission in Feb 1982 W/o encl KAMMERER, C Office of Congressional Affairs 82/01/27 OTTINGER, R L House of Rep , Energy & Commerce SIMPSON, A Senate, Environment & Public Works UDALL, M House of Rep , Interior & Insular Affairs 2pp 22438 026 24X Fiche 50-000,83/11/30,8402270002
- --B402270082 Forwards rept covering Phase 2 investigation into circumstances surrounding development of "Preliminary Rept, Beismic Reverification Program" W/o encl KAMMERER, C Defice of Congressional Affairs 82/02/10 OTTINGER, R L House of Rep , Energy & Commerce SIMPSON, A Benate, Environment & Public Works UDALL, M House of Rep , Interior & Insular Affairs 2ps 22438 028 24X Fiche 50-000, 83/11/30, 8402290002
- --8402290091 Forwards proposed policy statement on safety goals for nuclear power plants, approved for publication in FR Rept discussing development of proposed policy statement. NUREG-0880. will be forwarded when available W.P. encl KAMMERER, C. Office of Congressional Affairs 82/02/11 OTTINGER, R. L. House of Rep., Energy & Commerce SIMPBDN, A Senate, Environment & Public Works UDALL. M. House of Rep., Interior & Insular Affairs 1p 22438 030
- --8402290098 Forwards announcement of ACRS 820303 technical meeting at site W/o encl
 KAMMERER, C Dffice of Congressional Affairs B2/02/18
 DTTINGER, R L House of Rep. Energy & Commerce SIMPSON, A
 Benate, Environment & Public Works UDALL, M House of Rep,
 Interior & Insular Affairs 1p 22438 031 24X
 Fichs 50-000,83/11/30,8402290002
- ---B402290103 Forwards NRC rept to Congress on AOs at licensed nuclear facilities (NUREO-0090) for Third Guarter CYB1 W/o encl KAMMERER, C Office of Congressional Affairs 82/03/10 OYTINGER, R L House of Rep, Energy & Commerce BIMPSON, A Sanate, Environment & Public Horks UDALL, H House of Rep, Interior & Insular Affairs 1p 22438 032.
- --B402290108 Forwards advance copy of NRC Annual Rept for 1981
 Bubcommittee will be provided w/rept when available, W/o
 encl
 KAMMERER, C Office of Congressional Affairs 82/03/19
 OFTINOER, R. L. House of Rep., Energy & Commerce MOFFETT, T Hausof Rep., Government Operations UDALL, M House of Rep., Interior
 & Insular Affairs 1p 22438 033
- --B402290114 Forwards announcement that NRC will hold 1-day public meetings on proposed safety goals for nuclear power plants W/o encl.

 KAMMERER: Office of Congressional Affairs B2/03/31
 OTTINOER: R L House of Rep., Energy & Commerce SIMPSON, A Senate, Environment & Public Works UDALL.M. House of Rep., Interior & Insular Affairs 1p 22438 034
- --8402270118 Discusses seismic design verification program for facilities, required by Commission Biili? order. NRC approved proposal of util to retain Teledyne to conduct independent audit

 KAMMERER.C. Office of Congressional Affairs. 82/04/01.

 MOFFETT.T. House of Rep. Government Operations HATFIELD, M
 Benate. Appropriations BEVILL. T House of Rep. Appropriations 1p. 22438-035 24% Fichs 50-000.83/11/30.8402270002
- --8402290121 Forwards "Rept of Special Moster in TMI-1 Restart
 Proceeding " W/o encl
 KAMMERER.C Office of Congressional Affairs. 82/04/29
 OTTINGER.R L House of Rep . Energy & Commerce DEVILL.T House
 of Rep . Appropriations HATFIELD.M Senate, Appropriations ip
 22438.036 24% Fiche 50-000.83/11/30.8402290002
- --8402270127 Informs that NRC upgrading investigative capabilities by consolidating NRC investigatory functions in new Ofc of Investigation, FALLADING, N. J. Commissioners 82/06/10 HATFIELD, M. Senate, Appropriations 1p 22438 038
- --8402290127 Forwards latest set of tables re future licensing activities by Commission. W/o encl
 KAMMERER.C. Office of Congressional Affairs 82/04/22
 HATFIELD.M O. Senate, Appropriations ip. 22438:039.
- --8402270137 Forwards ASLB 820621 initial decision in DL proceeding Decision does not address Miami Valley Power Project 820518 motion seeking admission of eight new contentions re GA & corporate computence KATMERER. C Dffice of Congressional Affairs 82/06/24 OTINOER.R. House of Rep., Energy & Commerce SIMPBON, A Sanete, Environment & Public Works UDALL.M. House of Rep. Interior & Insular Affairs 2pp 22438 041 24X Fiche. 50-000, 83/11/30, 8402270002.

- --8402290153 Forwards NRC rept to Congress on AOs at licensed nuclear facilities (NUREO-0090) for Second Quarter CY82.per Bection 208 of Energy Reorganization Act of 1974 W/o encl KAMMERER. C Office of Congressional Affairs 82/12/30 OTTINGER.R L House of Rep. Energy & Commerce SIMPSON.A Senate, Environment & Public Works UDALL.M House of Rep. Interior & Insular Affairs 1p 22438 043
- --BA02290163 Informs that Region III completed investigation into allegations re const imadequaties No technical issues remain to preclude operation above 0% power KAMMERER, C. Office of Congressional Affairs B2/07/23 OTTINGER, R. I. House of Rep. Energy & Commerce BEVILL, T. House of Rep., Appropriations HATFIELD, M. Benate, Appropriations ip 22438 044 24% Fiche 50-000, B3/11/30, 8402290002
- --840229017! Forwards NRC rept to Congress on ADs at licensed nuclear facilities (NUREG-0090) for First Quarter CV82 W/o encl MAMMERER. C Office of Congressional Affairs 82/08/19 OTTINOER, R L House of Rep , Energy & Commerce BEVILL, T House of Rep , Appropriations HATFIELD, M Senate, Appropriations ip 22438 043
- --B402270178 Forwards NUREQ-0784, "Long-Range Research Plan "Plan covers FY84-88 W/o encl KAMMERER.C Office of Congressional Affairs 82/09/28 HATFIELD.M O Senate, Appropriations ip 22438 046
- --B402270182 Forwards ABLB rept summarizing activities of Board for FYB2 W/o encl MAMMERER.C Office of Congressional Affairs 82/11/16 OTTINGER.R L Mouse of Rep., Energy & Commerce SIMPSON, A Senate. Environment & Public Works UDALL.M House of Rep., Interior & Insular Affairs 1p 22438 047
- --8402290190 Forwards announcement that NRC groposes to fine Louisiana Power & Light Co \$20,000 for alleged violation of NRC regulations Info distributed to news media W/o encl KAMMEREN.C Office of Congressional Affairs 82/12/07 OTTINGER.R L House of Rep . Energy & Commerce SIMPSON.A Senate. Environment & Public Works VDALL.M House of Rep . Interior & Insular Affairs 1p 22438 049.
- --840229020; Forwards announcement of ASLB scheduled hearing to begin on B30208 in New Orleans, LA KAMERER: C Office of Congressional Affairs 83/01/27. OTTINOER: R House of Rep. Energy & Commerce SIMPSON, A. HART Senate, Environment & Public Horks 1p. 22438 050 24% Fiche 50-000, 83/11/30, 8402290002
- --B402270226 Forwards rept of NRC fact-finding task force established to analyze B30225 ATMS event. W/o encl
 KAMMERER. C Dffice of Congressional Affairs B3/03/23
 OTTINGER.R L House of Rep. Energy & Commerce SIMPBON, HARY Senate. Environment & Public Works ip. 22438 051. 24X
 Fiche 50-000,83/11/30,8402270002
- --8402270241 Forwards announcement that ASLAB will hear oral argument on 830419 in New Orleans, LA.
 KAMMERER, C. Office of Congressional Affairs 83/04/05
 OTTINGER, R.L. House of Rep , Energy & Commerce. SIMPSON, HART Senate, Environment & Public Horks ip 22438 052 24X
 Firhe, 50-000, 83/11/30, 8402290002
- --8402270250 Forwards NRC order re facility. Btatements prepared by Cheirman Palladino & Commissioners Ahearne & Roberts also encl Commissioners Gliinsky & Assolatine did not have prepared statements W/o encls KAMMERER, C Office of Congressional Affairs 83/05/05 BIMPSON.A. HART. G Senate. Environment & Public Works OTTINGER, R House of Rep. . Energy & Commercs. ip 22438'053 24X Fiche 50-000, 83/11/30, 8402270002.
- --8402290271 Requests approval to reprogram portion of FYB3 available funds to compensate for 1982 pay raises & to increase efforts in QA & use of cost-benefit analysis Proposed reprogramming adjustments, w/explanations, detailed in encl PALLADINO,N J Commissioners 83/02/03 MATFIELD,M D. Senste, Appropriations 6pp. 22438,091.
- --B402290273 Forwards SSER 1.dtd May 1983 W/o encl * Office of Nuclear Reactor Regulation, Director. 83/05/28 HATFIELD.M.G Senate, Appropriations. 4pp. 22438 096. 24X Fiche 50-000, 83/11/30, 8402270002
- --8402290282 Ack receipt of 830827 ltr re emergency preparadness plans for facility, Reply will be forwarded as soon as possible KAMMERER.C. Diffice of Congressional Affairs. 83/06/01 JOHNSTON, J.B. Senste, Energy & Natural Resources 1p. 22438:100 24X Fiche 50-000-83/11/30.8402270002.

- ---B402270285 Requests NRC to begin rev of regulations immediately to eliminate present abuses re veto power over emergency planning provided by NRC & FEMA regulations to state NRC & FEMA should act forcefully to resolve crisis at facility JOHNBTON, J B Senate, Energy & Natural Resources 83/05/27 PALLADINO, N J Commissioners 2pp 22438 101 24X Fiche 50-000,83/11/30,84028700002
- --8402290290 Forwards announcement of ASLB scheduled prehearing conference in DL application proceeding W/o announcement. KAMMERER.C Office of Congressional Affairs 83/06/01.
 OTTINOER.R L House of Rep., Energy & Commerce SIMPBON, A Senate, Environment & Public Works UDALL.M K House of Rep., Interior & Insular Affairs ip 22438 103 24X
 Fiche 50-000,83/11/30,8402290002
- --8402290297 Forwards SBER 2.dtd May 1983 W/o encl * Office of Nuclear Reactor Regulation, Director 83/06/10 HATFIELD.M O Benate. Appropriations 1p 22438 108 24X Fiche 50-000,83/11/30,8402290002
- --8402270303 Responds to 830527 ltr expressing concern re Commission contemplated shutdown of facility for emergency preparedness deficiencies On 830610. Commission decided not to take enforcement action Decision encl W/o encl KAMMERER, C Office of Congressional Affairs 83/06/20 JUNHSTON, J B Senate, Energy & Natural Resources ip 22438 112 24X Fichs 50-000.83/11/30.8402270002
- --8402270310 Forwards FY83 base table for NRC through 830430 KAMMERER.C Office of Congressional Affairs 83/08/04 OTTINGER,R.L. House of Rep. Energy & Commerce BIMPSON, A K Senate, Environment & Public Works UDALL, M K House of Rep. Interior & Insular Affairs 3pp 22438-117
- --8402290313 Forwards Aug 1983 issue of NRC summary info rept
 (NUREQ-0871) W/O encl.
 KAMMERER, C Office of Congressional Affairs 83/08/16,
 OTTINGER, R L House of Rep., Energy & Commerce SIMPBON, A
 Senate, Environment & Public Works UDALL, M House of Rep.,
 Interior & Insular Affairs ip. 22438 123
- --B402290318 Forwards NRC orders re facility restart proceedings 14/0 encls
 KAMMERER, C. Office of Congressional Affairs. 83/10/07.
 OTTINGER, R.L. House of Rep., Energy & Commerce SIMPBON Senate.
 Environment & Public Works UDALL House of Rep., Interior & Insular Affairs 1p. 22438-125 24X Fiche 50-000.83/11/30, A402290002.
- 8402270044 FOIA request for NRC rept re 830713 incident at Shelwell Bycs in Licking County, DH & documentation leading up to issuance of rept & CARDNER, B L Frost, Freytag & Hunter , 83/11/08 Region 3, Office of Director. ip. 22431:183
- 8402270067 Responds to FOIA request for NRC rept re 830913 incident at Shalwell Syrs in Licking County, OH & documentation leading up to issuance of rept. Forwards App A documents. Insprept will be forwarded when completed FELTON, J. M. Division of Rules and Records 83/12/14 GARDWER, B L Frost, Freytag & Hunter 3pp. 22431, 184
- --8307270525 Forwards order to show cause & order temporarily suspandin License 34-10445-01 due to 830913 event where cut source resulted in release of 65-137 in powder form.

 DEYOUNG,R. C Director's Office, Office of Inspection and Enforcement EA-83-09& 83/09/20 Shelwell Services, Inc. 1)

 D2421-199.
- --8309270528 Order to show cause & order temporarily suspending License 34-10445-01 due to 830913 event where cut source resulted in release of Ca-137 in powder form DEYOUNO.R.C. Director's Office, Office of Inspection and Enforcement EA-83-096, 83/09/20. Shelwell Services, Inc. 5pp. 22431,200.
- --8402290083 PNO-III-83-085 on 830913, well logging source containing Cs-137 damaged during removal from storage container for installation in well logging tool, causing contamination of approx 10 square ft SLAWINSKI, W. BRENIEWSKI, D. Region 3, Office of Director 83/09/15 ip 22431 187.
- --8402270142 Forwards amended or add1 Apps A,B & C to answer NRC B31017 order to show cause & order temporarily suspending license.

 8HELTON.M. Shelwell Services, Inc. 83/10/28, DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 1p. 22431:209.
- --8402270145 "Radiological Safety Operating Procedures Manual Opverning All Uses of Licensed Radioactive Matls." SHELTON.M. Shelwell Services: Inc. 83/10/01. 32pp. 22431:210

- --8402290130 "Radiological Health Training Manual " 8 Shelwell Services, Inc 83/10/18 67pp 22431 243
- --8402270152 Submits listed info needed re licensee response to IE 830920 order to show cause & order temporarily suspending license Procedures will require certain changes prior to lifting of suspension
 DEVOUND, R. C. Director's Office, Office of Inspection and Enforcement EA-83-96 83/10/28 SHELTON, M. Shelwell Services.
 Inc. 2pp 22431 310
- --B402290139 Responds to seven items raised in NRC 831028 ltr Asst radiation safety officer will receive same training as radiation safety officer Operating procedures manual will be revised to reflect new training procedures BHELTON, M D Shakuell Services, Inc EA-83-96 83/10/28 DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 3pp 22431 312
- --B402270164 Advises that listed persons trained by Applied Health Physics, Inc. have satisfactorily completed training & passed stam to be qualified as operating engineers in response to B31028 request
 MILLER.P. D. Shelwell Services. Inc EA-83-96 B3/10/28
 DEVOUND,R. C. Director's Office, Office of Inspection and Enforcement 2pp 22431 315.
- --B402290167 Requests proposal from ANL to provide contractual assistance to NMSB. Encl statement of work details required work & should be used as basis for preparing proposal Proposal requested by 831200 BROWN, R. 8 Program Support Branch, FIN A-2161 B3/11/03 RAUCH, H Energy, Dept of, 4pp 22431 320

- --8402290185 Rescission of suspension & order modifying license. License 34-10445-01 modified to include licensee statements, representations & procedures as indicated in listed documents submitted to NRC.

 DEYOUNG, R. G. Director's Office, Office of Inspection and Enforcement, EA-83-96, 83/11/07. Bhelwell Services, Inc. 4pp. 22431.328
- --8402290191 Informs that AEOD undertaken case study on breaching of encapsulation of sealed well logging sources. Incident at Shelwell Sycs to be included in study. Region III repts on Shelwell Sycs incident requested BLACK, K.M. Nonreactor Assessment Staff, 89/11/16 AXELSON, W.L. Region 3, Office of Director. lp 22431.334,
- --8402290200 Informs that sealed sources at Illinois operation will be stored & locked on logging trucks inside shop Pictures & dimensions of storege containers encl. SHELTON.M.D. Shelwell Services. Inc. 83/12/14 Division of Fuel Cycle & Material Safety. App. 22431,342
- 8402290410 Responds to second part of 831208 FOIA request for draft response to petition for rulemaking PRM 50-31. First part of request will be addressed separately by NRR, Draft response withheld (ref FOIA Exemption 5) FELTON, J. M. Division of Rules and Records, 84/01/18, KATS, O. H. Citizens' Task Force, 1p. 22437:331
- 8402290415 FDIA request for draft response to petition for rulemaking FRM 50-31 KATS.0-H , SERNARD.J , LOTCHIN.P. Citizens' Tesk Force. 83/12/09. CHILK.S.J. NRC - No Detailed Affiliation Given ip. 22437.332.
- 8402270420 Responds to FDIA request for Contract NRC-10-84-256. Contract available in FDR. FELTON, J M. Division of Rules and Records. 84/01/17. HIRSCH, H Key Book Service: Inc. 1p. 22437:329.

- 8402290421 FOLA request for Contract NRC-10-84-254 HIRBCH:H Key Book Service, Inc 84/01/10 NRC - No Detailed Affiliation Given 1p 22437 330
- 8402290425 FOIA request for documents re const assessment team visit to facility in Aug & Sept 1983 HIATT-8 L Ohio Citizens for Responsible Energy 83/11/16 FELTON. J Division of Rules and Records 1p 22437 111 24X Fiche 50-440.83/11/16.8402290425
- 840229043i Partial response to FDIA request for documents re const assessment team visit to facility in Aug & Sept 1983 Forwards App A documents Search for addl documents continuing FELTON, J M Division of Rules and Records 84/01/17 HIATT, 8 Ohio Citizens for Responsible Energy 2pp 22437 112 24X Fiche 50~440,84/01/17,840229043i
- 8402270446 Responds to FOIA request for records re review of training at PMRs or organizations providing training on surveillance test procedures to licensees Specific RCS training not required to be included in insp repts
 FELTON, J M Division of Rules and Records 84/01/27 MADDEN, T J Kaye, Scholer, Fierman, Hays & Handler ip 22437 344.
- 8402290449 FOIA request for records re review of training at PMRs or organizations providing training on surveillance test procedures to licensees MADDEN, T J Kaye, Scholer, Fierman, Hays & Handler 83/12/12 NORRY, P G Office of Administration 2gp 22437 345
- 8402290455 Final response to FOIA request for records re anonymous allegations involving facilities submitted in D Fleischaker ltr to D Eisenhut Document withheld (ref FOIA Exemptions 5 & 7)
 FELTON, J M Division of Rules and Records 84/01/31 REYNOLDS, J R Center for Law in the Public Interest 2pp 22437 276 24x
 Fiche 50~275,84/01/31.8402290455

GEN TEC 18 GENERIC TECHNICAL IBSUES

- 8307270206 BECY-83-288
 Requests Commission approval for FR publication of notice of proposed rulemaking re-pressurized thermal shock DIRCKB.W J Office of the Executive Director for Operations 83/07/15 83pp. 22177 007
- 840119006B Board Notification B4-033: provides "Bys Interaction Program," task action plan for Unresolved Safety Issus A-17 Distribution list encl EISENHUT.D G. Division of Licensing 84/02/16 PALLADINU Commissioners. Bpp 22482.091 24X Fichs 50-000, 84/02/16. 840119004B
- 8401270182 Forwards draft Commission paper & NUREG documenting NRC evaluation & conclusions re need for rapid depressuritation capability on current C-E plants w/o FORVs Review & comments requested by 840R06
 DENTON, HR Office of Nuclear Reactor Regulation, Director 84/01/13 STELLO, V Regional Operations & Generic Requirements 100pp. 22079 045
- 8402010134 Forwards Rev 1 to "Rept on Control of Heavy Loads." updating areas of safe load path review & vendor analysis of reactor coolant pump motor lifting sling.per NUREG-0612 criteria.
 PETRICK.N A Standardized Nuclear Unit Power Plant System SLNRC 84-0008 84/01/27 DENTON.H.R Office of Nuclear Reactor Regulation, Director 3pp 22038 235. 24X Fiche: 50-000, 84/01/27, 8402010134
- --8402010149 Rev 1 to "Rept on Control of Heavy Loads."

 * Standardized Nuclear Unit Power Plant System 84/01/27 22pp
 22038: 238 24% Fichs: 50-000,84/01/27,8402010134.
- B402010410 Generic Ltr 84-04 to all operating PWR licensess, CP holders , & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Svc list encl.
 EISENHUT, D G, Division of Licensing, OL-84-04, 84/02/01 Gonsolidated Edison Co of New York, Inc 57pp 22177-087, 24X Fiche. 50-000,84/02/01,8402010410
- 8402010444 Responds to FDIA request for SECY-83-288 & SECY-83-443 to be placed in PDR, SECY-83-288 available in PDR, SECY-83-443 being placed in PDR, Forwards SECY-83-443 FELTON, J. M. Division of Rules and Records. 84/01/17 YENDUSKAB, J. Nawman & Holtzinger, ip. 22061, 272. 24X Ficher 50-000, 84/01/17, 8402010444.

- --8402010453 SECY-83-443
 Informs Commission of info obtained re flux reduction programs for pressurized thermal shock at lead plants, since 830225 interim rept (SECY 83-079).
 DIRCKS,W J Office of the Executive Director for Operations.
 83/10/28 lipp 22061 273 24X Fichs 50-000,84/01/17
- 8402030057 Forwards request for add1 info re Unresolved Safety Issue A-43. "Containment Emergency Sump Performance " Meeting should be arranged w/licensing project manager to discuss request & schedule for formal response submittal, KNIGHTON.6 W Licensing Branch 3 84/01/09 WOOLEVER.E J Duquesne Light Co 4pp 22091 059. 24X Fiche 50-412.84/01/09. 8402030057
- 8402040270 Forwards "Control of Heavy Loads at Nuclear Power Plants.
 Beaver Valley Nuclear Fower Plant Unit 2 (Phase J)." draft
 technical evaluation rept based on responses to NUREG-0412
 SER on subj will be issued on 840928
 KNICHTON.O H Licensing Branch 3. 84/01/17 WDOLEVER,E J
 Duquesne Light Co 3pp 22109,253 24X Fishe 50-412,84/01/17,
 8402040270
- --8401190528 "Control of Heavy Loads at Nuclear Power Plants, Beaver Valley Nuclear Power Plant Unit 2 (Phase I), " fraft technical evaluation rept FRIEDERICHS, 8 E640, Inc. FIN A-6457. 83/11/30 NRC - No Detailed Affiliation Given 45pp 22109 256 24X Fiche 50-412,84/01/17,8402060290
- 840207015B Forwards response to draft technical evaluation rept re control of heavy loads, per 821007 telcon. BAYNE, J P Power Authority of the State of New York JPN-84-06 84/01/31. VASSALLO, B Operating Reactors Branch 2 6pp 22103 052 24X Fiche 50-333.84/01/31.8402070158.
- 8402070302 Forwards revised schedule & task action plan for Unresolved Safety Issue A-49 re pressurized thermal shock for approval Final resolution scheduled for Dec 1985 BPEIS.T P. Division of Safety Technology B3/09/30 DENTON.M.R Office of Nuclear Reactor Regulation, Director, 37pp 22141 226
- 8402080032 EOG-NSMD-6343
 "RELAPS Thermal-Hydraulic Analysis of Pressurized Thermal
 Shock Sequences for Oconse-i PMR."
 FLETCHER:C D , BOLANDER:M A , STITT, B D EG&G, Inc. FIN A-6047
 B3/07/31 NRC No Detailed Affiliation Given 252pp 22173 003
 24X Fichs 50-269,83/07/31.8402080032
- 8402080043 Further response to FDIA request for documents re cleanup & decision to close U mill in Edgemont. 8D Forwards App A.B & C documents Review of remaining documents subj to request in progress FELTON.J M Division of Rules and Records 83/11/01 QARBUS. H Frankfurt. Garbus. Klein & Selz 10pp. 22169 009
- --8402380061 Requests assistance in obtaining clarification from appropriation committees if problem exists in continuing Edgement cleanup program W/o stated encl MARTIN.J B Division of Waste Management FIN B-2217 JJS-6 B1/01/09 KAYMERER, C Office of Congressional Affairs ip. 22169:335
- 8402080408 SECY-83-079
 Commission paper providing info obtained at recent licensee meatings re planning & status of flux reduction programs concerning pressurized thermal shock.
 DIRCKS, W.J. Office of the Executive Director for Operations 83/02/25 464pp. 22171 121
- B402090310 E00-EA-6296 DRFT

 "Browns Ferry Other Transients Failure Modes & Effects
 Analysis & Rejected Sys Justification Rept," preliminary
 rept

 BAXTER, D E E080: Inc FIN A-6477 83/05/31 NRC No Detailed
 Affiliation Given. 68pp 22187.27! 24X Fiche. 50-259.83/05/31;
 8402090310.
- B402090316 E0G-EA-62B2 DRFT
 "MB Robinson Steam Generator Overfill Transient Failure Mode
 & Effects Analysis & Rejected Sys Justification Rept,"
 preliminary rept.
 BAXTER.D E , BRUSKE.S J., STROMBERO.H M E060, Inc FIN A-6477
 83/05/31 NRC No Detailed Affiliation Given 47pp 22190:157
 24X Fiche 50-261,83/05/31.8402090314
- B402090324 EGG-EA-6297 DRFT

 "HB Robinson Overcooling Transient Failure Hode & Effects
 Analysis & Rejected Sys Justification Rept," preliminary
 rept

 BAXTER, D E , BRUSKE, S J E0&O, Inc FIN A-6477 83/05/31, NRC NO Detailes Affiliation Given 45pp 22187,145, 24X
 Fiche 50-261,83/05/31,8402090324.

- 8402070325 Forwards response to Section 2 1 of Generic Ltr B1-07 ; NUREG-0612. "Control of Heavy Loads at Nuclear Power Plants " Response to Sections 2 2:2 3 & 2 4 will be provided 6 months before first fuel load MILLE: L M Tennessee Valley Authority GL-81-07. 84/02/06 ADENSAN.E Licensing Dranch 4 479pp 22162.001 24X Fiche 50-390.84/02/06.8402090325
- 8402090427 Forwards response to 831031 ltr expressing concern revesolution of Unresolved Safety Issues A-47 & A-47 represented the special subjections of control systematical thermal shock & safety implications of control systematically PALLADING, N J Commissioners, 84/01/27 MARKEY, E J, House of Rep., Interior & Insular Affairs 33pp 22177 260
- 840209U469 Submits review of Generic Technical Activity B-10 ry resolution of Mark III issue Indications exist that suggest NRC relaxing criteria relevant to piping on case-by-case basis
 BUSH-S-H Battelle Memorial Institute, Pacific Northwest Leberator;
 BUSH-B-H ACRS Advisory Committee on Reactor Safaguards
 B3/10/28 BOEHNERT,F A ACRS Advisory Committee on Reactor Safaguards
 Safeguards 2pg 22192 338
- 8402130001 Requests exception to ANSI-B30 2-1976 Section 2-2 2 2 13).
 "Rated Load Test," per 821116 ltr re control of heavy
 loads Requirements unnecessary & too stringent Response
 requested prior to Mar 1984 Unit 2 outage
 ZIMMERMAN.S R Carolina Power & Light Co NLS-B4-042 84/02/06
 VASSALLO, D B Operating Reactors Branch 2 2pp 22204 070 241
 Fiche 50-324,84/02/06.8402130001
- 8402130228 Forwards responses to draft technical evaluation rept open items re control of heavy loads per 831103 ltr Crane operators trained per ANSI 830 2-1976 requirements.
 Installation of new fuel storage racks in progress,
 ZIMMERMAN 8 R Carolina Power & Light Co NLS-84-002 84/02/03
 VASSALUO, D B Operating Reactors Branch 2 10pp 22200: 121 241
 Fiche 50-324,84/02/03,8402130228
- 8402130625 Forwards for review, Rev i to draft NUREQ-0869 re Unreselvii Safety Issue A-43, "Containment Emergency Sump Performance "Comments requested by 840229 SERKIZ, A W. Generic Issues Branch. 84/02/03 HECKER, Q. Alden Research Laboratory PORSE, L. Affiliation Not Assigned. SWIFT, W. Creare, Inc. 90pp 22214 144
- 8402140328 Submits Phase II implementation schedule for control of heavy load review.per 831230 request Review essentially complete Rept will be submitted by 840307 HHITTIER.0 D Maine Yankee Atomic Power Co. MN-84-23 84/02/08 MILLER.J R. Operating Reactors Branch 3 1p. 22230 320 24X Fiche: 50-309,84/02/08,8402140328
- 8402150311 Provides charification re special lifting devices for control of heavy loads, per NUREQ-0612 Phase I requirements of NUREQ-0612 requested to be closed out in mext SSER COOK, K W Louisiana Power & Light Co. W3P83-3671 64/02/07 KNGHTON, O W Licensing Branch 3 3pp 22250, 183 24X Fiche 50-362, 84/02/09, 8402150311.
- --8402150313 Buppl 1 to "Response to NRC Draft Tachnical Evaluation Asji for Waterford 3 858 on Control of Heavy Loads" a Louisiana Power & Light Co. 83/11/30, 7pp 22250:186 241 Fichs: 50-382,84/02/09.8402150311
- 8402130430 Forwards "Control of Heavy Loads at Nuclear Power Plents, itmerick Generating Station Units 1 & 2 (Phase II)," draft technical evaluation rept Response to remaining concerns identified in Sections 2.3 1 C,2 3 2 C & 2 3 3 C requested SCHMENCER. A Licensing Branch 2 FIN A-6457 84/02/06, SAVER.E 9 Philadelphia Electric Co 3pp 2263:276 24X Fichs. 50-352,84/02/06,8402150430.
- --8402150435 "Control of Heavy Loads at Nuclear Power Plants. Limitic Generating Station Units 1 & 2 (Phase II), " draft technical evaluation rept FRIEDERICH8,8 EG&G. Inc FIN A-6457 83/10/30. NRC No Detailed Affiliation Given 29pp 22263:279, 24X Fiche 50-352,84/02/06,8402150430.
- 8402160148 Forwards pressurized thermal shock reactor vessel maths file summary, per 840119 discussion Review & concurrence by 840501 requested. Direction of analytical effort will be effected by results of review WILLIAMS, J W Florida Power & Light Co. L-84-31 84/02/10 EISENHUT, D 0 Division of Licensing. App 22276:247 24% Fiche: 30-250,84/02/10,8402160148.

- 8402220499 Submits changes to scheduled completion dates for proposed corrective actions noted in WC Jones 820121 response to Section 2 2-2 4 of Encl 3 to NUREG-0612 re control of heavy loads.

 JONES, W C Omaha Public Power District LIC-84-039 84/02/14 MILLER, J R Operating Reactors Branch 3 4pp 22334 082 24% Fiche, 50-285, 84/02/14, 8402220499
- B402230088 Responds to 831219 Generic Ltr 83-42 which indicated that guidelines of NUREO-0612 re single failure proof cranes may be deficient Review of diagrams indicates no single failure could result in uncontrolled motion of crane GEIER, J D. Illinois Power Co U-0676 84/02/10 BCHWENCER, A Licensing Branch 2 ip 22361 284 24X Fichs 50-461.84/02/10.
- 8402230128 Advises that B&W transmitted info re pressurized thermal shock flux reduction fuel mgt to J Carew in 840202 ltr HUKILL.H D general Public Utilities QPU Service Corp 5211-84-2037 84/02/15 870L7.J.F Operating Reactors Branch 4 ip 22361,206 24X Fiche: 50-287,84/02/15,8402230128
- E402240120 Forwards supplemental info to resolve NUREO-0612, "Control of Heavy Loads" Info also addresses concerns in Phases 1 & 2 of draft technical evaluation rept W/31 oversize drawings Aperture cards are in PDR BARNES; P.L. Commonwealth Edison Co. 8142N 84/02/10 DENTON:H R Office of Nuclear Reactor Regulation; Director. 27pp. 22374 289 24X Fiche 50-000;84/02/10,8402240120
- 8402270028 Forwards results of evaluation of reactor bldg polar crane dasign & special lifting device design conderations Bchedule of actions taken & planned to resolve heavy loads issue and!
 HUKILL, H B General Public Utilities OPU Service Corp 8211-84-2013 84/02/21 EIBENHUT, D G Division of Licensing 4pp 22388 001 24X Fiche 50-289,84/02/21,8402270028
- --B402270031 "Evaluation of Heavy Load Handling Operations at TMI-1. Responses to NRC Requests in Technical Evaluation Rept Transmitted Bi1021." HLADIK.M. GEORGE.H. General Public Utilities - GPU Bervice Corp 84/01/04. 94pp 22388.005 24X Fiche 50-289.84/02/21,8402270028
- 8402270034 Forwards "Control of Heavy Loads at Nuclear Power Plants Orand Oulf Nuclear Station Unit 1, (Phase II), "draft technical evaluation rept 8CH-MENCER.A. Licensing Branch 2. FIN A-6457 84/02/14 MCGANGHY, J.P. Mississippi Power & Light Co. 2pp. 20408: 308 24X Fichs. 50-416.84/02/14.8402270034
- --8402170216 Draft "Control of Heavy Loads at Nuclear Power Plants: Orand Gulf Nuclear Station Unit 1: (Phase II)."
 BEKOT, J.P E0kO, Inc. FIN A-6457. 84/01/31. 50pp 22408-310 24X Fichs: 50-416,88/02/14,8802270034
- 8402270068 Forwards 840207 proposed rule, "Analysis of Potential Pressurized Thermal Shock Events " Related correspondence WRIOHT, N. A. Hearing Branch 2. 84/02/21, BRENNER, L., MORRIB, P. A. COLE, F. Atomic Safety and Licensing Board Panel 11pp. 22387:331. 24X Fiche. 50-352,84/02/21,8402270068
- 8402270239 Forwards "Control of Heavy Loads (C-10). San Gnofre Nuclear Generating Station, Unit 1." draft technical evaluation rept Addl info requested re listed areas within 45 days of ltr receipt. CRUTCHFIELD, D. Operating Reactors Branch 5. L805-84-02-046. 84/02/22. BASKIN, K.P. Southern California Edison Co. Spp. 22386, 237. 24% Fiche 30-206, 84/02/22, 8402270239.
- --8402270253 TER-C5506-392
 "Control of Heavy Loads (C-10), San Dnofre Nuclear Generating Station, Unit 1," draft technical evaluation rept.
 BOHIEROER, C., AHHED, N., BARGENT, I. H. Franklin Institute/Franklin Research Center NRC-03-81-130 TAC 08082, 83/04/05 CLEMENBON, F. NRC NO Detailed Affiliation Given. 41pp 22386: 240. 24X Ficher 50-206,84/02/22,8402270239
- B402270263 Responds to FOIA request for JC Mark 801204 memo to ACRB re hydragen burn w/igniters & documents concerning generation, combustion or control of hydrogen in reactor accidents. Forwards App A documents hap B documents in FDR. FELTON, J. M. Division of Rules and Records 84/01/30 HIATT, B L. Ohio Citizens for Responsible Energy 7pp. 22412 051. 24X Fichs: 50-000,84/01/30,8402270263

- 8402280210 Clarifies commitment re performing NDE of all critical members & welds on reactor vessel head lifting rig in response to NUREO-0612 Exam will be performed prior to lifting reactor vessel head OIESLER.C W Wisconsin Public Bervice Corp NRC-84-32 84/02/24 VARGA.S A Operating Reactors Branch i lp 22399 278 24X Fiche 50-305.84/02/24,8402280210
- B402280406 Comments on proposed rule 10CFR90 on further protection against pressurized thermal shock Proposed amends pressure that basis & assumptions NRC & industry use correct Deficiencies to rule listed LEMI8.M I Leuts. M 47FR4498 001 84/02/16 Office of the Secretary of the Commission 2pp 22407 141
- B402280537 Corrects error in B40203 response to open issues in draft technical evaluation rept re control of heavy loads Testing & maint program for spent fuel cask yolk in compliance Wisgess ZIMMERMAN, S.R. Carolina Power & Light Co. NLS-84-071 84/02/20 VA9ALLO, D.B. Operating Reactors Branch 2 ip 22406-314 24X Fichs 50-324,84/02/20,8402280537

IMPECTION AND ENFORCEMENT

- B312120133 IE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps " Bvc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/25 Consolidated Edison Co of New York, Inc 120pp 22087:249 24X Fiche 50-000.84/01/25.8312120153
- 8401040328 PND-III-84-001 on 831230, radiation therapist received apparent overexposure to hands from handling radiation source holding device thought to be empty Device lent to Bethesda Hosp in Nov 1983. Investigation under way SRENIAWSKI,D , REICHHOLD,W Region 3, Office of Director 84/01/03 ip 21740 361
- B401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vahicular Excess Controls " Syc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/03. Consolidated Edison Co. of New York Inc. 119pp. 22114:179 24X Fiche 50-000,84/02/03,8401170016
- B401170017 IE Bulletin 84-01. "Cracks in BWR Mark I Containment Vent Headers " Byc list encl DEYOUNG:R C Director's Office, Office of Inspection and Enforcement B4/02/03. Consolidated Edison Co of New York, Inc 102pp 22177 156 24X Fiche. 50-000.84/02/03.8401190017
- B401190037 IE Info Notice 84-08, "10CFR50 7, 'Employee Protection '"

 8vc list encl
 JDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/02/14 Consolidated Edison Co of New
 York, Inc 115pp 22365 141 24X Fichs 50-000,84/02/14,8401190039
- 8401190041 IE Info Notice 84-09, "Lessons Learned From NRC Insps of Fire Protection Bafe Shutdown Bys (10CFR50, App R) " Byc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Enginearing Response (Post 830103) 84/02/13 Consolidated Edison Co. of New York, Inc. 124pp. 22365:259 24X Fiche 50-000,84/02/13,8401190041
- B401190045 IE Info Notice 83-63, Buppl 1, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103), B4/02/15 Consolidated Edison Co. of New York, Inc. 118pp. 22366:142 24X Fiche: 50-000,84/02/15,8401190045
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Buitches But Bulow Manufacturer Recommended Value " Svc list encl JURDAN, E. L. Division of Emergancy Preparedness & Engineering Response (Post 830103) 84/02/21 Consolidated Edison Co. of New York, Inc 116pp. 22366:024, 24X Fiche. 50-000,84/02/21,8401190062
- 8401190066 IE Info Notice 84-11, "Training Program Deficiencies."

 Byc list encl
 JDNDAN,E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24. Consolidated Edison Co., of New
 York, Inc. 115pp 82430:304 24X Fiche 50-000,84/02/24,8401190066
- 8401170067 IE Info Notice 84-12, "Failure of Soft Baat Valve Seals "
 Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/02/27. Consolidated Edison Co of New
 York, Inc. 120pp. 22431-060. 24X Fiche 50-000.84/02/27,8401170067

- 8401230110 Forwards draft IE bulletin re undervoltage trip attachments of reactor trip breakers Comments received prior to 840120 will be considered in preparation of final draft to be submitted to CRGR RDSSI, C E Events Analysis Branch 84/01/12 CROUSE, R P Babcock & Wilcox Operating Plants Owners Group GROUSE, R. P Toledo Edison Co. 500 21231 005
- 8402020120 PNU-I-84-011 on 840126, two spills discovered onto turbine bldg Elevation 656, below grade floor beneath main turbine hall Initial contamination surveys indicated max values of 500, 000 dpm per 100 CM2 on floor.

 JACOBS.R. SHANBAKY.M Region i, Diffice of Director 84/01/27 2gp 22036 213 24% Fiche 50-387.84/01/27.8402020120
- 8402020291 EN-84-003 notice of violation & proposed imposition of civil genalty of \$40,000 will be issued approx 840202 Action based on failure to have Tech Spec implementing procedures for entry into locked high radiation area FLACK.E. AXE.RAD.J Director's Office, Office of Inspection and Enforcement 84/01/30 2pp 22055 180 24X Fiche 50-250.84/01/30, page 20050 291
- 8402030384 EN-83-071A on B40130, order modifying license issued requiring submittal of timetable for decontamination activities Action based on inadequate response to 83101 order requiring assessment of 821204 Co-60 contamination. FLACK, E . AXELRAD, J Birector's Office. Office of Inspection and Enforcement 84/01/30 ip 82066 035
- B402070D19 Comments on draft IE bulletin. "Undervoltage Trip
 Attachments of Reactor Trip Breakers." as provided at B40116
 meeting Westinghouse plants will be included in bulletin
 scope. Maint statements & action items will be revised
 EISENHUT.D © Division of Licensing B4701/25. JORDAN. E. L
 Division of Emergency Preparedness & Engineering Response (Post
 B30103) Bpp 22142 267
- 8402080329 PND-I-84-012 on 840201.Franklin Machine Industries reveived shipment of restaurant table profestals & suspected pedestals contaminated u/Co-40 Inspector found no measurable radiation readings No further actions planned FRIEDMAN, OLENN,J., JOYNER,J Region i, Office of Director. 84/02/03 ig 22130-319
- 8402080398 PND-III-B4-013 on B40203, reactor shutdown commenced to prepare for 30-wk outage to replace recirculation sys piping due to intergranular stress corrosion cracking Media informed 970BE, J , WALKER, R , SHAPER, W Region 3, Office of Director. 84/02/03 1p 22130:362. 24% Fiche. 50-263,84/02/03,8402080398
- 8402140077 EN-83-070A on 831027 notice of violation & proposed imposition of civil penalties in amount of \$4,000 to be issued. Action based on eight apparent violations rebreakdown in mgt oversight & radiation safety program FLACKLE , AXELRAD, J Director's Office, Office of Inspection and Enforcement 84/02/10 ip. 22217 213.
 - N2140103 PNO-II-84-007 on 840204, seven vials of rediopherms missing rom Amersham Corp shipment found Matls consist of P-32 S-35 State of VA Bureau of Radiation Health recovered ials DTTER, J.P., COLLINS, D.M. Region 2, Office of Director, 84/02/07 app. 2217 353
- 402140111 FNS-V-B4-002 on B40207.RZ instrumentation cables in upper cable spreading room discovered deliberately cut.Util & Bachtel Const Co conducting investigation Findings & further plans will be reviewed on B40213-14.

 8CHAEFER: D W . NORDERHAUG: L R Region 5. Office of Director 84/02/09 ip R2219:055 24X Fiche 50-530,84/02/09,8402140111
- 8402140156 PNO-II-84-007. on 840203, NFS reported inventory difference resulting from 831228 physical inventory U exceeded limit of error, Investigation being conducted to determine cause, MCALPINE, E J Region 2, Office of Director. 84/02/06 ip 20089 200
- 8402140171 PND-II-84-006, on 840203, during routine insp of torus interior, licensee found open cract around circumference of torus vent header. Util working w/GE & Bechkel to demonstrate integrity of torus vent header of Unit 1. PANCIERAL W. ROGGE, JF Region 2. Office of Director. 84/02/03 2pp 22230.088 24X Ficher 50-366,84/02/03,8402140171.
- 8402140330 PND-IV-B3-010D on 840201.TX Appeals Court handed down judgment re Mar 1983 order suspending Gulf Nuclear, Inc license, On 830929 NRC filed amicus curise brief Am-241 exposure incident resolved.

 DOBA-R.J Region 4. Office of Director 84/02/08 2pp. 22221.046

- 8402140439 PNO-II-84-008 on 840126 unit taken out of syc to locate to repair steam generator tube leak Steam generator will be replaced & unit restarted in Jul HARDIN, A K, VERRELLI.D M Region 2, Office of Director, ip 22227 185 24X Fichs 50-261,84/02/07,8402140439
- B402140446 PNO-II-84-006A on 840203, crack found in torus vent header investigation of cause in progress Cause appears to be brittle type failure caused by significant temp changes due to introduction of nitrogen PANCIERA, V W , HERDT, A R Region 2, Office of Director. 84/02/06 2pp 22227 183 24X Fiche, 50-366, 84/02/06, 8402140446
- 8402150206 PNO-V-84-006 on 840207, electricians found 22 instrumentation cables cut in upper spreading room Licensee posted 24 h guard in vicinity & is contemplating press release DDDB, R, BISHOP, T Region 5, DPfice of Director 84/02/07, Ly 22244 OBB 24% Fiche 50-530,84/02/07,8402150206
- 8402150213 PNO-V-84-005 on 840204.Mt St Helens erupted Minor landalide occurred Plant has taken precentionary measures should fallout occur popps, R. BISHOP.T Region 5, Office of Director 84/02/07 pp 22244 138 24X Fiche 50-344.84/02/07.8402150213
- 8402150235 PNO-IV-84-003 on 840130 fire discovered in complex of trailers west of power block Local fire dept responded & fire extinguished on 840131 Licensee evaluating extent of damage JOHNSDN. W D . SCHUM, W B Region 4, Office of Director 84/01/31 to 22248 113 24X Fiche 50-482 84/01/31 8402150235.
- 8402:30239 PNO-III-84-015 licenses evaluating potential problem result of commercial grade equipment in safety-related applications Procedures may be developed to test & qualify mat!

 VANDEL.T E. HUNTER.D R. STREETER.J F Region 3. Office of Director 84/02/10 1p 22250 116 24X Fiche 50-341.84/02/10. 8402150259
- 8402150284 PNO-III-84-014 on 840207, contractor security guard accidentally discharged revolver on refueling floor of reactor bidg when removing pistol from holster Guard terminated by licensee No one injured CREED, J. R., AXELBON, W. L. Region 3, Office of Director. 84/02/19 1p 22242 117 24X Fiche 50-358,84/02/10,8402150284
- B402150327 PNO-II-B4-010 on 840209, NASLP terminated hearing on util license amend request to replace steem generators. Issuance of license amend verbally authorized. Written order expected within 10 days
 JUNEA, B W , GILLILAND, J T Region 2. Office of Director. B4/62/10 2pp 22250 100 24% Fiche 50-261,84/02/10,8402150327.
- 8402150342 PNO-II-84-012 on 840212 onsite power disruptions caused reactor trip Caused by personnel errors. Unit 3 restarted. Licensae responding to media inquiries State of FL informed ELROD, S. A., DANCE, H.C. Ragion 2, Office of Director. 84/02/13 2pp 22250 252. 24% Fiche 50-250,84/02/13,8402150342
- 8402150360 PNO-V-84-007 on 840207. licensee reported that during 840203 annual requalification exam, licensed operator admitted cheating Operator removed from licensed duties & volunterily resigned dn 840210. Region V will assess licensee action.
 MILLER, L., BISHOP, T Region 5, Office of Director 84/02/08. Sp. 22243, 122 24X Ficher 50-344, 84/02/08, 8402150360.
- 8402:50385 PND-IE-84-001: state depts & agencies being provided uplated listing of customers of Falcon Products, narrowing time period when contaminated table base parts shipped. Contaminated metal melted on 83:2210. METZOER.J.R. Director's Office. Office of Inspection and Enforcement 84/02/13. 2pp 22241:348
- 8402160382 PNO-I-84-013 on 840211 licensee commenced unschedules outage to locate & repair steam generator 22 tube leak. Plant placed in cold shutdown on 840214 Licensee plans to drain down primary sys to repair leak. RISTER: H Region 1, Office of Director 84/02/13 ip. 22264.094 24X Fiche 50-247,84/02/13,8402160382
- 8402170165 EN-BA-004 on 840216, notice of violation & proposed imposition of civil penalty in amount of \$5,625 to be issued re shipments of licensed matl w/surface radiation levels in excess of regulatory limits FLACK, E. AKELRAD, U Director's Office, Office of Inspection and Enforcement B4/02/10, ip. 22299 025.

- E402170195 PNS-V-84-003 on 840212; unauthorized individual entered protected area Individual observed by security at all times Individual arrested NRC will followup during next routine physical security insp ECHMAN, C. FIBH, R. F. Region 5, Office of Director 84/02/13 1p 22299 282. 24% Fiche 50-275,84/02/13,8402170195
- 8402170274 PNG-II-84-013 on 840214, inboard shutdown cooling suction valve 1-74-48 failed to open Caused by electrical problems Licensee deciared alert due to loss of shutdown cooling. Drywell will be entered to manually open valve VERRELLI, D., LEMIS, R. Region 2, Office of Director 84/02/14 ip 22297/163. 24X Fiche 50-237.64/02/14.8402170274
- 8402220049 PNG-III-84-015 on 840213.unit tripped as result of low condenser vacuum. Caused by failure of feedwater heater 14A strection steam expansion joint Unit will be brought to cold shutdown & repairs completed QUDEMOND.W. MALKER.R. Region 3. Office of Director 84/02/13 p 22334 362 24X Fiche 50-373.84/02/13.8402220049
- 3402220053 PNO-II-84-014 on 840216, electrical problems resulted in isolation of switchyard bus which feeds main feedwater pump, causing pump to trip & reactor trip Personnel error made while attempting repairs resulting in power disruption ELHRD, 81.A. DANCE, H C Region 2, Office of Director 84/02/16 2pp 22337:327 24X Fiche 50-250,84/02/16,8402220053
- 3402220059 PNO-II-84-013A.on 840214.reactor remained stable in cold shutdown.w/reactor coolant temp at 199 f & reactor pressure atmospheric for repair of shutdown cooling suction valve Unit will remain in alert status
 VERRELLI, D M. LEWIG.R C. Region 2. Diffice of Director 84/02/14
 2pp. 22337.325 24X Fiche.50-259,84/02/14.8402220059
- 3402220103 PMO-TMI-84-001.on 840215, initial preparations for load testing reactor bldg polar crane made Missile shields moved to load test frame to perform qualification load test Polar crane operated satisfactorily.

 MISBE, J. FASANO, A. BARRETY, L. TMI Program Office 84/02/15, 1p 22336.260. 24X Fiche: 30-320,84/02/15,8402220103
- 3402220169 PNO-I-84-016 on B40216 emergency diesel C failed 18-month surveillance test Gaused by turbocharger thrust bearing trouble. Thrust bearing replaced & turbocharger reassembled Licensee investigating cause of problem. PLISCO.L., MCCABE.E Region 1, Office of Director 84/02/17 ip 22340 138 24X Fiche 50-387,84/02/17,8402220169
- 8402220212 PNC-T-84-015 on 840216 package w/DDT White I radioactive label "T1-201,9 mCl," lost from Metcor (DOT carrier) truck in New Haven, CT, T1-201 accelerator produced & not under NRC jurisdiction. Carrier attempting to find package.

 JOHANBEN, OLENN, J. JOYNER, J. Ragion 1, Office of Director 84/02/16, 1p. 22339, 243
- 8402220557 PNG-III-84-016: on 840213, while at 90% power, unit tripped Caused by feedwater heater 14A extraction steam expansion joint failure resulting in low condenser vacuum Repairs scheduled for cold shutdown.

 QULDEMOND, 9 . MALKER R Region 3, Office of Director 84/02/13, 19 22333, 152. 24% Fiche 50-373, 84/02/13, 8402220557
- 3402220576 PNO-V-64-008 on B40130, shipment of low level redwaste received from 85M. Two drums found to have puncture holes in side. No lose contamination associated w/shipment, State of MA banned 85M from use of burial site THOMAS.R. D. Region 5, Office of Director. 84/02/10 ip. 22331:360
- 3402220582 PND-II-84-015: on 840216, workers clothing contaminated w/low rubidium levels when employees vented waste gas systyd control tank. Caused by waste gas compressor leak Morkers detained until rubidium activity decayed JENISON K.M., ELROD. 8. A Region 2, Office of Director 84/02/16. ip 22331:362, 24X Fiche:50-338,84/02/16,8402220382.
- 8402230211 PNO-V-B4-009 on 840215, limited number of workers treated following inhalation of fumes from unknown substance Cause believed to be tear gas from Marine Corps training activities Emergency drill interrupted.

 CARTER: H L , KIRSCH, D F. Region 5, Office of Director. 84/02/15, ip 22361.106 24X Fiche: 50-206, 84/02/15, 8402230211.
- B402270218 Forwards Buppl i to IE Info Notice 83-63, "Potential Failures of SA-1 Relays,"

 BAER.R.L. Engineering & Generic Communications Brench. 84/02/17

 SCHMIDT, W.J. Westinghouse Electric Corp. 1p 22407:314

- 8402270307 PNO-III-84-019 on 840221.licensee announced inability to meet scheduled fuel load date of Dec 1984 Delay caused by longer than planned time to install piping & electronic control circuitry Unit 2 date remains Third Guarter 1988 MARABITO.R . KONKLIN.J Region 3. Office of Director 84/02/22 ip 22391 240 24% Fiche 50-440.84/02/22,8402270307
- 8402270420 FNG-III-84-017 on 840218, licensee identified cracks on loop jet pump A instrument seal line Licensee evaluating whether to repair or replace cracked seal line on both loops A & B Ragion will follow licensee course of action MADISON.A. (CHRISSOTINOS.N. Region 3. Office of Director 84/02/21 ip 22389 362 24X Fiche 50-263,84/02/21,8402270420
- 8402270424 PNO-III-84-018 on 840217. while puiling out third control rod to verify shutdown margin capability, reactor went critical at rod position 18 on 325 s period Test terminated by returning three rods to fully inserted position MADISON.A., CHRIBBOTINOS.N Region 3. Office of Director 84/02/22 ip 22370 221 24X Fiche 50-265,84/02/22,8402270424
- 8402280372 PNO-III-84-020 on 840222; during routine surveillance test, three of four reactor degressurization sys isolation valves failed to open Licensee contacted valve vendor for assistance in evaluating incident.

 WRIGHT, 0 . BOYD, D . SHAFER, W Region 3, Office of Director 84/02/23 ip 22405 018 24% Fiche 50-155-84/02/23,8402280372
- 8403280455 PNO-I-84-017 on 840223. package of 6 3 uGi cobalt chloride found damaged at truck terminal in Bath.PA. Radiation & contamination surveys performed No contamination found NIMITY, R L , KINNEMAN.J D . GREENMAN.E G Region 1. Office of Director 84/02/23 1p 22407 057
- 8402270067 Responds to FOIA request for NRC rept re 830713 incident at Shelwell Bycs in Licting County, DH & documentation leading up to issuance of rept Forwards App A documents Insprept will be forwarded when completed FELTON, J M Division of Rules and Records 83/12/14, GARDNER, G L Frost, Freytag & Hunter, 3pp 22431 184,
- --8402270083 PNO-III-83-085.on 830913.well legging source containing Cs-137 damaged during removal from storage container for installation in wall legging tool, causing contamination of approx 10 Aquare ft SLAHINBKI, W., BRENIEWSKI, D. Region 3, Office of Director 83/09/15 ip 22431:187
- 8402270146 PNO-IE-84-002 updating info re contaminated rebar & cast iron table castings from Mexico Contaminated rebar secured in States of TX,NM,AZ,CO & NV awaiting shipment to Mexico Approx 90% of table bases found METZGER,J,R, 8LY,D,K Director's Office, Office of Inspection and Enforcement 84/02/27 2pp. 22428.148
- 8402290296 PNO-I-84-018 on 840224, unit tripped from 100% power due to main generator trip Caused by stator coil failure Extended outage may be required for repairs.

 LINVILLE-J . NORRHOLM-L. Region 1. Office of Director 84/02/27 ip 22426-302 24% Fiche 50-272,84/02/27.8402290296
- B402290347 Forwards IE Info Notice 83-63, Suppl 1, "Potential Failures of SA-1 Relays " Comments requested,

 BAER: R L Engineering & Generic Communications Brench 84/02/17 RHOADS, E W Brown Boveri Corp (subs of Brown Boveri & Co., Ltd.)

 Spp. 82438:269

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

- 8402010502 Requests assistance in review of CRT display evaluation at furthcoming workshop Staff developed checklists oriented at human factors evaluation Assessment by experts in non-nuclear industry suggested W/o encl BELTRACCHI,L. Human Factors Engineering Branch. 84/01/17 WILLIAMB,T.J Purdus Univ , West Lafayette: IN 2pp 22061:342
- 8402060467 Provides info re Whittaker Metals site in Greenville.PA Whittaker Metals stopped production in 1974 Ore & all slag containing thorium remained on property, Matls appear stable & insoluble.

 KINNEMAN.J D. Region i, Office of Director. 84/02/02 BLACK,K Pannaylvania, Commonwealth of, 2pp. 22083 086
- B402060485 Forwards review of NucleDyne passive containment sys desig Addl info must be developed & available before definitive review can be conducted DENTON, H.R. Office of Nuclear Reactor Regulation, Director, B4/01/26 FALLS, O. B. NucleDyne Engineering Corp., 22pp 22i10, 20

- 8402060492 Discusses requirements for successful completion of channel functional test, particularly evaluation of requirement to perform setpoint verification Requirement should be based on plant-specific setpoint methodology EISENHUT, D O Division of Licensing 84/01/23 OLSHINSKI.J A Division of Engineering & Operational Programs 29p 22110 167
- 8402070276 Responds to 83ii21 ltr expressing contern about NRC perception of use of highly enriched U in nonpower reactors Final decision on policy re conversion of nonpower reactor to low enriched U not yet finalized DENTON, HR Office of Nuclear Reactor Regulation, Director 84/01/29 WHITTEHORE, W.L. GA Technologies, Inc./General Atomic Co ip 22177 357
- 8402100251 Requests cancellation of one of two attached addresses HUNDRICK.K Germany, Federal Republic of 84/01/10 NRC No Detailed Affiliation Given 1p 22161 265
- 8402130084 Discusses NRC 831104 performance of radiation level surveys at Cameron-Sala Landfill areas identified by NUS while conducting other surveys & tests for EPA on 830921 No radiation levels above normal background detected KINNEMAN.J D Region I. Defice of Director 84/02/07 BEGAL. G Korman Corp 2pp 22199 278
- 8402130499 Requests concurrence on comments re Section 8 of Italian probabilistic based general design criteria for PMR plants entitled "Provisions for Decommissioning "Section should be expanded to include listed considerations THOMAS.C O Standardization & Special Projects Branch B4/01/27 EISENHUT.D O Division of Licensing 2pp 22214 345
- ---B402130502 Requests NRR div directors assign appropriate senior personnel to review & comment on Italian probabilistic based general design criteria for PWRs Comments should be submitted by B40123

 DENTON, HR Office of Nuclear Reactor Regulation, Director B4/01/10 MINGOUER, B Défice of Nuclear Regulatory Research, Director B5/01/10 MINGOUER, C Director's Défice, Défice of Inspection and Enforcement & SESNHUT, D & Division of Licensing 2pp
- --B40213050B Requests NRC comments & decisions re new Italian criteria for PWRs & latest ideas on new criteria for advanced PWRs & possible safety features NASCH1,0 Italy. Govt of. 84/01/27 PALLADIND.N J. Commissioners. 2pp 22214:350
- 8402140481 Forwards monthly FR notice to NSHC W/o encl DENTON,H R Office of Nuclear Reactor Regulation, Director 84/01/31 SIMPSON,A Senate, Environment & Public Works UDALLIK K House of Rep , Interior & Insular Affairs OffINGER,R L House of Rep , Energy & Commerce 2pp 22251 350
- 8402140488 Forwards "Summary of Nonreactor Event Rept Database for Jan-June 1983"
 HELTEMES,C J Director's Office AEGD/N307 83/12/28 DAVIB,J @ Office of Nuclear Material Safety & Bafeguards,Director.
 DEYDUNG,R C Director's Office Office of Inspection and Enforcement HERR, G.W. Office of State Programs, Director 1p 22254 284
- --8402140497 "Summary of Nonreactor Event Rept Database for Jan-June 1983 " BLACK, K. Director's Office AEDD/N307 83/12/28 15pp 22256 285
- 8402140525 Recommends formation of multidisciplinary group for initial assessment of potential safety problems associated w/locked doors & barriers in nuclear power plants EISENHUT.D 9 Division of Licensing 84/01/30 THOMPSON.H L Division of Human Factors 8afety 2pp 22258:254.
- --8401130140 Notifies of steps taken to address potential safety problems associated w/locked doors & barriers in plants, identified by Committee to Review Bafeguards Requirements at Power Reactors in NUREO-0992 EIRENHUT, Do Division of Licensing, 83/12/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director 4pp 22258, 254
- --8402010284 Responds to 831222 memo re steps taken to resolve potential safety problem associated w/locked doors & barriers in nuclear reactors Multi-disciplinary group should be established to make initial assessment DENTON:H R Office of Nuclear Reactor Regulation, Director 84/01/16 EISENHUT,D.O Division of Licensing 2pp 22258 243
- B402140537 Forwards comments on initial component list along w/suggested components for inclusion in present or future NPRDS list DENTON, H.R. Office of Nuclear Reactor Regulation, Director, 84/02/03 HELTEMES, C. J. Director's Office 11pp 22258 233

- --B312160328 Forwards initial list of key component application: for NPRDS List will be limited to label approx 400 component records in util data base Comments on encl list of generic PHR/BHR components requested by B31209
 HELTEMES.C J Director's Office B3/12/02 DENTON, H.R Office of Nuclear Reactor Regulation, Director DEYOUNG.R C Director's Office. Office of Insection and Enforcement MMMODUE.R B Office of Nuclear Regulatory Remeatch, Director 10pp 22258-244
- 8402210067 Requests that JL Watson be replaced on mailing list by D Larson, executive director SOMMERS, S D Western Interstate Nuclear Board 84/02/13 NRC No Detailed Affiliation Given 1p 22317 283
- 8402210398 Informs that 831101 memo re peer panel rept of differing prof opinion expressed by A Lakner on manual chapter placed in PDR. FLDRY.S Office of Nuclear Regulatory Research, Director MC-412384702/14 Record Services Branch (Document Control Desk) to
- ---B402210411 Responds to B31003 peer panel rept on differing profopinion expressed by A Lakner Conclusions & recommendations accepted per Manual Chapter 4125 Memo may be placed in PBR HIMBQUE, R B Office of Nuclear Regulatory Research, Diractor MC-4125 B3/11/01 ERNST, M Division of Risk Analysis. 2pp 22344 177
- --B402210416 Forwards peer panel rept on differing prof opinion expressed by A Lakner on Manual Chapter 4125 Section 6 2
 ROSS D F Office of Nuclear Regulatory Research, Director ROSSIC E Office of Nuclear Reactor Regulation, Director, RICHARDSON B Director's Office, Office of Inspection and Enforcement MC 4125 83/10/03 MINOGUER B. Dffice of Nuclear Regulatory Research, Director 30pp 22344 179.
- B402230150 Forwards NRR Ofc Ltr 44 notifying that scope of input to SALP evaluation greatly expanded Each NRR safeguards svaluation should be accompanied by SALP input.effective E40101
 THOMAS.C O Standardization & Special Projects Branch. B4/02/09 MCCORKLE.O W Power Reactor Safeguards Licensing Branch. 1p 22379 230
- --8402230154 Defines policies to improve participation in BALP protess by regularly summarizing NRR assessment of each util performance & heightening mgt awareness of potentially troublesome issues at plants under const DENTON, HR Office of Nuclear Reactor Regulation, Director 84/01/03 Office of Nuclear Reactor Regulation, Director 12pp 22379 231
- 8402270374 Ack receipt of NRC 840126 ltr commenting on NucleDyne passive containment sys design. Possibility of pursying design review process. per 100FR30. App O. being studied FALLS. O B NucleDyne Engineering Corp 84/02/07 DENTON. H. R Office of Nuclear Reactor Regulation, Director 2pp. 22438.236

NUREQ REPORTS AND RELATED CORRESPONDENCE

- 8310270388 RIL-136
 Interim Research Info Ltr 136 discusses accident sequence precursor program Data from draft 1980-81 rept being analysed Detailed info encl
 MINOQUE, R D Office of Nuclear Regulatory Research, Director, FIN 8-1983 63/10/14, DENTON, H R Office of Nuclear Reactor Regulation, Director, 29pp 22090 001.
- 8312120027 Generic Ltr 83-37 to representatives of utils re voluntary survey of licensed operators 8vc list encl.
 EIBENHUT, D 0. Division of Licensing QL-83-37 83/12/08
 Commenuealth Edison Co. 12pp 22313,006 24X Fiche 50-000, 83/12/08,8312120027.
- 8402010111 NUREG/CR-3242
 THE LOS ALAMOS NATIONAL LABORATORY/NEW MEXICO STATE
 UNIVERSITY FILTER PLUGGING TEST FACILITY DESCRIPTION AND
 PRELIMINARY TEST RESULTS
 FENTON,D L , DALLMAN,D J , SMITH,P R Los Alamos Scientific
 Laboratory, FIN A-7029 LA-9929-MS 84/01/31. Division of Right
 Analysis 13pp 28058 028

i

- 8402010134 Forwards Rev 1 to "Rept on Control of Heavy Loads," updating Areas of safe load path review & Vendor analysis of reactor caolant gump motor lifting sling, per NUREG-0612 critoria FETRICK, N A Standardized Nuclear Unit Power Plant System SLNRC 84-0608 B4/01/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 22038 235 24X Fiche 50-000, 84/01/27, 8402010134
- --8402010149 Rev 1 to "Rept on Control of Heavy Loads"

 Standardized Nuclear Unit Power Plant System 84/01/27 22pp
 22038 238 24X Fiche 50-000.84/01/27.8402010134
- 8402010151 Forwards "Safety Parameter Display Bys Program Plan" & responds to NRC 831205 ltr re control room design review in-progress audit Audit proposed to take place during wk of 840312.

 88EY.H L Public Bervice Co of Colorado P-84013 84/01/20 COLLINS.J T Region 4, Office of Director 2pp 22038 261 24 Fiche 50-267,84/01/20,8402010151
- --B402010157 "Bafety Parameter Display Bys Program Plan," in response to Generic Ltr 82-33, Suppl 1 to NUREG-0737 R Public Service Co of Colorado GL-82-33 83/09/30 38pp 22038 263 26X Fiche 50-267, 84/01/20, 8402010151
- 8402010160 Forwards "Evaluation of Georgia Power Co Emergency Preparedness Plan for EI Hatch Electric Generating Plant," final rept. KRIMI,R W Federal Emergency Management Agency 84/01/24 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 22039 223 24X Fiche 50-321,84/01/24, 8402010160
- --8402010165 "Evaluation of Georgia Power Co Emergency Preparedness Plan for EI Hatch Electric Generating Plant: "final rept # Federal Emergency Management Agency 83/10/28 55pp 22037: 225 24% Ficho: 50-321,84/01/24,8402010140
- 8402010174 Forwards request for add1 info re-procedures generation package Request based on review of 830831 submittal in response to Generic Ltr 82-33, "Suppl 1 to NUREQ-0737-Requirements for Emergency Response Capability "SCHMENCER, A Licensing Branch 2 QL-82-33 B4/01/18 CAHILL,W J Quif States Utilities Co 5pp. 22048 051 24X Fiche: 50-458.84/01/18,8402010174
- 8402010184 Forwards comments on detailed control room design review (DCRDR) program plan submittel per Suppl 1 to NUREG-0737, DCRDR summary repts submitted on 830930 & 1101 currently under review.

 VARQA, B A Operating Reactors Branch 1 84/01/16 WILLIAMB, J W Florida Power & Light Co. 10pp 22048 033 24X Fiche, 50-000, 84/01/16, 8402010184.
- 8402010194 Forwards exemption from 10CFR50, 44(c)(3)(iii) re RCB high point vents, per NUREO-0737. "Clarification of TMI Action Plan Requirements." in response to 830825 request. VARGA: 8 A Operating Reactors Branch 1 84/01/12 CAREY, J. J. Duquesne Light Co 7pp. 22047 341. 24X Fiche: 50-334, 84/01/12, 8402010194.
- 8402010207 Grants extension until 840315 for implementation of new licensed operator staffing rule, per IOCFR50 54(m)(2), Tech Space should be amended accordingly by 840315.
 EISENHUT, D. Q. Division of Licensing 84/01/12 QARRITY, J. H. Maine Yantee Atomic Power Co. 3pp. 22048.001 24X Fiche 50-309,84/01/12,8402010207.
- --8402010212 Safety evaluation supporting extension until 840315 for implementation of revised control room shift staffing rule, per 100FR50 54, # Office of Nuclear Reactor Regulation, Director 84/01/12 2pp 22048:004 24x Fiche: 50-309:84/01/12;8402010207.
- B402010221 Discusses review of util 820108 submittal re NUREG-0737, Item II. K. 2. 17, "Potential for Voiding in RCS During Transients," per Generic Ltr 81-21, "Natural Circulation Consident," Void accounted for in present analysis models VARGA: B A Operating Reactors Branch 1. GL-81-21 84/01/16. FARRAR, D. L. Commonwealth Edison Co. 11pp. 22047.330. 24X Fiche 50-293,84/01/16,8402010221
- B402010247 Forwards SER re NUREG-0737, Item II.F 2 & Generic Ltr 82-28, *Inadequate Core Cooling Sys " Add1 info requested to complete review of B30512 submittal Generic Westinghouse approach acceptable VARQALS.A. Operating Reactors Branch 1. GL-82-28, 84/01/17, STEKART.W L Virginia Electric & Power Co. 12pp. 22047:297, 24X Fiche: 50-280, 84/01/17, 8402010247

- 8402010250 Forwards interim justification positions for seismic & environ qualification of differential pressure indicating Barton Switch 288A & in-core thermocouples, cohnectors & ref junction box.per NUREO-0588 Graph withheld PETRICK:N A Standardized Nuclear Unit Power Plant System SLARC 84-0009 B4/01/27 DENTON.H R Office of Nuclear Reactor Regulation Director 133pp 22040 001 24% Fiche 50-000,84/01/27,8402010250 0
- 8402010252 Forwards SER re TMI Action Item II K 2 17, "Potential for Voiding in RCS During Transsents " Voiding generated in RCS during anticipated transients will not result in unacceptable consequences
 VARGA.5 A Operating Reactors Branch 1 IEB-79-06A B4/01/16
 UTLEY.E E Caroline Power & Light Co 10pp 22047 287 24X
 Fiche 50-241, 84/01/16, 8402010252
- B402010257 Forwards for review & comment, DES, (NUREG-1026) & FR notice of availability Comments due within 45 days after FR publication W/o DES YQUNOBLOOD, B J Licensing Branch 1 84/01/14 WOOD, J M Commerce, Dept of, Natl Decanographic & Atmospheric Administration ip 22047 284 24X Fiche 50-456,84/01/14,8402010257
- --8402010260 Notice of availability of DES (NVREG-1026) YGUNGBLUDD.8 J Licensing Branch 1 84/01/13 2pp 22047 285 24% Fiche 50-456.84/01/16.8402010257
- 8402010274 NUREO/CR-3553
 AN EFFICIENT SIMULATION APPROACH FOR EVALUATING THE POTENTIAL EFFECTS OF NUCLEAR POMER PLANT SHUTDOWNS ON ELECTRICAL GENERATING SYSTEMS
 VANKUIKEN, J C Argonne National Laboratory FIN A-2223
 ANL/LEES-TM-233 84/01/31 Office of Nuclear Regulatory Research, Director 37pp 22048 061
- 8402010276 Forwards "Conformance to NRR Generic Ltr 82-16, North Anna Power Station Units 1 & 2." technical evaluation rept Rept review indicates conformance to NUREG-0737 ltem requirements Amend will be issued within 14 days MILLER, J R Operating Reactors Branch 3 QL-82-16 84/01/12 STEWART.W L Virginia Electric & Power Co 2pp 22047 258 24X Fiche 50-338,84/01/12.8402010276
- --8402010279 EG0-EA-6430 "Conformance to NRR Generic Ltr 82-16.North Anna Power Station Units 1 & 2," technical evaluation rept VANDERBEEK,R EG80, Inc FIN A-6600. GL-82-16. 83/10/31 NRC - No Detailed Affiliation Given 24pp. 28047.260 24X Fiche 50-338,84/01/12:8408010276
- 8402010277 Forwards evaluation of util response to Generic Ltr 82-28, "Imadequate Core Cooling Instrumentation Sys." Addi info re existing core exit thermocouple & subcooling margin monitoring sys.per NUREO-0737 requested within 30 days MILLER, J R Operating Reactors Branch 3 GL-82-28 84/01/16 STEWART, W L Virginia Electric & Power Co 11pp 22046 340 24X Fiche. 50-338. 84/01/16, 8402010277
- B4020102B2 Application to amend License DPR-28. revising Tech Spacs to reflect change in main steam line law pressure isolation setpoint while in run mode. From 850 to 800 psig per NVREQ-0797, Item II K 3 16
 HEIDER, L H Vermont Yankee Nuclear Power Corp FVY 84-5 84/01/23 EISENHUT, D Q Division of Licensing 5pp. 22040 276 24X Fiche. 50-271, 84/01/23, 8402010282
- 8402010288 Summarizes ACRS 285th meeting on 840112-14 re license renewal & power increase Renewal of license at requested power level of 20 MH may be granted w/s undue risk to public health & safety EBERBOLE, J O ACRS Advisory Committee on Reactor Safeguards 84/01/17 PALLADINO, N J. Commissioners 4pp 22046 336. 24% Fiche 50-184,84/01/17,8402010283
- 8402010302 NUREO/CR-3408 ERR
 OROANDHALDGEN PROBUCTS FROM CHLORINATION OF COOLING MATER
 AT NUCLEAR POWER STATIONS
 BEAN-R M Battelle Memorial Institute, Pacific Northwest Leboratory
 FIN 8-2098, PNL-4788 84/01/18 Division of Health. Siting &
 Waste Management ip 22046:312
- B402010310 Forwards DES, (NUREC-1026) & FR notice of availability.W/o DES YOUNGBLOOD, B J Licensing Branch 1. 84/01/16 Illinois, State of 1p 22059 226 24X Fiche 50-456,84/01/16,8402010310
- 8402010313 NUREO/CR-3522 VO2
 REFERENCE MATERIALS FOR NONDESTRUCTIVE ASSAY OF SPECIAL
 NUCLEAR MATERIAL. Volume 2 Thin Metal Foils of Highly
 Enriched Uranium.
 SPRINKLE, J. K., LIKES, R. N., SMITH, H. A. Los Alamos Scientific
 Laboratory FIN A-7072. LA-9910-ME-VO2 84/01/31. Division of
 Facility Operations 15pp 22046 210.

- 8402010330 Forwards comments on 840103 memo re industry questions & NRC responses regarding LER rule (OCFR50 73 Guestions constructive NRC responses generally clear & concise Concurs w/guidance w/enc] exceptions
 DENTON Office of Nuclear Reactor Regulation, Director 83-43
 84/01/25 HELTEMES, CJ Director's Office 2pg 22057-236
- --8402010335 Forwards questions & answers on new LER rule 10 CFR50 73, suppl to NUREO-1022. "LER Sys " Comments should be submitted by 840116 HELTEMES, C J Director's Dffice 84/01/03 HINDQUE, R B Office of Nuclear Regulatory Research, Director DEYOUNG, R C Director's Office Office of Inspection and Enforcement DEWION, R C Office of Nuclear Regulation, Director 52pp. 22057 238
- 8402010364 Further response to FOIA request for records re Ofc of Inspector & Auditor review of NRC investigation reported in NUREG-0862 & other files concerning facilities Forwards App B documents App A B documents available in PDR FELTON.J M Division of Rules and Records 83/11/22 REYNOLDS, J Center for Law in the Public Interest 4pp 22058 203 24X Fiche 50-000.83/11/22.8402010364
- --B402010372 Recommends transmittal of investigation review rept to Congress per R Ottinger 820204 ltr re inconsistencies in NUREG-0862 & M Udall 820208 request Related info encl KAMMERER.C Office of Congressional Affairs 82/08/31 PALLADINO.N Commissioners 150pp 22058 207 24X Fiche 50-000.83/11/22.8402010364
- --8402010378 Forwards review of NUREO-0862, "Insp Rept of Preliminary Rept.Seismic Reverification Program at Diablo Canyon Units 1 & 2 "Related info encl BOULDEN,H Office of Inspector & Auditor 83/11/22. CUMMINOS.J J Office of Inspector & Auditor 39pp 22058 357 24% Fiche 50-000.83/11/22.8402010364
- 8402010365 NUREO/CR-3616
 TRANSPORT AND SCREEN BLOCKAGE CHARACTERISTICS OF
 REFLECTIVE METALLIC INSULATION WATERIALS
 BROCKARD.D N Alfen Research Laboratory
 FIN A-1294 ARL-124-83/M39F 84/01/31 Division of Safety
 Technology 48pp Available at NRC \$4 on 22061 040
- 8402010348 NUREC/CR-3522 VO1
 REFERENCE MATERIALS FOR NONDESTRUCTIVE ASSAY OF SPECIAL
 NUCLEAR MATERIALS, VOL 1 U Oxide Plus Graphite Powder.
 SPRINKLE, J K , LIKES, R N , PARKER, J L Los Alamos Scientific
 Laboratory FIN A-7082 LA-9910-M9 VO(84/01/31 Division of
 Facility Operations 41pp 22041 001
- 8402010373 NUREG/CR-3562
 STEAM GENERATOR TUBE INTEGRITY PROGRAM LEAK RATE TESTSPROGRESS REPORT.
 CLARK.R.A. BICKFORD,R L Battelle Memorial Institute, Pacific
 Northwest Laboratory. FIN 8-2097 PNL-4627 84/01/31 Division
 of Engineering Technology 68pp Available at NRC \$4 50
 22061.090
- 8402010410 Generic Ltr 84-04 to all operating PWR licensees, CP holders & applicants for CPs re-safety evaluation of Mestinghouse topical repts dealing w/elimination of pustulated pipe breaks in PWR primary main loops 8vc list enci EIBENNUT.D 0 Division of Licensing 0L-84-04 84/02/01 Convolidated Edison Co. of New York. Inc 59pp 22177-087. 24X Fiche: 50-000; 84/02/01, 8402010410
- 8402010465 Forwards DES (NUREG-1026) & FR notice of availability. W/o DES YOUNGBLOOD, B J Licensing Branch 1 84/01/16 FARRAR, D L Commonwealth Edison Co ip 82059 314 24X Fiche 50-456, 84/01/16, 8402010465
- B402020049 Requests review of encl NUREO/CR-1996, "Geochemical Parameters Used in Bedded Salt Ref Repository Risk Assessment Methodology " W/o encl ROSSBACH.L W High Level Waste Licensing Management Branch 00009 82/05/10 NEWTON:C Energy, Dept of 2pp 22062 295.
- B402020195 Forwards IE Insp Rept 50-286/83-22 on 831116-1215, No viglations noted STAROBIECKI, R. Division of Project & Resident Programs 83/12/27. BRDN8.J.C Power Authority of the State of New York 2pp. 22057 156 24% Fiche 50-286,83/12/27,8402020195
- --8402020204 IE Insp Rept 50-286/83-22 on 831116-1215 No violations noted. Major areas inspected radiological medical drill, IE bulletin followup, shift logs & records, actions on previous inspected findings, plant tour, surveillance & maint KENNY, T J , ROSSBACH, L W Region i. Office of Director, NORRHOLM, L Division of Project & Resident Programs IEB-79-24 83/12/22 lipp 22057 158 24% Fiche 50-286,83/12/27,8402020195

- 8402020237 Responds to NRC 810811 request re quarterly updates of const completion date Schedule for implementing Suppl 1 to NUREG-0737 will permit fuel loading by 840801 KEMPER. J S Philadelphia Electric Co 83/12/27 EISENHUT. D. Q Division of Licensing 2pp 22037 021 24X Fiche: 50-352,83/12/27. 8402020239
- 8402020245 Forwards IE Insp Repts 50-387/83-25 & 50-388/83-24 on 831107-1218 & notice of violation STAROSTECKIR Division of Project & Resident Programs 84/01/20 KENYON,8 D Pennsylvania Power & Light Co 2pp 22055.279 24X Fiche 50-387,84/01/20.8402020245
- --8402020232 IE Insp Repts 50-387/83-25 & 50-388/83-24 on 831107-1218
 Noncompliance noted failure to maintain average reactor
 coolant temp less than or equal to 140 F while in Condition
 5 (refusing)
 RHOADB-0 PLIBCO.L Region 1, Office of Director MCCABE, E C
 Division of Project & Resident Programs 50-388/83-24 83/12/29
 12pp 22055 302 24% Fiche 50-387,84/01/20,8402020245
- B402020289 Application for amend to License DPR-45 addressing items identified in NUREG-0737.in response to B31101 ltr to all BMRs
 LINDER,F Dairyland Power Cooperative LAC-9553 B4/01/30.
 CRUTCHFIELD.D Operating Reactors Branch 5 3pp 22055:163 24X Fiche 50-409.84/01/30.8402020289
- --8402020295 Proposed Tech Specs addressing items identified in NUREO-0737 ** Dairyland Power Cooperative 84/01/30 3pp 22055.166 24% Fiche 50-409.84/01/30.8402020289
- 8402020308 Responds to Generic Ltr 82-16 re NUREG-0737, Items I A 1 3 I & II K 3,3 concerning limiting overtime for plant staff & reporting safety & relief valve failures, respectively.

 CRUTCHFIELD.D Operating Reactors Branch 5, 6L-82-16 84/01/30.

 CDUNSIL, N G Connecticut Yankee Atomic Power Co 4pp 22055:095

 24X Fiche 30-213,84/01/30,8402020308
- 8402020351 Forwards corrected response to Question 420 6 previously submitted W/831216 ltr ra clarification of swergency response capabilities per Suppl 1 to NUREG-0737 (Generic Ltr 83-33) COUNSIL.W 9. Northeast Nuclear Energy Co (sub* of Northeast Utilities) B11002 84/01/13, YOUNGELOOD, B J. Licensing Branch L 399p 22053 213 24X Fichs 50-423,84/01/13,8402020351
- 8402020362 Forwards Rev O to "Control Room Design Review Pisn" & Rev O to "Control Room Design Review Rept," in response to 830912 telcon re Generic Ltf 82-33 (Suppl i to NUREG-0737), MEDFORD, N D Bouthern California Edison Co OL-82-33, 84/01/31, KNIGHTON, O W Licensing Branch 3, 2pp 22049; OO1 24X Fiche 50-361,84/01/31,8402020362
- --8402020364 Rev O to Procedure M37327, "Control Room Design Review Fian. San Onofre Nuclear Generating Station Units 2 & 3 " * Southern California Edison Co * Ban Diego Gas & Electric Co 84/01/31 23pp 22047 003 24X Fiche 50-261.84/01/31, 8402020362
- --B402020365 M3732B R00
 Rev O to "Control Room Design Review Rapt Ban Unofre Nuclear Generating Beation Units 2 & 3 "

 * Bouthern California Edison Co. * Ban Diego Cas & Electric Co B4/01/31 230pp 22049 027 24X Fiche 50-361,84/01/31,
- 8402020473 Summary of 840112 mesting w/util at facility re fire brigade training FSAR will be revised to include specific areas listed in SRP (NUREC-0800) HAUGHEY,M F Licensing Branch 2, 84/01/19, Licensing Branch 2 4pp 22042 157 24X Fiche 50-410,84/01/19,8402020473
- 8402030041 Notification of 840130-31 meetings w/util in Middletown. PA to review implementations of selected NUREO-0737 items. VAN VLIET Operating Reactors Branch 4. B4/01/27. BYQLZ, J.F. Operating Reactors Branch 4. 2pp. 22071.088. 24X Fiche. 50-289:84/01/27.8402030041.
- 8402030099 NUREO/CR-3461
 RESPONSE TREE EVALUATION IMPLICATIONS FOR THE USE OF ARTIFICIAL INTELLIGENCE IN PROCESS CONTROL ROOMS
 RRAY.M A , NELSON, W R , BLACKMAN, M S. EG&G, Inc FIN A-6308
 EGG-2272 84/01/31. Division of Facility Operations. 34pp. 22090 340.
- BAO2030155 Advises that based on review of 831116 & 1212 submittals rt NUREO-0737, Item II, B 3, "Post-Accident Bampling Sys," all 11 review criteria satisfied Item complete MILLER, J R Operating Reactors Branch 3, 01-83-37 B4/01/26, WITHERB, B, D, Portland General Electric Co 1p. 22089, 360, 24X Fiche 50-344, 84/01/26, 8402030155.



- 8402030314 Forwards Rev 2 to "Rept of Independent Review of Environ Qualification Programs to NUREO-0588 "Rev incorporates util 830728 response re surface temp calculation methods PETRICK.N A Standardized Nuclear Unit Power Plant System SLNRC 84-0013. 84/02/01 DENTON, H R Office of Nuclear Reactor Regulation. Director 4pp 22071 073 24X Fiche 50-000, 84/02/01. 8402030314
- --B402030319 Rev 2 to "Rept of Independent Review of Environ Qualification Programs to NVREO-0588" * Standardized Nuclear Unit Power Plant System 84/02/01 709pp 22071 073. 24X Fichs 50-000.84/02/01.8402030314
- --B402030334 Proposed Tech Specs re limiting condition for operations & surveillance requirements for accident monitoring instrumentation.per NOREG-0737 & Generic Ltr 83-36 e Fows Electric Light & Power Co. GL-83-36 84/01/27. 18pp 22069: 134 24X Fiche 50-331,84/01/27,8402030329
- 8402030330 Discusses three BEP issues to be covered through consequence study as part of integrated plant safety assessment (NUREO-OB27). Issues are seismic design considerations, tornado, missies & wind & tornado loadings
 LINDER, F Dairyland Power Cooperative LAC-9555 84/01/30
 CRUTCHFIELD.D. Operating Reactors Branch 5, Rpp 22069:345 24X
 Fichs: 50-409,84/01/30,8402030330
- 8402030425 Forwards IE Insp Rept 50-293/81-14 on 810621-26 & summary of 831130 mgt meeting.
 STAROSTECKI.R Division of Project & Resident Programs 84/01/12 HARRINOTON.W.D. Boston Edison Co 6pp 22068 242 24X
 Fiche 50-293.84/01/12.8402030425
- --8402030430 IE Insp Rept 50-293/B1-14 on Bi0621-26. Noncompliance noted failure to establish procedures for radiological & chemical analysis of primary coolant sampler under accident conditions.

 NMHITZ.R.L., GREENMAN.E Q Region 1, Office of Director 62/05/04 24pp 22068 248. 24X Fiche 50-293,84/01/12,8402030425
- 8402030443 Rev il to Administrative Procedurs 1029, "Conduct of Operations" W/840131 ltr.
 NELBON: M. A., TOCKE: R. J., HUKILL: H. D. General Public Utilities GPU Bervice Corp. 83/09/15 BTOLZ: J.F. Operating Reactors Branch 4 5pp. 22069.031, 24X Fiche: 50-289: 83/09/15, 8402030443
- 8402060012 Further response to FDIA request for three categories of documents Forwards App A documents FELTON, J. M. Division of Rules and Records. 83/10/31. PUNTENNEY, J. Bafe Energy Coalition. 4pp 22091.250
- --B402060079 Responds to B20927 ltr to ST Brewer of DOE re constituent concerns on transportation of spent fuel Explanation provided as to how routes chosen & criteria used for selection.

 DIRCKS, H J. Office of the Executive Director for Operations B2/11/26 0/4MOURS, N.E. House of Rep. 2pp. 22091 345.
- 8402060028 Further response to appeal re denial of FDIA request for documents concerning steam generator problems at facility.
 Forwards App A documents App 8 documents partially withheld (ref FDIA Exemption 4)
 DIRCKB.W J. Office of the Executive Director for Operations.
 83/10/27 DOROSHOW.J. Three Mile Island Alert 7pp 22111.153.
- 8402060087 Responds to SER. Section 4.4 3.4, Open Item 6 reinstrumentation for inadequate core cooling detection (TMI Item II.F 2) Phase i complete. Control room displays will be madified upon completion of control room design review TUCKER.H. B. Duke Power Co. 84/02/01. DENTON.H R. Défice of Nuclear Reactor Regulation, Director. ADENBAM.E G. Licensing Branch 4. 10pp, 22088-261 24X Fiche 50-413.84/02/01.8402060087.

- 8402040103 Forwards description of implementation of listed NUREG-0737 items per Generic Ltr 83-34 Current Tech Specs consistent w/requirements for NUREG-0737. Items II B 1.II B 3.II F 1 & II I B 3.4 DALE.L F Mississippi Power & Light Co AECM-84/0027 84/02/02 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 22088 277 24X Fiche 50-416.84/02/02.8402040103
- 8402040237 Forwards control room habitability study summary rept per NUREG-0737, ltem III D 3 4 % util 830606 ltr Results indicate that control room dose guidelines of SRP satisfied LEMPGES, T E Niagere Mchawk Power Corp 84/01/31 VASSALLO, D 8 Operating Reactors Branch 2 App 22087 213 24X Fichs 50-220,84/01/31,8402060237
- B402060266 Forwards SSER re SER Dutstanding Issue 1 re protection affects associated w/postulated rupture of piping autside containment Issue resolved YDUNOBLOOD, B. J. Licensing Branch 1 84/01/24 GARY, B. J. Texas Utilities Generating Co. 2pp. 22103 175, 24X Fiche 50-445, 84/01/24, 8402060266
- --8402060272 SSER re SER Gutstanding Issue 1 on protection against effects associated w/postulated rupture of piping outside containment Issue resolved

 * Auriliary Systems Branch 84/01/24 7pp 22103 177 24X Fiche 50-445
- 8402050290 Forwards "Control of Heavy Loads at Nuclear Power Plants, Beaver Valley Nuclear Power Plant Unit 2 (Phase 1)," dreft technical evaluation rept based on responses to NUREO-0612 SER on subj will be issued on 840928 KNIGHTON, O W Licensing Branch 3 84/01/17 WOOLEVER, E J Dequesne Light Co 3pp 22109.253 24X Fiche 50-412,84/01/17, 8402040270
- --B401190528 "Control of Heavy Loads at Nuclear Power Plants, Beaver Valley Nuclear Power Plant Unit 2 (Phase I)," draft technical evaluation rept FRIEDERICHS, B EONG, Inc FIN A-6457 B3/11/30 NRC No Detailed Affiliation Given 45pp 22109 256 24x Fiche 50-412, 84/01/17, 8402060290
- 8402060271 NUREG-0020 VO7 N11 LICENSED OPERATINO REACTORS STATUS SUMMARY REPORT Data As Of October 31, 1983 (Grey Book) * Management Information Branch 84/01/31 408pp 22105 267
- 8402060333 NUREO/CR-3477
 CONCENTRATIONS OF COPPER-BINDING PROTEINS IN LIVERS OF
 BLUGGILLS EXPOSED TO INCREASED CONCENTRATIONS OF SOLUBLE
 COPPER
 HARRISON.F L LAM, J R Lawrence Livermore Laboratory UCRL-53487
 84/01/31 Division of Health, Siting & Waste Management 30pp
 Available at NRC #3 75 22107 317
- 8402060336 NUREO/CR-3351 BECURITY OFFICER TACTICAL TRAINING ISSUES INVOLVING ESS EQUIPMENT. ROUNTREE,S L. Sandia Laboratories SANDB2-2933 64/01/31. Division of Safeguards. 44pp Available at NRC \$3 75 22107 272
- 8402060339 NUREO/CR-3435 A NEW IMPLICIT NUMERICAL SOLUTION SCHEME IN THE COMMIX-IA COMMUTER PROPRAM. DOMANUS,H M , SCHMITT,R C , SHA,W T Argonne National Laboratory FIN A-2045 ANL-83-64 84/01/31 Division of Accident Evaluation (Pre 840101), 52pp 22107 348
- 8402060341 NUREQ/CR-2210
 TECHNOLOGY, SAFETY AND COSTS OF DECOMMISSIONING REFERENCE
 INDEPENDENT SPENT FUEL STORAGE INSTALLATIONS
 LUDWICK, J D , MODRE, E B, Battelie Memorial Institute, Pacific
 Northwest Laboratory FIN 8-2036 84/01/31 Division of
 Engineering Technology. 7pp Available at NRC. \$9 50, 22105:001
- 8402060343 NUREQ/CR-3563 COBRA/TRAC BIMULATION OF SEMIBCALE B-UT-2 TEBT BIAN,S.H., THURGOOM J. KELLY.J M Battelle Memorial Institute, Pacific Northwest Laboratory, PNL-9708 84/01/31 Division of Accident Evaluation (Pre 840101). 63pp Available at NRC 64 50 22107-202.
- 8402060417 Forwards add1 info in response to open items re BEP Topic III-6, "Beismic Design Cansiderations " Index of final repts on analyses of structures.RCS piping components & supports & analyses of mechanical & slectrical squipment also encl. CGUNBIL.W.9. Gonnecticut Yankes Atomic Power Co. Bi0979. 84/01/19 CRUYCHFIELD.D. Operating Reactors Branch 5 9pp 22085:130 24X Fiche: 50-213, 84/01/19, 8402060417.

- 8402060420 Forwards IE Insp Rept 50-029/83-14 on 830901-1021 & notice of violation STARDSTECKI, R Division of Project & Resident Programs 84/01/18 HEIDER.L H Yankee Atomic Electric Co 2pp 22084 298 24X Fiche 50-029,84/01/18.8402040420
- --8402060426 IE Insp Rept 50-029/83-14 on 830901-1021 Violations noted failure to control math released from radiation control area & failure to svaluate recurrent Tech Spec violations & implement effective corrective actions CCLLINS.S J Region 1. Office of Director 83/11/10 18pp 22084 302 24X Fiche 50-029.84/01/18.8402060420
- 8402050429 Forwards "LACBWR Detailed Control Room Design Review Final Rept." as required by Generic Ltr 82-33 re emergency response capability & committed to in 820408.830408 & 1205 ltrs in response to NURGE-0737. Action Item I D i LINDER, F Dairyland Power Cooperative GL-82-33 84/01/26 EISENNUT, D G Division of Licensing ip 22085 165 24X Fiche 50-409.84/01/26.8402060429
- 8402050440 Provides info re TMI-1 safety parameter display sys.per B30804 commitment to provide NRC w/identifscation of addl instruments & schedule for implementation, in response to Generic Ltr 82-33 & NURED-0737.Item | I DZ HUKKILL.H D General Public Utilities ~ GPU Service Corp 521:-84-2023 84/02/01 ETSEN-MUT.D G Division of Licensing Spp 23083 092 24X Fiche 50-289.84/02/01.8402040440
- 8402060452 NUREO/CR-3536
 SIMULATION OF LOADING CONDITIONS FOR A TYPE A PACKAGE
 CONTAINING AMERICIUM-241 INVOLVED IN AN AIRPLANE CRASH AT
 DETROIT METRO AIRPORT IN JANUARY 1983
 MAXFIELD, 8 W, WOD. H R
 Lawrence Livermore Laboratory. FIN A-0291
 UCRL-53492 84/01/31
 Division of Fuel Cycle & Material Safety
 19pp Available at NRC \$3 75 22107 167
- 8402060457 NUREG/CR-3492 VOI HIGH-TEMPERATURE GAS-COOLED REACTOR BAFETY STUDIES FOR THE DIVISION OF ACCIDENT EVALUATION GUARTERLY PROGRESS REPORT, APRIL I-JUNE 30,1983 BALL,S J, CLEVELAND, J C . HARRINGTON, R Cax Ridge National Laboratory FIN 8-0122 84/01/31 Division of Accident Evaluation (Pre 840101) 13pp 22115 008
- 8402060478 NUREG/CR-3843
 SURVEY OF OPERATING EXPERIENCE FROM LERS TO IDENTIFY AGING
 TREND Progress Report September 1983
 MURPHY: G A · CASADA.M L · HOY.H C Oak Ridge National Laboratory
 FIN B-0822 ORNL/NSIC-216 84/01/31 Division of Engineering
 Technology 44pp 22110 230
- 8402050484 NUREG/CR-2815
 PROBABILISTIC SAFETY ANALYSIS PROCEDURES GUIDE
 BARI-R A . PAPAZOGLOU, I A . BUSLIK. A J Brookhaven National
 Laboratory BN.-NUREG-51559 84/01/31 Division of Safety
 Technology 234pp Available at NRC \$6 50 22109 014
- 8402060489 Forwards SER re NUREG-0737. Item II B 3, "Post-Accident Bampling Sys " Response to four remaining criteria identified in encl requested within 30 days VASSALLO.D B Operating Reactors Branch 2. 84/01/12. RHODES, 0 K Niagara Mohawk Power Corp 11pp. 22110 183. 24X Fiche 50-220,84/01/12,8402060489.
- B402060497 NUREG-0748 VO3 N12
 OPERATING REACTORS LICENSING ACTIONS SUMMARY Data As Of
 December 31,1983 (Orange Book)

 # Division of Data Automation & Management Information B4/01/31
 335pp. 22108 039.
- 8402060529 NUREG/CR-2000 VO2N12 LICENSEE EVENT REFORT (LER) COMPILATION FOR MONTH OF DECEMBER 1983 * Oak Ridge National Laboratory ORNL/NCIS-200 84/01/31 Director's Office 169pp 22092 143
- 8402070012 Notification of 840207-10 site meetings u/util to review status/schedule & completeness of installation for selected NUREO-0737 items MINER. 6. Operating Reactors Branch 4 84/01/27 8TOLZ, J F Operating Reactors Branch 4 3pp 22142 275, 24X Fiche 50-312,83/01/27,8402070012
- B402070027 Responds to FDIA request for SECY-83-202, "Generic Lessons Learned From Completed Licensing Reviews." to be placed in PDR Forwards SECY-83-202 Document also placed in FDR FELION.J M Division of Rules and Records 83/12/27. ADATO.M Union of Concerned Scientists 1p 22142 256

- --B402070032 SECY-B3-202
 Responds to Commission request for views on generic lessons
 learned from campleted licensing reviews of human factors
 areas
 DIRCKS,W J Office of the Executive Director for Operations
 B3/05/26 7pp 22142 257
- 8402070041 Responds to FDIA request for rept on Price-Anderson Act. mentioned in 830728 issue of Nucleonics Wk NUREO-0957, "Price-Anderson Act - Third Decade," encl W/o encl. FELTON, J M Division of Rules and Records 83/12/28 WILSON, B K International Energy Associates, Ltd 1p 22142 278
- B402070ii4 Forwards "Detailed Control Room Design Review Summary Rept."
 in response to NUREG-0737, Suppl 1
 PETRICK.N A Standardized Nuclear Unit Power Plant System, SLNRC
 B4-00i9 B4/02/02 DENTON, H R Office of Nuclear Reactor
 Regulation, Director ip 22103 081 24X Fiche 50-000.84/02/02.
 B402070ii4
- ---8402070117 "Detailed Control Room Design Review Summary Rept for SNUPFS," in response to Generic Ltr 82-33.NUREG-0737, Suppl 1 * Nuclear Products Co GL-82-33 84/02/02 92pp 22103 003 24X Fiche 50-000,84/02/02.8402070114
- 8402070138 Updates actions taken to satisfy requirements of NUREG-0737, Item II 3 2. "Plant Shielding " Consequences of accidents can be controlled w/o access to radwaste control panel through recently installed remote monitor KOBERIR W Rochester Oas & Electric Corp 84/02/01 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 22100 165. 24X Fiche 50-244.84/02/01,8402070138
- BAO2070152 Forwards presentation matl used at 830923 meeting re BER (ANREG-0853) Gutstanding Issue 1 on transportation accident to close issue M/o encl GEIER. J D Illinois Power Co U-0693 84/01/31 BCHWENCER. A Licensing Branch 2 ip 22103 041 24X Fiche 50-461,84/01/31.8402070152
- B40207015B Forwards response to draft technical evaluation rept recontrol of heavy loads, per 821007 telcon
 BAYNELJP Power Authority of the State of New York
 B4/01/31 VASALLO, ID Departing Reactors Branch 2
 22103 052 24X Fiche: 50-333, 84/01/31, 840207015B
- 8402070203 Forwards BER concluding that requirements of TMI Action Items II K 3 30 & II K 3.31 on small break LOCA analysis met CRUTCHFIELD, D. Operating Reactors Branch 5. LSU5-84-02-003. 84/02/02 LINDER, F. Dairyland Power Cooperative, App. 22102:207 24X Ficher 50-409, 84/02/02, 8402070203
- 8402070225 Informs that locking device installed on dc tie breakers physically prevents engaging breaker Rev 7 to Normal Operating Procedure NOP 2.16-1.per SEP Topic VI-7.C 1, Section 4 24 2 to NUREO-0826 resolves issue COUNSIL N 9 Connecticut Yankee Atomic Power Co. 810767 84/01/17 CRUTOHFIELD) Deperating Reactors Branch 5 2pp. 22101 038. 24X Fiche.50-213.84/01/17,8402070225
- 8402070265 Forwards comments on 840110 draft NUREQ-1070, "Severs Accident Program for Nuclear Power Plant Regulation" RAHE, E P Westinghouse Electric Corp NS-EPR-2880 84/01/30 EISENHUT, D. C Division of Licensing 4pp 22101,323
- B402070285 Forwards listed features re design of new smergency aperations facility consistent w/Buppl 1 to NUREG-0737, Item III.A 1 2 Facility will be completed & operational by 861231.

 HITHERS, B. D. Portland General Electric Co 84/01/27. EIBENHUT, D Q Division of Licensing 2pp 22079.123 24X Fiche 50-344,84/01/27.
- 8402070370 Rev 1 to "Procedure Generation Package for Yankes Emergancy Response Guidelines," in response to NUREG-0737, Suppl 1.
 Event based procedures revised per NUREG-0640, Item I C. 1.
 W/840202 ltr
 KAY, J A Yankes Atomic Electric Co. FYR 84-15 84/01/25.
 CRUTCHFIELD.D. Deparating Reactors Branch 5, 57pp. 22099:125 24X
 Fiche, 50-029, 84/01/25, 8402070370
- 8402070377 Informs of methods to obtain scaling factors for oil & irradiated components waste streams per iOCFR61. Scaling factors for irradiated components taken directly from NUREG-0782.

 ZIMMERMAN, 8 R Caroling Power & Light Co, NLS-84-037 84/02/02 EISENNUT, D 0 Division of Licensing 3pp 22099: 316 24X Fiche: 50-000, 84/02/02, 8402070377

- 8402070380 Forwards rept comparing instrumentation listed in Rev 2 to Reg Quide 1 97 & instrumentation available at facility Revised emergency procedures, developed to meat Suppl 1 to NUECO-0737 requirements, expected to be complete by Aug 1984 NAIER, J E Rochester Gas & Electric Corp 84/01/31 CRUTCHFIELD, D Operating Reactors Branch 5 Spp 22094 354 24X Fish: 50-244, 84/01/31, 8402070380
- 84920700382 Forwards comparison study to evaluate facility design basis compliance to Reg Guide 1 97, per NUREG-0737, Suppl 1 Mods Lientified in encl will be completed by end of second refueling after Jul 1985 for each unit STEWART, W.L. Virginia Electric & Power Co. 053 84/01/31 DENTON: H.R. Office of Nuclear Reactor Regulation, Director EISERNUT, D. & Division of Licensing 49pp 22075 201 24X Fiche 50-280, 84/01/31,8402070382
- BORO70399 Notification of 840213-14 meetings w/util in Seneca.SC to raview implementation of selected NUREG-0737 items SEERMANN.J.F Operating Reactors Branch 4 84/01/27 STOLZ.J.F Operating Reactors Branch 4 3pp 22142 137 24X Fichs.50-269.84/01/27.8402070399
- 8402070430 Responds to 831227 memo requesting NRR comment on IE proposal to updated IE Manual Chapters 1300,1310 & 1320 re NRC incident response by referencing NUREG-0728, Rev 1 & NUREG-0845, Documents acceptable.

 DENTON, HR Office of Nuclear Reactor Regulation, Director 84/01/26 JORDAN, E.L. Division of Emergency Preparadness & Engineering Response (Post 830103) 1p 22141:104
- --8401030405 Discusses rev to IE Manual Chepters 1300.1310 & 1320 re NRC incident response Comments requested by 840201 in order to issue revised manual chapter by Apr 1984 JORDAN, E. L. Director's Office, Office of Inspection and Enforcement, 84712/27 DEYDUNG, R. C. Director's Office, Office of Inspection and Enforcement 2pp 22141 105
- 8402070458 Forwards safety evaluation re Mark I containment long-term program pool dynamic & structural load aspects VASSALLD.D. B. Operating Reactors Branch 2 9L-83-02 84/01/20. PILANT.J M. Nebraska Public Power District 3pp. 22141.350 24X Fichr-50-298.84/01/20.8402070458
- --8402070440 Safety evaluation supporting Mark I containment long-term program pool dynamic loads review.

 B Office of Nuclear Reactor Regulation, Director 84/01/20 2pp 22141 353. 24% Fiche 50-279.84/01/20,8402070458
- --3402070462 Safety evaluation supporting Mark I containment long-term program structural review s Office of Nuclear Reactor Regulation, Director 84/01/20, 3pp 22141,355 24% Fiche, 50-298,84/01/20,8402070458
- --B310050311 BNL-04243

 *Technical Evaluation of Cooper Plant-Unique Analysis Rept,"

 #AMLETIJ.D Brookhaven National Laboratory FIN A-3713.

 83/07/30. NRC No Detailed Affiliation Given. 26pp

 64979,135. 244 Fiche 50-296,84/01/20.8402070458
- 8402070478 Notification of 840215-16 meetings w/util at plant site to discuss planning & implementation of various TMI action plan (AUREG-0737) items. HERNAN.R.W Operating Reactors Branch 4. 84/01/27. BTOLZ, J F Operating Reactors Branch 4. Sup. 22142.076. 24X Fichs.50-302.84/01/27.8402070478
- 8402070481 Addresses concerns stated by W Andrews during B31018 limited appearance before ABLB re potential hazard to Phosnizville potable water supply evacuation plan & handling waste satis. BER & DES entl W/o encis. SCHMENCER.A Licensing Branch 2. 84/01/27 ANDREWS, W Affiliation Not Assigned 4pp 22142 072. 24X Fiche 50-352,84/01/27,8402070481.
- 8402070490 Forwards safety evaluation re NUREG-0737. Item 11. K. 2 17. "Potential for Volding in RCS During Transients." per 801223 & 820426 submittals & Westinghouse Owners Group Rept WOG-57 litem satisfactorily resolved.

 NILLER. J. R. Operating Reactors Branch 3 84/01/24. FAY, C. W. Niscansin Electric Power Co. 10pp. 22141 340 24X Fiche 50-266.84/01/24,8402070490.
- 802070306 Requests submittal, within 30 days, of changes to physical security plan re designation of vital equipment for ECCS & RHS sys & employee screening program. YOUNGBLOOD, B. J. Licensing Branch 1 84/01/27 KDESTER, C. L. Kansas es Electric Co. 3pp 22141-276. 24X Fiche: 50-482, 84/01/27.

- B402080022 Forwards comments & concerns Te Suppl 1 to DES (NUREG-0974) FE operation of facilities
 BOVER.V 8 Philadelphia Electric Co 84/02/06 EISENHUT.D G
 Division of Licensing 11pp 22128 079 24% Fiche 50-352.84/02/06.8402080022
- B4020B0043 Further response to FOIA request for documents re cleanup & decision to close U mill, in Edgemont, SD Forwards App A, B & C documents Review of remaining documents subj to request in progress
 FELTUN, J M Division of Rules and Records 83/11/01 GARBUS, M Frankfurt, Garbus, Klein & Selz 10pp 22169 009
- ---B4020B01B0 NUREO/CP-0021 DRFT
 Draft "Proceedings of Workshop on Radiological Surveys in
 Support of Edgemont Cleanup Action Program," 810121-22,
 Denver.CO
 YOUNG.J A , JACKBON.P O , THOMAS, V W Battelle Memorial Institute,
 Pacific Northwest Laboratory FIN I-2216 PNL-3784 81/04/15
 100pp 22169 160
- --840208004B Ack receipt of Feb 1981 monthly rept for Edgement cleanup action program "Proceedings of Workshop on Radiological Surveys in Support of Edgement Cleanup Action Program" will be issued as NUREG/CR-2083
 EADIE.0 G Uranium Recovery Licensing Branch FIN D-2217
 81/06/01 WOMAN.N A Battelle Memorial Institute, Pacific Northwest Laboratory 2pp 22167 025
- 8402080110 Notification of 840206 & 07 meetings w/util in Russellville, AR to discuss status/schedule & completeness of installation for selected NUREO-0737 items identified in encl agenda VIBSING, @ Operating Reactors Branch 4 84/01/27 STDLZ, J F Operating Reactors Branch 4 84/01/27 STDLZ, J F Fiche 50-313,84/01/27,8402080110
- 8402080114 Forwards rept on issues for which resolution considered complete re integrated plant safety assessment (NUREO-0828) Info provided per 831107 commitment KRICH.R M Consumers Power Co 84/02/02 CRUTCHFIELD.D. Operating Reactors Branch 5 88pp. 22127 270 24X Fiche: 50-155:84/02/02.8402080114
- 8402080169 Forwards "Safety Parameter Display Sys BAR for NUREO-0696 Computer Project, North Anna & Surry Nuclear Power Stations," per 830415 response to NUREO-0737, Suppl 1 STEWART, W. L. Virginia Electric & Power Co. 044. 84/02/08 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 22134, 247. 24X Fiche, 50-000, 84/02/08, 8402080169.
- --8402080181 BAR-VEPCO-005

 "Bafety Parameter Display Bys BAR for NUREG-0694 Computer
 Project.North Anna & Burry Nuclear Power Btations"

 * Energy, Inc 84/01/20 225pp 22134:247 24X
 Fiche 50-000,84/02/08,8402080169
- BAG2080207 Forwards comments re detailed control room design review program plan Util will conduct review that meets intent of Suppl 1 to NUREG-0737 Concern expressed re appropriate identification of operator info in mergency CRUTCHFIELD.D. Operating Reactors Branch 5 LSB5-84-02-016 84/02/06 FIEDELER,P B General Public Utilities GPU Service Corp Spp 22130 115 24X Fiche: 50-219.84/02/06.8402080207
- 8402080215 Forwards response to questions in detailed design description & intermediate sys design description per TMI I tem II F.2 & "RCB Coolant Inventory Trending W/Reactor Coolant Pumps Operating," Encl withheld (ref 10CFR2 790) HUKILL,H D General Public Utilities GFU Service Corp 5211-83-379 84/01/31 BTOLZ,J F. Operating Reactors Brench 4 2pp. 22130 102 24X Fiche: 50-289,84/01/31,8402080215
- 8402080217 Forwards list of onsite emergency organization personnel as of 840101, per 88ER 4 (NUREG-0857).

 VAN BRUNTLE.E. Arizona Public Service Co ANPF-28737-WFG/
 84/01/27 KNIGHTON.O Lifensing Branch 3. 8pp. 22130 104. 24X
 Fiche 50-528.64/01/27,8402080217.
- 8402080836 Advises that proposed Tech Spec revs for NUREG-0737 items, per Generic Ltr 83-36, will be submitted by 840302 ZIMMERMAN, S. R. Caroline fower & Light Co. GL-83-36 84/01/27 VASSALLO, D B. Operating Reactors Branch 2 1p. 22134 234 24X Fiche 50-324, 84/01/27, 8402080234.

- 8402050420 Forwards IE Insp Rept 50-029/83-14 on 930901-j021 & notice of violation STARDSTECKLR Division of Project & Resident Programs 84/01/18 HEIDER, L H Yankee Atomic Electric Ca 200 22084, 298 24X Fiche 50-029,84/01/18,8402050420
- --B402060426 IE Insp Rept 50-027/83-14 on B30701-1021 Violations noted failure to control mat1 released from radiation control area & failure to evaluate recurrent Tech Spec violations & implement effective corrective actions COLLINS, 8 J Region 1, Office of Director 83/11/10 IBpp 22084 302 24X Fiche 50-027,84/01/18,8402060420
- 8402060429 Forwards "LACEWR Detailed Control Room Dasign Review Final Rept." as required by Generic Ltr 82-33 re emergency response capability & committed to in 82040B, 83040B & 1205 ltrs in response to NURSEG-0737. Action Item I D I LINDER, F Dairyland Power Cooperative CL-82-33 84/01/26 EISENNUT.D Q Division of Licensing Ip 22085 165 24X Fiche 50-409, 84/01/26, 8402060429.
- 8402050440 Provides info re THI-1 safety parameter display sys.psr 930804 commitment to provide NRC w/identification of add1 instruments & schedule for implementation in response to Generic Ltr 92-33 & NUREG-0737, Item I D 2 HUKILL, H D General Public Utilities - GPU Service Corp 3211-84-2023 84/02/01 EISEM-MUT.D G Division of Licensing 9pp 22083 092 24X Fiche 30-269,84/02/01,8402060440
- 8402040452 NUREO/CR-3536

 81MULATION OF LOADING CONDITIONS FOR A TYPE A PACKAGE
 CONTAINING AMERICIUM-241 INVOLVED IN AN AIRPLANE CRASH AT
 DETROIT METRO AIRPORT IN JANUARY 1983
 MAXFIELD. O W , WOO. H H Laurence Livermore Laboratory FIN A~0291
 UCRL-53492 84/01/31 Division of Fuel Cycle & Material Safety
 19pp Available at NRC \$3 75 22107 167.
- 8402060457 NUREG/CR-3492 VO1
 HIGH-TEMPERATURE CAS-COQLED REACTOR SAFETY STUDIES FOR THE
 DIVISION OF ACCIDENT EVALUATION GUARTERLY PROGRESS REPORT,
 APRIL 1-JUNE 30, 1983
 BALL, S J CLEVELAND. C , HARRINGTON, R Cak Ridge National
 Laboratory FIN 8-0122 84/01/31 Division of Accident
 Evaluation (Pre 840101) 13pp. 22115 008
- 8402040478 NUREG/CR-3543
 BURVEY OF OPERATING EXPERIENCE FROM LERS TO IDENTIFY AGING
 TREND Progress Report September 1983.
 HURPHY, G A , CASADA, M L. , HOY, H. C Dax Ridge National Laboratory
 FIN 8-0822 ORNL/NSIC-216 84/01/31 Division of Engineering
 Technology 44pp 22110 230
- 8402040484 NUREG/CR-2815
 PROBABILISTIC SAFETY ANALYSIS PROCEDURES GUIDE
 BARI.R.A., PAPAZOGLOU.I.A., BUSLIK.A., Brockhaven National
 Laboratory. BN.-NUREG-51557 B4/01/31 Division of Safety
 Technology. 234pp Available at NRC. 66 50 22109-014
- 8402060489 Forwards SER re NUREG-0737. Item II 8 3: "Post-Accident Bampling Bys " Response to four remaining criteria identified in encl requestes within 30 days VASSALLO,D B Operating Reactors Branch 2 84/01/12 RHODEB. 0 K Niagara Mohawk Power Corp iipp 22110 183 24% Fiche 80-220,84/01/12.8402060489
- 8402060497 NUREG-0748 V03 N12 OPERATING REACTORS LICENSING ACTIONS SUMMARY Data As Of December 31,1983 (Orange Book) # Division of Data Automation & Management Information. 84/01/31. 335pp 22108 039
- 8402040527 NUREG/CR-2000 VO2N12 LICENSEE EVENT REPORT (LER) COMPILATION FOR MONTH OF DECEMBER 1983 * Oak Ridge National Laboratory. ORNL/NCIS-200. 84/01/31 Director's Office 147pp. 22072 143
- 8402070012 Notification of 840209-10 site meetings w/util to review status/schedule & completeness of installation for selected NUREC-0737 Items
 MINER: G Operating Reactors Branch 4 84/01/27. BYOLZ, J F Operating Reactors Branch 4 3pp 22142 275. 24X Fiche 50-312,83/01/27.8402070012
- 8402070027 Responds to FDIA request for SECY-83-202, "Generic Lessons Learned From Completed Licensing Reviews," to be placed in PDR Forwards SECY-83-202, Document also placed in PDR FELTON.J M. Division of Rules and Records. 83/12/27. ADATD.M. Union of Concerned Scientists. ip 22142'256

- --B402070032 SECY-83-202
 Responds to Commission request for views on generic lessons
 learned from completed licensing reviews of human factors
 areas
 PIRCKS.W J (Office of the Executive Director for Operations
 B3/05/26 7pp 22142 257
- 8402070041 Responds to FQIA request for rept on Price-Anderson Act, mentioned in 830728 issue of Nucleanics Hk NUREG-0957, "Price-Anderson Act - Third Decade:" encl W/o encl FELTON, J M Division of Rules and Records 83/12/28 HILSON, F International Energy Associates, Ltd 1p 22142 278
- 8402070114 Forwards "Detailed Control Room Design Review Summary Repl."
 in response to NUREG-0737.Suppl 1
 PETRICK.N A Standardized Nuclear Unit Power Plant System SLMC
 84-0019 84/02/02 DENTON, H R Office of Nuclear Reactor
 Regulation, Director 1p 22103 081 24X Fichs 50-000.84/02/02,
 8402070114
- --8402070117 "Detailed Control Room Design Review Summary Rept for SNUPPS," in response to Generic Ltr 82-33, NUREG-0737, Suppl 1

 * Nuclear Products Co GL-82-33, 84/02/02 92pp. 22103 683 24X Fiche 50-000, 84/02/02, 8402070114
- 840207013B Updates actions taken to satisfy requirements of NUREG-0137. Item II.8 2. "Plant Shielding " Consequences of accidents can be controlled w/o access to radwaste control panel through recently installed remote monitor KOBER.R W Rochester Oas & Electric Corp 84/02/01. CRUTCHF18.8.1 Operating Reactors Branch S 2pp 22100 165 24X Fichs 50-244.84/02/01.8402070138
- 8402070152 Forwards presentation mat1 used at 830723 meeting ra SER (NUREG-0853) Gutstanding Issue 1 on transportation accident to close issue W/o encl GEIER.J D Illinois Power Co U-0673 84/01/31 BCHWENCER, A Licensing Branch 2 ip 22103 041 24X Fichs. 50-461. 84/01/35. 8402070152
- 6402070158 Forwards response to draft technical evaluation rept to control of heavy loads.per 821007 telcon
 BAYNE, J P Power Authority of the State of New York, 4PN-84-06.
 84/01/31 VASSALLO, D D Operating Reactors Branch 2 App.
 22103 052 24X Fiche. 50-333, 84/01/31, 8402070158
- 8402070203 Forwards SER concluding that requirements of TMI Action Items II K 3 30 & II.K 3.31 on small break LOCA analysis met.

 CRUTCHFIELD D Operating Reactors Branch 5 LE05-84-02-003 84/02/02 LINDER, F Dairyland Power Cooperative. 4pp. 22102 207 24X Fiche 50-409, 84/02/02, 8402070203.
- 8402070225 Informs that locking device installed on do tie breakti physically prevents engaging breaker. Rev 7 to Normal Operating Procedure NOP 2.16-1.per SEP Topic VI-7 C 1. Section 4 24 2 to NOREG-0826 resolves issue. CDUNSIL. W 0 Connecticut Yankee Atomic Power Co. B10967, E4/01/1 CRUTCHFIELD. D. Operating Reactors Branch 5. Rpg. 22101.038 21 Fiche. 50-213.84/01/17.8402070225
- 8402070265 Forwards comments on 840110 draft NURE9-1070, "Bevery Accident Program for Nuclear Power Plant Regulation"
 RAHE,E.P Westinghouse Electric Corp. NS-EPR-2880 84/01/30
 ETSENHUT:D 0 Division of Licensing. 4pp. 22101
- 8402070285 Forwards listed features to design of new emergency operations facility consistent w/Suppl 1 to NUREQ-0737, Item III.A i.2 Facility will be completed & operational by 861231.
 HITHERS B D Portland General Electric Co 84/01/27 EISEMENT.O Division of Licensing 2pp. 22099, 123 24X Fiche: 50-344.84/01/28402070285
- B402070370 Rev i to "Procedure Generation Package for Yankee Eaergehi Response Guidelines," in response to NUREO-0737. Suppl 1. Event based procedures revised per NUREO-0660. Item I. C i W/B40202 ltr KAY. J A Yankee Atomic Electric Co FYR B4-15 84/01/23. CRUTCHFIELD. D Operating Reactors Branch 5. 57pp 22099 125 2 Fiche. 50-029.84/01/25.8402070370
- B402070377 Informs of methods to obtain scaling fectors for oil to irradiated components waste streams per 10CFR61. Scaling factors for irradiated components taken directly from NUREQ-07B2 ZIMMERMAN, 8 R. Caroling Power & Light Co. NL6-84-037 B4/02/02 E15ENNUT, D Q Division of Licensing 3pp 22099:316 24X Fiche. 50-000, 84/02/02, 8402070377

- B402070380 Forwards rept comparing instrumentation listed in Rev 2 to Reg Ouide 1 97 & instrumentation available at facility Revised smargency procedures, developed to meet Suppl 1 to NURED-0737 requirements, espected to be complete by Aug 1984 MAIER. J E Rochester Gas & Electric Corp 84/01/31 CRUTCHFIELD, I Operating Reactors Branch 5 8pp 22094 354 24% Ficha 50-244,84/01/31,8402070380 CRUTCHFIELD, D
- B402070382 Forwards comparison study to evaluate facility design basis compliance to Reg Quide 1 97.per NUREO-0737. Suppl 1 Mods identified in encl will be completed by end of second refueling after Jul 1988 for each unit
 BTEMART.M L Virginia Electric & Power Co 053 B4/01/31
 BENTON.H R Defice of Nuclear Reactor Regulation, Director EIBENHUT.D.O Division of Licensing 49pp 22095 201 24X
 Fireb 50-280. B4/01/31.8402070382 Fiche 50-280,84/01/31,8402070382
- 8402070379 Notification of 840213-14 meetings w/util in Seneca, SC to Taview implementation of selected NUREG-0737 items
 BUERMANN, J F Dyerating Reactors Branch 4 84/01/27 STOLZ, J F Operating Reactors Branch 4 3pp 22142 137 24X
 Fiche 50-269,84/01/27,8402070399
- B402070430 Responds to 831227 memo requesting NRR comment on IE proposal to updated IE Manual Chapters 1300, 1310 & 1320 re NRC incident response by referencing NUREO-0728, Rev 1 & NUREO-0845 Documents acceptable DENTON, HR Office of Nuclear Reactor Regulation, Director 84/01/26 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) ip 22141 104
- --8401030405 Discusses rev to IE Manual Chapters 1300,1310 & 1320 re NRC incident response Comments requested by B40201 in order to issue revised manual chapter by Apr 1984 JCRDAN.E L Director's Office, Office of Inspection and Enforcement, 83/12/27 DEYOUND, R C Director's Office of Inspection and Enforcement Zpp 22141 105
- 8402070458 Forwards safety evaluation re Mark I containment long-term program pool dynamic & structural load aspects VASSALLO.D.B. Operating Reactors Branch 2 9L-83-02 84/01/20 FILANT.J M Nabraska Public Pawer District 3pp 22141 350 24X Fiche 50-298-84/01/20:8402070458
- --B402070460 Safety evaluation supporting Mark I containment long-term program gool dynamic loads review

 Office of Nuclear Reactor Regulation, Director 84/01/20 2pp 22141 353 24X Fichs 50-298.84/01/20.8402070458.
- --8402070462 Safety evaluation supporting Mark I containment long-term program structural review + Office of Nuclear Reactor Regulation, Director 84/01/20 3pp 22141 355 24X Fiche 50-278.84/01/20.8402070498
- --9310050311 BNL-04243
- 8402070478 Nobification of 840215-16 meetings w/util at plant site to discuss planning & implementation of various TMI action plan (NUREO-0737) items
 HERNAN,R.W Operating Reactors Branch 4 84/01/27 STOLZ, J.F., Operating Reactors Branch 4 3pp 22142 076 24X
 Fiche 50-302,84/01/27,8402070478
- 8402070481 Addresses concerns stated by W Andrews during 831018 limited appearance before ABLB re-potential hazard to Phoenizville potable water supply, evacuation plan & handling waste matis SER & DES enci W/o encis.

 8CHWENCER. A Licensing Branch 2 84/01/27 ANDREWS, W Affinct Assigned 4pp 22142 072, 24X Fiche 50-352,84/01/27,8402070481 Affiliation
- 8402070490 Forwards safety evaluation re NUREG-0737, Item II K 2 17. "Potential for Voiding in RCS During Transients," per 801223 & 820426 submittals & Westinghouse Owners Group Rept 800-57 Item satisfactorily resolved MILLER, J R Operating Reactors Branch 3. 84/01/24 FAY, C W Misconsin Electric Power Co. 10pp 22141 340 24X Fiche 50-266,84/01/24,8402070490
- B402070506 Requests submittal, within 30 days, of changes to physical security plan re designation of vital equipment for ECCS & RMR sys & employee screening program yourself. B4/01/27 KDESTER, Q. L. Kar Oas & Electric Co 3pp. 22141.296 24X Fiche, 50-482, 84/01/27, B402070506 Kansas

- 8402080022 Forwards comments & concerns Te Suppl 1 to DES (NUREG-0974) re operation of facilities BOVER, V S Philadelphia Electric Co 84/02/06 EISENHUT, D 9 Division of Licensing 11pp 22128 079 24X Fiche 50-352,84/02/06
- 8402080043 Further response to FOIA request for documents re cleanup & decision to close U mill, in Edgemont,8D Forwards App A,R & C documents Review of remaining documents subj to request in progress
 FELTON, J M Division of Rules and Records 83/11/01
 Frankfurt, Garbus, Klein & Selz 10pp 22:69 009 GARBUS, M
- ---8402080180 NUREG/CP-0021 DRFT
 Draft "Proceedings of Workshop on Radiological Surveys
 Support of Edgemont Cleanup Action Program," \$10121-22. Denver, CO Denver.CO YGUNG, J A , JACKSON, P O , THOMAS, V W Battelle Memorial Institute-Pacific Northwest Laboratory FIN B-2216 PNL-3784 Bi/04/15 100pp 22169 160
- --8402080048 Act receipt of Feb 1981 monthly rept for Edgement cleanup action program "Proceedings of Workshop on Radiological Surveys in Support of Edgement Cleanup Action Program" will be issued as NUREG/CR-2083

 EADIE, 0 0 Uranium Recovery Licensing Branch FIN 8-2217

 81/06/01 WDOMAN, A Battelle Memorial Institute, Pacific Northwest Laboratory 2pp 22169 025
- 8402080062 Forwards "Reg Quide 1 97 Review," per NUREG-0737, Suppl 1 Encl study performed to criteria of Reg Quide 1 97, Rev 3 Mods identified in study will be completed by end of second refueling after Jul 1985 BTEWART, W L Virginia Electric & Power Co. 054 84/01/31 DENTON H R Defice of Nuclear Reactor Regulation, Director 2pp 22128 002 24X Fiche 50-338,84/01/31,84020800042
- B4020B0110 Notification of B40206 & O7 meetings w/util in Russellville. AR to discuss status/schedule & completeness of installation for selected NUREG-0737 items identified in encl agenda VISSING. Operating Reactors Branch 4 84/01/27 STOLZ.J F Operating Reactors Branch 4 3pp 22172 324 24X Fiche: 50-313, 84/01/27, 8402080110
- 8402080114 Forwards rept on issues for which resolution considered complete re integrated plant safety assessment (NUREG-0828) Info provided par 83107 commitment RRICH:R M Consumers Power Co 84/02/02 CRUYCHFIELD D Does Reactors Branch 5 GBpp 22127 270 24X Fiche 50-155,84/02/02,8402080114 ent 84/02/02 CRUTCHFIELD.D Opera 270 24% Fiche 50-155,84/02/02,
- 8402080169 Forwards "Safety Parameter Display Bys BAR for NUREQ-0696 Computer Project, North Anna & Surry Nuclear Power Stations." per 830415 response to NUREQ-0737. Suppl 1 STEWART. H L Virginia Electric & Power Go 044 84/02/08 DENION. H R Dffice of Nuclear Reactor Regulation, Director. 2pp 22134 247 24X Fiche 50-000.84/02/08.8402080169
- --84020B0181 BAR-VEPCO-005
 "Safety Parameter Display Sys BAR for NUREO-0696 Computer Project North Anna & Surry Nuclear Power Stations"
 * Energy, Inc 84/01/20 225pp 22134 249 24X
 Fiche 50-000,84/02/08,84020B0169
- 8402080207 Forwards comments to detailed control room design review program plan Util will conduct review that meets intent of Suppl I to NUMEQ-07g7. Concern expressed re appropriate identification of operator info in emergency CRUTCHFIELD, D Operating Reactors Branch 5 LSO5-84-02-016, 84/02/06. FIEDLER, P B. General Public Utilities 079 Service Corp Bpp 22130 115, 24% Fiche. 50-219. 84/02/06.8402080207
- 8402080215 Forwards response to questions in detailed design description & intermediate sys design description per TMI Item II.F.2 & "RCB Goolant Inventory Trending W/Reactor Coplant Pumps Operating " Encl withheld (ref 100FR2 770) MUKILL.H D. General Public Utilities GPU Service Corp 5211-83-377 84/01/31, 8701.2.J F Operating Reactors Branch 4 2pp. 22130 102 24X Fiche 50-289,84/01/31,8402080215
- 8402080217 Forwards list of onsite emergency organization personnel as of 840101, per SSER 4 (NUREO-0857).

 VAN BRUNT, E.E. Arizona Public Service Co. ANPP-28737-WFG/
 84/01/27, KNIGHTON, G. Ličensing Branch 3. 8pp. 22130.104 24x
 Fiche 50-528,84/01/27,8402080217
- 8402080236 Advises that proposed Tech Spec revs for NUREG-0737 itams, per Generic Ltr 83-36, will be submitted by 840302 ZIMMERMAN,8 R Carolina Power & Light Co GL-83-36 84/01/27 VASSALLO,D B Operating Reactors Branch 2 1p 22:34-234 24X Fichs.50-324,84/01/27.8402080236.

- E402080272 Requests relief from NRC 830316 order re addi refueling cycle for installation of noble gas steam effluent monitor, per NUREG-0737, Item II F I i Feasibility of procuring & installing replacement monitor being investigated LUNDVALL.A & Daltimore Gas & Electric Co B4/02/03 MILLER, J R Operating Reactors Branch 3 3pp 22131 282 24X Fiche 50-317,84/02/03,8402080272
- 8402080318 FOLA request for B00508 generic ltr re NUREG-0645 on evaluation of feedwater transients & small break LOCA for Wastinghouse-designed reactors & 711005 rev to NUREG-0800. Ref 4 on Page 15 7 4-6 to be glaced in PDR PEDRO, J NUS Corp CD-15-83-497 83/10/31 Division of Rules and Records ip 22168 220
- B4020B0321 Responds to FOIA request for two categories of documents to be placed in PDR All generic ltrs on file in PDR under specific docket number Forwards NUREC-0B00, Ref 4 on Page 15 7 4-6 Info also available in PDR FELTON. J M Division of Rules and Records 83/12/95 PEDRO. J NUS Corp 19 2216B 221
- 8402080332 Advises that design of atmospheric dump valve accumulators reevaluated.per NUREG-0857 SER, Section 5-4-3 Design meets requirements Info unil be reflected in upcoming amend to FBAR VAN BRUNT, E.E. Arizona Public Service Co. ANPP-28738-WFG/. B4/01/27 KNIGHTON.G Licensing Branch 3 Spp. 22131 216 24X Fiche 50-328.84/01/27.8402080332
- 8402080369 Forwards IE Insp Rept 50-247/83-26 on 831201-840110 No violations noted STAROSTECKI,R Division of Project & Resident Programs 84/01/26 O'TOOLE,J D consolidated Edison Co of New York, Inc 2pp 22130 203 24X Fiche 50-247.84/01/26.8402080369
- --8402080377 IE Insp Rept 50-247/83-24 on 831201-840110 No violations noted Major areas inspected onsits activities & fire protection & mgt changes FCLEY, T. XOLTAYP. NORRHOLM.L. Region 1. Diffice of Director 84/01/24 12pp 22130 205 24X Fiche 50-247.84/01/26.8402080369
- 8402080388 Responds to FOIA request for latest NRC organization charts Rev 2 to NUREG-0325. "US NRC Functional Organization Charts." dtd 830101 available from NRC OPO Sales Program FELTON.J M Division of Rules and Records 83712707 LIFFMAN, M U S Organization Chart Service. Int. 19. 22168 218
- 8402080415 Clarifies NUREO-0737. Item II E 4 i re dedicated hydrogen penetrations Plant design incorporates containment atmosphere dilution sys to control gases following BBE BAYKE, J P Power Authority of the State of New York JPN-84-07 84/02/03 VASSALLO, D 8 Operating Reactors Branch 2 2pp 22130 228 24X Fiche 50-333, 84/02/03, 8402080415
- 8402080431 Partial response to FOIA request for all "Operating Reactor Event Memos" issued in 1981,1982 & 1983 & most current version of each NRR ofc ltr.re technical matters, to be glaced in PDR NRR ofc ltrs listed on app placed in PDR FELTON.J M Division of Rules and Records 83/11/28 SHOLLY, S C Union of Concerned Scientists 3pp 22174 151
- --B205210017 NRR Ofc itr 2.Revision 2 re NUREG-0800 "SRP for Review of SARs for Nuclear Power Plants" Distribution relationship of SRP to regulations & use of SRP in regulatory process discussed
 DENTON H R Office of Nuriser Reactor Regulation. Director
 - DENTON: HR Office of Nuclear Reactor Regulation, Director 82/04/28 Office of Nuclear Reactor Regulation, Director 28pp 22174 155
- 8402080495 Notification of 840203.06 & 07 meetings w/util in Oak Harbor.OH to review status/schedule & completeness of installation for NUREQ-0737 items Agenda for 840207 meeting encl VISSING.O Operating Reactors Branch 4 84/01/27. STOLZ.J F Operating Reactors Branch 4 3pp 22174.043 24X Fiche 50-346.84/01/27.8402080495
- 8402090054 Forwards SER & technical evaluation repts re NRC post-implementation audit review of facility plant-unique analysis rept for Mark I containment long-term program Mode acceptable per NUREG-0661
 ETQLZ, J F Operating Reactors Branch 4 84/01/25 BECKMAN, J T Georgia Power Co 3pp 22188 257 24% Fiche, 50-321, 84/01/25, 8402090054

- --8402090069 Safety evaluation re Mark I containment long-term program pool dynamic loads review Mods acceptable per NURCO-0661

 * Office of Nuclear Reactor Regulation, Director 84/01/25, 2pp 22188 260 24% Fiche 50-321,84/01/25,8402090054.
- --B310050295 BNL-04243

 "Technical Evaluation of Hatch Units 1 & 2 Plant-Unique
 Analysis Repts"

 RANLET, J D , ECONOMOS, C Brookhaven National Laboratory FIN
 A-3713 83/09/30 NRC No Detailed Affiliation Given 25p
 22188 263 24% Fiche 50-321.84/01/25.8402070054
- --8309290297 TER-C5504-329

 "Audit for Mark I Containment Long-Term Program Structural Analysis for Operating Reactors.EI Hatch Nuclear Plant Units 1 & 2," technical evaluation rept SUBRAMONIAN,N, TRIOLO, 5, LE, A K Franklin Institute/Franklin Research Center NRC-03-81-130 TAC 07939 83/09/27 614AM,NRC No Detailed Affiliation Given 44pp 22188 288 24X Fiche 50-321,84/01/25,8402090054
- B402090084 Responds to Generic Ltr 83-36, "NUREG-0737 Tech Spaces"
 Review of listed items indicates that either Tech Spec
 change requests submitted or NRC granted relief
 VANDEWALLE.D. J. Consumers Power Co. QL-83-36 84/02/06.
 CRUICHFIELD.D. Operating Reactors Branch 5 3pp 22160:215 24)
 Fiche 90~153,84/02/06,8402090084
- B402090182 Notifies of intent to submit TMI Tach Specs in Aug 1984 par NURRG-0737 Util involved in extensive effort to address intergranular stress corrosion issue during refueling outage HARRINGTON, W D Boston Edison Co QL-83-36 84/02/03 VASSALLO, D, B Operating Reactors Branch 2 2pp 22158 031 24X Fiche 50-293,84/02/03.8402090182
- 8402090209 Forwards "Program Plan for Detailed Control Room Design Review," in response to Generic Ltr 82-33. "Suppl 1 to NUREO-0737 ~ Requirements for Emergency Response Capability"

 BODKER, J E Gulf States Utilities Co GL-82-33 84/01/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 19 22159 303 24X Fiche 50-458,84/01/31,8402090209
- --8402090213 "Program Plan for Detailed Control Room Design Review * Gulf States Utilities Co 84/01/31 91pp. 22139 304 24x Fiche 50-458,84/01/31,8402090209.
- E402070291 Responds to NUREO-0988 demonstrating that electrical equipment required to perform safety-related function in harsh environ appropriately qualified TUCKER, H B Duke Power Co 64/02/08, DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENSAM, E Q. Licensing Branch 4 294pp 22163 326 24% Fiche, 50-413, 84/02/08, 8402090251
- 8402090264 RIL-138
 Research Info Ltr 138 transmits results of completed
 research task defining proper human actions & responses by
 nuclear power plant control room crews during normal, offnormal & accident conditions W/o stated encl
 MINGGUER B Office of Nuclear Regulatory Research, Director FfR
 B-7491 84/01/31 DENTON.H R Office of Nuclear Reactor
 Regulation, Director 7pp 22188 332
- 8402090323 Forwards Rev 3 to util response to Suppl 1 to NUREO-0737 correcting Section I re physical changes, Section II re surface enhancements & Page 6-7 re emergency procedure training TUCKER, H B Duke Power Co. 84/01/30 DENTON, H R. Office of Nuclear Reactor Regulation, Director ADENBAM, E O. Licensing Branch 4 6pp 22160 232 24X Fiche 50-413,84/01/30.8402090323.
- 8402090325 Forwards response to Bection 2 1 of Generic Ltr 81-07 re NUREO-0612, "Control of Heavy Loads at Nuclear Power Plants" Response to Sections 2 2,2 3 & 2,4 will be grovided 6 months before first Puel load MILLS,L.M Tennessee Valley Authority 9L-81-07. 84/02/06 ADENSAM: E Licensing Branch 4 479pp 22162:001 24X Fiche 50-390,84/02/06,8402090325
- 8402070327 Requests add1 info on 811227 request for changes to Tech Specs re requirements of NUREO-0737. Items II F. 1 i, "Noble Gas Effluent Monitor" & II F 1 2. "Effluent Monitoring of Radiolodines."

 VARQA:S A Operating Reactors Branch 1 84/01/31 0/TDGLE.J D Consolidated Edison Co of New York, Inc 3pp 22177:342 24X Fiche 50-247.84/01/31.8402070327

- 8402090392 Forwards procedures generation package, in response to generic Ltr 82-33. Suppl 1 to NUREG-0737. "Requirements for Eargency Response Capability " Procedures include plant-specific technical guidelines RORRIQUEI.R J Bacramento Municipal Utility District GL-82-33 B4/01/31 STOLZ.J F Operating Reactors Branch 4 3pp 22183 034 24% Fichs 50-000.84/01/31.8402090392
- --840209039A Procedure 32-1106885-00. "Abnormal Transient Operating Quid:lines Arkansas Nuclear One Unit 1 Rancho Seco Sys Comparison "
 BROWNELL, R B Babcock & Wilcox Operating Plants Owners Group QL-82-33 81/07/16 27pp 22183 037 24X Fiche 50-000.84/01/31.
- --BA02070400 Rev 1 to Procedure AF 47. "Emergency Operating Procedures Writers Guide "

 # Bacramento Municipal Utility District OL-82-33 83/09/16 17pp. 22183,063 24X Fiche 50-000,84/01/31.8402090372
- --B402090402 "Verification & Validation Program Description for Rancho Bete Procedures Generation Package Submittal " & Sacramento Municipal Utility District QL-82-33 84/01/31 3pp 22183 080. 24% Fiche 50-000,84/01/31,8402090392
- --8402090407 88-1128639-00
 "Transient Info Document for Loss of Offsits/Onsite
 Power at Rencho Beco."
 HILTUMEN, E. A. Sacramento Municipal Utility District B1/10/08
 167pp 22183 085 24X Fiche 50-000,84/01/31,8402090392.
- --8402090410 Procedure 86-1127307-00. "Abnormal Transient Operating Quidelines:Excessive Main Feedwater Event Transient Info Document "
 BROWNELL.R.B. Babcock & Hilcox Operating Flants Owners Group 81/09/03 76pp 22183,252. 24X Fiche 50-000,84/01/31,8402090392
- --8402090412 Procedure 86-1127426-00: "Abnormal Transient Operatine Quidelines for Loss of Feedwater Transient Info Document "
 KW-RE H Babcock & Wilcox Operating Plants Owners Group.
 81/08/20 29pp. 22183,328 24X Fiche 50-000.84/01/31,8402090392
- --8402090418 86-1127102-00
 "Transisht Info Document for Small Steam Line Break Event"
 SCHNENN, A. S. Babcock & Wilcox Operating Plants Owners Group
 81/08/17 30pp. 22183.357 24X Fichs.50-000.84/01/31,8402090392
- --6402070425 Procedure 74-1127469-00.Vol 1, "Abnormal Transient Operating Quidelines, Part I Procedural Quidelines "
 KELLY, J. J. Babcock & Wilcox Co. BMNP-20004 82/12/15 124pp 22184 024, 24X Fiche 50-000, 84/01/31, 84020
- ---8402070430 Procedure 74-1127469-00, Vol 1, "Abnormal Transient berating Guidelines, Part II: Fundamentals of Reactor Centrol for Abnormal Transients" * Babtock & Hilcox Co B2/10/08. 311pp. 22184 148. 24X Fiche: 50-000, 84/01/31, 8402070392
- 8402090404 FDIA request for four categories of documents re NUREQ-0103, *STB for B&H PMRs." STB for C-E & Westinghouse PMRs.Reg Oulds 1 43 & NUREO 7579B7 (NUREO-0800), "NRC SRP "ADDEN'T.J. Kaye, Scholer, Fierman, Hays & Handler 83/12/06, NORRY.F. 0. Office of Administration 2pp. 22173 001.
- 840209040B Partial response to FOIA request for four categories of decuments re MUREO-75/087 (NUREO-0800), "SRP for Review of SARs for Nuclear Flants." Review of remaining documents incomplate Forwards App A documents.

 FELTON. J. M Division of Roles and Records. 83/12/30, MADDEN. T. J. Kaya. Scholer. Fistman, Hays & Handler. 4pp. 22193'003. 24X Fiche: 50-000.83/12/30.8402090408.
- --9201230042 Discusses licensee question as to NRC policy re whether or not licenses could voluntarily enter into conditions which would lead to operation in degraded mode as permitted Tech Spec action statements.

 NARTIN.R A Operating Reactors Branch 3, 81/12/29 CLARK,R.A. Operating Reactors Branch 3, 81/12/29 CLARK,R.A.

- --8104290054 Forwards revised Section 5 2 5 of SRP Revision clarifies SRP by amend of existing acceptance criteria areas of review & procedures & incorporation of implementation section W/o encis
 PARR.O D Auxiliary Systems Branch 81/04/21 SKOVHOLT.D J Licensing Guidance Branch 1p 22193 244
- --8402090441 Forwards revised Section 5 2 5 of SRP, NUREO-0800 (formerly NUREO-75/087) Publication for comment unwarranted since changes either previously approved or clearly necessary Title page encl
 MURLEY.T E Division of Safety Technology ERNST, M L Assistant Director for Technology Review BAER.R L Safety Program Evaluation Branch 61/05/28 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22193 247
- --840209043B Describes safeguards requirements for safety sys prior to changing modes No requirements specifically address subj NUREG-090B, "Acceptance Criteria for Evaluation of Reactor Security Plant," contains guidelines for major maint MCPEEK.E W Division of Licensing 82/11/07, MIRA9LIA,F J Assistant Director for Safety Assessment 2pp 22193 244
- --8402100182 Forwards FS Controll 761129 memo re inconsistency in unidentified sys leak rates Recommends inconsistency in max primary sys leak rates for BWRs be referred to NRR for Tech Spec resolution.

 LONG, FJ Region 2. Atlanta, Office of the Director IEB-74-10B 76/12/10 SEVENTI, W Office of Inspection & Enforcement, Office of the Director ip 22193 028
- --B402100187 Identifies inconsistency in unidentified max primary systems rate, NUREG-75/067 cited as guidance Recommends inconsistency be referred to NRR for resolution CANTRELL.F 8 Region 2, Atlanta, Office of the Director 76/11/23 LONG.F J. Region 3. Chicago. Office of the Director in 22193 029 24X Fiche 50-000,83/12/30.8402090408
- --BI04290054 Forwards revised Bection 5 2 5 of ERP Revision clarifies SRP by amend of existing acceptance criteria areas of review & pracedures & incorporation of implementation section M/o encls PARR, Q D Auxiliary Systems Branch, B1/04/21 SKOVHOLT, D. J Licensing Guidance Branch ip 22193 246
- --B402090441 Forwards revised Section 5 2 5 of SRF.NUREO-0800 (formerly NUREO-75/087) Publication for comment unwarranted since changes either previously approved or clearly necessary Title page encl
 MURLEY.T.E. Division of Safety Technology. ERNBT.M L. Assistant
 Director for Technology Review EAER.R.L. Safety Program
 Evaluation Branch B1/05/28 DENTON.H R. Office of Nuclear
 Reactor Regulation, Director 2pp 22193:247
- 8402090439 Forwards SER on responses to Generic Ltr 82-28 & NUREG-0737, Item II F 2 re inadequate core cooling instrumentation (ICCI) & request for add) info re conformance of components in ICCI sys to NUREG design requirements W/o encl MILLER. J R Operating Reactors Branch 3 GL-82-28, 84/02/02 WITHERS B D Portland General Electric Co 2pp 22177:316 24X Fiche 50-344,84/02/02,8402090439.
- 8402100177 Discusses time at which hydrogen monitoring is initiated Intent of TMI Item II F.1(6) is to ensure timely hydrogen monitoring in event of core uncovery during LOCA Definition for onset of LOCA undefinable OUCHALL T Georgia Power Co NED 84-047. 84/02/03 STOLZ, J F Operating Reactors Branch 4 2pp 22182:181 24X Fiche 50-321.84/02/03.8402100179
- 8402100180 Responds to 831216 request for add1 info re proposed inadequate core cooling (ICC) instrumentation per TMI Item II F. 2. Meeting scheduled for 840301 in Bethesde. MD to discuss technical issues re ICC instrumentation CAREY, J J Duquesne Light Co G.—82-28 84/02/03, VARGA, S A Operating Reactors Branch i p 22182, 183 24X Fiche: 50-334, 84/02/03, 8402100180
- BA02100183 Forwards info re frequency of calibr, testing & training of operators for post-accident sampling sys, per 831216 BSER identifying open items in TMI Item It.B. 3

 STEMART, W.L. Virginia Electric & Power Co. 797. 84/02/03

 DENION, H.R. Office of Nuclear Reactor Regulation, Director. App. 22182, 184 24% Fiche 50-000, 84/02/03, 8402100183
- 8402100197 Addresses concern identified in NUREO-0824, "Integrated Plant Bafety Assessment:" re electrical isolation in safety-related sys.per SEP Topic VII-1 A. Probability of hot shorts of plus/minus 125-volts do or ac extremely remote COUNBIL, W. G. Northeast Nuclear Energy Co. (subs of Northeast Utilities). COUNBIL, W. G. Northeast Utilities. 811007 84/01/31 CRUTCHFIELD. D. Operating Reactors Branch 5. 2pp. 22182:191 24% Fichs: 50-245,84/01/31,8402100197

- 8402100246 Forwards info in response to NRC 820902 ltr re NUREG-0737. Item II D 3, "Post-Accident Sampling Sys " W/two oversize drawings Aperture cards are available in PDR NOBER R W Rachester Gas & Electric Corp 84/02/06 CRUTCHFIELD, D Operating Reactors Branch 5 64pp 22204 327 24X Fische 30-244.84/02/06.8402100246
- --8402100252 Rev 1 to Procedure EWR 2606, "Design Criteria Ginna Station Post-Accident Sampling Sys Implementation " MAMBRETTI.C J. DAVIS.R T Rochester Gas & Electric Corp 82/07/20 28pp 22209 043 24X Fiche 30-244.84/02/06.8402100246
- --8402100256 Rev O to Procedure PC-25 4. "Ouidance for Interpreting Post-Accident Sampling Results to Estimate Reactor Core Damage "
 * Rochester Oas % Electric Corp 83/03/16 9pp 22205 071 24X Fiche 50-244.84/02/06.8402100246
- 8402100288 Discusses & forwards Div of Waste Mgt rept. "BWIP Site Technical Position 1 i Hydrogeologic Testing Strategy for BWIP Site "Testing gragram should begin by testing Grande Ronde formation
 WRIOHT.R J Repository Projects Branch (Post 831001) 00667
 84/01/11 OLSON.D L Energy, Dept of 7pp 22205 299
- B402100388 Transcript of Commission B40202 briefing in Washington.DC re quarterly progress on safety goal evaluation rept & draft PRA document Pp 1-70 Supporting documentation encl * Commissioners B4/02/02 107pp 22211 001
- 8402100442 NUREQ-0580 V12 N12
 REGULATORY LICENSING STATUS SUMMARY REPORT Data As Of
 December 31.1983 (Blue Book)
 * Management Information Branch 84/01/31 60pp 22213 049
- 8402100461 Responds to FOIA request for Governor Janklow 931019 ltr & NRC response Forwards ltrs FELTON.JM Division of Rules and Records 83/11/30 PAY.D Affiliation Not Assigned 1p 22212 252
- --8402100465 Forwards response to 831019 request for info re low level radwaste compact formation NVREO-0962.describing state role in radwaste regulation per Low Level Radwaste Policy Act of 1980, encl W/o NVREO KERR.6 W Office of State Programs, Director 83/11/16
 JANKLOW,W J South Dakota, State of 5pp 22212 256
- B402100499 NUREQ/CP-0050
 PROCEEDINGS OF THE INTERNATIONAL BETA DOSIMETRY BYMPOSIUM
 Held at Washington, DC Feburary 15-18,1983
 * Office of Nuclear Regulatory Research, Director * Energy, Dept
 of * Health Physics Bociety 84/01/31 670pp Available at NRC
 \$12 00 22209 001
- 8402100502 NUREQ-0847 502
 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF WATTS
 BAR NUCLEAR PLANT.UNITS 1 AND 2 Docket Nos. 50-370 And
 50-391 (Tennessee Valley Authority)
 + Division of Licensing 84/01/31 37pp Available at NRC 3 75
 22213 109 24X Fiche 30-370.84/01/31.8402100502.
- B402130001 Requests exception to ANSI-B30 2-1976 Section 2-2 2 2 b(3)
 "Rated Load Test," per S21116 1tr re control of heavy
 loads Requirements unnecessary & too stringent. Response
 requested prior to Mar 1984 Unit 2 outsige
 ZIMMERMAN.S R Carolina Power & Light Co NLS-B4-042. B4/02/06
 VASSALLO.D B Operating Reactors Branch 2 2pp. 22204 090 24X
 Fiche: 50-324.84/02/06,8402130001
- 8402130013 Responds to FQIA request for two categories of documents re IDCOR program Forwards App A & D documents, Documents placed in PDR FELTON.J H Division of Rules and Records 83/12/21 SHOLLY, B, C Union of Concerned Scientists 5pp 22282 004 24X Fiche 50-000.85/12/21,8402130013.
- --8312170055 Summarizes comments re outline for source term rept, NUREO-0956 Chapter IV should include results of Containment Bahavior Group & Containment Loading Group activities. Section on generalization of results should be added NODNAN, V S Equipment Qualification Branch 83/11/28 VOLLMER, R H Division of Engineering 3pp. 22282 173
- --B312190179 Forwards revised outline incorporating comments received to date for NUREG-0936, "Reassessment of Accident Bource Term Evaluation Methods & Assumptions." Div of Risk Analysis assistance required Production schedule encl
 BERNEHO,R M Accident Bource Term Program Office 63/11/02 SARP Review Group 4pp. 22282-176

- 8402130015 Requests extension of 2 wks to provide final response to Sections 2 2 1 & 3 2 of Generic Ltr 83-28.per 831104 preliminary response due to activities associated w/upcoming Unit 1 refueling outage & Suppl 1 to NURED-0737 CLAYTON.F L Alabama Power Co QL-83-28 84/02/06 VARQA, 8 A Office of Nuclear Reactor Regulation, Director 1p 22204,086 24% Fiche 80-348,84/02/06,8402130015
- 8402130117 NUREG/CR-3478
 REVIEW OF IMPACT OF COPPER RELEASED INTO FRESHWATER
 ENVIRONS
 HARRISDN,F L Lawrence Livermore Laboratory FIN A-0119.
 UCRL-32488 84/01/31 Division of Health, Siting & Maste
 Management 98pp 22213 198
- B402130153 Forwards Rev 1 to position paper on Reg Ouide 1 97 & response to NUREO-0737, Suppl 1,Reg Ouide 1 97 resemble response facilities Rev supersedes 830930 submittal
 ZIMMERMAN, B R Caralina Power & Light Co NLB-84-025 84/02/01 VASSALLO, D B Operating Reactors Branch 2 1p. 22199 286 248 Fiche 30-324,84/02/01,8402130153
- 8402130175 Forwards add1 info on potential finding Repts 027.050 & 065, per SSER 5 (NUREO-0857), Section 17 7 3 re independent QA evaluation

 VAN BRUNT, E E Arizona Public Service Co ANPP-28797-WFG/
 84/02/06 KNIGHTON, C Licensing Branch 3 5pp 22204 134 24% Fiche 50-528, 64/02/06, 8402130175
- 8402130228 Forwards responses to draft technical evaluation rept open items re-control of heavy loads.per 831103 ltr Crane operators trained per ANSI 830 2-1976 requirements. Installation of new fuel storage racks in progress. ZIMMERMAN, S. R. Carolina Power & Light Co NLS-84-002 84/02/03 VASSALLO, D. B. Operating Reactors Branch 2, 10pp 22200, 121, 24% Fiche 50-324.84/02/03.8402130228
- 8402130234 Suppls 830415 & 0824 responses to Generic Ltr 83-33 re Suppl 1 to NUREO-0737 Control room design review program plan will be submitted by 841025 Schedule for implementation of Rev 2 to Reg Guide 1 97 will be submitted by 841201 BAYNEJJ P. Power Authority of the 8tate of New York QL-82-33 83/11/15 VASSALLO, D B. Operating Reactors Branch 2 3pp. 22204 285 24X Fiche 50-333,83/11/15,8402130234
- B402130304 Forwards comments on draft Suppl 1 to programmatic EIS (NUREQ-0683) rs decontamination & disposal of radioactive wastes resulting from 790328 accident.

 MOLHOLT, B Bryn Maur College 84/02/08 SNYDER, BJ, TMI Program Office 13pp. 22204 013 24X Fiche 50-320, B4/02/08, 8402130304.
- 8402130328 Documents addl info provided on 840104 re NUREQ-0737. Item II F i 4, II F. i 5 k II F i 6 concerning containment pressure, water level & hydrogen monitors, respectively ZIMMERMAN, 8 R. Carolina Power & Light Co. NLS-84-033 84/02/03 VARQA, 8 A. Operating Reactors Branch i, 2pp. 22177; i12. 24X Fiche 50-261, 84/02/03, 8402130329
- 8402130336 Forwards 43 revised oversize elementary diagrams reflecting implementation of NUREG-0737.TMI Action Plan Items II.K.3 13.II.K.3 15 & II.K.3 15 Info closes out BER Confirmatory Issues 28.45 & 46 Aperture cards in PDR GEIER.J D. Illinois Power Co. U-0689 84/02/09. SCHWENCER.A Licensing Branch 2 3pp. 22217 001. 24X Fiche. 50-461.84/02/09.
- 8402130375 Forwards safety evaluation on NUREO-0737, Item II K. 2 17 repotential for voiding in RCB anticipated transients Issue of steam formation in RCB of Westinghouse plants adequately addressed. Item resolved MILLER, J R. Operating Reactors Branch 3 84/01/24 STEWART, H. L. Virginia Electric & Power Co 7pp. 22216, 190. 24X Fichs 30-338, 84/01/24, 8402130375
- 8402130401 Responds to 831117 ltr re protection of safeguards info at util corporate records ctr Protection described, acceptable in accordance w/requirements of 10CFR73.21 & NUREO-0774
 KNIGHTON.6 M. Licensing Branch 3. 84/02/02. BASKIN.K. Southern California Edison Co. 4pp. 22216:181. 24X Fiche: 50-206.84/02/02, 8402130401
- 8402130412 "TMI Action Plan Tracking Sys." * Office of Resource Management, Director 83/08/31, 150pp. 22214:001
- B402130417 Forwards Procedure AP/1/A/5500/31, "Estimate of Failed Fuel Based on I-131 Concentration," in response to NRC request to complete review of NVREO-0737; Item II. B. 3 TUCKER: H. B., Duke Power Co. TM 2. B. 3 B4/02/07 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADEXISAN.E. Q. Licensing Branch 4. 7pp 22201:281 24X Fiche 50-413,84/02/07,8402130417.

- --8402130422 Procedure AP/1/A/5500/31, "Estimate of Failed Fuel Based on
- 8402130451 Requests review of enc1 EG&G technical evaluation rept. "Conformance to NRR Generic Ltr 82-14, St Lucie Plant, Units 1 & 2 " Response addressing deviations for Unit 1 requested within 30 days of itr receipt MILLER, J R Operating Reactors Branch 3 GL-82-14 84/01/30 MILLIMS, J W Florida Power & Light Co 2pp 22216 107 24X Fiche 50-335, 84/01/30,8402130451
- -- 9402130457 EQQ-EA-6432 DRFT O2130457 EGG-EA-6432 URFT "Conformance to NRR Oaneric Ltr 82-16.8t Lucie Plant, Units 1 & 2," preliminary rept VANDERBEEK, R EG&G, Inc FIN A-6600 GL-82-16 83/10/31 - No Detailed Affiliation Given 20pp 22216 107 24X Fiche 50-335,84/01/30,8402130451
- B4021304AB Responds to Generic Ltr 83-37 re Tech Spec changes for various NUREG-0737 items Dutstanding items listed Tech Spec change scheduled for submittal on 840518 JGHMSON, B. D. Consumers Power Co 6L-83-37 84/02/08 CRUTCHFIELD, D. Operating Reactors Branch 5 2pp 22201 149 Fiche 50-255,84/02/08,8402130448
- 8402130557 Forwards add1 info re AO rept to Congress for Fourth Guarter CVB3 & input to 831230 memo DENTON, HP R. Office of Nuclear Reactor Regulation, Director 84/01/25 HELIENES.C J Director's Office 5pp 22213 317.
- --B3122901&1 Forwards Core Performance Branch SER input re Cycle & rained Proposed changes acceptable
 RUBENSTEIN-L.8. Assistant Director for Core & Plant Systems. To
 49798 B3/12/19 LAINAB.Q C Assistant Director for Operating
 Reactors. 11pp 22213-330. Reactors. 11pp
- --8401110467 Requests input, described in encl.by 840113, to Fourth Quarter CYBS AO rept to Congress FÆLTEMES,C.J. Director's Office 83/12/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 12pp 22213 341
- E402130577 Forwards summary rept of toxic monitor spurious actuations & description of measures taken to resolve problems w/emergency filtration train sys, installed per NUREO-0737, Itse III, D. 3 4.

 LARSON.C E Northern States Power Co 84/02/01, KEPPLER, J G Region 3, Office of Director, 2pp 22201 175 24X
 Fiche 50-263,84/02/01,8402130577
- 8402130605 Forwards request for addl info re radiological assessment. IUXIIVOUD FORMARDS REQUEST for add1 info re radiological assessme to complete review of draft SER Response required by 840515 in order to meet present licensing schedule. BCHMENCER: A Licensing Branch 2 84/02/02, RHODE: 0 K, Niegar Notawk Power Corp. 3pp 22214:306 24X Fiche 50-410,84/02/02,8492130605
- 8402130612 NUREQ-1050 DRFT
 PROBABILIBTIC RISK ABBESSMENT (PRA) BTATUS REPORT AND GUIDANCE FOR REGULATORY APPLICATION. Draft Report For Macent, Division of Risk Analysis, 84/02/29 337pp, 22215-001.
- 8402190625 Forwards for review, Rev 1 to draft NUREO-0869 re Unresolved Eafety Issue A-43. "Containment Emergency Sump Performance "Comments requested by 840229.
 SERKIZ, A, W. Generic Issues Branch 84/02/03 HECKER, G. Alden Research Laboratory FORSE, L. Affiliation Not Assigned, SWIFT, W. Creere, Inc. 9099 22214.144.
- B402140135 Responds to NUREQ-0737, Suppl 1 re requirements for emergency response capabilities/emergency operations facilities Util intends to revise Section 7.1 of emergency plan whaddition of listed wording.

 COUNSIL, W 0 Northeast Utilities A03657 84/02/03, EISENHUT, D 0. Division of Licensing 2pp, 22219 038, 24X Fiche, 50-000, 84/02/03, 8402140145 8402140135
- 8402140205 Forwards response to Generic Ltr 83-36, requesting licensees to submit Tech Specs or schedule for NUREG-0737 items scheduled after 811231 All appropriate Tech Spec amend requests will be submitted by 840815
 BARNESI,P.L. Commonwealth Edison Co QL-83-36, 84/02/09, DENTON; HR Office of Nuclear Reactor Regulation, Director 9pp. 22227:341, 24% Fiche: 50-000, 84/02/09, 8402140205
- 8402140228 Forwards IE Insp Rept 50-344/83-33 on 831212-14. No noncompliance noted
 HENGLAMSKI,F A. Region 5, Office of Director. 84/01/27,
 HITHERS,B,D. Partiand general Electric Co 1p. 22227:148, 24X
 Fiche.50-344,84/01/27,8402140228.

- -8402140233 IE Insp Rept 50-344/83-33 on 831212-16 No noncompliance or deviations noted Major areas inspected implementation of NUMEG-0737, Action Items II B 3 & II F I CILLIS.N. WENSLAWSKI, F A Region 5. Office of Director 84/01/27 9pp 22227 149 24X Fichs 50-344.84/01/27,8402140228
- 8402140242 Ack receipt of 831214 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-335/83-34 & 50-387/83-62 Implementation of corrective actions will be examined during future insps
 DANCE: H C Division of Project & Resident Programs 84/01/18 WILLIAMS.J W Floride Fower & Light Co ip 22220 285 24X Fiche 50-335.84/01/18.8402140242
- --B402140303 IE Insp Repts 50-335/83-34 & 50-389/83-62 on 830911-1010 Noncompliance noted failure to implement procedures re valves locks & switches ELROD, 8 A , BIBB.H E Region 2. Office of Director LANDIS, K Division of Project & Resident Programs 50-389/83-62 83/11 Spp 22220 293 24X Fiche 50-335.84/01/18,8402140242 83/11/10
- 8402140328 Submits Phase II implementation schedule for control of heavy load review.per 831230 request Review assentially complete Rept will be submitted by 840307 HHITTIER.0 D Maine Yankee Atomic Power Co MN-84-25 84/02/08 MILLER.U R Operating Reactors Branch 3 1p 22230 320 24X Fiche 50-309,84/02/08,8402140328 84/02/08
- 8402140335 Notifies that util will respond to Generic Ltr 83-36 re NUREO-0737 Tech Specs by 940531 Delay necessary to accommodate manpower requirements associated w/upcoming Accommodate manpower requirements associated w/opcoming refueling outage LEMPGES, T E Niagara Mohawk Power Corp QL-83-36 84/02/ VASSALLO, D B Operating Reactors Branch 2 1p 22227 144 Fiche 50-220, 84/02/10,8402140335
- 840214033B Forwards changes per Buppl I to NUREC-0737 to implementation schedule for historical earthquake data solutions to be completed by end of first refueling outage.

 TUCKER, H B Duke Power Co 84/02/07 DENION, H R Office of Nuclear Reactor Regulation, Director ADENBAN, E O Licensing Branch 4 App 22220 234 24X Fishe 50-413, 84/02/07.8402140338
- 24X Fiche 50-261,84/02/07,8402140377
- 8402140384 Forwards summary of 840113 meeting in Region II ofc re emergency protective actions required by NUREO-0454 & clarified by IE Info Notice 83-28 VERRELLI,D M Division of Project & Resident Programs 84/01/2 FARRIS.H 0 Tennessee Valley Authority 4pp 22220.042 24X Fiche:50-000,84/01/26.8402140384 84/01/26
- B402140412 Advises that revs to Tech Specs not required, per review of request re completion of mods required for NUREG-0737 Items II.B i.II B.3.11 E.1 i.II F 1.II.F 2 & III D 3 4 (Generic Lira 83-37 & 83-36).

 WAREHBOURG, D W Public Service Co of Colorado P-84046 84/02/0' EIBENHUY, D G. Division of Licensing. 8pp 22275 122 24% Fiche 50-267, 84/02/09, 8402140412
 - 84/02/09
- --8309230347 Completes review of responses to questions re NUREQ-0737, Item III D 3 4, "Control Room Habitability " Criteria met Item closed MADSEN, G L. Region 4, Office of Director 83/09/08 LEE, O R Public Service Co. of Colorado. 29p. 22275. 220 24X Fiche, 50-267, 84/02/09, 8402140412
- 8402140470 Forwards inlet & discharge piping info omitted in 831026 ltr in response to SER. Section 3 9 3 2 & NUREG-0737, Item II.D. i 11.D.1 TUCKER, H B Duke Power Co 84/02/03 DENTON, H R Office of Nuclear Reactor Regulation, Director, ADENBAR, E G Licensing Branch 4 3pp. 22226-207 24X Fiche: 50-413,84/02/03,8402140470
- 8402140476 Advises that Đế small break LUCA model described in NEDD-20366.used in facility LOCA analysis per NURE9-0737. Item II.K.3 30/31.in response to 831228 request. NCGAUGHY, R W I IDWa Electric Light & Power Co. NC-84-0515 84/02/08 DENION, H Office of Nuclear Reactor Regulation, Director ip. 22226-214 24X Fichs 50-331.84/02/08.8402140476

- 8402140482 Responds to 840202 questions re Chicago Tribune article on safety problems Insp findings published in NUREO-0400. Vol 4.Number 2 DIRCKS, W J Office of the Executive Director for Operations 84/02/08 PALLADING.N J Commissioners 3pp 22281 352
- 8402140525 Recommends formation of multidisciplinary group for initial assessment of potential safety problems associated w/locked doors & barriers in nuclear power plants EISENHUT.D & Division of Licensing 84/01/30 THOMPSON, H L Division of Human Factors Safety 3pp 22258 234
- --B401i30140 Notifies of steps taken to address potential safety problems associated w/locked doors & barriers in plants, identified by Committee to Review Safeguards Requirements at Power Reactors in NUREO-0992
 EISENHUT.D Q Division of Licensing 83/12/22 DENTON.H R
 Office of Nuclear Reactor Regulation, Director 4pp 22258 254
- --8402010286 Responds to 831222 memo re steps taken to resolve potential safety problem associated u/locked doors & barriers in nuclear reactors Multi-disciplinary group should be established to make initial assessment DENTON.H R Office of Nuclear Reactor Regulation, Director 84/01/16 EISENHUT,D G Division of Licensing 2pp 22258 263
- 8402140606 Informs that info re NUREG-0737, Items 11 F 1 4-6, not yet received, per 820406 request Response to encl requests for addl info or schedule for response requested within 30 days of itr receipt VASSALLO, D 8 Operating Reactors Branch 2 84/02/02 UTLEY, E Carolina Power & Light Co 17pp 22236 300 24% Fiche 50-324, 84/02/02, 8402140606
- B402130020 Suppl I to application for amend to Licenses DPR-32 & DPR-37, adding description of post-accident sampling program to Section 4 re administrative controls in fullfillment of regularments of NURGE-0737, Items II F I 2 & II B 3 STEWART, W L Virginia Electric & Power Co GL-83-37 84/02/09 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, S A Operating Reactors Branch I 3pp 22249 310 24X Fiche 50-280, 84/02/09, 8402150020
- --8402150022 Proposed Tech Spec change adding description of postaccident sampling program to Section & re administrative controls in fullfillment of requirements of NUREG-0737. Items II F I & II B 3 * Virginia Electric & Power Co 84/02/09 App 22249 313 24X Fiche 50-280,84/02/09,8402150020
- 8402150176 Forwards data for Const Status Rept (NUREG-0300) for Fourth Guarter 1983 MCCAFFREY,B R Long Island Lighting Co SNRC-1010 84/01/19 Management Information Branch 4pp 22249 147, 24X Fiche 50-322,84/01/19,8402150176
- 8402150267 Supple 830603 application to amend Licenses NPF-4 & NPF-7, adding description of post-accident sampling program to Section 6 re administrative controls per NUREG-0737, Items II F 12 & II B 3
 STEMART, H L Virginia Electric & Power Co &62A 84/02/07 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 2pp 22250.285. 24X Fiche 50-338.84/02/07,8402150267
- ---B402150279 Proposed Tech Spec changes adding description of post-accident sampling program to Section 6 re administrative controls.per MJREQ-07037.ltems II F 1.2 & II B 3
 # Virginia Electric & Power Co B4/02/09 5pp 22250 267. 24X Fiche 50-338.84/02/09.8402150267
- 8402150269 Ack receipt of 831214 & 840127 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 30-366/89-29

 LEWIG.R C Division of Project & Resident Programs 84/02/06

 KELLY.R J Georgia Power Co. ip 22250 052. 24X

 Fiche 50-366.84/02/06.8402150269

- B4021503i1 Provides clarification re special lifting devices for control of heavy loads.per NUREG-0612 Phase I requirements of NUREG-0612 requested to be closed out in hext SEER CODK.X W Louisians Power & Light Co W3PB3-3671 84/02/09. KNIGHTON.6 W Licensing Branch 3 3pp 22250 183 24% Fiche 50-382.84/02/09.8402150311
- --8402150313 Suppl 1 to "Response to NRC Draft Technical Evaluation Rept for Waterford 3 SES on Control of Heavy Loads " # Louisiana Power & Light Co 63/11/30 9pp 22250.186 24X Fishe 50-392.84/02/09.8402150311
- 8402150317 Forwards presentation matl used at 830923 meeting re BER (NUREO-0853) Gutstanding Issue i on transportation accidents, inadvertently omitted from 840131 ltr GEIER, J D Illinois Power Co U-0694, 84/02/08 SCHWENCER, A Licensing Branch 2 ip 22251 050 24X Fiche 50-461,84/02/08,8402150317
- 8402150369 Forwards "Degraded Core Accident Hydrogen Control Program," quarterly status rept for quarter ending 830930, in response to request in SEER 4 (NUREG-0831)

 DALE, L F Mississippi Power & Light Co AECM-84/0099 84/02/09

 DENTON, H R Office of Nuclear Reactor Regulation, Director 11pp 22242 121 244 Fichs 50-416,84/02/09,8402150359
- 8402150424 Forwards SSER 4 (NUREG-0887) re facility operation W/o encl YDUNOBLODD, B J Licensing Branch 1 84/02/08 EDELMAN, M P. Cleveland Electric Illuminating Co 2pp 22263 312 24X Fiche 50-440.84/02/08.8402150424
- 8402150430 Forwards "Control of Heavy Loads at Nuclear Power Plants. Limerick Generating Station Units 1 & 2 (Phase II)," draft technical evaluation rept Response to remaining concerns identified in Sections 2 3 1 C, 2 3 2 C & 2 3 3 C requested. SCHWENCER.A Liconsing Branch 2 FIN A-6457 84/02/06 BAWER.E 9. Philadelphia Electric C 3pp 22263 276 24X Fichs 50-352.84/02/06,8402150430
- --8402150435 "Control of Heavy Loads at Nuclear Power Plants, Limerick Generating Station Units 1 & 2 (Phase II)," draft technical evaluation rept FRIEDERICHS, 8, STICKLEY, TH E080, Inc. FIN A-6457. 83/10/30 NRC No Detailed Affiliation Given 29pp 22263 279 24X Fiche 50-352,84/02/06,8402150430
- 8402150496 NUREG/BR-0075 NRC FIELD POLICY MANUAL — JANUARARY 1984. * Office of the Executive Director for Operations. 84/01/31 11pp
- 8402160003 Third partial response to FDIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILK.8 J. Office of the Secretary of the Commission 83/12/14 Public Document Branch ip 22281.023. 24% Fiche 50-000.83/12/14.8402160003
- --B402160212 Discusses SECY-82-171 re licensed fuel facility status rept & inventory difference data, NUREQ-0430, Vol 2, No 1, Jan-June 1781.
 CHILK, B. J. Office of the Secretary of the Commission. B2/05/28
 - CHILK.S.J Office of the Secretary of the Commission. 82/05/28 DIRCKS.W J Office of the Executive Director for Operations ip 22281 190 24X Fiche, 80-000, 83/12/14, 8402160003
- --B4021602B0 Discusses SECY-B2-386 re licensed fuel facility status rept inventory difference data, NUREQ-0430, Vol 2:No 2, Jul-Dec 1981 CHILK.B J Office of the Becretary of the Commission 62/09/29. DIRCKB.W J, Office of the Executive Director for Operations. 1p 22B1 227 24X Fiche 30-000.83/12/14.8402160003
- --8402160436 Discusses licensed fuel facility status rept inventory difference data:NUREG-0430.Vol 1.No 3.Jul 1982-Dec 1982.

 CHILK:S J Office of the Secretary of the Commission. 83/07/29.

 DIRCKS:W Office of the Executive Director for Operations. 1p. 22281 299 24X Fiche 50-000.83/12/14.8402160003.
- --B402160133 Discusses SECY-B1-509 ra NUREQ-0696 criteria for emergency operations facilities for nuclear power reactors CHILK: 8 J Office of the Secretary of the Commission. SB1-509. B1/09/30. DIRCKS, W J. Office of the Executive Director for Operations ip 22281:108 24X Fiche: 50-000.83/12/14.8402160003.
- --8402i60317 Discusses SECY-82-384 re status of TMI-1 NUREG-0737 items CHILK, S. J. Defice of the Secretary of the Commission. 82/10/19. DIRCKS, W. J. Defice of the Executive Director for Operations. 1p. 22881 234 24X Fichs 50-000.83/12/14,8402160003.

- --8402160349 Discusses SECY-81-582 re NUREG-0737. Item 11 F 2 concerning add1 instrumentation for detection of inadequate core cooking CHILK.8 J Office of the Secretary of the Commission S81-582 Bt/11/16 DIRCKS, W J Office of the Executive Director for Operations 1p 22281 242 24X Fiche 50-000, B3/12/14, 8402160003
- --8402160393 Discusses SECY-82-384A re status of TMI-1 NUREO-0737 items
 CHIEK.8 J Office of the Becretary of the Commission 83/01/05
 DIRCKS.W Office of the Executive Director for Operations ip
 22881 253 24X Fiche 50-000,83/12/14.8402160003
- --8402160426 Discusses SECY-82-498 re withdrawal of proposed rule to codify NUREG-0737 requirements for OL applicants CHILM.8 J Office of the Becretary of the Commission 83/02/01 DIRCKB.W Office of the Executive Director for Operations 1p 22281 260 24X Fiche 50-000,83/12/14.8402160003
- --B402160112 Discusses SECY-81-227 re long-range research plan, MREC-0740 CHILKS J Office of the Becretary of the Commission 581-227 81/07/31 DIRCKS,W J Office of the Executive Director for Operations 1p 22881 076 24X Fiche 50-000.83/12/14.8402160003
- 8402160005 Notifies of necessity to relocate technical support ctr 4T8C1 from Unit 1 computer room by Mar 1984 due to computer replacement program TSC proposed to he moved to new facility in May & to emergency operations facility in interim CDWNSIL.H Q Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.H G Northeast Utilities 810012 84/01/31 HILLER.J R Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 22276 202 24X Fiche 50-245,84/01/31.
- 8402160014 Forwards application for amend to License DPR-50, consisting of Tech Bpec Change Request 137 re installation of RCS vents per NUREO-0737, Item II B 1 & Generic Ltr 83-37 HWILL. H D General Public Utilities GPU Service Corp 5211-84-2014 84/02/07 BTDL7.J F Operating Reactors Branch 4 lp 22275 222. 24X Fiche 50-289,84/02/09.8402160014
- --8402160023 Application for amend to License DPR-50.consisting of Tech Bpec Change Request 137 re installation of RCS vents per MREQ-0737.Item II B 1 & Generic Ltr 83-37 HWKILL:H D General Public Utilities - GPU Bervice Corp QL-82-37. 84/02/09 2pp 22275 223 24X Fiche 50-289,84/02/09. 8402160014
- B402160031 Forwards SER & technical evaluation rept providing NRC review of detailed control room design review Program plan acceptable. however, summary rept does not show that detailed control room design meets Suppl 1.NUREO-0737 requirements SCHMENCER. A Licensing Branch 2 84/02/02. CURIIS.N W Pennsylvania Power & Light Co. 21pp 22301 258 24x Fichs 50-387.84/02/02.8402160031
- 8402160080 Annual Operating Rept for 1983. W/840210 ltr LARBON, C E Northern States Power Co 83/12/31 3pp 22276-195 24% Fiche: 50-263. 83/12/31, 8402160080
- 8402160087 Forwards response to requirements of Rev 2 to Reg Quide 1,97.per Section 6.2 of Suppl 1 to NOREG-0737 (Generic Ltr E2-33) & util 830415 ltr re post-accident monitoring to assess plant & environs during accident.

 MILLS.L.M Tennesses Valley Authority GL-82-33 84/01/30 ADENSAM.E. Licensing Branch 4 35pp 22276.152 24X Fichs.50-390.84/01/30,8402160089
- B402160159 Forwards updated Tab K to environ qualification audit for closing out open items contained in App 38 to SBER 5 COOK, K W Louisiana Power & Light Co W3F84-0249 84/02/10 MNIGHTON, G. W Licensing Branch 3 61pp 22275:306. 24X Fiche:36-382,84/02/10,8402160159
- 8402160228 Forwards Rev 1 to Procedure HNP-4848, "Determination of Eitent of Core Damage Under Accident Conditions," per NRC request & NUREG-0737, Item II B 3. OUCHAL T Georgie Power Co. 84/02/10 STOLZ, J F Operating Startors Branch 4. 1p 22276 317, 24X Fiche 50-321,84/02/10, R8021402028

- 8402160310 Forwards IE Insp Repts 50-277/63-35 & 50-278/83-33 on 831128-1202 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 84/02/01 DALTROFF, S L Philadelphia Electric Co 2pp 22269 125 24X Fiche 50-277, 84/02/01,8402160310
- --B402140333 IE Insp Repts 50-277/B3-35 & 50-278/B3-33 on B31128-1202
 No violations noted Major areas inspected implementation & status of NUREG-0737 Items II B 3.11 F I I -3 & III D 3 3
 re post-accident effluent monitoring & sampling
 WHITE.J R Region I. Office of Director HULL.A , KNOX.W
 Brookhaven National Laboratory 50-278/B3-33 84/01/29 22pp
 P0269 127 24X Fiche 50-277.84/02/01.8402160310
- B402160336 Forwards inservice insp rept Vols 1 & 2 for June-Aug 1983
 Rept describes insps performed on pipe supports & weld &
 other pressure retaining component exams, per Rev 1 to
 NUREQ-0313 & IE Bullstin 83-02
 BAYNE, J P Power Authority of the State of New York JPN-B4-08
 B4/02/07 VASSAKLU, D B Operating Reactors Branch 2 2pp
 22277 119 24X Fiche 50-333,84/02/07.8402160336
- --840216035B Inservice insp rept,Vols 1 & 2, for June-Aug 1983 Rept describes insps performed on pipe supports & weld & other pressure retaining component exams & susceptible stainless steel pipting.per Rev 1 to NUREG-0313 & IE Bulletin 83-02 * Ebasco Services, Inc (subs of Enserch Corp) IEB-83-02 83/12/15 1.100pp 22277.121 24X Fiche.50-333,84/02/07,8402160336
- 8402160429 Notifies that util will provide formal proposal to submit remaining NUREG-0737 required Tech Spec changes by 840330. in response to Generic Ltr 83-97 SCHOYLER, J O Pacific Oas & Electric Co GL-83-37 84/02/13 KNIGHTON, O W Licensing Branch 3 ip 22268 315 24X Fiche 50-275,84/02/13,8402160429
- B402i60449 Submits final summary of induction heating stress improvement program.per Rev 1 to NUREO-0313 & util B30914 ltr Total of 214 welds in reactor recirculation & RAR reviewed GORENSEN, C C Washington Public Fower Supply System GD2-84-67 B4/02/08 SCHWENCER, A Licensing Branch 2 2pp 22268 313 24 Fiche 50-397, B4/02/08,8402160449
- 8402160459 Forwards "Reactor Pressure Vessel Internals Seismic Load Assessment," per intergrated safety assessment rept (NUREG-0824) concerning SEP Topic III-6 "Seismic Design Considerations" COUNSIL, W. G. Montheast Nuclear Energy Co. (subs. of Northeast Utilities) COUNSIL, W. G. Northeast Utilities B10971 84/01/23 CRUTCHFIELD. D. Operating Reactors Branch 5 3pp 22277 041 24X Fiche: 50-245, 84/01/23, 8402160459
- --8402160462 "Reactor Pressure Vessel Internals Seismic Load Assessment " LIU.A S , HAABERG, B General Electric Co 83/07/31 13pp 22277 044 24X Fiche 50-245,84/01/23,8402160459
- B402160649 Forwards request for addl info on NUREG-0737. Item II D 1. "Performance Testing of Relief & Bafety Valves " Response within 60 days requested VAROA. B A Operating Reactors Branch 1 B4/02/09 STEWART. W L. Virginia Electric & Power Co Spp 22302 007. 24X Fiche: 50-280. 84/02/09. 8402160649
- B402160658 Forwards comments on detailed control room design review program plan, submitted per Suppl 1 to NUREQ-0727 & NUREQ-0700 & 0801 Plan does not address verification that improvements will provide correction of discrepancies. KNIOHTON, O W Licensing Branch 3 84/01/23 WOOLEVER, E J. Duquesne Light Co 14pp 22301 327. 24X First 50-412,84/01/23,8402160658
- 8402170001 Forwards functional description of safety parameter display sys, per Generic Ltr 62-33 rs compliance w/Suppl 1 to NUREG-0737 Encl also provides results of review of verification to validation plan recommendations GETER, J D Illinois Power Co QL-62-33 84/02/10 SCHWENCER, A Litemaing Branch 2 42pp. 22300 283 24X Fiche 50-461,84/02/10,8402170001
- 8402170007 Testimony of NJ Palladino to Subcommittee on Energy & Environ re NRG budgeting request for FY65 PALLADING, N J Commissioners 84/02/09 42pp 22319 158 24X Fiche: 50-289, 84/02/09, 8402170007.
- ---8402170027 Testimony of V Gilinsky to Subcommittee on Energy & Environ re NRC budget & experience w/Commission Answers to questions from Udall 840123 ltr & SRP encl. GILINSKY: V Commissioners. 84/02/09 120pp 22319 207

8402170042 Forwards request for add1 info re 820701 & 0901 submittals per NUREO-0737. Item II D 1. "Performance Testing of Relief & Bafety Valves" Response requested within 60 days of ltr receipt W/o encl MILLER. J R Operating Reactors Brench 3 84/02/08 BTEWART. W L Virginia Electric & Power Co 1p 22312 330 24% Fiche 50-338.84/02/08.8402170042

8402170060 NUREG-0790 V16 B02

NUCLEAR REGULATORY COMMISSION ISSUANCES October-December
1982 Pages 1.219-2.140

* Division of Technical Information & Document Control 82/12/31
76000 22307 264

8402170074 Summary of 840131 meeting w/util re status of fire protection analyses & proposed mod to mitigate fires [tems 35-57 in SER (NUREG-0991) satisfactorily addressed KINTNER.L L ticensing Branch 1 84/02/09 Licensing Branch 1 13pp 22318 168 24X Fiche 50-352.84/02/08.8402170074

8402170081 Forwards IE Insp Repts 50-010/83-22,50-237/83-32 & 50-249/83-30 on 831118-840119 & notice of violation 8HAFER: W D Region 3. Office of Director 84/02/01 REED, C Commonwealth Edison Co 2pp 22300 014 24X Fiche 50-010,84/02/01,8402170081

--B402170088 IE Insp Repts 50-010/B3-22.50-237/B3-32 & 90-249/83-30 on 831118-840119 Noncompliance noted isolation condenser drain valve 2-4808-501 found in closed position but not chained & locked & failure to have employee conduct procedure TDN9UE.T M. WALKER,R D. Region J. Office of Director 50-249/B3-30 84/01/31 20pp 22300 018 24X Fiche 50-010.84/02/01.8402170081

B402170121 NUREG-0750 V16 B01 NUCLEAR REGULATORY COMMISSION ISSUANCES July - September 1982 Pages 1-1.218 * Division of Technical Information & Document Control 82/09/30 1220 22306 001

B40B170167 Comments on proposed policy for severe accidents, per NURE9-1070, "Severe Accident Program for Nuclear Power Plant Regulation" Requirements to demonstrate consideration of insights afforded by risk analysis not well defined, SHERMODD, 6 0 General Electric Co MFNN 019-84 84/02/10 EISENHUT. D 0 Division of Licensing 3pp 22279.009

B402170173 Updates 830520 Itr re installation schedule for postaccident sampling sys per NUREG-0737. Item II B 3 Hardware uill be installed in mid-Aug & startup & testing will be completed by mid-Bept FIEDLER.P B General Public Utilities - GPU Service Corp 84/02/10 EJESNHUT.D 0 Division of Licensing ip 22279 073 24X Fiche 50-219.84/02/10.8402170173

8402170237 Provides status of control room design review program.per App F of SSER 5 & Suppl 1 to NUREG-0737 CURTIS:N W Pennsylvania Power & Light Co PLA-2046 84/02/13 SCHHENGER:A Licensing Branch 2 3pp 22296-359 24X Fiche 50-387,84/02/13.8402170237

8402170249 Modifies schedules provided in util 830413 ltm for safety parameter display sys & upgraded emergency operating procedures; per Buppl 1 to NUREO-0737 Procedures generation package will be submitted on 841001 WILLIAMS, J W Florida Power & Light Co L-84-33 84/02/14 EIEENHUT, D Q Division of Licensing 2pp 22276 150. 24X Fiche 50-230,84/02/14,8492170249

B402170258 Provides justification for revising schedule change for implementation of upgraded emergency operating procedures, ger Buppl 1 to MUREQ-0707 HILLIAMS.JW Florida Power & Light Co 84/02/17 EISENHUT,D.C. Division of Licensing 2pp 22277-182 24X Fiche 50-335,84/02/17,8402/70258

8402170304 NUREO/CR-3550
EVALUATION OF NUCLEAR FACILITY DECOMMISSIONING PROJECTS
Annual Summary Report - Fiscal Year 1983
MILLER:R t . BAUMANN.B L United Nuclear Corp FIN 8-7548
84/01/31 Division of Engineering Technology 173pp, 22304 029

B40217030B NUREC/CR-3580
STEAM GENERATOR GROUP PROJECT Semiannual Progress Report.
July-December 1982
CLARK, R A , LEWIS, M Battelle Memorial Institute, Pacific Northwest
Laboratory FIN B-2097 PNL-4692. B4/01/31 Division of
Engineering Technology 34pp Available at NRC \$3 75. 22318 223

8402170311 NUREG/CR-3579
STEAM GENERATOR OROUP PROJECT Progress Report On Data
Acquisition/Statistical Analysis
DDCTOR, P J. BUCHANAN, J A. MCINTYRE, J M Battelle Memorial
Institute, Pacific Northwest Laboratory FIN B-2097 PNL-3955
84/01/31 Division of Engineering Technology 38pp Available at
NRC \$3 75 22318 181

B402170320 NUREG-0040 V07 N04 LICENSEE CONTRACTOR AND VENDOR INSPECTION STATUS REPORT Quarterly Report, October 1983-December 1983 (White Book) * Region 4, Office of Director 84/01/31 190pp 22303.001

B402170417 NUREG/CR-3057
ANALYSIS OF AVAILABILITY OF PREVIOUSLY INDENTIFIED SITES
UNDER ALTERNATIVE DEMOGRAPHIC CRITERIA
KELLY.M J. RUSH.R M , OTT.W R Clak Ridge National Laboratory FIN
A-9043 GRNL-5936 84/01/31 Division of Health, Biting & Haste
Kanagement 44pp Available at NRC \$450 22320 041

8402170430 NUREG/CR-3530

REVIEW OF THE DAVIS-BESSE UNIT NO 1 AUXILIARY FEEDWAYER
SYSTEM RELIABILITY ANALYSIS
YGUNOSLOOD, R, PAPAZOCLOU, I A
BNL-NUREG-51722 84/02/29 Division of Safety Technology 179
Available at NRC \$3.75 22318 319 24% Fiche 50-346, 84/02/29,
8402170430

B402170439 NUREQ/CR-3056
POPULATION DISTRIBUTION ANALYBIS FOR NUCLEAR POWER PLANT
SITINO
DURFEE,R C , COLEMAN,P R Oak Ridge National Laboratory FIN
A-9043 ORNL/CSD/TM-197 B3/12/21 Division of Health, Siting &
Waste Management 104pp Available at NRC, \$8.50 22302:166

8402170460 Forwards BER on 821223 response to Generic Ltr 82-16 NURE9-0737. Items I A 1 1 3, "Shift Technical Advisor Training" & II E 4 1, "Dedicated Hydrogen Penetrations," identified as open VAR9A:S A Operating Reactors Branch 1 QL-82-16 84/02/10 Q1EBLER:C W Wisconsin Public Service Corp 7pp 22305 350 24 Fichs 50-305,84/02/10,8402170460

B402170463 Btaff requirements mamp re Commission 840202 briefing in Washington, DC on quanterly progress on safety goal evaluation rept & draft PRA document CHILK.S J Office of the Becretary of the Commission M840202A B4/02/0B Office of the Becretary of the Commission. ip. 22305 344

8402170489 Informs of cost to obtain NUREQ/CR-2639 "Historical Extreme Winds for US Atlantic & Qulf of Mexico Coastlines." Request & payment may be sent to listed address. VIETTI, A Licensing Branch 3 84/02/13 BUCHORN, K Citizens for Equitable Utilities ip, 22312 361 24X Fiche 50-478.84/02/13, 8402170489

8402170494 NUREO/CR-3444 VO1
THE IMPACT OF LWR DECONTAMINATIONS ON SOLIDIFICATION, WASTE
DISPOSAL AND ASSOCIATED DECUPATIONAL EXPOSURE Annual
Report
DAVIS:M 8 Brookhaven National Laboratory FIN A-3246
BNL-NUREG-51699 84/01/31 Division of Engineering Technology
124pp 22304 202

8402170498 NUREO/CR-3448
URANTUM HOLDUP MODELING.
PICARD/R R MARSHALL/R S, Los Alemos Scientific Laboratory. FIR
A-7226 LA-9853-MS 84/01/31 Division of Facility Operations.
10pp 22320 001

8402170503 NUREO/GR-9531

REVIEW OF SEABROOK UNITS 1 AND 2 AUXILIARY FEEDWATER SYSTEM
RELIABILITY ANALYSIS
FRESCO, A. YOUNGSLOOD, R., PAPAZOGLOU, I A Brookhaven National
Laboratory FIN A-9393 BNL-NUREO-51723 84/02/27 Division of
Safaty Technology 1749p Available at NRC \$6 00 22304:320
24X Fiche 50-443,84/02/29,8402170503

B402170513 NUREG/BR-0051 V05 N4 POWER REACTOR EVENTS July-August 1983 MABSARO, 8 A , TRENERY, S E Director's Office 84/01/31. 24pp. 22305.154

8402170514 NUREO-1040 ERR
U S NUCLEAR REGULATORY COMMISSION BUDGET ESTIMATES
FISCAL YEAR 1985, (Green Book)
* Division of Technical Information & Document Control. 84/02/02
4pp 22318 358

8402170517 NUREG-1045
QUIDANCE ON THE APPLICATION OF COMPENSATORY SAFEGUARDS
MEASURES FOR POWER REACTOR LICENSEES
BLUMENTHAL.H S Division of Safeguards 84/01/31 10pp Available
at NRC \$3 00. 22320 024

E402210013 NUREG/CR-3554
RADIDNUCLIDE MIGRATION IN GROUNDWATER Annual Progress Report
For 1982
ROBERTSON, D.E., TOSTE, A.P., ABEL, K.H. Battelie Momorial Institute,
Pacific Northwest Laboratory FIN B-2360 PNL-4773 84/01/31
Division of Health, Siting & Waste Management 92pp Available at
NRC \$4 50 22323 031

B402210016 NUREG-0940 VOS NII TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE November 1-30,1983 * Division of Technical Information & Document Control 84/01/31 58769 22324 001

B402210019 NUREO/CR-3483
A BTUDY OF THE REGULATORY POSITION ON POSTULATED PIPE
RUPTURE LOCATION CRITERIA
WCO.H Lawrence Livermore Laboratory FIN A-0363 UCRL-33490
84/01/31 Division of Engineering Technology 44pp Available at
NRC \$3 75 22323 115

B4D2210021 NUREG/CR-3428
APPLICATION OF THE SSMRP METHODOLOGY TO THE BEISMIC RIBK AT
THE ZION NUCLEAR POWER PLANT
BDHN.M P . SKIEH.L C . WELLS.J E Lawrence Livermore Laboratory
FIN A-0126 UCRL-53483 B4/01/31 Division of Engineering
Technology. 324pp Available at NRC \$8 00 22322 001. 24X
Fichs 50-295,84/01/31,8402210021

8402210024 NUREG/CR-3484
TRAN 8-i EXPERIMENTAL INVESTIGATION OF FUEL CRUST STABILITY
ON SURFACES OF AN ANNULAR FLOW CHANNEL
MCARTHUR, D.A., MAST, P. K. Sandia Laboratories FIN A-1016
EANDB3-1916 64/01/31 Division of Accident Evaluation (Pre
840101), 32pp 22343-281

8402210026 NUREG/CR-3496
REVIEW OF A TEST PRODRAM FOR QUALIFYING THE SOLIDIFICATION
OF EPICOR 11 RESINS WITH GEMENT.
BARLETTA, R E , DAVIS, R E
Brookhaven National Laboratory FIN
A-3162 BRL-NUREG-51712 B4/01/31 Division of Wasta Management
32pp. Available at NRC, \$3 75. 22323 001

8402210028 NUREG-0740 VO2 NO4 ENFORCEMENT ACTIONS SIGNIFICANT ACTIONS RESOLVED Guarterly Progress Report October-December 1983 • Director's Office, Office of Inspection and Enforcement 84/01/31. 437pp Available at NRC \$9

8402210073 NUREO/CR-3491
GCA-11.A CODE FOR CALCULATING THE BEHAVIOR OF 2-D AND 3-D
SURFACE FLAMB IN A PRESBURE VEBSEL SUBJECTED TO TEMPERATURE
AND PRESSURE TRANSIENTS
EALL.D. C., CHEVERTON: R D. DRAKE.J D. Oak Ridge National Laboratory
FIN B-0119 DRNL-5934. B4/02/29 Division of Engineering
Tachnology. 110pp 22323 189

840221007B NUREO-0020 VO7 N12 LICENBED OPERATING REACTORS STATUS SUMMARY REPORT Data As Of November 30,1983 (Ores Book) & Managament Information Branch 84/02/29 379pp 22320 313

E402210082 Responds to 831101 Generic Ltr 83-36 re Tech Spec review against requirements of NUREO-0737 & application for license amends in noncompliance areas Amends to change OL to possession-only will be requested in early 1984 ECHUYLER; J O. Pacific Gas & Electric Co GL-83-36. 64/02/13 ETGENANT, D.O. Division of Licensing 1p 22317 332 24X Fiche 30-133,84/02/13,8402210082

8402210107 Informs that util considers NUREO-0737 Items II K 3 30 % 31 closed as result of NRC 831213 acceptance of GE small break LOCA models.

8402210107 P Power Authority of the State of New York JPN-84-12 84/02/14, VASSALLO, D. B. Operating Reactors Branch 2 2pp. 22317, 237 24X Ficher 50-333, 84/02/14, 8402210107

8402210142 Forwards revised response re basis for selection of safety parameter display sys for facility.per Suppl 1 to NUREO-0737.
SMARTZ, E D. Commonwealth Edison Co. 8137N. 84/02/10 DENTON,H R Office of Nuclear Reactor Regulation, Director 5pp. 22317 172 24X Fiche: 50-275,84/02/10,8402210142.

8402210148 Notifies that RCS vent procedure will not be implemented until complete set of emergency operating instructions implemented per Generic Ltr 82-33, Suppl 1 to NUREG-0737 & TMI Item II B 1 MILLB.L M Tennessee Valley Authority GL-82-33 84/02/15 ADENSAM.E Licensing Branch 4 tp 22316 357 24X Fiche 50-327,84/02/15,8402210148

8402210168 Forwards Human Factors Engineering Branch draft SER re detailed control room design review per Suppl 1 to NUREG-0707 Add info needed to complete review VARGA:S A Operating Reactors Branch 1 84/02/02 HILLIAMS, J W Florida Power & Light Co 18pp 22346 029 24X Fiche 50-000,84/02/02.8402210168

B402210169 Submits new results, methodology & assumptions of study of airborne dose to control room occupants during postulated max credible accident, in response to Generic Ltr 82-33, Suppl 1 to NUREO-0737 & Post-TMI Item III D 3 4 LINDER, F Dairyland Power Cooperative LAC-9577 84/02/07 EISENHUT, D 9 Division of Licensing 5pp 22316 330 24% Fiche 50-409, B4/02/09.8402210169

840221018B NUREG-1040 FY 1985 BUDGET ESTIMATES * Division of Budget & Analysis 84/01/31 &8pp 22346 072

8402210388 Summary of 830819 meeting w/util re physical security plan per SRP (NUREQ-0800). Section 13 6 No major safeguards issues identified VIETTI.A Licensing Branch 3 84/02/03 Licensing Branch 3 3pp 22363 075 24X Fiche 50-508.84/02/03.8402210388

8402220004 Application for amend to License DPR-72 revising Tech Specs to include add1 DHR requirements Amend fee enc1 WESTAFER Florida Power Corp 3F0284-09 84/02/16 DENTON, H R Dffice of Nuclear Reactor Regulation, Director 4pp 22337 276 24X Fiche 50-302.84/02/16.8402220004

8402220055 Forwards draft "Detailed Control Room Design Review Program Plan:" per Suppl 1 to NUREG-0737 Meeting to discuss proposed actions requested 0'TOOLE.J D Consolidated Edison Co of New York, Inc 84/02/14 EIBENHUT.D C Division of Licensing 1p 22327 275 24X Fiche 50-247.84/02/14.84022095

--8402220058 Draft "Detailed Control Room Design Review Program Flan " # Consolidated Edison Co of New York, Inc. 1 5/020684 84/02/14 100pp 22327 297 24X Fiche 50-247.84/02/14, 8400220055

B40222007i Forwards Rev 3 to Vols 1 & 2 to "Response to Suppl 1, NUREO-0737" Encl rev includes control room review final a supplemental repts & safety parameter display sys safety analysis
TUCKER, H B Duke Power Co 84/02/16 DENTON, H R Office of Nuclear Reactor Regulation, Director Spp 22327 046 24% Fiche 50-269, 84/02/16, 840222007i

--8402220077 Rev 3 to Vols 1 & 2 to "Response to Suppl 1, NUREG-0737" * Duke Power Co 84/02/16 250pp 22327 049 24X Fiche: 50-269.84/02/16,8402220071

D402220079 NUREO/CR-3614
CONSTANT SYTEMSION RATE TESTING OF GASOZ GRADE B MATERIAL
IN NEUTRAL AND CHLORIDE SOLUTIONS
CZAJKOHSKI, C. J. Brockhaven National Laboratory, FIN A-3716
DKL-NUREO-51736 B4/02/29 Division of Engineering 48pp
Available at NRC \$4 00 22364 076

B402220210 Forwards preliminary Rev 2 to Procedure SP-5061. "Spec for Electric Transmitters" & addi info re proposed inadequate core cooling instrumentation sys.per NUREG-0737. Item II F 2 W/two oversize drawings Aperture cards in PBR WEBTAPER.9. R. Florids Power Corp. 3F0284-07 84/02/15 9T0LZ, J F Operating Reactors Branch 4 11pp 22335. 216 24X Fiche 50-302. B4/02/15. B402220210

--B402220217 Preliminary Rev 2 to Procedure BP-5061, "Spec for Electric Transmitters" * 8 Bone & Webster Engineering Corp 84/02/13 59pp 22335 227 24X Fiche 50-302.84/02/15.8402220210

8402220321 Forwards IE Insp Rept 50-285/83-31 on 831114-18 & notice of violation OAQLIARDO, J E. Region 4, Office of Director 84/01/05 JBNES, W C Dmaha Public Power District 2pp. 22336 267 24X Fiche 50-285,84/01/05,840220321.

- --B402220326 IE Insp Rept 50-285/63-31 on S31114-18 Violation noted weekly review of approx 14 standing radiation work permits not gerformed for Feb % May 1983 HOLLEY, W L , MURRAY, B , JOHNSON, W D Region 4, Office of Director B3/12/22 7pp 22336 270 24% Fiche 50-265.84/01/05,8402220321
- 8402220325 Forwards Rev 2 to util response to Suppl 1 to NUREG-0737, including control room review final rept & supplemental rept Rev does not include implementation schedule for control room mods
 TUCKER, H B Duke Power Co 84/02/16 DENTON, H R Office of Nuclear Reactor Regulation. Director ADENSAM, E G Licensing Branch 4 2pp 22338 022 24X Fiche 50-369, 84/02/16, 840220325
- --8402220328 Rev 2 to "Response to Suppl 1 to NUREC-0737"
 * Duke Power Co 84/02/16 200pp 22338 024 24x
 Fiche 50-369,84/02/16,8402220325
- 8402220331 Responds to 831215 request for add1 info re position on two of 11 NUREG-0737, Item II B 3 criteria Licenses should provide procedure to estimate extent of core damage based on radionuclide concentrations CLAYTON-FL Alabama Power Co 84/02/17 VARGA. S A Office of Nuclear Reactor Regulation. Director App 22334 225 24% Fichs 50-348,84/02/17.8402220331
- 8402220358 NUREG/CR-3636
 BENCHMARK PROBLEMS FOR REPOSITORY DESIGN MODELS
 WART.R J , SKIBA,E L , CURTIS.R H Acres American, Inc 84/02/29
 Division of Waste Management 191pp Available at NRC \$6 00
 22364 145
- 8402220385 Forwards revised historical earthquake data implementation schedule.per Section 18 2 of SER Open [tem 18. "Control Room Design Review " Implementation of identified historical earthquake data solutions acceptable TUCKERN # 8 Duke Power Co 64/02/20 DENTON.H R Office of Nuclear Reactor Regulation. Director ADENSAM.E G Licensing Branch 4 Bpp 22335 270 24% Fiche 30-413,84/02/20.8402220385
- 8402220442 Forwards revised schedule for submittal of responses to listed NRC ltrs Rev due to large number of submittals & limited personnel available to respond Changes to Tech Specs.ger Generic Ltr 83-43, will be sent by 840504 GIESLER, C W Wisconsin Public Service Corp NRC-84-30 84/02/16 VARGA-S A Operating Reactors Branch 1 6pp 22340 001 24X Fiche 30-305,84/02/16.8402220442
- 8402220497 Responds to Generic Ltr 83~35 & NUREG-0737, Items II K 3 30 & II.K 3 31 re small break LOCA analysis Westinghouse Owners Group program will demonstrate that NOTRUMP predicts lower temps than WFLASH CLAYTON, F L Alabama Power Co GL-83~35 84/02/10 VARQA, S A Office of Nuclear Reactor Regulation, Director 29p 22340 066 24X Fichs 50~348,84/02/10,8402220487
- B402220489 Forwards proprietary & nonproprietary "Comprehensive Vibratian Assessment Program for Palo Verde, Unit 1 (Sys 80 Prototype)," per SER (NUREG-0852) Proprietary rept withheld (ref 10CFR2 790) SCHERER, A & Combustion Engineering, Inc. LD-84-008 84/02/16 EISENHUT, D @ Division of Licensing 5pp 22333-057 24X Fiche 50-000,84/02/16,8402220489
- 8402220499 Submits changes to scheduled completion dates for proposed corrective actions noted in WC Jones 820121 response to Section 2 2-2 4 of Encl 3 to NUREG-0612 re control of heavy loads
 JONES W C Omaha Public Power District LIC-84-039 84/02/14
 MILLER J R Operating Reactors Branch 3 4pp 22334 082 24X
 Fiche 50-285,84/02/14.8402220499
- B402220513 Responds to B40208 request that NRC 800410 ltr describing NRC role in radiological emergency at plant be updated & reissued. NRC will respond to all significant incidents at power reactors per NUREO-0728 & NUREO-0845 PAPERIELLO,C J Region 3. Office of Director 84/02/14 SCHNELL,D F Union Electric Co ip 22333 360 24% Fiche 50-483.84/02/14.8402220513
- 8402220564 Advises of plans to perform approved mod on Unit 2 Mpdel D5 steam generators & provides plant-specific details required by NUREG-1014 Mods to Unit 1 steam generators will be completed prior to fuel loading date of 840501 TUCKER: H B Duke Power Co 84/02/20 DENTON, H R Office of Nuclear Reactor Regulation. Director ADENSAM, E G Licensing Branch 4 7pp 22333:143 24X Fiche 50-413,84/02/20,8402220564

- B402230006 Ack receipt of B40113 response to B31207 notice of deviation re HEPA filtration & test criteria Response to both deviations unacceptable Issue should be reconsidered & response supplied within 30 days B6CARANOR A Region 5, Office of Director 84/02/17 VAN BRUNT, E E Arizana Public Service Co 2pp 22362 056 24X Fiche 50-528,84/02/17,8402230006
- B402230012 Notifies of variance from requirements of NUREG-0737 Recent review of stack gas monitors revealed that display capabilities not in accord w/NUREG-0737, Item II F 1 1 VANDEWALLE, D J Consumers Power Co 84/02/20 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 22362 059 24X Fiche 50-000,84/02/20,8402230012
- 8402230023 Biscusses review of util 831013 response to NUREQ-O7:17.

 Item II E 4 2 7. "Primary Containment High Radiation to Close Vent & Purge Valves " Requirements met VABSALLO.D B Operating Reactors Branch 2 B4/01/30 LIU.L Iowa Electric Light & Power Co 2pp 22379 356 24X

 Fiche 50-331.84/01/30.8402230023
- 8402230088 Responds to 831217 Generic Ltr 83-42 which indicated that guidelines of NUREG-0612 re single failure proof cranes may be deficient Review of diagrams indicates no single failure could result in uncontrolled motion of crane GEIER, J D Illinois Power Co U-0676 84/02/10 8CHHENCER, A Licensing Branch 2 1p 22361 284 24% Fiche 50-461,84/02/10. 8402230088
- 8402230093 "Effluent & Waste Disposal Semiannual Rept.Jul-Dec 1983 "
 W/840213 ltr
 MURRAY.T D Toledo Edison Co RR 2 P-2-83-02 83/12/31
 KEPPLER J G Region 3, Office of Director 87pp 22362 145 24%
 Fiche 50-346.83/12/31.8402230093
- 8402230095 Forwards Vols 1-6 of plant-unique analysis regt.reacting applicable requirements of NUREO-0661, "SER Re Mark I Containment Long-Term Program"

 MITTL.R L Public Service Electric & Qas Co. of New Jarsey 84/02/10 SCHWENCER.A Licensing Branch 2 1p 22349.101 24X Fiche 30-354.84/02/10.8402230095
- 8402230106 Discusses installation of insp ports in each steam generator prior to startup after first refueling per Item 5 3 1 in SEER 4.NURS-0422 Steam generator monitoring & testing programs in effect & acceptable alternative planned TUCKER.H B Duke Power Co 84/02/14 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E G Licensing Branch 4 2pp 22362 134 24X Fichs 50-369,84/02/14,8402230106.
- 8402230107 Advises that Natl Weather Svc be contacted from technical support ctr & emergency operations facility.per Oeneric Ltr 82-33 (Suppl 1 to NUREO-0737) re requirements for emergency response capability LINDER: Dairyland Power Cooperative LAC-9389 84/02/16 EISENHUT, D 0 Division of Licensing 1p 22361 205 24X Fiche 50-409:84/02/16.8402230109
- 8402230143 Supplemental application for amend to Licenses DPR-32 & DPR-37, adding limiting conditions for operation & surveillance requirements for main control chlorine detection sys, per NUREO-0737, Item III, D 3 4
 SIEWART.W L Virginia Electric & Power Co 662C. 84/02/14.
 DENTON, H R. Office of Nuclear Reactor Regulation, Director VARGA, 8 A Operating Reactors Branch 1 2pp. 22361 033 R4X
 Fiche 50-280,84/02/14,8402230143
- 8402230173 Forwards table showing status for submitting Tech Bp#C change request for long-term NUREG-0737 items. in response to Generic Ltr 83-37
 HUKILL H D General Public Utilities QPU Bervice Corp 5211-84-2030 84/02/16 EISENHUT, D C Division of Licensing 3pp 22361 230 24% Fichs 50-289,84/02/16.8402230173
- 8402230190 Forwards application to amend License DPR-64 in response to requirements of Generic Ltr 83-37 re NUREG-0737 Tech Specs.
 BAYNE, J P Power Authority of the State of New York OL-83-37 84/02/17. EISEMHUT, D G Division of Licensing 2pp 22361 055 24X fiche 30-286,84/02/17,8402230190
- --8402230176 Application to amend License DPR-64 changing Tack Spacs in accordance w/requirements of Generic Ltr 83-37 BAYNEL JP Power Authority of the State of New York GL-83-37 84/02/17 App 22361:057 24X Fiche 30-286,84/02/17.8402230190
- ---B402230199 Proposed Tech Spec changes in response to requirements of Generic Ltr 83-37

 * Power Authority of the State of New York. GL-83-37. B4/02/17
 20pp 22361 061 24X Fiche 50-286.84/02/17,8402230190

- 8402230204 Forwards FR notice of issuance of order confirming licensee coamitments on emergency response capability schedules, per Generic Ltr 82-03 Order based on 830408,0811 & 1205 ltrs CRUTCHIELD, D Operating Reactors Branch 5 LS05-84-02-043 84/02/22 LINDER, F Dairyland Power Cooperative 4pp 22361 045 24x Fiche 50-409,84/02/22.8402230204
- --8402230214 Notice of issuance of order confirming licenses commitments on emergency response capability, per Suppl 1 to NUREG-0737 & Owneric Ltr 82-33 EIERNUT, D O Division of Licensing QL-82-33 84/02/22 6pp 22361 049 24X Fichs 50-409.84/02/22.8402230204
- 8402230235 Forwards "Function & Task Analysis of Emergency Operating Procedures" & "Control Room Design Review Program Plan "
 SOMENSEN, O C Mashington Public Power Supply System GO2-84-B1
 84702/17 SCHMENCER, A Licensing Branch 2 1p 22352 123 24X
 Fichs 50-397.84/02/17,8402R30225
- --8402230232 "Cantrol Room Design Review Program Flan " DEVALLE,R O Washington Public Power Supply System 84/02/29 68pp 22352 137. 24% Fiche 50~397,84/02/17,8402230225
- B40223023B Discusses resolution of SER open items re environ qualification of safety-related electrical equipment per B3[212 meeting General methodology used to establish aging & radiation qualification encl MUSOLF, D Northern States Power Co IEB-79-01B 84/02/10 Office of Nuclear Reactor Regulation, Director 31pp 22352 276 24% Fiche 50-263.84/02/10.8402230238
- B402230284 Summary of 840207 meeting w/util in Bethesda,MD re detailed control room design review per Suppl 1 to NUREO-0737 List of participants enci.
 BTEFANO,J J Licensing Branch 1 84/02/16 YOUNOBLOOD,D J Licensing Branch 1 3pp 22380 026 24X Fiche 50-440,84/02/16.
 B402230284
- B402230315 Forwards safety evaluation on NUREO-0737. Item II K 3 18 re automatic depressurization sys logic mods Maintaining sys w/o mod unacceptable Response requested within 30 days VASSALLO.D. B Operating Reactors Branch 2 84/02/02 UTLEY. E Catolina Fower & Light Co 7pp 22371 224 24X Fichs. 50-324.84/02/02.8402230315
- 8402230334 FOIA request for info re total expenditure on Contract FIN A-1123, beginning & termination date & breakdown of expenditures by major subcontracts & computer charges RICEV.J L. Affiliation Not Assigned FIN A-1123 83/09/13 FELTON.J H Division of Rules and Records 1p 22378 048
- 8402230357 Responds to FOIA request for records which indicate total expenditure on Contract FIN A-1123 beginning & termination date of contract & breakdown of expenditures by major subcontracts & computer charges
 FELTON, J M. Division of Rules and Records FIN A-1123 84/01/31 RILEY, J. L. Affiliation Not Assigned 1p 22378 047
- B402230378 NUREO/CR-2812
 THE RELATIVE IMPORTANCE OF TEMPERATURE, PH AND BORIC ACID
 CONCENTRATION ON RATES OF H2 PRODUCTION FROM GALVANIZED
 STEEL CORROBION
 LOYDLA, V M , MOMELBOUFF, J E Sandia Laboratories FIN A-1255
 SAVB82-1179. B4/01/31 Division of Accident Evaluation (Pre
 840101) 31pp 22374 177
- 8402230411 Responds to FDIA request for four categories of documents Forwards marked-up excerpt from Vol 3 of NUREG-0713 re occupational radiation exposure partial NUREG-0714 Vols 2 & 3 & draft rept on termination H/o NUREG-0714 & draft rept FELTON, J M Division of Rules and Records 83/12/13, MAYBERRY, S Public Citizen Litigation Group 2pp 28378 107
- --8402230413 NUREO-0713 DRFT
 Markwd-up excerpt from NUREO-0713, "Occupational Radiation Exposure at Commercial Nuclear Power Reactors 1981,"

 * NRC No Detailed Affiliation Given, 83/12/13, 14pp. 22378 109.
- E402230441 FDIA request for documents re licensed research reactors, including NUREQ-0020 on anticipated requests for licensing & relicensability of reactors.

 BELL.N Nuclear Information & Resource Service 83/11/22. Office of Administration ip 22371,345
- 8402240017 Forwards boron dilution analysis, per Reg Quide 1.70 & RUREO-06800. For failures in chemical & vol control sys, based on Westinghouse STB setpoints & limits No design changes recommended or implied. W/o encl COUNSIL, M.9. Northeast Utilities Bil030 84/02/10 YOUNDSLOOD, B J. Licensing Branch 1 ip 22375, 244, 24X Fiche 10-423, 84/02/10, 8402240017

- 8402240044 Forwards IE Insp Rept 30-214/83-24 on 831012,17-21 t 27 t notice of violation

 MARTIN.T T Division of Engineering t Technical Programs 84/02/09

 FIEDLER.P B General Public Utilities OPU Service Corp App 22373 309 24X Fiche 50-219,84/02/09.8402240044
- --B402240050 1E Insp Rept 50-219/83-24 on 831012.17-21 & 27 Violation noted failure to document certain NUREG-0737 design-related activities for containment monitors EAPEN.P K. NARROW.L., GREGG.H I Region 1. Office of Director IED-80-16 B3/12/12 14pg 22373 307 24X Fiche 50-219, 88/02/09.8400240044
- B402240086 Further response to FDIA request for 16 categories of dacuments Item 9 limited, per 831005 telcon Forwards Rev 7 to NUREG-0525 % App A documents Portions of App I documents uithheld (ref PDIA Exemption 4) App 9 documents also in PDR FELTON, J M Division of Rules and Records 83/12/12 SHOLLY, S O Union of Concerned Scientists 4pp 22394 150 24X Fiche 90-000, 83/12/12, 8402240086
- B408240093 Forwards IE lnsp Rept 50-322/83-38 on 831128-840122 No violations noted STARDSTECKI.R Division of Project & Resident Programs 84/08/07 POLLOCK.M S Long Island Lighting Co 2pp 22373 242 24X Ficha 50-322.84/02/07.8402240093
- --840224010A IE Insp Rept 50-322/83-38 on 831128-840122 No violations noted Major areas inspected IE Bulletin 79-24 & Circulars 77-12 & 80-02, cuntrol room human factors review, implementation of NUMEG-0737 items & surveillance testing PETRONE; C · SHEDLOSKY, J T · CODM. W Region I. Dffice of Director IEB-79-24 84/02/03 17pp 22373 244 24X Fiche 50-322, 84/02/07,8408240073
- 8402240074 Forwards response to NRC 830311 request for add1 info re NUREG-0737. Item II K 3 28, "Qualification of Automatic Depressurisation Sys (ADS) Accumulators " Util will replace ADS check valves w/qualified valves by 830627 BAYNG, J P Power Authority of the State of New York JPN-84-13 84/02/17 VASSALLO, D B Operating Reactors Branch 2 7pp 22373 289 24X Fiche 50-333,84/02/17,8402240094
- 8402240107 Responds to request for add1 info re NUREG-0737, Item II F 2 concerning reactor coolant inventory tracking, core exit thermocauple 2 subcooling margin monitor says Westinghouse subcooling margin monitor meets NUREG-0587 requirements DIXON.D W South Carolina Electric & Gas Co 84/02/17, DENTON, H R Office of Nuclear Reactor Regulation, Director Spp 22375 005 24X Fiche 50-395,84/02/17.8402240107.
- 8402240112 Forwards application to amend License DPR-50, consisting of Tech Spec Change Request 130 re backup in-core thermocouple display operability.per NUREG-0737, Item II F 2 HUKILL.H D General Public Utilities QPU Service Corp 5211-84-2003 84/02/13 8702.J F Operating Reactors Branch 4 ip 22373 296 24X Fiche 50-289,84/02/13,8402240112
- --8402240122 Tech Spec Change Request 130 re current status of backup in-core thermocouples.per NUREG-0737.Item II F 2 HUKELL.H D General Public Utilities - GPU Service Corp 84/02/13 3pp 22373 299, 24X Fiche 50-289.84/02/13,8402240112
- 84Q2240120 Forwards supplemental info to resolve NUREG-0612, "Control of Heavy Loads " Info also addresses conterns in Phases 1 & 2 of draft technical evaluation rept W/51 oversize drawings Aperture cards are in PDR.

 BARNES P L. Commonwealth Edison Co 8142N 84/02/10 DENTON, H R Office of Nuclear Reactor Regulation. Director 29pp 22374 287 24X Fiche 50-000 84/02/10, 8402240120
- 8402240124 Forwards review of Tech Specs for NUREG-0737 items scheduled after 811231 per Generic Ltr 83-36 Negotiation of reasonable schedule for development & submittal proposed SINCLAIR, J B Vermont Yankes Nuclear Power Corp GL-83-36 84/02/22 VASSALLO.D B. Operating Reactors Branch 2 3pp 22373 328 24X Fiche 50-271,84/02/22,8402240124
- 8402240145 Forwards response to request for add1 sustification for proposed completion schedule re NVREO-0737, Item II B 3, "Post-Accident Sampling Capability " Site verfication tests will be completed by 840501 OUCMA-L T Operaia Power Co NEO-84-077 84/02/20 STOLZ, J F Operating Roactors Branch 4 5pp 22375 071 24% Fiche 50-321,84/02/20.8402240145.
- 8402240172 FOIA request for comparative evaluation of compliance w/TMI-2 accident lessons learned requirements (NUREO-0578 & NUREO-0737 & suppl) by individual nuclear plants. WEI88 R R Union of Concerned Scientists 83/12/21 FELTON, J. Division of Rules and Records 1p. 22382 001

- 8402240173 Comments on Dec 1983 draft Suppl I to programmatic EI8 (NUREG-0683) Estimate of collective dose equivalent expected to occur during recovery operations should be increased FLETCHER.J C TMI-2 Technical Assistance & Advisory Group 84/02/27 SNYDER.B J TMI Program Office 6pp 22375 079 24% Fiche 50-320.84/02/27.8402240173
- 8408240175 Responds to FDIA request for comparative evaluation of compliance by individual nuclear plants w/TMI-2 accident lessons learned requirements (NUREG-0578 & NUREG-0777 & suppl) Forwards App A documents info also available in PDR FELTON, J M Division of Rules and Records 84/01/13 WEISS, E Union of Concerned Scientists 2pp 22382 002
- --8402240178 List of licenses implementation of NUREG-0737 ** NRC - No Detailed Affiliation Given 83/01/01 9pp 23382 004
- B402240199 Responds to FOIA request for SECY-83-404 to be placed in PDR Forwards SECY Bocument also available in PDR FELTON, J M Division of Rules and Records 84/02/07 BUCKLES.R NUS Corp ip 22381 289
- --B402240200 SECY-B3-404
 Advises Commission of evaluation of thiosulfate contamination & PORV corrosion problem at THI-1, as requested in S Chilk B30810 memo stemming from ALAB-724
 DIRCKS,W J Office of the Executive Director for Operations ALAB-724
 B3/07/30
 2pp
 22381
 290
- 8402240205 FBIA request for NUREO/CR-3121 (SAND83-0013), "Generic Modeling Approach for LMR Sys Analysis," to be placed in PDR Full explanation should be provided if rept exempt from public disclosure for security reasons SHOLLY.S C Union of Concerned Scientists 83/10/26 FELTON, J M Division of Rules and Records 1p 22373 164
- 8402240207 Responds to FDIA request for NUREO/CR-3121 to be made available in PDR Forwards NUREO/CR-3121 Document also placed in PDR FELTON, J M Division of Rules and Records 83/12/12 8HOLLY, 8 C Union of Concerned Scientists 1p 22393 165
- 8402240222 Notification of 840223 meeting w/BWR Owners Group & GE in Bethesda,MD to discuss 831118 submittal providing addl info re scram discharge piping in response to NUREG-0803 ECCLESTON.K T Deprating Reactors Branch 2 84/02/15 VASSALLD,D # Operating Reactors Branch 2 1p 22381 280
- B402240233 NUREG/CR-3984
 COMMONLY USED NUCLEAR MATERIAL MEASUREMENTS AND THEIR
 SOURCES OF ERROR
 ROBERTS, F P. DROWNS, R J., BYERS, K R Battelle Memorial Institute,
 Pacific Northwest Laboratory FIN B-8105 84/01/31 Division o
 Facility Operations 116pp R2381 001
- 8402240271 NUREG/BR-0059 RO1 SMALL BUSINESS INNOVATION RESEARCH PROGRAM Program Solicitation FY 1984 * Division of Contracts 84/04/22 41pp 22380 222
- B402240373 NUREO-1046 DRFT
 DISPOSAL OF HIGH-LEVEL RADIOACTIVE MASTES IN THE UNSATURATED
 ZONE TECHNICAL CONSIDERATIONS Draft Report For Comment
 OSTROWSKI,N · NICHOLEON,T J · ALEXANDER,D H. Division of Health,
 Siting & Waste Management B4/02/29 43pp 22380 244
- 8402240378 NUREG/CR-2721
 SCOPING STUDY OF THE ALTERNATIVES FOR MANAGING WASTE
 CONTAINING CHELATING DECONTAMIATION CHEMICALS
 PREMUZIC,E T, MANAKTOLA, H K Brookhaven Netional Laboratory FIN
 A-3159 BNL-NUREG-51593 84/02/27 Division of Waste Management
 56pp Available at NRC 84 25 22380 309
- 840224038) NUREG-0887 S04

 9AFETY EVALUATION REPORT RELATED TO THE OPERATION OF PERRY NUCLEAR POWER PLANT, UNITS 1 AND 2 Docket Nos 50-440 And 50-441 (Cleveland Electric [lluminating Company) # Division of Licensing 84/02/28 142pp 22381-118 24X Fiche 50-440.84/02/28.8402240381
- 8402270003 Informs that administrative & implementing procedures for fire protection plan will include listed controls.per Confirmatory Issue 37 of BER (NUREG-0991) Procedures will be issued prior to fuel load KEMPER.J S Philadelphia Electric Co 84/02/21 SCHWENCER.A Licensing Branch 2 Spp. 22391 284. 24X Fiche 50-352,84/02/21,8402270005

- 8402270028 Forwards results of evaluation of reactor bldg polar crane design & special lifting device design conderations Schedulp of actions taken & planned to resolve heavy loads issue encl HUKILL, H D General Public Utilities GPU Bervice Corp S211-84-2013 84/02/21 EISENHUT, D G Division of Licensing 4pp 22388 001 24% Fiche 50-289, 84/02/21, 8402270028
- ~~8402270031 "Evaluation of Heavy Load Handling Operations at TMI-1, Responses to NRC Requests in Technical Evaluation Rept Transmitted Bil021" HLADIK,M , GEORGE,H General Public Utilities - GPU Service Corp 84/01/04 94pp 22388 000 24X Fiche 50-289.84/02/21.8402270028,
- 8402270034 Forwards "Control of Heavy Loads at Nuclear Power Plants Grand Gulf Nuclear Station Unit 1. (Phase II)." draft technical evaluation rept SCHMENCER.A Licensing Branch 2 FIN A-6457 84/02/14 MCGAUGHY.J P Mississippi Power & Light Co 2pp 20408 308 24X Fiche 50-416.84/02/14,4002270034
- ---8402170216 Draft "Control of Heavy Loads at Nuclear Power Plants, Grand Gulf Nuclear Station Unit 1. (Phase II) " BEKOT, J P EG&G, Inc FIN A-6457 84/01/31 50pp 22408.310 24% Fiche 50-416.84/02/14.8402270034
- 8402270072 Final response to FOIA request for Commissioner voting & attendance records from 810401 to present Forwards documents listed on App A Documents also available in PDR FELTON.JM Division of Rules and Records 83/12/22 KAMENAR.P D Washington Legal Foundation 3pp 22410 109
- 8402270077 Submits addl info re proposed 42-inch Transco gipeline Analysis of steel structure showed that time for steel to reach 1.000 F is in excess of 60 s.while estimated burn time of gas cloud order of magnitude less CURTIS.N W Pennsylvania Power & Light Co PLA-2080 84/02/2i SCHMENCER.A Licensing Brench 2 2pp 22387 354 24% Fiche 50-387.84/02/21.8402270077
- 8402270166 Forwards draft FSAR changes to appear in Feb FSAR rev r. SER (NUREO-0971) Section 4 4 6. "Loose Parts Monitoring Sys."

 Table 4 1 Addl info requested in Table 4 1 should satisfy
 SER Confirmatory Issue 11

 KEMPER, J 5 Philadelphia Electric Co 84/02/21 SCHWENCER, A
 Licensing Branch 2 21pp 22386 043 24X Fiche 50-352,84/02/21,8409270166
- B402270207 NUREO/CR-3127
 PROBABILISTIC SEISHIC RESISTANCE OF STEEL CONTAINMENTS
 GREIMANN.L. FANOUS, F, KETELAAR, D Iowa State Univ., Ames, IA FN
 A-4132-2 B4/01/31 Division of Engineering, 132pp, Available
 at NRC \$5 00 22397 225
- 8402270212 Forwards request for addl info re review of NUREG-0737. Item III D 3 4. "Control Room Habitability " Provision of info requested within 60 days of itr receipt CRUTCHFIELD, D Operating Reactors Branch 5 L805-84-02-045 84/02/22 FIEDLER, PB Gameral Public Utilities GPU Service Corp 3pp 22384 360 24X Fiche 50-219,84/02/22,8402270212.
- B402270213 NUREO/CR-3541
 EDDY CURRENT ROUND ROBIN TEST ON LABORATORY PRODUCTED
 INTERGRANULAR STRESS CORROSION CRACKED INCONEL GTEAM
 GENERATOR TUBES
 BICKFORD, R L , CLARK, R A , DOCTOR, P Q Battelle Memorial Institute,
 Pacific Northwest Laboratory FIN B-2097 PNL-4695 B4/01/31
 Division of Engineering Technology 130pp Available at NRC
 \$5 00 22395 263
- 8402270234 "Annual Operating Rept.1983 " W/840220 ltr LARSON, C.E. Northern States Power Co. 83/12/31, KEPPLER, J. Q. Region 3, Office of Director 6pp 22386 325, 24X Fiche 50-282,83/12/31,8402270234
- 8402270239 Forwards "Control of Heavy Loads (C-i0), San Onofre Nuclear Generating Station, Unit 1." draft technical evaluation rept. Addl info requested re listed areas within 48 days of 1tr receipt CRUTCHFIELD, D. Operating Reactors Branch 5 LSO5-84-02-046 84/02/22 BASKIN, K.P. Southern Callfornia Edison Co. 3pp. 22384 237 24X Fiche 50-206,84/02/22,8402270239
- --8402270233 TER-C5306-392
 "Control of Heavy Loads (C-10). Ban Onofre Nuclear Generating
 Bitation, Unit 1." draft technical evaluation rept
 BOMBERGER.C. AHMED.N'. SARGENT, I. H., Franklin Institute/Franklin
 Research Center. NRC-03-81-130 TAC 08082. 83/04/05
 CLEMENSON.F NRC No Detailed Affiliation Given. 41pp
 22386-240 24X Fichs 50-206.84/02/22,8402270239

8402280014 NUREG/CR-3412

- 840:2270243 Forwards responses to items requiring resolution resulting from MRC review of radiological emergency response preparedness plan published in Suppl 3 of NUREG-0798 Items reviewed w/F Xantor of MRC.in 840201 telcon JEMS.W H Detroit Edison Co EF2-57.132 84/02/23 YEMMSLOOD.B J Licensing Branch 1 28pp 22386 196 24X Fiche 50-341.84/02/23.8402270243
- 8402270263 Responds to FDIA request for JC Mark 801204 memo to ACRS re hydrogen burn wrigniters & documents concerning generation, combustion or control of hydrogen in reactor accidents Forwards App A documents App B documents in PDR FELTON, J M Division of Rules and Records 84/01/30 HIATT, 8 L Ohio Citizens for Responsible Energy 7pp 22412 051 24X Fichs 50-000, 84/01/30, 8402270263
- --8402270351 Comments on NUREG/CR-1762. "Analysis of Hydrogen Mitigation for Degraded Core Accidents in Sequoyah Nuclear Power Plant "Strong recommendation that ignitors at top of ice condensers be removed debatable MARK.J C ACRS Advisory Committee on Reactor Safeguards BL/02/02 ACRS Advisory Committee on Reactor Safeguards 5pp 22412 156 24X Fiche 50-000.84/01/30.8402270263
- 8402270359 Comments on Suppl 1 to NUREO-0683, programmatic EIB re decontamination & disposal of radwaste Estimates of worker exposure not addressed DOMERTY.JF Boherty.JF 84/02/18 NRC - No Detailed Affiliation Given 4pp 22391 153 24X Fiche 50-320,84/02/18.
- 8402270362 Bubmits comments on DES (NUREO-1033) re operation of facility Evel cycle impact not completely described DOMERTY. J F Affiliation Not Assigned 84/02/19 VIETTI.A Division of Licensing 2pp 22391 189 24% Fiche 50-508,84/02/19.8402270362
- 8402270426 Forwards IE Insp Repts 50-254/83-30 & 50-265/83-31 on 831205-840131 No noncompliance noted 8402/10 REED, C Commonwealth Edison Co 2pp 22390 207 24X Fiche 50-254,84/02/10 8402270426
- --B402270432 IE Insp Repts 30-254/83-30 & 50-265/83-31 on 831205-840131 No noncompliances or deviations identified Major areas inspected previous insp findings, operational safety, maint, surveillance, LERs, IE bulletin followup & reactor scrams CHRIBSOTIMOS, N. MORRONGIELLO, A. WALKER, R. D. Region 3, Office of Director 50-265/83-31 84/02/09 12pp 22390 209 24X Fichs 50-254.84/02/10,8402270426
- B402270427 Discusses mod of automatic depressurization sys logic, per NARC-0737. Item II K 3 18 Proposes that NRC allow bypassing inhibit switch on Unit 2 until first refueling outage on Unit 1 CURIIE.N W. Pennsylvania Power & Light Co PLA-2070 84/02/22 SCHNENCER, A Licensing Branch 2 Ppp 22387 344 24X Fiche 50-387.84/02/22,8402270427
- 8402270434 Forwards Class III & I licensing fees.per 840203
 request Mod of order re schedule for completion of
 MURRO-0737. Item IIF i concering noble gas steam
 installation requested
 LUNDVALL,A E Baltimore Gas & Electric Co 84/02/16 MILLER, J R
 Operating Reactors Branch 3 1p. 22390 247 24x
 Fiche 50-317.84/02/16.8402270454
- 8402270495 Forwards revised pages to pump & valve testing program, categorizing prossure isolation valves as ac according to ABME Bection XI, per SER (NUREO-0857)

 WAN BRUNT, E. E. Arizona Public Bervice Co. ANPP 28907 WFG/
 84/02/17 KNIGHTON.0 Licensing Branch 3. 6pp 22389 258 24X
 Fiche 50-528,84/02/17.8402270495
- 8402270604 Approves priority ranking of DROF for Deneric Issue 34 re RCS leak Encl prioritization evaluation will be incorporated Into MUREG-0933, "Prioritization of Generic Safety Issues " DENION.H R. Office of Nuclear Reactor Regulation, Director 84/02/07, THOMPSON.H.L. Division of Human Factors Safety 5pp 32414 017. 24X Fiche 50-261,84/02/07,8402270604
- 8402270528 Forwards prioritization evaluation approving NRR actions necessary to resolve Generic Issue 36, "Loss of Svc Water (Celvert Cliffs Unit 1) " Evaluation will be incorporated into MURES-0933 SENTON H R Office of Nuclear Reactor Regulation, Director 84/02/15 MATTEON,R J Division of Systems Integration (pust 811005) 18pp 22412 339 24X Fiche 30-317,84/02/15,8402270628
- 8402290006 NUREG/CR-3585
 DE HINIMIS WASTE IMPACTS ANALYSIS METHODOLOGY
 DITUNALI.O I Dames & Moore, ROLEG, G W NRC No Detailed
 Affiliation Glyen FIN 8-7318 84/02/29 Division of Waste
 Management. 531pp 22415 001

- 8402280010 NUREG/CR-3512
 RAPID FIELD METHOD FOR THE CONCENTRATION OF RADIOIODINE FROM MILK
 SOLBBIGS R M , HUCHTON:R L . MOTES:B G Exxon Nuclear Co . Inc (subs of Exxon Corp) FIN A-6287 ENICO-1137 84/02/29 Division of Facility Operations 24pp 22429 280
- CONTAINMENT INTEGRITY PROGRAM QUARTERLY REPORT JANUARY-MARCH 1983 BELJWAS,TE, HORSCHEL,DS, JUNG,J Sandia Laboratories FIN A-1229 SANDB3-1482 84/02/29 Division of Engineering Technology 44pp 22429 308
- 8402280043 Forwards response to Generic Ltr 82-16 re MUREG-0737 Teth Specs Listed TMI items addressed KAY, J & Yankee Atomic Electric Co FYR 84-23 84/02/17 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 22401 i18 24X Fiche 50-029.84/02/17.8402280043
- 8402280030 Notifies that schedule for remaining info requested in Suppl 1 % to NUREG-0737 deferred to 850301 Revised schedule parmits completion of plan to integrate five emergency response capability programs
 WHITTIER: 0 D Maine Yankee Atomic Power Co GL-82-33 84/02/23 MILLER, JR Derating Reactors Branch 3 19 22400 279 24%
 Fiche 50-309,84/02/23,8402280050
- B402280114 NUREG/CR-3598
 OCCUPATIONAL RADIOLOGICAL MONITORING AT URANIUM MILLS
 SWAJA.R E , SIMS.C S Oak Ridge National Laboratory FIN B-0485
 ORNL-6023 84/02/29 Division of Facility Operations 97pp
 Available at NRC \$4 75 22416 199
- 8402280123 NUREO/CR-3329 VO3
 THERMAL/HYDRAULIC ANALYSIS RESEARCH PROGRAM QUARTERLY REPORT
 JULY-SEPTEMBER 1983
 ***THOMPSON.5 L Sandia Laboratories FIN A~1205 SAND83-1171
 84/02/29 Division of Accident Evaluation 84pp 22430
- 8402280210 Clarifies commitment re-performing NDE of all critical members & welds on reactor vessel head lifting rig in response to NUREG-0612 Exam will be performed prior to lifting reactor vessel head OIESLER:C W Wisconsin Public Bervice Corp NRC-84-32 84/02/24 VARGA, S A Operating Reactors Branch 1 lp 22399 278 24X Fiche 50-305, 84/02/24, 8402280210
- 8402280251 Confirms 840221 telcon re audit of detailed control room design review per Suppl 1 to NUREQ-0737 Audit scheduled for 840305-09 CRUTCHFIELD, D. Operating Reactors Branch 5 L805-84-02-053 84/02/24 LINDER: F. Dairyland Power Cooperative 2pp 22399 315 24X Fiche 30-407.84/02/24.8402280251
- B402280262 Atk receipt of 840209 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-416/E3-56 LEWIS.R C Division of Project & Resident Programs B4/02/17 RICHARD.J & Mississippi Power & Light Co ip 22398 318 24X Fiche 50-416.84/02/17.8402280262
- --B402280284 IE Insp Rept 50-416/83-56 on 831116-1213 Violations noted failure to document Tech Spec limiting conditions for operation when both diesel generators insperable & failure to failuw administrative procedures

 WARNER: A O Region 2, Office of Director JULIAN, C A Division of Project & Resident Programs 84/01/05 7pp 22398 336 24X Fiche 50-416,84/02/17,8402280262
- B402280344 Discusses 840708 ltr re problems associated w/operability of control room ventilation sys ammonia detectors, per NUREQ-0737, Item III D 3 4 Replacement detectors will be obtained, installed & operating by 841231.
 WITHERS, B D Portland General Electric Co 84/02/24 EIBENHUT, D G Division of Licensing 1p 22403 170 24X Fiche 50-344,84/02/24,8402280344
- 8402280453 Requests NRC review & approve use of installed reactor vessel level instrumentation sysper requirements of Generic Ltr 82-33, Suppl 1 to NUREG-0737 & TMI II F 2 STEMART.W L Virginia Electric & Power Co 057 84/02/23 DENTON.H R Defice of Nuclear Reactor Regulation, Director ElseNHUT.D Q. Division of Licensing 4pp 22407 058 24X Fiche: 50-880, 84/02/23, 8402280453
- 8402280517 Supple 840214 application flor amend to Licenses DPR-32 & DPR-37 re control room chlorine detection sys per NUREG-0737, Item III D 3 4 Encl attachments inadvertently omitted from previous submittel STEWART, W L. Virginia Electric & Power Co. 662D 84/08/21. DENTON, H R. Office of Nuclear Reactor Regulation, Director VARGA-5 A. Operating Reactors Branch i ip 22406-338 24X Fiche: 50-280, 84/02/21, 8402280817

- --8402280325 Proposed changes to Tech Specs re control room chlorine detection sys per TMI Item III D 3 4 * Virginia Electric & Power Co 84/02/21 8pp 22406 339 24X Fiche 50-280.84/02/21.8402280517
- 8402280597 Corrects error in 840209 response to open issues in draft technical evaluation rept re control of heavy loads Testing & maint program for spent fuel cask yolk in compliance wispecs
 ZIMMERMAN, 5 R Carolina Power & Light Co NLS-84-071 84/02/20 VASALLO.D D Operating Reactors Dranch 2 ip 22406 314 24X Fiche 50-324.84/02/20.8402280537
- 8402290002 Responds to FOIA request for currespondence NRC received from Senators J McClure.JB Johnston & P Laxalt during past 2 yrs Forwards App A documents Name of individual deleted from Documents 8 & 9 of App A (ref FOIA Exemption 6) FELTON.J H Division of Rules and Records B3/11/30 KOLI,E Cable News Network. Inc 6pp 22436 002 24% Fiche 50-000, 83/11/30,8402290002
- --8402270103 Forwards NRC rept to Congress on ADs at licensed nuclear facilities (NUREG-0070) for Third Guarter CYB1 W/o encl KAMMERER. C. Office of Congressional Affairs 82/03/10 OTTINOER. R. L. House of Rep , Energy & Commerce SIMPSON. A Senate. Environment & Public Works UDALL. M. House of Rep , Interior & Insular Affairs 1p 22438 032
- --B402270153 Forwards NRC rept to Congress on AOs at licensed nuclear facilities (NUREO-0090) for Second Gwarter CY82,per Section 208 of Energy Reorganization Act of 1974 M/o enci.
 KAMMERER.C Office of Congressional Affairs B2/12/30
 OTTINGER.R L House of Rep . Energy & Commerce SIMPBON.A
 Senates, Environment & Public Works UDALL,M House of Rep .
 Interior & Insular Affairs 1p 22438 043
- --8402290171 Forwards NRC rept to Congress on AOs at licensed muclear facilities (MUREG-0090) for First Guarter CYB2 M/o encl KANMERER. C Office of Congressional Affairs B2/08/19 OffINGER. R L House of Rep , Energy & Commerce BEVILL, T House of Rep , Appropriations HATFIELD, M Senate, Appropriations ip 22438 040
- --8402290178 Forwards NUREQ-0784, "Long-Range Research Plan " Plan covers FY84-86 W/o encl KAMMERER.C Office of Congressional Affairs 82/09/28 HATFIELD.M D Senate. Appropriations 1p 22438 046
- ---8402290313 Forwards Aug 1983 issue of NRC summary info rept (NUREG-0871) M/o encl KAMMERER, C. Diffice of Congressional Affairs 83/08/16 OTTINOER, R. L. House of Rep., Energy & Commerce SIMPBON, A Senate, Environment & Public Works UDALL, M. House of Rep., Interior & Insular Affairs & p. 22438 123
- ---B402290091 Forwards proposed splicy statement on safety goals for nuclear power plants, approved for publication in FR Rept discussing development of proposed policy statement, NUREG-0880, will be forwarded when available Wid encl KAMMERER, C. Office of Congressional Affairs. 82/02/11 OTTINOER, L. House of Rep., Energy & Commerce BIMPBON. A Senate, Environment & Public Works. UDALL.M. House of Rep., Interior & Insular Affairs. 1p. 22438 030
- --B402390ii4 Forwards announcement that NRC will hold i-day public meetings on proposed safety goals for nuclear power plants W/o encl KAMMERER.C Office of Congressional Affairs 82/03/3i DTTINGER.R L. House of Rep., Energy & Commerce SIMPBON, A Benate, Environment & Public Works UDALL.M House of Rep., Interior & Insular Affairs ip 22438 034
- 8408290100 Forwards response to MUREC-0737. Suppl i & Generic Ltr 82-33 re comparison of existing plant sys or planned improvements w/positions of Reg Guide i 97. Rev 2 GUCHA.L T Georgia Power Co NED-84-071 84/02/21 STOLZ.J F Operating Reactors Branch 4 336pp 22421 088 24X Ficha 50-321.84/02/21.8402290100
- 8402290154 Requests time extension for submitting addl info re NUREG-0737. Item II D : concerning performance testing of relief & safety valves, since unit out of syc since feb 1982 KRIEGER.R W Bouthern California Edison Co 84/02/22 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 22428 146 24X Fiche 50-206.84/02/22.8402290154
- B402270244 Forwards IE Insp Rept 30-155/83-19 on B31119-840131 No noncompliance noted BMAFER: W D Region 3. Office of Director 84/02/15 DEWITT.R B. Consumers Power Co. 2pp 22427 309 24X Fiche 50-155,84/02/15, 04002000044

- ---8402290254 IE Insp Rept 50-155/83-19 on 831119-840131. No noncompliance or deviation noted Major areas inspected license action on previous insp findings, operational safety, maint, surveillance, LERs. TMI item review & fire protection.

 MRIGHT, G C. BOTYD, D C. Region 3. Office of Director 84/02/09 6pp 22427 311 24X Fiche 50-155,84/02/15,8402290244
- B402270262 Comments on NUREG-0683. Suppl 1 re dose reduction in EIB Practice of exception to regulation when encountering problem at TMI must be discontinued HERMANIA A Affiliation Not Assigned 84/02/24 SNYDER, B J THJ Program Office 2pp 22427 216 24X Fichs 30-320.84/02/24, 8402270262
- 8402290305 Forwards IE Insp Repts 50-277/84-02 & 50-278/84-02 on 840114-20 & notice of violation MARTIN.J S Division of Engineering & Technical Programs 84/02/15 DALTROFF, S t Philadelphia Electric Co 2pp 22427 338. 24X Fiche 50-277.84/02/15.8402290305
- --B402270317 IE Insp Repts 50-277/84-02 & 50-278/84-02 on B40116-20 Violation identified inadequate controls & training in util mod activities

 EAPEN.P K Region I. Office of Director GDDY.A T Division of Engineering & Technical Programs 50-278/84-02 84/02/13 Spp 22427 342 24% Fiche 50-277/84/02/15.8402270305
- 8402270325 Forwards IE Insp Rept 50-289/84-03 on 840114-20 Deficiencies identified re post-accident sampling & analysis Conference will be held on 840223 to resolve deficiencies MARTIN.T T Division of Engineering & Technical Programs 84/02/14 HUXILL.H D General Public Utilities GPU Bervice Corp 2pp 22426 332 24x Fiche 50-289,84/02/14,8402270325
- --8402290328 IE Insp Rept 50-289/84-03 on 840116-20 Deficiencies identified re provision for post-accident sampling & analyses Major areas inspected post-accident sampling of reactor coolant & containment atmosphere MILLER.M T . SHANBAKY.M M Region I. Office of Director HULLA P Brookhayen National Laboratory 84/02/09 20pp 22426 334 24X Fiche 50-289,84/02/14,8402290325
- 8402290362 Forwards corrected FR notice extending 45-day comment period on DES (NUREG-1026) to 840312 due to delay of delivery on 840113 YOUNGBLOOD, 0 J Licensing Branch 1 84/02/17 PERRIN, 6. Environmental Protection Agency 1p 22438 245 24x Fiche 50-456.84/02/17,8402290362
- ---8402270366 Corrected notice of availability extending comment parice on DES (NUREO-1026) to 840312 YOUNOBLOOD, B J Licensing Branch 1 84/02/15 8pp 22438 246 24X Fichs 50-436,84/02/17.8402270362

DRO CORRESPONDENCE WITH OTHER ORGANIZATIONS

- B312120153 JE Info Notice 84-06, "Steam Binding of Auxiliary Feedwater Pumps" Svc list encl
 JCRDAN.C L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/01/25 Consolidated Edison Co. of New
 York
- 8401190016 IE Info Notice 84-07, "Design-Basis Threat & Review of Vehicular Excess Controls" Syc list encl.

 JURDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/03 Consolidated Edison Co of New York, Inc 119pp 22114:177 24X Fiche 80-000.84/02/03.8401190016
- 8401190017 IE Bulletin 84-01, "Cracks in BWR Mark I Containment Vent Headers " Svc list encl BEYOUNG,R C Director's Office, Office of Inspection and Enforcement 84/02/03 Consolidated Edison Co of New York, Inc 102pp. 22177
- 8401190039 IE Info Natice 84-08, "10CFR50.7, 'Employee Protection '*
 Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/14. Consolidated Edison Co. of New
 York, Inc. 115pp 22345 141 24X Fiche 50-000,84/02/14,8401190039
- B401190041 lE Info Notice 84-09, "Lessone Learned From NRC Insps of Fire Protection Bafe Shutdown Sys (10CFR50, App R) " Bvc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/13 Consolidated Edison Co of New York, Inc 124pp 22365 259 24X Fiche 50-000,84/02/13,8401190041

- 8401190045 am Info Notice 83-63, Suppl 1, "Potential Failures of Nestinghouse Type BA-1 Differential Relays " Svc list encl JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/02/15 Consolidated Edison Co of New York, Inc 118pp 22366 142 24X Fichs 50-000,84/02/15,8401190045
- 8401190062 IE Info Notice 84-10, "Motor-Operated Valve Torque Switches Set Selow Manufacturer Recommended Value " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/21 Consolidated Edison Co of New York Inc 116pp 22366 024 24% Fichs 50-000.84/02/21.8401190062
- B4011700&6 IE Info Notice 84-11, "Training Program Deficiencies"
 Syc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/24 Consolidated Edison Co of New
 York, Inc. 115pp 22430 304 24X Fiche 50-000,84/02/24,8401190066
- B4D1190067 IE Info Notice 84-12, "Failure of Soft Seat Valve Seals "
 Syc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 84/02/27 Consolidated Edison Co of New
 York, Inc. 120pp 22431 060 24X Fiche 50-000.84/02/27,8401170067
- B402010160 Forwards "Evaluation of Georgia Power Co Emergency Preparedness Plan for EI Hatch Electric Generating Plant," final rept KRIMM.R W Federal Emergency Management Agency 84/01/24 JORDAN.B L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 22039 223 24X Fichs 50-321.84/01/24,
- --8402010165 "Evaluation of Georgia Power Co Emergency Preparedness Plan for EI Hatch Electric Generating Plant," final rept # Federal Emergency Management Agency 83/10/28 55pp 22039 225 24X Fiche 50-321,84/01/24,8402010160
- 8402010244 Forwards FEMA 840130 ltr to ASLB & FEMA 840111 memo providing responses to offsite emergency planning questions raised at 831017-18 limited appearance sessions in Phoenisville:PA VOCLER.B H Hearing Branch 2 84/01/30 BRENNER.L Atomic Safety and Licensing Board Panel 5pp 22040 187 24X Fiche 50-352;84/01/30.8402010244
- 840206008B Forwards consultants group draft rapt on implementation of intervention levels in event of radiological emergency involving transboundary situations SUBLOM, O.L. Environmental Protection Agency 84/01/31 DEYDUNG, R.C. Director's Office, Office of Inspection and Enforcement. 3pp. 2208B 143
- --8402060394 Draft "Rept of Consultants Group on Implementation of Intervention Levels in Event of Radiological Emergency "

 * Interventional Atomic Energy Agency 83/10/21 33pp
- 8402070130 Forwards Speck 840125 ltr & Dircks 840126 response to FEMA review of util offsite emergency plan Certificate of Svc encl.

 BORDENICK, B M Hearing Branch 3 ISSUANCES OL 84/01/31
 LAURENSON, J A , KLINE, J R , SHON, F J Atomic Safety and Licensing Seard Panel. 4pp. 22100 201 24X Fiche 50-322,84/01/31,8402070130
- --9402070134 Inquires whether FEMA should continue modify or terminate NMC review of util emergency plan given Governor Guomo recent interpretation as to legal authority of util to implement plan.

 BFECK, S. W. Faderal Emergency Management Agency, 84/01/25
 DIRCKS, W. J. Office of the Executive Director for Operations 4pp 22100.205 24X Fiche:50-322.84/01/31.8402070130
- B4D2070376 Forwards joint exercise rept of B31101 exercise of bffeite radiological emergency preparedness plans for facility Bkate of HA & Manitowock & Kewaunes Gounties participated FRIMM.R W Federal Emergency Management Agency 84/01/30 JORDAN.E L Division of Emergency Freparedness & Engineering Response (Fost B30103) 2pp 22097 324 24X Fichs 50-305.84/01/30.8402070376
- --8402070379 Evaluation of offsite radiological emergency preparedness plan joint exercise rept for facility > Federal Emergency Management Agency. 83/12/14 45pp 22099:328 24X Fiche:50-305.84/01/30:8402070376
- 8402070422 Forwards request for DMB review & supporting statement re required actions based on generic implications of Balem ATMB events. NDRRY.P.O. Dffice of Administration 84/01/31 MACRAE.J B Office of Management & Budget 23pp 22142 103 24X Fiche 50-272, 84/01/31.8402070422.

- 8402080150 Forwards maths re adequacy of emergency planning at facility, including IE Insp Rept 50-289/93-35 which sets forth findings & conclusions of staff who observed exercise & INPO 831128 Itr re findings ZAHLER, R E Shaw. Fittman. Potts & Trowbridge 84/02/03 CHILK, S J Office of the Secretary of the Commission 24pp 22132 231 24X Fiche 50-289,84/02/03.8402080150
- B402070060 Forwards interim finding on offsite radiological emergency planning State of IL & Ogle & Winnebago Counties offsite plans acceptable KRIMM.R W Federal Emergency Management Agency 84/02/01 JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 21pp 22159 198 24X Fiche 90-454. B4/02/01.8402070060
- 8402070204 Forwards evaluation of 831115 joint exercise of offsite radiological amergency preparedness plans State of IL & Ogle & Winnebago Counties participated KRIMM.R W Federal Emergency Management Agency 84/02/01 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 22163 150 24X Fiche 50-454,84/02/01,8402070204
- --8402090207 Evaluation of 831115 joint exercise of offsite radiological emergency preparedness plans
 * Federal Emergency Management Agency 84/01/09 35pp 22163 152 24X Fiche 50-454,84/02/01.8402090204
- B402070211 Forwards revised evaluation of State of KS radiological amergency preparadness plan for facility KRIMM.R W Federal Emergency Management Agency 84/02/02 JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 2pp 22158 033 24X Fiche 50-482,84/02/02.8402070211
- ---B40207021B Revised evaluation of State of KS radiological emergency preparedness plan for facility + Federal Emergency Management Agency B4/01/05 26pp 2215B 035 24% Fiche 50-482.84/02/02:8402070211
- 8402090237 Forwards evaluation of PO&E emergency preparedness plan for Diablo Canyon KRIMM,R W Federal Emergency Management Agency 84/02/02 JERDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 22157 288 24X Fiche 50-275,84/02/02. 8402090237
- --8402090247 Evaluation of PG&E emergency preparedness plan for Diablo Canyon * Federal Emergency Management Agency 83/12/06 30pp 22197 290 24% Fiche 50-275,84/02/02.8402070237
- 8402090280 Forwards request for OMB review & supporting statement re ACCFRSS 41 & ICCFRSS.App A NORRY.P O Defice of Administration 84/02/08 MACRAE.J B Office of Management & Budget ip 22177 351
- B40209029B Requests response to NRC concurrence on potassium iodide statement of federal radiological preparedness coordinating committee KRIMM.R W Federal Emergency Management Agency B4/02/02 JRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) ip 22160 173
- 8402070336 Forwards evaluation of State of PA radiological emergency preparedness plan for TMI KRIMM.R W Federal Emergency Management Agency 84/02/07 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 5pp 22161 173 24X Fiche 50-287,84/02/07,8402070336
- --8402090339 Evaluation of State of PA radiological emergency preparadness plan for TMI # Federal Emergency Management Agency B3/12/20 160pp 22161 178 24X Fiche.50-FB9/84/02/07/8402090336
- 8402100228 Forwards joint exercise rept of 830914 exercise of offsite radiological emergency preparedness plans for Pacilities State of IL & Grundy, Kendail & Will Counties participated KRIMM. R W Federal Emergency Management Agency 84/02/06 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 22179 226 24% Fiche 50-010,84/02/06.8402100228
- --8402100233 Evaluation of joint exercise rept of 830714 exercise of offsite radiological emergency preparedness plans for facilities * Federal Emergency Management Agency 89/12/13 35pp 22179 228 24X Fiche, 50-010,84/02/04,8402100228.

- 8402100430 Forwards request for QMB review & supporting statement re Form 354. "Data Rept on Spouse" NORRY.P G Office of Administration 84/02/09 MACRAE.J B Office of Management & Budget ip 22212 308
- 8402100434 Supports proposed Section 2741 MOU for states participating in low level waste compacts Viable method of giving states appropriate legal authority to conduct inspinecessary WIGGINE A Atomic Industrial Forum 83/11/30 Office of State Programs: Director ip 22212 362
- 8402100448 Comments on proposed 2741 MBU for states participating in low level waste compacts Statement 5 re insp of Federal premises should not be altered or deleted COFFMAN.F E Energy. Dept of 83/12/02 KERR.G W Office of State Programs, Director 1p 22213 015
- 8402:30330 Comments on FEMA B3:206 ltr & final evaluations of B1:028 & 820728 emergency preparedness exercises No major deficiencies identifiae PAPERIELLO.C J Region 3, Office of Director 84/02/07 LIU.L lowa Electric Light & Power Co 1p 22:97 i95 24X Fiche 30-331.84/02/07.8402:30330
- --8402130335 "Evaluation of Implementation of State & Local Radiological Emergency Response Plans " Exercise conducted on 820728 * Federal Emergency Nanagement Agency 82/07/28 11pp 22197 196 24X Fiche 50-331,84/02/07.8402130330
- B402130358 Evaluation of LAPL & State of LA emergency preparedness exercise on 840208 for Waterford Unit 3 * Federal Emergency Management Agency 84/02/08 281pp 22197 288 24x Fiche 50-382.84/02/08.8402130338
- 8402130498 Responds to FOIA request for SECYs 83-268,271,278,281,299, 305,306 & 307 Forwards SECY 83-271,83-278 & portions of five other SECYs as listed on App A Info partially withheld (ref Exemptions 5 & 7)
 FELTON, J M Division of Rules and Records 83/11/20 WEISS, E R Harmon & Weiss 4pp 22237 220 24X Fiche 50-000.83/11/28, 8802130498
- --8402130533 Responds to 83070B telcon request Util prepared to support exercise of "Radiological Emergency Response Interim Plan for Implementing Compensating Measures for Rockland County," during which 83080B BAYNE,JP Power Authority of the State of New York JPB 42-83 83/07/11 PETRONE,F Federal Emergency Management Agency ip 22237 339 24% Fiche 50-000,83/11/28.8402130498
- 8402140127 Forwards FEMA comments on ASLO decision MODREJ E Hearing Branch I ISSUANCES SP 84/02/06 CHILK, 6 J Office of the Secretary of the Commission 1p 22218 249 24X Fiche 50-247,84/02/06,8402140127
- --8402140133 Response to ASLB 831024 recommendation to Commission # Federal Emergency Management Agency 84/01/30 110pp 22218 279 24% Fiche. 50-247. 84/02/04.8402140127
- 8402150119 Discusses review of util offsite emergency plan under request from NRC FEMA makes recommendations to NRC but ultimate judgement of sufficient level of planning & preparedness lies w/NRC W/Certificate of Svc JETT, 0 W Federal Emergency Management Agency ISSUANCES OL-3 84/02/10 DRDNN, H H Kirkpatrick, Lockhart, Hill, Christopher & Phillips 4pp 22249 265 24% Fiche 50-322,84/02/10.8402150119
- 8402150137 Forwards request that full-scale participation by affected local govts & substantial participation by State of BC not be required FEMA will support exemption from 10CFR50, App E. Section IV F 1
 KRIMM.R Federal Emergency Management Agency 84/02/09
 JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 3pp 22250 019 24X Fiche 50-395,84/02/08,8402150137
- 8402130221 Forwards evaluation of TVA radiological emergency preparedness plan for Browns Ferry for 831115-16 exercise. State of AL & Lauderdale-Lawrence, Limestone & Morgan Gounttes participated KRIMNR W Federal Emergency Management Agency 84/02/08 JURDAN, EL Division of Emergency Preparedness & Engineering Response (Fost 830103) ip 22244 251 24X Fiche 50-259,84/02/08,8402150221
- --8402150237 Evaluation of TVA radiological emergency preparedness plan for Browns Ferry for 831115-16 exercise * Federal Emergency Managament Agency 83/12/16 28pp 22244 252 24X Fiche 50-259.84/02/08.8402150221.

- 8402150332 Forwards 830916 interim finding on util 831227 addendum to interim finding.comments on EL Quarantelli rept & response to civil defense concerns, per NRC 830325 request Test plan exercise scheduled for 840208 KRIMM.R W Federal Emergency Management Agency 84/02/07 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 72pp 22251 122 24X Fiche 50-382. 04/02/07.8402150332
- 8402150370 Supports NRC exemption for state & local govt participation in annual radiological preparedness exercise for facilities on B40229 KRIMM R Federal Emergency Management Agency 84/02/0B JDRDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) ip 22242 135 24X Fiche 50-206,84/02/08, B402150370
- 840216003B Forwards request for DMB review & supporting statement re 10CFR31 concerning general domestic licenses for byproduct mat1 NDRRY,P G Office of Administration 84/02/14 MACRAE.J B Office of Management & Budget ip 22281 351
- B402160359 Forwards FEMA final exercise rept re B31116 joint exercise of state & local radiological emergency preparedness plans Five Category A deficiencies identified MARTIN.T T Division of Engineering & Technical Programs B4/02/10 MUXILL.H D General Public Utilities OPU Service Corp 3pp 22273 001 24X Fiche 50-289,84/02/10,8402160359
- --8402160362 Evaluation of State of PA & Counties of Dauphin, York, Lancaster, Cumberland, Lebanon, Berks, Schuykill, Snyder & Union emergency preparedness plans for TMI-1 * Federal Emergency Management Agency 83/12/20 161pp 22273 004 24X Fiche 50-289, 84/02/10, 8402160359
- 8402160371 Notifies of 831018 meeting w/util, FEMA & States of NE & IA in Chaha, NE, to discuss scenario for 831207 radiological embrgency response exercise Util should be prepared to discuss narrative & controller cards development SEIDLE, W C Region 4, Office of Director 83/10/06. JONES, W C Chaha Public Power District 2pp 22249 122 24X Fiche 50-285,83/10/06,8402160371
- 8402170264 Forwards request for CMB review & supporting statement re 10CFR70 concerning domestic licensing of SNM NORRY,P © Office of Administration 84/02/16 MACRAE,J B. Office of Management & Budget ip 22313 332
- 8402210076 Forwards FEMA final exercise rept for 83:116 joint exercises of state & local radiological emergency preparedness plans for TMI-1 due to Category A deficiencies noted in three areas
 - MARTIN, T T Division of Engineering & Technical Programs. B4/02/LO DALTROFF. B L Philadelphia Electric Co 3pp 22317 333 24X Fiche 50-000,84/02/10,8402210096
- --8402210102 Exercise evaluation rept of Commonwealth of PA & Dauphin, York, Lancaster, Cumberland, Lebanon, Berks, Schuykill, Snyder & Union Counties emergency preparedness plans # Federal Emergency Management Agency 83/12/20 157pp. 22317 336 24X Fiche 50-000,84/02/10,8402210096
- 8402220239 Forwards FEMA final exercise evaluation rept of exercise conducted on 83:116 Category A & B deficiencies identified.

 MARTIN.T T Bivision of Engineering & Technical Programs 84/02/15

 KANGA, B K General Public Utilities ~ 9U Service Corp. Spp.

 22330 172 24X Fichs. 50-320.84/02/15.8402220259.
- --8402220263 Emergancy preparedness exercise evaluation rept of exercise conducted on 831116
 # Faderal Emergancy Management Agency 83/12/20 158pp
 82330 175 24% Fiche 50-320,84/02/15.8402220259
- 8402270266 Forwards complete FEMA final exercise tept of B30712 radiological emergency preparedness exercise PAPERIELLD, C. J. Region 3. Office of Director 84/02/23. REED, C. Commonwealth Edison Co. 1p. 22386 067 24% Fiche 50-373,84/02/23,8402/270266
- 8402280713 Forwards joint NRC/FEMA querterly status rept on emergency preparedness for Oct-Dec 1983 Rept describes actions taken to upgrade emergency preparedness at sites.
 PALLADINO, N J Commissioners GIUFFRIDA, L O, Federal Emergency Management Agency 84/02/14 SIMPSON, A K Senate, Environment & Public Works Sipp 22414 282
- 8402290398 Forwards request for CMB review & supporting statement re 10CFR32 concerning specific licenses to mfg or transfer certain Items containing byproduct matl. NCRRY.P G Office of Administration 84/02/28 MACRAE, J. B Office of Management & Budget ip 22437 245

PROPOSED RULE

- 8401050255 Comments on proposed rules 10CFR2 & 72 re hybrid hearing procedures for expansions of onsite spont fuel storage capacity. Option 2 acceptable BRADBURY.R B Stone & Webster Engineering Corp 4BFR54479 003 B3/12/20
- 8402030345 Comments on proposed rules 10CFR30.40 & 190 re changes to requirements for reporting transfers of source matl Recommends wording to changed to include U metals intended for use to permit shipment of shielding components MCGOVERN.J J Union Carbide Corp 48FR93714 016 84/01/30 Decieting & Services Branch 2pp 22067.145
- 8402030346 Comments on proposed rules 10CFR30,40 & 150 re tritium & source metl repts. Recommends language of Section 180 17(d)(4) be changed to include U metals intended for use as permanently installed metal M1001M.E A Atomic Industrial Forum 48FR53714 017 84/01/30 Docketing & Services Branch 2pp 22089 154
- 6402030351 Comments on proposed rules 100FR30.40 & 150 re tritium & OPEGOGOS Comments on proposed rules 100FR30,40 & 150 re treduces meth repts. Requests Bubparagraph (6) be added to stempt reporting of natural or depleted U metals or alloys by DOD for use in military equipment or munitions, MALKER, L.D. Army. Dept of, 48FR53714 015 84/01/27 & Bervices Branch. ip 22069, 127. Dacketino
- 8402030353 Patkage of two comments supporting proposed rule 10CFR20. "Improving Personnel Dosimetry" HICKEY.J.E. Rhode Island, State of. GUILLIN.R.M Ohio. State of 49FR1205 84/02/01 Docketing & Bervices Branch 2pp TFH1205 84/02/01 22059-128
- 8402030334 Package of four comments supporting proposed rule 10CFR20, "leproving Personnel Dosimetry "
 GODWIN, A V Alabama: State of, RUTLEDGE, B Q Georgia, State of, Bept. of Human Resources BONNIE, T M Virginia, Commonwealth of, 49FR1205, 84/01/30, Docketing & Services Branch 4pp 22067, 136
- 8402030390 Comments on proposed rules 10CFR30,40 & 150 re tritium & source met1 repts. Submits several concerns to be addressed VEST.Q.D. Air Force, Dept. of 48FR33714 014 84/01/27 ROBERTSON Docketing & Services Sranch 1p 22066 030.
- 8402080177 Comments on proposed rules 10CFR30,40 & 150 re amend to reporting requirement for transfers of source mat1 Opposes rule Present reporting level of 1,000 kg should be maintained.

 84087-L.A. Amersham Corp. 48FR53714 018, 84/01/30 Docketing Services Branch. 2pp. 22128;272 Docketing &
- 8402080179 Comments on proposed rules 10CFR30, 40 & 150 re reducing min reportable transfers & inventory changes of U & thorium. Change would involve considerable reporting burden Shipments of U for non-nuclear end use should be exempted.

 CLARKE.E.T. Technical Operations, Inc. 48FR53714 019, 84/01/27 Bacieting & Services Branch 2pp 22128:317.
- 8402080184 Comments on proposed rule 10CFR20 re improved personnel dominatry processing. Absolute value of performance index w/o regard for sign should be used CRAIO.R.L. Okiahoma, State of, 49FR1205 84/01/31 Office of the Secretary of the Commission, 1p. #2128-324
- 8402080191 Package of four comments supporting proposed rule 10CFR20, "tagraved Personnel Dosimetry Processing."

 BRUCHAINN, 9 W. Hichigan, State of. LEAVITT, J. K. Oklahoma, State of. DONNT, D. K. North Dakota, State of. 49FR1205. 84/02/06.

 Office of the Bacretary of the Commission. 3pp. 22129'200
- 8402080225 Comments on proposed rule 10CFR20, "Improved Personnel Dosimetry Processing " Supports rule, EU-L.T., New Mexico, State of, 49FR1205 008, 84/01/27 Doct & Services Brench. 1p. 22130,133. Docksting
- 8402130378 Comments on proposed rule 10CFR20 re improved personnel fobiaetry processing Supports rule.
 8TOCKS-M.S. Indians, State of, 49FR1205 013 84/02/03.
 Docksting & Services Branch. 1p 22203-295.
- 8402i30403 Comments on proposed rule 10CFR20 re improved personnel desimilarly processing Alternative 3.Option B excellent Effective data of Feb 1986 ample to permit processors to begin participation in program.

 ALLEN. G. M. Kansas, State of 49FR1205 014 B4/02/06 CHILK, B. Office of the Becretary of the Commission ip 22203-296. CHILK, B. J.

- B4021702B0 Comments on proposed rule 10CFR20 re improved personnel desimetry processing Adoption of Alternative 3.Option 8 would improve accuracy in reported radiation dose data MCLAIN, E Radiation Measurement Systems, Inc. 49FR1205 018 84/02/09 Dacketing & Services Branch 2pp 22297 159
- 8402170288 Comments on proposed rule 10CFR20 re improved personnel dosimetry processing Suggests accreditation small be printed on each page from accredited processing lab LOVARS, A Colorada State Univ 49FR1205 016 84/02/08 Docketing & Services Branch 1p 22297 145
- 8402170293 Comments on proposed rule 10CFR20 re improved personnal dosimatry processing Concurs w/action proposed in Ref (a) Requests listed changes be implemented BAIETTI.A L ICN Pharmaceuticals. Inc (ICN-C&R Development) 49FR1205 015 84/02/08 Dacketing & Borvices Branch 2pp 22297.146
- 8402170295 Comments on proposed rule 10CFR20 re improved personnel dosimetry processing Supports rule HAZLE.A J Conference of Radiation Control Program Directors, Inc 49FR1205 017 84/02/09 Docketing & Services Branch 2pp 22297142
- 8402280382 Package of three comments supporting proposed rules 10CFR2 & 72 re hybrid hearing procedures for expansions of onsite spent fuel storage capacity at civilian nuclear power
- reactors MUSDLF, D. Northern States Power Co. KOEBTER, Q.L. Kansas Qas & Electric Co. LAHRENCE, M.J. Energy, Dept. of 48FR54499 84/02/27 Docketing & Services Branch. 12pp. 22402:234.
- 8402280406 Comments on proposed rule 10CFR50 on further protection against pressurized thermal shock Proposed amends presume that basis & assumptions NRC & industry use correct Deficiencies to rule listed.

 LEWIS.M I. Lewis, M 49FR4478 001 84/02/16 Office of the Becretary of the Commission 2pp 22407 141.
- 8402280465 Comments on proposed rules IOCFR2 & 72 re hybrid hearing procedures for expansion of onsite spent fuel storage capacity at civilian nuclear power reactors Opposes Option I Option 2 preferable-but inadequate COHAN.B 7 Atomic Industrial Forum. 48FR54499 012 84/02/21 CHILK, S J Office of the Secretary of the Commission 3pp 22404,350,
- 8402280487 Comments on proposed rules 10CFR2 & 72 re hybrid hearing procedures for expansion of onsite spent fuel storage capacity at civilian nuclear power reactors KEARNEY, J. Edison Electric Institute. 48FR54499 010 84/02/17 Docketing & Services Branch. 34pp 22402 314.
- 8402280502 Comments on proposed rules 10CFR2 & 72 re proposed hearing procedures for expansions of onsite spent fuel storage capacity at civilian nuclear power reactors Opposes rules KNOTTS, J B Bishop, Liberman, Cook, Purcell & Reyholds 48FR54479 Oil 84702/21, CHILK, B J Office of the Secretary of the Commission 18pp 22407:082
- 8402280510 Comments on proposed rules 10CFR2 & 72 rs change in hearing rules for used nuclear fuel storage Opposes rules LEMIS,M.I Lewis, M 48FR54497 009 83/12/13 Office of the Becretary of the Commission 1p 22407 215.
- B4022B0524 Package of two comments supporting proposed rule 10CFR20 re improved personnel dosimetry processing BHELLEY.N J. Kerr-McGee Corp. KGNITCH.L S. Labor, Dept. of 49FR1205 B4/02/24. Docketing & Bervices Branch 3pp 22406:347

PRM PETITION FOR HULEMAKING

- 8402050415 Commants on petition for rulemaking PRM-35-5 rs development of bone mineral analyzer requiring radiation source regulated by NRC Petition requests any health prof trained & experienced become licensed user in bone analyzers, ROBENBAUM,P. J. Nuclear Radiation Consultants. 84/01/19 Office of the Executive Director for Operations 1p. 22084-297
- 8402170291 Comments on petition for rulemaking PRM-20-14 re options for disposal of Very low concentrations of short-lived radionuclides No alternative methods of disposal investigated BILVIA:R. Marine Research: Inc. 49FR3667 001 B4/02/13 Docksting & Services Branch 1p. 22296:153,

- B4022B0402 Comments on petition for rolemaking PRM-20-14 re potential amend to NRC regulation for tritium & C-14 disposal Ruling usuld not affect college operation
 LAMPRA, J V Bunker Hill Community College 49FR3667 84/02/14
 Docketing & Services Branch 1p 22404 263
- 8402280494 Comments on petition for rulemaking PRM-20-14 re options for disposal of very low concentrations of short-lived radionuclides BENNEDETTO A R Texas, Univ of San Antonio, TX 49FR3667 004 84/02/21 Docketing & Services Branch 2pp 22402 287
- 8402280509 Package of two comments supporting petition for rulemaking PRM-20-14 re options for disposal of very low concentrations of short-lived radionuclides SCOTT, L M Gulf Oil Corp. BLAHD, W H , WETTERAU, L W Veterans Admin Hosp , Los Angeles, CA 49FR3667 84/02/27 Docketing & Services Branch 3pp. 22404 287

PROJ PROJECTS - PREDOCKET LICENSING

- 8402040207 Provides comments re proposed schedule in response to 831116 ltr submitting clarification of Hestinghouse objectives concerning application for preliminary design approval of RESAR-8P-90 DENTON, H R Office of Nuclear Reactor Regulation, Director 84/01/25 RAHE, E P Westinghouse Electric Corp 2pg. 22103 184
- 8402080422 Forwards "Topical SAR for Castor V Cast ISFSI (Dry Storage)," per 10CFR72 ROLLINS, J D General Nuclear Systems, Inc. 20259 83/12/16 ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 3pp 20174 3135
- --8402080425 "Topical SAR for Castor V Cask ISF8I (Dry Storage) "
 4 General Nuclear Systems, Inc. 23259 83/12/31 749pp
- 8402130633 Comments on Dames & Moore rept, "Beismic Hazard Analysis, West Valley Demonstration Project," per request Methods used to characterize Mest Valley site seismology reasonable & in general agreement w/pertinent NRC studies

 CLARK, A T Advanced Fuel & Spent Fuel Licensing Branch 84/02/06

 HANNUM, W H Energy, Dept of 3pp 22216 001
- --B402130638 Provides add1 comments to remarks contained in 831110 ltr to f Wimpey of Science Applications Inc re Dames & Moore Hest Valley Demonstration Project seismic hazard analysis rept ALEXANDER: S B Affiliation Not Assigned 23302 B4/01/20 HURT, D Advanced Fuel & Spent Fuel Licensing Branch ip 22216 004
- 8402140612 Responds to comments on summary minutes of 831220 update meeting re contamination find at West Valley Demonstration Project Project strategy is to first identify & isolate source term HANNUM. W.H. Energy, Dept. of, Idako Operations Office 23292. 84/01/27 CLARK. A.T. Advanced Fuel & Spent Fuel Licensing Branch ip 2228 143
- 8402230313 Summary of 840209 meeting w/Gesellschaft für Nuklear Svc in Silver Spring,MD re topical rept reviews for dry spent fuel storage cask design ISF81 ROBERTB.JF Advanced Fuel & Spent Fuel Licensing Branch, 84/02/15
- 8408230339 Summary of 840201-02 meetings w/desellschaft fur Nuklear Svc in Livermore,CA re safety review of topical SAR re Castor Ic nodular cast iron cask design. ROSERTS.JP Advanced Fuel & Spent Fuel Licensing Branch ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 299 22077-034
- 8402280666 Forwards "Transuranic Waste Certification Program Plan for West Valley Demonstration Project " Comments requested by 831028 HANNUM, W. H. Energy, Dept. of, Idaho Operations Office, 83/10/11. CLARK, A. T. Advanced Fuel & Spent Fuel Licensing Branch 3pp 22429 016
 - 3402280668 "Transuranic Waste Certification Program Plan for Hest Valley Demonstration Project " * Energy, Dept of, Idaho Operations Office. B3/09/30 39pp 32427-020

- 8402280676 Forwards response to 830825 questions re disposed area Quantity of isotopes extremely low HANNUM, W H Energy. Dept of, Idaho Operations Office 83/10/14 CLARK, A T Advanced Fuel & Spent Fuel Licensing Branch 4pp 22414 359
- PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE
- 8402010253 Part 21 rept re potential interference in full function of Bergen-Paterson strut assembly w/Pacific Scientific Commechanical shock arrestor Attempt to obtain corrective action from manufacturer unsucessful BECKSTED, W F Bergen-Paterson Pipe Support Corp 81/03/06, GRIER, B H Region I, Philadelphia, Office of the Director (91/03/01) 2pp 22040 205 24X Fiche 50-000, 81/03/06, 8402010253
- B402030315 Part 21 rept re unsecured wire terminations on Knox fuse blocks Two separate single 14 tab terminal wire terminals found loose in cubicles Recommends tab terminals be relocated from lower clamp to upper clamp area of connector. DWYER.F W General Electric Co 84/01/26 DEYOUNG.R. Director's Office. Office of Inspection and Enforcement 25pp 22055 120 24) Fiche 50-382.84/01/26,8402020315
- 8402030216 Revised interim Deficiency Rept DER 83-57 re cracks in control element assembly shroud Final rept will be completed by 840615
 VAN BRUNT.E E Arizona Public Service Co DER 83-57 84/01/20.
 BISHDP.T W Division of Resident Reactor Project & Engineering Programs 3pp 22067 217 24X Fiche 50-528,84/01/20.8402030216
- --8402030219 Forwards proprietary "Interim Rept on Performance Evaluation of Palo Vorde Control Element Assembly Shroud " Encl withheld (ref 10CFR2 770)
 FERGUSON, C Combustion Engineering, Inc V-CE-19414. 84/01/19
 VAN BRUNTLE E Artione Public Service Co lp. 22067 220 24X
 Fithe 50-528
- --8402030222 Affidavit of AE Scherer requesting proprietary CEN-267(V)-P re performance evaluation of control element assembly shroud be withheld (ref 10CFR2 790)
 SCHERER.A E Combustion Engineering, Inc 84/01/19, 4pp.
 22067 221 24X Fichs 50-528.84/01/20,8402030216
- 8402030298 Part 21 rept re athylene propylene elastomers in contact w/lubricant Mobil 28 Bettis engineering developing torque data for all nuclear actuators, including effects of increased friction due to seal swell LOCABCIO.A T GM-Bettis Corp 84/01/31. DEYDUNO.R. Director's Office, Office of Inspection and Enforcement 3pp 22066:254.
- 8402030297 Part 21 rept re potential problem w/battery ground detector relay IYE 278 Portions of solid state circuitry can be overstressed under certain operating conditions. Users of relay suil be notified. List of users of relay encl DUVALL.D.O Brown Boveri Corp (subs. of Brown Boveri & Co., Ltd.). 84/01/05 DEYGUNG, R C Director's Defice. Office of Inspection and Enforcement 3pp 22067,122 24X Fiche. 50-000, 84/01/05, 8402030299
- 8402030455 Rev i to final Deficiency Rapt DER 82-51 re Pullman-Kelleg pipe line failure in exsential cooling water sys Initially reported on 820910 Rev restates reportability under 10CFR21 VAN BRUNT, E E Arizona Public Bervice Co DER 82-51 84/01/19. BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 13pp 22069, 043. 24X Fiche 50-528, 84/01/19, 8402030455
- B402060500 Final Deficiency Rept RDC 78(83) re exhaust line back pressures exceeding manufacturers recommendations on diesel generators for HPCB sys Initially reported on 830805, Reported per Part 21 by Oilbert Assoc on 830727, EDELMAN, M. C. Cleveland Electric Illuminating Co. RDC 78(83) B4/01/30 KEPPLER, J. O. Region 3. Diffice of Director 2pp. 82083 112 84% Fiche 50-440.84/01/30,8402060500
- 840R060507 Final Deficiency Rept RDC 84(83) re Transamerica Delaval, Inc engine mounted fuel oil line on diesel generator engines initially reported on 831011 Rework on lines will be completed by 840601 Also reported per Part 21 by vandor EDELMAN,M R Cleveland Electric Illuminating Co RDC 84(83), 840/01/30 KEPPLER,J O. Region 3, Defice of Director 2pp. 22083 110 24X Fiche 50-440,84/01/30,8402040507
- 8402070344 Part 21 rapt re, svc water & circulating water pump house structure defect Analysis & design of structural mode to compression members re shrinkage effects approx 75% complete Next rept will be provided by 840227 KREIDER.H 0 United Engineers & Constructors, Inc. (subs. of Raytheon Co.) 84/01/31 Director's Office, Office of Inspection and Enforcement 3pp 22076 167 24% Fiche 50-443,84/01/31, 8402070344.

- 8402070365 Part 21 rapt re linear converter device w/possible generic defect Initially reported on 840116 Written notifications issued Customer responses should be received by 840331 Final rept will be submitted by 840430 DDSSON, J P Pacific Air Products Co 84/01/30 Director's Office, Office of Inspection and Enforcement 2pp 22114 299 24X Fichs 50-280, 84/01/30, 8402070365
- --8402070373 Part 21 rept re linear converter device w/possible generic defect Initially reported on 840116 Preliminary analysis indicates excessive wear of brass shaft guides Next rept will be submitted within 70 days Supporting info encl DODBONs.J.P Pacific Air Products Co 84/01/17 POTAPOVB.U Region 4, Office of Director 60pp 22114 301 24x Fiche 50-000,84/01/30,8402070365
- 3402070389 Biscusses potentially generic issue re Comsip. Inc. gas analyzer catalyst bed qualification life Vendor recommends replacement of std configuration catalyst beds Region I awaiting IE & ARCD reply STAROBTECKI.R. Division of Project & Resident Programs. B4/01/30 JORDAN.E.L. Director's Office, Office of Inspection and Enforcement Spp. 22095.107. 24X Fiche 50-000.84/01/30.8402070389
- 8402080200 Third interim deficiency rept re lack of Bingham-Williamette Co QA program for spare parts Initially reported on 830307 Cocrective actions narrowed to two listed options Next rept by 830114 Also reported per Part 21 MILLS.L.H Tennessee Valley Authority 84/01/30. C'REILLY.J P Region 2. Office of Director 2pp 22130 152 24X Fiche 30-438,84/01/30,8402080200
- 8402090283 Potential Part 21 rept re cable insulation damage found under outer jacket rework in one Class IE electrical cable investigation underway to determine safety significance & scope 1. ITTLEHALES, O Rockbestos Co 84/02/03 Region i, Office of Director 10 22157.349 24% Fiche 50-220.84/02/03.8402090283
- 8402130458 Final Deficiency Rept DER 83-86 re failure of C-E seismic analysis of shutdown HX to adequately address baseplate thickness. Initially reported on 831223 One-inch plates will be added to base plates Also reportable under Part 21 VAN BRUNT.E.E Arizona Public Service Co DER 83-86 84/01/26 BISHOP.T.M. Division of Resident.Reactor Project & Engineering Programs. 3pp 22202:115 24X Fichs.50-528,84/01/26,8402130458
- 8402140398 Requests add1 info re Part 21 rept dtd 831108 concerning.

 Mear ring failure in auxiliary feedwater pump furnished to
 facilities Info requested within 25 days.

 POTAPOVB.U. Region 4. Office of Director 83/11/30 PATTY.D.F
 Bingham-Hillamette Co ip 22221:250 24X Fiche:50-000,83/11/30,8402140398
- --8402140422 Supplemental Part 21 rept re wear ring failure in Auxiliary feedwater pumps, per 831130 request for addl info Wear rings will be replaced on returned units w/AISI 420 wrought matl. List of pumps in similar svc w/same wear ring encl PATTY.D F Bingham-Willamstts Co G3/12/20 Region 4, Office of Director, 2pp 22221 251 24X Fiche 50-000,83/11/30,8402140398.
- 8402140410 Buppl to final deficiency rept re failure of qualified cables on Transamerica Delayal generators to pass IEEE flame trut due to inadequate temp rating for cable insulation initially reported on 821214 Also reported per Part 21. MCGALOHY, J. P. Mississippi Power & Light Co AECM-84/0043. 884/02/02 0 (REILLY, J. P. Region 2. Office of Director 5pp 22220:338 24X Fiche.50-416,84/02/02,8402140410
- B402140413 Final deficiency rept, Item 122 re Class IE 480-volt motor control ctr protective grommets supplied by Gould, Inc.
 Initially reported on 830425, Corrective action completed Also reported per Part 21.
 PASSONB, R. M. Carolina Power & Light Co NRC-176 84/01/31, O'AEILLY, J. P. Region 2, Office of Director 4pp. 22230: 332 24X Fiche: 50-400, 84/01/31, 8402140413.
- 8402140432 Second supplemental deficiency rept re bonnet studs fearmerly torqued on DHR valves. Initially reported on Bl1222. Completion not expected until 840915 due to missing bonnet stude. Also reportable per Part 21.

 MILLS.L.M. Tennessee Valley Authority 84/02/01 0'REILLY.J.P. Region 2. Office of Director 1p 22227-140 24X Fiche: 50-438,84/02/01,8402140432.
- B402150209 Final Deficiency Rept DER 82-73 re ITT Grinnell pipe support clamps in main steam supply sys having excess gap & not properly securing scope. Initially reported on 831223. Replacement clamps installed, Also reported per Part 21 VAN BRUNT, E.E. Arizona Public Service Co. ANPP-28763-88K/. 84/61/31. BISHOP, T.W. Division of Resident, Reactor Project & Engineering Programs 4pp 22241.001. 24X Fiche 50-529, 84/01/31, 8402150209.

- B402150272 Final Deficiency Rept DER B3-40 re low pressure safety injection & containment spray pump motors w/defective welds & leaking oil Initially reported on B30627 Defective welds identified & repaired Also reported par Part 21 VAN BRUNTLE E Arisona Public Service Co ANPP-28778-BSK/B4702/02 BISHOP.T.W Division of Resident Reactor Project & Engineering Programs 4pp 22242 342 24X Fiche 50-328,84/02/02.843250270
- 8402170005 Part 21 rept re fabrication of piping subassemblies having wall thickness less than required by design specs Cause & extent of incident under review Nuclear isometric drawings will be reviewed by 831028

 BARNES, R P. GOODMIN. B J. Southwest Fabricating & Welding Co. (subs of IV International Corp.). 83/10/17 POTAPOVS, V. Region 4, Office of Director. 3pp. 22301 134 24X Fiche 50-400.83/10/17.8402170005
- B402170146 Part 21 rept re wearing ring failure on auxiliary feed water pump Pumps w/potential for wearing ring problems being evaluated Existing users should review application for possible replacement of rings.

 PATTY, D F Bingham-Willamette Co 83/11/08 Region 4, Office of Director 1p. 22299 022 24X Fichs. 50-528. 83/11/08, 8402170146
- 8402170176 Final Part 21 rept re potential problem concerning radiography of branch connection welds covered by ruinforcing pads Welds at Byron Braidwood & North Anna acceptable Weld 7 at Clinton reradiographed BORNES, R P Southwest Fabricating & Welding Co (subs of IV International Corp.) 84/01/02 POTAPUS, V Region 4, Office of Director 2pp 22276 126 24X Fiche 50-000.84/01/02.8402170176.
- 8402170263 Final Part 21 rept re cable separations in control room panels Separate insps for other facilities scheduled prior to fuel load to identify & correct cabling separation not in compliance w/Spec i3-EM-306
 PATTERSON.R L Bechtel Corp 83/10/05 COLLINS, J T. Region 4, Office of Director. 3pp 22276.073 24x Fiche 50-528,83/10/05,8402170263
- 8402170279 Part 21 rapt re fabrication of piping subassemblies w/wall thickness less than required design specs No add1 deviations found Incident considered closed BORNES.R.F., GDODHIN.B.J. Southwest Fabricating & Welding Co. (subs of IU International Corp.) 83/10/25 POTAPOVB.U. Region 4, Office of Director 2pp. 22294:086 24% Fichs 50-400.83/10/25.8402170279
- 8402170286 Final Deficiency Rept 84-01 re Gould/Rundel selector switch failures. Initially reported for Wolf Creek on 830824 & for Callaway on 830923 Generic failure results from design deficiency. Manufacturer requested to rept per Part 21 SEIKEN, S. J. Standardized Nuclear Unit Power Plant System SLNRC 84-0028 84/02/09 KEPPLER, J. O. Region 3, Office of Director CULLINS, J. T. Region 4, Office of Director 10pp 22297 149 24X Fiche 50-000.84/02/09,8402170284
- 8402170317 Supplemental Part 21 rapt re radiographic record evaluation, supplying add1 data to 830624 submittal Records show that 90 degree branch connections furnished to North Anna 1 & 2 jubsites. No noziles supplied to Zimmer Related info enci BORNES, R.P. Bouthwest Fabricating & Welding Co (subs of IU International Corp.) 83/10/04. POTAPUS, U Region 4, Office of Director. App 20296-156 24X Fiche 50-000, 83/10/04, 8402170317
- 8402220330 Part 21 rept re defective DBR & DBRV standby diesel generator turbocharger thrust bearing lubrication Deficiency not corrected by sys mod New recommendation will be sent to customers by 840330.

 BOYER, R E Transamerica Delavai, Inc. 84/02/15 Director's Office, Office of Inspection and Enforcement 5pp 22332 182 24X Fiche 50-000.84/02/15,840220533.
- 840224080 Interim deficiency rept re GH Bettis actuators in safety-related dampers in HVAC sys supplied by Pacific Air Products Co. Initially reported on 840104. Problem under investigation Next rept by 840316 Also reported per Part 21. RHODE, G M. Nisgara Mohauk Power Corp. (8016) 84/02/01. BTAROSTECKIR, Division of Project & Resident Programs 2pp. 22374.*** SAV Ficha 40-410.84/02/01.8402240080.

- 8402270255 Interim deficiency rept to Safety parameter display sys Model 156 isolators mfg by Technology for Energy Corp (TEC) Initially reported on 840106 All TEC isolators reviewed for corrective actions Also reported per Part 21 CURTIE.N W Pennsylvania Power & Light Co PLA-2063 84/02/06 MURLEY, TE Region 1. Office of Director 3pp 22386 281 24% Fiche 50-388.84/02/06.8402270255
- 840;2270349 Final deficiency rept re hydrogen catalyst used in Comsip Custom Line Model K-IV cuntainment gas monitoring panels initially reported on 840:13 Comsip redesigned catalyst will be installed Also reportable under Part 2: CURTIS, N W Pennsylvania Power & Light Co PLA-2073 84/02/13 MURLEY, T E Region i. Office of Director 4pp 22391 231 24% Fiche 50-388,84/02/13,8402270349
- 8402270337 Second interim deficiency rept re deficient square root extractor modules for reactor protection sys mfg by Bailey Meter Co Initially reported on B31114 BbW requested to determine root cause Also reportable per Part 21 HILLS.L M Tennessee Valley Authority B4/02/17 C/REILLY.J P Region 2. Office of Director 2pp 22370 361 24X Fiche 50-438.84/02/17.8408270357
- 8402270373 Third interim deficiency rept re defective 88W welds on baffle plates in core support assembly Initially reported on 830302 Results of joint inspect Next rept by 850111 Also reported per Part 21 MILLS.L. M. Tennessee Valley Authority 84/02/17 ("REILLY, J. P. Region 2. Office of Director 4pp 82371 026 24X Fiche 50-438.84/02/17.8402270393
- B402270404 Final deficiency rept for Unit 1 & interim deficiency rept for Unit 2 re cracked push rod balls on Transamerica Delaval diesel generators initially reported on B40216 Also reported per Part 21 for Unit 1 Next rapt expected by B40707 MCGAUGHY. J P Mississippi Power & Light Ca AECM-84/0105 84/02717 0'REILLY. J P Region 2. Office of Director Spp 22391 05B 24X Fiche 50-416.84/02/17.8402270404
- 8402270449 Part 21 rept re stabilized assay meter (SAM) relays SAM 11, 13 & 15 & certain SAM 99 special relays could be subj to possible misoperation SAM relays listed still under warranty Mod Xits will be supplied upon request MANKOFF.L.L. General Electric Co. 84/02/22 DEYOUNO, R. Director's Office, Office of Inspection and Enforcement. 2pg. 22390-245
- 8402280263 Forwards revised Part R1 Rept CAR-0023 re potential degradation of actuator stroking times initially reported on 831118 UPTON:R T GH-Bettis Corp. 84/02/20. DEYQUNG.R C Director's Office. Office of Inspection and Enforcement 1p 22399 167
- --8402280267 Part 21 rept re potential degradation of actuator stroking times initially reported on 831118 Cause traced to ethylene propolene seals absorbing grease hydrocarbons causing seals to swell Seals & grease will be replaced LOCASCIO.A T . KANE.R K OH-Bettis Corp CAR 0023, 84/02/13 Director's Office, Office of Inspection and Enforcement 18pp. 22397 148
- 8402270073 Part 2: rept re reportable defects on certain AKR-30 & AKR-50 low voltage power circuit breakers delivered por use at facility Breakers currently under repair reinsp & recertification
 DIXON D J General Electric Co 84/02/24 DEYOUNO, R C Director's Office, Office of Inspection and Enforcement 6pp. 22426 03: 24X Fiche 50-356.84/02/24.8402270073
- 8402290236 Porwards OH Bettis Part 21 Rept CAR 0023 re gotential degradation of actuator stroking time Review will require 3 who at which time relevant plants & NRC will be notified HTLSON,A.K. Henry Pratt Co. 84/02/22 KEPPLER.J.O. Region 3. Office of Director 1p. 22424 319

GA999 QUALITY ASSURANCE INSPECTIONS

- 8401040408 Act receipt of 831012 & 1209 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 97900712/83-01
 POTAFOVS.U Region 4. Office of Director. 83/12/28 CAPRA.L. A Systems Control
- --8401040412 Responds to NRC B31117 ltr re nonconformence noted in QA Program Insp Rept 97900712/B3-01 Corrective actions typical weld symbols reduced thereby reducing confusion during insp, CAPRAL A Systems Control, Inc. B3/12/09 POTAPOVS,U Region 4, Office of Director ip 21706 21B.

- --B401040416 Responds to NRC 830916 ltr re nonconformance noted in GA Program Insp Rept 99900712/83-01 Corrective actions Sys Control will not develop new procedure Analysis shows twice as much welding as necessary for integrity CAPRA-L A Systems Control, Inc 83/10/12 POTAPOVS,U Division of Vendor & Technical Programs 2pp 21706 221.
- 840119000 Board Notification 84-021 provides repts of Transamerica Delaval, Inc images conducted from Mar 1979 to Oct 1983 EIBENHUT, D 0 Division of Licensing 84/02/13 PALLADINO Commissioners 5pp 22314 001 24X Fiche 50-000,84/02/13, 8401190050
- 840201009 Confirms GA program insp at Boston MA & Cherry Hill, NJ. afts on 840205-10 & 14-17, respectively, per 840117 telcon Insp will relate to implementation of GA program POTAPDYSU Region 4, Office of Director 84/01/27 KELLY, R B. Stone & Hebster Engineering Corp ip 22042 254
- 8402010067 Ack receipt of 840112 ltr informing NRC of steps taken to correct violation & nonconformance noted in GA Program Insp Rept 99900829/83-01 POTAPD/SU Region 4, Office of Director 84/01/26 STAFLETON, G. P General Electric Co ip 22042 187
- --8402010077 Responds to NRC 831216 ltr re violation & nonconformance noted in GA Program Insp Rept 97900829/83-01 Corrective actions latest revs to 100FR21 on file review of quality mpt mahual in progress & overdue G-card closeout under May. STAPLETON.0 P General Electric Co 84/01/12 POTAPOVS.U. Region 4, Office of Director 3pp 28042 188.
- 8402010126 Confirms 9A program insp at State of CA Div of Sefety & Health facility on 840206-10.per 840110 telcon. POTAPOVS.U. Region 4. Office of Director 84/01/25 HORN.O. California. State of p 22041.362
- 8402010146 Act receipt of 831230 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99700928/83-01.
 POTAPOVS.U. Region 4, Office of Director. 84/01/16 PARKER.J G International Neutronics. Inc. 1p. 22038:221
- --B402010150 Responds to NRC B31202 ltr re nonconformance noted in GA Program Insp Rept 99900928/83-01 Corrective actions test spec form will be revised & personnel training records will be completed GUNBY.A L International Neutronics, Inc B3/12/30 POTAPOVS, U Region 4. Office of Director 2pp 22038:222
- 8402010136 Ack receipt of 831205 & 840105 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 97900025/83-01 POTAPOVS, U. Region 4. Office of Director. 84/01/24 GOODWIN, B J Southwest Fabricating & Welding Co (subs. of IV International Corp.) 1p 22038 303
- ~B402010163 Respands to NRC 831228 ltr re nonconformance noted in GA Program Insp Rept 99900025/83-01 Corrective actions meeting held on 840104 to assure & accept responsibilities in preparation & submittal of notices of deviation per Part 21. BORNES.R P Southwest Fabricating & Welding Co (subs. of IU International Corp.). 84/01/05 POTAPOVS,U. Region 4, Office of Director ip 22038,304
- --8402010173 Responds to NRC 831110 ltr re nonconformance noted in GA Program Insp Rept 99900025/83-01 Corrective actions:reviews of all contracts listed in nuclear log book will comply w/requirements of GAD-16 in future.

 BORNES.R.P. Bouthwest Fabricating & Helding Co. (subs of IU International Corp.). 83/12/05 POTAPOVS.U. Region 4, Office of Director. 2pp. 22038,306
- 8402070258 Forwards GA Program Insp Rept 99900002/83-02 on 830822-26 & notice of nonconformance POTAPOVG.U Region 4. Office of Director. 84/01/09. LICHTENBERGER Combustion Engineering, Inc. 2pp. 22101;200
- ---8402070261 Notice of nonconformance from insp on 830822-26 * Region 4, Office of Director. 84/01/09. 1p 22101:202

- --8402070266 GA Program Insp Rept 99900002/83-02 on 830822-26
 Nonconformance noted implementation of GA program failed to
 aget NRC requirements & measures did not assure that
 analytical sycs in conformance w/procurement documents
 HCNEILL, H. M. BARNES, I Region 4. Défice of Director 83/0
 10pp 22101.203 83/09/9A
- 8402070289 Ack receipt of 840111 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 39900907/83-01 POTAFOVS, U. Region 4. Office of Director 84/01/26 BESSEY, R L Southwest Research and Information Center 1p 22095 001
- 8402070306 Ack receipt of 840111 ltr informing NRC of steps taken to correct nanconformance noted in GA Program Insp Rept 99900369/83-02. 99900367/B3-02. PGITAPOWS,U Region 4. Office of Director 84/01/26 NAUMANN,H R Automatic Switch Co ip 22095 060
- --B402070311 Responds to NRC 831216 ltr re-nonconformance noted in QA Program Insp Rept 99700369/83-02 Corrective actions.new procedure written which incorporates requirement of 10CFR21 to purchase order NAMMANN,H R. Automatic Switch Co 84/01/11 POTAPOVS.U Region 4, Office of Director 1p 22095 061
- 8402080027 Responds to appeal re denial of FOIA request for certain portions of five records on alterations by ITT Grinnell Corp of radiographs of welds in piping subassemblies Forwards Documents 10-14 of App A to Felton 830916 itr DIRCKS, H. J. Diffice of the Executive Director for Operations 83/12/27 FUGUA, D H. Wallace, Hilburn, Clayton, Calhoon & Forster, Ltd ip 22173/312.
- 8402100025 Discusses need for immediate staff insp of cylinder heads at facility in light of Vendor Insp Program Repts 97900334/83-02 & 03 rs noncomformances in implementation of GA program for production of replacement heads DWAMER: A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips. 1880ANCES DL. 84/02/07 DENTON: H Office of Nuclear Reactor Regulation. Director 2pp 22230.023 24X Fiche 50-322,84/02/07,8402100025.
- --8402130510 Forwards GA Program Insp Repts 99900334/83-02 & 99900334/83-03 on 830906-15 & 1017-21, respectively & notices of nonconformance. POTAPOVE, U Region 4, Office of Director, 84/01/17 MATHEWS, C. Transamerica Delaval, Inc. 2pp. 22230, 027 24X Fiche: 50-322, 84/02/07, 8402100025.
- --8402130513 Notice of nanconformance from insp on 830706-15

 # Region 4, Office of Director 84/01/17 5pp 22230
 Fiche: 50-322, 84/02/07, 8402100025. 52230 · 029. 24X
- ~~8402130518 QA Program Insp Rept 99900334/83-02 on 830906-15.
 Noncompliance noted: QA program not imposed on exhaust
 silenter manufacturer & insp stamps & dates on process
 sheets did not provide evidence of insp
 8UTTON.J.W.: BARNES.I. Region 4. Office of Director. 84/
 21pp 22230: 034. 24X Fiche, 50-322,84/02/07,8402100025 84/01/16.
- --8402130521 Notice of manconformance from insp on 831017-21 + Region 4, Office of Director. 84/01/17 4pp 22230:053. 24X Fiche: 50-322,84/02/07,8402100025.
- --8402130324 QA Program Insp Rept 99900334/83-03 on 831017-21.
 Noncompliance noted engineering spec sheets did not include IEEE stds invoked by customer specs & written instructions for insp/ecceptance indication not provided to manufacturer SUTION.J.W. BARNES.I Region 4, Office of Director. 84/019pp 22230:057. 24X Fiche 50-322,84/02/07,8402100025.
- 8402100128 Forwards QA Program Insp Rept 99700833/83-01 on 831003,04 & O& & notices of nonconformance & violation, PITAPOUS U. Region 4, Defice of Director. 84/01/23, MEIBBNER, F. N Electro Bwitch Corp. 3pp. 22181,277
- --8402100132 Notice of Violation from insp on 831003,04 & 06.

 Region 4, Office of Director. 84/01/23. ip. 22181;280
- --8402100136 Notice of nunconformance from insp on 831003,04 & 06 * Region 4: Office of Director. 84/01/23. 1p 22181:281.

- ---8402100141 QA Program Insp Rept 99900833/83-01 on 831003,04 & 06
 Noncompliance nated Drawing 20KD-0512LA file copy not
 checked per 10CFR30,App B & Engineering Procedure E-1.
 Violation noted current copy of 10CFR21 not pasted
 FOSTER.W E , BARNES,1 Region 4, Office of Director 84/01/17
 6pp 22181 202
- 8402140074 Ack receipt of 840124 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9790273/83-03 POTAPOVS.V Region 4, Office of Director 84/02/09 SCHMIDT, W J Westinghouse Electric Corp ip 22217 251
- --B402140080 Responds to NRC B31216 ltr re deviation noted in GA
 Program Insp Rept 99900273/83-03 Corrective actions GA
 manual & procedures will be revised for implementation of
 iOCFR21.per Wastinghouse corporate council instructions
 SCHMIDT.W J Westinghouse Electric Corp 64/01/24 POTAPON
 Region 4. Office of Director 2pp 22217 252. POTAPOVS, U
- 8402140197 Ack receipt of 831117 & 840113 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 97900403/83-03 PDTAPOVS.V Region 4, Diffice of Director 84/02/06 BRUGGEMAN.W H General Electric Co ip 22223 346
- --B402140201 Responds to NRC B31216 ltr re nonconformance noted in GA Program Insp Rept 99900403/83-03 Corrective actions: GA & reliability operation will participate in independent review of representative sample of purchases BOML.L S General Electric Co B4/01/06 POTAPOVA, U Region 4, Office of Director ip 22223:347
- -8402140209 Ack receipt of 831117 ltr informing NRC of steps taken to correct nonconformance noted in 9A Program Insp Rept 99900403/83-03. Add info re generic corrective actions & praventive measures for Nonconformance B 2 requested. POTAPDV8.U. Region 4. Office of Director 83/12/16 BRUGGEMAN.W.H General Electric Co. 1p 22223 348.
- --8402140212 Responds to NRC B31021 ltr re nonconformance noted in GA Program Insp Rept 9990403/83-03 Corrective actions customers will be notified of design documents currently in deferred verification status BONL, L S General Electric Co B3/11/17 POTAPOVS, U Region 4, Office of Director App 22223 349.
- 8402140279 Forwards GA Program Insp Rept 99700507/83-03 on 831031-1103 No instance of failure to meet NRC requirements found POTAPOVS, U Region 4, Office of Director 83/12/28 KELLY, R. B Stone & Webster Engineering Corp 2pp 22228:258
- ---B40214030B QA Program Insp Rept 99900509/83-03 on 831031-1103 No violations or nonformances noted Major areas inspected: status of previous insp findings & wall thickness of 3/4-inch tubing BEAREIP, M. MADGEN, G. L. Region 4, Office of Director. 83/12/14, 11pp. 22228 260
- 8402140332 Ack receipt of 831110 & 840113 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900837/83-01 PDTAMPOVS.U Region 4, Office of Director 84/02/06, MURPHY, J Tobar, Inc. ip 22220-274
- --8402140337 Responds to NRC B31111 ltr re nonconformance noted in GA Program Insp Rept 99900837/83-01 Corrective actions product integrity will audit assembly & test operation for requirements of nuclear quality program procedure EAVLOR.K S. Tobar. Inc. 84/01/13 POTAPOVS.U Region 4, Office of Director ip 22220:277 Region 4, Office
- --8402140343 Ack receipt of 831110 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 97900837/83-01. Add info re actions to assure conformance to practice & procedure requirements requested within 25 days POTAPOVB.U Region 4. Office of Director 83/11/28 MURPHY, J Tober, Int 1p. 22220 R78.
- --8402140349 Responds to NRC 830830 ltr re nonconformance noted in QA Program Insp Rept 99900837/83-01. Corrective actions QM-102A reissued as Quality Manual FI-1, reflecting current TDBAR organization & titles.

 MURPHY-J H Tobar, Inc. 83/11/10, PDTAPQV9, U, Region 4, Office of Director, 3pp. 22220; 279.
- 8402140398 Requests add1 info re Part 21 rept dtd 831108 concerning wear ring feilure in auxiliary Psedwater pump furnished to facilities Info requested within 25 days POTAPOVS.U Region 4. Office of Director. 83/11/30 PATTY.D F. Bingham-Willamette Co ip 22221-250. 24X Fiche 50-000.83/11/30,8402140398

- --8402140422 Supplemental Part 21 rept re wear ring failure in auxiliary feadwater pumps, per 831130 request for add1 info Wear rings will be replaced on returned units w/AIS1 420 wrought mat1 tiet of pumps in similar svc w/seme wear ring encl PATTY, D F Bingham-Willamette Co 83/12/20 Region 4. Office of Director 2pp 22221 251 24X Fiche 50-000, 83/11/30, 8402140498
- B402140430 Confirms OA program insp at Monroeville.PA plant on 840227-0302.per 840208 telton POTAPDVS.U Region 4. Defice of Director. 84/02/09 SLEMBER.R J Westinghouse Electric Corp 1p 22227 139
- 8402150118 Forwards QA Program Insp Rept 99700053/63-03 on 831129-1202 b notice of nonconformance FOTAPOVS, U Region 4, Office of Director 84/01/12 CARON, A E Darling Valve & Mfg 2pp 22249 196
- --8402150126 Notice of nonconformance from insp on 831123-1202 * Division of Vendor & Technical Programs 84/01/12 ip 22249 198
- 8402150172 Confirms QA program insp at Galthersburg.MD plant on 840206-10.per 840127 telcon PDTAPQVS.V Region 4. Office of Director 84/01/31 GALLAGER.W J NUS Corp 1p 22245 148
- 8402150375 Confirms 840113 telcon requesting extension of completion date for corrective action to Nonconformance B of QA Program Insp Rept 97900532/83-01 Date for policy & procedure mod approved for 840301 BERA.M J Control Data Corp 84/01/16 PDTAPOVS.U Region 4. Office of Director 1p 22242 144
- 8402170055 Confirms QA program insp at Saugus,CA plant on 840227-0302. per 840209 telcon POTAPDVS,U Region 4, Office of Director 84/02/13 TRAW.H L National Technical Systems 1p 22300 001
- 8402170116 Ack receipt of 840117 ltr informing NRC of steps taken to correct nonconformance noted in OA Program Insp Rept 97900056/83-02
 FOTAPOVS, U Region 4, Office of Director 84/02/13 WILSON, A K. Henry Pratt Co in 22301:005
- --8402170120 Responds to NRC 831230 ltr ra noncompliance noted in GA Program Insg Rept 99900056/83-02. Corrective actions copies of actual exams of Conam Insp Level III examiner obtained & Change Order 1 to Purchase Order U-02456 issued 831019 CWM/INS, R Harry Pratt Co 84/01/17, POTAPOVS, U Region 4, Office of Director 3pp 22301.006
- B402150186 GA Program Insp Rept 59700053/83-03 on B31129-1202
 Noncompliance noted 12-inch, iffo lb flex wedge gate valves
 containing backfit radius less than 1/8-inch inspected &
 accepted at LaBalle
 KELLEY, W. D. BARNES, I. Region 4, Office of Director 84/01/06,
 9pp 22249 199
- B402170272 Confirms QA program insp at Langhorne, PA plant on E40227-0302 per 840208 telcon. POTAPOVS.U Region 4. Office of Director 84/02/13 RICHARDS.A QNB Batteries, Inc. ip 22297 164
- B402170281 Confirms GA program insp at Ann Arbor ofc on B40213-17, per 840127 telton Insp concerns GA program implementation, POTAPDVS,U Region 4. Office of Director 84/02/10 WAHL, H W. Bechtel Corp is 22297:161
- B402210079 Confirms GA program insp at Reading, PA ofc on 840227-0302, per 840121 telcon POTAPOVS, U Region 4. Office of Director 84/02/14, LORENZ, H Gilbert Associates, Inc. 1p 22316 207.
- B40221020B Responds to NRC B31213 ltr re nonconformance & violations noted in GA Program Insp Rept 99900033/83-01. Corrective actions pump seals being reviewed w/NRC to determine whether pump seals required for any safety-related function RUPPEL.H D. Westinghouse Electric Corp. WPS-45110. B4/02/10. PDTAPDV8.U Region 4. Office of Director 10pp 22316:197.
- 8402210215 Responds to NRC 831206 ltr re nonconformance noted in GA Program Insp Rept 99900732/83-02 Corrective actions: individual involved counseled & instructed to follow correct procedures when conducting insp QIEBLER, J V. Robert Shaw Controls Co 84/01/23, POTAPOVS, U. Region 4. Office of Director. 2pp 22316:316

- 8402220183 Ack receipt of 840124 ltr informing NRG of steps taken to correct nonconformances noted in QA Program Insp Rept 99900749/83-02 POTAFOVS,U Region 4, Office of Director 84/02/16 HEBS,L R Facific Air Products Co 1p 22340 345
- --8402220188 Responds to NRC 831223 ltr re nonconformances noted in GA Program Insp Rept 97900767/83-02 Corrective actions: inspectors recentified for 2-yr period Documentation package for nonsafety-related dampers amended DODSON.J P Pacific Air Products Co 84/01/24 POTAPOVB.U Region 4. Office of Director 2pp 22340 346
- 8402220255 Forwards portions of Los Angeles Power Div engineering dept procedure defining conditions under which commercial grade or off-the-shelf items will qualify for use in safety-related applications
 PATTERSON, R. L. Sechtel Corp. 84/02/09 POTAPOVS. V. Region 4, Office of Director. 3pp. 22334-359
- B402220256 Forwards QA Program Insp Rept 99900513/83-02 on 831213-15 No noncompliance noted PDTAPOVS.U Region 4. Office of Director 84/01/23 BAILEY.F C, Teledyne Engineering Services 2pp 22334,352
- --8402220265 GA Program Insp Rept 99900513/83-02 on 831213-15 No noncompliance noted Major areas inspected status of previous insp findings; implementation of fingosition of Part 21 requirements & Teledyne computer programs.

 EEARB.P. N. MADBEN.O L. Region 4, Office of Director 84/01/19 5pp 22334 334
- 8402280278 Forwards GA Program Insp Rept 99900912/83-02 on B31212-15 No noncompliance noted PDTAPOVS.U Region 4, Office of Director 84/01/31 COMOREY, 8 & Acton Environmental Testing Corp 2pp 22337 057
- --8402220281 GA Program Insp Rept 99900912/83-02 on 831212-15. No noncompliance noted Major areas inspected GA & equipment qualification program GA manual & implementing procedures, interviews w/personnel & observations by inspector AGEE, J R, PHILLIPS, H B Region 4, Office of Director. 84/01/30 Bpp 22337 059
- 8402220379 Ack receipt of 840119 ltr informing NRC of steps taken to correct nonconformances noted in GA Program Insp Rept 9790040288-01 PDTAPOVS.U Region 4, Office of Director 84/02/16. HOUSE, H C 0A Technologies. Inc /
- --8402220301 Responds to NRC 840103 ltr re nonconformances noted in QA Program Insp Rept 99900402/83-01 Corrective actions: five new lead auditors qualified to assist in maintaining audit schedule HOUSE: H C GA Technologies, Inc /General Atomic Co. 84/01/17 POTAPOVS.U Region 4. Office of Director 4pp 22335.353
- B402220308 Forwards GA Program Insp Rept 99900401/84-01 on 840116-19 No noncompliance noted PDTAPDV8.U Region 4, Office of Director 84/02/03 ETHERIDGE.N R Combustion Engineering, Inc. 2pp 22336 206
- --B402220319 QA Program Insp Rept 99900401/84-01 on 840116-19 No noncompliance noted Major areas inspected status of previous insp findings & QA practices for licensed computer programs & equipment qualification SEARS,P M., HADSEN,O,L. Region 4, Office of Director, 84/02/02 9pp 22336 208.
- 8402220370 Forwards QA Program Insp Rept 97900786/83-02 on 831129-1202 & notice of nonconformance POTAPOVS,U Region 4. Office of Director. 84/01/31 DEVAULT,E N General Electric Co 2pp 22335-321
- --8402220375 Notice of nonconformance from insp on 831127-1202 * Region 4, Office of Director 84/01/31 3pp. 22335.323
- ---8402220381 GA Program Insp Rept 99900786/83-02 on 831129-1202 Nonconformance noted adequate written procedure not available to control quality requirements for brazing as syidenced by nonpresentation of requested document. FOSTER.W E . BARNES.I Region 4. Office of Director, 84/01/30. 1400 22338.326
- 8402220390 Forwards GA Program Insp Rept 79700374/83-02 on 831212-15 & notice of nonconformance POTAPOVS.U Region 4. Defice of Director. 84/01/27. 8CHAFER, J C. Metal Bellows Corp. 2pp. 22334.108
- --8402220392 Notice of nonconformance from insp on 831212-15 # Region 4, Office of Director 84/01/27 1p. 22334:110.

- -8402070266 GA Program Insp Rept 99900002/83-02 on 830822-26

 Nonconformance noted implementation of GA program failed to meet NRC requirements & measures did not assure that analytical svcs in conformance w/procurement documents MCNEILL-W M , BARNES I Region 4. Office of Director 83/0 10pp 22101 203 83/09/24
- 8402070289 Ack receipt of 840111 ltr informing NRC of steps taken to correct conconformance noted in GA Program Insp Rept 99900909/83-01 99900909/83-01 POIAPOVS.U Region 4. Office of Director B4/01/26 Southwest Research and Information Center 1p 2209 BESSEY, R L 22095 001
- --8402070295 Responds to NRC 831213 ltr re nonconformance noted in GA Progrem Insp Rept 99700909/83-01 Corrective actions one amp applied through all closed contact resistance valves, producing acceptable results BEBSEY.R Southwest Research and Information Center 84/01/11 POTAPOVS, U Region 4, Office of Director 7pp 22073 002
- 8402070306 Act receipt of B40111 ltr informing NRC of steps taken to correct nanconformance noted in GA Program Insp Rept PGTAPOVS.U Region 4. Office of Director 84/01/26 NAUMANN, H R Automatic Switch Co ip 22095 060
- to purchase order NAUMANN.H R Automatic Switch Co 84/01/11 POTAPOVS.U Region 4. Office of Director ip 22095 061
- 8402080027 Responds to appeal re denial of FOIA request for certain portions of five records on alterations by ITT Grinnell Corp of radiographs of welds in piping subassemblies Forwards Documents 10-14 of App A to Felton 830916 ltr DIRCKS.H J Office of the Executive Director for Operations 83/12/29 FUGUA.D M Wallace. Hilburn. Clayton. Calhoon & Forster. Ltd 1p 22173 312
- 8402100025 Discusses need for immediate staff insp of cylinder heads at facility in light of Vendor Insp Program Repts 45900334/83-02 & 03 re noncomformances in implementation of A program for production of replacement heads 9748-ER.A R. Kiplpatrick, Lockhart, Hill, Christopher & Phillips 169UANCES DL 84/02/07. DENTON: H R Office of Nuclear Reactor Regulation. Director 2pp 22230 023. 24% Fiche 50-322,84/02/07. Regulation, Director 8402100025
- --8402130510 Forwards GA Program Insp Repts 97900334/83-02 & 97900334/83-03 on 830706-15 & 1017-21, respectively & notices APPROOF AND AN ASSOCIATION A 1017-R1 respectively & notices of nonconformance POINFOVS.U Region 4. Office of Director 84/01/17 MATHEMS, C Transcaserice Deleval, Inc. 2pp 22230 027 24X Fich: 30-322, 84/02/07, 8402100025
- --8402130513 Natice of monconformance from insp on 830704-15 + Region 4, Dffice of Director 84/01/17 5pp 22230 029 24X Fichs 50-022.84/02/07.8402100025
- --8402130518 GA Program Insp Rept 99900334/B3-02 on 830906-15
 Noncempliance noted: GA program not imposed on exhaust
 silencer manufacturer & insp stamps & dates on process
 sheets did not provide evidence of insp.
 SUTION, J M., BARNES, I Region 4, Office of Director 84,
 21pp 22230, 034 24X Fiche. 50-322, 84/02/07, 8402100025 84/01/16
- --8402130321 Natice of nonconformance from insp on 831017-21 + Region 4, Office of Director 84/01/17 4pp 22230 Fithe 50-322,84/02/07,8402100025 22230 053 24X
- -8402130324 QA Program Insp Rept 99900334/83-03 on 831017-21
 Noncompliance noted engineering spec sheets did not include
 IEEE stds invoked by customer specs & written instructions
 for insp/acceptance indication not provided to manufacturer
 SUT[QM, J Y . BANNES, I. Region 4. Office of Director 84/01
 19pp. 22230-057 24X Fiche 50-322,84/02/07,8402100025
- 8402100128 Forwards GA Program Insp Rept 99900833/83-01 on 831003,04 08 k notices of nonconformance & violation POTAPOVB.U Region 4, Office of Direction Suit-

- --B402100141 QA Program Insp Rept 99900B3783-01 on 831001,04 L Oh Noncompliance noted Drawing 20KD-0512LA file copy not checked per 10CFR50. App B & Engineering Procedure 1:-1 Violation noted current copy of 10CFR21 nat posted Violation noted current copy of 10CFR21 nat posted FOSTER. W E . BARNES. I Region 4. Office of Director (14/01/17 6pp 22181 282
- 8402140074 Ack receipt of 840124 ltr informing NRC of steps talen to correct deviation noted in GA Program Insp Rept 99900273/83-03 99900273/83-03 POTAPOVS, U Region 4, Office of Director Westinghouse Electric Corp 1p 22217 251
- --8402140080 Responds to NRC 831216 ltr re deviation noted in QA Program Insp Rept 99700273/83-03 Corrective actions QA manual & procedures will be revised for implementation of 100FR21, per Westinghouse corporate council instructions SCHMIDT,W J Wastinghouse Electric Corp 84/01/24 POTAMOV Region 4, Office of Director 2pp 22217 292
- 8402140199 Ack receipt of 831117 to 840113 ltrs informing NNC of elegatiate to correct nonconformance noted in GA Program Insp. Rept 97900403/83-03 POTAPOVS, U Region 4, Office of Director 84/02/06 DRUGUIMAN W V General Electric Co Ip 22223 344
- --8402140201 Responds to NRC 831216 ltr re nonconformance noted in 44 Program Insp Rept 99900403/83-03 Corrective actions GA & reliability operation will participate in independent review of representative sample of purchases BOHL-L S General Electric Co 84/01/06 POTAPBVB, U Region 4 Office of Director 1p 22223.347
- --8402140207 Ack receipt of 831117 Itr informing NRC of steps leter to correct nonconformance noted in GA Program Insp Rept 99900403/83-03 Addl info re generic corrective actions & preventive measures for Nanconformance B 2 requested PDTAPOVS.U Region 4. Office of Director B3/12/16 BRUGGEMAN, H H General Electric Co 1p 22223 348
- --8402140212 Responds to NRC 831021 ltr re nonconformance noted in da Program Insp Rept 99900403/83-03 Corrective actions, customers will be notified of design documents currently in deferred verification status BOHL, E General Electric Co 83/11/17 PDTAPOVO, V Region & Office of Director 6pp 22223 349
- 8402140279 Forwards QA Program Insp Rept 97900509/83-03 on 03104 Htt No instance of failure to meet NRC requirements found POTAPOVS, U Region 4. Office of Director 83/12/20 Stone & Webster Engineering Corp 2pp 22228/258
- --B402140308 QA Program Insp Rept 99900509/83-03 on 831031-110)#; violations or nonformances noted Major arms imperted. status of previous insp findings & wall thickness of 3/4states of previous lass states of Ginch tubing
 SEARS, P.M. MADSEN, G.L. Region 4, Office of Director
 11pp 22228 260
- 8402140332 Ack receipt of 831110 & 840113 ltrs informing NRC of the taken to correct nonconformance noted in GA Program Insp. Rept 9990837/83-01. POTAPUS.U. Region 4, Office of Director 84/02/06 MRPHY.J Tobar, Inc. 1p. 22220 276
- --8402140337 Responds to NRC 831111 ltr re nonconformance noted is a Program Insp Rept 99900837/83-01 Corrective actions product integrity will audit assembly & test operation for the conformance of nuclear quality appropriate the conformance of nuclear quality appropriate.

- --B402140422 Supplemental Part 21 rept re wear ring failure in auxiliary feedwater pumps, per B31130 request for addl info Wear rings will be replaced on returned units w/AISI 420 wrought matl List of pumps in similar svc w/same wear ring encl PATTY.DF Bingham-Hillamette Co 83/12/20 Region 4. Office of Director 2pp 22221 251 24X Fiche 50-000.B3/11/30. B402140388
- E402140430 Confirms GA program insp at Monroeville.PA plant on 840227~ G302.per 840208 telcon POTAPDV8.U Region 4. Office of Director 84/02/09 SLEMBER.R J Westinghouse Electric Corp 1p 22227 139
- 8402150118 Forwards GA Program Insp Rept 99900053/83-03 on 831129-1202 A notice of nonconformance
 POTAPOVS.U Region 4, Office of Director 84/01/12 CARON, A E
 Darling Valve & Mfg 2pp 22249 196
- --8402150126 Notice of nonconformance from insp on 831123-1202 * Division of Vendor & Technical Programs 84/01/12. Ip 22249 198
- B40215019R Confirms QA program insp at Gaithersburg,MD plant on B40226-10.per B40127 telcon POTAFOVS.U Region 4, Office of Director, B4/01/31 QALLAGER.W.J NUS Corp ip 22249 14B
- 8402150375 Confirms 840113 telcon requesting extension of completion date for corrective action to Nonconformance B of QA Program Insp Rept 99900532/83-01 Date for policy & procedure mod approved for 840301 Data Corp 84/01/16 FOTAPOVS.U Region 4. OPfice of Director 1p 22242 144
- 8402170055 Confirms QA program insp at Baugus, CA plant on 840227-0302. per 840207 telcon POTAPOVS.U Region 4. Office of Director, 84/02/13 TRAW.W L National Technical Systems ip 22300 001
- 8402170116 Ack receipt of 840117 ltr informing NRC of steps taken to correct nanconformance noted in GA Program Insp Rept 99900056/83-02 POTAPOVS,U Region 4, Office of Director 84/02/13. WILSON,A K Henry Pratt Co 1p 22301
- --8402170120 Responds to NRC 831230 ltr re noncompliance noted in GA Program Insp Rept 99700056/83-02 Corrective actions copies of actual exams of Comem Insp Level III examiner obtained & Change Order i to Purchase Order U-02456 issued 831019. CUMMINS.8 R Henry Pratt Co 84/01/17 POTAPOVS, U Region 4, Office of Director 3pp 22301.006
- 8402150186 QA Program Insp Rept 99700053/83-03 on 831129-1202 Noncompliance noted:12-inch.150 lb flax wedge gate valves containing backfit radius less than 1/8-inch inspected & accepted at LaBalle KELLEY,W D. BARNEG.I Region 4. Office of Director 84/01/06 7pp 22249 199.
- B402170272 Confirms GA program insp at Langhorne, PA plant on B40227-0302, per 840208 telcon. PDTAPOVB, U Region 4, Office of Director 84/02/13 RICHARDS, A GNB Batteries, Inc. ip 22297 164
- 8402170281 Confirms GA program insp at Ann Arbor ofc on 840213-17.per 840127 telton Insp concerns GA program implementation POTAPOVS.U Region 4. Office of Director 84/02/10 WAHL.H W. Bechtel Corp Ip. 22297.161.
- 8402210079 Confirms GA program insp at Reading. PA ofc on B40227-0302. per 840131 telcon POTAPOVO, U Region 4, Office of Director 84/02/14 LORENZ, H Gilbert Associates, Inc. 1p 22916:207
- 8402219208 Responds to NRC 831213 ltr re nonconformance & violations noted in GA Program Insp Rept 99900033/83-01. Corrective actions pump seals being reviewed w/NRC to determine whether pump seals required for any safety-related function. RUPPEL, H D Westinghouse Electric Corp WPS-45119, 84/02/10 PDTAPDVS.U Region 4, Office of Director, 10pp 22316,197
- 8402210215 Responds to NRC 831206 ltr re nonconformance noted in QA Program Insp Rept 99900732/63-02. Corrective actions: individual involved counseled & instructed to follow correct procedures when confucting insp GIEBLER,J V. Robert Shaw Controls Co. 84/01/23 POTAPOVS.U. Region 4. Office of Director. 2pp. 22316 316.

- 8402220183 Ack receipt of 840124 1tr informing NRC of steps taken to correct nonconformances noted in GA Program Insp Rept 99900769/83-02 PDTAPDVS.U Region 4. Office of Director 84/02/16 NESS.L.R. Pacific Air Products Co
- --B40222018B Responds to NRC B31223 ltr re nonconformances noted in the Program Insp Rept 99900769/83-02 Corrective actions: inspectors recentified for 2-up period Documentation package for nonsafety-related dampers amended DODBON, J P Pacific Air Products Co 84/01/24 POTAPOVB, U Region 4, Office of Director 2pp 22340 346
- 8402220255 Forwards portions of Los Angeles Power Div engineering dust procedure defining conditions under which commercial grade or off-the-shelf items will qualify for use in safetyrelated applications
 PATTERSON.R L Bechtel Corp 84/02/09 POTAPOVB, V Region 4.
 Defice of Director 3pp 22334 359
- 8402220256 Forwards GA Program Insp Rept 99700513/83-02 on 831213-15 Hz POTAPOVS.U Region 4, Office of Director 84/01/23 BAILEY.F.C, Teledyne Engineering Services 2pp 22334 352.
- -8402220265 GA Program Insp Rept 99900513/83-02 on 831213-15 No
- B402220278 Forwards GA Program Insp Rept 99900912/83-02 on 801212-15 kg noncompliance noted POTAPOV8,U Region 4, Office of Director. 84/01/31 COMDREY,R 8 Acton Environmental Testing Corp 2pp 22337.057
- --8402220281 QA Program Insp Rept 99900912/83-02 on 831212-15 No noncompliance noted Major areas inspected QA & equipment qualification program QA manual & implementing procedures, interviews w/personnel & observations by inspector AGE, JR , PHILLIPS, H & Region 4, Office of Director. 84/01/30 8pp. 22337 059.
- 8402220297 Ack receipt of 840119 1tr informing NRC of steps taken to correct nonconformances noted in GA Program Insp Regt 99900402/83-01 үүуии402/83-01 POTAPDVS,U Region 4, Office of Director 84/02/16. HOUSE,H.C **4A** Technologies, Inc /General Atomic Co ip. 22335-352.
- --8402220301 Responds to NRC 840103 ltr re nonconformances noted in GA Program Insp Rept 99900402/83-01 Corrective actions: five new lead auditors qualified to assist in maintaining audit schedule HOUSE, H C. GA Tachnologies, Inc./General Atomic Co B4/OL POTAPOVS, U Region 4, Office of Director 4pp 22335:353
- 8402220308 Forwards QA Program Insp Rept 99900401/84-01 on 840116-19 No noncompliance noted
 PDTAPOVS.U Region 4. Office of Director. B4/02/03 EYHER!00E.M R
 Combustion Engineering. Inc. 2pp. 22336 206
- --8402220319 GA Program Insp Rept 97900401/84-01 on 840116-19 No noncompliance noted Major areas inspected, status of previous insp findings & GA practices for licensed computer programs & equipment qualification SEARS.P. M. MADSEN.Q L. Region 4. Office of Director. 84/03/62 9pp. 22336 208.
- 8402220370 Forwards GA Program Insp Rept 99900786/83-02 on 801199-1202 & notice of Ronconformance POTAPOV8.U Region 4. Office of Director. 84/01/31 DEVAULT.E N General Electric Co. 2pp 22335.321.
- --8402220375 Notice of nonconformance from insp on 831127-1202 * Region 4, Office of Director. 84/01/31 3pp. 22335.3
- --B402220381 GA Program Insp Rept 99900786/83-02 on 831129-1202
 Nonconformance noted: adequate written procedure not
 available to control quality requirements for brazing as
 evidenced by nonpresentation of requested document.
 FOSTER.W. E., BARNES.I. Region 4. Office of Director. 84/01/30
 14pp 22335-324
- 8402220390 Forwards GA Program Insp Rept 99700394/83-02 on 831212-15 & notice of nonconformance. POTAPOVS.U. Region 4. Office of Director. 84/01/27. SCHAFER.J C Matal Bellows Corp 2pp 22334 108.
- --8402220392 Notice of nonconformance from insp on 831212-15 * Region 4, Office of Director. 84/01/27. ip. 22334: 110.

- --8402220376 0A Program Insp Rept 97900394/83-02 on 831212-15
 Nancompliance moted rejection rept for unacceptable dys
 penetrant indication not entered on mfg operation sheet &
 purchass order awarded to unapproved vendor
 OLLER, R. E., HALE, C. J. Region 4, Office of Director 84/01/26
 9pp 22334 111
- 8402220400 Forwards GA Program Insp Rept 99900330/83-02 on 830920-22 to natice of Violation. POTAPOVS, U Region 4, Office of Director 84/01/26 SAUTER, D M Wastinghouse Electric Corp 2pp 22334 097
- --8402220402 Notice of violation from insp on 830720-22 * Region 4, Office of Director 84/01/26 ip 22334 099
- --B40222BB0B GA Program Insp Rept 99900330/83-02 on 830920-22. Violation noted failure to notify NRC that defective basic undervoltage components shipped by Westinghouse on 830405 & 11 MCNEILL.W M , HALE,C J Region 4, Office of Director. 84/01/26
 - Bpp. 22334 100
- B402220403 Forwards GA Program Insp Rept 99700230/83-01 on 831128-1202 & notice of nanconformance PDTAPOVS, U Region 4. Office of Director 84/01/23 CARDELLO, P 8 Anaconda Ca (subs of Atlantic-Richfield Co) 2pp 22336 339
- --8402220407 Notice of nonconformance from insp on 831128-1202 * Region 4, Office of Director 84/01/23 ip 22336-341
- --8402220414 GA Program Insp Rept 99900230/83-01 on 831128-1202
 Nanconformance noted detailed document procedures not
 established to control activities potentially affecting
 equipment qualification testing
 HABBARD.G T., PHILLIPS.H 8 Region 4. Office of Director.
 84/01/17 14pp 22336.342
- 8402220419 Forwards GA Program Insp Rept 99900231/83-01 on 831115-17 & notices of nonconformance & violation POTAPOVB.U. Region 4. Office of Director 84/01/24 VIGGIANO, V A Okonite Co. 2pp. 22340-174
- --8402220421 Notice of violation from insp on 831115-17
 a Region 4, Office of Director 84/01/24 ip 22340 176
- --8402220423 Notice of nonconformance from insp on 831115-17
 * Region 4, Office of Director 84/01/24, ip 22340 177.
- --8402220427 GA Program Insp Rept 97900231/83-01 on 831115-17
 Nonconformance & violation notad, purchase order issued for safety-related testing svcs did not specify that 10CFR21 requirements applicable HUBBARD.0.T., PHILLIPS, H 8 Region 4, Office of Director. 84/01/20. 11pp 22340-178
- 6402220434 Forwards GA Program Insp Rept 99900826/83-01 on 831205-09 No noncompliance noted. POTAPOVS, U. Region 4, Office of Director 84/02/02 SCOTT. Q. A Anaconda Co (subs. of Atlantic-Richfield Cb.) 2pp 22340 020
- --8402220439 QA Program Insp Rept 99900826/83-01 on 831205-09. No noncompliance noted Major areas inspected repts re failures of Anaconda flexible conduit PARKER.L.B., PHILLIPS.H.B. Region 4. Office of Director 84/01/17.
- 8402220527 Forwards CA Program Insp Rept 99700378/63-01 on 831114-18 k notice of nonconformance PDTAPDVB,U Region 4, Office of Director 84/01/23 BMANSON,N.E. Acar-Claveland Co 2pp. 22333,345.
- --8402220532 Notice of nonconformance from insp on 831114-18.

 Begion 4, Office of Director 84/01/23 ip. 22333.347
- --8402220334 GA Program Insp Rept 79700378/83-01 on 831114-18.
 Nanconformance noted implementing procedures not issued & procedures to assure that test data accumulated using out-of-tolerance equipment not provided AOEE.J R., PHILLIPS,H B Region 4, Office of Director 84/01/17.
 12pp. 22333:348.
- 8402270358 Confirms QA program insp at New York, NY plant on 840227-0302,per 840210 telcon POTAPOVB, U Region 4, Office of Director. 84/02/22 TENZER, B. E Ebasco Services, Inc. (suba of Enserch Corp). 1p. 22391 152

REGULATORY GUIDES

- 8402020259 Forwards info documenting compliance w/Position 1 of Reg Quide I 43 consisting of description of calculation mathodology & representative time-current curves for thermal capability of penetration assemblies PETRICK:N A Standardized Nuclear Unit Power Plant System 84~0010 84/01/31 DENTON,H R Office of Nuclear Reactor Regulation, Director 24pp 22055.263 24X Fiche 50~000.84/01/31,8402020259
- 8402060166 Forwards partial response to 831230 request for info re radwaste disposal methods, per Reg Guide 1 86 Outer 1/2 to 3/4 inch of radwaste bidg walls will be spalled & removed for shipment as radwaste per ALARA principle FIEDLER.P B General Public Utilities OPU Service Corp 84/01/30 CRUTCHFIELD.D Operating Reactors Branch 5 3pp 22087 165 24x Fiche.50-219.84/01/30.8402060166
- 8402060322 Draft value/impact assessment of proposed Reg Guide 5 9, "Guidelines for Germanium Spectroscopy Sys for Measurement of SNN " Reg Guide should be revised to be brought up to date * Office of Nuclear Reactor Regulation. Director 83/12/31 Office of Nuclear Reactor Regulation. Director 8pp 22111 058
- 8402070382 Forwards comparison study to evaluate facility design basis compliance to Reg Quide 1 97.per NUREG-0737.Suppl | Mode identified in encl will be completed by end of second refueling after Jul 1985 for each unit

 STEWART.W.L. Virginia Electric & Power Co 053 84/01/31
 DENTON, HR Office of Nuclear Reactor Regulation, Director 49pp 22095 201 24x Fiche.50-280,84/01/31,8402070382
- 8402080052 Forwards "Reg Quide i 97 Review," per NUREO-0737, Suppl 1 Encl study performed to criteria of Reg Quide i 97.Rev 3 Mods identified in study will be completed by end of second refueling after Jul 1985 STEMART, W.L. Virginia Electric & Power Co. 054 84/01/31 DENYON, H.R. Office of Nuclear Reactor Regulation, Director. ETBENHUT, D.O. Division of Licensing 2pp 22128 002 24X Fiche. 50-338,84/01/31,8402080052.
- --8402080045 "Reg Guide i 97 Review "
 * Virginia Electric & Power Co 84/01/31. 47pp 22128:004 24X
 Fiche 50-338,84/01/31,8402080062
- 8402090408 Partial response to FOIA request for four categories of documents re NUREO-75/087 (NUREO-0800). "SRF for Review of BARs for Nuclear Plants." Review of remaining documents incomplete Forwards App A documents
 FELTON, J. M. Division of Rules and Records 83/12/30, MADDEN, T. J. Kaye, Scholer, Fierman, Hays & Handler App 22193,003 24X
 Fiche 50-000,83/12/30,8402090408
- --8402090411 Forwards draft summary of 780717 mesting re proposed rev to Reg Guide 1 16 on reporting of operating info. Comments on corrections, additions or deletions requested promptly to meet 780818 issue date Commitment dates requested MEDEIROS, M.S. NRC No Detailed Affiliation Given 78/08/11 NRC No Detailed Affiliation Given 22193, 165
- --B402090413 Forwards summary of 780717 meeting to proposed new to Reg Guide 1.16 on reporting of operating inforper GAO feedback program recommendations. ARLOTTO, O A. Office of Nuclear Reactor Regulation, Director 78/08/31. STELLO, V. BNIEZEK, J. MALLER, N. Office of Nuclear Reactor Regulation, Director. 1p 22193 183.
- --8402090416 Summarizes 780719 meeting in Rockville, MD re proposed rev to Reg Guide I.16 on reporting of operating info. Rev will proceed w/clarification of examples & simplification of language as goals. No major changes in scape of reporting * NRC No Detailed Affiliation Given 78/08/29. NRC No Detailed Affiliation Given 22193 184
- --B402090423 Forwards comments re-proposed rev to Reg Guide 1.16 un reporting of operating info. HALLER.N.M Office of Management and Program Analysis. 78/09/14 ARLOTTO.0.A Division of Engineering Standards. 18pp. 22193.196
- --8402090426 Forwards 780719 & 20 agenda for meetings re proposed rev to Reg Guide 1.16 on reporting of operating info ARLOUTIO.G.A. Division of Engineering Standards. 78/06/30. BTELLO,V Division of Operating Reactors SNIEZEK, J. Division of Reactor Operations Inspections. HALLER, N. Defice of Management and Progrem Analysis. 7pp. 22193.226

- --B402070477 Forwards comments re-proposed Rev 5 to Reg Quide 1 16,
 "Reporting of Operating Info App A Tech Specs," per 790202
 request for review Comments largely editorial Format readily
 understood & change clarified W/o encl
 NULLER,D R Division of Site Safety & Environmental Analysis
 79703/01 MORRISON.W M Division of Operating Reactura 2pp
 22193 067
- B402090518 Summary of ACRS Subcommittee on Regulatory Activities 831116 meeting in Hashington,DC re Reg Guide 1 105,Rev 2, "Instrument Setpoints for Safety-Rolated Bys " * ACRS - Advisory Committee on Reactor Safeguards 83/11/27 ACRS - Advisory Committee on Reactor Safeguards 11pp 22192 151
- 8402100186 Advises that 830720 request for add1 info re FSAR Sections 13 5 2 & 15 8 omitted info for 640 36 re conformance to Reg Quide 1 33 Amend to FSAR, including corrected form & revised response, requested SCHMENCER. A Licensing Branch 2 84/02/06 RHDDE.O K Niagara Mohawk Power Corp 2pp 22205 185 24X Fiche 50-410,84/02/06,8402100186
- 8402100409 "For Comment" issue of draft Reg Quide CE 227-4, "Btd Format & Content for Health & Safety Sections of License Renewal Applications for U Hexafluoride Production Plants " PEARSON, W R Office of Nuclear Regulatory Research, Director 84/01/31 44pp 22213 150
- --8402100412 Draft value/impact statement re proposed Reg Guide CE 227-4, "Std Format & Content for Health & Safety Sections of License Renewal Applications for U Hexafiluoride Production Plants "Reg guide will serve as basis for std review plan * Office of Nuclear Regulatory Research, Director 84/01/31 4pp 22213 194
- 8402130193 Forwards Rev i to position paper on Reg Guide 1 97 & response to NURGO-0737, Suppl 1, Reg Guide 1 97 reemspency response facilities Rev supersedes 830930 submittal ZIMMERHAN.8 R Carolina Power & Light Ca NLB-84-025 84/02/01 VABSALLO,D B Operating Reactors Branch 2 ip 29199 286 24X Fiche 50-324,84/02/01,8402130153
- --8402130159 Rev 1 to "Position Paper on Reg Quide 1 97 "
 BROWN,W E Carolina Power & Light Co 63/10/26 120pp.
 22199 287 24X Fiche 50-324,84/02/01.8402130153
- 8402140451 Notifies that response to Rep Guide 1 97 will be submitted by 840430 MILLS.L M Tennessee Valley Authority 84/02/06 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 22227 iii. 24X Fiche 50-239,84/02/06,840214045i
- 8402160089 Forwards response to requirements of Rev 2 to Reg Guide 1 97, per Bection 6 2 of Suppl 1 to NVREG-0737 (Generic Ltr 82-33) & util 830415 ltr re post-accident monitoring to assess plant & environs during accident MILLS, L H Tennessee Valley Authority GL-82-33 84/01/30 ADENSAM.E Licensing Branch 4. 39pp 22276 132 24X Fiche, 90-390, 84/01/30, 8402160089.
- 8402170453 Draft value/impact statement for draft reg guide, Task DP 212-4 re radiation protection training for personnel employed in medical facilities

 # Uffice of Nuclear Regulatory Research, Director 84/01/31 5pp 22318 240
- --8402170455 "For Comment" issue of draft Reg Guide OP 212-4, "Radiation Protection Training for Personn*1 Employed in Medical Facilities "

 * Office of Nuclear Regulatory Rusearch, Director 84/01/31
 55bp 22318 313
- 8402210110 Bubmits implementation date for requirements of Reg Quide i 97, per Generic Ltr 82-33 Requirements will be complied by end of Unit 2.Cycle 4 outage scheduled for 870902 MILLS.L M Tennessee Valley Authority QL-82-33. 84/02/14 ADENSAM.E Licensing Branch 4 ip 22316 362 24% fiche 50-327.84/02/14.8402210110
 - 02220196 Forwards add1 info requested for antitrust review in connection w/OL application Info prepared per Reg Guide 9 3. Response to Reg Guide 9 3 also filed on behalf of North sroline Eastern Municipal Fower Agency "DUFFIE.M A Carolina Fower & Light Co. NLS-84-049 84/02/18 ALBTON.A L Division of Engineering. 62pp 22341-224 24X he 50-400.84/02/16.8402220196

- B402240017 Forwards boron dilution analysis.per Reg Quide 1 70 & NUREG-0880.for failures in chemical & vol control sys.based on Hestinghouse STS setpoints & limits No design changes recammended or implied W/o encl COUNBIL.W O Northeast Utilities B11030 B4/02/10 YDUNGBLODB, B Licensing Branch 1 1p 22375 244 24% Fiche 50~423.84/02/10,8402240017
- 8402270257 Requests that schedule for upgrading environ qualification of accident manituring equipment per Reg Guide 1 97 & 10CFR50 49(g), be extended to sixth refueling outage, but no later than 851130 CLAYTON.F L. Alabame Power Co. 84/02/22 VARGA.8.A Office of Nuclear Reactor Regulation. Director 13pp 22386 224 24X Fiche 50-348,84/02/22,8402270259
- 8402280214 Reaffirms schedule for implementation of all Reg Quide 1 97 items by second refueling outage in Jul 1985 List of items, excluding in-core thermocouples, requiring addl work to achieve compliance encl
 BIEWART.W L Virginia Electric & Power Co OBB 84/02/21
 BENTON.H R Office of Nuclear Reactor Regulation, Director. 7pp. 22400 185 24X Fiche 50-000.84/02/21,8402280214
- 8402280495 Comments on draft reg guide.Task IC 609-5, "Criteria for Electric.Instrumentation & Control Portions of Safety Sigs " ALLEN.R E. Power Engineering Society 84-C-010 84/02/16 Docketing & Services Branch. Spp 22407 077
- 8408280500 Comments on draft reg guide. Task CE 227-4, "9td Format & Content for Health & Bafety Sections of License Renewal Application for U Mexafluoride Production Plants."

 CEMBER, H Northwestern Univ , Evanston, IL 84/02/17. Office of the Secretary of the Commission. ip 22407.081
- 8402290177 Forwards proposed changes to Section 1 B of FSAR re Reg Guides 1,28 & 1 33 covering preoperations1 & startup testing Changes will be incorporated into future FSAR amend. VAN BRUNT,E E. Artiona Public Service Co. ANPP-28943 HFQ/. B4/02/24 KNIGHTON,Q Licensing Branch 3 Spp. 22424, 289. 24X Fiche 50-528,84/02/24,8402290177

RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS

- B3i0270388 RIL-136
 Interim Research Info Ltr 136 discusses accident sequence
 procursor program Data from draft 1980-81 rept being
 analyzed Detailed info encl
 MINDQUE.R B. Office of Nuclear Regulatory Research, Director FIN
 B-1583 83/10/14 DENTON.H R Office of Nuclear Reactor
 Regulation, Director, 29pp 22090 001
- 8402080461 "Generic Study of Recycle of Contaminated Matls," monthly progress rept for Dec 1983 O'DDNNELL,F R. Oak Ridge National Laboratory FIN 8-0824 84/01/18 SOLBERG,D E. Transportation & Materials Risk Branch Spp. 22174 081
- 8402090264 RIL-138
 Research Info Ltr 138 transmits results of completed research task defining proper human actions & responses by nuclear power plant control room crews during normal, off normal & accident conditions. W/o stated and MNGGUE; R B Office of Nuclear Regulatory Research, Director, FIN B-7491 B4/01/31 DENTON, H R. Office of Nuclear Reactor Regulation, Director 7pp. 22188 332.

REVIEW ORP NRC RESEARCH REVIEW ORDUPS

- 8402280256 Summary of CROR Meeting 50 on 831026 re two proposed draft itrs concerning NRC current definition & interpretation of terms important to safety & safety-related used in NRC regulations
 STELLO, V Committee to Review Generic Requirements, 83/11/14
 DIRCKS.W J Office of the Executive Director for Operations, App 22399-128.
- 8402280283 Forwards addit comments on CROR Meeting 50 for includion in meeting minutes
 STELLO, V Committee to Review Generic Requirements, 83/12/02, DIRCKB, W J. Office of the Executive Director for Operations ip.
- --8402280289 Submits add) comments on minutes of CRQR Meeting BO BCINTO, J NRC - No Detailed Affiliation Given B3/11/21 BTELLO, V., MATTBUN.R., JURDAN.E. NRC - No Detailed Affiliation Given ip 22399,205.

1

- B402280501 Notification of CROR Meeting 50 on 831026, in response to request for expeditious review of draft itr re Util Safety Classification Group concerns on NRC position on terms important to safety & safety-related STELLO-Y Regional Operations & Generic Requirements 83/10/21 MATTBON.R.J Office of Nuclear Reactor Regulation, Director JORDAN, E. L. Director's Office, Office of Inspection and Enforcement CLANIKOHAM, R. Office of Nuclear Material Safety & Safeguards, Director 2pp 22402 285
- 6402280547 Bubmits summary of Beismic Qualification Util Group program outlining seismic capability of equipment used in nuclear power plants Masting on 840320 requested to discuss program SMITH.N.P. Seismic Qualification Utility Group 84/02/17 DENION.H R Office of Nuclear Reactor Regulation, Director 4pp 22406-252

SECY POSITION PAPERS BEFORE THE COMMISSION

830727020& BECY-83-289

Requests Commission approval for FR publication of notice of proposed rulemaking re pressurized thermal shock DIRCKB H J Office of the Executive Director for Operations 83/07/15 85pp 22177 007

8401190057 Board Notification 84-032 provides add1 info on environ qualification Submittal augments info in Board Notifications 84-004 & 84-007.

EIBENHUT, D.O. Division of Licensing 84/02/13 Atomic Safety and Licensing Board Panel 10pp 22314 204 24X Fiche 50-000, 84/02/13. 8401170059

--8402210280 BECY-83-4578
Provides Commission w/info developed by Bandia on equipment qualification & other matters
DIRCKB,W J Office of the Executive Director for Operations
84/01/10 28pp 22314 235 24X Fiche 50-000,84/02/13,8401190059

8402010423 Responds to FDIA request for BECY-83-311 "Proposed Insider Safeguards Rules," including apps, annexes & other math. Forwards BECY-83-311 & BECY-83-311A COM88.T. DPfice of the Becretary of the Commission 83/11/28 MARTIN.C.J Association for Advancement of Psychology ip

--8309120062 Forwards corrected Page 4 to SECY-83-311 rs proposed insider safeguards rules a effice of the Secretary of the Commission 83/08/25 Office of the Secretary of the Commission 2pp 22060.004

8402010444 Responds to FOIA request for SECY-83-288 & SECY-83-443 to be placed in PDR SECY-83-288 available in FDR SECY-83-443 being placed in PDR Forwards SECY-83-443 FELTON-J M Division of Rules and Records 84/01/17, YENDUSKAS, J Rewsan & Holtringer 1p. 22061-272. 24X Fiche 50-000.84/01/17, 8402010444,

--B402010453 BECY-83-443
Informs Commission of info obtained re flux reduction programs for pressurized thermal shock at lead plants, since 630225 interim rept (BECY 83-079).
DIRCKS,W J. Office of the Executive Director for Operations.
83/10/28, 11pp 22061 273, 24X Fiche 50-000,84/01/17,8402010444

8402010480 Responds to appeal re-denial of FOIA request for BECY-B2-4&6. "Preliminary Staff Analysis of Steam Generator Tube Ruyture Risk " Forwards requested document. Document also exitlable in PDR CHILM.S.J. Office of the Secretary of the Commission B3/11/08 JORDAN, W. S. Harmon & Weiss. 1p. 22061 320

-8212130066 Draft Commission paper re 821118 Commission briefing on multiple steam generator tube ruptures. Draft "Summary of Risk Analysis for Steam Generator Tube Rupture Events" encl 318088 M.J. Office of the Executive Director for Operations 82/11/24, 15pp 22061, 321

8402010491 Responds to FOIA request for BECY-83-318 & AEOD/T316 to be placed in PDR Forwards documents. Info partially deleted (ref FOIA Exemption 5). AEOD/T316 available in PDR FELTON.J.H Division of Rules and Records 83/11/15, QRABER, L D NUS Corp 2pp. 22060.339. 24X Fiche 50-289,83/11/15,8402010491

--8402010494 SECY 83-318
Informs that ALAB-698 draft order reversed ASLAB decision requiring emergency support director at TMI-1 to authorize protective action recommendations
MALSCH.M 9 Office of the General Counsel ZERBE, J E Office of Public Affairs 83/08/04 3pp 22060 341 24x
Fiche 50-289,83/11/15,8402010491

8402030047 SECY-84-010
Provides Commission w/info re detection of PORV corrosion
& corrective actions PORV refurbished w/fully qualified
noncorroded parts & is now acceptable
DIRCKS.W J Office of the Executive Director for Operations
84/01/09 4pp 22091 0B1 24X Fiche 50-289,84/01/09,8402030047

8402060028 Further response to appeal re denial of POIA request for documents concerning steam generator problems at facility Forwards App A documents App B documents partially withheld (ref FOIA Exemption 4) DIRCKB, W J Office of the Executive Director for Operations 83/10/27 DORDSHOW, J Three Mile Island Alert 7pg 22111 153

8402070027 Responds to FOIA request for SECY-83-202, "Generic Lessons Learned From Completed Licensing Reviews," to be placed in PDR Forwards SECY-89-202 Document also placed in PDR FELTON.J M Division of Rules and Records 83/12/27 ADATO.M Union of Concerned Scientists ip 22142 256

--8402070032 BECY-83-202
Responds to Commission request for views on generic lessons
learned from completed licensing reviews of human factors
areas
DIRCKB.W J Office of the Executive Director for Operations
83/05/26 7pp 22142 257

8402070039 Final response to FOIA request for documents re emergency operation facilities located 10-20 miles from nuclear plants to info approving/denying location over 20 miles away Forwards listed documents Info also in PDR FELTON.J H Division of Rules and Records 83/11/04 0'NEILL,J H Bhaw. Pittman. Potts & Trombridge 1p 22142 140 24X Fiche 50-000,83/11/04,8402070039

~-8309120090 SECY-83-363
Recommends Commission agree w/approval of util position to establish common backup emergency operations facility for Prairie Island & Monticella nuclear generating plants DIRCKB.W J Office of the Executive Director for Operations 83/08/30 86pp 22142 181 24X Fiche 50-000.83/11/04.8402070039

8402080039 Further response to FOIA request for documents re revised proposed rule on physical protection requirements for nonpower reactor licensess Forwards App A documents App B documents entirely withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records 83/11/04 AFTERGOOD.8 Committee to Bridge the Gap Spp 22172 269

--B211290127 BECY-82-456
Recommends that Commission approve publication for public comment of proposed amends to 10CFR73 Amends will establish physical protection requirements for nonpower reactor licensees possessing quantities of strategic BNH DIRCKS:H J Office of the Executive Director for Operations B2/11/16 R9pp 22172 287

8402080408 SECY-83-079
Commission paper providing info obtained at recent licensee meetings re planning & status of flux reduction programs concerning pressurized thermal shock.

DIRCKS, W J Office of the Executive Director for Operations 83/02/25. 464pp 22171 121

8402130007 Responds to appeal re denial of FDIA request for documents concerning investigation of oilegations at facility.Forwards App A documents Documents completely & partially withheld (ref FDIA Exemptions 7 & 4).
CHILK. 8 J. Office of the Secretary of the Commission BERNABELL. Government Accountability Project 44pp. 22238 100

--8402130182 SECY-83-065
Provides Ofc of Policy Evaluation immediate effectiveness analysis of Palo Verde licensing board decision for Unit 1. Related info encl
ZERSE, J E Office of Policy Evaluations 83/02/15 25pp.
22240 100

8402130498 Responds to FOIA request for SECYS 83-268.271.278.281.299. 305.306 & 307 Forwards SECY 83-271.83-278 & portions of five other SECYS as listed on App A Info partially withheld (ref Exemptions 5 & 7) FELTON.J M Division of Rules and Records 83/11/28 WEISS.E R Harmon & Weiss 4pp 22237 220 24% Fiche 50-000.83/11/28.

--8307200092 SECY-83-271
Informs that on 830630. US Court of Appeals for BC Circuit issued oginion which vacates & remands for reconsideration 820630 interim final rule suspending 820630 deadline for environ qualification of electrical equipment SLASGIE.E L Office of the General Counsel 83/07/05 32pp 22237 224 24X Fiche 50-000.83/11/28.8402130498

--9402130538 SECY-83-305

AUXIJUOUS SECY-83-305

Recommends that transcript of Commission 830621 meeting on TMI-1 restart be withheld in entirety under Exemptions 5 & 10 of Sunshine Act FlitZBERALD, J A Office of the General Counsel 83/07/28 ip 22237 340 24% Fiche 50-000,83/11/28/8402130498

---8402130544 SECY-B3-306

102130344 8ECY-83-304
Recommends that transcript of Commission 830330 meeting on pending investigations & possible enforcement action at TMI-1 be withheld in entirety under Exemptions 3 & 7 of Bunshine Act
FITZGERALD.J A Office of the General Counsel 83/07/28 ip 22237 341 24X fiche 50-000.83/11/28.8402130498

--8402130549 SECY-83~307

Recommends that transcript of Commission 830606 meeting on pending investigations at TMI-1 be withheld in entirety under Exemptions 5 & 7 of Bunshine Act FITZOERALD. J A Diffice of the General Counsel. 83/07/28 FITZOERALD, J.A. Office of the General Counsel. 22237 342 24X Fiche 50-000.83/11/28.8402130498 83/07/28 3pp

8402230344 SECY-84-007
Informs Commission of progress in developing long-term
approach for dealing wistress corrosion cracking in BWR
piping Future NRC actions & schedule for completing
recommendations discussed
DIRCKS W J Office of the Executive Director for Operations
84/01/10 5pp 22377 042

8402230347 SECY-B4-009A
Updates status rept on BWR pipe cracks & protection of upcoming licensee actions Insp results encl Evaluation & recommendations re interim & long-torm remedial measures expected by Hay 1984
DIRCKS

8402230429 Responds to FDIA request for SECYs 83-32,988,228,228,240,246 & 261 to be placed in PDR Forwards SECYs 83-228A,261 & 240 SECYs 83-228.240,246 & 261 partially withheld fref FDIA Exemption 6) SECYs 83-32.988 & 228A available in PDR FELTON.J M Division of Rules and Records 83/12/07 GRABER.L.D. NUS Corp 4pg 22371 269 24X Fichs 50-000.83/12/07,8402230429 Exemption ... FELTON.J M Di

--8402230432 SECY-83-228A
Discusses NRC suggestion to change policy & allow distribution of illuminated gunsights to general public. MALSCH.MC Office of the General Counsel 83/07/19. 13pp 22371 273

--8402230439 SECY-83-240

Discusses disposition of Suffolk County motion for Commission ruling on LILCO emergency preparedness plan, MALSCH.M O Office of the General Counsel 83/06/20 22371 291 24X Fiche 50-000.83/12/07.8402230429 53pg,

--B402230434 BECY-83-261
Discusses Safe Power for Maine 821020 request for show cause order re licensee alleged lack of financial qualifications.
MALSCH,M G. Uffice of the General Counsel DD-83-03. 83/06 5pp 22371 286 24X Fiche 50-000,83/12/07,8402230429.

8402240179 Responds to FOIA request for SECY-B3-404 to be placed in FDR Forwards SECY Document also available in FDR. FELTON, J M Division of Rules and Records 84/02/07. BUCKLES, R NUS Corp ip 22381.289 24% Fiche 50-289, 84/02/07, 8402240199

--8402240200 SECY-B3-404

NVERTURING TREET STATES
Advises Commission of evaluation of thiosulfate contamination & PORV corrosion problem at TMI-1, as requested in S Chilk 830810 memo stemming from ALAB-724
DIRCKS.W.J. Office of the Erecutive Director for Operations ALAB-724 83/09/30 2pp. 22381 290 24X Fiche 50-289,84/02/07,8402240199

8402270284 Further response to FOIA request for all 1982 SECY papers. Forwards SECY-82-140 Document also available in PDR. SECY encls partially & entirely withheld (ref FOIA Exemptions 5 &

7) FELTON, J M Division of Rules and Records 84/02/09 WEISS,E R Harmon & Weiss WEISB,E R Union of Concerned Bcientists 3pp Harmon & Weiss 22375 214

--8402270274 SECY-82-140
Discusses FOIA Appeal 82-A-2c (Devine) re investigative
jurisdiction of IE & Ofc of Inspector & Auditor Transmitts!
of proposed ltr (Attachment 4) recommended Info deleted &
withheld
BICKNIT, L Office of the General Counsel 82/04/05 Sipp

8402270367 Further response to FOIA request for all 1782 SECY papers Forwards SECYS 82-16.0.82-49, 82-61.82-1138 & 82-131 Info partially withheld (ref FOIA Exemption 5) Documents also available in PDR FELTON, J M Division of Rules and Records 84/02/13 HEI88, E R Union of Concerned Scientists 3pp 22411 271 24X Fiche 50-000.84/02/13.8402270367

--8402270375 SECY-82-016D

402270375 SECY-BR-016D
Provides preliminary analysis of opinions issued on 820514
by DC Circuit in Pane vs NRC re psychological effects of
restarting facility Info deleted
MALSCH.N G Office of the General Counsel 82/05/24 10;
22411 275 24X Fiche 50-000,84/02/13,8402270369

--B402270380 SECY-82-049

NOEZ/0380 BECY-84-049
Discusses delay in hearing schedule due to replacement of
Brown & Root, Inc as const contractor, change of design
engineer & const manager to Bechtel, Inc & release of Guadrex
Corp rept Info deleted
FITGERALD, J A Office of the General Counsel. 82/02/04 13pp.
22411 353 24X Fiche 50-000,84/02/13,8402270349.

--8402270384 SECY-82-061

Discusses amends to rules re ex parte communications & separation of functions, proposed on 790301 Info deleted. BICKHIT,L. Office of the General Counsel B2/02/12 lipp 22412 004

--8205060001 BECY-82-113A

Informs of District Court opinion in City of West Chicago Vs NRC Important to prevail on jurisdictional questions to avoid litigation in several district courts

BICKWIT. Office of the General Coursel 82/04/12 9p 82/04/12 9pp.

--B204160195 SECY-Bi-131
Informs Commission of successful defense of lawsuit re CT
Light & Fower.et al vs NRC
FITZGERALD, J % Office of the General Counsel. B2/03/27, 28pp.
22412 024

8402270487 Responds to FOIA request for SECY B3-272, SECY B3-279, BECY B3-311, SECY B3-333 & AEOD/E322 to be placed in PDR. AEOD/E322, SECY B3-292 & SECY B3-333 placed in PDR Portions of SECY B3-299 withheld (ref FOIA Exemption 5). FELTON.J M Division of Rules and Records. 84/01/12. QRABER, L. I NUS Corp. 4pp 22414 194 24X Fiche. 50-277, 84/01/12, 8402270487. ORABER, L. D.

--B308100453 BECY-83-272
Informs of plans to notify all operating LWR licensess that 10CFRSO 44 recombiner requirements not applicable to licensess not reliant on installed safety-grade purge repressurization sys as primary means of hydrogen control. DIRCKB:W J Diffice of the Executive Director for Operations. 83/07/19 9pp 22414:206

--8308240177 BECY-83-339
Recommends approval of publication of final rulemaking to amend 100FR2 200 & 100FR2 201, granting NRC authority to issue notices of violation to nonlicensees & to delegate authority to regional administrators.

DIRCKG.W J Giffice of the Executive Director for Operations 83/08/10 23pp 22414 215

STATE PROG STATE PROGRAMS

8402010042 Notification of contract execution, Mod 2 to "Rediation Monitoring Program Requirements." Contractor State of WA. UMBEL, D Technical Assistance Contracts Branch FIN 8-8551. NRC-32-83-682 B4/01/16. FRIGILLANA, E.B. Region 5, Office of Director HAMADA, Q NRC - No Detailed Affiliation Given. ip 22058 201.

- -8402010043 Mod 2 adding funds for CY84 & changing B&R number, to "Radiation Monitoring Program Requirements"
 * Washington, State of GUSTAVE, R P Technical Assistance Contracts Branch FIN 8-8551 NRC-32-83-682 84/01/16 ip 22058 202
- 8402010032 Notification of contract execution, Mod 2 to "Radiation Monitoring Program Requirements" Contractor State of OR UHBEL, D. Technical Assistance Contracts Branch FIN 8-8554 RRG-32-83-685. 84/01/17 FRIGILLANA, E.B. Region 5, Office of Director. HAMADA, G. NRC No Detailed Affiliation Given 1p 22058 195
- 8402010059 Notification of contract execution.Mod 2 to "Radiation Monitoring Program Requirements" Contractor State of CA WMSEL, D. Technical Assistance Contracts Branch FIN B-8553 NRC-32-83-684, 84/01/16 FRIOILLANALE B Division of Resource Tanagement & Administration HAMADA.O NRC No Detailed Affiliation Given 1p 22058 190
- --8402010065 Mos 2, adding incremental funding & changing B&R number, to "Radiation Monitoring Program Requirements"

 ** California, State of QUSTAVE, R P Division of Contracts FIN R-8553 NRC-32-83-684 84/01/16 ip 22058 \$91
- B402010072 Notification of contract execution, Mod 3 to "Radiation Menitoring Program Requirements" Contractor State of MO UMBEL.D. Technical Assistance Contracts Branch FIN 8-8454 MRC-30-63-643 84/01/18 BCH.DBSEL.L A Division of Resource Kanagement & Administration DESTMANN.M J NRC No Detailed Affiliation Given 19 22048 122
- --8402010081 Mod 3. providing funding, to "Radiation Monitoring Program (02010001 Now 67) Requirements." • Hisspuri, State of QUSTAVE, R P. Division of Contracts. FIN 8-8454. NRC-30-83-643 84/01/18 1p 22048-123
- 8402010171 Notification of contract execution, Mod 3 to "Radiation Monitoring Program Requirements" Contractor State of MN UMEEL D Technical Assistance Contracts Branch. FIN 8-8452 NRC-30-83-645. 84/01/19. SCHLOBERG, LA Division of Resource Hanagement & Administration DESTMANN, M J NRC No Detailed Affiliation Given 19 22048 056
- 6402010234 Ack receipt of 831212 ltr re State Liaison Officers 831207 aseting. Points made at meeting discussed DAYIS.J. Q. Office of Nuclear Material Safety & Safeguards, Director 00222. 84/01/06 BALL, W Q. Mississingi, State of 2pp 22047:317.
- 8402010265 Notification of contract execution, Mod 3 to "Radiation Monttoring Program Requirements." Contractor State of CH. UMBEL, D. Technical Assistance Contracts Branch FIN 9-8450 NRC-30-84-644, 84/01/13, 8CHLOSER, L. A. Division of Resource Management & Administration CESTMANN, M. J. NRC No Detailed Affiliation Given. 1p 22046:354 24X Fiche: 50-346, 84/01/13, 8402010265.
- -8402010273 Mod 3, providing funds for CY84 & incorporating environ monitoring at Davis-Besse, to "Radiation Monitoring Program monitoring at Davis-Besse, to "Nadiation monitoring Program
 Requirements."

 JACKBON.D.L Dhid, State of, QUSTAVE, R.F. Division of Contracts
 FIN 8-8450 NRC-30-83-646, 84/01/13 2pp 22046-355 24X

 Fiche: 50-346, 84/01/13, 8402010265.
- 8402010325 Notification of contract execution, Mod 5 to "Radiation Nonitoring Program Requirements." Contractor. State of WI UMBEL. D. Technical Assistance Contracts Branch. FIN 8-8453. NRC-30-83-647. 84/05/19 SCHLDSERF.L.A. Division of Resource Management & Administration. OESTMANN. M. J NRC No Detailed Affiliation Given. 1p. 22059:312
- --B402010328 Mad 5, providing increased funding, to "Radiation Monitoring Program Requirements"

 * Wisconsin: State of, GUSTAVE.R P Division of Contracts, FIN B403, NRC-30-83-647, 84/01/19, ip 22059.313
- 8402010331 Notification of contract execution.Mod 3 to "Radiation Monitoring Program Requirements" Contractor State of M1.
 UMBEL.D Technical Assistance Contracts Branch. FIN B-8451
 NRC-30-83-644. 84/01/19. SCHLOBBER.L A. Region 3. Office of Director. CESTMANN, M. J. NRC No Detailed Affiliation Given. ip. 22059:309.

- --8402010333 Mod 3, providing funding for CY84, to "Radiation Monitoring Program Requirements "

 * Michigan, State of QUBTAYE, R P Division of Contracts FIN 8-8451 NRC-30-83-644 84/01/17 ip 22057 310
- B402010385 Notification of contract execution.Mod 1 to "Radiation Program Monitoring Requirements" Contractor State of AL. UMBEL.D Technical Assistance Contracts Branch FIN B-8405 NRC-29-83-626 84/01/23 MALEY.R J Region 2. Office of Director MONTGOMERY.D M NRC No Detailed Affiliation Given 1 22059 317
- --9402010387 Mod i,providing incremental funding to "Radiation Monitoring Program Requirements" * Alabama, State of CUSTAYE.R P Division of Contracts FIN 8-8405 NRC-27-83-626 84/01/23 ip 22059 318
- 8402010522 Expresses appreciation for 830913 itr re NRC-state relations relative to high lovel nuclear waste LM Bohlinger designated point of contact for both NRC & DOE consultation process TREEN.D C Louisiana, State of 00183 83/11/04 BAVIS,J G DEFice of Nuclear Material Bafety & Safaguards, Director ip 22061.341
- B402020031 Bummary of 810429 meeting re concerns of EO Wermund, Univ of Texas at Austin, involving NRC contract work in State of TX BRAUN, J 0 Licensing Process & Integration Branch 00054 81/07/07 BUNTING, J O Licensing Process & Integration Branch 22062 306
- --8402020037 Expresses concern to NRC contract work in Paio Duro Basin Bensitive scientific programs should be coordinated w/Texas Energy & Natural Resources Advisory Council HERMUND, E. 9 Texas, Univ. of, Austin, TX, 00054 81/06/17 JUNNSON, R. L. High Level Waste Technical Development Branch 19 22062, 309
- 8402020042 Responds to 830203 submittal re State of MI comments on draft site characterization plan Passage of Public Law 97-425 heightens need for candor & frankness between DOE & states w/potential nuclear waste repositories GREEN, J.W. Mississippi, State of. 00061 83/03/01. GEORGE. C Energy, Dept. of 5pp. 22062 300
- 8402020033 Summary of 820721 meeting w/State of MS Energy & Transportation Board in Bilver Spring.MD re state participation in high level waste litensing & site characterization rept reviews
 ULECK.R B. High Level Waste Technical Development Branch. OOR 82/08/18 MILLERIB J High Level Waste Technical Development Branch. ip 22042 274
- 8402020056 Ack receipt of B31011 ltr requesting designation of contact person for NRC coordination w/State of TX Primary contact should be designated by Governor White LEMIS, G D. Texas, State of 00167 83/10/24 DAVIS, J 0 Office of Nuclear Material Safety & Bafeguards, Director 1p 22062 253
- BAO2020063 Ack receipt of ltr re communication between State of LA & NRC.Requests to be advised of any developments NUNEZ.8 B Louisians. State of ODIS2 B3/IO/19 DAVIS.J C Office of Nuclear Material Safety & Bafeguards.Director 1p 22062.272
- 8402020080 Responds to recent ltr requesting State of TX designate primary contact for NRC coordination w/state Primary contact should be designated by Governor White HDBBY, H Taxas, State of B3/10/04, DAVIS, J G. Office of Nuclear Material Safaty & Safeguards, Director. ip 22062 284.
- B4020200B7 Ack receipt of B30913 ltr Requests NRC communicate any & all matters re relations w/State of LA concerning disposal of hazardous wastes HAINKEL, J. J. Louisiane. State of B3/09/26 DAVIS, J. G. Office Nuclear Material Bafety & Bafeguards, Director ip 22062 283 3,**J G. Office of** 22062 283
- 8402020101 Forwards State of WA 840103 itr requesting technical assistance on raview of Nuclear Packaging. Inc high integrity container for use at Hanford site. Response requested by 840203 NUSSBAUMER, D. A. Assistant Director for State Agreements Programs 84/01/17 HIGGINBOTHAM. L. Low-Level Waste & Uranium Recovery Projects Branch. 1p. 22062 280
- --8402020103 Requests technical assistance in evaluation & approval of Nuclear Packaging, Inc FL50 high integrity container Addendum A to "Evaluation of Nuclear Packaging, Inc FL50 Container" encl W/s encl STRONO.T R Washington, State of, 84/01/05, NUSSBAUMER.D A Assistant Director for State Agreements Programs 1p. 22062, 281

- 8402020155 Discusses 831207 meeting re high level waste repository licensing in which NRC should establish relationship w/states similar to policy delineated in Section 117 of Nuclear Waste Policy Act BALL, W G Tennessee, State of 202 83/12/12 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director 1p 22062 231
- 8402020214 Forwards review & comments re draft NRC Licence
 12-13536-01 Conditions imposed by by-product and source
 matl license issued by State of SC should be adopted
 verbatum by NRC to avoid conflict between two licenses
 SHEALY.H G South Carolina, State of 84/01/10 NUSBBAUMER, D A
 Assistant Director for State Agreements Programs 4pp 22062 153
- B402020378 Forwards trip rept of attendance at State of UT high level activities state liaison officer meeting COLLINS, J T Region 4, Office of Director 00028 83/05/16 DIRCKS, M J Office of the Executive Director for Operations DAVIS, J G Office of Nuclear Material Safety & Bafeguards, Director ip 22042 208
- --8402020391 Discusses trip to Salt Lake City.UT to meet ω/state liaison officers re high level waste activities SANBORN.6 Region 4, Office of Director 00028 83/05/12 CCLLINS.J T Region 4. Office of Director 2pp 22042 209
- --B402020424 Transcript of 830503 & 04 public hearings on proposed nomination of sites in salt deposits for detailed site characterizations recommendations on issues to be addressed in environ assessments & site characterization plans
 TOMBIC.OR Utah, State of 00028 83705704 i7pp 22062 211
- B402020468 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements" Contractor State of GA UMBEL.D Technical Assistance Contracts Branch FIN 18-8404 NRC-27-83-828 84/01/20 MALEY.R J Region 2. Office of Director MONTGOMERY.D M NRC No Detailed Affiliation Given 1p 22062 161
- --8402020470 Mod 1.adding incremental funding & incorporating environ monitoring.to "Radiation Monitoring Program Requirements"

 * Georgia. State of GUSTAVE.R P Division of Contracts FIN B-8404 NRC-29-83-625 84/01/20 1p 22062 162
- 8402030070 Notification of contract execution, Mod i to "Radiation Monitoring Program Requirements" Contractor State of MS UMBEL.D Technical Assistance Contracts Branch FIN B-8400 NRC-29-83-621 84/01/19 MALEY, R J Region 2. Office of Director MONTODMERY, D M NRC No Detailed Affiliation Given ip
- --8402030096 Mod 1.providing incremental funding to "Radiation Monitoring Program Requirements" * Mississippi, State of GUSTAVE.R Division of Contracts FIN B-8400 NRC-29-83-621 84/01/19 tp 22091 025
- 8402030202 Notification of contract execution, Mod 3 to "State Legislative Reporting Svcs " Contractor Public Affairs Info. Inc.
 - PERLMAN. J Administrative Contracts Branch FIN 8-1592 NRC-06-83-266 84/01/06 KERR.W 9 Office of State Programs. Director LANDAU.M NRC - No Detailed Affiliation Given. 19
- ---B402030207 Mod 3 exercising option to extend period of performance to B50106 % increasing amount of contrart, to "State Legislative Reporting Svcs"

 * Public Affairs Information Inc HAGAN T F Division of Contracts FIN 8-1592 NRC-06-83-266 B4/01/06 ip 22089.359
- B40203034B Notification of contract execution. Mod 2 to "Radiation Monitoring Program Requirements" Contractor Univ of Iosa, UMBEL.D Technical Assistance Contracts Branch FIN 8-8456 NRC-30-83-64B B4/01/19 SCHL085ER.L A Division of Resource Management & Administration. OESTERMANN, M J. NRC No Detailed Affiliation Given 1p 22089, 356
- --8402030352 Mod 2.increasing funding to "Radiation Monitoring Program Requirements" * Iowa, Univ of, Iowa City, IA GUSTAVE, R P Division of Contracts. FIN 8-8456 NRC-30-83-648 84/01/19 1p 22089 357
- 8402060012 Further response to FOIA request for three categories of documents Forwards App A documents FELTON, J M Division of Rules and Records B3/10/31 PUNTENNEY, J Bafe Energy Coalition 4pp 22091:230
 - 8402050018 Forwards four categories of correspondence for Commissioner Ahearne Cogius of any info sent to Commissioner Ahearne should be sent to N Haller W/o encl KERR-0 W Office of State Programs. Director 82/09/09. DAVIS. J NRC - No Detailed Affiliation Given 19 28091 262

- 8402060097 Forwards State of MA Amend 16 to US Ecology License NN-I019-2 for Richland low level waste disposal sits NUSBBAUMER.D A Assistant Director for State Agreements Programs. 84/01/13 DAVIS.J Diffice of Nuclear Material Safety & Safeguards.Director DENTON.H Diffice of Nuclear Reactor Regulation, Director DEYOUNG, Director's Office of Inspection and Enforcement 31pp 22110 026
- 8402060104 "State of MS Position Statement rs Federal Legislation on Nuclear Waste Mgt" # Mississippi, State of 225 82/06/30 9pp 22110-014.
- 8402060172 Confirms 840124 telcon re ES Fuente 840112 ltr forwarding Amend 10 to Licensa NPF-13 & accompanying safety evaluation W/o encl SCHWENCER, A Licensing Branch 2 84/01/26 FUENTE, E 8 Hississippi, State of 2pp 22106 315 24X Fiche 50-416, 84/01/26, 8402060172
- 8402060498 Notification of contract execution, Mod 1 to "Rediation Monitoring Program Requirements" Contractor State of NE UMBEL.D. M Technical Assistance Contracts Branch FIN B-8303. NRC-31-83-670 84/01/26 MEYENB.D M Region 4. Office of Director NICHOLAS.J B NRC No Detailed Affiliation Given 19 22110 162
- --B402060502 Mod 3.providing funding & changing B&R number, to "Radiation Monitoring Program Requirements"

 * Nebraska, State of GUSTAVE.R P Division of Contracts. Fth B-B503 NRC-31-B3-670 84/01/26 1p 22110 163
- 8402060514 Notification of contract execution.Mod 1 to "Radiation Monitoring Program Requirements" Contractor Btate of PA UMBEL.D Technical Assistance Contracts Branch FIN B-8356. NRC-28-B3-607 84/01/26. MCGSCAR.J Region 1, Office of Director KUTTAN.J NRC No Detailed Affiliation Given 1p 22092.OBL.
- --8402060524 Mod 1, providing funds, changing B&R number & NRC authorited representative, to "Radiation Monitoring Program Requirements,"

 * Pennsylvania, Commonwealth of, GUSTAVE, R P Division of Contracts FIN B-8356 NRC-28-83-607 84/01/26 ip 22092,082
- 8402060531 Notification of contract execution. Mod 1 to "Radiation Monitoring Program Requirements." Contractor State of VT UMBEL.D Technical Assistance Contracts Branch FIN 19-8351. NRC-28-83-605 84/01/24 MCDSCAR.J Region 1, Office of Director KOTTAN, J NRC No Detailed Affiliation Given. ip 22092-141.
- --8402060534 Mod 1,providing funds, changing B&R number & NRC representative, to "Radiation Monitoring Program Requirements,"

 ** Vermont, State of, GUSTAVE, R. P Division of Contracts. FIN B-8351 NRC-28-83-605 84/01/26 1p 22092.142
- 8402060538 Notification of contract execution. Mod 1 to "Radiation Monitoring Program Requirements" Contractor State of MD. UMBEL.D Technical Assistance Contracts Branch FIN 8-8353 NRC-28-83-608. 84/01/26 MCOSCAR.J. Region 1. Office of Director KOTTAN.J NRC No Detailed Affiliation Olven. 1p. 22078.137.
- --8402060542 Mod 1.providing funds.changing B&R number & NRC authorized representative to "Radiation Monitoring Program Requirements."

 * Haryland, Btate of GUSTAVE, R P Division of Contracts, F1N B-8353, NRC-28-83-608 84/01/26 ip 22092 140
- 8402060585 Notification of contract *xecution, Mod 1 "Radiation Monitoring Program Requirements" Contractor State of TN UHBEL, D Technical Assistance Contracts Branch. FIN 8-8401. NRC-27-83-622 84/01/19 MALEY, R J Region 2. Office of Director MONTODMERY, D M. NRC No Detailed Affiliation Given 1p
- --B4020605B9 Mod 1, providing funds for CYB4 & changing consideration & payment, to "Radiation Monitoring Program Requirements,"

 * Tennessee, State of. GUBTAVE.R P Division of Contracts FIN B-8401. NRC-27-83-622 B4/01/17 1p. 22092:088
- 8402060612 Notification of contract execution, Mod 2 to "Radiation Monitoring Program Requirements" Contractor State of SC.
 UMBEL.D. Technical Assistance Contracts Branch. FIN B-8403.
 NRC-97-83-624 84/01/26 MALEY.R J Ragion 2, Office of Director ip 22092 083
- --8402060618 Mod 2, providing add1 funds for CY84 & incorporating environ monitoring for period Jan 1984 Dec 1985. to "Radiation Monitoring Program Requirements" # South Carolina, State of FIN B-8403, NRC-29-83-624. 84/01/26 1p 82092 084

- B402070104 Notification of contract execution.Mod 2 to "Radiation Monitoring Program Requirements" Contractor State of TX UMBEL D M Division of Contracts FIN B-8405 NRC-31-83-671 B4701/26 MEYERS D M Region 4. Office of Director NICHOLAS. NRC No Detailed Affiliation Given ip 22142 239 NICHOLAS, J D
- --B402070108 Mod 2, providing funding & changing B&R number, to "Radiation Monitoring Program Requirements"

 * Texas, State of GUSTAVE.R P Division of Contracts FIN 8-8405 NRC-31-83-671 84/01/26 ip 22142 240
- 8402070110 Responds to 831123 ltr summarizing findings of Oct 1983 audit of State of OR radiation control program Corrective audit of State of Dr. rediction tollers; program corrective actions underway. Issues involving agreement w/NRC should be addressed to Board of Health (CEBIE: K M Oregon, State of 84/01/23 MARTIN.) © Region 5, Office of Director 4pp 22100 184
- --8402070112 Contends that State of OR rules disallowing shipping or transport of radioactive matl w/o compliance w/federal notification rules consistent w/requirements of 100FR/1 97 & need not be modified

 FRANK,L. Oregon, State of 84/01/06 HORNOR,J Region 5, Office of Director 9pp 22100 188
- 8402070115 Notification of contract execution, Mod 1 to "Radiation Modiforing Program Requirements" Contractor State of DE UMBEL, D Technical Assistance Contracts Branch. FIN 8-0352 MC-028-63-602 84/01/26 MCOBCAR, J Region 1, Office of Director METAN, J NRC No Detailed Affiliation Given 1p 22142-237
- --8402070123 Mod 1, providing funds, changing B&R number & NRC authorized representative, to "Radiation Monitoring Program Requirements." quirements." Delaware, State of GUSTAVE,R P Division of Contracts FIN 3352 NRC-28-83-402 84/01/26 ip 22142:238
- 8492070200 Notification of contract execution Mod i to "Radiation frogram Monitoring Requirements" Contractor State of CT UMBL.D. Technical Assistance Contracts Branch FIN B-8358 MRC-28-B3-604 B4/01/24 MCOBCARJ Region 1 Office of Director KOTAN, J NRC ~ No Detailed Affiliation Given 1p 22142-140
- --8402070296 Mod 1, providing funds, changing B&R number & NRC authorized representative, to "Radiation Monitoring Program Requirements"

 Connecticut, State of GUSTAVE, R P Division of Contracts FIN B-8358 NRC-28-83-604 B4/01/26 ip. 22142 141
- 840207027B Notification of contract execution.Mod 1 to "Radiation Monitoring Program Requirements." Contractor. State of MA UMBEL.D M Technical Assistance Contracts Enanch Fin B-B350 NRC-28-88-566. B4701/24 MCOSCAR.J Region 1, Office of Director KOTTAN.J NRC No Detailed Affiliation Olvan 1p 22142 146
- --8402070307 Mod 1, providing funds, changing B&R number & NRC authorized representative, to "Radiation Monitoring Program Requirements "
 - Massachusetts, Commonwealth of GUSTAVE,R P Division of htracts FIN B-8350 NRC-28-83-606 84/01/26 ip 22142 147
- 8402070315 Notification of contract execution. Nod 1 to "Radiation donttoring Program Requirements" Contractor State of NH WHELLO Technical Assistance Contracts Branch FIN B-8364 NRC-28-83-611 84701/26 MC050ARJ, Region 1, Office of Director KDTTAN, J NRC No Detailed Affiliation Given 1p 22142:142.
- --9:02070323 Mod 1. providing funding changing N&R number & NRC authorized representative to "Radiation Monitoring Program Requirements"
 - New Hampshire, State of QUSTAVE, R P Division of Contracts | 8-8364 NRC-28-83-611. 84/01/26 ip 22142-143. FIN 8-8364
- B402070334 Notification of contract execution.Mpd 1 to "Radiation Manitoring Program Requirements" Contractor: State of NC.

 WASEL, D. Technical Assistance Contracts Branch FIN 8-B406,
 MC-97-83-627 84/01/29 MALEY.R J. Region 2, Office of Director MANTGOMERY, D. M. NRC No Detailed Affiliation Given 1p
- --Bi02070343 Mod i providing funds for CYB4 & changing Article V. to *Radiation Monitoring Program Requipments."

 † North Carolina, State of GUSTAVE.R P Division of Contracts FIN B-8406. NRC-29-83-627 84/01/23. 1p. 22142:145
- 8402070403 Notification of contract execution. Mod 1 to "Radiation Monitoring Program Requirements" Contractor State of NJ WHSEL, D Technical Assistance Contracts Branch FIN B-8354 NRC-28-83-609 B4/01/26 MCDSCAR. J Region 1. Office of Director KOTTAN. J NRC -- No Detailed Affiliation Given. 1p 22142 135

- -8402070418 Mod 1, providing funds, changing B&R number & NRC authorized representative, to "Radiation Monitoring Program Requirements"

 * New Jersey, State of CUSTAVE, R P Division of Contracts FTN B-8354 NRC-28-83-609 84/01/26 1p 22142 136
- B4020B0043 Further response to FOIA request for documents re cleanup & decision to close U mill, in Edgemont.SD Forwards App A, B & C documents Review of remaining documents subj to request in progress
 FELTON, J M Division of Rules and Records 83/11/01 GARBUS, M
 Frankfurt, Garbus, Klein & Sell 10pp 22169 009
- --7912:80235 Discusses 791107 telcon re program to assess required offsite remedial action for Edgemont/SD NRC has no objections to TVA procedures for soil sampling TRAGER.E A Uranium Recovery Licensing Branch 79/11/14 KALLEMEYN,V South Dakota, State of 1p 22169 259
- --84020800A3 Notifies that author assumed responsibilities of State Radiation Control Program director on 800918 Duties associated w/Edgemont V mill Edgemont offsite cleanup project & general radiation activities BRICH.R South Dakota. State of 81/01/14 MCGRATH.J Assist Director for State Agreements Programs 1p 22169 027
- --8402080078 Discusses Covernor Kneip 761108 concerns re Phase II studies If ERDA includes Edgemont mill in Phase II studies, Kneip concerns will be resolved.

 KERN, O W Assistant Director for State Agreements Programs 76/11/18 RYAN, R G Office of State Programs, Director ip 22169 079
- B402080474 Notification of contract execution, Mod 2 to "Radiation Monitoring Program Requirements" Contractor State of LA UMBEL, D M Technical Assistance Contracts Branch FIN B-8502 NRC-31-83-669 84/01/24 MEYER8, D M Region 2, Diffice of Director NICHOLAS, J B NRC No Detailed Affiliation Given 1p 22174 050
- --B4020804Bi Mod 2:providing funds for CY84 & changing B&R number, to "Radiation Monitoring Program Requirements" * Louisiana. State of OUSIAVE.R P Division of Contracts FIN D-8502 NRC-31-83-669 84/01/24 ip 22174 051
- 8402080498 Notification of contract execution, Mod 2 to "Radiation Manitoring Program Requirements" Contractor State of CO UMBEL, D H Technical Assistance Contracts Branch FIN B-B501 NRC-31-83-668 84/01/24 HEYERS, D M Region 4, Office of Director NICHOLAS, J D NRC No Detailed Affiliation Given 1p 22174,066
- --8402080497 Mod 2.providing funds for CY84 & changing B&R number, to "Radiation Monitoring Program Requirements " * Colorado, State of GUBTAVE,R P. Division of Contracts FIN B-8501 NRC-31-83-668 84/01/26 tp 22174 067
- B402090845 Notification of contract execution.Mad 1 to "Radiation Monitoring Program Requirements" Contractor State of VA UMBEL.D Technical Assistance Contracts Branch FIN B-8402 NRC-99-83-629 84/01/19, MALEY.R J Region 2. Office of Director MONTGONERY, D. M. NRC No Detailed Affiliation Given in
- --8402090548 Mod 1, providing funds for CYB4, to "Radiation Monitoring Program Requirements"

 * Virginia, Commonwealth of, GUSTAVE.R.P Division of
 Contracts FIN 8-8402 NRC-29-83-623 84/01/19 1p 22191 361
- 8402100089 Notification of contract execution, Mod 2 to "Radiation Monitoring Program Requirements" Contractor State of AR.
 UNUELL D M Technical Assistance Contracts Branch FIN 8-8500.
 NRC-31-83-667 84/01/26 MEYER8.D H Region 4: Dffice of Director NECHOLAS.J B NRC No Detailed Affiliation Civen 19 28205 083
- --8402100093 Mod 2, providing funds for CY84 & changing B&R number, to "Radiation Monitoring Program Requirements" A Arkansas, State of. GUSTAVE.R P Division of Contracts FIN B-BB00 NRC-31-83-667 B4/01/26 jg 22205 084
- B402100300 Forwards additemments on responses to approval of high integrity container design for EPICOR-II profilter wastes State should review US Ecology venting procedures for high integrity container NUSBBAUMER, D.A. Assistant Director for State Agreements Programs, 84402,01. KIRNER, N. Washington, State of, Dept. of Social & Health Services. 2pp. 22205-359
- B402100433 Comments on proposed MOU re interstate low level raduaste compact NRC should conduct preevaluation of site suitability to carry out waste inse program & implement review to datermine program effectiveness MURLEY, T.E. Region 1, Office of Director 83/10/26 KERR, G.W. Office of State Programs, Director. 1p. 22213-032

- 8402100434 Supports proposed Section 2741 MOU for states participating in low level waste compacts Viable method of giving states appropriate legal authority to conduct insy necessary MIGGINLE A Atomic Industrial Forum 83/11/30 Office of State Programs, Director 1p 22212 362
- 8402100435 Comments on proposed MOU for states participating in low level waste compacts NRC authority to enter into MOUs per Atomic Energy Act of 1954. Section 274i. disputed NRC should defer action pending results of Congressional reviews KEARNEY. J Edison Electric Institute 83/11/27 Office of State Programs. Director 4pp 28213 006
- 8402100436 Endorses JJ Kearney 831129 comments re proposed 2741 MOU for states participating in low level waste compacts TROSTEN.L M LeBosuf, Lamb. Leiby & MacRae TROSTEN.L M Electric Utility Companies Nuclear Transportation Group 93/11/29 Office of State Programs. Director ip 22210 362
- 8402100437 Comments on proposed 274i MOU for states participating in low level waste compacts Initial insp by state inspectors to satisfy state packaging & shipping requirements could be followed w/onsite insps on as needed basis CAREY.J J Duquesne Light Co B3/11/22 Office of State Programs, Director 2pp 22213 004
- B402100437 Comments on proposed 274i MOV for states involved in low level waste compacts Legal requirement for MOV does not exist if MOV developed, sections should be rewritten WILLIAMS, JW Flortda Power & Light Co 83/12/01 KERR, 0 W Office of State Programs, Director 3pp 22213 001
- 8402100440 Interposes no objections to intent & content of proposed 2741 MOV for states participating in low level waste compacts
 ANDERSON, H K Virginia, Commonwealth of, 83/11/30 Office of State Programs, Director ip 22212 261
- 8402100443 Comments on proposed 274i MOU for states participating in low level waste compacts Preamble language suggesting that Low Level Radwaste Policy Act authorizes states to manage low level waste should be deleted HDFFMAN.8 Kerr-McGee Corp 83/11/29 Office of Btate Programs, Director 4pp 22211 359
- B402100444 Comments on proposed 274i MOU for states participating in low level waste compacts States should be authorized to inspect waste packaged on premises of low level waste generators under mutually acceptable arrangements ROBINSON.R 0 American College of Nuclear Physicians LOKEN,M K Bociety of Nuclear Medicine 83/11/29 Office of State Programs, Director 2pp 22213 010
- 8402100446 Comments on MOU for states participating in low level waste compacts Specific performance criteria for state inspector precommended. Reporting requirements should be clarified to prevent duplicative reporting
 THORPE.J R General Public Utilities GPU Service Corp 83/11/30
 Office of State Programs, Director 2pp 22213 013
- 8402100448 Comments on proposed 274: MOU for states participating in low level waste compacts Statement 5 re insp of Federal premises should not be altered or deleted COFFMAN,F E Energy, Dept of 83/12/02 KERR,O W Office of State Programs, Director ip 22213 018
- 8402100451 Comments on proposed MOV re insp powers of compact states MOV should be revised to prevent duplication &/or overlapping regulatory authority SCHUYLER.J O Pacific Gas & Electric Co 83/12/01 KERR.O W Office of State Programs. Director ip 22213 016
- 9402100461 Responds to FOIA request for Governor Janklow 831019 ltr & NRC response Forwards ltre FELTON, J M Division of Rules and Records 83/11/30 PAY, D Affiliation Not Assigned 1p 22212 252
- --B402100464 Requests info re State of SD adopting plan to comply w/Low Level Radwaste Policy Act. State of SD legislature investigating available options JANKLOH, W J South Dakota, State of. 83/10/19 KERR, G W Office of State Programs, Director Syp 22212 253
- --8402100465 Forwards response to 831019 request for info re low level radwaste compact formation. NUREG-0762, describing state role in radwaste regulation per low Level Radwaste Policy Act of 1980, encl. M/o NUREG

 KERR. G W Office of State Programs. Director 83/11/16

 JANKLOW, N J South Dakota. State of 5pp 22212 256

- B402130532 Comments on proposed 2741 MOU for states involved in low level waste compacts Authority to investigate & correct waste mgt practices posing threat to public health may be restricted HUNGERFORD.5 W Alaska, Btate of B3/11/17 KUNIHIRO,D Region 5, Office of Director 2pp 22213 358
- 8402140070 Ack receipt of 840104 comments re 1983 review of State of SC radiation control program Comments will be incorporated into final rept WODDRUFF,R L. Region 2. Office of Director 84/01/20 SHEALY,H of South Carolina, State of ip 22217 188
- 8402140086 Ack receipt of 840104 ltr responding to comments following 1983 review of State of SC radiation control program Comments & responses will be incorporated into final rept of review MUDDRUFF,R L Office of State Programs, Director 84/01/20, SHEALY,H 0 South Carolina, State of 1p 22217 263
- 8402140115 Comments on Agreement State program evaluation Internal procedures established & medical insp repts will document pertinent info, including molybdenum breakthrough & dose calibrator GA tests
 SHEALY, H. 9. South Carolina, State of 84/01/04 O'REILLY, J. P. Region 2. Office of Director 1p. 22217 049
- 8402140125 Ack receipt of 840104 & 831221 ltrs re State of KY radiation control program Program for agreement matis adequate to protect public health & safety & compatible w/NRC regulations
 O'REILLY, J P Region 2. Office of Director 84/01/27 BELL. |
 Kentucky, Commonwealth of. 1p 22218 244
- 8402140310 Forwards response to technical comments per NRC 831205 lir re review of State of KY radiation control program Prelicensing imaps will be conducted for applications requiring comprehensive mgt review HUGHES.D R Kentucky, Commonwealth of, 83/12/21 D'REILLY, J.P. Region 2, Office of Director 5pp 22228 247
- B402140330 PND-IV-83-010D on B40201, TX Appeals Court handed down judgment re Mar 1983 order suspending Gulf Nuclear, Inc license, On B30929 NRC filed amicus curiae brief Am-241 exposure incident resolved DDDA, R J Region 4, Office of Director 84/02/08 2pp 22221 045
- 8402140405 Responds to 831205 ltr re insp of State of KY radioactive matls program State of KY approx 30% delinquent in insp phase of program due to staff turnovers & decreased staffing levels

 BELL, I Kentucky, Commonwealth of, 84/01/04 O'REILLY, J.P. Region 2, Office of Director 1p 22220 357
- 8402140479 Comments on 830603 ltr re review of State of NC radiation control program, including level of staffing in radioactive matis program, staff for emergency planning, surveillance of nuclear shipments & low level raduaste mgt MORROW, S T North Carolina, State of 83/11/15. G'REILLY, J P Region 2, Office of Director 2pp 22226 212
- B402140584 Forwards Dec 1983 highlights re UMTRA project. State of MY signed cooperative agreement Shiprock draft environ assessment & draft remedial action plan distributed & Durango DEB released MORLEY. J A Energy. Dept of 84/02/02 MARTIN. D Low-Level Matte & Uranium Recovery Projects Branch HIGGINBOTHAM. L Low Level Haste Licensing Branch LICMTMAN, S. Environmental Protection Agency 500 22256 324.
- 8402150027 Ack receipt of 831223 Itr in response to 1983 review of State of MA radiation control program Proposed changes will enable program to satisfy "Quidelines for NRC Review of Agreement State Radiation Control Programs "MARTIN-JB Region 5. Office of Director 84/02/08 BEARE.J Washington. State of. Dept of Social & Health Bervices. ip
- 8402190293 Forwards distribution list denoting correct number of documents listed individual supposed to receive.
 ROWLEY.L W North Carolina, State of 84/02/07 KNIGHTON, 9, W Licensing Branch 3 4pp 22250 084 24X Fiche 50-400, 84/02/07, 8402150273
- 8402150429 Comments on proposed 2741 MCU for states participating in low level wasts compacts MCU most appropriate for non-Agreement States MILSON,E F Arkansas, State of 83/11/28 KERR,O W Office of State Programs, Director, ip. 22263-311

- 8402150434 Discusses comments on proposed 2741 MOU for states, published in 48FR49362 on 831026 MOU can be modified to accommodate non-Agreement States by providing disposal capacity for waste generated in state LANDAU M Assistant Director for State & Licensee Relations 84/01/25 KERR, 0 W Office of State Programs, Director 5pp 22257 115
- E402150436 Comments on proposed 2741 MOU MOU does not recognize efficience of state authority in area of low level radwaste mgt. Including treatment storage & disposal EICHBAUM, H H Maryland, State of 83/12/27 KERR, G W Office of State Programs, Director 2pp 22258 357
- BIO2150438 Comments on proposed MOU for states participating in low level raduaste compacts MOU should be revised to indicate that NRC will evaluate state insp functions if insps will be used for enforcement actions MIBBINK,R. Q 3M Co. Minnesota Mining & Mfg Co. B3/12/01 Office of State Programs, Director 2pp 22258 355
- 8402150442 Opposes state authority to determine packaging & shipping compliance w/NRC stds NRC should porform all insps & be permitted to inspect any facility w/o prior notice CARNILA.B T Affiliation Not Assigned 83/11/25 Office of Strangeman, Director 1p 22298 290 Office of State Programs, Director
- 8402150445 Comments on proposed 2741 MOU MOU oversteps NRC statutory authority & treads illegally on states right under Low Level Radwaste Policy Act not to join compact or to withdraw PAY.D Technical Information Project 83/11/23 Office of State Programs. Director 2pp 22258 287
- B402150447 Comments on proposed 274i MOU for states participating in low level waste compacts NRC should withdraw proposed MOU for consistency w/Low Level Radwaste Policy Act of 1780 PATIERSDN.J D Middle South Services. Inc. 83/12/04 XERR.G W Office of State Programs. Director 2pp 22238 285
- 840213045; Ack receipt of proposed MOU for state insp of waste practices of NRC licensess Questions limitation re unannounced inspa GAMILLI,R L. California, State of 83/12/01 KERR,O W Office of State Programs, Director 1p 22263 248
- 8402150495 Comments on MOU between NRC & each state within compact
 Addition of proposed insp program would be redundant
 considering present regulation stds & would incur add1
 expense & time delays.
 ANDOCHINIS C Arizona Public Service Co NOLD 83-341 '83/12/07
 Office of the Secretary of the Commission 2pp 22263 245
- 8402130364 Notifies of 840126 meeting in Olympia.WA to discuss draft consultation & cooperation agreement QCMUD.B E Washington, State of QCA74 84/01/23 NRC No Detailed Affiliation Given ip 22258 360
- 8402150566 Provides NRC point of contact w/State of NV re Nuclear Waste Policy Act of 1982 & other issues re storage & disposal of high level radwaste matls BRYAN, R H. Navada. State of 00202 84/01/30 DAVIS, J 0 Office of Nuclear Material Safety & Safeguards, Director 1p 20258 359
- B402150570 Forwards Draft 1 of site technical position, "Repository Design Issues for State of NV Storage Site Investigations" NATARAJA: M S Engineering Branch (Post 831001) 00200. 84/01/30 COPLAN. B. M Repository Projects Branch (Post 831001) ip 22263-012.
- --8402150872 Draft site technical position "Repository Design Issues for State of NV Nuclear Waste Storage Investigations." Division of Waste Management. 00200 84/01/31 36pp.
- 8402160003 Third partial response to FDIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 (HILL 8 J. Office of the Secretary of the Commission B3/12/14 Public Document Branch, ip 22281 023, 24% Fiche 50-000, 83/12/14, B402160003.
- --8402160303 Discusses SECY-82-41 re proposed amended agreement between MRC & State of CO per Section 274 of Atomic Energy Act of 1954. CHILK, B J Office of the Becretary of the Commission SB2-41
 B2/03/01 DIRCKS, W J. Office of the Executive Director for
 Operations, lp. 22281,162 24X Fiche: 50-000, B3/12/14, 8402160003

- -8402160179 Discusses 56CY-82-110 re objective performance indications for evaluation of Agreement State radiation control programs
 CHILM.S J Office of the Secretary of the Commission 82/04/27 DIRCKS, W.J. Office of the Executive Director for Operations 22281 184 24X Fiche 50-000, 83/12/14, 8402160003
- --8402160401 Discusses SECY-63-68 re objective performance indicators for Evaluation of Agreement State radiation control programs
 CHILK.S.J. Diffice of the Secretary of the Commission 83/05/24
 DIRCKB.W. Office of the Executive Director for Operations 1p
 22281 288 24X Fiche 50-000.83/12/14,8402160003
- --8402160435 Discusses SECY-83-201 re publication of revised Criterion 9 for guidance of states & NRC in discontinuance of NRC regulatory authority & assumption thereof by states through agreement OHICKS J Diffice of the Secretary of the Commission B2/ DIRCKS,W Office of the Executive Director for Operations 22281 298 24% Fiche 50-000,83/12/14,8402160003 82/06/28
- -8402160257 Discusses SECY-81-646 re proposed agreement between NRC & State of WA per Section 274 of Atomic Energy Act of State of wa per Section 2/4 or Avonic Energy Act or 1754.as amended
 CHILK-5 J Office of the Secretary of the Commission S81-644
 82/01/07 DIRCKS.W J Office of the Executive Director for Operations 1p 22281 147 24X Fiche 50-000.83/12/14.8402160003
- 8402140340 Confirms J McGrath/W Eichbaum & D Rech discussion re review & evaluation of State of MD radiation control program Comments re three Category I indications provided Requests state plan to address problems W/o stated encl.

 MURLEY, T E Region 1. Office of Director 84/02/02 WILZACK, A Maryland, State of App 22269 342
- 8402170248 Forwards organizational chart list of members & member duties for Energy & Transportation Board Nuclear Waste Policy Advisory Council & Nuclear Waste Technical Review Committee Committee HAGGARD.K A Mississippi, State of of Waste Management lipp 22313 202 84/02/03 MATTSON.D Division
- B402170277 "High Level Nuclear Waste Mgt Legislative Proposals," status as of 840203 * Washington, State of 84/02/03 1p 22313 212
- 8402170289 Forwards borehole sealing research & application. Rept deals primarily w/salt areas & studies in State of TX. 81MPKINS, H W Texas. Univ of Austin. TX 84/01/31 RHDDERICK, J Division of Waste Management 33pp 22313 297
- B402170270 Requests listed documentation be forwarded in order to complete review of high level nuclear waste repository tesue issue DRIVER, B.M. Utah, State of 84/02/06 MATTSON, D. NRC - No Detailed Affiliation Given 3pp 22313 231.
- B402170298 Responds to 830913 ltr re implementation of Nuclear Waste MATTER T Texas, State of. 83/10/13 DAVIS, J 0 Office of Nuclear Matter T Texas, State of. 83/10/13 DAVIS, J 0 Office of Nuclear Material Safety & Safeguards, Director 2pp 22313 223
- 8402170516 Forwards Amend 38 to State of CA License 097, clarifying license conditions re waste form
 NUBSHAUMER.D A Assistant Director for State Agreements Programs
 84/01/24 DAVISI, J Office of Nuclear Material Safety &
 Safeguards. Director DENTON.H Office of Nuclear Reactor
 Regulation. Director DEYOUNO.R Director's Office, Office of
 Inspection and Enforcement Opp #2918 355
- 8402220063 Comments on State of AR program for regulation of agreement matls Program adequate to protect public health & safety NRC guidelines, technical comments & recommendations encl COULING.J T Region 4, Office of Director 84/02/16 BALTZMAN.B N Arkansas, State of 5pp 22337 306 PALT7MAN. II N
- 8402270072 Final response to FOIA request for Commissioner voting & attendance records from 810401 to present Forwards documents listed on App A Documents also available in PRR FELTON.J.H Division of Rules and Records 83/12/22. XAMENAR.P.D Washington Legal Foundation Spp 22410 109
- --B402270165 Discusses SECY-82-42 re proposed amended agreement between NRC & State of TX per Section 274 of Atomic Energy Act of 1954,as amended
 CHILK.S J Diffice of the Secretary of the Commission S82-4
 82/02/26 DIRCKS.W J. Office of the Executive Director for
 Operations 1p 22410 254.

- 8402270625 Submits notice of upcoming meetings, per 830719-20 meeting Notice will be updated weekly Requests T Taylor be notified of any add meetings not listed NEFF. J D Energy, Dept of 84/02/10 MILLER, H NRC No Detailed Affiliation Given CHRISTOFFERSON Utah. State of FRISHMAN, B Texas, State of 1p 22412 360
- 8402280103 Tentative agenda for High Level Nuclear Waste Advisory (Council 840217 meeting in Lacey MA to discuss update on state actions * Energy, Dept of 84/02/17 Energy, Dept of 3pp
- 8402280187 Discusses 831101 appreisal of performance under State of GA environ monitoring contract, culminating in B31114 mgt meeting Based on good performance & cooperation continuation of contract recommended OLSHINSKI, J.A. Region 2, Office of Director 83/12/15 LEDBETTER, J.L. Georgia. State of ip 22400 258
- 8402290447 Forwards list of persons responsible for coordinating radioactive maths mgt.nuclear safety & licensing Requests copies of correspondence to specified contacts be provided to DK lacker
 WHITE.N Texas. State of 84/02/02 PALLADING Commissioners
 300 22438 184
- TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE
- 8401270132 Forwards nonproprietary "Safety Injection Nozzle Thermal Liner" & "Resistance Temp Detector Thermowell," for docketing & distribution VAN BRUNT,C E Arizona Public Service Co ANPP-28681-WFQ/ 84/01/24 KNIGHTON,G W Licensing Branch 3 ip 22038 001 24X Fiche 50-528,84/01/24,8401270132
- --8402010433 CEN-264(V)-NP Nonproprietary "Rept on Palo Verde Unit 1 Safety Injection Notice Thermal Liner" * Combustion Engineering, Inc. 84/01/24 32pp 22038 002 24) Fiche 50-528,84/01/24,8401270152
- --8402010437 Nonproprietary "Rept on Palo Verde Unit 1 Resistance Temp Betector Thermowell " * Combustion Engineering, Inc 84/01/24 100pp 22038 034 24X Fiche 50-528,84/01/24,8401270152
- 8401270182 Forwards draft Commission paper & NUREO documenting NRC evaluation & conclusions re need for rapid depressurization capability un current C-E plants w/o PORVs Review & comments requested by 840204
 DENTEN. R Office of Nuclear Reactor Regulation, Director 84/01/13 STELLO, V Regional Operations & Generic Requirements 100pp 22079 045
- E402010050 Forwards Rev 2 to DAM-1474, "B&W Dwners Group Program for Evaluation of Reactor Vessel Properties" HUDSDN.C J Dabcock & Wilcox Operating Plants Cumers Group, ESG-055 B4/01/27 KADAMBI,N P NRC - No Detailed Affiliation Given 1p 22042 193
- --B402010063 BAW-1474 RO2 Rev 2 to "B&W Owners Group Program for Evaluation of Reactor Vessel Properties" * Beboock & Wilcor Co 83/11/30 50pp 22042 194
- 8402010195 Forwards "Analysis of Capsule T From TVA, Sequoyah Unit 1 Reartor Vessel Radiation Surveillance Program " No changes in Tech Spec pressure temp limit curves required MILLS, L M Tennessee Valley Authority 84/01/24 ADENSAM, E Licensing Branch 4 2pp 22036 130 24X Fiche 80-327,84/01/24, 8402010155
- -8402010162 WCAP-10340
 "Amalysis of Capsule T From TVA, Sequoyah Unit 1 Reactor
 Vessel Radiation Surveillance Program"
 MAGER, T R . YANICHKO, S E . ANDERSON, S L Westinghouse Electric
 Corp 83/05/31 76pp 22038.132 24X Fiche 50-327,84/01/24,840201035
- 102010282 Application to amend License DPR-28 revising Tech Epers to reflect change in main steam line low pressure isolation setpoint while in run mode, from 850 to 800 psig per NUREG-0737, teem II K 3 16 HEIDERLE H Vermont Yanker Nuclear Power Corp FVY 84-5, 84/01/23 EISENRUT, D & Division of Licensing 5pp 22040 276 24X Fichs. 50-271, 84/01/23, 8402010282

- --8402010287 NEDD-22243-1
 Rev I to "Safety Evaluation of MSIV Low Turbine Inlet
 Pressure Isolation Setpoint Change for Vermont Yankee
 Nuclear Power Station "
 CORNWELL.K F., HONG.F S General Electric Co DRF E52-000012
 83/05/31 17pp 22040 288 24X Fiche 50~271.84/01/23.8402010282
- 8402010410 Generic Ltr 84-04 to all operating PMR licensess.CP holders & applicants for CPs re safety evaluation of Westinghouse topical repts dealing w/elimination of postulated pipe breaks in PWR primary main loops Svc list encl
 LIEENHUTID 0 Division of Licensing QL-84-04 84/02/01
 Consolidated Edison Co of New York, Inc 59pp 22177 097 24x
 Fiche 50-000.84/02/01.8402010410
- 8402020270 Forwards proprietary proposed Amend 9 to Rev & to "OE 8td Application for Reactor Fuel," & justification review sheets for listed changes Encl withheld (ref 100FR2 790) CHARNLEV.J S General Electric Co 84/01/25 THOMAS.C O Standardization & Special Projects Branch 3pp 22055 063
- 8402060090 Forwards revised table re B&W Owners Group assignments Oroup understanding of purpose of identifying lead contact persons for both Owners Group & NRC delineated CROUSE, R P Toledo Edison Co N84-016 84/01/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 22088-278
- 8402060240 Forwards nonproprietary "Interim Rept on Performance Evaluation of Palo Verde Control Element Assembly Shroud" VAN BRUNT, E E Arizona Public Bervice Co ANPP-28756-WFQ/ 84/01/31 KNIGHTON.G Licensing Branch 3 1p 22084 213 24X Fiche: 50-528, 84/01/31.8402060240
- ---B402060247 CEN-267(V)-NP
 Nonproprietary "Interim Rept on Performance Evaluation of Palo Verde Control Element Assembly Shroud "

 * Combustion Engineering, Inc. 84/01/31 Bipp 22084: 214 247 Fiche, 30-528, 84/01/31, 8402060240
- 8402060337 Forwards Endorsements 47 & 48 to MAELU Policy MF-85. Endorsements 108 & 109 to NELIA Policy NF-111.Endorsement 41 to MAELU Policy MF-84 & Endorsement 107 to NELIA Policy NF-83 BOTHMAN.J E McDermott, Inc 84/02/02 DINITZ.I Division of Engineering 7pp 22083 108
- 8402070052 Submits comments re rev to LLL Insp Procedures 81475-B1490 requesting clarification of paragraph stating that IE inspector reviews security plan & use of traditional nomenclature re SNM THOMAS, CO Bandandization & Special Projects Branch 84/01/26 MCKEE, P F Operating Reactors Program Branch, 1p 22142:241
- 8402070265 Forwards comments on 840110 draft NURE9-1070, "Severe Accident Program for Nuclear Power Plant Regulation" RAHE, E P Westinghouse Electric Corp NS-EPR-2880 84/01/30, EISENHUT, D 9 Division of Licensing 4pp 22101.323
- 8402070363 Responds to Generic Ltr 83-41 Emergency generator sys for security sys started every 7 days Burveillance testing conducted 5 times in past 12 months REGANN A Babcock & Wilcox Co GL-83-41 84/01/31 EIBENHUT.D C Division of Licensing 2pp 22099 322
- 8402080003 Forwards request for add1 info re Westinghouse Topical Rept WCAP-10125(P), "Extended Burnup Evaluation of Westinghouse Fuel " Responses requested by 840224 THOMAS, C O Standardization & Special Projects Branch 84/02/01 RAHE, E. P Westinghouse Electric Corp. 4pp 22172 235
- --8401270103 Forwards request for add1 info,based on preliminary review of Westinghouse extended burnup Topical Rept WCAP-10125 BERLINGER,C H Core Performance Branch, TAC 48689 84/01/12 THOMAS,C Standardization & Special Projects Branch 1p 22172 239
- 8402080147 Provides add1 info re post-irradiation surveillance program, pur NRC 840118 & GE 831123 ltrs Insp of nonleakers not performed on routine basis GE fuel surveillance program currently planned to continue at approx present level CHARNLEY, J & General Electric Co MFN-007-64, 84/01/27, RUBENSTEIN, L & Assistant Director for Core & Plant Systems, 2pp.
- 8402080201 Discusses confirmatory issue re overheating of gadolinia fuel pelists Issue not plant-specific, as NRC contends, but generic. Requests closure of issue on generic basis CHARNLEY.J S General Electric Co MFN-015-84 84/02/02. RUBENSTEIN.L S Assistant Director for Core & Plant Systems. 1p.

- 8402080215 Forwards response to questions in detailed design description & intermediate sys design description per TMI tas II F 2 & "RCB Coolant Inventory Trending W.Rosctor Coolant Pumps Operating " Encl withheld (ref 10CFR2 790) HWKILL.H D General Public Utilities GPU Service Corp 5211-83-379 84/01/31 STOLZ.J F Operating Reactors Branch 4 200 22130 102 24X Fiche 50-287.84/01/31.8402080215
- B402080444 Notification of B40216 fourth quarterly meeting w/EPRI in Bethesda.MD to discuss progress on EPRI LWR standardized plant design evaluation program MORAN.D H Standardization & Special Projects Branch 84/01/31 THROMBS.C D Standardization & Special Projects Branch 3pp 22168 279
- 8402080451 Forwards evaluation re-schedule for resolving & completing Generic leave 80, "Pips Break Effects on Control Rod Drive Hydraulic Lines in Dryweil of BWR Mark I & II Containments "Priority ranking of low approved EMBON.N R Office of Nuclear Reactor Regulation, Director 84/01/26 MATISON.R J Division of Systems Integration (post 81005) 17pp 22168 260
- 8402070225 Requests cost breakdown of charges for review of BAW-10149, Rev I & brief description of how subcontractor charges for review TAYLOR, J H Babcock & Wilcox Co 84/01/30 MILLER, W O License For Kanagement Branch ip 22161 361
- B402090245 Forwards Endorsement 51 to NELIA Policy NF-160 CGMMELL.T.D: Dow Chemical Co 84/01/31 SALTZMAN.J D NRC - No Catalled Affiliation Given 2pp 22157 359
- 8402970273 Forwards proprietary response to NRC comments on steam panestor tube plugging requirements Requests that Tech Spectuse plugging limit for SNUPPS Model F steam generators be stablished Response withheld (ref 10CFR2 790)
 FERRICK.N A Standardized Nuclear Unit Power Plant System SLNRC 84-0017 84/02/02 DENTON.H R Defice of Nuclear Reactor Regulation. Director 2pp. 22160 218 24X Fiche 50-000,84/02/02,8402090273
- 8402070318 BAI-1-245-08-492-01
 *Broad Failure Modes & Effects Analysis for Nuclear Plant
 Sys Partinent to Overcooling Transients "W/two oversize
 trawings sncl. Aperture cards are available in PDR
 s Science Applications, Inc. 82/02/28 102pp 22188 001
- 8102090320 "Failure Modes & Effects Analysis of Pressurizer & Associated Equipment." 8 Science Applications, Inc. 83/05/31 44pp 22187 185
- B402070487 SAI i-245-08-492-00
 "Selection of Nuclear Plant Bys Pertinent to Overcooling Transients"
 1 Science Applications, Inc. 81/11/30 119pp 22192 001
- 8402090515 informs of recent issues re PWR low temp overpressure protection sys & provides clarification of Branch Technical Polition 5-2.

 MERON, B. W. Reactor Systems Branch 84/01/30 Reactor Systems Stanch 14pp. 22186/322
- --840i100029 Discusses meeting w/Westinghouse re low temp overpressure protection/design philosophy & safety factor reduction NRC indicated that exemptions from App G limits must be thoroughly substantiated RLIOT, B J, Materials Engineering Brench MARSH, L B Reactor Systems Branch, B3/12/27 LIAM, B. D Materials Engineering Branch Spp 22186-340
- B402100041 Forwards proprietary "Review of Exxon Nuclear Company Fuel Aliably LCCA-Belimic Response Repts XN-NF-81-51P & RH-NF-876 " Addl info requested by B40201 THOMAS, C O Standardization & Special Projects Branch 84/01/24 CHADLER, J C Exxon Nuclear Co , Inc (subs. of Exxon Corp). 1p 22181 2275.
- B402100321 Notification of 840209 meeting w/C-E in Bethesda, MD to discuss proposed C-E alternate reactor trip sys SULS.D E Operating Reactors Branch 3 84/02/03, MILLER, J. R. Obrating Reactors Branch 3. 2pp 22205 118 24x Fishe.50-335,84/02/03.8402100321

- B402100407 "Rept on Steam Generator Overfill," draft rept CLARK.F H. CLAPF.N E., BROADWATER.R. Oak Ridge National Laboratory B3/10/13 NRC - No Detailed Affiliation Given 72pp 22208 238
- 8402130252 Forwards Generic Ltr 84-04 informing utils of safety evaluation of Westinghause topical repts. Rev 2 to WCAP-9558. WCAP-9787 & Ltr Rept NS-EFR-2519. re elimination of postulated pipe breaks in PWR primary main loops EISENHUT, O G Division of Licensing L505-94-02-010 84/02/01 RAHE, E P Westinghouse Electric Corp 1p 22216 209
- --8402130287 Topical rept evaluation of WCAP-9558.Rev 2,WCAP-9787 & Ltr Rept NS-EPR-2519 Acceptable technical basis provided go asymmetric blowdown loads need not be considered in design basis * Division of Licensing 84/02/01 19pp 22216 213
- --8402130261 "Regulatory Analysis of Mechanistic Fracture Evaluation of Reactor Coolant Piping A-2 Westinghouse Dwnere Group Plants "
 - * Division of Licensing 84/02/01 33pp 22216 232
- B402130325 Forwards presentation made at 840125 meeting w/NRC re Anond 7 to NEDE-24011-P-A Encl withheld (ref 10CFR2 790) CHARNLEY.J S General Electric Co MFN-017-84 84/02/03 BERLINGER.C H Core Performance Branch ip 22197 111
- B402130890 Notification of B40207 meeting w/Exxon Nuclear Corp in Betheeds. MD for presentation & discussion of Exxon generic reload analysis methodology for BMR 9x9 fuel Meeting closed due to proprietary nature of matl MDRAN.D H Stendardization & Epecial Projects Branch B4/02/03 THEMAS.C 0 Standardization & Special Projects Branch 3pp 20214 309
- B402130623 Forwards safety evaluation re Westinghouse generic safety parameter display sys provided in WCAP-10170.per 810306 request for preimplementation review Design & design verification methods acceptable GRUTCHFIELD.D Operating Reactors Branch 5 LSOS-84-02-009 84/02/02 RAME, E.P. Westinghouse Electric Corp. 2pp. 22215 338
- --8402130643 SER re submittals concerning Westinghouse generic safety parameter display sys Design basis acceptable however, design intemplete Requests Westinghouse submit test plan for preimplementation audit
 BELTRACCHIL, LAUBENN, JOYCE, J. NRC No Detailed Affiliation Given 84/02/02 20pp 22215 340
- B402140025 Notification of B40222 meeting w/Westinghouse in Bethesda,MD for Mestinghouse presentation on evaluation methodology for ECCS-entitled "Convention of LDCA Heat Source Uncertainties "
 MORAND.B.H Standardization & Special Projects Branch 1HOMAS.C.O Standardization & Special Projects Branch 3pp
- 8402140438 Forwards "Insp Readiness of Operating Nuclear Reactors for Fire Protection Safe Shutdown " MACDDUOALLE A Brookhaven National Laboratory FIN A-3133-3 84/01/11 HHITNEY, L NRC - No Detailed Affiliation Given ip 22227 186
- --8402140442 "Insp Readiness of Operating Nuclear Reactors for Fire Protection Bafe Shutdown." Final rept THOMAS.H J. MACDOVALL.E A Brookhaven National Laboratory FIN A-3133-3, 83/12/31 NRC - No Detailed Affiliation Given 117pp 20227 187
- 8402150122 Requests that encl documents re Wastinghouse generic safety garameter display sys be placed in PDR BELTRACCHI, L. Human Factors Engineering Branch 84/02/08 BAILEY, J. K. Record Services Branch (Document Control Desk) 2pp 22262,001
- --8211040035 Forwards design verification audit plan for Wastinghouse safety parameter display sys Plan defines technical topics to be evaluated during 821025-27 audit MODRE V A Human Factors Engineering Branch 82/10/13 CRUTCHFIELD, D Operating Reactors Branch 5 ip 22262 003.
- --82ii010467 Definss plan for evaluating safety parameter display systeming to design the design verification activities at Westinghouse Two day technical audit scheduled for 821025-27.
 BELTRACCHI.L. Human Factors Engineering Branch 82/10/05
 MOORE.V A Human Factors Engineering Branch. 24pp 22262 004

```
--8210190584 Forwards results of review of Westinghouse safety parameter display sys design verification & validation program Basics of program acceptable for design & development of sys Draft ltr of transmittal forwarding review encl
KRAMER.J J Division of Human Factors Safety 82/09/29
MIRAGLIA,F J Assistant Director for Safety Assessment 10pp
  --8206030327 Informs of planned staff review of safety parameter display sys fleview structured to facilitate early implementation of sys in control room Audit assignments by discipline encl HATTSON, R. J. Division of Systems Integration (post 811005) THOMPSON, H. Division of Human Factors Safety 82/05/04 CISENHUT, D. O. Division of Licensing 8pp 22262 038
  --9208230400 Summary of 820506 meeting w/Westinghouse in Bethesda.MD re
review & audit of safety parameter display sys Agenda:
attendance list & viewgraphs encl
DELTRACCHI.L. Human Factors Engineering Branch. 82/08/06
MODRE.V A Human Factors Engineering Branch 48pp 22262 046
  --B306150045 Forwards audit rept on Westinghouse generic safety parameter display sys Scope of audit limited to evaluating design & design verification activities BELTRACCHI.L., LAPINSKY.G. Human Factors Engineering Branch 83/05/24 MODRE, V.A. Human Factors Engineering Branch 121pp 22262 113
  8402140497 WCAP-858781R4 ESE-22
         Accepted version of "Equipment Qualification Data Package,"
Rev 4 to Suppl 1.EGDP-ESE-22, "Four Section Power Range
Neutrun Detectors"
RANE, E P Westinghouse Electric Corp EGDP-ESE-22 83/11
            AHE.E P Westinghouse Electric Corp EGDP-E66-82 83/11/30 9pp
22271 030
 --8402160534 WCAP-858781R6
               Accepted version of Equipment Qualification Data Package,"
Rev & to "Methodology For Qualifying Westinghouse Water
Reactor Div Supplied NBSS Safety-Related Electrical
Equipment "
               Reactor Div Gupping Communication Corp. 83/11/30
Equipment "
BUTTERWORTH, G., Miller, R. B. Westinghouse Electric Corp. 83/11/30
43pp 22271 109
8402160277 Forwards Rev 7 to Topical Rept TVA-TR75-1A, "GA Program
Description for Design.Const & Operation of TVA Nuclear
Power Plants "
MILLSL M Tennessee Valley Authority 83/12/12 D'REILLY, J P
Region 2, Office of Director Rpp 22272 003
---B402160286 TVA-TR75-1A R07
Rev 7 to "GA Program Description for Design Const &
Operation of TVA Nuclear Power Plants "
* Tennesses Valley Authority 63/12/12 233pp 22272 005
8402160487 Forwards conpreprietary WCAP-8587, Suppl 1, "Equipment Qualification Data Packages," & proprietary WCAP-8687, Suppl 2, "Equipment Qualification Test Repts " WCAP-9780-A, "Methodology for Seismic Qualification " also forwarded RAHE.C P Westinghouse Electric Corp NB-EPR-2881 84/01/27 THOMAS.C O Standardization & Special Projects Branch 7pp 22270.048
        22270 048
--8402140488 WCAP-838781R3 E5E-17
Accepted version of "Equipment Qualification Data Package,"
Rev 3 to Buppl 1. E0DP-E8E-17, "Solid State Protection Sys
(BSP8) Three Train & Safeguard Test Cabinet "
RAHE, E P Westinghouse Electric Corp EQDP-E8E-17 83/11/30,
14pp 22270 274
--8402160489 Submits application for withholding proprietary MCAP-8687.
Suppl 2, "Equipment Qualification Test Repts." per
10CFR2 790 Affidavit (AM-80-27) encl
WIESEMANN, RA Westinghouse Electric Corp AW-84-05. 84/02/03
THOMAS.C D Standardization & Special Projects Branch Spp
--B402160490 WCAP-B3878184 EBE-21
Accepted version of "Equipment Qualification Data Package."
Rev 4 to Suppl 1.EQDP-EBE-21, "Pressure Sensor"
RAHE, E P. Westinghouse Electric Corp EGDP-EBE-21 83/11/30
14pp 22271 016
   ~8402160471 WCAP-808781R4 EGE-1A
Accepted version of "Equipment Qualification Data Package,"
Rev 4 to Suppl 1.GODP-ESE-1A, "Pressure Transmitters-
Qualification Group A"
RAHE. E P Westinghouse Electric Corp EGDP-ESE-1A 83/11/30
21pp 22270 288
```

```
--8402140492 WCAP-9750-A
             "Mothodology for Seismic Gualification of Westinghouse Water
Reactor Div Supplied Equipment "
KELLY'R E , MCINERNEY'J J Westinghouse Electric Corp. 80/1
60pp 22270 068
                                                                                         Westinghouse Electric Corp. 80/05/
 --8402160493 WCAP-858781R4 EBE-15
Accepted version of "Equipment Qualification Data Peckage,"
Rev 4 to Suppl 1.EQDP-ESE-15, "Recorders Post-Accident
Monitoring "
RAHE, E P Westinghouse Electric Corp EQDP-ESE-15 B3/11/30
12pp 22270 126
  --8402160494 WCAP-8587S1R4 HE-3/H
            NATIONATE WARE SOUTHING HE STATE ACCEPTED YEAR OF "Equipment Gualification Data Package," Rev 4 to Suppl 1.EQDP-HE-3/HE-6, "Safety-Related Externally Mounted Limit Switches (Gualification Group A) "RAHE.E P Westinghouse Electric Corp EGDP-HE-3/HE-6 83 8pp 22270 138
                                                                                                                                                                                  03/11/
---8402160495 WCAP-858781R5 AE-3
Accepted version of "Equipment Qualification Data Partage,"
Rev 5 to Suppl 1.60DF-AE-3, "Chempump Canned Motor Pump
(Dutside Containment) "
RAHE, E P Westinghouse Electric Corp. EQDF-AE-3 83/11/30
17pp 22270 309
 --8402160500 WCAP-8587S1R4 HE-2/H
Accepted version of "Equipment Qualification Data Package,"
Rev 4 to Suppl 1.60DP-HE-2/HE-5, "Safety-Related Solenoid
Valves (Qualification Groups A & B) "
RAHE, E P Westinghouse Electric Corp. EQDP-HE-2/HE-5 B3
16pp 22270 146
--8402160503 WCAP-8587SIR1 ESE-18
Accepted version of "Equipment Qualification Data Package, "
Rev I to Suppl 1.80DP-ESE-18, "Veritrak Pressure
Transmitters Qualification Group A "
RAHE, E P Westinghouse Electric Corp. EGDP-ESE-18 93/11/30
28pp 22270 326
 --8402160505 WCAP-858781R4 ESE-5
           ACCEPTED WORF-SOURSERS ESE-5
ACCEPTED VERSION OF "Equipment Qualification Data Package."
Rev 4 to Suppl 1.EdDP-ESE-5. "Resistance Temp Detectors.RCS
Bypess Manifold "
RAHE.E.P Westinghouse Electric Corp EGDP-ESE-5 83/11/3
13pp 22270 162
                                          Hestinghouse Electric Corp EGDP-ESE-5 83/11/30
 --8402140508 WCAP-858781R5 ESE-2
            O2160508 WCAP-85875185 EBE-2
Accepted version of "Equipment Quelification Data Package."
Rev 5 to Suppl 1.EQDP-EBE-2. "Pressure Transmitters"
Qualification Group II "
RAHE, E P Westinghouse Electric Corp EGDP-EBE-2 83/11/30.
18pp 22271 039
 --8402160509 WCAP-858751R4 EBE-16
Accepted version of "Equipment Qualification Data Package,"
Rev 4 to Suppl I:EQDP-EBE-16, "Solid State Protection Sys
Two Train (Three & Four Bay) & Safeguard Test Cabinet "
RAHE, E.P. Westinghouse Electric Corp EQDP-EBE-16, 83/18
             RAME, E P. West
Bns 22270, 354
                                                                                                                                                                        B3/11/3K
 --B402160510 WCAP-858781R6 EBE-4
Accepted version of "Equipment Gualification Data Packaga,"
Rev & to Suppl 1:EQDP-EBE-4, "Differential Pressure
Transmitters Qualification Group B "
RAHE: E P Westinghouse Electric Corp EGDP-EBE-4 B3/11/30
24pp 22270 175
 --8402160512 WCAP-858781R4 ESE-14
Accepted version of "Equipment Qualification Data Package,"
Rev 4 to Suppl ::CQDP-ESE-14, "Indicators:Post-Accident
Nonstoring "
RAHE, E.P. Westinghouse Electric Corp EGDP-ESE-14, 83/11/3
                               22270 362
 --8402160514 WCAP-858781R4 AE-1
Accepted version of "Equipment Qualification Data Package."
Rev 4 to Suppl 1: EQDP-AE-1, "Medium Pump Motors (Dutside
Containment)"
             Containment) "
RAHE E P Westinghouse Electric Corp EGDP-AE-1. 83/11/30.
13pp 22271 057
--8402140516 WCAP-858791R5 ESE-7
Accepted version of "Equipment Qualification Data Package,"
Rev 3 to Suppl 1.EGDP-ESE-7, "Resistance Temp Datectors. Fast
Response Well Mounted"
RAHE, E P Westinghouse Electric Corp. EGDP-ESE-7 B3/11/3
              14pp 22270 199
```

- --Bt02160518 WCAP-838751R4 HE-4
 Accepted version of "Equipment Qualification Data Package,"
 Rev 4 to Suppl 1.EGDP-HE-4, "Safety-Related Limitorque
 valve Electric Motor Operators (Qualification Group B)
 RAME.E P Westinghouse Electric Corp EGDP-HE-4 B3/11/30
 13pp 28271.070
- --B402160319 WCAP-B5B7SIR4 ESE-3A
 Accepted version of "Equipment Qualification Data Package,"
 Rev 4 to Suppl 1,EQDP-ESE-3A, "Barton Differential Pressure
 Transmitters Qualification Group A "
 RAME, E P Westinghouse Electric Corp EQDP-ESE-3A 83/11/30
 1808 28270 213
- --E402160525 WCAP-BSB781R4 ESE-19
 Accepted version of "Equipment Qualification Data Package,"
 Rev 4 to Suppl 1, EGDP-ESE-19, "Instrument Bus Distribution
 Panel"
 RAME, E P Wastinghouse Electric Corp EGDP-ESE-19 83/11/30
 14pp 22271 083
- --8402140927 MCAP-85878185 ESE-10
 Accepted version of "Equipment Qualification Data Package."
 Rev 3 to Suppl 1.EGDP-ESE-10. "Nuclear Instrumentation Sys
 (NIS) Console (Power Range Channel) "
 RAME.E P Westinghouse Electric Corp EGDP-ESE-10 63/11/30
 10pp 22270 231
- --8402160527 NCAP-858751R5 ESE-18
 Accepted version of "Equipment Qualification Data Package,"
 Ray 5 to Suppl 1, EQDP-ESE-18, "Instrumentation Bus Power
 Supply (Static Inverter) "
 RAHE, E P Westinghouse Electric Corp EQDP-ESE-18 63/11/30
 18pp 22271.097
- --8402160532 WCAP-858781R5 AE-2 Accepted version of "Equipment Qualification Data Perkege," Rev 5 to Suppl 1:EQDP-AE-2, "Large Pump Motors (Outside Containment) " RAHE,E P Westinghouse Electric Corp EQDP-AE-2 83/11/30 19p. 22270 241.
- --8403140335 MCAP-85878185 EBE-6
 Accepted version of "Equipment Qualification Data Package."
 Rev 5 to Suppl 1.EQDP-EBE-6, "Resistance Temp Detectors RCS
 Well Mounted "
 RAHE.E P Westinghouse Electric Corp EQDP-EBE-6 83/11/30
 1489 22270, 260
- --8402160538 HCAP-858781R1 ESE-38
 Accepted version of "Equipment Qualification Data Package,"
 Sev 1 to Suppl 1.EGDP-ESE-3B, "Veritrak Differential
 Pressure Transmitters Qualification Group A "
 RAME, E P Westinghouse Electric Corp. EQDP-ESE-3B 83/11/30
 26pp 22271 154
- 8402160396 Nptification of 840209 meeting w/GE & BNL in Bethesda, MD to discuss ABTPD methodology considerations for GESSAR II severe accident review SCMETTI.D C Standardization & Special Projects Branch 84/02/07 Etandardization & Special Projects Branch 2pp 28302.052, 24X Fithe 50-447,84/02/07,8402160596
- 8402170021 Bummary of 840126 meeting w/EPRI re anforcement study Request for proposal revised per discussions to provide for conducting study in phases & creating outside group to review study methodology & results

 TAYLOR.J M Director's Office. Office of Inspection and Enforcement 84/02/09 DIRCKS, W J Office of the Executive Director for Operations STELLO, V Committee to Review Generic Requirements. CUNNINGHAM, C H Office of the Executive Lagal Director 4pp
- 8402170124 Forwards "Preservice Insp Program for RCS Piping Welds "PETRICK.N A Btandardized Nuclear Unit Power Plant Bystem , SLNRC 84-0032. B4/02/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 22278 054 24X Fiche 50-000.84/02/14, 8402170124.
- --8402170135 "Preservice Insp Program for RCS Piping Welds " LEFEBVRE,B J. Westinghouse Electric Corp RATHBUN,O P Kansas Gas & Electric Co 84/01/12 116pp 22298 055 24X Fiche: 50-000, 84/02/14, 8402170124
- --8402170141 "Preservice Inap Program for RCS Piping Welds "
 LEFEBURE.B.J Westinghouse Electric Corp. STEPANORIC.D M Union Electric Co. 84/01/24 200pp 22298.163 24X Fichs.50-000,84/02/14.8402170124

- B402170167 Comments on proposed policy for severe accidents, per NUREG-1070, "Severe Accident Program for Nuclear Power Plant Regulation "Requirements to demonstrate consideration of insights afforded by risk analysis not well defined SHERWOOD.0 0 General Electric Co MFNW 019-84 84/02/10 EISENMUT, D G Division of Licensing 3pp 22299 009
- B402170254 Forwards notification of NRC B40216 meeting w/EPRI to discuss progress on LWR standardized plant design evaluation program Extends invitation to MD Beckher to address efforts re revs to 100FR50.App R W/o encl
 BERTON, H R Bffice of Nuclear Reactor Regulation, Director B4/02/13 INNOGUE, R B Office of Nuclear Regulatory Research, Director ip 22313 239
- 8402170467 Requests listed info on Westinghouse topical repts for generit topical rept program Response by 840215 requested THOMAS.C D Standardization & Special Projects Branch 84/02/09 RAHE.E P Westinghouse Electric Corp 1p 22308 345 24X Fiche \$0-087.84/02/09.8402170467
- B402210035 Responds to 840111 ltr re improvements in procedures STERN,F Westinghouse Electric Corp 84/02/03 POTAPOVS,U Region 4, Office of Director 1p 22317 254
- 84022100B7 Notification of 840213 meeting w/Westinghouse & Westinghouse Owners Group in Bethesde, MD to disuss Westinghouse steam generator tube rupture events program MANN.B Reactor Systems Branch 84/02/07 SHERON, B W Reactor Systems Branch 3pp 22321 336
- 8402220489 Forwards proprietary & nonproprietary "Comprehensive Vibration Assessment Program for Palo Verde, Unit 1 (89s 90 Prototype)." per SER (NUREO-0852) Proprietary rept withheld (ref 10CFR2 790) SCHERER, A E Combustion Engineering, Inc LD-94-008 B4/02/16 EISCNHUT. D @ Division of Licensing 5pp 22333 057 24X Fiche 50-000, 84/02/16.8402220469
- --B402220496 CEN-263(V)-NP
 Nonproprietary "Comprehensive Vibration Assessment Program
 for Palo Verde Nuclear Generating Station.Unit 1 (Sys BO
 Prototype)." preliminary evaluation of precore hot
 functional measurement & insp programs
 * Combustion Engineering, Inc. B4/02/16 66pp 22333 062 24x
 Fiche 50-000.84/02/16.8402220489
- 8402230102 Forwards "LYNXT Core Trensient Thermal-Hydraulic Program " Rept will be referenced by B&W util customers to support applications TAYLOR,J H Babcock & Wilcox Co 84/01/20 MGRAN,D Office of Nuclear Reactor Regulation, Director ip 22348 202
- ---8402230105 BAW-10156 "LYNXT - Core Transient Thermol-Hydraulic Program" JONES,J H , FIRTH,K J , GLOUDEMANS,J R Babcock & Wilcox Co 84/02/27 260pp 22348 203
- 8402230145 Forwards Rev 1 to "GE EWR Supplemental Relead Licensing Submittal for Pilgrin Nuclear Power Station, Unit 1. Relead A "Rev corrects error noted on Page 13 re plant response to MSIV closure HARRINGTON.H D Boston Edison Co SECO 84-027 84/02/21 VASSALLO.D B Operating Reactors Dranch 2 1p 22361 084 24X Fiche 30-293,84/02/21,8402230145
- B402230433 Summary of B40130 meeting w/Westinghouse & TVA to discuss Nestinghouse topical repts re SWR fuel reloads MORAN.D H Standardization & Special Projects Branch 84/02/15 THOMAS.C D Standardization & Special Projects Branch 3pp
- 840224003B Notification of 840216 meeting w/Transamerica Delaval.Inc Owners Oroup in Wading River,NY to discuss program plan proposed by group to qualify dissel generators CARUSO,R Division of Licensing 84/02/15 BERLINGER.C. Division of Licensing 2pp 22381 308
- B402240062 Forwards preprietary & nonproprietary versions of GEN-279(c)
 "Response to NRC Question on Haterford-3 Bypass Flourate."
 per 840201 request for add1 info on FBAR Sections 4 4 1 4 4
 4 4 2 4. Proprietary version withheld (ref 100FR2 790)
 COOK.K W Louisiana Power & Light Co W3P84-0446 84/02/22
 KNIGHTUN.G W Licensing Branch 3 7pp 22375 169 24X
 Fiche 90-382.84/02/22,8402240062.
- --8402240065 CEN-278(C)-NP
 Nonpreprietary, "Response to NRC Question on Waterford-3
 Bypass Flowrate"
 * Combustion Engineering, Inc. 84/01/16 13pp 22375 176 24X
 Fichs 50-382,84/02/22,8402240062

- 840,2240,222 Notification of B40,223 meeting w/BWR Clumers Group & GE in Bathesda, MD to discuss 831118 submittal providing add1 info re scram discharge piping in response to NUREG-CB03 ECCLESTON, K T Operating Reactors Branch 2 84/02/15 VASSALLO, D B Operating Reactors Branch 2 ip 22381 280
- 8402270061 Summary of 840207 meeting w/Exxon Nuclear Co in Bethesda.MD re reload analysis methodology for BWR 9:9 fuel Agenda & attendance list encl
 MCRAN.D H Standardisation & Special Projects Branch 84/02/14
 THOMAS.C O Standardization & Special Projects Branch 3pp
 22407 327
- 8402270225 Forwards revised organization chart dtd Jan 1984 Changes will be incorporated into next amend to Topical Rept GIBSAR-17A KEDDIS,N N Gibbs & Hill, Inc (subs of Dravo Corp.) 84/02/21 Record Services Branch (Document Control Desk.) ip 22389 111 24X Fiche 50-584.84/02/21,8402270225
- 8402270635 Notification of 840302 meeting w/C-E in Windsor,CT to perform audit of results of Phase I & II testing Agenda encl
 LICITRA,E A Licensing Branch 3 84/02/16 KNIGHTDN,0 W
 Licensing Branch 3 4pp 22414 022 24X Fiche 50-528,84/02/16,8402270635
- B4022B0104 Forwards Amend B to GA-A13010A, "GA Technologies GA Program " Amend reflects changes in name, organization, commitments to latest reg guides & changes in frequency of audits FISHER, C R GA Technologies. Inc /General Atomic Co LRS 015 CRF B4 B4/02/23 HAASS, W P Quality Assurance Branch in 22401 031
- --B40228010B Amend B to "GA Technologies GA Program" + GA Technologies, Inc /General Atomic Co B4/02/29 70pp 22401 032
- 8402280274 Forwards Westinghouse topical rept. "Use of Process Noise Measurements to Determine Response Characteristics of Protection Sensors in US Plants." for review & approval CDUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Northeast Utilities Bif034 84/02/15 YOUNDILOOD.B J Division of Licensing 2pp 22405 272 24X Fiche 50-423.84/02/15,8402280274
- 8402280835 Forwards application for withholding proprietary response to NRC 831028 request for info on WCAP-10106. "Description of Nuclear Design & Analysis Programs for DWRs " Proprietary response withhold (ref 10CFR2 790)
 RAME.E P Westinghouse Electric Corp NS-EPR-2887. 84/02/10
 THOMAS.C O NRC No Detailed Affiliation Olven 1p 22406 289
- --B402280546 Application for withholding proprietary response to request for info on MCAP-10106. "Description of Nuclear Design & Analysis Programs for DWRs "
 HIESEMANN. R A Westinghouse Electric Corp AM-84-11 B4/02/10
 THOMAS.C O NRC No Detailed Affiliation Oiven 1p 22406 290
 - 22280409 Notification of 840223 meeting w/C-E Owners Group in etherda.MD to discuss reactor vessel level monitoring sys Items I C 1.I C 8 & I C 9) IEEMS-I A Procedures & Systems Review Branch 84/02/15 IEMANN.D L Procedures & Systems Review Branch 2pp 22429 081
 - 228070i Notification of B40308 meeting w/Transamerica Delaval Inc [DI] Owners Group in Wading River NY to discuss TDI "roposed program plan to qualify generators .ARUSD R Division of Licensing 84/02/23. BERLINGER C. Division of Licensing 2pp 22414 340 24X Fichs 50-000,84/02/23, 1402280701

- 8402290169 Forwards Westinghouse rept. "Dynamic Collapse of Steam Generator Tubes." per NRC request KOBER.R W Rochester Gas & Electric Corp 84/02/24 CRUTCHFIELD, D. Operating Reactors Branch 5 ip 22425 243 24X Fiche 50-244.84/02/24.8402290169
- --8402270172 B2-7F6-EMVTL-R2
 "Dynamic Collapse of Steam Generator Tubes "
 PRIDEMORE, W H Westinghouse Electric Corp 82/11/16 35pp 22425 244 24X Fiche 30-244,84/02/24,8402270169
- 8402290194 Confirms discussions & commitments made in 840221 mesting w/NRC Emphasizes substantial evaluation, insp.maint & testing efforts accomplished to address problems & verify reliability of Transamerica Delaval, Inc diesel generators HCOAVONY, J P Mississippi Power & Light Co AECM-84/0113 84/02/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 27pp 22425 127 24X Fiche 50-416,84/02/26.8402290194
- 8402270307 Forwards procedures, "Diesel Electric Generating Units" &
 "Extended Operation Test of Diesel Generator 1A." in
 response to 831230 request Procurement, QA & operational
 experience w/diesel generators 1A & 1D discussed
 TUCKER, H B Duke Power Co 84/02/22 DENTON, H, R Defice of
 Nuclear Reactor Regulation, Director ADENBAM, EG Licensing Branch
 4, 4pp 22422 064 24X Fichs 50-413.84/02/22,8402270307
- --8402290312 Procedure CNS-1301 00-2, "Diesel Electric Generating Units '
 * Duke Power Co 84/02/09 225pp 22422.068 24X
 Fiche 50-413.84/02/22.8402290307
- --8402290314 Procedure "Extended Operation Test of Diesel Generator 1A *
 4 Duke Power Co 84/02/29 200p 22422 308 24X
 Fiche 50-413 84/02/28, 8402290307
- 8402290430 Notification of 840302 meeting w/Hydrogen Control Owners
 Group in Bethesda,MD to discuss status of Hydrogen Control
 Owners Group 1/4-scale testing program & response to request
 for addl info received from NRC in Dec 1983
 HOUSTON,M D Licensing Branch 2 84/02/16 SCHWENCER,A. Licensing
 Branch 2 7pp 22438 187 24% Fiche 50-000,84/02/16,8402290430

WASTE MGT NUCLEAR WASTE MANAGEMENT

- B402010001 Forwards minutes of B30719-20 nat1 waste terminal storage program meeting w/NRC & salt state representatives in Columbus, DH Comments on draft agenda for B30920-21 meeting requested NEFF, J D Energy, Dept of O0133 83/08/24 MILLER, H High Lavel Waste Technical Development Branch B8pp 22048:195.
- B402010002 Forwards "Selected NRC Products From High Level Waste Program," in response to B31014 request. Encl describes nature & function of various NRC guidance products MILLER, H J Repository Projects Branch (Post B31001) 00224, 84/01/08 NEFF, J O Energy, Dept of, 1p 22048 292
- 8402010006 "Breathing Zone Rept for Nov 1983" No rept generated tince Cotter Mill did not have mill run CAIN, J Cotter Corp 00768 83/11/30 HAZLE,A J Colorado, State of 2pp 22048 190.
- 8402010010 Notifies of upcoming Jan & Feb 1984 meetings per 830719-20 meetings
 NEFF.J O Energy. Dept of 00208 83/12/23 MILLER.H. NRC No Detailed Affiliation Given CHRISTOFFERSON Utah. State of, FRISHMAN.S Texas, State of 1p. 22048-189.
- B402010011 Advises of 840223 presentation on implementation of QA on U mill tailings remedial action (UMTRA) project MDRLEY, J A Energy, Dept of 84/01/16, HIGGINBOTHAM.L Division of Waste Management ip 22048 185.
- B402010015 Notifies of upcoming meetings in Jan & Feb 1984 per 830719-20 meetings NEFF, J D Energy, Dept of 00221. B4/01/13 MILLER, H NMC -- No Detailed Affiliation Given CHRISTOFFERSON Utah, State of. FRISHMAN, S Texas, State of 1p 22048 157
- B402010018 Forwards for signature, MDU between NRC & DOE rs init exchange & onsite characterization program & licensing needs for potential repository sites in salt prior to const authorization NEFF, J O Energy, Dept of 00101 83/05/04. BENNETT, J. W. Energy, Dept of 4pp. 22048:149

- 8402010022 Forwards "Review of INTERA & ERTEC Ground Water Flow Models of Gulf Coast Galt Domes.LA & MS." for review & evaluation of salt site hydrologic modeling under Interagency Agreement DE-AIP7-79ET44611 RDEENTBON.J B Interior, Dept of Goological Survey 00114 83710/10 NEFF,J O Energy, Dept of 25pp 22048 124
- H02010026 Notifies of upcoming Oct & Nov 1983 meetings per 830719-20 seetings.

 MEFF,J C. Energy, Dept of 00120 83/09/23 MILLER,H NRC N.

 Datailed Affiliation Given TOMSIC.6 Utah, State of FORSYTHE,R

 Mississippi, State of 1p 22048 106
- 3402010066 Forwards summary of BMIP hydrologic working group 840109 into meeting w/DGE, State of WA. PNWL. NRC. Morrison-Knudsen. USGB, Dept of Natural Resources, Umstilla Confederated Tribes & Yaktma Indians in Richland, WA GLSON, O. L. Energy, Dept. of O0657 84/01/09 WRIGHT, R. J. NRC Re Detailed Affiliation Civen MEYER, W. Interior, Dept of, Geological Survey PROVOST, D. Washington, State of 53pp 22058 138.
- 8402010118 Forwards 831116 ltr advising of review of environ assessment Plans will influence character of BWIP workshops WRIGHT, R. Repository Projects Branch (Post 831001) 83/12/18 OLSON.O L Energy, Dept. of ip 22048/316
- 8402010188 Responds to B30117 ltr re distribution of nuclear plant operation/DOE & ONMI documents for salt program Computer list review recommendations listed CHASEL High Level Maste Technical Development Branch 00102 83/04/29. NEFF.J.O Energy Dept of 19pp 22048 013
- 8402010202 Concurs w/suggestion to establish NRC/DOE agreement re info sichange & interactions for potential salt repository sites, per 821110 ltr Meeting suggested to discuss mechanics Review plan for site characterization repts & briefing info encl MillER; H J High Level Waste Technical Development Branch 00344 82/12/01. NEFF, J. O Energy, Dept of ip 22047 361
- 8402010227 Forwards HOU between NRC & DOE re info exchange & consultation on site characterization programs & licensing info needs for putential repository sites in salt prior to application for const authorization HILLER, H. J. High Level Waste Technical Development Branch B3/06/11 NEFF, J D Energy, Dept. of 1p 22047-321
- --B402010229 MOU between NRC & DOE re info exchange & consultation on site characterization program & licensing info needs for patential future repository sites in salt prior to application for const authorization
 MKLER, H.J., CHASE, L. High Level Waste Technical Development
 Branch BENNETT, J. H. Energy, Dept. of 00087 83/06/13 3pp.
 22047:322
- 8402010234 Ack receipt of 831212 ltr re State Liaison Officers 831207 ageting Points made at meeting discussed SAVIS.J. Office of Nuclear Meterial Safety & Safeguards.Director 0222. 84/01/06. BALL.W. O Mississippi, State of 2pp
- 8402010238 Forwards for signature NRC/DDE agreement re consultation on site characterization programs & license info needs for potential repository sites in salt. Agenda topics for first exchange meeting scheduled for Apr 1783 listed NILLER, H J High Level Waste Technical Development Branch. 00105 83/03/17. NEFF, J D Energy, Dept of Spp. 22046:359.
- 8402010269 Requests current summary of type & amount of DOE selt data evailable for licensing info needs.per 830419-20 meetings & 300516 telcon Example formet & content of data summary end (THASELL High Level Waste Technical Development Branch, 00097 83/05/13. NEFF.J.O Energy, Dept. of 3pp 22046 351
- 8402010281 Provides guidance re implementation of 830930 EPA 'mill tailings requirements Ofc of State Programs requested to provide same guidance to Agreement States currently repulating U recovery facilities Related info encl BROWNING, R.E. Division of Waste Management 84/01/09 COLLING, J. T. Region 4, Office of Director 46pp 22047 210.
- 8402010291 Forwards draft analysis of DDE site characterization rept on potential high level radwaste repository site at Hanford, WA serevation. W/o snc1
 HATTSON, D R. Licensing Process & Integration Branch. 00029, 83/05/05. BOHLINGER, L. H. Louisians. State of 2pp 22046:332
- 8602010305 Bummarizes 830419-20 meetings in Columbus, CH re preparation for submittal of Salt Site Characterization Program Steevations made by NRC & DOE & open items listed.

 NEFF, J.O. Energy, Dept. of. 00100 83/05/06, MILLER, H., CHASE, L., JOHNSDN.R. NRC No Detailed Affiliation Given 9pp 22046 289

- B402010308 Outlines policy for interactions between NRC & DDE field afcs Policy to be followed by staff & contractors until expected agreements w/NRC re interaction results in new procedure Cautions against comments re NRC regulations BALLARD.WW Energy, Dept of NE-330 82/05/12 GORANSON.R., KUNICH,M., NEFF,J Energy, Dept of 2pp 22046 238
- B402010314 Requests approval for meeting to discuss design & urganization of accelerated test programs & related statistical techniques Reeting supported w/listed limitations

 STAHL.B Battelle Memorial Institute, Columbus Laboratories 00084
 B3706/16 NEFF,J O Battelle Memorial Institute, Columbus Laboratories 3pp 22046 207
- 8402010322 Summary of third DDE/MRC Pre-SCP meeting on 830809-10 in Columbus, DH re Ofc of Nuclear Waste Isolation & NRC questions on waste package in salt repositories List of attenders & viewgraphs and CHANO. K C High Level Waste Licensing Management Branch 00132 83/08/29 88LL. M J High Level Waste Licensing Management Branch 54pp 22046 133
- 9402010323 Notifies of upcoming meetings during 830920-1219 re natl waste terminal storage program NEFF, J D Energy, Dept of CO122 83/09/16 MILLER, H NRC - No Detailed Affiliation Given TOMSIC. G Utah, State of FRISHMAN, S Texas, State of ip 22046 132
- B402010326 Notifies of upcoming meetings during 030920-1215 re natl waste terminal storage program
 NEFF.J O Energy Dept of 00127 83/09/02 MILLER.H NRC No Datailed Affiliation Given TOMSIC.Q Utah, State of FRISHMAN.S
 Taxas, State of 19 22046 131
- 8402010329 Notifies of upcoming meetings during 831003-1215 to nati waste terminal storage program NEFF, J O Energy, Dept of CO119 83/09/30 MILLER, H NRC - No Detailed Affiliation Given TOMBIC. O Utah, State of FRISHMAN, S Texas, State of 1p 22039 311
- 84020i0347 Notifies of upcoming meetings during 83i017-1215 re natl waste terminal storage program
 NEFF, J D Energy, Dept of OOI13 83/10/11 MILLER, H NRC No
 Detailed Affiliation Given TCMBIC, O Utah, State of FRISHMAN, S
 Texas, State of Ip 22059 358
- 9402010350 Notifies of upcoming meetings during 840126-0301 re natl waste terminal atorage program
 NEFF.J.O. Energy. Dept of 05034 84/01/20 MILLER.H NRC No Detailed Affiliation Given CHRISTQFFERSON Utah. State of FRISHMAN.S Texas. State of 1p 22059 357.
- 8402010360 Notifies of upcoming meetings during 831013-1215 re natiwaste terminal storage program NEFF.J D Energy. Dept of CO112 83/10/14 MILLER, H NRC - No Detailed Affiliation Given TCM91C.Q Utah, State of FRISHMAN. 8 Texas, State of 1p 22059 345.
- 8402010363 Notifies of upcoming meetings during 830920-1215 re natiwaste terminal storage program NEFF.J C Energy. Dept of 00321 83/09/09 MILLER.H NRC - No Detailed Affiliation Oiven TOMBIC.C Utab. State of FRISHMAN. 8 Texas. State of ip 22059:344
- 8402010377 Notifies of upcoming meetings during 830809-1215 re nati waste terminal storage program
 NEFF.J C Energy. Dept of 00145 83/08/05 MILLER.H NRC No Detailed Affiliation Given. TOMBIC.0 Utah. State of FRISHMAN.S Texas. State of ip 22059-326
- 8402010381 Forwards position on implementation of 10CFR61 re law level waste, incorporating comments from EEI Util Nuclear Haste Mgt Group & States of SC:NV & WA HIGGINBOTHAML, Low-Level Haste & Uranium Recovery Projects Branch 84/01/10 STANFORD,R Edison Electric Institute, App 22059 319
- 8402010424 Forwards summary of 830627~28 meetings w/DDE in Bilver Bpring.MD re preparation of selt site characterization plan List of attendees encl MILLER, H.J. High Level Waste Technical Development Branch. 00157 B3/07/07 NEFF, J D Energy, Dept. of 169pp. 22059,057
- 8402010427 Concurs w/recommendation to provide written response to hearing issues summarized in OMMI-505. NEFF.J O Energy, Dept of. c0116 83/10/07. GOLDSMITH.S. Ohio. State of. ip 22061 309

- 8402010430 Notifies of upcoming Sept.Grt & Dec meetings re performance assessment exploratory shaft design & tests & annual civilian radwaste mgt info
 NEFF.J O Energy, Dept of 00130 83/08/26 MILLER.H NRC No
 Detailed Affiliation Given FRISHMAN.S Texas, State of FORSYTHE.R Mississippi, State of ip 22061 307
- 8402010443 Extends invitation to be featured speaker at 630920 meeting w/representatives of four salt states & NRC at BMI in Columbus.CH Draft agenda encl NEFF.J O Energy. Dept of O0135 83/08/19 HUNTER.H E CONOCO, Inc (Continental Oil Co) 4pp 22061 185
- ---8402010446 "Drilled Shaft Const at Crownpoint, NM " Related info encl HUNTER, H E CONOCO, Inc (Continental Oil Co) 00135 83/08/19 62pp 22061 189
- --B402010448 "Drilling Large Diameter Holes " Related info encl ALLEN.J H Smith International, Inc 00135 83/08/19 2 22061 251
- 8402010474 Submits list of documents provided during hydrologic data review session held on 840107 at Richland.WA Addi hydrologic data will be forwarded in Feb 1984 OLSON.O L Energy, Dept of 00645 84/01/20 WRIGHT.R J High Level Waste Technical Development Branch 2pp 22061 349
- 8402010522 Expresses appreciation for 830913 ltr re NRC-state relations relative to high level nuclear waste LH Bohlinger designated point of contact for both NRC & DDE consultation process TREEN.D C Louisiana. State of 00183 83/11/04 DAVIB.J & Dffice of Nuclear Material Sefety & Safeguards. Director 1p 22061 341
- 8402010524 Notifies of 830802 meeting in Silver Spring, MD to discuss proposed DDE/NPD info mgt & transfer sys for salt repository project Agenda encl MILLER, MJ High Level Waste Technical Development Branch 00147 83/08/02 BELL, M, BUNTINO, J, BDYLE, J. NRC No Detailed Affiliation Given 4pp 22041 337
- 8402010527 Responds to 830802 request for comments on matta made available re DOE salt info transfer sys Proceeding too premature to formulate basic NRC discovery parameters & to consider legal aspects in connection w/licensing project RUTEERG. J. Office of the Executive Legal Director 00144 83/09/08 JOHNSON, B. NRC No Detailed Affiliation Given 1, 22061 336
- 8402010528 Notifies of upcoming meetings during 830809-1215 re national storage program.
 NEFF, J O Energy, Dept of CO148 83/08/01 MILLER, H NRC No Detailed Affiliation Given TOMBIC, G Utah, State of FRISHMAN, S Texas, State of 1¢ 22041 335
- 8402010529 Notifies of upcoming meetings during 831107-1215 re nat1 e02010529 Notifies of upcoming meetings during H31107-1215 re-matl waste terminal storage program NEFF.J O Energy, Dept of 00171 B3/10/28 MILLER,H. NRC - No Detailed Affiliation Given MOON,R Utah, State of FRISHMAN,B Taras, State of 1p 22061:334
- 8402020012 Forwards Bil007 communication to W Fisher, per W Hambleton NOVEWOODER FORWARDS GREAT COVERNMENT CONTROL OF THE CONTROL OF THE
- 8402020013 Forwards 811007 communication to W Fisher, per W Hambleton Suggestion M/o spicl
 WRIGHT,R J High Level Waste Technical Development Branch. 00051.
 B1/10/20 GLSON,N K South Carolina, State of ip 22062,321
- 8402020015 Forwards BilOD7 communication to W Fisher.per W Hambleton Suggestion W/o encl WRIGHT,R.J High Level Waste Technical Development Branch. 00049 81/10/20. OSTROM,M E Wisconsin, State of ip 22062 320
- 8402020017 Forwards 811007 communication to W Fisher, per W Hambleton suggestion H/o encl WRIGHT.R.J High Level Waste Technical Development Branch 81/10/20. SOCOLOW.A A Pennsylvania, Commonwealth of, 22062 319.
- 8402020022 Forwards Bli007 correspondence w/W Fisher, at suggestion of W Hambleton W/o encl REIGHT, R J High Level Waste Technical Development Branch 00047 81/10/20 FAKUNDINY, R H New York, State of 19 22062, 315

- 8402020026 Discusses Geological Soc of America 830303 south-central meeting in College Station.TX re geological licensing topics in high & low level radwaste mgt Abstracts of papers
- 8402020031 Summary of B10627 meeting re concerns of E0 Wermund, Univ of Texas at Austin, involving NRC contract work in State of TX BRAUN, J G Licensing Process & Integration Branch 00054
 B1/07/07 BUNIING, J D Licensing Process & Integration Branch. 22062 306
- ---8402020037 Expresses concern re NRC contract work in Palo Buro Basin Sensitive scientific programs should be coordinated w/Texas Energy Natural Resources Advisory Council HERMUND.E G Texas, Univ of, Austin, TX 00054 81/06/17 JOHNSON,R L High Level Waste Technical Development Branch in
- 8402020042 Responds to 830203 submittal re State of MI comments on draft site characterization plan Passage of Public Law 97-425 heightens need for candor & frankness between DDE & states w/potential nuclear waste repositories GREEN.J W Mississippi. State of 00061 83/03/01. GEORGE.C. Energy. Dept of 5pp 22062 300
- B402020045 Describes NRC progress in formulating regulations under which high level radwasts repository would be licensed Regulations will form 10CFR60 WRIGHTR V High Level Waste Technical Development Branch. 00052 B1/10/07 FISHER.W L Texas, State of 2pp 22062:278
- 8402020049 Requests review of enc1 NUREG/CR-1996, "Geochemical Parameters Used in Bedded Salt Ref Repository Risk Assessment Methodology " W/o enc! ROSSBACH,L W High Level Waste Licensing Management Branch, 00009 82/05/10 NEWTON,C Energy, Dept of 2pp. 22062 295.
- 8402020084 Forwards set of repts from Golder Assoc contract on high level nuclear waste repositories, per request during 831084 meeting in Columbus, OH W/o encls MATESUND R Division of Waste Management 00175 83/11/04, FRISHMAN, 6 Texas, State of 1p 22062 297
- 8402020055 Summary of 820721 meeting w/State of MS Energy & Transportation Board in Silver Spring. MD re state participation in high level waste licensing & site characterization rept reviews ULECK.R B High Level Waste Technical Davelopment Branch. OC 82/08/18 MILLER.H J High Level Waste Technical Davelopment Branch ip 22062 274
- B402020056 Ack receipt of B31011 ltr requesting designation of contact person for NRC coordination w/State of TX Primary contact should be designated by Governor White LEWIS.0 D Texas State of. 00167 B3/10/24 DAVIS.J 0. Office of Nuclear Material Safety & Bafeguards, Director. 1p 22062.293.
- 8402020063 Ack receipt of itr re communication between State of LA & NRC Requests to be advised of any developments.

 NUNEZ.S B Lauisians, State of ODIS2 83/10/19 DAVIS, J. Q. Office of Nuclear Material Safety & Safeguards, Director. ip. 28062, 292.
- B402020075 Forwards slides taken during Sept 1983 visit to Vitro Chemical site in Bouth Balt Lake.UT W/o encl WEBER.M Geotechnical Branch (Post 831001) 83/12/23 Offic Nuclear Material Safety & Safeguards.Director. 3pp 22062:285.
- 8402020080 Responds to recent ltr requesting State of TX designate primary contact for NRC coordination w/state. Primary contact should be designated by Governor White HOBBY.B Texas. State of B3/10/04 DAVIB.J O, Office of Nuclear Material Bafety & Bafeguards. Director 1p. 22062.284.
- 8402020087 Ack receipt of 830913 ltr Requests NRC communicate any & all matters re relations w/State of LA concerning disposal of hazardous wastes
 HAINKELJ J Louisiana, State of, 83/09/26. DAVIB, J G, Office Nuclear Material Safety & Safeguards, Director. 1p 22062; 283.
- 8402020097 Forwards info on basal type of sandstone deposits, discussed during field trip to Palo Duro Basin. W/o enrl. WRIGHT.R J High Lavel Waste Technical Development Branch. 00053 81/07/21 MGGOMEN, J H Texas. State of 1p 22062 282.

- 8402020101 Forwards State of WA 840105 ltr requesting technical assistance on review of Nuclear Packaging. Inc high integrity container for use at Hanford site Response requested by 840203 MMSSBAUHER, D. A. Assistant Director for State Agreements Programs 64/01/17 HIGGINBOTHAM.L Low-Level Waste & Uranium Recovery Projects Branch ip 22062 280
- --8402020103 Requests technical assistance in evaluation & approval of Hutlear Packaging, Inc FL50 high integrity container Addendum A to "Evaluation of Nuclear Packaging, Inc FL50 Container" encl M/o encl STRONG, T.R. Washington, State of 84/01/05 NUBSBAUMER, D.A. Assistant Director for State Agreements Programs ip 22062 281
- 8102020155 Discusses 831207 meeting re high level waste repository
 licansing in which NRC should establish relationship
 wfstates similar to policy delineated in Section 117 of
 Nuclear Haste Policy Act
 EALLNO Tennessee. State of 202 83/12/12 DAVIS, J. Office of
 Nuclear Material Safety & Bafeguards.Director 1p 22062 231
- BIO2020189 Forwards B31028 TX Register notice announcing 831109 public hearings in Amarillo, TX & B31118 public hearings in Austin TX re implementation of drilled or mined shafts FRISHMANS Toxas, Btate of 00180 83/10/31 BROWNING.R NRC No Detailed Affiliation Given 2pp 22062 250
- 8002020207 Forwards agenda for 830807 & 10 meetings in Columbus, CH to discus: NRC draft technical position on waste package reliability & evaluation of spent fuel waste releases REFF, J Q Energy, Dept of 00151 83/07/20 MILLER, H NRC No Patalled Affiliation Given. 3pp 22062 233
- 8102020374 Forwards agenda for first NPO/NRC 830417-30 mestings NEFF,J Q Energy, Dept of 00104 83/04/15, CHASE,L NRC - No Setable Affiliation Given 2pp 22042 147
- 8402020379 Forwards trip rept of attendance at State of UT high level activities state limits on officer meeting COLLINS.JT Region 4. Office of Director 00028, 83/05/16 DIRCKB,M J Office of the Executive Director for Operations DAVIS.J Q Office of Nuclear Material Safety & Safeguards, Director to 2002.208
- --8402020391 Discusses trip to Salt Lake City, UT to meet w/state liaison officers re high level waste activities SANBORN, G Region 4, Office of Director 00028 83/05/12 COLING, J T Region 4, Office of Director, 2pp 22062: 207
- --8402020424 Transcript of 830503 & 04 public hearings on proposed namination of sites in salt deposits for detailed site theracterizations recommendations on issues to be addressed in environ assessments & site characterization plans TOMSIC, O R Utah. State of 00028 83/05/04 19pp 22062 213
- 8402020440 Advises of meeting of task force created per 83:121 memoheld on 840123 re vicinity property measurements analysis for inclusion determination. MCRLEY, J. Emergy. Dept. of 84/01/11 WHITE, D. NRC - No Datalled Applitation Given ARTHUR, J., BAKER, K. Energy, Dept. of
- 8402030032 Updates status of NRC implementation of 400FR190 for U mils NRC currently reviewing 10 mill licenses & 400FR190 programs to determine if license or program changes needed Coepletion of rept scheduled for 840202 W/o encis.

 BROWNING, R. Office of Nuclear Material Safety & 8408LUM, Q L Environmental Protection Agency 1p 22091 245
- 8402030102 Forwards "Burvey of Balt Domes" re 800708-19 trip to Quif Interior Region. BELL:1 J. High Level Waste Technical Development Branch 00059 81/01/16. HEATH.C. Energy, Dept of Rpp. 22262,280.
- --8402030264 "Burvay of Balt Dome Investigations "
 KART.P., JOHNSON.R.L., NICHOLBON.T J Commissioners 00057
 61/01/31, 59pp 22262:282
- 8402030113 Forwards comments on DES for Rifle site Review indicates that DES will regulare major revs & additions, \$1991NBOTHAM, L. Low Level Waste Licensing Branch 84/01/10 KOREAN, A Energy, Dept. of 18pp 22070-305.
- 640200117 Forwards additinfo re implementation of 40CFR190, consisting of environ monitoring data repts submitted by licensees & MC reviews. NRC currently reviewing mill licensee & 40CFR190 progress to determine if change needed. W/o encl MARTIM.D E Low Level Waste Licensing Branch. 84/01/05. BD909; L. A Assritan Mining Congress ip 22089-362

- B402030119 Informs of completion of prgliminary review re surface water hydrology aspects of PBES for Durango remedial action program in-place stabilitation will likely not meet EPA long-term stability criteria HIGGINBOTHAM.L Low Level Waste Licensing Branch 84/01/10 MORLEY, J A Energy, Dept of 4pp 22070 301
- 8402030120 Responds to 831201)tr re Salt Lake City DES Issues need to be resulved for FES scheduled to be published in June 1984 MORLEY. J A Energy, Dept of 84/01/16 MARTIN, D NRC - No Detailed Affiliation Given 2pp 22090 299
- 8402030186 Forwards supplementary comments on NRC concurrence in DOE waste repository siting guidelines
 BERICK, D M Environmental Policy Institute 48FR50432 84/02/01
 CHILM, B J Office of the Secretary of the Commission ip
- --B402030190 Supplementary comments on NRC concurrence in DDE waste repository siting guidelines a Environmental Policy Institute 84/02/01 App 22068 182
- 8402030227 Forwards statement on NRC concurrence/nonconcurrence in DDE proposed guidelines for siting high level nuclear waste repositories for inclusion in record of public hearing USGS in agreement w/technical content & approach of guidelines DEVINE. J F Interior, Dept of, Geological Survey 48FR50432 84/02/01 CHILK-S J Office of the Secretary of the Commission 7pp. 22047 149
- B402030232 Confirms extension of time for submitting comments re NRC concurrence on DDE nuclear waste repository siting guidelines until 840203 BINDERBRAND. C Misconsin. State of 48FR50432 B4/01/31 CHILK.S Office of the Secretary of the Commission ip 22047 143
- 8402030237 Comments on petition for rulemaking re DOE guidelines on disposal of high level radwaste DOE must demonstrate clarity & veracity of method used to screen sites LOUX, R R Nevada, State of 48FR50432 84/01/30 NRC No Detailed Affiliation Given Spp 22067 178
- 8402030239 Forwards addit comments of Yakima Indian Nation on petition for rulemaking on NRC concurrence in DOE high level waste repository siting guidelines YOUSLEY, D.R. Harmon & Heits TOUSLEY, D.R. Yakima Indian Nation 48FR50432 84/02/01 CHILK, B.J. Bocketing & Services Branch 1p 22045:195
- --B402030243 Add1 comments supporting potition for rulemaking on NRC concurrence in DOE repository siting guidelines WEISS.ER. TOUSLEY.D.R. Yakima Indian Nation WEISS.ER Harmon & Weiss 48FR50432 84/02/01 9pp 22067 176
- B402030249 Comments on petition for rulemaking re DDE guidelines for disposal of high level radwaste Encls intended to suppl B4ate of MN testingny at 840111 hearing KALITOWERLIT Hinnesota, State of 48FR50432 84/01/24 CHILK, B J Office of the Secretary of the Commission 48pp 22067 202
- 8402030253 Bubmits addl comments on guidelines under Commission review & on which Commission will render concurrence decision Quidelines in present form unacceptable BALL.W. 0 Hississippi. Btate of 48FR50432 84/01/31 CHILK.9 J. Office of the Secretary of the Commission 3pp 22049.342
- 8402030272 Forwards trip rept of BiO511-20 visit to Paradox Basin.UT & Palo Duro Basin.TX to review current status of site screening in bedded salt studies MILLER.H J High Level Waste Technical Development Branch 00026 BI/09/21 HEATH.C Energy, Dept of 3pp 22090 192.
- --B40203028i Trip rept of B10511-20 visit to review DDE site screening in bedded salt in Paradox Basin, UT & Palo Duro Dasin, TX JOHNBON, R L , FENDLETON, M W , GUINN, E NRC No Detailed Affiliation Oiven 00026 B1/0B/31 NRC No Detailed Affiliation Oiven 00026 B2090 195
- B402030493 Agenda for B40120 meeting of high level nuclear waste advisory council in Lacey, WA # Washington, State of 00663 B4/01/20 Washington, State of 19pp. 22082 345
- B402030495 Forwards minutes of 831024 EA topical meeting in Columbus, DH re transportation, water use, water availability & water rights NEFF, J.O. Energy, Dept. of CO179 83/11/04. MILLER, H. High Level Waste Technical Development Branch. 28pp 22082 317.

- 8402030497 Confirms 830920-21 meetings w/salt state representatives & NRC in Columbus.OH NRC in Columbus.OH NEFF.J O Energy. Dapt of 00125 83/09/12 MILLER,H NRC - No Detailed Affiliation Given 3pp 22082 313
- 8402030499 Forwards for review, mgt review draft of Gulf interior salt dome trip rept JOHNBON, R L High Level Waste Technical Development Branch 00226 80/11/26 MARTIN, J B Division of Waste Management 1p 22090 030
- --8402030531 Trip rept of 800908-19 visit to Gulf interior salt domes HART,P., JOHNSON.R L., NICHOLSON.T J High Level Waste Technical Development Branch 00226 80/11/30 High Level Waste Technical Development Branch 58pp 22090 031
- 8402030502 Forwards trip rept of 830522-27 tour of Retsof Bedded Salt Mine & abstracts from Sixth Intl Symposium on Salt in Toronto, Canada NEFF, J D Energy, Dept of 00155 83/07/13 MILLER, H S NRC -No Detailed Affiliation Given 78pp 22082 235
- 8402030505 Trip rept of attendance at BMI 831017 briefing in Columbus. OH re development & operation of records & info sys & technical data mgt sys BUNTING, J O , MATTSON.D R , STILL, N Policy & Program Control Branch (Post 831001) 00186 83/11/15 BROWNING, R E Division of Waste Management 2ρp 22082 233
- 8402030506 Provides notice of upcoming meetings Notice will be updated weekly, per B30719-20 meetings
 NEFF, J O Energy, Dept of OO188 B3/11/14 MILLER, H NRC No Detailed Affiliation Given FRISHMAN, S Texas, State of MODN, R Utah, State of 1p 28082 232
- B402030508 Comments on Chapter 28 of State of TX water code re water wells & drilled & mined shafts & implementing regulations in state register New regulation would allow state more restrictive limits than either 10CFR60 or EPA std TIKTINSKY,D R Engineering Branch (Post 831001) 00167 83/10/27 OREEVES,J T Engineering Branch (Post 831001), 3pp 22082 229
- 8402030509 Provides notice of upcoming meetings Notice will be updated weekly.per 830719-20 meetings
 NEFF, J O Energy. Dept of 191 83/11/28 MILLER.H NRC No Detailed Affiliation Given MOON.R Utah. State of FRISHMAN, 8
 Texas. State of 1p 22082 228.
- 8402030511 Provides notice of upcoming meeting Notice will be updated weekly, per 830719-20 meetings
 NEFF, J O Energy, Dept of 312 83/10/21 MILLER, H NRC No Detailed Affiliation Given. MCON, R Utah, State of. FRISHMAN, S
 Texas, State of 1p 22082 227
- 8402030512 Forwards amended Chapter 28 of State of TX water code rewater wells & drilled or mined shafts Act requires that rules be proposed for implementation within 120 days of enactment FRISHMAN, 8 Texas, State of 00161 83/09/30 BROWNING, R NRC No Detailed Affiliation Given 24pp 22082:200
- B402030514 Provides notice of upcoming meetings Notice will be updated weekly,per 830719-20 meetings
 NEFF, J D Energy, Dept of 347 83/12/09. MILLER,H. NRC No Detailed Affiliation Given CHRISTOFFERSON Utah, State of. FRISHMAN,S Texas, State of 1p 22082 199
- 1402030515 Comments on DOE technical data mpt sys & info flow for Salt Project Sys will provide common base for DOE contractors to use in performing licensing analyses. Sys appears adequate for prelicensing reviews

 VUGT. D. K. Teknekron, Inc. 00146 83/08/05 JOHNSON, R. Division of Waste Management 2pp 20082 197
- 402030517 Provides notice of upcoming meetings. Notice will be updated weekly.per 830719-20 meetings.
 NEFF, J D Energy, Dept of 178 83/12/05 MILLER, H. NRC No Detailed Affiliation Given. CHRISTOFFERSON Utah, State of FRISHMAN, S Texas, State of 1p 22082.196
- 102030518 Provides notice of upcoming meetings Notice will be updated weekly.per 830719-20 meetings.

 NEFF.J D. Energy, Dept. of. 189 83/11/18 MILLER,H NRC No Detailed Affiliation Given, FRISHMAN.S Texas, State of, MODN,R Utah. State of, 1p 22082.195
- 102030321 Discusses implementation of state working group recommendations re Salt Repository Project Catalog & procedures set forth to facilitate selection of which repts should receive state review in draft form encil
 (NEFF, J O Energy, Dept of 00154 83/07/19 MILLER, H. NRC No libetailed Affiliation Given. 5pp 22082 185.

- 8402060014 Provides clarification re limitations on in situ tests w/radioactive matl.based on discussions at DOE/NRC wasto package 830809-10 meetings
 NEFF.J O Energy, Dept of 201 83/08/17 MILLER.H High Lavel Waste Technical Development Branch 2pp 22109 231
- B402050020 Forwards, for review & comment, draft "Remedial Action Plan for Stabilization of Inactive U Mill Tailings Site at Shiprock.NM " Comments requested by 840215 MARLEY, J A Energy, Dept of 84/01/03 HIQQINBOTHAM, L., MARTIN, D Low Level Waste Licensing Branch 2pp 22105 008
- --8402060022 Draft "Remedial Action Plan for Stabilization of Inactive U Mill Tailings Site at Shiprock.NM " * Energy, Dept of 83/12/31 257pp 22105 010
- 8402060029 Notifies that meeting will be held on 830823 in Columbus, DH to discuss environ assessment issues Agenda encl NEFF, J.O. Enorgy, Dept of, 00137 83/08/16, TOMSIC.9, Utah, State of 3pp 22109 248
- 8402060033 Extends invitation to be speaker at 831115-16 meetings re program w/salt states & NRC NEFF, J D Energy Dept of 00157 83/10/06, EQAN, D Environmental Protection Agency 2pp 22110 156
- 8402060044 Responds to 821005 ltr re progress of study of NV site. Btudy committee of legislature designated is NRC point of contact GIBSON, J I Nevada, State of O0173 83/12/16. DAVIS.J. 0 Office of Nuclear Material Safety & Safeguards. Director 1p 22110.155
- 8402060049 Forwards summary of 830920-21 meetings w/salt state representatives & NRC in Columbus.OH NEFF,J O Energy. Dept of 00170 83/10/27 MILLER,H, High Level Waste Technical Development Branch ip. 22110.063
- --8402060095 Summary of 830920-21 meetings w/salt state representatives & NRC in Columbus, OH # Energy, Dept of 83/09/21. Energy, Dept of 69pp 22110:064
- B402060104 "State of MS Position Statement re Federal Legislation on Nuclear Waste Mgt " * Mississippi, State of 225, 82/06/30, 7pp 22110-014.
- 8402060109 Documents 821218-19 meetings w/Benators McClure & Stannis in Washington DC re H. R. 3809 proposed hat1 nuclear waste mpt legislation & proposed senate amends FORBYTHE:R J Mississippi, State of. 00062, 82/12/19. Mississippi, State of 39pp 22109-337
- 8402040137 Forwards rept, "Evaluating of SWIFT Code for Use in Beddsd Balt." which constitutes successful Completion of Milestone 3, Planned Accomplishment 3 % Major Objective 2. KNAPP,M R High Level Waste Licensing Management Branch 00012 80/09/300 BUNTING,J O Licensing Process & Integration Branch 1p 22107,053
- --8402060142 "Evaluation of BWIFT Code for Use in Bedded Balt." LEHMAN,L L : ENG.A, NRC - No Detailed Affiliation Given B0/09/30 100pp 22107,054
- 8402060140 Provides addl comments for inclusion into record of 840111 mesting re NRC concurrence/nonconcurrence in DOE waste repository siting guidelines Commission urged to require that guidelines meet intent of Nuclear Waste Policy Act. FRISHMAN.S Texas, State of ABFR30432 84/01/30, PALLADINO,N J Commissioners. 32pp. 22089-025
- 8402040147 Forwards rept, "Simulations of Paradox Selt Basin," describing in-house modeling of bedded salt site GUINN.E J. ORNSTEIN.F M High Level Waste Licensing Management Branch, 00023 82/08/24 KNAPP.M.R High Level Waste Licensing Management Branch ip 22107.014.
- --B402060131 "Simulations of Paradox Salt Basin,"

 GUINN, E J, DRNSTEIN, P M NRC No Datailed Affiliation Given 00023. 82/08/24 38pp 22107:015.
- 8402040155 Forwards summary of 830809-10 meetings between NRC & BOE resubmittal of salt site characterization plan on waste package Meeting agenda & viewgraphs encl.
 NEFF.J.O. Energy, Dept of. 00139 83/08/15. MILLER.H. NRC No Detailed Affiliation Given 55pp. 22104-317.

- 84020A0194 Forwards 840107 supplemental memorandum opposing petition for rulemaking on NRC concurrence in DDE repository siting guidelines Exhibit 3 of preliminary memorandum also encl W/o encl W/o encl MATHESON.8 M Utah. State of 48FR5043R 84/01/31 PALLADIND.N J Commissioners 1p 22088 192
- 3402070324 Provides recommended mods to high level waste repository safety guidelines & constructive suggestions where quantification would be useful Recommendations simed primarily at implementation guidelines SENDERBRAND, C. Wisconsin, State of 48FR30432 84/02/02 CHILKS J. Office of the Secretary of the Commission 49pp 22096 334.
- 8402080033 Further response to FOIA request for documents re cleanup & decision to close down U mill in Edgemont. SD Forwards listed document fellDN.J M Division of Rules and Records 83/11/16 GARBUS, M Frantfust, Oarbus, Klein & Selz 1p 22172 347
- --8402080037 Informs that NRC does not have authority to conduct cleanup Q2080037 Informs that NRC does not have authority to conduct cleans activities of U mills at offsite locations in Edgemont. SD NRC quarly authorization acts through FY80 do not grant NRC authorization.

 BICKNITL Office of the General Counsel BI/01/30 AHEARNE.JF Commissioners. 2pp 2217R-347
- 8402080043 further response to FOIA request for documents re cleanup & decision to close U mill in Edgemont.SD Forwards App A.B & C documents Review of remaining documents subj to request in progress
 In progress
 FELION, J H Division of Rules and Records, 83/11/01 GARBUS, M
 FELION, J H Garbus, Klein & Selz 10pp 22169 009
- --9003250497 Discusses working level measurements in Edgemont, SD Bradford residence has highest working level determinations Other sonitored structures do not appear to be of immediate health rish concern. riss concern. EADIE.9 Uranium Recovery Licensing Branch 80/03/06 BCARAND,R A. Uranium Recovery Licensing Branch 2pp 22169 272
- --B4020B004B Ack receipt of Feb 17B1 monthly rept for Edgemont cleanup action program "Proceedings of Workshop on Radiological Surveys in Support of Edgemont Cleanup Action Program" will be issued as NOREO/CR-2003

 EADIE, O. G. Urenium Recovery Licensing Branch FIN B-2217
 31/06/01. WDQMAN.N A Battelle Memorial Institute, Pacific Northwest Laboratory 2pp 22167 025
- --B4020B0030 Discusses analysis of B.B 2358 NRC FYBI Authorization Bill, Section: Edgemont, BD Bill as reported on 800513, did not address responsibility for actual remediation work Major changes established by amends listed BRANN.J 9 Licensing Process & Integration Branch 80/08/RB MARTIN.J B Division of Waste Management 6pp 22169: 311
- -9402080052 Discusses NRC program for Edgemont mill tailings.per 800929 meeting LOOSLEY, D. J. Program Support Branch 80/09/30 DAVIS, J. G 02/169 of Nuclear Material Safety & Safeguards, Director 1, 22/169 317
- --849208005& Forwards data obtained on soils from Edgemont school yard, per 801027 telcom. Data indicates that matl found at specific locations is primarily tailings.
 HOCHAN,N A. Battells Memorial Institute, Pacific Northwest Laboratory, 80/10/27. SGARAND,R A. Office of Nuclear Material Safety & Bafeguards, Director 2pp _22169, 318
- --8402080039 Draft "Radiological Surveys at Edgemont, 8D, 1980 " # Battelle Hemorial Institute, Pacific Northwest Laboratory, 80/12/31, 15pp. 22169 320
- --84020800&1 Requests assistance in obtaining clarification from appropriation committees if problem exists in continuing Edgesont cleanup program M/o stated enci HARTIN-J B. Division of Waste Management. FIN B-2217 JJS-6
- --B402080063 Notifies that author assumed responsibilities of State
 Rediation Control Program director on S00918 Duties
 associated w/Edgemont U mill.Edgemont offsite cleanup
 preject & general radiation activities
 BRICK:R South Dakota, State of S1/01/14 MCGRATH. J Assistant
 Director for State Agreements Programs ip 22169.027

- --8402080067 Lists items to be discussed during meeting w/Senatur McGovern re U mining & milling in State of SD CARPENTER:R, MCGOVERN Senate 79/06/14 SCARAND,R NRC -Detailed Affiliation Given 2pp 22169 046 SCARANGER NRC - No
- ---8402080069 Submits third status rept re Edgement cleanup Summary of BNML radiological surveys through Aug 1781 encl SCARAND.R A Uranium Recovery Licensing Branch WM-81-554 B1/10/15 MARTIN.J B Division of Haste Management 5pp 22169 336
- --8402080074 Ack receipt of 761227 ltr re U mili tailings at Edgemont. SD Phase II study must be conducted before further action taken Excerpts from "Evaluation of Impact of Mines Development, Inc" encl KNEIP, R F. Bouth Dakota, State of 76/12/30 GDSSICK, L V taken Excerpts from "Evaluation of impact of mines Development,Inc" encl KNEIP:R F Bouth Dakota, State of 76/12/30 GCSS[CK, L V Office of the Executive Director for Operations 31pp 22:
- --B402080075 Discusses status of contracted work Summary of disequilibrium in Edgement soils almost complete Related info encl WOOMAN.N A Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2216 20108 82/02/01 EADIE.G 0 Vranium Recovery Licensing Brench 5pp 22169 341
- --8402080081 Draft "Edgemont Remedial Action Program," annual interim
- --B402080085 Requests Phase II designation for Edgement U mill Supporting 902000009 Requests Phase II designation for Edgemont V mill Sup documentation encl KNEIP.R.F South Dakota. State of 76/11/08 GOSBICK.L D Office of the Executive Director for Operations LIVERMAN.J L Energy Research & Development Admin (Presently DDE) 8pp 22169 080
- --8402080091 Discusses NRC 760826 visit to Edgement, 9D U milling plant Tailings piles generated by past operations found in various stages of reclamation Detailed plan to stabilize loose sand tailings area requested by 761115
 ROUSELL C Fuel Process & Fab Branch (Pre 790727) 76/09/17
 WILLIAMS: 0 Tennessee Valley Authority 2pp 22167 088
- --B402080097 "Edgemont Remedial Action Program," monthly rept for Sept 1780
 JACKBON.P O , DLBEN.K B , MAUCH.M L Battelle Memorial Institute,
 Pacific Northwest Laboratory FIN B-2217 80/09/30 NRC - No
 Detailed Affiliation Given 3pp 22170 106
- --BAO2080099 Discusses interim stabilization of sand tailings at Edgemont, 8D U mill, per 740901 conversation Concurs w/US Bureau of Mines article that combination chemical-vegetative method of stabilization best Related info encl CAMERON, R E Argonne National Laboratory 76/09/02 SCARAND, R Fuel Process & Fab Branch (Pre 790727) 6pp 22169.090
- --8402080104 "Edgemont Remedial Action Program," monthly rept for Oct NOOMAN, N.A., JACKSON, P.O., OLBEN, K.B. Battolle Memorial Institute.
 Pacific Northwest Laboratory FIN B-2217 80/10/31 NRC - No
 Detailed Affiliation Civen 4pp 22170 107
- -8402080106 Ack receipt of 760811 transmittal of Governor Kneip ltr to ROZOBITOS Ack receipt of 700811 transmittal or overnor knet little Senator Nicovern expressing concern re environ impact of tailings from past U milling operations at Edgemont, 80 Mill status clarified GOBSICK, L. V. Office of the Executive Director for Operations. 76/09/08 HURPHY, O.F. Congress, Joint Committee on Atomic Energy 3pp 22169 094
- --B4020B0112 "Edgement Remedial Action Program," Itr rept for Nov 1980 WOOMAN.N A JACKEDN,F O THOMASY W Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2217 B1/01/13 EADIE:O O Uranium Recovery Licensing Branch opp 22170.113
- ---B4020B0115 Forwards Governor Kneip request that site of Mines Development, Inc U mill in Edgemont, 8D be included in ERDA study list of inactive U mill sites Appropriate action requested ABDUREZK, J Senate 76/09/ Committee on Atomic Energy 76/09/16 PASTORE.J Congress Joint Thergy 4pp 22169 099.
- --8402080117 "Edgement Remedial Action Program," monthly rept for Dec 1980. WOOMAN,N A . JACKBON,P D . OLSEN:K B Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2217 80/12/31 NRC - No Detailed Affiliation Given App 22170 119

- --8402080120 Responds to 750805 ltr re TVA mill at Edgement, SD Since TVA is govt corp.mill would continue to operate under NRC litense even though SD became Agreement State EIS must accompany issuance of license for U mill XERR, G W NRC No Detailed Affiliation Given 75/09/12 NELSON, M O South Dakota, State of 1p 22149 103
- --B402080122 "Edgemont Remedial Action Program." Itr rept for Jan 1981 THOMAS.V W. WOGMAN.N A Battelle Memorial Institute. Pacific Northwest Laboratory FIN B-2217-0 B1/02/13 EADIE.9 G Uranium Recovery Licensing Branch 7pp 22170 125
- --8402080127 "Edgement Remedial Action Program," monthly rept for Feb 1981 HOGMAN,N A , JACKSON,P D Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2217-0 81/02/28 NRC - No Detailed Affiliation Given Spp 22170 132
- --8402080133 "Edgement Remedia) Action Program," monthly rept for May 1981 MCCMAN,N A , JACKSON,P O Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2217-0 81/03/31 NRC - No Detailed Affiliation Given 8pp 22170 137
- ---B4020B0137 "Edgement Remedial Action Program," monthly rept for June 1981 MOGMAN,N A., JACKSON,P O Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2217-O 81/06/30 NRC - No Detailed Affiliation Given 7pp 22170 145
- --B402080138 Responds to 750425 suggestion that TVA develop EIS for proposed U milling operation at Edgemont. SD TVA plans to submit environ info by 750801
 DIRCKG,W J GPfice of the Executive Director for Operations 75/06/07. GREEN,J A Environmental Protection Agency 1p 22169 104
- ~-8402080144 "Edgement Remedial Action Program." Itr rept for Jul 1981 JACKSON.P C . PERKINS.R W . WOOMAN.N A Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2217 81/08/10 EADIE.G C Uranium Recovery Licensing Branch 10pp 22170 152
- --B4020B0153 "Edgement Remedial Action Program," Itr rept for Aug 1981 JACKSON.P O . PERKINS.R W . MOGMAN.N A Battelle Hemorial Institute. Pacific Northwest Labbratory FIN B-2217 B1/09/11 EADIE.9 G Uranium Recovery Licensing Branch. 9pp 22170 162
- --8402080154 "Edgement Remedial Action Program," Itr rept for Sept 1981 JACKSON,F O . PERKINS,R W . WOMAN.N A Battella Hemorial Institute. Pacific Northwest Laboratory FIN B-2217 B1/10/07 EADIE.0 G Uranium Recovery Licensing Branch 9pp 22170'171
- --8402080159 "Edgemont Remedial Action Program." Itr rept for Feb 1982 JACKSON.P O . PERKINS.R W . WIGMAN.N A Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2217 82/03/11 EADIE.O O Uranium Recovery Licensing Branch 10pp 22170 180
- --8402080160 SA/TBB-18
 "Environ Evaluation of Mines Development, Inc & Vanadium
 Millings Operations at Edgement, SD "
 Environmental Protection Agency 73/04/30 46pp, 22169 105
 - 080163 "Edgement Remedial Action Program," monthly rept for May 82 GMAN,N A , JACKSON,P O Battelle Memorial Institute, Pacific rithwest Laboratory FIN 8-2217 82/05/31 NRC No Detailed filiation Given 15pp 22170.190
 - 2080168 "Edgemont Remedial Action Program." Itr rept for Jul 1982 ACKSUN.P O . PERKINDS.R W . WOOMAN.N A Battelle Memorial netitute, Pacific Northwest Laboratory FIN 8-2217 82/08/17. "LORY.C A Uranium Recovery Licensing Branch 129p 22170 219
 - 402080172 Discusses status of U mill site in Edgemont, SD, per 810731 discussion w/O Easie & F Anastasi Commission has no legal authority to conduct tailings removal or decontamination work
 - WONTGOHERY, J.L. Region 4, Dallas, Office of the Director (81/03/01) Bi/O8/07 Region 4, Dallas, Office of the Director (81/03/01) Rpp 22169 151
 - .402080176 "Recommended Protocols for Hadon Daughter Measurements in Bldgs in Edgement" * Battelle Memorial Institute, Pacific Northwest Laboratory. FIN B-2217 83/06/03 NRC - No Detailed Affiliation Given 10pp. 20170 244

- --B402080180 NUREG/CP-0021 DRFT

 Braft "Proceedings of Workshop on Radiological Surveys in
 Support of Edgemont Cleanup Action Program." S10121-22,
 Denver, CO
 YDUNG. J A Battelle Memorial Institute, Pacific Northwest
 Laboratory FIN B-2216 PNL-3784 81/04/15 100pp 22169 160
- --84020B02D2 "Indoor Radon Study at Edgemont & Cottonwood, BD, 800204-08 * NRC -- No Detailed Affiliation Given 80/02/08 lipp 22149 241
- --B402080206 Forwards revised data from soil samples taken in Edgement, SD in Nov 1979
 DDNOVAN, T K Tennessee Valley Authority 80/04/04 THRALL, J
 Environmental Protection Agency 8pp 22169 273
- --8402080211 Discusses radiation monitoring in Edgemont, 8D by BD Dapt of Health Measurements will utilize federal protocol.as listed SMITH, J Affiliation Not Assigned 80/04/09 RICHARDSON, R Affiliation Not Assigned 1p 22169 281
- --8402080214 Forwards memo from 8 Smith, 9D Dept of Health, re radiation monitoring in Edgemont Memo outlines process established to provide necessary monitoring for EPA & HUD at request of local homeowners and the state of 80/04/17 MILLER, H NRC No Detailed Affiliation Given 1p 22167 282
- --84020B0216 Responds to 800321 request for add1 info re NRC request for DDE assistance in remedial action program in Edgemont.BD.
 DIRCKS.W.J Office of the Executive Director for Operations
 B0/04/30 FRANGUS.T G Energy. Dept of 4pp 22169 283
- --B4020B0219 Forwards fact sheet prepared by NMBB re Benate Authorization Committee designation of NRC as lead agency for coordinating cleanup of offsite locations at Edgemont Two primary points listed Related info enc!

 DAVIS. J 0. NRC No Detailed Affiliation Given B0/05/22 KAMMERER.C NRC No Detailed Affiliation Given 19pp 22169 287
- 840R080t26 Provides additionments to DOE program guidelines draft
 Development of more specific guidelines & measurement
 criteria essential in assessing unique characteristics of
 specific media & specific sites as selected
 MODELD W Washington State of 48FR50432 84/01/31, PALLADINO, N
 Commissioners 5pp 22132 283
- 8402080128 Comments on petition for rulemaking re NRC concurrence in DDE nuclear waste repository guidelines Treaty-reserved fishery resource could be severely jeopardized Nonconcurrence urged PATAHA.E H Confederated Tribes of Umatilla Indian Reservation 4BFR30432 B4/02/01 CHILK,S J Office of the Secretary of the Commission 2pp 22132 145
- 8402080157 Buppls 840111 presentation to Commission re DOE general guidelines for recommendation of sites for nuclear waste repositories DOE heeds to adopt more specific procedures in evaluations between sites Comments encl
 SJOBLOM, O.L. Environmental Protection Agency 48FR50432 84/02/O
 CHILK S J Office of the Secretary of the Commission 12pp.
- B4020B017B Forwards supplemental brief rs NRC concurrence in high level waste repository safety guidelines under Nuclear Maste Policy Act of 1982, for inclusion in record of B40111 meeting MURPHY.M R Murphy & Davenport MURPHY.M R Nevada, State of 4BFR50432 B4/02/01 CHILK.B J Office of the Secretary of the Commission 1p 22128 294
- --B402080182 Supplemental brief re NRC concurrence in high layel waste repository safety guidelines under Nuclear Haste Folicy Act of 1982 MRPHY, M R Nevada, State of MURPHY, M R Murphy & Davenport 48FR50432 84/02/01 82pp 22128 295
- 8402100257 "Geotechnical Investigation for Bodo Canyon UMTRAP Burango Site, Burango, CO " WESB, W D , FORTER, K R Dames & Moore, 83/10/20 55pp. 22207, 224
- B402100262 Forwards comments on Dec 1983 draft environ assessment of remedial action at Shippock Mill tailing site Estimates of important engineering parameter calculations should be included
- included H1001NBOTHAM,L Low-Leval Waste & Uranium Recovery Projects Branch 84/01/30 MORLEY,J A Energy, Dept of 11pp 22205:338.

- 8402100284 Forwards final DDE/UMTRAP research summary chapter entitled.
 'Long-Term Protection of U Mill Tailings "
 HARTLEY, J N Battelle Memorial Institute, Pacific Northwest
 Laboratory. 84/01/18 MARTIN, D NRC No Detailed Affiliation
 given ip 22207:134
- --8402100287 "Long-Term Protection of U Mill Tailings " BEEDLOH,P.A., HARTLEY,J N Battelle Memorial Institute, Pacific Horthwest Laboratory. 83/12/31 72pp 22207 155
- 8402100288 Discusses & forwards Div of Waste Mgt rept, "BWIP Site Tethnical Position 1 i Hudrogeologic Testing Strategy for BMIP Bits " Testing program should begin by testing Grande Ronde formation WRIGHTR J Repository Projects Branch (Post B31001) 00467 8400711 0L80M.D L Energy, Dept of 7pp 22203 297
- B402100298 Bummarizes meetings of UMTRAP participants in Albuquerque, NM rs draft plan for implementing EPA atds & vicinity properties technical development status Viewgraphs & attendance list encl.

 KORLEY.J A Energy, Dept of 84/01/24 MARTIN, DE, NIXON, D NRC No Detailed Affiliation Given 100pp 22205 191
- 8402100300 Forwards add1 comments on responses to approvel of high integrity container design for EPICDR-II prefilter wastes State should review US Ecology venting procedures for Algh integrity container NUSSPAUNER. D. A. Assistant Director for State Agreements Programs 84/02/01. KERNER. N. Washington, State of, Dept of Social & Health Services 2pp. 22205 359.
- 8402100314 Forwards repts of listed telcons w/NRC personnel re post-Jul 1982 hydrology data.BWIP boreholes & postponement of repository design workshop ASM.E B Rockwell International Corp 00669 84/01/19 DLRDN.O L Energy, Dept. of 6pp 22207,293
- 8402100318 Notifies that on 840103, list of 8, 156 vicinity properties was designated by Director. Ofc of Terminal Waste Disposal & Readial Action Notice will be announced in FR. per US District Court for DC 830623 consent order BAVELITI. J E. Energy. Dept of. 84/01/26 BLANTON, R. Arizona, State of HAZLE. A. J. Colorado, State of FUNDERBURG, R. Idaho, State of. App. 22207: 287
- 8402100320 Forwards DDE summary of 820422 meeting w/NRC to discuss repository schedule/procedural rule & limited work authorization.

 MEAD.C. R. Energy, Dept. of 84/01/25 KEARNEY, M NRC No Detailed Affiliation Given 5pp. 22207.279
- --8402100323 Forwards current estimate of time taken to conduct each step in review of const authorization application & associated hearings for first repository Assumptions supporting estimates listed.

 WATTH-JR Division of Waste Management 82/05/12, COFFMAN.F.E. Energy, Dept. of 3pp 22207 284
- 8402100325 Notifies of UMTRAP Task Force 840213-14 meetings in Dak Ridge,TM re vicinity property measurements/analysis for Inclusion determination NGREY, J.A. Energy, Dept of. 84/02/02 FLORY, C., MARTIN, D. NRC -No Detailed Affiliation Given, Spp. 22205-349
- 94021000328 Notifies of UMTRAP 840216-17 meetings in Albuquerque, NM to discuss vicinity property mgt & implementation manual. MGREFY, J A Energy, Dept. of 84/01/26 MARTIN, D Low Level Waste Litensing Branch 2pp. 22205-357
- BM2100331 Motifies of 840131 meeting w/DOE, states & tribes in Fort tollins. CO re recent project accomplishments, const progress & plens, at Canonaburg site, availability of project & site-related documents & remedial action costs MORLEY. J. A. Energy, Dept of, 84/01/20 HIGGINBOTHAM, L. Low Level Maste Licensing Branch. 2pp. 22211-357.
- 8402100334 Forwards proprietary preliminary rept re testing of sisulated waste forms Comments received by 840127 will be incoporated into final topical rept W/o encl POMELLER H NUS Corp. PS-33-0674 84/01/03. LOHAUS, P. H Low-Level Waste & Uranium Recovery Projects Branch 2pp. 22208 360

- B402100410 Notifies that Topical Repts CNSI-WF-C-01-NP, "Waste Form Certification-Cement" & CNS-MIC-14571-01 NP, "Polyethylene High Integrity Containers," not subj to fee requirements WEISS.D License fee Management Branch B4/01/16 POPPE.L K Chem-Nuclear Systems, Inc. 1p. 22207 362
- 8402100413 Comments on outline of license application & environ rept for proposed low level radwaste facility in Edgement 5D Outline & rept should be submitted as two separate repts HIGGINBOTHAM. Low-Level Waste & Uranium Recovery Projects Branch 84/01/17 LEWIS M S Chem-Nuclear Systems, Inc 2pp 22208 311
- 8402100417 Ack receipt of IMPELL Corp rept. "Methodologies for Classification of Low Level Radwaste From Nuclear Power Plants" Rept can be used for classifying waste while waste stream sample analyses performed Comments encl HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch 84/01/27 STANFORD.R Edison Electric Institute 10pp 22211 323
- 8402100419 Forwards comments on draft "Vicinity Properties Mgt & Implementation Manual " NRC concurrence necessary to fulfill responsibility for remedial action at vicinity properties HIGOINBOTHAML, Low-Level Haste & Uranium Recovery Projects Branch 84/01/31 MCRLEY.JA Energy, Dept of 3pp 22211 318
- 8402100420 Responds to 831228 ltr requesting responses to questions recement qualification test program Testing acceptable for Portland type coments Other cements changing product characteristics should have separate testing programs LDHAUS, P H Low-Level Waste & Uranium Recovery Projects Branch 84/01/24 LEE, T A Stock Equipment Co ip 22211 317
- 8402100422 Discusses gradual reduction in number & extent of tailing deposits Unly remedial action plans that adequately address all contaminated creas at each site will be approved or receive official concurrence MAZLE.A J Colorado. State of 83/09/23 BAUBLITZ.J E Energy. Bept of 3pp 22211 165
- B402100492 Forwards "Plan for Implementing EPA Btds for UNTRA Bites "
 MDRLEY, J A Energy, Dept of B4/01/31 HIGGINSOTHAM, L Low-Level
 Waste & Uranium Recovery Projects Branch 3pp 22212 327
- ~-8402100495 UMTRA-DDE/AL-163
 "Plan for laplementing EPA Stds for UMTRA Sites "
 HORLEY,J A. Energy, Dept of 84/01/31 30pg 22212 33p
- 8402130271 Comments on petition for rulemaking on DDE general guidelines for recommendation of sites for nuclear waste repositories Partinent issues gummarized LAMPROCE, M J Energy, Dept of 48FR30432 84/02/01 PALLADINO, N J. Commissioners 61pp 22200 131
- 8402140155 Comments on DDE general guidelines for recommendations of sites for nuclear waste repositories NRC should not concur in guidelines unless provision made for incorporating screening methodology for acceptable sites

 JAGER.L E Michigan. State of 48FR50432 84/02/07 CMILK.B J
 Office of the Bacretary of the Commission 29p. 22230 105
- 8402140884 Forwards Dec 1983 highlights re UMTRA project State of MY signed cooperative agreement Shiprock draft environ assessment & draft remedial action plan distributed & Durango DES released MDHLEY, J A Energy, Dept. of 84/02/02 MARTIN, D Low-Level Maste & Uranium Recovery Projects Branch HIGGENBOTHAM, L Low Level Maste Licensing Branch LICHTMAN, S Environmental Protection Agency Dpp 22256 324
- B402150169 Expresses appreciation for chance to discuss w/RRC outstanding issues before NRC provided concurrence w/DDE draft guidelines.
 BTEVENS.D W. Mashington, State of 48FR50432 84/01/17 PALLADINO,N J. Commissioners, ip 22245 246.
- B402150404 Requests required documentation listed in encl. to accomplish review of burango preliminary DE9
 OREEVES.J T Engineering Branch (Post B31001) B4/01/12
 HIGGINBOTHAM.L Low-Level Waste & Uranium Recovery Projects Branch
 3pp 22263 348
- 8402150433 Trip rept of KC Chang attendance at DWIP/NRC 840109-12 workshop on geochemistry in Richland, HA Summary meeting notes & visugraphs encl (Post 831001) FIN A-4165 84/01/27 OREAVES, J. T Engineering Branch (Post 831001) 37pp 28259 309

- 8402150530 Forwards comments on groundwater aspects of alternative remedial actions for cleanup & control of contaminated matls re review of Durango preliminary DE9 HEBERN F Goodschoical Branch (Fost 831001) 84/01/30 PENNIFILL: R A Low-Level Waste & Uranium Recovery Projects Branch 250p. 2226132
- 8402150533 Forwards NRC response to DDE comments on borehole & shaft sealing technical position RHODERICK, J E Engineering Branch (Post 831001) 84/01/26 OREEVES, J T Engineering Branch (Post 831001) 28pp 22263 049
- 8402150534 Forwards "Info Needs for Demonstrating Compliance W/ Groundwater Aspects of 40CFR192 for UMTRAP." to be presented at sixth symposium on 840201-03 in Fort Collins.CO Viewgraphs also encl WEBER.N F Geotechnical Branch (Post 831001) 84/01/30 BROWNING.R E Division of Waste Management 21pp 22258 334
- 8402150537 Requests seismicity assessment of UNTRAP at Shiprock site Final written review needed by 840207 Draft environ assessment (DEA) & DOE contractor evaluation of potential earthquake effects encl M/o DEA JUSTUS, PS Geotechnical Branch (Post 831001) 84/01/27 JACKSON, R E Geosciences Branch 17pp 22238 317
- 8402150544 Forwards comments on listed sections of draft environ assessment for remedial actions at Shiprock UMTRAP site Sections inadequate to support assessment of alternative environ impacts of remedial actions.

 ORIFFIN.T T Geotechnical Branch (Post 831001) 84/02/02 PENNIFILL.R A Low-Level Waste & Uranium Recovery Projects Branch 7pp. 22258 307
- B402150562 Forwards map of trenches which NRC viewed as inadequate Issue must be resolved w/NRC VIETH,D L. Energy, Dept of Oo201 84/02/02 DVDLEY,W W Interior, Dept of Genlogical Survey. 2pp 22238 361
- 8402150564 Notifies of 840126 meeting in Olympia.WA to discuss draft consultation & cooperation agreement GOULD.8 E Washington, State of OC674 84/01/23 NRC No Detailed Affiliation Given ip 22258 360.
- 8402180566 Provides NRC point of contact w/State of NV re Muclear Waste Policy Act of 1982 & other issues re storage & disposal of high level radwaste matls BRYAN, R H Mevada, State of 00202 84/01/30, DAVIS, J G Office of Nuclear Material Bafety & Safeguards, Director. 1p. 22258 359
- B402150370 Forwards Draft 1 of site technical position, "Repository Design Issues for State of NV Storage Site Investigations "NATARAJA, N S Engineering Branch (Post 831001) 00200 84/01/30 COPLAN,8 N Repository Projects Branch (Post 831001). 1p 2023 012
- --8402:30372 Draft site technical position "Repository Design Issues for State of NV Nuclear Wasts Storage Investigations." # Division of Waste Management 00200 84/01/31 36pp 22263 0:3
- 8402160001 Forwards draft site technical position, "Repository Design Issues for Salt Repository Project Investigations" Consolidation of similar or overlapping issues identified in technical position will be accomplished as next step NEUDER: 8 H Engineering Branch (Post 831001) 00368 84/01/27 JOHNSON: R L Repository Projects Branch (Post 831001) 44pp 22281 306
- ~-8402160004 Draft site technical position, "Repository Design Issues for Balt Repository Project Investigations " # Division of Waste Management 00368 84/01/31 44pp 22281 307
- 8402:60465 Trip rept of 8312:4 & 15 visits to Shiprock.NM & Durango.CO re status of hydrogoologic investigations at four high priority UHTRAP sites Viewpraphs ent!
 ORIFFIN.T.T., WEBER.M F. Opentechnical Branch (Post 831001)
 8401/18 KNAPP.M R. Geotechnical Branch (Post 831001)
 822301-137
- 8402160514 Requests NRC documents to CRWN Salt Repository Project so appropriate info can be made evailable to review panel members, as needed HARRISON-W Argume National Leboratory, 84/01/31, MILLER, H High evel Waste Technical Development Branch 1p. 22302; 020

- --8402160618 Requests assistance in facilitating access by peer reviewers to NRC waste mgt publications Harrison.coordinator of reviews, should be placed on mailing list to receive all related publications NEFF, J O Energy, Dept of 84/01/23 MILLER, H High Level Waste Tachnical Development Branch opp 28302 021
- B402140625 Submits schedule of upcoming meetings from B40202-0301 NEFF, J O Energy, Dept of 84/02/03 MILLER, H NRC - No Detailed Affiliation Given FRISHMAN, B Utah, State of FORSYTHE, R Texas. State of ip 22302 017
- B402160626 Submits schedule of upcoming meetings from B40131-0301 NEFF,J O Energy, Dept of B4/01/27 MILLER.H NRC - No Detailed Affiliation Given FRISHMAN,S Texas, State of FORSYTHE,R Mississippi, State of Ip 22302 Oló
- B402170002 Forwards draft site technical position, "Hasto Package Issues for NV Nuclear Waste Storage Investigations " WICK.E A Engineering Branch (Post 831001) 84/01/27 COPLAN.S N Repository Projects Branch (Post 831001) 1p 22319 322
- --8402170003 TUPF SYP-2 0 DRFT
 Draft site technical position: "Waste Form & Package Issues
 for NV Nuclear Waste Storage Investigations."
 # Division of Waste Management 84/01/31 27pp 22319:323
- B40R170006 Forwards comments & questions re review of onsite slope stability aspects of Bhiprock DOE environ assessment & flood erosion protection features Assessment of alternative environ impacts of remedial actions unsupported OREEVES.J Engineering Branch (Post 831001) 84/01/24 HTGOINBOTHAM.L Low-Level Waste & Uranium Recovery Projects Branch Spp 22319 314
- 8402170011 Forwards comments & questions re slope stability & flood erosion protection features submitted in Durango proliminary DEE Submitted info does not support alternative environ impacts of remedial actions GREEVES.J Engineering Branch (Post 831001), 84/01/26. HIGGINBOTHAM.L Low-Level Waste & Uranium Recovery Projects Branch 7pp 22319 142
- 8402170248 Forwards organizational chart, list of members & members of duties for Energy & Transportation Board, Nuclear Waste Policy Advisory Council & Nuclear Waste Technical Review Committee HAGGAND, K A. Mississippi, State of 84/02/03. MATTSON, D. Division of Waste Management 11pp 22313, 202
- 8402170277 "High Level Nuclear Waste Mgt Legislative Proposals." -status as of 840203 Washington, State of 84/02/03 ip 22313 212
- 8402170289 Forwards borehole sealing research & application Rept deals primarily w/salt areas & studies in State of TX BIMPKINS,W W Texas. Univ of, Austin, TX. 84/01/31 RHODERICA, J Division of Waste Management 33pp. 22313:299
- B402170290 Requests listed documentation be forwarded in order to complete review of high level nuclear weste repository issue.

 DRIVER, B M Utah, State of B4/02/06 MATTBON, D NRC No Detailed Affiliation Given 3pp 22313 231
- 8402170294 Forwards repts of telcons w/NRC re DDE Contract DE-ACO6-77RL01030 on BMIP. ABH.E B Rockwell International Corp R84-0300 84/01/27. OLSON,O L Energy, Dept of 5pp 22313.226
- 8402170278 Responds to 830913 ltr re implementation of Nuclear Wasts Policy Act of 1982 WHITE.M Texas, State of 83/10/13 DAVIS, J. G Office of Nuclear Material Safety & Safeguards, Director. 2pp 22313 223.
- 8402170312 Forwards tentative agenda for NRC 840309 meeting w/DDE Nuclear Project Ofc.Ofc of Nuclear Waste Isolation & author, per 840206 telcon FLOYD, D.R Manufacturing Sciences Corp 84/02/06 JQHNSON, R. Division of Waste Management 2pp 22313 220
- B402170330 Forwards updated schedules for UNTRA project EIS & assessments.

 MCRLEV.J A Energy. Dept of 84/02/03 MARTIN.D NRC No Detailed Affiliation Oiyen 7pp 22313 213

- 8:02170335 Discusses encl "Determination of Underground Corrosion Rates From Polarization Resistance Measurements." which proposes way of using short-term polarization resistance measurements to predict average uniform corrosion rates of pipelines MCKELLH B Waste Management Branch 84/02/08 WICK, E A Engineering Branch (Post 831001) 7pp 22313 171
- E402170514 Forwards Amend 38 to State of CA License 097, clarifying license conditions re waste form MASSBAMMER. D. A. Assistant Director for State Agreements Programs B4701724 DAVIS, J. Office of Nuclear Material Safety & Safeguards, Director DENTON, H. Office of Nuclear Reactor Regulation, Director DEYOUNG, R. Director's Office. Office of Inspection and Enforcement. 3pp. 22318 355
- 8402210375 Forwards draft site technical position on "Waste Package Eswes for Nuclear Waste Storage Investigations in Salt "
 WICK E A Engineering Branch (Post 831001) 84/01/27 LINEMAN. J. JORGON R L Repository Projects Branch (Post 831001) 1p 2243 257
- --8402210380 SALT STP-2 0 DRFT Draft site technical position, "Waste Package Issues for Nuclear Haste Storage Investigations in Salt " a Division of Waste Management 84/01/31 23pp 22343 258
- 6502270038 Requests, on behalf of Yakima Indian Nation.compilation of data from Rockwell Hanford Operation files to review DDE groups to consider Hanford site for high level nuclear waste repository.

 HOVIS.J B Hovis, Cockrill, Weaver & Bjur 84/02/10 WRIGHT, R RPC No Detailed Affiliation Given ip 22407 335
- 840227018) Forwards summary meeting hotes & workshop handouts from MRC/DDE 840109-12 workshop on geothemistry OLSON.OL. Energy, Dept of 84/02/07 WRIGHT.R J NRC No Datailed Affiliation Given STEVENS.D W Washington, State of FARTLETT.J W Energy, Dept of 400pp 22409 001
- B402270361 Forwards BMIP Bulletin BB-B4-001 providing seismic data reprocessing results Existing geophysical & other data insufficient to adequately characterize geologic tignificance RECCA. J Energy, Dept of B4/02/08 WRIGHT, B NRC No Datailed Affiliation Given. Spp. 22412 336
- 8402270623 Bubmits notice of upcoming meetings, per 830719-20 meeting Halce will be updated weekly Requests T Taylor be notified of any Addl meetings not listed NEFF.J D Energy. Dept. of 84/02/10 MILLER, H NRC No Detailed Attilation Given CHRISTOFFERSON Utah, State of FRISHMAN, S Teras, State of, 1p 22412 360
- 8402270502 Ack receipt of 840125 ltr questioning adequacy of trench map graylded to MRC & consultants & reminding author of NRC requests for more in-depth field trip Illustration/ interpretation of detailed mapping done in field SUCLEY.M.M. Interior. Dept of Geological Burvey WMPD. DLV-406 84/01/27. Energy, Dept of 2pp 22414 029
- 81022706d3 Bubmits weekly highlights for wk anding 840203 No significant events occurred. VIETH.D L Energy. Dept of. 84/02/06 BENNETT, JW Energy. Dept of 2pp. 22414:027
- 902270534 Ack receipt of B31216 ltr which reviewed recent work in UNTRAP. HIGHEOTHAM, L. Low-Level Haste & Uranium Recovery Projects Branch 84/02/08. MORLEY, J. A. Energy, Dept of 1p 22414,024
- 6402280103 Tentative agenda for High Level Nuclear Waste Advisory Council 840217 meeting in Lacey. WA to discuss update on state actions. 4 Energy. Dept. of 84/02/17 Energy. Dept of 3pp. 22429.332
- 8402290247 Forwards revised EIB implementation plans for Grand Junction kRifls U mill tailings remedial action sites, per 831201 review comments on draft implementation plan for Rifls EIB grand Junction plan revised for consistency MRLEY, J A. Energy, Dept. of. 84/02/07 BTERN, R J., GRUELSEMA, D H Energy, Dept. of. 1p. 22427 145
- --8402280253 "Implementation Plan for EIS Re Remedial Actions at U Mill Tailings Site Near Rifle.CD." • Energy, Dept. of 64/01/31. 23pp 22427 146
- --8402280349 "Implementation Plan for EIB Re Remedial Actions at U Mill Tailings Site Near Grand Junction.CO " 4 Energy, Dept of 84/01/31. 23pp 22429 210

- 8402270346 Forwards trip rept of 840107-16 visit to Hanford reservation for NRC hydrogeologic data gathering session re NRC evaluation of DWIP site hydrologic characterization efforts GORDON N . COLEMAN.N Geotechnical Branch (Post 831001) 84/02/03 KNAPP.N R Geotechnical Branch (Post 831001) 6pp 22438 274
- 8402290447 Forwards list of persons responsible for coordinating radioactive matis mgt.nuclear safety & licensing Requests copies of correspondence to specified contacts be provided to DK Lacker WHITE-N Texas, State of 84/02/02 PALLADING Commissioners 3pp 22438 184

XPORTLIC EXPORT AND IMPORT LICENSES

- 8306210409 License for Mitsui & Co (USA).Inc to export 129,360 lb Zircaloy-2 tube shells to Japan PETERSON.MR Assistant Director for Export/Import & International Safeguards 136300 B3/06/09 ip 18937 072
- 8402010032 Application for license to export 100 pieces zirconium tubes for BMR fuel rods to Sweden HERBCH, M M Hestinghouse Electric Corp MMH-445 84/01/23 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguerds 1p 22048 [1]
- B402010035 Forwards application for export litense for minor nuclear export Ltr of assurance required ZIMHERRAN.JV Assistant Director for Export/Import & International Bafeguards 84/01/24 RAYMOND.J Energy, Dept of 1p
- --8402010051 Application for license to export 13,518 kg U.as U hexafluorida, to Japan FOSTER, C M Edlow International Co KLK-21 84/01/18 ip 22048 100
- 8402010082 Application for license to export 210 mg V,enriched to 3%, to Bueden GOLDMER, S Humanetics, Inc. 84/01/20 WRIGHT Dffice of International Programs, Director 2pp 22058 109.
- 8402010092 Forwards Westinghouse 840109 ltr requesting removal of two power reactor primary coolant pumps from canceled Export License XR-0142 Remaining components assigned component export license control number XCOM-0843 ZIMMERMAN.J V Assistant Director for Export/Import & International Safegords 84/01/20 8TD18ER.C R State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs 19 22058 107
- --8402010097 Application to amend literse to export removing two reactor coolant pumps HERBCH.M M Westinghouse Electric Corp MMH-439 84/01/09 ZIMMERMAN.J V. Assistant Director for Export/Import & International Bafeguards 19 22038 108
- 8402010131 Application for license to export 220 kg zirconium barrier tube shell to Japan EJIMAN Hitsui & Co (USA). Inc (subs of Mitsui & Co . Ltd) 803-256 84/01/20 lp 22048 311
- 8402010133 License for Westinghouse to export 100 pieces lirconium tubes to Bweden ZIMMERNAN.U V. Assistant Director for Export/Import & International Bafeguards 84/01/23 ip 22048 060
- 8402010295 Application for license to export five 23934 ion chambers to Canada HEETHER.W.H Westinghouse Clectric Corp 84/01/09 ip 22046 320
- 8402010297 Application for license to export three repaired 23934 ion chambers to Canada HEETHER.W H Westinghouse Electric Corp 84/01/09 Ip 22046 319
- 8402010278 Application for license to export spare parts for loading & unloading fuel elements into reactor to Canada SCHUAB-J B General Motors Corp WO 84116 84/01/06 ip 22046 318
- B402010299 Application for license to export spare parts for loading to unloading fuel elements into reactor to Canada SCHAUB.J B General Motors Corp NO B4117 B4/01/06 19. 22048-017
- B402010300 Application for license to export 3 215 kg U-235, as enriched U dioxide powder, to Japan. KOMORIS Marubeni America Corp. (subs of Marubeni Corp.) ZH0291 84/01/11 2pp 22046 315

- 8402010301 Application for license to export Model CS-1.Pu-239 alpha check source, to Australia ESINDSA, 0 Eberline Instrument Corp SO NO 896562 83/12/22 ip 22046 314
- B402010340 Advises that Edlow Intl 831128 application for license to import 3.780 kg Usenriched to 3.7% U-235, in form of eight FMR fuel assemblies, conforms to std provisions MDDRE, R N Assistant Director for Export/Import & International Safeguards 84/01/17 Assistant Director for Export/Import & International Safeguards 1p 22057 362
- 8402010341 Application to amend export liconse, increasing quantity to 793 34 kg U-235, contained in 22,560 kg U for export to West Germany HANNETT.B A Transnuclear, Inc 94/01/16 MODRE,R N Office of International Programs, Director 2pp 22061 311
- B402010356 Advises that Exxon B31130 application for license to import 925.000 kg U conforms to std provisions re shipment of normal & low enriched U Import will not constitute undue risk to public MODRE,R N Assistant Director for Export/Import & International Safeguards B4/01/11 Assistant Director for Export/Import & International Safeguards 1p 22039 351
- 8402010374 Application for license to export Zircaloy-4 barrier tube shell to Japan EJIMA,M Mitsui & Co (USA), Inc (subs of Mitsui & Co , Ltd) 803-262 84/01/20 ip 22059 336
- 8402010379 License for Catter Corp to export 330 kg natural U ore to Canada IMMERMAN.J V Assistant Director for Export/Import & International Safeguards 84/01/23 ip 22059 325
- 8402010426 Informs that License XSNM-2097 may be issued No matl changed circumstances since issuance of License XSNM-2081 MODRE,R.N Assistant Director for Export/Import & International Safeguards 84/01/19 Assistant Director for Export/Import & International Bafeguards 1p 22061 310
- 8402010428 Informs that License XSNM-2080 may be issued No math changed circumstances since issuance of License XSNM-2081 MODRE,R N Assistant Director for Export/Import & International Safeguards 84/01/19 Assistant Director for Export/Import & International Safeguards ip 22061 308
- B402010431 License for Edlow Intl Co to export 792 kg U-235, contained in 22, 755 kg U, to Japan ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards KLK-19 B4/01/24 2pp. 22061, 305.
- B402010447 Application for license to export 662 kg U-235.as enriched U dioxide, to Japan OKADA.6 Hitsui & Co (USA), Inc (subs of Mitsui & Co., Ltd) MBK-2Fi-R3(A) B4/01/13 ip 2204i 362
- B402010450 Application for license to export 1,000 g deuterium oxide, containing 99 80% deuterium to Canada ABEL 0 F. Bio-Rad Laboratories 84/01/16. 1p 22061:361.
- 8402010458 Application to amond export license, increasing enrichment to 3 85%.
 HANNETT, B A Transnuclear, Inc. RBU-351 84/01/18, MODRE, R N
 Office of International Programs, Director 1p. 22041:340.
- 8402010440 Application for license to export 88 lb reactor grade Zircaloy-4 fuel cladding tubes to Romania KITAYAMA.A Nikko Wolverine, Inc. 8248 84/01/17. lp. 22041.359
- B402010461 Application for license to export 450 guide thimble tubes to Japan.

 SHINGHARA, C I toh & Co (America), Inc. MGI-155. 84/01/10 ip
 - 'or export license for minor nuclear or for Export/Import & International J Energy, Dept of Spp
 - ort of 792 kgs U-235, contained in 84/01/11 RAYMOND, J F Energy.

- 8402020188 License for Westinghouse to export 350 g U-235,contained in 375 g U-to Belgium PETERSON,M R Assistant Director for Export/Import & International Bafeguards MMH-423 84/01/18 2pp 22062 252
- B402020192 Amend I to Honeywell Defense Sys Div export license, changing ultimate consigner name, extending expiration data from B31231 to 861231 & increasing quantity of matl from 535,800 kg depleted U to 2,007,500 kg depleted U T1MHERMAN, J V Assistant Director for Export/Import & International Bafeguards SUB-971 B4/01/20 ip 22062 249
- 8402020197 Amend 1 to Sigma Chemical Co export license, extending expiration date from 840201 to 860201 ZIMMERMAN.JV Assistant Director for Export/Import & International Safeguards D-90 84/01/11 1p 22062 248
- 8402020199 License for Exxon Nuclear Co.Inc to import 925.000 kg U. enriched to max 5% U-235 ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 84/01/12 2pp 22062 237
- B402020205 Ltr of assurance re export of 467 kg U-235,contained in 13.518 kg U, to Japan SHIRAKAWA, T Japan, Qoyt of 84/01/11 RAYMOND, TF Energy, Dept of 1p 22062 236
- B402020269 Ltr of assurance re export of 30,440 kg U.containing 996 kg U-235, to Sweden Lindstrom. M Sweden, Govt of 84/01/10 RAYMOND, J F Energy, Dept of 1p 22062 151
- 8402020303 License for Union Carbide Corp to export 10,500 lb nuclear grade graphite to United Kingdon. PETERSON,N R Assistant Director for Export/Import & International Safeguards 70-0059-10 84/01/20 1p. 22062 152
- B402020365 License for Edlow Intl Co to export 4 kg U-235.contained in 20 kg U.to Canada ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards AECL-28(83) 84/01/11 2pp 22062 149
- 8402020422 Application to amend export license, extending expiration date to 840101 FOSTER.C M. Edlow International Co 83/12/30 MODRE,R N Assistant Director for Export/Import & International Safeguards 19.
- 8402020425 Ltr of assurance re export of 350 g U-235,contain of in 375 g U.to Belgium
 DUBLIS, D European Communities, Commission of. 84/01/10
 RAYMOND, J Energy, Dept of ip 28068 183
- 8402020434 License for Union Carbide Corp to export 231,171 lb nuclear grade graphite to Japan PETERSON,M R Assistant Director for Export/Import & International Safeguards 07-0128-10 84/01/20 1p 22062 181
- 8402020443 Executive Branch position re Union Carbide Corp application to export 10.5000 to nuclear grade graphite sleeves & rods to United Kingdom License should be granted DEVINE, J. B. State, Dept. of, Bureau of Oceans & Intl. Environ & Scientific Affairs, 84/0/1/7 BHEA, J. R. Office of International Programs, Director 2pp 22062 175
- 8402030025 License for Edlow Intl Co to import 3.780 kg U.enriched to 3 7% U-235.from United Kingdom PETERSON,M R Assistant Director for Export/Import & International Baleguards 84/01/18 1p 22091 249.
- 8402030028 License for Carpenter Technology Corp to export 200 Zircalog-4 alloy fuel channels to West Germany ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 3-1209-031 84/01/13 1p 22091:247
- 8402030030 License for Carpenter Technology Corp to export 38
 Zircalog-4 alloy fuel channels to Japan.
 ZiMMERNAN,J V Assistant Director for Export/Import & International Safeguards 2-1221-054 84/01/13 ip 22071,246
- 8402030033 License for Carpenter Technology Corp to export 150 Tircalog-4 alloy fuel channels to West Germany TIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 3-1209-031 84/01/13 ip 22091 094
- 8402030056 License for Reuter-Stokes Inc to export one in-core flux probe Model R8-C6-0801-274. to Italy ZIMMERNAN. J V Assistant Director for Export/Import & International Safeguards 8-0083 84/01/13 ip 22071 093

- 6432030061 License for Mitsubishi Intl Corp to export 500 mCi Cf-252.as encapsulated cermet wire, to Japan IMPERNAN, J V Assistant Director for Export/Import & International Sifeyvards 84/01/13 1p 22091 058
- 6407030123 Forwards B40110 telex re Export License Application ISM-1975 stating reason for requesting increase in amount of math from 30 kg to 3B kg highly enriched U HANNETY.B A Transnuclear, Inc. HUK 40B 84/01/11 MODRE.R N Office of International Programs, Director 2pp 22090 297
- \$402030127 Discusses proposed license to export components to Sweden License issued w/o normal 15-day waiting period [INTERMAN.J V Assistant Director for Export/Import & International Safeguards \$4401/20 Assistant Director for Export/Import & international Bafeguards ip 22087 361
- 8402030322 Requests Executive Branch position re Nikko Wolverine, Inc application for license to export small quantity of Tirceley-4 tubes to Romania W/o encl TIPMERHAN, J V Assistant Director for Export/Import & International Sirguards 64/01/23 STOIBER, C R State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs 19 22089 351
- 6402030339 Forwards addl info from applicant re amend to export litemse Telex from NUKEM states addl matl required to fuel Prise reactor for full yr IMPERMAN.J V Assistant Director for Export/Import & International Sissuards 84/01/24 STDIBER.C State. Dapt of Bureau of Oceans & Intl Environ & Scientific Affairs 1p 22089 353
- SHOROGOGA Application for license to export emitter Models MX34720, MX34721 & self-powered radium neutron detectors to Greece a Mestinghouse Electric Corp. ZE 40186 84/01/18 1p. 22089 352
- 602060190 Forwards application for export license for minor nuclear expert Ltr of assurance required IMPERMAN.J V Assistant Director for Export/Import & International Balegoards 84/01/24 RAYMOND.J Energy, Dept of ip
- \$102060473 License for Eberline Instrument Corp to export 0.3 microgram Pv-237, contained in findel CS-1, alpha check source, stainless steb to Australia IMPERIAN.J V Assistant Director for Export/Import & International Safiguards 60 NO 896562 84/01/31 2pp 22110 284
- 6M2060480 Application for license to export U-235, deposited as U oxide an internal surface of Model RS-C3-2510-114 radiation aftector, to Bouth Africa FOMELO S Reuter-Stokes, Inc. 9E-8763 84/01/19, 3pp 22110 227
- #42060594 License for GM Corp to export miscellaneous specially essigned spare parts for loading & unloading fuel elements, to Canada International International Safeguards 84/02/01 1p 22092 085
- \$\\\\2000510 Advises that no matl changed circumstances since isouance of Lirense XSNM-2079 License XSNM-2081 may be issued MORER R Assistant Director for Export/Import & International Safiguards 84/01/19. Assistant Director for Export/Import & International Bafeguards 1p 22174 044
- E40200506 Ltr of assurance re export of 3 49 g U-235, contained in 2 ly U & 1 79 g Pu-239, contained in 2 07 g Pu to Wast Gereany West Greany West So European Communities, Commission of 84/01/11 RAMDRO, J Energy, Dept of 1p 32191, 359
- 8432996543 Requests withdrawal of export license application dtd 830222 KANNETT, B. A. Transmuciear, Inc. NUK-431 84/01/31 MDDRE, R. N Office of International Programs, Director ip 22191:362
- 842100342 Requests Executive Branch position re Saunders Roe
 Developments. Inc application for license to export 500,000
 (i tritium gas to United Kingdom, replacing License XB-1010
 which expired B30915
 [IMERMAN.J V Assistant Director for Export/Import & International
 Safeyuards B4/02/02 BTGIBER.C R State. Dept of, Bureau of
 Greans & Intl Environ & Scientific Affairs 1p 22207:361

- 8402100347 Requests Executive Branch position re Ediow Intl Co application for amend to license to export requesting reexport of 100 microgram source of CF-232 from United Kingdom to India 21MMERHAN.J V Assistant Director for Export/Import & International Safeguards 84/02/02 STOIDER.C R State Dept of Bureau of Oceans & Intl Environ & Scientific Affairs ip 22207 336
- --8402100351 Application for amend to license to export 600 microgram: CF-292 source to India FOSTER,C M Edlow International Co AMER-84 84/01/26 lp 22207 399
- 8402100362 Forwards ltr frum Marubeni America Corp correcting address of ultimate consignes for export license application ZIMMERMAN.J V Assistant Director for Export/Import & International Sofeguards 84/02/02 STOIDER.C R State, Dept of Bureau of Oceans & Intl Environ & Scientific Affairs 1p 22207 331
- ---B40210036G Corrects address for ultimate consignee for application for license to export SNM to Japan UHCV.P Marubeni America Corp (subs of Marubeni Corp) MAS-B209 84/01/25 WRIGHT.B L Assistant Director for Export/Import & International Safeguards ip 22207 332
- 8402100372 Forwards application for export license for minor nuclear export Ltr of assurance required
 ZIMMERMAN.JV Assistant Director for Export/Import & International Bafeguards 84/02/OP RAYMOND.J Energy, Bept of Ep
 22207 313
- ---8402100379 Forwards application to export slighty enriched
 U hexafluoride to Japan
 SHIMA,8 Mitsubish: International Corp (subs of Mitsubishi
 Corp) HBA-5403-07 B4/01/21 Assistant Director for
 Export/import & International Safeguards 2pp 22207 314
- --8402100385 Application for license to export 11.519 kg U, enriched to 3 45% U hexaflooride, to Jepan SHIMA, S Mitsubishi International Corp (subs of Mitsubishi Corp) H8A-5483-07 84/01/23 2pp 22207 316
- 3402100389 License for Humanoid Sys to export 4 930 mg U-235, container in 231 mg U, to Swedon PCTERSON H R Assistant Director for Export/Import & International Safeguards 84/02/02 2pp 22211 355
- 840@10039@ Application to amend license to export increasing quantity of matl by 1.326 298 kg U-235, contained in 93,321 646 kg U & 0 283 kg U-235, contained in 7 0 kg U HANNETT.B A Trabsnuclear. Inc ABU-395 84/01/31 MODRE,R N Office of International Programs, Director 1p 22210 338
- 8402100376 Application to amend license to export increasing quantity of matl by 2.995 kg U-235.69.contained in O48 kg U, extending expiration date to 901231 & changing ultimate consigner address
 HERSCH.M M Westinghouse Electric Corp MMH-448 84/01/26
 ZIMMERNAN, J V Assistant Director for Export/Import & International Safeguards 1p. 22208 362
- 8402100466 Forwards application for license to export 9 depleted U top crops to Canada CONVEY.D A Nuclear Netals, Inc. 84/01/27 HEMBY.E Office of International Programs, Director 1p. 22211 159
- --8402100469 Application for license to export 9 depleted U top crops to Canada
 * Nuclear Metals, Inc I-207-7 84/01/27 ip 22211 160
- 8402100480 Application for amend to license to export correcting address of ultimate consignoe UHOV.P Marubeni America Corp (subs of Marubeni Corp) MAS-8209 84/01/25 WRIGHTI I. Assistant Director for Export/Import & International Safeguards ip 22213 044
- B400:100483 Application for amend to license to export correcting date of estimated first use to June 1986 UMOV.P Marubeni America Corp. (subs of Marubeni Corp.) MAS-8209 B4/01/29 WRIGHT.S L. Assistant Director for Export/Import & International Safeguards ip. 22213 045
- 8402130139 Forewards application for export license for minor nuclear export Ltr of assurance required.

 ZIMMERMAN.J V Assistant Director for Export/Import & International Bafeguards 84/02/02 RAYMOND.J Energy, Dept of 1p 20216 347

- --8402i30i42 Forwards application to export slightly enriched U hexaflooride to Japan SHIMA,5 Mitsubishi International Corp (subs of Mitsubishi Corp) H8-5483-06 84/01/23 Assistant Director for Export/Import & International Safeguards 2pp 222i6 348
- --8402130147 Application for license to export 32.856 kg U.enriched to 3 40% U hexafluoride to Japan SHIMA.6 Mitsubishi International Corp (subs of Mitsubishi Corp) H5A-5483-06 84/01/16 2pp 22216-350
- 8402i303ii Discusses Humanoid Sys request to export RNM to Sweden Export meets requirements of Atomic Energy Act of 1954 License issued w/o customary 15-6ay waiting period HRIGHT.B L. Assistant Director for Export/Import & International Safeguards 84/02/02 Assistant Director for Export/Import & International Safeguards 1p 22237 154
- 8402130315 Forwards application for export license for minor nuclear export. Ltr of assurance required M/o encl
 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/02/07 RAYMOND, J Energy, Dept of 1p 22216 362
- 8402130320 Forwards Edlow Intl application for export license for minor nuclear export Ltr of assurance required ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 84/02/07 RAYMOND.J Energy, Dept of 1p 22216 360
- --B402130324 Application for license to export 28,553 kg U.as U hexafluoride,to Japan FOSTER,C M Edlow International Co KLK-22 84/01/27 lp. 22216 361
- B402130342 Forwards application to export 24,355 kg enriched U hexafluoride.containing 717 kg U-235,to Japan NAKAMURA,N Marubeni America Corp (subs of Marubeni Corp) B4/02/01 WRIGHT,B L Assistant Director for Export/Import & International Safeguards ip 22216 358
- ~-8402130348 Application for license to export 24,355 kg enriched U hexafluoride.containing 717 kg U-235,to Japan * Marubeni America Corp (subs of Marubeni Corp) ZHO321 B4/02/01 ip 22216 357
- B402130352 Forwards Westinghouse application for amend to litense for minor nuclear export Ltr of assurance required ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/02/07 RAYMOND, J Energy, Dept of ip. 22216 354
- --8402130363 Application to amend license to export 6,250 kg U-235, contained in 174,778 kg of U, to South Korea & extending expiration date to 901231
 HERSCHIM M Westinghouse Electric Corp MMH-448 84/01/26
 ZIMMERMARIJ V Assistant Director for Export/Import & International Safeguards ip 22216-355
- 8402130402 Forwards Transpucteer. Inc application for amend to export license for minor nuclear export Ltr of assurance required ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 84/02/07 RAYMOND.J Energy, Dept of 1p 22216 179
- ~~840213040B Application to amend license to export 3,032 058 kg U-235, contained in 93,321 646 kg U & 0 607 kg U-235, contained in 17 0 kg U to West Germany
 HANNETT, I A Transnuclean, Inc RBU-395 84/01/31 MODRE, R N
 Office of International Programs, Director 1p 22216 180
- B402130414 Executive Branch position re Braunkohle Transport USA application to export 1,500,000 kg natural U.in form of U ore concentrate or U hexafluoride to be used as fred matl to EURATOM License should be granted.

 MCGOLDRICK.F State. Dept of Bureau of Oceans & Intl Environ & Scientific Affairs B4/02/Q6 SHEA.J R Diffice of International Programs, Director 4pp 22214 165
- 3402130465 Forwards application to amend license to export 600 micrograms Cf-252 to Amersham Intl for reexport to India FOBTER.C M Ediaw International Co 84/01/26 HEMBY.E Assistant Director for Export/Import & International Safeguards ip 22214 361
- #8402130472 Application to amend license to export 400 micrograms Cf-352 to India.
 FDBTER.C M Edlow International Co 84/01/23 HEMBY.E
 Assistant Director for Export/Import & International Safeguards.
 1p 22214 362

- 8402130474 Application to amend license increasing exportable equipment value REYES.A J Nitsubishi International Corp (subs of Mitsubishi Corp) 84/01/23 HEMRY.E Assistant Director for Export/Import & International Safeguards ip 22214 360
- 8402130476 Application to amend export license to include listed plants in Japan SAITO,T Mitsubishi International Corp (subs of Mitsubishi Corp) PIT-L-4150 84/01/24 HENRY,E Assistant Director for Export/Import & International Safeguards ip 22214 359
- 8402130512 Telecopy application for license to export 8 items of nuclear matl to West Germany WALKER, J V Sandia Laboratories 11003310 84/01/19 IIMERMAN, J V Assistant Director for Export/Import & Internetional Safeguards 1p 22214 289
- 8402130517 License for GA Technologies, Inc to export miscellaneous specially designed or prepared parts & components for use in TRIGA reactor only to Brazil PETERSON, MR Assistant Director for Export/Import & International Safeguards IEL-3095 84/01/30 1p 22213 362
- 8402130570 License for C Itch & Ca to expert 650 guide thimble tuber to Japan ZIMMERMAN J V Assistant Director for Export/Import & International Safeguards MOI~155 84/01/30 ip 22213 361
- 8402130523 License for Exxon Nuclear Co to export 998 kg U-235, contained in 30,440 kg U to Sweden ZINMERMAN.J V Assistant Director for Export/Import & International Safeguards 84/01/24 2pp 28214 005
- B402130526 Amend 1 to Westinghouse Corp export license, adding intermediate consigner & another party to exported mat1 being sent to Japan ZIMMERMAN, J V Assistant Director for Export/Import & International Bafeguards ZE 60282 84/01/24 lp 22213 360
- 8402130536 Forwards application for license to export 1 0 mg 0 584 Ci Ca-252 neutron source to West Germany KIEL. 0 R Exxon Nuclear Co , Inc (subs of Exxon Corp). 84/01/27 ZIMMERMAN-J V Assistant Director for Export/Import & International Safeguards ip 22213 336
- --B402130540 Application for license to export 1 0 mg 0 BB4 Ci Cf-252 neutron source to West Germany KIEL.G R Exxon Nuclear Co , Inc (subs of Exxon Corp) 84/01/27 ip 22213 357
- 8402130537 Forwards Edipw Intl Co application for export license for minor nuclear export Ltr of assurance required ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/02/07 RAYMOND, J Energy, Dept of ip 22213 353
- --8402130368 Application for license to export 19,618 kg U.containing 677 kg U hexafluoride, to Japan FOSTER.C M Edlow International Co KLK-23 84/01/27 ip 22213 354
- B402140543 Application for license to export zirconium-4 fuel tubes, top end plugs, bottom end plugs & stainless steel springs to Belgium HERBCH, M M Wastinghouse Electric Corp MMH-453 B4/01/31 [p
- 8402140546 Forwards application to export 60,000 Ci tritium to Bwitzerland KEATING,L. Mark IV Industries 84/02/01 HEMBY,E D#fice of International Programs, Director 1p 22256 343

22256 345

- --8402140549 Application for license to export 60,000 Ci tritium to Switzerland KEATING, L. Mark IV Industries RCT 7-83 84/01/27 1p 22256 344
- 8402140566 Application for license to export 60,000 lb Zircaloy-2 TREX to West Germany AERNI, B L Teledyne Hah Chang Albany 3550 (JFM) 84/01/31 1p 22256 337
- B402140573 License for Saunders-Roe Development, Inc to export 30,000 Ci tritium to United Kingdom ZIMMERNAN, J V Assistant Director for Export/Import & International Safeguards NRC-607 84/02/08 ip 22236 331.

- 8402(40583 License for Westinghouse to export three ion chambers. Hadels 23934, to Canada INMERHAN, J V Assistant Director for Export/Import & International Safeguards RMR 84/02/07 ip 22256-330
- 8402140589 License for Mitsui & Co.Inc to export 440 Kg Zircalay-4 tarrier tube shells to Japan INMERHAN.J V Assistant Director for Export/Import & International Safaguards 803-262 84/02/07 ip 22256 323
- 8402140593 License for Westinghouse to export five ion chambers, Models 29934 to Canada IMMERNAN J V Assistant Director for Export/Import & International Safeguards RMR 84/02/06 ip 22256 322
- 8t02140594 Application for license to export two power range detector assemblies to Sweden SCHMAUTZ.C E Westinghouse Electric Corp ZE 20694 84/02/01 1p 22256 321
- 8602140595 Application for license to export six compensated ionization chambers. Type 23744.to France SCHMOUTZ, C E Westinghouse Electric Corp ZE 40187 84/02/01 1p 22253 320
- B402140578 Application for license to export one BF3 proportional counter to France SCHAUTZ, C. E. Westinghouse Electric Corp. ZE 40190 84/02/01 1p. 2225 317.
- 8402(AOSO) Application to amend license to export, increasing quantity to 1.348 364 kg U-235, contained in 37,643 kg U HAMETT, B A Transnuclear, Inc RBU-334 84/02/02 MOGRE, R N Office of International Programs, Director 1p 22253 362
- 8402140603 License for Bandvik Special Metals Corp to export 20 pieces IIrcaley-4 cladding to Japan IIMERMAN.J V Assistant Director for Export/Import & International Bafeguards SSM-31074/75 84/02/06 ip 22853 358
- B402140605 Application for license to export 200,000 lb Zircaloy-4 part filgered cladding to Canada BAMMERTER,D H Sandvik Special Metals Corp SSM-31016/31017 84/02/02 ip. 22253 352
- 8402140610 Application to amend license to export to show ATLAS,AB as fabricator/mfg of fuel elements End use statements encl NAMETT.B A Transnuclear, Inc. NUK-420 84/02/02 MOORE,R.N. Office of International Programs, Director 2pp 22254 332
- 8402140614 License for Dio-Rad Labs to export 5 kg deuterium oxide to Canada. ILMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/02/06 ip 22258 140
- 9402140617 License for Mitsui & Co.Inc to export 220 kg Zircaloy Warder tube shells to Japan IMMERHAN, J V. Assistant Director for Export/Import & International Safeguards 803-256 84/02/07 ip 22258 139
- 8402140620 License for Westinghouse to export one Model WX34720 neutron fatector & one Model WX34721 neutron detector to Greece. PETERSON, M R Assistant Director for Export/Import & International Safeguards ZE-40186. B4/02/03 ip 22238 i33
- B402140524 Informs of Transnuclear Inc 840131 request for withdrawal of export license application Withdrawal should be noted in except.
- records.
 IMMERMAN, J V Assistant Director for Export/Import & International Serguards 84/02/06 STOIDER.C.R State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs 1p 22258, 145
- 8402150021 Forwards application for license to export 11,519 kg U, containing 398 kg U-235, to Japan SHIMA, B Mitsubishi International Corp (subs. of Mitsubishi Corp.) HSA-3483-07 84/01/23. Assistant Director for Export/Import & International Bafeguards 3pp. 22262.360
- -B402150026 Application for license to export 11,519 kg U.containing 398 kg U-235, to Japan.

 † Kitsubishi International Corp (subs of Mitsubishi Corp.)

 H3A-3483-07 84/01/23 ip 22262 363
- 8402150029 Forwards application for license to export 32,856 kg U, containing 1,134 kg U-235, to Japan.

 \$\text{3HIMA.8. Mitsubishi International Corp (subs of Mitsubishi Corp)} \text{HSA-5463-06, 84/01/23 Assistant Director for Export/Import & International Safeguards. 3pp 22262 348

- ---8402150030 Application for license to export 32.856 kg U.containing 1.134 kg U-235 to Japan SHIMA.9 Mitsubishi International Corp (subs of Mitsubishi Corp) H34-5483-06 84/01/16 ip 22262 351
- 8402150465 License for Sandia Natl Labs to export 3,490 g U-235, contained in 6.25 g U & 2.070 g Pu-237, to West Germany PETERSONN R Assistant Director for Export/Import & International Safeguards 84/01/30 2pp 22263 211
- 8402150470 License for Mestinghouse to export one compensated ionization chamber. Model WL22084 & one uncompensated ionization chamber. Model LW6937A. to Brazil PETERSON.M & Assistant Director for Export/Import & International Safeguards 2W70142 84/01/30 ip 22263 210
- 8402150489 Forwards application to export 10.066 kg U hexafluoride to Japan NAMANURA,N MARISOL, Inc. 84/02/01 WRIGHT, B L. Assistant Director for Export/Import & International Safeguards ip 22263 209
- --B402150492 Application for license to export 10.046 kg V hexafluoride, containing 302 kg U-235, to Japan NAKAMURA: N Marubeni America Corp (subs of Marubeni Corp) ZH0321 84/02/01 ip 22263 208
- B402150500 Executive Branch position re Saunders-Roe Developments, Inc application to export 30,000 Ci bulk gaseous tritium for production of seeled light sources to United Kingdom License should be granted MCGOLDRICK, F. State, Dept. of, Bureau of Oceans & Intl Environ & Brientific Affairs 84/02/04 SHEAJ R. Office of International Programs, Director Ip 22263 195
- B402160003 Third partial response to FOIA request for info re votes & attendance at Commission meetings for Jul 1981 Jul 1983 CHILKS J Office of the Secretary of the Commission B3/12/14 Public Document Branch 1p 22281 023 24X Fiche 50-000, B3/12/14, B402/60003
- --B402160375 Discusses SECY-82-93 re license amend for proposed exports of dispersed tritium to add1 destinations
 CHILK.B J Diffice of the Secretary of the Commission S82-93
 62/03/15 DIRCKS.H J Office of the Executive Director for Operations ip. 22281 167 24X Fiche 50-000.83/12/14,8402160003
- --8402160413 Discusses SECY-83-187 re proposed licenses to export components to mixed oxide fuel fabrication facilities in Belgium & Federal Republic of Germany CHILK.H J Office of the Secretary of the Commission 63/06/06 DIRCKS.H Office of the Executive Director for Operations Ip 22861 271 24X Fiche 50-000,83/12/14,8402160003
- --B402160208 Discusses 6ECY-B2-1B2 re proposed license to export 3,000 kg deuterium oxide to 24 countries
 CHILK.B J Office of the Secretary of the Commission. 82/05/27
 DIRKRS.W J Office of the Executive Director for Operations lp
 22281 189 24X Fichs 50-000.83/12/14.8402160003
- --8402160338 Discusses SECY-83-104 re approval of proposed license to export natural U to EURATOM countries
 CHILK:S J Office of the Becretary of the Commission 83/03/29
 DIRCKS: W Office of the Executive Director for Operations 1p
 22281 275 24X Fiche 50-000,83/12/14,8402160003
- --B402160291 Discusses SECY-B2-376 re approval of proposed license to export research reactor & BMN to Bampladesh CHILK, B J Office of the Secretary of the Commission, 82/10/01 DIRCKS,W J Office of the Executive Director for Operations 1p 22281 231 24X Fiche 50-000,83/12/14,8408160003
- --8402160138 Discusses SECY-81-607 re approval of proposed license to export high enriched U to France CHILK,8 J Office of the Secretary of the Commission 981-607 81/11/25 DIRCKS,W J Office of the Executive Director for Operations. 1p 22281:128 24X Fiche 50-000,83/12/14,8402160003
- --8402160135 Discusses SECY-82-126.proposed export of low enriched U tual to Malaysia CHILK.S J Diffice of the Secretary of the Commission 82/04/05 DIRCKS.W J Office of the Executive Director for Operations. 1p 82281 178 24% Fiche 50-000,83/12/14,8402160003
- ---B402160074 Discusses BECY-Bi-511 re approval of proposed license to export high enriched U to Federal Republic of Germany.

 CHILK:S J Office of the Secretary of the Commission SHI-511

 B1707/04 DIRCKS:W J. Office of the Executive Director For Operations Ip 2278: 097 R4X Fiche 50-000.83/12/14.8402160003

- --8402160128 Discusses SECY-81-614 re proposed export of research reactor & fuel to Morocco CHILK, 5 J Office of the Secretary of the Commission \$81-614 B1/11/25 DIRCKS, W J Office of the Executive Director for Operations 1p 22281 127 24% Fiche 50-000,83/12/14,8402160003
- --B402160173 Discusses SECY-81-489, approval of proposed license to export high enrithed U to Foderal Republic of Germany CHILK, S J. Office of the Secretary of the Commission S81-489 B1/09/01 piRCKS, W J. Office of the Executive Director for Operations 1p 22281 089 24% Fiche 50-000.83/12/14,8402168003
- --8402160167 Discusses SECY-81-427 re approval of proposed license to export low enriched U to Philippines
 CHILK.9 J Office of the Secretary of the Commission S81-427
 BJ/08/31 DIRCKS.W J Office of the Executive Director for Operations ip 22281 088 24X Fiche 30-000.83/12/14,8402160003
- --B402160121 Discusses SECY-81-608 re approval of proposed license to export high enriched U to France
 CHILK.S J Office of the Secretary of the Commission S81-608
 B1/1/25 DIRCKS.W J Office of the Executive Director for Operations 1p 22281 126 24% Fiche 50-000.83/12/14,8402160003
- ---8402160115 Discusses SECY-81-519 re approval of proposed litense to export high enriched U to Canada CHILK-5 J Office of the Secretary of the Commission B1/09/22 DIRCKS W J Office of the Executive Director for Operations ip 22281 105 24X Fiche 50-000.83/12/14.8402160003
- --8402160291 Discusses SECY-82-374 re approval of proposed license to export research reactor & SNN to Dangladesh CHILK.S J Office of the Secretary of the Commission. 82/10/01 DIRCKS J J Office at the Executive Director for Operations ip 22281 231 24X Fiche 50-000.83/12/14.8402160003
- --8402160049 Discusses SECY-81-490 re approval of proposed license to export low enriched U to Talwan CMILK.S J Office of the Secretary of the Commission S81-490 81/09/01 DIRCKS.W J Office of the Executive Director for Operations IP 22281 070 24X Fiche 50-000.83/12/14,8402160003
- --840216026B Discusses SECY-82-238 re approval of proposed licenses to export low enriched U to Taiwan CHILK, B J Office of the Secretary of the Commission 82/06/28 DIRKS, W J Office of the Executive Director for Operations. 1p 22281 202 24X Fiche 50-000:83/12/14,8402160003
- --8402160124 Discusses SECY-82-108 re approval of proposed license to export high & medium enriched U to Switzerland CHILK.S J Office of the Secretary of the Commission 82/03/31 DIRCKS.W J Diffice of the Executive Director for Operations 1p 22281 176 24X Fiche 50-000,83/12/14.8402160003
- --8402160269 Discusses SECY-82-344 re proposed license to export high enriched U to Greece CHILK,S J Office of the Secretary of the Commission 82/09/22 DIRCKS,W J Office of the Executive Director for Operations ip 22281
- ~-8402160239 Discusses SECY-82-211 re approval of proposed license to export high enriched U to Canada CHILK.S J Office of the Secretary of the Commission 82/06/15 DIRCKB.W J Office of the Executive Director for Operations 1p 22281 196 24X Fiche 50-000/83/12/14/8402160003
- ---8402160255 Discusses SECY-82-359 re license amend to increase quantity of high enriched U for export to Canade CHILK.5 J Office of the Secretary of the Commission 92/09/17 DIRKS.W J Diffice of the Executive Director for Operations ip 22281 223 24X Fiche 50-000,83/12/14.8402160003
- --8402160350 Discusses SECY-83-116 re approval of proposed license to export high enriched U to Japan CHILK,9 J Office of the Secretary of the Commission 83/04/13 DIRCKS,W Office of the Executive Director for Operations, 1p 22281 279 24X Fiche 50-000,83/12/14,8402160003
- --8402160285 Discusses SECY-82-227 re approval of proposed license to export high enriched U to France for high-flux reactor in Grenoble CHILK.8 J Office of the Secretary of the Commission. 82/06/30. DIRCKS,W J Office of the Executive Director for Operations ip 22881 207 24% Ficho 50-000,83/12/14,8402160003
- --8402160268 Discusses, SECY-B2-238 re approval of proposed licenses to export low enriched U to Taiwan CHILK:S J Office of the Secretary of the Commission 82/06/28 DIRKS.W.J Office of the Executive Director for Operations ip 22881 202 24X Fiche 50-000.83/12/14.8402160003

- --8402160300 Discusses SECY-83-33 re approval of proposed license to export high enriched U to Canada CHILK.8 J Office of the Secretary of the Commission 83/02/07 DIRCKS,W J Office of the Executive Director for Operations, ip 22281 263 24X Fiche 50-000,83/12/14,8402160003
- --B4021603BB Discusses SECY-B3-164 re approval of proposed license to export low enriched V to Norway CHILK.S J Office of the Secretary of the Commission B3/05/17 DIRCKS.W Office of the Executive Director for Operations 1p 222B1 285 24X Fiche 50-000, B3/12/14, B402160003
- --8402160084 Discusses SECY-81-383 re proposed license to export natural U to EURATOM countries
 CHILK.S J Office of the Secretary of the Commission 861-303.
 81/11/03 DIRCKS.W J Office of the Executive Director for Operations 1p 22281 121 24X Fiche 50-000.83/12/14.8402160003
- 840217-0084 Amend 3 to export license, extending expiration date to 891231 & reflecting change in ultimate consignee address PETERSON, N R Assistant Director for Export/Import & International Safeguards MMH-449 84/02/20 ip 22312 341
- 8402170270 Application for temporary license to export 30,000 Ci matt.
 PAISLEY, E J Baunders-Roe Developments, Ltd NRC/607 84/01/31
 HEMBY, E NRC No Detailed Affiliation Given 1p 22313 234
- 8402170342 Application to amend export license, extending expiration date to 891231
 HERBCH M M Hestinghouse Electric Corp MMH-449 84/01/26
 ZIMMERMAN, J V Assistant Director for Export/Import & International Bafeguards ip 22313 190
- B402210034 Application for license to export 986 kg U.as U hexafluoride to Japan FOSTER C M Ediow International Co KLK-22 84/01/27 ip. 20203 312
- 8402220616 Amend 2 to Mitsui Air Intl. Inc export license, increasing value of equipment to be exported ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/02/15 tp 22363 089
- 8402220620 Application for license to export 6.300 g U dioxide, in Fore of powder & pellets, to United Kingdom
 HERSCH, M Westinghouse Electric Corp MMH-456 84/02/10 ip
- B402220693 Application for license to export three BF3 proportional counters to Italy
 HEETHER.W.H. Westinghouse Electric Corp. ZE 40193 84/02/07 [p.
- 8402220626 Amend 2 to Mitsubishi Intl Corp export license, authorizing addl consignees to receive miscellaneous specially designed or prepared reactor parts & components ZIMMERMAN, J V Assistant Director for Export/Import & International Bafoguards 84/02/15 2pp 22344 361
- 8402220631 Amend 2 to GE export license, extending expiration date to 870331 ZIMHERMAN, J V Assistant Director for Export/Import & International Safeguards 84/02/14 lp 22346-360
- 8402220635 Ltr of assurance re export of 14 030 kg U-235, contained in 15 038 kg U-to Denmark DUBGIS, D European Communities, Commission of TNP 421. 84/02/03 RAYMOND, J Energy, Dept of 1p 22346 359
- 8402220640 Application to amend licenses to export, increasing quantities of U & U-235, to Japan YAMARA, K Nissho lwai American Corp MPD-1821 84/02/01 MDORE, N Assistant Director for Export/Import & International Bafeguards 700. 28363 095
- 8402230015 Ltr of assurance re export of matl to South Korea. LEE, G B Korea, Republic of (Bouth Korea) 83/12/28, RAYMOND. J F Energy, Dept of 1p 22379 351
- 8402230164 License for Hestinghouse to export 200 g U-235, contained in 5,600 g U, to United Kingdom.
 ZIMMERMAN, J V Assistant Director for Export/Import & International Bafeguards MMH-436 84/02/21 2pp 22379; 200
- 8402230165 License for Westinghouse to Export two power range detector assemblies: Model 23686; to Sweden ZIMMERMAN, JV Assistant Director for Export/Import & Internetiones Bafeguards ZE20694 84/02/14 ip 22379*179

- B402230318 Discusses Westinghouse application for license to export SNM to United Kingdom License issued w/o customary 15-day waiting period IMMERMAN.J V Assistant Director for Export/Import & International Safeguards 84/02/14 Assistant Director for Export/Import & International Safeguards 1p 22371 223
- BIO2230349 Discusses Westinghouse 840201 application to export two pour range detector assemblies to Sweden License issued w/o normal 15-day waiting period IPMERNAN, J V Assistant Director for Export/Import & International 8ifeguards 84/02/14 Assistant Director for Export/Import & International Sufeguards 1p 22376 251
- B402230385 License for Nuclear Metals, Inc to export 380 kg depleted U to Canada 21MERMAN, J. V Assistant Director for Export/Import & International Safeguards 84/02/15 1p 22376 169
- 6402230397 License for Exxon Nuclear Co.Inc to export 1 mg Cf-252 to
- #Bat Germany
 IIMERMAN.J.V Assistant Director for Export/Import & International
 Bafeguards 84/02/15 1p 22376 163
- 8402240356 Forwards application for export license for minor nuclear export. Ltr of assurance required M/o encl INTERMAN, J V. Assistant Director for Export/Import & International Bafeguards 84/02/13. RAYMOND, J Energy, Dept of 1p 22930 1456
- --8402240360 Application for license to export U oxide powder, containing 6.600 g U, to Belgium + Hestinghouse Electric Corp MMH-454 84/01/31 ip 22380: 147.

- 8402270072 Final response to FOIA request for Commissioner voting & attendance records from 810401 to present Forwards documents listed on App A Documents also available in PDR FELTON, J M Division of Rules and Records 83/12/22 KAMENAR, P D Washington Legal Foundation 3pp 22410 109
- ---8402270107 Discusses SECY-81-397 re executive branch response on proposed export of tritium gas to Israel CHILK, 5 J Office of the Secretary of the Commission SBI-397 BI/07/24 DIRCKS, WJ Office of the Executive Director for Operations Ip 22410 164 581-397
- --8402270133 Discusses SECY-81-385 re approval of proposed license & amends to export low enriched U to Spain
 HOYLE, J C Office of the Secretary of the Commission 81/08/14
 DIRCKS.W J Office of the Executive Director for Operations ip
- --8402270147 Discusses SECY-81-430 re approval of proposed license to export high enriched U to Federal Republic of Germany CHILK-S J Office of the Secretary of the Commission S81-430 B170703 DIRCKS W J Deffice of the Executive Director for Operations 1p 22410 187
- --8402270141 Discusses SECY-81-462 re approval of proposed license to export high enriched U to Swaden CHILM.S J Office of the Secretary of the Commission 81/08/25 DIRCKS.N J Office of the Executive Director for Operations 1p 22410 175
- 8402270017 Application to amend license to import, extending expiration WILSON, D General Clectric Co DDW-19-84 84/02/06 WRI Office of International Programs, Director 1p 22497 325 HRIGHT, B L

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUS-JECT CATEGORY
MOST M M	8402280180	50-287 G	ALEXICH, M P	8402060373×	50-315 Q	AUSTIN M A	8402230147*	70-364
AMODT, M. M.	8402220156	50-289 G	ALEXICH, M P	8402070124	50-315 P		8402020271	50-250 G
AHODT, N O	8402290079	50-289 G	ALEXICH, M P	8402140122	50-315 F	AXELRAD, J		
AMODT, N. O						AXELRAD, J	8402030384	IFE
AHODI, N O	8402290080*		ALEXICH, M P	8402220474*	50-315 Q	AXELRAD, J	8402140077	40-279
BEL. 9 F	6402010450	XPORTLIC	ALEXICH, M P	B402290192	50-315 Q	AXELRAD, J	8402170165	40-6920
(SEL, X H	8402210013	NUREG	ALLEMAN, S A	B402070263*	50-382 F	AXELRAD, J.	8402280074*	FOIA
BOUREZK, J	8402080115*	40-1341	ALLEMAN, 8 A	8402090267*	50-382 F	AXELRAD, J A	8402030086	50-344 O
BRAHAM, W B	8402220057	50-416 \$	ALLEN, G W	8402130403	PR	AXELRAD, J. A	8402070522	50-416 G
MAH, H J	8402070036#	FOIA	ALLEN, J H	8402010448*	MARTE MOT	AXELRAD, J. A	8402230364	50-373 G
MAN, W J	8402090046*	FOIA	ALLEN, J R	8402160522*	50-424 C	AXELRAD, J A	8402280739	50-324 G
	8402070049*	FOIA	ALLEN, M T	8402030359	50-325 8	AXELSON W L	B402060006	50-341 G
U MAMAN J	8402270308*	FOIA	ALLEN, M T	B402030482	50-325 8		B402130453	50-331 F
DAM: H J						AXELBON N L		
UAH, H J	8402270311*	FOIA	ALLEN, M T	8402140005	50-025 9	AXELBON, W L	8402140454	50-266 Q
IDAMS, L. C	8402140453	50~424 I	ALLEN, R E.	8402280495	REGGD	AXELBON, W.L.	B402150284	50-35B B
IDATO, M	6402070020	FOIA	ALLEN, R R	8402030309	B, B1E-06	AXELGON, W L.	6402150321	50-315 F
(DENBAM) E	8402090598	50-390 A	ALLEN, R R	8402080349	50-317 B	AXELSON, W L	8402150334	50-315 F
DENSAM, E G	8402010243	50-413 F	ALLING, M E	84020905B1*	71~512	AXELSON, H. L.	8402220083	50-255 F
IDENSAM E G	8402070526	50-424 A	AMORUSO, A P	8402020125	50-329 H	AXELSON, W. L.	8402220303	50-346 F
IDENSAM E G	8402130561	50-369 P	AMORUSO, A P	8402020297	50-329 A	AXELSON, W L	B402220312	50-274 Q
ADENSAM E G	8402130564*	50-367 P	AMORUBO, A P	8402060365	50-329 A	AXELSON, W. L.	8402220544	50-266 F
ADENSAM, E. G.	8402130571*	50-369 P	AMY, Q. O	B402030436*	70-371	AXELBON: W L	8402270413	50-454 Q
	B402140008	50-395 F	ANANDAPPA, A	8402150233	50-207 8	AXELSON, W. L.	8402270440	50-463 0
ADENBAM, E. 9		50-424 A	ANDERSEN, M W	6402030244	50-331 8	BACHMAN, R. O	8402140202	50-155 G
ADENSAM, E. Q	8402140012	50-369 F	ANDERSON, C	8402080336*	50-423 G		8402280317*	50~170 C
ADENSAM, E G	B402140527					BACHMAN, R. G.		50-175 G
ADENBAM, E. G	8402160601	50-413 A	ANDERSON.C D	8402170088*	50-10 0	BACHMANN, R. C.	6402020024	90-199 A
ADENSAM, E. O	8402160642	50-390 F	ANDERSON, C J	8402160377*	50-352 0	BACHMANN, R. Q.	8402020210	50-261 0
ADENS'AM, E G	8402170073	50-375 P	ANDERSON, C J	8402290316*	50-443 G	BACHMANN, R. C.	8402280325*	50-170 0
ADENSAM, E Q	8402170075*	50-395 P	ANDERSON.H K	B402100440	State Prog	BACKES, C J	8402030082*	CONTRACT
ADENSAM, E. G	8402230029	50-424 A	ANDERSON, L E	8402130109#	FOIA	BACKUS, R A	8402140151	50-443 Q
ADENSAM, E. G	8402230075*	50-424 A	ANDERBON, R B	6402280408#	70-2077	BACKUS, R. A.	8402140151	50-443 0
AERNI, D L	8402140566	XPORTL1C	ANDERSON, S I	8402170226	FOIA	BACKUS, R A	8402220110	50-443 0
AGEE, J.R	8402220281*	GA777	ANDERSON, B L	8402010142×	50-327 P	BACKUS, R. A	8402220110	50-443 Q
AGEE, J R	8402220534*	QA777	ANDOGNINI, G C	8402150455	State Prog	BAER, R E	8402030221*	50-313 9
AHEARNE, J	B402080049*	FOIA	ANDREWS, J J	8402090070*	FOIA	BAER R E	8402030238*	50-29B 0
AMEARNE, J	8402080051*	FOIA	ANDROBIK, R	8402020304	50-318 8	BAER, R E	8402220261*	50-298 G
		ES 400 Y	AND 11 D	B402140320*	50-413 Q	54FD 0 1	8402070441*	FOIA
AHEARNE J F	8402090155*	50-498 T	ANG. W P		50-413 G 50-317 G	BAERIR L	8402270218	ILE I
AMEARNE J F.	8402070198*	50~320 U	ARCHITZEL,R E	8402240139*		BAER R L		ISE
AHEARNE, JF	8402240160*	50-3B2 G	ARIASIJ	8402130230	50-250 S 50-250 S	BAER, R. L	8402290349	PR
ahernb. p.	8402220200*	50-309 G	ARIAB, J	8402270414		BAGBY, L. A	8402080177	
AMMED, N	8402270253*	50-206 P	ARLDTTO, O A	8402070413#	FUIA	BAOCHI, O	8309240011*	50-171 P
ANRENB, P	8402220214*	50-309 0	ARLOTTO, O A	B402070426*	FOIA	BAGCHI, Q	8310030612*	FOIA
AHRENS, P	8402220230*	50-309 Q	ARLDTTO, Q A	B402130054*	50~295 P	BAIETTI, A L.	8402170293	PR
ALATORNE, R	8402010078	50-275 U	ASH, E B	B402100314	HASTE MOT	BAILEY, R. J.	8402020356*	50-293 G
ALBRECHT, R H	8402140380*	70-1151	ASH, E B.	8402170294	WASTE MOT	BAIR: O	8402170255	50-344 8
ALERIOHT, R H	8402150243*	50~241 G	ASHLEY, Q K	8402070251*	50-352 0	BAIR, G G.	8402130289	50-344 B
					-			-0.044 5
ALTRICHT, R H	8402280376*	50-261 0	Veseratine 1 K	B308090022*	50-352 U	DAIR. Q Q	8402130340	50-344 \$
ALDEN, W H	B402030432	50-277 R	ASSELSTINE, J K	B402080044*	FOIA	BAIR, 9 G	8402290122	50-344 8
ALDEN, H M	8402170143	50-277 R	ASSELSTINE, J K	B402170024#	50-269 T	DAIRD: J B	8402010132*	50-313 0
ALDRICH, D C.	8402270189*	FOIA	ATTERIDGE, D G	B402270506#	FOIA	BAIRD, J B	8402140354*	50-445 Q
ALDRICH, D C	8402270244*	FOIA	AVERBACH, C	8303280015*	50-289 P	BAIRD, J B.	8402160419*	50-285 G
ALESSELT A	8402130443	50-341 8	AUERBACH, M	8402010378*	50-275 0	BAIRD, J B.	8402280534*	50-445 G
ALEXANDER, D. H	8402240373	NUREO	AULUCK, R	8111230250#	50-397 A	BAISDEN, L	8402210085	CONTRACT
ALEXANDER, S. B.		PROJ	AUSTIN, Q.	8402130437	50-295 R	BAJWA, S B	6204290406*	50-289 P
	8402130438*		AUSTIN, M. A.	8402130310	70~135	DAKER, L	8402130036*	FOIA
ALEXICH, M.P.	8402030210	50-315 P	AUSTIN, M. A.	8402220450*	70-364	BAKER, L	8402130073*	FOIA
ALEXICH, M. P.	8402030472	50~315 P	WASTRILLY	~~~~~~~~~~	A M M M T	Dilleriti F		

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BAKER.N D BAKER.W E BAKER.W E BAKER.W E DALL.D &	8402240256* 8402100170* 8402100193* 8402170126* 8402210073	CONTRACT 50-445 T 50-445 T 50-445 G NUREG	DASSO,L F BASBO,L F BATEMAN,W H BAUBLITZ,J E BAUER,E G	8402080230 8402280144 8402150170* 8402100318 8402150548*	50-318 8 50-317 8 50-354 Q Waste Mgt 70-2988	BELL, N BELL, N BELL, N BELL, N	8402140483 8402220127 8402220139 8402220142+ 8402230441	FOIA 50-220 P 50-397 G 50-397 G FOIA
BALL,S J BALL,W G BALL,W G BALLARD,W W BANDY,R	8402040457 8402020155 8402030253 8402010308 8303280024*	NUREO WASTE MOT WASTE MOT WASTE MOT 50-289 P	BAUMANN.B L BAUSER.D B BAUSER.D B BAUSER.D B BAUSER.D B	8402170304 8402020227 8402020227 8402020230* 8402020230*	NUREG 50-400 G 50-400 G 50-400 G 50-400 G	BELL, N BELL, N BELL, N BELL, N	8402240079 8402240304 8402270295 8402270500 8402270585	50-480 Q 50-287 P 50-508 A FOIA FOIA
DANGERTER, D H BANHAUER, W K BARANOW, S W BARANOW, S W BARANOW, S W	8402140605 8402220172 8402070165* 8402070169* 8402070454*	XPORTL1C 50~302 S 50~329 G 50~329 G 50~329 G	BAUSER.D B. BAUSER.D B BAUSER.D B BAUSER.D B BAUSER.D B	8402030289 8402030289 8402070239 8402070239 8402070130	50-289 0 50-289 0 50-289 0 50-289 0 50-289 0	BELL, N BELL, N BELL, S W BELSER, A L	8402280326 8402280338 8402280458 8402090282# 8402280463	50-460 ' Q 50-250
DARBEE,R J BARI,R A BARKHURST,R P BARKHURST,R P BARLETYA,R E	8402160377 8402060484 8402090263* 8402090267* 8402210026	50~397 8 NUREC 50~382 F 50~382 F NUREC	BAUSER.D B BAXTER.D E BAXTER.D E BAXTER.D E BAXTER.D E	8402090130 8402090310 8402090316 8402090324 8402100421	50-289 0 50-259 P 50-261 P 50-261 P 50-259 8	BELTRACCHI, L BELTRACCHI, L BELTRACCHI, L BELTRACCHI, L BELTRACCHI, L	8208230400* 8211010467* 8306150045* 8402010502 8402130643*	Toprep Toprep Toprep MISC Toprep
BARNES, C BARNES, C BARNES, C BARNES, I BARNES, I	8402240184 8402240189 8402270346 8402070266* 8402100141*	70—1193 40—2061 70—925 Qa999 Ga999	BAXTER, T A	6402070197 8402070197 6402070201* 8402070201* 8402070047	50-482	BELTRACCHI, L BEMIS, PR BEMIS, PR BEMIS, PR BEMIS, PR	8402150122 8402020217# 8402140450# 8402150273# 8402280002#	TOPAEP 50-261 g 50-400 g 50-261 g 50-261 g
Darnes, I Barnes, I Barnes, I Barnes, I Barnes, P	8402130518* 8402130524* 8402130186* 8402220381* 8402140205	50-322 G 50-322 G GA797 GA797 50-237 F	BAXTER.T A BAXIER.T A BAXTER.T A BAXTER.T A BAXTER.T A	8402070067 8402150217 8402150217 8402150217 8402160201	50-400 0 50-400 0 50-400 0 50-400 0 50-400 0	BEMIB, PR BEMIB, PR. BENAROYA, V BENAROYA, V BENAROYA, V	8402280081* 8402280300* 8208070285* 8208250400* 8304270380*	50-324 q 50-62 q 50-889 p 50-889 p 50-889 p
Barnes, P L Barnes, P L Barnes, P L Darnes, R P Barnett, B J	8402150344 8402170134 8402240120 8402170005 8402100269	50-254 Q 30-454 Q 50-454 A 50-400 S 50-483 M	BAXTER,T A BAXTER,T A BAXTER,T A BAXTER,T A BAXTER,T A	8402160201 8402160207* 8402160207* 8402170103 8402170103	50-400 Q 50-400 Q 50-400 Q 50-400 Q 50-400 Q	DENDER,M BENDER,M BENEDICT,R A BENEDICT,R A, BENKERT,J W	8402070504 8402070504 7703230241* 8402070240* 8402070251*	ACRS ACRS 50-382 A 50-352 Q
BARR, K BARR, K BARR, K P DARR, K, P DARR, K P	8402020169# 8402070359# 8402140154# 8402140165# 8402140380#	50-320 G 50-320 G 50-321 G 50-348 G 70-1151	BAXTER,T A BAXTER,T A BAXTER,T A BAXTER,T A. BAXTER,T A	8402210207 8402210207 8402280340 8402280340 8402280362	50-287 0 50-287 0 50-287 0 50-287 0 50-400 0	BENNEDETTO:A R BENNETT:J W, BENBON:J J BENTBEN:L BERA:M J	8402280494 8402010229* 8402100378* 8402030489* 8402150375	PRM HABTE HOT 50-275 P 50-498 U GA999
BARR, K P Barr, K P Barr, K P, Barr, K P Barr, K P	8402150017* 8402150227* 8402150243* 8402150384* 8402280138*	50-269	BAYTER, T.A. BAYNE, J.P. BAYNE, J.P. BAYNE, J.P. BAYNE, J.P.	8402280362 8308050317* 8402070158 8402080415 8402130234	50-400 G 50-247 F 50-333 P 50-333 P 50-333 F	BERGAN, G. W BERGERUN, P. A BERGIN, J. M BERICK, D. M BERLIN, M. D.	8402030250 8402240143* 8402070305 8402030186 8402130191	50-237 B 50-23 P 50-336 B HASTE HOT 50-10 F
ARRIK P JARRIK P JARRETTIE M JARRETTIL JARRETTIL H	8402280374* 8402280527* 8402280375 8402220103 8402210375	50-261 0 50-280 0 50-382 0 50-380 R	H C. SANABE A C. SANABE A C. SANABE A C. SANABE A C. SANABE B C. S	8402130268 8402130445* 8402130533* 8402130184 8402160336	50-393 V 50-393 G 50-286 F 50-333 P 50-393 Q	Berlinger, C Berlinger, C. M Bernabei, L Bernabei, L. Bernabei, L.	8402220245 8401270103* 8402080026 8402130005 8402130108*	50-322 9 TOPAEP 50-528 8 50-528 A
ARRETT, L H ARRETT, L, H ARRETT, L H ARRETT, L H ARRETT, L H	8402020164 8402020198 8402070354 8402090271 8402140487	50-320	AYNE, J.P PAYNE, J.P J.SAYNE, J.P J.SAYNE, J.P J.SAYNE, J.P	8402210107 8402220180 8402230170 8402230176* 8402240094	50-333 P 50-266 P 50-266 P 50-266 P 50-333 P	BERNABEI, L. BERNABEI, L. BERNABEI, L BERNABEI, L. BERNARD, H	8402170457 8402240148 8402270550 8402270555 8402270482	FDIA 50-362 0 50-528 0 50-528 0 50-172 P
ARRETT, L H ARRETT, L H ARRETT, L H ARTH, C A ARTH, C A	8402170244 8402170491 8402270462 8402010190 8402010191	50-320 R 50-320 P 50-320 R 50-400 Q 50-400 G	Bazzani, C B Beach, A B. Beach, G Beahm, D. M Beal, B. K	8402100391* 8402140345* 8402170448 8402090310 8402270415*	CONTRACT 50-410 G 40-6622 50-259 P FUIA	BERNARD, J BERNERO, R. M. BERNERO, R. M BERNERO, R. M BERNERO, R. M	8402290415 8312190179# 8402130008# 8402130017# 8402130020#	FOIA FOIA FOIA FOIA
ARTH.C A ARTH.C A ARTH.C A ARTH.C.A ARTH.C A	8402070031 8402220234 8402220275 8402270034 8402270060#	50-400 G 50-400 G 50-400 G 50-400 G 50-400 G	BEAN, R. M BEAVER, J R BECK, G. P BECKER, B D BECKER, B D	8402010302 8402220264 8402150232 8402280471 8402280471	NUREG 50-320 F 50-151 R 50-454 G 50-454 G	BERNERO, R. M. BERNERO, R. M. BERNERO, R. M BERNERO, R. M BERNHOFT, B. L	8402130031* 8402270011* 8402270013* 8402270016* 8402030374	FDIA FDIA FDIA FDIA 50~305 8
RTH, C.A RTH, C.A RTH, C.A BDEXAB, D.L. BKIN, J.L	8402270065* 8402290097 8402290099 8303310317 8402230120*	50-400 0 50-400 0 50-400 0 ACRS 50-354 A	Beckham, J 8 Beckham, J T. Beckham, J. T Beckham, J. T	8402090013* 8402090040* 8402140436 8402150409 8402820514	CONTRACT CONTRACT 50-321 P 50-366 G 50-321 P	BERNREUTER, D L. BERREDA, J. BESSETTE, D. BESSETTE, D. BESBETTE, D	8402210021 8402090419* 8402270297* 8402270305* 8402270331*	50-295 P COMMISSION 50-327 0 50-327 D FUIA
BRIN, J. L Brin, J. L Brin, R. P. Brin, R. P. Brin, R. P.	8402230124* 8402270078* 8402030271* 8402170338 8402270180	50-354 A 50-341 A 50-206 G 50-361 K 50-206 P	DECKHAM, J.T. BECKSTED, W.F. BEEDLOW, P.A. BEER, J.L. BEINECKE, P.J.	8402280405 8402010253 8402100287* 8402230141* 8402170204	50-321 0 50-322 8 MASTE MOT 50-155 0 50-304 8	BESSEY, R BETHKE, Q. W BETTENHAUSEN, L BETTENHAUSEN, L BETTENHAUSEN, L	8402070295# 8402160356# 8402020280# 8402080333# 8402080375#	0A797 50-445 0 50-368 d 50-317 0 50-386 0
ibett. B ibin. N ibin. N ibin. N	8402100418 8402090257* 8402090265* 8402090322* 8402090331*	50-269 P FOIA FOIA FOIA FOIA	BELANGER, J L. BELCHER, R L. BELISLE, G A BELUWAB, T E BELL, I	8402270416* 8402060450* 8402280255* 8402280014 8402140405	50-454 @ 50-166 V 50-250 @ NUREG State Prog	BETTENHAUSEN, L BETTENHAUBEN, L BETTENHAUSEN, L. BETTENHAUSEN, L. BEVAN, R B.	8402090374* 8402160315* 8402160481* 8402290247* 8402100324	59-317 9 50-443 9 50-388 9 50-352 9 50-265 P
91N, N 81N, N 91N, N 91N, N	8402070333* 8402070377* 8402070382* 8402270577* 8402080351	FDIA FOIA FOIA FOIA 50-317 S	BELL, J BELL, J. M BELL, M. J BELL, N.	8402020167* 8402070357* 8402270578* 8402030102 8402080132	50-320 @ 50-320 @ FDIA WASTE MOT 50-460 @	BEVILL,M, BEVILL,M BIAN,B.H. BIBB,H E, BICEHOUSE,H	8402070414 8402150052 8402060343 8402140303# 8402080393#	71-9160 71-9161 NURE9 50-335 0 80-333 0

AUTHOR	ACCESSION WUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
1:15HOUSE H 8:(5HOUSE H 9:(5HOUSE H J 1:1AFORD A L 8:(5KFORD A L	8402150328* 8402160333* 8402150245* 8402010373 8402270213	50-220 G 50-277 Q 50-271 G NUREG NUREG	BOLIN, C W BOMBERGER, C BONNES, G EQNNIE, T M BOOKER, J E	8402220575# 8402270253# 8402010362# 8402030354 8401230407	90-413 E 90-206 P CONTRACT PR 50-45B B	BRADY, JA BRANCH, MW BRANDENBURG, B BRANDT, C Y BRANNOCK, E A	8402220264 8402280161* 8402090154 8402100170* 8402160685*	50-320 F 50-438 G 50-247 G 50-445 T CONTRACT
1:CAMITAL BICKMITAL BICKMITAL BICKMITAL JICHMITAL	8205060001* 8402080037* 8402080103* 8402090171* 8402270294*	FOIA FOIA 50~498 U 50-498 G FOIA	DODXEK') E BODXEK') E BODXEK') E BODXEK') E	8401240381 8402030174 8402040404 8402070342 8402080125	50-458 8 50-458 A 50-458 8 50-458 E 50-458 E	BRAUMULLER, A M BRAUN, J G BRAUN, J G BRAY, M A BREECE, G A	8402100190* 8402020031 8402080050* 8402030099 8402140520*	50-445 G HASTE MOT 40-1341 NUREG 50-424 G
CAMPT.E IDINGER.OH IDINGER.OH IDINGER.OH IDINGER.OH	8402270384* 8402060553* 8402080010 8402160476 8403290377	FOIA 70-2955 70-1151 70-820 70-1151	BOOKER') E BOOKER') E BOOKER') E BOOKER') E	B402090209 B402140017 B402140056 B402140109 B40214012B	50-458 F 50-458 8 50-458 6 50-458 8 50-458 8	BRENIZER, J S DRENNER, L BRENNER, L BRENNER, L BRENNER, L	8402280275* 8402020217 8402060071 8402220067 8402230033	50-352 0 50-352 0 50-352 0
I:ELAWSKI, A P 1(ELAWSKI, A P 1(SHOP, R W 1(SHOP, R W	8402060187 8402040187 8402100239 8402100239 8402100239	30-454 G 50-454 G 50-423 A 50-423 A 50-245 P	BOOKER'N E BOOKER'N E BOOKER'N E BOOKER'N E	8402140305 8402140349 8402140326 8402140415 8402170083	50-458 8 50-458 9 50-458 A 50-458 A 50-458 B	BRENNER, L BRENNER, L DRENNER, L BRESEMANN, R W BRESELER, M N	840223036 8402290071 8402290090 8402280410 8402100193*	50-352 0 50-352 0 50-352 0 50-10 I 50-445 T
1:S-OP.R W 1:S-OP.R.W 1:S-OP.R.W 1:S-OP.R W 1:S-OP.R W	8402160385 8402160424 8402220486 8402220486 6402080047*	50-245 P 50-334 P 50-423 A 50-423 A 50-528 S	BOOKER, J E BOOKER, J E BOOKER, J E BOOKER, J E	8402170115 8402170169 8402170256 8402170261 8402210104	50-458 F 50-458 S 50-458 S 50-458 S 30-458 A	BREY, H L BREY, H L BRICH, R BRIGGS, L DRIGGS, L	8402010151 8402170048 8402080063* 8402160315* 8402270247*	50-267 F 50-267 O FOLA 50-443 O 50-352 O
) 640p. t. 1840p. t. 650p. t. W 1840p. t. W	8402150206 8402150213 8402150360 8402030257 8402030263	50~530 8 50~344 8 50~344 8 50~397 9 50~206 0	BOOKER, J E BOOKER, J E BOOKER, J E BOOKER, J E	8402210112 8402210204 8402220393 8402220490 8402230080	50-458 E 50-458 A 50-458 S 50-458 A 50-458 A	BRIGHT.0 D BRIGHT.0 D BRIGHT.0 D BRIGHT.0 D BRINKMAN,D S	8402030204 8402280377 8402280450 8402270101 8402070437*	50-440
(1540P.T.W (1540P.T.H (1540P.T.H (1540P.T.H (1540P.T.H	8402030375 8402060404 8402080064* 8402140124 8402140279	50-275	BODKER, J E BODKER, J E BODKER, J E BODKER, J, E	8402280153 8402280230 8402280371 8402280484 8402290089	50-458 S 50-458 S 50-458 S 50-458 S 50-458 E	BRDADWATER, R BROCARD, D N BROMBERG, B J BROMBERG, B J BRONE, J C	8402100407 8402010345 8402210013 8402230292 8402030460	TOPREP NUREG NUREG CONTRACT 50-286 8
II SHOP, T. W. II SHOP, T. W II SSETT, P LACK, K. LACK, K. H	8402140466 8402280245 8402080290* 8402140497* 8402290170*	50~275 G 50~206 Q 50~271 G MISC FOIA	BORCHARDT, R BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDENICK, B M	8402240046# 8402070006 8402070033 8402070130 8402140095	50-293	BEONN'B V BEONE'N C BEONE'N C BEONE'N C	8402070076# 8402070172# 8402210058 8402010179# 8402160305	50-286 G 50-286 G 50-286 R 50-219 P 50-528 F
eack, X. H Lackman, H. S Lair, J. Lair, J. Lace, E. L.	8402270171* 8402030097 8402280507 8402220437* 8402130185	FOIA NUREO PRM 50-445 Q 50-289 Q	BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDENICK, B M BORNES, R P	8402220215 8402220238 8402220262* 8402220285 8402010143*	50-322	DROWN, C H BROWN, C R BROWN, J M BROWN, M W DROWN, R S	8402130284* 8402100170* 8402090368* 8402130542* 8402270167*	50-263 G 50-445 G FOIA CONTRACT FOIA
ARE, E. L. ARE, E. L. ARE, E. L. ARE, E. L. ARE, E. L.	8402130185 8402150150 8402150150 8402230076 8402230076	50-289 Q 50-424 Q 50-424 Q 50-289 Q 50-289 Q	BORNES, R P BORNES, R P BORNES, R P BORNES, R P BOTHMAN, J E.	8402010173* 8402170196 8402170279 8402170317 8402060357	0A979 50-336 8 50-400 8 50-338 8 TOPREP	BROWN, W.E. BROWNELL, R.B BROWNELL, R.B BROWNING, R.E BROWNING, R.E	8402130159* 8402070376* 8402070410* 8402010281 8402030032	50-324 F 50-312 F 50-312 F WASTE MOT WASTE MOT
AKE, J. J AKE, J. J. AKE, J. J. AKE, J. J. AKE, J. J.	8402140274* 8402140320* 8402140338* 8402140437* 8402140437*	50-413 G 50-413 G 50-257 G 50-395 G 50-259 G	BOUKNIGHT, R J BOUKNIGHT, R J BOUKNIA, A BOURNIA, A	8402070210 8402140001 8402010378* 8402070167* 8402070175*	50-395 B 50-395 B 50-275 Q 50-373 A 50-358 A	BROWNLEE, V BROWNE, R J BRUBAKER, H P BRUCHMANN, G W	8402280942* 8402140167* 8402240233 8402070340 8402080191	50~269 G 50~269 G NUREG 50~352 D PR
AKE, J. J AKE, J. J. AKCHARD, B AYCHARD, T. YTT, M.	8402140512* 8402150315* 8402220497 8402170223 8402010140	50-424 G 50-419 G 50-352 D 50-336 8 50-247 R	DDYACK, B BOYD, D BOYD, D C BOYD, D C. BOYD, D C	6402100418 6402280372 8402170313* 8402290203* 8402290204*	50-269 P 50-155 B 50-315 G 50-255 G	DRUEMHER, B M BRUNGARDT, R DRUNGARDT, R BRUNNER, J E BRUNNER, J E	8402270506* 8402280355 8402280474 8402070101* 8402070101*	FOIA 50-298 8 50-298 9 50-327 A 50-329 A
IND. A A. XH. P. B. XH. P. B. XH. P. B. XH. P. B.	8402270378 8402010210 8402020221 8402070121 8402070141	50-315 S 50-445 G 50-445 Q 50-445 Q 50-445 Q	BOYD, R 8 BOYER, R E. BOYER, V 8 BOYER, V 8 BOYER, V 8	8402020041* 6402220590 6402020288* 8402030270* 6402030275*	50~330 A 50~206 B 50~352 A 50~352 0 50~352 G	BRUSKE, 8 J BRUSKE, 8 J BRUSKE, 8 J BRYAN, M G	8402070310 8402070316 8402070324 8402100421 8402160419*	50-259 P 50-261 P 50-261 P 50-259 B 50-265 Q
кн. р. в. кн. р. в. кн. р. в. sson. J. N. s. l. A.	8402100113* 8402140176 8402240101 8402220170 8402150120	50-445 Q 50-445 Q 50-440 Q 40-8452 50-375 B	BOYER, V B BOYER, V B BOYER, V B BOYER, V B BOYER, V B	8402030277* 8402070312* 8402080022 8402220034 8402220118*	50-352	DRYAN, R H BRYAN, S E BRYAN, S E BRYANT, J ERYANT, J	8402150564 8004250213* 800502032* 8402140167* 8402280542*	HASTE MOT FOIA FOIA 50-269 G 50-249 G
HM, D. HENTHAL, H. S ROMAN, J. R. SE, J. T. SE, J. T.	8402270207 8402170517 8402270446* 8402280077* 8402280085*	NUREG NUREG 50-498 G FDIA FOIA	Bracken, k w Bradbury, r b Bradford, L Bradford, L Bradford, L	8402150001 8401050255 8402220260 8402220357 8402230087	71-5607 PR 50-289 G 50-289 G 50-289 G	BUCCI.D BUCHANAN.C.R BUCHANAN.J.A BUCHERT.K.P BUCHHOLZ.R H	8402270425* 8402270591* 8402170311 8402070251* 8402080040*	FDIA FDIA NUREO 50-352 0 50-245 0
XEN. O. a.L. S. a.L. S. b.H. P. NDERI M. A.	8402220097 6402140201* 6402140212* 6402210021 6402080032	40-8684 04979 04979 50-295 P 50-269 P	Bradford, P A Bradley, E J Bradley, E J Bradley, E J Bradley, E J.	6402140285 6402020277 8402020300 8402150547 6402150548*	50-309 H 50-352 A 50-352 E 70-2988 70-2988	BUCKLEB, R. BUCKLES, R. BUCKLEY, B. C. BUCKLEY, B. C. BUDNITZ, R	8402230407 8402240198 8402260529 8402240001 8402010342*	FDIA FDIA 50-400 A 50-400 A CONTRACT 50-302 S
N. C. N. C. H. N. C. H. N. C. H. N. C. W.	8402220563* 8402220542* 8402220552* 8402220573* 8402220573*	50-413 E 50-413 E 50-413 E 50-413 E 50-413 E	BRADLEY, E J. BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J.	8402270117 8402210145 8402210233 8402210335 8402270316	50-352 A 50-352 E 50-277 J 50-277 J 50-352 K	BUFE, J L. BUHL, A R BUHL, T BUHR, B. W BULLOCK, S V	8402030409 8402130057* 8402080225 8402090370* 8402100156*	50-302 B FDIA PR FOIA 50-244 G

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BUMPUS: S E BUNTING, J D BURCK: L H BURGE: C A BURGER: F J	8402210021 8402030505 8402140516* 8402030332* 8402170269	50-295 P WASTE MOT 50-287 P 50-354 F 50-271 R	CAPHTON.D L CAPHTON.D L CAPHTON.D L CAPHTON.D L CAPHTON.D L GAPHTON.D L	8402080340* 8402080374* 8402090357* 8402140288* 8402140373*	50-320 0 50-387 0 50-387 0 50-213 0 50-213 0	CHENG,C Y CHERNY,F CHEVERTON,R D CHIANGI,N J CHIEN,C T	8209230151* 8402270644* 8402210073 8402150388 8402060245*	50-220 P FGIA NAREG 50-400 S 50-309 P
BURGESS.B L BURGESS.B L BURKE.D J BURKEIT.M BURKLEY.D E	8402020256* 8402270221* 8402280447* 8402100418 8402030187*	50-327 Q 50-327 Q 50-280 Q 50-267 P 50-267 G	CAPHTON,D L CAPHTON,D L Capra,L a Capra,L a Carey,J J	8402240050* 8402240095* 8401040412* 8401040416* 8402100180	50-219 Q 50-277 G GA999 GA999 50-334 P	CHILDRESS,E T CHILK,S J CHILK,S J CHILK,S J	8402080101* 8204050442* 8304040550* 8402010480 8402030037	50-328 A FOIA 50-528 ' A FOIA 50-289 P
BURKLEY.D E BURKLEY.D E BURKLEY.D E	8402030187* 8402090125 8402090125 8402090129* 8402090129*	50-287	CAREY, J J CAREY, J J CARLSDN.E E CARLSDN.R A	8402100437 8402140490 8402220466 8402080435* 8402270296*	State Prog 50-334 0 50-334 0 50-397 A FOIA	CHILK, S. J CHILK, S. J CHILK, S. J CHILK, S. J CHILK, S. J	8402030051 8402030193 8402030527 8402060089 8402060481	50-275 P 50-312 0 100FR 50-275 P 100FR
BURLEY, O BURNBAUM, C BURNETT, P T BURNETT, P T BURNETT, P T	8402080322* 8402040520* 8402140211* 8402140366* 8402280300*	FD1A CONTRACT 50-267 0 50-367 0 30-62 0	CARNILA, 5 T CARPENTER, J H CARPENTER, R CARPENTER, T G CARROW, H	8402150442 8402280443 8402080067* 8402090592* 8402130233	State Prog 40-2061 40-1341 CONTRACT 50-400 G	CHILK, 8, J CHILK, 8, J CHILK, 8, J CHILK, 8, J	8402070045* 8402070122 8402070128 8402070188 8402080066*	50-263 F 50-440 9 50-10 0 50-440 9 FDIA
BURNS, 8 G BURSTEIN, C H BURSTEIN, S BURSTEIN, S BURTON, W	8402210121 8402280448 8402140237 8402140464* 8402270270	50-275 G 50-382 G 50-266 G 50-266 G 50-324 F	CARROW, H CARROW, H CARROW, H CARROW, H CARROW, H	8402130233 8402130238* 8402130238* 8402130266 8402280420	50-400 9 50-400 9 50-400 0 50-400 0 50-400 0	CHILK, B J CHILK, B J CHILK, B J CHILK, B J	8402080107 8402090026 8402090117 8402100102 8402100171	FOIA 50-289 T 50-356 9 50-483 9 50-289 T
BURWELL, 8 B BUSH, M W BUSH, M W BUSH, M W BUSH, M W	8402170033 8402070327 8402080139 8402100140 8402140175	50-445 A 50-352 G 50-352 G 50-352 G 50-352 G	CARTEAUX, P CARTER, H L CARTER, S CARTER, S D CARTER, S D	8402280461 8402230211 8402270376 8402080154 8402270411	50-315 F 50-206 S 50-259 S 50-260 S 50-259 S	CHILK'S A CHICK'S A CHICK'S A CHICK'S A	8402130007 8402130537 8402150195 8402160003 8402160007*	50-528 A 100FR 50-10 & 50-3 P 50-537 A
BOSTIK'Y J BOSH'B H BOSH'W M BOSH'W M	8402210277 8402220351 8402070445 8402070445 8402040484	50-352 0 50-352 0 ACRS ACRS NUREO	CARUSD, M CARUSD, R CARUSD, R CARUSD, R CASADA, M L	8402270644* 8402170061 8402240058 8402280701 8402060478	FDIA 50-204 P TOPREP 50-206 S NUREG	CHILK'S O CHICK'S O CHICK'S O CHICK'S O	8402160008# 8402160012# 8402160015# 8402160019# 8402160022#	F01A 50-382 A F01A 50-322 F F01A
BUSTARD, L D BUTCHER, R C BUTTERWORTH, G BYERS, K R BYRD, R	8402100378* 8402140164* 8402160534* 8402240233 8402130389	50-275 P 50-259 G TOPREP NUREC 50-414 S	CASE,E G CASHIDY,B P CATLOH,R D CATLOH,R D	8402090452* 8402210158* 8402080174 8402030371* 8402030378*	FOIA CONTRACT 50-482 0 50-397 8 50-397 8	CHICK'S O CHICK'S O CHICK'S O CHICK'S O	8402160025# 8402160030# 8402160033# 8402160035# 8402160037#	50-322 A 50-537 A FOIA FOIA
BYRD, R BYRD, R BYRD, R BYRD, R BYRD, R	8402130450 6402140013 8402220119 6402220126 6402220570	50-416 8 50-416 8 50-416 8 50-416 8 50-416 8	CATLOH,R D CATLOH,R D CATLOH,R D CATLOH,R D CATLOH,R D	8402030380* 8402030386* 8402030372* 8402030375* 8402030401*	50-397 8 50-397 8 50-397 8 50-397 8 50-397 8	CHICK'S A CHICK'S A CHICK'S'A CHICK'S'A	8402160041* 8402160043* 8402160047* 8402160049* 8402160052*	FOIA 50-3 P 50-275 P FOIA FOIA
BYRD, R BYRD, R BYRD, R W CACCIAPUTI, R CADMAN, T W	6402270085 6402270323 6402280550 6402240143* 8402060450*	50-416 8 50-416 8 50-416 8 50-29 F 50-166 V	CATTON, I CAULK, O H CEMBER, H CERMAX, J E CERMAK, J E	8402090527 8402090203 8402280500 8402080282* 840208028&*	ACRS FDIA REGGD 50-416 P 50-416 P	CHILK, B J CHILK, B J CHILK, B J CHILK, B J	8402160055* 8402160057* 8402160060* 8402160064* 8402160065*	FOIA FOIA FOIA FOIA FOIA
CAHILL, W J. CAHILL, W J CAIN, J CAIN, J M CALDWELL, D. M	B402090027* 8402140044 8402010006 8402280344 8402270473	50~459 8 50-459 K Waste Mot 50~382 0 Foia	CERNE,A C CHAMBERLAIN,W CHAMBERB,G T CHAN.E I CHAN.E I	8402020127# 8402230089 8402140424 8402070003 8402070004#	50-443	CHILK, B J CHILK, B J CHILK, B, J CHILK, B J,	8402160066* 8402160067* 8402160070* 8402160071* 8402160072*	FOIA FOIA FOIA FOIA 50-275 P
CALKINS.DE CALLAN.LJ CALLAN.LJ CALLAN.LJ CALLENDINE, G	B402100012* 8402220337* 8402220406* B402220396* 8402270341*	FOIA 50-313 G 50-313 G 50-313 G FOIA	CHAN: E I CHANDLER: L, J CHANDLER: L J CHANDLER: L J CHANDLER: L J	8402140004 8310130158 8402010215 8402010220 8402070058	50-482 0 50-275 0 50-275 0 50-275 0 50-275 0	CHILK, B J CHILK, B J CHILK, B J CHILK, B, J	8402160073* 8402160074* 8402160075* 8402160076* 8402160078*	FOIA FOIA FOIA FOIA FOIA
CALBOYAS, C D. CALVERT, M CALVERT, M CALVERT, M S CALVERT, M S	8402010494 8402070130 8402070130 8402100125 8402100125	50-206 I 50-413 G 50-413 G 50-413 G 50-413 G	CHANDLER, L J CHANEY, H D CHANG, K C CHANG, K C CHAPELL, D R	8402140223 8402220248* 8402010322 8402150433 8402270124*	50-275 G 50-285 G WASTE MOT WASTE MOT 50-344 F	CHILK, 8, J, CHILK, 8, J, CHILK, 8 J CHILK, 8 J,	8402160079* 8402160081* 8402160082* 8402160083* 8402160084*	50-287 F FOIA FOIA FOIA FOIA
CAMERON, R E CAMILLI, R. L CAMPBELL, R D CAMPBELL, R M CANDLER, W J	8402080079* 8402150451 8402160460* 8402080361* 8402160479*	40-1341 State Prog 50-329 A 50-443 G 50-424 C	CHARNTEA' 7 8 CHARNTEA' 7 8 CHARNTEA' 7 8 CHARNTEA' 7 E	8402220541* 8402020290 8402080147 8402080201 8402130325	50~324 G TOPREP TOPREP TOPREP TOPREP	CHILK, 8 J CHILK, 8 J CHILK, 8 J CHILK, 8, J	8402160085* 8402160086* 8402160087* 8402160090* 8402160091*	50-275 P FDIA FDIA FDIA 50-275 P
CANDLER, W. J CANDLER, H J CANONICO, D A CANTER, H L CANTER, H L	8402160517* 8402160522* 8402010115 8402140139* 8402140468*	50~424 C 50-424 C NUREQ 50-206 G 50-275 Q	CHASE, L CHASE, L CHASE, L CHASEEMI, M CHAUST, R H	8402010188 8402010229* 8402010269 8402020115 8402220539*	Waste Mot Waste Mot Waste Mot 40-8584 50-413 E	CHILK, B. J CHILK, B. J CHILK, B. J CHILK, B. J. CHILK, S. J.	8402160093* 8402160094* 8402160095* 8402160096* 8402160097*	FOIA PDIA FOIA 50-289 P FOIA
CANTER, H L CANTRELL, F S CANTRELL, F S CANTRELL, F S CANTRELL, F S	8402140471* 8402100187* 8402140136* 8402140164* 8402280417*	50-275 0 50-324 P 50-259 G 50-259 G 50-259 G	CHAUST, R H CHAUST, R H, CHAUST, R, H CHAUST, R, H, CHAUST, R, H,	8402220546* 8402220561* 8402220549* 8402220573* 8402220583*	50-413 E 50-413 E 50-413 E 50-413 E 50-413 E	CHILK, S.J. CHILK, S.J. CHILK, S.J. CHILK, S.J.	8402160098* 8402160099* 8402160102* 8402160103* 8402160104*	FOIA FOIA 50-267 F FOIA 50-443 A
CANTRELL, F 8 CAPHTON, D, L	8402280552* 8402020170* 8402020242* 8402020338* 8402080270*	50-239 G 50-247 G 50-293 G 50-245 G 50-271 G	CHAUST, R H CHAUST, R H, CHAUST, R. H CHEN, J, C CHENEY, D,	8402220588* 8402220591* 8402220594* 8402210021 8402280020*	50-413 E 50-413 E 50-413 E 50-275 P FOIA	CHILK, S J CHILK, S J CHILK, S J CHILK, S J	8402160105* 8402160107* 8402160109* 8402160110* 8402160112*	FOIA FOIA FOIA 50-275 P FOIA

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR	
CHILK, B. J. CHILK, B. J. CHILK, B. J. CHILK, B. J.	8402160114* 8402160115* 8402160116* 8402160118* 8402160119*	FOIA FOIA FOIA FOIA FOIA	CHILK'S A CHICK'S A CHICK'S A CHICK'S A	8402160249* 6402160250* 6402160252* 6402160253*	FOIA FOIA FOIA 50-546 A FOIA	CHILK, S J CHILK, S J CHILK, S J CHILK, S J	8402140421* 8402140422* 8402140425* 8402140426* 8402160427*	FOIA 50-344 FOIA FOIA FOIA	P
CHILK, S. J. CHILK, S. J. CHILK, S. J. CHILK, S. J.	8402140120* 8402140121* 8402140123* 8402140123* 8402140124*	FOIA FOIA FOIA 50-289 P FOIA	CHICK'S A CHICK'S A CHICK'S A CHICK'S A	8402160256* 8402160257* 8402160258* 8402160259* 8402160261*	FOIA FOIA FOIA 50-244 P FOIA	CHILK,S J CHILK,S J CHILK,S J CHILK,S J	8402160428* 8402160430* 8402160431* 8402160434* 8402160435*	FOIA FOIA FOIA FOIA	
CHILK.S J CHILK.S J CHILK.S J CHILK.S J.	8402160126* 8402160128* 8402160127* 8402160131* 8402160132*	FOIA FOIA FOIA FOIA FOIA	CHILK'S Y CHILK'S Y CHILK'S Y CHILK'S Y	8402160263* 8402160265* 8402160266* 8402160268* 8402160269*	FOIA FOIA FOIA FOIA FOIA	CHILK, B J CHILK, B J CHILK, B J CHILK, B J	8402160436* 8402160439* 8402160440* 8402160441* 8402160442*	FOIA FOIA FOIA FOIA	
CHILK: S. J. CHILK: S. J. CHILK: S. J. CHILK: S. J.	8402160133* 8402160134* 8402160135* 8402160136* 8402160138*	FDIA FOIA FOIA FOIA FOIA	CHILK'S A CHIFK'S A CHIFK'S A CHIFK'S A CHIFK'S A	8402160272* 8402160273* 8402160274* 8402160275* 8402160279*	FOIA FOIA FOIA FOIA FOIA	CHILK'S J CHILK'S J CHILK'S J	8402160443* 8402160444* 8402160445* 8402160446* 8402160448*	F01A A107 A107 E-06 A107	Р
CHICK, S. J CHICK, S. J CHICK, B. J CHICK, B. J CHICK, S. J	8402160140* 8402160142* 8402160143* 8402160144* 8402160145*	FOIA FOIA 50-289 P 50-387 A 50-369 P	CHICK'S A CHICK'S A CHICK'S A CHICK'S A CHICK'S A	8402160280* 8402160281* 8402160285* 8402160287* 8402160287*	FDIA FDIA FDIA 50-289 P FOIA	CHILK'S J CHILK'S J CHILK'S J CHILK'S J	B402170041 B402170214 B402170221 B402170463 B402210101	50-275 10CFR 10CFR 10CFR 50~483	6
CHICK, S. J CHICK, S. J CHICK, S. J CHICK, S. J CHICK, S. J	8402160146* 8402160149* 8402160150* 8402160151* 8402160152*	FOIA FOIA FOIA 50-289 P FOIA	CHIFK'S N CHIFK'S N CHIFK'S N CHIFK'S N	8402160291* 8402160297* 8402160300* 8402160302* 8402160303*	FOIA FOIA FOIA FOIA FOIA	CHILK'S A CHILK'S A CHILK'S A CHILK'S A	8402210106 8402210109* 8402210111 8402220129 8402220163	10CFR 10CFR 50-329 50-382 50-440	0
CHILK, 8, J CHILK, 8, J CHILK, 8, J CHILK, 8, J. CHILK, 8, J.	8402140153* 8402140155* 8402140154* 8402140156* 8402140140*	FOIA FOIA FOIA FOIA FOIA	CHILK, B J CHILK, B J CHILK, B J CHILK, B J	8402160304* 8402160308* 8402160309* 8402160311* 8402160313*	FDIA FDIA FDIA 50-289 P FDIA	CHILK'S A CHICK'S A CHICK'S A CHICK'S A	8402230032 8402240051 8402240219 8402240248 8402270092*	50-354 FOIA	P P
MILK, S. J. MILK, S. J. MILK, S. J. MILK, S. J MILK, S. J	8402160161* 8402160162* 8402160163* 8402160165* 8402160166*	FDIA FDIA FDIA FDIA 50-289 F	CHIFK'S O CHIFK'S O CHIFK'S O CHIFK'S O	8402160316# 8402160317# 8402160319# 8402160320# 8402160322#	50-352 A 50-289 P FOIA FOIA	CHINYS J CHINYS J CHINYS J CHINYS J	8402270107= 8402270127* 8402270141* 8402270149* 8402270154*	FOIA FOIA FOIA FOIA	
HILK.S. J HILK.S. J HILX.S. J HILX.S. J HILK.S J	8402160167* 8402160168* 8402160169* 8402160171* 8402160172*	FOIA FOIA FOIA FOIA FOIA	CHILK,S J CHILK,S J CHILK,S J CHILK,S J	9402160324* 8402160325* 8402160328* 8402160327* 8402160330*	FOIA FOIA FOIA FOIA FOIA	CHICK'S A CHICK'S A CHICK'S A CHICK'S A	8402270162* 8402270165* 8402270170* 8402270179* 8402270183*	FOIA FOIA FOIA FOIA FOIA	
HILK, 9, J HILK, 9, J HILK, 9, J, HILK, 8, J HILK, 8, J	8402160173* 8402160175* 8402160177* 8402160179* 8402160182*	FOIA FOIA 50-269 P FOIA FOIA	CHILK, S J CHILK, S J CHILK, S J CHILK, S J CHILK, B J,	8402160332* 8402160335* 8402160338* 8402160341* 8402160342*	FOIA FOIA FOIA FOIA FOIA	CHIFK'S Y CHIFK'S Y CHIFK'S Y CHIFK'S Y	8402270172* 8402270178* 8402270204* 84022702011* 8402270216*	FDIA FOIA FOIA FOIA FOIA	
HILK, S. J HILK, S. J. HILK, S. J. HILK, S. J. HILK, B. J.	8402160183* 8402160184* 8402160185* 8402160186* 8402160187*	FOIA FOIA FOIA FOIA FOIA	CHILK, B J CHILK, B, J CHILK, B J CHILK, B J CHILK, B J	8402160345* 8402160348* 8402160349* 8402160350* 8402160352*	FOIA FOIA FOIA FOIA FOIA	CHICK'S A CHICK'S A CHICK'S A CHICK'S A	8402270221 * 8402270484 8402280035* 8402280042* 8402280310	FOIA FOIA FOIA FOIA 50-289	G
HILK, 8, J. MILK, 8, J. MILK, 8, J. MILK, 8, J. MILK, 8, J.	8402140187 8402140191* 8402160192* 8402160193* 8402160199*	50~443 Q FOIA FOIA FOIA FOIA	CHILK, B J CHILK, B J CHILK, B J CHILK, B J	8402160354* 8402160355* 8402160357* 8402160360* 8402160361*	FOIA 50-358 A FOIA FOIA FOIA	CHILK, B J CHILK, W J. CHIRAMAL, M CHRISSOTIMOS, N	8402290077 8402160413* 8402220205 8306240184* 8402070485*	FOIA 50-304	0 5 5 7
MLK, B. J. MCK, B. J. MCK, B. J. MLK, B. J. MLK, B. J.	8402160202* 8402160204* 8402160205* 8402160206* 8402160208*	FOIA FOIA FOIA FOIA FOIA	CHILK, B. J CHILK, B. J CHILK, B. J CHILK, B. J CHILK, B. J	8402160363* 8402160364* 8402160365* 8402160368* 8402160375*	FOIA FOIA FOIA 50-3 P FOIA	CHR ISSOTIMOS: N CHR ISSOTIMOS: N CHR ISSOTIMOS: N CHR ISTENDURY: E CHR ISTENBON: S.	8402270420 8402270424 8402270432* 8309300031* 8402070264	50-265 50-254 50-382	B G A G
MEK, B. J. MEK, B. J. MEK, B. J. MEK, B. J. MEK, B. J.	8402160210* 8402160212* 8402160215* 8402160216* 8402160218*	FOIA FOIA FOIA FOIA FOIA	CHIFK'S A CHIFK'S A CHIFK'S A CHIFK'S A	8402160379* 8402160380* 8402160383* 8402160384* 8402160388*	FOIA FOIA FOIA 50-341 A FOIA	CHRISTIANSON, F CHRISTMAN, J. N CHRISTMAN, J. N CHRISTNOT, E CHRISTNOT, E	8402130312# 8402090126 8402090126 8402100223# 8402150181#	50-322 50-322 50-440	0 0 0
HLK, 8, J. HLK, 8, J. HLK, 8, J. HLK, 8, J. HLK, B, J.	8402160220* 8402160221* 8402160224* 8402160225* 8402160229*	FÖIA FOIA FOIA FOIA FOIA	CHILK, S J CHILK, S J CHILK, S J. CHILK, S J.	8402160389* 8402160393* 8402160394* 8402160397* 8402160398*	FOIA 50-287 P 50-528 A FOIA FOIA	CHRISTOFFER: G CHRISTOFFER: G CHRISTY: H CHUNG: J W. CHURCHILL	8402150247* 8402270370* 8402070147 8402020280* 8402100142	50-315	0 0 0 0
ILK, 8, J. ILK, 8, J. ILK, 9, J. ILK, 8, J.	8402160230* 8402160234* 8402160235* 8402160236* 8402160239*	FOIA FOIA 50-250 P FOIA FOIA	CHILK, S J.	8402160401* 8402160402* 8402160406* 8402160407* 8402160409*	FOIA 50-397 A FOIA 50-289 P FOIA	CHURCHILL CHURCH	8402100142 8402030170 8402030170 8402030183 8402030183	50-287 50-289 50-289 50-289 50-289	G G G O
ILK, 8, J. ILK, 8, J. ILK, 8, J. ILK, 8, J. ILK, 8, J.	8402140240* 8402160243* 8402160244* 8402160246* 8402160248*	FDIA FDIA FDIA FDIA FDIA	CHILK,8 J. CHILK,8 J. CHILK,8 J. CHILK,8 J. CHILK,6 J.	8402160411* 8402160412* 8402160416* 8402160418* 8402160420*	FOIA 50-289 P FOIA FOIA 50-275 P	CHURCHILL, B W CHURCHILL, B W, CHURCHILL, B W CHURCHILL, B W CHURCHILL, B W	8402050174 8402050174 8402090137 8402090137 8402130190	50-289 50-289 50-289 50-289 50-289	0 0 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEORY
CHURCHILL. B W CHURCHILL. B W CHURCHILL. B W CHURCHILL. B W	8402130305 8402130305 8402130305 8402130309 8402130309	50-289 G 50-289 G 50-289 G 50-289 G 50-289 G	COLBURN, T. G COLE, R. F COLE, S COLE, S COLEMAN, F E	8402160588 8402140116 8402070178 8402070178 8402070179	50-266 P 50-529 G 50-322 T 50-322 T 50-445 G	COOK, K W COOK, K W COOK, K W COOK, K W	8402140261 8402150311 8402160106 8402160159 8402160353	90-382 £ 50-382 £ 50-382 £
CHURCHILL.B W CHURCHILL.B W CHURCHILL.B W CHURCHILL.B W	8402220074 8402220074 8402220133 8402220133 8402230111	50-287	COLEMAN, L F COLEMAN, N COLEMAN, P R COLEMAN, R COLEY, J L	8402030364* 8402270346 8402170437 8402150415 8402140358*	50-397 S WASTE MOT NUREO CONTRACT 50-259 G	COOK, K W COOK, K W COOK, K W COOK, K W	8402170235 8402220044 8402220189 8402220536 8402230001	50-382 A 50-382 A 50-382 A 50-382 A
CHURCHILL, B W CHURCHILL, B W CHURCHILL, B W CILIMBERG, R L CILLIS, M	8402230111 8402280343 8402280343 8402150014* 8402140233*	50-287 Q 50-287 G 50-287 G 50-483 G 50-344 G	COLLINS.D J COLLINS.D J COLLINS.D J COLLINS.D M.	8402140443* 8402270478* 8402150328* 8402080348* 8402140103	50-259 G FDIA 50-220 G 50-277 G I&E	COOK, K W COOK, K W COOK, K W COOK, K W	8402240062 8402280219 8402280229 8402280515 8402020236*	50-382 A 50-382 F 50-382 A 50-382 A 50-329 6
CLAPP, N E CLARDY, L S CLARK, A T CLARK, D CLARK, F H	8402100407 8402130273* 8402130633 8402170202 8402100407	TOPREP 50-409 G PROJ 50-245 S TOPREP	COLLINS.D M COLLINS.J COLLINS.J T. COLLINS.J T. COLLINS.S J	8402270588* 8402270274* 8402020378 8402220063 8402020171*	FOIA 50-317 Q WASTE MOT Btate Prog 50-410 Q	COOK, R. J COOK, W COONEY, M. J COONEY, M. J	8402100199* 8402290221* 8402240106* 8402020355 8402030432	50-329 A 50-329 9 50-322 4 50-276 9 50-277 E
CLARK, L CLARK, L CLARK, P CLARK, R CLARK, R CLARK, R	8402080325 8402130108* 8402070350 8402010373 8402170308	50-20 % 50-528 @ 50-289 P Nureg Nureg	COLLINS, B J COLLINS, B J COLLINS, B J. COLLINS, B J.	8402020260* 8402060426* 8402070221* 8402130063 8402240078*	50-333 Q 50-29 Q 50-333 Q 50-244 V 50-244 Q	COONEY, M J COONEY, M, J COONEY, M, J COONEY, M, J	8402030438 8402060113 8402060254 8402070263 8402070325	50-276 \$ 50-278 \$ 50-277 \$ 50-277 \$ 50-278 \$
CLARK, R A CLARK, R J CLARK, R J CLARKE, E T CLAY, E L	8402270213 8402010408 8402130541 8402080179 8402280534*	NUREO 50-259 P 50-259 P PR 70-143	COLLING. S. J. COLLING. T. D. COLOMBO. R. COLOMBO. R. W. COLOMBO. R. W.	8402280707 8402160345* 8402220350 8402230034 8402030355	50-244 V 50-424 C 50-312 R 50-312 B 50-312 B	CODNEY, M J COONEY, M, J COOPER, J W COOPER, M R	8402140260 8402140321 8402090276# 8402270303# 8402280451	50-277 1 50-276 8 FOIA FOIA 50-327 \$
CLAYBROOK: 8 W CLAYTON: F L CLAYTON: F L CLAYTON: F L CLAYTON: F. L	8402130043± 8402030176 8402030437 8402060067 8402060360	FOIA 50~348 F 50~348 S 50~348 S 50~348 B	COLOMBO, R W COLOMBO, R W COLOMBO, R. W COMBB, F C. COMBB, T	8402140388 8402160141 8402230206 8402270293* 8402010423	50-312 8 50-312 8 50-312 6 FOIA FOIA	COPELAND, V Q COPELAND, V, Q COPELAND, V Q COPELAND, V Q COPELAND, V, Q	8402030209 8402030209 8402030212* 8402030212* 8402070194	50-155 @ 50-155 @ 50-155 @ 50-155 @ 50-155 @
CLAYTON.F L CLAYTON.F L CLAYTON.F L CLAYTON.F L CLAYTON.F L	8402050433 8402080350 8402130015 8402140152 8402140342	50-348 8 50-348 8 50-348 F 50-348 P 50-348 P	CONGEL.F J CONLEY, O P CONLON.T E CONLON.T E. CONLON.T E.	8302020052* 8402280447 8402140183* 8402150014* 8402150256*	50-287 P 50-309 H 50-348 G 50-269 G 50-413 Q	COPELAND, V Q COPELAND, V Q COPELAND, V Q COPELAND, V, Q COPELAND, V, Q	8402070194 8402140215* 8402140215* 8402140197 8402160197	50-155 6 50-155 6 50-155 6 50-155 6
CLAYTON, F. L CLAYTON, F. L CLAYTON, F. L CLAYTON, F. L CLAYTON, F. L.	8402140088 8402140441 8402170089 8402170127 8402170192	50-364 P 50-368 F 50-364 R 50-348 R 50-364 S	CONLON, T E CONLON, T E CONLON, T E. CONLON, T E. CONNAUGHTON, K.	8402150378* 8402280011* 8402280204* 8402280285* 8402089326*	50-389 G 50-400 G 50-400 G 50-413 G 50-454 G	GDPELAND, V. G. COPELAND, V. G COPELAND, V. G COPELAND, V. G. CORBESIA, D. M	8402210353# 8402210353# 8402280430 8402280430 84022140531	50-153 9 50-153 9 50-153 9 50-153 9 71-451
CLAYTON, F L CLAYTON, F L CLAYTON, F L. CLAYTON, F L. CLAYTON, F L	8402170220 8402170243 8402170326 8402210298 8402220331	50-348 P 50-364 P 50-348 P 50-348 P 50-348 P	CONNER.E. CONNER.T.B. CONNER.T.B. CONNER.T.B. CONNER.T.B.	8402100332 8402040059 8402040059 8402040219 8402040219	50-352 Q 50-352 Q 50-352 Q 50-352 Q 50-352 Q	CORDARD, M. C CORLEY, W O CORMIER, W H CORMIER, M. H CORNWELL, K F.	8402140058* 8402150387* 8402070237 8402220142 8402010287*	50-322 6 50-329 6 50-142 6 50-142 6 50-271 F
CLAYTON, F, L CLAYTON, F L, CLAYTON, F L, CLAYTON, F L, CLAYTON, H B.	8402220487 8402220511 8402270259 8402270262 8304010054*	50-348 P 50-348 P 50-348 P 50-364 B 50-289 P	GONNER, T B CONNER, T B CONNER, T B CONNER, T B CONNER, T B	8402080124* 8402080124* 8402130274 8402130276 8402160209	50-354 G 50-354 G 50-354 G 50-354 G 50-352 G	CDRRADINI, M CORRADINI, M. CORYELL, O. P COTTER, B. P COTTER, B. P.	8402070491 8402070491 8402150337* 8402010189 8402020231	ACRB ACRB 70-143: 50-463 g 50-424 g
CLEMENTS, B R. CLEMENTS, B R CLEMONS, P CLEMONS, P CLEMONS, P	8402160203 8402230122 8402020003* 8402060045* 8402060075*	50-445 F 50-445 K 50-220 Q 50-217 Q 70-364	CONNER, T B. CONNER, T B CONNER, T B CONNER, T, B CONNER, T, B	8402160209 8402160264 8402160264 8402240057*	50-352 Q 50-352 Q 50-352 Q 50-416 Q 50-416 Q	COTTER, B P COTTINOHAM, A. W COUGHLIN, L COUNSIL, W G COUNSIL, W. G,	8402290113 8402270301 8309130483+ 8402010219 8402010219	50-413 8 50-413 8 COM188100 50-213 F 50-213 F
CLEMONS, P CLEVELAND, J C. CLINE, W E. CLINE, W.E.	8402290302* 8402060437 8402140063* 8402140407* 8402140428*	50-307 G NURE9 70-1201 70-27 70-824	CONNER, T. B.	8402280335 8402280335 8402280347 8402280347 8402070162*	50-352 Q 50-352 Q 50-416 Q 50-416 Q 50-382 Q	CDUNBIL, W G CDUNBIL, W. G. CDUNBIL, W. G. CDUNBIL, W. G. CDUNBIL, W. G.	8402010219 8402020152 8402020152 8402020351 8402030251	50-213
CLOUD, R. L CLYDE, M R COALWELL, T D COCHRAN, P. COCHRAN, T. B.	8402070375 8402160305 8402090245 8402030230 8402210336*	50-275 P 50-528 F TOPREP 50-265 9 50-320 P	CONVEY, D. A. CONVAY, T & CODK, J CODK, J W CODK, J W	8402100466 8402280596* 8402100258 8402020161 8402060124	XPORTLIC FDIA 50-333 R 50-327 R 50-327 S	COUNSIL, W. Q. COUNSIL, W. Q. COUNSIL, W. Q. COUNSIL, W. Q. COUNSIL, W. Q	8402030397* 8402030397* 8402030402* 8402030402* 840203040211	50-336 6 50-336 4 50-336 4 50-338 3
COCHRAN, T. B. COELHO, T COFFEY, J A. COFFEY, J A. COFFEY, J A	8402210460* 8402280020* 8402030215 8402030471 8402080154	50-320 P FOTA 50-260 8 50-259 8 50-260 8	COOK, J. W. COOK, J. W. COOK, J. W.	8402040371 8402040414 8402040454 8402070341 8402080227	50-327 B 50-329 Q 50-329 B 50-329 B 50-329 B	COUNBIL, W O COUNBIL, W. G COUNBIL, W G. COUNBIL, W G.	8402060211 8402060417 8402070225 8402070246* 8402080247	50-423 1 50-213 P 50-213 P 50-213 6 50-423 A
COFFEY, J A COFFEY, J A COFFEY, J A COFFEY, J A COFFEY, T. A	8402080220 8402080287 8402140218 8402140426 8402030389	50-327 8 50-260 8 50-259 8 50-260 8 50-328 8	COOK, J. W. COOK, J. W. COOK, J. W. COOK, J. W.	8402090255 8402160458 8402220193 8402220404 8402220504	50-327 A 50-327 A 50-327 B 50-327 B 50-327 B	COUNBIL, W. O. COUNBIL, W. Q. COUNBIL, W. Q. COUNBIL, W. Q. COUNBIL, W. Q.	8402080247 8402080283 8402080283 8402080283 8402100197	50-423 A 50-336 B 50-336 B 50-336 B 50-245 P
CDFFMAN, F E COHEN, I, COHEN, M. COLBURN, T G,	8402100448 8402020357* 8402080404* 8402270342 8402090519	8tate Prog 50-244	COOK, J. W COOK, K. W. COOK, K. W. COOK, K. W.	8402270452 8402040208 8402100013 8402100237 8402100243	50-327 B 50-382 E 50-362 A 50-382 A 50-382 A	COUNBIL, H. Q COUNBIL, H. Q. COUNBIL, H. Q. COUNBIL, H. Q. COUNBIL, H. Q.	8402100197 8402100239 8402100239 8402140135 8402140135	50-245 F 50-423 A 50-423 A 50-213 F 50-213 F

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
COMMITTING COMMITTING	8402140135 8402140416 8402140416 8402150009 8402150009	50-213 F 50-336 P 50-336 P 50-213 P 50-213 P	CROCKER, H W CROCKER, H W CROCKER, H W CRONYN, M W CROSSMAN, W A	8402020357* 8402080404* 8402220467* 8402280196 8402070162*	50-244 Q 50-277 Q 50-322 Q 50-288 F 50-382 Q	CUNNINGHAM, G H CUOMD, M CURRAN, D CURRAN, D CURRAN, D	8402240114* 8402070179 8402130290* 8402130270* 8402030313	50-287 6 50-322 6 50-443 6 50-443 6 50-388 5
COONSIL'H 0 COONSIL'H 0 COONSIL'H 0 COONSIL'H 0	8402150009 8402150182 8402150182 8402150298 8402150307	50-213 P 50-245 F 50-245 F 50-213 F 50-245 P	CROSEMAN, W A	8402070191* 8402220347* 8402220372* 8402220393* 8402270446*	50-498	CURTIS, N W CURTIS, N W CURTIS, N W CURTIS, N W CURTIS, N W	8402070196 8402070200 8402070243 8402070254 8402070270	50-387 P 50-387 F 50-387 P 50-388 E 50-387 P
COUNSIL.N 0 COUNSIL.N 0 COUNSIL.N 0 COUNSIL.N 0 COUNSIL.N 0	8402190307 8402190340 8402150340 8402160005 8402160005	50-245 P 50-336 P 50-336 P 50-245 F 50-245 F	CROUBE, R P CROUSE, R P CROUBE, R P CROUBE, R P CROUBE, R P	8402030242 8402030311 8402060090 8402060354 8402060367*	90-346 P 50-346 P TOPREP 50-346 F 50-346 Q	CURTIS, N W	8402070349 8402130214 8402140204 8402170237 8402270077	50-389 E 50-387 P 50-387 S 50-387 E 50-387 P
COUNSIL. W G COUNSIL. W G COUNSIL. W G COUNSIL. W G	8402160044 8402160044 8402160100 8402160100 8402160113	50-336 P 50-336 P 50-336 P 50-336 P 50-336 Q	CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P	8402140385 8402150207 8402150217* 8402240014 8402240056	50-346 P 50-346 P 50-346 P 50-346 P 50-346 P	CURTIS, N W	B4022701B6 B402270255 B402270349 B402270429 B402280243	50-388 8 50-388 8 50-388 9 50-387 P 50-387 P
COUNSIL.W 0 COUNSIL.W 0 COUNSIL.W 0 COUNSIL.W 0	8402160113 8402160385 8402160385 8402160424 8402160424	50-336 0 50-245 P 50-245 P 50-336 P 50-336 P	CROUSE, R P CROUSE, R P CROW, W T CROW, W T CROW, W T	8402270115 8402270120* 8402010334 8402070427 8402100402*	50-346 P 50-346 P 70-25 70-498 70-135	CURTIS.R H CUSTODID.D B CUTTER.A B CUTTER.A B CUTTER.A B	8402220358 8402040118 8402040114 8402080158 8402280407	MRE0 50-217 8 50-324 P 50-261 8 50-261 P
COUNSIL, H C COUNSIL, H C COUNSIL, H C COUNSIL, H C COUNSIL, H C.	8402160437 8402160437 8402160459 8402160459 8402170044	50-336 P 50-336 P 50-245 P 50-245 P 50-245 P	CRUNKLETON, J CRUNKLETON, J CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D.	8402020132 8402070387 8402010068 8402010075* 8402010147	50-317 8 50-318 9 50-244 P 50-244 P 50-219 P	CZAJKOWSKI,C J CZAYA,P.F DALC,L. DALE,L F DALE,L F	8402220099 8402150225 8402090156* 8402010166 8402030342	NUREG 50-219 8 50-416 A 50-416 G 50-416 9
COUNSIL, H 0. COUNSIL, H 0 COUNSIL, H 0 COUNSIL, H 0	8402170044 8402210257 8402210257 8402220190 8402220190	50-245 P 50-336 Q 50-336 Q 50-336 P 50-336 P	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8402010175* 8402020308 8402020390 8402070010 8402070163	50-219 P 50-213 P 50-244 G 50-409 F 50-213 P	DALE, L F DALE, L F DALE, L F DALE, L F DALE, L F	8402040083 8402040084 8402040103 8402080279 8402090194	50-416 H 50-416 P 50-416 P 50-416 P 50-416 P
COUNSIL, H 0 COUNSIL, H 0 COUNSIL, H 0 COUNSIL, H 0. COUNSIL, H 0	8402220417 8402220460 8402220486 8402220486 8402230103	50-423 E 50-213 P 50-423 A 50-423 A 50-245 P	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D	8402070202 8402070203 8402070207 8402070208 8402070328	50-10 F 50-409 P 50-206 F 50-27 F 50-219 P	DALE, L F DALE, L F DALE, L F DALE, L F DALE, L F	8402130389 8402130430 8402130450 8402140013 8402150369	50-416 S 50-416 S 50-416 B 50-416 B 50-416 R
COUNSIL, H O COUNSIL, H O COUNSIL, H O COUNSIL, H O	8402230103 8402240005 8402240005 8402240017 8402240113	50-245 P 50-423 A 50-423 A 50-423 A 50-245 P	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8402070333* 8402070337 8402070345 8402070383 8402070362	90-217 P 50-213 F 50-155 F 50-244 F 50-217 F	DALE, L F DALE, L F DALE, L F DALE, L F DALE, L F	8402170171 8402220057 8402220069 8402220060 8402220119	50-416 8 50-416 8 50-416 8 50-416 8 50-416 8
COUNSIL, H O COUNSIL, H O. COUNSIL, H O. COUNSIL, H O COUNSIL, H O	8402240113 8402240240 8402280233 8402280274 8402280274	50-245 P 50-423 A 50-423 B 50-423 A 50-423 A	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8402080207 8402090321 8402100028 8402100220 8402100224*	50-219 F 50-206 G 50-29 P 50-244 P 50-244 P	DALE, L F DALE, L F DALE, L F DALE, L F DALE, L F	8402220124 8402220329 8402220401 8402220531 8402220570	50-416 8 50-416 8 50-416 P 50-416 8 50-416 8
COVER, L. C. COMAN, B. Z. COMAN, K. D. COX, J. H. COX, J. H.	8402210021 8402280465 8402020141 8402220842* 8402220846*	50-295 P PR 50-397 R 50-413 E 50-413 E	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8402130423 8402140378 8402140381 8402170228 8402170259	TOPREP 50-237	DALE, L F DALE, L F DALE, L F DALE, L F DALE, L F.	8402240030 8402240059 8402240060* 8402270085 8402270144	50-416 P 50-416 R 50-416 B 50-416 S
COX* 1 H COX* 1 H COX* 1 H COX* 1 H	8402220549* 8402220549* 8402220572* 8402220575* 8402220580*	50-413 E 50-413 E 50-413 E 50-413 E 50-413 E	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8402170274* 8402210075 8402210138 8402220485 8402220471*	50-237 P 50-219 P 50-219 P 50-204 P 50-204 P	DALE, L F DALE, L F DALE, L F DALE, L F DALE, L F	8402270159 8402270227 8402270323 8402270407 8402280265*	50-416 8 50-416 8 50-416 8 50-416 8 50-416 0
CDX.J W CDX.J W CDX.J W CDX.T	8402220587* 8402220591* 8402220594* 8402220595* 8402090195*	50-413 E 50-413 E 50-413 E 50-413 E 50-498 A	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8402230121 8402230134 8402230136* 8402230204 8402230236	50-204 P 50-206 P 50-206 P 50-407 F 50-244 V	DALE, L F DALE, L F DALE, L F DALE, L F DALE, L F	6402260272* 6402260421* 6402260423* 8402280427* 8402280428*	50-416 G 50-416 G 50-416 G 50-416 G
COX: T. H. COX: T M. COYLE: F T CRAIG: R. L CRANE: P.	8401170077* 8402070275* 8402070446 8402080186 8402090193*	50-397 A 50-397 A 40-6940 PR 50-322 G	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8402270212 8402270239 8402270400 8402280251 8402280457	50-217 P 50-204 P 50-237 P 50-409 F 50-237 P	DALE, L.F. DALLMAN, D. J. DALTROFF, B.L. DALTROFF, B.L. DANGE, H. C.	8402260550 8402010111 8402220374* 8402240138 8402080224	50-416 S MUREQ 50-277 Q 50-277 Q 50-335 Q
CRANE, PA CRAMEOND, K. CRAMLEY, D. CREED, J. R. CREED, J. R.	8402280197 8402220477 8402220096 8402060009* 8402150284	50-133	CRUTCHFIELD, D. CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D, CRUTCHFIELD, D, CULLEN, D, P	8402280472* 8402270377 8402270382 8402270385* 8402030409	50-237 P 50-155 P 50-155 P 50-155 P 50-159 P 50-302 8	DANCE, H. C. DANCE, H. C. DANCE, H. C. DANCE, H. C. DANCE, H. C.	8402140140 8402140143 8402140147 8402140153* 8402140203	50-364 0 50-267 0 50-321 0 50-267 0 50-269 0
CREED, J. R. CREED, J. R. CREED, J. R CREWS, J. L CRISCIONE	8402220345* 8402270416* 8402270444* 8402140379* 8402100206	50-274 Q 50-454 Q 50-463 Q 50-344 Q 50-336 B	CUMMINGS, J. CUMMINS, B. R CUMMINS, J. E CUMMINS, J. E CUMMINS, J. E	8402240166* 8402170120* 8402220339* 8402220406* 8402220596*	50-382 A GA999 50-313 G 50-313 G 50-313 G	DANCE, H C DANCE, H, C DANCE, H C DANCE, H C DANCE, H C	B402140207 B402140242 B402140275* B402140278 B402140306	50-414 G 50-335 G 50-335 G 50-349 F 50-413 G
CRISPIA. CRLENJAKIR V. CRLENJAKIR V CRLENJAKIR V. CROCKERIH W	8402220574* 8402150274* 8402280246* 8402280485* 8402020158*	50-413 E 50-366 G 50-321 G 50-366 G 50-213 G	CUNNINGHAM, A.L. CUNNINGHAM, A.L. CUNNINGHAM, G.E. CUNNINGHAM, G.H. CUNNINGHAM, G.H.	8402140356* 8402150157* 8402130427 8402170387 8402240105*	50-321 Q 50-413 G 70-754 COMMISBION 50-269 0	DANCE, H C DANCE, H C DANCE, H C, DANCE, H C, DANCE, H C	8402140314* 8402140316 8402140350 8402140353 8402140362	50-413 0 50-321 V 50-321 G 50-387 0 50-347 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGORY
DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8402140400 8402150011 8402150012 8402150152 8402150236	50-335 F 50-269 G 50-269 G 50-413 G 50-413 G	DELOATCH, V DENHAN, F K DENISE, R P DENNING, R S, DENNING, R S	8402100450 8402240127 8402280462 8402130025* 8402130027*	CONTRACT 50-483 B 50-362 R FOIA FOIA	DEWEY, L B DEYOUNG, R C DEYOUNG, R C DEYOUNG, R C DEYOUNG, R C	8402140116 8307190353# 8307190358# 8309270525# 8309270528#	50-529 Q 50-247 P 50-247 P FOIA FOIA
DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8402150246 8402150274 8402150342 8402150373 8402220053	50-413 0 50-413 0 50-250 S 50-3B7 0 50-250 S	DENNING.R S DENNIS,N A DENNY,I C. DENNY,I L DENTON	8402130048* 8402020330* 8402290277 8402270388 8402010330	FOIA 40-6920 40-2061 40-2061 NUREG	DEYDUNG, R C DEYDUNG, R C DEYDUNG, R C DEYDUNG, R C DEYDUNG, R C	8401190017 8402060381 8402130446 8402130447# 8402140129#	50-3 q 50-263 0 50-390 0 50-390 0 FOIA
DANCE.H C DANCE.H C DANCE.H C DANCE.H C DANCE.H C	8402280003 8402280082 8402280135 8402280148 8402280146*	50-413	DENTON, H DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8205240576* 8108190047* 8205210017* 8212290011* 8212290017*	FOIA FOIA FOIA FOIA FOIA	DEYDUNG, R C DEYDUNG, R C DEYDUNG, R C DEYDUNG, R C DEYDUNG, R C	8402140317 8402140324* 8402140339 8402170486 8402290152*	40-299 40-299 50-410
DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8402280239 8402280264 8402280277 8402280442 8402280467	50~321 0 50~269 0 50~413 0 50~302 0 50~339 0	DENTON: HR DENTON: HR DENTON: HR DENTON: HR DENTON: HR DENTON: HR	8304140137* 8305200042* 8311230177* 8401270182 8402010286*	FOIA FOIA FOIA TOPREP MISC	DEYDUNG.R C DEYDUNG.R C DICK.G. DICK.G.F. DICKEY.C	8402270181* 8402270185* 8402010083* 8402140072 8402220347*	POIA FOIA 50-244 P 50-413 E
DANCE, H C DANCE, H C DANCE, H C DANDOIS, D B DANDOIS, D B	8402280477* 8402280304 8402280332 8402230340* 8402230342*	50-339 G 50-413 G 50-269 G FOIA FOIA	DENTON, H R	840201031	50-327 H PROJ MISC NUREG TOPREP	DICKEY,C B DICKEY,C B DICKHONER,W H DICKHONER,W H DIEDERICH,O J	8402220548* 8402220540* 8402030240 8402270310 8402030217	50-410 E 50-410 E 50-356 A 50-356 A 50-370 S
DANDOIS, D B DANDOIS, D B DANDOIS, D B DANDOIS, D B DANDOIS, D B	8402230368* 8402230368* 8402230370* 8402230372* 8402230374*	FOIA FOIA FOIA FOIA FOIA	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8402080455* 8402080477* 8402090276 8402090417 8402090424*	FDIA FDIA MISC 50-289 P 50-289 P	DIEDERICH, G J DIEDERICH, G J DIEDERICH, G J DIEDERICH, G J DIEDERICH, G J	8402030224 8402080041 8402150352 8402150376 8402160284	50-373 8 50-373 8 50-373 8 50-373 8 50-374 8
DANDDIS,D B DANDDIS,D B DANDDIS,D B DANDDIS,D B DANDDIS,D B	8402230377* 8402230379* 8402230383* 8402230387* 8402230390*	FOIA FOIA FOIA FOIA FOIA	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	6402100200 8402130502* 6402130557 8402140481 8402140518	50-206 P MISC NUREG MISC 50-440 M	DIEDERICH, G J DIEDERICH, G J DIEDERICH, G J DIEDERICH, G J DIEDERICH, G J	8402140334 8402210261* 840222001 8402220013 8402220176	50-373 8 50-373 8 50-373 8 50-373 8 50-373 8
DANDOIS,D B DANDOIS,D B DANDOIS,D B DANDOIS,D B DANDOIS,D B	8402230393* 8402230394* 8402230400* 8402230402* 8402270241*	FOIA FOIA FOIA FOIA FOIA	DENTON, H R	8402140537 8402150420 8402150423* 8402170254 8402210450	MISC 50-352 9 50-352 9 TOPREP 50-373 P	DIEDERICH, O J DIEDERICH, O J DIEDERICH, O L DIELMAN, R DIELMAN, R W	8402220284 8402220559 8402080055 8402270276* 8402270265*	50-373 8 50-373 8 50-374 8 FOIA FOIA
DANDDIS.D 8 DANDDIS.D 8 DANESE.F L DANESE.F L DANESE.F L	8402270248* 8402270251* 8402060046* 8402060073* 8402180076	F01A F01A F01A F01A 50-266 F	DENTON:H R DENTON:H R DENTON:H R DENTON:H R DENTON:H R	8402230154* 8402230363 8402270187 8402270604 8402270628	M18C 50-416 P 50-546 E 50-261 P 50-317 P	DIELMAN,R W DIENEB,A.F DIENEB,A F. DIETZ,C R DIETZ,C R	8402270268* 8401130193 8402140177 8402030276 8402030359	FDIA 50-255 R 50-255 R 50-324 8 50-325 8
DANIEL, 8 L DANIELSON, D H DANIELSON, D H DANIELSON, D H DANIELSON, D H	8402240207* 8402020316* 8402070216* 8402100208* 8402150016*	POIA 50-461 G 50-373 Q 50-255 Q 50-483 G	DENTON:H R DENTON:H R. DENTON:H R DESLANDES,K D DESMAN:R J	8402290467 8402290473* 8402290477* 8402080251 8402280447	50-320 0 50-320 0 50-320 0 50-334 9 40-8724	DIETZ, C, R DIETZ, C, R DIETZ, C, R, DIETZ, C, R, DIETZ, C, R	8402030363 8402030407 8402030450 8402030482 8402130359	50-324 8 50-324 8 50-324 8 50-325 8 50-324 8
DANIELSON, D H DANIELSON, D H DANIELSON, D H DANIELSON, D H, DANIELSON, D H	8402220592* 8402270095* 8402270434* 8402270135* 8402270247*	50-454 Q 50-454 Q 50-483 Q 50-454 Q 50-456 Q	DETJEN, R J DETJEN, J DEVALLE, R O DEVINCENTIB, J	8402280656* 8402070015 8402080087* 8402230232* 8402210145	40~8724 50~289 T FDIA 50~397 F 50~443 8	DIETZ, C R. DIETZ, C R. DIETZ, C, R. DIETZ, C, R. DIETZ, C, R. DIETZ, C, R.	8402140005 8402140232* 8402140248* 8402140300* 8402140364	50-325 8 50-324 0 50-324 0 50-324 0 50-324 8
DARLING, S.S. DARU, V.C. DAVENPORT, K.E. DAVENPORT, K.E. DAVENPORT, C.A.	8402280147 8402170162* 8402280270* 8402280484* 8402170194*	50-318 S 50-482 S 50-269 Q 50-339 Q 50-322 Q	DEVINCENTIB, J DEVINCENTIB, J DEVINCENTIB, J DEVINCENTIB, J	8402010145 8402030235 8402030235 8402030305 8402030305	50-443	DIETZ, C R DIETZ, C R DIETZ, C R DIETZ, C R DIETZ, C R	8402140458 8402150344 8402160125 8402220553 8402220586	50-324 8 50-324 8 50-325 A 50-324 8 50-324 9
DAVIS, J C DAVIS, J C DAVIS, J C DAVIS, L. A	8402010234 8402060050* 8402060060* 8402080219* 8402230272*	WASTE MGT 50-250 P 50-250 P 40-1341 CONTRACT	DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J	8402030422 8402030422 8402040225 8402040225 8402070255	50-443 8 50-443 8 50-443 8 50-443 8 50-443 A	DIETZ, C R DIGOB, R DIGOB, R M DIGGS, R M DIGOB, R M	8402270381 8402070509 8402030529 8402030535 8402070529	50-025 8 50-155 A 50-220 P 50-286 F 50-282 A
AVIS,M S AVIS,M S AVIS,R E AVIS,R T AVIS,T	8402280449* 8402170494 8402210026 8402100252* 8402280593	50-280 Q NUREO NUREO 50-244 P FOIA	DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J	8402070255 8402080400 8402080400 8402140208 8402140208	50-443 A 50-443 S 50-443 S 50-443 A 50-443 A	DIGGS, R M DIGGS, R M, DIGGS, R M DIGGS, R M DIGGS, R M,	8402130653 8402170186 8402170297 8402230022 8402270327	50-293 4 50-219 7 50-259 7 50-302 7 50-333 7
W V, RIVAD W,V, BIVAD M D, NOBWAD B R, NASD T B, EBBD	8402010143 8402020196 8402070535 8402140520* 8402140165*	50~352 D 50~456 D 71~7001 50~297 P 50~348 Q	DEVINGENTIS, J DEVINCENTIS, J DEVINCENTIS, J DEVINGENTIS, J	8402150363 8402150363 8402150365* 8402150365* 8402210129	50-443 S 50-443 S 50-443 Q 50-443 Q 50-443 F	BIGNAN, T. G DIGNAN, T. G. DIGNAN, T. G. DIGNAN, T. G. DIGNAN, T. G	8402070004* 8402130290* 8402130290* 8402220200* 8402220200*	50-293 9 50-443 9 50-443 9 50-309 9 50-309 9
DELAIGLE, R DELANEY, C E. DELBELLO, A B DELBELLO, A B DELGEORGE, L. D	8402150195 8402130300 8402070121 8402070126* 8402270442*	50-424	DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J DEVINE, H F	8402210127 8402220482* 8402220482* 8402280083 8402020209	50-443 F 50-443 Q 50-443 Q 50-443 S 50-409 J	DIGNAN, T G. DIGNAN, T. G DIGNAN, T. G DIGNAN, T G. DIGNAN, T. G.	8402220224* 8402220230* 8402220230* 8402280350	50-309 9 50-309 9 50-309 9 50-309 9 50-443 9
BELLA RATTA, A DELLA RATTA, A DELGACH, G. L DELDATCH, V DELGATCH, V	840202022 6* 8402240027 * 8402150167 8402010355 8402060856	70-371 70-371 50-424 g CGNTRACT CONTRACT	DEVINE, J B DEVINE, J F. DEVINE, T. DEWANDEL, E P DEWEY, L G	8402020443 6402030227 8402130251 8402100203 8402010141	XPORTLIC WASTE MGT 50-275 0 50-280 F 50-529 0	DIGNAN.T.O DIIANNI.D.C. DIIANNI.D C DILLON.R.L DILLON.R.L	8402280350 8402140489* 8402140492* 8402070509	50-443 9 50-306 P 50-306 P ACRS ACRS

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGGRY	AUTHOR	ACCESSION NUMBER	GUBJECT CATEGORY	AUHTUA	ACCESION NUMBER	BUBJECT CATEGORY
CIMMICK, D M CIMMICK, D M CIPCKS, H J DIRCKS, H J DIRCKS, H J	8402140618 8402140621* 8201300218* 8211270127* 8212130066*	71-9080 71-9080 50-498 Q FOIA FOIA	DOBLITTLE, E L DOBLITTLE, E L DOBLITTLE, E L DOBLITTLE, E L DORDSHOW, J	8402230249 8402230371 8402230384 8402230386 8402060025	50-423 A 50-423 E 50-423 A 50-423 A 50-289 P	EADIE, Q EADIE, G G, EAGLE, J EAPEN, P K EAPEN, P K	8003250487* 8402080048* 8402130383 8402080374* 8402090357*	A0-1341 FOIA 50-265 8 50-387 9 50-387 9
DISCKB'M N DISCKB'M N DISCKB'M N EISCKB'M N	8304040543* 8306270165* 8307270206 8308100453* 8308180043*	50-528 A F01A SECY F01A 50-382 U	L WINHEORDD TO WORDSHOW A L YTRIHOUDD B L YTRIHOUDD B L YTRIHOUDD	8402230087 8402280215 8402210274* 8402160245 8402160245	50-287 0 50-287 0 50-329 R 50-322 0 50-322 0	EAPEN, P K EAPEN, P K EARLEY, A F EARLEY, A F EAHLEY, A F	8402240050* 8402270317* 8402020225 8402020275 8402080054	50-217 0 50-277 0 50-222 0 50-322 0 50-322 0
CIRCKS.W J CIRCKS.W J DIRCKS.W J DIRCKS.W J CIRCKS.W J	8308240177* 8309120090* 8309120255* 8309150464* 8402010453*	FOIA 50-263 F FOIA COMMISSION 50-250 P	DDUGHTY,J DOVICASE,S J DOVICSAK,R A DOVLE,J DDYLE,J.	8402010471 8402280699 8402080070* 8402060156* 8402100072*	50-443 A 40-8794 FOIA 50-445 O 50-445 T	EARLEY, A F EARLEY, A F EARLEY, A F EARLEY, A F CARLEY, A F	8402080054 8402130165 8402130165 8402140075 8402140075	20-355 0 20-355 0 20-355 0 20-355 0
DIRCKS.W J CIRCKS.W J CIRCKS.W J DIRCKS.W J	8402020092* 8402030047 8402030385 8402030487 8402060028	50~259 B 50~289 P 50~275 P 50~478 U 50~289 P	DOYLE,K A DRAGOUN,T DRAGOUN,T DRAGOUN,T DRAGOUN,T F	8402080062* 8402020324* 8402060402 8402070367* 8402240072*	50-528 R 50-219 Q 50-272 P 50-272 Q 50-367 Q	CARLEY, A F EARLEY, A F EARLEY, A F EARLEY, A F	8402220152 8402220152 8402220454 8402220454 8001040264#	LOIV 20-35% 0 20-35% 0 20-35% 0 20-356 0
CIRCKS, W J. DIACKS, W J DIACKS, W J DIRCKS, W J DIRCKS, W J.	8402040056* 8402040077* 8402040111 8402070032* 8402070035	FDIA FDIA 50-289 U FDIA COMMISSION	DRAKE, J B DRAMBRINGE, D L DREY, K DREY, K DRISCOLL, W J	8402210073 8402270397 8209170054 8402170314 8402070049	NUREQ 50-29 8 50-220 H 50-483 H FOIA	EARLY, P. J. EABLEY, P. EBERBOLE, J. C. EBERBOLE, J. C. EBERBOLE, J. C.	8402270324* 8402130064* 8402010278 8402010283 8402010284	FDIA FDIA ACRB 50~184 () ACRB
(RCKS, W J)[ACKS, W J,)[ACKS, W J,)[ACKS, W J)[ACKS, W J	8402070137* 8402080027 8402080060* 8402080138* 8402080214*	50-322 0 50-397 0 F0IA 40-1341 40-1341	DRISKILL,D D DRIVER,B M DRUGA,R,J DRUGA,R J DRUGA,R J	8402270067* 8402170290 8402230098 8402280366 8402070531	50-382 0 WASTE MOT 50-334 8 50-334 9 70-2946	EBERBOLE, J C EBERBOLE, J C EBNER, A M EBNER, A M EBNETER, B D	8402230235 8402230235 8402090037* 840209004 <i>2</i> * 84020202860*	50-275 U ACRS 50-443 R 50-443 R 50-388 G
IRCKB, H J. IRCKB, H J IRCKB, H J IRCKB, H J IRCKB, H J	8402080232 8402080408 8402090093+ 8402090594 8402100375+	50-287 P SECY 50-498 A 50-416 P 50-275 P	DRUMMOND.F J DRUMMOND.F J DUBGIS,D DUBGIS,D. DUBGIS,D.	8402140571 8402240064 8402020425 8402090506 8402220635	70-2946 50-302 A XPORTLIC XPORTLIC XPORTLIC	ECCLESTON, K T ECKES, J J ECONOMOS, C ECONOMOS, N EDDLEMAN, W	8402240222 8402130222 8310050275* 8402150315* 8402030306	TOPREP 50-456 D 50-321 P 50-413 G 50-400 Q
INCKA'N Y INCKA'N Y INCKA'N Y INCKA'N Y	8402130265 8402140482 8402170457 8402210280* 8402210282*	50-3 H 50-454 A 50-528 G 50-275 P 50-275 P	DUCK.JR R DUCK.JR DUCK.JR DUCK.JR DUCK.JR DUCK.JR	8402070238* 8402020343 8402160321 8402160343 8402210231	50-278 Q 50-335 J 50-327 J 50-370 J 50-259 J	EDDLEMAN, W EDDLEMAN, W EDDLEMAN, H EDDLEMAN, H EDDLEMAN, H	8402030312* 8402030317* 8402030320* 8402030321* 8402030324*	50-400 Q 50-400 Q 50-400 Q 50-400 Q 50-400 Q
IBCKS'M N IBCKS'M N IBCKS'M N IBCKS'M N IBCKS'M N	8402230344 8402230347 8402240200* 8402270004 8402280671	BECY 50-249 S 50-287 P 50-358 R 50-289 U	DUCK, J. R DUDLEY, R DUDLEY, W W DUFFY, M DUGGIN, G.	8402210242 8402220377 8402270632 8402270557 8402060205	50-438 J 50-409 P WASTE MOT FOIA 50-327 8	EDDLEMAN, W, EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W	8402130314 8402130314 8402130317* 8402130322* 8402130322*	50-400 Q 50-400 Q 50-400 Q 50-400 Q 50-400 Q
(SE, DP (SE, DP. (KON, D, J (KON, D H (ICON, D W	8402020126 8402060224 8402290093 8402030418 8402060372	50-410 8 50-410 8 50-354 8 50-375 8 50-375 R	DUGOIN, O DUGOIN, O DUGOIN, O DUGOIN, O. E DUGOIN, O. E	8402220161 8402280367 8402280441 8402080220 8402140191	50-327 8 50-327 8 50-328 8 50-327 0 50-327 8	EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W EDELMAN, M	8402140061 8402160226 8402280226 8402280425 8402080312	50-400 G 50-400 G 50-400 G 50-400 G 50-440 K
ITON.O.W IXON.O W IXON.O W IXON.O W	8402060430 8402060470 8402070210 8402070386 8402130272	50-375 F 50-375 P 50-375 S 50-375 F 50-375 R	DUGGIN, O E DUGGIN, O E DUGBTAD, D DUKE, J R. DUMMER, Q. H	8402140331 8402140371 8402150183 8402150358 8402280404*	50-927 B 50-928 S 50-282 R 50-237 F CONTRACT	EDELMAN, M R EDFLMAN, M R EDELMAN, M R EDELMAN, M R EDELMAN, M R	D402030248 B402060048 B402060105 G402060358 G402060359	50-440 8 50-440 A 50-440 B 50-440 B 50-440 B
1004, 0 H 1204, 0 H 1204, 0 H	8402140001 8402140235 8402150120 8402150179 8402220070	50-395 8 50-395 8 50-395 8 50-395 6 50-395 8	DUNLAP, J M, DUPONT, B Q DURFEE, R, C, DURLACHER, J, E DURLACHER, J E,	8402246027* 8402020267* 8402170439 8402270280* 8402270283*	70-371 50-341 G NUREO FOIA FOIA	EDELMAN, M. R. EDELMAN, M. R. EDELMAN, M. R. EDELMAN, M. R. EDELMAN, M. R.	0402060378 0402060400 0402060411 0402060500 0402060507	50-440 9 50-440 9 50-440 8 50-440 9
TON, G U TON, G U TON, G U TON, G U CTOR, P G	8402220079 8402220227 8402240107 8402270174 8402270213	50-395 8 50-395 8 50-395 P 50-395 P NUREO	DURLACHER, J E DURR, J. P DURR, J. P DURR, J. P. DURR, J. P.	8402270288* 8402020318* 8402080361* 8402090337* 8402150004*	FOIA 50-334 Q 50-443 Q 50-354 Q 50-443 Q	edelman, m r edelman, m r edelman, m r edelman, m r edelman, m r	0402070280 x 0402170039 0402170149 0402170273 0402290166	50-440 G 50-440 G 50-440 G 50-440 G 50-440 G
Ctor. P. J. 8a. r. J. 80. c. v 80s. r 80s. r	8402170311 8402140330 8402040074* 8402150204 8402150213	NUREQ I&E 50-287 P 50-330 S 50-344 S	DURR.J P. DURR.J P DURR.J.P DURR.J.P DUVALL.D D	8402160282* 8402160339* 8402160454* 8402290195* 8402290299	50-423 0 50-317 0 50-309 0 50-387 0 50-312 8	edoar, O. L. Edoemorth, P Edoemorth, P Edoemorth, P Edoemorth, P	B4022200B4 B402070005 B402070023 B402150516 B402210022	50-537 Q CONTRACT CONTRACT CONTRACT CONTRACT
DDB.R T. DSON.J.P DSON.J.P. DSON.J.P. ERFLEIN.L.T	8402140284* 8402070365 8402070373* 8402220188* 8402020260*	50-397 Q 50-280 8 50-280 B GA979 50-333 Q	DHYER, P W DHYER, R E DYNNER, A R DYNNER, A. R DYNNER, A. R	8402020315 8402130365* 8402080167 8402100025 8402100175	50-382 6 50-322 0 50-322 0 50-322 0	EDLOH, J EDMONDB, D F EDWARDB, N H EDWARDB, N H EDWARDB, N H	G402150032 E402910115 E402230101* E402230108* E402230113*	70-2955 NJRCQ 50-354 A 50-354 A 50-354 A
ERFLEIN, L. T ERTY, J. F ERTY, J. F ERTY, J. F ERTY, J. F.	8402070221* 8402040200 8402070004* 8402270359 8402270362	50-333 G 50-443 G 50-273 G 50-320 P 50-508 D	DYNNER, A.R DYNNER, A.R DYNNER, A.R DYNNER, A.R DYNNER, A.R DYNNER, A.R	6402100175 6402160219 6402160219 6402160223* 6402160223*	50-322 0 50-322 0 50-322 0 50-322 0 50-322 0	EDWARDS, N.W. EDWARDS, N.W. EDWARDS, N.W. EDWARDS, N.W. EDWARDS, N.W. EDWARDS, N.W.	0402270116* 0402230120* 0402230126* 0402270096* 0402270103*	50-054 A 50-054 A 50-054 A 50-041 A
MANUS, H N MOVAN, T K XLTTLE, E, L XLTTLE, E, L, XLTTLE, E, L,	8402060337 8402080206* 8402230178 8402230186 8402230245	NUREG 40-1341 50-423 A 50-423 E 50-423 V	DYNNER, A R DYNNER, A R DYNNER, A R DYNNER, A R DYNNER, A R	8402210113 8402210113 8402220302 8402280213 8402280213	20-355 0 20-355 0 20-355 0 20-355 0	EDWARDS, N W EDWARDS, N W EGER, N. U EHASZ, J. L EICHBAUM, W M	B402270106* B402270107* B402270138 B4022740170* U402150436	50-341 A 50-341 A 70-1308 50-302 A State Prog

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBSION NUMBER	EUBJECT CATEOGRY
EISENHUT, D EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8305240101* 8103270357* 8211060310* 8303300416* 8304070057*	50-289 P 50-368 P 50-307 S 50-289 P FDIA	ELROD, S A ELROD, S A ELROD, S A ELSASSER, T ELSASSER, T	8402220582 8402280186* 8402280449* 8402270344* 8402270264*	50-338 B 50-335 Q 50-280 G 50-423 Q 50-423 Q	FARRAR, D L FARRAR, D L FARRAR, D L FARRAR, D L FARRAR, D L	8402220270# 8402270153# 8402270448# 8402290225# 8402290232#	50-373 q 50-373 q 50-295 q 50-374 q 50-374 q
EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G	8304140324* 8305110172* 8307250016* 8307080080* 8307120033*	FOIA 50-410 A 50-287 P 50-289 G FOIA	ELSASSER.T C. ELSASSER.T C ELSASSER.T C ELSASSER.T.C ELSASSER.T C	8402020171* 8402020348* 8402070170* 8402080270* 8402080328*	50-336	FARRELL, E V FABAND, A FABAND, A FABAND, A FAUSKE, H K	8402070372 8402020169# 8402070359# 8402220103 8402130131#	50-317 8 50-320 0 50-320 0 50-320 6 FOIA
EIBENHUT, D G EISENHUT, D G EISENHUT, D G EIBENHUT, D G	8311140287* 8312120029 8312120134 8312120160 8401130140*	50-382 A 50-10 P 50-247 F 50-275 S MISC	ELSASSER.T.C ELSASSER.T.C ELSASSER.T.C ELSASSER.T.C ELSBERGAS.V.J	8402240008 * 8402240139 * 8402270233 * 8402270275 * 8402280146 *	50-223 0 50-317 9 70-1100 50-336 0 50-358 9	FAY,C W FAY,C W FAY,C W FAY,C W FAY,C W	8402050137 8402070116 8402070186 8402080194 8402100222	50-266 P 50-266 F 50-266 P 50-266 P 50-266 F
EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8401170012 8401170015 8401170017 8401170036 8401170040	50-312 P 50-312 P 50-275 T 50-275 T 50-275 P	ELSEN, M J ELY, J F EMCH, R EMCH, R. L ENC, A	8402220232* 8402160117* 8402270644* 8402220016 8402060142*	27-48 50-336 G FDIA 50-195 P WASTE MOT	FAY,C W FAY,C W FAY,C W FAY,C W FAY,C W	8402100234* 8402130177 8402140227 8402150261 8402160181	50-266 F 50-266 P 50-266 P 50-266 P
EISENHUT.D Q EISENHUT.D Q EISENHUT.D Q EISENHUT.D Q,	8401170048 8401170050 8401170053 8401170057 8401170057	50-322 8 50-312 0 50-206 9 50-358 A 50-275 P	eng, pl eng, pl engelken, rh engelken, rh engelken, rh	8402020010# 8402270075# 8402270029# 8402270114# 8402270136#	50-461 0 50-454 9 50-344 F 50-344 0 50-344 0	FAY.C W FAY.C W FAY.T D. FEINBERG.J D FELTON.J M	8402210120 8402280433 8402060413* 8402160247 8401060163	50-266 # 50-301 9 50-463 A 50-322 9 50-463 F
EIBENHUT.D 0 EISENHUT.D 0 EISENHUT.D 0 EISENHUT.D 0	8401170064 8401170068 8402010021* 8402010121* 8402010178*	50-382 S 50-247 P 50-333 P 50-315 F 50-334 P	ENGLE, L B ENGLE, L B ENTWISLE, E B ENTWISLE, E B	8402160600 8402270626 8402060002* 8402280317* 8402280317*	50-33B P 50-33B P 50-395 G 50-170 G 50-170 G	FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M	8401170065 8402010364 8402010402 8402010418 8402010444	50-397 A 50-275 4 50-250 8 FOIA 50-250 P
EISENHUT.D Q EISENHUT.D Q EISENHUT.D Q EISENHUT.D Q	8402010207 8402010336* 8402010410 8402060386 8402060492	50-309 V 50-348 F 50-3 P 50-277 P MISC	entwisle, e B entwisle, e. B ercanbrack, s B erlin, B ernst, m L	8402280325* 8402280325* 8402170311 8402080414* 8402090441*	50-170 0 50-170 0 NUREO 50-237 0 FDIA	FCLTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8402010457 8402010468 8402010476 8402010484 8402010491	50-206 FOIA 50-443 A FOIA 50-209 F
EISENHUT.D G EISENHUT.D G EISENHUT.D G	8402070017 8402070533 8402070051* 8402070053* 8402070058*	1&E 50-341 F FOIA FOIA FDIA	ERNSTTHAL, H ESINDSA, G ETHERINGTON, H EVANS, C A EVANS, C A	8402170200 8402010301 8402270337* 8402220518* 8402220596*	FOIA XPORTLIC 50-320 C 50-285 G 50-313 G	FELTON, J M FELTON, J, M. FELTON, J M. FELTON, J M FELTON, J M	8402020033 8402040012 8402040284 8402040325 8402040332	50-329 A 71-9103 50-329 Q FBIA 50-409 Q
EIBENHUT.D G EIBENHUT.D G EIBENHUT.D G EIBENHUT.D G	8402090429* 8402130252 8402140525 8402160479 8402160480*	FOIA TOPREP MISC 50-443 A 50-449 A	EVANS, D EVANS, D D EVANS, L D EVANS, L D EVANS, L D	8402170242* 8402240373 8402220539* 8402220546* 8402220547*	50~373 G NUREO 50~413 E 50~413 E 50~413 E	FELTON, J. M FELTON, J. M. FELTON, J. M. FELTON, J. M. FELTON, J. M	8402070017 8402070027 8402070030 8402070038 8402070039	50-269 P FOIA FOIA 50-329 A 50-263 F
EISENHUT: D G EISENHUT: D G EISENHUT: D G EISENHUT: D. G	8402140653 8402170181 8402170504 8402230038* 8402230214*	50-528 F 50-289 P 50-284 F 50-424 A 50-409 F	EVANS, L D EVANS, L D EVANS, L D EVANS, L D, EVANS, L D.	8402220548* 8402220547* 8402220552* 8402220554* 8402220555*	50-413 E 50-413 E 50-413 E 50-413 E 50-413 E	FELTON, J M, FELTON, J M, FELTON, J M, FELTON, J M, FELTON, J M	8402070041 8402070048 8402070050 8402080007 8402080017	FOIA FOIA FOIA FOIA
EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8402230438* 8402240344 8402270017 8402280119* 8402270406	50-339 F 50-352 A 50-286 F FDIA 50-341 A	EVANS, L D. EVANS, L D. EVANS, L. D. EVANS, L. D. EVANS, L D.	8402220561 * 8402220566 * 8402220572 * 8402220575 * 8402220577 *	50-413 E 50-413 E 50-413 E 50-413 E 50-419 E	FELTON, J. M.	8402080019 8402080029 8402080033 8402080039 8402080043	50-250 8 50-265 8 FOIA FOIA FOIA
EISENHUT, D G. EISENHUT, D G. EISENHUT, P G EISTER, H M EJIMA, M	8402290408* 8402290446* 8402170510* 8402130150* 8402010131	50-341 A 50-275 P 50-286 F FDIA XPORTLIC	EVANS, L. D. EVANS, L. D EVANS, L. D EVANS, L. D EVANS, L. D	8402220580* 8402220581* 8402220585* 8402220587* 8402220591*	50-413 E 50-413 E 50-413 E 50-413 E 50-419 E	FELTON: J. M FELTON: J. M. FELTON: J. M FELTON: J. M. FELTON: J. M.	8402080087 8402080093 8402080098 8402080309 8402080314	FOIA 50-478 Q FOIA FOIA FOIA
EJIMA, M EL-BASSIONI, A ELAM, B D ELASSER, T C ELEY, G D	8402010374 8402060484 8402280352* 8402280273* 8402270271*	XPORTLIC NUREQ 50-287 0 50-245 0 50-322 0	EVANS, L. D. EVERTZ, H. A EWALD, B. C. FAGER, J. E FAIRCHENT, J. E	8402220593* 8402130226 8402080331 8402240233 8402240233	50-413 E 50-302 H 50-321 F NURE9 50-445 Q	FELTON, J. M FELTON, J. M. FELTON, J. M. FELTON, J. M. FELTON, J. M	8402080321 8402080381 8402080388 8402080394 8402080403	FOIA 50-366 P FOIA FOIA 50-358 A
ELLIOT.B J ELLIOT.C W ELLIOTT.S.D ELLIS,J ELLIS,J	8401100027* 8402220143 8402080313 8402040150 8402040153*	TGPREP 50~352 G FOIA 50~445 G 50~445 G	FALAHEE, J B FALCONER, D FALCONER, D FALEVITS, Z FALEVITS, Z,	8402020159* 8402140167* 8402280342* 8402100223* 8402150181*	50-327 A 50-267 G 50-267 G 50-440 G 50-358 G	FELTON, J. M.	8402080413 8402080431 8402080487 8402070003 8402070018	FOIA FOIA 50-3(1 A FOIA
EFF18' 7 EFF18' 7 EFF18' 9 EFF18' 9	8402070171 8402100066 8402150077 8402150144 8402150208	50-445 Q 50-445 T 50-445 Q 50-445 Q 50-445 Q	FALKENHEINER, D FALLB, Q B. FALZONE, R. R FALZONE, R R FANDUS, F	8402280331 8402290374 8402170100 8402170100 8402270207	50-458 Q MIGC 50-322 Q 50-322 Q MUREQ	FELTON, J. M. FELTON, J. M FELTON, J. M FELTON, J. M. FELTON, J. M.	8402070027 8402070081 8402070077 8402070143 8402070206	FOIA 50-498 Q 50-528 B 50-280 8 FOIA
ELLIS, J ELLIS, T S, ELLIS, T S, ELLIS, T, S	8402220347 8402100135* 8402100135* 8402140071 8402140071	50-445 Q 50-322 Q 50-322 Q 50-322 A 50-322 A	FARBER, M. J FARMER, F. G. FARMER, F. G. FARNEY, W. L. FARR, K. M	8402100138* 8402100352* 8402150538* 8402020086* 8402270532	50-483 G 50-243 P 50-220 P 50-358 G 50-255 H	FELTON: J. M FELTON: J. M. FELTON: J. M. FELTON: J. M. FELTON: J. M.	8402070408 8402100005 8402100447 8402100453 8402100458	50-206 P 50-327 A 50-260 S FUIA FUIA
ELLIS, T S. ELLIS, T S. ELROD, S A ELROD, S A ELROD, S A.	8402160254 8402160254 8402140303* 8402150342 8402220053	50-322 Q 50-322 Q 50-335 Q 50-250 S 50-250 S	FARRAR, D.L. FARRAR, D.L. FARRAR, D.L. FARRAR, D.L. FARRAR, D.L.	8402020345* 8402130531* 8402130534* 8402130543* 8402130554*	50-10 G 50-454 G 50-454 G 50-454 G 50-454 G	FELTON, J. M FELTON, J. M FELTON, J. M. FELTON, J. M. FELTON, J. M.	8402100451 8402130004 8402130013 8402130433 8402130498	FOIA 50-171 F FOIA FOIA

POHTUA	ACCEBBION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FELTON, J M FELTON, J M FELTON, J H FELTON, J H FELTON, J H FELTON, J H	8402140020 8402140486 8402170197 8402170208 8402170217	FDIA 50-287 P FDIA 50-250 S FDIA	FENTON D L FERGUSON C FERKIN Z FERKIN Z FERKIN Z FERKIN Z	8402010111 8402030219* 8402080188 8402080190* 8402020229	NUREG 50-528 8 50-352 G 50-352 G 50-352 0	FOLEY, T FOLEY, W J FOLEY, W J FONNER, R L FONNER, R L	8402080377* 8402140516* 8402140520* 8402020025 8402280386	50-247 0 50-287 P 50-287 P 40-2041 27-39
FELTON, J. H FELTON, J. H FELTON, J. H FELTON, J. H FELTON, J. H	8402170222 8402170449 8402170454 8402170465 8402170474	50~509 A Foia Foia 50~352 A Foia	FERNANDEZ.S FERRELL,C M FEY,F L FEY,F L FEY,F L	8402100190* 8402220300* 8402060444 8402080317* 8402160390	50-445 0 50-352 T 50-263 F 50-262 F 50-262 F	FONTANA, M FORD, J T FORD, J, T FORD, N FORNEY, W L	8402130077* 8402100158 8402140536 8402010466 8402220166*	FDIA 70-1201 70-1201 FDIA 50-358 Q
Felton, J H	8402210003 8402220123 8402220130 8402220144 8402220154	50-498	FIEDLER, P B, FIEDLER, P B, FIEDLER, P B FIEDLER, P B FIEDLER, P B	8402020305 8402040146 8402070120 8402070111 8402070341	50-219 8 50-219 P 50-219 P 50-219 F 50-219 P	FORSYTHE, R J FORTUNA, R A FORTUNA, R A FOSTER, C M FOSTER, C M	8402040109 8402140062* 8402140088* 8402010051* 8402020422	WASTE MOT FOIA FOIA XPORTLIC XPORTLIC
Felton, J H Felton, J H Felton, J H Felton, J H Felton, J H	8402230397 8402230397 8402230408 8402230411 8402230423	FOIA FOIA FOIA FOIA FOIA	FIEDLER, P B	8402140244 8402150225 8402150285 8402170159 8402170173	50-219 P 50-219 B 50-219 P 50-219 F 50-219 P	FOSTER, C M FOSTER, C M FOSTER, C M FOSTER, C M FOSTER, C M	8402100351* 8402130324* 8402130465 8402130472* 8402130868*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
Felton, J K Felton, J, K Felton, J, K Felton, J, K Felton, J, K	8402230429 8402230442 8402240043 8402240081 8402240086	FDIA FOIA FOIA 50-289 P 50-334 B	FIEDLER, P B FIEDLER, P B FIELDS, E N FIELDS, J S	8402220286 8402240126 8402240131 8402020216* 8402150264	50-219 P 50-219 G 50-219 P 50-261 G 50-387 R	FOSTER, C M FOSTER, D O FOSTER, D O FOSTER, D O FOSTER, D O	8402210034 8402030400 8402140238 8402140480 8402140498*	XPORTLIC 50-424 K 50-424 A 50-424 M 50-424 Q
Felton: J H Felton: J, H Felton: J H Felton: J K Felton: J K	8402240153 8402240175 8402240160 8402240199 8402240207	50-382	FIELDB.J B FIELDB.J B FILBURN.T FILBURN.T FINAMORE.B A	8402150366 8402270342 8402220398 8402220398 8402280149	50-387 0 50-387 P 50-336 S 50-336 B 50-537 0	FOSTER.D O FOSTER.D O FOSTER.D O FOSTER.D O FOSTER.D O	6402150241 6402150405 6402160376 6402160476 6402260376	50-424 S 50-424 C 50-424 C 50-424 C
FELTON: J. H FELTON: J H FELTON: J H FELTON: J H	8402240214 8402240216 8402240263 8402240277 8402240283	50-315 S 50-220 P FOIA 50-352 A FOIA	FINAMORE, B A	8402080149 8402080152* 8402080152* 8402080152* 8402080166*	50-537	FOSTER, J E FOSTER, J E FOSTER, W E FOSTER, W E FOTIADES, G	8402040348* 8402100045* 8402100141* 8402820381* 8402150331*	50-409 0 FDIA 97999 97999 60-329 A
TERMIN O TA TELONIAL TA TELONIAL TA TELONIAL TA TELONIAL TA TELONIAL TA	8402240293 8402240309 8402240315 8402240328 8402240340	FOIA 50-287 P 50-352 E FOIA FOIA	FINAMORE, B A. FINAMORE, B. A. FINCH, P T FINDLEY, D E FINKEL, A E	8402080166* 8402080166* 8402080440 8402280682* 8402160397*	50-537 0 50-537 9 71-9032 CONTRACT 50-352 0	FOWLER, R D FRAGULA, J FRALEY, R. F FRANCE, G M FRANCIS, E	8402030077 6402060484 8201200678* 8402150254* 8402170445	NUREO NUREO FOIA 50-6 G 40-8566
TETON: J. H. TETON: J. H. TETON: J. H. TETON: J. H. TETON: J. H.	8402240366 8402270001 8402270009 8402270036 8402270046	F01A 50-344 F F01A 50-10 F 50-320 P	FINKELIA E FIORELLIA FIRTHIK J. FISCHERID. FISCHERID C	8402290316# 8402090428# 8402230103# 8402100403 8402080008	50-443 G FOIA TOPREP 50-311 P 50-272 P	FRANK,L FRANK,L FRANK,L FRANK,L FRATIANNI,B C	8402070112* 8402290140* 8402290179* 8402290206* 8402080161	State Prog 50-269 G 50-269 G 50-269 G 50-269 G
LETION' A R LETION' A R LETION' A R LETION' A R LETION' A' Y'	8402270051 8402270072 8402270184 8402270250 8402270263	50-382 Q 50-528 A FOIA FOIA 50-247 D	Fischer.d C Fish, H Fish, R F, Fisher, C R. Fisher, W. C	8402230005 8402100294* 8402170195 8402280104 8402100454	50-272 F COMMISSION 50-275 B TOPREP FOIA	FREDERICK, A J FREEMAN, M D FREEMAN, M D FREEMAN, B D FREECO, A	8402220293* 8402210467 8402210475 8402090117* 8402170503	50-219 P 40-8768 40-8768 50-438 A 50-443 A
Felton, J. H Felton, J. H. Felton, J. H Felton, J. H Felton, J. H	8402270284 8402270302 8402270304 8402270369 8402270459	FOIA 50-341 T 50-413 G 50-287 P 50-358 T	FITZGERALD, J A FITZGERALD, J A FITZGERALD, J. A FITZGERALD, J A FITZGERALD, J, A	8204160195* 8402060043 8402130538* 8402130544* 8402130549*	FOIA FOIA 50-289 P 50-289 F 50-289 F	FRIEDERICHS, S. FRIEDERICHS, S FRIEDMAN FRIMM, R. W FRISHMAN, B	8401190528* 8402150435* 8402090327 8402070374 8402020189	50-412 A 50-352 A 18E 50-305 F WASTE MGT
FELTON: J. H FELTON: J. H FELTON: J. H FELTON: J. H	8402270476 8402270485 8402270487 8402270494 8402270503	F01A F01A 50-277 P 50-329 A F01A	FITZGERALD.J A Flack.e Flack.e Flack.e Flack.e	8402270380* 8402020291 8402030384 840214007 <i>9</i> 8402170165	50~498 A 50~250 B 1&E 40~279 40~6720	FRISHMAN, 8 FRIEHMAN, 8 FRITZ, D M FRYE, J. H FRYE, J. H	84020305f2 8402040140 8402010347* 8402080176 8402140082	HASTE MOT HASTE MOT 40-8463 50-70 0 50-70 0
FELTON, J. H FELTON, J. H FELTON, J. H FELTON, J. H FELTON, J. H	8402270304 8402270323 8402270331 8402270333 8402270333	FDIA 40-7580 50-329 0 50-255 H FOIA	FLEENOR: C, FLEENOR: C FLEENOR: C FLEENOR: C, FLEENOR: C	8402010058 840208044# 8402140024 8402170062 8402217417	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	FRYE, J.H. FRYE, J.H. FRYE, J.H FRYE, J.H.	8402240053 8402260375 8402260443 8402260450 8402270085	50-70 9 50-142 9 40-2061 50-142 0 50-70 9
FILTON, J. M.	8402270543 8402270544 6402270548 8402270568 8402270573	FOIA 50-528 G FOIA FOIA FOIA	FLEENOR, C. FLEENOR, C. FLEENOR, G FLEIBCHMANN, R FLEIBCHMANN, R,	8402230269 8402280633 8402280688 8309070010* 8402130223	CONTRACT CONTRACT CONTRACT 50~277 S 50~278 P	FRYLING, R FUHRMAN, G R FUHRMAN, G R FULLER, C. FULLER, C	8402220115 8402040123 8402270285 8402040129 8402210197	50-354 0 50-317 5 50-317 8 50-267 R 50-267 R
REPORT J. N. RELYON J. H.	8402270639 8402280018 8402280116 8402280094 8402270002	FOIA 50-471 A 50-250 P FDIA 50-537 U	FLEIGHER, Z. B. FLETCHER, C D. FLETCHER, J C. FLIPPO, T. A FLOREK, D.	8402080184 8402080032 8402240173 8402070162* 8402080374*	50-247 0 50-249 P 50-320 P 50-382 0 50-387 0	FULLER: C FULLER: C FULLER: C FULLER: C FUNCHES: J	8402280379* 8402280383* 8402280385* 8402280385* 9303090697*	
FELTON, J. H. FELTON, J. H. FELTON, J. M. FELTON, J. M. FELTON, J. M.	8402290067 6402290410 6402290420 6402290431 8402290446	FOIA FOIA FOIA 30-440 A FOIA	FLOREK, D J. FLOREK, B J FLORY, B FLOYD, D R FLOYD, P R	8402080375* 8402160481* 8402210398 8402170312 8402210088*	50-38B Q 50-38B Q MISC WASTE MOT CONTRACT	FUNCHES, J L FUNCHES, J L FUGUA, D M QAD, R K GAD, R K,	8201190717* 8402080465* 8402080014 8402070004* 8402130283	FOIA FOIA 50-293 G 50-443 G
BION, J. M. BII. D. E. BII. D. E. BII. D. E. DSTERSTOCK, J.	8402290455 8311030099 8402070348 8402270367* 8402260482*	50-275 9 50-128 8 50-128 F 50-128 9 CONTRACT	FLOYD, W. C. FLOYD, W. C. FLOYD, W. C. FLYNN, M. J. FOLEY, M. O.	8401240470* 8402140027* 8402140035* 8402170253 8402080089*	50-250 P 50-250 P 50-250 P CONTRAGT FOIA	GAD.R K GAD.R K GAD.R.K GAD.R.K GAD.R.K	8402130283 8402130283 8402130283 8402130290 8402220200	50-443 G

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
GAD, R X GAD, R X GAD, R K GAD, R K GAD, R K	8402220200* 8402220224* 8402220224* 8402220230* 8402220230*	90-309 0 50-309 0 90-309 0 90-309 0 50-309 0	GARY: R J GARY: R. J GARY: R J GARY: R J GARY: R J	8402140333 8402170282 8402220033 8402220171 8402220420	50-446 8 50-445 8 50-445 5 50-445 8 50-445 8	OILINSKY, V GILLILAND, J T GILLIS, J C GILLIS, J C	8402270289* 8402290084 8402150327 8402130089* 8402100294*	50~327 0 50~275 9 50~261 8 FOTA COMMISSION
GADLER, S J GAGLIANDO, J GAGLIANDO, J GAGLIANDO, J E GAGLIANDO, J E	8402010318* 8402150188 8402220509 8402010129 8402030208	50-313 G 50-313 G 50-313 H	GARY, R. J GARY, R. J GARY, R. J GASSER, E R GAULT, G. W	8402220545 8402280268 8402280493 8402060488* 8402220096	50-445 S 50-445 S 50-445 S CONTRACT 50-327 F	GILMAN,B A GILMAN,B.A GILOY,E W GILRAY,J W GIRARD,E H	8402010384* 8402240075 8402080198* 8402090363* 8402140443*	50-247 U 50-247 U 50-434 P FDIA 50-239 P
GAGLIARDO, J E	8402030370	50-313 0	GAUTAM, A	8402170187#	50-454 G	GIBCLON, J M	8402070368	30-275 B
GAGLIARDO, J E	8402100238	50-482 0	GAUTAM, A S	8402100215#	50-456 G	GIUFFRIDA, L D	8402280713	COMMISSION
GAGLIARDO, J E	8402160408	50-285 0	GAVIGAN, F X.	8402270212	50-537 A	GLASSER, H	8402090340*	FOLA
GAGLIARDO, J E	8402220237	50-285 0	GAYNOR, R K	8402220006	27-39	GLENN, J	8402080329	ILE
GAGLIARDO, J E	8402220271	50-313 0	GEARS, G.	8402170518	50-277 P	GLENN, J	8402220212	ILE
GAGLIARDD.J E GAGLIARDD.J E GAGLIARDD.J E GAGLIARDD.J E GAGLIARDD.J E	8402220274 8402220321 8402220337 8402220338 8402220355	50-72 0 50-285 0 50-285 0 50-313 0 50-313 0	GEBBIE, K M GEIER, J D GEIER, J D GEIER, J D.	8402070110 8402070152 8402130336 8402150317 8402170001	8tate Prog 50-461 E 50-461 E 50-461 E 50-461 F	GLISSMAN, M GLOERSEN, W. P GLOUDEMANS, J R. GODDARD, R J GODDARD, R J	8402240041 8402150247* 8402230105* 8402010200 8402020024	50-315 F 50-454 & Toprep 50-46! & 50-153 &
GAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E	8402220371 8402220383 8402220441 8402220444 8402220448	50-482 Q 50-313 Q 50-482 Q 50-482 Q 50-285 Q	GEIER, J D GEIER, J D GEORGE, H GEORGE, J D GEORGE, L D.	8402230088 8402240007 8402270031* 8402150421* 8402160231*	50-461 A 50-461 E 50-289 P 71-133 50-454 9	GODDARD, R. J GODDARD, R. J GODDARD, R. J GODDARD, R. J GODDARD, R. J	8402140202 8402220254 8402220258 8402220262* 8402220343	50-155 9 50-322 9 50-322 9 50-461 8
GAGLIARDD.J E	8402220468	50-313 Q	GEOROIEY, O B	8402140345*	50-410 0	GDDDARD,R J	8402290104	50-469 9
GAGLIARDD.J E	8402220471	50-462 Q	GERETY, H F,	8402170130	50-219 J	GDDWIN,A V.	8402030354	PR
GAGLIARDD.J E	8402220478	50-313 Q	GERETY, H F,	8402230131	50-219 J	GDDY,A T	8402020224#	70-371
GAGLIARDD.J E	8402220474	50-482 Q	GERRETS, T. F	8402010088	50-382 8	GDDY,A T	8402020354#	50-293 9
GAGLIARDD.J E	8402220505	50-285 Q	GERRETS, T F	8402010148	50-382 8	GODY,A T	8402290317#	50-277 6
GAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E	8402220562 8402220578 8402270152 8402270163 8402270327	50-482	GERRETS, T. F GERRETS, T. F GERRETS, T. F. GERRETS, T. F GERRETS, T. F	8402050418 8402050468 8402140056 8402140060 84021400272	50-382 8 50-382 8 50-382 8 50-382 8	GDGGIN, A GDGOL, E. GDGOL, E M GDGDL, E M GDLDBERG, J. H	8402130434 8402140242 8312220247* 8312220247* 8402220034	FOIA 50-295 0 50-454 A 50-454 A 50-498 A
GAINEY, D	8402150244	50-261 F	GERRETS, T F GERRETS, T F GERRETS, T F GERRETS, T F. GERRETS, T F.	8402140319	50-382 8	ODLDBERG, J H	8402220037*	50-498 K
GALL, W R	8402070480	ACRS		8402140395	50-382 8	GOLDBERG, J, R	8402010196	50-344 9
GALL, W. R	8402070480	ACRS		8402140431	50-382 8	GOLDBERG, J, R	8402010204	50-344 9
GALL, W R	8402070497	ACRS		8402170019	50-382 8	GOLDBERG, J R	8402010254	50-344 9
GALL, W R	8402070497	ACRS		8402170229	50-382 8	GOLDBERG, J R.	8402140006	50-289 9
gall, W. R	8402070534	ACRS	OERRETS,T F	8402210207#	50-382 0	odldberg, J R	8402270035	50-299 0
Gall, W. R	8402070534	ACRS	GERRETS,T.F	8402280017	50-382 8	Goldberg, R.	8402070222	50-440 M
Gall, W. S	8402070581*	71-512	GERRETS,T F.	8402280292	50-382 8	Goldberg, R	8402070222	50-440 M
Gallo, J	8402030154	50-155 G	GEST.R E	8402130427	70-754	Goldberg, R	8402240052	50-440 M
Gallo, J	8402030154	50-155 G	GIACOBBE,F S	8402280352#	50-289 0	Goldberg, R.	8402240052	50-440 M
GALLO, J.	8402140210#	50-155 G	GIBBONS, T D	8402140183*	50-348 Q	GOLDEN, M P	8402020109	50-345 J
GALLO, J.	8402140215#	50-155 G	GIBBONE, T D.	8402150014*	50-269 Q	GOLDEN, M. P.	8402090335	50-285 J
GALLO, J	8402140215#	50-155 G	GIBBON, A F.	8402060101	27-47	GOLDEN, M P	8402160327	50-272 J
GALLO, J	8402210345	50-155 G	GIBBON, A F	8402280570*	50-416 Q	GOLDEN, B	8402010082	XPORTLIC
GALLO, J	8402210345	50-155 G	GIBBON, J. 1.	8402060044	HABTE MOT	GOLDSMITH, R.	8402150306*	50-307 H
GALLO, J GALLO, J GALLO, J GALLO, J	6402210347* 6402210347* 6402210353* 6402210353* 8402230138	50-155 Q 50-155 Q 50-155 Q 50-155 Q 50-155 Q	GIEBLER.C W GIEBLER.C.W GIEBLER.C W. GIEBLER.C W GIEBLER.C W	8402030374 8402060460 8402070223 8402070279 8402070327	50-305 8 50-305 P 50-305 V 50-305 P 50-305 F	QDLDSMITH,R, QDLLER,K.R. QOLLER,K.R QDLLER,K.R QDLLER,K.R.	8402150510* 7907050105* 8402090451* 8402090453* 8402090456*	50-309 H FOIA FOIA FOIA FOIA
GALLO, J GALLO, R GALLO, R GALLO, R M. GALLO, R M	8402230138 8402240038* 8402240046* 8402020127* 8402160301*	50-155 0 50-293 0 50-293 0 50-293 0 50-443 0 50-271 0	GIESLER, C W GIESLER, C W GIESLER, C W GIESLER, C W GIESLER, C W.	6402070341 8402080228 8402080239* 8402140078 8402140435	50-305 G 50-305 P 50-305 F 50-305 R 50-305 F	GOLLER, K. R GOLLER, K. R. GOLLER, K. R. GONTZ, B. J GOODIE, J. B.	8402090966* 8402130009* 8402130236* 8402140150 8402160237	FOIA FOIA FOIA 50-352 5 27-37
CALLO, R. M	8402210444	50-293 G	GIEBLER, C W	8402150230	50-305 P	Goddman, L. 8.	8402060432*	50-409 F
CALLUP, D. R.	8402240207*	FOIA	GIEBLER, C W	8402220442	50-305 P	Goddman, L. 8.	8402080221	50-409 8
CARCIA, P. J.	8402010292	40-8084	GIEBLER, C W.	6402270174	50-305 P	Goddman, L. 8.	8402090271	50-409 8
CARCIA, P. J.	8402220047	40-8084	GIEBLER, C W.	6402270257*	50-305 P	Goddman, L. 8	8402160267	50-409 9
CARDE, Ø. P.	8402070028	50-329 A	GIEBLER, C W	8402280210	50-305 P	Goddman, L. 8	8402160295*	50-409 F
GARDE, B P.	8402070136	50-280 S	GIESLER, J V.	8402210215	QA999	A HAMBEDO	E401170073*	50-397 A
	8402130108*	50-528 Q	GILBERT, L. D.	8402140002	50-445 T	OLDWIN, B. J.	8402170005	50-400 B
	8402240148	50-382 G	GILBERT, L D.	8402220372*	50-458 Q	GOLDWIN, B. J.	8402170279	50-400 \$
	8402240277	FDIA	GILBERT, L D.	8402270074*	50-445 O	GOLDWIN, G. M.	8402010115	NUREV
	8402270471	50-329 A	GILBERT, R A.	8402010061	50-237 P	GOLDWIN, W. L.	8402100019	70-1151
OARDE, B. P	8402270536	50~327 G	GILBERT,R.A	84020900BB*	50-322 A	ODRDON, M.	8402270346	Habie Mi
GARDNER, B. J.	8402130143*	50~526 A	GILBERT,R.A.	8402090190*	50-322 A	ODRSKI, J. P.	8402060245*	50-309 F
GARDNER, R. N	8402020256*	50~327 G	GILBERT,R.A.	8402090191	50-249 G	ODSSELINO, S. R.	8402240007*	50-206 F
GARDNER, R. N	8402070131*	50~329 G	GILBERT,R.A	8402280345	50-249 P	ODSSICK, L. V.	8402280106*	40-1341
GARDNER, R. N	8402290221*	50~329 Q	GILDENHORN,A.J	8402060465	CONTRACT	ODULD, S. E.	8402180564	Habie Mi
GARDNER, B L	8402290064	FDIA	GILDENHORN, A. J	8402040475	CONTRACT	GRABER, L. D.	8402010488	FOIA
GAREIA, P U	8402230203	40-1162	GILDENHORN, A. J	8402040504	CONTRACT	Graber, L. D.	8402100457	FOIA
GARNER, L W	8402280081*	50-324 G	GILDENHORN, A. J.	8402040515	CONTRACT	Graber, L. D.	8402230425	FOIA
GARRICK, J	8402070262*	50-443 A	GILDENHORN, A. J	8402040545	CONTRACT	Graber, L. D.	8402240201	50-315 E
GARRITY, J H	8402290304	50-309 P	GILDENHORN, A. J	8402170147	CONTRACT	Graber, L. D.	8402270479	FOIA
GARRITY, J H	8402290308*	50-307 P	oildenhorn, A.J	8402210347	CONTRACT	GRAESBER, K, L	8402060135	50-295 8
GARY, R J.	8402070008*	50-445 G	Gildner, M. L	8402130327*	50-440 G	GRAESBER, K, L,	8402070127	50-295 9
GARY, R J.	8402070088	50-445 A	Gilinsky, V.	8402080042*	FOIA	GRAESBER, K, L,	8402070157	50-304 9
GARY, R, J.	8402100435	70-2792	Gilinsky, V.	8402080142	50-142 G	GRAESBER, K, L	8402070164	50-304 9
GARY, R, J.	8402130156	50-445 A	Gilinsky, V	8402170027*	COMMISSION	GRAESBER, K, L	8402070172	50-295 6

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
Maesser. K L Maesser. K L Maesser. K L Maesser. K L Maesser. K L Maesser. K L	8402130439 8402140134 8402170204 8402220154 8402220205	50-295 R 50-295 F 50-304 S 50-295 B 50-304 B	GUINN, F K GUINN, P R GUINN, P R GUINN, P R GUINN, P R	8402280483 8104280232* 8402070234* 8402070376* 8402270617*	70-143 F01A F01A F01A F01A	HAASIM N HAASSIN P HACKNEY, C A HAGAN, T F HAGAN, T, F	8402010073* 8007110548* 8402010132* 8402010048* 8402010351*	CONTRACT 50-498 A 50-313 Q 50-498 Q CONTRACT
Maesser, k l Maham, m. J Maham, m. J Maham, m. J Mang, R. A	8402220413 8207090028* 8210130553* 840228035 <i>2</i> * 8402020191*	50-295 8 50-289 P 50-289 P 50-289 G 50-410 G	GUINN, PR GULBRANBEN, E A GULBRANBEN, E A GULDEMOND, W GULDEMOND, W	8402270619* 8402290478* 8402290479* 8402170242* 8402220049	FOIA 50-320 G 50-320 G 50-373 G 50-373 S	HAGAN, T F HAGAN, T F HAGAN, T F HAGAN, T F HAGAN, T, F	8402010362* 8402010439* 8402020465* 8402030207* 8402030428*	CONTRACT CONTRACT CONTRACT CONTRACT
SANT. C	8402100018*	FOIA	GULDEMOND, W	8402220557	50-373 9	HAGAN, T F	8402060471*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
SANT. J. H	8402020127*	50-443 G	GUMBLE, F W	8402030460	50-286 9	HAGAN, T F	8402060482*	
SANT. J. H	8402140345*	50-410 G	GUNBY, A L	8402010150*	GA777	HAGAN, T. F	8402060488*	
SANT. W B	8402270392*	50-282 G	GUNDERSON, R D	8402130024*	50-528 9	HAGAN, T F	8402060520*	
SAY, E H	8402080361*	50-443 G	GUSTAVE, R	8402030096*	CONTRACT	HAGAN, T F	8402060539*	
PAY, E. H	8402140282*	50-423 G	GUSTAVE,R	8402230272*	CONTRACT CONTRACT CONTRACT 50-47B A CONTRACT	HAGAN, T F	8402060547*	CONTRACT
PAY, E. H	8402240239*	50-220 P	GUSTAVE,R P	8402100462*		HAGAN, T F	8402140683*	CONTRACT
REEN. J D	8402100190*	50-445 G	GUSTAVE,R P	8402010037*		HAGAN, T F	8402160685*	CONTRACT
REEN. J W	8402020042	WABTE MOT	GUSTAVE,R P	8402010040*		HAGAN, T F	8402170012*	CONTRACT
PEENE, T	8402140232*	50-321 P	GUSTAVE,R P	8402010043*		HAGAN, T F	8402170016*	CONTRACT
uene. T	8402240055	50-321 F	GUSTAVE,R P	8402010090*	CONTRACT	HAGAN, T F.	8402170030*	CONTRACT
Repe. T a	8402280607	TOPREP	GUSTAVE,R P	8402010054*	CONTRACT	HAGAN, T F.	8402170158*	CONTRACT
Reprorn. R a	8402160063*	CONTRACT	GUSTAVE,R P	8402010062*	CONTRACT	HAGAN, T F.	8402210351*	CONTRACT
Peenlee. E a	8402170012*	CONTRACT	GUSTAVE,R P	8402010065*	CONTRACT	HAGAN, T F.	8402230273*	CONTRACT
Reenlee. E, a	8402170016*	CONTRACT	GUSTAVE,R P	8402010073*	CONTRACT	HAGAN, T F	8402230275*	CONTRACT
REENMAN, E. O	8402030430*	50-293 G	GUBTAVE.R P	8402010081#	CONTRACT CONTRACT CONTRACT 50-346 F CONTRACT	HAGAN: T F	8402240231*	CONTRACT
REENMAN, E. O	8402070397	70-364	GUBTAVE.R P	8402010110#		HAGAN: T F	8402240256*	CONTRACT
REENMAN, E. O	8402070604*	70-364	GUBTAVE.R P	8402010176#		HAGEY: H A	8402080316*	FOIA
REENMAN, E. O	8402220318*	50-309 G	GUBTAVE.R P	8402010273#		HAGEY: H A	8402160686	CONTRACT
REENMAN, E. O	8402230142	70-364	GUBTAVE.R P	8402010328#		HAGGARD: K. A	8402170248	WASTE MOT
RENMAN.E O REVES, J REVES, J REVES, J T REVER, L R	8402280455 8402170006 8402170011 8402150404 8402150254*	TWE MOT WASTE MOT WASTE MOT G	GUSTAVE,R.P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P	8402010333* 8402010342* 8402010359* 8402010389* 8402020470*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	HAINKEL, J J HAIRSTON, W G HAIRSTON, W G HAIRSTON, W G HAIRSTON, W G	8402020087 8402030447* 8402030453* 8402030456* 8402060438*	WASTE MOT 50-348 S 50-348 S 50-348 S 50-348 S
KOER, L. R.	8402150257*	50-10 G	GUSTAVE,R P	8402030067*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	HAIRSTON, W. G	8402040442*	50-348 8
KOER, L. R.	8402150268*	50-331 G	GUSTAVE,R.P.	8402030352*		HAIRSTON, W. G	8402040448*	50-348 8
KOER, L. R.	8402270226*	50-461 G	GUSTAVE,R P	8402060184*		HAIRSTON, W. G	8402170089	50-364 R
KOER, L. R.	8402270361*	50-255 G	GUSTAVE,R P	8402060502*		HAIRSTON, W. G	8402170127	50-348 R
KOER, L. R.	8402270392*	50-282 G	GUSTAVE,R P	8402060524*		HAIRSTON, W. G	8402170172	50-364 8
egg, M. I Egg, H. J. Egory, H 9 Eimann L Evier, B L	8402160399* 8402240050* 8402010111 8402270207 8104280270*	50-352 G 50-219 G NUREG NUREG FOIA	GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P.	8402060534* 6402060542* 6402060556* 6402060567* 6402060615*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT A CONTRACT	HAIRSTON, W G HALE, C J HALE, G L HALL, D. P	8402270262 8402220398* 8402220508* 8402080479* 8402030227	50-364 8 DA777 GA777 50-335 G 50-461 S
WIER, BL	8402270201*	FOIA	GUSTAVE, R P	8402070108*	CONTRACT	HALL, D. P	8402040052	50-461 R
WIER, BL	8402270208*	FOIA	GUSTAVE, R. P	8402070123*	CONTRACT	HALL, D. P.	8402040428	50-461 S
WIER, BL	8402270217*	FOIA	GUSTAVE, R P	8402070276*	CONTRACT	HALL, D. P.	8402170143	50-461 G
WIER, BL	8402270230*	FOIA	GUSTAVE, R P	8402070307*	CONTRACT	HALL, D. P.	8402270021	50-461 B
WIER, BL	8402270236*	FOIA	GUSTAVE, R P	8402070323*	CONTRACT	HALL, D. P.	8402270025	50-461 B
FFIN.T T	8402150544	Wable Mot	QUSTAVE, R P	8402070343*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	HALL, D P	8402270261	50-461 8
FFIN.T.T	8402160465	Wable Mot	GUSTAVE, R P	8402070418*		HALL, D P	8402270276	50-461 B
REG.B.K.	8402070466#	Foia	GUSTAVE, R P	8402080440*		HALL, R E	8402060484	NUREG
HIARD.T	8402080077#	50-528 R	GUSTAVE, R P	8402080491*		HALL, R E	8402220367*	50-313 G
ME, J.	8402080398	50-263 8	GUSTAVE, R, P	8402080497*		HALLER, N M	8402070114*	50-438 A
OSCUP, O M. DSSMAN, H OSSMAN, L OSSMAN, L.	8402270336 8402030204 8402100152 8402080491 8402090228#	50-247 B 50-460 9 50-244 9 FOIA FOIA	GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P	8402090526# 8402090548# 8402090592# 8402100093# 8402100357#	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	HALLER, N M HALLFORD, J E HAMEL, D B HAMEL, D B, HAMILTON, P.	8402090423* 8402100190* 8402070015 8402140447 8402220010	FO1A 50-445 G 50-331 S 50-331 S 50-273 R
SSMAM.L	8402090232*	F01A	GUSTAVE.R.P	8402100382*	CONTRACT	HAMILTON, P. J	8402080343	50-293 S
OTEMHU!S.M	8402030052	50-325 P	GUSTAVE.R.P.	8402100415*	CONTRACT	HAMLIN, J. B	8402080308	FOIA
OTEMHU!S.M	8402170086	50-305 P	GUSTAVE.R.P	8402100456*	CONTRACT	HAMMER, M. F	8402100020	50-263 S
MDSTROM.R	8402130171*	50-483 F	GUSTAVE.R.P	8402130041*	CONTRACT	HAMMER, M. F	8402140382	50-263 S
MDSTROM.R	8402130173*	50-483 F	GUSTAVE.R.P	8402130087*	CONTRACT	HAMMITT, H. A	8402270517	40-7580
MOSTROM, R	8402130178#	50-483 F	QUBTAVE.R P	8402160063*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	HAN.T Y.	8402130081*	FOIA
MA, L. T.	8402100179	50-321 P	GUBTAVE.R P.	8402179031*		HAN.T.Y	8402130077*	FOIA
WA, L. T.	8402140441	50-321 P	GUBTAVE.R P	8402170063*		HANAUER.B H	8105120144*	50-382 G
WA, L. T.	8402150197	50-321 P	GUBTAVE.R P	8402170484*		HANNETT.B.A	8402010341	XPORTLIC
WA, C. T.	8402150277#	50-366 G	GUBTAVE.R P	8402210014*		HANNETT.B.A	8402010458	XPORTLIC
WALL T.	8402150288	50-364 G	GUSTAVE, R P	8402210460*	CONTRACT	HANNETT, B A	8402030123	XPORTLIC
WALL T.	8402160228	50-321 P	GUSTAVE, R P	8402210439*	CONTRACT		8402090543	XPORTLIC
WALL T	8402240145	50-321 P	GUSTAVE, R, P	8402210476*	CONTRACT		8402100392	XPORTLIC
WALL T	8402270215	50-321 P	GUSTAVE, R, P	8402230446*	CONTRACT		8402130408*	XPORTLIC
WALL T.	8402280466*	50-366 G	GUSTAVE, R, P	8402240379*	CONTRACT		8402140601	XPORTLIC
Male T	8402270100	50-321 F	GUSTAVE, R P	8402280642*	CONTRACT	Hannett.b a	8402140410	XPORTLIC PROJ PROJ PROJ PROJ 50-352 D
Misial T.	8402150266	50-320 H	GUSTAVE, R. P	8402280692*	CONTRACT	Harnum.w.H	8402140412	
LDAR	8402160260	50-413 9	GUSTAVE, R P,	8402280672*	CONTRACT	Harnum.w.H	8402280444	
LLAP N	8402160502*	50-424 C	GUSTIN, H L	8402080040*	50-265 G	Hannum.w.H,	8402280474	
LLAP N	8402160526*	50-424 C	GUTHRIE, S	8402170242*	50-373 G	Hanbler.g M.	8402060080	
M. F. K M. F. K M. F. K M. F. K	8402070527 8402140425 8402140463 8402280040 8402280303*	70-143 70-143 70-143 70-143 70-143	GUTTMAN, J GWYNN, T P GWYNN, T P. Haaberg, B. Haagar, E M,	8402160387* 8402020086* 8402220166* 8402160462* 8402270384	50~255 P 50~358 Q 50~358 Q 50~245 P 50~461 H	HANSLER, 9 M. HANSON, W.A. HARBOUR, J. HARDGROVE, T. W. HARDGROVE, T. W.	8402270253 8402140345* 8402030204 8402210286 8402230163	50-352 D 50-410 G 50-460 G 40-2257 40-2257

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHDR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HARDIN, A K HARDIN, C M HARDING, M R HARDING, M R HARPSTER, T L	8402140439 8402210172* 8402030389 8402080220 8209290283*	50-261 S CONTRACT 50-328 S 50-327 S 50-382 0	HAYNES, J G C RENYAH C RENYAH C RENYAH C RENYAH C RENYAH	8402070224 8402130166 8402130169 8402130279 8402130333	50-206 F 50-362 S 50-362 S 50-362 S 50-361 S	HICKEY, J W HICKEY, J W HICKEY, J W HICKEY, J W	8402090305* 8402090354* 8402090350* 8402270278* 84022140065	FOIA FOIA FOIA FOIA 50-445 Q
HARRELL, E W	8402140186	50-338 9	D LEBAYAAH	8402130346	50-206 8	HIERZER, Q A	8402030241	Hable Hol
HARRELL, E W	8402140297	50-338 9	O LEBAYAAH	8402130387	50-361 8	HIERZER, G A	8402150140	Hable Hol
HARRELL, E W	8402140406	50-338 6	O LEBAYAAH	8402130440	50-362 8	HIGGINBOTHAM, L	8402010381	Hable Hol
HARRELL, E W	840222009	50-338 8	O LEBAYAAH	8402130509	50-362 8	HIGGINBOTHAM, L	8402030113	Hable Hol
HARR INGTON	8402220010	50-273 8	O LEBAYAAH	8402140163	50-362 8	HIGGINBOTHAM, L	8402030119	Hable Hol
HARRINGTON, R HARRINGTON, W D HARRINGTON, W D HARRINGTON, W D HARRINGTON, W D	8402060457	NUREO	D LEBNYAH	8402150218	50-362 8	HIGGINBOTHAM, L	8402100262	WASTE NOT
	8402080343	50-273 S	D LEBNYAH	8402160386	50-361 8	HIGGINBOTHAM, L	8402100413	WASTE NOT
	8402090182	50-273 P	D LEBNYAH	8402210244	50-361 8	HIGGINBOTHAM, L	8402100417	WASTE NOT
	8402090253	50-273 F	D LEBNYAH	8402210245	50-361 8	HIGGINBOTHAM, L	8402100419	WASTE NOT
	8402130341	50-273 F	D LEBNYAH	8402230148	50-361 8	HIGGINBOTHAM, L	8402170305	27-48
HARRINGTON, W D	8402140234* 8402140460 8402160423 8402230145 8402270271	50-293	HAYNES, J G HAYNES, J G HAYNES, R. C HAYS, J K HAZLE, A J	8402280413 8402290138 8402140033* 8402010407* 8402100422	50-361 8 50-206 8 FOIA 50-250 8 WASTE MOT	HIGGINBOTHAM, L HILDENBRAND, P HILDENBRAND, P HILL, D HILL, D	8402270534 8402210485 8402220045 8402060471* 8402170268*	HASTE HOT 40-9691 40-9511 CONTRACT CONTRACT
Harrington, W D	8402270277	50-293	HAZLE,A J	8402170295	PR	HILL, W M.	8402020086*	50-358 Q
Harrington, W D	8402270465		HEAD,C R	8402100320	WASTE MOT	HILL, W M	8402220166*	50-358 Q
Harrington, W D	8402290202		HEBBLE,T L	8402010115	NUREO	HILTUNEN, E. A	8402090407*	50-312 F
Harris, J R	8402150256*		HEDAL,L	8402100021*	FOIA	HIME, W G	8402080414*	50-237 Q
Harris, K N	8402070383*		HEETHER,W H	8402010295	XPORTLIC	HIND, J A	8402060348*	50-409 Q
HARRIS, K N	8402070385*	50-335 F	HEETHER, W H HEETHER, W H HEHL, C W HEIDEL, C H HEIDER, L, H	8402010297	XPORTLIC	HIND, J A.	8402080210*	50-341 0
MARRIS, K N	8402080383	50-335 F		8402220423	XPORYLIC	HIND, J A	8402270338	50-255 0
HARRIS, M S.	8402070300	50-331 S		8402280570#	50-416 G	HIND, J A	8402270348*	50-255 0
HARRIS, M S	8402150127	50-331 S		8402230159#	50-341 K	HINDS, J	8402210243	50-275 8
MARRIS, M S.	8402280339	50-331 S		8402010282	50-271 P	HINRICHS, ©	8402030272	50-247 8
HARRIS, R H	8402080361*	50-443 0	HEIDER, L. H	B402150160	50-271 P	Hinrichs, G	8402030373	50-247 8
HARRIS, T H	8402280454	50-275 G	HEIDER, L. H	B402150278	50-271 P	Hinrichs, G	8402270326	50-247 8
HARRISON, F	8402140364	50-324 R	HEIDER, L. H	B402150283	50-271 P	Hinrichs, G	8402270336	50-247 8
HARRISON, F	8402160125	50-325 R	HEIDER, L. H	B402160453	50-27 P	Hirsch, A	8402020122	50-308 D
HARRISON, F L	8402060333	NUREO	HEIDER, L. H	B402240137	50-29 P	Hirsch, A.	8402020160	50-456 D
HARRISON: F L O .0021RAH HARRISON: J J HARRISON: J J HARRISON: J J HARRISON: J J	8402130117 8402240385 8402020178* 8402020256* 8402030326	NUREQ 50-461 F 50-329 Q 50-329 Q 50-329 A	HEIDER, L H HEIDER, L H HEISHMAN, R F HEITNER, K L HEITNER, K L	8402280054 8402280171# 8402140345# 8402040318 8402130151	50-271 F 50-29 G 50-410 G 50-309 P 50-336 F	HIRBCH, D HIRBCH, D HIRBCH, H HLADIK, M	8402070256 8402210167 8402220360 8402270421 8402270031*	50-142 G 50-142 G 50-142 G FOIA 50-287 P
HARRISON, J J	8402070131*	50-329 Q	HELLER, J K	8402170313*	50-315 G	HOBBY, B,	8402020080	HASTE HOT
HARRISON, J J	8402100188	50-329 A	HELTEMES, C J	8312160328*	MISC	HOCH, J B,	8402030258	50-275 E
HARRISON, J, J	8402270221*	50-329 Q	HELTEMES, C J	8401110467*	NUREG	HODGDON, A,	8402010208	50-352 G
HARRISON, H.	8402160614	HASTE MOT	HELTEMES, C J	8402010335*	NUREG	HODGDON, A, P	8402220221	50-352 G
HARRISON, R	8402070127	50-275 9	HELTEMES, C, J.	8402140488	MISC	HODGDON, A, P	8402220233	50-352 G
IART, P	8402030264*	HABTE NOT	HELTEMES, C J	8402140522*	FOIA	HODEDON, A. P.	8402220250	50-352 Q
HART, P	8402030531*	HABTE HOT	MENEAGE, J	840208088*	50-528 R	HODEDON, A. P	8402220251	50-352 Q
HARTLEY, J N	8402080087*	FOIA	HENRY, R. E.	8402130036*	FOIA	HODEDON, A. P	8402290104	50-352 Q
HARTLEY, J N	8402100284	HABTE HGT	HENRY, R. E.	8402130115*	FOIA	HOF, P. J	8402170311	MUREQ
HARTLEY, J N	8402100287*	HABTE MOY	HENRY, R. E.	8402130131*	FOIA	HOFFMAN, B.	8402100443	Btate Prog
HARTMAN, B. L HARTMAN, S. L HARTMAN, S. L HARTMAN, S. L HARTMANN, P. L	B402100111 B402100115* B402100115* B402130273 B402130273*	50-445 0 50-445 0 50-445 0 50-445 0 50-407 0	HENRY, W. M. HENBLEY, K. D HENBLEY, K. D HERBORN, D. I KERDT, A. R	8402020148* 8402100164 8402140556 8402280235 8402140446	70-2362 70-143 70-143 50-461 A 50-366 8	HDFFMAN, Q. L HOFFMAN, Q. L HOFFMAN, Q. L HOGAN, R. HOGAN, R	8402210285* 8402230086* 8402230091* 8402020003*	40-299 40-299 40-299 50-280 60-289
Habbell D F	B402070053	50-50B Q	HERMAN, A. A	8402270262	50-320 H	HOGAN, T. F.	8402170150*	CONTRACT
Hathaway, C. H	B402030427	50-341 J	HERMANN, R. A	8402150522	50-220 P	HOGARTH, W T	8402130246*	50-400 9
Haugh: J J	B402130043*	FOIA	HERMANN, R. A	8402160405	50-220 P	HOLAHAN, G.	8402080047*	50-528 8
Haughey, M.	B402070061*	50-410 A	HERMANN, R. A	8402170057	50-220 P	HOLAHAN, G.	8402240241*	50-220 F
Haughey, M	B402070063*	50-410 A	HERMANN, R. A	8402240376	50-220 F	HOLDEN, C	8402220318*	50-309 9
MAUGHEY, M F HAUGHEY, M F HAUGHEY, M, F HAUGHEY, M F HAUGHEY, M F	B402010004 B402020473 B402100445 B402240260 B402270157	30-410 A 30-410 F 50-410 A 50-410 A 50-410 A	HERNAN, R. W. HERNANDEZ, G. H. HERRINGTON, W. N. HERRINGTON, W. N. HERBCH, M. M.	8402070478 8310130140* 8402160356* 8402280536* 8402010032	50-302 P 50-275 0 50-445 G 50-445 G XPDRTLIC	HOLDER: 8. D. HOLIAN: P. D. HOLLAND: W. E. HOLLAR: D. E. HOLLENBACH: D. F	8402140528* 8402130345 8402150143* 8402220247 8402140137*	50-424 C 50-184 B 50-370 9 50-400 9 50-205 G
Hawkins, D Hawkins, D a Hawkins, E f Hawkins, E f Hawkins, E f	8402010436 8402010358 8402210485 8402210488 8402220045	CONTRACT CONTRACT 40-8681 40-8745 40-8511	HERBCH, M M. HERBCH, M M HERBCH, M M. MERBCH, M M HERBCH, M M.	8402010097# 8402100374 8402130343# 8402140343 8402170342	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	HOLLEY, W.L. HOLLEY, W.L. HOLMES-RAY, P HOLMES-RAY, P HOLMES-RAY, P	8402030221* 8402220326* 8402150274* 8402280246* 8402280485*	50-313 0 50-285 0 50-366 0 50-366 0
HAWKINS,N.A	8402060486	CONTRACT	HERSCH, M M.	8402220420	XPORTLIC	HOFENICH'A A	8402020460	50-482 F
HAWXHURST,J	8402080404*	50-277 G	HEWARD, R W	8402270074	50-146 R	HOFENICH'A A'	8402100426	50-483 A
HAYES,B.B.	8401070571*	50-392 B	HIATT, S L	8402080170	50-440 Q	HOFENICH'A A'	8402150515	50-482 A
HAYES,B.B.	8402130211*	50-528 A	HIATT, S L	8402150389	50-412 A	HOFENICH'A A'	8402230327	50-482 A
HAYES,D.W.	8402080326*	50-454 G	HIATT, S. L	8402220136	50-440 G	HOFENICH'A A'	8402070161	50-247 9
HAYNES, J O. HAYES, D H. HAYES, D H. HAYES, D H.	8402130312# 8402170164# 8402210036# 8401040360 8402030273	50-461	HIATT, B L HIATT, B L HIATT, B L, HIATT, B, L HICKEY, E E	8402220237 8402220353 8402270247 8402270425 8402160417*	50-440 Q 50-440 Q FOIA 50-440 A 50-283 Q	HOLT, J HOLT, J HOLYDAK, R H. HONG, F, S	8402080130 8402080135 8402080193 8402210259* 8402010287*	50-247 0 50-247 0 50-247 0 50-273 5 50-271 P
HAYNEB' 7 O' HEANEB' 7 O' HEANEB' 7 O' HEANEB' 7 O'	8402030366 8402030378 8402030420 8402030459 8402060361	50-361 8 50-362 8 50-361 8 50-362 8 50-362 8	HICKEY, J E. HICKEY, J W. HICKEY, J W. HICKEY, J W.	8402030333 84022704&9 8402090249* 8402090252* 8402090270*	PR 50-358 T FDIA FDIA FOIA	HOOD, D HOOD, D. HOOKE, P. K' HOPKEI, S.	8112220708* 8402020213* 8402280618 8402150232 8402030080	20-352 b 20-353 y 20-353 y 20-353 y

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	EUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY
-CFFEF, A. -CFIN, W.A. -CFIN, W.A. -CFIN, W.A.	8402140030 8402010209 8402010209 8402030160 8402030160	CONTRACT 50-445 G 50-445 G 50-445 G 50-445 G	HUCHTON, R. L. HUDSON, C. J. HUDSON, H. HUDSPETH, J. B HUDSPETH, J. B	8402280010 8402010060 8402150329* 8402030419 8402090080	NUREG TOPREP 50-275 8 50-348 P 50-348 F	IRWIN, D P IRWIN, D P IRWIN, D P ISKANDER, S K ISLEY, T	8402170049* 8402280231 8402280231 8402210073 8402130405	50-322 G 50-322 G 50-322 G NUREG 50-346 S
6314.14. A 6314.14. A 6314.14. A 6314.14. A	8402060138 8402060138 8402210340 8402210340 8402280014	50-445 G 50-445 G 50-445 G 50-445 G NUREG	HUCHES, D R HUCHES, D R HUKILL, H HUKILL, H	8402150268* 8402030354 8402140310 8402030310 8402240034	50-331	JABBOUR,K N JABBOUR,K N JAOBOUR,K N JACKIW,I N JACKIW,I N	8402100429 8402100438 8402100474 8402060R33* 8402130273*	50-419 A 50-414 A 50-413 A 50-346 Q 50-409 Q
CSEY, C M CSEY, C M. -CSSLER, D E -CSSLER, D E +CRIHAN, L	8402150229* 8402280529* 8304270275* 8305190338* 8402140116	50-390 Q 50-280 Q 50-289 P 50-289 P 50-529 G	HUKILL,H D HUKILL,H D HUKILL,H D HUKILL,H D	8402030233 8402030356 8402030443 8402030452 8402060388	50-269 P 50-269 S 50-269 P 50-269 R 50-269 P	JACKEON, D L JACKEON, D L JACKEON, G JACKEON, G JACKEON, G	8402280307* 8402010273* 8402090296* 8402140623* 8402150046*	50-346 0 50-346 F FOIA 71-9080 71-6058
CSE. H. C CSTON. H D CSTON. H D CSTON. R H CSTON. R H	8402220301* 8402270079 8402270430 8205170430* 8206250072*	QA999 50-416 P 50-416 P 50-220 P 50-220 P	HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H D	8402060440 8402070175# 8402070252 8402070291 8402080215	50-269 F 50-269 G 50-269 P 50-269 P 50-289 P	JACKBON, G JACKBON, J JACKBON, J JACKBON, J E JACKBON, J E	8402170522 8402280659* 8402140029* 8402090116* 8402230341	71-9009 40-8724 FGIA 50-528 5 50-528 A
MUSTON, R. H. MUSTON, R. H. MUSTON, B. MUSTON, B. MUSTO	8402030217 8402030224 8402270038 8402080278 8402130140	50-373 5 50-373 5 WASTE MGT 50-324 F 50-325 9	HUKILL,H D HUKILL,H D HUKILL,H D HUKILL,H D HUKILL,H D	8402080246 8402070001 8402140323 8402140340 8402160014	50-269 9 50-269 F 50-269 9 50-269 P 50-269 P	JACKBON, L H JACKBON, L H JACKBON, P O JACKBON, P O JACKBON, P O	8402140178* 8402280073* 8402080081* 8402080077* 8402080104*	50-390
OE P. H. OE P. H. OE P. H. OE P. H. OE P. H.	8402140447 8402170232 8402220537 8402230077 84022300101	50-324 0 50-324 F 50-324 0 50-324 P 50-325 S	HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H D	8402160023# 8402160323 8402160375 8402170140 8402210217#	50-267 P 50-267 P 50-267 P 50-267 F 50-267 G	JACKSON: P O JACKSON: P O JACKSON: P O JACKSON: P O JACKSON: P O	8402080112* 8402080117* 8402080127* 8402080133* 8402080137*	40-1341 40-1341 40-1341 40-1341 40-1341
HOME, P. M. HOME, P. M. HOME, P. M. HOME, P. M. HOME, T. L. H	8402270270 8402280056* 8402280320 8402280469 8402210285*	50-324 F 50-324 G 50-324 G 50-324 F 40-277	HUKILL,H D HUKILL,H D HUKILL,H D HUKILL,H D	8402230128 8402230129 8402240112 8402240116* 8402240122*	50-287 P 50-287 R 50-287 P 50-289 P 50-289 P	JACKSON, P C JACKSON, P C JACKSON, P C JACKSON, P C JACKSON, P C	8402080144* 8402080153* 8402080156* 8402080157* 8402080163*	40-1341 40-1341 40-1341 40-1341 40-1341
KUTAL. R CAH C. KAEA KAEAJ. C KAEAJ. C	8402060184* 8402060478 8402060122 8402160050* 8402160178*	CONTRACT NUREG CONTRACT FOIA FOIA	HUKILL, H, D HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H, D	8402270028 8402280275 8402280381 8402280387 8402280371	50-289 P 50-289 P 50-289 P 50-289 P 50-289 P	JACKSON: P O JACKSON: P O JACOBS: A JACOBS: A JACOBS: A	8402080168* 8402080180* 8402030062 8402070513 8402070583	40-1341 40-1341 CONTRACT CONTRACT CONTRACT
KAE, J. C. KAE, J. C KAE, J. C KAE, J. C KAE, J. C	8402160190* 8402160194* 8402160198* 8402160200* 8402160346*	FOIA FOIA FOIA FOIA FOIA	HUKILL H D HULL: A HULL: A P HUNOERFORD: 5 W. HUNNICUTT: D M	B402230173 B402140333* B402270328* B402130532 B402030238*	50-289 P 50-277 G 50-289 G State Prog 50-298 G	JACOBE, A JACOBE, A JACOBE, A JACOBE, A	8402100354 8402100441 8402170029 8402170474 8402210002	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
化气E, J C, 肥气E, J C 肥石, H F, 肥石, H F, 肥木, C,	8402140376* 8402270133* 8402020223 8402280330 8310040351*	50-287 P FOIA 50-443 9 50-443 Q 50-277 P	HUNNICUTT, D M	8402070238* 8402100248* 8402160356* 8402220261* 8402220437*	50-298 G 50-445 G 50-445 G 50-298 G 50-445 G	JACOBB.A JACOBB.H R JACOBB.R JACOBB.R JACOBB.R	8402210464 8402220276* 8402220479 8207200441* 8402020120	CONTRACT 50-72 G 50-407 R 50-289 P 50-387 S
HUMO, Y. HILACEK, M. O HIBARD, O. T HIBARD, Q. T.	8402230144 8402010048* 8402210018* 8402220414* 8402220427*	50-285 P 50-498 Q 50-498 A QA999 QA999	HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M HUNBTAD, A A HUNT, M D.	8402220484* 8402220535* 8402280536* 8402070358 8402150256*	50-298 G 50-298 G 50-445 G 50-282 B 50-413 G	JAFFE,D H. JAFFE,D H JAGER,L E JANG,J C JANG,J C	B402130480 B402170015 B402140155 B402020124* B4020B03B4*	50-317 P 50-317 P WASTE MOT 50-320 G 50-245 G
ABER, J. E. 43er, B. A. Hier, B. A. Hoer, B. A. Koer, S. A.	8104280035* 7905300623* 7907120678* 7910110337* 8102190624*	FOIA FOIA FOIA FOIA FOIA	HUNT, M D HUNTER, D R. HUNTER, H E HURST, S M HUTCHERBON, M N	8402280011* 8402150259 8402010444* 8402170094* 8402130131*	50-400 G 50-341 S WASTE MOT 50-352 G FDIA	JANG, J. C JANKLOW, W. J. JAPE, F. JAPE, F. JAPE, F.	B402240025* B402100454* B402140211* B402140365* B402150253*	50-387 G FOIA 50-269 G 50-369 G 50-413 G
4.767 - 8. A. 4.567 - 8. A. 4.767 - 8. A. 4.767 - 8. A. 4.767 - 8. A.	8104070747* 8104210566* 8206110307* 8402070019 8402070210*	FOIA FOIA FOIA POIA FOIA	IDEKER,R L ILBERG,D IPPOLITO,T IRBY,B IRVING,B M	8402100414 84020&0484 8402140479* 8402030471 8402130207	70-143 NUREQ 50-309 8 50-259 9 50-458 M	JAPE: F. JAPE: F. JAPE: F. JAPE: F. JAUDON: J. P	8402280004* 8402280033* 8402280270* 8402280484* 8402280484*	50-413 0 50-390 0 50-269 0 50-339 0 50-382 0
4867, 8. A 4367, 8. A. 4367, B. A 4367, B. A 4367, S. A	8402070215# 8402070221* 8402070239* 8402070244* 8402070248*	FOIA FOIA FOIA FOIA FOIA	IRWIN, D P. IRWIN, D, P. IRWIN, D P. IRWIN, D P. IRWIN, D P. IRWIN, D P.	8402090153 8402090153 8402090153 8402090157* 8402090157*	50-322 0 50-322 0 50-322 0 50-322 0	JAUDON, J P JAWORSKY, M JAWORSKY, M JEFFERSON, G A	8402220535* 6402220576* 6402010232* 8402010237* 8402220149	50-298 0 50-313 0 50-213 F 50-213 F FOIA
Leer, S. A Leer, B. A Keer, B. A Keer, B. A Keer, B. A.	8402070272* 8402070304* 8402070312* 8402070315* 8402070317*	FOIA FOIA FOIA FOIA FOIA	IRWIN, D P IRWIN, D P IRWIN, D P IRWIN, D P IRWIN, D P.	8402090163# 8402090163# 8402140049# 8402140049# 8402140051#	50-322 9 50-322 9 50-322 9 50-322 9	JENISON, K M JENISON, K, M JENKINB, C D JENKINB, G R JENKINB, G R	8402220582 8402280186* 8402210146 8402140063* 8402140407*	50-338 8 50-335 0 50-219 P 70-1201 70-27
LPER S A LBER S A LBER S A LBER S A LBER S A	8402090319* 8402090326* 8402090346* 8402090347* 8402090353*	FOIA FOIA FOIA FOIA FOIA	IRWIN, D. P IRWIN, D. P. IRWIN, D. P. IRWIN, D. P. IRWIN, D. P	8402140051* 8402140102 8402140102 8402150110 8402150110	50-322 0 50-322 0 50-322 0 50-322 0	DENS'M H DENS'M H DENS'M H DENS'M H	8402140428* 8402060395* 8402100169 8402210143 8402220038	70-824 50-341 G 50-341 A 50-341 A 50-341 A
næer, b. a nber, b. a. nber, b. a nber, b. a nber, b. a	8402090363* 8402090365* 8402090372* 8402090387* 8402090393*	FOIA FOIA FOIA FOIA FOIA	IRWIN, D P IRWIN, D P, IRWIN, D P IRWIN, D P, IRWIN, D P,	8402160278 8402160278 8402170022 8402170022 8402170049*	50-322 9 50-322 9 50-322 9 50-322 9 50-322 9	H W. Senac H W. Senac H W. Senac H W. Senac	8402220438* 8402270070 8402270243 8402280327 8402290228*	50-341 Q 50-341 A 50-341 F 50-341 F 50-341 Q

AUTHGR	ACCESSION NUMBER	BUBJECT CATEGERY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
JENSEN: W L JENSEN: W L JERMAN: P C JERMAN: P C JERMAN: P C	8402270187* 8402270211* 8402280477* 8402280700* 8402280700*	50-289 G 50-289 G FOIA FOIA	JOHNSON, W D JOHNSON, W D JOHNSON, W D JOHNSON, W P JOHNSTON, J B	8402220518* 840222055* 840222055* 840222055* 8402270231 8308180641*	50-285 Q 50-278 Q 50-313 Q 50-443 K 50-382 U	JUNGE, M A	8402080397 8402280147 8402230340 8402020024 8402150537	50-317 S 50-319 S 50-317 S HASTE HOT HASTE HOT
JESSUP, B JETT, O W JOHNSON, A B JOHNSON, A R	8402010337 8402150119 8402220212 8402140379* 8402280201	50-257 V 50-322 G 1&E 50-344 G 50-482 G	B r'NBUSHAC A M'NOLSHAC A M'NOLSHAC C r'NOLSHAC B r'NOLSHAC	8402270285* 8401110107* 8304010480* 8304030387* 8408150227	50-247 U COMMISBION 50-289 P 50-289 P 50-424 G	KADAMBI,N P KAEPPEL,F KAHLE,J B KALITOWSKI,T KALIVIANAKIS,N	8307150381* 8402070220 8402140154* 8402030247 8402030230	FOIA 50-245 / 8 50-321 0 HASTE HO7 50-245 8
0 4.002NHBC 10 102NHBC 10 102NHBC 101NBBN 10 101NBBN 10 101NBBN 10	8402230107* 8402030259 8402030437 8402100235 8402100253	50-454 G 50-235 P 50-255 S 50-255 S 50-255 G	JOINER, J E JONES, O T JONES, O T JONES, O T	8402150227 8402150327 8402020222 8402030267 8402060472	50-424	KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N	8402030285 8402070220 8402070303 8402130383 8402170202	50-254 B 50-265 B 50-265 B 50-265 B 50-265 B
0 8 "NOSUHOR 6 8 "NOSUHOR 10 "NOSUHOR 10 "NOSUHOR 10 "NOSUHOR	8402130468 8402140461 8402150297 8402210091 8402210105	50-255 P 50-255 P 50-255 R 50-155 G 50-255 P	JONES.G T JONES.G T JONES.G T JONES.G T JONES.G T	8402130434 8402140257 8402140415 8402170142 8402210198	50-257 S 50-260 S 50-257 S 50-257 S 50-257 S	KALIVIANAKIS,N KAMMER.D B KAMMERER.C KAMMERER.C KAMMERER.C	8402220332 8402280504# 8207010514# 8402010372# 8402010374#	50-254 R 50-259 Q FOIA 50-275 Q FOIA
70HN2ON, E H 70HN2ON, D 70HN2ON, D 70HN2ON, D 70HN2ON, B 70HN2ON, B 70HN2ON, B 70HN2ON, B 70HN2ON, B 70HN2ON, B 70HN2ON, B 70HN2ON, B 70HN2ON, B	8402230240 8402130471 8402270015 8402280577 8402010153	50-255 P 50-329 A 50-329 S 50-329 S 50-267 X	JENEB. G T JENES. G T JENES. G T JENEB. G T	8402220477 8402240147 8402240157 8402270376 8402270411	50-274 8 50-257 8 50-257 8 50-257 8 50-257 8	KAMMERER, C KAMMERER, C KAMMERER, C KAMMERER, C KAMMERER, C	8402070146# 8402070147# 8402070164# 8402070168# 8402070176#	50-498 T 50-498 T 50-498 A 50-498 T 50-498 A
JOHNSON, E. H JOHNSON, E. H JOHNSON, E. H JOHNSON, E. H	8402010233 8402030225 8402070005 8402070149 8402070173	50~267 P 50~278 G 50~445 G 50~382 G 50~478 G	омеа'л Ч Ч С'вамог Ч С'вамог Томеа'л Ч	8402280019 7911130224* 8402090311* 8402090313* 8402230105*	50-274 B FOIA FOIA FOIA TOPREP	KAMMERER, C KAMMERER, C KAMMERER, C KAMMERER, C KAMMERER, C	8402070180* 8402070188* 8402140039* 8402140108* 8402140119*	50-498 A 50-498 A FOIA FOIA FOIA
ланизам; е н панизам; е н панизам; е н панизам; е н	8402070235 8402070367# 8402100022 8402100198 8402100244	50-298 Q 50-267 P 50-498 A 50-298 Q 50-445 Q	JONES'M C JONES'M C JONES'M C JONES'M C	8401170226 8402040370 8402070229 8402070276 8402130277	50-285 R 50-285 P 50-285 P 50-285 P 50-285 P	Kammerer, C Kammerer, C Kammerer, C Kammerer, C Kammerer, C	8402280070* 8402270005* 8402270024* 8402270054* 8402270060*	FDIA 50-537 U 50-537 U FDIA FDIA
лонивои, е. н чонивои, е. н чонивои, е. н чонивои, е. н	8402150185 8402160347 8402210043 8402210180 8402210200	50-267 9 50-445 0 50-278 9 50-267 P 50-382 0	JONES, W C JONES, W C JONES, W C JONES, W C	8402140092 8402150359 8402160414 8402220061 8402220168	50-285 P 50-285 G 50-285 P 50-285 R 50-285 Q	Kammerer, C Kammerer, C Kammerer, C Kammerer, C Kammerer, C	8402270062* 8402270067* 8402270082* 8402270071* 8402270078*	FDIA 50-275 U 50-275 U FDIA 50-382 U
70HN80N' E H 70HN80N' E H 70HN80N' E H 70HN80N' E H	8402210212 8402220257 8402220298 8402220344 8402220365	50~267 P 50~278 Q 50~382 A 50~382 Q 50~458 Q	JONES, H C JONES, H C JONES, H C JONES, H C	B402220479 B402270171* B402270366 B402270368 B402270368	50-285 P 50-285 Q 50-285 Q 50-285 Q 50-285 Q	Kammerer, C Kammerer, C. Kammerer, C Kammerer, C Kammerer, C	8402270103* 8402270108* 8402270114* 8402270118* 8402270121*	FDIA FDIA FOIA 50-275 U 50-289 U
лонигом; е н лонигом; е н лонигом; е н лонигом; е н лонигом; е н	B4022203B8 B402220425 B4022204B0 B402220533 B402270443	50-362	JORDANI E. JORDANI E. L. JORDANI E. L. JORDANI E. L. JORDANI E. L.	8402240241* 6010160407* 6312120153 8401030405* 6401170016	50-220 P FDIA 50-3 G NUREG 50-3 G	Kammerer, C Kammerer, C Kammerer, C, Kammerer, C Kammerer, C	8402270127# 8402270137# 8402270153# 8402270163# 8402270171#	FOIA 50-358 U FOIA 50-373 U FOIA
JOHNSON, E H JOHNSON, Q JOHNSON, Q, E JOHNSON, Q, E JOHNSON, Q E	8402280514 8402290075 8402010175 8402010247 8402070046	50-445 Q 50-413 Q 50-413 Q 50-413 Q 50-413 Q	JORDAN, E. L. JORDAN, E. L. JORDAN, E. L. JORDAN, E. L. JORDAN, E. L.	8401170037 8401170041 8401170045 8401170062 8401170066	50~3 Q 50~3 Q 50~3 Q 50~3 Q 50~3 Q	Kammerer, C Kammerer, C Kammerer, C. Kammerer, C. Kammerer, C	8402270178# 8402270182# 8402270170# 8402270201# 8402270226#	FDIA FDIA FOIA 50-382 U 50-272 U
OHNOON, GE OHNOON, H OHNOON, J OHNOON, J OHNOON, J J	8402220242 8402170462 8402240038* 8402240046* 8402210021	50-413 G FDIA 50-293 G 50-293 G 50-295 P	JORDAN, E. L. JORDAN, E. L. JORDAN, M. J. JORDAN, R. L. JORDAN, W. H.	8401170067 8402170219* 8402130273* 8402080058* 8402090121	50-3 Q FDIA 50-409 Q 50-397 Q 50-445 Q	Kammerer, C. Kammerer, C Kammerer, C. Kammerer, C. Kammerer, C	8402270241# 8402270250# 8402270282# 8402270270# 8402270303#	50-382 U 50-247 U 50-247 U 50-458 U 50-247 U
ICHNSON, R. L. ICHNSON, R. L. ICHNSON, R. L. ICHNSON, R. L. JOHNSON, R. W	8402030264* 8402030281* 8402030479 8402030531* 8402140214	WASTE MOT WASTE MOT WASTE MOT 50-344 Q	Jordan, W H Jordan, W S Jordan, W S Jorgensen, B L Josef, L R	8402090161 8402010477 8402080121 8402290203* 8402080468*	50-445 Q FOIA FOIA 50-255 Q FOIA	KAMMERER, C. Kammerer, C Kammerer, C Kammeyer, J. C. Kane, R. K	8402270310# 8402270318# 8402270318# 8402130170# 8402280267#	FDIA FDIA 50-289 U 50-322 9 PT21
IOHNSON, T IOHNSON, T IOHNSON, H IOHNSON, H D IOHNSON, H D	8402280401 8402220040 8402010132* 8402030221* 8402030383*	50-424 0 40-8084 50-313 0 50-313 0 50-313 0	JDYCE, J JOYNER, J JOYNER, J, H JOYNER, J, H,	8402130449* 8402080327 8402220212 8402240027* 8402270207*	TOPREP 1&E 1&E 70-371 50-213 Q	KANGA, B.K. KANGA, B.K. KANGA, B.K KANGA, B.K KANGA, B.K.	8402020367 8402030435 8402030451 8402100231 8402140113	50-320 8 50-320 P 50-320 P 50-320 R 50-320 F
HNBON, W D	8402150235 8402160419* 8402220248* 8402220280* 8402220286*	50-482 8 50-285 0 50-285 0 50-313 0 50-285 0	JULIAN, C. A JULIAN, C. A JULIAN, C. A JULIAN, C. A	8402150143* 8402280161* 8402280284* 8402280570* 8402280014	50-390 Q 50-438 Q 50-416 Q 50-416 Q NUREQ	KANGA, B. K KANGA, B. K KANGA, B. K KANGA, B. K KANGLEY, J. P	8402140288 8402140427 8402210236 8402230115 8402140609	50-320 9 50-320 9 50-320 \$ 50-320 P 71-6574
)HNSDN, W D HNSDN, W D.)HNSDN, W D HNSDN, W, D. KNSDN, W D.	8402220339* 8402220341* 8402220367* 8402220372* 6402220406*	50-313 Q 50-285 Q 50-313 Q 50-458 Q 50-313 Q	JUNGE, M. JUNGE, M. A. JUNGE, M. A. JUNGE, M. A. JUNGE, M. A.	8402070387 8402020248 8402030309 8402030337 8402030403	50-318 8 50-318 8 50-318 8 50-318 8 50-318 8	KANYO, JP KARI, B, M, KARI, B M, KARMAN, M KARR, J E,	8401040174* 7906200195* 7908140043* 8402140004 8402030191	50-480 F 50-330 A 50-364 A 50-482 G 50-327 A
OHNSON: W D OHNSON: W D OHNSON: W D OHNSON: W D	8402220451# 8402220455# 8402220475# 8402220503# 8402220510#	50~482	JUNGE: M A JUNGE: M A JUNGE: M A JUNGE: M, A,	8402030413 8402070384 8402080339 8402080349 8402080373	50-318 8 50-317 8 50-317 8 50-317 8 50-317 8	KARRIJE KARRIJE, KARRIJE, KARRIJE,	8402030271 8402030276 8402060058 8402060230 8402060244	50-329 A 50-329 A 50-329 A 50-329 A 50-329 A

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WAR, J. E.	8402060247	50-329 S	KELLY, W J	8402100245	50-275 S	KNIGHTON, G W	8402050270	50-412 A
WAR, J. E.	8402060276	50-329 S	KEMPER. J S	8402020239	50-352 R		8402070431	50-528 A
WAR, J. E.	8402060461	50-329 A	KEMPER. J S	8402020358	50-352 S		8402070070*	50-528 A
WAR, J. E.	8402080370	50-329 A	KEMPER. J S	8402220348*	50-352 G		8402130401	50-204 F
SARP, J. E.	8402130343	50-329 R	KEMPER. J S	8402230084	50-352 A		8402150374*	50-412 A
MAR, J.E. MAR, J.E. MAR, J.E. MAR, J.E. MAR, J.E.	8402130355 8402130346 8402130420 8402130425 8402130427	50-329 8 50-329 8 50-329 A 50-329 A 50-329 R	KEMPER.JS KEMPER.JS KEMPER.JS KEMPER.JS KEMPER.JS	8402270005 8402270166 8402270401 8402280464* 8402280687	50-352 E 50-352 E 50-352 E 50-353 G 70-2988	KNIGHTON, 0 W	8402150412* 8402160470 8402160476 8402160485* 8402160584	50-351 P 50-528 A 50-443 A 50-443 A 50-412 A
MAR, J. E. MAR, J. E. MAR, J. E. MAR, J. E. MAR, J. E.	8402130463 8402130466 8402130473 8402150248 8402150318	50-327 S 50-327 A 50-327 S 50-327 A 50-327 S	N B NYVYYNAN KENNY, T J KENNY, T J KENNY, T J	8402130269* 8402020190* 8402020204* 8402020336* 8402090243*	50~3 H 50-247 G 50-286 G 50-272 G 50-286 G	MNICHTON, G W KNICHTON, G W KNICHTON, G W KNICHTON, G W KNICHTON, G W.	8402160681 8402170010 8402170496 8402170496	50-412 F 50-443 A 50-508 D 50-412 A 50-443 A
MARS J. E. MARS J. E. MARS J. E. MARS J. E. MARS J. E.	8402150322 6402150330 6402150354 8402220184 6402220567	50-327 8 50-327 A 50-327 8 50-327 8 50-327 H	KENYON, B D KENYON, B D KENYON, B D KENYON, T J	8402220456* 8402270261* 8402270423* 8402280354 8402030076	50-387 G 50-387 G 50-387 G 50-387 F 50-390 A	KNIGHTON, O W. KNIGHTON, O W KNIGHTON, O W KNIGHTON, O W KNIGHTON, O W	8402230004 8402240211 8402270352 8402270357 8402270365	50-443 A 50-361 F 50-528 F 50-400 F 50-275 F
JARR, J. E JARR, J. E. JARR, J. E. JARR, J. E. JARR, J. E.	8402270100 8402270123 8402270315 8402270437 8402280321	50-329 \$ 50-329 \$ 50-329 \$ 50-329 \$ 50-329 \$	KEPPLER'1 C KEPPLER'1 C KEPPLER'1 C KENAON'1 1	8402130113 8402150541 8402040297* 8402040309* 8402040369	50-390 A 50-390 A 50-329 Q 50-329 Q 50-315 Q	KNIGHTON, G W KNIGHTON, G W KNOP, R C KNOP, R C KNOP, R C	8402290456 8402290461 8402080323 8402080326# 8402130303	50-275 D 50-275 P 50-454 G 50-454 G 50-461 G
KARR. J. E.	8402280336	50-329 8	KEPPLER, J G	8402080204	50-341 Q	KNOP.R C	8402130306*	50-461 Q
KARR. J. E.	8402280440	50-327 8	KEPPLER, J G	8402100224	50-358 H	KNOP.R C	8402130323	50-440 Q
KARR. J. E.	8402280581	50-327 8	KEPPLER, J G	8402170278	50-454 Q	KNOP.R.C	8402170155	50-456 Q
JARR. J. E.	8402280584	50-327 8	KEPPLER, J G	8402220524*	50-483 F	KNOP.R C	8402170160*	50-456 Q
KARSCH. R. D	8402040494	50-329 8	KERCH, H W	8402150004*	50-443 Q	KNOTTS.J B	8402280502	PR
MASSAKATIB,L D MASSAKATIB,L D MASSAKATIB,L D MASSAKATIB,L D	8402220387 8402220512 8402270111 8402270125 8402270131	50-397 S 50-397 S 50-397 S 50-397 S 50-397 S	MEREKES, W A MEREKES, W A MERE, G W MERE, G W MERE, G W	8402170144* 8402170148* 8402040018* 8402080078* 8402080120*	50-322 0 50-322 0 FDIA 40-1341 40-1341	KNDX, H KNOX, W KNOX, W H KNUBEL, J KNUBEL, J	8402130041* 8402160333* 8402290328* 8402210196 8402210223	CONTRACT 50-277 Q 50-269 Q 50-219 F 50-219 P
Kassakatib.i. d	8402270273	50-397 \$ CONTRACT CONTRACT FOIA FOIA	Kerr, g W	8402100465*	FOTA	KNUBEL, J.	8402280286	50-219 P
Kasterbero.h	8402100473*		Kebbinger, w W	8402150255	50-275 S	KOBER, R. W	8402070138	50-244 P
Kasterbero.h e	8402010180*		Kebbinger, w W	8402210224	50-275 S	KOBER, R. W	8402100246	50-244 P
Kato.h.y.	8402130018*		Kessler, J.	8402070077	50-247 G	KOBER, R. W	8402150128	50-244 P
Kato.o.h.	8402270415		Ketelaar, D	8402270207	NUREG	KOBER, R. W	8402170284	50-244 F
KAUPHAN, P. D	8402150016*	50-483 G	KETZLACH, N	8402130548	70-698	KOBER, R W.	8402270107	50-244 F
KAY, J. A.	8402040068	50-27 P	KETZLACH, N	8402160604*	70-2932	KOBER, R. W	8402270167	50-244 P
KAY, J. A.	8402040252	50-27 P	KEY, W, J	8402020316*	50-461 G	KOESTER, G	8402280032	50-482 S
KAY, J. A.	8402070370	50-29 F	KEY, W J	8402290135*	50-454 G	KOESTER, G L	8402100241*	50-482 G
KAY, J. A.	8402210029	50-29 P	KIEHNER, E	8402150338*	50-329 A	KOESTER, G. L	8402130407	70-2960
IMY, J. A. IMY, J. A. IMY, J. A. IMY, M. A. ILAUNEY, J. J	8402220186 8402220283* 8402280043 8402280176 8402100435	80-29 F 80-29 G 50-29 F 80-288 F State Prog	KINNEMAN'Y D KINO'E' KIEC'G L KIEC'G'L'	8402130536 8402130540* 8402150514* 8402020330* 8402060467	XPORTLIC XPORTLIC 50-309 H 40-6920 MISC	KOESTER, O.L. KOESTER, O.L. KOESTER, O.L. KOESTER, O.L. KOESTER, O.L.	8402140168 8402140475 8402150400 8402170157 8402220209	00-482 A 50-462 B 50-482 B 50-482 B 50-482 F
ICAMEY, J. J	8402280487	PR	KINNEMAN, J D	8402130084	MIBC	KOESTER, O L	8402220377*	50-482 0
ICATINO, D. E	8402150016*	50-483 G	KINNEMAN, J D,	8402280455	1&E	KOESTER, O L	8402220452*	50-482 0
ICATINO, L.	8402140546	XPORTLIC	KINNEY, W W.	8402220273*	50-245 G	KOESTER, O L	8402220550	50-482 8
ICATINO, L.	8402140549*	XPORTLIC	KINNEY, W W	8402240008*	50-223 G	KOESTER, O L	8402220548*	50-482 0
ICOTIO, N. N	8402270225	50-584 A	KINTNER, L. L	8402010332	50-352 F	KOESTER, O L	8402280058	50-482 A
JEISER: H. W.	8402020117	50-387 8	KINTNER,L L	8402090147#	50-341 A	KDESTER, G L	8402280382	PR
MEISER: H. W	8402030214	50-387 8	KINTNER,L L,	8402170074	50-352 F	KDESTER, J E	8402170035	50~48R 8
MEISER: H. W.	8402030231	50-387 8	KIPP,T.R	8402160460#	50-329 A	KDH, Y	8402170268*	CONTRACT
JEISER: H. W.	8402030261	50-387 8	KIRK,Q.B	8402100212	50-327 8	KDHLENBERGER, G	8402270040	50-10 F
MEISER: H. W	8402030267	50-387 8	KIRK,Q B	8402140010	50-327 8	KDHLER, A D.	8402130432	50-50B 8
LE (SER, 14. W.	8402060239	50-387 8	Kirk, Q. B.	8402140206	50-327 S	KOLI,E	8402270001	FOIA
RE (SER, 14. W	8402070321	50-387 S	Kirkland, D	8402240073	50-424 0	KOLTAY,P.	8402080377*	50-247 G
RE (SER, 14. W	8402070332	50-387 8	Kirsch, D. F.	8402150326*	50-275 S	KOMORI,8.	8402010300	XPORTLIC
RE (SER, 14. W	8402070364	50-387 8	Kirsch, D. F.	8402230211	50-206 S	KONKLIN,J	8402270307	50-440 S
RE (SER, 14. W	8402080242	50-387 8	Kirslis, S	8402270128*	50-289 0	KONKLIN,JE	8402070170*	50-373 A
KEISER, H. W KEISER, H. W KEISER, H. W KEITH, H. N. KEITH, M.	8402150333 8402280120 8402280227 8402020234 8402070013	50-387 8 50-387 8 50-387 8 50-333 8 50-331 8	Kirslis, S. Kirslis, S Kirslis, S Kister, H Kitayama, A	8402270235* 8402270246* 8402270260* 8402160382 8402010460	50-289 0 50-289 0 50-289 0 50-247 S XPDRILIC	KONKLINJE KONWINSKIJO R KONWINSKIJO R KOONJA R	8402130327* 8402210455 8402210487 8207210485* 8402220075	50-440 Q 40-8584 40-8584 FOIA 50-395 S
EITH, W.	8402220006	50-331 R	KJARMA: H E	8402270213	NUREQ	KOSLA: B. M.	8402020072*	40-8027
ERLEY, D. L.	8402100248*	50-445 G	KLEIN: T. J.	8402210480	40-8584	KOSTEL: J. J	8402270403*	FOIA
ERLEY, J. L.	8402060204	50-413 G	KLIKA: J. C.	8402220559	50-379 S	KOSTAN: J. J	8402270409*	FOIA
ERLEY, J. L.	8402230090	50-413 'Q	KLINE: J. R	8402270101	50-440 Q	KOTTAN: J. J	8402020334*	50-352 G
ERLEY, J. L.	8402280358	50-413 Q	KNAPP: M R	8402060139	Waste MgT	KOTTAN: J. J	8402080347*	50-219 G
ISLEY, J. L.	8402280414	50-413 Q	KNAPP, P. J	8401030277#	50-361 P	KOTTAN, J J	8402130007*	50-213 G
ISLEY, H. D.	8402150184*	GA999	KNEIP, R. F.	8402080074#	40-1341	KOUTS, H. J.	8402130018*	FOIA
ISLLY, J. A.	8402220367*	50-313 Q	KNEIP, R F.	8402080085#	40-1341	KONITCHIL S	8402280524	PR
ISLLY, J. A.	8402220518*	50-265 Q	KNIGHT, G W	8402160467	50-382 A	KRAMER, J J	8210150584*	TOPREP
ISLLY, J. H. F	8402220596*	50-313 Q	KNIGHT, G W	8402160474	50-400 A	KRAUSE, B. F	8402220045	50-316 S
ELLY, J. J. ELLY, J. H. ELLY, H. J. ELLY, H. J.	8402070425* 8402060343 8402210056 8402170417 8402160472*	50-312 F NUREO 50-286 R NUREO TOPREP	KN19HT, J. P. KN19HT, J. P KN19HTON, 9, H. KN19HTON, 8, H. KN19HTON, 8, H	8304030079* 8307290197* 8402030054 8402030057 8402040201	50-220 P 50-287 P 50-508 D 50-412 A 50-400 D	Krause, R. Krause, R. Krause, R. Krause, R. Krause, R. W	8402080385* 8402080394* 8402080401* 8402080409* 8402280398	50-237 G 50-237 G 50-237 G 50-237 G 50-298 S

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SVBJECT CATEGORY
KREH, J L KREH, J L KREJDER, H Q KRICH, R M	84021400A3* 8402140407* 8402140428* 8402070344 8402080114	70-1201 70-27 70-824 50-443 8 50-155 P	LAUER, R J LAUER, R J LAUER, R J LAUER, R J LAURENBON, J A	8402010095* 8402010095* 8402170036 8402170036 8402010085	50-329 0 50-329 0 50-329 0 50-329 0 50-322 0	LEVIN.H A LEVINE,J M LEVINE,J M LEWIS,E LEWIS,O D	6402240027 8402210269 8402220181 8402060182 8402020054	50-329 A 50-313 F 50-368 8 50-454 0 WASTE HOT
MRICH,R M KRIEGER,R W KRIEGER,R W KRIMM,R. KRIMM,R	8402160314 8402070064 8402270154 8402150137 8402150370	50-155 P 50-206 P 50-206 P 50-395 F 50-206 F	LAURENSON, J A LAURENSON, J A LAURENSON, J A LAURENSON, J A LAURENSON, J A	B402020235 B402060193 B402070320 B402150104 B402220311	50-322	LEWIS, M I LEWIS, M I LEWIS, M I	8402170308 8210270116# 8402280406 8402280510 8402080460#	Nureo 50-289 p Pr Pr Contract
KRIMM,R W	8402010160	50-321 F	LAURENSON, J A	8402270092	50-322	LEWIB, M, T	8207300134*	50-289 P
KRIMM,R W	8402090060	50-454 F	LAVERTY, J. H	8402030197		LEWIS, N D	8402220380	50-443 H
KRIMM,R W	8402090204	50-454 F	LAVERTY, J H	8402030197		LEWIB, R	8402170274	50-259 B
KRIMM,R W	8402090211	50-482 F	LAVERTY, J H	8402030143		LEWIB, R C	8402130354	50-259 F
KRIMM,R W	8402090237	50-275 F	LAVERTY, J H	8402040143		LEWIB, R C	8402140138	50-416 F
KRIMM,R W	8402070278	080	LAVERTY, J H	8402240054	50-416 G	LEWIS, R C	8402140144	50-390 A
KRIMM,R W	8402070336	50~289 F	LAVERTY, J H	8402240054	50-416 G	LEWIS, R C	8402140180	50-259 F
KRIMM,R W	8402100228	50~10 F	LAWRENCE, M J	8402130271	WABTE MGT	LEWIS, R C	8402140253*	50-335 Q
KRIMM,R W	8402150221	50~259 F	LAWRENCE, M J	8402280382	PR	LEWIS, R C	8402140262	50-410 Q
KRIMM,R W	8402150332	50~382 F	LAWSON, L T	8402210213	50-269 J	LEWIS, R. C	8402140271*	50-259 Q
KROES, R J KROES, R J KUCZYNSKI, L A KUCZYNSKI, L A KUCZYNSKI, L A	B402020302 B402240235 B402070321 B4020B0242 B402150333	50-433 R 50-433 R 50-387 S 50-387 S 50-387 S	LAWTON, M D. LAZARUB, W J LAZARUB, W J LAZO, L. LAZO, R M	8402270014 8402020112* 8402020379* 8402210059 8402060062	40~8084 50~244	Lewib, R C Lewib, R C. Lewib, R C Lewib, R C Lewib, R C.	8402140286* 8402140275 8402140301 8402140307 8402140359	50-413 0 50-259 F 50-416 P 50-348 F 50-416 F
KUCZYNGKI,L A KUHR,E M KUHR,E J KUMAR,V J	8402280120 8402280227 8402090412* 8402130231 8402270098*	50-387 S 50-387 S 50-312 F 50-219 P 50-341 A	LE-A K LE-A K LE-A K. LEAHY-M LEAR-Q	8309290095* 8309290297* 8402070470* 8402290219 8308040572*	50-259 Q 50-321 P 50-298 P 50-237 B 50-329 A	LEWIB,R C LEWIB,R C LEWIB,R C LEWIS,R C LEWIS,R C	8402140392 8402140493 8402140494 8402140496 8402140500	50-259 P 50-424 Q 50-259 V 50-416 V 50-261 Q
KUMPORIS, T M	8402070353*	FOIA	LEAVITT.JK	8402080171	PR	LEWIS, R. C	8402140301*	50-424 0
KUNCE, L G	8402220027	50-298 P	LEDDICK.RS	8402070258	50-382 F	LEWIS, R. C	8402150178	50-390 V
KUO, P T	8402220307*	50-352 T	LEDDICK.RS	8402270325	50-382 A	LEWIS, R. C.	8402130252	50-261 0
KUZO, & B	8402140257*	50-327 G	LEDDICK.RS	8402270178	50-382 A	LEWIS, R. C.	8402130262*	50-261 0
'HEUREUX, R W	8402080337	50-317 B	LEE.GB.	8402230015	XPORTLIC	LEWIS, R. C	8402130267	50-366 0
ACEY.W 8 ACEY.W 8 ACEY.W 8 ACEY.W 8	6402020282 6402060357 6402020412 6402230078 640223044	50-334 8 50-334 8 50-334 8 50-324 8 50-334 9	LEE, J LEE, J LEE, D R LEE, T D LEFEBYRE, B J	8304050473* 8304050478* 8402170133 8402140298* 8402170135*	50-289 P 50-289 P 50-247 G 70-143 50-482 G	LEWIS, R. C. LEWIS, R. C. LEWIS, R. C. LEWIS, R. C. LEWIS, R. C	8402150282* 8402150270* 8402150310* 8402170190 8402220059	50-366 0 50-366 0 50-413 0 50-327 F 50-259 B
.AFAVE.W T	8402220306*	50-352 T	LEFEBURE, B J	8402170141*	50-482 G	LEWIS, R. C.	8402280125	50-400 0
LAFLAMME,8	8402210193	50-307 S	LEHMAN, L L	8402060142*	HABTE MOT	LEWIS, R. C.	8402280145	50-261 0
LAFLAMME,B J	8402020321	50-309 S	LEHNERT, R A	8402230101*	50-354 A	LEWIS, R. C.	8402280195	50-302 0
LAFLEUR,J D	8402130006*	FDIA	LEHNERT, R A	8402230120*	50-354 A	LEWIS, R. C.	8402280203*	50-302 0
LAFLEUR,J D	8402240361*	FOIA	LEMPGEB, T E	8402060005	50-220 P	LEWIS, R. C.	8402280237	50-250 0
LAFLEUR, J D	8402240367*	FOIA	LEMPOES, T, E	8402060156	50-220 F	Lewis, R C	8402280241	50-338 F
LAFLEUR, J D	8402270513*	FOIA	LEMPOES, T. E	8402060237	50-220 P	Lewis, R C.	8402280250*	50-250 0
LAGGART, M W.	8402060118	50-219 B	LEMPOES, T. E.	8402070146	50-220 P	Lewis, R, C.	8402280262	50-416 0
LAM, J. R.	8402060333	NUREG	LEMPOES, T. E.	8402070150*	50-220 P	Lewis, R, C.	8402280264	50-261 0
LAMBE, W	8402140533	50-458 M	LEMPOES, T. E	8402080155	50-220 P	Lewis, R. C.	8402280278*	50-416 0
LAMBE, W	8402230382	50-483 M	LEMPOES, T. E	8402080142*	50-220 P	LEWIS,R C	8402280287	50-280 F
LAMBE, W	8402230389	50-483 M	LEMPOES, T. E	8402080229	50-220 S	LEWIS,R C.	8402280293*	50-62 Q
LAMPKA, J V,	8402280402	PRM	LEMPOES, T. E	8402090048	50-220 P	LEWIS,R C.	8402280348*	50-261 Q
ANDAU, M	8402150434	State Prog	LEMPOES, T. E	8402090073*	50-220 P	LEWIS,R.C	8402280365*	50-261 Q
NDGRAF, L C	8402230152	50-341 K	LEMPOES, T. E	8402090277	50-220 P	LEWIS,R C	8402280415	50-416 Q
idisik	8402140303*	50-335 G	LEMPOES, T E	8402140335	50-220 P	LEWIB,R C.	8402280418	50-414 0
Idriev.f r	8402210202	50-354 R	LEMPOES, T. E	8402140344	50-220 S	Lewib,R C	8402280419	50-280 0
Idsman.r e	8402020178*	50-327 G	LEMPOES, T. E	8402150345	50-410 A	Lewib,R C	8402280432*	50-414 0
Idsman.r.e	8402020254*	50-327 G	LEMPOES, T. E	8402160366	50-220 R	Lewib,R.C.	8402280434*	50-280 0
Idsman.r b	8402270221*	50-327 G	LEMPOES, T. E	8402160404	50-220 P	Lewib,R.C.	8402280445	50-366 0
NE, V. M NEY, R V NPHER. L, C ANPHER. L C ANPHER. L C	8402170074 8402070297 8402100123 8402100123 8402230097	50-352 0 50-397 P 50-322 0 50-322 0 50-322 0	LEMPQES.T E LEMPQES.T E LEMPQES.T.E. LENTINE.F O. LENTINE.F O.	8402220132* 8402240146 8402240220* 8402020347 8402080151	50-220 P 50-410 B 50-220 R 50-275 P 50-275 F	Lewib, R. C. Lewib, R. C Lewib, R. C Lewib, R. C. Lewib, R. C.	8402280473* 8402280489 8402280499 8402280503 8402280511*	50-280 0 50-280 ¢ 50-280 ¢
ANPHER, L C	8402230097	50-322 G	LESHNOFF, D D	8402280352*	50-287 0	LEWIS,R C	B402280512*	50-259 Q
APINSKY, Q	8306150045*	TOPREP	LESSY, R. P	8402220174	50-307 0	LEWIS,R,C,	B402280520*	50-259 Q
APPA, D, A	8402210021	50-275 P	LESSY, R. P	8402220200*	50-309 0	LEWIS,R C	B402280540*	50-259 Q
ARIMORE, E	8001070206*	FOIA	LESTER, R. M	8402080399	FDIA	LEWIS,R,C	B402280578	50-416 Q
ARIMORE, R E.	8001070209*	FOIA	LETECHE, K. J	8402030145	50-322 0	LI,H,	B402010083*	50-244 P
ARBON, C. E. ARBON, C. E ARBON, C. E. ARBON, C. E _ARBON, C. E	8402130452* 6402130577 6402150320* 6402150369 8402160369	50~263 9 50~263 8 50~262 0 50~263 R 50~263 F	LETBCHE, K. J. LETBCHE, K. J. LETBCHE, K. J LETBCHE, K. J. LETBCHE, K. J.	8402030145 8402030148* 8402030148* 8402060185 8402060185	20-355 6 20-355 6 20-355 6 20-355 6	LIAW, B. D. LIAW, B. D. LICITRA, E. A. LICITRA, E. A LICITRA, E. A.	8304270217* 8305160343* 8310200052* 8402080143* 8402090076*	50-289 F FDIA 50-528 B 50-528 B 50-530 A
LARSON, C. E LARSON, C. E. LARSON, C. E LARSON, C. E LARSON, C. E	8402170101 8402220017 8402220056 8402220415 8402240123	50-282 0 50-282 0 50-263 0 50-263 0 50-263 0	LETBCHE, K.J. LETBCHE, K.J LETBCHE, K.J LETBCHE, K.J LETBCHE, K.J	8402060188* 8402060188* 8402150113 8402150113 8402150162	50-322 0 50-322 0 50-322 0 50-322 0	LICITRA, E. A LICITRA, E. A LIDEN, E. A LIDEN, E. A. LIDEN, E. A.	8402070107* 8402270635 8402010135 8402010137 8402060383	50-461 A 50-528 A 50-272 F 50-272 F 50-272 R
Larson, C. E	8402270234	50-282 R	LETSCHE, K. J	8402150162	50-322 0	LIDEN, E. A	8402070249#	50-311 0
Lash, T. R.	8402100338	27-39	LETSCHE, K. J	8402150171	50-322 0	LIDEN, E. A,	8402070253#	50-311 6
Lauben, N	8402130643*	TOPREP	LETSCHE, K. J	8402150171	50-322 0	LIDEN, E. A.	8402070374*	50-272 f
Lauer, R. J	8402010091	50-329 Q	LEVIN, H. A.	8402140174	50-329 A	LIDEN, E. A	8402130176	50-272 f
Lauer, R. J	8402010091	50-329 Q	LEVIN, H. A.	8402210271	50-329 R	LIDEN, E. A.	8402130319	50-272 p

#UTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
IRNUE, A IRNUE, A IRNUE, A IRNUE, A IRRUE, A IRRUE, A	8402130394 8402280216* 8402280220* 8402280311 8402140058*	50-272 F 50-272 Q 50-272 Q 50-272 Q 50-272 R 50-322 Q	LORENTZ,R E LOTCHIN,P LOTITO,E M LOTITO,M A LOUX,R R	8402170126* 8402290415 8402220440 8402160683* 8402030237	50-445 G FDIA 50-317 R CONTRACT WASTE MOT	MACBONALD.C E MACBONALD.C E MACBONALD.C E MACBONALD.C E MACBONALD.C E	8402150539* 8402160507 8402160515* 8402170198 8402170205*	71-6601 71-6679 71-6679 71-6579 71-6387
CEERMAN, J CEE, R. M. CEE, R. M. CET, COEMER, T. B.	8307180383* 8402010313 8402010368 8402270207 8402060457	50-329 A MUREO MUREO MUREO MUREO	LOVAAS,A LOVE,R S LOVE,R S LOVENDALE,P C LOW,L D	8402170288 8402020010* 8402100215* 8402270361* 8402100171*	PR 50~461	MACDONALD, C E	8402240310 840227060B 8402270355 840227036B 8402270370	71-133 71-5800 71-6574 71-5607 71-5450
1457, F 1457, F 1467, F 1467, F 1467, F	8402020289 8402030330 8402040429 8402070219 8402080221	50-409 P 50-409 P 50-409 F 50-409 S 50-409 S	LOWE, M F LOYOLA, V M LUCE, C F LUCK, W D LUCKB, A B	8402070153 8402230378 8402080435* 8402220084 8402070160*	50-413 6 NUREG 50-397 A 50-537 6 50-329 G	MACDONALD, D MACDOUGALL, E A MACKAY, S MACKAY, S	8207280427* 8402140438 8402140442* 8402060487 8402150507	50-287 P TOPREP TOPREP 50-324 F 50-324 F
ner.f ner.f ner.f ner.f ner.f	9402080363 8402070271 8402150172 8402160267 8402160270	50-409 P 50-409 G 50-409 F 50-409 B 50-409 P	LUCKB, A S LUCKB, A S LUCKB, A S LUCKB, A S LUCKB, A S	8402040345 8402070140* 8402070144* 8402070146* 8402070155*	50-329 A 50-329 G 50-329 G 50-329 G 50-329 G	MADDEN, T J MADDEN, T J MADDEN, T J MADDEN, W MADDEN, W	8402070404 8402240067 8402270449 8402020356* 8402270207*	FOIA 50-289 Q FOIA 50-293 Q 50-213 Q
ver. F. Ver. F. Ver. F. Ver. F. Ver. F.	8402170074 8402170078 8402170251* 8402210169 8402220073	50-409 G 50-409 F 50-409 G 50-409 F 50-409 P	FACO'N E FACO'N E FACO'N E FACO'N E	8402090517 8402090517 8402170031* 8402040341 8402280399	ACRB ACRB CONTRACT NUREG 50-142 G	MADEDA, T. J. MADEDA, T. J. MADISON, A. MADISON, A.	8402060009* 8402060346* 8402270416* 8402270420 8402270424	50-341 0 50-409 0 50-454 0 50-263 5 50-265 8
vier, f vier, f. vier, f vigtrom, m. vigtrom, r.	8402220236 8402220481 8402230109 8402020249 8402080385*	50-409 P 50-409 P 50-409 F XPORTLIC 50-237 G	LUEBXE, E A LUEHMAN, J 0 LUJAN, M LUMB, R F LUNDVALL, A E	8402280450 8402280360* 8401110113* 8402170484* 8402060098	50-142 G 50-62 G COMMISSION CONTRACT 50-318 P	MADSEN. G L MADSEN. G L MADSEN. G L MADSEN. G L MAGSER. T R	8309230347* 8402140308* 8402220265* 8402220319* 8402010162*	50-267 P GA999 GA999 GA999 50-327 P
Cstrom, R. Cstrom, R. W.U. Wille, J. Wille, J. C.	8402080374* 8402080401* 8402140508* 8402270276 8402020336*	50-237 G 50-237 G FDIA 50-272 B 50-272 G	LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E	8402060234 8402080272 8402100006 8402140327* 8402150136	50-317 P 50-317 P 90-317 P 50-317 G 50-317 F	MAGETTE, T E MAIER, J E MAIER, J E MALARD, J C MALLETT, B	8402270086 8402020255 8402070380 8402130072* 8402270335*	50-320 P 50-244 S 50-244 F FOIA FOIA
MILLE, J. C. FINSKI, D. FINSKI, D. R. FINSKI, D. R FFE, L	8402070351* 8402020171* 8402220273* 8402270275* 8401070577*	50-272 G 50-336 G 50-245 G 50-336 G 50-322 S	LUNDVALL, A E LUPTAK, A LYNCH, J L LYNCH, M D LYNCH, M D	8402270454 8402020171* 8402150303 8402070075* 8402070275*	50-317 P 50-336 Q 70-1389 50-440 A 50-397 A	MALLETT, B S MALMROS, M H MALODY, C. W MALSCH, M O MALSCH, M O	8402270273* 8402280536* 8402130418 8402010494* 8402230432*	FOIA 50-445 G 70-1257 50-289 F FOIA
FFKAN, M SENO, R. SENO, R. T. ITLE, M. B ITLE, M. B.	8402080392 8402220405 8402290255 8402020307 8402070215	FOIA 50-333 S 50-333 S 50-461 G 50-373 G	LYNCH, M D LYONS, B P LYONS, B P LYONS, P J LYONS, P J	8402270407* 8402280080* 8402280087* 8402210284 8402210423	50-341 A FDIA 50-471 A 40-299	MALSCH,M G MALSCH,M G MALSCH,M G MAMBRETTIJC J MANAKTOLAJH K	8402230434* 8402230437* 8402270375* 8402100252* 8402240378	50-309 0 50-322 0 50-289 P 50-244 P NUREO
III.E. W. S. III.E. W. S. III.E. W. S. III.E. W. S. III.E. W. S.	8402100205 8402100213 8402100217* 8402150015 8402150174	50~255 G 50~440 G 50~440 G 50~483 G 50~358 G	LYONS, P J L LYONS, P J L LYONS, P J L LYONS, P J L LYONS, W	8402230076 8402230151 8402230258 8402230264 8402020243	40-279 40-279 40-299 40-279 50-318 8	MANGAN, C V MANION, W J MANKOFF, L L MANLEY, G N MANN, B	8402030256 8402070581* 8402270447 8402140459* 8402210087	50-220 S 71-512 PT21 50-424 1 TOPREP
ine, M. 8 ine, M. 8 ine, M. 8 ine, M. 8 ine, M. 8	8402150350 8402170175 8402220584 8402270089 8402270428	50-454 Q 50-454 Q 50-454 Q 50-454 Q 50-483 Q	LYONS, W LYDNS, W T LYONS, W T MACDONALD, C E MACDONALD, C E	8402270455 8402030234 8402030413 8402010070 8402010074*	50-318 8 50-378 8 50-318 8 71-6601	MANNING, W J MANNO, B F MANOLY, K MANOLY, K MANOLY, K A	8402280074* 8402020397 8402020252* 8402270175* 8402020318*	FOIA 50-410 K 50-387 G 50-387 G 50-334 G
ITLE.W. S ITLE.W. S. ITLE.W. S. ITLE.W. S ITLEWALES, O	8402270433 8402270130 8402270214 8402270240 8402070283	50-454 Q 50-454 Q 50-374 Q 50-454 Q 50-220 B	MACDONALD, C E MACDONALD, C, E MACDONALD, C E MACDONALD, C E MACDONALD, C E	8402010114 8402010117 8402010122 8402010123* 8402010127	71-6717 71-9143 71-85 71-85 71-385	MANDLY,K A MARABITO,R MARANO,D MARGINKIEWICZ MARGINKIEWICZ	8402160282* 8402270307 8402070251* 8402280602* 8402280605*	50-423 Q 50-440 S 50-352 Q FOIA FOIA
WAS. BP.C. BM.C. BM.C. VEPMORE: H.H.	8402160462* 8402240170* 8402140294* 8402140512* 8402130312*	50~245 P 50~382 A 50~413 Q 50~424 Q 50~461 Q	MACDONALD, C E	8402010128* 8402010435 8402010438 8402010442* 8402020040	71-385 71-4949 71-5026 71-5026 71-9151	MARCINKIENICZ MARCINKIENICZ MARCINKIENICZ MARCINKIENICZ MARGULIES, M B	8402280407* 8402280611* 8402280490* 8402280496* 8402280496*	FDIA FDIA FOIA FOIA 50-261 Q
CYD. M. CASCID. A. T. CASCID. A. T. CASCID. A. T. CASCID. A. T. CASCID. A. T. CASCID. A. T.	8309150467* 8402030298 8402280267* 8402140015 8402080053	COMMISSION PT21 PT21 FOIA 50-440 G	MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E, MACDONALD, C E,	8402030095 8402030301 8402030308* 8402070429 8402070537	71-9107 71-19 71-19 71-19 71-4909 71-5957	MARGULIES, M B MARGULIES, T B MARK, J C. MARK, J C MARK, J C	8402270097 8307270458* 8101270309* 8402270344* 8402270351*	50-413 Q FOIA 50-320 D 50-327 D
FOREN.E. Fy. R. A. Gan. B. M. Hujs, P. H. Hi, J	8402040484 8402010110* 8402220107* 8402100420 8402280113	NUREG CONTRACT 40-8768 WASTE MGT 50-317 8	MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E, MACDONALD, C E	8402070540* 8402100425* 8402100427* 8402130242 8402130247	71-5957 71-6206 71-6206 71-9156 71-9186	MARKEY, E J MARKEY, E J MARKEY, E, J, MARKEY, E, J,	8402140044* 8402140050* 8402280045* 8402280045* 8402280045*	FOIA FOIA FOIA FOIA FOIA
-8. J F. -8. J F. -8. J F. -15. L -15. L -15. J J. -15. J J.	8402070372 8402280051 8402020212* 8402100444 8402030373	50-317 8 50-317 8 50-261 0 State Prog 50-219 F	MACDONALD, C E	8402130295 6402130302± 8402130349 8402130364± 8402140514	71-451 71-451 71-1 71-1 71-513	MARLEY, J. A MARSH, L. B MARSH, W. S MARSHALL, J. R MARSHALL, J. R	8402050020 8401100029* 8402210041* 8402010147 8402030458	WASTE MOT TOPREP CONTRACT 50-368 S 50-313 P
ng, F. J. Ng, J. M. OSLEY, D. J. POSER, A. K. PRESTI, C. A.	8402100182* 8402130308 8402080052* 8402160419* 8402270213	FOIA 50-346 B 40-1341 50-285 G NUREG	MACDONALD, C E	8402140519* 8402140613 8402140615* 8402150042* 8402150532	71-513 71-133 71-133 71-6058 71-6601	MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R	8402040107 8402040407 8402070308 8402130040 8402130184	50-368 P 50-368 B 50-368 R 50-313 F 50-313 J

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R	8402130258 8402160293 8402220040 8402220091 8402220476*	50-313 J 50-313 P 50-313 P 50-368 P 50-313 G	MARTIN, T T. MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8402080391 8402070329 8402070348 8402070359 8402070361	50-277	MAXWELL.D C MAXWELL.G F MAXWELL.J MAXWELL.J MAXWELL.J C	8402040133 8402140450* 8402090522 8402090522 8402090521	50-237 8 50-400 G ACRB ACRB ACRS
MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R	8402220488* 8402240035 8402270158* 8402280236 8402280400	50-313 0 50-313 P 50-313 0 50-369 9 50-368 0	MARTIN,T T MARTIN,T T MARTIN,T T MARTEN,T T MARTEN,T T	8402130441 8402140219 8402140309 6402140312 8402140326	50-333 0 50-293 Q 50-293 P 50-272 P 50-317 Q	MAXWELL.JC MAY.CB MAY.EL MAY.JR	8402070521 8402160635 8402160648 8402030277 8402090575	ACRS 40-7455 40-7455 , 50-29 B 71-312
MARSHALL, J S	8402220443	50-445 X	MARTIN.T T	8402150003	50-443	MAYBERRY. 8	8402230404	FOIA
MARSHALL, R S	8402170478	NUREG	MARTIN.T T	8402150005		MCAFEE, C	8402220583*	50-413 E
MARTIN, C J	8402010413	FDIA	MARTIN.T T	8402150222		MCALPINE, E J	8402140156	70-143
MARTIN, D E	8402030117	WASTE MOT	MARTIN.T T	8402150239		MCALPINE, E J	8402140298*	70-143
MARTIN, D O	8204040003*	FDIA	MARTIN.T T	8402150309		MCALPINE, E J	8402150337*	70-143
MARTIN, J B	8402080061*	FOJA	MARTIN.T T	8402150325	50-220 0	MCALPINE,E J	8402280534*	70-143
MARTIN, J B	8402100323*	WASTE MGT	MARTIN.T T	8402160270	50-423 0	MCARTHUR,D A	8402210024	NURE9
MARTIN, J B	8402140372	50-344 O	MARTIN.T.T	8402160276	50-213 0	MCBREARTY,R A	8402160339*	50-317 G
MARTIN, J B	8402140377*	50-344 O	MARTIN.T.T	8402160310	50-277 0	MCBRIDE,M	8402020326*	50-219 G
MARTIN, J B	8402150027	State Prog	MARTIN.T.T	8402160312	50-443 0	MCBRIDE,M.	8402150245*	50-271 G
MARTIN, J B	8402270321*	50-341 T	MARTIN.T.T	8402160331	50-317 Q	MCBRIDE,M	B40224003B*	50~293 0
MARTIN, J D	8402020141	50-397 R	MARTIN.T.T	8402160351	50-334 Q	MCBRIDE,M	B402240046*	50~293 0
MARTIN, J D	8402030357	50-397 S	MARTIN.T.T	8402160359	50-289 F	MCBRIDE,M H	8402080393*	50~333 0
MARTIN, J D	8402140377	50-397 S	MARTIN.T.T	8402160392	50-352 Q	MCCABE,E	8402220169	50~397 B
MARTIN, J D	8402220389	50-397 S	MARTIN.T.T	8402160452	50-309 Q	MCCABE,E C	8005020332*	FOIA
MARTIN.J D.	8402220512	50-397 8	MARTIN T T	8402160477	50-388 Q	MCCABE,E C	8402020252*	50-387 Q
MARTIN.J D	8402270111	50-397 8	MARTIN T T	8402210076	50-277 F	MCCABE,E C	8402150170*	50-354 Q
MARTIN.J D	8402270125	50-397 8	MARTIN T T,	8402220259	50-320 F	MCCABE,E C	8402240106*	50-322 Q
MARTIN.J D	8402270131	50-397 8	MARTIN T T	8402220354	50-352 Q	MCCAFFREY,B R	8402040405	50-322 F
ARTIN.J D	8402270273	50-397 5	MARTIN T T	8402220354	70-1362	MCCAFFREY,B R	8402150174	50-322 R
RTIN, J K RTIN, J B RTIN, R T RTIN, R A RTIN, R A	8402160175* 8402270305 8402270306 8201250042* 8402010111	50-266 P 50-277 G 50-443 G FDIA NUREG	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8402220432 8402220446 8402220463 8402240019 8402240021	40-1386 70-364 50-322	MCCAFFREY, B R MCCAFFREY, B R MCCANN, O M MCCANN, O M MCCLEBKEY, K E	8402150231 8402220198 8402270322# 8402270347# 8402170114	50-322 E 50-322 F FD1A FD1A 50-322 Q
ARTIN.R E ARTIN.R E MARTIN.R E MARTIN.T J MARTIN.T J	8402020452 8402130128 8402210001 8402020261 8402030387	50-352 A 50-352 A 50-352 A 50-354 S 50-354 S	MARTIN.T T MARTIN.T T MARTIN.T T MARTIN.T T MARTIN.T T	8402240022 9402240044 8402240089 8402240090 8402240130	70-371 50-219 0 50-277 0 50-387 0 50-220 F	MCCLEBKEY, K E, MCCLEBKEY, K E, MCCLEBKEY, K E, MCCLEBKEY, K E	8402170114 8402170139* 8402170139* 8402170161* 8402170161*	50-322 0 50-322 0 50-322 0 50-322 0 50-322 0
MARTINIT J	8402060374	50-354 B	MARTIN, T T	8402270252	50-387	MCCLESKEY, K E	8402170188#	50-322 Q
MARTINIT, J	8402080271	50-354 B	MARTIN, T T	8402270330		MCCLESKEY, K E	8402170188#	50-322 Q
MARTINIT J	8402220120*	50-354 G	MARTIN, T T	8402280159		MCCLURE, J A	8402290058#	FDIA
MARTINIT T	8402020001	50-220 G	MARTIN, T T	8402280205		MCCOLLOM, K, A	8402090121	50-445 Q
MARTINIT T	8402020119	50-320 G	MARTIN, T T	8402280404		MCCOLLOM, K, A	8402090161	50-445 Q
1ARTIN, T T	8402020149	70-2362	MARTIN, T T	8402280459	50-353 Q	MCCORQUODALE, D.	8402010262	50-275 U
1ARTIN, T T	8402020150	50-213 G	MARTIN, T T	8402290186	50-387 Q	MCCRACKEN	8402270128*	50-289 Q
5ARTIN, T T	8402020182	50-247 G	MARTIN, T, T	8402290204	50-213 Q	MCCRACKEN, C.	8208310444*	50-289 P
1ARTIN, T T	8402020215	70-371	MARTIN, T, T,	8402290210	50-423 Q	MCCRACKEN, C	8209280423*	50-289 P
1ARTIN, T T	8402020234	50-293 G	MARTIN, T, T	8402290239	50-352 Q	MCCRACKEN, C.	8211090398*	50-289 P
MARTIN, T T MARTIN, T T MARTIN, T, T MARTIN, T T. MARTIN, T, T.	8402020271 8402020275 8402020317 8402020320 8402020322	40-672 50-388 G 50-334 G 50-219 G 50-352 G	MARTIN, T. T MARTIN, T T MARTIN, T T MARTIN, T. T MARTINEX, P. A	8402270264 8402270287 8402270295 8402270325 8402020046*	40~672 50~317	MCCRACKEN, C MCCRACKEN, C. MCCRACKEN, C MCCRACKEN, C E MCCRACKEN, C. E.	8301060232* 8303110519* 8304270371* 8402290140* 8402290149*	50-289 P 50-289 P 50-289 P 50-289 ©
MARTIN, T T. MARTIN, T. T MARTIN, T T MARTIN, T Y MARTIN, T T.	8402020328 8402020335 8402020337 8402020352 8402020353	40-6920 50-245 G 70-221 50-293 G 50-244 G	Marton, K. V. Masnix, M. T. Mason, G. C. Mason, G. C. Mason, G. C.	8402210039# 8402210328 8402040205 8402100212 8402140010	CONTRACT 50-320 P 50-327 S 50-327 S 50-327 S	MCCRACKEN, C E MCCRACKEN, C E. MCCRACKEN, C E. MCCRACKEN, C E MCCRACKEN, C, E.	8402270168* 8402270177* 8402270206* 8402270223* 8402270233*	50-289 Q 50-289 Q 50-289 Q 50-289 Q
MARTIN:TT	8402030274	50-334 F	Magon, C. C.	8402140191	50-327 6	MCCRACKEN, C. E	8402270246*	50-289 0
MARTIN:TT,	8402030374	50-336 G	Magon, C. C.	8402140206	50-327 8	MCCRACKEN, C. E.	8402270260*	50-289 0
MARTIN:TT,	8402030424	50-289 F	Magon, C. G.	8402140301	50-327 8	MCCRACKEN, C. E	8402270270*	50-289 0
MARTIN:TT	8402060036	50-219 G	Magon, C. G.	8402140391	50-328 8	MCDONALD, D. Q	8402010473*	50-250 8
MARTIN:TT	8402060086	70-364	Magon, C. C.	8402220161	50-327 8	MCDONALD, D. Q.	8402270053	50-250 F
MARTIN,T T,	8402060110	70-710	Maeon, C C.	9402280367	50-327 B	MCDONALD, D. O.	8402280141*	50-250 P
MARTIN,T T	8402070001	50-309 G	Maeon, C C.	8402280441	50-328 S	MCDONALD, D. O	8402280155*	50-250 P
MARTIN,T T,	8402070093	50-286 G	Maeon, C C.	8402280451	50-327 S	MCDONALD, D. O	8402280158*	50-250 P
ARTIN,T I,	8402070168	50-289 G	Maegaro, B. A	84022170513	NUREO	MCDONALD, D. O.	8402280164*	FDIA
ARTIN,T,T	8402070180	50-412 G	Maet, P. K	8402210024	NUREO	MCDUFFIE, M. A	8402130175	50-261 P
ARTIN, T T	8402070182	50-286 Q	MATHEBON, B. M	8402060194	HABTE NOT	MCDUFFIE, M A. MCDUFFIE, M A MCDUFFIE, M A MCDUFFIE, M A MCDUFFIE, M A	8402130338	50-400 E
ARTIN, T, T	8402070230	50-247 Q	MATHEMB, C. B	8312200154*	50-312 P		8402140377	50-261 P
ARTIN, T, T	8402070241	50-213 Q	MATTHEMB, B A	8402060145	50-261 G		8402140390	50-261 P
ARTIN, T T	8402070392	50-233 Q	MATTHEMB, T P	8402220061	50-285 R		8402150275	50-324 Q
ARTIN, T T	8402080285	50-271 Q	MATTIA, M J	8402150417*	CONTRACT		8402220196	50-400 M
ARTIN, T T ARTIN, T. T. ARTIN, T T ARTIN, T T ARTIN, T T	8402080330 8402080335 8402080345 8402080354 8402080355	50-317 Q 50-423 Q 50-277 Q 50-443 Q 50-320 Q	MATTIA: M. J. MATTBON: D. R. MATTBON: D. R. MATTBON: D. R. MATTBON: B. J.	8402140488* 8402010291 8402020054 8402030505 8110300111*	CONTRACT WASTE MOT WASTE MOT WASTE MOT SO-466 O	MCDUFFIE, M. A, MCDUFFIE, M. A MCFARLAND, C, R MCFARLAND, C, R, MCGARRY, J. M	8402280407 8402270165 8402140145* 8402280073* 8402080164	50-400 G 50-400 F 50-366 G 50-413 G 50-413 G
ARTIN, T. T.	8402080362	50-219 0	MATTBON, R. J.	8206030327*	TOPREP	MCGARRY, J. M.	8402080164	50-413 0
ARTIN, T. T	8402080366	50-387 0	MATTBON, R. J.	8210200329*	50-289 P	MCGARRY, J. M	8402080171	50-413 0
ARTIN, T. T.	8402080368	50-389 0	MATTBON, R. J.	8402230244*	50-382 8	MCGARRY, J. M	8402080171	50-413 0
ARTIN, T. T.	8402080372	50-245 0	MAUCH, M. L.	8402080077*	40-1341	MCGARRY, J. M.	8402100125	50-413 0
IARTIN, T. T.	8402080386	50-333 0	MAXFIELD, B. W	8402060432	NUREG	MCGARRY, J. M	8402100125	50-413 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MANA M. M. CARNA M. CARNA M. CARNA M. CARNA M. CARNA M. CARNA	8402100145 8402100145 8402220275 8402220275 8402220273	50-413 0 50-413 0 50-413 0 50-413 0 50-413 0	MEDFORD, M O	8402090172 8402150383 8402170224 8402170252 8402210062	50-206 P 50-206 P 50-206 P 50-361 F 50-206 P	MILLER.H A MILLER.H E MILLER.H E MILLER.H I MILLER.H I	8402030071 8402070185 8402230050 8402140222 8402140222	50-484 A 50-537 Q 50-354 Q 50-454 Q 50-454 Q
May, J. H P. Krayer P. Krayer P. Krayer P. Krayer P. Krayer P. Krayer	8402280373* 8402140322 8402140410 8402220244 8402230228	50-413 G 50-416 G 50-416 S 50-416 F 50-416 S	MEDFORD, M O MEDFORD, M O MEDFORD, M O MEDLOCK, R L MELLOR, K	8402210103 8402240006 8402280276 8402230041 8402230034	50-361 P 50-206 P 50-206 P 40-8452 50-312 8	MILLER,M I MILLER,M I MILLER,M I MILLER,M I MILLER,M S	84021 60227* 84021 60227* 84021 60251 84021 60251 84021 50187	50-454 G 50-454 G 50-454 G 50-454 G 50-322 G
Sachy, J. P	8402270404	50-416 8	MELLOR, K	8402230206	50-312 8	MILLER,M 8	8402150187	50-322
Sachy, J. P,	8402280575	50-416 G	MENDEZ, R	8402100215*	50-456 G	MILLER,M 8	8402150193	
Sachy, J. P	8402290012	50-416 P	MENDEZ, R	8402150353*	50-454 G	MILLER,M 8	8402150193	
Sachy, J. P	8402270194	50-416 8	MENDEZ, R	8402170187*	50-454 G	MILLER,M T	8402030334*	
Sachy, R. H	8402020340	50-331 P	MENBING, R W	8402210021	50-275 P	MILLER,M T.	8402150314*	
Euchy, R. W	8402030329	50-331 P	MERRIWEATHER, N	8402140183*	50-348 G	MILLER,M T	8402240028*	50-293 G
Euchy, R. W	8402030379	50-331 P	MERRIWEATHER, N	8402280285*	50-413 G	MILLER,M T	8402290328*	50-267 G
Euchy, R. W	8402030403	50-331 P	MEBLER, R. B	8402070166	50-148 V	MILLER,P D.	8402290164*	FOIA
Euchy, R. W	8402030427	50-331 P	METZGER, J. R	8402150385	I&E	MILLER,R.D	8402160534*	TOPREP
Euchy, R. W	8402040250	50-331 S	METZGER, J. R	8402270146	I&E	MILLER,R.L	8402170304	NUREG
AUGHY, R. M	8402070119	50-331 P	MEYER, G	8402080374*	50-387 Q	MILLER, V L	8402070279#	FDIA
AUGHY, R. M	8402140476	90-331 P	MEYER, G W	8402020242*	50-293 Q	MILLER, W D	8402130628	50-271 F
AUGHY, R. M	8402150212	90-331 P	MEYER, G W	8402080360*	50-320 Q	MILLER, W H	8402150378#	50-387 G
AUGHY, R. M	8402150305	50-331 P	MEYER, G W	8402140288*	50-213 Q	MILLER, W J	8402140447	50-331 B
AUGHY, R. M	8402160337	90-331 P	MIKUWSKI, J	8402070052*	FOIA	MILLER, W J	8402280332	50-331 B
Muchy, R. W	8402290265	50-331 G	MIKOHSKI, J	8402270244	FOIA	MILLER, W J. MILLER, W O. MILLER, W O. MILLER, W O. MILLER, W O	8402280470	50-331 S
Kudrick, P	8402130414	XPORTLIC	MIKOHSKI, J	8402090057*	FOIA		8402010186	50-302 P
Kudrick, F.	8402150500	XPORTLIC	MIKOHSKI, J	8402090042*	FOIA		8402070525	50-327 P
Kuch, J. K.	8402090472*	FOIA	MIKOHSKI, J	8402090064*	FOIA		8402070558	50-250 P
Kuch, J. K.	8402090557*	FOIA	MILETI, D B	8402140058*	50-022 G		8402130616	50-269 P
OYERN	8402080067*	40-1341	MILEY, G H MILLER, D E MILLER, D B, MILLER, D B, MILLER, D B	8402150232	50-151 R	MILLER.W O	8402130620	50-219 F
OYERN, J. J	8402030345	PR		8402150254*	50-4 G	MILLER.W O	8402130636	50-313 F
OYERN, J. J.	8402270453*	70-487		840222020*	50-309 G	MILLER.W O	8402130649	50-327 P
RATH, R. B.	8402030008	50-309 8		840222020*	50-309 G	MILLER.W O	8402140009	50-243 P
REGOR, E. W	8402160344*	FOIA		8402220218*	50-309 G	MILLER.W O	8402170189	50-316 P
RESOR, L. O. NIAE, D. R. NIAE, D. R. NIAE, D. R. NIAE, S. A.	B402170164* B402060002* B4020B0477* B402220307* B311210544*	50-456	MILLER, D. 8 MILLER, D. 8 MILLER, D. 8 MILLER, H. J. MILLER, H. J.	8402220218* 8402220230* 8402220230* 8402010002 8402010202	50-309 0 50-309 0 50-309 0 WASTE MOT WASTE MOT	MILLER.W O MILLER.W O. MILLER.W O MILLER.W O	8402210492 8402230197 8402230420 8402280098 8402280740	50-282 F 50-513 A 50-324 P 50-213 P 50-280 P
URREN. H. J.	8402010220	50-275 0	MILLER, H. J.	8402010227	Mabte Mot	MILLER, W O	8402270344	50-348 F
URREN. H. J	8402010222	50-338 0	MILLER, H. J	8402010229*	Habte Mot	MILLS, L M	8401050474	50-438 B
URREN. H. J	8402140158	50-413 0	MILLER, H. J	8402010238	Habte Mot	MILLS, L M	8402010155	50-327 P
URREN. H. J	8402160130	50-413 0	MILLER, H. J	8402010424	Habte Mot	MILLS, L M	8402030011	50-438 B
NERNEY, J. J	8402160492*	TOPREP	MILLER, H. J	8402010324	Habte Mot	MILLS, L M	8402030013	50-438 B
ntyre, J. M Enna. E. Enna. E. K. Uney, C. J Ain, H. E.	8402170311 8402170231* 8402080292 8402030418 8402170280	NUREG 50-206 P 50-206 P 50-395 S PR	MILLER, H J MILLER, J B. MILLER, J R MILLER, J, R MILLER, J, R	8402030272 8402100348 8402010276 8402010277 8402010475	WASTE MOT 50-262 P 50-338 P 50-348 P	Mills, L M Mills, L, M Mills, L, M Mills, L, M Mills, L, M	8402030168 8402030226 8402060232 8402060261 8402060382	50-390 F 50-390 B 50-390 K 50-259 G 50-259 F
ACONLIN. L. EAREN, T. EAREN, T. EAREN, T. WAMAN, V. L.	8402270238 8402170008 8402170014 8402230274 8402150418	50-389 8 CONTRACT CONTRACT CONTRACT 71-133	MILLER, J R MILLER, J R MILLER, J, R MILLER, J R MILLER, J R	8402010478 8402020420 8402030155 8402070470 8402070437	50-348 Q 50-336 P 50-344 P 50-246 P 50-344 P	MILLB.L.M. MILLB.L.M MILLB.L.M MILLB.L.M.	8402070204 8402070211 8402080197 8402080200 8402080226	50-259 P 50-438 A 50-438 B 50-438 B 50-438 C
URMAY, C. M.	8402150124	20-385 0	MILLER, J. R	8402090590	50-313 P	MILLS, L. M	84020902&0	70-2910
URMAY, C. M	8402150124	20-385 0	MILLER, J. R.	8402130154*	50-336 P	MILLS, L. M	8402090325	50-370 A
URMAY, C. M	8402150135	20-385 0	MILLER, J. R	8402130274	50-317 P	MILLS, L. M	8402100214	50-390 F
URMAY, C. M	8402150135	20-385 0	MILLER, J. R	8402130375	50-338 P	MILLS, L. M	8402130279	50-327 P
URMAY, C. M.	8402150135	20-385 0	MILLER, J. R	8402130384	50-344 P	MILLS, L. M.	8402130316	50-259 F
erray, C. M.	8402160714	50-322 0	MILLER: J R.	8402130442	50-309 P	MILLS, L. M.	8402190380	50-327 F
Erray, C. M.	8402220148	50-322 0	MILLER: J.R	8402130451	50-335 P	MILLS, L. M.	8402130397	50-438 B
Erlyn, C. M.	8402220148	50-322 0	MILLER: J R	8402130615	50-285 Q	MILLS, L. M	8402130490	50-257 F
Erlyn, B.	8402170335	Waste Mgt	MILLER: J.R	8402140078	50-309 P	MILLS, L. M	8402140071	50-438 B
Erlli, B.	8402220567*	50-413 E	MILLER: J.R	8402160577	50-317 F	MILLS, L. M	8402140104*	50-259 G
EILLi ³ . EILLi ^C . A. EILLi ^C . A. EILLi ^C . A.	8402220372* 8402020234 8402020327 8402030247 8402070394*	50-413 E 50-333 B 50-333 B 50-333 Q 50-333 Q	Miller, J R. Miller, J. R Miller, J. R Miller, J. R Miller, J. R.	8402160561 8402160570* 8402160605* 8402160670 8402170018*	50-313 P 50-266 P 50-338 P 50-335 F 50-317 P	MILLE, L. M MILLE, E. M MILLE, E. M MILLE, L. M MILLE, L. M	8402140112* 8402140132* 8402140166 8402140175 8402140250*	50-259 Q 50-259 Q 50-259 Q 50-390 A 50-327 Q
EILL: C. A.	8402100258	50-333 R	MILLER, J. R	8402170042	50-338 P	MILLB.L.M	8402140252*	50-239 0
EILL: C. A.	8402130065*	50-333 G	MILLER, J. R.	8402170428	50-313 F	MILLB.L.M	8402140276*	50-289 0
EILL: C. A.	8402220405	50-333 S	MILLER, J. R	8402170431	50-309 P	MILLB.L.M	8402140351	50-438 8
EILL: C. A.	8402290255	50-333 S	MILLER, J. R	8402220604	50-309 F	MILLB.L.M	8402140370	50-391 8
EILL: W. M.	8402070266*	GA977,	MILLER, J. R	8402230013	50-309 G	MILLB.L.M	8402140371	50-390 8
ETLL: W. PS.	8402220508*	QA999	MILLER; J. R.	8402230227	50-285 P	MILLB, L. M	8402140397	50-390 F
EEK, E. W.	8402090438*	FOIA	MILLER; J. R.	8402230333	50-344 F	MILLB, L. M	8402140424*	50-259 Q
MERSON: P. R.	8402080287	50-260 8	MILLER; J. R.	8402230405	50-338 P	MILLB, L. M	8402140432	50-438 8
TERNAM: T. J	8402060342*	50-409 Q	MILLER; J. R.	8402240245	50-313 F	MILLB, L. M	8402140431	50-259 P
CA. J.	8402270561	Waste Mgt	MILLER; J. R.	8402150340	50-344 8	MILLB, L. M	8402150291	50-327 Q
ELROS. N. S	8402090411*	FOIA	MILLER, L K.	8402100201	50-272 R	MILLB,L M	8402150355	50-370 G
FORD. N. O.	8401030275	50-361 P	MILLER, L. K	8402100204*	50-272 R	MILLB,L M	8402140048	50-370 A
FORD. N. O.	8402010136	50-206 P	MILLER, L. K	8402210054	50-272 R	MILLB,L M.	8402140089	50-370 F
FORD. N. O.	8402020362	50-361 F	MILLER, L. K	8402210140	50-311 R	MILLB,L M.	84021400277	TOPREP
FORD. N. O.	8402030211	50-206 P	MILLER, H.	8402280724	50-289 G	MILLB,L.M	8402170051	50-370 A

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESBION NUMBER	SUBJECT CATEGORY
MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8402170112 8402170152 8402210071 8402210110 8402210148	50~370 A 50~438 A 50~257 P 50~327 P 50~327 F	MOLHOLT: B MOLHOLT: B MOLHOLT: C MONAHONA J A MONAHONA J A MONAHONA J A	8402130304 8402070393 8402070277 8402070277 8402280437	50-320 P 50-206 8 50-322 Q 50-322 G 50-322 G	MORRONGIELLO, A MORROW, B T MORSE, E A MORSE, E A MORTENSEN, W P	8402270432* 8402140479 84020302240 8402030303 8402270080*	50-254 Q State Prog 50-316 B 50-315 S 50-344 Q
MILLS, L M MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8402210278 8402210301 8402220007 8402220014 8402220031	50-259 F 50-259 F 50-390 S 50-390 S 50-438 S	MONAGHAN, J A MONTGOMERY, C R MONTGOMERY, C R MONTGOMERY, D M MONTGOMERY, D M	8402280437 8402020240 8402060180 8402140259* 8402140356*	50-322	MORTENSEN, W P MORTON, K V MORTON, K V MORTON, K V MORTON, K V	8402270146* 8402010346* 8402070013* 8402070040* 8402100371*	50-344 F 50-259 V CONTRACT CONTRACT CONTRACT
MILLES, L M MILLES, L M MILLES, L M MILLES, L M	8402220096 8402220128 8402220175 8402220219 8402220315	50-327 F 50-438 S 50-438 S 50-391 S 50-438 S	MONTGOMERY, J L, YRAMODTNOM MONTGOMERY, J L, YRAMODTNOM MONTGOMERY, J L, YRAMODTNOM	8402150157* 8402140419* 8402080172* 8402160354* 8402280536*	50-413 G 50-285 G 40-1341 50-445 G 50-445 G	MORTON, K V MORTON, K V MORTON, K V MORTON, K V MORTON, K, V	8402130106= 8402130141= 8402150524= 8402210025= 8402210041=	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACY
MILLS, E M MILLS, E M MILLS, L M MILLS, L M MILLS, L M	8402220428 8402230209 8402230223 8402270020 8402270087	50-327 F 50-390 F 50-438 G 50-438 S 50-438 S	MOONEY, J A MOONEY, J P MOONEY, J P MOONEY, J P MOORE, E B	8402150380 8402140247 8402140267 8402270318 8402060341	50-329 0 50-247 8 50-247 8 50-247 8 NUREO	MORTON, K V MORTON, K V MORTON, K V MORTON, K V MORTON, K V,	8402210044* 8402210054* 8402210088* 8402210158* 8402210172*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
MILLS.L M MILLS.L M MILLS.L M MILLS.L M	8402270191 8402270357 8402270393 8402270395 8402270403	50-390 S 50-438 S 50-438 S 50-438 S 50-438 S	MOORE, J E MOORE, J E MOORE, J E MOORE, J E MOORE, J E	8402010193 8402010223 8402140127 8402140130* 8402220835	50~400 G 50~400 G 50~247 G 50~247 G 50~400 G	MORTON,K V MORTON,K V MORELEY,N C MORIER,M O	8402240371* 8402280604* 8402290417* 8002070305* 8402240247*	CONTRACT CONTRACT CONTRACT FDIA 50-220 P
MILLS:L M MILLS:L M MILLS:L M MILLS:L M	8402280022 8402280185 8402280224 8402280259 8402280368	50-259 @ 50-327 P 50-259 P 50-390 E 50-327 P	MODRE.J P MODRE.J P MODRE.R B MODRE.R D MODRE.R D	8301250528* 8304250292* 8402060446 8402060464* 8402100137	50-289 P 50-289 P 50-10 F 50-10 F 50-10 F	MOBLAK,T MOTES,B.G. MOUNT,D K MOWRY,W R MOWRY,W R	8402070357* 8402280010 8402080171 8402090268 8402240132	50-320 G NUREO PR 70-734 50-87 R
MILLS, L M MILLS, L M MILLS, L M MILLS, L M MILSTEIN, H E	8402280478* 8402280528* 8402280530* 8402280556 8402220138	50-259	MODRE, R. D MODRE, R. D MODRE, R. D MODRE, R. D MODRE, R. N	8402100221 8402130220 8402140118 8402150358 8402010340	50-254 F 50-10 F 50-254 F 50-237 F XPDRTLIC	MDWRY, W R MDWRY, W R MROCZKA, E MROCZKA, E MROCZKA, E J	8402270078 8402280494 8402010232* 8402010237* 8402030274	50-163 R 50-89 P 50-213 F 50-213 F 50-245 B
MILTENBERGER MINECK,DL MINECK,DL MINECK,DL MINECK,DL	8402270385 8402030244 8402070013 8402070015 8402070300	50-483 A 50-331 8 50-331 8 50-331 5 50-331 5	MOORE, R. N. MOORE, B. J.	8402010356 8402010426 8402010428 8402080510 8402010437*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC CONTRACT	MRDGZKA, E. J MRDGZKA, E. J MRDGZKA, E. J MRDGZKA, E. J MRDGZKA, E. J	8402030274 8402070305 8402070305 8402080251 8402080251	50-245 8 50-336 8 50-336 8 50-336 8
MINECK, D L MINECK, D L MINECK, D L MINECK, D L	8402140447 8402150127 8402220006 8402230125 8402270200	50-331 S 50-331 S 50-331 R 50-331 R 50-331 R	MODRE, V A MOGS, D W MORAN, D M MORAN, D H MORAN, D H	B211040035* 8402080126 8402080444 8402130590 8402140025	TOPREP WASTE MOT TOPREP TOPREP TOPREP	MROCZKA, E J MROCZKA, E J, MROCZKA, E J MROCZKA, E, J MROCZKA, E, J	8402100206 8402100206 8402150214 8402150214 8402150348	50-334 8 50-334 8 50-334 8 50-334 8 50-334 8
MINECK, D L MINECK, D L MINECK, D L MINER, B MINER, S	8402280332 8402280339 8402280470 8402030087 8402070012	50-331 5 50-331 8 50-331 8 50-312 P 50-312 P	MDRAN, D H MORAN, D H MORAN, T M MORAN, T M MORELAND, J W	8402230433 8402270061 8212150120# 8304130440# 8402080127*	TOPREP TOPREP 50-289 P 50-289 P 50-528 R	MRDCZKA, E. J. MRDCZKA, E. J. MRDCZKA, E. J. MRDCZKA, E. J. MRDCZKA, E. J.	8402130348 8402160002 8402160002 8402170223 8402170223	50-334 B 50-336 0 50-336 G 50-336 S 50-336 S
MINER, B MINER, B MINOGUE, R B MINOGUE, R B MINOGUE, R B	8402070231* 8402150502 8310270388 8402070264 8402210411*	50-387 A 50-312 P RES REB MISC	MORELAND, PE Morgan, BJ Morgan, C Morgan, C, Morgan, C	8402020332* 8402150387* 8402070154 8402070154 8402070154	40-6920 50-329	MROGZKA, E. J MROGZKA, E. J MROGZKA, E. J MUDD, C. H. MUDD, C. H.	8402220378 8402280473 8402280473 8402030377 8402030404	50-336 8 71-6601 71-6601 50-348 F 50-348 F
MINTON, L E. MINTON, L E MIRACLE, R D MIRAGLIA, F J MIRAGLIA, F J	8402100133 8402100133 8402160539# 8204070041# 8307180123#	50-322 G 50-322 G 50-424 C 50-528 A FD1A	MORGAN,RE MORGAN,RE MORGAN,RE MORGAN,RE MORGAN,RE	8402030279 8402030341 8402150244 8402150258* 8402170178	50-261 \$ 50-261 F 50-261 F 50-261 G 50-261 R	MUDD, C H MUFFETT, J. W. MUFFETT, J W MULLER, D. R MULLER, D. R.	8402150142 8402070216* 840210020B* 8305020051* 8308150030*	50-348 F 50-373 G 50-255 G 50-287 P 50-287 P
MIRAGLIA:F J. MIRAGLIA:F.J MIRAGLIA:F.J MIBAK:A MISBIQ:D E	8402070541 8402080439 8402270008 8402220332 8402240152	50-354 E 50-410 E 50-412 E 50-254 R 50-346 S	MORGAN, R. E MORGAN, R. E MORGAN, R. E MORGAN, R. E MORKEN, D. J	8402280071 8402280170* 8402280357* 8402270117 8402100421	50-261 G 50-261 G 50-261 G 50-261 S 50-259 S	MULLER, D. R MULLEY, Q. A. MULLIKIN, R. P. MULLIKIN, R. P MUNDERLOH, D. J	8402090477* 8402240163* 8402220393* 8402220475* 8401170226	FDIA 50-382 A 50-382 Q 50-482 Q 50-285 R
MITTLIR L. MITTLIR L MITTLIR, L MITTLIR, L MITTLIR L	8401230422 8402010139 8402030327 8402070324 8402080185	50-354 A 50-354 A 50-354 F 50-354 A 50-354 X	MORLEY, G M MORLEY, G M MORLEY, J A MORLEY, J A MORLEY, J, A	8402210198 8402210279 8402010011 8402020440 8402030120	SO-259 B SO-277 F HASTE MOT HASTE MOT HASTE MOT	MUNRO, J. F. MUNRO, J. T. MURLEY, T. E MURLEY, T. E MURLEY, T. E.	8402280570* 8402140619 8402040283 8402090441* 8402100433	50-416 0 71-9187 50-271 G FDIA State Prog
MITTL,R L MITTL,R L MITTL,R,L MITTL,R,L, MIZUND, G S	8402230002 8402230078 8402230075 8402280312 8402010230	50-354 C 50-354 K 50-354 A 50-354 A 50-445 G	MORLEY, J A MORLEY, J A. MORLEY, J A MORLEY, J A. MORLEY, J A.	8402100278 8402100325 8402100328 8402100331 8402100472	Waste Mot Waste Mot Waste Mot Waste Mot Waste Mot	MURLEY, T. E MURLEY, T. E. MURLEY, T. E. MURLEY, T. E. MURLEY, T. E.	8402150002 8402150503 8402160340 8402220272 8402280168	50-320 0 50-309 H State Prop 50-29 0 50-410 0
MIZUNO.0, 8 MIZUND.0 9 MIZUNO.0 8 MIZUNO.0 8 MIZUNO.0 9	8402010231 8402070074 8402140168 8402140170 8402220187	50-445	MORLEY, J A MORLEY, J A MORLEY, J A. MORLEY, J, A MORRILL, P J	8402100495* 8402140584 8402170330 8402280247 8402140471*	WABTE MOT WABTE MOT WABTE MOT WABTE MOT 50-275 G	MURPHY, D. J. MURPHY, J. D. MURPHY, J. H. MURPHY, L. Q	8402070517 8402060478 8402070523 8402140349* 8402030100	71-1 NUREQ 71-9071 GA999 CONTRACT
MIZUNO, G. B. MIZUNO, G. S. MOE, H. F. MDEGGENBERG, D. MOFRIO, M. D.	8402270063 8402270073 8402090227* 8402010147 8402090108	50-445 0 50-445 0 FOIA 50-348 8 50-245 F	Morris, P.A. Morris, P.A. Morris, P.A. Morris, P.A. Morrison, W.M.	8402090476* 8402100167 8402150131 8402280443 7903020085*	FDIA 50-322 G 50-344 G 40-2061 FDIA	MURPHY, L. Q. MURPHY, M. E MURPHY, M. E MURPHY, M. R MURPHY, M. R.	8402030104 8402220280* 8402220341* 8402080178 8402080178	CONTRACT 50-313 0 50-285 0 HABTE MOT HABTE MCT

ROHTUA	ACCESTION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
м.Брну, к в м.Брну, к в м.Брну, к р м.Врну, к р м.Врну, к р	8402080182* 8402080182* 8402130424 8402170269 8402240111*	WASTE MGT 71-9151 50-271 R 50-29 P	NEFF.J O NEFF.J O NEFF.J O NEFF.J O NEFF.J O	8402010340 8402010343 8402010377 8402010427 8402010430	HASTE MGT HASTE MGT HASTE MGT HASTE MGT HASTE MGT	NORBERO, J A NORBERG, J A NORDERHAUG, L R NORDERHAUG, L R NORDERHAUG, L R	8311210028* 8402270327* 8402030265 8402140111 8402220408	FOIA FOIA 50-397 0 50-530 8 70-1257
M,RRAY, B M,FRAY, B M,FRAY, B M,FRAY, B M,FRAY, B	6402030221* 6402030238* 6402030363* 6402220248* 6402220261*	50-313	NEFF, J D NEFF, J D NEFF, J D NEFF, J D	B402010443 B40201052B B402010529 B402020207 B402020374	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT	NORDERHAUG, L. R NORDERHAUG, L. R NORDERHAUG, L. R NORDERHAUG, L. R NORDERHAUG, L. R	8402220411* 8402220418* 8402220449 8402220458* 8402220565	70-1257 70-1257 70-754 70-754 50-206 0
MARAY, B Maray, B Maray, B Maray, B Maray, T	0402220326* 0402220349* 0402220437* 0402220484* 0402130308	50-285 Q 50-382 Q 50-445 Q 50-296 Q 50-346 S	NEFF, J D NEFF, J D NEFF, J D NEFF, J D	8402030495 8402030497 8402030502 8402030504 8402030509	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT	NORDERHAUG, L R NORDERHAUG, L R NORDERHAUG, L R NORELIUS, C E NORELIUS, C E	8402270024* 8402270069* 8402270080* 8402020341 8402060228	50-344 0 50-344 0 FOIA 50-10 0 50-346 0
USRAY, T D USRAY, T D USRAY, T D USRAY, T D USRAY, T D.	B402130405 B402140105 B402220019 B402220334 B402230093	50-346 8 50-346 F 50-346 8 50-346 R 50-346 R	NEFF, J O NEFF, J O NEFF, J O NEFF, J O	8402030511 8402030514 8402030517 840203051B 8402030521	WASTE MOT WASTE MGT WASTE MGT WASTE MGT	NORELIUS.C E NORELIUS.C E NORELIUS.C E NORELIUS.C E	8402040362 8402070247 8402070355 8402090447* 8402090481*	50-346 0 50-440 0 50-255 0 FOIA FOIA
LPRAY, T D USCENTE, H D USCENTE, H D USCENTE, H D USOUP, D	8402240192 8402100190* 8402100193* 8402170126* 8402070011	90-346 S 50-445 T 50-445 T 50-445 G 50-282 P	NELL' 7 D NELL' 7 D NELL' 7 D NELL' 7 D	8402060014 8402060029 8402060033 8402060049 8402060135	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT	NORELIUS.C E NORELIUS.C E NORELIUS.C E NORELIUS.C E NORRHOLM.L	8402100139# 8402130467 8402280005 8402280564 8402020204*	FDIA 50-237 F 50-456 G 50-341 G 50-286 G
USOLE, D USOLE, D USOLE, D USOLE, D USOLE, D	8402070358 8402100020 8402140011 8402140382 8402150183	50~282 8 50~263 8 50~263 8 50~263 8 50~262 R	MELE' 7' O MELE' 7' O MELE' 7' O MELE' 7' O	8402160618* 8402160625 8402160626 8402270625 8402010093	WASTE MGT WASTE MGT WASTE MGT WASTE MGT 50-280 P	NORRHOLM.L NORRHOLM.L NORRHOLM.L NORRHOLM.L NORRHOLM.L	8402090377* 8402090243* 8402290296 8402020336* 8402070351*	50-247 0 50-286 0 50-272 5 50-272 0 50-272 0
USOLF,D USOLF,D USOLF,D USOLF,D YERS,D ()	B402160473 B402230238 B402240011 B402260382 8402020219*	50~263 P 50~263 P 50~R63 F PR 50~R61 0	NEIGHBORB, J D NEIGHBORB, J D NEIGHBORB, J D NEIGHBORB, J D NEIGHBORB, J D	B402010445 B402080503 B402160631 B402270203 B402070170*	50-280 P 50-280 P 50-280 F 50-305 F 50-373 A	NORRY,P C	8402270007 8402130427 8402020456 8402070422 8402070280	50-272 8 50-295 F 50-295 P 50-272 S CRG
Yerb.do Loal.y Alou.k Llou.k r Axamura.k	8402280081# 8402130329 8402150181# 8402106223# 8402130342	50-324	NELBON, G B. NELBON, G B NELBON, M NELBON, M A NELBON, M A	8402220418* 8402220458* 8402030310 8402030443 8402240036	70-1257 70-754 50-287 F 50-289 P 50-289 F	NDRRY, P G NDRRY, P G NORRY, P G NORRY, P G NOVACHEK, F	8402100430 8402160038 8402170264 8402270378 8402150204	080 080 080 080 50-267
AMAMURA, N AMAMURA, N AMAMAMA, P AMAMAMA, P AMOM, F, R	8402150489 8402150492* 8402130081* 8402130097* 8402060248	XPORTLIC XPORTLIC FOIA FOIA 50-361 P	NELSON, R NELSON, R. H NELSON, R. L NELSON, R. T NELSON, W. R	8402150382* 8402270421 8402130273* 8402070232 8402030099	50-454 Q 50-309 E 50-409 Q 50-133 8 NURE9	NOVAK, T NOVAK, T NOVAK, T M NOVAK, T M NOVAK, T M	8402140499* 8402240323 8303240052* 8312120110 8312230127*	50-309 50-416 50-410 50-454 50-312
UNSTAD, R. K LPUDA, G LPUDA, G LPUDA, G LPUDA, G	8402010115 8402020170* 8402020338* 8402140373* 8402240095*	NUREQ 50-247 G 50-245 G 50-334 G 50-277 G	NEMECEK, A D NCRBES, V NEUDER, S, M NEUMANN, M R NICHOLARDS, H	8402240040 8402210066 8402160001 8402010039 8402100341	FDIA 50-443 A WASTE MOT 40-6380 50-263 P	NGVAK, T M NGVAK, T M NGVAK, T M NGVAK, T M	8401170018 8401170055 8402130461 8402160606 8402170010	50-329 50-329 50-390 50-410 50-508
ARDI, A J ARDOCE,P, B ARDOCE,P, B ARDOCE,P, B. ARDOCE,P, B.	8402070508 8402030218 8402030223 8402030245 8402030284	70-1151 50-347 B 50-370 B 50-370 B 50-370 B	NICHOLABY O B NICHOLABY H H NICHOLABY H H NICHOLABY H H	8402030383# 8402080375# 8402160481# 8402220349# 8402220484#	50-313	NOVAK.T M NUNEZ.S B NUOLOSI.J F NUSSBAUMER.D A NUSSBAUMER.D A	8402170257 8402020063 8402240104 8402020101 8402040097	50-528 WASTE MG1 40-4458 WASTE MG1 27-37
RDOCT.P.D. GDOCT.P B GDOCT.P B GDOCT.P B GDOCT.P B	8402030349 8402030391 8402030449 8402140016 8402140184	50-370 8 50-369 8 50-369 8 50-369 8 50-370 8	NICHOLBON'N V NICHOLB'N N NICHOLB'N C NICHOLB'N C	8402160528# 8402160544# 8402220088 8402220088 8402230088	50-424 C 50-424 C 50-352 Q 50-352 G 50-10 Q	NUSSBAUMER, D A NUSSBAUMER, D A B'CONNELL, W J B'CONNGR, J J G'CONNGR, P W	8402100300 8402170514 8402210021 8402280410 8402100370	WASTE MOT WASTE MOT 50-295 P 50-10 I 50-482 G
ADOCIP B ADOCIP B. ADOCIP.B ADOCIP.B. AROMIL	8402270101 8402270304 8402280422 8402280507 84020803&1*	50-369 8 50-370 8 50-369 8 50-370 8 50-443 9	NICHOLSON, N A NICHOLSON, T J NICHOLSON, T J NICOLARAS, H	8402270392* 8402030264* 8402030531* 8402240373 8402010382	50-282 G WASTE MOT WASTE MOT NUREG 50-263 P	O'DONNELL, FR O'DWYER, GF O'DWYER, GF O'NEILL, J O'NEILL, J	9402090461 8402070216* 8402270075* 8402130259 8402140045	RES 50-373 (50-454 50-155 50-155
MROHAL MSCHELO MTARAJAH B MTANNAH R MENTIAR	8402240050* 8402130508* 8402150570 8402070311* 8402070133*	50-219 G MISC Wate Mot Ga999 50-445 A	NICOLARAS, H NICOLARAS, H NIGHTINGALE, E NIMITT, R L NIMITZ, R L.	8402030112 8402170072 8402020086* 8402030430* 8402150314*	50-263 P 50-263 P 50-358 Q 50-293 Q 50-334 Q	o'NEILL, J O'NEILL, J O'NEILL, J O'NEILL, J	8402150133 8402150138* 8402150147* 8402150153* 8402210185	50-155 50-155 (50-155 (50-155 Q 50-155 Q
ML. B L (FF. D. E (FF. J. D (FF. J. D	8309150480* 8402080282* 8402080286* 8402010001 8402010010	COMMISSION 50-416 P 50-416 P WASTE MOT WASTE MOT	NIMITZIR L. NIMITZIR L NIMITZIR L. NIXIH C. NIXIH C	8402150328* 8402240072* 8402280455 8402030414 8402130321	50-220 G 50-387 G 1&E 50-366 S 50-366 S	O.KEITTA' O b O.KEITTA' O b O.KEITT' O b O.NEITT' O b	8402160233 8402160233 8402010027 8402010038* 8402070356	50-400 0 50-400 0 50-324 0 50-324 0 50-250 0
th'n 0 th'n 0 th'n 0 th'n 0	8402010015 8402010018 8402010026 8402010227* 8402010305	TOM STEAM TOM STEAM TOM STEAM TOM STEAM TOM STEAM	NIX, H C NIX, H C NIX, H. C NIX, H. C	8402140334 8402150391 8402270093 8402270115 8402100402*	50-321 R 50-321 R 50-366 8 50-366 8 70-135	O.KEILTA'? b O.KEITTA'? b O.KEITTA'? b O.KEITTA'? b	8402070360* 8402140070 8402140073 8402140110* 8402140125	50-250 0 50-324 0 50-259 0 50-259 0 State Prog
FF.JO FF.JO FF.JO FF.JO	8402010323 8402010326 8402010327 8402010347 8402010350	WABTE MOT LAME TON TERM TON TERM TON TON TON	NIXON, W A NOONAN, V S NOONAN, V S NOONAN, V S NOONAN, V S	8402230266 8310210337* 8310240142* 8312190055* 8402270271*	40-206 FOIA FOIA FOIA 50-440 A	DAMEITTA'A b DAMEITTA'A b DAMEITTA'A b DAMEITTA'A b	8402140142# 8402140243 8402140243* 8402140334 8402280008	50-257 0 50-257 0 50-257 0 50-424 A 50-424 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
O'REILLY, J P O'REILLY, J P O'REILLY, J P	8402280132 8402280173 8402280192 8402280232 8402280242	50-257	Painter, R L Painter, R L Painter, R L Painter, R L Painter, R L	8402220554* 8402220555* 8402220560* 8402220563*	50-413 E 50-413 E 50-413 E 50-413 E 50-413 E	PARIB.O H PARKER.J PARKER,J PARKER,J PARKER,J	8402150131 8402030342 8402220049 8402220080 8402270144	50-344 9 50-416 8 50-416 8 50-416 8 50-416 9
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8402280249 8402280241 8402280282* 8402280290* 8402280411	50~400	PAINTER, R L	8402220575* 8402220577* 8402220580* 8402220581* 8402220585*	50-413 E 50-413 E 50-413 E 50-413 E 50-413 E	PARKER, J PARKER, J L PARKER, L PARKER, L B PARKINBON, T F	8402270407 8402010368 8402080334# 8402220439# 8402130345	50-416 3 NURE9 50-321 F GA799 50-124 8
O'TOOLE, J D O'TOOLE, J D O'TOOLE, J D	8402280424	50-250 S	PAINTER,R L	8402220587*	50-413 E	PARR.O D	8104270054*	FOIA
	8402280553	70-143	PAINTER,R L	8402220588*	50-413 E	PARR.O D	6307250073*	50-287 P
	8402010140	50-247 R	PAINTER,R L	8402220595*	50-413 E	PARRIS,M	6307060279*	50-247 H
	8402030292	50-247 S	PAISLEY,E J	8402170270	XPORTLIC	PARRISH,R A	6402280031*	FOIA
	8402030373	50-247 S	PALANISHAMY,R	8402070251*	50-352 G	PARSONS,R,M	8402080192	50-400 S
O'TOOLE, J D O'TOOLE, J D O'TOOLE, J D O'TOOLE, J D	8402130529* 6402140247 8402140267 8402220055 6402220066	50-247 F 50-247 S 50-247 S 50-247 F 50-247 P	PALEYIR PALLADINOIN J PALLADINOIN J PALLADINOIN J PALLADINOIN J	6402010483 8209150006* 8304260267* 8306140051* 8309150466*	FOIA FOIA FOIA COMMIBBION	PARSONE, R M PARSONS, R M PARSONS, R M PARSONS, R M PARSONB, R, M	8402140411# 8402140413 8402140417# 8402270131 8402230129#	50-400 G 50-400 S 50-400 Q 50-400 B 50-400 G
D'TOGLE.J D G'TOGLE.J D GDEGAARDEN,R H GERTEL.G.K GESTERLE.R G	8402270318 8402270326 8402140510 8402060669* 8402150387*	50-247 S 50-247 S 71-9080 F01A 50-329 Q	PALLADINO,N J. PALLADINO,N J. PALLADINO,N J. PALLADINO,N J. PALLADINO,N J.	9309150471* 8402010393* 8402060345 8402080068* 8402090415	COMMISSION LOIV COMWISSION COMMISSION	PARSUNB, R M PARTLOW, J, G PASCIAK, W PASCIAK, W PASCIAK, W,	8402280189* 8401070362* 8402020003* 8402060045* 8402060075*	50-400 q 50-322 g 50-220 g 50-219 q 70-364
DESTMANN, M J	8402080280*	50-454 Q	PALLADINO,N J	8402090427	COWNIBBION COWNIBBION COMMISSION COMMISSION	PABCIAK, W	8402290302*	50-307 6
OGLE, K M	8402170451	40-8783	PALLADINO,N J	8402090644		PABCIAK, W J	8402020124*	50-320 6
OKADA, S	8402010447	XPDRTLIC	PALLADINO,N J.	8402090647		PABCIAK, W J	8402080367*	50-217 6
OLLER, R E.	8402220396*	GA799	PALLADINO,N J.	8402100266		PABCIAK, W J	8402080384*	50-245 0
OLMSTEAD, C A	8402130318	50-344 F	PALLADINO,N J	8402100272#		PABCIAK, W J	8402150007*	50-213 6
OLMSTEAD, W J	7904100122*	50-329 A	PALLADINO,N J PALLADINO,N J PALLADINO,N J PALLADINO,N J PALLADINO,N J	8402100277*	COMMISSION	PASCIAX, W, J	8402240025*	50-387 0
OLSEN.A F	8402150414	71-5450		8402140055*	FOIA	PASTVA, M J.	8402030274	50-324 8
OLSEN.K B	8402080097*	40-1341		8402140484*	50-454 A	PASTVA, M J	8402030407	50-324 8
OLSEN.K B	8402080104*	40-1341		8402170007	50-289 T	PASTVA, M J	8402130359	50-324 8
OLSEN.K B	8402080117*	40-1341		8402280027*	FOIA	PASTVA, M J	8402140256	50-324 8
OLSHINSKI, J A	8402280187	State Prog	PALLADINO,N J	8402280061*	FOIA	PABTVA:M J PATAWA:E H. PATON:W D PATTERSON:J D PATTERSON:R.L	8402220553	50-324 8
OLSON, O L	8402010066	Waste Mot	PALLADINO,N J	8402280713	COMMISSION		8402080128	HABTE HOT
OLSON, O L	8402010474	Waste Mot	PALLADINO,N J,	8402270127*	FOIA		8402010214	50-329 Q
OLSON, O L	8402270181	Waste Mot	PALLADINO,N J	8402270271*	FOIA		8402150447	State Prog
OPREA, Q W	8402060385	50-498 B	PALMER	8402240215*	50-315 B		8402170263	50-528 B
OPREA, G W OPREA, G W OPREA, G W OPREA, G W OPREA, G W	8402050414 8402210046* 8402210051* 8402210058* 8402280149	50-478 S 50-478 A 50-478 A 50-478 A 50-478 S	PALMER, R. A PALOMINO, F O PALOMINO, F O PALOMINO, F. O PALOMINO, F. O	8402220089 8402030151 8402030201 8402070199 8402150164	90-315	PATTERSON, R L PATTERSON, W F PATTISON, R B PATTY, D F PATTY, D, F,	8402220255 8402220262 8402270014 8402140422* 8402170146	0A999 50-443 0 40-8084 50-245 \$ 50-526 \$
OPREA: 0 W	8402280448	50-498 S	PALOMINO: F G.	8402150180	50-322 0	PAUL,R.A	8402150257*	50-10 0
OPREA: 0 W	8402280572	50-498 G	PANCIERA: V.	8402280212*	50-302 0	PAUL,R.A.	8402270226*	50-461 0
TRDERB: W T	8402030349	50-370 B	PANCIERA: V	8402280246*	50-321 0	PAULK,G.L.	8402140136*	50-259 0
IMAN: K S	8402080408	50-358 A	FANCIERA: V W	8402140171	50-366 5	PAULK,G.L	8402140164*	50-259 0
INSTEIN: P M	8402060147	WASTE MØT	PANCIERA: V. W	8402140446	50-366 8	PAULK,G.L	8402280552*	50-259 0
NSTEIN, PN	8402050151*	WASTE MOT	PANCIERA: V W	8402150294*	50-364 0	PAULBON, W.	8402220495*	50-206 P
R.F	8402290184*	50-289 G	PANCIERA: V. W	8402280446*	50-302 0	PAULBON, W.A.	8402150371	50-255 P
BORN, T	8402270480	FOIA	PANCIERA: V W	8402280485*	50-364 0	PAVIS, G. S.	8402030360	50-317 S
BORNE, DB	8402140345*	50-410 G	PANDEY: S	8206210343*	50-287 P	PAVIS, G. S.	8402030403	50-318 S
TER, J.	8402020110	50-374 J	PANETTA: L E	8402280356	50-275 U	PAY, D.	8402100460	FOIA
STROWSKI,N	8402240373	NUREG	PAPAZOGLOU, I.A	8401300328	50-352 A	PAY, D	8402150445	State Prog
TT,W R	8402170417	NUREG	PAPAZOGLOU, I.A	8402060484	NUREQ	PAYNE, L	8402070371	50-272 F
TT,W R	8402170417	NUREG	PAPAZOGLOU, I.A	8402170430	50-346 P	PAYNE, M, T	8402280223	50-400 9
TTINGER,R	8203150319*	50-275 G	PAPAZOGLOU, I.A	8402170503	50-443 A	PAYNE, M T	8402280223	50-400 9
TTINGER,R	8402100294*	COMMISSION	PAPER IELLO, C. J	8402030315	50-373 F	PEARCE, W	8402280223	FOIA
ITUNALI,O I, ADEN.R C AGE, B M AGE, B M AGE, M	8402280006 8402270499 8402090537 8402090537 8402010071	Mireg Foia Acre Acre Contract	PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J	84020401390 8402080235 8402080275 8402080311 8402100229	50-341 0 50-305 F 50-454 0 50-282 F 50-246 F	PEARSON, W R PEDRO, J PEDRO, J PEERY, W, W	8402100409 8402080318 8402170447 8402270637 8402150384*	REGGD FOIA FOIA FOIA 50-395 G
Age, M	8402010339	CONTRACT	PAPERIELLO, C J	8402130330	50-931 F	PELLETIER, J, P	8402070378	50-271 9
Age, M	8402130037	CONTRACT	PAPERIELLO, C J	8402130361	50-295 F	PELTIER, I. A	8402090175*	50-358 A
Age, M	8402130074	CONTRACT	PAPERIELLO, C J	8402130367	50-483 Q	PENDLETON, M	8402020026	WASTE MOT
Age, M	8402230445	CONTRACT	PAPERIELLO, C J	8402130377	50-254 F	PENDLETON, M, W	8402030281*	WASTE MOT
'Age, M.	8402280470	CONTRACT	PAPERIELLO, C J,	8402130240	50-454 Q	PENTZ, D, L,	8402210039*	CONTRACT
PAGE, R E	8402270506*	FOIA	PAPERIELLO, C J	8402150247*	50-454 G	PENTZ,D,L	8402210054*	CONTRACT
PAGE, R G.	8402010354	70-2955	PAPERIELLO, C J	8402150249	50-6 G	PENZIEN,J	8402270417*	CONTRACT
PAGE, R G.	8402020067	40-8027	PAPERIELLO, C J	8402150250	50-10 G	PERCH,R,L,	8402210378	50-387 F
PAGE, R G.	8402030072	70-2955	PAPERIELLO, C J	8402150263	50-231 G	PERCH,R,L,	8402210382*	50-387 F
PAGE, R G.	8402060375	70-2955	PAPERIELLO, C J	8402150368	50-266 G	PERKINS,R W	8402080144*	40-1341
PAGE.R G	8402040552	70-2955	PAPERIELLO, C J	8402150386*	50-266 G	PERKINS, R. W	8402080153*	40-1341
PAGE.R G	8402040645	70-2910	PAPERIELLO, C, J	8402170244	50-409 G	PERKINS, R. W.	8402080156*	40-1341
PAGE.R G	8402100398	70-135	PAPERIELLO, C J	8402220294	27-39	PERKINS, R. W	8402080159*	40-1341
PAGE.R G	8402100400*	70-135	PAPERIELLO, C J	8402220513	50-483 F	PERKINS, R. W	8402080168*	40-1341
PAGE.R G	8402160462	70-2932	PAPERIELLO, C J	8402270199	50-461 G	PERLIS, R. Q	8402220240	50-424 \$
PAGE,R G PAGE,R G PAGE,R G PAINTER,R.L. PAINTER,R L	8402170123 8402270331 8402270372 8402220542* 8402220547*	40-2061 70-1113 70-2788 50-413 E 50-413 E	PAPERIELLO, C J.	8402270266 8402270279 8402270356 8402270387 8402280296	50-373 F 50-373 Q 50-315 G 50-262 Q 50-254 Q	PERLMAN, J. PERLMAN, J. PERLMAN, J. PERLMAN, J.	8402010044 8402010344 8402020462 8402030202 8402030421	50-49B \$ CONTRACT CONTRACT CONTRACT CONTRACT

ACCESSION

SUBJECT

#OR	ACCESSION NUMBER	CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ככבב	B402160682 B402160684 8402170017 B402170154 8402240045*	CONTRACT CONTRACT CONTRACT CONTRACT FOIA	PIRTLE, 0 L PLAINE, H PLIML, G PLISCO, L PLISCO, L	8402270444* 8402170367 8402140134 8402020252* 8402220169	50-483 0 COMMISSION 50-295 F 50-387 0 50-387 S	PROFIO.A E PSOMAS.P P PULLANI.S PURPLE.R A PURVIS.J	8402020302 8402070383* 8402070216 8402090435* 8402060047	50-493 H FOTA 50-317 G 50-272 S 27-47
3344	8402240228 8402240254 8402100003 8402080282* 8402080286*	CONTRACT CONTRACT FOIA 50-416 P 50-416 P	PLONIS,T R PLOBKI,T J PODMURST, B W POINDEXTER,T C POINDEXTER,T C	8402240379* 8402150247* 8402140604 8402130608 8402140523	CONTRACT 50-454 G 71-513 50-320 P 50-320 P	GUAKA, T E GUALLS, A M GUAMME, D L GUAMME, D L GUAMME, D L	6402100040* 8402230233* 8402020276 8402030331* 8402030335	50-373 P 50-438 G 50-329 A 50-329 A 50-329 A
9 M. 8 M. 8 M. 8 M.	8402240359 8306210409 8402020188 8402020303 8402020434	FDIA XPORTLIC XPORTLIC XPORTLIC XPORTLIC	POLK.P J POLK.P J POLK.P J POLK.P J	8205110034* 8402010080 8402130194 8402220135* 8402240234*	50-220 P 50-286 P 50-286 P 50-220 P 50-220 P	QUAMME, D. L. QUAMME, D. L. QUAMME, D. L. QUAMME, D. L. QUAMME, D. L.	8402030481 8402060427 8402080241 8402220012 8402220179	50-329 A 50-329 A 50-329 A 50-329 S 50-329 A
,M R ,M R ,M R ,M R ,M R	8402030025 8402100387 8402130517 8402140620 8402150465	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	POLMAR,S K POMEROY,P W POMEROY,P W POPPE,L K POPPE,L K	8402140034* 8402090483 8402090483 8402090442 8402090576	CONTRACT ACRE ACRE 71-6601 71-5026	QUANME, D L QUANME, D L QUANME, D L QUANME, D L QUILLEN, C E	8402220384 8402220457 8402280181 8402280431 8402010137	50-329 A 50-329 B 50-329 A 50-329 A 50-320 H
М В , И В , И В , И В , И В	8402150470 8402170084 8402240111* 8402220413 8402010134	XPORTLIC XPORTLIC 50-29 P 50-295 S 50-482 A	POPPE, L K POPPE, L K PORTER, K R PORTER, R J PORTER, R J	8402280663 8402280679 8402100257 8402020066 8402020304	71-910B 71-9148 WASTE MQT 50-317 S 50-318 S	GOINN'E 7 GOINN'E 7 GOINN'E 4 GOILLIN'E W	8402030353 8402030337 8402030281* 8402040147 8402040151*	PR 50-310 G WASTE MOT WASTE MOT WASTE MOT
4 V 4 V 4 V	8402010250 8402020257 8402020317 8402030314 8402040384	50-482 A 50-482 A 50-482 E 50-482 A 50-482 K	PORTER, R J POSEY, W W POTAPOVS, U POTAPOVS, U	8402060401 8402100236* 8402100240* 8007120143* 8007120148*	50-317 S 50-358 H 50-358 H FOIA FOIA	GUINN,R D GUINN,R D GUINN,R D GUIRK,J F GUIRK,J F	8402230108* 8402230113* 8402230116* 8402020323 8402080028	50-354 A 50-354 A 50-354 A 50-447 K 50-447 A
1 A 1 A 1 A	8402070024 8402070114 8402070136 8402070159 8402070204	50-482 E 50-482 F 50-482 E 50-482 A 50-482 E	POTAPOVS. U POTAPOVS. U POTAPOVS, U POTAPOVS, U POTAPOVS. U	8401040408 8402010009 8402010067 8402010126 8402010146	GA999 GA999 GA999 GA999 GA999	GUIRK, J F GUITTSCHREIGER GUITTSCHREIGER GUITTSCHREIGER RADER, R M	8402270240* 8402270282* 8402270360* 8402270371* 8402060131	50-321 P 50-247 D 50-271 D 50-367 D 50-352 Q
1 A 1 A 1 A	8402070301 8402080030 8402070273 8402130454 8402170004	50-482 E 50-482 E 50-482 A 50-482 S 50-482 E	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8402010156 8402010169* 8402070258 8402070269 8402070306	GA979 GA979 GA999 GA979 GA999	RADER,R M RADER,R M RADER,R M RADER,R M RADER,R M	8402040131 8402080118 8402080118 8402140068 8402140068	50-352 0 50-354 0 50-354 0 50-354 0 50-354 0
6 A 6 A 6 A 1 A	8402170124 8402270406 8402280258 8402280372 8402240106*	50-482 Q 50-482 A 50-482 A 50-482 A 50-322 Q	PDTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8402100128 8402130510* 8402140074 8402140199 8402140209*	GA797 50-322 G GA799 GA799 GA799	RAFEEDIE.D P RAHE.E P RAHE.E P RAHE.E P RAHE.E P	9402140334 9402070265 9402140487 8402140488* 9402140490*	50-321 R NUREG TOPREP TOPREP TOPREP
ErH ErH LrH, J, LrH J, LrH J.	8402010294 8402220040 8402210256 8402210289 8402210291	40-1341 40-8084 40-3453 40-8452 40-3453	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8402140299 8402140332 8402140343* 8402140398 8402140430	GA777 GA779 GA777 50-245 S GA777	RAHE, E P RAHE, E P RAHE, E P RAHE, E P RAHE, E P	8402160491* 8402160493* 8402160494* 8402160495* 8402160497*	TOPREP TOPREP TOPREP TOPREP TOPREP
L.H J L.H J L.H J,	8402210487 8402220047 8402230203 8402080205 8402220352	40-8584 40-8084 40-1162 50-269 8 50-287 8	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8402150118 8402150192 8402170055 8402170116 8402170272	GA999 GA999 GA997 GA999 GA999	rahe. e p rahe. e p rahe. e p rahe. e p rahe. e p	8402140500* 8402140503* 8402140505* 8402140508* 8402140509*	TOPREP TOPREP TOPREP TOPREP TOPREP
в Н, Н в, Н в	8402080244 8402210306 8402210027* 8101130714* 8402220281*	50-287 8 40-4659 50-498 0 50-498 0 QA999	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8402210079 8402220183 8402220256	GA999 GA999 GA999 GA999 GA999	RAHE, E P RAHE, E P RAHE, E P RAHE, E P RAHE, E P	8402160510* 8402160512* 8402160514* 8402160516* 8402160518*	TOPREP TOPREP TOPREP TOPREP TOPREP
H 8 H 8 H 8 H 8 H 14.	8402220414* 8402220427* 8402220437* 8402220534* 8402240345*	GA999 GA999 GA999 GA999 50-410 G	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8402220308 8402220370 8402220390	0A999 GA999 GA999 GA999 GA999	RAHE, E P RAHE, E P RAHE, E P RAHE, E P RAHE, E P	8402160519# 8402160525# 8402160527# 8402160529# 8402160532#	TOPREP TOPREP TOPREP TOPREP TOPREP
M H.P. H P R	8402270370* 8402150247* 8402150386* 8402170478 8402100190*	50-315 G 50-454 G 50-266 G NUREG 50-445 G	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8402220417 8402220434 8402220527 8402270358	GA 999 GA 999 GA 999 GA 999 GA 999	RAHE, E P RAHE, E P RAHE, E P RAJAN, J RAJAN, J R	8402160535= 8402160538= 8402280535 8207140125= 8402290148=	TOPREP TOPREP TOPREP 50-289 P 50-289 Q
4. P. 4. P . P. . P.	8402070307* 8402070347* 8402020132 8402020243 8402020270	FOIA FOIA 50-317 S 50-318 S 50-318 S	POTTER, J P POTTER, R W POTTER, R W, POTTER, W C POTTER, W C	8402220333 8402220336 8402220369 8402220369	1&E 50-354 A 50-359 Q 50-329 Q	RANDALL.F N RANDAZZA, J B RANDAZZA, J B RANLET, J B RANLET, J B	8402080212* 8402040235 8402220141 8310050295* 8310050311*	50-241 9 50-309 P 50-309 H 50-321 P 50-298 P
P P A P A. P. A	8402080351 8402270455 8402030234 8402080266 8402080353	50-317 8 50-318 8 50-378 8 50-317 8 50-317 8	POULK,R M POWELL,C B POWELL,R H PRATI,T PREIL,J	8402060480) 8402100334 8402130018* 8402080374# 5	50-324 S KPORTLIC 4ASTE MOT -01A 50-387 Q	RAPKIN, A. RATHBUN, G P RAWSON, R J RAYMOND, W A RAYMOND, W J	8402090550 8402170135# 8402010201 8402140141 8402140301#	40-2061 50-482 G 50-287 Q 50-275 G 50-271 G
1 1 1.	8402070120* 8402170287 8402100202* 8402210047* 8402270228	50-438 A 50-298 F 50-298 G 50-298 G 50-298 F	PRELL, J A. PREMUZIC, E T PRESTON, D E PREVATTE, R L PRIDEMORE, W H	8402240378 N 8402210470 4 8402140450* 5	50-219 0 MC-0 MC-0 MC-0 MC-400 G MC-244 P	RAYNDR, J W RAYNDR, J W RAYNDR, J W RAYNDR, J W REAVIS, J A	8402080266 8402080353 8402080373 8402080397 8402210122	50-317 9 50-317 8 50-317 9 50-317 9 50-269 R

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUNJECT CA TEGDRY	AUTHOR	ACCESSION NUMBER	5 B T 1
REBELLO, J E REBELLO, J E REBELLO, J E REBELLO, J E REBELLO, J E	8402010180* 8402030082* 8402060128* 8402100493* 8402130962*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	REYNOLDS, S REYNOLDS, S D REYNOLDS, S D REYNOLDS, S D RHDADS, G	8402030285 8402020112* 8402020379* 8402070337* 8402020252*	50-254 B 50-244 G 50-244 G 50-254 G 50-354 G	ROLES, 0 W ROLLING, J D ROMAN, T W ROMANO, F R ROMANO, F R	8402280006 8402080422 8402160366 8402060164 8402060168*	MCF - per ; 50 alud 10 50 cm a
REBELLO, J E REBELLO, J E REBELLO, J E REBELLO, J E	8402140034* 8402170230* 8402170245* 8402210369* 8402070344*	CONTRACT CONTRACT CONTRACT CONTRACT 50-423 @	RHODE, O K RHODE, O K RHODE, O K RHODERICK, J E	8402060425 8402130553* 8402150205 8402240080 8402150533	50-410 K 50-410 G 50-410 B 50-410 B WASTE MGT	ROMANO, F R ROMANO, F R ROMANO, F R ROMANO, F R ROMANO, F R	8402170215 8402220317 8402220320* 8402220324* 8402220327*	FC14 90 014 90 014 90 014 90 014
REBELOWSKI,T A REBD,C REBD,C REBSE,R T REBVES,E A	8402290264* 8402020162 8402070336 8402280014 8402100393	50-423 G 50-373 F 50-295 P NUREO 50-348 P	RHODES, M J RICHARDS, S RICHARDSON, J R RICHARDSON, S RICKARD, D C	8401190482* 8402080336* 8402080214* 8402210416* 8402280314	40-7580 50-423 G 40-1341 MIBC 50-170 G	ROMANO, F R ROMNEY, N D ROOD, H ROOD, H ROOD, H	8402280393 8402220309* 8402090173* 8402090177* 8402150408	50 07 1 50 07 4 50 07 4 50 07 4 50 07 8
REEVES, E A REEVES, E A REGAN, B REGAN, N A REGAN, N A	8402170023 8402240258 8402270237* 8402070363 8402140550	50-348 P 50-348 F FOIA TOPREP 70-27	RICKARD, D C RICKARD, D C RICKARD, D C RICKARD, D C RIDENHOUR, R	8402280317* 8402280317* 8402280325* 8402280325* 8402240156*	50-170 0 50-170 0 50-170 0 50-170 0 50-170 8	ROONEY, V ROONEY, V L ROSE, E C ROSENTIAUM, D M ROSENBAUM, P J	8402060359 8402100335+ 8402170016# 8402070002 8402060415	50 2". v 50 25" ; CONTRAL" FOIA PRM
REGANJU H REGANJU H REGANJU H REGANJU H	8402010320 8402130515 8402130519* 8402130546 8402150518*	50-461 M 50-483 M 50-483 M 50-483 M 50-309 H	RIDGWAY, D A RIDGWAY, D A RIDGWAY, D A RIDGWAY, D A RIDGWAY, D A	8402030175 8402030175 8402030175 8402060213 8402060213	50-400 Q 50-400 G 50-400 G 50-400 G 50-400 G	ROSOLIE, E. ROSS, 8 AOSS, B MOSS, D ROSS, D F	8402240076 8402010062= 8402280642= 8311300173= 8402210416=	50-744 (CENTPA) CENTPA) FDIA HISC
REHM, T A REICHEL, N I REICHEL, N I REICHEL, N I REICHEL, N I	8402240270 8402020118 8402030213 8402030236 8402030282	COMMISSION 50-329 A 50-329 A 50-329 A 50-329 A	RIDGWAY,D A RIDGWAY,K R RIEGLAND,J I RILEY,J L RILEY,J L	8402060213 8402130273* 8402090471* 8402080203 8402130235	50-400 G 50-409 G 50-368 A 50-413 G 50-413 G	RD99; D F RO99; W J. RO998ACH: L W RO998ACH: L W RO998ACH: L W	8402280119* 8402140437* 8402020049 8402020204* 8402090243*	FC 1A 50-295 8 HASTE WE 50-296 8
REICHEL,N I REICHEL,N I REICHEL,N I REICHEL,N I REICHEL,N I	8402030286 8402080324 8402080387 8402150337 8402220515	50-327 S 50-329 S 50-327 A 50-327 A 50-327 A	RILEY, J L RILEY, J L RING, M RINGHAM, M R RITGHIE, L T	8402130235 8402230354 8402150382* 8402130097* 8402270189*	50-413	3 0,1820X U,1470X U,1470X U,1470X	8401230110 8402210416* 8402020348* 8402070190* 8402080270*	70-31; 70-68; 70-68;
REICHEL,N I REICHEL,N I REICHHOLD,W REID-K A	8402270379 840228041 <i>6</i> 8402280429 8401060328 8402020268	50~329 A 50~329 8 50~329 A I&E 50~318 8	RITTS,F H RITTS,F H RITTS,F H RIVENBARK,G W RIVKIN,W B	8402080148 8402080148 8402210249 8402030046 7509170149*	50-458 M 50-458 M 50-458 M 50-321 P FDIA	ROTH, J ROTHBART, F ROUNTREE, S ROUSE, L ROUSE, L C	8402290233* 8402090347* 8402060336 8402080071* 8402090520	70-1130 FUIA MAREA 40-134, 70-764
REINMUTH, O W REIS, E J REIS, H F REIS, H F	8009210302* 8009120138* 8402220241 8402140181 8402140161	50-478 0 FOIA 50-527 0 50-250 0 50-250 0	RIVKIN, W B RIVKIN, W B ROACH, P A ROACH, P A ROACH, P A	6002130442* 8402270256* 8402100209 8402130266 8402280038	FDIA FDIA 50-250 S 50-250 S 50-250 S	ROBENSTEIN, L S ROWLEY, C W ROZAK, S ROZAK, S ROZAK, S ROBE, D S	8402170230* 8402160173* 8402150273 8402150268* 7710230546*	CONTRAC* 50-26% # 50-47C # 50-370 # 50-329 #
REMICK.F J RENTON,T.E RENZ,W F REPKA,D A REPKA,D A	8402070100* 8402140195# 8402170132* 8402070040 8402220225	50-458 A 50-266 P 50-322 G 50-322 G 50-322 G	ROBERTS, B J ROBERTS, F. P ROBERTS, J G ROBERTS, J P ROBERTS, J P	8402070454 8402240233 8402140105 8402230313 8402230339	ACR8 MUREG 50-346 F PROJ PROJ	RUBENSTEIN, L S RUBENSTEIN, L S RUBENSTEIN, L S RUBENSTEIN, L S RUBENSTEIN, L S	8109280153* 8306020182* 8308050626* 8311300460* 8312020436*	50-23* P 50-26* P 50-250 P 50-250 P
REPKÁ, D A RESNIKOFF, M REVELEY, W T REVELEY, W T REYES, A J	8402220287 8402080009 8402150159 8402150159 8402130474	50-450 0 50-219 P 50-322 0 50-322 0 XPORTLIC	ROBERTS, T ROBERTSON, D. E ROBERTSON, J. B ROBINSON, R. G ROBKIN, M. A	#402080046# E4001220048 E40201022 E402010444 E4406048	FOIA MUREO Waste mot State Prog 50-139 R	RUBENSTEIN, L S RUBENSTEIN, L S RUDGLPH, W. J RUFF, A B RUITER, O H	8312290161# 8402150396 8402070205# 8402280204# 8402140098	MURE9 50-482 9 50-400 8 50-303 R
REYNDLDS.J A REYNDLDS.A B REYNDLDS.J A	8402020267# 8402100138# 8402100382* 8402210369* 8402070177	50-341 G 50-483 Q 50-454 G CONTRACY 50-275 G	RDDABAUGH, E. C RODABAUGH, E. C RODRIQUEZ, J. H RODRIGUEZ, P RODRIGUEZ, P	6402090532 6402090532 6402060146 6402070161 6402060130	ACRS ACRS 50-354 G 50-247 G 50-247 G	RUNKLE, J RUDFF, J. C. RUPP, J. L. RUPP, J. L. RUPP, J. L.	8402280323 8402070156 8402020116 8402020146 8402020250	50-400 4 50-26: 2 50-272 8 50-272 8
BEANOTDS' 7 K BEANOTDS' 7 K BEANOTDS' 7 K BEANOTDS' 7 K	8402070177 8402070183* 8402070183* 8402170053 8402170053	50-275 G 50-275 G 50-275 G 50-275 G 50-275 G	RODRIGUEZ, R J RODRIGUEZ, R J RODRIGUEZ, R J RODRIGUEZ, R J RODRIGUEZ, R J	8402030252 8402030253 8402030355 8402060072 8402060231	50-312 G 50-312 P 50-312 S 50-312 P 50-312 P	RUPP, J. L. RUPP, J. L. RUPP, J. L. RUPP, J. L. RUPP, J. L.	8402030177 8402030187 8402030178 8402030200 8402030205	20-3.5 8 20-3.5 8 20-3.5 8 20-3.5 8
REYNOLDS, Y S REYNOLDS, Y S REYNOLDS, J R REYNOLDS, J R	8402220279 8402220279 8402010209 8402010209 8402030160	50-275 G 50-275 G 50-445 G 50-445 G 50-445 G	RODRIGUEZ,R J RODRIGUEZ,R J RODRIGUEZ,R J RODRIGUEZ,R J	8402070109 8402070209 8402090392 8402130437 8402140388	50-312 V 50-312 P 50-312 F 50-312 G 50-312 S	RUPP, J. L. RUPP, J. L. RUPP, J. L. RUPP, J. L. RUPP, J. L.	8402030323 8402030333 8402070142 8402070169 8402080371	50-311 8 50-272 8 50-272 8 50-213 8
REYNOLDS, N S REYNOLDS, N S REYNOLDS, N S REYNOLDS, N S	8402030140 8402040138 8402040138 8402070227 8402070227	50-445 Q 50-445 Q 50-445 Q 50-445 Q 50-445 Q	RODRIOUEZ, R J RODRIOUEZ, R J RODRIOUEZ, R. J RODRIOUEZ, R J ROOERB, A A	8402140141 8402220177 8402220350 8402220378 8402170012*	50-312 8 50-312 P 50-312 R 50-312 P CONTRACT	RUPP: J L. RUPP: J L RUPP: J L RUPP: J L RUPPEL: H D.	8402150010 8402150234 8402220173 8402240072 8402210208	50-31: 8 50-272 # 50-272 5 50-272 5
REYNOLDS, N S REYNOLDS, N S REYNOLDS, N S REYNOLDS, N S REYNOLDS, N S,	8402080057 8402080057 8402100184 8402100184 8402100184	50-508 G 50-508 G 50-445 T 50-445 T 50-445 G	ROGERS,D W ROGERS,P ROGERS,P. ROGERS,W. G	8402100235 8402030389 8402040407 8402280236 8402060233*	50-255	RUSCHE, B C RUSCHE, B C RUSCHE, B C RUSCH, R. M. RUSSELL, L B	8402080434* 8402080436* 8402080442* 8402170417 8402020006	FOIA FOIA FOIA MARES 50-317 U
REANDIDS'N 8 BEANDIDS'N 8 BEANDIDS'N 8 BEANDIDS'N 8	8402170119 8402210220 8402210220 8402210340 8402210340	50-445 G 50-445 G 50-446 G 50-445 G 50-445 G	RBOERS, W G ROODE, J F. ROODE, J F. ROODE, J F. ROHMER, D M	8402280307* 8402140171 8402150294* 8402280485* 8402280536*	50~345	RUSSELL, L B, RUSSELL, L, B RUSSELL, L, B RUSSELL, L, B RUSSELL, L, B	8402020132 8402020243 8402020268 8402020270 8402020304	50-317 % 50-318 % 50-318 % 50-318 %

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	GUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
RUSSELL, L B FUSSELL, L B FUSSELL, L B. RUSSELL, L B. RUSSELL, L B.	8402030234 8402030309 8402030337 8402030340 8402030403	50-378 8 50-318 8 50-318 8 50-317 8 50-318 8	SCHMIDT, W J BCHMITT, R C BCHMITT, R P BCHNAUTZ, C E BCHNAUTZ, C E	8402140080* 8402040337 8402030368 8402140574 8402140575	GA799 NUREQ 50-344 8 XPORTLIC XPORTLIC	Schwencer, a Schwencer, a Schwencer, a Schwencer, a Schwencer, a	8402130245 8402130254# 8402130605 8402130609 8402130609	50-373 P 50-373 P 50-410 E 50-352 E 50-450 A
RUSSELLIL B RUSSELLIL B RUSSELLIL B RUSSELLIL B RUSSELLIL B	8402030413 8402040401 8402070372 8402070384 8402070387	50-318 8 50-317 8 50-317 5 50-317 8	BCHNAUTZ.C E BCHNELL,D F BCHNELL,D F BCHNELL,D F BCHNELL,D F	8402140578 8402030411 8402040412 8402130370* 8402220035	XPORTLIC 50-483 F 50-483 A 50-483 Q 50-483 F	Schhencer, a Bchhencer, a Bchhencer, a Bchhencer, a Bchhencer, a	8402150430 8402160031 8402160615 8402160621 8402160637	50~352 A 50~387 F 50~354 D 50~461 A 50~322 A
FUSSELL, L B AUSSELL, L B AUSSELL, L B AUSSELL, L B MUSSELL, L B	8402080266 8402080337 8402080347 8402080331 8402080353	50-317 8 50-317 8 50-317 5 50-317 9 50-317 8	SCHNELL, D F SCHNELL, D F SCHNELL, D F SCHNELL, D F SCHROCK, V E	8402220342* 8402220520* 8402230140 8402240068 8402070469	50~483 G 50~483 F 50~483 A 50~483 A ACRS	Schwenger, a Schwenger, a Schwenger, a Schwenger, a Schwenger, a	8402160644 8402160647 8402160664 8402170193 8402170392	50-410 F 50-416 P 50-354 F 50-352 F 50-461 F
JSSELLLE JSSELLLE JSSELLLE JSSELLLE JSSELLLE	8402080373 8402080397 8402270455 8402270456 8402280051	50~317 S 50~317 S 50~318 S 50~317 S 50~317 S	BCHROEDER: C M BCHROEDER: G A BCHROCK: V E BCHROCK: V E	8402090469 8402090473 8402090473 8402150362 8402070151	ACRS ACRS ACRS 50~237 R 50~274 P	Schwencer, a Schwencer, a Schwencer, a Schwencer, a Schwencer, a	8402170395 8402170401 8402170405 8402170410 8402170425	50-416 F 50-352 F 50-322 F 50-373 F 50-354 F
ussellil B ussellil B ussellil B ussellil F utbergij	8402280113 8402280144 8402280147 8402080230 8402010527	50-317 8 50-317 8 50-318 8 50-318 8 WASTE MOT	BCHROEDER.C W BCHROEDER.C W BCHROEDER.C W SCHROEDER.C W BCHROEDER.C W	8402130428 8402210251 8402210265 8402220407 8402220416#	50~373 P 50~373 B 50~373 P 50~374 F 50~379 G	Schwencer, a Schwencer, a, Bchwencer, a Schwencer, a Schwencer, a	8402170429 8402170458 8402210253 8402210437 84022(0447	50~387 F 50~410 A 50~373 P 50~352 A 50~416 P
UTGERB. J.A JIGERB. J.A JILEDDELB.G. JILEDDELC JILEDDELF	8402020061* 8402020073* 8402030354 8402030043 8402270180	50-329 R 50-329 A PR 40-8585 FDIA	SCHULTI, D H SCHULTI, C J SCHULTI, C J SCHULTI, C J	8402240144 8402010276 8402220205 8402140354* 8402280536*	50~373 Q XPORTLIQ 50~304 S 50~445 Q 50~445 Q	Schwencer, a Schwencer, a Schwencer, a Schwencer, a Schwencer, a	8402210457* 8402210489 8402230279 8402240154 8402270034	50-373 P 50-458 A 50-458 F 50-354 F 30-416 P
athan, J. Izicha, H. O. Izicha, H. G. Izicha, H. O. Iau, R. H.	8402080136* 8402130423 8402150025 8402270445 8402100462*	90-528 R 71-4058 71-4058 70-467 CONTRACT	SCHULTZ: SP SCHUM, W S SCHUM, H, S SCHUMACHER, M SCHUMM, W S	8402240143* 8402150235 8402220451* 8402080220* 8402220503*	50-27 P 50-482 8 50-482 9 50-454 9 50-462 0	SCHWENCER. A SCHWENCER. A SCHYLER. J O SCINTO. J	8402290074 8402290364 8402090418* 8402280036 8402280289*	50-373 F 80-410 A 50-312 F 50-133 X REVIEW ORP
an, t Bacm, B Back, B Bak, B Bak, B	8402170113 8402130210 8402210307 8402060396 8402060035	50-286 F 50-237 G 50-265 P 50-237 S 50-245 Q	SCHUSTER, M D SCHUSTER, M D SCHUSTER, M D SCHUSTER, M D SCHUYLER, J, O	8402010016 8402270024* 8402270030* 8402270030*	50~204 F 50~344 0 50~344 F 50~244 Q 50~275 E	SCOTT.A E SCOTT.D J SCOTT.D J SCOTT.D J	8402170178 8402030250 8402060133 8402150233 8402150362	50-241 R 50-237 S 50-237 S 50-237 S 50-237 R
34M, B, 34M, B, 34M, B, 24M, B, 24M, B	8402080378 8402210238 8402210264 8402240115 8402280302*	50-237 G 50-237 P 50-234 P 50-237 P 50-234 G	BCHUYLER, J D. BCHUYLER, J D BCHUYLER, J D, BCHUYLER, J D,	8402020264 8402020382 8402030361* 8402060422 8402060424	50-275 E 50-275 F 50-275 G 50-275 F 50-275 E	SCOTT, D J SCOTT, L M SCOTT, L M SCORN, K M, SCROOGINS, R M	8402270217 8402080171 8402280507 8402140139* 8305040124*	50-237 S PR PRM 50-206 G FOIA
TER, E. H TOH, F. A ILER, H. F. ITO, T. AA, B	8402220104 8402100415* 8402140107 8402130474 8402210204	50-289 0 CONTRACT 50-440 8 XPORTLIC 50-416 8	BCHUYLER. J D BCHUYLER. J D BCHUYLER. J D BCHUYLER. J D	8402070234 8402070390 8402090241 8402090286 8402090299	50-133 P 50-275 E 50-275 E 50-275 E 50-275 E	Scrogoins, R M Sears, C F Sears, C F Sears, C F Sears, C F	8402070072* 8402030397* 8402030397* 8402160113 8402160113	50-412 A 50-336 Q 50-336 Q 50-336 Q
B.HA. B.M.AVA. A.B.RALA. U.GAMIT B.R.GHBGSV	8402210210* 8402070147 8402100378* 8402070610 840203032*	50-416 8 50-482 0 50-275 P 50-320 P 50-354 F	achnarerin o achnarerin o achnarerin o achnarerin o achnarerin o	8402090345 8402090373 8402100001 8402100451 8402130477	50-275 E 50-275 E 50-275 E State Prog 50-275 B	Sears, C F Sears, C F Sears, C F Sears, F M Sears, P M	8402210257 8402210257 8402220190 8402140308* 840222026\$*	50-336 Q 50-336 Q 50-336 P GA979 GA979
lanta, P X P. R. A Born, G. Chez, R. A Doutst, G M	8402060484 8402220121 8402020391* 8402230101* 8402220275*	NUREG FOIA WASTC MGT 50-354 A 50-72 G	GCHUYLER, J O, SCHUYLER, J D SCHUYLER, J D SCHUYLER, J O, SCHUYLER, J O,	8402140419 8402150255 8402160429 8402170013 8402R10061	50-275 E 50-275 B 50-275 P 50-133 P 50-275 E	Gears, P. M Sengal, B. R Seidle, W. C Seidle, W. C Seidle, W. C	8402220319# 8402130070# 8402160371 8402210017# 8402210046#	GA979 FDIA 50-285 F 50-496 G 50-498 A
SERT, I H SER, J INI, R, J INI, R, J, INI, R, J,	8402270253* 8309150474* 8402060329* 8402090208* 8402090223*	50-204 P COMMISSION FOIA FOIA FOIA	SCHUYLER, J D SCHUYLER, J D SCHUYLER, J D.	8402210082 840221021 <i>6</i> 8402210255 8402210267 8402220043	50-193 P 50-275 P 50-275 E 50-275 P 50-275 E	Seidle, H C Seidle, H C Seiken, B J Seiken, B J.	8402210049* 8402210064* 8402220465 8402060462 840206030	50-498 A 50-498 A 50-482 C 50-482 E 50-482
lor, M. S Letti, D. C. Rano, P. A Rano, P. A Hano, P. A	8402140337* 8402160576 8402080069* 8402140434 8402230006	0A779 50-447 A 40-1341 50-397 G 50-528 G	BCHUYLER, J. D BCHWAD, H M BCHWAN, G. BCHWARTZ, B BCHWEDT, A, R	8402240031 8402080435* 8402170195 8402040610* 8402080229	50-275 E 50-397 A 50-275 S 50-322 0 50-220 B	Seiken & J. Beiken & J. Beiken & J. Beiken & J Beiken & J	8402130225 6402160077 6402170209 8402170286 8402220062	50-482 50-482 50-482 50-482 50-482 E
地下原名。D. H 地下原名。D. H 化タ・J カ. 19年1月71、C 日日名。A E	8402140111 8402270080* 8402010279 8402220166* 8402030222*	50-530 B 50-344 G XPORTLIC 50-358 G 50-528 B	SCHHELLER, D SCHWELLER, D SCHWELLER, D SCHWENCER, A SCHWENCER, A	8402170148* 8402170172* 8402170233* 8402010174 8402020310*	50-322 0 50-322 0 50-322 9 50-458 F FD1A	SEKOT, J P SELLS. D E SERINI, S L SERKIZ.A W	8402170216* 8402030517 8402100321 8402060646* 8402130625	30-414 P 50-250 P 50-335 0 70-2910 NUREG
REA.A.E RR,SL J ERLINO,H IDT,A.D IDT,A.D	8402220489 8402240336 8402060499 8402070388# 8402070391#	50-470 E FOIA 50-275 P 50-335 F 50-335 F	Schhencer, A. Behvencer, A Behvencer, A Behvencer, A Behvencer, A.	8402030093 8402030443 8402060172 8402070066 8402070071*	50~458 A 50~416 F 50~416 P 50~373 P 50~373 P	GETTLES.A SEYFRIT.K V SEYFRIT.K V SEYFRIT.K V	8402160334 8402210012* 8402210020* 8402210040* 8402060339	50-373 S 50-498 Q 50-498 Q 50-498 Q MUREO
IDT+ A D IDT+ C R IDT+ H C. IDT+ H. C IDT+ H. C.	8402080383 8402080116* 8402230009 8402230061 8402240149	50-335 F 50-528 R 50-445 A 50-445 A 50-445 E	Schwencer, a Schwencer, a Schwencer, a. Schwencer, a. Schwencer, a	8402070475 8402070481 8402090352 8402090612 8402100186	50-352 A 50-352 A 50-461 A 50-397 P 50-410 A	SHACK, H J. SHACK, H J. SHACKLETON, O C SHACKLETON, O C	8402090494 8402090494 8402130010* 8402130012* 8402130014*	ACRS ACRS 50-528 A 50-528 A 50-528 A

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SHACKLETON, O C	8402130016*	50-528 A	SHIFFER, J.D	8402070368	50-275 S	SMITH, A L	8402140419*	50-285 @
SHACKLETON, O C	8402130019*	50-528 A	SHIFFER, J.D	8402100245	50-275 S	SMITH, A L	8402280536*	50-445 @
SHACKLETON, O C	8402130030*	50-528 A	SHIFFER, J.D	8402150356	50-275 S	SMITH, B W	8402240233	NUREQ
SHACKLETON, O C	8402130047*	50-528 A	SHIFFER, J.D	8402210224	50-275 S	SMITH, C F	8402280516*	50-413 @
SHACKLETON, O C	8402130122*	50-528 A	SHIFFER, J.D	8402210224	50-275 S	SMITH, D L	8402130434	50-259 9
SHACKLETON, O C	8402130127*	50-528 A	Shima, S	8402100379*	XPORTLIC	SMITH, D L	8402140257	50-260 8
SHACKLETON, O C	8402130134*	50-528 A	Shima, S	8402100385*	XPORTLIC	SMITH, D L	8402140415	50-257 9
SHACKLETON, O C	8402130168*	50-528 A	Shima, S	8402130142*	XPORTLIC	SMITH, D L	8402220477	50-276 8
SHACKLETON, O C	8402130221*	50-528 A	Shima, S	8402130147*	XPORTLIC	SMITH, D L	8402240147	50-257 9
SHACKLETON, O C	8402130227*	FOIA	Shima, S	8402130021	XPORTLIC	SMITH, D L	8402280013	50-276 9
SHACKLETON, O C	8402130232*	50-528 A	Shima, S	8402150029	XPORTLIC XPORTLIC XPORTLIC CONTRACT XPORTLIC	SMITH.G	8402020226#	70-371
SHACKLETON, O C	8402130237*	50-528 A	Shima, B	8402150030*		SMITH.G	8402240027#	70-371
SHACKLETON, O C	8402130241*	50-528 A	Shindhara, K	8402010461		SMITH.H A	8402010313	NUREQ
SHACKLETON, O C	8402130250*	50-528 A	Shinton, D	8402240231*		SMITH.H A	8402010368	NUREQ
SHACKLETON, O C	8402130242*	50-528 A	Shirakawa, T	8402020179		SMITH.I W	8402080175	50-454 Q
SHACKLETON,O C	8402270024*	50-344	SHIRAKAWA, T	8402020205	XPORTLIC	W I,HTIMB	8402150131	50-344 0
SHAFER.W	8402080378		SHOEMAKER, C J	8402010056	50-454 G	W I,HTIMB	8402240048	50-344 0
SHAFER.W	8402280372		SHOEMAKER, C J	8402030174	50-454 G	W I,HTIMB	8402270073	50-454 0
SHAFER.W D	8402060081		SHOEMAKER, C J	8402070131	50-537 G	L,HTIMB	8402080211*	40-1341
SHAFER.W D	8402130263		SHOEMAKER, C J	8402070151	50-454 G	R L,HTIMB	8402030067*	CONTRACT
SHAFER.W D	8402130267*	50-407 G	SHOEMAKER, C. J	8402130240	50-322 G	SMITH, M	8402010008	40-8786
SHAFER.W D	8402130278	50-263 G	SHOEMAKER, C. J	8402150201	50-413 G	SMITH, M J	8402150386*	50-266 0
SHAFER.W D	8402150319	50-282 G	SHOEMAKER, C. J	8402160241	50-454 G	SMITH, N P	8402280367	REVIEW GRP
SHAFER.W D	8402170081	50-10 G	SHOEMAKER, C. J	8402170108	50-440 G	SMITH, P R	8402010111	NUREO
SHAFER.W D	8402170085*	50-10 G	SHOEMAKER, C. J	8402210171	50-454 G	SMITH, R H	8402020158*	50-213 0
SHAFER.W D	8402170207	30-373 Q	SHOEMAKER, C J	8402230104	50-454 G	SMITH, W G	8402030240	50-316 8
SHAFER.W D	8402170211*	50-373 Q	SHOEMAKER, C J	8402280208	50-413 G	SMITH, W G	8402030303	50-315 8
SHAFER.W D	8402170299	50-315 Q	SHOEMAKER, C J	8402280333	50-275 G	SMITH, W G	8402130280	50-315 8
SHAFER.W D	8402170302*	50-315 Q	SHOEMAKER, C. J	8402280394	50-443 G	SMITH, W G	8402220065	50-316 8
SHAFER.W D	8402270147	50-373 Q	SHOEMAKER, C. J	8402290105	50-382 G	SMITH, W G	8402220089	50-315 8
SHAFER.W D SHAFER.W D SHAFER.W D SHAFER.W D	8402270245 8402270426 8402270441 8402280291 8402280298*	50~305 0 50~254 0 50~295 0 50~346 0	SHBEMAKER, C J SHBEMAKER, C J SHOLLY, S C SHOLLY, S C SHOLLY, S C	8402290110 8402290126 8402010399 8402080079 8402080380	50-482 G 50-460 G 50-250 S FDIA FOIA	SMITH, W G SMITH, W G SMOLEN, H BMOLEN, H SMYTH, C W	8402240215* 8402270378 8402010204 8402070331* 8402230129	50-315 8 50-315 8 50-352 0 50-352 0 50-289 R
SHAFER, W D	8402290193	50-255 Q	SHDLLY, S C	8402130011	FOIA	SNAPP, B A	8402140452	50-388 A
SHAFER, W D	8402290244	50-155 Q	SHDLLY, S C	8402240205	FOIA	SNELL, W	8402270370*	50-315 0
SHAH, V L	8402060339	NUREQ	SHDN, F J	8402100104	50-322 G	SNELL, W G	8402150386*	50-266 0
SHANDAKY, M	8402020120	50-387 S	SHON, F J	8402100129	50-323 G	SNELLING, R A	8402060063*	FOIA
SHANDAKY, M	8402020326*	50-219 Q	SHON, F J.	8402270086	50-463 G	SNIEZEK, J	8402140076*	FOIA
MANBAKY, M MANBAKY, M MANBAKY, M MANBAKY, M MANBAKY, M MANBAKY, M	8402060393* 8402090369* 8402150245* 8402150328* 8402160333*	50-333 G 50-272 G 50-271 G 50-220 G 50-277 G	SHOPENN SHOPENN, M SHYMLOCK, M B SHYMLOCK, M B	B402270423* B402210053 B402210228 B402280300* B402270374*	FOIA 70-2894 70-2986 50-62 G 50-327 D	SNIEZEK, J H SNIEZEK, J H SNYDER, A W SNYDER, B J	8402070420* 8402070462* 8402070560* 8402270260* 8402070425	FOIA FOIA 50-321 P FOIA 50-320 P
HANBAKY, M	8402240028*	50-293 @	SIEDER.J D	8402270242	50-334 Q	SNYDER.B J	8402100177	50-320 P
HANBAKY, M	8402080348*	50-277 @	SIEGEL.B L	8402100363	50-298 P	SNYDER.B J	8402130118	50-320 P
HANBAKY, M	8402150314*	50-334 @	SILDERG.J E	8402090139	50-482 Q	GR.YDEYNB	8402130121*	50-320 P
HANBAKY, M	8402240092*	50-387 @	SILDERG.J E	8402090139	50-482 Q	J	8402130146	50-320 P
HANBAKY, M	8402270274*	50-317 @	SILDERG.J E	8402090144#	50-482 Q	BNYDER.B J	8402130149*	50-320 P
JHANBAKY,M M	8402290328*	50-287 G	SILBERG.J E	8402090144*	50-482	BNYDER.B J	8402130484	50-320 P
SHARPE,T J	8402140218	50-257 8	SILBERG.J E	8402130179		SNYDER.B J	8402270350	50-320 P
SHATTERLY,L W	8402060374	70-1465	SILBERG.J E	8402130179		SNYDER.J	8402020270	50-318 8
SHAUB,E T	8402080340*	50-320 G	SILBERG.J E	8402280337		SNYDER.J A	8402020006	50-317 8
SHAUB,E T	8402080374*	50-367 G	SILBERG.J E	8402280337		BNYDER.J A.	8402060401	50-317 8
SHAUB,E T	8402090357*	50-387 G	SILVER, H	B306150573*	50-289 P	SOLAN, G M	8402040245*	50-309 8
SHEA.K H	8402020281	50-331 J	SILVIA, R	B402170291	PRM	BOLBRIG, R. M	8402280010	NURE9
SHEALY,H Q	8402020214	27-47	GIMAN-TOV, I	B402060457	NJREQ	SOMMERS, B. D.	8402210047	HISC
SHEALY,H Q	8402140115	State Prog	GIMCHUK, J D	B402090565	71-9186	BOONG, A L	8402170492	70-143
SHEARIN,R V	8402150178	50-413 G	GIMCHUK, J D	B402090578*	71-9186	BORENBEN, G C	8402030262*	50-397 9
SKEDLOSKY, J T	8402220273*	50-245 G	BIMPKINS, W W	8402170289	WASTE MGT	SORENBEN. G C	8402080430	50~397 A
SKEDLOSKY, J T	8402240106*	50-322 G	BIMPSON, J	8402070144*	50-482 G	SORENBEN. G C	8402100219	50~460 Q
SKEE, E J	8402160460*	50-329 A	BIMPSON, J	8402070144*	50-482 G	SORENBEN. G C	8402130002	50~397 F
SKEERAN, R, E	8402210094	70-1100	BIMPSON, J	8402070144*	50-482 G	SORENBEN. G C	8402130145	50~397 P
SKELLEY, W J	8402090332	40-2061	BIMPSON, J M	8402280412	50-482 G	SORENBEN. G C	8402140417	50~397 P
SHELLEY, W J SHELLEY, W J SHELLEY, W J SHELTON, M, SHELTON, M,	8402220101 8402220422 8402280524 8402290142+ 8402290145+	40-8768 70-925 PR FOIA FOIA	SIMCLAIR.J B. SINCLAIR.J B. SINCLAIR.J B SINCLAIR.J B	8402140381 8402280114 8402160176 8402210086 8402240124	50-297 H NUREQ 50-271 F 50-271 F 50-271 F	SORENBEN, 9 C SORENBEN, 9, C SORENBEN, 9 C SORENBEN, 9 C SORENBEN, 9 C	8402140447 8402140449 8402220015 8402220444 8402230225	50-397
SHELTON, M D	8402290159*	FOIA	SINDERBRAND, C	8402030232	WASTE MGT	SORRELL, E C	8402070236	50-321 F
SHELTON, M D	8402290200*	FOIA	SINDERBRAND, C.	8402070324	WASTE MGT	SORRELL, E C	8402240055	50-321 F
SHEPARD, A, M	8402240110	50-27 P	SINGH, M N	8402210439*	CONTRACT	SORRELL, E C	8402270419	50-321 F
SHEPARD, A M	8402240111*	50-27 P	SINTSI, J M	8402210227	50-273 J	SORRELL, E, C	8402280024	50-321 F
SHEPPARD, J J	8402290094	TOPREP	SINKE, G J	8402240357	40-8748	SOWELL, L L	8402150568	70-820
SHEPPARD, J J	8402290094	TOPREP	SISK, K, D	8402170125*	50~322 G	SPECK, S W	8402070134*	50-322
SHERON, B W	8402090443*	FOIA	SISK, K D	8402170125*	50~322 G	SPEIGHT, C W	8402150070	
SHERON, B W,	8402090515	TOPREP	SJOBLOM, G L	8402060088	DRG	SPEIS, T P	8307210350*	
SHERWOOD, G G	8402170167	NUREG	SJOBLOM, G, L	8402060157	WASTE MOT	SPEIS, T P	9312050175*	
SHEWMON, P G	8012310632*	50-320 O	SKIBA, E L	8402220358	NUREO	SPEIS, T, P	8312090072*	
SHIAD, A C.	8402240134*	50-219 P	SLADOIE, E L	B307200092*	FOIA	SPEIB, T P.	8402070502	GEN TEC 16
SHIEH, L C	8402210021	50-295 P	SLAHINSKI, W	B402270083*	FOIA	SPESSARD, R L	8402020007	50-461 9
SHIELDS, B W	8402290349	50-456 A	SLAHINSKI, W J	B402080280*	50-454 @	SPESSARD, R L	8402020007*	50-461 9
SHIELDS, B W	8402270193*	50-546 E	SLEAR, D G	B402280352*	50-289 G	SPESSARD, R L	8402100017	50-454 9
SHIFFER, J. D	8402070232	50-133 B	SLY, D K	B402270146	1&E	SPESSARD, R L	8402100207	50-454 9

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR	ACCESSION NUMBER	CATEGORY	
SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L	8402100211* 8402130455 8402130527 8402220140 8402220410	50-456 50-263 50-454 50-456	_ 0 0 0 0	STEINERT, L D STEINERT, L D STEINKOENIG, K STELLO, V STELLO, V	B402270106* B402270109* B402070136 B402090160* B402280256	50-341 50-341 50-280 50-478 REVIEW G	A A S T RP	STOLZ: J F STOLZ: J F STOLZ: J F STOLZ: J F STOLZ: J F	8402150440 8402150444* 8402150446 8402150452* 8402160593*	50-346 50-267 50-269	ም ድ P P
SPESSARD, R L SPESSARD, R L SPRINKLE, J K SPRINKLE, J K SPPUND, J L	8402220433 8402220469 8402010313 8402010368 8402270189*		a a	STELLO, V STELLO, V STEMOOS, A A STEPANORIC, D M STEPHENS, S	8402280283 8402280501 8402160370 8402170141* 8402010057	REVIEW G. REVIEW G. 50-282 50-482	RP RP F G H	STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F	8402170482 8402170524* 8402230202 8402230217* 8402240245	50-277 50-269 50-269 50-313	P 0 0 F
SRENIANSKI, D SRENIENSKI, D ST LAURENT, N ST LAURENT, N STAATS, A A	B401040328 B4022700B3* B402030297 B402270397 B402160528*	50-29	s s c	STEPHENSON, C J STEPTOE, P B STEPTOE, P B STERN, A STERN, F	8402030356 8402100149 8402100149 8402240227 8402210035	50-287 50-454 50-454 FOIA TOPREP	s c c	STONE, J T STONE, W S STREETER, J STREETER, J F STREETER, J F	8402286600* 8402070004* 8402070434* 8402020254 8402020258*	FOIA 50-293 FOIA 50-341	G G G
STADNICK, S STADNICK, S STAFFEL, J H STAHL, D STAPLETON, B W	8402150214 8402150348 8402150538* 8402010314 8402040009*	50-336 50-220 WASTE MGT	5 8 P G	STERN.P. STERN.P STERN.P STETKA.T F STETKA.T F	8402220200* 8402220214* 8402220230* 8402280212* 8402280446*	50-309 50-309 50-309 50-302 50-302	G G G	STREETER. J F STREETER. J F STREETER. J F STREETER. J F STREETER. J F	8402100130 8402100134* 8402150359 8402150364 8402150372*	50-483 50-483 50-341 50-454	0 0 0
STAPLETON B W STAPLETON G P STAROSTECKI R STAPOSTECKI R STAROSTECKI R	8402220345* 8402010077* 8402020107 8402020121 8402020146	GA999 50-244 50-443	a a a	BTEVENSID W STEVENSON, J D STEWART, C A STEWART, W L STEWART, W L	8402150169 8402170126* 8402150175 8402030444 8402030470	WASTE MG 50-445 50-416 50-338 50-338	G G P P	STREETER, J F STREETER, J F STREETER, J F STRIGHT, R L STRIP, D R	8402220246 8402220340 8402270222 8402070149* 8402270232*	50-373 50-483 50-341 50-311 FOIA	9 9 A
STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	8402020180 8402020175 8402020245 8402020251 8402020327	50-286 50-387 50-333	G G G	STEWART, W L STEWART, W L STEWART, W L STEWART, W L	8402070382 8402080062 8402080169 8402100183 8402130351	50-280 50-338 50-280 50-280 50-280	ዩ ዩ የ የ	STROMBERG, H M STRONG, T R STRUCKHEYER, R STRUCKHEYER, R STUART, R	8402090316 8402020103* 8402080384* 8402150007* 8402130070*	50-241 WASTE MG 50-245 50-213 FOIA	F O O
STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	8402020342 8402020373* 8402020379* 8402030425 8402030431	50~244	0 0	STEWART, W L STEWART, W L STEWART, W L STEWART, W L	8402150020 8402150173 8402150267 8402230143 8402240010	50-280 50-338 50-338 50-280 50-280	ዮ የ የ F	STUART, R G SUBRAMONIAN, N SUBRAMONIAN, N SUBRAMONIAN, N SUBRAMANN, J	8402130081* 8301170385* 8309290297* 8402070470* 8402240344*	FOIA 50-298 50-321 50-298 50-287	Р Р Р
STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	8402060242 8402060420 8402070187 8402070213 8402070214	50-29 70-1143 50-333	8 G G	STEWART, W L STEWART, W L STEWART, W L STEWART, W L	8402240012 8402240032 8402240084 8402280214 8402280426*	50-338 50-280 50-338 50-280 50-280	F F P G	SUERMANN, J F SUERMANN, J F SUERMANN, J F SUERMANN, J F SUERMANN, J F	8402070399 8402070099* 8402070184* 8402230192 8402240337*	50-269 50-498 50-498 50-269 50-287	A A P P
STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	8402070244 8402070347 8402070387 8402080243 8402080320	50-272 50-352 70-371	G G S	STEWART, W L STEWART, W L STEWART, W L STEWART, W L STEWART, W L	8402280453 8402280472* 8402280483 8402280505* 8402280517	50-280 50-339 50-338 50-280 50-280	F Q P P	SUERMANN, J F SUGARMAN, R J SUGARMAN, R J SUGARMAN, R J SUGARMAN, R J	8402240353* 8402170461 8402220113 8402220113 8402230391	50-287 50-352 50-352 50-352 50-352	PAOGA
STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R. STAROSTECKI, R. STAROSTECKI, R.	8402080369 8402090235 8402090334 8402130059 8402150163	50-286 50-423 50-333	G G G G	STICKLEY, T H STILL, N STILLER, M A STILLER, M A STILLWELL, D D	8402150435* 8402030505 8402220039* 8402220041* 8402020385*	50-352 WASTE MG 50-483 50-275	A F F F	SUGARMAN, R J SUGARMAN, R J SUGARMAN, R J SUMMERS, R J SUMMERS, R J	8402230375* 8402240275 8402240308 8402020336* 8402070351*	50~352 50~352 50~352 50~272 50~272	A E G
STAROSTECKI, R STAROSTECKI, R. STAROSTECKI, R. STAROSTECKI, R STAROSTECKI, R	8402150302 8402150361 8402160296 8402210217 8402220268	50-443 50-271 50-289	G G G G	STINER, D STITT, B D STOCKS, H S STOETZEL, G A STOFFEL, J W	8402100085* 8402080032 8402130398 8402160356* 8402100352*	50-445 50-269 PR 50-445 50-263	T P Q P	SUND, H J SUTTON, J W SUTTON, J W SWAJA, R E SWAN, W B	8402220541* 8402130518* 8402130524* 8402280114 8402150143*	50-324 50-322 50-322 NURE0 50-390	0 0 0
STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	8402220287* 8402220314 8402220364 8402220453 8402220473	50-29 50-309 50-277 50-387 50-443	Q Q Q Q	9 TO SHOTS 1 TO SHOTS 2 TO SHOTS 3 TO SHOTS 4 TO SHOTS 4 TO SHOTS 5 TO SHOTS 5 TO SHOTS 7 TO SHOTS 8 TO SHOTS	8402140057 8402140271 8402140375 8402140403 8402140423	70-1201 70-143 70-1151 70-27 70-624		SWANSON, E R SWARTZ, E D SWARTZ, E D SWARTZ, J D SWENSON, F A	8402170313* 8402210142 8402280240 8402220019 8402070326*	50-315 50-295 50-454 50-346 CONTRACT	
Starostecki.r Starostecki.r Starostecki.r Starostecki.r. Starostecki.r.	8402240002 8402240034 8402240039 8402240073 8402240076	50-223 50-273 50-273 50-322 50-244	G G G G	STOHR, J P. STOHR, J P. STOHR, J P STOHR, J P STOHR, J P	8402150335 8402220304 8402220340 8402280277 8402280277	70-143 70-143 70-143 70-143 70-143		SWETLAND, P. D SWIGER, M A SWIGER, M A SWIGER, M A SWIGER, M A	8402080328* 8402010055 8402010055 8402070233 8402070233	50-213 50-440 50-440 50-440 50-440	999
STAROSIECKI, R. STAROSIECKI, R. STAROSIECKI, R. STAROSIECKI, R STAROSIECKI, R	8402240128 8402240241* 8402240244* 8402270418 8402280179*	50-317 50-220 50-220 50-387 50-410	Q P P Q G	STOICK, A F STOICK, A F STOKLEY, D L STOLZ, J F STOLZ, J F.	8402010345 8402010347* 8402140459* 8402010224 8402030035	40-8663 40-8663 50-424 50-289 50-269	I P P	SWICER, M A SWIGER, M A SWIGER, M A SWIGER, M A SWIGER, M A	8402150107 8402150107 8402150190 8402230054 8402230054	50-440 50-440 50-440 50-440 50-440	G G
STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STARÒSTECKI, R STASEK, S	8402290220 8402290257 8402290269 8402290321 8402170088*	70-1100 50-423 50-336 50-334 50-10	G G G	STOLZ.J F STOLZ.J F. STOLZ.J F. STOLZ.J F. STOLZ.J F.	8402030045* 8402030475 8402060154 8402060243* 8402060274	50-269 50-277 50-313 50-289 50-312	₽ ₽ ₽	SWINTH K L SZCZECH:R A TALWANI.P TALWANI.P TAM.P	8402240233 8402080244 8402130275* 8402270478* 8402240176*	NUREG 50-287 50-395 FOIA FOIA	S R
STAUDER'S J STEARNS, W STEARNS, W STEFAND, J STEFAND, J STEFAND, J	8402100456* 8402080071* 8402080111* 8402070503	CONTRACT 50-528 50-528 50-440 50-440	R R A F	STOLZ, J F STOLZ, J F. STOLZ, J F STOLZ, J F STOLZ, J F	8402040278* 8402040312* 8402040331 8402040374* 8402070433	50-312 50-312 50-313 50-277 50-313	P P P P	Tam.p S Tam.p S Tam.p S Tapia,J I Tapia,J I	8402030125 8402160573 8402240253 8402070191* 8402210031*	50-334 50-334 50-334 50-478 50-478	р Р О О
STEFAND, J. J STEFAND, J. J STEINERT, L. D STEINERT, L. D. STEINERT, L. D.	8402230284 8402270452 8402270076* 8402270078* 8402270103*	50-440 50-440 50-341 50-341 50-341	F A A	STOLZ, J F. STOLZ, J F. STOLZ, J F. STOLZ, J F. STOLZ, J F.	8402070514 8402080305 8402090054 8402090590 8402100432	50-277 50-312 50-321 50-313 50-277	F P P Q	TAYLOR.J A TAYLOR.J A TAYLOR.J A TAYLOR.J A TAYLOR.J A	8402230367* 8402140236 840214038 8402210075 8402270083	50-416 50-260 50-280 50-260 50-338	8 P S

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	BUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	BUBJECT CATEGORY
TAYLOR, J A TAYLOR, J H TAYLOR, J. H TAYLOR, J H TAYLOR, J H TAYLOR, J H	8402280274 8402090141* 8402090145* 8402090148* 8402090225	50-338 8 50-287 0 50-287 0 50-287 0 TOPREP	TIKTINSKY, D H TIPPS, S B TIPPS, S B TIPPS, S B TIPPS, S B	8402030508 8402030414 8402130321 8402270093 8402270115	WASTE MOT 50-366	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8402140338 8402140470 8402150300* 8402150304* 8402150308*	50-413 F 50-413 E 50-413 0 50-413 0
TAYLOR, J H TAYLOR, J H TAYLOR, J H TAYLOR, J M TAYLOR, P A	8402220091* 8402230102 8402230117* 8402170021 8402150253*	50-289 G TOPREP 50-289 G TOPREP 50-413 G	TOALSTON, A L TOBIN, W J TOBIN, W J TOLL, J S TOMLINSON, D P	8402210486 8402220307* 8402270317* 8402060431 8402070171*	50-498 M 70-143 FDIA 50-166 V 50-498 0	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8402150324 8402150341 8402150357 8402160374 8402170292	50-413 8 50-270 0 50-414 8 50-369 F 50-413 A
TAYLOR, P A TAYLOR, R G TAYLOR, R G TEDESCO, R L TEDESCO, R L	8402280004* 8402140002 8402270076* 8108110074* 8401170071*	50-413 G 50-445 T 50-445 G 50-327 A 50-397 A	TOMODKA.H TOMPKINS.B A TOMSIC.C R TONGUE.T M TONGUE.T M	B402070009 B401050299 B402020424* B4020600B5* B4021700BB*	40-8302 50-289 G WASTE MOT 50-10 G 50-10 G	TUCKER, H B	8402210077 8402210174 8402220051 8402220071 8402220325	50~269 P 50~269 P 50~413 B 50~269 F 50~369 F
TEDESCO.R L TEDFORD.C F TELFORD.J L TEMUS.C J	8402070134* 8402130044* 8402060484 8402130022* 8402070510	50-458 A 50-528 A Nureo Foia 71-9175	TODLE,R TODLE,R J TODLE,R J TOSTE,A P TOTTEN,M	8402030310 8402030443 8402240034 8402210013 8402240324	50-289 F 50-289 P 50-289 F NJREG FOIA	TUCKER.H B TUCKER.H B TUCKER.H B TUCKER.H B TUCKER.H B	8402220352 8402220359 8402220385 8402220493 8402220517	50-287 8 50-413 E 50-413 E 50-359 F 50-259 P
TEMUS,C J TEMUS,C J TERRY,G A THADANI,M C THADANI,M C	8402140597 8402140599 8402030038 8402130196 8402150545	71-9184 71-9181 70-687 50-331 P 50-331 P	TOURIGNY, E G TOUSLEY, D R TOUSLEY, D R TOUSLEY, D R	8402080100 8402030239 8402030239 8402030243* 8402030243*	50-265 P WASTE MOT WASTE MOT WASTE MOT WASTE MOT	TUCKER, H B	8402220538 8402220564 8402230106 8402230146 8402240085	50~413 E 50~413 A 50~369 E 50~369 P 50~413 F
THADANI.M C THERD.O L THOMAS.C O THOMAS.C O THOMAS.C.O	8402290423 8402070205# 8402010012 8402060316 8402060321	50-331 P 50-482 G 50-166 V 50-250 F 50-148 P	TOWNSEND, B L	8402010170 8402030081 8402100489 8402130559 8402170225	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H, B	8402270101 8402270119 8402270185 8402270304 8402280177	50-369 8 50-370 8 50-369 P 50-370 8 50-369 0
THOMAS, C O	8402040571 8402070052 8402080003 8402070436* 8402100041	50-184 O TOPREP TOPREP FOIA TOPREP	TOWNSEND, B L. TOWNSEND, B L TRAGER, E A TRAINOR, E F TRAMM, T R	8402170237 8402210363 7912180235* 8402080013 8402080375	CONTRACT CONTRACT 40-1341 FOIA 50-454 S	TUCKER, H B TUCKER, H. B TUCKER, H B TUCKMAN, M S TUCKMAN, M S	8402280422 8402280507 8402270307 8402220539* 8402220547*	50-369 9 50-370 9 50-413 8 50-413 E 50-413 E
THOMAS, C O	8402130495 8402140021 8402150393 8402150397 8402160692	MISC 50-250 P 50-454 F 50-462 A 50-396 P	TRAMM, T R TRAMMELL, C M TREBY, S A TREBY, S A TREEN, D C	8402240108 8402280622 8402020044 8402140003 8402010522	50-454 A 50-344 P 50-358 Q 50-170 Q HABTE MQT	TUCKMAN.M S TUCKMAN.M S TUCKMAN.M S TUCKMAN.M S TUCKMAN.M S	8402220548* 8402220552* 8402220554* 8402220555* 8402220560*	50-413 E 50-413 E 50-413 E 50-413 E 30-413 E
MAB, C D AB, C D AB, C D AB, C D	8402170440 8402170443* 8402170467 8402170511 8402230180	50-297 P 50-297 P 50-87 P 50-280 F MIEC	TRENERY, S E TRIMBLE, D. C TRIOLO, S TRIPP, L E. TRIPP, L E	8402170513 8402240139* 8309290297* 8402150306* 8402280714	NUREO 50-317 G 50-321 P 50-412 G 50-277 G	TUCKMAN, M B TUCKMAN, M B TUCKMAN, M, B, TUCKMAN, M B TUCKMAN, M B	8402220561* 8402220566* 8402220573* 8402220579*	50-413 E 50-413 E 50-413 E 50-413 E 50-413 E
AB, C D 1AB, G D 1AB, G R MAS, H J MAS, J	8402230428 8402210129 8402130070* 8402140442* 8402070359*	50-B9 P 50-443 F FOIA TOPREP 50-320 Q	TRIPP, L.E. TROSKOSKI.W M TROSTEN, L.M TROSTEN, L.M TROWBRIDGE, Q.F	8402270326* 8402270326* 8402100436 8402100436 8402230058	50-334 G 50-334 G State Prog State Prog 50-424 G	TUCKMAN, M B TUCKMAN, M B TUCKMAN, M B TUCKMAN, M, B TUCKMAN, M, B	8402220581# 8402220583# 8402220585# 8402220588# 8402220593#	50-413 E 50-413 E 50-413 E 50-413 E 50-413 E
omas, m omas, r d omas, r d omas, r d omas, v, w	8402280033* 8402070573 8402220232* 8402220576 8402080081*	50-390 Q 70-2950 27-48 I&E 40-1341	TROWERIDOE, G F TRUBATCH, E L TRUBATCH, E L TUCKER, H B, TUCKER, H B	8402230058 8402220137 8402220363 8402030218 8402030223	50-424 0 50-142 0 50-275 P 50-369 8 50-370 B	TURK, B E TURK, B E TURK, B E TURK, B E TURK, S E TURK, S E,	8402070007 8402140162 8402220182 8402270032 8402270107	50-70 9 50-463 9 50-70 9 50-537 9 50-382 9
OMAS. V W IOMAS. V W IOMAS. V W IOMASON. P V HOMASON. P V	8402080112* 8402080122* 8402080180* 8402280355 8402280398	40-1341 40-1341 40-1341 50-278 S 50-278 S	TUCKER, H. B TUCKER, H. B, TUCKER, H. B TUCKER, H. B TUCKER, H. B	8402030245 8402030284 8402030287 8402030391 8402030449	50-370 B 50-370 8 50-370 B 50-369 B 50-369 B	TURK, 8, E TYKULSKER, D TYREE, A, TYREE, A UDALL, M K,	8402270112* 840224028 8402070178 8402070178 8402060120*	50-382 0 FOIA 50-322 T 50-322 T 50-289 U
THOMASON, P V THOMPSON, G A THOMPSON, G A THOMPSON, H L THOMPSON, H L	8402280474 8402090529 8402090529 8202170355* 8203040546*	50-29B 8 ACRS ACRS FOIA FOIA	TUCKER,H B TUCKER,H B TUCKER,H B TUCKER,H B TUCKER,H B	8402040077 8402040087 8402040100 8402040273 8402070181	50-413 E 50-413 E 50-413 F 50-413 E 50-413 A	UDALL, M K UDALL, M K. UDALL, M, K UDERITZ, R A UDERITZ, R, A	8402070127* 8402070132* 8402280370 8305160003* 8402070217*	50-275 U 50-498 U 50-275 U 50-272 S 50-272 Q
THOMPSON, H L THOMPSON, H L THOMPSON, H L. THOMPSON, J M THOMPSON, L B.	8206030327* 8307150063* 8402080447* 8402080070* 8402130043*	TOPREP 50-269 F FOLA FOLA FOLA	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8402070310 8402080205 8402080244 8402090251 8402090323	50-413 K 50-249 8 50-287 8 50-413 A 50-413 F	UHOV, P UHOV, P UHOV, P. ULECK, R. B ULLRICH, W T	8402100368* 8402100480 8402100483 8402020055 8402170143	XPORTLIC XPORTLIC XPORTLIC MASTE MOT 50-277 R
THOMPSON, R B THOMPSON, R B THOMPSON, R H THOMPSON, S, L THOMPSON, S, L	8402070488 8402070488 8402220335 8402280123 8402070357*	ACR8 ACR8 50-302 B NUREO 50-320 Q	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8402090395 8402130332 8402130337 8402130409 8402130417	50-369 P 50-413 V 50-413 E 50-413 F 50-413 A	UMBEL, D UMBEL, D UMBEL, D UMBEL, D, UMBEL, D,	8402010030 8402010033 8402010042 8402010046 8402010052	CONTRACT 50-498 A CONTRACT CONTRACT CONTRACT
THORNDERRYIR C THORPE,J R THURGOOD,M J TIEN,C,L TIEN,C L	8402020263 8402100446 8402060343 8402090511 8402090511	50-275 R State Prog NUREQ 50-335 O 50-335 O	TUCKER, H B. TUCKER, H B. TUCKER, H B. TUCKER, H B. TUCKER, H, B.	8402130469 8402140016 8402140149* 8402140184 8402140185	50-413 A 50-369 8 50-269 0 50-370 8 50-370 8	UMBEL, D UMBEL, D, UMBEL, D UMBEL, D, UMBEL, D,	8402010059 8402010072 8402010171 8402010265 8402010325	CONTRACT CONTRACT CONTRACT 50-345 F CONTRACT
TIERNAN.J A TIERNAN.J A TIERNEY,J E TIERNEY,J P. TIETZ,G C	8402220270 8402270408 8402220230* 8402070055 8402070303	50-317 S 50-317 R 50-309 Q FOIA 50-265 S	TUCKER, H B. TUCKER, H B. TUCKER, H B. TUCKER, H, B TUCKER, H B.	8402140216* 8402140230 8402140269* 8402140280* 8402140311*	50-414	UMBEL: D UMBEL: D UMBEL: D. UMBEL: D UMBEL: D	8402010331 8402010385 8402020448 8402030070 8402030348	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT

APTIME AND CONTROL OF THE CONTROL OF		ACCESSION	SUBJECT			ACCESSION	SUBJECT	,	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
No.	AUTHOR	NUMBER	CATEGURY				CATEGORY	-				
Valid	Ursel.D Ursel.D Ursel.D Ursel.D	8402060514 8402060531 8402060538 8402060585	CONTRACT CONTRACT CONTRACT CONTRACT	,	VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8402270495 8402280301 8402280324	50-528 50-528 50-528	E S S	VASBALLO, D B VASBALLO, D B VASBALLO, D B	8310060224* 8402010013 8402010386* 8402010417*	50-333 P 50-263 P 50-259 P	
Colling	LMSEL. D LMSEL. D LMSEL. D LMSEL. D	8402070115 8402070280 8402070315 8402070334	CONTRACT CONTRACT CONTRACT		VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8402280452 8402280456 8402280481	50~528 50-528 50-528	5 5	VASSALLO, D B VASSALLO, D B VASSALLO, D B	8402060070 8402060117 8402060280	50-324 P 50-259 G 50-324 P 50-333 P	
March D	UNSEL.D UNSEL.D UNSEL.D UNSEL.D	8402070545 8402100380 8402100387 8402130130	CONTRACT CONTRACT CONTRACT CONTRACT		VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8402290102 8402290177 8402290207	50-528 50-528 50-528	5 A 5	VASSALLO, D B VASSALLO, D B VASSALLO, D B	8402060487 8402070458 8402090303 8402100346*	50-220 P 50-298 P 50-259 P 50-263 P	
MARCH 19 040204032 0504064	Unsel. D Unsel. D Unsel. D Unsel. D	8402210032 8402210037 8402210038 8402210045	CONTRACT CONTRACT CONTRACT CONTRACT		VAN DOORN, P K VAN VLIET VANDE KAUTER, S	8402270312* 8402030041 8402100026*	50-413 50-289 FOLA	GI P	VASSALLO, D B VASSALLO, D B VASSALLO, D B	8402(30202* 8402140509 8402140606 8402150529*	50-331 P 50-324 P 50-324 P 50-220 P	
MABLLO D BAGGOODIGA CONTRACT VARIBALLE D J BAGGOODIGA CONTRACT VARIBALLA A J SAGGOODIGA CONTRACT VARIBALA A J	UHBEL.D UHBEL.D UHBEL.D UHBEL.D H	8402240368 8402240372 8402280598 8402060177	CONTRACT CONTRACT CONTRACT CONTRACT		VANDENBERG, D VANDENBURGH, C VANDERBEEK, R	8402140177 8402150382* 8402010279*	50-255 50-454 50-338	R G P	VASSALLO, D B VASSALLO, D B VASSALLO, D B	8402170067# 8402170077# 8402210083	50-220 P 50-263 P 50-333 P 50-331 P	
NEBELL D II	UNBEL.D H UNBEL.D H UNBEL.D H UNBEL.D H	8402070104 8402070298 8402080474 8402080498	CONTRACT CONTRACT CONTRACT CONTRACT		VANDEWALLE, D J VANDEWALLE, D J VANDEWALLE, D J VANDEWALLE, D J	8402090084 8402140007 8402170227	50~155 50-255 50-155	P F F	VASSALLO, D B VASSALLO, D B VASSALLO, D B	8402230315 8402230353 8402230410 8402230436	50-324 P 50-333 Q 50-263 P 50-333 F	
PRIGHT B BA022800148 S0-413 S0-413 S0-414 S	LABEL, D M LABEL, D M LABEL, D M LABEL, D M	8402130078 8402210155 8402270376 8402280255*	CONTRACT CONTRACT CONTRACT 50-250		VANKUIKEN, J C VARELA, A A VARELA, A A VARELA, A A	8402020318* 8402160282* 8402160454*	50-334 50-423 50-307	⊕	VAUGHAN, C M	8402290432* 8402140540 8402170525*	50-331 P 70-1113 71-9009 50-424 I	
STOCK STOC	VERIGHT CH VERIGHT CH VERIGHT CH	8402140084# 8402140145# 8402140198# 8402280093#	50-390 50-366 50-390 50-413	G G	VARGA, S A VARGA, S A VARGA, S A VARGA, S A	8310190334* 8312160258* 8402010086*	50-250 50-250 50-286	P P	VERRELLI,D VERRELLI,D M VERRELLI,D M	8402170274 8402060001 8402140017	50-257 S 50-395 G 50-416 G 50-390 G	
VAN BRINTI, E E	US1. V. UTLEY: E E VACH18TON: P	8402160457 8402290234 8402090074* 8401270152	50-317 50-261 FOIA 50-528	F A	VARGA, S A VARGA, S A VARGA, S A VARGA, S A	8402010177 8402010181* 8402010184	50-275 50-275 50-250	P P F	VERRELLI, D M VERRELLI, D M VERRELLI, D M	8402140121* 8402140157 8402140182	50-259 0 50-348 0 50-348 0 50-390 0	
VAN BRINTI, E. B. BA0203045 50-529 5	VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E,	8402030214 8402030302 8402030318 8402030352	50-528 50-528 50-528 50-528	8 9 9	VARGA, S A VARGA, S A VARGA, S A VARGA, S A	8402010179* 8402010221 8402010247	50-275 50-275 50-280	P P P	VERRELLI, D M VERRELLI, D M VERRELLI, D M	8402140227 8402140241 8402140246 8402140251*	50-324 0 50-324 0 50-327 0 50-327 0	: ! !
VAN BRINT, E E. 8402100130 50-528 G VAROA. S A. 840200005 50-280 F VERRELLI. D M 8402140413 50-281 F VAROA. S A. 840200005 50-280 F VERRELLI. D M 8402140413 50-281 F VAROA. S A. 840200005 50-280 F VERRELLI. D M 8402140413 50-281 F VAROA. S A. 840200005 50-280 F VERRELLI. D M 8402140413 50-281 F VAROA. S A. 840200005 50-280 F VERRELLI. D M 8402140413 50-281 F VAROA. S A. 840200005 50-280 F VERRELLI. D M 8402140410 50-281 F VAROA. S A. 840200007 F VERRELLI. D M 8402140410 F VAROA. S A. 840200007 F VAN BRINT, E E. 840213003 50-280 S VAROA. S A. 840200007 F VAROA. S A. 840200000 F VAROA. S A. 84020000 F VAROA. S A. 8402000 F VAROA. S A. 840200 F VAROA. S A. 8402100 F VAROA. S A. 840210	VAN BRUNTIE E. VAN BRUNTIE E. VAN BRUNTIE E	8402030408 8402030415 8402030423	50~529 50~528 50~528 50~528	9 9 9 9	VARGA, S. A. VARGA, S. A. VARGA, S. A. VARGA, S. A.	8402010304 8402010327 8402010449*	50~286 50~348 50~280	p F P	VERRELLI.D M VERRELLI.D M VERRELLI.D M	8402140273 8402140352 8402140384	50-324 0 50-259 0 50-259 F 50-400 0) ;
VAN BRUNT, E E 8402130038 50-328 E VARGA, S A 8402090076* 50-348 P VERRELLI, D M 8402130134 50-395 VAN BRUNT, E E 8402130291 50-528 S VARGA, S A 8402090327 50-247 P VERRELLI, D M 840213020 50-390 VAN BRUNT, E E 8402130291 50-528 S VARGA, S A 8402090407 50-280 Q VERRELLI, D M 840213020 50-390 VAN BRUNT, E E 8402130391 50-528 S VARGA, S A 8402090422* 50-280 Q VERRELLI, D M 8402150379 50-391 VAN BRUNT, E E 8402130385 50-528 S VARGA, S A 8402090422* 50-280 Q VERRELLI, D M 8402150379 50-391 VAN BRUNT, E E 8402130385 50-528 S VARGA, S A 8402090422* 50-280 Q VERRELLI, D M 8402250097 50-391 VAN BRUNT, E E 8402130385 50-528 S VARGA, S A 8402090422* 50-280 Q VERRELLI, D M 8402250097 50-391 VAN BRUNT, E E 8402130385 50-528 S VARGA, S A 8402090523 50-272 F VERRELLI, D M 8402280007 50-280 Q VARGA, S A 8402100379 50-328 S VARGA, S A 8402100379 50-348 P VERRELLI, D M 8402280029 50-280 Q VARGA, S A 8402100379 50-328 S VARGA, S A 8402100379 50-341 P VERRELLI, D M 8402280029 50-280 Q VARGA, S A 8402160587 50-334 P VERRELLI, D M 8402280049 50-280 Q VARGA, S A 8402160547 50-348 P VERRELLI, D M 8402280047 SO-328 S VARGA, S A 8402160547 50-348 P VERRELLI, D M 8402280047 SO-328 S VARGA, S A 8402170079 SO-348 P VERRELLI, D M 8402280047 SO-348 P VERRELLI, D M 84022801974 SO-348 P VERRELLI, D M 8402280047 SO-348 P VERRELLI, D M 84022801974 SO-348 P VERRELLI, D M 8402280047 SO-348 P VERRELLI, D M 8402280047 SO-348 P VERRELLI, D M 8402280319 SO-348 P VERRELLI, D M 8402280047 SO-348 P VERRELLI, D M 840228039 P VERRELLI, D M 8	VAN BRUNT, E E. VAN BRUNT, E E. VAN BRUNT, E. E	8402060410* 8402070133 8402080217	50-528 50-528 50-528	0 0 F E	VARGA, S.A. VARGA, S.A. VARGA, S.A. VARGA, S.A.	8402080016 8402080506* 8402070055	50-272 50-260 50-260	Y P F	VERRELLI, D M VERRELLI, D M VERRELLI, D M	8402140427* 8402140435 8402140437	50-259 0 50-395 0 50-261 8))
WAN BRINT, E. E. 8402130385 50-528 8 VAROA, 8 A 8402070524 50-261 P VERRELLI, D. M 8402280007 SC VAROA, 8 A 8402100377* 50-348 P VERRELLI, D. M 8402280007 SC VAROA, 8 A 8402100377* 50-348 P VERRELLI, D. M 8402280007 SC VAROA, 8 A 8402100377* 50-348 P VERRELLI, D. M 8402280023 SC VAROA, 8 A 8402100405* 50-311 P VERRELLI, D. M 8402280023 SC VAROA, 8 A 8402100405* 50-311 P VERRELLI, D. M 8402280023 SC VAROA, 8 A 8402100405* 50-311 P VERRELLI, D. M 8402280023 SC VAROA, 8 A 8402100405* 50-311 P VERRELLI, D. M 8402280023 SC VAROA, 8 A 8402100405* 50-348 P VERRELLI, D. M 8402280157 SO VAROA, 8 A 8402170026* 50-348 P VERRELLI, D. M 8402280157 SO VAROA, 8 A 8402170079 SO SO SC VAROA, 8 A 8402170040 SO SO SO SC VAROA, 8 A 8402170400 SO SO SO SO SC VAROA, 8 A 8402170400 SO SO SO SC SC VAROA, 8 A 8402170400 SO SO SO SC SC VAROA, 8 A 8402170400 SO SO SO SC SC SC VAROA, 8 A 8402170400 SO SO SC SC SC SC VAROA, 8 A 8402170400 SO SO SC SC SC SC SC SC SC SC VAROA, 8 A 8402170400 SO SO SC	VAN BRUNT, E E. VAN BRUNT, E E. VAN BRUNT, E E VAN BRUNT, E E	6402130038 8402130175 8402130285 8402130291	50-528 50-528 50-528 50-529	E 8 9	VARGA, S A VARGA, S A VARGA, S A VARGA, S A	8402090078* 8402090327 8402090409 8402090422*	50-247 50-280 50-280	P G	VERRELLI, D M VERRELLI, D M VERRELLI, D M	8402150134 8402150220 8402150238	50-390 50-390 50-261	
VAN BRUNT, E. E. 8402130411 50-528 5 VARGA, S. A. 8402170026* 50-348 P VERRELLI, D. M. 8402280157 50 VAN BRUNT, E. E. 8402130426 50-528 S VARGA, S. A. 8402170026* 50-348 P VERRELLI, D. M. 8402280152 5 VAN BRUNT, E. E. 8402130426 50-528 S VARGA, S. A. 8402170079 50-305 P VERRELLI, D. M. 8402280194* 5 VAN BRUNT, E. E. 8402130464 50-528 S VARGA, S. A. 84021700460 50-305 P VERRELLI, D. M. 8402280234 5 VAN BRUNT, E. E. 8402130464 50-528 S VARGA, S. A. 8402170460 50-305 P VERRELLI, D. M. 8402280234 5 VAN BRUNT, E. E. 8402150274 50-528 S VARGA, S. A. 8402170460 50-305 P VERRELLI, D. M. 8402280319 50-328 S VARGA, S. A. 8402170460 50-305 P VERRELLI, D. M. 8402280334 S VAN BRUNT, E. E. 8402150275 50-528 S VARGA, S. A. 8402170464 50-348 G VERRELLI, D. M. 8402280397 PR VAN BRUNT, E. E. 8402150277 50-528 F VARGA, S. A. 8402170472* 50-348 G VERRELLI, D. M. 8402280397 PR VAN BRUNT, E. E. 8402150272 50-528 S VARGA, S. A. 8402170472* 50-250 P VEST, G. D. 8402280397 PR VAN BRUNT, E. E. 8402150272 50-528 S VARGA, S. A. 8402210484 50-315 P VIETH, D. L. 8402150562 WARGA S VARGA, S. A. 8402210484 50-315 P VIETH, D. L. 8402150562 WARGA, S. A. 8402210484 50-315 P VIETH, D. L. 8402150563 WARGA S VARGA, S. A. 8402210484 50-315 P VIETH, D. L. 8402150549 S VARGA, S. A. 8402210484 50-315 P VIETH, D. L. 8402150549 S VARGA, S. A. 8402210484 50-315 P VIETH, D. L. 8402150549 S VARGA, S. A. 8402210484 50-315 P VIETH, D. L. 8402150549 S VARGA, S. A. 8402210484 50-315 P VIETH, D. L. 8308160549 S VARGA, S. A. 8402240209 PR VARGA,	VAN BRUNT, E.E. VAN BRUNT, E.E. VAN BRUNT, E.E.	6402130385 8402130386 8402130371 6402130376	50-528 50-529 50-529	S S S	VARGA, 9 A VARGA, 9 A VARGA, 8 A VARGA, B A	6402090403 6402100397* 6402100405*	50-272 50-348 50-311	P P P	VERRELLI, D. M VERRELLI, D. M VERRELLI, D. M	8402280001 8402280007 8402280023	50 50 50	
VAN BRUNT, E E. 8402150024 50-528 8 VARQA, 8 A 8402170474 50-348 0 VERRELLI, D M 8402030319 50-32 VAN BRUNT, E E. 8402150271 50-528 F VARQA, 8 A 8402170472* 50-348 0 VESELY, W 8402030370 PR VAN BRUNT, E E. 8402150271 50-528 F VARQA, 8 A 8402170478 50-250 P VEST, G D 8402030370 PR VAN BRUNT, E E. 8402150272 50-528 8 VARQA, 8 A 840221048 50-250 F VICKMAN, W 8402080410 FDIA VAN BRUNT, E E. 8402150274 50-529 8 VARQA, 8 A 8402210484 50-315 P VIETH, D L VAN BRUNT, E E. 8402160069 50-528 F VARQA, 8 A 8402210484 50-315 P VIETH, D L VAN BRUNT, E E. 8402160305 50-528 F VARQA, 8 A 8402240209* FDIA VAN BRUNT, E E. 8402160305 50-528 F VARQA, 8 A 8402240209* FDIA VAN BRUNT, E E. 8402160305 50-528 F VARQA, 8 A 8402240209* FDIA VAN BRUNT, E E. 8402160305 50-528 F VARQA, 8 A 8402240209* FDIA VAN BRUNT, E E. 8402160305 50-528 F VARQA, 8 A 8402240209* FDIA VAN BRUNT, E E. 8402160305 50-528 F VARQA, 8 A 8402240209* FDIA VAN BRUNT, E E. 8402160305 50-528 F VARQA, 8 A 8402240209* FDIA VARQA, 8 A VIETTI, A 8308180730* 50-350* 50-450	VAN BRUNT, E.E. VAN BRUNT, E.E. VAN BRUNT, E.E. VAN BRUNT, E.E.	8402130411 8402130415 8402130426 8402130458	50-528 50-528 50-528 50-528	5 5 5	VARGA: B A VARGA: S A VARGA: S A VARGA: S A	8402160647 8402170026* 8402170077 8402170070*	50-348 50-348 50-305	P P	VERRELLI.D M VERRELLI.D M VERRELLI.D M	8402280157 8402280182 8402280194	50 5″ ⊭ 5	
VARIANTIE E. 8402160069 50-028 F VARIANDO 9 84022402098 FOLA VIETTIA 83081807508 50-50 VARIANDO 9 84022402098 FOLA VIETTIA 83081807508 50-50 VARIANDO 9 84021701588 CONTRACT VIETTIA 83081807508 50-50 VARIANDO 9 84021701588 CONTRACT VIETTIA 83082044008 50-45 VARIANDO 9 79041001178 50-329 A VIETTIA 83082044008 50-50 VARIANDO 9 79041001178 50-50 VARIANDO 9 79041001178 50-50 VARIANDO 9 79041001178 50-50 VARIANDO 9 790410011	VAN BRUNT, E E. VAN BRUNT, E E. VAN BRUNT, E E.	8402150024 8402150209 8402150271 8402150272	50-528 50-529 50-528 50-528 50-529	ទ F ទ ទ	VARGA, B A VARGA, S A VARGA, S A VARGA, B A	8402170464 8402170472* 8402170478 8402210168	50-348 50-250 50-250	g P F	VESELY.W VEST.G D VICKMAN.W	8402040484 8402030370 8402080410	NUREG PR FDIA	
VAN BRUNT, E. E 8402230117 50-528 K VASSALLO, D. B 8303160017* 50-220 P VIETTI, A 83102703100 VAN BRUNT, E. E 8402270340 50-528 A VASSALLO, D. B	VAN BRUNT, E. E. VAN BRUNT, E. E. VAN BRUNT, E E VAN BRUNT, E E	8402160305 8402160305 8402170241 8402220386 8402230119	50-528 50-528 50-528 50-528 50-528	F A F K	VARGA, S. A. VARNADO, G. B. VARNER, L. S. VASSALLO, D. B.	8402230017 8402240209* 8402170158* 7904100117*	FOIA CONTRAC	T	VIETTI.A	8308160549 8308180750	% 50-478 % 50-509 % 50-478	# A A

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUDJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
VIETTI. A VIETTI. A VIETTI. A VIETTI. A VIETTI. A	8402170010 8402170489 8402210072 8402210080 8402210388	50-508 D 50-498 H 50-498 F 50-498 A 50-508 F	WALKER,R D WALKER,R D WALKER,R D WALKER,R S WALKER,R S	8402130284* 8402170088* 8402270432* 8402030116* 8402280695*	50-263	WELLS,DA WELLS,DA WELLS,DH WELLS,JE	8402270157 8402290267 8402290286 8402290248 8402210021	50-341 S 50-341 S 50-341 S 50-341 S 50-295 P
VIETTI, A VIETTI, A VIETTI, A VIETTI, A VIETTI, A	8402210453 8402230277 8402230299 8402230398 8402230444	50-50B A 50-498 A 50-498 A 50-508 A 50-508 A	WALKER,W J WALKER,W J WALKER,W J WALLACE,M J WALSH,M A	B402090219# B402090274# B402090293# B402220134 B402060161#	FOIA FOIA FOIA 50-456 A 50-445 G	WELLS,R WELLS,R A WEN,P C WEN,P C WENNER,T J	8402020367 8402270010 8402080333* 8402090374* 8402220541*	50-320 8 50-327 8 50-317 0 50-317 0 50-324 0
VIETTI.A VIETTI.A VISSING.G VISSING.G VIESING.G	8402290398 8402290405 8402080110 8402080495 8402160679	50-498 A 50-498 F 50-313 P 50-346 P 50-346 F	WALSH,M A WALTERMIRE,M G WALTON,G A WANG,A WANG,J	8402100079# 8402210285# 8402150304* 8402270431* 8402090397*	50-445 T 40~279 50-412 G FDIA FOIA	WENNERHOLM, M J WENSLAWSKI, F A WENSLAWSKI, F A WENSLAWSKI, F A WENSLAWSKI, F A	8402220156 8402020135 8402130350 8402140228 8402140233*	50-295 S 50-142 Q 50-206 P 50-344 Q 50-344 Q
VITO.D J VOGEL.A M VOGLER.D H VOGLER.B H VOGLER.B H	8402220273* 8402270456 8402010235 8402010244 8402140179	50-245 0 50-317 S 50-352 0 50-352 0 50-440 M	Ward, K. D Ward, K. D Ward, K. D Warembourg, D Warembourg, D	8402270095# 8402270434# 8402290249# 8402150204 8402210197	50-454 Q 50-483 G 50-456 Q 50-267 S 50-267 R	WENSLAWSKI,FA WENSLAWSKI,FA WENSLAWSKI,FA WERMUND,EG WESCOTT,HM	8402140445* 8402220224 8402220232* 8402020037* 8402020127*	50-397 O 27-48 27-48 1481E MOT 50-443 O
VOGLER. 8 H VOGLER. 8 H VOGLER. 8 H OGLER. 8 H OGLER. 6 H	8402220150 8402220228 8402220231 8402220244 8402220296	50-483 M 50-352 G 50-440 M 50-440 M 50-352 T	WAREMBOURG, D WAREMBOURG, D W WAREMBOURG, D W WAREMBOURG, D W WAREMBOURG, D W	8402220048 8308170014* 8309200043* 8402060127 8402140412	90-267 8 50-267 8 50-267 8 50-267 R 50-267 P	WESCOTT, R O WESTAFER WESTAFER, O R WESTAFER, O R WESTAFER, G R	8402220313* 8402220004 8402030409 8402030416 8402060226	50-352 T 50-302 P 50-302 S 50-302 B 50-302 P
OGLER. BH OGLER. BH OGLER. BH OGLER. BH	8402240077 8402270003 8402270082 8402270003 8402270076	50-352	WAREMBOURG,D W WAREMBOURG,D W WARNER,D L WARNICK,R F WARNICK,R F	8402150148 8402280377 8402060128* 8402020078 8402020168	50-267 P 50-267 R CONTRACT 50-358 Q 50-329 G	Westafer, G R Westafer, G R Westafer, G R Westafer, G R Westafer, G R	8402060379 8402060435 8402080021 8402080134 8402150199	50-302 F 50-302 P 50-302 P 50-302 P 50-302 P
VDGT, D K VDIGT, H H VDIGT, H H VQIGT, H H	8402030515 8402040143 8402040143 8402040147* 8402040147*	WASTE NOT 50-244	WARNICK, R F WARNICK, R F WARNICK, R F WARNICK, R F WARNICK, R F	8402020247 8402070125 8402100194 8402100232* 8402160469*	50-329	WESTAFER, OR WESTAFER, OR WESTAFER, OR WESTAFER, OR WESTAFER, OR	8402220172 8402220210 8402220335 8402240121 8402280200*	50~302 8 50~302 P 50~302 8 50~302 8 50~302 0
VOIGT.H H VOLGER, D H VOLLMER, H H VOLLMER, R VOLLMER, R	8402240217 8402220247 8402070251* 8210070023* 8304140047*	FDIA 50-352 G 50-352 G 50-289 P 50-289 P	WARNICK, R F WARNICK, R F, WARNICK, R F WARNICK, R F WARNICK, R J	8402220159 8402220424 8402270208 8402270214* 8402220358	50-358	WESTPHAL, B S WESTPHAL, B, S WESTPHAL, B, S WESTERAU, L, W WESTERAU, M, J	8402080041 8402140284 8402220284 8402280309 8402030254	50-373 B 50-374 B 50-373 B PRM 50-352 Q
VOLLMER, R COLLMER, R COLLMER, R COLLMER, R H COLLMER, R H COLLMER, R H	8402080047* 8402140499* 8104280266* 8302020181* 8306020257*	50-528	WASHINGTON, D L WASTLER, S L WATSON, L J WATZL, E L WAYNE, M E	8402270081 8402210488 8402280570* 8402080209 8402060378*	50-456 D 40-8745 50-416 G 50-282 S 50-237 S	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J	8402070242 8402070242 8402070282 8402070282 8402070284	50-352 9 50-352 9 50-352 9 50-352 9
ILLMER, R H JLLMER, R H OLLMER, R H OLLMER, R H JOLMER, R H	8311150374* 8311300146* 8402270176* 8402270206* 8402270214*	FOIA FOIA FOIA FOIA FOIA	WEBB.W D WEBER.M WEBER.M F WEBER.M F WEBER.M F	8402100257 8402020075 8402150530 8402150534 8402160465	ТОМ ЭТЕАН ТОМ ЭТВАН ТОМ ЭТВАН ТОМ ЭТВАН ТОМ ЭТВАН	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J	8402070286 8402070287* 8402070287* 8402070292* 8402070292*	50-352
VOLLMER, R H VUMBACO, F J WADE, D H WAGNER, A G WAGNER, D	8402270224* 8402020274* 8402030165* 8402280284* 8402240267	F01/ 40-672 50-445 G 50-416 G 50-354 A	MEINKAM.E J MEOBI.W F MEOBI.W F MEOBI.W F MEOBI.W F MEODINGTON, R E	8402150017* 8402020138* 8402160059 8402080482 8402090166*	50-269 0 50-142 0 50-142 S 50-458 E 50-458 A	HETTERHAHN, M J HETTERHAHN, M J HETTERHAHN, M, J. HETTERHAHN, M J. HETTERHAHN, M J.	8402070309* 8402070309* 8402150094 8402150094 8402160209	50-352 0 50-352 0 50-352 0 50-352 0 50-352 0
WAGNER, D H WAGNER, D H HAGNER, E J WAGNER, E J WAGNER, E J	8402090478 8402090547 8402060393 8402080389 8402220064	50-354 A 50-354 F 50-358 G 50-358 S 50-358 S	Weinkam, E J Weise, S Weise, S P Weisemantle, J A	8402150507 8402150273* 6402280002* 8402020219* 6402140058*	50-458 A 50-241 G 50-241 G 50-241 G 50-322 G	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M, J, WETTERHAHN, M J WETTERHAHN, M J	8402160209 8402160238 8402160238 8402220088 8402220088	50-352 9 50-352 9 50-352 9 50-352 9
WAGNER, E J WAGNER, M E WAGNER, M E WAGNER, M E WAGNER, M E	8402270272 8402010182 8402010203 8402010224 8402070051	50-358 A 50-287 0 50-287 0 50-287 0 50-287 0	ME182'E K ME18WANTTE'A V ME18WANTTE'A V	8402170118* 8402170153* 8402170180* 8402100410 8402010064	50-322	HETTERHAHN, M J. HETTERHAHN, M J. HETTERHAHN, M J. HETTERHAHN, M J. HETTERHAHN, M J.	8402220114 8402220114 8402220122* 8402220122* 8402280328	50-352 0 50-352 0 50-352 0 50-352 0 50-352 0
WAGNER, M E	8402140120 8402140174 8402150439 8402220243 8402220253	50-287 G 50-289 G 50-289 G 50-289 G 50-289 G	Weigb, e r Weigb, e r Weigb, e r Weigb, e r Weigb, e r	8402010064 8402030243* 8402030243* 8402070267 8402130248	50-289	WETTERHAHN, M J. WETTERHAHN, M J WHARTON, R. J WHEELER, L, L WHEELER, L L	8402280328 8402280476 8402030441 8111170178* 8402090077*	50-352 0 50-352 0 50-361 P 50-443 A 50-443 A
WAGNER, M E WAGNER, M E WAGNER, M E WAGNER, M E WAGNER, P, C	8402220292 8402270072 8402270123 8402270158 8402270366	50-289 G 50-416 G 50-289 G 50-289 G 50-267 P	Weiss, e R Weiss, e R Weiss, e R. Weiss, e R. Weiss, e R	8402130493 8402170470 8402210175 8402210181* 8402220153	FOIA FOIA 50-287 G 50-287 G 50-287 G	WHICHER, J. M WHICHER, J. M WHICHER, J. M WHICHER, J. M WHICHER, J. M	8402080131 8402080131 8402170034 8402210118 8402210118	50-454 0 50-454 0 50-454 0 50-454 0 50-454 0
WALKER, J B WALKER, J B WALKER, J V WALKER, J V	8402020222 8402030215 8402240187 8402130512 8402039381	50-240 8 50-240 8 50-257 8 XPORTLIC PR	Weiss, e r Weiss, e r Welch, s e Welch, s e Welch, s e	8402220153 8402240172 8402220249 8402220252 8402240041	50-287 G FOIA 50-315 F 50-315 F 50-315 F	WHICHER, J. M WHITAKER, L. D. WHITE, J WHITE, J. H.	8402280218 8402210448 8402290369* 8402240038* 8207300124*	50-367 0 50-247 V 50-272 0 50-273 0 FOIA
WALKER,P WALKER,R WALKER,R WALKER,R WALKER,R	8402170242* 8402080378 8402220049 8402220357 8402060085*	50-373 Q 50-263 B 50-373 B 50-373 S 50-10 Q	WELLS, D A WELLS, D A WELLS, D A WELLS, D A WELLS, D, A	8402080313# 8402080338 8402130444 8402270018 8402280568#	50-341 G 50-341 G 50-341 B 50-341 B 50-341 G	WHITE, J.R WHITE, J.R. WHITE, M. WHITE, M WHITNEY, G.C	8402160333* 8402240028* 8402170298 8402290447 8402270277	50-277 Q 50-293 Q HASTE HOT HASTE HOT 50-293 S

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MAITNEY, G O MAITNEY, G O MAITTEER, G D MAITTEER, G D MAITTEER, G D	8402140460 8402270469 8402020321 8402070002# 8402070021	50-293 8 50-293 8 50-309 8 50-309 9 50-309 F	WILLIAMS, J W WILLIAMS, L A WILLIAMS, N H WILLIAMS, R E WILLIAMS, R E	8402280490 8402210044* 8402220373 8402040558* 8402170045*	50-250 0 CONTRACT 50-445 A CONTRACT CONTRACT	MONO, H J MOD, H MOD, H H MOODHEAD, C P MOODHEAD, C P	8402140345+ 8402210019 8402040452 8402010187 8402010197	50-410 G MUREG NUREG 50-440 G 50-440 G
MITTER, CD MITTER, CD MITTER, CD MITTER, CD MITTER, CD MITTER, CD	8402140328 8402210193 8402220178 8402220391 8402270174	50-309 P 50-309 S 50-309 P 50-309 P 50-309 P	WILLIAMSON, T G WILSON, A K WILSON, B A WILSON, B D	8402280275* 8402070034 8402270236 8402280570* 8402280570	50-62 G FUIA P121 50-416 G XPORTLIC	WOODHEAD, C P WOODHEAD, C P WOODHEAD, C P WOODHEAD, C P WOODHEAD, C P	8402010213 8402020030 8402070036 8402070037 8402070040	50-142 G 50-142 G 50-440 G 50-440 G 50-142 G
Hittier, o d Hittier, o d Hittesey, k. a Hittesey, k. a Hick, e. a	8402270421 8402280050 8402220451* 8402220503* 8402170002	50-309 B 50-309 F 50-482 G 50-482 G Waste Mot	WILSON, 8 K WILSON, 8 F WILSON, J WILSON, J H	8402070043 8402150425 8402100203 8402240032 8402080509	FOIA State Prog 50-280 F 50-280 F 50-382 A	HOODHEAD, C P HOODHEAD, C P HOODHEAD, C P WOODRUFF, R L HOODRUFF, R L	8402270055 8402270059 8402270088 8402140070 8402140086	50-250 G 50-440 G 50-440 G State Frog State Prog
HICK, E A HIDICK, R HIEBE, J HIEBE, J HIECHHANN, B M	8402210375 8402030215 8402070359* 8402220103 8402210237	WASTE MOT 50-2A0 S 50-320 G 50-320 S 50-344 J	M1F8OV') F M1F8OV') F M1F8OV') F M1F8OV') H	8402270648 8402070152* 8402140401 8402220146 8402220155*	90~382 A 50~280 S 50~280 S 50~281 S 50~281 E	WODDS, T G WOODWARD, K W WOOLDRIDGE, R A WOOLDRIDGE, R A WOOLEVER, E J	8402040078 8402220070 8402230085 8402230085 8305180559	50-528 H 50-395 S 50-445 G 50-445 G 50-412 A
MIECHKANN, B M MIECERAN, D G MIECER, A. V MIECER, A. V MIEGELMAN, K	8402230219 8206110300* 8402220418* 8402220458* 84022090242*	50-344 J FOIA 70-1257 70-754 FOIA	MILSON, J L WILSON, J L WILSON, J L WILSON, J L	8402220160* 8402220164* 8402220165* 8402220208 8402220435	50-281 8 50-281 8 50-280 8 50-280 8 50-280 5	MODIEVER: E J MODIEVER: E J MODIEVER: E J MODIEVER: E J	8401240177 8402030447 8402070184* 8402130046 8402130184	50-412 A 50-412 S 50-412 G 50-412 C 50-412 K
wieselhan, k Wieselhan, k Wieselhan, k Wieselhan, x Wieselhan, x	8402070246# 8402070254# 8402070257# 8402070262# 8402070266#	FOIA FOIA FOIA FOIA FOIA	WILSON, L B WILSON, R WILSON, R F WILSON, R F WILSON, R F	8402220176 8402210115 8402210135 8402240099* 8402240099*	50-373 5 50-400 0 50-289 F 50-289 P 50-289 P	WOOLEVER, E J WOOLEVER, E J WOOLEVER, E J WRAY, J R WRIGHT	8402130470 8402240155 8402290238 8402280138* 8402020208	50-412 C 50-412 A 50-412 A 50-413 G 27-48
Wieselhan, K Wieselhan, K Wieselhan, K Wiesekann, R Wiesekann, R	8402070284* 8402070288* 8402090300* 8402070285* 8402140489*	FOIA FOIA FOIA SO-482 A TOPREP	WIETZ, J W WIETZ, J W WIETZ, J W WINDHAM, R	8402160506* 8402160511* 8402160531* 8402160536* 8402270228	50-424 C 50-424 C 50-424 C 50-424 C 50-278 F	HRIGHT, B L WRIGHT, C L WRIGHT, C L WRIGHT, E Q WRIGHT, E G	8402130311 8402030279 8402290117 8402090233* 8402090249*	%PORTLIC 50-261 S 50-261 S FOIA FOIA
WIESERANN, R A WIGGIN, E A WIGGIN, E, A WIGGINTON, D. L WIGGINTON, D. L	8402280546# 8402030346 8402100434 8402100476 8402230008	TOPREP PR State Prog 50-295 P 50-315 F	WISE,R WISE,R WISE,R WISENBURG,M R WISENBURG,M R	8402030383* 8402220484* 8402280030 8402160356*	50-313 G 50-445 G 50-298 G 50-498 K 50-445 G	WRIGHT, E Q WRIGHT, G WRIGHT, G C WRIGHT, N A WRIGHT, N A	8402090359* 8402280372 8402290254* 8402010225 8402270068	FD1A 50-195 8 50-195 0 50-352 0 50-352 0
MILCOVE,M N MILKINSON,B W MILMS,B L WILMS,B L MILMS,B L	8402010205 8402100011 8402020117 8402030214 8402060239	50-352 G 50-294 R 50-387 S 50-387 S 50-387 B	WISNER.C E WISBINK.R G WITHERS.B D WITHERS.B D WITHERS.B D	8402280534* 8402150438 8402030442 8402030448 8402070285	90-445	A HADIAM PATENTER PAT	8402290003 8402010118 8402170231# 8402020012 8402020013	50-352 G Wabte Mgt 50-206 P Waste Mgt Wabte Mgt
WILKS, B L HILKS, B L HILLIAMS, C. HILLIAMS, C. C.	9402070362 8402070364 9402140284* 6402150353* 8402020010*	50~387 S 50~387 S 50~397 G 50~454 G 50~461 G	WITHERS, B D WITHERS, B D WITHERS, B D WITHERS, B D WITT, W A	8402130181 8402210137 8402220431 8402280344 8402040413*	50-344 P 50-344 P 50-344 F 50-344 5 50-483 A	WRICHTER J WRICHTER J WRICHTER J WRICHTER J WRICHTER J	8402020015 8402020017 8402020022 8402020045 8402020097	HASTE MGT HASTE MGT HASTE MOT HASTE MOT HASTE MOT
HILLIAMS, C. C WILLIAMS, C. C. WILLIAMS, C. C. WILLIAMS, C. C. WILLIAMS, D.	8402100215* 8402100223* 8402150181* 8402170187* 8402150382*	50-456 G 50-440 G 50-358 G 50-454 G 50-454 G	Woelfing, M Woelfing, M Woelfing, M Wogman, N Wogman, N	8402130253 8402130260 8402130264* 8402080056* 8402080075*	50-289 G 50-289 G 50-289 G 40-1341 40-1341	HRIGHT.A J HRIGHT.A W WG.P HU.P HU.P	6402100288 8402140084* 8211110543* 8304010048* 8402290149*	MASTE MOT 50~390 G 50~289 P 50~289 P 50~289 G
WILLIAMS, J. C WILLIAMS, J. L WILLIAMS, J. W WILLIAMS, J. W WILLIAMS, J. W	8402270043* 8402270105* 8402030220 8402040387 8402040444	50-344 F 50-344 G 50-250 P 50-250 G 50-250 P	WOGMAN, N A	8402080104* 8402080112* 8402080117* 8402080122* 8402080122*	40-1341 40-1341 40-1341 40-1341 40-1341	AVEGES HE MANGALDEN' 22 D MANGALDEN' 22 D MANGALDEN' 22 D	8402270223* 8402270270* 8402100251 8402010361 8402170212*	50~289 50~289 MI9C 70~820 50~250 8
H C,8MAIJIH H J,8MAIJIH H J,8MAIJIH H C,8MAIJIH H C,8MAIJIH	8402070381 8402080383 8402080405 8402100207 8402100439	50-335 F 50-335 F 50-387 F 50-250 8 State Prog	HDGMAN, N A HDGMAN, N A HDGMAN, N A HDGMAN, N A	8402080133* 8402080137* 8402080144* 8402080153* 8402080156*	40-1341 40-1341 40-1341 40-1341 40-1341	YAHNER, A C YAMARA, K YANDELL, L A YANDELL, L A YANICHKO, B E	8402070010 8402220640 8402220455* 8402220510* 8402010162*	50-289 7 XPORTLIC 50-285 50-285 50-327
w U,emailliw W U,emailliw W U,emailliw W U,emailliw	8402130230 8402130288 8402130362 8402130449 8402140074	50-250 S 50-250 S 50-335 F 50-335 F 50-250 G	WOGMAN.N A WOGMAN.N A WOHLD.P R WOJCHOUSKI.A V	8402080157* 8402080163* 8402080168* 8402100138* 8402140011	40-1341 40-1341 40-1341 50-483 0 50-263 8	AIN'A C AIN'A'C AIN'I L AIN'I C AEMORENDE AEMO	840201044 8402220592* 8402230108* 8402230113* 8402230116*	FGIA 50-45* 50-3: 50-3:
u C,emaijin u C,emaijin u C,emaijin u C,emaijin u C,emaijin u C,emaijin	8402140085 8402140266* 8402140495 8402150149 8402160148	50~250 Q 50~335 Q 50~387 S 50~335 P 50~250 P	MOUNAS, E J WOLF, T R WOLFE, R WOLFE, S J. WOLFE, S J	8402220467* 8402090569 8401060176* 8402030166 8402070274	50-322	YORK, J. W YOUNG, A YOUNG, A YOUNG, A	8402280161* 8402240119* 8402240125* 8402240129* 8402240125*	50-43£ 50-295 50-295 50-295 50-295
Williams, J W. Williams, J W. Williams, J W. Williams, J, W. Williams, J, W.	8402170249 8402170258 8402210116 8402220571 8402270238	50~250 F 50~335 F 50~250 F 50~335 G 50~389 S	WOLFE, B J WOLFE, B J WOLLETT, S WOLLETT, S	8402130255 8402230092 8402280384 8402010105 8402100411	50-482 G 50-289 G 50-289 G CONTRACT CONTRACT	L . Sunda A L . Sunda A L . Sunda A M . Sunda A M . Sunda	8402140173* 8402080081* 8402080180* 8402010218 8402220330	FOIA 40-1341 40-1341 50-244 G 50-250 G
uilliams, J W Williams, J W Williams, J, W. Williams, J, W. Williams, J W	8402270397 8402270414 8402280038 8402280156* 8402280244*	50~250 F 50~250 S 50~250 S 50~335 G 50~250 G	WOLTHER, E WONELSDUFF, J E WOND, A K WOND, C T	8402020158* 8402230378 8402020280* 8402070251* 8402230126*	50-213 G NUREG 50-38B G 50-352 G 50-354 A	YOUNG M A YOUNG M A YOUNG M A YOUNG M C	8402270006 8402270084 8402270075 84022130005 8402010216	50-250

AUTHOR	ACCESSION NUMBER	SUBJEC CATEGO		AUTURN	ACCESS10N	SUBJEC	
				AUTHOR	NUMBER	CATEGO	H Y
ADANGBEODD'S 1	8402010257 8402010260*	50~456 50-456	D	ZIMMERMAN, J V	8402130320	XPORTL I	
ADOMOBECOD: 8 7	8402010263	50-456 50-341	D A	ZIMMERMAN, J V ZIMMERMAN, J V	8402130352	XPORTLI	
YOUNGBLOOD, B J	8402010306	50-440	E	ZIMMEMAN, J V	8402130402 8402130520	XPORTL I XPORTL I	
ADMNOBFOOD'S ?	0160102019	50-456	D	ZIMMERMAN, J V	8402130523	XPORTLI	С
ABONOBF dob' B 1	8402010369	50-546	С	ZIMMERMAN, J V	8402130526	XPORTL1	c
YOUNGBLOOD B J	8402010465	50-456	D	ZIMMERMAN.J V	8402130539	XPORTLI	
ACONOBIOCO 8 7 ACONOBIOCO 8 7	8402020020 8402030540	50~445 50~445	Ε	ZIMMERMAN.J V ZIMMERMAN.J V	B402140573	XPORTL I	
YOUNGBLOOD, B J	8402060266	50-445	E	ZIMMERMANJU	8402140583 8402140587	XPORTL I XPORTL I	
YOUNGBLOOD, B.J.	8402060568	50-445					
YOUNGBLOOD, B J	8402060637	50~445	E	ZIMMERMAN, J V ZIMMERMAN, J V	8402140593 8402140603	XPORTLI XPORTLI	
YOUNGELOOD, B J	8402060640#	50-445	F	ZIMMERMAN, J V	B402140614	XPORTL I	
YOUNGBLOOD, B J	8402070506 8402070511	50-482 50-484	F A	ZIMMERHAN, J V	B402140617	XPORTLI	
		20 404		ZIMMERMAN, J V	8402140624	XPORTLI	C
YOUNGBLOOD B J YOUNGBLOOD B J	8402080083 8402070364	50-440 50-482	E	ZIMMERMAN, J V	8402220416	XPORTLE	
AONWERFOOD' B 1	84021304BB	50-483	A F	ZIMMERMAN, J V ZIMMERMAN, J V	8402220626 8402220631	XPORTLI XPORTLI	
YOUNGBLOOD, B J	8402140526	50-482	E	ZIMMERMAN, J V	8402230164	XPORTL I	
FEONGRECODY B O	8402140528	50~440	F	ZIMMERMAN, J V	8402230165	XPORTL I	С
ADDNEBTOOD B 1	8402150390	50-423	A	ZIMMERMAN, J V	8402230318	XPQRTL10	2
AONWOBFOOD'S 1	9402150424 8402160574	50-440	Ε	ZIMMERMAN.J V	8402230349	XPORTLI	3
YOUNGOLOOD, B J	8402160574	50-341 50-445	F	ZIMMERMAN, J V ZIMMERMAN, J V	8402230385 8402230397	XPORTLIC XPORTLIC	
AGANGBEDOD'B ?	8402160630	50-445	Á	ZIMMERMAN, J V	8402240356	XPORTL I	
YOUNGBLOOD, B. J	8402240270	50-483	A	TIME POLICE B. O.			_
AUNNOBFOOD II 1	8402240272	50-482	Ä	ZIMMERMAN,R P ZIMMERMAN,R P	8402020112* 840224009B*	50-244 50-244	9
AGNAGBEGOD'B A	B402270287	50-440	A	ZIMMERMAN, S R	8402070377	50-261	X
AGANGBEOGD' B 1	8402270362 8402270366*	50-456 50-456	D D	ZIMMERMAN,S R Zimmerman,S R	B4020B0236	50-324	P
				E THINDENIMA BIR	B402130001	50-324	P
AONNOBFOOD'B 1	8402290392 8402290409#	50-440 50-341	S	ZIMMERMAN, B R	8402130153	50-324	F
YOUNGELOOD, B J	8402290413*	50-341	Ä	ZIMMERMAN,S R ZIMMERMAN,S R	640213022B 6402130244	50-324 50-324	P
YOUNGBLOOD, R YOUNGBLOOD, R	8402170430	50-346	P	ZIMMERMAN, S R	8402130294	50-324	P
THONGUL DUD, K	B402170503	50-443	Α	ZIMMERMAN, B R	8402130328	50~261	P
YOUNGBLOOD, R W	B402060484	NUREG		ZIMMERMAN, S R	8402220430	50~324	P
YUHAS, Q P YUNDT, C P	8402140445* 8402030368	50-397 50-344	G S	ZIMMERMAN, S R	8402280537	50-324	P
YUNDT, C P	8402130289	50-344	8	ZITZER, P. ZITZER, P	8402060173 8402100029	50-352 50-352	9
YUNDTIC P	8402130340	50-344	8	ZITZER, P	84021 GD178	50-352	Ğ
YUNDT, C P	8402170255	50-344	9	ZUMHALT,L R	0400170045-	071175107	
YUNDT, C. P	8402270122	50-344	ធ	ZUPKO. J M	8402170245* 8402020116	CONTRACT 50-272	9
ZACK,A M Zahler,r e	8402020029 8402080150	50-329	A	ZUPKO, J M	8402020146	50-272	8
ZAHLER, R E	8402080150	50-269 50-269	G G	ZUPKO.J M ZUPKO.J M	8402020250 8402030177	50-272 50-272	9 9
ZAHNLEUTER, R. J.	G45555465		_		0,02000177	30-212	
ZAHNLEUTER, R J	8402070199 8402220125	50-322 50-322	G G	ZUPKO,J M	8402030189	50-272	В
ZAHNLEUTER, R J	B402220131	50-322	Ģ	ZUPKO.J M	8402030198 8402030200	50-272 50-272	5 5
ZAHNLEUTER,R J ZEITERS,J R	8402280322 8402280388	50-322 50-320	g P	ZUPKO. J. M	8402030295	50-272	8
	4102240556	30-320	•	ZUPKO, J M	8402030323	50-311	s
ZERBE,JE ZERBE,JE	B402010494*	50-287	F	ZUPKOJJ M	8402030333	50-272	8
ZEUGIN, L B	8402130182* 8402140047	50-528 50-322	A. G	ZUPKO'N W	8402070142	50-272	8
ZEUGIN L B	8402140047	50-322	Ğ	ZUFKO, J K	8402070189 8402080371	50-311 50-272	S
ZIBULSKY, H	8402020224*	70-371		ZUPKO, J M	8402150010	50-311	8
ZIDZIUNAS,W J	B402240037	50-370	Α	ZUPKO.J M	8402150234	50-272	8
ZIEMANN, D L ZIMMERMAN, J V	7903240077*	50-206	P	ZUPKO, J M	8402210056	50-272	R
ZIMMERMAN, J V	8402010035 8402010092	XPORTLIC XPORTLIC		ZUPKO, J. M ZUPKO, J. M	8402210140	50-311	R
ZIMMERMAN, J V	B402010133	XPORTLIC		ZUPKO, J H	8402220173 8402240072	50~272 50~272	S
ZIMMERMAN, J V	8402010379	XPORTLIC					
ZIMMERMAN, J V	8402010431	XPORTLIC					
ZIMMERMAN,J V	8402010464	XPORTLIC					
ZIMMERMAN, J V	8402020192 8402020197	XPORTLIC XPORTLIC					
77MP8444 1 1							
ZIMMERMAN, J V ZIMMERMAN, J V	8402020199 8402020365	XPORTLIC XPORTLIC					
ZIMMERMAN, J V	8402030028	XPORTL IC					
ZIMMERMAN, J V ZIMMERMAN, J V	8402030030	XPORTLIC					
Z4111461111941 V Y	8402030033	XPORTLIC					
ZIMMERMAN, J V	8402030054	XPORTLIC					
ZIMMERMAN, J V ZIMMERMAN, J V.	8402030061 8402030127	XPORTLIC					
ZIMMERMAN, J V.	B402030322	XPORTLIC XPORTLIC					
ZIMMERMAN, J. V	8402030339	XPDRTLIC					
ZIMMERMAN, J V	8402060190	XPORTL10					
ZIMMERMAN, J V	B402040473	XPORTLIC					
ZIMMERMAN, J V ZIMMERMAN, J V	8402060476 8402060594	XPORTLIC XPORTLIC					
ZIMMERMAN, J V	8402100342	XPORTLIC					
ZIMMERHAN,J V							
ZIMMERMAN, J V	8402100347 8402100362	XPORTLIC XPORTLIC					
ZIMMERMAN,J V	8402100372	XPORTLIC					
ZIMMERMAN, J V ZIMMERMAN, J V	8402130139 8402130315	XPORTLIC XPORTLIC					
···· - •		~ -111-10					

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEOC	JR Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	
34 Co , Hinnesota Mining & Mfg Co	8402150438	State F		3	8402140152	50-348	P
AW Inc	B402130150*	FOIA	,		8402140342	80-34B	P
Asnadis	8402220158	50-2B9	G		8402140342 8402140347*	50~348 50~348	P
Access Coro	6402280180	50-269	. 0		8402140347*	50-348	ė
wrease Colb	8402240256*	CONTRAC	:τ				
Acres American, Inc	8402220358	NUREO			8402150142	50-34B 50-364	F
Advanced Technology, Inc	8402010351*	CONTRAC	7		8402160088 8402160092#	50-364	P
lendantiana na r	8402160693*	CONTRAC			8402140461	50-349	ŕ
Ajriculture, Dept. of	8402010143	50-352	D		8402170089	50-364	R
	8402020196	50-456	ם				_
	8402130222	50-456	D		B402170527	50~348 50~364	R
	8402170158*	CONTRAC	Ŧ		8402170192 8402170220	50-34B	p
Alf Force, Dapt. or	8402030390	PR			8402170243	50-364	þ
Air and Water Pollution Patrol	8402060164	50-352	Q		8402170324	50-348	F
	8402060164	50-352	Q				_
	8402060168*	50-352	Q		8402170326	50-248 50-348	F
	8402060168*	50-352	G		8402210298 8402220331	50-348	P
	6402170215	FOIA			B402220331	50-348	Ė
	8402220317	50-352	G		8402220487	50-348	P
	8402220317	50-352	Ø				
	8402220320*	50~352	G		B402220487	50-348	P
	8402220324*	50-352	ā		B402220511	50-349 50-348	P
	8402220327#	50-352	G		R402220511 8402220516#	50-348	þ
	B402220327*	50-352	9		9402220516*	50-348	P
	8402280393	50-352	g				
Al Stern Associates	8402240227	FOIA			8402270259	50-348 50-364	F
Alabama Power Co	B402030176	50-34B	P		8402270262 8402010387*	CONTRAC	
	B402030176	50-346	P	Alabama. State of	8402030354	PR	
	8402030203*	50-348	P	Alaska, State of	8402130532	State Pi	rog
	6402030203 *	50-348	P	Viska, erace ni			•
	B402030382	50-348	F	Alden Research Laboratory	8402010365	NUREG	
	8402030382	50-348	F	American College of Nuclear Physicians	8402100444 8402130106#	State Process	
	8402030399	50-348	F	American Physical Society	8402140308*	FOIA	•
	8402030399	50-346	Ę	American Society of Machanical Engineers American Corp.	8402080177	PR	
	B402030406	50-348	F				
	8402030406	50-348	F	Ames Laboratory, Energy & Mineral	B402090488	ACRS	
	B402030419	50-348	P	Resources Research Institute	8402070517	71-1	
	8402030419	50-348	P	Anefco, Inc	B402070519*	71-1	
	8402030439	50-348	s		8402070523	71-9071	
	8402030447*	50~348	25	Appling County, GA	B402080334*	50-321	F
	B402030453*	50-348	8		8402010274	NUREG	
	8402030456#	50-348	8	Argonne Mational Laboratory	8402060339	NUREG	
	8402060067	50-348	S		8402080079#	40-1341	
	B402060067	50~348	5 6		8402090494	ACRS	
	8402060360	50~348	-		8402130036#	FOIA	
	8402060360	50~34B	8		8402130073*	FOLA	
	8402060433	50~34B	8		8402160614	M STEAM	QΥ
	8402060433	50~348	8	Arizona Public Service Co.	8401270152	50~528	A
	8402060438*	50~348 50~348	8 9	414	8401270152	50~52B	A
	8402060442#	7U~U4G			8402030176	50~528	5
	8402060448*	50-34B	9		8402030216	50~528	8
	8402080350	50~348	5 F		8402030302	50-528	8
	8402090080	50~346 50~346	F		8402030302	50-528	8
	8402130015 8402140152	50~348	P				B
	GANETANIAN						125

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8402030302 8402030318 8402030362 8402030362 8402030362	50-528 50-528 50-528 50-528 50-528	ន ន ទ ទ ទ		8402280360 8402280360 8402280452 8402280456 8402280456	50-528 8 50-528 8 50-528 8 50-528 8 50-528 6
	8402030365 8402030365 8402030365 8402030408 8402030415	50-528 50-528 50-528 50-529 50-528			8409280456 8402280481 8408270034 8408270034 8408270034	50-528 8 50-528 A 50-528 A 50-528 A
	8402030415 8402030423 8402030423 8402030455 8402060078	50-528 50-528 50-528 50-528 50-528	8 9 9 E		8402290068 8402290068 8402290068 8402290102 8402290177	50-528 A 50-528 A 50-528 B 50-528 A
	8402060078 8402060078 8402060240 8402060240 8402060240	50-528 50-528 50-528 50-528 50-528	H H A A		8402270177 8402270177 8402270207 8402270207 8402270207	50-528 A 50-528 A 50-528 B 50-528 B
	8402040410* 8402070133 8402080217 8402080217 8402080217	50-528 50-528 50-528 50-528 50-528	Q Q F F F	Arizona State Univ	8402270258 8402270263 8402270263 8402270263 8402270363	50-530 8 50-528 8 50-528 8 50-528 8 CONTRACT
	8402080332 8402080332 8402080332 8402090128* 8402130038	50-528 50-528 50-528 50-528 50-528	E E A H	Arizona, State of Arkansas Power & Light Co	8402130044* 8402010147 8402030458 8402060107 8402060407	50-528 A 50-368 B 50-313 P 50-368 P 50-368 B
	8402130038 8402130038 8402130143* 8402130175 8402130175	50-528 50-528 50-528 50-528 50-528	H H A E E		8402070308 8402130040 8402130186 8402130186 8402130258	50-348 R 50-313 F 50-313 J 50-313 J 50-313 J
	8402130175 8402130285 8402130285 8402130285 8402130291	50-528 50-528 50-528 50-528 50-528	E 8 8 8		8402130258 8402160293 8402210269 8402220060 8402220091	50-313 J 50-313 P 50-313 F 50-313 P 50-368 P
	6402130291 6402130291 6402130362 6402130365 6402130386	50-528 50-528 50-529 50-528 50-528	# # # # # # # # # # # # # # # # # # # #		8402220181 8402220476* 8402220488* 8402240035 8402270158*	50-348 8 50-313 0 50-313 0 50-313 P 50-313 0
	8402130391 8402130396 8402130406 6402130411 8402130411	50-528 50-529 50-528 50-528 50-528	8	Arkansas, State of Arkansas, Univ of, Fayetteville, AR	8402280236 8402280400 8402100073* 8402150425 8402240371*	50-368 8 50-368 0 CONTRACT State Prog CONTRACT
	8402130411 8402130415 8402130415 8402130415 8402130426	50-528 50-528 50-528 50-528 50-528	9 9 9	Armed Farces Radiobiological Research Institute Army, Dept of Army, Dept of, Corps of Engineers Aspen Systems, Inc	8402280319* 8402280325* 8402030351 8402100462* 8402030428*	50-170 0 50-170 0 PR CONTRACT CONTRACT
	8402130458 8402130458 8402130458 8402130464 8402150024	50-528 50-528 50-528 50-528 50-528	s .	Association for Advancement of Psychology Atomic Industrial Forum	8402160685# 8402240231# 8402010413 8402030346 8402100434	CONTRACT CONTRACT FOIA PR State Prog
	8402150024 8402150207 8402150271 8402150272 8402150374	50-528 50-529 50-528 50-528 50-529	S S	Automatic Switch Co Automation Industries, Inc Nabcock & Wilcox Co	8402280465 8402070311* 8402020332* 8212150120* 8301250628*	PR GA777 40-6720 50-287 P 50-287 P
	84021 50455 84021 60067 84021 60067 84021 60067 84021 60305	State Pr 50-528 50-528 50-528	Ä A A F		8304130440* 8304250292* 8402010063* 8402070363 8402090141*	50-289 P 50-289 P TOPREP TOPREP 50-289 0
	8402170241 8402170241 8402220386 8402220386 8402220386	50-528 50-528 50-528 50-528	A A F F F		8402070145* 8402070148* 8402070225 8402070425* 8402070430*	50-289 0 50-289 0 TOPREP 50-312 F 50-312 F
	8402230117 8402270340 8402270383 8402270495 8402280301	50-528 50-528 50-528 50-528 50-528	K A E 9		8402070430* 8402070432* 8402070432* 8402100158 8402130310	50-312 F 50-312 F 50-312 F 70-1201 70-135
	8402280324 8402280324 8402280324 8402280351 8402280360	50-528 50-528 50-528 50-528 50-528	:: :: : : : : : : : : : : : : : : : :		8402140538 8402140550 8402150070 8402150414	70-1201 70-27 70-1201 71-5450

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8402220081* 8402220450* 8402230102 8402230105* 8402230117*	50-289 G 70-364 TOPREP TOPREP 50-289 G		8402080089* 8402080097* 8402080104* 8402080112* 8402080117*	FD1A 40-1341 40-1341 40-1341 40-1341
Enlage & Hilcox Operating Plants Owners Group	8402230147# 8402270132# 8402010060	70-344 50-346 P TOPREP 50-312 F		8402080122* 8402080127* 6402080133* 6402080137* 8402080144*	40-1341 40-1341 40-1341 40-1341 40-1341
Parlus, Shea & Megor	8402070396* 8402070410* 8402070412* 8402070418* 8402140151	50-312 F 50-312 F 50-312 F 50-443 G		8402080153* 8402080155* 8402080155* 8402080153* 8402080168*	40-1341 40-1341 40-1341 40-1341 40-1341
tall. Hayden, Kiernan & Livingston faitimore Gas & Electric Go	8402220110 6402240288 8402020006 8402020132 8402020243	50-443 G F01A 50-317 S 50-317 B 50-318 B		8402080174* 8402080180* 8402090465 8402090507 8402100284	40-1341 40-1341 ACRS ACRS WASTE MOT
	8402020268 8402020270 8402020304 8402030234 8402030307	50-316 S 50-316 S 50-316 S 50-376 S 50-376 S		8402100287* 8402160386* 8402160419* 8402170308 8402170311	WASTE MGT 50-445 G 50-285 G NUREO NUREO
	8402030337 8402030340 8402030403 8402030413	50-318 S 50-317 S 50-318 S 50-318 B 50-318 P		6402210013 8402240233 8402270213 8402270506*	NUREO NUREO NUREO FOTA
	8402040098 8402040106* 8402040123 8402040234 8402040234	50~318 P 50~317 S 50~317 P 50~317 P	Bear Creek Uranium Co Bechtol Corp	8402280536* 8402220170 8402230041 8402020038* 8402020046*	40-8452 40-8452 50-329 A 50-329 R
	8402040238* 8402040238* 8402040401 8402070372 8402070384	50-317 P 50-317 P 50-317 S 50-317 S 50-317 S		8402020052* 8402020061* 8402020064* 8402020073* 8402030241	50-329 R 50-329 R 50-329 R 50-329 A 50-329 A
	8402070387 8402080230 8402080266 8402080272 8402080272	50-318 S 50-318 S 50-317 B 50-317 P 50-317 P		8402080417* 8402130024* 8402130174* 8402150140 8402170162*	50-237 9 50-528 9 50-528 A 50-327 A 50-482 8
	8402080339 8402080349 8402080351 8402080353	50~317 S 50~317 S 50~317 B 50~317 B		8402170209 8402170263 8402220147* 8402220255	50~482 S 50~528 S 50~397 G GA999
	8402080373 8402080397 8402100006 8402100004	50-317 8 50-317 9 50-317 P 50-317 P	Bergen-Paterson Pipe Support Corp Berger & Montague Bingham-Willamette Co	8402240275* 8402010253 8402080405 8402140422* 8402170145	50-352 A 50-322 S 50-358 A 50-245 B 50-528 S
	8402140329* 8402150156 8402160457 8402220290	50-317	Bio-Rad Laboratories Bishop, Liberman, Cook, Purcell & Regnalds	8402010209 8402010209 8402010209	XPORTLIC 50-445 0 50-445 0 50-445 0
	8402220440 8402270285 8402270408 8402270454 8402270455	50-317 R 50-317 B 50-317 R 30-317 P 50-318 B		8402030160 8402060138 8402060138 8402070227	50-445 G 50-445 G 50-445 G 50-508 G
	8402270456 8402280051 8402280113 8402280144 8402280147	50-317 8 50-317 8 50-317 8 50-317 8 50-318 B		8402080164 8402080171 8402090150 8402100111	50-413 Q 50-413 Q 50-413 Q 50-445 Q
Earris, Bott, Denn & Driker Pattelle Memorial Institute, Columbus Laboratories	8402020027 8402010314 8402040484	50-329 A WASTE MOT NUREQ FOIA		8402100115# 8402100115# 8402100125 8402100125	50-445 0 50-445 0 50-413 0 50-413 0
	8402130025* 8402130027* 8402130068* 8402160550* 8402160552*	FOIA FOIA 50-424 C 50-424 C		8402100145 8402100145 8402100184 8402100184 8402130293	50-413 G 50-413 G 50-445 T 50-445 T 50-445 G
Bettulle Memorial Instituts, Pacific Northwest Laboratory	8402010302 8402010373	CONTRACT NUREO NUREO		8402170119 8402210220 8402210220 8402210340	50-445 G 50-445 G 50-445 G 50-445 G
	8402060341 8402060343 8402080056* 8402080059*	NUREO NUREO 40-1341 40-1341		8402220275 8402220275 8402220275 84022803734	50-413 G 50-413 G 50-413 G
	8402080075* 8402080081*	1961-04 1961-04		B402280373*	20 410 0

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
Dlack & Veatch Boeing Computer Services, Inc (subs of Boeing Co)	8402280502 8402160294 8402240037	PR 50~390 50-390 FOIA	A		8402060114 8402060114 8402060213 8402060213 8402070377	50-324 50-324 50-400 50-400 50-261	P G Q X
Boston College, Chestnut Hill, MA Doston Edison Co	8402030047* 8402070004* 8402080343 8402070182 8402070253	CONTRACT 50-293 50-293 50-293 50-293	0 8 4 4		8402070377 8402070377 8402080158 8402080192 8402080234	50-241 50-261 50-261 50-400 50-324	X S S
	8402130341 8402140234* 8402140460 8402160423 8408220010 8402230145	50-273 50-273 50-273 50-273 50-273 50-273	6 6 6 7 8		84020B0278 84020B0278 84020B0301* 8402070067 8402070067	50-324 50-324 50-324 50-400 50-400	E E E G G
Grockton Hosp , Brockton, MA	8402270271 8402270277 8402270465 8402270202 8402020148*	50-293 50-293 50-293 50-293 70-2362	G 9 9 R		8402130001 8402130001 8402130153 8402130159* 8402130160	50-324 50-324 50-324 50-325	p. p
Broothaves National Laboratory	8303280015* 8303280024* 8310050295* 8310050311* 8401300328		P P P A		8402130195 8402130228 8402130228 8402130233 8402130233	50-261 50-324 50-324 50-400 50-400	P P Q
	8402040484 8402130018* 8402130021* 8402140438 8402140442*	NUREO FOIA FOIA TOPREP TOPREP			8402130238* 8402130238* 8402130244 8402130244 8402130246*	50~400 50~400 50~324 50~324 50~400	9 F F 0
	8402160333* 8402170430 8402170494 8402170503 8402210026	50-277 50-344 NUREQ 50-443 NUREQ	g P		8402130246* 8402130266 8402130294 8402130294 8402130328	50-400 50-400 50-324 50-324 50-261	e P P
Orown & Root Corp (subs of Halliburton Corp)	8402220077 8402240378 8402270328*	NUREQ NUREG 50-289 50-445	0 G		8402130338 8402130359 8402140005 8402140232* 8402140248*	50-400 50-324 50-325 50-324 50-324	0 8 8 8
Brown Bayeri Corp (subs of Brown Boveri & Co , Ltd) Brown Univ , Providence, RI Bryn Mawr College	8402030299 8402130141* 8402130304	50-312 CONTRACT 50-320	S		8402140254 8402140300* 8402140364 8402140364 8402140377	50-324 50-324 50-324 50-324 50-261	8 0 R P
Bunker Hill Community College Burke County, GA Businessmen for the Public Interest	8402280402 8402150155 8402210118 8402280218	PRM 50~424 50~454 50~347	0		8402140389* 8402140390 8402140394* 8402140411*	50-261 50-261 50-261 50-400	P P Q
C Itoh & Co (America), Inc CONUCO, Inc (Continental Oil Co) Cable News Network, Inc Cabat Corp California, State of	8402010461 8402010446* 8402290001 8402090446	XPORTLIC WASTE MG FOIA 40-6940 CONTRACT	r		8402140417* 8402140417* 8402140458 8402140458 8402140467	50-400 50-400 50-324 50-324 50-324	8 8 8
	8402010078 8402010242 8402150451 8402230087	50-275 50-275 State Pri 50-275	U U Pg H		8402150217 8402150244 8402150258* 8402150275	50-400 50-261 50-261 50-324	P O
California, Univ of, Berkeley, CA California, Univ of, Los Angeles, CA	8402090469 8402090473 8402090511 8402020138* 8402070237	ACRB ACRS 50-335 50-142 50-142	о о		8402150375 8402150344 8402150388 8402160125 8402160201	50-324 50-324 50-400 50-325 50-400	() () () () ()
California, Univ of, Santa Barbara, CA Callendine, G W	8402160057 8402220162 8402020302 8402240235 8402270341*	50-142 50-142 50-433 50-433 FDIA	B G R R		8402160201 8402160207* 8402160207* 8402160233	50-400 50-400 50-400 50-400	0 0
Campaign for Prosperous Georgia Carolina Environmental Study Group Carolina Power & Light Co	8402280401 8402130235 8402270180 8402020227	50-424 50-413 F01A 50-400	0 0		8402140233 8402170103 8402170178	50-400 50-400 50-261 50-324	e e e
	8402020227 8402020230* 8402020230* 8402030175	50-400 50-400 50-400 50-400	0 0 0		6402220194 6402220267 6402220267 8402220249*	50-400 50-400 50-400 50-400	9 9
	8402030175 8402030276 8402030277 8402030341	50-261 50-261	G 8 F S		8402220269* 8402220430 8402220430 8402220537 8402220553	50-400 50-324 50-324 50-324 50-324	9 P 0 8
	8402030357 8402030340 8402030407 8402030450 8402030482		3 9 8 8		8402220586 8402230077 8402230077 8402240101 8402270131	50-324 50-324 50-324 50-325 50-400	8 P 8 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC*		AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGOS	
	8402270270 8402270270 8402270381 8402280056* 8402280071	50~ 324 50~ 324 50~ 325 50~ 324 50~ 261	F F G Q		8402020314* 8402030248 8402060048 8402060048 8402060105	50-440 50-440 50-440 50-440 50-440	KSAAE
	8402280129* 8402280170* 8402280189* 8402280320 8402280357*	50-400 50-241 50-400 50-324 50-261	9 9 9 9 9		8402040105 8402040358 8402040358 8402040359 8402040359	50~440 50~440 50~440 50~440 50~440	8888
	8402280362 8402280362 8402280407 8402280407 8402280420	50-400 50-400 50-400 50-261 50-400	6 G G P G		8402060378 8402060378 8402060400 8402060400 8402060411	50-440 50-440 50-440 50-440 50-440	s s s s
	8402280429 8402280469 8402280537 8402290094 8402290117	50-327 50-324 50-324 TOPREP 50-241	A F P		84020A0411 84020A0500 84020A0500 84020A0507 84020A0507	50-440 50-440 50-440 50-440 50-440	ន្ទ
rier for Applied Psychology Mir for Energy & Environmental	8402290165 8402290234 8402290237* 8402080468* 8402080092	50-400 50-261 50-261 FDIA FOIA	F F F		8402070233 8402070250* 8402150107 8402150107 8402150170	50-440 50-440 50-440 50-440 50-440	9 9 9
ter for Law in the Public Interest	8402070177 8402070183* 8402170053 8402220279	50-275 50-275 50-275 50-275	0 0		8402170039 8402170039 8402170149 8402170149 8402170273	50-440 50-440 50-440 50-440 50-440	5 5 5 5 5 5
-tral Power & Light Co ga-hucleur Systems, Inc.	8402130157 8402060047 8402080460* 8402090442 8402090444* 8402090576	50-556 27-47 CONTRACT 71-6601 71-6601 71-5026	г	Cleveland, OH	8402170273 8402230054 8402280337 8402290166 8402070222	50-440 50-440 50-440 50-440 50-440	8 0 9 8
uitran Corp	8402070577* 8402280643 8402280677 8402280647 8402280652*	71-9024 71-9108 71-9168 40-8724 40-8724		Coalition for Safe Power	8402240052 8402080132 8402220139 8402220142* 8402240076	90-440 90-460 50-397 50-397 50-344	H 0 0 0
res Contracting Corp Visty. W	B4022B0454* B402140531 B402140535* B402070147 B402070144*	40-8724 71-451 71-451 50-462 50-462	0	Colorado State Univ	8402240077 8402270585 8402280326 8402280458 8402170288	50-460 F01A 50-460 50-508 PR	0 0 0
rtirnati Gas & Electric Co	8402030260 8402060393 8402080389 8402220064 8402270272	50-358 50-358 50-358 50-358 50-358	9 9 9	Colorado State Univ . Ft Collins, CO Colorado, State of	8402080282* 8402080282* 8402080286* 8402080286* 8402080497*	50-416 50-416 50-416 50-416 CONTRACT	P P P
riroati, OH Liens Against Nuclear Power	8402270310 8402100236* 8402100240* 8402160242	50-358 50-358 50-358 50-253	A H H	Combustion Engineering, Inc	8402100422 8402010433* 8402010437* 8402030219* 8402030222*	NASTE MG 50-528 50-528 50-528 50-528	A A S S
litths Association for Sound Energy	8402060150 8402060153* 8402060153* 8402060158*	50-445 50-445 50-445 50-445	0 0 0		8402060247* 8402210094 8402220489 8402220489 8402220496*	50-528 70-1100 50-470 50-470 50-470	A E E E
	8402050161* 8402070171 8402100066 8402100066 8402100072*	50-445 50-445 50-445 50-445	G T T T	Comex Corp Commerce. Dept of,	8402220496+ 8402240065+ 8402160356+ 8402280536+ 8402130041+	50-470 50-382 50-445 50-445 CONTRACT	E A G
	8402100079* 8402100079* 8402100079* 8402100085*	50-445 50-445 50-445 50-445	T T T	Commerce, Dept. of, National Bureau of Standards Commerce, Dept. of, Natl Oceanographic S Atmospheric Administration Committee to Bridge the Gap	8402010040# \$ 8402060184* 8402070236	50-498 CONTRACT 50-142	A G
	8402150097 8402150097 8402150097 8402150144 8402150144 8402150208 8402150208	50-445 50-445 50-445 50-445 50-445 50-445	T 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	Commonwealth Edison Co	8402210167 8402220360 8402020110 8402020162 8402020162 8402020345* 8402020347	50-142 50-142 50-374 50-373 50-373 50-10 50-275	
ilens for Nuclear Reactor Safety. Inc liens' Task Force - land Electric Illuminating Co	8402280347 8402280319* 8402280325* 8402290418 8402010055	50-445 50-170 50-170 FOIA 50-440	0 0 0		8402020349 8402030217 8402030224 8402030230 8402030230	50-295 50-373 50-373 50-265 50-237	9 8 8
	8402010055 8402020312 8402020312 8402020314#	50-440 50-440 50-440 50-440	е к к		8402030285 8402060133 8402060135	50-254 50-237 50-295	9 9

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	n w ne L. ne m ee le	ACCESSION NUMBER	BUBJECT	
	8402040167 8402040374 8402040378* 8402040444 8402040444	50-454 50-237 50-237 50-10 50-10	6 5 5 F		E E	14021 50346 14021 50352 14021 50358 14021 50358 14021 50358	50-254 50-373 50-237 50-237 50-237	0 8 F F
	8402060446 8402060446 8402060464* 8402060464* 8402060464*	50-10 50-10 50-10 50-10 50-10	F F F F		E 8	14021 50358 14021 50358 14021 50358 14021 50358 14021 50358	50-237 50-237 50-237 50-237 50-237	FFFF
	8402050464* 8402050464* 8402050464* 8402050464* 8402050464*	50-10 50-10 50-10 50-10 50-10	E E E E		8 8 8	1402150358 1402150358 1402150358 1402150362 1402150376	50-237 50-237 50-237 50-237 50-373	FFRS
	8402050464* 8402050464* 8402050464* 8402070127 8402070151	50-10 50-10 50-10 50-275 50-374	F F 영 P		E E	8402160039 8402160222 8402160222 8402160227* 8402160227*	50-373 50-454 50-454 50-454 50-454	F 0 0 0
	8402070187 8402070164 8402070172 8402070220 8402070303	50-304 50-304 50-295 50-265 50-265	9 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		E E	0402160231* 0402160231* 0402160251 0402160251	50-454 50-454 50-454 50-454 50-374	00008
	8402070336 8402080035 8402080041 8402080055 8402080151	50-275 50-245 50-373 50-374 50-295	P 9 8 8 F		E E	8402160334 8402170134 8402170134 8402170202 8402170204	50-373 50-454 50-454 50-265 50-304	8 0 8 8
	8402080378 8402080375 8402090290 8402100040* 8402100042*	50-237 50-454 50-373 50-373 50-373	Q 5 P P		E 6	1402210142 1402210238 1402210238 1402210251 1402210251	50-295 50-237 50-237 50-373 50-373	F P 8 8
	8402100137 8402100137 8402100137 8402100137 8402100137	50-10 50-10 50-10 50-10 50-10	F F F F		E E	8402210259* 8402210261* 8402210264 8402210264 8402210265	50-373 50-373 50-254 50-254 50-373	8 0 P
	8402100137 8402100137 8402100137 8402100137 8402100137	50-10 50-10 50-10 50-10 50-10	F F F F		E 6	9402210265 9402210307 9402220001 9402220013 9402220134	50-373 50-265 50-373 50-373 50-456	P 8 8
	8402100137 8402100137 8402100137 8402100137 8402100149	50-10 50-10 50-10 50-10 50-454	F F G		E E	3402220156 3402220176 3402220205 340222027 <u>0</u> * 1402220270*	50-295 50-373 50-304 50-373 50-373	\$ \$ 0
	8402100221 8402130191 8402130215 8402130220 8402130220	50-254 50-10 50-10 50-10 50-10	부 F F		E 8	8402220284 8402220332 8402220407 8402220412* 8402220413	50-373 50-254 50-374 50-374 50-275	8 F F 8
	8402130220 8402130220 8402130220 8402130220 8402130220	50-10 50-10 50-10 50-10 50-10	F F F F		E 8	402220416* 8402220416* 8402220524 8402220524 8402220528	50-373 50-373 50-275 50-295 50-295	0 6 F F
	8402130220 8402130220 8402130220 8402130220 8402130220	50-10 50-10 50-10 50-10 50-10	F F F F		£ £	8402220528 8402220551 8402220551 8402220559 8402240108	50-295 50-295 50-295 50-373 50-434	F F B A
	8402130220 8402130220 8402130365* 8402130383 8402130428	50-10 50-10 50-295 50-265 50-373	F F F S P		6 6	1402240115 1402240115 1402240118* 1402240118*	50-237 50-237 50-237 50-237 50-275	9 9 8
	8402130437 8402130439 8402130531* 8402130534* 8402130543*	50-295 50-295 50-454 50-454 50-454	R R G G		E E	402240120 402240120 402240120 402240125* 402240129*	50-454 50-454 50-454 50-295 50-295	A A 8 8
	8402130554* 8402140118 8402140134 8402140205 8402140205	50-454 50-254 50-295 50-237 50-237	Q F F P		E E	8402240135# 8402240141# 8402240144 8402270153# 8402270319	50-295 50-295 50-373 50-373 50-373	8 0 0 F
	8402140205 8402150210 8402150210 8402150233 8402150346	50-237 50-237 50-237 50-237 50-254	P G G S G		E E	8402270442* 8402270448* 8402270448* 8402280240 8402280240	50-454 50-275 50-275 50-454 50-454	0 0 E E

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8402220066 8402220068* 8402270318 8402270326 8402270336	50-247 50-247 50-247 50-247 50-247	ដ ខ ទ		8402280240 8402280240 8402280302* 8402280375 8402280410	50-454 50-454 50-254 50-10 50-10	E G E
-struction Technology Laboratories -1.mers Power Co	8402150387* 8401130173 8402010071 8402010071 8402010075*	50-329 50-255 50-329 50-329 50-329	G R G G G		8402280471 8402280471 8402290074 8402290078* 8402290219	50-454 50-454 50-373 50-373 50-237	0 F F S
	8402010095* 8402010098* 8402010098* 8402020059* 8402020068*	50-329 50-329 50-329 50-329 50-329	G G O A A	Computer Data Systems, Inc Confederated Tribes of Umatilla Indian Reservation	8402270225* 8402270232* 8402170150* 8402270542 8402080128	50-374 50-374 CONTRACT FOLA WASTE MO	
	8402020070* 8402020079* 8402020118 8402020118 8402020159*	50-329 50-329 50-329 50-329 50-329	A A A A	Conference of Radiation Control Program Directors, Inc Connecticut Yankee Atomic Power Co	8402170295 8402210172* 8402010219 8402010228*	50-213	F
	8402020141 840202020276 8402020276 8402020272	50-327 50-327 50-327 50-327 50-327	R A A R		6402030251 6402040417 8402070225 8402070226* 6402070246* 6402080283	50-213 50-213 50-213 50-213 50-213 50-334	9 P P P Q
	0402030154 0402030207 0402030212* 0402030213	50-155 50-155 50-155 50-155 50-327	G G A A		8402140135 8402150007 8402150007 8402150007 8402150007	50-213 50-213 50-213 50-213 50-213	
	8402030236 8402030236 8402030257 8402030282	50-329 50-329 50-255 50-329	A A P A	Connecticut, State of Conner & Watterhahn	8402220460 8402070296* 8402030197 8402030254 8402040059	50-213 CONTRACT 50-352 50-352 50-352	P G G
	8402030286 8402030286 8402030331* 8402030331*	50-329 50-329 50-329 50-329	8 8 A A		8402040059 8402040131 8402040143 8402040219 8402040219	50-352 50-352 50-416 50-352 50-352	0 0 0 0
	8402030335 8402030412 8402030437 8402030461	50-327 50-155 50-255 50-327	A F 8 8		8402070242 8402070242 8402070282 8402070282 8402070284	50-352 50-352 50-352 50-352 50-352	G G G G
	8402030481 8402030481 8402060124 8402060124	50-329 50-329 50-329 50-329 50-329	A A B S		8402070284 8402070287* 8402070287* 8402070292* 8402070292*	50~352 50~352 50~352 50~352 50~352	0 0 0 0
	8402040368 8402040371 8402040372 8402040372	50-329 50-329 50-329 50-329 50-329	A 8 8 8		8402070309* 8402070309* 8402080118 8402080124* 8402130276	50-352 50-352 50-354 50-354 50-354	0000
	8402060377 8402060377 8402060397 8402060416	50-329 50-329 50-330 50-329	A A B Q		8402140068 8402150074 8402160207 8402160207 8402160238	50-354 50-352 50-352 50-352 50-352	00000
	8402060427 8402060427 8402060454 8402060454	50-329 50-329 50-329 50-329 50-155	A A B S		8402140238 8402140264 8402220088 8402220088 8402220114	50-352 50-352 50-352 50-352 50-352	0 6 9 9
	8402070361 8402070361 8402080114 8402080222 8402080227	50-329 50-329 50-155 50-255	8 8 7 8		8402220122* 8402220122* 8402240054 8402240057* 8402240057*	50-352 50-352 50-416 50-416 50-416	0 0 0 0
	8402080227 8402080237 8402080237 8402080241	50-329 50-329 50-329 50-329 50-329	8 8 A	Consolidated Edison Co of New York: Inc	8402280328 8402280335 8402280347 8402280476 8402010140	50-352 50-352 50-416 50-352 50-247	0 0 0 R
	6402060324 6402060324 6402060387 6402060367	50-329 50-329 50-329 50-329 50-155	5 8 A A P		8402030292 8402030373 8402090154 8402130529* 8402140247	50-247 50-247 50-247 50-247 50-247	ងឧត្ត
	8402090101* 8402090199* 8402090255 8402090255	50-329 50-329 50-329 50-329	A A A		8402140267 8402220055 8402220058*	50-247 50-247 50-247	S F F

AUTHOR AFFILIATION	ACCESSION NUMBER	SVBJEC CATEOD		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8402100235 8402100253 8402130459 8402130459 8402130468	50-255 50-255 50-329 50-329 50-255	5 0 A A P		8402270010 8402270010 8402270015 8402270015 8402270379	50-329 50-329 50-329 50-329 50-329	8 8 9 9
	8402130471 8402130471 8402130475 8402140007 8402140177	50-329 50-329 50-329 50-255 50-255	A A F R		8402270379 8402270452 8402270452 8402270532 8402280181	50-329 50-329 50-329 50-255 50-329	A B H A
	8402140210* 8402140215* 8402140461 8402150224 8402150224	50-155 50-155 50-255 50-327 50-329	G G P A A		8402280181 8402280364 8402280364 8402280416 8402280416	50-329 50-329 50-329 50-329 50-329	A 9 8 8
	8402150228 8402150228 8402150276 8402150276 8402150287	50-329 50-329 50-329 50-329 50-329	5 6 A A		8402280430 8402280431 8402280431 8402280435 8402280435	50-155 50-329 50-329 50-329 50-329	0 A B B
	8402150287 8402150276 8402150276 8402150297 8402150297	50-329 50-329 50-329 50-255 50-329	A 5 8 R 5		8402280573 8402280573 8402280577 8402280577 8402290096	50-329 50-329 50-329 50-329 50-155	A 8 8
	8402150299 8402150301* 8402150314 8402150314 8402150339	50-329 50-255 50-329 50-329 50-329	S R B B A		8402270151 8402270151 8402270155 8402270155 8402270155	50-329 50-329 50-329 50-329 50-329	9 9 8
	8402150339 8402150347 8402150347 8402150380 8402150380	50-329 50-329 50-329 50-329 50-329	A 5 9 0 0		8402270213 8402270218 8402270218 8402270252 8402270252	50-329 50-329 50-329 50-329 50-329	6 6 6 8
	8402150395 8402150395 8402150395 8402160197 8402160314	50-155 50-155 50-155 50-155 50-155	F G P	Control Data Corp	8402290256 8402290256 8402290278 8402290278 8402250375	50-327 50-327 50-327 50-329 0A977	8 8 8
	8402160458 8402160458 8402170036 8402170036 8402170227	50-329 50-329 50-329 50-329 50-153	A G G F	Cotter Corp Cygna Energy Services Dairyland Power Cooperative	8402270499 8402010006 8402080013 8402220373 8402020209	FOIA WASTE NO FOIA 50-445 50-409	A A
	8402210091 8402210105 8402210345 8402210349* 8402210353*	50-155 50-255 50-155 50-155 50-155	() P O O		8402020287 8402020275* 8402030330 8402040427 8402040432*	50-409 50-409 50-409 50-409 50-409	р Р Р Г
	8402220012 8402220012 8402220111 8402220111 8402220179	50-329 50-329 50-329 50-329 50-329	8 8 8 8		8402070219 8402080221 8402080363 8402090291 8402150172	50-409 50-409 50-409 50-409 50-409	8 P B F
	8402220179 8402220185* 8402220193 8402220193 8402220199	50-329 50-329 50-329 50-329 50-329	A A S S S		8402160267 8402160290 8402160295* 8402170076 8402170098	50-407 50-409 50-409 50-409 50-409	8 P Q F
	8402220199 8402220202 8402220202 8402220206 8402220206	50-327 50-327 50-327 50-327 50-327	ន		8402170251# 8402210169 8402220093 6402220236 8402220481	50-409 50-409 50-409 50-409 50-409	G F P P
	8402220369 8402220384 8402220384 8402220404 8402220404	50-329 50-329 50-329 50-329 50-329	0 A A B B	Dala Electronics, Inc	B402230109 8402270603* B402270603* B402270609* B402270609*	50-407 FOIA FOIA FOIA FOIA	F
	8402220457 8402220457 8402220501 8402220504 8402220504	50-329 50-329 50-155 50-329 50-329	\$ \$ F \$ \$	Dallas Morning News Dames & Moore Data Consultants, Inc.	8402140015 8402040392 8402100257 8402280004 8402010362*	FOIA 50-395 WASTE MO NUREQ CONTRACT	r T
	8402220507 8402220507 8402220515	50-327 50-327 50-329	9 9 A	DaKalb Area Allianca for Responsible Energy	8402150417* 8402170034	CONTRACT 50-454	ø
	8402220522 8402220522	50-329 50-329	s s	Debevoise & Liberman Decision Management Co , Inc.	8402210118 8402270301 8402270205*	50-454 50-413 50-392	Q Q A
	8402230012 8402230012 8402230138 8402230141* 8402230240	50-155 50-155 50-155 50-155 50-255	P P G P	Defense. Dept of, Defense Nuclear Agency Del-Aware Unlimited, Inc	8402280314 8402280319* 8402280325* 8402220113	50~170 50~170 50~170 50~352	0000

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	lY	AUTH AFFILIA	HDR ATION	ACCESSION NUMBER	SUBJECT CATEGOR	RY
Celaware River Basin Commission Celaware, State of Patrolt Edison Co	8402040080 8402270253 8402070123* 8402130300 8402030427	50-352 50-352 CONTRACT 50-354 50-341	D D			8402130417 8402130422* 8402130422* 8402130469 8402130469	50-413 50-413 50-413 50-413 50-413	A A A
	8402040375* 8402080213* 8402080338 8402100147 8402100174*	50-341 50-341 50-341 50-341 50-341	@ @ @ A			8402140016 8402140149* 8402140184 8402140185 8402140216*	50-349 50-249 50-370 50-370 50-414	S 0 5 6 6
	8402130443 8402130444 8402210143 8402220038 8402220436*	50-341 50-341 50-341 50-341 50-341	S B A A G			8402140230 8402140230 8402140269* 8402140269* 8402140280*	50-413 50-413 50-413 50-413 50-413	6 9 9
	8402230159* 8402230166* 8402270018 8402270090	50-341 50-341 50-341 50-341 50-341	К К 8 А F			8402140280* 8402140311* 8402140336 8402140338 8402140470	50-413 50-413 50-413 50-413 50-413	0 6 7 6
	8402280327 8402280368* 8402290157 8402290228* 8402290248	50-341 50-341 50-341 50-341 50-341	F G 8 G B			8402140470 8402180178 8402180178 8402180300* 8402180304*	50-413 50-413 50-413 50-413	6 6 0 0
Splean Consultants. Inc	8402290267 8402290286 8402270265* 8402270268* 9402270276*	50-341 50-341 FOIA FOIA FOIA	8 S			8402150308* 8402150308* 8402150324 8402150324 8402150324	50-413 50-413 50-413 50-413 50-270	0 5 8
Diserty, J.F. Sch.L. Mayner, Inc	8402040200 8402070004* 8402270359 8402030106* 8402040128*	50-443 50-293 50-320 CONTRACT				8402150357 8402160374 8402170292 8402170292 8402210077	50-414 50-369 50-413 50-413 50-269	5 A A P
Cougherty, JB Im Chemical Co I, la Power Co	8402140245 8402070245 8402030218 8402030223 8402030225	50-322 TOPREP 50-369 50-370 50-370	ទ ទ ទ ទ			8402210077 8402210077 8402210081* 8402210081* 8402210081*	50-247 50-247 50-247 50-247 50-247	P P P
	8402030284 8402030287 8402030340 8402030340 8402030349	50-370 50-370 50-413 50-413 50-370	8 T T S			8402210122 8402210174 8402210174 8402210174 8402210184*	50-249 50-249 50-249 50-249 50-249	я 9 9
	8402030391 8402030449 8402060077 8402060077 8402060087	50-367 50-367 50-413 50-413 50-413	8 E E			8402210184* 6402210164* 6402210191* 6402210213 8402210213	50-249 50-269 50-249 50-269 50-269	7 4 4
	8402060087 8402060100 8402060100 8402060273 8402060273	50-413 50-413 50-413 50-413 50-413	E F E E			8402220051 8402220071 8402220071 8402220071 8402220077*	50-413 50-267 50-269 50-269 50-269	8 F F F F
	8402070181 8402070181 8402070310 8402070310 8402070316*	50-413 50-413 50-413 50-413	А А К К К			6402220077* 6402220077* 6402220275 6402220325 6402220325	50-269 50-269 50-413 50-369 50-369	# # 0 F F
	8402070316* 8402080164 8402080171 8402080171 8402080205	50-413 50-413 50-413 50-413 50-269	K G G G S			8402220328* 8402220328* 8402220358 8402220359 8402220359	50-369 50-369 50-287 50-413 50-413	FFBEE
	8402080212 8402080212 8402080244 8402090150 8402090251	50-413 50-413 50-287 50-413 50-413	T T 9 Q A			8402220385 8402220385 8402220493 8402220493 8402220517	50-413 50-413 50-369 50-369 50-269	EEFFP
	8402070251 8402070323 8402070323 8402070375 8402100125	50-413 50-413 50-413 50-369 50-413	A F F P			8402220517 8402220517 8402220521* 8402220521* 8402220521*	50-269 50-269 50-269 50-269 50-269	P P P P
	8402100125 8402100145 8402100145 8402130332 8402130332	50-413 50-413 50-413 50-413	6 6 7 7			8402220538 8402220538 8402220537* 8402220542* 8402220546*	50-413 50-413 50-413 50-413 50-413	EEE
	8402130337 8402130337 8402130409 8402130409 8402130417	50-413 50-413 50-413 50-413 50-413	E F F A			8402220547* 8402220548* 8402220549* 8402220549* 8402220552*	50-413 50-413 50-413 50-413 50-413	REBEE

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEORY
	8402220554* 8402220555* 8402220560* 8402220561* 8402220563*	50-413 50-413 50-413 50-413 50-413	# # #		6402130457* 8402150435* 6402150536* 8402170216* 6402010073*	50~335 P 50~352 A 50~220 P 50~416 P CONTRACT
	8402220564 8402220564 8402220566*	50-413 50-413 50-413	A A E	Earthquake Engineering Research Institute Ebasco Services. Inc (subs of Enserch Corp)	8402270417 * 8402160358*	TOARTHOO 50-333 G
	8402220549* 8402220 5 72*	50-413 50-413	E	Eberline Instrument Corp	8402240170* 8402010301 8402030306	50-392 A XPORTLIC 50-400 G
	8402220572* 8402220573* 8402220575* 8402220575* 8402220579*	50-413 50-413 50-413 50-413 50-413	E E E		8402030312* 8402030317* 8402030320* 8402030320* 8402030321*	50-400 Q 50-400 Q 50-400 Q 50-400 Q
	8402220580* 8402220581* 8402220583* 8402220585* 8402220587*	50-413 50-413 50-413 50-413 50-413	EEE		8402030324* 8402130314 8402130317* 8402130322* 8402140061	50-400 Q 50-400 Q 50-400 Q 50-400 Q 50-400 Q
	8402220587# 8402220588# 8402220570# 8402220570# 8402220571#	50-413 50-413 50-413 50-413		Edelstein & Payne	8402160226 8402280226 8402280425 8402280223 8402100435	50-400 Q 50-400 Q 50-400 Q 50-400 Q State Prog
	8402220573# 8402220574# 8402220575# 8402230106 8402230144	50-413 50-413 50-413 50-269 50-369	E E E	Edlow Intermational Co	8402280487 8402010051* 8402020422 8402100351* 8402130324*	PR XPORTLIC XPORTLIC XPORTLIC XPORTLIC
	8402230146 8402230149* 8402230149* 8402240085 8402240085	50-369 50-369 50-369 50-413 50-413	P P F F		8402130465 8402130472* 8402130568* 8402140604 8402140607*	XPORTLIC XPORTLIC XPORTLIC 71-513 71-513
	8402270101 8402270119 8402270185 8402270185 8402270195*	50-367 50-370 50-367 50-369 50-369	8 8 8 9 9	Electric Power Research Institute	8402150032 8402210034 8402130043* 8402130070* 8402130081*	70-2955 XPORTLIC FOIA FOIA FOIA
	8402270195* 8402270304 8402280177 8402280422	50-349 50-370 50-369 50-369	P 8 9 5		8402130109* 8402100436	FOIA State Prog
	8402280507 8402290307	50-370 50-413	5 9	Ely, Ritts, Pietrowski & Brickfield	8402080148 8402210247 8402010001	50-458 M 50-458 M Waste Mot
Duquesne Light Co	8402290312* 8402290314* 8305180559 8401240177	50-413 50-413 50-412 50-412 50-334	\$ 8 A A		8402010010 8402010011 8402010015 8402010018 8402010026	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT
	8402030467 8402070184* 8402080359 8402080412	50-412 50-412 50-334 50-334	8 9 8 8		8402010066 8402010229* 8402010305 8402010308 8402010323	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT
	8402100437 8402130046 8402130048* 8402130184 8402130188*	State Pr 50-412 50-412 50-412	C C K		B402010326 B402010329 B402010347 B402010350 B402010360	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT
	8402130470 8402140160* 8402140490 8402220466	50-412 50-412 50-334 50-334	C A Q G		8402010363 8402010377 8402010427 8402010430 8402010443	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT
Distribution 1.5	8402240155 8402270242 8402280366 8402290238	50-412 50-334 50-334 50-412	A Q S A		8402010474 8402010528 8402010529 8402020207	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT
Durlacher, J E E C Rodabaugh Associates, Inc EG&G, Inc	8402270280* 8402270283* 8402270288* 8402090332 8401190528*	FOIA FOIA FOIA ACR9 50-412	A		8402020374 8402020440 8402030120 8402030495 8402030497	WASTE MOT WASTE MOT WASTE MOT WASTE MOT
	8402010279* 8402030099 8402080032 8402090310 8402090310	50-338 NUREG 50-269 50-259 50-259	P P P		8402030502 8402030504 8402030509 8402030511 8402030514	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT
	8402090316 8402090324 8402100352* 8402100421 8402130457*	50-261 50-261 50-263 50-259 50-335	P P 9 9		8402030517 8402030518 8402030521 8402040014	WASTE MOT WASTE MOT WASTE MOT WASTE MOT

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	
	8402060020 8402060022* 8402060027 8402060033 8402060049	WASTE MOT WASTE MOT WASTE MOT WASTE MOT		8402010165* 8402070134* 8402070376 9402070379* 8402080174	50-321 50-322 50-305 50-305 50-482	F G F G
	8402060055* 8402060069* 8402060155 8402100298 8402100318	WASTE MOT FOIA WASTE MOT WASTE MOT WASTE MOT		8402070060 8402070060 8402070204 8402070204 8402070207*	50-454 50-454 50-454 50-454 50-454	F F F F
	8402100320 8402100325 8402100328 8402100331 8402100448	WASTE MOT WASTE MOT WASTE MOT WASTE MOT State Prog		8402090211 8402090218* 8402090237 8402090247* 8402090298	50-482 50-482 50-275 50-275 ORO	F F F
	8402100492 8402100495* 8402100499 8402130271 8402140584	WASTE MOT WASTE MOT NUREO WASTE MOT WASTE MOT		8402070334 8402070337* 8402070337* 8402100228 8402100233*	50-289 50-289 50-289 50-10 50-10	F F F F
	8402150001 8402150542 8402140418* 8402140425 8402140424	71-5607 WASTE MOT WASTE MOT WASTE MOT WASTE MOT		8402130335* 8402130358 8402140133* 8402150119 8402150137	50-331 50-382 50-247 50-322 50-395	F G G F
	8402170148* 8402170172* 8402170233* 8402170330 8402220084	50-322 G 50-322 G 50-322 G WASTE MOT 50-537 G		8402150221 8402150237* 8402150332 8402150370 8402150370	50-257 50-259 50-382 50-206 50-206	F F F F
	8402270181 8402270561 8402270625 8402270633 8402280103	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT	•	8402160362* 8402210102* 8402210102* 8402220263* 8402280713	50-289 50-277 50-277 50-320 COMM1891	F F F ton
	8402280247 8402280253* 8402280347* 8402280382 8402270212	WASTE MOT WASTE MOT WASTE MOT PR 50-537 A	Fischer, Franktin, Ford, Bimon & Hogg Florida Power & Light Go	8402220367 8402010407* 8402030220 8402060387 8402060466	50-329 50-250 50-250 50-250 50-250	8 P G P
g, Dept of, Idaho Operations Office	8402290215* 8402140612 8402280646 8402280668* 8402280676	50-537 A PROJ PROJ PROJ PROJ		8402050465 8402050467* 8402050467* 8402050470 8402070381	50-250 50-250 50-250 50-389 50-335	P P P F
-	8402080181* 8402130033* 8402130083* 8402140173* 8402210439*	50-280 F FOIA FOIA FOIA CONTRACT		8402070383* 8402070383* 8402070385* 8402070385* 8402070388*	50-335 50-335 50-335 50-335 50-335	F F F F
isle, E 8 esnaemtal Congress of Mid-Michigan esnaemtal Policy Institute	8402280672* 8402280317* 8402280325* 8402070034 8402030186	CONTRACT 50-170 G 50-170 G FOIA WASTE MOT		8402070388* 8402070391* 8402070391* 8402080383 8402080383	50-335 50-335 50-335 50-335 50-335	F F F F
ronaental Protection Agency	8402030190* 8402020122 8402020160 8402060088 8402070340	WASTE MOT 50-50B D 50-456 D ORO 50-352 D		8402080405 8402100209 8402100439 8402130230 8402130288	50-389 50-250 State Pr 50-250 50-250	F 99 99
enaental Burveillance Laboratory , Hime Associates, Inc. tear Communities, Commission of	8402080157 8402080160* 8402010050* 8402080414* 8402020425	WASTE MOT 40-1341 CONTRACT 50-237 G XPORTLIC		8402130362 8402130368* 8402130368* 8402130449 8402130449	50-335 50-335 50-335 50-335 50-335	F F F F
i D.D Noctuar Co , Inc (subs of Exxon	8402070506 8402220635 8402240373 8402130418	XPORTLIC XPORTLIC NUREG 70-1287		8402130501 8402130501 8402140076 8402140076 8402140076	50-335 50-335 50-250 50-250 50-250	F 0 0
iervšcas	8402130536 8402130540* 8402140040* 8402280010 8402270517	XPORTLIC XPORTLIC 70-1257 NUREO 40-7580		8402140074 8402140085 8402140181 8402140181 8402140266*	50-250 50-250 50-250 50-250 50-335	9
rg Motual Research Corp n Carriers, Inc g & Associates, Inc	8402210041* 8402070373 8402130036* 8402130060* 8402130103*	CONTRACT 50-204 B FOIA FOIA FOIA		8402140495 8402150149 8402150154* 8402160148 8402160148	50-389 50-335 50-335 50-250 50-250	5 P P P
gi Emergency Management Agency	8402130119* 8402130119* 8402130131* 8402130137* 8402010160	FOIA FOIA FOIA FOIA 50-321 F		8402170212# 6402170247 6402170238 6402210116 6402210116	50-250 50-250 50-335 50-250 50-250	9 F F F

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGO!		AF	AUTHOR FILIATION	ACCESSION NUMBER	SUBJEC CATE©D	IRY
	8402220571 8402270238 8402270399 8402270399 8402270399	50-335 50-367 50-250 50-250 50-250	0 5 F F	General Motors C	orp	8402270138 8402270449 8402290017 8402290093 8402010298	70-1308 PT21 XPORTL I 50-354 XPORTL I	ic B
	8402270377 8402270377 8402270414 8402280038 8402280156*	50~250 50-250 50-250 50-250 50-335	E 8 8 0	General Nuclear General Public G Corp	Systems. Inc /tilities - GPU Service	8402010299 8402080422 8402080425* 8207090028*	XPORTL I PROJ PROJ 50-289	C P
	6402280156* 6402280244* 8402280244*	50-335 50-250 50-250	α α α	Corp		8208310181* 8210130553* 8402010137	50-289 50-289 50-320	Р Р Н
Florida Power Corp	8402280490 8402030409 8402030416	50-250 50-302 50-302	Q 3 5			8402020240 8402020305 8402020367	50-146 50-21 <i>9</i> 50-320	9
	8402040224 8402040379 8402040435 8402080021	50-302 50-302 50-302 50-302	P F P			8402030233 8402030246# 8402030310 8402030356 8402030435	50-289 50-289 50-289 50-289 50-320	₽ \$ \$
	8402080134 8402080141* 8402130226 8402150199 8402150203*	50-302 50-302 50-302 50-302 50-302	P P H P			8402030443 8402030451 8402030452 8402060118 8402060166	50-289 50-320 50-289 50-219 50-219	P P R S P
	8402220004 8402220005* 8402220172 8402220210 8402220335	50-302 50-302 50-302 50-302 50-302	P P S P S			8402040388 8402040440 8402070120 8402070175# 8402070252	50-287 50-287 50-217 50-287 50-287	P F G P
Florida, Univ of, Gainesville, FL Franklin Institute/Franklin Research Center	8402240121 8402280200* 8402160367 8206210343*	50-302 50-302 50-83 50-267	8 Q F P			9402070257* 9402070260* 9402070291 9402070350	50-287 50-287 50-287 50-287	P P P
	8301170355* 8309290095*	50~278 50-257	F Q			8402080215 8402080246	50-289 50-289	P S
Fried, Frank, Harris, Shriver & Kampelman	8309290297* 8402070470* 8402270253*	50-321 50-278 50-204 FOIA	P P			8402070001 8402070111 8402070341 8402100142	50-287 50-217 50-217 50-287	FPO
Frost, Freytag & Hunter Future Resources Associates, Inc GA Technologies, Inc /General Atomic Co	8402280085* 8402290064 8402010342* 8402090268 8402220301*	FDIA FDIA CONTRACT 70-734 GA999				8402100231 8402100446 8402130327 8402140113 8402140244	50-320 State P 50-219 50-320 50-219	R gor q q q
	8402240132 8402270078 8402280104 8402280108* 8402280496	50-89 50-163 TOPREP TOPREP 50-89	R R P			8402140288 8402140323 8402140340 8402140427 8402150225	50-320 50-289 50-289 50-320 50-219	0 8 P 0
GH-Bettis Corp Gall, W R	8402280494 8402030298 8402280263 8402280267* 8402290480	50-89 PT21 PT21 PT21 ACR8	P			8402150285 8402160014 8402160023* 8402160029* 8402160323	50-219 50-289 50-289 50-289 50-289	P P P
Gambit Gard, Inc Garvey, Schubert, Adams & Barer	8402090499 8402090534 8402240156* 8402100415* 8402170226	ACRB ACRB 50-382 CONTRACT FOIA	В			8402140395 8402170130 8402170140 8402170157 8402170157	50-289 50-219 50-289 50-219 50-219	9 F F
Gasaer Associates Gearhiser, Peters & Horton General Electric Co	8402040488* 8402080313 8402010077* 8402010287* 8402020290	CONTRACT FOIA GA999 50-271 TOPREP	P			8402210135 8402210195 8402210219* 8402210223 8402210235	50-267 50-219 50-289 50-219 50-320	F G P S
	8402020315 8402020323 8402070535 8402080028 8402080147	50-382 50-447 71-9001 50-447 TDPREP	V R			8402220264 8402220266 8402220293* 8402220427 8402220115	50-320 50-219 50-219 50-320 50-320	14 14 14
	8402080201 8402100148 8402130325 8402130427 8402130431	TOPREP 70-1113 TOPREP 70-754 70-1308				8402230128 8402230129 8402230131 8402230173 840224003&	50-289 50-289 50-219 50-289 50-289	P J P F
	8402140201* 8402140212* 8402140456* 8402140540 8402160462*	0A999 0A999 50-321 70-1113 50-245	P P			8402240099# 8402240112 8402240116# 8402240122# 8402240126	50-289 50-289 50-289 50-289 50-219	P P 0
	8402160610 8402170167 8402170325# 8402170527#	70-1308 NUREG 71-9009 71-9009				8402240131 8402240134* 8402270028 8402270031*	50-217 50-219 50-289 50-289	P P P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE CATEG	ORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	
	8402270074 8402270364 8402280286 8402280295 8402280340	50-146 50-320 50-219 50-289 50-289	۲ م م		8402270240* 8402270240* 8402270419 8402280024 8402280024	50-321 50-321 50-321 50-321 50-321	P F F F
·ila Power Co	8402280381 8402280387 8402280391 8402030400 8402030414	50-289 50-289 50-289 50-424 50-364	P K		8402280378 8402280405 8402280405 8402280466* 8402290100	50~424 50~321 50~321 50~366 50~321	9 9 9 F
	8402030417# 8402070236 8402080331 8402080331	50-424 50-321 50-321 50-321	K F F		8402020470* 8402240073 8402030354	CONTRAC1 50-424 PR	G
	8402100179	50~321	Р	Geotrans, Inc	8402010062* 8402280642*	CONTRACT CONTRACT	
	8402130321 8402130452 8402130452 8402130478 8402130478	50-366 50-321 50-321 50-321 50-321	8 F F F F	Getty/Petrotomics Co	8402100251 8402210306 8402210311* 8402210315* 8402270225	M18C 40~6459 40~6659 40~6659 50~584	A
	8402140238 8402140238 8402140334 8402140436 8402140441	50-424 50-424 50-321 50-321 50-321	A R P	Galdberg, Fieldman & Letham, F C Galder Associates	8402140107 8402070222 8402240052 8402210037* 8402210054*	50-440 50-440 50-440 CONTRACT CONTRACT	S H M
	8402140448* 8402140480 8402140480 8402140498* 8402150150	50-321 50-424 50-424 50-424 50-424	Р М О	Coadson & Associates, Inc Covernment Accountability Project	8402270473 8402210040* 8402070028 8402070028 8402080024	FOIA CONTRACT 50-327 50-329 50-528	A A S
	8402150150 8402150197 8402150197 8402150227 8402150227	50-424 50-321 50-321 50-424 50-424	р Р О		8402080203 8402070136 8402100016* 8402100021* 8402130003	50-413 50-280 FDIA FDIA 50-528	Q S A
	8402150241 8402150241 8402150277* 8402150288* 8402150391	50-424 50-424 50-366 50-366 50-321	S G G R	! !	9402130108* 8402170457 8402240148 9402240279 9402270491	50-528 FOIA 50-382 FOIA 50-329	6 0 A
	8402150391 8402150405 8402150405 8402150409 8402160228	50-321 50-424 50-424 50-366 50-321	R 8 8 9	8 6	8402270491 8402270536 8402270536 8402270550 8402270555	50-327 50-327 50-526	A 0 0 0 0 0 0 0 0
	8402140228 8402160232* 8402160396 8402160396 8402160410*	50-321 50-321 50-424 50-424 50-424	P C C	Gulf Dil Gorp	3402090414 3402150052 3402080191 3402280509 3401230407	71-9160 71-9161 PR PRM 50-458	5
	8402160498 8402160498 8402160499* 8402160499* 8402160502*	50-424 50-424 50-424 50-424 50-424	C C C	8 8	401240381 402030174 402040404 402070342 402080125	50-458 50-458 50-458	S A S E
	8402160506* 8402160506* 8402160511* 8402160511* 8402160517*	50-424 50-424 50-424 50-424 50-424	G G G	8 8	402080125 402090027* 402090209 402090213* 402140017	50-458 50-458 50-458	E 5 F 6
	8402160520* 8402160522* 8402160522* 8402160526* 8402160526*	50-424 50-424 50-424 50-424 50-424	6 6 6	8 9 8	4021 40064 4021 40064 4021 40066 4021 40067* 4021 40067*	50-458 50-458 50-458	KKSKK
	8402160528# 8402160531# 8402160531* 8402160536* 8402160536*	50-424 50-424 50-424 50-424 50-424	C C C	8 8	402140109 402140128 402140305 402140369 402160326	50-458 50-458 50-458	8 8 8 8
	8402160539* 8402160539* 8402160544* 8402160545* 8402220514	50-424 50-424 50-424 50-424 50-321	С С С С	B B	402160326 402160415 402160415 402170083 402170115	50-458 50-458 50-458	A A A B F
	8402220514 8402230058 8402240055 8402240055	50-321 50-424 50-321 50-321 50-321	P 0 F F P	8 8:	402170115 402170169 402170256 402170261 402210104	50-458 50-458 50-458	F 8 8 8
	8402240145 8402270073 8402270115 8402270215 8402270215	50-321 50-366 50-321 50-321	P 5 9 P	8· Bi	402210112 402210112 402210204 402210204	50~458 50~458	E A A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGD	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJEC BUBJEC	
	8402220395 8402220490 8402220490 8402230080 8402280153	50-458 50-458 50-458 50-458 50-458	5 A A S		8402130165 8402140047 8402140049* 8402140051* 8402140075	50-322 50-322 50-322 50-322 50-322	0000
Harmon & Weiss	8402280230 8402280371 8402280486 8402270089 8402010064	50-458 50-458 50-458 50-458 50-289	5 5 E 0		8402140091 8402140102 8402150110 8402150159 8402160254	50-322 50-322 50-322 50-322 50-322	A 0 0 0
	8402010477 6402020225 8402030239 8402030243* 6402080121	FOIA 50-322 WASTE M WASTE M FOIA			8402140278 8402170022 8402170100 8402170114 8402170125*	50-322 50-322 50-322 50-322 50-322	00000
Hartsville Group	8402130290* 8402130493 8402170049* 8402220153 8402260145	50-443 FOIA 50-322 50-287 50-261	0 0 0		8402170139* 8402170161* 8402170188* 8402220152 8402220454	50-322 50-322 50-322 50-322	0000
Harvey L, Walner & Associates, Ltd Hayward Tyler Pump Co Health Physics Associates, Ltd.	8402070156 8402100026* 8402280080* 8402280087* 7909170149*	50-261 FOIA FOIA 50-471 FOIA	G A	Hydro-Engineering	8402280231 8402280437 8402210285* 8402230086* 8402230091*	50-322 50-322 40-299 40-299 40-299	0
Health Physics Society Henry Pratt Co	8002130492* 8402270258* 8402100497 8402170120* 8402270234	FOIA FOIA NUREO GA999 PT21		ICN Pharmaceuticals, Inc (ICN-C&R Development) IIT Research Inst ITT Grinnell Industrial Piping, Inc (subs of ITT)	8402170293 8402100382* 8402080070*	PR CONTRACT FOIA	г
Hittman Nuclear & Development Corp (subs of Hittman Corp)	8402140618	71-9080		ITT Research Institute Illinais Power Co	8402240379* 8402030227	CONTRACT	r 8
House of Rep	8402140621* 8309150467* 8309150480* 8309150483*	71-9080 COMMISSI COMMISSI COMMISSI	ION ION		8402060052 8402060428 8402070152 8402130336 8402150317	50-461 50-461 50-461 50-461 50-461	8 E E
	8402010384* 8402040116* 8402100294* 8402240075 8402280020*	50-247 50-289 COMMISSI 50-247 FOIA	Ü EGN U		8402170001 8402170163 8402230088 8402240007 8402270021	50-461 50-461 50-461 50-461 50-461	F O A E S
House of Rep., Energy & Commerce House of Rep., Interior & Insular Affairs	8401110113*	50-275 50-287 50-275 FOIA COMMISSI			8402270025 8402270386 8402280235 8402280261 8402270274	50-461 50-461 50-461 50-461 50-461	8 8
	8402060120* 8402090127* 8402090132* 8402140044* 8402140050*	50-287 50-275 50-478 FOIA FOIA	U U	Illinois, State of Illinois, Univ. of, Urbana, IL	8402070550 8402100338 8402160237 8402270081 8402150232	40~2061 27~39 27~39 50~456 50~151	D A
Houston Lighting & Power Co	8402280045* 8402280045* 8402280049* 8402280370 8402040385	FOIA FOIA FOIA 50-275 50-498	U B	Illinois, Univ of, at Chicago Circle Impell Corp Indiana & Michigan Electric Co	8402100371# 8402170168# 8402030210 8402030210 8402030240	CONTRACT 50-322 50-315 50-315 50-316	
	8402060385 8402060414 8402060414 8402210046* 8402210051*	50-478 50-478 50-478 50-478 50-478	5 8 8 A A		8402030303 8402030316 8402030316 8402030464 8402030464	50-315 50-315 50-315 50-315 50-315	2 P P F
	8402210068* 8402220036 8402220037* 8402220037*	50-498 50-498 50-498 50-498 50-498	A K K K		8402030472 8402030472 8402060373* 8402060373* 8402070124	50-315 50-315 50-315 50-315 50-315	P 0 0 P
	8402280030 8402280147 8402280147 8402280448 8402280572	50-498 50-498 50-498 50-498 50-498	K 5 9 9		8402130280 8402140122 840220065 8402220087 8402220247	50-315 50-315 50-316 50-315 50-315	8 F 8 F
Hovis, Gockrill, Heaver & Bjur Hubacek, W G Humanetics, Inc Hunton & Williams	8402270038 8402010046* 8402010082 8402070277 8402080054	WASTE MO 50-498 XPORTLIC 50-322 50-322	0 0		8402220249 8402220252 8402220252 8402220474* 8402220474*	50-315 50-315 50-315 50-315	FFGG
	8402080149 8402080152* 8402080166* 8402090126 8402090153	50-537 50-537 50-537 50-322 50-322	G G G G	Indiana & Michigan Power Co.	8402240215* 8402270378 8402280461 8402290192 8402240041	50-315 50-315 50-315 50-315	0 0 F 0 F
	8402090157* 8402090163* 8402100133 8402100135*	50-322 50-322 50-322 50-322	0 0 0	Indiana, State of Information Systems & Network Corp Interior, Dept of	8402130398 8402230293* 8402220497	PR CONTRACT 50-352	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	RY
Interior, Dept of, Fish & Wildlife Service Interior, Dept of, Geological Survey International Atomic Energy Agency	8402130231 8402010022 8402030227 8402270632 8402060094*	WASTE M WASTE M WASTE M ORG	19T 19T	Justice, Dept of XOH Systems, Inc Kansans for Sensible Energy Kansas Gas & Electric Co	8408270080+ 8401070577* 8402170268* 8402280412 8402070136	50-287 50-322 CONTRACT 50-482	G S
International Energy Associates, Ltd International Nautronics, Inc Iowa Electric Light & Power Co	8402070043 8402010150* 8402020340 8402020346* 8402030244	FO1A 0A979 50-331 50-331	F F S		8402070136 8402070197 8402070201* 8402070205* 8402070139	50-482 50-482 50-482 50-482 50-482	E G G G
	8402030327 8402030334* 8402030377 8402030405 8402030410*	50-331 50-331 50-331 50-331 50-331	ե ե ե ե	•	8402070144* 8402100241* 8402130179 8402130407 8402130410*	50-462 50-462 50-462 70-2960 70-2960	G G
	8402030427 8402030433* 8402060250 8402070013 8402070015	50-331 50-331 50-331 50-331 50-331	P P S S		8402140188 8402140172* 8402140475 8402150400 8402170035	50-482 50-482 50-482 50-482 50-482	A & & & &
	8402070119 8402070300 8402140447 8402140476	50-331 50-331 50-331 50-331	P S S P		8402170135* 8402170157 8402220207 6402220377* 8402220452*	50-482 50-482 50-482 50-482 50-482	G S F G
	8402150127 8402150212 8402150305 8402160337 8402220006 8402230125	50-331 50-331 50-331 50-331	8 9 9		8402220550 8402220568* 8402280032 8402280058 8402280062*	50-492 50-482 50-482 50-482 50-482	S O S A A
	8402230123 8402270200 8402280332 8402280337 8402280470	50-331 50-331 50-331 50-331 50-331	R R S S S O	Kansas, State of Kansas, Univ of, Lawrence, KS Kastenberg, W.E	8402280382 8402130403 8402070166 8402070170* 8402010180*		v
lowe Btate Univ , Ames, 1A lowe, Univ of, Ioua City, IA lrving, S.M liham, Lincoln & Beale	8402270207 8402030382* 8402030307 8402010091 8402010091	NUREG CONTRAC 50-458 50-329 50-329		Kaye, Scholer, Fierman, Hays & Handler Kentucky, Commonwealth of,	8402100493* 8402070404 8402240067 8402290449 8402030354	CONTRACT FOIA 50-287 FOIA PR	Q
	8402010075* 8402010075* 8402030134 8402030209	50-329 50-329 50-155 50-155	9 9 9 9	Kentucky, Univ of, Lexington. KY Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp)	8402140310 8402140405 8402030101* 8402080187	State Pro State Pro CONTRACT 40-2041 40-8768	ag
	8402030212* 8402050187 8402070194 8402070101* 8402100149 8402140215*	50-454 50-455 50-327 50-454 50-155	G G A G	Kerr-KcGee Corp	8402270388 8402070332 8402100443 8402210475 8402220101	40-2061 40-2061 State Pro 40-8768 40-8768	og
	8402160197 8402160222 8402160222 8402160227* 8402160227*	50-155 50-454 50-454 50-454 50-454	0 0 0 8	Key Dook Service, Inc	8402220107* 8402220422 8402280524 8402270277 8402270421	40-8749 70-925 PR 40-2041 FOIA	
	8402160251 8402170036 8402210345 8402210349* 8402210353*	50-454 50-329 50-155 50-155 50-155	0 0 0	Kirkpatrick, Lockhart, Hili, Christopher & Phillips	8402030145 8402030148* 8402040185 8402040188*	50-322 50-322 50-322	0 0000
1ehitawajima — Harima Heavy Industries Co ∙Ltd.	8402230138 8402280430 8402280471 8402270518*	50-155 50-155 50-454 FOIA	e e o		8402100025 8402100123 8402100175 8402150113 8402150124	50-322 50-322 50-322	9 9 9
[taly, Govt of, Jacksonians United for Livable Energy	B402130508* B402150175	MISC 50-414	G		8402150135 8402150162	50~322 50~322	Q G
Poli¢ies Japan, Covt of Jaycor	8402020179 8402020205 8402130081*	XPORTLIC XPORTLIC FOIA			8402150171 8402150187 8402150193	50-322	0
Johnson Controls, Inc. Joint Intervenors — Diable Canyon	8402130097* 8402080058* 8402070177 8402070183*	FOIA 50-397 50-275 50-275	G G		8402160214 8402160219 8402160223* 8402210113 8402220148	50-322 50-322	0000
Joint Intervenors - Shearon Harris	8402130251 8402170053 8402220279 8402130314 8402130322*	50-275 50-275 50-275 50-400 50-400	G G G	Kohn, Milstein, Cohen & Hausfeld	840222002 8402220097 8402280213 8402090010 8402220138	50-322 50-322 50-322 50-287 50-287	0 0 T 0
Joint Intervenors — Waterford Joint Petitioners — TMI	8402280323 8402280468 8402290079	50-400 50-382 50-287	6 6 6	Kores, Republic of (South Kores) Kudzu Alliance LIXI, Inc	8402230015 8402280223 8402060329*	XPORTLIC 50-400 FOIA	c

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEOD!	
	8402080491 8402090208* 8402090223* 8402090228* 8402090232*	FOIA FOIA FOIA FOIA FOIA			8402170194* 8402210113 8402220152 8402220169 8402220198	50-322 50-322 50-322 50-440 50-322	9 9 9 F
	8402090242* 8402090246* 8402090254* 8402090259* 8402090262*	FOIA FOIA FOIA FOIA			8402220203* 84022204 54 8402280231 8402280375 8402280437	50-322 50-322 50-322 50-322 50-322	F 0 0 0 0
Labat-Anderson, Inc	8402070266* 8402070284* 8402070268* 8402070300* 8402230278*	FOIA FOIA FOIA CONTRACT		Los Alamos Scientific Laboratory	8402010111 8402010313 8402010368 8402100418 8402170498	NUREO NUREO NUREO SO-269 NUREO	þ
Labor, Dept of Lancaster, PA Larimore, R E Lawrence Livermore Laboratory	8402280524 8402220104 8001070204* 8001070207* 8402040333	PR 50-289 FOIA FOIA NUREG	G	Louisiana Consumer's League, Inc Louisiana Power & Light Co	8402280331 8402010088 8402010148 8402040208 8402040418	50-458 50-382 50-382 50-382 50-382	9 9 8
	8402040452 8402130117 8402150392* 8402210019 8402210021	NUREG NUREG 50-423 NUREG 50-275	A P		8402060468 8402070531 8402070258 8402070263* 8402070267*	50-382 70-2948 50-382 50-382 50-362	В F F
LeBoeuf, Lamb, Leiby & MacRao	8402060163 8402060167* 8402100436 8402230182 8402240217	50-244 50-244 State Pr 50-341 FOIA	o o cog K		8402100013 8402100237 8402100243 8402140056 8402140060	50-382 50-382 50-382 50-382 50-382	A A A B
League of Women Voters of Rockford, IL	8402040182 8402080131 8402230107* 8207300134* 8210290114*	50-454 50-454 50-454 50-289 50-289	G G G P P		8402140261 8402140272 8402140317 8402140395 8402140431	50-382 50-382 50-382 50-382 50-382	A 5 5 5 5
Limerick Ecology Action	8402280406 8402280510 8402060173 8402060173 8402060176*	PR PR 50-352 50-352 50-352	0 6 0		8402140571 8402150311 8402150313* 8402160106 8402160159	70-2946 50-382 50-382 50-382 50-382	E
Limitorque Corp	8402060176* 8402100027 8402100178 8402220143 8402240127	50-352 50-352 50-352 50-352 50-483	2 0 6 0		8402160353 8402170019 8402170229 8402170235 8402210207#	50-382 50-382 50-382 50-382 50-382	0 8 8 0
Literature Research Go Logical Technical Service Corp Long Island Lighting Go	8402170030* 8402170012* 8402170016* 8402060405 8402060407*	CONTRACT CONTRACT CONTRACT 50-322 50-322	F F		8402220044 8402220189 8402220536 8402230001 8402240062	50-362 50-362 50-362 50-362 50-362	A
	8402070277 8402070126 8402070153 8402070157* 8402070163*	50-322 50-322 50-322 50-322 50-322	6 9 9 9		8402240064 8402270325 8402280017 8402280217 8402280227	50-382 50-382 50-382 50-382 50-382	A A B F
	8402100133 8402100135* 8402130165 8402130170* 8402140047	50-322 50-322 50-322 50-322	6 9 0 0 6	Louisiana, State of	8402280272 8402280346 8402280515 8402290178 8402010522	50-382 50-382 50-382 50-382 Waste Mo	S A A A
	8402140049* 8402140051* 8402140058* 8402140075 8402140071	50-322 50-322 50-322	G G A	MARISOL, Inc. Maine Yankee Atomic Power Co	8402020063 8402020087 8402080481* 8402130489 8402020321	WASTE MO WASTE MO CONTRACT XPORTLIC 50-309	T
	8402140102 8402150110 8402150159 8402150176 840215011	50-322 50-322 50-322 50-322 50-322	9 9 8 R E		8402030008 8402060235 8402060241* 8402060245* 8402070002*	50-307 50-307 50-307 50-307 50-307	8 P P Q
	8402160254 8402160278 8402170022 8402170049* 8402170100	50-322 50-322 50-322 50-322	G G G G		8402070021 8402140328 8402210193 8402220141 8402220178	50-307 50-307 50-309 50-309 50-309	F P B H P
	8402170114 8402170118* 8402170125* 8402170132* 8402170137*	50-322 50-322 50-322 50-322	G G G		8402220200* 8402220224* 8402220230* 8402220371 8402270174	50-309 50-309 50-309 50-309	0 0 P P
	8402170144* 8402170153* 8402170161* 8402170180* 8402170188*	90-322 50-322 50-322 50-322	0 0 0 0		8402270421 8402280050 8402280478 8402270304 8402270308*	50-309 50-309 50-309 50-309 50-309	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
raine. State of	8402140285 840222020* 8402220214* 8402220230* 8402280447	50-309 H 50-309 G 50-309 G 50-309 G 50-309 H		84020A0084 84020A0103 84020A0103 84020A0143 8402080279	50-416 P 50-416 P 50-416 P 50-416 G 50-416 P
unufacturing Sciences Corp wrine Research, Inc Urt IV Industries	8402170312 8402210088* 8402170291 8402140546 8402140549*	WASTE MOT CONTRACT PRM XPORTLIC XPORTLIC		8402080279 8402090196 8402130389 8402130430 8402130430	50-416 P 50-416 P 50-416 S 50-416 S 50-416 S
arsh & McLonnan, Inc	8402020109 8402020343 8402020343 8402090335 8402140327	50~346 J 50~335 J 50~335 J 50~286 J 50~272 J		8402140013 8402140013 8402140322 8402140322 8402140410	50-416 S 50-416 S 50-416 G 50-416 S
arubanı America Corp (subs of Marubani	8402160343 8402210227 8402210231 8402210242 8402010300	50-390 J 50-253 J 50-259 J 50-438 J XPORTLIC		8402140410 8402150369 8402150369 8402170171 8402220057	50-416 S 50-416 R 50-416 R 50-416 B 50-416 S
Corp)	8402100368* 8402100480 8402100483 8402130342 8402130348*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC		8402220060 8402220119 8402220126 8402220246	50-416 S 50-416 S 50-416 S 50-416 S 50-416 F
iryland. State of	8402150492* 8402060542* 8402150436 8402270086 8402270086	XPORTLIC CONTRACT State Prog 50-320 P 50-166 V		8402220327 8402220401 8402220401 8402220531 8402220570	50-416 S 50-416 P 50-416 P 50-416 S 50-416 S
saachusetts Institute of Technology,	8402060450* 8402040455* 8402210158* 8402080325	50-146 V 50-166 V CONTRACT 50-20 K		8402230228 8402230228 8402230234* 8402240030 8402240030	50-416 S 50-416 S 50-416 S 50-416 P 50-416 P
stachusetts, Commonwealth of Liea Corp. Inell, J C	8402080327* 8402280404* 8402070307* 8402010357* 8402070521	50-20 K CONTRACT CONTRACT CONTRACT AGR8		8402240054 8402240054 8402240057* 8402240057* 8402240059	50-416 0 50-416 0 50-416 0 50-416 0 50-416 R
Dermott, Inc Graw-Hill Publications Co Sical Physics Consultants, Inc sel, Jacobs, Pierno & Gersh	8402070522 8402060357 8402010439* 8402270274* 84022160635	ACRB TOPREP CONTRACT FOIA 40-7455		8402240059 8402240060* 8402270085 8402270144 8402270159	50-416 R 50-416 R 50-416 S 50-416 S 50-416 S
ophia State Univ., Mamphis, TN tropolitan Edison Co.	8402090592* 8402030170 8402030183 8402030187* 8402030289	CONTRACT 50-289 0 50-289 0 50-289 6 50-289 0		8402270227 8402270323 8402270404 8402270404 8402270407	50-416 S 50-416 S 50-416 S 50-416 S 50-416 S
	8402050174 8402070259 8402080150 8402090125	50-289 G 50-289 G 50-289 G 50-289 G		8402280265# 8402280272# 8402280347 8402280421# 8402280423#	50-416 G 50-416 G 50-416 G 50-416 G 50-416 G
	8402070127* 8402070130 8402070137 8402130185 8402130190	50-289 G 50-289 G 50-289 G 50-289 G		8402280427* 8402280428* 8402280550 8402280575	50-416 0 50-416 0 50-416 8 50-416 0 50-416 0
	8402130305 8402130307 8402210207 8402220074 8402220133	50-287 9 50-287 9 50-287 9 50-287 9 50-287 9	Miasissippi, State of	8402270012 8402270013* 8402270174 8402020042 8402030076*	50-416 P 50-416 P 50-416 S HASTE HOT CONTRACT
	8402230076 8402230111 8402240077* 8402280343 8402280352*	50-287	Missouri, State of	8402030253 8402040104 8402040107 8402170248 8402010081*	WASTE MOT WASTE MOT WASTE MOT WASTE MOT CONTRACT
higan State Univ., Eest Lansing, MI higan, State of	8402100011 8402010333*	50-294 R CONTRACT	Mitsubiski International Corp (subs of Mitsubishi Corp)	8402100269 8402100379#	50-493 H XPORTL IC
higan, Univ. of, Ann Arbor, MI fle South Services, Inc ler. D S	8402080191 8402140155 8402270374* 8402150447 8402220200*	PR WASTE MOT 50-327 O State Prog 50-307 G	Urangatana asib .	8402100385* 8402130142* 8402130147*	XPORTLIC XPORTLIC XPORTLIC
nesota, State of	8402220218* 8402220230* 8402010176* 8402030247 8402010166	50-309 G 50-309 G CONTRACT WASTE MOT 50-416 G		8402130476 8402150021 8402150026# 8402150029	XPORTLIC XPORTLIC XPORTLIC
sissippi Power & Light Co.	8402040083 8402040083 8402040084	50-416 B 50-416 H 50-416 P	Mitsul & Co (USA), Inc (subs of Mitsus & Co , Ltd.)	8402150030* 8402010131 8402010374	XPORTLIC XPORTLIC XPORTLIC

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHDR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY
Mobil Cil Corp (subs Mobil Corp) Molycorp, Inc	8402010447 8402270040 8402280499 8402280704# 8402280708*	XPORTLIC 50-10 F 40-8794 40-8794 40-8794	New England Coalition on Nuclear Pollution New Hampshire, State of New Jersey, State of	8402150566 8402130290* 8402070323* 8402060148	WASTE MOT 50~443 G
Morgan Associates Multidisciplinary Energy & Environ Sys &	8402090154	50-247 G 40-8584	Hem Datised, Trace of	8402080399	50-354 G CONTRACT FOIA
Applications Municipal Electrical Authority of Georgia Murphy & Davenport		50-424 I 50-424 I WASTE MGT	New Mexico, State of	8402210146 8402220333 8402220336 8402080225	50-219 P 50-354 A 50-354 9 PR
ND Resources, Inc	8402080182* 8402010345 8402010347* 8402010488 8402080318	WASTE MGT 40-8643 40-8663 FOIA FOIA	New York, State Univ of, Stony Brook, NY New York, State of	8402070178 8402030151 8402030201 8402070121 8402070126*	50-322 T 50-322 0 50-322 0 50-247 0 50-247 0
	8402100334 8402100459 8402170447 8402230407 8402230425	WASTE MOT FOIA FOIA FOIA FOIA		8402070199 8402100175 8402150164 8402150180 8402160247	20-355 6 20-355 6 20-355 6 20-355 6
	8402240198 8402240201 8402270479 8402270637 8402280 5 96*	FOIA 50-315 S FOIA FOIA FOIA	Newman & Holtzinger	8402220125 8402220131 8402220148 8402280322 8402010441	50-322 9 50-322 0 50-322 0 50-322 0 FOIA
	8402280600* 8402280602* 8402280605* 8402280607* 8402280611*	FOIA FOIA FOIA FOIA	Niagara Mohawk Power Corp	840202020126 8402020359 8402020363* 8402030256	50-331 J 50-410 B 50-410 X 50-410 K 50-220 S
	8402280614* 8402280615* 8402280620* 8402280623* 8402280627*	FOIA FOIA FOIA FOIA		8402060005 8402060156 8402060224 8402060237 8402060425	50-220 P 50-220 F 50-410 S 50-220 P 50-410 K
	8402280631* 8402280636* 8402280637* 8402280646* 8402280647*	FOIA FOIA FOIA FOIA		8402070146 8402070150* 8402070154* 8402080155 8402080162*	50-220 P 50-220 P 50-220 P 50-220 P 50-220 P
NUSAC, Inc	8402280453* 8402280457* 8402280490* 8402280494* 8402170484*	FOIA FOIA FOIA FOIA CONTRACT		8402080165# 8402080229 8402090068 8402090073# 8402090075*	50-220 F 50-220 S 50-220 F 50-220 F 50-220 P
NUTECH Engineers, Inc	8402080038* 8402080040* 8402080045* 8402220541* 8402230101*	50-265 G 50-265 G 50-265 G 50-324 G 50-354 A		8402070277 8402130553* 8402140335 8402140344 8402150205	50-220 P 50-410 Q 50-220 P 50-220 B 50-410 B
	8402230108* 8402230113* 8402230116* 8402230120* 8402230126*	50-354 A 50-354 A 50-354 A 50-354 A		8402150345 8402160366 8402160404 8402220132* 8402240080	50-410 A 50-220 R 50-220 P 50-220 P 50-410 S
	8402270076* 8402270078* 8402270103* 8402270106* 8402270107*	50-341 A 50-341 A 50-341 A 50-341 A 50-341 A	Nikko Wolverine, Inc Nissho Iwai American Corp North Carolina Municipal Power Agencies	8402240146 8402240220* 8402010460 8402220640 8402030175	50-410 B 50-220 R XPORTLIC XPORTLIC 50-400 9
National Research Council Natural Resources Defense Council	8402090483 8402080149 8402080152* 8402080166* 8402210336*	ACRB 50-537 G 50-537 G 50-537 G 50-320 P		8402060213 8402130233 8402130233 8402130238* 8402130238*	50-400 0 50-400 0 50-400 0 50-400 0 50-400 0
Navy, Dept of Navy, Dept of, Pearl Harbor Naval Shipyard	8402240336 8402070440 8402150418 8402150421*	FOIA 71-9032 71-133 71-133	North Carolina State Univ , Raleigh, NC North Carolina, State of	8402150219 8402140381 8402070343* 8402140479 8402150293	50-400 G 50-277 H CONTRACT State Prog 50-400 A
Nebraska Public Power District	8402100202* 8402170287	50-278 G 50-278 F	North Dakota, State of Northeast Nuclear Energy Co (subs of	8402080191 8402010219	PR 50-213 F
	8402210047* 8402220029 8402220032* 8402270228	50-278 P 50-278 P 50-278 P 50-278 F	Northeast Utilities)	8402010232* 8402010232* 8402010237*	50-213 F 50-213 F 50-213 F
Nebraska, State of	8402280355 8402280398 8402280474 8402060502* 8402030237	50-298 8 50-298 8 50-298 8 CONTRACT WASTE MGT		8402010237* 8402020152 8402020156* 8402020351 8402030274	50-213 F 50-423 C 50-423 C 50-423 F 50-245 S
	8402060044 8402080178 8402080182*	WASTE MOT WASTE MOT WASTE MOT		8402030397# 8402030402# 8402060211	50-336 0 50-336 0 50-423 6

- AUTHOR AFFILIATION	ACCESSION NUMBER	CATEG	PORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE CATEG	ORY
	8402070305 8402080247 8402080251 8402080283 8402100197	50-336 50-423 50-336 50-336 50-245	5 A	Northeast Utilities Service Co (subs	9402240240 9402280233 8402280274 8402280673	50-423 50-423 50-423 71-440	A S A
	8402100204 8402100237 8402140135 8402140414 8402140407	50-334 50-423 50-213 50-334	S S A A F A P	Northeast Utilities)	8402140117* 8402220170 8402220484	50-245 50-336 50-336 50-423	G P A
	8402150007 8402150192	71-657 50-213 50-245	₽	Northern States Power Co	8402240113 8402060444	50-245 50-263	F
	8402150182 8402150214 8402150307 8402150307	50-245 50-336 50-245 50-245	F S P		8402060449* 8402070011 8402070011 8402070358 8402080209	50-243 50-282 50-282 50-282 50-282	F P 9 5
	8402150340 8402150343* 8402150348 8402160002	50-336 50-336 50-336 50-336	9 9 9		8402080317* 8402080317* 8402080319* 8402100020 8402130442*	50-282 50-282 50-282 50-263 50-263	F F S
	8402160005 8402160005 8402160044 8402160053* 8402160100	50-245 50-245 50-336 50-336 50-336	F P P		8402130577 8402140011 8402140382 8402150183 8402150183	50-263 50-263 50-263 50-282 50-282	S S R R
	8402160183 8402160385 8402160391# 8402160424	50-336 50-245 50-245 50-336	0 P P		8402150320* 8402150320* 8402160080 8402160369 8402160390	50-282 50-282 50-263 50-263 50-282	0 8 F F
	8402160459 8402170044 8402170046* 8402170223	50-245 50-245 50-245 50-336 50-336	P P 9 9		9402160473 9402160473 9402170101 9402220067 9402220056	50~263 50~263 50~282 50~282 50~263	P Q Q
	8402220170 8402220378 8402230103 8402240005	50-336 50-334 50-245 50-423 50-245	P S P A		8402220415 8402230238 8402240011 8402240123 8402270234	50-263 50-263 50-263 50-263 50-262	Q P G R
hartheast Utilities	8402280294 8402280673 8402010219 8402020152	50-423 71-6601 50-213 50-423	Α	Northwestern Univ , Evanston, IL NucleDyne Engineering Corp Nuclear Associates, Inc Nuclear Assurance Corp	8402280382 8402280300 8402290374 8402090340* 8402060046*	PR REGGD MISC FOIA FOIA	
	8402030397# 8402030402* 8402040211 8402070305	50-336 50-336 50-423 50-336	0 9 9 8	Nuclear Awareness Network Nuclear Energy Service, Inc	8402060073* 8402150076 8402010057 8402280201 8402070575	FOIA 50-246 50-482 50-482 71-512	F H G
	8402080251 8402080283 8402100197	50-334 50-334 50-245	8 0 P	Muclear Fuel Services, Inc (subt of Getty Di) Co)	8402070381* 8402070327	71-512 70-143	
	8402100206 8402100239 8402140135	50-336 50-423 50-213	S A F		8402100164 8402100414 8402100416*	70-143 70-143 70-143	
	8402140135 8402140135 8402140416 8402150007 8402150182	50-213 50-213 50-336 50-213 50-245	F F P P F		8402140425 8402140463 6402140556 8402280040 6402280303*	70-143 70-143 70-143 70-143 70-143	
	8402150182 8402150214 8402150307 8402150340	50-245 50-336 50-245 50-336	F S P	Nuclear Information & Resource Service	8402280685 6402140483 8402220127 8402230441 8402240304	70-143 FOIA 50-220 FOIA 50-287	P P
	8402150348 8402160002 8402160005 8402160044	50-336 50-336 50-245 50-336	8 0 F P	Nuclear Hedirine Associates, Inc., Cleveland, OH	8402270295 8402270500 8402280338 8001040264*	50-508 FOIA 50-250 FOIA	A P
	8402140113 8402140385 8402160424 8402160437	50-334 50-245 50-334 50-336	В Р Р	Nuclear Metals, Inc	8402270324* 8402020274* 8402100466	FOIA 40-672 XPORTLIC	
	8402160459 8402170044 8402170223 8402210257	50-245 50-245 50-334 50-334	P P S Q	Nuclear Packaging, Inc.	8402100467* 8402090565 8402090578* 8402090584*	XPORTLIC 71-9186 71-9186 71-9186	
	8402220378 8402220417 8402220486	50-336 50-423 50-423	S E A	Nuclear Products Co Nuclear Radiation Consultants	8402140597 8402160599 8402070117* 8402040415	71-9184 71-9181 50-482 PRM	F
	8402230103 8402240005 8402240017	50-245 50-423 50-423	P A A	D'Neill, J	8402130259 8402140045	50-155 50-155	e e

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	. AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEODRY
	8402150133 8402150138* 8402150147* 8402150153* 8402210185	50-155 G 50-155 G 50-155 G 50-155 G 50-155 G		8402140146* 8402140419 8402150255 8402150356 8402160429	50-275 0 50-275 E 50-275 S 50-275 S 50-275 P
Oak Ridge Associated Univs Oak Ridge National Laboratory	8402150568 8402010115 8402060076* 8402060457 8402060478	70-820 NUREG 50-287 P NUREG NUREG		8402170013 8402210061 8402210082 8402210216 8402210216	50-133 P 50-275 E 50-133 P 50-275 P 50-275 P
	8402060529 8402080418# 8402080461 8402100407 8402170417	NUREG FOIA RES TOPREP NUREG		8402210224 8402210243 8402210255 8402210267 8402220043	50-275 S 50-275 S 50-275 E 50-275 P 50-275 E
Ohio Citizens for Responsible Energy	8402170439 8402210073 8402280114 8402080170 8402150389	NUREG NUREG NUREG 50-440 G 50-412 A	Parific Nuclear Systems & Services, Inc Palmetto Alliance	8402240031 8402280036 8402280197 8402070510 8402070153	50-275 E 50-133 X 50-133 9 71-9175 50-413 G
	8402220136 8402220136 8402220237 8402220237 8402220353	50-440	Parameter, Inc	6402130235 6402160260 6402280373* 6402010110* 6402140516*	50-413 0 50-413 0 50-413 0 CONTRACT 50-287 P
Dhio, State of	8402220353 8402270247 8402270425 8402010273* 8402030353	50~440 G FOIA 50~440 A 50~346 P PR	Parents Concerned About Indian Point	8402140516* 8402140520* 8402140520* 8402070161 8402070161	50-287 P 50-287 P 50-287 P 50-247 G 50-247 G
Oklahoma, State of Omaha Public Power District	8402080186 8402080171 8401170226 8402060370 8402070229	PR PR 50-285 R 50-285 P 50-285 P	Pathfindor Mines Corp Pennsylvania Power & Light Co	8402080130 8402080130 8402210286 8402230163 8402020117	50-247 Q 50-247 Q 40-2259 40-2259 50-387 8
	8402070276 8402130277 8402140092 8402150359 8402160414	50-285 P 50-285 P 50-285 P 50-285 Q 50-285 P		8402030214 8402030231 8402030261 8402030267 8402030313	50-387 8 50-387 8 50-387 8 50-387 8 50-388 8
	6402220061 6402220168 6402220479 6402270171* 6402270366	50-285 R 50-285 O 50-285 P 50-285 O 50-285 O		8402030426 8402030426 8402060237 8402070176 8402070178	50-387 F 50-387 F 50-387 8 50-387 P 50-367 P
Oregon, State of	8402270368 8402010054* 8402070110 8402070112* 8402270043*	50-285 G CONTRACT State Prog State Prog 50-344 F		8402070200 8402070200 8402070243 8402070243 8402070254	50-367 F 50-367 F 50-367 P 50-367 P 50-368 E
Ossining, NY Pacific Air Products Co Pacific Gas & Electric Co	8402080161 8402070365 8402070373* 8402220188* 8401240481	50-247 F 50-280 8 50-280 S GAY99 50-275 E		8402070270 8402070270 8402070321 8402070349 8402070352	50-367 P 50-367 P 50-367 S 50-368 E 50-367 S
	8402020263 8402020264 8402020265* 8402020265* 8402020272*	50-275 R 50-275 E 50-275 R 50-275 R 50-275 R		8402070364 8402080242 8402130214 8402140204 8402140204	50-387 8 50-387 8 50-387 P 50-387 8 50-387 8
	8402020272* 8402020382 8402020385* 8402030258 8402030381*	50-275 R 50-275 F 50-275 F 50-275 E 50-275 Q		8402140452 8402140457* 8402150264 8402150264 8402150333	50-388 A 50-388 A 50-387 R 50-387 R 50-387 B
	8402060422 8402060422 8402060424 8402060424 8402070232	50-275 P 50-275 P 50-275 E 50-275 E 50-133 S		8402150366 8402170237 8402170237 8402220322 8402220456#	50-387 0 50-387 E 50-387 E 50-387 F 50-387 G
	8402070234 8402070234 8402070368 8402070370 8402070241	50-133 P 50-133 P 50-275 S 50-275 E 50-275 E		8402270077 8402270077 8402270186 8402270255 8402270261#	50-387 P 50-387 P 50-388 S 50-388 S 50-387 G
	8402090296 8402090296 8402090299 8402090345 8402090373	50-275 E 50-275 E 50-275 E 50-275 E 50-275 E		8402270342 8402270342 8402270349 8402270423* 8402270423*	50-387 P 50-388 B 50-387 Q 50-387 Q
	8402100001 8402100245 8402100451 8402130477 8402140141	50-275 E 50-275 B State Prog 50-275 B 50-275 G		8402270429 8402270429 8402280120 8402280227 8402280243	50-387 P 50-387 P 50-387 S 50-387 S 50-387 P

AUTHOR AFFILIATION	ACCESSION NUMBER	EUBJE	DRY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	
Pennsylvania, Commonwealth of,	8402280248* 8402280354 8402080229 8402060524* 8402080188	50~387 50~387 50~352	F G CT		8402170117 8402170143 8402210145 8402210145 8402210233	50-352 50-277 50-352 50-352 50-277	A R E E J
	8402080188 9402080170* 9402080170* 9402130253 9402130260		0		8402210233 8402210279 8402210335 8402210335 8402220034	50-277 50-277 50-277 50-277 50-277	ン ド リ リ リ リ リ リ
Peru. Gavt of Philadelphia Electric Co	8402130264* 8402140190 8402280463 8402090419* 8309070010*	50-352 50-352	D O SIGN		8402220088 8402220089 8402220116 8402220118* 8402220118*	50-352 50-352 50-352 50-352 50-352	9999
	84020202027 8402020277 8402020277 8402020288* 8402020288*	50-352 50-352 50-352 50-352 50-352	^ ^		8402220122* 8402220122* 8402220348* 8402220374* 8402230084	50-352 50-352 50-352 50-277 50-352	G G G
	8402020293* 8402020293* 8402020296* 8402020296* 8402020299*	50-352 50-352 50-352 50-352	A F K		8402230084 8402240138 8402240295* 8402270005 8402270005	50~352 50~277 50~352 50~352 50~352	A A E E
	8402020299% 8402020300 8402020300 8402020355 8402020358	50~352 50~352 50~352 50~278 50~352	8 6 K		8402270166 8402270166 8402270316 8402270316 8402270401	50-352 50-352 50-352 50-352 50-352	EEKKS
	8402020361* 8402030197 8402030197 8402030270* 8402030270*	50-278 50-352 50-352 50-352 50-352	G G G		8402270401 8402280328 8402280328 8402280335 8402280464*	50-352 50-352 50-352 50-352 50-353	9 9 9
	8402030275* 8402030277* 8402030277* 8402030277* 8402030432	50-352 50-352 50-352 50-352 50-277	0 0 0 8	Philadelphia Inquirer, Philadelphia, PA Philadelphia, PA	8402280479* 8402280479* 8402280489 8402090015 8402010204	50-352 50-352 70-2988 50-289 50-352	G G F Q
	8402030438 8402060057 8402060057 8402060113 8402060131	50-278 50-352 50-352 50-278 50-352	9 9 9		8402070327 8402070327 8402070331* 8402070331* 8402080139	50-352 50-352 50-352 50-352 50-352	0000
	8402060131 8402060219 8402060219 8402060254 8402060254	50-352 50-352 50-352 50-277 50-277	0 0 5 8		8402080139 8402080145* 8402080145* 8402080146* 8402080146*	50-352 50-352 50-352 50-352	0000
	8402070242 8402070242 8402070251* 8402070251* 8402070263	50-352 50-352 50-352 50-352 50-277	0 0 0		8402100140 8402140175 8402210277 8402220351 8402060482*	50-352 50-352 50-352 50-352 CONTRACT	9 9 9
	8402070282 8402070282 8402070286 8402070286 8402070287*	50-352 50-352 50-352 50-352 50-352	0 0 0	Pittsburgh, Univ of, Pittsburgh, PA Planning Research Corp	8402070262* 8402290479* 8402290479* 8402080020* 8402030368	50-443 50-320 50-320 FOIA 50-344	A G G
	8402070287* 8402070292* 8402070292* 8402070309* 8402070309*	50-352 50-352 50-352 50-352 50-352	0 0 0 0		8402030442 8402030448 8402070285 8402130181 8402130287	50-344 50-344 50-344 50-344 50-344	P P P P
	8402070312* 8402070312* 8402070317* 8402070317* 8402070322*	50-352 50-352 50-352 50-352 50-352	0 0 0 0		8402130318 8402130340 8402140214 8402170255 8402210137	50-344 50-344 50-344 50-344 50-344	F 5 6 9
	8402070322* 8402070325 8402080022 8402130223 8402140240	50-352 50-278 50-352 50-278 50-277	g B D P S		8402210237 8402220431 8402230217 8402270105* 8402280344	50~344 50~344 50~344 50~344 50~344	Ј Б О
	8402140321 8402150094 8402150547 8402150548* 8402160209	50-278 50-352 70-2988 70-2988 50-352	8 0 0	Power Authority of the State of New York	8402290122 8308050317* 8402020234 8402020327 8402030247	50-344 50-247 50-333 50-333	S 9 9
	8402160207 8402160238 8402160238 8402160264 8402170117	50-352 50-352 50-352 50-352 50-352	G G G A		8402030460 8402070096* 8402070158 8402070172* 8402070374*	50-286 50-286 50-333 50-286 50-333	9 0 0 0

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEO		AUTHOR AFFILIATION	ACCESSION NUMBER	SVBJEC CATEGO	
	8402080415 8402070154 8402100258 8402130065* 8402130234	50-333 50-247 50-333 50-333 50-333	P Q R Q F		8402010139 8402010159 8402020116 8402020146 8402020250	50-272 50-354 50-272 50-272 50-272	F A B B
	840213026B 8402130445* 8402130533* 8402150184 8402160336	50-333 50-333 50-286 50-333 50-333	V G F P G		8402020261 8402030177 8402030189 8402030198 8402030200	50-354 50-272 50-272 50-272 50-272	*****
	8402170113 8402210058 8402210107 8402220180 8402220405	50-286 50-286 50-333 50-286 50-333	F R P P S		8402030275 8402030323 8402030327 6402030332* 8402030333	50-272 50-311 50-354 50-272	9 8 F F 8
	8402230190 8402230196* 8402230199* 8402240094 8402270235	50-286 50-286 50-286 50-333 50-333	P P P S		84020303B7 8402040374 8402040380* 8402040383 8402070142	50-354 50-354 50-354 50-272 50-272	8 8 8 8
Power Engineering Society Professional Reactor Operator Society Project Management Corp Public Affairs Information, Inc	8402280495 8402240359 8402220084 8402020465* 8402030207*	REGGD FOIA 50-537 CONTRAC CONTRAC			8402070189 8402070217* 8402070249* 8402070253* 8402070326	50-311 50-272 50-311 50-311 50-354	8 0 0 A
Public Citizen Litigation Group Public Interest Research Group, New York	8402230404 8402240324 8402070161 8402070161 8402080130	FOIA FOIA 50-247 50-247 50-247	0 0 0		8402070371 8402070374* 8402070374* 8402080118 8402080124*	50-272 50-272 50-272 50-354 50-354	F F G
Public Service Co of Colorado	8402080130 8402080135 8402080173 8308170014* 8309200043*	50-247 50-247 50-247 50-267 50-267	0 0 0 8 8		8402080185 8402080189* 8402080271 8402080371 8402100201	50-354 50-354 50-354 50-272 50-272	K K S R
	8402010151 8402010157* 8402060129 8402140412 8402150148	50-267 50-267 50-267 50-267 50-267	ፑ ዩ የ የ		8402100204* 8402130176 8402130176 8402130276 8402130319	50-272 50-272 50-272 50-354 50-272	# F O P
	8402150204 8402170048 8402170133 8402210197 8402210212	50-247 50-267 50-267 50-267 50-267	5 Q Q R P		8402130326* 8402130394 8402130394 8402140068 8402150010	50-272 50-272 50-272 50-354 50-311	Р F Q В
	8402220048 8402280377 8402280379* 8402280383* 8402280385*	50-267 50-267 50-267 50-267 50-267	5 R R R		8402150234 8402210054 8402210140 8402210202 8402220115	50-272 50-272 50-311 50-354 50-354	S R R R
Public Service Co of Indiana, Inc	8402280389* 8402090349 8402270193* 8402010145 8402030235	50-267 50-456 50-546 50-443 50-443	R A E S S		8402220120* 8402220173 8402230002 8402230078 8402230078	50-354 50-272 50-354 50-354 50-354	S C K A
	8402030305 8402030305 9402030422 8402030422 8402040225	50-443 50-443 50-443 50-443 50-443	8 8 8 8		8402240072 8402280214* 8402280216* 8402280220* 8402280311	50-272 50-272 50-272 50-272 50-272	9 0 0 R
	8402070255 8402080400 8402090045* 8402130283 8402130283	50-443 50-443 50-443 50-443 60-443	A S R Q Q	Pullman, Inc Purdue Research Foundation Quadrex Corp Querytech, Inc	8402280312 8402150327* 8402140063* 8402140195* 8402070304	90-354 50-275 CONTRACT 50-266 ACRS	A B P
	8402130286* 8402130286* 8402130290* 8402130290* 8402140208	50-443 50-443 50-443 50-443 50-443	0 Q 0 A	Radiation Management Corp Radiation Measurement Systems, Inc Radiation Service Organization Reed College, Portland, OR Rehab Group, Inc	8402140411 8402170280 8402070203 8402280174 8402100454	40-7455 PR FOIA 50-288 FOIA	F
	840214020B 8402150363 8402150365* 8402210129 8402220482*	50-443 50-443 50-443 50-443 50-443	A G F G	Reuter-Stokes, Inc Rhode Island, State of Rio Algom, Ltd Robert L Cloud Associates, Inc	8402060480 8402030353 8402290014 8402070375 8402100007#	XPDRTLIC PR 40-8084 50-275 50-275	P E
Public Service Electric & Gas Co of New Jersey	8402270231 8402270233* 8402280083 8402280350 8305160003*	50-443 50-443 50-443 50-443 50-272	K K S G B	Robert Shaw Controls Co Rochester Gas & Electric Corp	8402210215 8402020255 8402040163 8402040169* 8402070138	GA999 50-244 50-244 50-244 50-244	9 9 9
	B401230422 B402010135 B402010135 B402010139	50-354 50-272 50-272 50-272	A F F		8402070380 8402100246 8402100252* 8402100256* 8402150128	50-244 50-244 50-244 50-244 50-244	# # # # #

AUTHDR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
-thbestos Co -chland Citizens for Safe Energy	8402170284 8402290109 8402290169 8402290283 8402090077	50-244 F 50-244 F 50-244 P 50-220 S 50-247 G	Seismic Gualification Utility Group Senate	8402220110 8402280567 8308180641* 8309150474* 8401110109*	50-443 G REVIEW ORP 50-392 U COMMISSION COMMISSION
cckland County, NY schwell International Corp schy Mountain Energy Co	8307060279* 8402100314 8402170294 8402010039 8402210467	50-247 H WASTE MGT WASTE MGT 40-8380 40-8768	Senate: Energy & Natural Resources	8402030487* 8402080067* 8402080115* 8402130267* 8402270058*	50-498 U 40-1341 40-1341 50-3 H FOIA
jjes & Gray	8402210470 8402230053* 8402230057* 8402230064* 8402070004*	40-8380 40-8452 40-8452 40-8452 50-293 G	Sensible Maine Power Shaw, Pittman, Potts & Trowbridge	8402270285* 8402220200* 8402220218* 8402220230* 8402010055	50-247 U 50-309 0 50-309 0 50-309 0 50-440 0
	8402130283 8402130286* 8402130286* 8402130270* 8402220200*	50-443 0 50-443 0 50-443 0 50-443 0 50-309 0		8402020227 8402020227 8402020230* 8402020230* 8402030170	50-400 0 50-400 0 50-400 0 50-400 0 50-289 0
owe Associates Levy, Inc.	8402220224* 6402220230* 8402280350 8402170230* 8402130089*	50-309		8402030175 8402030193 8402030197* 8402030289 8402040174	50-400 0 50-287 0 50-287 0 50-287 0 50-287 0
eramento Municipal Utility District	8402030252 8402030255 8402030355 8402060072 8402060231	50-312 Q 50-312 P 50-312 S 50-312 P 50-312 P		8402040213 8402070197 8402070201* 8402070233 8402070259	50-400 G 50-482 0 50-482 9 50-440 G 50-287 0
	8402060236# 8402070107 8402070209 8402090392 8402090392	50-312 P 50-312 V 50-312 P 50-312 F 50-312 F		8402080150 8402080308 8402090067 8402090125 8402090129#	50-289 Q FOIA 50-400 G 50-289 Q 50-289 Q
	8402070400* 8402070402* 8402070402* 8402070405* 8402070405*	50-312 F 50-312 F 50-312 F 50-312 F 50-312 F		8402070130 8402070137 8402070137 8402070144* 8402100142	50-289 0 50-289 0 50-482 0 50-482 0 50-289 0
	8402070407* 8402130437 8402140388 8402160141 8402220177	50-312 F 50-312 G 50-312 S 50-312 S 50-312 F		8402130179 8402130185 8402130190 8402130305 8402130307	50-482 Q 50-289 Q 50-289 Q 50-289 Q
)fe Power for Maine	8402220350 8402220378 8402230034 8402230206 8402130514#	50-312 R 50-312 F 50-312 S 50-312 S 50-307 H		8402150107 8402150150 8402150217 8402160201 8402160201	50-440 0 50-424 0 50-400 0 50-400 0
ilava, M E , Intervenor im Rayburn G&T, Inc. in Diego Gas & Electric Co.	8402070147 8402070144* 8402080148 8402020354*	50~482		8402160207* 8402160207* 8402160233 8402160233 8402170103	50-400 0 50-400 0 50-400 0 50-400 0
india Laboratories	8402020366* 8402020366* 8402010365 8402060336 8402100378*	50-361 F 50-361 F NUREG NUREG 50-275 P		8402210207 8402220074 8402220121 8402220133 8402230034	50-289 0 50-289 0 FDIA 50-289 0 50-440 0
	8402130512 8402210024 8402230378 8402240209* 8402270189*	XPORTLIC NUREG HOLA FOLA		8402230058 8402230076 8402230111 8402270467 8402280337	50-424 G 50-289 G 50-289 G 50-358 T 50-440 G
	8402270232* 8402270244* 8402270260* 8402280014 8402280123	FOIA FOIA FOIA NUREG NUREG	Sheffield, Univ of, Sheffield, UX Shelwell Services, Inc	8402280340 8402280343 8402280362 8402130562* 8402270142*	50-289 0 50-289 0 50-400 0 CONTRACT FDIA
ndvik Epecial Matals Corp undårs-Rog Developments, Ltd iton Nuclear Experimental Corp tence Applications, Inc	8402140605 8402170270 8402060180 8402030532* 8402060484	XPORTLIC XPORTLIC 50-144 I 50-387 F NUREO		8402270145* 8402270147* 8402270150* 8402270157* 8402270164*	FOIA FOIA FOIA FOIA FOIA
	8402090306 8402090318 8402090320 8402090330* 8402090487	50-269 P TOPREP TOPREP 50-230 F TOPREP	Shorekam Opponents Coalition Sterra Club	8402270200* 8402160245 8402080009 8402080152* 8402080166*	F01A 50-322 0 50-217 P 50-537 0 50-537 0
acoast Anti-Pollution League	8402090608 8402130087* 8402280682* 8402010471 8402140151	50-269 P CONTRACT CONTRACT 50-443 A 50-443 G	Sjerra Geophysics,Inc Simpson, J M Small Business Administration	8402070174* 8402070144* 8402060471* 8402160688* 8402170012*	50-206 P 50-482 G CDNTRACT CDNTRACT CONTRACT

AUTHÚR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	RY.	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	
	8402170016# 8402170268* 8402210351# 8402230293* 8402230295*	CONTRAC CONTRAC CONTRAC CONTRAC CONTRAC	T T T T		8402170347* 8402170347* 8402170348* 8402170348* 8402170350*	50-361 50-361 50-361 50-361 50-361	K K K K
Smith International, Inc Society of Nuclear Medicine South Carolina Electric & Gas Co	8402010448* 8402100444 8402170200 8402030418 8402060372	WASTE M State P FDIA 50-395 50-395			8402170350* 8402170351* 8402170351* 8402170352* 8402170352*	50-361 50-361 50-361 50-361 50-361	K K K K
	8402060430 8402060470 8402070210 8402070386 8402130272	50-395 50-395 50-395 50-395 50-395	F P S F R		8402170353* 8402170353* 8402170354* 8402170354* 8402170355*	50-361 50-361 50-361 50-361 50-361	K K K K
	8402140001 8402140235 8402150120 8402150179 8402220070	50-395 50-395 50-395 50-395 50-395	5 5 6 8		8402170355* 8402170357* 8402170357* 8402170358* 8402170358*	50-361 50-361 50-361 50-361 50-361	ц к к к
South Carolina, State of	8402220075 8402220227 8402240107 8402290174 8402020214	50-375 50-375 50-375 50-375 27-47	S S P P		8402170359* 8402170359* 8402170361* 8402170361* 8402170362*	50-361 50-361 50-361 50-361 50-361	н н н н
South Carolina, Univ of, Columbia, SC	8402060618* 8402140115 8402090013* 8402090040* 8402130275*	50-413 State Pi CONTRACT CONTRACT 50-375			8402170362* 8402170363* 8402170363* 8402170364* 8402170364*	50-361 50-361 50-361 50-361 50-361	K K K K
South Datota, State of	8402270478* 8402080063* 8402080074* 8402080085* 8402080214*	FDIA FOIA 40-1341 40-1341 40-1341			8402170365* 8402170365* 8402170366* 8402170366* 8402170367*	50-361 50-361 50-361 50-361 50-361	K K K
South Mississippi Electric Power Association Southern California Edison Co	8402100464* 8402230367* 8401030275 8401030277*	FOIA 50-414 50-361 50-361	P P P		8402170367* 8402170368* 8402170368* 8402170369* 8402170369*	50-361 50-361 50-361 50-361 50-361	K K K K
	8401040360 8402010136 8402020362 8402020362 8402020364*	50-362 50-361 50-361 50-361	5 F F F		8402170370* 8402170370* 8402170372* 8402170372* 8402170373*	50-361 50-361 50-361 50-361 50-361	K K K K
	6402020354* 6402020356* 6402020366* 6402030211 6402030271* 8402030273	50-341 50-341 50-341 50-204 50-206 50-341	F F P Q S		8402170373# 8402170375# 8402170375# 8402170376# 8402170376#	50-361 50-361 50-361 50-361 50-361	и к к к
	8402030364 8402030398 8402030420 8402030459 8402060248	50-361 50-362 50-361 50-362 50-361	8 8 8 8		8402170377* 8402170377* 8402170379* 8402170379* 8402170380*	50-361 50-361 50-361 50-361 50-361	K K K
	8402040361 8402070224 8402070064 8402070172 8402130166	50-362 50-206 50-206 50-206 50-362	F P P		8402170381* 8402170381* 8402170383* 8402170383*	50-361 50-361 50-361 50-361 50-361	K K K
	8402130169 8402130299 8402130333 8402130346 8402130387	50-362 50-362 50-361 50-206 50-361	\$ \$ \$		B402170384* B402170385* B402170385* B402170385* B402170388*	50-361 50-361 50-361 50-361 50-361	K K K
	8402130440 8402130509 8402140163 8402150218 8402150383	50-362 50-362 50-362 50-362 50-266	9 9 9		8402170388* 8402170387* 8402170387* 8402170390* 8402170390*	50-361 50-361 50-361 50-361 50-361	K K K
	8402130383 8402130384 8402170224 8402170252 8402170252 8402170338	50-341 50-204 50-341 50-341 50-361	г 9 F F K		8402170391* 8402170391* 8402170393* 8402170393* 8402170394*	50-341 50-361 50-361 50-361 50-361	X X X X
	8402170338 8402170339* 8402170339* 8402170341*	50-361 50-361 50-361 50-361	K K K K		8402170394* 8402170396* 8402170396* 8402170397* 8402170397*	50-361 50-361 50-361 50-361 50-361	К К К
	8402170344* 8402170344* 8402170344* 8402170345* 8402170345*	50-361 50-361 50-361 50-361	K K K		B402170399# B402170399# B402170400# B402170400# B402170402#	50-361 165-06 165-06 165-06 165-06	K K K

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE	CT DRY	AUTHÜR AFFILIATION	ACCESSION NUMBER	SUBJE CATEG	
	8402170402* 8402170403* 8402170403* 8402170404* 8402170404*	50-361 50-361 50-361 50-361 50-361	К К К К К		8104210566* 8104280035* 8204110307* 8402090019 8402090210*	FOIA FOIA	
	8402170407* 8402170407* 8402170408* 8402170408* 8402170409*	50-361 50-361 50-361 50-361 50-361	K K K K		8402090215* 8402090221* 8402090239* 8402090244* 8402090248*	FOIA FOIA FOIA	
	8402170409* 8402170411* 8402170411* 8402170412* 8402170412*	50-361 50-361 50-361 50-361 50-361	K K K K		8402090272* 8402090304* 8402090312* 8402090315* 8402090317*	FOIA FOIA FOIA FOIA	
	8402170413* 8402170413* 8402170414* 8402170414* 8402170415*	50-361 50-361 50-361 50-361 50-361	ж к к		8402090319* 8402090326* 8402090346* 8402090353*	FOIA FOIA FOIA FOIA	
	8402170415* 8402170416* 8402170416* 8402170418* 8402170418*	50-361 50-361 50-361 50-361 50-361	К К К К		8402090363* 8402090365* 8402090370* 8402090372* 8402090387*	FOIA FOIA FOIA FOIA	
	8402170419# 8402170419# 8402170420* 8402170420*	50-361 50-361 50-361 50-361	К К Ж	Standard Nuclear Consultants, Ltd Standardized Nuclear Unit Power Plant System	8402070373* 8402270246 8402010134	FOIA FOIA 50-482	A
	8402170421* 8402170421*	50-361 50-361	Х		8402010134 8402010134	50-482 50-482	A
	8402170422* 8402170422* 8402170423* 8402170423*	50-361 50-361 50-361 50-361	К К К К		8402010149* 8402010149* 8402010149* 8402010250 8402010250	50-482 50-482 50-482 50-482 50-482	A A A
	8402170424# 8402170424# 8402170426# 8402170426# 8402170427#	50-361 50-361 50-361 50-361 50-361	K K K K		8402010250 8402020259 8402020259 8402020257 8402020319	50-482 50-482 50-482 50-482 50-482	A A A E
	8402170427# 8402170432# 8402170432# 8402170433# 8402170433#	50-361 50-361 50-361 50-361 50-361	K K K K		8402020319 8402020319 8402030314 8402030314 8402030314	50~482 50~482 50~482 50~482 50~482	E A A
	8402170435# 8402170435# 8402170436# 8402170436# 8402170437#	50-361 50-361 50-361 50-361 50-361	K K K		8402030319+ 8402030319+ 8402030319+ 8402040384 8402040384	50-482 50-482 50-482 50-482 50-482	A A K K
	8402170437* 8402170441* 8402170441* 8402170442* 8402170442*	50-361 50-361 50-361 50-361 50-361	* * * * * *		8402060384 8402060387+ 8402060387+ 8402060387+ 8402060462	50-482 50-482 50-482 50-482 50-482	к к к
	8402170446* 8402170496* 8402170450* 8402170450* 8402210662	50-361 50-361 50-361 50-361 50-206	K K K R		8402070024 8402070026* 8402070026* 8402070026* 8402070114	50-482 50-482 50-482 50-482 50-482	E E E #
	8402210103 8402210244 8402210245 8402230148 8402240006	50-361 50-361 50-361 50-361 50-206	P 5 8 9 P		8402070114 8402070114 8402070159 8402070159 8402070159	50-482 50-482 50-482 50-482 50-482	F F A A
	8402240009* 8402280276 8402280413 8402290138 8402290154	50-204 50-204 50-341 50-204 50-206	P ' P S P		8402070204 8402070204 8402070204 8402070301 8402070301	50-482 50-482 50-482 50-482 50-482	8888
hwest Fabricating & Walding Co.	8402290180 8402010143*	50-204 GA999	Р		8402070301 8402080030	50-482 50-482	E
bs. of IU International Corp)	8402010173* 8402170003 8402170174	GA999 . 50-400 50-338	6 6		8402080030 8402080030 8402090273	50-482 50-482 50-482	E
twest Research and Information Center Louis Univ , St Louis, MD A. Huber Consultants, Inc	8402170279 8402170317 8402070295* 8402100454* 7905300623*	50-400 50-338 GA999 CONTRACT FOIA	8 8		8402090273 8402090273 8402100230 8402130225 8402130454	50-482 50-482 50-482 50-482 50-482	A G G S
	7907120678* 7910110337* 8102190624* 8104090747*	FOIA FOIA FOIA			8402130454 8402130454 8402160077 8402160077	50-482 50-482 50-482 50-482	8 9 9

AUTHOR APFILIATION	ACCESSION NUMBER	CATEGOR		AUTHOR AFFIL (AT LON	ACCESSION NUMBER	BUBJECT
	8402160077 8402170004 8402170004 8402170004 8402170124	50-482 50-482 50-482 50-482 50-482	0 E E E		8402150248 8402150248 8402150318 8402150318 8402150322	50-329 A 50-329 A 50-329 S 50-329 S 50-329 S
	8402170124 8402170124 8402170209 8402170209 8402170209	50-482 50-482 50-482 50-482 50-482	0 9 5 5		8402150330 8402150330 8402150331* 8402150338* 8402150338*	50-329 A 50-329 A 50-329 A 50-329 A
	8402170286 8402170286 8402170286 8402220062 8402220062	50-482 50-482 50-482 50-482 50-482	5 5 5 5 5		8402150354 8402150354 8402220184 8402220184 8402220567	50-327 8 50-327 8 50-327 8 50-327 8
	8402220062 8402270406 8402270406 8402270406 8402280258	50-482 50-482 50-482 50-482 50-482	S A A A		8402270100 8402270123 8402270315 8402270315 8402270437	50-327 8 50-327 9 50-327 9 50-329 8
Stanford Univ , Stanford, CA	8402280372 8402280372 8402280372 8402070527 8402070537	50-482 50-482 50-482 ACRS ACRS	A A A		8402270437 8402280321 8402280321 8402280334 8402280334	50-329 \$ 50-329 \$ 50-329 \$ 50-329 \$
State, Bept of. Bureau of Oceans & Intl Environ & Scientific Affairs	8402020443	XPORTL IC	;		8402280440 8402280440	50-327 S 50-327 S
Steel, Hector & Davis Stone & Webster Engineering Corp	8402130414 8402150500 8402140181 8401050255	XPORTL IC XPORTL IC 30-250 PR			8402280581 8402280581 8402280584	50-327 9 50-327 9 50-327 9
	9402130048 * 9402220217 *	50-412 50-302	C P	Structural & Earthquake Engineering Consultants	8402280584 8402170031*	50-329 8 CONTRACT
Stone & Webster, Inc	8402020125 8402020297 8402020297	50-329 50-329 50-329	H A A	Structural Mechanics Associates Suburban General Hosp , Norristown, PA Suffolk County, NY	8402160460* 8402280408* 8402030145	50-329 A 70-2077 50-322 g
	8402030191 8402030191 8402030291 8402030291 8402030296	50-329 50-329 50-329 50-329 50-329	A A A A		8402030148* 8402040185 8402060188* 8402070178 8402070264	50-352 0 50-352 T 50-352 G 50-352 G
	8402060058 8402060058 8402060230 8402060230 8402060230	50-329 50-329 50-329 50-329 50-329	A A A		8402070271* 8402100123 8402150113 8402150124 8402150135	50-322
	8402060244 8402060247 8402060247 8402060247 8402060276	50-329 50-329 50-329 50-329 50-327	A 9 8		8402150162 8402150171 8402150187 8402150193 8402160214	50-322 0 50-322 0 50-322 0 50-322 0
	8402060276 8402060365 8402060365 8402060461 8402060461	50-327 50-327 50-327 50-327 50-327	5 A A A	Sugarman & Denworth	8402160219 8402160223* 8402230097 8402280213 8402170461	50-322 0 50-322 0 50-322 0 50-322 A
	B402070140# B402070144# B402070148# B402070148# B402070155#	50-329 50-329 50-329 50-329 50-329	0 0 0 0		8402220113 8402230391 8402230395* 8402240275 8402240308	50-352 0 50-352 A 50-352 A 50-352 A 50-352 E
	8402070155* 8402070160* 8402070165* 8402070169* 8402070454*	50-327 50-327 50-327 50-327 50-327	G G G O	Sunflower Alliance Sweden, Govt of Systems Control, Inc TERA Corp	8402080053 8402020269 8401040412# 8401040416# 8402140194	50-440 0 XPORTLIC QA999 QA999 50-329 A
	8402080390 8402080390 8402130343 8402130343 8402130355	50-327 50-327 50-327 50-327 50-327	A R R S		8402210271 8402210271 8402210274* 8402210274* 8402240027	50-329 R 50-329 R 50-329 R 50-329 R 50-329 A
	8402130355 8402130366	50-329 50-329	s s	TMI-2 Technical Assistance & Advisory Group	8402240173	50-320 P
	8402130366 8402130420 8402130420	50-329 50-329 50-329	S A A	Technical Analysis Corp Technical Analysis Corp Technical Audit Associates, Inc	8402060471* 8402060539* 8402090002 8402070297	CONTRACT CONTRACT FOIA 50-397 P
	8402130425 8402130425 8402130429 8402130429 8402130463	50-329 50-329 50-329 50-329 50-329	A A R R S	Technical Information Project Technical Operations, Inc Technology for Energy Corp	8402150445 8402080179 8402140419 8402140622* 8402130057*	State Prog PR 71-9187 71-9187 FOLA
	8402130463 8402130466 8402130473 8402130473	50-329 50-329 50-329 50-329	8 A 8 9	Teknekron, Inc	8402130077# 8402130080# 8402030515	FOIA FOIA WASTE MOT

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJEC CATEGO		AUTHOR AFFILIAT)	ACCESSION NUMBER	SUBJECT	
iyne Wah Chang Albany essee Valley Authority	8402220358 8402140564 8401050474 8402010155 8402020222	NUREG XPORTL I 50-438 50-327 50-260	C S P S		8402140432 8402140451 8402150291 8402150291 8402150355	50-438 50-259 50-327 50-327 50-390	8 9 0
	8402030011 8402030011 8402030013 8402030188 8402030188	50-43B 50-43B 50-43B 50-390 50-390	ក្នុង នេះ		8402150355 8402150355 8402150355 8402150355 8402140048	50-370 50-370 50-370 50-370 50-370	G G G A
	8402030215 8402030226 8402030226 8402030269 8402030389	50-260 50-390 50-390 50-259 50-328	5 5 5 5 5 5		8402160087 8402160087 8402160277 8402160286* 8402160321	50-390 50-390 TOPREP TOPREP 50-327	F F
	8402030471 8402060205 8402060232 8402060232 8402060261	50-259 50-327 50-390 50-390 50-259	5 5 К К 0		8402170051 8402170051 8402170051 8402170112 8402170142	50-390 50-390 50-390 50-390 50-259	A A A S
	8402060382 8402060472 8402070206 8402070204 8402070204	50-259 50-259 50-259 50-259 50-259	F 5 P P		8402170152 8402170152 8402210071 8402210071 8402210110	50-438 50-438 50-239 50-259 50-327	A P P
	8402070211 8402070211 8402070302 8402080154 8402080197	50-438 50-438 50-259 50-260 50-438	A A R S S		8402210148 8402210148 8402210198 8402210278 8402210278	50-327 50-327 50-259 50-259 50-259	F 93 F F
	8402080197 8402080200 8402080206* 8402080220 8402080226	50~438 50~438 40~1341 50~327 50~438	8 8 6		8402210278 8402210278 8402210278 8402210301 8402210301	50-259 50-259 50-259 50-259 50-259	F F F F
	8402080224 8402080287 8402090117* 8402090240 8402090325	50-438 50-260 50-438 70-291 0 50-390	C S A		8402210301 8402220307 8402220307 8402220314 8402220314	50-257 50-370 50-390 50-390 50-390	F 9 9 9
	8402100212 8402100214 8402100214 8402130279 8402130279	50-327 50-390 50-390 50-327 50-327	9 F P P		8402220031 8402220031 8402220084 8402222096 8402220096	50-438 50-438 50-537 50-327 50-327	8 0 F F
	8402130282* 8402130282* 8402130316 8402130316 8402130316	50-327 50-327 50-259 50-259 50-259	P F F F		8402220128 8402220128 8402220161 8402220175 8402220175	50-438 50-438 50-327 50-438 50-438	S S S S
	8402130316 8402130316 8402130316 8402130380 8402130397	50-257 50-257 50-259 50-327 50-438	F F F S		8402220219 8402220315 8402220315 8402220428 8402220477	50-391 50-438 50-438 50-327 50-296	5 5 5 F 5
	8402130434 8402130470 8402140010 8402140071 8402140071	50-259 50-259 50-327 50-438 50-438	9 F 8 9		8402230207 8402230207 8402230223 8402230233* 8402240147	50-390 50-390 50-438 50-438 50-259	F Q Q S
	8402140104* 8402140112* 8402140132* 8402140166 8402140191	50-259 50-259 50-259 50-259 50-259	0 0 0 0 5		8402240157 8402270020 8402270020 8402270087 8402270087	50-259 50-438 50-438 50-438 50-438	55 55 55 55 55 55 55 55 55 55 55 55 55
	8402140195 8402140206 8402140218 8402140250* 8402140252*	50-370 50-327 50-257 50-327 50-257	A 8 0 0		8402270171 8402270171 8402270171 8402270191 8402270357	50-390 50-390 50-390 50-390 50-439	56565
	8402140257 8402140276* 8402140331 8402140351 8402140351	50-260 50-257 50-327 50-438 50-438	9 0 5 9		8402270357 8402270376 8402270373 8402270375 8402270375	50-438 50-259 50-438 50-438 50-438	99999
	8402140370 8402140371 8402140371 8402140391 8402140397	50-391 50-390 50-390 50-328 50-390	ទេជ ១ ជ		8402270403 8402270403 8402270411 8402280013 8402280022	50-438 50-438 50-257 50-276 50-257	S S S S G
	8402140397 8402140415 8402140424* 8402140426 8402140432	50-390 50-259 50-259 50-260 50-438	F S O S S		8402280022 8402280185 8402280185 8402280224 8402280259	50-257 50-327 50-327 50-259 50-390	0 P P E

AUTHOR AFFILIATION	ACCESSION MAEMUN	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8402280259	50-390 E 50-327 P	Texas. Univ of, Austin, TX	8402020037* 8402170289	WASTE MOT
	8402280361* 8402280361* 8402280367 8402280368	50-327 P 50-327 P 50-327 S 50-327 P	Texas, Univ of, San Antonio, TX Thorek Hosp & Medical Center Chicago, IL	8402280494	WASTE MOT PRM FOIA FOIA
	8402280368 8402280441 8402280451 8402280498* 8402280498*	50-327 P 50-328 S 50-327 S 50-239 G 50-259 G	Three Mile Island Alert	8402060025 8402220260 8402220357 8402230087 8402280215	50~287 P 50~287 9 50~287 9 50~287 9 50~287 0
	8402280504* 8402280504* 8402280528* 8402280530* 8402280556	50-259	Tokyo Electric Power Co , Inc	8402140337* 8402140349* 8402270518* 8402270520* 8402270525*	GA777 GA779 FOIA FOIA FOIA
Tennessee, State of Texas A&M Univ , College Station, TX	8402280556 8402020155 8402040589* 8311030099 8402070348	SO-390 S WASTE MGT CONTRACT 50-128 S 50-128 F	Toleda Edison Co	8402030242 8402030311 8402040090 8402040354 8402060367*	50-346 P 50-346 P TOPREP 50-346 F 50-346 Q
Texas Utilities Generating Co	8402270357* 8402010209 8402010209 8402030160 8402030160	50-128 S 50-445 G 50-445 G 50-445 G 50-445 G		8402130308 8402130405 8402140105 8402140385 8402150207	50-346 B 50-346 B 50-346 F 50-346 P 50-346 P
	8402030145* 8402030145* 8402040138 8402040138 8402070008*	50-445 G 50-445 G 50-445 G 50-445 G 50-445 G		8402150217# 8402150223# 8402170151 8402220019 8402220117	50-346 P 50-346 P 50-346 F 50-346 8 50-346 F
	8402070088 8402070227 8402100115* 8402100115* 8402100184	50-445 A 50-445 G 50-445 G 50-445 G 50-445 T		8402220334 8402230073 8402240014 8402240056 8402240152	50-346 R 50-346 R 50-346 P 50-346 P 50-346 8
	8402100184 8402100190* 8402100190* 8402100193* 8402100193*	50-445 T 50-445 T 50-445 I 50-445 T 50-445 T	Toshiba Corp Transamerica Delaval, Inc	8402290115 8402290120* 8402270518* 8402270520* 8312200154*	50-346 P 50-346 P FOIA FOIA 50-312 P
	8402100455 8402130156 8402130156 8402140333 8402160203	70-2932 50-445 A 50-445 A 50-446 S 50-445 F	Transnuclear, Inc	8402220530 8402010341 8402010458 8402030123 8402090543	50-204 9 XPORTLIC XPORTLIC XPORTLIC XPORTLIC
	8402170119 8402170119 8402170282 8402170282 8402210220	50-445 G 50-445 G 50-445 S 50-445 S 50-445 G	Treasure Coast Regional Planning Council,FL	8402100392 8402130408* 8402140601 8402140610 8402280388	XPORTLIC XPORTLIC XPORTLIC XPORTLIC 50-320 P
	8402210220 8402210340 8402210340 8402220033 8402220033	50-445 9 50-445 9 50-445 9 50-445 8 50-445 8	Troutman, Sanders, Lockerman & Ashmore Tuskeges Institute, Tuskegee, AL U B Ecology, Inc (formerly Nuclear Engineering, Inc)	8402150227 8402210044* 8402020208	50-424 Q CONTRACT 27-48
	8402220171 8402220171 8402220420 8402220420 8402220443	50-445 8 50-445 8 50-445 8 50-445 8 50-445 K	U S - Organization Chart Bervice, Inc Underwriters Laboratory Union Carbide Corp	8402220008 8402080392 8402100216* 8402270373* 8402030345	27-39 FOIA 50-390 F 50-285 G PR
	8402220443 8402220545 8402220545 8402230009 8402230009	50-445 X 50-445 B 50-445 B 50-445 A 50-445 A		8402130423 8402150025 8402210284 8402210423 8402210424* 8402230074	71-6038 71-6038 40-297 40-297 40-299
	8402230041 8402230061 8402230085 8402230085 8402230122	50-445 A 50-445 G 50-445 G 50-445 G 50-445 K		8402230151 8402230157* 8402230258 8402230264 8402270445	40-297 40-299 40-299 40-299 70-687
	8402240149 8402240149 8402280268 8402280268 8402280493	50-445 E 50-445 B 50-445 B 50-445 B 50-445 B	Union Electric Ca	8402270453* 8401060174* 8401060176* 8402030411 8402060412 8402060413*	70-483 F 50-483 F 50-483 F 50-483 A 50-483 A
Texas, State of	8402020054 8402020080 8402020189 8402030512	WASTE MOT WASTE MOT WASTE MOT WASTE MOT		8402070240 8402130163 8402130167* 8402130171*	50-483 F 50-483 F 50-483 F 50-483 F
	8402050140 8402070108* 8402140065 8402170298 8402290447	WASTE MGT CONTRACT 50-445 G WASTE MGT WASTE MGT		8402130178* 8402130178* 8402130370* 8402130372*	50-483 F 50-483 F 50-483 G 50-493 G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	RY	ROHTUA ROJTAJJISAA	ACCESSION NUMBER	SUBJE CATEG	DRY
	8402170141* 8402220035 8402220039* 8402220041* 8402220342*	50-482 50-483 50-483 50-483 50-483	0 F F G		8402 40405 8402 50020 8402 50020 8402 50022 8402 50022	50-338 50-280 50-280 50-280	В Р Р
iion Minerals	8402220920* 8402230140 8402240048 8402270385 8402210480	50-483 50-483 50-483 50-483 40-9584	F A A		8402150173 8402150267 8402150267 8402150279* 8402150279*		P P P
ilon of Concerned Scientists	8402010064 8402010399 8402070020 8402070267 8402080079	50-207 50-250 FOIA 50-247 FOIA	0 9 0		8402210095 8402210095 8402220009 8402220146 8402220155*	50-280 50-280 50-338 50-281 50-281	ខ្លួ
	8402080380 8402130011 8402130248 8402170470 8402210175	FD1A F01A 50-267 F01A 50-269	G G		8402220140* 8402220144* 8402220145* 940220208 8402220435	50~281 50~281 50~280 50~280 50~280	5 5 5 5 6
ited Engineers & Constructors, Inc	8402210181* 8402220153 8402240172 8402240205 8402070344	50-289 50-289 FOIA FOIA 50-443	0 0		8402230143 8402240010 8402240012 8402240012 8402240012	50-280 50-280 50-338 50-338 50-280	P F F
ted Nuclear Corp	8402070037* 8402070042* 8402030436* 8402170304 8402020424*	50-443 50-443 70-371 NUREO WASTE M	R R DT		840224002 8402240084 8402240084 8402270083 8402270083	50-280 50-338 50-338 50-338 50-280	F F S P
h, Univ of, Salt Lake City, UT Lity Esfety Classification Group	8402060194 8402170290 8402220276* 8402220479 8402020225	WASTE M WASTE M 50-72 50-407 50-322			8402280214 8402280214 8402280214 8402280274 84022804264	50-280 50-280 50-280 50-336 50-280	p P S G
sont Yankee Nuclear Power Corp	8402080054 8402090153 8402010282 8402010285* 8402070378	50-322 50-322 50-271 50-271 50-271	0 P B		6402280453 6402280472* 8402280483 8402280483 8402280505	50-280 50-339 50-338 50-338 50-280	F G P G
	8402130424 8402150160 8402150166* 8402150278 8402150280*	71-9151 50-271 50-271 50-271 50-271	부 무 무	Virginia Polytechnic Institu Univ , Blacksburg, VA	8402280517 8402280517 84022805125 8402280525 te & State 8402130345	50-280 50-280 50-280 50-280 50-124	P P P S
	8402150283 8402150286* 8402150267 8402170267 8402210086	50-271 50-271 50-271 50-271 50-271	P F R F	Virginia, Commonwealth of, Virginia, Univ of, Charlotte	8402030354 8402030354 8402100440 840210369* 8402210369* 8402280275*	PR CONTRACT State Pr CONTRACT 50-62	rog
ont, State of rans Admin. Hosp , Los Angeles, CA	8402240124 8402280054 8402060063* 8402060534* 8402280509	50-271 50-271 FOIA CONTRACT	P P	Wallace, Hilburn, Clayton, Ca Forster, Ltd Washington Public Power Suppl		FOIA 50-397 50-397 50-397 50-397	A A A
nict. Inc Inla Electric & Power Co	8402060520* 8402030444 8402030470 8402030470 8402060246	CONTRACT 50~338 50~338 50~338 50~280	1 6 6 7		8401170072* 8401170092* 8402020141 8402030262* 8402030357	50-397 50-397 50-397 50-397 50-397	A A R G
	8402070382 8402080062 8402080062 8402080065* 8402080065*	50-338 50-338 50-338 50-238	1 1 1 1 1		8402030364* 8402030371* 8402030378* 8402030380* 8402030386*	50-397 50-397 50-397 50-397 50-397	8 8 8 8
	8402080169 8402080169 8402090152* 8402100183 8402100183	50-280 50-280 50-280 50-280 50-280	다 다 다 다		8402030372* 8402030375* 8402030401* 8402080057 84020800430	50-397 50-397 50-397 50-397 50-397	8 9 9
	6402100163 6402100203 6402100203 6402130351 6402130351	50~260 50~260 50~260 50~260 50~260	ም F P P		8402100217 8402130002 8402130145 8402130442 8402140098	50-460 50-397 50-397 50-308 50-305	8 8 8
	8402130356* 8402130356* 8402140186 8402140234 8402140236	50-280 50-280 50-280 50-280	P 8 8 8		8402160377 8402160417 8402160447 9402160447	50-397 50-397 50-397 50-397	9 P P
	8402140297 8402140383 8402140383 8402140401	50-338 50-280 50-280 50-280	9 P 9				

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8402220512 8402230225	50-397 S 50-397 F	Westinghouse Operating Plants Owners Group	8402290094	TOPREP
	8402230227# 8402230232# 8402290111	50-397 F 50-397 F 50-397 S	Weston Geophysical Corp Wharton, R J Whicher, J M Williams & Associates	8307010075* 8402030441 8402080131 8402040558*	50-309 P 50-361 P 50-454 G CONTRACT
Washington Univ , St Louis, MD Washington, State of	8402290125 8402290131 8402270293 8402140034* 8402010043*	50-397 S 50-397 S 50-397 S CONTRACT CONTRACT	Wilson Hill Associates, Inc Wilson, R Wisconsin Electric Power Co	8402170045* 8402160488* 8402210351* 8402210115	CONTRACT CONTRACT CONTRACT 50-400 9 50-266 F
	8402020103# 8402030493 8402080126 8402150149 8402150544	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT		8402070116 8402070116 8402070186 8402070186 8402070186	50-266 F 50-266 F 50-266 P 50-266 P
Washington, Univ of Seattle, WA Water, Waste & Land, Inc West Branch Conservation Association	8402170277 8402220380 8402060443 8402230272* 8402080184	WASTE MGT 50-443 H 50-139 R CONTRACT 50-247 G		8402080194 8402080199* 8402080199* 8402100222 8402100222	50~266 P 50~266 P 50~266 P 50~266 F 50~266 F
Western Environmental Services & Testing Western Interstate Nuclear Board Western Nuclear, Inc. (subs. of Phelps	8402210320* 8402210323* 8402210067 8402220097	40-6659 40-6659 Misc 40-8684		8402100225* 8402100225* 8402100234*	50-266 F 50-266 F 50-266 F
Dodge Corp) Western Water Consultants, Inc	8402010347*	E448-04		8402130177 8402130177	50-266 P 50-266 P
Westinghouse Electric Corp	8402010032 8402010097* 8402010162* 8402010295 8402010297	XPORTLIC XPORTLIC 50-327 P XPORTLIC XPORTLIC		8402130187* 8402130187* 8402140227 8402140227 8402140239	50-266 P 50-266 P 50-266 R 50-266 R 50-266 Q
	8402030367 8402030457* 8402070009 8402070265 8402070508	XPORTLIC 50-287 R 40-8502 NUREQ 70-1151		8402140239 8402140464* 8402140464* 8402150261 8402160181	50~266 Q 50~266 Q 50~266 Q 50~264 P 50~266 P
	8402070285+ 8402100017 8402100396 8402130043+ 8402130363+	50-482 A 70-1151 XPORTLIC FQIA XPORTLIC		8402160181 8402160188* 8402160188* 8402210120 8402280433	50-266 P 50-266 P 50-266 P 50-266 V 50-301 G
	8402140080 * 8402140543 8402140594 8402140595 8402140598	GA999 XPORTLIC XPORTLIC XPORTLIC XPORTLIC	Wisconsin Public Service Corp	8402030374 8402040460 8402070223 8402070279 8402070329	50-305 B 50-305 P 50-305 V 50-305 P 50-305 F
	8402160487 8402160489* 8402160489* 8402160490* 8402160491*	TOPREP TOPREP TOPREP TOPREP TOPREP		8402070335* 8402070339* 8402070341 8402070346* 8402080228	50-305 F 50-305 F 50-305 G 50-305 F 50-305 P
	8402160492* 8402160493* 8402160494* 8402160495* 8402160497*	TOPREP TOPREP TOPREP TOPREP TOPREP		8402080231* 8402080237* 8402140455 8402150230 8402220442	50-305 P 50-305 F 50-305 F 50-305 P 50-305 P
	8402160500# 8402160503# 8402160505# 8402160508# 8402160507#	TOPREP TOPREP TOPREP TOPREP TOPREP	Wisconsin, State of	8402270194 8402270202* 8402270257* 8402280210 8402010328*	50-305 P 50-305 P 50-305 Q 50-305 P CONTRACT
	8402160510# 8402160512# 8402160514# 8402160516# 8402160518#	TOPREP TOPREP TOPREP TOPREP TOPREP	Wisconsin, Univ of, Green Bay, WI Wisconsin, Univ of, Madison, WI Wiss, Janney, Elstner & Associates, Inc.	8402030232 8402070324 8402030082* 8402090491 8402080385*	WASTE HOT WASTE HOT CONTRACT ACRE 50-237 G
	8402160519# 8402160525* 8402160527* 8402160529* 8402160532*	TOPREP TOPREP TOPREP TOPREP TOPREP		8402080374* 8402080374* 8402080374* 8402080374*	50-237
	8402160535* 8402160535* 8402160539* 8402170135* 8402170141*	TOPREP TOPREP TOPREP 50-482 0 50-482 0		8402080401 * 8402080401 * 8402080401 * 8402080401 *	50-237 0 50-237 0 50-237 0 50-237 0 50-237 0
	8402170342 8402210035 8402210208 8402220620 8402220623	XPORTLIC TOPREP GA999 XPORTLIC XPORTLIC	Wolfbein, 8.i. Worsham, Forsythe & Bampels Wyoming Mineral Corp Wyoming, State of	8402080407* 8402040547* 8402230085 8402030043 8402010008	50-237 @ CONTRACT 50-445 9 40-8585 40-8786
	8402240360* 8402280535 8402280546* 8402290172*	XPORTLIC TOPREP TOPREP 50-244 P	Yakima Indian Nation	8402170445 8402170448 8402170451 8402030239	40-8584 40-4422 40-8783 Waste Mgt

AUTHOR	ACCESSION	SUBJECT	
AFFILIATION	NUMBER	CATEGORY	
**	8402030243*	WASTE MOT	_
	8402010145		s
Yanhee Atomic Electric Co	B402030235		9
	8402030257	50-29	5
	B402030277	50-443	5
	P405070 302	20-11-13	n
	8402030305	50-443	s
	8402030422		ŝ
	8402030422		s
	8402060068		P
	8402060225		s
			-
	8402060252	50-29	Р
	8402070255	50-443	A
	8402070370		F
	8402080400		9
	8402140208		۸
	8402150363	50~443	알
	8402150365*	50-443	Q
	8402160453	50-29	P
	8402160455*	50-29	Р
	8402210029	50-29	Ρ
	8402210129		F
	8402220186		F
	8402220283*		G
	8402220482*		a
	8402240110	50-27	b,
			_
	B402240110		P
	8402240110		P
	8402240111#		Р
	8402240111*		P
	8402240111*	50-29	þ
	8402240137	50-29	Р
	8402240140*		P.
	8402240143#		þ
	8402270397		8
	8402280043		ņ
	0102200010	30-E7	•
	8402280171*	50-27	0
rankton Daily Press & Dakotan, Yankton,	8402270559	FOIA	
5D			
Tech Co	8402100012#	FOIA	
14 2-	8402100030*	FOIA	
	8402100033*	FOIA	
	#402100034#	FOIA	
lupualt, L A	B402170245*	CONTRACT	

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of Information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this Index Indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT
	03101501001	50-287 P		EGG-EA-6432 DRFT	6402130457#	50~335 I	P GL-82-16
00B R01	8212150120* 8304130440*	50-269 P		EACY-CMSN-603	8402080032		P -
008 RO2 6854-31	B402290078*	50-373 F		EPR! NP-3400	8402140195*	,	p p
60-402	8402100042*	50-373 P		IE-123	8402140516= 8402140520=		P NRC-1E-80/81 P NRC-1E-80/81
82-7P6-EMVTL-R2	8402290172*	50-244 P		IE-123 ROI	8405140550=	DO- EU/	. Mich . C doing
	0400000444	RES		LA-UR-83-3162	840210041B		P
6402080461	6402080461 6402090407*	50-312 F		LAC-TR-123	8402060432*		F / *=
66-1126639~00 66-1127102-00	8402090410*	30-312 F		LAC-TR-124	8402160295*		P WP-6 17 F
PINF-IAFOI ROD	8/102080129*	50-520 R		LTS-1000-34 R01 M37328 R00	8402220412* 8402020366*		F
91HF-1CH01 R00	8402080095*	50-528 R		M37358 K00	B-OEOEDDGB-	ub	•
	8402080107*	50~52B R		NEDO-22243-1	8402010297#		P DRF E52-000012
9 F-1ED01 RG0 9 F-1RC01 RG0	6402080123*	50-528 R		NUREQ-0020 VO7 N11	8402060291	NUREG	
914F~1RCOR ROD	8402080111#	50-528 R		NUREG-0020 VO7 N12	8402210078 8402170320	NUREO NUREO	
PINF-18COL ROL	8402080071*	50~528 R		NUREG-0040 VO7 N04 NUREG-0540 VO5 N11	8402210016	NUREG	
91HF-15F02 ROO	B4020B0077*	50~52B A	18078/09788	MOREG-0540 405 1411	DIVELLOUID		
	8402080088*	50-528 R	17978/09780	NUREG-0580 V12 N12	8402100442	NUREG	
91HF-18F03 R00 DR 07	8402080101*		16248/09768	NUREG-0713 DRFT	8402230413#	FOIA NUREO	
91HF-18101 ROO	84020B0082*	50-528 R		NUREG-0748 VO3 N12	8402960497 8402170121	NUREG	
92HF-18V01 R00	8402080116#	50-528 R		NUREG-0750 VIA 001 NUREG-0750 VIA 802	8402170060	NUREO	
72HF-12Z01 ROO	8402080136*	50~52B R	DN-1821B/0959B	Moved-0320 Ato Des	010211.0000		
	8402080119#	50-528 R		NURE9-0847 SO2	8402100502		E E
93HF-1MAO5 ROO AEOP/T340	8402090571#	50-366 E		NUREG-0887 604	8402240381	50-440 NUREQ	E.
BAN-10156	8402230105*	TOPREP		NUREO-0940 VOR NO4	8402210028 8402210188	NUREG	
BAH-1474 RO⊇	8402010063#	TOPREP		NUREG-1040 NUREG-1040 ERR	6402170514	NUREO	
BAH-1760	8301250628*	50-289 F	QPUN-TDR-QO7	MANTA-10-10 Citie	_,		
	6304250272*	50-289 F	GPUN-TDR-007	NUREG-1045	8402170517	NUREG	
BAH-1760 RO1 BAN-1783 RO1	8402290132*	50~346 F		NUREG-1046 DRFT	8402240373 8402130612	NUREG NUREG	
BNL-04243	8310050275*	50-321 F		NUREG-1050 DRFT NUREG/BR-0051 V05 N4	840217 051 3	NUREO	
BNL-04243	8310050311#	50-27B F		NUREG/BR-0057 ROI	8402240271	NUREO	
BFC-01-300-1 VO1 R00	8402230101*	50-354 4	1	MONEAL DOG . 1101			
BPC-01-300-2 V02 R00	8402230108*	50-354 4		NUREG/BR-0075	8402150474	NUREG 40-1341	PNL-3784
86C-01-300-5 A05 KOO	8402230113*	50-354 4		NUREG/CP-0021 DRFT	8402080180* 8402100477	NURES	FIRE OF DA
BPC-01-300-4 VO4 R00	8402230116*	50~354 /	1	NUMEG/CR-2000 VORNIS	8402060529	NUREG	DRNL/NC18-200
BPC-01-300-5 V05 R00	8402230120*	50-354 /		NUREG/CR-2210	8402060341	NUREO	
BPC-01-300-6 V06 R00	8402230126*	50~354	•	144111111111111111111111111111111111111			nu skinca ki sad
	8402220496#	50-470 E	:	NUREO/CR-2721	8402240378	NUREO Nureo	BNL-NUREG-51593 SAND62-1179
CEN-593(A) -Nb	8402010433*	50~526		NUREO/CR-2812	8402230378 8402050484	NUREO	ENL-NUREO-51559
CEN-264(V)-NP CEN-267(V)-NP	B402060247*	50-52日		NUREQ/CR-2615 NUREG/CR-3056	8402170439	NUREO	DRNL/CBD/TH-197
CEN-275(C)-NP	8402240065#	50-362 /		NUREG/CR-3057	8402170417	NUREO	ORNL-5936
COM-71-020 ROO	8402080045*	20-572 (ł	Manage			
	8402080040*	50-265 (CDM075 0200	NUREG/CR-3127	8402270207 8402010111	NUREG NUREG	LA-9929-M
COM-75-001 RO2	8402220541*			NUREO/CR-3242	8402280123	NUREO	BAND83-1171
CPL-13-104 RO1 DCP-HD-2003	8402210191*			NUREG/CR-3327 VO3 NUREG/CR-3351	8402040334	NUREO	EANDB2-2933
DET-04-028-1 ROL	B402270076#	50-341	\	NUREO/CR-3331 NUREO/CR-3408 ERR	8402010302	NUREO	PNL~4788
DET-04-028-1A ROD	840227009B *	50-341	1	Manney on Title Time			
41 5 521	8402270103*	50-341	4	NUPEG/CR-3412	8402280014 8402210021	NURE9 50-295	BANDB3-1482 P UCRL-53483
DET-04-020-2 R01	8402270105*		Š	NUREG/CR-3428	8402060339	NUREO	ANL-83-64
DET-04-028-3 R01 DET-20-015-5 R01	8402270109*	50-341	Ý	NUREG/CR-3435 NUREG/CR-3444 VOI	8402170494	NURED	BNL-NUREG-51699
EEG-EA-4360	8402150538*	50-220	TAG 43042	NUREG/CR-3448	8402170498	NUREO	LA-9853-HS
EGG-EA-6202 DRFT	8402090316	50-261	•		04000000CC	NUREO	E09-2272
and constitution	B402090310	50-259	1	HUREG/CP-3441	9402030099 8402040333	NUREO	UCRL-53487
EGG-EA-6296 DRFT EGG-EA-6297 DRFT	B402090324		•	NUREG/CR-3477 NUREG/CR-3478	8402130117	NUREO	UCRL-53488
EGG-EA-6353	8402100421	50-259	3	NUREG/CR-3482	8402010115	NUREO	DRNL-4024
EGG-EA-6359	8402100352*		TAC 43020	NUREG/CR-3483	8402210019	NUREG	UCRL-53490
EGG-EA-6430	8402010279*	90-33B	> GF-85-19	*********			

REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	
NUREG/CR-3484 NUREG/CR-3491 NUREG/CR-3492 VO1 NUREG/CR-3496	8402210024 8402210073 8402060457 8402210026	NUREG NUREG NUREG NUREG	SAND83-1916 ORNL-5934 BNL-NUREG-51712
NUREG/CR-3512 NUREG/CR-3522 VO1 NUREG/CR-3522 VO2 NUREG/CR-3530 NUREG/CR-3531 NUREG/CR-3534	8402260010 8402010368 8402010313 8402170430 8402170503 8402040452		ENICO-1137 LA-9910-MS VO1 LA-9910-MS-VO2 BNL-NUREG-51722 BNL-NUREG-51723 UCRL-53492
NUREG/CR-3543 NUREG/CR-3550 NUREG/CR-3553 NUREG/CR-3554 NUREG/CR-3561	8402060478 8402170304 8402010274 8402210013 8402270213	NUREG NUREG NUREG NUREG NUREG	DRNL/NS1C-214 ANL/EES-TM-233 PNL-4773 PNL-4695
NUREG/CR-3562 NUREG/CR-3563 NUREG/CR-3579 NUREG/CR-3580 NUREG/CR-3584	8402010373 8402060343 8402170311 8402170308 8402240233	NUREG NUREG NUREG NUREG NUREG	PNL-4629 PNL-4908 PNL-3955 PNL-4692
NUREG/CR-3585 NUREG/CR-3598 NUREG/CR-3614 NUREG/CR-3616 NUREG/CR-3636	8402280004 8402280114 8402220099 8402010365 8402220358	NUREG NUREG NUREG NUREG NUREG	ORNL-6023 BNL-NUREG-51736 ARL-124-83/M39F
GRNL/NB1-176 PA 82-196 ROO PLO-0300 PNL-4608-2 RIL-136	8402080418* 8402160117* 8402070262* 8402080089* 8310270388	50-336 Q 50-443 A	62-196-247GP
RIL-138 SA/T38-18 SAI 1-245-08-492-00 SAI-1-245-08-492-01 SAI-184-351-48	8402090264 8402080160* 8402090487 8402090318 8402090330*	TOPREP TOPREP	
SAI-186-351-73 SALT 91P-2 0 DRFT SAND79-0095 SAR-VEPCO-005 BECY 83-318	8402030532* 8402210380* 8402270187* 8402080181* 8402010474*	WASTE MOT FOIA 50-280 F	
SECY-81-131 SECY-82-01&D SECY-82-049 SECY-82-0&1 SECY-82-113A	8204160195* 8402270375* 8402270380* 8402270384* 8205060001*	50-287 P 50-498 A FOIA	
SECY-82-140 SECY-82-456 SECY-83-045 SECY-83-079 SECY-83-202	8402270294* 8211290127* 8402130182* 8402080408 8402070032*	FOIA 50-526 A SECY	
8ECY-83-228A 8ECY-83-240 8ECY-83-261 8ECY-83-271 8ECY-83-288	8402230432* 8402230434* 8402230434* 8307200092* 8307270206	50-322 0 50-309 0	DD-83-03
8ECY-83-292 SECY-83-305 SECY-83-304 SECY-83-307 8ECY-83-333	8308100453* 8402130538* 8402130544* 8402130549* 8308240177*	50-267 P	
SECY-83-363 SECY-83-404 SECY-83-443 SECY-83-4578 SECY-83-457C	8309120090* 8402240200* 8402010453* 8402210280* 8402210282*	50-269 F 50-289 P 50-250 P 50-275 P 50-275 P	AL AB-724
SECY-84-003 BECY-84-009 SECY-84-009A SECY-84-010 SGI-R-84-103	8402030385 8402230344 8402230347 8402030047 8402090174*	50-275 P BECY 50-247 B 50-289 P 50-206 P	
SMA 13701 058003 V07 TDR 503 R00 TER-C5506-257 TER-C5506-316 TER-C5506-327	8402160460* 8402220273* 8307290075* 8301170355* 8307290297*	50-219 P 50-259 G 50-298 P	TAC 07939
TER-C5506-392 TER-C5506-418 TR-006 R01 TUFF STP-2 O DRFT TVA-TR75-1A R07	8402270253* 8402070470* 8210130553* 8402170003* 8402160286*	50-206 P 50-298 P 50-289 P WASTE MOT TOPREP	TAC 08082 TAC 07934
UMTRA-DDE/AL-163 WCAP-10340 WCAP-858781R1 E8E-18 WCAP-858781R1 E8E-38 WCAP-858781R3 E8E-17	8402100495* 8402010162* 8402160503* 8402160538* 8402160488*	WASTE MOT 50-327 P TOPREP TOPREP TOPREP	EGDP-ESE-1B EGDP-ESE-3B EGDP-ESE-17

REPORT		CESSION	SUBJECT	OTHER REPORT
NUMBER	1	IUMBER	CATEGORY	NUMBER
			~~~~~	
WCAP-858781R4 A			TOPREP	EGDP-AE-1
WCAP-858781R4 E			TOPREP	EGDP-ESE-14
WCAP-050781R4 E			TOPREP	EGDP-ESE-15
WCAP-050781R4 E			TOPREP	EGDP-ESE-14
WCAP-858791R4 E	SE-19 840	2160525*	TOPREP	EGDP-ESE-19
			*	
WCAP-858751R4 E			TOPREP	EQDP-ESE-1A
WCAP-058791R4 E			TOPREP	EGDP~ESE-21
WCAP-058791R4 E			TOPREP	EGDb-E8E-55
WCAP-85078184 E			TOPREP	EGDP~ESE-3A
WCAP-85879184 E	SE-5 840	2160505#	TOPREP	EGDP-ESE-5
WCAP-058781R4 H			TOPREP	EQDP-HE-2/HE-5
WCAP-859781R4 H	IE-3/H 840	2160494*	TOPREP	EGDP~HE-3/HE-6
WCAP→B58781R4 H	E-4 840	2160518*	TOPREP	EGDP-HE-4
WCAP-85878185 A	E-2 840	*SE6091S	TOPREP	EGDP-AE-2
WCAP-858781R5 A	E-3 840	2160495#	TOPREP	EGDP-AE-3
			TOPREP	EGDP-ESE-10
WCAP-85B781R5 E	SE-18 840	2160529*	TOPREP	EGDP-ESE-18
WCAP-058781R5 E	SE-2 840	2140508*	TOPREP	EGDP-ESE-2
WCAP-858781R5 E	SE-6 840	2160535*	TOPREP	EGDP-ESE-6
WCAP-858781R5 E	SE-7 840	2160516*	TOPREP	EGDP-ESE-7
WCAP-858781R6	840	2160534*	TOPREP	
WCAP-858781R6 E	SE-4 840	2160510*	TOPREP	EGDP-ESE-4
WCAP-9750-A	840	2160492*	TOPREP	
YAEC-1394	840	2060245*	50-309 P	
YAEC-1397	B40	2240143#	50-29 P	

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject catagories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix 8 and listed in the Contents.

Medicasto	M MOURER			
	PRINCIPAL	DATE	SUBJEC	т:
ENCLOSURE	DOCUMENT	ISSUED	CATEGO	
7903020095	840209040B	93/12/30	FOIA	
7903230241	8402090003	83/10/31	20~382	Α
7903260077	8402090408	83/12/30	50-206	P
7904100117	8402060286	83/11/15	50-329	A
7904100122	6402060286	83/11/15	50~329	Α
7905300523	8402090206	83/12/20	FOIA	
7908200195	8402020033	B3/11/04	50-330	Α
7907050105	840207040B	83/12/30	FOIA	
7907120678	B402090206	83/12/20	FOIA	
7908160043	8402070003	63/10/31	50-364	Α
7909170149	B402270250	84/02/08	FOIA	
7910110337	8402090206	83/12/20	FOIA	
7910230546	6402060286	B3/11/15	50-329	Α
7911130224	6402090206	B3/12/20	FOIA	м
7912180235	8402080043	83/11/01	40-1341	
		03/11/01	40-1341	
B001040244	8402270250	84/02/09	FOIA	
8001090206	8402270250	84/02/08	FOIA	
8001090209	Ø402270250	84/02/08	FOIA	
8002070305	840209040B	83/12/30	FOIA	
6002130492	8402270250	B4/02/08	FOIA	
6003250487	8402080043	83/11/01	40-1341	
BO04250213	840209040B	83/12/30	FOIA	
BQQ5020329	840207040B	83/12/30	FOIA	
BQ05020332	8402070408	83/12/30	FOIA	
6008210302	8402070081	83/12/20	50~498	G
8007110548	8402070081	85/45/56	ED 400	
B007120138	6402080309	83/12/20 83/12/01	50-498 FOIA	Α
6009120145	6402060309	83/12/01	FOIA	
6009120148	8402080309	B3/12/01	FOIA	
6010160407	8402230408	84/02/07	FOIA	
	040×230400	64702747	FUIN	
BO12310632	8402270263	B4/01/30	50-320	D
BL01130714	8402210003	B3/11/29	50-498	G
B101270307	8402270263	84/01/30	50-320	o
6102170624	8402070206	03/12/20	FOIA	
ØL03270357	8402080381	83/12/05	50-348	P
B104090747	8402070206	83/12/20	FOIA	
B104210566	8402090206	83/12/20	FOIA	
8104280035	8402090206	83/12/20	FOIA	
E104260232	8402090206	83/12/20	FOIA	
<b>8104280266</b>	8402270184	83/12/14	FOIA	
\$1,04280270	8402270184	B3/12/14	FOIA	
B104270054	8402090408	B3/12/30	FOIA	
8105120144	B402270051	B4/01/26	50-382	G
8108110074	8402020033	83/11/04	50-329	Ă
8108190047	8402080431	03/11/20	FOIA	
#4.00000.co				
#1092B0153	8402270263	84/01/30	FDIA	_
#110300111	8402270243	84/01/30	50-466	0
B111170178	8402090003	B3/10/31	50-443	Ą
B111230250	B402090003	83/10/31	50-397	A
BL12220708	8402020033	B3/11/04	50-329	~

ACCESSION NUMBER

	PRINCIPAL	0.470	Outs 1074	• •
		DATE	SUBJEC	
ENCLOSURE	DOCUMENT	1 SSUED	CATEGO	JRY
8201190717	B4020B0431	93/11/28	FOIA	
8201200478	8402140486	83/12/02	FUIA	
8201250042	8402070408	83/12/30	FOIA	
8201300218	6402080093	83/12/23	50-498	0
8202170355	8402080431	83/11/29	FOIA	_
OECET \ GGGG	E-105000401	CO/II/EG	( MIG	
8203040564	8402080431	83/11/28	FOIA	
8203150319	8402010354	63/11/22	50-275	Q
			FOLA	_
8204050442	8402160003	83/12/14		_
8204070041	8402070003	83/10/31	50~528	Α
8204160175	8402270349	B4/02/13	FOIA	
DODEN / AAA 1	0400000000	0.100115	CO.	
8202070001	8402270369	84/02/13	FOIA	
8205190430	B402240216	84/02/03	50-220	₽
B205210017	8402080431	83/11/28	FOIA	
B205240576	8402080431	83/11/28	FOIA	
8204030327	8402150122	Ø4/02/0B	TOPREP	
E204040003	8402050012	B3/10/31	FOIA	
8206110034	8402240216	84/02/03	50-220	P
8206110300	8402090206	83/12/20	FOIA	
8206110307	6402090206	83/12/20	FOLA	
8206210343	8402050028	B3/10/27	50-2B9	P
B500% 10242	0405050050	D3/10/E/	30-207	г
8206250072	8402240216	84/02/03	50-220	P
B20629060B	8402040028	83/10/27	50~287	P
			50-289	è
8207090028	8402040028	83/10/27		
8207140125	8402060028	83/10/27	50~287	₽
8207200441	8402040028	83/10/27	50-287	P
		50 11 5 15 15 15 15 15 15 15 15 15 15 15 1	ea	
e207300124	8402050028	83/10/27	FOIA	
8207300136	8402060028	83/10/27	50-289	2
8208090285	8402060028	63/10/27	50-287	p
8208230400	8402150122	64/02/08	TOPREP	•
				_
8208250400	8402040028	83/10/27	50~287	Р
8208310181	8402060028	B3/10/27	50-289	₽
		63/10/27	50-289	ģ
8208310444	8402040028			
0207010516	8402290002	83/11/30	FÜIA	
8209150004	8402060012	B3/10/31	FOIA	
8207210485	6402140486	83/12/02	FOIA	
9401K10402	M40#140400	COLLEGE		
				_
B209230151	B402240216	84/02/03	50-220	P
8209280423	8402040028	63/10/27	50~289	P
8207280427	8402060028	63/10/27	50-287	P
8207290283	8402270051	84/01/26	50-382	Q.
8210070023	8402060028	<b>9</b> 3/10/27	50-287	P
210130553	940704.0038	93/10/27	50-289	ρ
	8402040028			г
3210150584	8402150122	84/02/OB	TOPREP	
3210270116	8402060028	83/10/27	50-257	P
211010469	8402150122	84/02/08	TOPREP	
211040035	8402150122	84/02/08	TOPREP	
211040310	8402140486	83/12/02	50-309	S
211090598	8402040028	83/10/27	50-287	P
211110543	8402060028	69/10/27	50-287	P
211290127	8402080039	B3/11/04	FOIA	
212130066	8402010480	83/11/08	FDIA	
T	aro10.00			

ACCESSION NUMBER

ACCESSION					ACCESS 10			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC CATEGO		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8212150120 8212290011 8212290017 8301060232 8301170355	8402060028 8402080431 8402080431 8402060028 8402070458	83/10/27 83/11/28 83/11/28 83/10/27 84/01/20	50-289 FOIA FOIA 50-289 50-298	P P	8309120033 8309120062 8309120090 8309120255 8309150464	8402170449 8402010423 8402070039 8402270503 8402100264	84/01/27 83/11/28 83/11/04 84/02/09 84/01/23	A107 A107 A107 A107 A107 NO1881MM00
8301250428 8302020181 8302070497 8303110519	8402060028 8402060028 8402060028 8402080431 8402060028	83/10/27 83/10/27 63/10/27 83/11/28 83/10/27	50-289 50-289 50-289 FOIA 50-289	P P	8309150466 8309150467 8309150471 8309150474 8309150480	8402100266 8402100266 8402100266 8402100266 8402100266	84/01/23 84/01/23 84/01/23 84/01/23 84/01/23	COMMISSION COMMISSION COMMISSION COMMISSION
8303160017 8303240052 8303280015 8303280024 8303300416	8402240214 8402090003 8402040028 8402040028 8402040028	84/02/03 83/10/31 83/10/27 83/10/27 83/10/27	50-220 50-410 50-289 50-289 50-289	P A P P	6307150463 8307200043 8307230347 8307250011 8307270525	8402100266 8402240086 8402140412 8402130013 8402270067	64/01/23 63/12/12 64/02/09 63/12/21 63/12/14	COMMISSION 50-267 8 50-267 P 50-171 P FOIA
830401004B 8304040543 8304040550 8304050473 8304050478	8402040028 8402130007 8402270072 8402040028 8402040028	83/10/27 83/11/10 83/12/22 83/10/27 83/10/27	50-289 50-528 50-528 50-289 50-289	P A P P	8309270528 8309290095 8309290297 8309300031 8310030612	8402270067 8402060117 8402070054 8402240153 8402130013	83/12/14 84/01/16 84/01/25 83/12/07 83/12/21	FOIA 50-259 @ 50-321 P 50-382 A FOIA
8304070059 8304130440 8304140047 8304140139 8304140324	840209040B 8402060028 8402060028 8402080431 840209040B	83/12/30 83/10/27 83/10/27 83/11/28 83/12/30	FOIA 30-289 50-289 FOIA FOIA	P P	8310050245 8310050311 8310060214 8310060224 8310060351	8402070054 8402070458 8402240216 8402240216 8402270487	84/01/25 84/01/20 84/02/03 84/02/03 84/01/12	50-321 P 50-298 P 50-220 P 50-220 P 50-277 P
8304250292 8304260267 8304270219 8304270275 8304270371	8402060028 8402270002 8402060028 8402060028 8402060028	83/10/27 83/11/30 83/10/27 83/10/27 83/10/27	50-289 FOIA 50-289 50-289 50-289	Р Р Р	8310040353 8310130140 8310190334 8310200052 8310200329	8402270487 8310130158 8402280114 8402080029 8402240081	84/01/12 83/10/06 84/01/05 83/11/16 84/02/08	50-277 P 50-275 G 50-250 P 50-528 S 50-289 P
B304270380 B305020051 B305040124 B305110172 B305140003	8402040028 8402240309 8402090003 8402090003 8402240086	83/10/27 83/12/14 83/10/31 83/10/31 83/12/12	50-289 50-287 FOIA 50-410 50-272	P P A S	8310210339 8310240142 8310270514 8311140287 8311150394	8402130013 8402130013 8402210453 8402240153 8402130013	83/12/21 83/12/21 84/02/13 83/12/09 83/12/21	FOIA FOIA 50-508 A 50-382 A FOIA
8305160343 8305170338 8305200042 8305240101 8304010054	8402140486 6402060028 6402080431 8402060028 6402060028	83/12/02 83/10/27 83/11/28 83/10/27 83/10/27	FOIA 50-289 FOIA 50-289 50-289	P P	8311210028 8311210544 8311230199 8311300146 8311300173	8402130004 8402130004 8402130013 8402130013 8402130013	83/12/30 83/12/30 83/12/21 83/12/21	FOIA FOIA FOIA FOIA
8306010480 8306020182 8306020257 8306030079 8306030387	8402060028 8402240309 8402060028 8402240216 8402060028	83/10/27 83/12/14 83/10/27 84/02/03 83/10/27	50-287 50-287 50-287 50-220 50-28?	부 무 무	831200460 8312020436 8312050175 8312070072 8312160258	8402280116 8402280116 8402130013 8402130013 8402280116	84/01/05 84/01/05 83/12/21 83/12/21 84/01/05	50-250 P 50-250 P FOIA FOIA 50-250 P
8306140051 8306150045 8306150873 8306240184 8306270165	8402270002 8402150122 8402060028 8402010471 8402270263	83/11/30 84/02/08 83/10/27 83/11/15 84/01/30	FOIA TOPREP 50-289 50-289 FOIA	6 P	6312160320 6312190055 6312190179 8312200154 6312220267	8402140537 8402130013 8402130013 8401170012 8312120110	84/02/03 83/12/21 83/12/21 84/01/24 84/01/12	MIBC FDIA FDIA 50-312 P 50-454 A
B307040279 B307150043 B3071503B1 B307180123 B307180303	8402130498 8402060028 8402140486 8402140486 8402280116	83/11/28 83/10/27 83/12/02 83/12/02 84/01/05	50-247 50-269 FOIA FDIA 50-250	H P	8312220269 8312230127 8312290161 8401030277 8401030405	8312120110 8401190012 8402130557 8401030275 8402070430	84/01/12 84/01/24 84/01/25 83/12/29 84/01/26	50-454 A 50-312 P NUREG 50-361 P NUREG
8307180383 8307190353 8307190358 8307200092 8307210350	8402270474 8402130478 8402130478 8402130478 8402130013	84/02/09 83/11/28 83/11/28 83/11/28 83/12/21	50-329 50-247 50-247 FOIA FOIA	A P P	8401040412 8401040416 8401040174 8401040176 8401090362	8401040408 8401040408 8401060163 8401060163 8401190048	83/12/28 83/12/28 83/12/28 83/12/28 84/02/09	QA999 QA999 50~483 F 50~322 8
8307250016 8307250073 8307270197 8307270458 8308040572	8402240309 8402240309 8402240309 8402270184 8402270494	83/12/14 83/12/14 83/12/14 83/12/14 84/02/09	50-287 50-287 50-287 FDIA 50-329	P P P	8401090571 8401090577 8401100029 8401110109 8401110113	8401190048 8401190048 8402090515 8402100266 8402100266	84/02/09 84/02/09 84/01/30 84/01/23 84/01/23	50-322 B 50-322 B TOPREP COMMISSION COMMISSION
B308050317 B308050426 B308070022 B308100453 B308150030	8402130498 8402240309 6402240277 8402270487 8402240309	83/11/28 83/12/14 84/01/27 84/01/12 83/12/14	50-247 50-287 50-352 F01A 50-287	F U P	8401110467 8401130140 8401170071 8401170073 8401170077	8402130557 8402140525 8401170065 8401170065	84/01/25 84/01/30 83/10/24 83/10/24 83/10/24	NUREQ HIBC 50-397 A 50-397 A 50-397 A
B308160549 B308170014 B308180043 B308180641 B308180750	8402270405 8402240086 8402270002 8402270002 8402230444	84/02/13 83/12/12 83/11/30 83/11/30 84/02/13	50-498 50-267 50-382 50-382 50-508	F 8 U 4	8401170083 8401170089 8401170092 8401170482 8401170528	8401170065 8401170065 8401170065 8402270523 8402060290	83/10/24 83/10/24 83/10/24 84/01/16 84/01/17	50-397 A 50-397 A 50-397 A 40-7580 50-412 A
3308240177 3308240400 3309010095 3309070010 3309080080	8402270487 8402270388 8402140078 8402240086 8402240081	84/01/12 84/02/13 84/02/10 83/12/12 84/02/08	FOIA 50-478 80-309 50-277 50-289	A P S O	8401260470 8401270103 8402010021 8402010037 8402010038	8402140021 8402080003 8402010013 8402010030 8402010027	84/01/26 84/02/01 83/12/30 83/12/13 84/01/10	50-250 P TOPREP 50-333 P CONTRACT 50-324 Q

ACCEBBION	NUMBER				ACCESSION	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	BUBJECT CATEGORY	
3402050040 3402010048 3402010050 3402010050 3402010051	8402010033 8402010042 8402010044 8402010046 8402010035	84/01/12 84/01/16 84/01/20 84/01/17 84/01/24	CONTRACT	~ A	8402010446 8402010448 8402010449 8402010453 8402010453	8402010443 8402010443 8402010445 8402010444 8402010445	83/08/19 83/08/19 84/01/17 84/01/17 84/01/17	WASTE HOT WASTE HOT 50-280 F 50-250 F 50-260 F	P
1402010054 1402010062 1402010063 1402010065 402010073	8402010052 8402010058 8402010040 8402010059 8402010071	84/01/17 84/01/06 84/01/27 84/01/16 83/12/28	CONTRACT CONTRACT TOPREP CONTRACT CONTRACT		8402010493 8402010494 8402020003 8402020003 8402020009	8402010402 8402010491 8402020001 8402020007	83/11/16 83/11/15 84/01/19 84/01/19 84/01/17	50~250 \$ 50~269 F 50~220 C 50~220 C	F G G
402010074 402010075 402010077 402010081 402010083	8402010070 8402010068 8402010067 8402010072 8402010068	84/01/24 84/01/30 84/01/26 84/01/18 84/01/30	QA999 CONTRACT	P P	8402020010 8402020037 8402020041 8402020041 8402020046	8402020007 8402020031 8402020033 8402020033 8402020033	84/01/17 81/07/07 83/11/04 83/11/04 83/11/04	50-461 ( HASTE MOT 50-327 A 50-330 A 50-329 R	A A R
402010086 402010089 402010095 402010097 402010098	8402010080 8402010080 8402010091 8402010092 8402010091	84/01/13 84/01/13 84/01/27 84/01/20 84/01/27	50-206 50-329 XPDRTLIC	P P G	8402020032 8402020059 8402020064 8402020068 8402020068	8402020033 8402020033 8402020033 8402020033 8402020033	83/11/04 83/11/04 83/11/04 83/11/04 83/11/04	50-329 A 50-329 A 50-329 A 50-329 A	A R A
102010199 102010102 102010121 102010121	8402010073 8402010073 8402010105 8402010116 8402010122	84/01/17 84/01/17 84/01/18 83/12/23 84/01/17	50-200 CONTRACT	ម គ	8402020070 8402020072 8402020073 8402020079 8402020086	84020200033 8402020067 8402020033 8402020078	83/11/04 84/01/24 83/11/04 83/11/04 84/01/20	30-329 / 40-8027 50-329 / 50-358 (	A A D
102010124 102010128 -02010132 -02010149 02010150	8402010114 8402010127 8402010129 8402010134 8402010146	83/12/23 84/01/24 84/01/12 84/01/27 84/01/16	71-365	f' G A	8402020092 8402020103 8402020108 8402020112 8402020123	8402020033 8402020101 8402020107 6402020107 6402020121	83/11/04 84/01/17 83/12/28 83/12/27	50-259 8 WASTE MOT 50-244 0 50-244 0 50-443 0	0
02010157 02010162 02010163 02010165 02010168	8402010151 8402010155 8402010156 8402010160 8402010156	84/01/20 84/01/24 84/01/24 84/01/24 84/01/24	50-267 50-327 GA999 50-321 GA999	F F 약	8402020124 6402020127 6402020138 8402020142 8402020145	8402020119 8402020121 8402020135 8402020033 8402020033	83/12/27 63/12/27 84/01/30 83/11/04 83/11/04		œ
02010173 02010175 02010176 02010179 02010180	8402010154 8402010157 8402010171 8402010157 8402010170	84/01/24 84/01/30 84/01/19 84/01/30 84/01/17	GA999 50-219 CONTRACT 50-219 CONTRACT	P P	8402020148 6402020147 8402020154 8402020156 8402020158	8402020143 8402020033 8402020150 8402020152 8402020150	84/01/07 83/11/04 84/01/20 84/01/20 84/01/20	70-2362 50-329 / 50-213 ( 50-423 ( 50-213 (	œ C
02010181 02010198 02010199 02010212 02010228	8402010177 8402010194 8402010192 8402010207 8402010219	83/12/23 84/01/12 84/01/05 84/01/12 84/01/12	50-295 50-334 50-295 50-309 50-213	후 후 부 <b>(</b>	8402020159 8402020149 8402020171 8402020178 8402020183	8402020033 8402020164 8402020164 8402020168 8402020180	83/11/04 84/01/18 84/01/20 84/01/18 83/12/30	50-329 6 50-320 6 50-336 6 50-329 6 50-410 6	a a a
)2010229 )2010232 )2010237 )2010260 )2010273	8402010227 8402010219 8402010219 8402010257 8402010257	83/06/11 84/01/12 84/01/12 84/01/16 84/01/13	WASTE MOT 50-213 50-213 50-456 50-346	T F B P	8402020185 8402020187 8402020190 8402020191 8402020204	8402020192 8402020180 8402020182 8402020180 8402020195	63/15/53 63/15/30 63/15/30 63/15/54	50-247 0 50-410 0 50-247 0 50-410 0 50-296 0	0 0 0
12010279 12010285 12010286 12010287 12010318	8402010274 8402010282 8402140525 8402010282 8402010314	84/01/12 84/01/23 84/01/30 84/01/23 84/01/20	50-338 50-271 MISC 50-271 50-329	Р Р Р Н	8402020212 8402020213 8402020216 8402020219 8402020226	8402020210 84020200033 8402020210 8402020210 8402020213	84/01/20 83/11/04 64/01/20 84/01/20 83/12/30		
2010328 2010333 2010335 2010334 2010342	8402010325 8402010331 8402010330 8402010327 8402010337	84/01/19 84/01/19 84/01/25 83/12/30 84/01/20	TOARTMOD TOARTMOD PERUN PERUN TOARTMOD	F	8402020230 8402020238 8402020242 8402020246 8402020252	8402020227 8402020236 8402020236 8402020245 8402020245	84/01/30 83/12/27 83/12/27 84/01/20 84/01/20	50~293 ( 50~387 (	Q Q Q Q
2010346 2010349 2010351 2010359 2010362	8402010337 8402010345 8402010344 8402010355 8402010358	83/12/27 83/12/12 83/12/14 84/01/17 84/01/20	50-259 40-8663 CONTRACT CONTRACT CONTRACT	V	8402020253 6402020254 6402020258 6402020260 6402020265	8402020251 8402020247 8402020254 8402020251 8402020263	84/01/17 84/01/20 84/01/18 84/01/17 84/01/30	50-329 ( 50-341 ( 50-333 (	a a a c
2010372 2010378 2010384 2010386 2010389	8402010364 8402010364 8402010364 8402010362 8402010365	83/11/22 83/11/22 83/11/22 84/01/10 84/01/23	50-275 50-275 50-247 50-263 CONTRACT	Q Q U P	8402020267 8402020272 8402020274 8402020288 8402020288	8402020254 8402020263 8402020271 8402020275 8402020277	84/01/18 84/01/30 84/01/17 84/01/18 84/01/31	50-352 /	R G A
2010393 2010394 2010404 2010407 2010409	8402010364 8402010364 8402010402 8402010402 8402010402	83/11/22 83/11/22 83/11/16 83/11/16 83/11/16	POIA POIA 50-250 50-250 50-348	8 9 F	8402020293 8402020295 8402020296 8402020299 8402020310	8402020277 6402020267 6402020277 6402020277 8402020033	84/01/31 84/01/30 84/01/31 84/01/31 83/11/04	50-409 F 50-352 I 50-352 I FOIA	F
1010417 1010433 1010437 1010439 1010442	8402010408 8401270152 8401270152 8402010436 8402010438	84/01/16 84/01/24 84/01/24 84/01/20 84/01/24	50-259 50-528 50-528 50-528 CONTRACT 71-5024	P A A	8402020314 6402020316 8402020318 8402020324 8402020324	8402020312 8402020307 8402020317 8402020320 8402020320	84/01/31 84/01/17 83/12/27 83/12/28 83/12/28	50-334 ( 50-219 (	000

ACCESS10	N NUMBER					N NUMBER			
ENCLOSURE	PRINCIPAL OBCUMENT	DATE ISSUED	SUBJEC		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEGOR	
8402020330 8402020332	8402020328 8402020328	83/12/27 83/12/27	40-6920 40-6920		8402030428 8402030428	8402030421 8402030425	84/01/24 84/01/12	CONTRACT 50-293	T G
8402020334 8402020334	8402020322 8402020329	84/01/17 83/12/30	50-352 50-272	G G	8402030433 840203043 <i>6</i>	8402030427 8402030431	84/01/27 84/01/24	50-331 70-371	P
8402020338	8402020335	83/12/27	50-245	Q	8402030447	8402030439	84/01/24	50-348	8
8402020339 8402020344 8402020345	8402020337 8402020342 8402020341	84/01/09 84/01/20 84/01/27	70-221 70-487 50-10	Œ	8402030453 8402030454 8402030457	8402030439 8402030439 8402030452	84/01/24 84/01/24 84/01/31	50-348 50-348 50-289	S S R
8402020346 8402020348	8402020340 8402020342	84/01/26 84/01/20	50-331 70-687	P	8402030487 8402030531	8402030487 8402030499	84/01/24 80/11/24	SO-498 WASTE MG	U
8402020356 8402020357	8402020352 8402020353	83/12/30 84/01/18	50-293 50-244	Q Q	8402030532 8402040002	6402160031 8402060001	84/02/02 84/01/31	50-387 50-395	F Q
8402020361 8402020363	8402020355 8402020355	84/01/18 84/01/25	50-278 50-410	Q K	8402060009 8402060018	8402060006 8402060012	84/02/01 83/10/31	50-341 FOIA	Ğ.
8402020364	84020203 <i>6</i> 2	84/01/31	125-06	F	8402040022	8402060020	84/01/03	WASTE MO	
8402020366 8402020388 8402020371	8402020362 8402020382 8402020378	84/01/31 84/01/19 83/05/14	50-361 50-275 WASTE M	F F	B402040040 8402040041 8402040045	8402060036 8402060012 8402060036	84/01/17 83/10/31 84/01/17	50-219 71-9103 50-219	G G
8402020393 8402020396	8402020370 8402020370	84/01/11 84/01/11	50-244 50-244	Q Q	8402060046 8402060050	8402060012 8402140021	83/10/31 84/01/24	FDIA 50-250	P
8402020399	8402020370	84/01/11	50-244	G	8402060055 8402060056	8402060049 8402060012	83/10/27	WASTE MG	7
8402020424 8402020445 8402020470	8402020378 8402020462 6402020468	83/05/16 83/12/14	CONTRACTOR	Г	840206006 8402060063 8402060063	8402060012 8402140021	83/10/31 84/01/26 83/10/31	50-250 FDIA	P
8402030045	B402030035	84/01/20 84/01/16	50-269	P	E402060069	8402060012	83/10/31	FOIA	
8402030065 8402030047	8402030035 8402030062	84/01/16 84/01/30	50-269 CONTRAC		8402060073 8402060074	8402060012 8402060028	83/10/31 83/10/27	50-269	P
8402030082 8402030074 8402030101	8402030081 8402030090 8402030100	84/01/25 84/01/19 84/02/18	CONTRAC CONTRAC CONTRAC	r	8402060079 8402060085 8402060091	8402040012 8402040081 8402060086	83/10/31 84/01/18 83/12/23	FDIA 50-10 70-364	q
8402030104	B402030104	84/01/24	CONTRAC		8402060094	8402060088	84/01/31	gre	
8402030116 8402030121	8402030112 8402030112	84/01/16 84/01/16	50-263 50-263	P	8402060095 8402060106	8402060086 8402060078	83/12/23 84/01/27	70-364 50-316	P
8402030148 8402030145	8402030145 8402030140	84/01/30 84/02/01	50-322 50-445	G G	8402060116 8402060120	8402060111 8402060111	84/01/25 84/01/25	50-269 50-269	Ü
8402030187 8402030190	8402030183 8402030186	84/01/31 84/02/01	50-289 WASTE MO	C T	84020 <u>6</u> 0128 84020 <u>6</u> 0142	8402060122 8402060139	84/01/23 80/09/30	CONTRACT	
8402030203 8402030207	840203019 <i>6</i> 8402030202	84/01/27 84/01/06	50-348 CONTRACT		8402060144 8402060151	8402060119 8402060147	84/01/14 82/08/24	50-259 Waste Mg	
8402030212 8402030219	8402030209 8402030216	84/02/02 84/01/20	50~155 50~528	o s	8402060153 8402040158	8402060150 8402060150	84/02/01 84/02/01	50-445	0
8402030221 8402030222	840203020B 8402030216	83/12/05 84/01/20	50-313 50-528	a	8402060161 8402060168	8402060150 8402060164	84/02/01 84/02/01	50-445 50-352	ě
6402030228 6402030238	8402030225 8402030225	83/12/08 83/12/08	50-278 50-278	g g	8402060169 8402060176	8402060163 8402060173	84/01/31 84/01/31	50-244 50-352	0
8402030243 8402030246	8402030239 8402 <b>0</b> 30233	84/02/01 84/01/27	WASTE MO	Τ	8402040184 8402040188	8402060177 8402060185	B3/12/02 B4/02/01	CONTRACT	,
8402030242 8402030244	8402030257 8402030102	84/01/31 81/01/16	50-397 WASTE MG	G	8402060233 8402060236	8402060228 8402060231	84/01/20 84/01/26	50-346 50-312	Ğ
8402030270	8402030254	84/01/27	50-352	G	8402040238	8402060234	84/01/27	50-317	b
8402030271 8402030275 8402030277	8402030253 8402030254 8402030254	84/01/31 84/01/27 84/01/27	50-206 50-352 50-352	0	8402060241 8402060243 8402060245	8402060235 8402060028 8402060235	84/01/27 83/10/27 84/01/27	50~307 50~289 50~309	P P
8402030281 8402030308	8402030272 8402030301	81/09/21 84/01/24	WASTE MG		8402060247 8402060272	8402060240 8402060266	84/01/31 84/01/24	50-528 50-445	Ā
8402030312	8402030304	84/01/30	50-400	G	8402060289	8402060283	84/02/01	50~271	a
8402030317 8402030319 8402030320	8402030304 8402030314 8402030306	84/01/30 84/02/01 84/01/30	50~400 50~482 50~400	Q A G	8402060277 8402060278 8402060303	8402060286 8402060274 8402060286	83/11/15 84/01/20	50~329 50~312 50~329	P
8402030321	8402030306	84/01/30	50-400	Ö	8402060304	8402060294	83/11/15 84/01/20	20-315	G P
8402030324 8402030331	8402030304 8402030326	84/01/30 84/01/30	50-400 50-329	G A	8402040308 8402040309	8402060294 8402060286	B4/01/20 B3/11/15	50-312 50-329	P G
8402030332 8402030334 8402030352	8402030327 8402030327 8402030348	84/01/31 84/01/27	50~354 50~331	F P	8402060312 8402060327 8402060334	8402040294 8402040325	84/01/20 83/11/07	50-312 FOIA	P
8402030364	8402030348	84/01/19 84/01/20	CENTRACT 50~397	9	8402060342	8402060331 8402060332	84/01/24 83/11/08	50-313 50-409	P G
8402030371 8402030376	8402030357 8402030370	84/01/20 83/12/07	50-397 50-313	9 G	8402060348 8402060367	8402060332 8402060362	83/11/08 84/02/03	50-409 50-346	G G
8402030378 8402030380	8402030357 8402030357	84/01/20 84/01/20	50~397 50~397	8 8	9402060373 9402060380	8402040349 8402040374	84/02/02 83/10/21	50-315 50-354	Q B
8402030381 8402030383	8402030375 6402030370	84/01/31 83/12/09	50-275 50-313	G G	8402060389 8402060391	8402060384 8402060386	84/02/02 84/01/20	50~482 50~277	K P
8402030386 8402030372	8402030357 8402030357	84/01/20 84/01/20	50~397 50~397	8	8402040394 8402040395	8402060386 8402060390	84/01/20 84/02/01	50~277 50~341	e G
B402030395	8402030357	84/01/20	50~397	B	8402060398	8402060396	84/01/30	50-237	8
3402030397 3402030401 3402030402	8402030394 8402030357 8402030394	84/01/27 84/01/20 84/01/27	50-334 50-397 50-336	0 8 0	8402040409 8402040410 8402040413	8402060405 8402060406 8402060412	84/01/20 84/01/30 84/01/31	50-322 50-528 50-483	F G A
3402030410 3402030417	8402030405 8402030400	84/01/26 84/01/27	50-331 50-424	P K	8402040473 840005048 840005048	8402060420 8402060420	84/01/18 84/01/18	50-29 50-29	G G

AC CESSION	NUMBER					ACCESSION	NUMBER			
NCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY			ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	Υ
H02040432 H02040438 H02040442 A02040448 402040449	8402060427 8402060433 8402060433 8402060433 8402060444	84/01/26 84/01/30 84/01/30 84/01/30 84/02/02	50-348 50-348 50-348	- F 8 8 F		8402070287 8402070292 8402070295 8402070296 8402070307	8402070262 8402070282 8402070287 8402070280 8402070298	84/02/03 84/02/03 84/01/26 84/01/26 84/01/26	50-352 50-332 GA999 CONTRACT CONTRACT	 6
1402060450 402060455 402060464 402060469 402060471	8402060431 8402060431 8402060446 8402060466 8402040465	84/02/02 84/02/02 84/01/30 84/01/31 84/01/06		V V F P		8402070309 8402070311 8402070312 8402070316 8402070317	8402070282 8402070306 8402070286 8402070310 8402070386	84/02/03 84/01/24 84/02/03 84/01/26 84/02/03	50-352 0A999 50-352 50-413 50-352	G G K G
102040482 102040488 102040502 102040520	8402040475 8402040484 8402040498 8402040518 8402040514	84/01/26 84/01/26 84/01/26 84/01/18 84/01/26	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT			8402070322 8402070323 8402070331 8402070333 8402070335	8402070284 8402070315 8402070327 8402070328 8402070329	84/02/03 84/01/26 84/02/01 84/02/06 84/02/01	50-352 CONTRACT 50-352 50-219 50-305	Q P F
102060534 102060539 102060542 102060547 102060553	8402040531 8402040504 8402040538 8402040545 8402040552	84/01/24 83/12/14 84/01/26 83/12/14 84/01/27	CONTRACT CONTRACT CONTRACT CONTRACT 70-2955			8402070338 8402070339 8402070343 8402070346 8402070351	8402070328 8402070327 8402070334 8402070327 8402070347	84/02/04 84/02/01 84/01/23 84/02/01 84/01/23	50-272	P F G
102040359 102040589 102040610 102040618 02060640	8402040598 8402060585 8402070060 8402060612 8402040637	84/01/30 84/01/19 84/02/01 84/01/24	CONTRACT CONTRACT 50-322 50-413 50-445	Q A F		9402070357 8402070359 8402070360 8402070367 8402070369	8402070354 8402070354 8402070356 8402070366 8402070366	84/01/23 84/01/23 84/02/02 84/01/25 84/01/25	50-320 50-250	000 P P
02050545 02070002 02070004 02070008 02070026	8402060645 8402070001 8402070003 8402070005 8402070024	84/01/27 84/02/02 84/01/25 84/02/01 84/02/22	70-2910 50-309 50-293 50-445 50-482	G G G E		8402070373 8402070374 8402070379 8402070383 8402070385	8402070365 8402070371 8402070376 8402070381 8402070381	84/01/30 84/02/01 84/01/30 84/02/02 84/02/02	50-280 50-272 50-305 50-335 50-335	4448
02070032 02070044 02070045 02070071 02070076	8402070027 8402070038 8402070039 8402070066 8402070066	83/12/27 83/12/28 83/11/04 84/01/17 84/01/17	FOIA FOIA 50-263 50-373 50-373	F P P		8402070388 8402070391 8402070394 8402070418 8402070454	8402070381 8402070381 8402070392 8402070403 8402070125	84/02/02 84/02/02 84/02/02 84/01/26 84/02/03	50-335 50-335 50-333 CONTRACT 50-329	FOI
02070096 02070108 02070112 02070117 02070123	6402070093 6402070104 6402070110 6402070114 6402070115	84/01/27 84/01/26 84/01/23 84/02/02 84/01/26	50-284 CONTRACT State Pro 50-482 CONTRACT	G G		8402070460 8402070462 8402070470 8402070515 8402070519	8402070458 8402070458 8402070458 8402070514 8402070517	84/01/20 84/01/20 84/01/20 84/01/26 84/01/17	50-298 50-298 50-298 50-277 71-1	P P F
2070124 2070131 2070134 2070139 2070140	8402070121 8402070125 8402070130 8402070130 8402070125	84/02/03 84/02/03 84/01/31 84/01/31 84/02/03	50-247 50-327 50-322 50-322 50-327	0 0 0		8402070540 8402080020 8402080036 8402080037 8402080038	8402070537 8402080017 8402080029 8402080033 8402080033	84/01/31 83/12/14 83/11/16 83/11/16 84/01/27	71~5957 FOIA 50-206 FOIA 50-265	s
2070144 2070148 2070150 2070154 2070155	8402070125 8402070125 8402070146 8402070146 8402070125	E0\20\48 20\20\48 20\10\48 20\10\48 20\22\48	50~327 50~329 50~220 50~220 50~327	0 0 P P		8402080040 8402080042 8402080044 8402080045 8402080046	8402080035 8402080037 8402080037 8402080035 8402080037	84/01/27 83/11/04 83/11/04 84/01/27 83/11/04	50-245 FOIA FOIA 50-265 FOIA	Q Q
2070160 2070162 2070165 2070169 2070170	8402070125 8402070149 8402070125 8402070125 8402070166	84/02/03 84/01/20 84/02/03 84/02/03 84/01/31	50~329 50~382 50~329 50~329 50~148	9 9 9 9		8402080047 8402080048 8402080049 8402080050 8402080051	8402080029 8402080043 8402080039 8402080043 8402080039	83/11/14 83/11/01 83/11/04 83/11/01 63/11/04	50-528 FOIA FOIA 40-1341 FOIA	8
2070175 2070179 2070183 2070184 2070190	8402070168 8402070173 8402070177 8402070180 8402070187	84/01/25 84/01/30 84/02/03 84/02/02 84/01/23	50-289 50-498 50-275 50-412 70-1143	0 0 0		8402080052 8402080056 8402080059 8402080057 8402080060	8402080043 8402080043 8402080027 8402080043 8402080037	83/11/01 83/11/01 83/12/29 83/11/01 83/11/04	40-1341 40-1341 50-397 40-1341 FOIA	œ
2070191 2070192 2070201 2070205 2070216	8402070173 8402070182 8402070197 8402070197 8402070215	84/01/30 84/01/26 84/02/03 84/02/03 84/01/23	50-498 50-286 50-482 50-482 50-373	0 0 0		8402080061 8402080063 8402080064 8402080065 8402080066	8402080043 8402080043 8402080027 8402080042 8402080037	83/11/01 83/11/01 83/11/16 84/01/31 83/11/04		S F
1070217 1070221 1070228 1070238 1070246	8402070214 8402070213 8402070225 8402070235 8402070241	84/02/01 84/01/23 84/01/17 84/01/20 84/02/01	50-272 50-333 50-213 50-278 50-213	6 F G	·	8402080067 8402080069 6402080069 8402080070 8402080071	8402080043 8402080039 8402080043 8402080027 8402080027	83/11/01 83/11/04 83/11/01 83/12/29 83/11/16	40-1341 FOIA 40-1341 FOIA 50-328	R
070249 070250 070251 070253 070257	8402070244 8402070247 8402070242 8402070244 8402070252	84/02/02 84/02/03 84/02/03 84/02/02 84/01/26	50-311 50-440 50-352 50-311 50-287	0 0 0 0 P		8402080074 8402080075 8402080077 8402080078 8402080081	8402080043 8402080043 6402080029 8402080043 8402080043	83/11/01 83/11/01 83/11/14 83/11/01 83/11/01	40-1341 40-1341 50-528 40-1341 40-1341	R
070260 070261 070262 070266 070271	8402070252 8402070258 8402070255 8402070258 8402070264	84/01/26 84/01/09 84/01/30 84/01/09 84/02/06	50-289 GA999 50-443 GA999 50-322	P A Q		8402080082 8402080085 8402080088 8402080089 8402080091	8402080029 8402080043 8402080029 8402080043 8402080043	83/11/16 93/11/01 63/11/16 83/11/01 83/11/01	50-528 40-1341 50-528 FOIA 40-1341	R

ACCESS IO	NUMBER				ACCESS10	N NUMBER			
ENCLOSURE	PRINCIPAL BOCUMENT	DATE ISSUED	SUBJECT CATEGOR		ENCLOBURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	
8402080095 8402080097 8402080099 8402080101	8402080027 8402080043 8402080043 8402080027	83/11/14 83/11/01 83/11/01 83/11/14	50-528 40-1341 40-1341 50-528	R	8402080351 8402080357 8402080370 8402080370 8402080375	8402080354 8402080362 8402080366 8402080366 8402080369	84/01/25 84/01/25 84/01/24 84/01/26 84/01/25	50-443 50-219 50-367 50-367 50-366	G G G
8402080103 8402080104 8402080106 8402080107 8402080111	8402080093 8402080043 8402080043 8402080029 8402080029	83/11/01 83/11/01 83/11/01 83/11/16	50~498 40~1341 40~1341 50~528 50~528 40~1341	R R	8402080374 8402080377 8402080384 8402080383 8402080383	8402080372 8402080349 8402080372 8402080378 8402080386	84/01/25 84/01/24 84/01/25 84/02/02 84/01/25	50-245 50-247 50-245 50-237 50-333	9 9 9
8402080112 8402080115 8402080116 8402080117 8402080119 8402080120	8402080043 8402080043 8402080029 8402080029 8402080029	83/11/01 83/11/01 83/11/16 83/11/01 83/11/16	40-1341 50-528 40-1341 50-528 40-1341	R R	8402080374 8402080401 8402080404 8402080404 8402080414	8402080378 8402080378 8402080371 8402080378 8402080378	84/02/02 84/02/02 84/01/24 84/02/02 84/02/02	50-237 50-237 50-277 50-237 50-237	9 9 9
8402080122 8402080123 8402080124 8402080127 8402080127	8402080043 8402080027 8402080118 8402080043 8402080027	83/11/01 83/11/16 84/02/03 83/11/01 83/11/16	40~1341 50~528 50~354 40~1341 50~528	R G R	8402080418 8402080419 8402080425 8402080434 8402080435	8402080413 8402080378 8402080422 8402080431 8402080430	83/12/06 84/02/02 83/12/16 83/11/28 83/12/08	FDIA 50-237 PROJ FOIA 50-397	G A
8402080133 8402080136 8402080137 8402080138 8402080141	8402080043 8402080027 8402080043 8402080043 8402080134	83/11/01 83/11/16 83/11/01 83/11/01 84/02/03	40-1341 50-528 40-1341 40-1341 50-302	R	8402080436 8402080442 8402080447 8402080452 8402080455	8402080431 8402080431 8402080431 8402080431 8402080431	83/11/28 83/11/28 83/11/28 83/11/28 83/11/28	FDIA FOIA FOIA FOIA FOIA	
8402080143 8402080144 8402080145 8402080144 8402080152	8402080027 8402080043 8402080139 8402080139 8402080149	83/11/16 83/11/01 84/02/03 84/02/03 84/02/06	50-528 40-1341 50-352 50-352 50-537	8 0 0	8402080440 8402080465 8402080466 8402080477 8402080477	8402080448 8402080431 8402080431 8402080431 8402080224	83/12/13 83/11/28 83/11/28 83/11/28 84/02/02	CONTRACT FDIA FOIA FDIA 50-335	· G
6402080153 6402080156 6402080159 6402080160 6402080162	8402080043 8402080043 8402080043 840208043 8402080155	83/11/01 83/11/01 83/11/01 83/11/01 84/02/01	40-1341 40-1341 40-1341 40-1341 50-220	þ	8402080481 8402080499 8402080505 8402080507 8402090013	8402080474 8402080478 8402080503 8402080503 8402070005	84/01/24 84/01/26 84/01/31 84/01/31 84/01/04	CONTRACT CONTRACT 50-280 50-280 CONTRACT	P P
8402080163 8402080165 8402080166 8402080168 8402080172	8402080043 8402080155 8402080147 8402080043 8402080043	83/11/01 84/02/01 84/02/06 83/11/01 83/11/01	40-1341 50-220 50-537 40-1341 40-1341	P G	B402090027 B402090036 B402090037 B402090040 B402090042	8402070003 8402070027 8402070003 8402070023 8402070003	83/10/31 83/12/29 83/10/31 83/12/23 83/10/31	50-458 FDIA 50-443 CONTRACT 50-443	8 R
8402080176 9402080180 9402080181 9402080182 402080189	8402080043 8402080043 8402080169 8402080178 8402080185	83/11/01 83/11/01 84/02/08 84/02/01 84/02/06	40~1341 40~1341 50~280 WASTE MG	F F K	8402070045 8402070046 8402070049 8402070050 8402070051	8402090003 8402090029 8402090029 8402090026 8402090003	83/10/31 83/12/29 83/12/29 83/12/20 83/10/31	50-443 FDIA FDIA FDIA FDIA	R
402080190 402080198 402080199 402080202 9402080206	8402080188 8402080195 8402080194 8402080043 8402080043	84/01/31 84/02/06 84/01/27 83/11/01 83/11/01	50-352 50-454 50-266 40-1341 40-1341	g G P	8402070052 8402070053 8402070057 8402070058 8402070059	8402090029 8402090003 8402090029 8402090003 8402090003	83/12/29 83/10/31 83/12/29 83/10/31 83/10/31	FOIA FOIA FOIA FOIA 50-410	A
3402080208 3402080210 3402080211 3402080213 3402080214	8402080204 8402080204 8402080043 8402080204 8402080043	84/02/06 84/02/06 63/11/01 84/02/06 83/11/01	50-341 50-341 40-1341 50-341 40-1341	Q Q	8402090061 8402090062 8402090063 8402090064 8402090069	8402070003 8402070027 8402070003 8402070029 8402070054	83/10/31 83/12/29 83/10/31 83/12/29 84/01/25	50-410 FOIA 50-410 FOIA 50-321	A A P
3402080216 8402080219 8402080231 8402080239 8402080249	8402080043 8402080043 8402080228 8402080235 8402080243	83/11/01 83/11/01 84/01/27 84/02/03 84/01/26	40-1341 40-1341 50-305 50-305 70-371	P	8402090070 8402090072 8402090073 8402090074 8402090075	8402070003 8402070003 8402070068 8402070027 8402070068	83/10/31 83/10/31 84/01/31 83/12/29 84/01/31	50-528 50-528 50-220 FOIA 50-220	A A P
8402080253 8402080270 8402080280 8402080282 8402080284	8402080243 8402080243 8402080275 8402080279 8402080279	84/01/26 84/01/26 84/01/27 84/02/06 84/02/06	70-371 70-371 50-454 50-416 50-416	Q P P	8402090076 8402090078 8402090079 8402090082 8402090083	8402090003 8402090071 8402090003 8402090071	83/10/31 84/01/26 83/10/31 83/10/31 84/01/26	50-530 50-348 50-443 50-528 50-348	A A A P
8402080270 6402080301 6402080314 8402080317 8402080317	8402080285 8402080278 8402080314 8402080311 8402080311	84/01/13 84/01/30 83/12/05 84/02/03 84/02/03	50-271 50-324 FOIA 50-282 50-282	0 F F	8402090086 8402090087 8402090088 8402090090 8402090091	8402090003 8402090003 8402090003 8402090003	83/10/31 83/10/31 83/10/31 83/10/31	50-329 50-328 50-322 50-438 50-440	A A A A
8402080322 8402080326 8402080327 8402080328 8402080333	8402080321 8402080323 8402080325 8402080320 8402080330	83/12/05 84/01/30 84/02/03 84/01/25 84/01/25	FOIA 50-454 50-20 50-213 50-317	g K G	8402090092 8402090093 8402090094 8402090095 8402090098	8402070003 8402070081 8402070003 8402070003	83/10/31 83/12/20 83/10/31 83/10/31 83/10/31	50-412 50-478 50-438 50-440 50-454	A A A A
8402080334 8402080335 8402080348 8402080357 8402080350	8402080331 8402080335 8402080345 8402080355 8402080355	84/02/02 84/01/26 84/01/23 84/01/23 84/01/23	50-321 50-423 50-277 50-320 50-320	F G G	8402090097 8402090100 8402090101 8402090102 8402090103	8402070081 8402070003 8402070003 8402070003 8402070003	83/12/20 83/10/31 83/10/31 83/10/31 83/10/31	50~498 50~458 50~329 50~413 50~413	A A A A

ACCESSIO	NUMBER					ACCESSION				
EXCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJECT		EN	ICLOBURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	
6402090107 6402090109	8402090003 8402090003	83/10/31 83/10/31	50-413 50-461	A	84	102090234 102090236	8402090003 8402090206	83/10/31 83/12/20	50-424 FOIA	A
6402090114 6402090116 6402090117	8402070003 8402070097 8402070003	83/10/31 83/12/22 83/10/31	50~438 50~528 50-438	A S A	£4	10209023B 102090239 102090240	8402090003 8402090204 8402090003	83/10/31 83/12/20 83/10/31	50-392 F01A 50-392	A
8402090118 8402090118	8402090003 8402090003	83/10/31 83/10/31	50~329 50~438	A		02090242 02090243	8402090206 8402090235	83/12/20 84/01/26	FOIA 50-286	Q
\$402090122 \$402090124 \$402090127	8402090003 8402090003 8402090081	83/10/31 83/10/31 83/12/20	50-329 50-413 50-275	A U	84 84	102090244 102090246 102090247	8402090205 8402090205 8402090237	83/12/20 83/12/20 84/02/02	FOIA FOIA 50-275	F
402090128 402090129	8402090097 8402090125	83/12/22 84/02/06	50-528 50-289	A G		02090249 102090249	8402090204 8402090206	83/12/20 83/12/20	FOIA FOIA	
402090132 402090133 402090134	8402090081 8402090003 8402090003	83/12/20 83/10/31 83/10/31	50-478 50-445 50-458	U A A	84	102090250 102090252 102090254	8402070003 8402070204 8402070204	83/10/31 83/12/20 83/12/20	50-390 FOIA FOIA	A
402090138 402090138	8402090003 8402090003	B3/10/31	50-329 50-445	A		102090257 102090259	8402090206 8402090206	83/12/20 83/12/20	FOIA FOIA	
402090140 402090141 402090142	8402090003 8402090137 8402090003	83/10/31 84/02/06 83/10/31	50~445 50~267 50~327	A O A	<b>84</b>	102070261 102070262 102070263	8402070003 8402070204 8402070258	83/10/31 83/12/20 84/01/30	50-482 FOIA 50-382	A
402090144 402090145	8402090139 8402090137	84/02/06 84/02/06	50~482 50-289	0		02070245	8402070204 8402090206	83/12/20	FO1A FO1A	
102090146 102090147 102090148	8402070081 8402070003 8402070137	83/12/20 83/10/31 84/02/06	50-498 50-341 50-289	T A Q	84	02090267 02090269 02090270	8402090258 8402090204 8402090204	84/01/30 83/12/20 83/12/20	50-302 F01A F01A	F
102090149 102090152	8402090081 8402090143	83/12/20 83/12/12	50-498 50-280	T 6	B41	02070272 02070274	8402070206 8402070206	83/12/20 83/12/20	FOIA FOIA	
102090155 102090156 .02090157	8402070081 8402070003 8402070153	83/12/20 83/10/31 84/02/06	50-498 50-416 50-322	T A G	84	02090275 02090278 02090279	8402090003 8402090206 8402090206	63/10/31 83/12/20 83/12/20	50-397 FOIA FOIA	A
02090159 02090160	8402090003 8402090081	83/10/31 83/12/20	50-416 50-498	A T	844	02070282 02070284	8402090206 8402090206	83/12/20 83/12/20	FOIA FOIA 50-482	A
02090162 02090163 02090164	8402070003 8402070153 8402070081	83/10/31 84/02/06 83/12/20	50-400 50-322 50-498	A A	844	02090285 02090287 02090286	8402090273 8402090003 8402090206	84/02/02 83/10/31 83/12/20	50-397 FDIA	Ä
02070165 02070166	8402090003 8402090003	83/10/31 83/10/31	50-354 50-458 50-373	A	840	02090293 02090295 02090296	8402090206 8402090003 8402090206	83/12/20 83/10/31 83/12/20	FOIA 50-397 FOIA	A
02090167 02090169 02090169	8402090003 8402090081 8402090903	83/10/31 83/12/20 83/10/31	50-498 50-311	A T A	840	02070276 02070300 02070301	8402090206 8402090203	83/12/20 83/10/31	FOIA 50-508	A
02090170 02090171	8402090003 8402090081	83/10/31 83/12/20	50-373 50-478 50-361	A G A	840	02090304 02090305 02090307	8402070204 8402070204 8402070003	83/12/20 83/12/20 83/10/31	FOIA FOIA 50-358	A
02090179 02090174 02090175	8402090003 8402090172 8402090003	83/10/31 84/02/07 83/10/31	50-20A 50-35B	P A	B40	02090309 02090311	8402090204 8402090206	B3/15/50 B3/15/50	FOIA FOIA	-
)2090176 )2090177 )2090178	8402090081 8402090003 8402090003	83/12/20 83/10/31 83/10/31	50-498 50-341 50-352	A A	840	02090312 02090313 02090315	8402090204 8402090204 8402090206	83/12/20 83/12/20 83/12/20	FOIA FOIA FOIA	
12090180 12090180	8402070081 8402070003	83/12/20 83/10/31	50-498 50-443	Ä	B40	02090317	8402070206 8402070206	83/12/20 83/12/20	FOIA FOIA	
2090184 2090185	8402090081 8402090003	83/12/20 83/10/31	50-498 50-454 50-322	A A A	840	02070326	8402070206 8402070206 8402070321	83/12/20 83/12/20 84/02/07	FOIA FOIA 50-204	G
2070187 2070188 2070187	8402070003 8402070081 8402070003	83/10/31 83/12/20 83/10/31	50-499 50-454	Ä	840	02090330	8402210168 8402070204	84/02/02 83/12/20	50-250 FDIA	F
2090190 2090192	8402090003 8402090003	83/10/31 83/10/31	50-322 50-327 50-322	A A Q	840	02090337	6402070205 6402070327 6402070335	83/12/20 84/01/27 84/02/07	F01A 50-354 50-287	g F
5040148 5040148 5040143	8402090001 8402090003 8402090081	83/12/20 83/10/31 83/12/20	50-322 50-498 50-320	ů	840	2090340			FDIA 50-423	G
2090201 2090201	B402090003 B402090003	83/10/31 83/10/31 84/02/01	50-329 50-389 50-454	A A F	840	2090347	8402090206 8402090206 8402090349		FOIA FOIA 50-387	a
2090207 2090208 2090210	8402070204 8402070206 8402070206	83/12/20 83/12/20	FOIA FOIA	•	840	2090353	8402090206	83/12/20	FOIA FOIA	
1090213 1090215	8402090209 8402090206	84/01/31 83/12/20 84/02/02	50-458 FOIA 50-482	F F	E40	2090358	8402090348 8402090204 8402090204		50-367 FOIA FOIA	G
000550 000514 000518	8402070211 8402070206 8402070003	83/12/20 83/10/31	50-462 FOIA 50-395	A	840	2090365 2090368	840209020A 840209020A	83/12/20	FOIA FOIA	
090221 090223	8402090206 8402090206	83/12/20 83/12/20	FDIA FOIA 50-388	A	E40	2090370	8402090205		50-272 FOIA FOIA	0
090224 090226 090227	8402070003 8402070003 8402070206	83/10/31 83/10/31	50-386 50-387 FOIA	Ā	B40	2090374	840209036i	84/01/27 83/12/20	50-317 F01A	G .
090230 090228	8402090206 8402090003	83/12/20 83/10/31	FOIA 50-382 50-387	A	840 840	2090382	8402090206 8402090206	83/12/20 83/12/20	FOIA FOIA FOIA	
040533 040533 040531	8402070003 8402070206 8402070206	83/10/31 83/12/20 83/12/20	FOIA FOIA	A	840	2090387	9402070206	83/12/20	FOIA FOIA	

ACCESSION NUMBER					ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 185UED	SUBJECT CATEGOR		ENCLOSURE		DATE ISSUED	SUBJECT CATEGORY	
8402070374 8402070374 8402070377 8402070400 8402070402	8402090206 8402090392 8402090206 8402090392 8402090392	83/12/20 84/01/31 83/12/20 84/01/31 84/01/31	FOIA 50-312 FOIA 50-312 50-312	 F F	840210015 840210015 840210014 840210015 840210015	88 8402100130 89 8402090408 11 8402100128 86 8402100152	84/01/24 83/12/30 84/01/23 84/02/09 83/12/30	50-483 G FDIA GA999 50-244 G 50-247 P	
8402090405 8402090407 8402090410 8402090411 8402090412	8402070372 8402070372 8402070372 8402070408 8402070372	B4/01/31 84/01/31 84/01/31 83/12/30 B4/01/31	50-312 50-312 50-312 FOIA 50-312	F F F	840210017 840210016 640210016 840210019 840210019	9402090408 17 B402090408 8402100184	84/02/06 83/12/30 83/12/30 84/02/08 84/02/08	50-341 A FOIA 50-324 P 50-445 T 50-445 T	
8402090413 8402090416 8402090418 8402090419 8402090420	8402090408 8402090408 8402090392 8402090415 8402090408	83/12/30 83/12/30 84/01/31 84/01/23 83/12/30	FOIA FOIA 50-312 COMMISSI FOIA	F ION	940210019 940210019 940210020 940210020 940210020	77 8402100194 92 8402100198 94 8402100201	84/02/03 84/02/06 84/02/06 84/01/23 84/01/27	50-289 T 50-329 R 50-298 G 50-272 R 50-255 G	
8402070422 8402070423 6402070424 8402070425 8402070426	8402070409 8402070408 8402070417 8402090392 8402090408	84/01/24 83/12/30 84/01/27 84/01/31 83/12/30	50~280 FOIA 50~287 50~312 FOIA	O P F	64021.0021 64021.0021 64021.0021 64021.0021 64021.0021	1 8402100207 5 8402100207 6 8402100214	84/02/08 84/01/27 84/01/27 84/01/30 84/01/27	50-206 P 50-456 Q 50-456 Q 50-390 F 50-440 Q	
8402090428 8402090429 8402090430 8402090431 8402090432	8402070408 8402070408 8402070392 8402070407 8402070392	83/12/30 83/12/30 84/01/31 84/01/24 84/01/31	FOIA FOIA 50-312 50-280 50-312	F O F	64021 0022 64021 0022 84021 0022 84021 0022 64021 0023	4 8402100220 5 8402100222 7 8402100220	84/01/27 84/02/08 84/02/03 84/02/08 84/02/02	50-440 Q 50-244 P 50-266 F 50-244 P 50-327 A	
8402090434 8402090435 8402090436 8402090437 8402090438	8402070408 8402070408 8402070408 8402070408 8402070408	83/12/30 84/01/31 83/12/30 83/12/30 83/12/30	FOIA 50~272 FOIA FOIA FOIA	6	64021 0023 64021 0023 84021 0024 84021 0024 64021 0024	4 8402100229 6 8402100226 0 8402100226	84/02/06 84/02/07 84/02/06 84/02/06 84/02/06	90-10 F 50-266 F 50-358 H 50-358 H 50-482 G	
8402090441 8402090443 8402090444 8402090447 8402090451	8402070408 8402070408 8402070442 8402070408 8402070408	83/12/30 83/12/30 84/01/18 83/12/30 83/12/30	FOIA FOIA 71-4601 FOIA FOIA		840210024 840210025 840210025 840210027 840210027	2 8402100246 6 8402100246 2 8402100266	84/01/23 84/02/04 84/02/06 84/01/23 84/01/23	50-445 G 50-244 P 50-244 P COMMISSION COMMISSION	
8402070453 8402070456 8402070462 8402070466 8402070471	8402070408 8402070408 8402070408 8402070408 8402070408	83/12/30 83/12/30 83/12/30 83/12/30 83/12/30	FOIA FOIA FOIA FOIA 50-348	A	840210028 840210029 840210032 840210032 840210033	1 8402100288 4 8402100246 3 8402100320	84/01/18 84/01/11 84/01/23 84/01/25 84/01/24	WABTE MOT WABTE MOT COMMISSION WABTE MOT 50-265 P	
8402090472 8402090476 8402090477 8402090481 8402090485	8402090408 8402090408 8402090408 8402090408 8402090408	83/12/30 83/12/30 83/12/30	FOIA FOIA FOIA FOIA 50-331	Р	840210033 840210034 840210034 840210035 840210035	6 8402100341 9 8402100341 1 8402100347	84/01/24 84/01/23 84/01/23 84/02/02 84/01/23	50-265 P 50-263 P 50-263 P XPORTLIC 50-263 P	
8402070526 8402070548 8402070557 8402070560 8402070563	8402070513 8402070545 8402070408 8402070408 8402070408	84/01/24 84/01/19 83/12/30 83/12/30 83/12/30	CONTRACT CONTRACT FOIA 50-321 FOIA		640210035 840210035 840210036 840210036 840210037	8 8402100348 6 8402100343 8 8402100362	84/01/23 84/01/31 84/01/20 84/02/02 84/01/20	CONTRACT 50-282 P 50-298 P XPORTLIC 50-298 P	
8402090544 8402090571 8402090578 8402090579 8402090581	8402070408 8402070567 8402070565 8402070576	83/12/30 83/12/02 84/01/13 84/01/18 84/01/18	FOIA 50-366 71-9186 71-5026 71-512	8	840210037 840210037 840210037 840210038 840210038	8401170057 9 8402100372 2 8402100380	84/02/13 84/02/13 84/02/02 84/01/30 84/02/02	50-275 P 50-275 P XPORTLIC CONTRACT XPORTLIC	
8402090584 8402090592 8402090401 8402090604 8402100007	8402090365 8402090583 8402090597 8402090597 8402100001	84/01/13 84/01/30 84/01/30 84/01/30 84/02/03	71-9186 CONTRACT 70-364 70-364 50-275	E	840210039 840210039 840210040 840210040 840210040	7 8402100393 0 8402100398 1 8402100393	84/02/02 84/01/27 84/02/07 84/01/27 84/02/07	CONTRACT 50-348 P 70-135 50-348 P 70-135	
8402100012 8402100018 8402100021 8402100026 8402100030	8402100005 8402100005 8402100005 8402100005 8402100005	83/11/28 83/11/28 83/11/28 83/11/28 83/11/28	FOIA FOIA FOIA FOIA		840210040 840210040 840210041 840210041 840210041	6 8402100403 2 8402100407 5 8402100411	84/01/27 84/01/27 64/01/31 64/01/13 64/01/23	50-311 P 50-311 P REGOD GUNTRACT 70-143	
8402100033 8402100036 8402100040 8402100042 8402100045	8402100005 6402100005 6402100005 6402100005	83/11/28 83/11/28 83/11/28 83/11/28	FOIA FOIA 50-373 50-373 FOIA	P P	840210042 840210044 840210046 840210046 840210046	9 8402100447 5 8402100441 2 8402100450	84/02/04 83/11/30 84/01/25 83/10/19 83/11/30	71-6206 50-200 8 CONTRACT CONTRACT FOIA	
8402100072 8402100079 8402100085 8402100073 8402100113	84021000&6 84021000&6 84021000&6 84021000B9 8402100111	84/02/07 84/02/07 84/02/07 84/01/26 84/02/08	50-445 50-445 50-445 CONTRACT 50-445	T T Q	84021004 <i>6</i> 84021004 <i>6</i> 84021004 <i>7</i> 84021004 <i>7</i> 840213000	9 8402100466 9 8402100489 5 8402100492	83/11/30 84/01/27 84/02/02 84/01/31 83/12/30	FOIA XPORTLIC CONTRACT WASTE MOT FOIA	
8402100115 8402100132 8402100134 8402100135 8402100136	8402100111 8402100128 8402100130 8402100133 8402100128	84/02/08 84/01/23 84/01/26 84/02/07 84/01/23	50-445 GA999 50-483 50-322 GA999	G G	840213000 840213000 840213001 840213001	9 8402130004 0 8402130007 2 8402130007	83/12/30 83/12/30 83/11/10 83/11/10 83/11/10	FOIA FOIA 50-328 A 50-528 A 50-528 A	

ACCESSION					ACCESSIO	N NUMBER		
YCLOSUSE	PRINCIPAL DOCUMENT	DATE 185VED	SUBJECT CATEGORY	,	ENCLOSURE	PRINCIPAL DOCUMENT	DATE DATE	SUBJECT CATEGORY
402130014 402130017 402130018 102130019 402130020	8402130007 8402130013 8402130004 8402130007 6402130013	83/11/10 83/12/21 83/12/30 83/11/10 83/12/21	FOIA FOIA	A	8402130238 8402130241 8402130246 8402130246 8402130230	8402130233 8402130007 8402130233 8402130007 8402130245	84/02/07 83/11/10 84/02/07 83/11/10 84/01/27	50-400 9 50-528 A 50-400 9 50-528 A 50-373 P
1021 30021 1021 30022 1021 30024 1021 30025 021 30027	8402130004 8402130013 8402130007 8402130013 8402130013	83/12/20 83/12/21 83/11/10 83/12/21 83/12/21	FOIA FOIA 50-528 FOIA FOIA	G	8402130257 8402130261 8402130262 8402130264 8402130264	6402130252 6402130252 6402130007 6402130260 6402130263	64/02/01 64/02/01 83/11/10 84/02/08 84/01/25	TOPREP TOPREP 50-528 A 50-289 G 50-409 G
021 30030 021 30031 021 30033 021 30036 021 30041	8402130007 8402130013 8402130013 8402130013 8402130037	93/11/10 93/12/21 93/12/21 93/12/21 94/01/13	50-528 FOIA FOIA FOIA CONTRACT	Α	6402130267 8402130270 8402130273 8402130275 8402130282	8402130265 8402130007 8402130263 8402130272 8402130279	84/02/02 83/11/10 84/01/25 84/02/07 84/02/07	50-3 H 50-528 T 50-409 G 50-395 R 50-327 P
021 30043 021 30044 021 30047 021 30048 021 30053	8402130013 8402130007 8402130007 8402130046 8402130007	83/12/21 83/11/10 83/11/10 84/02/07 83/11/10		A C A	8402130284 8402130286 8402130280 6402130302 8402130302	8402130278 8402120283 8402130283 8402130278 8402130303	84/01/25 84/02/08 84/02/08 84/02/01 84/01/27	50-263 0 50-443 0 50-443 0 71-451 50-461 0
02130054 02130057 02130060 02130064 02130065	8402130013 8402130013 8402130013 8402130013 8402130059	83/12/21 83/12/21 83/12/21 83/12/21 84/02/06	50-295 FOIA FOIA FOIA 50-333	P Q	8402130312 8402130317 8402130322 9402130324 8402130324	8402130303 8402130314 8402130314 8402130320 8402130319	84/01/27 84/02/06 84/02/06 84/02/07 84/02/06	50~461 G 50-400 G 50-400 G XPORTLIC 50~272 P
/21/30069 121/30070 121/30072 121/30073 121/30076	8402130013 8402130013 8402130013 8402130013 8401190036	83/12/21 83/12/21 83/12/21 83/12/21 84/02/08	FOIA FOIA FOIA FOIA 50-275	Ť	8402130327 8402130315 8402130318 8402130318 8402130356	8402130323 8402130330 8402130342 8402130351 8402130352	84/01/25 84/02/07 84/02/01 84/02/03 84/02/07	50-440 G 50-331 F XFORTLIC 50-280 F XPORTLIC
2130077 2130080 2130081 2130083 2130087	8402130013 8402130013 8402130013 8402130013 8402130074	83/12/21 83/12/21 83/12/21 83/12/21 84/01/27	FOIA FOIA FOIA FOIA CONTRACT		8402130364 8402130365 8402130366 8402130370 8402130372	8402130347 8402130341 8402130342 8402130347 8402130347	84/02/01 84/02/08 84/02/07 84/02/08 84/02/08	71-1 50-295 F 50-335 F 50-483 G 50-483 G
2130089 2130097 2130103 2130104 2130108	8402130013 8402130013 8402130013 8402130078 8402130007	83/12/21 83/12/21 83/12/21 84/02/04 83/11/10	FOIA FOIA FOIA CONTRACT 50-528	G	8402130388 8402130408 8402130400 8402130422 8402130445	8402130384 8402130402 8402130407 8402130417 8402130441	84/01/26 84/02/07 84/01/23 84/02/07 84/02/02	50~344 F XPORTLIC 70~2960 50~413 A 50~333 0
2130109 2130115 2130119 2130121 2130122	8402130013 8402130013 8402130013 8402130118 8402130007	83/12/21 83/12/21 83/12/21 83/12/21 83/11/10	FOIA FOIA FOIA 50-320 50-528	P A	8402130447 8402130457 8402130462 8402130462 8402130502	8402130446 8402130451 8402130455 8402130465 8402130495	84/02/03 84/01/30 84/02/07 84/01/26 84/01/27	50-320 G 50-335 F 50-263 G XPORTLIC MISC
2130123 2130127 2130131 2130134 2130137	8402130118 8402130007 8402130013 8402130007 8402130013	84/01/31 83/11/10 83/12/21 83/11/10 83/12/21	50-320 50-528 FOIA 50-528 FOIA	p A	8402130508 8402130510 8402130513 8402130518 8402130518	8402130495 8402100025 8402100025 8402100025 8402130515	89/01/27 84/02/07 84/02/07 84/02/07 84/02/06	MIBC 50-322 C 50-322 G 50-322 G 50-483 M
2130141 1130142 1130143 1130147 1130149	8402130130 8402130137 8402130007 8402130139 8402130146	84/02/02 84/02/02 83/11/10 84/02/02 84/01/31	CONTRACT XPORTLIC 50-528 XPORTLIC 50-320	A	8402130521 8402130524 8402130527 8402130531 8402130533	8402100023 8402100025 8402130498 8402130527 8402130498	84/02/07 84/02/07 83/11/28 84/02/06 83/11/28	50-322 0 50-322 0 50-247 F 50-454 0 50-286 F
1130150 1130152 130154 130158 130157	8402130007 8402130146 8402130151 8402130151 8402130153	83/11/10 84/01/31 84/01/27 84/01/27 84/02/01	FOIA 50-320 50-336 50-336 50-324	₽ የ የ	8402130534 8402130538 8402130540 8402130543 8402130544	8402130527 8402130478 8402130536 8402130527 8402130478	84/02/06 93/11/28 84/01/27 84/02/06 83/11/28	50~454 C 50~289 F XPORTLIC 50~454 G 50~289 P
130167 130168 130170 130171 130173	8402130163 8402130007 8402130165 8402130163 8402130163	84/02/02 83/11/10 84/02/08 84/02/02 84/02/02	50-483 50-528 50-322 50-483 50-483	F A G F F	8402130547 8402130552 8402130553 8402130554 84021305442	8402130478 8402130541 8402280168 8402130527 8402130559	83/11/28 84/01/25 84/02/23 84/02/06 84/02/06	50-287 F 50-257 F 50-410 G 50-454 G CONTRACT
130174 130178 130182 130187 130188	8402130007 8402130163 8402130007 8402130177 8402130184	83/11/10 84/02/02 83/11/10 84/02/07 84/02/09	50-528 50-483 50-528 50-286 50-412	A F A P K	8402130364 8402130367 8402130368 8402130371 8402130638	8402130541 8402130541 8402130539 8402130541 8402130433	84/02/04 84/02/04 84/02/07 84/02/04 84/02/06	50-349 F 50-349 F XFORTLIC 50-349 F PROJ
130179 130202 130205 130211 30217	8402130174 8402130176 8402130176 8402130007 8402130007	84/02/02 84/01/23 84/01/23 83/11/10 83/11/10	50-286 50-331 50-331 50-528 50-528	Р Р А А	8402130443 8402140027 8402140027 8402140033 8402140034	8402130623 8402140024 8402140020 8402140020 8402140030	84/02/02 84/01/26 83/12/07 83/12/07 84/02/06	TOPREP 50~250 F FOIA FOIA CONTRACT
30221 30227 30232 30232 30234 30237	8402130007 8402130007 8402130007 8402130004 8402130007	83/11/10 83/11/10 83/11/10 83/12/30 83/11/10	50-528 FOIA 50-528 FOIA 50-528	A A	9402140035 8402140039 8402140040 8402140044 8402140047	8402140021 8402140020 8402130418 8402140020 8402140047	84/01/26 83/12/07 83/12/05 83/12/07 84/02/10	50-250 F FOIA 70-1257 FOIA 50-322 G

ACCESSIO	N NUMBER				ACCESSIO	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 19SUED	CATEGO	RY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEGOR'	Y
8402140050 8402140051 8402140055 8402140058 8402140062	8402140020 8402140047 8402140020 8402140047 8402140020	83/12/07 84/02/10 83/12/07 84/02/10 83/12/07	FOIA 50-322 FOIA 50-322 FOIA	0	8402140337 8402140343 8402140343 8402140347 8402140349	8402140332 8402140332 8402140339 8402140342 8402140332	84/02/06 84/02/06 84/01/31 84/02/03 84/02/06	GA777 GA777 50-410 50-348 GA777	g P
8402140063 8402140067 8402140080 8402140084 8402140088	8402140059 8402140064 8402140074 8402140077 8402140020	84/01/13 84/01/31 84/02/07 84/01/09 83/12/07	70-1201 50-458 04799 50-390 FOLA	K G	8402140356 8402140358 8402140357 8402140379 8402140380	8402140350 8402140352 8402140362 8402140372 8402140375	84/01/06 84/01/03 84/01/11 84/01/25 84/01/10	50-321 50-259 50-369 50-344 70-1151	G G G
8402140104 8402140104 8402140108 8402140110 8402140112	8402140020 8402140093 8402140020 8402140093 8402140106	83/12/07 84/02/03 83/12/07 84/02/03 84/01/19	FOIA 50-259 FOIA 50-259 50-259	G G	8402140389 8402140394 8402140407 8402140411 8402140411	B402140377 B402140390 B402140403 B402140404 B402140404	84/02/07 84/02/07 84/01/13 84/01/30 84/01/30	50-261 50-261 70-27 50-400 50-400	P P Q G
8402140119 8402140121 8402140126 8402140129 8402140130	8402140020 8402140106 8402140106 8402140020 8402140127	83/12/07 84/01/19 84/01/19 83/12/07 84/02/06	FOIA 50-259 50-259 FDIA 50-247	g G	8402140422 8402140424 8402140428 8402140427 8402140433	8402140398 8402140420 8402140423 8402140420 8402140420	83/11/30 84/02/03 84/01/12 84/02/03 84/02/03	50-245 50-259 70-824 50-259 50-259	9 0 0
8402140132 8402140133 8402140136 8402140139 8402140142	8402140093 8402140127 8402140106 8402140124 8402140093	84/02/03 84/02/06 84/01/19 84/01/31 84/02/03	50-257 50-247 50-259 50-206 50-259	0 0 0 0	8402140437 8402140440 8402140442 8402140443 8402140444	8402140435 8402140404 8402140438 8402140420 8402140404	84/01/13 84/01/30 84/01/31 84/02/03 84/01/30	50-395 50-400 Tüprep 50-259 50-400	() () () ()
8402140145 8402140146 8402140148 8402140149 8402140153	8402140140 8402140141 8402140073 8402140143 8402140143	84/01/11 84/02/10 84/02/03 84/01/31 84/01/31	50-366 50-275 50-259 50-269 50-269	0 0 0 0	8402140445 8402140448 840214054 8402140454 8402140457	8402140434 8402140436 8402140404 8402140436 8402140452	84/01/25 84/02/04 84/01/30 84/02/06 84/02/10	50-397 50-321 50-400 50-321 50-388	O P G P A
8402140154 8402140157 8402140160 8402140164 8402140165	8402140147 8402140143 8305180559 8402140093 8402140159	84/01/17 84/01/31 83/05/16 84/02/03 84/01/12	50-321 50-269 50-412 50-259 50-348	0 0 A 0	8402140459 8402140464 8402140464 8402140461 8402140484	8402140453 8402140454 8402140466 8402140466 8402140482	84/02/10 84/02/02 84/01/31 84/01/31 84/02/08	50-424 50-266 50-275 50-275 50-454	I G Q G A
8402140167 8402140173 8402140183 8402140192 8402140198	8402140143 8402130013 8402140182 8402140188 8402140197	84/01/31 83/12/21 84/01/12 84/02/09 84/01/10	50-269 FOIA 50-348 50-482 50-390	G G A G	8402140487 8402140497 8402140497 8402140498 8402140498	8402140486 8402140486 8402140488 8402140473 8402140486	83/12/02 83/12/02 83/12/28 84/01/26 83/12/02	50-306 50-306 MIBC 50-424 50-307	9 0 8
8402140201 8402140209 8402140210 8402140211 8402140212	8402140199 8402140199 8402140202 8402140203 8402140199	84/02/06 84/02/06 84/02/03 84/01/12 84/02/06	GA959 GA959 30-155 50-269 GA559	o 0	9402140501 9402140504 9402140506 9402140507 9402140507	8402140493 8402140486 8402140493 8402140500 8402140486	84/01/24 83/12/02 84/01/26 84/02/03 83/12/02	50-424 50-309 50-424 50-261 FOIA	0 8 0
84021 40215 84021 40216 84021 40220 84021 40232 84021 40233	84021 40202 84021 40207 84021 40202 84021 40229 84021 40228	84/02/03 84/01/17 84/02/03 84/01/31 84/01/27	50-155 50-414 50-155 50-324 50-344	0 0 0	8402140512 8402140516 8402140517 8402140520 8402140522	8402140493 8402140486 8402140514 8402140486 8402140486	84/01/26 83/12/02 84/02/06 83/12/02 83/12/02	50-424 50-287 71-313 50-287 FOIA	Q P
84021 40234 84021 40248 84021 40250 84021 40251 84021 40252	8402140219 8402140241 8402140246 8402140246 8402140243	84/02/06 84/01/19 84/01/27 84/01/27 84/01/20	50-293 50-324 50-327 50-327 50-259	0 0 0	8402140584 8402140535 8402140549 8402140507 8402140508	8402140484 8402140531 8402140546 8402140604 8402140507	83/12/02 84/01/12 84/02/01 84/01/31 84/01/27	50-317 71-451 XPORTLIC 71-513 50-324	8 P
8402140253 8402140255 8402140259 8402140263 8402140266	8402140242 8402140246 8402140246 8402140243 8402140242	84/01/18 84/01/27 84/01/27 84/01/20 84/01/18	50-335 50-327 50-327 50-259 50-335	0 0 0 0	8402140615 8402140621 8402140623 8402140623 8402150004	8402140618 8402140618 8402140619 8402140618 8402150003	84/02/08 83/12/06 83/12/27 83/12/06 84/01/26	71-133 71-9080 71-9187 71-9080 50-443	a
8402140269 8402140271 8402140275 8402140276 8402140280	8402140262 8402140243 8402140248 8402140243 8402140262	84/01/26 84/01/20 84/01/18 84/01/20 84/01/26	50-413 50-259 50-335 50-259 50-413	G G G	84021 50006 84021 50007 84021 50016 84021 50016 84021 50017	B402150005 B402150005 B402150011 B402150015 B402150012	84/01/31 84/01/31 84/01/17 84/02/02 84/01/17	50-213 50-213 50-269 50-483 50-269	0 0 0
8402140283 8402140284 8402140286 8402140290 8402140294	8402140242 8402140279 8402140262 8402140262 8402140262	84/01/18 84/01/23 84/01/26 84/01/26 84/01/26	50-335 50-397 50-413 50-413	0 0 0 0	84021 50022 84021 50026 84021 50030 84021 50042 84021 50048	B402150020 B402150021 8402150029 B402150025 B402150025	84/02/09 84/01/23 84/01/23 83/11/10 83/11/10	50-280 XPDRTLIC XPDRTLIC 71-6058 71-6058	P
8402140298 8402140300 8402140303 8402140308 8402140311	8402140271 8402140273 8402140242 8402140277 8402140306	64/01/25 64/01/19 64/01/16 63/12/26 64/01/17	70-143 50-324 50-335 GA999 50-413	g g g	8402150126 8402150138 8402150147 8402150147 8402150153	8402150118 8402150133 8402150134 8402150133 8402150133	64/01/12 64/02/09 64/01/23 64/02/09 64/02/09	GA999 50~155 50~390 50~155 50~155	9 9 9
8402140314 8402140315 8402140320 8402140324 8402140329	8402140306 8402140306 8402140306 8402140317 8402140326	64/01/17 64/01/17 64/01/17 84/02/10 64/02/06	50-413 50-413 50-413 40-299 50-317	0 9 9	8402150154 8402150157 8402150166 8402150168 8402150170	8402150147 8402150152 8402150160 8402150163 8402150163	84/02/10 84/01/20 84/02/07 84/01/30 84/01/30	50-335 50-413 50-271 50-354 50-354	P

ACCESS10	N NUMBER				ACCESSION NUMB	IER			
VOLOSURIE	PRINCIPAL DOCUMENT	DATE 198UED	SUBJECT CATEGOR			CIPAL UMENT	DATE ISSUED	CATEC:	
102150177 102150181 102150186 102150203 102150215	8402150172 8402150174 8402170118 8402150199 8402150208	84/02/06 84/02/01 84/01/12 84/02/06 84/02/10	50-409 50-358 GA999 50-302 50-445	F G	8402150338 8402 8402150537 8402 8402150548 8402 8402150578 8402	11 50522 11 50532 11 50547 11 50570	84/02/02 84/02/10 84/02/10 84/01/24 84/01/30 84/01/27	50-220 71-6601 70-2988 WASTE N	
02150217 02150223 02150229 02150237 02150242	8402150207 8402150207 8402150220 8402150221 8402150239	84/02/07 84/02/07 84/01/17 84/02/08 84/01/31	50-346 50-346 50-390 50-259 50-271	Р О Б	840216000B 8402 8402160012 8402 8402160015 8402	160003 160003 160003 160003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	50-537 F01A 50-382 F01A 50-322	A A
02150243 02150245 02150247 02150253 12150254	84 021 50238 84 021 50237 84 021 50240 84 021 50246 84 021 50247	84/01/20 84/01/31 84/02/03 84/01/19 84/02/03	50-261 50-271 50-454 50-413 50-6	0 0 0	8402140023 8402 8402140023 8402 8402160029 8402	160003 160014 160003 160014 160003	83/12/14 84/02/09 83/12/14 84/02/09 83/12/14	FOIA 50-289 50-322 50-289 50-537	P A P A
2150254 2150257 12150258 12150242 12150245	8402150236 6402150250 6402150252 8402150252 8402150252	84/01/20 84/02/03 84/02/08 84/02/08 84/02/08	50-413 50-10 50-261 50-261 50-261	0 0 0	8402160035 8402 8402160037 8402 8402160041 8402	160003 160003 160003 160003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	FOIA FOIA FOIA FOIA 50-3	P
2150248 2150273 2150277 2150279 2150280	8402150263 8402150252 8402150269 8402150267 8402150278	84/02/03 84/02/08 84/02/04 84/02/09 84/02/07	50-331 50-261 50-366 50-338 50-271	0 0 P P	8402160049 8402 8402160050 8402 8402160052 8402	160003 160003 160003 160003 160044	83/12/14 83/12/14 83/12/14 83/12/14 84/01/25	50-275 FOIA FOIA FOIA 50-336	P
5120555 5120560 5120568 5120569 5120565	8402150269 8402150283 8402150269 8402150269 8402150269	84/02/06 84/02/07 84/02/06 84/02/06 84/02/06	50-366 50-271 50-366 50-366 50-366	0 0 0 0	8402160057 8402 8402160060 8402: 8402160063 8402:	160003 160003 160003 160026 160003	83/12/14 83/12/14 83/12/14 84/01/19 83/12/14	FOIA FOIA FOIA CONTRAC FOIA	т
21 50294 21 50300 21 50301 21 50304 21 50305	8402150269 8402150274 8402150297 8402150274 8402150302	84/02/06 84/02/06 84/02/06 84/02/06 84/01/31	50-366 50-413 50-255 50-413 50-412	G R G	8402140066 8402; 8402160067 8402; 8402160070 8402;	60003 60003 60003 60003 60003	83/12/14 83/12/14 83/12/14 83/12/14 93/12/14	FOIA FOIA FOIA FOIA	
1150308 1150310 1150312 1150313 1150314	8402150274 8402150274 8402150274 8402150311 8402150309	84/02/06 84/02/06 84/02/06 84/02/09 84/01/31	50-413 50-413 50-413 50-382 50-334	0 0 E 0	8402160073 84021 8402160074 84021 8402160075 84021	60003 60003 60003 60003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	50-275 FOTA FOTA FOTA FOTA	P
150315 150320 150323 150324 150328	8402150274 8402150319 8312120160 8312120160 8402150325	84/02/06 84/02/10 84/01/24 84/01/24 84/01/31	50-413 50-282 50-275 50-275 50-220	0 8 8	8402160079 84021 8402160081 84021 8402160082 84021	60003 60003 60003 60003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	FOIA 50-289 FOIA FOIA	Þ
150329 150331 150337 150338 150343	8312120160 8402150330 8402150335 8402150330 8402150340	84/01/24 84/02/09 84/01/25 84/02/09 84/01/18	50-275 50-329 70-143 50-329 50-336	B A A P	9402160085 84021 8402160086 84021 8402160087 84021	60003 60003 60003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	FOIA 50-275 FOIA FOIA FOIA	р
150353 150365 150372 150377 150378	8402150350 8402150361 8402150364 8402150368 8402150373	84/02/02 84/02/07 84/01/31 84/02/02 84/01/18	50-454 50-443 50-454 50-266 50-389	0 0 0	8402160091 84021 8402160092 84021 8402160093 84021 8402160094 84021 8402160095 84021	88000 60003 60003	83/12/14 84/02/10 83/12/14 83/12/14 83/12/14	50-275 50-364 FDIA FDIA FOIA	P
50382 50384 50386 50387 50392	8402150364 8402150379 8402150368 8402150380 8402150370	84/01/31 84/01/18 84/02/02 84/02/08 84/02/03	50-454 50-395 50-266 50-327 50-423	0 0 0 0 A	8402160096 84021 8402160097 84021 8402160098 84021 8402160099 84021 8402160102 84021	60003 60003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	50-289 FOIA FOIA FOIA 50-289	P P
50394 50399 50402 50412 50417	8402150389 8402150397 8402150389 8402150408 8402150415	84/02/10 84/02/03 84/02/10 84/01/30 84/02/04	50-412 50-492 50-412 50-361 GDNTRACT	A A P	8402160103 84021 8402160104 84021 8402160105 84021 8402160107 84021 8402160107 84021	60003 50003 50003	83/12/14 83/12/14 83/12/14 83/12/14 84/01/20	FOIA 50-443 FOIA FOIA 50-334	A P
50421 50423 50435 50444 50448	8402150418 8402150420 8402150430 8402150440 8402150440	84/01/26 84/01/31 84/02/06 84/01/20 84/01/20	71-193 50-352 50-352 50-346 50-346	G A P P	8402160109 840216 8402160110 840216 8402160112 840216 8402160114 840216 8402160115 840216	50003 50003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	FOIA 50-275 FOIA FOIA FOIA	P
30452 30457 30492 30506 30510	8402150446 8402150446 8402150489 8402150503 8402150503	84/01/30 84/01/30 84/02/01 84/02/06 84/02/06	50-269 50-269 XPORTLIC 50-309 50-309	P H H	8402160116 840218 8402160117 840218 8402160118 840218 8402160119 840218 8402160120 840218	50003 50003	83/12/14 83/12/30 83/12/14 83/12/14 83/12/14	AIOA 50-336 FOIA FOIA FOIA	G
0514 0518 0524 0529 0531	8402150503 8402150503 8402150516 8402150522 8402150522	84/02/06 84/02/06 84/01/24 84/02/02 84/02/02	50-309 CONTRACT 50-220	Н Н Р	8402160121 840216 8402160122 840216 8402160123 840216 8402160124 840216 8402160126 840216	0003 0003		FOIA FOIA 50-289 FOIA FOIA	P

ACCESSI	DN NUMBER				ACCESSIO	ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC	ЯY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISBUED	SUBJEC CATEGO	
8402160128 8402160129 8402160131 8402160132 8402160133	8402160003 8402160003 8402160003 8402160003	83/12/14 83/12/14 83/12/14 83/12/14	FOIA FOIA FOIA FOIA		8402160240 8402160243 8402160243 8402160246 8402160248	8402160003 8402160003 8402160003 8402160003 8402160003	03/12/14 03/12/14 03/12/14 03/12/14 03/12/14	FOIA FOIA FOIA FOIA FOIA	
8402160134 8402160135 8402160136 8402160136 8402160140	8402140003 8402140003 8402140003 8402140003 8402140003	83/12/14 63/12/14 83/12/14 83/12/14 83/12/14	FOIA FOIA FOIA FOIA		8402160249 8402160250 8402160253 8402160253	8402160003 8402160003 8402160003 8402160003 8402160003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	FOIA FOIA FOIA 50-546 FOIA	A
8402160142 8402160143 8402160144 8402160145 8402160146	8402140003 8402140003 8402140003 8402140003 8402140003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	FDIA 50-267 50-367 50-369 FDIA	P A P	8402160256 8402160257 8402160259 8402160259 8402160261	8402160003 8402160003 8402160003 8402160003 8402160003	63/12/14 63/12/14 63/12/14 63/12/14 63/12/14	FOIA FOIA FOIA 50-244 FOIA	P
8402160149 8402160150 8402160151 8402160152 8402160153	8402160003 8402160003 8402160003 8402160003 8402160003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	FDIA FOIA 50-269 FOIA FOIA	P	8402160263 8402160265 8402160266 8402160268 8402160269	8402140003 8402140003 8402140003 8402140003 8402160003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	FOIA FOIA FOIA FOIA	
8402160199 8402160196 8402160198 8402160160 8402160161	8402160003 8402160003 8402160003 8402160003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	FOIA FOIA FOIA FOIA		B402140272 B402160273 B402160274 B402160275 B402160279	8402160003 8402160003 8402160003 8402160003 8402160003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	FOIA FOIA FOIA FOIA FOIA	
8402160162 8402160163 8402160165 8402160166 8402160167	8402160003 8402160003 8402160003 8402160003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	FOIA FOIA FOIA 50-289 FOIA	Р	8402160280 8402160281 8402160282 8402160283 8402160283	8402160003 8402160003 8402160270 8402160276 8402160003	83/12/14 83/12/14 84/02/01 84/02/02 83/12/14	FOIA FOIA 50-423 50-213 FOIA	G G
8402160169 8402160171 8402160172 8402160172	8402160003 8402160003 8402160003 8402160003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	FOIA FOIA FOIA FOIA		8402160286 8402160287 8402160288 8402160289 8402160291	8402160277 8402160003 8402160276 8402160003 8402160003	83/12/12 83/12/14 84/02/02 83/12/14 83/12/14	TOPREP 50-289 50-213 FOIA FOIA	P G
8402160175 8402160177 8402160178 8402160179 8402160182	8402160003 8402160003 8402160003 8402160003 8402160003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	FOIA 50-269 FOIA FOIA FOIA	P	9402160295 8402160297 6402160300 8402160301 8402160302	8402160093 8402160003 8402160003 8402160003	84/02/07 83/12/14 83/12/14 84/02/01 83/12/14	50-409 FOIA FOIA 50-271 FOIA	P Gr
8402160183 8402160184 8402160185 8402160186 8402160187	6402160003 6402160003 6402160003 6402160003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	FOIA FOIA FOIA FOIA		9402160303 9402160304 8402160308 9402160308 9402160311	8402140003 8402140003 8402140003 8402140003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	FOIA FOIA FOIA FOIA 50-289	P
8402160188 6402160190 8402160191 8402160192 6402160193	8402160181 8402160003 8402160003 8402160003	84/02/07 83/12/14 83/12/14 83/12/14 83/12/14	50-266 FOIA FOIA FOIA FOIA	þ	8402160313 8402160315 8402160316 8402160317 8402160317	8402160003 8402160312 8402160003 8402160003	83/12/14 84/02/02 83/12/14 83/12/14 83/12/14	FOIA 50-443 50-352 50-287 FOIA	G A P
402160194 402160195 402160198 102160199 102160200	84021 60003 84021 60181 84021 60003 84021 60003 84021 60003	83/12/14 84/02/07 83/12/14 83/12/14 83/12/14	FOIA 50~244 FOIA FOIA FOIA	₽	8402140320 8402140322 8402140324 8402160325 8402140328	8402160003 8402160003 8402160003 8402160003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	FOIA FOIA FOIA FOIA	
02160202 02160204 02160205 02160206 2160207	84021 40003 84021 40003 84021 40003 84021 40003 84021 40201	83/12/14 83/12/14 83/12/14 83/12/14 84/02/14	FOIA FOIA FOIA FOIA 50-400	G	8402160329 8402160330 8402160332 8402160333 8402160335	8402160003 8402160003 8402160003 8402160310 8402160003	83/12/14 83/12/14 83/12/14 84/02/01 83/12/14	FOIA FOIA FOIA 50-277 FOIA	a
160208 160210 60212 50215 19216	8402160003 8402160003 8402160003 8402160003 8402160003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	FOIA FOIA FOIA FOIA		84021 60338 84021 60339 84021 60341 84021 60342 84021 60342	8402160003 8402160331 8402160003 8402160003	83/12/14 84/02/01 83/12/14 83/12/14	FOIA 50-317 FOIA FOIA FOIA	G.
53 51 50 51	8402160003 8402160003 8402160003 8402160219 8402160003	83/12/14 83/12/14 83/12/14 84/02/14 83/12/14	FOIA FOIA FOIA 50-322 FOIA	G	84021 60345 84021 60346 84021 60348 84021 60347 84021 60350	8402140003 8402140003 8402160003 8402160003 8402160003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	FDIA FDIA FDIA FOIA FOIA	
	8402140003 8402140222 8402140003 8402140003	83/12/14 84/02/13 83/12/14 83/12/14 84/02/13	FDIA 50-454 FDIA FDIA 50-454	G G	8402140352 8402160354 8402160355 8402160355 8402160357	8402160003 8402160003 8402160003 8402160347 8402160003	83/12/14 83/12/14 83/12/14 84/01/23 83/12/14	FOIA FOIA 50-358 50-445 FOIA	A G
	8402140028 6402140003 8402140003 8402140003 8402140003	84/02/10 83/12/14 83/12/14 83/12/14 83/12/14	50-321 FDIA 50-250 FDIA FDIA	P	B40214035B 8402160340 8402160361 B402160362 B402160363	8402160036 8402160003 8402160003 8402160357 8402160003	84/02/07 83/12/14 '93/12/14 84/02/10 83/12/14	50-933 FOIA FOIA 50-287 FOIA	G F

ACCESSION	N NUMBER					ACCESSI	ON NUMBER			
ENCLOSURE	PRINCIPAL DECUMENT	DATE IBSUED	CATEOD	łY.		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC	
E4021 40344 E4021 40345 E4021 40348 E4021 40373 E4021 40375	8402140003 8402140003 8402140003 84021400351 8402140003	83/12/14 83/12/14 83/12/14 84/02/02 83/12/14	FOIA FOIA 50~3 50~334 FOIA	р G		8402160511 8402160512 8402160514 8402160515 8402160516	8402160498 8402160487 8402160487 8402160487 8402160487	84/02/10 84/01/27 84/01/27 84/02/07 84/01/27	50-424 TOPREP TOPREP 71-6679 TOPREP	C
8402160376 6402160379 6402160380 6402160383 6402160384	8402160003 8402160003 8402160003 8402160003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	50-289 FOIA FOIA FOIA 50-341	P		8402160518 8402160518 8402160519 8402160520 8402160522	8402160498 8402160487 8402160487 8402160498 8402160498	84/02/10 84/01/27 84/01/27 84/02/10 84/02/10	50-424 TOPREP TOPREP 50-424 50-424	c c c
24021 60387 24021 60388 24021 60389 54021 60391 34021 60393	8402160381 8402160003 8402160003 8402160385 8402160003	84/02/14 83/12/14 83/12/14 84/02/01 83/12/14	50-255 FOIA FOIA 50-245 50-289	p P		8402160525 8402160526 8402160527 8402160528 8402160529	8402160487 8402160498 8402160487 8402160498 8402160487	84/01/27 84/02/10 84/01/27 84/02/10 84/01/27	TOPREP 50-424 TOPREP 50-424 TOPREP	c c
94021 60394 94021 60397 94021 60398 94021 60399 94021 60401	8402160003 8402160003 8402160003 8402160392 8402160003	83/12/14 83/12/14 83/12/14 84/02/01 83/12/14	50-528 FOIA FOIA 50-352 FOIA	A G		8402160531 8402160532 8402160534 8402160535 8402160536	8402160498 8402160487 8402150487 8402160487 8402160498	84/02/10 84/01/27 84/01/27 84/01/27 84/02/10	50-424 TOPREP TOPREP TOPREP 50-424	c c
14021 60402 14021 60406 14021 60407 14021 60407 14021 60410	8402160003 8402160003 8402160003 8402160003 8402160376	83/12/14 83/12/14 83/12/14 83/12/14 84/02/10	50-397 FOIA 50-289 FOIA 50-424	A P C		8402160538 8402160539 8402160544 8402160545 8402160550	8402160487 8402160498 8402160498 8402160498 8402160498	84/01/27 84/02/10 84/02/10 84/02/10 84/02/10	TOPREP 50-424 50-424 50-424 50-424	000
H02160411 H02160412 H02160413 H02160416 H02160418	8402160003 8402160003 8402160003 8402160003 8402160003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	FOIA 50~287 FOIA FOIA FDIA	ħ		8402160552 8402160570 8402160573 8402160574 8402160604	8402150498 8402150588 8402150581 8402150588 8402150502	84/02/10 84/02/02 84/02/01 84/02/02 84/02/09	50-424 50-266 50-313 50-266 70-2932	C P P
402160419 402160420 402160421 402160422 402160423	8402160408 8402160003 8402160003 8402160003	84/01/18 83/12/14 83/12/14 83/12/14 83/12/14	50~265 50~275 FOIA 50-344 FOIA	Q P P		8402160605 8402160618 8402160683 8402160685 8402160688	8402160600 8402160614 8402160682 8402160684 8402160686	84/02/01 84/01/31 84/02/08 84/02/07 84/01/31	50-338 WASTE MC CONTRACT CONTRACT	r r
402160426 402160427 402160428 402160430 402160431	8402160003 8402160003 8402160003 8402160003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	FOIA FOIA FOIA FOIA			8402170003 8402170012 8402170016 8402170018 8402170024	8402170002 8402170008 8402170014 8402170015 8402170007	84/01/27 84/01/31 84/01/02 84/02/09 84/02/09	WASTE MO CONTRACT CONTRACT 50-317 50-289	r
4021 60434 4021 60435 4021 60436 4021 60439 4021 60440	8402160003 8402160003 8402160003 8402160003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	FOIA FOIA FOIA FOIA FOIA			8402170026 8402170027 8402170028 8402170030 8402170031	8402170023 8402170007 8402170023 8402170017 8402170029	84/02/09 84/02/09 84/02/09 84/02/08 84/02/01	50-348 COMMISSI 50-348 CONTRACT	p
402160441 402160442 402160443 402160444 402160445	8402160003 8402160003 8402160003 8402160003 8402160003	83/12/14 83/12/14 83/12/14 83/12/14 83/12/14	FDIA FOIA FOIA FOIA FOIA			8402170045 8402170049 8402170063 8402170054 8402170065	8402170044 8402170022 8402170057 8402170057 8402170062	84/01/30 84/02/14 84/02/01 84/02/01 84/01/19	50-245 50-322 50-220 50-220 CONTRACT	P G P
1021 60446 1021 60448 1021 60450 1021 60454 1021 60455	8402160003 8402160003 8402160447 8402160452 8402160453	83/12/14 83/12/14 84/02/08 84/02/01 84/01/23	50-3 FOIA 50-397 50-309 50-29	P Q P		8402170068 8402170069 8402170075 8402170077 8402170078	8402170057 8402170057 8402170073 8402170072 8402170073	84/02/01 84/02/01 84/02/03 84/02/02 84/02/03	50-220 50-220 50-395 50-263 50-395	р Р Р Р
1021 60460 1021 60462 1021 60469 1021 60460 1021 60481	8402160458 8402160459 8401190055 8402160479 8402160477	84/02/09 84/01/23 84/02/14 84/01/27 84/02/02	50-329 50-245 50-329 50-443 50-388	A B A Q	6 6	8402170080 8402170085 8402170088 8402170090 8402170092	8402170072 6402170081 8402170081 8402170086 8402170086	84/02/02 84/02/01 84/02/01 84/02/07 84/02/09	50-263 50-10 50-10 50-305 50-305	P G P P
021 60483 021 60485 021 60488 021 60489 021 60490	8402160479 8402160479 8402160487 8402160487 8402160487	84/01/27 84/01/27 84/01/27 84/01/27 84/01/27	50-443 50-443 TOPREP TOPREP	A	£ 8	3402170094 3402170118 3402170120 3402170125 3402170126	8402170094 8402170114 8402170115 8402170114 8402170119	84/02/13 84/02/13 84/02/13 84/02/13 84/02/15	50-352 50-322 9A979 50-322 50-445	G G G
021 &0491 021 &0492 021 &0493 021 &0494 021 &0495	8402160487 8402160487 8402160487 8402160487 8402160487	84/01/27 84/01/27 84/01/27 84/01/27 84/01/27	TOPREP TOPREP TOPREP TOPREP TOPREP		9 9	1402170132 1402170135 1402170137 1402170137 1402170139	8402170114 8402170124 8401190053 8402170114 8402170124	84/02/13 84/02/14 84/02/13 84/02/13 84/02/14	50-322 50-482 50-206 50-322 50-482	0 0 5 0
021 60497 021 60499 021 60500 021 60502 021 60503	8402150487 8402160498 8402160487 8402160498 8402160487	84/01/27 84/02/10 84/01/27 84/02/10 84/01/27	TOPREP 50-424 TOPREP 50-424 TOPREP	c c	8	402170144 402170148 402170150 402170153 402170158	8402170147 8402170114	64/02/13 84/02/07	50-322 50-322 CONTRACT 50-322 CONTRACT	<b>6</b>
02160505 02160506 02160508 02160509 02160510	8402160497 8402160498 8402160487 8402160487 8402160487	84/01/27 84/02/10 84/01/27 84/01/27 84/01/27	TOPREP 50-424 TOPREP TOPREP TOPREP	С	8 8	402170160 402170161 402170162 402170164 402170168	8402170157 8402170155	84/02/13 84/02/10 84/02/03	50-456 50-322 50-482 50-456 50-322	0 8 0 0

	N NUMBER				ACCESSIC	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188VED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATECUR	
8402170172	8402170114	84/02/13	50-322	0	8402170420	8402170338	84/02/10	50~361	ĸ
8402170180 8402170187	8402170114 8402170175	64/02/13 64/02/03	50-322 50-454	G	8402170421 8402170422	8402170338 8402170338	84/02/10 84/02/10	50-361 50-361	K
8402170188 8402170194	8402170114 8402170114	84/02/13 84/02/13	50-322 50-322	G	8402170423 8402170424	8402170338 8402170338	84/02/10 84/02/10	50-361 50-361	K
8402170205	8402170198	B4/02/09	71-6387		8402170426	8402170338	84/02/10	50-361	ĸ
8402170211 8402170212	8402170207 840217020B	84/01/30 83/11/28	50-373 50-250	0 8	8402170427 8402170432	8402170338 8402170338	84/02/10 84/02/10	146-08 146-08	K
8402170214	8402270034	84/02/14	50-416	P	8402170433	BEE0712048	84/02/10	50-361	K
8402170219 8402170230	8402170217 8402170225	83/12/01	FOIA CONTRACT		8402170435	840217033B 8402170338	84/02/10	50-361 50-361	K
8402170231	8402170228	84/02/16	50-206	P	B402170437	8402170338	84/02/10	50-361	К
8402170233	8402170114	84/02/13 84/01/30	50~322	G	8402170441 8402170442	8402170338 8402170338	84/02/10 84/02/10	50-361 50-361	K
8402170242 8402170245	8402170207 8402170239	84/02/02	50-373 CONTRACT	. a	8402170443	8402170440	84/02/10	50-297	P
8402170251 8402170268	8402170244 8402170253	84/02/14 84/01/31	50~409 CONTRACT	G	8402170446 8402170450	8402170338 8402170338	B4/02/10 B4/02/10	50-361 50-361	K
8402170276	8402170255	84/02/14	50-237	P	8402170455	8402170453	84/01/31	REGOD	•
6402170302 6402170313	84021 <i>7</i> 0299 84021 <i>7</i> 0299	84/02/03 84/02/03	50-315 50-315	G G	8402170466 8402170472	8402170464 8402170464	84/02/10 84/02/10	50-348 50-348	G G
8402170339	8402170338	84/02/10	50~361	к	8402170484	8402170476	84/02/09	CONTRACT	
8402170341	8402170338	84/02/10	1 &C-02	ĸ	B402170510	8402170506	84/02/02	50-286	F
8402170344 8402170345	8402170338 8402170338	84/02/10 84/02/10	50~361 50~361	ĸ	8402170524 8402170525	840217051B 8402170522	84/02/10 84/02/07	50-277 719009	P
8402170347	8402170338	84/02/10	148-06	К	8402170526	8402170518	84/02/10	50-277	P
8402170348 8402170350	8402170338 8402170338	84/02/10 84/02/10	50-361 50-361	ĸ	8402170527 8402210006	8402170522 8402210003	84/02/07 83/11/29	71-7009 50-498	Α
B402170351	8402170338	64/02/10	50-361	ĸ	8402210012	8402210003	83/11/29	50-49B	G
8402170352 8402170353	8402170338 8402170338	B4/02/10 84/02/10	50-361 50-361	K	8402210014 8402210017	8402210002 6402210003	84/01/27 83/11/29	CONTRACT 50-498	G
8402170354	8402170338	84/02/10	50-361	ĸ	8402210018	8402210003	83/11/27	50-498	Α
8402170355	8402170338	84/02/10	50-361	К	8402210020	8402210003	83/11/27	50-498	G
8402170357 8402170358	8402170338 8402170338	84/02/10 84/02/10	50-361 50-361	K	8402210025 8402210027	8402210022 8402210003	84/01/16 83/11/29	CONTRACT 50-498	a
8402170359	8402170338	84/02/10	50-361	K	B402210031	8402210003	83/11/29	50-478	ä
8402170361 8402170362	8402170338 8402170338	84/02/10 84/02/10	145-0 <b>5</b> 145-0 <b>5</b>	ĸ	8402210036 8402210037	B402210003 B402210030	83/11/29 84/02/06	50-498 CONTRACT	G
8402170363	8402170338	B4/02/10	50-361	ĸ	8402210040	8402210003	83/11/29	50-478	g
8402170364 8402170365	8402170338 8402170338	B4/02/10 B4/02/10	50-361 50-361	K K	8402210041 8402210044	8402210032 8402210038	83/12/27 84/02/13	CONTRACT CONTRACT	
B402170386	8402170338	84/02/10	50-341	и	8402210046	8402210003	83/11/29	50~49日	A
8402170367 8402170368	8402170338 8402170338	84/02/10 84/02/10	50-361 50-361	K	8402210047	B402210043	84/02/13	50-298 50-498	Ģ
8402170369	8402170338	84/02/10	50-361	ĸ	8402210049 8402210049	8402210003 8402210003	83/11/2 <b>7</b> 83/11/29	30-47B	A
B402170370	8402170338	84/02/10	50-341	K	6402210051	8402210003	83/11/29	50-498	A
8402170372 8402170373	8402170338 8402170338	84/02/10 84/02/10	30-361 50-361	K	B402210054 8402210060	8402210037 8402210045	84/02/05 84/02/13	CONTRACY	
B402170375	8402170338	84/02/10	50-361	ĸ	8402210064	8402210003	83/11/29	50-49B	Α
8402170376 8402170377	8402170338 8402170338	84/02/10 84/02/10	50-361 50-361	K	8402210068 8402210081	8402210003 8402210077	83/11/29 84/02/13	50-498 50-269	P
8402170379	8402170338	84/02/10	50-361	ĸ	8402210088	9402210095	84/02/13	CONTRACT	
9402170380 9402170381	840217 <i>0</i> 338 8402170338	84/02/10 84/02/10	50~361 50~361	ĸ	8402210102 8402210109	8402210096 8402210106	84/02/10 84/02/14	50-277 10CFR	F
0402170383	8402170338	84/02/10	50-361	ĸ	8402210158	8402210155	84/02/13	CONTRACT	
8402170384	8402170338	84/02/10	50-361	K	8402210172	8402210166	84/02/13	CONTRACT	_
8402170385 8402170388	8402170338 8402170338	84/02/10 84/02/10	50-341 50-361	K	8402210181 8402210184	8402210175 8402210174	84/02/16 84/02/13	50-269 50-269	P
8402170389	840217033B	84/02/10	50-361	ĸ	8402210191	8402210174	84/02/13	50-269	P
8402170390 8402170391	8402170338 8402170338	84/02/10 84/02/10	50-341 50-361	K	8402210207 8402210210	8402210200 8402210204	84/02/13 83/10/07	50-382 50-416	9 6
8402170393	8402170338	84/02/10	50-341	K	B402210219	8402210217	84/02/13	50-289	g
8402170394 8402170394	6402170338 8402170338	84/02/10 84/02/10	50-361 50-361	K	8402210259 8402210261	8402210251 8402210251	84/02/09 84/02/09	50-373 50-373	8
8402170397	8402170338	84/02/10	50~361	ĸ	8402210274	8402210271	84/02/15	50~329	R
8402170399	8402170338	84/02/10	50-361	K	8402210280	8401190059	84/02/13	50-275	P
8402170400 8402170402	8402170338 8402170338	84/02/10 84/02/10	145-05 145-05	K	8402210282 8402210285	8401190059 8402210284	84/02/13 84/01/13	50-275 40-299	P
8402170403 8402170406	8402170338	84/02/10	50-361	K	8402210311	8402210306	83/09/01	40-6659	
8402170407	8402170338 8402170338	84/02/10 84/02/10	14E-06	K	8402210315 8402210320	840221030 <i>6</i> 840221030 <i>6</i>	83/09/01 83/09/01	40-6659 40-6659	
8402170408	8402170338	84/02/10	50~361	ĸ	8402210323	8402210306	83/09/01	40-6659	
8402170409 8402170411	8402170338 8402170338	84/02/10 84/02/10		K	8402210334 8402210349	8402210326 8402210345	84/02/06 84/02/14	50-320 50-155	Ġ P
8402170412	8402170338	84/02/10	50-361	K	6402210351	8402210347	84/01/25	CONTRACT	
8402170413	9402170338	84/02/10	50~361	K	6402210353	8402210345	84/02/14	50-155	Q
8402170414 8402170415	9402170338 9402170338	84/02/10 84/02/10		K	8402210369 8402210380	8402210363 8402210375	84/02/02 84/01/27	CONTRACT WASTE MOT	
#40₽170416	840217033B	84/02/10	50-361	ĸ	8402210382	8402210378	<b>94/02/14</b>	50-387	F
8402170418 8402170419	8402170338 8402170338	84/02/10 84/02/10		K K	8402210411 8402210416	8402210398 8402210398	84/02/14 84/02/14	MISC	
SERIES PA."					WTWWALVTIG	- 14-FI0010		,	

ACCESSIO	N NUMBER				ACCESSION NUMBE	ir			
0√LOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC CATEGO		PRINC ENCLOSURE DOC		ATE	800750	
6402210424	8402210423	84/01/20	40-299				SVED  01/31	CATEGE CAPPP	
#02210439 #02210457	8402210419 8402210450	84/01/26 84/02/09	CONTRAC 50-373	T P	8402220377 84022	20371 84/4	01/13	50-482	a
H02210460	8402210328 8402210328	84/02/06 84/02/06	50-320 50-320	P P	8402220387 84022	20383 84/	01/30 01/31	9A999 50-313	ø
							01/27	9999	
H022210476 H02220005	8402210464 8402220004	84/01/31 84/02/16	CONTRAC 50-302	Р			01/16	50-382 GA999	G
#02220032 #02220037	8402220029 8402220036	84/02/14 84/02/17	50~278 50~498	PK	8402220397 84022	20383 84/0	01/20 01/26	50-313 98999	G
BC2220039	8402220035	84/02/15	50-483	F			01/20	50-313	G
H02220041	8402220035	84/02/15	50-483	F	84 <u>02220407</u> 84023		01/23	0A999	
110555-0078 110555-0028	8402220055 8402220066	84/02/14 84/02/16	50~247 50~247	P	8402220411 84022 6402220412 84022		02/16 02/17	70-1257 50-374	F
H022220077	8402220071 8402220074	84/02/16 84/02/15	50~269 50~289	F	8402220414 84022 8402220416 84022	20403 8470	01/23 02/17	0A999 50-373	0
H02220107	8402220101	83/09/24	40-8769	_					ŭ
H3555011B	8402220116	B4/02/17	50-352	Q	8402220421 84022	20419 B4/0	02/16 01/24	70-1257 GA999	
805550155 805550150	6402220115 6402220116	84/02/14 84/02/17	50~354 50~352	G	8402220423 84022 8402220427 84022		)1/24 )1/24	0A777 0A777	
Hu5550154	8402220123	84/02/09	FOIA		8402220437 B4022		1/19	50-445	G
H02220132	840R220130	84/01/23	50~220 50~220	P	8402220438 84022		2/15	50-341	Q
H02220135 H02220142	8402220130 8402220139	84/01/23 83/11/01	50-220 50-397	Ð	8402220439 84022 8402220445 84022		)2/02 )1/23	0A999 50-462	G
#^2220147 #02220155	8402220144 8402220146	83/12/07 84/02/13	50-3 <b>97</b> 50-281	Q 5	8402220447 84022 8402220450 84022		2/15	40-1386 70-364	
902220160 902220164	8402220146 8402220146	84/02/13 84/02/13	50-281 50-281	8	6402220451 64022 6402220452 64022	20444 84/0	1/23 1/13	50-482 50-482	G.
8022220165 8022220165	8402220154 8402220159	83/11/30 84/02/07	50-280 50-358	5 0	8402220455 84022 8402220456 84022		)1/20 )2/13	50-285 50-387	G G
M5550182	8402220179	84/02/19	90-329	Ä	B40222045B B4022		2/14	70-754	_
302220188	8402220183	84/02/16	QA999		84022.20467 84022		2/04	50-322	G
%*2220200  %*2220203	8402220174 8402220178	84/02/16 84/02/17	50-309 50-322	Ģ	8402220470 84022 8402220474 84022		4/21 2/14	50-482 50-315	Gi Gi
#02220214 402220217	8402220174 8402220210	84/02/16 84/02/15	50-309 50~302	Q P	9402220475 84022 8402220474 84022		1/05 2/08	50-482 50-313	Gr Gr
302220218	B402220194	B4/02/16	50-309	G	8402220482 84022		2/16	50-443	a
102220224	8402220194	B4/02/16	50-309	Ģ	B402220484 84022	20480 83/1	5/53	50-298	œ
%5550535 %5550530	8402220194 8402220226	84/02/16 84/02/17	50-309 27-48	G	8402220488 84022 8402220491 84022			50-313 50-206	Q P
H02220248	8402220237	83/15/58	50-285	G	8402220475 84022			50-206	P
132220261	8402220257	84/01/10	50-298	Q	8402220496 84022			50~470	E
105550593 105550595	6402220254 6402220259	B4/02/14 B4/02/15	50-322 50-320	G F	8402220498 84022 8402220500 84022	0494 83/1		50-482 50-482	Q Q
102220265 102220265	8402220256 8402220267	84/01/23 84/02/17	9A999 50-400	o	8402220503 840222 8402220506 840222			50~482 50-285	Q Q
02220270	6402220244	84/02/15	50-373	G.	8402220508 840222	0400 84/0	1726	QA799	
P2220273	8402220268	84/02/06	50-245	G	8402220510 840222	0505 83/1	2/23	50-285	9
1/2220274 1/222 <b>027</b> 7	8402220274 8402220272	83/11/10 84/02/16	50-72 50-29	G G	8402220516 840222 8402220518 84022	0509 B4/0	1/18	50-348 50-285	P Q
03550580	8402220271	B4/01/10	50-313	G	940222052O 840222	0513 84/0	2/14	50-493	F
02220283 02220281	8402220278 8402220272	84/01/31 84/02/16	GA999 50-29	G	8402220521 840222 8402220524 840222			50~269 50~493	P F
12220289	8402220272	B4/02/16	50-29	G	8402220332 840222	0529 84/01	1/23	GA777 GA777	•
\$22 <b>2029</b> 7	8402220286 8402220274	84/02/10 84/02/17	50-219 27-39	P	8402220534 840222 8402220535 840222			50-278	G.
M2550300	8402220294	B4/02/17	50-352	т	8402220539 840222			50~413	E
#2220301 #2220306	8402220299 8402220296	84/02/16 84/02/17	9779 985-08	т	6402220341 640222 6402220342 640222			50-324 50-413	Q. E
<b>02220307</b>	8402220304	84/02/15	70-143		8402220346 840222 8402220347 840222	0538 84/02	2/15	50-413 50-413	Ē
3550303	8402220276	84/02/17	50-352	T	_,				
(55503)3 (55503)3	8402220294 8402220316	84/02/17 84/02/13	50-352 50-307	T G	8402220548 840222 8402220549 840222	0538 84/02	7/15	50-413 50-413	E
2220317 2220320	840222030B 8402220317	84/02/03 84/02/10	GA999 50-352	G.	8402220552 840222 8402220554 840222			50-413 50-413	E
3350353	8402220321	84/01/05	50-265	ă	8402220555 840222			50-413	Ē
12220324	8402220317	84/02/10	50-352	Q	8402220560 840222			50-413	E
2220326 2220327	8402220321 8402220317	84/01/05 84/02/10	50-265 50-352	G G	8402220561 840222 8402220563 840222	0538 84/02	2/15	30-413 50-413	E
2220328	8402220325	84/02/16	50-369 50-313	Ē	8402220566 840222 8402220568 840222			50-413 50-482	E Q
2220339	8402220338	83/12/23			9402220569 840222			50-413	E
7220341 7220342	8402220337 8402220340	84/01/10 84/02/14	50-285 50-483	G G	8402220572 840222	)538 <b>8</b> 4/02	715	30-413	E
2220345 2220348	8402220312 8402220344	84/02/15 84/02/15	50-274 50-352	Q Q	8402220573 840222 8402220575 840222		/15	50~413 50~413	Ē
2220348	8402220344	84/01/19	50-382	G	B402220579 B40222			50-413	E
220361	8402220354	83/12/23	70-1362		8402220580 8402220			50-413 50-413	E
9220347 9220348	8402220355 8402220365	84/01/18 84/01/20	50-313 50-458	Q G	8402220581 840222 8402220583 8402224	)538 B4/02	/15	50-413	E
2220372	6402220345	84/01/20	50~458 50~277	G G	8402220585 840222 8402220587 840222			50-413 50-413	E
220374	8402220364	84/02/09	JU-#11	u					

ACCESSIO	N NUMBER				ACCESSIO	ON NUMBER			
ENCLOSURE	PRINCIPAL DDCUMENT	DATE ISSUED	SUBJECT CATEGOR		ENCLOBURE	PRINCIPAL DOCUMENT	DATE ISBUED	SUBJECT CATEGOR	
8402220588 8402220589 8402220590 8402220591 8402220592	8402220538 8402220578 8402220538 8402220538 8402220584	84/02/15 83/11/28 84/02/15 84/02/15 84/02/06	50-413 50-313 50-413 50-413 50-454	E G	8402240023 8402240025 8402240025 8402240028 8402240038	8402240019 8402240019 8402240022 8402240021 8402240034	84/02/08 84/02/08 84/02/09 84/02/08 84/02/09	50-387 50-387 70-371 50-293 50-293	0 0
8402220593 8402220594 8402220595 8402220596 8402230038	8402220538 8402220538 8402220538 8402220578 8402230029	84/02/15 84/02/15 84/02/15 83/11/28 84/02/13	50-413 50-413 50-413 50-313 50-424	E E G A	8402240042 8402240045 8402240045 8402240047 8402240050	8402240039 8402240043 8402240039 8402240044 8402240044	84/02/09 83/12/09 84/02/09 84/02/09 84/02/09	50-293 FOIA 50-293 50-219 50-219	G G G
8402230053 8402230057 8402230064 8402230071 8402230075	8402230041 8402230041 8402230041 8402230027 8402230029	83/11/22 83/11/22 83/11/22 84/02/13 84/02/13	40-8452 40-8452 40-8452 50-424 50-424	A A	8402240057 8402240065 8402240065 8402240091	8402240054 8402240059 8402240062 8402240089 8402240090	84/02/22 84/02/22 84/02/09 84/02/09	50-416 50-416 50-382 50-277 50-387	G A G
8402230086 8402230091 8402230101 8402230105 8402230107	8402230076 8402230076 8402230095 8402230102 8402230104	84/01/26 84/01/26 84/02/10 84/01/20 84/02/22	40~297 40~299 50~354 70PREP 50~454	A Q	8402240095 8402240097 8402240098 8402240099 8402240105	8402240089 8402240096 8402240096 8402240081 8402240081	84/02/09 84/02/07 84/02/07 84/02/08 84/02/08	50-277 50-244 50-244 50-289 50-289	0 0 P 0
B402230108 B402230113 B402230116 B402230117 B402230120	B402230095 B402230095 B402230095 B402230111 B402230095	84/02/10 84/02/10 84/02/10 84/02/20 84/02/10	50-354 50-354 50-354 50-287 50-354	A A Q A	8402240106 8402240111 8402240114 8402240116 8402240118	8402240093 8402240110 8402240081 8402240112 8402240113	84/02/07 84/02/15 84/02/08 84/02/13 84/02/10	50-322 50-29 50-287 50-287 50-237	G P G P
8402230126 8402230136 8402230137 8402230141 8402230147	8402230095 8402230134 8402230134 640223013B 8402230142	84/02/10 84/02/17 84/02/17 84/02/20 84/02/09	50-354 50-206 50-206 50-155 70-364	А Р 9	8402240117 8402240122 8402240125 8402240127 8402240133	84022400B6 8402240112 84022400B6 84022400B6 840224012B	83/12/12 84/02/13 83/12/12 83/12/12 84/02/07	50-295 50-289 50-295 50-295 50-317	5 P S G
8402230147 8402230154 8402230157 8402230157 8402230166	8402230144 8402230150 8402230151 8402230152 8402230152	84/02/17 84/02/09 83/12/05 84/02/22 84/02/22	50~369 MISC 40~299 50-341 50-341	P K K	B402240134 B402240135 B402240139 B402240140 B402240141	8402240131 8402240086 8402240128 8402240137 8402240086	84/02/21 83/12/12 84/02/07 84/02/21 83/12/12	50-219 50-295 50-317 50-29 50-295	P G P S
8402230196 8402230199 8402230212 8402230214 8402230217	8402230190 8402230190 8402230202 8402230204 8402230202	84/02/17 84/02/17 84/02/14 84/02/22 84/02/14	50-286 50-286 50-269 50-409 50-269	P G F G	8402240143 8402240150 8402240160 8402240163 8402240163	8402240137 8402240153 8402240153 8402240153 8402240153	84/02/21 83/12/09 83/12/09 83/12/09 83/12/09	50-29 50-382 50-382 50-382	B G A A
B402230229 B402230232 B402230233 B402230234 B402230244	8402230225 8402230225 8402230223 8402230228 8401190064	84/02/17 84/02/17 84/02/15 84/02/20 84/02/16	50-397 50-397 50-438 50-416 50-302	F G S	8402240170 8402240178 8402240174 8402240197 8402240197	8402240153 8402240175 8402240175 8402240175 8402240179	83/12/09 84/01/13 84/01/13 84/01/13 84/02/07	50-382 FOIA FOIA FOIA 50-289	A
8402230272 8402230293 8402230295 8402230359 8402230360	8402230269 8402230292 8402230294 8402230353 8402230357	84/01/24 84/02/09 84/02/15 84/01/31 84/01/31	CONTRACT CONTRACT CONTRACT 50-333 FOIA	a	8402240209 8402240215 8402240220 8402240223 8402240231	8402240207 8402240214 8402240216 8402240219 8402240228	83/12/12 84/02/03 84/02/03 84/02/03 84/02/16	FOIA 50-315 50-220 FOIA CONTRACT	S R
8402230362 8402230365 8402230367 8402230368 8402230370	8402230357 8402230357 8402230363 8402230357 8402230357	84/01/31 84/01/31 84/02/08 84/01/31 84/01/31	FDIA FDIA 50-416 FDIA FDIA	P	8402240234 8402240237 8402240241 8402240244 8402240244	8402240216 8402240216 8402240216 8402240216 8402240216	84/02/03 84/02/03 84/02/03 84/02/03	50-220 50-220 50-220 50-220 50-220	F F P
8402230372 8402230374 8402230377 8402230379 8402230383	8402230357 8402230357 8402230357 8402230357 8402230357	84/01/31 84/01/31 84/01/31 84/01/31 84/01/31	FOIA FOIA FOIA FOIA FOIA		8402240249 8402240256 8402240257 8402240275 8402240333	8402240216 8402240254 8402240263 8402240277 8402240328	84/02/03 84/02/12 84/02/03 84/01/27 84/02/03	50-220 CONTRACT FDIA 50-352 FOIA	P A
8402230387 8402230390 8402230393 8402230394 8402230395	8402230357 8402230357 8402230357 8402230357 8402230371	84/01/31 84/01/31 84/01/31 84/01/31 84/01/09	FOIA FOIA FOIA FOIA 50-352	A	8402240337 840224034 8402240343 8402240360 8402240360	8402240307 8402240307 8402240307 8402240356 8402240340	83/12/14 83/12/14 83/12/14 84/02/13 84/02/02	50-287 50-287 50-287 XPORTLIC FOIA	P P
8402230400 8402230402 8402230413 8402230414 8402230424	8402230357 8402230357 8402230411 8402230410 8402230423	84/01/31 84/01/31 83/12/13 84/01/31 83/12/12	FOIA FOIA FOIA 50-263 FOIA	P	8402240367 8402240371 8402240379 8402270011 8402270013	8402240340 8402240368 8402240372 8402270009 8402270009	84/02/02 84/02/17 84/02/09 84/02/02 84/02/02	FDIA CONTRACT CONTRACT FOIA FOIA	
8402230427 8402230432 8402230434 8402230438 8402230439	8402230423 8402230427 8402230427 8402230436 8402230427	83/12/12 83/12/07 83/12/07 84/02/01 83/12/07	FOIA FOIA 50-309 50-333 50-322	O F G	8402270016 8402270024 8402270029 8402270031 8402270043	8402270009 8402270001 8402270001 8402270028 8402270001	84/02/02 83/12/12 83/12/12 84/02/21 83/12/12	FOIA 50-344 50-344 50-287 50-344	G F P F
8402230443 8402230446 8402240004 8402240008 8402240009	8402230442 8402230445 8402240002 8402240002 8402240002	83/12/12 84/02/16 84/02/09 84/02/09 84/02/21	FOIA CONTRACT 50-223 50-223 50-206	a a P	8402270054 8402270060 8402270062 8402270064 8402270065	8402270001 8402270056 8402270051 8402270051 8402270056	83/12/12 84/02/21 84/01/26 84/01/26 84/02/21	50-344 50-400 FOIA FOIA 50-400	F Q Q

ACCESSION	NUMBER				ACCESBI	ON NUMBER			
EXCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	CATEGO	ŤΥ	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJE CATEG	
6402270067 6402270069 6402270076 6402270080 6402270091	8402270051 8402270001 8402270073 8402270001 8402270001	84/01/26 83/12/12 84/02/17 83/12/12 83/12/12	50-382 50-344 50-445 50-344 50-344	G G G	8402270303 8402270305 8402270308 8402270311 8402270312	8402270250 8402270263 8402270250 8402270250 8402270306	84/02/08 84/01/30 84/02/08 84/02/08 84/02/01	FOIA 50-327 FOIA FOIA 50-413	-
5102270092 5102270095 5102270096 5102270098 5102270103	8402270072 8402270089 8402270090 8402270090 8402270090	83/12/22 84/02/09 84/02/21 84/02/21 84/02/21	FOIA 50-454 50-341 50-341 50-341	G A A	9402270317 940227031 9402270322 9402270324 9402270324	8402270306 8402270302 8402270250 8402270250 8402270263	84/02/01 84/01/20 84/02/08 84/02/08 84/01/30	FOIA 50-341 FOIA FOIA FOIA	٢
6402270105 6402270105 6402270107 6402270109 8402270114	8402270001 8402270090 8402270072 8402270090 8402270001	83/12/12 84/02/21 83/12/22 84/02/21 83/12/12	50-344 50-341 FDIA 50-341 50-344	Q A A G	8402270331 8402270337 8402270337 8402270341 8402270344	8402270263 8402270250 8402270263 8402270250 8402270263	84/01/30 84/02/08 84/01/30 84/02/08 84/01/30	FD1A F01A 50-320 F01A 50-320	_
8402270126 8402270127 8402270133 8402270136 8402270141	8402270001 8402270072 8402270072 8402270001 8402270072	63/12/22 63/12/22 63/12/22 63/12/12	50-344 FOIA FOIA 50-344 FOIA	F G	8402270347 8402270348 8402270351 8402270360 8402270361	8402270250 8402270338 8402270263 8402270263 8402270338	84/02/08 84/02/09 84/01/30 84/01/30 84/02/09	FDIA 50-255 50-327 50-271 50-255	a 0 0
8402270146 8402270147 8402270153 8402270154 8402270158	8402270001 8402270072 8402270147 8402270072 8402270072	83/12/12 83/12/22 84/02/17 63/12/22 84/02/22	50-344 F01A 50-373 F01A 50-313	F G	8402270363 8402270367 8402270370 8402270371 8402270373	8402270302 8311030079 8402270356 8402270263 8402270368	84/01/20 83/10/28 84/02/10 84/01/30 83/09/30	FOIA 50-128 50-315 50-369 50-265	S 0 0
8402270162 8402270165 8402270170 8402270171 8402270179	8402270072 8402270072 8402270072 8402270072 8402270072	63/12/22 63/12/22 63/12/22 64/02/22	FOIA FOIA FOIA 50-285 FOIA	Q	8402270374 8402270375 8402270380 8402270384 8402270392	8402270263 8402270369 8402270369 8402270369 8402270387	84/01/30 84/02/13 84/02/13 84/02/13 84/02/08	50-327 50-289 50-498 FOIA 50-282	D P A G
8402270183 8402270187 8402270192 8402270193 8402270195	8402270072 8402270184 8402270072 8402270187 8402270185	83/12/22 83/12/14 83/12/22 84/02/21 84/02/20	FOIA FOIA FOIA 50-546 50-369	€ P	8402270402 8402270415 8402270416 8402270423 8402270423	8402270400 8402270263 8402270413 8402270418 8402270263	84/02/24 84/01/30 84/02/21 84/02/23 84/01/30	50-237 FOIA 50-454 50-387 FOIA	G G
B402270196 B402270198 B402270201 B402270202 B402270204	8402270184 8402270072 8402270184 8402270194 8402270072	83/12/14 83/12/22 83/12/14 84/02/22 83/12/22	FOIA FOIA FOIA 50~305 FOIA	P	8402270431 8402270432 8402270434 8402270442 8402270444	8402270263 8402270426 8402270428 8402270433 8402270440	84/01/30 84/02/10 84/02/09 84/02/22 84/02/22	FOIA 50-254 50-483 50-454 50-483	0 0 0
8402270206 8402270208 8402270211 8402270214 8402270216	8402270184 8402270184 8402270072 8402270184 8402270072	83/12/14 83/12/14 83/12/22 83/12/14 83/12/22	FOIA FOIA FOIA FOIA		9402270446 8402270448 8402270478 8402270497 8402270506	8402270443 8402270441 8402270474 8402270494 8402270503	84/02/09 84/02/17 84/02/09 84/02/09 84/02/09	50-498 50-295 FOIA 50-329 FOIA	G G A
8402270217 8402270221 8402270224 8402270226 8402270230	8402270184 8402270072 8402270184 8402270199 8402270184	83/12/14 83/12/22 83/12/14 84/02/08 83/12/14	FOIA FOIA FOIA 50-461 FOIA	Q	8402270509 8402270513 8402270518 8402270520 8402270525	8402270504 8402270503 8402270503 8402270503 8402270503	84/01/12 84/02/09 84/02/09 84/02/09 84/02/09	FOIA FOIA FOIA FOIA	
8402270232 8402270233 8402270237 8402270240 8402270241	8402270184 8402270231 8402270184 8402270215 8402270184	83/12/14 84/02/15 83/12/14 84/02/24 83/12/14	FDIA 50-443 FDIA 50-321 FDIA	K P	8402270578 8402270598 8402270591 8402270597 8402270603	8402270573 8402270573 8402270573 8402270573 8402270573	84/01/04 84/01/04 84/01/04 84/01/04 84/01/04	FOIA FOIA FOIA FOIA	
6402270244 6402270248 6402270251 6402270253 8402270256	8402270184 8402270184 8402270184 8402270239 8402270184	83/12/14 83/12/14 83/12/14 84/02/22 83/12/14	FOIA FOIA FOIA 50-204 FOIA	P	8402270609 8402270617 8402270619 8402270623 8402270644	8402270573 8402270573 8402270573 8402270573 8402270637	84/01/04 84/01/04 84/01/04 84/01/04 84/01/12	FOIA FOIA FOIA FOIA	
8402270257 8402270258 8402270260 8402270261 8402270265	8402270245 8402270250 8402270184 8402270252 8402270250	84/02/17 84/02/08 83/12/14 84/02/16 84/02/08	50-305 F01A F01A 50-387 F01A	G G	8402280002 8402280004 8402280011 8402280020 8402280027	8402280001 8402280003 8402280007 8402280018 8402280018	84/01/27 84/02/02 84/02/01 93/12/21 83/12/21	50-261 50~413 50-400 FOIA FOIA	<u>0</u> 0
8402270268 8402270273 8402270276 8402270278 8402270280	8402270250 8402270250 8402270250 8402270250 8402270250	84/02/08 84/02/08 84/02/08 84/02/08 84/02/08	FOIA FOIA FOIA FOIA FOIA		8402280031 8402280033 8402280033 8402280037 8402280042	8402280018 8402280023 8402280018 6402280018 8402280018	83/12/21 84/01/26 83/12/21 83/12/21 83/12/21	FOIA 50-390 FOIA FOIA FOIA	G
8402270282 8402270283 8402270284 8402270288 8402270289	8402270263 8402270250 8402270277 8402270250 8402270263	84/01/30 84/02/08 84/02/22 84/02/08 84/01/30	50-247 FOIA 50-373 FOIA 50-327	0 @ D	8402280045 8402280045 8402280041 8402280042 8402280045	8402280018 8402280018 8402280018 8402280058 8402280018	83/12/21 84/02/13 83/12/21 84/02/24 83/12/21	FOIA 50-324 FOIA 50-482 FOIA	œ A
8402270291 8402270293 8402270294 8402270296 8402270297	8402270287 8402270250 8402270284 8402270250 8402270250	94/02/14 84/02/08 84/02/09 84/02/08 84/01/30	50-440 FOIA FOIA FOIA 50-327	A 0	8402280047 8402280047 8402280073 8402280074 8402280077	8402280048 8402280018 8402280048 8402280018 8402280018	84/02/13 83/12/21 84/02/13 63/12/21 83/12/21	50-324 FOIA 50-324 FOIA FOIA	G G

ACCESSION NUMBER

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER

ACCE9810	IN NUMBER				ACCESSIO	IN KUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT		SUBJECT CATEGORY		ENCLUSURE	PRINCIPAL DOCUMENT	DATE ISSUED	BU9JEC CATEGO	
8402280080 8402280081 8402280085 8402280087	8402280018 8402280048 8402280018 8402280018	83/12/21 84/02/13 83/12/21	FOIA 50-324 FOIA 50-471	Q		8402280418 8402280415	84/02/13 84/02/14 84/02/14 84/02/09	50-416 50-416 50-416 50-280	0 0 0
8402280070 8402280073	6402260018 6402260018	63/12/21	FOIA	A G	8402280436 8402280436	8402280415 8402280415	84/02/14	50-280 50-280	e e
8402280074 8402280108 8402280117	8402280018 8402280104 8402280114	83/12/21 84/02/23	FOIA TOPREP FOIA		8402280444 8402280444 8402280447	8402280415 8402280442 8402280419	84/02/14 84/01/24 84/02/09	50-416 50-302 50-280	G G
8402280126 8402280127	8402280116 8402280125	84/02/09		G .	8402280464 8402280466	8402280459 8402280445	84/02/22	50-353	G G
8402280138 8402280141 8402280155 8402280156	8402280133 8402280116 8402280116 8402280148	84/02/01 84/01/05 84/01/05 84/02/08	50~250 50~250	Q P P Q	8402280472 8402280473 8402280473 8402280477	8402280467 8402280445 8402280445 8402280467	84/02/13 84/02/15 84/02/15 84/02/13	50-339 50-366 50-366 50-339	G G G
8402280158 8402280161 8402280164	8402280116 8402280157 8402280116	84/01/05 84/01/27 84/01/05	50~438 F01a	P G	8402280479 8402280480 8402280484	8402280476 8402280467 8402280467	84/02/22 84/02/13 84/02/13	50-352 50-339 50-339	G G
8402280166 8402280170 8402280171	8402280148 8402280165 8402280159	84/02/08 84/02/09 84/02/17	50~261	0 0	8402280485 8402280492 8402280498	8402280445 8402280457 8402280489	84/02/15 84/02/24 84/02/15	50-366 50-237 50-259	G P G
8402280172 8402280174 8402280179	8402280148 8402280148 8402280148	84/02/23 84/02/08 84/02/23	50~410 50~335	9	8402280504 8402280505 840228051 1	8402280489 8402280499 8402280499	84/02/15 84/02/21 84/02/21	50-259 50-280 50-280	9
8402280185	6402280148 6402280182	84/02/08 84/02/10	50~400	a a	8402280512 8402280516	8402280489 8402280506	84/02/15 84/02/02	50-259 50-413	G G
8402280174 8402280177 8402280200 8402280203	8402280182 8402280182 8402280175 8402280175	84/02/10 84/02/10 84/02/13 84/02/13	50~400 50~302	a a a	6402260518 6402280520 6402280522 8402280525	8402280499 8402280489 8402280499 8402280517	84/02/21 84/02/15 84/02/21 84/02/21	50-280 50-259 50-280 50-280	Q Q P
8402280204 8402280204 8402280212	8402280182 8402280195 8402280195	84/02/10 84/02/13 84/02/13	50-302	0 0	8402280528 8402280529 8402280530	8402280519 8402280499 8402280489	84/02/17 84/02/21 84/02/15	50-327 50-260 50-259	Q Q Q:
8402280214 8402280220	8402280205 8402280205	84/02/17 84/02/17	50-272	Q Q	8402280531 8402280534	8402280457 8402280523	84/02/24 84/02/09	50-237 70-143	P
8402280244 8402280246 8402280248 8402280250	8402280237 8402280239 8402280243 8402280237	84/02/09 84/01/31 84/02/23 84/02/09	50~321 i	Q Q P	8402280535 8402280540 8402280542	8402280514 8402280487 8402280532	84/02/08 84/02/15 84/01/30	50~445 50~259 50-249	G G
8402280252 8402280253	8402280237 8402280237	84/02/07 84/02/07		G G	8402280543 8402280546 8402280552	8402280489 8402280535 8402280489	84/02/15 84/02/10 84/02/15	50-259 TOPREP 50-259	G G
8402280255 8402280265 8402280267	8402280237 8402280262 8402280263	84/02/09 84/02/17 84/02/20	50-250 50-416 PTQ1	a	9402290569 9402290570 9402290596	8402280564 8402280415 8402280594	84/02/23 84/02/14 84/01/16	50-341 50-416 FDIA	G. O
8402280270 8402280272 8402280275	8402280266 8402280262 8402280261	84/01/26 84/02/17 84/02/16	50~416	a a	8402280600 8402280602 8402280604	8402280574 8402280574 8402280578	84/01/16 84/01/16 84/02/13	FOIA CONTRACT	т
8402280278 8402280280 8402280282	8402280262 8402280262 8402280261	84/02/17 84/02/17 84/02/16	50~416 6 50~416	ā a a	8402280605 8402280607 8402280611	8402280574 8402280574 8402280574	84/01/16 84/01/16 84/01/16	FOIA FOIA FDIA	
8402280284 8402280285 8402280287	8402280262 8402280277 8402280283	84/02/17 84/01/30 83/12/02		G G	8402280614 8402280615 8402280620	8402280574 8402280574 8402280574	84/01/16 84/01/16 84/01/16	FOIA FOIA FOIA	
8402280290 8402280293	B402280261 B402280261	84/02/16 84/02/16	50-62 (	a a	8402280623 8402280623	8402280594 8402280594	84/01/16 84/01/16	FOIA FOIA	
8402280298 8402280300 8402280302	8402280291 8402280261 8402280296	84/02/07 84/02/16 84/02/24	50-346 6 50-62 6 50-254 6	G	8402280631 8402280636 8402280639	8402280594 8402280594 8402280594	84/01/16 84/01/16 84/01/16	FOIA FOIA FOIA	
8402280303 8402280307 8402280319	8402280279 8402280271 8402280314	84/02/08 84/02/07 84/02/24	70~143 50~346 6 50~170 6	-	8402280642 8402280646 8402280647	6402280594 6402280594	84/02/13 84/01/16 84/01/16	CONTRACT FOIA FDIA	i
8402280325 8402280348 8402280349	8402280314 8402280264 8402280247	84/02/24 84/02/17 84/02/07	50-170 G 50-261 G WASTE MOT	g	8402280453 8402280453 8402280454	8402280574 8402280574 8402280574	83/11/18 84/01/16 83/11/18	40-8724 FOIA 40-8724	
8402280352 8402280357	8402280343 8402280264	84/02/24 84/02/17	50~289 G	_	8402280457 8402280459	8402280574 8402280547	84/01/16 83/11/18	FOIA 40-8724	
8402280361 8402280365 8402280369 8402280373	8402280185 8402280264 8402280264 8402280358	84/02/22 84/02/17 84/02/17 84/02/27	50~327 P 50~261 G 50~261 G 50~413 G	3 3	8402280657 8402280657 8402280659 8402280682	8402280566 8402280594 8402280570 8402280594	83/10/11 84/01/16 84/02/22 84/01/16	PROJ FOIA CONTRACT FOIA	r
8402280376 8402280379 8402280383	8402280264 8402280377 8402280377	84/02/17 84/02/23 84/02/23	50~261 0 50~267 R 50~267 R	₹	8402280492 8402280495 8402280494	8402280688 8402280691 8402280594	84/02/08 84/02/22 84/01/16	CONTRACT 50-289 FOIA	U
8402280385 8402280387	8402280377 8402280377	84/02/23 84/02/23	50~267 R 50~267 R		8402280700 8402280704	8402280594 8402280699	84/01/16 84/01/11	FOIA 40-8794	
8402280408 8402280417 8402280421 8402280423	8402280404 8402280411 8402280418 8402280415	84/02/23 84/01/05 84/02/13 84/02/14	70~2077 50~259 G 50~416 G 50~416 G	ì	8402280706 8402280708 8402280008	8402280594 8402280699 8402290002	84/01/16 84/01/11 83/11/30	FOIA 40-8794 50-537	U P
B402280426	8402280419	84/02/09	20-580 d		84022 <del>7</del> 0013 84022 <del>7</del> 0024	8402270012 8402270002	84/02/27 83/11/30	50-416 50-537	Ü

8402290477 8402290478 8402290479 8402290467 8402290467 8402290467

ACCESS10	N NUMBER			
rosuke	PRINCIPAL DOCUMENT	DATE ISSUED	CATEGO	
2290054	8402270002	83/11/30	FOIA	
0800755	8402270002 8402270002	83/11/30 83/11/30	FOIA FOIA	
2270062	8402290002	B3/11/30	FOIA	
	8402290002	B3/11/30	90-275	U
2290078 2290080	8402270074 8402270079	84/02/22 84/02/27	50-373 50-289	F
2290082	8402290002	83/11/30	50-275	ŭ
72290083 72290091	8402290067 8402290002	83/12/14 83/11/30	FOIA FOIA	
2270098	8402270002	83/11/30	50~382	u
2270103 2270108	8402270002 8402270002	83/11/30 83/11/30	FDIA FOIA	
2270112	8402270107	84/02/24	50-382	G
SS50114	8402270002	83/11/30	FOIA	
4290120 2290118	8402290002 8402290115	83/11/30 84/02/17	50-275 50-346	U P
2270121 2270124	8402290002 8402290123	83/11/30 84/02/24	50-267	U
2270127	8402290002	83/11/30	50-289 FDIA	G
2270128	8402290123	84/02/24	50-289	G
2270129 2270132	8402290002 8402290115	83/11/30 84/02/17	FDIA 50~346	р
2290134 2290135	8402270123 8402270130	84/02/24 84/02/14	50-289 50-454	Ġ
2290137	8402290002		50-358	
2290140	8402290123	83/11/30 84/02/24	50-269	G
2290142 2290143	8402290067 8402290123	83/12/14 84/02/24	FOIA 50-287	9
2290145	8402290047	83/12/14	FDIA	
2270147 2270149	84022900 <i>6</i> 7 8402290123	83/12/14 84/02/24	FOIA 50-289	G
2290150	8402290067	83/12/14	FOIA	G
2290152 2290153	8402290067 8402290002	83/12/14 83/11/30	FOIA FOIA	
2290159	8402290067	83/12/14	FOIA	
2290162 2290163	8402270158 8402270002	84/02/24 83/11/30	50-289 50-373	G U
2290164 2290167	8402270067 8402270067	83/12/14 83/12/14	FOIA FOIA	
2270169	8402270067		50~289	
2270170 2270171	8402270067	84/02/24 83/12/14	FOIA	G
?270171 ?270172	8402290002 8402290169	83/11/30 84/02/24	FOIA 50-244	р
2270173	8402270158	84/02/24	50-289	g
2290178 2290179	8402270002 6402270158	83/11/30 84/02/24	FOIA 50-289	G
	8402270067	83/12/14	FOIA	•
270182 270184	8402290002 8402290158	83/11/30 84/02/24	F01A 50~289	Q
2290185	8402290067	83/12/14	FOIA	
290187 290190	8402290158 8402290002	84/02/24 83/11/30	50-289 FDIA	G
290191 290195	8402290067	83/12/14	FDIA 50-397	G
	8402290188	84/02/15		
290197 2902 <b>0</b> 0	8402270158 8402270067	84/02/24 83/12/14	50-287 FOIA	G
270201 270203	8402290002 8402290193	83/11/30 84/02/10	50-382 50-255	G
270205	8402290198	B4/01/10	90-382	Ä
290204	8402290158	84/02/24 84/02/14	50~289	0
340311 340304	8402270204 8402270158	84/02/24	50-213 50-289	0
290214 290215	8402270208 8402270212	84/02/15 84/02/27	50-329 50-537	Q A
290217	8402270158	B4/02/24	50-289	G
290221 290223	8402290208 8402290158	84/02/15 84/02/24	50-329 50-289	Ğ O
290224	8402270220	84/02/13	70-1100	
290225	8402270216	84/02/23	50-374	Q
290226 290228	8402270002 8402270222	83/11/30 84/02/23	50-272 50-341	ū
290228 290229	8402270158 8402270216	84/02/24 84/02/23	50-289 50-374	G G
540533 540535	8402290220	84/02/13	70-1100	-
290235	8402290158	84/02/24	50-287	Ģ
290237 290241	8402270234 8402270002	84/02/06 83/11/30	50-261 50-382	F
290242 290246	8402270158 8402270158	84/02/24 84/02/24	50-289 50-289	G
£ 7VE/10		·		-

ACCESS 1	ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 195UED	SUBJEC	
			50-352	
8402290247	8402290239	84/02/14	50-456	9
8402290249	8402290240	84/02/16		•
8402290250	8402270002	83/11/30	50-247	Ų
8402290251	840227015B	B4/02/24	50-289	9
8402290254	8402290244	84/02/15	50-155	0
8402270260	8402290158	84/02/24	50-289	G
8402270264	8402290257	84/02/15	50-423	G
8402290268	8402270158	84/02/24	50~289	G
8402290270	8402290158	84/02/24	50~289	G
8402290271	8402270002	83/11/30	FOIA	
0400000000	646796666	55/11/25	50-537	E
8402290273	8402290002	83/11/30		ā
8402290275	8402290269	84/02/13	50-336	
8402290282	8402290002	83/11/30	50-247	U
8402270265	8402290002	83/11/30	50-247	U
8402270270	B402290002	63/11/30	50-45B	Ų
8402290294	8402270287	84/02/13	50-317	g
8402290297	6402290002	63/11/30	50-537	E
8402270278	8402270295	84/02/14	50~309	0
8402290302	8402290295	84/02/14	50~309	G
B402290303	8402270002	B3/11/30	50-247	U
8402270308	8402270304	84/02/17	50~309	Р
8402290309	B402270305	84/02/15	50~277	ā
8402270310	8402270002	83/11/30	FOIA	_
8402270311	8402290306	84/02/14	50-443	O
6402270312	8402290307	84/02/22	50-413	š
8405540315	0405530701	047V2722	20-410	
8402290313	6402270002	83/11/30	FOIA	
8402270314	8402290307	64/02/22	50-413	8
8402270316	8402290306	84/02/14	50-443	O O
B402270317	8402290303	84/02/15	50-277	Œ
8402290318	8402290002	83/11/30	50-269	U
8402270324	8402290321	84/02/14	50-334	Q
8402270325	8402270321	B4/02/14	50-334	C)
8402290328	8402270325	84/02/14	50-289	ä
8402270366	8402290362	84/02/17	50-456	ñ
8402270385	84022703B2	84/02/17	50-155	þ
a.enacena	0400000000	01/00/17	50-155	Р
8402290387	8402270382	84/02/17		-
8402270408	8402290406	64/02/21	50-341	Ą
8402270407	8402270406	84/02/21	50-341	Ą
8402290413	8402290406	84/02/21	50-341	Α
8402290417	8402290394	84/02/13	CONTRACT	
8402290432	8402296423	84/02/14	50-331	ρ
6402270437	8402290423	84/02/14	50-331	Р
8402270453	8402290445	84/01/26	70-687	
8402290466	8402290461	84/02/12	50-275	P
8402270473	8402290467	B4/02/17	50-320	Q.
				-

50-320 50-320 50-320

84/02/17 84/02/17 84/02/17 0

			1
			;

#### APPENDIX A

# DEFINITIONS OF DOCKET 50 CATEGORIES

# A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are

- 1 Application for construction permit.
- 2. General Information submitted with construction permit application.
- 3 Amendments and changes to items 1 and 2.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5 Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review.
- 11. Environmental review information
- 12. Application for operating license.
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

# B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

- 3. Transmittal and acknowledgement letters.
- 4. Certificates of service to the PSAR.

# C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- 3. Transmittal and acknowledgement letters.
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

# D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

- 1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2. Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- 5. Transmittal and acknowledgement letters.
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Federal register notice citing availability of items 1 and 2.
- 9. Site visits to obtain information for DES or FES.
- 10. Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

# E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A. P. or W, depending on the phase of the licensing process.

- 1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
- 2. Supplements to SER.
- 3. Correspondence relating to SER.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests,
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8. Transmittal and acknowledgement letters.

# F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

- 1. Fire Hazard Protection Plan and surveys.
- 2. Plant evacuation correspondence.
- 3. Safeguards Contingency Plans.
- 4. Review of Health Physics Program.
- 5. Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

### G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3. Requests to make appearances at hearings.
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8.

### H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included

- 1. Change of address notifications.
- 2. Changes in structure of organization.
- 3. Changes in service lists
- 4. NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6. Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8. Correspondence regarding the Local Public Document Rooms (LPDRs).
- 9. Professional qualification statements not pertaining to the hearing process.

### I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application of its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

#### J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- 3. Other correspondence regarding indemnity and insurance matters.

### K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2. Amendments and changes to the FSAR.
- 3. Federal register notices citing availability of items 1 and 2.
- 4. Transmittal and acknowledgement letters.
- 5. Certificates of service to the FSAR.

# L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

- 1. Limited Work Authorizations (LWA) and amendments.
- 2. Correspondence pertaining to work performed under LWAs.

#### M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review"
- 2. Correspondence where the primary topic of discussion is antitrust matters.
- 3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

# N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

# O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- 1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
- 2. Correspondence from ACRS.
- 3. Announcement of ACRS meetings.
- 4. Transmittal and acknowledgement letters.
- 5. ACRS reports.
- 6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
- 7. Minutes at ACRS Subcommittee Meetings.

# P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

- 1. Operating license, amendments, proposed amendments, changes and related correspondence.
- Technical specifications and changes.

- 3 Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license
- 8. Information on the Standard Review Plan (STP).
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Quality assurance information.
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool,
- 17. Start-up test reports,
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.

# Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1. Inspection reports,
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN s).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

# R PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature

- 1 Monthly semiannual or annual operating reports (other than financial)
- 2 Periodic environmental monitoring effluent testing of similar reports.
- 3 Periodic personnel exposure reports
- 4 Operational Logbooks

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets.

5 Correspondence or other documents relating to the above listed items

# S REPORTABLE OCCURRENCES, PNOS, PNSs AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes

- All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences)
- 2 Potential or possible reportable deficiency reports and related correspondence.
- 3 Personnel exposure reports
- 4. Construction deficiency reports submitted under 10 CFR 50 55e.
- Preliminary Notification of Occurrence (PNOs) and Preliminary Notification of Safeguards Events (PNs).
- 6. Environmental Technical Specifications violation reports and Invironmental Event reports.
- 7. Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to items 1-7

# T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U)

- Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2. Testimony and statements submitted to ASLB and ASLAB.
- 3. Commission meeting transcrip
- 4. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings
- 6 Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.
- 8. Corrections to above items.

#### U CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H

- Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches
- 2 Preparatory and backup documents for item 1.
- 3 Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters

# V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1 Operator licenses or administrative information bearing on licensing of operators
- 2 NRC examination results.
- 3 Power plant examination summary sheet.

#### W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward

- 1 Application for authority to voluntarily surrender license.
- 2. Application to dismantle the facility and dispose of component parts.
- 3. Technical documents submitted in support of items 1 and 2, such as Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning
- 4. Documents relating to disposal of radioactive material and decontamination of the site.
- 5. Other correspondence relating to above items
- 6 All documentation relating to the ongoing operation of the plan, formerly filed in category P.

# X. ONSITE LOW-LEVEL WASTES STORAGE

This category contains items related to the onsite storage of low-level radioactive wastes generated onsite.

# Y. INDEPENDENT SPENT FUEL STORAGE INSTALLATIONS (ISFSI)

This category contains documents with an NMSS license and/or a Docket-72 number. For installations on a reactor site, the associated Docket-50 number will also be identified.

- 1. License applications, licenses, amendments and proposed amendments to possess power reactor spent fuel and other radioactive materials associated with spent storage in an independent spent fuel storage installation. (Such spent fuel storage installations may be on a reactor site or at a separate site.)
- All related correspondence and reports to the above.

#### APPENDIX B

# **DEFINITIONS OF NONDOCKETED CATEGORIES**

### 10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes

- 1 Sunshine Act Lederal Register notices
- 2 Full, written explanation of closed meetings
- 3 Certification of General Counsel on closed meetings.
- 4 Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
- 5. Verbatim unofficial and official transcripts of portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- 6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
- 7. Staff requirements memoranda for open meetings, memoranda to record, record of votes of Commissioners on items under consideration at meetings.

### ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
- 2. ACRS meeting announcements; description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available
- 4. ACRS consultant reports, comments and related correspondence.
- 5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

#### ADVCM - NRC Advisory Committees

This category contains documentation pertaining to the responsibilities of all NRC advisory committees, other than the Advisory Committee on Reactor Safeguards. The documents in this category are:

- 1. Charters of each advisory committee.
- 2. Verbatim transcripts of committee meetings.

- 3. Meeting announcements; description of meeting agendas.
- 4. Committee generated reports, memoranda, and correspondence that are publicly available.
- 5. Committee related correspondence.

#### COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including

- Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures
- 2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners
- Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

#### CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
- 2. Solicitations (RFP or IFB) issued by the NRC.
- 3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any,

#### DISCLOSURE - Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

### FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

- 1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- 2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

# GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation

- 1 Draft reports of action plans to accomplish generic tasks in the regulatory program.
- 2 Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues
- 3. Meeting notifications and minutes.
- Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

# I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1. 1&E Circulars, which describe an event at a licensed facility and are informational in nature.
- 2 I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3 I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
- 4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

#### MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

# NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- 1. These reports are normally final work products and are characterized by the following criteria:
  - They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
  - b. They present the results of Commission licensing and policy decisions
  - c. They present the results of technical research conducted for the Commission.
- 2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- 3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

### ORG - Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

- 1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
- 2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

#### PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR).
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- 4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

### PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- 1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.

- 3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
- 4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

# PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

- A. Application/Construction Stage
  - 1. Application submitted by the utility.
  - 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
  - 3. Applicant's Quality Assurance Manual.
  - 4. Early site review information.
  - 5. Backup technical documents submitted in support of the application.
  - 6. Early site visits.
- B. Utility PSAR and Amendments
  - 1. PSARs submitted by the utility.
  - 2. Amendments and changes to the PSAR.
  - 3. Transmittal letters.
  - Letters acknowledging receipt of the PSAR.
- G. Adjudicatory Correspondence
  - 1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.
- M. Antitrust Correspondence
  - 1. Submittals and related material pertaining to the antitrust review.

## Q. Inspection Reports

- 1. Inspection reports of the applicant's quality assurance program.
- 2. Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

#### 2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

# PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include.

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- 2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited.
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

# QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- 1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

# REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC staff for implementing specific parts of the NRC's regulations. They also deminate techniques and by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

# RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
  - a. model documentation reports
  - b. code documentation reports
  - c. code verification reports
- 3. Pre-test prediction reports.
- 4. "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- 9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

# REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

- 1. Agendas for quarterly review group meetings.
- Summary minutes of review group meetings representing views expressed, including dissenting views.
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

### RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

# SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- 1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

#### **STATE PROG** — State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies; and (3) a wide range of haison and cooperative activities regarding such functions as licensing and siting. It includes:

- 1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
  - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
  - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
- 2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
- 3. State Legislative Reports.
- 4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

#### TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

# WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- 2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

- 3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
- 4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

# XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.
- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public.
- 6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8. Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

NRC FORM 335 US NUCLEAR REGULATORY COMMISSION BIBLIOGRAPHIC DATA SHEET  4 TITLE AND SUBTITLE (Add Volume No., if appropriate) Title List of Documents Made Publicly Available February 1984		1. REPORT NUMBER (Assigned by DDC) NUREG-0540 Vol. 6, No. 2 2 (Leave blank) 3 RECIPIENT'S ACCESSION NO					
				7 AUTHOR(S)		5 DATE REPORT (	OMPLETED YEAR
				Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, DC 20555		DATE REPORT II	SSUED
						MONTH YEAR 1984	
6 (Leave blank)							
6 (Leave brank)							
8 (Leave blank)							
SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code) Same as 9, above.		10. PROJECT/TASK/WORK UNIT NO					
		11 FIN NO					
13. TYPE OF REPORT	PERIOD COVERED (Inclusive dates)						
Monthly	1 f	ebruary 1-29,1984					
5 SUPPLEMENTARY NOTES		14 (Leave plank)					
This document is a monthly publication contain received and generated by the U.S. NRC. This material associated with civilian nuclear power active materials, and (2) nondocketed material pertinent to its role as a regulatory agency. Personal Author Index, Corporate Source Index, Reference to Principal Documents Index.	information or plants and received a The follow	n includes (1) nd other uses o and generated b ving indexes ar	docketed of radio- oy NRC re included:				
17. KEY WORDS AND DOCUMENT ANALYSIS	17a DESCRIPTOR	s					
17b. IDENTIFIERS/OPEN-ENDED TERMS							
18 AVAILABILITY STATEMENT	Uncla	Y CLASS (This renord)	21 NO OF PAGES				
Unlimited	20 SECURITY	YCLASS <i>(Thispean)</i> ISSIFIED	22 PRICE S				